MIL-M-48292 (PA)
Amendment 9
30 December 1975
SUPERSEDING
Amendment 8
23 July 1975

MILITARY SPECIFICATION

MINE, ANTI-TANK, METAL PARTS ASSEMBLY FOR M56 MINE

This Amendment forms a part of Military Specification MIL-M-48292 (PA) dated 20 February 1974 and is approved for use by all Departments and Agencies of the Department of Defense.

Paragraph 3.3.1, Delete

Paragraph 3.3.2 delete in its entirety and substitute the following:

3.3.2 Switch housing bond strength. - The switch housing shall not separate when tested in accordance with paragraph 4.4.11.2.

Paragraph 3.3.3, Delete.

Add new paragraph 3.8:

"3.8 Battery Cap Assembly Continuity Resistance. - The maximum resistance between the threads and the snap terminal shall be one (1) ohm maximum".

Add new paragraph 3.9:

"3.9 Fuze Cover Continuity Resistance. - The maximum resistance of the inside surface of the fuze cover shall be one (1) ohm maximum."

Paragraph 4.2.1a - Delete, "twenty-five (25) sets of all components" and substitute, "ten (10) sets of all components".

Paragraph 4.2.2.b, Delete, "twenty-five (25)" and substitute, "ten (10)".

FSC: 1345

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:21Z
Check the source to verify that this is the current version before use.

Paragraph 4.2.2.c, Delete, "twenty-five (25)" and substitute, "ten (10)".

Paragraph 4.2.2.d, Delete, "twenty-five (25)" and substitute, "ten (10)".

Paragraph 4.2.2.e, Delete, "twenty-five (25)" and substitute, "ten (10)".

Paragraph 4.2.2.f, Delete, "twenty-five (25)" and substitute, "ten (10)".

Paragraph 4.2.2.g, Delete, "twenty-five (25)" and substitute, "ten (10)".

Paragraph 4.2.2.h, Delete, "twenty-five (25)" and substitute, "ten (10)".

Paragraph 4.2.2.j, Delete, "twenty-five (25)" and substitute, "ten (10)".

Paragraph 4.2.2.k, delete.

Paragraph 4.2.2.m, Delete, "three (3) mine body assemblies" and substitute "twenty-five (25) mine body assemblies".

Paragraph 4.2.2.1(1), delete.

Paragraph 4.2.2.1(3), delete.

Paragraph 4.2.2.n, Delete, "twenty-five (25)" and substitute, "ten (10)".

Add new paragraph 4.2.2.p(3):

"4.2.2.p(3) Leakage testing in accordance with 4.4.13.3."

Paragraph 4.2.2.p(4), Add new paragraph:

"4.2.2.p(4) Maximum profile test in accordance with 4.4.13.4".

Paragraph 4.3.3.r, delete.

Paragraph 4.2.2.s, add new paragraph:



Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:21Z
Check the source to verify that this is the current version before use.

"4.2.2.s Twenty-five (25) mine bodies shall be tested in accordance with 4.4.11.5".

Paragraph 4.2.3, Delete:

"Rejection. - If item fails" and substitute, "Rejection. - If any sample fails".

Paragraph 4.3.2.1 delete,

"101. Outside contour ..... Gage 01001"

Paragraph 4.3.2.1, Delete,

"102. Flatness ..... Gage 01002
and substitute
102. Straightness ..... Gage 01002"

Paragraph 4.3.2.2, delete,

"101. Helix angle in wrong direction ..... Visual 03001

Minor: AQL 1.5 percent
201. Spring Angle ..... Gage 03002"
and substitite
"Minor: AQL 1.0 percent"

*Paragraph 4.3.2.3, delete,

"Major: AQL 0.65 percent
101. Length, maximum (max)..... Gage 05001

Minor: AQL 1.0 percent
201. Width, max..... Gage 05004"
and substitute:
"Major: AQL 0.40 percent
Minor: AQL 0.65 percent"

Paragraph 4.3.2.6, Delete,

"101. Overall length ..... Gage 08001"
and substitute:
"101. Overall length to stop shoulder ..... Gage 08001"



Source: https://assist.dla.mil -- Downloaded: 202610-22T19:21Z
Check the source to verify that this is the current version before use.

Paragraph 4.3.2.7, delete

| | | | |
|---|---|---|---|
| "101. | Outside diameter, max ..... | Gage | 10001 |
| 102. | Thread pitch diameter ..... | Gage | 10002" |

Paragraph 4.3.2.8, Delete,

| | | | |
|---|---|---|---|
| "101. | Rubber loose or peeling ..... | Visual/ Manual | 11001 |
| 104. | Overall height ..... | Gage | 11004" |

and substitute:

| | | | |
|---|---|---|---|
| "101. | Rubber loose or peeling beyond feathering effect ..... | Visual/ Manual | 11001 |
| 104. | Overall height at switch location ..... | Gage | 11004" |

Paragraph 4.3.2.9, Delete,

| | | | |
|---|---|---|---|
| "203. | Height, Max. ..... | Gage | 12005" |

and substitute:

| | | | |
|---|---|---|---|
| "203. | Height, minimum ..... | Gage | 12005" |

Paragraph 4.3.2.9, delete,

| | | | |
|---|---|---|---|
| "101. | Location of mounting holes ... | Gage | 12001 |

Minor: AQL 2.5 percent

| | | | |
|---|---|---|---|
| 202. | Width, max ..... | Gage | 12004 |
| 204. | Pressure plate opening contour ..... | Gage | 12006" |

and substitute:
"Minor AQL 1.5 percent"

Paragraph 4.3.2.10, Delete,

| | | | |
|---|---|---|---|
| "107. | Booster cup not covered with protective coat ..... | Visual | 13007" |

Paragraph 4.3.2.10, delete,

| | | | |
|---|---|---|---|
| "101. | Height of switch housing, max ..... | Gage | 13001" |



Source: https://assist.dla.mil -- Downloaded: 202610-22T19:21Z
Check the source to verify that this is the current version before use.

Paragraph 4.3.2.11, delete,

"Minor AQL 2.5 percent

| | | | |
|---|---|---|---|
| 201. | Location of plunger assembly hole ..... | Gage | 14005 |
| 204. | Location of switch plunger hole ..... | Gage | 14008" |

*Paragraph 4.3.2.11, Delete,

| | | | |
|---|---|---|---|
| "102. | Plunger assembly hole diameter..... | Gage | 14002 |

Minor: AQL 1.5 percent

| | | | |
|---|---|---|---|
| 202. | Depth of plunger assembly hole..... | Gage | 14006" |

and substitute:
"Minor: AQL 1.0 percent"

Paragraph 4.3.2.12, Delete,

| | | | |
|---|---|---|---|
| "101. | Curved wall thickness at 3 points, min. ..... | Gage | 15001 |
| 109. | Location of switch housing mounting hole ..... | Gage | 15009" |

and substitute:

| | | | |
|---|---|---|---|
| "101. | Curved wall thickness at 3 points, min. (Equally spaced). | Gage | 15001" |

Paragraph 4.3.2.12, Delete,

| | | | |
|---|---|---|---|
| "102. | Cavity opening, min. ..... | Gage | 15002 |
| 103. | Inside radius..... | Gage | 15003 |
| 104. | Position of inside radius ... | Gage | 15004 |
| 205. | Height of curved section, max. ..... | Gage | 15016" |

Paragraph 4.3.2.12, Add,

| | | | |
|---|---|---|---|
| "112. | Wall thickness on pressure plate surface (3-points equally spaced on both sides of shoulder) ..... | Gage | 15020 |
| | Body outside radius maximum (9-points) ..... | Gage | 15021" |



Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:21Z
Check the source to verify that this is the current version before use.

3 sets of measurements on an arc and each set longitudinally along the body.

Paragraph 4.3.2.12, delete,

| | | | |
|---|---|---|---|
| "104. | Position of inside radius .... | Gage | 15004 |
| 108. | Location of switch housing cavity hole ..... | Gage | 15008 |
| 110. | Cavity top surface parallelism ..... | Gage | 15010 |
| 204. | Location of pressure plate surface ..... | Gage | 15015 |
| 205. | Height of curved section, max ..... | Gage | 15016 |
| 206. | Location of flex cable hole .. | Gage | 15017" |

Paragraph 4.3.2.13, Delete Code No. 16012 from the "1.5 percent AQL grouping" and substitute:

| | | | |
|---|---|---|---|
| "Major: | | Sample Size: | 10 parts |
| 112. | Surface finish of bore rider hole ..... | Gage | 16012. |

The lot shall be rejected if one (1) or more samples are classed defective."

Paragraph 4.3.2.13, delete,

| | | | |
|---|---|---|---|
| "107. | Diameter of booster cup stop hole, min ..... | Gage | 16007 |
| 108. | Booster cup thru hole diameter ..... | Gage | 16008 |
| 202. | Pitch diameter of cover plate mounting hole ..... | Gage | 16014" |

Paragraph 4.3.2.14, Delete,

"101. Assembly damaged or distorted ... Visual 17001"

and substitute,

| | | | |
|---|---|---|---|
| "101. | Assembly damaged, distorted or bent ..... | Visual | 17001" |



Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:21Z
Check the source to verify that this is the current version before use.

Paragraph 4.3.2.15, Delete,

"201. Gasket loose ..... Manual 18003"
and substitute
"201. Gasket hanging loose ..... Manual 18003"

Paragraph 4.3.2.16, delete,

"Minor: AQL 1.5 percent
201. Diameter of mounting holes, min . Gage 19006"
and substitute:
"Minor: AQL 1.0 percent"

Paragraph 4.3.2.18, Delete,

"102. Retainer plate screw(s) missing . Gage 21001

106. Finish damaged ..... Gage 21006"
and substitute,
"102. Retainer plate screw(s) missing . Visual 21002

106. Finish damaged ..... Visual 21006"

Paragraph 4.3.2.20, delete,

"102. Paint on threads ..... Gage 23002

Minor: AQL 1.0 percent
201. Slots distorted or damaged ..... Visual 23003"
and substitute,
"Minor AQL 0.65 percent"

Paragraph 4.3.2.21, Delete,

"103. Length of thread ..... Gage 24003

201. Overall length ..... Gage 24005"
and substitute,
"201. Length of thread ..... Gage 24005"

Paragraph 4.3.2.22, delete,

"101. Inside diameter of cup ..... Gage 25001



Source: https://assist.dla.mil -- Downloaded: 202610-22T19:21Z
Check the source to verify that this is the current version before use.

Minor 1.0 percent
201. Diameter of stop diameter, max ... Gage 25003"
and substitute:
"Minor 0.65 percent"

Paragraph 4.3.3.10, delete.

Paragraph 4.3.3.11, Delete, "(dwg. 9281630)."

Paragraph 4.3.3.11.1, Delete, "(see 3.3.1)" and substitute, "(see dwg. 9281613)".

Paragraph 4.3.3.11.1, Delete

Paragraph 4.3.3.11.2, Delete: "Three (3) assemblies" and substitute: "Five (5) assemblies".

Paragraph 4.3.3.11.3.1, Delete and substitute,

"4.3.3.11.3 Mine Body to Fuze Well Strength, (see dwg. 9281630) Major Defect, Code No. 13011. - The five (5) samples from 4.3.3.11.2 shall be used as the test samples for this test. Testing shall be in accordance with 4.4.11.3. The lot shall be rejected if one (1) or more samples fail to comply with the minimum force and are classed defective".

Add new paragraph 4.3.3.11.3.2:

"4.3.3.11.3.2 Mine Body to Fuze Well Bond Strength (Informational Test Only). - The testing of 4.3.3.11.3.1 shall be continued in accordance with 4.4.11.3 until separation occurs. Testing is informational only".

Paragraph 4.3.3.11.5, Delete, "(see dwg. 9281630)" and substitute, "(See dwg. 9281632)."

Add new paragraph 4.3.3.13.3:

"4.3.3.13.3 Leakage Test, Major Defect (See 3.4.3) Code No. 21001. - The lot shall be tested 100 percent for the requirements in accordance with 4.4.13.3. Any classed defective shall be removed from the lot. (Non-Destructive Test)"

Add new paragraph 4.3.3.13.4:

"4.3.3.13.4 Maximum Profile Test (see dwg. 9281613), Major Defect, Code No. 21012. - Two hundred (200) samples shall be randomly selected from each lot and tested in accordance with 4.4.13.4. The lot shall be rejected if three (3) or more samples are classed defective (Non-destructive test)".



Source: https://assist.dla.mil -- Downloaded: 202610-22T19:21Z
Check the source to verify that this is the current version before use.

Paragraph 4.3.3.13.5, delete.

Paragraph 4.3.3.15, delete.

Add new paragraph 4.3.3.18:

"4.3.3.18 Battery Cap Assembly Continuity Resistance (see 3.8) - Major Defect, Code No. 24007. Thirty-two (32) samples shall be randomly selected from each lot and tested in accordance with 4.4.16. The lot shall be rejected if two (2) or more samples are classed defective. (Non-destructive test)".

Add new paragraph 4.3.3.19:

"4.3.3.19 Fuze Cover Continuity Resistance (see 3.9), Major Defect, Code No. 18006. - Thirty-two (32) fuze covers shall be randomly selected from each lot and tested in accordance with 4.4.17. The lot shall be rejected if two (2) or more samples are classed defective (Non-destructive test)".

Paragraph 4.4.1, Add after paragraph number: "Spring, Plunger, Spring Rate".

Paragraph 4.4.1, delete from the first sentence, "and the free length."

Paragraph 4.4.1, delete, "wire diameter"

Paragraph 4.4.3, delete, "wire diameter and the"

Paragraph 4.4.9, delete and substitute:

"4.4.9 Bore rider spring spring rate.- The spring shall be loaded with the specified loads and measured at the specified respective heights for each load. The spring shall be classed defective if it fails to meet the specified height at each required load."

Paragraph 4.4.9, after the first sentence add,
"In addition to the load requirements, the outer formed coil diameter shall be measured for the specified dimension."

Paragraph 4.4.10, delete.



Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:21Z
Check the source to verify that this is the current version before use.

Paragraph 4.4.11.1, delete.

Paragraph 4.4.11.2 Delete in its entirety and substitute the following:

"4.4.11.2 Switch housing to mine body bond strength. - The mine body shall be tested using an approved fixture and as specified in drawing (dwg.) 9281630. Any item failing to comply with the specified requirement shall be classed defective."

Paragraph 4.4.11.3, Add after "one (1) inch per minute" - "The body shall be measured and examined for separation after the minimum force has been applied. The force shall then be increased in value until separation occurs. Variable data shall be accumulated and sent to the Contracting Officer in accordance with 3.6 and 6.4".

Paragraph 4.4.13.3 delete and substitute:

"4.4.13.3 Leakage Test. - The mine metal parts assembly shall be pressurized in the fuze well cavity, submerged in water, and observed for evidence of leaks at the pressure plate and retainer assembly and the bore rider. The assembly shall be classed defective if the assembly shows leakage at any location."

Add new paragraph 4.4.13.4:

"4.4.13.4 Maximum Profile Test. - The fins shall be folded in accordance with the applicable drawing and placed in a gage that measures all of the maximum profile dimensions in accordance with the applicable drawing. Any sample failing to comply with all of the specified dimensions shall be classed defective."

Paragraph 4.4.13.5, delete.

Paragraph 4.4.15, delete.

Add new paragraph 4.4.16:

"4.4.16 Battery Cap Assembly Continuity Resistance. - The resistance between the threads and inside of snap cap shall be measured using an ohmmeter. Any assembly with resistance exceeding the specified value shall be classed defective."



Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:21Z
Check the source to verify that this is the current version before use.

Add new paragraph 4.4.17:

"4.4.17 Fuze Cover Continuity Resistance. - The resistance between the battery contact area and any screw hole shall be measured with an ohmmeter. A minimum of three (3) holes shall be tested for the resistance. Any fuze cover with resistance exceeding the specified value shall be classed defective."

Asterisks (*) denotes changes in addition to or different from Amendment 8 dated 23 July 1975. This was done as a convenience only and the Government assumes no liability whatsoever for any inaccuracies in these notations. Contractors are cautioned to evaluate the requirements of this document based on the entire content irrespective of the marginal notations and relationship to the last previous issue.

Custodian:
Army-PA

Preparing Activity:
Army-PA

Project Number: 1345-A-152



Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:21Z
Check the source to verify that this is the current version before use.