MILITARY SPECIFICATION

ADAPTION KIT, WH, GM, M75 WITH AUXILIARIES PACKAGES 1, 2, and 4 of 4

1. SCOPE

1.1 This specification covers requirements, quality assurance provisions, and the preparation for delivery criteria for three packages of the four packages that make up the adaption kit and auxiliaries, less fuze and power supply, entitled Adaption Kit, WH, GM, M75 with Auxiliaries Packages 1, 2 and 4 which are used with the Nike Hercules warhead section.

2. APPLICABLE DOCUMENTS

2.1 The following documents, of the issue in effect on date of invitation for bids or request for proposals, form a part of this specification to the extent specified herein:

SPECIFICATIONS

MILITARY

MIL-P-116	- Preservation, Methods of
MIL-B-48817	- Baroswitch Assembly, M5.
MIL-C-48838	- Cartridge Assembly, M75.
MIL-T-48824	- Tube, Static, Self-Aligning, M2.

STANDARDS

MILITARY

MIL-STD-105	- Sampling Procedures and Tables for Inspection by Attributes.
MIL-STD-1168	- Lot Numbering of Ammunition.

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:41Z
Check the source to verify that this is the current version before use.

DRAWINGS

ORDNANCE CORPS

8800030 - Static Tube M2.
8801504 - Ring Adapter.
8801619 - Bracket Capacitor No 2.
8801744 - Bag, Packaging Ammunition, for Cable Assembly W6-F.
8801752 - Bag, Packaging Ammunition, for Cable Assembly Special Purpose Electrical Bundle W5-F.
8801762 - Carton, Packaging Ammunition for Destructor Lead Assembly.
8801763 - Bag, Packaging, for Handling Ring Adapter to Warhead.
8801764 - Bag, Packaging, for Handling Ring Adapter to Missile.
8801765 - Bag, Packaging, Ammunition for A.K. to Warhead.
8806600 - Bags, Packaging for Repair Parts.
8806618 - Bags, Packaging for Spare Parts and A.K. Parts.
8824887 - Carton Packaging Ammunition for Parts for AK M75E1 and Guided Missile.
8824888 - Box, Packaging Ammunition for Parts for AK M75E1 and Guided Missile.
8824890 - Container Metal Ammunition for AK M75 Guided Missile, Package 2 of 4.
8824891 - Container Metal Ammunition for AK, M75 Guided Missile, Package 1 of 4.
8824892 - Packing for AK Atomic Warhead to Guided Missile: M75.
8825013 - Cartridge Assembly: M75E1.
8825064 - Adaption Kit, WH, GM, M75.
EL-8828891 - Equipment List.

PURCHASE DESCRIPTIONS

HARRY DIAMOND LABORATORIES

TL-PA-79 - Safing-Arming Device, Atomic Weapon: XM36.

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:41Z
Check the source to verify that this is the current version before use.

(Copies of specifications, standards, drawings, and publications required by suppliers in connection with specific procurement functions should be obtained from the procuring activity or as directed by the contracting officer.)

3. REQUIREMENTS

3.1 Materials. The contractor shall furnish objective evidence (see 6.2) that the material complies with the specifications listed on the applicable drawing.

3.2 Assembly. The adaption kit shall comply with all requirements specified on the drawing (dwg)8825064, with all requirements specified herein, and with the requirements of all applicable specifications to the extent specified on the drawing and herein.

3.3 First article testing. Requirements for the submission of first article samples by the contractor shall be as specified in the contract (see 4.2).

3.4 Auxiliaries. The following auxiliaries shall comply with all requirements specified in the following specifications:

a. Cartridge Assembly: M75 - MIL-C-48838
b. Tube, Static, Self-Aligning, M2- MIL-T-48824
c. Safing-Arming Device: M36 - TL-PD-79
d. Baroswitch Assembly, M5 - MIL-B-48817

3.5 Leakage. The container shall not exhibit any loss of pressure during a 30 minute period when tested as specified in 4.4.1.

3.6 Workmanship.

3.6.1 Plastic and metal characteristics. All components shall be free from cracks, splits, cold flow, shrinkage, cold shuts, inclusions, porosity, or any similar characteristic.

3.6.2 Threads. Threads shall be full and undamaged for the entire minimum length or depth as required on the applicable drawing.

3.6.3 Burrs. Parts shall be free from burrs.

3.6.4 Foreign matter. Parts shall be free from chips, dirt, grease, rust, corrosion, or any embedded foreign material.

3.6.5 Cleaning. The cleaning method shall not be injurious to any of the parts, nor shall the parts be contaminated by the cleaning agent.

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:41Z
Check the source to verify that this is the current version before use.

3.6.6 Electrical. Cable assemblies and wires shall be dressed in such a manner as to prevent pinching or chafing of the wire insulation. Ends of wires shall be free from burrs, sharp edges, or points. All parts shall be free from flux, chips, dirt, grease, rust or foreign material.

4. QUALITY ASSURANCE PROVISIONS

4.1 Responsibility for inspection. Unless otherwise specified in the contract or purchase order, the supplier is responsible for the performance of all inspection requirements as specified herein. Except as otherwise specified in the contract or order, the supplier may use his own or any other facilities suitable for the performance of the inspection requirements specified herein, unless disapproved by the Government. The Government reserves the right to perform any of the inspections set forth in the specification where such inspections are deemed necessary to assure supplies and services conform to prescribed requirements.

4.2 First article inspection.

4.2.1 Quantity to be submitted. When the contract requires first article inspection, the contractor shall submit 1 complete assemblies (see dwg 8825064) for first article testing to the testing facility designated in the invitation for bids or request for proposal.

4.2.2 Inspection and testing to be performed. The first article inspection sample shall be subjected to the inspections and tests specified in Table I. Tests shall be conducted in order specified in Table I.

Table I

First article inspection and tests

Inspection or Test	Dest	Non-Dest
1. Classification of characteristics (see 4.3.2.1)		X
2. Leakage (see 3.5)		X

4.2.3 Inspection equipment. The inspection and testing specified in 4.2.2 shall be accomplished by using the gages and test equipment specified in 4.3.4.1.

4.2.4 Rejection. If any item fails to comply with any of the applicable requirements, the first article sample shall be rejected.

4.3 Quality conformance inspection.

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:41Z
Check the source to verify that this is the current version before use.

4.3.1 Lot formation.

4.3.1.1 Production lot. A lot shall consist of parts and assemblies produced by one manufacturer in one unchanged process, in accordance with the same drawing, same drawing revision, same specification and same specification revision. Drawing, specification and process changes not affecting safety, performance, storage, or interchangeability, as determined by the Government, shall not necessitate changing the lot interfix number. The criteria and procedures for the assignment of lot numbers shall be in accordance with MIL-STD-1168.

4.3.1.2 Inspection lot. A lot or batch and its formation, size, and presentation is described in MIL-STD-105, Section 5. Accordingly, a lot shall mean an inspection lot and a batch shall mean an inspection batch for the purpose of this specification. The manner in which each inspection lot or batch is to be presented and identified by the contractor, shall be designated or approved by the Government representative.

4.3.2 Product inspection examination. Critical characteristics shall require 100 percent inspection of all items in the inspection lot. A sample shall be selected at random from each inspection lot in accordance with the applicable major or minor characteristic table (see Table II and Table III), and inspected for all characteristics in the applicable classification. Any characteristics in the sample found to be defective shall reject the inspection lot. Sequence for the inspection of characteristics in each classification need not be followed as long as all characteristic inspections are performed.

Table II
Major Characteristics

Lot Size	Sample Size	Lot Size	Sample Size	Lot Size	Sample Size	Lot Size	Sample Size
1-16	all	28-29	23	52-56	31	132-156	39
17	16	30-31	24	57-62	32	157-191	40
18	17	32-34	25	63-69	33	192-244	41
19-20	18	35-36	26	70-76	34	245-334	42
21	19	37-40	27	77-86	35	335-519	43
22-23	20	41-43	28	87-97	36	520-1120	44
24-25	21	44-47	29	98-112	37	over 1120	45
26-27	22	48-51	30	113-131	38		

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:41Z
Check the source to verify that this is the current version before use.

Table III
Minor Characteristics

Lot Size	Sample Size	Lot Size	Sample Size	Lot Size	Sample Size	Lot Size	Sample Size
1-9	all	14-16	12	28-33	16	77-121	20
10	9	17-18	13	34-41	17	122-273	21
11	10	19-22	14	42-54	18	over 273	22
12-13	11	23-27	15	55-76	19		

4.3.2.1 Classification of characteristics (see 3.2). Critical, major and minor characteristics are defined in MIL-STD-105. Inspection shall be conducted as follows:

4.3.2.1.1 Bags and intermediate bags, prior to sealing package 1 of 4 (see dwg 8806600, 8801766, 8801619, 8801752, 8801744, 8806602, 8806618, 8801763, 8801762, 8801765, and 8801764 covering a detail of dwg 8824891).

Categories	Characteristics	Method of Inspection
Critical:	None defined.	
Major:		
***101.	Height of pin(s) (pins of the same diameter must all appear to be within 1/16 inch in height relative to adjacent pins)	Visual
*102.	Any pin bent	Visual
*103.	Foreign material on pin or insert unless removable	Visual
*104.	Any pin missing (as evidenced by empty hole in insert)	Visual
*105.	Portion of the connector or coupler broken away (minor chips, scratches, burrs, or gouges that do not affect the mating are not objectionable)	Visual
106.	Creak in any component part	Visual
*107.	Connector, coupler or cap deformed	Visual
108.	Threads damaged to the extent of preventing subsequent assembly	Visual
*109.	Coupler missing	Visual
*110.	Streamer missing or of incorrect color	Visual
111.	Incorrect component or quantity missing from bag	Visual

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:41Z
Check the source to verify that this is the current version before use.

112.	Any packing component or quantity missing from bag	Visual
113.	Tape missing or inadequate (as applicable)	Visual
*114.	Tape in contact with rubber or metal of cable assembly (as applicable)	Visual
*115.	Cable improperly coiled (as applicable)	Visual
116.	Desiccant bag torn or missing	Visual
117.	Humidity indicator card missing	Visual
*118.	Cable crushed, torn and/or cut extending into individual lead	Visual
*119.	Torn or frayed insulation on cables	Visual
*120.	Marking, misleading, unidentifiable or mislocated (incorrect, incomplete, superimposed or otherwise smeared)	Visual
*121.	Key slot missing	Visual
122.	Objective evidence relating to material missing or improper (see 3.1)	Visual

Minor:

201.	Evidence of poor workmanship (see 3.6)	Visual

4.3.2.1.2 Bags and intermediate bags, sealed, package 1 of 4 (see dwgs 8806600, 8801766, 8801752, 8801744, 8806618, 8801763, 8801765, and 8801764 covering a detail of dwg 8824891).

Categories	Characteristics	Method of Inspection

Critical: None defined.

Major:

101.	Bag torn or perforated	Visual
102.	Seal mislocated	Visual
103.	Bag insecurely sealed	Visual

Minor: None defined.

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:41Z
Check the source to verify that this is the current version before use.

4.3.2.1.3 Carton, prior to sealing, package 1 of 4 (see dwg 8824887, covering a detail of dwg 8824891).

Categories	Characteristics	Method of Inspection
Critical:	None defined.	
Major:		
	101. Bottom flaps not secured	Visual
	102. Any required bag of components missing	Visual
	103. Cushioning material missing	Visual
	104. Packing list missing or mutilated	Visual
	105. Incorrect number desiccant bags or desiccant bag mutilated	Visual
	106. Objective evidence relating to material missing or improper (see 3.1)	Visual
Minor:		
	201. Evidence of poor workmanship (see 3.6)	Visual

4.3.2.1.4 Carton sealed, package 1 of 4 (see dwg 8824887 covering a detail of dwg 8824891).

Categories	Characteristics	Method of Inspection
Critical:	None defined.	
Major:		
	101. Marking missing, misleading or unidentifiable (incomplete, incorrect, superimposed or otherwise smeared)	Visual
	102. Carton damaged to extent that the contents are exposed (sealed bag exposed)	Visual
	103. Sealing strip missing or partially detached	Visual
	104. Contents loose in carton (sufficiently loose to jeopardize contents)	Manual
	105. Bag of screw wrench missing or improperly secured	Visual
Minor:		
	201. Evidence of poor workmanship (see 3.6)	Visual

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:41Z
Check the source to verify that this is the current version before use.

4.3.2.1.5 Cartridge assembly, prior to assembling cap or cover and prior to assembling into container (see dwg 8825013 covering a detail of dwg 8824891).

Categories		Characteristics	Method of Inspection
Critical:		None defined.	
Major:			
	101.	Any pin(s) bent	Visual
	***102.	Height of pins (pins of the same diameter must all appear to be within 1/16 inch in height relative to adjacent pins)	Visual
	103.	Pin missing from insert	Visual
	104.	Foreign material on pin, insert, insert hole or socket unless removable	Visual
	105.	Crack in pin, insert, coupling ring, shell or fuze	Visual
	106.	Portion of shell or coupling ring broden away (minor chips, scratches, burrs or gouges that do not affect the mating are not abjectionable)	Visual
	107.	Socket, coupling ring or shell deformed	Visual
	108.	Coupling ring thread damaged (if applicable)	Visual
	109.	Coupling ring missing (if applicable)	Visual
	110.	Chips or gouges	Visual
	111.	Any socket missing (as evidenced by empty hole in insert)	Visual
	****112.	Depth of socket(s) (female sockets of the same diameter must all appear to be within 1/16 inch in depth relative to adjacent sockets)	Visual
	113.	Objective evidence relating to material missing or improper (see 3.1)	Visual
Minor:			
	201.	Evidence of poor workmanship (see 3.6)	Visual

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:41Z
Check the source to verify that this is the current version before use.

4.3.2.1.6 Cartridge assembly, prior to assembling into container (see dwg 8825013 covering a detail of dwg 8824891).

Categories	Characteristics	Method of Inspection
Critical:		
**1.	Improper fuse in 2 amp, 5 amp, or 10 amp fuse holders	Visual/Manual
Major:		
101.	Assembly damaged	Visual
102.	Protective coating damaged to the extent of exposing bare metal	Visual
103.	Marking missing, misleading or unidentifiable (incorrect, incomplete, superimposed or otherwise smeared)	Visual
104.	Air intake valve damaged to the extent it will affect mating	Visual
105.	Cap or cover missing	Visual
106.	Objective evidence relating to material missing or improper (see 3.1)	Visual
Minor:		
201.	Evidence of poor workmanship (see 3.6)	Visual

4.3.2.1.7 Container, prior to sealing package 1 of 4 (see dwg 8824891).

Categories	Characteristics	Method of Inspection
Critical:	None defined.	
Major:		
101.	Cartridge assembly missing or improperly positioned	Visual
102.	Spacer damaged, improperly positioned or insecure	Visual
103.	Any packing material missing	Visual
104.	Carton of accessories missing or improperly positioned	Visual
105.	Incorrect number of desiccant bags or desiccant bags mutilated	Visual
106.	Carton damaged or improperly positioned	Visual

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:41Z
Check the source to verify that this is the current version before use.

107. Packing list missing or mutilated.....Visual
108. Humidity indicator missing or of incorrect color.....Visual
109. Objective evidence relating to material missing or improper (see 3.1).....Visual

Minor:
201. Evidence of poor workmanship (see 3.6).....Visual

4.3.2.1.8 Container sealed, package 1 of 4 (see dwg 8824891).

Categories	Characteristics	Method of Inspection
Critical:	None defined.	
Major:		
	101. Container fractured	Visual
	102. Coating damaged (exposing bare metal)	Visual
	103. Car seal missing, misleading or unidentifiable	Visual
	104. Marking missing, misleading or unidentifiable (incorrect, incomplete, superimposed or otherwise smeared)	Visual
	105. Cover loose	Visual/Manual
	106. Humidity indicator missing or color changed by moisture	Visual
Minor:		
	201. Evidence of poor workmanship (see 3.6)	Visual

4.3.2.1.9 Static Tube M2 prior to packing, package 2 of 4 (see dwg 8800030).

Categories	Characteristics	Method of Inspection
Critical:	None defined.	
Major:		
	101. Static probe or vanes bent or deformed	Visual
	102. Incomplete brazing of vanes	Visual

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:41Z
Check the source to verify that this is the current version before use.

103. Foreign matter in orifices unless removable.....Visual
104. Orifice openings deformed.....Visual
105. Corrosion or fungus growth.....Visual
106. Any component missing, loose or damaged.....Visual/Manual
107. Objective evidence relating to material missing or improper (see 3.1).....Visual

Minor:
201. Evidence of poor workmanship (see 3.6).....Visual

4.3.2.1.10 Container, prior to scaling (see dwg 8824890 covering a detial of dwg 8824892).

Categories	Characteristics	Method of Inspection

Critical: None defined.

Major:
101. Static tube damaged or missing.....Visual
102. Allen wrench missing, improperly positioned or taped.....Visual
103. Desiccant bags missing, torn, improperly positioned or taped.....Visual
104. Container insert assembly damaged or improperly seated.....Visual
105. Center support damaged or improperly positioned.....Visual
106. End wrench missing or improperly bolted.....Visual
107. Any packing material missing.....Visual
108. Casket missing or improperly positioned.....Visual
109. Static tube improperly aligned and secured.....Visual/Manual
110. Packing list missing or mutilated.....Visual
111. Objective evidence relating to material missing or improper (see 3.1).....Visual

Minor:
201. Evidence of poor workmanship (see 3.6).....Visual

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:41Z
Check the source to verify that this is the current version before use.

4.3.2.1.11 Container, sealed package 2 of 4 (see dwg 8824890 covering a detail of dwg 8824892).

Categories	Characteristics	Method of Inspection
Critical:	None defined.	
Major:		
	101. Container fractured	Visual
	102. Car seal missing, unsealed, broken or mislocated	Visual
	103. Marking incorrect, mislocated or unidentifiable (incorrect, incomplete superimposed or otherwise smeared)	Visual
	104. Contents loose to the extent of being in jeopardy	Manual
	105. Cover loose or improperly assembled	Visual/Manual
	106. Protective coating of container damaged (bare spots)	Visual
Minor:		
	201. Car seal camaged or mislocated	Visual
	202. Evidence of poor workmanship (see 3.6)	Visual

4.3.2.1.12 Ring, adapter prior to wrapping, package 4 of 4 (see dwg 8801504).

Categories	Characteristics	Method of Inspection
Critical:	None defined.	
Major:		
	101. Foreign material in holes unless removable	Visual
	102. Ring distorted or cracked	Visual
	103. Protective coating damaged to the extent of exposing bare metal	Visual
	104. Marking missing, misleading or unidentifiable (incomplete, incorrect, superimposed or otherwise smeared)	Visual
	105. Objective evidence relating to material missing or improper (see 3.1)	Visual

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:41Z
Check the source to verify that this is the current version before use.

Minor:
201. Evidence of poor workmanship (see 3.6).....Visual

4.3.2.1.13 Ring, adapter prior to securing in carton, package 4 of 4 (see dwg 8824888, covering a detail of dwg 8824892).

Categories	Characteristics	Method of Inspection
Critical:	None defined.	
Major:		
101.	Barrier material torn or perforated	Visual
102.	Taping incomplete	Visual
Minor:	None defined.	

4.3.2.1.14 Carton, sealed (see dwg 8824888 covering a detail of dwg 8824892).

Categories	Characteristics	Method of Inspection
Critical:	None defined.	
Major:		
101.	Tape improperly secured	Visual
102.	Marking missing, misleading or unidentifiable (incomplete, incorrect, superimposed or otherwise smeared)	Visual
103.	Carton fractured exposing conetnts	Visual
Minor:	None defined.	

4.3.2.1.15 Box open package 4 of 4 (see dwg 8824888 covering a detail of dwg 8824892).

Categories	Characteristics	Method of Inspection
Critical:	None defined.	
Major:		
101.	Carton containing adapter ring missing	Visual
102.	Any required packing material missing	Visual

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:41Z
Check the source to verify that this is the current version before use.

103. Packing list missing or mutilated.....Visual
104. Objective evidence relating to material missing or improper (see 3.1).....Visual

Minor:
201. Evidence of poor workmanship (see 3.6).....Visual

4.3.2.1.16 Box, sealed package 4 of 4 (see dwg 8824888 covering a detail of dwg 8824892).

Categories	Characteristics	Method of Inspection
Critical:	None defined.	
Major:		
	101. Hardware or strapping missing, broken or loose	Visual/Manual
	102. Strapping mislocated	Visual
	103. Car seals missing, broken or unsealed	Visual/Manual
	104. Marking missing, mislocated on unidentifiable (incorrect, incomplete, superimposed or otherwise smeared)	Visual
	105. Box broken, board split, nail protruding	Visual
	106. Contents loose to the extent of being in jeopardy	Visual/Manual
Minor:		
	201. Evidence of poor workmanship (see 3.6)	Visual

*Applicable to electrical plugs and/or cables.

**One fuse at a time shall be removed, inspected and replaced before removing a second fuse.

***In the event pin(s) do not appear to be within 1/16 inch in height relative to the adjacent pins, Gage (see 4.3.4.1) shall be used to determine the variation from the normal height. Reject any pin that varies by more than 0.063 inch max. from the normal pin height of the individual connector. The normal height of the individual connector pins shall be determined by calculating the average height from measurements taken of pins adjacent to the pin that appears to be defective. The forward metal edge of the connector shall be utilized as the reference surface of all measurements of pin heights.

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:41Z
Check the source to verify that this is the current version before use.

****In the event socket inserts do not appear to be within 1/16 inch in depth relative to the adjacent socket, Gage (see 4.3.4.1) shall be used to determine the variation from the normal depth. Reject any insert that varies by more than 0.063 inch max. from the normal socket insert depth of the individual connector. The normal depth of the individual connector sockets shall be determined by calculating the average depth from measurements taken of sockets adjacent to the socket that appears to be defective. The forward edge of the connector insert shall be utilized as the reference surface for all measurements of connector socket depths.

4.3.3 Testing. All tests shall be performed. Tests shall be performed in the order specified below:

Test	Test classification
a. Leakage	Major

None of these tests are considered destructive and samples so tested may be returned to the lot.

4.3.3.1 Leakage. Each metal container in the lot shall be tested in accordance with 4.4.1. If any item fails to comply with 3.5, the item shall be rejected and removed from the lot.

4.3.4 Acceptance inspection equipment.

4.3.4.1 Critical and major characteristics and tests. Inspection and testing shall be performed with the acceptance inspection equipment, operating instructions, and calibration instructions specified on the Equipment Lists (EL) (See EL-8828891). When either of the conditions listed below exist, the contractor shall design required equipment or specify suitable commercial equipment and obtain approval prior to use on the contract.

a. Any deviation from equipment or procedures specified on the EL is desired (see 6.3).
b. The code "CD" is listed in the "Part or Identifying Number" column on the EL (see 6.1.2).

4.3.4.2 Minor characteristics and tests. Acceptance inspection equipment for minor characteristics is not specified on ELs. The acceptance inspection equipment, operating instructions and calibration instructions used by the contractor for minor classification inspection shall be approved by the Government representative authorized by the procuring agency.

4.4 Test methods. The tolerances specified herein are absolute with no allowance for test equipment inaccuracy. The tolerances used by the manufacturer shall be equal to the absolute tolerances less the accuracy tolerances of the test equipment used.

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:41Z
Check the source to verify that this is the current version before use.

4.4.1 Leakage.

4.4.1.1 Method I. The equipment shall be set up with the test chamber connected to an air supply and a measuring device (manometer) as shown on Figure 1. Testing shall be in accordance with the applicable operating procedures.

4.4.1.2 Method II. The container shall be tested in accordance with the pressure retention test specified in MIL-P-116, paragraph 4.4.3.5, except that the containers shall not be submerged in water.

5. PREPARATION FOR DELIVERY

5.1 Packing and Marking. Not applicable.

6. NOTES

6.1 Ordering data. Procurement documents should specify the title, number and date of this specification.

6.2 Objective evidence. Records of contractor quality control and inspections which can be verified.

6.3 Acceptance inspection equipment (see 4.3.4.1). The contractor shall obtain approval from the Commander, Picatinny Arsenal, Dover, New Jersey 07801, ATTN: SARPA-QA-T.

6.4 Supersession data. This specification supersedes the requirements of Purchase Description PA-PD-1753 Rev 2 dated 12 October 1962.

Custodian:
Army - PA

Preparing activity:
Army - PA

Project No. 1135-A205

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:41Z
Check the source to verify that this is the current version before use.

STANDARDIZATION DOCUMENT IMPROVEMENT PROPOSAL

OMB Approval
No. 22-R255

INSTRUCTIONS: The purpose of this form is to solicit beneficial comments which will help achieve procurement of suitable products at reasonable cost and minimum delay, or will otherwise enhance use of the document. DoD contractors, government activities, or manufacturers/vendors who are prospective suppliers of the product are invited to submit comments to the government. Fold on lines on reverse side, staple in corner, and send to preparing activity. Comments submitted on this form do not constitute or imply authorization to waive any portion of the referenced document(s) or to amend contractual requirements. Attach any pertinent data which may be of use in improving this document. If there are additional papers, attach to form and place both in an envelope addressed to preparing activity.

DOCUMENT IDENTIFIER AND TITLE

NAME OF ORGANIZATION AND ADDRESS

CONTRACT NUMBER

MATERIAL PROCURED UNDER A

☐ DIRECT GOVERNMENT CONTRACT ☐ SUBCONTRACT

1. HAS ANY PART OF THE DOCUMENT CREATED PROBLEMS OR REQUIRED INTERPRETATION IN PROCUREMENT USE?

A. GIVE PARAGRAPH NUMBER AND WORDING.

B. RECOMMENDATIONS FOR CORRECTING THE DEFICIENCIES

2. COMMENTS ON ANY DOCUMENT REQUIREMENT CONSIDERED TOO RIGID

3. IS THE DOCUMENT RESTRICTIVE?

☐ YES ☐ NO *(If "Yes", in what way?)*

4. REMARKS

SUBMITTED BY *(Printed or typed name and address - Optional)*

TELEPHONE NO.

DATE

DD FORM 1 JAN 72 1426 REPLACES EDITION OF 1 JAN 68 WHICH MAY BE USED

Source: https://assist.dla.mil Downloaded: 2026-Mar-27 14:41:12
Check the source to verify that this is the current version before use.