INCH-POUND

MIL-M-83521/4(USAF)
AMENDMENT 1
5 September 2003

DETAIL SPECIFICATION SHEET

MAINTENANCE KITS, ELECTRICAL CONNECTORS, CONTACTS,
AND CONNECTOR AND CABLE ACCESSORIES:
MAINTENANCE KIT FOR PAVE SPIKE SYSTEM

This amendment forms a part of MIL-M-83521/4(USAF), dated 29 March 1991,
and is approved for use by all Departments and Agencies of the Department of Defense.

PAGE 30

Table 1, fourth column: Delete “M24308/16-2”; delete “M24308/16-3”; delete “M24308/16-4”; delete “M24308/16-5”.

PAGE 32

Table 1, second column: Delete “M81511/46FG01( )” and substitute “MS3433( )”; delete “M81511/46FJ01( )” and substitute “MS3433( )”; delete “M81511/46FD02( )” and substitute “MS3433( )”; delete “M81511/46FE02( )” and substitute “MS3433( )”; delete “M81511/46FD03( )” and substitute MS3433( )”; delete “M81511/46FH04( )” and substitute MS3433( )”.
Table 1, bottom row, cable group B: Delete “M81044/18-22”; delete “M27500-22RC1S6” and substitute “NEMA-WC27500( ).

PAGE 33

Table 1, second column: Delete “M83723/52 & /53” and substitute MS3459”.

PAGE 46

Requirements, materials, insert and retainer pad: Delete “PPP-C-1752” and substitute “A-A-59135 and A-A-59136”.


DISTRIBUTION STATEMENT A. Approved for public release; distribution is unlimited.

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T08:34Z
Check the source to verify that this is the current version before use.

CONCLUDING MATERIAL

Custodians:
Air Force - 11
DLA - CC

Review activities:
Air Force - 19, 99

Preparing activity:
DLA - CC

(Project 5935-4423-003)



Source: https://assist.dla.mil -- Downloaded: 2026-10-23T08:34Z
Check the source to verify that this is the current version before use.