QUALIFICATIONS CERTIFIED
APRIL 1990

QPL-7873-22
29 July 992
SUPERSEDING
QPL-7873-21
2 MAY 1990

# QUALIFIED PRODUCTS LIST

OF

PRODUCTS QUALIFIED UNDER MILITARY SPECIFICATION

MIL-N-7873 FSC 5310

NUT, SELF-LOCKING, 1200°F

This list has been prepared **for use by or for the Government in the acquisition of products covered by the subject specification and such listing of a product is not intended to and does not connote endorsement of the product by the Department of Defense. All products listed herein have been qualified under the requirements for the product as specified in the latest effective issue of the applicable** specification. This list is subject to change without notice; revision or amendment of this list wi1l be Issued as necessary. The Iistlng of a **product does not release the supplier** from compliance **with the** specification requirements.

**THE ACTIVITY RESPONSIBLE FOR** THIS QUALIFIED PRODUCTS LIST IS THE NAVAL AIR SYSTEMS **COMMAND (ATTENTION: COMMANDING** OFFICER, NAVAL AIR WARFARE CENTER AIRCRAFT DIVISION LAKEHURST, (CODE SR3), LAKEHURST, NJ 08733-5100)

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION | TEST OR QUALIFICATION REFERENCE | MANUFACTURER'S NAME AND ADDRESS |
|---|---|---|---|
| MS20500-428 | H19475-4 | Report No. NAMC-AML-AE6201 .40 Part XVI of 14 Mar 1961 | Kaynar Mfg. Co., **Inc. Division of Microdot Inc. 800 South State College** Blvd. P.O. Box 3001 Fullerton, CA 92634-3001 Plant: Same address |
| MS2050O-1032<br>MS20500-524 | H19475-3<br>H19475-5 | Report No. NAMC-AML-1391 of 15 Feb 1962 | |
| **MS20500-624** | **H19475-6** | AMD Report No. MA770 522 of 20 Ott 1970 | |

Note: Manufacturing process for all nuts listed: Forged.

AMSC N/A



DISTRIBUTION STATEMENT A. Approved for public release; distribution is unlimited"

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:07Z
Check the source to verify that this is the current version before use.

| GOVERNMENT DESIGNATION | MANUFACTURER' S OESIGNATION | TEST OF QUALIFI-CATION REFERENCE | MANUFACTURER'S NAME AND ADDRESS |
|---|---|---|---|
| MS20500-918<br>MS20500-1018<br>MS20500-1216<br>MS20500-1414 | 99F12-918<br>99F12-1018<br>99F12-1216<br>99F12-1414 | NADC Report No. 305Q82075 of 9 Apr 1982 | SPS Technologies<br>Highland Avenue<br>Jenkintown, PA 19046<br>Plant: Same address |
| Note: Manufacturlng process: Machined. | | | |
| MS20500-1032<br>MS20500-428<br>MS20500-524<br>MS20500-624<br>MS20500-720A<br>MS20500-820 | 99F12-1032<br>99F12-428<br>99F12-524<br>99F12-624<br>99F12-72OUN<br>99F12-820 | AML NAM AE6221.1 | |
| MS205OO-1032<br>MS20500-428<br>MS20500-524<br>MS20500-624<br>MS20500-720<br>MS20500-720A<br>MS20500-820 | 1802-02<br>1802-048<br>1802-054<br>1802-064<br>1802-070<br>1802-070U<br>1802-080 | AML NAM AE6221.2 | Elastic Stop Nut<br>A Division of Harvard Industries, Inc.<br>2330 Vauxhall Road<br>Union, NJ 07083<br>Plant: Same address |
| MS20501-832<br>MS20501-1032<br>MS20501-428<br>MS20501-524 | ZA1913W-82<br>ZA1913W-02<br>ZA1913W-048<br>ZA1913W-054 | Report No. AML 6201.40 Part I of 2 Mar 1959 | |
| MS20501W832<br>MS20501W1032<br>MS20501W428<br>MS20501W524 | ZA1913WP-82<br>ZA1913WP-02<br>ZA1913WP-048<br>ZA1913WP-054 | Report No. AML 6201.40, Part I of 2 Mar 1959 NAMC ltr XM-621-FTR:mlp J9 (9959) of 30 Mar 1959 | |
| MS20501-624<br><br>MS20501W624 | ZA1913W-064<br>3/8-24UNF-3B<br><br>ZA19131WP-064<br>3/8-24UNF-3B | Report No. NAMC-AML-1522 of 31 Ott 1962 | |
| MS20500-1032<br>MS20500-428<br>MS20500-524 | LH1802-02<br>LH1802-048<br>LH1802-054 | Report No. NAEC-AML-1600 of 6 Feb 1963 | |
| Note: Manufacturing process for all nuts: Machined or forged. | | | |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:07Z
Check the source to verify that this is the current version before use.

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION | TEST OF QUALIFICATION REFERENCE | MANUFACTURER'S NAME AND ADDRESS |
|---|---|---|---|
| **MS20500-918**<br>MS20500-1018<br>MS20500-1216 | **1802-098**<br>1802-108<br>1802-126 | Report No. NAEC-AML-2074 of 3 Dec 1964 | Elasitc Stop Nut (Cond't) |
| **MS20501-832**<br>**MS20501-1032**<br>MS20501-428<br>MS20501-524 | **2700SS-82**<br>**2700SS-02**<br>2700SS-048<br>2700SS-054 | **Report No. NAEC-of 28** Feb 1963 | **SPS Technologies**<br>2701 S. Harbor Blvd.<br>**Santa** Aria, CA 92702<br>Plant: Same address |
| Note: **Manufacturing process** for all nuts: Machined. | | | |
| **MS20500-1032**<br>**MS20500-428**<br>MS20500-524<br>MS20500-624<br><br>Note: Parts machined | **RH20C3**<br>**RH20C4**<br>RH20C5<br>RH20C6 | **305Q79047**<br>of 7 Feb. 1979 | **Republic Fastener**<br>Manufacturing Corp.<br>1300 Rancho Conejo Blvd.<br>Newbury Park, CA 91320<br>**Plant: Same address** |
| **MS20500-1032**<br>**MS20500-428**<br>MS20500-524 | **JL2C1032**<br>**JL2C428**<br>JL2C524 | **601Q9001 of 3** JAN 7990 | |
| **MS20500-428** | **RH20C4** | **601Q9012 of 11 Jun 1990** | |
| NOTE : Manufacturing Process: Forged | | | |
| MS20500-624 | RH20C6 | 601Q9015 of 26 Jul 1990 | |
| NOTE : Manufacturing Process: Forged | | | |

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:07Z
Check the source to verify that this is the current version before use.