MIL-F-50983B (AR)
AMENDMENT 8
22 February 1984
SUPERSEDING
AMENDMENT 7
6 June 1983

MILITARY SPECIFICATION

FUZE, MT, SQ, M577
LOADING, ASSEMBLING, PACKING AND METAL PARTS
FUZE, MT, SQ, M582 METAL PARTS

This amendment forms a part of Military Specification MIL-F-50983B (AR), dated 30 June 1980, and is approved for use by the US Army Armament, Munitions and Chemical Command and is available for use by all Departments and Agencies of the Department of Defense.

PAGE 2

* 3.3: In the last sentence delete, "No worse than depicted in Figure 4" and substitute "as specified on the applicable drawing."

* 3.4: Delete "Tests 101.1" and substitute "Tests 101.2, Procedure II."

* 3.5: Delete "Test 104" and substitute "Test 401, Procedure II."

PAGE 3

* 3.6: Delete "Test 103" and substitute "Test 103.2"

3.7: Delete in its entirety.

PAGE 5

* 3.14: Delete "(Dwg. 9236634)".

* 3.17.2: Delete "Figures 5 and 6" and substitute "Figures 1 and 2".

FSC 1390

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:46Z
Check the source to verify that this is the current version before use.

Add the following new paragraphs:

"3.19 Barrel housing static load. The barrel housing (dwg. 9236688) shall not fracture when a load as specified on the applicable drawing is applied.

3.20 Rotor, SSD (see dwg. 11786092). The rotor teeth shall not fracture when a load as specified on the applicable drawing is applied."

PAGE 6

4.3.1:

To the group entitled 15 each, delete: "9236518".

To the group entitled 15 each, add: "9236729, 9236730 and 9236731".

To the group entitled 15 each, delete: "9236540" and add "11786095."

To the group entitled 50 each, delete: "9236528, 9236537, 9236604" and add "11786090, 11786093 and 9357827."

PAGE 7

4.3.1: To the group entitled 50 each, add "9236712, 9236733".

PAGE 22

4.4.2.13:

Add the following major defects:

Major category:

"Major 103 Die casting defect 10 a 3.17 Visual w/aid C

* Major 104 Static load test 10 a 3.19 4.5.22."

* To the block entitled Notes, add the following:

"a. Reject the lot if one (1) or more defective units are found."

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:46Z
Check the source to verify that this is the current version before use.

Major 104, in the column "No. of Sample Units", add "b" after "10".

To the block entitled Notes, add: "b. Destructive Test".

PAGE 23

* 4.4.2.14: Delete in its entirety.

PAGE 41

* 4.4.2.32: In the block entitled Drawing Number add "9236718".

PAGE 42

* 4.4.2.33: In the block entitled Drawing Number add "9236713".

PAGE 45

4.4.2.36:

To the block entitled Drawing Number, add: "9236712 and 9236733".

To the block entitled Next Higher Assembly, add: "9236711 and 9236732".

* Add the following Major category:

"Major 107: Balance wheel outside tolerance zone 0.40% 3.2 Gage"

In the block entitled Notes, add the following:

"e. Major 102 applies to 9236635 only.

f. Major 107 applies to 9236712 only as applicable."

PAGE 46

4.4.2.37:

To the block entitled Drawing Number, add: "9236732".

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:46Z
Check the source to verify that this is the current version before use.

Add:

Category	Examination	No. of Sample Units	AQL or 100%	Reqmt. Para.	Para. Ref. Insp Method
"112	91b. axial load	d	e	3.2	4.5.1ae".

Note b, add: "and 9236742".

Note c, add "and 9236732".

To block entitled Notes, add "d. Destructive. See paragraph 4.4.3.7 for applicable sample plan."

To block entitled Notes, add "e. Reject the Timer Assembly inspection lot if one (1) or more defective units are found."

PAGE 54

4.4.2.45: In the block entitled Drawing Number, delete "9236619" and substitute "9357826."

PAGE 62

4.4.2.53, add the following Major defects:

Major category:

"Major 107: True position of safety plate pivot hole 0.40% 3.2 Gage"

Major 108: Diameter of safety plate pivot hole, max 0.40% 3.2 Gage."

PAGE 63

4.4.2.54: Delete in its entirety and substitute the following new paragraph 4.4.2.54 included.

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:46Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE		SHEET OF		DRAWING NUMBER
4.4.2.54	Spacer, Trigger				9357827
					NEXT HIGHER ASSEMBLY 9236603
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	True position of top pins		0.40%	3.2	Gage
102	True position of bottom pins		0.40%	3.2	Gage
103	25 lb. axial unseating load on bottom pins	80a	b	3.2	4.5.1.u
104	5 lb. axial unseating load on top pins	80a	b	3.2	4.5.1.v
105	Height of bottom pins above spacer surface		0.65%	3.2	Gage
106	Height of top pins above spacer surface		0.65%	3.2	Gage
107	True position of release lever pivot hole		0.40%	3.2	Gage
108	Diameter of release lever pivot hole,max		0.40%	3.2	Gage
109	Density incorrect	10c	d	3.2	Gage
Minor					
201	Evidence of poor workmanship		1.0%	3.3	Visual

a. Destructive.
b. Reject the lot if two (2) or more defective units are found.
c. Destructive.
d. Reject the lot if one (1) or more defective units are found.
e. Alternative "Compressive Load Test" may be performed in lieu of Inspections 107 and 108. See para. 4.4.2.56 Trigger Assembly.

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:46Z
Check the source to verify that this is the current version before use.

PAGE 64

4.4.2.55: Delete in its entirety.

PAGE 65

* 4.4.2.56: Delete Note b and substitute the following: "b. If the tests of 103, 104 and 105 are performed while the trigger assembly is under the compressive load stipulated on the drawing, then the inspections noted in paragraph 4.4.2.54 and those required by paragraphs 4.4.2.40 and 4.4.2.53 may be omitted.

PAGE 73

4.4.2.64: To block entitled Drawing Number, delete "9236575" and substitute "9345286".

PAGE 74

* 4.4.2.65: Delete Major categories "102" and "103" in their entirety.

PAGE 75

* 4.4.2.66:

Major category 107: Delete "Skirt crimps missing or insecure" and substitute "heat staking missing or insecure".

* Add the following Major categories:

Major category:

Major 114: Hairline not stationary with respect to body and in excess of allowable tolerances 0.40% 3.2 Manual

Major 115: Index lines missing or unreadable 0.40% 3.2 Visual."

Minor defect 108: Delete "9.0 + 4.0 in. lb." and substitute "10.0 + 4.0 in. lb."

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:46Z
Check the source to verify that this is the current version before use.

PAGE 78

4.4.2.68:

To block entitled Drawing Number, delete:"9236562" and substitute "9345287".

Add the following:

Category	Examinations	No. of Sample Units	AQL or 100%	Req'mt Para.	Para Ref Insp. Method
"105	Height of ribs	-	0.40%	3.2	Gage".

PAGE 79

4.4.2.69: Delete in its entirety.

PAGE 80

4.4.2.70: Add the following:

Category	Examination	No. of Sample Units	AQL or 100%	Req'mt Para.	Para. Ref. Insp. Method
"103	Detonator(s) missing or inverted		0.40%	3.2	Visual
104	Crimp missing over detonator holder		0.40%	3.2	Visual
105	Tape missing		0.40%	3.2	Visual
106	Detonator(s) not positioned over MDF		0.65%	3.2	Visual"

PAGE 87

4.4.2.77:

In the block entitled Drawing Number, delete: "9236541" and substitute "11786096".

In the block entitled Next Higher Assembly, delete: "9236540" and substitute "11786095".

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:46Z
Check the source to verify that this is the current version before use.

Delete category 102 in its entirety.

PAGE 88

4.4.2.78:

In the block entitled Drawing Number delete: "9236540" and substitute "11786095".

Delete category 1 in its entirety.

After critical, in the examination or test column, add "None defined."

PAGE 89

4.4.2.79: In the block entitled Next Higher Assembly delete: "9236537" and substitute "11786093".

PAGE 90

4.4.2.80: In the block entitled Drawing Number delete: "9236537" and substitute "11786093".

PAGE 93

4.4.2.83:

In the block entitled Drawing Number delete: "9236529" and substitute "11786091".

In the block Next Higher Assembly delete: "9236528" and substitute "11786090".

PAGE 94

4.4.2.84:

In the block entitled Drawing Number delete: "9236528" and substitute "11786090".

Delete category 101, 102, and 104 and Note "c" in their entirety.

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:46Z
Check the source to verify that this is the current version before use.

PAGE 97

4.4.2.87:

To the block entitled Title, delete: "Element, Crush" and substitute "Plug, Retainer".

To the block entitled Drawing Number, delete: "9236518" and substitute "9236731".

To the block entitled Next Higher Assembly, delete: "9236516" and substitute "9236729".

To the block entitled Examination or Test, delete: "Static Load Test" and substitute "Outside diameter".

To the block entitled No. of Sample Units, delete: "40a".

To the block entitled AQL or 100%, delete: "b" and substitute "0.40%".

To the block entitled Paragraph Reference/Inspection Method, delete: "4.5.1f" and substitute "Gage".

To the block entitled Notes, delete: Note a and Note b in their entirety.

PAGE 98

4.4.2.88:

To the block entitled Drawing Number, delete: "9236516" and substitute "9236729".

To the block entitled Examination or Test, delete: "Crush retainer missing" and substitute "Plug retainer missing".

To the block entitled Examination or Test, delete: "Crush element missing" and substitute "Axial static load test".

Major 102, to the block entitled No. of Sample Units, add "40a".

To the block entitled AQL or 100%, delete: "0.40%" and substitute: "b".

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:46Z
Check the source to verify that this is the current version before use.

To the block entitled Paragraph Reference/Inspection Method, delete "Manual" and substitute "4.5.1.f".

To the block entitled Notes, add: "a. Destructive".

To the block entitled Notes, add: "b. Reject the lot if one (1) or more defective units are found."

PAGE 106

* 4.4.2.96:

Delete in its entirety and substitute new paragraph 4.4.2.96 included.

Delete category 101 in its entirety.

Add the following defect classification:

Ref./ Category	Examination or Test	No. of Units	Sample 100%	AQL or Para.	Req. Insp. Method	Para
Info						
300 Ballistic	ICM Mechanical Time Test	10	-	-		4.5.21.6

PAGE 108

* 4.4.2.98: In the block entitled Drawing Number add "9236720".

Add new paragraphs 4.4.2.100, 4.4.2.101, and 4.4.2.102.

* Add new paragraphs 4.4.2.103 and 4.4.2.104 attached.

* Paragraph 4.4.2.102, in the block entitled "Notes", delete Note b and substitute "b. Destructive Test".

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:46Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE	SHEET	DRAWING NUMBER
4.4.2.96	Fuze Mechanical Time and Superquick, M577/ M582 Destructive Lot Acceptance Test	1 OF 3	9236500/9236700
			NEXT HIGHER ASSEMBLY: Final

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical:					
	Jolt and Jumble Test	f	-	3.4	4.5.16
1	a. Functioning of explosive element				
6	b. SSD rotor gear not located and locked in the safe position by both spin and interlock detents				
7	c. Trigger setback pin and spin detent not secure and in the safe position				
8	d. SSD spin detent broken and the interlock pin not secure and restrained by by the trigger release lever				
9	e. Trigger firing arm assembly not secure and restrained by the release lever				
2	Transportation Vibration Test	g	-	3.5	4.5.17
3	Forty Foot Drop Test	5	h.	3.6	4.4.3.3, 4.5.18
	Proving Ground Test				
4	a. Ballistic impact non-functioning	10.a		3.12.3.1	4.5.21.1
5	b. Premature	70.b		3.12.1	4.5.21
Special					
10	Jolt and Jumble f. Any part broken or damaged	f	-	3.4	4.5.16

NOTES:

DRSMC-OA (D) Form 160, 1 Aug 83 replaces edition of 1 Jul 77 which may be used until exhausted.

Source: https://assist.daiml ... Downloaded: 2020-10-22T20:48Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE	SHEET	DRAWING NUMBER
4.4.2.96	Fuze Mechanical Time and Superquick, M577/ M582 Destructive Lot Acceptance Test	2 OF 3	9236500/9236700
			NEXT HIGHER ASSEMBLY: Final

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Major					
102	Water Proofness Test Proving Ground Test	4	h	3.8	4.4.3.5, 4.5.20
103	c. Ballistic impact functioning	10	-	3.12.3.2	4.5.21.2
104	d. Group reliability	50c	-	3.12.3.3	4.5.21
105	e. Estimated percent defective	50d	-	3.12.3.3	4.5.21
106	f. Off times	50d	i	3.12.3.3	4.5.21
107	g. Fuze setting	70b	i	3.12.2	4.5.21
108	h. Total duds	60e	-	3.12.3	4.5.21
Info					
300	ICM Ballistic Mechanical Time Test	10	-	-	4.5.21.6

NOTES:

a. Samples for this test are transportation vibrated fuzes from Catetory 2. The sample size shall be as specified in Table IV.

b. Samples for this test are those fuzes subject to ballistic impact nonfunctioning, ballistic impact functioning, mechanical time, and extreme temperature test. The sample size shall be as specified in Table IV.

NOTES:

DRSMC-OA (D) Form 160, 1 Aug 83 replaces edition of 1 Jul 77 which may be used until exhausted.

Source: https://assist.dla.mil - Downloaded: 2020-10-22T20:46Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE		SHEET 3 OF 3		DRAWING NUMBER
4.4.2.96	Fuze Mechanical Time and Superquick, M577/ M582 Destructive Lot Acceptance Test				9236500/9236700
					NEXT HIGHER ASSEMBLY: Final
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
	c. Samples for this test are those fuzes subjected to mechanical time and extreme temperature test. The sample size shall be as specified in Table IV, and shall include 10 transportation vibrated fuzes from Category 2. d. Samples are the samples from Category 104. e. Samples for this test are those fuzes subjected to ballistic impact functioning, mechanical time, and extreme temperature test. The sample size shall be as specified in Table IV. f. Sample size shall be as specified in 4.4.3.1. g. Sample size shall be as specified in 4.4.3.2. h. Reject the lot if one (1) or more defective units are found.				

NOTES:

DRSMC-OA (D) Form 160, 1 Aug 83 replaces edition of 1 Jul 77 which may be used until exhausted.

Source: https://assist.dla.mil - Downloaded: 2026-01-22T20:40:40Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-F-50983B (AR)
AMENDMENT 8

PARAGRAPH	TITLE	SHEET OF	DRAWING NUMBER
4.4.2.100	Spacer & Plate Assembly, SSD		9236552
			NEXT HIGHER ASSEMBLY 9236526

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Rotor lock does not return to dimension indicated after being depressed to surface "x".		0.40%	3.2	Gage
Minor					
201	Evidence of poor workmanship		1.0%	3.3	Visual

NOTES:

DRDAR-QA Form 160 Jul 77

14 (109a)

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:46Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE		SHEET OF		DRAWING NUMBER
4.4.2.101	Lever, SSD				11786097
					NEXT HIGHER ASSEMBLY
					11786095
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Profile incorrect		0.40%	3.2	Gage
Minor					
201	Evidence of poor workmanship		1.0%	3.3	Visual

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:46Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-F-50983B (AR)
AMENDMENT 8

PARAGRAPH	TITLE	SHEET OF	DRAWING NUMBER
4.4.2.102	Rotor, SSD		11786092
			NEXT HIGHER ASSEMBLY 11786090

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Die casting defect	10	a	3.17	Visual w/aid C
102	Torque on rotor teeth	10b	a	3.20	4.5.23
Minor					
201	Evidence of poor workmanship		1.0%	3.3	Visual

NOTES:
a. Reject the lot if one (1) or more defective units are found.
b. Non-destructive.

DRDAR-QA Form 160 Jul 77

16 (109c)

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:46Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

MIL-F-50983B (AR)
AMENDMENT 8

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE	SHEET	DRAWING NUMBER
4.4.2.103	Support, End, Timer	1 OF 1	9236715
			NEXT HIGHER ASSEMBLY 9236714

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical:	None defined.				
Major 101	Tube diameter, min.		0.40%	3.2	Gage
Minor 201	Evidence of Poor Workmanship		1.0%	3.3	Visual

NOTES:

DRSMC-OA (D) Form 160, 1 Aug 83 replaces edition of 1 Jul 77 which may be used until exhausted.

(P60I) 17

Source: https://assist.dla.mil -- Downloaded: 2026-03-23T20:43Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE	SHEET	DRAWING NUMBER
4.4.2.104	Support and Pivot Assembly, Timer	1 OF 1	9236714
			NEXT HIGHER ASSEMBLY: 9236712

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical:	None defined.				
Major					
101	3.0 Inch lb torque on hairspring pivot	80a	b	3.2	4.5.2.g
102	15 lb axial load on hairspring, pivot	80a	b	3.2	4.5.1.ar
103	Inside diameter of pivot after staking, min.		0.40%	3.2	Gage
Minor					
201	Evidence of poor workmanship		1.0%	3.3	Visual

NOTES:
a. Non-Destructive.
b. Reject the lot if two (2) or more defect units are found.

DRSMC-OA (D) Form 160, 1 Aug 83 replaces edition of 1 Jul 77 which may be used until exhausted.

Source: https://assist.dla.mil - Downloaded: 2026-10-22 20:48Z
Check the source to verify that this is the current version before use.

PAGE 110

4.4.3.3, delete in its entirety and substitute:

"4.4.3.3 Forty (40) foot drop. Beginning with the first article sample and continuing until three (3) additional consecutive production lots have complied with the acceptance criteria specified herein, a sample as specified in 4.4.2.96 shall be randomly selected from each lot and subjected to the tests as specified in 4.5.18. If one or more assemblies are found defective, the lot shall be rejected. After three consecutive lots are found acceptable, the test shall be discontinued. A first article sample shall be submitted, when necessary, as required by 4.3.1."

4.4.3.3.1, 4.4.3.3.2: Delete in their entirety.

PAGE 111

4.4.3.4, 4.4.3.4.1, 4.4.3.4.2: Delete in their entirety.

PAGE 112

Add: "4.4.3.7 Axial load test. The Timer Hair-spring and Timer Support and Pivot Assembly samples selected for the axial load test shall be randomly selected from each batch used to assemble the Timer Assembly inspection lot. One sample shall be welded at the beginning of the Timer Assembly inspection lot manufacturing period, two samples shall be welded at random times during the period and one sample at the end of the same period. The samples shall contain the number of welds specified on drawing 9236711 and shall be welded on the equipment used to manufacture the Timer Assembly inspection lot using the same equipment lot using the same equipment parameters (tip, frequency, pressure and energy). The equipment parameters used during an inspection lot manufacturing period shall be recorded. If prior to welding the required number of test samples, the inspection lot manufacturing period is interrupted and can not be continued on the same equipment with the same parameters. Timer Assemblies shall be selected from the inspection lot as test samples. The last Timer Assembly of the inspection lot manufacturing period shall be selected and, if necessary, Timer Assemblies shall be randomly selected from the same period. A Timer Assembly inspection lot shall consist of a maximum of two (2) hours production and manufactured on the same equipment and the same equipment parameters".

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:46Z
Check the source to verify that this is the current version before use.

4.5.1:

Table I, subparagraph f, delete: "Crush Element (Dwg. 9236518)" and substitute "Setting Key Assembly (Dwg. 9236729)".

Table I, subparagraph h. and j., delete: in their entirety.

Table I, subparagraph i., delete: "dwg. 9236528" and substitute "dwg. 11786090".

PAGE 115

4.5.1:

Table I, subparagraph l, delete: "dwg. 9236537" and substitute "dwg. 11786093".

Table I, subparagraph m., delete: "dwg. 9236540" and substitute "dwg. 11786095".

Table I, subparagraph q., delete in its entirety.

PAGE 116

4.5.1:

Table I, subparagraph s. delete: in its entirety.

Table I, subparagraph u., delete: "Pin, spacer assembly (dwg. 9236604)" and substitute "Pin, spacer trigger (dwg. 9357827)"

Under Load & Application column, delete: "35 lb." and substitute "25 lb.".

Table I, subparagraph v, delete: "Pin, spacer assembly (dwg. 9236604)" and substitute "Pin, spacer trigger (dwg. 9357827)".

PAGE 117

* 4.5.1:

Table I, subparagraph ab, add: "9236733".

Table I, subparagraph ac, add: "9236733".

Table I, subparagraph ad, add: "9236733".

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:46Z
Check the source to verify that this is the current version before use.

Table I, subparagraph ae, add: "9236733".

Table I, subparagraph ae, delete: "9236712".

PAGE 119

4.5.1, subparagraph ap: Under Load & Application delete: "16 lb." and substitute "15 lb."

PAGE 121

4.5.2, Table II, subparagraph d, add: "9236733".

PAGE 121

4.5.2, Table II, subparagraph c, delete: "9.0 + 4.0 in. lb." and substitute "10.0 + 4.0 in. lb."

PAGE 122

4.5.3, Table III, delete: Subparagraph "d".

PAGE 123

* 4.5.4: Delete all references to "Figure 1.a, 1.b, and 1.c".

* 4.5.5: Delete all references to "Figure 1.a, 1.b, and 1.c".

PAGE 126

* 4.5.16: In the first sentence, delete "Test 101.1" and substitute "Test 101.2, Procedure II."

* Delete all references to "Figure 1.a and Figure 2."

* 4.5.17: In the first sentence, delete "Test 104" and substutute "Test 401."

PAGE 127

* 4.5.18: In the first sentence, delete "Test 103" and substutute "Test 103.2".

4.5.19: Delete in its entirety.

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:46Z
Check the source to verify that this is the current version before use.

* 4.5.21, after the last sentence add the following:

"All fuzes shall be x-rayed and the x-ray films reviewed to assure that the fuzes are safe to fire prior to test. The x-ray films shall demonstrate that the setback pin disc and the SSD rotor gear are in their proper position.

PAGE 129

* 4.5.21.2: Delete the third sentence and substitute the following:

"Closed circuit video coverage shall be employed to observe fuze functioning beyond the screen."

* 4.5.21.3 Delete and substitute the following:

"4.5.21.3 Mechanical time functioning. The fuze assembly shall be set and fired airburst functioning. All fuze settings shall be photographed utilizing an instant, self processing, camera. Three independent infrared sensing chronograph systems shall be used to measure time to burst. The times shall be recorded from the chronograph counters to four decimal places. The three recorded time values for each round are averaged and the average is rounded to the nearest 0.001 second using the method prescribed by the American Society for Testing Materials and recorded. If one time value is lose or is determined to be invalid (see 4.5.21.3.1), the remaining two values are used. If a round fails to function in flight, observations shall be made to determine if the round functions on impact. All defects shall be recorded. A back-up system of electric clocks or stopwatches shall also be employed and their measurements recorded to the nearest 0.01 second; these times shall not be used in computations. Any fuze which does not airburst function shall be classed a time dud (see 6.6)."

PAGE 131

4.5.21.3.4, second and third line: Delete "and the suspect value falls outside the function time limits".

4.5.21.4.1, delete the third sentence and substitute the following:

"The chamber shall then be maintained at $+70^{o}F \pm 10^{o}F$, $145^{o}F\ -5^{o}F$, $-35^{o}F + 5^{o}F$ of the specified temperature (see Table IV)."

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:46Z
Check the source to verify that this is the current version before use.

Add the following new paragraphs:

"4.5.21.6 Improved conventional munitions ballistic mechanical time test (information only). The fuzes shall be assembled to the M483A1 projectile. Five projectiles shall contain inert cargo and contain an expulsion charge. Five projectiles shall be inert loaded and contain a self registration charge. The projectiles shall be fired from the M185 cannon using the M119 series propelling charge. An 82 second fuze time setting shall be used and the fuze time of function or failure to function shall be recorded. The test method for measuring fuze time shall be the same as paragraph 4.5.21.3.

4.5.22 Static load test of barrel housing. The barrel housing shall be placed in a sleeve (dwg. 9236631). The load specified on the drawing shall be applied to the entire barrel housing shoulder at a deflection rate of less than 0.100 inches per second.

4.5.23 Torque of rotor teeth. The rotor shall be placed in a suitable test fixture and the torque specified on the drawing shall be applied. After the test, the rotor teeth shall be examined for compliance with the requirements of 3.20."

Add Figures 1 and 2 attached.

PAGE 133

6.12: Delete "AID A-3X" and "AID B-5" and substutute "AID A-2-1/2X" and "AID B-4X".


The margins of this amendment are marked with an asterisk to indicate where changes (additions, modifications, corrections, deletions) from the previous amendment were made. This was done as a convenience only and the Government assumes no liability whatsoever for any inaccuracies in these notations. Bidders and contractors are cautioned to evaluate the requirements of this document based on the entire content irrespective of the marginal notations and relationship to the last previous amendment.

Custodian:
Army - AR

Preparing activity:
Army - AR

(Project 1390-A408)


Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:46Z
Check the source to verify that this is the current version before use.



FEATURE	MAX SINGLE PORE SIZE IN ANY DIRECTION (IN.)	MIN REMAINING IDEAL SURFACE (%)
HOLE A	.02	90
HOLE B	.02	90
HOLE C	.10	80
HOLE D	.02	90
HOLE E	.10	80
SURFACE F	.02	80
SURFACE G	.02	80
SURFACE H	.02	80

FIGURE 1

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:46Z
Check the source to verify that this is the current version before use.



SURFACE A = NO POROSITY PERMITTED

SURFACE B = NO POROSITY PERMITTED

SURFACE C = NO POROSITY PERMITTED

FIGURE 2

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:46Z
Check the source to verify that this is the current version before use.