NOT MEASUREMENT SENSITIVE

MIL-HDBK-103U
14 SEPTEMBER 2004
SUPERSEDING
MIL-HDBK-103T
17 MARCH 2004

# DEPARTMENT OF DEFENSE
# HANDBOOK
## LIST OF STANDARD MICROCIRCUIT DRAWINGS

**This handbook is for guidance only. Do not cite this document as a requirement.**

**AMSC N/A** **FSC 5962**

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

# FOREWORD

1. This handbook is approved for use by all Departments and Agencies of the Department of Defense.

2. This handbook is for guidance only. This handbook cannot be cited as a requirement. If it is, the contractor does not have to comply.

3. The proliferation of industry prepared drawings for the same part used in a variety of military applications has become an ever increasing item of expense to the DoD. Numerous situations have arisen where one military acquisition document would be more appropriate and cost effective than the multiplicity of contractor prepared drawings. Standard Microcircuit Drawings (SMDs) are being prepared to eliminate the need for the multitude of contractor prepared drawings for the same device when the minimum requirements of SMD's are sufficient to meet the requirements of the application on an interim or permanent basis.

4. Comments, suggestions, or questions on this document should be addressed to: Commander, Defense Supply Center Columbus, ATTN: DSCC-VAS, 3990 East Broad St., Columbus, OH 43218-3990, or emailed to linear@dscc.dla.mil. Since contact information can change, you may want to verify the currency of this address information using the ASSIST online database at www.dodssp.daps.mil.



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

CONTENTS


| PARAGRAPH | | PAGE |
|---|---|---|
| 1. | SCOPE | 1 |
| 1.1 | Purpose | 1 |
| 1.2 | Part or identifying number (PIN) | 1 |
| 1.2.1 | Drawing number | 1 |
| 1.2.2 | Device class designator | 1 |
| 1.2.3 | Case outline / lead finish | 1 |
| 1.2.4 | Substitutability | 1 |
| 2. | APPLICABLE DOCUMENTS | 2 |
| 3. | DEFINITIONS | 2 |
| 4. | REQUIREMENTS | 2 |
| 4.1 | Drawing requirements | 2 |
| 4.2 | Preparation procedures | 2 |
| 4.3 | Drawing effectivity and duration | 2 |
| 4.4 | Approved sources of supply | 2 |
| 4.5 | Radiation hardness assurance (RHA) levels | 2 |
| 4.6 | Electrostatic discharge sensitivity (ESD) listing | 2 |
| 5. | CONFIGURATION MANAGEMENT | 3 |
| 5.1 | Configuration management of SMDs | 3 |
| 5.2 | Record of users | 3 |
| 6. | DISTRIBUTION and REQUESTS | 4 |
| 6.1 | Distribution | 4 |
| 6.1.1 | Automatic distribution | 4 |
| 6.1.2 | Electronic distribution | 4 |
| 6.2 | Requests | 4 |
| 7. | NOTES | 4 |
| 7.1 | Intended use | 4 |
| 7.2 | Subject item (key word) listing | 4 |
| TABLE 1 | Noun code descriptions | 5 |
| SECTION 1 | Microcircuits | 12 |
| Part I | Listed by SMD PIN | 12 |
| Part II | Listed by generic PIN | 620 |
| Part III | Listed approved sources | 804 |
| | Concluding material | 809 |





Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

1. SCOPE


1.1 Purpose. The Standard Microcircuit Drawing Program (SMDP) is directly under the auspices of the DoD Parts Management Program (PMP). The PMP is implemented by MIL-HDBK-512, "Parts Management." The PMP will be the avenue for screening candidate parts for the SMDP by the DSCC Military Parts Control Advisory Group (MPCAG).

1.2 Part or Identifying number (PIN). The PIN's listed in section 1, part I, are composed of the elements shown in the following example (see 1.2.2 for one part - one part number differentiation):

One part - one part number PIN




Non - one part - one part number PIN




1.2.1 Drawing number. One part - one part number SMD's for device classes Q, V, H, and K may cover custom device products which are generally used to specify application specific integrated circuits (both monolithic and hybrid). To differentiate between one part - one part number SMD's that cover standard product from custom product a single alpha character will be placed in the unique 3 digit portion of the SMD drawing number as in the following example: 5962-90A23. This will be the only change to the SMD PIN for custom products.

1.2.2 Device class designator. One part - one part number SMD's (fully implemented after SMD 5962-90659) contain device requirements for all three of the major military microcircuit requirements documents. By establishing a one part number system covering all three documents, the OEM can acquire to the highest level available for a given generic device to meet system needs without modifying the original contract parts selection criteria.

| Military documentation format | Example PIN | Manufacturing source listing | Document listing |
|---|---|---|---|
| New MIL-PRF-38535 Standard Microcircuit Drawings | 5962-XXXXXZZ(Q,V,T or N)YY | QML-38535 | MIL-HDBK-103 |
| New MIL-PRF-38534 Standard Microcircuit Drawings | 5962-XXXXXZZ(H,K,D,G or E)YY | QML-38534 | MIL-HDBK-103 |
| New 1.2.1 of MIL-STD-883 Standard Microcircuit Drawings, based on Appendix A of MIL-PRF-38535 | 5962-XXXXXZZ(M)YY | MIL-HDBK-103 | MIL-HDBK-103 |

1.2.3 Case outline/lead finish. Case outline and lead finish are as described in each SMD. The lead finish indicated in the section 1 Part I listing is the most readily available from the manufacturer listed for the part. The manufacturer is authorized to supply other lead finishes than what is listed provided that further testing/qualification is performed by the manufacturer on the other lead finish(es). The user needs to contact the manufacturer to determine the availability of other lead finishes not listed herein.

1.2.4 Substitutability. Device-class-Q devices will replace device-class-M devices.

This handbook is for guidance only and cannot be cited as a requirement.



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

2. APPLICABLE DOCUMENTS This section is not applicable to the handbook.

3. DEFINITIONS This section is not applicable to the handbook.

4. REQUIREMENTS

4.1 Drawing requirements. SMD's will be prepared in accordance with ASME Y14.100 and DOD directives.

4.2 Preparation procedures. The procedures for the generation of an SMD are provided in MIL-HDBK-780.

4.3 Drawing effectivity and duration. SMD's and device class M one part - one part number SMDs which have become inactive for new design are reflected in section 1, part 1 of the appendix of this document with an "I" in the status column.

4.4 Approved sources of supply. The approved sources of supply list in this handbook supersedes the approved sources formerly listed in each individual SMD/DSCC Drawing. This handbook is the official list of approved sources of supply for non-one part - one part number SMD PIN's and for device class M one part - one part number SMD PIN's. Device classes B, S, Q, V, T, N (monolithic) and H, K, D, G, E (hybrid) one part - one part number SMD PIN's are listed for the convenience of the users. Official listing for B, S, Q, V, T, N, H, K, D, G, and E levels are available in the applicable QML. Manufacturers should notify DSCC-VA in writing if they no longer wish to be listed as an approved source of supply for any device listed herein. This letter will be used by DSCC to remove the manufacturer from MIL-HDBK-103 for those devices that the manufacturer specifies that he will no longer supply.

4.5 Radiation hardness assurance (RHA) levels. SMD devices which meet the RHA requirements of MIL-PRF-38535 or MIL-PRF-38534 will be marked with the appropriate RHA designator M, D, P, L, R, F, G, or H replacing the dash (-) in the PIN as indicated in the following example:

5962(M, D, P, L, R, F, G, or H)8999901EA

Only the highest RHA level for which the device is qualified will be listed in Section 1, Part I of the appendix of this document; however, at the request of the customer, the manufacturer is authorized to supply any lower RHA level device. At the request of the customer, the non-RHA PIN designated with a dash (-) may be supplied at the option of the manufacturer. The manufacturer may also opt to submit a certificate of compliance to have the non-RHA PIN listed in addition to the RHA PIN in Section 1, Part I of the appendix of this document.

4.6 Electrostatic discharge sensitivity (ESD) listing. ESD classification levels, as required by MIL-PRF-38534 or MIL-PRF-38535, will be listed in the status column of section 1, part 1, of the appendix. Manufacturers are required to send these classification levels to DSCC-VA for all Standard Microcircuit Drawings for which they are an approved source. The ESD listing in section 1, part 1 of the appendix will be in accordance with the following:

| STATUS | INTERPRETATION |
|---|---|
| Blank | Data not submitted to DSCC |
| 0 | Not tested |
| 1 | Class 1; 0 - 1999V |
| 2 | Class 2; 2000V - 3999V |
| 3 | Class 3; >= 4000V |
| I | Inactive for new design |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

## 5. CONFIGURATION MANAGEMENT

5.1 Configuration management of SMDs. All proposed changes to existing SMDs will be coordinated with the military activities and industry users of record for the individual documents. This coordination will be accomplished using DD Form 1693, Engineering Change Proposal (Short Form).

5.2 Record of users. Industrial users should inform Defense Supply Center Columbus when a system application requires use of the SMD. When notified, DSCC will maintain a record of users and this list will be used for coordination and distribution of changes to the drawings. Users of drawings covering microelectronic devices (FSC 5962) should contact DSCC-VAC, telephone (614) 692-0544.



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

## 6. DISTRIBUTION AND REQUESTS

6.1 Distribution. Requests for individual drawings and revisions to existing drawings may be addressed to:

Defense Supply Center Columbus
ATTN: DSCC-VAC
3990 E. Broad Street
Columbus, OH 43218-3990
Autovon 850-0547
Commercial (614) 692-0547

6.1.1 Automatic distribution. To be added to a mailing list for automatic distribution of new drawings and revisions to existing drawings requests may be addressed to:

Defense Supply Center Columbus
ATTN: DSCC-VAS
3990 E. Broad Street
Columbus, OH 43218-3990
Autovon 850-0528
Commercial (614) 692-0528

6.1.2 Electronic distribution. Electronic copies of Standard Microcircuit Drawings are available on the World Wide Web at http://www.dscc.dla.mil/Programs/MilSpec.

6.2 Requests. Requests for copies may be available online at http://assist.daps.dla.mil/quicksearch/ or www.dodssp.daps.mil or from the Standardization Document Order Desk, 700 Robbins Avenue, Building 4D, Philadelphia, PA 19111-5094

## 7. NOTES

7.1 Intended use. This list has been prepared for use by or for the Government in the acquisition of products covered by SMDs. Listing of a product is not intended to and does not connote endorsement of the product by the Department of Defense. This list is subject to change without notice; revision or amendment of this list will be issued as necessary. This listing supersedes the approved source of supply listing in the individual Standard Microcircuit Drawings, however the listing of a product does not release the supplier from compliance with the SMD requirements.

7.2 Subject item (key word) listing.

Part or identifying number (PIN)
Drawing number
Device class designator
Drawing requirements
Preparation procedures
Drawing effectivity and duration
Approved sources of supply
Radiation hardness assurance (RHA) levels
Electrostatic discharge sensitivity (ESD) listing
Configuration management of SMDs
Noun code descriptions



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

TABLE I. Noun Code Descriptions.

| Noun | Description |
|---|---|
| 100 | MICROCIRCUIT, POSITIVE-NAND GATES, QUAD 2-INPUT |
| 101 | MICROCIRCUIT, POSITIVE-NAND GATES, QUAD 2-INPUT, OPEN COLLECTOR OUTPUTS |
| 102 | MICROCIRCUIT, POSITIVE-NAND GATES, TRIPLE 3-INPUT |
| 103 | MICROCIRCUIT, POSITIVE-NAND GATES, TRIPLE 3-INPUT, OPEN COLLECTOR OUTPUTS |
| 104 | MICROCIRCUIT, POSITIVE-NAND GATES, DUAL 4-INPUT |
| 105 | MICROCIRCUIT, POSITIVE-NAND GATES, DUAL 4-INPUT, OPEN COLLECTOR OUTPUTS |
| 106 | MICROCIRCUIT, POSITIVE-NAND GATES, SINGLE 8-INPUT |
| 107 | MICROCIRCUIT, POSITIVE-NAND GATES, SINGLE 8-INPUT, EXPANDABLE |
| 108 | MICROCIRCUIT, POSITIVE-NAND GATES (GREATER THAN 8-INPUT) |
| 109 | MICROCIRCUIT, POSITIVE-NAND GATES, NOT OTHERWISE CLASSIFIED |
| 110 | MICROCIRCUIT, POSITIVE-AND GATES, QUAD 2-INPUT |
| 111 | MICROCIRCUIT, POSITIVE-AND GATES, QUAD 2-INPUT, OPEN COLLECTOR OUTPUTS |
| 112 | MICROCIRCUIT, POSITIVE-AND GATES, TRIPLE 3-INPUT |
| 113 | MICROCIRCUIT, POSITIVE-AND GATES, TRIPLE 3-INPUT, OPEN COLLECTOR OUTPUTS |
| 114 | MICROCIRCUIT, POSITIVE-AND GATES, DUAL 4-INPUT |
| 115 | MICROCIRCUIT, POSITIVE-AND GATES, DUAL 4-INPUT, OPEN COLLECTOR OUTPUTS |
| 119 | MICROCIRCUIT, POSITIVE-AND GATES, N.O.C. |
| 120 | MICROCIRCUIT, POSITIVE-NOR GATES, QUAD 2-INPUT |
| 121 | MICROCIRCUIT, POSITIVE-NOR GATES, QUAD 2-INPUT, OPEN COLLECTOR OUTPUTS |
| 122 | MICROCIRCUIT, POSITIVE-NOR GATES, TRIPLE 3-INPUT |
| 123 | MICROCIRCUIT, POSITIVE-NOR GATES, DUAL 4-INPUT |
| 124 | MICROCIRCUIT, POSITIVE-NOR GATES, N.O.C. |
| 125 | MICROCIRCUIT, POSITIVE-OR GATES |
| 130 | MICROCIRCUIT, AND-OR-INVERT GATES, DUAL 2-WIDE |
| 131 | MICROCIRCUIT, AND-OR-INVERT GATES, 4-WIDE |
| 132 | MICROCIRCUIT, AND-OR-INVERT GATES, 2-WIDE |
| 133 | MICROCIRCUIT, AND-OR-INVERT GATES, DUAL 2-WIDE, EXPANDABLE |
| 134 | MICROCIRCUIT, AND-OR-INVERT GATES, 4-WIDE, EXPANDABLE |
| 135 | MICROCIRCUIT, AND-OR-INVERT GATES, 2-WIDE, EXPANDABLE |
| 139 | MICROCIRCUIT, AND-OR-INVERT GATES, N.O.C. |
| 140 | MICROCIRCUIT, EXCLUSIVE-OR GATES |
| 141 | MICROCIRCUIT, EXCLUSIVE-NOR GATES |
| 142 | MICROCIRCUIT, OR-AND GATES |
| 143 | MICROCIRCUIT, HEX INVERTERS |
| 144 | MICROCIRCUIT, HEX INVERTERS, OPEN COLLECTOR |
| 145 | MICROCIRCUIT, EXPANDERS |
| 149 | MICROCIRCUIT, LOGIC GATES, N.O.C. |
| 150 | MICROCIRCUIT, FLIP FLOPS, AND-GATED, SINGLE J-K FLIP FLOP |
| 151 | MICROCIRCUIT, FLIP FLOPS, AND-OR-GATED, SINGLE J-K FLIP FLOP |
| 152 | MICROCIRCUIT, FLIP FLOPS, DUAL J-K (2-COMPLETELY INDEPENDENT CIRCUITS) |
| 153 | MICROCIRCUIT, FLIP FLOPS, DUAL J-K (ONE OR MORE COMMON INPUTS) |
| 154 | MICROCIRCUIT, FLIP FLOPS, AND-GATED, SINGLE J-K, NEGATIVE EDGE TRIGGERED FLIP FLOP |
| 155 | MICROCIRCUIT, FLIP FLOPS, AND-OR-GATED, SINGLE AND NEGATIVE EDGE TRIGGERED FLIP FLOP |
| 156 | MICROCIRCUIT, FLIP FLOPS, DUAL J-K, NEGATIVE EDGE TRIGGERED FLIP FLOP (INDEPENDENT CIRCUIT) |
| 157 | MICROCIRCUIT, FLIP FLOPS, DUAL J-K, NEGATIVE EDGE TRIGGERED FLIP FLOP (ONE OR MORE COMMON INPUTS) |
| 158 | MICROCIRCUIT, FLIP FLOPS, SINGLE OR DUAL D-TYPE |
| 159 | MICROCIRCUIT, FLIP FLOPS, QUAD OR HEX D-TYPE |
| 160 | MICROCIRCUIT, FLIP FLOPS, R-S |
| 161 | MICROCIRCUIT, FLIP FLOPS, AC COUPLED |
| 164 | MICROCIRCUIT, FLIP FLOPS, N.O.C. |
| 165 | MICROCIRCUIT, MULTIVIBRATORS, SINGLE |
| 166 | MICROCIRCUIT, MULTIVIBRATORS, DUAL |
| 167 | MICROCIRCUIT, MULTIVIBRATORS, VOLTAGE CONTROLLED |
| 169 | MICROCIRCUIT, MULTIVIBRATORS, N.O.C. |
| 180 | MICROCIRCUIT, ANALOG GATES/SWITCHES, SPST, 1 CHANNEL |
| 181 | MICROCIRCUIT, ANALOG GATES/SWITCHES, SPST, 2 CHANNEL |
| 182 | MICROCIRCUIT, ANALOG GATES/SWITCHES, SPST, 3 CHANNEL |
| 183 | MICROCIRCUIT, ANALOG GATES/SWITCHES, SPST, 4 CHANNEL |
| 184 | MICROCIRCUIT, ANALOG GATES/SWITCHES, SPST, 5 CHANNEL |
| 185 | MICROCIRCUIT, ANALOG GATES/SWITCHES, SPDT, 1 CHANNEL |
| 186 | MICROCIRCUIT, ANALOG GATES/SWITCHES, SPDT, 2 CHANNEL |
| 187 | MICROCIRCUIT, ANALOG GATES/SWITCHES, DPST, 1 CHANNEL |
| 188 | MICROCIRCUIT, ANALOG GATES/SWITCHES, DPST, 2 CHANNEL |
| 189 | MICROCIRCUIT, ANALOG GATES/SWITCHES, DPST, 3 CHANNEL |
| 190 | MICROCIRCUIT, ANALOG GATES/SWITCHES, DPDT |
| 191 | MICROCIRCUIT, ANALOG GATES/SWITCHES, 4 PST |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

TABLE I. Noun Code Descriptions.

| Noun | Description |
|---|---|
| 192 | MICROCIRCUIT, ANALOG GATES/SWITCHES, 4-CHANNEL DIFF MULTIPLEXER |
| 193 | MICROCIRCUIT, ANALOG GATES/SWITCHES, 8-CHANNEL MULTIPLEXER |
| 194 | MICROCIRCUIT, ANALOG GATES/SWITCHES, 8-CHANNEL DIFF MULTIPLEXER |
| 195 | MICROCIRCUIT, ANALOG GATES/SWITCHES, 16-CHANNEL MULTIPLEXER |
| 199 | MICROCIRCUIT, ANALOG GATES/SWITCHES, N.O.C. |
| 200 | MICROCIRCUIT, ARITHMETIC CIRCUITS, ADDERS, SINGLE 1 BIT |
| 201 | MICROCIRCUIT, ARITHMETIC CIRCUITS, ADDERS, SINGLE 2 BIT |
| 202 | MICROCIRCUIT, ARITHMETIC CIRCUITS, ADDERS, SINGLE 4 BIT |
| 203 | MICROCIRCUIT, ARITHMETIC CIRCUITS, ADDERS, DUAL 1 BIT |
| 204 | MICROCIRCUIT, ARITHMETIC CIRCUITS, ADDERS, N.O.C. |
| 205 | MICROCIRCUIT, ARITHMETIC CIRCUITS, ALU FUNCTIONS GENERATORS |
| 206 | MICROCIRCUIT, ARITHMETIC CIRCUITS, LOOK-AHEAD CARRY GENERATORS |
| 207 | MICROCIRCUIT, ARITHMETIC CIRCUITS, TRUE/COMPLEMENT, ZERO/ONE ELEMENTS |
| 208 | MICROCIRCUIT, ARITHMETIC CIRCUITS, MULTIPLIERS, BINARY/RATE |
| 209 | MICROCIRCUIT, ARITHMETIC CIRCUITS, COMPARATORS |
| 210 | MICROCIRCUIT, ARITHMETIC CIRCUITS, PARITY GENERATORS/CHECKERS/PARITY TREES |
| 211 | MICROCIRCUIT, ARITHMETIC CIRCUITS, SUBTRACTORS |
| 217 | MICROCIRCUIT, ARITHMETIC CIRCUITS, CALCULATOR CIRCUITS |
| 218 | MICROCIRCUIT, ARITHMETIC CIRCUITS, CENTRAL PROCESSOR UNITS |
| 219 | MICROCIRCUIT, ARITHMETIC CIRCUITS, N.O.C. |
| 220 | MICROCIRCUIT, REGISTERS, 4 BIT, PARALLEL IN, PARALLEL OUT |
| 221 | MICROCIRCUIT, REGISTERS, 4 BIT, PARALLEL IN SERIAL OUT |
| 222 | MICROCIRCUIT, REGISTERS, 4 BIT, N.O.C. |
| 223 | MICROCIRCUIT, REGISTERS, 5 BIT |
| 224 | MICROCIRCUIT, REGISTERS, 8 BIT, PARALLEL IN PARALLEL OUT |
| 225 | MICROCIRCUIT, REGISTERS, 8 BIT, PARALLEL IN SERIAL OUT |
| 226 | MICROCIRCUIT, REGISTERS, 8 BIT, SERIAL IN PARALLEL OUT |
| 227 | MICROCIRCUIT, REGISTERS, 8 BIT, SERIAL IN SERIAL OUT |
| 228 | MICROCIRCUIT, REGISTERS, 8 BIT, N.O.C. |
| 229 | MICROCIRCUIT, REGISTERS, 9-15 BIT |
| 230 | MICROCIRCUIT, REGISTERS, 16 BIT |
| 231 | MICROCIRCUIT, REGISTERS, 17-31 BIT |
| 232 | MICROCIRCUIT, REGISTERS, 32 BIT |
| 233 | MICROCIRCUIT, REGISTERS, 33-63 BIT |
| 234 | MICROCIRCUIT, REGISTERS, 64 BIT |
| 235 | MICROCIRCUIT, REGISTERS, 65-127 BIT |
| 236 | MICROCIRCUIT, REGISTERS, 128 BIT |
| 237 | MICROCIRCUIT, REGISTERS, 129-255 BIT |
| 238 | MICROCIRCUIT, REGISTERS, 256 BIT |
| 239 | MICROCIRCUIT, REGISTERS, 257-511 BIT |
| 240 | MICROCIRCUIT, REGISTERS, 512 BIT |
| 241 | MICROCIRCUIT, REGISTERS, 513-1023 BIT |
| 242 | MICROCIRCUIT, REGISTERS, 1024 BIT |
| 243 | MICROCIRCUIT, REGISTERS, 1025-2047 BIT |
| 244 | MICROCIRCUIT, REGISTERS, 2048 BIT |
| 245 | MICROCIRCUIT, REGISTERS, 2049-4095 BIT |
| 246 | MICROCIRCUIT, REGISTERS, 4096 BIT |
| 247 | MICROCIRCUIT, REGISTERS, GREATER THAN 4096 BIT |
| 249 | MICROCIRCUIT, REGISTERS, N.O.C. |
| 260 | MICROCIRCUIT, CODE CONVERTERS, USACII TO EBCDIC (OR VICE VERSA) |
| 261 | MICROCIRCUIT, CODE CONVERTERS, USACII TO SELECTRIC |
| 262 | MICROCIRCUIT, CODE CONVERTERS, BINARY TO BCD (OR VICE VERSA) |
| 263 | MICROCIRCUIT, CODE CONVERTERS, HOLLERITH TO USACII |
| 269 | MICROCIRCUIT, CODE CONVERTERS, N.O.C. |
| 270 | MICROCIRCUIT, DATA SELECTORS, MULTIPLEXERS, 16-LINE-TO-1-LINE |
| 271 | MICROCIRCUIT, DATA SELECTORS, MULTIPLEXERS, 8-LINE-TO-1-LINE |
| 272 | MICROCIRCUIT, DATA SELECTORS, MULTIPLEXERS, 8-LINE-TO-1-LINE TRI-STATE OUTPUT |
| 273 | MICROCIRCUIT, DATA SELECTORS, MULTIPLEXERS, DUAL 4-LINE-TO-1-LINE |
| 274 | MICROCIRCUIT, DATA SELECTORS, MULTIPLEXERS, DUAL 4-LINE-TO-1-LINE TRI-STATE OUTPUT |
| 275 | MICROCIRCUIT, DATA SELECTORS, MULTIPLEXERS, QUAD 2-LINE-TO-1-LINE |
| 276 | MICROCIRCUIT, DATA SELECTORS, MULTIPLEXERS, QUAD 2-LINE-TO-1-LINE TRI-STATE OUTPUT |
| 279 | MICROCIRCUIT, DATA SELECTORS, MULTIPLEXERS, N.O.C. |
| 280 | MICROCIRCUIT, DECODERS/DEMULTIPLEXERS, 4-LINE-TO-16-LINE |
| 281 | MICROCIRCUIT, DECODERS/DEMULTIPLEXERS, 4-LINE-TO-10-LINE |
| 282 | MICROCIRCUIT, DECODERS/DEMULTIPLEXERS, 3-LINE-TO-8-LINE |
| 283 | MICROCIRCUIT, DECODERS/DEMULTIPLEXERS, DUAL 2-LINE-TO-4-LINE |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

TABLE I. Noun Code Descriptions.

| Noun | Description |
|---|---|
| 284 | MICROCIRCUIT, DECODERS/DEMULTIPLEXERS, 1-LINE-TO-8-LINE |
| 289 | MICROCIRCUIT, DECODERS/DEMULTIPLEXERS, N.O.C. |
| 290 | MICROCIRCUIT, DISPLAY DECODERS/DRIVERS, BCD-TO-DECIMAL |
| 291 | MICROCIRCUIT, DISPLAY DECODERS/DRIVERS, BCD-TO-SEVEN SEGMENT |
| 292 | MICROCIRCUIT, DISPLAY DECODERS/DRIVERS, BCD-TO-DECIMAL WITH COUNTER/LATCH |
| 293 | MICROCIRCUIT, DISPLAY DECODERS/DRIVERS, BCD-TO-SEVEN SEGMENT WITH COUNTER LATCH |
| 299 | MICROCIRCUIT, DISPLAY DECODERS/DRIVERS, N.O.C. |
| 300 | MICROCIRCUIT, COUNTERS, BCD, ASYNCHRONOUS |
| 301 | MICROCIRCUIT, COUNTERS, BCD, SYNCHRONOUS |
| 302 | MICROCIRCUIT, COUNTERS, BCD, N.O.C. |
| 303 | MICROCIRCUIT, COUNTERS, BINARY, ASYNCHRONOUS |
| 304 | MICROCIRCUIT, COUNTERS, BINARY, SYNCHRONOUS |
| 305 | MICROCIRCUIT, COUNTERS, BINARY, N.O.C. |
| 306 | MICROCIRCUIT, COUNTERS, DECIMAL |
| 307 | MICROCIRCUIT, COUNTERS, RING |
| 308 | MICROCIRCUIT, COUNTERS, HEXADECIMAL |
| 309 | MICROCIRCUIT, COUNTERS, VARIABLE MODULO |
| 319 | MICROCIRCUIT, COUNTERS, N.O.C. |
| 320 | MICROCIRCUIT, CHARACTER GENERATORS, STATIC, ASCII FONT, RASTER-COLUMN SCAN |
| 321 | MICROCIRCUIT, CHARACTER GENERATORS, STATIC, ASCII FONT, RASTER-ROW SCAN |
| 322 | MICROCIRCUIT, CHARACTER GENERATORS, STATIC, CUSTOM, RASTER-COLUMN SCAN |
| 323 | MICROCIRCUIT, CHARACTER GENERATORS, STATIC, CUSTOM, RASTER-ROW SCAN |
| 324 | MICROCIRCUIT, CHARACTER GENERATORS, STATIC, NUMERIC |
| 329 | MICROCIRCUIT, CHARACTER GENERATORS, STATIC, N.O.C. |
| 330 | MICROCIRCUIT, CHARACTER GENERATORS, DYNAMIC, ASCII FONT |
| 331 | MICROCIRCUIT, CHARACTER GENERATORS, DYNAMIC, CUSTOM |
| 339 | MICROCIRCUIT, CHARACTER GENERATORS, DYNAMIC, N.O.C. |
| 340 | MICROCIRCUIT, LATCHES, 4-BIT |
| 341 | MICROCIRCUIT, LATCHES, 8-BIT |
| 342 | MICROCIRCUIT, LATCHES, N.O.C. |
| 345 | MICROCIRCUIT, PRIORITY ENCODERS |
| 350 | MICROCIRCUIT, PRESCALERS |
| 355 | MICROCIRCUIT, MSI/LSI MULTIPLE-FUNCTION CIRCUITS |
| 360 | MICROCIRCUIT, DIGITAL DELAY LINES |
| 365 | MICROCIRCUIT, GATE ARRAY, SEMICUSTOM |
| 366 | MICROCIRCUIT, LOGIC ARRAY, SEMICUSTOM |
| 367 | MICROCIRCUIT, STANDARD CELL ARRAY |
| 368 | MICROCIRCUIT, CELL ARRAY |
| 380 | MICROCIRCUIT, PROGRAMMABLE LOGIC DEVICE |
| 381 | MICROCIRCUIT, FIELD-PROGRAMMABLE GATE ARRAY |
| 399 | MICROCIRCUIT, DIGITAL CIRCUITS, N.O.C. |
| 400 | MICROCIRCUIT, MICROPROCESSORS, BIT/SLICE |
| 401 | MICROCIRCUIT, MICROPROCESSORS, 4-BIT |
| 402 | MICROCIRCUIT, MICROPROCESSORS, 8-BIT |
| 403 | MICROCIRCUIT, MICROPROCESSORS, 16-BIT |
| 404 | MICROCIRCUIT, MICROPROCESSORS, 32-BIT |
| 409 | MICROCIRCUIT, MICROPROCESSORS, NOC |
| 410 | MICROCIRCUIT, MICROCOMPUTERS, 8-BIT |
| 411 | MICROCIRCUIT, MICROCOMPUTERS, 16-BIT |
| 412 | MICROCIRCUIT, MICROCOMPUTERS, 32-BIT |
| 419 | MICROCIRCUIT, MICROCOMPUTERS, NOC |
| 420 | MICROCIRCUIT, MICROPROCESSOR SUPPORT CIRCUITS, CONTROLLERS |
| 421 | MICROCIRCUIT, MICROPROCESSOR SUPPORT CIRCUITS, INPUT/OUTPUT/INTERFACE |
| 422 | MICROCIRCUIT, MICROPROCESSOR OR SUPPORT CIRCUITS, CLOCK GENERATORS |
| 423 | MICROCIRCUIT, DMA CONTROLLERS |
| 424 | MICROCIRCUIT, PROGRAMMABLE INTERVAL TIMER |
| 429 | MICROCIRCUIT, MICROPROCESSOR SUPPORT CIRCUITS, NOC |
| 430 | MICROCIRCUIT, MICROPROCESSOR MULTIPLIERS |
| 431 | MICROCIRCUIT, FIELD PROGRAMMABLE LOGIC ARRAYS (FPLA) |
| 432 | MICROCIRCUIT, DIGITAL SIGNAL PROCESSOR |
| 433 | MICROCIRCUIT, DATA ACQUISITION SYSTEM |
| 439 | MICROCIRCUIT, VLSI MICROPROCESSOR SPECIAL CIRCUIT, NOC |
| 440 | MICROCIRCUIT, MICROPROCESSOR CONVERTERS |
| 441 | MICROCIRCUIT, MANCHESTER ENCODERS |
| 449 | MICROCIRCUIT, LINEAR MICROPROCESSOR SUPPORT CIRCUITS, NOC |
| 450 | MICROCIRCUIT, ANALOG MICROPROCESSORS |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

TABLE I. Noun Code Descriptions.

| Noun | Description |
|---|---|
| 460 | OPTIC ISOLATORS/COUPLERS |
| 461 | SENSOR ARRAYS |
| 462 | MICROCIRCUIT, PHOTO DETECTOR |
| 500 | MICROCIRCUIT, BUFFERS/DRIVERS (TOTEM POLE, STD. VOLTAGE OUTPUT) NAND QUAD 2-INPUT |
| 501 | MICROCIRCUIT, BUFFERS/DRIVERS (TOTEM POLE, STD. VOLTAGE OUTPUT) NAND DUAL 4-INPUT |
| 502 | MICROCIRCUIT, BUFFERS/DRIVERS (TOTEM POLE, STD. VOLTAGE OUTPUT) AND |
| 503 | MICROCIRCUIT, BUFFERS/DRIVERS (TOTEM POLE, STD. VOLTAGE OUTPUT) NOR |
| 509 | MICROCIRCUIT, BUFFERS/DRIVERS (TOTEM POLE, STD. VOLTAGE OUTPUT) N.O.C. |
| 510 | MICROCIRCUIT, BUFFERS/DRIVERS (OPEN-COLLECTOR, HIGH VOLTAGE OUTPUT) NAND |
| 511 | MICROCIRCUIT, BUFFERS/DRIVERS (OPEN-COLLECTOR, HIGH VOLTAGE OUTPUT) AND |
| 512 | MICROCIRCUIT, BUFFERS DRIVERS (OPEN-COLLECTOR, HIGH VOLTAGE OUTPUT) NOR |
| 513 | MICROCIRCUIT, BUFFERS DRIVERS (OPEN-COLLECTOR, HIGH VOLTAGE OUTPUT) HEX |
| 514 | MICROCIRCUIT, BUFFERS DRIVERS (OPEN-COLLECTOR, HIGH VOLTAGE OUTPUT) HEX INVERTER |
| 519 | MICROCIRCUIT, BUFFERS DRIVERS (OPEN-COLLECTOR, HIGH VOLTAGE OUTPUT) N.O.C. |
| 520 | MICROCIRCUIT, BUFFERS DRIVERS (TRI-STATE OUTPUT) QUAD |
| 521 | MICROCIRCUIT, BUFFERS DRIVERS (TRI-STATE OUTPUT) QUAD INVERTER |
| 522 | MICROCIRCUIT, BUFFERS DRIVERS (TRI-STATE OUTPUT) HEX |
| 523 | MICROCIRCUIT, BUFFERS DRIVERS (TRI-STATE OUTPUT) HEX INVERTER |
| 529 | MICROCIRCUIT, BUFFERS/DRIVERS (TRI-STATE OUTPUT) N.O.C. |
| 530 | MICROCIRCUIT, POWER DRIVERS (HIGH CURRENT IN "ON" STATE, HIGH VOLTAGE IN "OFF" STATE) NAND |
| 531 | MICROCIRCUIT, POWER DRIVERS (HIGH CURRENT IN "ON" STATE, HIGH VOLTAGE IN "OFF" STATE) OR |
| 532 | MICROCIRCUIT, POWER DRIVERS (HIGH CURRENT IN "ON" STATE, HIGH VOLTAGE IN "OFF" STATE) NOR |
| 533 | MICROCIRCUIT, POWER DRIVERS (HIGH CURRENT IN "ON" STATE, HIGH VOLTAGE IN "OFF" STATE) AND |
| 539 | MICROCIRCUIT, POWER DRIVERS, N.O.C. |
| 540 | MICROCIRCUIT, CMOS BUFFERS/CONVERTERS, HEX |
| 541 | MICROCIRCUIT, CMOS BUFFERS/CONVERTERS, HEX INVERTERS |
| 542 | MICROCIRCUIT, CMOS BUFFERS/CONVERTERS, QUAD |
| 544 | MICROCIRCUIT, CMOS BUFFERS/CONVERTERS, N.O.C. |
| 545 | MICROCIRCUIT, LOGIC-LEVEL CONVERTERS/TRANSLATORS, HIGH-TO-LOW OR VICE VERSA |
| 546 | MICROCIRCUIT, LOGIC-LEVEL CONVERTERS/TRANSLATORS, SATURATED-TO-ECL OR VICE VERSA |
| 547 | MICROCIRCUIT, LOGIC-LEVEL CONVERTERS/TRANSLATORS, TTL-TO-ECL OR VICE VERSA |
| 548 | MICROCIRCUIT, LOGIC-LEVEL CONVERTERS/TRANSLATORS, TTL-TO-MOS OR VICE VERSA |
| 549 | MICROCIRCUIT, LOGIC-LEVEL CONVERTERS/TRANSLATORS, N.O.C. |
| 550 | MICROCIRCUIT, MOS CLOCK DRIVERS |
| 555 | MICROCIRCUIT, FET SWITCH DRIVERS |
| 560 | MICROCIRCUIT, LINE/BUSS DRIVERS, NAND |
| 561 | MICROCIRCUIT, LINE/BUSS DRIVERS, NOR |
| 562 | MICROCIRCUIT, LINE/BUSS DRIVERS, DUAL, SINGLE OUTPUT |
| 563 | MICROCIRCUIT, LINE/BUSS DRIVERS, TRIPLE |
| 564 | MICROCIRCUIT, LINE/BUSS DRIVERS, DUAL, DIFFERENTIAL OUTPUT |
| 565 | MICROCIRCUIT, LINE/BUSS DRIVERS, TRI-STATE OUTPUT |
| 566 | MICROCIRCUIT, LINE/BUSS DRIVERS, TERMINATED |
| 569 | MICROCIRCUIT, LINE/BUSS DRIVERS, N.O.C. |
| 570 | MICROCIRCUIT, LINE RECEIVERS, DUAL |
| 571 | MICROCIRCUIT, LINE RECEIVERS, TRIPLE |
| 572 | MICROCIRCUIT, LINE RECEIVERS, QUAD |
| 573 | MICROCIRCUIT, LINE RECEIVERS, DUAL DIFFERENTIAL INPUT |
| 574 | MICROCIRCUIT, LINE RECEIVERS, TRIPLE DIFFERENTIAL INPUT |
| 575 | MICROCIRCUIT, LINE RECEIVERS, QUAD DIFFERENTIAL INPUT |
| 579 | MICROCIRCUIT, LINE RECEIVERS, N.O.C. |
| 580 | MICROCIRCUIT, PERIPHERAL DRIVERS, DUAL POS-AND |
| 581 | MICROCIRCUIT, PERIPHERAL DRIVERS, DUAL POS-NAND |
| 582 | MICROCIRCUIT, PERIPHERAL DRIVERS, DUAL POS-OR |
| 583 | MICROCIRCUIT, PERIPHERAL DRIVERS, DUAL POS-NOR |
| 584 | MICROCIRCUIT, PERIPHERAL DRIVERS, MEMORY DRIVERS |
| 589 | MICROCIRCUIT, PERIPHERAL DRIVERS, N.O.C. |
| 590 | MICROCIRCUIT, LINE TRANSCEIVERS |
| 591 | MICROCIRCUIT, D/A CONVERTERS |
| 592 | MICROCIRCUIT, A/D CONVERTERS |
| 593 | MICROCIRCUIT, V/F, F/V CONVERTERS- |
| 594 | MICROCIRCUIT, CONVERTERS, N.O.C. |
| 599 | MICROCIRCUIT, INTERFACE CIRCUITS, N.O.C. |
| 600 | MICROCIRCUIT, READ-WRITE MEMORIES, 16-BIT (4X4), STATIC |
| 601 | MICROCIRCUIT, READ-WRITE MEMORIES, 16-BIT (16X1), STATIC |
| 602 | MICROCIRCUIT, READ-WRITE MEMORIES, 64-BIT (16X4), STATIC |
| 603 | MICROCIRCUIT, READ-WRITE MEMORIES, 64-BIT (64X1), STATIC |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

TABLE I. Noun Code Descriptions.

| Noun | Description |
|---|---|
| 604 | MICROCIRCUIT, READ-WRITE MEMORIES, 256-BIT (64X4), STATIC |
| 605 | MICROCIRCUIT, READ-WRITE MEMORIES, 256-BIT (64X4), DYNAMIC |
| 606 | MICROCIRCUIT, READ-WRITE MEMORIES, 256-BIT (256X1), STATIC |
| 607 | MICROCIRCUIT, READ-WRITE MEMORIES, 512-WORD, STATIC |
| 608 | MICROCIRCUIT, READ-WRITE MEMORIES, 1024-BIT, STATIC |
| 609 | MICROCIRCUIT, READ-WRITE MEMORIES, 1024-BIT, DYNAMIC |
| 610 | MICROCIRCUIT, READ-WRITE MEMORIES, 2048-BIT, STATIC |
| 611 | MICROCIRCUIT, READ-WRITE MEMORIES, 2048-BIT, DYNAMIC |
| 612 | MICROCIRCUIT, READ-WRITE MEMORIES, 4096-BIT, STATIC |
| 613 | MICROCIRCUIT, READ-WRITE MEMORIES, 4096-BIT, DYNAMIC |
| 614 | MICROCIRCUIT, READ-WRITE MEMORIES, 8192-BIT, STATIC |
| 615 | MICROCIRCUIT, READ-WRITE MEMORIES, 8192-BIT, DYNAMIC |
| 616 | MICROCIRCUIT, READ-WRITE MEMORIES, 16384-BIT, STATIC |
| 617 | MICROCIRCUIT, READ-WRITE MEMORIES, 16384-BIT, DYNAMIC |
| 618 | MICROCIRCUIT, READ-WRITE MEMORIES, 32768-BIT, STATIC |
| 619 | MICROCIRCUIT, READ-WRITE MEMORIES, 32768-BIT, DYNAMIC |
| 620 | MICROCIRCUIT, READ-WRITE MEMORIES, 65536-BIT, STATIC |
| 621 | MICROCIRCUIT, READ-WRITE MEMORIES, 65536-BIT, DYNAMIC |
| 622 | MICROCIRCUIT, READ-WRITE MEMORIES, 128K |
| 623 | MICROCIRCUIT, READ-WRITE MEMORIES, 256K |
| 624 | MICROCIRCUIT, READ-WRITE MEMORIES, 512K |
| 625 | MICROCIRCUIT, READ-WRITE MEMORIES, 1024K |
| 627 | MICROCIRCUIT, READ-WRITE MEMORIES, MULTIPLE PORT REGISTERS |
| 628 | MICROCIRCUIT, READ-WRITE MEMORIES, CONTENT ADDRESSABLE |
| 629 | MICROCIRCUIT, READ-WRITE MEMORIES, N.O.C. |
| 630 | MICROCIRCUIT, READ-ONLY MEMORIES, MASK PROGRAMMABLE, 32X8 |
| 631 | MICROCIRCUIT, READ-ONLY MEMORIES, MASK PROGRAMMABLE, 64X8 |
| 632 | MICROCIRCUIT, READ-ONLY MEMORIES, MASK PROGRAMMABLE, 128X8 |
| 633 | MICROCIRCUIT, READ-ONLY MEMORIES, MASK PROGRAMMABLE, 256X4 |
| 634 | MICROCIRCUIT, READ-ONLY MEMORIES, MASK PROGRAMMABLE, 256X8 |
| 635 | MICROCIRCUIT, READ-ONLY MEMORIES, MASK PROGRAMMABLE, 256X10/256X12 |
| 636 | MICROCIRCUIT, READ-ONLY MEMORIES, MASK PROGRAMMABLE, 512 WORD |
| 637 | MICROCIRCUIT, READ-ONLY MEMORIES, MASK PROGRAMMABLE, 1024 WORD |
| 638 | MICROCIRCUIT, READ-ONLY MEMORIES, MASK PROGRAMMABLE, 2048 WORD |
| 639 | MICROCIRCUIT, READ-ONLY MEMORIES, MASK PROGRAMMABLE, 4096 WORD |
| 640 | MICROCIRCUIT, READ-ONLY MEMORIES, MASK PROGRAMMABLE, 8192 WORD |
| 641 | MICROCIRCUIT, READ-ONLY MEMORIES, MASK PROGRAMMABLE, 16384 WORD |
| 642 | MICROCIRCUIT, READ-ONLY MEMORIES, MASK PROGRAMMABLE, 32768 WORD |
| 549 | MICROCIRCUIT, READ-ONLY MEMORIES, MASK PROGRAMMABLE, N.O.C. |
| 650 | MICROCIRCUIT, READ-ONLY MEMORIES, ELECTRICALLY PROGRAMMABLE, 32X8 |
| 651 | MICROCIRCUIT, READ-ONLY MEMORIES, ELECTRICALLY PROGRAMMABLE, 64X8 |
| 652 | MICROCIRCUIT, READ-ONLY MEMORIES, ELECTRICALLY PROGRAMMABLE, 256X1 |
| 653 | MICROCIRCUIT, READ-ONLY MEMORIES, ELECTRICALLY PROGRAMMABLE, 256X4 |
| 654 | MICROCIRCUIT, READ-ONLY MEMORIES, ELECTRICALLY PROGRAMMABLE, 256X8 |
| 655 | MICROCIRCUIT, READ-ONLY MEMORIES, ELECTRICALLY PROGRAMMABLE, 512X4 |
| 656 | MICROCIRCUIT, READ-ONLY MEMORIES, ELECTRICALLY PROGRAMMABLE, 4096 |
| 657 | MICROCIRCUIT, READ-ONLY MEMORIES, ELECTRICALLY PROGRAMMABLE, 8192 BIT |
| 658 | MICROCIRCUIT, READ-ONLY MEMORIES, ELECTRICALLY PROGRAMMABLE, 16384 BIT |
| 659 | MICROCIRCUIT, READ-ONLY MEMORIES, ELECTRICALLY PROGRAMMABLE, 32768 BIT |
| 660 | MICROCIRCUIT, READ-ONLY MEMORIES, ELECTRICALLY PROGRAMMABLE, 65536 BIT |
| 661 | MICROCIRCUIT, READ-ONLY MEMORIES, ELECTRICALLY PROGRAMMABLE, 128K BIT |
| 662 | MICROCIRCUIT, READ-ONLY MEMORIES, ELECTRICALLY PROGRAMMABLE AND ALTERABLE, UV ERASABLE, 256K |
| 663 | MICROCIRCUIT, PROMS, 512K |
| 664 | MICROCIRCUIT, PROMS, 1024K |
| 669 | MICROCIRCUIT, READ-ONLY MEMORIES, ELECTRICALLY PROGRAMMABLE, NOC |
| 670 | MICROCIRCUIT, FIRST-IN-FIRST-OUT (FIFO) MEMORIES |
| 671 | MICROCIRCUIT, BUBBLE MEMORIES, MAGNETIC |
| 699 | MICROCIRCUIT, MEMORY DEVICES, N.O.C. |
| 700 | MICROCIRCUIT, OPERATIONAL AMPLIFIER, INTERNALLY COMPENSATED, GENERAL PURPOSE |
| 701 | MICROCIRCUIT, OPERATIONAL AMPLIFIER, INTERNALLY COMPENSATED, LOW CURRENT |
| 702 | MICROCIRCUIT, OPERATIONAL AMPLIFIER, INTERNALLY COMPENSATED, HIGH SPEED |
| 703 | MICROCIRCUIT, OP AMP, INTERNALLY COMPENSATED, FET INPUT |
| 710 | MICROCIRCUIT, OPERATIONAL AMPLIFIER, DUAL AMPLIFIER |
| 711 | MICROCIRCUIT, VOLTAGE FOLLOWERS |
| 712 | MICROCIRCUIT, DIFFERENTIAL AMPS (DIFFERENTIAL OUTPUT) |
| 713 | MICROCIRCUIT, QUAD AMPS |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

TABLE I. Noun Code Descriptions.

| Noun | Description |
|---|---|
| 719 | MICROCIRCUIT, OP AMPS, INTERNALLY COMPENSATED, N.O.C. |
| 720 | MICROCIRCUIT, EXT COMP SINGLE AMP DIFF INPUT SINGLE OUTPUT GENERAL PURPOSE |
| 721 | MICROCIRCUIT, EXT COMP SINGLE AMP DIFF INPUT SINGLE OUTPUT LOW CURRENT MAX INPUT OFFSET CURRENT AT 25 DEG C < 30 |
| 722 | MICROCIRCUIT, EXT COMP SINGLE AMP DIFF INPUT SINGLE OUTPUT HIGH SPEED (TYP SLEW RATE AT 25 DEG C GREATER 5 V/MICRO S) |
| 723 | MICROCIRCUIT, EXT COMP SINGLE AMP DIFF INPUT SINGLE OUTPUT FET INPUT |
| 724 | MICROCIRCUIT, EXT COMP SINGLE AMP DIFF INPUT SINGLE OUTPUT POWER |
| 730 | MICROCIRCUIT, OP AMPS, EXTERNALLY COMPENSATED, DUAL |
| 738 | MICROCIRCUIT, OP AMPS, EXTERNALLY COMPENSATED, N.O.C. |
| 739 | MICROCIRCUIT, OP AMPS, N.O.C. |
| 740 | MICROCIRCUIT, SENSE AMPS, SINGLE CHANNEL |
| 741 | MICROCIRCUIT, SENSE AMPS, DUAL CHANNEL, COMMON OUTPUT |
| 742 | MICROCIRCUIT, SENSE AMPS, DUAL CHANNEL, INDEPENDENT OUTPUT |
| 743 | MICROCIRCUIT, SENSE AMPS, 4-CHANNEL W/CHANNEL SELECT |
| 749 | MICROCIRCUIT, SENSE AMPS, N.O.C. |
| 750 | MICROCIRCUIT, RF/IF AMPS |
| 751 | MICROCIRCUIT, PROGRAMMABLE AMPLIFIERS |
| 752 | MICROCIRCUIT, CURRENT AMPLIFIERS |
| 753 | MICROCIRCUIT, POWER AMPLIFIERS |
| 754 | MICROCIRCUIT, INSTRUMENTATION AMPLIFIERS |
| 755 | MICROCIRCUIT, WIDEBAND DC AMPLIFIERS |
| 760 | MICROCIRCUIT, VIDEO AMPLIFIERS |
| 765 | MICROCIRCUIT, AUDIO AMPLIFIERS |
| 770 | MICROCIRCUIT, DIFFERENTIAL VOLTAGE COMPARATORS, SINGLE AMPLIFIER, SINGLE OUTPUT |
| 771 | MICROCIRCUIT, DIFFERENTIAL VOLTAGE COMPARATORS, SINGLE AMPLIFIER, SINGLE OUTPUT, WITH STROBE |
| 772 | MICROCIRCUIT, DIFFERENTIAL VOLTAGE COMPARATORS, DIFFERENTIAL OUTPUT |
| 773 | MICROCIRCUIT, DIFFERENTIAL VOLTAGE COMPARATORS, DUAL, COMMON OUTPUT |
| 774 | MICROCIRCUIT, DIFFERENTIAL VOLTAGE COMPARATORS, DUAL SEPARATE OUTPUT |
| 775 | MICROCIRCUIT, DIFFERENTIAL VOLTAGE COMPARATORS, DUAL,SEPARATE OUTPUTS, WITH STROBE |
| 776 | MICROCIRCUIT, DIFFERENTIAL VOLTAGE COMPARATORS, QUAD (4 SEPARATE AMPS) |
| 779 | MICROCIRCUIT, DIFFERENTIAL VOLTAGE COMPARATORS, N.O.C. |
| 780 | MICROCIRCUIT, VOLTAGE REGULATORS, POSITIVE, VARIABLE |
| 781 | MICROCIRCUIT, VOLTAGE REGULATORS, NEGATIVE, VARIABLE |
| 782 | MICROCIRCUIT, VOLTAGE REGULATORS, POSITIVE, FIXED |
| 783 | MICROCIRCUIT, VOLTAGE REGULATORS, NEGATIVE, FIXED |
| 784 | MICROCIRCUIT, VOLTAGE REGULATORS, TRACKING |
| 785 | MICROCIRCUIT, REGULATOR/REFERENCE DIODE |
| 786 | MICROCIRCUIT, SWITCHING REGULATORS |
| 787 | MICROCIRCUIT, REGULATOR CONTROL CIRCUITS |
| 789 | MICROCIRCUIT, VOLTAGE REGULATORS, N.O.C. |
| 790 | MICROCIRCUIT, ARRAYS, TRANSISTOR |
| 791 | MICROCIRCUIT, ARRAYS, DIODE |
| 792 | MICROCIRCUIT, ARRAYS, NOC |
| 800 | MICROCIRCUIT, COMMUNICATION CIRCUITS, LOGARITHMIC AMPLIFIERS/ANTILOG AMPLIFIERS |
| 801 | MICROCIRCUIT, BALANCED MIXERS |
| 802 | MICROCIRCUIT, COMMUNICATION CIRCUITS, PHASE-FREQUENCY DETECTORS |
| 803 | MICROCIRCUIT, COMMUNICATION CIRCUITS, PHASE-LOCKED LOOPS |
| 804 | MICROCIRCUIT, COMMUNICATION CIRCUITS, MODULATORS-DEMODULATORS |
| 805 | MICROCIRCUIT, ACTIVE FILTERS |
| 806 | MICROCIRCUIT, SIGNALING CIRCUITS |
| 807 | MICROCIRCUIT, CODEC CIRCUITS |
| 808 | MICROCIRCUIT, MODEM CIRCUITS |
| 809 | MICROCIRCUIT, COMMUNICATION CIRCUITS, N.O.C. |
| 810 | MICROCIRCUIT, LINEAR CIRCUITS, MISCELLANEOUS, QUADRANT MULTIPLIERS/DIVIDERS |
| 812 | MICROCIRCUIT, LINEAR CIRCUITS, MISCELLANEOUS, ZERO-VOLTAGE SWITCHES |
| 813 | MICROCIRCUIT, LINEAR CIRCUITS, MISCELLANEOUS, WAVEFORM-FUNCTION GENERATORS |
| 814 | MICROCIRCUIT, LINEAR CIRCUITS, MISCELLANEOUS, TIMERS |
| 815 | MICROCIRCUIT, LINEAR CIRCUITS, MISCELLANEOUS, OSCILLATORS, VOLTAGE CONTROLLED |
| 816 | MICROCIRCUIT, LINEAR CIRCUITS, MISCELLANEOUS, OSCILLATORS, RF/IF |
| 817 | MICROCIRCUIT, LINEAR CIRCUITS, MISCELLANEOUS, OSCILLATORS, AUDIO |
| 818 | MICROCIRCUIT, LINEAR CIRCUITS, MISCELLANEOUS, SAMPLE AND HOLD CIRCUITS |
| 819 | MICROCIRCUIT, LINEAR CIRCUITS, MISCELLANEOUS, MULTIPLE FUNCTION CIRCUITS |
| 820 | MICROCIRCUIT, AM/FM RECEIVER CIRCUITS |
| 821 | MICROCIRCUIT, LINEAR CIRCUITS, MISCELLANEOUS, CURRENT SOURCE/DRIVER |
| 822 | MICROCIRCUIT, IMAGE SENSOR |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

TABLE I. Noun Code Descriptions.

| Noun | Description |
|---|---|
| 830 | MICROCIRCUIT, GRAPHIC AND TV CIRCUITS |
| 831 | MICROCIRCUIT, SOUND GENERATION CIRCUITS |
| 839 | MICROCIRCUIT, SPECIAL FUNCTION CIRCUITS, NOC |
| 899 | MICROCIRCUIT, LINEAR CIRCUITS, N.O.C. |
| 998 | MICROCIRCUIT, TEMPORARILY UNCLASSIFIED |
| 999 | GENERAL SPECS MIL PART NUMBERS |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-0050101QXA | B | 04/18/2002 | 1 | NATIONAL | | Y | LM136AH-2.5-SMD | 785 |
| 5962R0050101QXA | B | 04/18/2002 | | (NONE) | | | LM136A-2.5 (GEN) | 785 |
| 5962R0050101VXA | B | 04/18/2002 | 1 | NATIONAL | | Y | LM136AH-2.5RQV | 785 |
| 5962-0050201KXC | A | 03/13/2003 | 1 | AEROFLEX | | Y | ACT8500-S | 199 |
| 5962-0050202KXC | A | 03/13/2003 | 1 | AEROFLEX | | Y | ACT8501-S | 199 |
| 5962-0050401QXC | | 11/15/2001 | 1 | ATMEL GREN. | | Y | TS8388BMFSB/Q | 592 |
| 5962-0050401QYC | | 11/15/2001 | 1 | ATMEL GREN. | | Y | TS8388BMFB/Q | 592 |
| 5962-0050601Q2A | A | 12/12/2000 | 2 | TI | | Y | SNJ54LVC157AFK | 275 |
| 5962-0050601QEA | A | 12/12/2000 | 2 | TI | | Y | SNJ54LVC157AJ | 275 |
| 5962-0050601QFA | A | 12/12/2000 | 2 | TI | | Y | SNJ54LVC157AW | 275 |
| 5962-0050701QEA | A | 01/22/2004 | 1 | SARNOFF | | Y | GEM22101QEA | 319 |
| 5962-0050701QEC | A | 01/22/2004 | 1 | SARNOFF | | Y | GEM22101QEC | 319 |
| 5962-0050901Q2A | | 12/07/2000 | 1 | TI | | Y | SNJ54LVC257AFK | 275 |
| 5962-0050901QEA | | 12/07/2000 | 1 | TI | | Y | SNJ54LVC257AJ | 275 |
| 5962-0050901QFA | | 12/07/2000 | 1 | TI | | Y | SNJ54LVC257AW | 275 |
| 5962-0051001QXA | A | 07/23/2002 | 1 | TI | | Y | SMJ320C6203 | 432 |
| 5962-0051101NXD | | 01/16/2001 | 1 | TI | | Y | THS1408MPHP | 592 |
| 5962-0051201Q2A | C | 10/03/2002 | 1 | TI | | Y | TLV2460MFKB | 719 |
| 5962-0051201QHA | C | 10/03/2002 | 1 | TI | | Y | TLV2460MUB | 719 |
| 5962-0051201QPA | C | 10/03/2002 | 1 | TI | | Y | TLV2460MJGB | 719 |
| 5962-0051202Q2A | C | 10/03/2002 | 1 | TI | | Y | TLV2460AMFKB | 719 |
| 5962-0051202QHA | C | 10/03/2002 | 1 | TI | | Y | TLV2460AMUB | 719 |
| 5962-0051202QPA | C | 10/03/2002 | 1 | TI | | Y | TLV2460AMJGB | 719 |
| 5962-0051203Q2A | C | 10/03/2002 | 1 | TI | | Y | TLV2461MFKB | 719 |
| 5962-0051203QHA | C | 10/03/2002 | 1 | TI | | Y | TLV2461MUB | 719 |
| 5962-0051203QPA | C | 10/03/2002 | 1 | TI | | Y | TLV2461MJGB | 719 |
| 5962-0051204Q2A | C | 10/03/2002 | 1 | TI | | Y | TLV2461AMFKB | 719 |
| 5962-0051204QHA | C | 10/03/2002 | 1 | TI | | Y | TLV2461AMUB | 719 |
| 5962-0051204QPA | C | 10/03/2002 | 1 | TI | | Y | TLV2461AMJGB | 719 |
| 5962-0051205Q2A | C | 10/03/2002 | 1 | TI | | Y | TLV2462MFKB | 719 |
| 5962-0051205QHA | C | 10/03/2002 | 1 | TI | | Y | TLV2462MUB | 719 |
| 5962-0051205QPA | C | 10/03/2002 | 1 | TI | | Y | TLV2462MJGB | 719 |
| 5962-0051206Q2A | C | 10/03/2002 | 1 | TI | | Y | TLV2462AMFKB | 719 |
| 5962-0051206QHA | C | 10/03/2002 | 1 | TI | | Y | TLV2462AMUB | 719 |
| 5962-0051206QPA | C | 10/03/2002 | 1 | TI | | Y | TLV2462AMJGB | 719 |
| 5962-0051207Q2A | C | 10/03/2002 | 1 | TI | | Y | TLV2463MFKB | 719 |
| 5962-0051207QCA | C | 10/03/2002 | 1 | TI | | Y | TLV2463MUB | 719 |
| 5962-0051208Q2A | C | 10/03/2002 | 1 | TI | | Y | TLV2463AMFKB | 719 |
| 5962-0051208QCA | C | 10/03/2002 | 1 | TI | | Y | TLV2463AMUB | 719 |
| 5962-0051301QCA | B | 04/09/2003 | 1 | TI | | Y | CD54ACT20F3A | 104 |
| 5962-0051302QXA | B | 04/09/2003 | 2 | STMICRO | | Y | 54ACT20K02Q | 104 |
| 5962-0051302QXC | B | 04/09/2003 | 2 | STMICRO | | Y | 54ACT20K01Q | 104 |
| 5962-0051302VXA | B | 04/09/2003 | 2 | STMICRO | | Y | 54ACT20K02V | 104 |
| 5962-0051302VXC | B | 04/09/2003 | 2 | STMICRO | | Y | 54ACT20K01V | 104 |
| 5962-0051401Q2A | | 08/21/2001 | 1 | TI | | Y | UC1708L883B | 539 |
| 5962-0051401V2A | | 08/21/2001 | 1 | TI | | Y | UC1708LQMLV | 539 |
| 5962-0051401QEA | | 08/21/2001 | 1 | TI | | Y | UC1708JE883B | 539 |
| 5962-0051401VEA | | 08/21/2001 | 1 | TI | | Y | UC1708JEQMLV | 539 |
| 5962-0051401QPA | | 08/21/2001 | 1 | TI | | Y | UC1708J883B | 539 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-0051401VPA | | 08/21/2001 | 1 | TI | | Y | UC1708JQMLV | 539 |
| 5962-0051501VHA | B | 07/29/2002 | 1 | ANALOG (5) | | Y | AD8561AL/QMLV | 779 |
| 5962R0051501VHA | B | 07/29/2002 | 1 | ANALOG (5) | | Y | AD8561AL/QMLR | 779 |
| 5962-0051501VPA | B | 07/29/2002 | 1 | ANALOG (5) | | Y | AD8561AQ/QMLV | 779 |
| 5962R0051501VPA | B | 07/29/2002 | 1 | ANALOG (5) | | Y | AD8561AQ/QMLR | 779 |
| 5962-0051601V2A | B | 04/22/2002 | 1 | ANALOG (5) | | Y | REF05ARC/QMLV | 785 |
| 5962R0051601V2A | B | 04/22/2002 | 1 | ANALOG (5) | | Y | REF05ARC/QMLR | 785 |
| 5962-0051601VGA | B | 04/22/2002 | 1 | ANALOG (5) | | Y | REF05AJ/QMLV | 785 |
| 5962R0051601VGA | B | 04/22/2002 | 1 | ANALOG (5) | | Y | REF05AJ/QMLR | 785 |
| 5962-0051601VHA | B | 04/22/2002 | 1 | ANALOG (5) | | Y | REF05AL/QMLV | 785 |
| 5962R0051601VHA | B | 04/22/2002 | 1 | ANALOG (5) | | Y | REF05AL/QMLR | 785 |
| 5962-0051601VPA | B | 04/22/2002 | 1 | ANALOG (5) | | Y | REF05AZ/QMLV | 785 |
| 5962R0051601VPA | B | 04/22/2002 | 1 | ANALOG (5) | | Y | REF05AZ/QMLR | 785 |
| 5962-0051701VCA | D | 11/13/2001 | 2 | ANALOG (5) | | Y | OP484AY/QMLV | 713 |
| 5962R0051701VCA | D | 11/13/2001 | 2 | ANALOG (5) | | Y | OP484AY/QMLR | 713 |
| 5962-0051701VDA | D | 11/13/2001 | 2 | ANALOG (5) | | Y | OP484AM/QMLV | 713 |
| 5962R0051701VDA | D | 11/13/2001 | 2 | ANALOG (5) | | Y | OP484AM/QMLR | 713 |
| 5962-0051801QQC | A | 08/27/2002 | 2 | ATMEL NANTES | | Y | MC80C32E-30MQ | 420 |
| 5962-0051801VQC | A | 08/27/2002 | 2 | ATMEL NANTES | | Y | SC80C32E-30SV | 420 |
| 5962-0051801QXC | A | 08/27/2002 | 2 | ATMEL NANTES | | Y | MJ80C32E-30MQ | 420 |
| 5962-0051801VXC | A | 08/27/2002 | 2 | ATMEL NANTES | | Y | SJ80C32E-30SV | 420 |
| 5962R0052001V9A | B | 04/30/2002 | 2 | INTERSIL | | Y | IS0-2981RH-Q | 821 |
| 5962R0052001QVC | B | 04/30/2002 | 2 | INTERSIL | | Y | IS1-2981RH-8 | 821 |
| 5962R0052001TVC | B | 04/30/2002 | 2 | INTERSIL | | Y | IS1-2981RH-T | 821 |
| 5962R0052001VVC | B | 04/30/2002 | 2 | INTERSIL | | Y | IS1-2981RH-Q | 821 |
| 5962F0052101V9A | D | 06/19/2003 | 2 | INTERSIL | | Y | IS0-1715ARH-Q | 555 |
| 5962F0052101QXC | D | 06/19/2003 | 2 | INTERSIL | | Y | IS9-1715ARH-8 | 555 |
| 5962F0052101VXC | D | 06/19/2003 | 2 | INTERSIL | | Y | IS9-1715ARH-Q | 555 |
| 5962R0052101TXC | D | 06/19/2003 | 2 | INTERSIL | | Y | IS9-1715ARH-T | 555 |
| 5962-0052201HXA | A | 12/16/2002 | 1 | INTERPOINT | | Y | MSA2805D/883 | 594 |
| 5962-0052201HXC | A | 12/16/2002 | 1 | INTERPOINT | | Y | MSA2805D/883 | 594 |
| 5962-0052201HYA | A | 12/16/2002 | 1 | INTERPOINT | | Y | MGA2805D/883 | 594 |
| 5962-0052201HYC | A | 12/16/2002 | 1 | INTERPOINT | | Y | MGA2805D/883 | 594 |
| 5962-0052201HZA | A | 12/16/2002 | 1 | INTERPOINT | | Y | MGA2805DZ/883 | 594 |
| 5962F0052301V9A | D | 05/25/2004 | 2 | INTERSIL | | Y | IS0-1009RH-Q | 899 |
| 5962F0052301QXC | D | 05/25/2004 | 2 | INTERSIL | | Y | IS2-1009RH-8 | 899 |
| 5962F0052301VXC | D | 05/25/2004 | 2 | INTERSIL | | Y | IS2-1009RH-Q | 899 |
| 5962F0052301QYC | D | 05/25/2004 | 2 | INTERSIL | | Y | ISYE-1009RH-8 | 899 |
| 5962F0052301VYC | D | 05/25/2004 | 2 | INTERSIL | | Y | ISYE-1009RH-Q | 899 |
| 5962P0052401QGA | C | 03/07/2003 | | (NONE) | | | LM111 (GEN) | 770 |
| 5962P0052401VGA | C | 03/07/2003 | 1 | NATIONAL | 09/07/2005 | Y | LM111HPQMLV | 770 |
| 5962P0052401VHA | C | 03/07/2003 | 1 | NATIONAL | 09/07/2005 | Y | LM111WPQMLV | 770 |
| 5962P0052401QPA | C | 03/07/2003 | | (NONE) | | | LM111 (GEN) | 770 |
| 5962P0052401VPA | C | 03/07/2003 | 1 | NATIONAL | | Y | LM111J-8PQMLV | 770 |
| 5962P0052401QZA | C | 03/07/2003 | | (NONE) | | | LM111 (GEN) | 770 |
| 5962P0052401VZA | C | 03/07/2003 | 1 | NATIONAL | 09/07/2005 | Y | LM111WGPQMLV | 770 |
| 5962-0052601HXA | A | 12/16/2002 | 1 | INTERPOINT | | Y | SLH2805S/HO | 594 |
| 5962-0052601HXC | A | 12/16/2002 | 1 | INTERPOINT | | Y | SLH2805S/HO | 594 |
| 5962L0052601HXA | A | 12/16/2002 | 1 | INTERPOINT | | Y | SLH2805S/HL | 594 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962L0052601HXC | A | 12/16/2002 | 1 | INTERPOINT | | Y | SLH2805S/HL | 594 |
| 5962L0052601KXA | A | 12/16/2002 | 1 | INTERPOINT | | Y | SLH2805S/KL | 594 |
| 5962L0052601KXC | A | 12/16/2002 | 1 | INTERPOINT | | Y | SLH2805S/KL | 594 |
| 5962R0052601HXA | A | 12/16/2002 | 1 | INTERPOINT | | Y | SLH2805S/HR | 594 |
| 5962R0052601HXC | A | 12/16/2002 | 1 | INTERPOINT | | Y | SLH2805S/HR | 594 |
| 5962R0052601KXA | A | 12/16/2002 | 1 | INTERPOINT | | Y | SLH2805S/KR | 594 |
| 5962R0052601KXC | A | 12/16/2002 | 1 | INTERPOINT | | Y | SLH2805S/KR | 594 |
| 5962-0052701HXA | A | 02/07/2001 | 1 | INTERPOINT | | Y | SLH2812S/HO | 594 |
| 5962-0052701HXC | A | 02/07/2001 | 1 | INTERPOINT | | Y | SLH2812S/HO | 594 |
| 5962L0052701HXA | A | 02/07/2001 | 1 | INTERPOINT | | Y | SLH2812S/HL | 594 |
| 5962L0052701HXC | A | 02/07/2001 | 1 | INTERPOINT | | Y | SLH2812S/HL | 594 |
| 5962L0052701KXA | A | 02/07/2001 | 1 | INTERPOINT | | Y | SLH2812S/KL | 594 |
| 5962L0052701KXC | A | 02/07/2001 | 1 | INTERPOINT | | Y | SLH2812S/KL | 594 |
| 5962R0052701HXA | A | 02/07/2001 | 1 | INTERPOINT | | Y | SLH2812S/HR | 594 |
| 5962R0052701HXC | A | 02/07/2001 | 1 | INTERPOINT | | Y | SLH2812S/HR | 594 |
| 5962R0052701KXA | A | 02/07/2001 | 1 | INTERPOINT | | Y | SLH2812S/KR | 594 |
| 5962R0052701KXC | A | 02/07/2001 | 1 | INTERPOINT | | Y | SLH2812S/KR | 594 |
| 5962-0052801HXA | A | 12/16/2002 | 1 | INTERPOINT | | Y | SLH2815S/HO | 594 |
| 5962-0052801HXC | A | 12/16/2002 | 1 | INTERPOINT | | Y | SLH2815S/HO | 594 |
| 5962L0052801HXA | A | 12/16/2002 | 1 | INTERPOINT | | Y | SLH2815S/HL | 594 |
| 5962L0052801HXC | A | 12/16/2002 | 1 | INTERPOINT | | Y | SLH2815S/HL | 594 |
| 5962L0052801KXA | A | 12/16/2002 | 1 | INTERPOINT | | Y | SLH2815S/KL | 594 |
| 5962L0052801KXC | A | 12/16/2002 | 1 | INTERPOINT | | Y | SLH2815S/KL | 594 |
| 5962R0052801HXA | A | 12/16/2002 | 1 | INTERPOINT | | Y | SLH2815S/HR | 594 |
| 5962R0052801HXC | A | 12/16/2002 | 1 | INTERPOINT | | Y | SLH2815S/HR | 594 |
| 5962R0052801KXA | A | 12/16/2002 | 1 | INTERPOINT | | Y | SLH2815S/KR | 594 |
| 5962R0052801KXC | A | 12/16/2002 | 1 | INTERPOINT | | Y | SLH2815S/KR | 594 |
| 5962-0052901QXA | | 06/28/2000 | 1 | NATIONAL | | Y | 54ACTQ16541FMQB | 529 |
| 5962-0053001HXA | A | 04/10/2002 | 1 | ANALOG (6) | | Y | AD13280BZ/QMLH | 592 |
| 5962-0053501QXA | A | 06/26/2003 | 1 | ATMEL GREN. | | Y | TSPC106AMGSB/Q66C | 420 |
| 5962-0053502QXA | A | 06/26/2003 | 1 | ATMEL GREN. | | Y | TSPC106AMGSB/Q83C | 420 |
| 5962D0053601Q9A | D | 12/08/2002 | 2 | UTMC | | Y | UT9Q512-QDIE | 629 |
| 5962L0053601Q9A | D | 12/08/2002 | 2 | UTMC | | Y | UT9Q512_QDIE | 629 |
| 5962L0053601T9A | D | 12/08/2002 | 2 | UTMC | | Y | UT9Q512_TDIE | 629 |
| 5962D0053601QUA | D | 12/08/2002 | 2 | UTMC | | Y | UT9Q512-UCCA | 629 |
| 5962D0053601QUC | D | 12/08/2002 | 2 | UTMC | | Y | UT9Q512-UCC | 629 |
| 5962D0053601TUA | D | 12/08/2002 | 2 | UTMC | | Y | UT9Q512-UCCA | 629 |
| 5962D0053601TUC | D | 12/08/2002 | 2 | UTMC | | Y | UT9Q512-UCC | 629 |
| 5962L0053601QUA | D | 12/08/2002 | 2 | UTMC | | Y | UT9Q512-UCA | 629 |
| 5962L0053601QUC | D | 12/08/2002 | 2 | UTMC | | Y | UT9Q512-UCC | 629 |
| 5962L0053601TUA | D | 12/08/2002 | 2 | UTMC | | Y | UT9Q512-UCA | 629 |
| 5962L0053601TUC | D | 12/08/2002 | 2 | UTMC | | Y | UT9Q512-UCC | 629 |
| 5962D0053601QXA | D | 12/08/2002 | 2 | UTMC | | Y | UT9Q512-ICCA | 629 |
| 5962D0053601QXC | D | 12/08/2002 | 2 | UTMC | | Y | UT9Q512-ICC | 629 |
| 5962D0053601TXA | D | 12/08/2002 | 2 | UTMC | | Y | UT9Q512-ICCA | 629 |
| 5962D0053601TXC | D | 12/08/2002 | 2 | UTMC | | Y | UT9Q512-ICC | 629 |
| 5962L0053601QXA | D | 12/08/2002 | 2 | UTMC | | Y | UT9Q512-ICA | 629 |
| 5962L0053601QXC | D | 12/08/2002 | 2 | UTMC | | Y | UT9Q512-ICC | 629 |
| 5962L0053601TXA | D | 12/08/2002 | 2 | UTMC | | Y | UT9Q512-ICA | 629 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962L0053601TXC | D | 12/08/2002 | 2 | UTMC | | Y | UT9Q512-ICC | 629 |
| 5962L0053602Q9A | D | 12/08/2002 | 2 | UTMC | | Y | UT9Q512_QDIE | 629 |
| 5962L0053602T9A | D | 12/08/2002 | 2 | UTMC | | Y | UT9Q512_TDIE | 629 |
| 5962L0053602QUA | D | 12/08/2002 | 2 | UTMC | | Y | UT9Q512-UWA | 629 |
| 5962L0053602QUC | D | 12/08/2002 | 2 | UTMC | | Y | UT9Q512-UWC | 629 |
| 5962L0053602TUA | D | 12/08/2002 | 2 | UTMC | | Y | UT9Q512-UWA | 629 |
| 5962L0053602TUC | D | 12/08/2002 | 2 | UTMC | | Y | UT9Q512-UWC | 629 |
| 5962L0053602QXA | D | 12/08/2002 | 2 | UTMC | | Y | UT9Q512-IWA | 629 |
| 5962L0053602QXC | D | 12/08/2002 | 2 | UTMC | | Y | UT9Q512-IWC | 629 |
| 5962L0053602TXA | D | 12/08/2002 | 2 | UTMC | | Y | UT9Q512-IWA | 629 |
| 5962L0053602TXC | D | 12/08/2002 | 2 | UTMC | | Y | UT9Q512-IWC | 629 |
| 5962L0053603Q9A | D | 12/08/2002 | 2 | UTMC | | Y | UT9Q512_QDIE | 629 |
| 5962L0053603T9A | D | 12/08/2002 | 2 | UTMC | | Y | UT9Q512_TDIE | 629 |
| 5962L0053603QUA | D | 12/08/2002 | 2 | UTMC | | Y | UT9Q512-UCA | 629 |
| 5962L0053603QUC | D | 12/08/2002 | 2 | UTMC | | Y | UT9Q512-UCC | 629 |
| 5962L0053603TUA | D | 12/08/2002 | 2 | UTMC | | Y | UT9Q512-UCA | 629 |
| 5962L0053603TUC | D | 12/08/2002 | 2 | UTMC | | Y | UT9Q512-UCC | 629 |
| 5962L0053603QXA | D | 12/08/2002 | 2 | UTMC | | Y | UT9Q512-ICA | 629 |
| 5962L0053603QXC | D | 12/08/2002 | 2 | UTMC | | Y | UT9Q512-ICC | 629 |
| 5962L0053603TXA | D | 12/08/2002 | 2 | UTMC | | Y | UT9Q512-ICA | 629 |
| 5962L0053603TXC | D | 12/08/2002 | 2 | UTMC | | Y | UT9Q512-ICC | 629 |
| 5962L0053604Q9A | D | 12/08/2002 | 2 | UTMC | | Y | UT9Q512_QDIE | 629 |
| 5962L0053604T9A | D | 12/08/2002 | 2 | UTMC | | Y | UT9Q512_TDIE | 629 |
| 5962L0053604QUA | D | 12/08/2002 | 2 | UTMC | | Y | UT9Q512-UWA | 629 |
| 5962L0053604QUC | D | 12/08/2002 | 2 | UTMC | | Y | UT9Q512-UWC | 629 |
| 5962L0053604TUA | D | 12/08/2002 | 2 | UTMC | | Y | UT9Q512-UWA | 629 |
| 5962L0053604TUC | D | 12/08/2002 | 2 | UTMC | | Y | UT9Q512-UWC | 629 |
| 5962L0053604QXA | D | 12/08/2002 | 2 | UTMC | | Y | UT9Q512-IWA | 629 |
| 5962L0053604QXC | D | 12/08/2002 | 2 | UTMC | | Y | UT9Q512-IWC | 629 |
| 5962L0053604TXA | D | 12/08/2002 | 2 | UTMC | | Y | UT9Q512-IWA | 629 |
| 5962L0053604TXC | D | 12/08/2002 | 2 | UTMC | | Y | UT9Q512-IWC | 629 |
| 5962F0053801V9A | C | 09/08/2004 | | (NONE) | | | IS-705RH (GEN) | 449 |
| 5962R0053801V9A | C | 09/08/2004 | 1 | INTERSIL | | Y | IS0-705RH-Q | 449 |
| 5962F0053801QXC | C | 09/08/2004 | | (NONE) | | | IS-705RH (GEN) | 449 |
| 5962F0053801VXC | C | 09/08/2004 | | (NONE) | | | IS-705RH (GEN) | 449 |
| 5962R0053801QXC | C | 09/08/2004 | 1 | INTERSIL | | Y | IS9-705RH-8 | 449 |
| 5962R0053801TXC | C | 09/08/2004 | 1 | INTERSIL | | Y | IS9-705RH-T | 449 |
| 5962R0053801VXC | C | 09/08/2004 | 1 | INTERSIL | | Y | IS9-705RH-Q | 449 |
| 5962-0053901QXA | C | 10/24/2002 | | (NONE) | | | 320VC33 (GEN) | 432 |
| 5962-0053901QYA | C | 10/24/2002 | 2 | TI | | Y | SMJ320VC33HFGM150 | 432 |
| 5962-0053901QYC | C | 10/24/2002 | 2 | TI | | Y | SMJ320VC33HFGM150 | 432 |
| 5962-0053902QYA | C | 10/24/2002 | 2 | TI | | Y | SMJ320VC33HFGM | 432 |
| 5962-0053902QYC | C | 10/24/2002 | 2 | TI | | Y | SMJ320VC33HFGM | 432 |
| 5962-0054001Q9A | A | 04/23/2003 | 2 | ATMEL NANTES | | Y | TSC695F-25MBMQ | 409 |
| 5962-0054001V9A | A | 04/23/2003 | 2 | ATMEL NANTES | | Y | TSC695F-25SBSV | 409 |
| 5962-0054001QXC | A | 04/23/2003 | 2 | ATMEL NANTES | | Y | TSC695F-25MAMQ | 409 |
| 5962-0054001VXC | A | 04/23/2003 | 2 | ATMEL NANTES | | Y | TSC695F-25SASV | 409 |
| 5962R0054001VXC | A | 04/23/2003 | 2 | ATMEL NANTES | | Y | TSC695F-25SASR | 409 |
| 5962-0054101HGA | | 06/12/2002 | 1 | MS KENNEDY | | Y | MSK1476H | 739 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-0054101HGC | | 06/12/2002 | 1 | MS KENNEDY | | Y | MSK1476H | 739 |
| 5962-0054301QXC | C | 03/25/2003 | 1 | ACTEL | | Y | A54SX72A-CQ256B | 381 |
| 5962-0054301QYC | C | 03/25/2003 | 1 | ACTEL | | Y | A54SX72A-CQ208B | 381 |
| 5962-0054302QXC | C | 03/25/2003 | 1 | ACTEL | | Y | A54SX72A-1CQ256B | 381 |
| 5962-0054302QYC | C | 03/25/2003 | 1 | ACTEL | | Y | A54SX72A-1CQ208B | 381 |
| 5962-00A0101QXC | | 10/20/1999 | 3 | AMI | | Y | 6805-057 | 365 |
| 5962-00A0201QXC | | 11/03/1999 | 3 | AMI | | Y | 6580-065 | 365 |
| 5962-00A0301QXC | A | 02/11/2000 | | (NONE) | | | 6830-006 (GEN) | 365 |
| 5962-00A0302QXC | A | 02/11/2000 | 3 | AMI | | Y | 6830-007 | 365 |
| 5962-00A0401QXC | | 11/22/1999 | 3 | AMI | | Y | 6817-532 | 365 |
| 5962-00A0501QXC | | 11/22/1999 | 3 | AMI | | Y | 6589-007 | 365 |
| 5962-00A0601NXB | | 01/25/2000 | 3 | AMI | | Y | 6817-045 | 365 |
| 5962-00A0701QXC | | 01/27/2000 | 3 | AMI | | Y | 6571-030 | 365 |
| 5962-00A0801QXC | | 01/04/2000 | 3 | AMI | | Y | 6571-028 | 365 |
| 5962-00A0901NXB | | 01/25/2000 | 2 | AMI | | Y | 6805-053 | 365 |
| 5962-00A1001QXA | | 03/14/2000 | 1 | AMI | | Y | 9864-006 | 365 |
| 5962-00A1101QXC | | 03/20/2000 | 3 | AMI | | Y | 6830-005 | 365 |
| 5962-00A1201NXB | | 09/18/2000 | 3 | AMI | | Y | 6821-016 | 365 |
| 5962-00A1301QXC | | 11/28/2000 | 3 | AMI | | Y | 6821-526 | 365 |
| 5962-00A1401QXC | | 09/01/2000 | 3 | AMI | | Y | 6821-527 | 365 |
| 5962-00A1501QXC | | 09/01/2000 | 3 | AMI | | Y | 6817-531 | 365 |
| 5962-00A1601QXC | A | 09/20/2001 | 3 | AMI | | Y | 6829-010 | 365 |
| 5962-00A1701NXB | C | 12/19/2003 | 3 | AMI | | Y | 11624-001 | 365 |
| 5962-00B0101Q*C | A | 09/06/2000 | 3 | ATMEL NANTES | | Y | MG1014E | 365 |
| 5962-00B0101V*C | A | 09/06/2000 | 3 | ATMEL NANTES | | Y | MG1014E | 365 |
| 5962-00B0101Q9A | A | 09/06/2000 | 3 | ATMEL NANTES | | Y | MM0-G1014EH*MQ | 365 |
| 5962-00B0101V9A | A | 09/06/2000 | 3 | ATMEL NANTES | | Y | SM0-G1014EH*SV | 365 |
| 5962-00B0102Q*C | A | 09/06/2000 | 3 | ATMEL NANTES | | Y | MG1042E | 365 |
| 5962-00B0102V*C | A | 09/06/2000 | 3 | ATMEL NANTES | | Y | MG1042E | 365 |
| 5962-00B0102Q9A | A | 09/06/2000 | 3 | ATMEL NANTES | | Y | MM0-G1042EH*MQ | 365 |
| 5962-00B0102V9A | A | 09/06/2000 | 3 | ATMEL NANTES | | Y | SM0-G1042EH*SV | 365 |
| 5962-00B0103Q*C | A | 09/06/2000 | 3 | ATMEL NANTES | | Y | MG1090E | 365 |
| 5962-00B0103V*C | A | 09/06/2000 | 3 | ATMEL NANTES | | Y | MG1090E | 365 |
| 5962-00B0103Q9A | A | 09/06/2000 | 3 | ATMEL NANTES | | Y | MM0-G1090EH*MQ | 365 |
| 5962-00B0103V9A | A | 09/06/2000 | 3 | ATMEL NANTES | | Y | SM0-G1090EH*SV | 365 |
| 5962-00B0104Q*C | A | 09/06/2000 | 3 | ATMEL NANTES | | Y | MG1140E | 365 |
| 5962-00B0104V*C | A | 09/06/2000 | 3 | ATMEL NANTES | | Y | MG1140E | 365 |
| 5962-00B0104Q9A | A | 09/06/2000 | 3 | ATMEL NANTES | | Y | MM0-G1140EH*MQ | 365 |
| 5962-00B0104V9A | A | 09/06/2000 | 3 | ATMEL NANTES | | Y | SM0-G1140EH*SV | 365 |
| 5962-00B0105Q*C | A | 09/06/2000 | 3 | ATMEL NANTES | | Y | MG1200E | 365 |
| 5962-00B0105V*C | A | 09/06/2000 | 3 | ATMEL NANTES | | Y | MG1200E | 365 |
| 5962-00B0105Q9A | A | 09/06/2000 | 3 | ATMEL NANTES | | Y | MM0-G1200EH*MQ | 365 |
| 5962-00B0105V9A | A | 09/06/2000 | 3 | ATMEL NANTES | | Y | SM0-G1200EH*SV | 365 |
| 5962-00B0106Q*C | A | 09/06/2000 | 3 | ATMEL NANTES | | Y | MG1265E | 365 |
| 5962-00B0106V*C | A | 09/06/2000 | 3 | ATMEL NANTES | | Y | MG1265E | 365 |
| 5962-00B0106Q9A | A | 09/06/2000 | 3 | ATMEL NANTES | | Y | MM0-G1265EH*MQ | 365 |
| 5962-00B0106V9A | A | 09/06/2000 | 3 | ATMEL NANTES | | Y | SM0-G1265EH*SV | 365 |
| 5962-00B0107Q*C | A | 09/06/2000 | 3 | ATMEL NANTES | | Y | MG1480E | 365 |
| 5962-00B0107Q9A | A | 09/06/2000 | 3 | ATMEL NANTES | | Y | MM0-G1480EH*MQ | 365 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-00B0108Q*C | A | 09/06/2000 | 3 | ATMEL NANTES | | Y | MG1014 | 365 |
| 5962-00B0108Q9A | A | 09/06/2000 | 3 | ATMEL NANTES | | Y | MM0-G1014*MQ | 365 |
| 5962-00B0109Q*C | A | 09/06/2000 | 3 | ATMEL NANTES | | Y | MG1042 | 365 |
| 5962-00B0109Q9A | A | 09/06/2000 | 3 | ATMEL NANTES | | Y | MM0-G1042*MQ | 365 |
| 5962-00B0110Q*C | A | 09/06/2000 | 3 | ATMEL NANTES | | Y | MG1052 | 365 |
| 5962-00B0111Q*C | A | 09/06/2000 | 3 | ATMEL NANTES | | Y | MG1090 | 365 |
| 5962-00B0111Q9A | A | 09/06/2000 | 3 | ATMEL NANTES | | Y | MM0-G1090*MQ | 365 |
| 5962-00B0112Q*C | A | 09/06/2000 | 3 | ATMEL NANTES | | Y | MG1140 | 365 |
| 5962-00B0112Q9A | A | 09/06/2000 | 3 | ATMEL NANTES | | Y | MM0-G1140*MQ | 365 |
| 5962-00B0113Q*C | A | 09/06/2000 | 3 | ATMEL NANTES | | Y | MG1200 | 365 |
| 5962-00B0113Q9A | A | 09/06/2000 | 3 | ATMEL NANTES | | Y | MM0-G1200*MQ | 365 |
| 5962-00B0114Q*C | A | 09/06/2000 | 3 | ATMEL NANTES | | Y | MG1265 | 365 |
| 5962-00B0114Q9A | A | 09/06/2000 | 3 | ATMEL NANTES | | Y | MM0-G1265*MQ | 365 |
| 5962-00B0115Q*C | A | 09/06/2000 | 3 | ATMEL NANTES | | Y | MG1480 | 365 |
| 5962-00B0115Q9A | A | 09/06/2000 | 3 | ATMEL NANTES | | Y | MM0-G1480*MQ | 365 |
| 5962-00B0201Q*C | E | 03/08/2002 | 3 | ATMEL NANTES | | Y | MG2044E | 365 |
| 5962-00B0201V*C | E | 03/08/2002 | 3 | ATMEL NANTES | | Y | MG2044E | 365 |
| 5962-00B0201Q9A | E | 03/08/2002 | 3 | ATMEL NANTES | | Y | MM0-G2044EH*MQ | 365 |
| 5962-00B0201V9A | E | 03/08/2002 | 3 | ATMEL NANTES | | Y | SM0-G2044EH*SV | 365 |
| 5962-00B0202Q*C | E | 03/08/2002 | 3 | ATMEL NANTES | | Y | MG2091E | 365 |
| 5962-00B0202V*C | E | 03/08/2002 | 3 | ATMEL NANTES | | Y | MG2091E | 365 |
| 5962-00B0202Q9A | E | 03/08/2002 | 3 | ATMEL NANTES | | Y | MM0-G2091EH*MQ | 365 |
| 5962-00B0202V9A | E | 03/08/2002 | 3 | ATMEL NANTES | | Y | SM0-G2091EH*SV | 365 |
| 5962-00B0203Q*C | E | 03/08/2002 | 3 | ATMEL NANTES | | Y | MG2140E | 365 |
| 5962-00B0203V*C | E | 03/08/2002 | 3 | ATMEL NANTES | | Y | MG2140E | 365 |
| 5962-00B0203Q9A | E | 03/08/2002 | 3 | ATMEL NANTES | | Y | MM0-G2140EH*MQ | 365 |
| 5962-00B0203V9A | E | 03/08/2002 | 3 | ATMEL NANTES | | Y | SM0-G2140EH*SV | 365 |
| 5962-00B0204Q*C | E | 03/08/2002 | 3 | ATMEL NANTES | | Y | MG2194E | 365 |
| 5962-00B0204V*C | E | 03/08/2002 | 3 | ATMEL NANTES | | Y | MG2194E | 365 |
| 5962-00B0204Q9A | E | 03/08/2002 | 3 | ATMEL NANTES | | Y | MM0-G2194EH*MQ | 365 |
| 5962-00B0204V9A | E | 03/08/2002 | 3 | ATMEL NANTES | | Y | SM0-G2194EH*SV | 365 |
| 5962-00B0205Q*C | E | 03/08/2002 | 3 | ATMEL NANTES | | Y | MG2265E | 365 |
| 5962-00B0205V*C | E | 03/08/2002 | 3 | ATMEL NANTES | | Y | MG2265E | 365 |
| 5962-00B0205Q9A | E | 03/08/2002 | 3 | ATMEL NANTES | | Y | MM0-G2265EH*MQ | 365 |
| 5962-00B0205V9A | E | 03/08/2002 | 3 | ATMEL NANTES | | Y | SM0-G2265EH*SV | 365 |
| 5962-00B0206Q*C | E | 03/08/2002 | 3 | ATMEL NANTES | | Y | MG2360E | 365 |
| 5962-00B0206V*C | E | 03/08/2002 | 3 | ATMEL NANTES | | Y | MG2360E | 365 |
| 5962-00B0206Q9A | E | 03/08/2002 | 3 | ATMEL NANTES | | Y | MM0-G2360EH*MQ | 365 |
| 5962-00B0206V9A | E | 03/08/2002 | 3 | ATMEL NANTES | | Y | SM0-G2360EH*SV | 365 |
| 5962-00B0207Q*C | E | 03/08/2002 | 3 | ATMEL NANTES | | Y | MG2480E | 365 |
| 5962-00B0207Q9A | E | 03/08/2002 | 3 | ATMEL NANTES | | Y | MM0-G2480EH*MQ | 365 |
| 5962-00B0208Q*C | E | 03/08/2002 | 3 | ATMEL NANTES | | Y | MG2700E | 365 |
| 5962-00B0209Q*C | E | 03/08/2002 | 3 | ATMEL NANTES | | Y | MG2044 | 365 |
| 5962-00B0209Q9A | E | 03/08/2002 | 3 | ATMEL NANTES | | Y | MM0-G2044*MQ | 365 |
| 5962-00B0210Q*C | E | 03/08/2002 | 3 | ATMEL NANTES | | Y | MG2091 | 365 |
| 5962-00B0210Q9A | E | 03/08/2002 | 3 | ATMEL NANTES | | Y | MM0-G2091*MQ | 365 |
| 5962-00B0211Q*C | E | 03/08/2002 | 3 | ATMEL NANTES | | Y | MG2140 | 365 |
| 5962-00B0211Q9A | E | 03/08/2002 | 3 | ATMEL NANTES | | Y | MM0-G2140*MQ | 365 |
| 5962-00B0212Q*C | E | 03/08/2002 | 3 | ATMEL NANTES | | Y | MG2194 | 365 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-00B0212Q9A | E | 03/08/2002 | 3 | ATMEL NANTES | | Y | MM0-G2194*MQ | 365 |
| 5962-00B0213Q*C | E | 03/08/2002 | 3 | ATMEL NANTES | | Y | MG2265 | 365 |
| 5962-00B0213Q9A | E | 03/08/2002 | 3 | ATMEL NANTES | | Y | MM0-G2265*MQ | 365 |
| 5962-00B0214Q*C | E | 03/08/2002 | 3 | ATMEL NANTES | | Y | MG2360 | 365 |
| 5962-00B0214Q9A | E | 03/08/2002 | 3 | ATMEL NANTES | | Y | MM0-G2360*MQ | 365 |
| 5962-00B0215Q*C | E | 03/08/2002 | 3 | ATMEL NANTES | | Y | MG2480 | 365 |
| 5962-00B0215Q9A | E | 03/08/2002 | 3 | ATMEL NANTES | | Y | MM0-G2480*MQ | 365 |
| 5962-00B0216Q*C | E | 03/08/2002 | 3 | ATMEL NANTES | | Y | MG2M044E | 365 |
| 5962-00B0216V*C | E | 03/08/2002 | 3 | ATMEL NANTES | | Y | MG2M044E | 365 |
| 5962-00B0216Q9A | E | 03/08/2002 | 3 | ATMEL NANTES | | Y | MM0-G2M044EH*MQ | 365 |
| 5962-00B0216V9A | E | 03/08/2002 | 3 | ATMEL NANTES | | Y | SM0-G2M044EH*SV | 365 |
| 5962-00B0217Q*C | E | 03/08/2002 | 3 | ATMEL NANTES | | Y | MG2M091E | 365 |
| 5962-00B0217V*C | E | 03/08/2002 | 3 | ATMEL NANTES | | Y | MG2M091E | 365 |
| 5962-00B0217Q9A | E | 03/08/2002 | 3 | ATMEL NANTES | | Y | MM0-G2M091EH*MQ | 365 |
| 5962-00B0217V9A | E | 03/08/2002 | 3 | ATMEL NANTES | | Y | SM0-G2M091EH*SV | 365 |
| 5962-00B0218Q*C | E | 03/08/2002 | 3 | ATMEL NANTES | | Y | MG2M140E | 365 |
| 5962-00B0218V*C | E | 03/08/2002 | 3 | ATMEL NANTES | | Y | MG2M140E | 365 |
| 5962-00B0218Q9A | E | 03/08/2002 | 3 | ATMEL NANTES | | Y | MM0-G2M140EH*MQ | 365 |
| 5962-00B0218V9A | E | 03/08/2002 | 3 | ATMEL NANTES | | Y | SM0-G2M140EH*SV | 365 |
| 5962-00B0219Q*C | E | 03/08/2002 | 3 | ATMEL NANTES | | Y | MG2M194E | 365 |
| 5962-00B0219V*C | E | 03/08/2002 | 3 | ATMEL NANTES | | Y | MG2M194E | 365 |
| 5962-00B0219Q9A | E | 03/08/2002 | 3 | ATMEL NANTES | | Y | MM0-G2M194EH*MQ | 365 |
| 5962-00B0219V9A | E | 03/08/2002 | 3 | ATMEL NANTES | | Y | SM0-G2M194EH*SV | 365 |
| 5962-00B0220Q*C | E | 03/08/2002 | 3 | ATMEL NANTES | | Y | MG2M265E | 365 |
| 5962-00B0220V*C | E | 03/08/2002 | 3 | ATMEL NANTES | | Y | MG2M265E | 365 |
| 5962-00B0220Q9A | E | 03/08/2002 | 3 | ATMEL NANTES | | Y | MM0-G2M265EH*MQ | 365 |
| 5962-00B0220V9A | E | 03/08/2002 | 3 | ATMEL NANTES | | Y | SM0-G2M265EH*SV | 365 |
| 5962-00B0221Q*C | E | 03/08/2002 | 3 | ATMEL NANTES | | Y | MG2M360E | 365 |
| 5962-00B0221V*C | E | 03/08/2002 | 3 | ATMEL NANTES | | Y | MG2M360E | 365 |
| 5962-00B0221Q9A | E | 03/08/2002 | 3 | ATMEL NANTES | | Y | MM0-G2M360EH*MQ | 365 |
| 5962-00B0221V9A | E | 03/08/2002 | 3 | ATMEL NANTES | | Y | SM0-G2M360EH*SV | 365 |
| 5962-00B0222Q*C | E | 03/08/2002 | 3 | ATMEL NANTES | | Y | MG2M480E | 365 |
| 5962-00B0222V*C | E | 03/08/2002 | 3 | ATMEL NANTES | | Y | MG2M480E | 365 |
| 5962-00B0222Q9A | E | 03/08/2002 | 3 | ATMEL NANTES | | Y | MM0-G2M480EH*MQ | 365 |
| 5962-00B0222V9A | E | 03/08/2002 | 3 | ATMEL NANTES | | Y | SM0-G2M480EH*SV | 365 |
| 5962-00B0223Q*C | E | 03/08/2002 | 3 | ATMEL NANTES | | Y | MG2M044 | 365 |
| 5962-00B0223Q9A | E | 03/08/2002 | 3 | ATMEL NANTES | | Y | MM0-G2M044*MQ | 365 |
| 5962-00B0224Q*C | E | 03/08/2002 | 3 | ATMEL NANTES | | Y | MG2M091 | 365 |
| 5962-00B0224Q9A | E | 03/08/2002 | 3 | ATMEL NANTES | | Y | MM0-G2M091*MQ | 365 |
| 5962-00B0225Q*C | E | 03/08/2002 | 3 | ATMEL NANTES | | Y | MG2M140 | 365 |
| 5962-00B0225Q9A | E | 03/08/2002 | 3 | ATMEL NANTES | | Y | MM0-G2M140*MQ | 365 |
| 5962-00B0226Q*C | E | 03/08/2002 | 3 | ATMEL NANTES | | Y | MG2M194 | 365 |
| 5962-00B0226Q9A | E | 03/08/2002 | 3 | ATMEL NANTES | | Y | MM0-G2M194*MQ | 365 |
| 5962-00B0227Q*C | E | 03/08/2002 | 3 | ATMEL NANTES | | Y | MG2M265 | 365 |
| 5962-00B0227Q9A | E | 03/08/2002 | 3 | ATMEL NANTES | | Y | MM0-G2M265*MQ | 365 |
| 5962-00B0228Q*C | E | 03/08/2002 | 3 | ATMEL NANTES | | Y | MG2M360 | 365 |
| 5962-00B0228Q9A | E | 03/08/2002 | 3 | ATMEL NANTES | | Y | MM0-G2M360*MQ | 365 |
| 5962-00B0229Q*C | E | 03/08/2002 | 3 | ATMEL NANTES | | Y | MG2M480 | 365 |
| 5962-00B0229Q9A | E | 03/08/2002 | 3 | ATMEL NANTES | | Y | MM0-G2M480*MQ | 365 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-00B0301Q*C | C | 10/27/2003 | 3 | ATMEL NANTES | | Y | MG2RTPL_M01 | 365 |
| 5962-00B0301V*C | C | 10/27/2003 | 3 | ATMEL NANTES | | Y | MG2RTPL_M01 | 365 |
| 5962-00B0302Q*C | C | 10/27/2003 | 3 | ATMEL NANTES | | Y | MG2RTPL_MB02 | 365 |
| 5962-00B0302V*C | C | 10/27/2003 | 3 | ATMEL NANTES | | Y | MG2RTPL_MB02 | 365 |
| 5962-00B0303Q*C | C | 10/27/2003 | 3 | ATMEL NANTES | | Y | MG2044P | 365 |
| 5962-00B0303V*C | C | 10/27/2003 | 3 | ATMEL NANTES | | Y | MG2044P | 365 |
| 5962R00B0303V4C | C | 10/27/2003 | 3 | ATMEL NANTES | | Y | SMFW-G2044PHxxxSR | 365 |
| 5962-00B0303Q9A | C | 10/27/2003 | 3 | ATMEL NANTES | | Y | MM0-G2044PH*MQ | 365 |
| 5962-00B0303V9A | C | 10/27/2003 | 3 | ATMEL NANTES | | Y | SM0-G2044PH*SV | 365 |
| 5962R00B0303VNC | C | 10/27/2003 | 3 | ATMEL NANTES | | Y | SMF7-G2044PHxxxSR | 365 |
| 5962-00B0304Q*C | C | 10/27/2003 | 3 | ATMEL NANTES | | Y | MG2142P | 365 |
| 5962-00B0304V*C | C | 10/27/2003 | 3 | ATMEL NANTES | | Y | MG2142P | 365 |
| 5962R00B0304V4C | C | 10/27/2003 | 3 | ATMEL NANTES | | Y | SMFW-G2142PHxxxSR | 365 |
| 5962R00B0304V5C | C | 10/27/2003 | 3 | ATMEL NANTES | | Y | SMF9-G2142PHxxxSR | 365 |
| 5962R00B0304V6C | C | 10/27/2003 | 3 | ATMEL NANTES | | Y | SMKZ-G2142PHxxxSR | 365 |
| 5962-00B0304Q9A | C | 10/27/2003 | 3 | ATMEL NANTES | | Y | MM0-G2142PH*MQ | 365 |
| 5962-00B0304V9A | C | 10/27/2003 | 3 | ATMEL NANTES | | Y | SM0-G2142PH*SV | 365 |
| 5962R00B0304VNC | C | 10/27/2003 | 3 | ATMEL NANTES | | Y | SMF7-G2142PHxxxSR | 365 |
| 5962-00B0305Q*C | C | 10/27/2003 | 3 | ATMEL NANTES | | Y | MG2270P | 365 |
| 5962-00B0305V*C | C | 10/27/2003 | 3 | ATMEL NANTES | | Y | MG2270P | 365 |
| 5962R00B0305V4C | C | 10/27/2003 | 3 | ATMEL NANTES | | Y | SMFW-G2270PHxxxSR | 365 |
| 5962R00B0305V5C | C | 10/27/2003 | 3 | ATMEL NANTES | | Y | SMF9-G2270PHxxxSR | 365 |
| 5962R00B0305V6C | C | 10/27/2003 | 3 | ATMEL NANTES | | Y | SMKZ-G2270PHxxxSR | 365 |
| 5962R00B0305V7C | C | 10/27/2003 | 3 | ATMEL NANTES | | Y | SMYC-G2270PHxxxSR | 365 |
| 5962-00B0305Q9A | C | 10/27/2003 | 3 | ATMEL NANTES | | Y | MM0-G2270PH*MQ | 365 |
| 5962-00B0305V9A | C | 10/27/2003 | 3 | ATMEL NANTES | | Y | SM0-G2270PH*SV | 365 |
| 5962R00B0305VNC | C | 10/27/2003 | 3 | ATMEL NANTES | | Y | SMF7-G2270PHxxxSR | 365 |
| 5962-0150101HXA | A | 10/26/2001 | 1 | INTERPOINT | | Y | MTR283R3S/883 | 594 |
| 5962-0150101HXC | A | 10/26/2001 | 1 | INTERPOINT | | Y | MTR283R3S/883 | 594 |
| 5962-0150101HZA | A | 10/26/2001 | 1 | INTERPOINT | | Y | MTR283R3SF/883 | 594 |
| 5962-0150101HZC | A | 10/26/2001 | 1 | INTERPOINT | | Y | MTR283R3SF/883 | 594 |
| 5962-0150102HXA | A | 10/26/2001 | 1 | INTERPOINT | | Y | SMTR283R3S/HO | 594 |
| 5962-0150102HXC | A | 10/26/2001 | 1 | INTERPOINT | | Y | SMTR283R3S/HO | 594 |
| 5962R0150102HXA | A | 10/26/2001 | 1 | INTERPOINT | | Y | SMTR283R3S/HR | 594 |
| 5962R0150102HXC | A | 10/26/2001 | 1 | INTERPOINT | | Y | SMTR283R3S/HR | 594 |
| 5962R0150102KXA | A | 10/26/2001 | 1 | INTERPOINT | | Y | SMTR283R3S/KR | 594 |
| 5962R0150102KXC | A | 10/26/2001 | 1 | INTERPOINT | | Y | SMTR283R3S/KR | 594 |
| 5962-0150102HZA | A | 10/26/2001 | 1 | INTERPOINT | | Y | SMTR283R3SF/HO | 594 |
| 5962-0150102HZC | A | 10/26/2001 | 1 | INTERPOINT | | Y | SMTR283R3SF/HO | 594 |
| 5962R0150102HZA | A | 10/26/2001 | 1 | INTERPOINT | | Y | SMTR283R3SF/HR | 594 |
| 5962R0150102HZC | A | 10/26/2001 | 1 | INTERPOINT | | Y | SMTR283R3SF/HR | 594 |
| 5962R0150102KZA | A | 10/26/2001 | 1 | INTERPOINT | | Y | SMTR283R3SF/KR | 594 |
| 5962R0150102KZC | A | 10/26/2001 | 1 | INTERPOINT | | Y | SMTR283R3SF/KR | 594 |
| 5962-0150201QXA | A | 03/28/2001 | 1 | UTMC | | Y | UT1750AR12GCA | 409 |
| 5962-0150201QXC | A | 03/28/2001 | 1 | UTMC | | Y | UT1750AR12GCC | 409 |
| 5962H0150201QXA | A | 03/28/2001 | 1 | UTMC | | Y | UT1750AR12GCAH | 409 |
| 5962H0150201QXC | A | 03/28/2001 | 1 | UTMC | | Y | UT1750AR12GCCH | 409 |
| 5962H0150201VXA | A | 03/28/2001 | 1 | UTMC | | Y | UT1750AR12GCAH | 409 |
| 5962H0150201VXC | A | 03/28/2001 | 1 | UTMC | | Y | UT1750AR12GCAH | 409 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-0150201QYC | A | 03/28/2001 | 1 | UTMC | | Y | UT1750AR12WCC | 409 |
| 5962H0150201QYC | A | 03/28/2001 | 1 | UTMC | | Y | UT1750AR12WCCH | 409 |
| 5962H0150201VYC | A | 03/28/2001 | 1 | UTMC | | Y | UT1750AR12WCCH | 409 |
| 5962-0150202QXA | A | 03/28/2001 | 1 | UTMC | | Y | UT1750AR16GCA | 409 |
| 5962-0150202QXC | A | 03/28/2001 | 1 | UTMC | | Y | UT1750AR16GCC | 409 |
| 5962H0150202QXA | A | 03/28/2001 | 1 | UTMC | | Y | UT1750AR16GCAH | 409 |
| 5962H0150202QXC | A | 03/28/2001 | 1 | UTMC | | Y | UT1750AR16GCCH | 409 |
| 5962H0150202VXA | A | 03/28/2001 | 1 | UTMC | | Y | UT1750AR16GCAH | 409 |
| 5962H0150202VXC | A | 03/28/2001 | 1 | UTMC | | Y | UT1750AR16GCCH | 409 |
| 5962-0150202QYC | A | 03/28/2001 | 1 | UTMC | | Y | UT1750AR16WCC | 409 |
| 5962H0150202QYC | A | 03/28/2001 | 1 | UTMC | | Y | UT1750AR16WCCH | 409 |
| 5962H0150202VYC | A | 03/28/2001 | 1 | UTMC | | Y | UT1750AR16WCCH | 409 |
| 5962-0150301DXA | | 01/18/2001 | | (NONE) | | | APT6040DN (GEN) | 899 |
| 5962-0150401DXA | | 03/05/2001 | | (NONE) | | | APT5020DN (GEN) | 899 |
| 5962-0150601HXA | A | 04/10/2002 | | (NONE) | 08/29/2003 | | AD13465 (GEN) | 592 |
| 5962-0150701Q2A | | 03/06/2001 | 2 | SARNOFF | | Y | GEM31701Q2A | 206 |
| 5962-0150701Q2C | | 03/06/2001 | 2 | SARNOFF | | Y | GEM31701Q2C | 206 |
| 5962-0150701QEA | | 03/06/2001 | 2 | SARNOFF | | Y | GEM31701QEA | 206 |
| 5962-0150701QEC | | 03/06/2001 | 2 | SARNOFF | | Y | GEM31701QEC | 206 |
| 5962-0150801QXC | C | 08/27/2004 | 1 | ACTEL | | Y | RT54SX32S-CQ256B | 381 |
| 5962-0150801QYC | C | 08/27/2004 | 1 | ACTEL | | Y | RT54SX32S-CQ208B | 381 |
| 5962-0150802QXC | C | 08/27/2004 | 1 | ACTEL | | Y | RT54SX32S-1CQ256B | 381 |
| 5962-0150802QYC | C | 08/27/2004 | 1 | ACTEL | | Y | RT54SX32S-1CQ208B | 381 |
| 5962-0150803QXC | C | 08/27/2004 | 1 | ACTEL | | Y | RT54SX32S-CQ256E | 381 |
| 5962-0150803QYC | C | 08/27/2004 | 1 | ACTEL | | Y | RT54SX32S-CQ208E | 381 |
| 5962-0150804QXC | C | 08/27/2004 | 1 | ACTEL | | Y | RT54SX32S-1CQ256E | 381 |
| 5962-0150804QYC | C | 08/27/2004 | 1 | ACTEL | | Y | RT54SX32S-1CQ208E | 381 |
| 5962-0150805QXC | C | 08/27/2004 | 1 | ACTEL | | Y | RTSX32SU-CQ256B | 381 |
| 5962-0150805QYC | C | 08/27/2004 | 1 | ACTEL | | Y | RTSX32SU-CQ208B | 381 |
| 5962-0150806QXC | C | 08/27/2004 | 1 | ACTEL | | Y | RTSX32SU-1CQ256B | 381 |
| 5962-0150806QYC | C | 08/27/2004 | 1 | ACTEL | | Y | RTSX32SU-1CQ208B | 381 |
| 5962-0150807QXC | C | 08/27/2004 | 1 | ACTEL | | Y | RTSX32SU-CQ256E | 381 |
| 5962-0150807QYC | C | 08/27/2004 | 1 | ACTEL | | Y | RTSX32SU-CQ208E | 381 |
| 5962-0150808QXC | C | 08/27/2004 | 1 | ACTEL | | Y | RTSX32SU-1CQ256E | 381 |
| 5962-0150808QYC | C | 08/27/2004 | 1 | ACTEL | | Y | RTSX32SU-1CQ208E | 381 |
| 5962F0150901V9A | E | 09/19/2003 | 2 | INTERSIL | | Y | IS0-1845ASRH-Q | 787 |
| 5962F0150901QPC | E | 09/19/2003 | 2 | INTERSIL | | Y | IS7-1845ASRH-8 | 787 |
| 5962F0150901VPC | E | 09/19/2003 | 2 | INTERSIL | | Y | IS7-1845ASRH-Q | 787 |
| 5962F0150901QXC | E | 09/19/2003 | 2 | INTERSIL | | Y | IS9-1845ASRH-8 | 787 |
| 5962F0150901VXC | E | 09/19/2003 | 2 | INTERSIL | | Y | IS9-1845ASRH-Q | 787 |
| 5962F0151001V9A | B | 12/04/2002 | 1 | INTERSIL | | Y | IS0-139ASRH-Q | 776 |
| 5962F0151001QXC | B | 12/04/2002 | 1 | INTERSIL | | Y | IS9-139ASRH-8 | 776 |
| 5962F0151001VXC | B | 12/04/2002 | 1 | INTERSIL | | Y | IS9-139ASRH-Q | 776 |
| 5962L0151101QXA | D | 06/30/2003 | 2 | UTMC | | Y | UT9Q512K32-SCA | 629 |
| 5962L0151101QXC | D | 06/30/2003 | 2 | UTMC | | Y | UT9Q512K32-SCC | 629 |
| 5962L0151101TXA | D | 06/30/2003 | 2 | UTMC | | Y | UT9Q512K32-SCA | 629 |
| 5962L0151101TXC | D | 06/30/2003 | 2 | UTMC | | Y | UT9Q512K32-SCC | 629 |
| 5962-0151201Q2A | | 04/11/2001 | 1 | TI | | Y | UC1709L883B | 555 |
| 5962-0151201V2A | | 04/11/2001 | 1 | TI | | Y | UC1709LQMLV | 555 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-0151201QPA | | 04/11/2001 | 1 | TI | | Y | UC1709J883B | 555 |
| 5962-0151201VPA | | 04/11/2001 | 1 | TI | | Y | UC1709JQMLV | 555 |
| 5962-0151301QXC | | 05/29/2001 | 1 | TI | | Y | MPT57605 | 589 |
| 5962-0151401HMA | A | 10/02/2001 | 1 | DDC | | Y | BU-61865G3-140 | 899 |
| 5962-0151401HMA | A | 10/02/2001 | 1 | DDC | | Y | BU-61865G3-150 | 899 |
| 5962-0151401HMA | A | 10/02/2001 | 1 | DDC IRELAND | | Y | BU-61865G3-140 | 899 |
| 5962-0151401HMA | A | 10/02/2001 | 1 | DDC IRELAND | | Y | BU-61865G3-150 | 899 |
| 5962-0151401HMC | A | 10/02/2001 | 1 | DDC | | Y | BU-61865G3-130 | 899 |
| 5962-0151401HMC | A | 10/02/2001 | 1 | DDC | | Y | BU-61865G3-110 | 899 |
| 5962-0151401HMC | A | 10/02/2001 | 1 | DDC IRELAND | | Y | BU-61865G3-110 | 899 |
| 5962-0151401HMC | A | 10/02/2001 | 1 | DDC IRELAND | | Y | BU-61865G3-130 | 899 |
| 5962-0151401HTA | A | 10/02/2001 | 1 | DDC | | Y | BU-61865F3-140 | 899 |
| 5962-0151401HTA | A | 10/02/2001 | 1 | DDC | | Y | BU-61865F3-150 | 899 |
| 5962-0151401HTA | A | 10/02/2001 | 1 | DDC IRELAND | | Y | BU-61865F3-150 | 899 |
| 5962-0151401HTA | A | 10/02/2001 | 1 | DDC IRELAND | | Y | BU-61865F3-140 | 899 |
| 5962-0151401HTC | A | 10/02/2001 | 1 | DDC | | Y | BU-61865F3-130 | 899 |
| 5962-0151401HTC | A | 10/02/2001 | 1 | DDC | | Y | BU-61865F3-110 | 899 |
| 5962-0151401HTC | A | 10/02/2001 | 1 | DDC IRELAND | | Y | BU-61865F3-110 | 899 |
| 5962-0151401HTC | A | 10/02/2001 | 1 | DDC IRELAND | | Y | BU-61865F3-130 | 899 |
| 5962-0151402HMA | A | 10/02/2001 | 1 | DDC | | Y | BU-61865G4-140 | 899 |
| 5962-0151402HMA | A | 10/02/2001 | 1 | DDC | | Y | BU-61865G4-150 | 899 |
| 5962-0151402HMA | A | 10/02/2001 | 1 | DDC IRELAND | | Y | BU-61865G4-150 | 899 |
| 5962-0151402HMA | A | 10/02/2001 | 1 | DDC IRELAND | | Y | BU-61865G4-140 | 899 |
| 5962-0151402HMC | A | 10/02/2001 | 1 | DDC | | Y | BU-61865G4-110 | 899 |
| 5962-0151402HMC | A | 10/02/2001 | 1 | DDC | | Y | BU-61865G4-130 | 899 |
| 5962-0151402HMC | A | 10/02/2001 | 1 | DDC IRELAND | | Y | BU-61865G4-110 | 899 |
| 5962-0151402HMC | A | 10/02/2001 | 1 | DDC IRELAND | | Y | BU-61865G4-130 | 899 |
| 5962-0151402HTA | A | 10/02/2001 | 1 | DDC | | Y | BU-61865F4-140 | 899 |
| 5962-0151402HTA | A | 10/02/2001 | 1 | DDC | | Y | BU-61865F4-150 | 899 |
| 5962-0151402HTA | A | 10/02/2001 | 1 | DDC IRELAND | | Y | BU-61865F4-150 | 899 |
| 5962-0151402HTA | A | 10/02/2001 | 1 | DDC IRELAND | | Y | BU-61865F4-140 | 899 |
| 5962-0151402HTC | A | 10/02/2001 | 1 | DDC | | Y | BU-61865F4-130 | 899 |
| 5962-0151402HTC | A | 10/02/2001 | 1 | DDC | | Y | BU-61865F4-110 | 899 |
| 5962-0151402HTC | A | 10/02/2001 | 1 | DDC IRELAND | | Y | BU-61865F4-130 | 899 |
| 5962-0151402HTC | A | 10/02/2001 | 1 | DDC IRELAND | | Y | BU-61865F4-110 | 899 |
| 5962-0151403HMA | A | 10/02/2001 | 1 | DDC | | Y | BU-61864G3-150 | 899 |
| 5962-0151403HMA | A | 10/02/2001 | 1 | DDC | | Y | BU-61864G3-140 | 899 |
| 5962-0151403HMA | A | 10/02/2001 | 1 | DDC IRELAND | | Y | BU-61864G3-140 | 899 |
| 5962-0151403HMA | A | 10/02/2001 | 1 | DDC IRELAND | | Y | BU-61864G3-150 | 899 |
| 5962-0151403HMC | A | 10/02/2001 | 1 | DDC | | Y | BU-61864G3-130 | 899 |
| 5962-0151403HMC | A | 10/02/2001 | 1 | DDC | | Y | BU-61864G3-110 | 899 |
| 5962-0151403HMC | A | 10/02/2001 | 1 | DDC IRELAND | | Y | BU-61864G3-130 | 899 |
| 5962-0151403HMC | A | 10/02/2001 | 1 | DDC IRELAND | | Y | BU-61864G3-110 | 899 |
| 5962-0151403HTA | A | 10/02/2001 | 1 | DDC | | Y | BU-61864F3-140 | 899 |
| 5962-0151403HTA | A | 10/02/2001 | 1 | DDC | | Y | BU-61864F3-150 | 899 |
| 5962-0151403HTA | A | 10/02/2001 | 1 | DDC IRELAND | | Y | BU-61864F3-150 | 899 |
| 5962-0151403HTA | A | 10/02/2001 | 1 | DDC IRELAND | | Y | BU-61864F3-140 | 899 |
| 5962-0151403HTC | A | 10/02/2001 | 1 | DDC | | Y | BU-61864F3-110 | 899 |
| 5962-0151403HTC | A | 10/02/2001 | 1 | DDC | | Y | BU-61864F3-130 | 899 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-0151403HTC | A | 10/02/2001 | 1 | DDC IRELAND | | Y | BU-61864F3-130 | 899 |
| 5962-0151403HTC | A | 10/02/2001 | 1 | DDC IRELAND | | Y | BU-61864F3-110 | 899 |
| 5962-0151404HMA | A | 10/02/2001 | 1 | DDC | | Y | BU-61864G4-150 | 899 |
| 5962-0151404HMA | A | 10/02/2001 | 1 | DDC | | Y | BU-61864G4-140 | 899 |
| 5962-0151404HMA | A | 10/02/2001 | 1 | DDC IRELAND | | Y | BU-61864G4-150 | 899 |
| 5962-0151404HMA | A | 10/02/2001 | 1 | DDC IRELAND | | Y | BU-61864G4-140 | 899 |
| 5962-0151404HMC | A | 10/02/2001 | 1 | DDC | | Y | BU-61864G4-110 | 899 |
| 5962-0151404HMC | A | 10/02/2001 | 1 | DDC | | Y | BU-61864G4-130 | 899 |
| 5962-0151404HMC | A | 10/02/2001 | 1 | DDC IRELAND | | Y | BU-61864G4-110 | 899 |
| 5962-0151404HMC | A | 10/02/2001 | 1 | DDC IRELAND | | Y | BU-61864G4-130 | 899 |
| 5962-0151404HTA | A | 10/02/2001 | 1 | DDC | | Y | BU-61864F4-150 | 899 |
| 5962-0151404HTA | A | 10/02/2001 | 1 | DDC | | Y | BU-61864F4-140 | 899 |
| 5962-0151404HTA | A | 10/02/2001 | 1 | DDC IRELAND | | Y | BU-61864F4-140 | 899 |
| 5962-0151404HTA | A | 10/02/2001 | 1 | DDC IRELAND | | Y | BU-61864F4-150 | 899 |
| 5962-0151404HTC | A | 10/02/2001 | 1 | DDC | | Y | BU-61864F4-110 | 899 |
| 5962-0151404HTC | A | 10/02/2001 | 1 | DDC | | Y | BU-61864F4-130 | 899 |
| 5962-0151404HTC | A | 10/02/2001 | 1 | DDC IRELAND | | Y | BU-61864F4-130 | 899 |
| 5962-0151404HTC | A | 10/02/2001 | 1 | DDC IRELAND | | Y | BU-61864F4-110 | 899 |
| 5962-0151405HMA | A | 10/02/2001 | 1 | DDC | | Y | BU-61745G3-140 | 899 |
| 5962-0151405HMA | A | 10/02/2001 | 1 | DDC | | Y | BU-61745G3-150 | 899 |
| 5962-0151405HMA | A | 10/02/2001 | 1 | DDC IRELAND | | Y | BU-61745G3-150 | 899 |
| 5962-0151405HMA | A | 10/02/2001 | 1 | DDC IRELAND | | Y | BU-61745G3-140 | 899 |
| 5962-0151405HMC | A | 10/02/2001 | 1 | DDC | | Y | BU-61745G3-130 | 899 |
| 5962-0151405HMC | A | 10/02/2001 | 1 | DDC | | Y | BU-61745G3-110 | 899 |
| 5962-0151405HMC | A | 10/02/2001 | 1 | DDC IRELAND | | Y | BU-61745G3-110 | 899 |
| 5962-0151405HMC | A | 10/02/2001 | 1 | DDC IRELAND | | Y | BU-61745G3-130 | 899 |
| 5962-0151405HTA | A | 10/02/2001 | 1 | DDC | | Y | BU-61745F3-150 | 899 |
| 5962-0151405HTA | A | 10/02/2001 | 1 | DDC | | Y | BU-61745F3-140 | 899 |
| 5962-0151405HTA | A | 10/02/2001 | 1 | DDC IRELAND | | Y | BU-61745F3-150 | 899 |
| 5962-0151405HTA | A | 10/02/2001 | 1 | DDC IRELAND | | Y | BU-61745F3-140 | 899 |
| 5962-0151405HTC | A | 10/02/2001 | 1 | DDC | | Y | BU-61745F3-130 | 899 |
| 5962-0151405HTC | A | 10/02/2001 | 1 | DDC | | Y | BU-61745F3-110 | 899 |
| 5962-0151405HTC | A | 10/02/2001 | 1 | DDC IRELAND | | Y | BU-61745F3-110 | 899 |
| 5962-0151405HTC | A | 10/02/2001 | 1 | DDC IRELAND | | Y | BU-61745F3-130 | 899 |
| 5962-0151406HMA | A | 10/02/2001 | 1 | DDC | | Y | BU-61745G4-140 | 899 |
| 5962-0151406HMA | A | 10/02/2001 | 1 | DDC | | Y | BU-61745G4-150 | 899 |
| 5962-0151406HMA | A | 10/02/2001 | 1 | DDC IRELAND | | Y | BU-61745G4-150 | 899 |
| 5962-0151406HMA | A | 10/02/2001 | 1 | DDC IRELAND | | Y | BU-61745G4-140 | 899 |
| 5962-0151406HMC | A | 10/02/2001 | 1 | DDC | | Y | BU-61745G4-130 | 899 |
| 5962-0151406HMC | A | 10/02/2001 | 1 | DDC | | Y | BU-61745G4-110 | 899 |
| 5962-0151406HMC | A | 10/02/2001 | 1 | DDC IRELAND | | Y | BU-61745G4-110 | 899 |
| 5962-0151406HMC | A | 10/02/2001 | 1 | DDC IRELAND | | Y | BU-61745G4-130 | 899 |
| 5962-0151406HTA | A | 10/02/2001 | 1 | DDC | | Y | BU-61745F4-140 | 899 |
| 5962-0151406HTA | A | 10/02/2001 | 1 | DDC | | Y | BU-61745F4-150 | 899 |
| 5962-0151406HTA | A | 10/02/2001 | 1 | DDC IRELAND | | Y | BU-61745F4-140 | 899 |
| 5962-0151406HTA | A | 10/02/2001 | 1 | DDC IRELAND | | Y | BU-61745F4-150 | 899 |
| 5962-0151406HTC | A | 10/02/2001 | 1 | DDC | | Y | BU-61745F4-130 | 899 |
| 5962-0151406HTC | A | 10/02/2001 | 1 | DDC | | Y | BU-61745F4-110 | 899 |
| 5962-0151406HTC | A | 10/02/2001 | 1 | DDC IRELAND | | Y | BU-61745F4-110 | 899 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-0151406HTC | A | 10/02/2001 | 1 | DDC IRELAND | | Y | BU-61745F4-130 | 899 |
| 5962-0151407HMA | A | 10/02/2001 | 1 | DDC | | Y | BU-61743G3-150 | 899 |
| 5962-0151407HMA | A | 10/02/2001 | 1 | DDC | | Y | BU-61743G3-140 | 899 |
| 5962-0151407HMA | A | 10/02/2001 | 1 | DDC IRELAND | | Y | BU-61743G3-150 | 899 |
| 5962-0151407HMA | A | 10/02/2001 | 1 | DDC IRELAND | | Y | BU-61743G3-140 | 899 |
| 5962-0151407HMC | A | 10/02/2001 | 1 | DDC | | Y | BU-61743G3-130 | 899 |
| 5962-0151407HMC | A | 10/02/2001 | 1 | DDC | | Y | BU-61743G3-110 | 899 |
| 5962-0151407HMC | A | 10/02/2001 | 1 | DDC IRELAND | | Y | BU-61743G3-110 | 899 |
| 5962-0151407HMC | A | 10/02/2001 | 1 | DDC IRELAND | | Y | BU-61743G3-130 | 899 |
| 5962-0151407HTA | A | 10/02/2001 | 1 | DDC | | Y | BU-61743F3-150 | 899 |
| 5962-0151407HTA | A | 10/02/2001 | 1 | DDC | | Y | BU-61743F3-140 | 899 |
| 5962-0151407HTA | A | 10/02/2001 | 1 | DDC IRELAND | | Y | BU-61743F3-150 | 899 |
| 5962-0151407HTA | A | 10/02/2001 | 1 | DDC IRELAND | | Y | BU-61743F3-140 | 899 |
| 5962-0151407HTC | A | 10/02/2001 | 1 | DDC | | Y | BU-61743F3-130 | 899 |
| 5962-0151407HTC | A | 10/02/2001 | 1 | DDC | | Y | BU-61743F3-110 | 899 |
| 5962-0151407HTC | A | 10/02/2001 | 1 | DDC IRELAND | | Y | BU-61743F3-110 | 899 |
| 5962-0151407HTC | A | 10/02/2001 | 1 | DDC IRELAND | | Y | BU-61743F3-130 | 899 |
| 5962-0151408HMA | A | 10/02/2001 | 1 | DDC | | Y | BU-61743G4-140 | 899 |
| 5962-0151408HMA | A | 10/02/2001 | 1 | DDC | | Y | BU-61743G4-150 | 899 |
| 5962-0151408HMA | A | 10/02/2001 | 1 | DDC IRELAND | | Y | BU-61743G4-150 | 899 |
| 5962-0151408HMA | A | 10/02/2001 | 1 | DDC IRELAND | | Y | BU-61743G4-140 | 899 |
| 5962-0151408HMC | A | 10/02/2001 | 1 | DDC | | Y | BU-61743G4-110 | 899 |
| 5962-0151408HMC | A | 10/02/2001 | 1 | DDC | | Y | BU-61743G4-130 | 899 |
| 5962-0151408HMC | A | 10/02/2001 | 1 | DDC IRELAND | | Y | BU-61743G4-130 | 899 |
| 5962-0151408HMC | A | 10/02/2001 | 1 | DDC IRELAND | | Y | BU-61743G4-110 | 899 |
| 5962-0151408HTA | A | 10/02/2001 | 1 | DDC | | Y | BU-61743F4-140 | 899 |
| 5962-0151408HTA | A | 10/02/2001 | 1 | DDC | | Y | BU-61743F4-150 | 899 |
| 5962-0151408HTA | A | 10/02/2001 | 1 | DDC IRELAND | | Y | BU-61743F4-150 | 899 |
| 5962-0151408HTA | A | 10/02/2001 | 1 | DDC IRELAND | | Y | BU-61743F4-140 | 899 |
| 5962-0151408HTC | A | 10/02/2001 | 1 | DDC | | Y | BU-61743F4-130 | 899 |
| 5962-0151408HTC | A | 10/02/2001 | 1 | DDC | | Y | BU-61743F4-110 | 899 |
| 5962-0151408HTC | A | 10/02/2001 | 1 | DDC IRELAND | | Y | BU-61743F4-130 | 899 |
| 5962-0151408HTC | A | 10/02/2001 | 1 | DDC IRELAND | | Y | BU-61743F4-110 | 899 |
| 5962-0151409HMA | A | 10/02/2001 | 1 | DDC | | Y | BU-61705G3-150 | 899 |
| 5962-0151409HMA | A | 10/02/2001 | 1 | DDC | | Y | BU-61705G3-140 | 899 |
| 5962-0151409HMA | A | 10/02/2001 | 1 | DDC IRELAND | | Y | BU-61705G3-140 | 899 |
| 5962-0151409HMA | A | 10/02/2001 | 1 | DDC IRELAND | | Y | BU-61705G3-150 | 899 |
| 5962-0151409HMC | A | 10/02/2001 | 1 | DDC | | Y | BU-61705G3-110 | 899 |
| 5962-0151409HMC | A | 10/02/2001 | 1 | DDC | | Y | BU-61705G3-130 | 899 |
| 5962-0151409HMC | A | 10/02/2001 | 1 | DDC IRELAND | | Y | BU-61705G3-130 | 899 |
| 5962-0151409HMC | A | 10/02/2001 | 1 | DDC IRELAND | | Y | BU-61705G3-110 | 899 |
| 5962-0151409HTA | A | 10/02/2001 | 1 | DDC | | Y | BU-61705F3-150 | 899 |
| 5962-0151409HTA | A | 10/02/2001 | 1 | DDC | | Y | BU-61705F3-140 | 899 |
| 5962-0151409HTA | A | 10/02/2001 | 1 | DDC IRELAND | | Y | BU-61705F3-150 | 899 |
| 5962-0151409HTA | A | 10/02/2001 | 1 | DDC IRELAND | | Y | BU-61705F3-140 | 899 |
| 5962-0151409HTC | A | 10/02/2001 | 1 | DDC | | Y | BU-61705F3-110 | 899 |
| 5962-0151409HTC | A | 10/02/2001 | 1 | DDC | | Y | BU-61705F3-130 | 899 |
| 5962-0151409HTC | A | 10/02/2001 | 1 | DDC IRELAND | | Y | BU-61705F3-130 | 899 |
| 5962-0151409HTC | A | 10/02/2001 | 1 | DDC IRELAND | | Y | BU-61705F3-110 | 899 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-0151410HMA | A | 10/02/2001 | 1 | DDC | | Y | BU-61705G4-150 | 899 |
| 5962-0151410HMA | A | 10/02/2001 | 1 | DDC | | Y | BU-61705G4-140 | 899 |
| 5962-0151410HMA | A | 10/02/2001 | 1 | DDC IRELAND | | Y | BU-61705G4-140 | 899 |
| 5962-0151410HMA | A | 10/02/2001 | 1 | DDC IRELAND | | Y | BU-61705G4-150 | 899 |
| 5962-0151410HMC | A | 10/02/2001 | 1 | DDC | | Y | BU-61705G4-110 | 899 |
| 5962-0151410HMC | A | 10/02/2001 | 1 | DDC | | Y | BU-61705G4-130 | 899 |
| 5962-0151410HMC | A | 10/02/2001 | 1 | DDC IRELAND | | Y | BU-61705G4-130 | 899 |
| 5962-0151410HMC | A | 10/02/2001 | 1 | DDC IRELAND | | Y | BU-61705G4-110 | 899 |
| 5962-0151410HTA | A | 10/02/2001 | 1 | DDC | | Y | BU-61705F4-150 | 899 |
| 5962-0151410HTA | A | 10/02/2001 | 1 | DDC | | Y | BU-61705F4-140 | 899 |
| 5962-0151410HTA | A | 10/02/2001 | 1 | DDC IRELAND | | Y | BU-61705F4-150 | 899 |
| 5962-0151410HTA | A | 10/02/2001 | 1 | DDC IRELAND | | Y | BU-61705F4-140 | 899 |
| 5962-0151410HTC | A | 10/02/2001 | 1 | DDC | | Y | BU-61705F4-130 | 899 |
| 5962-0151410HTC | A | 10/02/2001 | 1 | DDC | | Y | BU-61705F4-110 | 899 |
| 5962-0151410HTC | A | 10/02/2001 | 1 | DDC IRELAND | | Y | BU-61705F4-110 | 899 |
| 5962-0151410HTC | A | 10/02/2001 | 1 | DDC IRELAND | | Y | BU-61705F4-130 | 899 |
| 5962-0151411HMA | A | 10/02/2001 | 1 | DDC | | Y | BU-61703G3-150 | 899 |
| 5962-0151411HMA | A | 10/02/2001 | 1 | DDC | | Y | BU-61703G3-140 | 899 |
| 5962-0151411HMA | A | 10/02/2001 | 1 | DDC IRELAND | | Y | BU-61703G3-150 | 899 |
| 5962-0151411HMA | A | 10/02/2001 | 1 | DDC IRELAND | | Y | BU-61703G3-140 | 899 |
| 5962-0151411HMC | A | 10/02/2001 | 1 | DDC | | Y | BU-61703G3-130 | 899 |
| 5962-0151411HMC | A | 10/02/2001 | 1 | DDC | | Y | BU-61703G3-110 | 899 |
| 5962-0151411HMC | A | 10/02/2001 | 1 | DDC IRELAND | | Y | BU-61703G3-130 | 899 |
| 5962-0151411HMC | A | 10/02/2001 | 1 | DDC IRELAND | | Y | BU-61703G3-110 | 899 |
| 5962-0151411HTA | A | 10/02/2001 | 1 | DDC | | Y | BU-61703F3-150 | 899 |
| 5962-0151411HTA | A | 10/02/2001 | 1 | DDC | | Y | BU-61703F3-140 | 899 |
| 5962-0151411HTA | A | 10/02/2001 | 1 | DDC IRELAND | | Y | BU-61703F3-150 | 899 |
| 5962-0151411HTA | A | 10/02/2001 | 1 | DDC IRELAND | | Y | BU-61703F3-140 | 899 |
| 5962-0151411HTC | A | 10/02/2001 | 1 | DDC | | Y | BU-61703F3-110 | 899 |
| 5962-0151411HTC | A | 10/02/2001 | 1 | DDC | | Y | BU-61703F3-130 | 899 |
| 5962-0151411HTC | A | 10/02/2001 | 1 | DDC IRELAND | | Y | BU-61703F3-130 | 899 |
| 5962-0151411HTC | A | 10/02/2001 | 1 | DDC IRELAND | | Y | BU-61703F3-110 | 899 |
| 5962-0151412HMA | A | 10/02/2001 | 1 | DDC | | Y | BU-61703G4-150 | 899 |
| 5962-0151412HMA | A | 10/02/2001 | 1 | DDC | | Y | BU-61703G4-140 | 899 |
| 5962-0151412HMA | A | 10/02/2001 | 1 | DDC IRELAND | | Y | BU-61703G4-150 | 899 |
| 5962-0151412HMA | A | 10/02/2001 | 1 | DDC IRELAND | | Y | BU-61703G4-140 | 899 |
| 5962-0151412HMC | A | 10/02/2001 | 1 | DDC | | Y | BU-61703G4-130 | 899 |
| 5962-0151412HMC | A | 10/02/2001 | 1 | DDC | | Y | BU-61703G4-110 | 899 |
| 5962-0151412HMC | A | 10/02/2001 | 1 | DDC IRELAND | | Y | BU-61703G4-130 | 899 |
| 5962-0151412HMC | A | 10/02/2001 | 1 | DDC IRELAND | | Y | BU-61703G4-110 | 899 |
| 5962-0151412HTA | A | 10/02/2001 | 1 | DDC | | Y | BU-61703F4-150 | 899 |
| 5962-0151412HTA | A | 10/02/2001 | 1 | DDC | | Y | BU-61703F4-140 | 899 |
| 5962-0151412HTA | A | 10/02/2001 | 1 | DDC IRELAND | | Y | BU-61703F4-140 | 899 |
| 5962-0151412HTA | A | 10/02/2001 | 1 | DDC IRELAND | | Y | BU-61703F4-150 | 899 |
| 5962-0151412HTC | A | 10/02/2001 | 1 | DDC | | Y | BU-61703F4-130 | 899 |
| 5962-0151412HTC | A | 10/02/2001 | 1 | DDC | | Y | BU-61703F4-110 | 899 |
| 5962-0151412HTC | A | 10/02/2001 | 1 | DDC IRELAND | | Y | BU-61703F4-130 | 899 |
| 5962-0151412HTC | A | 10/02/2001 | 1 | DDC IRELAND | | Y | BU-61703F4-110 | 899 |
| 5962-0151413HMA | A | 10/02/2001 | 1 | DDC | | Y | BU-61845G3-150 | 899 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-0151413HMA | A | 10/02/2001 | 1 | DDC | | Y | BU-61845G3-140 | 899 |
| 5962-0151413HMA | A | 10/02/2001 | 1 | DDC IRELAND | | Y | BU-61845G3-150 | 899 |
| 5962-0151413HMA | A | 10/02/2001 | 1 | DDC IRELAND | | Y | BU-61845G3-140 | 899 |
| 5962-0151413HMC | A | 10/02/2001 | 1 | DDC | | Y | BU-61845G3-110 | 899 |
| 5962-0151413HMC | A | 10/02/2001 | 1 | DDC | | Y | BU-61845G3-130 | 899 |
| 5962-0151413HMC | A | 10/02/2001 | 1 | DDC IRELAND | | Y | BU-61845G3-110 | 899 |
| 5962-0151413HMC | A | 10/02/2001 | 1 | DDC IRELAND | | Y | BU-61845G3-130 | 899 |
| 5962-0151413HTA | A | 10/02/2001 | 1 | DDC | | Y | BU-61845F3-150 | 899 |
| 5962-0151413HTA | A | 10/02/2001 | 1 | DDC | | Y | BU-61845F3-140 | 899 |
| 5962-0151413HTA | A | 10/02/2001 | 1 | DDC IRELAND | | Y | BU-61845F3-150 | 899 |
| 5962-0151413HTA | A | 10/02/2001 | 1 | DDC IRELAND | | Y | BU-61845F3-140 | 899 |
| 5962-0151413HTC | A | 10/02/2001 | 1 | DDC | | Y | BU-61845F3-130 | 899 |
| 5962-0151413HTC | A | 10/02/2001 | 1 | DDC | | Y | BU-61845F3-110 | 899 |
| 5962-0151413HTC | A | 10/02/2001 | 1 | DDC IRELAND | | Y | BU-61845F3-130 | 899 |
| 5962-0151413HTC | A | 10/02/2001 | 1 | DDC IRELAND | | Y | BU-61845F3-110 | 899 |
| 5962-0151414HMA | A | 10/02/2001 | 1 | DDC | | Y | BU-61845G4-140 | 899 |
| 5962-0151414HMA | A | 10/02/2001 | 1 | DDC | | Y | BU-61845G4-150 | 899 |
| 5962-0151414HMA | A | 10/02/2001 | 1 | DDC IRELAND | | Y | BU-61845G4-150 | 899 |
| 5962-0151414HMA | A | 10/02/2001 | 1 | DDC IRELAND | | Y | BU-61845G4-140 | 899 |
| 5962-0151414HMC | A | 10/02/2001 | 1 | DDC | | Y | BU-61845G4-130 | 899 |
| 5962-0151414HMC | A | 10/02/2001 | 1 | DDC | | Y | BU-61845G4-110 | 899 |
| 5962-0151414HMC | A | 10/02/2001 | 1 | DDC IRELAND | | Y | BU-61845G4-130 | 899 |
| 5962-0151414HMC | A | 10/02/2001 | 1 | DDC IRELAND | | Y | BU-61845G4-110 | 899 |
| 5962-0151414HTA | A | 10/02/2001 | 1 | DDC | | Y | BU-61845F4-150 | 899 |
| 5962-0151414HTA | A | 10/02/2001 | 1 | DDC | | Y | BU-61845F4-140 | 899 |
| 5962-0151414HTA | A | 10/02/2001 | 1 | DDC IRELAND | | Y | BU-61845F4-150 | 899 |
| 5962-0151414HTA | A | 10/02/2001 | 1 | DDC IRELAND | | Y | BU-61845F4-140 | 899 |
| 5962-0151414HTC | A | 10/02/2001 | 1 | DDC | | Y | BU-61845F4-110 | 899 |
| 5962-0151414HTC | A | 10/02/2001 | 1 | DDC | | Y | BU-61845F4-130 | 899 |
| 5962-0151414HTC | A | 10/02/2001 | 1 | DDC IRELAND | | Y | BU-61845F4-130 | 899 |
| 5962-0151414HTC | A | 10/02/2001 | 1 | DDC IRELAND | | Y | BU-61845F4-110 | 899 |
| 5962-0151415HMA | A | 10/02/2001 | 1 | DDC | | Y | BU-61843G3-150 | 899 |
| 5962-0151415HMA | A | 10/02/2001 | 1 | DDC | | Y | BU-61843G3-140 | 899 |
| 5962-0151415HMA | A | 10/02/2001 | 1 | DDC IRELAND | | Y | BU-61843G3-150 | 899 |
| 5962-0151415HMA | A | 10/02/2001 | 1 | DDC IRELAND | | Y | BU-61843G3-140 | 899 |
| 5962-0151415HMC | A | 10/02/2001 | 1 | DDC | | Y | BU-61843G3-130 | 899 |
| 5962-0151415HMC | A | 10/02/2001 | 1 | DDC | | Y | BU-61843G3-110 | 899 |
| 5962-0151415HMC | A | 10/02/2001 | 1 | DDC IRELAND | | Y | BU-61843G3-130 | 899 |
| 5962-0151415HMC | A | 10/02/2001 | 1 | DDC IRELAND | | Y | BU-61843G3-110 | 899 |
| 5962-0151415HTA | A | 10/02/2001 | 1 | DDC | | Y | BU-61843F3-150 | 899 |
| 5962-0151415HTA | A | 10/02/2001 | 1 | DDC | | Y | BU-61843F3-140 | 899 |
| 5962-0151415HTA | A | 10/02/2001 | 1 | DDC IRELAND | | Y | BU-61843F3-150 | 899 |
| 5962-0151415HTA | A | 10/02/2001 | 1 | DDC IRELAND | | Y | BU-61843F3-140 | 899 |
| 5962-0151415HTC | A | 10/02/2001 | 1 | DDC | | Y | BU-61843F3-110 | 899 |
| 5962-0151415HTC | A | 10/02/2001 | 1 | DDC | | Y | BU-61843F3-130 | 899 |
| 5962-0151415HTC | A | 10/02/2001 | 1 | DDC IRELAND | | Y | BU-61843F3-130 | 899 |
| 5962-0151415HTC | A | 10/02/2001 | 1 | DDC IRELAND | | Y | BU-61843F3-110 | 899 |
| 5962-0151416HMA | A | 10/02/2001 | 1 | DDC | | Y | BU-61843G4-150 | 899 |
| 5962-0151416HMA | A | 10/02/2001 | 1 | DDC | | Y | BU-61843G4-140 | 899 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-0151416HMA | A | 10/02/2001 | 1 | DDC IRELAND | | Y | BU-61843G4-150 | 899 |
| 5962-0151416HMA | A | 10/02/2001 | 1 | DDC IRELAND | | Y | BU-61843G4-140 | 899 |
| 5962-0151416HMC | A | 10/02/2001 | 1 | DDC | | Y | BU-61843G4-130 | 899 |
| 5962-0151416HMC | A | 10/02/2001 | 1 | DDC | | Y | BU-61843G4-110 | 899 |
| 5962-0151416HMC | A | 10/02/2001 | 1 | DDC IRELAND | | Y | BU-61843G4-130 | 899 |
| 5962-0151416HMC | A | 10/02/2001 | 1 | DDC IRELAND | | Y | BU-61843G4-110 | 899 |
| 5962-0151416HTA | A | 10/02/2001 | 1 | DDC | | Y | BU-61843F4-150 | 899 |
| 5962-0151416HTA | A | 10/02/2001 | 1 | DDC | | Y | BU-61843F4-140 | 899 |
| 5962-0151416HTA | A | 10/02/2001 | 1 | DDC IRELAND | | Y | BU-61843F4-140 | 899 |
| 5962-0151416HTA | A | 10/02/2001 | 1 | DDC IRELAND | | Y | BU-61843F4-150 | 899 |
| 5962-0151416HTC | A | 10/02/2001 | 1 | DDC | | Y | BU-61843F4-110 | 899 |
| 5962-0151416HTC | A | 10/02/2001 | 1 | DDC | | Y | BU-61843F4-130 | 899 |
| 5962-0151416HTC | A | 10/02/2001 | 1 | DDC IRELAND | | Y | BU-61843F4-110 | 899 |
| 5962-0151416HTC | A | 10/02/2001 | 1 | DDC IRELAND | | Y | BU-61843F4-130 | 899 |
| 5962-0151501QXC | D | 08/27/2004 | 1 | ACTEL | | Y | RT54SX72S-CQ256B | 381 |
| 5962-0151501QYC | D | 08/27/2004 | 1 | ACTEL | | Y | RT54SX72S-CQ208B | 381 |
| 5962-0151502QXC | D | 08/27/2004 | 1 | ACTEL | | Y | RT54SX72S-1CQ256B | 381 |
| 5962-0151502QYC | D | 08/27/2004 | 1 | ACTEL | | Y | RT54SX72S-1CQ208B | 381 |
| 5962-0151503QXC | D | 08/27/2004 | 1 | ACTEL | | Y | RT54SX72S-CQ256E | 381 |
| 5962-0151503QYC | D | 08/27/2004 | 1 | ACTEL | | Y | RT54SX72S-CQ208E | 381 |
| 5962-0151504QXC | D | 08/27/2004 | 1 | ACTEL | | Y | RT54SX72S-1CQ256E | 381 |
| 5962-0151504QYC | D | 08/27/2004 | 1 | ACTEL | | Y | RT54SX72S-1CQ208E | 381 |
| 5962-0151505QXC | D | 08/27/2004 | 1 | ACTEL | | Y | RTSX72SU-CQ256B | 381 |
| 5962-0151505QYC | D | 08/27/2004 | 1 | ACTEL | | Y | RTSX72SU-CQ208B | 381 |
| 5962-0151506QXC | D | 08/27/2004 | 1 | ACTEL | | Y | RTSX72SU-1CQ256B | 381 |
| 5962-0151506QYC | D | 08/27/2004 | 1 | ACTEL | | Y | RTSX72SU-1CQ208B | 381 |
| 5962-0151507QXC | D | 08/27/2004 | 1 | ACTEL | | Y | RTSX72SU-CQ256E | 381 |
| 5962-0151507QYC | D | 08/27/2004 | 1 | ACTEL | | Y | RTSX72SU-CQ208E | 381 |
| 5962-0151508QXC | D | 08/27/2004 | 1 | ACTEL | | Y | RTSX72SU-1CQ256E | 381 |
| 5962-0151508QYC | D | 08/27/2004 | 1 | ACTEL | | Y | RTSX72SU-1CQ208E | 381 |
| 5962H0151601QXA | A | 05/15/2001 | 1 | UTMC | | Y | UT28F64LVC-55PCA | 657 |
| 5962H0151601QXC | A | 05/15/2001 | 1 | UTMC | | Y | UT28F64LVC-55PCC | 657 |
| 5962H0151601VXA | A | 05/15/2001 | 1 | UTMC | | Y | UT28F64LVC-55PCA | 657 |
| 5962H0151601VXC | A | 05/15/2001 | 1 | UTMC | | Y | UT28F64LVC-55PCC | 657 |
| 5962H0151601QYA | A | 05/15/2001 | 1 | UTMC | | Y | UT28F64LVC-55UCA | 657 |
| 5962H0151601QYC | A | 05/15/2001 | 1 | UTMC | | Y | UT28F64LVC-55UCC | 657 |
| 5962H0151601VYA | A | 05/15/2001 | 1 | UTMC | | Y | UT28F64LVC-55UCA | 657 |
| 5962H0151601VYC | A | 05/15/2001 | 1 | UTMC | | Y | UT28F64LVC-55UCC | 657 |
| 5962H0151701QXA | A | 05/25/2004 | 1 | UTMC | | Y | UT28F256LVC-65UCA | 650 |
| 5962H0151701QXC | A | 05/25/2004 | 1 | UTMC | | Y | UT28F256LVC-65UCC | 650 |
| 5962H0151701VXA | A | 05/25/2004 | 1 | UTMC | | Y | UT28F256LVC-65UCA | 650 |
| 5962H0151701VXC | A | 05/25/2004 | 1 | UTMC | | Y | UT28F256LVC-65UCC | 650 |
| 5962H0151701QYA | A | 05/25/2004 | 1 | UTMC | | Y | UT28F256LVC-65PCA | 650 |
| 5962H0151701QYC | A | 05/25/2004 | 1 | UTMC | | Y | UT28F256LVC-65PCC | 650 |
| 5962H0151701VYA | A | 05/25/2004 | 1 | UTMC | | Y | UT28F256LVC-65PCA | 650 |
| 5962H0151701VYC | A | 05/25/2004 | 1 | UTMC | | Y | UT28F256LVC-65PCC | 650 |
| 5962H0151702QXA | A | 05/25/2004 | 1 | UTMC | | Y | UT28F256LVQLC-65UC | 650 |
| 5962H0151702QXC | A | 05/25/2004 | 1 | UTMC | | Y | UT28F256LVQLC-65UC | 650 |
| 5962H0151702VXA | A | 05/25/2004 | 1 | UTMC | | Y | UT28F256LVQLC-65UC | 650 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962H0151702VXC | A | 05/25/2004 | 1 | UTMC | | Y | UT28F256LVQLC-65UC | 650 |
| 5962F0151703QXA | A | 05/25/2004 | 1 | UTMC | | Y | UT28F256LVQLC-65UC | 650 |
| 5962F0151703QXC | A | 05/25/2004 | 1 | UTMC | | Y | UT28F256LVQLC-65UC | 650 |
| 5962F0151703VXA | A | 05/25/2004 | 1 | UTMC | | Y | UT28F256LVQLC-65UC | 650 |
| 5962F0151703VXC | A | 05/25/2004 | 1 | UTMC | | Y | UT28F256LVQLC-65UC | 650 |
| 5962-0151801QXC | C | 03/25/2003 | 1 | ACTEL | | Y | A54SX32A-CQ256B | 381 |
| 5962-0151801QYC | C | 03/25/2003 | 1 | ACTEL | | Y | A54SX32A-CQ208B | 381 |
| 5962-0151802QXC | C | 03/25/2003 | 1 | ACTEL | | Y | A54SX32A-1CQ256B | 381 |
| 5962-0151802QYC | C | 03/25/2003 | 1 | ACTEL | | Y | A54SX32A-1CQ208B | 381 |
| 5962R0151901TXA | | 09/14/2001 | | (NONE) | 08/29/2003 | | AD10265 (GEN) | 592 |
| 5962-0152001QPA | B | 04/04/2003 | 1 | TI | | Y | UC1710J883B | 555 |
| 5962-0152001VPA | B | 04/04/2003 | 1 | TI | | Y | UC1710JQMLV | 555 |
| 5962-0152001VXA | B | 04/04/2003 | 1 | TI | | Y | UC1710JQMLV | 555 |
| 5962F0152101V9A | A | 06/11/2001 | 1 | INTERSIL | | Y | ISL74422ARHVX | 555 |
| 5962F0152101QXC | A | 06/11/2001 | 1 | INTERSIL | | Y | ISL74422ARHQF | 555 |
| 5962F0152101VXC | A | 06/11/2001 | 1 | INTERSIL | | Y | ISL74422ARHVF | 555 |
| 5962-0152401QXA | | 05/24/2001 | 2 | STMICRO | | Y | 54AC573K02Q | 341 |
| 5962-0152401QXC | | 05/24/2001 | 2 | STMICRO | | Y | 54AC573K01Q | 341 |
| 5962-0152401VXA | | 05/24/2001 | 2 | STMICRO | | Y | 54AC573K02V | 341 |
| 5962-0152401VXC | | 05/24/2001 | 2 | STMICRO | | Y | 54AC573K01V | 341 |
| 5962-0152901MYA | | 12/12/2001 | 1 | PYRAMID | | | P4C167-45L20MB | 616 |
| 5962-0153001QXA | | 04/22/2003 | 2 | TI | | Y | SMJ320VC5416HFG | 432 |
| 5962L0153201QYA | B | 02/21/2003 | 2 | UTMC | | Y | UT8Q1024-UWA | 629 |
| 5962L0153201QYC | B | 02/21/2003 | 2 | UTMC | | Y | UT8Q1024-UWC | 629 |
| 5962L0153201TYA | B | 02/21/2003 | 2 | UTMC | | Y | UT8Q1024-UWA | 629 |
| 5962L0153201TYC | B | 02/21/2003 | 2 | UTMC | | Y | UT8Q1024-UWC | 629 |
| 5962L0153301QXC | B | 06/30/2003 | 2 | UTMC | | Y | UT8Q512K32-SCA | 629 |
| 5962L0153301TXC | B | 06/30/2003 | 2 | UTMC | | Y | UT8Q512K32-SCC | 629 |
| 5962R0153401Q9A | C | 10/27/2003 | 1 | UTMC | | Y | UT54LVDS217-QDIE | 599 |
| 5962R0153401V9A | C | 10/27/2003 | 1 | UTMC | | Y | UT54LVDS217-VDIE | 599 |
| 5962R0153401QXA | C | 10/27/2003 | 1 | UTMC | | Y | UT54LVDS217UCA | 599 |
| 5962R0153401QXC | C | 10/27/2003 | 1 | UTMC | | Y | UT54LVDS217UCC | 599 |
| 5962R0153401VXA | C | 10/27/2003 | 1 | UTMC | | Y | UT54LVDS217UCA | 599 |
| 5962R0153401VXC | C | 10/27/2003 | 1 | UTMC | | Y | UT54LVDS217UCC | 599 |
| 5962F0153402Q9A | C | 10/27/2003 | 1 | UTMC | | Y | UT54LVDS217-QDIE | 599 |
| 5962F0153402V9A | C | 10/27/2003 | 1 | UTMC | | Y | UT54LVDS217-VDIE | 599 |
| 5962H0153402Q9A | C | 10/27/2003 | 1 | UTMC | | Y | UT54LVDS217-QDIE | 599 |
| 5962H0153402V9A | C | 10/27/2003 | 1 | UTMC | | Y | UT54LVDS217-VDIE | 599 |
| 5962F0153402QXA | C | 10/27/2003 | 1 | UTMC | | Y | UT54LVDS217UCA | 599 |
| 5962F0153402QXC | C | 10/27/2003 | 1 | UTMC | | Y | UT54LVDS217UCC | 599 |
| 5962F0153402VXA | C | 10/27/2003 | 1 | UTMC | | Y | UT54LVDS217UCA | 599 |
| 5962F0153402VXC | C | 10/27/2003 | 1 | UTMC | | Y | UT54LVDS217UCC | 599 |
| 5962F0153402VXC | C | 10/27/2003 | 1 | UTMC | | Y | UT54LVDS217UCC | 599 |
| 5962H0153402QXA | C | 10/27/2003 | 1 | UTMC | | Y | UT54LVDS217UCA | 599 |
| 5962H0153402QXC | C | 10/27/2003 | 1 | UTMC | | Y | UT54LVDS217UCC | 599 |
| 5962H0153402VXA | C | 10/27/2003 | 1 | UTMC | | Y | UT54LVDS217UCA | 599 |
| 5962H0153402VXC | C | 10/27/2003 | 1 | UTMC | | Y | UT54LVDS217UCC | 599 |
| 5962H0153501Q9A | A | 11/10/2003 | 1 | UTMC | | Y | UT54LVDS218-QDIE | 599 |
| 5962H0153501V9A | A | 11/10/2003 | 1 | UTMC | | Y | UT54LVDS218-VDIE | 599 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962H0153501QXA | A | 11/10/2003 | 1 | UTMC | | Y | UT54LVDS218UCA | 599 |
| 5962H0153501QXC | A | 11/10/2003 | 1 | UTMC | | Y | UT54LVDS218UCC | 599 |
| 5962H0153501VXA | A | 11/10/2003 | 1 | UTMC | | Y | UT54LVDS218UCA | 599 |
| 5962H0153501VXC | A | 11/10/2003 | 1 | UTMC | | Y | UT54LVDS218UCC | 599 |
| 5962H0153502Q9A | A | 11/10/2003 | 1 | UTMC | | Y | UT54LVDS218-QDIE | 599 |
| 5962H0153502V9A | A | 11/10/2003 | 1 | UTMC | | Y | UT54LVDS218-VDIE | 599 |
| 5962H0153502QXA | A | 11/10/2003 | 1 | UTMC | | Y | UT54LVDS218UCA | 599 |
| 5962H0153502QXC | A | 11/10/2003 | 1 | UTMC | | Y | UT54LVDS218UCC | 599 |
| 5962H0153502VXA | A | 11/10/2003 | 1 | UTMC | | Y | UT54LVDS218UCA | 599 |
| 5962H0153502VXC | A | 11/10/2003 | 1 | UTMC | | Y | UT54LVDS218UCC | 599 |
| 5962H0153601QYA | C | 04/08/2003 | 1 | UTMC | | Y | UT54LVDM328UCA | 599 |
| 5962H0153601QYC | C | 04/08/2003 | 1 | UTMC | | Y | UT54LVDM328UCC | 599 |
| 5962H0153601VYA | C | 04/08/2003 | 1 | UTMC | | Y | UT54LVDM328UCA | 599 |
| 5962H0153601VYC | C | 04/08/2003 | 1 | UTMC | | Y | UT54LVDM328UCC | 599 |
| 5962R0153601QYA | C | 04/08/2003 | 1 | UTMC | | Y | UT54LVDM328UCA | 599 |
| 5962R0153601QYC | C | 04/08/2003 | 1 | UTMC | | Y | UT54LVDM328UCC | 599 |
| 5962R0153601VYA | C | 04/08/2003 | 1 | UTMC | | Y | UT54LVDM328UCA | 599 |
| 5962R0153601VYC | C | 04/08/2003 | 1 | UTMC | | Y | UT54LVDM328UCC | 599 |
| 5962H0153701QXA | A | 11/08/2002 | 1 | UTMC | | Y | UT54LVDM228UPA | 599 |
| 5962H0153701QXC | A | 11/08/2002 | 1 | UTMC | | Y | UT54LVDM228UPC | 599 |
| 5962H0153701VXA | A | 11/08/2002 | 1 | UTMC | | Y | UT54LVDM228UPA | 599 |
| 5962H0153701VXC | A | 11/08/2002 | 1 | UTMC | | Y | UT54LVDM228UPC | 599 |
| 5962-01A0101QXA | | 10/24/2001 | 2 | AMI | | Y | 15028-505 | 365 |
| 5962-01A0301QXC | | 08/07/2001 | 2 | AMI | | Y | 15022-009 | 365 |
| 5962-01A0401QXC | | 11/21/2000 | 3 | AMI | | Y | 6825-518 | 365 |
| 5962-01A0501QXA | | 09/10/2001 | 1 | AMI | | Y | 13612-501 | 365 |
| 5962-01A0601QXC | | 12/05/2000 | 3 | AMI | | Y | 6817-534 | 365 |
| 5962-01A0701QXC | | 01/09/2001 | 2 | AMI | | Y | 6817-533 | 365 |
| 5962-01A0801NXB | | 05/07/2001 | 2 | AMI | | Y | 8697-001 | 365 |
| 5962-01A0901NXB | | 05/07/2001 | 2 | AMI | | Y | 8828-001 | 365 |
| 5962-01A1001NXB | | 03/27/2001 | 3 | AMI | | Y | 6817-536 | 365 |
| 5962-01A1101NXB | | 03/26/2001 | 3 | AMI | | Y | 6805-063 | 365 |
| 5962-01A1201NXB | | 03/27/2001 | 3 | AMI | | Y | 6825-013 | 365 |
| 5962-01A1301QXC | | 05/09/2001 | 3 | AMI | | Y | 12032-501 | 365 |
| 5962-01A1401QXC | | 05/09/2001 | 2 | AMI | | Y | 06580-044 | 365 |
| 5962-01A1501NXB | | 01/30/2003 | 3 | AMI | | Y | 13755-502 | 365 |
| 5962-01A1601QXC | | 09/04/2001 | 1 | AMI | | Y | 15028-507 | 365 |
| 5962-01A1701QXC | | 08/08/2001 | 2 | ATMEL NANTES | | Y | TSS901EAMQ | 365 |
| 5962-01A1701VXC | | 08/08/2001 | 2 | ATMEL NANTES | | Y | TSS901EASV | 365 |
| 5962-01A1801QXC | A | 07/24/2002 | | (NONE) | | | 29C516E (GEN) | 365 |
| 5962-01A1801VXC | A | 07/24/2002 | | (NONE) | | | 29C516E (GEN) | 365 |
| 5962-01A1801QYC | A | 07/24/2002 | 2 | ATMEL NANTES | | Y | MMFR-29C516EMQ | 365 |
| 5962-01A1801VYC | A | 07/24/2002 | 2 | ATMEL NANTES | | Y | SMFR-29C516ESV | 365 |
| 5962-01A1801QZC | A | 07/24/2002 | 2 | ATMEL NANTES | | Y | MMKR-29C516EMQ | 365 |
| 5962-01A1801VZC | A | 07/24/2002 | 2 | ATMEL NANTES | | Y | SMKR-29C516ESV | 365 |
| 5962-01A1901QXC | | 09/04/2001 | 2 | AMI | | Y | 15022-512 | 365 |
| 5962-01A2001NXB | | 10/15/2001 | 1 | AMI | | Y | 12074-001 | 365 |
| 5962-01B0101Q*C | C | 07/20/2004 | 3 | ATMEL NANTES | | Y | TH1099RHabc*MQ | 365 |
| 5962-01B0101V*C | C | 07/20/2004 | 3 | ATMEL NANTES | | Y | TH1099RHabc*SV | 365 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962R01B0101V*C | C | 07/20/2004 | 3 | ATMEL NANTES | | Y | TH1099RHabc*SR | 365 |
| 5962-01B0101Q9A | C | 07/20/2004 | 3 | ATMEL NANTES | | Y | TH1099RHabcDDMQ | 365 |
| 5962-01B0101V9A | C | 07/20/2004 | 3 | ATMEL NANTES | | Y | TH1099RHabcDDSV | 365 |
| 5962-01B0102Q*C | C | 07/20/2004 | 3 | ATMEL NANTES | | Y | TH1156RHabc*MQ | 365 |
| 5962-01B0102V*C | C | 07/20/2004 | 3 | ATMEL NANTES | | Y | TH1156RHabc*SV | 365 |
| 5962R01B0102V*C | C | 07/20/2004 | 3 | ATMEL NANTES | | Y | TH1156RHabc*SR | 365 |
| 5962-01B0102Q9A | C | 07/20/2004 | 3 | ATMEL NANTES | | Y | TH1156RHabcDDMQ | 365 |
| 5962-01B0102V9A | C | 07/20/2004 | 3 | ATMEL NANTES | | Y | TH1156RHabcDDSV | 365 |
| 5962-01B0103Q*C | C | 07/20/2004 | 3 | ATMEL NANTES | | Y | TH1242RHabc*MQ | 365 |
| 5962-01B0103V*C | C | 07/20/2004 | 3 | ATMEL NANTES | | Y | TH1242RHabc*SV | 365 |
| 5962R01B0103V*C | C | 07/20/2004 | 3 | ATMEL NANTES | | Y | TH1242RHabc*SR | 365 |
| 5962-01B0103Q9A | C | 07/20/2004 | 3 | ATMEL NANTES | | Y | TH1242RHabcDDMQ | 365 |
| 5962-01B0103V9A | C | 07/20/2004 | 3 | ATMEL NANTES | | Y | TH1242RHabcDDSV | 365 |
| 5962-01B0104Q*C | C | 07/20/2004 | 3 | ATMEL NANTES | | Y | TH1332RHabc*MQ | 365 |
| 5962-01B0104Q9A | C | 07/20/2004 | 3 | ATMEL NANTES | | Y | TH1332RHabcDDMQ | 365 |
| 5962-01B0105Q*C | C | 07/20/2004 | 3 | ATMEL NANTES | | Y | TH1099SHabc*MQ | 365 |
| 5962-01B0105V*C | C | 07/20/2004 | 3 | ATMEL NANTES | | Y | TH1099SHabc*SV | 365 |
| 5962R01B0105V*C | C | 07/20/2004 | 3 | ATMEL NANTES | | Y | TH1099SHabc*SR | 365 |
| 5962-01B0105Q9A | C | 07/20/2004 | 3 | ATMEL NANTES | | Y | TH1099SHabcDDMQ | 365 |
| 5962-01B0105V9A | C | 07/20/2004 | 3 | ATMEL NANTES | | Y | TH1099SHabcDDSV | 365 |
| 5962-01B0106Q*C | C | 07/20/2004 | 3 | ATMEL NANTES | | Y | TH1156SHabc*MQ | 365 |
| 5962-01B0106V*C | C | 07/20/2004 | 3 | ATMEL NANTES | | Y | TH1156SHabc*SV | 365 |
| 5962R01B0106V*C | C | 07/20/2004 | 3 | ATMEL NANTES | | Y | TH1156SHabc*SR | 365 |
| 5962-01B0106Q9A | C | 07/20/2004 | 3 | ATMEL NANTES | | Y | TH1156SHabcDDMQ | 365 |
| 5962-01B0106V9A | C | 07/20/2004 | 3 | ATMEL NANTES | | Y | TH1156SHabcDDSV | 365 |
| 5962-01B0107Q*C | C | 07/20/2004 | 3 | ATMEL NANTES | | Y | TH1242SHabc*MQ | 365 |
| 5962-01B0107V*C | C | 07/20/2004 | 3 | ATMEL NANTES | | Y | TH1242SHabc*SV | 365 |
| 5962R01B0107V*C | C | 07/20/2004 | 3 | ATMEL NANTES | | Y | TH1242SHabc*SR | 365 |
| 5962-01B0107Q9A | C | 07/20/2004 | 3 | ATMEL NANTES | | Y | TH1242SHabcDDMQ | 365 |
| 5962-01B0107V9A | C | 07/20/2004 | 3 | ATMEL NANTES | | Y | TH1242SHabcDDSV | 365 |
| 5962-01B0108Q*C | C | 07/20/2004 | 3 | ATMEL NANTES | | Y | TH1332SHabc*MQ | 365 |
| 5962-01B0108Q9A | C | 07/20/2004 | 3 | ATMEL NANTES | | Y | TH1332SHabcDDMQ | 365 |
| 5962-01B0109Q_C | C | 07/20/2004 | 3 | ATMEL NANTES | | Y | TH1REHabc_MQ | 365 |
| 5962-01B0109V_C | C | 07/20/2004 | 3 | ATMEL NANTES | | Y | TH1REHabc_SV | 365 |
| 5962R01B0109V_C | C | 07/20/2004 | 3 | ATMEL NANTES | | Y | TH1REHabc_SR | 365 |
| 5962-01B0109Q9A | C | 07/20/2004 | 3 | ATMEL NANTES | | Y | TH1REHabcDDMQ | 365 |
| 5962-01B0109V9A | C | 07/20/2004 | 3 | ATMEL NANTES | | Y | TH1REHabcDDSV | 365 |
| 5962-01B0110Q_C | C | 07/20/2004 | 3 | ATMEL NANTES | | Y | TH1REHabc_MQ | 365 |
| 5962-01B0110V_C | C | 07/20/2004 | 3 | ATMEL NANTES | | Y | TH1REHabc_SV | 365 |
| 5962R01B0110V_C | C | 07/20/2004 | 3 | ATMEL NANTES | | Y | TH1REHabc_SR | 365 |
| 5962-01B0110Q9A | C | 07/20/2004 | 3 | ATMEL NANTES | | Y | TH1REHabcDDMQ | 365 |
| 5962-01B0110V9A | C | 07/20/2004 | 3 | ATMEL NANTES | | Y | TH1REHabcDDSV | 365 |
| 5962-01B0111Q_C | C | 07/20/2004 | 3 | ATMEL NANTES | | Y | TH1REHabc_MQ | 365 |
| 5962-01B0111V_C | C | 07/20/2004 | 3 | ATMEL NANTES | | Y | TH1REHabc_SV | 365 |
| 5962R01B0111V_C | C | 07/20/2004 | 3 | ATMEL NANTES | | Y | TH1REHabc_SR | 365 |
| 5962-01B0111Q9A | C | 07/20/2004 | 3 | ATMEL NANTES | | Y | TH1REHabcDDMQ | 365 |
| 5962-01B0111V9A | C | 07/20/2004 | 3 | ATMEL NANTES | | Y | TH1REHabcDDSV | 365 |
| 5962-01B0112Q_C | C | 07/20/2004 | 3 | ATMEL NANTES | | Y | TH1REHabc_MQ | 365 |
| 5962-01B0112Q9A | C | 07/20/2004 | 3 | ATMEL NANTES | | Y | TH1REHabcDDMQ | 365 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-01B0113Q_C | C | 07/20/2004 | 3 | ATMEL NANTES | | Y | TH1SEHabc_MQ | 365 |
| 5962-01B0113V_C | C | 07/20/2004 | 3 | ATMEL NANTES | | Y | TH1SEHabc_SV | 365 |
| 5962R01B0113V_C | C | 07/20/2004 | 3 | ATMEL NANTES | | Y | TH1SEHabc_SR | 365 |
| 5962-01B0113Q9A | C | 07/20/2004 | 3 | ATMEL NANTES | | Y | TH1SEHabcDDMQ | 365 |
| 5962-01B0113V9A | C | 07/20/2004 | 3 | ATMEL NANTES | | Y | TH1SEHabcDDSV | 365 |
| 5962-01B0114Q_C | C | 07/20/2004 | 3 | ATMEL NANTES | | Y | TH1SEHabc_MQ | 365 |
| 5962-01B0114V_C | C | 07/20/2004 | 3 | ATMEL NANTES | | Y | TH1SEHabc_SV | 365 |
| 5962R01B0114V_C | C | 07/20/2004 | 3 | ATMEL NANTES | | Y | TH1SEHabc_SR | 365 |
| 5962-01B0114Q9A | C | 07/20/2004 | 3 | ATMEL NANTES | | Y | TH1SEHabcDDMQ | 365 |
| 5962-01B0114V9A | C | 07/20/2004 | 3 | ATMEL NANTES | | Y | TH1SEHabcDDSV | 365 |
| 5962-01B0115Q_C | C | 07/20/2004 | 3 | ATMEL NANTES | | Y | TH1SEHabc_MQ | 365 |
| 5962-01B0115V_C | C | 07/20/2004 | 3 | ATMEL NANTES | | Y | TH1SEHabc_SV | 365 |
| 5962R01B0115V_C | C | 07/20/2004 | 3 | ATMEL NANTES | | Y | TH1SEHabc_SR | 365 |
| 5962-01B0115Q9A | C | 07/20/2004 | 3 | ATMEL NANTES | | Y | TH1SEHabcDDMQ | 365 |
| 5962-01B0115V9A | C | 07/20/2004 | 3 | ATMEL NANTES | | Y | TH1SEHabcDDSV | 365 |
| 5962-01B0116Q_C | C | 07/20/2004 | 3 | ATMEL NANTES | | Y | TH1SEHabc_MQ | 365 |
| 5962-01B0116Q9A | C | 07/20/2004 | 3 | ATMEL NANTES | | Y | TH1SEHabcDDMQ | 365 |
| 5962-01B0117Q_C | C | 07/20/2004 | 3 | ATMEL NANTES | | Y | TH1099Rabc_MQ | 365 |
| 5962-01B0117Q9A | C | 07/20/2004 | 3 | ATMEL NANTES | | Y | TH1099RabcDDMQ | 365 |
| 5962-01B0118Q_C | C | 07/20/2004 | 3 | ATMEL NANTES | | Y | TH1156Rabc_MQ | 365 |
| 5962-01B0118Q9A | C | 07/20/2004 | 3 | ATMEL NANTES | | Y | TH1156RabcDDMQ | 365 |
| 5962-01B0119Q_C | C | 07/20/2004 | 3 | ATMEL NANTES | | Y | TH1242Rabc_MQ | 365 |
| 5962-01B0119Q9A | C | 07/20/2004 | 3 | ATMEL NANTES | | Y | TH1242RabcDDMQ | 365 |
| 5962-01B0120Q_C | C | 07/20/2004 | 3 | ATMEL NANTES | | Y | TH1332Rabc_MQ | 365 |
| 5962-01B0120Q9A | C | 07/20/2004 | 3 | ATMEL NANTES | | Y | TH1332RabcDDMQ | 365 |
| 5962-01B0121Q_C | C | 07/20/2004 | 3 | ATMEL NANTES | | Y | TH1099Sabc_MQ | 365 |
| 5962-01B0121Q9A | C | 07/20/2004 | 3 | ATMEL NANTES | | Y | TH1099SabcDDMQ | 365 |
| 5962-01B0122Q_C | C | 07/20/2004 | 3 | ATMEL NANTES | | Y | TH1156Sabc_MQ | 365 |
| 5962-01B0122Q9A | C | 07/20/2004 | 3 | ATMEL NANTES | | Y | TH1156SabcDDMQ | 365 |
| 5962-01B0123Q_C | C | 07/20/2004 | 3 | ATMEL NANTES | | Y | TH1242Sabc_MQ | 365 |
| 5962-01B0123Q9A | C | 07/20/2004 | 3 | ATMEL NANTES | | Y | TH1242SabcDDMQ | 365 |
| 5962-01B0124Q_C | C | 07/20/2004 | 3 | ATMEL NANTES | | Y | TH1332Sabc_MQ | 365 |
| 5962-01B0124Q9A | C | 07/20/2004 | 3 | ATMEL NANTES | | Y | TH1332SabcDDMQ | 365 |
| 5962-01B0125Q_C | C | 07/20/2004 | 3 | ATMEL NANTES | | Y | TH1RDabc_MQ | 365 |
| 5962-01B0125Q9A | C | 07/20/2004 | 3 | ATMEL NANTES | | Y | TH1RDabcDDMQ | 365 |
| 5962-01B0126Q_C | C | 07/20/2004 | 3 | ATMEL NANTES | | Y | TH1RDabc_MQ | 365 |
| 5962-01B0126Q9A | C | 07/20/2004 | 3 | ATMEL NANTES | | Y | TH1RDabcDDMQ | 365 |
| 5962-01B0127Q_C | C | 07/20/2004 | 3 | ATMEL NANTES | | Y | TH1RDabc_MQ | 365 |
| 5962-01B0127Q9A | C | 07/20/2004 | 3 | ATMEL NANTES | | Y | TH1RDabcDDMQ | 365 |
| 5962-01B0128Q_C | C | 07/20/2004 | 3 | ATMEL NANTES | | Y | TH1RDabc_MQ | 365 |
| 5962-01B0128Q9A | C | 07/20/2004 | 3 | ATMEL NANTES | | Y | TH1RDabcDDMQ | 365 |
| 5962-01B0129Q_C | C | 07/20/2004 | 3 | ATMEL NANTES | | Y | TH1SDabc_MQ | 365 |
| 5962-01B0129Q9A | C | 07/20/2004 | 3 | ATMEL NANTES | | Y | TH1SDabcDDMQ | 365 |
| 5962-01B0130Q_C | C | 07/20/2004 | 3 | ATMEL NANTES | | Y | TH1SDabc_MQ | 365 |
| 5962-01B0130Q9A | C | 07/20/2004 | 3 | ATMEL NANTES | | Y | TH1SDabcDDMQ | 365 |
| 5962-01B0131Q_C | C | 07/20/2004 | 3 | ATMEL NANTES | | Y | TH1SDabc_MQ | 365 |
| 5962-01B0131Q9A | C | 07/20/2004 | 3 | ATMEL NANTES | | Y | TH1SDabcDDMQ | 365 |
| 5962-01B0132Q_C | C | 07/20/2004 | 3 | ATMEL NANTES | | Y | TH1SDabc_MQ | 365 |
| 5962-01B0132Q9A | C | 07/20/2004 | 3 | ATMEL NANTES | | Y | TH1SDabcDDMQ | 365 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-0250101QXC | B | 09/07/2004 | 1 | ATMEL NANTES | | Y | MMDJ-65609EV-40MQ | 625 |
| 5962-0250101VXC | B | 09/07/2004 | 1 | ATMEL NANTES | | Y | SMDJ-65609EV-40SV | 625 |
| 5962R0250101VXC | B | 09/07/2004 | 1 | ATMEL NANTES | | Y | SMDJ-65609EV-40SR | 625 |
| 5962G0250201QXC | | 10/29/2001 | 1 | BAE SYSTEMS | | Y | LMP2568T3V-Q10X | 669 |
| 5962G0250201VXC | | 10/29/2001 | 1 | BAE SYSTEMS | | Y | LMP2568T3V-V10X | 669 |
| 5962F0250301V9A | | 11/27/2001 | 2 | INTERSIL | | Y | ISL72991RHVX | 781 |
| 5962F0250301QXC | | 11/27/2001 | 2 | INTERSIL | | Y | ISL72991RHQF | 781 |
| 5962F0250301VXC | | 11/27/2001 | 2 | INTERSIL | | Y | ISL72991RHVF | 781 |
| 5962-0250401HXA | | 12/11/2001 | 1 | INTERPOINT | | Y | SLH2805D/HO | 594 |
| 5962-0250401HXC | | 12/11/2001 | 1 | INTERPOINT | | Y | SLH2805D/HO | 594 |
| 5962R0250401HXA | | 12/11/2001 | 1 | INTERPOINT | | Y | SLH2805D/HR | 594 |
| 5962R0250401HXC | | 12/11/2001 | 1 | INTERPOINT | | Y | SLH2805D/HR | 594 |
| 5962R0250401KXA | | 12/11/2001 | 1 | INTERPOINT | | Y | SLH2805D/KR | 594 |
| 5962R0250401KXC | | 12/11/2001 | 1 | INTERPOINT | | Y | SLH2805D/KR | 594 |
| 5962-0250502HXA | A | 11/07/2003 | 1 | MICROPAC | | Y | 52445 | 787 |
| 5962-0250502HXC | A | 11/07/2003 | 1 | MICROPAC | | Y | 52445 | 787 |
| 5962-0250503HXA | A | 11/07/2003 | 1 | MICROPAC | | Y | 52446 | 787 |
| 5962-0250503HXC | A | 11/07/2003 | 1 | MICROPAC | | Y | 52446 | 787 |
| 5962-0250601HXA | | 01/31/2002 | 1 | MICROPAC | | Y | 52447 | 899 |
| 5962-0250601HXC | | 01/31/2002 | 1 | MICROPAC | | Y | 52447 | 899 |
| 5962P0250701QXA | A | 10/17/2003 | 2 | STMICRO | | Y | RHPX16245K02Q | 590 |
| 5962P0250701QXC | A | 10/17/2003 | 2 | STMICRO | | Y | RHPX16245K01Q | 590 |
| 5962P0250701VXA | A | 10/17/2003 | 2 | STMICRO | | Y | RHPX16245K02V | 590 |
| 5962P0250701VXC | A | 10/17/2003 | 2 | STMICRO | | Y | RHPX16245K01V | 590 |
| 5962P0250801QXA | A | 10/17/2003 | 2 | STMICRO | | Y | RHPX162245K02Q | 590 |
| 5962P0250801QXC | A | 10/17/2003 | 2 | STMICRO | | Y | RHPX162245K01Q | 590 |
| 5962P0250801VXA | A | 10/17/2003 | 2 | STMICRO | | Y | RHPX162245K02V | 590 |
| 5962P0250801VXC | A | 10/17/2003 | 2 | STMICRO | | Y | RHPX162245K01V | 590 |
| 5962R0250801QXA | A | 10/17/2003 | 2 | STMICRO | | Y | RHRXH162245K02Q | 590 |
| 5962R0250801QXC | A | 10/17/2003 | 2 | STMICRO | | Y | RHRXH162245K01Q | 590 |
| 5962R0250801VXA | A | 10/17/2003 | 2 | STMICRO | | Y | RHRXH162245K02V | 590 |
| 5962R0250801VXC | A | 10/17/2003 | 2 | STMICRO | | Y | RHRXH162245K01V | 590 |
| 5962-0251001HXA | B | 08/24/2004 | 1 | INTERPOINT | | Y | MHF+283R3S/883 | 594 |
| 5962-0251001HXC | B | 08/24/2004 | 1 | INTERPOINT | | Y | MHF+283R3S/883 | 594 |
| 5962-0251001HZA | B | 08/24/2004 | 1 | INTERPOINT | | Y | MHF+283R3SF/883 | 594 |
| 5962-0251001HZC | B | 08/24/2004 | 1 | INTERPOINT | | Y | MHF+283R3SF/883 | 594 |
| 5962-0251002HXA | B | 08/24/2004 | 1 | INTERPOINT | | Y | SMHF283R3S/HO | 594 |
| 5962-0251002HXC | B | 08/24/2004 | 1 | INTERPOINT | | Y | SMHF283R3S/HO | 594 |
| 5962L0251002HXA | B | 08/24/2004 | 1 | INTERPOINT | | Y | SMHF283R3S/HL | 594 |
| 5962L0251002HXC | B | 08/24/2004 | 1 | INTERPOINT | | Y | SMHF283R3S/HL | 594 |
| 5962L0251002KXA | B | 08/24/2004 | 1 | INTERPOINT | | Y | SMHF283R3S/KL | 594 |
| 5962L0251002KXC | B | 08/24/2004 | 1 | INTERPOINT | | Y | SMHF283R3S/KL | 594 |
| 5962R0251002HXA | B | 08/24/2004 | 1 | INTERPOINT | | Y | SMHF283R3S/HR | 594 |
| 5962R0251002HXC | B | 08/24/2004 | 1 | INTERPOINT | | Y | SMHF283R3S/HR | 594 |
| 5962R0251002KXA | B | 08/24/2004 | 1 | INTERPOINT | | Y | SMHF283R3S/KR | 594 |
| 5962R0251002KXC | B | 08/24/2004 | 1 | INTERPOINT | | Y | SMHF283R3S/KR | 594 |
| 5962-0251002HZA | B | 08/24/2004 | 1 | INTERPOINT | | Y | SMHF283R3SF/HO | 594 |
| 5962-0251002HZC | B | 08/24/2004 | 1 | INTERPOINT | | Y | SMHF283R3SF/HO | 594 |
| 5962L0251002HZA | B | 08/24/2004 | 1 | INTERPOINT | | Y | SMHF283R3SF/HL | 594 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962L0251002HZC | B | 08/24/2004 | 1 | INTERPOINT | | Y | SMHF283R3SF/HL | 594 |
| 5962L0251002KZA | B | 08/24/2004 | 1 | INTERPOINT | | Y | SMHF283R3SF/KL | 594 |
| 5962L0251002KZC | B | 08/24/2004 | 1 | INTERPOINT | | Y | SMHF283R3SF/KL | 594 |
| 5962R0251002HZA | B | 08/24/2004 | 1 | INTERPOINT | | Y | SMHF283R3SF/HR | 594 |
| 5962R0251002HZC | B | 08/24/2004 | 1 | INTERPOINT | | Y | SMHF283R3SF/HR | 594 |
| 5962R0251002KZA | B | 08/24/2004 | 1 | INTERPOINT | | Y | SMHF283R3SF/KR | 594 |
| 5962R0251002KZC | B | 08/24/2004 | 1 | INTERPOINT | | Y | SMHF283R3SF/KR | 594 |
| 5962F0251101V9A | A | 06/17/2003 | 2 | INTERSIL | | Y | IS0-1825ASRH-Q | 787 |
| 5962F0251101QEC | A | 06/17/2003 | 2 | INTERSIL | | Y | IS1-1825ASRH-8 | 787 |
| 5962F0251101VEC | A | 06/17/2003 | 2 | INTERSIL | | Y | IS1-1825ASRH-Q | 787 |
| 5962F0251101QXC | A | 06/17/2003 | 2 | INTERSIL | | Y | IS9-1825ASRH-8 | 787 |
| 5962F0251101VXC | A | 06/17/2003 | 2 | INTERSIL | | Y | IS9-1825ASRH-Q | 787 |
| 5962-0251201QXA | | 05/07/2003 | 3 | TI | | Y | SMJ320LC549HFGW60 | 432 |
| 5962-0251301HXA | | 04/10/2002 | 1 | INTERPOINT | | Y | MSA285R2S/883 | 594 |
| 5962-0251701NXA | A | 04/06/2004 | 1 | VERTICAL | | Y | SD128MX84 | 629 |
| 5962-0251701NXB | A | 04/06/2004 | 1 | VERTICAL | | Y | SD128MX84 | 629 |
| 5962-0251702NXA | A | 04/06/2004 | 1 | VERTICAL | | Y | SD128MX88 | 629 |
| 5962-0251702NXB | A | 04/06/2004 | 1 | VERTICAL | | Y | SD128MX88 | 629 |
| 5962-0251802NXA | | 02/07/2003 | 1 | VERTICAL | | Y | SD256MX88 | 629 |
| 5962-0251802NXB | | 02/07/2003 | 1 | VERTICAL | | Y | SD256MX88 | 629 |
| 5962-0252201EXA | A | 04/21/2004 | 1 | NATEL | | Y | SMC51676/2 | 899 |
| 5962F0252301Q9A | | 09/26/2002 | 2 | UTMC | | Y | UT80CRH196KDS-QCD | 420 |
| 5962F0252301V9A | | 09/26/2002 | 2 | UTMC | | Y | UT80CRH196KDS-VCD | 420 |
| 5962-0252301QXA | | 09/26/2002 | 2 | UTMC | | Y | UT80CRH196KDS-WCA | 420 |
| 5962-0252301QXC | | 09/26/2002 | 2 | UTMC | | Y | UT80CRH196KDS-WC | 420 |
| 5962F0252301QXA | | 09/26/2002 | 2 | UTMC | | Y | UT80CRH196KDS-WCA | 420 |
| 5962F0252301QXC | | 09/26/2002 | 2 | UTMC | | Y | UT80CRH196KDS-WC | 420 |
| 5962F0252301VXA | | 09/26/2002 | 2 | UTMC | | Y | UT80CRH196KDS-WCA | 420 |
| 5962F0252301VXC | | 09/26/2002 | 2 | UTMC | | Y | UT80CRH196KDS-WC | 420 |
| 5962F0252302Q9A | | 09/26/2002 | 2 | UTMC | | Y | UT80CRH196KDS-QW | 420 |
| 5962F0252302V9A | | 09/26/2002 | 2 | UTMC | | Y | UT80CRH196KDS-VWD | 420 |
| 5962-0252302QXA | | 09/26/2002 | 2 | UTMC | | Y | UT80CRH196KDS-WW | 420 |
| 5962-0252302QXC | | 09/26/2002 | 2 | UTMC | | Y | UT80CRH196KDS-WW | 420 |
| 5962F0252302QXA | | 09/26/2002 | 2 | UTMC | | Y | UT80CRH196KDS-WW | 420 |
| 5962F0252302QXC | | 09/26/2002 | 2 | UTMC | | Y | UT80CRH196KDS-WW | 420 |
| 5962F0252302VXA | | 09/26/2002 | 2 | UTMC | | Y | UT80CRH196KDS-WW | 420 |
| 5962F0252302VXC | | 09/26/2002 | 2 | UTMC | | Y | UT80CRH196KDS-WW | 420 |
| 5962F0252401VXA | A | 02/19/2003 | 3 | STMICRO | | Y | RHFL4913KPA-02V | 780 |
| 5962F0252401VXC | A | 02/19/2003 | 3 | STMICRO | | Y | RHFL4913KPA-01V | 780 |
| 5962F0252402VYA | A | 02/19/2003 | 3 | STMICRO | | Y | RHFL4913SOA-04V | 780 |
| 5962F0252402VYC | A | 02/19/2003 | 3 | STMICRO | | Y | RHFL4913SOA-03V | 780 |
| 5962F0252402VZA | A | 02/19/2003 | 3 | STMICRO | | Y | RHFL4913KA-06V | 780 |
| 5962F0252402VZC | A | 02/19/2003 | 3 | STMICRO | | Y | RHFL4913KA-05V | 780 |
| 5962-0252501EXA | A | 11/07/2003 | 1 | NATEL | | Y | SMC51677/2 | 899 |
| 5962-0252501EXA | A | 11/07/2003 | 1 | SATCON | | Y | 1500 | 899 |
| 5962F0253401VXA | A | 02/19/2003 | 3 | STMICRO | | Y | RHFL4913KP25-02V | 782 |
| 5962F0253401VXC | A | 02/19/2003 | 3 | STMICRO | | Y | RHFL4913KP25-01V | 782 |
| 5962F0253402VYA | A | 02/19/2003 | 3 | STMICRO | | Y | RHFL4913S25-04V | 782 |
| 5962F0253402VYC | A | 02/19/2003 | 3 | STMICRO | | Y | RHFL4913S25-03V | 782 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962F0253402VZA | A | 02/19/2003 | 3 | STMICRO | | Y | RHFL4913ESY2506V | 782 |
| 5962F0253402VZC | A | 02/19/2003 | 3 | STMICRO | | Y | RHFL4913ESY2505V | 782 |
| 5962F0253501VXA | A | 02/19/2003 | 3 | STMICRO | | Y | RHFL4913KP33-02V | 782 |
| 5962F0253501VXC | A | 02/19/2003 | 3 | STMICRO | | Y | RHFL4913KP33-01V | 782 |
| 5962F0253502VYA | A | 02/19/2003 | 3 | STMICRO | | Y | RHFL4913S33-04V | 782 |
| 5962F0253502VYC | A | 02/19/2003 | 3 | STMICRO | | Y | RHFL4913S33-03V | 782 |
| 5962F0253502VZA | A | 02/19/2003 | 3 | STMICRO | | Y | RHFL4913ESY3306V | 782 |
| 5962F0253502VZC | A | 02/19/2003 | 3 | STMICRO | | Y | RHFL4913ESY3305V | 782 |
| 5962F0253601VXA | A | 02/19/2003 | 3 | STMICRO | | Y | RHFL4913KP50-02V | 782 |
| 5962F0253601VXC | A | 02/19/2003 | 3 | STMICRO | | Y | RHFL4913KP50-01V | 782 |
| 5962F0253602VYA | A | 02/19/2003 | 3 | STMICRO | | Y | RHFL4913S50-04V | 782 |
| 5962F0253602VYC | A | 02/19/2003 | 3 | STMICRO | | Y | RHFL4913S50-03V | 782 |
| 5962F0253602VZA | A | 02/19/2003 | 3 | STMICRO | | Y | RHFL4913ESY5006V | 782 |
| 5962F0253602VZC | A | 02/19/2003 | 3 | STMICRO | | Y | RHFL4913ESY5005V | 782 |
| 5962-0253801VXA | A | 05/28/2003 | 1 | ANALOG (5) | | Y | AD9042SD/QMLV | 592 |
| 5962R0253801VXA | A | 05/28/2003 | 1 | ANALOG (5) | | Y | AD9042SD/QMLR | 592 |
| 5962-0253801VZA | A | 05/28/2003 | 1 | ANALOG (5) | | Y | AD9042SF/QMLV | 592 |
| 5962R0253801VZA | A | 05/28/2003 | 1 | ANALOG (5) | | Y | AD9042SF/QMLR | 592 |
| 5962-0254001EXA | C | 07/15/2004 | 1 | NATEL | | Y | SMC51675/2 | 899 |
| 5962F0254201V9A | | 08/30/2002 | 2 | INTERSIL | | Y | ISL7124SRHVX | 713 |
| 5962F0254201QXC | | 08/30/2002 | 2 | INTERSIL | | Y | ISL7124SRHQF | 713 |
| 5962F0254201VXC | | 08/30/2002 | 2 | INTERSIL | | Y | ISL7124SRHVF | 713 |
| 5962H0254301QXA | | 03/13/2003 | 1 | UTMC | | Y | UT54ACS162245SUCA | 599 |
| 5962H0254301QXC | | 03/13/2003 | 1 | UTMC | | Y | UT54ACS162245SUCC | 599 |
| 5962H0254301VXA | | 03/13/2003 | 1 | UTMC | | Y | UT54ACS162245SUCA | 599 |
| 5962H0254301VXC | | 03/13/2003 | 1 | UTMC | | Y | UT54ACS162245SUCC | 599 |
| 5962-0254401QPA | A | 06/01/2004 | 2 | NATIONAL | | Y | LMH6624J-QML | 739 |
| 5962-0254401VPA | A | 06/01/2004 | 2 | NATIONAL | | Y | LMH6624J-QMLV | 739 |
| 5962-0254401QZA | A | 06/01/2004 | 2 | NATIONAL | | Y | LMH6624WG-QML | 739 |
| 5962-0254401VZA | A | 06/01/2004 | 2 | NATIONAL | | Y | LMH6624WG-QMLV | 739 |
| 5962-0254501MPA | | 05/08/2003 | 3 | NATIONAL | | Y | LMH6628J-QML | 710 |
| 5962-0254501VPA | | 05/08/2003 | 3 | NATIONAL | | Y | LMH6628J-QMLV | 710 |
| 5962F0254501MPA | | 05/08/2003 | 3 | NATIONAL | | Y | LMH6628JFQML | 710 |
| 5962F0254501VPA | | 05/08/2003 | 3 | NATIONAL | | Y | LMH6628JFQMLV | 710 |
| 5962-0254501MZA | | 05/08/2003 | 3 | NATIONAL | | Y | LMH6628WG-QML | 710 |
| 5962-0254501VZA | | 05/08/2003 | 3 | NATIONAL | | Y | LMH6628WG-QMLV | 710 |
| 5962F0254501MZA | | 05/08/2003 | 3 | NATIONAL | | Y | LMH6628WGFQML | 710 |
| 5962F0254501VZA | | 05/08/2003 | 3 | NATIONAL | | Y | LMH6628WGFQMLV | 710 |
| 5962-0254601QPA | | 03/04/2004 | 1 | NATIONAL | | Y | LMH6702J-QML | 719 |
| 5962-0254601QZA | | 03/04/2004 | 1 | NATIONAL | | Y | LMH6702WG-QML | 719 |
| 5962-0254701QPA | | 05/08/2003 | 2 | NATIONAL | | Y | LMH6715J-QML | 710 |
| 5962-0254701VPA | | 05/08/2003 | 2 | NATIONAL | | Y | LMH6715J-QMLV | 710 |
| 5962F0254701QPA | | 05/08/2003 | 2 | NATIONAL | | Y | LMH6715JFQML | 710 |
| 5962F0254701VPA | | 05/08/2003 | 2 | NATIONAL | | Y | LMH6715JFQMLV | 710 |
| 5962-0254801HUA | | 11/06/2002 | 1 | ADV. ANALOG | | Y | AFL1203R3SW/CH | 594 |
| 5962-0254801HUC | | 11/06/2002 | 1 | ADV. ANALOG | | Y | AFL1203R3SW/CH | 594 |
| 5962-0254801HXA | | 11/06/2002 | 1 | ADV. ANALOG | | Y | AFL1203R3SX/CH | 594 |
| 5962-0254801HXC | | 11/06/2002 | 1 | ADV. ANALOG | | Y | AFL1203R3SX/CH | 594 |
| 5962-0254801HYA | | 11/06/2002 | 1 | ADV. ANALOG | | Y | AFL1203R3SY/CH | 594 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-0254801HYC | | 11/06/2002 | 1 | ADV. ANALOG | | Y | AFL1203R3SY/CH | 594 |
| 5962-0254801HZA | | 11/06/2002 | 1 | ADV. ANALOG | | Y | AFL1203R3SZ/CH | 594 |
| 5962-0254801HZC | | 11/06/2002 | 1 | ADV. ANALOG | | Y | AFL1203R3SZ/CH | 594 |
| 5962-0254901HUA | | 11/06/2002 | 1 | ADV. ANALOG | | Y | AFL12008SW/CH | 594 |
| 5962-0254901HUC | | 11/06/2002 | 1 | ADV. ANALOG | | Y | AFL12008SW/CH | 594 |
| 5962-0254901HXA | | 11/06/2002 | 1 | ADV. ANALOG | | Y | AFL12008SX/CH | 594 |
| 5962-0254901HXC | | 11/06/2002 | 1 | ADV. ANALOG | | Y | AFL12008SX/CH | 594 |
| 5962-0254901HYA | | 11/06/2002 | 1 | ADV. ANALOG | | Y | AFL12008SY/CH | 594 |
| 5962-0254901HYC | | 11/06/2002 | 1 | ADV. ANALOG | | Y | AFL12008SY/CH | 594 |
| 5962-0254901HZA | | 11/06/2002 | 1 | ADV. ANALOG | | Y | AFL12008SZ/CH | 594 |
| 5962-0254901HZC | | 11/06/2002 | 1 | ADV. ANALOG | | Y | AFL12008SZ/CH | 594 |
| 5962-0255001HUA | | 11/06/2002 | 1 | ADV. ANALOG | | Y | AFL12009SW/CH | 594 |
| 5962-0255001HUC | | 11/06/2002 | 1 | ADV. ANALOG | | Y | AFL12009SW/CH | 594 |
| 5962-0255001HXA | | 11/06/2002 | 1 | ADV. ANALOG | | Y | AFL12009SX/CH | 594 |
| 5962-0255001HXC | | 11/06/2002 | 1 | ADV. ANALOG | | Y | AFL12009SX/CH | 594 |
| 5962-0255001HYA | | 11/06/2002 | 1 | ADV. ANALOG | | Y | AFL12009SY/CH | 594 |
| 5962-0255001HYC | | 11/06/2002 | 1 | ADV. ANALOG | | Y | AFL12009SY/CH | 594 |
| 5962-0255001HZA | | 11/06/2002 | 1 | ADV. ANALOG | | Y | AFL12009SZ/CH | 594 |
| 5962-0255001HZC | | 11/06/2002 | 1 | ADV. ANALOG | | Y | AFL12009SZ/CH | 594 |
| 5962-0255101HUA | | 11/06/2002 | 1 | ADV. ANALOG | | Y | AFL12012SW/CH | 594 |
| 5962-0255101HUC | | 11/06/2002 | 1 | ADV. ANALOG | | Y | AFL12012SW/CH | 594 |
| 5962-0255101HXA | | 11/06/2002 | 1 | ADV. ANALOG | | Y | AFL12012SX/CH | 594 |
| 5962-0255101HXC | | 11/06/2002 | 1 | ADV. ANALOG | | Y | AFL12012SX/CH | 594 |
| 5962-0255101HYA | | 11/06/2002 | 1 | ADV. ANALOG | | Y | AFL12012SY/CH | 594 |
| 5962-0255101HYC | | 11/06/2002 | 1 | ADV. ANALOG | | Y | AFL12012SY/CH | 594 |
| 5962-0255101HZA | | 11/06/2002 | 1 | ADV. ANALOG | | Y | AFL12012SZ/CH | 594 |
| 5962-0255101HZC | | 11/06/2002 | 1 | ADV. ANALOG | | Y | AFL12012SZ/CH | 594 |
| 5962-0255201HUA | | 11/06/2002 | 1 | ADV. ANALOG | | Y | AFL12015SW/CH | 594 |
| 5962-0255201HUC | | 11/06/2002 | 1 | ADV. ANALOG | | Y | AFL12015SW/CH | 594 |
| 5962-0255201HXA | | 11/06/2002 | 1 | ADV. ANALOG | | Y | AFL12015SX/CH | 594 |
| 5962-0255201HXC | | 11/06/2002 | 1 | ADV. ANALOG | | Y | AFL12015SX/CH | 594 |
| 5962-0255201HYA | | 11/06/2002 | 1 | ADV. ANALOG | | Y | AFL12015SY/CH | 594 |
| 5962-0255201HYC | | 11/06/2002 | 1 | ADV. ANALOG | | Y | AFL12015SY/CH | 594 |
| 5962-0255201HZA | | 11/06/2002 | 1 | ADV. ANALOG | | Y | AFL12015SZ/CH | 594 |
| 5962-0255201HZC | | 11/06/2002 | 1 | ADV. ANALOG | | Y | AFL12015SZ/CH | 594 |
| 5962-0255301HUA | | 11/06/2002 | 1 | ADV. ANALOG | | Y | AFL12028SW/CH | 594 |
| 5962-0255301HUC | | 11/06/2002 | 1 | ADV. ANALOG | | Y | AFL12028SW/CH | 594 |
| 5962-0255301HXA | | 11/06/2002 | 1 | ADV. ANALOG | | Y | AFL12028SX/CH | 594 |
| 5962-0255301HXC | | 11/06/2002 | 1 | ADV. ANALOG | | Y | AFL12028SX/CH | 594 |
| 5962-0255301HYA | | 11/06/2002 | 1 | ADV. ANALOG | | Y | AFL12028SY/CH | 594 |
| 5962-0255301HYC | | 11/06/2002 | 1 | ADV. ANALOG | | Y | AFL12028SY/CH | 594 |
| 5962-0255301HZA | | 11/06/2002 | 1 | ADV. ANALOG | | Y | AFL12028SZ/CH | 594 |
| 5962-0255301HZC | | 11/06/2002 | 1 | ADV. ANALOG | | Y | AFL12028SZ/CH | 594 |
| 5962-0255401HUA | | 11/06/2002 | 1 | ADV. ANALOG | | Y | AFL12005DW/CH | 594 |
| 5962-0255401HUC | | 11/06/2002 | 1 | ADV. ANALOG | | Y | AFL12005DW/CH | 594 |
| 5962-0255401HXA | | 11/06/2002 | 1 | ADV. ANALOG | | Y | AFL12005DX/CH | 594 |
| 5962-0255401HXC | | 11/06/2002 | 1 | ADV. ANALOG | | Y | AFL12005DX/CH | 594 |
| 5962-0255401HYA | | 11/06/2002 | 1 | ADV. ANALOG | | Y | AFL12005DY/CH | 594 |
| 5962-0255401HYC | | 11/06/2002 | 1 | ADV. ANALOG | | Y | AFL12005DY/CH | 594 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-0255401HZA | | 11/06/2002 | 1 | ADV. ANALOG | | Y | AFL12005DZ/CH | 594 |
| 5962-0255401HZC | | 11/06/2002 | 1 | ADV. ANALOG | | Y | AFL12005DZ/CH | 594 |
| 5962-0255501HUA | | 11/06/2002 | 1 | ADV. ANALOG | | Y | AFL12015DW/CH | 594 |
| 5962-0255501HUC | | 11/06/2002 | 1 | ADV. ANALOG | | Y | AFL12015DW/CH | 594 |
| 5962-0255501HXA | | 11/06/2002 | 1 | ADV. ANALOG | | Y | AFL12015DX/CH | 594 |
| 5962-0255501HXC | | 11/06/2002 | 1 | ADV. ANALOG | | Y | AFL12015DX/CH | 594 |
| 5962-0255501HYA | | 11/06/2002 | 1 | ADV. ANALOG | | Y | AFL12015DY/CH | 594 |
| 5962-0255501HYC | | 11/06/2002 | 1 | ADV. ANALOG | | Y | AFL12015DY/CH | 594 |
| 5962-0255501HZA | | 11/06/2002 | 1 | ADV. ANALOG | | Y | AFL12015DZ/CH | 594 |
| 5962-0255501HZC | | 11/06/2002 | 1 | ADV. ANALOG | | Y | AFL12015DZ/CH | 594 |
| 5962-0255601HUA | | 11/06/2002 | 1 | ADV. ANALOG | | Y | AFL503R3SW/CH | 594 |
| 5962-0255601HUC | | 11/06/2002 | 1 | ADV. ANALOG | | Y | AFL503R3SW/CH | 594 |
| 5962-0255601HXA | | 11/06/2002 | 1 | ADV. ANALOG | | Y | AFL503R3SX/CH | 594 |
| 5962-0255601HXC | | 11/06/2002 | 1 | ADV. ANALOG | | Y | AFL503R3SX/CH | 594 |
| 5962-0255601HYA | | 11/06/2002 | 1 | ADV. ANALOG | | Y | AFL503R3SY/CH | 594 |
| 5962-0255601HYC | | 11/06/2002 | 1 | ADV. ANALOG | | Y | AFL503R3SY/CH | 594 |
| 5962-0255601HZA | | 11/06/2002 | 1 | ADV. ANALOG | | Y | AFL503R3SZ/CH | 594 |
| 5962-0255601HZC | | 11/06/2002 | 1 | ADV. ANALOG | | Y | AFL503R3SZ/CH | 594 |
| 5962-0255701HUA | | 11/21/2002 | 1 | ADV. ANALOG | | Y | AFL5005SW/CH | 594 |
| 5962-0255701HUC | | 11/21/2002 | 1 | ADV. ANALOG | | Y | AFL5005SW/CH | 594 |
| 5962-0255701HXA | | 11/21/2002 | 1 | ADV. ANALOG | | Y | AFL5005SX/CH | 594 |
| 5962-0255701HXC | | 11/21/2002 | 1 | ADV. ANALOG | | Y | AFL5005SX/CH | 594 |
| 5962-0255701HYA | | 11/21/2002 | 1 | ADV. ANALOG | | Y | AFL5005SY/CH | 594 |
| 5962-0255701HYC | | 11/21/2002 | 1 | ADV. ANALOG | | Y | AFL5005SY/CH | 594 |
| 5962-0255701HZA | | 11/21/2002 | 1 | ADV. ANALOG | | Y | AFL5005SZ/CH | 594 |
| 5962-0255701HZC | | 11/21/2002 | 1 | ADV. ANALOG | | Y | AFL5005SZ/CH | 594 |
| 5962-0255801HUA | | 11/21/2002 | 1 | ADV. ANALOG | | Y | AFL5008SW/CH | 594 |
| 5962-0255801HUC | | 11/21/2002 | 1 | ADV. ANALOG | | Y | AFL5008SW/CH | 594 |
| 5962-0255801HXA | | 11/21/2002 | 1 | ADV. ANALOG | | Y | AFL5008SX/CH | 594 |
| 5962-0255801HXC | | 11/21/2002 | 1 | ADV. ANALOG | | Y | AFL5008SX/CH | 594 |
| 5962-0255801HYA | | 11/21/2002 | 1 | ADV. ANALOG | | Y | AFL5008SY/CH | 594 |
| 5962-0255801HYC | | 11/21/2002 | 1 | ADV. ANALOG | | Y | AFL5008SY/CH | 594 |
| 5962-0255801HZA | | 11/21/2002 | 1 | ADV. ANALOG | | Y | AFL5008SZ/CH | 594 |
| 5962-0255801HZC | | 11/21/2002 | 1 | ADV. ANALOG | | Y | AFL5008SZ/CH | 594 |
| 5962-0255901HUA | | 11/21/2002 | 1 | ADV. ANALOG | | Y | AFL5009SW/CH | 594 |
| 5962-0255901HUC | | 11/21/2002 | 1 | ADV. ANALOG | | Y | AFL5009SW/CH | 594 |
| 5962-0255901HXA | | 11/21/2002 | 1 | ADV. ANALOG | | Y | AFL5009SX/CH | 594 |
| 5962-0255901HXC | | 11/21/2002 | 1 | ADV. ANALOG | | Y | AFL5009SX/CH | 594 |
| 5962-0255901HYA | | 11/21/2002 | 1 | ADV. ANALOG | | Y | AFL5009SY/CH | 594 |
| 5962-0255901HYC | | 11/21/2002 | 1 | ADV. ANALOG | | Y | AFL5009SY/CH | 594 |
| 5962-0255901HZA | | 11/21/2002 | 1 | ADV. ANALOG | | Y | AFL5009SZ/CH | 594 |
| 5962-0255901HZC | | 11/21/2002 | 1 | ADV. ANALOG | | Y | AFL5009SZ/CH | 594 |
| 5962-0256001HUA | | 11/21/2002 | 1 | ADV. ANALOG | | Y | AFL5012SW/CH | 594 |
| 5962-0256001HUC | | 11/21/2002 | 1 | ADV. ANALOG | | Y | AFL5012SW/CH | 594 |
| 5962-0256001HXA | | 11/21/2002 | 1 | ADV. ANALOG | | Y | AFL5012SX/CH | 594 |
| 5962-0256001HXC | | 11/21/2002 | 1 | ADV. ANALOG | | Y | AFL5012SX/CH | 594 |
| 5962-0256001HYA | | 11/21/2002 | 1 | ADV. ANALOG | | Y | AFL5012SY/CH | 594 |
| 5962-0256001HYC | | 11/21/2002 | 1 | ADV. ANALOG | | Y | AFL5012SY/CH | 594 |
| 5962-0256001HZA | | 11/21/2002 | 1 | ADV. ANALOG | | Y | AFL5012SZ/CH | 594 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-0256001HZC | | 11/21/2002 | 1 | ADV. ANALOG | | Y | AFL5012SZ/CH | 594 |
| 5962-0256101HUA | | 11/21/2002 | 1 | ADV. ANALOG | | Y | AFL5015SW/CH | 594 |
| 5962-0256101HUC | | 11/21/2002 | 1 | ADV. ANALOG | | Y | AFL5015SW/CH | 594 |
| 5962-0256101HXA | | 11/21/2002 | 1 | ADV. ANALOG | | Y | AFL5015SX/CH | 594 |
| 5962-0256101HXC | | 11/21/2002 | 1 | ADV. ANALOG | | Y | AFL5015SX/CH | 594 |
| 5962-0256101HYA | | 11/21/2002 | 1 | ADV. ANALOG | | Y | AFL5015SY/CH | 594 |
| 5962-0256101HYC | | 11/21/2002 | 1 | ADV. ANALOG | | Y | AFL5015SY/CH | 594 |
| 5962-0256101HZA | | 11/21/2002 | 1 | ADV. ANALOG | | Y | AFL5015SZ/CH | 594 |
| 5962-0256101HZC | | 11/21/2002 | 1 | ADV. ANALOG | | Y | AFL5015SZ/CH | 594 |
| 5962-0256201HUA | | 11/21/2002 | 1 | ADV. ANALOG | | Y | AFL5028SW/CH | 594 |
| 5962-0256201HUC | | 11/21/2002 | 1 | ADV. ANALOG | | Y | AFL5028SW/CH | 594 |
| 5962-0256201HXA | | 11/21/2002 | 1 | ADV. ANALOG | | Y | AFL5028SX/CH | 594 |
| 5962-0256201HXC | | 11/21/2002 | 1 | ADV. ANALOG | | Y | AFL5028SX/CH | 594 |
| 5962-0256201HYA | | 11/21/2002 | 1 | ADV. ANALOG | | Y | AFL5028SY/CH | 594 |
| 5962-0256201HYC | | 11/21/2002 | 1 | ADV. ANALOG | | Y | AFL5028SY/CH | 594 |
| 5962-0256201HZA | | 11/21/2002 | 1 | ADV. ANALOG | | Y | AFL5028SZ/CH | 594 |
| 5962-0256201HZC | | 11/21/2002 | 1 | ADV. ANALOG | | Y | AFL5028SZ/CH | 594 |
| 5962-0256301HUA | | 11/21/2002 | 1 | ADV. ANALOG | | Y | AFL5005DW/CH | 594 |
| 5962-0256301HUC | | 11/21/2002 | 1 | ADV. ANALOG | | Y | AFL5005DW/CH | 594 |
| 5962-0256301HXA | | 11/21/2002 | 1 | ADV. ANALOG | | Y | AFL5005DX/CH | 594 |
| 5962-0256301HXC | | 11/21/2002 | 1 | ADV. ANALOG | | Y | AFL5005DX/CH | 594 |
| 5962-0256301HYA | | 11/21/2002 | 1 | ADV. ANALOG | | Y | AFL5005DY/CH | 594 |
| 5962-0256301HYC | | 11/21/2002 | 1 | ADV. ANALOG | | Y | AFL5005DY/CH | 594 |
| 5962-0256301HZA | | 11/21/2002 | 1 | ADV. ANALOG | | Y | AFL5005DZ/CH | 594 |
| 5962-0256301HZC | | 11/21/2002 | 1 | ADV. ANALOG | | Y | AFL5005DZ/CH | 594 |
| 5962-0256401HUA | | 11/21/2002 | 1 | ADV. ANALOG | | Y | AFL5012DW/CH | 594 |
| 5962-0256401HUC | | 11/21/2002 | 1 | ADV. ANALOG | | Y | AFL5012DW/CH | 594 |
| 5962-0256401HXA | | 11/21/2002 | 1 | ADV. ANALOG | | Y | AFL5012DX/CH | 594 |
| 5962-0256401HXC | | 11/21/2002 | 1 | ADV. ANALOG | | Y | AFL5012DX/CH | 594 |
| 5962-0256401HYA | | 11/21/2002 | 1 | ADV. ANALOG | | Y | AFL5012DY/CH | 594 |
| 5962-0256401HYC | | 11/21/2002 | 1 | ADV. ANALOG | | Y | AFL5012DY/CH | 594 |
| 5962-0256401HZA | | 11/21/2002 | 1 | ADV. ANALOG | | Y | AFL5012DZ/CH | 594 |
| 5962-0256401HZC | | 11/21/2002 | 1 | ADV. ANALOG | | Y | AFL5012DZ/CH | 594 |
| 5962-0256501HUA | | 11/21/2002 | 1 | ADV. ANALOG | | Y | AFL5015DW/CH | 594 |
| 5962-0256501HUC | | 11/21/2002 | 1 | ADV. ANALOG | | Y | AFL5015DW/CH | 594 |
| 5962-0256501HXA | | 11/21/2002 | 1 | ADV. ANALOG | | Y | AFL5015DX/CH | 594 |
| 5962-0256501HXC | | 11/21/2002 | 1 | ADV. ANALOG | | Y | AFL5015DX/CH | 594 |
| 5962-0256501HYA | | 11/21/2002 | 1 | ADV. ANALOG | | Y | AFL5015DY/CH | 594 |
| 5962-0256501HYC | | 11/21/2002 | 1 | ADV. ANALOG | | Y | AFL5015DY/CH | 594 |
| 5962-0256501HZA | | 11/21/2002 | 1 | ADV. ANALOG | | Y | AFL5015DZ/CH | 594 |
| 5962-0256501HZC | | 11/21/2002 | 1 | ADV. ANALOG | | Y | AFL5015DZ/CH | 594 |
| 5962-02A0101QXC | | 01/23/2002 | 1 | AMI | | Y | 9863-027 | 365 |
| 5962-02A0201QXC | | 04/04/2002 | 2 | ATMEL NANTES | | Y | T7906EKTMQ | 365 |
| 5962-02A0201VXC | | 04/04/2002 | 2 | ATMEL NANTES | | Y | T7906EKTSV | 365 |
| 5962-02A0301QXA | | 12/06/2001 | 3 | AMI | | Y | 06583-011 | 365 |
| 5962-02A0401QXA | | 12/06/2001 | 3 | AMI | | Y | 06583-014 | 365 |
| 5962-02A0501QXA | | 12/06/2001 | 3 | AMI | | Y | 08785-001 | 365 |
| 5962-02A0601QXC | | 01/07/2002 | 3 | AMI | | Y | 06817-539 | 365 |
| 5962-02A0701QXC | | 06/24/2002 | 2 | ATMEL NANTES | | Y | TSS902EAMQ | 365 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-02A0701VXC | | 06/24/2002 | 2 | ATMEL NANTES | | Y | TSS902EASV | 365 |
| 5962-02A0901QXC | | 06/02/2003 | 2 | ATMEL NANTES | | Y | T7905EFWMQ | 365 |
| 5962-02A0901VXC | | 06/02/2003 | 2 | ATMEL NANTES | | Y | T7905EFWMV | 365 |
| 5962-02A1001QXC | | 08/06/2002 | 2 | AMI | | Y | 15022-517 | 365 |
| 5962-02B0101QXC | | 08/27/2002 | 3 | ATMEL NANTES | | Y | MG2044E | 365 |
| 5962-02B0101VXC | | 08/27/2002 | 3 | ATMEL NANTES | | Y | MG2044E | 365 |
| 5962F0320101VXA | A | 02/19/2003 | 3 | STMICRO | | Y | RHFL4913KP30-02V | 782 |
| 5962F0320101VXC | A | 02/19/2003 | 3 | STMICRO | | Y | RHFL4913KP30-01V | 782 |
| 5962F0320102VYA | A | 02/19/2003 | 3 | STMICRO | | Y | RHFL4913S30-04V | 782 |
| 5962F0320102VYC | A | 02/19/2003 | 3 | STMICRO | | Y | RHFL4913S30-03V | 782 |
| 5962F0320102VZA | A | 02/19/2003 | 3 | STMICRO | | Y | RHFL4913ESY3006V | 782 |
| 5962F0320102VZC | A | 02/19/2003 | 3 | STMICRO | | Y | RHFL4913ESY3005V | 782 |
| 5962-0320201QXA | | 01/23/2003 | 1 | QP SEMI | | | 82S181A-50/QXA | 664 |
| 5962-0320301Q3A | | 01/27/2003 | 1 | QP SEMI | | Y | 82S191-65/Q3A | 669 |
| 5962-0320301QJA | | 01/27/2003 | 1 | QP SEMI | | Y | 82S191-65/QJA | 669 |
| 5962-0320301QKA | | 01/27/2003 | 1 | QP SEMI | | Y | 82S191-65/QKA | 669 |
| 5962-0320301QLA | | 01/27/2003 | 1 | QP SEMI | | Y | 82S191-65/QLA | 669 |
| 5962-0320301QXA | | 01/27/2003 | 1 | QP SEMI | | Y | 82S191-65/QXA | 669 |
| 5962-0320302Q3A | | 01/27/2003 | 1 | QP SEMI | | Y | 82S191-50/Q3A | 669 |
| 5962-0320302QJA | | 01/27/2003 | 1 | QP SEMI | | Y | 82S191-50/QJA | 669 |
| 5962-0320302QKA | | 01/27/2003 | 1 | QP SEMI | | Y | 82S191-50/QKA | 669 |
| 5962-0320302QLA | | 01/27/2003 | 1 | QP SEMI | | Y | 82S191-50/QLA | 669 |
| 5962-0320302QXA | | 01/27/2003 | 1 | QP SEMI | | Y | 82S191-50/QXA | 669 |
| 5962-0323201HXA | | 11/26/2003 | 1 | MS KENNEDY | | Y | MSK5275-1.5H | 782 |
| 5962-0323201HXC | | 11/26/2003 | 1 | MS KENNEDY | | Y | MSK5275-1.5H | 782 |
| 5962-0323202HXA | | 11/26/2003 | 1 | MS KENNEDY | | Y | MSK5275-1.7H | 782 |
| 5962-0323202HXC | | 11/26/2003 | 1 | MS KENNEDY | | Y | MSK5275-1.7H | 782 |
| 5962-0323203HXA | | 11/26/2003 | 1 | MS KENNEDY | | Y | MSK5275-1.8H | 782 |
| 5962-0323203HXC | | 11/26/2003 | 1 | MS KENNEDY | | Y | MSK5275-1.8H | 782 |
| 5962-0323204HXA | | 11/26/2003 | 1 | MS KENNEDY | | Y | MSK5275-1.9H | 782 |
| 5962-0323204HXC | | 11/26/2003 | 1 | MS KENNEDY | | Y | MSK5275-1.9H | 782 |
| 5962-0323205HXA | | 11/26/2003 | 1 | MS KENNEDY | | Y | MSK5275-2.5H | 782 |
| 5962-0323205HXC | | 11/26/2003 | 1 | MS KENNEDY | | Y | MSK5275-2.5H | 782 |
| 5962-0323206HXA | | 11/26/2003 | 1 | MS KENNEDY | | Y | MSK5275-3.3H | 782 |
| 5962-0323206HXC | | 11/26/2003 | 1 | MS KENNEDY | | Y | MSK5275-3.3H | 782 |
| 5962-0323207HXA | | 11/26/2003 | 1 | MS KENNEDY | | Y | MSK5275-3.4H | 782 |
| 5962-0323207HXC | | 11/26/2003 | 1 | MS KENNEDY | | Y | MSK5275-3.4H | 782 |
| 5962-0323208HXA | | 11/26/2003 | 1 | MS KENNEDY | | Y | MSK5275-5.0H | 782 |
| 5962-0323208HXC | | 11/26/2003 | 1 | MS KENNEDY | | Y | MSK5275-5.0H | 782 |
| 5962-0323209HXA | | 11/26/2003 | 1 | MS KENNEDY | | Y | MSK5275-12H | 782 |
| 5962-0323209HXC | | 11/26/2003 | 1 | MS KENNEDY | | Y | MSK5275-12H | 782 |
| 5962-0323401KXC | | 03/13/2003 | 1 | AEROFLEX | | Y | ACT8502-S | 199 |
| 5962F0323501QUA | | 11/14/2003 | 2 | UTMC | | Y | UT8R512K8-15UCA | 629 |
| 5962F0323501QUC | | 11/14/2003 | 2 | UTMC | | Y | UT8R512K8-15UCC | 629 |
| 5962F0323501VUA | | 11/14/2003 | 2 | UTMC | | Y | UT8R512K8-15UCA | 629 |
| 5962F0323501VUC | | 11/14/2003 | 2 | UTMC | | Y | UT8R512K8-15UCC | 629 |
| 5962F0323502QUA | | 11/14/2003 | 2 | UTMC | | Y | UT8R512K8-15UWA | 629 |
| 5962F0323502QUC | | 11/14/2003 | 2 | UTMC | | Y | UT8R512K8-15UWC | 629 |
| 5962F0323502VUA | | 11/14/2003 | 2 | UTMC | | Y | UT8R512K8-15UWA | 629 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962F0323502VUC | | 11/14/2003 | 2 | UTMC | | Y | UT8R512K8-15UWC | 629 |
| 5962F0323601QXA | A | 10/20/2003 | 2 | UTMC | | Y | UT8R128K32-15WCA | 629 |
| 5962F0323601QXC | A | 10/20/2003 | 2 | UTMC | | Y | UT8R128K32-15WCC | 629 |
| 5962F0323601VXA | A | 10/20/2003 | 2 | UTMC | | Y | UT8R128K32-15WCA | 629 |
| 5962F0323601VXC | A | 10/20/2003 | 2 | UTMC | | Y | UT8R128K32-15WCC | 629 |
| 5962F0323602QXA | A | 10/20/2003 | 2 | UTMC | | Y | UT8R128K32-15WWA | 629 |
| 5962F0323602QXC | A | 10/20/2003 | 2 | UTMC | | Y | UT8R128K32-15WWC | 629 |
| 5962F0323602VXA | A | 10/20/2003 | 2 | UTMC | | Y | UT8R128K32-15WWA | 629 |
| 5962F0323602VXC | A | 10/20/2003 | 2 | UTMC | | Y | UT8R128K32-15WWC | 629 |
| 5962-0323701MXA | | 11/25/2003 | 1 | INTER. RECT. | | | OM7580ASMM | 780 |
| 5962-0323701MYA | | 11/25/2003 | 1 | INTER. RECT. | | | OM7580ASCM | 780 |
| 5962-0323702MXA | | 11/25/2003 | 1 | INTER. RECT. | | | OM7581SMM | 780 |
| 5962-0323702MZA | | 11/25/2003 | 1 | INTER. RECT. | | | OM7581SCM | 780 |
| 5962-0323703MMA | | 11/25/2003 | 1 | INTER. RECT. | | | OM7585ANMM | 780 |
| 5962-0323703MTA | | 11/25/2003 | 1 | INTER. RECT. | | | OM7585ASTM | 780 |
| 5962-0323703MUA | | 11/25/2003 | 1 | INTER. RECT. | | | OM7585ASRM | 780 |
| 5962-0323801MXA | | 12/05/2003 | 1 | INTER. RECT. | | | OM7764ASM | 780 |
| 5962-0323801MYA | | 12/05/2003 | 1 | INTER. RECT. | | | OM7764ASC | 780 |
| 5962-0324101HXA | A | 04/19/2004 | 1 | VPT | | Y | DVSA283R3S/H-E | 594 |
| 5962-0324101HXC | A | 04/19/2004 | 1 | VPT | | Y | DVSA283R3S/H | 594 |
| 5962-0324102HXA | A | 04/19/2004 | 1 | VPT | | Y | DVSA2805S/H-E | 594 |
| 5962-0324102HXC | A | 04/19/2004 | 1 | VPT | | Y | DVSA2805S/H | 594 |
| 5962-0324103HXA | A | 04/19/2004 | 1 | VPT | | Y | DVSA285R2S/H-E | 594 |
| 5962-0324103HXC | A | 04/19/2004 | 1 | VPT | | Y | DVSA285R2S/H | 594 |
| 5962-0324104HXA | A | 04/19/2004 | 1 | VPT | | Y | DVSA2812S/H-E | 594 |
| 5962-0324104HXC | A | 04/19/2004 | 1 | VPT | | Y | DVSA2812S/H | 594 |
| 5962-0324105HXA | A | 04/19/2004 | 1 | VPT | | Y | DVSA2815S/H-E | 594 |
| 5962-0324105HXC | A | 04/19/2004 | 1 | VPT | | Y | DVSA2815S/H | 594 |
| 5962-0324201HXA | A | 04/19/2004 | 1 | VPT | | Y | DVSA2805D/H-E | 594 |
| 5962-0324201HXC | A | 04/19/2004 | 1 | VPT | | Y | DVSA2805D/H | 594 |
| 5962-0324202HXA | A | 04/19/2004 | 1 | VPT | | Y | DVSA2812D/H-E | 594 |
| 5962-0324202HXC | A | 04/19/2004 | 1 | VPT | | Y | DVSA2812D/H | 594 |
| 5962-0324203HXA | A | 04/19/2004 | 1 | VPT | | Y | DVSA2815D/H-E | 594 |
| 5962-0324203HXC | A | 04/19/2004 | 1 | VPT | | Y | DVSA2815D/H | 594 |
| 5962-0324301HXA | A | 04/21/2004 | 1 | VPT | | Y | DVHF283R3S/H-E | 594 |
| 5962-0324301HXC | A | 04/21/2004 | 1 | VPT | | Y | DVHF283R3S/H | 594 |
| 5962-0324301HYA | A | 04/21/2004 | 1 | VPT | | Y | DVHF283R3SF/H-E | 594 |
| 5962-0324301HYC | A | 04/21/2004 | 1 | VPT | | Y | DVHF283R3SF/H | 594 |
| 5962-0324302HXA | A | 04/21/2004 | 1 | VPT | | Y | DVHF2805S/H-E | 594 |
| 5962-0324302HXC | A | 04/21/2004 | 1 | VPT | | Y | DVHF2805S/H | 594 |
| 5962-0324302HYA | A | 04/21/2004 | 1 | VPT | | Y | DVHF2805SF/H-E | 594 |
| 5962-0324302HYC | A | 04/21/2004 | 1 | VPT | | Y | DVHF2805SF/H | 594 |
| 5962-0324303HXA | A | 04/21/2004 | 1 | VPT | | Y | DVHF285R2S/H-E | 594 |
| 5962-0324303HXC | A | 04/21/2004 | 1 | VPT | | Y | DVHF285R2S/H | 594 |
| 5962-0324303HYA | A | 04/21/2004 | 1 | VPT | | Y | DVHF285R2SF/H-E | 594 |
| 5962-0324303HYC | A | 04/21/2004 | 1 | VPT | | Y | DVHF285R2SF/H | 594 |
| 5962-0324304HXA | A | 04/21/2004 | 1 | VPT | | Y | DVHF2812S/H-E | 594 |
| 5962-0324304HXC | A | 04/21/2004 | 1 | VPT | | Y | DVHF2812S/H | 594 |
| 5962-0324304HYA | A | 04/21/2004 | 1 | VPT | | Y | DVHF2812SF/H-E | 594 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-0324304HYC | A | 04/21/2004 | 1 | VPT | | Y | DVHF2812SF/H | 594 |
| 5962-0324305HXA | A | 04/21/2004 | 1 | VPT | | Y | DVHF2815S/H-E | 594 |
| 5962-0324305HXC | A | 04/21/2004 | 1 | VPT | | Y | DVHF2815S/H | 594 |
| 5962-0324305HYA | A | 04/21/2004 | 1 | VPT | | Y | DVHF2815SF/H-E | 594 |
| 5962-0324305HYC | A | 04/21/2004 | 1 | VPT | | Y | DVHF2815SF/H | 594 |
| 5962-0324401HXA | A | 04/21/2004 | 1 | VPT | | Y | DVHF2805D/H-E | 594 |
| 5962-0324401HXC | A | 04/21/2004 | 1 | VPT | | Y | DVHF2805D/H | 594 |
| 5962-0324401HYA | A | 04/21/2004 | 1 | VPT | | Y | DVHF2805DF/H-E | 594 |
| 5962-0324401HYC | A | 04/21/2004 | 1 | VPT | | Y | DVHF2805DF/H | 594 |
| 5962-0324402HXA | A | 04/21/2004 | 1 | VPT | | Y | DVHF2812D/H-E | 594 |
| 5962-0324402HXC | A | 04/21/2004 | 1 | VPT | | Y | DVHF2812D/H | 594 |
| 5962-0324402HYA | A | 04/21/2004 | 1 | VPT | | Y | DVHF2812DF/H-E | 594 |
| 5962-0324402HYC | A | 04/21/2004 | 1 | VPT | | Y | DVHF2812DF/H | 594 |
| 5962-0324403HXA | A | 04/21/2004 | 1 | VPT | | Y | DVHF2815D/H-E | 594 |
| 5962-0324403HXC | A | 04/21/2004 | 1 | VPT | | Y | DVHF2815D/H | 594 |
| 5962-0324403HYA | A | 04/21/2004 | 1 | VPT | | Y | DVHF2815DF/H-E | 594 |
| 5962-0324403HYC | A | 04/21/2004 | 1 | VPT | | Y | DVHF2815DF/H | 594 |
| 5962-0324501QXA | A | 03/11/2004 | 2 | TI | | Y | SMJ320C6415DGADW | 432 |
| 5962-0324601Q9A | | 08/14/2003 | 2 | ATMEL NANTES | | Y | TSC695FL-15MBMQ | 439 |
| 5962-0324601V9A | | 08/14/2003 | 2 | ATMEL NANTES | | Y | TSC695FL-15SBSV | 439 |
| 5962-0324601QXC | | 08/14/2003 | 2 | ATMEL NANTES | | Y | TSC695FL-15MAMQ | 439 |
| 5962-0324601VXC | | 08/14/2003 | 2 | ATMEL NANTES | | Y | TSC695FL-15SASV | 439 |
| 5962R0324601VXC | | 08/14/2003 | 2 | ATMEL NANTES | | Y | TSC695FL-15SASR | 439 |
| 5962-0324701HXA | | 07/23/2003 | 1 | MICROPAC | | Y | 53252-117 | 460 |
| 5962-0324701HXC | | 07/23/2003 | 1 | MICROPAC | | Y | 53252-118 | 460 |
| 5962-0324701HYA | | 07/23/2003 | 1 | MICROPAC | | Y | 53252-107 | 460 |
| 5962-0324701HYC | | 07/23/2003 | 1 | MICROPAC | | Y | 53252-108 | 460 |
| 5962F0324801V9A | | 09/30/2003 | 1 | INTERSIL | | Y | ISL74422BRHVX | 555 |
| 5962F0324801QXC | | 09/30/2003 | 1 | INTERSIL | | Y | ISL74422BRHQF | 555 |
| 5962F0324801VXC | | 09/30/2003 | 1 | INTERSIL | | Y | ISL74422BRHVF | 555 |
| 5962-0324901QCA | | 03/25/2004 | 3 | NATIONAL | | Y | LMH6722J-QML | 713 |
| 5962-0324901QZA | | 03/25/2004 | 3 | NATIONAL | | Y | LMH6722WG-QML | 713 |
| 5962-0325001QXA | A | 07/04/2004 | 2 | ATMEL NANTES | | Y | AT40KEL040KW1MQ | 381 |
| 5962-0325001VXA | A | 07/04/2004 | 2 | ATMEL NANTES | | Y | AT40KEL040KW1SV | 381 |
| 5962-0325001QYA | A | 07/04/2004 | 2 | ATMEL NANTES | | Y | AT40KEL040KZ1MQ | 381 |
| 5962-0325001VYA | A | 07/04/2004 | 2 | ATMEL NANTES | | Y | AT40KEL040KZ1SV | 381 |
| 5962-0325101HXA | | 03/03/2004 | 1 | DDC | | Y | RDC-19220-143 | 594 |
| 5962-0325101HXC | | 03/03/2004 | 1 | DDC | | Y | RDC-19220-113 | 594 |
| 5962-0325102HYA | | 03/03/2004 | 1 | DDC | | Y | RDC-19222-143 | 594 |
| 5962-0325102HYC | | 03/03/2004 | 1 | DDC | | Y | RDC-19222-113 | 594 |
| 5962-0325103HXA | | 03/03/2004 | 1 | DDC | | Y | RDC-19220S-143 | 594 |
| 5962-0325103HXC | | 03/03/2004 | 1 | DDC | | Y | RDC-19220S-113 | 594 |
| 5962-0325104HYA | | 03/03/2004 | 1 | DDC | | Y | RDC-19222S-143 | 594 |
| 5962-0325104HYC | | 03/03/2004 | 1 | DDC | | Y | RDC-19222S-113 | 594 |
| 5962-0325301HXA | A | 08/19/2004 | 1 | INTERPOINT | | Y | MHF+285R2S/883 | 594 |
| 5962-0325301HXC | A | 08/19/2004 | 1 | INTERPOINT | | Y | MHF+285R2S/883 | 594 |
| 5962-0325301HZA | A | 08/19/2004 | 1 | INTERPOINT | | Y | MHF+285R2SF/883 | 594 |
| 5962-0325301HZC | A | 08/19/2004 | 1 | INTERPOINT | | Y | MHF+285R2SF/883 | 594 |
| 5962-03A0101NXC | | 06/03/2004 | 2 | AMI | | Y | 13925-001 | 365 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-03A0201NXA | | 05/19/2003 | 2 | AMI | | Y | 14050-501 | 365 |
| 5962-03A0301NXB | | 01/29/2003 | 1 | AMI | | Y | 11788-001 | 365 |
| 5962-03A0401QQC | A | 03/07/2003 | 1 | AMI | | Y | 15004-022 | 365 |
| 5962-03A0501NXA | | 06/24/2003 | 1 | AMI | | Y | 14174-501 | 365 |
| 5962-03A0601QXC | | 08/11/2003 | 3 | ATMEL NANTES | | Y | AT7908EJLMQ | 365 |
| 5962-03A0601VXC | | 08/11/2003 | 3 | ATMEL NANTES | | Y | AT7908EJLSV | 365 |
| 5962-03B0101QXC | A | 12/04/2003 | | (NONE) | | | MG2RTPL (GEN) | 365 |
| 5962-03B0102QXC | A | 12/04/2003 | | (NONE) | | | MG2RTPL (GEN) | 365 |
| 5962-03B0103QXC | A | 12/04/2003 | 3 | ATMEL NANTES | | Y | MMKU-MG2044PHxxxM | 365 |
| 5962-03B0103VXC | A | 12/04/2003 | 3 | ATMEL NANTES | | Y | SMKU-MG2044PHxxxS | 365 |
| 5962R03B0103VXC | A | 12/04/2003 | 3 | ATMEL NANTES | | Y | SMKU-MG2044PHxxxS | 365 |
| 5962-03B0103QYC | A | 12/04/2003 | 3 | ATMEL NANTES | | Y | MMKN-MG2044PHxxxM | 365 |
| 5962-03B0103VYC | A | 12/04/2003 | 3 | ATMEL NANTES | | Y | SMKN-MG2044PHxxxS | 365 |
| 5962R03B0103VYC | A | 12/04/2003 | 3 | ATMEL NANTES | | Y | SMKN-MG2044PHxxxS | 365 |
| 5962-03B0103QZC | A | 12/04/2003 | 3 | ATMEL NANTES | | Y | MMKW-G2044PHxxxM | 365 |
| 5962-03B0103VZC | A | 12/04/2003 | 3 | ATMEL NANTES | | Y | SMKW-G2044PHxxxSV | 365 |
| 5962R03B0103VZC | A | 12/04/2003 | 3 | ATMEL NANTES | | Y | SMKW-G2044PHxxxSR | 365 |
| 5962-03B0104QYC | A | 12/04/2003 | 3 | ATMEL NANTES | | Y | MMKN-G2142PHxxxMQ | 365 |
| 5962-03B0104VYC | A | 12/04/2003 | 3 | ATMEL NANTES | | Y | SMKN-G2142PHxxxSV | 365 |
| 5962R03B0104VYC | A | 12/04/2003 | 3 | ATMEL NANTES | | Y | SMKN-G2142PHxxxSR | 365 |
| 5962-03B0104QZC | A | 12/04/2003 | 3 | ATMEL NANTES | | Y | MMKW-G2142PHxxxM | 365 |
| 5962-03B0104VZC | A | 12/04/2003 | 3 | ATMEL NANTES | | Y | SMKW-G2142PHxxxSV | 365 |
| 5962R03B0104VZC | A | 12/04/2003 | 3 | ATMEL NANTES | | Y | SMKW-G2142PHxxxSR | 365 |
| 5962-03B0105QUC | A | 12/04/2003 | 3 | ATMEL NANTES | | Y | MM2E-G2270PHxxxMQ | 365 |
| 5962-03B0105VUC | A | 12/04/2003 | 3 | ATMEL NANTES | | Y | SM2E-G2270PHxxxSV | 365 |
| 5962R03B0105VUC | A | 12/04/2003 | 3 | ATMEL NANTES | | Y | SM2E-G2270PHxxxSR | 365 |
| 5962-03B0105QYC | A | 12/04/2003 | 3 | ATMEL NANTES | | Y | MMKN-G2270PHxxxMQ | 365 |
| 5962-03B0105VYC | A | 12/04/2003 | 3 | ATMEL NANTES | | Y | SMKN-G2270PHxxxSV | 365 |
| 5962R03B0105VYC | A | 12/04/2003 | 3 | ATMEL NANTES | | Y | SMKN-G2270PHxxxSR | 365 |
| 5962-03B0105QZC | A | 12/04/2003 | 3 | ATMEL NANTES | | Y | MMKW-G2270PHxxxM | 365 |
| 5962-03B0105VZC | A | 12/04/2003 | 3 | ATMEL NANTES | | Y | SMKW-G2270PHxxxSV | 365 |
| 5962R03B0105VZC | A | 12/04/2003 | 3 | ATMEL NANTES | | Y | SMKW-G2270PHxxxSR | 365 |
| 5962H0420101QYA | | 01/05/2004 | 1 | UTMC | | Y | UT54LVDS032LVTUCA | 575 |
| 5962H0420101QYC | | 01/05/2004 | 1 | UTMC | | Y | UT54LVDS032LVTUCC | 575 |
| 5962H0420101VYA | | 01/05/2004 | 1 | UTMC | | Y | UT54LVDS032LVTUCA | 575 |
| 5962H0420101VYC | | 01/05/2004 | 1 | UTMC | | Y | UT54LVDS032LVTUCC | 575 |
| 5962R0420102QYA | | 01/05/2004 | 1 | UTMC | | Y | UT54LVDS032LVTUCA | 575 |
| 5962R0420102QYC | | 01/05/2004 | 1 | UTMC | | Y | UT54LVDS032LVTUCC | 575 |
| 5962R0420102VYA | | 01/05/2004 | 1 | UTMC | | Y | UT54LVDS032LVTUCA | 575 |
| 5962R0420102VYC | | 01/05/2004 | 1 | UTMC | | Y | UT54LVDS032LVTUCC | 575 |
| 5962-0420201QPA | | 06/29/2004 | 3 | NATIONAL | | Y | LMH6714J-QML | 739 |
| 5962-0420201QZA | | 06/29/2004 | 3 | NATIONAL | | Y | LMH6714WG-QML | 739 |
| 5962-0420301QPA | | 03/22/2004 | 3 | NATIONAL | | Y | LMH6720J-QML | 739 |
| 5962-0420301QZA | | 03/22/2004 | 3 | NATIONAL | | Y | LMH6720WG-QML | 739 |
| 5962-0420401HPA | | 08/13/2004 | 1 | AGILENT | | Y | HCPL-5121-200 | 460 |
| 5962-0420401HPC | | 08/13/2004 | 1 | AGILENT | | Y | HCPL-5121 | 460 |
| 5962-0420401HXA | | 08/13/2004 | 1 | AGILENT | | Y | HCPL-5121-300 | 460 |
| 5962-0420401HYA | | 08/13/2004 | 1 | AGILENT | | Y | HCPL-5121-100 | 460 |
| 5962-0420401HYC | | 08/13/2004 | 1 | AGILENT | | Y | HCPL-5121-100 | 460 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-0420501HPA | | 08/13/2004 | 1 | AGILENT | | Y | HCPL-5151-200 | 460 |
| 5962-0420501HPC | | 08/13/2004 | 1 | AGILENT | | Y | HCPL-5151 | 460 |
| 5962-0420501HXA | | 08/13/2004 | 1 | AGILENT | | Y | HCPL-5151-300 | 460 |
| 5962-0420501HYA | | 08/13/2004 | 1 | AGILENT | | Y | HCPL-5151-100 | 460 |
| 5962-0420501HYC | | 08/13/2004 | 1 | AGILENT | | Y | HCPL-5151-100 | 460 |
| 5962-0420801QXA | A | 05/11/2004 | 2 | NATIONAL | | Y | ADC1175MW-QML | 592 |
| 5962-0421001QXA | | 02/25/2004 | 2 | STMICRO | | Y | 54AC16244K02Q | 529 |
| 5962-0421001QXC | | 02/25/2004 | 2 | STMICRO | | Y | 54AC16244K01Q | 529 |
| 5962-0421001VXA | | 02/25/2004 | 2 | STMICRO | | Y | 54AC16244K02V | 529 |
| 5962-0421001VXC | | 02/25/2004 | 2 | STMICRO | | Y | 54AC16244K01V | 529 |
| 5962F0421001QXA | | 02/25/2004 | 2 | STMICRO | | Y | RHFAC16244K02Q | 529 |
| 5962F0421001QXC | | 02/25/2004 | 2 | STMICRO | | Y | RHFAC16244K01Q | 529 |
| 5962F0421001VXA | | 02/25/2004 | 2 | STMICRO | | Y | RHFAC16244K02V | 529 |
| 5962F0421001VXC | | 02/25/2004 | 2 | STMICRO | | Y | RHFAC16244K01V | 529 |
| 5962-0421101QXA | | 03/16/2004 | 2 | STMICRO | | Y | 54AC16245K02Q | 590 |
| 5962-0421101QXC | | 03/16/2004 | 2 | STMICRO | | Y | 54AC16245K01Q | 590 |
| 5962-0421101VXA | | 03/16/2004 | 2 | STMICRO | | Y | 54AC16245K02V | 590 |
| 5962-0421101VXC | | 03/16/2004 | 2 | STMICRO | | Y | 54AC16245K01V | 590 |
| 5962F0421101QXA | | 03/16/2004 | 2 | STMICRO | | Y | RHFAC16245K02Q | 590 |
| 5962F0421101QXC | | 03/16/2004 | 2 | STMICRO | | Y | RHFAC16245K01Q | 590 |
| 5962F0421101VXA | | 03/16/2004 | 2 | STMICRO | | Y | RHFAC16245K02V | 590 |
| 5962F0421101VXC | | 03/16/2004 | 2 | STMICRO | | Y | RHFAC16245K01V | 590 |
| 5962-0421201QXA | | 03/16/2004 | 2 | STMICRO | | Y | 54AC16373K02Q | 342 |
| 5962-0421201QXC | | 03/16/2004 | 2 | STMICRO | | Y | 54AC16373K01Q | 342 |
| 5962-0421201VXA | | 03/16/2004 | 2 | STMICRO | | Y | 54AC16373K02V | 342 |
| 5962-0421201VXC | | 03/16/2004 | 2 | STMICRO | | Y | 54AC16373K01V | 342 |
| 5962F0421201QXA | | 03/16/2004 | 2 | STMICRO | | Y | RHFAC16373K02Q | 342 |
| 5962F0421201QXC | | 03/16/2004 | 2 | STMICRO | | Y | RHFAC16373K01Q | 342 |
| 5962F0421201VXA | | 03/16/2004 | 2 | STMICRO | | Y | RHFAC16373K02V | 342 |
| 5962F0421201VXC | | 03/16/2004 | 2 | STMICRO | | Y | RHFAC16373K01V | 342 |
| 5962-0421301QXA | | 03/16/2004 | 2 | STMICRO | | Y | 54AC16374K02Q | 159 |
| 5962-0421301QXC | | 03/16/2004 | 2 | STMICRO | | Y | 54AC16374K01Q | 159 |
| 5962-0421301VXA | | 03/16/2004 | 2 | STMICRO | | Y | 54AC16374K02V | 159 |
| 5962-0421301VXC | | 03/16/2004 | 2 | STMICRO | | Y | 54AC16374K01V | 159 |
| 5962F0421301QXA | | 03/16/2004 | 2 | STMICRO | | Y | RHFAC16374K02Q | 159 |
| 5962F0421301QXC | | 03/16/2004 | 2 | STMICRO | | Y | RHFAC16374K01Q | 159 |
| 5962F0421301VXA | | 03/16/2004 | 2 | STMICRO | | Y | RHFAC16374K02V | 159 |
| 5962F0421301VXC | | 03/16/2004 | 2 | STMICRO | | Y | RHFAC16374K01V | 159 |
| 5962-04A0101QXA | | 02/24/2004 | 1 | AUSTIN SEMI. | | | X-27S37-032-EC-01 | 365 |
| 5962-04A0102QXA | | 02/24/2004 | 1 | AUSTIN SEMI. | | | X-27S37-032-EC-02 | 365 |
| 5962-04A0103QXA | | 02/24/2004 | 1 | AUSTIN SEMI. | | | X-27S37-032-EC-03 | 365 |
| 5962-04A0104QXA | | 02/24/2004 | 1 | AUSTIN SEMI. | | | X-27S37-032-EC-04 | 365 |
| 5962-04A0105QXA | | 02/24/2004 | 1 | AUSTIN SEMI. | | | X-27S37-032-EC-05 | 365 |
| 5962-04A0106QXA | | 02/24/2004 | 1 | AUSTIN SEMI. | | | X-27S37-032-EC-06 | 365 |
| 5962-04A0107QXA | | 02/24/2004 | 1 | AUSTIN SEMI. | | | X-27S37-032-EC-07 | 365 |
| 5962-04A0108QXA | | 02/24/2004 | 1 | AUSTIN SEMI. | | | X-27S37-032-EC-08 | 365 |
| 5962-04A0109QXA | | 02/24/2004 | 1 | AUSTIN SEMI. | | | X-27S37-032-EC-09 | 365 |
| 5962-04A0110QXA | | 02/24/2004 | 1 | AUSTIN SEMI. | | | X-27S37-032-EC-10 | 365 |
| 5962-04B0101Q*C | A | 09/01/2004 | 2 | UTMC | | Y | UT06MRA010 | 365 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962F04B0101V*C | A | 09/01/2004 | 2 | UTMC | | Y | UT06MRA010 | 365 |
| 5962-04B0102Q*C | A | 09/01/2004 | 2 | UTMC | | Y | UT06MRA025 | 365 |
| 5962F04B0102V*C | A | 09/01/2004 | 2 | UTMC | | Y | UT06MRA025 | 365 |
| 5962-04B0103Q*C | A | 09/01/2004 | 2 | UTMC | | Y | UT06MRA050 | 365 |
| 5962F04B0103V*C | A | 09/01/2004 | 2 | UTMC | | Y | UT06MRA050 | 365 |
| 5962-04B0104Q*C | A | 09/01/2004 | 2 | UTMC | | Y | UT06MRA075 | 365 |
| 5962F04B0104V*C | A | 09/01/2004 | 2 | UTMC | | Y | UT06MRA075 | 365 |
| 5962-04B0105Q*C | A | 09/01/2004 | 2 | UTMC | | Y | UT06MRA100 | 365 |
| 5962R04B0105V*C | A | 09/01/2004 | 2 | UTMC | | Y | UT06MRA100 | 365 |
| 5962-04B0106Q*C | A | 09/01/2004 | 2 | UTMC | | Y | UT06MRA150 | 365 |
| 5962R04B0106V*C | A | 09/01/2004 | 2 | UTMC | | Y | UT06MRA150 | 365 |
| 5962-04B0107Q*C | A | 09/01/2004 | 2 | UTMC | | Y | UT06MRA200 | 365 |
| 5962R04B0107V*C | A | 09/01/2004 | 2 | UTMC | | Y | UT06MRA200 | 365 |
| 5962-04B0108Q*C | A | 09/01/2004 | 2 | UTMC | | Y | UT06MRA250 | 365 |
| 5962R04B0108V*C | A | 09/01/2004 | 2 | UTMC | | Y | UT06MRA250 | 365 |
| 5962-04B0109Q*C | A | 09/01/2004 | 2 | UTMC | | Y | UT06MRA300 | 365 |
| 5962R04B0109V*C | A | 09/01/2004 | 2 | UTMC | | Y | UT06MRA300 | 365 |
| 5962-04B0110Q*C | A | 09/01/2004 | 2 | UTMC | | Y | UT06MRA350 | 365 |
| 5962R04B0110V*C | A | 09/01/2004 | 2 | UTMC | | Y | UT06MRA350 | 365 |
| 5962-04B0111Q*C | A | 09/01/2004 | 2 | UTMC | | Y | UT06MRA400 | 365 |
| 5962R04B0111V*C | A | 09/01/2004 | 2 | UTMC | | Y | UT06MRA400 | 365 |
| 5962-04B0112Q*C | A | 09/01/2004 | 2 | UTMC | | Y | UT06MRA450 | 365 |
| 5962R04B0112V*C | A | 09/01/2004 | 2 | UTMC | | Y | UT06MRA450 | 365 |
| 5962-04B0113Q*C | A | 09/01/2004 | 2 | UTMC | | Y | UT06MRA500 | 365 |
| 5962R04B0113V*C | A | 09/01/2004 | 2 | UTMC | | Y | UT06MRA500 | 365 |
| 5962-04B0114Q*C | A | 09/01/2004 | 2 | UTMC | | Y | UT06MRA550 | 365 |
| 5962R04B0114V*C | A | 09/01/2004 | 2 | UTMC | | Y | UT06MRA550 | 365 |
| 5962-04B0115Q*C | A | 09/01/2004 | 2 | UTMC | | Y | UT06MRA600 | 365 |
| 5962R04B0115V*C | A | 09/01/2004 | 2 | UTMC | | Y | UT06MRA600 | 365 |
| 5962-3812801M2A | D | 09/06/2002 | | (NONE) | | | AD584S (GEN) | 785 |
| 5962-3812801VGA | D | 09/06/2002 | 3 | ANALOG (5) | | Y | AD584SH/QMLV | 785 |
| 5962R3812801VGA | D | 09/06/2002 | 3 | ANALOG (5) | | Y | AD584SH/QMLVR | 785 |
| 5962-3812802M2A | D | 09/06/2002 | | (NONE) | | | AD584T (GEN) | 785 |
| 5962-3812802VGA | D | 09/06/2002 | 3 | ANALOG (5) | | Y | AD584TH/QMLV | 785 |
| 5962R3812802VGA | D | 09/06/2002 | 3 | ANALOG (5) | | Y | AD584TH/QMLVR | 785 |
| 5962-3812803M2C | D | 09/06/2002 | | (NONE) | | | MX584S (GEN) | 785 |
| 5962-3812803MGC | D | 09/06/2002 | 1 | MAXIM INTEG. | | | MX584SH/883B | 785 |
| 5962-3812803MPA | D | 09/06/2002 | 1 | MAXIM INTEG. | | | MX584SQ/883B | 785 |
| 5962-3812804M2C | D | 09/06/2002 | | (NONE) | | | MX584T (GEN) | 785 |
| 5962-3812804MGC | D | 09/06/2002 | 1 | MAXIM INTEG. | | | MX584TH/883B | 785 |
| 5962-3812804MPA | D | 09/06/2002 | 1 | MAXIM INTEG. | | | MX584TQ/883B | 785 |
| 5962-3826701MTA | G | 10/05/2001 | 2 | ATMEL | | | AT28C010-25UM/883 | 669 |
| 5962-3826701MUA | G | 10/05/2001 | 2 | ATMEL | | | AT28C010-25EM/883 | 669 |
| 5962-3826701MWC | G | 10/05/2001 | | (NONE) | 09/09/1999 | | 28C010-25 (GEN) | 669 |
| 5962-3826701MXA | G | 10/05/2001 | 2 | ATMEL | | | AT28C010-25DM/883 | 669 |
| 5962-3826701MYA | G | 10/05/2001 | 2 | ATMEL | | | AT28C010-25LM/883 | 669 |
| 5962-3826701MZA | G | 10/05/2001 | 2 | ATMEL | | | AT28C010-25FM/883 | 669 |
| 5962-3826702MWA | G | 10/05/2001 | | (NONE) | | | 28C010-250 (GEN) | 669 |
| 5962-3826702MXA | G | 10/05/2001 | | (NONE) | | | 28C010-250 (GEN) | 669 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-3826702MYA | G | 10/05/2001 | | (NONE) | | | 28C010-250 (GEN) | 669 |
| 5962-3826702MZA | G | 10/05/2001 | | (NONE) | | | 28C010-250 (GEN) | 669 |
| 5962-3826703MTA | G | 10/05/2001 | 2 | ATMEL | | | AT28C010-20UM/883 | 669 |
| 5962-3826703MUA | G | 10/05/2001 | 2 | ATMEL | | | AT28C010-20EM/883 | 669 |
| 5962-3826703MWC | G | 10/05/2001 | | (NONE) | 09/09/1999 | | 28C010-20 (GEN) | 669 |
| 5962-3826703MXA | G | 10/05/2001 | 2 | ATMEL | | | AT28C010-20DM/883 | 669 |
| 5962-3826703MYA | G | 10/05/2001 | 2 | ATMEL | | | AT28C010-20LM/883 | 669 |
| 5962-3826703MZA | G | 10/05/2001 | 2 | ATMEL | | | AT28C010-20FM/883 | 669 |
| 5962-3826704MWA | G | 10/05/2001 | | (NONE) | | | 28C010-200 (GEN) | 669 |
| 5962-3826704MXA | G | 10/05/2001 | | (NONE) | | | 28C010-200 (GEN) | 669 |
| 5962-3826704MYA | G | 10/05/2001 | | (NONE) | | | 28C010-200 (GEN) | 669 |
| 5962-3826704MZA | G | 10/05/2001 | | (NONE) | | | 28C010-200 (GEN) | 669 |
| 5962-3826705MTA | G | 10/05/2001 | 2 | ATMEL | | | AT28C010-15UM/883 | 669 |
| 5962-3826705MUA | G | 10/05/2001 | 2 | ATMEL | | | AT28C010-15EM/883 | 669 |
| 5962-3826705MWC | G | 10/05/2001 | | (NONE) | 09/09/1999 | | 28C010-15 (GEN) | 669 |
| 5962-3826705MXA | G | 10/05/2001 | 2 | ATMEL | | | AT28C010-15DM/883 | 669 |
| 5962-3826705MXA | G | 10/05/2001 | 3 | XICOR | | | X28C010DMB-15 | 669 |
| 5962-3826705MYA | G | 10/05/2001 | 2 | ATMEL | | | AT28C010-15LM/883 | 669 |
| 5962-3826705MZA | G | 10/05/2001 | 2 | ATMEL | | | AT28C010-15FM/883 | 669 |
| 5962-3826706MWA | G | 10/05/2001 | | (NONE) | | | 28C010-150 (GEN) | 669 |
| 5962-3826706MXA | G | 10/05/2001 | | (NONE) | | | 28C010-150 (GEN) | 669 |
| 5962-3826706MYA | G | 10/05/2001 | | (NONE) | | | 28C010-150 (GEN) | 669 |
| 5962-3826706MZA | G | 10/05/2001 | | (NONE) | | | 28C010-150 (GEN) | 669 |
| 5962-3826707MTA | G | 10/05/2001 | 2 | ATMEL | | | AT28C010-12UM/883 | 669 |
| 5962-3826707MUA | G | 10/05/2001 | 2 | ATMEL | | | AT28C010-12EM/883 | 669 |
| 5962-3826707MWC | G | 10/05/2001 | | (NONE) | 09/09/1999 | | 28C010-12 (GEN) | 669 |
| 5962-3826707MXA | G | 10/05/2001 | 2 | ATMEL | | | AT28C010-12DM/883 | 669 |
| 5962-3826707MXA | G | 10/05/2001 | 3 | XICOR | | | X28C010DMB-12 | 669 |
| 5962-3826707MYA | G | 10/05/2001 | 2 | ATMEL | | | AT28C010-12LM/883 | 669 |
| 5962-3826707MZA | G | 10/05/2001 | 2 | ATMEL | | | AT28C010-12FM/883 | 669 |
| 5962-3826716Q6C | G | 10/05/2001 | 1 | MAXWELL | | Y | 28C010TRPFB-25 | 669 |
| 5962-3826716Q7C | G | 10/05/2001 | 1 | MAXWELL | | Y | 28C011TRPFB-25 | 669 |
| 5962-3826716QMA | G | 10/05/2001 | 1 | AUSTIN SEMI. | | Y | AS58C1001F-25/883C | 669 |
| 5962-3826716QMC | G | 10/05/2001 | 1 | MAXWELL | | Y | 28C010TFB-25 | 669 |
| 5962-3826716QNA | G | 10/05/2001 | 1 | AUSTIN SEMI. | | Y | AS58C1001SF-25/883C | 669 |
| 5962-3826716QUA | G | 10/05/2001 | 1 | AUSTIN SEMI. | | Y | AS58C1001ECA-25/883 | 669 |
| 5962-3826717Q6C | G | 10/05/2001 | 1 | MAXWELL | | Y | 28C010TRPFB-20 | 669 |
| 5962-3826717Q7C | G | 10/05/2001 | 1 | MAXWELL | | Y | 28C011TRPFB-20 | 669 |
| 5962-3826717QMA | G | 10/05/2001 | 1 | AUSTIN SEMI. | | Y | AS58C1001F-20/883C | 669 |
| 5962-3826717QMC | G | 10/05/2001 | 1 | MAXWELL | | Y | 28C010TFB-20 | 669 |
| 5962-3826717QNA | G | 10/05/2001 | 1 | AUSTIN SEMI. | | Y | AS58C1001SF-20/883C | 669 |
| 5962-3826717QUA | G | 10/05/2001 | 1 | AUSTIN SEMI. | | Y | AS58C1001ECA-20/883 | 669 |
| 5962-3826718Q6C | G | 10/05/2001 | 1 | MAXWELL | | Y | 28C010TRPFB-15 | 669 |
| 5962-3826718Q7C | G | 10/05/2001 | 1 | MAXWELL | | Y | 28C011TRPFB-15 | 669 |
| 5962-3826718QMA | G | 10/05/2001 | 1 | AUSTIN SEMI. | | Y | AS58C1001F-15/883C | 669 |
| 5962-3826718QMC | G | 10/05/2001 | 1 | MAXWELL | | Y | 28C010TFB-15 | 669 |
| 5962-3826718QNA | G | 10/05/2001 | 1 | AUSTIN SEMI. | | Y | AS58C1001SF-15/883C | 669 |
| 5962-3826718QUA | G | 10/05/2001 | 1 | AUSTIN SEMI. | | Y | AS58C1001ECA-15/883 | 669 |
| 5962-3826719Q6C | G | 10/05/2001 | 1 | MAXWELL | | Y | 28C010TRPFB-12 | 669 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-3826719Q7C | G | 10/05/2001 | 1 | MAXWELL | | Y | 28C011TRPFB-12 | 669 |
| 5962-3826719QMC | G | 10/05/2001 | 1 | MAXWELL | | Y | 28C010TFB-12 | 669 |
| 5962-3829401MTA | G | 02/20/1998 | | (NONE) | | | 7164150 (GEN) | 620 |
| 5962-3829401MXA | G | 02/20/1998 | | (NONE) | | | 7164150 (GEN) | 620 |
| 5962-3829401MYA | G | 02/20/1998 | | (NONE) | | | 7164150 (GEN) | 620 |
| 5962-3829401MZA | G | 02/20/1998 | | (NONE) | | | 7164150 (GEN) | 620 |
| 5962-3829402MTA | G | 02/20/1998 | | (NONE) | | | 7164120 (GEN) | 620 |
| 5962-3829402MXA | G | 02/20/1998 | | (NONE) | | | 7164120 (GEN) | 620 |
| 5962-3829402MYA | G | 02/20/1998 | | (NONE) | | | 7164120 (GEN) | 620 |
| 5962-3829402MZA | G | 02/20/1998 | | (NONE) | | | 7164120 (GEN) | 620 |
| 5962-3829403MTA | G | 02/20/1998 | | (NONE) | | | 7164120 (GEN) | 620 |
| 5962-3829403MXA | G | 02/20/1998 | | (NONE) | | | 7164120 (GEN) | 620 |
| 5962-3829403MYA | G | 02/20/1998 | | (NONE) | | | 7164120 (GEN) | 620 |
| 5962-3829403MZA | G | 02/20/1998 | | (NONE) | | | 7164120 (GEN) | 620 |
| 5962-3829404MTA | G | 02/20/1998 | | (NONE) | | | 7164100 (GEN) | 620 |
| 5962-3829404MXA | G | 02/20/1998 | | (NONE) | | | 7164100 (GEN) | 620 |
| 5962-3829404MYA | G | 02/20/1998 | | (NONE) | | | 7164100 (GEN) | 620 |
| 5962-3829404MZA | G | 02/20/1998 | | (NONE) | | | 7164100 (GEN) | 620 |
| 5962-3829405MTA | G | 02/20/1998 | | (NONE) | | | 7164100 (GEN) | 620 |
| 5962-3829405MXA | G | 02/20/1998 | | (NONE) | | | 7164100 (GEN) | 620 |
| 5962-3829405MYA | G | 02/20/1998 | | (NONE) | | | 7164100 (GEN) | 620 |
| 5962-3829405MZA | G | 02/20/1998 | | (NONE) | | | 7164100 (GEN) | 620 |
| 5962-3829406MTA | G | 02/20/1998 | | (NONE) | 01/01/1999 | | 7164L70 (GEN) | 620 |
| 5962-3829406MUA | G | 02/20/1998 | | (NONE) | | | 7C185-70 (GEN) | 620 |
| 5962-3829406MXA | G | 02/20/1998 | 0 | IDT | | Y | IDT7164L70DB | 620 |
| 5962-3829406MYA | G | 02/20/1998 | 0 | IDT | | Y | IDT7164L70L32B | 620 |
| 5962-3829406MZA | G | 02/20/1998 | 0 | IDT | | Y | IDT7164L70TDB | 620 |
| 5962-3829407MMA | G | 02/20/1998 | | (NONE) | | | 5C6408-70 (GEN) | 620 |
| 5962-3829407MTA | G | 02/20/1998 | | (NONE) | 01/01/1999 | | 7164S70 (GEN) | 620 |
| 5962-3829407MUA | G | 02/20/1998 | | (NONE) | | | 5C6408-70 (GEN) | 620 |
| 5962-3829407MXA | G | 02/20/1998 | 0 | IDT | | Y | IDT7164S70DB | 620 |
| 5962-3829407MXA | G | 02/20/1998 | 0 | PYRAMID | | | P4C164-70DWMB | 620 |
| 5962-3829407MXA | G | 02/20/1998 | 3 | QP SEMI | | Y | QP7C186A-70DMB | 620 |
| 5962-3829407MYA | G | 02/20/1998 | 0 | IDT | | Y | IDT7164S70L32B | 620 |
| 5962-3829407MYA | G | 02/20/1998 | 3 | QP SEMI | | Y | QP7C186A-70LMB | 620 |
| 5962-3829407MZA | G | 02/20/1998 | 0 | IDT | | Y | IDT7164S70TDB | 620 |
| 5962-3829407MZA | G | 02/20/1998 | 3 | QP SEMI | | Y | QP7C185A-70DMB | 620 |
| 5962-3829408MMA | G | 02/20/1998 | | (NONE) | | | 5C6408-55 (GEN) | 620 |
| 5962-3829408MTA | G | 02/20/1998 | | (NONE) | 01/01/1999 | | 7164L55 (GEN) | 620 |
| 5962-3829408MUA | G | 02/20/1998 | | (NONE) | | | 5C6408-55 (GEN) | 620 |
| 5962-3829408MXA | G | 02/20/1998 | 0 | IDT | | Y | IDT7164L55DB | 620 |
| 5962-3829408MXA | G | 02/20/1998 | 0 | PYRAMID | | | P4C164L-55DWMB | 620 |
| 5962-3829408MYA | G | 02/20/1998 | 0 | IDT | | Y | IDT7164L55L32B | 620 |
| 5962-3829408MZA | G | 02/20/1998 | 0 | IDT | | Y | IDT7164L55TDB | 620 |
| 5962-3829409MMA | G | 02/20/1998 | | (NONE) | | | 5C6408-55 (GEN) | 620 |
| 5962-3829409MTA | G | 02/20/1998 | | (NONE) | 01/01/1999 | | 7164S55 (GEN) | 620 |
| 5962-3829409MUA | G | 02/20/1998 | | (NONE) | | | 5C6408-55 (GEN) | 620 |
| 5962-3829409MXA | G | 02/20/1998 | 0 | IDT | | Y | IDT7164S55DB | 620 |
| 5962-3829409MXA | G | 02/20/1998 | 0 | PYRAMID | | | P4C164-55DWMB | 620 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-3829409MXA | G | 02/20/1998 | 3 | QP SEMI | | Y | QP7C186A-55DMB | 620 |
| 5962-3829409MYA | G | 02/20/1998 | 0 | IDT | | Y | IDT7164S55L32B | 620 |
| 5962-3829409MYA | G | 02/20/1998 | 3 | QP SEMI | | Y | QP7C186A-55LMB | 620 |
| 5962-3829409MZA | G | 02/20/1998 | 0 | IDT | | Y | IDT7164S55TDB | 620 |
| 5962-3829409MZA | G | 02/20/1998 | 0 | PYRAMID | | | P4C164-55DMB | 620 |
| 5962-3829409MZA | G | 02/20/1998 | 3 | QP SEMI | | Y | QP7C185A-55DMB | 620 |
| 5962-3829410MMA | G | 02/20/1998 | | (NONE) | | | 5C6408-45 (GEN) | 620 |
| 5962-3829410MTA | G | 02/20/1998 | | (NONE) | 01/01/1999 | | 7164L45 (GEN) | 620 |
| 5962-3829410MUA | G | 02/20/1998 | | (NONE) | | | 5C6408-45 (GEN) | 620 |
| 5962-3829410MXA | G | 02/20/1998 | 0 | IDT | | Y | IDT7164L45DB | 620 |
| 5962-3829410MXA | G | 02/20/1998 | 0 | PYRAMID | | | P4C164L-45DWMB | 620 |
| 5962-3829410MYA | G | 02/20/1998 | 0 | IDT | | Y | IDT7164L45L32B | 620 |
| 5962-3829410MZA | G | 02/20/1998 | 0 | IDT | | Y | IDT7164L45TDB | 620 |
| 5962-3829411MMA | G | 02/20/1998 | | (NONE) | | | 5C6408-45 (GEN) | 620 |
| 5962-3829411MTA | G | 02/20/1998 | | (NONE) | 01/01/1999 | | 7164S45 (GEN) | 620 |
| 5962-3829411MUA | G | 02/20/1998 | | (NONE) | | | 5C6408-45 (GEN) | 620 |
| 5962-3829411MXA | G | 02/20/1998 | 0 | IDT | | Y | IDT7164S45DB | 620 |
| 5962-3829411MXA | G | 02/20/1998 | 0 | PYRAMID | | | P4C164-45DWMB | 620 |
| 5962-3829411MXA | G | 02/20/1998 | 3 | QP SEMI | | Y | QP7C186A-45DMB | 620 |
| 5962-3829411MYA | G | 02/20/1998 | 0 | IDT | | Y | IDT7164S45L32B | 620 |
| 5962-3829411MYA | G | 02/20/1998 | 3 | QP SEMI | | Y | QP7C186A-45LMB | 620 |
| 5962-3829411MZA | G | 02/20/1998 | 0 | IDT | | Y | IDT7164S45TDB | 620 |
| 5962-3829411MZA | G | 02/20/1998 | 3 | QP SEMI | | Y | QP7C185A-45DMB | 620 |
| 5962-3829412MMA | G | 02/20/1998 | | (NONE) | | | 5C6408-35 (GEN) | 620 |
| 5962-3829412MTA | G | 02/20/1998 | | (NONE) | 01/01/1999 | | 7164L35 (GEN) | 620 |
| 5962-3829412MUA | G | 02/20/1998 | | (NONE) | | | 5C6408-35 (GEN) | 620 |
| 5962-3829412MXA | G | 02/20/1998 | 0 | IDT | | Y | IDT7164L35DB | 620 |
| 5962-3829412MXA | G | 02/20/1998 | 0 | PYRAMID | | | P4C164L-35DWMB | 620 |
| 5962-3829412MYA | G | 02/20/1998 | 0 | IDT | | Y | IDT7164L35L32B | 620 |
| 5962-3829412MZA | G | 02/20/1998 | 0 | IDT | | Y | IDT7164L35TDB | 620 |
| 5962-3829413MMA | G | 02/20/1998 | | (NONE) | | | 5C6408-35 (GEN) | 620 |
| 5962-3829413MTA | G | 02/20/1998 | | (NONE) | 01/01/1999 | | 7164S35 (GEN) | 620 |
| 5962-3829413MUA | G | 02/20/1998 | | (NONE) | | | 5C6408-35 (GEN) | 620 |
| 5962-3829413MXA | G | 02/20/1998 | 0 | IDT | | Y | IDT7164S35DB | 620 |
| 5962-3829413MXA | G | 02/20/1998 | 0 | PYRAMID | | | P4C164-35DWMB | 620 |
| 5962-3829413MXA | G | 02/20/1998 | 3 | QP SEMI | | Y | QP7C186A-35DMB | 620 |
| 5962-3829413MYA | G | 02/20/1998 | 0 | IDT | | Y | IDT7164S35L32B | 620 |
| 5962-3829413MYA | G | 02/20/1998 | 3 | QP SEMI | | Y | QP7C186A-35LMB | 620 |
| 5962-3829413MZA | G | 02/20/1998 | 0 | IDT | | Y | IDT7164S35TDB | 620 |
| 5962-3829413MZA | G | 02/20/1998 | 3 | QP SEMI | | Y | QP7C185A-35DMB | 620 |
| 5962-3829414MMA | G | 02/20/1998 | 1 | PYRAMID | | | P4C164-25FSMB | 620 |
| 5962-3829414MTA | G | 02/20/1998 | 1 | PYRAMID | | | P4C164-25FMB | 620 |
| 5962-3829414MUA | G | 02/20/1998 | | (NONE) | | | 5C6408-25 (GEN) | 620 |
| 5962-3829414MXA | G | 02/20/1998 | 0 | IDT | | Y | IDT7164L25DB | 620 |
| 5962-3829414MXA | G | 02/20/1998 | 0 | PYRAMID | | | P4C164L-25DWMB | 620 |
| 5962-3829414MYA | G | 02/20/1998 | 0 | IDT | | Y | IDT7164L25L32B | 620 |
| 5962-3829414MZA | G | 02/20/1998 | 0 | IDT | | Y | IDT7164L25TDB | 620 |
| 5962-3829415MMA | G | 02/20/1998 | 1 | PYRAMID | | | P4C164-25FSMB | 620 |
| 5962-3829415MTA | G | 02/20/1998 | 1 | PYRAMID | | | P4C164-25FMB | 620 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-3829415MUA | G | 02/20/1998 | | (NONE) | | | 5C6408-25 (GEN) | 620 |
| 5962-3829415MXA | G | 02/20/1998 | 0 | IDT | | Y | IDT7164S25DB | 620 |
| 5962-3829415MXA | G | 02/20/1998 | 0 | PYRAMID | | | P4C164-25DWMB | 620 |
| 5962-3829415MXA | G | 02/20/1998 | 3 | QP SEMI | | Y | QP7C186A-25DMB | 620 |
| 5962-3829415MYA | G | 02/20/1998 | 0 | IDT | | Y | IDT7164S25L32B | 620 |
| 5962-3829415MYA | G | 02/20/1998 | 3 | QP SEMI | | Y | QP7C186A-25LMB | 620 |
| 5962-3829415MZA | G | 02/20/1998 | 0 | IDT | | Y | IDT7164S25TDB | 620 |
| 5962-3829415MZA | G | 02/20/1998 | 3 | QP SEMI | | Y | QP7C185A-25DMB | 620 |
| 5962-3829416MMA | G | 02/20/1998 | | (NONE) | | | 5C6408-20 (GEN) | 620 |
| 5962-3829416MTA | G | 02/20/1998 | | (NONE) | 01/01/1999 | | 7164L20 (GEN) | 620 |
| 5962-3829416MUA | G | 02/20/1998 | | (NONE) | | | 5C6408-20 (GEN) | 620 |
| 5962-3829416MXA | G | 02/20/1998 | 0 | IDT | | Y | IDT7164L20DB | 620 |
| 5962-3829416MXA | G | 02/20/1998 | 0 | PYRAMID | | | P4C164L-20DWMB | 620 |
| 5962-3829416MYA | G | 02/20/1998 | 0 | IDT | | Y | IDT7164L20L32B | 620 |
| 5962-3829416MZA | G | 02/20/1998 | 0 | IDT | | Y | IDT7164L20TDB | 620 |
| 5962-3829417MMA | G | 02/20/1998 | | (NONE) | | | 5C6408-20 (GEN) | 620 |
| 5962-3829417MTA | G | 02/20/1998 | | (NONE) | 01/01/1999 | | 7164S20 (GEN) | 620 |
| 5962-3829417MUA | G | 02/20/1998 | | (NONE) | | | 5C6408-20 (GEN) | 620 |
| 5962-3829417MXA | G | 02/20/1998 | 0 | IDT | | Y | IDT7164S20DB | 620 |
| 5962-3829417MXA | G | 02/20/1998 | 0 | PYRAMID | | | P4C164-20DWMB | 620 |
| 5962-3829417MXA | G | 02/20/1998 | 3 | QP SEMI | | Y | QP7C186A-20DMB | 620 |
| 5962-3829417MYA | G | 02/20/1998 | 0 | IDT | | Y | IDT7164S20L32B | 620 |
| 5962-3829417MYA | G | 02/20/1998 | 3 | QP SEMI | | Y | QP7C186A-20LMB | 620 |
| 5962-3829417MZA | G | 02/20/1998 | 0 | IDT | | Y | IDT7164S20TDB | 620 |
| 5962-3829417MZA | G | 02/20/1998 | 3 | QP SEMI | | Y | QP7C185A-20DMB | 620 |
| 5962-3829418MMA | G | 02/20/1998 | 1 | AUSTIN SEMI. | | Y | MT5C6408F-15L | 620 |
| 5962-3829418MMA | G | 02/20/1998 | 1 | PYRAMID | | | P4C164L-15FSMB | 620 |
| 5962-3829418MTA | G | 02/20/1998 | | (NONE) | | | 7C185-15 (GEN) | 620 |
| 5962-3829418MUA | G | 02/20/1998 | 1 | AUSTIN SEMI. | | Y | MT5C6408EC-15L | 620 |
| 5962-3829418MUA | G | 02/20/1998 | 1 | PYRAMID | | | P4C164L-15LMB | 620 |
| 5962-3829418MXA | G | 02/20/1998 | 0 | PYRAMID | | | P4C164L-15DWMB | 620 |
| 5962-3829418MYA | G | 02/20/1998 | 1 | AUSTIN SEMI. | | Y | MT5C6408ECW-15L | 620 |
| 5962-3829418MYA | G | 02/20/1998 | 1 | PYRAMID | | | P4C164L-15L32MB | 620 |
| 5962-3829418MZA | G | 02/20/1998 | 1 | AUSTIN SEMI. | | Y | MT5C6408C-15L | 620 |
| 5962-3829418MZA | G | 02/20/1998 | 0 | PYRAMID | | | P4C164L-15DMB | 620 |
| 5962-3829419MMA | G | 02/20/1998 | 1 | AUSTIN SEMI. | | Y | MT5C6408F-15 | 620 |
| 5962-3829419MMA | G | 02/20/1998 | 1 | PYRAMID | | | P4C164-15FSMB | 620 |
| 5962-3829419MTA | G | 02/20/1998 | 0 | PYRAMID | | | P4C164-15FMB | 620 |
| 5962-3829419MUA | G | 02/20/1998 | 1 | AUSTIN SEMI. | | Y | MT5C6408EC-15 | 620 |
| 5962-3829419MUA | G | 02/20/1998 | 1 | PYRAMID | | | P4C164-15LSMB | 620 |
| 5962-3829419MXA | G | 02/20/1998 | 0 | PYRAMID | | | P4C164-15DWMB | 620 |
| 5962-3829419MYA | G | 02/20/1998 | 1 | AUSTIN SEMI. | | Y | MT5C6408ECW-15 | 620 |
| 5962-3829419MYA | G | 02/20/1998 | 1 | PYRAMID | | | P4C164L-15L32MB | 620 |
| 5962-3829419MZA | G | 02/20/1998 | 1 | AUSTIN SEMI. | | Y | MT5C6408C-15 | 620 |
| 5962-3829419MZA | G | 02/20/1998 | 0 | PYRAMID | | | P4C164-15DMB | 620 |
| 5962-3829420MUA | G | 02/20/1998 | | (NONE) | | | 7C185-70 (GEN) | 620 |
| 5962-3829421MUA | G | 02/20/1998 | 0 | PYRAMID | | | P4C164-70LMB | 620 |
| 5962-3829421MUA | G | 02/20/1998 | 3 | QP SEMI | | Y | QP7C185A-70LMB | 620 |
| 5962-3829422MUA | G | 02/20/1998 | 0 | PYRAMID | | | P4C164L-55LMB | 620 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-3829423MUA | G | 02/20/1998 | 0 | PYRAMID | | | P4C164-55LMB | 620 |
| 5962-3829423MUA | G | 02/20/1998 | 3 | QP SEMI | | Y | QP7C185A-55LMB | 620 |
| 5962-3829424MUA | G | 02/20/1998 | 0 | PYRAMID | | | P4C164L-45LMB | 620 |
| 5962-3829425MUA | G | 02/20/1998 | 0 | PYRAMID | | | P4C164-45LMB | 620 |
| 5962-3829425MUA | G | 02/20/1998 | 3 | QP SEMI | | Y | QP7C185A-45LMB | 620 |
| 5962-3829426MUA | G | 02/20/1998 | 0 | PYRAMID | | | P4C164L-35LMB | 620 |
| 5962-3829427MUA | G | 02/20/1998 | 0 | PYRAMID | | | P4C164-35LMB | 620 |
| 5962-3829427MUA | G | 02/20/1998 | 3 | QP SEMI | | Y | QP7C185A-35LMB | 620 |
| 5962-3829428MUA | G | 02/20/1998 | 0 | PYRAMID | | | P4C164L-25LMB | 620 |
| 5962-3829429MUA | G | 02/20/1998 | 0 | PYRAMID | | | P4C164-25LMB | 620 |
| 5962-3829429MUA | G | 02/20/1998 | 3 | QP SEMI | | Y | QP7C185A-25LMB | 620 |
| 5962-3829430MUA | G | 02/20/1998 | 0 | PYRAMID | | | P4C164-20LMB | 620 |
| 5962-3829430MUA | G | 02/20/1998 | 3 | QP SEMI | | Y | QP7C185A-20LMB | 620 |
| 5962-3829431MXA | G | 02/20/1998 | | (NONE) | | | 8810100 (GEN) | 620 |
| 5962-3829431MYA | G | 02/20/1998 | | (NONE) | | | 8810100 (GEN) | 620 |
| 5962-3829432MXA | G | 02/20/1998 | | (NONE) | | | 881070 (GEN) | 620 |
| 5962-3829432MYA | G | 02/20/1998 | | (NONE) | | | 881070 (GEN) | 620 |
| 5962-3829433MMA | G | 02/20/1998 | | (NONE) | | | 7C185-55 (GEN) | 620 |
| 5962-3829433MTA | G | 02/20/1998 | | (NONE) | | | 7C185-55 (GEN) | 620 |
| 5962-3829433MUA | G | 02/20/1998 | | (NONE) | | | 7C185-55 (GEN) | 620 |
| 5962-3829433MXA | G | 02/20/1998 | 1 | PYRAMID | | | P4C164L-55DWMB | 620 |
| 5962-3829433MYA | G | 02/20/1998 | | (NONE) | | | 7C185-55 (GEN) | 620 |
| 5962-3829433MZA | G | 02/20/1998 | | (NONE) | | | 7C185-55 (GEN) | 620 |
| 5962-3829434MMA | G | 02/20/1998 | | (NONE) | | | 7C185-45 (GEN) | 620 |
| 5962-3829434MTA | G | 02/20/1998 | | (NONE) | | | 7C185-45 (GEN) | 620 |
| 5962-3829434MUA | G | 02/20/1998 | | (NONE) | | | 7C185-45 (GEN) | 620 |
| 5962-3829434MXA | G | 02/20/1998 | 1 | PYRAMID | | | P4C164L-45DWMB | 620 |
| 5962-3829434MYC | G | 02/20/1998 | | (NONE) | | | 7C185-45 (GEN) | 620 |
| 5962-3829434MZA | G | 02/20/1998 | | (NONE) | | | 7C185-45 (GEN) | 620 |
| 5962H3829435BNA | G | 02/20/1998 | 2 | UTMC | 01/30/2006 | Y | UT6716485 | 620 |
| 5962H3829435BNC | G | 02/20/1998 | 2 | UTMC | 01/30/2006 | Y | UT6716485 | 620 |
| 5962H3829435SNA | G | 02/20/1998 | 2 | UTMC | 01/30/2006 | Y | UT6716485 | 620 |
| 5962H3829435SNC | G | 02/20/1998 | 2 | UTMC | 01/30/2006 | Y | UT6716485 | 620 |
| 5962H3829435BXA | G | 02/20/1998 | 2 | UTMC | 01/30/2006 | Y | UT6716485 | 620 |
| 5962H3829435BXC | G | 02/20/1998 | 2 | UTMC | 01/30/2006 | Y | UT6716485 | 620 |
| 5962H3829435SXA | G | 02/20/1998 | 2 | UTMC | 01/30/2006 | Y | UT6716485 | 620 |
| 5962H3829435SXC | G | 02/20/1998 | 2 | UTMC | 01/30/2006 | Y | UT6716485 | 620 |
| 5962H3829436BNA | G | 02/20/1998 | 2 | UTMC | 01/30/2006 | Y | UT6716470 | 620 |
| 5962H3829436BNC | G | 02/20/1998 | 2 | UTMC | 01/30/2006 | Y | UT6716470 | 620 |
| 5962H3829436SNA | G | 02/20/1998 | 2 | UTMC | 01/30/2006 | Y | UT6716470 | 620 |
| 5962H3829436SNC | G | 02/20/1998 | 2 | UTMC | 01/30/2006 | Y | UT6716470 | 620 |
| 5962H3829436BXA | G | 02/20/1998 | 2 | UTMC | 01/30/2006 | Y | UT6716470 | 620 |
| 5962H3829436BXC | G | 02/20/1998 | 2 | UTMC | 01/30/2006 | Y | UT6716470 | 620 |
| 5962H3829436SXA | G | 02/20/1998 | 2 | UTMC | 01/30/2006 | Y | UT6716470 | 620 |
| 5962H3829436SXC | G | 02/20/1998 | 2 | UTMC | 01/30/2006 | Y | UT6716470 | 620 |
| 5962H3829437BNA | G | 02/20/1998 | | (NONE) | | | UT6716455 (GEN) | 620 |
| 5962H3829437SNA | G | 02/20/1998 | | (NONE) | | | UT6716455 (GEN) | 620 |
| 5962H3829437BXA | G | 02/20/1998 | | (NONE) | | | UT6716455 (GEN) | 620 |
| 5962H3829437SXA | G | 02/20/1998 | | (NONE) | | | UT6716455 (GEN) | 620 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962H3829438Q9C | G | 02/20/1998 | | (NONE) | | | HC6364/1 (GEN) | 620 |
| 5962H3829438V9C | G | 02/20/1998 | | (NONE) | | | HC6364/1 (GEN) | 620 |
| 5962H3829440Q9C | G | 02/20/1998 | | (NONE) | | | HC6364/1 (GEN) | 620 |
| 5962H3829440V9C | G | 02/20/1998 | | (NONE) | | | HC6364/1 (GEN) | 620 |
| 5962H3829442Q9C | G | 02/20/1998 | | (NONE) | | | HC6364/1 (GEN) | 620 |
| 5962H3829442V9C | G | 02/20/1998 | | (NONE) | | | HC6364/1 (GEN) | 620 |
| 5962H3829443Q9C | G | 02/20/1998 | | (NONE) | | | HC6364/1 (GEN) | 620 |
| 5962H3829443V9C | G | 02/20/1998 | | (NONE) | | | HC6364/1 (GEN) | 620 |
| 5962H3829444Q8A | G | 02/20/1998 | | (NONE) | | | | 620 |
| 5962H3829444V8A | G | 02/20/1998 | | (NONE) | | | | 620 |
| 5962H3829444Q9C | G | 02/20/1998 | | (NONE) | 12/20/2001 | | LOR6408C-55 (GEN) | 620 |
| 5962H3829444V9C | G | 02/20/1998 | | (NONE) | 12/20/2001 | | LOR6408C-55 (GEN) | 620 |
| 5962H3829445Q9C | G | 02/20/1998 | | (NONE) | | | HC6364/2 (GEN) | 620 |
| 5962H3829445V9C | G | 02/20/1998 | | (NONE) | | | HC6364/2 (GEN) | 620 |
| 5962-3829446MMA | G | 02/20/1998 | 1 | AUSTIN SEMI. | | Y | MT5C6408F-12L | 620 |
| 5962-3829446MMA | G | 02/20/1998 | 1 | PYRAMID | | | P4C164L-12FSMB | 620 |
| 5962-3829446MUA | G | 02/20/1998 | 1 | AUSTIN SEMI. | | Y | MT5C6408EC-12L | 620 |
| 5962-3829446MUA | G | 02/20/1998 | 1 | PYRAMID | | | P4C164L-12LSMB | 620 |
| 5962-3829446MYA | G | 02/20/1998 | 1 | AUSTIN SEMI. | | Y | MT5C6408ECW-12L | 620 |
| 5962-3829446MZA | G | 02/20/1998 | 1 | AUSTIN SEMI. | | Y | MT5C6408C-12L | 620 |
| 5962-3829446MZA | G | 02/20/1998 | 1 | PYRAMID | | | P4C164L-12DMB | 620 |
| 5962-3829447MMA | G | 02/20/1998 | 1 | AUSTIN SEMI. | | Y | MT5C6408F-12 | 620 |
| 5962-3829447MMA | G | 02/20/1998 | 1 | PYRAMID | | | P4C164-12FSMB | 620 |
| 5962-3829447MUA | G | 02/20/1998 | 1 | AUSTIN SEMI. | | Y | MT5C6408EC-12 | 620 |
| 5962-3829447MUA | G | 02/20/1998 | 1 | PYRAMID | | | P4C164-12LSMB | 620 |
| 5962-3829447MYA | G | 02/20/1998 | 1 | AUSTIN SEMI. | | Y | MT5C6408ECW-12 | 620 |
| 5962-3829447MZA | G | 02/20/1998 | 1 | AUSTIN SEMI. | | Y | MT5C6408C-12 | 620 |
| 5962-3829447MZA | G | 02/20/1998 | 1 | PYRAMID | | | P4C164-12DMB | 620 |
| 5962-3829448MMA | G | 02/20/1998 | 1 | AUSTIN SEMI. | | Y | MT5C6408F-70 | 620 |
| 5962-3829448MMA | G | 02/20/1998 | 1 | PYRAMID | | | P4C164-70FSMB | 620 |
| 5962-3829448MUA | G | 02/20/1998 | 1 | AUSTIN SEMI. | | Y | MT5C6408EC-70 | 620 |
| 5962-3829448MUA | G | 02/20/1998 | 1 | PYRAMID | | | P4C164-70LSMB | 620 |
| 5962-3829448MXA | G | 02/20/1998 | 1 | PYRAMID | | | P4C164-70DWMB | 620 |
| 5962-3829448MYA | G | 02/20/1998 | 1 | AUSTIN SEMI. | | Y | MT5C6408ECW-70 | 620 |
| 5962-3829448MYA | G | 02/20/1998 | 1 | PYRAMID | | | P4C164-70L32MB | 620 |
| 5962-3829448MZA | G | 02/20/1998 | 1 | AUSTIN SEMI. | | Y | MT5C6408C-70 | 620 |
| 5962-3829448MZA | G | 02/20/1998 | 1 | PYRAMID | | | P4C164-70DMB | 620 |
| 5962-3829449MMA | G | 02/20/1998 | 1 | AUSTIN SEMI. | | Y | MT5C6408F-55L | 620 |
| 5962-3829449MMA | G | 02/20/1998 | 1 | PYRAMID | | | P4C164L-55FSMB | 620 |
| 5962-3829449MTA | G | 02/20/1998 | 1 | PYRAMID | | | P4C164L-55FMB | 620 |
| 5962-3829449MUA | G | 02/20/1998 | 1 | AUSTIN SEMI. | | Y | MT5C6408ECW-55L | 620 |
| 5962-3829449MUA | G | 02/20/1998 | 1 | PYRAMID | | | P4C164L-55LSMB | 620 |
| 5962-3829449MXA | G | 02/20/1998 | 1 | PYRAMID | | | P4C164L-55DWMB | 620 |
| 5962-3829449MYA | G | 02/20/1998 | 1 | AUSTIN SEMI. | | Y | MT5C6408ECW-55L | 620 |
| 5962-3829449MYA | G | 02/20/1998 | 1 | PYRAMID | | | P4C164L-55L32MB | 620 |
| 5962-3829449MZA | G | 02/20/1998 | 1 | AUSTIN SEMI. | | Y | MT5C6408C-55L | 620 |
| 5962-3829449MZA | G | 02/20/1998 | 1 | PYRAMID | | | P4C164L-55DMB | 620 |
| 5962-3829450MMA | G | 02/20/1998 | 1 | AUSTIN SEMI. | | Y | MT5C6408F-55 | 620 |
| 5962-3829450MTA | G | 02/20/1998 | 1 | PYRAMID | | | P4C164-55FMB | 620 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-3829450MUA | G | 02/20/1998 | 1 | AUSTIN SEMI. | | Y | MT5C6408EC-55 | 620 |
| 5962-3829450MUA | G | 02/20/1998 | 1 | PYRAMID | | | P4C164-55LSMB | 620 |
| 5962-3829450MXA | G | 02/20/1998 | 1 | PYRAMID | | | P4C164-55DWMB | 620 |
| 5962-3829450MYA | G | 02/20/1998 | 1 | AUSTIN SEMI. | | Y | MT5C6408ECW-55 | 620 |
| 5962-3829450MYA | G | 02/20/1998 | 1 | PYRAMID | | | P4C164-55L32MB | 620 |
| 5962-3829450MZA | G | 02/20/1998 | 1 | AUSTIN SEMI. | | Y | MT5C6408C-55 | 620 |
| 5962-3829450MZA | G | 02/20/1998 | 1 | PYRAMID | | | P4C164-55DMB | 620 |
| 5962-3829451MMA | G | 02/20/1998 | 1 | AUSTIN SEMI. | | Y | MT5C6408F-45 | 620 |
| 5962-3829451MMA | G | 02/20/1998 | 1 | PYRAMID | | | P4C164L-45FSMB | 620 |
| 5962-3829451MTA | G | 02/20/1998 | 1 | PYRAMID | | | P4C164L-45FMB | 620 |
| 5962-3829451MUA | G | 02/20/1998 | 1 | AUSTIN SEMI. | | Y | MT5C6408EC-45 | 620 |
| 5962-3829451MUA | G | 02/20/1998 | 1 | PYRAMID | | | P4C164L-45LSMB | 620 |
| 5962-3829451MXA | G | 02/20/1998 | 1 | PYRAMID | | | P4C164L-45DWMB | 620 |
| 5962-3829451MYA | G | 02/20/1998 | 1 | AUSTIN SEMI. | | Y | MT5C6408ECW-45 | 620 |
| 5962-3829451MYA | G | 02/20/1998 | 1 | PYRAMID | | | P4C164L-45L32MB | 620 |
| 5962-3829451MZA | G | 02/20/1998 | 1 | AUSTIN SEMI. | | Y | MT5C6408C-45 | 620 |
| 5962-3829451MZA | G | 02/20/1998 | 1 | PYRAMID | | | P4C164L-45DMB | 620 |
| 5962-3829452MMA | G | 02/20/1998 | 1 | AUSTIN SEMI. | | Y | MT5C6408F-45 | 620 |
| 5962-3829452MMA | G | 02/20/1998 | 1 | PYRAMID | | | P4C164-45FSMB | 620 |
| 5962-3829452MTA | G | 02/20/1998 | 1 | PYRAMID | | | P4C164-45FMB | 620 |
| 5962-3829452MUA | G | 02/20/1998 | 1 | AUSTIN SEMI. | | Y | MT5C6408EC-45 | 620 |
| 5962-3829452MUA | G | 02/20/1998 | 1 | PYRAMID | | | P4C164-45LSMB | 620 |
| 5962-3829452MXA | G | 02/20/1998 | 1 | PYRAMID | | | P4C164-45DWMB | 620 |
| 5962-3829452MYA | G | 02/20/1998 | 1 | AUSTIN SEMI. | | Y | MT5C6408ECW-45 | 620 |
| 5962-3829452MYA | G | 02/20/1998 | 1 | PYRAMID | | | P4C164-45L32MB | 620 |
| 5962-3829452MZA | G | 02/20/1998 | 1 | AUSTIN SEMI. | | Y | MT5C6408C-45 | 620 |
| 5962-3829452MZA | G | 02/20/1998 | 1 | PYRAMID | | | P4C164-45DMB | 620 |
| 5962-3829453MMA | G | 02/20/1998 | 1 | AUSTIN SEMI. | | Y | MT5C6408F-35L | 620 |
| 5962-3829453MMA | G | 02/20/1998 | 1 | PYRAMID | | | P4C164L-35FSMB | 620 |
| 5962-3829453MTA | G | 02/20/1998 | 1 | PYRAMID | | | P4C164L-35FMB | 620 |
| 5962-3829453MUA | G | 02/20/1998 | 1 | AUSTIN SEMI. | | Y | MT5C6408EC-35L | 620 |
| 5962-3829453MUA | G | 02/20/1998 | 1 | PYRAMID | | | P4C164L-35LSMB | 620 |
| 5962-3829453MXA | G | 02/20/1998 | 1 | PYRAMID | | | P4C164L-35DWMB | 620 |
| 5962-3829453MYA | G | 02/20/1998 | 1 | AUSTIN SEMI. | | Y | MT5C6408ECW-35L | 620 |
| 5962-3829453MYA | G | 02/20/1998 | 1 | PYRAMID | | | P4C164L-35L32MB | 620 |
| 5962-3829453MZA | G | 02/20/1998 | 1 | AUSTIN SEMI. | | Y | MT5C6408C-35L | 620 |
| 5962-3829453MZA | G | 02/20/1998 | 1 | PYRAMID | | | P4C164L-35DMB | 620 |
| 5962-3829454MMA | G | 02/20/1998 | 1 | AUSTIN SEMI. | | Y | MT5C6408F-35 | 620 |
| 5962-3829454MMA | G | 02/20/1998 | 1 | PYRAMID | | | P4C164-35FSMB | 620 |
| 5962-3829454MTA | G | 02/20/1998 | 1 | PYRAMID | | | P4C164-35FMB | 620 |
| 5962-3829454MUA | G | 02/20/1998 | 1 | AUSTIN SEMI. | | Y | MT5C6408EC-35 | 620 |
| 5962-3829454MUA | G | 02/20/1998 | 1 | PYRAMID | | | P4C164-35LSMB | 620 |
| 5962-3829454MXA | G | 02/20/1998 | 1 | PYRAMID | | | P4C164-35DWMB | 620 |
| 5962-3829454MYA | G | 02/20/1998 | 1 | AUSTIN SEMI. | | Y | MT5C6408ECW-35 | 620 |
| 5962-3829454MYA | G | 02/20/1998 | 1 | PYRAMID | | | P4C164-35L32MB | 620 |
| 5962-3829454MZA | G | 02/20/1998 | 1 | AUSTIN SEMI. | | Y | MT5C6408C-35 | 620 |
| 5962-3829454MZA | G | 02/20/1998 | 1 | PYRAMID | | | P4C164-35DMB | 620 |
| 5962-3829455MMA | G | 02/20/1998 | 1 | AUSTIN SEMI. | | Y | MT5C6408F-25L | 620 |
| 5962-3829455MMA | G | 02/20/1998 | 1 | PYRAMID | | | P4C164L-25FSMB | 620 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-3829455MTA | G | 02/20/1998 | 1 | PYRAMID | | | P4C164L-25FMB | 620 |
| 5962-3829455MUA | G | 02/20/1998 | 1 | AUSTIN SEMI. | | Y | MT5C6408EC-25L | 620 |
| 5962-3829455MUA | G | 02/20/1998 | 1 | PYRAMID | | | P4C164L-25LSMB | 620 |
| 5962-3829455MXA | G | 02/20/1998 | 1 | PYRAMID | | | P4C164L-25DWMB | 620 |
| 5962-3829455MYA | G | 02/20/1998 | 1 | AUSTIN SEMI. | | Y | MT5C6408ECW-25L | 620 |
| 5962-3829455MYA | G | 02/20/1998 | 1 | PYRAMID | | | P4C164L-25L32MB | 620 |
| 5962-3829455MZA | G | 02/20/1998 | 1 | AUSTIN SEMI. | | Y | MT5C6408C-25L | 620 |
| 5962-3829455MZA | G | 02/20/1998 | 1 | PYRAMID | | | P4C164L-25DMB | 620 |
| 5962-3829456MMA | G | 02/20/1998 | 1 | AUSTIN SEMI. | | Y | MT5C6408F-25 | 620 |
| 5962-3829456MMA | G | 02/20/1998 | 1 | PYRAMID | | | P4C164-25FSMB | 620 |
| 5962-3829456MTA | G | 02/20/1998 | 1 | PYRAMID | | | P4C164-25FMB | 620 |
| 5962-3829456MUA | G | 02/20/1998 | 1 | AUSTIN SEMI. | | Y | MT5C6408EC-25 | 620 |
| 5962-3829456MUA | G | 02/20/1998 | 1 | PYRAMID | | | P4C164-25LSMB | 620 |
| 5962-3829456MXA | G | 02/20/1998 | 1 | PYRAMID | | | P4C164-25DWMB | 620 |
| 5962-3829456MYA | G | 02/20/1998 | 1 | AUSTIN SEMI. | | Y | MT5C6408ECW-25 | 620 |
| 5962-3829456MYA | G | 02/20/1998 | 1 | PYRAMID | | | P4C164-25L32MB | 620 |
| 5962-3829456MZA | G | 02/20/1998 | 1 | AUSTIN SEMI. | | Y | MT5C6408C-25 | 620 |
| 5962-3829456MZA | G | 02/20/1998 | 1 | PYRAMID | | | P4C164-25DMB | 620 |
| 5962-3829457MMA | G | 02/20/1998 | 1 | AUSTIN SEMI. | | Y | MT5C6408F-20L/883C | 620 |
| 5962-3829457MMA | G | 02/20/1998 | 1 | PYRAMID | | | P4C164L-20FSMB | 620 |
| 5962-3829457MTA | G | 02/20/1998 | 1 | PYRAMID | | | P4C164L-20FMB | 620 |
| 5962-3829457MUA | G | 02/20/1998 | 1 | AUSTIN SEMI. | | Y | MT5C6408EC-20L/883C | 620 |
| 5962-3829457MUA | G | 02/20/1998 | 1 | PYRAMID | | | P4C164L-20LSMB | 620 |
| 5962-3829457MXA | G | 02/20/1998 | 1 | PYRAMID | | | P4C164L-20DWMB | 620 |
| 5962-3829457MYA | G | 02/20/1998 | 1 | AUSTIN SEMI. | | Y | MT5C6408ECW-20L/88 | 620 |
| 5962-3829457MYA | G | 02/20/1998 | 1 | PYRAMID | | | P4C164L-20L32MB | 620 |
| 5962-3829457MZA | G | 02/20/1998 | 1 | AUSTIN SEMI. | | Y | MT5C6408C-20L/883C | 620 |
| 5962-3829457MZA | G | 02/20/1998 | 1 | PYRAMID | | | P4C164L-20DMB | 620 |
| 5962-3829458MMA | G | 02/20/1998 | 1 | AUSTIN SEMI. | | Y | MT5C6408F-20/883C | 620 |
| 5962-3829458MMA | G | 02/20/1998 | 1 | PYRAMID | | | P4C164-20FSMB | 620 |
| 5962-3829458MTA | G | 02/20/1998 | 1 | PYRAMID | | | P4C164-20FMB | 620 |
| 5962-3829458MUA | G | 02/20/1998 | 1 | AUSTIN SEMI. | | Y | MT5C6408EC-20/883C | 620 |
| 5962-3829458MUA | G | 02/20/1998 | 1 | PYRAMID | | | P4C164-20LSMB | 620 |
| 5962-3829458MXA | G | 02/20/1998 | 1 | PYRAMID | | | P4C164-20DWMB | 620 |
| 5962-3829458MYA | G | 02/20/1998 | 1 | AUSTIN SEMI. | | Y | MT5C6408ECW-20/883 | 620 |
| 5962-3829458MYA | G | 02/20/1998 | 1 | PYRAMID | | | P4C164-20L32MB | 620 |
| 5962-3829458MZA | G | 02/20/1998 | 1 | AUSTIN SEMI. | | Y | MT5C6408C-20/883C | 620 |
| 5962-3829458MZA | G | 02/20/1998 | 1 | PYRAMID | | | P4C164-20DMB | 620 |
| 5962-3829459MUA | G | 02/20/1998 | 1 | PYRAMID | | | P4C164-70LMB | 620 |
| 5962-3829460MUA | G | 02/20/1998 | 1 | PYRAMID | | | P4C164L-55LMB | 620 |
| 5962-3829461MUA | G | 02/20/1998 | 1 | PYRAMID | | | P4C164-55LMB | 620 |
| 5962-3829462MUA | G | 02/20/1998 | 1 | PYRAMID | | | P4C164L-45LMB | 620 |
| 5962-3829463MUA | G | 02/20/1998 | 1 | PYRAMID | | | P4C164-45LMB | 620 |
| 5962-3829464MUA | G | 02/20/1998 | 1 | PYRAMID | | | P4C164L-35LMB | 620 |
| 5962-3829465MUA | G | 02/20/1998 | 1 | PYRAMID | | | P4C164-35LMB | 620 |
| 5962-3829466MUA | G | 02/20/1998 | 1 | PYRAMID | | | P4C164L-25LMB | 620 |
| 5962-3829467MUA | G | 02/20/1998 | 1 | PYRAMID | | | P4C164-25LMB | 620 |
| 5962-3829468MUA | G | 02/20/1998 | 1 | PYRAMID | | | P4C164-20LMB | 620 |
| 5962-3848001MQA | | 06/17/1993 | | (NONE) | | | Z08400 (GEN) | 402 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-3848001MXA | | 06/17/1993 | | (NONE) | | | Z08400 (GEN) | 402 |
| 5962-3848001MYA | | 06/17/1993 | | (NONE) | | | Z08400 (GEN) | 402 |
| 5962-3848002MQA | | 06/17/1993 | | (NONE) | | | Z08400 (GEN) | 402 |
| 5962-3848002MXA | | 06/17/1993 | | (NONE) | | | Z08400 (GEN) | 402 |
| 5962-3848002MYA | | 06/17/1993 | | (NONE) | | | Z08400 (GEN) | 402 |
| 5962-3848003MQA | | 06/17/1993 | | (NONE) | | | Z08400 (GEN) | 402 |
| 5962-3848003MXA | | 06/17/1993 | | (NONE) | | | Z08400 (GEN) | 402 |
| 5962-3848003MYA | | 06/17/1993 | | (NONE) | | | Z08400 (GEN) | 402 |
| 5962-3870501M2A | D | 02/20/1998 | 1 | NATIONAL | | Y | LP2951E/883 | 789 |
| 5962-3870501S2A | D | 02/20/1998 | 1 | NATIONAL | | Y | LP2951E | 789 |
| 5962-3870501BGA | D | 02/20/1998 | | (NONE) | 03/09/1999 | | LP295 (GEN) | 789 |
| 5962-3870501MGA | D | 02/20/1998 | 1 | NATIONAL | | Y | LP2951H/883 | 789 |
| 5962-3870501SGA | D | 02/20/1998 | | (NONE) | 03/09/1999 | | LP2951 (GEN) | 789 |
| 5962-3870501BPA | D | 02/20/1998 | 1 | NATIONAL | | Y | LP2951J | 789 |
| 5962-3870501MPA | D | 02/20/1998 | 1 | NATIONAL | | Y | LP2951J/883 | 789 |
| 5962-3870501SPA | D | 02/20/1998 | 1 | NATIONAL | | Y | LP2951J | 789 |
| 5962-3870501MXA | D | 02/20/1998 | 1 | NATIONAL | | Y | LP2951WG/883 | 789 |
| 5962-3870701MGC | B | 02/27/2004 | 1 | MAXIM INTEG. | | | MAX1044MTV/883B | 594 |
| 5962-3870701MPA | B | 02/27/2004 | 1 | MAXIM INTEG. | | | MAX1044MJA/883B | 594 |
| 5962-3870702MGC | B | 02/27/2004 | 1 | MAXIM INTEG. | | | ICL7660AMTV/883B | 789 |
| 5962-3870702MPA | B | 02/27/2004 | 1 | MAXIM INTEG. | | | ICL7660AMJA/883B | 789 |
| 76002012A | G | 11/14/2002 | 1 | LANSDALE | | Y | SL54LS157/B2A | 275 |
| 76002012A | G | 11/14/2002 | I | TI | | Y | SNJ54LS157FK | 275 |
| 76002012C | G | 11/14/2002 | 1 | LANSDALE | | Y | SL54LS157/B2C | 275 |
| 7600201EA | G | 11/14/2002 | 1 | LANSDALE | | Y | SL54LS157/BEA | 275 |
| 7600201EA | G | 11/14/2002 | 1 | TI | | Y | SNJ54LS157J | 275 |
| 7600201FA | G | 11/14/2002 | 1 | LANSDALE | | Y | SL54LS157/BFA | 275 |
| 7600201FA | G | 11/14/2002 | I | TI | | Y | SNJ54LS157W | 275 |
| 76003012A | F | 04/27/1992 | | (NONE) | | | 54LS122 (GEN) | 165 |
| 7600301CA | F | 04/27/1992 | | (NONE) | 09/30/1995 | | 54LS122 (GEN) | 165 |
| 7600301DA | F | 04/27/1992 | | (NONE) | | | 54LS122 (GEN) | 165 |
| 7600401CA | G | 11/19/2002 | 1 | TI | | Y | SNJ54LS132J | 109 |
| 7600401DA | G | 11/19/2002 | 1 | TI | | Y | SNJ54LS132W | 109 |
| 76005012A | F | 11/19/2002 | 1 | LANSDALE | | Y | SL54LS138/B2A | 282 |
| 76005012A | F | 11/19/2002 | I | TI | | Y | SNJ54LS138FK | 282 |
| 76005012C | F | 11/19/2002 | 1 | LANSDALE | | Y | SL54LS138/B2C | 282 |
| 7600501EA | F | 11/19/2002 | 1 | LANSDALE | | Y | SL54LS138/BEA | 282 |
| 7600501EA | F | 11/19/2002 | I | TI | | Y | SN54LS138J | 282 |
| 7600501FA | F | 11/19/2002 | 1 | LANSDALE | | Y | SL54LS138/BFA | 282 |
| 7600501FA | F | 11/19/2002 | I | TI | | Y | SNJ54LS138W | 282 |
| 76006012A | J | 12/05/2002 | I | TI | | Y | SNJ54LS193FK | 304 |
| 7600601EA | J | 12/05/2002 | I | TI | | Y | SN54LS193J | 304 |
| 7600601FA | J | 12/05/2002 | I | TI | | Y | SN54LS193W | 304 |
| 76007012A | F | 12/09/2002 | | TI | | Y | SNJ54LS139AFK | 283 |
| 7600701EA | F | 12/09/2002 | 1 | LANSDALE | | Y | SL54LS139/BEA | 283 |
| 7600701EA | F | 12/09/2002 | | TI | | Y | SNJ54LS139AJ | 283 |
| 7600701FA | F | 12/09/2002 | 1 | LANSDALE | | Y | SL54LS139/BFA | 283 |
| 7600701FA | F | 12/09/2002 | | TI | | Y | SNJ54LS139AW | 283 |
| 76008012A | K | 01/20/2004 | 1 | LANSDALE | | Y | SL54LS161/B2A | 304 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 76008012A | K | 01/20/2004 | 3 | TI | | Y | SNJ54LS161AFK | 304 |
| 76008012C | K | 01/20/2004 | 1 | LANSDALE | | Y | SL54LS161/B2C | 304 |
| 5962-7600801VEA | K | 01/20/2004 | 3 | TI | | Y | SNV54LS161AJ | 304 |
| 7600801EA | K | 01/20/2004 | 1 | LANSDALE | | Y | SL54LS161/BEA | 304 |
| 7600801EA | K | 01/20/2004 | 3 | TI | | Y | SNJ54LS161AJ | 304 |
| 5962-7600801VFA | K | 01/20/2004 | 3 | TI | | Y | SNV54LS161AW | 304 |
| 7600801FA | K | 01/20/2004 | 1 | LANSDALE | | Y | SL54LS161/BFA | 304 |
| 7600801FA | K | 01/20/2004 | 3 | TI | | Y | SNJ54LS161AW | 304 |
| 76009012A | G | 01/07/2003 | I | TI | | Y | SNJ54LS191EK | 304 |
| 7600901EA | G | 01/07/2003 | I | TI | | Y | SNJ54LS191J | 304 |
| 7600901FA | G | 01/07/2003 | I | TI | | Y | SNJ54LS191W | 304 |
| 76010012A | F | 01/09/2003 | 1 | SARNOFF | | Y | GEM03701B2A | 271 |
| 76010012A | F | 01/09/2003 | I | TI | | Y | SNJ54LS151FK | 271 |
| 76010012C | F | 01/09/2003 | 1 | SARNOFF | | Y | GEM03701B2C | 271 |
| 7601001EA | F | 01/09/2003 | 1 | SARNOFF | | Y | GEM03701BEA | 271 |
| 7601001EA | F | 01/09/2003 | I | TI | | Y | SNJ54LS151J | 271 |
| 7601001EC | F | 01/09/2003 | 1 | SARNOFF | | Y | GEM03701BEC | 271 |
| 7601001FA | F | 01/09/2003 | 1 | SARNOFF | | Y | GEM03701BFA | 271 |
| 7601001FA | F | 01/09/2003 | I | TI | | Y | SNJ54LS151W | 271 |
| 7601001FC | F | 01/09/2003 | 1 | SARNOFF | | Y | GEM03701BFC | 271 |
| 76011012A | G | 01/21/2003 | 1 | LANSDALE | | Y | SL54LS153/B2A | 273 |
| 76011012A | G | 01/21/2003 | I | TI | | Y | SNJ54LS153FK | 273 |
| 76011012C | G | 01/21/2003 | 1 | LANSDALE | | Y | SL54LS153/B2C | 273 |
| 7601101EA | G | 01/21/2003 | 1 | LANSDALE | | Y | SL54LS153/BEA | 273 |
| 7601101EA | G | 01/21/2003 | I | TI | | Y | SNJ54LS153J | 273 |
| 7601101FA | G | 01/21/2003 | 1 | LANSDALE | | Y | SL54LS153/BFA | 273 |
| 7601101FA | G | 01/21/2003 | I | TI | | Y | SNJ54LS153W | 273 |
| 5962-7601201VEA | G | 01/20/2004 | 1 | TI | | Y | SNV54LS75J | 340 |
| 7601201EA | G | 01/20/2004 | 1 | LANSDALE | | Y | SL54LS75/BEA | 340 |
| 7601201EA | G | 01/20/2004 | 1 | TI | | Y | SNJ54LS75J | 340 |
| 5962-7601201VFA | G | 01/20/2004 | 1 | TI | | Y | SNV54LS75W | 340 |
| 7601201FA | G | 01/20/2004 | 1 | LANSDALE | | Y | SL54LS75/BFA | 340 |
| 7601201FA | G | 01/20/2004 | 1 | TI | | Y | SNJ54LS75W | 340 |
| 76013012A | H | 01/30/2003 | | TI | | Y | SNJ54LS76AFK | 156 |
| 7601301EA | H | 01/30/2003 | | TI | | Y | SNJ54LS76AJ | 156 |
| 7601301FA | H | 01/30/2003 | | TI | | Y | SNJ54ALS76AW | 156 |
| 7601401EA | F | 02/20/2003 | 1 | LANSDALE | | Y | SL54LS83A/BEA | 202 |
| 7601401FA | F | 02/20/2003 | 1 | LANSDALE | | Y | SL54LS83A/BFA | 202 |
| 7601501CA | B | 03/03/2003 | 1 | LANSDALE | | Y | SL54LS197/BCA | 303 |
| 7601501CA | B | 03/03/2003 | 1 | TI | 06/30/2004 | Y | SNJ54LS197J | 303 |
| 7601501DA | B | 03/03/2003 | 1 | LANSDALE | | Y | SL54LS197/BDA | 303 |
| 7601501DA | B | 03/03/2003 | 1 | TI | 06/30/2003 | Y | SNJ54LS197W | 303 |
| 7601601EA | H | 03/05/2003 | 1 | LANSDALE | | Y | SL54LS251/BEA | 272 |
| 7601601EA | H | 03/05/2003 | I | TI | | Y | SN54LS251J | 272 |
| 7601601FA | H | 03/05/2003 | 1 | LANSDALE | | Y | SL54LS251/BFA | 272 |
| 7601601FA | H | 03/05/2003 | I | TI | | Y | SN54LS251W | 272 |
| 76017012A | G | 03/12/2003 | 1 | TI | | Y | SNJ54LS253FK | 274 |
| 7601701EA | G | 03/12/2003 | 1 | LANSDALE | | Y | SL54LS253/BEA | 274 |
| 7601701EA | G | 03/12/2003 | 1 | TI | | Y | SNJ54LS253J | 274 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 7601701FA | G | 03/12/2003 | 1 | LANSDALE | | Y | SL54LS253/BFA | 274 |
| 7601701FA | G | 03/12/2003 | 1 | TI | | Y | SNJ54LS253W | 274 |
| 76018012A | G | 03/20/2003 | I | TI | | Y | SNJ54LS279AFK | 340 |
| 7601801EA | G | 03/20/2003 | I | TI | | Y | SNJ54LS279AJ | 340 |
| 7601801FA | G | 03/20/2003 | I | TI | | Y | SNJ54LS279AW | 340 |
| 7601901EA | G | 03/27/2003 | 1 | LANSDALE | | Y | SL54LS298/BEA | 275 |
| 7601901EA | G | 03/27/2003 | 1 | SARNOFF | | Y | GEM15201QEA | 275 |
| 7601901EA | G | 03/27/2003 | 1 | TI | | Y | SNJ54LS298J | 275 |
| 7601901EC | G | 03/27/2003 | 1 | SARNOFF | | Y | GEM15201QEC | 275 |
| 7601901FA | G | 03/27/2003 | 1 | LANSDALE | | Y | SL54LS298/BFA | 275 |
| 7601901FA | G | 03/27/2003 | 1 | SARNOFF | | Y | GEM15201QFA | 275 |
| 7601901FA | G | 03/27/2003 | 1 | TI | | Y | SNJ54LS298W | 275 |
| 7601901FC | G | 03/27/2003 | 1 | SARNOFF | | Y | GEM15201QFC | 275 |
| 5962-7602001VCA | G | 01/20/2004 | 1 | TI | | Y | SNV54LS26J | 510 |
| 7602001CA | G | 01/20/2004 | 1 | LANSDALE | | Y | SL54LS26/BCA | 510 |
| 7602001CA | G | 01/20/2004 | 1 | TI | | Y | SNJ54LS26J | 510 |
| 5962-7602001VDA | G | 01/20/2004 | 1 | TI | | Y | SNV54LS26W | 510 |
| 7602001DA | G | 01/20/2004 | 1 | LANSDALE | | Y | SL54LS26/BDA | 510 |
| 7602001DA | G | 01/20/2004 | 1 | TI | | Y | SNJ54LS26W | 510 |
| 76031012A | C | 09/25/1987 | | (NONE) | 09/15/1995 | | 54LS42 (GEN) | 281 |
| 7603101EA | C | 09/25/1987 | | (NONE) | 09/30/1995 | | 54LS42 (GEN) | 281 |
| 7603101FA | C | 09/25/1987 | | (NONE) | 09/15/1995 | | 54LS42 (GEN) | 281 |
| 76032012A | D | 04/07/2003 | | (NONE) | | | 54LS90 (GEN) | 300 |
| 7603201AA | D | 04/07/2003 | | (NONE) | | | 54LS90 (GEN) | 300 |
| 7603201BA | D | 04/07/2003 | | (NONE) | | | 54LS90 (GEN) | 300 |
| 7603201CA | D | 04/07/2003 | I | TI | | Y | SNJ54LS90J | 300 |
| 7603201DA | D | 04/07/2003 | I | TI | | Y | SNJ54LS90W | 300 |
| 76033012A | D | 05/06/2003 | 1 | LANSDALE | | Y | SL54LS158/B2A | 275 |
| 76033012A | D | 05/06/2003 | I | TI | | Y | SNJ54LS158FK | 275 |
| 76033012C | D | 05/06/2003 | 1 | LANSDALE | | Y | SL54LS158/B2C | 275 |
| 7603301EA | D | 05/06/2003 | 1 | LANSDALE | | Y | SL54LS158/BEA | 275 |
| 7603301EA | D | 05/06/2003 | I | TI | | Y | SNJ54LS158J | 275 |
| 7603301FA | D | 05/06/2003 | 1 | LANSDALE | | Y | SL54LS158/BFA | 275 |
| 7603301FA | D | 05/06/2003 | I | TI | | Y | SNJ54LS158W | 275 |
| 76034012A | E | 06/20/2003 | 1 | LANSDALE | | Y | SL54LS163A/B2A | 304 |
| 76034012C | E | 06/20/2003 | 1 | LANSDALE | | Y | SL54LS163A/B2C | 304 |
| 7603401EA | E | 06/20/2003 | 1 | LANSDALE | | Y | SL54LS163A/BEA | 304 |
| 7603401EA | E | 06/20/2003 | I | TI | | Y | SNJ54LS163AJ | 304 |
| 7603401FA | E | 06/20/2003 | 1 | LANSDALE | | Y | SL54LS163A/BFA | 304 |
| 7603401FA | E | 06/20/2003 | I | TI | | Y | SNJ54LS163AW | 304 |
| 76035012A | C | 10/19/1987 | | (NONE) | 09/15/1995 | | 54LS190 (GEN) | 304 |
| 7603501EA | C | 10/19/1987 | | (NONE) | 09/15/1995 | | 54LS190 (GEN) | 304 |
| 7603501FA | C | 10/19/1987 | | (NONE) | 09/15/1995 | | 54LS190 (GEN) | 304 |
| 76036012A | D | 05/09/2003 | 1 | SARNOFF | | Y | GEM051012A | 301 |
| 76036012C | D | 05/09/2003 | 1 | SARNOFF | | Y | GEM051012C | 301 |
| 7603601EA | D | 05/09/2003 | 1 | SARNOFF | | Y | GEM05101EA | 301 |
| 7603601EC | D | 05/09/2003 | 1 | SARNOFF | | Y | GEM05101EC | 301 |
| 7603601FA | D | 05/09/2003 | 2 | SARNOFF | | Y | GEM05101FX | 301 |
| 7603601FC | D | 05/09/2003 | 2 | SARNOFF | | Y | GEM05101FX | 301 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-7603701VEA | F | 11/13/2003 | 3 | TI | | Y | SNV54LS257BJ | 276 |
| 7603701EA | F | 11/13/2003 | 3 | TI | | Y | SNJ54LS257BJ | 276 |
| 5962-7603701VFA | F | 11/13/2003 | 3 | TI | | Y | SNV54LS257BW | 276 |
| 7603701FA | F | 11/13/2003 | 3 | TI | | Y | SNJ54LS257BW | 276 |
| 76038012A | D | 06/06/2003 | I | TI | | Y | SNJ54LS258BFK | 276 |
| 7603801EA | D | 06/06/2003 | | TI | | Y | SNJ54LS258BJ | 276 |
| 7603801FA | D | 06/06/2003 | I | TI | | Y | SNJ54LS258BW | 276 |
| 5962-7603901VEA | F | 11/06/2003 | 1 | TI | | Y | SNV54LS123J | 166 |
| 7603901EA | F | 11/06/2003 | 1 | TI | | Y | SNJ54LS123J | 166 |
| 5962-7603901VFA | F | 11/06/2003 | 1 | TI | | Y | SNV54LS123W | 166 |
| 7603901FA | F | 11/06/2003 | 1 | TI | | Y | SNJ54LS123W | 166 |
| 7604001EA | E | 09/08/2003 | 1 | LANSDALE | | Y | SL54S194/BEA | 220 |
| 7604001EA | E | 09/08/2003 | 1 | TI | | Y | SNJ54S194J | 220 |
| 7604001FA | E | 09/08/2003 | 1 | LANSDALE | | Y | SL54S194/BFA | 220 |
| 7604001FA | E | 09/08/2003 | 1 | TI | | Y | SNJ54S194W | 220 |
| 76041012A | G | 07/14/2003 | 0 | TI | | Y | SNJ54S138FK | 282 |
| 7604101EA | G | 07/14/2003 | I | TI | | Y | SNJ54S138J | 282 |
| 7604101FA | G | 07/14/2003 | I | TI | | Y | SNJ54S138W | 282 |
| 76042012A | F | 08/14/2003 | 1 | TI | | Y | SNJ54LS221FK | 166 |
| 7604201EA | F | 08/14/2003 | 1 | TI | | Y | SNJ54LS221J | 166 |
| 7604201FA | F | 08/14/2003 | 1 | TI | | Y | SNJ54LS221W | 166 |
| 76043012A | D | 05/13/2004 | 1 | LANSDALE | | Y | SL54LS283/B2A | 202 |
| 76043012A | D | 05/13/2004 | I | TI | | Y | SNJ54LS283FK | 202 |
| 76043012C | D | 05/13/2004 | 1 | LANSDALE | | Y | SL54LS283/B2C | 202 |
| 7604301EA | D | 05/13/2004 | 1 | LANSDALE | | Y | SL54LS283/BEA | 202 |
| 7604301EA | D | 05/13/2004 | I | TI | | Y | SNJ54LS283J | 202 |
| 7604301FA | D | 05/13/2004 | 1 | LANSDALE | | Y | SL54LS283/BFA | 202 |
| 7604301FA | D | 05/13/2004 | I | TI | | Y | SNJ54LS283W | 202 |
| 7604501EA | D | 08/20/2003 | 1 | TI | | Y | SNJ54LS47J | 291 |
| 7604501FA | D | 08/20/2003 | 1 | TI | | Y | SNJ54LS47W | 291 |
| 7700101AA | F | 08/26/2003 | 1 | LANSDALE | | Y | SL54LS93/BAA | 303 |
| 7700101CA | F | 08/26/2003 | 1 | LANSDALE | | Y | SL54LS93/BCA | 303 |
| 7700101DA | F | 08/26/2003 | 1 | LANSDALE | | Y | SL54LS93/BDA | 303 |
| 7700201QX | B | 01/25/1978 | | (NONE) | | | 8080A (GEN) | 402 |
| 7700401EA | E | 05/13/2004 | 2 | SARNOFF | | Y | GEM08501QEA | 283 |
| 7700401EA | E | 05/13/2004 | I | TI | | Y | SNJ54S139J | 283 |
| 7700401EC | E | 05/13/2004 | 2 | SARNOFF | | Y | GEM08501QEC | 283 |
| 7700401FA | E | 05/13/2004 | 2 | SARNOFF | | Y | GEM08501QFA | 283 |
| 7700401FA | E | 05/13/2004 | I | TI | | Y | SNJ54S139W | 283 |
| 7700401FC | E | 05/13/2004 | 2 | SARNOFF | | Y | GEM08501QFC | 283 |
| 5962-7700601VEA | E | 02/21/1992 | 1 | TI | | Y | SNV54LS165AJ | 225 |
| 7700601EA | E | 02/21/1992 | 1 | TI | | Y | SNJ54LS165AJ | 225 |
| 5962-7700601VFA | E | 02/21/1992 | 1 | TI | | Y | SNV54LS165AW | 225 |
| 7700601FA | E | 02/21/1992 | 1 | TI | | Y | SNJ54LS165AW | 225 |
| 7700701QA | E | 08/25/1988 | | (NONE) | 08/31/1995 | | 2901A (GEN) | 400 |
| 7700701ZA | E | 08/25/1988 | | (NONE) | | | 2901A (GEN) | 400 |
| 7700702QA | E | 08/25/1988 | | (NONE) | | | 2901 (GEN) | 400 |
| 7700703QA | E | 08/25/1988 | 2 | SARNOFF | | Y | GEM06803QQA | 400 |
| 7700703QC | E | 08/25/1988 | 2 | SARNOFF | | Y | GEM06803QQC | 400 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 7700703ZA | E | 08/25/1988 | 2 | SARNOFF | | Y | GEM06803QZA | 400 |
| 7700703ZC | E | 08/25/1988 | 2 | SARNOFF | | Y | GEM06803QZC | 400 |
| 77008012A | F | 04/22/2003 | 1 | TI | | Y | LM139FKB | 776 |
| 7700801AA | F | 04/22/2003 | | (NONE) | | | LM139 (GEN) | 776 |
| 5962-7700801VCA | F | 04/22/2003 | 1 | TI | | Y | LM139JQMLV | 776 |
| 7700801CA | F | 04/22/2003 | 1 | TI | | Y | LM139JB | 776 |
| 7700801DA | F | 04/22/2003 | 1 | TI | | Y | LM139WB | 776 |
| 7700901EA | D | 04/07/2004 | 1 | LANSDALE | | Y | SL54LS160A/BEA | 301 |
| 7700901FA | D | 04/07/2004 | 1 | LANSDALE | | Y | SL54LS160A/BFA | 301 |
| 77010012A | F | 04/14/2004 | | (NONE) | | | 54LS196 (GEN) | 300 |
| 7701001CA | F | 04/14/2004 | 1 | SARNOFF | | Y | GEM31001QCA | 300 |
| 7701001CC | F | 04/14/2004 | 1 | SARNOFF | | Y | GEM31001QCC | 300 |
| 7701001DA | F | 04/14/2004 | 1 | SARNOFF | | Y | GEM31001QDA | 300 |
| 7701001DC | F | 04/14/2004 | 1 | SARNOFF | | Y | GEM31001QDC | 300 |
| 7702001EA | D | 01/24/2001 | | (NONE) | 09/30/1995 | | 4502B (GEN) | 541 |
| 7702001FA | D | 01/24/2001 | | (NONE) | | | 4502B (GEN) | 541 |
| 7702002EA | D | 01/24/2001 | 2 | TI | | Y | CD4502BF3A | 541 |
| 7702301EA | E | 03/07/2001 | 1 | TI | | Y | CD4520BF3A | 304 |
| 7702301FA | E | 03/07/2001 | | (NONE) | | | 4520B (GEN) | 304 |
| 7702401CA | E | 02/23/2001 | | (NONE) | 09/30/1995 | | 4081B (GEN) | 110 |
| 7702401DA | E | 02/23/2001 | | (NONE) | | | 4081B (GEN) | 110 |
| 7702402CA | E | 02/23/2001 | 1 | TI | | Y | CD4081BF3A | 110 |
| 7702501EA | H | 04/13/2001 | 1 | TI | | Y | CD4094BF3A | 249 |
| 7702501FA | H | 04/13/2001 | | (NONE) | | | 4094B (GEN) | 249 |
| 7702502EA | H | 04/13/2001 | | (NONE) | | | 4094B (GEN) | 249 |
| 7702601EA | B | 09/05/1984 | | (NONE) | | | 4044B (GEN) | 340 |
| 7702601FA | B | 09/05/1984 | | (NONE) | | | 4044B (GEN) | 340 |
| 7702701CX | C | 07/20/1982 | | (NONE) | | | 4069UB (GEN) | 143 |
| 7702701DX | C | 07/20/1982 | | (NONE) | | | 4069UB (GEN) | 143 |
| 7702801XA | F | 12/16/2003 | 0 | MICROSEMI | | Y | SG103Z-1.8 | 785 |
| 7702802XA | F | 12/16/2003 | | (NONE) | | | LM103H-2.0 (GEN) | 785 |
| 7702803XA | F | 12/16/2003 | | (NONE) | | | LM103H-2.2 (GEN) | 785 |
| 7702804XA | F | 12/16/2003 | | (NONE) | | | LM103H-2.4 (GEN) | 785 |
| 7702805XA | F | 12/16/2003 | 0 | MICROSEMI | | Y | SG103Z-2.7 | 785 |
| 7702806XA | F | 12/16/2003 | | (NONE) | 03/08/2000 | | LM103H-3.0 (GEN) | 785 |
| 7702807XA | F | 12/16/2003 | | (NONE) | 09/09/1999 | | LM103-3.3 (GEN) | 785 |
| 7702808XA | F | 12/16/2003 | | (NONE) | | | LM103H-3.6 (GEN) | 785 |
| 7702809XA | F | 12/16/2003 | | (NONE) | 09/06/2000 | | LM103H-3.9 (GEN) | 785 |
| 7702810XA | F | 12/16/2003 | | (NONE) | | | LM103H-4.3 (GEN) | 785 |
| 7702811XA | F | 12/16/2003 | 0 | MICROSEMI | | Y | SG103Z-4.7 | 785 |
| 7702812XA | F | 12/16/2003 | | (NONE) | | | LM103H-5.1 (GEN) | 785 |
| 7702813XA | F | 12/16/2003 | | (NONE) | | | LM103H-5.6 (GEN) | 785 |
| 77030012A | B | 10/04/1984 | | (NONE) | | | 54185A (GEN) | 262 |
| 7703001EA | B | 10/04/1984 | | (NONE) | | | 54185A (GEN) | 262 |
| 7703001FA | B | 10/04/1984 | | (NONE) | | | 54185A (GEN) | 262 |
| 7703101EA | A | 04/12/1979 | | (NONE) | | | 4060A (GEN) | 305 |
| 7703101FA | A | 04/12/1979 | | (NONE) | | | 4060A (GEN) | 305 |
| 7703201JA | F | 03/02/2001 | 1 | TI | | Y | CD4515BF3A | 280 |
| 7703201ZA | F | 03/02/2001 | | (NONE) | | | 4515B (GEN) | 280 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 7703301GA | C | 07/10/1996 | | (NONE) | | | CA3130 (GEN) | 723 |
| 77034012A | V | 12/10/2003 | 3 | INTER. RECT. | | | OM1320N2/883B | 780 |
| 77034012A | V | 12/10/2003 | 3 | MICROSEMI | | Y | SG117L/883B | 780 |
| 77034012A | V | 12/10/2003 | 1 | SOLITRON | | | SDP1172MD | 780 |
| 77034015A | V | 12/10/2003 | 1 | SEMELAB | | Y | IP117E | 780 |
| 7703401MA | V | 12/10/2003 | 1 | INTER. RECT. | | | OM117SM/883B | 780 |
| 7703401MA | V | 12/10/2003 | 1 | SOLITRON | | | SDP117MMD | 780 |
| 7703401NA | V | 12/10/2003 | 3 | INTER. RECT. | | | OM1320NM/883B | 780 |
| 7703401NA | V | 12/10/2003 | 1 | SOLITRON | | | SDP117NMD | 780 |
| 7703401TA | V | 12/10/2003 | 0 | INTER. RECT. | | | OM117NT/883B | 780 |
| 7703401TA | V | 12/10/2003 | 1 | SEMELAB | | Y | IP117G-DESC | 780 |
| 7703401TA | V | 12/10/2003 | 1 | SOLITRON | | | SDP117TMD | 780 |
| 7703401UA | V | 12/10/2003 | 0 | INTER. RECT. | | | OM117ST/883B | 780 |
| 7703401UA | V | 12/10/2003 | 2 | MICROSEMI | | Y | SG117IG/883B | 780 |
| 7703401UA | V | 12/10/2003 | 1 | SEMELAB | | Y | IP117IG-DESC | 780 |
| 7703401UA | V | 12/10/2003 | 1 | SOLITRON | | | SDP117UMD | 780 |
| 7703401XA | V | 12/10/2003 | 3 | MICROSEMI | | Y | SG117T/883B | 780 |
| 7703401XA | V | 12/10/2003 | 1 | SEMELAB | | Y | IP117MH-DESC | 780 |
| 7703401XA | V | 12/10/2003 | 1 | SOLITRON | | | SDP117XMD | 780 |
| 7703401YA | V | 12/10/2003 | 3 | INTER. RECT. | | | OM1320NK/883B | 780 |
| 7703401YA | V | 12/10/2003 | 3 | MICROSEMI | | Y | SG117K/883B | 780 |
| 7703401YA | V | 12/10/2003 | 1 | SEMELAB | | Y | IP117K-DESC | 780 |
| 7703401YA | V | 12/10/2003 | 1 | SOLITRON | | | SDP117YMD | 780 |
| 7703401ZA | V | 12/10/2003 | 3 | MICROSEMI | | Y | SG117R/883B | 780 |
| 7703401ZA | V | 12/10/2003 | 1 | SEMELAB | | Y | IP117R-DESC | 780 |
| 77034022A | V | 12/10/2003 | 3 | INTER. RECT. | | | OM1321N2/883B | 780 |
| 77034022A | V | 12/10/2003 | 1 | SOLITRON | | | SDP117HV2MD | 780 |
| 77034025A | V | 12/10/2003 | 1 | SEMELAB | | Y | IP117HVE | 780 |
| 7703402MA | V | 12/10/2003 | 1 | INTER. RECT. | | | OM117HVSM/883B | 780 |
| 7703402MA | V | 12/10/2003 | 1 | SOLITRON | | | SDP117HVMMD | 780 |
| 7703402NA | V | 12/10/2003 | 3 | INTER. RECT. | | | OM1321NM/883B | 780 |
| 7703402NA | V | 12/10/2003 | 1 | SOLITRON | | | SDP117HVNMD | 780 |
| 7703402TA | V | 12/10/2003 | 0 | INTER. RECT. | | | OM117HVNT/883B | 780 |
| 7703402TA | V | 12/10/2003 | 1 | SEMELAB | | Y | IP117HVG-DESC | 780 |
| 7703402TA | V | 12/10/2003 | 1 | SOLITRON | | | SDP117HVTMD | 780 |
| 5962R7703402MUA | V | 12/10/2003 | 1 | INTER. RECT. | | | OMR1321STM/883B | 780 |
| 7703402UA | V | 12/10/2003 | 0 | INTER. RECT. | | | OM117HVST/883B | 780 |
| 7703402UA | V | 12/10/2003 | 1 | SEMELAB | | Y | IP117HVIG-DESC | 780 |
| 7703402UA | V | 12/10/2003 | 1 | SOLITRON | | | SDP117HVUMD | 780 |
| 7703402XA | V | 12/10/2003 | 3 | INTER. RECT. | | | OM1321NH/883B | 780 |
| 7703402XA | V | 12/10/2003 | 1 | SEMELAB | | Y | IP117MHVH-DESC | 780 |
| 7703402XA | V | 12/10/2003 | 1 | SOLITRON | | | SDP117HVXMD | 780 |
| 7703402YA | V | 12/10/2003 | 3 | INTER. RECT. | | | OM1321NK/883B | 780 |
| 7703402YA | V | 12/10/2003 | 1 | SEMELAB | | Y | IP117HVK-DESC | 780 |
| 7703402YA | V | 12/10/2003 | 1 | SOLITRON | | | SDP117HVYMD | 780 |
| 7703402ZA | V | 12/10/2003 | 1 | SEMELAB | | Y | IP117HVR-DESC | 780 |
| 77034032A | V | 12/10/2003 | 3 | INTER. RECT. | | | OM1322N2/883B | 781 |
| 77034032A | V | 12/10/2003 | 3 | MICROSEMI | | Y | SG137L/883B | 781 |
| 77034032A | V | 12/10/2003 | 1 | SOLITRON | | | SDP1372MD | 781 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 77034036A | V | 12/10/2003 | 1 | SEMELAB | | Y | IP137E | 781 |
| 7703403MA | V | 12/10/2003 | 1 | INTER. RECT. | | | OM137SM/883B | 781 |
| 7703403MA | V | 12/10/2003 | 1 | SOLITRON | | | SDP137MMD | 781 |
| 7703403NA | V | 12/10/2003 | 3 | INTER. RECT. | | | OM1322NM/883B | 781 |
| 7703403NA | V | 12/10/2003 | 1 | SOLITRON | | | SDP137NMD | 781 |
| 7703403TA | V | 12/10/2003 | 0 | INTER. RECT. | | | OM137NT/883B | 781 |
| 7703403TA | V | 12/10/2003 | 1 | SEMELAB | | Y | IP137G-DESC | 781 |
| 7703403TA | V | 12/10/2003 | 1 | SOLITRON | | | SDP137TMD | 781 |
| 7703403UA | V | 12/10/2003 | 0 | INTER. RECT. | | | OM137ST/883B | 781 |
| 7703403UA | V | 12/10/2003 | 1 | SEMELAB | | Y | IP137IG-DESC | 781 |
| 7703403UA | V | 12/10/2003 | 1 | SOLITRON | | | SDP137UMD | 781 |
| 7703403XA | V | 12/10/2003 | I | MICROSEMI | | Y | SG137T/883B | 781 |
| 7703403XA | V | 12/10/2003 | 3 | NATIONAL | | Y | LM137H/883B | 781 |
| 7703403XA | V | 12/10/2003 | 1 | SEMELAB | | Y | IP137MH-DESC | 781 |
| 7703403XA | V | 12/10/2003 | 1 | SOLITRON | | | SDP137XMD | 781 |
| 7703403YA | V | 12/10/2003 | 3 | INTER. RECT. | | | OM1322NK/883B | 781 |
| 7703403YA | V | 12/10/2003 | 3 | NATIONAL | | Y | LM137K/883B | 781 |
| 7703403YA | V | 12/10/2003 | 1 | SEMELAB | | Y | IP137K-DESC | 781 |
| 7703403YA | V | 12/10/2003 | 1 | SOLITRON | | | SDP137YMD | 781 |
| 7703403ZA | V | 12/10/2003 | 1 | SEMELAB | | Y | IP137R-DESC | 781 |
| 77034042A | V | 12/10/2003 | 3 | INTER. RECT. | | | OM1323N2/883B | 781 |
| 77034042A | V | 12/10/2003 | 1 | SOLITRON | | | SDP137HV2MD | 781 |
| 77034046A | V | 12/10/2003 | 1 | SEMELAB | | Y | IP137HVE | 781 |
| 7703404MA | V | 12/10/2003 | 1 | INTER. RECT. | | | OM137HVSM/883B | 781 |
| 7703404MA | V | 12/10/2003 | 1 | SOLITRON | | | SDP137HVMMD | 781 |
| 7703404NA | V | 12/10/2003 | 3 | INTER. RECT. | | | OM1323NM/883B | 781 |
| 7703404NA | V | 12/10/2003 | 1 | SOLITRON | | | SDP137HVNMD | 781 |
| 7703404TA | V | 12/10/2003 | 0 | INTER. RECT. | | | OM137HVNT/883B | 781 |
| 7703404TA | V | 12/10/2003 | 1 | SEMELAB | | Y | IP137HVG-DESC | 781 |
| 7703404TA | V | 12/10/2003 | 1 | SOLITRON | | | SDP137HVTMD | 781 |
| 7703404UA | V | 12/10/2003 | 0 | INTER. RECT. | | | OM137HVST/883B | 781 |
| 7703404UA | V | 12/10/2003 | 1 | SEMELAB | | Y | IP137HVIG-DESC | 781 |
| 7703404UA | V | 12/10/2003 | 1 | SOLITRON | | | SDP137HVUMD | 781 |
| 5962-7703404VXA | V | 12/10/2003 | | (NONE) | | | LM137HV (GEN) | 781 |
| 7703404XA | V | 12/10/2003 | 3 | NATIONAL | | Y | LM137HVH/883 | 781 |
| 7703404XA | V | 12/10/2003 | 1 | SEMELAB | | Y | IP137HVH-DESC | 781 |
| 7703404XA | V | 12/10/2003 | 1 | SOLITRON | | | SDP137HVXMD | 781 |
| 5962-7703404VYA | V | 12/10/2003 | 3 | NATIONAL | | Y | LM137HVK-QMLV | 781 |
| 7703404YA | V | 12/10/2003 | 3 | INTER. RECT. | | | OM1323NK/883B | 781 |
| 7703404YA | V | 12/10/2003 | 3 | NATIONAL | | Y | LM137HVK/883 | 781 |
| 7703404YA | V | 12/10/2003 | 1 | SEMELAB | | Y | IP137HVK-DESC | 781 |
| 7703404YA | V | 12/10/2003 | 1 | SOLITRON | | | SDP137HVYMD | 781 |
| 7703404ZA | V | 12/10/2003 | 1 | SEMELAB | | Y | IP137HVR-DESC | 781 |
| 77034052A | V | 12/10/2003 | 3 | INTER. RECT. | | | OM1324N2/883B | 780 |
| 77034052A | V | 12/10/2003 | 3 | MICROSEMI | | Y | SG117AL/883B | 780 |
| 77034052A | V | 12/10/2003 | 1 | SOLITRON | | | SDP117A2MD | 780 |
| 77034055A | V | 12/10/2003 | 1 | SEMELAB | | Y | IP117AE | 780 |
| 7703405MA | V | 12/10/2003 | 1 | INTER. RECT. | | | OM117ASM/883B | 780 |
| 7703405MA | V | 12/10/2003 | 1 | SOLITRON | | | SDP117AMMD | 780 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 7703405NA | V | 12/10/2003 | 3 | INTER. RECT. | | | OM1324NM/883B | 780 |
| 7703405NA | V | 12/10/2003 | 1 | SOLITRON | | | SDP117ANMD | 780 |
| 7703405TA | V | 12/10/2003 | 0 | INTER. RECT. | | | OM117ANT/883B | 780 |
| 7703405TA | V | 12/10/2003 | 1 | SEMELAB | | Y | IP117AG-DESC | 780 |
| 7703405TA | V | 12/10/2003 | 1 | SOLITRON | | | SDP117ATMD | 780 |
| 7703405UA | V | 12/10/2003 | 0 | INTER. RECT. | | | OM117AST/883B | 780 |
| 7703405UA | V | 12/10/2003 | 3 | MICROSEMI | | Y | SG117AIG/883B | 780 |
| 7703405UA | V | 12/10/2003 | 1 | SEMELAB | | Y | IP117AIG-DESC | 780 |
| 7703405UA | V | 12/10/2003 | 1 | SOLITRON | | | SDP117AUMD | 780 |
| 7703405XA | V | 12/10/2003 | 3 | MICROSEMI | | Y | SG117AT/883B | 780 |
| 7703405XA | V | 12/10/2003 | 1 | SEMELAB | | Y | IP117MAH-DESC | 780 |
| 7703405XA | V | 12/10/2003 | 1 | SOLITRON | | | SDP117AXMD | 780 |
| 7703405YA | V | 12/10/2003 | 3 | INTER. RECT. | | | OM1324NK/883B | 780 |
| 7703405YA | V | 12/10/2003 | 3 | MICROSEMI | | Y | SG117AK/883B | 780 |
| 7703405YA | V | 12/10/2003 | 1 | SEMELAB | | Y | IP117AK-DESC | 780 |
| 7703405YA | V | 12/10/2003 | 1 | SOLITRON | | | SDP117AYMD | 780 |
| 7703405ZA | V | 12/10/2003 | 3 | MICROSEMI | | Y | SG117AR/883B | 780 |
| 7703405ZA | V | 12/10/2003 | 1 | SEMELAB | | Y | IP117AR-DESC | 780 |
| 77034062A | V | 12/10/2003 | 3 | INTER. RECT. | | | OM1325N2/883B | 781 |
| 77034062A | V | 12/10/2003 | 3 | MICROSEMI | | Y | SG137AL/883B | 781 |
| 77034062A | V | 12/10/2003 | 1 | SOLITRON | | | SDP137A2MD | 781 |
| 77034066A | V | 12/10/2003 | 1 | SEMELAB | | Y | IP137AE | 781 |
| 7703406MA | V | 12/10/2003 | 1 | INTER. RECT. | | | OM137ASM/883B | 781 |
| 7703406MA | V | 12/10/2003 | 1 | SOLITRON | | | SDP137AMMD | 781 |
| 7703406NA | V | 12/10/2003 | 3 | INTER. RECT. | | | OM1325NM/883B | 781 |
| 7703406NA | V | 12/10/2003 | 1 | SOLITRON | | | SDP137ANMD | 781 |
| 7703406TA | V | 12/10/2003 | 0 | INTER. RECT. | | | OM137ANT/883B | 781 |
| 7703406TA | V | 12/10/2003 | 1 | SEMELAB | | Y | IP137AG-DESC | 781 |
| 7703406TA | V | 12/10/2003 | 1 | SOLITRON | | | SDP137ATMD | 781 |
| 7703406UA | V | 12/10/2003 | 0 | INTER. RECT. | | | OM137AST/883B | 781 |
| 7703406UA | V | 12/10/2003 | 1 | SEMELAB | | Y | IP137AIG-DESC | 781 |
| 7703406UA | V | 12/10/2003 | 1 | SOLITRON | | | SDP137AUMD | 781 |
| 7703406XA | V | 12/10/2003 | 3 | MICROSEMI | | Y | SG137AT/883B | 781 |
| 7703406XA | V | 12/10/2003 | 1 | SEMELAB | | Y | IP137AH-DESC | 781 |
| 7703406XA | V | 12/10/2003 | 1 | SOLITRON | | | SDP137AXMD | 781 |
| 7703406YA | V | 12/10/2003 | 3 | INTER. RECT. | | | OM1325NK/883B | 781 |
| 7703406YA | V | 12/10/2003 | 1 | SEMELAB | | Y | IP137AK-DESC | 781 |
| 7703406YA | V | 12/10/2003 | 1 | SOLITRON | | | SDP137AYMD | 781 |
| 7703406ZA | V | 12/10/2003 | 1 | SEMELAB | | Y | IP137AR-DESC | 781 |
| 77034072A | V | 12/10/2003 | 3 | INTER. RECT. | | | OM1326N2/883B | 780 |
| 77034072A | V | 12/10/2003 | 1 | SOLITRON | | | SDP117AHV2MD | 780 |
| 77034074A | V | 12/10/2003 | 1 | INTER. RECT. | | | OM1326SRM/883B | 780 |
| 77034075A | V | 12/10/2003 | 1 | SEMELAB | | Y | IP117AHVE | 780 |
| 7703407MA | V | 12/10/2003 | 1 | INTER. RECT. | | | OM117AHVSM/883B | 780 |
| 7703407MA | V | 12/10/2003 | 1 | SOLITRON | | | SDP117AHVMMD | 780 |
| 7703407NA | V | 12/10/2003 | 3 | INTER. RECT. | | | OM1326NM/883B | 780 |
| 7703407NA | V | 12/10/2003 | 1 | SOLITRON | | | SDP117AHVNMD | 780 |
| 7703407TA | V | 12/10/2003 | 0 | INTER. RECT. | | | OM117AHVNT/883B | 780 |
| 7703407TA | V | 12/10/2003 | 1 | SEMELAB | | Y | IP117AHVG-DESC | 780 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 7703407TA | V | 12/10/2003 | 1 | SOLITRON | | | SDP117AHVTMD | 780 |
| 5962R7703407MUA | V | 12/10/2003 | 1 | INTER. RECT. | | | OMR1326STM/883B | 780 |
| 7703407UA | V | 12/10/2003 | 0 | INTER. RECT. | | | OM117AHVST/883B | 780 |
| 7703407UA | V | 12/10/2003 | 1 | SEMELAB | | Y | IP117AHVIG-DESC | 780 |
| 7703407UA | V | 12/10/2003 | 1 | SOLITRON | | | SDP117AHVUMD | 780 |
| 7703407XA | V | 12/10/2003 | 3 | INTER. RECT. | | | OM1326NH/883B | 780 |
| 7703407XA | V | 12/10/2003 | 1 | SEMELAB | | Y | IP117MAHVH-DESC | 780 |
| 7703407XA | V | 12/10/2003 | 1 | SOLITRON | | | SDP117AHVXMD | 780 |
| 7703407YA | V | 12/10/2003 | 3 | INTER. RECT. | | | OM1326NK/883B | 780 |
| 7703407YA | V | 12/10/2003 | 1 | SEMELAB | | Y | IP117AHVK-DESC | 780 |
| 7703407YA | V | 12/10/2003 | 1 | SOLITRON | | | SDP117AHVYMD | 780 |
| 7703407ZA | V | 12/10/2003 | 1 | SEMELAB | | Y | IP117AHVR-DESC | 780 |
| 77034082A | V | 12/10/2003 | 3 | INTER. RECT. | | | OM1327N2/883B | 781 |
| 77034082A | V | 12/10/2003 | 1 | SOLITRON | | | SDP137AHV2MD | 781 |
| 77034086A | V | 12/10/2003 | 1 | SEMELAB | | Y | IP137AHVE | 781 |
| 7703408MA | V | 12/10/2003 | 1 | INTER. RECT. | | | OM137AHVSM/883B | 781 |
| 7703408MA | V | 12/10/2003 | 1 | SOLITRON | | | SDP137AHVMMD | 781 |
| 7703408NA | V | 12/10/2003 | 3 | INTER. RECT. | | | OM1327NM/883B | 781 |
| 7703408NA | V | 12/10/2003 | 1 | SOLITRON | | | SDP137AHVNMD | 781 |
| 7703408TA | V | 12/10/2003 | 0 | INTER. RECT. | | | OM137AHVNT/883B | 781 |
| 7703408TA | V | 12/10/2003 | 1 | SEMELAB | | Y | IP137AHVG-DESC | 781 |
| 7703408TA | V | 12/10/2003 | 1 | SOLITRON | | | SDP137AHVTMD | 781 |
| 7703408UA | V | 12/10/2003 | 0 | INTER. RECT. | | | OM137AHVST/883B | 781 |
| 7703408UA | V | 12/10/2003 | 1 | SEMELAB | | Y | IP137AHVIG-DESC | 781 |
| 7703408UA | V | 12/10/2003 | 1 | SOLITRON | | | SDP137AHVUMD | 781 |
| 7703408XA | V | 12/10/2003 | 1 | SEMELAB | | Y | IP137AHVH-DESC | 781 |
| 7703408XA | V | 12/10/2003 | 1 | SOLITRON | | | SDP137AHVXMD | 781 |
| 7703408YA | V | 12/10/2003 | 3 | INTER. RECT. | | | OM1327NK/883B | 781 |
| 7703408YA | V | 12/10/2003 | 1 | SEMELAB | | Y | IP137AHVK-DESC | 781 |
| 7703408YA | V | 12/10/2003 | 1 | SOLITRON | | | SDP137AHVYMD | 781 |
| 7703408ZA | V | 12/10/2003 | 1 | SEMELAB | | Y | IP137AHVR-DESC | 781 |
| 7703501JA | | 09/26/1977 | | (NONE) | | | 4514B (GEN) | 340 |
| 7703501ZA | | 09/26/1977 | | (NONE) | | | 4514B (GEN) | 340 |
| 7703601AA | C | 05/07/2001 | | (NONE) | | | 54C08 (GEN) | 110 |
| 7703601CA | C | 05/07/2001 | 1 | NATIONAL | | Y | MM54C08J/883B | 110 |
| 7703601DA | C | 05/07/2001 | | (NONE) | | | 54C08 (GEN) | 110 |
| 7703701EA | F | 05/07/2001 | 1 | NATIONAL | | Y | MM54C85J/883 | 209 |
| 7703701FA | F | 05/07/2001 | | (NONE) | 09/09/1998 | | MM54C85 (GEN) | 209 |
| 7703702EA | F | 05/07/2001 | 1 | TI | | Y | CD4585BF3A | 209 |
| 7703702FA | F | 05/07/2001 | | (NONE) | | | 4585B (GEN) | 209 |
| 7703901GA | B | 07/10/1996 | | (NONE) | | | 4250 (GEN) | 739 |
| 7703901HA | B | 07/10/1996 | | (NONE) | | | 4250 (GEN) | 739 |
| 7703901PA | B | 07/10/1996 | | (NONE) | | | 4250 (GEN) | 739 |
| 77040012A | E | 05/04/1993 | | (NONE) | 05/31/1994 | | 79M05 (GEN) | 783 |
| 7704001HA | E | 05/04/1993 | | (NONE) | 08/15/1999 | | 79M05 (GEN) | 783 |
| 7704001PA | E | 05/04/1993 | | (NONE) | | | 79M05 (GEN) | 783 |
| 7704001XA | E | 05/04/1993 | 1 | SEMELAB | | Y | IP79M05H-DESC | 783 |
| 7704001YA | E | 05/04/1993 | 1 | SEMELAB | | Y | IP7905K-DESC | 783 |
| 7704003XA | E | 05/04/1993 | 1 | SEMELAB | | Y | IP120MH-12-DESC | 783 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 7704003YA | E | 05/04/1993 | 1 | SEMELAB | | Y | IP120K-12-DESC | 783 |
| 7704004XA | E | 05/04/1993 | 1 | SEMELAB | | Y | IP120MH-15-DESC | 783 |
| 7704004YA | E | 05/04/1993 | 1 | SEMELAB | | Y | IP120K-15-DESC | 783 |
| 7704005XA | E | 05/04/1993 | | (NONE) | | | LM120H-24 (GEN) | 783 |
| 7704005YA | E | 05/04/1993 | | (NONE) | | | LM120H-24 (GEN) | 783 |
| 7704101EA | A | 09/25/1981 | | (NONE) | | | 54LS124 (GEN) | 815 |
| 7704101FA | A | 09/25/1981 | | (NONE) | | | 54LS124 (GEN) | 815 |
| 5962-7704201VEA | H | 01/20/2004 | 1 | TI | | Y | SNV54LS670J | 600 |
| 7704201EA | H | 01/20/2004 | 1 | LANSDALE | | Y | SL54LS670/BEA | 600 |
| 7704201EA | H | 01/20/2004 | 1 | TI | | Y | SNJ54LS670J | 600 |
| 5962-7704201VFA | H | 01/20/2004 | 1 | TI | | Y | SNV54LS670W | 600 |
| 7704201FA | H | 01/20/2004 | 1 | LANSDALE | | Y | SL54LS670/BFA | 600 |
| 7704201FA | H | 01/20/2004 | 1 | TI | | Y | SNJ54LS670W | 600 |
| 77043012A | N | 03/24/2003 | 1 | TI | | Y | LM124FKB | 713 |
| 7704301AA | N | 03/24/2003 | | (NONE) | | | LM124 (GEN) | 713 |
| 5962-7704301VCA | N | 03/24/2003 | 1 | TI | | Y | LM124JQMLV | 713 |
| 7704301CA | N | 03/24/2003 | I | NATIONAL | | Y | LM124J/883 | 713 |
| 7704301CA | N | 03/24/2003 | 1 | TI | | Y | LM124JB | 713 |
| 7704301DA | N | 03/24/2003 | 1 | TI | | Y | LM124WB | 713 |
| 7704301XA | N | 03/24/2003 | | (NONE) | 06/07/2001 | | LM124 (GEN) | 713 |
| 77043022A | N | 03/24/2003 | 1 | NATIONAL | | Y | LM124AE/883 | 713 |
| 77043022A | N | 03/24/2003 | 1 | TI | | Y | LM124AFKB | 713 |
| 7704302CA | N | 03/24/2003 | I | NATIONAL | | Y | LM124AJ/883 | 713 |
| 7704302CA | N | 03/24/2003 | 1 | TI | | Y | LM124AJB | 713 |
| 7704302DA | N | 03/24/2003 | 1 | TI | | Y | LM124AWB | 713 |
| 7704302XA | N | 03/24/2003 | 1 | NATIONAL | | Y | LM124AWG/883 | 713 |
| 7704401AA | E | 03/20/2001 | | (NONE) | | | 4078B (GEN) | 124 |
| 7704401CA | E | 03/20/2001 | | (NONE) | | | 4078B (GEN) | 124 |
| 7704402CA | E | 03/20/2001 | 1 | TI | | Y | CD4078BF3A | 124 |
| 7704403CA | E | 03/20/2001 | 1 | TI | | Y | CD4002BF3A | 124 |
| 7704501EA | E | 11/02/1987 | | (NONE) | | | 4528B (GEN) | 166 |
| 7704501FA | E | 11/02/1987 | | (NONE) | | | 4528B (GEN) | 166 |
| 7704502EA | E | 11/02/1987 | | (NONE) | | | 4528B (GEN) | 166 |
| 7704601CA | E | 05/07/2001 | 0 | NATIONAL | | Y | CD4093BMJ/883 | 109 |
| 7704601DA | E | 05/07/2001 | | (NONE) | | | CD4093B (GEN) | 109 |
| 7704602CA | E | 05/07/2001 | 1 | TI | | Y | CD4093BF3A | 109 |
| 7704701EA | F | 06/15/2001 | 1 | TI | | Y | CD4555BF3A | 283 |
| 7704702EA | F | 06/15/2001 | | (NONE) | | | 14555B (GEN) | 283 |
| 7704702FA | F | 06/15/2001 | | (NONE) | | | 14555B (GEN) | 283 |
| 7704801EA | E | 06/25/2001 | 1 | TI | | Y | CD4556BF3A | 283 |
| 7704801FA | E | 06/25/2001 | | (NONE) | | | 4556B (GEN) | 283 |
| 77049012A | H | 01/15/2003 | 1 | MICROSEMI | | Y | SG55452BL/883B | 581 |
| 77049012A | H | 01/15/2003 | 3 | TI | | Y | SNJ55452BFK | 581 |
| 7704901PA | H | 01/15/2003 | I | MICROSEMI | | Y | SG55452BY/883B | 581 |
| 7704901PA | H | 01/15/2003 | I | TI | | Y | SNJ55452BJG | 581 |
| 77049022A | H | 01/15/2003 | 1 | MICROSEMI | | Y | SG55451BL/883B | 580 |
| 77049022A | H | 01/15/2003 | 0 | TI | | Y | SNJ55451BFK | 580 |
| 7704902PA | H | 01/15/2003 | 0 | MICROSEMI | | Y | SG55451Y/883B | 580 |
| 7704902PA | H | 01/15/2003 | 0 | TI | | Y | SNJ55451BJG | 580 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 7705001CA | D | 11/24/2003 | 1 | QP SEMI | | Y | RM2211 | 803 |
| 7705101CA | E | 05/17/2001 | | (NONE) | 09/30/1995 | | 4073B (GEN) | 112 |
| 7705101DA | E | 05/17/2001 | | (NONE) | | | 4073B (GEN) | 112 |
| 7705102CA | E | 05/17/2001 | 1 | TI | | Y | CD4073BF3A | 112 |
| 77052012A | K | 02/04/2003 | 1 | ANALOG (3) | | Y | ADG508ATE/883B | 193 |
| 77052012A | K | 02/04/2003 | | INTERSIL | | Y | HI4-508/883 | 193 |
| 77052012C | K | 02/04/2003 | 1 | MAXIM INTEG. | | | DG508AAZ/883B | 193 |
| 7705201EA | K | 02/04/2003 | 1 | ANALOG (3) | | Y | ADG508ATQ/883B | 193 |
| 7705201EA | K | 02/04/2003 | I | INTERSIL | | Y | HI1-508/883 | 193 |
| 7705201EA | K | 02/04/2003 | 1 | MAXIM INTEG. | | | DG508AAK/883B | 193 |
| 7705201FA | K | 02/04/2003 | | (NONE) | | | DG508A (GEN) | 193 |
| 7705201XA | K | 02/04/2003 | | (NONE) | | | DG508A (GEN) | 193 |
| 7705201XC | K | 02/04/2003 | 1 | MAXIM INTEG. | | | DG508AAL/883B | 193 |
| 77052022A | K | 02/04/2003 | 0 | INTERSIL | | Y | HI4-548/883 | 193 |
| 7705202EA | K | 02/04/2003 | | INTERSIL | | Y | HI1-548/883 | 193 |
| 77052032C | K | 02/04/2003 | 1 | MAXIM INTEG. | | | MAX358MLP/883B | 193 |
| 7705203EA | K | 02/04/2003 | 1 | MAXIM INTEG. | | | MAX358MJE/883B | 193 |
| 77053012A | L | 02/12/2003 | 1 | SILICONIX | | Y | DG201AAZ/883 | 183 |
| 77053012C | L | 02/12/2003 | 1 | MAXIM INTEG. | | | DG201AAZ/883B | 183 |
| 7705301EA | L | 02/12/2003 | I | MAXIM INTEG. | | | DG201AAK/883B | 183 |
| 7705301EA | L | 02/12/2003 | I | SILICONIX | | Y | DG201AAK/883 | 183 |
| 7705301FA | L | 02/12/2003 | | (NONE) | | | DG201A (GEN) | 183 |
| 7705301XA | L | 02/12/2003 | 1 | SILICONIX | | Y | DG201AAL/883 | 183 |
| 7705301XC | L | 02/12/2003 | 1 | MAXIM INTEG. | | | DG201AAL/883B | 183 |
| 77053022A | L | 02/12/2003 | 1 | INTERSIL | 10/05/2004 | Y | HI4-201/883 | 183 |
| 77053022C | L | 02/12/2003 | 1 | MAXIM INTEG. | | | HI4-201/883B | 183 |
| 7705302EA | L | 02/12/2003 | 1 | MAXIM INTEG. | | | HI1-201/883B | 183 |
| 7705401CA | F | 05/19/2004 | 1 | AUSTIN SEMI. | | Y | RM4194DC | 784 |
| 7705401CA | F | 05/19/2004 | 1 | QP SEMI | | Y | RM4194DC | 784 |
| 7705401RA | F | 05/19/2004 | 1 | QP SEMI | | Y | RM4194DC | 784 |
| 7705501EA | B | 09/25/1981 | | (NONE) | | | 4098B (GEN) | 166 |
| 7705501FA | B | 09/25/1981 | | (NONE) | | | 4098B (GEN) | 166 |
| 7705601AA | | 12/09/1977 | | (NONE) | | | 54C906 (GEN) | 513 |
| 7705601CA | | 12/09/1977 | | (NONE) | | | 54C906 (GEN) | 513 |
| 7705601DA | | 12/09/1977 | | (NONE) | | | 54C906 (GEN) | 513 |
| 7705701RA | F | 07/19/2004 | 1 | LANSDALE | | Y | SL54LS244/BRA | 529 |
| 7705701RA | F | 07/19/2004 | I | TI | | Y | SNJ54LS244J | 529 |
| 7705701SA | F | 07/19/2004 | 1 | LANSDALE | | Y | SL54LS244/BSA | 529 |
| 7705701SA | F | 07/19/2004 | I | TI | | Y | SNJ54LS244W | 529 |
| 7705801EA | F | 08/19/2003 | 2 | NATIONAL | | Y | CD4040BMJ/883 | 305 |
| 7705801FA | F | 08/19/2003 | | (NONE) | | | 4040B (GEN) | 305 |
| 7705901CA | D | 05/17/2001 | | (NONE) | 09/30/1995 | | 4082B (GEN) | 114 |
| 7705901DA | D | 05/17/2001 | | (NONE) | | | 4082B (GEN) | 114 |
| 7705902CA | D | 05/17/2001 | 1 | TI | | Y | CD4082BF3A | 114 |
| 7706001CA | D | 05/17/2001 | | (NONE) | 09/30/1995 | | 4072B (GEN) | 125 |
| 7706001DA | D | 05/17/2001 | | (NONE) | | | 4072B (GEN) | 125 |
| 7706002CA | D | 05/17/2001 | 1 | TI | | Y | CD4072BF3A | 125 |
| 7800301GA | J | 04/02/2004 | | (NONE) | | | LM144H (GEN) | 721 |
| 78003022A | J | 04/02/2004 | | (NONE) | | | 2640 (GEN) | 701 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 7800302GC | J | 04/02/2004 | 1 | INTERSIL | | Y | HA2-2640/883 | 701 |
| 7800302PA | J | 04/02/2004 | 1 | INTERSIL | | Y | HA7-2640/883 | 701 |
| 7800303PA | J | 04/02/2004 | 0 | MICROSEMI | | Y | SG143Y/883B | 701 |
| 7800303XA | J | 04/02/2004 | 0 | MICROSEMI | | Y | SG143T/883B | 701 |
| 7800304PA | J | 04/02/2004 | 0 | MICROSEMI | | Y | SG1536Y/883B | 701 |
| 7800304XA | J | 04/02/2004 | 0 | MICROSEMI | | Y | SG1536T/883B | 701 |
| 7800701CA | D | 06/10/2004 | 1 | ROCHESTER | | Y | LM7709AJ/883 | 701 |
| 7800701GA | D | 06/10/2004 | 1 | ROCHESTER | | Y | LM7709AH/883 | 701 |
| 7800701HA | D | 06/10/2004 | 1 | ROCHESTER | | Y | LM7709AW/883 | 701 |
| 7800701PA | D | 06/10/2004 | 1 | ROCHESTER | | Y | LM7709AJ8/883 | 701 |
| 7800801CA | G | 04/14/2004 | | (NONE) | | | 0056 (GEN) | 550 |
| 7800801GA | G | 04/14/2004 | | (NONE) | | | 0056 (GEN) | 550 |
| 7800802CA | G | 04/14/2004 | 3 | ROCHESTER | | Y | DS0026J/883 | 550 |
| 7800802GA | G | 04/14/2004 | 3 | ROCHESTER | | Y | DS0026H/883 | 550 |
| 7800802PA | G | 04/14/2004 | | (NONE) | | | 0026 (GEN) | 550 |
| 78009012A | D | 07/19/2004 | 1 | LANSDALE | | Y | SL10516/B2A | 574 |
| 78009012A | D | 07/19/2004 | 3 | SARNOFF | | Y | GEM17001Q2A | 574 |
| 78009012C | D | 07/19/2004 | 1 | LANSDALE | | Y | SL10516/B2C | 574 |
| 78009012C | D | 07/19/2004 | 3 | SARNOFF | | Y | GEM17001Q2C | 574 |
| 7800901EA | D | 07/19/2004 | 1 | LANSDALE | | Y | SL10516/BEA | 574 |
| 7800901EA | D | 07/19/2004 | 3 | SARNOFF | | Y | GEM17001QEA | 574 |
| 7800901EC | D | 07/19/2004 | 3 | SARNOFF | | Y | GEM17001QEC | 574 |
| 7800901FA | D | 07/19/2004 | 1 | LANSDALE | | Y | SL10516/BFA | 574 |
| 7800901FA | D | 07/19/2004 | 3 | SARNOFF | | Y | GEM17001QFA | 574 |
| 7800901FC | D | 07/19/2004 | 3 | SARNOFF | | Y | GEM17001QFC | 574 |
| 78010012A | E | 12/15/2003 | 1 | LANSDALE | | Y | SL54LS273/B2A | 159 |
| 78010012A | E | 12/15/2003 | 1 | TI | | Y | SNJ54LS273FK | 159 |
| 78010012C | E | 12/15/2003 | 1 | LANSDALE | | Y | SL54LS273/B2C | 159 |
| 5962-7801001VRA | E | 12/15/2003 | 1 | TI | | Y | SNV54LS273J | 159 |
| 7801001RA | E | 12/15/2003 | 1 | LANSDALE | | Y | SL54LS273/BRA | 159 |
| 7801001RA | E | 12/15/2003 | 1 | TI | | Y | SNJ54LS273J | 159 |
| 5962-7801001VSA | E | 12/15/2003 | 1 | TI | | Y | SNV54LS273W | 159 |
| 7801001SA | E | 12/15/2003 | 1 | LANSDALE | | Y | SL54LS273/BSA | 159 |
| 7801001SA | E | 12/15/2003 | 1 | TI | | Y | SNJ54LS273W | 159 |
| 78011012A | G | 12/15/2003 | 1 | LANSDALE | | Y | SL54LS374/B2A | 159 |
| 78011012C | G | 12/15/2003 | 1 | LANSDALE | | Y | SL54LS374/B2C | 159 |
| 7801101RA | G | 12/15/2003 | 1 | LANSDALE | | Y | SL54LS374/BRA | 159 |
| 7801101SA | G | 12/15/2003 | 1 | LANSDALE | | Y | SL54LS374/BSA | 159 |
| 78011022A | G | 12/15/2003 | 1 | TI | | Y | SNJ54LS374FK | 159 |
| 5962-7801102VRA | G | 12/15/2003 | 1 | TI | | Y | SNV54LS374J | 159 |
| 7801102RA | G | 12/15/2003 | 1 | TI | | Y | SNJ54LS374J | 159 |
| 5962-7801102VSA | G | 12/15/2003 | 1 | TI | | Y | SNV54LS374W | 159 |
| 7801102SA | G | 12/15/2003 | 1 | TI | | Y | SNJ54LS374W | 159 |
| 78012012A | C | 01/16/1987 | 1 | TI | | Y | SNJ54LS240FK | 529 |
| 78012012C | C | 01/16/1987 | 1 | LANSDALE | | Y | SL54S240/B2C | 529 |
| 5962-7801201VRA | C | 01/16/1987 | 1 | TI | | Y | SNV54LS240J | 529 |
| 7801201RA | C | 01/16/1987 | 1 | LANSDALE | | Y | SL54S240/BRA | 529 |
| 7801201RA | C | 01/16/1987 | 1 | TI | | Y | SNJ54LS240J | 529 |
| 5962-7801201VSA | C | 01/16/1987 | 1 | TI | | Y | SNV54LS240W | 529 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 7801201SA | C | 01/16/1987 | 1 | LANSDALE | | Y | SL54S240/BSA | 529 |
| 7801201SA | C | 01/16/1987 | 1 | TI | | Y | SNJ54LS240W | 529 |
| 7801301GA | L | 02/23/2004 | | (NONE) | | | CTS0002 (GEN) | 739 |
| 7801301XA | L | 02/23/2004 | 1 | MS KENNEDY | | Y | MSK0002H | 739 |
| 7801301XA | L | 02/23/2004 | 1 | SATCON | | Y | FLH0002H/883 | 739 |
| 7801301XA | L | 02/23/2004 | 1 | SENSITRON | | Y | SEN-0002H | 739 |
| 7801301XC | L | 02/23/2004 | 1 | MS KENNEDY | | Y | MSK0002H | 739 |
| 7801301XC | L | 02/23/2004 | 1 | SENSITRON | | Y | SEN-0002H | 739 |
| 7801401AA | J | 03/11/2003 | | (NONE) | | | DG129A (GEN) | 188 |
| 7801401CA | J | 03/11/2003 | 1 | SILICONIX | | Y | DG129AP/883 | 188 |
| 7801401XA | J | 03/11/2003 | | SILICONIX | | Y | DG129AL/883 | 188 |
| 78015012A | G | 07/12/1989 | 0 | SARNOFF | | Y | GEM13501Q2A | 602 |
| 78015012C | G | 07/12/1989 | 0 | SARNOFF | | Y | GEM13501Q2C | 602 |
| 7801501EA | G | 07/12/1989 | 0 | SARNOFF | | Y | GEM13501QEA | 602 |
| 7801501EC | G | 07/12/1989 | 0 | SARNOFF | | Y | GEM13501QEC | 602 |
| 7801501FA | G | 07/12/1989 | 0 | SARNOFF | | Y | GEM13501QFA | 602 |
| 7801501FC | G | 07/12/1989 | 0 | SARNOFF | | Y | GEM13501QFC | 602 |
| 78015022A | G | 07/12/1989 | 1 | LANSDALE | | Y | SL54S189/B2A | 602 |
| 78015022A | G | 07/12/1989 | 3 | SARNOFF | | Y | GEM24202Q2A | 602 |
| 78015022C | G | 07/12/1989 | 1 | LANSDALE | | Y | SL54S189/B2C | 602 |
| 78015022C | G | 07/12/1989 | 3 | SARNOFF | | Y | GEM24202Q2C | 602 |
| 7801502EA | G | 07/12/1989 | 1 | LANSDALE | | Y | SL54S189/BEA | 602 |
| 7801502EA | G | 07/12/1989 | 3 | SARNOFF | | Y | GEM24202QEA | 602 |
| 7801502EC | G | 07/12/1989 | 3 | SARNOFF | | Y | GEM24202QEC | 602 |
| 7801502FA | G | 07/12/1989 | 1 | LANSDALE | | Y | SL54S189/BFA | 602 |
| 7801502FA | G | 07/12/1989 | 3 | SARNOFF | | Y | GEM24202QFA | 602 |
| 7801502FC | G | 07/12/1989 | 3 | SARNOFF | | Y | GEM24202QFC | 602 |
| 78015032A | G | 07/12/1989 | 3 | SARNOFF | | Y | GEM13503Q2A | 602 |
| 78015032C | G | 07/12/1989 | 3 | SARNOFF | | Y | GEM13503Q2C | 602 |
| 7801503EA | G | 07/12/1989 | 3 | SARNOFF | | Y | GEM13503QEA | 602 |
| 7801503EC | G | 07/12/1989 | 3 | SARNOFF | | Y | GEM13503QEC | 602 |
| 7801503FA | G | 07/12/1989 | 3 | SARNOFF | | Y | GEM13503QFA | 602 |
| 7801503FC | G | 07/12/1989 | 3 | SARNOFF | | Y | GEM13503QFC | 602 |
| 78015042A | G | 07/12/1989 | 1 | SARNOFF | | Y | GEM19804Q2A | 602 |
| 78015042C | G | 07/12/1989 | 1 | SARNOFF | | Y | GEM19804Q2C | 602 |
| 7801504EA | G | 07/12/1989 | 1 | SARNOFF | | Y | GEM19804QEA | 602 |
| 7801504EC | G | 07/12/1989 | 1 | SARNOFF | | Y | GEM19804QEC | 602 |
| 7801504FA | G | 07/12/1989 | 1 | SARNOFF | | Y | GEM19804QFA | 602 |
| 7801504FC | G | 07/12/1989 | 1 | SARNOFF | | Y | GEM19804QFC | 602 |
| 78015052A | G | 07/12/1989 | | (NONE) | | | 27S07-20 (GEN) | 602 |
| 7801505EA | G | 07/12/1989 | | (NONE) | | | 27S07-20 (GEN) | 602 |
| 7801505FA | G | 07/12/1989 | | (NONE) | | | 27S07-20 (GEN) | 602 |
| 78015062A | G | 07/12/1989 | | (NONE) | | | 27LS07-30 (GEN) | 602 |
| 7801506EA | G | 07/12/1989 | | (NONE) | | | 27LS07-30 (GEN) | 602 |
| 7801506FA | G | 07/12/1989 | | (NONE) | | | 27LS07-30 (GEN) | 602 |
| 78016013A | F | 08/07/2000 | 1 | LANSDALE | | Y | SL82S141/B3A | 656 |
| 78016013A | F | 08/07/2000 | 1 | QP SEMI | | Y | 82S141/B3A | 656 |
| 7801601JA | F | 08/07/2000 | 1 | LANSDALE | | Y | SL82S141/BJA | 656 |
| 7801601JA | F | 08/07/2000 | 1 | QP SEMI | | Y | 82S141/BJA | 656 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 7801601KA | F | 08/07/2000 | 1 | LANSDALE | | Y | SL82S141/BKA | 656 |
| 7801601KA | F | 08/07/2000 | 1 | QP SEMI | | Y | 82S141/BKA | 656 |
| 7801601UA | F | 08/07/2000 | | (NONE) | | | 27S31 (GEN) | 656 |
| 78016023A | F | 08/07/2000 | | (NONE) | 08/02/1996 | | 27S31A (GEN) | 656 |
| 7801602JA | F | 08/07/2000 | | (NONE) | 08/02/1996 | | 27S31A (GEN) | 656 |
| 7801602KA | F | 08/07/2000 | | (NONE) | 08/02/1996 | | 27S31A (GEN) | 656 |
| 7801602UA | F | 08/07/2000 | | (NONE) | | | 27S31A (GEN) | 656 |
| 7801701QA | E | 08/26/2003 | | (NONE) | 08/31/1995 | | 2910 (GEN) | 420 |
| 7801701QA | E | 08/26/2003 | | (NONE) | 08/31/1995 | | 2910 (GEN) | 420 |
| 7801701ZA | E | 08/26/2003 | | (NONE) | | | 2910 (GEN) | 420 |
| 7801702QA | E | 08/26/2003 | 1 | ROCHESTER | | Y | 2910A/BQA | 420 |
| 7801702ZA | E | 08/26/2003 | 1 | ROCHESTER | | Y | 2910A/BZA | 420 |
| 7801702ZC | E | 08/26/2003 | 1 | ROCHESTER | | Y | 2910A/BZC | 420 |
| 7801801EA | E | 01/26/1989 | | (NONE) | | | AM686 (GEN) | 772 |
| 7801801IA | E | 01/26/1989 | | (NONE) | | | AM686 (GEN) | 772 |
| 7801901EA | D | 05/09/1989 | | (NONE) | 06/30/1994 | | AM687 (GEN) | 774 |
| 7801902EA | D | 05/09/1989 | | (NONE) | | | AM6687 (GEN) | 774 |
| 78019032A | D | 05/09/1989 | | (NONE) | 10/27/2000 | | 96687 (GEN) | 774 |
| 7801903EA | D | 05/09/1989 | | (NONE) | 10/27/2000 | | 96687 (GEN) | 774 |
| 5962-7802001M2A | T | 05/03/2001 | 2 | QP SEMI | | Y | QP26LS32/B2A | 575 |
| 78020012A | T | 05/03/2001 | | (NONE) | 5962-7802001M2A | | 26LS32 (GEN) | 575 |
| 5962-7802001MEA | T | 05/03/2001 | 2 | QP SEMI | | Y | QP26LS32/BEA | 575 |
| 7802001EA | T | 05/03/2001 | | (NONE) | 5962-7802001MEA | | 26LS32 (GEN) | 575 |
| 5962-7802001MFA | T | 05/03/2001 | 2 | QP SEMI | | Y | QP26LS32/BFA | 575 |
| 7802001FA | T | 05/03/2001 | | (NONE) | 5962-7802001MFA | | 26LS32 (GEN) | 575 |
| 5962-7802002M2A | T | 05/03/2001 | 1 | QP SEMI | | Y | QP26LS33/B2A | 575 |
| 78020022A | T | 05/03/2001 | | (NONE) | 5962-7802002M2A | | 26LS33 (GEN) | 575 |
| 5962-7802002MEA | T | 05/03/2001 | 1 | QP SEMI | | Y | QP26LS33/BEA | 575 |
| 7802002EA | T | 05/03/2001 | | (NONE) | 5962-7802002MEA | | 26LS33 (GEN) | 575 |
| 5962-7802002MFA | T | 05/03/2001 | 1 | QP SEMI | | Y | QP26LS33/BFA | 575 |
| 7802002FA | T | 05/03/2001 | | (NONE) | 5962-7802002MFA | | 26LS33 (GEN) | 575 |
| 5962-7802003M2A | T | 05/03/2001 | 1 | TI | | Y | AM26LS32AMFKB | 575 |
| 78020032A | T | 05/03/2001 | 0 | TI | 5962-7802003M2A | Y | AM26LS32AMFKB | 575 |
| 5962-7802003MEA | T | 05/03/2001 | 1 | TI | | Y | AM26LS32AMJB | 575 |
| 7802003EA | T | 05/03/2001 | 0 | TI | 5962-7802003MEA | Y | AM26LS32AMJB | 575 |
| 5962-7802003MFA | T | 05/03/2001 | 1 | TI | | Y | AM26LS32AMWB | 575 |
| 7802003FA | T | 05/03/2001 | | (NONE) | 5962-7802003MFA | | 26LS32A (GEN) | 575 |
| 5962-7802004M2A | T | 05/03/2001 | 1 | TI | | Y | AM26LS33AMFKB | 575 |
| 78020042A | T | 05/03/2001 | | (NONE) | 5962-7802004M2A | | 26LS33A (GEN) | 575 |
| 5962-7802004MEA | T | 05/03/2001 | 1 | TI | | Y | AM26LS33AMJB | 575 |
| 7802004EA | T | 05/03/2001 | 0 | TI | 5962-7802004MEA | Y | AM26LS33AMJB | 575 |
| 5962-7802004MFA | T | 05/03/2001 | 1 | TI | | Y | AM26LS33AMWB | 575 |
| 7802004FA | T | 05/03/2001 | 0 | TI | 5962-7802004MFA | Y | AM26LS33AMWB | 575 |
| 5962-7802005M2A | T | 05/03/2001 | 1 | NATIONAL | | Y | DS26F32ME/883 | 575 |
| 5962F7802005Q2A | T | 05/03/2001 | | (NONE) | | | 26F32 (GEN) | 575 |
| 5962R7802005Q2A | T | 05/03/2001 | 1 | NATIONAL | | Y | DS26F32MER-QML | 575 |
| 5962-7802005MEA | T | 05/03/2001 | 1 | NATIONAL | | Y | DS26F32MJ/883 | 575 |
| 5962-7802005VEA | T | 05/03/2001 | 1 | NATIONAL | | Y | DS26F32MJ-QMLV | 575 |
| 5962F7802005QEA | T | 05/03/2001 | | (NONE) | | | 26F32 (GEN) | 575 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962F7802005VEA | T | 05/03/2001 | | (NONE) | | | 26F32 (GEN) | 575 |
| 5962R7802005QEA | T | 05/03/2001 | 1 | NATIONAL | | Y | DS26F32MJR-QML | 575 |
| 5962R7802005VEA | T | 05/03/2001 | 1 | NATIONAL | | Y | DS26F32MJRQMLV | 575 |
| 5962-7802005MFA | T | 05/03/2001 | 1 | NATIONAL | | Y | DS26F32MW/883 | 575 |
| 5962-7802005VFA | T | 05/03/2001 | 1 | NATIONAL | | Y | DS26F32MW-QMLV | 575 |
| 5962F7802005QFA | T | 05/03/2001 | | (NONE) | | | 26F32 (GEN) | 575 |
| 5962F7802005VFA | T | 05/03/2001 | | (NONE) | | | 26F32 (GEN) | 575 |
| 5962R7802005QFA | T | 05/03/2001 | 1 | NATIONAL | | Y | DS26F32MWR-QML | 575 |
| 5962R7802005VFA | T | 05/03/2001 | 1 | NATIONAL | | Y | DS26F32MWRQMLV | 575 |
| 5962-7802005MZA | T | 05/03/2001 | 1 | NATIONAL | | Y | DS26F32MWG/883 | 575 |
| 5962-7802005VZA | T | 05/03/2001 | 1 | NATIONAL | | Y | DS26F32MWG-QMLV | 575 |
| 5962R7802005VZA | T | 05/03/2001 | 1 | NATIONAL | | Y | DS26F32MWGRQMLV | 575 |
| 5962-7802006Q2A | T | 05/03/2001 | 1 | NATIONAL | | Y | DS26LS32ME/883 | 575 |
| 5962-7802006QEA | T | 05/03/2001 | 1 | NATIONAL | | Y | DS26LS32MJ/883 | 575 |
| 5962-7802006QFA | T | 05/03/2001 | 1 | NATIONAL | | Y | DS26LS32MW/883 | 575 |
| 7802201JA | M | 04/02/2001 | 1 | ROCHESTER | | Y | MC2716M/BJA | 658 |
| 7802202JA | M | 04/02/2001 | | (NONE) | | | | 658 |
| 7802203JA | M | 04/02/2001 | | (NONE) | | | | 658 |
| 7802204JA | M | 04/02/2001 | | (NONE) | | | | 658 |
| 7802205JA | M | 04/02/2001 | | (NONE) | | | | 658 |
| 7802206JA | M | 04/02/2001 | | (NONE) | | | | 658 |
| 7802207JA | M | 04/02/2001 | | (NONE) | | | | 658 |
| 7802208JA | M | 04/02/2001 | | (NONE) | | | | 658 |
| 7802209JA | M | 04/02/2001 | | (NONE) | | | | 658 |
| 5962-7802301M2A | R | 05/02/2001 | 1 | QP SEMI | | Y | QP26LS31/B2A | 569 |
| 5962-7802301Q2A | R | 05/02/2001 | 2 | NATIONAL | | Y | DS26LS31ME/883 | 569 |
| 5962F7802301Q2A | R | 05/02/2001 | 2 | NATIONAL | | Y | DS26LS31MEFQML | 569 |
| 78023012A | R | 05/02/2001 | | (NONE) | 5962-7802301M2A | | 26LS31 (GEN) | 569 |
| 5962-7802301MEA | R | 05/02/2001 | 2 | NATIONAL | | Y | DS26LS31MJ/883 | 569 |
| 5962-7802301MEA | R | 05/02/2001 | 1 | QP SEMI | | Y | QP26LS31/BEA | 569 |
| 5962-7802301VEA | R | 05/02/2001 | 2 | NATIONAL | | Y | DS26LS31MJ-QMLV | 569 |
| 5962F7802301MEA | R | 05/02/2001 | 2 | NATIONAL | | Y | DS26LS31MJFQML | 569 |
| 5962F7802301VEA | R | 05/02/2001 | 2 | NATIONAL | | Y | DS26LS31MJFQMLV | 569 |
| 7802301EA | R | 05/02/2001 | | (NONE) | 5962-7802301MEA | | 26LS31 (GEN) | 569 |
| 5962-7802301MFA | R | 05/02/2001 | 2 | NATIONAL | | Y | DS26LS31MW/883 | 569 |
| 5962-7802301MFA | R | 05/02/2001 | 1 | QP SEMI | | Y | QP26LS31/BFA | 569 |
| 5962-7802301VFA | R | 05/02/2001 | 2 | NATIONAL | | Y | DS26LS31MW-QMLV | 569 |
| 5962F7802301MFA | R | 05/02/2001 | 2 | NATIONAL | | Y | DS26LS31MWFQML | 569 |
| 5962F7802301VFA | R | 05/02/2001 | 2 | NATIONAL | | Y | DS26LS31MWFQMLV | 569 |
| 7802301FA | R | 05/02/2001 | | (NONE) | 5962-7802301MFA | | 26LS31 (GEN) | 569 |
| 5962-7802302M2A | R | 05/02/2001 | 1 | NATIONAL | | Y | DS26F31ME/883 | 569 |
| 5962-7802302MEA | R | 05/02/2001 | 1 | NATIONAL | | Y | DS26F31MJ/883 | 569 |
| 5962-7802302VEA | R | 05/02/2001 | 1 | NATIONAL | | Y | DS26F31MJ-QMLV | 569 |
| 5962F7802302VEA | R | 05/02/2001 | 1 | NATIONAL | | Y | DS26F31MJFQMLV | 569 |
| 5962-7802302MFA | R | 05/02/2001 | 1 | NATIONAL | | Y | DS26F31MW/883 | 569 |
| 5962-7802302VFA | R | 05/02/2001 | 1 | NATIONAL | | Y | DS26F31MW-QMLV | 569 |
| 5962F7802302VFA | R | 05/02/2001 | 1 | NATIONAL | | Y | DS26F31MWFQMLV | 569 |
| 5962-7802302MZA | R | 05/02/2001 | 1 | NATIONAL | | Y | DS26F31MWG/883 | 569 |
| 5962F7802302VZA | R | 05/02/2001 | 1 | NATIONAL | | Y | DS26F31MWGFQMLV | 569 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 78024012A | J | 07/27/2004 | 1 | TI | | Y | SNJ54LS299FK | 228 |
| 7802401RA | J | 07/27/2004 | 1 | TI | | Y | SNJ54LS299J | 228 |
| 7802401SA | J | 07/27/2004 | 1 | TI | | Y | SNJ54LS299W | 228 |
| 7802402RA | J | 07/27/2004 | | (NONE) | | | 25LS299 (GEN) | 228 |
| 7802402SA | J | 07/27/2004 | | (NONE) | | | 25LS299 (GEN) | 228 |
| 7802601EA | D | 07/27/2004 | I | TI | | Y | SNJ54LS390J | 300 |
| 7802601FA | D | 07/27/2004 | 1 | TI | | Y | SNJ54LS390W | 300 |
| 78027012A | D | 07/26/2004 | 0 | TI | | Y | SNJ54LS148FK | 345 |
| 7802701EA | D | 07/26/2004 | 0 | TI | | Y | SNJ54LS148J | 345 |
| 7802701FA | D | 07/26/2004 | 0 | TI | | Y | SNJ54LS148W | 345 |
| 7802801EA | H | 05/22/2002 | I | MICROSEMI | | Y | SG1524J/883B | 787 |
| 78029013A | G | 05/14/2001 | 1 | INTERSIL | | Y | HD4-15530-8 | 441 |
| 7802901JA | G | 05/14/2001 | 1 | INTERSIL | | Y | HD1-15530-8 | 441 |
| 79008012A | G | 11/07/2000 | | (NONE) | 12/31/2001 | | 55182 (GEN) | 573 |
| 7900801CA | G | 11/07/2000 | | (NONE) | 12/31/2001 | | 55182 (GEN) | 573 |
| 7900801DA | G | 11/07/2000 | | (NONE) | 12/31/2001 | | 55182 (GEN) | 573 |
| 79009012A | F | 11/17/2000 | 2 | TI | | Y | SNJ55183FK | 573 |
| 7900901AA | F | 11/17/2000 | | (NONE) | | | 55183 (GEN) | 573 |
| 7900901CA | F | 11/17/2000 | 2 | TI | | Y | SNJ55183J | 573 |
| 7900901DA | F | 11/17/2000 | 2 | TI | | Y | SNJ55183W | 573 |
| 7901001QA | F | 10/05/2000 | 1 | ROCHESTER | | Y | MD8085AH/B | 402 |
| 7901101CA | E | 02/17/1994 | | (NONE) | 09/02/2003 | | 4013B (GEN) | 158 |
| 7901101DA | E | 02/17/1994 | | NATIONAL | | Y | CD4013BMW/883 | 158 |
| 7901102CA | E | 02/17/1994 | | (NONE) | | | 4013B (GEN) | 158 |
| 7901102DA | E | 02/17/1994 | | (NONE) | | | 4013B (GEN) | 158 |
| 7901103CA | E | 02/17/1994 | | (NONE) | | | 4013B (GEN) | 158 |
| 7901201EA | A | 02/27/1986 | | (NONE) | | | 4021B (GEN) | 225 |
| 7901201FA | A | 02/27/1986 | | (NONE) | | | 4021B (GEN) | 225 |
| 7901301CA | E | 05/07/2001 | 1 | NATIONAL | | Y | CD4023BMJ/883B | 102 |
| 7901301DA | E | 05/07/2001 | | (NONE) | | | 4023B (GEN) | 102 |
| 7901302CA | E | 05/07/2001 | | (NONE) | | | 14023B (GEN) | 102 |
| 7901302DA | E | 05/07/2001 | | (NONE) | | | 14023B (GEN) | 102 |
| 7901401EA | B | 05/12/1987 | | (NONE) | | | 4049UB (GEN) | 541 |
| 7901401FA | B | 05/12/1987 | | (NONE) | | | 4049UB (GEN) | 541 |
| 7901501EA | H | 08/19/2003 | 2 | NATIONAL | | Y | CD4052BMJ/883 | 192 |
| 7901501FA | H | 08/19/2003 | | (NONE) | | | 4052B (GEN) | 192 |
| 7901502EA | H | 08/19/2003 | 1 | TI | | Y | CD4052BF3A | 192 |
| 7901503EA | H | 08/19/2003 | | (NONE) | | | 14052B (GEN) | 192 |
| 7901601EA | B | 11/18/1992 | | (NONE) | 09/30/1995 | | 4557B (GEN) | 234 |
| 7901601FA | B | 11/18/1992 | | (NONE) | | | 4557B (GEN) | 234 |
| 7901701QA | | 07/10/1979 | | (NONE) | | | 1854 (GEN) | 590 |
| 7901801JA | B | 06/26/1996 | | (NONE) | | | 1823 (GEN) | 608 |
| 7901901EA | | 06/13/1979 | | (NONE) | | | 1853 (GEN) | 284 |
| 7902401JA | B | 08/01/2000 | 1 | QP SEMI | | Y | R29633 | 657 |
| 79024023A | B | 08/01/2000 | 1 | QP SEMI | | Y | R29633 | 657 |
| 7902402JA | B | 08/01/2000 | 1 | QP SEMI | | Y | R29633 | 657 |
| 7902402KA | B | 08/01/2000 | 1 | QP SEMI | | Y | R29633 | 657 |
| 7902402LA | B | 08/01/2000 | 1 | QP SEMI | | Y | R29633 | 657 |
| 7902402XA | B | 08/01/2000 | 1 | QP SEMI | | Y | R29633 | 657 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 8000301UA | F | 06/11/2003 | 1 | QP SEMI | | | Z0800104LMB | 403 |
| 8000301XA | F | 06/11/2003 | 1 | QP SEMI | | | Z0800104CMB | 403 |
| 8000301ZA | F | 06/11/2003 | | (NONE) | | | Z8001CPU (GEN) | 403 |
| 8000302QA | F | 06/11/2003 | 1 | QP SEMI | | | Z0800204CMB | 403 |
| 8000302YA | F | 06/11/2003 | 1 | QP SEMI | | | Z0800204LMB | 403 |
| 8000303UA | F | 06/11/2003 | 1 | QP SEMI | | | Z0800106LMB | 403 |
| 8000303XA | F | 06/11/2003 | 1 | QP SEMI | | | Z0800106LMB | 403 |
| 8000303ZA | F | 06/11/2003 | | (NONE) | | | Z8001ACPU (GEN) | 403 |
| 8000304UA | F | 06/11/2003 | 1 | QP SEMI | | | Z0800110LMB | 403 |
| 8000304XA | F | 06/11/2003 | 1 | QP SEMI | | | Z0800110CMB | 403 |
| 8000304ZA | F | 06/11/2003 | | (NONE) | | | Z8001B (GEN) | 403 |
| 8000305QA | F | 06/11/2003 | 1 | QP SEMI | | | Z0800210CMB | 403 |
| 8000305YA | F | 06/11/2003 | 1 | QP SEMI | | | Z0800210LMB | 403 |
| 8000306QA | F | 06/11/2003 | 1 | QP SEMI | | | Z0800206CMB | 403 |
| 8000306YA | F | 06/11/2003 | 1 | QP SEMI | | | Z0800206LMB | 403 |
| 8001201JA | G | 05/23/1988 | | (NONE) | 12/24/1997 | | 2732 (GEN) | 659 |
| 8001202JA | G | 05/23/1988 | | (NONE) | | | | 659 |
| 8001203JA | G | 05/23/1988 | | (NONE) | 06/15/1996 | | 2732A25 (GEN) | 659 |
| 8001204JA | G | 05/23/1988 | | (NONE) | 06/15/1996 | | 2732A45 (GEN) | 659 |
| 8001205JA | G | 05/23/1988 | | (NONE) | | | | 659 |
| 8001206JA | G | 05/23/1988 | | (NONE) | | | | 659 |
| 8001207JA | G | 05/23/1988 | | (NONE) | | | | 659 |
| 8001208JA | G | 05/23/1988 | | (NONE) | | | | 659 |
| 8001209JA | G | 05/23/1988 | | (NONE) | | | | 659 |
| 8001210JA | G | 05/23/1988 | | (NONE) | | | | 659 |
| 8001211JA | G | 05/23/1988 | | (NONE) | | | | 659 |
| 8001301ZA | N | 06/22/1998 | 1 | MS KENNEDY | | Y | MSK0032B | 722 |
| 8001301ZA | N | 06/22/1998 | 1 | SATCON | | Y | FLH0032G/883 | 722 |
| 8001301ZC | N | 06/22/1998 | 1 | MS KENNEDY | | Y | MSK0032B | 722 |
| 8001401ZA | M | 02/23/2004 | 1 | MS KENNEDY | | Y | MSK0033B | 738 |
| 8001401ZA | M | 02/23/2004 | 1 | SATCON | | Y | FLH0033G/883 | 738 |
| 8001401ZC | M | 02/23/2004 | 1 | MS KENNEDY | | Y | MSK0033B | 738 |
| 80016012A | C | 06/21/2001 | 1 | INTERSIL | 10/05/2004 | Y | HA4-2420/883 | 818 |
| 8001601CA | C | 06/21/2001 | 1 | INTERSIL | | Y | HA1-2420/883 | 818 |
| 8001701EA | C | 08/26/2002 | I | TI | | Y | SNJ54LS166AJ | 225 |
| 8001701FA | C | 08/26/2002 | I | TI | | Y | SNJ54LS166AW | 225 |
| 8001801EA | E | 01/29/2004 | | (NONE) | | | 54LS168 (GEN) | 301 |
| 8001801FA | E | 01/29/2004 | | (NONE) | | | 54LS168 (GEN) | 301 |
| 80018022A | E | 01/29/2004 | 1 | LANSDALE | | Y | SL54LS169/B2A | 304 |
| 80018022A | E | 01/29/2004 | 3 | TI | | Y | SNJ54LS169FK | 304 |
| 80018022C | E | 01/29/2004 | 1 | LANSDALE | | Y | SL54LS169/B2C | 304 |
| 8001802EA | E | 01/29/2004 | 1 | LANSDALE | | Y | SL54LS169/BEA | 304 |
| 8001802EA | E | 01/29/2004 | 3 | TI | | Y | SNJ54LS169BJ | 304 |
| 8001802FA | E | 01/29/2004 | 1 | LANSDALE | | Y | SL54LS169/BFA | 304 |
| 8001802FA | E | 01/29/2004 | 3 | TI | | Y | SNJ54LS169BW | 304 |
| 80019012A | F | 08/27/2002 | 1 | LANSDALE | | Y | SL54LS09/B2A | 111 |
| 80019012A | F | 08/27/2002 | I | TI | | Y | SNJ54LS09FK | 111 |
| 80019012C | F | 08/27/2002 | 1 | LANSDALE | | Y | SL54LS09/B2C | 111 |
| 8001901CA | F | 08/27/2002 | 1 | LANSDALE | | Y | SL54LS09/BCA | 111 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 8001901CA | F | 08/27/2002 | I | TI | | Y | SNJ54LS09J | 111 |
| 8001901DA | F | 08/27/2002 | 1 | LANSDALE | | Y | SL54LS09/BDA | 111 |
| 8001901DA | F | 08/27/2002 | I | TI | | Y | SNJ54LS09W | 111 |
| 80020012A | E | 01/29/2004 | | (NONE) | | | 54LS242 (GEN) | 590 |
| 8002001CA | E | 01/29/2004 | | (NONE) | | | 54LS242 (GEN) | 590 |
| 8002001DA | E | 01/29/2004 | | (NONE) | | | 54LS242 (GEN) | 590 |
| 80020022A | E | 01/29/2004 | | (NONE) | | | 54LS243 (GEN) | 590 |
| 8002002CA | E | 01/29/2004 | 1 | TI | | Y | SNJ54LS243J | 590 |
| 8002002DA | E | 01/29/2004 | 1 | TI | | Y | SNJ54LS243W | 590 |
| 80021012A | H | 01/07/2004 | 1 | LANSDALE | | Y | SL54S245/B2A | 590 |
| 80021012A | H | 01/07/2004 | 1 | TI | | Y | SNJ54LS245FK | 590 |
| 5962-8002101VRA | H | 01/07/2004 | 1 | TI | | Y | SNV54LS245J | 590 |
| 5962-8002101VSA | H | 01/07/2004 | 1 | TI | | Y | SNV54LS245W | 590 |
| 8002101SA | H | 01/07/2004 | 1 | LANSDALE | | Y | SL54S245/BSA | 590 |
| 8002101SA | H | 01/07/2004 | 1 | TI | | Y | SNJ54LS245W | 590 |
| 80022012A | D | 09/30/2002 | 1 | LANSDALE | | Y | SL54S251/B2A | 272 |
| 80022012C | D | 09/30/2002 | 1 | LANSDALE | | Y | SL54S251/B2C | 272 |
| 8002201EA | D | 09/30/2002 | 1 | LANSDALE | | Y | SL54S251/BEA | 272 |
| 8002201FA | D | 09/30/2002 | 1 | LANSDALE | | Y | SL54S251/BFA | 272 |
| 8002301EA | B | 09/30/2002 | 1 | LANSDALE | | Y | SL54S258/BEA | 276 |
| 8002301EA | B | 09/30/2002 | 1 | SARNOFF | | Y | GEM08801QEA | 276 |
| 8002301EA | B | 09/30/2002 | 1 | TI | | Y | SNJ54S258J | 276 |
| 8002301EC | B | 09/30/2002 | 1 | SARNOFF | | Y | GEM08801QEC | 276 |
| 8002301FA | B | 09/30/2002 | 1 | LANSDALE | | Y | SL54S258/BFA | 276 |
| 8002301FA | B | 09/30/2002 | 1 | SARNOFF | | Y | GEM08801QFA | 276 |
| 8002301FA | B | 09/30/2002 | 1 | TI | | Y | SNJ54S258W | 276 |
| 8002301FC | B | 09/30/2002 | 1 | SARNOFF | | Y | GEM08801QFC | 276 |
| 8002501EA | B | 09/26/2002 | 1 | LANSDALE | | Y | SL54LS170/BEA | 600 |
| 8002501FA | B | 09/26/2002 | 1 | LANSDALE | | Y | SL54LS170/BFA | 600 |
| 8002501FA | B | 09/26/2002 | 1 | TI | | Y | SNJ54LS170W | 600 |
| 8002601EA | A | 03/16/1986 | 1 | ROCHESTER | | Y | 54LS261/BEA | 208 |
| 8002601FA | A | 03/16/1986 | 1 | ROCHESTER | | Y | 54LS261/BFA | 208 |
| 8003701CA | D | 09/26/1988 | | (NONE) | | | LM106 (GEN) | 771 |
| 8003701DA | D | 09/26/1988 | | (NONE) | | | LM106 (GEN) | 771 |
| 8003701GA | D | 09/26/1988 | | (NONE) | 06/08/1999 | | LM106 (GEN) | 771 |
| 8003701PA | D | 09/26/1988 | | (NONE) | | | LM106 (GEN) | 771 |
| 80041012A | D | 11/17/2000 | | (NONE) | | | 7831 (GEN) | 565 |
| 8004101EA | D | 11/17/2000 | I | NATIONAL | 12/01/2004 | Y | DS7831J/883B | 565 |
| 8004101FA | D | 11/17/2000 | 1 | NATIONAL | 12/01/2004 | Y | DS7831W/883B | 565 |
| 80041022A | D | 11/17/2000 | 1 | ROCHESTER | | Y | DS7832E/883B | 565 |
| 8004102EA | D | 11/17/2000 | 1 | ROCHESTER | | Y | DS7832J/883B | 565 |
| 8004102FA | D | 11/17/2000 | 1 | ROCHESTER | | Y | DS7832W/883B | 565 |
| 8100601AA | H | 03/10/2003 | | (NONE) | | | HI5040 (GEN) | 180 |
| 8100601EA | H | 03/10/2003 | 1 | MAXIM INTEG. | | | IH5040MJE/883B | 180 |
| 8100602AA | H | 03/10/2003 | | (NONE) | | | IH5041 (GEN) | 181 |
| 8100602EA | H | 03/10/2003 | 1 | MAXIM INTEG. | | | IH5041MJE/883B | 181 |
| 8100602IA | H | 03/10/2003 | | (NONE) | | | DG5141 (GEN) | 181 |
| 8100603AA | H | 03/10/2003 | | (NONE) | | | IH5042 (GEN) | 185 |
| 8100603EA | H | 03/10/2003 | 1 | MAXIM INTEG. | | | IH5042MJE/883B | 185 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 8100604AA | H | 03/10/2003 | | (NONE) | | | IH5043 (GEN) | 186 |
| 8100604EA | H | 03/10/2003 | 1 | MAXIM INTEG. | | | IH5043MJE/883B | 186 |
| 8100605AA | H | 03/10/2003 | | (NONE) | | | IH5044 (GEN) | 187 |
| 8100605EA | H | 03/10/2003 | 1 | MAXIM INTEG. | | | IH5044MJE/883B | 187 |
| 8100605IA | H | 03/10/2003 | | (NONE) | | | DG5144 (GEN) | 187 |
| 8100606AA | H | 03/10/2003 | | (NONE) | | | IH5045 (GEN) | 188 |
| 8100606EA | H | 03/10/2003 | 1 | MAXIM INTEG. | | | IH5045MJE/883B | 188 |
| 8100606XC | H | 03/10/2003 | 1 | MAXIM INTEG. | | | IH5045MFD/883B | 188 |
| 8100607AA | H | 03/10/2003 | | (NONE) | | | IH5046 (GEN) | 190 |
| 8100607EA | H | 03/10/2003 | | (NONE) | | | IH5046 (GEN) | 190 |
| 8100608AA | H | 03/10/2003 | | (NONE) | | | IH5047 (GEN) | 191 |
| 8100608EA | H | 03/10/2003 | 1 | MAXIM INTEG. | | | IH5047MJE/883B | 191 |
| 8100609EA | H | 03/10/2003 | 1 | MAXIM INTEG. | | | IH5140MJE/883B | 180 |
| 8100609IA | H | 03/10/2003 | | (NONE) | | | DG5140 (GEN) | 180 |
| 8100610EA | H | 03/10/2003 | 1 | MAXIM INTEG. | | | IH5141MJE/883B | 186 |
| 8100610IA | H | 03/10/2003 | | (NONE) | | | DG5141 (GEN) | 186 |
| 8100611EA | H | 03/10/2003 | 1 | MAXIM INTEG. | | | IH5142MJE/883B | 185 |
| 81006122A | H | 03/10/2003 | 1 | INTERSIL | | Y | HI4-5043/883 | 186 |
| 8100612EA | H | 03/10/2003 | 1 | MAXIM INTEG. | | | IH5143MJE/883B | 186 |
| 8100613EA | H | 03/10/2003 | 1 | MAXIM INTEG. | | | IH5144MJE/883B | 187 |
| 8100613IA | H | 03/10/2003 | | (NONE) | | | DG5144 (GEN) | 187 |
| 81006142A | H | 03/10/2003 | | (NONE) | 09/29/1995 | | HI5045 (GEN) | 188 |
| 8100614EA | H | 03/10/2003 | 1 | MAXIM INTEG. | | | IH5145MJE/883B | 188 |
| 8100615EA | H | 03/10/2003 | | (NONE) | 12/24/2000 | | HI-5046 (GEN) | 190 |
| 8100616EA | H | 03/10/2003 | 1 | MAXIM INTEG. | | | IH5047MJE/883B | 191 |
| 8100617EA | H | 03/10/2003 | 1 | INTERSIL | | Y | HI1-5046A/883 | 190 |
| 8100618EA | H | 03/10/2003 | | (NONE) | 12/24/2000 | | HI-5047A (GEN) | 191 |
| 8100619EA | H | 03/10/2003 | | (NONE) | | | IH5148 (GEN) | 181 |
| 81006202A | H | 03/10/2003 | | (NONE) | 09/29/1995 | | HI5049 (GEN) | 188 |
| 8100620EA | H | 03/10/2003 | 1 | MAXIM INTEG. | | | IH5149MJE/883B | 188 |
| 8100621EA | H | 03/10/2003 | 1 | MAXIM INTEG. | | | IH5150MJE/883B | 185 |
| 81006222A | H | 03/10/2003 | 1 | INTERSIL | 10/05/2004 | Y | HI4-5051/883 | 186 |
| 8100622EA | H | 03/10/2003 | 1 | INTERSIL | 10/05/2004 | Y | HI1-5051/883 | 186 |
| 8100622EA | H | 03/10/2003 | 1 | MAXIM INTEG. | | | IH5151MJE/883B | 186 |
| 8100801JA | A | 03/14/1984 | | (NONE) | | | 562 (GEN) | 591 |
| 8100802JA | A | 03/14/1984 | | (NONE) | | | 563 (GEN) | 591 |
| 8101501FA | B | 08/11/1987 | | (NONE) | | | | 617 |
| 8101601EA | E | 04/07/1992 | | (NONE) | 12/03/2002 | | 4029B (GEN) | 319 |
| 8101601FA | E | 04/07/1992 | | (NONE) | | | 4029B (GEN) | 319 |
| 8101602EA | E | 04/07/1992 | 1 | TI | | Y | CD4029BF3A | 319 |
| 8101701EA | F | 05/17/2001 | 1 | TI | | Y | CD4035BF3A | 222 |
| 8101701FA | F | 05/17/2001 | | (NONE) | | | 4035B (GEN) | 222 |
| 8101702EA | F | 05/17/2001 | | (NONE) | | | 14035B (GEN) | 222 |
| 8101801EA | G | 07/09/2003 | 1 | TI | | Y | CD4053BF3A | 199 |
| 8101801FA | G | 07/09/2003 | | (NONE) | | | 4053B (GEN) | 199 |
| 8101802EA | G | 07/09/2003 | | (NONE) | 09/30/1995 | | 4053B (GEN) | 199 |
| 8101803EA | G | 07/09/2003 | | (NONE) | | | 4053B (GEN) | 199 |
| 8101803FA | G | 07/09/2003 | | (NONE) | 06/07/2000 | | 4053B (GEN) | 199 |
| 8101901EA | B | 12/14/1984 | | (NONE) | | | 4042B (GEN) | 340 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 8102001CA | E | 12/12/1994 | 1 | TI | | Y | CD4047BF3A | 165 |
| 8102001DA | E | 12/12/1994 | | (NONE) | | | 4047B (GEN) | 165 |
| 8102002CA | E | 12/12/1994 | | (NONE) | | | 4047B (GEN) | 165 |
| 8102002DA | E | 12/12/1994 | | (NONE) | | | 4047B (GEN) | 165 |
| 81021012A | D | 09/30/2002 | 1 | TI | | Y | SNJ54LS629FK | 815 |
| 8102101EA | D | 09/30/2002 | 1 | TI | | Y | SNJ54LS629J | 815 |
| 8102101FA | D | 09/30/2002 | 1 | TI | | Y | SNJ54LS629W | 815 |
| 81023012A | J | 04/30/2004 | | (NONE) | 12/31/2001 | | TL061 (GEN) | 703 |
| 8102301GA | J | 04/30/2004 | | (NONE) | | | TL061 (GEN) | 703 |
| 8102301HA | J | 04/30/2004 | | (NONE) | | | TL061 (GEN) | 703 |
| 8102301PA | J | 04/30/2004 | | (NONE) | 12/31/2001 | | TL061 (GEN) | 703 |
| 81023022A | J | 04/30/2004 | 2 | TI | | Y | TL062MFKB | 710 |
| 8102302CA | J | 04/30/2004 | | (NONE) | | | TL062 (GEN) | 710 |
| 8102302GA | J | 04/30/2004 | | (NONE) | | | TL062 (GEN) | 710 |
| 8102302HA | J | 04/30/2004 | 2 | TI | | Y | TL062MUB | 710 |
| 8102302PA | J | 04/30/2004 | 2 | TI | | Y | TL062MJGB | 710 |
| 81023032A | J | 04/30/2004 | 2 | TI | | Y | TL064MFKB | 713 |
| 8102303CA | J | 04/30/2004 | 2 | TI | | Y | TL064MJB | 713 |
| 8102303DA | J | 04/30/2004 | 2 | TI | | Y | TL064MWB | 713 |
| 81023042A | J | 04/30/2004 | | (NONE) | 12/31/2001 | | TL071 (GEN) | 703 |
| 8102304GA | J | 04/30/2004 | | (NONE) | | | TL071 (GEN) | 703 |
| 8102304HA | J | 04/30/2004 | | (NONE) | | | TL071 (GEN) | 703 |
| 8102304PA | J | 04/30/2004 | | (NONE) | 12/31/2001 | | TL071 (GEN) | 703 |
| 81023052A | J | 04/30/2004 | 1 | TI | | Y | TL072MFKB | 710 |
| 8102305CA | J | 04/30/2004 | | (NONE) | | | TL072 (GEN) | 710 |
| 8102305GA | J | 04/30/2004 | | (NONE) | | | TL072 (GEN) | 710 |
| 8102305HA | J | 04/30/2004 | 1 | TI | | Y | TL072MUB | 710 |
| 8102305PA | J | 04/30/2004 | 1 | TI | | Y | TL072MJGB | 710 |
| 81023062A | J | 04/30/2004 | 1 | TI | | Y | TL074MFKB | 713 |
| 8102306CA | J | 04/30/2004 | 1 | NATIONAL | | Y | LF147D/883 | 713 |
| 8102306CA | J | 04/30/2004 | 1 | TI | | Y | TL074MJB | 713 |
| 8102306DA | J | 04/30/2004 | 1 | TI | | Y | TL074MWB | 713 |
| 8102401VA | E | 10/12/1993 | | (NONE) | | | | 612 |
| 8102401XA | E | 10/12/1993 | | (NONE) | | | | 612 |
| 8102402VA | E | 10/12/1993 | | (NONE) | 03/25/2001 | | HM-6514S (GEN) | 612 |
| 8102402XA | E | 10/12/1993 | | (NONE) | | | | 612 |
| 8102403VA | E | 10/12/1993 | | TI | | | HM-6504B (GEN) | 612 |
| 8102403XA | E | 10/12/1993 | | (NONE) | | | | 612 |
| 8102404VA | E | 10/12/1993 | | (NONE) | | | | 612 |
| 8102404XA | E | 10/12/1993 | | (NONE) | | | | 612 |
| 8102405VA | E | 10/12/1993 | | (NONE) | | | | 612 |
| 8102405XA | E | 10/12/1993 | | (NONE) | | | | 612 |
| 8102406VA | E | 10/12/1993 | | (NONE) | 03/25/2001 | | HM1-6514 (GEN) | 612 |
| 8102406XA | E | 10/12/1993 | | (NONE) | | | | 612 |
| 8102407YA | E | 10/12/1993 | | (NONE) | | | | 612 |
| 8102408VA | E | 10/12/1993 | | (NONE) | | | 3611143 (GEN) | 612 |
| 8102409VA | E | 10/12/1993 | | (NONE) | | | 3611150 (GEN) | 612 |
| 8102801EA | L | 02/26/2004 | 3 | AGILENT | | Y | 6N134/883B#200 | 460 |
| 8102801EA | L | 02/26/2004 | 1 | MICROPAC | | Y | 66013-001 | 460 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 8102801EC | L | 02/26/2004 | 3 | AGILENT | | Y | 6N134/883B | 460 |
| 8102801EC | L | 02/26/2004 | 1 | MICROPAC | | Y | 66013-001 | 460 |
| 8102801TA | L | 02/26/2004 | 3 | AGILENT | | Y | 6N134/883B#300 | 460 |
| 8102801UA | L | 02/26/2004 | 3 | AGILENT | | Y | 6N134/883B#100 | 460 |
| 8102801UC | L | 02/26/2004 | 3 | AGILENT | | Y | 6N134/883B#100 | 460 |
| 8102801XA | L | 02/26/2004 | 1 | MICROPAC | | Y | 66072-001/883B | 460 |
| 8102801XC | L | 02/26/2004 | 1 | MICROPAC | | Y | 66072-001/883B | 460 |
| 8102802PA | L | 02/26/2004 | 3 | AGILENT | | Y | HCPL-5631#200 | 460 |
| 8102802PA | L | 02/26/2004 | 1 | MICROPAC | | Y | 66056-103 | 460 |
| 8102802PC | L | 02/26/2004 | 3 | AGILENT | | Y | HCPL-5631 | 460 |
| 8102802PC | L | 02/26/2004 | 1 | MICROPAC | | Y | 66056-103 | 460 |
| 8102802YA | L | 02/26/2004 | 3 | AGILENT | | Y | HCPL-5631#100 | 460 |
| 8102802YC | L | 02/26/2004 | 3 | AGILENT | | Y | HCPL-5631#100 | 460 |
| 8102802ZA | L | 02/26/2004 | 3 | AGILENT | | Y | HCPL-5631#300 | 460 |
| 81028032A | L | 02/26/2004 | 3 | AGILENT | | Y | HCPL-6631 | 460 |
| 81028032A | L | 02/26/2004 | 1 | MICROPAC | | Y | 66123-001 | 460 |
| 81028032C | L | 02/26/2004 | 1 | MICROPAC | | Y | 66123-001 | 460 |
| 8102804FC | L | 02/26/2004 | 3 | AGILENT | | Y | HCPL-6651 | 460 |
| 8102805PA | L | 02/26/2004 | 3 | AGILENT | | Y | HCPL-5651#200 | 460 |
| 8102805PC | L | 02/26/2004 | 3 | AGILENT | | Y | HCPL-5651 | 460 |
| 81035012A | E | 06/13/1988 | | (NONE) | | | PAL10H8 (GEN) | 431 |
| 8103501RA | E | 06/13/1988 | | (NONE) | | | PAL10H8 (GEN) | 431 |
| 8103501SA | E | 06/13/1988 | | (NONE) | | | PAL10H8 (GEN) | 431 |
| 81035022A | E | 06/13/1988 | | (NONE) | | | PAL12H6 (GEN) | 431 |
| 8103502RA | E | 06/13/1988 | | (NONE) | | | PAL12H6 (GEN) | 431 |
| 8103502SA | E | 06/13/1988 | | (NONE) | | | PAL12H6 (GEN) | 431 |
| 81035032A | E | 06/13/1988 | | (NONE) | | | PAL14H4 (GEN) | 431 |
| 8103503RA | E | 06/13/1988 | | (NONE) | | | PAL14H4 (GEN) | 431 |
| 8103503SA | E | 06/13/1988 | | (NONE) | | | PAL14H4 (GEN) | 431 |
| 81035042A | E | 06/13/1988 | | (NONE) | | | PAL16H2 (GEN) | 431 |
| 8103504RA | E | 06/13/1988 | | (NONE) | | | PAL16H2 (GEN) | 431 |
| 8103504SA | E | 06/13/1988 | | (NONE) | | | PAL16H2 (GEN) | 431 |
| 81035052A | E | 06/13/1988 | | (NONE) | | | PAL16C1 (GEN) | 431 |
| 8103505RA | E | 06/13/1988 | | (NONE) | | | PAL16C1 (GEN) | 431 |
| 8103505SA | E | 06/13/1988 | | (NONE) | | | PAL16C1 (GEN) | 431 |
| 81035062A | E | 06/13/1988 | | (NONE) | | | PAL10L8 (GEN) | 431 |
| 8103506RA | E | 06/13/1988 | | (NONE) | | | PAL10L8 (GEN) | 431 |
| 8103506SA | E | 06/13/1988 | | (NONE) | | | PAL10L8 (GEN) | 431 |
| 81035072A | E | 06/13/1988 | | (NONE) | | | PAL12L6 (GEN) | 431 |
| 8103507RA | E | 06/13/1988 | | (NONE) | | | PAL12L6 (GEN) | 431 |
| 8103507SA | E | 06/13/1988 | | (NONE) | | | PAL12L6 (GEN) | 431 |
| 81035082A | E | 06/13/1988 | | (NONE) | | | PAL14L4 (GEN) | 431 |
| 8103508RA | E | 06/13/1988 | | (NONE) | | | PAL14L4 (GEN) | 431 |
| 8103508SA | E | 06/13/1988 | | (NONE) | | | PAL14L4 (GEN) | 431 |
| 81035092A | E | 06/13/1988 | | (NONE) | | | PAL16L2 (GEN) | 431 |
| 8103509RA | E | 06/13/1988 | | (NONE) | | | PAL16L2 (GEN) | 431 |
| 8103509SA | E | 06/13/1988 | | (NONE) | | | PAL16L2 (GEN) | 431 |
| 8103510RA | E | 06/13/1988 | | (NONE) | | | PAL10H8A (GEN) | 431 |
| 8103511RA | E | 06/13/1988 | | (NONE) | | | PAL12H6A (GEN) | 431 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 8103512RA | E | 06/13/1988 | | (NONE) | | | PAL14H4A (GEN) | 431 |
| 8103513RA | E | 06/13/1988 | | (NONE) | | | PAL16H2A (GEN) | 431 |
| 8103514RA | E | 06/13/1988 | | (NONE) | | | PAL10L8A (GEN) | 431 |
| 8103515RA | E | 06/13/1988 | | (NONE) | | | PAL12L6A (GEN) | 431 |
| 8103516RA | E | 06/13/1988 | | (NONE) | | | PAL14L4A (GEN) | 431 |
| 8103517RA | E | 06/13/1988 | | (NONE) | | | PAL16L2A (GEN) | 431 |
| 81036012A | K | 09/13/1996 | | (NONE) | | | PAL16L8 (GEN) | 431 |
| 8103601RA | K | 09/13/1996 | | (NONE) | | | PAL16L8 (GEN) | 431 |
| 81036022A | K | 09/13/1996 | | (NONE) | | | PAL16R8 (GEN) | 431 |
| 8103602RA | K | 09/13/1996 | | (NONE) | | | PAL16R8 (GEN) | 431 |
| 81036032A | K | 09/13/1996 | | (NONE) | | | PAL16R6 (GEN) | 431 |
| 8103603RA | K | 09/13/1996 | | (NONE) | | | PAL16R6 (GEN) | 431 |
| 81036042A | K | 09/13/1996 | | (NONE) | | | PAL16R4 (GEN) | 431 |
| 8103604RA | K | 09/13/1996 | | (NONE) | | | PAL16R4 (GEN) | 431 |
| 81036052A | K | 09/13/1996 | | (NONE) | | | PAL16X4 (GEN) | 431 |
| 8103605RA | K | 09/13/1996 | | (NONE) | | | PAL16X4 (GEN) | 431 |
| 81036062A | K | 09/13/1996 | | (NONE) | | | PAL16A4 (GEN) | 431 |
| 8103606RA | K | 09/13/1996 | | (NONE) | | | PAL16A4 (GEN) | 431 |
| 81036072A | K | 09/13/1996 | 2 | TI | | Y | PAL16L8AMFKB | 431 |
| 8103607RA | K | 09/13/1996 | I | TI | | Y | PAL16L8AMJB | 431 |
| 8103607SA | K | 09/13/1996 | 2 | TI | | Y | PAL16L8AMWB | 431 |
| 81036082A | K | 09/13/1996 | 0 | TI | | Y | PAL16R8AMFKB | 431 |
| 8103608RA | K | 09/13/1996 | I | TI | | Y | PAL16R8AMJB | 431 |
| 8103608SA | K | 09/13/1996 | 0 | TI | | Y | PAL16R8AMWB | 431 |
| 81036092A | K | 09/13/1996 | 0 | TI | | Y | PAL16R6AMFKB | 431 |
| 8103609RA | K | 09/13/1996 | I | TI | | Y | PAL16R6AMJB | 431 |
| 8103609SA | K | 09/13/1996 | 0 | TI | | Y | PAL16R6AMWB | 431 |
| 81036102A | K | 09/13/1996 | 0 | TI | | Y | PAL16R4AMFKB | 431 |
| 8103610RA | K | 09/13/1996 | I | TI | | Y | PAL16R4AMJB | 431 |
| 8103610SA | K | 09/13/1996 | 0 | TI | | Y | PAL16R4AMWB | 431 |
| 81036112A | K | 09/13/1996 | 0 | TI | | Y | PAL16L8A-2MFKB | 431 |
| 8103611RA | K | 09/13/1996 | I | TI | | Y | PAL16L8A-2MJB | 431 |
| 8103611SA | K | 09/13/1996 | 0 | TI | | Y | PAL16L8A-2MWB | 431 |
| 81036122A | K | 09/13/1996 | 0 | TI | | Y | PAL16R8A-2MFKB | 431 |
| 8103612RA | K | 09/13/1996 | I | TI | | Y | PAL16R8A-2MJB | 431 |
| 8103612SA | K | 09/13/1996 | 0 | TI | | Y | PAL16R8A-2MWB | 431 |
| 81036132A | K | 09/13/1996 | 0 | TI | | Y | PAL16R6A-2MFKB | 431 |
| 8103613RA | K | 09/13/1996 | I | TI | | Y | PAL16R6A-2MJB | 431 |
| 8103613SA | K | 09/13/1996 | 0 | TI | | Y | PAL16R6A-2MWB | 431 |
| 81036142A | K | 09/13/1996 | 1 | TI | | Y | PAL16R4A-2MFKB | 431 |
| 8103614RA | K | 09/13/1996 | I | TI | | Y | PAL16R4A-2MJB | 431 |
| 8103614SA | K | 09/13/1996 | 1 | TI | | Y | PAL16R4A-2MWB | 431 |
| 8103901JA | F | 06/26/1996 | | (NONE) | | | | 616 |
| 8103901ZA | F | 06/26/1996 | | (NONE) | | | | 616 |
| 8103902JA | F | 06/26/1996 | | (NONE) | | | | 616 |
| 8103902ZA | F | 06/26/1996 | | (NONE) | | | | 616 |
| 8103903JA | F | 06/26/1996 | | (NONE) | | | | 616 |
| 8103903ZA | F | 06/26/1996 | | (NONE) | | | | 616 |
| 8103904JA | F | 06/26/1996 | | (NONE) | | | | 616 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 8103904ZA | F | 06/26/1996 | | (NONE) | | | | 616 |
| 8103905JA | F | 06/26/1996 | | (NONE) | | | | 616 |
| 8103905ZA | F | 06/26/1996 | | (NONE) | | | | 616 |
| 8103906JA | F | 06/26/1996 | | (NONE) | | | 9128-90 (GEN) | 616 |
| 8103907JA | F | 06/26/1996 | | (NONE) | | | 9128-12 (GEN) | 616 |
| 8103908JA | F | 06/26/1996 | | (NONE) | | | 9128-20 (GEN) | 616 |
| 8200501YA | D | 08/31/1987 | | (NONE) | | | 2764-450 (GEN) | 660 |
| 8200501ZA | D | 08/31/1987 | | (NONE) | | | 2764-450 (GEN) | 660 |
| 8200502YA | D | 08/31/1987 | | (NONE) | | | 2764-250 (GEN) | 660 |
| 8200502ZA | D | 08/31/1987 | | (NONE) | | | 2764-250 (GEN) | 660 |
| 8200503YA | D | 08/31/1987 | | (NONE) | 04/15/1994 | | 2764A-35 (GEN) | 660 |
| 8200503ZA | D | 08/31/1987 | | (NONE) | 04/15/1994 | | 2764A-35 (GEN) | 660 |
| 8200504YA | D | 08/31/1987 | | (NONE) | 04/15/1994 | | 2764A-25 (GEN) | 660 |
| 8200504ZA | D | 08/31/1987 | | (NONE) | 04/15/1994 | | 2764A-25 (GEN) | 660 |
| 8200505YA | D | 08/31/1987 | | (NONE) | | | 2764A-20 (GEN) | 660 |
| 8200505ZA | D | 08/31/1987 | | (NONE) | | | 2764A-20 (GEN) | 660 |
| 8200506YA | D | 08/31/1987 | | (NONE) | | | 2764-150 (GEN) | 660 |
| 8200507YA | D | 08/31/1987 | | (NONE) | | | 2764-200 (GEN) | 660 |
| 8200701RA | B | 10/07/1988 | | (NONE) | | | 4167 (GEN) | 616 |
| 8200702RA | B | 10/07/1988 | | (NONE) | | | 2167-70 (GEN) | 616 |
| 8200702XA | B | 10/07/1988 | | (NONE) | | | 2167-70 (GEN) | 616 |
| 8200703RA | B | 10/07/1988 | | (NONE) | | | 2167-55 (GEN) | 616 |
| 8200703XA | B | 10/07/1988 | | (NONE) | | | 2167-55 (GEN) | 616 |
| 8200704RA | B | 10/07/1988 | | (NONE) | | | 2167-45 (GEN) | 616 |
| 8200704XA | B | 10/07/1988 | | (NONE) | | | 2167-40 (GEN) | 616 |
| 82008013A | J | 05/29/1997 | 1 | LANSDALE | | Y | SL82HS32131 | 659 |
| 82008013A | J | 05/29/1997 | 1 | QP SEMI | | Y | R29771 | 659 |
| 8200801JA | J | 05/29/1997 | 1 | LANSDALE | | Y | SL82HS321J1 | 659 |
| 8200801JA | J | 05/29/1997 | 1 | QP SEMI | | Y | R29771 | 659 |
| 8200801KA | J | 05/29/1997 | 1 | LANSDALE | | Y | SL82HS321K1 | 659 |
| 8200801LA | J | 05/29/1997 | 1 | QP SEMI | | Y | R29771 | 659 |
| 8200801XA | J | 05/29/1997 | 1 | QP SEMI | | Y | R29771 | 659 |
| 82008023A | J | 05/29/1997 | 1 | LANSDALE | | Y | SL82HS32131 | 659 |
| 82008023A | J | 05/29/1997 | 3 | QP SEMI | | Y | 82HS321A/B3A | 659 |
| 8200802JA | J | 05/29/1997 | 1 | LANSDALE | | Y | SL82HS321J1 | 659 |
| 8200802JA | J | 05/29/1997 | 3 | QP SEMI | | Y | 82HS321A/BJA | 659 |
| 8200802KA | J | 05/29/1997 | 1 | LANSDALE | | Y | SL82HS321K1 | 659 |
| 8200802KA | J | 05/29/1997 | 3 | QP SEMI | | Y | 82HS321A/BKA | 659 |
| 8200802XA | J | 05/29/1997 | | (NONE) | | | 27S43A (GEN) | 659 |
| 82008033A | J | 05/29/1997 | | LANSDALE | | Y | SL82HS321K1 | 659 |
| 8200803JA | J | 05/29/1997 | | LANSDALE | | Y | SL82HS321J1 | 659 |
| 8200803JA | J | 05/29/1997 | 3 | QP SEMI | | Y | 82HS321A/BJA | 659 |
| 8200803KA | J | 05/29/1997 | | LANSDALE | | Y | SL82HS321K1 | 659 |
| 8200803KA | J | 05/29/1997 | 3 | QP SEMI | | Y | 82HS321A/BKA | 659 |
| 82008043A | J | 05/29/1997 | | (NONE) | | | (SEE DWG) (GEN) | 659 |
| 8200804JA | J | 05/29/1997 | | (NONE) | | | (SEE DWG) (GEN) | 659 |
| 8200804KC | J | 05/29/1997 | | (NONE) | | | 29771 (GEN) | 659 |
| 8200804LA | J | 05/29/1997 | | (NONE) | | | 29771 (GEN) | 659 |
| 82009013A | J | 05/12/1997 | 1 | QP SEMI | | Y | R29791 | 660 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 8200901JA | J | 05/12/1997 | 1 | QP SEMI | | Y | R29791 | 660 |
| 8200901KA | J | 05/12/1997 | 1 | QP SEMI | | Y | R29791 | 660 |
| 8200901LA | J | 05/12/1997 | 1 | QP SEMI | | Y | R29791 | 660 |
| 8200901LC | J | 05/12/1997 | 1 | QP SEMI | | Y | R29791 | 660 |
| 8200901XA | J | 05/12/1997 | 1 | QP SEMI | | Y | R29791 | 660 |
| 8200901XC | J | 05/12/1997 | 1 | QP SEMI | | Y | R29791 | 660 |
| 8200901ZA | J | 05/12/1997 | 1 | QP SEMI | | Y | R29791 | 660 |
| 82009023A | J | 05/12/1997 | | (NONE) | 06/01/1997 | | 82HS641A (GEN) | 660 |
| 8200902JA | J | 05/12/1997 | | (NONE) | | | 82HS641A (GEN) | 660 |
| 8200902KA | J | 05/12/1997 | | (NONE) | 08/02/1996 | | 27S49A (GEN) | 660 |
| 8200902LA | J | 05/12/1997 | | (NONE) | | | 93667-55 (GEN) | 660 |
| 8200902ZA | J | 05/12/1997 | | (NONE) | | | 27S49A (GEN) | 660 |
| 82009033A | J | 05/12/1997 | | (NONE) | | | 82HS641B (GEN) | 660 |
| 8200903JA | J | 05/12/1997 | | (NONE) | | | 82HS641B (GEN) | 660 |
| 8200903LA | J | 05/12/1997 | | (NONE) | | | 93667-45 (GEN) | 660 |
| 8201001EA | F | 12/22/2000 | I | ATMEL GREN. | | | MKB4564P-82 | 621 |
| 8201002EA | F | 12/22/2000 | I | ATMEL GREN. | | | MKB4564P-82 | 621 |
| 8201003EA | F | 12/22/2000 | I | ATMEL GREN. | | | MKB4564P-83 | 621 |
| 8201004EA | F | 12/22/2000 | | (NONE) | | | 4264-15 (GEN) | 621 |
| 8201004ZA | F | 12/22/2000 | | (NONE) | | | 4264-15 (GEN) | 621 |
| 8201005EA | F | 12/22/2000 | | (NONE) | | | 4264-20 (GEN) | 621 |
| 8201005ZA | F | 12/22/2000 | | (NONE) | | | 4264-20 (GEN) | 621 |
| 8201006EA | F | 12/22/2000 | 1 | ROCHESTER | | Y | 4164-15JDS/BEA | 621 |
| 8201006ZA | F | 12/22/2000 | | (NONE) | 09/15/1995 | | 4164-15 (GEN) | 621 |
| 8201007EA | F | 12/22/2000 | 1 | ROCHESTER | | Y | 4164-20JDS/BEA | 621 |
| 8201007ZA | F | 12/22/2000 | | (NONE) | 09/15/1995 | | 4164-20 (GEN) | 621 |
| 8201008EA | F | 12/22/2000 | 1 | ROCHESTER | | Y | 4164-12JDS/BEA | 621 |
| 8201008ZA | F | 12/22/2000 | | (NONE) | 09/15/1995 | | 4164-12 (GEN) | 621 |
| 8201009EA | F | 12/22/2000 | | (NONE) | | | 9064-15 (GEN) | 621 |
| 8201010EA | F | 12/22/2000 | | (NONE) | | | 9064-15 (GEN) | 621 |
| 8202101TA | F | 10/05/1992 | | (NONE) | | | 68000-6 (GEN) | 403 |
| 8202101YA | F | 10/05/1992 | | (NONE) | | | 68000-6 (GEN) | 403 |
| 8202101ZA | F | 10/05/1992 | | (NONE) | | | 68000-6 (GEN) | 403 |
| 8202102TA | F | 10/05/1992 | | (NONE) | | | 68000-8 (GEN) | 403 |
| 8202102UC | F | 10/05/1992 | | (NONE) | 09/30/1995 | | 68000-8 (GEN) | 403 |
| 8202102XA | F | 10/05/1992 | | (NONE) | 09/30/1995 | | 68000-8 (GEN) | 403 |
| 8202102YA | F | 10/05/1992 | | (NONE) | | | 68000-8 (GEN) | 403 |
| 8202102ZA | F | 10/05/1992 | | (NONE) | | | 68000-8 (GEN) | 403 |
| 8202103TA | F | 10/05/1992 | | (NONE) | | | 68000-10 (GEN) | 403 |
| 8202103UC | F | 10/05/1992 | | (NONE) | 09/30/1995 | | 68000-10 (GEN) | 403 |
| 8202103XA | F | 10/05/1992 | | (NONE) | 09/30/1995 | | 68000-10 (GEN) | 403 |
| 8202103YA | F | 10/05/1992 | | (NONE) | | | 68000-10 (GEN) | 403 |
| 8202103ZA | F | 10/05/1992 | | (NONE) | | | 68000-10 (GEN) | 403 |
| 8202104TA | F | 10/05/1992 | | (NONE) | | | 68000-12 (GEN) | 403 |
| 8202104XA | F | 10/05/1992 | | (NONE) | | | 68000-12 (GEN) | 403 |
| 8202104YA | F | 10/05/1992 | | (NONE) | | | 68000-12 (GEN) | 403 |
| 8202104ZA | F | 10/05/1992 | | (NONE) | | | 68000-12 (GEN) | 403 |
| 8202201EA | A | 05/07/2001 | | (NONE) | 03/04/2003 | | 40174B (GEN) | 159 |
| 8202201FA | A | 05/07/2001 | | (NONE) | 06/08/1999 | | 40174B (GEN) | 159 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 8202501YA | G | 09/05/2002 | | (NONE) | | | 27128-450 (GEN) | 661 |
| 8202501ZA | G | 09/05/2002 | | (NONE) | | | 27128-450 (GEN) | 661 |
| 8202502YA | G | 09/05/2002 | | (NONE) | | | 27128-250 (GEN) | 661 |
| 8202502ZA | G | 09/05/2002 | | (NONE) | | | 27128-250 (GEN) | 661 |
| 8202503YA | G | 09/05/2002 | 1 | ROCHESTER | | Y | MC27128A-20/BYA | 661 |
| 8202503ZA | G | 09/05/2002 | 1 | ROCHESTER | | Y | MR27128A-20/BZA | 661 |
| 8202504YA | G | 09/05/2002 | 1 | ROCHESTER | | Y | MC27128A-30/BYA | 661 |
| 8202504ZA | G | 09/05/2002 | 1 | ROCHESTER | | Y | MR27128A-30/BZA | 661 |
| 8202505YA | G | 09/05/2002 | 1 | ROCHESTER | | Y | MC27128A-25/BYA | 661 |
| 8202505ZA | G | 09/05/2002 | 1 | ROCHESTER | | Y | MR27128A-25/BZA | 661 |
| 8202506YA | G | 09/05/2002 | 1 | ROCHESTER | | Y | MC27128A-15/BYA | 661 |
| 8202506ZA | G | 09/05/2002 | 1 | ROCHESTER | | Y | MR27128A-15/BZA | 661 |
| 8202507YA | G | 09/05/2002 | 1 | ROCHESTER | | Y | MC27128A-11/BYA | 661 |
| 8202507ZA | G | 09/05/2002 | 1 | ROCHESTER | | Y | MR27128A-11/BZA | 661 |
| 8202508YA | G | 09/05/2002 | | (NONE) | | | 27128-200 (GEN) | 661 |
| 8202508ZA | G | 09/05/2002 | | (NONE) | | | 27128-200 (GEN) | 661 |
| 8202509YA | G | 09/05/2002 | | (NONE) | | | 27128-300 (GEN) | 661 |
| 8202509ZA | G | 09/05/2002 | | (NONE) | | | 27128-300 (GEN) | 661 |
| 82036012A | D | 07/13/1993 | | (NONE) | 04/14/2001 | | OP07A (GEN) | 701 |
| 8203601GA | D | 07/13/1993 | | (NONE) | 04/14/2001 | | OP07A (GEN) | 701 |
| 8203601PA | D | 07/13/1993 | | (NONE) | 04/14/2001 | | OP07A (GEN) | 701 |
| 82036022A | D | 07/13/1993 | | (NONE) | 04/14/2001 | | OP07 (GEN) | 701 |
| 8203602GA | D | 07/13/1993 | | (NONE) | 04/14/2001 | | OP07 (GEN) | 701 |
| 8203602PA | D | 07/13/1993 | | (NONE) | 04/14/2001 | | OP07 (GEN) | 701 |
| 8300101QA | C | 01/27/1988 | 1 | QP SEMI | | | Z0853604CMB | 421 |
| 8300101YA | C | 01/27/1988 | 1 | QP SEMI | | | Z0853604LMB | 421 |
| 8300102QA | C | 01/27/1988 | 1 | QP SEMI | | | Z0853606CMB | 421 |
| 8300102YA | C | 01/27/1988 | 1 | QP SEMI | | | Z0853606LMB | 421 |
| 8300201JA | G | 10/29/2002 | | (NONE) | 08/29/2003 | | DAC87 (GEN) | 591 |
| 8300201JC | G | 10/29/2002 | | (NONE) | 08/29/2003 | | DAC87 (GEN) | 591 |
| 8300201XA | G | 10/29/2002 | | (NONE) | | | DAC87 (GEN) | 591 |
| 8300301JA | B | 11/02/1992 | 1 | ANALOG (2) | | Y | ADDAC87D-CBI-V/883 | 591 |
| 8301301QA | D | 04/13/1995 | | (NONE) | 06/03/1997 | | NSC800 (GEN) | 402 |
| 8301301ZA | D | 04/13/1995 | | (NONE) | 06/03/1997 | | NSC800 (GEN) | 402 |
| 8301302QA | D | 04/13/1995 | | (NONE) | 06/03/1997 | | NSC800 (GEN) | 402 |
| 8301302ZA | D | 04/13/1995 | | (NONE) | 06/03/1997 | | NSC800 (GEN) | 402 |
| 8301501QA | D | 01/21/1989 | | (NONE) | | | Z8442A (GEN) | 420 |
| 8301502QA | D | 01/21/1989 | | (NONE) | | | Z8442 (GEN) | 420 |
| 8301601XA | D | 01/21/1989 | | (NONE) | | | Z8430A (GEN) | 424 |
| 8301602XA | D | 01/21/1989 | | (NONE) | | | Z8430 (GEN) | 424 |
| 83017013A | F | 02/05/1992 | 1 | LANSDALE | | Y | SL54LS154/B3A | 280 |
| 83017013C | F | 02/05/1992 | 1 | LANSDALE | | Y | SL54LS154/B2C | 280 |
| 8301701JA | F | 02/05/1992 | 1 | LANSDALE | | Y | SL54LS154/BJA | 280 |
| 8301701KA | F | 02/05/1992 | 1 | LANSDALE | | Y | SL54LS154/BKA | 280 |
| 83019012A | F | 07/10/1992 | I | TI | | Y | SNJ54ALS174FK | 159 |
| 8301901EA | F | 07/10/1992 | I | TI | | Y | SNJ54ALS174J | 159 |
| 8301901FA | F | 07/10/1992 | 2 | TI | | Y | SNJ54ALS174W | 159 |
| 83019022A | F | 07/10/1992 | I | TI | | Y | SNJ54ALS175FK | 159 |
| 8301902EA | F | 07/10/1992 | I | TI | | Y | SNJ54ALS175J | 159 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 8301902FA | F | 07/10/1992 | 2 | TI | | Y | SNJ54ALS175W | 159 |
| 83020012A | F | 10/28/1997 | 2 | TI | | Y | SNJ54ALS373AFK | 159 |
| 8302001RA | F | 10/28/1997 | 2 | TI | | Y | SNJ54ALS373AJ | 159 |
| 8302001SA | F | 10/28/1997 | 2 | TI | | Y | SNJ54ALS373AW | 159 |
| 83020022A | F | 10/28/1997 | 2 | TI | | Y | SNJ54ALS374AFK | 159 |
| 8302002RA | F | 10/28/1997 | 2 | TI | | Y | SNJ54ALS374AJ | 159 |
| 8302002SA | F | 10/28/1997 | 2 | TI | | Y | SNJ54ALS374AW | 159 |
| 83021012A | G | 10/09/2002 | 1 | TI | | Y | SNJ54ALS299FK | 228 |
| 8302101RA | G | 10/09/2002 | 1 | TI | | Y | SNJ54ALS299J | 228 |
| 8302101SA | G | 10/09/2002 | 1 | TI | | Y | SNJ54ALS299W | 228 |
| 83021022A | G | 10/09/2002 | 1 | TI | | Y | SNJ54ALS323FK | 228 |
| 8302102RA | G | 10/09/2002 | 1 | TI | | Y | SNJ54ALS323J | 228 |
| 8302102SA | G | 10/09/2002 | 1 | TI | | Y | SNJ54ALS323W | 228 |
| 83022012A | H | 07/25/2002 | I | TI | | Y | SNJ54ALS161BFK | 304 |
| 8302201EA | H | 07/25/2002 | I | TI | | Y | SNJ54ALS161BJ | 304 |
| 8302201FA | H | 07/25/2002 | 3 | TI | | Y | SNJ54ALS161BW | 304 |
| 83022022A | H | 07/25/2002 | I | TI | | Y | SNJ54ALS163BFK | 304 |
| 8302202EA | H | 07/25/2002 | I | TI | | Y | SNJ54ALS163BJ | 304 |
| 8302202FA | H | 07/25/2002 | 2 | TI | | Y | SNJ54ALS163BW | 304 |
| 83022032A | H | 07/25/2002 | | (NONE) | | | 54ALS561A (GEN) | 304 |
| 8302203RA | H | 07/25/2002 | | (NONE) | 12/31/2001 | | 54ALS561A (GEN) | 304 |
| 8302203SA | H | 07/25/2002 | | (NONE) | | | 54ALS561A (GEN) | 304 |
| 8302401EA | J | 07/01/2002 | 3 | AGILENT | | Y | 6N140A/883B#200 | 460 |
| 8302401EA | J | 07/01/2002 | 1 | MICROPAC | | Y | 6N140A | 460 |
| 8302401EC | J | 07/01/2002 | 3 | AGILENT | | Y | 6N140A/883B | 460 |
| 8302401EC | J | 07/01/2002 | 1 | MICROPAC | | Y | 6N140A | 460 |
| 8302401FC | J | 07/01/2002 | 3 | AGILENT | | Y | HCPL-6751 | 460 |
| 8302401XA | J | 07/01/2002 | 3 | AGILENT | | Y | 6N140A/883B#300 | 460 |
| 8302401XA | J | 07/01/2002 | 1 | MICROPAC | | Y | 6N140A | 460 |
| 8302401YA | J | 07/01/2002 | 3 | AGILENT | | Y | 6N140A/883B#100 | 460 |
| 8302401YC | J | 07/01/2002 | 3 | AGILENT | | Y | 6N140A/883B#100 | 460 |
| 8302401ZA | J | 07/01/2002 | 3 | AGILENT | | Y | 6N140A/883B#600 | 460 |
| 8302401ZC | J | 07/01/2002 | 3 | AGILENT | | Y | 6N140A/883B#600 | 460 |
| 83025012A | G | 07/31/2002 | 0 | TI | | Y | SNJ54ALS169BFK | 304 |
| 8302501EA | G | 07/31/2002 | I | TI | | Y | SNJ54ALS169BJ | 304 |
| 8302501FA | G | 07/31/2002 | 0 | TI | | Y | SNJ54ALS169BW | 304 |
| 83025022A | G | 07/31/2002 | 1 | TI | | Y | SNJ54ALS569AFK | 304 |
| 8302502RA | G | 07/31/2002 | 1 | TI | | Y | SNJ54ALS569AJ | 304 |
| 8302502SA | G | 07/31/2002 | 1 | TI | | Y | SNJ54ALS569AW | 304 |
| 84000012A | C | 07/07/1992 | 3 | TI | | Y | SNJ54ALS109AFK | 152 |
| 8400001EA | C | 07/07/1992 | 3 | TI | | Y | SNJ54ALS109AJ | 152 |
| 8400001FA | C | 07/07/1992 | 3 | TI | | Y | SNJ54ALS109AW | 152 |
| 84000022A | C | 07/07/1992 | 1 | TI | | Y | SNJ54ALS112AFK | 156 |
| 8400002EA | C | 07/07/1992 | I | TI | | Y | SNJ54ALS112AJ | 156 |
| 8400002FA | C | 07/07/1992 | 1 | TI | | Y | SNJ54ALS112AW | 156 |
| 84001012A | J | 07/29/2002 | 2 | TI | | Y | SNJ54ALS574BFK | 159 |
| 8400101RA | J | 07/29/2002 | 2 | TI | | Y | SNJ54ALS574BJ | 159 |
| 8400101SA | J | 07/29/2002 | 2 | TI | | Y | SNJ54ALS574BW | 159 |
| 84001022A | J | 07/29/2002 | 2 | TI | | Y | SNJ54ALS576BFK | 159 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 8400102RA | J | 07/29/2002 | 2 | TI | | Y | SNJ54ALS576BJ | 159 |
| 8400102SA | J | 07/29/2002 | 2 | TI | | Y | SNJ54ALS576BW | 159 |
| 84010013A | C | 08/08/2002 | 2 | TI | | Y | SNJ54ALS874BFK | 158 |
| 8401001KA | C | 08/08/2002 | 2 | TI | | Y | SNJ54ALS874BW | 158 |
| 8401001LA | C | 08/08/2002 | 2 | TI | | Y | SNJ54ALS874BJT | 158 |
| 84010023A | C | 08/08/2002 | | (NONE) | | | 54ALS876 (GEN) | 158 |
| 8401002KA | C | 08/08/2002 | | (NONE) | | | 54ALS876 (GEN) | 158 |
| 8401002LA | C | 08/08/2002 | | (NONE) | | | 54ALS876 (GEN) | 158 |
| 84011012A | F | 07/29/2002 | I | TI | | Y | SNJ54ALS74AFK | 158 |
| 8401101AA | F | 07/29/2002 | | (NONE) | | | 54ALS74A (GEN) | 158 |
| 8401101BA | F | 07/29/2002 | | (NONE) | | | 54ALS74A (GEN) | 158 |
| 8401101CA | F | 07/29/2002 | I | TI | | Y | SNJ54ALS74AJ | 158 |
| 8401101DA | F | 07/29/2002 | 2 | TI | | Y | SNJ54ALS74AW | 158 |
| 84012012A | F | 08/19/2002 | 2 | TI | | Y | SNJ54ALS573CFK | 341 |
| 8401201RA | F | 08/19/2002 | 2 | TI | | Y | SNJ54ALS573CJ | 341 |
| 8401201SA | F | 08/19/2002 | 2 | TI | | Y | SNJ54ALS573CW | 341 |
| 84012022A | F | 08/19/2002 | 2 | TI | | Y | SNJ54ALS580BFK | 341 |
| 8401202RA | F | 08/19/2002 | 2 | TI | | Y | SNJ54ALS580BJ | 341 |
| 8401202SA | F | 08/19/2002 | 2 | TI | | Y | SNJ54ALS580BW | 341 |
| 84013012A | E | 10/05/1992 | | (NONE) | | | 54ALS242B (GEN) | 590 |
| 8401301CA | E | 10/05/1992 | | (NONE) | | | 54ALS242B (GEN) | 590 |
| 8401301DA | E | 10/05/1992 | | (NONE) | | | 54ALS242B (GEN) | 590 |
| 84013022A | E | 10/05/1992 | 2 | TI | | Y | SNJ54ALS243AFK | 590 |
| 8401302CA | E | 10/05/1992 | 2 | TI | | Y | SNJ54ALS243AJ | 590 |
| 8401302DA | E | 10/05/1992 | 2 | TI | | Y | SNJ54ALS243AW | 590 |
| 84030012A | D | 08/19/1992 | 2 | TI | | Y | SNJ54ALS245AFK | 590 |
| 8403001RA | D | 08/19/1992 | 2 | TI | | Y | SNJ54ALS245AJ | 590 |
| 8403001SA | D | 08/19/1992 | 2 | TI | | Y | SNJ54ALS245AW | 590 |
| 84031012A | C | 10/05/1992 | 2 | TI | | Y | SNJ54ALS1034FK | 513 |
| 8403101BA | C | 10/05/1992 | 2 | TI | | Y | SNJ54ALS1034WA | 513 |
| 8403101CA | C | 10/05/1992 | I | TI | | Y | SNJ54ALS1034J | 513 |
| 8403101DA | C | 10/05/1992 | 2 | TI | | Y | SNJ54ALS1034W | 513 |
| 84032013A | B | 09/11/1987 | 2 | TI | | Y | SNJ54ALS873FK | 341 |
| 8403201KA | B | 09/11/1987 | 2 | TI | | Y | SNJ54ALS873W | 341 |
| 8403201LA | B | 09/11/1987 | 2 | TI | | Y | SNJ54ALS873JT | 341 |
| 84032023A | B | 09/11/1987 | | (NONE) | | | 54ALS880 (GEN) | 341 |
| 8403202KA | B | 09/11/1987 | | (NONE) | | | 54ALS880 (GEN) | 341 |
| 8403202LA | B | 09/11/1987 | | (NONE) | | | 54ALS880 (GEN) | 341 |
| 84033012A | C | 07/10/1992 | 2 | TI | | Y | SNJ54ALS645AFK | 590 |
| 8403301RA | C | 07/10/1992 | 2 | TI | | Y | SNJ54ALS645AJ | 590 |
| 8403301SA | C | 07/10/1992 | 2 | TI | | Y | SNJ54ALS645AW | 590 |
| 8403601JA | F | 09/27/2000 | | (NONE) | 03/25/2001 | | HM-6516 (GEN) | 616 |
| 8403601ZA | F | 09/27/2000 | | (NONE) | 03/25/2001 | | HM-6516 (GEN) | 616 |
| 8403602JA | F | 09/27/2000 | 1 | INTERSIL | | Y | HM1-65162/883 | 616 |
| 8403602ZA | F | 09/27/2000 | 1 | INTERSIL | 10/05/2004 | Y | HM4-65162/883 | 616 |
| 8403603JA | F | 09/27/2000 | 1 | INTERSIL | 10/05/2004 | Y | HM1-65162C/883 | 616 |
| 8403603ZA | F | 09/27/2000 | | (NONE) | | | 65162C (GEN) | 616 |
| 8403604JA | F | 09/27/2000 | | (NONE) | | | 6116-82 (GEN) | 616 |
| 8403604ZA | F | 09/27/2000 | | (NONE) | | | | 616 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 8403605JA | F | 09/27/2000 | | (NONE) | | | 6116-83 (GEN) | 616 |
| 8403605ZA | F | 09/27/2000 | | (NONE) | | | | 616 |
| 8403606JA | F | 09/27/2000 | 1 | INTERSIL | | Y | HM1-65162B/883 | 616 |
| 8403606ZA | F | 09/27/2000 | | (NONE) | | | | 616 |
| 8403607JA | F | 09/27/2000 | | (NONE) | 09/24/2000 | | 6516B (GEN) | 616 |
| 8403607ZA | F | 09/27/2000 | | (NONE) | | | | 616 |
| 84036083A | F | 09/27/2000 | | (NONE) | 05/06/1997 | | 6116LA45 (GEN) | 616 |
| 8403608JA | F | 09/27/2000 | 1 | IDT | | Y | IDT6116LA45DB | 616 |
| 8403608KA | F | 09/27/2000 | | (NONE) | 01/01/1999 | | 6116LA45 (GEN) | 616 |
| 8403608LA | F | 09/27/2000 | 1 | IDT | | Y | IDT6116LA45TDB | 616 |
| 8403608XA | F | 09/27/2000 | | (NONE) | 05/06/1997 | | 6116LA45 (GEN) | 616 |
| 8403608YA | F | 09/27/2000 | | (NONE) | | | | 616 |
| 84036093A | F | 09/27/2000 | 1 | PYRAMID | | | P4C116-45L28MB | 616 |
| 84036093A | F | 09/27/2000 | 2 | QP SEMI | | Y | QP6116A-45LMB | 616 |
| 8403609JA | F | 09/27/2000 | 1 | IDT | | Y | IDT6116SA45DB | 616 |
| 8403609JA | F | 09/27/2000 | 2 | QP SEMI | | Y | QP6116A-45DMB | 616 |
| 8403609KA | F | 09/27/2000 | 1 | PYRAMID | | | P4C116-45FMB | 616 |
| 8403609KA | F | 09/27/2000 | 2 | QP SEMI | | Y | QP7C128A-45KMB | 616 |
| 8403609LA | F | 09/27/2000 | 1 | IDT | | Y | IDT6116SA45TDB | 616 |
| 8403609LA | F | 09/27/2000 | 1 | PYRAMID | | | P4C116-45DMB | 616 |
| 8403609LA | F | 09/27/2000 | 2 | QP SEMI | | Y | QP7C128A-45DMB | 616 |
| 8403609XA | F | 09/27/2000 | 2 | QP SEMI | | Y | QP6117A-45LMB | 616 |
| 8403609YA | F | 09/27/2000 | 1 | PYRAMID | | | P4C116-45LMB | 616 |
| 8403609YA | F | 09/27/2000 | 2 | QP SEMI | | Y | QP7C128A-45LMB | 616 |
| 84036103A | F | 09/27/2000 | 1 | QP SEMI | | Y | 6116-55/3A | 616 |
| 8403610JA | F | 09/27/2000 | 1 | IDT | | Y | IDT6116LA55DB | 616 |
| 8403610KA | F | 09/27/2000 | 1 | QP SEMI | | Y | 6116-55/KA | 616 |
| 8403610LA | F | 09/27/2000 | 1 | IDT | | Y | IDT6116LA55TDB | 616 |
| 8403610XA | F | 09/27/2000 | 1 | QP SEMI | | Y | 6116-55/XA | 616 |
| 8403610YA | F | 09/27/2000 | 1 | QP SEMI | | Y | 6116-55/YA | 616 |
| 84036113A | F | 09/27/2000 | 1 | PYRAMID | | | P4C116-55L28MB | 616 |
| 84036113A | F | 09/27/2000 | 2 | QP SEMI | | Y | QP6116A-55LMB | 616 |
| 8403611JA | F | 09/27/2000 | 1 | IDT | | Y | IDT6116SA55DB | 616 |
| 8403611JA | F | 09/27/2000 | 2 | QP SEMI | | Y | QP6116A-55DMB | 616 |
| 8403611KA | F | 09/27/2000 | 1 | PYRAMID | | | P4C116-55FMB | 616 |
| 8403611KA | F | 09/27/2000 | 2 | QP SEMI | | Y | QP7C128A-55KMB | 616 |
| 8403611LA | F | 09/27/2000 | 1 | IDT | | Y | IDT6116SA55TDB | 616 |
| 8403611LA | F | 09/27/2000 | 1 | PYRAMID | | | P4C116-55DMB | 616 |
| 8403611LA | F | 09/27/2000 | 2 | QP SEMI | | Y | QP7C128A-55DMB | 616 |
| 8403611XA | F | 09/27/2000 | 2 | QP SEMI | | Y | QP6117A-55LMB | 616 |
| 8403611YA | F | 09/27/2000 | 1 | PYRAMID | | | P4C116-55LMB | 616 |
| 8403611YA | F | 09/27/2000 | 2 | QP SEMI | | Y | QP7C128A-55LMB | 616 |
| 84036123A | F | 09/27/2000 | | (NONE) | 05/06/1997 | | 6116LA70 (GEN) | 616 |
| 8403612JA | F | 09/27/2000 | 1 | IDT | | Y | IDT6116LA70DB | 616 |
| 8403612KA | F | 09/27/2000 | | (NONE) | 01/01/1999 | | 6116LA70 (GEN) | 616 |
| 8403612LA | F | 09/27/2000 | 1 | IDT | | Y | IDT6116LA70TDB | 616 |
| 8403612XA | F | 09/27/2000 | | (NONE) | 05/06/1997 | | 6116LA70 (GEN) | 616 |
| 8403612YA | F | 09/27/2000 | | (NONE) | | | | 616 |
| 84036133A | F | 09/27/2000 | | (NONE) | 05/06/1997 | | 6116SA70 (GEN) | 616 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 8403613JA | F | 09/27/2000 | 1 | IDT | | Y | IDT6116SA70DB | 616 |
| 8403613KA | F | 09/27/2000 | | (NONE) | 01/01/1999 | | 6116SA70 (GEN) | 616 |
| 8403613LA | F | 09/27/2000 | 1 | IDT | | Y | IDT6116SA70TDB | 616 |
| 8403613XA | F | 09/27/2000 | | (NONE) | 05/06/1997 | | 6116SA70 (GEN) | 616 |
| 8403613YA | F | 09/27/2000 | | (NONE) | | | | 616 |
| 84036143A | F | 09/27/2000 | 1 | PYRAMID | | | P4C116-35L28MB | 616 |
| 84036143A | F | 09/27/2000 | 2 | QP SEMI | | Y | QP6116A-35LMB | 616 |
| 8403614JA | F | 09/27/2000 | 2 | QP SEMI | | Y | QP6116A-35DMB | 616 |
| 8403614KA | F | 09/27/2000 | 1 | PYRAMID | | | P4C116-35FMB | 616 |
| 8403614KA | F | 09/27/2000 | 2 | QP SEMI | | Y | QP7C128A-35KMB | 616 |
| 8403614LA | F | 09/27/2000 | 1 | PYRAMID | | | P4C116-35DMB | 616 |
| 8403614LA | F | 09/27/2000 | 2 | QP SEMI | | Y | QP7C128A-35DMB | 616 |
| 8403614XA | F | 09/27/2000 | 2 | QP SEMI | | Y | QP6117A-35LMB | 616 |
| 8403614YA | F | 09/27/2000 | 1 | PYRAMID | | | P4C116-35LMB | 616 |
| 8403614YA | F | 09/27/2000 | 2 | QP SEMI | | Y | QP7C128A-35LMB | 616 |
| 84036153A | F | 09/27/2000 | 1 | QP SEMI | | Y | 6116-120/3A | 616 |
| 8403615JA | F | 09/27/2000 | 1 | IDT | | Y | IDT6116LA120DB | 616 |
| 8403615KA | F | 09/27/2000 | 1 | QP SEMI | | Y | 6116-120/KA | 616 |
| 8403615LA | F | 09/27/2000 | 1 | IDT | | Y | IDT6116LA120TDB | 616 |
| 8403615XA | F | 09/27/2000 | 1 | QP SEMI | | Y | 6116-120/XA | 616 |
| 8403615YA | F | 09/27/2000 | 1 | QP SEMI | | Y | 6116-120/YA | 616 |
| 84036163A | F | 09/27/2000 | | (NONE) | 05/06/1997 | | 6116LA90 (GEN) | 616 |
| 8403616JA | F | 09/27/2000 | 1 | IDT | | Y | IDT6116LA90DB | 616 |
| 8403616KA | F | 09/27/2000 | | (NONE) | 01/01/1999 | | 6116LA90 (GEN) | 616 |
| 8403616LA | F | 09/27/2000 | 1 | IDT | | Y | IDT6116LA90TDB | 616 |
| 8403616XA | F | 09/27/2000 | | (NONE) | 05/06/1997 | | 6116LA90 (GEN) | 616 |
| 8403616YA | F | 09/27/2000 | | (NONE) | | | 6116L-90 (GEN) | 616 |
| 84037012A | H | 01/25/2002 | 2 | TI | | Y | SNJ54HC00FK | 100 |
| 8403701AA | H | 01/25/2002 | | (NONE) | | | 54HC00 (GEN) | 100 |
| 8403701BA | H | 01/25/2002 | | (NONE) | | | 54HC00 (GEN) | 100 |
| 5962-8403701VCA | H | 01/25/2002 | 2 | TI | | Y | SNV54HC00J | 100 |
| 8403701CA | H | 01/25/2002 | 2 | TI | | Y | SNJ54HC00J | 100 |
| 8403701CA | H | 01/25/2002 | 2 | TI | | Y | CD54HC00F3A | 100 |
| 5962-8403701VDA | H | 01/25/2002 | 2 | TI | | Y | SNV54HC00W | 100 |
| 8403701DA | H | 01/25/2002 | 2 | TI | | Y | SNJ54HC00W | 100 |
| 5962-8403701VXA | H | 01/25/2002 | 2 | STMICRO | | Y | 54HC00K02V | 100 |
| 5962-8403701VXC | H | 01/25/2002 | 2 | STMICRO | | Y | 54HC00K01V | 100 |
| 8403701XA | H | 01/25/2002 | 2 | STMICRO | | Y | 54HC00K02Q | 100 |
| 8403701XC | H | 01/25/2002 | 2 | STMICRO | | Y | 54HC00K01Q | 100 |
| 84038012A | F | 01/25/2002 | 2 | TI | | Y | SNJ54HC10FK | 102 |
| 8403801AA | F | 01/25/2002 | | (NONE) | | | 54HC10 (GEN) | 102 |
| 8403801BA | F | 01/25/2002 | | (NONE) | | | 54HC10 (GEN) | 102 |
| 8403801CA | F | 01/25/2002 | 2 | TI | | Y | SNJ54HC10J | 102 |
| 8403801CA | F | 01/25/2002 | 2 | TI | | Y | CD54HC10F3A | 102 |
| 8403801DA | F | 01/25/2002 | 2 | TI | | Y | SNJ54HC10W | 102 |
| 5962-8403801VXA | F | 01/25/2002 | 2 | STMICRO | | Y | 54HC10K02V | 102 |
| 5962-8403801VXC | F | 01/25/2002 | 2 | STMICRO | | Y | 54HC10K01V | 102 |
| 8403801XA | F | 01/25/2002 | 2 | STMICRO | | Y | 54HC10K02Q | 102 |
| 8403801XC | F | 01/25/2002 | 2 | STMICRO | | Y | 54HC10K01Q | 102 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 84039012A | E | 08/24/2001 | 1 | TI | | Y | SNJ54HC20FK | 104 |
| 8403901AA | E | 08/24/2001 | | (NONE) | | | 54HC20 (GEN) | 104 |
| 8403901BA | E | 08/24/2001 | | (NONE) | | | 54HC20 (GEN) | 104 |
| 8403901CA | E | 08/24/2001 | 1 | TI | | Y | SNJ54HC20J | 104 |
| 8403901DA | E | 08/24/2001 | 1 | TI | | Y | SNJ54HC20W | 104 |
| 84040012A | E | 08/24/2001 | 1 | ROCHESTER | | Y | 54HC30/B2A | 106 |
| 8404001AA | E | 08/24/2001 | | (NONE) | | | 54HC30 (GEN) | 106 |
| 8404001BA | E | 08/24/2001 | | (NONE) | 05/31/1994 | | 54HC30 (GEN) | 106 |
| 8404001CA | E | 08/24/2001 | 1 | TI | | Y | CD54HC30F3A | 106 |
| 8404001DA | E | 08/24/2001 | 1 | ROCHESTER | | Y | 54HC30/BDA | 106 |
| 84041012A | G | 02/14/2002 | 1 | TI | | Y | SNJ54HC02FK | 120 |
| 8404101AA | G | 02/14/2002 | | (NONE) | | | 54HC02 (GEN) | 120 |
| 8404101BA | G | 02/14/2002 | | (NONE) | | | 54HC02 (GEN) | 120 |
| 5962-8404101VCA | G | 02/14/2002 | 1 | TI | | Y | SNV54HC02J | 120 |
| 8404101CA | G | 02/14/2002 | 1 | TI | | Y | SNJ54HC02J | 120 |
| 8404101CA | G | 02/14/2002 | 1 | TI | | Y | CD54HC02F3A | 120 |
| 5962-8404101VDA | G | 02/14/2002 | 1 | TI | | Y | SNV54HC02W | 120 |
| 8404101DA | G | 02/14/2002 | 1 | TI | | Y | SNJ54HC02W | 120 |
| 5962-8404101VXA | G | 02/14/2002 | 2 | STMICRO | | Y | 54HC02K02V | 120 |
| 5962-8404101VXC | G | 02/14/2002 | 2 | STMICRO | | Y | 54HC02K01V | 120 |
| 8404101XA | G | 02/14/2002 | 2 | STMICRO | | Y | 54HC02K02Q | 120 |
| 8404101XC | G | 02/14/2002 | 2 | STMICRO | | Y | 54HC02K01Q | 120 |
| 84042012A | G | 02/08/2002 | 2 | TI | | Y | SNJ54HC27FK | 122 |
| 8404201AA | G | 02/08/2002 | | (NONE) | | | 54HC27 (GEN) | 122 |
| 8404201BA | G | 02/08/2002 | | (NONE) | | | 54HC27 (GEN) | 122 |
| 8404201CA | G | 02/08/2002 | 2 | TI | | Y | CD54HC27F3A | 122 |
| 8404201CA | G | 02/08/2002 | 2 | TI | | Y | SNJ54HC27J | 122 |
| 5962-8404201VDA | G | 02/08/2002 | | (NONE) | | | 54HC27 (GEN) | 122 |
| 8404201DA | G | 02/08/2002 | 2 | TI | | Y | SNJ54HC27W | 122 |
| 5962-8404201VXA | G | 02/08/2002 | 2 | STMICRO | | Y | 54HC27K02V | 122 |
| 5962-8404201VXC | G | 02/08/2002 | 2 | STMICRO | | Y | 54HC27K01V | 122 |
| 8404201XA | G | 02/08/2002 | 2 | STMICRO | | Y | 54HC27K02Q | 122 |
| 8404201XC | G | 02/08/2002 | 2 | STMICRO | | Y | 54HC27K01Q | 122 |
| 84043012A | D | 08/24/2001 | | (NONE) | | | 54HC266 (GEN) | 141 |
| 8404301AA | D | 08/24/2001 | | (NONE) | | | 54HC266 (GEN) | 141 |
| 8404301BA | D | 08/24/2001 | | (NONE) | | | 54HC266 (GEN) | 141 |
| 8404301CA | D | 08/24/2001 | | (NONE) | | | 54HC266 (GEN) | 141 |
| 8404301DA | D | 08/24/2001 | | (NONE) | | | 54HC266 (GEN) | 141 |
| 84043022A | D | 08/24/2001 | | (NONE) | | | 54HC7266 (GEN) | 141 |
| 8404302AA | D | 08/24/2001 | | (NONE) | | | 54HC7266 (GEN) | 141 |
| 8404302CA | D | 08/24/2001 | 1 | TI | | Y | CD54HC7266F3A | 141 |
| 84044012A | E | 08/28/2001 | 2 | TI | | Y | SNJ54HC4002FK | 123 |
| 8404401AA | E | 08/28/2001 | | (NONE) | | | 54HC4002 (GEN) | 123 |
| 8404401BA | E | 08/28/2001 | | (NONE) | | | 54HC4002 (GEN) | 123 |
| 8404401CA | E | 08/28/2001 | 2 | TI | | Y | SNJ54HC4002J | 123 |
| 8404401CA | E | 08/28/2001 | 2 | TI | | Y | CD54HC4002F3A | 123 |
| 8404401DA | E | 08/28/2001 | 2 | TI | | Y | SNJ54HC4002W | 123 |
| 84045012A | H | 02/08/2002 | 2 | TI | | Y | SNJ54HC32FK | 125 |
| 8404501AA | H | 02/08/2002 | | (NONE) | | | 54HC32 (GEN) | 125 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 8404501BA | H | 02/08/2002 | | (NONE) | | | 54HC32 (GEN) | 125 |
| 5962-8404501VCA | H | 02/08/2002 | 2 | TI | | Y | SNV54HC32J | 125 |
| 8404501CA | H | 02/08/2002 | 2 | TI | | Y | SNJ54HC32J | 125 |
| 8404501CA | H | 02/08/2002 | 2 | TI | | Y | CD54HC32F3A | 125 |
| 5962-8404501VDA | H | 02/08/2002 | 2 | TI | | Y | SNV54HC32W | 125 |
| 8404501DA | H | 02/08/2002 | 2 | TI | | Y | SNJ54HC32W | 125 |
| 5962-8404501VXA | H | 02/08/2002 | 2 | STMICRO | | Y | 54HC32K02V | 125 |
| 5962-8404501VXC | H | 02/08/2002 | 2 | STMICRO | | Y | 54HC32K01V | 125 |
| 8404501XA | H | 02/08/2002 | 2 | STMICRO | | Y | 54HC32K02Q | 125 |
| 8404501XC | H | 02/08/2002 | 2 | STMICRO | | Y | 54HC32K01Q | 125 |
| 84046012A | F | 02/08/2002 | 2 | TI | | Y | SNJ54HC86FK | 140 |
| 8404601AA | F | 02/08/2002 | | (NONE) | | | 54HC86 (GEN) | 140 |
| 8404601BA | F | 02/08/2002 | | (NONE) | | | 54HC86 (GEN) | 140 |
| 8404601CA | F | 02/08/2002 | 2 | TI | | Y | SNJ54HC86J | 140 |
| 8404601CA | F | 02/08/2002 | 2 | TI | | Y | CD54HC86F3A | 140 |
| 5962-8404601VDA | F | 02/08/2002 | | (NONE) | | | 54HC86 (GEN) | 140 |
| 8404601DA | F | 02/08/2002 | 2 | TI | | Y | SNJ54HC86W | 140 |
| 5962-8404601VXA | F | 02/08/2002 | 2 | STMICRO | | Y | 54HC86K02V | 140 |
| 5962-8404601VXC | F | 02/08/2002 | 2 | STMICRO | | Y | 54HC86K01V | 140 |
| 8404601XA | F | 02/08/2002 | 2 | STMICRO | | Y | 54HC86K02Q | 140 |
| 8404601XC | F | 02/08/2002 | 2 | STMICRO | | Y | 54HC86K01Q | 140 |
| 84047012A | F | 02/14/2002 | 1 | TI | | Y | SNJ54HC08FK | 110 |
| 8404701BA | F | 02/14/2002 | | (NONE) | | | 54HC08 (GEN) | 110 |
| 5962-8404701VCA | F | 02/14/2002 | 1 | TI | | Y | SNV54HC08J | 110 |
| 8404701CA | F | 02/14/2002 | 1 | TI | | Y | SNJ54HC08J | 110 |
| 8404701CA | F | 02/14/2002 | 1 | TI | | Y | CD54HC08F3A | 110 |
| 5962-8404701VDA | F | 02/14/2002 | 1 | TI | | Y | SNV54HC08W | 110 |
| 8404701DA | F | 02/14/2002 | 1 | TI | | Y | SNJ54HC08W | 110 |
| 5962-8404701VXA | F | 02/14/2002 | 2 | STMICRO | | Y | 54HC08K02V | 110 |
| 5962-8404701VXC | F | 02/14/2002 | 2 | STMICRO | | Y | 54HC08K01V | 110 |
| 8404701XA | F | 02/14/2002 | 2 | STMICRO | | Y | 54HC08K02Q | 110 |
| 8404701XC | F | 02/14/2002 | 2 | STMICRO | | Y | 54HC08K01Q | 110 |
| 84048012A | D | 08/28/2001 | 2 | TI | | Y | SNJ54HC11FK | 112 |
| 8404801AA | D | 08/28/2001 | | (NONE) | | | 54HC11 (GEN) | 112 |
| 8404801BA | D | 08/28/2001 | | (NONE) | | | 54HC11 (GEN) | 112 |
| 8404801CA | D | 08/28/2001 | 2 | TI | | Y | SNJ54HC11J | 112 |
| 8404801CA | D | 08/28/2001 | 2 | TI | | Y | CD54HC11F3A | 112 |
| 8404801DA | D | 08/28/2001 | 2 | TI | | Y | SNJ54HC11W | 112 |
| 8405201QA | D | 05/31/1990 | | (NONE) | 12/23/2001 | | 80C86 (GEN) | 403 |
| 8405201XA | D | 05/31/1990 | | (NONE) | 03/25/2001 | | 80C86 (GEN) | 403 |
| 8405202QA | D | 05/31/1990 | | (NONE) | 03/25/2001 | | 80C86-2 (GEN) | 403 |
| 8405202XA | D | 05/31/1990 | | (NONE) | 03/25/2001 | | 80C86-2 (GEN) | 403 |
| 8405301QA | B | 06/09/1989 | | (NONE) | | | 32010 (GEN) | 432 |
| 8405301ZA | B | 06/09/1989 | | (NONE) | | | 32010 (GEN) | 432 |
| 84056012A | E | 01/14/2002 | 2 | TI | | Y | SNJ54HC74FK | 158 |
| 8405601AA | E | 01/14/2002 | | (NONE) | | | 54HC74 (GEN) | 158 |
| 8405601BA | E | 01/14/2002 | | (NONE) | | | 54HC74 (GEN) | 158 |
| 5962-8405601VCA | E | 01/14/2002 | 2 | TI | | Y | SNV54HC74J | 158 |
| 8405601CA | E | 01/14/2002 | 2 | TI | | Y | SNJ54HC74J | 158 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-8405601VDA | E | 01/14/2002 | 2 | TI | | Y | SNV54HC74W | 158 |
| 8405601DA | E | 01/14/2002 | 2 | TI | | Y | SNJ54HC74W | 158 |
| 5962-8405601VXA | E | 01/14/2002 | 2 | STMICRO | | Y | 54HC74K02V | 158 |
| 5962-8405601VXC | E | 01/14/2002 | 2 | STMICRO | | Y | 54HC74K01V | 158 |
| 8405601XA | E | 01/14/2002 | 2 | STMICRO | | Y | 54HC74K02Q | 158 |
| 8405601XC | E | 01/14/2002 | 2 | STMICRO | | Y | 54HC74K01Q | 158 |
| 8405701QA | D | 08/04/2003 | | (NONE) | | | 2901C (GEN) | 400 |
| 8405701ZA | D | 08/04/2003 | 1 | SARNOFF | | Y | GEM06801QZA | 400 |
| 8405701ZC | D | 08/04/2003 | 1 | SARNOFF | | Y | GEM06801QZC | 400 |
| 84059012A | A | 11/26/1984 | | (NONE) | | | 54ALS1000A (GEN) | 500 |
| 8405901BA | A | 11/26/1984 | | (NONE) | | | 54ALS1000A (GEN) | 500 |
| 8405901CA | A | 11/26/1984 | | (NONE) | | | 54ALS1000A (GEN) | 500 |
| 8405901DA | A | 11/26/1984 | | (NONE) | | | 54ALS1000A (GEN) | 500 |
| 84060012A | A | 04/27/1987 | | (NONE) | | | 54ALS1010A (GEN) | 509 |
| 8406001BA | A | 04/27/1987 | | (NONE) | | | 54ALS1010A (GEN) | 509 |
| 8406001CA | A | 04/27/1987 | | (NONE) | | | 54ALS1010A (GEN) | 509 |
| 8406001DA | A | 04/27/1987 | | (NONE) | | | 54ALS1010A (GEN) | 509 |
| 84061012A | | 08/27/1984 | | (NONE) | | | 54ALS1004 (GEN) | 514 |
| 8406101BA | | 08/27/1984 | | (NONE) | | | 54ALS1004 (GEN) | 514 |
| 8406101CA | | 08/27/1984 | | (NONE) | | | 54ALS1004 (GEN) | 514 |
| 8406101DA | | 08/27/1984 | | (NONE) | | | 54ALS1004 (GEN) | 514 |
| 84062012A | G | 01/16/2002 | 3 | TI | | Y | SNJ54HC138FK | 282 |
| 5962-8406201VEA | G | 01/16/2002 | 3 | TI | | Y | SNV54HC138J | 282 |
| 8406201EA | G | 01/16/2002 | 3 | TI | | Y | CD54HC138F3A | 282 |
| 8406201EA | G | 01/16/2002 | 3 | TI | | Y | SNJ54HC138J | 282 |
| 5962-8406201VFA | G | 01/16/2002 | 3 | TI | | Y | SNV54HC138W | 282 |
| 8406201FA | G | 01/16/2002 | 3 | TI | | Y | SNJ54HC138W | 282 |
| 5962-8406201VXA | G | 01/16/2002 | 2 | STMICRO | | Y | 54HC138K02V | 282 |
| 5962-8406201VXC | G | 01/16/2002 | 2 | STMICRO | | Y | 54HC138K01V | 282 |
| 8406201XA | G | 01/16/2002 | 2 | STMICRO | | Y | 54HC138K02Q | 282 |
| 8406201XC | G | 01/16/2002 | 2 | STMICRO | | Y | 54HC138K01Q | 282 |
| 84064012A | D | 10/19/2001 | | (NONE) | | | 54HC147 (GEN) | 345 |
| 8406401EA | D | 10/19/2001 | 1 | TI | | Y | CD54HC147F3A | 345 |
| 8406401FA | D | 10/19/2001 | | (NONE) | | | 54HC147 (GEN) | 345 |
| 84065013A | D | 04/01/1999 | 1 | INTERSIL | | Y | MR82C54/883 | 424 |
| 8406501JA | D | 04/01/1999 | 1 | INTERSIL | | Y | MD82C54/883 | 424 |
| 84065023A | D | 04/01/1999 | 1 | INTERSIL | | Y | MR82C54-12/883 | 424 |
| 8406502JA | D | 04/01/1999 | | (NONE) | 09/23/2001 | | 82C54-12 (GEN) | 424 |
| 8406601QA | E | 08/05/2003 | | (NONE) | 03/25/2001 | | 82C55A-5 (GEN) | 421 |
| 8406601XA | E | 08/05/2003 | | (NONE) | | | 82C55A-5 (GEN) | 421 |
| 8406602QA | E | 08/05/2003 | 1 | INTERSIL | | Y | MD82C55A/883 | 421 |
| 8406602XA | E | 08/05/2003 | 1 | INTERSIL | | Y | MR82C55A/883 | 421 |
| 84067012A | C | 11/16/2001 | | (NONE) | 03/25/2001 | | 82C82 (GEN) | 569 |
| 8406701RA | C | 11/16/2001 | 1 | INTERSIL | | Y | MD82C82/883 | 569 |
| 84067022A | C | 11/16/2001 | | (NONE) | | | 82C83H (GEN) | 569 |
| 8406702RA | C | 11/16/2001 | | (NONE) | 03/25/2001 | | 82C83H (GEN) | 569 |
| 84068012A | D | 04/18/2003 | | (NONE) | 03/25/2001 | | 82C84A (GEN) | 422 |
| 8406801VA | D | 04/18/2003 | 1 | INTERSIL | | Y | MD82C84A/883 | 422 |
| 8406802VA | D | 04/18/2003 | | (NONE) | 12/24/1997 | | 82C84A (GEN) | 422 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 84069012A | E | 11/15/1994 | | (NONE) | 03/25/2001 | | 82C88 (GEN) | 420 |
| 8406901RA | E | 11/15/1994 | 1 | INTERSIL | | Y | MD82C88/883 | 420 |
| 8406902RA | E | 11/15/1994 | | (NONE) | | | 82C88-10 (GEN) | 420 |
| 84070012A | C | 11/07/2001 | 1 | ROCHESTER | | Y | 54HC75/B2A | 340 |
| 8407001EA | C | 11/07/2001 | 1 | TI | | Y | CD54HC75F3A | 340 |
| 8407001FA | C | 11/07/2001 | 1 | ROCHESTER | | Y | 54HC75/BFA | 340 |
| 84071012A | G | 01/14/2002 | 2 | TI | | Y | SNJ54HC374FK | 159 |
| 5962-8407101VRA | G | 01/14/2002 | 2 | TI | | Y | SNV54HC374J | 159 |
| 8407101RA | G | 01/14/2002 | 2 | TI | | Y | SNJ54HC374J | 159 |
| 5962-8407101VSA | G | 01/14/2002 | 2 | TI | | Y | SNV54HC374W | 159 |
| 8407101SA | G | 01/14/2002 | 2 | TI | | Y | SNJ54HC374W | 159 |
| 5962-8407101VXA | G | 01/14/2002 | 2 | STMICRO | | Y | 54HC374K02V | 159 |
| 5962-8407101VXC | G | 01/14/2002 | 2 | STMICRO | | Y | 54HC374K01V | 159 |
| 8407101XA | G | 01/14/2002 | 2 | STMICRO | | Y | 54HC374K02Q | 159 |
| 8407101XC | G | 01/14/2002 | 2 | STMICRO | | Y | 54HC374K01Q | 159 |
| 84072012A | F | 02/08/2002 | 2 | TI | | Y | SNJ54HC373FK | 341 |
| 5962-8407201VRA | F | 02/08/2002 | 2 | TI | | Y | SNV54HC373J | 341 |
| 8407201RA | F | 02/08/2002 | 2 | TI | | Y | SNJ54HC373J | 341 |
| 8407201RA | F | 02/08/2002 | 2 | TI | | Y | CD54HC373F3A | 341 |
| 5962-8407201VSA | F | 02/08/2002 | 2 | TI | | Y | SNV54HC373W | 341 |
| 8407201SA | F | 02/08/2002 | 2 | TI | | Y | SNJ54HC373W | 341 |
| 5962-8407201VXA | F | 02/08/2002 | 2 | STMICRO | | Y | 54HC373K02V | 341 |
| 5962-8407201VXC | F | 02/08/2002 | 2 | STMICRO | | Y | 54HC373K01V | 341 |
| 8407201XA | F | 02/08/2002 | 2 | STMICRO | | Y | 54HC373K02Q | 341 |
| 8407201XC | F | 02/08/2002 | 2 | STMICRO | | Y | 54HC373K01Q | 341 |
| 84073012A | E | 12/11/2001 | 1 | TI | | Y | SNJ54HC174FK | 159 |
| 8407301EA | E | 12/11/2001 | 1 | TI | | Y | SNJ54HC174J | 159 |
| 8407301FA | E | 12/11/2001 | 1 | TI | | Y | SNJ54HC174W | 159 |
| 84074012A | E | 02/14/2002 | 2 | TI | | Y | SNJ54HC240FK | 529 |
| 8407401RA | E | 02/14/2002 | 2 | TI | | Y | SNJ54HC240J | 529 |
| 8407401RA | E | 02/14/2002 | 2 | TI | | Y | CD54HC240F3A | 529 |
| 5962-8407401VSA | E | 02/14/2002 | | (NONE) | | | 54HC240 (GEN) | 529 |
| 8407401SA | E | 02/14/2002 | 2 | TI | | Y | SNJ54HC240W | 529 |
| 5962-8407401VXA | E | 02/14/2002 | 2 | STMICRO | | Y | 54HC240K02V | 529 |
| 5962-8407401VXC | E | 02/14/2002 | 2 | STMICRO | | Y | 54HC240K01V | 529 |
| 8407401XA | E | 02/14/2002 | 2 | STMICRO | | Y | 54HC240K02Q | 529 |
| 8407401XC | E | 02/14/2002 | 2 | STMICRO | | Y | 54HC240K01Q | 529 |
| 84075012A | E | 01/16/2002 | 2 | TI | | Y | SNJ54HC161FK | 304 |
| 8407501EA | E | 01/16/2002 | 2 | TI | | Y | SNJ54HC161J | 304 |
| 8407501EA | E | 01/16/2002 | 2 | TI | | Y | CD54HC161F3A | 304 |
| 8407501FA | E | 01/16/2002 | 2 | TI | | Y | SNJ54HC161W | 304 |
| 5962-8407501VXA | E | 01/16/2002 | 2 | STMICRO | | Y | 54HC161K02V | 304 |
| 5962-8407501VXC | E | 01/16/2002 | 2 | STMICRO | | Y | 54HC161K01V | 304 |
| 8407501XA | E | 01/16/2002 | 2 | STMICRO | | Y | 54HC161K02Q | 304 |
| 8407501XC | E | 01/16/2002 | 2 | STMICRO | | Y | 54HC161K01Q | 304 |
| 84079012A | E | 09/20/1999 | 1 | ROCHESTER | | Y | 54ALS162B/B2A | 301 |
| 8407901EA | E | 09/20/1999 | 1 | AUSTIN SEMI. | | D | AS54ALS162C16/883C | 301 |
| 8407901EA | E | 09/20/1999 | 1 | ROCHESTER | | Y | 54ALS162B/BEA | 301 |
| 8407901FA | E | 09/20/1999 | 1 | ROCHESTER | | Y | 54ALS162B/BFA | 301 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 84085012A | D | 02/14/2002 | 2 | TI | | Y | SNJ54HC245FK | 590 |
| 5962-8408501VRA | D | 02/14/2002 | 2 | TI | | Y | SNV54HC245J | 590 |
| 8408501RA | D | 02/14/2002 | 2 | TI | | Y | SNJ54HC245J | 590 |
| 8408501RA | D | 02/14/2002 | 2 | TI | | Y | CD54HC245F3A | 590 |
| 5962-8408501VSA | D | 02/14/2002 | 2 | TI | | Y | SNV54HC245W | 590 |
| 8408501SA | D | 02/14/2002 | 2 | TI | | Y | SNJ54HC245W | 590 |
| 5962-8408501VXA | D | 02/14/2002 | 2 | STMICRO | | Y | 54HC245K02V | 590 |
| 5962-8408501VXC | D | 02/14/2002 | 2 | STMICRO | | Y | 54HC245K01V | 590 |
| 8408501XA | D | 02/14/2002 | 2 | STMICRO | | Y | 54HC245K02Q | 590 |
| 8408501XC | D | 02/14/2002 | 2 | STMICRO | | Y | 54HC245K01Q | 590 |
| 84088012A | D | 12/11/2001 | 3 | TI | | Y | SNJ54HC112FK | 156 |
| 8408801EA | D | 12/11/2001 | 3 | TI | | Y | SNJ54HC112J | 156 |
| 8408801FA | D | 12/11/2001 | 3 | TI | | Y | SNJ54HC112W | 156 |
| 84089012A | C | 07/19/2000 | 2 | TI | | Y | SNJ54HC175FK | 159 |
| 8408901EA | C | 07/19/2000 | 2 | TI | | Y | CD54HC175F3A | 159 |
| 8408901EA | C | 07/19/2000 | 2 | TI | | Y | SNJ54HC175J | 159 |
| 8408901FA | C | 07/19/2000 | 2 | TI | | Y | SNJ54HC175W | 159 |
| 5962-8408901VXA | C | 07/19/2000 | 2 | STMICRO | | Y | 54HC175K02V | 159 |
| 5962-8408901VXC | C | 07/19/2000 | 2 | STMICRO | | Y | 54HC175K01V | 159 |
| 8408901XA | C | 07/19/2000 | 2 | STMICRO | | Y | 54HC175K02Q | 159 |
| 8408901XC | C | 07/19/2000 | 2 | STMICRO | | Y | 54HC175K01Q | 159 |
| 84090012A | C | 12/11/2001 | | (NONE) | | | 54HC243 (GEN) | 590 |
| 8409001BA | C | 12/11/2001 | | (NONE) | | | 54HC243 (GEN) | 590 |
| 8409001CA | C | 12/11/2001 | 1 | TI | | Y | CD54HC243F3A | 590 |
| 8409001DA | C | 12/11/2001 | | (NONE) | | | 54HC243 (GEN) | 590 |
| 84091012A | F | 02/08/2002 | 1 | TI | | Y | SNJ54HC14FK | 143 |
| 8409101BA | F | 02/08/2002 | | (NONE) | | | 54HC14 (GEN) | 143 |
| 5962-8409101VCA | F | 02/08/2002 | 2 | TI | | Y | SNV54HC14J | 143 |
| 8409101CA | F | 02/08/2002 | 2 | TI | | Y | SNJ54HC14J | 143 |
| 8409101CA | F | 02/08/2002 | 2 | TI | | Y | CD54HC14F3A | 143 |
| 5962-8409101VDA | F | 02/08/2002 | 2 | TI | | Y | SNV54HC14W | 143 |
| 8409101DA | F | 02/08/2002 | 2 | TI | | Y | SNJ54HC14W | 143 |
| 5962-8409101VXA | F | 02/08/2002 | 2 | STMICRO | | Y | 54HC14K02V | 143 |
| 5962-8409101VXC | F | 02/08/2002 | 2 | STMICRO | | Y | 54HC14K01V | 143 |
| 8409101XA | F | 02/08/2002 | 2 | STMICRO | | Y | 54HC14K02Q | 143 |
| 8409101XC | F | 02/08/2002 | 2 | STMICRO | | Y | 54HC14K01Q | 143 |
| 84092012A | D | 01/16/2002 | 2 | TI | | Y | SNJ54HC139FK | 283 |
| 8409201EA | D | 01/16/2002 | 2 | TI | | Y | SNJ54HC139J | 283 |
| 8409201EA | D | 01/16/2002 | 2 | TI | | Y | CD54HC139F3A | 283 |
| 8409201FA | D | 01/16/2002 | 2 | TI | | Y | SNJ54HC139W | 283 |
| 5962-8409201VXA | D | 01/16/2002 | 2 | STMICRO | | Y | 54HC139K02V | 283 |
| 5962-8409201VXC | D | 01/16/2002 | 2 | STMICRO | | Y | 54HC139K01V | 283 |
| 8409201XA | D | 01/16/2002 | 2 | STMICRO | | Y | 54HC139K02Q | 283 |
| 8409201XC | D | 01/16/2002 | 2 | STMICRO | | Y | 54HC139K01Q | 283 |
| 84093012A | D | 01/22/2002 | 1 | TI | | Y | SNJ54HC153FK | 273 |
| 8409301EA | D | 01/22/2002 | 1 | TI | | Y | SNJ54HC153J | 273 |
| 8409301EA | D | 01/22/2002 | 1 | TI | | Y | CD54HC153F3A | 273 |
| 8409301FA | D | 01/22/2002 | 1 | TI | | Y | SNJ54HC153W | 273 |
| 84094012A | B | 02/12/1988 | | (NONE) | | | 54HC162 (GEN) | 301 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 8409401EA | B | 02/12/1988 | | (NONE) | 06/01/2001 | | 54HC162 (GEN) | 301 |
| 8409401FA | B | 02/12/1988 | | (NONE) | | | 54HC162 (GEN) | 301 |
| 84095012A | C | 02/04/2002 | 1 | TI | | Y | SNJ54HC165FK | 225 |
| 8409501EA | C | 02/04/2002 | 1 | TI | | Y | SNJ54HC165J | 225 |
| 8409501EA | C | 02/04/2002 | 1 | TI | | Y | CD54HC165F3A | 225 |
| 8409501FA | C | 02/04/2002 | 1 | TI | | Y | SNJ54HC165W | 225 |
| 5962-8409501VXA | C | 02/04/2002 | 2 | STMICRO | | Y | 54HC165K02V | 225 |
| 5962-8409501VXC | C | 02/04/2002 | 2 | STMICRO | | Y | 54HC165K01V | 225 |
| 8409501XA | C | 02/04/2002 | 2 | STMICRO | | Y | 54HC165K02Q | 225 |
| 8409501XC | C | 02/04/2002 | 2 | STMICRO | | Y | 54HC165K01Q | 225 |
| 84096012A | G | 02/04/2002 | 2 | TI | | Y | SNJ54HC244FK | 529 |
| 5962-8409601VRA | G | 02/04/2002 | 2 | TI | | Y | SNV54HC244J | 529 |
| 8409601RA | G | 02/04/2002 | 2 | TI | | Y | SNJ54HC244J | 529 |
| 8409601RA | G | 02/04/2002 | 2 | TI | | Y | CD54HC244F3A | 529 |
| 5962-8409601VSA | G | 02/04/2002 | 2 | TI | | Y | SNV54HC244W | 529 |
| 8409601SA | G | 02/04/2002 | 2 | TI | | Y | SNJ54HC244W | 529 |
| 5962-8409601VXA | G | 02/04/2002 | 2 | STMICRO | | Y | 54HC244K02V | 529 |
| 5962-8409601VXC | G | 02/04/2002 | 2 | STMICRO | | Y | 54HC244K01V | 529 |
| 8409601XA | G | 02/04/2002 | 2 | STMICRO | | Y | 54HC244K02Q | 529 |
| 8409601XC | G | 02/04/2002 | 2 | STMICRO | | Y | 54HC244K01Q | 529 |
| 84097012A | | 08/23/1984 | | (NONE) | | | 54ALS1008A (GEN) | 502 |
| 8409701BA | | 08/23/1984 | | (NONE) | | | 54ALS1008A (GEN) | 502 |
| 8409701CA | | 08/23/1984 | | (NONE) | | | 54ALS1008A (GEN) | 502 |
| 8409701DA | | 08/23/1984 | | (NONE) | | | 54ALS1008A (GEN) | 502 |
| 84098012A | D | 06/21/2000 | 1 | TI | | Y | SNJ54HC04FK | 143 |
| 8409801BA | D | 06/21/2000 | | (NONE) | | | 54HC04 (GEN) | 143 |
| 5962-8409801VCA | D | 06/21/2000 | 1 | TI | | Y | SNV54HC04J | 143 |
| 8409801CA | D | 06/21/2000 | 1 | TI | | Y | SNJ54HC04J | 143 |
| 5962-8409801VDA | D | 06/21/2000 | 1 | TI | | Y | SNV54HC04W | 143 |
| 8409801DA | D | 06/21/2000 | 1 | TI | | Y | SNJ54HC04W | 143 |
| 5962-8409801VXA | D | 06/21/2000 | 2 | STMICRO | | Y | 54HC04K02V | 143 |
| 5962-8409801VXC | D | 06/21/2000 | 2 | STMICRO | | Y | 54HC04K01V | 143 |
| 8409801XA | D | 06/21/2000 | 2 | STMICRO | | Y | 54HC04K02Q | 143 |
| 8409801XC | D | 06/21/2000 | 2 | STMICRO | | Y | 54HC04K01Q | 143 |
| 84099012A | G | 01/16/2002 | 2 | TI | | Y | SNJ54HC273FK | 159 |
| 8409901RA | G | 01/16/2002 | 2 | TI | | Y | SNJ54HC273J | 159 |
| 8409901RA | G | 01/16/2002 | 2 | TI | | Y | CD54HC273F3A | 159 |
| 5962-8409901VSA | G | 01/16/2002 | | (NONE) | | | 54HC273 (GEN) | 159 |
| 8409901SA | G | 01/16/2002 | 2 | TI | | Y | SNJ54HC273W | 159 |
| 5962-8409901VXA | G | 01/16/2002 | 2 | STMICRO | | Y | 54HC273K02V | 159 |
| 5962-8409901VXC | G | 01/16/2002 | 2 | STMICRO | | Y | 54HC273K01V | 159 |
| 8409901XA | G | 01/16/2002 | 2 | STMICRO | | Y | 54HC273K02Q | 159 |
| 8409901XC | G | 01/16/2002 | 2 | STMICRO | | Y | 54HC273K01Q | 159 |
| 84100012A | D | 01/22/2002 | 1 | TI | | Y | SNJ54HC393FK | 303 |
| 8410001BA | D | 01/22/2002 | | (NONE) | | | 54HC393 (GEN) | 303 |
| 8410001CA | D | 01/22/2002 | 1 | TI | | Y | SNJ54HC393J | 303 |
| 8410001CA | D | 01/22/2002 | 1 | TI | | Y | CD54HC393F3A | 303 |
| 8410001DA | D | 01/22/2002 | 1 | TI | | Y | SNJ54HC393W | 303 |
| 84109012A | B | 01/29/1996 | | (NONE) | 08/15/1999 | | TL431 (GEN) | 785 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 8410901PA | B | 01/29/1996 | | (NONE) | 08/15/1999 | | TL431 (GEN) | 785 |
| 8411101YA | D | 01/11/1989 | | (NONE) | 04/15/1995 | | 27256-35 (GEN) | 662 |
| 8411101ZA | D | 01/11/1989 | | (NONE) | 04/15/1995 | | 27256-35 (GEN) | 662 |
| 8411102YA | D | 01/11/1989 | | (NONE) | 04/15/1995 | | 27256-25 (GEN) | 662 |
| 8411102ZA | D | 01/11/1989 | | (NONE) | 04/15/1995 | | 27256-25 (GEN) | 662 |
| 8411103YA | D | 01/11/1989 | | (NONE) | 04/15/1995 | | 27256-20 (GEN) | 662 |
| 8411103ZA | D | 01/11/1989 | | (NONE) | 04/15/1995 | | 27256-20 (GEN) | 662 |
| 8411104YA | D | 01/11/1989 | | (NONE) | 04/15/1995 | | 27256-17 (GEN) | 662 |
| 8411105YA | D | 01/11/1989 | | (NONE) | | | 27256-30 (GEN) | 662 |
| 84128012A | B | 01/22/2002 | 1 | TI | | Y | SNJ54HC151FK | 271 |
| 8412801EA | B | 01/22/2002 | 1 | TI | | Y | SNJ54HC151J | 271 |
| 8412801EA | B | 01/22/2002 | 1 | TI | | Y | CD54HC151F3A | 271 |
| 84129013A | E | 08/06/2004 | | (NONE) | 08/02/1996 | | PAL20L8A (GEN) | 431 |
| 8412901JA | E | 08/06/2004 | | (NONE) | | | PAL20L8A (GEN) | 431 |
| 8412901KA | E | 08/06/2004 | 0 | TI | | Y | TIBPAL20L8-20MWB | 431 |
| 8412901LA | E | 08/06/2004 | 0 | TI | | Y | TIBPAL20L8-20MJTB | 431 |
| 8412901XA | E | 08/06/2004 | | TI | | Y | TIBPAL20L8-20MXB | 431 |
| 84129023A | E | 08/06/2004 | | (NONE) | 08/02/1996 | | PAL20R8A (GEN) | 431 |
| 8412902JA | E | 08/06/2004 | | (NONE) | | | PAL20R8A (GEN) | 431 |
| 8412902KA | E | 08/06/2004 | 0 | TI | | Y | TIBPAL20R8-20MWB | 431 |
| 8412902LA | E | 08/06/2004 | 0 | TI | | Y | TIBPAL20R8-20MJTB | 431 |
| 8412902XA | E | 08/06/2004 | | TI | | Y | TIBPAL20R8-20MXB | 431 |
| 84129033A | E | 08/06/2004 | | (NONE) | 08/02/1996 | | PAL20R6A (GEN) | 431 |
| 8412903JA | E | 08/06/2004 | | (NONE) | | | PAL20R6A (GEN) | 431 |
| 8412903KA | E | 08/06/2004 | 0 | TI | | Y | TIBPAL20R6-20MWB | 431 |
| 8412903LA | E | 08/06/2004 | 0 | TI | | Y | TIBPAL20R6-20MJT | 431 |
| 8412903XA | E | 08/06/2004 | | TI | | Y | TIBPAL20R6-20MXB | 431 |
| 84129043A | E | 08/06/2004 | | (NONE) | 08/02/1996 | | PAL20R4A (GEN) | 431 |
| 8412904JA | E | 08/06/2004 | | (NONE) | | | PAL20R4A (GEN) | 431 |
| 8412904KA | E | 08/06/2004 | 0 | TI | | Y | TIBPAL20R4-20MWB | 431 |
| 8412904LA | E | 08/06/2004 | 0 | TI | | Y | TIBPAL20R4-20MJTB | 431 |
| 8412904XA | E | 08/06/2004 | | TI | | Y | TIBPAL20R4-20MXB | 431 |
| 84129053A | E | 08/06/2004 | | (NONE) | | | PAL20L10A (GEN) | 431 |
| 8412905KA | E | 08/06/2004 | | (NONE) | | | PAL20L10A (GEN) | 431 |
| 8412905LA | E | 08/06/2004 | | (NONE) | | | PAL20L10A (GEN) | 431 |
| 8412905XA | E | 08/06/2004 | | (NONE) | | | PAL20L10A (GEN) | 431 |
| 84129063A | E | 08/06/2004 | | (NONE) | | | PAL20X8A (GEN) | 431 |
| 8412906KA | E | 08/06/2004 | | (NONE) | | | PAL20X8A (GEN) | 431 |
| 8412906LA | E | 08/06/2004 | | (NONE) | | | PAL20X8A (GEN) | 431 |
| 8412906XA | E | 08/06/2004 | | (NONE) | | | PAL20X8A (GEN) | 431 |
| 84129073A | E | 08/06/2004 | | (NONE) | | | PAL20X10A (GEN) | 431 |
| 8412907KA | E | 08/06/2004 | | (NONE) | | | PAL20X10A (GEN) | 431 |
| 8412907LA | E | 08/06/2004 | | (NONE) | | | PAL20X10A (GEN) | 431 |
| 8412907XA | E | 08/06/2004 | | (NONE) | | | PAL20X10A (GEN) | 431 |
| 84129083A | E | 08/06/2004 | | (NONE) | | | PAL20X4A (GEN) | 431 |
| 8412908KA | E | 08/06/2004 | | (NONE) | | | PAL20X4A (GEN) | 431 |
| 8412908LA | E | 08/06/2004 | | (NONE) | | | PAL20X4A (GEN) | 431 |
| 8412908XA | E | 08/06/2004 | | (NONE) | | | PAL20X4A (GEN) | 431 |
| 84129093A | E | 08/06/2004 | | (NONE) | 08/02/1996 | | PAL20L8A-2 (GEN) | 431 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 8412909KA | E | 08/06/2004 | | (NONE) | 08/02/1996 | | PAL20L8A-2 (GEN) | 431 |
| 8412909LA | E | 08/06/2004 | | (NONE) | 08/02/1996 | | PAL20L8A-2 (GEN) | 431 |
| 84129103A | E | 08/06/2004 | | (NONE) | 08/02/1996 | | PAL20R8A-2 (GEN) | 431 |
| 8412910KA | E | 08/06/2004 | | (NONE) | 08/02/1996 | | PAL20R8A-2 (GEN) | 431 |
| 8412910LA | E | 08/06/2004 | | (NONE) | 08/02/1996 | | PAL20R8A-2 (GEN) | 431 |
| 84129113A | E | 08/06/2004 | | (NONE) | 08/02/1996 | | PAL20L6A-2 (GEN) | 431 |
| 8412911KA | E | 08/06/2004 | | (NONE) | 08/02/1996 | | PAL20R6A-2 (GEN) | 431 |
| 8412911LA | E | 08/06/2004 | | (NONE) | 08/02/1996 | | PAL20R6A-2 (GEN) | 431 |
| 84129123A | E | 08/06/2004 | | (NONE) | 08/02/1996 | | PAL20R4A-2 (GEN) | 431 |
| 8412912KA | E | 08/06/2004 | | (NONE) | 08/02/1996 | | PAL20R4A-2 (GEN) | 431 |
| 8412912LA | E | 08/06/2004 | | (NONE) | 08/02/1996 | | PAL20R4A-2 (GEN) | 431 |
| 8413201RA | B | 09/13/1988 | | (NONE) | 09/24/2000 | | 65262 (GEN) | 616 |
| 8413201YA | B | 09/13/1988 | | (NONE) | | | | 616 |
| 8413202RA | B | 09/13/1988 | 2 | QP SEMI | | Y | CY7C167A-45DMB | 616 |
| 8413202SA | B | 09/13/1988 | 2 | QP SEMI | | Y | CY7C167A-45KMB | 616 |
| 8413202YA | B | 09/13/1988 | 2 | QP SEMI | | Y | CY7C167A-45LMB | 616 |
| 8413203RA | B | 09/13/1988 | | (NONE) | | | HM-65262 (GEN) | 616 |
| 8413203YA | B | 09/13/1988 | 1 | INTERSIL | | Y | HM4-65262B/883 | 616 |
| 8413204RA | B | 09/13/1988 | 1 | IDT | | Y | IDT6167LA35DB | 616 |
| 8413204SA | B | 09/13/1988 | | (NONE) | 01/01/1999 | | 6167LA35 (GEN) | 616 |
| 8413204YA | B | 09/13/1988 | | (NONE) | 08/10/1999 | | 6167LA35 (GEN) | 616 |
| 8413205RA | B | 09/13/1988 | 1 | IDT | | Y | IDT6167SA35DB | 616 |
| 8413205RA | B | 09/13/1988 | 2 | QP SEMI | | Y | CY7C167A-35DMB | 616 |
| 8413205SA | B | 09/13/1988 | 2 | QP SEMI | | Y | CY7C167A-35KMB | 616 |
| 8413205YA | B | 09/13/1988 | 2 | QP SEMI | | Y | CY7C167A-35LMB | 616 |
| 8413206RA | B | 09/13/1988 | 1 | IDT | | Y | IDT6167SA25DB | 616 |
| 8413206SA | B | 09/13/1988 | | (NONE) | | | 6167SA25 (GEN) | 616 |
| 8413206YA | B | 09/13/1988 | | (NONE) | 08/10/1999 | | 6167SA25 (GEN) | 616 |
| 8413207RA | B | 09/13/1988 | | (NONE) | | | | 616 |
| 8413207SA | B | 09/13/1988 | | (NONE) | | | | 616 |
| 8413207YA | B | 09/13/1988 | | (NONE) | | | | 616 |
| 8413208RA | B | 09/13/1988 | | (NONE) | | | | 616 |
| 8413208YA | B | 09/13/1988 | | (NONE) | | | | 616 |
| 8413209RA | B | 09/13/1988 | 1 | IDT | | Y | IDT6167LA45DB | 616 |
| 8413209SA | B | 09/13/1988 | | (NONE) | 01/01/1999 | | 6167LA45 (GEN) | 616 |
| 8413209YA | B | 09/13/1988 | | (NONE) | 08/10/1999 | | 6167LA45 (GEN) | 616 |
| 84134012A | B | 10/05/1992 | 2 | TI | | Y | SNJ54ALS153FK | 273 |
| 8413401EA | B | 10/05/1992 | 2 | TI | | Y | SNJ54ALS153J | 273 |
| 8413401FA | B | 10/05/1992 | 2 | TI | | Y | SNJ54ALS153W | 273 |
| 84135012A | D | 07/06/1992 | 2 | TI | | Y | SNJ54ALS251FK | 272 |
| 8413501EA | D | 07/06/1992 | 2 | TI | | Y | SNJ54ALS251J | 272 |
| 8413501FA | D | 07/06/1992 | 2 | TI | | Y | SNJ54ALS251W | 272 |
| 84136012A | D | 07/06/1992 | 2 | TI | | Y | SNJ54ALS273FK | 159 |
| 8413601RA | D | 07/06/1992 | 2 | TI | | Y | SNJ54ALS273J | 159 |
| 8413601SA | D | 07/06/1992 | 2 | TI | | Y | SNJ54ALS273W | 159 |
| 84141012A | D | 10/05/1992 | 2 | TI | | Y | SNJ54ALS151FK | 271 |
| 8414101EA | D | 10/05/1992 | 2 | TI | | Y | SNJ54ALS151J | 271 |
| 8414101FA | D | 10/05/1992 | 2 | TI | | Y | SNJ54ALS151W | 271 |
| 84142012A | B | 03/17/1987 | 2 | TI | | Y | SNJ54ALS09FK | 111 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 8414201BA | B | 03/17/1987 | 2 | TI | | Y | SNJ54ALS09WA | 111 |
| 8414201CA | B | 03/17/1987 | 2 | TI | | Y | SNJ54ALS09J | 111 |
| 8414201DA | B | 03/17/1987 | 2 | TI | | Y | SNJ54ALS09W | 111 |
| 84143012A | E | 07/06/1992 | 2 | TI | | Y | SNJ54ALS21AFK | 114 |
| 8414301BA | E | 07/06/1992 | | (NONE) | | | 54ALS21 (GEN) | 114 |
| 8414301CA | E | 07/06/1992 | 2 | TI | | Y | SNJ54ALS21AJ | 114 |
| 8414301DA | E | 07/06/1992 | 2 | TI | | Y | SNJ54ALS21AW | 114 |
| 84145012A | C | 10/05/1992 | 2 | TI | | Y | SNJ54ALS832AFK | 509 |
| 8414501RA | C | 10/05/1992 | 2 | TI | | Y | SNJ54ALS832AJ | 509 |
| 8414501SA | C | 10/05/1992 | 2 | TI | | Y | SNJ54ALS832AW | 509 |
| 84150012A | E | 01/16/2002 | 2 | TI | | Y | SNJ54HC109FK | 152 |
| 8415001EA | E | 01/16/2002 | 2 | TI | | Y | SNJ54HC109J | 152 |
| 8415001EA | E | 01/16/2002 | 2 | TI | | Y | CD54HC109F3A | 152 |
| 8415001FA | E | 01/16/2002 | 2 | TI | | Y | SNJ54HC109W | 152 |
| 5962-8415001VXA | E | 01/16/2002 | 2 | STMICRO | | Y | 54HC109K02V | 152 |
| 5962-8415001VXC | E | 01/16/2002 | 2 | STMICRO | | Y | 54HC109K01V | 152 |
| 8415001XA | E | 01/16/2002 | 2 | STMICRO | | Y | 54HC109K02Q | 152 |
| 8415001XC | E | 01/16/2002 | 2 | STMICRO | | Y | 54HC109K01Q | 152 |
| 84151012A | | 07/08/1985 | 1 | TI | | Y | SNJ54LS682FK | 209 |
| 8415101RA | | 07/08/1985 | 1 | TI | | Y | SNJ54LS682J | 209 |
| 8415101SA | | 07/08/1985 | 1 | TI | | Y | SNJ54LS682W | 209 |
| 84152012A | B | 08/09/2002 | 1 | TI | | Y | SNJ54LS684FK | 209 |
| 8415201RA | B | 08/09/2002 | 1 | TI | | Y | SNJ54LS684J | 209 |
| 8415201SA | B | 08/09/2002 | 1 | TI | | Y | SNJ54LS684W | 209 |
| 84153012A | B | 11/07/2003 | 1 | TI | | Y | SNJ54LS688FK | 209 |
| 5962-8415301VRA | B | 11/07/2003 | 1 | TI | | Y | SNV54LS688J | 209 |
| 8415301RA | B | 11/07/2003 | 1 | TI | | Y | SNJ54LS688J | 209 |
| 5962-8415301VSA | B | 11/07/2003 | 1 | TI | | Y | SNV54LS688W | 209 |
| 8415301SA | B | 11/07/2003 | 1 | TI | | Y | SNJ54LS688W | 209 |
| 84154012A | C | 08/13/2002 | 1 | TI | | Y | SNJ54LS399FK | 355 |
| 8415401EA | C | 08/13/2002 | 1 | TI | | Y | SNJ54LS399J | 355 |
| 8415401FA | C | 08/13/2002 | 1 | TI | | Y | SNJ54LS399W | 355 |
| 84155012A | D | 08/14/2002 | 1 | LANSDALE | | Y | SL54LS540/B2A | 529 |
| 84155012A | D | 08/14/2002 | 0 | TI | | Y | SNJ54LS540FK | 529 |
| 84155012C | D | 08/14/2002 | 1 | LANSDALE | | Y | SL54LS540/B2C | 529 |
| 8415501RA | D | 08/14/2002 | 1 | LANSDALE | | Y | SL54LS540/BRA | 529 |
| 8415501RA | D | 08/14/2002 | 1 | TI | | Y | SNJ54LS540J | 529 |
| 8415501SA | D | 08/14/2002 | 1 | LANSDALE | | Y | SL54LS540/BSA | 529 |
| 8415501SA | D | 08/14/2002 | 0 | TI | | Y | SNJ54LS540W | 529 |
| 84156012A | D | 08/20/2002 | 1 | LANSDALE | | Y | SL54LS541/B2A | 529 |
| 84156012A | D | 08/20/2002 | I | TI | | Y | SNJ54LS541FK | 529 |
| 84156012C | D | 08/20/2002 | 1 | LANSDALE | | Y | SL54LS541/B2C | 529 |
| 8415601SA | D | 08/20/2002 | 1 | LANSDALE | | Y | SL54LS541/BSA | 529 |
| 8415601SA | D | 08/20/2002 | 0 | TI | | Y | SNJ54LS541W | 529 |
| 84161012A | A | 12/15/2003 | 1 | LANSDALE | | Y | SL54LS640/B2A | 590 |
| 84161012A | A | 12/15/2003 | 1 | TI | | Y | SNJ54LS640FK | 590 |
| 84161012C | A | 12/15/2003 | 1 | LANSDALE | | Y | SL54LS640/B2C | 590 |
| 5962-8416101VRA | A | 12/15/2003 | 1 | TI | | Y | SNV54LS640J | 590 |
| 8416101RA | A | 12/15/2003 | 1 | LANSDALE | | Y | SL54LS640/BRA | 590 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 8416101RA | A | 12/15/2003 | 1 | TI | | Y | SNJ54LS640J | 590 |
| 5962-8416101VSA | A | 12/15/2003 | 1 | TI | | Y | SNV54LS640W | 590 |
| 8416101SA | A | 12/15/2003 | 1 | LANSDALE | | Y | SL54LS640/BSA | 590 |
| 8416101SA | A | 12/15/2003 | 1 | TI | | Y | SNJ54LS640W | 590 |
| 84162012A | D | 02/01/2002 | 2 | TI | | Y | SNJ54HC164FK | 226 |
| 8416201BA | D | 02/01/2002 | | (NONE) | | | 54HC164 (GEN) | 226 |
| 5962-8416201VCA | D | 02/01/2002 | 2 | TI | | Y | SNV54HC164J | 226 |
| 8416201CA | D | 02/01/2002 | 2 | TI | | Y | SNJ54HC164J | 226 |
| 8416201CA | D | 02/01/2002 | 2 | TI | | Y | CD54HC164F3A | 226 |
| 5962-8416201VDA | D | 02/01/2002 | 2 | TI | | Y | SNV54HC164W | 226 |
| 8416201DA | D | 02/01/2002 | | (NONE) | | | 54HC164 (GEN) | 226 |
| 5962-8416201VXA | D | 02/01/2002 | 2 | STMICRO | | Y | 54HC164K02V | 226 |
| 5962-8416201VXC | D | 02/01/2002 | 2 | STMICRO | | Y | 54HC164K01V | 226 |
| 8416201XA | D | 02/01/2002 | 2 | STMICRO | | Y | 54HC164K02Q | 226 |
| 8416201XC | D | 02/01/2002 | 2 | STMICRO | | Y | 54HC164K01Q | 226 |
| 8416901XA | A | 05/05/1989 | | (NONE) | | | F9450-15 (GEN) | 403 |
| 8416901YA | A | 05/05/1989 | | (NONE) | | | F9450-15 (GEN) | 403 |
| 8416902XA | A | 05/05/1989 | | (NONE) | | | F9450-F18 (GEN) | 403 |
| 8416902YA | A | 05/05/1989 | | (NONE) | | | F9450-F18 (GEN) | 403 |
| 8416903XA | A | 05/05/1989 | | (NONE) | | | F9450-F20 (GEN) | 403 |
| 8416903YA | A | 05/05/1989 | | (NONE) | | | F9450-F20 (GEN) | 403 |
| 8416904XA | A | 05/05/1989 | | (NONE) | | | F9450-F15 (GEN) | 403 |
| 8416904YA | A | 05/05/1989 | | (NONE) | | | F9450-F15 (GEN) | 403 |
| 84179013A | A | 12/20/1988 | | (NONE) | | | 8282 (GEN) | 341 |
| 8417901RA | A | 12/20/1988 | | (NONE) | 12/24/1997 | | 8282 (GEN) | 341 |
| 84179023A | A | 12/20/1988 | 1 | LANSDALE | | Y | IL8283/B3A | 341 |
| 84179023C | A | 12/20/1988 | 1 | LANSDALE | | Y | IL8283/B2C | 341 |
| 8417902RA | A | 12/20/1988 | 1 | LANSDALE | | Y | IL8283/BRA | 341 |
| 84179033A | A | 12/20/1988 | 1 | LANSDALE | | Y | IL8282/B3A | 341 |
| 84179033C | A | 12/20/1988 | 1 | LANSDALE | | Y | IL8282/B3C | 341 |
| 8417903RA | A | 12/20/1988 | 1 | LANSDALE | | Y | IL8282/BRA | 341 |
| 84179043A | A | 12/20/1988 | | (NONE) | | | 8283 (GEN) | 341 |
| 8417904RA | A | 12/20/1988 | 0 | LANSDALE | | Y | IL8283/BRA | 341 |
| 8418001XA | D | 02/07/2003 | | (NONE) | 12/31/2001 | | LM136A-2.5 (GEN) | 785 |
| 8418002XA | D | 02/07/2003 | 1 | NATIONAL | | Y | LM136AH-5.0/883 | 785 |
| 8418003XA | D | 02/07/2003 | 1 | NATIONAL | | Y | LM136AH-2.5/883 | 785 |
| 84185012A | D | 01/10/2003 | | (NONE) | 06/30/2000 | | 733 (GEN) | 760 |
| 8418501CA | D | 01/10/2003 | | (NONE) | 06/30/2000 | | 733 (GEN) | 760 |
| 8418501HA | D | 01/10/2003 | | (NONE) | 06/30/2000 | | 733 (GEN) | 760 |
| 8418501IA | D | 01/10/2003 | | (NONE) | 09/30/1995 | | 733 (GEN) | 760 |
| 84185022A | D | 01/10/2003 | | (NONE) | 09/15/1995 | | 592 (GEN) | 760 |
| 8418502CA | D | 01/10/2003 | | (NONE) | 06/01/1997 | | 592 (GEN) | 760 |
| 8418502HA | D | 01/10/2003 | | (NONE) | | | 592 (GEN) | 760 |
| 8418502IA | D | 01/10/2003 | | (NONE) | | | 592 (GEN) | 760 |
| 84185032A | D | 01/10/2003 | | (NONE) | 05/31/1994 | | TL027 (GEN) | 760 |
| 8418503CA | D | 01/10/2003 | | (NONE) | 05/31/1994 | | TL027 (GEN) | 760 |
| 8418601QA | C | 12/30/1988 | | (NONE) | | | Z8420A (GEN) | 420 |
| 8418602QA | C | 12/30/1988 | | (NONE) | | | Z8420 (GEN) | 420 |
| 8419001QA | D | 12/03/2001 | 1 | ROCHESTER | | Y | 8751H-8/BQA | 410 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 8419001QA | D | 12/03/2001 | 1 | ROCHESTER | | Y | MC8751H-8/BQA | 410 |
| 8419001YA | D | 12/03/2001 | 1 | ROCHESTER | | Y | 8751H-8/BYA | 410 |
| 8419001YA | D | 12/03/2001 | 1 | ROCHESTER | | Y | MR8751H-8/BYA | 410 |
| 8419002QA | D | 12/03/2001 | 1 | ROCHESTER | | Y | 8751H/BQA | 410 |
| 8419002YA | D | 12/03/2001 | 1 | ROCHESTER | | Y | 8751H/BYA | 410 |
| 85001012A | C | 09/05/2001 | 1 | TI | | Y | SNJ54HC365FK | 522 |
| 8500101EA | C | 09/05/2001 | 1 | TI | | Y | SNJ54HC365J | 522 |
| 8500101FA | C | 09/05/2001 | 1 | ROCHESTER | | Y | 54HC365/BFA | 522 |
| 85002012A | D | 09/05/2001 | 2 | TI | | Y | SNJ54HC367FK | 522 |
| 8500201EA | D | 09/05/2001 | 2 | TI | | Y | SNJ54HC367J | 522 |
| 8500201FA | D | 09/05/2001 | | (NONE) | | | 54HC367 (GEN) | 522 |
| 85003012A | C | 09/13/2001 | 1 | TI | | Y | SNJ54HC4020FK | 305 |
| 8500301EA | C | 09/13/2001 | 1 | TI | | Y | SNJ54HC4020J | 305 |
| 8500301FA | C | 09/13/2001 | 1 | TI | | Y | SNJ54HC4020W | 305 |
| 85004012A | E | 01/25/2002 | 1 | TI | | Y | SNJ54HC4040FK | 305 |
| 8500401EA | E | 01/25/2002 | 1 | TI | | Y | SNJ54HC4040J | 305 |
| 8500401EA | E | 01/25/2002 | 1 | TI | | Y | CD54HC4040F3A | 305 |
| 5962-8500401VFA | E | 01/25/2002 | | (NONE) | | | 54HC4040 (GEN) | 305 |
| 8500401FA | E | 01/25/2002 | 1 | TI | | Y | SNJ54HC4040W | 305 |
| 5962-8500401VXA | E | 01/25/2002 | 2 | STMICRO | | Y | 54HC4040K02V | 305 |
| 5962-8500401VXC | E | 01/25/2002 | 2 | STMICRO | | Y | 54HC4040K01V | 305 |
| 8500401XA | E | 01/25/2002 | 2 | STMICRO | | Y | 54HC4040K02Q | 305 |
| 8500401XC | E | 01/25/2002 | 2 | STMICRO | | Y | 54HC4040K01Q | 305 |
| 8501001YA | E | 09/27/2000 | 1 | ROCHESTER | | Y | MQ80186-8/B | 403 |
| 8501001ZA | E | 09/27/2000 | 1 | ROCHESTER | | Y | MG80186-8/B | 403 |
| 8501002YA | E | 09/27/2000 | 1 | ROCHESTER | | Y | MQ80186-6/B | 403 |
| 8501002ZA | E | 09/27/2000 | 1 | ROCHESTER | | Y | MG80186-6/B | 403 |
| 85015013A | D | 05/24/2001 | 1 | INTERSIL | | Y | MR82C52/883 | 421 |
| 8501501XA | D | 05/24/2001 | 1 | INTERSIL | | Y | MD82C52/883 | 421 |
| 5962-85016013A | C | 06/05/2001 | 1 | INTERSIL | 10/05/2004 | Y | MR82C59A-5B | 420 |
| 5962-8501601YA | C | 06/05/2001 | 1 | INTERSIL | | Y | MD82C59A-5B | 420 |
| 5962-85016023A | C | 06/05/2001 | 1 | INTERSIL | | Y | MR82C59A/B | 420 |
| 5962-8501602YA | C | 06/05/2001 | 1 | INTERSIL | | Y | MD82C59A/B | 420 |
| 85030013A | F | 01/08/1999 | 1 | SATCON | | Y | HC2700SLCC/883B | 785 |
| 8503001CA | F | 01/08/1999 | | (NONE) | 09/01/2000 | | 2700 (GEN) | 785 |
| 8503001XA | F | 01/08/1999 | | (NONE) | | | 2700 (GEN) | 785 |
| 8503001YA | F | 01/08/1999 | 1 | ANALOG (6) | | Y | AD2700SD/883B | 785 |
| 8503001YA | F | 01/08/1999 | 1 | SATCON | | Y | HC2700SD/883B | 785 |
| 85030023A | F | 01/08/1999 | 1 | SATCON | | Y | HC2700ULCC/883B | 785 |
| 8503002CA | F | 01/08/1999 | | (NONE) | 09/01/2000 | | 2700U (GEN) | 785 |
| 8503002XC | F | 01/08/1999 | | (NONE) | | | 2700U (GEN) | 785 |
| 8503002YA | F | 01/08/1999 | 1 | ANALOG (6) | | Y | AD2700UD/883B | 785 |
| 8503002YA | F | 01/08/1999 | 1 | SATCON | | Y | HC2700UD/883B | 785 |
| 85030033A | F | 01/08/1999 | 1 | SATCON | | Y | HC2702SLCC/883B | 785 |
| 8503003CA | F | 01/08/1999 | | (NONE) | 09/01/2000 | | 2702S (GEN) | 785 |
| 8503003XA | F | 01/08/1999 | | (NONE) | | | 2702S (GEN) | 785 |
| 8503003YA | F | 01/08/1999 | 1 | ANALOG (6) | | Y | AD2702SD/883B | 785 |
| 8503003YA | F | 01/08/1999 | 1 | SATCON | | Y | HC2702SD/883B | 785 |
| 8503003YC | F | 01/08/1999 | | (NONE) | 08/29/2003 | | AD2702S (GEN) | 785 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 85030043A | F | 01/08/1999 | 1 | SATCON | | Y | HC2702ULCC/883B | 785 |
| 8503004CA | F | 01/08/1999 | | (NONE) | 09/01/2000 | | 2702U (GEN) | 785 |
| 8503004XA | F | 01/08/1999 | | (NONE) | | | 2702U (GEN) | 785 |
| 8503004YA | F | 01/08/1999 | 1 | ANALOG (6) | | Y | AD2702UD/883B | 785 |
| 8503004YA | F | 01/08/1999 | 1 | SATCON | | Y | HC2702UD/883B | 785 |
| 8503004YC | F | 01/08/1999 | 1 | ANALOG (6) | | Y | AD2702UD/883B | 785 |
| 85030053A | F | 01/08/1999 | 1 | SATCON | | Y | HC2701SLCC/883B | 785 |
| 8503005CA | F | 01/08/1999 | | (NONE) | 09/01/2000 | | 2701 (GEN) | 785 |
| 8503005YA | F | 01/08/1999 | 1 | SATCON | | Y | HC2701SD/883B | 785 |
| 85030063A | F | 01/08/1999 | 1 | SATCON | | Y | HC2701ULCC/883B | 785 |
| 8503006CA | F | 01/08/1999 | | (NONE) | 09/01/2000 | | 2701 (GEN) | 785 |
| 8503006YA | F | 01/08/1999 | 1 | SATCON | | Y | HC2701UD/883B | 785 |
| 8506301YA | B | 10/19/2000 | 1 | ROCHESTER | | Y | MQ8097/B | 420 |
| 8506301ZA | B | 10/19/2000 | 1 | ROCHESTER | | Y | MG8097/B | 420 |
| 5962-8506401MMA | J | 12/18/2002 | 1 | QP SEMI | | Y | TS80C31BH/BMA | 420 |
| 5962-8506401MMA | J | 12/18/2002 | 1 | QP SEMI | | Y | 80C31BH/BMA | 420 |
| 5962-8506401MQA | J | 12/18/2002 | 1 | QP SEMI | | Y | 80C31BH/BQA | 420 |
| 5962-8506401MQA | J | 12/18/2002 | 1 | QP SEMI | | Y | TS80C31BH/BQA | 420 |
| 8506401QA | J | 12/18/2002 | | (NONE) | 12/24/1997 | | 80C31BH (GEN) | 420 |
| 5962-8506401NUA | J | 12/18/2002 | | (NONE) | | | 80C31BH (GEN) | 420 |
| 5962-8506401NVA | J | 12/18/2002 | | (NONE) | | | 80C31BH (GEN) | 420 |
| 5962-8506401MXA | J | 12/18/2002 | 1 | QP SEMI | | Y | TS80C31BH/BUA | 420 |
| 5962-8506401MXA | J | 12/18/2002 | 1 | QP SEMI | | Y | 80C31BH/BUA | 420 |
| 8506401XA | J | 12/18/2002 | | (NONE) | 12/24/1997 | | 80C31BH (GEN) | 420 |
| 5962-8506401MYA | J | 12/18/2002 | | (NONE) | | | 80C31BH (GEN) | 420 |
| 8506401YA | J | 12/18/2002 | | (NONE) | 5962-8506401MYA | | 80C31BH (GEN) | 420 |
| 5962-8506402MMA | J | 12/18/2002 | | (NONE) | 09/01/1997 | | 80C51BH (GEN) | 420 |
| 5962-8506402MQA | J | 12/18/2002 | | (NONE) | | | 80C51 (GEN) | 420 |
| 8506402QA | J | 12/18/2002 | | (NONE) | 12/24/1997 | | 80C51BH (GEN) | 420 |
| 5962-8506402NUA | J | 12/18/2002 | | (NONE) | | | 80C51BH (GEN) | 420 |
| 5962-8506402NVA | J | 12/18/2002 | | (NONE) | | | 80C51BH (GEN) | 420 |
| 5962-8506402MXA | J | 12/18/2002 | | (NONE) | | | 80C51BH (GEN) | 420 |
| 8506402XA | J | 12/18/2002 | | (NONE) | 12/24/1997 | | 80C51BH (GEN) | 420 |
| 5962-8506402MYA | J | 12/18/2002 | | (NONE) | 09/01/1997 | | 80C51BH (GEN) | 420 |
| 8506402YA | J | 12/18/2002 | | (NONE) | 5962-8506402MYA | | 80C51BH (GEN) | 420 |
| 5962-8506403MMA | J | 12/18/2002 | 1 | QP SEMI | | Y | TS80C31BH-16 | 420 |
| 5962-8506403MMA | J | 12/18/2002 | 1 | QP SEMI | | Y | 80C31BH-16 | 420 |
| 5962-8506403MQA | J | 12/18/2002 | 1 | QP SEMI | | Y | TS80C31BH-16 | 420 |
| 5962-8506403MQA | J | 12/18/2002 | 1 | QP SEMI | | Y | 80C31BH-16 | 420 |
| 8506403QA | J | 12/18/2002 | | (NONE) | 12/24/1997 | | 80C31BH16 (GEN) | 420 |
| 5962-8506403NUA | J | 12/18/2002 | | (NONE) | | | 80C31BH-16 (GEN) | 420 |
| 5962-8506403NVA | J | 12/18/2002 | | (NONE) | | | 80C31BH-16 (GEN) | 420 |
| 5962-8506403MXA | J | 12/18/2002 | 1 | QP SEMI | | Y | TS80C31BH-16 | 420 |
| 5962-8506403MXA | J | 12/18/2002 | 1 | QP SEMI | | Y | 80C31BH-16 | 420 |
| 8506403XA | J | 12/18/2002 | | (NONE) | 12/24/1997 | | 80C31BH16 (GEN) | 420 |
| 5962-8506403MYA | J | 12/18/2002 | | (NONE) | | | 80C31BH-16 (GEN) | 420 |
| 8506403YA | J | 12/18/2002 | | (NONE) | 5962-8506403MYA | | 80C31BH-16 (GEN) | 420 |
| 5962-8506404MMA | J | 12/18/2002 | | (NONE) | | | 80C51BH-16 (GEN) | 420 |
| 5962-8506404MQA | J | 12/18/2002 | | (NONE) | | | 80C51 (GEN) | 420 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 8506404QA | J | 12/18/2002 | | (NONE) | 12/24/1997 | | 80C51BH16 (GEN) | 420 |
| 5962-8506404NUA | J | 12/18/2002 | | (NONE) | | | 80C51BH-16 (GEN) | 420 |
| 5962-8506404NVA | J | 12/18/2002 | | (NONE) | | | 80C51BH-16 (GEN) | 420 |
| 5962-8506404MXA | J | 12/18/2002 | | (NONE) | | | 80C51BH-16 (GEN) | 420 |
| 8506404XA | J | 12/18/2002 | | (NONE) | 12/24/1997 | | 80C51BH16 (GEN) | 420 |
| 5962-8506404MYA | J | 12/18/2002 | | (NONE) | | | 80C51BH-16 (GEN) | 420 |
| 8506404YA | J | 12/18/2002 | | (NONE) | | | 80C51BH-16 (GEN) | 420 |
| 5962-8506405NUA | J | 12/18/2002 | | (NONE) | | | 80C31BH (GEN) | 420 |
| 5962-8506405NVA | J | 12/18/2002 | | (NONE) | | | 80C31BH (GEN) | 420 |
| 5962-8506406NUA | J | 12/18/2002 | | (NONE) | | | 80C51BH (GEN) | 420 |
| 5962-8506406NVA | J | 12/18/2002 | | (NONE) | | | 80C51BH (GEN) | 420 |
| 5962-8506407NUA | J | 12/18/2002 | | (NONE) | | | 80C31BH-16 (GEN) | 420 |
| 5962-8506407NVA | J | 12/18/2002 | | (NONE) | | | 80C31BH-16 (GEN) | 420 |
| 5962-8506408NUA | J | 12/18/2002 | | (NONE) | | | 80C51BH-16 (GEN) | 420 |
| 5962-8506408NVA | J | 12/18/2002 | | (NONE) | | | 80C51BH-16 (GEN) | 420 |
| 85065012A | A | 05/25/1988 | | (NONE) | | | PAL16L8A-4 (GEN) | 431 |
| 8506501RA | A | 05/25/1988 | | (NONE) | | | PAL16L8A-4 (GEN) | 431 |
| 8506501SA | A | 05/25/1988 | | (NONE) | | | PAL16L8A-4 (GEN) | 431 |
| 85065022A | A | 05/25/1988 | | (NONE) | | | PAL16R8A-4 (GEN) | 431 |
| 8506502RA | A | 05/25/1988 | | (NONE) | | | PAL16R8A-4 (GEN) | 431 |
| 8506502SA | A | 05/25/1988 | | (NONE) | | | PAL16R8A-4 (GEN) | 431 |
| 85065032A | A | 05/25/1988 | | (NONE) | | | PAL16R6A-4 (GEN) | 431 |
| 8506503RA | A | 05/25/1988 | | (NONE) | | | PAL16R6A-4 (GEN) | 431 |
| 8506503SA | A | 05/25/1988 | | (NONE) | | | PAL16R6A-4 (GEN) | 431 |
| 85065042A | A | 05/25/1988 | | (NONE) | | | PAL16R4A-4 (GEN) | 431 |
| 8506504RA | A | 05/25/1988 | | (NONE) | | | PAL16R4A-4 (GEN) | 431 |
| 8506504SA | A | 05/25/1988 | | (NONE) | | | PAL16R4A-4 (GEN) | 431 |
| 85084012A | A | 12/05/2001 | 1 | TI | | Y | SNJ54LS145FK | 290 |
| 8508401EA | A | 12/05/2001 | 1 | TI | | Y | SNJ54LS145J | 290 |
| 8508401FA | A | 12/05/2001 | 1 | TI | | Y | SNJ54LS145W | 290 |
| 8508701ZA | G | 03/10/2004 | 1 | MS KENNEDY | | Y | MSK0041B | 724 |
| 8508701ZA | G | 03/10/2004 | 1 | SATCON | | Y | FLH0041G/883 | 724 |
| 8508701ZC | G | 03/10/2004 | 1 | MS KENNEDY | | Y | MSK0041B | 724 |
| 8508801YA | F | 07/01/1998 | 1 | MS KENNEDY | | Y | MSK0021B | 753 |
| 8508801YA | F | 07/01/1998 | 1 | SATCON | | Y | FLH0021K/883 | 753 |
| 8508801YC | F | 07/01/1998 | 1 | MS KENNEDY | | Y | MSK0021B | 753 |
| 8508901YA | B | 02/13/2002 | 1 | SATCON | | Y | FLH0101AK/883 | 724 |
| 8508902YA | B | 02/13/2002 | 1 | SATCON | | Y | FLH0101K/883 | 724 |
| 85096012A | D | 07/10/1992 | 2 | TI | | Y | SNJ54ALS253FK | 274 |
| 8509601EA | D | 07/10/1992 | 2 | TI | | Y | SNJ54ALS253J | 274 |
| 8509601FA | D | 07/10/1992 | 2 | TI | | Y | SNJ54ALS253W | 274 |
| 85097012A | E | 12/06/2001 | 3 | TI | | Y | SNJ54ALS257AFK | 276 |
| 8509701EA | E | 12/06/2001 | 3 | TI | | Y | SNJ54ALS257AJ | 276 |
| 8509701FA | E | 12/06/2001 | 3 | TI | | Y | SNJ54ALS257AW | 276 |
| 8510201YA | D | 06/23/2000 | 1 | ROCHESTER | | Y | MD27C64-25/BYA | 660 |
| 8510201ZA | D | 06/23/2000 | 1 | ROCHESTER | | Y | MR27C64-25/BZA | 660 |
| 8510202YA | D | 06/23/2000 | 1 | ROCHESTER | | Y | MD27C64-35/BYA | 660 |
| 8510202ZA | D | 06/23/2000 | 1 | ROCHESTER | | Y | MR27C64-35/BZA | 660 |
| 8510203YA | D | 06/23/2000 | 1 | QP SEMI | | Y | 27C64-20/YA | 660 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 8510203YA | D | 06/23/2000 | 1 | ROCHESTER | | Y | MD27C64-20/BYA | 660 |
| 8510203ZA | D | 06/23/2000 | 1 | QP SEMI | | Y | 27C64-20/ZA | 660 |
| 8510203ZA | D | 06/23/2000 | 1 | ROCHESTER | | Y | MR27C64-20/BZA | 660 |
| 8510204YA | D | 06/23/2000 | | (NONE) | | | 27C64-90 (GEN) | 660 |
| 8510204ZA | D | 06/23/2000 | | (NONE) | | | 27C64-90 (GEN) | 660 |
| 8510205YA | D | 06/23/2000 | | (NONE) | | | 27C64-12 (GEN) | 660 |
| 8510205ZA | D | 06/23/2000 | | (NONE) | | | 27C64-12 (GEN) | 660 |
| 8510206YA | D | 06/23/2000 | | (NONE) | | | 27C64-15 (GEN) | 660 |
| 8510206ZA | D | 06/23/2000 | | (NONE) | | | 27C64-15 (GEN) | 660 |
| 8510207YA | D | 06/23/2000 | | (NONE) | | | 57C64-70 (GEN) | 660 |
| 8510207ZA | D | 06/23/2000 | | (NONE) | | | 57C64-70 (GEN) | 660 |
| 85124012A | E | 01/18/2002 | 3 | TI | | Y | SNJ54HC257FK | 276 |
| 8512401EA | E | 01/18/2002 | 3 | TI | | Y | SNJ54HC257J | 276 |
| 8512401EA | E | 01/18/2002 | 3 | TI | | Y | CD54HC257F3A | 276 |
| 5962-8512401VFA | E | 01/18/2002 | | (NONE) | | | 54HC257 (GEN) | 276 |
| 8512401FA | E | 01/18/2002 | | (NONE) | | | 54HC257 (GEN) | 276 |
| 5962-8512401VXA | E | 01/18/2002 | 2 | STMICRO | | Y | 54HC257K02V | 276 |
| 5962-8512401VXC | E | 01/18/2002 | 2 | STMICRO | | Y | 54HC257K01V | 276 |
| 8512401XA | E | 01/18/2002 | 2 | STMICRO | | Y | 54HC257K02Q | 276 |
| 8512401XC | E | 01/18/2002 | 2 | STMICRO | | Y | 54HC257K01Q | 276 |
| 85125012A | A | 04/09/2003 | 3 | TI | | Y | SNJ54HC251FK | 272 |
| 8512501EA | A | 04/09/2003 | 3 | TI | | Y | SNJ54HC251J | 272 |
| 8512501FA | A | 04/09/2003 | | (NONE) | | | 54HC251 (GEN) | 272 |
| 85126012A | B | 09/11/1992 | 1 | LANSDALE | | Y | SL54LS33/B2A | 512 |
| 85126012A | B | 09/11/1992 | 1 | TI | | Y | SNJ54LS33FK | 512 |
| 85126012C | B | 09/11/1992 | 1 | LANSDALE | | Y | SL54LS33/B2C | 512 |
| 8512601BA | B | 09/11/1992 | 1 | LANSDALE | | Y | SL54LS33/BBA | 512 |
| 8512601CA | B | 09/11/1992 | 1 | LANSDALE | | Y | SL54LS33/BCA | 512 |
| 8512601CA | B | 09/11/1992 | 1 | TI | | Y | SNJ54LS33J | 512 |
| 8512601DA | B | 09/11/1992 | 1 | LANSDALE | | Y | SL54LS33/BDA | 512 |
| 8512601DA | B | 09/11/1992 | 1 | TI | | Y | SNJ54LS33W | 512 |
| 85126022A | B | 09/11/1992 | 2 | SARNOFF | | Y | GEM18802Q2A | 503 |
| 85126022C | B | 09/11/1992 | 2 | SARNOFF | | Y | GEM18802Q2C | 503 |
| 8512602BA | B | 09/11/1992 | 2 | SARNOFF | | Y | GEM18802QBA | 503 |
| 8512602BC | B | 09/11/1992 | 2 | SARNOFF | | Y | GEM18802QBC | 503 |
| 8512602CA | B | 09/11/1992 | 2 | SARNOFF | | Y | GEM18802QCA | 503 |
| 8512602CC | B | 09/11/1992 | 2 | SARNOFF | | Y | GEM18802QCC | 503 |
| 8512602DA | B | 09/11/1992 | 2 | SARNOFF | | Y | GEM18802QDA | 503 |
| 8512602DC | B | 09/11/1992 | 2 | SARNOFF | | Y | GEM18802QDC | 503 |
| 5962-85127013A | J | 04/25/2003 | 1 | ANALOG (2) | | Y | AD574AUE/883B | 592 |
| 5962-8512701VXA | J | 04/25/2003 | 1 | ANALOG (2) | | Y | AD574AUD/QMLV | 592 |
| 5962-8512701XA | J | 04/25/2003 | I | ANALOG (2) | | Y | AD574AUD/883B | 592 |
| 5962-8512701XC | J | 04/25/2003 | 1 | MAXIM INTEG. | | | MX574AUD/883B | 592 |
| 5962R8512701VXA | J | 04/25/2003 | 1 | ANALOG (2) | | Y | AD574AUD/QMLR | 592 |
| 5962-8512701VZA | J | 04/25/2003 | 1 | ANALOG (2) | | Y | AD574AUF/QMLV | 592 |
| 5962R8512701VZA | J | 04/25/2003 | 1 | ANALOG (2) | | Y | AD574AUF/QMLR | 592 |
| 5962-85127023A | J | 04/25/2003 | 1 | ANALOG (2) | | Y | AD574ATE/883B | 592 |
| 5962-85127023C | J | 04/25/2003 | 1 | MAXIM INTEG. | | | MX574ATE/883B | 592 |
| 5962-8512702VXA | J | 04/25/2003 | 1 | ANALOG (2) | | Y | AD574ATD/QMLV | 592 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-8512702XA | J | 04/25/2003 | I | ANALOG (2) | | Y | AD574ATD/883B | 592 |
| 5962-8512702XA | J | 04/25/2003 | 1 | MAXIM INTEG. | | | MX574ATQ/883B | 592 |
| 5962-8512702XC | J | 04/25/2003 | 1 | MAXIM INTEG. | | | MX574ATD/883B | 592 |
| 5962R8512702VXA | J | 04/25/2003 | 1 | ANALOG (2) | | Y | AD574ATD/QMLR | 592 |
| 5962-8512702VZA | J | 04/25/2003 | 1 | ANALOG (2) | | Y | AD574ATF/QMLV | 592 |
| 5962R8512702VZA | J | 04/25/2003 | 1 | ANALOG (2) | | Y | AD574ATF/QMLR | 592 |
| 5962-8512703XA | J | 04/25/2003 | 1 | INTERSIL | 07/02/2004 | Y | HI1-574AUD/883 | 592 |
| 5962-8512703YA | J | 04/25/2003 | | (NONE) | | | 574AU (GEN) | 592 |
| 5962-8512704XA | J | 04/25/2003 | 1 | INTERSIL | | Y | HI1-574ATD/883 | 592 |
| 5962-8512704YA | J | 04/25/2003 | | (NONE) | | | 574AT (GEN) | 592 |
| 5962-85127053A | J | 04/25/2003 | | (NONE) | | | 574ZA (GEN) | 592 |
| 5962-8512705XC | J | 04/25/2003 | | (NONE) | | | 574ZA (GEN) | 592 |
| 5962-85127063A | J | 04/25/2003 | | (NONE) | | | 574ZB (GEN) | 592 |
| 5962-8512706XC | J | 04/25/2003 | | (NONE) | | | 574ZB (GEN) | 592 |
| 5962-85127073C | J | 04/25/2003 | | (NONE) | | | HS574AU (GEN) | 592 |
| 5962-8512707XC | J | 04/25/2003 | | (NONE) | | | HS574AU (GEN) | 592 |
| 5962-85127083C | J | 04/25/2003 | | (NONE) | | | HS574AT (GEN) | 592 |
| 5962-8512708XC | J | 04/25/2003 | | (NONE) | | | HS574AT (GEN) | 592 |
| 85128012A | D | 07/16/2003 | 3 | TI | | Y | SNJ54HC573AFK | 341 |
| 5962-8512801VRA | D | 07/16/2003 | 3 | TI | | Y | SNV54HC573AJ | 341 |
| 8512801RA | D | 07/16/2003 | 3 | TI | | Y | SNJ54HC573AJ | 341 |
| 5962-8512801VSA | D | 07/16/2003 | 3 | TI | | Y | SNV54HC573AW | 341 |
| 8512801SA | D | 07/16/2003 | 3 | TI | | Y | SNJ54HC573AW | 341 |
| 85130012A | C | 08/05/2003 | 1 | TI | | Y | SNJ54HCT244FK | 529 |
| 5962-8513001VRA | C | 08/05/2003 | 1 | TI | | Y | SNV54HCT244J | 529 |
| 8513001RA | C | 08/05/2003 | 1 | TI | | Y | SNJ54HCT244J | 529 |
| 5962-8513001VSA | C | 08/05/2003 | 1 | TI | | Y | SNV54HCT244W | 529 |
| 5962-85131013A | E | 12/30/2002 | 1 | INTERSIL | | Y | HI4-546/883 | 195 |
| 5962-8513101XA | E | 12/30/2002 | 1 | INTERSIL | | Y | HI1-546/883 | 195 |
| 5962-85131023A | E | 12/30/2002 | 1 | INTERSIL | | Y | HI4-547/883 | 194 |
| 5962-8513102XA | E | 12/30/2002 | 1 | INTERSIL | | Y | HI1-547/883 | 194 |
| 5962-85131032A | E | 12/30/2002 | 1 | INTERSIL | 10/05/2004 | Y | HI4-549/883 | 192 |
| 5962-8513103EA | E | 12/30/2002 | 1 | INTERSIL | | Y | HI1-549/883 | 192 |
| 5962-8513104XA | E | 12/30/2002 | | (NONE) | | | IH5116 (GEN) | 195 |
| 5962-8513105XA | E | 12/30/2002 | | (NONE) | | | IH5216 (GEN) | 194 |
| 5962-85131062C | E | 12/30/2002 | 1 | MAXIM INTEG. | | | MAX359MLP/883B | 192 |
| 5962-8513106EA | E | 12/30/2002 | 1 | MAXIM INTEG. | | | MAX359MJE/883B | 192 |
| 5962-85131073A | E | 12/30/2002 | 1 | INTERSIL | | Y | HI4-506/883 | 195 |
| 5962-85131073C | E | 12/30/2002 | 1 | MAXIM INTEG. | | | DG506AAZ/883B | 195 |
| 5962-8513107XA | E | 12/30/2002 | 1 | INTERSIL | | Y | HI1-506/883 | 195 |
| 5962-85131083A | E | 12/30/2002 | 1 | INTERSIL | 10/03/2004 | Y | HI4-507/883 | 194 |
| 5962-85131083C | E | 12/30/2002 | 1 | MAXIM INTEG. | | | DG507AAZ/883B | 194 |
| 5962-8513108XA | E | 12/30/2002 | 1 | INTERSIL | 07/02/2004 | Y | HI1-507/883 | 194 |
| 5962-85131092A | E | 12/30/2002 | 1 | INTERSIL | | Y | HI4-509/883 | 192 |
| 5962-85131092C | E | 12/30/2002 | 1 | MAXIM INTEG. | | | DG509AAZ/883B | 192 |
| 5962-8513109EA | E | 12/30/2002 | 1 | INTERSIL | 10/05/2004 | Y | HI1-509/883 | 192 |
| 5962-8513301QA | | 10/27/1986 | | (NONE) | 12/24/1997 | | 8028710 (GEN) | 409 |
| 5962-8513302QA | | 10/27/1986 | | (NONE) | 12/24/1997 | | 802878 (GEN) | 409 |
| 5962-8513303QA | | 10/27/1986 | | (NONE) | 12/24/1997 | | 802875 (GEN) | 409 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-8513501YA | B | 10/28/1988 | | (NONE) | 04/15/1995 | | 27512-25 (GEN) | 663 |
| 5962-8513502YA | B | 10/28/1988 | | (NONE) | 04/15/1995 | | 27512-35 (GEN) | 663 |
| 5962-8513503YA | B | 10/28/1988 | | (NONE) | | | 27512-30 (GEN) | 663 |
| 5962-8513503ZA | B | 10/28/1988 | | (NONE) | | | 27512-30 (GEN) | 663 |
| 5962-8513504YA | B | 10/28/1988 | | (NONE) | | | 27512-45 (GEN) | 663 |
| 5962-8513504ZA | B | 10/28/1988 | | (NONE) | | | 27512-45 (GEN) | 663 |
| 5962-8513505YA | B | 10/28/1988 | | (NONE) | 04/15/1995 | | 27512-20 (GEN) | 663 |
| 5962-8514801XA | A | 08/20/1987 | | (NONE) | 12/24/1997 | | 802868 (GEN) | 403 |
| 5962-8514801YA | A | 08/20/1987 | | (NONE) | 12/24/1997 | | 802868 (GEN) | 403 |
| 5962-8514802XA | A | 08/20/1987 | | (NONE) | 12/24/1997 | | 802866 (GEN) | 403 |
| 5962-8514802YA | A | 08/20/1987 | | (NONE) | 12/24/1997 | | 802866 (GEN) | 403 |
| 5962-8514803XA | A | 08/20/1987 | | (NONE) | 12/24/1997 | | 8028610 (GEN) | 403 |
| 5962-8514803YA | A | 08/20/1987 | | (NONE) | 12/24/1997 | | 8028610 (GEN) | 403 |
| 5962-8514901RA | A | 11/23/1988 | | (NONE) | | | 82288-6 (GEN) | 420 |
| 5962-8514902RA | A | 11/23/1988 | | (NONE) | | | 82288-8 (GEN) | 420 |
| 8515201EA | E | 12/01/1993 | | (NONE) | 09/15/1995 | | 4256-15 (GEN) | 623 |
| 8515201XA | E | 12/01/1993 | | (NONE) | | | 1259-15 (GEN) | 623 |
| 8515201YA | E | 12/01/1993 | | (NONE) | 09/15/1995 | | 4256-15 (GEN) | 623 |
| 8515202EA | E | 12/01/1993 | | (NONE) | 09/15/1995 | | 4256-20 (GEN) | 623 |
| 8515202XA | E | 12/01/1993 | | (NONE) | | | 1259-20 (GEN) | 623 |
| 8515202YA | E | 12/01/1993 | | (NONE) | 09/15/1995 | | 4256-20 (GEN) | 623 |
| 8515203EA | E | 12/01/1993 | | (NONE) | 09/15/1995 | | 4256-12 (GEN) | 623 |
| 8515203XA | E | 12/01/1993 | | (NONE) | | | 1258-12 (GEN) | 623 |
| 8515203YA | E | 12/01/1993 | | (NONE) | 09/15/1995 | | 4256-12 (GEN) | 623 |
| 5962-85153012A | B | 10/18/2001 | | (NONE) | | | 54HC73 (GEN) | 152 |
| 5962-8515301CA | B | 10/18/2001 | 1 | TI | | Y | CD54HC73F3A | 152 |
| 5962-85154012A | B | 10/18/2001 | | (NONE) | 05/31/1994 | | 54HC107 (GEN) | 156 |
| 5962-8515401CA | B | 10/18/2001 | 1 | TI | | Y | CD54HC107F3A | 156 |
| 5962-85155012A | F | 01/11/2001 | 1 | TI | | Y | TIBPAL16L8-20MFKB | 431 |
| 5962-8515501RA | F | 01/11/2001 | 1 | TI | | Y | TIBPAL16L8-20MJB | 431 |
| 5962-8515501SA | F | 01/11/2001 | 1 | TI | | Y | TIBPAL16L8-20MWB | 431 |
| 5962-85155022A | F | 01/11/2001 | 1 | TI | | Y | TIBPAL16R8-20MFKB | 431 |
| 5962-8515502RA | F | 01/11/2001 | 1 | TI | | Y | TIBPAL16R8-20MJB | 431 |
| 5962-8515502SA | F | 01/11/2001 | 1 | TI | | Y | TIBPAL16R8-20MWB | 431 |
| 5962-85155032A | F | 01/11/2001 | 1 | TI | | Y | TIBPAL16R6-20MFKB | 431 |
| 5962-8515503RA | F | 01/11/2001 | 1 | TI | | Y | TIBPAL16R6-20MJB | 431 |
| 5962-8515503SA | F | 01/11/2001 | 1 | TI | | Y | TIBPAL16R6-20MWB | 431 |
| 5962-85155042A | F | 01/11/2001 | 1 | TI | | Y | TIBPAL16R4-20MFKB | 431 |
| 5962-8515504RA | F | 01/11/2001 | 1 | TI | | Y | TIBPAL16R4-20MJB | 431 |
| 5962-8515504SA | F | 01/11/2001 | 1 | TI | | Y | TIBPAL16R4-20MWB | 431 |
| 5962-85155052A | F | 01/11/2001 | 1 | TI | | Y | TIBPAL16L8-30MFKB | 431 |
| 5962-8515505RA | F | 01/11/2001 | 1 | TI | | Y | TIBPAL16L8-30MJB | 431 |
| 5962-8515505SA | F | 01/11/2001 | 1 | TI | | Y | TIBPAL16L8-30MWB | 431 |
| 5962-85155062A | F | 01/11/2001 | 1 | TI | | Y | TIBPAL16R8-30MFKB | 431 |
| 5962-8515506RA | F | 01/11/2001 | 1 | TI | | Y | TIBPAL16R8-30MJB | 431 |
| 5962-8515506SA | F | 01/11/2001 | 1 | TI | | Y | TIBPAL16R8-30MWB | 431 |
| 5962-85155072A | F | 01/11/2001 | 1 | TI | | Y | TIBPAL16R6-30MFKB | 431 |
| 5962-8515507RA | F | 01/11/2001 | 1 | TI | | Y | TIBPAL16R6-30MJB | 431 |
| 5962-8515507SA | F | 01/11/2001 | 1 | TI | | Y | TIBPAL16R6-30MWB | 431 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-85155082A | F | 01/11/2001 | 1 | TI | | Y | TIBPAL16R4-30MFKB | 431 |
| 5962-8515508RA | F | 01/11/2001 | 1 | TI | | Y | TIBPAL16R4-30MJB | 431 |
| 5962-8515508SA | F | 01/11/2001 | 1 | TI | | Y | TIBPAL16R4-30MWB | 431 |
| 5962-85155092A | F | 01/11/2001 | 1 | TI | | Y | TIBPAL16L8-15MFKB | 431 |
| 5962-8515509RA | F | 01/11/2001 | 1 | TI | | Y | TIBPAL16L8-15MJB | 431 |
| 5962-8515509SA | F | 01/11/2001 | 1 | TI | | Y | TIBPAL16L8-15MWB | 431 |
| 5962-85155102A | F | 01/11/2001 | 1 | TI | | Y | TIBPAL16R8-15MFKB | 431 |
| 5962-8515510RA | F | 01/11/2001 | 1 | TI | | Y | TIBPAL16R8-15MJB | 431 |
| 5962-8515510SA | F | 01/11/2001 | 1 | TI | | Y | TIBPAL16R8-15MWB | 431 |
| 5962-85155112A | F | 01/11/2001 | 1 | TI | | Y | TIBPAL16R6-15MFKB | 431 |
| 5962-8515511RA | F | 01/11/2001 | 1 | TI | | Y | TIBPAL16R6-15MJB | 431 |
| 5962-8515511SA | F | 01/11/2001 | 1 | TI | | Y | TIBPAL16R6-15MWB | 431 |
| 5962-85155122A | F | 01/11/2001 | 1 | TI | | Y | TIBPAL16R4-15MFKB | 431 |
| 5962-8515512RA | F | 01/11/2001 | 1 | TI | | Y | TIBPAL16R4-15MJB | 431 |
| 5962-8515512SA | F | 01/11/2001 | 1 | TI | | Y | TIBPAL16R4-15MWB | 431 |
| 5962-85155132A | F | 01/11/2001 | 3 | TI | | Y | TIBPAL16L8-12MFKB | 431 |
| 5962-8515513RA | F | 01/11/2001 | 3 | TI | | Y | TIBPAL16L8-12MJB | 431 |
| 5962-8515513SA | F | 01/11/2001 | 3 | TI | | Y | TIBPAL16L8-12MWB | 431 |
| 5962-85155142A | F | 01/11/2001 | 3 | TI | | Y | TIBPAL16R8-12MFKB | 431 |
| 5962-8515514RA | F | 01/11/2001 | 3 | TI | | Y | TIBPAL16R8-12MJB | 431 |
| 5962-8515514SA | F | 01/11/2001 | 3 | TI | | Y | TIBPAL16R8-12MWB | 431 |
| 5962-85155152A | F | 01/11/2001 | 3 | TI | | Y | TIBPAL16R6-12MFKB | 431 |
| 5962-8515515RA | F | 01/11/2001 | 3 | TI | | Y | TIBPAL16R6-12MJB | 431 |
| 5962-8515515SA | F | 01/11/2001 | 3 | TI | | Y | TIBPAL16R6-12MWB | 431 |
| 5962-85155162A | F | 01/11/2001 | 2 | TI | | Y | TIBPAL16R4-12MFKB | 431 |
| 5962-8515516RA | F | 01/11/2001 | 2 | TI | | Y | TIBPAL16R4-12MJB | 431 |
| 5962-8515516SA | F | 01/11/2001 | 2 | TI | | Y | TIBPAL16R4-12MWB | 431 |
| 5962-85155172A | F | 01/11/2001 | 2 | TI | | Y | TIBPAL16L8-10MFKB | 431 |
| 5962-8515517RA | F | 01/11/2001 | 2 | TI | | Y | TIBPAL16L8-10MJB | 431 |
| 5962-8515517SA | F | 01/11/2001 | 2 | TI | | Y | TIBPAL16L8-10MWB | 431 |
| 5962-85155182A | F | 01/11/2001 | 2 | TI | | Y | TIBPAL16R8-10MFKB | 431 |
| 5962-8515518RA | F | 01/11/2001 | 2 | TI | | Y | TIBPAL16R8-10MJB | 431 |
| 5962-8515518SA | F | 01/11/2001 | 2 | TI | | Y | TIBPAL16R8-10MWB | 431 |
| 5962-85155192A | F | 01/11/2001 | 2 | TI | | Y | TIBPAL16R6-10MFKB | 431 |
| 5962-8515519RA | F | 01/11/2001 | 2 | TI | | Y | TIBPAL16R6-10MJB | 431 |
| 5962-8515519SA | F | 01/11/2001 | 2 | TI | | Y | TIBPAL16R6-10MWB | 431 |
| 5962-85155202A | F | 01/11/2001 | 2 | TI | 07/15/2005 | Y | TIBPAL16R4-10MFKB | 431 |
| 5962-8515520RA | F | 01/11/2001 | 2 | TI | 07/15/2005 | Y | TIBPAL16R4-10MJB | 431 |
| 5962-8515520SA | F | 01/11/2001 | 2 | TI | 07/15/2005 | Y | TIBPAL16R4-10MWB | 431 |
| 5962-85155212A | F | 01/11/2001 | 2 | TI | | Y | TIBPAL16R8-7MFKB | 431 |
| 5962-8515521RA | F | 01/11/2001 | 2 | TI | | Y | TIBPAL16R8-7MJB | 431 |
| 5962-8515521SA | F | 01/11/2001 | 2 | TI | | Y | TIBPAL16R8-7MWB | 431 |
| 5962-85155222A | F | 01/11/2001 | 1 | TI | | Y | TIBPAL16R4-7MFKB | 431 |
| 5962-8515522RA | F | 01/11/2001 | 1 | TI | | Y | TIBPAL16R4-7MJB | 431 |
| 5962-8515522SA | F | 01/11/2001 | 1 | TI | | Y | TIBPAL16R4-7MWB | 431 |
| 8550001CA | C | 11/30/2000 | 1 | ROCHESTER | | | UHD508R/883C | 530 |
| 8550001DA | C | 11/30/2000 | | (NONE) | | | UH508 (GEN) | 530 |
| 5962-8550101CA | C | 11/15/2001 | 0 | NATIONAL | | Y | CD40106BMJ/883 | 541 |
| 5962-8550102CA | C | 11/15/2001 | | (NONE) | 09/30/1995 | | 14584B (GEN) | 541 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 8550201UA | C | 09/15/2003 | 1 | LANSDALE | | Y | 8X305/BUA | 420 |
| 8550201XA | C | 09/15/2003 | 1 | LANSDALE | | Y | 8X305/BXA | 420 |
| 8550201YA | C | 09/15/2003 | 1 | LANSDALE | | Y | 8X305/BYA | 420 |
| 8550202UA | C | 09/15/2003 | | (NONE) | | | 8X305-10 (GEN) | 420 |
| 8550202XA | C | 09/15/2003 | | (NONE) | | | 8X305-10 (GEN) | 420 |
| 8550202YA | C | 09/15/2003 | | (NONE) | | | 8X305-10 (GEN) | 420 |
| 5962-8550301QA | A | 05/18/1987 | | (NONE) | | | 8X320 (GEN) | 420 |
| 5962-8550301UA | A | 05/18/1987 | | (NONE) | | | 8X320 (GEN) | 420 |
| 85504012A | C | 10/18/2001 | 2 | TI | | Y | SNJ54HCT138FK | 282 |
| 8550401EA | C | 10/18/2001 | 2 | TI | | Y | SNJ54HCT138J | 282 |
| 8550401FA | C | 10/18/2001 | 2 | TI | | Y | SNJ54HCT138W | 282 |
| 85505012A | B | 11/16/2001 | 2 | TI | | Y | SNJ54HCT240FK | 529 |
| 8550501RA | B | 11/16/2001 | 2 | TI | | Y | SNJ54HCT240J | 529 |
| 85506012A | D | 09/11/2003 | 2 | TI | | Y | SNJ54HCT245FK | 590 |
| 5962-8550601VRA | D | 09/11/2003 | 2 | TI | | Y | SNV54HCT245J | 590 |
| 8550601RA | D | 09/11/2003 | 2 | TI | | Y | SNJ54HCT245J | 590 |
| 8550601RA | D | 09/11/2003 | 2 | TI | | Y | CD54HCT245F3A | 590 |
| 5962-8550601VSA | D | 09/11/2003 | 2 | TI | | Y | SNV54HCT245W | 590 |
| 85507012A | E | 09/11/2003 | 1 | TI | | Y | SNJ54HCT374FK | 159 |
| 5962-8550701VRA | E | 09/11/2003 | 1 | TI | | Y | SNV54HCT374J | 159 |
| 8550701RA | E | 09/11/2003 | 1 | TI | | Y | SNJ54HCT374J | 159 |
| 8550701RA | E | 09/11/2003 | 1 | TI | | Y | CD54HCT374F3A | 159 |
| 5962-8550701VSA | E | 09/11/2003 | 1 | TI | | Y | SNV54HCT374W | 159 |
| 85508012A | B | 01/31/2002 | 1 | LANSDALE | | Y | SL54LS353/B2A | 274 |
| 85508012A | B | 01/31/2002 | 2 | SARNOFF | | Y | GEM23001Q2A | 274 |
| 85508012C | B | 01/31/2002 | 2 | SARNOFF | | Y | GEM23001Q2C | 274 |
| 8550801EA | B | 01/31/2002 | 1 | LANSDALE | | Y | SL54LS353/BEA | 274 |
| 8550801EA | B | 01/31/2002 | 2 | SARNOFF | | Y | GEM23001QEA | 274 |
| 8550801EC | B | 01/31/2002 | 2 | SARNOFF | | Y | GEM23001QEC | 274 |
| 8550801FA | B | 01/31/2002 | 1 | LANSDALE | | Y | SL54LS353/BFA | 274 |
| 8550801FA | B | 01/31/2002 | 2 | SARNOFF | | Y | GEM23001QFA | 274 |
| 8550801FC | B | 01/31/2002 | 2 | SARNOFF | | Y | GEM23001QFC | 274 |
| 85511012A | C | 02/20/2002 | I | TI | | Y | SNJ54F245FK | 590 |
| 8551101RA | C | 02/20/2002 | I | TI | | Y | SNJ54F245J | 590 |
| 8551101SA | C | 02/20/2002 | I | TI | | Y | SNJ54F245W | 590 |
| 5962-8551401V2A | G | 02/07/2001 | 1 | ANALOG (5) | | Y | REF02ARC/QMLV | 785 |
| 5962R8551401V2A | G | 02/07/2001 | 1 | ANALOG (5) | | Y | REF02ARC/QMLR | 785 |
| 85514012A | G | 02/07/2001 | 1 | ANALOG (5) | | Y | REF-02ARC/883 | 785 |
| 5962-8551401VGA | G | 02/07/2001 | 1 | ANALOG (5) | | Y | REF02AJ/QMLV | 785 |
| 5962R8551401VGA | G | 02/07/2001 | 1 | ANALOG (5) | | Y | REF02AJ/QMLR | 785 |
| 8551401GA | G | 02/07/2001 | 1 | ANALOG (5) | | Y | REF02AJ/883 | 785 |
| 5962-8551401VHA | G | 02/07/2001 | 1 | ANALOG (5) | | Y | REF02AL/QMLV | 785 |
| 5962R8551401VHA | G | 02/07/2001 | 1 | ANALOG (5) | | Y | REF02AL/QMLR | 785 |
| 5962-8551401VPA | G | 02/07/2001 | 1 | ANALOG (5) | | Y | REF02AZ/QMLV | 785 |
| 5962R8551401VPA | G | 02/07/2001 | 1 | ANALOG (5) | | Y | REF02AZ/QMLR | 785 |
| 8551401PA | G | 02/07/2001 | 1 | ANALOG (5) | | Y | REF-02AZ/883 | 785 |
| 85514022C | G | 02/07/2001 | | (NONE) | | | REF02 (GEN) | 785 |
| 8551402GC | G | 02/07/2001 | | (NONE) | | | REF02 (GEN) | 785 |
| 8551402PA | G | 02/07/2001 | | (NONE) | | | REF02 (GEN) | 785 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 8551403GC | G | 02/07/2001 | 1 | MAXIM INTEG. | | | REF02AJ/883B | 785 |
| 8551403PA | G | 02/07/2001 | 1 | MAXIM INTEG. | | | REF02AZ/883B | 785 |
| 85514042C | G | 02/07/2001 | 1 | MAXIM INTEG. | | | REF02RC/883B | 785 |
| 8551404GC | G | 02/07/2001 | 1 | MAXIM INTEG. | | | REF02J/883B | 785 |
| 8551404PA | G | 02/07/2001 | 1 | MAXIM INTEG. | | | REF02Z/883B | 785 |
| 85515012A | F | 02/07/2002 | 1 | MICROSEMI | | Y | SG1526BL/883 | 787 |
| 85515012A | F | 02/07/2002 | 2 | TI | | Y | UC1526L/883B | 787 |
| 8551501VA | F | 02/07/2002 | I | MICROSEMI | | Y | SG1526BJ/883 | 787 |
| 8551501VA | F | 02/07/2002 | I | TI | | Y | UC1526J/883 | 787 |
| 85515022A | F | 02/07/2002 | 2 | TI | | Y | UC1526AL/883B | 787 |
| 8551502VA | F | 02/07/2002 | 2 | TI | | Y | UC1526AJ/883 | 787 |
| 8551701QA | | 05/14/1986 | 1 | QP SEMI | | | Z8036ACMB | 421 |
| 8551701YA | | 05/14/1986 | 1 | QP SEMI | | | Z8036ALMB | 421 |
| 8551702QA | | 05/14/1986 | 1 | QP SEMI | | | Z8036CMB | 421 |
| 8551702YA | | 05/14/1986 | 1 | QP SEMI | | | Z8036LMB | 421 |
| 5962-8551801QA | A | 11/06/1987 | | (NONE) | | | Z8030A (GEN) | 420 |
| 5962-8551801YA | A | 11/06/1987 | | (NONE) | | | Z8030A (GEN) | 420 |
| 5962-8551802QA | A | 11/06/1987 | | (NONE) | | | Z8030 (GEN) | 420 |
| 5962-8551802YA | A | 11/06/1987 | | (NONE) | | | Z8030 (GEN) | 420 |
| 85519012A | B | 11/26/2001 | 1 | TI | | Y | SNJ54HC259FK | 341 |
| 8551901EA | B | 11/26/2001 | 1 | TI | | Y | SNJ54HC259J | 341 |
| 8551901FA | B | 11/26/2001 | 1 | TI | | Y | SNJ54HC259W | 341 |
| 8552001XA | A | 11/12/1987 | | (NONE) | 12/24/1997 | | 8397 (GEN) | 420 |
| 8552001YA | A | 11/12/1987 | | (NONE) | 12/24/1997 | | 8397 (GEN) | 420 |
| 5962-8552301QA | A | 02/03/2003 | 1 | QP SEMI | | Y | 9513A/BQA | 424 |
| 5962-8552301QA | A | 02/03/2003 | 1 | ROCHESTER | | Y | 9513A/BQA | 424 |
| 5962-8552301XA | A | 02/03/2003 | 1 | QP SEMI | | Y | 9513A/BUA | 424 |
| 5962-8552301XA | A | 02/03/2003 | 1 | ROCHESTER | | Y | 9513A/BUA | 424 |
| 5962-8552501XA | B | 10/29/1990 | | (NONE) | 5962-3829401MXA | | 8808AC-15 (GEN) | 620 |
| 5962-8552501YA | B | 10/29/1990 | | (NONE) | 5962-3829401MYA | | 8808AC-15 (GEN) | 620 |
| 5962-8552502XA | B | 10/29/1990 | | PYRAMID | 5962-3829403MXA | | P4C164-120DWMB | 620 |
| 5962-8552502YA | B | 10/29/1990 | | (NONE) | 5962-3829403MYA | | 8808AC-12 (GEN) | 620 |
| 5962-8552503XA | B | 10/29/1990 | | PYRAMID | 5962-3829405MXA | | P4C164-100DWMB | 620 |
| 5962-8552503YA | B | 10/29/1990 | | (NONE) | 5962-3829405MYA | | 8808AC-10 (GEN) | 620 |
| 5962-8552504XA | B | 10/29/1990 | | PYRAMID | 5962-3829407MXA | | P4C164-70DWMB | 620 |
| 5962-8552504YA | B | 10/29/1990 | | (NONE) | 5962-3829407MYA | | 8808AC-70 (GEN) | 620 |
| 5962-8552505TA | B | 10/29/1990 | | (NONE) | 5962-3829409MTA | | 7C185-55 (GEN) | 620 |
| 5962-8552505UA | B | 10/29/1990 | | (NONE) | 5962-3829423MUA | | 7C185-55 (GEN) | 620 |
| 5962-8552505XA | B | 10/29/1990 | | (NONE) | 5962-3829409MXA | | 8808AC-55 (GEN) | 620 |
| 5962-8552505YA | B | 10/29/1990 | | (NONE) | 5962-3829409MYA | | 8808AC-55 (GEN) | 620 |
| 5962-8552505ZA | B | 10/29/1990 | | (NONE) | 5962-3829409MZA | | 7C185-55 (GEN) | 620 |
| 5962-8552506TA | B | 10/29/1990 | | (NONE) | 5962-3829411MTA | | 5C6408-45 (GEN) | 620 |
| 5962-8552506UA | B | 10/29/1990 | | (NONE) | 5962-3829425MUA | | 7C185-45 (GEN) | 620 |
| 5962-8552506XA | B | 10/29/1990 | | PYRAMID | 5962-3829411MXA | | P4C164-45DWMB | 620 |
| 5962-8552506YA | B | 10/29/1990 | | (NONE) | 5962-3829411MYA | | 5C6408-45 (GEN) | 620 |
| 5962-8552506ZA | B | 10/29/1990 | | (NONE) | 5962-3829411MZA | | 7C185-45 (GEN) | 620 |
| 5962-8552507TA | B | 10/29/1990 | | (NONE) | 03/05/1996 | | 7C185-35 (GEN) | 620 |
| 5962-8552507UA | B | 10/29/1990 | | (NONE) | 5962-3829427MUA | | 7C185-35 (GEN) | 620 |
| 5962-8552507XA | B | 10/29/1990 | | PYRAMID | 5962-3829413MXA | | P4C164-35DWMB | 620 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-8552507YA | B | 10/29/1990 | | (NONE) | 5962-3829413MYA | | 7164S35 (GEN) | 620 |
| 5962-8552507ZA | B | 10/29/1990 | | (NONE) | 5962-3829413MZA | | 7C185-35 (GEN) | 620 |
| 5962-8552508TA | B | 10/29/1990 | | (NONE) | 5962-3829412MTA | | 7C185L-35 (GEN) | 620 |
| 5962-8552508UA | B | 10/29/1990 | | (NONE) | 5962-3829426MUA | | 7C185L-35 (GEN) | 620 |
| 5962-8552508XA | B | 10/29/1990 | | PYRAMID | 5962-3829412MXA | | P4C164L-35DWMB | 620 |
| 5962-8552508YA | B | 10/29/1990 | | (NONE) | 5962-3829412MYA | | 7164L35 (GEN) | 620 |
| 5962-8552508ZA | B | 10/29/1990 | | (NONE) | 5962-3829412MZA | | 7164L35 (GEN) | 620 |
| 5962-8552509TA | B | 10/29/1990 | | (NONE) | 5962-3829410MTA | | 7C185L-45 (GEN) | 620 |
| 5962-8552509UA | B | 10/29/1990 | | (NONE) | 5962-3829424MUA | | 7C185L-45 (GEN) | 620 |
| 5962-8552509XA | B | 10/29/1990 | | PYRAMID | 5962-3829410MXA | | P4C164L-45DWMB | 620 |
| 5962-8552509YA | B | 10/29/1990 | | (NONE) | 5962-3829410MYA | | 7164L45 (GEN) | 620 |
| 5962-8552509ZA | B | 10/29/1990 | | (NONE) | 5962-3829410MZA | | 7164L45 (GEN) | 620 |
| 5962-8552510TA | B | 10/29/1990 | | (NONE) | 5962-3829408MTA | | 7C185L-55 (GEN) | 620 |
| 5962-8552510UA | B | 10/29/1990 | | (NONE) | 5962-3829422MUA | | 7C185L-55 (GEN) | 620 |
| 5962-8552510XA | B | 10/29/1990 | | PYRAMID | 5962-3829408MXA | | P4C164L-55DWMB | 620 |
| 5962-8552510YA | B | 10/29/1990 | | (NONE) | 5962-3829408MYA | | 7164L55 (GEN) | 620 |
| 5962-8552510ZA | B | 10/29/1990 | | (NONE) | 5962-3829408MZA | | 7164L55 (GEN) | 620 |
| 5962-8552511XA | B | 10/29/1990 | | PYRAMID | 5962-3829406MXA | | P4C164L-70DWMB | 620 |
| 5962-8552511YA | B | 10/29/1990 | | (NONE) | 5962-3829406MYA | | 7164L70 (GEN) | 620 |
| 5962-8552512XA | B | 10/29/1990 | 1 | IDT | 5962-3829404MXA | Y | IDT7164L85DB | 620 |
| 5962-8552512XA | B | 10/29/1990 | | PYRAMID | 5962-3829404MXA | | P4C164L-100DWMB | 620 |
| 5962-8552512YA | B | 10/29/1990 | 1 | IDT | 5962-3829404MYA | Y | IDT7164L85LB | 620 |
| 5962-8552513XA | B | 10/29/1990 | | PYRAMID | 5962-3829402MXA | | P4C164L-120DWMB | 620 |
| 5962-8552513YA | B | 10/29/1990 | | (NONE) | 5962-3829402MYA | | 8808ACL-12 (GEN) | 620 |
| 5962-85526013A | B | 03/22/1996 | | (NONE) | 08/02/1996 | | 27PS191 (GEN) | 658 |
| 5962-8552601JA | B | 03/22/1996 | | (NONE) | 08/02/1996 | | 27PS191 (GEN) | 658 |
| 5962-8552601KA | B | 03/22/1996 | | (NONE) | 08/02/1996 | | 27PS191 (GEN) | 658 |
| 5962-8552601XA | B | 03/22/1996 | | (NONE) | 08/02/1996 | | 27PS191 (GEN) | 658 |
| 5962-85526023A | B | 03/22/1996 | | (NONE) | 08/02/1996 | | 27PS191A (GEN) | 658 |
| 5962-8552602JA | B | 03/22/1996 | | (NONE) | 08/02/1996 | | 27PS191A (GEN) | 658 |
| 5962-8552602KA | B | 03/22/1996 | | (NONE) | | | 27PS191A (GEN) | 658 |
| 5962-8552602XA | B | 03/22/1996 | | (NONE) | 08/02/1996 | | 27PS191A (GEN) | 658 |
| 5962-8552603LA | B | 03/22/1996 | | (NONE) | 08/02/1996 | | 27PS291 (GEN) | 658 |
| 5962-8552604LA | B | 03/22/1996 | | (NONE) | 08/02/1996 | | 27PS291A (GEN) | 658 |
| 5962-85527013A | B | 03/22/1996 | | (NONE) | 08/02/1996 | | 27S45 (GEN) | 658 |
| 5962-8552701KA | B | 03/22/1996 | | (NONE) | | | 27S45 (GEN) | 658 |
| 5962-8552701LA | B | 03/22/1996 | | (NONE) | 08/02/1996 | | 27S45 (GEN) | 658 |
| 5962-8552701XA | B | 03/22/1996 | | (NONE) | 08/02/1996 | | 27S45 (GEN) | 658 |
| 5962-85527023A | B | 03/22/1996 | | (NONE) | 08/02/1996 | | 27S45A (GEN) | 658 |
| 5962-8552702KA | B | 03/22/1996 | | (NONE) | 08/02/1996 | | 27S45A (GEN) | 658 |
| 5962-8552702LA | B | 03/22/1996 | | (NONE) | 08/02/1996 | | 27S45A (GEN) | 658 |
| 5962-8552702XA | B | 03/22/1996 | | (NONE) | 08/02/1996 | | 27S45A (GEN) | 658 |
| 5962-85527033A | B | 03/22/1996 | | (NONE) | 08/02/1996 | | 27S47 (GEN) | 658 |
| 5962-8552703KA | B | 03/22/1996 | | (NONE) | | | 27S47 (GEN) | 658 |
| 5962-8552703LA | B | 03/22/1996 | | (NONE) | 08/02/1996 | | 27S47 (GEN) | 658 |
| 5962-8552703XA | B | 03/22/1996 | | (NONE) | | | 27S47 (GEN) | 658 |
| 5962-85527043A | B | 03/22/1996 | | (NONE) | 08/02/1996 | | 27S47A (GEN) | 658 |
| 5962-8552704KA | B | 03/22/1996 | | (NONE) | 08/02/1996 | | 27S47A (GEN) | 658 |
| 5962-8552704LA | B | 03/22/1996 | | (NONE) | 08/02/1996 | | 27S47A (GEN) | 658 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-8552704XA | B | 03/22/1996 | | (NONE) | 08/02/1996 | | 27S47A (GEN) | 658 |
| 5962-85528012A | | 11/19/1986 | | (NONE) | | | 82C89 (GEN) | 420 |
| 5962-8552801RA | | 11/19/1986 | | (NONE) | 03/25/2001 | | 82C89 (GEN) | 420 |
| 8600801EA | C | 04/07/1993 | | (NONE) | 03/30/2001 | | LT685 (GEN) | 772 |
| 8600801IA | C | 04/07/1993 | | (NONE) | 03/30/2001 | | LT685 (GEN) | 772 |
| 8600802EA | C | 04/07/1993 | | (NONE) | 03/30/2001 | | LT685 (GEN) | 772 |
| 8600802IA | C | 04/07/1993 | | (NONE) | 03/30/2001 | | LT685 (GEN) | 772 |
| 8600803EA | C | 04/07/1993 | | (NONE) | | | 6685 (GEN) | 772 |
| 8600803IA | C | 04/07/1993 | | (NONE) | | | 6685 (GEN) | 772 |
| 86008042A | C | 04/07/1993 | | (NONE) | 10/27/2000 | | 96685 (GEN) | 772 |
| 8600804EA | C | 04/07/1993 | | (NONE) | 10/27/2000 | | 96685 (GEN) | 772 |
| 8600804IA | C | 04/07/1993 | | (NONE) | 10/27/2000 | | 96685 (GEN) | 772 |
| 86009012A | C | 11/05/1991 | 1 | ROCHESTER | | Y | 54HC390/B2A | 300 |
| 8600901EA | C | 11/05/1991 | 1 | ROCHESTER | | Y | 54HC390/BEA | 300 |
| 86010012A | C | 06/18/2004 | 1 | TI | | Y | SNJ54HCU04FK | 143 |
| 8601001CA | C | 06/18/2004 | 1 | TI | | Y | SNJ54HCU04J | 143 |
| 86011012A | B | 11/26/2001 | | (NONE) | | | 54HC4017 (GEN) | 306 |
| 8601101EA | B | 11/26/2001 | 1 | TI | | Y | CD54HC4017F3A | 306 |
| 86012012A | B | 11/21/2001 | 1 | TI | | Y | SNJ54HC4024FK | 305 |
| 8601201CA | B | 11/21/2001 | 1 | TI | | Y | SNJ54HC4024J | 305 |
| 86013012A | D | 01/25/2002 | | (NONE) | 12/01/1993 | | 54HC85 (GEN) | 209 |
| 8601301EA | D | 01/25/2002 | 1 | TI | | Y | CD54HC85F3A | 209 |
| 5962-8601301VFA | D | 01/25/2002 | | (NONE) | | | 54HC85 (GEN) | 209 |
| 8601301FA | D | 01/25/2002 | | (NONE) | | | 54HC85 (GEN) | 209 |
| 5962-8601301VXA | D | 01/25/2002 | 2 | STMICRO | | Y | 54HC85K02V | 209 |
| 5962-8601301VXC | D | 01/25/2002 | 2 | STMICRO | | Y | 54HC85K01V | 209 |
| 8601301XA | D | 01/25/2002 | 2 | STMICRO | | Y | 54HC85K02Q | 209 |
| 8601301XC | D | 01/25/2002 | 2 | STMICRO | | Y | 54HC85K01Q | 209 |
| 86014012A | G | 06/27/2002 | 1 | NATIONAL | | Y | LM119E-SMD | 774 |
| 8601401CA | G | 06/27/2002 | 1 | NATIONAL | | Y | LM119J-SMD | 774 |
| 8601401DA | G | 06/27/2002 | | (NONE) | | | LM119 (GEN) | 774 |
| 8601401HA | G | 06/27/2002 | 1 | NATIONAL | | Y | LM119W-SMD | 774 |
| 8601401IA | G | 06/27/2002 | 1 | NATIONAL | | Y | LM119H-SMD | 774 |
| 8601401XA | G | 06/27/2002 | 1 | NATIONAL | | Y | LM119WG-SMD | 774 |
| 8601402CA | G | 06/27/2002 | | (NONE) | 03/30/2001 | | LT119A (GEN) | 774 |
| 8601402IA | G | 06/27/2002 | | (NONE) | 03/30/2001 | | LT119A (GEN) | 774 |
| 5962-8601501XA | A | 06/17/1988 | | (NONE) | | | 5C6401-35 (GEN) | 620 |
| 5962-8601501YA | A | 06/17/1988 | 1 | IDT | | Y | IDT7187S35DB | 620 |
| 5962-8601501ZA | A | 06/17/1988 | | (NONE) | | | 5C6401-35 (GEN) | 620 |
| 5962-8601502XA | A | 06/17/1988 | | (NONE) | | | 5C6401-35 (GEN) | 620 |
| 5962-8601502YA | A | 06/17/1988 | | (NONE) | 11/10/1998 | | 7C187-35 (GEN) | 620 |
| 5962-8601502ZA | A | 06/17/1988 | | (NONE) | | | 5C6401-35 (GEN) | 620 |
| 5962-8601503XA | A | 06/17/1988 | | (NONE) | | | 5C6401-45 (GEN) | 620 |
| 5962-8601503YA | A | 06/17/1988 | 1 | IDT | | Y | IDT7187S45DB | 620 |
| 5962-8601503ZA | A | 06/17/1988 | | (NONE) | | | 5C6401-45 (GEN) | 620 |
| 5962-8601504XA | A | 06/17/1988 | | (NONE) | | | 5C6401-45 (GEN) | 620 |
| 5962-8601504YA | A | 06/17/1988 | 1 | IDT | | Y | IDT7187L45DB | 620 |
| 5962-8601504ZA | A | 06/17/1988 | | (NONE) | | | 5C6401-45 (GEN) | 620 |
| 5962-8601505XA | A | 06/17/1988 | | (NONE) | | | 5C6401-55 (GEN) | 620 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-8601505YA | A | 06/17/1988 | 1 | IDT | | Y | IDT7187S55DB | 620 |
| 5962-8601505ZA | A | 06/17/1988 | | (NONE) | | | 5C6401-55 (GEN) | 620 |
| 5962-8601506XA | A | 06/17/1988 | | (NONE) | | | 5C6401-55 (GEN) | 620 |
| 5962-8601506YA | A | 06/17/1988 | 1 | IDT | | Y | IDT7187L55DB | 620 |
| 5962-8601506ZA | A | 06/17/1988 | | (NONE) | | | 5C6401-55 (GEN) | 620 |
| 5962-8601507XA | A | 06/17/1988 | | (NONE) | | | 61CD64S-70 (GEN) | 620 |
| 5962-8601507YA | A | 06/17/1988 | 1 | IDT | | Y | IDT7187S70DB | 620 |
| 5962-8601507ZA | A | 06/17/1988 | | (NONE) | 08/10/1999 | | 7187S70 (GEN) | 620 |
| 5962-8601508XA | A | 06/17/1988 | | (NONE) | | | 61CD64L-70 (GEN) | 620 |
| 5962-8601508YA | A | 06/17/1988 | 1 | IDT | | Y | IDT7187L70DB | 620 |
| 5962-8601508ZA | A | 06/17/1988 | | (NONE) | 08/10/1999 | | 7187L70 (GEN) | 620 |
| 5962-8601601QA | B | 08/11/2003 | 1 | INTERSIL | 10/05/2004 | Y | MD80C88/883 | 402 |
| 5962-8601601XA | B | 08/11/2003 | | (NONE) | 03/25/2001 | | 80C88 (GEN) | 402 |
| 8601701QA | C | 02/13/2003 | 1 | ROCHESTER | | Y | 2904/BQA | 420 |
| 8601701YA | C | 02/13/2003 | 1 | ROCHESTER | | Y | 2904/BYA | 420 |
| 8601701YC | C | 02/13/2003 | 1 | ROCHESTER | | Y | 2904/BYC | 420 |
| 8601801QA | B | 10/15/1990 | 1 | ROCHESTER | | Y | 55500EJ/BQA | 299 |
| 8601801XA | B | 10/15/1990 | 1 | ROCHESTER | | Y | 55500EFJ/BXA | 299 |
| 8601801ZA | B | 10/15/1990 | 1 | ROCHESTER | | Y | 55500EFD/BZA | 299 |
| 8601802QA | B | 10/15/1990 | 1 | ROCHESTER | | Y | 55501EJ/BQA | 299 |
| 8601802XA | B | 10/15/1990 | 1 | ROCHESTER | | Y | 55501EFJ/BXA | 299 |
| 8601802ZA | B | 10/15/1990 | 1 | ROCHESTER | | Y | 55501EFD/BZA | 299 |
| 8602001EA | B | 06/26/1996 | 1 | ROCHESTER | | Y | 27LS00/BEA | 606 |
| 8602001EA | B | 06/26/1996 | 2 | SARNOFF | | Y | GEM09201QEA | 606 |
| 8602001EC | B | 06/26/1996 | 2 | SARNOFF | | Y | GEM09201QEC | 606 |
| 8602001FA | B | 06/26/1996 | 1 | ROCHESTER | | Y | 27LS00/BFA | 606 |
| 8602001FA | B | 06/26/1996 | 2 | SARNOFF | | Y | GEM09201QFA | 606 |
| 8602001FC | B | 06/26/1996 | 2 | SARNOFF | | Y | GEM09201QFC | 606 |
| 8602002EA | B | 06/26/1996 | 1 | ROCHESTER | | Y | 27LS00A/BEA | 606 |
| 8602002EA | B | 06/26/1996 | 2 | SARNOFF | | Y | GEM09202QEA | 606 |
| 8602002EC | B | 06/26/1996 | 2 | SARNOFF | | Y | GEM09202QEC | 606 |
| 8602002FA | B | 06/26/1996 | 1 | ROCHESTER | | Y | 27LS00A/BFA | 606 |
| 8602002FA | B | 06/26/1996 | 2 | SARNOFF | | Y | GEM09202QFA | 606 |
| 8602002FC | B | 06/26/1996 | 2 | SARNOFF | | Y | GEM09202QFC | 606 |
| 8602003EA | B | 06/26/1996 | | (NONE) | | | 27LS01 (GEN) | 606 |
| 8602003FA | B | 06/26/1996 | | (NONE) | | | 27LS01 (GEN) | 606 |
| 8602004EA | B | 06/26/1996 | | (NONE) | | | 27LS01A (GEN) | 606 |
| 8602004FA | B | 06/26/1996 | | (NONE) | | | 27LS01A (GEN) | 606 |
| 5962-8602101XA | D | 10/05/1992 | | (NONE) | | | 68881-12 (GEN) | 409 |
| 5962-8602102XA | D | 10/05/1992 | | (NONE) | | | 68881-16 (GEN) | 409 |
| 5962-8602102YA | D | 10/05/1992 | | (NONE) | | | 68881-16 (GEN) | 409 |
| 5962-8602103XA | D | 10/05/1992 | | (NONE) | | | 68881-20 (GEN) | 409 |
| 5962-8602103YA | D | 10/05/1992 | | (NONE) | | | 68881-20 (GEN) | 409 |
| 8602301EA | B | 06/26/1996 | 1 | LANSDALE | | Y | SL82S16/BEA | 604 |
| 8602301FA | B | 06/26/1996 | 1 | LANSDALE | | Y | SL82S16/BFA | 604 |
| 86025013A | D | 02/03/2000 | | (NONE) | | | 29705A (GEN) | 602 |
| 8602501XA | D | 02/03/2000 | 1 | QP SEMI | | Y | 29705/XA | 602 |
| 8602501YA | D | 02/03/2000 | 1 | QP SEMI | | Y | 29705/YA | 602 |
| 86025023A | D | 02/03/2000 | 1 | SARNOFF | | Y | GEM10702Q3A | 602 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 86025023C | D | 02/03/2000 | 1 | SARNOFF | | Y | GEM10702Q3C | 602 |
| 8602502XA | D | 02/03/2000 | 1 | SARNOFF | | Y | GEM10702QXA | 602 |
| 8602502XC | D | 02/03/2000 | 1 | SARNOFF | | Y | GEM10702QXC | 602 |
| 8602502YA | D | 02/03/2000 | 1 | SARNOFF | | Y | GEM10702QYA | 602 |
| 8602502YC | D | 02/03/2000 | 1 | SARNOFF | | Y | GEM10702QYC | 602 |
| 86027013A | D | 01/21/2003 | | (NONE) | | | 2909A (GEN) | 420 |
| 8602701XA | D | 01/21/2003 | | (NONE) | | | 2909A (GEN) | 420 |
| 8602701YA | D | 01/21/2003 | | (NONE) | | | 2909A (GEN) | 420 |
| 8602701ZA | D | 01/21/2003 | | (NONE) | | | 2909A (GEN) | 420 |
| 8602801RA | C | 11/30/1992 | | (NONE) | 08/31/1995 | | 2911A (GEN) | 420 |
| 8602901QA | C | 10/07/1988 | | (NONE) | 08/31/1995 | | 2914 (GEN) | 420 |
| 8602901UA | C | 10/07/1988 | | (NONE) | | | 2914 (GEN) | 420 |
| 8602901YA | C | 10/07/1988 | | (NONE) | | | 2914 (GEN) | 420 |
| 86030013A | B | 05/02/2000 | 1 | ROCHESTER | | Y | 2940/B3A | 423 |
| 86030013A | B | 05/02/2000 | 1 | SARNOFF | | Y | GEM14101Q3A | 423 |
| 86030013C | B | 05/02/2000 | 1 | SARNOFF | | Y | GEM14101Q3C | 423 |
| 8603001XA | B | 05/02/2000 | 1 | ROCHESTER | | Y | 2940/BXA | 423 |
| 8603001XA | B | 05/02/2000 | 1 | SARNOFF | | Y | GEM14101QXA | 423 |
| 8603001XC | B | 05/02/2000 | 1 | SARNOFF | | Y | GEM14101QXC | 423 |
| 8603001YA | B | 05/02/2000 | 1 | ROCHESTER | | Y | 2940/BYA | 423 |
| 8603001YA | B | 05/02/2000 | 1 | SARNOFF | | Y | GEM14101QYA | 423 |
| 8603001YC | B | 05/02/2000 | 1 | SARNOFF | | Y | GEM14101QYC | 423 |
| 5962-8603201XA | G | 05/27/1999 | | (NONE) | | | 68020-12 (GEN) | 404 |
| 5962-8603202XA | G | 05/27/1999 | 1 | ATMEL GREN. | | Y | TS68020MR1B/C16 | 404 |
| 5962-8603202XC | G | 05/27/1999 | 1 | ATMEL GREN. | | Y | TS68020MRB/C16 | 404 |
| 5962-8603202YA | G | 05/27/1999 | 1 | ATMEL GREN. | | Y | TS68020MF1B/C16 | 404 |
| 5962-8603202YC | G | 05/27/1999 | 1 | ATMEL GREN. | | Y | TS68020MFB/C16 | 404 |
| 5962-8603203XA | G | 05/27/1999 | 1 | ATMEL GREN. | | Y | TS68020MR1B/C20 | 404 |
| 5962-8603203XC | G | 05/27/1999 | 1 | ATMEL GREN. | | Y | TS68020MRB/C20 | 404 |
| 5962-8603203YA | G | 05/27/1999 | 1 | ATMEL GREN. | | Y | TS68020MF1B/C20 | 404 |
| 5962-8603203YC | G | 05/27/1999 | 1 | ATMEL GREN. | | Y | TS68020MFB/C20 | 404 |
| 5962-8603204XA | G | 05/27/1999 | 1 | ATMEL GREN. | | Y | TS68020MR1B/C25 | 404 |
| 5962-8603204XC | G | 05/27/1999 | 1 | ATMEL GREN. | | Y | TS68020MRB/C25 | 404 |
| 5962-8603204YA | G | 05/27/1999 | 1 | ATMEL GREN. | | Y | TS68020MF1B/C25 | 404 |
| 5962-8603204YC | G | 05/27/1999 | 1 | ATMEL GREN. | | Y | TS68020MFB/C25 | 404 |
| 5962-8604901XA | E | 02/25/2002 | | (NONE) | | | BUS-63105 (GEN) | 590 |
| 5962-8604902TC | E | 02/25/2002 | 1 | DDC | | Y | BUS-63106II-601 | 590 |
| 5962-8604902TC | E | 02/25/2002 | 1 | DDC | | Y | BUS-63106II-110 | 590 |
| 5962-8604902TC | E | 02/25/2002 | 1 | DDC | | Y | BUS-63106II-130 | 590 |
| 5962-8604902ZA | E | 02/25/2002 | 1 | DDC | | Y | BUS-63105II-634 | 590 |
| 5962-8604902ZA | E | 02/25/2002 | 1 | DDC | | Y | BUS-63105II-140 | 590 |
| 5962-8604902ZA | E | 02/25/2002 | 1 | DDC | | Y | BUS-63105II-150 | 590 |
| 5962-8604902ZA | E | 02/25/2002 | 1 | DDC IRELAND | | Y | BUS-63105II-634 | 590 |
| 5962-8604902ZA | E | 02/25/2002 | 1 | DDC IRELAND | | Y | BUS-63105II-150 | 590 |
| 5962-8604902ZA | E | 02/25/2002 | 1 | DDC IRELAND | | Y | BUS-63105II-140 | 590 |
| 5962-8604902ZC | E | 02/25/2002 | 1 | DDC | | Y | BUS-63105II-133 | 590 |
| 5962-8604902ZC | E | 02/25/2002 | 1 | DDC | | Y | BUS-63105II-110 | 590 |
| 5962-8604902ZC | E | 02/25/2002 | 1 | DDC | | Y | BUS-63105II-130 | 590 |
| 5962-8604902ZC | E | 02/25/2002 | 1 | DDC IRELAND | | Y | BUS-63105II-110 | 590 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-8604902ZC | E | 02/25/2002 | 1 | DDC IRELAND | | Y | BUS-63105II-130 | 590 |
| 5962-8604902ZC | E | 02/25/2002 | 1 | DDC IRELAND | | Y | BUS-63105II-633 | 590 |
| 5962-8604903YA | E | 02/25/2002 | 1 | AEROFLEX | | Y | ARX2402 | 590 |
| 5962-8604903YC | E | 02/25/2002 | 1 | AEROFLEX | | Y | ARX2402 | 590 |
| 5962-8604904UA | E | 02/25/2002 | 1 | AEROFLEX | | Y | ARX3402 | 590 |
| 5962-8604904UC | E | 02/25/2002 | 1 | AEROFLEX | | Y | ARX3402 | 590 |
| 5962-8604905XA | E | 02/25/2002 | 1 | DDC | | Y | BUS-8553-150 | 590 |
| 5962-8604905XA | E | 02/25/2002 | 1 | DDC | | Y | BUS-8553-140 | 590 |
| 5962-8604905XA | E | 02/25/2002 | 1 | DDC IRELAND | | Y | BUS-8553-140 | 590 |
| 5962-8604905XA | E | 02/25/2002 | 1 | DDC IRELAND | | Y | BUS-63100-618 | 590 |
| 5962-8604905XA | E | 02/25/2002 | 1 | DDC IRELAND | | Y | BUS-8553-150 | 590 |
| 5962-8604905XC | E | 02/25/2002 | 1 | DDC | | Y | BUS-8553-130 | 590 |
| 5962-8604905XC | E | 02/25/2002 | 1 | DDC | | Y | BUS-8553-110 | 590 |
| 5962-8604905XC | E | 02/25/2002 | 1 | DDC IRELAND | | Y | BUS-8553-130 | 590 |
| 5962-8604905XC | E | 02/25/2002 | 1 | DDC IRELAND | | Y | BUS-8553-110 | 590 |
| 5962-8604905XC | E | 02/25/2002 | 1 | DDC IRELAND | | Y | BUS-63100-617 | 590 |
| 5962-8604905YA | E | 02/25/2002 | 1 | DDC | | Y | BUS-8553-150 | 590 |
| 5962-8604905YA | E | 02/25/2002 | 1 | DDC | | Y | BUS-8553-140 | 590 |
| 5962-8604905YA | E | 02/25/2002 | 1 | DDC IRELAND | | Y | BUS-8553-140 | 590 |
| 5962-8604905YA | E | 02/25/2002 | 1 | DDC IRELAND | | Y | BUS-8553-150 | 590 |
| 5962-8604905YC | E | 02/25/2002 | 1 | DDC | | Y | BUS-8553-110 | 590 |
| 5962-8604905YC | E | 02/25/2002 | 1 | DDC | | Y | BUS-8553-130 | 590 |
| 5962-8604905YC | E | 02/25/2002 | 1 | DDC IRELAND | | Y | BUS-8553-130 | 590 |
| 5962-8604905YC | E | 02/25/2002 | 1 | DDC IRELAND | | Y | BUS-8553-110 | 590 |
| 5962-8604906TA | E | 02/25/2002 | 1 | NATIONAL HYB | | Y | NHI-1509FP | 590 |
| 5962-8604906TC | E | 02/25/2002 | 1 | NATIONAL HYB | | Y | NHI-1509FP | 590 |
| 5962-8604906YA | E | 02/25/2002 | 1 | NATIONAL HYB | | Y | NHI-1509 | 590 |
| 5962-8604906YC | E | 02/25/2002 | 1 | NATIONAL HYB | | Y | NHI-1509 | 590 |
| 5962-8604907XA | E | 02/25/2002 | 1 | CMAC MICRO. | | Y | FC155361 | 590 |
| 5962-8604907XC | E | 02/25/2002 | 1 | CMAC MICRO. | | Y | FC155361 | 590 |
| 5962-8604908XA | E | 02/25/2002 | 1 | CMAC MICRO. | | Y | FC155362 | 590 |
| 5962-8604908XC | E | 02/25/2002 | 1 | CMAC MICRO. | | Y | FC155362 | 590 |
| 8605001RA | | 03/07/1986 | | (NONE) | | | 2932 (GEN) | 420 |
| 86051012A | B | 06/13/1989 | | (NONE) | | | 27S02 (GEN) | 602 |
| 8605101EA | B | 06/13/1989 | | (NONE) | 08/02/1996 | | 27S02 (GEN) | 602 |
| 8605101FA | B | 06/13/1989 | | (NONE) | 08/02/1996 | | 27S02 (GEN) | 602 |
| 86051022A | B | 06/13/1989 | | (NONE) | | | 27S02A (GEN) | 602 |
| 8605102EA | B | 06/13/1989 | | (NONE) | 08/02/1996 | | 27S02A (GEN) | 602 |
| 8605102FA | B | 06/13/1989 | | (NONE) | 08/02/1996 | | 27S02A (GEN) | 602 |
| 86051032A | B | 06/13/1989 | | (NONE) | | | 27LS02 (GEN) | 602 |
| 8605103EA | B | 06/13/1989 | | (NONE) | | | 27LS02 (GEN) | 602 |
| 8605103FA | B | 06/13/1989 | | (NONE) | | | 27LS02 (GEN) | 602 |
| 86051042A | B | 06/13/1989 | 1 | SARNOFF | | Y | GEM13404Q2A | 602 |
| 86051042C | B | 06/13/1989 | 1 | SARNOFF | | Y | GEM13404Q2C | 602 |
| 8605104EA | B | 06/13/1989 | 1 | SARNOFF | | Y | GEM13404QEA | 602 |
| 8605104EC | B | 06/13/1989 | 1 | SARNOFF | | Y | GEM13404QEC | 602 |
| 8605104FA | B | 06/13/1989 | 1 | SARNOFF | | Y | GEM13404QFA | 602 |
| 8605104FC | B | 06/13/1989 | 1 | SARNOFF | | Y | GEM13404QFC | 602 |
| 86051052A | B | 06/13/1989 | | (NONE) | 08/02/1996 | | 27S03A (GEN) | 602 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 8605105EA | B | 06/13/1989 | | (NONE) | 08/02/1996 | | 27S03A (GEN) | 602 |
| 8605105FA | B | 06/13/1989 | | (NONE) | 08/02/1996 | | 27S03A (GEN) | 602 |
| 86051062A | B | 06/13/1989 | | (NONE) | 08/02/1996 | | 27LS03 (GEN) | 602 |
| 8605106EA | B | 06/13/1989 | 1 | SARNOFF | | Y | GEM31606QEA | 602 |
| 8605106EC | B | 06/13/1989 | 1 | SARNOFF | | Y | GEM31606QEC | 602 |
| 8605106FA | B | 06/13/1989 | 1 | SARNOFF | | Y | GEM31606QFA | 602 |
| 8605106FC | B | 06/13/1989 | 1 | SARNOFF | | Y | GEM31606QFC | 602 |
| 86051072A | B | 06/13/1989 | | (NONE) | | | 27S02-20 (GEN) | 602 |
| 8605107EA | B | 06/13/1989 | | (NONE) | | | 27S02-20 (GEN) | 602 |
| 8605107FA | B | 06/13/1989 | | (NONE) | | | 27S02-20 (GEN) | 602 |
| 86051082A | B | 06/13/1989 | | (NONE) | | | 27S03-20 (GEN) | 602 |
| 8605108EA | B | 06/13/1989 | | (NONE) | | | 27S03-20 (GEN) | 602 |
| 8605108FA | B | 06/13/1989 | | (NONE) | | | 27S03-20 (GEN) | 602 |
| 86051092A | B | 06/13/1989 | | (NONE) | | | 27LS03-30 (GEN) | 602 |
| 8605109EA | B | 06/13/1989 | | (NONE) | | | 27LS03-30 (GEN) | 602 |
| 8605109FA | B | 06/13/1989 | | (NONE) | | | 27LS03-30 (GEN) | 602 |
| 5962-86052013A | B | 06/26/1996 | 1 | LANSDALE | | Y | SL8X350/B3A | 610 |
| 5962-86052013C | B | 06/26/1996 | 1 | LANSDALE | | Y | IL8X350/B3C | 610 |
| 5962-8605201WA | B | 06/26/1996 | 1 | LANSDALE | | Y | SL8X350/BWA | 610 |
| 5962-86053013A | F | 01/03/2002 | 2 | TI | | Y | TIBPAL22V10AMFKB | 431 |
| 5962-8605301KA | F | 01/03/2002 | 2 | TI | | Y | PAL22V10AMWB | 431 |
| 5962-8605301LA | F | 01/03/2002 | 2 | TI | | Y | PAL22V10AMJTB | 431 |
| 5962-86053023A | F | 01/03/2002 | | (NONE) | 08/02/1996 | | PAL22V10 (GEN) | 431 |
| 5962-8605302KA | F | 01/03/2002 | | (NONE) | 08/02/1996 | | PAL22V10 (GEN) | 431 |
| 5962-8605302LA | F | 01/03/2002 | | (NONE) | 08/02/1996 | | PAL22V10 (GEN) | 431 |
| 5962-86053033A | F | 01/03/2002 | 0 | TI | | Y | TIBPAL22VP1025MFKB | 431 |
| 5962-8605303KA | F | 01/03/2002 | 0 | TI | | Y | TIBPAL22VP10-25MWB | 431 |
| 5962-8605303LA | F | 01/03/2002 | 0 | TI | | Y | TIBPAL22VP1025MJTB | 431 |
| 5962-86053043A | F | 01/03/2002 | 2 | TI | | Y | TIBPAL22V10-20MKFB | 431 |
| 5962-8605304KA | F | 01/03/2002 | 2 | TI | | Y | TIBPAL22V10-20MWB | 431 |
| 5962-8605304LA | F | 01/03/2002 | 2 | TI | | Y | TIBPAL22V10-20MJTB | 431 |
| 5962-86053053A | F | 01/03/2002 | | (NONE) | 08/02/1996 | | PAL22V10-12 (GEN) | 431 |
| 5962-8605305KA | F | 01/03/2002 | | (NONE) | 08/02/1996 | | PAL22V10-12 (GEN) | 431 |
| 5962-8605305LA | F | 01/03/2002 | | (NONE) | 08/02/1996 | | PAL22V10-12 (GEN) | 431 |
| 5962-8605401XA | | 01/02/1992 | | (NONE) | 05/31/1994 | | 55551 (GEN) | 599 |
| 5962-8605401YA | | 01/02/1992 | | (NONE) | | | 55551 (GEN) | 599 |
| 5962-8605402XA | | 01/02/1992 | | (NONE) | 05/31/1994 | | 55552 (GEN) | 599 |
| 5962-8605402YA | | 01/02/1992 | | (NONE) | 05/31/1994 | | 55552 (GEN) | 599 |
| 5962-8605501XA | | 01/02/1992 | | (NONE) | 05/31/1994 | | 55553 (GEN) | 599 |
| 5962-8605501YA | | 01/02/1992 | | (NONE) | 05/31/1994 | | 55553 (GEN) | 599 |
| 5962-8605502XA | | 01/02/1992 | | (NONE) | 05/31/1994 | | 55554 (GEN) | 599 |
| 5962-8605502YA | | 01/02/1992 | | (NONE) | 05/31/1994 | | 55554 (GEN) | 599 |
| 5962-86058012A | C | 05/22/2002 | 0 | MICROSEMI | | Y | SG2803L/883B | 790 |
| 5962-8605801VA | C | 05/22/2002 | I | MICROSEMI | | Y | SG2803J/883B | 790 |
| 5962-86061012A | C | 02/01/2002 | 2 | TI | | Y | SNJ54HC157FK | 275 |
| 5962-8606101EA | C | 02/01/2002 | 2 | TI | | Y | CD54HC157F3A | 275 |
| 5962-8606101EA | C | 02/01/2002 | 2 | TI | | Y | SNJ54HC157J | 275 |
| 5962-8606101VXA | C | 02/01/2002 | 2 | STMICRO | | Y | 54HC157K02V | 275 |
| 5962-8606101VXC | C | 02/01/2002 | 2 | STMICRO | | Y | 54HC157K01V | 275 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-8606101XA | C | 02/01/2002 | 2 | STMICRO | | Y | 54HC157K02Q | 275 |
| 5962-8606101XC | C | 02/01/2002 | 2 | STMICRO | | Y | 54HC157K01Q | 275 |
| 5962-86062012A | C | 12/04/2001 | 1 | ROCHESTER | | Y | 54HC563/B2A | 341 |
| 5962-8606201RA | C | 12/04/2001 | 1 | TI | | Y | CD54HC563F3A | 341 |
| 5962-8606201SA | C | 12/04/2001 | 1 | ROCHESTER | | Y | 54HC563/BSA | 341 |
| 5962-8606301UA | G | 04/06/1997 | 1 | QP SEMI | | | AT27C256R-20/UA | 662 |
| 5962-8606301UA | G | 04/06/1997 | 1 | QP SEMI | | | WS27C256L-20TMB | 662 |
| 5962-8606301XA | G | 04/06/1997 | 0 | AUSTIN SEMI. | | Y | SMJ27C256-20JM | 662 |
| 5962-8606301XA | G | 04/06/1997 | 1 | QP SEMI | | | AT27C256R-20/XA | 662 |
| 5962-8606301XA | G | 04/06/1997 | 1 | QP SEMI | | | WS27C256L-20DMB | 662 |
| 5962-8606301YA | G | 04/06/1997 | 1 | QP SEMI | | | AT27C256R-20/YA | 662 |
| 5962-8606301YA | G | 04/06/1997 | 1 | QP SEMI | | | WS27C256L-20CMB | 662 |
| 5962-8606301YC | G | 04/06/1997 | 1 | QP SEMI | | | AT27C256R-20/YC | 662 |
| 5962-8606301YC | G | 04/06/1997 | 1 | QP SEMI | | | WS27C256L-20CMB | 662 |
| 5962-8606301ZA | G | 04/06/1997 | | (NONE) | 10/27/1995 | | 27C256-20 (GEN) | 662 |
| 5962-8606302UA | G | 04/06/1997 | 1 | QP SEMI | | | AT27C256R-25/UA | 662 |
| 5962-8606302UA | G | 04/06/1997 | 1 | QP SEMI | | | WS27C256L-25TMB | 662 |
| 5962-8606302XA | G | 04/06/1997 | 0 | AUSTIN SEMI. | | Y | SMJ27C256-25JM | 662 |
| 5962-8606302XA | G | 04/06/1997 | 1 | QP SEMI | | | WS27C256L-25DMB | 662 |
| 5962-8606302XA | G | 04/06/1997 | 1 | QP SEMI | | | AT27C256R-25/XA | 662 |
| 5962-8606302YA | G | 04/06/1997 | 1 | QP SEMI | | | AT27C256R-25/YA | 662 |
| 5962-8606302YA | G | 04/06/1997 | 1 | QP SEMI | | | WS27C256L-25CMB | 662 |
| 5962-8606302YC | G | 04/06/1997 | 1 | QP SEMI | | | AT27C256R-25/YC | 662 |
| 5962-8606302YC | G | 04/06/1997 | 1 | QP SEMI | | | WS27C256L-25CMB | 662 |
| 5962-8606302ZA | G | 04/06/1997 | | (NONE) | 10/27/1995 | | 27C256-25 (GEN) | 662 |
| 5962-8606303UA | G | 04/06/1997 | 1 | QP SEMI | | | WS27C256L-30TMB | 662 |
| 5962-8606303UA | G | 04/06/1997 | 1 | QP SEMI | | | AT27C256R-30/UA | 662 |
| 5962-8606303XA | G | 04/06/1997 | 0 | AUSTIN SEMI. | | Y | SMJ27C256-30JM | 662 |
| 5962-8606303XA | G | 04/06/1997 | 1 | QP SEMI | | | WS27C256L-30DMB | 662 |
| 5962-8606303XA | G | 04/06/1997 | 1 | QP SEMI | | | AT27C256R-30/XA | 662 |
| 5962-8606303YA | G | 04/06/1997 | 1 | QP SEMI | | | AT27C256R-30/YA | 662 |
| 5962-8606303YA | G | 04/06/1997 | 1 | QP SEMI | | | WS27C256L-30CMB | 662 |
| 5962-8606303YC | G | 04/06/1997 | 1 | QP SEMI | | | AT27C256R-30/YC | 662 |
| 5962-8606303YC | G | 04/06/1997 | 1 | QP SEMI | | | WS27C256L-30CMB | 662 |
| 5962-8606303ZA | G | 04/06/1997 | | (NONE) | 10/27/1995 | | 27C256-30 (GEN) | 662 |
| 5962-8606304UA | G | 04/06/1997 | 1 | QP SEMI | | | AT27C256R-17/UA | 662 |
| 5962-8606304UA | G | 04/06/1997 | 1 | QP SEMI | | | WS27C256L-17TMB | 662 |
| 5962-8606304XA | G | 04/06/1997 | 0 | AUSTIN SEMI. | | Y | SMJ27C256-17JM | 662 |
| 5962-8606304XA | G | 04/06/1997 | 1 | QP SEMI | | | AT27C256R-17/XA | 662 |
| 5962-8606304XA | G | 04/06/1997 | 1 | QP SEMI | | | WS27C256L-17DMB | 662 |
| 5962-8606304YA | G | 04/06/1997 | 1 | QP SEMI | | | AT27C256R-17/YA | 662 |
| 5962-8606304YA | G | 04/06/1997 | 1 | QP SEMI | | | WS27C256L-17CMB | 662 |
| 5962-8606304YC | G | 04/06/1997 | 1 | QP SEMI | | | WS27C256L-17CMB | 662 |
| 5962-8606304YC | G | 04/06/1997 | 1 | QP SEMI | | | AT27C256R-17/YC | 662 |
| 5962-8606304ZA | G | 04/06/1997 | | (NONE) | 10/27/1995 | | 27C256-17(GEN) | 662 |
| 5962-8606305UA | G | 04/06/1997 | 1 | QP SEMI | | | AT27C256R-15/UA | 662 |
| 5962-8606305UA | G | 04/06/1997 | 1 | QP SEMI | | | WS27C256L-15TMB | 662 |
| 5962-8606305XA | G | 04/06/1997 | 0 | AUSTIN SEMI. | | Y | SMJ27C256-15JM | 662 |
| 5962-8606305XA | G | 04/06/1997 | 1 | QP SEMI | | | WS27C256L-15DMB | 662 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-8606305XA | G | 04/06/1997 | 1 | QP SEMI | | | AT27C256R-15/XA | 662 |
| 5962-8606305YA | G | 04/06/1997 | 1 | QP SEMI | | | WS27C256L-15CMB | 662 |
| 5962-8606305YA | G | 04/06/1997 | 1 | QP SEMI | | | AT27C256R-15/YA | 662 |
| 5962-8606305YC | G | 04/06/1997 | 1 | QP SEMI | | | AT27C256R-15/YC | 662 |
| 5962-8606305YC | G | 04/06/1997 | 1 | QP SEMI | | | WS27C256L-15CMB | 662 |
| 5962-8606305ZA | G | 04/06/1997 | | (NONE) | 10/27/1995 | | 27C256-150 (GEN) | 662 |
| 5962-8606306UA | G | 04/06/1997 | 1 | QP SEMI | | | AT27C256R-12/UA | 662 |
| 5962-8606306XA | G | 04/06/1997 | 1 | QP SEMI | | | AT27C256R-12/XA | 662 |
| 5962-8606306XA | G | 04/06/1997 | 1 | QP SEMI | | | WS27C256L-12DMB | 662 |
| 5962-8606306YA | G | 04/06/1997 | 1 | QP SEMI | | | WS27C256L-12CMB | 662 |
| 5962-8606306YA | G | 04/06/1997 | 1 | QP SEMI | | | AT27C256R-12/YA | 662 |
| 5962-8606306YC | G | 04/06/1997 | 1 | QP SEMI | | | AT27C256R-12/YC | 662 |
| 5962-8606306YC | G | 04/06/1997 | 1 | QP SEMI | | | WS27C256L-12CMB | 662 |
| 5962-8606306ZA | G | 04/06/1997 | | (NONE) | 10/27/1995 | | 27C256-120 (GEN) | 662 |
| 5962-8606307UA | G | 04/06/1997 | 1 | QP SEMI | | | AT27C256R-90/UA | 662 |
| 5962-8606307XA | G | 04/06/1997 | 1 | QP SEMI | | | AT27C256R-90/XA | 662 |
| 5962-8606307YA | G | 04/06/1997 | 1 | QP SEMI | | | AT27C256R-90/YA | 662 |
| 5962-8606307YC | G | 04/06/1997 | 1 | QP SEMI | | | AT27C256R-90/YC | 662 |
| 5962-8606307ZA | G | 04/06/1997 | | (NONE) | 10/27/1995 | | 27C256-90 (GEN) | 662 |
| 5962-8606308UA | G | 04/06/1997 | 1 | QP SEMI | | | AT27C256R-70/UA | 662 |
| 5962-8606308XA | G | 04/06/1997 | 1 | QP SEMI | | | AT27C256R-70/XA | 662 |
| 5962-8606308XA | G | 04/06/1997 | 2 | QP SEMI | | | 57C256F-70 | 662 |
| 5962-8606308YA | G | 04/06/1997 | 2 | QP SEMI | | | 57C256F-70 | 662 |
| 5962-8606308YA | G | 04/06/1997 | 1 | QP SEMI | | | AT27C256R-70/YA | 662 |
| 5962-8606308YC | G | 04/06/1997 | 1 | QP SEMI | | | AT27C256R-70/YC | 662 |
| 5962-8606308YC | G | 04/06/1997 | 2 | QP SEMI | | | 57C256F-70 | 662 |
| 5962-8606308ZA | G | 04/06/1997 | | (NONE) | 10/27/1995 | | 27C256-70 (GEN) | 662 |
| 5962-8606309UA | G | 04/06/1997 | 1 | QP SEMI | | | AT27C256R-55/UA | 662 |
| 5962-8606309UA | G | 04/06/1997 | 1 | QP SEMI | | | 57C256F-55 | 662 |
| 5962-8606309XA | G | 04/06/1997 | 1 | QP SEMI | | | AT27C256R-55/XA | 662 |
| 5962-8606309XA | G | 04/06/1997 | 1 | QP SEMI | | | 57C256F-55 | 662 |
| 5962-8606309YA | G | 04/06/1997 | 1 | QP SEMI | | | 57C256F-55 | 662 |
| 5962-8606309YA | G | 04/06/1997 | 1 | QP SEMI | | | AT27C256R-55/YA | 662 |
| 5962-8606309YC | G | 04/06/1997 | 1 | QP SEMI | | | AT27C256R-55/YC | 662 |
| 5962-8606309YC | G | 04/06/1997 | 1 | QP SEMI | | | 57C256F-55 | 662 |
| 5962-8606310UA | G | 04/06/1997 | 1 | QP SEMI | | | AT27C256R-45/UA | 662 |
| 5962-8606310UA | G | 04/06/1997 | 1 | QP SEMI | | | 57C256F-45 | 662 |
| 5962-8606310XA | G | 04/06/1997 | 1 | QP SEMI | | | AT27C256R-45/XA | 662 |
| 5962-8606310XA | G | 04/06/1997 | 1 | QP SEMI | | | 57C256F-45 | 662 |
| 5962-8606310YA | G | 04/06/1997 | 1 | QP SEMI | | | 57C256F-45 | 662 |
| 5962-8606310YA | G | 04/06/1997 | 1 | QP SEMI | | | AT27C256R-45/YA | 662 |
| 5962-8606310YC | G | 04/06/1997 | 1 | QP SEMI | | | AT27C256F-45/YC | 662 |
| 5962-8606310YC | G | 04/06/1997 | 1 | QP SEMI | | | 57C256F-45 | 662 |
| 5962-8606311UA | G | 04/06/1997 | 1 | QP SEMI | | | AT27C256R-20/UA | 662 |
| 5962-8606311QXA | G | 04/06/1997 | | (NONE) | 04/10/2000 | | 27C256A-200 (GEN) | 662 |
| 5962-8606311XA | G | 04/06/1997 | 1 | QP SEMI | | | AT27C256R-20/XA | 662 |
| 5962-8606311QYA | G | 04/06/1997 | | (NONE) | 04/10/2000 | | 27C256A-200 (GEN) | 662 |
| 5962-8606311YA | G | 04/06/1997 | 1 | QP SEMI | | | AT27C256R-20/YA | 662 |
| 5962-8606312UA | G | 04/06/1997 | 1 | QP SEMI | | | AT27C256R-25/UA | 662 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-8606312QXA | G | 04/06/1997 | | (NONE) | 04/10/2000 | | 27C256A-250 (GEN) | 662 |
| 5962-8606312XA | G | 04/06/1997 | 1 | QP SEMI | | | AT27C256R-25/XA | 662 |
| 5962-8606312QYA | G | 04/06/1997 | | (NONE) | 04/10/2000 | | 27C256A-250 (GEN) | 662 |
| 5962-8606312YA | G | 04/06/1997 | 1 | QP SEMI | | | AT27C256R-25/YA | 662 |
| 5962-8606313UA | G | 04/06/1997 | 1 | QP SEMI | | | AT27C256R-30/UA | 662 |
| 5962-8606313QXA | G | 04/06/1997 | | (NONE) | 04/10/2000 | | 27C256A-300 (GEN) | 662 |
| 5962-8606313XA | G | 04/06/1997 | 1 | QP SEMI | | | AT27C256R-30/XA | 662 |
| 5962-8606313QYA | G | 04/06/1997 | | (NONE) | 04/10/2000 | | 27C256A-300 (GEN) | 662 |
| 5962-8606313YA | G | 04/06/1997 | 1 | QP SEMI | | | AT27C256R-30/YA | 662 |
| 5962-8606314UA | G | 04/06/1997 | 1 | QP SEMI | | | AT27C256R-17/UA | 662 |
| 5962-8606314QXA | G | 04/06/1997 | | (NONE) | 04/10/2000 | | 27C256A-170 (GEN) | 662 |
| 5962-8606314XA | G | 04/06/1997 | 1 | QP SEMI | | | AT27C256R-17/XA | 662 |
| 5962-8606314QYA | G | 04/06/1997 | | (NONE) | 04/10/2000 | | 27C256A-170 (GEN) | 662 |
| 5962-8606314YA | G | 04/06/1997 | 1 | QP SEMI | | | AT27C256R-17/YA | 662 |
| 5962-8606315UA | G | 04/06/1997 | 1 | QP SEMI | | | AT27C256R-15/UA | 662 |
| 5962-8606315QXA | G | 04/06/1997 | | (NONE) | 04/10/2000 | | 27C256A-150 (GEN) | 662 |
| 5962-8606315XA | G | 04/06/1997 | 1 | QP SEMI | | | AT27C256R-15/XA | 662 |
| 5962-8606315QYA | G | 04/06/1997 | | (NONE) | 04/10/2000 | | 27C256A-150 (GEN) | 662 |
| 5962-8606315YA | G | 04/06/1997 | 1 | QP SEMI | | | AT27C256R-15/YA | 662 |
| 5962-8606316UA | G | 04/06/1997 | 1 | QP SEMI | | | AT27C256R-12/UA | 662 |
| 5962-8606316QXA | G | 04/06/1997 | | (NONE) | 04/10/2000 | | 27C256A-120 (GEN) | 662 |
| 5962-8606316XA | G | 04/06/1997 | 1 | QP SEMI | | | AT27C256R-12/XA | 662 |
| 5962-8606316QYA | G | 04/06/1997 | | (NONE) | 04/10/2000 | | 27C256A-120 (GEN) | 662 |
| 5962-8606316YA | G | 04/06/1997 | 1 | QP SEMI | | | AT27C256R-12/YA | 662 |
| 5962-8606317UA | G | 04/06/1997 | 1 | QP SEMI | | | AT27C256R-90/UA | 662 |
| 5962-8606317QXA | G | 04/06/1997 | | (NONE) | 04/10/2000 | | 27C256A-90 (GEN) | 662 |
| 5962-8606317XA | G | 04/06/1997 | 1 | QP SEMI | | | AT27C256R-90/XA | 662 |
| 5962-8606317QYA | G | 04/06/1997 | | (NONE) | 04/10/2000 | | 27C256A-90 (GEN) | 662 |
| 5962-8606317YA | G | 04/06/1997 | 1 | QP SEMI | | | AT27C256R-90/YA | 662 |
| 5962-8606318UA | G | 04/06/1997 | 1 | QP SEMI | | | AT27C256R-70/XA | 662 |
| 5962-8606318QXA | G | 04/06/1997 | | (NONE) | 04/10/2000 | | 27C256A-70 (GEN) | 662 |
| 5962-8606318XA | G | 04/06/1997 | 1 | QP SEMI | | | AT27C256R-70/XA | 662 |
| 5962-8606318QYA | G | 04/06/1997 | | (NONE) | 04/10/2000 | | 27C256A-70 (GEN) | 662 |
| 5962-8606318YA | G | 04/06/1997 | 1 | QP SEMI | | | AT27C256R-70/YA | 662 |
| 5962-8606319UA | G | 04/06/1997 | 1 | QP SEMI | | | AT27C256R-55/UA | 662 |
| 5962-8606319QXA | G | 04/06/1997 | | (NONE) | 04/10/2000 | | 27C256A-55 (GEN) | 662 |
| 5962-8606319XA | G | 04/06/1997 | 1 | QP SEMI | | | AT27C256R-55/XA | 662 |
| 5962-8606319QYA | G | 04/06/1997 | | (NONE) | 04/10/2000 | | 27C256A-55 (GEN) | 662 |
| 5962-8606319YA | G | 04/06/1997 | 1 | QP SEMI | | | AT27C256R-55/YA | 662 |
| 5962-8606320QXA | G | 04/06/1997 | | (NONE) | 04/10/2000 | | 27C256A-45 (GEN) | 662 |
| 5962-8606320QYA | G | 04/06/1997 | | (NONE) | 04/10/2000 | | 27C256A-45 (GEN) | 662 |
| 5962-8606321QXA | G | 04/06/1997 | | (NONE) | 04/10/2000 | | 27C256A-35 (GEN) | 662 |
| 5962-8606321QYA | G | 04/06/1997 | | (NONE) | 04/10/2000 | | 27C256A-35 (GEN) | 662 |
| 5962-8606401CA | B | 07/10/1996 | | (NONE) | 06/01/1997 | | 5539 (GEN) | 755 |
| 5962-86069012A | | 10/03/1986 | | (NONE) | | | 54F85 (GEN) | 209 |
| 5962-8606901EA | | 10/03/1986 | | (NONE) | | | 54F85 (GEN) | 209 |
| 5962-8606901FA | | 10/03/1986 | | (NONE) | | | 54F85 (GEN) | 209 |
| 5962-86070012A | B | 11/08/1999 | | (NONE) | 06/01/1997 | | 54F148 (GEN) | 345 |
| 5962-8607001EA | B | 11/08/1999 | 1 | QP SEMI | | Y | 54F148/BEA | 345 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-8607001FA | B | 11/08/1999 | | (NONE) | 06/01/1997 | | 54F148 (GEN) | 345 |
| 5962-86071012A | C | 02/27/2002 | 3 | NATIONAL | | Y | 54F164ALMQB | 226 |
| 5962-8607101CA | C | 02/27/2002 | 3 | NATIONAL | | Y | 54F164ADMQB | 226 |
| 5962-8607101DA | C | 02/27/2002 | 3 | NATIONAL | | Y | 54F164AFMQB | 226 |
| 5962-86072012A | D | 03/07/2002 | 2 | NATIONAL | | Y | 54F169LMQB | 304 |
| 5962-8607201EA | D | 03/07/2002 | 2 | NATIONAL | | Y | 54F169DMQB | 304 |
| 5962-8607201FA | D | 03/07/2002 | 2 | NATIONAL | | Y | 54F169FMQB | 304 |
| 5962-86074012A | C | 03/20/2002 | | (NONE) | | | 54F322 (GEN) | 228 |
| 5962-8607401RA | C | 03/20/2002 | 1 | NATIONAL | | Y | 54F322DMQB | 228 |
| 5962-8607401SA | C | 03/20/2002 | | (NONE) | 09/09/1998 | | 54F322 (GEN) | 228 |
| 5962-86075012A | B | 12/10/1991 | | (NONE) | 06/01/1997 | | 54F350 (GEN) | 222 |
| 5962-8607501EA | B | 12/10/1991 | | (NONE) | 06/01/1997 | | 54F350 (GEN) | 222 |
| 5962-8607501FA | B | 12/10/1991 | | (NONE) | 06/01/1997 | | 54F350 (GEN) | 222 |
| 86076012A | D | 01/25/2002 | 2 | TI | | Y | SNJ54HC163FK | 304 |
| 8607601EA | D | 01/25/2002 | 2 | TI | | Y | SNJ54HC163J | 304 |
| 8607601EA | D | 01/25/2002 | 2 | TI | | Y | CD54HC163F3A | 304 |
| 8607601FA | D | 01/25/2002 | 2 | TI | | Y | SNJ54HC163W | 304 |
| 5962-8607601VXA | D | 01/25/2002 | 2 | STMICRO | | Y | 54HC163K02V | 304 |
| 5962-8607601VXC | D | 01/25/2002 | 2 | STMICRO | | Y | 54HC163K01V | 304 |
| 8607601XA | D | 01/25/2002 | 2 | STMICRO | | Y | 54HC163K02Q | 304 |
| 8607601XC | D | 01/25/2002 | 2 | STMICRO | | Y | 54HC163K01Q | 304 |
| 86077012A | B | 12/10/2001 | 1 | ROCHESTER | | Y | 54HC280/B2A | 210 |
| 8607701CA | B | 12/10/2001 | 1 | TI | | Y | CD54HC280F3A | 210 |
| 5962-8608101RA | B | 06/26/1996 | | (NONE) | | | 2168-55 (GEN) | 616 |
| 5962-8608101XA | B | 06/26/1996 | | (NONE) | | | 2168-55 (GEN) | 616 |
| 5962-8608102RA | B | 06/26/1996 | | (NONE) | | | 2168-70 (GEN) | 616 |
| 5962-8608102XA | B | 06/26/1996 | | (NONE) | | | 2168-70 (GEN) | 616 |
| 5962-8608103RA | B | 06/26/1996 | | (NONE) | | | 2169-50 (GEN) | 616 |
| 5962-8608103XA | B | 06/26/1996 | | (NONE) | | | 2169-50 (GEN) | 616 |
| 5962-8608104RA | B | 06/26/1996 | | (NONE) | | | 2169-70 (GEN) | 616 |
| 5962-8608104XA | B | 06/26/1996 | | (NONE) | | | 2169-70 (GEN) | 616 |
| 5962-8608105RA | B | 06/26/1996 | | (NONE) | | | 2168-45 (GEN) | 616 |
| 5962-8608105XA | B | 06/26/1996 | | (NONE) | | | 2168-45 (GEN) | 616 |
| 5962-8608106RA | B | 06/26/1996 | | (NONE) | | | 2169-40 (GEN) | 616 |
| 5962-8608106XA | B | 06/26/1996 | | (NONE) | | | 2169-40 (GEN) | 616 |
| 5962-8608801QA | | 10/27/1986 | | (NONE) | | | 82720 (GEN) | 399 |
| 5962-86701013A | C | 12/13/2001 | | (NONE) | | | 54HCT154 (GEN) | 280 |
| 5962-8670101JA | C | 12/13/2001 | 1 | TI | | Y | CD54HCT154F3A | 280 |
| 5962-8670101KA | C | 12/13/2001 | | (NONE) | | | 54HCT154 (GEN) | 280 |
| 5962-8670101LA | C | 12/13/2001 | | (NONE) | | | 54HCT154 (GEN) | 280 |
| 5962-86702012A | A | 04/10/2002 | 1 | SARNOFF | | Y | GEM07301Q2A | 159 |
| 5962-86702012C | A | 04/10/2002 | 1 | SARNOFF | | Y | GEM07301Q2C | 159 |
| 5962-8670201RA | A | 04/10/2002 | 1 | SARNOFF | | Y | GEM07301QRA | 159 |
| 5962-8670201RC | A | 04/10/2002 | 1 | SARNOFF | | Y | GEM07301QRC | 159 |
| 5962-8670201SA | A | 04/10/2002 | 1 | SARNOFF | | Y | GEM07301QSA | 159 |
| 5962-8670201SC | A | 04/10/2002 | 1 | SARNOFF | | Y | GEM07301QSC | 159 |
| 5962-86703012A | D | 08/09/2000 | | (NONE) | 08/02/1996 | | 27S19 (GEN) | 650 |
| 5962-8670301EA | D | 08/09/2000 | 1 | LANSDALE | | Y | SL82S123A/BEA | 650 |
| 5962-8670301EA | D | 08/09/2000 | 1 | QP SEMI | | Y | 82S123A/BEA | 650 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-8670301FA | D | 08/09/2000 | 1 | LANSDALE | | Y | SL82S123A/BFA | 650 |
| 5962-8670301FA | D | 08/09/2000 | 1 | QP SEMI | | Y | 82S123A/BFA | 650 |
| 5962-86703022A | D | 08/09/2000 | | (NONE) | 08/02/1996 | | 27S19A (GEN) | 650 |
| 5962-8670302EA | D | 08/09/2000 | 1 | LANSDALE | | Y | SL82S123B/BEA | 650 |
| 5962-8670302EA | D | 08/09/2000 | 1 | QP SEMI | | Y | 82S123B/BEA | 650 |
| 5962-8670302FA | D | 08/09/2000 | 1 | LANSDALE | | Y | SL82S123B/BFA | 650 |
| 5962-8670302FA | D | 08/09/2000 | 1 | QP SEMI | | Y | 82S123B/BFA | 650 |
| 5962-86704012A | L | 12/19/2003 | 2 | MICROSEMI | | Y | SG1842L/883B | 787 |
| 5962-8670401V2A | L | 12/19/2003 | | (NONE) | | | 1842 (GEN) | 787 |
| 5962-8670401CA | L | 12/19/2003 | 2 | MICROSEMI | | Y | SG1842J/883B | 787 |
| 5962-8670401DA | L | 12/19/2003 | 1 | TI | | Y | UC1842W/883B | 787 |
| 5962-8670401EA | L | 12/19/2003 | | (NONE) | | | 1842 (GEN) | 787 |
| 5962-8670401FA | L | 12/19/2003 | | (NONE) | | | 1842 (GEN) | 787 |
| 5962-8670401HA | L | 12/19/2003 | 2 | MICROSEMI | | Y | SG1842F/883B | 787 |
| 5962-8670401PA | L | 12/19/2003 | 2 | MICROSEMI | | Y | SG1842Y/883B | 787 |
| 5962-8670401PA | L | 12/19/2003 | 1 | SEMELAB | | Y | IP1842J-DESC | 787 |
| 5962-8670401PA | L | 12/19/2003 | 1 | TI | | Y | UC1842J/883B | 787 |
| 5962-8670401VPA | L | 12/19/2003 | 1 | TI | | Y | UC1842JQMLV | 787 |
| 5962-8670401VXA | L | 12/19/2003 | 1 | TI | | Y | UC1842LQMLV | 787 |
| 5962-8670401XA | L | 12/19/2003 | 1 | TI | | Y | UC1842L/883B | 787 |
| 5962-86704022A | L | 12/19/2003 | 2 | MICROSEMI | | Y | SG1843L/883B | 787 |
| 5962-8670402V2A | L | 12/19/2003 | | (NONE) | | | 1843 (GEN) | 787 |
| 5962-8670402CA | L | 12/19/2003 | 2 | MICROSEMI | | Y | SG1843J/883B | 787 |
| 5962-8670402DA | L | 12/19/2003 | 1 | TI | | Y | UC1843W/883B | 787 |
| 5962-8670402EA | L | 12/19/2003 | | (NONE) | | | 1843 (GEN) | 787 |
| 5962-8670402FA | L | 12/19/2003 | | (NONE) | | | 1843 (GEN) | 787 |
| 5962-8670402HA | L | 12/19/2003 | 2 | MICROSEMI | | Y | SG1843F/883B | 787 |
| 5962-8670402PA | L | 12/19/2003 | 2 | MICROSEMI | | Y | SG1843Y/883B | 787 |
| 5962-8670402PA | L | 12/19/2003 | 1 | SEMELAB | | Y | IP1843J-DESC | 787 |
| 5962-8670402PA | L | 12/19/2003 | 1 | TI | | Y | UC1843J/883B | 787 |
| 5962-8670402VPA | L | 12/19/2003 | 1 | TI | | Y | UC1843JQMLV | 787 |
| 5962-8670402VXA | L | 12/19/2003 | 1 | TI | | Y | UC1843LQMLV | 787 |
| 5962-8670402XA | L | 12/19/2003 | 1 | TI | | Y | UC1843L/883B | 787 |
| 5962-86704032A | L | 12/19/2003 | 2 | MICROSEMI | | Y | SG1844L/883B | 787 |
| 5962-8670403V2A | L | 12/19/2003 | | (NONE) | | | 1844 (GEN) | 787 |
| 5962-8670403CA | L | 12/19/2003 | 2 | MICROSEMI | | Y | SG1844J/883B | 787 |
| 5962-8670403DA | L | 12/19/2003 | 1 | TI | | Y | UC1844W/883B | 787 |
| 5962-8670403EA | L | 12/19/2003 | | (NONE) | | | 1844 (GEN) | 787 |
| 5962-8670403FA | L | 12/19/2003 | | (NONE) | | | 1844 (GEN) | 787 |
| 5962-8670403HA | L | 12/19/2003 | 2 | MICROSEMI | | Y | SG1844F/883B | 787 |
| 5962-8670403PA | L | 12/19/2003 | 2 | MICROSEMI | | Y | SG1844Y/883B | 787 |
| 5962-8670403PA | L | 12/19/2003 | 1 | SEMELAB | | Y | IP1844J-DESC | 787 |
| 5962-8670403PA | L | 12/19/2003 | 1 | TI | | Y | UC1844J/883B | 787 |
| 5962-8670403VPA | L | 12/19/2003 | 1 | TI | | Y | UC1844JQMLV | 787 |
| 5962-8670403VXA | L | 12/19/2003 | 1 | TI | | Y | UC1844LQMLV | 787 |
| 5962-8670403XA | L | 12/19/2003 | 1 | TI | | Y | UC1844L/883B | 787 |
| 5962-86704042A | L | 12/19/2003 | 2 | MICROSEMI | | Y | SG1845L/883B | 787 |
| 5962-8670404V2A | L | 12/19/2003 | | (NONE) | | | 1845 (GEN) | 787 |
| 5962-8670404CA | L | 12/19/2003 | 2 | MICROSEMI | | Y | SG1845J/883B | 787 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-8670404DA | L | 12/19/2003 | 1 | TI | | Y | UC1845W/883B | 787 |
| 5962-8670404EA | L | 12/19/2003 | | (NONE) | | | 1845 (GEN) | 787 |
| 5962-8670404FA | L | 12/19/2003 | | (NONE) | | | 1845 (GEN) | 787 |
| 5962-8670404HA | L | 12/19/2003 | 2 | MICROSEMI | | Y | SG1845F/883B | 787 |
| 5962-8670404PA | L | 12/19/2003 | 2 | MICROSEMI | | Y | SG1845Y/883B | 787 |
| 5962-8670404PA | L | 12/19/2003 | 1 | SEMELAB | | Y | IP1845J-DESC | 787 |
| 5962-8670404PA | L | 12/19/2003 | 1 | TI | | Y | UC1845J/883B | 787 |
| 5962-8670404VPA | L | 12/19/2003 | 1 | TI | | Y | UC1845JQMLV | 787 |
| 5962-8670404VXA | L | 12/19/2003 | 1 | TI | | Y | UC1845LQMLV | 787 |
| 5962-8670404XA | L | 12/19/2003 | 1 | TI | | Y | UC1845L/883B | 787 |
| 5962-8670405V2A | L | 12/19/2003 | | (NONE) | | | 1842A (GEN) | 787 |
| 5962-8670405DA | L | 12/19/2003 | 1 | TI | | Y | UC1842AW/883B | 787 |
| 5962-8670405PA | L | 12/19/2003 | 1 | TI | | Y | UC1842AJ/883B | 787 |
| 5962-8670405VPA | L | 12/19/2003 | 1 | TI | | Y | UC1842AJQMLV | 787 |
| 5962-8670405VXA | L | 12/19/2003 | 1 | TI | | Y | UC1842ALQMLV | 787 |
| 5962-8670405XA | L | 12/19/2003 | 1 | TI | | Y | UC1842AL/883B | 787 |
| 5962-8670406V2A | L | 12/19/2003 | | (NONE) | | | 1843A (GEN) | 787 |
| 5962-8670406DA | L | 12/19/2003 | 1 | TI | | Y | UC1843AW/883B | 787 |
| 5962-8670406PA | L | 12/19/2003 | 1 | TI | | Y | UC1843AJ/883B | 787 |
| 5962-8670406VPA | L | 12/19/2003 | 1 | TI | | Y | UC1843AJQMLV | 787 |
| 5962-8670406VXA | L | 12/19/2003 | 1 | TI | | Y | UC1843ALQMLV | 787 |
| 5962-8670406XA | L | 12/19/2003 | 1 | TI | | Y | UC1843AL/883B | 787 |
| 5962-8670407V2A | L | 12/19/2003 | | (NONE) | | | 1844A (GEN) | 787 |
| 5962-8670407DA | L | 12/19/2003 | 1 | TI | | Y | UC1844AW/883B | 787 |
| 5962-8670407PA | L | 12/19/2003 | 1 | TI | | Y | UC1844AJ/883B | 787 |
| 5962-8670407VPA | L | 12/19/2003 | 1 | TI | | Y | UC1844AJQMLV | 787 |
| 5962-8670407VXA | L | 12/19/2003 | 1 | TI | | Y | UC1844ALQMLV | 787 |
| 5962-8670407XA | L | 12/19/2003 | 1 | TI | | Y | UC1844AL/883B | 787 |
| 5962-8670408V2A | L | 12/19/2003 | | (NONE) | | | 1845A (GEN) | 787 |
| 5962-8670408DA | L | 12/19/2003 | 1 | TI | | Y | UC1845AW/883B | 787 |
| 5962-8670408PA | L | 12/19/2003 | 1 | TI | | Y | UC1845AJ/883B | 787 |
| 5962-8670408VPA | L | 12/19/2003 | 1 | TI | | Y | UC1845AJQMLV | 787 |
| 5962-8670408VXA | L | 12/19/2003 | 1 | TI | | Y | UC1845ALQMLV | 787 |
| 5962-8670408XA | L | 12/19/2003 | 1 | TI | | Y | UC1845AL/883B | 787 |
| 5962-8670501RA | E | 08/07/2000 | 1 | PYRAMID | | | P4C168-25DMB | 616 |
| 5962-8670501UA | E | 08/07/2000 | 1 | PYRAMID | | | P4C168-25LMB | 616 |
| 5962-8670501XA | E | 08/07/2000 | 1 | PYRAMID | | | P4C168-25LMB | 616 |
| 5962-8670502RA | E | 08/07/2000 | 1 | IDT | | Y | IDT6168LA25DB | 616 |
| 5962-8670502RA | E | 08/07/2000 | 1 | PYRAMID | | | P4C168L-25DMB | 616 |
| 5962-8670502UA | E | 08/07/2000 | 1 | IDT | | Y | 6168LA25LB | 616 |
| 5962-8670502UA | E | 08/07/2000 | 1 | PYRAMID | | | P4C168L-25LMB | 616 |
| 5962-8670502XA | E | 08/07/2000 | 1 | PYRAMID | | | P4C168L-25LMB | 616 |
| 5962-8670503RA | E | 08/07/2000 | 1 | PYRAMID | | | P4C168-35DMB | 616 |
| 5962-8670503UA | E | 08/07/2000 | 1 | PYRAMID | | | P4C168-35LMB | 616 |
| 5962-8670503XA | E | 08/07/2000 | 1 | PYRAMID | | | P4C168-35LMB | 616 |
| 5962-8670503YA | E | 08/07/2000 | 1 | PYRAMID | | | P4C168-35FMB | 616 |
| 5962-8670504RA | E | 08/07/2000 | 1 | PYRAMID | | | P4C168L-35DMB | 616 |
| 5962-8670504UA | E | 08/07/2000 | 1 | PYRAMID | | | P4C168L-35LMB | 616 |
| 5962-8670504XA | E | 08/07/2000 | 1 | PYRAMID | | | P4C168L-35LMB | 616 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-8670504YA | E | 08/07/2000 | 1 | PYRAMID | | | P4C168L-35FMB | 616 |
| 5962-8670505RA | E | 08/07/2000 | 1 | PYRAMID | | | P4C168-45DMB | 616 |
| 5962-8670505UA | E | 08/07/2000 | 1 | PYRAMID | | | P4C168-45LMB | 616 |
| 5962-8670505XA | E | 08/07/2000 | 1 | PYRAMID | | | P4C168-45LMB | 616 |
| 5962-8670505YA | E | 08/07/2000 | 1 | PYRAMID | | | P4C168-45FMB | 616 |
| 5962-8670506RA | E | 08/07/2000 | 1 | IDT | | Y | IDT6168LA45DB | 616 |
| 5962-8670506RA | E | 08/07/2000 | 1 | PYRAMID | | | P4C168L-45DMB | 616 |
| 5962-8670506UA | E | 08/07/2000 | 1 | IDT | | Y | 6168LA45LB | 616 |
| 5962-8670506UA | E | 08/07/2000 | 1 | PYRAMID | | | P4C168L-45LMB | 616 |
| 5962-8670506XA | E | 08/07/2000 | 1 | PYRAMID | | | P4C168L-45LMB | 616 |
| 5962-8670506YA | E | 08/07/2000 | 1 | PYRAMID | | | P4C168L-45FMB | 616 |
| 5962-8670507RA | E | 08/07/2000 | 1 | PYRAMID | | | P4C168-55DMB | 616 |
| 5962-8670507UA | E | 08/07/2000 | 1 | PYRAMID | | | P4C168-55LMB | 616 |
| 5962-8670507XA | E | 08/07/2000 | 1 | PYRAMID | | | P4C168-55LMB | 616 |
| 5962-8670507YA | E | 08/07/2000 | 1 | PYRAMID | | | P4C168-55FMB | 616 |
| 5962-8670508RA | E | 08/07/2000 | 1 | PYRAMID | | | P4C168L-55DMB | 616 |
| 5962-8670508UA | E | 08/07/2000 | 1 | PYRAMID | | | P4C168L-55LMB | 616 |
| 5962-8670508XA | E | 08/07/2000 | 1 | PYRAMID | | | P4C168L-55LMB | 616 |
| 5962-8670508YA | E | 08/07/2000 | 1 | PYRAMID | | | P4C168L-55FMB | 616 |
| 5962-8670509RA | E | 08/07/2000 | 1 | PYRAMID | | | P4C168-70DMB | 616 |
| 5962-8670509UA | E | 08/07/2000 | 1 | PYRAMID | | | P4C168-70LMB | 616 |
| 5962-8670509XA | E | 08/07/2000 | 1 | PYRAMID | | | P4C168-70LMB | 616 |
| 5962-8670509YA | E | 08/07/2000 | 1 | PYRAMID | | | P4C168-70FMB | 616 |
| 5962-8670510RA | E | 08/07/2000 | 1 | PYRAMID | | | P4C168L-70DMB | 616 |
| 5962-8670510UA | E | 08/07/2000 | 1 | PYRAMID | | | P4C168L-70LMB | 616 |
| 5962-8670510XA | E | 08/07/2000 | 1 | PYRAMID | | | P4C168L-70LMB | 616 |
| 5962-8670510YA | E | 08/07/2000 | 1 | PYRAMID | | | P4C168L-70FMB | 616 |
| 5962-8670511RA | E | 08/07/2000 | 1 | IDT | | Y | IDT6168SA25DB | 616 |
| 5962-8670511RA | E | 08/07/2000 | 1 | PYRAMID | | | P4C168-25DMB | 616 |
| 5962-8670511UA | E | 08/07/2000 | 1 | IDT | | Y | 6168SA25LB | 616 |
| 5962-8670511UA | E | 08/07/2000 | 1 | PYRAMID | | | P4C168-25LMB | 616 |
| 5962-8670511XA | E | 08/07/2000 | 1 | PYRAMID | | | P4C168-25LMB | 616 |
| 5962-8670511ZA | E | 08/07/2000 | 1 | PYRAMID | | | P4C168-25FSMB | 616 |
| 5962-8670512RA | E | 08/07/2000 | 1 | PYRAMID | | | P4C168-35DMB | 616 |
| 5962-8670512UA | E | 08/07/2000 | 1 | PYRAMID | | | P4C168-35LMB | 616 |
| 5962-8670512XA | E | 08/07/2000 | 1 | PYRAMID | | | P4C168-35LMB | 616 |
| 5962-8670512ZA | E | 08/07/2000 | 1 | PYRAMID | | | P4C168-35FSMB | 616 |
| 5962-8670513RA | E | 08/07/2000 | 1 | IDT | | Y | IDT6168SA45DB | 616 |
| 5962-8670513RA | E | 08/07/2000 | 1 | PYRAMID | | | P4C168-45DMB | 616 |
| 5962-8670513UA | E | 08/07/2000 | 1 | IDT | | Y | 6168SA45LB | 616 |
| 5962-8670513UA | E | 08/07/2000 | 1 | PYRAMID | | | P4C168-45LMB | 616 |
| 5962-8670513XA | E | 08/07/2000 | 1 | PYRAMID | | | P4C168-45LMB | 616 |
| 5962-8670513ZA | E | 08/07/2000 | 1 | PYRAMID | | | P4C168-45FSMB | 616 |
| 5962-8670514RA | E | 08/07/2000 | 1 | PYRAMID | | | P4C168-55DMB | 616 |
| 5962-8670514UA | E | 08/07/2000 | 1 | PYRAMID | | | P4C168-55LMB | 616 |
| 5962-8670514XA | E | 08/07/2000 | 1 | PYRAMID | | | P4C168-55LMB | 616 |
| 5962-8670514ZA | E | 08/07/2000 | 1 | PYRAMID | | | P4C168-55FSMB | 616 |
| 5962-8670515RA | E | 08/07/2000 | 1 | PYRAMID | | | P4C168-70DMB | 616 |
| 5962-8670515UA | E | 08/07/2000 | 1 | PYRAMID | | | P4C168-70LMB | 616 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-8670515XA | E | 08/07/2000 | 1 | PYRAMID | | | P4C168-70LMB | 616 |
| 5962-8670515ZA | E | 08/07/2000 | 1 | PYRAMID | | | P4C168-70FSMB | 616 |
| 5962-86706013A | B | 03/22/1996 | | (NONE) | | | 27S35 (GEN) | 657 |
| 5962-8670601KA | B | 03/22/1996 | | (NONE) | 08/02/1996 | | 27S35 (GEN) | 657 |
| 5962-8670601LA | B | 03/22/1996 | | (NONE) | 08/02/1996 | | 27S35 (GEN) | 657 |
| 5962-8670601XA | B | 03/22/1996 | | (NONE) | 08/02/1996 | | 27S35 (GEN) | 657 |
| 5962-86706023A | B | 03/22/1996 | | (NONE) | | | 27S35A (GEN) | 657 |
| 5962-8670602KA | B | 03/22/1996 | | (NONE) | 08/02/1996 | | 27S35A (GEN) | 657 |
| 5962-8670602LA | B | 03/22/1996 | | (NONE) | 08/02/1996 | | 27S35A (GEN) | 657 |
| 5962-8670602XA | B | 03/22/1996 | | (NONE) | 08/02/1996 | | 27S35A (GEN) | 657 |
| 5962-86706033A | B | 03/22/1996 | | (NONE) | 08/02/1996 | | 27S37 (GEN) | 657 |
| 5962-8670603KA | B | 03/22/1996 | | (NONE) | 08/02/1996 | | 27S37 (GEN) | 657 |
| 5962-8670603LA | B | 03/22/1996 | | (NONE) | 08/02/1996 | | 27S37 (GEN) | 657 |
| 5962-8670603XA | B | 03/22/1996 | | (NONE) | 08/02/1996 | | 27S37 (GEN) | 657 |
| 5962-86706043A | B | 03/22/1996 | | (NONE) | 08/02/1996 | | 27S37A (GEN) | 657 |
| 5962-8670604KA | B | 03/22/1996 | | (NONE) | 08/02/1996 | | 27S37A (GEN) | 657 |
| 5962-8670604LA | B | 03/22/1996 | | (NONE) | 08/02/1996 | | 27S37A (GEN) | 657 |
| 5962-8670604XA | B | 03/22/1996 | | (NONE) | 08/02/1996 | | 27S37A (GEN) | 657 |
| 5962-86707012A | | 09/11/1986 | | (NONE) | 06/30/1994 | | 2965 (GEN) | 584 |
| 5962-8670701RA | | 09/11/1986 | | (NONE) | 06/30/1994 | | 2965 (GEN) | 584 |
| 5962-86707022A | | 09/11/1986 | | (NONE) | 06/30/1994 | | 2966 (GEN) | 584 |
| 5962-8670702RA | | 09/11/1986 | | (NONE) | 06/30/1994 | | 2966 (GEN) | 584 |
| 5962-8670801EA | | 10/30/1986 | | (NONE) | | | 25LS399 (GEN) | 355 |
| 5962-8670801FA | | 10/30/1986 | | (NONE) | | | 25LS399 (GEN) | 355 |
| 5962-86709013A | E | 01/04/2002 | 1 | LANSDALE | | Y | SL82S105/B3A | 431 |
| 5962-86709013A | E | 01/04/2002 | 1 | QP SEMI | | Y | 82S105/B3A | 431 |
| 5962-8670901XA | E | 01/04/2002 | 1 | LANSDALE | | Y | SL82S105/BXA | 431 |
| 5962-8670901XA | E | 01/04/2002 | 1 | QP SEMI | | Y | 82S105/BXA | 431 |
| 5962-8670901YA | E | 01/04/2002 | 1 | LANSDALE | | Y | SL82S105/BYA | 431 |
| 5962-8670901YA | E | 01/04/2002 | 1 | QP SEMI | | Y | 82S105/BYA | 431 |
| 5962-86709023A | E | 01/04/2002 | | (NONE) | | | 82S105 (GEN) | 431 |
| 5962-8670902XA | E | 01/04/2002 | | (NONE) | | | 82S105 (GEN) | 431 |
| 5962-8670902YA | E | 01/04/2002 | | (NONE) | | | 82S105 (GEN) | 431 |
| 5962-86710012A | A | 02/16/1993 | | (NONE) | 09/30/1995 | | 54F381 (GEN) | 205 |
| 5962-8671001RA | A | 02/16/1993 | | (NONE) | 09/30/1995 | | 54F381 (GEN) | 205 |
| 5962-8671001SA | A | 02/16/1993 | | (NONE) | 09/30/1995 | | 54F381 (GEN) | 205 |
| 5962-86710023A | A | 02/16/1993 | | NATIONAL | | Y | 54F181LMQB | 205 |
| 5962-8671002JA | A | 02/16/1993 | | NATIONAL | | Y | 54F181DMQB | 205 |
| 5962-8671101XA | D | 02/14/2003 | 3 | NATIONAL | | Y | LM113H-SMD | 785 |
| 5962-8671101ZA | D | 02/14/2003 | 3 | NATIONAL | | Y | LM113WG-SMD | 785 |
| 5962-8671102XA | D | 02/14/2003 | 3 | NATIONAL | | Y | LM113-1H-SMD | 785 |
| 5962-8671102ZA | D | 02/14/2003 | 3 | NATIONAL | | Y | LM113-1WG-SMD | 785 |
| 5962-8671103XA | D | 02/14/2003 | | (NONE) | 09/09/1999 | | LM113-2 (GEN) | 785 |
| 5962-8671201CA | C | 07/10/1996 | | (NONE) | 09/30/1995 | | 1545 (GEN) | 755 |
| 5962-8671201IA | C | 07/10/1996 | | (NONE) | 09/30/1995 | | 1545 (GEN) | 755 |
| 5962-86713012A | A | 05/01/2002 | 1 | ROCHESTER | | Y | 25LS2521/B2A | 209 |
| 5962-86713012A | A | 05/01/2002 | 1 | SARNOFF | | Y | GEM12401B2A | 209 |
| 5962-86713012C | A | 05/01/2002 | 1 | SARNOFF | | Y | GEM12401B2C | 209 |
| 5962-8671301RA | A | 05/01/2002 | 1 | ROCHESTER | | Y | 25LS2521/BRA | 209 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-8671301RA | A | 05/01/2002 | 1 | SARNOFF | | Y | GEM12401BRA | 209 |
| 5962-8671301RC | A | 05/01/2002 | 1 | SARNOFF | | Y | GEM12401BRC | 209 |
| 5962-8671301SA | A | 05/01/2002 | 1 | ROCHESTER | | Y | 25LS2521/BSA | 209 |
| 5962-8671301SA | A | 05/01/2002 | 1 | SARNOFF | | Y | GEM12401BSA | 209 |
| 5962-8671301SC | A | 05/01/2002 | 1 | SARNOFF | | Y | GEM12401BSC | 209 |
| 5962-86714012A | B | 06/10/2002 | 1 | ROCHESTER | | Y | 2917A/B2A | 590 |
| 5962-8671401RA | B | 06/10/2002 | 1 | ROCHESTER | | Y | 2917A/BRA | 590 |
| 5962-8671401SA | B | 06/10/2002 | 1 | ROCHESTER | | Y | 2917A/BSA | 590 |
| 5962-86715012A | A | 01/29/1999 | 1 | ROCHESTER | | Y | 25S18/B2A | 159 |
| 5962-86715012A | A | 01/29/1999 | 0 | SARNOFF | | Y | GEM12001Q2A | 159 |
| 5962-86715012C | A | 01/29/1999 | 0 | SARNOFF | | Y | GEM12001Q2C | 159 |
| 5962-8671501EA | A | 01/29/1999 | 1 | ROCHESTER | | Y | 25S18/BEA | 159 |
| 5962-8671501EA | A | 01/29/1999 | 0 | SARNOFF | | Y | GEM12001QEA | 159 |
| 5962-8671501EC | A | 01/29/1999 | 0 | SARNOFF | | Y | GEM12001QEC | 159 |
| 5962-8671501FA | A | 01/29/1999 | 1 | ROCHESTER | | Y | 25S18/BFA | 159 |
| 5962-8671501FA | A | 01/29/1999 | 0 | SARNOFF | | Y | GEM12001QFA | 159 |
| 5962-8671501FC | A | 01/29/1999 | 0 | SARNOFF | | Y | GEM12001QFC | 159 |
| 5962-86716012A | D | 05/01/2003 | 1 | INTERSIL | | Y | HI4-201HS/883 | 183 |
| 5962-86716012A | D | 05/01/2003 | 1 | SILICONIX | | Y | DG201HSAZ/883 | 183 |
| 5962-8671601EA | D | 05/01/2003 | 1 | INTERSIL | | Y | HI1-201HS/883 | 183 |
| 5962-8671601EA | D | 05/01/2003 | 1 | SILICONIX | | Y | DG201HSAK/883 | 183 |
| 5962-86716022A | D | 05/01/2003 | 1 | SILICONIX | | Y | DG271AZ/883 | 183 |
| 5962-8671602EA | D | 05/01/2003 | 1 | SILICONIX | | Y | DG271AK/883 | 183 |
| 5962-86716032A | D | 05/01/2003 | 1 | ANALOG (3) | | Y | ADG201HSTE/883B | 183 |
| 5962-8671603EA | D | 05/01/2003 | 1 | ANALOG (3) | | Y | ADG201HSTQ/883B | 183 |
| 5962-8671603VEA | D | 05/01/2003 | | (NONE) | | | ADG201HST (GEN) | 183 |
| 5962-86717012A | D | 06/20/2002 | 1 | TI | | Y | SNJ54LS595FK | 226 |
| 5962-8671701EA | D | 06/20/2002 | 1 | TI | | Y | SNJ54LS595J | 226 |
| 5962-8671701FA | D | 06/20/2002 | 1 | TI | | Y | SNJ54LS595W | 226 |
| 5962-86718012A | B | 06/26/2002 | 1 | ROCHESTER | | Y | 25S10/B2A | 220 |
| 5962-8671801EA | B | 06/26/2002 | 1 | ROCHESTER | | Y | 25S10/BEA | 220 |
| 5962-8671801FA | B | 06/26/2002 | 1 | ROCHESTER | | Y | 25S10/BFA | 220 |
| 5962-86719012A | | 10/10/1986 | | (NONE) | | | 29LS18 (GEN) | 220 |
| 5962-8671901EA | | 10/10/1986 | | (NONE) | | | 29LS18 (GEN) | 220 |
| 5962-8671901FA | | 10/10/1986 | | (NONE) | | | 29LS18 (GEN) | 220 |
| 5962-86720012A | A | 11/26/2001 | 1 | ROCHESTER | | Y | 26S10/B2A | 590 |
| 5962-8672001EA | A | 11/26/2001 | 1 | ROCHESTER | | Y | 26S10/BEA | 590 |
| 5962-8672001FA | A | 11/26/2001 | 1 | ROCHESTER | | Y | 26S10/BFA | 590 |
| 5962-86721012A | C | 07/10/2003 | | (NONE) | 12/01/1993 | | 26LS30 (GEN) | 569 |
| 5962-8672101EA | C | 07/10/2003 | 1 | NATIONAL | | Y | DS1691AJ/883 | 569 |
| 5962-8672101FA | C | 07/10/2003 | | (NONE) | 12/01/1993 | | 26LS30 (GEN) | 569 |
| 5962-8672201EA | D | 11/01/2001 | 1 | SEMELAB | | Y | IP5560J-DESC | 787 |
| 5962-86723012A | C | 11/28/2001 | 1 | ROCHESTER | | Y | 2947/B2A | 590 |
| 5962-86723012A | C | 11/28/2001 | 1 | SARNOFF | | Y | GEM07501Q2A | 590 |
| 5962-86723012C | C | 11/28/2001 | 1 | SARNOFF | | Y | GEM07501Q2C | 590 |
| 5962-8672301RA | C | 11/28/2001 | 1 | ROCHESTER | | Y | 2947/BRA | 590 |
| 5962-8672301RA | C | 11/28/2001 | 1 | SARNOFF | | Y | GEM07501QRA | 590 |
| 5962-8672301RC | C | 11/28/2001 | 1 | SARNOFF | | Y | GEM07501QRC | 590 |
| 5962-86723022A | C | 11/28/2001 | 1 | ROCHESTER | | Y | 2946/B2A | 590 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-86723022A | C | 11/28/2001 | 1 | SARNOFF | | Y | GEM13302B2A | 590 |
| 5962-86723022C | C | 11/28/2001 | 1 | SARNOFF | | Y | GEM13302B2C | 590 |
| 5962-8672302RA | C | 11/28/2001 | 1 | ROCHESTER | | Y | 2946/BRA | 590 |
| 5962-8672302RA | C | 11/28/2001 | 1 | SARNOFF | | Y | GEM13302BRA | 590 |
| 5962-8672302RC | C | 11/28/2001 | 1 | SARNOFF | | Y | GEM13302BRC | 590 |
| 5962-8672401RA | A | 09/15/1987 | | (NONE) | | | 25S240 (GEN) | 529 |
| 5962-8672401SA | A | 09/15/1987 | | (NONE) | | | 25S240 (GEN) | 529 |
| 5962-8672501RA | A | 03/17/1987 | | (NONE) | 06/30/1994 | | 25S241 (GEN) | 529 |
| 5962-8672501SA | A | 03/17/1987 | | (NONE) | 06/30/1994 | | 25S241 (GEN) | 529 |
| 5962-8672601EA | A | 10/19/1987 | 2 | SARNOFF | | Y | GEM09301EA | 210 |
| 5962-8672601EC | A | 10/19/1987 | 2 | SARNOFF | | Y | GEM09301EC | 210 |
| 5962-8672601FA | A | 10/19/1987 | 2 | SARNOFF | | Y | GEM09301FA | 210 |
| 5962-8672701EA | | 02/23/1987 | 1 | ROCHESTER | | Y | 93S16/BEA | 304 |
| 5962-8672701FA | | 02/23/1987 | 1 | ROCHESTER | | Y | 93S16/BFA | 304 |
| 5962-8672801EA | | 03/02/1987 | 1 | ROCHESTER | | Y | 25S09/BEA | 275 |
| 5962-8672801FA | | 03/02/1987 | 1 | ROCHESTER | | Y | 25S09/BFA | 275 |
| 5962-86801013A | A | 03/07/1988 | | (NONE) | 06/30/1994 | | 2942 (GEN) | 429 |
| 5962-8680101WA | A | 03/07/1988 | | (NONE) | 06/30/1994 | | 2942 (GEN) | 429 |
| 5962-8680201VA | D | 02/07/2003 | 1 | ANALOG (2) | | Y | AD570SD/883B | 592 |
| 5962-8680202VA | D | 02/07/2003 | 1 | ANALOG (2) | | Y | AD571SD/883B | 592 |
| 5962-8680203VVA | D | 02/07/2003 | 1 | ANALOG (5) | | Y | AD571SD/QMLV | 592 |
| 5962-86803013A | A | 05/31/1988 | | (NONE) | | | PAL20RA10 (GEN) | 431 |
| 5962-8680301KA | A | 05/31/1988 | | (NONE) | | | PAL20RA10 (GEN) | 431 |
| 5962-8680301LA | A | 05/31/1988 | | (NONE) | | | PAL20RA10 (GEN) | 431 |
| 5962-86804013A | | 09/29/1987 | | (NONE) | | | PAL18L4 (GEN) | 431 |
| 5962-8680401KA | | 09/29/1987 | | (NONE) | | | PAL18L4 (GEN) | 431 |
| 5962-8680401LA | | 09/29/1987 | | (NONE) | | | PAL18L4 (GEN) | 431 |
| 5962-86804023A | | 09/29/1987 | | (NONE) | | | PAL12L10 (GEN) | 431 |
| 5962-8680402KA | | 09/29/1987 | | (NONE) | | | PAL12L10 (GEN) | 431 |
| 5962-8680402LA | | 09/29/1987 | | (NONE) | | | PAL12L10 (GEN) | 431 |
| 5962-86804033A | | 09/29/1987 | | (NONE) | | | PAL14L8 (GEN) | 431 |
| 5962-8680403KA | | 09/29/1987 | | (NONE) | | | PAL14L8 (GEN) | 431 |
| 5962-8680403LA | | 09/29/1987 | | (NONE) | | | PAL14L8 (GEN) | 431 |
| 5962-86804043A | | 09/29/1987 | | (NONE) | | | PAL16L6 (GEN) | 431 |
| 5962-8680404KA | | 09/29/1987 | | (NONE) | | | PAL16L6 (GEN) | 431 |
| 5962-8680404LA | | 09/29/1987 | | (NONE) | | | PAL16L6 (GEN) | 431 |
| 5962-86804053A | | 09/29/1987 | | (NONE) | | | PAL20L2 (GEN) | 431 |
| 5962-8680405KA | | 09/29/1987 | | (NONE) | | | PAL20L2 (GEN) | 431 |
| 5962-8680405LA | | 09/29/1987 | | (NONE) | | | PAL20L2 (GEN) | 431 |
| 5962-86804063A | | 09/29/1987 | | (NONE) | | | PAL20C1 (GEN) | 431 |
| 5962-8680406KA | | 09/29/1987 | | (NONE) | | | PAL20C1 (GEN) | 431 |
| 5962-8680406LA | | 09/29/1987 | | (NONE) | | | PAL20C1 (GEN) | 431 |
| 5962-8680501QA | E | 07/24/2000 | 2 | QP SEMI | | | AT27C1024-30/QA | 664 |
| 5962-8680501XA | E | 07/24/2000 | 2 | QP SEMI | | | AT27C1024-30/XA | 664 |
| 5962-8680502QA | E | 07/24/2000 | 2 | QP SEMI | | | AT27C1024-25/QA | 664 |
| 5962-8680502XA | E | 07/24/2000 | 2 | QP SEMI | | | AT27C1024-25/XA | 664 |
| 5962-8680503QA | E | 07/24/2000 | 2 | QP SEMI | | | AT27C1024-20/QA | 664 |
| 5962-8680503XA | E | 07/24/2000 | 2 | QP SEMI | | | AT27C1024-20/XA | 664 |
| 5962-8680504QA | E | 07/24/2000 | 2 | QP SEMI | | | AT27C1024-17/QA | 664 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-8680504XA | E | 07/24/2000 | 2 | QP SEMI | | | AT27C1024-17/XA | 664 |
| 5962-8680504XC | E | 07/24/2000 | 2 | QP SEMI | | | AT27C1024-17/XC | 664 |
| 5962-8680505QA | E | 07/24/2000 | 2 | QP SEMI | | | AT27C1024-15/QA | 664 |
| 5962-8680505XA | E | 07/24/2000 | 2 | QP SEMI | | | AT27C1024-15/XA | 664 |
| 5962-8680506QA | E | 07/24/2000 | 2 | QP SEMI | | | AT27C1024-12/QA | 664 |
| 5962-8680506XA | E | 07/24/2000 | 2 | QP SEMI | | | AT27C1024-12/XA | 664 |
| 5962-8680507QA | E | 07/24/2000 | 2 | QP SEMI | | | AT27C1024-90/QA | 664 |
| 5962-8680507XA | E | 07/24/2000 | 2 | QP SEMI | | | AT27C1024-90/XA | 664 |
| 5962-8680508QA | E | 07/24/2000 | 2 | QP SEMI | | | AT27HC1024-70/QA | 664 |
| 5962-8680508XA | E | 07/24/2000 | 2 | QP SEMI | | | AT27HC1024-70/XA | 664 |
| 5962-86806012A | D | 03/04/2003 | 1 | MICROSEMI | | Y | SG1846L/883B | 787 |
| 5962-86806012A | D | 03/04/2003 | 1 | TI | | Y | UC1846L/883B | 787 |
| 5962-8680601V2A | D | 03/04/2003 | 1 | TI | | Y | UC1846LQMLV | 787 |
| 5962-8680601EA | D | 03/04/2003 | 1 | MICROSEMI | | Y | SG1846J/883B | 787 |
| 5962-8680601EA | D | 03/04/2003 | 1 | TI | | Y | UC1846J/883B | 787 |
| 5962-8680601VEA | D | 03/04/2003 | 1 | TI | | Y | UC1846JQMLV | 787 |
| 5962-8680601FA | D | 03/04/2003 | 1 | MICROSEMI | | Y | SG1846F/883B | 787 |
| 5962-86806022A | D | 03/04/2003 | | (NONE) | 12/31/2001 | | UC1847 (GEN) | 787 |
| 5962-8680602EA | D | 03/04/2003 | | (NONE) | 12/31/2001 | | UC1847 (GEN) | 787 |
| 5962-8680602FA | D | 03/04/2003 | | (NONE) | | | 1847 (GEN) | 787 |
| 5962-8680901YA | C | 03/01/2004 | 1 | ROCHESTER | | Y | MQ8797BH/BYA | 420 |
| 5962-8680901YC | C | 03/01/2004 | 1 | ROCHESTER | | Y | MQ8797BH/BYC | 420 |
| 5962-8680901ZA | C | 03/01/2004 | 1 | ROCHESTER | | Y | MG8797BH/BZA | 420 |
| 5962-8680901ZC | C | 03/01/2004 | 1 | ROCHESTER | | Y | MG8797BH/BZC | 420 |
| 5962-8681001XA | A | 12/20/1988 | | (NONE) | 09/01/1997 | | 68562 (GEN) | 420 |
| 5962-8681101XA | | 02/26/1991 | | (NONE) | | | 68442-8 (GEN) | 423 |
| 5962-8681101YA | | 02/26/1991 | | (NONE) | | | 68442-8 (GEN) | 423 |
| 5962-86812012A | C | 05/28/2004 | 3 | TI | | Y | SNJ54HC368FK | 523 |
| 5962-8681201EA | C | 05/28/2004 | 3 | TI | | Y | SNJ54HC368J | 523 |
| 5962-86813012A | B | 05/15/2003 | | (NONE) | | | 54HC533 (GEN) | 341 |
| 5962-8681301RA | B | 05/15/2003 | 1 | TI | | Y | CD54HC533F3A | 341 |
| 5962-86814012A | B | 04/15/2004 | 1 | ROCHESTER | | Y | 54HC534/B2A | 159 |
| 5962-8681401RA | B | 04/15/2004 | 1 | TI | | Y | CD54HC534F3A | 159 |
| 5962-86815012A | B | 04/15/2004 | | (NONE) | | | 54HC564 (GEN) | 159 |
| 5962-8681501RA | B | 04/15/2004 | 1 | TI | | Y | CD54HC564F3A | 159 |
| 5962-86816012A | C | 08/22/2003 | 3 | TI | | Y | SNJ54HC595FK | 226 |
| 5962-8681601EA | C | 08/22/2003 | 3 | TI | | Y | SNJ54HC595J | 226 |
| 5962-8681601VEA | C | 08/22/2003 | 3 | TI | | Y | SNV54HC595J | 226 |
| 5962-8681601VFA | C | 08/22/2003 | 3 | TI | | Y | SNV54HC595W | 226 |
| 5962-86817012A | B | 01/07/1991 | | (NONE) | | | 54HC597 (GEN) | 225 |
| 5962-8681701EA | B | 01/07/1991 | 1 | TI | | Y | CD54HC597F3A | 225 |
| 5962-86818012A | C | 10/25/1990 | 1 | TI | | Y | SNJ54HC688FK | 209 |
| 5962-8681801RA | C | 10/25/1990 | 1 | TI | | Y | SNJ54HC688J | 209 |
| 5962-86819012A | E | 01/25/2002 | | (NONE) | | | 54HC4049 (GEN) | 541 |
| 5962-8681901EA | E | 01/25/2002 | 1 | TI | | Y | CD54HC4049F3A | 541 |
| 5962-8681901FA | E | 01/25/2002 | | (NONE) | | | 54HC4049 (GEN) | 541 |
| 5962-8681901VFA | E | 01/25/2002 | | (NONE) | | | 54HC4049 (GEN) | 541 |
| 5962-8681901VXA | E | 01/25/2002 | 2 | STMICRO | | Y | 54HC4049K02V | 541 |
| 5962-8681901VXC | E | 01/25/2002 | 2 | STMICRO | | Y | 54HC4049K01V | 541 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-8681901XA | E | 01/25/2002 | 2 | STMICRO | | Y | 54HC4049K02Q | 541 |
| 5962-8681901XC | E | 01/25/2002 | 2 | STMICRO | | Y | 54HC4049K01Q | 541 |
| 5962-86820012A | E | 01/25/2002 | | (NONE) | | | 54HC4050 (GEN) | 540 |
| 5962-8682001EA | E | 01/25/2002 | 1 | TI | | Y | CD54HC4050F3A | 540 |
| 5962-8682001FA | E | 01/25/2002 | | (NONE) | | | 54HC4050 (GEN) | 540 |
| 5962-8682001VFA | E | 01/25/2002 | | (NONE) | | | 54HC4050 (GEN) | 540 |
| 5962-8682001VXA | E | 01/25/2002 | 2 | STMICRO | | Y | 54HC4050K02V | 540 |
| 5962-8682001VXC | E | 01/25/2002 | 2 | STMICRO | | Y | 54HC4050K01V | 540 |
| 5962-8682001XA | E | 01/25/2002 | 2 | STMICRO | | Y | 54HC4050K02Q | 540 |
| 5962-8682001XC | E | 01/25/2002 | 2 | STMICRO | | Y | 54HC4050K01Q | 540 |
| 5962-86821012A | C | 06/18/2004 | 1 | TI | | Y | SNJ54HC42FK | 281 |
| 5962-8682101EA | C | 06/18/2004 | 1 | TI | | Y | SNJ54HC42J | 281 |
| 5962-8682101FA | C | 06/18/2004 | | (NONE) | | | 54HC42 (GEN) | 281 |
| 5962-86822013A | D | 03/10/2004 | | (NONE) | | | 54HC154 (GEN) | 280 |
| 5962-8682201JA | D | 03/10/2004 | 1 | TI | | Y | CD54HC154F3A | 280 |
| 5962-8682201LA | D | 03/10/2004 | | (NONE) | | | 54HC154 (GEN) | 280 |
| 5962-86823012A | B | 12/08/1988 | | (NONE) | | | 54HC158 (GEN) | 275 |
| 5962-8682301EA | B | 12/08/1988 | | (NONE) | 12/31/2001 | | 54HC158 (GEN) | 275 |
| 5962-86824012A | A | 04/10/1987 | | (NONE) | | | 54HC160 (GEN) | 301 |
| 5962-8682401EA | A | 04/10/1987 | | (NONE) | 06/01/2001 | | 54HC160 (GEN) | 301 |
| 5962-8682401FA | A | 04/10/1987 | | (NONE) | | | 54HC160 (GEN) | 301 |
| 5962-86825012A | B | 05/15/2003 | 1 | ROCHESTER | | Y | 54HC173/B2A | 159 |
| 5962-8682501EA | B | 05/15/2003 | 1 | TI | | Y | CD54HC173F3A | 159 |
| 5962-86826012A | B | 06/01/1989 | 1 | ROCHESTER | | Y | 54HC194/B2A | 220 |
| 5962-8682601EA | B | 06/01/1989 | 1 | TI | | Y | CD54HC194F3A | 220 |
| 5962-86827012A | B | 12/12/2001 | 1 | TI | | Y | SNJ54HC195FK | 220 |
| 5962-8682701EA | B | 12/12/2001 | 1 | TI | | Y | SNJ54HC195J | 220 |
| 5962-86828012A | C | 06/18/2004 | 1 | TI | | Y | SNJ54HC366FK | 514 |
| 5962-8682801EA | C | 06/18/2004 | 1 | TI | | Y | SNJ54HC366J | 514 |
| 5962-8683001XA | A | 01/10/1989 | | (NONE) | | | 2864-250 (GEN) | 660 |
| 5962-8683001YA | A | 01/10/1989 | | (NONE) | | | 2864-250 (GEN) | 660 |
| 5962-8683001ZA | A | 01/10/1989 | | (NONE) | | | 2864-250 (GEN) | 660 |
| 5962-8683002XA | A | 01/10/1989 | | (NONE) | | | 2864-350 (GEN) | 660 |
| 5962-8683002YA | A | 01/10/1989 | | (NONE) | | | 2864-350 (GEN) | 660 |
| 5962-8683002ZA | A | 01/10/1989 | | (NONE) | | | 2864-350 (GEN) | 660 |
| 5962-8683003XA | A | 01/10/1989 | | (NONE) | | | 2864-300 (GEN) | 660 |
| 5962-8683003YA | A | 01/10/1989 | | (NONE) | | | 2864-300 (GEN) | 660 |
| 5962-8683003ZA | A | 01/10/1989 | | (NONE) | | | 2864-300 (GEN) | 660 |
| 5962-8683004XA | A | 01/10/1989 | | (NONE) | | | 5233-250 (GEN) | 660 |
| 5962-8683004YA | A | 01/10/1989 | | (NONE) | | | 5233-250 (GEN) | 660 |
| 5962-8683004ZA | A | 01/10/1989 | | (NONE) | | | 5233-250 (GEN) | 660 |
| 5962-8683005XA | A | 01/10/1989 | | (NONE) | | | 2864-250 (GEN) | 660 |
| 5962-8683005YA | A | 01/10/1989 | | (NONE) | | | 2864-250 (GEN) | 660 |
| 5962-8683005ZA | A | 01/10/1989 | | (NONE) | | | 2864-250 (GEN) | 660 |
| 5962-8683006XA | A | 01/10/1989 | | (NONE) | 02/01/1994 | | 2864-25 (GEN) | 660 |
| 5962-8683006YA | A | 01/10/1989 | | (NONE) | 02/01/1994 | | 2864-25 (GEN) | 660 |
| 5962-8683006ZA | A | 01/10/1989 | | (NONE) | 02/01/1994 | | 2864-25 (GEN) | 660 |
| 5962-8683007XA | A | 01/10/1989 | | (NONE) | 02/01/1994 | | 2864-35 (GEN) | 660 |
| 5962-8683007YA | A | 01/10/1989 | | (NONE) | 02/01/1994 | | 2864-35 (GEN) | 660 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-8683007ZA | A | 01/10/1989 | | (NONE) | 02/01/1994 | | 2864-35 (GEN) | 660 |
| 5962-8683008XA | A | 01/10/1989 | | (NONE) | | | 2864-25 (GEN) | 660 |
| 5962-8683008YA | A | 01/10/1989 | | (NONE) | | | 2864-25 (GEN) | 660 |
| 5962-8683008ZA | A | 01/10/1989 | | (NONE) | | | 2864-25 (GEN) | 660 |
| 5962-8683009XA | A | 01/10/1989 | | (NONE) | | | 2864-300 (GEN) | 660 |
| 5962-8683009YA | A | 01/10/1989 | | (NONE) | | | 2864-300 (GEN) | 660 |
| 5962-8683009ZA | A | 01/10/1989 | | (NONE) | | | 2864-300 (GEN) | 660 |
| 5962-8683010XA | A | 01/10/1989 | | (NONE) | | | 2864 (GEN) | 660 |
| 5962-8683010YA | A | 01/10/1989 | | (NONE) | | | 2864 (GEN) | 660 |
| 5962-8683010ZA | A | 01/10/1989 | | (NONE) | | | 2864 (GEN) | 660 |
| 5962-8683101CA | A | 01/31/1995 | 1 | TI | | Y | CD54HCT00F3A | 100 |
| 5962-86833012A | C | 11/01/2001 | I | TI | | Y | SNJ54ALS00AFK | 100 |
| 5962-8683301DA | C | 11/01/2001 | I | TI | | Y | SNJ54ALS00AW | 100 |
| 5962-86834012A | A | 06/22/2000 | 1 | QP SEMI | | Y | 54F243/2A | 590 |
| 5962-8683401CA | A | 06/22/2000 | 1 | QP SEMI | | Y | 54F243/CA | 590 |
| 5962-8683401DA | A | 06/22/2000 | 1 | QP SEMI | | Y | 54F243/DA | 590 |
| 5962-86836012A | C | 10/30/2001 | I | TI | | Y | SNJ54ALS32FK | 125 |
| 5962-8683601DA | C | 10/30/2001 | 2 | TI | | Y | SNJ54ALS32W | 125 |
| 5962-86837012A | B | 07/06/1992 | I | TI | | Y | SNJ54ALS30AFK | 106 |
| 5962-8683701DA | B | 07/06/1992 | 2 | TI | | Y | SNJ54ALS30AW | 106 |
| 5962-86838012A | C | 10/31/2001 | I | TI | | Y | SNJ54ALS27FK | 122 |
| 5962-8683801DA | C | 10/31/2001 | 1 | TI | | Y | SNJ54ALS27W | 122 |
| 5962-86839012A | D | 01/18/1996 | 2 | TI | | Y | SNJ54ALS244CFK | 529 |
| 5962-8683901RA | D | 01/18/1996 | 2 | TI | | Y | SNJ54ALS244CJ | 529 |
| 5962-8683901SA | D | 01/18/1996 | 2 | TI | | Y | SNJ54ALS244CW | 529 |
| 5962-86840012A | D | 06/05/1996 | 2 | TI | | Y | SNJ54ALS191AFK | 304 |
| 5962-8684001EA | D | 06/05/1996 | 2 | TI | | Y | SNJ54ALS191AJ | 304 |
| 5962-8684001FA | D | 06/05/1996 | 2 | TI | | Y | SNJ54ALS191AW | 304 |
| 5962-86841012A | C | 01/21/1998 | 2 | TI | | Y | SNJ54ALS11AFK | 112 |
| 5962-8684101CA | C | 01/21/1998 | 2 | TI | | Y | SNJ54ALS11AJ | 112 |
| 5962-8684101DA | C | 01/21/1998 | 2 | TI | | Y | SNJ54ALS11AW | 112 |
| 5962-86842012A | C | 01/22/1998 | 2 | TI | | Y | SNJ54ALS08FK | 110 |
| 5962-8684201CA | C | 01/22/1998 | 2 | TI | | Y | SNJ54ALS08J | 110 |
| 5962-8684201DA | C | 01/22/1998 | 2 | TI | | Y | 72404L10 (GEN) | 110 |
| 5962-86843012A | B | 07/07/1992 | I | TI | | Y | SNJ54ALS04BFK | 143 |
| 5962-8684301DA | B | 07/07/1992 | 2 | TI | | Y | SNJ54ALS04BW | 143 |
| 5962-86844012A | C | 11/20/1992 | I | TI | | Y | SNJ54ALS02AFK | 120 |
| 5962-8684401DA | C | 11/20/1992 | | (NONE) | | | IDT72404 (GEN) | 120 |
| 5962-8684501IA | B | 10/25/1994 | | (NONE) | 03/30/2001 | | LT1016 (GEN) | 779 |
| 5962-8684501PA | B | 10/25/1994 | | (NONE) | 03/30/2001 | | LT1016 (GEN) | 779 |
| 5962-86846012A | C | 04/03/2001 | | (NONE) | | | 7C404-10 (GEN) | 670 |
| 5962-8684601SA | C | 04/03/2001 | | (NONE) | | | 72404L25 (GEN) | 670 |
| 5962-8684601VA | C | 04/03/2001 | | (NONE) | 10/29/2001 | | 72404L10 (GEN) | 670 |
| 5962-8684601XA | C | 04/03/2001 | | (NONE) | | | 72404L10 (GEN) | 670 |
| 5962-86846022A | C | 04/03/2001 | | (NONE) | | | 7C404-15 (GEN) | 670 |
| 5962-8684602SA | C | 04/03/2001 | | (NONE) | | | 72404L15 (GEN) | 670 |
| 5962-8684602VA | C | 04/03/2001 | 1 | IDT | 10/31/2004 | Y | IDT72404L15DB | 670 |
| 5962-8684602XA | C | 04/03/2001 | | (NONE) | | | 72404L15 (GEN) | 670 |
| 5962-86846032A | C | 04/03/2001 | | (NONE) | | | 7C404-25 (GEN) | 670 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-8684603SA | C | 04/03/2001 | | (NONE) | | | 72404L25 (GEN) | 670 |
| 5962-8684603VA | C | 04/03/2001 | | (NONE) | 10/29/2001 | | 72404L25 (GEN) | 670 |
| 5962-8684603XA | C | 04/03/2001 | | (NONE) | | | 72404L25 (GEN) | 670 |
| 5962-86846042A | C | 04/03/2001 | | (NONE) | | | 72404L35 (GEN) | 670 |
| 5962-8684604SA | C | 04/03/2001 | | (NONE) | | | 72404L35 (GEN) | 670 |
| 5962-8684604VA | C | 04/03/2001 | 1 | IDT | 10/31/2004 | Y | IDT72404L35DB | 670 |
| 5962-8684701EA | C | 12/20/2001 | 1 | TI | | Y | CD54HC123F3A | 166 |
| 5962-86847022A | C | 12/20/2001 | 1 | NATIONAL | | Y | MM54HC123AE/883 | 166 |
| 5962-8684702EA | C | 12/20/2001 | 1 | NATIONAL | | Y | MM54HC123AJ/883 | 166 |
| 5962-86848012A | C | 06/12/2001 | 3 | TI | | Y | SNJ54HC126FK | 520 |
| 5962-8684801CA | C | 06/12/2001 | 3 | TI | | Y | SNJ54HC126J | 520 |
| 5962-8684901PA | A | 06/11/2002 | 0 | MICROSEMI | | Y | SG1549Y/883B | 899 |
| 5962-86850012A | | 06/26/1987 | | (NONE) | 06/01/1997 | | 54F194 (GEN) | 220 |
| 5962-8685001EA | | 06/26/1987 | | (NONE) | 06/01/1997 | | 54F194 (GEN) | 220 |
| 5962-8685001FA | | 06/26/1987 | | (NONE) | 06/01/1997 | | 54F194 (GEN) | 220 |
| 5962-8685101XA | B | 12/04/1992 | | (NONE) | | | 8X376 (GEN) | 421 |
| 5962-8685201CA | A | 03/11/2003 | 1 | TI | | Y | CD54HCT32F3A | 125 |
| 5962-8685301CA | A | 04/09/2003 | 1 | TI | | Y | CD54HCT74F3A | 158 |
| 5962-8685401EA | | 01/15/1987 | | (NONE) | 06/01/2001 | | 54HCT161 (GEN) | 304 |
| 5962-8685501EA | A | 05/20/2003 | 1 | TI | | Y | CD54HCT165F3A | 225 |
| 5962-8685601RA | A | 04/09/2003 | 1 | TI | | Y | CD54HCT573F3A | 341 |
| 5962-8685701RA | A | 03/11/2003 | 1 | TI | | Y | CD54HCT688F3A | 209 |
| 5962-8685901LA | A | 10/22/1991 | 1 | PYRAMID | | | P4C198A-85DMB | 620 |
| 5962-8685901XA | A | 10/22/1991 | 1 | PYRAMID | | | P4C198A-85LMB | 620 |
| 5962-8685902LA | A | 10/22/1991 | 1 | PYRAMID | | | P4C198AL-85DMB | 620 |
| 5962-8685902XA | A | 10/22/1991 | 1 | PYRAMID | | | P4C198AL-85LMB | 620 |
| 5962-8685903LA | A | 10/22/1991 | 1 | PYRAMID | | | P4C198A-70DMB | 620 |
| 5962-8685903XA | A | 10/22/1991 | 1 | PYRAMID | | | P4C198A-70LMB | 620 |
| 5962-8685904LA | A | 10/22/1991 | 1 | PYRAMID | | | P4C198AL-70DMB | 620 |
| 5962-8685904XA | A | 10/22/1991 | 1 | PYRAMID | | | P4C198AL-70LMB | 620 |
| 5962-8685905LA | A | 10/22/1991 | 1 | PYRAMID | | | P4C198A-55CMB | 620 |
| 5962-8685905XA | A | 10/22/1991 | 1 | PYRAMID | | | P4C198A-55LMB | 620 |
| 5962-8685906LA | A | 10/22/1991 | 1 | PYRAMID | | | P4C198AL-55CMB | 620 |
| 5962-8685906XA | A | 10/22/1991 | 1 | PYRAMID | | | P4C198AL-55LMB | 620 |
| 5962-8685907LA | A | 10/22/1991 | 1 | PYRAMID | | | P4C198A-45CMB | 620 |
| 5962-8685907XA | A | 10/22/1991 | 1 | PYRAMID | | | P4C198A-45LMB | 620 |
| 5962-8685908LA | A | 10/22/1991 | 1 | PYRAMID | | | P4C198AL-45CMB | 620 |
| 5962-8685908XA | A | 10/22/1991 | 1 | PYRAMID | | | P4C198AL-45LMB | 620 |
| 5962-8685909LA | A | 10/22/1991 | 1 | PYRAMID | | | P4C198A-35CMB | 620 |
| 5962-8685909XA | A | 10/22/1991 | 1 | PYRAMID | | | P4C198A-35LMB | 620 |
| 5962-8685910LA | A | 10/22/1991 | 1 | PYRAMID | | | P4C198AL-35CMB | 620 |
| 5962-8685910XA | A | 10/22/1991 | 1 | PYRAMID | | | P4C198AL-35LMB | 620 |
| 5962-8685911KA | A | 10/22/1991 | | (NONE) | 06/01/1996 | | 6198L70 (GEN) | 620 |
| 5962-8685911LA | A | 10/22/1991 | 1 | AUSTIN SEMI. | | Y | MT5C6405C-70L | 620 |
| 5962-8685911UA | A | 10/22/1991 | 1 | AUSTIN SEMI. | | Y | MT5C6405EC-70L | 620 |
| 5962-8685911XA | A | 10/22/1991 | | (NONE) | 06/01/1996 | | 6198L70 (GEN) | 620 |
| 5962-8685912KA | A | 10/22/1991 | | (NONE) | 06/01/1996 | | 6198S70 (GEN) | 620 |
| 5962-8685912LA | A | 10/22/1991 | 1 | AUSTIN SEMI. | | Y | MT5C6405C-70 | 620 |
| 5962-8685912UA | A | 10/22/1991 | 1 | AUSTIN SEMI. | | Y | MT5C6405EC-70 | 620 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-8685912XA | A | 10/22/1991 | | (NONE) | 06/01/1996 | | 6198S70 (GEN) | 620 |
| 5962-8685913KA | A | 10/22/1991 | | (NONE) | 06/01/1996 | | 6198L55 (GEN) | 620 |
| 5962-8685913LA | A | 10/22/1991 | 1 | AUSTIN SEMI. | | Y | MT5C6405C-55L | 620 |
| 5962-8685913UA | A | 10/22/1991 | 1 | AUSTIN SEMI. | | Y | MT5C6405EC-55L | 620 |
| 5962-8685913XA | A | 10/22/1991 | | (NONE) | | | P4C198L-55 (GEN) | 620 |
| 5962-8685914KA | A | 10/22/1991 | | (NONE) | 06/01/1996 | | 6198S55 (GEN) | 620 |
| 5962-8685914LA | A | 10/22/1991 | 1 | AUSTIN SEMI. | | Y | MT5C6405C-55 | 620 |
| 5962-8685914UA | A | 10/22/1991 | 1 | AUSTIN SEMI. | | Y | MT5C6405EC-55 | 620 |
| 5962-8685914XA | A | 10/22/1991 | | (NONE) | | | P4C198-55 (GEN) | 620 |
| 5962-8685915KA | A | 10/22/1991 | | (NONE) | 06/01/1996 | | 6198L45 (GEN) | 620 |
| 5962-8685915LA | A | 10/22/1991 | 1 | AUSTIN SEMI. | | Y | MT5C6405C-45L | 620 |
| 5962-8685915UA | A | 10/22/1991 | 1 | AUSTIN SEMI. | | Y | MT5C6405EC-45L | 620 |
| 5962-8685915XA | A | 10/22/1991 | | (NONE) | | | P4C198L-45 (GEN) | 620 |
| 5962-8685916KA | A | 10/22/1991 | | (NONE) | 06/01/1996 | | 6198S45 (GEN) | 620 |
| 5962-8685916LA | A | 10/22/1991 | 1 | AUSTIN SEMI. | | Y | MT5C6405C-45 | 620 |
| 5962-8685916UA | A | 10/22/1991 | 1 | AUSTIN SEMI. | | Y | MT5C6405EC-45 | 620 |
| 5962-8685916XA | A | 10/22/1991 | | (NONE) | | | P4C198-45 (GEN) | 620 |
| 5962-8685917KA | A | 10/22/1991 | | (NONE) | 06/01/1996 | | 6198L35 (GEN) | 620 |
| 5962-8685917LA | A | 10/22/1991 | 1 | AUSTIN SEMI. | | Y | MT5C6405C-35L | 620 |
| 5962-8685917LA | A | 10/22/1991 | 1 | PYRAMID | | | P4C198L-35CMB | 620 |
| 5962-8685917UA | A | 10/22/1991 | 1 | AUSTIN SEMI. | | Y | MT5C6405EC-35L | 620 |
| 5962-8685917UA | A | 10/22/1991 | 1 | PYRAMID | | | P4C198L-35LMB | 620 |
| 5962-8685917XA | A | 10/22/1991 | 1 | PYRAMID | | | P4C198L-35LMB | 620 |
| 5962-8685918KA | A | 10/22/1991 | | (NONE) | 06/01/1996 | | 6198S35 (GEN) | 620 |
| 5962-8685918LA | A | 10/22/1991 | 1 | AUSTIN SEMI. | | Y | MT5C6405C-35 | 620 |
| 5962-8685918LA | A | 10/22/1991 | 1 | PYRAMID | | | P4C198-35CMB | 620 |
| 5962-8685918UA | A | 10/22/1991 | 1 | AUSTIN SEMI. | | Y | MT5C6405EC-35 | 620 |
| 5962-8685918UA | A | 10/22/1991 | 1 | PYRAMID | | | P4C198-35LMB | 620 |
| 5962-8685918XA | A | 10/22/1991 | 1 | PYRAMID | | | P4C198-35LMB | 620 |
| 5962-8685919KA | A | 10/22/1991 | | (NONE) | 01/01/1999 | | 7188L55 (GEN) | 620 |
| 5962-8685919TA | A | 10/22/1991 | 1 | AUSTIN SEMI. | | Y | MT5C6404C-55L | 620 |
| 5962-8685919WA | A | 10/22/1991 | | (NONE) | | | 1621-55 (GEN) | 620 |
| 5962-8685919YA | A | 10/22/1991 | | IDT | | Y | IDT7188L55DB | 620 |
| 5962-8685919ZA | A | 10/22/1991 | | (NONE) | | | P4C188L-55 (GEN) | 620 |
| 5962-8685920KA | A | 10/22/1991 | | (NONE) | 01/01/1999 | | 7188S55 (GEN) | 620 |
| 5962-8685920TA | A | 10/22/1991 | 1 | AUSTIN SEMI. | | Y | MT5C6404C-55 | 620 |
| 5962-8685920WA | A | 10/22/1991 | | (NONE) | | | 1620-55 (GEN) | 620 |
| 5962-8685920YA | A | 10/22/1991 | | IDT | | Y | IDT7188S55DB | 620 |
| 5962-8685920ZA | A | 10/22/1991 | | (NONE) | | | P4C188-55 (GEN) | 620 |
| 5962-8685921KA | A | 10/22/1991 | | (NONE) | | | 7C164L-45 (GEN) | 620 |
| 5962-8685921TA | A | 10/22/1991 | 1 | AUSTIN SEMI. | | Y | MT5C6404C-45L | 620 |
| 5962-8685921WA | A | 10/22/1991 | | (NONE) | | | 1621-45 (GEN) | 620 |
| 5962-8685921YA | A | 10/22/1991 | | IDT | | Y | IDT7188L45DB | 620 |
| 5962-8685921ZA | A | 10/22/1991 | | (NONE) | | | P4C188L-45 (GEN) | 620 |
| 5962-8685922KA | A | 10/22/1991 | | (NONE) | | | 7C164-45 (GEN) | 620 |
| 5962-8685922TA | A | 10/22/1991 | 1 | AUSTIN SEMI. | | Y | MT5C6404C-45 | 620 |
| 5962-8685922WA | A | 10/22/1991 | | (NONE) | | | 1620-45 (GEN) | 620 |
| 5962-8685922YA | A | 10/22/1991 | | IDT | | Y | IDT7188S45DB | 620 |
| 5962-8685922ZA | A | 10/22/1991 | | (NONE) | | | P4C188-45 (GEN) | 620 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-8685923KA | A | 10/22/1991 | | (NONE) | | | 7C164L-35 (GEN) | 620 |
| 5962-8685923TA | A | 10/22/1991 | 1 | AUSTIN SEMI. | | Y | MT5C6404C-35L | 620 |
| 5962-8685923TA | A | 10/22/1991 | 1 | PYRAMID | | | P4C188L-35CMB | 620 |
| 5962-8685923WA | A | 10/22/1991 | | (NONE) | | | 1621-35 (GEN) | 620 |
| 5962-8685923YA | A | 10/22/1991 | | IDT | | Y | IDT7188L35DB | 620 |
| 5962-8685923ZA | A | 10/22/1991 | 1 | PYRAMID | | | P4C188L-35LMB | 620 |
| 5962-8685924KA | A | 10/22/1991 | | (NONE) | | | 7C164-35 (GEN) | 620 |
| 5962-8685924TA | A | 10/22/1991 | 1 | AUSTIN SEMI. | | Y | MT5C6404C-35 | 620 |
| 5962-8685924TA | A | 10/22/1991 | 1 | PYRAMID | | | P4C188-35CMB | 620 |
| 5962-8685924WA | A | 10/22/1991 | | (NONE) | | | 1620-35 (GEN) | 620 |
| 5962-8685924YA | A | 10/22/1991 | | IDT | | Y | IDT7188S35DB | 620 |
| 5962-8685924ZA | A | 10/22/1991 | 1 | PYRAMID | | | P4C188-35LMB | 620 |
| 5962-86860012A | B | 01/27/2004 | 1 | INTERSIL | | Y | HA4-4902/883 | 776 |
| 5962-8686001EA | B | 01/27/2004 | 1 | INTERSIL | | Y | HA1-4902/883 | 776 |
| 5962-8686101PA | E | 06/20/2002 | 3 | MICROSEMI | | Y | SG1503Y/883B | 785 |
| 5962-8686101XA | E | 06/20/2002 | 3 | ANALOG (2) | | Y | AD580SH/883B | 785 |
| 5962-8686101XC | E | 06/20/2002 | 1 | MAXIM INTEG. | | | MX580SH/883B | 785 |
| 5962-8686101YA | E | 06/20/2002 | 3 | MICROSEMI | | Y | SG1503T/883B | 785 |
| 5962-8686102PA | E | 06/20/2002 | | (NONE) | | | 1503A (GEN) | 785 |
| 5962-8686102XA | E | 06/20/2002 | 3 | ANALOG (2) | | Y | AD580TH/883B | 785 |
| 5962-8686102XC | E | 06/20/2002 | 1 | MAXIM INTEG. | | | MX580TH/883B | 785 |
| 5962-8686103XA | E | 06/20/2002 | 3 | ANALOG (2) | | Y | AD580UH/883B | 785 |
| 5962-8686103XC | E | 06/20/2002 | 1 | MAXIM INTEG. | | | MX580UH/883B | 785 |
| 5962-86862012A | B | 11/28/1989 | | (NONE) | 04/27/1998 | | 54FCT299 (GEN) | 228 |
| 5962-8686201RA | B | 11/28/1989 | | (NONE) | 04/27/1998 | | 54FCT299 (GEN) | 228 |
| 5962-8686201SA | B | 11/28/1989 | | (NONE) | 04/27/1998 | | 54FCT299 (GEN) | 228 |
| 5962-86862022A | B | 11/28/1989 | | (NONE) | 04/27/1998 | | 54FCT299A (GEN) | 228 |
| 5962-8686202RA | B | 11/28/1989 | | (NONE) | 04/27/1998 | | 54FCT299A (GEN) | 228 |
| 5962-8686202SA | B | 11/28/1989 | | (NONE) | 04/27/1998 | | 54FCT299A (GEN) | 228 |
| 5962-8686301XA | | 01/26/1987 | | (NONE) | 06/30/1994 | | 29116 (GEN) | 403 |
| 5962-8686401LA | | 08/26/1988 | | (NONE) | 10/31/1996 | | 600 (GEN) | 431 |
| 5962-8686401XA | | 08/26/1988 | | (NONE) | 07/30/1993 | | 600 (GEN) | 431 |
| 5962-86865012A | C | 03/24/1995 | 2 | TI | | Y | SNJ54ALS10AFK | 102 |
| 5962-8686501CA | C | 03/24/1995 | 2 | TI | | Y | SNJ54ALS10AJ | 102 |
| 5962-8686501DA | C | 03/24/1995 | 2 | TI | | Y | SNJ54ALS10AW | 102 |
| 5962-86866012A | B | 07/10/1992 | I | TI | | Y | SNJ54ALS138AFK | 282 |
| 5962-8686601FA | B | 07/10/1992 | 2 | TI | | Y | SNJ54ALS138AW | 282 |
| 5962-86867012A | D | 09/11/2003 | 3 | TI | | Y | SNJ54HCT373FK | 341 |
| 5962-8686701RA | D | 09/11/2003 | 3 | TI | | Y | SNJ54HCT373J | 341 |
| 5962-8686701VRA | D | 09/11/2003 | 3 | TI | | Y | SNV54HCT373J | 341 |
| 5962-8686701SA | D | 09/11/2003 | | (NONE) | | | 54HCT373 (GEN) | 341 |
| 5962-8686701VSA | D | 09/11/2003 | 3 | TI | | Y | SNV54HCT373W | 341 |
| 5962-86868013A | A | 12/24/1988 | 1 | LANSDALE | | Y | IL8286/B3A | 590 |
| 5962-86868013C | A | 12/24/1988 | 1 | LANSDALE | | Y | IL8286/B3C | 590 |
| 5962-8686801RA | A | 12/24/1988 | 1 | LANSDALE | | Y | IL8286/BRA | 590 |
| 5962-86868023A | A | 12/24/1988 | 1 | LANSDALE | | Y | IL8287/B3A | 590 |
| 5962-8686802RA | A | 12/24/1988 | 1 | LANSDALE | | Y | IL8287/BRX | 590 |
| 5962-86869012A | B | 07/06/1992 | 2 | TI | | Y | SNJ54ALS157AFK | 275 |
| 5962-8686901EA | B | 07/06/1992 | 2 | TI | | Y | SNJ54ALS157AJ | 275 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-8686901FA | B | 07/06/1992 | 2 | TI | | Y | SNJ54ALS157AW | 275 |
| 5962-86870012A | | 09/17/1987 | | (NONE) | | | 54ALS164 (GEN) | 226 |
| 5962-8687001DA | | 09/17/1987 | | (NONE) | | | 54ALS164 (GEN) | 226 |
| 5962-86871012A | C | 07/06/1992 | 1 | TI | | Y | SNJ54ALS38BFK | 510 |
| 5962-8687101BA | C | 07/06/1992 | | (NONE) | | | 54ALS38B (GEN) | 510 |
| 5962-8687101CA | C | 07/06/1992 | 1 | TI | | Y | SNJ54ALS38BJ | 510 |
| 5962-8687101DA | C | 07/06/1992 | 1 | TI | | Y | SNJ54ALS38BW | 510 |
| 5962-86872012A | A | 03/03/1988 | | (NONE) | 06/01/1997 | | 54F38 (GEN) | 510 |
| 5962-8687201CA | A | 03/03/1988 | | (NONE) | 06/01/1997 | | 54F38 (GEN) | 510 |
| 5962-8687201DA | A | 03/03/1988 | | (NONE) | 06/01/1997 | | 54F38 (GEN) | 510 |
| 5962-8687301UA | B | 09/17/1993 | | (NONE) | 08/21/1995 | | 7216L40 (GEN) | 208 |
| 5962-8687301VA | B | 09/17/1993 | | (NONE) | 04/01/2000 | | 7216L40 (GEN) | 208 |
| 5962-8687301VC | B | 09/17/1993 | | (NONE) | 04/01/2000 | | 7216L40 (GEN) | 208 |
| 5962-8687301XA | B | 09/17/1993 | | (NONE) | 04/01/2000 | | 7216L40 (GEN) | 208 |
| 5962-8687301XC | B | 09/17/1993 | | (NONE) | 04/01/2000 | | 7216L40 (GEN) | 208 |
| 5962-8687301YA | B | 09/17/1993 | | (NONE) | 04/01/2000 | | 7216L40 (GEN) | 208 |
| 5962-8687301YC | B | 09/17/1993 | | (NONE) | 04/01/2000 | | 7216L40 (GEN) | 208 |
| 5962-8687301ZA | B | 09/17/1993 | | (NONE) | 08/05/1996 | | 7216L40 (GEN) | 208 |
| 5962-8687302UA | B | 09/17/1993 | | (NONE) | 08/21/1995 | | 7216L55 (GEN) | 208 |
| 5962-8687302VA | B | 09/17/1993 | | (NONE) | 04/01/2000 | | 7216L55 (GEN) | 208 |
| 5962-8687302VC | B | 09/17/1993 | | (NONE) | 04/01/2000 | | 7216L55 (GEN) | 208 |
| 5962-8687302XA | B | 09/17/1993 | | (NONE) | 04/01/2000 | | 7216L55 (GEN) | 208 |
| 5962-8687302XC | B | 09/17/1993 | | (NONE) | 04/01/2000 | | 7216L55 (GEN) | 208 |
| 5962-8687302YA | B | 09/17/1993 | | (NONE) | 04/01/2000 | | 7216L55 (GEN) | 208 |
| 5962-8687302YC | B | 09/17/1993 | | (NONE) | 04/01/2000 | | 7216L55 (GEN) | 208 |
| 5962-8687302ZA | B | 09/17/1993 | | (NONE) | 08/05/1996 | | 7216L55 (GEN) | 208 |
| 5962-8687303UA | B | 09/17/1993 | | (NONE) | 08/21/1995 | | 7216L75 (GEN) | 208 |
| 5962-8687303VA | B | 09/17/1993 | | (NONE) | 04/01/2000 | | 7216L75 (GEN) | 208 |
| 5962-8687303VC | B | 09/17/1993 | | (NONE) | 04/01/2000 | | 7216L75 (GEN) | 208 |
| 5962-8687303XA | B | 09/17/1993 | | (NONE) | 04/01/2000 | | 7216L75 (GEN) | 208 |
| 5962-8687303XC | B | 09/17/1993 | | (NONE) | 04/01/2000 | | 7216L75 (GEN) | 208 |
| 5962-8687303YA | B | 09/17/1993 | | (NONE) | 04/01/2000 | | 7216L75 (GEN) | 208 |
| 5962-8687303YC | B | 09/17/1993 | | (NONE) | 04/01/2000 | | 7216L75 (GEN) | 208 |
| 5962-8687303ZA | B | 09/17/1993 | | (NONE) | | | 7216L75 (GEN) | 208 |
| 5962-8687304UA | B | 09/17/1993 | | (NONE) | 08/21/1995 | | 7216L30 (GEN) | 208 |
| 5962-8687304VA | B | 09/17/1993 | | (NONE) | 04/01/2000 | | 7216L30 (GEN) | 208 |
| 5962-8687304VC | B | 09/17/1993 | | (NONE) | 04/01/2000 | | 7216L30 (GEN) | 208 |
| 5962-8687304XA | B | 09/17/1993 | | (NONE) | 04/01/2000 | | 7216L30 (GEN) | 208 |
| 5962-8687304XC | B | 09/17/1993 | | (NONE) | 04/01/2000 | | 7216L30 (GEN) | 208 |
| 5962-8687304YA | B | 09/17/1993 | | (NONE) | 04/01/2000 | | 7216L30 (GEN) | 208 |
| 5962-8687304YC | B | 09/17/1993 | | (NONE) | 04/01/2000 | | 7216L30 (GEN) | 208 |
| 5962-8687304ZA | B | 09/17/1993 | | (NONE) | 08/05/1996 | | 7216L30 (GEN) | 208 |
| 5962-8687305UA | B | 09/17/1993 | | (NONE) | 08/21/1995 | | 7216L25 (GEN) | 208 |
| 5962-8687305VA | B | 09/17/1993 | | (NONE) | 04/01/2000 | | 7216L25 (GEN) | 208 |
| 5962-8687305VC | B | 09/17/1993 | | (NONE) | 04/01/2000 | | 7216L25 (GEN) | 208 |
| 5962-8687305XA | B | 09/17/1993 | | (NONE) | 04/01/2000 | | 7216L25 (GEN) | 208 |
| 5962-8687305XC | B | 09/17/1993 | | (NONE) | 04/01/2000 | | 7216L25 (GEN) | 208 |
| 5962-8687305YA | B | 09/17/1993 | | (NONE) | 04/01/2000 | | 7216L25 (GEN) | 208 |
| 5962-8687305YC | B | 09/17/1993 | | (NONE) | 04/01/2000 | | 7216L25 (GEN) | 208 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-8687305ZA | B | 09/17/1993 | | (NONE) | 08/05/1996 | | 7216L25 (GEN) | 208 |
| 5962-8687306UA | B | 09/17/1993 | | (NONE) | 08/21/1995 | | 7216L20 (GEN) | 208 |
| 5962-8687306ZA | B | 09/17/1993 | | (NONE) | 08/05/1996 | | 7216L20 (GEN) | 208 |
| 5962-86874012A | B | 07/30/1997 | 2 | TI | | Y | SNJ54F241FK | 529 |
| 5962-8687401RA | B | 07/30/1997 | 2 | TI | | Y | SNJ54F241J | 529 |
| 5962-8687401SA | B | 07/30/1997 | 2 | TI | | Y | SNJ54F241W | 529 |
| 5962-8687501UA | C | 04/28/1993 | 1 | IDT | | Y | IDT7130SA90FB | 614 |
| 5962-8687501UA | C | 04/28/1993 | 2 | QP SEMI | | Y | CY7C130-90FMB | 614 |
| 5962-8687501XA | C | 04/28/1993 | 1 | IDT | | Y | IDT7130SA90CB | 614 |
| 5962-8687501XA | C | 04/28/1993 | 2 | QP SEMI | | Y | CY7C130-90DMB | 614 |
| 5962-8687501YA | C | 04/28/1993 | 1 | IDT | | Y | IDT7130SA90L48B | 614 |
| 5962-8687501YA | C | 04/28/1993 | 2 | QP SEMI | | Y | CY7C130-90LMB | 614 |
| 5962-8687501ZA | C | 04/28/1993 | 2 | QP SEMI | | Y | CY7C131-90LMB | 614 |
| 5962-8687502UA | C | 04/28/1993 | 1 | IDT | | Y | IDT7130SA70FB | 614 |
| 5962-8687502UA | C | 04/28/1993 | 2 | QP SEMI | | Y | CY7C130-70FMB | 614 |
| 5962-8687502XA | C | 04/28/1993 | 1 | IDT | | Y | IDT7130SA70CB | 614 |
| 5962-8687502XA | C | 04/28/1993 | 2 | QP SEMI | | Y | CY7C130-70DMB | 614 |
| 5962-8687502YA | C | 04/28/1993 | 1 | IDT | | Y | IDT7130SA70L48B | 614 |
| 5962-8687502YA | C | 04/28/1993 | 2 | QP SEMI | | Y | CY7C130-70LMB | 614 |
| 5962-8687502ZA | C | 04/28/1993 | 2 | QP SEMI | | Y | CY7C131-70LMB | 614 |
| 5962-8687503UA | C | 04/28/1993 | 1 | IDT | | Y | IDT7130SA55FB | 614 |
| 5962-8687503UA | C | 04/28/1993 | 2 | QP SEMI | | Y | CY7C130-55FMB | 614 |
| 5962-8687503XA | C | 04/28/1993 | 1 | IDT | | Y | IDT7130SA55CB | 614 |
| 5962-8687503XA | C | 04/28/1993 | 2 | QP SEMI | | Y | CY7C130-55DMB | 614 |
| 5962-8687503YA | C | 04/28/1993 | 1 | IDT | | Y | IDT7130SA55L48B | 614 |
| 5962-8687503YA | C | 04/28/1993 | 2 | QP SEMI | | Y | CY7C130-55LMB | 614 |
| 5962-8687503ZA | C | 04/28/1993 | 2 | QP SEMI | | Y | CY7C131-55LMB | 614 |
| 5962-8687504UA | C | 04/28/1993 | 1 | IDT | | Y | IDT7130SA45FB | 614 |
| 5962-8687504UA | C | 04/28/1993 | 2 | QP SEMI | | Y | CY7C130-45FMB | 614 |
| 5962-8687504XA | C | 04/28/1993 | 1 | IDT | | Y | IDT7130SA45CB | 614 |
| 5962-8687504XA | C | 04/28/1993 | 2 | QP SEMI | | Y | CY7C130-45DMB | 614 |
| 5962-8687504YA | C | 04/28/1993 | 1 | IDT | | Y | IDT7130SA45L48B | 614 |
| 5962-8687504YA | C | 04/28/1993 | 2 | QP SEMI | | Y | CY7C130-45LMB | 614 |
| 5962-8687504ZA | C | 04/28/1993 | 2 | QP SEMI | | Y | CY7C131-45LMB | 614 |
| 5962-8687505UA | C | 04/28/1993 | 1 | IDT | | Y | IDT7130LA90FB | 614 |
| 5962-8687505XA | C | 04/28/1993 | 1 | IDT | | Y | IDT7130LA90CB | 614 |
| 5962-8687505YA | C | 04/28/1993 | 1 | IDT | | Y | IDT7130LA90L48B | 614 |
| 5962-8687505ZA | C | 04/28/1993 | | (NONE) | | | 7130-90 (GEN) | 614 |
| 5962-8687506UA | C | 04/28/1993 | 1 | IDT | | Y | IDT7130LA70FB | 614 |
| 5962-8687506XA | C | 04/28/1993 | 1 | IDT | | Y | IDT7130LA70CB | 614 |
| 5962-8687506YA | C | 04/28/1993 | 1 | IDT | | Y | IDT7130LA70L48B | 614 |
| 5962-8687506ZA | C | 04/28/1993 | | (NONE) | | | 7130-70 (GEN) | 614 |
| 5962-8687507UA | C | 04/28/1993 | 1 | IDT | | Y | IDT7130LA55FB | 614 |
| 5962-8687507XA | C | 04/28/1993 | 1 | IDT | | Y | IDT7130LA55CB | 614 |
| 5962-8687507YA | C | 04/28/1993 | 1 | IDT | | Y | IDT7130LA55L48B | 614 |
| 5962-8687507ZA | C | 04/28/1993 | | (NONE) | | | 7130-55 (GEN) | 614 |
| 5962-8687508UA | C | 04/28/1993 | 1 | IDT | | Y | IDT7130LA45FB | 614 |
| 5962-8687508XA | C | 04/28/1993 | 1 | IDT | | Y | IDT7130LA45CB | 614 |
| 5962-8687508YA | C | 04/28/1993 | 1 | IDT | | Y | IDT7130LA45L48B | 614 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-8687508ZA | C | 04/28/1993 | | (NONE) | | | 7130-45 (GEN) | 614 |
| 5962-8687509UA | C | 04/28/1993 | 1 | IDT | | Y | IDT7140SA90FB | 614 |
| 5962-8687509XA | C | 04/28/1993 | 1 | IDT | | Y | IDT7140SA90CB | 614 |
| 5962-8687509YA | C | 04/28/1993 | 1 | IDT | | Y | IDT7140SA90L48B | 614 |
| 5962-8687509ZA | C | 04/28/1993 | | (NONE) | | | 7140-90 (GEN) | 614 |
| 5962-8687510UA | C | 04/28/1993 | 1 | IDT | | Y | IDT7140SA70FB | 614 |
| 5962-8687510XA | C | 04/28/1993 | 1 | IDT | | Y | IDT7140SA70CB | 614 |
| 5962-8687510YA | C | 04/28/1993 | 1 | IDT | | Y | IDT7140SA70L48B | 614 |
| 5962-8687510ZA | C | 04/28/1993 | | (NONE) | | | 7140-70 (GEN) | 614 |
| 5962-8687511UA | C | 04/28/1993 | 1 | IDT | | Y | IDT7140SA55FB | 614 |
| 5962-8687511XA | C | 04/28/1993 | 1 | IDT | | Y | IDT7140SA55CB | 614 |
| 5962-8687511YA | C | 04/28/1993 | 1 | IDT | | Y | IDT7140SA55L48B | 614 |
| 5962-8687511ZA | C | 04/28/1993 | | (NONE) | 05/31/1998 | | 7C141-55 (GEN) | 614 |
| 5962-8687512UA | C | 04/28/1993 | 1 | IDT | | Y | IDT7140SA45FB | 614 |
| 5962-8687512XA | C | 04/28/1993 | 1 | IDT | | Y | IDT7140SA45CB | 614 |
| 5962-8687512YA | C | 04/28/1993 | 1 | IDT | | Y | IDT7140SA45L48B | 614 |
| 5962-8687512ZA | C | 04/28/1993 | | (NONE) | | | 7C141-45 (GEN) | 614 |
| 5962-8687513UA | C | 04/28/1993 | 1 | IDT | | Y | IDT7140LA90FB | 614 |
| 5962-8687513XA | C | 04/28/1993 | 1 | IDT | | Y | IDT7140LA90CB | 614 |
| 5962-8687513YA | C | 04/28/1993 | 1 | IDT | | Y | IDT7140LA90L48B | 614 |
| 5962-8687513ZA | C | 04/28/1993 | | (NONE) | | | 7140-90 (GEN) | 614 |
| 5962-8687514UA | C | 04/28/1993 | 1 | IDT | | Y | IDT7140LA70FB | 614 |
| 5962-8687514XA | C | 04/28/1993 | 1 | IDT | | Y | IDT7140LA70CB | 614 |
| 5962-8687514YA | C | 04/28/1993 | 1 | IDT | | Y | IDT7140LA70L48B | 614 |
| 5962-8687514ZA | C | 04/28/1993 | | (NONE) | | | 7140-70 (GEN) | 614 |
| 5962-8687515UA | C | 04/28/1993 | 1 | IDT | | Y | IDT7140LA55FB | 614 |
| 5962-8687515XA | C | 04/28/1993 | 1 | IDT | | Y | IDT7140LA55CB | 614 |
| 5962-8687515YA | C | 04/28/1993 | 1 | IDT | | Y | IDT7140LA55L48B | 614 |
| 5962-8687515ZA | C | 04/28/1993 | | (NONE) | | | 7140-55 (GEN) | 614 |
| 5962-8687516UA | C | 04/28/1993 | 1 | IDT | | Y | IDT7140LA45FB | 614 |
| 5962-8687516XA | C | 04/28/1993 | 1 | IDT | | Y | IDT7140LA45CB | 614 |
| 5962-8687516YA | C | 04/28/1993 | 1 | IDT | | Y | IDT7140LA45L48B | 614 |
| 5962-8687516ZA | C | 04/28/1993 | | (NONE) | | | 7140-45 (GEN) | 614 |
| 5962-8687517UA | C | 04/28/1993 | | (NONE) | | | 7130-35 (GEN) | 614 |
| 5962-8687517XA | C | 04/28/1993 | | (NONE) | | | 7130-35 (GEN) | 614 |
| 5962-8687517YA | C | 04/28/1993 | | (NONE) | | | 7130-35 (GEN) | 614 |
| 5962-8687517ZA | C | 04/28/1993 | | (NONE) | | | 7131-35 (GEN) | 614 |
| 5962-8687518UA | C | 04/28/1993 | | (NONE) | | | 7140-35 (GEN) | 614 |
| 5962-8687518XA | C | 04/28/1993 | | (NONE) | | | 7140-35 (GEN) | 614 |
| 5962-8687518YA | C | 04/28/1993 | | (NONE) | | | 7140-35 (GEN) | 614 |
| 5962-8687518ZA | C | 04/28/1993 | | (NONE) | | | 7141-35 (GEN) | 614 |
| 5962-8687519UA | C | 04/28/1993 | 2 | QP SEMI | | Y | CY7C130-35FMB | 614 |
| 5962-8687519XA | C | 04/28/1993 | 2 | QP SEMI | | Y | CY7C130-35DMB | 614 |
| 5962-8687519YA | C | 04/28/1993 | 2 | QP SEMI | | Y | CY7C130-35LMB | 614 |
| 5962-8687519ZA | C | 04/28/1993 | 2 | QP SEMI | | Y | CY7C131-35LMB | 614 |
| 5962-8687520UA | C | 04/28/1993 | | (NONE) | | | 7140-35 (GEN) | 614 |
| 5962-8687520XA | C | 04/28/1993 | | (NONE) | | | 7C140-35 (GEN) | 614 |
| 5962-8687520YA | C | 04/28/1993 | | (NONE) | | | 7140-35 (GEN) | 614 |
| 5962-8687520ZA | C | 04/28/1993 | | (NONE) | 05/31/1998 | | 7141-35 (GEN) | 614 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-8687521UA | C | 04/28/1993 | 1 | IDT | | Y | IDT7130LA35FB | 614 |
| 5962-8687521XA | C | 04/28/1993 | 1 | IDT | | Y | IDT7130LA35CB | 614 |
| 5962-8687521YA | C | 04/28/1993 | 1 | IDT | | Y | IDT7130LA35L48B | 614 |
| 5962-8687521ZA | C | 04/28/1993 | | (NONE) | | | 7130-35 (GEN) | 614 |
| 5962-8687522UA | C | 04/28/1993 | 2 | IDT | | Y | IDT7140LA35FB | 614 |
| 5962-8687522XA | C | 04/28/1993 | 2 | IDT | | Y | IDT7140LA35CB | 614 |
| 5962-8687522YA | C | 04/28/1993 | 2 | IDT | | Y | IDT7140LA35L48B | 614 |
| 5962-8687522ZA | C | 04/28/1993 | | (NONE) | | | 7140-35 (GEN) | 614 |
| 5962-86876012A | A | 10/06/1987 | | (NONE) | | | 54LS668 (GEN) | 301 |
| 5962-8687601EA | A | 10/06/1987 | | (NONE) | | | 54LS668 (GEN) | 301 |
| 5962-8687601FA | A | 10/06/1987 | | (NONE) | | | 54LS668 (GEN) | 301 |
| 5962-86877012A | D | 02/22/2001 | 1 | AUSTIN SEMI. | | Y | AS111E020/883C | 770 |
| 5962-8687701Q2A | D | 02/22/2001 | 1 | NATIONAL | | Y | LM111E-SMD | 770 |
| 5962-8687701GA | D | 02/22/2001 | 1 | AUSTIN SEMI. | | Y | AS111T008/883C | 770 |
| 5962-8687701QGA | D | 02/22/2001 | 1 | NATIONAL | | Y | LM111H-SMD | 770 |
| 5962-8687701PA | D | 02/22/2001 | 1 | AUSTIN SEMI. | | Y | AS111C008/883C | 770 |
| 5962-8687701QPA | D | 02/22/2001 | 1 | NATIONAL | | Y | LM111J-8-SMD | 770 |
| 5962-8687701QZA | D | 02/22/2001 | 1 | NATIONAL | | Y | LM111WG-SMD | 770 |
| 5962-8687702GA | D | 02/22/2001 | | (NONE) | 03/30/2001 | | LT111A (GEN) | 770 |
| 5962-8687702PA | D | 02/22/2001 | | (NONE) | 03/30/2001 | | LT111A (GEN) | 770 |
| 5962-8687801CA | | 02/02/1987 | | (NONE) | | | TL514 (GEN) | 774 |
| 5962-86879013A | D | 07/08/2002 | | (NONE) | | | HI-8382 (GEN) | 569 |
| 5962-8687901EA | D | 07/08/2002 | 2 | HOLT | | | HI-8382CM-03 | 569 |
| 5962-8687901EA | D | 07/08/2002 | 1 | INTERSIL | | Y | HS1-3182/883 | 569 |
| 5962-8688001QA | C | 09/12/2003 | 1 | INTERSIL | | Y | HS1-3282/883 | 421 |
| 5962-8688001XA | C | 09/12/2003 | 1 | INTERSIL | 10/03/2004 | Y | HS4-3282/883 | 421 |
| 5962-8688002QA | C | 09/12/2003 | 2 | HOLT | | | HI-8282CM-03 | 421 |
| 5962-8688002XA | C | 09/12/2003 | | (NONE) | | | HI-8282 (GEN) | 421 |
| 5962-86881012A | A | 04/29/1992 | 1 | SARNOFF | | Y | GEM10801B2A | 205 |
| 5962-86881012C | A | 04/29/1992 | 1 | SARNOFF | | Y | GEM10801B2C | 205 |
| 5962-8688101RA | A | 04/29/1992 | 1 | SARNOFF | | Y | GEM10801BRA | 205 |
| 5962-8688101RC | A | 04/29/1992 | 1 | SARNOFF | | Y | GEM10801BRC | 205 |
| 5962-8688101SA | A | 04/29/1992 | 1 | SARNOFF | | Y | GEM10801BSA | 205 |
| 5962-8688101SC | A | 04/29/1992 | 1 | SARNOFF | | Y | GEM10801BSC | 205 |
| 5962-8688201XA | B | 06/12/2002 | 1 | ANALOG (2) | | Y | AD581SH/883B | 785 |
| 5962-8688201XA | B | 06/12/2002 | 1 | LINEAR TECH. | | Y | LH0070-0H/883 | 785 |
| 5962-8688202XA | B | 06/12/2002 | 1 | ANALOG (2) | | Y | AD581TH/883B | 785 |
| 5962-8688202XA | B | 06/12/2002 | 1 | LINEAR TECH. | | Y | LH0070-1H/883 | 785 |
| 5962-8688203XA | B | 06/12/2002 | 1 | ANALOG (2) | | Y | AD581UH/883B | 785 |
| 5962-8688203XA | B | 06/12/2002 | 1 | LINEAR TECH. | | Y | LH0070-2H/883 | 785 |
| 5962-8688301CA | A | 04/09/2003 | 1 | TI | | Y | CD54HCT08F3A | 110 |
| 5962-86884012A | A | 11/03/1987 | 1 | ROCHESTER | | Y | 54HC238/B2A | 282 |
| 5962-8688401EA | A | 11/03/1987 | 1 | TI | | Y | CD54HC238F3A | 282 |
| 5962-86885013A | D | 01/10/2002 | | (NONE) | | | 54HC646 (GEN) | 590 |
| 5962-8688501JA | D | 01/10/2002 | 1 | TI | | Y | CD54HC646F3A | 590 |
| 5962-8688501LA | D | 01/10/2002 | | (NONE) | | | 54HC646 (GEN) | 590 |
| 5962-86886012A | A | 06/12/2001 | | (NONE) | 12/01/1993 | | 54HC4538 (GEN) | 166 |
| 5962-8688601EA | A | 06/12/2001 | 1 | TI | | Y | CD54HC4538F3A | 166 |
| 5962-8688701CA | A | 07/10/1996 | 1 | MINCO | | Y | MTLOP-227AJ/883 | 710 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-8688701CC | A | 07/10/1996 | 1 | MINCO | | Y | MTLOP-227AJ/883 | 710 |
| 5962-86888012A | F | 06/25/2002 | | (NONE) | 12/31/2001 | | 55189 (GEN) | 572 |
| 5962-8688801CA | F | 06/25/2002 | | (NONE) | 12/31/2001 | | 55189 (GEN) | 572 |
| 5962-86888022A | F | 06/25/2002 | 1 | TI | | Y | SNJ55189AFK | 572 |
| 5962-8688802CA | F | 06/25/2002 | 1 | TI | | Y | SNJ55189AJ | 572 |
| 5962-8688802DA | F | 06/25/2002 | 1 | TI | | Y | SNJ55189AW | 572 |
| 5962-86889012A | C | 06/27/2002 | 1 | TI | | Y | SNJ55188FK | 569 |
| 5962-8688901CA | C | 06/27/2002 | 1 | TI | | Y | SNJ55188J | 569 |
| 5962-8688901DA | C | 06/27/2002 | 1 | TI | | Y | SNJ55188W | 569 |
| 5962-86890012A | B | 10/11/1990 | 2 | SARNOFF | | Y | GEM06301Q2A | 143 |
| 5962-86890012A | B | 10/11/1990 | 2 | TI | | Y | SNJ54HCT14FK | 143 |
| 5962-86890012C | B | 10/11/1990 | 2 | SARNOFF | | Y | GEM06301Q2C | 143 |
| 5962-8689001CA | B | 10/11/1990 | 2 | SARNOFF | | Y | GEM06301QCA | 143 |
| 5962-8689001CA | B | 10/11/1990 | 2 | TI | | Y | SNJ54HCT14J | 143 |
| 5962-8689001CC | B | 10/11/1990 | 2 | SARNOFF | | Y | GEM06301QCC | 143 |
| 5962-8689001DA | B | 10/11/1990 | 2 | SARNOFF | | Y | GEM06301QDA | 143 |
| 5962-8689001DA | B | 10/11/1990 | 2 | TI | | Y | SNJ54HCT14W | 143 |
| 5962-8689001DC | B | 10/11/1990 | 2 | SARNOFF | | Y | GEM06301QDC | 143 |
| 5962-86891012A | B | 01/25/2002 | 2 | TI | | Y | SNJ54HC191FK | 304 |
| 5962-8689101EA | B | 01/25/2002 | 2 | TI | | Y | CD54HC191F3A | 304 |
| 5962-8689101EA | B | 01/25/2002 | 2 | TI | | Y | SNJ54HC191J | 304 |
| 5962-8689101VXA | B | 01/25/2002 | 2 | STMICRO | | Y | 54HC191K02V | 304 |
| 5962-8689101VXC | B | 01/25/2002 | 2 | STMICRO | | Y | 54HC191K01V | 304 |
| 5962-8689101XA | B | 01/25/2002 | 2 | STMICRO | | Y | 54HC191K02Q | 304 |
| 5962-8689101XC | B | 01/25/2002 | 2 | STMICRO | | Y | 54HC191K01Q | 304 |
| 5962-87001012A | B | 11/26/1991 | 1 | LANSDALE | | Y | ML10H536/B2A | 319 |
| 5962-8700101EA | B | 11/26/1991 | 1 | LANSDALE | | Y | ML10H536/BEA | 319 |
| 5962-8700101FA | B | 11/26/1991 | 1 | LANSDALE | | Y | ML10H536/BFA | 319 |
| 5962-8700201TA | D | 09/06/1994 | 2 | IDT | | Y | IDT7132SA45FB | 616 |
| 5962-8700201UA | D | 09/06/1994 | 1 | IDT | | Y | IDT7132SA-45L48B | 616 |
| 5962-8700201XA | D | 09/06/1994 | | (NONE) | | | 7132SA-45 (GEN) | 616 |
| 5962-8700201YA | D | 09/06/1994 | | (NONE) | | | 7132SA-45 (GEN) | 616 |
| 5962-8700201ZA | D | 09/06/1994 | 1 | IDT | | Y | IDT7132SA-45CB | 616 |
| 5962-8700202TA | D | 09/06/1994 | 2 | IDT | | Y | IDT7132SA90FB | 616 |
| 5962-8700202UA | D | 09/06/1994 | 1 | IDT | | Y | IDT7132SA-90L48B | 616 |
| 5962-8700202XA | D | 09/06/1994 | | (NONE) | | | 7132SA-90 (GEN) | 616 |
| 5962-8700202YA | D | 09/06/1994 | | (NONE) | | | 7132SA-90 (GEN) | 616 |
| 5962-8700202ZA | D | 09/06/1994 | 1 | IDT | | Y | IDT7132SA-90CB | 616 |
| 5962-8700203TA | D | 09/06/1994 | 2 | IDT | | Y | IDT7132SA70FB | 616 |
| 5962-8700203UA | D | 09/06/1994 | 1 | IDT | | Y | IDT7132SA-70L48B | 616 |
| 5962-8700203XA | D | 09/06/1994 | | (NONE) | | | 7132SA-70 (GEN) | 616 |
| 5962-8700203YA | D | 09/06/1994 | | (NONE) | | | 7132SA-70 (GEN) | 616 |
| 5962-8700203ZA | D | 09/06/1994 | 1 | IDT | | Y | IDT7132SA-70CB | 616 |
| 5962-8700204TA | D | 09/06/1994 | 2 | IDT | | Y | IDT7132SA55FB | 616 |
| 5962-8700204UA | D | 09/06/1994 | 1 | IDT | | Y | IDT7132SA-55L48B | 616 |
| 5962-8700204XA | D | 09/06/1994 | | (NONE) | | | 7132SA-55 (GEN) | 616 |
| 5962-8700204YA | D | 09/06/1994 | | (NONE) | | | 7132SA-55 (GEN) | 616 |
| 5962-8700204ZA | D | 09/06/1994 | 1 | IDT | | Y | IDT7132SA-55CB | 616 |
| 5962-8700205TA | D | 09/06/1994 | 2 | IDT | | Y | IDT7132LA45FB | 616 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-8700205UA | D | 09/06/1994 | 1 | IDT | | Y | IDT7132LA-45L48B | 616 |
| 5962-8700205XA | D | 09/06/1994 | | (NONE) | | | 7132LA-45 (GEN) | 616 |
| 5962-8700205YA | D | 09/06/1994 | | (NONE) | | | 7132LA-45 (GEN) | 616 |
| 5962-8700205ZA | D | 09/06/1994 | 1 | IDT | | Y | IDT7132LA-45CB | 616 |
| 5962-8700206TA | D | 09/06/1994 | 2 | IDT | | Y | IDT7132LA90FB | 616 |
| 5962-8700206UA | D | 09/06/1994 | 1 | IDT | | Y | IDT7132LA-90L48B | 616 |
| 5962-8700206XA | D | 09/06/1994 | | (NONE) | | | 7132LA-90 (GEN) | 616 |
| 5962-8700206YA | D | 09/06/1994 | | (NONE) | | | 7132LA-90 (GEN) | 616 |
| 5962-8700206ZA | D | 09/06/1994 | 1 | IDT | | Y | IDT7132LA-90CB | 616 |
| 5962-8700207TA | D | 09/06/1994 | 2 | IDT | | Y | IDT7132LA70FB | 616 |
| 5962-8700207UA | D | 09/06/1994 | 1 | IDT | | Y | IDT7132LA-70L48B | 616 |
| 5962-8700207XA | D | 09/06/1994 | | (NONE) | | | 7132LA-70 (GEN) | 616 |
| 5962-8700207YA | D | 09/06/1994 | | (NONE) | | | 7132LA-70 (GEN) | 616 |
| 5962-8700207ZA | D | 09/06/1994 | 1 | IDT | | Y | IDT7132LA-70CB | 616 |
| 5962-8700208TA | D | 09/06/1994 | 2 | IDT | | Y | IDT7132LA55FB | 616 |
| 5962-8700208UA | D | 09/06/1994 | 1 | IDT | | Y | IDT7132LA-55L48B | 616 |
| 5962-8700208XA | D | 09/06/1994 | | (NONE) | | | 7132LA-55 (GEN) | 616 |
| 5962-8700208YA | D | 09/06/1994 | | (NONE) | | | 7132LA-55 (GEN) | 616 |
| 5962-8700208ZA | D | 09/06/1994 | 1 | IDT | | Y | IDT7132LA-55CB | 616 |
| 5962-8700209TA | D | 09/06/1994 | 2 | IDT | | Y | IDT7142SA45FB | 616 |
| 5962-8700209UA | D | 09/06/1994 | 1 | IDT | | Y | IDT7142SA-45L48B | 616 |
| 5962-8700209XA | D | 09/06/1994 | | (NONE) | | | 7142SA-45 (GEN) | 616 |
| 5962-8700209YA | D | 09/06/1994 | | (NONE) | | | 7142SA-45 (GEN) | 616 |
| 5962-8700209ZA | D | 09/06/1994 | 1 | IDT | | Y | IDT7142SA-45CB | 616 |
| 5962-8700210TA | D | 09/06/1994 | 2 | IDT | | Y | IDT7142SA90FB | 616 |
| 5962-8700210UA | D | 09/06/1994 | 1 | IDT | | Y | IDT7142SA-90L48B | 616 |
| 5962-8700210XA | D | 09/06/1994 | | (NONE) | | | 7142SA-90 (GEN) | 616 |
| 5962-8700210YA | D | 09/06/1994 | | (NONE) | | | 7142SA-90 (GEN) | 616 |
| 5962-8700210ZA | D | 09/06/1994 | 1 | IDT | | Y | IDT7142SA-90CB | 616 |
| 5962-8700211TA | D | 09/06/1994 | 2 | IDT | | Y | IDT7142SA70FB | 616 |
| 5962-8700211UA | D | 09/06/1994 | 1 | IDT | | Y | IDT7142SA-70L48B | 616 |
| 5962-8700211XA | D | 09/06/1994 | | (NONE) | | | 7142SA-70 (GEN) | 616 |
| 5962-8700211YA | D | 09/06/1994 | | (NONE) | | | 7142SA-70 (GEN) | 616 |
| 5962-8700211ZA | D | 09/06/1994 | 1 | IDT | | Y | IDT7142SA-70CB | 616 |
| 5962-8700212TA | D | 09/06/1994 | 2 | IDT | | Y | IDT7142SA55FB | 616 |
| 5962-8700212UA | D | 09/06/1994 | 1 | IDT | | Y | IDT7142SA-55L48B | 616 |
| 5962-8700212XA | D | 09/06/1994 | | (NONE) | | | 7142SA-55 (GEN) | 616 |
| 5962-8700212YA | D | 09/06/1994 | | (NONE) | | | 7142SA-55 (GEN) | 616 |
| 5962-8700212ZA | D | 09/06/1994 | 1 | IDT | | Y | IDT7142SA-55CB | 616 |
| 5962-8700213TA | D | 09/06/1994 | 2 | IDT | | Y | IDT7142LA45FB | 616 |
| 5962-8700213UA | D | 09/06/1994 | 1 | IDT | | Y | IDT7142LA-45L48B | 616 |
| 5962-8700213XA | D | 09/06/1994 | | (NONE) | | | 7142LA-45 (GEN) | 616 |
| 5962-8700213YA | D | 09/06/1994 | | (NONE) | | | 7142LA-45 (GEN) | 616 |
| 5962-8700213ZA | D | 09/06/1994 | 1 | IDT | | Y | IDT7142LA-45CB | 616 |
| 5962-8700214TA | D | 09/06/1994 | 2 | IDT | | Y | IDT7142LA90FB | 616 |
| 5962-8700214UA | D | 09/06/1994 | 1 | IDT | | Y | IDT7142LA-90L48B | 616 |
| 5962-8700214XA | D | 09/06/1994 | | (NONE) | | | 7142LA-90 (GEN) | 616 |
| 5962-8700214YA | D | 09/06/1994 | | (NONE) | | | 7142LA-90 (GEN) | 616 |
| 5962-8700214ZA | D | 09/06/1994 | 1 | IDT | | Y | IDT7142LA-90CB | 616 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-8700215TA | D | 09/06/1994 | 2 | IDT | | Y | IDT7142LA70FB | 616 |
| 5962-8700215UA | D | 09/06/1994 | 1 | IDT | | Y | IDT7142LA-70L48B | 616 |
| 5962-8700215XA | D | 09/06/1994 | | (NONE) | | | 7142LA-70 (GEN) | 616 |
| 5962-8700215YA | D | 09/06/1994 | | (NONE) | | | 7142LA-70 (GEN) | 616 |
| 5962-8700215ZA | D | 09/06/1994 | 1 | IDT | | Y | IDT7142LA-70CB | 616 |
| 5962-8700216TA | D | 09/06/1994 | 2 | IDT | | Y | IDT7142LA55FB | 616 |
| 5962-8700216UA | D | 09/06/1994 | 1 | IDT | | Y | IDT7142LA-55L48B | 616 |
| 5962-8700216XA | D | 09/06/1994 | | (NONE) | | | 7142LA-55 (GEN) | 616 |
| 5962-8700216YA | D | 09/06/1994 | | (NONE) | | | 7142LA-55 (GEN) | 616 |
| 5962-8700216ZA | D | 09/06/1994 | 1 | IDT | | Y | IDT7142LA-55CB | 616 |
| 5962-8700217TA | D | 09/06/1994 | 2 | IDT | | Y | IDT7132SA35FB | 616 |
| 5962-8700217UA | D | 09/06/1994 | 2 | IDT | | Y | IDT7132SA35L48B | 616 |
| 5962-8700217ZA | D | 09/06/1994 | 2 | IDT | | Y | IDT7132SA35CB | 616 |
| 5962-8700218TA | D | 09/06/1994 | 2 | IDT | | Y | IDT7132LA35FB | 616 |
| 5962-8700218UA | D | 09/06/1994 | 2 | IDT | | Y | IDT7132LA35L48B | 616 |
| 5962-8700218ZA | D | 09/06/1994 | 2 | IDT | | Y | IDT7132LA35CB | 616 |
| 5962-8700219TA | D | 09/06/1994 | 2 | IDT | | Y | IDT7132SA25FB | 616 |
| 5962-8700219UA | D | 09/06/1994 | 2 | IDT | | Y | IDT7132SA25L48B | 616 |
| 5962-8700219ZA | D | 09/06/1994 | | (NONE) | | | 7132S25 (GEN) | 616 |
| 5962-8700220TA | D | 09/06/1994 | 2 | IDT | | Y | IDT7132LA25FB | 616 |
| 5962-8700220UA | D | 09/06/1994 | 2 | IDT | | Y | IDT7132LA25L48B | 616 |
| 5962-8700220ZA | D | 09/06/1994 | | (NONE) | | | 7132L25 (GEN) | 616 |
| 5962-8700221TA | D | 09/06/1994 | 2 | IDT | | Y | IDT7142SA35FB | 616 |
| 5962-8700221UA | D | 09/06/1994 | 2 | IDT | | Y | IDT7142SA35L48B | 616 |
| 5962-8700221ZA | D | 09/06/1994 | 2 | IDT | | Y | IDT7142SA35CB | 616 |
| 5962-8700222TA | D | 09/06/1994 | 2 | IDT | | Y | IDT7142LA35FB | 616 |
| 5962-8700222UA | D | 09/06/1994 | 2 | IDT | | Y | IDT7142LA35L48B | 616 |
| 5962-8700222ZA | D | 09/06/1994 | 2 | IDT | | Y | IDT7142LA35CB | 616 |
| 5962-8700223TA | D | 09/06/1994 | 2 | IDT | | Y | IDT7142SA25FB | 616 |
| 5962-8700223UA | D | 09/06/1994 | 2 | IDT | | Y | IDT7142SA25L48B | 616 |
| 5962-8700223ZA | D | 09/06/1994 | | (NONE) | | | 7142S25 (GEN) | 616 |
| 5962-8700224TA | D | 09/06/1994 | 2 | IDT | | Y | IDT7142LA25FB | 616 |
| 5962-8700224UA | D | 09/06/1994 | 2 | IDT | | Y | IDT7142LA25L48B | 616 |
| 5962-8700224ZA | D | 09/06/1994 | | (NONE) | | | 7142L25 (GEN) | 616 |
| 5962-8700301CA | A | 07/10/1996 | | (NONE) | 06/01/1997 | | 567 (GEN) | 806 |
| 5962-8700301PA | A | 07/10/1996 | | (NONE) | 09/01/1997 | | 567 (GEN) | 806 |
| 5962-87501012A | D | 08/10/1998 | 1 | AUSTIN SEMI. | | Y | AS10H515EC20/883C | 575 |
| 5962-87501012A | D | 08/10/1998 | 1 | MINCO | | Y | MTL10H5152A | 575 |
| 5962-8750101EA | D | 08/10/1998 | 1 | AUSTIN SEMI. | | Y | AS10H515C16/883C | 575 |
| 5962-8750101EA | D | 08/10/1998 | 1 | MINCO | | Y | MTL10H515EA | 575 |
| 5962-8750101FA | D | 08/10/1998 | 1 | MINCO | | Y | MTL10H515FA | 575 |
| 5962-8750101XA | D | 08/10/1998 | 1 | AUSTIN SEMI. | | Y | AS10H515F16/883C | 575 |
| 5962-87502012A | E | 08/11/1998 | 1 | AUSTIN SEMI. | | Y | AS10H516EC20/883C | 574 |
| 5962-87502012A | E | 08/11/1998 | 1 | MINCO | | Y | 10H516-2883C | 574 |
| 5962-8750201EA | E | 08/11/1998 | 1 | AUSTIN SEMI. | | Y | AS10H516C16/883C | 574 |
| 5962-8750201EA | E | 08/11/1998 | 1 | MINCO | | Y | 10H516E883C | 574 |
| 5962-8750201FA | E | 08/11/1998 | 1 | MINCO | | Y | 10H516F883C | 574 |
| 5962-8750201XA | E | 08/11/1998 | 1 | AUSTIN SEMI. | | Y | AS10H516F16/883C | 574 |
| 5962-87503012A | D | 08/11/1998 | 1 | AUSTIN SEMI. | | Y | AS10H501EC20/883C | 149 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-8750301EA | D | 08/11/1998 | 1 | AUSTIN SEMI. | | Y | AS10H501C16/883C | 149 |
| 5962-8750301FA | D | 08/11/1998 | | (NONE) | 09/30/1995 | | 10H501 (GEN) | 149 |
| 5962-8750301XA | D | 08/11/1998 | 1 | AUSTIN SEMI. | | Y | AS10H501F16/883C | 149 |
| 5962-87504012A | E | 09/12/2001 | 1 | AUSTIN SEMI. | | Y | AS10H504EC20/883C | 110 |
| 5962-8750401EA | E | 09/12/2001 | 1 | AUSTIN SEMI. | | Y | AS10H504C16/883C | 110 |
| 5962-8750401FA | E | 09/12/2001 | | (NONE) | 09/30/1995 | | 10H504 (GEN) | 110 |
| 5962-8750401XA | E | 09/12/2001 | 1 | AUSTIN SEMI. | | Y | AS10H504F16/883C | 110 |
| 5962-87505012A | B | 04/12/1993 | | (NONE) | 09/30/1995 | | 10H535 (GEN) | 153 |
| 5962-8750501EA | B | 04/12/1993 | | (NONE) | 09/30/1995 | | 10H535 (GEN) | 153 |
| 5962-8750501FA | B | 04/12/1993 | | (NONE) | 09/30/1995 | | 10H535 (GEN) | 153 |
| 5962-87506012A | A | 03/29/1993 | | (NONE) | 09/30/1995 | | 10H574 (GEN) | 273 |
| 5962-8750601EA | A | 03/29/1993 | | (NONE) | 09/30/1995 | | 10H574 (GEN) | 273 |
| 5962-8750601FA | A | 03/29/1993 | | (NONE) | 09/30/1995 | | 10H574 (GEN) | 273 |
| 5962-87507012A | B | 11/27/1991 | | (NONE) | 09/30/1995 | | 10H505 (GEN) | 149 |
| 5962-8750701EA | B | 11/27/1991 | | (NONE) | 09/30/1995 | | 10H505 (GEN) | 149 |
| 5962-8750701FA | B | 11/27/1991 | | (NONE) | 09/30/1995 | | 10H505 (GEN) | 149 |
| 5962-87508012A | D | 09/15/1998 | 1 | AUSTIN SEMI. | | Y | AS10H525EC20/883C | 547 |
| 5962-87508012A | D | 09/15/1998 | 1 | MINCO | | Y | MTL10H5252A | 547 |
| 5962-8750801EA | D | 09/15/1998 | 1 | AUSTIN SEMI. | | Y | AS10H525C16/883C | 547 |
| 5962-8750801EA | D | 09/15/1998 | 1 | MINCO | | Y | MTL10H525EA | 547 |
| 5962-8750801FA | D | 09/15/1998 | 1 | MINCO | | Y | MTL10H525FA | 547 |
| 5962-8750801XA | D | 09/15/1998 | 1 | AUSTIN SEMI. | | Y | AS10H525F16/883C | 547 |
| 5962-87509012A | B | 11/27/1991 | | (NONE) | | | 10H588 (GEN) | 143 |
| 5962-8750901EA | B | 11/27/1991 | | (NONE) | | | 10H588 (GEN) | 143 |
| 5962-8750901FA | B | 11/27/1991 | | (NONE) | | | 10H588 (GEN) | 143 |
| 5962-87510012A | A | 03/29/1993 | | (NONE) | 09/30/1995 | | 10H589 (GEN) | 143 |
| 5962-8751001EA | A | 03/29/1993 | | (NONE) | 09/30/1995 | | 10H589 (GEN) | 143 |
| 5962-8751001FA | A | 03/29/1993 | | (NONE) | 09/30/1995 | | 10H589 (GEN) | 143 |
| 5962-87511012A | A | 03/29/1993 | | (NONE) | 09/30/1995 | | 10H541 (GEN) | 222 |
| 5962-8751101EA | A | 03/29/1993 | | (NONE) | 09/30/1995 | | 10H541 (GEN) | 222 |
| 5962-8751101FA | A | 03/29/1993 | | (NONE) | 09/30/1995 | | 10H541 (GEN) | 222 |
| 5962-87512012A | C | 08/12/1998 | 1 | AUSTIN SEMI. | | Y | AS10H576EC20/883C | 159 |
| 5962-8751201EA | C | 08/12/1998 | 1 | AUSTIN SEMI. | | Y | AS10H576C16/883C | 159 |
| 5962-8751201FA | C | 08/12/1998 | | (NONE) | 09/30/1995 | | 10H576 (GEN) | 159 |
| 5962-8751201XA | C | 08/12/1998 | 1 | AUSTIN SEMI. | | Y | AS10H576F16/883C | 159 |
| 5962-8751301VA | B | 08/09/1996 | | (NONE) | | | 120325 (GEN) | 612 |
| 5962-8751301XA | B | 08/09/1996 | | (NONE) | | | 120325 (GEN) | 612 |
| 5962-8751302VA | B | 08/09/1996 | | (NONE) | 03/31/1992 | | 120335 (GEN) | 612 |
| 5962-8751302XA | B | 08/09/1996 | | (NONE) | | | 120335 (GEN) | 612 |
| 5962-8751303VA | B | 08/09/1996 | | (NONE) | | | 120345 (GEN) | 612 |
| 5962-8751303XA | B | 08/09/1996 | | (NONE) | | | 120345 (GEN) | 612 |
| 5962-8751304VA | B | 08/09/1996 | | (NONE) | | | 122325 (GEN) | 612 |
| 5962-8751304XA | B | 08/09/1996 | | (NONE) | | | 122325 (GEN) | 612 |
| 5962-8751305VA | B | 08/09/1996 | | (NONE) | | | 122325 (GEN) | 612 |
| 5962-8751305XA | B | 08/09/1996 | | (NONE) | | | 122335 (GEN) | 612 |
| 5962-8751306VA | B | 08/09/1996 | | (NONE) | | | 122345 (GEN) | 612 |
| 5962-8751306XA | B | 08/09/1996 | | (NONE) | | | 122345 (GEN) | 612 |
| 5962-8751307VA | B | 08/09/1996 | 2 | QP SEMI | | Y | CY7C148-25DMB | 612 |
| 5962-8751308VA | B | 08/09/1996 | 2 | QP SEMI | | Y | CY7C148-35DMB | 612 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-8751309VA | B | 08/09/1996 | 2 | QP SEMI | | Y | CY7C148-45DMB | 612 |
| 5962-8751310VA | B | 08/09/1996 | 3 | PYRAMID | | | P4C148-35DMB | 612 |
| 5962-8751401XA | E | 06/04/2004 | | (NONE) | 04/07/2000 | | 28C64-35 (GEN) | 660 |
| 5962-8751401YA | E | 06/04/2004 | | (NONE) | 12/15/1999 | | 28C64-35 (GEN) | 660 |
| 5962-8751401ZC | E | 06/04/2004 | | (NONE) | 12/15/1999 | | 28C64-35 (GEN) | 660 |
| 5962-8751402XA | E | 06/04/2004 | | (NONE) | 04/07/2000 | | 28C64-30 (GEN) | 660 |
| 5962-8751402YA | E | 06/04/2004 | | (NONE) | 04/07/2000 | | 28C64-30 (GEN) | 660 |
| 5962-8751402ZC | E | 06/04/2004 | | (NONE) | 01/07/2000 | | 28C64-30 (GEN) | 660 |
| 5962-8751403XA | E | 06/04/2004 | | (NONE) | 04/07/2000 | | 28C64-25 (GEN) | 660 |
| 5962-8751403YA | E | 06/04/2004 | | (NONE) | 04/07/2000 | | 28C64-25 (GEN) | 660 |
| 5962-8751403ZC | E | 06/04/2004 | | (NONE) | 04/07/2000 | | 28C64-25 (GEN) | 660 |
| 5962-8751404XA | E | 06/04/2004 | | (NONE) | 04/07/2000 | | 28C64-20 (GEN) | 660 |
| 5962-8751404YA | E | 06/04/2004 | | (NONE) | 04/07/2000 | | 28C64-20 (GEN) | 660 |
| 5962-8751404ZC | E | 06/04/2004 | | (NONE) | 01/07/2000 | | 28C64-20 (GEN) | 660 |
| 5962-8751405XA | E | 06/04/2004 | | (NONE) | 04/07/2000 | | 28C64-25 (GEN) | 660 |
| 5962-8751405YA | E | 06/04/2004 | | (NONE) | 04/07/2000 | | 28C64-25 (GEN) | 660 |
| 5962-8751405ZC | E | 06/04/2004 | | (NONE) | 01/07/2000 | | 28C64-25 (GEN) | 660 |
| 5962-8751406UA | E | 06/04/2004 | | (NONE) | | | 286435 (GEN) | 660 |
| 5962-8751406XA | E | 06/04/2004 | | (NONE) | | | 286435 (GEN) | 660 |
| 5962-8751406YA | E | 06/04/2004 | | (NONE) | | | 286435 (GEN) | 660 |
| 5962-8751407UA | E | 06/04/2004 | | (NONE) | | | 286430 (GEN) | 660 |
| 5962-8751407XA | E | 06/04/2004 | | (NONE) | | | 286430 (GEN) | 660 |
| 5962-8751407YA | E | 06/04/2004 | | (NONE) | | | 286430 (GEN) | 660 |
| 5962-8751408UA | E | 06/04/2004 | | (NONE) | | | 286425 (GEN) | 660 |
| 5962-8751408XA | E | 06/04/2004 | | (NONE) | 12/31/1999 | | 286425 (GEN) | 660 |
| 5962-8751408YA | E | 06/04/2004 | | (NONE) | | | 286425 (GEN) | 660 |
| 5962-8751409UA | E | 06/04/2004 | | (NONE) | | | 286420 (GEN) | 660 |
| 5962-8751409XA | E | 06/04/2004 | | (NONE) | 12/31/1999 | | 286420 (GEN) | 660 |
| 5962-8751409YA | E | 06/04/2004 | | (NONE) | | | 286420 (GEN) | 660 |
| 5962-8751410UA | E | 06/04/2004 | | (NONE) | | | 286412 (GEN) | 660 |
| 5962-8751410XA | E | 06/04/2004 | | (NONE) | 12/31/1999 | | 286412 (GEN) | 660 |
| 5962-8751410YA | E | 06/04/2004 | | (NONE) | | | 286412 (GEN) | 660 |
| 5962-8751411UA | E | 06/04/2004 | | (NONE) | | | 286490 (GEN) | 660 |
| 5962-8751411XA | E | 06/04/2004 | | (NONE) | 12/31/1999 | | 286490 (GEN) | 660 |
| 5962-8751411YA | E | 06/04/2004 | | (NONE) | | | 286490 (GEN) | 660 |
| 5962-8751412UA | E | 06/04/2004 | | (NONE) | | | 286470 (GEN) | 660 |
| 5962-8751412XA | E | 06/04/2004 | | (NONE) | 12/31/1999 | | 286470 (GEN) | 660 |
| 5962-8751412YA | E | 06/04/2004 | | (NONE) | | | 286470 (GEN) | 660 |
| 5962-8751413UA | E | 06/04/2004 | | (NONE) | | | 286435 (GEN) | 660 |
| 5962-8751413XA | E | 06/04/2004 | | (NONE) | 12/31/1999 | | 286435 (GEN) | 660 |
| 5962-8751413YA | E | 06/04/2004 | | (NONE) | 12/31/1999 | | 286435 (GEN) | 660 |
| 5962-8751413ZA | E | 06/04/2004 | | (NONE) | 12/31/1999 | | 286435 (GEN) | 660 |
| 5962-8751414UA | E | 06/04/2004 | | (NONE) | | | 286430 (GEN) | 660 |
| 5962-8751414XA | E | 06/04/2004 | | (NONE) | 12/31/1999 | | 286430 (GEN) | 660 |
| 5962-8751414YA | E | 06/04/2004 | | (NONE) | 12/31/1999 | | 286430 (GEN) | 660 |
| 5962-8751415UA | E | 06/04/2004 | | (NONE) | | | 286425 (GEN) | 660 |
| 5962-8751415XA | E | 06/04/2004 | | (NONE) | 12/31/1999 | | 286425 (GEN) | 660 |
| 5962-8751415YA | E | 06/04/2004 | | (NONE) | 12/31/1999 | | 286425 (GEN) | 660 |
| 5962-8751415ZA | E | 06/04/2004 | | (NONE) | 12/31/1999 | | 286425 (GEN) | 660 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-8751416UA | E | 06/04/2004 | | (NONE) | | | 286420 (GEN) | 660 |
| 5962-8751416XA | E | 06/04/2004 | | (NONE) | 12/31/1999 | | 286420 (GEN) | 660 |
| 5962-8751416YA | E | 06/04/2004 | | (NONE) | 12/31/1999 | | 286420 (GEN) | 660 |
| 5962-8751417UA | E | 06/04/2004 | | (NONE) | | | 286415 (GEN) | 660 |
| 5962-8751417XA | E | 06/04/2004 | | (NONE) | 12/31/1999 | | 286415 (GEN) | 660 |
| 5962-8751417YA | E | 06/04/2004 | | (NONE) | 12/31/1999 | | 286415 (GEN) | 660 |
| 5962-8751418UA | E | 06/04/2004 | | (NONE) | | | 286435 (GEN) | 660 |
| 5962-8751418XA | E | 06/04/2004 | | (NONE) | 12/31/1999 | | 286435 (GEN) | 660 |
| 5962-8751418YA | E | 06/04/2004 | | (NONE) | 12/31/1999 | | 286435 (GEN) | 660 |
| 5962-8751419UA | E | 06/04/2004 | | (NONE) | | | 286430 (GEN) | 660 |
| 5962-8751419XA | E | 06/04/2004 | | (NONE) | 12/31/1999 | | 286430 (GEN) | 660 |
| 5962-8751419YA | E | 06/04/2004 | | (NONE) | 12/31/1999 | | 286430 (GEN) | 660 |
| 5962-8751420UA | E | 06/04/2004 | | (NONE) | | | 286425 (GEN) | 660 |
| 5962-8751420XA | E | 06/04/2004 | | (NONE) | 12/31/1999 | | 286425 (GEN) | 660 |
| 5962-8751420YA | E | 06/04/2004 | | (NONE) | 12/31/1999 | | 286425 (GEN) | 660 |
| 5962-8751420ZA | E | 06/04/2004 | | (NONE) | 12/31/1999 | | 286425 (GEN) | 660 |
| 5962-8751421UA | E | 06/04/2004 | | (NONE) | | | 286420 (GEN) | 660 |
| 5962-8751421XA | E | 06/04/2004 | | (NONE) | 12/31/1999 | | 286420 (GEN) | 660 |
| 5962-8751421YA | E | 06/04/2004 | | (NONE) | 12/31/1999 | | 286420 (GEN) | 660 |
| 5962-8751422UA | E | 06/04/2004 | | (NONE) | | | 286415 (GEN) | 660 |
| 5962-8751422XA | E | 06/04/2004 | | (NONE) | 12/31/1999 | | 286415 (GEN) | 660 |
| 5962-8751422YA | E | 06/04/2004 | | (NONE) | 12/31/1999 | | 286415 (GEN) | 660 |
| 5962-8751423XA | E | 06/04/2004 | | (NONE) | | | 2865350 (GEN) | 660 |
| 5962-8751423YA | E | 06/04/2004 | | (NONE) | | | 2865350 (GEN) | 660 |
| 5962-8751423ZA | E | 06/04/2004 | | (NONE) | | | 2865350 (GEN) | 660 |
| 5962-8751424XA | E | 06/04/2004 | | (NONE) | | | 2865300 (GEN) | 660 |
| 5962-8751424YA | E | 06/04/2004 | | (NONE) | | | 2865300 (GEN) | 660 |
| 5962-8751424ZA | E | 06/04/2004 | | (NONE) | | | 2865300 (GEN) | 660 |
| 5962-8751425XA | E | 06/04/2004 | | (NONE) | | | 2865250 (GEN) | 660 |
| 5962-8751425YA | E | 06/04/2004 | | (NONE) | | | 2865250 (GEN) | 660 |
| 5962-8751425ZA | E | 06/04/2004 | | (NONE) | | | 2865250 (GEN) | 660 |
| 5962-8751426XA | E | 06/04/2004 | | (NONE) | | | 2865200 (GEN) | 660 |
| 5962-8751426YA | E | 06/04/2004 | | (NONE) | | | 2865200 (GEN) | 660 |
| 5962-8751426ZA | E | 06/04/2004 | | (NONE) | | | 2865200 (GEN) | 660 |
| 5962-8751427XA | E | 06/04/2004 | | (NONE) | | | 5565250 (GEN) | 660 |
| 5962-8751427YA | E | 06/04/2004 | | (NONE) | | | 5565250 (GEN) | 660 |
| 5962-8751427ZA | E | 06/04/2004 | | (NONE) | | | 5565250 (GEN) | 660 |
| 5962-8751428XA | E | 06/04/2004 | | (NONE) | 12/31/1999 | | 286420 (GEN) | 660 |
| 5962-8751428YA | E | 06/04/2004 | | (NONE) | 12/31/1999 | | 286420 (GEN) | 660 |
| 5962-87515013A | A | 01/21/1993 | 1 | QP SEMI | | | WS57C49C-45CMB | 660 |
| 5962-87515013C | A | 01/21/1993 | 1 | QP SEMI | | | WS57C49C-45CMB | 660 |
| 5962-8751501JA | A | 01/21/1993 | 1 | QP SEMI | | | WS57C49C-45DMB | 660 |
| 5962-8751501KA | A | 01/21/1993 | 1 | QP SEMI | | | WS57C49C-45FMB | 660 |
| 5962-8751501LA | A | 01/21/1993 | 1 | QP SEMI | | | WS57C49C-45TMB | 660 |
| 5962-87515023A | A | 01/21/1993 | 1 | QP SEMI | | | WS57C49C-55CMB | 660 |
| 5962-87515023C | A | 01/21/1993 | 1 | QP SEMI | | | WS57C49C-55CMB | 660 |
| 5962-8751502JA | A | 01/21/1993 | 1 | QP SEMI | | | WS57C49C-55DMB | 660 |
| 5962-8751502KA | A | 01/21/1993 | 1 | QP SEMI | | | WS57C49C-55FMB | 660 |
| 5962-8751502LA | A | 01/21/1993 | 1 | QP SEMI | | | WS57C49C-55TMB | 660 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-87515033A | A | 01/21/1993 | 1 | QP SEMI | | | WS57C49C-70CMB | 660 |
| 5962-87515033C | A | 01/21/1993 | 1 | QP SEMI | | | WS57C49C-70CMB | 660 |
| 5962-8751503JA | A | 01/21/1993 | 1 | QP SEMI | | | WS57C49C-70DMB | 660 |
| 5962-8751503KA | A | 01/21/1993 | 1 | QP SEMI | | | WS57C49C-70FMB | 660 |
| 5962-8751503LA | A | 01/21/1993 | 1 | QP SEMI | | | WS57C49C-70TMB | 660 |
| 5962-87515043A | A | 01/21/1993 | 1 | QP SEMI | | | WS57C49C-90CMB | 660 |
| 5962-87515043C | A | 01/21/1993 | 1 | QP SEMI | | | WS57C49C-90CMB | 660 |
| 5962-8751504JA | A | 01/21/1993 | 1 | QP SEMI | | | WS57C49C-90DMB | 660 |
| 5962-8751504KA | A | 01/21/1993 | 1 | QP SEMI | | | WS57C49C-90-MB | 660 |
| 5962-8751504LA | A | 01/21/1993 | 1 | QP SEMI | | | WS57C49C-90TMB | 660 |
| 5962-87515053A | A | 01/21/1993 | 1 | QP SEMI | | | WS57C49C-45CMB | 660 |
| 5962-87515053C | A | 01/21/1993 | 1 | QP SEMI | | | WS57C49C-45CMB | 660 |
| 5962-8751505JA | A | 01/21/1993 | 1 | QP SEMI | | | WS57C49C-45DMB | 660 |
| 5962-8751505KA | A | 01/21/1993 | 1 | QP SEMI | | | WS57C49C-45FMB | 660 |
| 5962-8751505LA | A | 01/21/1993 | 2 | CYPRESS | | Y | CY7C261-45WMB | 660 |
| 5962-8751505LA | A | 01/21/1993 | 1 | QP SEMI | | | WS57C49C-45TMB | 660 |
| 5962-87515063A | A | 01/21/1993 | 1 | QP SEMI | | | WS57C49C-55CMB | 660 |
| 5962-87515063C | A | 01/21/1993 | 1 | QP SEMI | | | WS57C49C-55CMB | 660 |
| 5962-8751506JA | A | 01/21/1993 | 1 | QP SEMI | | | WS57C49C-55DMB | 660 |
| 5962-8751506KA | A | 01/21/1993 | 1 | QP SEMI | | | WS57C49C-55FMB | 660 |
| 5962-8751506LA | A | 01/21/1993 | 2 | CYPRESS | | Y | CY7C261-55WMB | 660 |
| 5962-8751506LA | A | 01/21/1993 | 1 | QP SEMI | | | WS57C49C-55TMB | 660 |
| 5962-87515073A | A | 01/21/1993 | 2 | CYPRESS | | Y | CY7C261-35QMB | 660 |
| 5962-87515073A | A | 01/21/1993 | 1 | QP SEMI | | | WS57C49C-35CMB | 660 |
| 5962-87515073C | A | 01/21/1993 | 1 | QP SEMI | | | WS57C49C-35CMB | 660 |
| 5962-8751507JA | A | 01/21/1993 | 1 | QP SEMI | | | WS57C49C-35DMB | 660 |
| 5962-8751507KA | A | 01/21/1993 | 1 | QP SEMI | | | WS57C49C-35FMB | 660 |
| 5962-8751507LA | A | 01/21/1993 | 1 | QP SEMI | | | WS57C49C-35TMB | 660 |
| 5962-87515083A | A | 01/21/1993 | 1 | QP SEMI | | | WS57C49C-35CMB | 660 |
| 5962-87515083C | A | 01/21/1993 | 1 | QP SEMI | | | WS57C49C-35CMB | 660 |
| 5962-8751508JA | A | 01/21/1993 | 1 | QP SEMI | | | WS57C49C-35DMB | 660 |
| 5962-8751508KA | A | 01/21/1993 | 1 | QP SEMI | | | WS57C49C-35FMB | 660 |
| 5962-8751508LA | A | 01/21/1993 | 2 | CYPRESS | | Y | CY7C263-35WMB | 660 |
| 5962-8751508LA | A | 01/21/1993 | 1 | QP SEMI | | | WS57C49C-35TMB | 660 |
| 5962-87515093A | A | 01/21/1993 | 1 | QP SEMI | | | WS57C49C-45CMB | 660 |
| 5962-87515093C | A | 01/21/1993 | 1 | QP SEMI | | | WS57C49C-45CMB | 660 |
| 5962-8751509JA | A | 01/21/1993 | 1 | QP SEMI | | | WS57C49C-45DMB | 660 |
| 5962-8751509KA | A | 01/21/1993 | 1 | QP SEMI | | | WS57C49C-45FMB | 660 |
| 5962-8751509LA | A | 01/21/1993 | 1 | QP SEMI | | | WS57C49C-45TMB | 660 |
| 5962-87515103A | A | 01/21/1993 | 1 | QP SEMI | | | WS57C49C-55CMB | 660 |
| 5962-87515103C | A | 01/21/1993 | 1 | QP SEMI | | | WS57C49C-55CMB | 660 |
| 5962-8751510JA | A | 01/21/1993 | 1 | QP SEMI | | | WS57C49C-55DMB | 660 |
| 5962-8751510KA | A | 01/21/1993 | 1 | QP SEMI | | | WS57C49C-55FMB | 660 |
| 5962-8751510LA | A | 01/21/1993 | 1 | QP SEMI | | | WS57C49C-55TMB | 660 |
| 5962-87515113A | A | 01/21/1993 | 2 | QP SEMI | | Y | CY7C263-25QMB | 660 |
| 5962-8751511JA | A | 01/21/1993 | 2 | QP SEMI | | Y | CY7C264-25WMB | 660 |
| 5962-8751511KA | A | 01/21/1993 | 2 | QP SEMI | | Y | CY7C263-25TMB | 660 |
| 5962-8751511LA | A | 01/21/1993 | 2 | QP SEMI | | Y | CY7C263-25WMB | 660 |
| 5962-87515123A | A | 01/21/1993 | 2 | QP SEMI | | Y | CY7C261-25QMB | 660 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-8751512KA | A | 01/21/1993 | 2 | QP SEMI | | Y | CY7C261-25TMB | 660 |
| 5962-8751512LA | A | 01/21/1993 | 2 | CYPRESS | | Y | CY7C261-25WMB | 660 |
| 5962-8751601CA | C | 06/26/2002 | 1 | QP SEMI | | Y | 521/BCA | 773 |
| 5962-8751601DA | C | 06/26/2002 | 1 | QP SEMI | | Y | 521/BDA | 773 |
| 5962-8751602CA | C | 06/26/2002 | | (NONE) | 09/01/1997 | | 522 (GEN) | 773 |
| 5962-8751602DA | C | 06/26/2002 | | (NONE) | 09/01/1997 | | 522 (GEN) | 773 |
| 5962-87517012A | B | 11/29/2001 | 1 | TI | | Y | SNJ54LS590FK | 304 |
| 5962-8751701EA | B | 11/29/2001 | 1 | TI | | Y | SNJ54LS590J | 304 |
| 5962-8751701FA | B | 11/29/2001 | 1 | TI | | Y | SNJ54LS590W | 304 |
| 5962-87518013A | C | 07/14/2000 | 1 | ROCHESTER | | Y | MR8259A/B | 420 |
| 5962-8751801XA | C | 07/14/2000 | 1 | ROCHESTER | | Y | MD8259A/B | 420 |
| 5962-8751901QA | A | 09/20/1991 | | (NONE) | 10/17/1997 | | 9914A (GEN) | 420 |
| 5962-8751901XA | A | 09/20/1991 | | (NONE) | | | 9914A (GEN) | 420 |
| 5962-8752001JA | C | 10/05/2000 | | (NONE) | | | 8253 (GEN) | 424 |
| 5962-8752002JA | C | 10/05/2000 | 1 | ROCHESTER | | Y | MD8253/B | 424 |
| 5962-8752003JA | C | 10/05/2000 | | (NONE) | | | 8253-5 (GEN) | 424 |
| 5962-8752101VA | B | 07/17/2001 | | (NONE) | 09/02/2003 | | 54C922 (GEN) | 399 |
| 5962-87522012A | B | 12/06/2000 | 1 | NATIONAL | 12/01/2004 | Y | DS9622ME/883 | 573 |
| 5962-8752201AA | B | 12/06/2000 | | (NONE) | 09/09/1998 | | DS9622 (GEN) | 573 |
| 5962-8752201CA | B | 12/06/2000 | 1 | NATIONAL | 12/01/2004 | Y | DS9622MJ/883 | 573 |
| 5962-8752301PA | B | 12/06/2000 | 3 | NATIONAL | | Y | DS9636AJ/883 | 573 |
| 5962-8752401PA | B | 12/06/2000 | 2 | NATIONAL | | Y | DS9637AMJ/883 | 573 |
| 5962-87525012A | C | 07/03/2002 | | (NONE) | | | 54ACT74 (GEN) | 158 |
| 5962-8752501B2A | C | 07/03/2002 | 3 | NATIONAL | | Y | JM54ACT74B2A | 158 |
| 5962-8752501M2A | C | 07/03/2002 | 3 | NATIONAL | | Y | 54ACT74LMQB | 158 |
| 5962-8752501M2A | C | 07/03/2002 | 3 | TI | | Y | SNJ54ACT74FK | 158 |
| 5962-8752501S2A | C | 07/03/2002 | | (NONE) | | | 54ACT74 (GEN) | 158 |
| 5962R8752501B2A | C | 07/03/2002 | 3 | NATIONAL | | Y | JM54ACT74B2A-RH | 158 |
| 5962R8752501S2A | C | 07/03/2002 | 3 | NATIONAL | | Y | JM54ACT74S2A-RH | 158 |
| 5962-8752501BCA | C | 07/03/2002 | 3 | NATIONAL | | Y | JM54ACT74BCA | 158 |
| 5962-8752501CA | C | 07/03/2002 | | (NONE) | | | 54ACT74 (GEN) | 158 |
| 5962-8752501MCA | C | 07/03/2002 | 3 | NATIONAL | | Y | 54ACT74DMQB | 158 |
| 5962-8752501MCA | C | 07/03/2002 | 3 | TI | | Y | SNJ54ACT74J | 158 |
| 5962-8752501SCA | C | 07/03/2002 | | (NONE) | 03/05/2002 | | 54ACT74 (GEN) | 158 |
| 5962R8752501BCA | C | 07/03/2002 | 3 | NATIONAL | | Y | JM54ACT74BCA-RH | 158 |
| 5962R8752501SCA | C | 07/03/2002 | 3 | NATIONAL | | Y | JM54ACT74SCA-RH | 158 |
| 5962-8752501BDA | C | 07/03/2002 | 3 | NATIONAL | | Y | JM54ACT74BDA | 158 |
| 5962-8752501DA | C | 07/03/2002 | | (NONE) | | | 54ACT74 (GEN) | 158 |
| 5962-8752501MDA | C | 07/03/2002 | 3 | NATIONAL | | Y | 54ACT74FMQB | 158 |
| 5962-8752501MDA | C | 07/03/2002 | 3 | TI | | Y | SNJ54ACT74W | 158 |
| 5962-8752501SDA | C | 07/03/2002 | 3 | NATIONAL | | Y | JM54ACT74SDA | 158 |
| 5962R8752501BDA | C | 07/03/2002 | 3 | NATIONAL | | Y | JM54ACT74BDA-RH | 158 |
| 5962R8752501SDA | C | 07/03/2002 | 3 | NATIONAL | | Y | JM54ACT74SDA-RH | 158 |
| 5962R8752501SZA | C | 07/03/2002 | 3 | NATIONAL | | Y | JM54ACT74SZA-RH | 158 |
| 5962-87525022A | C | 07/03/2002 | | (NONE) | 09/15/1995 | | 54ACT11074 (GEN) | 158 |
| 5962-8752502M2A | C | 07/03/2002 | 1 | ROCHESTER | | Y | 54ACT11074/B2A | 158 |
| 5962-8752502CA | C | 07/03/2002 | | (NONE) | 09/15/1995 | | 54ACT11074 (GEN) | 158 |
| 5962-8752502MCA | C | 07/03/2002 | 1 | ROCHESTER | | Y | 54ACT11074/BCA | 158 |
| 5962-8752502DA | C | 07/03/2002 | | (NONE) | 09/15/1995 | | 54ACT11074 (GEN) | 158 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-8752502MDA | C | 07/03/2002 | 1 | ROCHESTER | | Y | 54ACT11074/BDA | 158 |
| 5962-8752503QXA | C | 07/03/2002 | 2 | STMICRO | | Y | 54ACT74K02Q | 158 |
| 5962-8752503QXC | C | 07/03/2002 | 2 | STMICRO | | Y | 54ACT74K01Q | 158 |
| 5962-8752503VXA | C | 07/03/2002 | 2 | STMICRO | | Y | 54ACT74K02V | 158 |
| 5962-8752503VXC | C | 07/03/2002 | 2 | STMICRO | | Y | 54ACT74K01V | 158 |
| 5962-87526012A | A | 01/22/1988 | | (NONE) | | | Z0858110 (GEN) | 422 |
| 5962-8752601VA | A | 01/22/1988 | | (NONE) | | | Z0858110 (GEN) | 422 |
| 5962-87526022A | A | 01/22/1988 | | (NONE) | | | Z0858106 (GEN) | 422 |
| 5962-8752602VA | A | 01/22/1988 | | (NONE) | | | Z0858106 (GEN) | 422 |
| 5962-8752701QA | | 04/02/1987 | | (NONE) | | | Z0853006 (GEN) | 420 |
| 5962-8752701YA | | 04/02/1987 | | (NONE) | | | Z0853006 (GEN) | 420 |
| 5962-8752702QA | | 04/02/1987 | | (NONE) | | | Z0853004 (GEN) | 420 |
| 5962-8752702YA | | 04/02/1987 | | (NONE) | | | Z0853004 (GEN) | 420 |
| 5962-87528012A | | 08/07/1987 | | (NONE) | | | PAL18P8A (GEN) | 431 |
| 5962-8752801RA | | 08/07/1987 | | (NONE) | | | PAL18P8A (GEN) | 431 |
| 5962-8752801SA | | 08/07/1987 | | (NONE) | | | PAL18P8A (GEN) | 431 |
| 5962-87528022A | | 08/07/1987 | | (NONE) | | | PAL18P8B (GEN) | 431 |
| 5962-8752802RA | | 08/07/1987 | | (NONE) | | | PAL18P8B (GEN) | 431 |
| 5962-8752802SA | | 08/07/1987 | | (NONE) | | | PAL18P8B (GEN) | 431 |
| 5962-87528032A | | 08/07/1987 | | (NONE) | | | PAL18P8AL (GEN) | 431 |
| 5962-8752803RA | | 08/07/1987 | | (NONE) | | | PAL18P8AL (GEN) | 431 |
| 5962-8752803SA | | 08/07/1987 | | (NONE) | | | PAL18P8AL (GEN) | 431 |
| 5962-87528042A | | 08/07/1987 | | (NONE) | | | PAL18P8L (GEN) | 431 |
| 5962-8752804RA | | 08/07/1987 | | (NONE) | | | PAL18P8L (GEN) | 431 |
| 5962-8752804SA | | 08/07/1987 | | (NONE) | | | PAL18P8L (GEN) | 431 |
| 5962-87528052A | | 08/07/1987 | | (NONE) | | | PAL18P8Q (GEN) | 431 |
| 5962-8752805RA | | 08/07/1987 | | (NONE) | | | PAL18P8Q (GEN) | 431 |
| 5962-8752805SA | | 08/07/1987 | | (NONE) | | | PAL18P8Q (GEN) | 431 |
| 5962-87529013A | C | 08/30/2000 | 1 | QP SEMI | | | WS57C45-45CMB | 658 |
| 5962-87529013C | C | 08/30/2000 | 1 | QP SEMI | | | WS57C45-45CMB | 658 |
| 5962-8752901KA | C | 08/30/2000 | 1 | QP SEMI | | | WS57C45-45FMB | 658 |
| 5962-8752901LA | C | 08/30/2000 | 1 | QP SEMI | | | WS57C45-45TMB | 658 |
| 5962-87529023A | C | 08/30/2000 | 1 | QP SEMI | | | WS57C45-35CMB | 658 |
| 5962-87529023C | C | 08/30/2000 | 1 | QP SEMI | | | WS57C45-35CMB | 658 |
| 5962-8752902KA | C | 08/30/2000 | 1 | QP SEMI | | | WS57C45-35FMB | 658 |
| 5962-8752902LA | C | 08/30/2000 | 1 | QP SEMI | | | WS57C45-35TMB | 658 |
| 5962-87530013A | | 05/03/1988 | | (NONE) | | | 2010 (GEN) | 431 |
| 5962-8753001KA | | 05/03/1988 | | (NONE) | | | | 431 |
| 5962-8753001LA | | 05/03/1988 | | (NONE) | | | | 431 |
| 5962-87530023A | | 05/03/1988 | | (NONE) | | | | 431 |
| 5962-8753002KA | | 05/03/1988 | | (NONE) | | | | 431 |
| 5962-8753002LA | | 05/03/1988 | | (NONE) | | | | 431 |
| 5962-87530033A | | 05/03/1988 | | (NONE) | | | | 431 |
| 5962-8753003KA | | 05/03/1988 | | (NONE) | | | | 431 |
| 5962-8753003LA | | 05/03/1988 | | (NONE) | | | | 431 |
| 5962-87530043A | | 05/03/1988 | | (NONE) | | | | 431 |
| 5962-8753004KA | | 05/03/1988 | | (NONE) | | | | 431 |
| 5962-8753004LA | | 05/03/1988 | | (NONE) | | | | 431 |
| 5962-8753101TA | C | 01/17/2001 | 0 | IDT | | Y | IDT7201LA30TDB | 670 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-8753101UA | C | 01/17/2001 | | (NONE) | 10/29/2001 | | 7201LA30 (GEN) | 670 |
| 5962-8753101XA | C | 01/17/2001 | 1 | IDT | | Y | IDT7201LA30DB | 670 |
| 5962-8753101YA | C | 01/17/2001 | 1 | IDT | | Y | IDT7201LA30LB | 670 |
| 5962-8753101ZA | C | 01/17/2001 | | (NONE) | | | | 670 |
| 5962-8753102TA | C | 01/17/2001 | 0 | IDT | | Y | IDT7201LA50TDB | 670 |
| 5962-8753102UA | C | 01/17/2001 | | (NONE) | 10/29/2001 | | 7201LA50 (GEN) | 670 |
| 5962-8753102XA | C | 01/17/2001 | 1 | IDT | | Y | IDT7201LA50DB | 670 |
| 5962-8753102YA | C | 01/17/2001 | | (NONE) | 10/29/2001 | | 7201LA50 (GEN) | 670 |
| 5962-8753102ZA | C | 01/17/2001 | | (NONE) | | | | 670 |
| 5962-8753103TA | C | 01/17/2001 | 0 | IDT | | Y | IDT7201LA80TDB | 670 |
| 5962-8753103UA | C | 01/17/2001 | | (NONE) | 10/29/2001 | | 7201LA80 (GEN) | 670 |
| 5962-8753103XA | C | 01/17/2001 | 1 | IDT | | Y | IDT7201LA80DB | 670 |
| 5962-8753103YA | C | 01/17/2001 | | (NONE) | 10/29/2001 | | 7201LA80 (GEN) | 670 |
| 5962-8753103ZA | C | 01/17/2001 | | (NONE) | | | | 670 |
| 5962-8753201EA | A | 11/28/1988 | | (NONE) | 07/01/1994 | | 2069 (GEN) | 790 |
| 5962-8753202EA | A | 11/28/1988 | | (NONE) | 07/01/1994 | | 2070 (GEN) | 790 |
| 5962-87533013A | B | 10/29/2001 | 1 | TI | | Y | SNJ54ALS857FK | 279 |
| 5962-8753301KA | B | 10/29/2001 | | (NONE) | | | 54ALS857 (GEN) | 279 |
| 5962-8753301LA | B | 10/29/2001 | 1 | TI | | Y | SNJ54ALS857J | 279 |
| 5962-87534012A | B | 10/19/1987 | 2 | SARNOFF | | Y | GEM19501Q2A | 590 |
| 5962-87534012C | B | 10/19/1987 | 2 | SARNOFF | | Y | GEM19501Q2C | 590 |
| 5962-8753401EA | B | 10/19/1987 | 2 | SARNOFF | | Y | GEM19501QEA | 590 |
| 5962-8753401EC | B | 10/19/1987 | 2 | SARNOFF | | Y | GEM19501QEC | 590 |
| 5962-8753401FA | B | 10/19/1987 | 2 | SARNOFF | | Y | GEM19501QFA | 590 |
| 5962-8753401FC | B | 10/19/1987 | 2 | SARNOFF | | Y | GEM19501QFC | 590 |
| 5962-87534022A | B | 10/19/1987 | 1 | ROCHESTER | | Y | 26S12A/B2A | 590 |
| 5962-8753402EA | B | 10/19/1987 | 1 | ROCHESTER | | Y | 26S12A/BEA | 590 |
| 5962-8753402FA | B | 10/19/1987 | 1 | ROCHESTER | | Y | 26S12A/BFA | 590 |
| 5962-8753501XA | E | 12/16/2002 | | (NONE) | | | BUS-65112 (GEN) | 590 |
| 5962-8753501YA | E | 12/16/2002 | | (NONE) | | | BUS-65117 (GEN) | 590 |
| 5962-8753502XA | E | 12/16/2002 | 1 | AEROFLEX | | Y | ARX2452-001-2 | 590 |
| 5962-8753502XC | E | 12/16/2002 | 1 | AEROFLEX | | Y | ARX2452-001-1 | 590 |
| 5962-8753502YA | E | 12/16/2002 | 1 | AEROFLEX | | Y | ARX2452-202-2 | 590 |
| 5962-8753502YC | E | 12/16/2002 | 1 | AEROFLEX | | Y | ARX2452-202-1 | 590 |
| 5962-8753503XA | E | 12/16/2002 | 1 | AEROFLEX | | Y | CT-2512-001-2 | 590 |
| 5962-8753503XC | E | 12/16/2002 | 1 | AEROFLEX | | Y | CT-2512-001-1 | 590 |
| 5962-8753503ZA | E | 12/16/2002 | 1 | AEROFLEX | | Y | CT-2512-201-2 | 590 |
| 5962-8753503ZC | E | 12/16/2002 | 1 | AEROFLEX | | Y | CT-2512-201-1 | 590 |
| 5962-8753601RA | | 04/01/1987 | | (NONE) | | | 25S244 (GEN) | 529 |
| 5962-8753601SA | | 04/01/1987 | | (NONE) | | | 25S244 (GEN) | 529 |
| 5962D8753801XA | | 01/24/1990 | | (NONE) | | | HS1-1840RH (GEN) | 195 |
| 5962D8753801YA | | 01/24/1990 | | (NONE) | | | HS9-1840RH (GEN) | 195 |
| 5962-87539013A | J | 01/04/2002 | 2 | QP SEMI | | Y | PALC22V10-25QMB | 431 |
| 5962-8753901KA | J | 01/04/2002 | 2 | QP SEMI | | Y | PALC22V10-25TMB | 431 |
| 5962-8753901LA | J | 01/04/2002 | 1 | CYPRESS | 05/03/2004 | Y | PALC22V10-25WMB | 431 |
| 5962-8753901LA | J | 01/04/2002 | 2 | QP SEMI | | Y | PALC22V10-25WMB | 431 |
| 5962-87539023A | J | 01/04/2002 | 2 | QP SEMI | | Y | PALC22V10-30QMB | 431 |
| 5962-8753902KA | J | 01/04/2002 | 2 | QP SEMI | | Y | PALC22V10-30TMB | 431 |
| 5962-8753902LA | J | 01/04/2002 | 2 | QP SEMI | | Y | PALC22V10-30WMB | 431 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-87539033A | J | 01/04/2002 | 2 | QP SEMI | | Y | PALC22V10-40QMB | 431 |
| 5962-8753903KA | J | 01/04/2002 | 2 | QP SEMI | | Y | PALC22V10-40TMB | 431 |
| 5962-8753903LA | J | 01/04/2002 | 2 | QP SEMI | | Y | PALC22V10-40WMB | 431 |
| 5962-87539043A | J | 01/04/2002 | 2 | QP SEMI | | Y | PALC22V10B-20QMB | 431 |
| 5962-8753904KA | J | 01/04/2002 | 2 | QP SEMI | | Y | PALC22V10B-20TMB | 431 |
| 5962-8753904LA | J | 01/04/2002 | 2 | CYPRESS | 05/03/2004 | Y | PALC22V10B-20WMB | 431 |
| 5962-8753904LA | J | 01/04/2002 | 2 | QP SEMI | | Y | PALC22V10B-20WMB | 431 |
| 5962-87539053A | J | 01/04/2002 | 2 | QP SEMI | | Y | PALC22V10B-15QMB | 431 |
| 5962-8753905KA | J | 01/04/2002 | 2 | QP SEMI | | Y | PALC22V10B-15TMB | 431 |
| 5962-8753905LA | J | 01/04/2002 | 2 | QP SEMI | | Y | PALC22V10B-15WMB | 431 |
| 5962-87539063A | J | 01/04/2002 | | (NONE) | | | 22V10B (GEN) | 431 |
| 5962-8753906LA | J | 01/04/2002 | | (NONE) | | | 22V10B (GEN) | 431 |
| 5962-8753906XA | J | 01/04/2002 | | (NONE) | | | 22V10B (GEN) | 431 |
| 5962-87540012A | C | 08/06/2002 | 1 | ANALOG (2) | | Y | AD585SE/883B | 818 |
| 5962-8754001CA | C | 08/06/2002 | 1 | ANALOG (2) | | Y | AD585SQ/883B | 818 |
| 5962-87541012A | B | 03/16/1992 | | (NONE) | 09/30/1995 | | 10H610 (GEN) | 125 |
| 5962-8754101EA | B | 03/16/1992 | | (NONE) | 09/30/1995 | | 10H610 (GEN) | 125 |
| 5962-8754101FA | B | 03/16/1992 | | (NONE) | 09/30/1995 | | 10H610 (GEN) | 125 |
| 5962-87542012A | B | 10/11/2001 | 1 | SARNOFF | | Y | GEM02901B2A | 345 |
| 5962-87542012C | B | 10/11/2001 | 1 | SARNOFF | | Y | GEM02901B2C | 345 |
| 5962-8754201RA | B | 10/11/2001 | 1 | SARNOFF | | Y | GEM02901BRA | 345 |
| 5962-8754201RC | B | 10/11/2001 | 1 | SARNOFF | | Y | GEM02901BRC | 345 |
| 5962-8754201SA | B | 10/11/2001 | 1 | SARNOFF | | Y | GEM02901BSA | 345 |
| 5962-8754201SC | B | 10/11/2001 | 1 | SARNOFF | | Y | GEM02901BSC | 345 |
| 5962-8754301CA | B | 10/04/2001 | 1 | LANSDALE | | Y | SL82S62/BCA | 210 |
| 5962-8754301DA | B | 10/04/2001 | 1 | LANSDALE | | Y | SL82S62/BDA | 210 |
| 5962-87544012A | B | 02/28/2000 | 1 | ROCHESTER | | Y | 25LS2569/B2A | 304 |
| 5962-8754401RA | B | 02/28/2000 | 1 | ROCHESTER | | Y | 25LS2569/BRA | 304 |
| 5962-8754401SA | B | 02/28/2000 | 1 | ROCHESTER | | Y | 25LS2569/BSA | 304 |
| 5962-8754501CA | A | 03/17/1993 | | (NONE) | 06/08/1999 | | LM760 (GEN) | 772 |
| 5962-8754501GA | A | 03/17/1993 | | (NONE) | 06/08/1999 | | LM760 (GEN) | 772 |
| 5962-8754601PA | A | 07/12/2002 | 2 | NATIONAL | | Y | DS9638J/883 | 589 |
| 5962-87547012A | C | 07/12/2002 | 3 | TI | | Y | SNJ55110AFK | 562 |
| 5962-8754701CA | C | 07/12/2002 | 3 | TI | | Y | SNJ55110AJ | 562 |
| 5962-8754701DA | C | 07/12/2002 | 3 | TI | | Y | SNJ55110AW | 562 |
| 5962-87547022A | C | 07/12/2002 | | (NONE) | 05/01/1998 | | 55109 (GEN) | 562 |
| 5962-8754702CA | C | 07/12/2002 | | (NONE) | 05/01/1998 | | 55109 (GEN) | 562 |
| 5962-8754702DA | C | 07/12/2002 | | (NONE) | 05/01/1998 | | 55109 (GEN) | 562 |
| 5962-8754801XA | C | 07/14/2000 | | (NONE) | | | 8251A (GEN) | 421 |
| 5962-87548023A | C | 07/14/2000 | 1 | ROCHESTER | | Y | MR8251A/B | 421 |
| 5962-8754802XA | C | 07/14/2000 | 1 | ROCHESTER | | Y | MD8251A/B | 421 |
| 5962-87549012A | E | 10/01/2003 | 3 | NATIONAL | | Y | 54AC00LMQB | 100 |
| 5962-87549012A | E | 10/01/2003 | 2 | TI | | Y | SNJ54AC00FK | 100 |
| 5962-8754901CA | E | 10/01/2003 | 3 | NATIONAL | | Y | 54AC00DMQB | 100 |
| 5962-8754901CA | E | 10/01/2003 | 2 | TI | | Y | SNJ54AC00J | 100 |
| 5962-8754901DA | E | 10/01/2003 | 3 | NATIONAL | | Y | 54AC00FMQB | 100 |
| 5962-8754901DA | E | 10/01/2003 | 2 | TI | | Y | SNJ54AC00W | 100 |
| 5962-8754901VXA | E | 10/01/2003 | | (NONE) | | | 54AC00 (GEN) | 100 |
| 5962-8754901XA | E | 10/01/2003 | | (NONE) | | | 54AC00 (GEN) | 100 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962F8754901VXA | E | 10/01/2003 | 2 | STMICRO | | Y | RHFAC00K02V | 100 |
| 5962F8754901VXC | E | 10/01/2003 | 2 | STMICRO | | Y | RHFAC00K01V | 100 |
| 5962F8754901XA | E | 10/01/2003 | 2 | STMICRO | | Y | RHFAC00K02Q | 100 |
| 5962F8754901XC | E | 10/01/2003 | 2 | STMICRO | | Y | RHFAC00K01Q | 100 |
| 5962-87549022A | E | 10/01/2003 | | (NONE) | 09/15/1995 | | 54AC11000 (GEN) | 100 |
| 5962-8754902EA | E | 10/01/2003 | | (NONE) | 09/15/1995 | | 54AC11000 (GEN) | 100 |
| 5962-8754902FA | E | 10/01/2003 | | (NONE) | | | 54AC11000 (GEN) | 100 |
| 5962-87550012A | D | 07/23/2001 | 3 | NATIONAL | | Y | 54AC240LMQB | 529 |
| 5962-87550012A | D | 07/23/2001 | 1 | TI | | Y | SNJ54AC240FK | 529 |
| 5962-8755001RA | D | 07/23/2001 | 3 | NATIONAL | | Y | 54AC240DMQB | 529 |
| 5962-8755001RA | D | 07/23/2001 | 1 | TI | | Y | SNJ54AC240J | 529 |
| 5962-8755001SA | D | 07/23/2001 | 3 | NATIONAL | | Y | 54AC240FMQB | 529 |
| 5962-8755001SA | D | 07/23/2001 | 1 | TI | | Y | SNJ54AC240W | 529 |
| 5962-8755001VXA | D | 07/23/2001 | 2 | STMICRO | | Y | 54AC240K02V | 529 |
| 5962-8755001VXC | D | 07/23/2001 | 2 | STMICRO | | Y | 54AC240K01V | 529 |
| 5962-8755001XA | D | 07/23/2001 | 2 | STMICRO | | Y | 54AC240K02Q | 529 |
| 5962-8755001XC | D | 07/23/2001 | 2 | STMICRO | | Y | 54AC240K01Q | 529 |
| 5962-8755001ZA | D | 07/23/2001 | 3 | NATIONAL | | Y | 54AC240WG-QML | 529 |
| 5962-87550023A | D | 07/23/2001 | 1 | ROCHESTER | | | 54AC11240/B3A | 529 |
| 5962-8755002JA | D | 07/23/2001 | 1 | ROCHESTER | | | 54AC11240/BJA | 529 |
| 5962-8755002KA | D | 07/23/2001 | 1 | ROCHESTER | | | 54AC11240/BKA | 529 |
| 5962-87551012A | C | 08/27/2001 | 3 | NATIONAL | | Y | 54AC241LMQB | 529 |
| 5962-8755101RA | C | 08/27/2001 | 3 | NATIONAL | | Y | 54AC241DMQB | 529 |
| 5962-8755101SA | C | 08/27/2001 | 3 | NATIONAL | | Y | 54AC241FMQB | 529 |
| 5962-8755101ZA | C | 08/27/2001 | 3 | NATIONAL | | Y | 54AC241WG-QML | 529 |
| 5962-87551023A | C | 08/27/2001 | 1 | ROCHESTER | | Y | 54AC11241/B3A | 529 |
| 5962-8755102LA | C | 08/27/2001 | 1 | ROCHESTER | | Y | 54AC11241/BLA | 529 |
| 5962-87552012A | G | 07/23/2001 | 3 | NATIONAL | | Y | 54AC244LMQB | 529 |
| 5962-87552012A | G | 07/23/2001 | 2 | TI | | Y | SNJ54AC244FK | 529 |
| 5962-8755201RA | G | 07/23/2001 | 3 | NATIONAL | | Y | 54AC244DMQB | 529 |
| 5962-8755201RA | G | 07/23/2001 | 2 | TI | | Y | SNJ54AC244J | 529 |
| 5962-8755201VRA | G | 07/23/2001 | 2 | TI | | Y | SNV54AC244J | 529 |
| 5962-8755201SA | G | 07/23/2001 | 3 | NATIONAL | | Y | 54AC244FMQB | 529 |
| 5962-8755201SA | G | 07/23/2001 | 2 | TI | | Y | SNJ54AC244W | 529 |
| 5962-8755201VSA | G | 07/23/2001 | 2 | TI | | Y | SNV54AC244W | 529 |
| 5962-8755201VXA | G | 07/23/2001 | 2 | STMICRO | | Y | 54AC244K02V | 529 |
| 5962-8755201VXC | G | 07/23/2001 | 2 | STMICRO | | Y | 54AC244K01V | 529 |
| 5962-8755201XA | G | 07/23/2001 | 2 | STMICRO | | Y | 54AC244K02Q | 529 |
| 5962-8755201XC | G | 07/23/2001 | 2 | STMICRO | | Y | 54AC244K01Q | 529 |
| 5962-8755201ZA | G | 07/23/2001 | 3 | NATIONAL | | Y | 54AC244WG-QML | 529 |
| 5962-87552023A | G | 07/23/2001 | | (NONE) | 09/15/1995 | | 54AC11244 (GEN) | 529 |
| 5962-8755202JA | G | 07/23/2001 | | (NONE) | | | 54AC11244 (GEN) | 529 |
| 5962-8755202KA | G | 07/23/2001 | | (NONE) | | | 54AC11244 (GEN) | 529 |
| 5962-8755202LA | G | 07/23/2001 | | (NONE) | 09/15/1995 | | 54AC11244 (GEN) | 529 |
| 5962-87553012A | A | 07/17/2001 | 3 | NATIONAL | | Y | 54ACT139LMQB | 283 |
| 5962-8755301EA | A | 07/17/2001 | 3 | NATIONAL | | Y | 54ACT139DMQB | 283 |
| 5962-8755301FA | A | 07/17/2001 | 3 | NATIONAL | | Y | 54ACT139FMQB | 283 |
| 5962-87554012A | E | 05/05/2004 | | (NONE) | | | 54ACT138 (GEN) | 282 |
| 5962-8755401B2A | E | 05/05/2004 | | (NONE) | | | 54ACT138 (GEN) | 282 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-8755401M2A | E | 05/05/2004 | 3 | NATIONAL | | Y | 54ACT138LMQB | 282 |
| 5962-8755401S2A | E | 05/05/2004 | | (NONE) | 03/05/2002 | | 54ACT138 (GEN) | 282 |
| 5962R8755401B2A | E | 05/05/2004 | 3 | NATIONAL | | Y | JM54ACT138B2A-R | 282 |
| 5962R8755401S2A | E | 05/05/2004 | 3 | NATIONAL | | Y | JM54ACT138S2A-R | 282 |
| 5962-8755401BEA | E | 05/05/2004 | 3 | NATIONAL | | Y | JM54ACT138BEA | 282 |
| 5962-8755401EA | E | 05/05/2004 | | (NONE) | 5962-8755401MEA | | 54ACT138 (GEN) | 282 |
| 5962-8755401MEA | E | 05/05/2004 | 3 | NATIONAL | | Y | 54ACT138DMQB | 282 |
| 5962-8755401SEA | E | 05/05/2004 | | (NONE) | | | 54ACT138 (GEN) | 282 |
| 5962R8755401BEA | E | 05/05/2004 | 3 | NATIONAL | | Y | JM54ACT138BEA-R | 282 |
| 5962R8755401SEA | E | 05/05/2004 | 3 | NATIONAL | | Y | JM54ACT138SEA-R | 282 |
| 5962-8755401BFA | E | 05/05/2004 | | (NONE) | | | 54ACT138 (GEN) | 282 |
| 5962-8755401FA | E | 05/05/2004 | | (NONE) | 5962-8755401MFA | | 54ACT138 (GEN) | 282 |
| 5962-8755401MFA | E | 05/05/2004 | 3 | NATIONAL | | Y | 54ACT138FMQB | 282 |
| 5962-8755401SFA | E | 05/05/2004 | | (NONE) | | | 54ACT138 (GEN) | 282 |
| 5962R8755401BFA | E | 05/05/2004 | 3 | NATIONAL | | Y | JM54ACT138BFA-R | 282 |
| 5962R8755401SFA | E | 05/05/2004 | 3 | NATIONAL | | Y | JM54ACT138SFA-R | 282 |
| 5962-8755402M2A | E | 05/05/2004 | 1 | ROCHESTER | | Y | 54ACT11138/B2A | 282 |
| 5962-8755402MEA | E | 05/05/2004 | 1 | ROCHESTER | | Y | 54ACT11138/BEA | 282 |
| 5962-8755403QXA | E | 05/05/2004 | 2 | STMICRO | | Y | 54ACT138K02Q | 282 |
| 5962-8755403QXC | E | 05/05/2004 | 2 | STMICRO | | Y | 54ACT138K01Q | 282 |
| 5962-8755403VXA | E | 05/05/2004 | 2 | STMICRO | | Y | 54ACT138K02V | 282 |
| 5962-8755403VXC | E | 05/05/2004 | 2 | STMICRO | | Y | 54ACT138K01V | 282 |
| 5962F8755403QXA | E | 05/05/2004 | 2 | STMICRO | | Y | RHFACT138K02Q | 282 |
| 5962F8755403QXC | E | 05/05/2004 | 2 | STMICRO | | Y | RHFACT138K01Q | 282 |
| 5962F8755403VXA | E | 05/05/2004 | 2 | STMICRO | | Y | RHFACT138K02V | 282 |
| 5962F8755403VXC | E | 05/05/2004 | 2 | STMICRO | | Y | RHFACT138K01V | 282 |
| 5962-87555012A | D | 01/10/2001 | 3 | NATIONAL | | Y | 54AC373LMQB | 341 |
| 5962-87555012A | D | 01/10/2001 | 3 | TI | | Y | SNJ54AC373FK | 341 |
| 5962-8755501RA | D | 01/10/2001 | 3 | NATIONAL | | Y | 54AC373DMQB | 341 |
| 5962-8755501RA | D | 01/10/2001 | 3 | TI | | Y | SNJ54AC373J | 341 |
| 5962-8755501VRA | D | 01/10/2001 | 3 | TI | | Y | SNV54AC373J | 341 |
| 5962-8755501SA | D | 01/10/2001 | 3 | NATIONAL | | Y | 54AC373FMQB | 341 |
| 5962-8755501SA | D | 01/10/2001 | 3 | TI | | Y | SNJ54AC373W | 341 |
| 5962-8755501VSA | D | 01/10/2001 | 3 | TI | | Y | SNV54AC373W | 341 |
| 5962-8755501VXA | D | 01/10/2001 | 2 | STMICRO | | Y | 54AC373K02V | 341 |
| 5962-8755501VXC | D | 01/10/2001 | 2 | STMICRO | | Y | 54AC373K01V | 341 |
| 5962-8755501XA | D | 01/10/2001 | 2 | STMICRO | | Y | 54AC373K02Q | 341 |
| 5962-8755501XC | D | 01/10/2001 | 2 | STMICRO | | Y | 54AC373K01Q | 341 |
| 5962-87555023A | D | 01/10/2001 | | (NONE) | 09/15/1995 | | 54AC11373 (GEN) | 341 |
| 5962-8755502LA | D | 01/10/2001 | | (NONE) | 09/15/1995 | | 54AC11373 (GEN) | 341 |
| 5962-87556012A | C | 06/19/2002 | 3 | NATIONAL | | Y | 54ACT373LMQB | 341 |
| 5962-87556012A | C | 06/19/2002 | 3 | TI | | Y | SNJ54ACT373FK | 341 |
| 5962-8755601RA | C | 06/19/2002 | 3 | NATIONAL | | Y | 54ACT373DMQB | 341 |
| 5962-8755601RA | C | 06/19/2002 | 3 | TI | | Y | SNJ54ACT373J | 341 |
| 5962-8755601VRA | C | 06/19/2002 | 3 | TI | | Y | SNV54ACT373J | 341 |
| 5962-8755601SA | C | 06/19/2002 | 3 | NATIONAL | | Y | 54ACT373FMQB | 341 |
| 5962-8755601SA | C | 06/19/2002 | 3 | TI | | Y | SNJ54ACT373W | 341 |
| 5962-8755601VSA | C | 06/19/2002 | 3 | TI | | Y | SNV54ACT373W | 341 |
| 5962-87556023A | C | 06/19/2002 | | (NONE) | 09/15/1995 | | 54ACT11373 (GEN) | 341 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-8755602LA | C | 06/19/2002 | | (NONE) | 09/15/1995 | | 54ACT11373 (GEN) | 341 |
| 5962-8755603VXA | C | 06/19/2002 | 2 | STMICRO | | Y | 54ACT373K02V | 341 |
| 5962-8755603VXC | C | 06/19/2002 | 2 | STMICRO | | Y | 54ACT373K01V | 341 |
| 5962-8755603XA | C | 06/19/2002 | 2 | STMICRO | | Y | 54ACT373K02Q | 341 |
| 5962-8755603XC | C | 06/19/2002 | 2 | STMICRO | | Y | 54ACT373K01Q | 341 |
| 5962-87557012A | D | 08/12/1998 | 1 | AUSTIN SEMI. | | Y | AS10H502EC20/883C | 120 |
| 5962-8755701EA | D | 08/12/1998 | 1 | AUSTIN SEMI. | | Y | AS10H502C16/883C | 120 |
| 5962-8755701FA | D | 08/12/1998 | | (NONE) | 09/30/1995 | | 10H502 (GEN) | 120 |
| 5962-8755701XA | D | 08/12/1998 | 1 | AUSTIN SEMI. | | Y | AS10H502F16/883C | 120 |
| 5962-87558012A | C | 02/16/2000 | 1 | QP SEMI | | Y | 10H513/2A | 140 |
| 5962-8755801EA | C | 02/16/2000 | 1 | QP SEMI | | Y | 10H513/EA | 140 |
| 5962-8755801FA | C | 02/16/2000 | 1 | QP SEMI | | Y | 10H513/FA | 140 |
| 5962-87559012A | B | 04/12/1993 | | (NONE) | | | 10H518 (GEN) | 142 |
| 5962-8755901EA | B | 04/12/1993 | | (NONE) | | | 10H518 (GEN) | 142 |
| 5962-8755901FA | B | 04/12/1993 | | (NONE) | | | 10H518 (GEN) | 142 |
| 5962-87560012A | E | 10/20/1998 | 1 | AUSTIN SEMI. | | Y | AS10H524EC20/883C | 547 |
| 5962-8756001EA | E | 10/20/1998 | 1 | AUSTIN SEMI. | | Y | AS10H524C16/883C | 547 |
| 5962-8756001FA | E | 10/20/1998 | | (NONE) | 09/30/1995 | | 10H524 (GEN) | 547 |
| 5962-8756001XA | E | 10/20/1998 | 1 | AUSTIN SEMI. | | Y | AS10H524F16/883C | 547 |
| 5962-87561012A | E | 08/13/1998 | 1 | AUSTIN SEMI. | | Y | AS10H531EC20/883C | 158 |
| 5962-8756101EA | E | 08/13/1998 | 1 | AUSTIN SEMI. | | Y | AS10H531C16/883C | 158 |
| 5962-8756101FA | E | 08/13/1998 | | (NONE) | 09/30/1995 | | 10H531 (GEN) | 158 |
| 5962-8756101XA | E | 08/13/1998 | 1 | AUSTIN SEMI. | | Y | AS10H531F16/883C | 158 |
| 5962-87562012A | B | 12/05/1991 | | (NONE) | | | 10H560 (GEN) | 210 |
| 5962-8756201EA | B | 12/05/1991 | | (NONE) | | | 10H560 (GEN) | 210 |
| 5962-8756201FA | B | 12/05/1991 | | (NONE) | | | 10H560 (GEN) | 210 |
| 5962-87563012A | C | 03/26/1993 | | (NONE) | 09/30/1995 | | 10H586 (GEN) | 159 |
| 5962-8756301EA | C | 03/26/1993 | | (NONE) | 09/30/1995 | | 10H586 (GEN) | 159 |
| 5962-8756301FA | C | 03/26/1993 | | (NONE) | 09/30/1995 | | 10H586 (GEN) | 159 |
| 5962-87564012A | B | 12/05/1991 | | (NONE) | 09/30/1995 | | 10H506 (GEN) | 124 |
| 5962-8756401EA | B | 12/05/1991 | | (NONE) | 09/30/1995 | | 10H506 (GEN) | 124 |
| 5962-8756401FA | B | 12/05/1991 | | (NONE) | 09/30/1995 | | 10H506 (GEN) | 124 |
| 5962-87565012A | C | 04/12/1993 | | (NONE) | 09/30/1995 | | 10H503 (GEN) | 125 |
| 5962-8756501EA | C | 04/12/1993 | | (NONE) | 09/30/1995 | | 10H503 (GEN) | 125 |
| 5962-8756501FA | C | 04/12/1993 | | (NONE) | 09/30/1995 | | 10H503 (GEN) | 125 |
| 5962-87566012A | E | 05/01/2002 | 1 | QP SEMI | | Y | 10H558/2A | 275 |
| 5962-8756601EA | E | 05/01/2002 | 1 | QP SEMI | | Y | 10H558/EA | 275 |
| 5962-8756601FA | E | 05/01/2002 | 1 | QP SEMI | | Y | 10H558/FA | 275 |
| 5962-87567012A | E | 08/17/1998 | 1 | AUSTIN SEMI. | | Y | AS10H561EC20/883C | 282 |
| 5962-8756701EA | E | 08/17/1998 | 1 | AUSTIN SEMI. | | Y | AS10H561C16/883C | 282 |
| 5962-8756701FA | E | 08/17/1998 | | (NONE) | 09/30/1995 | | 10H561 (GEN) | 282 |
| 5962-8756701XA | E | 08/17/1998 | 1 | AUSTIN SEMI. | | Y | AS10H561F16/883C | 282 |
| 5962-87568012A | B | 12/09/1991 | | (NONE) | | | 10H571 (GEN) | 283 |
| 5962-8756801EA | B | 12/09/1991 | | (NONE) | | | 10H571 (GEN) | 283 |
| 5962-8756801FA | B | 12/09/1991 | | (NONE) | | | 10H571 (GEN) | 283 |
| 5962-87569012A | C | 04/12/1993 | | (NONE) | 09/30/1995 | | 10H609 (GEN) | 149 |
| 5962-8756901EA | C | 04/12/1993 | | (NONE) | 09/30/1995 | | 10H609 (GEN) | 149 |
| 5962-8756901FA | C | 04/12/1993 | | (NONE) | 09/30/1995 | | 10H609 (GEN) | 149 |
| 5962-8757001QA | D | 04/02/2001 | 1 | ROCHESTER | | Y | MD8255A/BQA | 421 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-8757001XA | D | 04/02/2001 | 1 | ROCHESTER | | Y | MR8255A/BXA | 421 |
| 5962-8757002QA | D | 04/02/2001 | | (NONE) | | | 8255A-5 (GEN) | 421 |
| 5962-8757101XA | F | 05/24/2002 | 2 | ANALOG (2) | | Y | AD590JF/883B | 899 |
| 5962-8757101YA | F | 05/24/2002 | 2 | ANALOG (2) | | Y | AD590JH/883B | 899 |
| 5962-8757102VXA | F | 05/24/2002 | | (NONE) | | | AD590K (GEN) | 899 |
| 5962-8757102XA | F | 05/24/2002 | 2 | ANALOG (2) | | Y | AD590KF/883B | 899 |
| 5962-8757102VYA | F | 05/24/2002 | | (NONE) | | | AD590K (GEN) | 899 |
| 5962-8757102YA | F | 05/24/2002 | 2 | ANALOG (2) | | Y | AD590KH/883B | 899 |
| 5962-8757103VXA | F | 05/24/2002 | 2 | ANALOG (5) | | Y | AD590LF/QMLV | 899 |
| 5962-8757103XA | F | 05/24/2002 | 2 | ANALOG (2) | | Y | AD590LF/883B | 899 |
| 5962R8757103VXA | F | 05/24/2002 | 2 | ANALOG (5) | | Y | AD590LF/QMLR | 899 |
| 5962-8757103VYA | F | 05/24/2002 | 2 | ANALOG (5) | | Y | AD590LH/QMLV | 899 |
| 5962-8757103YA | F | 05/24/2002 | 2 | ANALOG (2) | | Y | AD590LH/883B | 899 |
| 5962R8757103VYA | F | 05/24/2002 | 2 | ANALOG (5) | | Y | AD590LH/QMLR | 899 |
| 5962-8757104VXA | F | 05/24/2002 | 2 | ANALOG (5) | | Y | AD590MF/QMLV | 899 |
| 5962-8757104XA | F | 05/24/2002 | 2 | ANALOG (2) | | Y | AD590MF/883B | 899 |
| 5962-8757104VYA | F | 05/24/2002 | 2 | ANALOG (5) | | Y | AD590MH/QMLV | 899 |
| 5962-8757104YA | F | 05/24/2002 | 2 | ANALOG (2) | | Y | AD590MH/883B | 899 |
| 5962-8757201CA | C | 11/18/2003 | | (NONE) | 09/01/1997 | | 527 (GEN) | 772 |
| 5962-8757201DA | C | 11/18/2003 | | (NONE) | 09/01/1997 | | 527 (GEN) | 772 |
| 5962-8757202CA | C | 11/18/2003 | 1 | QP SEMI | | Y | 529/BCA | 772 |
| 5962-8757202DA | C | 11/18/2003 | 1 | QP SEMI | | Y | 529/BDA | 772 |
| 5962-8757203BA | C | 11/18/2003 | 1 | QP SEMI | | Y | LM161/BA | 772 |
| 5962-8757203CA | C | 11/18/2003 | 1 | QP SEMI | | Y | LM161/CA | 772 |
| 5962-8757203CA | C | 11/18/2003 | 1 | ROCHESTER | | Y | LM161J/883 | 772 |
| 5962-8757203IA | C | 11/18/2003 | 1 | QP SEMI | | Y | LM161/IA | 772 |
| 5962-8757203IA | C | 11/18/2003 | 1 | ROCHESTER | | Y | LM161H/883 | 772 |
| 5962-87573013A | A | 11/17/1988 | | (NONE) | 06/30/1994 | | 2930 (GEN) | 420 |
| 5962-8757301XA | A | 11/17/1988 | | (NONE) | 06/30/1994 | | 2930 (GEN) | 420 |
| 5962-8757301YA | A | 11/17/1988 | | (NONE) | | | 2930 (GEN) | 420 |
| 5962-8757401QA | B | 07/24/2002 | 1 | ROCHESTER | | Y | 2964B/BQA | 423 |
| 5962-8757401UA | B | 07/24/2002 | 1 | ROCHESTER | | Y | 2964B/BUA | 423 |
| 5962-8757501QA | A | 11/23/1992 | | (NONE) | | | 9517A (GEN) | 423 |
| 5962-8757502QA | A | 11/23/1992 | | (NONE) | | | 9517A-4 (GEN) | 423 |
| 5962-8757601XA | A | 12/09/1992 | | (NONE) | | | 8X371 (GEN) | 421 |
| 5962-87577012A | A | 05/19/2000 | | (NONE) | 03/25/2001 | | 82C86H-5 (GEN) | 590 |
| 5962-8757701RA | A | 05/19/2000 | 1 | INTERSIL | | Y | MD82C86H-5/883 | 590 |
| 5962-87577022A | A | 05/19/2000 | | (NONE) | 03/25/2001 | | 82C87H-5 (GEN) | 590 |
| 5962-8757702RA | A | 05/19/2000 | 1 | INTERSIL | | Y | MD82C87H-5/883 | 590 |
| 5962-87578012A | B | 05/04/1995 | 1 | MINCO | | Y | MTL1007AM2/883 | 702 |
| 5962-87578012C | B | 05/04/1995 | 1 | MINCO | | Y | MTL1007AM2/883 | 702 |
| 5962-8757801GA | B | 05/04/1995 | 1 | MINCO | | Y | MTL1007AMH/883 | 702 |
| 5962-8757801GC | B | 05/04/1995 | 1 | MINCO | | Y | MTL1007AMH/883 | 702 |
| 5962-8757801PA | B | 05/04/1995 | 1 | MINCO | | Y | MTL1007AMJ8/883 | 702 |
| 5962-8757801PA | B | 05/04/1995 | 1 | MINCO | | Y | MTL1007AMD8/883 | 702 |
| 5962-8757801PC | B | 05/04/1995 | 1 | MINCO | | Y | MTL1007AMD8/883 | 702 |
| 5962-8757801PC | B | 05/04/1995 | 1 | MINCO | | Y | MTL1007AMJ8/883 | 702 |
| 5962-87578022A | B | 05/04/1995 | 1 | MINCO | | Y | MTL1007AM2/883 | 702 |
| 5962-87578022C | B | 05/04/1995 | 1 | MINCO | | Y | MTL1007AM2/883 | 702 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-8757802GA | B | 05/04/1995 | 1 | MINCO | | Y | MTL1007MH/883 | 702 |
| 5962-8757802GC | B | 05/04/1995 | 1 | MINCO | | Y | MTL1007MH/883 | 702 |
| 5962-8757802PA | B | 05/04/1995 | 1 | MINCO | | Y | MTL1007MJ8/883 | 702 |
| 5962-8757802PA | B | 05/04/1995 | 1 | MINCO | | Y | MTL1007MD8/883 | 702 |
| 5962-8757802PC | B | 05/04/1995 | 1 | MINCO | | Y | MTL1007MJ8/883 | 702 |
| 5962-8757802PC | B | 05/04/1995 | 1 | MINCO | | Y | MTL1007MD8/883 | 702 |
| 5962-8757901XA | L | 06/20/1996 | | (NONE) | | | BUS-63125 (GEN) | 590 |
| 5962-8757901YA | L | 06/20/1996 | | (NONE) | | | BUS-63125 (GEN) | 590 |
| 5962-8757902XA | L | 06/20/1996 | 1 | DDC | | Y | BUS-63125II | 590 |
| 5962-8757902XA | L | 06/20/1996 | 1 | DDC IRELAND | | Y | BUS63125II | 590 |
| 5962-8757902XC | L | 06/20/1996 | 1 | DDC | | Y | BUS-63125II | 590 |
| 5962-8757902XC | L | 06/20/1996 | 1 | DDC IRELAND | | Y | BUS63125II | 590 |
| 5962-8757902YA | L | 06/20/1996 | 1 | DDC | | Y | BUS-63126II | 590 |
| 5962-8757902YA | L | 06/20/1996 | 1 | DDC IRELAND | | Y | BUS63126II | 590 |
| 5962-8757902YC | L | 06/20/1996 | 1 | DDC | | Y | BUS-63126II | 590 |
| 5962-8757902YC | L | 06/20/1996 | 1 | DDC IRELAND | | Y | BUS63126II | 590 |
| 5962-8757903XA | L | 06/20/1996 | | (NONE) | | | ARX2411 (GEN) | 590 |
| 5962-8757903YA | L | 06/20/1996 | | (NONE) | | | ARX2411 (GEN) | 590 |
| 5962-8757904UA | L | 06/20/1996 | | (NONE) | | | ARX3411 (GEN) | 590 |
| 5962-8757904XA | L | 06/20/1996 | | (NONE) | | | ARX3411 (GEN) | 590 |
| 5962-8757904YA | L | 06/20/1996 | | (NONE) | | | ARX3411 (GEN) | 590 |
| 5962-8757904ZA | L | 06/20/1996 | | (NONE) | | | ARX3431 (GEN) | 590 |
| 5962-8757905XA | L | 06/20/1996 | 1 | NATIONAL HYB | | Y | NHI-1500 | 590 |
| 5962-8757905XC | L | 06/20/1996 | 1 | NATIONAL HYB | | Y | NHI-1500 | 590 |
| 5962-8757905YA | L | 06/20/1996 | 1 | NATIONAL HYB | | Y | NHI-1500FP | 590 |
| 5962-8757905YC | L | 06/20/1996 | 1 | NATIONAL HYB | | Y | NHI-1500FP | 590 |
| 5962-8757906XA | L | 06/20/1996 | 1 | CMAC MICRO. | | Y | FC1553623 | 590 |
| 5962-8757906XC | L | 06/20/1996 | 1 | CMAC MICRO. | | Y | FC1553623 | 590 |
| 5962-8757906YA | L | 06/20/1996 | 1 | CMAC MICRO. | | Y | FC1553623FP | 590 |
| 5962-8757906YC | L | 06/20/1996 | 1 | CMAC MICRO. | | Y | FC1553623FP | 590 |
| 5962-8757907XA | L | 06/20/1996 | | (NONE) | | | CT1487D (GEN) | 590 |
| 5962-8757907YA | L | 06/20/1996 | | (NONE) | | | CT1487D (GEN) | 590 |
| 5962-8757908XA | L | 06/20/1996 | | (NONE) | | | MR63125M (GEN) | 590 |
| 5962-8757908YA | L | 06/20/1996 | | (NONE) | | | MR63125M (GEN) | 590 |
| 5962-8757909XA | L | 06/20/1996 | 1 | CMAC MICRO. | | Y | FC1553621 | 590 |
| 5962-8757909XC | L | 06/20/1996 | 1 | CMAC MICRO. | | Y | FC1553621 | 590 |
| 5962-8757909YA | L | 06/20/1996 | 1 | CMAC MICRO. | | Y | FC1553621FP | 590 |
| 5962-8757909YC | L | 06/20/1996 | 1 | CMAC MICRO. | | Y | FC1553621FP | 590 |
| 5962-8757910XA | L | 06/20/1996 | 1 | AEROFLEX | | Y | ACT4487-D | 590 |
| 5962-8757910XC | L | 06/20/1996 | 1 | AEROFLEX | | Y | ACT4487-D | 590 |
| 5962-8757910YA | L | 06/20/1996 | 1 | AEROFLEX | | Y | ACT4487-DF | 590 |
| 5962-8757910YC | L | 06/20/1996 | 1 | AEROFLEX | | Y | ACT4487-DF | 590 |
| 5962-87590012A | B | 12/09/1991 | | (NONE) | 09/30/1995 | | 10H416 (GEN) | 305 |
| 5962-8759001EA | B | 12/09/1991 | | (NONE) | 09/30/1995 | | 10H416 (GEN) | 305 |
| 5962-8759001FA | B | 12/09/1991 | | (NONE) | 09/30/1995 | | 10H416 (GEN) | 305 |
| 5962-87591013C | C | 08/30/2001 | 1 | MAXIM INTEG. | | | MX7572SE12/883B | 592 |
| 5962-8759101LA | C | 08/30/2001 | 0 | ANALOG (3) | | Y | AD7572SQ12/883B | 592 |
| 5962-8759101LA | C | 08/30/2001 | 1 | MAXIM INTEG. | | | MX7572SQ12/883B | 592 |
| 5962-87591023A | C | 08/30/2001 | | (NONE) | | | AD7572T (GEN) | 592 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-8759102LA | C | 08/30/2001 | | (NONE) | | | AD7572T (GEN) | 592 |
| 5962-87591033A | C | 08/30/2001 | | (NONE) | | | AD7572U (GEN) | 592 |
| 5962-8759103LA | C | 08/30/2001 | | (NONE) | | | AD7572U (GEN) | 592 |
| 5962-87591043A | C | 08/30/2001 | 1 | ANALOG (3) | | Y | AD7572SE05/883B | 592 |
| 5962-87591043C | C | 08/30/2001 | 1 | MAXIM INTEG. | | | MX7572SE05/883B | 592 |
| 5962-8759104LA | C | 08/30/2001 | 0 | ANALOG (3) | | Y | AD7572SQ05/883B | 592 |
| 5962-8759104LA | C | 08/30/2001 | 1 | MAXIM INTEG. | | | MX7572SQ05/883B | 592 |
| 5962-87591053A | C | 08/30/2001 | 1 | ANALOG (3) | | Y | AD7572TE05/883B | 592 |
| 5962-8759105LA | C | 08/30/2001 | 0 | ANALOG (3) | | Y | AD7572TQ05/883B | 592 |
| 5962-87591063A | C | 08/30/2001 | | (NONE) | | | AD7572U (GEN) | 592 |
| 5962-8759106LA | C | 08/30/2001 | | (NONE) | | | AD7572U (GEN) | 592 |
| 5962-8759201KA | B | 09/29/2000 | | (NONE) | | | 9150-25 (GEN) | 612 |
| 5962-8759201LA | B | 09/29/2000 | | (NONE) | | | 9150-25 (GEN) | 612 |
| 5962-8759201XA | B | 09/29/2000 | | (NONE) | | | 9150-25 (GEN) | 612 |
| 5962-8759202KA | B | 09/29/2000 | | (NONE) | | | 9150-35 (GEN) | 612 |
| 5962-8759202LA | B | 09/29/2000 | | (NONE) | | | 9150-35 (GEN) | 612 |
| 5962-8759202XA | B | 09/29/2000 | | (NONE) | | | 9150-35 (GEN) | 612 |
| 5962-8759203KA | B | 09/29/2000 | | (NONE) | | | 9150-45 (GEN) | 612 |
| 5962-8759203LA | B | 09/29/2000 | | (NONE) | | | 9150-45 (GEN) | 612 |
| 5962-8759203XA | B | 09/29/2000 | | (NONE) | | | 9150-45 (GEN) | 612 |
| 5962-8759301QA | B | 09/19/2000 | 1 | ROCHESTER | | Y | MD8155H/BQA | 610 |
| 5962-8759302QA | B | 09/19/2000 | | (NONE) | | | 8156 (GEN) | 610 |
| 5962-87594012A | E | 12/06/2002 | 3 | NATIONAL | | Y | LM185E1.2/883 | 785 |
| 5962-8759401XA | E | 12/06/2002 | 3 | NATIONAL | | Y | LM185H-1.2/883 | 785 |
| 5962-8759401VYA | E | 12/06/2002 | 3 | NATIONAL | | Y | LM185WG-1.2-QV | 785 |
| 5962-8759401YA | E | 12/06/2002 | 3 | NATIONAL | | Y | LM185WG-1.2/883 | 785 |
| 5962-87594022A | E | 12/06/2002 | | (NONE) | 03/09/1999 | | LM185-2.5 (GEN) | 785 |
| 5962-8759402XA | E | 12/06/2002 | 3 | NATIONAL | | Y | LM185H-2.5/883 | 785 |
| 5962-8759402VYA | E | 12/06/2002 | 3 | NATIONAL | | Y | LM185WG-2.5-QV | 785 |
| 5962-8759402YA | E | 12/06/2002 | 3 | NATIONAL | | Y | LM185WG-2.5/883 | 785 |
| 5962-8759403XA | E | 12/06/2002 | | (NONE) | | | LM185BX1.2 (GEN) | 785 |
| 5962-8759404XA | E | 12/06/2002 | | (NONE) | | | LM185BX2.5 (GEN) | 785 |
| 5962-8759405XA | E | 12/06/2002 | 3 | NATIONAL | | Y | LM185BYH1.2/883 | 785 |
| 5962-8759406VXA | E | 12/06/2002 | 3 | NATIONAL | | Y | LM185BYH2.5-QV | 785 |
| 5962-8759406XA | E | 12/06/2002 | 3 | NATIONAL | | Y | LM185BYH2.5/883 | 785 |
| 5962-87595013A | B | 09/25/2001 | 2 | TI | | | SNJ54AS646FK | 590 |
| 5962-8759501KA | B | 09/25/2001 | 2 | TI | | | SNJ54AS646W | 590 |
| 5962-8759501LA | B | 09/25/2001 | 2 | TI | | | SNJ54AS646JT | 590 |
| 5962-87596012A | B | 05/15/1992 | | (NONE) | | | 26LS34 (GEN) | 575 |
| 5962-8759601EA | B | 05/15/1992 | | (NONE) | 12/01/1993 | | 26LS34 (GEN) | 575 |
| 5962-8759601FA | B | 05/15/1992 | | (NONE) | | | 26LS34 (GEN) | 575 |
| 5962-8759701XA | A | 03/30/2000 | 1 | QP SEMI | | Y | 9519A/XA | 420 |
| 5962-8759701XA | A | 03/30/2000 | 1 | ROCHESTER | | Y | 9519A/BXA | 420 |
| 5962-8759701YA | A | 03/30/2000 | 1 | QP SEMI | | Y | 9519A/YA | 420 |
| 5962-8759701YA | A | 03/30/2000 | 1 | ROCHESTER | | Y | 9519A/BYA | 420 |
| 5962-8759801EA | | 01/05/1988 | | (NONE) | | | 3183A (GEN) | 790 |
| 5962-87600013A | | 12/08/1987 | | (NONE) | | | TDC1048 (GEN) | 592 |
| 5962-8760001XA | | 12/08/1987 | | (NONE) | | | TDC1048 (GEN) | 592 |
| 5962-8760201UA | A | 07/26/1988 | | (NONE) | | | 2960 (GEN) | 355 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-8760201XA | A | 07/26/1988 | | (NONE) | 06/30/1994 | | 2960 (GEN) | 355 |
| 5962-8760201YA | A | 07/26/1988 | | (NONE) | | | 2960 (GEN) | 355 |
| 5962-8760201ZA | A | 07/26/1988 | | (NONE) | | | 2960 (GEN) | 355 |
| 5962-87603013A | B | 11/02/1992 | | (NONE) | 08/04/1995 | | 29C841 (GEN) | 342 |
| 5962-8760301KA | B | 11/02/1992 | | (NONE) | 08/04/1995 | | 29C841 (GEN) | 342 |
| 5962-8760301LA | B | 11/02/1992 | | (NONE) | 08/04/1995 | | 29C841 (GEN) | 342 |
| 5962-87603023A | B | 11/02/1992 | | (NONE) | 08/04/1995 | | 29C843 (GEN) | 342 |
| 5962-8760302KA | B | 11/02/1992 | | (NONE) | 08/04/1995 | | 29C843 (GEN) | 342 |
| 5962-8760302LA | B | 11/02/1992 | | (NONE) | 08/04/1995 | | 29C843 (GEN) | 342 |
| 5962-8760303LA | B | 11/02/1992 | | (NONE) | | | 29C941 (GEN) | 342 |
| 5962-8760304LA | B | 11/02/1992 | | (NONE) | | | 29C943 (GEN) | 342 |
| 5962-87603053A | B | 11/02/1992 | | (NONE) | | | 29C841A (GEN) | 342 |
| 5962-8760305KA | B | 11/02/1992 | | (NONE) | | | 29C841A (GEN) | 342 |
| 5962-8760305LA | B | 11/02/1992 | | (NONE) | | | 29C841A (GEN) | 342 |
| 5962-87603063A | B | 11/02/1992 | | (NONE) | | | 29C843A (GEN) | 342 |
| 5962-8760306KA | B | 11/02/1992 | | (NONE) | | | 29C843A (GEN) | 342 |
| 5962-8760306LA | B | 11/02/1992 | | (NONE) | | | 29C843A (GEN) | 342 |
| 5962-8760401GA | E | 03/20/2003 | 1 | NATIONAL | | Y | LM10H/883B | 899 |
| 5962-8760401PA | E | 03/20/2003 | | (NONE) | 03/30/2001 | | LM10 (GEN) | 899 |
| 5962-8760501IA | A | 05/21/1990 | | (NONE) | | | LM104 (GEN) | 781 |
| 5962-8760601CA | A | 01/16/1990 | 1 | ROCHESTER | | Y | LM110J/883 | 711 |
| 5962-8760601GA | A | 01/16/1990 | 1 | ROCHESTER | | Y | LM110H/883 | 711 |
| 5962-8760601PA | A | 01/16/1990 | 1 | ROCHESTER | | Y | LM110J-8/883 | 711 |
| 5962-8760701GA | A | 09/03/1987 | | (NONE) | | | LM131A (GEN) | 593 |
| 5962-8760801GA | E | 05/12/2003 | 1 | NATIONAL | | Y | LF198H/883 | 818 |
| 5962-8760801QZA | E | 05/12/2003 | 1 | NATIONAL | | Y | LF198WG/883 | 818 |
| 5962-8760801VZA | E | 05/12/2003 | 1 | NATIONAL | | Y | LF198WG-QMLV | 818 |
| 5962-8760802PA | E | 05/12/2003 | | (NONE) | | | 5537 (GEN) | 818 |
| 5962-87609012A | D | 08/20/2004 | 3 | NATIONAL | | Y | 54AC04LMQB | 143 |
| 5962-87609012A | D | 08/20/2004 | 3 | TI | | Y | SNJ54AC04FK | 143 |
| 5962-8760901CA | D | 08/20/2004 | 3 | NATIONAL | | Y | 54AC04DMQB | 143 |
| 5962-8760901CA | D | 08/20/2004 | 3 | TI | | Y | SNJ54AC04J | 143 |
| 5962-8760901DA | D | 08/20/2004 | 3 | NATIONAL | | Y | 54AC04FMQB | 143 |
| 5962-8760901DA | D | 08/20/2004 | 3 | TI | | Y | SNJ54AC04W | 143 |
| 5962-8760901VXA | D | 08/20/2004 | 2 | STMICRO | | Y | 54AC04K02V | 143 |
| 5962-8760901VXC | D | 08/20/2004 | 2 | STMICRO | | Y | 54AC04K01V | 143 |
| 5962-8760901XA | D | 08/20/2004 | 2 | STMICRO | | Y | 54AC04K02Q | 143 |
| 5962-8760901XC | D | 08/20/2004 | 2 | STMICRO | | Y | 54AC04K01Q | 143 |
| 5962F8760901VXA | D | 08/20/2004 | 2 | STMICRO | | Y | RHFAC04K02V | 143 |
| 5962F8760901VXC | D | 08/20/2004 | 2 | STMICRO | | Y | RHFAC04K01V | 143 |
| 5962F8760901XA | D | 08/20/2004 | 2 | STMICRO | | Y | RHFAC04K02Q | 143 |
| 5962F8760901XC | D | 08/20/2004 | 2 | STMICRO | | Y | RHFAC04K01Q | 143 |
| 5962-87609022A | D | 08/20/2004 | 1 | ROCHESTER | | Y | 54AC11004/B2A | 143 |
| 5962-8760902RA | D | 08/20/2004 | 1 | ROCHESTER | | Y | 54AC11004/BRA | 143 |
| 5962-8760902SA | D | 08/20/2004 | 1 | ROCHESTER | | Y | 54AC11004/BSA | 143 |
| 5962-87610012A | B | 11/01/2000 | 3 | NATIONAL | | Y | 54AC10LMQB | 102 |
| 5962-87610012A | B | 11/01/2000 | 2 | TI | | Y | SNJ54AC10FK | 102 |
| 5962-8761001CA | B | 11/01/2000 | 3 | NATIONAL | | Y | 54AC10DMQB | 102 |
| 5962-8761001CA | B | 11/01/2000 | 2 | TI | | Y | SNJ54AC10J | 102 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-8761001DA | B | 11/01/2000 | 3 | NATIONAL | | Y | 54AC10FMQB | 102 |
| 5962-8761001DA | B | 11/01/2000 | 2 | TI | | Y | SNJ54AC10W | 102 |
| 5962-8761001VXA | B | 11/01/2000 | 2 | STMICRO | | Y | 54AC10K02V | 102 |
| 5962-8761001VXC | B | 11/01/2000 | 2 | STMICRO | | Y | 54AC10K01V | 102 |
| 5962-8761001XA | B | 11/01/2000 | 2 | STMICRO | | Y | 54AC10K02Q | 102 |
| 5962-8761001XC | B | 11/01/2000 | 2 | STMICRO | | Y | 54AC10K01Q | 102 |
| 5962F8761001VXA | B | 11/01/2000 | 2 | STMICRO | | Y | RHFAC10K02V | 102 |
| 5962F8761001VXC | B | 11/01/2000 | 2 | STMICRO | | Y | RHFAC10K01V | 102 |
| 5962F8761001XA | B | 11/01/2000 | 2 | STMICRO | | Y | RHFAC10K02Q | 102 |
| 5962F8761001XC | B | 11/01/2000 | 2 | STMICRO | | Y | RHFAC10K01Q | 102 |
| 5962-87610022A | B | 11/01/2000 | | (NONE) | 09/15/1995 | | 54AC11010 (GEN) | 102 |
| 5962-8761002EA | B | 11/01/2000 | | (NONE) | 09/15/1995 | | 54AC11010 (GEN) | 102 |
| 5962-8761002FA | B | 11/01/2000 | | (NONE) | 09/15/1995 | | 54AC11010 (GEN) | 102 |
| 5962-87611012A | C | 05/17/2004 | 3 | NATIONAL | | Y | 54AC11LMQB | 112 |
| 5962-87611012A | C | 05/17/2004 | 2 | TI | | Y | SNJ54AC11FK | 112 |
| 5962-8761101CA | C | 05/17/2004 | 3 | NATIONAL | | Y | 54AC11DMQB | 112 |
| 5962-8761101CA | C | 05/17/2004 | 2 | TI | | Y | SNJ54AC11J | 112 |
| 5962-8761101DA | C | 05/17/2004 | 3 | NATIONAL | | Y | 54AC11FMQB | 112 |
| 5962-8761101DA | C | 05/17/2004 | 2 | TI | | Y | SNJ54AC11W | 112 |
| 5962-8761101VXA | C | 05/17/2004 | 2 | STMICRO | | Y | 54AC11K02V | 112 |
| 5962-8761101VXC | C | 05/17/2004 | 2 | STMICRO | | Y | 54AC11K01V | 112 |
| 5962-8761101XA | C | 05/17/2004 | 2 | STMICRO | | Y | 54AC11K02Q | 112 |
| 5962-8761101XC | C | 05/17/2004 | 2 | STMICRO | | Y | 54AC11K01Q | 112 |
| 5962F8761101VXA | C | 05/17/2004 | 2 | STMICRO | | Y | RHFAC11K02V | 112 |
| 5962F8761101VXC | C | 05/17/2004 | 2 | STMICRO | | Y | RHFAC11K01V | 112 |
| 5962F8761101XA | C | 05/17/2004 | 2 | STMICRO | | Y | RHFAC11K02Q | 112 |
| 5962F8761101XC | C | 05/17/2004 | 2 | STMICRO | | Y | RHFAC11K01Q | 112 |
| 5962-87611022A | C | 05/17/2004 | 1 | ROCHESTER | | | 54AC11011/B2A | 112 |
| 5962-8761102EA | C | 05/17/2004 | 1 | ROCHESTER | | | 54AC11011/BEA | 112 |
| 5962-8761102FA | C | 05/17/2004 | 1 | ROCHESTER | | | 54AC11011/BFA | 112 |
| 5962-87612012A | C | 10/23/2000 | 2 | NATIONAL | | Y | 54AC02LMQB | 120 |
| 5962-8761201CA | C | 10/23/2000 | 2 | NATIONAL | | Y | 54AC02DMQB | 120 |
| 5962-8761201DA | C | 10/23/2000 | 2 | NATIONAL | | Y | 54AC02FMQB | 120 |
| 5962-8761201VXA | C | 10/23/2000 | 2 | STMICRO | | Y | 54AC02K02V | 120 |
| 5962-8761201VXC | C | 10/23/2000 | 2 | STMICRO | | Y | 54AC02K01V | 120 |
| 5962-8761201XA | C | 10/23/2000 | 2 | STMICRO | | Y | 54AC02K02Q | 120 |
| 5962-8761201XC | C | 10/23/2000 | 2 | STMICRO | | Y | 54AC02K01Q | 120 |
| 5962-87612022A | C | 10/23/2000 | | (NONE) | 09/15/1995 | | 54AC11002 (GEN) | 120 |
| 5962-8761202EA | C | 10/23/2000 | | (NONE) | 09/15/1995 | | 54AC11002 (GEN) | 120 |
| 5962-8761202FA | C | 10/23/2000 | | (NONE) | 09/15/1995 | | 54AC11002 (GEN) | 120 |
| 5962-87613012A | B | 06/19/2002 | 2 | NATIONAL | | Y | 54AC20LMQB | 104 |
| 5962-8761301CA | B | 06/19/2002 | 2 | NATIONAL | | Y | 54AC20DMQB | 104 |
| 5962-8761301DA | B | 06/19/2002 | 2 | NATIONAL | | Y | 54AC20FMQB | 104 |
| 5962-87613022A | B | 06/19/2002 | | (NONE) | 09/15/1995 | | 54AC11020 (GEN) | 104 |
| 5962-8761302CA | B | 06/19/2002 | | (NONE) | 09/15/1995 | | 54AC11020 (GEN) | 104 |
| 5962-8761302DA | B | 06/19/2002 | | (NONE) | 09/15/1995 | | 54AC11020 (GEN) | 104 |
| 5962-8761303VXA | B | 06/19/2002 | 2 | STMICRO | | Y | 54AC20K02V | 104 |
| 5962-8761303VXC | B | 06/19/2002 | 2 | STMICRO | | Y | 54AC20K01V | 104 |
| 5962-8761303XA | B | 06/19/2002 | 2 | STMICRO | | Y | 54AC20K02Q | 104 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-8761303XC | B | 06/19/2002 | 2 | STMICRO | | Y | 54AC20K01Q | 104 |
| 5962-87614012A | F | 12/09/2003 | 3 | NATIONAL | | Y | 54AC32LMQB | 125 |
| 5962-87614012A | F | 12/09/2003 | 2 | TI | | Y | SNJ54AC32FK | 125 |
| 5962-8761401CA | F | 12/09/2003 | 3 | NATIONAL | | Y | 54AC32DMQB | 125 |
| 5962-8761401CA | F | 12/09/2003 | 2 | TI | | Y | SNJ54AC32J | 125 |
| 5962-8761401DA | F | 12/09/2003 | 3 | NATIONAL | | Y | 54AC32FMQB | 125 |
| 5962-8761401DA | F | 12/09/2003 | 2 | TI | | Y | SNJ54AC32W | 125 |
| 5962-8761401VDA | F | 12/09/2003 | | (NONE) | | | 54AC32 (GEN) | 125 |
| 5962-8761401VXA | F | 12/09/2003 | 2 | STMICRO | | Y | 54AC32K02V | 125 |
| 5962-8761401VXC | F | 12/09/2003 | 2 | STMICRO | | Y | 54AC32K01V | 125 |
| 5962-8761401XA | F | 12/09/2003 | 2 | STMICRO | | Y | 54AC32K02Q | 125 |
| 5962-8761401XC | F | 12/09/2003 | 2 | STMICRO | | Y | 54AC32K01Q | 125 |
| 5962F8761401VXA | F | 12/09/2003 | 2 | STMICRO | | Y | RHFAC32K02V | 125 |
| 5962F8761401VXC | F | 12/09/2003 | 2 | STMICRO | | Y | RHFAC32K01V | 125 |
| 5962F8761401XA | F | 12/09/2003 | 2 | STMICRO | | Y | RHFAC32K02Q | 125 |
| 5962F8761401XC | F | 12/09/2003 | 2 | STMICRO | | Y | RHFAC32K01Q | 125 |
| 5962-87614022A | F | 12/09/2003 | | (NONE) | 09/15/1995 | | 54AC11032 (GEN) | 125 |
| 5962-8761402EA | F | 12/09/2003 | | (NONE) | 09/15/1995 | | 54AC11032 (GEN) | 125 |
| 5962-87615012A | D | 12/09/2003 | 3 | NATIONAL | | Y | 54AC08LMQB | 110 |
| 5962-87615012A | D | 12/09/2003 | 2 | TI | | Y | SNJ54AC08FK | 110 |
| 5962-8761501CA | D | 12/09/2003 | 3 | NATIONAL | | Y | 54AC08DMQB | 110 |
| 5962-8761501CA | D | 12/09/2003 | 2 | TI | | Y | SNJ54AC08J | 110 |
| 5962-8761501DA | D | 12/09/2003 | 3 | NATIONAL | | Y | 54AC08FMQB | 110 |
| 5962-8761501DA | D | 12/09/2003 | 2 | TI | | Y | SNJ54AC08W | 110 |
| 5962-8761501VXA | D | 12/09/2003 | 2 | STMICRO | | Y | 54AC08K02V | 110 |
| 5962-8761501VXC | D | 12/09/2003 | 2 | STMICRO | | Y | 54AC08K01V | 110 |
| 5962-8761501XA | D | 12/09/2003 | 2 | STMICRO | | Y | 54AC08K02Q | 110 |
| 5962-8761501XC | D | 12/09/2003 | 2 | STMICRO | | Y | 54AC08K01Q | 110 |
| 5962F8761501VXA | D | 12/09/2003 | 2 | STMICRO | | Y | RHFAC08K02V | 110 |
| 5962F8761501VXC | D | 12/09/2003 | 2 | STMICRO | | Y | RHFAC08K01V | 110 |
| 5962F8761501XA | D | 12/09/2003 | 2 | STMICRO | | Y | RHFAC08K02Q | 110 |
| 5962F8761501XC | D | 12/09/2003 | 2 | STMICRO | | Y | RHFAC08K01Q | 110 |
| 5962-87615022A | D | 12/09/2003 | | (NONE) | 09/15/1995 | | 54AC11008 (GEN) | 110 |
| 5962-8761502EA | D | 12/09/2003 | | (NONE) | 09/15/1995 | | 54AC11008 (GEN) | 110 |
| 5962-87616012A | A | 05/15/1992 | | (NONE) | 12/01/1993 | | 26LS32B (GEN) | 575 |
| 5962-8761601EA | A | 05/15/1992 | | (NONE) | 12/01/1993 | | 26LS32B (GEN) | 575 |
| 5962-8761601FA | A | 05/15/1992 | | (NONE) | 12/01/1993 | | 26LS32B (GEN) | 575 |
| 5962-8761701XA | D | 02/19/1999 | 1 | CMAC MICRO. | | Y | 11563-DESC | 509 |
| 5962-8761701XA | D | 02/19/1999 | 1 | MICROPAC | | Y | 51992 | 509 |
| 5962-8761701XA | D | 02/19/1999 | 1 | MS KENNEDY | | Y | MSK 0006H | 509 |
| 5962-8761701XC | D | 02/19/1999 | 1 | CMAC MICRO. | | Y | 11563-DESC | 509 |
| 5962-8761701XC | D | 02/19/1999 | 1 | MICROPAC | | Y | 51992 | 509 |
| 5962-8761701XC | D | 02/19/1999 | 1 | MS KENNEDY | | Y | MSK 0006H | 509 |
| 5962-8761701YA | D | 02/19/1999 | 1 | CMAC MICRO. | | Y | 11105-DESC | 509 |
| 5962-8761701YC | D | 02/19/1999 | 1 | CMAC MICRO. | | Y | 11105-DESC | 509 |
| 5962-8761702XA | D | 02/19/1999 | 1 | MS KENNEDY | | Y | MSK 0008H | 509 |
| 5962-8761702XC | D | 02/19/1999 | 1 | MS KENNEDY | | Y | MSK 0008H | 509 |
| 5962-8761801VA | A | 01/06/1993 | | (NONE) | 12/24/2000 | | HI-524 (GEN) | 199 |
| 5962-87619012A | G | 11/07/2002 | 1 | TI | | Y | UC1707L/81032 | 787 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-8761901V2A | G | 11/07/2002 | 1 | TI | | Y | UC1707LQMLV | 787 |
| 5962-8761901EA | G | 11/07/2002 | 1 | TI | | Y | UC1707J/80900 | 787 |
| 5962-8761901VEA | G | 11/07/2002 | 1 | TI | | Y | UC1707JQMLV | 787 |
| 5962-8761902NXB | G | 11/07/2002 | | (NONE) | | | UC2707 (GEN) | 787 |
| 5962-8761902NYB | G | 11/07/2002 | | (NONE) | | | UC2707 (GEN) | 787 |
| 5962-8762001XA | D | 09/25/2003 | 1 | MICROPAC | | Y | 42106 | 753 |
| 5962-8762001XC | D | 09/25/2003 | 1 | MICROPAC | | Y | 42106 | 753 |
| 5962-8762001YA | D | 09/25/2003 | 1 | APEX MICRO. | | Y | PA51M/883 | 753 |
| 5962-8762002XA | D | 09/25/2003 | 1 | MICROPAC | | Y | 42106-1 | 753 |
| 5962-8762002XC | D | 09/25/2003 | 1 | MICROPAC | | Y | 42106-1 | 753 |
| 5962-8762002YA | D | 09/25/2003 | 1 | APEX MICRO. | | Y | PA51M/883 | 753 |
| 5962-87621012A | | 09/14/1987 | 1 | TI | | Y | SNJ54LS592FK | 304 |
| 5962-8762101EA | | 09/14/1987 | 1 | TI | | Y | SNJ54LS592J | 304 |
| 5962-8762101FA | | 09/14/1987 | 1 | TI | | Y | SNJ54LS592W | 304 |
| 5962-87622012A | D | 05/14/2004 | 3 | NATIONAL | | Y | 54AC138LMQB | 282 |
| 5962-8762201EA | D | 05/14/2004 | 3 | NATIONAL | | Y | 54AC138DMQB | 282 |
| 5962-8762201FA | D | 05/14/2004 | 3 | NATIONAL | | Y | 54AC138FMQB | 282 |
| 5962-8762201VXA | D | 05/14/2004 | 2 | STMICRO | | Y | 54AC138K02V | 282 |
| 5962-8762201VXC | D | 05/14/2004 | 2 | STMICRO | | Y | 54AC138K01V | 282 |
| 5962-8762201XA | D | 05/14/2004 | 2 | STMICRO | | Y | 54AC138K02Q | 282 |
| 5962-8762201XC | D | 05/14/2004 | 2 | STMICRO | | Y | 54AC138K01Q | 282 |
| 5962F8762201VXA | D | 05/14/2004 | 2 | STMICRO | | Y | RHFAC138K02V | 282 |
| 5962F8762201VXC | D | 05/14/2004 | 2 | STMICRO | | Y | RHFAC138K01V | 282 |
| 5962F8762201XA | D | 05/14/2004 | 2 | STMICRO | | Y | RHFAC138K02Q | 282 |
| 5962F8762201XC | D | 05/14/2004 | 2 | STMICRO | | Y | RHFAC138K01Q | 282 |
| 5962-87623012A | A | 09/05/2001 | 3 | NATIONAL | | Y | 54AC139LMQB | 283 |
| 5962-8762301EA | A | 09/05/2001 | 3 | NATIONAL | | Y | 54AC139DMQB | 283 |
| 5962-8762301FA | A | 09/05/2001 | 3 | NATIONAL | | Y | 54AC139FMQB | 283 |
| 5962-8762301VXA | A | 09/05/2001 | 2 | STMICRO | | Y | 54AC139K02V | 283 |
| 5962-8762301VXC | A | 09/05/2001 | 2 | STMICRO | | Y | 54AC139K01V | 283 |
| 5962-8762301XA | A | 09/05/2001 | 2 | STMICRO | | Y | 54AC139K02Q | 283 |
| 5962-8762301XC | A | 09/05/2001 | 2 | STMICRO | | Y | 54AC139K01Q | 283 |
| 5962F8762301VXA | A | 09/05/2001 | 2 | STMICRO | | Y | RHFAC139K02V | 283 |
| 5962F8762301VXC | A | 09/05/2001 | 2 | STMICRO | | Y | RHFAC139K01V | 283 |
| 5962F8762301XA | A | 09/05/2001 | 2 | STMICRO | | Y | RHFAC139K02Q | 283 |
| 5962F8762301XC | A | 09/05/2001 | 2 | STMICRO | | Y | RHFAC139K01Q | 283 |
| 5962-87624012A | A | 07/12/2000 | 3 | NATIONAL | | Y | 54AC14LMQB | 143 |
| 5962-87624012A | A | 07/12/2000 | 3 | TI | | Y | SNJ54AC14FK | 143 |
| 5962-8762401CA | A | 07/12/2000 | 3 | NATIONAL | | Y | 54AC14DMQB | 143 |
| 5962-8762401CA | A | 07/12/2000 | 3 | TI | | Y | SNJ54AC14J | 143 |
| 5962-8762401VCA | A | 07/12/2000 | 3 | TI | | Y | SNV54AC14J | 143 |
| 5962-8762401DA | A | 07/12/2000 | 3 | NATIONAL | | Y | 54AC14FMQB | 143 |
| 5962-8762401DA | A | 07/12/2000 | 3 | TI | | Y | SNJ54AC14W | 143 |
| 5962-8762401VDA | A | 07/12/2000 | 3 | TI | | Y | SNV54AC14W | 143 |
| 5962-8762401VXA | A | 07/12/2000 | 2 | STMICRO | | Y | 54AC14K02Q | 143 |
| 5962-8762401VXC | A | 07/12/2000 | 2 | STMICRO | | Y | 54AC14K01Q | 143 |
| 5962-8762401XA | A | 07/12/2000 | 2 | STMICRO | | Y | 54AC14K02Q | 143 |
| 5962-8762401XC | A | 07/12/2000 | 2 | STMICRO | | Y | 54AC14K01Q | 143 |
| 5962-87625012A | A | 06/05/1993 | 2 | NATIONAL | | Y | 54AC153LMQB | 273 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-8762501EA | A | 06/05/1993 | 2 | NATIONAL | | Y | 54AC153DMQB | 273 |
| 5962-8762501FA | A | 06/05/1993 | 2 | NATIONAL | | Y | 54AC153FMQB | 273 |
| 5962-87626012A | A | 07/18/2002 | 3 | NATIONAL | | Y | 54AC174LMQB | 159 |
| 5962-8762601EA | A | 07/18/2002 | 3 | NATIONAL | | Y | 54AC174DMQB | 159 |
| 5962-8762601FA | A | 07/18/2002 | 3 | NATIONAL | | Y | 54AC174FMQB | 159 |
| 5962-8762602VXA | A | 07/18/2002 | 2 | STMICRO | | Y | 54AC174K02V | 159 |
| 5962-8762602VXC | A | 07/18/2002 | 2 | STMICRO | | Y | 54AC174K01V | 159 |
| 5962-8762602XA | A | 07/18/2002 | 2 | STMICRO | | Y | 54AC174K02Q | 159 |
| 5962-8762602XC | A | 07/18/2002 | 2 | STMICRO | | Y | 54AC174K01Q | 159 |
| 5962-87627012A | B | 11/25/1991 | 3 | NATIONAL | | Y | 54FCT377LMQB | 159 |
| 5962-8762701RA | B | 11/25/1991 | 3 | NATIONAL | | Y | 54FCT377DMQB | 159 |
| 5962-8762701SA | B | 11/25/1991 | 3 | NATIONAL | | Y | 54FCT377FMQB | 159 |
| 5962-87627022A | B | 11/25/1991 | | (NONE) | 09/01/1996 | | 54FCT377A (GEN) | 159 |
| 5962-8762702RA | B | 11/25/1991 | | (NONE) | 09/01/1996 | | 54FCT377A (GEN) | 159 |
| 5962-8762702SA | B | 11/25/1991 | | (NONE) | 09/01/1996 | | 54FCT377A (GEN) | 159 |
| 5962-87628012A | C | 11/29/1989 | 1 | IDT | | Y | IDT54FCT374LB | 159 |
| 5962-87628012A | C | 11/29/1989 | 2 | NATIONAL | | Y | 54FCT374LMQB | 159 |
| 5962-8762801RA | C | 11/29/1989 | 1 | IDT | | Y | IDT54FCT374DB | 159 |
| 5962-8762801RA | C | 11/29/1989 | 2 | NATIONAL | | Y | 54FCT374DMQB | 159 |
| 5962-8762801SA | C | 11/29/1989 | 2 | NATIONAL | | Y | 54FCT374FMQB | 159 |
| 5962-87628022A | C | 11/29/1989 | 1 | IDT | | Y | IDT54FCT374A | 159 |
| 5962-8762802RA | C | 11/29/1989 | 1 | IDT | | Y | IDT54FCT374ADB | 159 |
| 5962-8762802SA | C | 11/29/1989 | | (NONE) | 04/29/2002 | | 54FCT374A (GEN) | 159 |
| 5962-87629012A | D | 08/26/2003 | 2 | IDT | | Y | IDT54FCT245LB | 590 |
| 5962-87629012A | D | 08/26/2003 | 3 | NATIONAL | | Y | 54FCT245LMQB | 590 |
| 5962-8762901RA | D | 08/26/2003 | 2 | IDT | | Y | IDT54FCT245DB | 590 |
| 5962-8762901RA | D | 08/26/2003 | 3 | NATIONAL | | Y | 54FCT245DMQB | 590 |
| 5962-8762901SA | D | 08/26/2003 | 3 | NATIONAL | | Y | 54FCT245FMQB | 590 |
| 5962-87629022A | D | 08/26/2003 | 2 | IDT | | Y | IDT54FCT245ALB | 590 |
| 5962-8762902RA | D | 08/26/2003 | 2 | IDT | | Y | IDT54FCT245ADB | 590 |
| 5962-8762902SA | D | 08/26/2003 | | (NONE) | 04/29/2002 | | 54FCT245A (GEN) | 590 |
| 5962-87630012A | D | 08/26/2003 | 2 | IDT | | Y | IDT54FCT244LB | 529 |
| 5962-87630012A | D | 08/26/2003 | 2 | NATIONAL | | Y | 54FCT244LMQB | 529 |
| 5962-8763001RA | D | 08/26/2003 | 2 | IDT | | Y | IDT54FCT244DB | 529 |
| 5962-8763001RA | D | 08/26/2003 | 2 | NATIONAL | | Y | 54FCT244DMQB | 529 |
| 5962-8763001SA | D | 08/26/2003 | 2 | NATIONAL | | Y | 54FCT244FMQB | 529 |
| 5962-87630022A | D | 08/26/2003 | 2 | IDT | | Y | IDT54FCT244ALB | 529 |
| 5962-8763002RA | D | 08/26/2003 | 2 | IDT | | Y | IDT54FCT244ADB | 529 |
| 5962-8763002SA | D | 08/26/2003 | | (NONE) | 04/29/2002 | | 54FCT244A (GEN) | 529 |
| 5962-87631012A | B | 12/23/2002 | 2 | NATIONAL | | Y | 54ACT374LMQB | 159 |
| 5962-87631012A | B | 12/23/2002 | 2 | TI | | Y | SNJ54ACT374FK | 159 |
| 5962-8763101RA | B | 12/23/2002 | 2 | NATIONAL | | Y | 54ACT374DMQB | 159 |
| 5962-8763101RA | B | 12/23/2002 | 2 | TI | | Y | SNJ54ACT374J | 159 |
| 5962-8763101VRA | B | 12/23/2002 | 2 | TI | | Y | SNV54ACT374J | 159 |
| 5962-8763101SA | B | 12/23/2002 | 2 | NATIONAL | | Y | 54ACT374FMQB | 159 |
| 5962-8763101SA | B | 12/23/2002 | 2 | TI | | Y | SNJ54ACT374W | 159 |
| 5962-8763101VSA | B | 12/23/2002 | 2 | TI | | Y | SNV54ACT374W | 159 |
| 5962-87631023A | B | 12/23/2002 | 1 | ROCHESTER | | Y | 54ACT11374/B3A | 159 |
| 5962-8763102LA | B | 12/23/2002 | 1 | ROCHESTER | | Y | 54ACT11374/BLA | 159 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-8763103VXA | B | 12/23/2002 | 2 | STMICRO | | Y | 54ACT374K02V | 159 |
| 5962-8763103VXC | B | 12/23/2002 | 2 | STMICRO | | Y | 54ACT374K01V | 159 |
| 5962-8763103XA | B | 12/23/2002 | 2 | STMICRO | | Y | 54ACT374K02Q | 159 |
| 5962-8763103XC | B | 12/23/2002 | 2 | STMICRO | | Y | 54ACT374K01Q | 159 |
| 5962-8763201XA | | 08/29/1988 | | (NONE) | | | BUS-65111 (GEN) | 590 |
| 5962-8763301QA | F | 08/04/2003 | | (NONE) | 02/19/1998 | | 320C10 (GEN) | 432 |
| 5962-8763301XA | F | 08/04/2003 | | (NONE) | | | 320C10 (GEN) | 432 |
| 5962-8763302QA | F | 08/04/2003 | | (NONE) | 02/19/1998 | | 320C10-25 (GEN) | 432 |
| 5962-8763302XA | F | 08/04/2003 | | (NONE) | | | 320C10-25 (GEN) | 432 |
| 5962-8763303QA | F | 08/04/2003 | | (NONE) | 05/01/1998 | | 320CM10 (GEN) | 432 |
| 5962-8763303XA | F | 08/04/2003 | | (NONE) | 05/01/1998 | | 320CM10 (GEN) | 432 |
| 5962-8763304QA | F | 08/04/2003 | | (NONE) | 05/01/1998 | | 320CM10-25 (GEN) | 432 |
| 5962-8763304XA | F | 08/04/2003 | | (NONE) | 05/01/1998 | | 320CM10-25 (GEN) | 432 |
| 5962-8763305QA | F | 08/04/2003 | | (NONE) | | | 320C10-25 (GEN) | 432 |
| 5962-8763305XA | F | 08/04/2003 | | (NONE) | 05/01/1998 | | 320C10-25 (GEN) | 432 |
| 5962-8763306QA | F | 08/04/2003 | | (NONE) | | | 320E15 (GEN) | 432 |
| 5962-8763307QA | F | 08/04/2003 | | (NONE) | 02/19/1998 | | 320C15 (GEN) | 432 |
| 5962-8763307XA | F | 08/04/2003 | | (NONE) | | | 320C15 (GEN) | 432 |
| 5962-8763307YA | F | 08/04/2003 | | (NONE) | 02/19/1998 | | 320C15 (GEN) | 432 |
| 5962-8763308QA | F | 08/04/2003 | 2 | TI | | Y | SMJ320C15-25JDM | 432 |
| 5962-8763308XA | F | 08/04/2003 | | (NONE) | | | 320C15-25 (GEN) | 432 |
| 5962-8763308YA | F | 08/04/2003 | 2 | TI | | Y | SMJ320C15-25FJM | 432 |
| 5962-8763501RA | B | 08/20/2002 | 1 | ANALOG (2) | | Y | AD670SD/883B | 592 |
| 5962-8764001WA | B | 08/23/2002 | 1 | MICREL | | | MIC5801AJBQ | 599 |
| 5962-8764002CA | B | 08/23/2002 | | (NONE) | 03/31/1998 | | MIC5800 (GEN) | 599 |
| 5962-8764101EA | | 03/17/1988 | | (NONE) | 03/31/1998 | | MIC5822 (GEN) | 599 |
| 5962-87643012A | A | 11/15/1989 | | (NONE) | 09/30/1995 | | 3517 (GEN) | 804 |
| 5962-8764301EA | A | 11/15/1989 | | (NONE) | 09/30/1995 | | 3517 (GEN) | 804 |
| 5962-87644012A | B | 07/28/2003 | 2 | NATIONAL | | Y | 54FCT373LMQB | 341 |
| 5962-8764401RA | B | 07/28/2003 | 2 | NATIONAL | | Y | 54FCT373DMQB | 341 |
| 5962-8764401SA | B | 07/28/2003 | 2 | NATIONAL | | Y | 54FCT373FMQB | 341 |
| 5962-87644022A | B | 07/28/2003 | | (NONE) | 04/27/1998 | | 54FCT373A (GEN) | 341 |
| 5962-8764402RA | B | 07/28/2003 | | (NONE) | 04/27/1998 | | 54FCT373A (GEN) | 341 |
| 5962-8764402SA | B | 07/28/2003 | | (NONE) | 04/27/1998 | | 54FCT373A (GEN) | 341 |
| 5962-8764501EA | C | 08/27/2002 | 0 | MICROSEMI | | Y | SG1524BJ/883B | 787 |
| 5962-8764501EA | C | 08/27/2002 | 1 | SEMELAB | | Y | IP1524BJ-DESC | 787 |
| 5962-8764502EA | C | 08/27/2002 | 0 | TI | | Y | UC1524AJ/883B | 787 |
| 5962-8764601EA | | 02/03/1988 | | (NONE) | 09/30/1995 | | 14490A (GEN) | 399 |
| 5962-87647012A | A | 12/15/1992 | 1 | TI | | Y | SNJ54HC03FK | 101 |
| 5962-8764701CA | A | 12/15/1992 | 1 | TI | | Y | SNJ54HC03J | 101 |
| 5962-8764801XA | D | 07/07/1997 | 1 | AUSTIN SEMI. | | Y | SMJ27C512-15JM | 663 |
| 5962-8764801YA | D | 07/07/1997 | 1 | AUSTIN SEMI. | | Y | AS27C512-15ECAM | 663 |
| 5962-8764801ZA | D | 07/07/1997 | | (NONE) | 10/27/1995 | | 27C512-150 (GEN) | 663 |
| 5962-8764802XA | D | 07/07/1997 | 1 | AUSTIN SEMI. | | Y | SMJ27C512-20JM | 663 |
| 5962-8764802YA | D | 07/07/1997 | 1 | AUSTIN SEMI. | | Y | AS27C512-20ECAM | 663 |
| 5962-8764802ZA | D | 07/07/1997 | | (NONE) | 10/27/1995 | | 27C512-200 (GEN) | 663 |
| 5962-8764803XA | D | 07/07/1997 | 1 | AUSTIN SEMI. | | Y | SMJ27C512-25JM | 663 |
| 5962-8764803YA | D | 07/07/1997 | 1 | AUSTIN SEMI. | | Y | AS27C512-25ECAM | 663 |
| 5962-8764803ZA | D | 07/07/1997 | | (NONE) | 10/27/1995 | | 27C512-250 (GEN) | 663 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-8764804XA | D | 07/07/1997 | 1 | AUSTIN SEMI. | | Y | AS27C512-12JM | 663 |
| 5962-8764804YA | D | 07/07/1997 | 1 | AUSTIN SEMI. | | Y | AS27C512-12ECAM | 663 |
| 5962-8764804ZA | D | 07/07/1997 | | (NONE) | 10/27/1995 | | 27C512-120 (GEN) | 663 |
| 5962-8764805XA | D | 07/07/1997 | | (NONE) | 08/02/1996 | | 27C512-90 (GEN) | 663 |
| 5962-8764805YA | D | 07/07/1997 | | (NONE) | 08/02/1996 | | 27C512-90 (GEN) | 663 |
| 5962-8764805ZA | D | 07/07/1997 | | (NONE) | 10/27/1995 | | 27C512-90 (GEN) | 663 |
| 5962-8764806QXA | D | 07/07/1997 | | (NONE) | 08/12/2000 | | 27C512-70 (GEN) | 663 |
| 5962-8764806QYA | D | 07/07/1997 | | (NONE) | 08/12/2000 | | 27C512-70 (GEN) | 663 |
| 5962-8764807QXA | D | 07/07/1997 | | (NONE) | 08/12/2000 | | 27C512-55 (GEN) | 663 |
| 5962-8764807QYA | D | 07/07/1997 | | (NONE) | 08/12/2000 | | 27C512-55 (GEN) | 663 |
| 5962-8764808QXA | D | 07/07/1997 | | (NONE) | 08/12/2000 | | 27C512-45 (GEN) | 663 |
| 5962-8764808QYA | D | 07/07/1997 | | (NONE) | 08/12/2000 | | 27C512-45 (GEN) | 663 |
| 5962-8764809QXA | D | 07/07/1997 | | (NONE) | 08/12/2000 | | 27H512-35 (GEN) | 663 |
| 5962-8764809QYA | D | 07/07/1997 | | (NONE) | 08/12/2000 | | 27H512-35 (GEN) | 663 |
| 5962-8764810QXA | D | 07/07/1997 | | (NONE) | 08/12/2000 | | 27C512-90 (GEN) | 663 |
| 5962-8764810QYA | D | 07/07/1997 | | (NONE) | 08/12/2000 | | 27C512-90 (GEN) | 663 |
| 5962-8764811QXA | D | 07/07/1997 | 1 | AUSTIN SEMI. | | Y | AS27C512-12JM | 663 |
| 5962-8764811QYA | D | 07/07/1997 | 1 | AUSTIN SEMI. | | Y | AS27C512-12ECAM | 663 |
| 5962-8764812QXA | D | 07/07/1997 | 1 | AUSTIN SEMI. | | Y | AS27C512-15JM | 663 |
| 5962-8764812QYA | D | 07/07/1997 | 1 | AUSTIN SEMI. | | Y | AS27C512-15ECAM | 663 |
| 5962-8764813QXA | D | 07/07/1997 | 1 | AUSTIN SEMI. | | Y | AS27C512-20JM | 663 |
| 5962-8764813QYA | D | 07/07/1997 | 1 | AUSTIN SEMI. | | Y | AS27C512-20ECAM | 663 |
| 5962-8764814QXA | D | 07/07/1997 | 1 | AUSTIN SEMI. | | Y | AS27C512-25JM | 663 |
| 5962-8764814QYA | D | 07/07/1997 | 1 | AUSTIN SEMI. | | Y | AS27C512-25ECAM | 663 |
| 5962-8764901XA | | 01/19/1988 | | (NONE) | | | | 662 |
| 5962-8764901YA | | 01/19/1988 | | (NONE) | | | | 662 |
| 5962-8764901ZA | | 01/19/1988 | | (NONE) | | | | 662 |
| 5962-8764902XA | | 01/19/1988 | | (NONE) | | | | 662 |
| 5962-8764902YA | | 01/19/1988 | | (NONE) | | | | 662 |
| 5962-8764902ZA | | 01/19/1988 | | (NONE) | | | | 662 |
| 5962-8764903XA | | 01/19/1988 | | (NONE) | | | | 662 |
| 5962-8764903YA | | 01/19/1988 | | (NONE) | | | | 662 |
| 5962-8764903ZA | | 01/19/1988 | | (NONE) | | | | 662 |
| 5962-87650013A | E | 12/16/2002 | 1 | QP SEMI | | | WS57C291C-50CMB | 658 |
| 5962-87650013C | E | 12/16/2002 | 1 | QP SEMI | | | WS57C291C-50CMB | 658 |
| 5962-8765001JA | E | 12/16/2002 | 1 | QP SEMI | | | WS57C191C-50DMB | 658 |
| 5962-8765001KA | E | 12/16/2002 | 1 | QP SEMI | | | WS57C291C-50FMB | 658 |
| 5962-8765001LA | E | 12/16/2002 | 1 | QP SEMI | | | WS57C291C-50TMB | 658 |
| 5962-87650023A | E | 12/16/2002 | 1 | QP SEMI | | | WS57C291C-55CMB | 658 |
| 5962-87650023C | E | 12/16/2002 | 1 | QP SEMI | | | WS57C291C-55CMB | 658 |
| 5962-8765002JA | E | 12/16/2002 | 1 | QP SEMI | | | WS57C191C-55DMB | 658 |
| 5962-8765002KA | E | 12/16/2002 | 1 | QP SEMI | | | WS57C291C-55FMB | 658 |
| 5962-8765002LA | E | 12/16/2002 | 1 | QP SEMI | | | WS57C291C-55TMB | 658 |
| 5962-87650033A | E | 12/16/2002 | 1 | QP SEMI | | Y | 7C291-35/3A | 658 |
| 5962-87650033A | E | 12/16/2002 | 1 | QP SEMI | | | WS57C291C-35CMB | 658 |
| 5962-87650033C | E | 12/16/2002 | 1 | QP SEMI | | | WS57C291C-35CMB | 658 |
| 5962-8765003KA | E | 12/16/2002 | 1 | QP SEMI | | Y | 7C291-35/KA | 658 |
| 5962-8765003KA | E | 12/16/2002 | 1 | QP SEMI | | | WS57C291C-35FMB | 658 |
| 5962-8765003LA | E | 12/16/2002 | 1 | CYPRESS | | Y | CY7C291-35WMB | 658 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-8765003LA | E | 12/16/2002 | 1 | QP SEMI | | | WS57C291C-35TMB | 658 |
| 5962-87650043A | E | 12/16/2002 | 1 | QP SEMI | | | WS57C291C-45CMB | 658 |
| 5962-87650043C | E | 12/16/2002 | 1 | QP SEMI | | | WS57C291C-45CMB | 658 |
| 5962-8765004JA | E | 12/16/2002 | 1 | QP SEMI | | | WS57C191C-45DMB | 658 |
| 5962-8765004KA | E | 12/16/2002 | 1 | QP SEMI | | | WS57C291C-45FMB | 658 |
| 5962-8765004LA | E | 12/16/2002 | 1 | QP SEMI | | | WS57C291C-45TMB | 658 |
| 5962-87650053A | E | 12/16/2002 | 1 | QP SEMI | | Y | 7C291A-25/3A | 658 |
| 5962-87650053A | E | 12/16/2002 | 1 | QP SEMI | | | WS57C291C-25CMB | 658 |
| 5962-87650053C | E | 12/16/2002 | 1 | QP SEMI | | | WS57C291C-25CMB | 658 |
| 5962-8765005KA | E | 12/16/2002 | 1 | QP SEMI | | Y | 7C291A-25/KA | 658 |
| 5962-8765005KA | E | 12/16/2002 | 1 | QP SEMI | | | WS57C291C-25FMB | 658 |
| 5962-8765005LA | E | 12/16/2002 | 1 | QP SEMI | | | WS57C291C-25TMB | 658 |
| 5962-87651013A | B | 08/19/1994 | | (NONE) | | | | 657 |
| 5962-8765101JA | B | 08/19/1994 | | (NONE) | | | | 657 |
| 5962-8765101KA | B | 08/19/1994 | | (NONE) | | | | 657 |
| 5962-8765101LA | B | 08/19/1994 | | (NONE) | | | | 657 |
| 5962-87651023A | B | 08/19/1994 | 2 | QP SEMI | | Y | CY7C281A-45LMB | 657 |
| 5962-8765102JA | B | 08/19/1994 | 2 | QP SEMI | | Y | CY7C282A-45DMB | 657 |
| 5962-8765102KA | B | 08/19/1994 | 2 | QP SEMI | | Y | CY7C281A-45KMB | 657 |
| 5962-8765102LA | B | 08/19/1994 | 2 | QP SEMI | | Y | CY7C281A-45DMB | 657 |
| 5962-87651033A | B | 08/19/1994 | 2 | QP SEMI | | Y | CY7C281A-30LMB | 657 |
| 5962-8765103JA | B | 08/19/1994 | 2 | QP SEMI | | Y | CY7C282A-30DMB | 657 |
| 5962-8765103KA | B | 08/19/1994 | 2 | QP SEMI | | Y | CY7C281A-30KMB | 657 |
| 5962-8765103LA | B | 08/19/1994 | 2 | QP SEMI | | Y | CY7C281A-30LMB | 657 |
| 5962-8765301JA | A | 10/21/1991 | | (NONE) | 12/26/1999 | | ICM7170 (GEN) | 429 |
| 5962-87654012A | B | 07/22/1992 | 3 | NATIONAL | | Y | 54FCT138LMQB | 282 |
| 5962-8765401EA | B | 07/22/1992 | 3 | NATIONAL | | Y | 54FCT138DMQB | 282 |
| 5962-8765401FA | B | 07/22/1992 | 3 | NATIONAL | | Y | 54FCT138FMQB | 282 |
| 5962-87654022A | B | 07/22/1992 | | (NONE) | 04/27/1998 | | 54FCT138A (GEN) | 282 |
| 5962-8765402EA | B | 07/22/1992 | | (NONE) | 04/27/1998 | | 54FCT138A (GEN) | 282 |
| 5962-8765402FA | B | 07/22/1992 | | (NONE) | 04/27/1998 | | 54FCT138A (GEN) | 282 |
| 5962-87655012A | B | 08/22/2003 | 2 | NATIONAL | | Y | 54FCT240LMQB | 529 |
| 5962-8765501RA | B | 08/22/2003 | 2 | NATIONAL | | Y | 54FCT240DMQB | 529 |
| 5962-8765501SA | B | 08/22/2003 | 2 | NATIONAL | | Y | 54FCT240FMQB | 529 |
| 5962-87655022A | B | 08/22/2003 | | (NONE) | 04/27/1998 | | 54FCT240A (GEN) | 529 |
| 5962-8765502RA | B | 08/22/2003 | | (NONE) | 04/27/1998 | | 54FCT240A (GEN) | 529 |
| 5962-8765502SA | B | 08/22/2003 | | (NONE) | 04/27/1998 | | 54FCT240A (GEN) | 529 |
| 5962-87656012A | A | 12/07/1989 | 3 | NATIONAL | | Y | 54FCT273LMQB | 159 |
| 5962-8765601RA | A | 12/07/1989 | 3 | NATIONAL | | Y | 54FCT273DMQB | 159 |
| 5962-8765601SA | A | 12/07/1989 | 3 | NATIONAL | | Y | 54FCT273FMQB | 159 |
| 5962-87656022A | A | 12/07/1989 | | (NONE) | 04/27/1998 | | 54FCT273A (GEN) | 159 |
| 5962-8765602RA | A | 12/07/1989 | | (NONE) | 04/27/1998 | | 54FCT273A (GEN) | 159 |
| 5962-8765602SA | A | 12/07/1989 | | (NONE) | 04/27/1998 | | 54FCT273A (GEN) | 159 |
| 5962-8765701GA | B | 10/02/2001 | 1 | LANSDALE | | Y | ML1590/BGA | 755 |
| 5962-87658012A | B | 08/28/2002 | 1 | TI | | Y | TLC372MFKB | 774 |
| 5962-8765801PA | B | 08/28/2002 | 1 | TI | | Y | TLC372MJGB | 774 |
| 5962-87659012A | C | 04/14/2003 | 1 | TI | | Y | TLC374MFKB | 776 |
| 5962-8765901CA | C | 04/14/2003 | 1 | TI | | Y | TLC374MJB | 776 |
| 5962-87659022A | C | 04/14/2003 | 1 | TI | | Y | TLC139MFKB | 776 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-8765902CA | C | 04/14/2003 | 1 | TI | | Y | TLC139MJB | 776 |
| 5962-8766001GC | A | 12/17/2001 | 2 | MAXIM INTEG. | | | ICL7667MTV/883B | 519 |
| 5962-8766001GC | A | 12/17/2001 | 1 | ROCHESTER | | Y | ICL7667MTV/883B | 519 |
| 5962-8766001PA | A | 12/17/2001 | 2 | MAXIM INTEG. | | | ICL7667MJA/883B | 519 |
| 5962-8766001PA | A | 12/17/2001 | 1 | ROCHESTER | | Y | ICL7667MJA/883B | 519 |
| 5962-8766101XA | E | 12/03/1999 | 1 | QP SEMI | | Y | 27C128-90 | 661 |
| 5962-8766101YC | E | 12/03/1999 | 1 | QP SEMI | | Y | 27C128-90 | 661 |
| 5962-8766102XA | E | 12/03/1999 | 1 | QP SEMI | | Y | 27C128-120 | 661 |
| 5962-8766102YC | E | 12/03/1999 | 1 | QP SEMI | | Y | 27C128-120 | 661 |
| 5962-8766103XA | E | 12/03/1999 | 1 | QP SEMI | | Y | 27C128-150 | 661 |
| 5962-8766103YC | E | 12/03/1999 | 1 | QP SEMI | | Y | 27C128-150 | 661 |
| 5962-8766104XA | E | 12/03/1999 | 1 | QP SEMI | | Y | 27C128-170 | 661 |
| 5962-8766104YC | E | 12/03/1999 | 1 | QP SEMI | | Y | 27C128-170 | 661 |
| 5962-8766105XA | E | 12/03/1999 | 1 | QP SEMI | | Y | 27C128-200 | 661 |
| 5962-8766105YC | E | 12/03/1999 | 1 | QP SEMI | | Y | 27C128-200 | 661 |
| 5962-8766106XA | E | 12/03/1999 | 1 | QP SEMI | | Y | 27C128-250 | 661 |
| 5962-8766106YC | E | 12/03/1999 | 1 | QP SEMI | | Y | 27C128-250 | 661 |
| 5962-8766107XA | E | 12/03/1999 | 1 | QP SEMI | | Y | 27C128-300 | 661 |
| 5962-8766107YC | E | 12/03/1999 | 1 | QP SEMI | | Y | 27C128-300 | 661 |
| 5962-8766108XA | E | 12/03/1999 | 1 | QP SEMI | | | WS57C128FB-70DMB | 661 |
| 5962-8766108XA | E | 12/03/1999 | 1 | QP SEMI | | Y | 27C128-70 | 661 |
| 5962-8766108YC | E | 12/03/1999 | 1 | QP SEMI | | | WS57C128FB-70CMB | 661 |
| 5962-8766108YC | E | 12/03/1999 | 1 | QP SEMI | | Y | 27C128-70 | 661 |
| 5962-8766201EA | A | 08/16/2000 | 1 | ROCHESTER | | Y | 26S02/BEA | 166 |
| 5962-8766201FA | A | 08/16/2000 | 1 | ROCHESTER | | Y | 26S02/BFA | 166 |
| 5962-87663012A | D | 12/18/2002 | | (NONE) | 5962-8766301M2A | | 54ACT245 (GEN) | 590 |
| 5962-8766301B2A | D | 12/18/2002 | 3 | NATIONAL | | Y | JM54ACT245B2A | 590 |
| 5962-8766301M2A | D | 12/18/2002 | 3 | NATIONAL | | Y | 54ACT245LMQB | 590 |
| 5962-8766301M2A | D | 12/18/2002 | 2 | TI | | Y | SNJ54ACT245FK | 590 |
| 5962-8766301S2A | D | 12/18/2002 | | (NONE) | 03/05/2002 | | 54ACT245 (GEN) | 590 |
| 5962R8766301B2A | D | 12/18/2002 | 3 | NATIONAL | | Y | JM54ACT245B2A-R | 590 |
| 5962R8766301S2A | D | 12/18/2002 | 3 | NATIONAL | | Y | JM54ACT245S2A-R | 590 |
| 5962-8766301BRA | D | 12/18/2002 | 3 | NATIONAL | | Y | JM54ACT245BRA | 590 |
| 5962-8766301MRA | D | 12/18/2002 | 3 | NATIONAL | | Y | 54ACT245DMQB | 590 |
| 5962-8766301MRA | D | 12/18/2002 | 2 | TI | | Y | SNJ54ACT245J | 590 |
| 5962-8766301RA | D | 12/18/2002 | | (NONE) | 5962-8766301MRA | | 54ACT245 (GEN) | 590 |
| 5962-8766301SRA | D | 12/18/2002 | 2 | TI | | Y | SNV54ACT245J | 590 |
| 5962R8766301BRA | D | 12/18/2002 | 3 | NATIONAL | | Y | JM54ACT245BRA-R | 590 |
| 5962R8766301SRA | D | 12/18/2002 | 3 | NATIONAL | | Y | JM54ACT245SRA-R | 590 |
| 5962-8766301BSA | D | 12/18/2002 | 3 | NATIONAL | | Y | JM54ACT245BSA | 590 |
| 5962-8766301MSA | D | 12/18/2002 | 3 | NATIONAL | | Y | 54ACT245FMQB | 590 |
| 5962-8766301MSA | D | 12/18/2002 | 2 | TI | | Y | SNJ54ACT245W | 590 |
| 5962-8766301SA | D | 12/18/2002 | | (NONE) | 5962-8766301MSA | | 54ACT245 (GEN) | 590 |
| 5962-8766301SSA | D | 12/18/2002 | 2 | TI | | Y | SNV54ACT245W | 590 |
| 5962R8766301BSA | D | 12/18/2002 | 3 | NATIONAL | | Y | JM54ACT245BSA-R | 590 |
| 5962R8766301SSA | D | 12/18/2002 | 3 | NATIONAL | | Y | JM54ACT245SSA-R | 590 |
| 5962-8766302M3A | D | 12/18/2002 | 1 | ROCHESTER | | Y | 54ACT11245/B3A | 590 |
| 5962-8766302MLA | D | 12/18/2002 | 1 | ROCHESTER | | Y | 54ACT11245/BLA | 590 |
| 5962-8766303QXA | D | 12/18/2002 | 2 | STMICRO | | Y | 54ACT245K02Q | 590 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-8766303QXC | D | 12/18/2002 | 2 | STMICRO | | Y | 54ACT245K01Q | 590 |
| 5962-8766303VXA | D | 12/18/2002 | 2 | STMICRO | | Y | 54ACT245K02V | 590 |
| 5962-8766303VXC | D | 12/18/2002 | 2 | STMICRO | | Y | 54ACT245K01V | 590 |
| 5962-87664012A | B | 07/18/2000 | 3 | NATIONAL | | Y | 54ACT573LMQB | 341 |
| 5962-87664012A | B | 07/18/2000 | 3 | TI | | Y | SNJ54ACT573FK | 341 |
| 5962R87664012A | B | 07/18/2000 | 3 | NATIONAL | | Y | 54ACT573LMQB-RH | 341 |
| 5962-8766401RA | B | 07/18/2000 | 3 | NATIONAL | | Y | 54ACT573DMQB | 341 |
| 5962-8766401RA | B | 07/18/2000 | 3 | TI | | Y | SNJ54ACT573J | 341 |
| 5962R8766401RA | B | 07/18/2000 | 3 | NATIONAL | | Y | 54ACT573DMQB-RH | 341 |
| 5962-8766401SA | B | 07/18/2000 | 3 | NATIONAL | | Y | 54ACT573FMQB | 341 |
| 5962-8766401SA | B | 07/18/2000 | 3 | TI | | Y | SNJ54ACT573W | 341 |
| 5962R8766401SA | B | 07/18/2000 | 3 | NATIONAL | | Y | 54ACT573FMQB-RH | 341 |
| 5962-8766501TA | C | 05/27/1999 | | PYRAMID | | | P1750A-15GMB | 403 |
| 5962-8766501UA | C | 05/27/1999 | | PYRAMID | | | P1750A-15QLMB | 403 |
| 5962-8766501XA | C | 05/27/1999 | | PYRAMID | | | P1750A-15CMB | 403 |
| 5962-8766501YA | C | 05/27/1999 | | PYRAMID | | | P1750A-15QGMB | 403 |
| 5962-8766501ZA | C | 05/27/1999 | | PYRAMID | | | P1750A-15PGMB | 403 |
| 5962-8766502TA | C | 05/27/1999 | | PYRAMID | | | P1750A-20GMB | 403 |
| 5962-8766502UA | C | 05/27/1999 | | PYRAMID | | | P1750A-20QLMB | 403 |
| 5962-8766502XA | C | 05/27/1999 | | PYRAMID | | | P1750A-20CMB | 403 |
| 5962-8766502YA | C | 05/27/1999 | | PYRAMID | | | P1750A-20QGMB | 403 |
| 5962-8766502ZA | C | 05/27/1999 | | PYRAMID | | | P1750A-20PGMB | 403 |
| 5962-8766503TA | C | 05/27/1999 | | PYRAMID | | | P1750A-30GMB | 403 |
| 5962-8766503UA | C | 05/27/1999 | | PYRAMID | | | P1750A-30QLMB | 403 |
| 5962-8766503XA | C | 05/27/1999 | | PYRAMID | | | P1750A-30CMB | 403 |
| 5962-8766503YA | C | 05/27/1999 | | PYRAMID | | | P1750A-30QGMB | 403 |
| 5962-8766503ZA | C | 05/27/1999 | | PYRAMID | | | P1750A-30PGMB | 403 |
| 5962-8766504TA | C | 05/27/1999 | | PYRAMID | | | P1750A-40GMB | 403 |
| 5962-8766504UA | C | 05/27/1999 | | PYRAMID | | | P1750A-40QLMB | 403 |
| 5962-8766504XA | C | 05/27/1999 | | PYRAMID | | | P1750A-40CMB | 403 |
| 5962-8766504YA | C | 05/27/1999 | | PYRAMID | | | P1750A-40QGMB | 403 |
| 5962-8766504ZA | C | 05/27/1999 | | PYRAMID | | | P1750A-40PGMB | 403 |
| 5962-8766505TA | C | 05/27/1999 | | PYRAMID | | | P1750AE-20GMB | 403 |
| 5962-8766505UA | C | 05/27/1999 | | PYRAMID | | | P1750AE-20QLMB | 403 |
| 5962-8766505XA | C | 05/27/1999 | | PYRAMID | | | P1750AE-20CMB | 403 |
| 5962-8766505YA | C | 05/27/1999 | | PYRAMID | | | P1750AE-20QGMB | 403 |
| 5962-8766505ZA | C | 05/27/1999 | | PYRAMID | | | P1750AE-20PGMB | 403 |
| 5962-8766506UA | C | 05/27/1999 | | PYRAMID | | | P1750AE-30QLMB | 403 |
| 5962-8766506YA | C | 05/27/1999 | | PYRAMID | | | P1750AE-30QGMB | 403 |
| 5962-8766506ZA | C | 05/27/1999 | | PYRAMID | | | P1750AE-30PGMB | 403 |
| 5962-8766507UA | C | 05/27/1999 | | PYRAMID | | | P1750AE-40QLMB | 403 |
| 5962-8766507YA | C | 05/27/1999 | | PYRAMID | | | P1750AE-40QGMB | 403 |
| 5962-8766507ZA | C | 05/27/1999 | | PYRAMID | | | P1750AE-40PGMB | 403 |
| 5962-8766601VA | A | 08/03/1989 | | (NONE) | 03/30/2001 | | LT1080 (GEN) | 590 |
| 5962-8766602EA | A | 08/03/1989 | | (NONE) | 03/30/2001 | | LT1081 (GEN) | 590 |
| 5962-87667013A | C | 03/19/1993 | | (NONE) | | | 29C827 (GEN) | 544 |
| 5962-8766701KA | C | 03/19/1993 | | (NONE) | | | 29C827 (GEN) | 544 |
| 5962-8766701LA | C | 03/19/1993 | | (NONE) | | | 29C827 (GEN) | 544 |
| 5962-87667023A | C | 03/19/1993 | | (NONE) | 08/04/1995 | | 29C828 (GEN) | 544 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-8766702KA | C | 03/19/1993 | | (NONE) | 08/04/1995 | | 29C828 (GEN) | 544 |
| 5962-8766702LA | C | 03/19/1993 | | (NONE) | 08/04/1995 | | 29C828 (GEN) | 544 |
| 5962-8766703LA | C | 03/19/1993 | | (NONE) | | | 29C927 (GEN) | 544 |
| 5962-8766704LA | C | 03/19/1993 | | (NONE) | | | 29C928 (GEN) | 544 |
| 5962-87667053A | C | 03/19/1993 | | (NONE) | | | 29C827A (GEN) | 544 |
| 5962-8766705KA | C | 03/19/1993 | | (NONE) | | | 29C827A (GEN) | 544 |
| 5962-8766705LA | C | 03/19/1993 | | (NONE) | | | 29C827A (GEN) | 544 |
| 5962-87667063A | C | 03/19/1993 | | (NONE) | | | 29C828A (GEN) | 544 |
| 5962-8766706KA | C | 03/19/1993 | | (NONE) | | | 29C828A (GEN) | 544 |
| 5962-8766706LA | C | 03/19/1993 | | (NONE) | | | 29C828A (GEN) | 544 |
| 5962-8766801MXA | C | 09/24/1991 | | (NONE) | 12/24/1997 | | 8038616 (GEN) | 404 |
| 5962-8766801XA | C | 09/24/1991 | | (NONE) | 12/24/1997 | | 8038616 (GEN) | 404 |
| 5962-8766801MYA | C | 09/24/1991 | | (NONE) | 12/24/1997 | | 8038616 (GEN) | 404 |
| 5962-8766801YA | C | 09/24/1991 | | (NONE) | 12/24/1997 | | 8038616 (GEN) | 404 |
| 5962-8766802MXA | C | 09/24/1991 | | (NONE) | | | 80386-12 (GEN) | 404 |
| 5962-8766802XA | C | 09/24/1991 | | (NONE) | | | 80386-12 (GEN) | 404 |
| 5962-8766802MYA | C | 09/24/1991 | | (NONE) | | | 80386-12 (GEN) | 404 |
| 5962-8766802YA | C | 09/24/1991 | | (NONE) | | | 80386-12 (GEN) | 404 |
| 5962-8766803MXA | C | 09/24/1991 | | (NONE) | 12/24/1997 | | 8038620 (GEN) | 404 |
| 5962-8766803QXA | C | 09/24/1991 | | (NONE) | | | 80386-20 (GEN) | 404 |
| 5962-8766803XA | C | 09/24/1991 | | (NONE) | 12/24/1997 | | 8038620 (GEN) | 404 |
| 5962-8766803MYA | C | 09/24/1991 | | (NONE) | 12/24/1997 | | 8038620 (GEN) | 404 |
| 5962-8766803QYA | C | 09/24/1991 | | (NONE) | | | 80386-20 (GEN) | 404 |
| 5962-8766803YA | C | 09/24/1991 | | (NONE) | 12/24/1997 | | 8038620 (GEN) | 404 |
| 5962-8766804MXA | C | 09/24/1991 | | (NONE) | 12/24/1997 | | 8038625 (GEN) | 404 |
| 5962-8766804QXA | C | 09/24/1991 | | (NONE) | | | 80386-25 (GEN) | 404 |
| 5962-8766804XA | C | 09/24/1991 | | (NONE) | 12/24/1997 | | 8038625 (GEN) | 404 |
| 5962-8766804MYA | C | 09/24/1991 | | (NONE) | 12/24/1997 | | 8038625 (GEN) | 404 |
| 5962-8766804QYA | C | 09/24/1991 | | (NONE) | | | 80386-25 (GEN) | 404 |
| 5962-8766804YA | C | 09/24/1991 | | (NONE) | 12/24/1997 | | 8038625 (GEN) | 404 |
| 5962-8766901VA | | 09/23/1987 | | (NONE) | 12/24/1997 | | 8238416 (GEN) | 422 |
| 5962-8766902VA | | 09/23/1987 | | (NONE) | 12/24/1997 | | 8238412 (GEN) | 422 |
| 5962-8767001EA | | 01/15/1988 | | (NONE) | 12/01/1993 | | 26LS29 (GEN) | 569 |
| 5962-8767001FA | | 01/15/1988 | | (NONE) | | | 26LS29 (GEN) | 569 |
| 5962-87671013A | E | 01/07/2002 | 0 | TI | | Y | TIBPAL20L8-20MFDB | 431 |
| 5962-8767101KA | E | 01/07/2002 | 0 | TI | | Y | TIBPAL20L8-20MWB | 431 |
| 5962-8767101LA | E | 01/07/2002 | 0 | TI | | Y | TIBPAL20L8-20MJTB | 431 |
| 5962-87671023A | E | 01/07/2002 | 0 | TI | | Y | TIBPAL20R8-20MFDB | 431 |
| 5962-8767102KA | E | 01/07/2002 | 0 | TI | | Y | TIBPAL20R8-20MWB | 431 |
| 5962-8767102LA | E | 01/07/2002 | 0 | TI | | Y | TIBPAL20R8-20MJTB | 431 |
| 5962-87671033A | E | 01/07/2002 | 0 | TI | | Y | TIBPAL20R6-20MFDB | 431 |
| 5962-8767103KA | E | 01/07/2002 | 0 | TI | | Y | TIBPAL20R6-20MWB | 431 |
| 5962-8767103LA | E | 01/07/2002 | 0 | TI | | Y | TIBPAL20R6-20MJTB | 431 |
| 5962-87671043A | E | 01/07/2002 | 0 | TI | | Y | TIBPAL20R4-20MFDB | 431 |
| 5962-8767104KA | E | 01/07/2002 | 0 | TI | | Y | TIBPAL20R4-20MWB | 431 |
| 5962-8767104LA | E | 01/07/2002 | 0 | TI | | Y | TIBPAL20R4-20MJTB | 431 |
| 5962-87671053A | E | 01/07/2002 | | (NONE) | | | PLUS20L8 (GEN) | 431 |
| 5962-8767105KA | E | 01/07/2002 | | (NONE) | | | PLUS20L8 (GEN) | 431 |
| 5962-8767105LA | E | 01/07/2002 | | (NONE) | | | PLUS20L8 (GEN) | 431 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-87671063A | E | 01/07/2002 | | (NONE) | | | PLUS20R8 (GEN) | 431 |
| 5962-8767106KA | E | 01/07/2002 | | (NONE) | | | PLUS20R8 (GEN) | 431 |
| 5962-8767106LA | E | 01/07/2002 | | (NONE) | | | PLUS20R8 (GEN) | 431 |
| 5962-87671073A | E | 01/07/2002 | | (NONE) | | | PAL20L8-15 (GEN) | 431 |
| 5962-8767107LA | E | 01/07/2002 | | (NONE) | | | PAL20L8-15 (GEN) | 431 |
| 5962-87671083A | E | 01/07/2002 | | (NONE) | | | PAL20R8-15 (GEN) | 431 |
| 5962-8767108LA | E | 01/07/2002 | | (NONE) | | | PAL20R8-15 (GEN) | 431 |
| 5962-87671093A | E | 01/07/2002 | | (NONE) | | | PAL20R6-15 (GEN) | 431 |
| 5962-8767109LA | E | 01/07/2002 | | (NONE) | | | PAL20R6-15 (GEN) | 431 |
| 5962-87671103A | E | 01/07/2002 | | (NONE) | | | PAL20L4-15 (GEN) | 431 |
| 5962-8767110LA | E | 01/07/2002 | | (NONE) | | | PAL20R4-15 (GEN) | 431 |
| 5962-87671113A | E | 01/07/2002 | | (NONE) | 08/04/1995 | | PAL20L8-12 (GEN) | 431 |
| 5962-8767111LA | E | 01/07/2002 | | (NONE) | 08/04/1995 | | PAL20L8-12 (GEN) | 431 |
| 5962-87671123A | E | 01/07/2002 | | (NONE) | 08/04/1995 | | PAL20R8-12 (GEN) | 431 |
| 5962-8767112LA | E | 01/07/2002 | | (NONE) | 08/04/1995 | | PAL20R8-12 (GEN) | 431 |
| 5962-87671133A | E | 01/07/2002 | | (NONE) | 08/04/1995 | | PAL20R6-12 (GEN) | 431 |
| 5962-8767113LA | E | 01/07/2002 | | (NONE) | 08/04/1995 | | PAL20R6-12 (GEN) | 431 |
| 5962-87671143A | E | 01/07/2002 | | (NONE) | 08/04/1995 | | PAL20R4-12 (GEN) | 431 |
| 5962-8767114LA | E | 01/07/2002 | | (NONE) | 08/04/1995 | | PAL20R4-12 (GEN) | 431 |
| 5962-87671153A | E | 01/07/2002 | 2 | TI | | Y | TIBPAL20L8-10MFKB | 431 |
| 5962-8767115KA | E | 01/07/2002 | 2 | TI | | Y | TIBPAL20L8-10MWB | 431 |
| 5962-8767115LA | E | 01/07/2002 | 2 | TI | | Y | TIBPSL20L8-10MJTB | 431 |
| 5962-87671163A | E | 01/07/2002 | 2 | TI | 07/15/2005 | Y | TIBPAL20R8-10MFKB | 431 |
| 5962-8767116KA | E | 01/07/2002 | 2 | TI | 07/15/2005 | Y | TIBPAL20R8-10MWB | 431 |
| 5962-8767116LA | E | 01/07/2002 | 2 | TI | 07/15/2005 | Y | TIBPAL20R8-10MJTB | 431 |
| 5962-87671173A | E | 01/07/2002 | 2 | TI | | Y | TIBPAL20R6-10MFKB | 431 |
| 5962-8767117KA | E | 01/07/2002 | 2 | TI | | Y | TIBPAL20R6-10MWB | 431 |
| 5962-8767117LA | E | 01/07/2002 | 2 | TI | | Y | TIBPAL20R6-10MJTB | 431 |
| 5962-87671183A | E | 01/07/2002 | 2 | TI | | Y | TIBPAL20R4-10MFKB | 431 |
| 5962-8767118KA | E | 01/07/2002 | 2 | TI | | Y | TIBPAL20R4-10MWB | 431 |
| 5962-8767118LA | E | 01/07/2002 | 2 | TI | | Y | TIBPAL20R4-10MJTB | 431 |
| 5962-87671193A | E | 01/07/2002 | 2 | TI | | Y | TIBPAL20R8-7MFKB | 431 |
| 5962-8767119KA | E | 01/07/2002 | 2 | TI | | Y | TIBPAL20R8-7MWB | 431 |
| 5962-8767119LA | E | 01/07/2002 | 2 | TI | | Y | TIBPAL20R8-7MJTB | 431 |
| 5962-8767201YA | | 06/30/1987 | | (NONE) | 12/24/1997 | | 82188 (GEN) | 420 |
| 5962-8767301AA | B | 09/23/2002 | | (NONE) | | | DG180A (GEN) | 181 |
| 5962-8767301CA | B | 09/23/2002 | 1 | SILICONIX | | Y | DG180AP/883 | 181 |
| 5962-8767301IA | B | 09/23/2002 | 1 | SILICONIX | | Y | DG180AA/883 | 181 |
| 5962-8767301XA | B | 09/23/2002 | 1 | SILICONIX | | Y | DG180AL/883 | 181 |
| 5962-8767401CA | A | 05/29/2002 | 1 | QP SEMI | | Y | LM160 | 772 |
| 5962-8767401GA | A | 05/29/2002 | 1 | NATIONAL | | Y | LM160H/883 | 772 |
| 5962-8767401PA | A | 05/29/2002 | 1 | QP SEMI | | Y | LM160 | 772 |
| 5962-8767501TA | E | 05/14/2002 | 3 | INTER. RECT. | | | OM3910NT/883B | 780 |
| 5962-8767501TA | E | 05/14/2002 | 1 | SEMELAB | | Y | IP150G-DESC | 780 |
| 5962-8767501UA | E | 05/14/2002 | 3 | INTER. RECT. | | | OM3910ST/883B | 780 |
| 5962-8767501UA | E | 05/14/2002 | 1 | SEMELAB | | Y | IP150IG-DESC | 780 |
| 5962-8767501XA | E | 05/14/2002 | I | NATIONAL | | Y | LM150K/883 | 780 |
| 5962-8767501XA | E | 05/14/2002 | 1 | SEMELAB | | Y | IP150K-DESC | 780 |
| 5962-8767501YA | E | 05/14/2002 | 1 | INTER. RECT. | | | OM3910SRM/883B | 780 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-8767501ZA | E | 05/14/2002 | 1 | INTER. RECT. | | | OM3910N5M/883B | 780 |
| 5962-8767502TA | E | 05/14/2002 | 3 | INTER. RECT. | | | OM3911NT/883B | 780 |
| 5962-8767502TA | E | 05/14/2002 | 1 | SEMELAB | | Y | IP150AG-DESC | 780 |
| 5962-8767502UA | E | 05/14/2002 | 3 | INTER. RECT. | | | OM3911ST/883B | 780 |
| 5962-8767502UA | E | 05/14/2002 | 1 | SEMELAB | | Y | IP150AIG-DESC | 780 |
| 5962R8767502UA | E | 05/14/2002 | 1 | INTER. RECT. | | | OMR3911STM/883B | 780 |
| 5962-8767502XA | E | 05/14/2002 | 1 | SEMELAB | | Y | IP150AK-DESC | 780 |
| 5962-8767601VA | A | 05/04/1988 | | (NONE) | | | MT4067-12 (GEN) | 623 |
| 5962-8767601XA | A | 05/04/1988 | | (NONE) | | | MT4067-12 (GEN) | 623 |
| 5962-8767602VA | A | 05/04/1988 | | (NONE) | | | MT4067-15 (GEN) | 623 |
| 5962-8767602XA | A | 05/04/1988 | | (NONE) | | | MT4067-15 (GEN) | 623 |
| 5962-8767603VA | A | 05/04/1988 | | (NONE) | | | MT4067-20 (GEN) | 623 |
| 5962-8767603XA | A | 05/04/1988 | | (NONE) | | | MT4067-20 (GEN) | 623 |
| 5962-8767604VA | A | 05/04/1988 | | (NONE) | | | MT4067-10 (GEN) | 623 |
| 5962-8767604XA | A | 05/04/1988 | | (NONE) | | | MT4067-10 (GEN) | 623 |
| 5962-87677012A | B | 09/18/2002 | 1 | INTERSIL | | Y | HA4-5330/883 | 818 |
| 5962-8767701CA | B | 09/18/2002 | 1 | INTERSIL | 10/05/2004 | Y | HA1-5330/883 | 818 |
| 5962-8767801EA | A | 04/11/1991 | | (NONE) | 06/30/1996 | | 8690A (GEN) | 319 |
| 5962-87679012A | H | 04/09/1998 | | (NONE) | | | 66024 (GEN) | 460 |
| 5962-8767901EA | H | 04/09/1998 | 1 | AGILENT | | Y | 4N55/883B#200 | 460 |
| 5962-8767901EA | H | 04/09/1998 | 1 | MICROPAC | | Y | 66024-001 | 460 |
| 5962-8767901EC | H | 04/09/1998 | 1 | AGILENT | | Y | 4N55/883B | 460 |
| 5962-8767901EC | H | 04/09/1998 | 1 | MICROPAC | | Y | 66024-001 | 460 |
| 5962-8767901TA | H | 04/09/1998 | 1 | AGILENT | | Y | 4N55/883B#300 | 460 |
| 5962-8767901TA | H | 04/09/1998 | 1 | MICROPAC | | Y | 66024-001J | 460 |
| 5962-8767901TC | H | 04/09/1998 | 1 | MICROPAC | | Y | 66024-001J | 460 |
| 5962-8767901UA | H | 04/09/1998 | 1 | AGILENT | | Y | 4N55/883B#100 | 460 |
| 5962-8767901UC | H | 04/09/1998 | 1 | AGILENT | | Y | 4N55/883B#100 | 460 |
| 5962-8767902PA | H | 04/09/1998 | 3 | AGILENT | | Y | HCPL-5531#200 | 460 |
| 5962-8767902PA | H | 04/09/1998 | 1 | MICROPAC | | Y | 66126-103 | 460 |
| 5962-8767902PC | H | 04/09/1998 | 3 | AGILENT | | Y | HCPL-5531 | 460 |
| 5962-8767902PC | H | 04/09/1998 | 1 | MICROPAC | | Y | 66126-103 | 460 |
| 5962-8767902XA | H | 04/09/1998 | 3 | AGILENT | | Y | HCPL-5531#300 | 460 |
| 5962-8767902XA | H | 04/09/1998 | 1 | MICROPAC | | Y | 66126-103J | 460 |
| 5962-8767902XC | H | 04/09/1998 | 1 | MICROPAC | | Y | 66126-103J | 460 |
| 5962-8767902YA | H | 04/09/1998 | 3 | AGILENT | | Y | HCPL-5531#100 | 460 |
| 5962-8767902YC | H | 04/09/1998 | 3 | AGILENT | | Y | HCPL-5531#100 | 460 |
| 5962-87679032A | H | 04/09/1998 | 1 | AGILENT | | Y | HCPL-6531 | 460 |
| 5962-87679032A | H | 04/09/1998 | 1 | MICROPAC | | Y | 66125-001 | 460 |
| 5962-87679032C | H | 04/09/1998 | 1 | MICROPAC | | Y | 66125-001 | 460 |
| 5962-8767904FC | H | 04/09/1998 | 3 | AGILENT | | Y | HCPL-6551 | 460 |
| 5962-8767905KEA | H | 04/09/1998 | 3 | AGILENT | | Y | HCPL-275K#200 | 460 |
| 5962-8767905KEA | H | 04/09/1998 | 1 | MICROPAC | | Y | 66024-300 | 460 |
| 5962-8767905KEC | H | 04/09/1998 | 3 | AGILENT | | Y | HCPL-275K | 460 |
| 5962-8767905KEC | H | 04/09/1998 | 1 | MICROPAC | | Y | 66024-300 | 460 |
| 5962-8767905KTA | H | 04/09/1998 | 3 | AGILENT | | Y | HCPL-275K#300 | 460 |
| 5962-8767905KTA | H | 04/09/1998 | 1 | MICROPAC | | Y | 66024-300T | 460 |
| 5962-8767905KTC | H | 04/09/1998 | 1 | MICROPAC | | Y | 66024-300T | 460 |
| 5962-8767905KUA | H | 04/09/1998 | 3 | AGILENT | | Y | HCPL-275K#100 | 460 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-8767905KUC | H | 04/09/1998 | 3 | AGILENT | | Y | HCPL-275K#100 | 460 |
| 5962-8767906KPA | H | 04/09/1998 | 3 | AGILENT | | Y | HCPL-553K#200 | 460 |
| 5962-8767906KPA | H | 04/09/1998 | 1 | MICROPAC | | Y | 66126-300 | 460 |
| 5962-8767906KPC | H | 04/09/1998 | 3 | AGILENT | | Y | HCPL-553K | 460 |
| 5962-8767906KPC | H | 04/09/1998 | 1 | MICROPAC | | Y | 66126-300 | 460 |
| 5962-8767906KXA | H | 04/09/1998 | 3 | AGILENT | | Y | HCPL-553K#300 | 460 |
| 5962-8767906KXA | H | 04/09/1998 | 1 | MICROPAC | | Y | 66126-300J | 460 |
| 5962-8767906KXC | H | 04/09/1998 | 1 | MICROPAC | | Y | 66126-300J | 460 |
| 5962-8767906KYA | H | 04/09/1998 | 3 | AGILENT | | Y | HCPL-553K#100 | 460 |
| 5962-8767906KYC | H | 04/09/1998 | 3 | AGILENT | | Y | HCPL-553K#100 | 460 |
| 5962-8767907K2A | H | 04/09/1998 | 3 | AGILENT | | Y | HCPL-653K | 460 |
| 5962-8767907K2A | H | 04/09/1998 | 1 | MICROPAC | | Y | 66125-300 | 460 |
| 5962-8767908KFC | H | 04/09/1998 | 3 | AGILENT | | Y | HCPL-655K | 460 |
| 5962-87680012A | B | 11/04/1994 | | (NONE) | | | 54HC4060 (GEN) | 305 |
| 5962-8768001EA | B | 11/04/1994 | 1 | TI | | Y | CD54HC4060F3A | 305 |
| 5962-87681012A | H | 07/19/2002 | 1 | MICROSEMI | | Y | SG1825CL/883B | 787 |
| 5962-87681012A | H | 07/19/2002 | 1 | TI | | Y | UC1825L/883B | 787 |
| 5962-8768101V2A | H | 07/19/2002 | 1 | TI | | Y | UC1825L/QMLV | 787 |
| 5962-8768101EA | H | 07/19/2002 | 1 | MICROSEMI | | Y | SG1825CJ/883B | 787 |
| 5962-8768101EA | H | 07/19/2002 | 1 | TI | | Y | UC1825J/883B | 787 |
| 5962-8768101VEA | H | 07/19/2002 | 1 | TI | | Y | UC1825J/QMLV | 787 |
| 5962-8768101QFA | H | 07/19/2002 | 1 | TI | | Y | UC1825W/883B | 787 |
| 5962-87681022A | H | 07/19/2002 | 1 | TI | | Y | UC1825AL/883B | 787 |
| 5962-8768102V2A | H | 07/19/2002 | 1 | TI | | Y | UC1825AL/QMLV | 787 |
| 5962-8768102EA | H | 07/19/2002 | 1 | TI | | Y | UC1825AJ/883B | 787 |
| 5962-8768102VEA | H | 07/19/2002 | 1 | TI | | Y | UC1825AJ/QMLV | 787 |
| 5962-8768102XA | H | 07/19/2002 | | (NONE) | | | 1825A (GEN) | 787 |
| 5962-87681032A | H | 07/19/2002 | | (NONE) | 12/31/2001 | | 1825B (GEN) | 787 |
| 5962-8768103EA | H | 07/19/2002 | | (NONE) | 12/31/2001 | | 1825B (GEN) | 787 |
| 5962-8768103XA | H | 07/19/2002 | | (NONE) | | | 1825B (GEN) | 787 |
| 5962-87682012A | E | 01/14/2002 | | (NONE) | 09/01/1997 | | 82S153A (GEN) | 431 |
| 5962-8768201M2A | E | 01/14/2002 | 1 | QP SEMI | | Y | 82S153A/B2A | 431 |
| 5962-8768201MRA | E | 01/14/2002 | 1 | QP SEMI | | Y | 82S153A/BRA | 431 |
| 5962-8768201RA | E | 01/14/2002 | | (NONE) | 09/01/1997 | | 82S153A (GEN) | 431 |
| 5962-8768201MSA | E | 01/14/2002 | | (NONE) | | | 82S153A (GEN) | 431 |
| 5962-8768201SA | E | 01/14/2002 | | (NONE) | | | 82S153A (GEN) | 431 |
| 5962-87683012A | B | 10/05/1992 | 3 | TI | | Y | SNJ54ALS139FK | 283 |
| 5962-8768301EA | B | 10/05/1992 | 3 | TI | | Y | SNJ54ALS139J | 283 |
| 5962-8768301FA | B | 10/05/1992 | 3 | TI | | Y | SNJ54ALS139W | 283 |
| 5962-8768401MMA | F | 09/03/2004 | 2 | QP SEMI | | Y | 87C51/BMA | 420 |
| 5962-8768401MQA | F | 09/03/2004 | 2 | QP SEMI | | Y | 87C51/BQA | 420 |
| 5962-8768401QA | F | 09/03/2004 | | (NONE) | 12/24/1997 | | 87C51 (GEN) | 420 |
| 5962-8768401MUA | F | 09/03/2004 | 2 | QP SEMI | | Y | 87C51/BUA | 420 |
| 5962-8768401UA | F | 09/03/2004 | | (NONE) | 5962-8768401MUA | | 87C51 (GEN) | 420 |
| 5962-8768402MMA | F | 09/03/2004 | 2 | QP SEMI | | Y | 87C51-16/BMA | 420 |
| 5962-8768402MQA | F | 09/03/2004 | 2 | QP SEMI | | Y | 87C51-16/BQA | 420 |
| 5962-8768402QA | F | 09/03/2004 | | (NONE) | 12/24/1997 | | 87C5116 (GEN) | 420 |
| 5962-8768402MUA | F | 09/03/2004 | 2 | QP SEMI | | Y | 87C51-16/BUA | 420 |
| 5962-8768402UA | F | 09/03/2004 | | (NONE) | 12/24/1997 | | 87C5116 (GEN) | 420 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-8768403NXA | F | 09/03/2004 | | (NONE) | | | 87C51 (GEN) | 420 |
| 5962-8768403NYA | F | 09/03/2004 | | (NONE) | | | 87C51 (GEN) | 420 |
| 5962-8768404NXA | F | 09/03/2004 | | (NONE) | | | 87C51-16 (GEN) | 420 |
| 5962-8768404NYA | F | 09/03/2004 | | (NONE) | | | 87C51-16 (GEN) | 420 |
| 5962-8768405NXA | F | 09/03/2004 | | (NONE) | | | 87C51 (GEN) | 420 |
| 5962-8768405NYA | F | 09/03/2004 | | (NONE) | | | 87C51 (GEN) | 420 |
| 5962-8768406NXA | F | 09/03/2004 | | (NONE) | | | 87C51-16 (GEN) | 420 |
| 5962-8768406NYA | F | 09/03/2004 | | (NONE) | | | 87C51-16 (GEN) | 420 |
| 5962-8768501QA | | 11/09/1987 | | (NONE) | | | 8088 (GEN) | 402 |
| 5962-8768601UA | D | 03/19/1999 | | (NONE) | 08/21/1995 | | 7217L-40 (GEN) | 208 |
| 5962-8768601XA | D | 03/19/1999 | | (NONE) | 08/05/1996 | | 7217L-40 (GEN) | 208 |
| 5962-8768601YA | D | 03/19/1999 | | (NONE) | | | 7217L-40 (GEN) | 208 |
| 5962-8768601ZA | D | 03/19/1999 | | (NONE) | 08/05/1996 | | 7217L-40 (GEN) | 208 |
| 5962-8768602TA | D | 03/19/1999 | | (NONE) | 04/01/2000 | | LMU17 (GEN) | 208 |
| 5962-8768602UA | D | 03/19/1999 | | (NONE) | 04/01/2000 | | LMU17 (GEN) | 208 |
| 5962-8768602XA | D | 03/19/1999 | | (NONE) | 04/01/2000 | | LMU17 (GEN) | 208 |
| 5962-8768602YA | D | 03/19/1999 | | (NONE) | 04/01/2000 | | LMU17 (GEN) | 208 |
| 5962-8768602ZA | D | 03/19/1999 | | (NONE) | | | LMU17 (GEN) | 208 |
| 5962-8768603TA | D | 03/19/1999 | | (NONE) | 04/01/2000 | | LMU17 (GEN) | 208 |
| 5962-8768603UA | D | 03/19/1999 | | (NONE) | 04/01/2000 | | LMU17 (GEN) | 208 |
| 5962-8768603XA | D | 03/19/1999 | | (NONE) | 04/01/2000 | | LMU17 (GEN) | 208 |
| 5962-8768603YA | D | 03/19/1999 | | (NONE) | 04/01/2000 | | LMU17 (GEN) | 208 |
| 5962-8768603ZA | D | 03/19/1999 | | (NONE) | | | LMU17 (GEN) | 208 |
| 5962-8768604TA | D | 03/19/1999 | | (NONE) | 04/01/2000 | | LMU17 (GEN) | 208 |
| 5962-8768604UA | D | 03/19/1999 | | (NONE) | 04/01/2000 | | LMU17 (GEN) | 208 |
| 5962-8768604XA | D | 03/19/1999 | | (NONE) | 04/01/2000 | | LMU17 (GEN) | 208 |
| 5962-8768604YA | D | 03/19/1999 | | (NONE) | 04/01/2000 | | LMU17 (GEN) | 208 |
| 5962-8768605TA | D | 03/19/1999 | | (NONE) | 04/01/2000 | | LMU17 (GEN) | 208 |
| 5962-8768605UA | D | 03/19/1999 | | (NONE) | 04/01/2000 | | LMU17 (GEN) | 208 |
| 5962-8768605XA | D | 03/19/1999 | | (NONE) | 04/01/2000 | | LMU17 (GEN) | 208 |
| 5962-8768605YA | D | 03/19/1999 | | (NONE) | 04/01/2000 | | LMU17 (GEN) | 208 |
| 5962-8768606TA | D | 03/19/1999 | | (NONE) | 04/01/2000 | | LMU17 (GEN) | 208 |
| 5962-8768606UA | D | 03/19/1999 | | (NONE) | 04/01/2000 | | LMU17 (GEN) | 208 |
| 5962-8768606XA | D | 03/19/1999 | | (NONE) | 04/01/2000 | | LMU17 (GEN) | 208 |
| 5962-8768606YA | D | 03/19/1999 | | (NONE) | 04/01/2000 | | LMU17 (GEN) | 208 |
| 5962-8768701XA | D | 12/20/1996 | | (NONE) | | | HSDC8920 (GEN) | 594 |
| 5962-8768701YA | D | 12/20/1996 | | (NONE) | | | RDC14505-638C (GEN) | 594 |
| 5962-8768702XA | D | 12/20/1996 | | (NONE) | | | RDC14505-639 (GEN) | 594 |
| 5962-8768702YA | D | 12/20/1996 | | (NONE) | | | RDC14505-639C (GEN) | 594 |
| 5962-8768703XA | D | 12/20/1996 | | (NONE) | | | RDC14505-641 (GEN) | 594 |
| 5962-8768703YA | D | 12/20/1996 | | (NONE) | | | RDC14505-641C (GEN) | 594 |
| 5962-8768801XA | A | 04/16/1991 | 1 | MICRO NETWKS | | Y | MN3008H/B | 591 |
| 5962-8768801XC | A | 04/16/1991 | 1 | MICRO NETWKS | | Y | MN3008H/B | 591 |
| 5962-8768801YA | A | 04/16/1991 | | (NONE) | | | MN3008 (GEN) | 591 |
| 5962-8768802XA | A | 04/16/1991 | 1 | MICRO NETWKS | | Y | MN3009H/B | 591 |
| 5962-8768802XC | A | 04/16/1991 | 1 | MICRO NETWKS | | Y | MN3009H/B | 591 |
| 5962-8768802YA | A | 04/16/1991 | | (NONE) | | | MN3009 (GEN) | 591 |
| 5962-8768901VA | B | 09/29/2003 | 1 | MAXIM INTEG. | | | DG528AK/883B | 193 |
| 5962-8768901VA | B | 09/29/2003 | 0 | SILICONIX | 08/31/2004 | Y | DG528AK/883 | 193 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-87690012A | | 08/05/1987 | | (NONE) | 08/02/1996 | | 27S29 (GEN) | 656 |
| 5962-8769001RA | | 08/05/1987 | | (NONE) | 08/02/1996 | | 27S29 (GEN) | 656 |
| 5962-8769001SA | | 08/05/1987 | | (NONE) | 08/02/1996 | | 27S29 (GEN) | 656 |
| 5962-87690022A | | 08/05/1987 | | (NONE) | 08/02/1996 | | 27S29A (GEN) | 656 |
| 5962-8769002RA | | 08/05/1987 | | (NONE) | 08/02/1996 | | 27S29A (GEN) | 656 |
| 5962-8769002SA | | 08/05/1987 | | (NONE) | 08/02/1996 | | 27S29A (GEN) | 656 |
| 5962-87691012A | | 08/28/1987 | 2 | NATIONAL | | Y | 54AC151LMQB | 271 |
| 5962-8769101EA | | 08/28/1987 | 2 | NATIONAL | | Y | 54AC151DMQB | 271 |
| 5962-8769101FA | | 08/28/1987 | 2 | NATIONAL | | Y | 54AC151FMQB | 271 |
| 5962-87692012A | B | 03/11/1999 | 3 | NATIONAL | | Y | 54AC251LMQB | 272 |
| 5962-8769201V2A | B | 03/11/1999 | | (NONE) | | | 54AC251 (GEN) | 272 |
| 5962R87692012A | B | 03/11/1999 | 3 | NATIONAL | | Y | 54AC251LMQB-RH | 272 |
| 5962R8769201V2A | B | 03/11/1999 | 3 | NATIONAL | | Y | 54AC251ERQMLV | 272 |
| 5962-8769201EA | B | 03/11/1999 | 3 | NATIONAL | | Y | 54AC251DMQB | 272 |
| 5962-8769201VEA | B | 03/11/1999 | | (NONE) | | | 54AC251 (GEN) | 272 |
| 5962R8769201EA | B | 03/11/1999 | 3 | NATIONAL | | Y | 54AC251DMQB-RH | 272 |
| 5962R8769201VEA | B | 03/11/1999 | 3 | NATIONAL | | Y | 54AC251JRQMLV | 272 |
| 5962-8769201FA | B | 03/11/1999 | 3 | NATIONAL | | Y | 54AC251FMQB | 272 |
| 5962-8769201VFA | B | 03/11/1999 | | (NONE) | | | 54AC251 (GEN) | 272 |
| 5962R8769201FA | B | 03/11/1999 | 3 | NATIONAL | | Y | 54AC251FMQB-RH | 272 |
| 5962R8769201VFA | B | 03/11/1999 | 3 | NATIONAL | | Y | 54AC251WRQMLV | 272 |
| 5962-87693012A | | 08/10/1987 | 2 | NATIONAL | | Y | 54AC253LMQB | 274 |
| 5962-8769301EA | | 08/10/1987 | 2 | NATIONAL | | Y | 54AC253DMQB | 274 |
| 5962-8769301FA | | 08/10/1987 | 2 | NATIONAL | | Y | 54AC253FMQB | 274 |
| 5962-87694012A | D | 01/10/2001 | 2 | NATIONAL | | Y | 54AC374LMQB | 159 |
| 5962-87694012A | D | 01/10/2001 | 3 | TI | | Y | SNJ54AC374FK | 159 |
| 5962-8769401RA | D | 01/10/2001 | 2 | NATIONAL | | Y | 54AC374DMQB | 159 |
| 5962-8769401RA | D | 01/10/2001 | 3 | TI | | Y | SNJ54AC374J | 159 |
| 5962-8769401VRA | D | 01/10/2001 | 3 | TI | | Y | SNV54AC374J | 159 |
| 5962-8769401SA | D | 01/10/2001 | 2 | NATIONAL | | Y | 54AC374FMQB | 159 |
| 5962-8769401SA | D | 01/10/2001 | 3 | TI | | Y | SNJ54AC374W | 159 |
| 5962-8769401VSA | D | 01/10/2001 | 3 | TI | | Y | SNV54AC374W | 159 |
| 5962-8769401VXA | D | 01/10/2001 | 2 | STMICRO | | Y | 54AC374K02V | 159 |
| 5962-8769401VXC | D | 01/10/2001 | 2 | STMICRO | | Y | 54AC374K01V | 159 |
| 5962-8769401XA | D | 01/10/2001 | 2 | STMICRO | | Y | 54AC374K02Q | 159 |
| 5962-8769401XC | D | 01/10/2001 | 2 | STMICRO | | Y | 54AC374K01Q | 159 |
| 5962-87695012A | | 12/08/1987 | 3 | NATIONAL | | Y | 54AC540LMQB | 529 |
| 5962-8769501RA | | 12/08/1987 | 3 | NATIONAL | | Y | 54AC540DMQB | 529 |
| 5962-8769501SA | | 12/08/1987 | 3 | NATIONAL | | Y | 54AC540FMQB | 529 |
| 5962-87697012A | B | 01/15/1993 | | (NONE) | 5962-8769701M2A | | 54ACT377 (GEN) | 159 |
| 5962-8769701B2A | B | 01/15/1993 | 3 | NATIONAL | | Y | JM54ACT377B2A | 159 |
| 5962-8769701M2A | B | 01/15/1993 | 3 | NATIONAL | 09/01/2004 | Y | 54ACT377LMQB | 159 |
| 5962-8769701S2A | B | 01/15/1993 | | (NONE) | | | 54ACT377 (GEN) | 159 |
| 5962-8769701BRA | B | 01/15/1993 | 3 | NATIONAL | | Y | JM54ACT377BRA | 159 |
| 5962-8769701MRA | B | 01/15/1993 | 3 | NATIONAL | | Y | 54ACT377DMQB | 159 |
| 5962-8769701RA | B | 01/15/1993 | | (NONE) | 5962-8769701MRA | | 54ACT377 (GEN) | 159 |
| 5962-8769701SRA | B | 01/15/1993 | 3 | NATIONAL | | Y | JM54ACT377SRA | 159 |
| 5962-8769701BSA | B | 01/15/1993 | 3 | NATIONAL | | Y | JM54ACT377BSA | 159 |
| 5962-8769701MSA | B | 01/15/1993 | 3 | NATIONAL | | Y | 54ACT377FMQB | 159 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-8769701SA | B | 01/15/1993 | | (NONE) | 5962-8769701MSA | | 54ACT377 (GEN) | 159 |
| 5962-8769701SSA | B | 01/15/1993 | 3 | NATIONAL | | Y | JM54ACT377SSA | 159 |
| 5962-87698012A | A | 07/28/2003 | 3 | NATIONAL | | Y | 54ACT153LMQB | 273 |
| 5962-8769801EA | A | 07/28/2003 | 3 | NATIONAL | | Y | 54ACT153DMQB | 273 |
| 5962-8769801FA | A | 07/28/2003 | 3 | NATIONAL | | Y | 54ACT153FMQB | 273 |
| 5962-87699012A | E | 09/09/2004 | | (NONE) | 5962-8769901M2A | | 54ACT00 (GEN) | 100 |
| 5962-8769901B2A | E | 09/09/2004 | 2 | NATIONAL | | Y | JM54ACT00B2A | 100 |
| 5962-8769901M2A | E | 09/09/2004 | 2 | NATIONAL | | Y | 54ACT00LMQB | 100 |
| 5962-8769901M2A | E | 09/09/2004 | 2 | TI | | Y | SNJ54ACT00FK | 100 |
| 5962-8769901S2A | E | 09/09/2004 | | (NONE) | | | 54ACT00 (GEN) | 100 |
| 5962R8769901B2A | E | 09/09/2004 | 2 | NATIONAL | | Y | JM54ACT00B2A-RH | 100 |
| 5962R8769901S2A | E | 09/09/2004 | 2 | NATIONAL | | Y | JM54ACT00S2A-RH | 100 |
| 5962-8769901BCA | E | 09/09/2004 | 2 | NATIONAL | | Y | JM54ACT00BCA | 100 |
| 5962-8769901CA | E | 09/09/2004 | | (NONE) | 5962-8769901MCA | | 54ACT00 (GEN) | 100 |
| 5962-8769901MCA | E | 09/09/2004 | 2 | NATIONAL | | Y | 54ACT00DMQB | 100 |
| 5962-8769901MCA | E | 09/09/2004 | 2 | TI | | Y | SNJ54ACT00J | 100 |
| 5962-8769901SCA | E | 09/09/2004 | | (NONE) | | | 54ACT00 (GEN) | 100 |
| 5962R8769901BCA | E | 09/09/2004 | 2 | NATIONAL | | Y | JM54ACT00BCA-RH | 100 |
| 5962R8769901SCA | E | 09/09/2004 | 2 | NATIONAL | | Y | JM54ACT00SCA-RH | 100 |
| 5962-8769901BDA | E | 09/09/2004 | 2 | NATIONAL | | Y | JM54ACT00BDA | 100 |
| 5962-8769901DA | E | 09/09/2004 | | (NONE) | 5962-8769901MDA | | 54ACT00 (GEN) | 100 |
| 5962-8769901MDA | E | 09/09/2004 | 2 | NATIONAL | | Y | 54ACT00FMQB | 100 |
| 5962-8769901MDA | E | 09/09/2004 | 2 | TI | | Y | SNJ54ACT00W | 100 |
| 5962-8769901SDA | E | 09/09/2004 | | (NONE) | | | 54ACT00 (GEN) | 100 |
| 5962R8769901BDA | E | 09/09/2004 | 2 | NATIONAL | | Y | JM54ACT00BDA-RH | 100 |
| 5962R8769901SDA | E | 09/09/2004 | 2 | NATIONAL | | Y | JM54ACT00SDA-RH | 100 |
| 5962R8769901SZA | E | 09/09/2004 | 2 | NATIONAL | | Y | JM54ACT00SZA-RH | 100 |
| 5962-87699022A | E | 09/09/2004 | | (NONE) | 09/15/1995 | | 54ACT11000 (GEN) | 100 |
| 5962-8769902M2A | E | 09/09/2004 | 1 | ROCHESTER | | Y | 54ACT11000/B2A | 100 |
| 5962-8769902EA | E | 09/09/2004 | | (NONE) | 09/15/1995 | | 54ACT11000 (GEN) | 100 |
| 5962-8769902MEA | E | 09/09/2004 | 1 | ROCHESTER | | Y | 54ACT11000/BEA | 100 |
| 5962-8769903QXA | E | 09/09/2004 | 2 | STMICRO | | Y | 54ACT00K02Q | 100 |
| 5962-8769903QXC | E | 09/09/2004 | 2 | STMICRO | | Y | 54ACT00K01Q | 100 |
| 5962-8769903VXA | E | 09/09/2004 | 2 | STMICRO | | Y | 54ACT00K02V | 100 |
| 5962-8769903VXC | E | 09/09/2004 | 2 | STMICRO | | Y | 54ACT00K01V | 100 |
| 5962F8769903QXA | E | 09/09/2004 | 2 | STMICRO | | Y | RHFACT00K02Q | 100 |
| 5962F8769903QXC | E | 09/09/2004 | 2 | STMICRO | | Y | RHFACT00K01Q | 100 |
| 5962F8769903VXA | E | 09/09/2004 | 2 | STMICRO | | Y | RHFACT00K02V | 100 |
| 5962F8769903VXC | E | 09/09/2004 | 2 | STMICRO | | Y | RHFACT00K01V | 100 |
| 5962-87700012A | B | 09/30/2003 | 1 | ANALOG (3) | | Y | AD7524SE/883B | 591 |
| 5962-87700012C | B | 09/30/2003 | 1 | MAXIM INTEG. | | | MX7524SE/883B | 591 |
| 5962-8770001EA | B | 09/30/2003 | 1 | MAXIM INTEG. | | | MX7524SQ/883B | 591 |
| 5962-8770001EA | B | 09/30/2003 | | TI | 07/15/2005 | Y | AD7524MJ | 591 |
| 5962-87700022A | B | 09/30/2003 | 1 | ANALOG (3) | | Y | AD7524TE/883B | 591 |
| 5962-87700022C | B | 09/30/2003 | 1 | MAXIM INTEG. | | | MX7524TE/883B | 591 |
| 5962-8770002EA | B | 09/30/2003 | 1 | ANALOG (3) | | Y | AD7524TQ/883B | 591 |
| 5962-8770002EA | B | 09/30/2003 | 1 | MAXIM INTEG. | | | MX7524TQ/883B | 591 |
| 5962-87700032A | B | 09/30/2003 | 1 | ANALOG (3) | | Y | AD7524UE/883B | 591 |
| 5962-87700032C | B | 09/30/2003 | 1 | MAXIM INTEG. | | | MX7524UE/883B | 591 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-8770003EA | B | 09/30/2003 | 1 | ANALOG (3) | | Y | AD7524UQ/883B | 591 |
| 5962-8770003EA | B | 09/30/2003 | 1 | MAXIM INTEG. | | | MX7524UQ/883B | 591 |
| 5962-87701012A | C | 12/15/2003 | | (NONE) | | | AD7528S (GEN) | 591 |
| 5962-8770101RA | C | 12/15/2003 | 1 | ANALOG (3) | | Y | AD7528SQ/883B | 591 |
| 5962-8770101RA | C | 12/15/2003 | 1 | MAXIM INTEG. | | | MX7528SQ/883B | 591 |
| 5962-87701022A | C | 12/15/2003 | 1 | ANALOG (3) | | Y | AD7528TE/883B | 591 |
| 5962-8770102RA | C | 12/15/2003 | 1 | ANALOG (3) | | Y | AD7528TQ/883B | 591 |
| 5962-8770102RA | C | 12/15/2003 | 1 | MAXIM INTEG. | | | MX7528TQ/883B | 591 |
| 5962-87701032A | C | 12/15/2003 | 1 | ANALOG (3) | | Y | AD7528UE/883B | 591 |
| 5962-8770103RA | C | 12/15/2003 | 1 | ANALOG (3) | | Y | AD7528UQ/883B | 591 |
| 5962-8770103RA | C | 12/15/2003 | 1 | MAXIM INTEG. | | | MX7528UQ/883B | 591 |
| 5962-87702012C | D | 01/07/2004 | 1 | MAXIM INTEG. | | | MX7545SE/883B | 591 |
| 5962-8770201RA | D | 01/07/2004 | 1 | ANALOG (3) | | Y | AD7545SQ/883B | 591 |
| 5962-8770201RA | D | 01/07/2004 | 1 | MAXIM INTEG. | | | MX7545SQ/883B | 591 |
| 5962-87702022C | D | 01/07/2004 | 1 | MAXIM INTEG. | | | MX7545TE/883B | 591 |
| 5962-8770202RA | D | 01/07/2004 | 1 | ANALOG (3) | | Y | AD7545TQ/883B | 591 |
| 5962-8770202RA | D | 01/07/2004 | 1 | MAXIM INTEG. | | | MX7545TQ/883B | 591 |
| 5962-87702032C | D | 01/07/2004 | 1 | MAXIM INTEG. | | | MX7545UE/883B | 591 |
| 5962-8770203RA | D | 01/07/2004 | 1 | ANALOG (3) | | Y | AD7545UQ/883B | 591 |
| 5962-8770203RA | D | 01/07/2004 | 1 | MAXIM INTEG. | | | MX7545UQ/883B | 591 |
| 5962-87702042A | D | 01/07/2004 | 1 | ANALOG (3) | | Y | AD7545AUE/883B | 591 |
| 5962-8770204RA | D | 01/07/2004 | 1 | ANALOG (3) | | Y | AD7545AUQ/883B | 591 |
| 5962-8770204RA | D | 01/07/2004 | 1 | MAXIM INTEG. | | | MX7545AUQ/883B | 591 |
| 5962-87702052A | D | 01/07/2004 | | (NONE) | | | 7545B (GEN) | 591 |
| 5962-8770205RA | D | 01/07/2004 | | (NONE) | | | 7545B (GEN) | 591 |
| 5962-87702062A | D | 01/07/2004 | | (NONE) | | | 7545A (GEN) | 591 |
| 5962-8770206RA | D | 01/07/2004 | | (NONE) | | | 7545A (GEN) | 591 |
| 5962-8770207RA | D | 01/07/2004 | | (NONE) | | | 7545S (GEN) | 591 |
| 5962-8770301WA | | 11/09/1987 | 1 | LANSDALE | | Y | SL82S212/BWA | 629 |
| 5962-8770302WA | | 11/09/1987 | | (NONE) | | | | 629 |
| 5962-8770303WA | | 11/09/1987 | | (NONE) | | | | 629 |
| 5962-87704013A | C | 03/22/1993 | | (NONE) | | | 29C861 (GEN) | 590 |
| 5962-8770401KA | C | 03/22/1993 | | (NONE) | | | 29C861 (GEN) | 590 |
| 5962-8770401LA | C | 03/22/1993 | | (NONE) | | | 29C861 (GEN) | 590 |
| 5962-87704023A | C | 03/22/1993 | | (NONE) | 08/04/1995 | | 29C863 (GEN) | 590 |
| 5962-8770402KA | C | 03/22/1993 | | (NONE) | 08/04/1995 | | 29C863 (GEN) | 590 |
| 5962-8770402LA | C | 03/22/1993 | | (NONE) | 08/04/1995 | | 29C863 (GEN) | 590 |
| 5962-8770403LA | C | 03/22/1993 | | (NONE) | | | 29C961 (GEN) | 590 |
| 5962-8770404LA | C | 03/22/1993 | | (NONE) | | | 29C963 (GEN) | 590 |
| 5962-87704053A | C | 03/22/1993 | | (NONE) | | | 29C861A (GEN) | 590 |
| 5962-8770405KA | C | 03/22/1993 | | (NONE) | | | 29C861A (GEN) | 590 |
| 5962-8770405LA | C | 03/22/1993 | | (NONE) | | | 29C861A (GEN) | 590 |
| 5962-87704063A | C | 03/22/1993 | | (NONE) | | | 29C863A (GEN) | 590 |
| 5962-8770406KA | C | 03/22/1993 | | (NONE) | | | 29C863A (GEN) | 590 |
| 5962-8770406LA | C | 03/22/1993 | | (NONE) | | | 29C863A (GEN) | 590 |
| 5962-8770501XA | A | 08/08/1990 | 1 | LANSDALE | | Y | SL68172/BXA | 420 |
| 5962-8770601GA | A | 06/26/2000 | | (NONE) | 10/15/2003 | | OP-17A (GEN) | 703 |
| 5962-8770601PA | A | 06/26/2000 | | (NONE) | 10/15/2003 | | OP-17A (GEN) | 703 |
| 5962-8770602GA | A | 06/26/2000 | | (NONE) | 10/15/2003 | | OP-17B (GEN) | 703 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-8770602PA | A | 06/26/2000 | | (NONE) | 10/15/2003 | | OP-17B (GEN) | 703 |
| 5962-87707012A | A | 11/10/1988 | 1 | ROCHESTER | | Y | 2907/B2A | 590 |
| 5962-8770701RA | A | 11/10/1988 | 1 | ROCHESTER | | Y | 2907/BRA | 590 |
| 5962-8770701SA | A | 11/10/1988 | 1 | ROCHESTER | | Y | 2907/BSA | 590 |
| 5962-8770801QA | C | 11/15/1993 | | (NONE) | 05/10/1995 | | 29C10A (GEN) | 420 |
| 5962-8770801UA | C | 11/15/1993 | | (NONE) | 05/10/1995 | | 29C10A (GEN) | 420 |
| 5962-8770802QA | C | 11/15/1993 | | (NONE) | 05/01/1995 | | 39C10B (GEN) | 420 |
| 5962-8770802UA | C | 11/15/1993 | | (NONE) | 05/01/1995 | | 39C10B (GEN) | 420 |
| 5962-8770803QA | C | 11/15/1993 | | (NONE) | 05/01/1995 | | 39C10C (GEN) | 420 |
| 5962-8770803UA | C | 11/15/1993 | | (NONE) | 05/01/1995 | | 39C10C (GEN) | 420 |
| 5962-8770804QA | C | 11/15/1993 | | (NONE) | 03/05/1996 | | 7C910-51 (GEN) | 420 |
| 5962-8770804UA | C | 11/15/1993 | | (NONE) | | | 7C910-51 (GEN) | 420 |
| 5962-8770805QA | C | 11/15/1993 | | (NONE) | 03/05/1996 | | 7C910-46 (GEN) | 420 |
| 5962-8770805UA | C | 11/15/1993 | | (NONE) | | | 7C910-46 (GEN) | 420 |
| 5962-87710012A | G | 10/17/2002 | 1 | TI | | Y | LM158FKB | 710 |
| 5962-8771001GA | G | 10/17/2002 | 1 | NATIONAL | | Y | LM158H/883 | 710 |
| 5962-8771001PA | G | 10/17/2002 | 1 | NATIONAL | | Y | LM158J/883 | 710 |
| 5962-8771001PA | G | 10/17/2002 | 1 | TI | | Y | LM158JGB | 710 |
| 5962-87710022A | G | 10/17/2002 | 1 | TI | | Y | LM158AFKB | 710 |
| 5962-8771002GA | G | 10/17/2002 | 1 | NATIONAL | | Y | LM158AH/883 | 710 |
| 5962-8771002VGA | G | 10/17/2002 | 1 | NATIONAL | | Y | LM158AH-QMLV | 710 |
| 5962L8771002QGA | G | 10/17/2002 | | (NONE) | | | LM158A (GEN) | 710 |
| 5962L8771002VGA | G | 10/17/2002 | 1 | NATIONAL | | Y | LM158AHLQMLV | 710 |
| 5962-8771002PA | G | 10/17/2002 | 1 | NATIONAL | | Y | LM158AJ/883 | 710 |
| 5962-8771002PA | G | 10/17/2002 | 1 | TI | | Y | LM158AJGB | 710 |
| 5962-8771002VPA | G | 10/17/2002 | 1 | NATIONAL | | Y | LM158AJ-QMLV | 710 |
| 5962L8771002QPA | G | 10/17/2002 | 1 | NATIONAL | | Y | LM158AJLQML | 710 |
| 5962L8771002VPA | G | 10/17/2002 | 1 | NATIONAL | | Y | LM158AJLQMLV | 710 |
| 5962-8771002QXA | G | 10/17/2002 | 1 | NATIONAL | | Y | LM158AWG/883 | 710 |
| 5962-8771002VXA | G | 10/17/2002 | 1 | NATIONAL | | Y | LM158AWG-QMLV | 710 |
| 5962L8771002QXA | G | 10/17/2002 | | (NONE) | | | LM158A (GEN) | 710 |
| 5962L8771002VXA | G | 10/17/2002 | 1 | NATIONAL | | Y | LM158AWGLQMLV | 710 |
| 5962-8771101EA | A | 09/19/2001 | 1 | LANSDALE | | Y | SL54221/BEA | 166 |
| 5962-8771101EA | A | 09/19/2001 | 2 | TI | | | SNJ54221J | 166 |
| 5962-8771201XA | B | 12/13/1991 | | (NONE) | | | 2004-25 (GEN) | 612 |
| 5962-8771201YA | B | 12/13/1991 | | (NONE) | | | 2004-25 (GEN) | 612 |
| 5962-8771202XA | B | 12/13/1991 | | (NONE) | | | 2004 (GEN) | 612 |
| 5962-8771202YA | B | 12/13/1991 | | (NONE) | | | 2004 (GEN) | 612 |
| 5962-8771301QA | A | 11/14/1991 | | (NONE) | 06/15/1996 | | 8274 (GEN) | 420 |
| 5962-8771401GA | C | 12/17/2003 | | (NONE) | 04/14/2001 | | OP-14A (GEN) | 710 |
| 5962-8771401PA | C | 12/17/2003 | | (NONE) | 04/14/2001 | | OP-14A (GEN) | 710 |
| 5962-8771402GA | C | 12/17/2003 | | (NONE) | | | OP-14B (GEN) | 710 |
| 5962-8771402PA | C | 12/17/2003 | | (NONE) | | | OP-14B (GEN) | 710 |
| 5962-8771501CA | A | 08/28/2000 | 1 | MINCO | | Y | MTL1002AMJ/883 | 710 |
| 5962-8771601EA | A | 12/13/2000 | 1 | ANALOG (5) | | Y | MUX-08AQ | 193 |
| 5962-87716022A | A | 12/13/2000 | 1 | ANALOG (5) | | Y | MUX-08BRC | 193 |
| 5962-8771602EA | A | 12/13/2000 | 1 | ANALOG (5) | | Y | MUX-08BQ | 193 |
| 5962-8771701XA | B | 12/11/2002 | 1 | ANALOG (5) | | Y | MUX-16AT | 195 |
| 5962-87717023A | B | 12/11/2002 | 1 | ANALOG (5) | | Y | MUX-16BTC | 195 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-8771702XA | B | 12/11/2002 | 1 | ANALOG (5) | | Y | MUX-16BT | 195 |
| 5962-8771801EA | A | 12/13/2000 | | (NONE) | | | MUX-24A (GEN) | 192 |
| 5962-8771802EA | A | 12/13/2000 | | (NONE) | | | MUX-24B (GEN) | 192 |
| 5962-87719012A | C | 11/02/2000 | | (NONE) | | | AD625 (GEN) | 754 |
| 5962-8771901EA | C | 11/02/2000 | 1 | ANALOG (2) | | Y | AD625SD/883B | 754 |
| 5962-87721012A | C | 07/13/2000 | 3 | TI | | Y | SNJ54HC125FK | 520 |
| 5962-8772101CA | C | 07/13/2000 | 3 | TI | | Y | SNJ54HC125J | 520 |
| 5962-8772101DA | C | 07/13/2000 | | (NONE) | | | 54HC125 (GEN) | 520 |
| 5962-87722012A | | 10/13/1987 | | (NONE) | | | 54HC4075 (GEN) | 125 |
| 5962-8772201CA | | 10/13/1987 | 1 | TI | | Y | CD54HC4075BF3A | 125 |
| 5962-8772201DA | | 10/13/1987 | | (NONE) | | | 54HC4075 (GEN) | 125 |
| 5962-87723012A | | 10/19/1987 | 1 | ROCHESTER | | Y | 54HC133/B2A | 108 |
| 5962-8772301EA | | 10/19/1987 | 1 | ROCHESTER | | Y | 54HC133/BEA | 108 |
| 5962-87724012A | B | 01/25/2002 | 3 | TI | | Y | SNJ54HC193FK | 304 |
| 5962-8772401EA | B | 01/25/2002 | 3 | TI | | Y | CD54HC193F3A | 304 |
| 5962-8772401EA | B | 01/25/2002 | 3 | TI | | Y | SNJ54HC193J | 304 |
| 5962-8772401VXA | B | 01/25/2002 | 2 | STMICRO | | Y | 54HC193K02V | 304 |
| 5962-8772401VXC | B | 01/25/2002 | 2 | STMICRO | | Y | 54HC193K01V | 304 |
| 5962-8772401XA | B | 01/25/2002 | 2 | STMICRO | | Y | 54HC193K02Q | 304 |
| 5962-8772401XC | B | 01/25/2002 | 2 | STMICRO | | Y | 54HC193K01Q | 304 |
| 5962-8772501RA | A | 03/22/1988 | 1 | TI | | Y | CD54HCT273F3A | 159 |
| 5962-87727012A | B | 12/09/1991 | 1 | AUSTIN SEMI. | | Y | AS10H507C16/883C | 140 |
| 5962-8772701EA | B | 12/09/1991 | 1 | AUSTIN SEMI. | | Y | AS10H507EC16/883C | 140 |
| 5962-8772701FA | B | 12/09/1991 | | (NONE) | 09/30/1995 | | 10H507 (GEN) | 140 |
| 5962-87728012A | B | 12/09/1991 | | (NONE) | | | 10H519 (GEN) | 142 |
| 5962-8772801EA | B | 12/09/1991 | | (NONE) | | | 10H519 (GEN) | 142 |
| 5962-8772801FA | B | 12/09/1991 | | (NONE) | | | 10H519 (GEN) | 142 |
| 5962-87729012A | D | 08/17/1998 | 1 | AUSTIN SEMI. | | Y | AS10H564EC20/883C | 271 |
| 5962-8772901EA | D | 08/17/1998 | 1 | AUSTIN SEMI. | | Y | AS10H564C16/883C | 271 |
| 5962-8772901FA | D | 08/17/1998 | | (NONE) | 09/30/1995 | | 10H564 (GEN) | 271 |
| 5962-8772901XA | D | 08/17/1998 | 1 | AUSTIN SEMI. | | Y | AS10H564F16/883C | 271 |
| 5962-87730012A | B | 12/10/1991 | | (NONE) | | | 10H521 (GEN) | 142 |
| 5962-8773001EA | B | 12/10/1991 | | (NONE) | | | 10H521 (GEN) | 142 |
| 5962-8773001FA | B | 12/10/1991 | | (NONE) | | | 10H521 (GEN) | 142 |
| 5962-87732012A | B | 10/21/1991 | | (NONE) | | | 54HC76 (GEN) | 156 |
| 5962-8773201EA | B | 10/21/1991 | | (NONE) | | | 54HC76 (GEN) | 156 |
| 5962-87733012A | A | 11/26/1990 | | (NONE) | | | 54HC4511 (GEN) | 291 |
| 5962-8773301EA | A | 11/26/1990 | 1 | TI | | Y | CD54HC4511F3A | 291 |
| 5962-8773401VA | B | 05/14/1992 | | (NONE) | 12/24/1997 | | 82C28410 (GEN) | 422 |
| 5962-8773402VA | B | 05/14/1992 | | (NONE) | 12/24/1997 | | 82C2848 (GEN) | 422 |
| 5962-8773403VA | B | 05/14/1992 | | (NONE) | 12/24/1997 | | 82C2846 (GEN) | 422 |
| 5962-8773501XC | B | 06/01/1998 | | (NONE) | 09/07/2001 | | 2100S (GEN) | 432 |
| 5962-8773502XA | B | 06/01/1998 | | (NONE) | | | 2100T (GEN) | 432 |
| 5962-8773503XC | B | 06/01/1998 | | (NONE) | 09/07/2001 | | 2100AS (GEN) | 432 |
| 5962-8773504XC | B | 06/01/1998 | | (NONE) | 09/07/2001 | | 2100AT (GEN) | 432 |
| 5962-8773505XC | B | 06/01/1998 | | (NONE) | 09/07/2001 | | 2100AU (GEN) | 432 |
| 5962-8773506XC | B | 06/01/1998 | | (NONE) | 09/07/2001 | | 2100AV (GEN) | 432 |
| 5962-87738012A | D | 07/16/2003 | 1 | ANALOG (2) | | Y | OP-77BRC/883 | 701 |
| 5962-8773801GA | D | 07/16/2003 | 1 | ANALOG (2) | | Y | OP-77BJ/883 | 701 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-8773801PA | D | 07/16/2003 | 1 | ANALOG (2) | | Y | OP-77BZ/883 | 701 |
| 5962-8773802V2A | D | 07/16/2003 | 1 | ANALOG (5) | | Y | OP77ARC/QMLV | 701 |
| 5962-8773802GA | D | 07/16/2003 | 1 | ANALOG (2) | | Y | OP-77AJ/883 | 701 |
| 5962-8773802VGA | D | 07/16/2003 | 1 | ANALOG (5) | | Y | OP77AJ/QMLV | 701 |
| 5962-8773802VHA | D | 07/16/2003 | 1 | ANALOG (5) | | Y | OP77AL/QMLV | 701 |
| 5962-8773802PA | D | 07/16/2003 | 1 | ANALOG (2) | | Y | OP-77AZ/883 | 701 |
| 5962-8773802VPA | D | 07/16/2003 | 1 | ANALOG (5) | | Y | OP77AZ/QMLV | 701 |
| 5962-8773803GA | D | 07/16/2003 | | (NONE) | 03/30/2001 | | LT1001A (GEN) | 701 |
| 5962-8773803PA | D | 07/16/2003 | | (NONE) | 03/30/2001 | | LT1001A (GEN) | 701 |
| 5962-87739012A | G | 08/08/2002 | 1 | NATIONAL | | Y | LM139AE-SMD | 776 |
| 5962-87739012A | G | 08/08/2002 | | TI | | | LM139AFKB | 776 |
| 5962-8773901V2A | G | 08/08/2002 | 1 | ANALOG (5) | | Y | PM139ARC/QMLV | 776 |
| 5962R8773901V2A | G | 08/08/2002 | 1 | ANALOG (5) | | Y | PM139ARC/QMLR | 776 |
| 5962-8773901CA | G | 08/08/2002 | 1 | NATIONAL | | Y | LM139AJ-SMD | 776 |
| 5962-8773901CA | G | 08/08/2002 | | TI | | | LM139AJB | 776 |
| 5962-8773901VCA | G | 08/08/2002 | 1 | ANALOG (5) | | Y | PM139AY/QMLV | 776 |
| 5962R8773901VCA | G | 08/08/2002 | 1 | ANALOG (5) | | Y | PM139AY/QMLR | 776 |
| 5962-8773901DA | G | 08/08/2002 | 1 | NATIONAL | | Y | LM139AW-SMD | 776 |
| 5962-8773901DA | G | 08/08/2002 | | TI | | Y | LM139AWB | 776 |
| 5962-8773901VDA | G | 08/08/2002 | 1 | ANALOG (5) | | Y | PM139AM/QMLV | 776 |
| 5962R8773901VDA | G | 08/08/2002 | 1 | ANALOG (5) | | Y | PM139AM/QMLR | 776 |
| 5962-8773901XA | G | 08/08/2002 | 1 | NATIONAL | | Y | LM139AWG-SMD | 776 |
| 5962R8773902V2A | G | 08/08/2002 | 1 | ANALOG (5) | | Y | PM139RC/QMLR | 776 |
| 5962R8773902VCA | G | 08/08/2002 | 1 | ANALOG (5) | | Y | PM139Y/QMLR | 776 |
| 5962R8773902VDA | G | 08/08/2002 | 1 | ANALOG (5) | | Y | PM139M/QMLR | 776 |
| 5962-8774001EA | B | 09/25/2002 | | MICROSEMI | | Y | SG1543J/883B | 787 |
| 5962-8774001EA | B | 09/25/2002 | 1 | SEMELAB | | Y | IP1543J-DESC | 787 |
| 5962-8774001EA | B | 09/25/2002 | 3 | TI | | Y | UC1543J/883B | 787 |
| 5962-8774002VA | B | 09/25/2002 | | MICROSEMI | | Y | SG1544J/883B | 787 |
| 5962-8774002VA | B | 09/25/2002 | 1 | SEMELAB | | Y | IP1544J-DESC | 787 |
| 5962-8774101TA | F | 04/30/2002 | 3 | INTER. RECT. | | | OM3914NT/883B | 781 |
| 5962-8774101UA | F | 04/30/2002 | 3 | INTER. RECT. | | | OM3914ST/883B | 781 |
| 5962P8774101UA | F | 04/30/2002 | 1 | INTER. RECT. | | | OMR3914STM/883B | 781 |
| 5962-8774101XA | F | 04/30/2002 | 1 | INTER. RECT. | | | OM3914NKM/883B | 781 |
| 5962-8774101YA | F | 04/30/2002 | 3 | INTER. RECT. | | | OM3914SRM/883B | 781 |
| 5962-87742012A | C | 04/22/2003 | 1 | TI | | Y | UC1834L/883B | 789 |
| 5962-8774201V2A | C | 04/22/2003 | 1 | TI | | Y | UC1834LQMLV | 789 |
| 5962-8774201EA | C | 04/22/2003 | 1 | TI | | Y | UC1834J/883B | 789 |
| 5962-8774201VEA | C | 04/22/2003 | 1 | TI | | Y | UC1834JQMLV | 789 |
| 5962-8774301MEA | A | 09/24/1992 | 1 | LANSDALE | | Y | SL12511E1 | 350 |
| 5962-8774301MFA | A | 09/24/1992 | 1 | LANSDALE | | Y | SL12511F1 | 350 |
| 5962-8774401QA | | 10/09/1987 | | (NONE) | 04/15/1994 | | 27210 (GEN) | 664 |
| 5962-8774402QA | | 10/09/1987 | | (NONE) | | | 27210 (GEN) | 664 |
| 5962-8774801MEA | A | 09/24/1992 | 1 | LANSDALE | | Y | ML12509E1 | 350 |
| 5962-8774801MFA | A | 09/24/1992 | 1 | LANSDALE | | Y | ML12509F1 | 350 |
| 5962-8774901MEA | B | 03/26/1993 | 1 | LANSDALE | | Y | ML12513E1 | 350 |
| 5962-87750012A | | 07/22/1988 | | (NONE) | | | 10612 (GEN) | 149 |
| 5962-8775001EA | | 07/22/1988 | | (NONE) | | | 10612 (GEN) | 149 |
| 5962-8775001FA | | 07/22/1988 | | (NONE) | | | 10612 (GEN) | 149 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-8775101MEA | | 01/20/1993 | | (NONE) | 09/30/1995 | | 12514 (GEN) | 410 |
| 5962-87752012A | A | 12/23/1991 | | LANSDALE | | Y | ML12540/B2A | 802 |
| 5962-8775201CA | A | 12/23/1991 | | LANSDALE | | Y | ML12540/BCA | 802 |
| 5962-8775301EA | | 07/19/1988 | | (NONE) | | | 14551B (GEN) | 199 |
| 5962-8775401EA | | 05/25/1988 | 1 | TI | | Y | CD54HC4053F3A | 199 |
| 5962-87755013A | A | 03/05/2001 | | (NONE) | 08/04/1995 | | 29821A (GEN) | 421 |
| 5962-8775501KA | A | 03/05/2001 | | (NONE) | 08/04/1995 | | 29821A (GEN) | 421 |
| 5962-8775501LA | A | 03/05/2001 | | (NONE) | 08/04/1995 | | 29821A (GEN) | 421 |
| 5962-87755023A | A | 03/05/2001 | | (NONE) | 08/04/1995 | | 29823A (GEN) | 421 |
| 5962-8775502KA | A | 03/05/2001 | | (NONE) | 08/04/1995 | | 29823A (GEN) | 421 |
| 5962-8775502LA | A | 03/05/2001 | | (NONE) | 08/04/1995 | | 29823A (GEN) | 421 |
| 5962-87755033A | A | 03/05/2001 | | (NONE) | 06/30/1994 | | 29825A (GEN) | 421 |
| 5962-8775503KA | A | 03/05/2001 | | (NONE) | 06/30/1994 | | 29825A (GEN) | 421 |
| 5962-8775503LA | A | 03/05/2001 | | (NONE) | 06/30/1994 | | 29825A (GEN) | 421 |
| 5962-8775504LA | A | 03/05/2001 | | (NONE) | | | 29921A (GEN) | 421 |
| 5962-8775505LA | A | 03/05/2001 | | (NONE) | | | 29923A (GEN) | 421 |
| 5962-8775506LA | A | 03/05/2001 | | (NONE) | | | 29925A (GEN) | 421 |
| 5962-8775507Q3A | A | 03/05/2001 | 3 | SARNOFF | | Y | GEM32307Q3A | 421 |
| 5962-8775507Q3C | A | 03/05/2001 | 3 | SARNOFF | | Y | GEM32307Q3C | 421 |
| 5962-8775507QKA | A | 03/05/2001 | 3 | SARNOFF | | Y | GEM32307QKA | 421 |
| 5962-8775507QKC | A | 03/05/2001 | 3 | SARNOFF | | Y | GEM32307QKC | 421 |
| 5962-8775507QLA | A | 03/05/2001 | | (NONE) | | | 29823A (GEN) | 421 |
| 5962-8775508Q3A | A | 03/05/2001 | 3 | SARNOFF | | Y | GEM32208Q3A | 421 |
| 5962-8775508Q3C | A | 03/05/2001 | 3 | SARNOFF | | Y | GEM32208Q3C | 421 |
| 5962-8775508QKA | A | 03/05/2001 | 3 | SARNOFF | | Y | GEM32208QKA | 421 |
| 5962-8775508QKC | A | 03/05/2001 | 3 | SARNOFF | | Y | GEM32208QKC | 421 |
| 5962-8775508QLA | A | 03/05/2001 | | (NONE) | | | 29825A (GEN) | 421 |
| 5962-8775509QLA | A | 03/05/2001 | 3 | SARNOFF | | Y | GEM32109QLA | 421 |
| 5962-8775509QLC | A | 03/05/2001 | 3 | SARNOFF | | Y | GEM32109QLC | 421 |
| 5962-87756012A | C | 08/07/2001 | 3 | NATIONAL | | Y | 54AC273LMQB | 159 |
| 5962-8775601RA | C | 08/07/2001 | 3 | NATIONAL | | Y | 54AC273DMQB | 159 |
| 5962-8775601SA | C | 08/07/2001 | 3 | NATIONAL | | Y | 54AC273FMQB | 159 |
| 5962-8775601VSA | C | 08/07/2001 | | (NONE) | | | 54AC273 (GEN) | 159 |
| 5962-8775601VXA | C | 08/07/2001 | 2 | STMICRO | | Y | 54AC273K02V | 159 |
| 5962-8775601VXC | C | 08/07/2001 | 2 | STMICRO | | Y | 54AC273K01V | 159 |
| 5962-8775601XA | C | 08/07/2001 | 2 | STMICRO | | Y | 54AC273K02Q | 159 |
| 5962-8775601XC | C | 08/07/2001 | 2 | STMICRO | | Y | 54AC273K01Q | 159 |
| 5962-8775601ZA | C | 08/07/2001 | 3 | NATIONAL | | Y | 54AC273WG-QML | 159 |
| 5962-87757012A | A | 12/18/2001 | 3 | NATIONAL | | Y | 54ACT174LMQB | 159 |
| 5962-8775701EA | A | 12/18/2001 | 3 | NATIONAL | | Y | 54ACT174DMQB | 159 |
| 5962-8775701FA | A | 12/18/2001 | 3 | NATIONAL | | Y | 54ACT174FMQB | 159 |
| 5962-8775701VXA | A | 12/18/2001 | 2 | STMICRO | | Y | 54ACT174K02V | 159 |
| 5962-8775701VXC | A | 12/18/2001 | 2 | STMICRO | | Y | 54ACT174K01V | 159 |
| 5962-8775701XA | A | 12/18/2001 | 2 | STMICRO | | Y | 54ACT174K02Q | 159 |
| 5962-8775701XC | A | 12/18/2001 | 2 | STMICRO | | Y | 54ACT174K01Q | 159 |
| 5962-87758012A | E | 07/23/2001 | 3 | NATIONAL | | Y | 54AC245LMQB | 590 |
| 5962-87758012A | E | 07/23/2001 | 3 | TI | | Y | SNJ54AC245FK | 590 |
| 5962-8775801RA | E | 07/23/2001 | 3 | NATIONAL | | Y | 54AC245DMQB | 590 |
| 5962-8775801RA | E | 07/23/2001 | 3 | TI | | Y | SNJ54AC245J | 590 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-8775801VRA | E | 07/23/2001 | 3 | TI | | Y | SNV54AC245J | 590 |
| 5962-8775801SA | E | 07/23/2001 | 3 | NATIONAL | | Y | 54AC245FMQB | 590 |
| 5962-8775801SA | E | 07/23/2001 | 3 | TI | | Y | SNJ54AC245W | 590 |
| 5962-8775801VSA | E | 07/23/2001 | 3 | TI | | Y | SNV54AC245W | 590 |
| 5962-8775801VXA | E | 07/23/2001 | 2 | STMICRO | | Y | 54AC245K02V | 590 |
| 5962-8775801VXC | E | 07/23/2001 | 2 | STMICRO | | Y | 54AC245K01V | 590 |
| 5962-8775801XA | E | 07/23/2001 | 2 | STMICRO | | Y | 54AC245K02Q | 590 |
| 5962-8775801XC | E | 07/23/2001 | 2 | STMICRO | | Y | 54AC245K01Q | 590 |
| 5962-8775801ZA | E | 07/23/2001 | 3 | NATIONAL | | Y | 54AC245WG-QML | 590 |
| 5962-87759012A | C | 12/17/2002 | | (NONE) | 5962-8775901M2A | | 54ACT240 (GEN) | 529 |
| 5962-8775901B2A | C | 12/17/2002 | 3 | NATIONAL | | Y | JM54ACT240B2A | 529 |
| 5962-8775901M2A | C | 12/17/2002 | 3 | NATIONAL | | Y | 54ACT240LMQB | 529 |
| 5962-8775901M2A | C | 12/17/2002 | 2 | TI | | Y | SNJ54ACT240FK | 529 |
| 5962-8775901S2A | C | 12/17/2002 | | (NONE) | | | 54ACT240 (GEN) | 529 |
| 5962R8775901B2A | C | 12/17/2002 | 3 | NATIONAL | | Y | JM54ACT240B2A-R | 529 |
| 5962R8775901S2A | C | 12/17/2002 | 3 | NATIONAL | | Y | JM54ACT240S2A-R | 529 |
| 5962-8775901BRA | C | 12/17/2002 | 3 | NATIONAL | | Y | JM54ACT240BRA | 529 |
| 5962-8775901MRA | C | 12/17/2002 | 3 | NATIONAL | | Y | 54ACT240DMQB | 529 |
| 5962-8775901MRA | C | 12/17/2002 | 2 | TI | | Y | SNJ54ACT240J | 529 |
| 5962-8775901RA | C | 12/17/2002 | | (NONE) | 5962-8775901MRA | | 54ACT240 (GEN) | 529 |
| 5962-8775901SRA | C | 12/17/2002 | | (NONE) | | | 54ACT240 (GEN) | 529 |
| 5962R8775901BRA | C | 12/17/2002 | 3 | NATIONAL | | Y | JM54ACT240BRA-R | 529 |
| 5962R8775901SRA | C | 12/17/2002 | 3 | NATIONAL | | Y | JM54ACT240SRA-R | 529 |
| 5962-8775901BSA | C | 12/17/2002 | 3 | NATIONAL | | Y | JM54ACT240BSA | 529 |
| 5962-8775901MSA | C | 12/17/2002 | 3 | NATIONAL | | Y | 54ACT240FMQB | 529 |
| 5962-8775901MSA | C | 12/17/2002 | 2 | TI | | Y | SNJ54ACT240W | 529 |
| 5962-8775901SA | C | 12/17/2002 | | (NONE) | 5962-8775901MSA | | 54ACT240 (GEN) | 529 |
| 5962-8775901SSA | C | 12/17/2002 | | (NONE) | | | 54ACT240 (GEN) | 529 |
| 5962R8775901BSA | C | 12/17/2002 | 3 | NATIONAL | | Y | JM54ACT240BSA-R | 529 |
| 5962R8775901SSA | C | 12/17/2002 | 3 | NATIONAL | | Y | JM54ACT240SSA-R | 529 |
| 5962-87759023A | C | 12/17/2002 | | (NONE) | 09/15/1995 | | 54ACT11240 (GEN) | 529 |
| 5962-8775902M3A | C | 12/17/2002 | | (NONE) | 09/15/1995 | | 54ACT11240 (GEN) | 529 |
| 5962-8775902LA | C | 12/17/2002 | | (NONE) | 09/15/1995 | | 54ACT11240 (GEN) | 529 |
| 5962-8775902MLA | C | 12/17/2002 | | (NONE) | 09/15/1995 | | 54ACT11240 (GEN) | 529 |
| 5962-8775903QXA | C | 12/17/2002 | 2 | STMICRO | | Y | 54ACT240K02Q | 529 |
| 5962-8775903QXC | C | 12/17/2002 | 2 | STMICRO | | Y | 54ACT240K01Q | 529 |
| 5962-8775903VXA | C | 12/17/2002 | 2 | STMICRO | | Y | 54ACT240K02V | 529 |
| 5962-8775903VXC | C | 12/17/2002 | 2 | STMICRO | | Y | 54ACT240K01V | 529 |
| 5962-87760012A | F | 11/06/2003 | | (NONE) | 5962-8776001M2A | | 54ACT244 (GEN) | 529 |
| 5962-8776001B2A | F | 11/06/2003 | 3 | NATIONAL | | Y | JM54ACT244B2A | 529 |
| 5962-8776001M2A | F | 11/06/2003 | 3 | NATIONAL | | Y | 54ACT244LMQB | 529 |
| 5962-8776001M2A | F | 11/06/2003 | 2 | TI | | Y | SNJ54ACT244FK | 529 |
| 5962-8776001S2A | F | 11/06/2003 | 2 | TI | | Y | SNV54ACT244FK | 529 |
| 5962R8776001B2A | F | 11/06/2003 | 3 | NATIONAL | | Y | JM54ACT244B2A-RH | 529 |
| 5962R8776001S2A | F | 11/06/2003 | 3 | NATIONAL | | Y | JM54ACT244S2A-RH | 529 |
| 5962-8776001BRA | F | 11/06/2003 | 3 | NATIONAL | | Y | JM54ACT244BRA | 529 |
| 5962-8776001MRA | F | 11/06/2003 | 3 | NATIONAL | | Y | 54ACT244DMQB | 529 |
| 5962-8776001MRA | F | 11/06/2003 | 2 | TI | | Y | SNJ54ACT244J | 529 |
| 5962-8776001RA | F | 11/06/2003 | | (NONE) | 5962-8776001MRA | | 54ACT244 (GEN) | 529 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-8776001SRA | F | 11/06/2003 | 2 | TI | | Y | SNV54ACT244J | 529 |
| 5962R8776001BRA | F | 11/06/2003 | 3 | NATIONAL | | Y | JM54ACT244BRA-RH | 529 |
| 5962R8776001SRA | F | 11/06/2003 | 3 | NATIONAL | | Y | JM54ACT244SRA-RH | 529 |
| 5962-8776001BSA | F | 11/06/2003 | 3 | NATIONAL | | Y | JM54ACT244BSA | 529 |
| 5962-8776001MSA | F | 11/06/2003 | 3 | NATIONAL | | Y | 54ACT244FMQB | 529 |
| 5962-8776001MSA | F | 11/06/2003 | 2 | TI | | Y | SNJ54ACT244W | 529 |
| 5962-8776001SA | F | 11/06/2003 | | (NONE) | 5962-8776001MSA | | 54ACT244 (GEN) | 529 |
| 5962-8776001SSA | F | 11/06/2003 | 2 | TI | | Y | SNV54ACT244W | 529 |
| 5962F8776001SSA | F | 11/06/2003 | 3 | NATIONAL | | Y | JM54ACT244SSA-F | 529 |
| 5962R8776001BSA | F | 11/06/2003 | 3 | NATIONAL | | Y | JM54ACT244BSA-RH | 529 |
| 5962R8776001SSA | F | 11/06/2003 | 3 | NATIONAL | | Y | JM54ACT244SSA-RH | 529 |
| 5962F8776001SZA | F | 11/06/2003 | 3 | NATIONAL | | Y | JM54ACT244SZA-F | 529 |
| 5962R8776001SZA | F | 11/06/2003 | 3 | NATIONAL | | Y | JM54ACT244SZA-RH | 529 |
| 5962-87760023A | F | 11/06/2003 | | (NONE) | 09/15/1995 | | 54ACT11244 (GEN) | 529 |
| 5962-8776002M3A | F | 11/06/2003 | | (NONE) | 09/15/1995 | | 54ACT11244 (GEN) | 529 |
| 5962-8776002LA | F | 11/06/2003 | | (NONE) | 09/15/1995 | | 54ACT11244 (GEN) | 529 |
| 5962-8776002MLA | F | 11/06/2003 | | (NONE) | 09/15/1995 | | 54ACT11244 (GEN) | 529 |
| 5962-8776003QXA | F | 11/06/2003 | 2 | STMICRO | | Y | 54ACT244K02Q | 529 |
| 5962-8776003QXC | F | 11/06/2003 | 2 | STMICRO | | Y | 54ACT244K01Q | 529 |
| 5962-8776003VXA | F | 11/06/2003 | 2 | STMICRO | | Y | 54ACT244K02V | 529 |
| 5962-8776003VXC | F | 11/06/2003 | 2 | STMICRO | | Y | 54ACT244K01V | 529 |
| 5962-87761012A | | 01/22/1988 | 3 | NATIONAL | | Y | 54ACT253LMQB | 274 |
| 5962-8776101EA | | 01/22/1988 | 3 | NATIONAL | | Y | 54ACT253DMQB | 274 |
| 5962-8776101FA | | 01/22/1988 | 3 | NATIONAL | | Y | 54ACT253FMQB | 274 |
| 5962-87762012A | A | 12/21/2000 | | (NONE) | | | AD7575S (GEN) | 592 |
| 5962-8776201VA | A | 12/21/2000 | | (NONE) | | | AD7575S (GEN) | 592 |
| 5962-87762022A | A | 12/21/2000 | | (NONE) | | | AD7575T (GEN) | 592 |
| 5962-8776202VA | A | 12/21/2000 | 1 | ANALOG (3) | | Y | AD7575TQ/883B | 592 |
| 5962-87763013C | A | 01/27/2004 | 1 | MAXIM INTEG. | | | MX7537SE/883B | 591 |
| 5962-8776301LA | A | 01/27/2004 | 1 | ANALOG (3) | | Y | AD7537SQ/883B | 591 |
| 5962-8776301LA | A | 01/27/2004 | 1 | MAXIM INTEG. | | | MX7537SQ/883B | 591 |
| 5962-87763023C | A | 01/27/2004 | 1 | MAXIM INTEG. | | | MX7537TE/883B | 591 |
| 5962-8776302LA | A | 01/27/2004 | 1 | MAXIM INTEG. | | | MX7537TQ/883B | 591 |
| 5962-87763033C | A | 01/27/2004 | 1 | MAXIM INTEG. | | | MX7537UE/883B | 591 |
| 5962-8776303LA | A | 01/27/2004 | 1 | ANALOG (3) | | Y | AD7537UQ/883B | 591 |
| 5962-8776303LA | A | 01/27/2004 | 1 | MAXIM INTEG. | | | MX7537UQ/883B | 591 |
| 5962-87766012A | C | 07/17/2001 | 2 | TI | | | SNJ54AS804BFK | 509 |
| 5962-8776601RA | C | 07/17/2001 | 2 | TI | | | SNJ54AS804BJ | 509 |
| 5962-8776601SA | C | 07/17/2001 | 2 | TI | | | SNJ54AS804BW | 509 |
| 5962-87767012A | A | 06/27/2001 | 3 | TI | | | SNJ54AS760FK | 529 |
| 5962-8776701RA | A | 06/27/2001 | 3 | TI | | | SNJ54AS760J | 529 |
| 5962-8776701SA | A | 06/27/2001 | 3 | TI | | | SNJ54AS760W | 529 |
| 5962-87769012A | A | 09/12/2001 | | (NONE) | 12/31/2001 | | 55121 (GEN) | 569 |
| 5962-8776901EA | A | 09/12/2001 | | (NONE) | 12/31/2001 | | 55121 (GEN) | 569 |
| 5962-87770012A | B | 10/02/2002 | 1 | MICROSEMI | | Y | SG1532L | 780 |
| 5962-8777001CA | B | 10/02/2002 | | MICROSEMI | | Y | SG1532J | 780 |
| 5962-8777001IA | B | 10/02/2002 | | MICROSEMI | | Y | SG1532T | 780 |
| 5962-87771013A | D | 12/17/2002 | | (NONE) | | | OP-400A (GEN) | 713 |
| 5962-8777101M3A | D | 12/17/2002 | 1 | ANALOG (5) | | Y | OP400ATC/883 | 713 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-8777101V3A | D | 12/17/2002 | 1 | ANALOG (5) | | Y | OP400ATC/QML | 713 |
| 5962-8777101CA | D | 12/17/2002 | | (NONE) | | | OP-400A (GEN) | 713 |
| 5962-8777101MCA | D | 12/17/2002 | 1 | ANALOG (5) | | Y | OP400AY/883 | 713 |
| 5962-8777101VCA | D | 12/17/2002 | 1 | ANALOG (5) | | Y | OP400AY/QML | 713 |
| 5962-8777101VKA | D | 12/17/2002 | 1 | ANALOG (5) | | Y | OP400AN/QML | 713 |
| 5962-8777201LA | A | 09/10/2001 | | (NONE) | 06/30/1994 | | 2952A (GEN) | 421 |
| 5962-8777202LA | A | 09/10/2001 | | (NONE) | | | 2953A (GEN) | 421 |
| 5962-87773012A | A | 03/26/1993 | | (NONE) | 09/30/1995 | | 10598 (GEN) | 165 |
| 5962-8777301EA | A | 03/26/1993 | | (NONE) | 09/30/1995 | | 10598 (GEN) | 165 |
| 5962-8777301FA | A | 03/26/1993 | | (NONE) | 09/30/1995 | | 10598 (GEN) | 165 |
| 5962-8777401YA | A | 06/16/2004 | 1 | SEMELAB | | Y | LM109K-DESC | 782 |
| 5962-8777501YA | B | 06/18/2004 | 1 | SEMELAB | | Y | IP123K-05-DESC | 782 |
| 5962-8777502YA | B | 06/18/2004 | 1 | SEMELAB | | Y | IP123AK-05-DESC | 782 |
| 5962-87776012A | H | 10/09/2002 | 3 | INTER. RECT. | | | OM1812N2/883B | 782 |
| 5962-87776012A | H | 10/09/2002 | 1 | MICROSEMI | | Y | SG7812AL/883B | 782 |
| 5962-87776012A | H | 10/09/2002 | 1 | SOLITRON | | | SDP7812A2MD | 782 |
| 5962-87776014A | H | 10/09/2002 | 1 | INTER. RECT. | | | OM1812SRM | 782 |
| 5962-87776015A | H | 10/09/2002 | 1 | INTER. RECT. | | | OM1812N5M | 782 |
| 5962-8777601MA | H | 10/09/2002 | 3 | INTER. RECT. | | | OM1812SM/883B | 782 |
| 5962-8777601NA | H | 10/09/2002 | 3 | INTER. RECT. | | | OM1812NM/883B | 782 |
| 5962-8777601NA | H | 10/09/2002 | 1 | SOLITRON | | | SDP7812ANMD | 782 |
| 5962-8777601PA | H | 10/09/2002 | 1 | SEMELAB | | Y | IP78M12AJ-DESC | 782 |
| 5962-8777601TA | H | 10/09/2002 | 0 | INTER. RECT. | | | OM7812AH/883B | 782 |
| 5962-8777601TA | H | 10/09/2002 | 1 | SEMELAB | | Y | IP7812AG-DESC | 782 |
| 5962-8777601TA | H | 10/09/2002 | 1 | SOLITRON | | | SDP7812ATMD | 782 |
| 5962-8777601UA | H | 10/09/2002 | 0 | INTER. RECT. | | | OM7812AIH/883B | 782 |
| 5962-8777601UA | H | 10/09/2002 | 1 | MICROSEMI | | Y | SG7812AIG/883B | 782 |
| 5962-8777601UA | H | 10/09/2002 | 1 | SEMELAB | | Y | IP7812AIG-DESC | 782 |
| 5962-8777601UA | H | 10/09/2002 | 1 | SOLITRON | | | SDP7812AUMD | 782 |
| 5962F8777601UA | H | 10/09/2002 | 3 | INTER. RECT. | | | OMR1812STM/883B | 782 |
| 5962-8777601XA | H | 10/09/2002 | 1 | MICROSEMI | | Y | SG7812AT/883B | 782 |
| 5962-8777601XA | H | 10/09/2002 | 1 | SEMELAB | | Y | IP78M12AH-DESC | 782 |
| 5962-8777601YA | H | 10/09/2002 | 3 | INTER. RECT. | | | OM1812NK/883B | 782 |
| 5962-8777601YA | H | 10/09/2002 | 1 | MICROSEMI | | Y | SG7812AK/883B | 782 |
| 5962-8777601YA | H | 10/09/2002 | 1 | SEMELAB | | Y | IP7812AK-DESC | 782 |
| 5962-8777601ZA | H | 10/09/2002 | 1 | MICROSEMI | | Y | SG7812AR/883B | 782 |
| 5962-8777601ZA | H | 10/09/2002 | 1 | SEMELAB | | Y | IP7812AR-DESC | 782 |
| 5962-8777601ZA | H | 10/09/2002 | 1 | SOLITRON | | | SDP7812AZMD | 782 |
| 5962-87776022A | H | 10/09/2002 | | (NONE) | 05/31/1994 | | 78M12 (GEN) | 782 |
| 5962-8777602PA | H | 10/09/2002 | 1 | SEMELAB | | Y | IP78M12J-DESC | 782 |
| 5962-8777602XA | H | 10/09/2002 | 1 | SEMELAB | | Y | IP78M12H-DESC | 782 |
| 5962-8777701XA | B | 01/16/2001 | 2 | NATIONAL | | Y | LM194H/883 | 790 |
| 5962-8777801XA | A | 01/16/2001 | 3 | NATIONAL | | Y | LM195H/883 | 790 |
| 5962-8777801YA | A | 01/16/2001 | 3 | NATIONAL | | Y | LM195K/883 | 790 |
| 5962-8778001CA | | 08/25/1989 | | (NONE) | | | INA101 (GEN) | 754 |
| 5962-8778002IA | | 08/25/1989 | | (NONE) | | | INA101 (GEN) | 754 |
| 5962-87782012A | J | 03/09/2004 | 1 | INTER. RECT. | | | OM7805AL/883B | 782 |
| 5962-87782012A | J | 03/09/2004 | 1 | MICROSEMI | | Y | SG7805AL/883B | 782 |
| 5962-87782012A | J | 03/09/2004 | 1 | SOLITRON | | | SDP7805A2MD | 782 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-87782015A | J | 03/09/2004 | 1 | INTER. RECT. | | | OM7805SRM | 782 |
| 5962-87782016A | J | 03/09/2004 | 1 | INTER. RECT. | | | OM7805N5M | 782 |
| 5962-8778201MA | J | 03/09/2004 | 3 | INTER. RECT. | | | OM1805SM/883B | 782 |
| 5962-8778201NA | J | 03/09/2004 | 1 | INTER. RECT. | | | OM7805NMM/883B | 782 |
| 5962-8778201NA | J | 03/09/2004 | 1 | SOLITRON | | | SDP7805ANMD | 782 |
| 5962-8778201TA | J | 03/09/2004 | 1 | INTER. RECT. | | | OM7805AH/883B | 782 |
| 5962-8778201TA | J | 03/09/2004 | 1 | SEMELAB | | Y | IP7805AG-DESC | 782 |
| 5962-8778201TA | J | 03/09/2004 | 1 | SOLITRON | | | SDP7805ATMD | 782 |
| 5962-8778201UA | J | 03/09/2004 | 1 | INTER. RECT. | | | OM7805AIH/883B | 782 |
| 5962-8778201UA | J | 03/09/2004 | 1 | MICROSEMI | | Y | SG7805AIG/883B | 782 |
| 5962-8778201UA | J | 03/09/2004 | 1 | SEMELAB | | Y | IP7805AIG-DESC | 782 |
| 5962-8778201UA | J | 03/09/2004 | 1 | SOLITRON | | | SDP7805AUMD | 782 |
| 5962F8778201UA | J | 03/09/2004 | 1 | INTER. RECT. | | | OMR1805STM/883B | 782 |
| 5962-8778201XA | J | 03/09/2004 | 1 | MICROSEMI | | Y | SG7805AT/883B | 782 |
| 5962-8778201XA | J | 03/09/2004 | 1 | SEMELAB | | Y | IP78M05AH-DESC | 782 |
| 5962-8778201YA | J | 03/09/2004 | 1 | INTER. RECT. | | | OM7805AK/883B | 782 |
| 5962-8778201YA | J | 03/09/2004 | 1 | MICROSEMI | | Y | SG7805AK/883B | 782 |
| 5962-8778201YA | J | 03/09/2004 | 1 | SEMELAB | | Y | IP7805AK-DESC | 782 |
| 5962-8778201ZA | J | 03/09/2004 | 1 | MICROSEMI | | Y | SG7805AR/883B | 782 |
| 5962-8778201ZA | J | 03/09/2004 | 1 | SEMELAB | | Y | IP7805AR-DESC | 782 |
| 5962-8778201ZA | J | 03/09/2004 | 1 | SOLITRON | | | SDP7805AZMD | 782 |
| 5962-87782022A | J | 03/09/2004 | | (NONE) | 05/31/1994 | | 78M05 (GEN) | 782 |
| 5962-8778202PA | J | 03/09/2004 | 1 | SEMELAB | | Y | IP78M05J-DESC | 782 |
| 5962-8778202XA | J | 03/09/2004 | 1 | SEMELAB | | Y | IP78M05H-DESC | 782 |
| 5962-87782032A | J | 03/09/2004 | 1 | INTER. RECT. | | | OM1805-03N2M/883B | 782 |
| 5962-87782034A | J | 03/09/2004 | | (NONE) | | | 7805A (GEN) | 782 |
| 5962-87783012A | B | 01/27/2004 | 1 | INTERSIL | 10/03/2004 | Y | HA4-2400/883 | 739 |
| 5962-8778301EA | B | 01/27/2004 | 0 | INTERSIL | 10/05/2004 | Y | HA1-2400/883 | 739 |
| 5962-87784012A | D | 06/09/2004 | 1 | INTERSIL | | Y | HA4-5190/883 | 755 |
| 5962-8778401CA | D | 06/09/2004 | 1 | INTERSIL | 10/03/2004 | Y | HA1-5190/883 | 755 |
| 5962-8778401XC | D | 06/09/2004 | | (NONE) | | | HA-5190 (GEN) | 755 |
| 5962-87784022A | D | 06/09/2004 | | (NONE) | 09/30/1993 | | EL-2190 (GEN) | 755 |
| 5962-8778402CA | D | 06/09/2004 | | (NONE) | 09/30/1993 | | EL-2190 (GEN) | 755 |
| 5962-8778402XA | D | 06/09/2004 | | (NONE) | 09/30/1993 | | EL-2190 (GEN) | 755 |
| 5962-8778501CA | C | 06/09/2004 | 1 | INTERSIL | 07/02/2004 | Y | HA1-2541/883 | 755 |
| 5962-8778501XC | C | 06/09/2004 | 1 | INTERSIL | | Y | HA2-2541/883 | 755 |
| 5962-87785022A | C | 06/09/2004 | | (NONE) | | | EL2041 (GEN) | 755 |
| 5962-8778502CA | C | 06/09/2004 | | (NONE) | | | EL2041 (GEN) | 755 |
| 5962-8778502XA | C | 06/09/2004 | | (NONE) | | | EL2041 (GEN) | 755 |
| 5962-8778503CA | C | 06/09/2004 | 1 | INTERSIL | 07/02/2004 | Y | HA1-2841/883 | 755 |
| 5962-8778503PA | C | 06/09/2004 | | (NONE) | 09/29/1999 | | HA7-2841 (GEN) | 755 |
| 5962-8778601VA | B | 02/25/2004 | 1 | QP SEMI | | | TDC1046 | 592 |
| 5962-87787012A | A | 09/19/2002 | | (NONE) | 03/31/1995 | | HA2539 (GEN) | 755 |
| 5962-8778701CA | A | 09/19/2002 | 1 | INTERSIL | | Y | HA1-2539/883 | 755 |
| 5962-87787022A | A | 09/19/2002 | | (NONE) | 09/30/1993 | | EL2039 (GEN) | 755 |
| 5962-8778702CA | A | 09/19/2002 | | (NONE) | 09/30/1993 | | EL2039 (GEN) | 755 |
| 5962-87788012A | C | 04/03/2001 | | (NONE) | 08/02/1996 | | 27S21 (GEN) | 653 |
| 5962-8778801EA | C | 04/03/2001 | | (NONE) | | | 82S129 (GEN) | 653 |
| 5962-8778801FA | C | 04/03/2001 | 1 | LANSDALE | | Y | SL82S129/BFA | 653 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-8778801FA | C | 04/03/2001 | 1 | QP SEMI | | Y | 82S129/BFA | 653 |
| 5962-87788022A | C | 04/03/2001 | | (NONE) | 08/02/1996 | | 27S21A (GEN) | 653 |
| 5962-8778802EA | C | 04/03/2001 | 1 | LANSDALE | | Y | SL82S129A/BEA | 653 |
| 5962-8778802EA | C | 04/03/2001 | 1 | QP SEMI | | Y | 82S129A/BEA | 653 |
| 5962-8778802FA | C | 04/03/2001 | 1 | LANSDALE | | Y | SL82S129A/BFA | 653 |
| 5962-8778802FA | C | 04/03/2001 | 1 | QP SEMI | | Y | 82S129A/BFA | 653 |
| 5962-87789012A | B | 01/25/2001 | 1 | ANALOG (2) | | Y | AD558SE/883B | 591 |
| 5962-8778901EA | B | 01/25/2001 | 1 | ANALOG (2) | | Y | AD558SD/883B | 591 |
| 5962-87789022A | B | 01/25/2001 | 1 | ANALOG (2) | | Y | AD558TE/883B | 591 |
| 5962-8778902EA | B | 01/25/2001 | 1 | ANALOG (2) | | Y | AD558TD/883B | 591 |
| 5962-87791012A | B | 10/30/1989 | | (NONE) | | | 57401 (GEN) | 670 |
| 5962-8779101EA | B | 10/30/1989 | | (NONE) | | | 57401 (GEN) | 670 |
| 5962-87791022A | B | 10/30/1989 | | (NONE) | | | 57402 (GEN) | 670 |
| 5962-8779102VA | B | 10/30/1989 | | (NONE) | | | 57402 (GEN) | 670 |
| 5962-87791032A | B | 10/30/1989 | | (NONE) | 06/30/1994 | | 57401A (GEN) | 670 |
| 5962-8779103EA | B | 10/30/1989 | | (NONE) | 06/30/1994 | | 57401A (GEN) | 670 |
| 5962-87791042A | B | 10/30/1989 | | (NONE) | | | 57402A (GEN) | 670 |
| 5962-8779104VA | B | 10/30/1989 | | (NONE) | | | 57402A (GEN) | 670 |
| 5962-87791052A | B | 10/30/1989 | | (NONE) | | | C57401 (GEN) | 670 |
| 5962-8779105EA | B | 10/30/1989 | | (NONE) | | | C57401 (GEN) | 670 |
| 5962-87791062A | B | 10/30/1989 | | (NONE) | | | C57402 (GEN) | 670 |
| 5962-8779106VA | B | 10/30/1989 | | (NONE) | | | C57402 (GEN) | 670 |
| 5962-87791072A | B | 10/30/1989 | | (NONE) | 06/30/1994 | | C57401A (GEN) | 670 |
| 5962-8779107EA | B | 10/30/1989 | | (NONE) | 06/30/1994 | | C57401A (GEN) | 670 |
| 5962-87791082A | B | 10/30/1989 | | (NONE) | | | C57402A (GEN) | 670 |
| 5962-8779108VA | B | 10/30/1989 | | (NONE) | | | C57402A (GEN) | 670 |
| 5962-8779109EA | B | 10/30/1989 | | (NONE) | | | 57L401D (GEN) | 670 |
| 5962-8779110VA | B | 10/30/1989 | | (NONE) | | | 57L402D (GEN) | 670 |
| 5962-8779111EA | B | 10/30/1989 | | (NONE) | | | 57L4013D (GEN) | 670 |
| 5962-87792012A | A | 12/10/1991 | 1 | LANSDALE | | Y | SL10558/B2A | 275 |
| 5962-87792012A | A | 12/10/1991 | 3 | SARNOFF | | Y | GEM17601Q2A | 275 |
| 5962-87792012C | A | 12/10/1991 | 1 | LANSDALE | | Y | SL10558/B2C | 275 |
| 5962-87792012C | A | 12/10/1991 | 3 | SARNOFF | | Y | GEM17601Q2C | 275 |
| 5962-8779201EA | A | 12/10/1991 | 1 | LANSDALE | | Y | SL10558/BEA | 275 |
| 5962-8779201EA | A | 12/10/1991 | 3 | SARNOFF | | Y | GEM17601QEA | 275 |
| 5962-8779201EC | A | 12/10/1991 | 3 | SARNOFF | | Y | GEM17601QEC | 275 |
| 5962-8779201FA | A | 12/10/1991 | 1 | LANSDALE | | Y | SL10558/BFA | 275 |
| 5962-8779201FA | A | 12/10/1991 | 3 | SARNOFF | | Y | GEM17601QFA | 275 |
| 5962-8779201FC | A | 12/10/1991 | 3 | SARNOFF | | Y | GEM17601QFC | 275 |
| 5962-87793012A | | 08/30/1988 | 3 | SARNOFF | | Y | GEM32401Q2A | 159 |
| 5962-87793012C | | 08/30/1988 | 3 | SARNOFF | | Y | GEM32401Q2C | 159 |
| 5962-8779301EA | | 08/30/1988 | 3 | SARNOFF | | Y | GEM32401QEA | 159 |
| 5962-8779301EC | | 08/30/1988 | 3 | SARNOFF | | Y | GEM32401QEC | 159 |
| 5962-8779301FA | | 08/30/1988 | 3 | SARNOFF | | Y | GEM32401QFA | 159 |
| 5962-8779301FC | | 08/30/1988 | 3 | SARNOFF | | Y | GEM32401QFC | 159 |
| 5962-87794012A | B | 06/20/2001 | 1 | TI | | | SNJ54AS805BFK | 503 |
| 5962-8779401RA | B | 06/20/2001 | 1 | TI | | | SNJ54AS805BJ | 503 |
| 5962-8779401SA | B | 06/20/2001 | 1 | TI | | | SNJ54AS805BW | 503 |
| 5962-8780101XA | B | 01/09/1989 | I | ANALOG (2) | | Y | AD567SD/883B | 591 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-87802012A | C | 02/21/2001 | 1 | TI | | Y | TLC7226MFKB | 591 |
| 5962-87802012C | C | 02/21/2001 | 1 | ANALOG (3) | | Y | AD7226TE/883B | 591 |
| 5962-87802012C | C | 02/21/2001 | 1 | MAXIM INTEG. | | | MX7226TE/883B | 591 |
| 5962-87802012C | C | 02/21/2001 | 1 | TI | | Y | TLC7226MFKB | 591 |
| 5962-8780201RA | C | 02/21/2001 | 1 | ANALOG (3) | | Y | AD7226TQ/883B | 591 |
| 5962-8780201RA | C | 02/21/2001 | 1 | MAXIM INTEG. | | | MX7226TQ/883B | 591 |
| 5962-8780301AA | C | 06/09/2004 | | (NONE) | | | 4344 (GEN) | 802 |
| 5962-8780301CA | C | 06/09/2004 | 1 | LANSDALE | | Y | ML4344/BCA | 802 |
| 5962-8780301DA | C | 06/09/2004 | 1 | LANSDALE | | Y | ML4344/BDA | 802 |
| 5962-87804012A | | 06/24/1987 | 1 | TI | | | SNJ54AS21FK | 114 |
| 5962-8780401BA | | 06/24/1987 | 1 | TI | | | SNJ54AS21WA | 114 |
| 5962-8780401CA | | 06/24/1987 | | (NONE) | | | 54AS21 (GEN) | 114 |
| 5962-8780401DA | | 06/24/1987 | 1 | TI | | | SNJ54AS21W | 114 |
| 5962-8780501EA | | 04/14/1987 | 1 | TI | | Y | CD54HC221F3A | 166 |
| 5962-87805022A | | 04/14/1987 | 1 | ROCHESTER | | Y | 54HC221AE/B2A | 166 |
| 5962-8780502EA | | 04/14/1987 | 1 | ROCHESTER | | Y | 54HC221AJ/BEA | 166 |
| 5962-87806012A | B | 11/26/1990 | | (NONE) | | | 54HC299 (GEN) | 228 |
| 5962-8780601RA | B | 11/26/1990 | 1 | TI | | Y | CD54HC299F3A | 228 |
| 5962-87807012A | A | 11/19/1991 | 1 | TI | | Y | SNJ54HC377FK | 159 |
| 5962-8780701RA | A | 11/19/1991 | 1 | TI | | Y | SNJ54HC377J | 159 |
| 5962-87808012A | | 04/17/1987 | | (NONE) | | | 54HC192 (GEN) | 301 |
| 5962-8780801EA | | 04/17/1987 | 1 | TI | | Y | CD54HC192F3A | 301 |
| 5962-87809012A | A | 09/14/1990 | 3 | TI | | Y | SNJ54HC640FK | 590 |
| 5962-8780901RA | A | 09/14/1990 | 3 | TI | | Y | SNJ54HC640J | 590 |
| 5962-8850101YA | F | 12/03/2001 | 1 | ROCHESTER | | Y | MQ80C186-10/BYA | 403 |
| 5962-8850101YC | F | 12/03/2001 | 1 | ROCHESTER | | Y | MQ80C186-10/BYC | 403 |
| 5962-8850101ZA | F | 12/03/2001 | 1 | ROCHESTER | | Y | MG80C186-10/BZA | 403 |
| 5962-8850101ZC | F | 12/03/2001 | 1 | ROCHESTER | | Y | MG80C186-10/BZC | 403 |
| 5962-8850102YA | F | 12/03/2001 | 1 | ROCHESTER | | Y | MQ80C186-12/BYA | 403 |
| 5962-8850102YC | F | 12/03/2001 | 1 | ROCHESTER | | Y | MQ80C186-12/BYC | 403 |
| 5962-8850102ZA | F | 12/03/2001 | 1 | ROCHESTER | | Y | MG80C186-12/BZA | 403 |
| 5962-8850102ZC | F | 12/03/2001 | 1 | ROCHESTER | | Y | MG80C186-12/BZC | 403 |
| 5962-8850103ZA | F | 12/03/2001 | | (NONE) | 12/24/1997 | | 80C186XL20 (GEN) | 403 |
| 5962-8850104ZA | F | 12/03/2001 | | (NONE) | 12/24/1997 | | 80C186XL16 (GEN) | 403 |
| 5962-8850105ZA | F | 12/03/2001 | | (NONE) | 12/24/1997 | | 80C186XL12 (GEN) | 403 |
| 5962-8850106ZA | F | 12/03/2001 | | (NONE) | 12/24/1997 | | 80C186XL10 (GEN) | 403 |
| 5962-88502012A | B | 11/01/2001 | 1 | INTERSIL | | Y | HA4-5104/883 | 713 |
| 5962-8850201CA | B | 11/01/2001 | 1 | INTERSIL | 10/03/2004 | Y | HA1-5104/883 | 713 |
| 5962-88503012C | J | 07/28/2003 | 1 | MAXIM INTEG. | | | TSC426MNP/883B | 539 |
| 5962-8850301PA | J | 07/28/2003 | 1 | MAXIM INTEG. | | | TSC426MJA/883B | 539 |
| 5962-88503022C | J | 07/28/2003 | 1 | MAXIM INTEG. | | | TSC427MNP/883B | 539 |
| 5962-8850302PA | J | 07/28/2003 | 1 | MAXIM INTEG. | | | TSC427MJA/883B | 539 |
| 5962-88503032C | J | 07/28/2003 | 1 | MAXIM INTEG. | | | TSC428MNP/883B | 539 |
| 5962-8850303PA | J | 07/28/2003 | 1 | MAXIM INTEG. | | | TSC428MJA/883B | 539 |
| 5962-88503042A | J | 07/28/2003 | | (NONE) | | | TSC4423 (GEN) | 599 |
| 5962-8850304PA | J | 07/28/2003 | | (NONE) | 03/31/1998 | | MIC4423 (GEN) | 599 |
| 5962-88503052A | J | 07/28/2003 | | (NONE) | | | TSC4424 (GEN) | 599 |
| 5962-8850305PA | J | 07/28/2003 | | MICREL | | | MIC4424AJBQ | 599 |
| 5962-88503062A | J | 07/28/2003 | | (NONE) | | | TSC4425 (GEN) | 599 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-8850306HA | J | 07/28/2003 | | (NONE) | 03/31/1998 | | MIC4425 (GEN) | 599 |
| 5962-8850306PA | J | 07/28/2003 | | (NONE) | 03/31/1998 | | MIC4425 (GEN) | 599 |
| 5962-88503072A | J | 07/28/2003 | | (NONE) | | | TSC4426 (GEN) | 539 |
| 5962-8850307PA | J | 07/28/2003 | | MICREL | | | MIC4426AJBQ | 539 |
| 5962-88503082A | J | 07/28/2003 | | (NONE) | | | TSC4427 (GEN) | 539 |
| 5962-8850308HA | J | 07/28/2003 | | (NONE) | 03/31/1998 | | MIC4427 (GEN) | 539 |
| 5962-8850308PA | J | 07/28/2003 | | MICREL | | | MIC4427AJBQ | 539 |
| 5962-88503092A | J | 07/28/2003 | | (NONE) | | | TSC4428 (GEN) | 539 |
| 5962-8850309PA | J | 07/28/2003 | | MICREL | | | MIC4428AJBQ | 539 |
| 5962-8850310XA | J | 07/28/2003 | 1 | AUSTIN SEMI. | | Y | AS404F10 | 599 |
| 5962-8850401LA | C | 10/18/2001 | | (NONE) | | | PLS161 (GEN) | 431 |
| 5962-8850402LA | C | 10/18/2001 | 1 | AUSTIN SEMI. | | Y | ASPLS173C24/883C | 431 |
| 5962-8850402LA | C | 10/18/2001 | 1 | QP SEMI | | Y | PLS173/BLA | 431 |
| 5962-8850501RA | A | 06/20/2001 | 1 | ANALOG (2) | | Y | AD573SD/883 | 592 |
| 5962-8850502RA | A | 06/20/2001 | 1 | ANALOG (2) | | Y | AD673SD/883 | 592 |
| 5962-8850601XC | | 04/25/1988 | | (NONE) | 06/29/2001 | | 68901-4 (GEN) | 429 |
| 5962-8850601YA | | 04/25/1988 | | (NONE) | 06/29/2001 | | 68901-4 (GEN) | 429 |
| 5962-8850602XC | | 04/25/1988 | | (NONE) | 06/29/2001 | | 68901-5 (GEN) | 429 |
| 5962-8850602YA | | 04/25/1988 | | (NONE) | 06/29/2001 | | 68901-5 (GEN) | 429 |
| 5962-8850701LA | A | 11/01/2001 | 1 | AUSTIN SEMI. | | Y | ASPLS179C24/883C | 431 |
| 5962-8850701LA | A | 11/01/2001 | 1 | QP SEMI | | Y | PLS179/BLA | 431 |
| 5962-8850801XA | A | 10/22/1991 | 1 | DATEL | | Y | ADC-HX/883B | 592 |
| 5962-8850801XC | A | 10/22/1991 | 1 | DATEL | | Y | ADC-HX/883B | 592 |
| 5962-8850802XA | A | 10/22/1991 | 1 | DATEL | | Y | ADC-HZ/883B | 592 |
| 5962-8850802XC | A | 10/22/1991 | 1 | DATEL | | Y | ADC-HZ/883B | 592 |
| 5962-8850901XA | D | 06/28/2002 | | (NONE) | 08/29/2003 | | AD390S (GEN) | 591 |
| 5962-8850901XC | D | 06/28/2002 | | (NONE) | 08/29/2003 | | AD390S (GEN) | 591 |
| 5962-8850902XA | D | 06/28/2002 | 1 | ANALOG (6) | | Y | AD390TD/883B | 591 |
| 5962-8850902XC | D | 06/28/2002 | | (NONE) | 08/29/2003 | | AD390T (GEN) | 591 |
| 5962-8851001XA | B | 01/15/1998 | | (NONE) | 04/14/2001 | | AD394S (GEN) | 591 |
| 5962-8851002XA | B | 01/15/1998 | | (NONE) | 04/14/2001 | | AD394T (GEN) | 591 |
| 5962-8851003XA | B | 01/15/1998 | | (NONE) | | | AD395S (GEN) | 591 |
| 5962-8851004XA | B | 01/15/1998 | | (NONE) | | | AD395T (GEN) | 591 |
| 5962-88511012A | A | 04/30/2001 | 1 | TI | 07/15/2005 | Y | SNJ55116FK | 590 |
| 5962-8851101EA | A | 04/30/2001 | 1 | TI | 07/15/2005 | Y | SNJ55116J | 590 |
| 5962-88511022A | A | 04/30/2001 | | (NONE) | | | 55117 (GEN) | 590 |
| 5962-8851102PA | A | 04/30/2001 | | (NONE) | | | 55117 (GEN) | 590 |
| 5962-88511032A | A | 04/30/2001 | | (NONE) | | | 55118 (GEN) | 590 |
| 5962-8851103EA | A | 04/30/2001 | | (NONE) | | | 55118 (GEN) | 590 |
| 5962-88511042A | A | 04/30/2001 | | (NONE) | | | 55119 (GEN) | 590 |
| 5962-8851104PA | A | 04/30/2001 | | (NONE) | | | 55119 (GEN) | 590 |
| 5962-8851201QEA | | 05/28/1998 | | (NONE) | 12/31/2001 | | 55138 (GEN) | 590 |
| 5962-88513012A | E | 07/23/2002 | 1 | ANALOG (5) | | Y | OP-42ARC/883 | 703 |
| 5962-8851301V2A | E | 07/23/2002 | 1 | ANALOG (5) | | Y | OP-42ARC/QMLV | 703 |
| 5962-8851301GA | E | 07/23/2002 | 1 | ANALOG (5) | | Y | OP-42AJ/883 | 703 |
| 5962-8851301VGA | E | 07/23/2002 | 1 | ANALOG (5) | | Y | OP-42AJ/QMLV | 703 |
| 5962-8851301PA | E | 07/23/2002 | 1 | ANALOG (5) | | Y | OP-42AZ/883 | 703 |
| 5962-8851301VPA | E | 07/23/2002 | 1 | ANALOG (5) | | Y | OP-42AZ/QMLV | 703 |
| 5962-8851302HA | E | 07/23/2002 | | ANALOG (5) | | Y | OP-42BL/883 | 703 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-8851401XA | F | 01/05/2000 | | (NONE) | 09/01/2000 | | HS9403-8 (GEN) | 433 |
| 5962-8851402XA | F | 01/05/2000 | | (NONE) | 09/01/2000 | | HS9403-16 (GEN) | 433 |
| 5962-8851402YA | F | 01/05/2000 | | (NONE) | | | HS9403-16 (GEN) | 433 |
| 5962-8851403XA | F | 01/05/2000 | 1 | DATEL | | Y | HDAS-8/883 | 433 |
| 5962-8851403XC | F | 01/05/2000 | 1 | DATEL | | Y | HDAS-8/883 | 433 |
| 5962-8851404XA | F | 01/05/2000 | 1 | DATEL | | Y | HDAS-16/883 | 433 |
| 5962-8851404XC | F | 01/05/2000 | 1 | DATEL | | Y | HDAS-16/883 | 433 |
| 5962-88515012A | | 07/21/1988 | | (NONE) | 08/04/1995 | | PAL16L8B-4 (GEN) | 431 |
| 5962-8851501RA | | 07/21/1988 | | (NONE) | 08/04/1995 | | PAL16L8B-4 (GEN) | 431 |
| 5962-8851501SA | | 07/21/1988 | | (NONE) | 08/04/1995 | | PAL16L8B-4 (GEN) | 431 |
| 5962-88515022A | | 07/21/1988 | | (NONE) | 08/04/1995 | | PAL16R8B-4 (GEN) | 431 |
| 5962-8851502RA | | 07/21/1988 | | (NONE) | 08/04/1995 | | PAL16R8B-4 (GEN) | 431 |
| 5962-8851502SA | | 07/21/1988 | | (NONE) | 08/04/1995 | | PAL16R8B-4 (GEN) | 431 |
| 5962-88515032A | | 07/21/1988 | | (NONE) | 08/04/1995 | | PAL16R6B-4 (GEN) | 431 |
| 5962-8851503RA | | 07/21/1988 | | (NONE) | 08/04/1995 | | PAL16R6B-4 (GEN) | 431 |
| 5962-8851503SA | | 07/21/1988 | | (NONE) | 08/04/1995 | | PAL16R6B-4 (GEN) | 431 |
| 5962-88515042A | | 07/21/1988 | | (NONE) | 08/04/1995 | | PAL16R4B-4 (GEN) | 431 |
| 5962-8851504RA | | 07/21/1988 | | (NONE) | 08/04/1995 | | PAL16R4B-4 (GEN) | 431 |
| 5962-8851504SA | | 07/21/1988 | | (NONE) | 08/04/1995 | | PAL16R4B-4 (GEN) | 431 |
| 5962-88516013A | D | 12/10/2002 | 2 | SARNOFF | | Y | GEM19401Q3A | 421 |
| 5962-88516013C | D | 12/10/2002 | 2 | SARNOFF | | Y | GEM19401Q3C | 421 |
| 5962-8851601KA | D | 12/10/2002 | 2 | SARNOFF | | Y | GEM19401QKA | 421 |
| 5962-8851601KC | D | 12/10/2002 | 2 | SARNOFF | | Y | GEM19401QKC | 421 |
| 5962-8851601LA | D | 12/10/2002 | 2 | SARNOFF | | Y | GEM19401QLA | 421 |
| 5962-8851601LC | D | 12/10/2002 | 2 | SARNOFF | | Y | GEM19401QLC | 421 |
| 5962-88516023A | D | 12/10/2002 | 2 | SARNOFF | | Y | GEM18902Q3A | 421 |
| 5962-88516023C | D | 12/10/2002 | 2 | SARNOFF | | Y | GEM18902Q3C | 421 |
| 5962-8851602KA | D | 12/10/2002 | 2 | SARNOFF | | Y | GEM18902QKA | 421 |
| 5962-8851602KC | D | 12/10/2002 | 2 | SARNOFF | | Y | GEM18902QKC | 421 |
| 5962-8851602LA | D | 12/10/2002 | 2 | SARNOFF | | Y | GEM18902QLA | 421 |
| 5962-8851602LC | D | 12/10/2002 | 2 | SARNOFF | | Y | GEM18902QLC | 421 |
| 5962-8851603LA | D | 12/10/2002 | | (NONE) | | | 29C921 (GEN) | 421 |
| 5962-8851604LA | D | 12/10/2002 | | (NONE) | | | 29C923 (GEN) | 421 |
| 5962-88516053A | D | 12/10/2002 | | (NONE) | | | 29C821A (GEN) | 421 |
| 5962-8851605KA | D | 12/10/2002 | | (NONE) | | | 29C821A (GEN) | 421 |
| 5962-8851605LA | D | 12/10/2002 | | (NONE) | | | 29C821A (GEN) | 421 |
| 5962-88516063A | D | 12/10/2002 | | (NONE) | | | 29C823A (GEN) | 421 |
| 5962-8851606KA | D | 12/10/2002 | | (NONE) | | | 29C823A (GEN) | 421 |
| 5962-8851606LA | D | 12/10/2002 | | (NONE) | | | 29C823A (GEN) | 421 |
| 5962-8851701XA | C | 04/23/2004 | 1 | DDC | | Y | DAC-02310-112 | 591 |
| 5962-8851701XC | C | 04/23/2004 | 1 | DDC | | Y | DAC-02310-112 | 591 |
| 5962-8851701YA | C | 04/23/2004 | 1 | DDC | | Y | DAC-02311-112 | 591 |
| 5962-8851701YC | C | 04/23/2004 | 1 | DDC | | Y | DAC-02311-112 | 591 |
| 5962-8851702XA | C | 04/23/2004 | 1 | DDC | | Y | DAC-02310-113 | 591 |
| 5962-8851702XC | C | 04/23/2004 | 1 | DDC | | Y | DAC-02310-113 | 591 |
| 5962-8851702YA | C | 04/23/2004 | 1 | DDC | | Y | DAC-02311-113 | 591 |
| 5962-8851702YC | C | 04/23/2004 | 1 | DDC | | Y | DAC-02311-113 | 591 |
| 5962-88518013A | C | 09/20/1994 | | (NONE) | | | | 656 |
| 5962-8851801LA | C | 09/20/1994 | | (NONE) | | | | 656 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-88518023A | C | 09/20/1994 | | (NONE) | | | | 656 |
| 5962-8851802LA | C | 09/20/1994 | | (NONE) | | | | 656 |
| 5962-88518033A | C | 09/20/1994 | | (NONE) | | | | 656 |
| 5962-8851803LA | C | 09/20/1994 | | (NONE) | | | | 656 |
| 5962-88518043A | C | 09/20/1994 | 2 | QP SEMI | | Y | CY7C225A-30LMB | 656 |
| 5962-8851804LA | C | 09/20/1994 | 2 | QP SEMI | | Y | CY7C225A-30DMB | 656 |
| 5962-88518053A | C | 09/20/1994 | 2 | QP SEMI | | Y | CY7C225A-35LMB | 656 |
| 5962-8851805LA | C | 09/20/1994 | 2 | CYPRESS | 05/03/2004 | Y | CY7C225A-35DMB | 656 |
| 5962-8851805LA | C | 09/20/1994 | 2 | QP SEMI | | Y | CY7C225A-35DMB | 656 |
| 5962-88518063A | C | 09/20/1994 | 2 | QP SEMI | | Y | CY7C225A-40LMB | 656 |
| 5962-8851806LA | C | 09/20/1994 | 2 | QP SEMI | | Y | CY7C225A-40DMB | 656 |
| 5962-88518073A | C | 09/20/1994 | 2 | QP SEMI | | Y | CY7C225A-25LMB | 656 |
| 5962-8851807LA | C | 09/20/1994 | 2 | QP SEMI | | Y | CY7C225A-25DMB | 656 |
| 5962-8851901VA | | 07/28/1988 | | (NONE) | 07/01/1994 | | 2981 (GEN) | 539 |
| 5962-8851902VA | | 07/28/1988 | | (NONE) | 07/01/1994 | | 2983 (GEN) | 539 |
| 5962-88520012A | C | 01/10/2001 | 3 | NATIONAL | | Y | 54AC74LMQB | 158 |
| 5962-88520012A | C | 01/10/2001 | 3 | TI | | Y | SNJ54AC74FK | 158 |
| 5962-8852001CA | C | 01/10/2001 | 3 | NATIONAL | | Y | 54AC74DMQB | 158 |
| 5962-8852001CA | C | 01/10/2001 | 3 | TI | | Y | SNJ54AC74J | 158 |
| 5962-8852001VCA | C | 01/10/2001 | 3 | TI | | Y | SNV54AC74J | 158 |
| 5962-8852001DA | C | 01/10/2001 | 3 | NATIONAL | | Y | 54AC74FMQB | 158 |
| 5962-8852001DA | C | 01/10/2001 | 3 | TI | | Y | SNJ54AC74W | 158 |
| 5962-8852001VDA | C | 01/10/2001 | 3 | TI | | Y | SNV54AC74W | 158 |
| 5962-8852001VXA | C | 01/10/2001 | 2 | STMICRO | | Y | 54AC74K02V | 158 |
| 5962-8852001VXC | C | 01/10/2001 | 2 | STMICRO | | Y | 54AC74K01V | 158 |
| 5962-8852001XA | C | 01/10/2001 | 2 | STMICRO | | Y | 54AC74K02Q | 158 |
| 5962-8852001XC | C | 01/10/2001 | 2 | STMICRO | | Y | 54AC74K01Q | 158 |
| 5962-88520022A | C | 01/10/2001 | | (NONE) | 09/15/1995 | | 54AC11074 (GEN) | 158 |
| 5962-8852002CA | C | 01/10/2001 | | (NONE) | 09/15/1995 | | 54AC11074 (GEN) | 158 |
| 5962-8852002DA | C | 01/10/2001 | | (NONE) | 09/15/1995 | | 54AC11074 (GEN) | 158 |
| 5962-88522012A | A | 06/13/2001 | 2 | TI | | | SNJ54AS808BFK | 502 |
| 5962-8852201RA | A | 06/13/2001 | 2 | TI | | | SNJ54AS808BJ | 502 |
| 5962-8852201SA | A | 06/13/2001 | 2 | TI | | | SNJ54AS808BW | 502 |
| 5962-88523012A | A | 06/06/2001 | 1 | TI | | | SNJ54AS832BFK | 509 |
| 5962-8852301RA | A | 06/06/2001 | 1 | TI | | | SNJ54AS832BJ | 509 |
| 5962-8852301SA | A | 06/06/2001 | 1 | TI | | | SNJ54AS832BW | 509 |
| 5962-8852501UA | C | 02/14/1995 | 1 | ATMEL | | | AT28C256-35UM/883 | 662 |
| 5962-8852501XA | C | 02/14/1995 | 1 | ATMEL | | | AT28C256-35DM/883 | 662 |
| 5962-8852501YA | C | 02/14/1995 | 1 | ATMEL | | | AT28C256-35LM/883 | 662 |
| 5962-8852501ZA | C | 02/14/1995 | 1 | ATMEL | | | AT28C256-35FM/883 | 662 |
| 5962-8852502UA | C | 02/14/1995 | 1 | ATMEL | | | AT28C256-30UM/883 | 662 |
| 5962-8852502XA | C | 02/14/1995 | 1 | ATMEL | | | AT28C256-30DM/883 | 662 |
| 5962-8852502YA | C | 02/14/1995 | 1 | ATMEL | | | AT28C256-30LM/883 | 662 |
| 5962-8852502ZA | C | 02/14/1995 | 1 | ATMEL | | | AT28C256-30FM/883 | 662 |
| 5962-8852503UA | C | 02/14/1995 | 1 | ATMEL | | | AT28C256-25UM/883 | 662 |
| 5962-8852503XA | C | 02/14/1995 | 1 | ATMEL | | | AT28C256-25DM/883 | 662 |
| 5962-8852503YA | C | 02/14/1995 | 1 | ATMEL | | | AT28C256-25LM/883 | 662 |
| 5962-8852503ZA | C | 02/14/1995 | 1 | ATMEL | | | AT28C256-25FM/883 | 662 |
| 5962-8852504UA | C | 02/14/1995 | 1 | ATMEL | | | AT28C256-20UM/883 | 662 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-8852504XA | C | 02/14/1995 | 1 | ATMEL | | | AT28C256-20DM/883 | 662 |
| 5962-8852504YA | C | 02/14/1995 | 1 | ATMEL | | | AT28C256-20LM/883 | 662 |
| 5962-8852504ZA | C | 02/14/1995 | 1 | ATMEL | | | AT28C256-20FM/883 | 662 |
| 5962-8852505UA | C | 02/14/1995 | 1 | ATMEL | | | AT28C256E-25UM/883 | 662 |
| 5962-8852505XA | C | 02/14/1995 | 1 | ATMEL | | | AT28C256E-25DM/883 | 662 |
| 5962-8852505YA | C | 02/14/1995 | 1 | ATMEL | | | AT28C256E-25LM/883 | 662 |
| 5962-8852505ZA | C | 02/14/1995 | 1 | ATMEL | | | AT28C256E-25FM/883 | 662 |
| 5962-8852506UA | C | 02/14/1995 | 1 | ATMEL | | | AT28C256-15UM/883 | 662 |
| 5962-8852506XA | C | 02/14/1995 | 1 | ATMEL | | | AT28C256-15DM/883 | 662 |
| 5962-8852506YA | C | 02/14/1995 | 1 | ATMEL | | | AT28C256-15LM/883 | 662 |
| 5962-8852506ZA | C | 02/14/1995 | 1 | ATMEL | | | AT28C256-15FM/883 | 662 |
| 5962-8852507UA | C | 02/14/1995 | 1 | ATMEL | | | AT28C256F-15UM/883 | 662 |
| 5962-8852507XA | C | 02/14/1995 | 1 | ATMEL | | | AT28C256F-15DM/883 | 662 |
| 5962-8852507YA | C | 02/14/1995 | 1 | ATMEL | | | AT28C256F-15LM/883 | 662 |
| 5962-8852507ZA | C | 02/14/1995 | 1 | ATMEL | | | AT28C256F-15FM/883 | 662 |
| 5962-8852508UA | C | 02/14/1995 | 1 | ATMEL | | | AT28C256E-15UM/883 | 662 |
| 5962-8852508XA | C | 02/14/1995 | 1 | ATMEL | | | AT28C256E-15DM/883 | 662 |
| 5962-8852508YA | C | 02/14/1995 | 1 | ATMEL | | | AT28C256E-15LM/883 | 662 |
| 5962-8852508ZA | C | 02/14/1995 | 1 | ATMEL | | | AT28C256E-15FM/883 | 662 |
| 5962-8852509UA | C | 02/14/1995 | 2 | ATMEL | | | AT28C256-35UM/883 | 662 |
| 5962-8852509XA | C | 02/14/1995 | 2 | ATMEL | | | AT28C256-35DM/883 | 662 |
| 5962-8852509YA | C | 02/14/1995 | 2 | ATMEL | | | AT28C256-35LM/883 | 662 |
| 5962-8852509ZA | C | 02/14/1995 | 2 | ATMEL | | | AT28C256-35FM/883 | 662 |
| 5962-8852510UA | C | 02/14/1995 | 2 | ATMEL | | | AT28C256-30UM/883 | 662 |
| 5962-8852510XA | C | 02/14/1995 | 2 | ATMEL | | | AT28C256-300DM/883 | 662 |
| 5962-8852510YA | C | 02/14/1995 | 2 | ATMEL | | | AT28C256-30LM/883 | 662 |
| 5962-8852510ZA | C | 02/14/1995 | 2 | ATMEL | | | AT28C256-30FM/883 | 662 |
| 5962-8852511UA | C | 02/14/1995 | 2 | ATMEL | | | AT28C256-25UM/883 | 662 |
| 5962-8852511XA | C | 02/14/1995 | 2 | ATMEL | | | AT28C256-25DM/883 | 662 |
| 5962-8852511YA | C | 02/14/1995 | 2 | ATMEL | | | AT28C256-25LM/883 | 662 |
| 5962-8852511ZA | C | 02/14/1995 | 2 | ATMEL | | | AT28C256-25FM/883 | 662 |
| 5962-8852512UA | C | 02/14/1995 | 2 | ATMEL | | | AT28C256-20UM/883 | 662 |
| 5962-8852512XA | C | 02/14/1995 | 2 | ATMEL | | | AT28C256-20DM/883 | 662 |
| 5962-8852512YA | C | 02/14/1995 | 2 | ATMEL | | | AT28C256-20LM/883 | 662 |
| 5962-8852512ZA | C | 02/14/1995 | 2 | ATMEL | | | AT28C256-20FM/883 | 662 |
| 5962-8852513UA | C | 02/14/1995 | 1 | ATMEL | | | AT28C256E-25UM/883 | 662 |
| 5962-8852513XA | C | 02/14/1995 | 2 | ATMEL | | | AT28C256E-25DM/883 | 662 |
| 5962-8852513YA | C | 02/14/1995 | 2 | ATMEL | | | AT28C256E-25LM/883 | 662 |
| 5962-8852513ZA | C | 02/14/1995 | 2 | ATMEL | | | AT28C256E-25FM/883 | 662 |
| 5962-8852514UA | C | 02/14/1995 | 1 | ATMEL | | | AT28C256-15UM/883 | 662 |
| 5962-8852514XA | C | 02/14/1995 | 2 | ATMEL | | | AT28C256-15DM/883 | 662 |
| 5962-8852514YA | C | 02/14/1995 | 2 | ATMEL | | | AT28C256-15LM/883 | 662 |
| 5962-8852514ZA | C | 02/14/1995 | 2 | ATMEL | | | AT28C256-15FM/883 | 662 |
| 5962-8852515UA | C | 02/14/1995 | 1 | ATMEL | | | AT28C256F-15UM/883 | 662 |
| 5962-8852515XA | C | 02/14/1995 | 2 | ATMEL | | | AT28C256F-15DM/883 | 662 |
| 5962-8852515YA | C | 02/14/1995 | 2 | ATMEL | | | AT28C256F-15LM/883 | 662 |
| 5962-8852515ZA | C | 02/14/1995 | 2 | ATMEL | | | AT28C256F-15FM/883 | 662 |
| 5962-8852516UA | C | 02/14/1995 | 1 | ATMEL | | | AT28C256E-15UM/883 | 662 |
| 5962-8852516XA | C | 02/14/1995 | 2 | ATMEL | | | AT28C256E-15DM/883 | 662 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-8852516YA | C | 02/14/1995 | 2 | ATMEL | | | AT28C256E-15LM/883 | 662 |
| 5962-8852516ZA | C | 02/14/1995 | 2 | ATMEL | | | AT28C256E-15FM/883 | 662 |
| 5962-88527012A | B | 06/06/2001 | 1 | LANSDALE | | Y | SL10564/B2A | 271 |
| 5962-88527012A | B | 06/06/2001 | 3 | SARNOFF | | Y | GEM17701B2A | 271 |
| 5962-88527012C | B | 06/06/2001 | 1 | LANSDALE | | Y | SL10564/B2C | 271 |
| 5962-88527012C | B | 06/06/2001 | 3 | SARNOFF | | Y | GEM17701B2C | 271 |
| 5962-8852701EA | B | 06/06/2001 | 1 | LANSDALE | | Y | SL10564/BEA | 271 |
| 5962-8852701EA | B | 06/06/2001 | 3 | SARNOFF | | Y | GEM17701BEA | 271 |
| 5962-8852701EC | B | 06/06/2001 | 3 | SARNOFF | | Y | GEM17701BEC | 271 |
| 5962-8852701FA | B | 06/06/2001 | 1 | LANSDALE | | Y | SL10564/BFA | 271 |
| 5962-8852701FA | B | 06/06/2001 | 3 | SARNOFF | | Y | GEM17701BFA | 271 |
| 5962-8852701FC | B | 06/06/2001 | 3 | SARNOFF | | Y | GEM17701BFC | 271 |
| 5962-8853201TC | C | 01/21/2003 | 1 | QP SEMI | | | TDC1049/TC | 592 |
| 5962-8853201UA | C | 01/21/2003 | 1 | QP SEMI | | | TDC1049L1V | 592 |
| 5962-8853201XA | C | 01/21/2003 | 1 | QP SEMI | | | TDC1049J0V | 592 |
| 5962-8853201YA | C | 01/21/2003 | 1 | QP SEMI | | | TDC1049J3V | 592 |
| 5962-8853201ZA | C | 01/21/2003 | 1 | QP SEMI | | | TDC1049C1V | 592 |
| 5962-8853301TA | C | 04/20/1994 | | (NONE) | 08/21/1995 | | 49C460A (GEN) | 355 |
| 5962-8853301UA | C | 04/20/1994 | | (NONE) | 08/05/1996 | | 49C460A (GEN) | 355 |
| 5962-8853301XA | C | 04/20/1994 | | (NONE) | | | 49C460A (GEN) | 355 |
| 5962-8853301YA | C | 04/20/1994 | | (NONE) | | | 49C460A (GEN) | 355 |
| 5962-8853301ZA | C | 04/20/1994 | | (NONE) | | | 49C460A (GEN) | 355 |
| 5962-8853302TA | C | 04/20/1994 | | (NONE) | 08/21/1995 | | 49C460B (GEN) | 355 |
| 5962-8853302UA | C | 04/20/1994 | | (NONE) | 08/05/1996 | | 49C460B (GEN) | 355 |
| 5962-8853302XA | C | 04/20/1994 | | (NONE) | | | 49C460B (GEN) | 355 |
| 5962-8853302YA | C | 04/20/1994 | | (NONE) | | | 49C460B (GEN) | 355 |
| 5962-8853302ZA | C | 04/20/1994 | | (NONE) | | | 49C460B (GEN) | 355 |
| 5962-8853303UA | C | 04/20/1994 | | (NONE) | 08/04/1995 | | 29C660A (GEN) | 355 |
| 5962-8853304UA | C | 04/20/1994 | | (NONE) | 08/04/1995 | | 29C660B (GEN) | 355 |
| 5962-8853305UA | C | 04/20/1994 | | (NONE) | 08/04/1995 | | 29C660C (GEN) | 355 |
| 5962-8853306TA | C | 04/20/1994 | | (NONE) | 08/21/1995 | | 49C460C (GEN) | 355 |
| 5962-8853306UA | C | 04/20/1994 | | (NONE) | 08/05/1996 | | 49C460C (GEN) | 355 |
| 5962-8853306XA | C | 04/20/1994 | | (NONE) | | | 49C460C (GEN) | 355 |
| 5962-8853306YA | C | 04/20/1994 | | (NONE) | | | 49C460C (GEN) | 355 |
| 5962-8853307TA | C | 04/20/1994 | | (NONE) | 08/21/1995 | | 49C460D (GEN) | 355 |
| 5962-8853307UA | C | 04/20/1994 | | (NONE) | 08/05/1996 | | 49C460D (GEN) | 355 |
| 5962-88534012A | B | 07/13/2001 | 3 | NATIONAL | | Y | 54ACT109LMQB | 152 |
| 5962R88534012A | B | 07/13/2001 | 3 | NATIONAL | | Y | 54ACT109LMQB-RH | 152 |
| 5962R8853401V2A | B | 07/13/2001 | 3 | NATIONAL | | Y | 54ACT109ERQMLV | 152 |
| 5962-8853401EA | B | 07/13/2001 | 3 | NATIONAL | | Y | 54ACT109DMQB | 152 |
| 5962R8853401EA | B | 07/13/2001 | 3 | NATIONAL | | Y | 54ACT109DMQB-RH | 152 |
| 5962R8853401VEA | B | 07/13/2001 | 3 | NATIONAL | | Y | 54ACT109JRQMLV | 152 |
| 5962-8853401FA | B | 07/13/2001 | 3 | NATIONAL | | Y | 54ACT109FMQB | 152 |
| 5962R8853401FA | B | 07/13/2001 | 3 | NATIONAL | | Y | 54ACT109FMQB-RH | 152 |
| 5962R8853401VFA | B | 07/13/2001 | 3 | NATIONAL | | Y | 54ACT109WRQMLV | 152 |
| 5962-8853401VXA | B | 07/13/2001 | 2 | STMICRO | | Y | 54ACT109K02V | 152 |
| 5962-8853401VXA | B | 07/13/2001 | 2 | STMICRO | | Y | 54ACT109K01V | 152 |
| 5962-8853401XA | B | 07/13/2001 | 2 | STMICRO | | Y | 54ACT109K02Q | 152 |
| 5962-8853401XC | B | 07/13/2001 | 2 | STMICRO | | Y | 54ACT109K01Q | 152 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-88534022A | B | 07/13/2001 | 1 | ROCHESTER | | Y | 54ACT11109/B2A | 152 |
| 5962-8853402EA | B | 07/13/2001 | 1 | ROCHESTER | | Y | 54ACT11109/BEA | 152 |
| 5962-8853402FA | B | 07/13/2001 | 1 | ROCHESTER | | Y | 54ACT11109/BFA | 152 |
| 5962-8853501QA | B | 06/10/2002 | | (NONE) | 03/05/1996 | | 7C901-32 (GEN) | 400 |
| 5962-8853501XA | B | 06/10/2002 | | (NONE) | 03/05/1996 | | 7C901-32 (GEN) | 400 |
| 5962-8853501YA | B | 06/10/2002 | | (NONE) | | | 7C901-32 (GEN) | 400 |
| 5962-8853502QA | B | 06/10/2002 | | (NONE) | 03/05/1996 | | 7C901-27 (GEN) | 400 |
| 5962-8853502XA | B | 06/10/2002 | | (NONE) | 03/05/1996 | | 7C901-27 (GEN) | 400 |
| 5962-8853502YA | B | 06/10/2002 | | (NONE) | | | 7C901-27 (GEN) | 400 |
| 5962-8853503QA | B | 06/10/2002 | 2 | SARNOFF | | Y | GEM32003QQA | 400 |
| 5962-8853503QC | B | 06/10/2002 | 2 | SARNOFF | | Y | GEM32003QQC | 400 |
| 5962-8853503XA | B | 06/10/2002 | 2 | SARNOFF | | Y | GEM32003QXA | 400 |
| 5962-8853503XC | B | 06/10/2002 | 2 | SARNOFF | | Y | GEM32003QXC | 400 |
| 5962-8853503YA | B | 06/10/2002 | 2 | SARNOFF | | Y | GEM32003QYA | 400 |
| 5962-8853503YC | B | 06/10/2002 | 2 | SARNOFF | | Y | GEM32003QYC | 400 |
| 5962-88537012A | C | 05/20/2003 | | (NONE) | 09/15/1995 | | OP-37A (GEN) | 719 |
| 5962-8853701V2A | C | 05/20/2003 | 3 | ANALOG (5) | | Y | OP37ARC/QMLV | 719 |
| 5962-8853701GA | C | 05/20/2003 | | (NONE) | 04/16/2002 | | OP-37A (GEN) | 719 |
| 5962-8853701VGA | C | 05/20/2003 | 3 | ANALOG (5) | | Y | OP37AJ/QMLV | 719 |
| 5962-8853701VHA | C | 05/20/2003 | 3 | ANALOG (5) | | Y | OP37AL/QMLV | 719 |
| 5962-8853701PA | C | 05/20/2003 | | (NONE) | 04/16/2002 | | OP-37A (GEN) | 719 |
| 5962-8853701VPA | C | 05/20/2003 | 3 | ANALOG (5) | | Y | OP37AZ/QMLV | 719 |
| 5962-88537022A | C | 05/20/2003 | | (NONE) | 04/16/2002 | | OP-37B (GEN) | 719 |
| 5962-8853702GA | C | 05/20/2003 | 2 | ANALOG (5) | 05/28/2005 | Y | OP-37BJ/883 | 719 |
| 5962-8853702PA | C | 05/20/2003 | 2 | ANALOG (5) | | Y | OP-37BZ/883 | 719 |
| 5962-88537032A | C | 05/20/2003 | | (NONE) | 09/15/1995 | | OP-37C (GEN) | 702 |
| 5962-8853703GA | C | 05/20/2003 | | (NONE) | 04/16/2002 | | OP-37C (GEN) | 702 |
| 5962-8853703PA | C | 05/20/2003 | | (NONE) | 03/30/2001 | | OP-37C (GEN) | 702 |
| 5962-88538012A | D | 08/06/2004 | 1 | ANALOG (5) | | Y | OP215ARC/883C | 710 |
| 5962-8853801V2A | D | 08/06/2004 | 2 | ANALOG (5) | | Y | OP215ARC/QMLV | 710 |
| 5962R8853801V2A | D | 08/06/2004 | 2 | ANALOG (5) | | Y | OP215ARC/QMLR | 710 |
| 5962-8853801GA | D | 08/06/2004 | | (NONE) | 04/16/2002 | | OP215A (GEN) | 710 |
| 5962-8853801VGA | D | 08/06/2004 | 2 | ANALOG (5) | | Y | OP215AJ/QMLV | 710 |
| 5962R8853801VGA | D | 08/06/2004 | 2 | ANALOG (5) | | Y | OP215AJ/QMLR | 710 |
| 5962-8853801PA | D | 08/06/2004 | 1 | ANALOG (5) | | Y | OP215AZ/883 | 710 |
| 5962-8853801VPA | D | 08/06/2004 | 2 | ANALOG (5) | | Y | OP215AZ/QMLV | 710 |
| 5962R8853801VPA | D | 08/06/2004 | 2 | ANALOG (5) | | Y | OP215AZ/QMLR | 710 |
| 5962-8853802GA | D | 08/06/2004 | 1 | ANALOG (5) | | Y | OP215BJ/883 | 710 |
| 5962-8853802PA | D | 08/06/2004 | | (NONE) | 04/16/2002 | | OP215B (GEN) | 710 |
| 5962-88538032A | D | 08/06/2004 | | (NONE) | 04/16/2002 | | OP215BR (GEN) | 710 |
| 5962-88539012A | D | 08/06/2004 | | (NONE) | | | AD524 (GEN) | 754 |
| 5962-8853901V2A | D | 08/06/2004 | 1 | ANALOG (5) | | Y | AD524SE/QMLV | 754 |
| 5962R8853901V2A | D | 08/06/2004 | 1 | ANALOG (5) | | Y | AD524SE/QMLR | 754 |
| 5962-8853901EA | D | 08/06/2004 | 1 | ANALOG (2) | | Y | AD524SD/883B | 754 |
| 5962-8853901VEA | D | 08/06/2004 | 1 | ANALOG (5) | | Y | AD524SD/QMLV | 754 |
| 5962R8853901VEA | D | 08/06/2004 | 1 | ANALOG (5) | | Y | AD524SD/QMLR | 754 |
| 5962-88540012A | B | 05/22/2001 | 2 | TI | | Y | SNJ54ALS05AFK | 144 |
| 5962-8854001CA | B | 05/22/2001 | 2 | TI | | Y | SNJ54ALS05AJ | 144 |
| 5962-8854001DA | B | 05/22/2001 | 2 | TI | | Y | SNJ54ALS05AW | 144 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-88541012A | B | 03/23/1992 | | (NONE) | 08/02/1996 | | 27S13A (GEN) | 655 |
| 5962-8854101EA | B | 03/23/1992 | | (NONE) | 08/02/1996 | | 27S13A (GEN) | 655 |
| 5962-8854101FA | B | 03/23/1992 | | (NONE) | 08/02/1996 | | 27S13A (GEN) | 655 |
| 5962-88541022A | B | 03/23/1992 | | (NONE) | 08/02/1996 | | 27S13 (GEN) | 655 |
| 5962-8854102EA | B | 03/23/1992 | | (NONE) | 08/02/1996 | | 27S13 (GEN) | 655 |
| 5962-8854102FA | B | 03/23/1992 | | (NONE) | 08/02/1996 | | 27S13 (GEN) | 655 |
| 5962-8854201XA | D | 09/29/1999 | | (NONE) | | | ADC00300 (GEN) | 592 |
| 5962-8854201YA | D | 09/29/1999 | | (NONE) | | | ADC00302 (GEN) | 592 |
| 5962-88543012A | B | 05/10/1990 | 1 | IDT | | Y | IDT54FCT521LB | 209 |
| 5962-88543012A | B | 05/10/1990 | 3 | NATIONAL | | Y | 54FCT521LMQB | 209 |
| 5962-8854301RA | B | 05/10/1990 | 1 | IDT | | Y | IDT54FCT521DB | 209 |
| 5962-8854301RA | B | 05/10/1990 | 3 | NATIONAL | | Y | 54FCT521DMQB | 209 |
| 5962-8854301SA | B | 05/10/1990 | 3 | NATIONAL | | Y | 54FCT521FMQB | 209 |
| 5962-88543022A | B | 05/10/1990 | 1 | IDT | | Y | IDT54FCT521ALB | 209 |
| 5962-8854302RA | B | 05/10/1990 | 1 | IDT | | Y | IDT54FCT521ADB | 209 |
| 5962-8854302SA | B | 05/10/1990 | | (NONE) | 04/29/2002 | | 54FCT521A (GEN) | 209 |
| 5962-88543032A | B | 05/10/1990 | 1 | IDT | | Y | IDT54FCT521BLB | 209 |
| 5962-8854303RA | B | 05/10/1990 | 1 | IDT | | Y | IDT54FCT521BDB | 209 |
| 5962-8854303SA | B | 05/10/1990 | | (NONE) | 04/29/2002 | | 54FCT521B (GEN) | 209 |
| 5962-8854401LA | B | 02/13/1992 | 1 | AUSTIN SEMI. | | Y | MT5C2561C35L883C | 623 |
| 5962-8854401XA | B | 02/13/1992 | 1 | AUSTIN SEMI. | | Y | MT5C2561EC35L883C | 623 |
| 5962-8854401YA | B | 02/13/1992 | | (NONE) | | | 81256LP35 (GEN) | 623 |
| 5962-8854402LA | B | 02/13/1992 | 1 | AUSTIN SEMI. | | Y | MT5C2561C45L883C | 623 |
| 5962-8854402XA | B | 02/13/1992 | 1 | AUSTIN SEMI. | | Y | MT5C2561EC45L883C | 623 |
| 5962-8854402YA | B | 02/13/1992 | | (NONE) | | | 81256LP45 (GEN) | 623 |
| 5962-8854403LA | B | 02/13/1992 | 1 | AUSTIN SEMI. | | Y | MT5C2561C55L883C | 623 |
| 5962-8854403XA | B | 02/13/1992 | 1 | AUSTIN SEMI. | | Y | MT5C2561EC55L883C | 623 |
| 5962-8854403YA | B | 02/13/1992 | | (NONE) | | | 81256LP55 (GEN) | 623 |
| 5962-8854404LA | B | 02/13/1992 | 1 | AUSTIN SEMI. | | Y | MT5C2561C70L883C | 623 |
| 5962-8854404XA | B | 02/13/1992 | 1 | AUSTIN SEMI. | | Y | MT5C2561EC70L883C | 623 |
| 5962-8854404YA | B | 02/13/1992 | | (NONE) | | | 81256P70 (GEN) | 623 |
| 5962-8854501LA | B | 04/04/2001 | 1 | AUSTIN SEMI. | | Y | MT5C2564C-35L/883C | 623 |
| 5962-8854501XA | B | 04/04/2001 | 1 | AUSTIN SEMI. | | Y | MT5C2564EC-35L/883C | 623 |
| 5962-8854501YA | B | 04/04/2001 | 1 | AUSTIN SEMI. | | Y | MT5C2564F-35L/883C | 623 |
| 5962-8854502LA | B | 04/04/2001 | 1 | AUSTIN SEMI. | | Y | MT5C2564C-45L/883C | 623 |
| 5962-8854502XA | B | 04/04/2001 | 1 | AUSTIN SEMI. | | Y | MT5C2564EC-45L/883C | 623 |
| 5962-8854502YA | B | 04/04/2001 | 1 | AUSTIN SEMI. | | Y | MT5C2564F-45L/883C | 623 |
| 5962-8854503LA | B | 04/04/2001 | 1 | AUSTIN SEMI. | | Y | MT5C2564C-55L/883C | 623 |
| 5962-8854503XA | B | 04/04/2001 | 1 | AUSTIN SEMI. | | Y | MT5C2564EC-55L/883C | 623 |
| 5962-8854503YA | B | 04/04/2001 | 1 | AUSTIN SEMI. | | Y | MT5C2564F-55L/883C | 623 |
| 5962-8854504LA | B | 04/04/2001 | 1 | AUSTIN SEMI. | | Y | MT5C2564C-70L/883C | 623 |
| 5962-8854504XA | B | 04/04/2001 | 1 | AUSTIN SEMI. | | Y | MT5C2564EC-70L/883C | 623 |
| 5962-8854504YA | B | 04/04/2001 | 1 | AUSTIN SEMI. | | Y | MT5C2564F-70L/883C | 623 |
| 5962-88546013A | A | 08/15/1989 | | (NONE) | | | 54F676 (GEN) | 230 |
| 5962-8854601KA | A | 08/15/1989 | | (NONE) | | | 54F676 (GEN) | 230 |
| 5962-8854601LA | A | 08/15/1989 | | (NONE) | | | 54F676 (GEN) | 230 |
| 5962-8854701QA | A | 04/10/1990 | | (NONE) | 12/24/1997 | | 80872 (GEN) | 409 |
| 5962-8854702QA | A | 04/10/1990 | | (NONE) | 12/24/1997 | | 8087 (GEN) | 409 |
| 5962-8854801QA | A | 09/11/1992 | | (NONE) | 06/30/1995 | | EP900-60 (GEN) | 431 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-8854901XA | A | 04/17/1992 | | (NONE) | 10/31/1996 | | 1800-90 (GEN) | 431 |
| 5962-8854901YA | A | 04/17/1992 | | (NONE) | | | | 431 |
| 5962-8854901ZA | A | 04/17/1992 | | (NONE) | 04/15/1995 | | 5C180-90 (GEN) | 431 |
| 5962-8854902UA | A | 04/17/1992 | | (NONE) | | | | 431 |
| 5962-8854902YA | A | 04/17/1992 | | (NONE) | | | | 431 |
| 5962-88550012A | C | 05/21/2001 | 3 | NATIONAL | | Y | 54F273/LMQB | 159 |
| 5962-8855001RA | C | 05/21/2001 | 3 | NATIONAL | | Y | 54F273/DMQB | 159 |
| 5962-8855001SA | C | 05/21/2001 | 3 | NATIONAL | | Y | 54F273/FMQB | 159 |
| 5962-8855101CA | A | 07/01/1992 | | (NONE) | | | UH503 (GEN) | 531 |
| 5962-8855101DA | A | 07/01/1992 | | (NONE) | | | UH503 (GEN) | 531 |
| 5962-8855201MA | F | 08/16/2002 | | (NONE) | 05/06/1997 | | 71256L100 (GEN) | 623 |
| 5962-8855201NA | F | 08/16/2002 | 2 | QP SEMI | | Y | QP7C199L-100KMB | 623 |
| 5962-8855201UA | F | 08/16/2002 | 1 | IDT | | Y | IDT71256L100TDB | 623 |
| 5962-8855201UA | F | 08/16/2002 | 2 | QP SEMI | | Y | QP7C199L-100DMB | 623 |
| 5962-8855201XA | F | 08/16/2002 | 1 | IDT | | Y | IDT71256L100DB | 623 |
| 5962-8855201XA | F | 08/16/2002 | 2 | QP SEMI | | Y | QP7C198L-100DMB | 623 |
| 5962-8855201YA | F | 08/16/2002 | 1 | IDT | | Y | IDT71256L100L32B | 623 |
| 5962-8855201YA | F | 08/16/2002 | 2 | QP SEMI | | Y | QP7C198L-100LMB | 623 |
| 5962-8855201ZA | F | 08/16/2002 | | (NONE) | | | | 623 |
| 5962-8855202MA | F | 08/16/2002 | | (NONE) | 05/06/1997 | | 71256L70 (GEN) | 623 |
| 5962-8855202NA | F | 08/16/2002 | 2 | QP SEMI | | Y | QP7C199L-70KMB | 623 |
| 5962-8855202UA | F | 08/16/2002 | 1 | IDT | | Y | IDT71256L70TDB | 623 |
| 5962-8855202UA | F | 08/16/2002 | 2 | QP SEMI | | Y | QP7C199L-70DMB | 623 |
| 5962-8855202XA | F | 08/16/2002 | 1 | IDT | | Y | IDT71256L70DB | 623 |
| 5962-8855202XA | F | 08/16/2002 | 2 | QP SEMI | | Y | QP7C198L-70DMB | 623 |
| 5962-8855202YA | F | 08/16/2002 | 1 | IDT | | Y | IDT71256L70L32B | 623 |
| 5962-8855202YA | F | 08/16/2002 | 2 | QP SEMI | | Y | QP7C198L-70LMB | 623 |
| 5962-8855202ZA | F | 08/16/2002 | | (NONE) | | | | 623 |
| 5962-8855203MA | F | 08/16/2002 | | (NONE) | 05/06/1997 | | 71256L55 (GEN) | 623 |
| 5962-8855203NA | F | 08/16/2002 | 2 | QP SEMI | | Y | QP7C199L-55KMB | 623 |
| 5962-8855203UA | F | 08/16/2002 | 1 | IDT | | Y | IDT71256L55TDB | 623 |
| 5962-8855203UA | F | 08/16/2002 | 2 | QP SEMI | | Y | QP7C199L-55DMB | 623 |
| 5962-8855203XA | F | 08/16/2002 | 1 | IDT | | Y | IDT71256L55DB | 623 |
| 5962-8855203XA | F | 08/16/2002 | 2 | QP SEMI | | Y | QP7C198L-55DMB | 623 |
| 5962-8855203YA | F | 08/16/2002 | 1 | IDT | | Y | IDT71256L55L32B | 623 |
| 5962-8855203YA | F | 08/16/2002 | 2 | QP SEMI | | Y | QP7C198L-55LMB | 623 |
| 5962-8855203ZA | F | 08/16/2002 | | (NONE) | | | | 623 |
| 5962-8855204MA | F | 08/16/2002 | | (NONE) | 05/06/1997 | | 71256L45 (GEN) | 623 |
| 5962-8855204NA | F | 08/16/2002 | 2 | QP SEMI | | Y | QP7C199L-45KMB | 623 |
| 5962-8855204UA | F | 08/16/2002 | 1 | IDT | | Y | IDT71256L45TDB | 623 |
| 5962-8855204UA | F | 08/16/2002 | 2 | QP SEMI | | Y | QP7C199L-45DMB | 623 |
| 5962-8855204XA | F | 08/16/2002 | 1 | IDT | | Y | IDT71256L45DB | 623 |
| 5962-8855204XA | F | 08/16/2002 | 2 | QP SEMI | | Y | QP7C198L-45DMB | 623 |
| 5962-8855204YA | F | 08/16/2002 | 1 | IDT | | Y | IDT71256L45L32B | 623 |
| 5962-8855204YA | F | 08/16/2002 | 2 | QP SEMI | | Y | QP7C198L-45LMB | 623 |
| 5962-8855204ZA | F | 08/16/2002 | | (NONE) | | | | 623 |
| 5962-8855205MA | F | 08/16/2002 | 1 | AUSTIN SEMI. | | Y | AS5C2568EC-35L/883C | 623 |
| 5962-8855205MA | F | 08/16/2002 | 2 | QP SEMI | | Y | QP7C199L-35LMB | 623 |
| 5962-8855205NA | F | 08/16/2002 | 2 | QP SEMI | | Y | QP7C199L-35KMB | 623 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-8855205TA | F | 08/16/2002 | 1 | AUSTIN SEMI. | | Y | AS5C2568F-35L/883C | 623 |
| 5962-8855205TA | F | 08/16/2002 | 2 | QP SEMI | | Y | QP7C199L-35FMB | 623 |
| 5962-8855205UA | F | 08/16/2002 | 1 | AUSTIN SEMI. | | Y | AS5C2568C-35L/883C | 623 |
| 5962-8855205UA | F | 08/16/2002 | 2 | QP SEMI | | Y | QP7C199L-35DMB | 623 |
| 5962-8855205XA | F | 08/16/2002 | 1 | AUSTIN SEMI. | | Y | AS5C2568CW-35L/883 | 623 |
| 5962-8855205XA | F | 08/16/2002 | 2 | QP SEMI | | Y | QP7C198L-35DMB | 623 |
| 5962-8855205YA | F | 08/16/2002 | 1 | AUSTIN SEMI. | | Y | AS5C2568ECW-35L/88 | 623 |
| 5962-8855205YA | F | 08/16/2002 | 2 | QP SEMI | | Y | QP7C198L-35LMB | 623 |
| 5962-8855205ZA | F | 08/16/2002 | | (NONE) | | | 7C199-35 (GEN) | 623 |
| 5962-8855206MA | F | 08/16/2002 | 1 | AUSTIN SEMI. | | Y | AS5C2568EC-25L/883C | 623 |
| 5962-8855206MA | F | 08/16/2002 | 2 | QP SEMI | | Y | QP7C199L-25LMB | 623 |
| 5962-8855206NA | F | 08/16/2002 | 2 | QP SEMI | | Y | QP7C199L-25KMB | 623 |
| 5962-8855206TA | F | 08/16/2002 | 1 | AUSTIN SEMI. | | Y | AS5C2568F-25L/883C | 623 |
| 5962-8855206TA | F | 08/16/2002 | 2 | QP SEMI | | Y | QP7C199L-25FMB | 623 |
| 5962-8855206UA | F | 08/16/2002 | 1 | AUSTIN SEMI. | | Y | AS5C2568C-25L/883C | 623 |
| 5962-8855206UA | F | 08/16/2002 | 1 | IDT | | Y | IDT71256L25TDB | 623 |
| 5962-8855206UA | F | 08/16/2002 | 2 | QP SEMI | | Y | QP7C199L-25DMB | 623 |
| 5962-8855206XA | F | 08/16/2002 | 1 | AUSTIN SEMI. | | Y | AS5C2568CW-25L/883 | 623 |
| 5962-8855206XA | F | 08/16/2002 | 1 | IDT | | Y | IDT71256L25DB | 623 |
| 5962-8855206XA | F | 08/16/2002 | 2 | QP SEMI | | Y | QP7C198L-25DMB | 623 |
| 5962-8855206YA | F | 08/16/2002 | 1 | AUSTIN SEMI. | | Y | AS5C2568ECW-25L/88 | 623 |
| 5962-8855206YA | F | 08/16/2002 | 1 | IDT | | Y | IDT71256L25L32B | 623 |
| 5962-8855206YA | F | 08/16/2002 | 2 | QP SEMI | | Y | QP7C198L-25LMB | 623 |
| 5962-8855206ZA | F | 08/16/2002 | | (NONE) | | | | 623 |
| 5962-8855207MA | F | 08/16/2002 | 1 | AUSTIN SEMI. | | Y | AS5C2568EC-70L/883C | 623 |
| 5962-8855207MA | F | 08/16/2002 | 2 | QP SEMI | | Y | QP7C199L-70LMB | 623 |
| 5962-8855207NA | F | 08/16/2002 | 2 | QP SEMI | | Y | QP7C199L-70KMB | 623 |
| 5962-8855207TA | F | 08/16/2002 | 1 | AUSTIN SEMI. | | Y | AS5C2568F-70L/883C | 623 |
| 5962-8855207TA | F | 08/16/2002 | 2 | QP SEMI | | Y | QP7C199L-70FMB | 623 |
| 5962-8855207UA | F | 08/16/2002 | 1 | AUSTIN SEMI. | | Y | AS5C2568C-70L/883C | 623 |
| 5962-8855207UA | F | 08/16/2002 | 2 | QP SEMI | | Y | QP7C199L-70DMB | 623 |
| 5962-8855207XA | F | 08/16/2002 | 1 | AUSTIN SEMI. | | Y | AS5C2568CW-70L/883 | 623 |
| 5962-8855207XA | F | 08/16/2002 | 2 | QP SEMI | | Y | QP7C198L-70DMB | 623 |
| 5962-8855207YA | F | 08/16/2002 | 1 | AUSTIN SEMI. | | Y | AS5C2568ECW-70L/88 | 623 |
| 5962-8855207YA | F | 08/16/2002 | 2 | QP SEMI | | Y | QP7C198L-70LMB | 623 |
| 5962-8855207ZA | F | 08/16/2002 | | (NONE) | | | | 623 |
| 5962-8855208MA | F | 08/16/2002 | 1 | AUSTIN SEMI. | | Y | AS5C2568EC-55L/883C | 623 |
| 5962-8855208MA | F | 08/16/2002 | 2 | QP SEMI | | Y | QP7C199L-55LMB | 623 |
| 5962-8855208NA | F | 08/16/2002 | 2 | QP SEMI | | Y | QP7C199L-55KMB | 623 |
| 5962-8855208TA | F | 08/16/2002 | 1 | AUSTIN SEMI. | | Y | AS5C2568F-55L/883C | 623 |
| 5962-8855208TA | F | 08/16/2002 | 2 | QP SEMI | | Y | QP7C199L-55FMB | 623 |
| 5962-8855208UA | F | 08/16/2002 | 1 | AUSTIN SEMI. | | Y | AS5C2568C-55L/883C | 623 |
| 5962-8855208UA | F | 08/16/2002 | 2 | QP SEMI | | Y | QP7C199L-55DMB | 623 |
| 5962-8855208XA | F | 08/16/2002 | 1 | AUSTIN SEMI. | | Y | AS5C2568CW-55L/883 | 623 |
| 5962-8855208XA | F | 08/16/2002 | 2 | QP SEMI | | Y | QP7C198L-55DMB | 623 |
| 5962-8855208YA | F | 08/16/2002 | 1 | AUSTIN SEMI. | | Y | AS5C2568ECW-55L/88 | 623 |
| 5962-8855208YA | F | 08/16/2002 | 2 | QP SEMI | | Y | QP7C198L-55LMB | 623 |
| 5962-8855208ZA | F | 08/16/2002 | | (NONE) | | | 7C199-55 (GEN) | 623 |
| 5962-8855209MA | F | 08/16/2002 | 1 | AUSTIN SEMI. | | Y | AS5C2568EC-45L/883C | 623 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-8855209MA | F | 08/16/2002 | 2 | QP SEMI | | Y | QP7C199L-45LMB | 623 |
| 5962-8855209NA | F | 08/16/2002 | 2 | QP SEMI | | Y | QP7C199L-45KMB | 623 |
| 5962-8855209TA | F | 08/16/2002 | 1 | AUSTIN SEMI. | | Y | AS5C2568F-45L/883C | 623 |
| 5962-8855209TA | F | 08/16/2002 | 2 | QP SEMI | | Y | QP7C199L-45FMB | 623 |
| 5962-8855209UA | F | 08/16/2002 | 1 | AUSTIN SEMI. | | Y | AS5C2568C-45L/883C | 623 |
| 5962-8855209UA | F | 08/16/2002 | 2 | QP SEMI | | Y | QP7C199L-45DMB | 623 |
| 5962-8855209XA | F | 08/16/2002 | 1 | AUSTIN SEMI. | | Y | AS5C2568CW-45L/883 | 623 |
| 5962-8855209XA | F | 08/16/2002 | 2 | QP SEMI | | Y | QP7C198L-45DMB | 623 |
| 5962-8855209YA | F | 08/16/2002 | 1 | AUSTIN SEMI. | | Y | AS5C2568ECW-45L/88 | 623 |
| 5962-8855209YA | F | 08/16/2002 | 2 | QP SEMI | | Y | QP7C198L-45LMB | 623 |
| 5962-8855209ZA | F | 08/16/2002 | | (NONE) | | | 7C199-45L (GEN) | 623 |
| 5962-8855210MA | F | 08/16/2002 | 1 | AUSTIN SEMI. | | Y | AS5C2568EC-20L/883C | 623 |
| 5962-8855210MA | F | 08/16/2002 | 2 | QP SEMI | | Y | QP7C199L-20LMB | 623 |
| 5962-8855210NA | F | 08/16/2002 | 2 | QP SEMI | | Y | QP7C199L-20KMB | 623 |
| 5962-8855210TA | F | 08/16/2002 | 1 | AUSTIN SEMI. | | Y | AS5C2568F-20L/883C | 623 |
| 5962-8855210TA | F | 08/16/2002 | 2 | QP SEMI | | Y | QP7C199L-20FMB | 623 |
| 5962-8855210UA | F | 08/16/2002 | 1 | AUSTIN SEMI. | | Y | AS5C2568C-20L/883C | 623 |
| 5962-8855210UA | F | 08/16/2002 | 2 | QP SEMI | | Y | QP7C199L-20DMB | 623 |
| 5962-8855210XA | F | 08/16/2002 | 1 | AUSTIN SEMI. | | Y | AS5C2568CW-20L/883 | 623 |
| 5962-8855210XA | F | 08/16/2002 | 2 | QP SEMI | | Y | QP7C198L-20DMB | 623 |
| 5962-8855210YA | F | 08/16/2002 | 1 | AUSTIN SEMI. | | Y | AS5C2568ECW-20L/88 | 623 |
| 5962-8855210YA | F | 08/16/2002 | 2 | QP SEMI | | Y | QP7C198L-20LMB | 623 |
| 5962-8855211MA | F | 08/16/2002 | 1 | AUSTIN SEMI. | | Y | AS5C2568EC-17L/883C | 623 |
| 5962-8855211MA | F | 08/16/2002 | 2 | QP SEMI | | Y | QP7C199L-17LMB | 623 |
| 5962-8855211NA | F | 08/16/2002 | 2 | QP SEMI | | Y | QP7C199L-17KMB | 623 |
| 5962-8855211TA | F | 08/16/2002 | 1 | AUSTIN SEMI. | | Y | AS5C2568F-17L/883C | 623 |
| 5962-8855211TA | F | 08/16/2002 | 2 | QP SEMI | | Y | QP7C199L-17FMB | 623 |
| 5962-8855211UA | F | 08/16/2002 | 1 | AUSTIN SEMI. | | Y | AS5C2568C-17L/883C | 623 |
| 5962-8855211UA | F | 08/16/2002 | 2 | QP SEMI | | Y | QP7C199L-17DMB | 623 |
| 5962-8855211XA | F | 08/16/2002 | 1 | AUSTIN SEMI. | | Y | AS5C2568CW-17L/883 | 623 |
| 5962-8855211XA | F | 08/16/2002 | 2 | QP SEMI | | Y | QP7C198L-17DMB | 623 |
| 5962-8855211YA | F | 08/16/2002 | 1 | AUSTIN SEMI. | | Y | AS5C2568ECW-17L/88 | 623 |
| 5962-8855211YA | F | 08/16/2002 | 2 | QP SEMI | | Y | QP7C198L-17LMB | 623 |
| 5962-8855212MA | F | 08/16/2002 | 1 | AUSTIN SEMI. | | Y | AS5C2568EC-15L/883C | 623 |
| 5962-8855212MA | F | 08/16/2002 | 2 | QP SEMI | | Y | QP7C199L-15LMB | 623 |
| 5962-8855212NA | F | 08/16/2002 | 2 | QP SEMI | | Y | QP7C199L-15KMB | 623 |
| 5962-8855212TA | F | 08/16/2002 | 1 | AUSTIN SEMI. | | Y | AS5C2568F-15L/883C | 623 |
| 5962-8855212TA | F | 08/16/2002 | 2 | QP SEMI | | Y | QP7C199L-15FMB | 623 |
| 5962-8855212UA | F | 08/16/2002 | 1 | AUSTIN SEMI. | | Y | AS5C2568C-15L/883C | 623 |
| 5962-8855212UA | F | 08/16/2002 | 2 | QP SEMI | | Y | QP7C199L-15DMB | 623 |
| 5962-8855212XA | F | 08/16/2002 | 1 | AUSTIN SEMI. | | Y | AS5C2568CW-15L/883 | 623 |
| 5962-8855212XA | F | 08/16/2002 | 2 | QP SEMI | | Y | QP7C198L-15DMB | 623 |
| 5962-8855212YA | F | 08/16/2002 | 1 | AUSTIN SEMI. | | Y | AS5C2568ECW-15L/88 | 623 |
| 5962-8855212YA | F | 08/16/2002 | 2 | QP SEMI | | Y | QP7C198L-15LMB | 623 |
| 5962-8855213MA | F | 08/16/2002 | 1 | AUSTIN SEMI. | | Y | AS5C2568EC-12L/883C | 623 |
| 5962-8855213TA | F | 08/16/2002 | 1 | AUSTIN SEMI. | | Y | AS5C2568F-12L/883C | 623 |
| 5962-8855213UA | F | 08/16/2002 | 1 | AUSTIN SEMI. | | Y | AS5C2568C-12L/883C | 623 |
| 5962-8855213XA | F | 08/16/2002 | 1 | AUSTIN SEMI. | | Y | AS5C2568CW-12L/883 | 623 |
| 5962-8855213YA | F | 08/16/2002 | 1 | AUSTIN SEMI. | | Y | AS5C2568ECW-12L/88 | 623 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-88553012A | F | 02/11/2002 | 1 | MICROSEMI | | Y | SG7815AL/883B | 782 |
| 5962-88553012A | F | 02/11/2002 | 1 | SOLITRON | | | SDP7815A2MD | 782 |
| 5962-88553014A | F | 02/11/2002 | | (NONE) | | | 7815A (GEN) | 782 |
| 5962-88553015A | F | 02/11/2002 | | (NONE) | | | 7815A (GEN) | 782 |
| 5962-8855301MA | F | 02/11/2002 | | (NONE) | | | 7815A (GEN) | 782 |
| 5962-8855301NA | F | 02/11/2002 | 1 | SOLITRON | | | SDP7815ANMD | 782 |
| 5962-8855301TA | F | 02/11/2002 | 1 | SEMELAB | | Y | IP7815AG-DESC | 782 |
| 5962-8855301TA | F | 02/11/2002 | 1 | SOLITRON | | | SDP7815ATMD | 782 |
| 5962-8855301UA | F | 02/11/2002 | 0 | MICROSEMI | | Y | SG7815AIG/883B | 782 |
| 5962-8855301UA | F | 02/11/2002 | 1 | SEMELAB | | Y | IP7815AIG-DESC | 782 |
| 5962-8855301UA | F | 02/11/2002 | 1 | SOLITRON | | | SDP7815AUMD | 782 |
| 5962F8855301UA | F | 02/11/2002 | | (NONE) | | | 7815A (GEN) | 782 |
| 5962-8855301XA | F | 02/11/2002 | 0 | MICROSEMI | | Y | SG7815AT/883B | 782 |
| 5962-8855301XA | F | 02/11/2002 | 1 | SEMELAB | | Y | IP78M15AH-DESC | 782 |
| 5962-8855301YA | F | 02/11/2002 | 0 | MICROSEMI | | Y | SG7815AK/883B | 782 |
| 5962-8855301YA | F | 02/11/2002 | 1 | SEMELAB | | Y | IP7815AK-DESC | 782 |
| 5962-8855301ZA | F | 02/11/2002 | 0 | MICROSEMI | | Y | SG7815AR/883B | 782 |
| 5962-8855301ZA | F | 02/11/2002 | 1 | SEMELAB | | Y | IP7815AR-DESC | 782 |
| 5962-8855301ZA | F | 02/11/2002 | 1 | SOLITRON | | | SDP7815AZMD | 782 |
| 5962-8855401XA | B | 07/20/2001 | 1 | MICROSEMI | | Y | SG7824AT/883B | 782 |
| 5962-8855401YA | B | 07/20/2001 | 1 | MICROSEMI | | Y | SG7824AK/883B | 782 |
| 5962-8855401ZA | B | 07/20/2001 | 1 | MICROSEMI | | Y | SG7824AR/883B | 782 |
| 5962-88555012A | C | 05/02/2001 | | (NONE) | 02/27/1998 | | 54F378 (GEN) | 159 |
| 5962-8855501EA | C | 05/02/2001 | 3 | NATIONAL | | Y | 54F378DMQB | 159 |
| 5962-8855501FA | C | 05/02/2001 | 3 | NATIONAL | | Y | 54F378FMQB | 159 |
| 5962-8855601EA | | 05/16/1988 | 1 | TI | | Y | CD54HC4052F3A | 192 |
| 5962-88557012A | B | 04/10/2000 | 1 | LANSDALE | | Y | SL10541/B2A | 222 |
| 5962-88557012A | B | 04/10/2000 | 3 | SARNOFF | | Y | GEM17401Q2A | 222 |
| 5962-88557012C | B | 04/10/2000 | 1 | LANSDALE | | Y | SL10541/B2C | 222 |
| 5962-88557012C | B | 04/10/2000 | 3 | SARNOFF | | Y | GEM17401Q2C | 222 |
| 5962-8855701EA | B | 04/10/2000 | 1 | LANSDALE | | Y | SL10541/BEA | 222 |
| 5962-8855701EA | B | 04/10/2000 | 3 | SARNOFF | | Y | GEM17401QEA | 222 |
| 5962-8855701EC | B | 04/10/2000 | 3 | SARNOFF | | Y | GEM17401QEC | 222 |
| 5962-8855701FA | B | 04/10/2000 | 1 | LANSDALE | | Y | SL10541/BFA | 222 |
| 5962-8855701FA | B | 04/10/2000 | 3 | SARNOFF | | Y | GEM17401QFA | 222 |
| 5962-8855701FC | B | 04/10/2000 | 3 | SARNOFF | | Y | GEM17401QFC | 222 |
| 5962-8855901CA | B | 08/06/2004 | | (NONE) | 04/16/2002 | | OP421B (GEN) | 713 |
| 5962-8855902CA | B | 08/06/2004 | 1 | ANALOG (5) | | Y | OP421CY | 713 |
| 5962-88560012A | A | 05/28/1992 | | (NONE) | | | 10545 (GEN) | 602 |
| 5962-8856001EA | A | 05/28/1992 | | (NONE) | 12/31/1994 | | 10545 (GEN) | 602 |
| 5962-8856001FA | A | 05/28/1992 | | (NONE) | 12/31/1994 | | 10545 (GEN) | 602 |
| 5962-8856101XA | B | 04/27/1993 | 2 | NATIONAL | | Y | LM199AH/883 | 785 |
| 5962-8856102XA | B | 04/27/1993 | | (NONE) | 03/30/2001 | | LM199 (GEN) | 785 |
| 5962-8856103XA | B | 04/27/1993 | | (NONE) | | | LM199A-20 (GEN) | 785 |
| 5962-8856201XA | C | 12/06/2001 | 1 | MINCO | | Y | MTL1010MH | 739 |
| 5962-8856201YA | C | 12/06/2001 | 1 | MINCO | | Y | MTL1010MK | 739 |
| 5962-88563013A | | 10/17/1988 | | (NONE) | | | DAC703 (GEN) | 591 |
| 5962-8856301JA | | 10/17/1988 | | (NONE) | | | DAC703 (GEN) | 591 |
| 5962-8856401CA | B | 01/30/2001 | 3 | SARNOFF | | Y | GEM14701QCA | 599 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-8856401CC | B | 01/30/2001 | 3 | SARNOFF | | Y | GEM14701QCC | 599 |
| 5962-8856401DA | B | 01/30/2001 | 3 | SARNOFF | | Y | GEM14701QDA | 599 |
| 5962-8856401DC | B | 01/30/2001 | 3 | SARNOFF | | Y | GEM14701QDC | 599 |
| 5962-88565012A | F | 03/19/2003 | 1 | ANALOG (5) | | Y | OP-470ARC/883C | 713 |
| 5962-8856501V2A | F | 03/19/2003 | 2 | ANALOG (5) | | Y | OP-470ARC/QMLV | 713 |
| 5962R8856501V2A | F | 03/19/2003 | 2 | ANALOG (5) | | Y | OP-470ARC/QMLR | 713 |
| 5962-88565013A | F | 03/19/2003 | | (NONE) | 04/16/2002 | | OP-470A (GEN) | 713 |
| 5962-8856501CA | F | 03/19/2003 | 1 | ANALOG (5) | | Y | OP-470AY/883C | 713 |
| 5962-8856501VCA | F | 03/19/2003 | 2 | ANALOG (5) | | Y | OP-470AY/QMLV | 713 |
| 5962R8856501VCA | F | 03/19/2003 | 2 | ANALOG (5) | | Y | OP-470AY/QMLR | 713 |
| 5962-8856501VKA | F | 03/19/2003 | 2 | ANALOG (5) | | Y | OP-470AN/QMLV | 713 |
| 5962R8856501VKA | F | 03/19/2003 | 2 | ANALOG (5) | | Y | OP-470AN/QMLR | 713 |
| 5962-88565022A | F | 03/19/2003 | 3 | ANALOG (5) | | Y | OP-471ARC/883C | 713 |
| 5962-8856502V2A | F | 03/19/2003 | 2 | ANALOG (5) | | Y | OP-471ARC/QMLV | 713 |
| 5962R8856502V2A | F | 03/19/2003 | 2 | ANALOG (5) | | Y | OP-471ARC/QMLR | 713 |
| 5962-88565023A | F | 03/19/2003 | 3 | ANALOG (5) | | Y | OP-471ATC/883C | 713 |
| 5962-8856502CA | F | 03/19/2003 | 3 | ANALOG (5) | | Y | OP-471AY/883C | 713 |
| 5962-8856502VCA | F | 03/19/2003 | 2 | ANALOG (5) | | Y | OP-471AY/QMLV | 713 |
| 5962R8856502VCA | F | 03/19/2003 | 2 | ANALOG (5) | | Y | OP-471AY/QMLR | 713 |
| 5962-8856502VDA | F | 03/19/2003 | 2 | ANALOG (5) | | Y | OP-471AM/QMLV | 713 |
| 5962R8856502VDA | F | 03/19/2003 | 2 | ANALOG (5) | | Y | OP-471AM/QMLR | 713 |
| 5962-8856502VKA | F | 03/19/2003 | 2 | ANALOG (5) | | Y | OP-471AN/QMLV | 713 |
| 5962R8856502VKA | F | 03/19/2003 | 2 | ANALOG (5) | | Y | OP-471AN/QMLR | 713 |
| 5962-8856601XA | C | 03/25/1994 | | (NONE) | 06/01/1997 | | 2681 (GEN) | 590 |
| 5962-8856602QA | C | 03/25/1994 | | (NONE) | 09/01/1997 | | 2681 (GEN) | 590 |
| 5962-8856602UA | C | 03/25/1994 | | (NONE) | 09/01/1997 | | 2681 (GEN) | 590 |
| 5962-8856602YA | C | 03/25/1994 | | (NONE) | 09/01/1997 | | 2681 (GEN) | 590 |
| 5962-8856603QA | C | 03/25/1994 | | (NONE) | | | 68681 (GEN) | 590 |
| 5962-8856603UA | C | 03/25/1994 | | (NONE) | 09/01/1997 | | 68681 (GEN) | 590 |
| 5962-88567012A | B | 12/08/1992 | | (NONE) | 09/15/1995 | | LT1037A (GEN) | 701 |
| 5962-8856701GA | B | 12/08/1992 | | (NONE) | 03/30/2001 | | LT1037A (GEN) | 701 |
| 5962-8856701PA | B | 12/08/1992 | | (NONE) | 03/30/2001 | | LT1037A (GEN) | 701 |
| 5962-8856801QA | | 05/17/1988 | | (NONE) | 10/15/1995 | | 8035AHL (GEN) | 410 |
| 5962-8856802QA | | 05/17/1988 | | (NONE) | 10/15/1995 | | 8048AH (GEN) | 410 |
| 5962-8857101CA | A | 05/17/1994 | | (NONE) | 09/30/1995 | | 1596 (GEN) | 804 |
| 5962-8857101IA | A | 05/17/1994 | | (NONE) | 09/30/1995 | | 1596 (GEN) | 804 |
| 5962-8857201QA | B | 11/07/1991 | | (NONE) | | | 68154 (GEN) | 421 |
| 5962-88573013A | C | 06/22/1992 | | (NONE) | 08/04/1995 | | 29C853 (GEN) | 590 |
| 5962-8857301KA | C | 06/22/1992 | | (NONE) | 08/04/1995 | | 29C853 (GEN) | 590 |
| 5962-8857301LA | C | 06/22/1992 | | (NONE) | 08/04/1995 | | 29C853 (GEN) | 590 |
| 5962-88573023A | C | 06/22/1992 | | (NONE) | | | 29C855 (GEN) | 590 |
| 5962-8857302KA | C | 06/22/1992 | | (NONE) | | | 29C855 (GEN) | 590 |
| 5962-8857302LA | C | 06/22/1992 | | (NONE) | | | 29C855 (GEN) | 590 |
| 5962-88573033A | C | 06/22/1992 | | (NONE) | | | 29C853A (GEN) | 590 |
| 5962-8857303KA | C | 06/22/1992 | | (NONE) | | | 29C853A (GEN) | 590 |
| 5962-8857303LA | C | 06/22/1992 | | (NONE) | | | 29C853A (GEN) | 590 |
| 5962-88573043A | C | 06/22/1992 | | (NONE) | | | 29C833A (GEN) | 590 |
| 5962-8857304KA | C | 06/22/1992 | | (NONE) | | | 29C833A (GEN) | 590 |
| 5962-8857304LA | C | 06/22/1992 | | (NONE) | | | 29C833A (GEN) | 590 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-88574012A | A | 04/28/1994 | | (NONE) | 12/01/1993 | | 54HC4078 (GEN) | 124 |
| 5962-8857401CA | A | 04/28/1994 | | (NONE) | 12/01/1993 | | 54HC4078 (GEN) | 124 |
| 5962-88575013A | | 09/27/1989 | | (NONE) | | | 54FCT841A (GEN) | 342 |
| 5962-8857501KA | | 09/27/1989 | | (NONE) | 04/27/1998 | | 54FCT841A (GEN) | 342 |
| 5962-8857501LA | | 09/27/1989 | | (NONE) | 04/27/1998 | | 54FCT841A (GEN) | 342 |
| 5962-88575023A | | 09/27/1989 | | (NONE) | 04/27/1998 | | 54FCT841B (GEN) | 342 |
| 5962-8857502KA | | 09/27/1989 | | (NONE) | 04/27/1998 | | 54FCT841B (GEN) | 342 |
| 5962-8857502LA | | 09/27/1989 | | (NONE) | 04/27/1998 | | 54FCT841B (GEN) | 342 |
| 5962-88576012A | | 08/10/1988 | 2 | TI | | | SNJ54HC21FK | 114 |
| 5962-8857601CA | | 08/10/1988 | 2 | TI | | | SNJ54HC21J | 114 |
| 5962-8857601DA | | 08/10/1988 | 1 | TI | | | SNJ54HC21W | 114 |
| 5962-88577012A | C | 04/24/2001 | 1 | SARNOFF | | Y | GEM26401Q2A | 142 |
| 5962-88577012C | C | 04/24/2001 | 1 | SARNOFF | | Y | GEM26401Q2C | 142 |
| 5962-8857701EA | C | 04/24/2001 | 1 | SARNOFF | | Y | GEM26401QEA | 142 |
| 5962-8857701EC | C | 04/24/2001 | 1 | SARNOFF | | Y | GEM26401QEC | 142 |
| 5962-8857701FA | C | 04/24/2001 | 1 | SARNOFF | | Y | GEM26401QFA | 142 |
| 5962-8857701FC | C | 04/24/2001 | 1 | SARNOFF | | Y | GEM26401QFC | 142 |
| 5962-88578012A | B | 04/12/2001 | 2 | TI | | Y | SNJ54ALS688FK | 209 |
| 5962-8857801RA | B | 04/12/2001 | 2 | TI | | Y | SNJ54ALS688J | 209 |
| 5962-8857801SA | B | 04/12/2001 | 2 | TI | | Y | SNJ54ALS688W | 209 |
| 5962-8857901XC | A | 03/29/2002 | | (NONE) | 04/14/2001 | | HOS-050A (GEN) | 760 |
| 5962-8857902XC | A | 03/29/2002 | | (NONE) | 08/29/2003 | | HOS-060S (GEN) | 760 |
| 5962-88581012A | | 02/21/1989 | | (NONE) | 06/30/1996 | | MOH0268D (GEN) | 569 |
| 5962-8858101EA | | 02/21/1989 | | (NONE) | 06/30/1996 | | MOH0268D (GEN) | 569 |
| 5962-8858101FA | | 02/21/1989 | | (NONE) | 06/30/1996 | | MOH0268D (GEN) | 569 |
| 5962-88582012A | A | 02/26/1992 | | (NONE) | 06/30/1996 | | MOHO272C (GEN) | 579 |
| 5962-8858201EA | A | 02/26/1992 | | (NONE) | 06/30/1996 | | MOHO272C (GEN) | 579 |
| 5962-8858201FA | A | 02/26/1992 | | (NONE) | 06/30/1996 | | MOHO272C (GEN) | 579 |
| 5962-88583012A | A | 07/26/2001 | | AUSTIN SEMI. | | Y | MOF1305D | 569 |
| 5962-8858301EA | A | 07/26/2001 | | (NONE) | 06/30/1996 | | MOF1305D (GEN) | 569 |
| 5962-8858301FA | A | 07/26/2001 | | (NONE) | 06/30/1996 | | MOF1305D (GEN) | 569 |
| 5962-88584012A | B | 10/11/2002 | | AUSTIN SEMI. | | Y | MOR1623K | 590 |
| 5962-8858401EA | B | 10/11/2002 | | (NONE) | 06/30/1996 | | MOR1623K (GEN) | 590 |
| 5962-8858401FA | B | 10/11/2002 | | (NONE) | 06/30/1996 | | MOR1623K (GEN) | 590 |
| 5962-8858501XA | B | 02/25/2002 | 1 | AEROFLEX | | Y | CT2565-001-2 | 420 |
| 5962-8858501XC | B | 02/25/2002 | 1 | AEROFLEX | | Y | CT2565-001-1 | 420 |
| 5962-8858501YA | B | 02/25/2002 | 1 | AEROFLEX | | Y | CT2565-201-2 | 420 |
| 5962-8858501YC | B | 02/25/2002 | 1 | AEROFLEX | | Y | CT2565-201-1 | 420 |
| 5962-8858502XA | B | 02/25/2002 | 1 | AEROFLEX | | Y | CT2565-002-2 | 420 |
| 5962-8858502XC | B | 02/25/2002 | 1 | AEROFLEX | | Y | CT2565-002-1 | 420 |
| 5962-8858502YA | B | 02/25/2002 | 1 | AEROFLEX | | Y | CT2565-202-2 | 420 |
| 5962-8858502YC | B | 02/25/2002 | 1 | AEROFLEX | | Y | CT2565-202-1 | 420 |
| 5962-8858601XA | D | 06/18/2004 | 1 | DDC | | Y | BUS-66300II-140 | 590 |
| 5962-8858601XC | D | 06/18/2004 | 1 | DDC | | Y | BUS-66300II-883B | 590 |
| 5962-8858601YA | D | 06/18/2004 | 1 | DDC | | Y | BUS-66301II-140 | 590 |
| 5962-8858601YC | D | 06/18/2004 | 1 | DDC | | Y | BUS-66301II-883B | 590 |
| 5962-8858602XA | D | 06/18/2004 | 1 | AEROFLEX | | Y | CT2566-001-2 | 590 |
| 5962-8858602XC | D | 06/18/2004 | 1 | AEROFLEX | | Y | CT2566-001-1 | 590 |
| 5962-8858602YA | D | 06/18/2004 | 1 | AEROFLEX | | Y | CT2566-201-2 | 590 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-8858602YC | D | 06/18/2004 | 1 | AEROFLEX | | Y | CT2566-201-1 | 590 |
| 5962-8858603XA | D | 06/18/2004 | 1 | AEROFLEX | | Y | CT2566-002-2 | 590 |
| 5962-8858603XC | D | 06/18/2004 | 1 | AEROFLEX | | Y | CT2566-002-1 | 590 |
| 5962-8858603YA | D | 06/18/2004 | 1 | AEROFLEX | | Y | CT2566-202-2 | 590 |
| 5962-8858603YC | D | 06/18/2004 | 1 | AEROFLEX | | Y | CT2566-202-1 | 590 |
| 5962-8858701VA | A | 08/09/1996 | | (NONE) | | | | 612 |
| 5962-8858701XA | A | 08/09/1996 | | (NONE) | | | | 612 |
| 5962-8858701YA | A | 08/09/1996 | | (NONE) | | | | 612 |
| 5962-8858702VA | A | 08/09/1996 | | (NONE) | | | | 612 |
| 5962-8858702XA | A | 08/09/1996 | | (NONE) | | | | 612 |
| 5962-8858702YA | A | 08/09/1996 | | (NONE) | | | | 612 |
| 5962-8858703VA | A | 08/09/1996 | 3 | PYRAMID | | | P4C147-35DMB | 612 |
| 5962-8858703XA | A | 08/09/1996 | 3 | PYRAMID | | | P4C147-35FMB | 612 |
| 5962-8858703YA | A | 08/09/1996 | 3 | PYRAMID | | | P4C147-35LMB | 612 |
| 5962-8858801KA | B | 05/01/2002 | | (NONE) | | | | 608 |
| 5962-8858801LA | B | 05/01/2002 | | (NONE) | | | 7C150-35 (GEN) | 608 |
| 5962-8858801XA | B | 05/01/2002 | | (NONE) | | | | 608 |
| 5962-8858802KA | B | 05/01/2002 | | (NONE) | | | | 608 |
| 5962-8858802LA | B | 05/01/2002 | | (NONE) | | | 7C150-25 (GEN) | 608 |
| 5962-8858802XA | B | 05/01/2002 | | (NONE) | | | | 608 |
| 5962-8858803KA | B | 05/01/2002 | | (NONE) | | | | 608 |
| 5962-8858803LA | B | 05/01/2002 | | (NONE) | 05/30/1998 | | 7150-15 (GEN) | 608 |
| 5962-8858803XA | B | 05/01/2002 | | (NONE) | | | | 608 |
| 5962-8858804KA | B | 05/01/2002 | 3 | PYRAMID | | | P4C150-35FMB | 612 |
| 5962-8858804LA | B | 05/01/2002 | 3 | PYRAMID | | | P4C150-35DMB | 612 |
| 5962-8858804XA | B | 05/01/2002 | 3 | PYRAMID | | | P4C150-35LMB | 612 |
| 5962-8858805KA | B | 05/01/2002 | 3 | PYRAMID | | | P4C150-25FMB | 612 |
| 5962-8858805LA | B | 05/01/2002 | 3 | PYRAMID | | | P4C150-25DMB | 612 |
| 5962-8858805XA | B | 05/01/2002 | 3 | PYRAMID | | | P4C150-25LMB | 612 |
| 5962-8858806KA | B | 05/01/2002 | 3 | PYRAMID | | | P4C150-15FMB | 612 |
| 5962-8858806LA | B | 05/01/2002 | 3 | PYRAMID | | | P4C150-15DMB | 612 |
| 5962-8858806XA | B | 05/01/2002 | 3 | PYRAMID | | | P4C150-15LMB | 612 |
| 5962-8858807KA | B | 05/01/2002 | 3 | PYRAMID | | | P4C150-15FMB | 612 |
| 5962-8858901DA | C | 02/15/2001 | 1 | TI | | Y | SNJ54ALS20AW | 104 |
| 5962-8859001FA | B | 02/07/2001 | 2 | TI | | Y | SNJ54ALS133W | 108 |
| 5962-8859101SA | B | 02/05/2001 | 2 | TI | | Y | SNJ54ALS240AW | 529 |
| 5962-88593012A | D | 05/01/2003 | | (NONE) | | | OP-200A (GEN) | 710 |
| 5962-8859301M2A | D | 05/01/2003 | 1 | ANALOG (5) | | Y | OP-200ARC/883 | 710 |
| 5962-8859301V2A | D | 05/01/2003 | 1 | ANALOG (5) | | Y | OP200AZ/QML | 710 |
| 5962-8859301MPA | D | 05/01/2003 | 1 | ANALOG (5) | | Y | OP-200AZ/883 | 710 |
| 5962-8859301PA | D | 05/01/2003 | | (NONE) | | | OP-200A (GEN) | 710 |
| 5962-8859301VPA | D | 05/01/2003 | 1 | ANALOG (5) | | Y | OP200AZ/QML | 710 |
| 5962-8859401KA | B | 10/10/1991 | 1 | PYRAMID | | | P4C422-15FMB | 608 |
| 5962-8859401WA | B | 10/10/1991 | | PYRAMID | | | P4C422-15DMB | 608 |
| 5962-8859401XA | B | 10/10/1991 | | PYRAMID | | | P4C422-15LMB | 608 |
| 5962-8859402KA | B | 10/10/1991 | | PYRAMID | | | P4C422-35FMB | 608 |
| 5962-8859402WA | B | 10/10/1991 | | PYRAMID | | | P4C422-35DMB | 608 |
| 5962-8859402XA | B | 10/10/1991 | | PYRAMID | | | P4C422-35LMB | 608 |
| 5962-8859403KA | B | 10/10/1991 | 1 | PYRAMID | | | P4C422-25FMB | 608 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-8859403WA | B | 10/10/1991 | | PYRAMID | | | P4C422-25DMB | 608 |
| 5962-8859403XA | B | 10/10/1991 | | PYRAMID | | | P4C422-25LMB | 608 |
| 5962-8859501KA | A | 04/21/1989 | | (NONE) | | | 9122-35 (GEN) | 608 |
| 5962-8859501WA | A | 04/21/1989 | | (NONE) | | | 9122-35 (GEN) | 608 |
| 5962-8859601SA | C | 01/30/2001 | | (NONE) | | | 54ALS241 (GEN) | 529 |
| 5962-8859602SA | C | 01/30/2001 | 2 | TI | | | SNJ54ALS241BW | 529 |
| 5962-8859701XA | A | 12/11/2001 | | (NONE) | 12/31/2001 | | LT1004-1.2 (GEN) | 785 |
| 5962-8859702XA | A | 12/11/2001 | | (NONE) | 12/31/2001 | | LT1004-2.5 (GEN) | 785 |
| 5962-88598013A | A | 08/22/1990 | | (NONE) | | | 2925 (GEN) | 422 |
| 5962-8859801LA | A | 08/22/1990 | | (NONE) | | | 2925 (GEN) | 422 |
| 5962-88598023A | A | 08/22/1990 | | (NONE) | 08/04/1995 | | 2925A (GEN) | 422 |
| 5962-8859802LA | A | 08/22/1990 | | (NONE) | 08/04/1995 | | 2925A (GEN) | 422 |
| 5962-8859901JA | | 04/07/1988 | | (NONE) | | | 32C201-10 (GEN) | 420 |
| 5962-8860001GA | C | 07/01/2004 | 1 | LINEAR TECH. | | Y | LT1021BMH-10/883B | 785 |
| 5962-8860002GA | C | 07/01/2004 | 1 | LINEAR TECH. | | Y | LT1021CMH-10/883B | 785 |
| 5962-8860003GA | C | 07/01/2004 | 1 | LINEAR TECH. | | Y | LT1021DMH-10/883B | 785 |
| 5962-88602013A | B | 12/22/2000 | 3 | TI | | Y | SNJ54LS673FK | 230 |
| 5962-8860201JA | B | 12/22/2000 | 3 | TI | | Y | SNJ54LS673J | 230 |
| 5962-8860201KA | B | 12/22/2000 | 3 | TI | | Y | SNJ54LS673W | 230 |
| 5962-8860201LA | B | 12/22/2000 | 3 | TI | | Y | SNJ54LS673JT | 230 |
| 5962-88604013A | A | 08/14/1990 | | (NONE) | | | 29861A (GEN) | 590 |
| 5962-8860401KA | A | 08/14/1990 | | (NONE) | | | 29861A (GEN) | 590 |
| 5962-8860401LA | A | 08/14/1990 | | (NONE) | 06/30/1994 | | 29861A (GEN) | 590 |
| 5962-88604023A | A | 08/14/1990 | | (NONE) | | | 29863A (GEN) | 590 |
| 5962-8860402KA | A | 08/14/1990 | | (NONE) | | | 29863A (GEN) | 590 |
| 5962-8860402LA | A | 08/14/1990 | | (NONE) | 06/30/1994 | | 29863A (GEN) | 590 |
| 5962-88605013A | B | 03/05/2001 | | (NONE) | | | 29827A (GEN) | 569 |
| 5962-8860501KA | B | 03/05/2001 | | (NONE) | | | 29827A (GEN) | 569 |
| 5962-8860501LA | B | 03/05/2001 | | (NONE) | | | 29827A (GEN) | 569 |
| 5962-88605023A | B | 03/05/2001 | | (NONE) | | | 29828A (GEN) | 509 |
| 5962-8860502KA | B | 03/05/2001 | | (NONE) | | | 29828A (GEN) | 509 |
| 5962-8860502LA | B | 03/05/2001 | | (NONE) | 06/30/1994 | | 29828A (GEN) | 509 |
| 5962-8860503QKA | B | 03/05/2001 | 3 | SARNOFF | | Y | GEM19303QKA | 569 |
| 5962-8860503QKC | B | 03/05/2001 | 3 | SARNOFF | | Y | GEM19303QKC | 569 |
| 5962-8860503QLA | B | 03/05/2001 | 3 | SARNOFF | | Y | GEM19303QLA | 569 |
| 5962-8860503QLC | B | 03/05/2001 | 3 | SARNOFF | | Y | GEM19303QLC | 569 |
| 5962-88606012A | C | 01/25/2002 | 1 | ROCHESTER | | Y | 54HC237/B2A | 282 |
| 5962-8860601EA | C | 01/25/2002 | 1 | TI | | Y | CD54HC237F3A | 282 |
| 5962-8860601FA | C | 01/25/2002 | 1 | ROCHESTER | | Y | 54HC237/BFA | 282 |
| 5962-8860601VFA | C | 01/25/2002 | | (NONE) | | | 54HC237 (GEN) | 282 |
| 5962-8860601VXA | C | 01/25/2002 | 2 | STMICRO | | Y | 54HC237K02V | 282 |
| 5962-8860601VXC | C | 01/25/2002 | 2 | STMICRO | | Y | 54HC237K01V | 282 |
| 5962-8860601XA | C | 01/25/2002 | 2 | STMICRO | | Y | 54HC237K02Q | 282 |
| 5962-8860601XC | C | 01/25/2002 | 2 | STMICRO | | Y | 54HC237K01Q | 282 |
| 5962-88607013A | B | 01/29/2001 | 1 | TI | | Y | SNJ54LS674FK | 230 |
| 5962-8860701JA | B | 01/29/2001 | 1 | TI | | Y | SNJ54LS674J | 230 |
| 5962-8860701KA | B | 01/29/2001 | 1 | TI | | Y | SNJ54LS674W | 230 |
| 5962-8860701LA | B | 01/29/2001 | 1 | TI | | Y | SNJ54LS674JT | 230 |
| 5962-88608013A | A | 01/15/2004 | 2 | IDT | | Y | IDT54FCT821ALB | 229 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-8860801KA | A | 01/15/2004 | | (NONE) | 04/29/2002 | | 54FCT821A (GEN) | 229 |
| 5962-8860801LA | A | 01/15/2004 | 2 | IDT | | Y | IDT54FCT821ADB | 229 |
| 5962-88608023A | A | 01/15/2004 | 2 | IDT | | Y | IDT54FCT821BLB | 229 |
| 5962-8860802KA | A | 01/15/2004 | | (NONE) | 04/29/2002 | | 54FCT821B (GEN) | 229 |
| 5962-8860802LA | A | 01/15/2004 | 2 | IDT | | Y | IDT54FCT821BDB | 229 |
| 5962-8861001UA | E | 12/01/1999 | | (NONE) | | | | 618 |
| 5962-8861001XA | E | 12/01/1999 | | (NONE) | | | | 618 |
| 5962-8861001YA | E | 12/01/1999 | | (NONE) | | | | 618 |
| 5962-8861001ZA | E | 12/01/1999 | | (NONE) | | | | 618 |
| 5962-8861002UA | E | 12/01/1999 | | (NONE) | | | | 618 |
| 5962-8861002XA | E | 12/01/1999 | | (NONE) | | | | 618 |
| 5962-8861002YA | E | 12/01/1999 | | (NONE) | | | | 618 |
| 5962-8861002ZA | E | 12/01/1999 | | (NONE) | | | | 618 |
| 5962-8861003UA | E | 12/01/1999 | | (NONE) | | | | 618 |
| 5962-8861003XA | E | 12/01/1999 | | (NONE) | | | | 618 |
| 5962-8861003YA | E | 12/01/1999 | | (NONE) | | | | 618 |
| 5962-8861003ZA | E | 12/01/1999 | | (NONE) | | | | 618 |
| 5962-8861004UA | E | 12/01/1999 | | (NONE) | | | | 618 |
| 5962-8861004XA | E | 12/01/1999 | | (NONE) | | | | 618 |
| 5962-8861004YA | E | 12/01/1999 | | (NONE) | | | | 618 |
| 5962-8861004ZA | E | 12/01/1999 | | (NONE) | | | | 618 |
| 5962-8861005UA | E | 12/01/1999 | | (NONE) | | | | 618 |
| 5962-8861005XA | E | 12/01/1999 | | (NONE) | | | | 618 |
| 5962-8861005YA | E | 12/01/1999 | | (NONE) | | | | 618 |
| 5962-8861005ZA | E | 12/01/1999 | | (NONE) | | | | 618 |
| 5962-8861006UA | E | 12/01/1999 | | (NONE) | | | | 618 |
| 5962-8861006XA | E | 12/01/1999 | | (NONE) | | | | 618 |
| 5962-8861006YA | E | 12/01/1999 | | (NONE) | | | | 618 |
| 5962-8861006ZA | E | 12/01/1999 | | (NONE) | | | | 618 |
| 5962-8861007UA | E | 12/01/1999 | 2 | IDT | | Y | IDT7133SA90FB | 618 |
| 5962-8861007ZA | E | 12/01/1999 | 2 | IDT | | Y | IDT7133SA90GB | 618 |
| 5962-8861008UA | E | 12/01/1999 | 2 | IDT | | Y | IDT7143SA90FB | 618 |
| 5962-8861008ZA | E | 12/01/1999 | 2 | IDT | | Y | IDT7143SA90GB | 618 |
| 5962-8861009UA | E | 12/01/1999 | 2 | IDT | | Y | IDT7133SA70FB | 618 |
| 5962-8861009ZA | E | 12/01/1999 | 2 | IDT | | Y | IDT7133SA70GB | 618 |
| 5962-8861010UA | E | 12/01/1999 | 2 | IDT | | Y | IDT7143SA70FB | 618 |
| 5962-8861010ZA | E | 12/01/1999 | 2 | IDT | | Y | IDT7143SA70GB | 618 |
| 5962-8861011UA | E | 12/01/1999 | 2 | IDT | | Y | IDT7133SA55FB | 618 |
| 5962-8861011ZA | E | 12/01/1999 | 2 | IDT | | Y | IDT7133SA55GB | 618 |
| 5962-8861012UA | E | 12/01/1999 | 2 | IDT | | Y | IDT7143SA55FB | 618 |
| 5962-8861012ZA | E | 12/01/1999 | 2 | IDT | | Y | IDT7143SA55GB | 618 |
| 5962-88611013A | A | 12/09/1991 | | (NONE) | 06/01/1996 | | 71682LA70 (GEN) | 616 |
| 5962-8861101KA | A | 12/09/1991 | | (NONE) | 06/01/1996 | | 71682LA70 (GEN) | 616 |
| 5962-8861101LA | A | 12/09/1991 | | (NONE) | 06/01/1996 | | 71682LA70 (GEN) | 616 |
| 5962-88611023A | A | 12/09/1991 | | (NONE) | 06/01/1996 | | 71682LA55 (GEN) | 616 |
| 5962-8861102KA | A | 12/09/1991 | | (NONE) | 06/01/1996 | | 71682LA55 (GEN) | 616 |
| 5962-8861102LA | A | 12/09/1991 | | (NONE) | 06/01/1996 | | 71682LA55 (GEN) | 616 |
| 5962-88611033A | A | 12/09/1991 | | (NONE) | 06/01/1996 | | 71682LA45 (GEN) | 616 |
| 5962-8861103KA | A | 12/09/1991 | | (NONE) | 06/01/1996 | | 71682LA45 (GEN) | 616 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-8861103LA | A | 12/09/1991 | | (NONE) | 06/01/1996 | | 71682LA45 (GEN) | 616 |
| 5962-88611043A | A | 12/09/1991 | | (NONE) | 06/01/1996 | | 71682LA35 (GEN) | 616 |
| 5962-8861104KA | A | 12/09/1991 | | (NONE) | 06/01/1996 | | 71682LA35 (GEN) | 616 |
| 5962-8861104LA | A | 12/09/1991 | | (NONE) | 06/01/1996 | | 71682LA35 (GEN) | 616 |
| 5962-88611053A | A | 12/09/1991 | | (NONE) | 06/01/1996 | | 71682LA25 (GEN) | 616 |
| 5962-8861105KA | A | 12/09/1991 | | (NONE) | 06/01/1996 | | 71682LA25 (GEN) | 616 |
| 5962-8861105LA | A | 12/09/1991 | | (NONE) | 06/01/1996 | | 71682LA25 (GEN) | 616 |
| 5962-8861201UA | A | 04/10/1990 | | (NONE) | | | 7C9116-99 (GEN) | 403 |
| 5962-8861201XA | A | 04/10/1990 | | (NONE) | | | 7C9116-99 (GEN) | 403 |
| 5962-8861201XC | A | 04/10/1990 | | (NONE) | 06/30/1994 | | 29C116 (GEN) | 403 |
| 5962-8861201YA | A | 04/10/1990 | | (NONE) | | | 7C9116-99 (GEN) | 403 |
| 5962-8861201YC | A | 04/10/1990 | | (NONE) | 06/30/1994 | | 29C116 (GEN) | 403 |
| 5962-8861201ZA | A | 04/10/1990 | | (NONE) | 06/30/1994 | | 29C116 (GEN) | 403 |
| 5962-8861202UA | A | 04/10/1990 | | (NONE) | | | 7C9116-75 (GEN) | 403 |
| 5962-8861202XA | A | 04/10/1990 | | (NONE) | | | 7C9116-75 (GEN) | 403 |
| 5962-8861202XC | A | 04/10/1990 | | (NONE) | 06/30/1994 | | 29C116-1 (GEN) | 403 |
| 5962-8861202YA | A | 04/10/1990 | | (NONE) | | | 7C9116-75 (GEN) | 403 |
| 5962-8861202YC | A | 04/10/1990 | | (NONE) | 06/30/1994 | | 29C116-1 (GEN) | 403 |
| 5962-8861202ZA | A | 04/10/1990 | | (NONE) | 06/30/1994 | | 29C116-1 (GEN) | 403 |
| 5962-8861203UA | A | 04/10/1990 | | (NONE) | | | 7C9116-65 (GEN) | 403 |
| 5962-8861203XA | A | 04/10/1990 | | (NONE) | | | 7C9116-65 (GEN) | 403 |
| 5962-8861203XC | A | 04/10/1990 | | (NONE) | 06/30/1994 | | 29C116-2 (GEN) | 403 |
| 5962-8861203YA | A | 04/10/1990 | | (NONE) | | | 7C9116-65 (GEN) | 403 |
| 5962-8861203YC | A | 04/10/1990 | | (NONE) | 06/30/1994 | | 29C116-2 (GEN) | 403 |
| 5962-8861203ZA | A | 04/10/1990 | | (NONE) | 06/30/1994 | | 29C116-2 (GEN) | 403 |
| 5962-8861204UA | A | 04/10/1990 | | (NONE) | | | 7C9116-40 (GEN) | 403 |
| 5962-8861204XA | A | 04/10/1990 | | (NONE) | | | 7C9116-40 (GEN) | 403 |
| 5962-8861204YA | A | 04/10/1990 | | (NONE) | | | 7C9116-40 (GEN) | 403 |
| 5962-8861301TA | B | 11/25/1991 | | (NONE) | | | 39C60A (GEN) | 355 |
| 5962-8861301UA | B | 11/25/1991 | | (NONE) | | | 39C60A (GEN) | 355 |
| 5962-8861301XA | B | 11/25/1991 | | (NONE) | 05/01/1995 | | 39C60A (GEN) | 355 |
| 5962-8861302TA | B | 11/25/1991 | | (NONE) | | | 39C60 (GEN) | 355 |
| 5962-8861302UA | B | 11/25/1991 | | (NONE) | | | 39C60 (GEN) | 355 |
| 5962-8861302XA | B | 11/25/1991 | | (NONE) | 05/01/1995 | | 39C60 (GEN) | 355 |
| 5962-8861303UA | B | 11/25/1991 | | (NONE) | | | 29C60A (GEN) | 355 |
| 5962-8861303XA | B | 11/25/1991 | | (NONE) | | | 29C60A (GEN) | 355 |
| 5962-8861303YA | B | 11/25/1991 | | (NONE) | | | 29C60A (GEN) | 355 |
| 5962-8861303ZA | B | 11/25/1991 | | (NONE) | | | 29C60A (GEN) | 355 |
| 5962-88615013A | | 08/30/1991 | | (NONE) | | | AD674AU (GEN) | 592 |
| 5962-8861501XA | | 08/30/1991 | | (NONE) | | | AD674AU (GEN) | 592 |
| 5962-88615023A | | 08/30/1991 | | (NONE) | | | AD674AT (GEN) | 592 |
| 5962-8861502XA | | 08/30/1991 | | (NONE) | | | AD674AT (GEN) | 592 |
| 5962-8861701PA | | 04/11/1991 | | (NONE) | 06/30/1996 | | SP8718 (GEN) | 319 |
| 5962-8861901XA | D | 01/31/2000 | 2 | TI | | | SMJ320C25GBM | 432 |
| 5962-8861901YA | D | 01/31/2000 | 2 | TI | | | SMJ320C25FBM | 432 |
| 5962-8861901ZA | D | 01/31/2000 | 2 | TI | | | SMJ320C25FJM | 432 |
| 5962-8861902XA | D | 01/31/2000 | 2 | TI | | | SMJ320C25-50GBM | 432 |
| 5962-8861902ZA | D | 01/31/2000 | 2 | TI | | | SMJ320C25-50FJM | 432 |
| 5962-8861903XA | D | 01/31/2000 | 1 | TI | | | SMJ320C26BGBM | 423 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-8861903YA | D | 01/31/2000 | 1 | TI | | | SMJ320C26BFDM | 423 |
| 5962-88620012A | | 07/28/1988 | | (NONE) | | | 54HC09 (GEN) | 111 |
| 5962-8862001CA | | 07/28/1988 | | (NONE) | | | 54HC09 (GEN) | 111 |
| 5962-88621012A | B | 11/30/2000 | 2 | TI | | Y | SNJ54ALS86FK | 140 |
| 5962-8862101CA | B | 11/30/2000 | 2 | TI | | Y | SNJ54ALS86J | 140 |
| 5962-8862101DA | B | 11/30/2000 | 2 | TI | | Y | SNJ54ALS86W | 140 |
| 5962-8862201GA | B | 01/30/1996 | | (NONE) | | | LT1028 (GEN) | 702 |
| 5962-8862201PA | B | 01/30/1996 | | (NONE) | 03/30/2001 | | LT1028 (GEN) | 702 |
| 5962-8862201XA | B | 01/30/1996 | | (NONE) | 03/30/2001 | | LT1028 (GEN) | 702 |
| 5962-8862202GA | B | 01/30/1996 | | (NONE) | | | LT1028A (GEN) | 702 |
| 5962-8862202PA | B | 01/30/1996 | | (NONE) | 03/30/2001 | | LT1028A (GEN) | 702 |
| 5962-8862202XA | B | 01/30/1996 | | (NONE) | 03/30/2001 | | LT1028A (GEN) | 702 |
| 5962-8862401JA | | 08/10/1988 | | (NONE) | 06/01/2001 | | 54HCT4059 (GEN) | 319 |
| 5962-88625012A | B | 11/30/2000 | 3 | TI | | Y | SNJ54ALS158FK | 275 |
| 5962-8862501EA | B | 11/30/2000 | 3 | TI | | Y | SNJ54ALS158J | 275 |
| 5962-8862501FA | B | 11/30/2000 | 3 | TI | | Y | SNJ54ALS158W | 275 |
| 5962-88626012A | C | 12/07/2000 | 3 | TI | | Y | SNJ54ALS258AFK | 276 |
| 5962-8862601EA | C | 12/07/2000 | 3 | TI | | Y | SNJ54ALS258AJ | 276 |
| 5962-8862601FA | C | 12/07/2000 | 3 | TI | | Y | SNJ54ALS258AW | 276 |
| 5962-88627013A | B | 11/19/1993 | | (NONE) | | | 54F269 (GEN) | 304 |
| 5962-8862701KA | B | 11/19/1993 | | (NONE) | | | 54F269 (GEN) | 304 |
| 5962-8862701LA | B | 11/19/1993 | | (NONE) | 06/01/1997 | | 54F269 (GEN) | 304 |
| 5962-8862801TA | D | 06/14/2001 | 1 | UTMC | | Y | UT1553BBCRTF | 420 |
| 5962-8862801TC | D | 06/14/2001 | 1 | UTMC | | Y | UT1553BBCRTF | 420 |
| 5962H8862801TA | D | 06/14/2001 | 1 | UTMC | | Y | UT1553BCRTFAH | 420 |
| 5962H8862801TC | D | 06/14/2001 | 1 | UTMC | | Y | UT1553BCRTFCH | 420 |
| 5962H8862801VTA | D | 06/14/2001 | 1 | UTMC | | Y | UT1553BCRTVFAH | 420 |
| 5962H8862801VTC | D | 06/14/2001 | 1 | UTMC | | Y | UT1553BCRTVFCH | 420 |
| 5962-8862801XA | D | 06/14/2001 | 1 | UTMC | | Y | UT1553BBCRTG | 420 |
| 5962-8862801XC | D | 06/14/2001 | 1 | UTMC | | Y | UT1553BBCRTG | 420 |
| 5962H8862801VXA | D | 06/14/2001 | 1 | UTMC | | Y | UT1553BCRTVGAH | 420 |
| 5962H8862801VXC | D | 06/14/2001 | 1 | UTMC | | Y | UT1553BCRTVGCH | 420 |
| 5962H8862801XA | D | 06/14/2001 | 1 | UTMC | | Y | UT1553BCRTGAH | 420 |
| 5962H8862801XC | D | 06/14/2001 | 1 | UTMC | | Y | UT1553BCRTGCH | 420 |
| 5962-8862801YA | D | 06/14/2001 | 1 | UTMC | | Y | UT1553BBCRTW | 420 |
| 5962-8862801YC | D | 06/14/2001 | 1 | UTMC | | Y | UT1553BBCRTW | 420 |
| 5962H8862801VYA | D | 06/14/2001 | 1 | UTMC | | Y | UT1553BCRTVWAH | 420 |
| 5962H8862801VYC | D | 06/14/2001 | 1 | UTMC | | Y | UT1553BCRTVWCH | 420 |
| 5962H8862801YA | D | 06/14/2001 | 1 | UTMC | | Y | UT1553BCRTWAH | 420 |
| 5962H8862801YC | D | 06/14/2001 | 1 | UTMC | | Y | UT1553BCRTWCH | 420 |
| 5962-8862801ZA | D | 06/14/2001 | 1 | UTMC | | Y | UT1553BBCRTA | 420 |
| 5962-8862801ZC | D | 06/14/2001 | 1 | UTMC | | Y | UT1553BBCRTA | 420 |
| 5962H8862801VZA | D | 06/14/2001 | 1 | UTMC | | Y | UT1553BCRTVAAH | 420 |
| 5962H8862801VZC | D | 06/14/2001 | 1 | UTMC | | Y | UT1553BCRTVACH | 420 |
| 5962H8862801ZA | D | 06/14/2001 | 1 | UTMC | | Y | UT1553BCRTAAH | 420 |
| 5962H8862801ZC | D | 06/14/2001 | 1 | UTMC | | Y | UT1553BCRTACH | 420 |
| 5962-8862901XA | B | 11/25/1996 | | (NONE) | 09/01/2000 | | HS9324 (GEN) | 591 |
| 5962-8863001V3A | D | 11/22/2002 | 1 | ANALOG (5) | | Y | AMP01ATC/QMLV | 754 |
| 5962-8863001VKA | D | 11/22/2002 | 1 | ANALOG (5) | | Y | AMP01AN/QMLV | 754 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-8863001VA | D | 11/22/2002 | 1 | ANALOG (5) | | Y | AMP-01AX/883 | 754 |
| 5962-8863001VVA | D | 11/22/2002 | 1 | ANALOG (5) | | Y | AMP01AD/QMLV | 754 |
| 5962-88630023A | D | 11/22/2002 | 1 | ANALOG (5) | | Y | AMP-01BTC/883 | 754 |
| 5962-8863002VA | D | 11/22/2002 | 1 | ANALOG (5) | | Y | AMP-01BX/883 | 754 |
| 5962-8863003V3A | D | 11/22/2002 | 1 | ANALOG (5) | | Y | AMP01TC/QMLV | 754 |
| 5962-8863003VKA | D | 11/22/2002 | 1 | ANALOG (5) | | Y | AMP01N/QMLV | 754 |
| 5962-8863003VVA | D | 11/22/2002 | 1 | ANALOG (5) | | Y | AMP01D/QMLV | 754 |
| 5962-8863101GA | D | 02/18/2004 | 1 | ROCHESTER | | Y | DS1631H/883 | 580 |
| 5962-8863101PA | D | 02/18/2004 | 1 | ROCHESTER | | Y | DS1631J-8/883 | 580 |
| 5962-8863401UA | E | 08/07/2000 | 1 | ATMEL | | | AT28HC256-12UM/883 | 662 |
| 5962-8863401UC | E | 08/07/2000 | 3 | XICOR | | | X28HC256KMB-12 | 662 |
| 5962-8863401XA | E | 08/07/2000 | 1 | ATMEL | | | AT28HC256-12DM/883 | 662 |
| 5962-8863401XA | E | 08/07/2000 | 3 | XICOR | | | X28HC256DMB-12 | 662 |
| 5962-8863401YA | E | 08/07/2000 | 1 | ATMEL | | | AT28HC256-12LM/883 | 662 |
| 5962-8863401ZA | E | 08/07/2000 | 1 | ATMEL | | | AT28HC256-12FM/883 | 662 |
| 5962-8863401ZC | E | 08/07/2000 | 3 | XICOR | | | X28HC256FMB-12 | 662 |
| 5962-8863402UA | E | 08/07/2000 | 1 | ATMEL | | | AT28HC256F-12UM/88 | 662 |
| 5962-8863402XA | E | 08/07/2000 | 1 | ATMEL | | | AT28HC256F-12DM/88 | 662 |
| 5962-8863402YA | E | 08/07/2000 | 1 | ATMEL | | | AT28HC256F-12LM/88 | 662 |
| 5962-8863402ZA | E | 08/07/2000 | 1 | ATMEL | | | AT28HC256F-12FM/8 | 662 |
| 5962-8863403UA | E | 08/07/2000 | 1 | ATMEL | | | AT28HC256-90UM/883 | 662 |
| 5962-8863403XA | E | 08/07/2000 | 1 | ATMEL | | | AT28HC256-90DM/883 | 662 |
| 5962-8863403YA | E | 08/07/2000 | 1 | ATMEL | | | AT28HC256-90LM/883 | 662 |
| 5962-8863403ZA | E | 08/07/2000 | 1 | ATMEL | | | AT28HC256-90FM/883 | 662 |
| 5962-8863404UA | E | 08/07/2000 | 1 | ATMEL | | | AT28HC256F-90UM/88 | 662 |
| 5962-8863404XA | E | 08/07/2000 | 1 | ATMEL | | | AT28HC256F-90DM/88 | 662 |
| 5962-8863404YA | E | 08/07/2000 | 1 | ATMEL | | | AT28HC256F-90LM/88 | 662 |
| 5962-8863404ZA | E | 08/07/2000 | 1 | ATMEL | | | AT28HC256F-90FM/88 | 662 |
| 5962-8863405UA | E | 08/07/2000 | 2 | ATMEL | | | AT28HC256-70UM/883 | 662 |
| 5962-8863405XA | E | 08/07/2000 | 2 | ATMEL | | | AT28HC256-70DM/883 | 662 |
| 5962-8863405YA | E | 08/07/2000 | 2 | ATMEL | | | AT28HC256-70LM/883 | 662 |
| 5962-8863405ZA | E | 08/07/2000 | 2 | ATMEL | | | AT28HC256-70FM/883 | 662 |
| 5962-8863501RA | A | 11/03/1993 | | (NONE) | | | | 431 |
| 5962-8863502RA | A | 11/03/1993 | | (NONE) | 06/30/1995 | | EP220-15 (GEN) | 431 |
| 5962-8863503RA | A | 11/03/1993 | | (NONE) | 06/30/1995 | | EP220-12 (GEN) | 431 |
| 5962-88636013A | B | 08/19/1994 | 1 | QP SEMI | | Y | 7C235A-40 | 657 |
| 5962-8863601KA | B | 08/19/1994 | 1 | QP SEMI | | Y | 7C235A-40 | 657 |
| 5962-8863601LA | B | 08/19/1994 | 1 | QP SEMI | | Y | 7C235A-40 | 657 |
| 5962-88636023A | B | 08/19/1994 | 1 | QP SEMI | | Y | 7C235A-30 | 657 |
| 5962-8863602KA | B | 08/19/1994 | 1 | QP SEMI | | Y | 7C235A-30 | 657 |
| 5962-8863602LA | B | 08/19/1994 | 1 | QP SEMI | | Y | 7C235A-30 | 657 |
| 5962-88636033A | B | 08/19/1994 | 1 | QP SEMI | | Y | 7C235A-40 | 657 |
| 5962-8863603KA | B | 08/19/1994 | 1 | QP SEMI | | Y | 7C235A-40 | 657 |
| 5962-8863603LA | B | 08/19/1994 | 2 | CYPRESS | | Y | CY7C235A-40DMB | 657 |
| 5962-88636043A | B | 08/19/1994 | 1 | QP SEMI | | Y | 7C235A-30 | 657 |
| 5962-8863604KA | B | 08/19/1994 | 1 | QP SEMI | | Y | 7C235A-30 | 657 |
| 5962-8863604LA | B | 08/19/1994 | | (NONE) | 11/03/2003 | | 7C235A-30 (GEN) | 657 |
| 5962-88636053A | B | 08/19/1994 | 1 | QP SEMI | | Y | 7C235A-25 | 657 |
| 5962-8863605KA | B | 08/19/1994 | 1 | QP SEMI | | Y | 7C235A-25 | 657 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-8863605LA | B | 08/19/1994 | 1 | QP SEMI | | Y | 7C235A-25 | 657 |
| 5962-88637013A | B | 07/28/1999 | | (NONE) | | | 20G10-40 (GEN) | 431 |
| 5962-8863701KA | B | 07/28/1999 | | (NONE) | | | 20G10-40 (GEN) | 431 |
| 5962-8863701LA | B | 07/28/1999 | | (NONE) | | | 20G10-40 (GEN) | 431 |
| 5962-88637023A | B | 07/28/1999 | 2 | CYPRESS | 05/03/2004 | Y | PLDC20G10-30LMB | 431 |
| 5962-8863702KA | B | 07/28/1999 | | (NONE) | | | 20G10-30 (GEN) | 431 |
| 5962-8863702LA | B | 07/28/1999 | 2 | CYPRESS | 05/03/2004 | Y | PLDC20G10-30DMB | 431 |
| 5962-8863802XC | C | 10/04/1996 | | (NONE) | 01/01/1999 | | 2018-33 (GEN) | 431 |
| 5962-8863803XC | C | 10/04/1996 | | (NONE) | 01/01/1999 | | 2018-50 (GEN) | 431 |
| 5962-8863804XC | C | 10/04/1996 | | (NONE) | 01/01/1999 | | 2018-70 (GEN) | 431 |
| 5962-8863805XC | C | 10/04/1996 | | (NONE) | 01/01/1999 | | 2018-100 (GEN) | 431 |
| 5962-88639012A | B | 06/19/1992 | 2 | NATIONAL | | Y | 54FCT573LMQB | 341 |
| 5962-8863901RA | B | 06/19/1992 | 2 | NATIONAL | | Y | 54FCT573DMQB | 341 |
| 5962-8863901SA | B | 06/19/1992 | 2 | NATIONAL | | Y | 54FCT573FMQB | 341 |
| 5962-88639022A | B | 06/19/1992 | | (NONE) | 04/27/1998 | | 54FCT573A (GEN) | 341 |
| 5962-8863902RA | B | 06/19/1992 | | (NONE) | 04/27/1998 | | 54FCT573A (GEN) | 341 |
| 5962-8863902SA | B | 06/19/1992 | | (NONE) | 04/27/1998 | | 54FCT573A (GEN) | 341 |
| 5962-88640012A | A | 03/06/1992 | | (NONE) | | | 54FCT161 (GEN) | 304 |
| 5962-8864001EA | A | 03/06/1992 | | (NONE) | | | 54FCT161 (GEN) | 304 |
| 5962-8864001FA | A | 03/06/1992 | | (NONE) | | | 54FCT161 (GEN) | 304 |
| 5962-88640022A | A | 03/06/1992 | | (NONE) | 05/27/1997 | | 54FCT161 (GEN) | 304 |
| 5962-8864002EA | A | 03/06/1992 | | (NONE) | 05/27/1997 | | 54FCT161 (GEN) | 304 |
| 5962-8864002FA | A | 03/06/1992 | | (NONE) | 05/27/1997 | | 54FCT161 (GEN) | 304 |
| 5962-88640032A | A | 03/06/1992 | | (NONE) | 05/27/1997 | | 54FCT161A (GEN) | 304 |
| 5962-8864003EA | A | 03/06/1992 | | (NONE) | 05/27/1997 | | 54FCT161A (GEN) | 304 |
| 5962-8864003FA | A | 03/06/1992 | | (NONE) | 05/27/1997 | | 54FCT161A (GEN) | 304 |
| 5962-8864101RA | B | 09/24/2002 | 1 | MINCO | | Y | MTL1060MJ20 | 805 |
| 5962-8864102RA | B | 09/24/2002 | | (NONE) | 03/30/2001 | | LTC1060 (GEN) | 805 |
| 5962-8864201UA | | 03/10/1992 | 1 | PYRAMID | | | P1754-20QLMB | 429 |
| 5962-8864201YA | | 03/10/1992 | 1 | PYRAMID | | | P1754-20QGMB | 429 |
| 5962-8864201ZA | | 03/10/1992 | 1 | PYRAMID | | | P1754-20PGMB | 429 |
| 5962-8864202UA | | 03/10/1992 | 1 | PYRAMID | | | P1754-30QLMB | 429 |
| 5962-8864202YA | | 03/10/1992 | 1 | PYRAMID | | | P1754-30QGMB | 429 |
| 5962-8864202ZA | | 03/10/1992 | 1 | PYRAMID | | | P1754-30PGMB | 429 |
| 5962-8864203UA | | 03/10/1992 | 1 | PYRAMID | | | P1754-40QLMB | 429 |
| 5962-8864203YA | | 03/10/1992 | 1 | PYRAMID | | | P1754-40QGMB | 429 |
| 5962-8864203ZA | | 03/10/1992 | 1 | PYRAMID | | | P1754-40PGMB | 429 |
| 5962-8864204TA | | 03/10/1992 | 1 | PYRAMID | | | P1754-20GMB | 429 |
| 5962-8864204XA | | 03/10/1992 | 1 | PYRAMID | | | P1754-20CMB | 429 |
| 5962-8864205TA | | 03/10/1992 | 1 | PYRAMID | | | P1754-30GMB | 429 |
| 5962-8864205XA | | 03/10/1992 | 1 | PYRAMID | | | P1754-30CMB | 429 |
| 5962-8864206TA | | 03/10/1992 | 1 | PYRAMID | | | P1754-40GMB | 429 |
| 5962-8864206XA | | 03/10/1992 | 1 | PYRAMID | | | P1754-40CMB | 429 |
| 5962-8864301XA | B | 05/10/1994 | | (NONE) | 05/01/1995 | | 49C410 (GEN) | 420 |
| 5962-8864301YA | B | 05/10/1994 | | (NONE) | | | 49C410 (GEN) | 420 |
| 5962-8864301ZA | B | 05/10/1994 | | (NONE) | 05/01/1995 | | 49C410 (GEN) | 420 |
| 5962-8864302XA | B | 05/10/1994 | | (NONE) | 05/01/1995 | | 49C410A (GEN) | 420 |
| 5962-8864302YA | B | 05/10/1994 | | (NONE) | | | 49C410A (GEN) | 420 |
| 5962-8864302ZA | B | 05/10/1994 | | (NONE) | 05/01/1995 | | 49C410A (GEN) | 420 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-8864303XA | B | 05/10/1994 | 1 | SARNOFF | | Y | GEM22703QXA | 420 |
| 5962-8864303XC | B | 05/10/1994 | 1 | SARNOFF | | Y | GEM22703QXC | 420 |
| 5962-8864303YA | B | 05/10/1994 | 1 | SARNOFF | | Y | GEM22703QYA | 420 |
| 5962-8864303YC | B | 05/10/1994 | 1 | SARNOFF | | Y | GEM22703QYC | 420 |
| 5962-8864401UA | E | 10/07/2003 | 2 | UTMC | | Y | UT63M105PB | 590 |
| 5962-8864401UC | E | 10/07/2003 | 2 | UTMC | | Y | UT63M105PB | 590 |
| 5962R8864401VUA | E | 10/07/2003 | 2 | UTMC | | Y | UT63M105PVA | 590 |
| 5962R8864401VUC | E | 10/07/2003 | 2 | UTMC | | Y | UT63M105PVC | 590 |
| 5962-8864402UA | E | 10/07/2003 | 2 | UTMC | | Y | UT63M107PB | 590 |
| 5962-8864402UC | E | 10/07/2003 | 2 | UTMC | | Y | UT63M107PB | 590 |
| 5962-8864403UA | E | 10/07/2003 | | (NONE) | | | UT63M115 (GEN) | 590 |
| 5962-8864404UA | E | 10/07/2003 | | (NONE) | | | UT63M117 (GEN) | 590 |
| 5962-8864405XA | E | 10/07/2003 | 2 | UTMC | | Y | UT63M125BB | 590 |
| 5962-8864405XC | E | 10/07/2003 | 2 | UTMC | | Y | UT63M125BB | 590 |
| 5962R8864405VXA | E | 10/07/2003 | 2 | UTMC | | Y | UT63M125BVA | 590 |
| 5962R8864405VXC | E | 10/07/2003 | 2 | UTMC | | Y | UT63M125BVC | 590 |
| 5962-8864405YA | E | 10/07/2003 | 2 | UTMC | | Y | UT63M125DB | 590 |
| 5962-8864405YC | E | 10/07/2003 | 2 | UTMC | | Y | UT63M125DB | 590 |
| 5962R8864405VYA | E | 10/07/2003 | 2 | UTMC | | Y | UT63M125DVA | 590 |
| 5962R8864405VYC | E | 10/07/2003 | 2 | UTMC | | Y | UT63M125DVC | 590 |
| 5962-8864405ZA | E | 10/07/2003 | 2 | UTMC | | Y | UT63M125CB | 590 |
| 5962-8864405ZC | E | 10/07/2003 | 2 | UTMC | | Y | UT63M125CB | 590 |
| 5962R8864405VZA | E | 10/07/2003 | 2 | UTMC | | Y | UT63M125CVA | 590 |
| 5962R8864405VZC | E | 10/07/2003 | 2 | UTMC | | Y | UT63M125CVC | 590 |
| 5962-8864406XA | E | 10/07/2003 | 2 | UTMC | | Y | UT63M127BB | 590 |
| 5962-8864406XC | E | 10/07/2003 | 2 | UTMC | | Y | UT63M127BB | 590 |
| 5962-8864406YA | E | 10/07/2003 | 2 | UTMC | | Y | UT63M127DB | 590 |
| 5962-8864406YC | E | 10/07/2003 | 2 | UTMC | | Y | UT63M127DB | 590 |
| 5962-8864406ZA | E | 10/07/2003 | 2 | UTMC | | Y | UT63M127CB | 590 |
| 5962-8864406ZC | E | 10/07/2003 | 2 | UTMC | | Y | UT63M127CB | 590 |
| 5962-8864407XA | E | 10/07/2003 | | (NONE) | | | UT63M135 (GEN) | 590 |
| 5962-8864407YA | E | 10/07/2003 | | (NONE) | | | UT63M135 (GEN) | 590 |
| 5962-8864407ZA | E | 10/07/2003 | | (NONE) | | | UT63M135 (GEN) | 590 |
| 5962-8864408XA | E | 10/07/2003 | | (NONE) | | | UT63M137 (GEN) | 590 |
| 5962-8864408YA | E | 10/07/2003 | | (NONE) | | | UT63M137 (GEN) | 590 |
| 5962-8864408ZA | E | 10/07/2003 | | (NONE) | | | UT63M137 (GEN) | 590 |
| 5962-8864501XA | C | 06/21/2001 | 1 | UTMC | | Y | UT1553RTMPGCA | 590 |
| 5962-8864501XC | C | 06/21/2001 | 1 | UTMC | | Y | UT1553RTMPGCC | 590 |
| 5962-8864501YA | C | 06/21/2001 | 1 | UTMC | | Y | UT1553RTMPWCA | 590 |
| 5962-8864501YC | C | 06/21/2001 | 1 | UTMC | | Y | UT1553RTMPWCC | 590 |
| 5962-8864501ZA | C | 06/21/2001 | 1 | UTMC | | Y | UT1553RTMPACA | 590 |
| 5962-8864601MA | F | 02/11/2002 | 1 | INTER. RECT. | | | OM1850SRM | 780 |
| 5962-8864601NA | F | 02/11/2002 | 1 | INTER. RECT. | | | OM1850NMM | 780 |
| 5962-8864601NA | F | 02/11/2002 | 1 | SOLITRON | | | SDP1085NMD | 780 |
| 5962-8864601NB | F | 02/11/2002 | 1 | INTER. RECT. | | | OM1850NMM | 780 |
| 5962-8864601TA | F | 02/11/2002 | 1 | INTER. RECT. | | | OM1850N5M | 780 |
| 5962-8864601UA | F | 02/11/2002 | 1 | INTER. RECT. | | | OM185STM/883 | 780 |
| 5962-8864601UA | F | 02/11/2002 | 1 | MINCO | | Y | MTL1085MP | 780 |
| 5962-8864601UA | F | 02/11/2002 | 1 | SOLITRON | | | SDP1085UMD | 780 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962L8864601UA | F | 02/11/2002 | 1 | INTER. RECT. | | | OMR1850STM/883 | 780 |
| 5962-8864601XA | F | 02/11/2002 | 1 | INTER. RECT. | | | OM1850NKM/883B | 780 |
| 5962-8864601XA | F | 02/11/2002 | 1 | MINCO | | Y | MTL1085MK | 780 |
| 5962-8864601XA | F | 02/11/2002 | 1 | SOLITRON | | | SDP1085XMD | 780 |
| 5962-8864701GA | | 08/30/1988 | | (NONE) | 03/30/2001 | | LT1021BM-7 (GEN) | 785 |
| 5962-8864702GA | | 08/30/1988 | | (NONE) | 03/30/2001 | | LT1021DM-7 (GEN) | 785 |
| 5962-88648012A | E | 03/14/2002 | | (NONE) | 06/01/2001 | | 55ALS194 (GEN) | 569 |
| 5962-8864801EA | E | 03/14/2002 | | (NONE) | 06/01/2001 | | 55ALS194 (GEN) | 569 |
| 5962-8864801FA | E | 03/14/2002 | | (NONE) | 06/01/2001 | | 55ALS194 (GEN) | 569 |
| 5962-88649012A | D | 10/04/2002 | | (NONE) | 06/01/2001 | | 55ALS195 (GEN) | 575 |
| 5962-8864901EA | D | 10/04/2002 | | (NONE) | 06/01/2001 | | 55ALS195 (GEN) | 575 |
| 5962-8864901FA | D | 10/04/2002 | | (NONE) | 06/01/2001 | | 55ALS195 (GEN) | 575 |
| 5962-88650012A | B | 03/25/2004 | 1 | ANALOG (3) | | Y | AD7820UE/883B | 592 |
| 5962-88650012C | B | 03/25/2004 | 1 | MAXIM INTEG. | | | MX7820UE/883B | 592 |
| 5962-8865001RA | B | 03/25/2004 | 1 | ANALOG (3) | | Y | AD7820UQ/883B | 592 |
| 5962-8865001RA | B | 03/25/2004 | 1 | MAXIM INTEG. | | | MX7820UQ/883B | 592 |
| 5962-88650022A | B | 03/25/2004 | 1 | ANALOG (3) | | Y | AD7820TE/883B | 592 |
| 5962-88650022C | B | 03/25/2004 | 1 | MAXIM INTEG. | | | MX7820TE/883B | 592 |
| 5962-8865002RA | B | 03/25/2004 | 1 | ANALOG (3) | | Y | AD7820TQ/883B | 592 |
| 5962-8865002RA | B | 03/25/2004 | 1 | MAXIM INTEG. | | | MX7820TQ/883B | 592 |
| 5962-88651012A | | 05/15/1989 | 3 | NATIONAL | | Y | 54FCT533LMQB | 341 |
| 5962-8865101RA | | 05/15/1989 | 3 | NATIONAL | | Y | 54FCT533DMQB | 341 |
| 5962-8865101SA | | 05/15/1989 | | (NONE) | | | 54FCT533 (GEN) | 341 |
| 5962-88651022A | | 05/15/1989 | | (NONE) | 09/01/1996 | | 54FCT533 (GEN) | 341 |
| 5962-8865102RA | | 05/15/1989 | | (NONE) | 09/01/1996 | | 54FCT533 (GEN) | 341 |
| 5962-8865102SA | | 05/15/1989 | | (NONE) | 09/01/1996 | | 54FCT533 (GEN) | 341 |
| 5962-88652012A | | 06/20/1989 | | (NONE) | | | 54FCT182 (GEN) | 206 |
| 5962-8865201EA | | 06/20/1989 | | (NONE) | | | 54FCT182 (GEN) | 206 |
| 5962-8865201FA | | 06/20/1989 | | (NONE) | | | 54FCT182 (GEN) | 206 |
| 5962-88652022A | | 06/20/1989 | | (NONE) | | | 54FCT182A (GEN) | 206 |
| 5962-8865202EA | | 06/20/1989 | | (NONE) | | | 54FCT182A (GEN) | 206 |
| 5962-8865202FA | | 06/20/1989 | | (NONE) | | | 54FCT182A (GEN) | 206 |
| 5962-88653012A | | 06/01/1989 | | (NONE) | 09/01/1996 | | 54FCT645 (GEN) | 590 |
| 5962-8865301RA | | 06/01/1989 | | (NONE) | 09/01/1996 | | 54FCT645 (GEN) | 590 |
| 5962-8865301SA | | 06/01/1989 | | (NONE) | 09/01/1996 | | 54FCT645 (GEN) | 590 |
| 5962-88653022A | | 06/01/1989 | | (NONE) | 09/01/1996 | | 54FCT645A (GEN) | 590 |
| 5962-8865302RA | | 06/01/1989 | | (NONE) | 09/01/1996 | | 54FCT645A (GEN) | 590 |
| 5962-8865302SA | | 06/01/1989 | | (NONE) | 09/01/1996 | | 54FCT645A (GEN) | 590 |
| 5962-88654012A | | 05/31/1989 | | (NONE) | 09/01/1996 | | 54FCT640 (GEN) | 590 |
| 5962-8865401RA | | 05/31/1989 | | (NONE) | 09/01/1996 | | 54FCT640 (GEN) | 590 |
| 5962-8865401SA | | 05/31/1989 | | (NONE) | 09/01/1996 | | 54FCT640 (GEN) | 590 |
| 5962-88654022A | | 05/31/1989 | | (NONE) | 09/01/1996 | | 54FCT640 (GEN) | 590 |
| 5962-8865402RA | | 05/31/1989 | | (NONE) | 09/01/1996 | | 54FCT640 (GEN) | 590 |
| 5962-8865402SA | | 05/31/1989 | | (NONE) | 09/01/1996 | | 54FCT640 (GEN) | 590 |
| 5962-88655012A | | 05/30/1989 | | (NONE) | 09/01/1996 | | 54FCT534 (GEN) | 159 |
| 5962-8865501RA | | 05/30/1989 | | (NONE) | 09/01/1996 | | 54FCT534 (GEN) | 159 |
| 5962-8865501SA | | 05/30/1989 | | (NONE) | 09/01/1996 | | 54FCT534 (GEN) | 159 |
| 5962-88655022A | | 05/30/1989 | | (NONE) | 09/01/1996 | | 54FCT534A (GEN) | 159 |
| 5962-8865502RA | | 05/30/1989 | | (NONE) | 09/01/1996 | | 54FCT534A (GEN) | 159 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-8865502SA | | 05/30/1989 | | (NONE) | 09/01/1996 | | 54FCT534A (GEN) | 159 |
| 5962-88656013A | A | 01/15/2004 | 2 | IDT | | Y | IDT54FCT823ALB | 229 |
| 5962-8865601KA | A | 01/15/2004 | | (NONE) | 04/29/2002 | | 54FCT823A (GEN) | 229 |
| 5962-8865601LA | A | 01/15/2004 | 2 | IDT | | Y | IDT54FCT823ADB | 229 |
| 5962-88656023A | A | 01/15/2004 | 2 | IDT | | Y | IDT54FCT823BLB | 229 |
| 5962-8865602KA | A | 01/15/2004 | | (NONE) | 04/29/2002 | | 54FCT823B (GEN) | 229 |
| 5962-8865602LA | A | 01/15/2004 | 2 | IDT | | Y | IDT54FCT823BDB | 229 |
| 5962-88657012A | A | 10/14/1992 | | (NONE) | | | 54FCT163 (GEN) | 304 |
| 5962-8865701EA | A | 10/14/1992 | | (NONE) | | | 54FCT163 (GEN) | 304 |
| 5962-8865701FA | A | 10/14/1992 | | (NONE) | | | 54FCT163 (GEN) | 304 |
| 5962-88657022A | A | 10/14/1992 | | (NONE) | | | 54FCT163A (GEN) | 304 |
| 5962-8865702EA | A | 10/14/1992 | | (NONE) | | | 54FCT163A (GEN) | 304 |
| 5962-8865702FA | A | 10/14/1992 | | (NONE) | | | 54FCT163A (GEN) | 304 |
| 5962-88657032A | A | 10/14/1992 | | (NONE) | 05/27/1997 | | 54FCT163 (GEN) | 304 |
| 5962-8865703EA | A | 10/14/1992 | | (NONE) | 05/27/1997 | | 54FCT163 (GEN) | 304 |
| 5962-8865703FA | A | 10/14/1992 | | (NONE) | 05/27/1997 | | 54FCT163 (GEN) | 304 |
| 5962-88657042A | A | 10/14/1992 | | (NONE) | 05/27/1997 | | 54FCT163A (GEN) | 304 |
| 5962-8865704EA | A | 10/14/1992 | | (NONE) | 05/27/1997 | | 54FCT163A (GEN) | 304 |
| 5962-8865704FA | A | 10/14/1992 | | (NONE) | 05/27/1997 | | 54FCT163A (GEN) | 304 |
| 5962-8865801XA | C | 10/29/2002 | | (NONE) | 08/29/2003 | | AD578S (GEN) | 592 |
| 5962-8865802XA | C | 10/29/2002 | | (NONE) | 08/29/2003 | | AD578T (GEN) | 592 |
| 5962-8865803XA | C | 10/29/2002 | | (NONE) | 08/29/2003 | | AD578ZS (GEN) | 592 |
| 5962-8865804XA | C | 10/29/2002 | | (NONE) | 08/29/2003 | | AD578ZT (GEN) | 592 |
| 5962-88659013A | B | 02/25/2002 | 1 | ANALOG (2) | | Y | AD667SE/883B | 591 |
| 5962-8865901XA | B | 02/25/2002 | 1 | ANALOG (2) | | Y | AD667SD/883B | 591 |
| 5962-88661013A | | 02/01/1989 | | (NONE) | 04/27/1998 | | 54FCT863A (GEN) | 590 |
| 5962-8866101KA | | 02/01/1989 | | (NONE) | 04/27/1998 | | 54FCT863A (GEN) | 590 |
| 5962-8866101LA | | 02/01/1989 | | (NONE) | 04/27/1998 | | 54FCT863A (GEN) | 590 |
| 5962-88661023A | | 02/01/1989 | | (NONE) | 04/27/1998 | | 54FCT863B (GEN) | 590 |
| 5962-8866102KA | | 02/01/1989 | | (NONE) | 04/27/1998 | | 54FCT863B (GEN) | 590 |
| 5962-8866102LA | | 02/01/1989 | | (NONE) | 04/27/1998 | | 54FCT863B (GEN) | 590 |
| 5962-8866201MA | C | 04/14/1995 | 1 | PYRAMID | | | P4C1256-100FMB | 623 |
| 5962-8866201MA | C | 04/14/1995 | 2 | QP SEMI | | Y | QP7C199-100KMB | 623 |
| 5962-8866201NA | C | 04/14/1995 | 1 | AUSTIN SEMI. | | Y | MT5C2568C-70883C | 623 |
| 5962-8866201NA | C | 04/14/1995 | 0 | IDT | | Y | IDT71256S100TDB | 623 |
| 5962-8866201NA | C | 04/14/1995 | 1 | PYRAMID | | | P4C1256-100DMB | 623 |
| 5962-8866201NA | C | 04/14/1995 | 2 | QP SEMI | | Y | QP7C199-100DMB | 623 |
| 5962-8866201NC | C | 04/14/1995 | 1 | PYRAMID | | | P4C1256-100CMB | 623 |
| 5962-8866201TA | C | 04/14/1995 | 1 | AUSTIN SEMI. | | Y | MT5C2568F-100883C | 623 |
| 5962-8866201TA | C | 04/14/1995 | 2 | QP SEMI | | Y | QP7C199-100FMB | 623 |
| 5962-8866201UA | C | 04/14/1995 | 1 | AUSTIN SEMI. | | Y | MT5C2568EC-100883C | 623 |
| 5962-8866201UA | C | 04/14/1995 | 1 | PYRAMID | | | P4C1256-100L28MB | 623 |
| 5962-8866201UA | C | 04/14/1995 | 2 | QP SEMI | | Y | QP7C199-100LMB | 623 |
| 5962-8866201XA | C | 04/14/1995 | 1 | AUSTIN SEMI. | | Y | MT5C2568CW-100883C | 623 |
| 5962-8866201XA | C | 04/14/1995 | 1 | IDT | | Y | IDT71256S100DB | 623 |
| 5962-8866201XA | C | 04/14/1995 | 1 | PYRAMID | | | P4C1256-100DWMB | 623 |
| 5962-8866201XA | C | 04/14/1995 | 2 | QP SEMI | | Y | QP7C198-100DMB | 623 |
| 5962-8866201YA | C | 04/14/1995 | 1 | AUSTIN SEMI. | | Y | MT5C2568ECW-100883 | 623 |
| 5962-8866201YA | C | 04/14/1995 | 1 | IDT | | Y | IDT71256S100L32B | 623 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-8866201YA | C | 04/14/1995 | 1 | PYRAMID | | | P4C1256-100L32MB | 623 |
| 5962-8866201YA | C | 04/14/1995 | 2 | QP SEMI | | Y | QP7C198-100LMB | 623 |
| 5962-8866201ZA | C | 04/14/1995 | | (NONE) | | | | 623 |
| 5962-8866202MA | C | 04/14/1995 | 1 | PYRAMID | | | P4C1256-70FMB | 623 |
| 5962-8866202MA | C | 04/14/1995 | 2 | QP SEMI | | Y | QP7C199-70KMB | 623 |
| 5962-8866202NA | C | 04/14/1995 | 1 | AUSTIN SEMI. | | Y | MT5C2568C-70883C | 623 |
| 5962-8866202NA | C | 04/14/1995 | 0 | IDT | | Y | IDT71256S70TDB | 623 |
| 5962-8866202NA | C | 04/14/1995 | 1 | PYRAMID | | | P4C1256-70DMB | 623 |
| 5962-8866202NA | C | 04/14/1995 | 2 | QP SEMI | | Y | QP7C199-70DMB | 623 |
| 5962-8866202NC | C | 04/14/1995 | 1 | PYRAMID | | | P4C1256-70CMB | 623 |
| 5962-8866202TA | C | 04/14/1995 | 1 | AUSTIN SEMI. | | Y | MT5C2568F-70883C | 623 |
| 5962-8866202TA | C | 04/14/1995 | 2 | QP SEMI | | Y | QP7C199-70FMB | 623 |
| 5962-8866202UA | C | 04/14/1995 | 1 | AUSTIN SEMI. | | Y | MT5C2568EC-70883C | 623 |
| 5962-8866202UA | C | 04/14/1995 | 1 | PYRAMID | | | P4C1256-70L28MB | 623 |
| 5962-8866202UA | C | 04/14/1995 | 2 | QP SEMI | | Y | QP7C199-70LMB | 623 |
| 5962-8866202XA | C | 04/14/1995 | 1 | AUSTIN SEMI. | | Y | MT5C2568CW-70883C | 623 |
| 5962-8866202XA | C | 04/14/1995 | 1 | IDT | | Y | IDT71256S70DB | 623 |
| 5962-8866202XA | C | 04/14/1995 | 1 | PYRAMID | | | P4C1256-70DWMB | 623 |
| 5962-8866202XA | C | 04/14/1995 | 2 | QP SEMI | | Y | QP7C198-70DMB | 623 |
| 5962-8866202YA | C | 04/14/1995 | 1 | AUSTIN SEMI. | | Y | MT5C2568ECW-70883 | 623 |
| 5962-8866202YA | C | 04/14/1995 | 1 | IDT | | Y | IDT71256S70L32B | 623 |
| 5962-8866202YA | C | 04/14/1995 | 1 | PYRAMID | | | P4C1256-70L32MB | 623 |
| 5962-8866202YA | C | 04/14/1995 | 2 | QP SEMI | | Y | QP7C198-70LMB | 623 |
| 5962-8866202ZA | C | 04/14/1995 | | (NONE) | | | | 623 |
| 5962-8866203MA | C | 04/14/1995 | 1 | PYRAMID | | | P4C1256-55FMB | 623 |
| 5962-8866203MA | C | 04/14/1995 | 2 | QP SEMI | | Y | QP7C199-55KMB | 623 |
| 5962-8866203NA | C | 04/14/1995 | 1 | AUSTIN SEMI. | | Y | MT5C2568C-55883C | 623 |
| 5962-8866203NA | C | 04/14/1995 | 0 | IDT | | Y | IDT71256S55TDB | 623 |
| 5962-8866203NA | C | 04/14/1995 | 1 | PYRAMID | | | P4C1256-55DMB | 623 |
| 5962-8866203NA | C | 04/14/1995 | 2 | QP SEMI | | Y | QP7C199-55DMB | 623 |
| 5962-8866203NC | C | 04/14/1995 | 1 | PYRAMID | | | P4C1256-55CMB | 623 |
| 5962-8866203TA | C | 04/14/1995 | 1 | AUSTIN SEMI. | | Y | MT5C2568F-55883C | 623 |
| 5962-8866203TA | C | 04/14/1995 | 2 | QP SEMI | | Y | QP7C199-55FMB | 623 |
| 5962-8866203UA | C | 04/14/1995 | 1 | AUSTIN SEMI. | | Y | MT5C2568EC-55883C | 623 |
| 5962-8866203UA | C | 04/14/1995 | 1 | PYRAMID | | | P4C1256-55L28MB | 623 |
| 5962-8866203UA | C | 04/14/1995 | 2 | QP SEMI | | Y | QP7C199-55LMB | 623 |
| 5962-8866203XA | C | 04/14/1995 | 1 | AUSTIN SEMI. | | Y | MT5C2568CW-55883C | 623 |
| 5962-8866203XA | C | 04/14/1995 | 1 | IDT | | Y | IDT71256S55DB | 623 |
| 5962-8866203XA | C | 04/14/1995 | 1 | PYRAMID | | | P4C1256-55DWMB | 623 |
| 5962-8866203XA | C | 04/14/1995 | 2 | QP SEMI | | Y | QP7C198-55DMB | 623 |
| 5962-8866203YA | C | 04/14/1995 | 1 | AUSTIN SEMI. | | Y | MT5C2568ECW-55883 | 623 |
| 5962-8866203YA | C | 04/14/1995 | 1 | IDT | | Y | IDT71256S55L32B | 623 |
| 5962-8866203YA | C | 04/14/1995 | 1 | PYRAMID | | | P4C1256-55L32MB | 623 |
| 5962-8866203YA | C | 04/14/1995 | 2 | QP SEMI | | Y | QP7C198-55LMB | 623 |
| 5962-8866203ZA | C | 04/14/1995 | | (NONE) | | | | 623 |
| 5962-8866204MA | C | 04/14/1995 | 1 | PYRAMID | | | P4C1256-45FMB | 623 |
| 5962-8866204MA | C | 04/14/1995 | 2 | QP SEMI | | Y | QP7C199-45KMB | 623 |
| 5962-8866204NA | C | 04/14/1995 | 1 | AUSTIN SEMI. | | Y | MT5C2568C-45883C | 623 |
| 5962-8866204NA | C | 04/14/1995 | 0 | IDT | | Y | IDT71256S45TDB | 623 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-8866204NA | C | 04/14/1995 | 1 | PYRAMID | | | P4C1256-45DMB | 623 |
| 5962-8866204NA | C | 04/14/1995 | 2 | QP SEMI | | Y | QP7C199-45DMB | 623 |
| 5962-8866204NC | C | 04/14/1995 | 1 | PYRAMID | | | P4C1256-45CMB | 623 |
| 5962-8866204TA | C | 04/14/1995 | 1 | AUSTIN SEMI. | | Y | MT5C2568F-45883C | 623 |
| 5962-8866204TA | C | 04/14/1995 | 2 | QP SEMI | | Y | QP7C199-45FMB | 623 |
| 5962-8866204UA | C | 04/14/1995 | 1 | AUSTIN SEMI. | | Y | MT5C2568EC-45883C | 623 |
| 5962-8866204UA | C | 04/14/1995 | 1 | PYRAMID | | | P4C1256-45L28MB | 623 |
| 5962-8866204UA | C | 04/14/1995 | 2 | QP SEMI | | Y | QP7C199-45LMB | 623 |
| 5962-8866204XA | C | 04/14/1995 | 1 | AUSTIN SEMI. | | Y | MT5C2568CW-45883C | 623 |
| 5962-8866204XA | C | 04/14/1995 | 1 | IDT | | Y | IDT71256S45DB | 623 |
| 5962-8866204XA | C | 04/14/1995 | 1 | PYRAMID | | | P4C1256-45DWMB | 623 |
| 5962-8866204XA | C | 04/14/1995 | 2 | QP SEMI | | Y | QP7C198-45DMB | 623 |
| 5962-8866204YA | C | 04/14/1995 | 1 | AUSTIN SEMI. | | Y | MT5C2568ECW-45883 | 623 |
| 5962-8866204YA | C | 04/14/1995 | 1 | IDT | | Y | IDT71256S45L32B | 623 |
| 5962-8866204YA | C | 04/14/1995 | 1 | PYRAMID | | | P4C1256-45L32MB | 623 |
| 5962-8866204YA | C | 04/14/1995 | 2 | QP SEMI | | Y | QP7C198-45LMB | 623 |
| 5962-8866204ZA | C | 04/14/1995 | | (NONE) | | | | 623 |
| 5962-8866205MA | C | 04/14/1995 | 1 | PYRAMID | | | P4C1256-35FMB | 623 |
| 5962-8866205MA | C | 04/14/1995 | 2 | QP SEMI | | Y | QP7C199-35KMB | 623 |
| 5962-8866205NA | C | 04/14/1995 | 1 | AUSTIN SEMI. | | Y | MT5C2568C-35883C | 623 |
| 5962-8866205NA | C | 04/14/1995 | 0 | IDT | | Y | IDT71256S35TDB | 623 |
| 5962-8866205NA | C | 04/14/1995 | 1 | PYRAMID | | | P4C1256-35DMB | 623 |
| 5962-8866205NA | C | 04/14/1995 | 2 | QP SEMI | | Y | QP7C199-35DMB | 623 |
| 5962-8866205NC | C | 04/14/1995 | 1 | PYRAMID | | | P4C1256-35CMB | 623 |
| 5962-8866205TA | C | 04/14/1995 | 1 | AUSTIN SEMI. | | Y | MT5C2568F-35883C | 623 |
| 5962-8866205TA | C | 04/14/1995 | 2 | QP SEMI | | Y | QP7C199-35FMB | 623 |
| 5962-8866205UA | C | 04/14/1995 | 1 | AUSTIN SEMI. | | Y | MT5C2568EC-35883C | 623 |
| 5962-8866205UA | C | 04/14/1995 | 1 | PYRAMID | | | P4C1256-35L28MB | 623 |
| 5962-8866205UA | C | 04/14/1995 | 2 | QP SEMI | | Y | QP7C199-35LMB | 623 |
| 5962-8866205XA | C | 04/14/1995 | 1 | AUSTIN SEMI. | | Y | MT5C2568CW-35883C | 623 |
| 5962-8866205XA | C | 04/14/1995 | 0 | IDT | | Y | IDT71256S35DB | 623 |
| 5962-8866205XA | C | 04/14/1995 | 1 | PYRAMID | | | P4C1256-35DWMB | 623 |
| 5962-8866205XA | C | 04/14/1995 | 2 | QP SEMI | | Y | QP7C198-35DMB | 623 |
| 5962-8866205YA | C | 04/14/1995 | 1 | AUSTIN SEMI. | | Y | MT5C2568ECW-35883 | 623 |
| 5962-8866205YA | C | 04/14/1995 | 0 | IDT | | Y | IDT71256S35L32B | 623 |
| 5962-8866205YA | C | 04/14/1995 | 1 | PYRAMID | | | P4C1256-35L32MB | 623 |
| 5962-8866205YA | C | 04/14/1995 | 2 | QP SEMI | | Y | QP7C198-35LMB | 623 |
| 5962-8866206MA | C | 04/14/1995 | 1 | PYRAMID | | | P4C1256-25FMB | 623 |
| 5962-8866206MA | C | 04/14/1995 | 2 | QP SEMI | | Y | QP7C199-25KMB | 623 |
| 5962-8866206NA | C | 04/14/1995 | 1 | AUSTIN SEMI. | | Y | MT5C2568C-25883C | 623 |
| 5962-8866206NA | C | 04/14/1995 | 0 | IDT | | Y | IDT71256S25TDB | 623 |
| 5962-8866206NA | C | 04/14/1995 | 1 | PYRAMID | | | P4C1256-25DMB | 623 |
| 5962-8866206NA | C | 04/14/1995 | 2 | QP SEMI | | Y | QP7C199-25DMB | 623 |
| 5962-8866206NC | C | 04/14/1995 | 1 | PYRAMID | | | P4C1256-25CMB | 623 |
| 5962-8866206TA | C | 04/14/1995 | 1 | AUSTIN SEMI. | | Y | MT5C2568F-25883C | 623 |
| 5962-8866206TA | C | 04/14/1995 | 2 | QP SEMI | | Y | QP7C199-25FMB | 623 |
| 5962-8866206UA | C | 04/14/1995 | 1 | AUSTIN SEMI. | | Y | MT5C2568EC-25883C | 623 |
| 5962-8866206UA | C | 04/14/1995 | 1 | PYRAMID | | | P4C1256-25L28MB | 623 |
| 5962-8866206UA | C | 04/14/1995 | 2 | QP SEMI | | Y | QP7C199-25LMB | 623 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-8866206XA | C | 04/14/1995 | 1 | AUSTIN SEMI. | | Y | MT5C2568CW-25883C | 623 |
| 5962-8866206XA | C | 04/14/1995 | 0 | IDT | | Y | IDT71256S25DB | 623 |
| 5962-8866206XA | C | 04/14/1995 | 1 | PYRAMID | | | P4C1256-25DWMB | 623 |
| 5962-8866206XA | C | 04/14/1995 | 2 | QP SEMI | | Y | QP7C198-25DMB | 623 |
| 5962-8866206YA | C | 04/14/1995 | 1 | AUSTIN SEMI. | | Y | MT5C2568ECW-25883 | 623 |
| 5962-8866206YA | C | 04/14/1995 | 0 | IDT | | Y | IDT71256S25L32B | 623 |
| 5962-8866206YA | C | 04/14/1995 | 1 | PYRAMID | | | P4C1256-25L32MB | 623 |
| 5962-8866206YA | C | 04/14/1995 | 2 | QP SEMI | | Y | QP7C198-25LMB | 623 |
| 5962-8866207MA | C | 04/14/1995 | 1 | PYRAMID | | | P4C1256-20FMB | 623 |
| 5962-8866207MA | C | 04/14/1995 | 2 | QP SEMI | | Y | QP7C199-20KMB | 623 |
| 5962-8866207NA | C | 04/14/1995 | 1 | AUSTIN SEMI. | | Y | MT5C2568C-20883C | 623 |
| 5962-8866207NA | C | 04/14/1995 | 1 | PYRAMID | | | P4C1256-20DMB | 623 |
| 5962-8866207NA | C | 04/14/1995 | 2 | QP SEMI | | Y | QP7C199-20DMB | 623 |
| 5962-8866207NC | C | 04/14/1995 | 1 | PYRAMID | | | P4C1256-20CMB | 623 |
| 5962-8866207TA | C | 04/14/1995 | 1 | AUSTIN SEMI. | | Y | MT5C2568F-20883C | 623 |
| 5962-8866207TA | C | 04/14/1995 | 2 | QP SEMI | | Y | QP7C199-20FMB | 623 |
| 5962-8866207UA | C | 04/14/1995 | 1 | AUSTIN SEMI. | | Y | MT5C2568EC-20883C | 623 |
| 5962-8866207UA | C | 04/14/1995 | 1 | PYRAMID | | | P4C1256-20L28MB | 623 |
| 5962-8866207UA | C | 04/14/1995 | 2 | QP SEMI | | Y | QP7C199-20LMB | 623 |
| 5962-8866207XA | C | 04/14/1995 | 1 | AUSTIN SEMI. | | Y | MT5C2568CW-20883C | 623 |
| 5962-8866207XA | C | 04/14/1995 | 1 | IDT | | Y | IDT71256S20DB | 623 |
| 5962-8866207XA | C | 04/14/1995 | 1 | PYRAMID | | | P4C1256-20DWMB | 623 |
| 5962-8866207XA | C | 04/14/1995 | 2 | QP SEMI | | Y | QP7C198-20DMB | 623 |
| 5962-8866207YA | C | 04/14/1995 | 1 | AUSTIN SEMI. | | Y | MT5C2568ECW-20883 | 623 |
| 5962-8866207YA | C | 04/14/1995 | 1 | IDT | | Y | IDT71256S20L32B | 623 |
| 5962-8866207YA | C | 04/14/1995 | 1 | PYRAMID | | | P4C1256-20L32MB | 623 |
| 5962-8866207YA | C | 04/14/1995 | 2 | QP SEMI | | Y | QP7C198-20LMB | 623 |
| 5962-8866208MA | C | 04/14/1995 | 1 | PYRAMID | | | P4C1256-15FMB | 623 |
| 5962-8866208MA | C | 04/14/1995 | 2 | QP SEMI | | Y | QP7C199-15KMB | 623 |
| 5962-8866208NA | C | 04/14/1995 | 1 | AUSTIN SEMI. | | Y | MT5C2568C-15883C | 623 |
| 5962-8866208NA | C | 04/14/1995 | 1 | PYRAMID | | | P4C1256-15DMB | 623 |
| 5962-8866208NA | C | 04/14/1995 | 2 | QP SEMI | | Y | QP7C199-15DMB | 623 |
| 5962-8866208TA | C | 04/14/1995 | 1 | AUSTIN SEMI. | | Y | MT5C2568F-15883C | 623 |
| 5962-8866208TA | C | 04/14/1995 | 2 | QP SEMI | | Y | QP7C199-15FMB | 623 |
| 5962-8866208UA | C | 04/14/1995 | 1 | AUSTIN SEMI. | | Y | MT5C2568EC-15883C | 623 |
| 5962-8866208UA | C | 04/14/1995 | 1 | PYRAMID | | | P4C1256-15L28MB | 623 |
| 5962-8866208UA | C | 04/14/1995 | 2 | QP SEMI | | Y | QP7C199-15LMB | 623 |
| 5962-8866208XA | C | 04/14/1995 | 1 | AUSTIN SEMI. | | Y | MT5C2568CW-15883C | 623 |
| 5962-8866208XA | C | 04/14/1995 | 1 | PYRAMID | | | P4C1256-15DWMB | 623 |
| 5962-8866208XA | C | 04/14/1995 | 2 | QP SEMI | | Y | QP7C198-15DMB | 623 |
| 5962-8866208YA | C | 04/14/1995 | 1 | AUSTIN SEMI. | | Y | MT5C2568ECW-15883 | 623 |
| 5962-8866208YA | C | 04/14/1995 | 1 | PYRAMID | | | P4C1256-15L32MB | 623 |
| 5962-8866208YA | C | 04/14/1995 | 2 | QP SEMI | | Y | QP7C198-15LMB | 623 |
| 5962-8866209NA | C | 04/14/1995 | 1 | AUSTIN SEMI. | | Y | MT5C2568C-12883C | 623 |
| 5962-8866209TA | C | 04/14/1995 | 1 | AUSTIN SEMI. | | Y | MT5C2568F-12883C | 623 |
| 5962-8866209UA | C | 04/14/1995 | 1 | AUSTIN SEMI. | | Y | MT5C2568EC-12883C | 623 |
| 5962-8866209XA | C | 04/14/1995 | 1 | AUSTIN SEMI. | | Y | MT5C2568CW-12883C | 623 |
| 5962-8866209YA | C | 04/14/1995 | 1 | AUSTIN SEMI. | | Y | MT5C2568ECW-12883 | 623 |
| 5962-88663013A | A | 04/25/2002 | 1 | ANALOG (3) | | Y | AD7228TE/883B | 591 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-8866301LA | A | 04/25/2002 | | (NONE) | | | AD7228T (GEN) | 591 |
| 5962-88663023A | A | 04/25/2002 | 1 | ANALOG (3) | | Y | AD7228UE/883B | 591 |
| 5962-8866302LA | A | 04/25/2002 | 1 | ANALOG (3) | | Y | AD7228UQ/883B | 591 |
| 5962-8866401EA | A | 06/25/2002 | 0 | MICROSEMI | | Y | SG3081J/883B | 790 |
| 5962-8866501XA | D | 12/09/1996 | | (NONE) | | | | 618 |
| 5962-8866501YA | D | 12/09/1996 | | (NONE) | | | | 618 |
| 5962-8866501ZA | D | 12/09/1996 | | (NONE) | | | | 618 |
| 5962-8866502XA | D | 12/09/1996 | | (NONE) | | | | 618 |
| 5962-8866502YA | D | 12/09/1996 | | (NONE) | | | | 618 |
| 5962-8866502ZA | D | 12/09/1996 | | (NONE) | | | | 618 |
| 5962-8866503XA | D | 12/09/1996 | | (NONE) | | | | 618 |
| 5962-8866503YA | D | 12/09/1996 | | (NONE) | | | | 618 |
| 5962-8866503ZA | D | 12/09/1996 | | (NONE) | | | | 618 |
| 5962-8866504XA | D | 12/09/1996 | | (NONE) | | | | 618 |
| 5962-8866504YA | D | 12/09/1996 | | (NONE) | | | | 618 |
| 5962-8866504ZA | D | 12/09/1996 | | (NONE) | | | | 618 |
| 5962-8866505XA | D | 12/09/1996 | | (NONE) | | | | 618 |
| 5962-8866505YA | D | 12/09/1996 | | (NONE) | | | | 618 |
| 5962-8866505ZA | D | 12/09/1996 | | (NONE) | | | | 618 |
| 5962-8866506XA | D | 12/09/1996 | | (NONE) | | | | 618 |
| 5962-8866506YA | D | 12/09/1996 | | (NONE) | | | | 618 |
| 5962-8866506ZA | D | 12/09/1996 | | (NONE) | | | | 618 |
| 5962-8866507UA | D | 12/09/1996 | 3 | IDT | | Y | IDT7133LA90FB | 618 |
| 5962-8866507ZA | D | 12/09/1996 | 2 | IDT | | Y | IDT7133LA90GB | 618 |
| 5962-8866508UA | D | 12/09/1996 | 3 | IDT | | Y | IDT7143LA90FB | 618 |
| 5962-8866508ZA | D | 12/09/1996 | 2 | IDT | | Y | IDT7143LA90GB | 618 |
| 5962-8866509UA | D | 12/09/1996 | 3 | IDT | | Y | IDT7133LA70FB | 618 |
| 5962-8866509ZA | D | 12/09/1996 | 2 | IDT | | Y | IDT7133LA70GB | 618 |
| 5962-8866510UA | D | 12/09/1996 | 3 | IDT | | Y | IDT7143LA70FB | 618 |
| 5962-8866510ZA | D | 12/09/1996 | 2 | IDT | | Y | IDT7143LA70GB | 618 |
| 5962-8866511UA | D | 12/09/1996 | 3 | IDT | | Y | IDT7133LA55FB | 618 |
| 5962-8866511ZA | D | 12/09/1996 | 2 | IDT | | Y | IDT7133LA55GB | 618 |
| 5962-8866512UA | D | 12/09/1996 | 3 | IDT | | Y | IDT7143LA55FB | 618 |
| 5962-8866512ZA | D | 12/09/1996 | 2 | IDT | | Y | IDT7143LA55GB | 618 |
| 5962-8866513UA | D | 12/09/1996 | 3 | IDT | | Y | IDT7133LA45FB | 618 |
| 5962-8866513ZA | D | 12/09/1996 | 2 | IDT | | Y | IDT7133LA45GB | 618 |
| 5962-8866514UA | D | 12/09/1996 | 3 | IDT | | Y | IDT7143LA45FB | 618 |
| 5962-8866514ZA | D | 12/09/1996 | 2 | IDT | | Y | IDT7143LA45GB | 618 |
| 5962-8866515UA | D | 12/09/1996 | 3 | IDT | | Y | IDT7133LA35FB | 618 |
| 5962-8866515ZA | D | 12/09/1996 | 2 | IDT | | Y | IDT7133LA35GB | 618 |
| 5962-8866516UA | D | 12/09/1996 | 3 | IDT | | Y | IDT7143LA35FB | 618 |
| 5962-8866516ZA | D | 12/09/1996 | 2 | IDT | | Y | IDT7143LA35GB | 618 |
| 5962-8866601QA | | 06/10/1988 | | (NONE) | | | 68155 (GEN) | 421 |
| 5962-88668012A | C | 04/18/2000 | 2 | TI | | Y | SNJ54ALS534AFK | 159 |
| 5962-8866801RA | C | 04/18/2000 | 2 | TI | | Y | SNJ54ALS534AJ | 159 |
| 5962-8866801SA | C | 04/18/2000 | 2 | TI | | Y | SNJ54ALS534AW | 159 |
| 5962-8866901UA | D | 02/25/1997 | 3 | QP SEMI | | Y | CY7C429-80KMB | 670 |
| 5962-8866901XA | D | 02/25/1997 | 3 | QP SEMI | | Y | CY7C428-80DMB | 670 |
| 5962-8866901YA | D | 02/25/1997 | 3 | QP SEMI | | Y | CY7C429-80DMB | 670 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-8866901ZA | D | 02/25/1997 | 3 | QP SEMI | | Y | CY7C429-80LMB | 670 |
| 5962-8866902UA | D | 02/25/1997 | 3 | QP SEMI | | Y | CY7C429-65KMB | 670 |
| 5962-8866902XA | D | 02/25/1997 | 3 | QP SEMI | | Y | CY7C428-65DMB | 670 |
| 5962-8866902YA | D | 02/25/1997 | 3 | QP SEMI | | Y | CY7C429-65DMB | 670 |
| 5962-8866902ZA | D | 02/25/1997 | 3 | QP SEMI | | Y | CY7C429-65LMB | 670 |
| 5962-8866903UA | D | 02/25/1997 | 3 | QP SEMI | | Y | CY7C429-50KMB | 670 |
| 5962-8866903XA | D | 02/25/1997 | 3 | QP SEMI | | Y | CY7C428-50DMB | 670 |
| 5962-8866903YA | D | 02/25/1997 | 3 | QP SEMI | | Y | CY7C429-50DMB | 670 |
| 5962-8866903ZA | D | 02/25/1997 | 3 | QP SEMI | | Y | CY7C429-50LMB | 670 |
| 5962-8866904UA | D | 02/25/1997 | 3 | QP SEMI | | Y | CY7C429-40KMB | 670 |
| 5962-8866904XA | D | 02/25/1997 | 3 | QP SEMI | | Y | CY7C428-40DMB | 670 |
| 5962-8866904YA | D | 02/25/1997 | 3 | QP SEMI | | Y | CY7C429-40DMB | 670 |
| 5962-8866904ZA | D | 02/25/1997 | 3 | QP SEMI | | Y | CY7C429-40LMB | 670 |
| 5962-8866905UA | D | 02/25/1997 | 3 | QP SEMI | | Y | CY7C429-30KMB | 670 |
| 5962-8866905XA | D | 02/25/1997 | 3 | QP SEMI | | Y | CY7C428-30DMB | 670 |
| 5962-8866905YA | D | 02/25/1997 | 2 | IDT | | Y | IDT7203S30TDB | 670 |
| 5962-8866905YA | D | 02/25/1997 | 3 | QP SEMI | | Y | CY7C429-30DMB | 670 |
| 5962-8866905ZA | D | 02/25/1997 | 0 | IDT | | Y | IDT7203S30LB | 670 |
| 5962-8866905ZA | D | 02/25/1997 | 3 | QP SEMI | | Y | CY7C429-30LMB | 670 |
| 5962-8866906UA | D | 02/25/1997 | 3 | QP SEMI | | Y | CY7C429-20KMB | 670 |
| 5962-8866906XA | D | 02/25/1997 | 3 | QP SEMI | | Y | CY7C428-20DMB | 670 |
| 5962-8866906YA | D | 02/25/1997 | 2 | IDT | | Y | IDT7203S20TDB | 670 |
| 5962-8866906YA | D | 02/25/1997 | 3 | QP SEMI | | Y | CY7C429-20DMB | 670 |
| 5962-8866906ZA | D | 02/25/1997 | 0 | IDT | | Y | IDT7203S20LB | 670 |
| 5962-8866906ZA | D | 02/25/1997 | 3 | QP SEMI | | Y | CY7C429-20LMB | 670 |
| 5962-8866907UA | D | 02/25/1997 | 3 | QP SEMI | | Y | CY7C429-25KMB | 670 |
| 5962-8866907XA | D | 02/25/1997 | 3 | QP SEMI | | Y | CY7C428-25DMB | 670 |
| 5962-8866907YA | D | 02/25/1997 | 3 | QP SEMI | | Y | CY7C429-25DMB | 670 |
| 5962-8866907ZA | D | 02/25/1997 | 3 | QP SEMI | | Y | CY7C429-25LMB | 670 |
| 5962-88670013A | C | 11/02/2001 | 1 | CYPRESS | 05/03/2004 | Y | PALC22V10-25LMB | 431 |
| 5962-88670013A | C | 11/02/2001 | 2 | QP SEMI | | Y | PALC22V10-25LMB | 431 |
| 5962-8867001KA | C | 11/02/2001 | 2 | QP SEMI | | Y | PALC22V10-25KMB | 431 |
| 5962-8867001LA | C | 11/02/2001 | 1 | CYPRESS | 05/03/2004 | Y | PALC22V10-25DMB | 431 |
| 5962-8867001LA | C | 11/02/2001 | 2 | QP SEMI | | Y | PALC22V10-25DMB | 431 |
| 5962-88670023A | C | 11/02/2001 | 2 | QP SEMI | | Y | PALC22V10-30LMB | 431 |
| 5962-8867002KA | C | 11/02/2001 | 2 | QP SEMI | | Y | PALC22V10-30KMB | 431 |
| 5962-8867002LA | C | 11/02/2001 | 1 | CYPRESS | 05/03/2004 | Y | PALC22V10-30DMB | 431 |
| 5962-8867002LA | C | 11/02/2001 | 2 | QP SEMI | | Y | PALC22V10-30DMB | 431 |
| 5962-88670033A | C | 11/02/2001 | 2 | QP SEMI | | Y | PALC22V10-40LMB | 431 |
| 5962-8867003KA | C | 11/02/2001 | 2 | QP SEMI | | Y | PALC22V10-40KMB | 431 |
| 5962-8867003LA | C | 11/02/2001 | 2 | QP SEMI | | Y | PALC22V10-40DMB | 431 |
| 5962-88670043A | C | 11/02/2001 | 2 | CYPRESS | 05/03/2004 | Y | PALC22V10B-20LMB | 431 |
| 5962-88670043A | C | 11/02/2001 | 2 | QP SEMI | | Y | PALC22V10B-20LMB | 431 |
| 5962-8867004KA | C | 11/02/2001 | 2 | CYPRESS | 05/03/2004 | Y | PALC22V10B-20KMB | 431 |
| 5962-8867004KA | C | 11/02/2001 | 2 | QP SEMI | | Y | PALC22V10B-20KMB | 431 |
| 5962-8867004LA | C | 11/02/2001 | 2 | CYPRESS | 05/03/2004 | Y | PALC22V10B-20DMB | 431 |
| 5962-8867004LA | C | 11/02/2001 | 2 | QP SEMI | | Y | PALC22V10B-20DMB | 431 |
| 5962-88670053A | C | 11/02/2001 | 2 | CYPRESS | 05/03/2004 | Y | PALC22V10B-15LMB | 431 |
| 5962-88670053A | C | 11/02/2001 | 2 | QP SEMI | | Y | PALC22V10B-15LMB | 431 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-8867005KA | C | 11/02/2001 | 2 | CYPRESS | 05/03/2004 | Y | PALC22V10B-15KMB | 431 |
| 5962-8867005KA | C | 11/02/2001 | 2 | QP SEMI | | Y | PALC22V10B-15KMB | 431 |
| 5962-8867005LA | C | 11/02/2001 | 2 | CYPRESS | 05/03/2004 | Y | PALC22V10B-15DMB | 431 |
| 5962-8867005LA | C | 11/02/2001 | 2 | QP SEMI | | Y | PALC22V10B-15DMB | 431 |
| 5962-8867101EA | | 07/19/1988 | 1 | TI | | Y | CD54HCT191F3A | 304 |
| 5962-8867201EA | | 07/25/1988 | 1 | TI | | Y | CD54HCT85F3A | 209 |
| 5962-88673013A | C | 09/05/1997 | 2 | TI | | Y | SNJ54ALS652FK | 590 |
| 5962-8867301KA | C | 09/05/1997 | 2 | TI | | Y | SNJ54ALS652W | 590 |
| 5962-8867301LA | C | 09/05/1997 | 2 | TI | | Y | SNJ54ALS652JT | 590 |
| 5962-88674013A | | 09/15/1988 | | (NONE) | 04/27/1998 | | 54FCT825A (GEN) | 421 |
| 5962-8867401KA | | 09/15/1988 | | (NONE) | 04/27/1998 | | 54FCT825A (GEN) | 421 |
| 5962-8867401LA | | 09/15/1988 | | (NONE) | 04/27/1998 | | 54FCT825A (GEN) | 421 |
| 5962-88674023A | | 09/15/1988 | | (NONE) | 04/27/1998 | | 54FCT825B (GEN) | 421 |
| 5962-8867402KA | | 09/15/1988 | | (NONE) | 04/27/1998 | | 54FCT825B (GEN) | 421 |
| 5962-8867402LA | | 09/15/1988 | | (NONE) | 04/27/1998 | | 54FCT825B (GEN) | 421 |
| 5962-88675013A | | 09/06/1988 | | (NONE) | | | 54FCT845A (GEN) | 599 |
| 5962-8867501KA | | 09/06/1988 | | (NONE) | | | 54FCT845A (GEN) | 599 |
| 5962-8867501LA | | 09/06/1988 | | (NONE) | | | 54FCT845A (GEN) | 599 |
| 5962-88675023A | | 09/06/1988 | | (NONE) | | | 54FCT845B (GEN) | 599 |
| 5962-8867502KA | | 09/06/1988 | | (NONE) | | | 54FCT845B (GEN) | 599 |
| 5962-8867502LA | | 09/06/1988 | | (NONE) | | | 54FCT845B (GEN) | 599 |
| 5962-8867601JA | | 02/13/1989 | | (NONE) | | | | 658 |
| 5962-8867601LA | | 02/13/1989 | | (NONE) | | | | 658 |
| 5962-8867601XA | | 02/13/1989 | | (NONE) | | | | 658 |
| 5962-8867602JA | | 02/13/1989 | | (NONE) | | | | 658 |
| 5962-8867602LA | | 02/13/1989 | | (NONE) | | | | 658 |
| 5962-8867602XA | | 02/13/1989 | | (NONE) | | | | 658 |
| 5962-8867603JA | | 02/13/1989 | | (NONE) | | | | 658 |
| 5962-8867603LA | | 02/13/1989 | | (NONE) | | | | 658 |
| 5962-8867603XA | | 02/13/1989 | | (NONE) | | | | 658 |
| 5962-8867701XA | B | 09/08/2004 | 1 | ROCHESTER | | Y | 2903A/BXA | 401 |
| 5962-8867701YA | B | 09/08/2004 | 1 | ROCHESTER | | Y | 2903A/BYA | 401 |
| 5962-8867701YC | B | 09/08/2004 | 1 | ROCHESTER | | Y | 2903A/BYC | 401 |
| 5962-8867701ZA | B | 09/08/2004 | 1 | ROCHESTER | | Y | 2903A/BZA | 401 |
| 5962-8867701ZC | B | 09/08/2004 | 1 | ROCHESTER | | Y | 2903A/BZC | 401 |
| 5962-8867801RA | A | 12/13/1989 | 1 | QP SEMI | | Y | PALC16L8-40WMB | 431 |
| 5962-8867801SA | A | 12/13/1989 | 1 | QP SEMI | | Y | PALC16L8-40TMB | 431 |
| 5962-8867801XA | A | 12/13/1989 | 1 | QP SEMI | | Y | PALC16L8-40QMB | 431 |
| 5962-8867802RA | A | 12/13/1989 | 1 | QP SEMI | | Y | PALC16R8-40WMB | 431 |
| 5962-8867802SA | A | 12/13/1989 | 1 | QP SEMI | | Y | PALC16R8-40TMB | 431 |
| 5962-8867802XA | A | 12/13/1989 | 1 | QP SEMI | | Y | PALC16R8-40QMB | 431 |
| 5962-8867803RA | A | 12/13/1989 | 1 | QP SEMI | | Y | PALC16R6-40WMB | 431 |
| 5962-8867803SA | A | 12/13/1989 | 1 | QP SEMI | | Y | PALC16R6-40TMB | 431 |
| 5962-8867803XA | A | 12/13/1989 | 1 | QP SEMI | | Y | PALC16R6-40QMB | 431 |
| 5962-8867804RA | A | 12/13/1989 | | (NONE) | 05/31/1998 | | C16R4-40 (GEN) | 431 |
| 5962-8867804SA | A | 12/13/1989 | | (NONE) | | | C16R4-40 (GEN) | 431 |
| 5962-8867804XA | A | 12/13/1989 | | (NONE) | | | C16R4-40 (GEN) | 431 |
| 5962-8867805RA | A | 12/13/1989 | 1 | QP SEMI | | Y | PALC16L8-30WMB | 431 |
| 5962-8867805SA | A | 12/13/1989 | 1 | QP SEMI | | Y | PALC16L8-30TMB | 431 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-8867805XA | A | 12/13/1989 | 1 | QP SEMI | | Y | PALC16L8-30QMB | 431 |
| 5962-8867806RA | A | 12/13/1989 | 1 | QP SEMI | | Y | PALC16R8-30WMB | 431 |
| 5962-8867806SA | A | 12/13/1989 | 1 | QP SEMI | | Y | PALC16R8-30TMB | 431 |
| 5962-8867806XA | A | 12/13/1989 | 1 | QP SEMI | | Y | PALC16R8-30QMB | 431 |
| 5962-8867807RA | A | 12/13/1989 | 1 | QP SEMI | | Y | PALC16R6-30WMB | 431 |
| 5962-8867807SA | A | 12/13/1989 | 1 | QP SEMI | | Y | PALC16R6-30TMB | 431 |
| 5962-8867807XA | A | 12/13/1989 | 1 | QP SEMI | | Y | PALC16R6-30QMB | 431 |
| 5962-8867808RA | A | 12/13/1989 | | (NONE) | | | C16R4-30 (GEN) | 431 |
| 5962-8867808SA | A | 12/13/1989 | | (NONE) | | | C16R4-30 (GEN) | 431 |
| 5962-8867808XA | A | 12/13/1989 | | (NONE) | | | C16R4-30 (GEN) | 431 |
| 5962-8867809RA | A | 12/13/1989 | 1 | QP SEMI | | Y | PALC16L8-20WMB | 431 |
| 5962-8867809SA | A | 12/13/1989 | 1 | QP SEMI | | Y | PALC16L8-20TMB | 431 |
| 5962-8867809XA | A | 12/13/1989 | 1 | QP SEMI | | Y | PALC16L8-20QMB | 431 |
| 5962-8867810RA | A | 12/13/1989 | 1 | QP SEMI | | Y | PALC16R8-20WMB | 431 |
| 5962-8867810SA | A | 12/13/1989 | 1 | QP SEMI | | Y | PALC16R8-20TMB | 431 |
| 5962-8867810XA | A | 12/13/1989 | 1 | QP SEMI | | Y | PALC16R8-20QMB | 431 |
| 5962-8867811RA | A | 12/13/1989 | 1 | QP SEMI | | Y | PALC16R6-20WMB | 431 |
| 5962-8867811SA | A | 12/13/1989 | 1 | QP SEMI | | Y | PALC16R6-20TMB | 431 |
| 5962-8867811XA | A | 12/13/1989 | 1 | QP SEMI | | Y | PALC16R6-20QMB | 431 |
| 5962-8867812RA | A | 12/13/1989 | | (NONE) | 05/30/1999 | | C16R4-20 (GEN) | 431 |
| 5962-8867812SA | A | 12/13/1989 | | (NONE) | | | C16R4-20 (GEN) | 431 |
| 5962-8867812XA | A | 12/13/1989 | | (NONE) | | | C16R4-20 (GEN) | 431 |
| 5962-88680013A | | 12/04/1991 | | (NONE) | | | | 658 |
| 5962-8868001KA | | 12/04/1991 | | (NONE) | | | | 658 |
| 5962-8868001LA | | 12/04/1991 | | (NONE) | 05/31/1998 | | 7C293A-50 (GEN) | 658 |
| 5962-88680023A | | 12/04/1991 | | (NONE) | | | | 658 |
| 5962-8868002KA | | 12/04/1991 | | (NONE) | | | | 658 |
| 5962-8868002LA | | 12/04/1991 | | (NONE) | 05/31/1998 | | 7C293A-35 (GEN) | 658 |
| 5962-88680033A | | 12/04/1991 | | (NONE) | | | | 658 |
| 5962-8868003KA | | 12/04/1991 | | (NONE) | | | | 658 |
| 5962-8868003LA | | 12/04/1991 | | (NONE) | 05/31/1998 | | 7C293A-30 (GEN) | 658 |
| 5962-88680043A | | 12/04/1991 | | (NONE) | | | | 658 |
| 5962-8868004KA | | 12/04/1991 | | (NONE) | | | | 658 |
| 5962-8868004LA | | 12/04/1991 | | (NONE) | | | 7C293A-25 (GEN) | 658 |
| 5962-8868101LA | C | 08/19/1997 | 1 | AUSTIN SEMI. | | Y | MT5C2564C-35/883C | 623 |
| 5962-8868101XA | C | 08/19/1997 | 1 | AUSTIN SEMI. | | Y | MT5C2564EC-35/883C | 623 |
| 5962-8868101YA | C | 08/19/1997 | 1 | AUSTIN SEMI. | | Y | MT5C2564F-35/883C | 623 |
| 5962-8868102LA | C | 08/19/1997 | 1 | AUSTIN SEMI. | | Y | MT5C2564C-45/883C | 623 |
| 5962-8868102XA | C | 08/19/1997 | 1 | AUSTIN SEMI. | | Y | MT5C2564EC-45/883C | 623 |
| 5962-8868102YA | C | 08/19/1997 | 1 | AUSTIN SEMI. | | Y | MT5C2564F-45/883C | 623 |
| 5962-8868103LA | C | 08/19/1997 | 1 | AUSTIN SEMI. | | Y | MT5C2564C-55/883C | 623 |
| 5962-8868103XA | C | 08/19/1997 | 1 | AUSTIN SEMI. | | Y | MT5C2564EC-55/883C | 623 |
| 5962-8868103YA | C | 08/19/1997 | 1 | AUSTIN SEMI. | | Y | MT5C2564F-55/883C | 623 |
| 5962-8868104LA | C | 08/19/1997 | 1 | AUSTIN SEMI. | | Y | M5C2564C-70/883C | 623 |
| 5962-8868104XA | C | 08/19/1997 | 1 | AUSTIN SEMI. | | Y | MT5C2564EC-70/883C | 623 |
| 5962-8868104YA | C | 08/19/1997 | 1 | AUSTIN SEMI. | | Y | MT5C2564F-70/883C | 623 |
| 5962-8868105LA | C | 08/19/1997 | 1 | AUSTIN SEMI. | | Y | MT5C2564C-25/883C | 629 |
| 5962-8868105XA | C | 08/19/1997 | 1 | AUSTIN SEMI. | | Y | MT5C2564EC-25/883C | 629 |
| 5962-8868105YA | C | 08/19/1997 | 1 | AUSTIN SEMI. | | Y | MT5C2564F-25/883C | 629 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-8868106LA | C | 08/19/1997 | 1 | AUSTIN SEMI. | | Y | MT5C2564C-20/883C | 629 |
| 5962-8868106XA | C | 08/19/1997 | 1 | AUSTIN SEMI. | | Y | MT5C2564EC-20/883C | 629 |
| 5962-8868106YA | C | 08/19/1997 | 1 | AUSTIN SEMI. | | Y | MT5C2564F-20/883C | 629 |
| 5962-88682012A | A | 10/30/1992 | 3 | TI | | Y | SNJ54HC253FK | 273 |
| 5962-8868201EA | A | 10/30/1992 | 3 | TI | | Y | SNJ54HC253J | 273 |
| 5962-8868301UA | A | 08/25/1997 | | (NONE) | | | P4C163L-45 (GEN) | 629 |
| 5962-8868301XA | A | 08/25/1997 | | (NONE) | | | P4C163L-45 (GEN) | 629 |
| 5962-8868301YA | A | 08/25/1997 | | (NONE) | | | P4C163L-45 (GEN) | 629 |
| 5962-8868301ZA | A | 08/25/1997 | | (NONE) | | | P4C163L-45 (GEN) | 629 |
| 5962-8868302UA | A | 08/25/1997 | | (NONE) | | | P4C163L-35 (GEN) | 629 |
| 5962-8868302XA | A | 08/25/1997 | | (NONE) | | | P4C163L-35 (GEN) | 629 |
| 5962-8868302YA | A | 08/25/1997 | | (NONE) | | | P4C163L-35 (GEN) | 629 |
| 5962-8868302ZA | A | 08/25/1997 | | (NONE) | | | P4C163L-35 (GEN) | 629 |
| 5962-8868303UA | A | 08/25/1997 | | (NONE) | | | P4C163L-25 (GEN) | 629 |
| 5962-8868303XA | A | 08/25/1997 | | (NONE) | | | P4C163L-25 (GEN) | 629 |
| 5962-8868303YA | A | 08/25/1997 | | (NONE) | | | P4C163L-25 (GEN) | 629 |
| 5962-8868303ZA | A | 08/25/1997 | | (NONE) | | | P4C163L-25 (GEN) | 629 |
| 5962-8868304UA | A | 08/25/1997 | 1 | PYRAMID | | | P4C163L-45LMB | 629 |
| 5962-8868304XA | A | 08/25/1997 | 1 | PYRAMID | | | P4C163L-45DWMB | 629 |
| 5962-8868304YA | A | 08/25/1997 | 1 | PYRAMID | | | P4C163L-45CMB | 629 |
| 5962-8868304ZA | A | 08/25/1997 | 1 | PYRAMID | | | P4C163L-45FMB | 629 |
| 5962-8868305UA | A | 08/25/1997 | 1 | PYRAMID | | | P4C163L-35LMB | 629 |
| 5962-8868305XA | A | 08/25/1997 | 1 | PYRAMID | | | P4C163L-35DWMB | 629 |
| 5962-8868305YA | A | 08/25/1997 | 1 | PYRAMID | | | P4C163L-35CMB | 629 |
| 5962-8868305ZA | A | 08/25/1997 | 1 | PYRAMID | | | P4C163L-35FMB | 629 |
| 5962-8868306UA | A | 08/25/1997 | 1 | PYRAMID | | | P4C163L-25LMB | 629 |
| 5962-8868306XA | A | 08/25/1997 | 1 | PYRAMID | | | P4C163L-25DWMB | 629 |
| 5962-8868306YA | A | 08/25/1997 | 1 | PYRAMID | | | P4C163L-25CMB | 629 |
| 5962-8868306ZA | A | 08/25/1997 | 1 | PYRAMID | | | P4C163L-25FMB | 629 |
| 5962-8868401CA | | 04/11/1991 | | (NONE) | 06/30/1996 | | SP8755 (GEN) | 319 |
| 5962-88685012A | J | 06/14/2000 | | (NONE) | 05/01/1998 | | TL7705AM (GEN) | 787 |
| 5962-8868501PA | J | 06/14/2000 | | (NONE) | 05/01/1998 | | TL7705AM (GEN) | 787 |
| 5962-88685022A | J | 06/14/2000 | | (NONE) | 05/01/1998 | | TL7702AM (GEN) | 787 |
| 5962-8868502PA | J | 06/14/2000 | | (NONE) | 05/01/1998 | | TL7702AM (GEN) | 787 |
| 5962-88685032A | J | 06/14/2000 | | (NONE) | 12/31/2001 | | TL7705B (GEN) | 787 |
| 5962-8868503HA | J | 06/14/2000 | | (NONE) | 12/31/2001 | | TL7705B (GEN) | 787 |
| 5962-8868503PA | J | 06/14/2000 | | (NONE) | 12/31/2001 | | TL7705B (GEN) | 787 |
| 5962-88685042A | J | 06/14/2000 | | (NONE) | 08/15/1999 | | TL7702B (GEN) | 787 |
| 5962-8868504HA | J | 06/14/2000 | | (NONE) | 08/15/1999 | | TL7702B (GEN) | 787 |
| 5962-8868504PA | J | 06/14/2000 | | (NONE) | 08/15/1999 | | TL7702B (GEN) | 787 |
| 5962-88685052A | J | 06/14/2000 | | (NONE) | 12/31/2001 | | TL7705B (GEN) | 787 |
| 5962-8868505HA | J | 06/14/2000 | | (NONE) | 12/31/2001 | | TL7705B (GEN) | 787 |
| 5962-8868505PA | J | 06/14/2000 | | (NONE) | 12/31/2001 | | TL7705B (GEN) | 787 |
| 5962-88687013A | B | 07/20/2000 | 2 | TI | | | SNJ54AS652FK | 590 |
| 5962-8868701KA | B | 07/20/2000 | 2 | TI | | | SNJ54AS652W | 590 |
| 5962-8868701LA | B | 07/20/2000 | 2 | TI | | | SNJ54AS652JT | 590 |
| 5962-8868901QA | C | 12/18/2002 | 1 | QP SEMI | | | Z85C3006CMB | 420 |
| 5962-8868901YA | C | 12/18/2002 | 1 | QP SEMI | | | Z85C3006LMB | 420 |
| 5962-8868902QA | C | 12/18/2002 | 1 | QP SEMI | | | Z85C3008CMB | 420 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-8868902YA | C | 12/18/2002 | 1 | QP SEMI | | | Z85C3008LMB | 420 |
| 5962-8868903QA | C | 12/18/2002 | | (NONE) | 08/04/1995 | | 85C30-10 (GEN) | 420 |
| 5962-8868903YA | C | 12/18/2002 | | (NONE) | 08/04/1995 | | 85C30-10 (GEN) | 420 |
| 5962-8868904QA | C | 12/18/2002 | | (NONE) | | | 85C30-12 (GEN) | 420 |
| 5962-8868904YA | C | 12/18/2002 | | (NONE) | | | 85C30-12 (GEN) | 420 |
| 5962-8868905QA | C | 12/18/2002 | | (NONE) | 08/04/1995 | | 85C30-16 (GEN) | 420 |
| 5962-8868905YA | C | 12/18/2002 | | (NONE) | 08/04/1995 | | 85C30-16 (GEN) | 420 |
| 5962-8868906QA | C | 12/18/2002 | | (NONE) | 08/04/1995 | | 85C30-8 (GEN) | 420 |
| 5962-8868906YA | C | 12/18/2002 | | (NONE) | 08/04/1995 | | 85C30-8 (GEN) | 420 |
| 5962-8868907QA | C | 12/18/2002 | 1 | QP SEMI | | | Z85C3010CMB | 420 |
| 5962-8868907XA | C | 12/18/2002 | 1 | QP SEMI | | | Z85C3010NMB | 420 |
| 5962-8868907YA | C | 12/18/2002 | 1 | QP SEMI | | | Z85C3010LMB | 420 |
| 5962-8868908QA | C | 12/18/2002 | 1 | QP SEMI | | | Z8523010CMB | 420 |
| 5962-8868908YA | C | 12/18/2002 | 1 | QP SEMI | | | Z8523010LMB | 420 |
| 5962-8868909QA | C | 12/18/2002 | 1 | QP SEMI | | | Z8523016CMB | 420 |
| 5962-8868909YA | C | 12/18/2002 | 1 | QP SEMI | | | Z8523016LMB | 420 |
| 5962-8868910QA | C | 12/18/2002 | 1 | QP SEMI | | | Z8523008CMB | 420 |
| 5962-8868910YA | C | 12/18/2002 | 1 | QP SEMI | | | Z8523008LMB | 420 |
| 5962-88690013A | A | 10/05/2000 | | (NONE) | | | HM4-6642 (GEN) | 656 |
| 5962-8869001JA | A | 10/05/2000 | | (NONE) | 03/25/2001 | | HM1-6642 (GEN) | 656 |
| 5962-8869001LA | A | 10/05/2000 | | (NONE) | | | HM6-6642 (GEN) | 656 |
| 5962-88690023A | A | 10/05/2000 | | (NONE) | | | HM4-6642B (GEN) | 656 |
| 5962-8869002JA | A | 10/05/2000 | | (NONE) | | | HM1-6642B (GEN) | 656 |
| 5962-8869002LA | A | 10/05/2000 | | (NONE) | 09/23/2001 | | HM6-6642B (GEN) | 656 |
| 5962-88691012A | B | 05/04/2000 | 2 | TI | | Y | SNJ54ALS520FK | 209 |
| 5962-8869101RA | B | 05/04/2000 | 2 | TI | | Y | SNJ54ALS520J | 209 |
| 5962-8869201TA | K | 08/28/2000 | | (NONE) | 11/30/2001 | | BUS61563 (GEN) | 899 |
| 5962-8869201XA | K | 08/28/2000 | | (NONE) | 11/30/2001 | | BUS61553 (GEN) | 899 |
| 5962-8869201YA | K | 08/28/2000 | | (NONE) | | | BUS61563 (GEN) | 899 |
| 5962-8869201ZA | K | 08/28/2000 | | (NONE) | | | BUS61563 (GEN) | 899 |
| 5962-8869202TA | K | 08/28/2000 | | (NONE) | 11/30/2001 | | BUS61564 (GEN) | 899 |
| 5962-8869202XA | K | 08/28/2000 | | (NONE) | 11/30/2001 | | BUS61554 (GEN) | 899 |
| 5962-8869202XC | K | 08/28/2000 | | (NONE) | 11/30/2001 | | BUS61554 (GEN) | 899 |
| 5962-8869202YA | K | 08/28/2000 | | (NONE) | | | BUS61564 (GEN) | 899 |
| 5962-8869202ZA | K | 08/28/2000 | | (NONE) | | | BUS61564 (GEN) | 899 |
| 5962-8869203XA | K | 08/28/2000 | | (NONE) | 11/30/2001 | | BUS61555 (GEN) | 899 |
| 5962-8869203YA | K | 08/28/2000 | | (NONE) | 11/30/2001 | | BUS61565 (GEN) | 899 |
| 5962-8869203ZA | K | 08/28/2000 | | (NONE) | | | BUS61565 (GEN) | 899 |
| 5962-8869204XA | K | 08/28/2000 | | (NONE) | 11/30/2001 | | BUS61556 (GEN) | 899 |
| 5962-88693012A | C | 07/28/2000 | 2 | TI | | Y | SNJ54ALS804AFK | 509 |
| 5962-8869301RA | C | 07/28/2000 | 2 | TI | | Y | SNJ54ALS804AJ | 509 |
| 5962-8869301SA | C | 07/28/2000 | 2 | TI | | Y | SNJ54ALS804AW | 509 |
| 5962-88694012A | B | 09/19/2000 | | (NONE) | 12/31/2001 | | 54ALS805A (GEN) | 502 |
| 5962-8869401RA | B | 09/19/2000 | | (NONE) | 12/31/2001 | | 54ALS805A (GEN) | 502 |
| 5962-8869401SA | B | 09/19/2000 | 1 | TI | | Y | SNJ54ALS805AW | 502 |
| 5962-88695012A | A | 10/05/1992 | | (NONE) | | | 54ALS808 (GEN) | 502 |
| 5962-8869501RA | A | 10/05/1992 | | (NONE) | | | 54ALS808 (GEN) | 502 |
| 5962-8869501SA | A | 10/05/1992 | | (NONE) | | | 54ALS808 (GEN) | 502 |
| 5962-8869601XA | A | 08/20/1990 | | (NONE) | 08/04/1995 | | 2968A (GEN) | 423 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-8869602YA | A | 08/20/1990 | | (NONE) | | | 2968A (GEN) | 423 |
| 5962-88697012A | D | 05/22/2001 | 1 | TI | | Y | UC1903L/883B | 787 |
| 5962-8869701VA | D | 05/22/2001 | 1 | TI | | Y | UC1903J/883B | 787 |
| 5962-88698012A | C | 08/07/1997 | 2 | TI | | Y | SNJ54ALS193AFK | 304 |
| 5962-8869801EA | C | 08/07/1997 | 2 | TI | | Y | SNJ54ALS193AJ | 304 |
| 5962-8869801FA | C | 08/07/1997 | 2 | TI | | Y | SNJ54ALS193AW | 304 |
| 5962-88699013A | | 12/20/1988 | | (NONE) | 09/29/1995 | | HI516 (GEN) | 195 |
| 5962-8869901XA | | 12/20/1988 | | (NONE) | 09/29/1995 | | HI516 (GEN) | 195 |
| 5962-88700012A | B | 09/08/2000 | 2 | TI | | Y | SNJ54ALS563BFK | 341 |
| 5962-8870001RA | B | 09/08/2000 | 2 | TI | | Y | SNJ54ALS563BJ | 341 |
| 5962-8870001SA | B | 09/08/2000 | 2 | TI | | Y | SNJ54ALS563BW | 341 |
| 5962-8870101UA | C | 05/21/2002 | 1 | INTER. RECT. | | Y | OMA541SDZB | 753 |
| 5962-8870101UA | C | 05/21/2002 | 1 | MS KENNEDY | | Y | MSK147B | 753 |
| 5962-8870101UC | C | 05/21/2002 | 1 | MS KENNEDY | | Y | MSK147B | 753 |
| 5962-8870101XA | C | 05/21/2002 | 1 | INTER. RECT. | | Y | OMA541SKB | 753 |
| 5962-8870101XA | C | 05/21/2002 | 1 | MS KENNEDY | | Y | MSK541B | 753 |
| 5962-8870101XC | C | 05/21/2002 | 1 | MS KENNEDY | | Y | MSK541B | 753 |
| 5962-8870101YA | C | 05/21/2002 | 1 | INTER. RECT. | | Y | OMA541SDB | 753 |
| 5962-8870101YA | C | 05/21/2002 | 1 | MS KENNEDY | | Y | MSK146B | 753 |
| 5962-8870101YC | C | 05/21/2002 | 1 | MS KENNEDY | | Y | MSK146B | 753 |
| 5962-8870101ZC | C | 05/21/2002 | 1 | MS KENNEDY | | Y | MSK145B | 753 |
| 5962-8870102XA | C | 05/21/2002 | 1 | INTER. RECT. | | Y | OMA541SKCB | 753 |
| 5962-88702012A | A | 06/11/2003 | 3 | NATIONAL | | Y | 54AC377LMQB | 159 |
| 5962-8870201RA | A | 06/11/2003 | 3 | NATIONAL | | Y | 54AC377DMQB | 159 |
| 5962-8870201SA | A | 06/11/2003 | 3 | NATIONAL | | Y | 54AC377FMQB | 159 |
| 5962-88703012A | B | 09/19/2000 | 2 | NATIONAL | | Y | 54AC257LMQB | 276 |
| 5962-8870301EA | B | 09/19/2000 | 2 | NATIONAL | | Y | 54AC257DMQB | 276 |
| 5962-8870301FA | B | 09/19/2000 | 2 | NATIONAL | | Y | 54AC257FMQB | 276 |
| 5962-8870301VFA | B | 09/19/2000 | | (NONE) | | | 54AC257 (GEN) | 276 |
| 5962-8870301VXA | B | 09/19/2000 | 2 | STMICRO | | Y | 54AC257K02V | 276 |
| 5962-8870301VXC | B | 09/19/2000 | 2 | STMICRO | | Y | 54AC257K01Q | 276 |
| 5962-8870301XA | B | 09/19/2000 | 2 | STMICRO | | Y | 54AC257K02Q | 276 |
| 5962-8870301XC | B | 09/19/2000 | 2 | STMICRO | | Y | 54AC257K01Q | 276 |
| 5962-88704012A | A | 06/11/2003 | 3 | NATIONAL | | Y | 54ACT258LMQB | 276 |
| 5962-8870401EA | A | 06/11/2003 | 3 | NATIONAL | | Y | 54ACT258DMQB | 276 |
| 5962-8870401FA | A | 06/11/2003 | 3 | NATIONAL | | Y | 54ACT258FMQB | 276 |
| 5962-88705013A | A | 06/10/2003 | 3 | NATIONAL | | Y | 54ACT821LMQB | 159 |
| 5962-8870501KA | A | 06/10/2003 | 3 | NATIONAL | | Y | 54ACT821FMQB | 159 |
| 5962-8870501LA | A | 06/10/2003 | 3 | NATIONAL | | Y | 54ACT821SDMQB | 159 |
| 5962-88706012A | C | 08/06/2001 | 3 | NATIONAL | | Y | 54AC541LMQB | 529 |
| 5962-8870601RA | C | 08/06/2001 | 3 | NATIONAL | | Y | 54AC541DMQB | 529 |
| 5962-8870601SA | C | 08/06/2001 | 3 | NATIONAL | | Y | 54AC541FMQB | 529 |
| 5962-8870601VSA | C | 08/06/2001 | | (NONE) | | | 54AC541 (GEN) | 529 |
| 5962-8870601VXA | C | 08/06/2001 | 2 | STMICRO | | Y | 54AC541K02V | 529 |
| 5962-8870601VXC | C | 08/06/2001 | 2 | STMICRO | | Y | 54AC541K01Q | 529 |
| 5962-8870601XA | C | 08/06/2001 | 2 | STMICRO | | Y | 54AC541K02Q | 529 |
| 5962-8870601XC | C | 08/06/2001 | 2 | STMICRO | | Y | 54AC541K01Q | 529 |
| 5962-8870601ZA | C | 08/06/2001 | 3 | NATIONAL | | Y | 54AC541WG-QML | 529 |
| 5962-88707013A | C | 04/22/1992 | | (NONE) | 09/01/1997 | | 54F776 (GEN) | 590 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-8870701XA | C | 04/22/1992 | | (NONE) | 09/01/1997 | | 54F776 (GEN) | 590 |
| 5962-8870701YA | C | 04/22/1992 | | (NONE) | 09/01/1997 | | 54F776 (GEN) | 590 |
| 5962-88708012A | A | 08/10/2000 | 2 | TI | | Y | SNJ54F30FK | 106 |
| 5962-8870801CA | A | 08/10/2000 | 2 | TI | | Y | SNJ54F30J | 106 |
| 5962-8870801DA | A | 08/10/2000 | 2 | TI | | Y | SNJ54F30W | 106 |
| 5962-88709012A | | 08/10/1988 | | (NONE) | | | 54F36 (GEN) | 120 |
| 5962-8870901CA | | 08/10/1988 | | (NONE) | | | 54F36 (GEN) | 120 |
| 5962-8870901DA | | 08/10/1988 | | (NONE) | | | 54F36 (GEN) | 120 |
| 5962-88710012A | | 08/17/1988 | | (NONE) | | | 54F518 (GEN) | 209 |
| 5962-8871001RA | | 08/17/1988 | | (NONE) | | | 54F518 (GEN) | 209 |
| 5962-8871001SA | | 08/17/1988 | | (NONE) | | | 54F518 (GEN) | 209 |
| 5962-88711012A | | 08/19/1988 | | (NONE) | | | 54F519 (GEN) | 209 |
| 5962-8871101RA | | 08/19/1988 | | (NONE) | | | 54F519 (GEN) | 209 |
| 5962-8871101SA | | 08/19/1988 | | (NONE) | | | 54F519 (GEN) | 209 |
| 5962-88712012A | | 09/02/1988 | | (NONE) | | | 54F520 (GEN) | 209 |
| 5962-8871201RA | | 09/02/1988 | | (NONE) | | | 54F520 (GEN) | 209 |
| 5962-8871201SA | | 09/02/1988 | | (NONE) | | | 54F520 (GEN) | 209 |
| 5962-8871301RA | | 09/23/1988 | 1 | QP SEMI | | Y | PALC16L8-40DMB | 431 |
| 5962-8871301SA | | 09/23/1988 | 1 | QP SEMI | | Y | PALC16L8-40KMB | 431 |
| 5962-8871301XA | | 09/23/1988 | 1 | QP SEMI | | Y | PALC16L8-40LMB | 431 |
| 5962-8871302RA | | 09/23/1988 | 1 | QP SEMI | | Y | PALC16R8-40DMB | 431 |
| 5962-8871302SA | | 09/23/1988 | 1 | QP SEMI | | Y | PALC16R8-40KMB | 431 |
| 5962-8871302XA | | 09/23/1988 | 1 | QP SEMI | | Y | PALC16R8-40LMB | 431 |
| 5962-8871303RA | | 09/23/1988 | 1 | QP SEMI | | Y | PALC16R6-40DMB | 431 |
| 5962-8871303SA | | 09/23/1988 | 1 | QP SEMI | | Y | PALC16R6-40KMB | 431 |
| 5962-8871303XA | | 09/23/1988 | 1 | QP SEMI | | Y | PALC16R6-40LMB | 431 |
| 5962-8871304RA | | 09/23/1988 | | (NONE) | | | C16R4-40 (GEN) | 431 |
| 5962-8871304SA | | 09/23/1988 | | (NONE) | | | C16R4-40 (GEN) | 431 |
| 5962-8871304XA | | 09/23/1988 | | (NONE) | | | C16R4-40 (GEN) | 431 |
| 5962-8871305RA | | 09/23/1988 | 1 | QP SEMI | | Y | PALC16L8-30DMB | 431 |
| 5962-8871305SA | | 09/23/1988 | 1 | QP SEMI | | Y | PALC16L8-30KMB | 431 |
| 5962-8871305XA | | 09/23/1988 | 1 | QP SEMI | | Y | PALC16L8-30LMB | 431 |
| 5962-8871306RA | | 09/23/1988 | 1 | QP SEMI | | Y | PALC16R8-30DMB | 431 |
| 5962-8871306SA | | 09/23/1988 | 1 | QP SEMI | | Y | PALC16R8-30KMB | 431 |
| 5962-8871306XA | | 09/23/1988 | 1 | QP SEMI | | Y | PALC16R8-30LMB | 431 |
| 5962-8871307RA | | 09/23/1988 | 1 | QP SEMI | | Y | PALC16R6-30DMB | 431 |
| 5962-8871307SA | | 09/23/1988 | 1 | QP SEMI | | Y | PALC16R6-30 KMB | 431 |
| 5962-8871307XA | | 09/23/1988 | 1 | QP SEMI | | Y | PALC16R6-30LMB | 431 |
| 5962-8871308RA | | 09/23/1988 | | (NONE) | | | C16R4-30 (GEN) | 431 |
| 5962-8871308SA | | 09/23/1988 | | (NONE) | | | C16R4-30 (GEN) | 431 |
| 5962-8871308XA | | 09/23/1988 | | (NONE) | | | C16R4-30 (GEN) | 431 |
| 5962-8871309RA | | 09/23/1988 | 1 | QP SEMI | | Y | PALC16L8-20DMB | 431 |
| 5962-8871309SA | | 09/23/1988 | 1 | QP SEMI | | Y | PALC16L8-20KMB | 431 |
| 5962-8871309XA | | 09/23/1988 | 1 | QP SEMI | | Y | PALC16L8-20LMB | 431 |
| 5962-8871310RA | | 09/23/1988 | 1 | QP SEMI | | Y | PALC16R8-20DMB | 431 |
| 5962-8871310SA | | 09/23/1988 | 1 | QP SEMI | | Y | PALC16R8-20KMB | 431 |
| 5962-8871310XA | | 09/23/1988 | 1 | QP SEMI | | Y | PALC16R8-20LMB | 431 |
| 5962-8871311RA | | 09/23/1988 | 1 | QP SEMI | | Y | PALC16R6-20DMB | 431 |
| 5962-8871311SA | | 09/23/1988 | 1 | QP SEMI | | Y | PALC16R6-20KMB | 431 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-8871311XA | | 09/23/1988 | 1 | QP SEMI | | Y | PALC16R6-20LMB | 431 |
| 5962-8871312RA | | 09/23/1988 | | (NONE) | 05/30/1999 | | C16R4-20 (GEN) | 431 |
| 5962-8871312SA | | 09/23/1988 | | (NONE) | | | C16R4-20 (GEN) | 431 |
| 5962-8871312XA | | 09/23/1988 | | (NONE) | 05/30/1999 | | C16R4-20 (GEN) | 431 |
| 5962-88715012A | C | 06/01/2004 | 1 | MICROSEMI | | Y | SG55454BL/883B | 583 |
| 5962-88715022A | C | 06/01/2004 | 1 | MICROSEMI | | Y | SG55464L/883B | 583 |
| 5962-8871502PA | C | 06/01/2004 | 1 | MICROSEMI | | Y | SG55464Y/883B | 583 |
| 5962-88715032A | C | 06/01/2004 | 1 | MICROSEMI | | Y | SG55474L/883B | 583 |
| 5962-8871503PA | C | 06/01/2004 | 1 | MICROSEMI | | Y | SG55474Y/883B | 583 |
| 5962-8871601CA | B | 10/17/2002 | 0 | MICROSEMI | | Y | SG1626J/883B | 550 |
| 5962-8871601GA | B | 10/17/2002 | 0 | MICROSEMI | | Y | SG1626T/883B | 550 |
| 5962-8871601PA | B | 10/17/2002 | 0 | MICROSEMI | | Y | SG1626Y/883B | 550 |
| 5962-8871601XA | B | 10/17/2002 | 0 | MICROSEMI | | Y | SG1626R/883B | 550 |
| 5962-88718012A | A | 07/31/1992 | 1 | TI | | Y | SNJ54HC05FK | 144 |
| 5962-8871801CA | A | 07/31/1992 | 1 | TI | | Y | SNJ54HC05J | 144 |
| 5962-8871901MXA | C | 08/07/2002 | 1 | ANALOG (2) | | Y | AD664TD-UNI/883B | 591 |
| 5962-8871902MXA | C | 08/07/2002 | 1 | ANALOG (2) | | Y | AD664TD-BIP/883B | 591 |
| 5962-8871903MYA | C | 08/07/2002 | 1 | ANALOG (2) | | Y | AD664TE/883B | 591 |
| 5962-88721012A | C | 03/21/2003 | | (NONE) | 04/16/2002 | | OP-270A (GEN) | 710 |
| 5962-8872101V2A | C | 03/21/2003 | 2 | ANALOG (5) | | Y | OP-270ARC/QMLV | 710 |
| 5962R8872101V2A | C | 03/21/2003 | 2 | ANALOG (5) | | Y | OP-270ARC/QMLR | 710 |
| 5962-8872101VDA | C | 03/21/2003 | 2 | ANALOG (5) | | Y | OP-270AM/QMLV | 710 |
| 5962R8872101VDA | C | 03/21/2003 | 2 | ANALOG (5) | | Y | OP-270AM/QMLR | 710 |
| 5962-8872101PA | C | 03/21/2003 | 1 | ANALOG (5) | | Y | OP-270AZ/883C | 710 |
| 5962-8872101VPA | C | 03/21/2003 | 2 | ANALOG (5) | | Y | OP-270AZ/QMLV | 710 |
| 5962R8872101VPA | C | 03/21/2003 | 2 | ANALOG (5) | | Y | OP-270AZ/QMLR | 710 |
| 5962-88721022A | C | 03/21/2003 | | (NONE) | 04/16/2002 | | OP-271A (GEN) | 710 |
| 5962-8872102PA | C | 03/21/2003 | | (NONE) | 04/16/2002 | | OP-271A (GEN) | 710 |
| 5962-88722013A | | 10/04/1988 | | (NONE) | | | 54F30244 (GEN) | 529 |
| 5962-8872201KA | | 10/04/1988 | | (NONE) | | | 54F30244 (GEN) | 529 |
| 5962-8872201LA | | 10/04/1988 | | (NONE) | | | 54F30244 (GEN) | 529 |
| 5962-88723012A | | 09/06/1988 | | (NONE) | | | 54F09 (GEN) | 111 |
| 5962-8872301CA | | 09/06/1988 | | (NONE) | | | 54F09 (GEN) | 111 |
| 5962-8872301DA | | 09/06/1988 | | (NONE) | | | 54F09 (GEN) | 111 |
| 5962-88724013A | C | 11/05/2001 | 2 | ATMEL | | | AT22V10L-25LM/883 | 431 |
| 5962-88724013A | C | 11/05/2001 | 1 | AUSTIN SEMI. | | | AT22V10L-25LM/883 | 431 |
| 5962-8872401KA | C | 11/05/2001 | | (NONE) | 03/30/1994 | | C22V10L-25 (GEN) | 431 |
| 5962-8872401LA | C | 11/05/2001 | 2 | ATMEL | | | AT22V10L-25DM/883 | 431 |
| 5962-8872401LA | C | 11/05/2001 | 1 | AUSTIN SEMI. | | | AT22V10L-25DM/883 | 431 |
| 5962-88724023A | C | 11/05/2001 | 1 | AUSTIN SEMI. | | | AT22V10L-30LM/883 | 431 |
| 5962-8872402KA | C | 11/05/2001 | | (NONE) | 03/30/1994 | | C22V10L-30 (GEN) | 431 |
| 5962-8872402LA | C | 11/05/2001 | 1 | AUSTIN SEMI. | | | AT22V10L-30DM/883 | 431 |
| 5962-88724033A | C | 11/05/2001 | 1 | AUSTIN SEMI. | | | AT22V10L-40LM/883 | 431 |
| 5962-8872403KA | C | 11/05/2001 | | (NONE) | 03/30/1994 | | C22V10L-40 (GEN) | 431 |
| 5962-8872403LA | C | 11/05/2001 | 1 | AUSTIN SEMI. | | | AT22V10L-40DM/883 | 431 |
| 5962-88724043A | C | 11/05/2001 | 2 | ATMEL | | | AT22V10L-20LM/883 | 431 |
| 5962-88724043A | C | 11/05/2001 | 1 | AUSTIN SEMI. | | | AT22V10L-20LM/883 | 431 |
| 5962-8872404KA | C | 11/05/2001 | | (NONE) | 03/30/1994 | | C22V10L (GEN) | 431 |
| 5962-8872404LA | C | 11/05/2001 | 2 | ATMEL | | | AT22V10L-20DM/883 | 431 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-8872404LA | C | 11/05/2001 | 1 | AUSTIN SEMI. | | | AT22V10L-20DM/883 | 431 |
| 5962-8872501LA | B | 10/23/2000 | 1 | AUSTIN SEMI. | | Y | MT5C2561C-35 | 623 |
| 5962-8872501XA | B | 10/23/2000 | 1 | AUSTIN SEMI. | | Y | MT5C2561EC-35 | 623 |
| 5962-8872501YA | B | 10/23/2000 | | (NONE) | | | EDI81256C-35 (GEN) | 623 |
| 5962-8872502LA | B | 10/23/2000 | 1 | AUSTIN SEMI. | | Y | MT5C2561C-45 | 623 |
| 5962-8872502XA | B | 10/23/2000 | 1 | AUSTIN SEMI. | | Y | MT5C2561EC-45 | 623 |
| 5962-8872502YA | B | 10/23/2000 | | (NONE) | | | EDI81256C-45 (GEN) | 623 |
| 5962-8872503LA | B | 10/23/2000 | 1 | AUSTIN SEMI. | | Y | MT5C256C-55 | 623 |
| 5962-8872503XA | B | 10/23/2000 | 1 | AUSTIN SEMI. | | Y | MT5C2561EC-55 | 623 |
| 5962-8872503YA | B | 10/23/2000 | | (NONE) | | | EDI81256C-55 (GEN) | 623 |
| 5962-8872504LA | B | 10/23/2000 | 1 | AUSTIN SEMI. | | Y | MT5C2561C-70 | 623 |
| 5962-8872504XA | B | 10/23/2000 | 1 | AUSTIN SEMI. | | Y | MT5C2561EC-70 | 623 |
| 5962-8872504YA | B | 10/23/2000 | | (NONE) | | | EDI81256C-70 (GEN) | 623 |
| 5962-8872505LA | B | 10/23/2000 | 1 | AUSTIN SEMI. | | Y | MT5C2561C-25 | 623 |
| 5962-8872505XA | B | 10/23/2000 | 1 | AUSTIN SEMI. | | Y | MT5C2561EC-25 | 623 |
| 5962-88726013A | D | 09/06/2002 | | (NONE) | 03/30/1994 | | V750 (GEN) | 431 |
| 5962-8872601LA | D | 09/06/2002 | | (NONE) | 03/30/1994 | | V750 (GEN) | 431 |
| 5962-8872601XA | D | 09/06/2002 | | (NONE) | | | V750 (GEN) | 431 |
| 5962-88726023A | D | 09/06/2002 | | (NONE) | 12/31/1995 | | V750-35 (GEN) | 431 |
| 5962-8872602LA | D | 09/06/2002 | | (NONE) | 12/31/1995 | | V750-35 (GEN) | 431 |
| 5962-8872602XA | D | 09/06/2002 | | (NONE) | | | V750 (GEN) | 431 |
| 5962-88726033A | D | 09/06/2002 | | (NONE) | | | V750-25 (GEN) | 431 |
| 5962-8872603LA | D | 09/06/2002 | | (NONE) | | | V750-25 (GEN) | 431 |
| 5962-8872603XA | D | 09/06/2002 | | (NONE) | | | V750 (GEN) | 431 |
| 5962-8872603YA | D | 09/06/2002 | | (NONE) | | | V750 (GEN) | 431 |
| 5962-88726043A | D | 09/06/2002 | | (NONE) | | | V750-20 (GEN) | 431 |
| 5962-8872604LA | D | 09/06/2002 | | (NONE) | | | V750-20 (GEN) | 431 |
| 5962-8872604XA | D | 09/06/2002 | | (NONE) | | | V750 (GEN) | 431 |
| 5962-8872604YA | D | 09/06/2002 | | (NONE) | | | V750 (GEN) | 431 |
| 5962-88726063A | D | 09/06/2002 | | (NONE) | | | V750L (GEN) | 431 |
| 5962-8872606LA | D | 09/06/2002 | | (NONE) | | | V750L (GEN) | 431 |
| 5962-8872606XA | D | 09/06/2002 | | (NONE) | | | V750L (GEN) | 431 |
| 5962-88726073A | D | 09/06/2002 | | (NONE) | | | V750L-25 (GEN) | 431 |
| 5962-8872607LA | D | 09/06/2002 | | (NONE) | | | V750L-25 (GEN) | 431 |
| 5962-8872607XA | D | 09/06/2002 | | (NONE) | | | V750L (GEN) | 431 |
| 5962-8872607YA | D | 09/06/2002 | | (NONE) | | | V750L (GEN) | 431 |
| 5962-88726083A | D | 09/06/2002 | 2 | ATMEL | | | ATV750B-10LM/883 | 431 |
| 5962-8872608LA | D | 09/06/2002 | 2 | ATMEL | | | ATV750B-10DM/883 | 431 |
| 5962-8872608YA | D | 09/06/2002 | | (NONE) | | | V750B (GEN) | 431 |
| 5962-88726093A | D | 09/06/2002 | 2 | ATMEL | | | ATV750B-15LM/883 | 431 |
| 5962-8872609LA | D | 09/06/2002 | 2 | ATMEL | | | ATV750B-15DM/883 | 431 |
| 5962-8872609YA | D | 09/06/2002 | | (NONE) | | | V750B (GEN) | 431 |
| 5962-88726103A | D | 09/06/2002 | | (NONE) | | | V750B (GEN) | 431 |
| 5962-8872610LA | D | 09/06/2002 | | (NONE) | | | V750B (GEN) | 431 |
| 5962-8872610YA | D | 09/06/2002 | | (NONE) | | | V750B (GEN) | 431 |
| 5962-88726113A | D | 09/06/2002 | 2 | ATMEL | | | ATV750BL-15LM/883 | 431 |
| 5962-8872611LA | D | 09/06/2002 | 2 | ATMEL | | | ATV750BL-15DM/883 | 431 |
| 5962-8872611YA | D | 09/06/2002 | | (NONE) | | | V750BL3 (GEN) | 431 |
| 5962-88726123A | D | 09/06/2002 | 2 | ATMEL | | | ATV750BL-25LM/883 | 431 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-8872612LA | D | 09/06/2002 | 2 | ATMEL | | | ATV750BL-25DM/883 | 431 |
| 5962-8872612YA | D | 09/06/2002 | | (NONE) | | | V750BL (GEN) | 431 |
| 5962-88727012A | B | 11/27/2000 | 3 | TI | | Y | SNJ54ALS640BFK | 590 |
| 5962-8872701RA | B | 11/27/2000 | 3 | TI | | Y | SNJ54ALS640BJ | 590 |
| 5962-8872701SA | B | 11/27/2000 | 3 | TI | | Y | SNJ54ALS640BW | 590 |
| 5962-88728012A | B | 11/27/2000 | 2 | TI | | Y | SNJ54ALS564BFK | 159 |
| 5962-8872801RA | B | 11/27/2000 | 2 | TI | | Y | SNJ54ALS564BJ | 159 |
| 5962-8872801SA | B | 11/27/2000 | 2 | TI | | Y | SNJ54ALS564BW | 159 |
| 5962-88729012A | A | 11/01/2000 | 2 | TI | | | SNJ54AS1004AFK | 514 |
| 5962-8872901CA | A | 11/01/2000 | 2 | TI | | | SNJ54AS1004AJ | 514 |
| 5962-8872901DA | A | 11/01/2000 | 2 | TI | | | SNJ54AS1004AW | 514 |
| 5962-88730012A | A | 11/17/2000 | 2 | TI | | | SNJ54AS1032AFK | 125 |
| 5962-8873001CA | A | 11/17/2000 | | (NONE) | 12/31/2001 | | 54AS1032A (GEN) | 125 |
| 5962-8873001DA | A | 11/17/2000 | 2 | TI | | | SNJ54AS1032AW | 125 |
| 5962-88731012A | A | 11/01/2000 | 2 | TI | | | SNJ54AS1034AFK | 513 |
| 5962-8873101CA | A | 11/01/2000 | 2 | TI | | | SNJ54AS1034AJ | 513 |
| 5962-8873101DA | A | 11/01/2000 | 2 | TI | | | SNJ54AS1034AW | 513 |
| 5962-8873301TA | D | 01/15/1997 | | (NONE) | 08/21/1995 | | 7210L-55 (GEN) | 208 |
| 5962-8873301UA | D | 01/15/1997 | | (NONE) | 04/01/2000 | | 1010-55 (GEN) | 208 |
| 5962-8873301XA | D | 01/15/1997 | | (NONE) | 04/01/2000 | | 1010-55 (GEN) | 208 |
| 5962-8873301YA | D | 01/15/1997 | | (NONE) | 04/01/2000 | | 1010-55 (GEN) | 208 |
| 5962-8873301ZA | D | 01/15/1997 | | (NONE) | | | 1010-55 (GEN) | 208 |
| 5962-8873302TA | D | 01/15/1997 | | (NONE) | 08/21/1995 | | 7210L-65 (GEN) | 208 |
| 5962-8873302UA | D | 01/15/1997 | | (NONE) | 04/01/2000 | | 1010-65 (GEN) | 208 |
| 5962-8873302XA | D | 01/15/1997 | | (NONE) | 04/01/2000 | | 1010-65 (GEN) | 208 |
| 5962-8873302YA | D | 01/15/1997 | | (NONE) | 04/01/2000 | | 1010-65 (GEN) | 208 |
| 5962-8873302ZA | D | 01/15/1997 | | (NONE) | | | 1010-65 (GEN) | 208 |
| 5962-8873303TA | D | 01/15/1997 | | (NONE) | 08/21/1995 | | 7210L75 (GEN) | 208 |
| 5962-8873303UA | D | 01/15/1997 | | (NONE) | 04/01/2000 | | 1010-75 (GEN) | 208 |
| 5962-8873303XA | D | 01/15/1997 | | (NONE) | 04/01/2000 | | 1010-75 (GEN) | 208 |
| 5962-8873303YA | D | 01/15/1997 | | (NONE) | 04/01/2000 | | 1010-75 (GEN) | 208 |
| 5962-8873303ZA | D | 01/15/1997 | | (NONE) | | | 1010-75 (GEN) | 208 |
| 5962-8873304TA | D | 01/15/1997 | | (NONE) | 08/21/1995 | | 7210L30 (GEN) | 208 |
| 5962-8873304XA | D | 01/15/1997 | | (NONE) | 08/05/1996 | | 7210L30 (GEN) | 208 |
| 5962-8873304ZA | D | 01/15/1997 | | (NONE) | 08/05/1996 | | 7210L30 (GEN) | 208 |
| 5962-8873305TA | D | 01/15/1997 | | (NONE) | 08/21/1995 | | 7210L40 (GEN) | 208 |
| 5962-8873305XA | D | 01/15/1997 | | (NONE) | 08/05/1996 | | 7210L40 (GEN) | 208 |
| 5962-8873305ZA | D | 01/15/1997 | | (NONE) | 08/05/1996 | | 7210L40 (GEN) | 208 |
| 5962-88734013A | B | 11/02/2000 | 1 | QP SEMI | | | WS57C291C-55ZMB | 658 |
| 5962-88734013C | B | 11/02/2000 | 1 | QP SEMI | | | WS57C291C-55ZMB | 658 |
| 5962-8873401JA | B | 11/02/2000 | 1 | QP SEMI | | | WS57C191C-55YMB | 658 |
| 5962-8873401KA | B | 11/02/2000 | 1 | QP SEMI | | | WS57C191C-55HMB | 658 |
| 5962-8873401LA | B | 11/02/2000 | 2 | QP SEMI | | Y | 7C291A-55DMB | 658 |
| 5962-8873401LA | B | 11/02/2000 | 1 | QP SEMI | | | WS57C291C-55KMB | 658 |
| 5962-88734023A | B | 11/02/2000 | 2 | CYPRESS | | Y | CY7C291A-45LMB | 658 |
| 5962-88734023A | B | 11/02/2000 | 1 | QP SEMI | | | WS57C291C-45ZMB | 658 |
| 5962-88734023C | B | 11/02/2000 | 1 | QP SEMI | | | WS57C291C-45ZMB | 658 |
| 5962-8873402JA | B | 11/02/2000 | 1 | QP SEMI | | | WS57C191C-45YMB | 658 |
| 5962-8873402KA | B | 11/02/2000 | 1 | QP SEMI | | | WS57C191C-45HMB | 658 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-8873402LA | B | 11/02/2000 | 2 | QP SEMI | | Y | 7C291A-45DMB | 658 |
| 5962-8873402LA | B | 11/02/2000 | 1 | QP SEMI | | | WS57C291C-45KMB | 658 |
| 5962-88734033A | B | 11/02/2000 | 2 | CYPRESS | 06/28/2005 | Y | CY7C291A-35LMB | 658 |
| 5962-88734033A | B | 11/02/2000 | 1 | QP SEMI | | | WS57C291C-35ZMB | 658 |
| 5962-88734033C | B | 11/02/2000 | 1 | QP SEMI | | | WS57C291C-35ZMB | 658 |
| 5962-8873403JA | B | 11/02/2000 | 1 | QP SEMI | | | WS57C191C-35YMB | 658 |
| 5962-8873403KA | B | 11/02/2000 | 1 | QP SEMI | | | WS57C191C-35HMB | 658 |
| 5962-8873403LA | B | 11/02/2000 | 2 | QP SEMI | | Y | 7C291A-35DMB | 658 |
| 5962-8873403LA | B | 11/02/2000 | 1 | QP SEMI | | | WS57C291C-35KMB | 658 |
| 5962-88734043A | B | 11/02/2000 | 2 | CYPRESS | 11/08/2004 | Y | CY7C291A-25LMB | 658 |
| 5962-88734043A | B | 11/02/2000 | 1 | QP SEMI | | | WS57C291C-25ZMB | 658 |
| 5962-88734043C | B | 11/02/2000 | 1 | QP SEMI | | | WS57C291C-25ZMB | 658 |
| 5962-8873404JA | B | 11/02/2000 | 1 | QP SEMI | | | WS57C191C-25YMB | 658 |
| 5962-8873404KA | B | 11/02/2000 | 1 | QP SEMI | | | WS57C191C-25HMB | 658 |
| 5962-8873404LA | B | 11/02/2000 | 2 | CYPRESS | | Y | CY7C291A-25DMB | 658 |
| 5962-8873404LA | B | 11/02/2000 | 1 | QP SEMI | | | WS57C291C-25KMB | 658 |
| 5962-88735013A | D | 01/05/2001 | 1 | QP SEMI | | | WS57C45-45ZMB | 658 |
| 5962-88735013C | D | 01/05/2001 | 1 | QP SEMI | | | WS57C45-45ZMB | 658 |
| 5962-8873501KA | D | 01/05/2001 | 1 | QP SEMI | | | WS57C45-45HMB | 658 |
| 5962-8873501LA | D | 01/05/2001 | 1 | QP SEMI | | | WS57C45-45KMB | 658 |
| 5962-88735023A | D | 01/05/2001 | 1 | QP SEMI | | | WS57C45-35ZMB | 658 |
| 5962-88735023C | D | 01/05/2001 | 1 | QP SEMI | | | WS57C45-35ZMB | 658 |
| 5962-8873502KA | D | 01/05/2001 | 1 | QP SEMI | | | WS57C45-35HMB | 658 |
| 5962-8873502LA | D | 01/05/2001 | 1 | QP SEMI | | | WS57C45-35KMB | 658 |
| 5962-88735033A | D | 01/05/2001 | 1 | QP SEMI | | | WS57C45-35ZMB | 658 |
| 5962-88735033C | D | 01/05/2001 | 1 | QP SEMI | | | WS57C45-35ZMB | 658 |
| 5962-8873503KA | D | 01/05/2001 | 1 | QP SEMI | | | WS57C45-35HMB | 658 |
| 5962-8873503LA | D | 01/05/2001 | 1 | QP SEMI | | | WS57C45-35KMB | 658 |
| 5962-88735043A | D | 01/05/2001 | 1 | QP SEMI | | | WS57C45-25ZMB | 658 |
| 5962-88735043C | D | 01/05/2001 | 1 | QP SEMI | | | WS57C45-25ZMB | 658 |
| 5962-8873504KA | D | 01/05/2001 | 1 | QP SEMI | | | WS57C45-25HMB | 658 |
| 5962-8873504LA | D | 01/05/2001 | 2 | CYPRESS | | Y | CY7C245A-25DMB | 658 |
| 5962-8873504LA | D | 01/05/2001 | 1 | QP SEMI | | | WS57C45-25KMB | 658 |
| 5962-88736013A | A | 03/12/1992 | | (NONE) | 04/27/1998 | | 29FCT520A (GEN) | 249 |
| 5962-8873601KA | A | 03/12/1992 | | (NONE) | 04/27/1998 | | 29FCT520A (GEN) | 249 |
| 5962-8873601LA | A | 03/12/1992 | | (NONE) | 04/27/1998 | | 29FCT520A (GEN) | 249 |
| 5962-88736023A | A | 03/12/1992 | | (NONE) | | | 29FCT521A (GEN) | 249 |
| 5962-8873602KA | A | 03/12/1992 | | (NONE) | | | 29FCT521A (GEN) | 249 |
| 5962-8873602LA | A | 03/12/1992 | | (NONE) | | | 29FCT521A (GEN) | 249 |
| 5962-88736033A | A | 03/12/1992 | | (NONE) | 04/27/1998 | | 29FCT520B (GEN) | 249 |
| 5962-8873603KA | A | 03/12/1992 | | (NONE) | 04/27/1998 | | 29FCT520B (GEN) | 249 |
| 5962-8873603LA | A | 03/12/1992 | | (NONE) | 04/28/1998 | | 29FCT520B (GEN) | 249 |
| 5962-88736043A | A | 03/12/1992 | | (NONE) | | | 29FCT521B (GEN) | 249 |
| 5962-8873604KA | A | 03/12/1992 | | (NONE) | | | 29FCT521B (GEN) | 249 |
| 5962-8873604LA | A | 03/12/1992 | | (NONE) | | | 29FCT521B (GEN) | 249 |
| 5962-88737012A | B | 10/17/2000 | 2 | TI | | Y | SNJ54ALS1245AFK | 590 |
| 5962-8873701RA | B | 10/17/2000 | 2 | TI | | Y | SNJ54ALS1245AJ | 590 |
| 5962-88738012A | B | 05/31/2000 | 2 | TI | | Y | SNJ54ALS1244AFK | 529 |
| 5962-8873801RA | B | 05/31/2000 | 2 | TI | | Y | SNJ54ALS1244AJ | 529 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-8873901QA | F | 05/30/2000 | 1 | QP SEMI | | | TMC208K | 208 |
| 5962-8873901XA | F | 05/30/2000 | 1 | QP SEMI | | | TMC208KC2V | 208 |
| 5962-8873902QA | F | 05/30/2000 | 1 | QP SEMI | | | TMC208K | 208 |
| 5962-8873902XA | F | 05/30/2000 | 1 | QP SEMI | | | TMC208KC2V1 | 208 |
| 5962-8873903QA | F | 05/30/2000 | 1 | QP SEMI | | | TMC208KU | 208 |
| 5962-8873903XA | F | 05/30/2000 | 1 | QP SEMI | | | TMC208KU | 208 |
| 5962-8873904QA | F | 05/30/2000 | 1 | QP SEMI | | | TMC208KU | 208 |
| 5962-8873904XA | F | 05/30/2000 | 1 | QP SEMI | | | TMC208KU | 208 |
| 5962-8873905QA | F | 05/30/2000 | 1 | QP SEMI | | | TMC208K | 208 |
| 5962-8873905XA | F | 05/30/2000 | 1 | QP SEMI | | | TMC208K | 208 |
| 5962-8873906QA | F | 05/30/2000 | 1 | QP SEMI | | | TMC208K | 208 |
| 5962-8873906XA | F | 05/30/2000 | 1 | QP SEMI | | | TMC208K | 208 |
| 5962-8873907QA | F | 05/30/2000 | 1 | QP SEMI | | | TMC208KU | 208 |
| 5962-8873907XA | F | 05/30/2000 | 1 | QP SEMI | | | TMC208KU | 208 |
| 5962-8873908QA | F | 05/30/2000 | 1 | QP SEMI | | | TMC208KU | 208 |
| 5962-8873908XA | F | 05/30/2000 | 1 | QP SEMI | | | TMC208KU | 208 |
| 5962-88740013A | C | 01/12/2001 | 1 | PYRAMID | | | P4C116L-35L28MB | 616 |
| 5962-8874001JA | C | 01/12/2001 | 1 | IDT | | Y | 6116LA35DB | 616 |
| 5962-8874001KA | C | 01/12/2001 | 1 | PYRAMID | | | P4C116L-35FMB | 616 |
| 5962-8874001LA | C | 01/12/2001 | 1 | IDT | | Y | 6116LA35TDB | 616 |
| 5962-8874001LA | C | 01/12/2001 | 1 | PYRAMID | | | P4C116L-35DMB | 616 |
| 5962-8874001XA | C | 01/12/2001 | | (NONE) | 05/06/1997 | | 6116LA35 (GEN) | 616 |
| 5962-8874001YA | C | 01/12/2001 | 1 | PYRAMID | | | P4C116L-35LMB | 616 |
| 5962-88740023A | C | 01/12/2001 | 1 | PYRAMID | | | P4C116L-25L28MB | 616 |
| 5962-8874002JA | C | 01/12/2001 | 1 | IDT | | Y | 6116LA25DB | 616 |
| 5962-8874002KA | C | 01/12/2001 | 1 | PYRAMID | | | P4C116L-25FMB | 616 |
| 5962-8874002LA | C | 01/12/2001 | 1 | IDT | | Y | 6116LA25TDB | 616 |
| 5962-8874002LA | C | 01/12/2001 | 1 | PYRAMID | | | P4C116L-25DMB | 616 |
| 5962-8874002XA | C | 01/12/2001 | | (NONE) | 05/06/1997 | | 6116LA25 (GEN) | 616 |
| 5962-8874002YA | C | 01/12/2001 | 1 | PYRAMID | | | P4C116L-25LMB | 616 |
| 5962-88741012A | B | 09/21/2000 | 2 | TI | | Y | SNJ54ALS259FK | 341 |
| 5962-8874101EA | B | 09/21/2000 | 2 | TI | | Y | SNJ54ALS259J | 341 |
| 5962-8874101FA | B | 09/21/2000 | 2 | TI | | Y | SNJ54ALS259W | 341 |
| 5962-88742012A | A | 07/28/2004 | 2 | TI | | Y | SNJ54ALS1035FK | 513 |
| 5962-8874201CA | A | 07/28/2004 | 2 | TI | | Y | SNJ54ALS1035J | 513 |
| 5962-8874201DA | A | 07/28/2004 | 2 | TI | | Y | SNJ54ALS1035W | 513 |
| 5962-88743013A | B | 09/05/1991 | | (NONE) | | | 75C48S20 (GEN) | 592 |
| 5962-8874301XA | B | 09/05/1991 | | (NONE) | | | 75C48S20 (GEN) | 592 |
| 5962-88743023A | B | 09/05/1991 | | (NONE) | | | 75C48SC30 (GEN) | 592 |
| 5962-8874302XA | B | 09/05/1991 | | (NONE) | | | 75C48SC30 (GEN) | 592 |
| 5962-88744012A | D | 03/25/2004 | 3 | TI | | Y | SNJ55113FK | 564 |
| 5962-8874401EA | D | 03/25/2004 | 3 | TI | | Y | SNJ55113J | 564 |
| 5962-8874401FA | D | 03/25/2004 | 3 | TI | | Y | SNJ55113W | 564 |
| 5962-88744022A | D | 03/25/2004 | 2 | TI | | Y | SNJ55114FK | 564 |
| 5962-8874402EA | D | 03/25/2004 | 2 | TI | | Y | SNJ55114J | 564 |
| 5962-8874402FA | D | 03/25/2004 | 2 | TI | | Y | SNJ55114W | 564 |
| 5962-88745012A | B | 04/08/2004 | 1 | TI | | Y | SNJ55115FK | 573 |
| 5962-8874501FA | B | 04/08/2004 | 1 | TI | | Y | SNJ55115W | 573 |
| 5962-88746012A | F | 02/11/2002 | 3 | INTER. RECT. | | | OM1905N2/883B | 783 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-88746012A | F | 02/11/2002 | 3 | MICROSEMI | | Y | SG7905AL/883B | 783 |
| 5962-88746012A | F | 02/11/2002 | 1 | SOLITRON | | | SDP7905A2MD | 783 |
| 5962-88746014A | F | 02/11/2002 | 1 | INTER. RECT. | | | OM7905SRM/883B | 783 |
| 5962-88746015A | F | 02/11/2002 | 1 | INTER. RECT. | | | OM7905N5M/883B | 783 |
| 5962-8874601MA | F | 02/11/2002 | 3 | INTER. RECT. | | | OM1905SM/883B | 783 |
| 5962-8874601NA | F | 02/11/2002 | 1 | INTER. RECT. | | | OM7905NM/883B | 783 |
| 5962-8874601NA | F | 02/11/2002 | 1 | SOLITRON | | | SDP7905ANMD | 783 |
| 5962-8874601TA | F | 02/11/2002 | 0 | INTER. RECT. | | | OM7905AH/883B | 783 |
| 5962-8874601TA | F | 02/11/2002 | 1 | SOLITRON | | | SDP7905ATMD | 783 |
| 5962-8874601UA | F | 02/11/2002 | 0 | INTER. RECT. | | | OM7905AIH/883B | 783 |
| 5962-8874601UA | F | 02/11/2002 | 3 | MICROSEMI | | Y | SG7905AIG/883B | 783 |
| 5962-8874601UA | F | 02/11/2002 | 1 | SOLITRON | | | SDP7905AUMD | 783 |
| 5962F8874601UA | F | 02/11/2002 | 1 | INTER. RECT. | | | OM1905STM/883B | 783 |
| 5962-8874601XA | F | 02/11/2002 | 3 | MICROSEMI | | Y | SG7905AT/883B | 783 |
| 5962-8874601YA | F | 02/11/2002 | 1 | INTER. RECT. | | | OM7905NK/883B | 783 |
| 5962-8874601YA | F | 02/11/2002 | 3 | MICROSEMI | | Y | SG7905AK/883B | 783 |
| 5962-8874601YA | F | 02/11/2002 | 1 | SEMELAB | | Y | IP7905AK-DESC | 783 |
| 5962-8874601ZA | F | 02/11/2002 | 3 | MICROSEMI | | Y | SG7905AR/883B | 783 |
| 5962-8874601ZA | F | 02/11/2002 | 1 | SEMELAB | | Y | IP7905AR-DESC | 783 |
| 5962-8874601ZA | F | 02/11/2002 | 1 | SOLITRON | | | SDP7905AZMD | 783 |
| 5962-88747012A | E | 04/15/2002 | 3 | INTER. RECT. | | | OM1912N2/883B | 783 |
| 5962-88747012A | E | 04/15/2002 | 3 | MICROSEMI | | Y | SG7912AL/883B | 783 |
| 5962-88747012A | E | 04/15/2002 | 1 | SOLITRON | | | SDP7912A2MD | 783 |
| 5962-88747014A | E | 04/15/2002 | 1 | INTER. RECT. | | | OM1912SRM/883B | 783 |
| 5962-88747015A | E | 04/15/2002 | 1 | INTER. RECT. | | | OM1912N5M/883B | 783 |
| 5962-8874701MA | E | 04/15/2002 | 3 | INTER. RECT. | | | OM1912SMM/883B | 783 |
| 5962-8874701NA | E | 04/15/2002 | 1 | INTER. RECT. | | | OM1912NMM/883B | 783 |
| 5962-8874701NA | E | 04/15/2002 | 1 | SOLITRON | | | SDP7912ANMD | 783 |
| 5962-8874701TA | E | 04/15/2002 | 0 | INTER. RECT. | | | OM7912AH/883B | 783 |
| 5962-8874701TA | E | 04/15/2002 | 1 | SEMELAB | | Y | IP7912AG-DESC | 783 |
| 5962-8874701TA | E | 04/15/2002 | 1 | SOLITRON | | | SDP7912ATMD | 783 |
| 5962-8874701UA | E | 04/15/2002 | 3 | INTER. RECT. | | | OM1912STM/883B | 783 |
| 5962-8874701UA | E | 04/15/2002 | 0 | MICROSEMI | | Y | SG7912AIG/883B | 783 |
| 5962-8874701UA | E | 04/15/2002 | 1 | SEMELAB | | Y | IP7912AIG-DESC | 783 |
| 5962-8874701UA | E | 04/15/2002 | 1 | SOLITRON | | | SDP7912AUMD | 783 |
| 5962F8874701UA | E | 04/15/2002 | 3 | INTER. RECT. | | | OMR1912STM/883B | 783 |
| 5962-8874701XA | E | 04/15/2002 | 0 | MICROSEMI | | Y | SG7912AT/883B | 783 |
| 5962-8874701XA | E | 04/15/2002 | 1 | SEMELAB | | Y | IP79M12AH-DESC | 783 |
| 5962-8874701YA | E | 04/15/2002 | 3 | INTER. RECT. | | | OM1912NK/883B | 783 |
| 5962-8874701YA | E | 04/15/2002 | 0 | MICROSEMI | | Y | SG7912AK/883B | 783 |
| 5962-8874701YA | E | 04/15/2002 | 1 | SEMELAB | | Y | IP7912AK-DESC | 783 |
| 5962-8874701ZA | E | 04/15/2002 | 0 | MICROSEMI | | Y | SG7912AR/883B | 783 |
| 5962-8874701ZA | E | 04/15/2002 | 1 | SEMELAB | | Y | IP7912AR-DESC | 783 |
| 5962-8874701ZA | E | 04/15/2002 | 1 | SOLITRON | | | SDP7912AZMD | 783 |
| 5962-88748012A | D | 03/05/2002 | 3 | INTER. RECT. | | | OM1915N2/883B | 783 |
| 5962-88748012A | D | 03/05/2002 | 3 | MICROSEMI | | Y | SG7915AL/883B | 783 |
| 5962-88748012A | D | 03/05/2002 | 1 | SOLITRON | | | SDP7915A2MD | 783 |
| 5962-88748014A | D | 03/05/2002 | 1 | INTER. RECT. | | | OM1915SRM/883B | 783 |
| 5962-88748015A | D | 03/05/2002 | 1 | INTER. RECT. | | | OM1915N5M/883B | 783 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-8874801MA | D | 03/05/2002 | 3 | INTER. RECT. | | | OM1915SM/883B | 783 |
| 5962-8874801NA | D | 03/05/2002 | 3 | INTER. RECT. | | | OM1915NM/883B | 783 |
| 5962-8874801TA | D | 03/05/2002 | 0 | INTER. RECT. | | | OM7915AH/883B | 783 |
| 5962-8874801TA | D | 03/05/2002 | 1 | SEMELAB | | Y | IP7915AG-DESC | 783 |
| 5962-8874801TA | D | 03/05/2002 | 1 | SOLITRON | | | SDP7915ATMD | 783 |
| 5962-8874801UA | D | 03/05/2002 | 0 | INTER. RECT. | | | OM7915AIH/883B | 783 |
| 5962-8874801UA | D | 03/05/2002 | 0 | MICROSEMI | | Y | SG7915AIG/883B | 783 |
| 5962-8874801UA | D | 03/05/2002 | 1 | SEMELAB | | Y | IP7915AIG-DESC | 783 |
| 5962-8874801UA | D | 03/05/2002 | 1 | SOLITRON | | | SDP7915AUMD | 783 |
| 5962F8874801UA | D | 03/05/2002 | 3 | INTER. RECT. | | | OMR1915STM/883B | 783 |
| 5962-8874801XA | D | 03/05/2002 | 0 | MICROSEMI | | Y | SG7915AT/883B | 783 |
| 5962-8874801XA | D | 03/05/2002 | 1 | SEMELAB | | Y | IP79M15AH-DESC | 783 |
| 5962-8874801YA | D | 03/05/2002 | 3 | INTER. RECT. | | | OM1915NK/883B | 783 |
| 5962-8874801YA | D | 03/05/2002 | 0 | MICROSEMI | | Y | SG7915AK/883B | 783 |
| 5962-8874801YA | D | 03/05/2002 | 1 | SEMELAB | | Y | IP7915AK-DESC | 783 |
| 5962-8874801ZA | D | 03/05/2002 | 0 | MICROSEMI | | Y | SG7915AP/883B | 783 |
| 5962-8874801ZA | D | 03/05/2002 | 1 | SEMELAB | | Y | IP7915AR-DESC | 783 |
| 5962-8874801ZA | D | 03/05/2002 | 1 | SOLITRON | | | SDP7915AZMD | 783 |
| 5962-8874901XA | | 08/20/1990 | | (NONE) | | | IP7924 (GEN) | 783 |
| 5962-8874901YA | | 08/20/1990 | | (NONE) | | | IP7924 (GEN) | 783 |
| 5962-8874901ZA | | 08/20/1990 | | (NONE) | | | IP7924 (GEN) | 783 |
| 5962-8875001EA | A | 08/09/2002 | | (NONE) | | | IH5352 (GEN) | 183 |
| 5962-8875101VA | B | 01/11/1993 | | (NONE) | 12/31/2001 | | LT1039 (GEN) | 590 |
| 5962-8875102EA | B | 01/11/1993 | | (NONE) | 03/30/2001 | | LT1039 (GEN) | 590 |
| 5962-88752012A | C | 06/11/2003 | 3 | NATIONAL | | Y | 54F14LMQB | 143 |
| 5962-8875201CA | C | 06/11/2003 | 3 | NATIONAL | | Y | 54F14DMQB | 143 |
| 5962-8875201DA | C | 06/11/2003 | 3 | NATIONAL | | Y | 54F14FMQB | 143 |
| 5962-88753013A | A | 02/19/1992 | 1 | ROCHESTER | | Y | 54AS651/B3A | 590 |
| 5962-8875301KA | A | 02/19/1992 | 1 | ROCHESTER | | Y | 54AS651/BKA | 590 |
| 5962-8875301LA | A | 02/19/1992 | 1 | ROCHESTER | | Y | 54AS651/BLA | 590 |
| 5962-88754012A | B | 09/19/2000 | 3 | NATIONAL | | Y | 54AC299LMQB | 228 |
| 5962-8875401RA | B | 09/19/2000 | 3 | NATIONAL | | Y | 54AC299DMQB | 228 |
| 5962-8875401SA | B | 09/19/2000 | 3 | NATIONAL | | Y | 54AC299FMQB | 228 |
| 5962-8875401VSA | B | 09/19/2000 | | (NONE) | | | 54AC299 (GEN) | 228 |
| 5962-8875401VXA | B | 09/19/2000 | | (NONE) | | | 54AC299 (GEN) | 228 |
| 5962-8875401XA | B | 09/19/2000 | | (NONE) | | | 54AC299 (GEN) | 228 |
| 5962-88755012A | A | 10/25/2002 | 3 | NATIONAL | | Y | 54ACT158LMQB | 275 |
| 5962-8875501EA | A | 10/25/2002 | 3 | NATIONAL | | Y | 54ACT158DMQB | 275 |
| 5962-8875501FA | A | 10/25/2002 | 3 | NATIONAL | | Y | 54ACT158FMQB | 275 |
| 5962-8875502VXA | A | 10/25/2002 | 2 | STMICRO | | Y | 54ACT158K02V | 275 |
| 5962-8875502VXC | A | 10/25/2002 | 2 | STMICRO | | Y | 54ACT158K01V | 275 |
| 5962-8875502XA | A | 10/25/2002 | 2 | STMICRO | | Y | 54ACT158K02Q | 275 |
| 5962-8875502XC | A | 10/25/2002 | 2 | STMICRO | | Y | 54ACT158K01Q | 275 |
| 5962-88756012A | B | 05/06/1998 | | (NONE) | 5962-8875601M2A | | 54ACT151 (GEN) | 271 |
| 5962-8875601B2A | B | 05/06/1998 | | (NONE) | | | 54ACT151 (GEN) | 271 |
| 5962-8875601M2A | B | 05/06/1998 | 3 | NATIONAL | | Y | 54ACT151LMQB | 271 |
| 5962-8875601S2A | B | 05/06/1998 | | (NONE) | | | 54ACT151 (GEN) | 271 |
| 5962R8875601B2A | B | 05/06/1998 | 3 | NATIONAL | | Y | JM54ACT151B2A-R | 271 |
| 5962R8875601S2A | B | 05/06/1998 | 3 | NATIONAL | | Y | JM54ACT151S2A-R | 271 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-8875601BEA | B | 05/06/1998 | | (NONE) | | | 54ACT151 (GEN) | 271 |
| 5962-8875601EA | B | 05/06/1998 | | (NONE) | 5962-8875601MEA | | 54ACT151 (GEN) | 271 |
| 5962-8875601MEA | B | 05/06/1998 | 3 | NATIONAL | | Y | 54ACT151DMQB | 271 |
| 5962-8875601SEA | B | 05/06/1998 | | (NONE) | | | 54ACT151 (GEN) | 271 |
| 5962R8875601BEA | B | 05/06/1998 | 3 | NATIONAL | | Y | JM54ACT151BEA-R | 271 |
| 5962R8875601SEA | B | 05/06/1998 | 3 | NATIONAL | | Y | JM54ACT151SEA-R | 271 |
| 5962-8875601BFA | B | 05/06/1998 | | (NONE) | | | 54ACT151 (GEN) | 271 |
| 5962-8875601FA | B | 05/06/1998 | | (NONE) | 5962-8875601MFA | | 54ACT151 (GEN) | 271 |
| 5962-8875601MFA | B | 05/06/1998 | 3 | NATIONAL | | Y | 54ACT151FMQB | 271 |
| 5962-8875601SFA | B | 05/06/1998 | | (NONE) | | | 54ACT151 (GEN) | 271 |
| 5962R8875601BFA | B | 05/06/1998 | 3 | NATIONAL | | Y | JM54ACT151BFA-R | 271 |
| 5962R8875601SFA | B | 05/06/1998 | 3 | NATIONAL | | Y | JM54ACT151SFA-R | 271 |
| 5962-8875701EA | A | 07/10/1992 | 1 | TI | | Y | CD54HCT4046AF3A | 803 |
| 5962-88758012A | | 04/11/1991 | | (NONE) | | | 54HC4016 (GEN) | 183 |
| 5962-8875801CA | | 04/11/1991 | | (NONE) | | | 54HC4016 (GEN) | 183 |
| 5962-8875901EA | A | 12/11/2001 | 1 | TI | | Y | CD54HCT173F3A | 159 |
| 5962-88760012A | D | 03/13/2002 | 1 | MINCO | | Y | MTL1013AML20 | 710 |
| 5962-88760012A | D | 03/13/2002 | 1 | TI | | Y | LT1013AMFKB | 710 |
| 5962-8876001GA | D | 03/13/2002 | 1 | MINCO | | Y | MTL1013AMH | 710 |
| 5962-8876001PA | D | 03/13/2002 | 1 | MINCO | | Y | MTL1013AMD8 | 710 |
| 5962-8876001PA | D | 03/13/2002 | 1 | TI | | Y | LT1013AMJGB | 710 |
| 5962-88760022A | D | 03/13/2002 | 1 | MINCO | | Y | MTL1013ML20 | 710 |
| 5962-88760022A | D | 03/13/2002 | 1 | TI | | Y | LT1013MFKB | 710 |
| 5962-8876002GA | D | 03/13/2002 | 1 | MINCO | | Y | MTL1013MH | 710 |
| 5962-8876002PA | D | 03/13/2002 | 1 | MINCO | | Y | MTL1013MD8 | 710 |
| 5962-8876002PA | D | 03/13/2002 | 1 | TI | | Y | LT1013MJGB | 710 |
| 5962-8876101EA | A | 07/05/2001 | 1 | NATIONAL | | Y | UA78S40DMQB | 787 |
| 5962-8876201GA | B | 07/28/2004 | 1 | LINEAR TECH. | | Y | LT1021BMH-5/883B | 785 |
| 5962-8876202GA | B | 07/28/2004 | 1 | LINEAR TECH. | | Y | LT1021CMH-5/883B | 785 |
| 5962-8876203GA | B | 07/28/2004 | 1 | LINEAR TECH. | | Y | LT1021DMH-5/883B | 785 |
| 5962-8876301IA | | 01/19/1990 | | (NONE) | | | 1568 (GEN) | 784 |
| 5962-8876302CA | | 01/19/1990 | | (NONE) | | | 1568 (GEN) | 784 |
| 5962-8876401LA | B | 07/08/2004 | 0 | ANALOG (3) | | Y | AD7824TQ/883B | 592 |
| 5962-8876401LA | B | 07/08/2004 | 1 | MAXIM INTEG. | | | MX7824TQ/883B | 592 |
| 5962-8876402LA | B | 07/08/2004 | 0 | ANALOG (3) | | Y | AD7824UQ/883B | 592 |
| 5962-8876402LA | B | 07/08/2004 | 1 | MAXIM INTEG. | | | MX7824UQ/883B | 592 |
| 5962-8876403XA | B | 07/08/2004 | 0 | ANALOG (3) | | Y | AD7828TQ/883B | 592 |
| 5962-8876403XA | B | 07/08/2004 | 1 | MAXIM INTEG. | | | MX7828TQ/883B | 592 |
| 5962-88764043A | B | 07/08/2004 | 0 | ANALOG (3) | | Y | AD7828UE/883B | 592 |
| 5962-8876404XA | B | 07/08/2004 | 0 | ANALOG (3) | | Y | AD7828UQ/883B | 592 |
| 5962-8876404XA | B | 07/08/2004 | 1 | MAXIM INTEG. | | | MX7828UQ/883B | 592 |
| 5962-8876501RA | B | 09/04/2002 | 1 | ANALOG (3) | | Y | AD7549SQ/883B | 591 |
| 5962-8876502RA | B | 09/04/2002 | 1 | ANALOG (3) | | Y | AD7549TQ/883B | 591 |
| 5962-88766013A | A | 07/14/2004 | 3 | ANALOG (3) | | Y | AD7245ATE/883B | 591 |
| 5962-8876601LA | A | 07/14/2004 | 3 | ANALOG (3) | | Y | AD7245ATQ/883B | 591 |
| 5962-8876602RA | A | 07/14/2004 | 3 | ANALOG (3) | | Y | AD7248ATQ/883B | 591 |
| 5962-8876701LA | C | 05/03/2004 | 1 | MAXIM INTEG. | | | MAX502AMRG/883B | 591 |
| 5962-8876702LA | C | 05/03/2004 | 1 | MAXIM INTEG. | | | MAX502BMRG/883B | 591 |
| 5962-8876801PA | F | 05/14/2003 | 1 | AGILENT | | Y | HCPL-5201#200 | 460 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-8876801PC | F | 05/14/2003 | 1 | AGILENT | | Y | HCPL-5201 | 460 |
| 5962-8876801XA | F | 05/14/2003 | 1 | AGILENT | | Y | HCPL-5201#300 | 460 |
| 5962-8876801YA | F | 05/14/2003 | 1 | AGILENT | | Y | HCPL-5201#100 | 460 |
| 5962-8876801YC | F | 05/14/2003 | 1 | AGILENT | | Y | HCPL-5201#100 | 460 |
| 5962-8876802KPA | F | 05/14/2003 | 1 | AGILENT | | Y | HCPL-520K#200 | 460 |
| 5962-8876802KPC | F | 05/14/2003 | 1 | AGILENT | | Y | HCPL-520K | 460 |
| 5962-8876802KXA | F | 05/14/2003 | 1 | AGILENT | | Y | HCPL-520K#300 | 460 |
| 5962-8876802KYA | F | 05/14/2003 | 1 | AGILENT | | Y | HCPL-520K#100 | 460 |
| 5962-8876802KYC | F | 05/14/2003 | 1 | AGILENT | | Y | HCPL-520K#100 | 460 |
| 5962-8876901PA | G | 05/10/1998 | 3 | AGILENT | | Y | HCPL-5231#200 | 460 |
| 5962-8876901PC | G | 05/10/1998 | 3 | AGILENT | | Y | HCPL-5231 | 460 |
| 5962-8876901XA | G | 05/10/1998 | 3 | AGILENT | | Y | HCPL-5231#300 | 460 |
| 5962-8876901YA | G | 05/10/1998 | 3 | AGILENT | | Y | HCPL-5231#100 | 460 |
| 5962-8876901YC | G | 05/10/1998 | 3 | AGILENT | | Y | HCPL-5231#100 | 460 |
| 5962-88769022A | G | 05/10/1998 | 1 | AGILENT | | Y | HCPL-6231 | 460 |
| 5962-8876903FC | G | 05/10/1998 | 3 | AGILENT | | Y | HCPL-6251 | 460 |
| 5962-8876904KPA | G | 05/10/1998 | 3 | AGILENT | | Y | HCPL-523K#200 | 460 |
| 5962-8876904KPC | G | 05/10/1998 | 3 | AGILENT | | Y | HCPL-523K | 460 |
| 5962-8876904KXA | G | 05/10/1998 | 3 | AGILENT | | Y | HCPL-523K#300 | 460 |
| 5962-8876904KYA | G | 05/10/1998 | 3 | AGILENT | | Y | HCPL-523K#100 | 460 |
| 5962-8876904KYC | G | 05/10/1998 | 3 | AGILENT | | Y | HCPL-523K#100 | 460 |
| 5962-8876905K2A | G | 05/10/1998 | 3 | AGILENT | | Y | HCPL-623K | 460 |
| 5962-8876906KFC | G | 05/10/1998 | 3 | AGILENT | | Y | HCPL-625K | 460 |
| 5962-88770012A | H | 07/25/2003 | | (NONE) | | | TSC429 (GEN) | 519 |
| 5962-8877001HA | H | 07/25/2003 | | (NONE) | 03/31/1998 | | MIC429 (GEN) | 519 |
| 5962-8877001PA | H | 07/25/2003 | | (NONE) | 03/31/1998 | | MIC429 (GEN) | 519 |
| 5962-88770022C | H | 07/25/2003 | 1 | MAXIM INTEG. | | | MAX4429MLP/883B | 519 |
| 5962-8877002HA | H | 07/25/2003 | | (NONE) | 03/31/1998 | | MIC4429 (GEN) | 519 |
| 5962-8877002PA | H | 07/25/2003 | 1 | MAXIM INTEG. | | | MAX4429MJA/883B | 519 |
| 5962-88770032C | H | 07/25/2003 | 1 | MAXIM INTEG. | | | MAX4420MLP/883B | 519 |
| 5962-8877003HA | H | 07/25/2003 | | (NONE) | 03/31/1998 | | MIC4420 (GEN) | 519 |
| 5962-8877003PA | H | 07/25/2003 | 1 | MAXIM INTEG. | | | MAX4420MJA/883B | 519 |
| 5962-8877003PA | H | 07/25/2003 | 2 | MICREL | | | MIC4420AJBQ | 519 |
| 5962-8877004HA | H | 07/25/2003 | | (NONE) | 03/31/1998 | | MIC4451 (GEN) | 519 |
| 5962-8877004PA | H | 07/25/2003 | | (NONE) | 03/31/1998 | | MIC4451 (GEN) | 519 |
| 5962-8877005HA | H | 07/25/2003 | | (NONE) | 03/31/1998 | | MIC4452 (GEN) | 519 |
| 5962-8877005PA | H | 07/25/2003 | | (NONE) | 03/31/1998 | | MIC4452 (GEN) | 519 |
| 5962-8877006HA | H | 07/25/2003 | | (NONE) | 03/31/1998 | | MIC44R21 (GEN) | 519 |
| 5962-8877006PA | H | 07/25/2003 | | (NONE) | | | MIC44R21 (GEN) | 519 |
| 5962-8877007HC | H | 07/25/2003 | 1 | INTER. RECT. | | | OM9422SFM | 519 |
| 5962-8877007PA | H | 07/25/2003 | | (NONE) | | | MIC44R22 (GEN) | 519 |
| 5962-88771012A | A | 10/25/2002 | 3 | NATIONAL | | Y | 54ACT299LMQB | 228 |
| 5962-8877101RA | A | 10/25/2002 | 3 | NATIONAL | | Y | 54ACT299DMQB | 228 |
| 5962-8877101SA | A | 10/25/2002 | 3 | NATIONAL | | Y | 54ACT299FMQB | 228 |
| 5962-8877102VXA | A | 10/25/2002 | | (NONE) | | | 54ACT299 (GEN) | 228 |
| 5962-8877102XA | A | 10/25/2002 | | (NONE) | | | 54ACT299 (GEN) | 228 |
| 5962-8877201CA | | 07/24/1989 | | (NONE) | 12/26/1999 | | 8038 (GEN) | 815 |
| 5962-88774012A | A | 11/22/1989 | | (NONE) | 06/01/1997 | | 54F51 (GEN) | 130 |
| 5962-8877401CA | A | 11/22/1989 | | (NONE) | 06/01/1997 | | 54F51 (GEN) | 130 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-8877401DA | A | 11/22/1989 | | (NONE) | 06/01/1997 | | 54F51 (GEN) | 130 |
| 5962-88775013A | A | 08/05/1991 | | (NONE) | 05/27/1997 | | 54FCT646 (GEN) | 590 |
| 5962-8877501KA | A | 08/05/1991 | | (NONE) | 05/27/1997 | | 54FCT646 (GEN) | 590 |
| 5962-8877501LA | A | 08/05/1991 | | (NONE) | 05/27/1997 | | 54FCT646 (GEN) | 590 |
| 5962-88775023A | A | 08/05/1991 | | (NONE) | 05/27/1997 | | 54FCT646A (GEN) | 590 |
| 5962-8877502KA | A | 08/05/1991 | | (NONE) | 05/27/1997 | | 54FCT646A (GEN) | 590 |
| 5962-8877502LA | A | 08/05/1991 | | (NONE) | 05/27/1997 | | 54FCT646A (GEN) | 590 |
| 5962-8877601XA | C | 01/20/2004 | 1 | SATCON | | Y | SP-2069 | 592 |
| 5962-8877601XC | C | 01/20/2004 | 1 | SATCON | | Y | SP-2069 | 592 |
| 5962-88778012A | A | 10/15/2002 | | (NONE) | | | 7645A (GEN) | 591 |
| 5962-8877801RA | A | 10/15/2002 | | (NONE) | | | 7645A (GEN) | 591 |
| 5962-88778022A | A | 10/15/2002 | | (NONE) | | | 7645B (GEN) | 591 |
| 5962-8877802RA | A | 10/15/2002 | | (NONE) | | | 7645B (GEN) | 591 |
| 5962-8943601MRA | | 02/19/1993 | 1 | TI | | Y | CD54HCT299F3A | 228 |
| 5962-89438013A | A | 07/29/2004 | 1 | NATIONAL | | Y | 54F821LMQB | 229 |
| 5962-8943801KA | A | 07/29/2004 | | (NONE) | | | 54F821 (GEN) | 229 |
| 5962-8943801LA | A | 07/29/2004 | 1 | NATIONAL | | Y | 54F821SDMQB | 229 |
| 5962-8944001CA | | 07/19/1994 | | (NONE) | 03/30/2001 | | LT1032 (GEN) | 569 |
| 5962-89441012A | C | 03/29/2002 | 1 | TI | | Y | UC1901L/883B | 899 |
| 5962-8944101CA | C | 03/29/2002 | 1 | TI | | Y | UC1901J/883B | 899 |
| 5962-8944101VCA | C | 03/29/2002 | 1 | TI | | Y | UC1901JQMLV | 899 |
| 5962-89444012A | A | 07/29/2004 | 0 | TI | | | SNJ54LS597FK | 225 |
| 5962-8944401EA | A | 07/29/2004 | 0 | TI | | | SNJ54LS597J | 225 |
| 5962-8944401FA | A | 07/29/2004 | 0 | TI | | | SNJ54LS597W | 225 |
| 5962-8944501JA | | 09/20/1990 | 1 | TI | | Y | CD54HC4059BF3A | 319 |
| 5962-89446013A | | 07/23/1991 | | (NONE) | 12/31/1995 | | TMC2011V (GEN) | 228 |
| 5962-8944601LA | | 07/23/1991 | | (NONE) | 12/31/1995 | | TMC2011V (GEN) | 228 |
| 5962-89446023A | | 07/23/1991 | | (NONE) | 12/31/1995 | | TMC2111V (GEN) | 228 |
| 5962-8944602LA | | 07/23/1991 | | (NONE) | 12/31/1995 | | TMC2111V (GEN) | 228 |
| 5962-8944701HUA | D | 05/18/2001 | | (NONE) | | | ARX3436 (GEN) | 590 |
| 5962-8944701HXA | D | 05/18/2001 | | (NONE) | | | ARX3416 (GEN) | 590 |
| 5962-8944701HYA | D | 05/18/2001 | | (NONE) | | | ARX3416 (GEN) | 590 |
| 5962-8944701HZA | D | 05/18/2001 | | (NONE) | | | ARX3436 (GEN) | 590 |
| 5962-8944702HXA | D | 05/18/2001 | 1 | NATIONAL HYB | | Y | NHI-1501 | 590 |
| 5962-8944702HXC | D | 05/18/2001 | 1 | NATIONAL HYB | | Y | NHI-1501 | 590 |
| 5962-8944702HYA | D | 05/18/2001 | 1 | NATIONAL HYB | | Y | NHI-1501FP | 590 |
| 5962-8944702HYC | D | 05/18/2001 | 1 | NATIONAL HYB | | Y | NHI-1501FP | 590 |
| 5962-8944703HXA | D | 05/18/2001 | 1 | CMAC MICRO. | | Y | FC1553622 | 590 |
| 5962-8944703HXC | D | 05/18/2001 | 1 | CMAC MICRO. | | Y | FC1553622 | 590 |
| 5962-8944703HYA | D | 05/18/2001 | 1 | CMAC MICRO. | | Y | FC1553622FP | 590 |
| 5962-8944703HYC | D | 05/18/2001 | 1 | CMAC MICRO. | | Y | FC1553622FP | 590 |
| 5962-8944704HXC | D | 05/18/2001 | 1 | DDC | | Y | BUS63135II | 590 |
| 5962-8944704HYC | D | 05/18/2001 | 1 | DDC | | Y | BUS63136II | 590 |
| 5962-8944705HXA | D | 05/18/2001 | | (NONE) | | | CT1487-DI (GEN) | 590 |
| 5962-8944706HXA | D | 05/18/2001 | 1 | AEROFLEX | | Y | 3416-511 | 590 |
| 5962-8944706HXC | D | 05/18/2001 | 1 | AEROFLEX | | Y | 3416-511 | 590 |
| 5962-8944707HYA | D | 05/18/2001 | | (NONE) | | | CT1487-DFI (GEN) | 590 |
| 5962-8944708HUA | D | 05/18/2001 | 1 | AEROFLEX | | Y | ACT4436-DI | 590 |
| 5962-8944708HUC | D | 05/18/2001 | 1 | AEROFLEX | | Y | ACT4436-DI | 590 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-8944708HXA | D | 05/18/2001 | 1 | AEROFLEX | | Y | ACT4487-DI | 590 |
| 5962-8944708HXC | D | 05/18/2001 | 1 | AEROFLEX | | Y | ACT4487-DI | 590 |
| 5962-8944708HYA | D | 05/18/2001 | 1 | AEROFLEX | | Y | ACT4487-DFI | 590 |
| 5962-8944708HYC | D | 05/18/2001 | 1 | AEROFLEX | | Y | ACT4487-DFI | 590 |
| 5962-8944708HZA | D | 05/18/2001 | 1 | AEROFLEX | | Y | ACT4436-DFI | 590 |
| 5962-8944708HZC | D | 05/18/2001 | 1 | AEROFLEX | | Y | ACT4436-DFI | 590 |
| 5962-8944901QA | A | 12/16/1994 | | (NONE) | 12/24/1997 | | 80C18710 (GEN) | 409 |
| 5962-8944901XA | A | 12/16/1994 | | (NONE) | 12/24/1997 | | 80C18710 (GEN) | 409 |
| 5962-8944902QA | A | 12/16/1994 | | (NONE) | 12/24/1997 | | 80C18712 (GEN) | 409 |
| 5962-8944902XA | A | 12/16/1994 | | (NONE) | 12/24/1997 | | 80C18712 (GEN) | 409 |
| 5962-8944903QA | A | 12/16/1994 | | (NONE) | 12/24/1997 | | 80C18716 (GEN) | 409 |
| 5962-8944903XA | A | 12/16/1994 | | (NONE) | 12/24/1997 | | 80C18716 (GEN) | 409 |
| 5962-8945801EA | | 10/04/1990 | 1 | TI | | Y | CD54HCT4020F3A | 305 |
| 5962-8946201MUA | A | 11/19/1993 | 1 | ATMEL GREN. | | | TS68C000MR1B/C8A | 403 |
| 5962-8946201MUC | A | 11/19/1993 | 1 | ATMEL GREN. | | | TS68C000MRB/C8A | 403 |
| 5962-8946201MXA | A | 11/19/1993 | 1 | ATMEL GREN. | | | TS68C000ME1B/C8A | 403 |
| 5962-8946201MYA | A | 11/19/1993 | 1 | ATMEL GREN. | | | TS68C000MC1B/C8A | 403 |
| 5962-8946201MYC | A | 11/19/1993 | 1 | ATMEL GREN. | | | TS68C000MCB/C8A | 403 |
| 5962-8946201MZA | A | 11/19/1993 | 1 | ATMEL GREN. | | | TS68C000MF1B/C8A | 403 |
| 5962-8946201MZC | A | 11/19/1993 | 1 | ATMEL GREN. | | | TS68C000MFB/C8A | 403 |
| 5962-8946202MUA | A | 11/19/1993 | 1 | ATMEL GREN. | | | TS68C000MR1B/C10A | 403 |
| 5962-8946202MUC | A | 11/19/1993 | 1 | ATMEL GREN. | | | TS68C000MRB/C10A | 403 |
| 5962-8946202MXA | A | 11/19/1993 | 1 | ATMEL GREN. | | | TS68C000ME1B/C10A | 403 |
| 5962-8946202MYA | A | 11/19/1993 | 1 | ATMEL GREN. | | | TS68C000MC1B/C10A | 403 |
| 5962-8946202MYC | A | 11/19/1993 | 1 | ATMEL GREN. | | | TS68C000MCB/C10A | 403 |
| 5962-8946202MZA | A | 11/19/1993 | 1 | ATMEL GREN. | | | TS68C000MF1B/C10A | 403 |
| 5962-8946202MZC | A | 11/19/1993 | 1 | ATMEL GREN. | | | TS68C000MFB/C10A | 403 |
| 5962-8946203MUA | A | 11/19/1993 | 1 | ATMEL GREN. | | | TS68C000MR1B/C12A | 403 |
| 5962-8946203MUC | A | 11/19/1993 | 1 | ATMEL GREN. | | | TS68C000MRB/C12A | 403 |
| 5962-8946203MXA | A | 11/19/1993 | 1 | ATMEL GREN. | | | TS68C000ME1B/C12A | 403 |
| 5962-8946203MYA | A | 11/19/1993 | 1 | ATMEL GREN. | | | TS68C000MC1B/C12A | 403 |
| 5962-8946203MYC | A | 11/19/1993 | 1 | ATMEL GREN. | | | TS68C000MCB/C12A | 403 |
| 5962-8946203MZA | A | 11/19/1993 | 1 | ATMEL GREN. | | | TS68C000MF1B/C12A | 403 |
| 5962-8946203MZC | A | 11/19/1993 | 1 | ATMEL GREN. | | | TS68C000MFB/C12A | 403 |
| 5962-8946204MUA | A | 11/19/1993 | | (NONE) | 09/30/1995 | | 68HC001-8 (GEN) | 409 |
| 5962-8946205MUA | A | 11/19/1993 | | (NONE) | 09/30/1995 | | 68HC001-10 (GEN) | 409 |
| 5962-8946206MUA | A | 11/19/1993 | | (NONE) | 09/30/1995 | | 68HC001-12 (GEN) | 409 |
| 5962-8946301XA | C | 05/04/2000 | 1 | ATMEL GREN. | | Y | TS68882MR1B/C16 | 403 |
| 5962-8946301XC | C | 05/04/2000 | 1 | ATMEL GREN. | | Y | TS68882MRB/C16 | 403 |
| 5962-8946301YA | C | 05/04/2000 | 1 | ATMEL GREN. | | Y | TS68882MF1B/C16 | 403 |
| 5962-8946301YC | C | 05/04/2000 | 1 | ATMEL GREN. | | Y | TS68882MFB/C16 | 403 |
| 5962-8946302XA | C | 05/04/2000 | 1 | ATMEL GREN. | | Y | TS68882MR1B/C20 | 403 |
| 5962-8946302XC | C | 05/04/2000 | 1 | ATMEL GREN. | | Y | TS68882MRB/C20 | 403 |
| 5962-8946302YA | C | 05/04/2000 | 1 | ATMEL GREN. | | Y | TS68882MF1B/C20 | 403 |
| 5962-8946302YC | C | 05/04/2000 | 1 | ATMEL GREN. | | Y | TS68882MFB/C20 | 403 |
| 5962-8946303XA | C | 05/04/2000 | 1 | ATMEL GREN. | | Y | TS68882MR1B/C25 | 403 |
| 5962-8946303XC | C | 05/04/2000 | 1 | ATMEL GREN. | | Y | TS68882MRB/C25 | 403 |
| 5962-8946303YA | C | 05/04/2000 | 1 | ATMEL GREN. | | Y | TS68882MF1B/C25 | 403 |
| 5962-8946303YC | C | 05/04/2000 | 1 | ATMEL GREN. | | Y | TS68882MFB/C25 | 403 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-8946304XA | C | 05/04/2000 | | ATMEL GREN. | | Y | TS68882MR1B/C33 | 403 |
| 5962-8946304XC | C | 05/04/2000 | | ATMEL GREN. | | Y | TS68882MRB/C33 | 403 |
| 5962-8946304YA | C | 05/04/2000 | | ATMEL GREN. | | Y | TS68882MF1B/C33 | 403 |
| 5962-8946304YC | C | 05/04/2000 | | ATMEL GREN. | | Y | TS68882MFB/C33 | 403 |
| 5962-8946401XA | B | 07/29/1994 | | (NONE) | 09/30/1995 | | 68030-16 (GEN) | 404 |
| 5962-8946401YC | B | 07/29/1994 | | (NONE) | 09/30/1995 | | 68030-16 (GEN) | 404 |
| 5962-8946402XA | B | 07/29/1994 | | (NONE) | 09/30/1995 | | 68030-20 (GEN) | 404 |
| 5962-8946402YC | B | 07/29/1994 | | (NONE) | 09/30/1995 | | 68030-20 (GEN) | 404 |
| 5962-8946403XA | B | 07/29/1994 | | (NONE) | 09/30/1995 | | 68030-25 (GEN) | 404 |
| 5962-8946403YC | B | 07/29/1994 | | (NONE) | 09/30/1995 | | 68030-25 (GEN) | 404 |
| 5962-8946404XA | B | 07/29/1994 | | (NONE) | 09/30/1995 | | 68030-33 (GEN) | 404 |
| 5962-8946404YC | B | 07/29/1994 | | (NONE) | 09/30/1995 | | 68030-33 (GEN) | 404 |
| 5962-89466012A | | 02/26/1991 | | (NONE) | | | 54F620 (GEN) | 590 |
| 5962-8946601RA | | 02/26/1991 | | (NONE) | | | 54F620 (GEN) | 590 |
| 5962-8946601SA | | 02/26/1991 | | (NONE) | | | 54F620 (GEN) | 590 |
| 5962-8946801XC | B | 02/26/1997 | 1 | CYPRESS | 05/03/2004 | Y | CY7C342B-35RMB | 431 |
| 5962-8946801XC | B | 02/26/1997 | 1 | QP SEMI | | Y | CY7C342B-35RMB | 431 |
| 5962-8946801YA | B | 02/26/1997 | 1 | CYPRESS | 05/03/2004 | Y | CY7C342B-35HMB | 431 |
| 5962-8946801YA | B | 02/26/1997 | 1 | QP SEMI | | Y | CY7C342B-35HMB | 431 |
| 5962-8946801ZA | B | 02/26/1997 | | (NONE) | 03/05/1996 | | 7C342B-35 (GEN) | 431 |
| 5962-8946802XC | B | 02/26/1997 | 1 | QP SEMI | | Y | CY7C342B-30RMB | 431 |
| 5962-8946802YA | B | 02/26/1997 | 1 | QP SEMI | | Y | CY7C342B-30HMB | 431 |
| 5962-8946802ZA | B | 02/26/1997 | | (NONE) | | | 7C342-30 (GEN) | 431 |
| 5962-8946803XC | B | 02/26/1997 | 1 | QP SEMI | | Y | CY7C342B-25RMB | 431 |
| 5962-8946803YA | B | 02/26/1997 | 1 | QP SEMI | | Y | CY7C342B-25HMB | 431 |
| 5962-8946803ZA | B | 02/26/1997 | | (NONE) | | | 7C342B-25 (GEN) | 431 |
| 5962-8946804XC | B | 02/26/1997 | 1 | QP SEMI | | Y | CY7C342B-20RMB | 431 |
| 5962-8946804YA | B | 02/26/1997 | 1 | QP SEMI | | Y | CY7C342B-20HMB | 431 |
| 5962-8946804ZA | B | 02/26/1997 | | (NONE) | | | 7C342B-20 (GEN) | 431 |
| 5962-8946805XC | B | 02/26/1997 | 1 | QP SEMI | | Y | CY7C342B-15RMB | 431 |
| 5962-8946805YA | B | 02/26/1997 | 1 | QP SEMI | | Y | CY7C342B-15HMB | 431 |
| 5962-8946901XA | B | 04/21/1994 | | (NONE) | | | | 431 |
| 5962-8946901YC | B | 04/21/1994 | | (NONE) | 10/31/1996 | | 1810 (GEN) | 431 |
| 5962-8947601LA | | 11/17/1992 | | (NONE) | 10/31/1996 | | 610 (GEN) | 431 |
| 5962-8947601XA | | 11/17/1992 | | (NONE) | | | | 431 |
| 5962-8947602LA | | 11/17/1992 | | (NONE) | 06/30/1995 | | EP610-25 (GEN) | 431 |
| 5962-8947603LA | | 11/17/1992 | | (NONE) | 06/30/1995 | | EP610-15 (GEN) | 431 |
| 5962-8947701PA | D | 06/14/2001 | 2 | AGILENT | | Y | HCPL-5761#200 | 460 |
| 5962-8947701PC | D | 06/14/2001 | 2 | AGILENT | | Y | HCPL-5761 | 460 |
| 5962-8947701XA | D | 06/14/2001 | 2 | AGILENT | | Y | HCPL-5761#300 | 460 |
| 5962-8947701YA | D | 06/14/2001 | 2 | AGILENT | | Y | HCPL-5761#100 | 460 |
| 5962-8947701YC | D | 06/14/2001 | 2 | AGILENT | | Y | HCPL-5761#100 | 460 |
| 5962-8947702KPA | D | 06/14/2001 | 2 | AGILENT | | Y | HCPL-576K#200 | 460 |
| 5962-8947702KPC | D | 06/14/2001 | 2 | AGILENT | | Y | HCPL-576K | 460 |
| 5962-8947702KXA | D | 06/14/2001 | 2 | AGILENT | | Y | HCPL-576K#300 | 460 |
| 5962-8947702KYA | D | 06/14/2001 | 2 | AGILENT | | Y | HCPL-576K#100 | 460 |
| 5962-8947702KYC | D | 06/14/2001 | 2 | AGILENT | | Y | HCPL-576K#100 | 460 |
| 5962-8947901V2A | C | 04/22/2002 | 2 | ANALOG (5) | | Y | REF10ARC/QMLV | 785 |
| 5962R8947901V2A | C | 04/22/2002 | 2 | ANALOG (5) | | Y | REF10ARC/QMLR | 785 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-8947901GA | C | 04/22/2002 | | (NONE) | | | REF10A (GEN) | 785 |
| 5962-8947901VGA | C | 04/22/2002 | 2 | ANALOG (5) | | Y | REF10AJ/QMLV | 785 |
| 5962R8947901VGA | C | 04/22/2002 | 2 | ANALOG (5) | | Y | REF10AJ/QMLR | 785 |
| 5962-8947901VHA | C | 04/22/2002 | 2 | ANALOG (5) | | Y | REF10AL/QMLV | 785 |
| 5962R8947901VHA | C | 04/22/2002 | 2 | ANALOG (5) | | Y | REF10AL/QMLR | 785 |
| 5962-8947901VPA | C | 04/22/2002 | 2 | ANALOG (5) | | Y | REF10AZ/QMLV | 785 |
| 5962R8947901VPA | C | 04/22/2002 | 2 | ANALOG (5) | | Y | REF10AZ/QMLR | 785 |
| 5962-8947902GA | C | 04/22/2002 | | (NONE) | 04/14/2001 | | REF10B (GEN) | 785 |
| 5962-89481012C | | 03/23/1990 | 1 | MAXIM INTEG. | | | MX7541ASE/883B | 591 |
| 5962-8948101VA | | 03/23/1990 | 1 | MAXIM INTEG. | | | MX7541ASQ/883B | 591 |
| 5962-89481022A | | 03/23/1990 | 1 | ANALOG (3) | | Y | AD7541ATE/883B | 591 |
| 5962-89481022C | | 03/23/1990 | 1 | MAXIM INTEG. | | | MX7541ATE/883B | 591 |
| 5962-8948102VA | | 03/23/1990 | 1 | ANALOG (3) | | Y | AD7541ATQ/883B | 591 |
| 5962-8948102VA | | 03/23/1990 | 1 | MAXIM INTEG. | | | MX7541ATQ/883B | 591 |
| 5962-89481032A | | 03/23/1990 | | (NONE) | | | PM7541AB (GEN) | 591 |
| 5962-8948103VA | | 03/23/1990 | | (NONE) | | | PM7541AB (GEN) | 591 |
| 5962-8948104VA | | 03/23/1990 | | (NONE) | | | PM7541AA (GEN) | 591 |
| 5962-8948301LA | D | 04/16/1996 | | (NONE) | 03/30/2001 | | LTC1064 (GEN) | 899 |
| 5962-8948401M3A | | 12/30/1993 | 3 | QP SEMI | | Y | CY7C265-50QMB | 660 |
| 5962-8948401MXA | | 12/30/1993 | 3 | QP SEMI | | Y | CY7C265-50WMB | 660 |
| 5962-8948401MYA | | 12/30/1993 | | (NONE) | 05/10/1995 | | 7C265-50 (GEN) | 660 |
| 5962-8948402M3A | | 12/30/1993 | 3 | QP SEMI | | Y | CY7C265-25QMB | 660 |
| 5962-8948402MXA | | 12/30/1993 | 3 | QP SEMI | | Y | CY7C265-25WMB | 660 |
| 5962-8948402MYA | | 12/30/1993 | | (NONE) | 05/10/1995 | | 7C265-25 (GEN) | 660 |
| 5962-8948403M3A | | 12/30/1993 | 3 | QP SEMI | | Y | CY7C265-15QMB | 660 |
| 5962-8948403MXA | | 12/30/1993 | 3 | QP SEMI | | Y | CY7C265-15WMB | 660 |
| 5962-8948403MYA | | 12/30/1993 | | (NONE) | 05/10/1995 | | 7C265-15 (GEN) | 660 |
| 5962-89487012A | A | 05/22/2001 | 3 | NATIONAL | | Y | 54F132LMQB | 100 |
| 5962-8948701CA | A | 05/22/2001 | 3 | NATIONAL | | Y | 54F132DMQB | 100 |
| 5962-8948701DA | A | 05/22/2001 | | (NONE) | | | 54F132 (GEN) | 100 |
| 5962-8949001XA | A | 06/02/1992 | 1 | SOLITRON | | Y | SD11089XHD | 789 |
| 5962-8949001XC | A | 06/02/1992 | 1 | SOLITRON | | Y | SD11089XHG | 789 |
| 5962-8949002XA | A | 06/02/1992 | 1 | INTER. RECT. | | Y | OM7501SC/883B | 789 |
| 5962-8949002XA | A | 06/02/1992 | 1 | SOLITRON | | Y | SD11081XHD | 789 |
| 5962-8949002XC | A | 06/02/1992 | 1 | SOLITRON | | Y | SD11081XHG | 789 |
| 5962-8949003XA | A | 06/02/1992 | 1 | INTER. RECT. | | Y | OM7502SC/883B | 789 |
| 5962-8949003XA | A | 06/02/1992 | 1 | SOLITRON | | Y | SD11082XHD | 789 |
| 5962-8949003XC | A | 06/02/1992 | 1 | SOLITRON | | Y | SD11082XHG | 789 |
| 5962-8949004XA | A | 06/02/1992 | 1 | INTER. RECT. | | Y | OM7503SC/883B | 789 |
| 5962-8949004XA | A | 06/02/1992 | 1 | SOLITRON | | Y | SD11083XHD | 789 |
| 5962-8949004XC | A | 06/02/1992 | 1 | SOLITRON | | Y | SD11083XHG | 789 |
| 5962-8949005XA | A | 06/02/1992 | 1 | INTER. RECT. | | Y | OM7504SC/883B | 789 |
| 5962-8949005XA | A | 06/02/1992 | 1 | SOLITRON | | Y | SD11084XHD | 789 |
| 5962-8949005XC | A | 06/02/1992 | 1 | SOLITRON | | Y | SD11084XHG | 789 |
| 5962-8949006XA | A | 06/02/1992 | 1 | INTER. RECT. | | Y | OM7505SC/883B | 789 |
| 5962-8949006XA | A | 06/02/1992 | 1 | SOLITRON | | Y | SD11085XHD | 789 |
| 5962-8949006XC | A | 06/02/1992 | 1 | SOLITRON | | Y | SD11085XHG | 789 |
| 5962-8949007XA | A | 06/02/1992 | 1 | INTER. RECT. | | Y | OM7506SC/883B | 789 |
| 5962-8949007XA | A | 06/02/1992 | 1 | SOLITRON | | Y | SD11086XHD | 789 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-8949007XC | A | 06/02/1992 | 1 | SOLITRON | | Y | SD11086XHG | 789 |
| 5962-8949008XA | A | 06/02/1992 | 1 | SOLITRON | | Y | SD11087XHD | 789 |
| 5962-8949008XC | A | 06/02/1992 | 1 | SOLITRON | | Y | SD11087XHG | 789 |
| 5962-8949009XA | A | 06/02/1992 | 1 | SOLITRON | | Y | SD11088XHD | 789 |
| 5962-8949009XC | A | 06/02/1992 | 1 | SOLITRON | | Y | SD11088XHG | 789 |
| 5962-8949201EA | | 04/04/1991 | | (NONE) | | | 54HC423A (GEN) | 166 |
| 5962-89494012A | C | 06/18/2001 | | (NONE) | | | TLC272 (GEN) | 710 |
| 5962-8949401HA | C | 06/18/2001 | | (NONE) | | | TLC272 (GEN) | 710 |
| 5962-8949401PA | C | 06/18/2001 | | (NONE) | | | TLC272 (GEN) | 710 |
| 5962-89494022A | C | 06/18/2001 | | (NONE) | | | TLC277 (GEN) | 710 |
| 5962-8949402HA | C | 06/18/2001 | | (NONE) | | | TLC277 (GEN) | 710 |
| 5962-8949402PA | C | 06/18/2001 | | (NONE) | | | TLC277 (GEN) | 710 |
| 5962-89494032A | C | 06/18/2001 | | (NONE) | | | TLC27L2 (GEN) | 710 |
| 5962-8949403HA | C | 06/18/2001 | | (NONE) | | | TLC27L2 (GEN) | 710 |
| 5962-8949403PA | C | 06/18/2001 | | (NONE) | | | TLC27L2 (GEN) | 710 |
| 5962-89494042A | C | 06/18/2001 | | (NONE) | | | TLC27L7 (GEN) | 710 |
| 5962-8949404HA | C | 06/18/2001 | | (NONE) | | | TLC27L7 (GEN) | 710 |
| 5962-8949404PA | C | 06/18/2001 | | (NONE) | | | TLC27L7 (GEN) | 710 |
| 5962-89494052A | C | 06/18/2001 | | (NONE) | | | TLC27M2 (GEN) | 710 |
| 5962-8949405HA | C | 06/18/2001 | | (NONE) | | | TLC27M2 (GEN) | 710 |
| 5962-8949405PA | C | 06/18/2001 | | (NONE) | | | TLC27M2 (GEN) | 710 |
| 5962-89494062A | C | 06/18/2001 | | (NONE) | | | TLC27M7 (GEN) | 710 |
| 5962-8949406HA | C | 06/18/2001 | | (NONE) | | | TLC27M7 (GEN) | 710 |
| 5962-8949406PA | C | 06/18/2001 | | (NONE) | | | TLC27M7 (GEN) | 710 |
| 5962-8949701MTA | A | 11/01/1994 | | (NONE) | | | | 625 |
| 5962-8949701MUA | A | 11/01/1994 | | (NONE) | | | | 625 |
| 5962-8949701MXA | A | 11/01/1994 | | (NONE) | | | | 625 |
| 5962-8949701MYA | A | 11/01/1994 | | (NONE) | | | | 625 |
| 5962-8949701MZA | A | 11/01/1994 | | (NONE) | | | | 625 |
| 5962-8949702MTA | A | 11/01/1994 | | (NONE) | | | | 625 |
| 5962-8949702MUA | A | 11/01/1994 | | (NONE) | | | | 625 |
| 5962-8949702MXA | A | 11/01/1994 | | (NONE) | | | | 625 |
| 5962-8949702MYA | A | 11/01/1994 | | (NONE) | | | | 625 |
| 5962-8949702MZA | A | 11/01/1994 | | (NONE) | | | | 625 |
| 5962-8949703MMA | A | 11/01/1994 | 2 | AUSTIN SEMI. | | Y | SMJ44C251B-12SVM | 625 |
| 5962-8949703MMA | A | 11/01/1994 | 1 | AUSTIN SEMI. | | Y | MT42C4256CZ-12/883C | 625 |
| 5962-8949703MTA | A | 11/01/1994 | 1 | AUSTIN SEMI. | | Y | MT42C4256DCJ-12/883 | 625 |
| 5962-8949703MUA | A | 11/01/1994 | 1 | AUSTIN SEMI. | | Y | MT42C4256F-12/883C | 625 |
| 5962-8949703MXA | A | 11/01/1994 | 1 | AUSTIN SEMI. | | Y | MT42C4256C-12/883C | 625 |
| 5962-8949703MXA | A | 11/01/1994 | 2 | AUSTIN SEMI. | | Y | SMJ44C251B-12JDM | 625 |
| 5962-8949703MYA | A | 11/01/1994 | 2 | AUSTIN SEMI. | | Y | SMJ44C251B-12HJM | 625 |
| 5962-8949703MZA | A | 11/01/1994 | 1 | AUSTIN SEMI. | | Y | MT42C4256EC-12/883C | 625 |
| 5962-8949703MZA | A | 11/01/1994 | 2 | AUSTIN SEMI. | | Y | SMJ44C251B-12HMM | 625 |
| 5962-8949704MMA | A | 11/01/1994 | 2 | AUSTIN SEMI. | | Y | SMJ44C251B-10SVM | 625 |
| 5962-8949704MMA | A | 11/01/1994 | 1 | AUSTIN SEMI. | | Y | MT42C4256CZ-10/883C | 625 |
| 5962-8949704MTA | A | 11/01/1994 | 1 | AUSTIN SEMI. | | Y | MT42C4256DCJ-10/883 | 625 |
| 5962-8949704MUA | A | 11/01/1994 | 1 | AUSTIN SEMI. | | Y | MT42C4256F-10/883C | 625 |
| 5962-8949704MXA | A | 11/01/1994 | 1 | AUSTIN SEMI. | | Y | MT42C4256C-10/883C | 625 |
| 5962-8949704MXA | A | 11/01/1994 | 2 | AUSTIN SEMI. | | Y | SMJ44C251B-10JDM | 625 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-8949704MYA | A | 11/01/1994 | 2 | AUSTIN SEMI. | | Y | SMJ44C251B-10HJM | 625 |
| 5962-8949704MZA | A | 11/01/1994 | 2 | AUSTIN SEMI. | | Y | SMJ44C251B-10HMM | 625 |
| 5962-8949704MZA | A | 11/01/1994 | 1 | AUSTIN SEMI. | | Y | MT42C4256EC-10/883C | 625 |
| 5962-8949801XA | F | 09/04/2002 | 1 | DDC | | Y | SDC-14561V-144 | 594 |
| 5962-8949801XA | F | 09/04/2002 | 1 | DDC IRELAND | | Y | SDC-14561V-144 | 594 |
| 5962-8949801XC | F | 09/04/2002 | 1 | DDC | | Y | SDC-14561V-114 | 594 |
| 5962-8949801XC | F | 09/04/2002 | 1 | DDC IRELAND | | Y | SDC-14561V-114 | 594 |
| 5962-8949801YA | F | 09/04/2002 | | (NONE) | | | 14561-603 (GEN) | 594 |
| 5962-8949802XA | F | 09/04/2002 | 1 | DDC | | Y | SDC-14561V-145 | 594 |
| 5962-8949802XA | F | 09/04/2002 | 1 | DDC IRELAND | | Y | SDC-14561V-145 | 594 |
| 5962-8949802XC | F | 09/04/2002 | 1 | DDC | | Y | SDC-14561V-115 | 594 |
| 5962-8949802XC | F | 09/04/2002 | 1 | DDC IRELAND | | Y | SDC-14561V-115 | 594 |
| 5962-8949802YA | F | 09/04/2002 | | (NONE) | | | 14561-604 (GEN) | 594 |
| 5962-8949803XC | F | 09/04/2002 | | (NONE) | | | 1066-349H/2 (GEN) | 594 |
| 5962-8949804XC | F | 09/04/2002 | | (NONE) | | | 1066-349V/2 (GEN) | 594 |
| 5962-8949805XA | F | 09/04/2002 | 1 | DDC | | Y | SDC-14562V-144 | 594 |
| 5962-8949805XA | F | 09/04/2002 | 1 | DDC IRELAND | | Y | SDC-14562V-144 | 594 |
| 5962-8949805XC | F | 09/04/2002 | 1 | DDC | | Y | SDC-14562V-114 | 594 |
| 5962-8949805XC | F | 09/04/2002 | 1 | DDC IRELAND | | Y | SDC-14562V-114 | 594 |
| 5962-8949805YA | F | 09/04/2002 | | (NONE) | | | 14562-114 (GEN) | 594 |
| 5962-8949901XA | J | 09/20/2002 | 1 | DDC | | Y | SDC14560-144 | 594 |
| 5962-8949901XA | J | 09/20/2002 | 1 | DDC IRELAND | | Y | SDC14560-114 | 594 |
| 5962-8949901XC | J | 09/20/2002 | 1 | DDC | | Y | SDC14560-114 | 594 |
| 5962-8949901XC | J | 09/20/2002 | 1 | DDC IRELAND | | Y | SDC14560-114 | 594 |
| 5962-8949901YA | J | 09/20/2002 | | (NONE) | | | 14560-144 (GEN) | 594 |
| 5962-8949901YC | J | 09/20/2002 | | (NONE) | | | 14560-114 (GEN) | 594 |
| 5962-8949902XA | J | 09/20/2002 | 1 | DDC | | Y | SDC14560-145 | 594 |
| 5962-8949902XA | J | 09/20/2002 | 1 | DDC IRELAND | | Y | SDC14560-115 | 594 |
| 5962-8949902XC | J | 09/20/2002 | 1 | DDC | | Y | SDC14560-115 | 594 |
| 5962-8949902XC | J | 09/20/2002 | 1 | DDC IRELAND | | Y | SDC14560-115 | 594 |
| 5962-8949902YA | J | 09/20/2002 | | (NONE) | | | 14560-145 (GEN) | 594 |
| 5962-8949902YC | J | 09/20/2002 | | (NONE) | | | 14560-115 (GEN) | 594 |
| 5962-8949903XA | J | 09/20/2002 | 1 | DDC IRELAND | | Y | SDC14560-605 | 594 |
| 5962-8949903XC | J | 09/20/2002 | 1 | DDC | | Y | SDC14560-605 | 594 |
| 5962-8949903XC | J | 09/20/2002 | 1 | DDC IRELAND | | Y | SDC14560-605 | 594 |
| 5962-8949903YA | J | 09/20/2002 | | (NONE) | | | 14560III-605 (GEN) | 594 |
| 5962-8949903YC | J | 09/20/2002 | | (NONE) | | | 14560III-605 (GEN) | 594 |
| 5962-8949904XC | J | 09/20/2002 | | (NONE) | | | 1066-341H/2 (GEN) | 594 |
| 5962-8949905XC | J | 09/20/2002 | | (NONE) | | | 1066-341V/2 (GEN) | 594 |
| 5962-8949906XC | J | 09/20/2002 | | (NONE) | | | 1066-C778H/2 (GEN) | 594 |
| 5962-8949907XA | J | 09/20/2002 | 1 | DDC | | Y | SDC-14560-142 | 594 |
| 5962-8949907XC | J | 09/20/2002 | 1 | DDC | | Y | SDC-14560-112 | 594 |
| 5962-8949907YA | J | 09/20/2002 | | (NONE) | | | 14560-142 (GEN) | 594 |
| 5962-8949907YC | J | 09/20/2002 | | (NONE) | | | 14560-112 (GEN) | 594 |
| 5962-8949908XA | J | 09/20/2002 | 1 | DDC | | Y | SDC-14560-141 | 594 |
| 5962-8949908XC | J | 09/20/2002 | 1 | DDC | | Y | SDC-14560-111 | 594 |
| 5962-8949908YA | J | 09/20/2002 | | (NONE) | | | 14560-141 (GEN) | 594 |
| 5962-8949908YC | J | 09/20/2002 | | (NONE) | | | 14560 (GEN) | 594 |
| 5962-8950101XA | C | 05/02/2001 | 1 | UTMC | | Y | UT1553BCRTMPG | 590 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-8950101XC | C | 05/02/2001 | 1 | UTMC | | Y | UT1553BCRTMPG | 590 |
| 5962-8950101YC | C | 05/02/2001 | 1 | UTMC | | Y | UT1553BCRTMPA | 590 |
| 5962-89502012A | C | 07/03/2002 | 1 | INTERSIL | 10/05/2004 | Y | HA4-2544/883 | 760 |
| 5962-8950201GC | C | 07/03/2002 | 1 | INTERSIL | | Y | HA2-2544/883 | 760 |
| 5962-8950201PA | C | 07/03/2002 | 1 | INTERSIL | | Y | HA7-2544/883 | 760 |
| 5962-89503012A | G | 12/21/2000 | | TI | | Y | TLC555MFKB | 814 |
| 5962-8950301PA | G | 12/21/2000 | | TI | | Y | TLC555MJGB | 814 |
| 5962-89503022A | G | 12/21/2000 | | TI | | Y | TLC556MFKB | 814 |
| 5962-8950302CA | G | 12/21/2000 | | TI | | Y | TLC556MJB | 814 |
| 5962-8950303GC | G | 12/21/2000 | | (NONE) | | | 7555 (GEN) | 814 |
| 5962-8950303PA | G | 12/21/2000 | | (NONE) | | | 7555 (GEN) | 814 |
| 5962-8950304CA | G | 12/21/2000 | | (NONE) | | | 7556 (GEN) | 814 |
| 5962-8950305CA | G | 12/21/2000 | | (NONE) | | | LMC555 (GEN) | 814 |
| 5962-8950305GA | G | 12/21/2000 | | (NONE) | 02/27/1998 | | LMC555 (GEN) | 814 |
| 5962-8950305PA | G | 12/21/2000 | 1 | NATIONAL | | Y | LMC555J/883C | 814 |
| 5962-8950401GA | A | 01/30/1996 | 1 | MINCO | | Y | MTL1017MH/883 | 773 |
| 5962-8950401GC | A | 01/30/1996 | 1 | MINCO | | Y | MTL1017MH/883 | 773 |
| 5962-8950401PA | A | 01/30/1996 | 1 | MINCO | | Y | MTL1017MJ8/883 | 773 |
| 5962-8950401PA | A | 01/30/1996 | 1 | MINCO | | Y | MTL1017MD8/883 | 773 |
| 5962-8950401PC | A | 01/30/1996 | 1 | MINCO | | Y | MTL1017MD8/883 | 773 |
| 5962-8950401PC | A | 01/30/1996 | 1 | MINCO | | Y | MTL1017MJ8/883 | 773 |
| 5962-8950402GA | A | 01/30/1996 | 1 | MINCO | | Y | MTL1018MH/883 | 773 |
| 5962-8950402GC | A | 01/30/1996 | 1 | MINCO | | Y | MTL1018MH/883 | 773 |
| 5962-8950402PA | A | 01/30/1996 | 1 | MINCO | | Y | MTL1018MJ8/883 | 773 |
| 5962-8950402PA | A | 01/30/1996 | 1 | MINCO | | Y | MTL1018MD8/883 | 773 |
| 5962-8950402PC | A | 01/30/1996 | 1 | MINCO | | Y | MTL1018MD8/883 | 773 |
| 5962-8950402PC | A | 01/30/1996 | 1 | MINCO | | Y | MTL1018MJ8/883 | 773 |
| 5962-8950501UA | | 03/19/1992 | 1 | PYRAMID | | | P1753-20QLMB | 429 |
| 5962-8950501YA | | 03/19/1992 | 1 | PYRAMID | | | P1753-20QGMB | 429 |
| 5962-8950501ZA | | 03/19/1992 | 1 | PYRAMID | | | P1753-20PGMB | 429 |
| 5962-8950502UA | | 03/19/1992 | 1 | PYRAMID | | | P1753-30QLMB | 429 |
| 5962-8950502YA | | 03/19/1992 | 1 | PYRAMID | | | P1753-30QGMB | 429 |
| 5962-8950502ZA | | 03/19/1992 | 1 | PYRAMID | | | P1753-30PGMB | 429 |
| 5962-8950503UA | | 03/19/1992 | 1 | PYRAMID | | | P1753-40QLMB | 429 |
| 5962-8950503YA | | 03/19/1992 | 1 | PYRAMID | | | P1753-40QGMB | 429 |
| 5962-8950503ZA | | 03/19/1992 | 1 | PYRAMID | | | P1753-40PGMB | 429 |
| 5962-8950504TA | | 03/19/1992 | 1 | PYRAMID | | | P1753-20GMB | 429 |
| 5962-8950504XA | | 03/19/1992 | 1 | PYRAMID | | | P1753-20CMB | 429 |
| 5962-8950505TA | | 03/19/1992 | 1 | PYRAMID | | | P1753-30GMB | 429 |
| 5962-8950505XA | | 03/19/1992 | 1 | PYRAMID | | | P1753-30CMB | 429 |
| 5962-8950506TA | | 03/19/1992 | 1 | PYRAMID | | | P1753-40GMB | 429 |
| 5962-8950506XA | | 03/19/1992 | 1 | PYRAMID | | | P1753-40CMB | 429 |
| 5962-89506013A | A | 12/22/1993 | 1 | IDT | | Y | IDT54FCT827ALB | 569 |
| 5962-8950601KA | A | 12/22/1993 | | (NONE) | 04/29/2002 | | 54FCT827A (GEN) | 569 |
| 5962-8950601LA | A | 12/22/1993 | 1 | IDT | | Y | IDT54FCT827ADB | 569 |
| 5962-89506023A | A | 12/22/1993 | 1 | IDT | | Y | IDT54FCT827BLB | 569 |
| 5962-8950602KA | A | 12/22/1993 | | (NONE) | 04/29/2002 | | 54FCT827B (GEN) | 569 |
| 5962-8950602LA | A | 12/22/1993 | 1 | IDT | | Y | IDT54FCT827BDB | 569 |
| 5962-89507012A | B | 07/18/2000 | 1 | ROCHESTER | | Y | 54HC4066/B2A | 183 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-8950701CA | B | 07/18/2000 | 1 | TI | | Y | CD54HC4066F3A | 183 |
| 5962-89508012A | | 04/27/1989 | | (NONE) | 04/27/1998 | | 54FCT139 (GEN) | 283 |
| 5962-8950801EA | | 04/27/1989 | | (NONE) | 04/27/1998 | | 54FCT139 (GEN) | 283 |
| 5962-8950801FA | | 04/27/1989 | | (NONE) | 04/27/1998 | | 54FCT139 (GEN) | 283 |
| 5962-89508022A | | 04/27/1989 | | (NONE) | 04/27/1998 | | 54FCT139A (GEN) | 283 |
| 5962-8950802EA | | 04/27/1989 | | (NONE) | 04/27/1998 | | 54FCT139A (GEN) | 283 |
| 5962-8950802FA | | 04/27/1989 | | (NONE) | 04/27/1998 | | 54FCT139A (GEN) | 283 |
| 5962-8950901XA | A | 04/09/2002 | 1 | ADV. ANALOG | | Y | RGBDAC3808H/B | 591 |
| 5962-89510012A | A | 08/05/2004 | 2 | TI | | Y | SNJ54F27FK | 122 |
| 5962-8951001CA | A | 08/05/2004 | 2 | TI | | Y | SNJ54F27J | 122 |
| 5962-8951001DA | A | 08/05/2004 | 2 | TI | | Y | SNJ54F27W | 122 |
| 5962-89511012A | C | 03/21/2001 | 1 | TI | | Y | UC1525AL/883B | 787 |
| 5962-8951101EA | C | 03/21/2001 | 1 | MICROSEMI | | Y | SG1525AJ/883B | 787 |
| 5962-8951101EA | C | 03/21/2001 | 1 | SEMELAB | | Y | IP1525AJ-DESC | 787 |
| 5962-8951101EA | C | 03/21/2001 | 1 | TI | | Y | UC1525AJ/883B | 787 |
| 5962-8951101FA | C | 03/21/2001 | 1 | MICROSEMI | | Y | SG1525AF/883B | 787 |
| 5962-89511022A | C | 03/21/2001 | 1 | TI | | Y | UC1527AL/883B | 787 |
| 5962-8951102EA | C | 03/21/2001 | 1 | MICROSEMI | | Y | SG1527AJ/883B | 787 |
| 5962-8951102EA | C | 03/21/2001 | 1 | SEMELAB | | Y | IP1527AJ-DESC | 787 |
| 5962-8951102EA | C | 03/21/2001 | 1 | TI | | Y | UC1527AJ/883B | 787 |
| 5962-89511032A | C | 03/21/2001 | 1 | TI | | Y | UC1525AL/883B | 787 |
| 5962-8951103V2A | C | 03/21/2001 | 1 | TI | | Y | UC1525ALQMLV | 787 |
| 5962-8951103EA | C | 03/21/2001 | 1 | TI | | Y | UC1525AJ/883B | 787 |
| 5962-8951103VEA | C | 03/21/2001 | 1 | TI | | Y | UC1525AJQMLV | 787 |
| 5962-89511042A | C | 03/21/2001 | 1 | TI | | Y | UC1527AL/883B | 787 |
| 5962-8951104EA | C | 03/21/2001 | 1 | TI | | Y | UC1527AJ/883B | 787 |
| 5962-89511052A | C | 03/21/2001 | 1 | TI | | Y | UC1525BL/883B | 787 |
| 5962-8951105V2A | C | 03/21/2001 | 1 | TI | | Y | UC1525BLQMLV | 787 |
| 5962-8951105EA | C | 03/21/2001 | 1 | TI | | Y | UC1525BJ/883B | 787 |
| 5962-8951105VEA | C | 03/21/2001 | 1 | TI | | Y | UC1525BJQMLV | 787 |
| 5962-8951201XA | D | 12/18/1995 | | (NONE) | | | 56001-20 (GEN) | 432 |
| 5962-8951201YC | D | 12/18/1995 | | (NONE) | | | 56001-20 (GEN) | 432 |
| 5962-8951202XA | D | 12/18/1995 | | (NONE) | 09/30/1995 | | 56001A-20 (GEN) | 432 |
| 5962-8951202YC | D | 12/18/1995 | | (NONE) | 09/30/1995 | | 56001A-20 (GEN) | 432 |
| 5962-89513012A | A | 01/13/1992 | 1 | IDT | | Y | IDT54FCT574LB | 159 |
| 5962-89513012A | A | 01/13/1992 | 2 | NATIONAL | | Y | 54FCT574LMQB | 159 |
| 5962-8951301RA | A | 01/13/1992 | 1 | IDT | | Y | IDT54FCT574DB | 159 |
| 5962-8951301RA | A | 01/13/1992 | 2 | NATIONAL | | Y | 54FCT574DMQB | 159 |
| 5962-8951301SA | A | 01/13/1992 | 2 | NATIONAL | | Y | 54FCT574FMQB | 159 |
| 5962-89513022A | A | 01/13/1992 | 1 | IDT | | Y | IDT54FCT574ALB | 159 |
| 5962-8951302RA | A | 01/13/1992 | 1 | IDT | | Y | IDT54FCT574ADB | 159 |
| 5962-8951302SA | A | 01/13/1992 | | (NONE) | 04/29/2002 | | 54FCT574A (GEN) | 159 |
| 5962-8951401QA | | 01/05/1989 | 1 | QP SEMI | | | Z84C2006CMB | 420 |
| 5962-8951501XA | A | 06/02/2003 | 1 | QP SEMI | | | Z84C3006CMB | 424 |
| 5962-8951601QA | | 01/25/1989 | | (NONE) | | | Z84C4206 (GEN) | 420 |
| 5962-8951701TA | A | 05/09/1994 | | (NONE) | 07/31/1995 | | 7C9101-45 (GEN) | 400 |
| 5962-8951701UA | A | 05/09/1994 | | (NONE) | | | 7C9101-45 (GEN) | 400 |
| 5962-8951701VA | A | 05/09/1994 | | (NONE) | 07/31/1995 | | 7C9101-45 (GEN) | 400 |
| 5962-8951701XA | A | 05/09/1994 | | (NONE) | | | 7C9101-45 (GEN) | 400 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-8951701YA | A | 05/09/1994 | | (NONE) | | | 7C9101-45 (GEN) | 400 |
| 5962-8951701ZA | A | 05/09/1994 | | (NONE) | 07/31/1995 | | 7C9101-45 (GEN) | 400 |
| 5962-8951702UA | A | 05/09/1994 | | (NONE) | | | 7C9101-35 (GEN) | 400 |
| 5962-8951702XA | A | 05/09/1994 | | (NONE) | | | 7C9101-35 (GEN) | 400 |
| 5962-8951702YA | A | 05/09/1994 | | (NONE) | | | 7C9101-35 (GEN) | 400 |
| 5962-8951702ZA | A | 05/09/1994 | | (NONE) | | | 7C9101-35 (GEN) | 400 |
| 5962-89518012A | A | 07/18/2002 | 1 | ANALOG (3) | | Y | AD7821TE/883B | 592 |
| 5962-8951801RA | A | 07/18/2002 | 1 | ANALOG (3) | | Y | AD7821TQ/883B | 592 |
| 5962-8951901MUA | F | 10/23/1998 | | (NONE) | | | BX1750A (GEN) | 403 |
| 5962-8951901MXC | F | 10/23/1998 | | (NONE) | 03/31/2000 | | 3611023 (GEN) | 403 |
| 5962-8951901XC | F | 10/23/1998 | | (NONE) | 03/31/2000 | | 3611023 (GEN) | 403 |
| 5962-8951901MYA | F | 10/23/1998 | | (NONE) | 03/31/2000 | | 3611023 (GEN) | 403 |
| 5962-8951901YA | F | 10/23/1998 | | (NONE) | 03/31/2000 | | 3611023 (GEN) | 403 |
| 5962-8951902MUA | F | 10/23/1998 | | (NONE) | | | BX1750A (GEN) | 403 |
| 5962-8951902MXC | F | 10/23/1998 | | (NONE) | 03/31/2000 | | 3611023 (GEN) | 403 |
| 5962-8951902MYA | F | 10/23/1998 | | (NONE) | 03/31/2000 | | 3611023 (GEN) | 403 |
| 5962-8951903MUA | F | 10/23/1998 | | (NONE) | | | BX1750A (GEN) | 403 |
| 5962-8951903MXC | F | 10/23/1998 | | (NONE) | 03/31/2000 | | 3611023 (GEN) | 403 |
| 5962-8951903MYA | F | 10/23/1998 | | (NONE) | 03/31/2000 | | 3611023 (GEN) | 403 |
| 5962-8951904VYA | F | 10/23/1998 | | (NONE) | 03/31/2000 | | 5165228 (GEN) | 403 |
| 5962-8951905VYA | F | 10/23/1998 | | (NONE) | 03/31/2000 | | 5165228 (GEN) | 403 |
| 5962-8951991MTA | F | 10/23/1998 | | (NONE) | | | BX1750A (GEN) | 403 |
| 5962-8951991MZC | F | 10/23/1998 | | (NONE) | 03/31/2000 | | 3611023 (GEN) | 403 |
| 5962-8951991ZC | F | 10/23/1998 | | (NONE) | 03/31/2000 | | 3611023 (GEN) | 403 |
| 5962-8951992MTA | F | 10/23/1998 | | (NONE) | | | BX1750A (GEN) | 403 |
| 5962-8951992MZC | F | 10/23/1998 | | (NONE) | 03/31/2000 | | 3611023 (GEN) | 403 |
| 5962-8951993MTA | F | 10/23/1998 | | (NONE) | | | BX1750A (GEN) | 403 |
| 5962-8951993MZC | F | 10/23/1998 | | (NONE) | 03/31/2000 | | 3611023 (GEN) | 403 |
| 5962-8952001XA | C | 03/01/2000 | 1 | SOLITRON | | | SDP1083XMD | 780 |
| 5962-8952001YA | C | 03/01/2000 | 0 | INTER. RECT. | | | OM183SCM/883 | 780 |
| 5962-8952001YA | C | 03/01/2000 | 1 | SOLITRON | | | SDP1083YMD | 780 |
| 5962R8952001YA | C | 03/01/2000 | 1 | INTER. RECT. | | | OMR1830SCM/883B | 780 |
| 5962-8952001ZA | C | 03/01/2000 | 1 | INTER. RECT. | | | OM1830NCM | 780 |
| 5962-8952001ZA | C | 03/01/2000 | 1 | SOLITRON | | | SDP1083ZMD | 780 |
| 5962-89521012A | E | 03/24/2000 | 1 | AUSTIN SEMI. | | Y | AS1084EC/883C | 780 |
| 5962-8952101XA | E | 03/24/2000 | 1 | INTER. RECT. | | | OM1840NKM/883B | 780 |
| 5962-8952101XA | E | 03/24/2000 | 1 | SOLITRON | | | SDP1084XMD | 780 |
| 5962-8952101YA | E | 03/24/2000 | 0 | INTER. RECT. | | | OM184SCM/883 | 780 |
| 5962-8952101YA | E | 03/24/2000 | 1 | SOLITRON | | | SDP1084YMD | 780 |
| 5962R8952101YA | E | 03/24/2000 | 1 | INTER. RECT. | | | OMR1840SCM/883B | 780 |
| 5962-8952101ZA | E | 03/24/2000 | 1 | INTER. RECT. | | | OM1840NCM | 780 |
| 5962-8952101ZA | E | 03/24/2000 | 1 | SOLITRON | | | SDP1084ZDM | 780 |
| 5962-8952201XA | F | 12/06/1995 | 1 | NATIONAL HYB | | Y | NHI-1559/883 | 590 |
| 5962-8952201XC | F | 12/06/1995 | 1 | NATIONAL HYB | | Y | NHI-1559/883 | 590 |
| 5962-8952201YA | F | 12/06/1995 | 1 | NATIONAL HYB | | Y | NHI-1559FP/883 | 590 |
| 5962-8952201YC | F | 12/06/1995 | 1 | NATIONAL HYB | | Y | NHI-1559FP/883 | 590 |
| 5962-8952202XA | F | 12/06/1995 | 1 | NATIONAL HYB | | Y | NHI-1529/883 | 590 |
| 5962-8952202XC | F | 12/06/1995 | 1 | NATIONAL HYB | | Y | NHI-1529/883 | 590 |
| 5962-8952202YA | F | 12/06/1995 | 1 | AEROFLEX | | Y | ARX-2453FP | 590 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-8952202YA | F | 12/06/1995 | 1 | NATIONAL HYB | | Y | NHI-1529FP/883 | 590 |
| 5962-8952202YC | F | 12/06/1995 | 1 | AEROFLEX | | Y | ARX-2453FP | 590 |
| 5962-8952202YC | F | 12/06/1995 | 1 | NATIONAL HYB | | Y | NHI-1529FP/883 | 590 |
| 5962-8952203XA | F | 12/06/1995 | 1 | NATIONAL HYB | | Y | NHI-1529 | 590 |
| 5962-8952203XC | F | 12/06/1995 | 1 | NATIONAL HYB | | Y | NHI-1529 | 590 |
| 5962-8952203YA | F | 12/06/1995 | 1 | NATIONAL HYB | | Y | NHI-1529FP | 590 |
| 5962-8952203YC | F | 12/06/1995 | 1 | NATIONAL HYB | | Y | NHI-1529FP | 590 |
| 5962-8952204XA | F | 12/06/1995 | 1 | NATIONAL HYB | | Y | NHI-1559/883 | 590 |
| 5962-8952204XC | F | 12/06/1995 | 1 | NATIONAL HYB | | Y | NHI-1559/883 | 590 |
| 5962-8952204YA | F | 12/06/1995 | 1 | NATIONAL HYB | | Y | NHI-1559FP/883 | 590 |
| 5962-8952204YC | F | 12/06/1995 | 1 | NATIONAL HYB | | Y | NHI-1559FP/883 | 590 |
| 5962-8952205UA | F | 12/06/1995 | | (NONE) | | | CT2521 (GEN) | 590 |
| 5962-8952205ZA | F | 12/06/1995 | | (NONE) | | | CT2521 (GEN) | 590 |
| 5962-8952206XA | F | 12/06/1995 | 1 | CMAC MICRO. | | Y | FC1553921 | 590 |
| 5962-8952206XA | F | 12/06/1995 | 1 | NATIONAL HYB | | Y | NHI-1529/883 | 590 |
| 5962-8952206XC | F | 12/06/1995 | 1 | CMAC MICRO. | | Y | FC1553921 | 590 |
| 5962-8952206XC | F | 12/06/1995 | 1 | NATIONAL HYB | | Y | NHI-1529/883 | 590 |
| 5962-8952206YA | F | 12/06/1995 | 1 | CMAC MICRO. | | Y | FC1553921FP | 590 |
| 5962-8952206YA | F | 12/06/1995 | 1 | NATIONAL HYB | | Y | NHI-1529FP/883 | 590 |
| 5962-8952206YC | F | 12/06/1995 | 1 | CMAC MICRO. | | Y | FC1553921FP | 590 |
| 5962-8952206YC | F | 12/06/1995 | 1 | NATIONAL HYB | | Y | NHI-1529FP/883 | 590 |
| 5962-8952207XA | F | 12/06/1995 | 1 | CMAC MICRO. | | Y | FC1553923 | 590 |
| 5962-8952207XA | F | 12/06/1995 | 1 | NATIONAL HYB | | Y | NHI-1559/883 | 590 |
| 5962-8952207XC | F | 12/06/1995 | 1 | CMAC MICRO. | | Y | FC1553923 | 590 |
| 5962-8952207XC | F | 12/06/1995 | 1 | NATIONAL HYB | | Y | NHI-1559/883 | 590 |
| 5962-8952207YA | F | 12/06/1995 | 1 | CMAC MICRO. | | Y | FC1553923 | 590 |
| 5962-8952207YA | F | 12/06/1995 | 1 | NATIONAL HYB | | Y | NHI-1559FP/883 | 590 |
| 5962-8952207YC | F | 12/06/1995 | 1 | CMAC MICRO. | | Y | FC1553923 | 590 |
| 5962-8952207YC | F | 12/06/1995 | 1 | NATIONAL HYB | | Y | NHI-1559FP/883 | 590 |
| 5962-8952208XA | F | 12/06/1995 | 1 | NATIONAL HYB | | Y | NHI-1529/883 | 590 |
| 5962-8952208XC | F | 12/06/1995 | 1 | NATIONAL HYB | | Y | NHI-1529/883 | 590 |
| 5962-8952208YA | F | 12/06/1995 | 1 | AEROFLEX | | Y | ARX-3453FP | 590 |
| 5962-8952208YA | F | 12/06/1995 | 1 | NATIONAL HYB | | Y | NHI-1529/883 | 590 |
| 5962-8952208YC | F | 12/06/1995 | 1 | AEROFLEX | | Y | ARX-3453FP | 590 |
| 5962-8952208YC | F | 12/06/1995 | 1 | NATIONAL HYB | | Y | NHI-1529/883 | 590 |
| 5962-8952209XA | F | 12/06/1995 | 1 | CMAC MICRO. | | Y | FC1553922 | 590 |
| 5962-8952209XA | F | 12/06/1995 | 1 | NATIONAL HYB | | Y | NHI-1529/883 | 590 |
| 5962-8952209XC | F | 12/06/1995 | 1 | CMAC MICRO. | | Y | FC1553922 | 590 |
| 5962-8952209XC | F | 12/06/1995 | 1 | NATIONAL HYB | | Y | NHI-1529/883 | 590 |
| 5962-8952209YA | F | 12/06/1995 | 1 | NATIONAL HYB | | Y | NHI-1529/883 | 590 |
| 5962-8952209YC | F | 12/06/1995 | 1 | NATIONAL HYB | | Y | NHI-1529/883 | 590 |
| 5962-8952210XA | F | 12/06/1995 | 1 | CMAC MICRO. | | Y | FC1553924 | 590 |
| 5962-8952210XA | F | 12/06/1995 | 1 | NATIONAL HYB | | Y | NHI-1559/883 | 590 |
| 5962-8952210XC | F | 12/06/1995 | 1 | CMAC MICRO. | | Y | FC1553924 | 590 |
| 5962-8952210XC | F | 12/06/1995 | 1 | NATIONAL HYB | | Y | NHI-1559/883 | 590 |
| 5962-8952210YA | F | 12/06/1995 | 1 | NATIONAL HYB | | Y | NHI-1559/883 | 590 |
| 5962-8952210YC | F | 12/06/1995 | 1 | NATIONAL HYB | | Y | NHI-1559/883 | 590 |
| 5962-8952211XA | F | 12/06/1995 | 1 | AEROFLEX | | Y | 4453-001-6 | 590 |
| 5962-8952211XC | F | 12/06/1995 | 1 | AEROFLEX | | Y | 4453-001-6 | 590 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-8952211YA | F | 12/06/1995 | 1 | AEROFLEX | | Y | 4453-201-6 | 590 |
| 5962-8952211YC | F | 12/06/1995 | 1 | AEROFLEX | | Y | 4453-201-6 | 590 |
| 5962-8952212XA | F | 12/06/1995 | 1 | AEROFLEX | | Y | 4453-001-3 | 590 |
| 5962-8952212XC | F | 12/06/1995 | 1 | AEROFLEX | | Y | 4453-001-3 | 590 |
| 5962-8952212YA | F | 12/06/1995 | 1 | AEROFLEX | | Y | 4453-201-3 | 590 |
| 5962-8952212YC | F | 12/06/1995 | 1 | AEROFLEX | | Y | 4453-201-3 | 590 |
| 5962-89523012A | B | 07/05/1994 | | (NONE) | | | 7C403-10 (GEN) | 670 |
| 5962-8952301EA | B | 07/05/1994 | 1 | IDT | | Y | IDT72403L10DB | 670 |
| 5962-89523022A | B | 07/05/1994 | | (NONE) | | | 7C403-15 (GEN) | 670 |
| 5962-8952302EA | B | 07/05/1994 | | (NONE) | 10/29/2001 | | 72403L15 (GEN) | 670 |
| 5962-89523032A | B | 07/05/1994 | | (NONE) | | | | 670 |
| 5962-8952303EA | B | 07/05/1994 | | (NONE) | 10/29/2001 | | 72403L25 (GEN) | 670 |
| 5962-89523042A | B | 07/05/1994 | | (NONE) | | | | 670 |
| 5962-8952304EA | B | 07/05/1994 | 1 | IDT | | Y | IDT72403L35DB | 670 |
| 5962-89523052A | B | 07/05/1994 | 1 | QP SEMI | | Y | CY7C401-10LMB | 670 |
| 5962-8952305EA | B | 07/05/1994 | 1 | IDT | | Y | IDT72401L10DB | 670 |
| 5962-8952305EA | B | 07/05/1994 | 1 | QP SEMI | | Y | CY7C401-10DMB | 670 |
| 5962-89523062A | B | 07/05/1994 | 1 | QP SEMI | | Y | CY7C401-15LMB | 670 |
| 5962-8952306EA | B | 07/05/1994 | 1 | IDT | | Y | IDT72401L15DMB | 670 |
| 5962-8952306EA | B | 07/05/1994 | 1 | QP SEMI | | Y | CY7C401-15DMB | 670 |
| 5962-8952307EA | B | 07/05/1994 | 1 | IDT | | Y | IDT72401L25DB | 670 |
| 5962-8952308EA | B | 07/05/1994 | 1 | IDT | | Y | IDT72401L35DB | 670 |
| 5962-8952401XA | A | 03/24/1994 | 1 | AUSTIN SEMI. | | Y | MT5C2565C-70 | 623 |
| 5962-8952401YA | A | 03/24/1994 | 1 | AUSTIN SEMI. | | Y | MT5C2565EC-70 | 623 |
| 5962-8952402XA | A | 03/24/1994 | 1 | AUSTIN SEMI. | | Y | MT5C2565C-55 | 623 |
| 5962-8952402YA | A | 03/24/1994 | 1 | AUSTIN SEMI. | | Y | MT5C2565EC-55 | 623 |
| 5962-8952403XA | A | 03/24/1994 | 1 | AUSTIN SEMI. | | Y | MT5C2565C-45 | 623 |
| 5962-8952403YA | A | 03/24/1994 | 1 | AUSTIN SEMI. | | Y | MT5C2565EC-45 | 623 |
| 5962-8952404XA | A | 03/24/1994 | 1 | AUSTIN SEMI. | | Y | MT5C2565C-35 | 623 |
| 5962-8952404YA | A | 03/24/1994 | 1 | AUSTIN SEMI. | | Y | MT5C2565EC-35 | 623 |
| 5962-8952405XA | A | 03/24/1994 | 1 | AUSTIN SEMI. | | Y | MT5C2565C-25 | 623 |
| 5962-8952405YA | A | 03/24/1994 | 1 | AUSTIN SEMI. | | Y | MT5C2565EC-25 | 623 |
| 5962-8952406XA | A | 03/24/1994 | 1 | AUSTIN SEMI. | | Y | MT5C2565C-20 | 623 |
| 5962-8952406YA | A | 03/24/1994 | 1 | AUSTIN SEMI. | | Y | MT5C2565EC-20 | 623 |
| 5962-8952407XA | A | 03/24/1994 | 1 | AUSTIN SEMI. | | Y | MT5C2565C-15 | 623 |
| 5962-8952407YA | A | 03/24/1994 | 1 | AUSTIN SEMI. | | Y | MT5C2565EC-15 | 623 |
| 5962-89525013A | B | 08/05/2004 | 1 | TI | | Y | SNJ54AS823AFK | 421 |
| 5962-8952501KA | B | 08/05/2004 | 1 | TI | | Y | SNJ54AS823AW | 421 |
| 5962-8952501LA | B | 08/05/2004 | 1 | TI | | Y | SNJ54AS823AJT | 421 |
| 5962-89526013A | B | 08/10/2004 | 1 | TI | | | SNJ54AS869FK | 304 |
| 5962-8952601KA | B | 08/10/2004 | 1 | TI | | | SNJ54AS869W | 304 |
| 5962-8952601LA | B | 08/10/2004 | 1 | TI | | | SNJ54AS869JT | 304 |
| 5962-8952701XA | B | 02/15/2002 | 1 | ATMEL GREN. | | Y | TS68HC811E2MC1B/C | 420 |
| 5962-8952701XC | B | 02/15/2002 | 1 | ATMEL GREN. | | Y | TS68HC811E2MCB/C | 420 |
| 5962-8952701YA | B | 02/15/2002 | 1 | ATMEL GREN. | | Y | TS68HC811E2MF1B/C | 420 |
| 5962-8952701YC | B | 02/15/2002 | 1 | ATMEL GREN. | | Y | TS68HC811E2MFB/C | 420 |
| 5962-8952701YC | B | 02/15/2002 | 1 | AUSTIN SEMI. | | Y | AS68HC811E2Q52/883 | 420 |
| 5962-8952801XA | A | 07/22/2002 | 1 | DATEL | | Y | DAC-HKB/883B | 591 |
| 5962-8952801XC | A | 07/22/2002 | 1 | DATEL | | Y | DAC-HKB/883B | 591 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-8952802XA | A | 07/22/2002 | 1 | DATEL | | Y | DAC-HKB-2/883B | 591 |
| 5962-8952802XC | A | 07/22/2002 | 1 | DATEL | | Y | DAC-HKB-2/883B | 591 |
| 5962-8953101HXC | K | 04/09/2002 | 1 | DATEL | | Y | DAC-HPB/883B | 591 |
| 5962-8953102HXC | K | 04/09/2002 | 1 | DATEL | | Y | DAC-HPB-1/883 | 591 |
| 5962-8953102HYA | K | 04/09/2002 | | (NONE) | 01/25/2000 | | MN3292 (GEN) | 591 |
| 5962-8953103HYA | K | 04/09/2002 | | (NONE) | 01/25/2000 | | MN3290 (GEN) | 591 |
| 5962-8953104HYA | K | 04/09/2002 | | (NONE) | 01/25/2000 | | MN3291 (GEN) | 591 |
| 5962-8953201XA | B | 03/16/1992 | 1 | QP SEMI | | Y | 2692/BXA | 590 |
| 5962-8953202QA | B | 03/16/1992 | 1 | QP SEMI | | Y | 2692/BQA | 590 |
| 5962-8953202UA | B | 03/16/1992 | 1 | QP SEMI | | Y | 2692/BUA | 590 |
| 5962-8953202YA | B | 03/16/1992 | 1 | QP SEMI | | Y | 2692/BYA | 590 |
| 5962-8953203QA | B | 03/16/1992 | | (NONE) | | | 68C681 (GEN) | 590 |
| 5962-8953203UA | B | 03/16/1992 | | (NONE) | | | 68C681 (GEN) | 590 |
| 5962-89533013A | | 09/26/1989 | | (NONE) | 04/27/1998 | | 54FCT861A (GEN) | 590 |
| 5962-8953301KA | | 09/26/1989 | | (NONE) | 04/27/1998 | | 54FCT861A (GEN) | 590 |
| 5962-8953301LA | | 09/26/1989 | | (NONE) | 04/27/1998 | | 54FCT861A (GEN) | 590 |
| 5962-89533023A | | 09/26/1989 | | (NONE) | 04/27/1998 | | 54FCT861B (GEN) | 590 |
| 5962-8953302KA | | 09/26/1989 | | (NONE) | 04/27/1998 | | 54FCT861B (GEN) | 590 |
| 5962-8953302LA | | 09/26/1989 | | (NONE) | 04/27/1998 | | 54FCT861B (GEN) | 590 |
| 5962-8953401MXA | C | 11/21/1991 | | (NONE) | 12/24/1997 | | 8038716 (GEN) | 409 |
| 5962-8953401MYA | C | 11/21/1991 | | (NONE) | 12/24/1997 | | 8038716 (GEN) | 409 |
| 5962-8953402MXA | C | 11/21/1991 | | (NONE) | 12/24/1997 | | 8038720 (GEN) | 409 |
| 5962-8953402MYA | C | 11/21/1991 | | (NONE) | 12/24/1997 | | 8038720 (GEN) | 409 |
| 5962-8953402QYA | C | 11/21/1991 | | (NONE) | | | 80387-20 (GEN) | 409 |
| 5962-8953403MXA | C | 11/21/1991 | | (NONE) | 12/24/1997 | | 8038725 (GEN) | 409 |
| 5962-8953403MYA | C | 11/21/1991 | | (NONE) | 12/24/1997 | | 8038725 (GEN) | 409 |
| 5962-8953403QYA | C | 11/21/1991 | | (NONE) | | | 80387-25 (GEN) | 409 |
| 5962-89535013A | C | 01/30/2002 | 1 | QP SEMI | | Y | 54F657 | 590 |
| 5962-8953501KA | C | 01/30/2002 | 1 | QP SEMI | | Y | 54F657 | 590 |
| 5962-8953501LA | C | 01/30/2002 | 1 | QP SEMI | | Y | 54F657 | 590 |
| 5962-8953601UA | E | 01/17/2001 | | (NONE) | 10/29/2001 | | 7202LA120 (GEN) | 670 |
| 5962-8953601XA | E | 01/17/2001 | | (NONE) | 10/29/2001 | | 7202LA120 (GEN) | 670 |
| 5962-8953601YA | E | 01/17/2001 | | (NONE) | 10/29/2001 | | 7202LA120 (GEN) | 670 |
| 5962-8953601ZA | E | 01/17/2001 | | (NONE) | 10/29/2001 | | 7202LA120 (GEN) | 670 |
| 5962-8953602UA | E | 01/17/2001 | | (NONE) | 10/29/2001 | | 7202LA80 (GEN) | 670 |
| 5962-8953602XA | E | 01/17/2001 | | (NONE) | 10/29/2001 | | 7202LA80 (GEN) | 670 |
| 5962-8953602YA | E | 01/17/2001 | | (NONE) | 10/29/2001 | | 7202LA80 (GEN) | 670 |
| 5962-8953602ZA | E | 01/17/2001 | | (NONE) | 10/29/2001 | | 7202LA80 (GEN) | 670 |
| 5962-8953603UA | E | 01/17/2001 | | (NONE) | 10/29/2001 | | 7202LA65 (GEN) | 670 |
| 5962-8953603XA | E | 01/17/2001 | | (NONE) | 10/29/2001 | | 7202LA65 (GEN) | 670 |
| 5962-8953603YA | E | 01/17/2001 | | (NONE) | 10/29/2001 | | 7202LA65 (GEN) | 670 |
| 5962-8953603ZA | E | 01/17/2001 | | (NONE) | 10/29/2001 | | 7202LA65 (GEN) | 670 |
| 5962-8953604UA | E | 01/17/2001 | | (NONE) | 10/29/2001 | | 7202LA40 (GEN) | 670 |
| 5962-8953604XA | E | 01/17/2001 | | (NONE) | 10/29/2001 | | 7202LA40 (GEN) | 670 |
| 5962-8953604YA | E | 01/17/2001 | | (NONE) | 10/29/2001 | | 7202LA40 (GEN) | 670 |
| 5962-8953604ZA | E | 01/17/2001 | | (NONE) | 10/29/2001 | | 7202LA40 (GEN) | 670 |
| 5962-8953605UA | E | 01/17/2001 | 2 | IDT | | Y | IDT7202LA30LB | 670 |
| 5962-8953605XA | E | 01/17/2001 | 2 | IDT | | Y | IDT7202LA30TDB | 670 |
| 5962-8953605YA | E | 01/17/2001 | 2 | IDT | | Y | IDT7202LA30DB | 670 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-8953605ZA | E | 01/17/2001 | | (NONE) | 10/29/2001 | | 7202LA30 (GEN) | 670 |
| 5962-8953606UA | E | 01/17/2001 | 2 | IDT | | Y | IDTT7202LA20LB | 670 |
| 5962-8953606XA | E | 01/17/2001 | 2 | IDT | | Y | IDT7202LA20TDB | 670 |
| 5962-8953606YA | E | 01/17/2001 | 2 | IDT | | Y | IDT7202LA20DB | 670 |
| 5962-8953606ZA | E | 01/17/2001 | | (NONE) | 10/29/2001 | | 7202LA20 (GEN) | 670 |
| 5962-8953701UA | A | 03/31/1994 | 2 | QP SEMI | | Y | CY7C251-65QMB | 661 |
| 5962-8953701YA | A | 03/31/1994 | 2 | QP SEMI | | Y | CY7C251-65WMB | 661 |
| 5962-8953701ZA | A | 03/31/1994 | | (NONE) | | | 7C251-65 (GEN) | 661 |
| 5962-8953702UA | A | 03/31/1994 | 2 | QP SEMI | | Y | CY7C251-55QMB | 661 |
| 5962-8953702YA | A | 03/31/1994 | 2 | QP SEMI | | Y | CY7C251-55WMB | 661 |
| 5962-8953702ZA | A | 03/31/1994 | | (NONE) | 05/30/1999 | | 7C251-55 (GEN) | 661 |
| 5962-8953703UA | A | 03/31/1994 | 2 | QP SEMI | | Y | CY7C251-45QMB | 661 |
| 5962-8953703YA | A | 03/31/1994 | 2 | QP SEMI | | Y | CY7C251-45WMB | 661 |
| 5962-8953703ZA | A | 03/31/1994 | | (NONE) | | | 7C251-45 (GEN) | 661 |
| 5962-8953801UA | A | 01/12/1993 | | (NONE) | | | | 661 |
| 5962-8953801XA | A | 01/12/1993 | | (NONE) | | | 7C254-65 (GEN) | 661 |
| 5962-8953801ZA | A | 01/12/1993 | | (NONE) | | | 7C254-65 (GEN) | 661 |
| 5962-8953802UA | A | 01/12/1993 | | (NONE) | | | | 661 |
| 5962-8953802XA | A | 01/12/1993 | | (NONE) | 05/31/1998 | | 7C254-55 (GEN) | 661 |
| 5962-8953802ZA | A | 01/12/1993 | | (NONE) | | | 7C254-55 (GEN) | 661 |
| 5962-8953803UA | A | 01/12/1993 | | (NONE) | | | 7C254-45 (GEN) | 661 |
| 5962-8953803XA | A | 01/12/1993 | | (NONE) | | | 7C254-45 (GEN) | 661 |
| 5962-8953803ZA | A | 01/12/1993 | | (NONE) | | | 7C254-45 (GEN) | 661 |
| 5962-89539012A | A | 12/28/2000 | 3 | NATIONAL | | Y | 54AC157LMQB | 275 |
| 5962-8953901EA | A | 12/28/2000 | 3 | NATIONAL | | Y | 54AC157DMQB | 275 |
| 5962-8953901FA | A | 12/28/2000 | 3 | NATIONAL | | Y | 54AC157FMQB | 275 |
| 5962-8953901VXA | A | 12/28/2000 | 2 | STMICRO | | Y | 54AC157K02V | 275 |
| 5962-8953901VXC | A | 12/28/2000 | 2 | STMICRO | | Y | 54AC157K01V | 275 |
| 5962-8953901XA | A | 12/28/2000 | 2 | STMICRO | | Y | 54AC157K02Q | 275 |
| 5962-8953901XC | A | 12/28/2000 | 2 | STMICRO | | Y | 54AC157K01Q | 275 |
| 5962-8954001JA | B | 10/10/2000 | | (NONE) | | | HM1-6617 (GEN) | 658 |
| 5962-8954001LA | B | 10/10/2000 | 1 | INTERSIL | | Y | HM6-6617/883 | 658 |
| 5962-8954001XA | B | 10/10/2000 | | (NONE) | | | HM4-6617 (GEN) | 658 |
| 5962-8954002JA | B | 10/10/2000 | | (NONE) | 03/25/2001 | | HM1-6617B (GEN) | 658 |
| 5962-8954002LA | B | 10/10/2000 | | (NONE) | | | HM6-6617B (GEN) | 658 |
| 5962-8954002XA | B | 10/10/2000 | | (NONE) | | | HM4-6617B (GEN) | 658 |
| 5962-8954101CA | A | 05/15/2001 | | (NONE) | | | SMP-11A (GEN) | 818 |
| 5962-89541022A | A | 05/15/2001 | 1 | ANALOG (5) | | Y | SMP-11BRC/883 | 818 |
| 5962-8954102CA | A | 05/15/2001 | 1 | ANALOG (5) | | Y | SMP-11BY/883 | 818 |
| 5962-8954103CA | A | 05/15/2001 | | (NONE) | | | SMP-10A (GEN) | 818 |
| 5962-89541042A | A | 05/15/2001 | | (NONE) | | | SMP-10B (GEN) | 818 |
| 5962-8954104CA | A | 05/15/2001 | | (NONE) | | | SMP-10B (GEN) | 818 |
| 5962-8954201GA | C | 02/18/2003 | | (NONE) | 04/16/2002 | | OP-15A (GEN) | 703 |
| 5962-8954201PA | C | 02/18/2003 | | (NONE) | 04/16/2002 | | OP-15A (GEN) | 703 |
| 5962-8954202GA | C | 02/18/2003 | | (NONE) | 04/14/2001 | | OP-15B (GEN) | 703 |
| 5962-8954203VGA | C | 02/18/2003 | 1 | ANALOG (5) | | Y | OP-15AJ/QMLV | 703 |
| 5962R8954203VGA | C | 02/18/2003 | 1 | ANALOG (5) | | Y | OP-15AJ/QMLR | 703 |
| 5962-8954203VHA | C | 02/18/2003 | 1 | ANALOG (5) | | Y | OP-15AL/QMLV | 703 |
| 5962R8954203VHA | C | 02/18/2003 | 1 | ANALOG (5) | | Y | OP-15AL/QMLR | 703 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-8954203VPA | C | 02/18/2003 | 1 | ANALOG (5) | | Y | OP-15AZ/QMLV | 703 |
| 5962R8954203VPA | C | 02/18/2003 | 1 | ANALOG (5) | | Y | OP-15AZ/QMLR | 703 |
| 5962-8954301GA | A | 03/16/2000 | | (NONE) | 04/16/2002 | | OP-16A (GEN) | 703 |
| 5962-8954301PA | A | 03/16/2000 | | (NONE) | 04/16/2002 | | OP-16A (GEN) | 703 |
| 5962-8954302GA | A | 03/16/2000 | | (NONE) | 04/14/2001 | | OP-16B (GEN) | 703 |
| 5962-8954302PA | A | 03/16/2000 | 1 | ANALOG (5) | | Y | OP-16BZ/883 | 703 |
| 5962-8954303GA | A | 03/16/2000 | | (NONE) | | | OP-16C (GEN) | 703 |
| 5962-8954303PA | A | 03/16/2000 | | (NONE) | 04/14/2001 | | OP-16C (GEN) | 703 |
| 5962-8954304VGA | A | 03/16/2000 | 1 | ANALOG (5) | | Y | OP-16AJ/QMLV | 703 |
| 5962R8954304VGA | A | 03/16/2000 | 1 | ANALOG (5) | | Y | OP-16AJ/QMLR | 703 |
| 5962-8954304VPA | A | 03/16/2000 | 1 | ANALOG (5) | | Y | OP-16AZ/QMLV | 703 |
| 5962R8954304VPA | A | 03/16/2000 | 1 | ANALOG (5) | | Y | OP-16AZ/QMLR | 703 |
| 5962-8954401GA | A | 02/23/2001 | | (NONE) | 04/16/2002 | | OP-97A (GEN) | 701 |
| 5962-8954401PA | A | 02/23/2001 | 1 | ANALOG (5) | | Y | OP-97AZ/883 | 701 |
| 5962-89545012A | A | 02/24/2000 | 1 | QP SEMI | | Y | 54F579/2A | 304 |
| 5962-8954501RA | A | 02/24/2000 | 1 | QP SEMI | | Y | 54F579/RA | 304 |
| 5962-8954501SA | A | 02/24/2000 | 1 | QP SEMI | | Y | 54F579/SA | 304 |
| 5962-89546013A | | 04/11/1989 | | (NONE) | | | | 431 |
| 5962-8954601XA | | 04/11/1989 | | (NONE) | 05/31/1998 | | 7C330-28 (GEN) | 431 |
| 5962-8954601YA | | 04/11/1989 | | (NONE) | | | | 431 |
| 5962-89546023A | | 04/11/1989 | | (NONE) | 05/31/1998 | | 7C330-40 (GEN) | 431 |
| 5962-8954602XA | | 04/11/1989 | | (NONE) | 05/31/1998 | | 7C330-40 (GEN) | 431 |
| 5962-8954602YA | | 04/11/1989 | | (NONE) | | | 7C330-40 (GEN) | 431 |
| 5962-89546033A | | 04/11/1989 | | (NONE) | 05/31/1998 | | 7C330-50 (GEN) | 431 |
| 5962-8954603XA | | 04/11/1989 | | (NONE) | 05/31/1998 | | 7C330-50 (GEN) | 431 |
| 5962-8954603YA | | 04/11/1989 | | (NONE) | 03/05/1996 | | 7C330-50 (GEN) | 431 |
| 5962-89547012A | F | 08/18/2004 | | (NONE) | 09/15/1995 | | 54ACT11008 (GEN) | 110 |
| 5962-8954701EA | F | 08/18/2004 | | (NONE) | 09/15/1995 | | 54ACT11008 (GEN) | 110 |
| 5962-89547022A | F | 08/18/2004 | 3 | NATIONAL | | Y | 54ACTQ08LMQB | 110 |
| 5962-89547022A | F | 08/18/2004 | 2 | TI | | Y | SNJ54ACT08FK | 110 |
| 5962-8954702V2A | F | 08/18/2004 | | (NONE) | | | 54ACTQ08 (GEN) | 110 |
| 5962R89547022A | F | 08/18/2004 | 3 | NATIONAL | | Y | 54ACTQ08LMQB-RH | 110 |
| 5962R8954702V2A | F | 08/18/2004 | 3 | NATIONAL | | Y | 54ACTQ08ERQMLV | 110 |
| 5962-8954702CA | F | 08/18/2004 | 3 | NATIONAL | | Y | 54ACTQ08DMQB | 110 |
| 5962-8954702CA | F | 08/18/2004 | 2 | TI | | Y | SNJ54ACT08J | 110 |
| 5962-8954702VCA | F | 08/18/2004 | | (NONE) | | | 54ACTQ08 (GEN) | 110 |
| 5962R8954702CA | F | 08/18/2004 | 3 | NATIONAL | | Y | 54ACTQ08DMQB-RH | 110 |
| 5962R8954702VCA | F | 08/18/2004 | 3 | NATIONAL | | Y | 54ACTQ08JRQMLV | 110 |
| 5962-8954702DA | F | 08/18/2004 | 3 | NATIONAL | | Y | 54ACTQ08FMQB | 110 |
| 5962-8954702DA | F | 08/18/2004 | 2 | TI | | Y | SNJ54ACT08W | 110 |
| 5962-8954702VDA | F | 08/18/2004 | | (NONE) | | | 54ACTQ08 (GEN) | 110 |
| 5962R8954702DA | F | 08/18/2004 | 3 | NATIONAL | | Y | 54ACTQ08FMQB-RH | 110 |
| 5962R8954702VDA | F | 08/18/2004 | 3 | NATIONAL | | Y | 54ACTQ08WRQMLV | 110 |
| 5962-8954703VXA | F | 08/18/2004 | 2 | STMICRO | | Y | 54ACT08K02V | 110 |
| 5962-8954703VXC | F | 08/18/2004 | 2 | STMICRO | | Y | 54ACT08K01V | 110 |
| 5962-8954703XA | F | 08/18/2004 | 2 | STMICRO | | Y | 54ACT08K02Q | 110 |
| 5962-8954703XC | F | 08/18/2004 | 2 | STMICRO | | Y | 54ACT08K01Q | 110 |
| 5962F8954703VXA | F | 08/18/2004 | 2 | STMICRO | | Y | RHFACT08K02V | 110 |
| 5962F8954703VXC | F | 08/18/2004 | 2 | STMICRO | | Y | RHFACT08K01V | 110 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962F8954703XA | F | 08/18/2004 | 2 | STMICRO | | Y | RHFACT08K02Q | 110 |
| 5962F8954703XC | F | 08/18/2004 | 2 | STMICRO | | Y | RHFACT08K01Q | 110 |
| 5962-89548012A | B | 03/13/2002 | 1 | INTERSIL | 07/02/2004 | Y | HA4-5102/883 | 710 |
| 5962-8954801GC | B | 03/13/2002 | 1 | INTERSIL | | Y | HA2-5102/883 | 710 |
| 5962-8954801PA | B | 03/13/2002 | 1 | INTERSIL | | Y | HA7-5102/883 | 710 |
| 5962-89549013A | | 05/10/1989 | | (NONE) | 08/04/1995 | | 29818A (GEN) | 249 |
| 5962-8954901KA | | 05/10/1989 | | (NONE) | 08/04/1995 | | 29818A (GEN) | 249 |
| 5962-8954901LA | | 05/10/1989 | | (NONE) | 08/04/1995 | | 29818A (GEN) | 249 |
| 5962-89550012A | E | 12/09/2003 | 2 | NATIONAL | | Y | 54AC86LMQB | 140 |
| 5962-89550012A | E | 12/09/2003 | 2 | TI | | Y | SNJ54AC86FK | 140 |
| 5962-8955001CA | E | 12/09/2003 | 2 | NATIONAL | | Y | 54AC86DMQB | 140 |
| 5962-8955001CA | E | 12/09/2003 | 2 | TI | | Y | SNJ54AC86J | 140 |
| 5962-8955001DA | E | 12/09/2003 | 2 | NATIONAL | | Y | 54AC86FMQB | 140 |
| 5962-8955001DA | E | 12/09/2003 | 2 | TI | | Y | SNJ54AC86W | 140 |
| 5962-8955001VDA | E | 12/09/2003 | | (NONE) | | | 54AC86 (GEN) | 140 |
| 5962-8955001VXA | E | 12/09/2003 | 2 | STMICRO | | Y | 54AC86K02V | 140 |
| 5962-8955001VXC | E | 12/09/2003 | 2 | STMICRO | | Y | 54AC86K01V | 140 |
| 5962-8955001XA | E | 12/09/2003 | 2 | STMICRO | | Y | 54AC86K02Q | 140 |
| 5962-8955001XC | E | 12/09/2003 | 2 | STMICRO | | Y | 54AC86K01Q | 140 |
| 5962F8955001VXA | E | 12/09/2003 | 2 | STMICRO | | Y | RHFAC86K02V | 140 |
| 5962F8955001VXC | E | 12/09/2003 | 2 | STMICRO | | Y | RHFAC86K01V | 140 |
| 5962F8955001XA | E | 12/09/2003 | 2 | STMICRO | | Y | RHFAC86K02Q | 140 |
| 5962F8955001XC | E | 12/09/2003 | 2 | STMICRO | | Y | RHFAC86K01Q | 140 |
| 5962-89551012A | A | 07/27/2001 | 3 | NATIONAL | | Y | 54AC109LMQB | 152 |
| 5962-8955101EA | A | 07/27/2001 | 3 | NATIONAL | | Y | 54AC109DMQB | 152 |
| 5962-8955101FA | A | 07/27/2001 | 3 | NATIONAL | | Y | 54AC109FMQB | 152 |
| 5962-8955101VXA | A | 07/27/2001 | 2 | STMICRO | | Y | 54AC109K02V | 152 |
| 5962-8955101VXC | A | 07/27/2001 | 2 | STMICRO | | Y | 54AC109K01V | 152 |
| 5962-8955101XA | A | 07/27/2001 | 2 | STMICRO | | Y | 54AC109K02Q | 152 |
| 5962-8955101XC | A | 07/27/2001 | 2 | STMICRO | | Y | 54AC109K01Q | 152 |
| 5962-89552012A | A | 11/12/1997 | 3 | NATIONAL | | Y | 54AC175LMQB | 159 |
| 5962R8955201V2A | A | 11/12/1997 | 3 | NATIONAL | | Y | 54AC175ERQMLV | 159 |
| 5962-8955201EA | A | 11/12/1997 | 3 | NATIONAL | | Y | 54AC175DMQB | 159 |
| 5962R8955201VEA | A | 11/12/1997 | 3 | NATIONAL | | Y | 54AC175JRQMLV | 159 |
| 5962-8955201FA | A | 11/12/1997 | 3 | NATIONAL | | Y | 54AC175FMQB | 159 |
| 5962R8955201VFA | A | 11/12/1997 | 3 | NATIONAL | | Y | 54AC175WRQMLV | 159 |
| 5962-89553012A | | 02/01/1989 | 2 | TI | | | SNJ54AS640FK | 590 |
| 5962-8955301RA | | 02/01/1989 | 2 | TI | | | SNJ54AS640J | 590 |
| 5962-8955301SA | | 02/01/1989 | 2 | TI | | | SNJ54AS640W | 590 |
| 5962-89554012A | | 02/01/1989 | | (NONE) | | | 54F21 (GEN) | 114 |
| 5962-8955401CA | | 02/01/1989 | | (NONE) | | | 54F21 (GEN) | 114 |
| 5962-8955401DA | | 02/01/1989 | | (NONE) | | | 54F21 (GEN) | 114 |
| 5962-89555013A | B | 08/31/1992 | | (NONE) | 06/01/1997 | | 54F544 (GEN) | 590 |
| 5962-8955501KA | B | 08/31/1992 | | (NONE) | 09/01/1997 | | 54F544 (GEN) | 590 |
| 5962-8955501LA | B | 08/31/1992 | | (NONE) | 06/01/1997 | | 54F544 (GEN) | 590 |
| 5962-89556012A | A | 06/10/2003 | 3 | NATIONAL | | Y | 54ACT563LMQB | 341 |
| 5962-8955601RA | A | 06/10/2003 | 3 | NATIONAL | | Y | 54ACT563DMQB | 341 |
| 5962-8955601SA | A | 06/10/2003 | 3 | NATIONAL | | Y | 54ACT563FMQB | 341 |
| 5962-89557012A | A | 06/11/2003 | 3 | NATIONAL | | Y | 54ACT564LMQB | 159 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-8955701RA | A | 06/11/2003 | 3 | NATIONAL | | Y | 54ACT564DMQB | 159 |
| 5962-8955701SA | A | 06/11/2003 | 3 | NATIONAL | | Y | 54ACT564FMQB | 159 |
| 5962-89558013A | K | 10/20/2003 | 1 | NATIONAL | | Y | 54F652LMQB | 590 |
| 5962-8955801KA | K | 10/20/2003 | | (NONE) | | | 54F652 (GEN) | 590 |
| 5962-8955801LA | K | 10/20/2003 | 1 | NATIONAL | | Y | 54F652SDMQB | 590 |
| 5962-8956001XA | | 12/12/1989 | | (NONE) | | | 4461 (GEN) | 629 |
| 5962-89561012A | A | 02/26/2001 | 3 | NATIONAL | | Y | 54AC161LMQB | 304 |
| 5962-8956101EA | A | 02/26/2001 | 3 | NATIONAL | | Y | 54AC161DMQB | 304 |
| 5962-8956101FA | A | 02/26/2001 | 3 | NATIONAL | | Y | 54AC161FMQB | 304 |
| 5962-8956101VXA | A | 02/26/2001 | 2 | STMICRO | | Y | 54AC161K02V | 304 |
| 5962-8956101VXC | A | 02/26/2001 | 2 | STMICRO | | Y | 54AC161K01V | 304 |
| 5962-8956101XA | A | 02/26/2001 | 2 | STMICRO | | Y | 54AC161K02Q | 304 |
| 5962-8956101XC | A | 02/26/2001 | 2 | STMICRO | | Y | 54AC161K01Q | 304 |
| 5962-8956201GA | F | 07/23/2004 | | (NONE) | | | LT1054 (GEN) | 789 |
| 5962-8956201PA | F | 07/23/2004 | 1 | MINCO | | Y | MTL1054MJ8/883 | 789 |
| 5962-8956201XA | F | 07/23/2004 | 1 | MINCO | | Y | MTL1054MH/883 | 789 |
| 5962-8956301HXA | A | 08/06/1991 | 1 | MICRO NETWKS | | Y | MN5290H/B | 592 |
| 5962-8956301HXC | A | 08/06/1991 | 1 | MICRO NETWKS | | Y | MN5290H/B | 592 |
| 5962-8956302HXA | A | 08/06/1991 | 1 | MICRO NETWKS | | Y | MN5291H/B | 592 |
| 5962-8956302HXC | A | 08/06/1991 | 1 | MICRO NETWKS | | Y | MN5291H/B | 592 |
| 5962-8956401EA | A | 07/30/1992 | | (NONE) | 09/01/1997 | | 604A (GEN) | 820 |
| 5962-8956501XA | A | 04/24/1991 | | (NONE) | 09/01/2000 | | HS362 (GEN) | 839 |
| 5962-8956601HCA | C | 03/15/1994 | | (NONE) | | | HS9716 (GEN) | 818 |
| 5962-8956601HXA | C | 03/15/1994 | | (NONE) | 09/01/2000 | | HS9716 (GEN) | 818 |
| 5962-8956701XA | A | 01/30/2001 | | (NONE) | 10/29/2001 | | 7203L120 (GEN) | 670 |
| 5962-8956701YA | A | 01/30/2001 | | (NONE) | | | | 670 |
| 5962-8956701ZA | A | 01/30/2001 | | (NONE) | 10/29/2001 | | 7203L120 (GEN) | 670 |
| 5962-8956702XA | A | 01/30/2001 | | (NONE) | 10/29/2001 | | 7203L80 (GEN) | 670 |
| 5962-8956702YA | A | 01/30/2001 | | (NONE) | | | | 670 |
| 5962-8956702ZA | A | 01/30/2001 | | (NONE) | 10/29/2001 | | 7203L80 (GEN) | 670 |
| 5962-8956703XA | A | 01/30/2001 | | (NONE) | 10/29/2001 | | 7203L65 (GEN) | 670 |
| 5962-8956703YA | A | 01/30/2001 | | (NONE) | | | | 670 |
| 5962-8956703ZA | A | 01/30/2001 | | (NONE) | 10/29/2001 | | 7203L65 (GEN) | 670 |
| 5962-8956704XA | A | 01/30/2001 | | (NONE) | 10/29/2001 | | 7203L50 (GEN) | 670 |
| 5962-8956704YA | A | 01/30/2001 | | (NONE) | | | | 670 |
| 5962-8956704ZA | A | 01/30/2001 | | (NONE) | 10/29/2001 | | 7203L50 (GEN) | 670 |
| 5962-8956705XA | A | 01/30/2001 | 1 | IDT | | Y | IDT7203L40DB | 670 |
| 5962-8956705YA | A | 01/30/2001 | | (NONE) | | | | 670 |
| 5962-8956705ZA | A | 01/30/2001 | 1 | IDT | | Y | IDT7203L40LB | 670 |
| 5962-8956801XA | J | 07/28/2003 | | (NONE) | 10/29/2001 | | 7204L120 (GEN) | 670 |
| 5962-8956801YA | J | 07/28/2003 | | (NONE) | 10/29/2001 | | 7204L120 (GEN) | 670 |
| 5962-8956801ZA | J | 07/28/2003 | | (NONE) | 10/29/2001 | | 7204L120 (GEN) | 670 |
| 5962-8956802XA | J | 07/28/2003 | | (NONE) | 10/29/2001 | | 7204L80 (GEN) | 670 |
| 5962-8956802YA | J | 07/28/2003 | | (NONE) | 10/29/2001 | | 7204L80 (GEN) | 670 |
| 5962-8956802ZA | J | 07/28/2003 | | (NONE) | 10/29/2001 | | 7204L80 (GEN) | 670 |
| 5962-8956803XA | J | 07/28/2003 | | (NONE) | 10/29/2001 | | 7204L65 (GEN) | 670 |
| 5962-8956803YA | J | 07/28/2003 | | (NONE) | 10/29/2001 | | 7204L65 (GEN) | 670 |
| 5962-8956803ZA | J | 07/28/2003 | | (NONE) | 10/29/2001 | | 7204L65 (GEN) | 670 |
| 5962-8956804QNC | J | 07/28/2003 | | (NONE) | | | 7204-50 (GEN) | 670 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-8956804VNC | J | 07/28/2003 | | (NONE) | | | 7204-50 (GEN) | 670 |
| 5962-8956804QTC | J | 07/28/2003 | | (NONE) | | | 7204-50 (GEN) | 670 |
| 5962-8956804VTC | J | 07/28/2003 | | (NONE) | | | 7204-50 (GEN) | 670 |
| 5962-8956804QUC | J | 07/28/2003 | | (NONE) | | | 7204-50 (GEN) | 670 |
| 5962-8956804UA | J | 07/28/2003 | | (NONE) | 10/29/2001 | | 7204L50 (GEN) | 670 |
| 5962-8956804VUC | J | 07/28/2003 | | (NONE) | | | 7204-50 (GEN) | 670 |
| 5962-8956804XA | J | 07/28/2003 | | (NONE) | 10/29/2001 | | 7204L50 (GEN) | 670 |
| 5962-8956804QYC | J | 07/28/2003 | | (NONE) | | | 7204-50 (GEN) | 670 |
| 5962-8956804VYC | J | 07/28/2003 | | (NONE) | | | 7204-50 (GEN) | 670 |
| 5962-8956804YA | J | 07/28/2003 | | (NONE) | 10/29/2001 | | 7204L50 (GEN) | 670 |
| 5962-8956804ZA | J | 07/28/2003 | | (NONE) | 10/29/2001 | | 7204L50 (GEN) | 670 |
| 5962-8956805QNC | J | 07/28/2003 | | (NONE) | | | 7204-40 (GEN) | 670 |
| 5962-8956805VNC | J | 07/28/2003 | | (NONE) | | | 7204-40 (GEN) | 670 |
| 5962-8956805QTC | J | 07/28/2003 | | (NONE) | | | 7204-40 (GEN) | 670 |
| 5962-8956805VTC | J | 07/28/2003 | | (NONE) | | | 7204-40 (GEN) | 670 |
| 5962-8956805QUC | J | 07/28/2003 | | (NONE) | | | 7204-40 (GEN) | 670 |
| 5962-8956805UA | J | 07/28/2003 | | (NONE) | 10/29/2001 | | 7204L40 (GEN) | 670 |
| 5962-8956805VUC | J | 07/28/2003 | | (NONE) | | | 7204-40 (GEN) | 670 |
| 5962-8956805XA | J | 07/28/2003 | | (NONE) | 10/29/2001 | | 7204L40 (GEN) | 670 |
| 5962-8956805QYC | J | 07/28/2003 | | (NONE) | | | 7204-40 (GEN) | 670 |
| 5962-8956805VYC | J | 07/28/2003 | | (NONE) | | | 7204-40 (GEN) | 670 |
| 5962-8956805YA | J | 07/28/2003 | | (NONE) | 10/29/2001 | | 7204L40 (GEN) | 670 |
| 5962-8956805ZA | J | 07/28/2003 | | (NONE) | 10/29/2001 | | 7204L40 (GEN) | 670 |
| 5962-8956806QNC | J | 07/28/2003 | 1 | ATMEL NANTES | | Y | MMDP-67204FV-30MQ | 670 |
| 5962-8956806VNC | J | 07/28/2003 | 1 | ATMEL NANTES | | Y | SMDP-67204FV-30SV | 670 |
| 5962D8956806VNC | J | 07/28/2003 | 1 | ATMEL NANTES | | Y | SMDP-67204FV-30SR | 670 |
| 5962-8956806QTC | J | 07/28/2003 | 1 | ATMEL NANTES | | Y | MMCP-67204FV-30MQ | 670 |
| 5962-8956806VTC | J | 07/28/2003 | 1 | ATMEL NANTES | | Y | SMCP-67204FV-30SV | 670 |
| 5962D8956806VTC | J | 07/28/2003 | 1 | ATMEL NANTES | | Y | SMCP-67204FV-30SR | 670 |
| 5962-8956806QUC | J | 07/28/2003 | | (NONE) | | | 7204-30 (GEN) | 670 |
| 5962-8956806UA | J | 07/28/2003 | 1 | IDT | | Y | IDT7204L30TDB | 670 |
| 5962-8956806VUC | J | 07/28/2003 | | (NONE) | | | 7204-30 (GEN) | 670 |
| 5962-8956806XA | J | 07/28/2003 | 2 | IDT | | Y | IDT7204L30DB | 670 |
| 5962-8956806QYC | J | 07/28/2003 | | (NONE) | | | 7204-30 (GEN) | 670 |
| 5962-8956806VYC | J | 07/28/2003 | | (NONE) | | | 7204-30 (GEN) | 670 |
| 5962-8956806YA | J | 07/28/2003 | | (NONE) | 10/29/2001 | | 7204L30 (GEN) | 670 |
| 5962-8956806ZA | J | 07/28/2003 | 2 | IDT | | Y | IDT7204L30LB | 670 |
| 5962-8956807UA | J | 07/28/2003 | 1 | IDT | | Y | IDT7204L20TDB | 670 |
| 5962-8956807XA | J | 07/28/2003 | 2 | IDT | | Y | IDT7204L20DB | 670 |
| 5962-8956807YA | J | 07/28/2003 | | (NONE) | 10/29/2001 | | 7204L20 (GEN) | 670 |
| 5962-8956807ZA | J | 07/28/2003 | 2 | IDT | | Y | IDT7204L20LB | 670 |
| 5962-8956808QNC | J | 07/28/2003 | 1 | ATMEL NANTES | | Y | MMDP-67204FV-15MQ | 670 |
| 5962-8956808VNC | J | 07/28/2003 | 1 | ATMEL NANTES | | Y | SMDP-67204FV-15SV | 670 |
| 5962D8956808VNC | J | 07/28/2003 | 1 | ATMEL NANTES | | Y | SMDP-67204FV-15SR | 670 |
| 5962-8956808QTC | J | 07/28/2003 | 1 | ATMEL NANTES | | Y | MMCP-67204FV-15MQ | 670 |
| 5962-8956808VTC | J | 07/28/2003 | 1 | ATMEL NANTES | | Y | SMCP-67204FV-15SV | 670 |
| 5962D8956808VTC | J | 07/28/2003 | 1 | ATMEL NANTES | | Y | SMCP-67204FV-15SR | 670 |
| 5962-8956808QUC | J | 07/28/2003 | | (NONE) | | | 7204-15 (GEN) | 670 |
| 5962-8956808VUC | J | 07/28/2003 | | (NONE) | | | 7204-15 (GEN) | 670 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-8956808QYC | J | 07/28/2003 | | (NONE) | | | 7204-15 (GEN) | 670 |
| 5962-8956808VYC | J | 07/28/2003 | | (NONE) | | | 7204-15 (GEN) | 670 |
| 5962-8956809QNC | J | 07/28/2003 | 1 | ATMEL NANTES | | Y | MMDP-67204HV-30MQ | 670 |
| 5962-8956809VNC | J | 07/28/2003 | 1 | ATMEL NANTES | | Y | SMDP-67204HV-30SV | 670 |
| 5962D8956809VNC | J | 07/28/2003 | 1 | ATMEL NANTES | | Y | SMDP-67204HV-30SR | 670 |
| 5962-8956809QTC | J | 07/28/2003 | 1 | ATMEL NANTES | | Y | MMCP-67204HV-30MQ | 670 |
| 5962-8956809VTC | J | 07/28/2003 | 1 | ATMEL NANTES | | Y | SMCP-67204HV-30SV | 670 |
| 5962D8956809VTC | J | 07/28/2003 | 1 | ATMEL NANTES | | Y | SMCP-67204HV-30SR | 670 |
| 5962-8956810QNC | J | 07/28/2003 | 1 | ATMEL NANTES | | Y | MMDP-67204HV-25MQ | 670 |
| 5962-8956810VNC | J | 07/28/2003 | 1 | ATMEL NANTES | | Y | SMDP-67204HV-25SV | 670 |
| 5962D8956810VNC | J | 07/28/2003 | 1 | ATMEL NANTES | | Y | SMDP-67204HV-25SR | 670 |
| 5962-8956810QTC | J | 07/28/2003 | 1 | ATMEL NANTES | | Y | MMCP-67204HV-25MQ | 670 |
| 5962-8956810VTC | J | 07/28/2003 | 1 | ATMEL NANTES | | Y | SMCP-67204HV-25SV | 670 |
| 5962D8956810VTC | J | 07/28/2003 | 1 | ATMEL NANTES | | Y | SMCP-67204HV-25SR | 670 |
| 5962-8956901HXA | B | 11/01/1991 | 1 | MICRO NETWKS | | Y | MN5295H/B | 592 |
| 5962-8956901HXC | B | 11/01/1991 | 1 | MICRO NETWKS | | Y | MN5295H/B | 592 |
| 5962-8957001PA | F | 05/15/2003 | 2 | AGILENT | | Y | HCPL-5401#200 | 460 |
| 5962-8957001PA | F | 05/15/2003 | 1 | MICROPAC | | Y | 66115-105 | 460 |
| 5962-8957001PC | F | 05/15/2003 | 2 | AGILENT | | Y | HCPL-5401 | 460 |
| 5962-8957001PC | F | 05/15/2003 | 1 | MICROPAC | | Y | 66115-105 | 460 |
| 5962-8957001XA | F | 05/15/2003 | 2 | AGILENT | | Y | HCPL-5401#300 | 460 |
| 5962-8957001YA | F | 05/15/2003 | 2 | AGILENT | | Y | HCPL-5401#100 | 460 |
| 5962-8957001YC | F | 05/15/2003 | 2 | AGILENT | | Y | HCPL-5401#100 | 460 |
| 5962-8957002KPA | F | 05/15/2003 | 2 | AGILENT | | Y | HCPL-540K#200 | 460 |
| 5962-8957002KPA | F | 05/15/2003 | 1 | MICROPAC | | Y | 66115-302 | 460 |
| 5962-8957002KPC | F | 05/15/2003 | 2 | AGILENT | | Y | HCPL-540K | 460 |
| 5962-8957002KPC | F | 05/15/2003 | 1 | MICROPAC | | Y | 66115-302 | 460 |
| 5962-8957002KXA | F | 05/15/2003 | 2 | AGILENT | | Y | HCPL-540K#300 | 460 |
| 5962-8957002KYA | F | 05/15/2003 | 2 | AGILENT | | Y | HCPL-540K#100 | 460 |
| 5962-8957002KYC | F | 05/15/2003 | 2 | AGILENT | | Y | HCPL-540K#100 | 460 |
| 5962-8957101PA | E | 05/15/2003 | 3 | AGILENT | | Y | HCPL-5431#200 | 460 |
| 5962-8957101PA | E | 05/15/2003 | 1 | MICROPAC | | Y | 66115-103 | 460 |
| 5962-8957101PC | E | 05/15/2003 | 3 | AGILENT | | Y | HCPL-5431 | 460 |
| 5962-8957101PC | E | 05/15/2003 | 1 | MICROPAC | | Y | 66115-103 | 460 |
| 5962-8957101XA | E | 05/15/2003 | 3 | AGILENT | | Y | HCPL-5431#300 | 460 |
| 5962-8957101YA | E | 05/15/2003 | 3 | AGILENT | | Y | HCPL-5431#100 | 460 |
| 5962-8957101YC | E | 05/15/2003 | 3 | AGILENT | | Y | HCPL-5431#100 | 460 |
| 5962-89571022A | E | 05/15/2003 | 3 | AGILENT | | Y | HCPL-6431 | 460 |
| 5962-89571022A | E | 05/15/2003 | 1 | MICROPAC | | Y | 66136-001 | 460 |
| 5962-8957103KPA | E | 05/15/2003 | 3 | AGILENT | | Y | HCPL-543K#200 | 460 |
| 5962-8957103KPA | E | 05/15/2003 | 1 | MICROPAC | | Y | 66115-301 | 460 |
| 5962-8957103KPC | E | 05/15/2003 | 3 | AGILENT | | Y | HCPL-543K | 460 |
| 5962-8957103KPC | E | 05/15/2003 | 1 | MICROPAC | | Y | 66115-301 | 460 |
| 5962-8957103KXA | E | 05/15/2003 | 3 | AGILENT | | Y | HCPL-543K#300 | 460 |
| 5962-8957103KYA | E | 05/15/2003 | 3 | AGILENT | | Y | HCPL-543K#100 | 460 |
| 5962-8957103KYC | E | 05/15/2003 | 3 | AGILENT | | Y | HCPL-543K#100 | 460 |
| 5962-8957104K2A | E | 05/15/2003 | 3 | AGILENT | | Y | HCPL-643K | 460 |
| 5962-8957104K2A | E | 05/15/2003 | 1 | MICROPAC | | Y | 66136-301 | 460 |
| 5962-8957201EA | E | 05/15/2003 | 1 | AGILENT | | Y | HCPL-1931#200 | 460 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-8957201EC | E | 05/15/2003 | 1 | AGILENT | | Y | HCPL-1931 | 460 |
| 5962-8957201XA | E | 05/15/2003 | 1 | AGILENT | | Y | HCPL-1931#300 | 460 |
| 5962-8957201YA | E | 05/15/2003 | 1 | AGILENT | | Y | HCPL-1931#100 | 460 |
| 5962-8957201YC | E | 05/15/2003 | 1 | AGILENT | | Y | HCPL-1931#100 | 460 |
| 5962-8957202KEA | E | 05/15/2003 | 1 | AGILENT | | Y | HCPL-193K#200 | 460 |
| 5962-8957202KEC | E | 05/15/2003 | 1 | AGILENT | | Y | HCPL-193K | 460 |
| 5962-8957202KXA | E | 05/15/2003 | 1 | AGILENT | | Y | HCPL-193K#300 | 460 |
| 5962-8957202KYA | E | 05/15/2003 | 1 | AGILENT | | Y | HCPL-193K#100 | 460 |
| 5962-8957202KYC | E | 05/15/2003 | 1 | AGILENT | | Y | HCPL-193K#100 | 460 |
| 5962-89573012A | C | 09/11/1992 | | (NONE) | 06/01/1997 | | 54F299 (GEN) | 228 |
| 5962-8957301RA | C | 09/11/1992 | | (NONE) | 06/01/1997 | | 54F299 (GEN) | 228 |
| 5962-8957301SA | C | 09/11/1992 | | (NONE) | 06/01/1997 | | 54F299 (GEN) | 228 |
| 5962-89574012A | A | 07/10/1992 | | (NONE) | 12/31/2001 | | 54ALS165 (GEN) | 225 |
| 5962-8957401EA | A | 07/10/1992 | | (NONE) | 12/31/2001 | | 54ALS165 (GEN) | 225 |
| 5962-8957401FA | A | 07/10/1992 | | (NONE) | 12/31/2001 | | 54ALS165 (GEN) | 225 |
| 5962-8957501XA | B | 05/25/2001 | 1 | UTMC | | Y | UT1760ARTSGA | 599 |
| 5962-8957501XC | B | 05/25/2001 | 1 | UTMC | | Y | UT1760ARTSGC | 599 |
| 5962-8957501YA | B | 05/25/2001 | | (NONE) | | | UT1760ARTS (GEN) | 599 |
| 5962-8957501ZA | B | 05/25/2001 | | (NONE) | | | UT1760ARTS (GEN) | 599 |
| 5962-8957601XA | B | 06/18/2001 | 1 | UTMC | | Y | UT1553BRTRGA | 590 |
| 5962-8957601XC | B | 06/18/2001 | 1 | UTMC | | Y | UT1553BRTRGC | 590 |
| 5962-8957601YA | B | 06/18/2001 | 1 | UTMC | | Y | UT1553BRTRWA | 590 |
| 5962-8957601YC | B | 06/18/2001 | 1 | UTMC | | Y | UT1553BRTRWC | 590 |
| 5962-8957601ZA | B | 06/18/2001 | 1 | UTMC | | Y | UT1553BRTRAA | 590 |
| 5962-8957601ZC | B | 06/18/2001 | 1 | UTMC | | Y | UT1553BRTRAC | 590 |
| 5962-8957701Q9A | H | 07/23/2002 | 1 | UTMC | | Y | UT1553BCRTM-QDIE | 420 |
| 5962-8957701V9A | H | 07/23/2002 | 1 | UTMC | | Y | UT1553BCRTM-VDIE | 420 |
| 5962H8957701Q9B | H | 07/23/2002 | 1 | UTMC | | Y | UT1553BCRTM-QDIE | 420 |
| 5962H8957701V9B | H | 07/23/2002 | 1 | UTMC | | Y | UT1553BCRTM-VDIE | 420 |
| 5962-8957701XA | H | 07/23/2002 | 1 | UTMC | | Y | UT1553BCRTMG | 420 |
| 5962-8957701XC | H | 07/23/2002 | 1 | UTMC | | Y | UT1553BCRTMG | 420 |
| 5962H8957701VXA | H | 07/23/2002 | 1 | UTMC | | Y | UT1553BCRTMVGAH | 420 |
| 5962H8957701VXC | H | 07/23/2002 | 1 | UTMC | | Y | UT1553BCRTMVGCH | 420 |
| 5962H8957701XA | H | 07/23/2002 | 1 | UTMC | | Y | UT1553BCRTMGAH | 420 |
| 5962H8957701XC | H | 07/23/2002 | 1 | UTMC | | Y | UT1553BCRTMGCH | 420 |
| 5962-8957701YA | H | 07/23/2002 | 1 | UTMC | | Y | UT1553BCRTMW | 420 |
| 5962-8957701YC | H | 07/23/2002 | 1 | UTMC | | Y | UT1553BCRTMW | 420 |
| 5962H8957701VYA | H | 07/23/2002 | 1 | UTMC | | Y | UT1553BCRTMVWAH | 420 |
| 5962H8957701VYC | H | 07/23/2002 | 1 | UTMC | | Y | UT1553BCRTMVWCH | 420 |
| 5962H8957701YA | H | 07/23/2002 | 1 | UTMC | | Y | UT1553BCRTMWAH | 420 |
| 5962H8957701YC | H | 07/23/2002 | 1 | UTMC | | Y | UT1553BCRTMWCH | 420 |
| 5962-8957701ZA | H | 07/23/2002 | 1 | UTMC | | Y | UT1553BCRTMA | 420 |
| 5962-8957701ZC | H | 07/23/2002 | 1 | UTMC | | Y | UT1553BCRTMA | 420 |
| 5962H8957701VZA | H | 07/23/2002 | 1 | UTMC | | Y | UT1553BCRTMVAAH | 420 |
| 5962H8957701VZC | H | 07/23/2002 | 1 | UTMC | | Y | UT1553BCRTMVACH | 420 |
| 5962H8957701ZA | H | 07/23/2002 | 1 | UTMC | | Y | UT1553BCRTMAAH | 420 |
| 5962H8957701ZC | H | 07/23/2002 | 1 | UTMC | | Y | UT1553BCRTMACH | 420 |
| 5962-89581012A | D | 04/15/2002 | | (NONE) | 04/30/2003 | | REF01A (GEN) | 785 |
| 5962-8958101V2A | D | 04/15/2002 | 2 | ANALOG (5) | | Y | REF01ARC/QMLV | 785 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962R8958101V2A | D | 04/15/2002 | 2 | ANALOG (5) | | Y | REF01ARC/QMLR | 785 |
| 5962-8958101GA | D | 04/15/2002 | | (NONE) | 04/30/2003 | | REF01A (GEN) | 785 |
| 5962-8958101VGA | D | 04/15/2002 | 2 | ANALOG (5) | | Y | REF01AJ/QMLV | 785 |
| 5962R8958101VGA | D | 04/15/2002 | 2 | ANALOG (5) | | Y | REF01AJ/QMLR | 785 |
| 5962-8958101VHA | D | 04/15/2002 | 2 | ANALOG (5) | | Y | REF01AL/QMLV | 785 |
| 5962R8958101VHA | D | 04/15/2002 | 2 | ANALOG (5) | | Y | REF01AL/QMLR | 785 |
| 5962-8958101PA | D | 04/15/2002 | 2 | ANALOG (5) | | Y | REF01AZ/883C | 785 |
| 5962-8958101VPA | D | 04/15/2002 | 2 | ANALOG (5) | | Y | REF01AZ/QMLV | 785 |
| 5962R8958101VPA | D | 04/15/2002 | 2 | ANALOG (5) | | Y | REF01AZ/QMLR | 785 |
| 5962-89581022A | D | 04/15/2002 | | (NONE) | 04/30/2003 | | REF01 (GEN) | 785 |
| 5962-8958102GA | D | 04/15/2002 | | (NONE) | 04/14/2001 | | REF01 (GEN) | 785 |
| 5962-8958102PA | D | 04/15/2002 | | (NONE) | 04/14/2001 | | REF01 (GEN) | 785 |
| 5962-89581032C | D | 04/15/2002 | 1 | MAXIM INTEG. | | | REF01ARC/883B | 785 |
| 5962-8958103GC | D | 04/15/2002 | 1 | MAXIM INTEG. | | | REF01AJ/883B | 785 |
| 5962-8958103PA | D | 04/15/2002 | 1 | MAXIM INTEG. | | | REF01AZ/883B | 785 |
| 5962-89581042C | D | 04/15/2002 | 1 | MAXIM INTEG. | | | REF01RC/883B | 785 |
| 5962-8958104GC | D | 04/15/2002 | 1 | MAXIM INTEG. | | | REF01J/883B | 785 |
| 5962-8958104PA | D | 04/15/2002 | 1 | MAXIM INTEG. | | | REF01Z/883B | 785 |
| 5962-89582012A | A | 05/10/2001 | 2 | NATIONAL | | Y | 54AC163LMQB | 304 |
| 5962-8958201EA | A | 05/10/2001 | 2 | NATIONAL | | Y | 54AC163DMQB | 304 |
| 5962-8958201FA | A | 05/10/2001 | 2 | NATIONAL | | Y | 54AC163FMQB | 304 |
| 5962-8958201VXA | A | 05/10/2001 | 2 | STMICRO | | Y | 54AC163K02V | 304 |
| 5962-8958201VXC | A | 05/10/2001 | 2 | STMICRO | | Y | 54AC163K01V | 304 |
| 5962-8958201XA | A | 05/10/2001 | 2 | STMICRO | | Y | 54AC163K02Q | 304 |
| 5962-8958201XC | A | 05/10/2001 | 2 | STMICRO | | Y | 54AC163K01Q | 304 |
| 5962-8958301XA | C | 10/27/2003 | | (NONE) | | | MN5200 (GEN) | 592 |
| 5962-8958301YA | C | 10/27/2003 | | (NONE) | | | MN5200 (GEN) | 592 |
| 5962-8958302XA | C | 10/27/2003 | | (NONE) | | | MN5203 (GEN) | 592 |
| 5962-8958302YA | C | 10/27/2003 | | (NONE) | | | MN5203 (GEN) | 592 |
| 5962-8958303XA | C | 10/27/2003 | | (NONE) | | | MN5201 (GEN) | 592 |
| 5962-8958303YA | C | 10/27/2003 | 1 | MICRO NETWKS | | Y | MN5201MYA | 592 |
| 5962-8958303YC | C | 10/27/2003 | 1 | MICRO NETWKS | | Y | MN5201MYC | 592 |
| 5962-8958304XA | C | 10/27/2003 | | (NONE) | | | MN5204 (GEN) | 592 |
| 5962-8958304YA | C | 10/27/2003 | | (NONE) | 01/31/2003 | | MN5204 (GEN) | 592 |
| 5962-8958305XA | C | 10/27/2003 | 1 | MICRO NETWKS | | Y | MN5202MXA | 592 |
| 5962-8958305XC | C | 10/27/2003 | 1 | MICRO NETWKS | | Y | MN5202MXC | 592 |
| 5962-8958305YA | C | 10/27/2003 | 1 | MICRO NETWKS | | Y | MN5202MYA | 592 |
| 5962-8958305YC | C | 10/27/2003 | 1 | MICRO NETWKS | | Y | MN5202MYC | 592 |
| 5962-8958306XA | C | 10/27/2003 | | (NONE) | | | MN5205 (GEN) | 592 |
| 5962-8958306YA | C | 10/27/2003 | 1 | MICRO NETWKS | | Y | MN5205MYA | 592 |
| 5962-8958306YC | C | 10/27/2003 | 1 | MICRO NETWKS | | Y | MN5205MYC | 592 |
| 5962-8958307XA | C | 10/27/2003 | | (NONE) | | | MN5206 (GEN) | 592 |
| 5962-8958307YA | C | 10/27/2003 | | (NONE) | | | MN5206 (GEN) | 592 |
| 5962-8958401XA | C | 10/31/2003 | | (NONE) | | | MN5210 (GEN) | 592 |
| 5962-8958401YA | C | 10/31/2003 | | (NONE) | | | MN5210 (GEN) | 592 |
| 5962-8958402XA | C | 10/31/2003 | | (NONE) | | | MN5213 (GEN) | 592 |
| 5962-8958402YA | C | 10/31/2003 | 1 | MICRO NETWKS | | Y | MN5213MYA | 592 |
| 5962-8958402YC | C | 10/31/2003 | 1 | MICRO NETWKS | | Y | MN5213MYC | 592 |
| 5962-8958403XA | C | 10/31/2003 | 1 | MICRO NETWKS | | Y | MN5211MXA | 592 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-8958403XC | C | 10/31/2003 | 1 | MICRO NETWKS | | Y | MN5211MXC | 592 |
| 5962-8958403YA | C | 10/31/2003 | 1 | MICRO NETWKS | | Y | MN5211MYA | 592 |
| 5962-8958403YC | C | 10/31/2003 | 1 | MICRO NETWKS | | Y | MN5211MYC | 592 |
| 5962-8958404XA | C | 10/31/2003 | | (NONE) | | | MN5214 (GEN) | 592 |
| 5962-8958404YA | C | 10/31/2003 | 1 | MICRO NETWKS | | Y | MN5214MYA | 592 |
| 5962-8958404YC | C | 10/31/2003 | 1 | MICRO NETWKS | | Y | MN5214MYC | 592 |
| 5962-8958405XA | C | 10/31/2003 | 1 | MICRO NETWKS | | Y | MN5212MXA | 592 |
| 5962-8958405XC | C | 10/31/2003 | 1 | MICRO NETWKS | | Y | MN5212MXC | 592 |
| 5962-8958405YA | C | 10/31/2003 | 1 | MICRO NETWKS | | Y | MN5212MYA | 592 |
| 5962-8958405YC | C | 10/31/2003 | 1 | MICRO NETWKS | | Y | MN5212MYC | 592 |
| 5962-8958406XA | C | 10/31/2003 | 1 | MICRO NETWKS | | Y | MN5215MXA | 592 |
| 5962-8958406XC | C | 10/31/2003 | 1 | MICRO NETWKS | | Y | MN5215MXC | 592 |
| 5962-8958406YA | C | 10/31/2003 | 1 | MICRO NETWKS | | Y | MN5215MYA | 592 |
| 5962-8958406YC | C | 10/31/2003 | 1 | MICRO NETWKS | | Y | MN5215MYC | 592 |
| 5962-8958407XA | C | 10/31/2003 | 1 | MICRO NETWKS | | Y | MN5216MXA | 592 |
| 5962-8958407XC | C | 10/31/2003 | 1 | MICRO NETWKS | | Y | MN5216MXC | 592 |
| 5962-8958407YA | C | 10/31/2003 | 1 | MICRO NETWKS | | Y | MN5216MYA | 592 |
| 5962-8958407YC | C | 10/31/2003 | 1 | MICRO NETWKS | | Y | MN5216MYC | 592 |
| 5962-8958601GA | B | 12/23/1994 | | (NONE) | 09/09/1998 | | LM1578 (GEN) | 786 |
| 5962-8958602GA | B | 12/23/1994 | | (NONE) | 03/09/1999 | | LM1578A (GEN) | 786 |
| 5962-8958701EA | G | 03/29/2002 | 3 | NATIONAL | | Y | LM2940J-5.0/883 | 782 |
| 5962-8958701MA | G | 03/29/2002 | 1 | INTER. RECT. | | | OM2940-5SRM/883B | 782 |
| 5962-8958701NA | G | 03/29/2002 | 1 | INTER. RECT. | | | OM2940-5N5M/883B | 782 |
| 5962-8958701UA | G | 03/29/2002 | 1 | INTER. RECT. | | | OM2940-5STM | 782 |
| 5962-8958701XA | G | 03/29/2002 | 3 | NATIONAL | | Y | LM2940WG5.0/883 | 782 |
| 5962-8958701YA | G | 03/29/2002 | | (NONE) | 09/09/1999 | | LM2940-5.0 (GEN) | 782 |
| 5962-8958801GA | | 10/11/1989 | | (NONE) | 09/04/2001 | | LM105 (GEN) | 780 |
| 5962-8958901CA | A | 08/19/2001 | | (NONE) | 03/09/1999 | | LM107 (GEN) | 701 |
| 5962-8958901GA | A | 08/19/2001 | 1 | NATIONAL | | Y | LM107H/883 | 701 |
| 5962-8958901PA | A | 08/19/2001 | | (NONE) | 03/09/1999 | | LM107 (GEN) | 701 |
| 5962-8959001PA | A | 05/31/1994 | | (NONE) | 04/07/2000 | | 24C04 (GEN) | 656 |
| 5962-8959201XA | B | 11/06/1991 | 1 | AEROFLEX | | Y | ARX3407 | 590 |
| 5962-8959201XC | B | 11/06/1991 | 1 | AEROFLEX | | Y | ARX3407 | 590 |
| 5962-8959201YA | B | 11/06/1991 | 1 | AEROFLEX | | Y | ARX3407FP | 590 |
| 5962-8959201YC | B | 11/06/1991 | 1 | AEROFLEX | | Y | ARX3407FP | 590 |
| 5962-8959202XA | B | 11/06/1991 | 1 | AEROFLEX | | Y | ARX3404 | 590 |
| 5962-8959202XC | B | 11/06/1991 | 1 | AEROFLEX | | Y | ARX3404 | 590 |
| 5962-8959202YA | B | 11/06/1991 | 1 | AEROFLEX | | Y | ARX3404FP | 590 |
| 5962-8959202YC | B | 11/06/1991 | 1 | AEROFLEX | | Y | ARX3404FP | 590 |
| 5962-8959203XA | B | 11/06/1991 | 1 | AEROFLEX | | Y | ARX3407-001 | 590 |
| 5962-8959203XC | B | 11/06/1991 | 1 | AEROFLEX | | Y | ARX3407-001 | 590 |
| 5962-8959203YA | B | 11/06/1991 | 1 | AEROFLEX | | Y | ARX3407-001FP | 590 |
| 5962-8959203YC | B | 11/06/1991 | 1 | AEROFLEX | | Y | ARX3407-001FP | 590 |
| 5962-8959204XA | B | 11/06/1991 | 1 | AEROFLEX | | Y | ARX3404-001 | 590 |
| 5962-8959204XC | B | 11/06/1991 | 1 | AEROFLEX | | Y | ARX3404-001 | 590 |
| 5962-8959204YA | B | 11/06/1991 | 1 | AEROFLEX | | Y | ARX3404-001FP | 590 |
| 5962-8959204YC | B | 11/06/1991 | 1 | AEROFLEX | | Y | ARX3404-001FP | 590 |
| 5962-8959205XA | B | 11/06/1991 | 1 | AEROFLEX | | Y | ARX3467 | 590 |
| 5962-8959205XC | B | 11/06/1991 | 1 | AEROFLEX | | Y | ARX3467 | 590 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-8959205YA | B | 11/06/1991 | 1 | AEROFLEX | | Y | ARX3467FP | 590 |
| 5962-8959205YC | B | 11/06/1991 | 1 | AEROFLEX | | Y | ARX3467FP | 590 |
| 5962-8959206XA | B | 11/06/1991 | 1 | AEROFLEX | | Y | ARX3464 | 590 |
| 5962-8959206XC | B | 11/06/1991 | 1 | AEROFLEX | | Y | ARX3464 | 590 |
| 5962-8959206YA | B | 11/06/1991 | 1 | AEROFLEX | | Y | ARX3464FP | 590 |
| 5962-8959206YC | B | 11/06/1991 | 1 | AEROFLEX | | Y | ARX3464FP | 590 |
| 5962-8959301YA | D | 09/26/1995 | | (NONE) | 12/24/1997 | | 8238016 (GEN) | 423 |
| 5962-8959301ZA | D | 09/26/1995 | | (NONE) | 12/24/1997 | | 8238016 (GEN) | 423 |
| 5962-8959302YA | D | 09/26/1995 | | (NONE) | 12/24/1997 | | 8238020 (GEN) | 423 |
| 5962-8959302ZA | D | 09/26/1995 | | (NONE) | 12/24/1997 | | 8238020 (GEN) | 423 |
| 5962-8959303YA | D | 09/26/1995 | | (NONE) | 12/24/1997 | | 8238025 (GEN) | 423 |
| 5962-8959303ZA | D | 09/26/1995 | | (NONE) | 12/24/1997 | | 8238025 (GEN) | 423 |
| 5962-8959401XA | C | 06/07/2000 | | (NONE) | 09/27/2002 | | CLC231A (GEN) | 701 |
| 5962-8959501XA | A | 06/25/1993 | 1 | MICRO NETWKS | | Y | MN5245H/B | 592 |
| 5962-8959501XC | A | 06/25/1993 | 1 | MICRO NETWKS | | Y | MN5245H/B | 592 |
| 5962-8959501YA | A | 06/25/1993 | | (NONE) | | | MN5245 (GEN) | 592 |
| 5962-8959502XA | A | 06/25/1993 | 1 | MICRO NETWKS | | Y | MN5245AH/B | 592 |
| 5962-8959502XC | A | 06/25/1993 | 1 | MICRO NETWKS | | Y | MN5245AH/B | 592 |
| 5962-8959502YA | A | 06/25/1993 | | (NONE) | | | MN5245A (GEN) | 592 |
| 5962-8959503XA | A | 06/25/1993 | 1 | MICRO NETWKS | | Y | MN5246H/B | 592 |
| 5962-8959503XC | A | 06/25/1993 | 1 | MICRO NETWKS | | Y | MN5246H/B | 592 |
| 5962-8959503YA | A | 06/25/1993 | | (NONE) | | | MN5246 (GEN) | 592 |
| 5962-8959504XA | A | 06/25/1993 | 1 | MICRO NETWKS | | Y | MN5246AH/B | 592 |
| 5962-8959504XC | A | 06/25/1993 | 1 | MICRO NETWKS | | Y | MN5246AH/B | 592 |
| 5962-8959504YA | A | 06/25/1993 | | (NONE) | | | MN5246A (GEN) | 592 |
| 5962-8959601YA | D | 05/04/2004 | 1 | ROCHESTER | | Y | MQ8097BH/BYA | 420 |
| 5962-8959601YC | D | 05/04/2004 | 1 | ROCHESTER | | Y | MQ8097BH/BYC | 420 |
| 5962-8959601ZA | D | 05/04/2004 | 1 | ROCHESTER | | Y | MG8097BH/BZA | 420 |
| 5962-8959601ZC | D | 05/04/2004 | 1 | ROCHESTER | | Y | MG8097BH/BZC | 420 |
| 5962-8959801M8A | N | 08/12/2003 | | (NONE) | | | | 625 |
| 5962-8959801M9A | N | 08/12/2003 | | (NONE) | | | | 625 |
| 5962-8959801MNA | N | 08/12/2003 | | (NONE) | | | L7C108-120 (GEN) | 625 |
| 5962-8959801MTA | N | 08/12/2003 | | (NONE) | | | L7C108-120 (GEN) | 625 |
| 5962-8959801MUA | N | 08/12/2003 | | (NONE) | | | | 625 |
| 5962-8959801MXA | N | 08/12/2003 | | (NONE) | | | | 625 |
| 5962-8959801MYA | N | 08/12/2003 | | (NONE) | | | L7C108-120 (GEN) | 625 |
| 5962-8959801MZA | N | 08/12/2003 | | (NONE) | | | L7C108-120 (GEN) | 625 |
| 5962-8959802M8A | N | 08/12/2003 | | (NONE) | | | | 625 |
| 5962-8959802M9A | N | 08/12/2003 | | (NONE) | | | | 625 |
| 5962-8959802MNA | N | 08/12/2003 | | (NONE) | | | L7C108-100 (GEN) | 625 |
| 5962-8959802MTA | N | 08/12/2003 | | (NONE) | | | L7C108-100 (GEN) | 625 |
| 5962-8959802MUA | N | 08/12/2003 | | (NONE) | | | | 625 |
| 5962-8959802MXA | N | 08/12/2003 | | (NONE) | | | | 625 |
| 5962-8959802MYA | N | 08/12/2003 | | (NONE) | | | L7C108-100 (GEN) | 625 |
| 5962-8959802MZA | N | 08/12/2003 | | (NONE) | | | L7C108-100 (GEN) | 625 |
| 5962-8959803M8A | N | 08/12/2003 | | (NONE) | | | | 625 |
| 5962-8959803M9A | N | 08/12/2003 | | (NONE) | | | | 625 |
| 5962-8959803MNA | N | 08/12/2003 | | (NONE) | | | L7C108-85 (GEN) | 625 |
| 5962-8959803MTA | N | 08/12/2003 | | (NONE) | | | L7C108-85 (GEN) | 625 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-8959803MUA | N | 08/12/2003 | | (NONE) | | | | 625 |
| 5962-8959803MXA | N | 08/12/2003 | | (NONE) | | | | 625 |
| 5962-8959803MYA | N | 08/12/2003 | | (NONE) | | | L7C108-85 (GEN) | 625 |
| 5962-8959803MZA | N | 08/12/2003 | | (NONE) | | | L7C108-85 (GEN) | 625 |
| 5962-8959804M8A | N | 08/12/2003 | | (NONE) | | | | 625 |
| 5962-8959804M9A | N | 08/12/2003 | | (NONE) | | | | 625 |
| 5962-8959804MNA | N | 08/12/2003 | | (NONE) | | | L7C108-70 (GEN) | 625 |
| 5962-8959804MTA | N | 08/12/2003 | | (NONE) | | | L7C108-70 (GEN) | 625 |
| 5962-8959804MUA | N | 08/12/2003 | | (NONE) | | | | 625 |
| 5962-8959804MXA | N | 08/12/2003 | | (NONE) | | | | 625 |
| 5962-8959804MYA | N | 08/12/2003 | | (NONE) | | | L7C108-70 (GEN) | 625 |
| 5962-8959804MZA | N | 08/12/2003 | | (NONE) | | | L7C108-70 (GEN) | 625 |
| 5962-8959805M7A | N | 08/12/2003 | 1 | AUSTIN SEMI. | | Y | MT5C1009DCJ-120L88 | 625 |
| 5962-8959805M8A | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88128LPS120ZB | 625 |
| 5962-8959805M9A | N | 08/12/2003 | | (NONE) | | | | 625 |
| 5962-8959805MMA | N | 08/12/2003 | 1 | AUSTIN SEMI. | | Y | MT5C1009ECA-120L88 | 625 |
| 5962-8959805MNA | N | 08/12/2003 | | (NONE) | | | L7C108-120 (GEN) | 625 |
| 5962-8959805BTA | N | 08/12/2003 | | (NONE) | | | | 625 |
| 5962-8959805MTA | N | 08/12/2003 | 1 | AUSTIN SEMI. | | Y | MT5C1009F-120L883C | 625 |
| 5962-8959805MTA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88128LPS120FB | 625 |
| 5962-8959805BUA | N | 08/12/2003 | | (NONE) | | | | 625 |
| 5962-8959805MUA | N | 08/12/2003 | 1 | AUSTIN SEMI. | | Y | MT5C1009EC-120L883 | 625 |
| 5962-8959805MUA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88128LPS120LB | 625 |
| 5962-8959805BXA | N | 08/12/2003 | | (NONE) | | | | 625 |
| 5962-8959805MXA | N | 08/12/2003 | 1 | AUSTIN SEMI. | | Y | MT5C1009CW-120L883 | 625 |
| 5962-8959805MXA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88128LPS120CB | 625 |
| 5962-8959805MYA | N | 08/12/2003 | 1 | AUSTIN SEMI. | | Y | MT5C1009SOJ-120L88 | 625 |
| 5962-8959805MYA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88128LPS120NB | 625 |
| 5962-8959805BZA | N | 08/12/2003 | | (NONE) | | | | 625 |
| 5962-8959805MZA | N | 08/12/2003 | 1 | AUSTIN SEMI. | | Y | MT5C1009C-120L883C | 625 |
| 5962-8959805MZA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88128LPS120TB | 625 |
| 5962-8959806M7A | N | 08/12/2003 | 1 | AUSTIN SEMI. | | Y | MT5C1009DCJ-100L88 | 625 |
| 5962-8959806M8A | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88128LPS100ZB | 625 |
| 5962-8959806M9A | N | 08/12/2003 | | (NONE) | | | | 625 |
| 5962-8959806MMA | N | 08/12/2003 | 1 | AUSTIN SEMI. | | Y | MT5C1009ECA-100L88 | 625 |
| 5962-8959806MNA | N | 08/12/2003 | | (NONE) | | | L7C108-100 (GEN) | 625 |
| 5962-8959806BTA | N | 08/12/2003 | | (NONE) | | | | 625 |
| 5962-8959806MTA | N | 08/12/2003 | 1 | AUSTIN SEMI. | | Y | MT5C1009F-100L883C | 625 |
| 5962-8959806MTA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88128LPS100FB | 625 |
| 5962-8959806BUA | N | 08/12/2003 | | (NONE) | | | | 625 |
| 5962-8959806MUA | N | 08/12/2003 | 1 | AUSTIN SEMI. | | Y | MT5C1009EC-100L883 | 625 |
| 5962-8959806MUA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88128LPS100LB | 625 |
| 5962-8959806BXA | N | 08/12/2003 | | (NONE) | | | | 625 |
| 5962-8959806MXA | N | 08/12/2003 | 1 | AUSTIN SEMI. | | Y | MT5C1009CW-100L883 | 625 |
| 5962-8959806MXA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88128LPS100CB | 625 |
| 5962-8959806MYA | N | 08/12/2003 | 1 | AUSTIN SEMI. | | Y | MT5C1009SOJ-100L88 | 625 |
| 5962-8959806MYA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88128LPS100NB | 625 |
| 5962-8959806BZA | N | 08/12/2003 | | (NONE) | | | | 625 |
| 5962-8959806MZA | N | 08/12/2003 | 1 | AUSTIN SEMI. | | Y | MT5C1009C-100L883C | 625 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-8959806MZA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88128LPS100TB | 625 |
| 5962-8959807M7A | N | 08/12/2003 | 1 | AUSTIN SEMI. | | Y | MT5C1009DCJ-85L883 | 625 |
| 5962-8959807M8A | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88128LPS85ZB | 625 |
| 5962-8959807M9A | N | 08/12/2003 | | (NONE) | | | | 625 |
| 5962-8959807MMA | N | 08/12/2003 | 1 | AUSTIN SEMI. | | Y | MT5C1009ECA-85L883 | 625 |
| 5962-8959807MNA | N | 08/12/2003 | | (NONE) | | | L7C108-85 (GEN) | 625 |
| 5962-8959807BTA | N | 08/12/2003 | | (NONE) | | | | 625 |
| 5962-8959807MTA | N | 08/12/2003 | 1 | AUSTIN SEMI. | | Y | MT5C1009F-85L883C | 625 |
| 5962-8959807MTA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88128LPS85FB | 625 |
| 5962-8959807BUA | N | 08/12/2003 | | (NONE) | | | | 625 |
| 5962-8959807MUA | N | 08/12/2003 | 1 | AUSTIN SEMI. | | Y | MT5C1009EC-85L883C | 625 |
| 5962-8959807MUA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88128LPS85LB | 625 |
| 5962-8959807BXA | N | 08/12/2003 | | (NONE) | | | | 625 |
| 5962-8959807MXA | N | 08/12/2003 | 1 | AUSTIN SEMI. | | Y | MT5C1009CW-85L883C | 625 |
| 5962-8959807MXA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88128LPS85CB | 625 |
| 5962-8959807MYA | N | 08/12/2003 | 1 | AUSTIN SEMI. | | Y | MT5C1009SOJ-85L883 | 625 |
| 5962-8959807MYA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88128LPS85NB | 625 |
| 5962-8959807BZA | N | 08/12/2003 | | (NONE) | | | | 625 |
| 5962-8959807MZA | N | 08/12/2003 | 1 | AUSTIN SEMI. | | Y | MT5C1009C-85L883C | 625 |
| 5962-8959807MZA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88128LPS85TB | 625 |
| 5962-8959808M7A | N | 08/12/2003 | 1 | AUSTIN SEMI. | | Y | MT5C1009DCJ-70L883 | 625 |
| 5962-8959808M8A | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88128LPS70ZB | 625 |
| 5962-8959808M9A | N | 08/12/2003 | | (NONE) | | | | 625 |
| 5962-8959808MMA | N | 08/12/2003 | 1 | AUSTIN SEMI. | | Y | MT5C1009ECA-70L883 | 625 |
| 5962-8959808MNA | N | 08/12/2003 | | (NONE) | | | L7C108-70 (GEN) | 625 |
| 5962-8959808BTA | N | 08/12/2003 | | (NONE) | | | | 625 |
| 5962-8959808MTA | N | 08/12/2003 | 1 | AUSTIN SEMI. | | Y | MT5C1009F-70L883C | 625 |
| 5962-8959808MTA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88128LPS70FB | 625 |
| 5962-8959808BUA | N | 08/12/2003 | | (NONE) | | | | 625 |
| 5962-8959808MUA | N | 08/12/2003 | 1 | AUSTIN SEMI. | | Y | MT5C1009EC-70L883C | 625 |
| 5962-8959808MUA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88128LPS70LB | 625 |
| 5962-8959808BXA | N | 08/12/2003 | | (NONE) | | | | 625 |
| 5962-8959808MXA | N | 08/12/2003 | 1 | AUSTIN SEMI. | | Y | MT5C1009CW-70L883C | 625 |
| 5962-8959808MXA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88128LPS70CB | 625 |
| 5962-8959808MYA | N | 08/12/2003 | 1 | AUSTIN SEMI. | | Y | MT5C1009SOJ-70L883 | 625 |
| 5962-8959808MYA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88128LPS70NB | 625 |
| 5962-8959808BZA | N | 08/12/2003 | | (NONE) | | | | 625 |
| 5962-8959808MZA | N | 08/12/2003 | 1 | AUSTIN SEMI. | | Y | MT5C1009C-70L883C | 625 |
| 5962-8959808MZA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88128LPS70TB | 625 |
| 5962-8959809M7A | N | 08/12/2003 | 1 | AUSTIN SEMI. | | Y | MT5C1009DCJ-55L | 625 |
| 5962-8959809M8A | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88128LPS55ZB | 625 |
| 5962-8959809M9A | N | 08/12/2003 | | (NONE) | | | | 625 |
| 5962-8959809MMA | N | 08/12/2003 | 1 | AUSTIN SEMI. | | Y | MT5C1009ECA-55L883 | 625 |
| 5962-8959809MNA | N | 08/12/2003 | | (NONE) | | | L7C108-55 (GEN) | 625 |
| 5962-8959809BTA | N | 08/12/2003 | | (NONE) | | | | 625 |
| 5962-8959809MTA | N | 08/12/2003 | 1 | AUSTIN SEMI. | | Y | MT5C1009F-55L883C | 625 |
| 5962-8959809MTA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88128LPS55FB | 625 |
| 5962-8959809BUA | N | 08/12/2003 | | (NONE) | | | | 625 |
| 5962-8959809MUA | N | 08/12/2003 | 1 | AUSTIN SEMI. | | Y | MT5C1009EC-55L883C | 625 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-8959809MUA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88128LPS55LB | 625 |
| 5962-8959809BXA | N | 08/12/2003 | | (NONE) | | | | 625 |
| 5962-8959809MXA | N | 08/12/2003 | 1 | AUSTIN SEMI. | | Y | MT5C1009CW-55L883C | 625 |
| 5962-8959809MXA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88128LPS55CB | 625 |
| 5962-8959809MYA | N | 08/12/2003 | 1 | AUSTIN SEMI. | | Y | MT5C1009SOJ-55L883 | 625 |
| 5962-8959809MYA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88128LPS55NB | 625 |
| 5962-8959809BZA | N | 08/12/2003 | | (NONE) | | | | 625 |
| 5962-8959809MZA | N | 08/12/2003 | 1 | AUSTIN SEMI. | | Y | MT5C1009C-55L883C | 625 |
| 5962-8959809MZA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88128LPS55TB | 625 |
| 5962-8959810M7A | N | 08/12/2003 | 1 | AUSTIN SEMI. | | Y | MT5C1009DCJ-45L883 | 625 |
| 5962-8959810M8A | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88128LPS45ZB | 625 |
| 5962-8959810M9A | N | 08/12/2003 | | (NONE) | | | | 625 |
| 5962-8959810MMA | N | 08/12/2003 | 1 | AUSTIN SEMI. | | Y | MT5C1009ECA-45L883 | 625 |
| 5962-8959810MNA | N | 08/12/2003 | | (NONE) | | | L7C108-45 (GEN) | 625 |
| 5962-8959810BTA | N | 08/12/2003 | | (NONE) | | | | 625 |
| 5962-8959810MTA | N | 08/12/2003 | 1 | AUSTIN SEMI. | | Y | MT5C1009F-45L883C | 625 |
| 5962-8959810MTA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88128LPS45FB | 625 |
| 5962-8959810BUA | N | 08/12/2003 | | (NONE) | | | | 625 |
| 5962-8959810MUA | N | 08/12/2003 | 1 | AUSTIN SEMI. | | Y | MT5C1009EC-45L883C | 625 |
| 5962-8959810MUA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88128LPS45LB | 625 |
| 5962-8959810BXA | N | 08/12/2003 | | (NONE) | | | | 625 |
| 5962-8959810MXA | N | 08/12/2003 | | AUSTIN SEMI. | | Y | MT5C1009CW-45L883C | 625 |
| 5962-8959810MXA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88128LPS45CB | 625 |
| 5962-8959810MYA | N | 08/12/2003 | 1 | AUSTIN SEMI. | | Y | MT5C1009SOJ-45L883 | 625 |
| 5962-8959810MYA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88128LPS45NB | 625 |
| 5962-8959810BZA | N | 08/12/2003 | | (NONE) | | | | 625 |
| 5962-8959810MZA | N | 08/12/2003 | 1 | AUSTIN SEMI. | | Y | MT5C1009C-45L883C | 625 |
| 5962-8959810MZA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88128LPS45TB | 625 |
| 5962-8959811M7A | N | 08/12/2003 | 1 | AUSTIN SEMI. | | Y | MT5C1009DCJ-35L883 | 625 |
| 5962-8959811M8A | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88128LPS35ZB | 625 |
| 5962-8959811M9A | N | 08/12/2003 | | (NONE) | | | | 625 |
| 5962-8959811MMA | N | 08/12/2003 | 1 | AUSTIN SEMI. | | Y | MT5C1009ECA-35L883 | 625 |
| 5962-8959811MNA | N | 08/12/2003 | | (NONE) | | | L7C108-35 (GEN) | 625 |
| 5962-8959811BTA | N | 08/12/2003 | | (NONE) | | | | 625 |
| 5962-8959811MTA | N | 08/12/2003 | 1 | AUSTIN SEMI. | | Y | MT5C1009F-35L883C | 625 |
| 5962-8959811MTA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88128LPS35FB | 625 |
| 5962-8959811BUA | N | 08/12/2003 | | (NONE) | | | | 625 |
| 5962-8959811MUA | N | 08/12/2003 | 1 | AUSTIN SEMI. | | Y | MT5C1009EC-35L883C | 625 |
| 5962-8959811MUA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88128LPS35LB | 625 |
| 5962-8959811BXA | N | 08/12/2003 | | (NONE) | | | | 625 |
| 5962-8959811MXA | N | 08/12/2003 | 1 | AUSTIN SEMI. | | Y | MT5C1009CW-35L883C | 625 |
| 5962-8959811MXA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88128LPS35CB | 625 |
| 5962-8959811MYA | N | 08/12/2003 | 1 | AUSTIN SEMI. | | Y | MT5C1009SOJ-35L883 | 625 |
| 5962-8959811MYA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88128LPS35NB | 625 |
| 5962-8959811BZA | N | 08/12/2003 | | (NONE) | | | | 625 |
| 5962-8959811MZA | N | 08/12/2003 | 1 | AUSTIN SEMI. | | Y | MT5C1009C-35L883C | 625 |
| 5962-8959811MZA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88128LPS35TB | 625 |
| 5962-8959812M7A | N | 08/12/2003 | 1 | AUSTIN SEMI. | | Y | MT5C1009DCJ-25L883 | 625 |
| 5962-8959812M8A | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88128LPS25ZB | 625 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-8959812M9A | N | 08/12/2003 | | (NONE) | | | | 625 |
| 5962-8959812MMA | N | 08/12/2003 | 1 | AUSTIN SEMI. | | Y | MT5C1009ECA-25L883 | 625 |
| 5962-8959812MNA | N | 08/12/2003 | | (NONE) | | | L7C108-25 (GEN) | 625 |
| 5962-8959812BTA | N | 08/12/2003 | | (NONE) | | | | 625 |
| 5962-8959812MTA | N | 08/12/2003 | 1 | AUSTIN SEMI. | | Y | MT5C1009F-25L883C | 625 |
| 5962-8959812MTA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88128LPS25FB | 625 |
| 5962-8959812BUA | N | 08/12/2003 | | (NONE) | | | | 625 |
| 5962-8959812MUA | N | 08/12/2003 | 1 | AUSTIN SEMI. | | Y | MT5C1009EC-25L883C | 625 |
| 5962-8959812MUA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88128LPS25LB | 625 |
| 5962-8959812BXA | N | 08/12/2003 | | (NONE) | | | | 625 |
| 5962-8959812MXA | N | 08/12/2003 | 1 | AUSTIN SEMI. | | Y | MT5C1009CW-25L883C | 625 |
| 5962-8959812MXA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88128LPS25CB | 625 |
| 5962-8959812MYA | N | 08/12/2003 | 1 | AUSTIN SEMI. | | Y | MT5C1009SOJ-25L883 | 625 |
| 5962-8959812MYA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88128LPS25NB | 625 |
| 5962-8959812BZA | N | 08/12/2003 | | (NONE) | | | | 625 |
| 5962-8959812MZA | N | 08/12/2003 | 1 | AUSTIN SEMI. | | Y | MT5C1009C-25L883C | 625 |
| 5962-8959812MZA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88128LPS25TB | 625 |
| 5962-8959813M7A | N | 08/12/2003 | 1 | AUSTIN SEMI. | | Y | MT5C1008DCJ-120L88 | 625 |
| 5962-8959813M9A | N | 08/12/2003 | | (NONE) | | | | 625 |
| 5962-8959813MMA | N | 08/12/2003 | 1 | AUSTIN SEMI. | | Y | MT5C1008ECA-120L88 | 625 |
| 5962-8959813MMA | N | 08/12/2003 | 3 | CYPRESS | | Y | CY7C1009L-120LMB | 625 |
| 5962-8959813MMA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88130LPS120L32B | 625 |
| 5962-8959813MNA | N | 08/12/2003 | | (NONE) | | | L7C109-120 (GEN) | 625 |
| 5962-8959813BTA | N | 08/12/2003 | | (NONE) | | | | 625 |
| 5962-8959813MTA | N | 08/12/2003 | 1 | AUSTIN SEMI. | | Y | MT5C1008F-120L883C | 625 |
| 5962-8959813MTA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88130LPS120FB | 625 |
| 5962-8959813BUA | N | 08/12/2003 | | (NONE) | | | | 625 |
| 5962-8959813MUA | N | 08/12/2003 | 1 | AUSTIN SEMI. | | Y | MT5C1008EC-120L883 | 625 |
| 5962-8959813MUA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88130LPS120LB | 625 |
| 5962-8959813BXA | N | 08/12/2003 | | (NONE) | | | | 625 |
| 5962-8959813MXA | N | 08/12/2003 | 1 | AUSTIN SEMI. | | Y | MT5C1008CW-120L883 | 625 |
| 5962-8959813MXA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88130LPS120CB | 625 |
| 5962-8959813MYA | N | 08/12/2003 | 1 | AUSTIN SEMI. | | Y | MT5C1008SOJ-120L88 | 625 |
| 5962-8959813MYA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88130LPS120NB | 625 |
| 5962-8959813BZA | N | 08/12/2003 | | (NONE) | | | | 625 |
| 5962-8959813MZA | N | 08/12/2003 | 1 | AUSTIN SEMI. | | Y | MT5C1008C-120L883C | 625 |
| 5962-8959813MZA | N | 08/12/2003 | 3 | CYPRESS | | Y | CY7C1009L-120DMB | 625 |
| 5962-8959813MZA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88130LPS120TB | 625 |
| 5962-8959814M7A | N | 08/12/2003 | 1 | AUSTIN SEMI. | | Y | MT5C1008DCJ-100L88 | 625 |
| 5962-8959814M9A | N | 08/12/2003 | | (NONE) | | | | 625 |
| 5962-8959814MMA | N | 08/12/2003 | 1 | AUSTIN SEMI. | | Y | MT5C1008ECA-100L88 | 625 |
| 5962-8959814MMA | N | 08/12/2003 | 3 | CYPRESS | | Y | CY7C1009L-100LMB | 625 |
| 5962-8959814MMA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88130LPS100L32B | 625 |
| 5962-8959814MNA | N | 08/12/2003 | | (NONE) | | | L7C109-100 (GEN) | 625 |
| 5962-8959814BTA | N | 08/12/2003 | | (NONE) | | | | 625 |
| 5962-8959814MTA | N | 08/12/2003 | 2 | AUSTIN SEMI. | | Y | MT5C1008F-100L883C | 625 |
| 5962-8959814MTA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88130LPS100FB | 625 |
| 5962-8959814BUA | N | 08/12/2003 | | (NONE) | | | | 625 |
| 5962-8959814MUA | N | 08/12/2003 | 2 | AUSTIN SEMI. | | Y | MT5C1008EC-100L883 | 625 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-8959814MUA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88130LPS100LB | 625 |
| 5962-8959814BXA | N | 08/12/2003 | | (NONE) | | | | 625 |
| 5962-8959814MXA | N | 08/12/2003 | 2 | AUSTIN SEMI. | | Y | MT5C1008CW-100L883 | 625 |
| 5962-8959814MXA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88130LPS100CB | 625 |
| 5962-8959814MYA | N | 08/12/2003 | 1 | AUSTIN SEMI. | | Y | MT5C1008SOJ-100L88 | 625 |
| 5962-8959814MYA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88130LPS100NB | 625 |
| 5962-8959814BZA | N | 08/12/2003 | | (NONE) | | | | 625 |
| 5962-8959814MZA | N | 08/12/2003 | 2 | AUSTIN SEMI. | | Y | MT5C1008C-100L883C | 625 |
| 5962-8959814MZA | N | 08/12/2003 | 3 | CYPRESS | | Y | CY7C1009L-100DMB | 625 |
| 5962-8959814MZA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88130LPS100TB | 625 |
| 5962-8959815M7A | N | 08/12/2003 | 1 | AUSTIN SEMI. | | Y | MT5C1008DCJ-85L883 | 625 |
| 5962-8959815M9A | N | 08/12/2003 | | (NONE) | | | | 625 |
| 5962-8959815MMA | N | 08/12/2003 | 1 | AUSTIN SEMI. | | Y | MT5C1008ECA-85L883 | 625 |
| 5962-8959815MMA | N | 08/12/2003 | 3 | CYPRESS | | Y | CY7C1009L-85LMB | 625 |
| 5962-8959815MMA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88130LPS85L32B | 625 |
| 5962-8959815MNA | N | 08/12/2003 | | (NONE) | | | L7C109-85 (GEN) | 625 |
| 5962-8959815BTA | N | 08/12/2003 | | (NONE) | | | | 625 |
| 5962-8959815MTA | N | 08/12/2003 | 2 | AUSTIN SEMI. | | Y | MT5C1008F-85L883C | 625 |
| 5962-8959815MTA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88130LPS85FB | 625 |
| 5962-8959815BUA | N | 08/12/2003 | | (NONE) | | | | 625 |
| 5962-8959815MUA | N | 08/12/2003 | 2 | AUSTIN SEMI. | | Y | MT5C1008EC-85L883C | 625 |
| 5962-8959815MUA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88130LPS85LB | 625 |
| 5962-8959815BXA | N | 08/12/2003 | | (NONE) | | | | 625 |
| 5962-8959815MXA | N | 08/12/2003 | 2 | AUSTIN SEMI. | | Y | MT5C1008CW-85L883C | 625 |
| 5962-8959815MXA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88130LPS85CB | 625 |
| 5962-8959815MYA | N | 08/12/2003 | 1 | AUSTIN SEMI. | | Y | MT5C1008SOJ-85L883 | 625 |
| 5962-8959815MYA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88130LPS85NB | 625 |
| 5962-8959815BZA | N | 08/12/2003 | | (NONE) | | | | 625 |
| 5962-8959815MZA | N | 08/12/2003 | 2 | AUSTIN SEMI. | | Y | MT5C1008C-85L883C | 625 |
| 5962-8959815MZA | N | 08/12/2003 | 3 | CYPRESS | | Y | CY7C1009L-85DMB | 625 |
| 5962-8959815MZA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88130LPS85TB | 625 |
| 5962-8959816M7A | N | 08/12/2003 | 1 | AUSTIN SEMI. | | Y | MT5C1008DCJ-70L883 | 625 |
| 5962-8959816M9A | N | 08/12/2003 | | (NONE) | | | | 625 |
| 5962-8959816MMA | N | 08/12/2003 | 1 | AUSTIN SEMI. | | Y | MT5C1008ECA-70L883 | 625 |
| 5962-8959816MMA | N | 08/12/2003 | 3 | CYPRESS | | Y | CY7C1009L-70LMB | 625 |
| 5962-8959816MMA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88130LPS70L32B | 625 |
| 5962-8959816MNA | N | 08/12/2003 | | (NONE) | | | L7C109-70 (GEN) | 625 |
| 5962-8959816BTA | N | 08/12/2003 | | (NONE) | | | | 625 |
| 5962-8959816MTA | N | 08/12/2003 | 2 | AUSTIN SEMI. | | Y | MT5C1008F-70L883C | 625 |
| 5962-8959816MTA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88130LPS70FB | 625 |
| 5962-8959816BUA | N | 08/12/2003 | | (NONE) | | | | 625 |
| 5962-8959816MUA | N | 08/12/2003 | 2 | AUSTIN SEMI. | | Y | MT5C1008EC-70L883C | 625 |
| 5962-8959816MUA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88130LPS70LB | 625 |
| 5962-8959816BXA | N | 08/12/2003 | | (NONE) | | | | 625 |
| 5962-8959816MXA | N | 08/12/2003 | 2 | AUSTIN SEMI. | | Y | MT5C1008CW-70L883C | 625 |
| 5962-8959816MXA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88130LPS70CB | 625 |
| 5962-8959816MYA | N | 08/12/2003 | 1 | AUSTIN SEMI. | | Y | MT5C1008SOJ-70L883 | 625 |
| 5962-8959816MYA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88130LPS70NB | 625 |
| 5962-8959816BZA | N | 08/12/2003 | | (NONE) | | | | 625 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-8959816MZA | N | 08/12/2003 | 2 | AUSTIN SEMI. | | Y | MT5C1008C-70L883C | 625 |
| 5962-8959816MZA | N | 08/12/2003 | 3 | CYPRESS | | Y | CY7C1009L-70DMB | 625 |
| 5962-8959816MZA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88130LPS70TB | 625 |
| 5962-8959817M7A | N | 08/12/2003 | 1 | AUSTIN SEMI. | | Y | MT5C1008DCJ-55L883 | 625 |
| 5962-8959817M9A | N | 08/12/2003 | | (NONE) | | | | 625 |
| 5962-8959817MMA | N | 08/12/2003 | 1 | AUSTIN SEMI. | | Y | MT5C1008ECA-55L883 | 625 |
| 5962-8959817MMA | N | 08/12/2003 | 3 | CYPRESS | | Y | CY7C1009L-55LMB | 625 |
| 5962-8959817MMA | N | 08/12/2003 | 2 | QP SEMI | | Y | QP7C1009BL-55LMB | 625 |
| 5962-8959817MMA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88130LPS55L32B | 625 |
| 5962-8959817MNA | N | 08/12/2003 | | (NONE) | | | L7C109-55 (GEN) | 625 |
| 5962-8959817BTA | N | 08/12/2003 | | (NONE) | | | | 625 |
| 5962-8959817MTA | N | 08/12/2003 | 2 | AUSTIN SEMI. | | Y | MT5C1008F-55L883C | 625 |
| 5962-8959817MTA | N | 08/12/2003 | 2 | QP SEMI | | Y | QP7C1009BL-55FMB | 625 |
| 5962-8959817MTA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88130LPS55FB | 625 |
| 5962-8959817BUA | N | 08/12/2003 | | (NONE) | | | | 625 |
| 5962-8959817MUA | N | 08/12/2003 | 2 | AUSTIN SEMI. | | Y | MT5C1008EC-55L883C | 625 |
| 5962-8959817MUA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88130LPS55LB | 625 |
| 5962-8959817BXA | N | 08/12/2003 | | (NONE) | | | | 625 |
| 5962-8959817MXA | N | 08/12/2003 | 2 | AUSTIN SEMI. | | Y | MT5C1008CW-55L883C | 625 |
| 5962-8959817MXA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88130LPS55CB | 625 |
| 5962-8959817MYA | N | 08/12/2003 | 1 | AUSTIN SEMI. | | Y | MT5C1008SOJ-55L883 | 625 |
| 5962-8959817MYA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88130LPS55NB | 625 |
| 5962-8959817BZA | N | 08/12/2003 | | (NONE) | | | | 625 |
| 5962-8959817MZA | N | 08/12/2003 | 2 | AUSTIN SEMI. | | Y | MT5C1008C-55L883C | 625 |
| 5962-8959817MZA | N | 08/12/2003 | 3 | CYPRESS | | Y | CY7C1009L-55DMB | 625 |
| 5962-8959817MZA | N | 08/12/2003 | 2 | QP SEMI | | Y | QP7C1009BL-55DMB | 625 |
| 5962-8959817MZA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88130LPS55TB | 625 |
| 5962-8959818M7A | N | 08/12/2003 | 1 | AUSTIN SEMI. | | Y | MT5C1008DCJ-45L883 | 625 |
| 5962-8959818M9A | N | 08/12/2003 | | (NONE) | | | | 625 |
| 5962-8959818MMA | N | 08/12/2003 | 1 | AUSTIN SEMI. | | Y | MT5C1008ECA-45L883 | 625 |
| 5962-8959818MMA | N | 08/12/2003 | 2 | QP SEMI | | Y | QP7C1009BL-45LMB | 625 |
| 5962-8959818MMA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88130LPS45L32B | 625 |
| 5962-8959818MNA | N | 08/12/2003 | | (NONE) | | | L7C109-45 (GEN) | 625 |
| 5962-8959818BTA | N | 08/12/2003 | | (NONE) | | | | 625 |
| 5962-8959818MTA | N | 08/12/2003 | 2 | AUSTIN SEMI. | | Y | MT5C1008F-45L883C | 625 |
| 5962-8959818MTA | N | 08/12/2003 | 2 | QP SEMI | | Y | QP7C1009BL-45FMB | 625 |
| 5962-8959818MTA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88130LPS45FB | 625 |
| 5962-8959818MTC | N | 08/12/2003 | 2 | ATMEL NANTES | | Y | MMDJ-65608EV-45MQ | 625 |
| 5962-8959818VTC | N | 08/12/2003 | 2 | ATMEL NANTES | | Y | SMDJ-65608EV-45SV | 625 |
| 5962-8959818BUA | N | 08/12/2003 | | (NONE) | | | | 625 |
| 5962-8959818MUA | N | 08/12/2003 | 1 | AUSTIN SEMI. | | Y | MT5C1008EC-45L883C | 625 |
| 5962-8959818MUA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88130LPS45LB | 625 |
| 5962-8959818BXA | N | 08/12/2003 | | (NONE) | | | | 625 |
| 5962-8959818MXA | N | 08/12/2003 | 2 | AUSTIN SEMI. | | Y | MT5C1008CW-45L883C | 625 |
| 5962-8959818MXA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88130LPS45CB | 625 |
| 5962-8959818MYA | N | 08/12/2003 | 1 | AUSTIN SEMI. | | Y | MT5C1008SOJ-45L883 | 625 |
| 5962-8959818MYA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88130LPS45NB | 625 |
| 5962-8959818BZA | N | 08/12/2003 | | (NONE) | | | | 625 |
| 5962-8959818MZA | N | 08/12/2003 | 2 | AUSTIN SEMI. | | Y | MT5C1008C-45L883C | 625 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-8959818MZA | N | 08/12/2003 | 2 | QP SEMI | | Y | QP7C1009BL-45DMB | 625 |
| 5962-8959818MZA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88130LPS45TB | 625 |
| 5962-8959818MZC | N | 08/12/2003 | 2 | ATMEL NANTES | | Y | MMC9-65608EV-45MQ | 625 |
| 5962-8959818VZC | N | 08/12/2003 | 2 | ATMEL NANTES | | Y | SMC9-65608EV-45SV | 625 |
| 5962-8959819M7A | N | 08/12/2003 | 1 | AUSTIN SEMI. | | Y | MT5C1008DCJ-35L883 | 625 |
| 5962-8959819M9A | N | 08/12/2003 | | (NONE) | | | | 625 |
| 5962-8959819MMA | N | 08/12/2003 | 1 | AUSTIN SEMI. | | Y | MT5C1008ECA-35L883 | 625 |
| 5962-8959819MMA | N | 08/12/2003 | 2 | QP SEMI | | Y | QP7C1009BL-35LMB | 625 |
| 5962-8959819MMA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88130LPS35L32B | 625 |
| 5962-8959819MNA | N | 08/12/2003 | | (NONE) | | | L7C109-35 (GEN) | 625 |
| 5962-8959819BTA | N | 08/12/2003 | | (NONE) | | | | 625 |
| 5962-8959819MTA | N | 08/12/2003 | 2 | AUSTIN SEMI. | | Y | MT5C1008F-35L883C | 625 |
| 5962-8959819MTA | N | 08/12/2003 | 2 | QP SEMI | | Y | QP7C1009BL-35FMB | 625 |
| 5962-8959819MTA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88130LPS35FB | 625 |
| 5962-8959819VTC | N | 08/12/2003 | | (NONE) | | | 65608-35 (GEN) | 625 |
| 5962-8959819BUA | N | 08/12/2003 | | (NONE) | | | | 625 |
| 5962-8959819MUA | N | 08/12/2003 | 2 | AUSTIN SEMI. | | Y | MT5C1008EC-35L883C | 625 |
| 5962-8959819MUA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88130LPS35LB | 625 |
| 5962-8959819BXA | N | 08/12/2003 | | (NONE) | | | | 625 |
| 5962-8959819MXA | N | 08/12/2003 | 2 | AUSTIN SEMI. | | Y | MT5C1008CW-35L883C | 625 |
| 5962-8959819MXA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88130LPS35CB | 625 |
| 5962-8959819MYA | N | 08/12/2003 | 1 | AUSTIN SEMI. | | Y | MT5C1008SOJ-35L883 | 625 |
| 5962-8959819MYA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88130LPS35NB | 625 |
| 5962-8959819BZA | N | 08/12/2003 | | (NONE) | | | | 625 |
| 5962-8959819MZA | N | 08/12/2003 | 2 | AUSTIN SEMI. | | Y | MT5C1008C-35L883C | 625 |
| 5962-8959819MZA | N | 08/12/2003 | 2 | QP SEMI | | Y | QP7C1009BL-35DMB | 625 |
| 5962-8959819MZA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88130LPS35TB | 625 |
| 5962-8959819VZC | N | 08/12/2003 | | (NONE) | | | 65608-35 (GEN) | 625 |
| 5962-8959820M7A | N | 08/12/2003 | 1 | AUSTIN SEMI. | | Y | MT5C1008DCJ-25L883 | 625 |
| 5962-8959820M9A | N | 08/12/2003 | | (NONE) | | | | 625 |
| 5962-8959820MMA | N | 08/12/2003 | 1 | AUSTIN SEMI. | | Y | MT5C1008ECA-25L883 | 625 |
| 5962-8959820MMA | N | 08/12/2003 | 2 | QP SEMI | | Y | QP7C1009BL-25LMB | 625 |
| 5962-8959820MMA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88130LPS25L32B | 625 |
| 5962-8959820MNA | N | 08/12/2003 | | (NONE) | | | L7C109-25 (GEN) | 625 |
| 5962-8959820BTA | N | 08/12/2003 | | (NONE) | | | | 625 |
| 5962-8959820MTA | N | 08/12/2003 | 2 | AUSTIN SEMI. | | Y | MT5C1008F-25L883C | 625 |
| 5962-8959820MTA | N | 08/12/2003 | 2 | QP SEMI | | Y | QP7C1009BL-25FMB | 625 |
| 5962-8959820MTA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88130LPS25FB | 625 |
| 5962-8959820BUA | N | 08/12/2003 | | (NONE) | | | | 625 |
| 5962-8959820MUA | N | 08/12/2003 | 2 | AUSTIN SEMI. | | Y | MT5C1008EC-25L883C | 625 |
| 5962-8959820MUA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88130LPS25LB | 625 |
| 5962-8959820BXA | N | 08/12/2003 | | (NONE) | | | | 625 |
| 5962-8959820MXA | N | 08/12/2003 | 2 | AUSTIN SEMI. | | Y | MT5C1008CW-25L883C | 625 |
| 5962-8959820MXA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88130LPS25CB | 625 |
| 5962-8959820MYA | N | 08/12/2003 | 1 | AUSTIN SEMI. | | Y | MT5C1008SOJ-25L883 | 625 |
| 5962-8959820MYA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88130LPS25NB | 625 |
| 5962-8959820BZA | N | 08/12/2003 | | (NONE) | | | | 625 |
| 5962-8959820MZA | N | 08/12/2003 | 2 | AUSTIN SEMI. | | Y | MT5C1008C-25L883C | 625 |
| 5962-8959820MZA | N | 08/12/2003 | 2 | QP SEMI | | Y | QP7C1009BL-25DMB | 625 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-8959820MZA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88130LPS25TB | 625 |
| 5962-8959821M7A | N | 08/12/2003 | 1 | AUSTIN SEMI. | | Y | MT5C1008DCJ-20L883 | 625 |
| 5962-8959821M9A | N | 08/12/2003 | | (NONE) | | | | 625 |
| 5962-8959821MMA | N | 08/12/2003 | 1 | AUSTIN SEMI. | | Y | MT5C1008ECA-20L883 | 625 |
| 5962-8959821MMA | N | 08/12/2003 | 2 | QP SEMI | | Y | QP7C1009BL-20LMB | 625 |
| 5962-8959821MMA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88130LPS20L32B | 625 |
| 5962-8959821MNA | N | 08/12/2003 | | (NONE) | | | L7C109-20 (GEN) | 625 |
| 5962-8959821MTA | N | 08/12/2003 | 2 | AUSTIN SEMI. | | Y | MT5C1008F-20L883C | 625 |
| 5962-8959821MTA | N | 08/12/2003 | 2 | QP SEMI | | Y | QP7C1009BL-20FMB | 625 |
| 5962-8959821MTA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88130LPS20FB | 625 |
| 5962-8959821MUA | N | 08/12/2003 | 2 | AUSTIN SEMI. | | Y | MT5C1008EC-20L883C | 625 |
| 5962-8959821MUA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88130LPS20LB | 625 |
| 5962-8959821MXA | N | 08/12/2003 | 2 | AUSTIN SEMI. | | Y | MT5C1008CW-20L883C | 625 |
| 5962-8959821MXA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88130LPS20CB | 625 |
| 5962-8959821MYA | N | 08/12/2003 | 1 | AUSTIN SEMI. | | Y | MT5C1008SOJ-20L883 | 625 |
| 5962-8959821MYA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88130LPS20NB | 625 |
| 5962-8959821MZA | N | 08/12/2003 | 2 | AUSTIN SEMI. | | Y | MT5C1008C-20L883C | 625 |
| 5962-8959821MZA | N | 08/12/2003 | 2 | QP SEMI | | Y | QP7C1009BL-20DMB | 625 |
| 5962-8959821MZA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88130LPS20TB | 625 |
| 5962-8959822M7A | N | 08/12/2003 | 1 | AUSTIN SEMI. | | Y | MT5C1009DCJ-120883 | 625 |
| 5962-8959822M8A | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88128CS120ZB | 625 |
| 5962-8959822M9A | N | 08/12/2003 | | (NONE) | | | | 625 |
| 5962-8959822MMA | N | 08/12/2003 | 1 | AUSTIN SEMI. | | Y | MT5C1009ECA-120L88 | 625 |
| 5962-8959822MNA | N | 08/12/2003 | | (NONE) | | | | 625 |
| 5962-8959822BTA | N | 08/12/2003 | | (NONE) | | | | 625 |
| 5962-8959822MTA | N | 08/12/2003 | 1 | AUSTIN SEMI. | | Y | MT5C1009F-120883C | 625 |
| 5962-8959822MTA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88128CS120FB | 625 |
| 5962-8959822BUA | N | 08/12/2003 | | (NONE) | | | | 625 |
| 5962-8959822MUA | N | 08/12/2003 | 1 | AUSTIN SEMI. | | Y | MT5C1009EC-120883C | 625 |
| 5962-8959822MUA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88128CS120LB | 625 |
| 5962-8959822BXA | N | 08/12/2003 | | (NONE) | | | | 625 |
| 5962-8959822MXA | N | 08/12/2003 | 1 | AUSTIN SEMI. | | Y | MT5C1009CW-120883C | 625 |
| 5962-8959822MXA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88128CS120CB | 625 |
| 5962-8959822MYA | N | 08/12/2003 | 1 | AUSTIN SEMI. | | Y | MT5C1009SOJ-120883 | 625 |
| 5962-8959822MYA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88128CS120NB | 625 |
| 5962-8959822BZA | N | 08/12/2003 | | (NONE) | | | | 625 |
| 5962-8959822MZA | N | 08/12/2003 | 1 | AUSTIN SEMI. | | Y | MT5C1009C-120883C | 625 |
| 5962-8959822MZA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88128CS120TB | 625 |
| 5962-8959823M7A | N | 08/12/2003 | 1 | AUSTIN SEMI. | | Y | MT5C1009DCJ-100883 | 625 |
| 5962-8959823M8A | N | 08/12/2003 | | WHITE ELEC. | | Y | EDI88128CS100ZB | 625 |
| 5962-8959823M9A | N | 08/12/2003 | | (NONE) | | | | 625 |
| 5962-8959823MMA | N | 08/12/2003 | 1 | AUSTIN SEMI. | | Y | MT5C1009ECA-100L88 | 625 |
| 5962-8959823MNA | N | 08/12/2003 | | (NONE) | | | | 625 |
| 5962-8959823BTA | N | 08/12/2003 | | (NONE) | | | | 625 |
| 5962-8959823MTA | N | 08/12/2003 | 1 | AUSTIN SEMI. | | Y | MT5C1009F-100883C | 625 |
| 5962-8959823MTA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88130CX100FB | 625 |
| 5962-8959823BUA | N | 08/12/2003 | | (NONE) | | | | 625 |
| 5962-8959823MUA | N | 08/12/2003 | 1 | AUSTIN SEMI. | | Y | MT5C1009EC-100883C | 625 |
| 5962-8959823MUA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88128CS100LB | 625 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-8959823BXA | N | 08/12/2003 | | (NONE) | | | | 625 |
| 5962-8959823MXA | N | 08/12/2003 | 1 | AUSTIN SEMI. | | Y | MT5C1009CW-100883C | 625 |
| 5962-8959823MXA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88128CS100CB | 625 |
| 5962-8959823MYA | N | 08/12/2003 | 1 | AUSTIN SEMI. | | Y | MT5C1009SOJ-100883 | 625 |
| 5962-8959823MYA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88128CS100NB | 625 |
| 5962-8959823BZA | N | 08/12/2003 | | (NONE) | | | | 625 |
| 5962-8959823MZA | N | 08/12/2003 | 1 | AUSTIN SEMI. | | Y | MT5C1009C-100883C | 625 |
| 5962-8959823MZA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88128CS100TB | 625 |
| 5962-8959824M7A | N | 08/12/2003 | 1 | AUSTIN SEMI. | | Y | MT5C1009DCJ-85883C | 625 |
| 5962-8959824M8A | N | 08/12/2003 | | WHITE ELEC. | | Y | EDI88128CS85ZB | 625 |
| 5962-8959824M9A | N | 08/12/2003 | | (NONE) | | | | 625 |
| 5962-8959824MMA | N | 08/12/2003 | 1 | AUSTIN SEMI. | | Y | MT5C1009ECA-85L883 | 625 |
| 5962-8959824MNA | N | 08/12/2003 | | (NONE) | | | | 625 |
| 5962-8959824BTA | N | 08/12/2003 | | (NONE) | | | | 625 |
| 5962-8959824MTA | N | 08/12/2003 | 1 | AUSTIN SEMI. | | Y | MT5C1009F-85883C | 625 |
| 5962-8959824MTA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88128CS85FB | 625 |
| 5962-8959824BUA | N | 08/12/2003 | | (NONE) | | | | 625 |
| 5962-8959824MUA | N | 08/12/2003 | 1 | AUSTIN SEMI. | | Y | MT5C1009EC-85883C | 625 |
| 5962-8959824MUA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88128CS85LB | 625 |
| 5962-8959824BXA | N | 08/12/2003 | | (NONE) | | | | 625 |
| 5962-8959824MXA | N | 08/12/2003 | 1 | AUSTIN SEMI. | | Y | MT5C1009CW-85883C | 625 |
| 5962-8959824MXA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88128CS85CB | 625 |
| 5962-8959824MYA | N | 08/12/2003 | 1 | AUSTIN SEMI. | | Y | MT5C1009SOJ-85883C | 625 |
| 5962-8959824MYA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88128CS85NB | 625 |
| 5962-8959824BZA | N | 08/12/2003 | | (NONE) | | | | 625 |
| 5962-8959824MZA | N | 08/12/2003 | 1 | AUSTIN SEMI. | | Y | MT5C1009C-85883C | 625 |
| 5962-8959824MZA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88128CS85TB | 625 |
| 5962-8959825M7A | N | 08/12/2003 | 1 | AUSTIN SEMI. | | Y | MT5C1009DCJ-70883C | 625 |
| 5962-8959825M8A | N | 08/12/2003 | | WHITE ELEC. | | Y | EDI88128CS70ZB | 625 |
| 5962-8959825M9A | N | 08/12/2003 | | (NONE) | | | | 625 |
| 5962-8959825MMA | N | 08/12/2003 | 1 | AUSTIN SEMI. | | Y | MT5C1009ECA-70L883 | 625 |
| 5962-8959825MNA | N | 08/12/2003 | | (NONE) | | | | 625 |
| 5962-8959825BTA | N | 08/12/2003 | | (NONE) | | | | 625 |
| 5962-8959825MTA | N | 08/12/2003 | 1 | AUSTIN SEMI. | | Y | MT5C1009F-70883C | 625 |
| 5962-8959825MTA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88128CS70FB | 625 |
| 5962-8959825BUA | N | 08/12/2003 | | (NONE) | | | | 625 |
| 5962-8959825MUA | N | 08/12/2003 | 1 | AUSTIN SEMI. | | Y | MT5C1009EC-70883C | 625 |
| 5962-8959825MUA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88128CS70LB | 625 |
| 5962-8959825BXA | N | 08/12/2003 | | (NONE) | | | | 625 |
| 5962-8959825MXA | N | 08/12/2003 | 1 | AUSTIN SEMI. | | Y | MT5C1009CW-70883C | 625 |
| 5962-8959825MXA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88128CS70CB | 625 |
| 5962-8959825MYA | N | 08/12/2003 | 1 | AUSTIN SEMI. | | Y | MT5C1009SOJ-70883C | 625 |
| 5962-8959825MYA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88128CS70NB | 625 |
| 5962-8959825BZA | N | 08/12/2003 | | (NONE) | | | | 625 |
| 5962-8959825MZA | N | 08/12/2003 | 1 | AUSTIN SEMI. | | Y | MT5C1009C-70883C | 625 |
| 5962-8959825MZA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88128CS70TB | 625 |
| 5962-8959826M7A | N | 08/12/2003 | 1 | AUSTIN SEMI. | | Y | MT5C1009DCJ-55883C | 625 |
| 5962-8959826M8A | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88128CS55ZB | 625 |
| 5962-8959826M9A | N | 08/12/2003 | | (NONE) | | | | 625 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-8959826MMA | N | 08/12/2003 | 1 | AUSTIN SEMI. | | Y | MT5C1009ECA-55L883 | 625 |
| 5962-8959826MNA | N | 08/12/2003 | | (NONE) | | | | 625 |
| 5962-8959826BTA | N | 08/12/2003 | | (NONE) | | | | 625 |
| 5962-8959826MTA | N | 08/12/2003 | 1 | AUSTIN SEMI. | | Y | MT5C1009F-55883C | 625 |
| 5962-8959826MTA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88128CS55FB | 625 |
| 5962-8959826BUA | N | 08/12/2003 | | (NONE) | | | | 625 |
| 5962-8959826MUA | N | 08/12/2003 | 1 | AUSTIN SEMI. | | Y | MT5C1009EC-55883C | 625 |
| 5962-8959826MUA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88128CS55LB | 625 |
| 5962-8959826BXA | N | 08/12/2003 | | (NONE) | | | | 625 |
| 5962-8959826MXA | N | 08/12/2003 | 1 | AUSTIN SEMI. | | Y | MT5C1009CW-55883C | 625 |
| 5962-8959826MXA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88128CS55CB | 625 |
| 5962-8959826MYA | N | 08/12/2003 | 1 | AUSTIN SEMI. | | Y | MT5C1009SOJ-55883C | 625 |
| 5962-8959826MYA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88128CS55NB | 625 |
| 5962-8959826BZA | N | 08/12/2003 | | (NONE) | | | | 625 |
| 5962-8959826MZA | N | 08/12/2003 | 1 | AUSTIN SEMI. | | Y | MT5C1009C-55883C | 625 |
| 5962-8959826MZA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88128CS55TB | 625 |
| 5962-8959827M7A | N | 08/12/2003 | 1 | AUSTIN SEMI. | | Y | MT5C1009DCJ-45883C | 625 |
| 5962-8959827M8A | N | 08/12/2003 | | WHITE ELEC. | | Y | EDI88128CS45ZB | 625 |
| 5962-8959827M9A | N | 08/12/2003 | | (NONE) | | | | 625 |
| 5962-8959827MMA | N | 08/12/2003 | 1 | AUSTIN SEMI. | | Y | MT5C1009ECA-45L883 | 625 |
| 5962-8959827MNA | N | 08/12/2003 | | (NONE) | | | L7C108-45 (GEN) | 625 |
| 5962-8959827BTA | N | 08/12/2003 | | (NONE) | | | | 625 |
| 5962-8959827MTA | N | 08/12/2003 | 1 | AUSTIN SEMI. | | Y | MT5C1009F-45883C | 625 |
| 5962-8959827MTA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88128CS45FB | 625 |
| 5962-8959827BUA | N | 08/12/2003 | | (NONE) | | | | 625 |
| 5962-8959827MUA | N | 08/12/2003 | 1 | AUSTIN SEMI. | | Y | MT5C1009EC-45883C | 625 |
| 5962-8959827MUA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88128CS45LB | 625 |
| 5962-8959827BXA | N | 08/12/2003 | | (NONE) | | | | 625 |
| 5962-8959827MXA | N | 08/12/2003 | 1 | AUSTIN SEMI. | | Y | MT5C1009CW-45883C | 625 |
| 5962-8959827MXA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88128CS45CB | 625 |
| 5962-8959827MYA | N | 08/12/2003 | 1 | AUSTIN SEMI. | | Y | MT5C1009SOJ-45883C | 625 |
| 5962-8959827MYA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88128CS45NB | 625 |
| 5962-8959827BZA | N | 08/12/2003 | | (NONE) | | | | 625 |
| 5962-8959827MZA | N | 08/12/2003 | 1 | AUSTIN SEMI. | | Y | MT5C1009C-45883C | 625 |
| 5962-8959827MZA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88128CS45TB | 625 |
| 5962-8959828M7A | N | 08/12/2003 | 1 | AUSTIN SEMI. | | Y | MT5C1009DCJ-35883C | 625 |
| 5962-8959828M8A | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88128CS35ZB | 625 |
| 5962-8959828M9A | N | 08/12/2003 | | (NONE) | | | | 625 |
| 5962-8959828MMA | N | 08/12/2003 | 1 | AUSTIN SEMI. | | Y | MT5C1009ECA-35L883 | 625 |
| 5962-8959828MNA | N | 08/12/2003 | | (NONE) | | | L7C108-35 (GEN) | 625 |
| 5962-8959828BTA | N | 08/12/2003 | | (NONE) | | | | 625 |
| 5962-8959828MTA | N | 08/12/2003 | 1 | AUSTIN SEMI. | | Y | MT5C1009F-35883C | 625 |
| 5962-8959828MTA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88128CS35FB | 625 |
| 5962-8959828BUA | N | 08/12/2003 | | (NONE) | | | | 625 |
| 5962-8959828MUA | N | 08/12/2003 | 1 | AUSTIN SEMI. | | Y | MT5C1009EC-35883C | 625 |
| 5962-8959828MUA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88128CS35LB | 625 |
| 5962-8959828BXA | N | 08/12/2003 | | (NONE) | | | | 625 |
| 5962-8959828MXA | N | 08/12/2003 | 1 | AUSTIN SEMI. | | Y | MT5C1009CW-35883C | 625 |
| 5962-8959828MXA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88128CS35CB | 625 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-8959828MYA | N | 08/12/2003 | 1 | AUSTIN SEMI. | | Y | MT5C1009SOJ-35883C | 625 |
| 5962-8959828MYA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88128CS35NB | 625 |
| 5962-8959828BZA | N | 08/12/2003 | | (NONE) | | | | 625 |
| 5962-8959828MZA | N | 08/12/2003 | 1 | AUSTIN SEMI. | | Y | MT5C1009C-35883C | 625 |
| 5962-8959828MZA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88128CS35TB | 625 |
| 5962-8959829M7A | N | 08/12/2003 | 1 | AUSTIN SEMI. | | Y | MT5C1009DCJ-25883C | 625 |
| 5962-8959829M8A | N | 08/12/2003 | | WHITE ELEC. | | Y | EDI88128CS25ZB | 625 |
| 5962-8959829M9A | N | 08/12/2003 | | (NONE) | | | | 625 |
| 5962-8959829MMA | N | 08/12/2003 | 1 | AUSTIN SEMI. | | Y | MT5C1009ECA-25L883 | 625 |
| 5962-8959829MNA | N | 08/12/2003 | | (NONE) | | | L7C108-25 (GEN) | 625 |
| 5962-8959829BTA | N | 08/12/2003 | | (NONE) | | | | 625 |
| 5962-8959829MTA | N | 08/12/2003 | 1 | AUSTIN SEMI. | | Y | MT5C1009F-25883C | 625 |
| 5962-8959829MTA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88128CS25FB | 625 |
| 5962-8959829BUA | N | 08/12/2003 | | (NONE) | | | | 625 |
| 5962-8959829MUA | N | 08/12/2003 | 1 | AUSTIN SEMI. | | Y | MT5C1009EC-25883C | 625 |
| 5962-8959829MUA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88128CS25LB | 625 |
| 5962-8959829BXA | N | 08/12/2003 | | (NONE) | | | | 625 |
| 5962-8959829MXA | N | 08/12/2003 | 1 | AUSTIN SEMI. | | Y | MT5C1009CW-25883C | 625 |
| 5962-8959829MXA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88128CS25CB | 625 |
| 5962-8959829MYA | N | 08/12/2003 | 1 | AUSTIN SEMI. | | Y | MT5C1009SOJ-25883C | 625 |
| 5962-8959829MYA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88128CS25NB | 625 |
| 5962-8959829BZA | N | 08/12/2003 | | (NONE) | | | | 625 |
| 5962-8959829MZA | N | 08/12/2003 | 1 | AUSTIN SEMI. | | Y | MT5C1009C-25883C | 625 |
| 5962-8959829MZA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88128CS25TB | 625 |
| 5962-8959830M7A | N | 08/12/2003 | 1 | AUSTIN SEMI. | | Y | MT5C1008DCJ-120883 | 625 |
| 5962-8959830M9A | N | 08/12/2003 | | (NONE) | | | | 625 |
| 5962-8959830MMA | N | 08/12/2003 | 1 | AUSTIN SEMI. | | Y | MT5C1008ECA-120L88 | 625 |
| 5962-8959830MMA | N | 08/12/2003 | 3 | CYPRESS | | Y | CY7C1009-120LMB | 625 |
| 5962-8959830MMA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88130CS120L32B | 625 |
| 5962-8959830MNA | N | 08/12/2003 | | (NONE) | | | | 625 |
| 5962-8959830BTA | N | 08/12/2003 | | (NONE) | | | | 625 |
| 5962-8959830MTA | N | 08/12/2003 | 2 | AUSTIN SEMI. | | Y | MT5C1008F-120883C | 625 |
| 5962-8959830MTA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88130CS120FB | 625 |
| 5962-8959830BUA | N | 08/12/2003 | | (NONE) | | | | 625 |
| 5962-8959830MUA | N | 08/12/2003 | 2 | AUSTIN SEMI. | | Y | MT5C1008EC-120883C | 625 |
| 5962-8959830MUA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88130CS120LB | 625 |
| 5962-8959830BXA | N | 08/12/2003 | | (NONE) | | | | 625 |
| 5962-8959830MXA | N | 08/12/2003 | 2 | AUSTIN SEMI. | | Y | MT5C1008CW-120883C | 625 |
| 5962-8959830MXA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88130CS120CB | 625 |
| 5962-8959830MYA | N | 08/12/2003 | 1 | AUSTIN SEMI. | | Y | MT5C1008SOJ-120883 | 625 |
| 5962-8959830MYA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88130CS120NB | 625 |
| 5962-8959830BZA | N | 08/12/2003 | | (NONE) | | | | 625 |
| 5962-8959830MZA | N | 08/12/2003 | 2 | AUSTIN SEMI. | | Y | MT5C1008C-120883C | 625 |
| 5962-8959830MZA | N | 08/12/2003 | 3 | CYPRESS | | Y | CY7C1009-120DMB | 625 |
| 5962-8959830MZA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88130CS120TB | 625 |
| 5962-8959831M7A | N | 08/12/2003 | 1 | AUSTIN SEMI. | | Y | MT5C1008DCJ-100883 | 625 |
| 5962-8959831M9A | N | 08/12/2003 | | (NONE) | | | | 625 |
| 5962-8959831MMA | N | 08/12/2003 | 1 | AUSTIN SEMI. | | Y | MT5C1008ECA-100L88 | 625 |
| 5962-8959831MMA | N | 08/12/2003 | 3 | CYPRESS | | Y | CY7C1009-100LMB | 625 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-8959831MMA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88130CS100L32B | 625 |
| 5962-8959831MNA | N | 08/12/2003 | | (NONE) | | | | 625 |
| 5962-8959831BTA | N | 08/12/2003 | | (NONE) | | | | 625 |
| 5962-8959831MTA | N | 08/12/2003 | 2 | AUSTIN SEMI. | | Y | MT5C1008F-100883C | 625 |
| 5962-8959831MTA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88130CS100FB | 625 |
| 5962-8959831BUA | N | 08/12/2003 | | (NONE) | | | | 625 |
| 5962-8959831MUA | N | 08/12/2003 | 2 | AUSTIN SEMI. | | Y | MT5C1008EC-100883C | 625 |
| 5962-8959831MUA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88130CS100LB | 625 |
| 5962-8959831BXA | N | 08/12/2003 | | (NONE) | | | | 625 |
| 5962-8959831MXA | N | 08/12/2003 | 2 | AUSTIN SEMI. | | Y | MT5C1008CW-100883C | 625 |
| 5962-8959831MXA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88128CS100CB | 625 |
| 5962-8959831MYA | N | 08/12/2003 | 1 | AUSTIN SEMI. | | Y | MT5C1008SOJ-100883 | 625 |
| 5962-8959831MYA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88130CS100NB | 625 |
| 5962-8959831BZA | N | 08/12/2003 | | (NONE) | | | | 625 |
| 5962-8959831MZA | N | 08/12/2003 | 2 | AUSTIN SEMI. | | Y | MT5C1008C-100883C | 625 |
| 5962-8959831MZA | N | 08/12/2003 | 3 | CYPRESS | | Y | CY7C1009-100DMB | 625 |
| 5962-8959831MZA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88130CS100TB | 625 |
| 5962-8959832M7A | N | 08/12/2003 | 1 | AUSTIN SEMI. | | Y | MT5C1008DCJ-85883C | 625 |
| 5962-8959832M9A | N | 08/12/2003 | | (NONE) | | | | 625 |
| 5962-8959832MMA | N | 08/12/2003 | 1 | AUSTIN SEMI. | | Y | MT5C1008ECA-85L883 | 625 |
| 5962-8959832MMA | N | 08/12/2003 | 3 | CYPRESS | | Y | CY7C1009-85LMB | 625 |
| 5962-8959832MMA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88130CS85L32B | 625 |
| 5962-8959832MNA | N | 08/12/2003 | | (NONE) | | | | 625 |
| 5962-8959832BTA | N | 08/12/2003 | | (NONE) | | | | 625 |
| 5962-8959832MTA | N | 08/12/2003 | 2 | AUSTIN SEMI. | | Y | MT5C1008F-85883C | 625 |
| 5962-8959832MTA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88130CS85FB | 625 |
| 5962-8959832BUA | N | 08/12/2003 | | (NONE) | | | | 625 |
| 5962-8959832MUA | N | 08/12/2003 | 2 | AUSTIN SEMI. | | Y | MT5C1008EC-85883C | 625 |
| 5962-8959832MUA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88130CS85LB | 625 |
| 5962-8959832BXA | N | 08/12/2003 | | (NONE) | | | | 625 |
| 5962-8959832MXA | N | 08/12/2003 | 2 | AUSTIN SEMI. | | Y | MT5C1008CW-85883C | 625 |
| 5962-8959832MXA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88130CS85CB | 625 |
| 5962-8959832MYA | N | 08/12/2003 | 1 | AUSTIN SEMI. | | Y | MT5C1008SOJ-85883C | 625 |
| 5962-8959832MYA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88130CS85NB | 625 |
| 5962-8959832BZA | N | 08/12/2003 | | (NONE) | | | | 625 |
| 5962-8959832MZA | N | 08/12/2003 | 2 | AUSTIN SEMI. | | Y | MT5C1008C-85883C | 625 |
| 5962-8959832MZA | N | 08/12/2003 | 3 | CYPRESS | | Y | CY7C1009-85DMB | 625 |
| 5962-8959832MZA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88130CS85TB | 625 |
| 5962-8959833M7A | N | 08/12/2003 | 1 | AUSTIN SEMI. | | Y | MT5C1008DCJ-70883C | 625 |
| 5962-8959833M9A | N | 08/12/2003 | | (NONE) | | | | 625 |
| 5962-8959833MMA | N | 08/12/2003 | 1 | AUSTIN SEMI. | | Y | MT5C1008ECA-70L883 | 625 |
| 5962-8959833MMA | N | 08/12/2003 | 3 | CYPRESS | | Y | CY7C1009-70LMB | 625 |
| 5962-8959833MMA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88130CS70L32B | 625 |
| 5962-8959833MNA | N | 08/12/2003 | | (NONE) | | | | 625 |
| 5962-8959833BTA | N | 08/12/2003 | | (NONE) | | | | 625 |
| 5962-8959833MTA | N | 08/12/2003 | 2 | AUSTIN SEMI. | | Y | MT5C1008F-70883C | 625 |
| 5962-8959833MTA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88130CS70FB | 625 |
| 5962-8959833BUA | N | 08/12/2003 | | (NONE) | | | | 625 |
| 5962-8959833MUA | N | 08/12/2003 | 2 | AUSTIN SEMI. | | Y | MT5C1008EC-70883C | 625 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-8959833MUA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88130CS70LB | 625 |
| 5962-8959833BXA | N | 08/12/2003 | | (NONE) | | | | 625 |
| 5962-8959833MXA | N | 08/12/2003 | 2 | AUSTIN SEMI. | | Y | MT5C1008CW-70883C | 625 |
| 5962-8959833MXA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88130CS70CB | 625 |
| 5962-8959833MYA | N | 08/12/2003 | 1 | AUSTIN SEMI. | | Y | MT5C1008SOJ-70883C | 625 |
| 5962-8959833MYA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88130CS70NB | 625 |
| 5962-8959833BZA | N | 08/12/2003 | | (NONE) | | | | 625 |
| 5962-8959833MZA | N | 08/12/2003 | 2 | AUSTIN SEMI. | | Y | MT5C1008C-70883C | 625 |
| 5962-8959833MZA | N | 08/12/2003 | 3 | CYPRESS | | Y | CY7C1009-70DMB | 625 |
| 5962-8959833MZA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88130CS70TB | 625 |
| 5962-8959834M7A | N | 08/12/2003 | 1 | AUSTIN SEMI. | | Y | MT5C1008DCJ-55883C | 625 |
| 5962-8959834M9A | N | 08/12/2003 | | (NONE) | | | | 625 |
| 5962-8959834MMA | N | 08/12/2003 | 1 | AUSTIN SEMI. | | Y | MT5C1008ECA-55L883 | 625 |
| 5962-8959834MMA | N | 08/12/2003 | 3 | CYPRESS | | Y | CY7C1009-55LMB | 625 |
| 5962-8959834MMA | N | 08/12/2003 | 2 | QP SEMI | | Y | QP7C1009B-55LMB | 625 |
| 5962-8959834MMA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88130CS55L32B | 625 |
| 5962-8959834MNA | N | 08/12/2003 | | (NONE) | | | | 625 |
| 5962-8959834BTA | N | 08/12/2003 | | (NONE) | | | | 625 |
| 5962-8959834MTA | N | 08/12/2003 | 2 | AUSTIN SEMI. | | Y | MT5C1008F-55883C | 625 |
| 5962-8959834MTA | N | 08/12/2003 | 2 | QP SEMI | | Y | QP7C1009B-55FMB | 625 |
| 5962-8959834MTA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88130CS55FB | 625 |
| 5962-8959834BUA | N | 08/12/2003 | | (NONE) | | | | 625 |
| 5962-8959834MUA | N | 08/12/2003 | 2 | AUSTIN SEMI. | | Y | MT5C1008EC-55883C | 625 |
| 5962-8959834MUA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88130CS55LB | 625 |
| 5962-8959834BXA | N | 08/12/2003 | | (NONE) | | | | 625 |
| 5962-8959834MXA | N | 08/12/2003 | 2 | AUSTIN SEMI. | | Y | MT5C1008CW-55883C | 625 |
| 5962-8959834MXA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88130CS55CB | 625 |
| 5962-8959834MYA | N | 08/12/2003 | 1 | AUSTIN SEMI. | | Y | MT5C1008SOJ-55883C | 625 |
| 5962-8959834MYA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88130CS55NB | 625 |
| 5962-8959834BZA | N | 08/12/2003 | | (NONE) | | | | 625 |
| 5962-8959834MZA | N | 08/12/2003 | 2 | AUSTIN SEMI. | | Y | MT5C1008C-55883C | 625 |
| 5962-8959834MZA | N | 08/12/2003 | 3 | CYPRESS | | Y | CY7C1009-55DMB | 625 |
| 5962-8959834MZA | N | 08/12/2003 | 2 | QP SEMI | | Y | QP7C1009B-55DMB | 625 |
| 5962-8959834MZA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88130CS55TB | 625 |
| 5962-8959835M7A | N | 08/12/2003 | 1 | AUSTIN SEMI. | | Y | MT5C1008DCJ-45883C | 625 |
| 5962-8959835M9A | N | 08/12/2003 | | (NONE) | | | | 625 |
| 5962-8959835MMA | N | 08/12/2003 | 1 | AUSTIN SEMI. | | Y | MT5C1008ECA-45L883 | 625 |
| 5962-8959835MMA | N | 08/12/2003 | 3 | CYPRESS | | Y | CY7C1009-45LMB | 625 |
| 5962-8959835MMA | N | 08/12/2003 | 2 | QP SEMI | | Y | QP7C1009B-45LMB | 625 |
| 5962-8959835MMA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88130CS45L32B | 625 |
| 5962-8959835MNA | N | 08/12/2003 | | (NONE) | | | L7C109-45 (GEN) | 625 |
| 5962-8959835BTA | N | 08/12/2003 | | (NONE) | | | | 625 |
| 5962-8959835MTA | N | 08/12/2003 | 2 | AUSTIN SEMI. | | Y | MT5C1008F-45883C | 625 |
| 5962-8959835MTA | N | 08/12/2003 | 2 | QP SEMI | | Y | QP7C1009B-45FMB | 625 |
| 5962-8959835MTA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88130CS45FB | 625 |
| 5962-8959835VTC | N | 08/12/2003 | | (NONE) | | | 65608-45 (GEN) | 625 |
| 5962-8959835BUA | N | 08/12/2003 | | (NONE) | | | | 625 |
| 5962-8959835MUA | N | 08/12/2003 | 2 | AUSTIN SEMI. | | Y | MT5C1008EC-45883C | 625 |
| 5962-8959835MUA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88130CS45LB | 625 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-8959835BXA | N | 08/12/2003 | | (NONE) | | | | 625 |
| 5962-8959835MXA | N | 08/12/2003 | 2 | AUSTIN SEMI. | | Y | MT5C1008CW-45883C | 625 |
| 5962-8959835MXA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88130CS45CB | 625 |
| 5962-8959835MYA | N | 08/12/2003 | 1 | AUSTIN SEMI. | | Y | MT5C1008SOJ-45883C | 625 |
| 5962-8959835MYA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88130CS45NB | 625 |
| 5962-8959835BZA | N | 08/12/2003 | | (NONE) | | | | 625 |
| 5962-8959835MZA | N | 08/12/2003 | 2 | AUSTIN SEMI. | | Y | MT5C1008C-45883C | 625 |
| 5962-8959835MZA | N | 08/12/2003 | 2 | QP SEMI | | Y | QP7C1009B-45DMB | 625 |
| 5962-8959835MZA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88130CS45TB | 625 |
| 5962-8959835VZC | N | 08/12/2003 | | (NONE) | | | 65608-45 (GEN) | 625 |
| 5962-8959836M7A | N | 08/12/2003 | 1 | AUSTIN SEMI. | | Y | MT5C1008DCJ-35883C | 625 |
| 5962-8959836M9A | N | 08/12/2003 | | (NONE) | | | | 625 |
| 5962-8959836MMA | N | 08/12/2003 | 1 | AUSTIN SEMI. | | Y | MT5C1008ECA-35L883 | 625 |
| 5962-8959836MMA | N | 08/12/2003 | 2 | QP SEMI | | Y | QP7C1009B-35LMB | 625 |
| 5962-8959836MMA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88130CS35L32B | 625 |
| 5962-8959836MNA | N | 08/12/2003 | | (NONE) | | | L7C109-35 (GEN) | 625 |
| 5962-8959836BTA | N | 08/12/2003 | | (NONE) | | | | 625 |
| 5962-8959836MTA | N | 08/12/2003 | 2 | AUSTIN SEMI. | | Y | MT5C1008F-35883C | 625 |
| 5962-8959836MTA | N | 08/12/2003 | 2 | QP SEMI | | Y | QP7C1009B-35FMB | 625 |
| 5962-8959836MTA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88130CS35FB | 625 |
| 5962-8959836VTC | N | 08/12/2003 | | (NONE) | | | 65608-35 (GEN) | 625 |
| 5962-8959836BUA | N | 08/12/2003 | | (NONE) | | | | 625 |
| 5962-8959836MUA | N | 08/12/2003 | 2 | AUSTIN SEMI. | | Y | MT5C1008EC-35883C | 625 |
| 5962-8959836MUA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88130CS35LB | 625 |
| 5962-8959836BXA | N | 08/12/2003 | | (NONE) | | | | 625 |
| 5962-8959836MXA | N | 08/12/2003 | 2 | AUSTIN SEMI. | | Y | MT5C1008CW-35883C | 625 |
| 5962-8959836MXA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88130CS35CB | 625 |
| 5962-8959836MYA | N | 08/12/2003 | 1 | AUSTIN SEMI. | | Y | MT5C1008SOJ-35883C | 625 |
| 5962-8959836MYA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88130CS35NB | 625 |
| 5962-8959836BZA | N | 08/12/2003 | | (NONE) | | | | 625 |
| 5962-8959836MZA | N | 08/12/2003 | 2 | AUSTIN SEMI. | | Y | MT5C1008C-35883C | 625 |
| 5962-8959836MZA | N | 08/12/2003 | 2 | QP SEMI | | Y | QP7C1009B-35DMB | 625 |
| 5962-8959836MZA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88130CS35TB | 625 |
| 5962-8959836VZC | N | 08/12/2003 | | (NONE) | | | 65608-35 (GEN) | 625 |
| 5962-8959837M7A | N | 08/12/2003 | 1 | AUSTIN SEMI. | | Y | MT5C1008DCJ-25883C | 625 |
| 5962-8959837M9A | N | 08/12/2003 | | (NONE) | | | | 625 |
| 5962-8959837MMA | N | 08/12/2003 | 1 | AUSTIN SEMI. | | Y | MT5C1008ECA-25883C | 625 |
| 5962-8959837MMA | N | 08/12/2003 | 2 | QP SEMI | | Y | QP7C1009B-25LMB | 625 |
| 5962-8959837MMA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88130CS25L32B | 625 |
| 5962-8959837MNA | N | 08/12/2003 | | (NONE) | 04/01/2000 | | 7C109-25 (GEN) | 625 |
| 5962-8959837BTA | N | 08/12/2003 | | (NONE) | | | | 625 |
| 5962-8959837MTA | N | 08/12/2003 | 2 | AUSTIN SEMI. | | Y | MT5C1008F-25883C | 625 |
| 5962-8959837MTA | N | 08/12/2003 | 2 | QP SEMI | | Y | QP7C1009B-25FMB | 625 |
| 5962-8959837MTA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88130CS25FB | 625 |
| 5962-8959837BUA | N | 08/12/2003 | | (NONE) | | | | 625 |
| 5962-8959837MUA | N | 08/12/2003 | 2 | AUSTIN SEMI. | | Y | MT5C1008EC-25883C | 625 |
| 5962-8959837MUA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88130CS25LB | 625 |
| 5962-8959837BXA | N | 08/12/2003 | | (NONE) | | | | 625 |
| 5962-8959837MXA | N | 08/12/2003 | 2 | AUSTIN SEMI. | | Y | MT5C1008CW-25883C | 625 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-8959837MXA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88130CS25CB | 625 |
| 5962-8959837MYA | N | 08/12/2003 | 1 | AUSTIN SEMI. | | Y | MT5C1008SOJ-25883C | 625 |
| 5962-8959837MYA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88130CS25NB | 625 |
| 5962-8959837BZA | N | 08/12/2003 | | (NONE) | | | | 625 |
| 5962-8959837MZA | N | 08/12/2003 | 2 | AUSTIN SEMI. | | Y | MT5C1008C-25883C | 625 |
| 5962-8959837MZA | N | 08/12/2003 | 2 | QP SEMI | | Y | QP7C1009B-25DMB | 625 |
| 5962-8959837MZA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88130CS25TB | 625 |
| 5962-8959838M7A | N | 08/12/2003 | 1 | AUSTIN SEMI. | | Y | MT5C1008DCJ-20883C | 625 |
| 5962-8959838M9A | N | 08/12/2003 | | (NONE) | | | | 625 |
| 5962-8959838MMA | N | 08/12/2003 | 1 | AUSTIN SEMI. | | Y | MT5C1008ECA-20L883 | 625 |
| 5962-8959838MMA | N | 08/12/2003 | 2 | QP SEMI | | Y | QP7C1009B-20LMB | 625 |
| 5962-8959838MMA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88130CS20L32B | 625 |
| 5962-8959838MNA | N | 08/12/2003 | | (NONE) | | | L7C109-20 (GEN) | 625 |
| 5962-8959838BTA | N | 08/12/2003 | | (NONE) | | | | 625 |
| 5962-8959838MTA | N | 08/12/2003 | 1 | AUSTIN SEMI. | | Y | MT5C1008F-20883C | 625 |
| 5962-8959838MTA | N | 08/12/2003 | 2 | QP SEMI | | Y | QP7C1009B-20FMB | 625 |
| 5962-8959838MTA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88130CS20FB | 625 |
| 5962-8959838BUA | N | 08/12/2003 | | (NONE) | | | | 625 |
| 5962-8959838MUA | N | 08/12/2003 | 1 | AUSTIN SEMI. | | Y | MT5C1008EC-20883C | 625 |
| 5962-8959838MUA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88130CS20LB | 625 |
| 5962-8959838BXA | N | 08/12/2003 | | (NONE) | | | | 625 |
| 5962-8959838MXA | N | 08/12/2003 | 1 | AUSTIN SEMI. | | Y | MT5C1008CW-20883C | 625 |
| 5962-8959838MXA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88130CS20CB | 625 |
| 5962-8959838MYA | N | 08/12/2003 | 1 | AUSTIN SEMI. | | Y | MT5C1008SOJ-20883C | 625 |
| 5962-8959838MYA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88130CS20NB | 625 |
| 5962-8959838BZA | N | 08/12/2003 | | (NONE) | | | | 625 |
| 5962-8959838MZA | N | 08/12/2003 | 1 | AUSTIN SEMI. | | Y | MT5C1008C-20883C | 625 |
| 5962-8959838MZA | N | 08/12/2003 | 2 | QP SEMI | | Y | QP7C1009B-20DMB | 625 |
| 5962-8959838MZA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88130CS20TB | 625 |
| 5962-8959839M7A | N | 08/12/2003 | 1 | AUSTIN SEMI. | | Y | MT5C1009DCJ-20883C | 625 |
| 5962-8959839M8A | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88128CS20ZB | 625 |
| 5962-8959839MMA | N | 08/12/2003 | 1 | AUSTIN SEMI. | | Y | MT5C1009ECA-20883C | 625 |
| 5962-8959839MNA | N | 08/12/2003 | | (NONE) | | | L7C108-20 (GEN) | 625 |
| 5962-8959839MTA | N | 08/12/2003 | 1 | AUSTIN SEMI. | | Y | MT5C1009F-20883C | 625 |
| 5962-8959839MTA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88128CS20FB | 625 |
| 5962-8959839MUA | N | 08/12/2003 | 1 | AUSTIN SEMI. | | Y | MT5C1009EC-20883C | 625 |
| 5962-8959839MUA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88128CS20LB | 625 |
| 5962-8959839MXA | N | 08/12/2003 | 1 | AUSTIN SEMI. | | Y | MT5C1009CW-20883C | 625 |
| 5962-8959839MXA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88128CS20CB | 625 |
| 5962-8959839MYA | N | 08/12/2003 | 1 | AUSTIN SEMI. | | Y | MT5C1009SOJ-20883C | 625 |
| 5962-8959839MYA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88128CS20NB | 625 |
| 5962-8959839MZA | N | 08/12/2003 | 1 | AUSTIN SEMI. | | Y | MT5C1009C-20883C | 625 |
| 5962-8959839MZA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88128CS20TB | 625 |
| 5962-8959840M7A | N | 08/12/2003 | 1 | AUSTIN SEMI. | | Y | MT5C1009DCJ-20L883 | 625 |
| 5962-8959840M8A | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88128LPS20ZB | 625 |
| 5962-8959840MMA | N | 08/12/2003 | 1 | AUSTIN SEMI. | | Y | MT5C1009ECA-20L883 | 625 |
| 5962-8959840MNA | N | 08/12/2003 | | (NONE) | | | L7C108-20 (GEN) | 625 |
| 5962-8959840MTA | N | 08/12/2003 | 1 | AUSTIN SEMI. | | Y | MT5C1009F-20L883C | 625 |
| 5962-8959840MTA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88128LPS20FB | 625 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-8959840MUA | N | 08/12/2003 | 1 | AUSTIN SEMI. | | Y | MT5C1009EC-20L883C | 625 |
| 5962-8959840MUA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88128LPS20LB | 625 |
| 5962-8959840MXA | N | 08/12/2003 | 1 | AUSTIN SEMI. | | Y | MT5C1009CW-20L883C | 625 |
| 5962-8959840MXA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88128LPS20CB | 625 |
| 5962-8959840MYA | N | 08/12/2003 | 1 | AUSTIN SEMI. | | Y | MT5C1009SOJ-20L883 | 625 |
| 5962-8959840MYA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88128LPS20NB | 625 |
| 5962-8959840MZA | N | 08/12/2003 | 1 | AUSTIN SEMI. | | Y | MT5C1009C-20L883C | 625 |
| 5962-8959840MZA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88128LPS20TB | 625 |
| 5962-8959841MMA | N | 08/12/2003 | 2 | QP SEMI | | Y | QP7C1009B-15LMB | 625 |
| 5962-8959841MMA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88130CS15L32 | 625 |
| 5962-8959841MTA | N | 08/12/2003 | 2 | QP SEMI | | Y | QP7C1009B-15FMB | 625 |
| 5962-8959841MZA | N | 08/12/2003 | 2 | QP SEMI | | Y | QP7C1009B-15DMB | 625 |
| 5962-8959841MZA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88130CS15TB | 625 |
| 5962-8959842MXA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88128LP70CB | 625 |
| 5962-8959842MYA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88128LP70NB | 625 |
| 5962-8959843MXA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88128C70CB | 625 |
| 5962-8959843MYA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88128C70NB | 625 |
| 5962-8959844MZA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88128CS15TB | 625 |
| 5962-8959845MMA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88130CS12L32B | 625 |
| 5962-8959845MZA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88130CS12TB | 625 |
| 5962-8959846MZA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88128CS12TB | 625 |
| 5962-8959847Q6A | N | 08/12/2003 | 2 | ATMEL NANTES | | Y | MM0-65608EV-30MQ | 625 |
| 5962-8959847V6A | N | 08/12/2003 | 2 | ATMEL NANTES | | Y | SM0-65608EV-30SV | 625 |
| 5962-8959847QTC | N | 08/12/2003 | 2 | ATMEL NANTES | | Y | MMDJ-65608EV-30MQ | 625 |
| 5962-8959847VTC | N | 08/12/2003 | 2 | ATMEL NANTES | | Y | SMDJ-65608EV-30SV | 625 |
| 5962-8959847QZC | N | 08/12/2003 | 2 | ATMEL NANTES | | Y | MMC9-65608EV-30MQ | 625 |
| 5962-8959847VZC | N | 08/12/2003 | 2 | ATMEL NANTES | | Y | SMC9-65608EV-30SV | 625 |
| 5962-8959848MTA | N | 08/12/2003 | 1 | WHITE ELEC. | | Y | EDI88128LPS15FB | 625 |
| 5962-89599012A | A | 06/11/2003 | 3 | NATIONAL | | Y | 54ACT251LMQB | 272 |
| 5962-8959901EA | A | 06/11/2003 | 3 | NATIONAL | | Y | 54ACT251DMQB | 272 |
| 5962-8959901FA | A | 06/11/2003 | 3 | NATIONAL | | Y | 54ACT251FMQB | 272 |
| 5962-89601012A | D | 09/24/2002 | | (NONE) | 5962-8960101M2A | | 54ACT574 (GEN) | 159 |
| 5962-8960101B2A | D | 09/24/2002 | 3 | NATIONAL | | Y | JM54ACT574B2A | 159 |
| 5962-8960101M2A | D | 09/24/2002 | 3 | NATIONAL | | Y | 54ACT574LMQB | 159 |
| 5962-8960101S2A | D | 09/24/2002 | | (NONE) | | | 54ACT574 (GEN) | 159 |
| 5962R8960101B2A | D | 09/24/2002 | 3 | NATIONAL | | Y | JM54ACT574B2A-R | 159 |
| 5962R8960101S2A | D | 09/24/2002 | 3 | NATIONAL | | Y | JM54ACT574S2A-R | 159 |
| 5962-8960101BRA | D | 09/24/2002 | | (NONE) | | | 54ACT574 (GEN) | 159 |
| 5962-8960101MRA | D | 09/24/2002 | 3 | NATIONAL | | Y | 54ACT574DMQB | 159 |
| 5962-8960101RA | D | 09/24/2002 | | (NONE) | 5962-8960101MRA | | 54ACT574 (GEN) | 159 |
| 5962-8960101SRA | D | 09/24/2002 | | (NONE) | | | 54ACT574 (GEN) | 159 |
| 5962R8960101BRA | D | 09/24/2002 | 3 | NATIONAL | | Y | JM54ACT574BRA-R | 159 |
| 5962R8960101SRA | D | 09/24/2002 | 3 | NATIONAL | | Y | JM54ACT574SRA-R | 159 |
| 5962-8960101BSA | D | 09/24/2002 | 3 | NATIONAL | | Y | JM54ACT574BSA | 159 |
| 5962-8960101MSA | D | 09/24/2002 | 3 | NATIONAL | | Y | 54ACT574FMQB | 159 |
| 5962-8960101SA | D | 09/24/2002 | | (NONE) | 5962-8960101MSA | | 54ACT574 (GEN) | 159 |
| 5962-8960101SSA | D | 09/24/2002 | | (NONE) | 03/05/2002 | | 54ACT574 (GEN) | 159 |
| 5962R8960101BSA | D | 09/24/2002 | 3 | NATIONAL | | Y | JM54ACT574BSA-R | 159 |
| 5962R8960101SSA | D | 09/24/2002 | 3 | NATIONAL | | Y | JM54ACT574SSA-R | 159 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-8960101QXA | D | 09/24/2002 | 2 | STMICRO | | Y | 54ACT574K02Q | 159 |
| 5962-8960101QXC | D | 09/24/2002 | 2 | STMICRO | | Y | 54ACT574K01Q | 159 |
| 5962-8960101VXA | D | 09/24/2002 | 2 | STMICRO | | Y | 54ACT574K02V | 159 |
| 5962-8960101VXC | D | 09/24/2002 | 2 | STMICRO | | Y | 54ACT574K01V | 159 |
| 5962R8960101SZA | D | 09/24/2002 | 3 | NATIONAL | | Y | JM54ACT574SZA-R | 159 |
| 5962-89602012A | A | 05/11/1992 | 2 | TI | | Y | SNJ54ALS541FK | 529 |
| 5962-8960201RA | A | 05/11/1992 | 2 | TI | | Y | SNJ54ALS541J | 529 |
| 5962-8960201SA | A | 05/11/1992 | 2 | TI | | Y | SNJ54ALS541W | 529 |
| 5962-89603012A | | 07/07/1989 | 0 | TI | | Y | SNJ54HC590AFK | 304 |
| 5962-8960301EA | | 07/07/1989 | 0 | TI | | Y | SNJ54HC590AJ | 304 |
| 5962-8960301FA | | 07/07/1989 | 0 | TI | | Y | SNJ54HC590AW | 304 |
| 5962-8960401CA | C | 04/15/2004 | 1 | ROCHESTER | | | UHD432/883 | 512 |
| 5962-8960401DA | C | 04/15/2004 | 1 | ROCHESTER | | | UHC432/883 | 512 |
| 5962-8960402CA | C | 04/15/2004 | 1 | ROCHESTER | | | UHD432-1/883 | 512 |
| 5962-8960402DA | C | 04/15/2004 | 1 | ROCHESTER | | | UHC432-1/883 | 512 |
| 5962-8960403CA | C | 04/15/2004 | 1 | ROCHESTER | | | UHD532/883 | 512 |
| 5962-8960403DA | C | 04/15/2004 | 1 | ROCHESTER | | | UHC532/883 | 512 |
| 5962-8960901EA | | 11/20/1989 | 1 | TI | | Y | CD54HC4046AF3A | 803 |
| 5962-8961001XA | A | 06/13/1990 | 1 | MINCO | | Y | MTL1009MH | 785 |
| 5962-8961001XC | A | 06/13/1990 | 1 | MINCO | | Y | MTL1009MH | 785 |
| 5962-89611012A | B | 04/18/2001 | 1 | TI | | Y | UC1706L/883BC | 787 |
| 5962-8961101EA | B | 04/18/2001 | 1 | TI | | Y | UC1706J/883B | 787 |
| 5962-8961401MXA | F | 02/05/2003 | 2 | QP SEMI | | | AT27C010-30DMB | 664 |
| 5962-8961401MXA | F | 02/05/2003 | 1 | QP SEMI | | | WS27C010L-30DMB | 664 |
| 5962-8961401XA | F | 02/05/2003 | 2 | QP SEMI | 5962-8961401MXA | | AT27C010-30DMB | 664 |
| 5962-8961401MYA | F | 02/05/2003 | 1 | QP SEMI | | | WS27C010L-30CMB | 664 |
| 5962-8961401MYA | F | 02/05/2003 | 2 | QP SEMI | | | AT27C010-30CMB | 664 |
| 5962-8961401MYC | F | 02/05/2003 | 2 | QP SEMI | | | AT27C010-30CMB | 664 |
| 5962-8961401MYC | F | 02/05/2003 | 1 | QP SEMI | | | WS27C010L-30CMB | 664 |
| 5962-8961401YA | F | 02/05/2003 | 2 | QP SEMI | 5962-8961401MYA | | AT27C010-30LMB | 664 |
| 5962-8961401MZA | F | 02/05/2003 | | (NONE) | | | | 664 |
| 5962-8961402MXA | F | 02/05/2003 | 2 | QP SEMI | | | AT27C010-25DMB | 664 |
| 5962-8961402MXA | F | 02/05/2003 | 1 | QP SEMI | | | WS27C010L-25DMB | 664 |
| 5962-8961402XA | F | 02/05/2003 | 2 | QP SEMI | 5962-8961402MXA | | AT27C010-25DMB | 664 |
| 5962-8961402MYA | F | 02/05/2003 | 1 | QP SEMI | | | WS27C010L-25CMB | 664 |
| 5962-8961402MYA | F | 02/05/2003 | 2 | QP SEMI | | | AT27C010-25CMB | 664 |
| 5962-8961402MYC | F | 02/05/2003 | 2 | QP SEMI | | | AT27C010-25CMB | 664 |
| 5962-8961402MYC | F | 02/05/2003 | 1 | QP SEMI | | | WS27C010L-25CMB | 664 |
| 5962-8961402YA | F | 02/05/2003 | 2 | QP SEMI | 5962-8961402MYA | | AT27C010-25LMB | 664 |
| 5962-8961402MZA | F | 02/05/2003 | | (NONE) | | | | 664 |
| 5962-8961403MXA | F | 02/05/2003 | 2 | QP SEMI | | | AT27C010-20DMB | 664 |
| 5962-8961403MXA | F | 02/05/2003 | 1 | QP SEMI | | | WS27C010L-20DMB | 664 |
| 5962-8961403QXA | F | 02/05/2003 | | (NONE) | | | 27C010A-20 (GEN) | 664 |
| 5962-8961403XA | F | 02/05/2003 | 2 | QP SEMI | 5962-8961403MXA | | AT27C010-20DMB | 664 |
| 5962-8961403MYA | F | 02/05/2003 | 1 | QP SEMI | | | WS27C010L-20CMB | 664 |
| 5962-8961403MYA | F | 02/05/2003 | 2 | QP SEMI | | | AT27C010-20CMB | 664 |
| 5962-8961403MYC | F | 02/05/2003 | 2 | QP SEMI | | | AT27C010-20CMB | 664 |
| 5962-8961403MYC | F | 02/05/2003 | 1 | QP SEMI | | | WS27C010L-20CMB | 664 |
| 5962-8961403QYA | F | 02/05/2003 | | (NONE) | | | 27C010A-20 (GEN) | 664 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-8961403YA | F | 02/05/2003 | 2 | QP SEMI | 5962-8961403MYA | | AT27C010-20LMB | 664 |
| 5962-8961403MZA | F | 02/05/2003 | | (NONE) | | | | 664 |
| 5962-8961404MXA | F | 02/05/2003 | 2 | QP SEMI | | | AT27C010-17DMB | 664 |
| 5962-8961404MXA | F | 02/05/2003 | 1 | QP SEMI | | | WS27C010L-17DMB | 664 |
| 5962-8961404XA | F | 02/05/2003 | 2 | QP SEMI | 5962-8961404MXA | | AT27C010-17DMB | 664 |
| 5962-8961404MYA | F | 02/05/2003 | 1 | QP SEMI | | | WS27C010L-17CMB | 664 |
| 5962-8961404MYA | F | 02/05/2003 | 2 | QP SEMI | | | AT27C010-17CMB | 664 |
| 5962-8961404MYC | F | 02/05/2003 | 2 | QP SEMI | | | AT27C010-17CMB | 664 |
| 5962-8961404MYC | F | 02/05/2003 | 1 | QP SEMI | | | WS27C010L-17CMB | 664 |
| 5962-8961404QYA | F | 02/05/2003 | | (NONE) | | | 27C010A-17 (GEN) | 664 |
| 5962-8961404YA | F | 02/05/2003 | 2 | QP SEMI | 5962-8961404MYA | | AT27C010-17LMB | 664 |
| 5962-8961404MZA | F | 02/05/2003 | | (NONE) | 10/27/1995 | | 27CT010-17 (GEN) | 664 |
| 5962-8961405MXA | F | 02/05/2003 | 2 | QP SEMI | | | AT27C010-15DMB | 664 |
| 5962-8961405MXA | F | 02/05/2003 | 1 | QP SEMI | | | WS27C010L-15DMB | 664 |
| 5962-8961405QXA | F | 02/05/2003 | | (NONE) | | | 27C010A-15 (GEN) | 664 |
| 5962-8961405XA | F | 02/05/2003 | 2 | QP SEMI | 5962-8961405MXA | | AT27C010-15DMB | 664 |
| 5962-8961405MYA | F | 02/05/2003 | 1 | QP SEMI | | | WS27C010L-15CMB | 664 |
| 5962-8961405MYA | F | 02/05/2003 | 2 | QP SEMI | | | AT27C010-15CMB | 664 |
| 5962-8961405MYC | F | 02/05/2003 | 2 | QP SEMI | | | AT27C010-15CMB | 664 |
| 5962-8961405MYC | F | 02/05/2003 | 1 | QP SEMI | | | WS27C010L-15CMB | 664 |
| 5962-8961405QYA | F | 02/05/2003 | | (NONE) | | | 27C010A-15 (GEN) | 664 |
| 5962-8961405YA | F | 02/05/2003 | 2 | QP SEMI | 5962-8961405MYA | | AT27C010-15LMB | 664 |
| 5962-8961406MXA | F | 02/05/2003 | 2 | QP SEMI | | | AT27C010-12DMB | 664 |
| 5962-8961406MXA | F | 02/05/2003 | 1 | QP SEMI | | | WS27C010L-12DMB | 664 |
| 5962-8961406QXA | F | 02/05/2003 | | (NONE) | | | 27C010A-12 (GEN) | 664 |
| 5962-8961406XA | F | 02/05/2003 | 2 | QP SEMI | 5962-8961406MXA | | AT27C010-12DMB | 664 |
| 5962-8961406MYA | F | 02/05/2003 | 1 | QP SEMI | | | WS27C010L-12CMB | 664 |
| 5962-8961406MYA | F | 02/05/2003 | 2 | QP SEMI | | | AT27C010-12CMB | 664 |
| 5962-8961406MYC | F | 02/05/2003 | 2 | QP SEMI | | | AT27C010-12CMB | 664 |
| 5962-8961406MYC | F | 02/05/2003 | 1 | QP SEMI | | | WS27C010L-12CMB | 664 |
| 5962-8961406QYA | F | 02/05/2003 | | (NONE) | | | 27C010A-12 (GEN) | 664 |
| 5962-8961406YA | F | 02/05/2003 | 2 | QP SEMI | 5962-8961406MYA | | AT27C010-12LMB | 664 |
| 5962-8961407MXA | F | 02/05/2003 | 1 | QP SEMI | | | WS57C010F-90DMB | 664 |
| 5962-8961407MYA | F | 02/05/2003 | 1 | QP SEMI | | | WS57C010F-90CMB | 664 |
| 5962-8961407MYC | F | 02/05/2003 | 1 | QP SEMI | | | WS57C010F-90CMB | 664 |
| 5962-8961408MXA | F | 02/05/2003 | 1 | QP SEMI | | | WS57C010F-70DMB | 664 |
| 5962-8961408MYA | F | 02/05/2003 | 1 | QP SEMI | | | WS57C010F-70CMB | 664 |
| 5962-8961408MYC | F | 02/05/2003 | 1 | QP SEMI | | | WS57C010F-70CMB | 664 |
| 5962-8961409MXA | F | 02/05/2003 | 1 | QP SEMI | | | WS57C010F-55DMB | 664 |
| 5962-8961409MYA | F | 02/05/2003 | 1 | QP SEMI | | | WS57C010F-55CMB | 664 |
| 5962-8961409MYC | F | 02/05/2003 | 1 | QP SEMI | | | WS57C010F-55CMB | 664 |
| 5962-8961410MXA | F | 02/05/2003 | 2 | QP SEMI | | | AT27C010L-15DMB | 664 |
| 5962-8961410MYA | F | 02/05/2003 | 2 | QP SEMI | | | AT27C010L-15LMB | 664 |
| 5962-8961411MXA | F | 02/05/2003 | 2 | QP SEMI | | | AT27C010L-12DMB | 664 |
| 5962-8961411MYA | F | 02/05/2003 | 2 | QP SEMI | | | AT27C010L-12LMB | 664 |
| 5962-8961412MXA | F | 02/05/2003 | 2 | QP SEMI | | | AT27C010L-90DMB | 664 |
| 5962-8961412MYA | F | 02/05/2003 | 2 | QP SEMI | | | AT27C010L-90LMB | 664 |
| 5962-8961413MXA | F | 02/05/2003 | 1 | QP SEMI | | | WS57C010F-70DMB | 664 |
| 5962-8961413QXA | F | 02/05/2003 | | (NONE) | 05/30/1999 | | 27H010-70 (GEN) | 664 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-8961413MYA | F | 02/05/2003 | 1 | QP SEMI | | | WS57C010F-70CMB | 664 |
| 5962-8961413MYC | F | 02/05/2003 | 1 | QP SEMI | | | WS57C010F-70CMB | 664 |
| 5962-8961413QYA | F | 02/05/2003 | | (NONE) | 05/30/1999 | | 27H010-70 (GEN) | 664 |
| 5962-8961414MXA | F | 02/05/2003 | 1 | QP SEMI | | | WS57C010F-55DMB | 664 |
| 5962-8961414QXA | F | 02/05/2003 | | (NONE) | 05/30/1999 | | 27H010-55 (GEN) | 664 |
| 5962-8961414MYA | F | 02/05/2003 | 1 | QP SEMI | | | WS57C010F-55CMB | 664 |
| 5962-8961414MYC | F | 02/05/2003 | 1 | QP SEMI | | | WS57C010F-55CMB | 664 |
| 5962-8961414QYA | F | 02/05/2003 | | (NONE) | 05/30/1999 | | 27H010-55 (GEN) | 664 |
| 5962-8961415MXA | F | 02/05/2003 | 1 | QP SEMI | | | WS57C010F-45DMB | 664 |
| 5962-8961415QXA | F | 02/05/2003 | | (NONE) | 05/30/1999 | | 27H010-45 (GEN) | 664 |
| 5962-8961415MYA | F | 02/05/2003 | 1 | QP SEMI | | | WS57C010F-45CMB | 664 |
| 5962-8961415MYC | F | 02/05/2003 | 1 | QP SEMI | | | WS57C010F-45CMB | 664 |
| 5962-8961415QYA | F | 02/05/2003 | | (NONE) | 05/30/1999 | | 27H010-45 (GEN) | 664 |
| 5962-8961416MXA | F | 02/05/2003 | 1 | QP SEMI | | | WS57C010F-35DMB | 664 |
| 5962-8961416QXA | F | 02/05/2003 | | (NONE) | 05/30/1999 | | 27H010-35 (GEN) | 664 |
| 5962-8961416MYA | F | 02/05/2003 | 1 | QP SEMI | | | WS57C010F-35CMB | 664 |
| 5962-8961416MYC | F | 02/05/2003 | 1 | QP SEMI | | | WS57C010F-35CMB | 664 |
| 5962-8961416QYA | F | 02/05/2003 | | (NONE) | 05/30/1999 | | 27H010-35 (GEN) | 664 |
| 5962-8961417QXA | F | 02/05/2003 | 1 | AUSTIN SEMI. | | Y | SMJ27C010A-20JM | 664 |
| 5962-8961417QYA | F | 02/05/2003 | 1 | AUSTIN SEMI. | | Y | AS27C010A-20ECAM | 664 |
| 5962-8961418QYA | F | 02/05/2003 | 1 | AUSTIN SEMI. | | Y | AS27C010A-17ECAM | 664 |
| 5962-8961419QXA | F | 02/05/2003 | 1 | AUSTIN SEMI. | | Y | SMJ27C010A-15JM | 664 |
| 5962-8961419QYA | F | 02/05/2003 | 1 | AUSTIN SEMI. | | Y | AS27C010A-15ECAM | 664 |
| 5962-8961420QXA | F | 02/05/2003 | 1 | AUSTIN SEMI. | | Y | SMJ27C010A-12JM | 664 |
| 5962-8961420QYA | F | 02/05/2003 | 1 | AUSTIN SEMI. | | Y | AS27C010A-12ECAM | 664 |
| 5962-89615012A | E | 04/20/2001 | 1 | NATIONAL | | Y | DS16F95E/883 | 590 |
| 5962-8961501HA | E | 04/20/2001 | 1 | NATIONAL | | Y | DS16F95W/883 | 590 |
| 5962-8961501VHA | E | 04/20/2001 | 1 | NATIONAL | | Y | DS16F95W-QMLV | 590 |
| 5962F8961501QHA | E | 04/20/2001 | 1 | NATIONAL | | Y | DS16F95WFQML | 590 |
| 5962F8961501VHA | E | 04/20/2001 | 1 | NATIONAL | | Y | DS16F95WFQMLV | 590 |
| 5962-8961501PA | E | 04/20/2001 | | NATIONAL | | Y | DS16F95J/883 | 590 |
| 5962-8961501VPA | E | 04/20/2001 | 1 | NATIONAL | | Y | DS16F95J-QMLV | 590 |
| 5962F8961501QPA | E | 04/20/2001 | 1 | NATIONAL | | Y | DS16F95JFQML | 590 |
| 5962F8961501VPA | E | 04/20/2001 | 1 | NATIONAL | | Y | DS16F95JFQMLV | 590 |
| 5962-8961501QXA | E | 04/20/2001 | 1 | NATIONAL | | Y | DS16F95WG/883 | 590 |
| 5962-8961501VXA | E | 04/20/2001 | 1 | NATIONAL | | Y | DS16F95WG-QMLV | 590 |
| 5962F8961501QXA | E | 04/20/2001 | 1 | NATIONAL | | Y | DS16F95WGFQML | 590 |
| 5962F8961501VXA | E | 04/20/2001 | 1 | NATIONAL | | Y | DS16F95WGFQMLV | 590 |
| 5962-8961601VA | C | 09/21/2001 | 0 | ANALOG (5) | | Y | ADC-908AX | 592 |
| 5962-89616022A | C | 09/21/2001 | 1 | ANALOG (5) | | Y | ADC-908RC | 592 |
| 5962-8961602VA | C | 09/21/2001 | 1 | ANALOG (5) | | Y | ADC-908BX | 592 |
| 5962-89616032C | C | 09/21/2001 | 1 | MAXIM INTEG. | | | MX7574TE/883B | 592 |
| 5962-8961603VA | C | 09/21/2001 | 1 | ANALOG (5) | | Y | PM-7574AX | 592 |
| 5962-8961603VA | C | 09/21/2001 | 1 | MAXIM INTEG. | | | MX7574TQ/883B | 592 |
| 5962-89616042A | C | 09/21/2001 | 1 | ANALOG (5) | | Y | PM-7574BRC | 592 |
| 5962-89616042C | C | 09/21/2001 | 1 | MAXIM INTEG. | | | MX7574SE/883B | 592 |
| 5962-8961604VA | C | 09/21/2001 | 1 | ANALOG (5) | | Y | PM-7574BX | 592 |
| 5962-8961604VA | C | 09/21/2001 | 1 | MAXIM INTEG. | | | MX7574SQ/883B | 592 |
| 5962-8961701LA | A | 07/06/2001 | 1 | ANALOG (2) | | Y | AD767SD/883B | 591 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-89620012A | C | 04/21/2000 | 1 | INTERSIL | | Y | HA4-5020/883 | 899 |
| 5962-8962001PA | C | 04/21/2000 | 1 | INTERSIL | 10/03/2004 | Y | HA7-5020/883 | 899 |
| 5962-89621012A | D | 05/22/2003 | | (NONE) | | | LM6161 (GEN) | 701 |
| 5962-8962101HA | D | 05/22/2003 | | (NONE) | | | LM6161 (GEN) | 701 |
| 5962-8962101PA | D | 05/22/2003 | 1 | NATIONAL | 06/02/2004 | Y | LM6161J/883 | 701 |
| 5962-8962101VPA | D | 05/22/2003 | 1 | NATIONAL | | Y | LM6161J-QMLV | 701 |
| 5962-8962101VXA | D | 05/22/2003 | 1 | NATIONAL | | Y | LM6161WG-QMLV | 701 |
| 5962-8962101XA | D | 05/22/2003 | 1 | NATIONAL | 06/02/2004 | Y | LM6161WG/883 | 701 |
| 5962-8962201GA | A | 09/28/1994 | | (NONE) | 03/30/2001 | | LT1022A (GEN) | 703 |
| 5962-8962202GA | A | 09/28/1994 | | (NONE) | 03/30/2001 | | LT1022 (GEN) | 703 |
| 5962-89623012A | | 05/24/1990 | | (NONE) | | | EL2003 (GEN) | 899 |
| 5962-8962301GA | | 05/24/1990 | | (NONE) | | | EL2003 (GEN) | 899 |
| 5962-8962301PA | | 05/24/1990 | | (NONE) | | | EL2003 (GEN) | 899 |
| 5962-8962302PA | | 05/24/1990 | | (NONE) | | | EL2033 (GEN) | 899 |
| 5962-89624012A | D | 05/30/2003 | | (NONE) | | | LM6164 (GEN) | 701 |
| 5962-8962401HA | D | 05/30/2003 | | (NONE) | | | LM6164 (GEN) | 701 |
| 5962-8962401PA | D | 05/30/2003 | 1 | NATIONAL | | Y | LM6164J/883 | 701 |
| 5962-8962401VPA | D | 05/30/2003 | 1 | NATIONAL | | Y | LM6164J-QMLV | 701 |
| 5962-8962401VXA | D | 05/30/2003 | 1 | NATIONAL | | Y | LM6164WG-QMLV | 701 |
| 5962-8962401XA | D | 05/30/2003 | 1 | NATIONAL | | Y | LM6164WG/883 | 701 |
| 5962-89625012A | D | 06/23/2003 | | (NONE) | | | LM6165 (GEN) | 702 |
| 5962-8962501HA | D | 06/23/2003 | | (NONE) | | | LM6165 (GEN) | 702 |
| 5962-8962501PA | D | 06/23/2003 | 1 | NATIONAL | | Y | LM6165J/883 | 702 |
| 5962-8962501VPA | D | 06/23/2003 | 1 | NATIONAL | | Y | LM6165J-QMLV | 702 |
| 5962-8962501VXA | D | 06/23/2003 | 1 | NATIONAL | | Y | LM6165WG-QMLV | 702 |
| 5962-8962501XA | D | 06/23/2003 | 1 | NATIONAL | | Y | LM6165WG/883 | 702 |
| 5962-8962601XA | A | 04/19/2001 | | MICROSEMI | | Y | SG7806AT/883B | 782 |
| 5962-8962601YA | A | 04/19/2001 | | MICROSEMI | | Y | SG7806AK/883B | 782 |
| 5962-8962601ZA | A | 04/19/2001 | | MICROSEMI | | Y | SG7806AR/883B | 782 |
| 5962-89627012A | A | 04/19/2001 | | (NONE) | 03/30/2000 | | HA-5127 (GEN) | 719 |
| 5962-8962701GC | A | 04/19/2001 | | (NONE) | | | HA-5127 (GEN) | 719 |
| 5962-8962701PA | A | 04/19/2001 | | INTERSIL | 10/03/2004 | Y | HA7-5127/883 | 719 |
| 5962-89627022A | A | 04/19/2001 | | (NONE) | 09/29/1995 | | HA5137 (GEN) | 755 |
| 5962-8962702GC | A | 04/19/2001 | | (NONE) | 09/29/1995 | | HA5137 (GEN) | 755 |
| 5962-8962702PA | A | 04/19/2001 | | (NONE) | 09/29/1995 | | HA5137 (GEN) | 755 |
| 5962-89627032A | A | 04/19/2001 | | (NONE) | 06/28/2002 | | HA-5147 (GEN) | 755 |
| 5962-8962703GC | A | 04/19/2001 | | (NONE) | 12/24/2000 | | HA-5147 (GEN) | 755 |
| 5962-8962703PA | A | 04/19/2001 | | (NONE) | 12/24/2000 | | HA-5147 (GEN) | 755 |
| 5962-8962801UA | C | 04/19/2001 | 1 | MICROSEMI | | Y | SG7808AIG/883B | 782 |
| 5962-8962801XA | C | 04/19/2001 | 1 | MICROSEMI | | Y | SG7808AT/883B | 782 |
| 5962-8962801YA | C | 04/19/2001 | 1 | MICROSEMI | | Y | SG7808AK/883B | 782 |
| 5962-8962801ZA | C | 04/19/2001 | 1 | MICROSEMI | | Y | SG7808AR/883B | 782 |
| 5962-89629013A | A | 07/13/2001 | 1 | ANALOG (3) | | Y | AD7569SE/883B | 599 |
| 5962-8962901LA | A | 07/13/2001 | | (NONE) | | | AD7569S (GEN) | 599 |
| 5962-8962902LA | A | 07/13/2001 | 1 | ANALOG (3) | | Y | AD7569TQ/883B | 599 |
| 5962-8963001EA | A | 06/13/2001 | 1 | NATIONAL | | Y | DS78C120J/883 | 573 |
| 5962-89631012A | A | 05/22/1992 | | (NONE) | 09/29/1995 | | HA5111 (GEN) | 721 |
| 5962-8963101GC | A | 05/22/1992 | | (NONE) | 09/29/1995 | | HA5111 (GEN) | 721 |
| 5962-8963101PA | A | 05/22/1992 | | (NONE) | 09/29/1995 | | HA5111 (GEN) | 721 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-89632012A | A | 06/10/1992 | | (NONE) | 09/29/1995 | | HA5112 (GEN) | 710 |
| 5962-8963201GC | A | 06/10/1992 | | (NONE) | 09/29/1995 | | HA5112 (GEN) | 710 |
| 5962-8963201PA | A | 06/10/1992 | | (NONE) | | | HA5112 (GEN) | 710 |
| 5962-8963301XC | B | 08/25/1993 | | (NONE) | | | HA5033 (GEN) | 830 |
| 5962-89634012A | B | 06/21/2001 | 1 | ROCHESTER | | Y | HA4-5114/883 | 713 |
| 5962-8963401CA | B | 06/21/2001 | 1 | ROCHESTER | | Y | HA1-5114/883 | 713 |
| 5962-89635012A | A | 04/09/2001 | 1 | INTERSIL | | Y | HA4-5101/883 | 701 |
| 5962-8963501GA | A | 04/09/2001 | | (NONE) | | | HA5101 (GEN) | 701 |
| 5962-8963501PA | A | 04/09/2001 | 1 | INTERSIL | 10/03/2004 | Y | HA7-5101/883 | 701 |
| 5962-89636012A | C | 04/11/2001 | 3 | INTERSIL | | Y | HA4-5002/883 | 821 |
| 5962-8963601GC | C | 04/11/2001 | 3 | INTERSIL | | Y | HA2-5002/883 | 821 |
| 5962-8963601PA | C | 04/11/2001 | 3 | INTERSIL | | Y | HA7-5002/883 | 821 |
| 5962-8963701CA | B | 06/13/2001 | 1 | ANALOG (2) | | Y | AD637SQ/883B | 594 |
| 5962-89638012A | | 09/05/1989 | | (NONE) | | | TSC170 (GEN) | 899 |
| 5962-8963801EA | | 09/05/1989 | | (NONE) | | | TSC170 (GEN) | 899 |
| 5962-89638022A | | 09/05/1989 | | (NONE) | | | TSC171 (GEN) | 899 |
| 5962-8963802EA | | 09/05/1989 | | (NONE) | | | TSC171 (GEN) | 899 |
| 5962-8963901VA | | 02/07/1991 | | (NONE) | | | LM604 (GEN) | 739 |
| 5962-89640012A | B | 04/09/2001 | | (NONE) | | | AD840 (GEN) | 755 |
| 5962-8964001CA | B | 04/09/2001 | | (NONE) | | | AD840 (GEN) | 755 |
| 5962-89641012A | C | 04/11/2001 | 1 | ANALOG (2) | | Y | AD841SE/883B | 702 |
| 5962-8964101CA | C | 04/11/2001 | 1 | ANALOG (2) | | Y | AD841SQ/883B | 702 |
| 5962-8964101XA | C | 04/11/2001 | | (NONE) | | | AD841 (GEN) | 702 |
| 5962-89642012A | C | 04/11/2001 | 1 | ANALOG (2) | | Y | AD842SE/883B | 755 |
| 5962-8964201CA | C | 04/11/2001 | 1 | ANALOG (2) | | Y | AD842SQ/883B | 755 |
| 5962-8964201XA | C | 04/11/2001 | | ANALOG (2) | | Y | AD842SH/883B | 755 |
| 5962-8964301XC | | 02/27/1992 | | (NONE) | | | HA-2542 (GEN) | 755 |
| 5962-8964401V2A | A | 07/17/2000 | 1 | ANALOG (5) | | Y | AD844SE/QMLV | 755 |
| 5962R8964401V2A | A | 07/17/2000 | 1 | ANALOG (5) | | Y | AD844SE/QMLR | 755 |
| 5962-8964401PA | A | 07/17/2000 | 1 | ANALOG (5) | | Y | AD844SQ/883B | 755 |
| 5962-8964401VPA | A | 07/17/2000 | 1 | ANALOG (5) | | Y | AD844SQ/QMLV | 755 |
| 5962R8964401VPA | A | 07/17/2000 | 1 | ANALOG (5) | | Y | AD844SQ/QMLR | 755 |
| 5962-8964501PA | A | 03/21/2001 | 1 | ANALOG (2) | | Y | AD845SQ/883B | 719 |
| 5962-8964601PA | A | 03/21/2001 | | (NONE) | | | AD846S (GEN) | 701 |
| 5962-8964701PA | A | 05/28/2002 | 1 | ANALOG (2) | | Y | AD847SQ/883 | 702 |
| 5962-89648012A | A | 05/12/2000 | | (NONE) | 03/31/1995 | | HA2540 (GEN) | 755 |
| 5962-8964801CA | A | 05/12/2000 | 1 | INTERSIL | 10/03/2004 | Y | HA1-2540/883 | 755 |
| 5962-89648022A | A | 05/12/2000 | | (NONE) | 09/30/1993 | | EL-2040 (GEN) | 755 |
| 5962-8964802CA | A | 05/12/2000 | | (NONE) | 09/30/1993 | | EL-2040 (GEN) | 755 |
| 5962-89652012A | | 02/23/1990 | | (NONE) | 09/01/1996 | | 54FCT399 (GEN) | 249 |
| 5962-8965201EA | | 02/23/1990 | | (NONE) | 09/01/1996 | | 54FCT399 (GEN) | 249 |
| 5962-8965201FA | | 02/23/1990 | | (NONE) | 09/01/1996 | | 54FCT399 (GEN) | 249 |
| 5962-89652022A | | 02/23/1990 | | (NONE) | 09/01/1996 | | 54FCT399A (GEN) | 249 |
| 5962-8965202EA | | 02/23/1990 | | (NONE) | 09/01/1996 | | 54FCT399A (GEN) | 249 |
| 5962-8965202FA | | 02/23/1990 | | (NONE) | 09/01/1996 | | 54FCT399A (GEN) | 249 |
| 5962-8965301LA | A | 01/11/1991 | | (NONE) | | | BT102 (GEN) | 591 |
| 5962-89654013A | D | 11/14/2001 | | (NONE) | 09/30/2000 | | AD9012S (GEN) | 592 |
| 5962-8965401XA | D | 11/14/2001 | 0 | ANALOG (4) | 05/28/2005 | Y | AD9012SQ/883B | 592 |
| 5962-89654023A | D | 11/14/2001 | | (NONE) | 09/30/2000 | | AD9012T (GEN) | 592 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-8965402XA | D | 11/14/2001 | 0 | ANALOG (4) | 05/28/2005 | Y | AD9012TQ/883B | 592 |
| 5962-8965501LA | B | 06/30/2004 | 1 | ANALOG (3) | | Y | AD7672TQ10/883B | 592 |
| 5962-8965502LA | B | 06/30/2004 | 1 | ANALOG (3) | | Y | AD7672UQ10/883B | 592 |
| 5962-8965503LA | B | 06/30/2004 | | (NONE) | | | AD7672TQ05 (GEN) | 592 |
| 5962-8965504LA | B | 06/30/2004 | | (NONE) | | | AD7672UQ05 (GEN) | 592 |
| 5962-89656012A | A | 03/08/2001 | | (NONE) | | | HA-5141 (GEN) | 701 |
| 5962-8965601GA | A | 03/08/2001 | | (NONE) | | | HA-5141 (GEN) | 701 |
| 5962-8965601PA | A | 03/08/2001 | | (NONE) | | | HA-5141 (GEN) | 701 |
| 5962-89656022A | A | 03/08/2001 | | (NONE) | | | HA-5142 (GEN) | 710 |
| 5962-8965602GC | A | 03/08/2001 | | (NONE) | | | HA-5142 (GEN) | 710 |
| 5962-8965602PA | A | 03/08/2001 | | (NONE) | | | HA-5142 (GEN) | 710 |
| 5962-89656032A | A | 03/08/2001 | | (NONE) | | | HA-5144 (GEN) | 713 |
| 5962-8965603CA | A | 03/08/2001 | 1 | INTERSIL | | Y | HA1-5144/883 | 713 |
| 5962-8965701LA | B | 12/17/2001 | 1 | MAXIM INTEG. | | | MX7547SQ/883B | 591 |
| 5962-89657023A | B | 12/17/2001 | 1 | ANALOG (3) | | Y | AD7547TE/883B | 591 |
| 5962-8965702LA | B | 12/17/2001 | 1 | ANALOG (3) | | Y | AD7547TQ/883B | 591 |
| 5962-8965702LA | B | 12/17/2001 | 1 | MAXIM INTEG. | | | MX7547TQ/883B | 591 |
| 5962-8965703LA | B | 12/17/2001 | 1 | ANALOG (3) | | Y | AD7547UQ/883B | 591 |
| 5962-8965703LA | B | 12/17/2001 | 1 | MAXIM INTEG. | | | MX7547UQ/883B | 591 |
| 5962-89658012A | | 03/05/1990 | 3 | NATIONAL | | Y | 54ACT534LMQB | 159 |
| 5962-8965801RA | | 03/05/1990 | 3 | NATIONAL | | Y | 54ACT534DMQB | 159 |
| 5962-8965801SA | | 03/05/1990 | 3 | NATIONAL | | Y | 54ACT534FMQB | 159 |
| 5962-89658023A | | 03/05/1990 | 1 | ROCHESTER | | | 54ACT11534/B3A | 159 |
| 5962-8965802LA | | 03/05/1990 | 1 | ROCHESTER | | | 54ACT11534/BLA | 159 |
| 5962-8965901XA | | 09/04/1990 | | (NONE) | 11/30/1997 | | EL2004 (GEN) | 899 |
| 5962-8965901XC | | 09/04/1990 | | (NONE) | 11/30/1997 | | EL2004 (GEN) | 899 |
| 5962-8965901YA | | 09/04/1990 | | (NONE) | | | EL2004 (GEN) | 899 |
| 5962-89661013A | | 08/22/1989 | | (NONE) | 05/10/1995 | | 7C409A-15 (GEN) | 670 |
| 5962-8966101XA | | 08/22/1989 | | (NONE) | 05/31/1998 | | 7C409A-15 (GEN) | 670 |
| 5962-8966101YA | | 08/22/1989 | | (NONE) | | | 7C409A-15 (GEN) | 670 |
| 5962-89661023A | | 08/22/1989 | | (NONE) | 05/10/1995 | | 7C409A-25 (GEN) | 670 |
| 5962-8966102XA | | 08/22/1989 | | (NONE) | 05/31/1998 | | 7C409A-25 (GEN) | 670 |
| 5962-8966102YA | | 08/22/1989 | | (NONE) | | | 7C409A-25 (GEN) | 670 |
| 5962-89663012A | | 05/11/1989 | | (NONE) | | | 54AS286 (GEN) | 210 |
| 5962-8966301CA | | 05/11/1989 | | (NONE) | | | 54AS286 (GEN) | 210 |
| 5962-8966301DA | | 05/11/1989 | | (NONE) | | | 54AS286 (GEN) | 210 |
| 5962-89664013A | A | 11/16/2000 | 2 | QP SEMI | | Y | CY7C408A-15LMB | 670 |
| 5962-8966401XA | A | 11/16/2000 | 2 | QP SEMI | | Y | CY7C408A-15DMB | 670 |
| 5962-8966401YA | A | 11/16/2000 | 2 | QP SEMI | | Y | CY7C408A-15KMB | 670 |
| 5962-89664023A | A | 11/16/2000 | 2 | QP SEMI | | Y | CY7C408A-25LMB | 670 |
| 5962-8966402XA | A | 11/16/2000 | 2 | QP SEMI | | Y | CY7C408A-25DMB | 670 |
| 5962-8966402YA | A | 11/16/2000 | 2 | QP SEMI | | Y | CY7C408A-25KMB | 670 |
| 5962-89665013A | | 11/30/1989 | | (NONE) | 04/27/1998 | | 54FCT824A (GEN) | 229 |
| 5962-8966501KA | | 11/30/1989 | | (NONE) | 04/27/1998 | | 54FCT824A (GEN) | 229 |
| 5962-8966501LA | | 11/30/1989 | | (NONE) | 04/27/1998 | | 54FCT824A (GEN) | 229 |
| 5962-89665023A | | 11/30/1989 | | (NONE) | 04/27/1998 | | 54FCT824B (GEN) | 229 |
| 5962-8966502KA | | 11/30/1989 | | (NONE) | 04/27/1998 | | 54FCT824B (GEN) | 229 |
| 5962-8966502LA | | 11/30/1989 | | (NONE) | 04/27/1998 | | 54FCT824B (GEN) | 229 |
| 5962-8966601UA | B | 11/02/2000 | | (NONE) | | | | 670 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-8966601XA | B | 11/02/2000 | | (NONE) | 10/29/2001 | | 7200L120 (GEN) | 670 |
| 5962-8966601YA | B | 11/02/2000 | | (NONE) | | | | 670 |
| 5962-8966601ZA | B | 11/02/2000 | | (NONE) | | | | 670 |
| 5962-8966602UA | B | 11/02/2000 | | (NONE) | | | | 670 |
| 5962-8966602XA | B | 11/02/2000 | | (NONE) | 10/29/2001 | | 7200L80 (GEN) | 670 |
| 5962-8966602YA | B | 11/02/2000 | | (NONE) | | | | 670 |
| 5962-8966602ZA | B | 11/02/2000 | | (NONE) | | | | 670 |
| 5962-8966603UA | B | 11/02/2000 | | (NONE) | | | | 670 |
| 5962-8966603XA | B | 11/02/2000 | | (NONE) | 10/29/2001 | | 7200L65 (GEN) | 670 |
| 5962-8966603YA | B | 11/02/2000 | | (NONE) | | | | 670 |
| 5962-8966603ZA | B | 11/02/2000 | | (NONE) | | | | 670 |
| 5962-8966604UA | B | 11/02/2000 | | (NONE) | | | | 670 |
| 5962-8966604XA | B | 11/02/2000 | | (NONE) | 10/29/2001 | | 7200L50 (GEN) | 670 |
| 5962-8966604YA | B | 11/02/2000 | | (NONE) | | | | 670 |
| 5962-8966604ZA | B | 11/02/2000 | | (NONE) | | | | 670 |
| 5962-8966605UA | B | 11/02/2000 | | (NONE) | | | | 670 |
| 5962-8966605XA | B | 11/02/2000 | | (NONE) | 10/29/2001 | | 7200L40 (GEN) | 670 |
| 5962-8966605YA | B | 11/02/2000 | | (NONE) | | | | 670 |
| 5962-8966605ZA | B | 11/02/2000 | | (NONE) | | | | 670 |
| 5962-8966606UA | B | 11/02/2000 | | (NONE) | | | | 670 |
| 5962-8966606XA | B | 11/02/2000 | 1 | IDT | | Y | IDT7200L30TDB | 670 |
| 5962-8966606YA | B | 11/02/2000 | | (NONE) | | | | 670 |
| 5962-8966606ZA | B | 11/02/2000 | | (NONE) | | | | 670 |
| 5962-8966701PA | A | 01/31/1994 | | (NONE) | 01/07/2000 | | 24C16 (GEN) | 658 |
| 5962-89668013A | A | 06/02/1997 | 1 | TI | | | SNJ54AS867FK | 304 |
| 5962-8966801KA | A | 06/02/1997 | 1 | TI | | | SNJ54AS867W | 304 |
| 5962-8966801LA | A | 06/02/1997 | 1 | TI | | | SNJ54AS867JT | 304 |
| 5962-89669012A | A | 11/07/2001 | 1 | ANALOG (5) | | Y | SW06BRC/883 | 183 |
| 5962-8966901EA | A | 11/07/2001 | 1 | ANALOG (5) | | Y | SW06BQ/883 | 183 |
| 5962-89670013A | A | 03/12/2001 | | (NONE) | 04/16/2002 | | OP490A (GEN) | 713 |
| 5962-8967001CA | A | 03/12/2001 | | (NONE) | 04/16/2002 | | OP490A (GEN) | 713 |
| 5962-89671013A | B | 11/05/2002 | | (NONE) | | | DAC8221A (GEN) | 591 |
| 5962-8967101LA | B | 11/05/2002 | 1 | ANALOG (5) | | Y | DAC-8221AW | 591 |
| 5962-8967201LA | A | 07/25/2001 | | (NONE) | 04/30/2003 | | DAC8222A (GEN) | 591 |
| 5962-8967301CA | | 11/17/1989 | | (NONE) | 04/14/2001 | | OP-50A (GEN) | 724 |
| 5962-8967302CA | | 11/17/1989 | | (NONE) | 04/14/2001 | | OP-50B (GEN) | 724 |
| 5962-8967401QC | C | 08/23/2001 | 1 | MAXWELL | | Y | SEI5014-SD14B | 592 |
| 5962-8967401XC | C | 08/23/2001 | 1 | MAXWELL | | Y | SEI5014-SE14B | 592 |
| 5962-8967402QC | C | 08/23/2001 | 1 | MAXWELL | | Y | SEI5014-TD14B | 592 |
| 5962-8967402XC | C | 08/23/2001 | 1 | MAXWELL | | Y | SEI5014-TE14B | 592 |
| 5962-8967601QA | C | 08/23/2001 | 1 | MAXWELL | | Y | SEI5016-SD16B | 592 |
| 5962-8967601XA | C | 08/23/2001 | 1 | MAXWELL | | Y | SEI5016-SE16B | 592 |
| 5962-8967602QA | C | 08/23/2001 | 1 | MAXWELL | | Y | SEI5016-TD16B | 592 |
| 5962-8967602XA | C | 08/23/2001 | 1 | MAXWELL | | Y | SEI5016-TE16B | 592 |
| 5962-89677012A | G | 02/06/2004 | 1 | TI | | Y | LT1014AMFKB | 713 |
| 5962-8967701CA | G | 02/06/2004 | 1 | TI | | Y | LT1014AMJB | 713 |
| 5962-89677022A | G | 02/06/2004 | 1 | TI | | Y | LT1014MFKB | 713 |
| 5962-8967702CA | G | 02/06/2004 | 1 | TI | | Y | LT1014MJB | 713 |
| 5962-8967702DA | G | 02/06/2004 | | (NONE) | | | LT1014 (GEN) | 713 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-8967702XA | G | 02/06/2004 | | (NONE) | 12/31/2001 | | LT1014 (GEN) | 713 |
| 5962-8967801XA | A | 08/03/2001 | | (NONE) | 04/30/2003 | | DAC8408A (GEN) | 591 |
| 5962-8967802XA | A | 08/03/2001 | | (NONE) | 04/30/2003 | | DAC8408B (GEN) | 591 |
| 5962-8967901QC | B | 08/13/2001 | 1 | MAXWELL | | Y | SEI5012-TD12B | 592 |
| 5962-8967901XC | B | 08/13/2001 | 1 | MAXWELL | | Y | SEI5012-TE12B | 592 |
| 5962-89680012A | B | 05/10/1996 | | (NONE) | 06/30/2000 | | 55ALS160 (GEN) | 590 |
| 5962-8968001RA | B | 05/10/1996 | | (NONE) | 06/30/2000 | | 55ALS160 (GEN) | 590 |
| 5962-8968001SA | B | 05/10/1996 | | (NONE) | 06/30/2000 | | 55ALS160 (GEN) | 590 |
| 5962-89681012A | C | 10/31/1996 | | (NONE) | 06/30/2000 | | 55ALS161 (GEN) | 590 |
| 5962-8968101RA | C | 10/31/1996 | | (NONE) | 06/30/2000 | | 55ALS161 (GEN) | 590 |
| 5962-8968101SA | C | 10/31/1996 | | (NONE) | 06/30/2000 | | 55ALS161 (GEN) | 590 |
| 5962-89682013A | A | 04/23/1999 | 3 | NATIONAL | | Y | 54AC646LMQB | 590 |
| 5962R89682013A | A | 04/23/1999 | 3 | NATIONAL | | Y | 54AC646LMQB-RH | 590 |
| 5962-8968201KA | A | 04/23/1999 | 3 | NATIONAL | | Y | 54AC646FMQB | 590 |
| 5962R8968201KA | A | 04/23/1999 | 3 | NATIONAL | | Y | 54AC646FMQB-RH | 590 |
| 5962-8968201LA | A | 04/23/1999 | 3 | NATIONAL | | Y | 54AC646SDMQB | 590 |
| 5962R8968201LA | A | 04/23/1999 | 3 | NATIONAL | | Y | 54AC646SDMQB-RH | 590 |
| 5962-8968301HXA | B | 03/26/2001 | 1 | ADV. ANALOG | | Y | AHE2805S/CH | 594 |
| 5962-8968301HZA | B | 03/26/2001 | 1 | ADV. ANALOG | | Y | AHE2805SF/CH | 594 |
| 5962-8968302HXA | B | 03/26/2001 | 1 | ADV. ANALOG | | Y | AHE2805S/CH-SLV | 594 |
| 5962-8968302HZA | B | 03/26/2001 | 1 | ADV. ANALOG | | Y | AHE2805SF/CH-SLV | 594 |
| 5962-8968303HXA | B | 03/26/2001 | 1 | ADV. ANALOG | | Y | AHE2805S/CH-MSTR | 594 |
| 5962-8968303HZA | B | 03/26/2001 | 1 | ADV. ANALOG | | Y | AHE2805SF/CH-MSTR | 594 |
| 5962-89684012A | A | 04/06/2004 | | MICROSEMI | | Y | SG2821L/883B | 790 |
| 5962-8968401VA | A | 04/06/2004 | | MICROSEMI | | Y | SG2821J/883B | 790 |
| 5962-89685012A | A | 12/03/2002 | | MICROSEMI | | Y | SG2823L/883B | 790 |
| 5962-8968501VA | A | 12/03/2002 | | MICROSEMI | | Y | SG2823J/883B | 790 |
| 5962-89686012A | A | 12/04/2002 | | MICROSEMI | | Y | SG2824L/883B | 790 |
| 5962-8968601VA | A | 12/04/2002 | | MICROSEMI | | Y | SG2824J/883B | 790 |
| 5962-89687013A | C | 08/10/2004 | 3 | TI | | Y | SNJ54ALS653FK | 590 |
| 5962-8968701KA | C | 08/10/2004 | 3 | TI | | Y | SNJ54ALS653W | 590 |
| 5962-8968701LA | C | 08/10/2004 | 3 | TI | | Y | SNJ54ALS653JT | 590 |
| 5962-89688012A | B | 09/24/2002 | 3 | NATIONAL | | Y | 54ACT157LMQB | 275 |
| 5962R89688012A | B | 09/24/2002 | 3 | NATIONAL | | Y | 54ACT157LMQB-RH | 275 |
| 5962R8968801V2A | B | 09/24/2002 | 3 | NATIONAL | | Y | 54ACT157ERQMLV | 275 |
| 5962-8968801EA | B | 09/24/2002 | 3 | NATIONAL | | Y | 54ACT157DMQB | 275 |
| 5962R8968801EA | B | 09/24/2002 | 3 | NATIONAL | | Y | 54ACT157DMQB-RH | 275 |
| 5962R8968801VEA | B | 09/24/2002 | 3 | NATIONAL | | Y | 54ACT157JRQMLV | 275 |
| 5962-8968801FA | B | 09/24/2002 | 3 | NATIONAL | | Y | 54ACT157FMQB | 275 |
| 5962R8968801FA | B | 09/24/2002 | 3 | NATIONAL | | Y | 54ACT157FMQB-RH | 275 |
| 5962R8968801VFA | B | 09/24/2002 | 3 | NATIONAL | | Y | 54ACT157WRQMLV | 275 |
| 5962R8968801VZA | B | 09/24/2002 | 3 | NATIONAL | | Y | 54ACT157WGRQMLV | 275 |
| 5962-8968802VXA | B | 09/24/2002 | 2 | STMICRO | | Y | 54ACT157K02V | 275 |
| 5962-8968802VXC | B | 09/24/2002 | 2 | STMICRO | | Y | 54ACT157K01V | 275 |
| 5962-8968802XA | B | 09/24/2002 | 2 | STMICRO | | Y | 54ACT157K02Q | 275 |
| 5962-8968802XC | B | 09/24/2002 | 2 | STMICRO | | Y | 54ACT157K01Q | 275 |
| 5962-89689012A | C | 03/20/2003 | 3 | NATIONAL | | Y | 54ACT257LMQB | 276 |
| 5962-8968901V2A | C | 03/20/2003 | | (NONE) | | | 54ACT257 (GEN) | 276 |
| 5962R89689012A | C | 03/20/2003 | 3 | NATIONAL | | Y | 54ACT257LMQB-RH | 276 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962R8968901V2A | C | 03/20/2003 | 3 | NATIONAL | | Y | 54ACT257ERQMLV | 276 |
| 5962-8968901EA | C | 03/20/2003 | 3 | NATIONAL | | Y | 54ACT257DMQB | 276 |
| 5962-8968901VEA | C | 03/20/2003 | | (NONE) | | | 54ACT257 (GEN) | 276 |
| 5962R8968901EA | C | 03/20/2003 | 3 | NATIONAL | | Y | 54ACT257DMQB-RH | 276 |
| 5962R8968901VEA | C | 03/20/2003 | 3 | NATIONAL | | Y | 54ACT257JRQMLV | 276 |
| 5962-8968901FA | C | 03/20/2003 | 3 | NATIONAL | | Y | 54ACT257FMQB | 276 |
| 5962-8968901VFA | C | 03/20/2003 | | (NONE) | | | 54ACT257 (GEN) | 276 |
| 5962R8968901FA | C | 03/20/2003 | 3 | NATIONAL | | Y | 54ACT257FMQB-RH | 276 |
| 5962R8968901VFA | C | 03/20/2003 | 3 | NATIONAL | | Y | 54ACT257FRQMLV | 276 |
| 5962-8968901VXA | C | 03/20/2003 | 2 | STMICRO | | Y | 54ACT257K02V | 276 |
| 5962-8968901VXC | C | 03/20/2003 | 2 | STMICRO | | Y | 54ACT257K01V | 276 |
| 5962-8968901XA | C | 03/20/2003 | 2 | STMICRO | | Y | 54ACT257K02Q | 276 |
| 5962-8968901XC | C | 03/20/2003 | 2 | STMICRO | | Y | 54ACT257K01Q | 276 |
| 5962-89690013A | | 10/16/1989 | 1 | PYRAMID | | | P4C116-25L28MB | 616 |
| 5962-89690013A | | 10/16/1989 | 2 | QP SEMI | | Y | QP6116A-25LMB | 616 |
| 5962-8969001JA | | 10/16/1989 | | IDT | | Y | IDT6116SA25DB | 616 |
| 5962-8969001JA | | 10/16/1989 | 2 | QP SEMI | | Y | QP6116A-25DMB | 616 |
| 5962-8969001KA | | 10/16/1989 | 1 | PYRAMID | | | P4C116-25FMB | 616 |
| 5962-8969001KA | | 10/16/1989 | 2 | QP SEMI | | Y | QP7C128A-25KMB | 616 |
| 5962-8969001LA | | 10/16/1989 | | IDT | | Y | IDT6116SA25TDB | 616 |
| 5962-8969001LA | | 10/16/1989 | 1 | PYRAMID | | | P4C116-25DMB | 616 |
| 5962-8969001LA | | 10/16/1989 | 2 | QP SEMI | | Y | QP7C128A-25DMB | 616 |
| 5962-8969001XA | | 10/16/1989 | | (NONE) | 05/06/1997 | | 6116SA25 (GEN) | 616 |
| 5962-8969001YA | | 10/16/1989 | 1 | PYRAMID | | | P4C116-25LMB | 616 |
| 5962-8969001YA | | 10/16/1989 | 2 | QP SEMI | | Y | QP7C128A-25LMB | 616 |
| 5962-8969001ZA | | 10/16/1989 | | (NONE) | | | | 616 |
| 5962-89690023A | | 10/16/1989 | 1 | PYRAMID | | | P4C116-20L28MB | 616 |
| 5962-89690023A | | 10/16/1989 | 2 | QP SEMI | | Y | QP6116A-20LMB | 616 |
| 5962-8969002JA | | 10/16/1989 | | IDT | | Y | IDT6116SA20DB | 616 |
| 5962-8969002JA | | 10/16/1989 | 2 | QP SEMI | | Y | QP6116A-205DMB | 616 |
| 5962-8969002KA | | 10/16/1989 | 1 | PYRAMID | | | P4C116-20FMB | 616 |
| 5962-8969002KA | | 10/16/1989 | 2 | QP SEMI | | Y | QP7C128A-20KMB | 616 |
| 5962-8969002LA | | 10/16/1989 | | IDT | | Y | IDT6116SA20TDB | 616 |
| 5962-8969002LA | | 10/16/1989 | 1 | PYRAMID | | | P4C116-20DMB | 616 |
| 5962-8969002LA | | 10/16/1989 | 2 | QP SEMI | | Y | QP7C128A-20DMB | 616 |
| 5962-8969002XA | | 10/16/1989 | | (NONE) | 05/06/1997 | | 6116SA20 (GEN) | 616 |
| 5962-8969002YA | | 10/16/1989 | 1 | PYRAMID | | | P4C116-20LMB | 616 |
| 5962-8969002YA | | 10/16/1989 | 2 | QP SEMI | | Y | QP7C128A-20LMB | 616 |
| 5962-8969002ZA | | 10/16/1989 | | (NONE) | | | | 616 |
| 5962-8969101TA | A | 10/29/1990 | 0 | PYRAMID | 5962-3829414MTA | | P4C164L-25FMB | 620 |
| 5962-8969101UA | A | 10/29/1990 | 0 | PYRAMID | 5962-3829428MUA | | P4C164L-25LMB | 620 |
| 5962-8969101XA | A | 10/29/1990 | 0 | PYRAMID | 5962-3829414MXA | | P4C164L-25DWMB | 620 |
| 5962-8969101ZA | A | 10/29/1990 | 0 | PYRAMID | 5962-3829414MZA | | P4C164L-25CMB | 620 |
| 5962-8969102NA | A | 10/29/1990 | | (NONE) | 5962-3829415MUA | | 5C6408-25 (GEN) | 620 |
| 5962-8969102TA | A | 10/29/1990 | 0 | PYRAMID | 5962-3829415MTA | | P4C164-25FMB | 620 |
| 5962-8969102UA | A | 10/29/1990 | 0 | PYRAMID | 5962-3829429MUA | | P4C164-25LMB | 620 |
| 5962-8969102XA | A | 10/29/1990 | 0 | PYRAMID | 5962-3829415MXA | | P4C164-25DWMB | 620 |
| 5962-8969102YA | A | 10/29/1990 | | (NONE) | 5962-3829415MYA | | 5C6408-25 (GEN) | 620 |
| 5962-8969102ZA | A | 10/29/1990 | 0 | PYRAMID | 5962-3829415MZA | | P4C164-25CMB | 620 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-8969102ZA | A | 10/29/1990 | 3 | QP SEMI | 5962-3829415MZA | Y | QP7C185A-25DMB | 620 |
| 5962-8969104NA | A | 10/29/1990 | | (NONE) | 5962-3829417MUA | | 5C6408-20 (GEN) | 620 |
| 5962-8969104TA | A | 10/29/1990 | 0 | PYRAMID | 5962-3829417MTA | | P4C164-20FMB | 620 |
| 5962-8969104UA | A | 10/29/1990 | 0 | PYRAMID | 5962-3829430MUA | | P4C164-20LMB | 620 |
| 5962-8969104XA | A | 10/29/1990 | 0 | PYRAMID | 5962-3829417MXA | | P4C164-20DWMB | 620 |
| 5962-8969104YA | A | 10/29/1990 | | (NONE) | 5962-3829417MYA | | 5C6408-20 (GEN) | 620 |
| 5962-8969104ZA | A | 10/29/1990 | 0 | PYRAMID | 5962-3829417MZA | | P4C164-20CMB | 620 |
| 5962-8969104ZA | A | 10/29/1990 | 3 | QP SEMI | 5962-3829417MZA | Y | QP7C185A-20DMB | 620 |
| 5962-8969106NA | A | 10/29/1990 | | (NONE) | 5962-3829419MUA | | 5C6408-15 (GEN) | 620 |
| 5962-8969106TA | A | 10/29/1990 | 0 | PYRAMID | 5962-3829419MTA | | P4C164-15FMB | 620 |
| 5962-8969106UA | A | 10/29/1990 | | (NONE) | 5962-3829419MUA | | 7B185-15 (GEN) | 620 |
| 5962-8969106XA | A | 10/29/1990 | 0 | PYRAMID | 5962-3829419MXA | | P4C164-15DWMB | 620 |
| 5962-8969106YA | A | 10/29/1990 | | (NONE) | 5962-3829419MYA | | 5C6408-15 (GEN) | 620 |
| 5962-8969106ZA | A | 10/29/1990 | 0 | PYRAMID | 5962-3829419MZA | | P4C164-15CMB | 620 |
| 5962-8969201KA | | 12/12/1989 | 1 | PYRAMID | | | P4C188L-25FMB | 620 |
| 5962-8969201XA | | 12/12/1989 | 1 | PYRAMID | | | P4C188L-25CMB | 620 |
| 5962-8969201YA | | 12/12/1989 | 1 | IDT | | Y | IDT7188L-25DB | 620 |
| 5962-8969201YA | | 12/12/1989 | 1 | PYRAMID | | | P4C188L-25DMB | 620 |
| 5962-8969201ZA | | 12/12/1989 | 1 | PYRAMID | | | P4C188L-25LMB | 620 |
| 5962-8969202KA | | 12/12/1989 | 1 | PYRAMID | | | P4C188-25FMB | 620 |
| 5962-8969202XA | | 12/12/1989 | 1 | AUSTIN SEMI. | | Y | MT5C6404C-25883C | 620 |
| 5962-8969202XA | | 12/12/1989 | 1 | PYRAMID | | | P4C188-25CMB | 620 |
| 5962-8969202YA | | 12/12/1989 | 1 | IDT | | Y | IDT7188S25DB | 620 |
| 5962-8969202YA | | 12/12/1989 | 1 | PYRAMID | | | P4C188-25DMB | 620 |
| 5962-8969202ZA | | 12/12/1989 | 1 | AUSTIN SEMI. | | Y | MT5C6404EC-25883C | 620 |
| 5962-8969202ZA | | 12/12/1989 | 1 | PYRAMID | | | P4C188-25LMB | 620 |
| 5962-8969203KA | | 12/12/1989 | 1 | PYRAMID | | | P4C188L-20FMB | 620 |
| 5962-8969203XA | | 12/12/1989 | 1 | PYRAMID | | | P4C188L-20CMB | 620 |
| 5962-8969203YA | | 12/12/1989 | 1 | PYRAMID | | | P4C188L-20DMB | 620 |
| 5962-8969203ZA | | 12/12/1989 | 1 | PYRAMID | | | P4C188L-20LMB | 620 |
| 5962-8969204KA | | 12/12/1989 | 1 | PYRAMID | | | P4C188-20FMB | 620 |
| 5962-8969204XA | | 12/12/1989 | | AUSTIN SEMI. | | Y | MT5C6404C-20883C | 620 |
| 5962-8969204XA | | 12/12/1989 | 1 | PYRAMID | | | P4C188-20CMB | 620 |
| 5962-8969204YA | | 12/12/1989 | 1 | PYRAMID | | | P4C188-20DMB | 620 |
| 5962-8969204ZA | | 12/12/1989 | 1 | AUSTIN SEMI. | | Y | MT5C6404EC-20883C | 620 |
| 5962-8969204ZA | | 12/12/1989 | 1 | PYRAMID | | | P4C188-20LMB | 620 |
| 5962-8969205KA | | 12/12/1989 | 1 | PYRAMID | | | P4C188L-15FMB | 620 |
| 5962-8969205XA | | 12/12/1989 | 1 | PYRAMID | | | P4C188L-15CMB | 620 |
| 5962-8969205YA | | 12/12/1989 | 1 | PYRAMID | | | P4C188L-15DMB | 620 |
| 5962-8969205ZA | | 12/12/1989 | 1 | PYRAMID | | | P4C188L-15LMB | 620 |
| 5962-8969206KA | | 12/12/1989 | 1 | PYRAMID | | | P4C188-15FMB | 620 |
| 5962-8969206XA | | 12/12/1989 | | AUSTIN SEMI. | | Y | MT5C6404C-15883C | 620 |
| 5962-8969206XA | | 12/12/1989 | 1 | PYRAMID | | | P4C188-15CMB | 620 |
| 5962-8969206YA | | 12/12/1989 | 1 | PYRAMID | | | P4C188-15DMB | 620 |
| 5962-8969206ZA | | 12/12/1989 | 1 | AUSTIN SEMI. | | Y | MT5C6404EC-15883C | 620 |
| 5962-8969206ZA | | 12/12/1989 | 1 | PYRAMID | | | P4C188-15LMB | 620 |
| 5962-89693012A | A | 06/22/1998 | 3 | NATIONAL | | Y | 54ACT175LMQB | 159 |
| 5962-8969301V2A | A | 06/22/1998 | 3 | NATIONAL | | Y | 54ACT175E-QMLV | 159 |
| 5962R89693012A | A | 06/22/1998 | 3 | NATIONAL | | Y | 54ACT175LMQB-RH | 159 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962R8969301V2A | A | 06/22/1998 | 3 | NATIONAL | | Y | 54ACT175ERQMLV | 159 |
| 5962-8969301EA | A | 06/22/1998 | 3 | NATIONAL | | Y | 54ACT175DMQB | 159 |
| 5962-8969301VEA | A | 06/22/1998 | 3 | NATIONAL | | Y | 54ACT175J-QMLV | 159 |
| 5962R8969301EA | A | 06/22/1998 | 3 | NATIONAL | | Y | 54ACT175DMQB-RH | 159 |
| 5962R8969301VEA | A | 06/22/1998 | 3 | NATIONAL | | Y | 54ACT175JRQMLV | 159 |
| 5962-8969301FA | A | 06/22/1998 | 3 | NATIONAL | | Y | 54ACT175FMQB | 159 |
| 5962-8969301VFA | A | 06/22/1998 | 3 | NATIONAL | | Y | 54ACT175W-QMLV | 159 |
| 5962R8969301FA | A | 06/22/1998 | 3 | NATIONAL | | Y | 54ACT175FMQB-RH | 159 |
| 5962R8969301VFA | A | 06/22/1998 | 3 | NATIONAL | | Y | 54ACT175WRQMLV | 159 |
| 5962-8969401EA | B | 01/19/2000 | | (NONE) | | | 7C190-25 (GEN) | 602 |
| 5962-8969401FA | B | 01/19/2000 | | (NONE) | 05/10/1995 | | 7C190-25 (GEN) | 602 |
| 5962-8969401XA | B | 01/19/2000 | | (NONE) | | | 7C190-25 (GEN) | 602 |
| 5962-8969402EA | B | 01/19/2000 | 1 | SARNOFF | | Y | GEM25402BEA | 602 |
| 5962-8969402EC | B | 01/19/2000 | 1 | SARNOFF | | Y | GEM25402BEC | 602 |
| 5962-8969402FA | B | 01/19/2000 | 1 | SARNOFF | | Y | GEM25402BFA | 602 |
| 5962-8969402FC | B | 01/19/2000 | 1 | SARNOFF | | Y | GEM25402BFC | 602 |
| 5962-8969402XA | B | 01/19/2000 | 1 | SARNOFF | | Y | GEM25402BXA | 602 |
| 5962-8969402XC | B | 01/19/2000 | 1 | SARNOFF | | Y | GEM25402BXC | 602 |
| 5962-8969402YA | B | 01/19/2000 | 1 | SARNOFF | | Y | GEM25402BYA | 602 |
| 5962-8969402YC | B | 01/19/2000 | 1 | SARNOFF | | Y | GEM25402BYC | 602 |
| 5962-89695012A | | 04/09/1990 | | (NONE) | 12/01/1993 | | 54HC113 (GEN) | 156 |
| 5962-8969501CA | | 04/09/1990 | | (NONE) | 12/01/1993 | | 54HC113 (GEN) | 156 |
| 5962-8969601XA | C | 04/21/1998 | | (NONE) | 12/31/1998 | | 65787 (GEN) | 620 |
| 5962-8969601ZA | C | 04/21/1998 | | (NONE) | | | | 620 |
| 5962-8969602XA | C | 04/21/1998 | 1 | PYRAMID | | | P4C187L-25CMB | 620 |
| 5962-8969602ZA | C | 04/21/1998 | 1 | PYRAMID | | | P4C187L-25LMB | 620 |
| 5962-8969603XA | C | 04/21/1998 | | (NONE) | 12/31/1998 | | 65787 (GEN) | 620 |
| 5962-8969603ZA | C | 04/21/1998 | | (NONE) | | | | 620 |
| 5962-8969604XA | C | 04/21/1998 | 1 | PYRAMID | | | P4C187L-20CMB | 620 |
| 5962-8969604ZA | C | 04/21/1998 | 1 | PYRAMID | | | P4C187L-20LMB | 620 |
| 5962-8969605XA | C | 04/21/1998 | 1 | PYRAMID | | | P4C187-15CMB | 620 |
| 5962-8969605ZA | C | 04/21/1998 | 1 | PYRAMID | | | P4C187-15LMB | 620 |
| 5962-8969606XA | C | 04/21/1998 | 1 | PYRAMID | | | P4C187L-15CMB | 620 |
| 5962-8969606ZA | C | 04/21/1998 | 1 | PYRAMID | | | P4C187L-15LMB | 620 |
| 5962-8969607XA | C | 04/21/1998 | 1 | PYRAMID | | | P4C187-25CMB | 620 |
| 5962-8969607ZA | C | 04/21/1998 | 1 | PYRAMID | | | P4C187-25LMB | 620 |
| 5962-8969608XA | C | 04/21/1998 | 1 | PYRAMID | | | P4C187-20CMB | 620 |
| 5962-8969608ZA | C | 04/21/1998 | 1 | PYRAMID | | | P4C187-20LMB | 620 |
| 5962-8969609XA | C | 04/21/1998 | 1 | PYRAMID | | | P4C187-12CMB | 620 |
| 5962-8969609ZA | C | 04/21/1998 | 1 | PYRAMID | | | P4C187-12LMB | 620 |
| 5962-8969610XA | C | 04/21/1998 | 1 | PYRAMID | | | P4C187L-12CMB | 620 |
| 5962-8969610ZA | C | 04/21/1998 | 1 | PYRAMID | | | P4C187L-12LMB | 620 |
| 5962-89697013A | B | 12/07/2001 | 1 | ANALOG (3) | | Y | AD7846SE/883B | 591 |
| 5962-8969701XA | B | 12/07/2001 | 1 | ANALOG (3) | | Y | AD7846SQ/883B | 591 |
| 5962-8969801LA | A | 10/02/2001 | 1 | ANALOG (3) | | Y | AD7579SQ/883B | 592 |
| 5962-8969802LA | A | 10/02/2001 | | (NONE) | | | AD7580 (GEN) | 592 |
| 5962-8970001EA | | 07/24/1989 | 1 | TI | | Y | CD54HCT123F3A | 166 |
| 5962-8970101EA | A | 09/25/1992 | 1 | TI | | Y | CD54HCT175F3A | 159 |
| 5962-8970201EA | | 07/28/1989 | 1 | TI | | Y | CD54HCT112F3A | 152 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-8970301CA | A | 04/05/1993 | 1 | TI | | Y | CD54HCT27F3A | 122 |
| 5962-8970401CA | A | 04/13/1993 | 1 | TI | | Y | CD54HCT164F3A | 226 |
| 5962-8970501EA | | 08/08/1989 | 1 | TI | | Y | CD54HCT257F3A | 276 |
| 5962-8970701EA | | 08/01/1989 | 1 | TI | | Y | CD54HCT162BF3A | 301 |
| 5962-8970801EA | | 08/28/1989 | 1 | TI | | Y | CD54HCT258F3A | 276 |
| 5962-8970901CA | | 09/29/1989 | 1 | TI | | Y | CD54HCT11F3A | 112 |
| 5962-89710013A | B | 10/29/1992 | 1 | ANALOG (3) | | Y | ADG526ATE/883B | 195 |
| 5962-8971001XA | B | 10/29/1992 | 1 | ANALOG (3) | | Y | ADG526ATQ/883B | 195 |
| 5962-89710023A | B | 10/29/1992 | 1 | ANALOG (3) | | Y | ADG527ATE/883B | 193 |
| 5962-8971002XA | B | 10/29/1992 | 1 | ANALOG (3) | | Y | ADG527ATQ/883B | 193 |
| 5962-89711013A | A | 08/04/1992 | 1 | QP SEMI | | | TMC2023C3V | 399 |
| 5962-8971101JA | A | 08/04/1992 | 1 | QP SEMI | | | TMC2023J7V | 399 |
| 5962-8971101LA | A | 08/04/1992 | 1 | QP SEMI | | | TMC2023J2V | 399 |
| 5962-89711023A | A | 08/04/1992 | 1 | QP SEMI | | | TMC2023C3V1 | 399 |
| 5962-8971102JA | A | 08/04/1992 | 1 | QP SEMI | | | TMC2023J7V1 | 399 |
| 5962-8971102LA | A | 08/04/1992 | 1 | QP SEMI | | | TMC2023J2V1 | 399 |
| 5962-89711033A | A | 08/04/1992 | 1 | QP SEMI | | | TMC2023C3V2 | 399 |
| 5962-8971103JA | A | 08/04/1992 | 1 | QP SEMI | | | TMC2023J7V2 | 399 |
| 5962-8971103LA | A | 08/04/1992 | 1 | QP SEMI | | | TMC2023J2V2 | 399 |
| 5962-89711043A | A | 08/04/1992 | 1 | QP SEMI | | | TMC2023C3V3 | 399 |
| 5962-8971104JA | A | 08/04/1992 | 1 | QP SEMI | | | TMC2023J7V3 | 399 |
| 5962-8971104LA | A | 08/04/1992 | 1 | QP SEMI | | | TMC2023J2V3 | 399 |
| 5962-8971201UA | A | 05/04/1999 | 1 | PYRAMID | | | P4C1982-45LMB | 620 |
| 5962-8971201XA | A | 05/04/1999 | 1 | PYRAMID | | | P4C1982-45CMB | 620 |
| 5962-8971201YA | A | 05/04/1999 | 1 | PYRAMID | | | P4C1982-45FMB | 620 |
| 5962-8971201ZA | A | 05/04/1999 | 1 | PYRAMID | | | P4C1982-45LMB | 620 |
| 5962-8971202UA | A | 05/04/1999 | 1 | PYRAMID | | | P4C1982-35LMB | 620 |
| 5962-8971202XA | A | 05/04/1999 | 1 | PYRAMID | | | P4C1982-35CMB | 620 |
| 5962-8971202YA | A | 05/04/1999 | 1 | PYRAMID | | | P4C1982-35FMB | 620 |
| 5962-8971202ZA | A | 05/04/1999 | 1 | PYRAMID | | | P4C1982-35LMB | 620 |
| 5962-8971203UA | A | 05/04/1999 | 1 | PYRAMID | | | P4C1982-25LMB | 620 |
| 5962-8971203XA | A | 05/04/1999 | 1 | PYRAMID | | | P4C1982-25CMB | 620 |
| 5962-8971203YA | A | 05/04/1999 | 1 | PYRAMID | | | P4C1982-25FMB | 620 |
| 5962-8971203ZA | A | 05/04/1999 | 1 | PYRAMID | | | P4C1982-25LMB | 620 |
| 5962-8971204UA | A | 05/04/1999 | 1 | PYRAMID | | | P4C1982-20LMB | 620 |
| 5962-8971204XA | A | 05/04/1999 | 1 | PYRAMID | | | P4C1982-20CMB | 620 |
| 5962-8971204YA | A | 05/04/1999 | 1 | PYRAMID | | | P4C1982-20FMB | 620 |
| 5962-8971204ZA | A | 05/04/1999 | 1 | PYRAMID | | | P4C1982-20LMB | 620 |
| 5962-8971301Q8A | F | 02/01/2002 | | (NONE) | | | 3042-50 (GEN) | 431 |
| 5962-8971301M9C | F | 02/01/2002 | | (NONE) | 01/15/2000 | | 3042-50 (GEN) | 431 |
| 5962-8971301MMC | F | 02/01/2002 | | (NONE) | 01/15/2000 | | 3042-50 (GEN) | 431 |
| 5962-8971301MNC | F | 02/01/2002 | | (NONE) | 01/15/2000 | | 3042-50 (GEN) | 431 |
| 5962-8971301QTA | F | 02/01/2002 | | (NONE) | | | 3042-50 (GEN) | 431 |
| 5962-8971301QUA | F | 02/01/2002 | | (NONE) | | | 3042-50 (GEN) | 431 |
| 5962-8971301MXC | F | 02/01/2002 | | (NONE) | 01/15/2000 | | 3042-50 (GEN) | 431 |
| 5962-8971301XC | F | 02/01/2002 | | (NONE) | 01/15/2000 | | 3042-50 (GEN) | 431 |
| 5962-8971301MYC | F | 02/01/2002 | | (NONE) | 01/15/2000 | | 3042-50 (GEN) | 431 |
| 5962-8971301YC | F | 02/01/2002 | | (NONE) | 01/15/2000 | | 3042-50 (GEN) | 431 |
| 5962-8971301MZC | F | 02/01/2002 | | (NONE) | 01/15/2000 | | 3042-50 (GEN) | 431 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-8971301QZA | F | 02/01/2002 | | (NONE) | | | 3042-50 (GEN) | 431 |
| 5962-8971301ZC | F | 02/01/2002 | | (NONE) | 01/15/2000 | | 3042-50 (GEN) | 431 |
| 5962-8971302Q8A | F | 02/01/2002 | | (NONE) | | | 3042-70 (GEN) | 431 |
| 5962-8971302M9C | F | 02/01/2002 | | (NONE) | 01/15/2000 | | 3042-70 (GEN) | 431 |
| 5962-8971302MMC | F | 02/01/2002 | | (NONE) | 01/15/2000 | | 3042-70 (GEN) | 431 |
| 5962-8971302MNC | F | 02/01/2002 | | (NONE) | 01/15/2000 | | 3042-70 (GEN) | 431 |
| 5962-8971302QTA | F | 02/01/2002 | | (NONE) | | | 3042-70 (GEN) | 431 |
| 5962-8971302QUA | F | 02/01/2002 | | (NONE) | | | 3042-70 (GEN) | 431 |
| 5962-8971302MXC | F | 02/01/2002 | | (NONE) | 01/15/2000 | | 3042-70 (GEN) | 431 |
| 5962-8971302XC | F | 02/01/2002 | | (NONE) | 01/15/2000 | | 3042-70 (GEN) | 431 |
| 5962-8971302MYC | F | 02/01/2002 | | (NONE) | 01/15/2000 | | 3042-70 (GEN) | 431 |
| 5962-8971302YC | F | 02/01/2002 | | (NONE) | 01/15/2000 | | 3042-70 (GEN) | 431 |
| 5962-8971302MZC | F | 02/01/2002 | | (NONE) | 01/15/2000 | | 3042-70 (GEN) | 431 |
| 5962-8971302QZA | F | 02/01/2002 | | (NONE) | | | 3042-70 (GEN) | 431 |
| 5962-8971302ZC | F | 02/01/2002 | | (NONE) | 01/15/2000 | | 3042-70 (GEN) | 431 |
| 5962-8971303Q8A | F | 02/01/2002 | | (NONE) | | | 3042-100 (GEN) | 431 |
| 5962-8971303M9C | F | 02/01/2002 | 1 | XILINX | | Y | XC3042-100CB100B | 431 |
| 5962-8971303MMC | F | 02/01/2002 | 1 | XILINX | | Y | XC3042-100CQ100B | 431 |
| 5962-8971303MNC | F | 02/01/2002 | 1 | XILINX | | Y | XC3042-100CQ100B | 431 |
| 5962-8971303QTA | F | 02/01/2002 | | (NONE) | | | 3042-100 (GEN) | 431 |
| 5962-8971303QUA | F | 02/01/2002 | | (NONE) | | | 3042-100 (GEN) | 431 |
| 5962-8971303MXC | F | 02/01/2002 | 1 | XILINX | | Y | XC3042-100PG84B | 431 |
| 5962-8971303MYC | F | 02/01/2002 | 1 | XILINX | | Y | XC3042-100CQ100B | 431 |
| 5962-8971303MZC | F | 02/01/2002 | 1 | XILINX | | Y | XC3042-100PG132B | 431 |
| 5962-8971303QZA | F | 02/01/2002 | | (NONE) | | | 3042-100 (GEN) | 431 |
| 5962-8971304Q8A | F | 02/01/2002 | | (NONE) | | | 3042-125 (GEN) | 431 |
| 5962-8971304QTA | F | 02/01/2002 | | (NONE) | | | 3042-125 (GEN) | 431 |
| 5962-8971304QUA | F | 02/01/2002 | | (NONE) | | | 3042-125 (GEN) | 431 |
| 5962-8971304QZA | F | 02/01/2002 | | (NONE) | | | 3042-125 (GEN) | 431 |
| 5962-8971501XC | B | 09/18/1998 | | (NONE) | 12/31/1995 | | TMC2301 (GEN) | 399 |
| 5962-8971501YA | B | 09/18/1998 | | (NONE) | 12/31/1995 | | TMC2301 (GEN) | 399 |
| 5962-8971502XC | B | 09/18/1998 | | (NONE) | 12/31/1995 | | TMC2301 (GEN) | 399 |
| 5962-8971502YA | B | 09/18/1998 | | (NONE) | 12/31/1995 | | TMC2301 (GEN) | 399 |
| 5962-8971503XA | B | 09/18/1998 | | (NONE) | 04/01/2000 | | LF2301-55 (GEN) | 399 |
| 5962-8971503YA | B | 09/18/1998 | | (NONE) | 04/01/2000 | | LF2301-55 (GEN) | 399 |
| 5962-8971601MQC | B | 04/15/1996 | | (NONE) | | | LPR520 (GEN) | 249 |
| 5962-8971601MXC | B | 04/15/1996 | | (NONE) | | | LPR520 (GEN) | 249 |
| 5962-8971602MQC | B | 04/15/1996 | | (NONE) | | | LPR520 (GEN) | 249 |
| 5962-8971602MXC | B | 04/15/1996 | | (NONE) | | | LPR520 (GEN) | 249 |
| 5962-8971603MQC | B | 04/15/1996 | | (NONE) | | | LPR520 (GEN) | 249 |
| 5962-8971603MXC | B | 04/15/1996 | | (NONE) | | | LPR520 (GEN) | 249 |
| 5962-8971604MQC | B | 04/15/1996 | | (NONE) | | | LPR521 (GEN) | 249 |
| 5962-8971604MXC | B | 04/15/1996 | | (NONE) | | | LPR521 (GEN) | 249 |
| 5962-8971605MQC | B | 04/15/1996 | | (NONE) | | | LPR521 (GEN) | 249 |
| 5962-8971605MXC | B | 04/15/1996 | | (NONE) | | | LPR521 (GEN) | 249 |
| 5962-8971606MQC | B | 04/15/1996 | | (NONE) | | | LPR521 (GEN) | 249 |
| 5962-8971606MXC | B | 04/15/1996 | | (NONE) | | | LPR521 (GEN) | 249 |
| 5962-8971701MXA | A | 10/29/1992 | | (NONE) | 04/01/2000 | | LSH32-50 (GEN) | 232 |
| 5962-8971701MYA | A | 10/29/1992 | | (NONE) | 04/01/2000 | | LSH32-50 (GEN) | 232 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-8971702MXA | A | 10/29/1992 | | (NONE) | 04/01/2000 | | LSH32-40 (GEN) | 232 |
| 5962-8971702MYA | A | 10/29/1992 | | (NONE) | 04/01/2000 | | LSH32-40 (GEN) | 232 |
| 5962-8971801XA | B | 11/19/1991 | 1 | MICRO NETWKS | | Y | MN3020H/B | 591 |
| 5962-8971801XC | B | 11/19/1991 | 1 | MICRO NETWKS | | Y | MN3020H/B | 591 |
| 5962-89721012A | B | 03/15/2001 | | (NONE) | | | HA-2529 (GEN) | 702 |
| 5962-8972101GC | B | 03/15/2001 | 1 | INTERSIL | 10/03/2004 | Y | HA2-2529/883 | 702 |
| 5962-8972101PA | B | 03/15/2001 | | (NONE) | | | HA-2529 (GEN) | 702 |
| 5962-89722013A | | 08/11/1989 | | (NONE) | | | 54F30245 (GEN) | 590 |
| 5962-8972201KA | | 08/11/1989 | | (NONE) | | | 54F30245 (GEN) | 590 |
| 5962-8972201LA | | 08/11/1989 | | (NONE) | | | 54F30245 (GEN) | 590 |
| 5962-89723012A | | 08/11/1989 | | (NONE) | 06/01/1997 | | 54F259 (GEN) | 341 |
| 5962-8972301EA | | 08/11/1989 | | (NONE) | 06/01/1997 | | 54F259 (GEN) | 341 |
| 5962-8972301FA | | 08/11/1989 | | (NONE) | 06/01/1997 | | 54F259 (GEN) | 341 |
| 5962-89724012A | A | 11/22/1991 | | (NONE) | 06/01/1997 | | 54F574 (GEN) | 159 |
| 5962-8972401RA | A | 11/22/1991 | | (NONE) | 06/01/1997 | | 54F574 (GEN) | 159 |
| 5962-8972401SA | A | 11/22/1991 | | (NONE) | 06/01/1997 | | 54F574 (GEN) | 159 |
| 5962-8972501XA | A | 03/29/1995 | | (NONE) | 12/24/1997 | | 82510 (GEN) | 420 |
| 5962-89725023A | A | 03/29/1995 | | (NONE) | 12/24/1997 | | 82510 (GEN) | 420 |
| 5962-8972601MMA | C | 06/07/1993 | 3 | QP SEMI | | Y | 80C451/BMA | 420 |
| 5962-8972601MUA | C | 06/07/1993 | | (NONE) | | | 80C451 (GEN) | 420 |
| 5962-8972601UA | C | 06/07/1993 | | (NONE) | 5962-8972601MUA | | 80C451 (GEN) | 420 |
| 5962-8972601MXA | C | 06/07/1993 | | (NONE) | | | 80C451 (GEN) | 420 |
| 5962-8972601XA | C | 06/07/1993 | | (NONE) | 5962-8972601MXA | | 80C451 (GEN) | 420 |
| 5962-8972602MMA | C | 06/07/1993 | | (NONE) | | | 83C451 (GEN) | 420 |
| 5962-8972602MUA | C | 06/07/1993 | | (NONE) | | | 83C451 (GEN) | 420 |
| 5962-8972602UA | C | 06/07/1993 | | (NONE) | 5962-8972602MUA | | 83C451 (GEN) | 420 |
| 5962-8972602MXA | C | 06/07/1993 | | (NONE) | | | 83C451 (GEN) | 420 |
| 5962-8972602XA | C | 06/07/1993 | | (NONE) | 5962-8972602MXA | | 83C451 (GEN) | 420 |
| 5962-89728012A | A | 03/30/2001 | | (NONE) | 04/30/2003 | | AD588S (GEN) | 785 |
| 5962-8972801EA | A | 03/30/2001 | | (NONE) | 04/30/2003 | | AD588S (GEN) | 785 |
| 5962-89728022A | A | 03/30/2001 | 1 | ANALOG (2) | | Y | AD588TE/883B | 785 |
| 5962-8972802EA | A | 03/30/2001 | | (NONE) | 04/30/2003 | | AD588T (GEN) | 785 |
| 5962-89729012A | D | 01/10/2001 | 3 | NATIONAL | | Y | 54AC158LMQB | 275 |
| 5962-8972901V2A | D | 01/10/2001 | | (NONE) | | | 54AC158 (GEN) | 275 |
| 5962R8972901Q2A | D | 01/10/2001 | | (NONE) | | | 54AC158 (GEN) | 275 |
| 5962R8972901V2A | D | 01/10/2001 | 3 | NATIONAL | | Y | 54AC158ERQMLV | 275 |
| 5962-8972901EA | D | 01/10/2001 | 3 | NATIONAL | | Y | 54AC158DMQB | 275 |
| 5962-8972901VEA | D | 01/10/2001 | 3 | NATIONAL | | Y | 54AC158J-QMLV | 275 |
| 5962R8972901QEA | D | 01/10/2001 | | (NONE) | | | 54AC158 (GEN) | 275 |
| 5962R8972901VEA | D | 01/10/2001 | 3 | NATIONAL | | Y | 54AC158JRQMLV | 275 |
| 5962-8972901FA | D | 01/10/2001 | 3 | NATIONAL | | Y | 54AC158FMQB | 275 |
| 5962-8972901VFA | D | 01/10/2001 | 3 | NATIONAL | | Y | 54AC158W-QMLV | 275 |
| 5962R8972901QFA | D | 01/10/2001 | | (NONE) | | | 54AC158 (GEN) | 275 |
| 5962R8972901VFA | D | 01/10/2001 | 3 | NATIONAL | | Y | 54AC158WRQMLV | 275 |
| 5962-8972901VXA | D | 01/10/2001 | 2 | STMICRO | | Y | 54AC158K02V | 275 |
| 5962-8972901VXC | D | 01/10/2001 | 2 | STMICRO | | Y | 54AC158K01V | 275 |
| 5962-8972901XA | D | 01/10/2001 | 2 | STMICRO | | Y | 54AC158K02Q | 275 |
| 5962-8972901XC | D | 01/10/2001 | 2 | STMICRO | | Y | 54AC158K01Q | 275 |
| 5962-89730013A | A | 02/10/1992 | 1 | IDT | | Y | IDT54FCT543LB | 590 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-8973001KA | A | 02/10/1992 | | (NONE) | 04/29/2002 | | 54FCT543 (GEN) | 590 |
| 5962-8973001LA | A | 02/10/1992 | 1 | IDT | | Y | IDT54FCT543DB | 590 |
| 5962-89730023A | A | 02/10/1992 | 1 | IDT | | Y | IDT54FCT543ALB | 590 |
| 5962-8973002KA | A | 02/10/1992 | | (NONE) | 04/29/2002 | | 54FCT543A (GEN) | 590 |
| 5962-8973002LA | A | 02/10/1992 | 1 | IDT | | Y | IDT54FCT543ADB | 590 |
| 5962-89731013A | | 09/22/1989 | | (NONE) | 04/27/1998 | | 54FCT833A (GEN) | 590 |
| 5962-8973101KA | | 09/22/1989 | | (NONE) | 04/27/1998 | | 54FCT833A (GEN) | 590 |
| 5962-8973101LA | | 09/22/1989 | | (NONE) | 04/27/1998 | | 54FCT833A (GEN) | 590 |
| 5962-89731023A | | 09/22/1989 | | (NONE) | 04/27/1998 | | 54FCT833B (GEN) | 590 |
| 5962-8973102KA | | 09/22/1989 | | (NONE) | 04/27/1998 | | 54FCT833B (GEN) | 590 |
| 5962-8973102LA | | 09/22/1989 | | (NONE) | 04/27/1998 | | 54FCT833B (GEN) | 590 |
| 5962-89732012A | | 09/20/1989 | | (NONE) | | | 54PCT241 (GEN) | 529 |
| 5962-8973201RA | | 09/20/1989 | | (NONE) | | | 54PCT241 (GEN) | 529 |
| 5962-8973201SA | | 09/20/1989 | | (NONE) | | | 54PCT241 (GEN) | 529 |
| 5962-89732022A | | 09/20/1989 | | (NONE) | | | 54PCT241A (GEN) | 529 |
| 5962-8973202RA | | 09/20/1989 | | (NONE) | | | 54PCT241A (GEN) | 529 |
| 5962-8973202SA | | 09/20/1989 | | (NONE) | | | 54PCT241A (GEN) | 529 |
| 5962-89733012A | B | 09/13/1992 | | (NONE) | | | 54FCT191 (GEN) | 304 |
| 5962-8973301EA | B | 09/13/1992 | | (NONE) | | | 54FCT191 (GEN) | 304 |
| 5962-8973301FA | B | 09/13/1992 | | (NONE) | | | 54FCT191 (GEN) | 304 |
| 5962-89733022A | B | 09/13/1992 | | (NONE) | | | 54FCT191A (GEN) | 304 |
| 5962-8973302EA | B | 09/13/1992 | | (NONE) | | | 54FCT191A (GEN) | 304 |
| 5962-8973302FA | B | 09/13/1992 | | (NONE) | | | 54FCT191A (GEN) | 304 |
| 5962-89733032A | B | 09/13/1992 | | (NONE) | 09/01/1996 | | 54FCT191 (GEN) | 304 |
| 5962-8973303EA | B | 09/13/1992 | | (NONE) | 09/01/1996 | | 54FCT191 (GEN) | 304 |
| 5962-8973303FA | B | 09/13/1992 | | (NONE) | 09/01/1996 | | 54FCT191 (GEN) | 304 |
| 5962-89733042A | B | 09/13/1992 | | (NONE) | 09/01/1996 | | 54FCT191A (GEN) | 304 |
| 5962-8973304EA | B | 09/13/1992 | | (NONE) | 09/01/1996 | | 54FCT191A (GEN) | 304 |
| 5962-8973304FA | B | 09/13/1992 | | (NONE) | 09/01/1996 | | 54FCT191A (GEN) | 304 |
| 5962-89734012A | C | 06/24/2002 | 3 | NATIONAL | | Y | 54ACTQ04LMQB | 143 |
| 5962-89734012A | C | 06/24/2002 | 3 | TI | | Y | SNJ54ACT04FK | 143 |
| 5962-8973401V2A | C | 06/24/2002 | 3 | NATIONAL | | Y | 54ACTQ04E-QMLV | 143 |
| 5962-8973401CA | C | 06/24/2002 | 3 | NATIONAL | | Y | 54ACTQ04DMQB | 143 |
| 5962-8973401CA | C | 06/24/2002 | 3 | TI | | Y | SNJ54ACT04J | 143 |
| 5962-8973401VCA | C | 06/24/2002 | 3 | NATIONAL | | Y | 54ACTQ04J-QMLV | 143 |
| 5962-8973401VCA | C | 06/24/2002 | 3 | TI | | Y | SNV54ACT04J | 143 |
| 5962-8973401DA | C | 06/24/2002 | 3 | NATIONAL | | Y | 54ACTQ04FMQB | 143 |
| 5962-8973401DA | C | 06/24/2002 | 3 | TI | | Y | SNJ54ACT04W | 143 |
| 5962-8973401VDA | C | 06/24/2002 | 3 | NATIONAL | | Y | 54ACTQ04W-QMLV | 143 |
| 5962-8973401VDA | C | 06/24/2002 | 3 | TI | | Y | SNV54ACT04W | 143 |
| 5962-89734022A | C | 06/24/2002 | 1 | ROCHESTER | | Y | 54ACT11004/B2A | 143 |
| 5962-8973402RA | C | 06/24/2002 | 1 | ROCHESTER | | Y | 54ACT11004/BRA | 143 |
| 5962-8973403VXA | C | 06/24/2002 | 2 | STMICRO | | Y | 54ACT04K02V | 143 |
| 5962-8973403VXC | C | 06/24/2002 | 2 | STMICRO | | Y | 54ACT04K01V | 143 |
| 5962-8973403XA | C | 06/24/2002 | 2 | STMICRO | | Y | 54ACT04K02Q | 143 |
| 5962-8973403XC | C | 06/24/2002 | 2 | STMICRO | | Y | 54ACT04K01Q | 143 |
| 5962-89735012A | D | 08/16/2000 | 1 | NATIONAL | | Y | 54ACTQ273LMQB | 159 |
| 5962-8973501V2A | D | 08/16/2000 | | (NONE) | | | 54ACTQ273 (GEN) | 159 |
| 5962R89735012A | D | 08/16/2000 | 1 | NATIONAL | | Y | 54ACTQ273LMQB-R | 159 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962R8973501V2A | D | 08/16/2000 | 1 | NATIONAL | | Y | 54ACTQ273ERQMLV | 159 |
| 5962-8973501RA | D | 08/16/2000 | 1 | NATIONAL | | Y | 54ACTQ273DMQB | 159 |
| 5962-8973501VRA | D | 08/16/2000 | | (NONE) | | | 54ACTQ273 (GEN) | 159 |
| 5962R8973501RA | D | 08/16/2000 | 1 | NATIONAL | | Y | 54ACTQ273DMQB-R | 159 |
| 5962R8973501VRA | D | 08/16/2000 | 1 | NATIONAL | | Y | 54ACTQ273JRQMLV | 159 |
| 5962-8973501SA | D | 08/16/2000 | 1 | NATIONAL | | Y | 54ACTQ273FMQB | 159 |
| 5962-8973501VSA | D | 08/16/2000 | | (NONE) | | | 54ACTQ273 (GEN) | 159 |
| 5962R8973501SA | D | 08/16/2000 | 1 | NATIONAL | | Y | 54ACTQ273FMQB-R | 159 |
| 5962R8973501VSA | D | 08/16/2000 | 1 | NATIONAL | | Y | 54ACTQ273WRQMLV | 159 |
| 5962-89736012A | C | 05/07/2004 | 3 | NATIONAL | | Y | 54ACTQ32LMQB | 125 |
| 5962R8973601V2A | C | 05/07/2004 | 3 | NATIONAL | | Y | 54ACTQ32ERQMLV | 125 |
| 5962-8973601CA | C | 05/07/2004 | 3 | NATIONAL | | Y | 54ACTQ32DMQB | 125 |
| 5962R8973601VCA | C | 05/07/2004 | 3 | NATIONAL | | Y | 54ACTQ32JRQMLV | 125 |
| 5962-8973601DA | C | 05/07/2004 | 3 | NATIONAL | | Y | 54ACTQ32FMQB | 125 |
| 5962R8973601VDA | C | 05/07/2004 | 3 | NATIONAL | | Y | 54ACTQ32WRQMLV | 125 |
| 5962-89736022A | C | 05/07/2004 | | (NONE) | 09/15/1995 | | 54ACT11032 (GEN) | 125 |
| 5962-8973602EA | C | 05/07/2004 | | (NONE) | 09/15/1995 | | 54ACT11032 (GEN) | 125 |
| 5962-8973603VXA | C | 05/07/2004 | 2 | STMICRO | | Y | 54ACT32K02V | 125 |
| 5962-8973603VXC | C | 05/07/2004 | 2 | STMICRO | | Y | 54ACT32K01V | 125 |
| 5962-8973603XA | C | 05/07/2004 | 2 | STMICRO | | Y | 54ACT32K02Q | 125 |
| 5962-8973603XC | C | 05/07/2004 | 2 | STMICRO | | Y | 54ACT32K01Q | 125 |
| 5962F8973603VXA | C | 05/07/2004 | 2 | STMICRO | | Y | RHFACT32K02V | 125 |
| 5962F8973603VXC | C | 05/07/2004 | 2 | STMICRO | | Y | RHFACT32K01V | 125 |
| 5962F8973603XA | C | 05/07/2004 | 2 | STMICRO | | Y | RHFACT32K02Q | 125 |
| 5962F8973603XC | C | 05/07/2004 | 2 | STMICRO | | Y | RHFACT32K01Q | 125 |
| 5962-8974001RA | A | 04/16/1992 | 1 | TI | | Y | 54HCT640F3A | 590 |
| 5962-8974101EA | | 01/10/1990 | | (NONE) | | | 54HCT597 (GEN) | 228 |
| 5962-8974201RA | | 03/05/1993 | 1 | TI | | Y | CD54HCT574F3A | 159 |
| 5962-8974301EA | | 03/13/1990 | 1 | TI | | Y | 54HCT174F3A | 159 |
| 5962-89745012A | | 08/25/1989 | 2 | TI | | Y | SNJ54HCT238FK | 282 |
| 5962-8974501EA | | 08/25/1989 | 2 | TI | | Y | SNJ54HCT238J | 282 |
| 5962-8974601CA | | 12/14/1989 | 1 | TI | | Y | 54HCT30F3A | 106 |
| 5962-89747012A | B | 09/11/2003 | 1 | TI | | Y | SNJ54HCT04FK | 143 |
| 5962-8974701CA | B | 09/11/2003 | 1 | TI | | Y | SNJ54HCT04J | 143 |
| 5962-8974701VCA | B | 09/11/2003 | 1 | TI | | Y | SNV54HCT04J | 143 |
| 5962-8974701VDA | B | 09/11/2003 | 1 | TI | | Y | SNV54HCT04W | 143 |
| 5962-89748012A | | 06/15/1990 | 1 | LANSDALE | | Y | SL54LS642/B2A | 590 |
| 5962-89748012C | | 06/15/1990 | 1 | LANSDALE | | Y | SL54LS642/B2C | 590 |
| 5962-8974801RA | | 06/15/1990 | 1 | LANSDALE | | Y | SL54LS642/BRA | 590 |
| 5962-8974801SA | | 06/15/1990 | 1 | LANSDALE | | Y | SL54LS642/BSA | 590 |
| 5962-89749012A | | 03/13/1990 | 3 | NATIONAL | | Y | 54AC191LMQB | 304 |
| 5962-8974901EA | | 03/13/1990 | 3 | NATIONAL | | Y | 54AC191DMQB | 304 |
| 5962-8974901FA | | 03/13/1990 | 3 | NATIONAL | | Y | 54AC191FMQB | 304 |
| 5962-8975101CA | A | 10/22/1991 | 1 | TI | | Y | CD54HCT02F3A | 120 |
| 5962-89754013A | B | 08/11/2004 | 1 | NATIONAL | | Y | 54F646LMQB | 590 |
| 5962-8975401KA | B | 08/11/2004 | 1 | NATIONAL | | Y | 54F646FMQB | 590 |
| 5962-8975401LA | B | 08/11/2004 | 1 | NATIONAL | | Y | 54F646SDMQB | 590 |
| 5962-89754023A | B | 08/11/2004 | 1 | NATIONAL | | Y | 54F648LMQB | 590 |
| 5962-8975402KA | B | 08/11/2004 | | (NONE) | | | 54F648 (GEN) | 590 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-8975402LA | B | 08/11/2004 | 1 | NATIONAL | | Y | 54F648SDMQB | 590 |
| 5962-89755013A | C | 11/08/2001 | 2 | ATMEL | | | AT22V10L-25NM/883 | 431 |
| 5962-89755013A | C | 11/08/2001 | 1 | AUSTIN SEMI. | | | AT22V10L-25NM/883 | 431 |
| 5962-8975501KA | C | 11/08/2001 | | (NONE) | 03/30/1994 | | C22V10L (GEN) | 431 |
| 5962-8975501LA | C | 11/08/2001 | 2 | ATMEL | | | AT22V10L-25GM/883 | 431 |
| 5962-8975501LA | C | 11/08/2001 | 1 | AUSTIN SEMI. | | | AT22V10L-25GM/883 | 431 |
| 5962-89755023A | C | 11/08/2001 | 1 | AUSTIN SEMI. | | | AY22V10L-30NM/883 | 431 |
| 5962-8975502KA | C | 11/08/2001 | | (NONE) | 03/30/1994 | | C22V10L (GEN) | 431 |
| 5962-8975502LA | C | 11/08/2001 | 1 | AUSTIN SEMI. | | | AT22V10L-30GM/883 | 431 |
| 5962-89755033A | C | 11/08/2001 | 1 | AUSTIN SEMI. | | | AT22V10L-40NM/883 | 431 |
| 5962-8975503KA | C | 11/08/2001 | | (NONE) | 03/30/1994 | | C22V10L (GEN) | 431 |
| 5962-8975503LA | C | 11/08/2001 | 1 | AUSTIN SEMI. | | | AT22V10L-40GM/883 | 431 |
| 5962-89755043A | C | 11/08/2001 | 2 | ATMEL | | | AT22V10L-20NM/883 | 431 |
| 5962-89755043A | C | 11/08/2001 | 1 | AUSTIN SEMI. | | | AT22V10L-20NM/883 | 431 |
| 5962-8975504KA | C | 11/08/2001 | | (NONE) | 03/30/1994 | | C22V10L (GEN) | 431 |
| 5962-8975504LA | C | 11/08/2001 | 2 | ATMEL | | | AT22V10L-20GM/883 | 431 |
| 5962-8975504LA | C | 11/08/2001 | 1 | AUSTIN SEMI. | | | AT22V10L-20GM/883 | 431 |
| 5962-89756012A | A | 08/26/1992 | | (NONE) | | | 54LS598 (GEN) | 224 |
| 5962-8975601RA | A | 08/26/1992 | | (NONE) | 12/31/2001 | | 54LS598 (GEN) | 224 |
| 5962-8975601SA | A | 08/26/1992 | | (NONE) | | | 54LS598 (GEN) | 224 |
| 5962-89757013A | B | 08/17/2004 | 2 | TI | | | SNJ54AS885FK | 209 |
| 5962-8975701KA | B | 08/17/2004 | 2 | TI | | | SNJ54AS885W | 209 |
| 5962-8975701LA | B | 08/17/2004 | 2 | TI | | | SNJ54AS885JT | 209 |
| 5962-89758013A | | 03/16/1992 | | (NONE) | | | 54FCT843A (GEN) | 342 |
| 5962-8975801KA | | 03/16/1992 | | (NONE) | | | 54FCT843A (GEN) | 342 |
| 5962-8975801LA | | 03/16/1992 | | (NONE) | | | 54FCT843A (GEN) | 342 |
| 5962-89758023A | | 03/16/1992 | | (NONE) | | | 54FCT843B (GEN) | 342 |
| 5962-8975802KA | | 03/16/1992 | | (NONE) | | | 54FCT843B (GEN) | 342 |
| 5962-8975802LA | | 03/16/1992 | | (NONE) | | | 54FCT843B (GEN) | 342 |
| 5962-89758033A | | 03/16/1992 | | (NONE) | | | 54FCT843C (GEN) | 342 |
| 5962-8975803KA | | 03/16/1992 | | (NONE) | | | 54FCT843C (GEN) | 342 |
| 5962-8975803LA | | 03/16/1992 | | (NONE) | | | 54FCT843C (GEN) | 342 |
| 5962-8976001MXA | A | 01/04/2002 | 1 | SILICONIX | | Y | DG538AAP/883 | 192 |
| 5962-89763012A | A | 11/04/1992 | 0 | SILICONIX | 5962-8976301M2A | Y | DG403AZ/883 | 186 |
| 5962-8976301M2A | A | 11/04/1992 | 0 | SILICONIX | | Y | DG403AZ/883 | 186 |
| 5962-8976301M2C | A | 11/04/1992 | 1 | MAXIM INTEG. | | | DG403AZ/883B | 186 |
| 5962-8976301EA | A | 11/04/1992 | 0 | SILICONIX | 5962-8976301MEA | Y | DG403AK/883 | 186 |
| 5962-8976301MEA | A | 11/04/1992 | 2 | INTERSIL | 10/05/2004 | Y | DG403AK/883 | 186 |
| 5962-8976301MEA | A | 11/04/1992 | 1 | MAXIM INTEG. | | | DG403AK/883B | 186 |
| 5962-8976301MEA | A | 11/04/1992 | 0 | SILICONIX | | Y | DG403AK/883 | 186 |
| 5962-8976401MXA | A | 10/23/1997 | 2 | IDT | | Y | IDT7134SA70CB | 618 |
| 5962-8976401MYA | A | 10/23/1997 | 2 | IDT | | Y | IDT7134SA70L48B | 618 |
| 5962-8976401MZA | A | 10/23/1997 | 3 | IDT | | Y | IDT7134SA70FB | 618 |
| 5962-8976402MXA | A | 10/23/1997 | 2 | IDT | | Y | IDT7134LA70CB | 618 |
| 5962-8976402MYA | A | 10/23/1997 | 2 | IDT | | Y | IDT7134LA70L48B | 618 |
| 5962-8976402MZA | A | 10/23/1997 | 3 | IDT | | Y | IDT7134LA70FB | 618 |
| 5962-8976403MXA | A | 10/23/1997 | 2 | IDT | | Y | IDT7134SA55CB | 618 |
| 5962-8976403MYA | A | 10/23/1997 | 2 | IDT | | Y | IDT7134SA55L48B | 618 |
| 5962-8976403MZA | A | 10/23/1997 | 3 | IDT | | Y | IDT7134SA55FB | 618 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-8976404MXA | A | 10/23/1997 | 2 | IDT | | Y | IDT7134LA55CB | 618 |
| 5962-8976404MYA | A | 10/23/1997 | 2 | IDT | | Y | IDT7134LA55L48B | 618 |
| 5962-8976404MZA | A | 10/23/1997 | 3 | IDT | | Y | IDT7134LA55FB | 618 |
| 5962-8976405MXA | A | 10/23/1997 | 2 | IDT | | Y | IDT7134SA45CB | 618 |
| 5962-8976405MYA | A | 10/23/1997 | 2 | IDT | | Y | IDT7134SA45L48B | 618 |
| 5962-8976405MZA | A | 10/23/1997 | 3 | IDT | | Y | IDT7134SA45FB | 618 |
| 5962-8976406MXA | A | 10/23/1997 | 2 | IDT | | Y | IDT7134LA45CB | 618 |
| 5962-8976406MYA | A | 10/23/1997 | 2 | IDT | | Y | IDT7134LA45L48B | 618 |
| 5962-8976406MZA | A | 10/23/1997 | 3 | IDT | | Y | IDT7134LA45FB | 618 |
| 5962-8976407MXA | A | 10/23/1997 | 2 | IDT | | Y | IDT7134SA35CB | 618 |
| 5962-8976407MYA | A | 10/23/1997 | 2 | IDT | | Y | IDT7134SA35L48B | 618 |
| 5962-8976407MZA | A | 10/23/1997 | 3 | IDT | | Y | IDT7134SA35FB | 618 |
| 5962-8976408MXA | A | 10/23/1997 | 2 | IDT | | Y | IDT7134LA35CB | 618 |
| 5962-8976408MYA | A | 10/23/1997 | 2 | IDT | | Y | IDT7134LA35L48B | 618 |
| 5962-8976408MZA | A | 10/23/1997 | 3 | IDT | | Y | IDT7134LA35FB | 618 |
| 5962-8976501EA | C | 01/25/2002 | 1 | TI | | Y | CD54HC283F3A | 202 |
| 5962-8976501FA | C | 01/25/2002 | | (NONE) | | | 54HC283 (GEN) | 202 |
| 5962-8976501VFA | C | 01/25/2002 | | (NONE) | | | 54HC283 (GEN) | 202 |
| 5962-8976501VXA | C | 01/25/2002 | 2 | STMICRO | | Y | 54HC283K02V | 202 |
| 5962-8976501VXC | C | 01/25/2002 | 2 | STMICRO | | Y | 54HC283K01V | 202 |
| 5962-8976501XA | C | 01/25/2002 | 2 | STMICRO | | Y | 54HC283K02Q | 202 |
| 5962-8976501XC | C | 01/25/2002 | 2 | STMICRO | | Y | 54HC283K01Q | 202 |
| 5962-89766012A | | 09/14/1989 | | IDT | | Y | IDT54FCT541LB | 529 |
| 5962-89766012A | | 09/14/1989 | 2 | NATIONAL | | Y | 54FCT541LMQB | 529 |
| 5962-8976601RA | | 09/14/1989 | | IDT | | Y | IDT54FCT541DB | 529 |
| 5962-8976601RA | | 09/14/1989 | 2 | NATIONAL | | Y | 54FCT541DMQB | 529 |
| 5962-8976601SA | | 09/14/1989 | | IDT | | Y | IDT54FCT541EB | 529 |
| 5962-89766022A | | 09/14/1989 | | IDT | | Y | IDT54FCT541ALB | 529 |
| 5962-8976602RA | | 09/14/1989 | | IDT | | Y | IDT54FCT541ADB | 529 |
| 5962-8976602SA | | 09/14/1989 | | (NONE) | 04/29/2002 | | 54FCT541A (GEN) | 529 |
| 5962-89767012A | | 09/12/1989 | 2 | NATIONAL | | Y | 54FCT540LMQB | 529 |
| 5962-8976701RA | | 09/12/1989 | 2 | NATIONAL | | Y | 54FCT540DMQB | 529 |
| 5962-8976701SA | | 09/12/1989 | | (NONE) | | | 54FCT540 (GEN) | 529 |
| 5962-89767022A | | 09/12/1989 | | (NONE) | 09/01/1996 | | 54FCT540A (GEN) | 529 |
| 5962-8976702RA | | 09/12/1989 | | (NONE) | 09/01/1996 | | 54FCT540A (GEN) | 529 |
| 5962-8976702SA | | 09/12/1989 | | (NONE) | 09/01/1996 | | 54FCT540A (GEN) | 529 |
| 5962-8976901RA | | 08/27/1990 | 1 | TI | | Y | CD54HCT377F3A | 159 |
| 5962-8977101EA | | 10/02/1990 | 1 | TI | | Y | CD54HCT4060F3A | 305 |
| 5962-8977201MZA | | 08/04/1992 | | (NONE) | 04/30/1996 | | 8397BH (GEN) | 420 |
| 5962-89775012A | | 02/11/1991 | | (NONE) | | | EP2015 (GEN) | 790 |
| 5962-8977501CA | | 02/11/1991 | | (NONE) | | | EP2015 (GEN) | 790 |
| 5962-89775022A | | 02/11/1991 | | (NONE) | | | EP2015A (GEN) | 790 |
| 5962-8977502CA | | 02/11/1991 | | (NONE) | | | EP2015A (GEN) | 790 |
| 5962-89776012A | A | 07/15/1993 | | (NONE) | | | EN2016 (GEN) | 790 |
| 5962-8977601CA | A | 07/15/1993 | | (NONE) | | | EN2016 (GEN) | 790 |
| 5962-89776022A | A | 07/15/1993 | | (NONE) | | | EN2016A (GEN) | 790 |
| 5962-8977602CA | A | 07/15/1993 | | (NONE) | | | EN2016A (GEN) | 790 |
| 5962-89777013A | B | 04/19/1993 | | (NONE) | 06/30/1995 | | 7684T (GEN) | 592 |
| 5962-8977701XA | B | 04/19/1993 | | (NONE) | 12/30/1995 | | 7684T (GEN) | 592 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-89777023A | B | 04/19/1993 | | (NONE) | 06/30/1995 | | 7684S (GEN) | 592 |
| 5962-8977702XA | B | 04/19/1993 | | (NONE) | 12/30/1995 | | 7684S (GEN) | 592 |
| 5962-89777033A | B | 04/19/1993 | | (NONE) | 06/30/1995 | | 7684AT (GEN) | 592 |
| 5962-8977703XA | B | 04/19/1993 | | (NONE) | 12/30/1995 | | 7684AT (GEN) | 592 |
| 5962-89777043A | B | 04/19/1993 | | (NONE) | 06/30/1995 | | 7684AS (GEN) | 592 |
| 5962-8977704XA | B | 04/19/1993 | | (NONE) | 12/30/1995 | | 7684AS (GEN) | 592 |
| 5962-8977705LA | B | 04/19/1993 | | (NONE) | 12/30/1995 | | 7690AT (GEN) | 592 |
| 5962-8977706LA | B | 04/19/1993 | | (NONE) | 12/30/1995 | | 7690AS (GEN) | 592 |
| 5962-89778012A | | 03/24/1992 | | (NONE) | 09/30/1995 | | 1648 (GEN) | 815 |
| 5962-8977801CA | | 03/24/1992 | | (NONE) | 09/30/1995 | | 1648 (GEN) | 815 |
| 5962-8977801DA | | 03/24/1992 | | (NONE) | 09/30/1995 | | 1648 (GEN) | 815 |
| 5962-8978001PA | | 10/31/1989 | | (NONE) | 09/30/1995 | | 3523 (GEN) | 899 |
| 5962-8978201CA | | 11/22/1989 | | (NONE) | 03/30/2001 | | LTC1052 (GEN) | 738 |
| 5962-8978201GA | | 11/22/1989 | | (NONE) | 03/30/2001 | | LTC1052 (GEN) | 738 |
| 5962-8978201PA | | 11/22/1989 | | (NONE) | 03/30/2001 | | LTC1052 (GEN) | 738 |
| 5962-89783012A | A | 03/08/2001 | | (NONE) | 04/16/2002 | | OP290A (GEN) | 710 |
| 5962-8978301PA | A | 03/08/2001 | | (NONE) | 04/16/2002 | | OP290A (GEN) | 710 |
| 5962-8978501PA | G | 11/07/1997 | 3 | AGILENT | | Y | HCPL-5731#200 | 460 |
| 5962-8978501PA | G | 11/07/1997 | 1 | MICROPAC | | Y | 66058-003 | 460 |
| 5962-8978501PC | G | 11/07/1997 | 3 | AGILENT | | Y | HCPL-5731 | 460 |
| 5962-8978501PC | G | 11/07/1997 | 1 | MICROPAC | | Y | 66058-003 | 460 |
| 5962-8978501XA | G | 11/07/1997 | 1 | MICROPAC | | Y | 66071-001 | 460 |
| 5962-8978501XC | G | 11/07/1997 | 1 | MICROPAC | | Y | 66071-001 | 460 |
| 5962-8978501YA | G | 11/07/1997 | 3 | AGILENT | | Y | HCPL-5731#100 | 460 |
| 5962-8978501YC | G | 11/07/1997 | 3 | AGILENT | | Y | HCPL-5731#100 | 460 |
| 5962-8978501ZA | G | 11/07/1997 | 3 | AGILENT | | Y | HCPL-5731#300 | 460 |
| 5962-89785022A | G | 11/07/1997 | 2 | AGILENT | | Y | HCPL-6731 | 460 |
| 5962-89785022A | G | 11/07/1997 | 1 | MICROPAC | | Y | 66124-001 | 460 |
| 5962-89785022C | G | 11/07/1997 | 1 | MICROPAC | | Y | 66124-001 | 460 |
| 5962-8978503KPA | G | 11/07/1997 | 3 | AGILENT | | Y | HCPL-573K#200 | 460 |
| 5962-8978503KPA | G | 11/07/1997 | 1 | MICROPAC | | Y | 66058-300 | 460 |
| 5962-8978503KPC | G | 11/07/1997 | 3 | AGILENT | | Y | HCPL-573K | 460 |
| 5962-8978503KPC | G | 11/07/1997 | 1 | MICROPAC | | Y | 66058-300 | 460 |
| 5962-8978503KYA | G | 11/07/1997 | 3 | AGILENT | | Y | HCPL-573K#100 | 460 |
| 5962-8978503KYC | G | 11/07/1997 | 3 | AGILENT | | Y | HCPL-573K#100 | 460 |
| 5962-8978503KZA | G | 11/07/1997 | 3 | AGILENT | | Y | HCPL-573K#300 | 460 |
| 5962-8978504K2A | G | 11/07/1997 | 3 | AGILENT | | Y | HCPL-673K | 460 |
| 5962-8978504K2A | G | 11/07/1997 | 1 | MICROPAC | | Y | 66124-300 | 460 |
| 5962-8978504K2C | G | 11/07/1997 | 1 | MICROPAC | | Y | 66124-300 | 460 |
| 5962-8978505KXA | G | 11/07/1997 | 1 | MICROPAC | | Y | 66071-300 | 460 |
| 5962-8978505KXC | G | 11/07/1997 | 1 | MICROPAC | | Y | 66071-300 | 460 |
| 5962-8978701MEA | A | 01/08/2002 | 1 | NATIONAL | 03/08/2005 | Y | DS9627MJ/883 | 570 |
| 5962-89790013A | | 12/21/1992 | | (NONE) | 06/01/1996 | | 71682LA20 (GEN) | 616 |
| 5962-8979001KA | | 12/21/1992 | | (NONE) | 06/01/1996 | | 71682LA20 (GEN) | 616 |
| 5962-8979001LA | | 12/21/1992 | | (NONE) | 06/01/1996 | | 71682LA20 (GEN) | 616 |
| 5962-89790023A | | 12/21/1992 | | (NONE) | | | 7C172A-20 (GEN) | 616 |
| 5962-8979002KA | | 12/21/1992 | | (NONE) | | | 7C172A-20 (GEN) | 616 |
| 5962-8979002LA | | 12/21/1992 | | (NONE) | 03/31/1998 | | 7C172A-20 (GEN) | 616 |
| 5962-89790033A | | 12/21/1992 | | (NONE) | 06/01/1996 | | 71682LA15 (GEN) | 616 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-8979003KA | | 12/21/1992 | | (NONE) | 06/01/1996 | | 71682LA15 (GEN) | 616 |
| 5962-8979003LA | | 12/21/1992 | | (NONE) | 06/01/1996 | | 71682LA15 (GEN) | 616 |
| 5962-89790043A | | 12/21/1992 | | (NONE) | 06/01/1996 | | 71682SA15 (GEN) | 616 |
| 5962-8979004KA | | 12/21/1992 | | (NONE) | 06/01/1996 | | 71682SA15 (GEN) | 616 |
| 5962-8979004LA | | 12/21/1992 | | (NONE) | 06/01/1996 | | 71682SA15 (GEN) | 616 |
| 5962-8979101QXA | A | 12/11/2001 | 2 | STMICRO | | Y | 54ACT02K02Q | 120 |
| 5962-8979101QXC | A | 12/11/2001 | 2 | STMICRO | | Y | 54ACT02K01Q | 120 |
| 5962-8979101VXA | A | 12/11/2001 | 2 | STMICRO | | Y | 54ACT02K02V | 120 |
| 5962-8979101VXC | A | 12/11/2001 | 2 | STMICRO | | Y | 54ACT02K01V | 120 |
| 5962-89793012A | A | 02/26/1991 | 3 | NATIONAL | | Y | 54ACT520LMQB | 209 |
| 5962-8979301RA | A | 02/26/1991 | 3 | NATIONAL | | Y | 54ACT520DMQB | 209 |
| 5962-8979301SA | A | 02/26/1991 | 3 | NATIONAL | | Y | 54ACT520FMQB | 209 |
| 5962-89793022A | A | 02/26/1991 | 3 | NATIONAL | | Y | 54ACT521LMQB | 209 |
| 5962-8979302RA | A | 02/26/1991 | 3 | NATIONAL | | Y | 54ACT521DMQB | 209 |
| 5962-8979302SA | A | 02/26/1991 | 3 | NATIONAL | | Y | 54ACT521FMQB | 209 |
| 5962-89793032A | A | 02/26/1991 | | (NONE) | 09/15/1995 | | 54ACT11520 (GEN) | 209 |
| 5962-8979303RA | A | 02/26/1991 | | (NONE) | 09/15/1995 | | 54ACT11520 (GEN) | 209 |
| 5962-89793042A | A | 02/26/1991 | 1 | ROCHESTER | | | 54ACT11521/B2A | 209 |
| 5962-8979304RA | A | 02/26/1991 | 1 | ROCHESTER | | | 54ACT11521/BRA | 209 |
| 5962-8979501QXA | | 07/25/2001 | 2 | STMICRO | | Y | 54ACT541K02Q | 529 |
| 5962-8979501QXC | | 07/25/2001 | 2 | STMICRO | | Y | 54ACT541K01Q | 529 |
| 5962-8979501VXA | | 07/25/2001 | 2 | STMICRO | | Y | 54ACT541K02V | 529 |
| 5962-8979501VXC | | 07/25/2001 | 2 | STMICRO | | Y | 54ACT541K01V | 529 |
| 5962-8979801XC | F | 05/24/2002 | | (NONE) | 11/30/2001 | | BUS-65142 (GEN) | 590 |
| 5962-8979801YA | F | 05/24/2002 | | (NONE) | 11/30/2001 | | BUS-65144 (GEN) | 590 |
| 5962-8979802XA | F | 05/24/2002 | | (NONE) | 11/30/2001 | | BUS-65143 (GEN) | 590 |
| 5962-8979802YA | F | 05/24/2002 | | (NONE) | 11/30/2001 | | BUS-65145 (GEN) | 590 |
| 5962-8979803XA | F | 05/24/2002 | 1 | AEROFLEX | | Y | CT2542 | 590 |
| 5962-8979803XC | F | 05/24/2002 | 1 | AEROFLEX | | Y | CT2542 | 590 |
| 5962-8979803YA | F | 05/24/2002 | 1 | AEROFLEX | | Y | CT2542-FP | 590 |
| 5962-8979803YC | F | 05/24/2002 | 1 | AEROFLEX | | Y | CT2542-FP | 590 |
| 5962-8979804XA | F | 05/24/2002 | 1 | AEROFLEX | | Y | CT2543 | 590 |
| 5962-8979804XC | F | 05/24/2002 | 1 | AEROFLEX | | Y | CT2543 | 590 |
| 5962-8979804YA | F | 05/24/2002 | 1 | AEROFLEX | | Y | CT2543-FP | 590 |
| 5962-8979804YC | F | 05/24/2002 | 1 | AEROFLEX | | Y | CT2543-FP | 590 |
| 5962-8979805TA | F | 05/24/2002 | | (NONE) | | | BU-65142 (GEN) | 590 |
| 5962-8979805ZA | F | 05/24/2002 | | (NONE) | | | BU-65142 (GEN) | 590 |
| 5962-8979806TA | F | 05/24/2002 | | (NONE) | | | BU-65142 (GEN) | 590 |
| 5962-8979806ZA | F | 05/24/2002 | | (NONE) | | | BU-65142 (GEN) | 590 |
| 5962-8979807TA | F | 05/24/2002 | | (NONE) | | | BU-65142 (GEN) | 590 |
| 5962-8979807ZA | F | 05/24/2002 | | (NONE) | | | BU-65142 (GEN) | 590 |
| 5962-8979901XA | A | 02/10/1992 | 1 | CMAC MICRO. | | Y | FC155391 | 590 |
| 5962-8979901XC | A | 02/10/1992 | 1 | CMAC MICRO. | | Y | FC155391 | 590 |
| 5962-8979902XA | A | 02/10/1992 | 1 | CMAC MICRO. | | Y | FC155392 | 590 |
| 5962-8979902XC | A | 02/10/1992 | 1 | CMAC MICRO. | | Y | FC155392 | 590 |
| 5962-89801012A | C | 04/16/2001 | | ANALOG (5) | | Y | OP-11ARC | 713 |
| 5962-8980101V2A | C | 04/16/2001 | | (NONE) | | | OP11A (GEN) | 713 |
| 5962-8980101CA | C | 04/16/2001 | | ANALOG (5) | | Y | OP-11AY | 713 |
| 5962-8980101VCA | C | 04/16/2001 | 1 | ANALOG (5) | | Y | OP11AM/QMLV | 713 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-8980101VCA | C | 04/16/2001 | 1 | ANALOG (5) | | Y | OP11AY/QMLV | 713 |
| 5962-89801022A | C | 04/16/2001 | | (NONE) | 04/14/2001 | | OP-11B (GEN) | 713 |
| 5962-8980102CA | C | 04/16/2001 | | ANALOG (5) | | Y | OP-11BY | 713 |
| 5962-89801032A | C | 04/16/2001 | 1 | ANALOG (5) | | Y | OP-11ARC | 713 |
| 5962-8980103CA | C | 04/16/2001 | 1 | ANALOG (5) | | Y | OP-11AY | 713 |
| 5962-8980201XA | A | 05/06/2004 | 1 | LINEAR TECH. | | Y | LT1031-BMH/883B | 785 |
| 5962-8980202XA | A | 05/06/2004 | 1 | LINEAR TECH. | | Y | LT1031-CMH/883B | 785 |
| 5962-8980202XA | A | 05/06/2004 | 1 | MINCO | | Y | MTL1031CMH | 785 |
| 5962-8980203XA | A | 05/06/2004 | 1 | LINEAR TECH. | | Y | LT1031-DMH/883B | 785 |
| 5962-8980301XA | | 10/05/1990 | | (NONE) | 06/30/1996 | | SL523AC (GEN) | 800 |
| 5962-89804012A | C | 03/27/2001 | | (NONE) | | | OP44A (GEN) | 702 |
| 5962-8980401GA | C | 03/27/2001 | | (NONE) | | | OP44A (GEN) | 702 |
| 5962-8980401PA | C | 03/27/2001 | | (NONE) | | | OP44A (GEN) | 702 |
| 5962-89805012A | A | 01/08/2002 | 1 | ANALOG (2) | | Y | AD536ASE/883B | 594 |
| 5962-89805012C | A | 01/08/2002 | 1 | MAXIM INTEG. | | | MX536ASE/883B | 594 |
| 5962-8980501CA | A | 01/08/2002 | 1 | ANALOG (2) | | Y | AD536ASD/883B | 594 |
| 5962-8980501CA | A | 01/08/2002 | 1 | MAXIM INTEG. | | | MX536ASQ/883B | 594 |
| 5962-8980501CC | A | 01/08/2002 | 1 | MAXIM INTEG. | | | MX536ASD/883B | 594 |
| 5962-8980501IA | A | 01/08/2002 | 1 | ANALOG (2) | | Y | AD536ASH/883B | 594 |
| 5962-8980501IC | A | 01/08/2002 | 1 | MAXIM INTEG. | | | MX536ASH/883B | 594 |
| 5962-89807012A | A | 03/27/2001 | 1 | ANALOG (2) | | Y | AD630SE/883 | 804 |
| 5962-8980701RA | A | 03/27/2001 | 1 | ANALOG (2) | | Y | AD630SD/883 | 804 |
| 5962-8980801JA | B | 03/07/2002 | | (NONE) | | | AD568SQ (GEN) | 591 |
| 5962-8980801LA | B | 03/07/2002 | 1 | ANALOG (2) | | Y | AD568SQ/883B | 591 |
| 5962-89808023A | B | 03/07/2002 | | (NONE) | 04/14/2001 | | AD568SE (GEN) | 591 |
| 5962-89809012A | B | 03/27/2001 | 0 | ANALOG (2) | | Y | AD539SE/883B | 810 |
| 5962-8980901EA | B | 03/27/2001 | 1 | ANALOG (2) | | Y | AD539SD/883B | 810 |
| 5962-8981001PA | F | 08/21/2002 | 2 | AGILENT | | Y | HCPL-5701#200 | 460 |
| 5962-8981001PA | F | 08/21/2002 | 1 | MICROPAC | | Y | 66058-105 | 460 |
| 5962-8981001PC | F | 08/21/2002 | 2 | AGILENT | | Y | HCPL-5701 | 460 |
| 5962-8981001PC | F | 08/21/2002 | 1 | MICROPAC | | Y | 66058-105 | 460 |
| 5962-8981001XA | F | 08/21/2002 | 2 | AGILENT | | Y | HCPL-5701#300 | 460 |
| 5962-8981001YA | F | 08/21/2002 | 2 | AGILENT | | Y | HCPL-5701#100 | 460 |
| 5962-8981001YC | F | 08/21/2002 | 2 | AGILENT | | Y | HCPL-5701#100 | 460 |
| 5962-8981002KPA | F | 08/21/2002 | 2 | AGILENT | | Y | HCPL-570K#200 | 460 |
| 5962-8981002KPA | F | 08/21/2002 | 1 | MICROPAC | | Y | 66058-300 | 460 |
| 5962-8981002KPC | F | 08/21/2002 | 2 | AGILENT | | Y | HCPL-570K | 460 |
| 5962-8981002KPC | F | 08/21/2002 | 1 | MICROPAC | | Y | 66058-300 | 460 |
| 5962-8981002KXA | F | 08/21/2002 | 2 | AGILENT | | Y | HCPL-570K#300 | 460 |
| 5962-8981002KYA | F | 08/21/2002 | 2 | AGILENT | | Y | HCPL-570K#100 | 460 |
| 5962-8981002KYC | F | 08/21/2002 | 2 | AGILENT | | Y | HCPL-570K#100 | 460 |
| 5962-89813013A | B | 02/18/1999 | 1 | SATCON | | Y | HC1437L/883 | 755 |
| 5962-8981301GA | B | 02/18/1999 | 1 | MS KENNEDY | | Y | MSK437B | 755 |
| 5962-8981301GC | B | 02/18/1999 | 1 | MS KENNEDY | | Y | MSK437B | 755 |
| 5962-8981302GA | B | 02/18/1999 | 1 | MS KENNEDY | | Y | MSK438B | 755 |
| 5962-8981302GC | B | 02/18/1999 | 1 | MS KENNEDY | | Y | MSK438B | 755 |
| 5962-89815013A | A | 02/07/2001 | 1 | QP SEMI | | | WS57C45-35ZMB | 658 |
| 5962-89815013C | A | 02/07/2001 | 1 | QP SEMI | | | WS57C45-35ZMB | 658 |
| 5962-8981501KA | A | 02/07/2001 | 1 | QP SEMI | | | WS57C45-35HMB | 658 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-8981501LA | A | 02/07/2001 | 1 | QP SEMI | | | WS57C45-35KMB | 658 |
| 5962-89815023A | A | 02/07/2001 | 1 | QP SEMI | | | WS57C45-25ZMB | 658 |
| 5962-89815023C | A | 02/07/2001 | 1 | QP SEMI | | | WS57C45-25ZMB | 658 |
| 5962-8981502KA | A | 02/07/2001 | 1 | QP SEMI | | | WS57C45-25HMB | 658 |
| 5962-8981502LA | A | 02/07/2001 | 1 | QP SEMI | | | WS57C45-25KMB | 658 |
| 5962-89815033A | A | 02/07/2001 | | (NONE) | 04/10/2001 | | 7C245A-18 (GEN) | 658 |
| 5962-8981503KA | A | 02/07/2001 | 1 | QP SEMI | | Y | 7C245A/KA | 658 |
| 5962-8981503LA | A | 02/07/2001 | | (NONE) | 11/05/2001 | | 7C245A-18 (GEN) | 658 |
| 5962-8981701XA | B | 10/01/1993 | | (NONE) | | | 7C271-55 (GEN) | 662 |
| 5962-8981701YA | B | 10/01/1993 | | (NONE) | 05/30/1999 | | 7C271-55 (GEN) | 662 |
| 5962-8981701ZA | B | 10/01/1993 | | (NONE) | 11/03/2003 | | 7C271-55 (GEN) | 662 |
| 5962-8981702XA | B | 10/01/1993 | 2 | CYPRESS | | Y | CY7C271-45WMB | 662 |
| 5962-8981702YA | B | 10/01/1993 | | (NONE) | 05/31/1998 | | 7C271-45 (GEN) | 662 |
| 5962-8981702ZA | B | 10/01/1993 | 2 | CYPRESS | | Y | CY7C271-45QMB | 662 |
| 5962-8981703XA | B | 10/01/1993 | | (NONE) | 04/10/2001 | | 7C271-35 (GEN) | 662 |
| 5962-8981703YA | B | 10/01/1993 | | (NONE) | 05/30/1999 | | 7C271-35 (GEN) | 662 |
| 5962-8981703ZA | B | 10/01/1993 | | (NONE) | 05/31/1998 | | 7C271-35 (GEN) | 662 |
| 5962-8981704UA | B | 10/01/1993 | | (NONE) | 05/31/1998 | | 7C274-55 (GEN) | 662 |
| 5962-8981704ZA | B | 10/01/1993 | | (NONE) | 11/05/2001 | | 7C274-55 (GEN) | 662 |
| 5962-8981705UA | B | 10/01/1993 | | (NONE) | 04/10/2001 | | 7C274-45 (GEN) | 662 |
| 5962-8981705ZA | B | 10/01/1993 | | (NONE) | 05/31/1998 | | 7C274-45 (GEN) | 662 |
| 5962-8981706UA | B | 10/01/1993 | | (NONE) | | | 7C274-35 (GEN) | 662 |
| 5962-8981706ZA | B | 10/01/1993 | 2 | CYPRESS | | Y | CY7C274-35QMB | 662 |
| 5962-8982101GA | | 01/11/1990 | | (NONE) | 03/09/1999 | | DS1634 (GEN) | 583 |
| 5962-8982101PA | | 01/11/1990 | | (NONE) | 09/09/1998 | | DS1634 (GEN) | 583 |
| 5962-8982301MTC | G | 11/09/2001 | | (NONE) | 01/15/2000 | | 3090-50 (GEN) | 431 |
| 5962-8982301MUA | G | 11/09/2001 | | (NONE) | | | 3090-50 (GEN) | 431 |
| 5962-8982301MXC | G | 11/09/2001 | | (NONE) | 01/15/2000 | | 3090-50 (GEN) | 431 |
| 5962-8982301QXA | G | 11/09/2001 | | (NONE) | | | 3090-50 (GEN) | 431 |
| 5962-8982301XC | G | 11/09/2001 | | (NONE) | 01/15/2000 | | 3090-50 (GEN) | 431 |
| 5962-8982301MYA | G | 11/09/2001 | | (NONE) | | | 3090-50 (GEN) | 431 |
| 5962-8982301YA | G | 11/09/2001 | | (NONE) | 5962-8982301MYA | | 3090-50 (GEN) | 431 |
| 5962-8982301MZC | G | 11/09/2001 | | (NONE) | 01/15/2000 | | 3090-50 (GEN) | 431 |
| 5962-8982301QZA | G | 11/09/2001 | | (NONE) | | | 3090-50 (GEN) | 431 |
| 5962-8982301ZC | G | 11/09/2001 | | (NONE) | 01/15/2000 | | 3090-50 (GEN) | 431 |
| 5962-8982302MTC | G | 11/09/2001 | | (NONE) | 01/15/2000 | | 3090-70 (GEN) | 431 |
| 5962-8982302MUA | G | 11/09/2001 | | (NONE) | | | 3090-70 (GEN) | 431 |
| 5962-8982302MXC | G | 11/09/2001 | | (NONE) | 01/15/2000 | | 3090-70 (GEN) | 431 |
| 5962-8982302QXA | G | 11/09/2001 | | (NONE) | | | 3090-70 (GEN) | 431 |
| 5962-8982302XC | G | 11/09/2001 | | (NONE) | 01/15/2000 | | 3090-70 (GEN) | 431 |
| 5962-8982302MYA | G | 11/09/2001 | | (NONE) | | | 3090-70 (GEN) | 431 |
| 5962-8982302YA | G | 11/09/2001 | | (NONE) | 5962-8982302MYA | | 3090-70 (GEN) | 431 |
| 5962-8982302MZC | G | 11/09/2001 | | (NONE) | 01/15/2000 | | 3090-70 (GEN) | 431 |
| 5962-8982302QZA | G | 11/09/2001 | | (NONE) | | | 3090-70 (GEN) | 431 |
| 5962-8982302ZC | G | 11/09/2001 | | (NONE) | 01/15/2000 | | 3090-70 (GEN) | 431 |
| 5962-8982303MTC | G | 11/09/2001 | 1 | XILINX | | Y | XC3090-100CB164B | 431 |
| 5962-8982303MXC | G | 11/09/2001 | | XILINX | | Y | XC3090-100PG175B | 431 |
| 5962-8982303QXA | G | 11/09/2001 | | (NONE) | | | 3090-100 (GEN) | 431 |
| 5962-8982303MZC | G | 11/09/2001 | | XILINX | | Y | XC3090-100CB164B | 431 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-8982303QZA | G | 11/09/2001 | | (NONE) | | | 3090-100 (GEN) | 431 |
| 5962-8982304QXA | G | 11/09/2001 | | (NONE) | | | 3090-125 (GEN) | 431 |
| 5962-8982304QZA | G | 11/09/2001 | | (NONE) | | | 3090-125 (GEN) | 431 |
| 5962-8982401PA | B | 03/30/2001 | 1 | ANALOG (2) | | Y | AD586SQ/883B | 785 |
| 5962-8982402PA | B | 03/30/2001 | 1 | ANALOG (2) | | Y | AD586TQ/883B | 785 |
| 5962-8982501PA | A | 10/24/2003 | | (NONE) | 04/30/2003 | | AD587S (GEN) | 785 |
| 5962-8982502PA | A | 10/24/2003 | 1 | ANALOG (2) | | Y | AD587TQ/883B | 785 |
| 5962-8982503PA | A | 10/24/2003 | 1 | ANALOG (2) | | Y | AD587UQ/883B | 785 |
| 5962-8982601XA | D | 02/22/1996 | 1 | DDC | | Y | BUS-63127II | 590 |
| 5962-8982601XA | D | 02/22/1996 | 1 | DDC IRELAND | | Y | BUS63127II | 590 |
| 5962-8982601XC | D | 02/22/1996 | 1 | DDC | | Y | BUS-63127II | 590 |
| 5962-8982601XC | D | 02/22/1996 | 1 | DDC IRELAND | | Y | BUS63127II | 590 |
| 5962-8982601YA | D | 02/22/1996 | 1 | DDC | | Y | BUS-63128II | 590 |
| 5962-8982601YA | D | 02/22/1996 | 1 | DDC IRELAND | | Y | BUS63128II | 590 |
| 5962-8982601YC | D | 02/22/1996 | 1 | DDC | | Y | BUS-63128II | 590 |
| 5962-8982601YC | D | 02/22/1996 | 1 | DDC IRELAND | | Y | BUS63128II | 590 |
| 5962-8982602XA | D | 02/22/1996 | 1 | AEROFLEX | | Y | ARX3419 | 590 |
| 5962-8982602XC | D | 02/22/1996 | 1 | AEROFLEX | | Y | ARX3419 | 590 |
| 5962-8982602YA | D | 02/22/1996 | 1 | AEROFLEX | | Y | ARX3419FP | 590 |
| 5962-8982602YC | D | 02/22/1996 | 1 | AEROFLEX | | Y | ARX3419FP | 590 |
| 5962-8982603XA | D | 02/22/1996 | 1 | NATIONAL HYB | | Y | NHI-1502 | 590 |
| 5962-8982603XC | D | 02/22/1996 | 1 | NATIONAL HYB | | Y | NHI-1502 | 590 |
| 5962-8982603YA | D | 02/22/1996 | 1 | NATIONAL HYB | | Y | NHI-1502FP | 590 |
| 5962-8982603YC | D | 02/22/1996 | 1 | NATIONAL HYB | | Y | NHI-1502FP | 590 |
| 5962-8982604XA | D | 02/22/1996 | 1 | NATIONAL HYB | | Y | NHI-1523 | 590 |
| 5962-8982604XC | D | 02/22/1996 | 1 | NATIONAL HYB | | Y | NHI-1523 | 590 |
| 5962-8982604YA | D | 02/22/1996 | 1 | NATIONAL HYB | | Y | NHI-1523FP | 590 |
| 5962-8982604YC | D | 02/22/1996 | 1 | NATIONAL HYB | | Y | NHI-1523FP | 590 |
| 5962-8982605XA | D | 02/22/1996 | 1 | CMAC MICRO. | | Y | FC1553721 | 590 |
| 5962-8982605XC | D | 02/22/1996 | 1 | CMAC MICRO. | | Y | FC1553721 | 590 |
| 5962-8982605YA | D | 02/22/1996 | 1 | CMAC MICRO. | | Y | FC1553721FP | 590 |
| 5962-8982605YC | D | 02/22/1996 | 1 | CMAC MICRO. | | Y | FC1553721FP | 590 |
| 5962-8982606XA | D | 02/22/1996 | | (NONE) | | | CT1589 (GEN) | 590 |
| 5962-8982606YA | D | 02/22/1996 | | (NONE) | | | CT1589 (GEN) | 590 |
| 5962-8982607XA | D | 02/22/1996 | 1 | CMAC MICRO. | | Y | FC1553722 | 590 |
| 5962-8982607XC | D | 02/22/1996 | 1 | CMAC MICRO. | | Y | FC1553722 | 590 |
| 5962-8982607YA | D | 02/22/1996 | 1 | CMAC MICRO. | | Y | FC1553722FP | 590 |
| 5962-8982607YC | D | 02/22/1996 | 1 | CMAC MICRO. | | Y | FC1553722FP | 590 |
| 5962-8982608XA | D | 02/22/1996 | 1 | CMAC MICRO. | | Y | FC1553726 | 590 |
| 5962-8982608XC | D | 02/22/1996 | 1 | CMAC MICRO. | | Y | FC1553726 | 590 |
| 5962-8982608YA | D | 02/22/1996 | 1 | CMAC MICRO. | | Y | FC1553726FP | 590 |
| 5962-8982608YC | D | 02/22/1996 | 1 | CMAC MICRO. | | Y | FC1553726FP | 590 |
| 5962-8982609UA | D | 02/22/1996 | 1 | AEROFLEX | | Y | ACT3433-001-1 | 590 |
| 5962-8982609UC | D | 02/22/1996 | 1 | AEROFLEX | | Y | ACT3433-001-2 | 590 |
| 5962-8982609ZA | D | 02/22/1996 | 1 | AEROFLEX | | Y | ACT3433-201-1 | 590 |
| 5962-8982609ZC | D | 02/22/1996 | 1 | AEROFLEX | | Y | ACT3433-201-2 | 590 |
| 5962-8982610XA | D | 02/22/1996 | 1 | NATIONAL HYB | | Y | NHI-1522/883 | 590 |
| 5962-8982610XC | D | 02/22/1996 | 1 | NATIONAL HYB | | Y | NHI-1522/883 | 590 |
| 5962-8982610YA | D | 02/22/1996 | 1 | NATIONAL HYB | | Y | NHI-1522FP/883 | 590 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-8982610YC | D | 02/22/1996 | 1 | NATIONAL HYB | | Y | NHI-1522FP/883 | 590 |
| 5962-8982801EA | A | 05/18/1992 | | (NONE) | | | TDC1044 (GEN) | 592 |
| 5962-8983001RA | C | 10/15/1993 | | (NONE) | | | LTC1090 (GEN) | 433 |
| 5962-8983002RA | C | 10/15/1993 | | (NONE) | 03/30/2001 | | LTC1290B (GEN) | 433 |
| 5962-8983003RA | C | 10/15/1993 | | (NONE) | 03/30/2001 | | LTC1290C (GEN) | 433 |
| 5962-8983004RA | C | 10/15/1993 | | (NONE) | 03/30/2001 | | LTC1290D (GEN) | 433 |
| 5962-89839012A | E | 08/04/1999 | | (NONE) | 08/04/1995 | | 16V8H25E4 (GEN) | 431 |
| 5962-8983901RA | E | 08/04/1999 | 2 | LATTICE SEMI | | | GAL16V8D-30LD/883C | 431 |
| 5962-89839022A | E | 08/04/1999 | 2 | LATTICE SEMI | | | GAL16V8D-20LR/883C | 431 |
| 5962-8983902RA | E | 08/04/1999 | 2 | LATTICE SEMI | | | GAL16V8D-20LD/883C | 431 |
| 5962-8983902SA | E | 08/04/1999 | | (NONE) | | | 16V8 (GEN) | 431 |
| 5962-89839032A | E | 08/04/1999 | 2 | LATTICE SEMI | | | GAL16V8D-15LR/883C | 431 |
| 5962-8983903RA | E | 08/04/1999 | 2 | LATTICE SEMI | | | GAL16V8D-15LD/883C | 431 |
| 5962-8983903SA | E | 08/04/1999 | | (NONE) | | | 16V8 (GEN) | 431 |
| 5962-89839042A | E | 08/04/1999 | 2 | LATTICE SEMI | | | GAL16V8D-10LR/883C | 431 |
| 5962-8983904RA | E | 08/04/1999 | 2 | LATTICE SEMI | | | GAL16V8D-10LD/883C | 431 |
| 5962-89839052A | E | 08/04/1999 | | (NONE) | | | 16V8 (GEN) | 431 |
| 5962-8983905RA | E | 08/04/1999 | | (NONE) | | | 16V8 (GEN) | 431 |
| 5962-89839062A | E | 08/04/1999 | | (NONE) | | | 16V8 (GEN) | 431 |
| 5962-8983906RA | E | 08/04/1999 | | (NONE) | | | 16V8 (GEN) | 431 |
| 5962-89839072A | E | 08/04/1999 | 2 | LATTICE SEMI | | | GAL16V8D-7LR/883 | 431 |
| 5962-8983907RA | E | 08/04/1999 | 2 | LATTICE SEMI | | | GAL16V8D-7LD/883 | 431 |
| 5962-89839082A | E | 08/04/1999 | | (NONE) | | | 16V8L25 (GEN) | 431 |
| 5962-8983908RA | E | 08/04/1999 | | (NONE) | | | 16V8L25 (GEN) | 431 |
| 5962-89839092A | E | 08/04/1999 | | (NONE) | | | 16V815 (GEN) | 431 |
| 5962-8983909RA | E | 08/04/1999 | | (NONE) | | | 16V815 (GEN) | 431 |
| 5962-89839102A | E | 08/04/1999 | | (NONE) | | | 16V8L15 (GEN) | 431 |
| 5962-8983910RA | E | 08/04/1999 | | (NONE) | | | 16V8L15 (GEN) | 431 |
| 5962-89839112A | E | 08/04/1999 | | (NONE) | 04/10/2001 | | 16V8-10 (GEN) | 431 |
| 5962-8983911RA | E | 08/04/1999 | | (NONE) | 04/10/2001 | | 16V8-10 (GEN) | 431 |
| 5962-89839122A | E | 08/04/1999 | | (NONE) | 04/10/2001 | | 16V8L-25 (GEN) | 431 |
| 5962-8983912RA | E | 08/04/1999 | | (NONE) | 04/10/2001 | | 16V8L-25 (GEN) | 431 |
| 5962-89839132A | E | 08/04/1999 | 2 | CYPRESS | 05/03/2004 | Y | PALCE16V8-15LMB | 431 |
| 5962-8983913RA | E | 08/04/1999 | 2 | CYPRESS | 05/03/2004 | Y | PALCE16V8-15DMB | 431 |
| 5962-89839142A | E | 08/04/1999 | | (NONE) | 04/10/2001 | | 16V8L-15 (GEN) | 431 |
| 5962-8983914RA | E | 08/04/1999 | | (NONE) | 04/10/2001 | | 16V8L-15 (GEN) | 431 |
| 5962-89840013A | C | 01/27/1994 | | (NONE) | | | 20V8B-30 (GEN) | 431 |
| 5962-8984001LA | C | 01/27/1994 | | (NONE) | | | 20V8B-30 (GEN) | 431 |
| 5962-89840023A | C | 01/27/1994 | 2 | LATTICE SEMI | | | GAL20V8B-20LR/883C | 431 |
| 5962-8984002LA | C | 01/27/1994 | 1 | LATTICE SEMI | | | GAL20V8B-20LD/883C | 431 |
| 5962-89840033A | C | 01/27/1994 | 2 | LATTICE SEMI | | | GAL20V8B-15LR/883C | 431 |
| 5962-8984003LA | C | 01/27/1994 | 2 | LATTICE SEMI | | | GAL20V8B-15LD/883C | 431 |
| 5962-89840043A | C | 01/27/1994 | 2 | LATTICE SEMI | | | GAL20V8B-10LR/883C | 431 |
| 5962-8984004LA | C | 01/27/1994 | 2 | LATTICE SEMI | | | GAL20V8B-10LD/883C | 431 |
| 5962-89841013A | J | 10/10/2002 | 3 | QP SEMI | | Y | QPC22V10-30/B3A | 431 |
| 5962-8984101KA | J | 10/10/2002 | 3 | QP SEMI | | Y | QPC22V10-30/BKA | 431 |
| 5962-8984101LA | J | 10/10/2002 | 2 | LATTICE SEMI | | | GAL22V10C-30LD/883 | 431 |
| 5962-8984101LA | J | 10/10/2002 | 2 | LATTICE SEMI | | | GAL22V10D-30LD/883 | 431 |
| 5962-8984101LA | J | 10/10/2002 | 3 | QP SEMI | | Y | QPC22V10-30/BLA | 431 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-89841023A | J | 10/10/2002 | 2 | LATTICE SEMI | | | GAL22V10C-20LR/883 | 431 |
| 5962-89841023A | J | 10/10/2002 | 2 | LATTICE SEMI | | | GAL22V10D-20LR/883 | 431 |
| 5962-89841023A | J | 10/10/2002 | 3 | QP SEMI | | Y | QPC22V10-20/B3A | 431 |
| 5962-8984102KA | J | 10/10/2002 | 3 | CYPRESS | 05/03/2004 | Y | PALC22V10D-20KMB | 431 |
| 5962-8984102KA | J | 10/10/2002 | 3 | CYPRESS | 05/03/2004 | Y | PALCE22V10-20KMB | 431 |
| 5962-8984102KA | J | 10/10/2002 | 3 | QP SEMI | | Y | QPC22V10-20/BKA | 431 |
| 5962-8984102LA | J | 10/10/2002 | 3 | CYPRESS | 05/03/2004 | Y | PALCE22V10-20DMB | 431 |
| 5962-8984102LA | J | 10/10/2002 | 3 | CYPRESS | 05/03/2004 | Y | PALC22V10D-20DMB | 431 |
| 5962-8984102LA | J | 10/10/2002 | 2 | LATTICE SEMI | | | GAL22V10D-20LD/883 | 431 |
| 5962-8984102LA | J | 10/10/2002 | 2 | LATTICE SEMI | | | GAL22V10C-20LD/883 | 431 |
| 5962-8984102LA | J | 10/10/2002 | 3 | QP SEMI | | Y | QPC22V10-20/BLA | 431 |
| 5962-89841033A | J | 10/10/2002 | 1 | ATMEL | | | ATF22V10B-15NM/883 | 431 |
| 5962-89841033A | J | 10/10/2002 | 3 | CYPRESS | 05/03/2004 | Y | PALC22V10D-15LMB | 431 |
| 5962-89841033A | J | 10/10/2002 | 3 | CYPRESS | 05/03/2004 | Y | PALCE22V10-15LMB | 431 |
| 5962-89841033A | J | 10/10/2002 | 2 | LATTICE SEMI | | | GAL22V10D-15LR/883 | 431 |
| 5962-89841033A | J | 10/10/2002 | 2 | LATTICE SEMI | | | GAL22V10C-15LR/883 | 431 |
| 5962-89841033A | J | 10/10/2002 | 3 | QP SEMI | | Y | QPC22V10-15/B3A | 431 |
| 5962-8984103KA | J | 10/10/2002 | 3 | QP SEMI | | Y | QPC22V10-15/BKA | 431 |
| 5962-8984103LA | J | 10/10/2002 | 1 | ATMEL | | | ATF22V10B-15GM/883 | 431 |
| 5962-8984103LA | J | 10/10/2002 | 3 | CYPRESS | 05/03/2004 | Y | PALCE22V10-15DMB | 431 |
| 5962-8984103LA | J | 10/10/2002 | 3 | CYPRESS | 05/03/2004 | Y | PALC22V10D-15DMB | 431 |
| 5962-8984103LA | J | 10/10/2002 | 2 | LATTICE SEMI | | | GAL22V10D-15LD/883 | 431 |
| 5962-8984103LA | J | 10/10/2002 | 2 | LATTICE SEMI | | | GAL22V10C-15LD/883 | 431 |
| 5962-8984103LA | J | 10/10/2002 | 3 | QP SEMI | | Y | QPC22V10-15/BLA | 431 |
| 5962-8984103LC | J | 10/10/2002 | 2 | DPA LABS | | | DPA22V10-15LC | 431 |
| 5962-89841043A | J | 10/10/2002 | 3 | CYPRESS | 05/03/2004 | Y | PALCE22V10-25LMB | 431 |
| 5962-89841043A | J | 10/10/2002 | 3 | CYPRESS | 05/03/2004 | Y | PALC22V10D-25LMB | 431 |
| 5962-89841043A | J | 10/10/2002 | 3 | QP SEMI | | Y | QPC22V10-25/B3A | 431 |
| 5962-8984104KA | J | 10/10/2002 | 3 | QP SEMI | | Y | QPC22V10-25/BKA | 431 |
| 5962-8984104LA | J | 10/10/2002 | 2 | LATTICE SEMI | | | GAL22V10D-25LD/883 | 431 |
| 5962-8984104LA | J | 10/10/2002 | 2 | LATTICE SEMI | | | GAL22V10C-25LD/883 | 431 |
| 5962-8984104LA | J | 10/10/2002 | 3 | QP SEMI | | Y | QPC22V10-25/BLA | 431 |
| 5962-89841053A | J | 10/10/2002 | 1 | ATMEL | | | ATF22V10B-15NM/883 | 431 |
| 5962-89841053A | J | 10/10/2002 | 3 | QP SEMI | | Y | QPC22V10-15/B3A | 431 |
| 5962-8984105KA | J | 10/10/2002 | 3 | QP SEMI | | Y | QPC22V10-15/BKA | 431 |
| 5962-8984105LA | J | 10/10/2002 | 1 | ATMEL | | | ATF22V10B-15GM/883 | 431 |
| 5962-8984105LA | J | 10/10/2002 | 3 | CYPRESS | 05/03/2004 | Y | PALC22V10D-15DMB | 431 |
| 5962-8984105LA | J | 10/10/2002 | 3 | CYPRESS | 05/03/2004 | Y | PALCE22V10-15DMB | 431 |
| 5962-8984105LA | J | 10/10/2002 | 3 | QP SEMI | | Y | QPC22V10-15/BLA | 431 |
| 5962-89841063A | J | 10/10/2002 | 1 | ATMEL | | | ATF22V10B-10NM/883 | 431 |
| 5962-89841063A | J | 10/10/2002 | 3 | CYPRESS | 05/03/2004 | Y | PALCE22V10-10LMB | 431 |
| 5962-89841063A | J | 10/10/2002 | 3 | CYPRESS | 05/03/2004 | Y | PALC22V10D-10LMB | 431 |
| 5962-89841063A | J | 10/10/2002 | 2 | LATTICE SEMI | | | GAL22V10C-10LR/883 | 431 |
| 5962-89841063A | J | 10/10/2002 | 2 | LATTICE SEMI | | | GAL22V10D-10LR/883 | 431 |
| 5962-89841063A | J | 10/10/2002 | 3 | QP SEMI | | Y | QPC22V10-10/B3A | 431 |
| 5962-8984106KA | J | 10/10/2002 | 3 | CYPRESS | 05/03/2004 | Y | PALCE22V10-10KMB | 431 |
| 5962-8984106KA | J | 10/10/2002 | 3 | CYPRESS | 05/03/2004 | Y | PALC22V10D-10KMB | 431 |
| 5962-8984106KA | J | 10/10/2002 | 3 | QP SEMI | | Y | QPC22V10-10/BKA | 431 |
| 5962-8984106LA | J | 10/10/2002 | 1 | ATMEL | | | ATF22V10B-10GM/883 | 431 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-8984106LA | J | 10/10/2002 | 3 | CYPRESS | 05/03/2004 | Y | PALCE22V10-10DMB | 431 |
| 5962-8984106LA | J | 10/10/2002 | 3 | CYPRESS | 05/03/2004 | Y | PALC22V10D-10DMB | 431 |
| 5962-8984106LA | J | 10/10/2002 | 2 | LATTICE SEMI | | | GAL22V10D-10LD/883 | 431 |
| 5962-8984106LA | J | 10/10/2002 | 2 | LATTICE SEMI | | | GAL22V10C-10LD/883 | 431 |
| 5962-8984106LA | J | 10/10/2002 | 3 | QP SEMI | | Y | QPC22V10-10/BLA | 431 |
| 5962-89841073A | J | 10/10/2002 | 3 | QP SEMI | | Y | QPC22V10-30/B3A | 431 |
| 5962-8984107KA | J | 10/10/2002 | 3 | QP SEMI | | Y | QPC22V10-30/BKA | 431 |
| 5962-8984107LA | J | 10/10/2002 | 3 | QP SEMI | | Y | QPC22V10-30/BLA | 431 |
| 5962-89841083A | J | 10/10/2002 | 3 | CYPRESS | | Y | PALCE22V10-20LMB | 431 |
| 5962-89841083A | J | 10/10/2002 | 3 | CYPRESS | | Y | PALC22V10D-20LMB | 431 |
| 5962-89841083A | J | 10/10/2002 | 3 | QP SEMI | | Y | QPC22V10-20/B3A | 431 |
| 5962-8984108KA | J | 10/10/2002 | 3 | CYPRESS | | Y | PALCE22V10-20KMB | 431 |
| 5962-8984108KA | J | 10/10/2002 | 3 | CYPRESS | | Y | PALC22V10D-20KMB | 431 |
| 5962-8984108KA | J | 10/10/2002 | 3 | QP SEMI | | Y | QPC22V10-20/BKA | 431 |
| 5962-8984108LA | J | 10/10/2002 | 3 | CYPRESS | | Y | PALCE22V10-20DMB | 431 |
| 5962-8984108LA | J | 10/10/2002 | 3 | CYPRESS | | Y | PALC22V10D-20DMB | 431 |
| 5962-8984108LA | J | 10/10/2002 | 3 | QP SEMI | | Y | QPC22V10-20/BLA | 431 |
| 5962-89841093A | J | 10/10/2002 | 3 | QP SEMI | | Y | QPC22V10-15/B3A | 431 |
| 5962-8984109KA | J | 10/10/2002 | 3 | QP SEMI | | Y | QPC22V10-15/BKA | 431 |
| 5962-8984109LA | J | 10/10/2002 | 3 | QP SEMI | | Y | QPC22V10-15/BLA | 431 |
| 5962-89841103A | J | 10/10/2002 | 3 | CYPRESS | | Y | PALC22V10D-25LMB | 431 |
| 5962-89841103A | J | 10/10/2002 | 3 | CYPRESS | | Y | PALCE22V10-25LMB | 431 |
| 5962-89841103A | J | 10/10/2002 | 3 | QP SEMI | | Y | QPC22V10-25/B3A | 431 |
| 5962-8984110KA | J | 10/10/2002 | 3 | CYPRESS | | Y | PALC22V10D-25KMB | 431 |
| 5962-8984110KA | J | 10/10/2002 | 3 | CYPRESS | | Y | PALCE22V10-25KMB | 431 |
| 5962-8984110KA | J | 10/10/2002 | 3 | QP SEMI | | Y | QPC22V10-25/BKA | 431 |
| 5962-8984110LA | J | 10/10/2002 | 3 | CYPRESS | | Y | PALCE22V10-25DMB | 431 |
| 5962-8984110LA | J | 10/10/2002 | 3 | CYPRESS | | Y | PALC22V10D-25DMB | 431 |
| 5962-8984110LA | J | 10/10/2002 | 3 | QP SEMI | | Y | QPC22V10-25/BLA | 431 |
| 5962-89841113A | J | 10/10/2002 | 3 | QP SEMI | | Y | QPC22V10-15/B3A | 431 |
| 5962-8984111KA | J | 10/10/2002 | 3 | QP SEMI | | Y | QPC22V10-15/BKA | 431 |
| 5962-8984111LA | J | 10/10/2002 | 3 | QP SEMI | | Y | QPC22V10-15/BLA | 431 |
| 5962-89841123A | J | 10/10/2002 | 3 | QP SEMI | | Y | QPC22V10-10/B3A | 431 |
| 5962-8984112KA | J | 10/10/2002 | 3 | QP SEMI | | Y | QPC22V10-10/BKA | 431 |
| 5962-8984112LA | J | 10/10/2002 | 3 | QP SEMI | | Y | QPC22V10-10/BLA | 431 |
| 5962-89841133A | J | 10/10/2002 | | (NONE) | 02/29/2000 | | 22V10-25 (GEN) | 431 |
| 5962-8984113LA | J | 10/10/2002 | | (NONE) | 02/29/2000 | | 22V10-25 (GEN) | 431 |
| 5962-89841143A | J | 10/10/2002 | | (NONE) | 02/29/2000 | | 22V10-20 (GEN) | 431 |
| 5962-8984114LA | J | 10/10/2002 | | (NONE) | 02/29/2000 | | 22V10-20 (GEN) | 431 |
| 5962-8984201GC | | 10/27/1989 | | (NONE) | | | ICL8211 (GEN) | 899 |
| 5962-8984202GC | | 10/27/1989 | | (NONE) | 12/24/2000 | | ICL8212 (GEN) | 899 |
| 5962-8984301CA | | 08/18/1989 | 1 | TI | | Y | CD54HCT10F3A | 102 |
| 5962-8984401CA | | 08/29/1990 | 1 | TI | | Y | CD54HCT86F3A | 140 |
| 5962-8984501CA | C | 02/08/2002 | 2 | TI | | Y | CD54HCT132F3A | 109 |
| 5962-89845022A | C | 02/08/2002 | 2 | TI | | Y | SNJ54HC132FK | 109 |
| 5962-8984502CA | C | 02/08/2002 | 2 | TI | | Y | SNJ54HC132J | 109 |
| 5962-8984502VCA | C | 02/08/2002 | 2 | TI | | Y | SNV54HC132J | 109 |
| 5962-8984502DA | C | 02/08/2002 | 2 | TI | | Y | SNJ54HC132W | 109 |
| 5962-8984502VDA | C | 02/08/2002 | 2 | TI | | Y | SNV54HC132W | 109 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-8984502VXA | C | 02/08/2002 | 2 | STMICRO | | Y | 54HC132K02V | 109 |
| 5962-8984502VXC | C | 02/08/2002 | 2 | STMICRO | | Y | 54HC132K01V | 109 |
| 5962-8984502XA | C | 02/08/2002 | 2 | STMICRO | | Y | 54HC132K02Q | 109 |
| 5962-8984502XC | C | 02/08/2002 | 2 | STMICRO | | Y | 54HC132K01Q | 109 |
| 5962-89847012A | C | 08/16/2002 | 3 | NATIONAL | | Y | 54ACT241LMQB | 529 |
| 5962-89847012A | C | 08/16/2002 | 2 | TI | | Y | SNJ54ACT241FK | 529 |
| 5962-8984701V2A | C | 08/16/2002 | 3 | NATIONAL | | Y | 54ACT241E-QMLV | 529 |
| 5962-8984701RA | C | 08/16/2002 | 3 | NATIONAL | | Y | 54ACT241DMQB | 529 |
| 5962-8984701RA | C | 08/16/2002 | 2 | TI | | Y | SNJ54ACT241J | 529 |
| 5962-8984701VRA | C | 08/16/2002 | 3 | NATIONAL | | Y | 54ACT241J-QMLV | 529 |
| 5962-8984701SA | C | 08/16/2002 | 3 | NATIONAL | | Y | 54ACT241FMQB | 529 |
| 5962-8984701SA | C | 08/16/2002 | 2 | TI | | Y | SNJ54ACT241W | 529 |
| 5962-8984701VSA | C | 08/16/2002 | 3 | NATIONAL | | Y | 54ACT241W-QMLV | 529 |
| 5962-8984701VZA | C | 08/16/2002 | 3 | NATIONAL | | Y | 54ACT241WG-QMLV | 529 |
| 5962-89847023A | C | 08/16/2002 | 1 | ROCHESTER | | Y | 54ACT11241/B3A | 529 |
| 5962-8984702LA | C | 08/16/2002 | 1 | ROCHESTER | | Y | 54ACT11241/BLA | 529 |
| 5962-8984901RA | | 11/02/1989 | | TI | | Y | CD54HCT534F3A | 159 |
| 5962-8985201EA | | 02/26/1993 | 1 | TI | | Y | CD54HCT259F3A | 341 |
| 5962-8985501M3A | A | 06/09/1992 | | (NONE) | | | 7C331-40 (GEN) | 431 |
| 5962-8985501MXA | A | 06/09/1992 | | (NONE) | | | 7C331-40 (GEN) | 431 |
| 5962-8985501MYA | A | 06/09/1992 | | (NONE) | | | 7C331-40 (GEN) | 431 |
| 5962-8985501MZA | A | 06/09/1992 | | (NONE) | | | 7C331-40 (GEN) | 431 |
| 5962-8985502M3A | A | 06/09/1992 | | (NONE) | | | 7C331-30 (GEN) | 431 |
| 5962-8985502MXA | A | 06/09/1992 | | (NONE) | | | 7C331-30 (GEN) | 431 |
| 5962-8985502MYA | A | 06/09/1992 | | (NONE) | | | 7C331-30 (GEN) | 431 |
| 5962-8985502MZA | A | 06/09/1992 | | (NONE) | | | 7C331-30 (GEN) | 431 |
| 5962-8985503M3A | A | 06/09/1992 | | (NONE) | | | 7C331-25 (GEN) | 431 |
| 5962-8985503MXA | A | 06/09/1992 | | (NONE) | 04/10/2001 | | 7C331-25 (GEN) | 431 |
| 5962-8985503MYA | A | 06/09/1992 | | (NONE) | | | 7C331-25 (GEN) | 431 |
| 5962-8985503MZA | A | 06/09/1992 | | (NONE) | | | 7C331-25 (GEN) | 431 |
| 5962-89856012A | B | 08/19/1993 | | (NONE) | 09/30/1995 | | 10H509 (GEN) | 149 |
| 5962-8985601EA | B | 08/19/1993 | | (NONE) | 09/30/1995 | | 10H509 (GEN) | 149 |
| 5962-8985601FA | B | 08/19/1993 | | (NONE) | 09/30/1995 | | 10H509 (GEN) | 149 |
| 5962-89857012A | | 03/22/1993 | | (NONE) | 06/01/1997 | | 54F367 (GEN) | 522 |
| 5962-8985701EA | | 03/22/1993 | | (NONE) | 06/01/1997 | | 54F367 (GEN) | 522 |
| 5962-8985701FA | | 03/22/1993 | | (NONE) | 06/01/1997 | | 54F367 (GEN) | 522 |
| 5962-8985801XA | C | 06/07/2000 | | (NONE) | 09/27/2002 | | CLC206A (GEN) | 755 |
| 5962-8986201XA | | 08/18/1992 | | (NONE) | 09/01/2000 | | HS9378 (GEN) | 591 |
| 5962-8986202XA | | 08/18/1992 | | (NONE) | 09/01/2000 | | HS9378 (GEN) | 591 |
| 5962-8986301UA | | 09/17/1990 | 3 | QP SEMI | | Y | CY7C421-80KMB | 670 |
| 5962-8986301XA | | 09/17/1990 | 3 | QP SEMI | | Y | CY7C420-80DMB | 670 |
| 5962-8986301YA | | 09/17/1990 | 3 | QP SEMI | | Y | CY7C421-80DMB | 670 |
| 5962-8986301ZA | | 09/17/1990 | 3 | QP SEMI | | Y | CY7C421-80LMB | 670 |
| 5962-8986302UA | | 09/17/1990 | 3 | QP SEMI | | Y | CY7C421-65KMB | 670 |
| 5962-8986302XA | | 09/17/1990 | 3 | QP SEMI | | Y | CY7C420-65DMB | 670 |
| 5962-8986302YA | | 09/17/1990 | 3 | QP SEMI | | Y | CY7C421-65DMB | 670 |
| 5962-8986302ZA | | 09/17/1990 | 3 | QP SEMI | | Y | CY7C421-65LMB | 670 |
| 5962-8986303UA | | 09/17/1990 | 3 | QP SEMI | | Y | CY7C421-50KMB | 670 |
| 5962-8986303XA | | 09/17/1990 | 3 | QP SEMI | | Y | CY7C420-50DMB | 670 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-8986303YA | | 09/17/1990 | 0 | IDT | | Y | IDT7201SA50TDB | 670 |
| 5962-8986303YA | | 09/17/1990 | 3 | QP SEMI | | Y | CY7C421-50DMB | 670 |
| 5962-8986303ZA | | 09/17/1990 | 3 | QP SEMI | | Y | CY7C421-50LMB | 670 |
| 5962-8986304UA | | 09/17/1990 | 3 | QP SEMI | | Y | CY7C421-40KMB | 670 |
| 5962-8986304XA | | 09/17/1990 | 3 | QP SEMI | | Y | CY7C420-40DMB | 670 |
| 5962-8986304YA | | 09/17/1990 | 3 | QP SEMI | | Y | CY7C421-40DMB | 670 |
| 5962-8986304ZA | | 09/17/1990 | 3 | QP SEMI | | Y | CY7C421-40LMB | 670 |
| 5962-8986305UA | | 09/17/1990 | 3 | QP SEMI | | Y | CY7C421-30KMB | 670 |
| 5962-8986305XA | | 09/17/1990 | 3 | QP SEMI | | Y | CY7C420-30DMB | 670 |
| 5962-8986305YA | | 09/17/1990 | 2 | CYPRESS | 05/03/2004 | Y | CY7C421-30DMB | 670 |
| 5962-8986305YA | | 09/17/1990 | 0 | IDT | | Y | IDT7201SA30TDB | 670 |
| 5962-8986305YA | | 09/17/1990 | 3 | QP SEMI | | Y | CY7C421-30DMB | 670 |
| 5962-8986305ZA | | 09/17/1990 | 3 | QP SEMI | | Y | CY7C421-30LMB | 670 |
| 5962-8986306UA | | 09/17/1990 | 3 | QP SEMI | | Y | CY7C421-25KMB | 670 |
| 5962-8986306XA | | 09/17/1990 | 3 | QP SEMI | | Y | CY7C420-25DMB | 670 |
| 5962-8986306YA | | 09/17/1990 | 3 | QP SEMI | | Y | CY7C421-25DMB | 670 |
| 5962-8986306ZA | | 09/17/1990 | 3 | QP SEMI | | Y | CY7C421-25LMB | 670 |
| 5962-8986701CA | A | 11/12/1991 | | (NONE) | 07/01/1994 | | UH507 (GEN) | 500 |
| 5962-8986801QYA | | 12/19/2001 | 1 | SEMELAB | | Y | IP138AK-DESC | 780 |
| 5962-8987001TA | A | 02/15/2001 | 3 | MICROSEMI | | Y | SG7908AG/883B | 783 |
| 5962-8987001UA | A | 02/15/2001 | 3 | MICROSEMI | | Y | SG7908AIG/883B | 783 |
| 5962-8987001XA | A | 02/15/2001 | 3 | MICROSEMI | | Y | SG7908AT/883B | 783 |
| 5962-8987001YA | A | 02/15/2001 | 3 | MICROSEMI | | Y | SG7908AK/883B | 783 |
| 5962-8987001ZA | A | 02/15/2001 | 3 | MICROSEMI | | Y | SG7908AR/883B | 783 |
| 5962-8987101GA | B | 07/28/1995 | | (NONE) | 04/14/2001 | | CMP01 (GEN) | 770 |
| 5962-8987101PA | B | 07/28/1995 | | (NONE) | 04/14/2001 | | CMP01 (GEN) | 770 |
| 5962-8987301YA | | 03/17/1992 | | (NONE) | | | LT1003 (GEN) | 782 |
| 5962-8987501CA | A | 09/22/1994 | | (NONE) | | | 1595 (GEN) | 810 |
| 5962-8987601EA | B | 12/02/2002 | 2 | MICROSEMI | | Y | SG2023J/883B | 790 |
| 5962-8987601FA | B | 12/02/2002 | 2 | MICROSEMI | | Y | SG2023F/883B | 790 |
| 5962-89877012C | B | 06/02/1999 | 1 | MAXIM INTEG. | | | MAX232MLP/883B | 590 |
| 5962-8987701EA | B | 06/02/1999 | 1 | MAXIM INTEG. | | | MAX232MJE/883B | 590 |
| 5962-8987701XA | B | 06/02/1999 | 1 | AUSTIN SEMI. | | Y | AS232F16/883C | 590 |
| 5962-8987702RA | B | 06/02/1999 | 1 | MAXIM INTEG. | | | MAX230MJP/883B | 590 |
| 5962-8987703CA | B | 06/02/1999 | 1 | MAXIM INTEG. | | | MAX231MJD/883B | 590 |
| 5962-8987704EA | B | 06/02/1999 | 1 | MAXIM INTEG. | | | MAX234MJE/883B | 590 |
| 5962-8987705JA | B | 06/02/1999 | 1 | MAXIM INTEG. | | | MAX236MRG/883B | 590 |
| 5962-8987706JA | B | 06/02/1999 | 1 | MAXIM INTEG. | | | MAX237MRG/883B | 590 |
| 5962-8987707JA | B | 06/02/1999 | 1 | MAXIM INTEG. | | | MAX238MRG/883B | 590 |
| 5962-8987708JA | B | 06/02/1999 | 1 | MAXIM INTEG. | | | MAX239MRG/883B | 590 |
| 5962-8987801EA | B | 10/24/2003 | 1 | MICROSEMI | | Y | SG1548J/883B | 899 |
| 5962-89880012A | B | 03/30/1993 | | (NONE) | 12/31/2002 | | HA-2522 (GEN) | 702 |
| 5962-8988001GC | B | 03/30/1993 | 1 | INTERSIL | 07/02/2004 | Y | HA2-2522/883 | 702 |
| 5962-8988001PA | B | 03/30/1993 | | (NONE) | 12/24/2000 | | HA-2522 (GEN) | 702 |
| 5962-89880022A | B | 03/30/1993 | | (NONE) | | | HA2520 (GEN) | 702 |
| 5962-8988002GC | B | 03/30/1993 | 1 | INTERSIL | | Y | HA2-2520/883 | 702 |
| 5962-8988002PA | B | 03/30/1993 | 1 | INTERSIL | 10/05/2004 | Y | HA7-2520/883 | 702 |
| 5962-8988201CA | A | 01/11/2002 | | (NONE) | 09/02/2003 | | 78C30 (GEN) | 564 |
| 5962-8988301XA | B | 11/27/1995 | | (NONE) | 03/31/1995 | | 8908CA55 (GEN) | 629 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-8988301YA | B | 11/27/1995 | | (NONE) | 03/31/1995 | | 8908CA55 (GEN) | 629 |
| 5962-8988301ZA | B | 11/27/1995 | | (NONE) | 03/31/1995 | | 8908CA55 (GEN) | 629 |
| 5962-8988302XA | B | 11/27/1995 | | (NONE) | 03/31/1995 | | 8908CA45 (GEN) | 629 |
| 5962-8988302YA | B | 11/27/1995 | | (NONE) | 03/31/1995 | | 8908CA45 (GEN) | 629 |
| 5962-8988302ZA | B | 11/27/1995 | | (NONE) | 03/31/1995 | | 8908CA45 (GEN) | 629 |
| 5962-8988303XA | B | 11/27/1995 | | (NONE) | 03/31/1995 | | 8908CA35 (GEN) | 629 |
| 5962-8988303YA | B | 11/27/1995 | | (NONE) | 03/31/1995 | | 8908CA35 (GEN) | 629 |
| 5962-8988303ZA | B | 11/27/1995 | | (NONE) | 03/31/1995 | | 8908CA35 (GEN) | 629 |
| 5962-8988304XA | B | 11/27/1995 | | (NONE) | 12/31/1998 | | 65779 (GEN) | 629 |
| 5962-89889013A | B | 09/02/1992 | | (NONE) | | | 54ALS870 (GEN) | 627 |
| 5962-8988901KA | B | 09/02/1992 | | (NONE) | | | 54ALS870 (GEN) | 627 |
| 5962-8988901LA | B | 09/02/1992 | | (NONE) | | | 54ALS870 (GEN) | 627 |
| 5962-8989001CA | A | 07/13/1999 | 1 | TI | | Y | CD54HCT393F3A | 305 |
| 5962-8989101LA | A | 11/30/2000 | 1 | PYRAMID | | | P4C198AL-25DMB | 620 |
| 5962-8989101XA | A | 11/30/2000 | | (NONE) | 05/06/1997 | | 7198L25 (GEN) | 620 |
| 5962-8989102LA | A | 11/30/2000 | 1 | PYRAMID | | | P4C198A-25DMB | 620 |
| 5962-8989102XA | A | 11/30/2000 | | (NONE) | 05/06/1997 | | 7198S25 (GEN) | 620 |
| 5962-8989103LA | A | 11/30/2000 | 1 | PYRAMID | | | P4C198AL-20DMB | 620 |
| 5962-8989103XA | A | 11/30/2000 | | (NONE) | 05/06/1997 | | 7198L20 (GEN) | 620 |
| 5962-8989104LA | A | 11/30/2000 | 1 | PYRAMID | | | P4C198A-20DMB | 620 |
| 5962-8989104XA | A | 11/30/2000 | | (NONE) | 05/06/1997 | | 7198S20 (GEN) | 620 |
| 5962-8989105LA | A | 11/30/2000 | 1 | PYRAMID | | | P4C198AL-15DMB | 620 |
| 5962-8989105XA | A | 11/30/2000 | 1 | PYRAMID | | | P4C198AL-15LMB | 620 |
| 5962-8989106LA | A | 11/30/2000 | 1 | PYRAMID | | | P4C198A-15DMB | 620 |
| 5962-8989106XA | A | 11/30/2000 | 1 | PYRAMID | | | P4C198A-15LMB | 620 |
| 5962-8989201KA | A | 11/30/2000 | 1 | PYRAMID | | | P4C198L-25FMB | 620 |
| 5962-8989201LA | A | 11/30/2000 | 1 | PYRAMID | | | P4C198L-25DMB | 620 |
| 5962-8989201XA | A | 11/30/2000 | 1 | PYRAMID | | | P4C198L-25LMB | 620 |
| 5962-8989201YA | A | 11/30/2000 | 1 | PYRAMID | | | P4C198L-25L1MB | 620 |
| 5962-8989202KA | A | 11/30/2000 | 1 | PYRAMID | | | P4C198-25FMB | 620 |
| 5962-8989202LA | A | 11/30/2000 | 1 | PYRAMID | | | P4C198-25DMB | 620 |
| 5962-8989202XA | A | 11/30/2000 | 1 | PYRAMID | | | P4C198-25LMB | 620 |
| 5962-8989202YA | A | 11/30/2000 | 1 | PYRAMID | | | P4C198-25L1MB | 620 |
| 5962-8989203KA | A | 11/30/2000 | 1 | PYRAMID | | | P4C198L-20FMB | 620 |
| 5962-8989203LA | A | 11/30/2000 | 1 | PYRAMID | | | P4C198L-20DMB | 620 |
| 5962-8989203XA | A | 11/30/2000 | 1 | PYRAMID | | | P4C198L-20LMB | 620 |
| 5962-8989203YA | A | 11/30/2000 | 1 | PYRAMID | | | P4C198L-20L1MB | 620 |
| 5962-8989204KA | A | 11/30/2000 | 1 | PYRAMID | | | P4C198-20FMB | 620 |
| 5962-8989204LA | A | 11/30/2000 | 1 | PYRAMID | | | P4C198-20DMB | 620 |
| 5962-8989204XA | A | 11/30/2000 | 1 | PYRAMID | | | P4C198-20LMB | 620 |
| 5962-8989204YA | A | 11/30/2000 | 1 | PYRAMID | | | P4C198-20L1MB | 620 |
| 5962-8989205KA | A | 11/30/2000 | 1 | PYRAMID | | | P4C198L-15FMB | 620 |
| 5962-8989205LA | A | 11/30/2000 | 1 | PYRAMID | | | P4C198L-15DMB | 620 |
| 5962-8989205XA | A | 11/30/2000 | 1 | PYRAMID | | | P4C198L-15LMB | 620 |
| 5962-8989205YA | A | 11/30/2000 | 1 | PYRAMID | | | P4C198L-15L1MB | 620 |
| 5962-8989206KA | A | 11/30/2000 | 1 | PYRAMID | | | P4C198-15FMB | 620 |
| 5962-8989206LA | A | 11/30/2000 | 1 | PYRAMID | | | P4C198-15DMB | 620 |
| 5962-8989206XA | A | 11/30/2000 | 1 | PYRAMID | | | P4C198-15LMB | 620 |
| 5962-8989206YA | A | 11/30/2000 | 1 | PYRAMID | | | P4C198-15L1MB | 620 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-89896012A | B | 03/15/2001 | 1 | ANALOG (5) | | Y | OP90ARC/883 | 701 |
| 5962-8989601PA | B | 03/15/2001 | | (NONE) | 04/16/2002 | | OP90A (GEN) | 701 |
| 5962-8989701CA | B | 11/20/2002 | 1 | MINCO | | Y | MTL1058AMJ/883 | 713 |
| 5962-8989701XA | B | 11/20/2002 | | (NONE) | 12/31/2001 | | LT1058A (GEN) | 713 |
| 5962-8989702CA | B | 11/20/2002 | | (NONE) | 12/31/2001 | | LT1058 (GEN) | 713 |
| 5962-8989702XA | B | 11/20/2002 | | (NONE) | 12/31/2001 | | LT1058 (GEN) | 713 |
| 5962-89899012A | A | 08/30/1993 | | (NONE) | | | UC1838A (GEN) | 899 |
| 5962-8989901EA | A | 08/30/1993 | | (NONE) | | | UC1838A (GEN) | 899 |
| 5962-89900013A | | 06/27/1994 | | (NONE) | | | AD9000 (GEN) | 592 |
| 5962-8990001EA | | 06/27/1994 | | (NONE) | | | AD9000 (GEN) | 592 |
| 5962-8990401CA | B | 01/27/2004 | 2 | ANALOG (5) | | Y | CMP404AY | 776 |
| 5962-8990402CA | B | 01/27/2004 | | (NONE) | 04/14/2001 | | CMP404B (GEN) | 776 |
| 5962-8990403CA | B | 01/27/2004 | | (NONE) | 04/16/2002 | | CMP04B (GEN) | 776 |
| 5962-89905012A | E | 06/04/2002 | 3 | TI | | Y | UC1823L/883BC | 787 |
| 5962-8990501EA | E | 06/04/2002 | 3 | TI | | Y | UC1823J/883BC | 787 |
| 5962-89905022A | E | 06/04/2002 | 3 | TI | | Y | UC1823AL/883BC | 787 |
| 5962-8990502EA | E | 06/04/2002 | 3 | TI | | Y | UC1823AJ/883BC | 787 |
| 5962-8990502VEA | E | 06/04/2002 | 1 | TI | | Y | UC1823AJQMLV | 787 |
| 5962-89905032A | E | 06/04/2002 | | (NONE) | 12/31/2001 | | 1823B (GEN) | 787 |
| 5962-8990503EA | E | 06/04/2002 | | (NONE) | 12/31/2001 | | 1823B (GEN) | 787 |
| 5962-8990801XA | K | 04/23/2004 | 1 | DDC | | Y | SDC14565-144 | 594 |
| 5962-8990801XA | K | 04/23/2004 | 1 | DDC IRELAND | | Y | SDC14565-144 | 594 |
| 5962-8990801XC | K | 04/23/2004 | 1 | DDC | | Y | SDC14565-114 | 594 |
| 5962-8990801XC | K | 04/23/2004 | 1 | DDC IRELAND | | Y | SDC14565-114 | 594 |
| 5962-8990801YC | K | 04/23/2004 | | (NONE) | | | SDC14565-629 (GEN) | 594 |
| 5962-8990801ZC | K | 04/23/2004 | | (NONE) | | | SDC14565-621 (GEN) | 594 |
| 5962-8990802XA | K | 04/23/2004 | 1 | DDC | | Y | SDC14565-145 | 594 |
| 5962-8990802XA | K | 04/23/2004 | 1 | DDC IRELAND | | Y | SDC14565-145 | 594 |
| 5962-8990802XC | K | 04/23/2004 | 1 | DDC | | Y | SDC14565-115 | 594 |
| 5962-8990802XC | K | 04/23/2004 | 1 | DDC IRELAND | | Y | SDC14565-115 | 594 |
| 5962-8990802YC | K | 04/23/2004 | | (NONE) | | | SDC14565-630 (GEN) | 594 |
| 5962-8990802ZC | K | 04/23/2004 | | (NONE) | | | SDC14565-622 (GEN) | 594 |
| 5962-8990803XC | K | 04/23/2004 | 1 | DDC | | Y | SDC14565-616 | 594 |
| 5962-8990803XC | K | 04/23/2004 | 1 | DDC IRELAND | | Y | SDC14565-616 | 594 |
| 5962-8990803ZC | K | 04/23/2004 | | (NONE) | | | SDC14565-616 (GEN) | 594 |
| 5962-8990804XA | K | 04/23/2004 | 1 | DDC | | Y | SDC14566-145 | 594 |
| 5962-8990804XA | K | 04/23/2004 | 1 | DDC IRELAND | | Y | SDC14566-145 | 594 |
| 5962-8990804XC | K | 04/23/2004 | 1 | DDC | | Y | SDC14566-115 | 594 |
| 5962-8990804XC | K | 04/23/2004 | 1 | DDC IRELAND | | Y | SDC14566-115 | 594 |
| 5962-8990804YC | K | 04/23/2004 | | (NONE) | | | SDC14566-609 (GEN) | 594 |
| 5962-8990804ZC | K | 04/23/2004 | | (NONE) | | | SDC14566-608 (GEN) | 594 |
| 5962-8990805XC | K | 04/23/2004 | | (NONE) | | | SDC14565-618 (GEN) | 594 |
| 5962-8990805ZC | K | 04/23/2004 | | (NONE) | | | SDC14565-618 (GEN) | 594 |
| 5962-8990806XC | K | 04/23/2004 | | (NONE) | | | HRD1066-341H (GEN) | 594 |
| 5962-8990807XC | K | 04/23/2004 | | (NONE) | | | HRD1066-341V (GEN) | 594 |
| 5962-8990808XC | K | 04/23/2004 | | (NONE) | | | HRD1066-381H (GEN) | 594 |
| 5962-8990809XC | K | 04/23/2004 | 1 | DDC | | Y | SDC14565-602 | 594 |
| 5962-8990809XC | K | 04/23/2004 | 1 | DDC IRELAND | | Y | SDC14565-602 | 594 |
| 5962-8990809ZC | K | 04/23/2004 | | (NONE) | | | SDC14565-602 (GEN) | 594 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-8990810XC | K | 04/23/2004 | 1 | DDC | | Y | SDC14565-603 | 594 |
| 5962-8990810XC | K | 04/23/2004 | 1 | DDC IRELAND | | Y | SDC14565-603 | 594 |
| 5962-8990810ZC | K | 04/23/2004 | | (NONE) | | | SDC14565-603 (GEN) | 594 |
| 5962-8990811XA | K | 04/23/2004 | 1 | DDC | | Y | SDC-14565-142 | 594 |
| 5962-8990811XA | K | 04/23/2004 | 1 | DDC IRELAND | | Y | SDC-14565-142 | 594 |
| 5962-8990811XC | K | 04/23/2004 | 1 | DDC | | Y | SDC-14565-112 | 594 |
| 5962-8990811XC | K | 04/23/2004 | 1 | DDC IRELAND | | Y | SDC-14565-112 | 594 |
| 5962-8990812XA | K | 04/23/2004 | 1 | DDC | | Y | SDC-14566-142 | 594 |
| 5962-8990812XA | K | 04/23/2004 | 1 | DDC IRELAND | | Y | SDC-14566-142 | 594 |
| 5962-8990812XC | K | 04/23/2004 | 1 | DDC | | Y | SDC-14566-112 | 594 |
| 5962-8990812XC | K | 04/23/2004 | 1 | DDC IRELAND | | Y | SDC-14566-112 | 594 |
| 5962-8990813XA | K | 04/23/2004 | 1 | DDC | | Y | SDC-14566-144 | 594 |
| 5962-8990813XA | K | 04/23/2004 | 1 | DDC IRELAND | | Y | SDC-14566-144 | 594 |
| 5962-8990813XC | K | 04/23/2004 | 1 | DDC | | Y | SDC-14566-114 | 594 |
| 5962-8990813XC | K | 04/23/2004 | 1 | DDC IRELAND | | Y | SDC-14566-114 | 594 |
| 5962-8991001XA | C | 06/06/2000 | | (NONE) | 09/27/2002 | | CLC200A (GEN) | 702 |
| 5962-8991101XA | C | 06/06/2000 | | (NONE) | 09/27/2002 | | CLC220A (GEN) | 701 |
| 5962-89915012A | A | 02/15/2001 | 1 | MICROSEMI | | Y | SG7818AL/883B | 782 |
| 5962-8991501UA | A | 02/15/2001 | 1 | MICROSEMI | | Y | SG7818AIG/883B | 782 |
| 5962-8991501XA | A | 02/15/2001 | 1 | MICROSEMI | | Y | SG7818AT/883B | 782 |
| 5962-8991501YA | A | 02/15/2001 | 1 | MICROSEMI | | Y | SG7818AK/883B | 782 |
| 5962-8991501ZA | A | 02/15/2001 | 1 | MICROSEMI | | Y | SG7818AR/883B | 782 |
| 5962-89920012A | A | 01/17/2001 | 1 | ROCHESTER | | Y | UC1840L/883 | 787 |
| 5962-8992001VA | A | 01/17/2001 | 1 | ROCHESTER | | Y | UC1840J/883 | 787 |
| 5962-89920022A | A | 01/17/2001 | | (NONE) | 12/31/2001 | | UC1841 (GEN) | 787 |
| 5962-8992002VA | A | 01/17/2001 | | (NONE) | 12/31/2001 | | UC1841 (GEN) | 787 |
| 5962-8992101XA | A | 01/17/2001 | | (NONE) | 09/02/2003 | | LM129A (GEN) | 785 |
| 5962-8992102XA | A | 01/17/2001 | | (NONE) | 03/30/2001 | | LM129B (GEN) | 785 |
| 5962-8992103XA | A | 01/17/2001 | | (NONE) | 03/30/2001 | | LM129C (GEN) | 785 |
| 5962-89925012A | A | 08/19/2004 | 1 | LANSDALE | | Y | SL54LS378/B2A | 159 |
| 5962-89925012A | A | 08/19/2004 | 1 | TI | | Y | SNJ54LS378FK | 159 |
| 5962-89925012C | A | 08/19/2004 | 1 | LANSDALE | | Y | SL54LS378/B2C | 159 |
| 5962-8992501EA | A | 08/19/2004 | 1 | LANSDALE | | Y | SL54LS378/BEA | 159 |
| 5962-8992501EA | A | 08/19/2004 | 1 | TI | | Y | SNJ54LS378J | 159 |
| 5962-8992501FA | A | 08/19/2004 | 1 | LANSDALE | | Y | SL54LS378/BFA | 159 |
| 5962-8992501FA | A | 08/19/2004 | 1 | TI | | Y | SNJ54LS378W | 159 |
| 5962-8992801XA | A | 07/20/1993 | | (NONE) | 02/29/2000 | | TLC34058-110 (GEN) | 591 |
| 5962-8992901VXA | A | 03/31/2004 | 3 | ANALOG (5) | | Y | AD589TH/QMLV | 785 |
| 5962-8993001MIA | C | 06/03/2003 | 1 | QP SEMI | | Y | LM126/MIA | 784 |
| 5962-89932012A | D | 12/22/2000 | 1 | ANALOG (5) | | Y | DAC08XRC | 591 |
| 5962R8993201V2A | D | 12/22/2000 | 1 | ANALOG (5) | | Y | DAC08XRC/QMLR | 591 |
| 5962R8993201VEA | D | 12/22/2000 | 1 | ANALOG (5) | | Y | DAC08XQ/QMLR | 591 |
| 5962R8993201VFA | D | 12/22/2000 | 1 | ANALOG (5) | | Y | DAC08XF/QMLR | 591 |
| 5962R8993202V2A | D | 12/22/2000 | 1 | ANALOG (5) | | Y | DAC08ARC/QMLR | 591 |
| 5962R8993202VEA | D | 12/22/2000 | 1 | ANALOG (5) | | Y | DAC08AQ/QMLR | 591 |
| 5962R8993202VFA | D | 12/22/2000 | 1 | ANALOG (5) | | Y | DAC08AF/QMLR | 591 |
| 5962-8993301GA | | 08/29/1994 | | (NONE) | 12/31/2001 | | 1006 (GEN) | 701 |
| 5962-8993301PA | | 08/29/1994 | | (NONE) | 12/31/2001 | | 1006 (GEN) | 701 |
| 5962-8993302GA | | 08/29/1994 | | (NONE) | 03/30/2001 | | LT1006A (GEN) | 701 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-8993302PA | | 08/29/1994 | | (NONE) | 03/30/2001 | | LT1006A (GEN) | 701 |
| 5962-8993501XA | A | 08/30/2000 | 1 | AUSTIN SEMI. | | Y | AS5C2566C-45 | 623 |
| 5962-8993501YA | A | 08/30/2000 | | (NONE) | | | 7C192-45 (GEN) | 623 |
| 5962-8993501ZA | A | 08/30/2000 | | (NONE) | 03/05/1996 | | 7C192-45 (GEN) | 623 |
| 5962-8993502XA | A | 08/30/2000 | 1 | AUSTIN SEMI. | | Y | AS5C2566C-35 | 623 |
| 5962-8993502YA | A | 08/30/2000 | | (NONE) | | | 7C192-35 (GEN) | 623 |
| 5962-8993502ZA | A | 08/30/2000 | | (NONE) | | | 7C192-35 (GEN) | 623 |
| 5962-8993503XA | A | 08/30/2000 | 1 | AUSTIN SEMI. | | Y | AS5C2566C-25 | 623 |
| 5962-8993503YA | A | 08/30/2000 | | (NONE) | | | 7C192-25 (GEN) | 623 |
| 5962-8993503ZA | A | 08/30/2000 | | (NONE) | 03/05/1996 | | 7C192-25 (GEN) | 623 |
| 5962-8994001HXC | A | 10/01/2003 | | (NONE) | | | AD346S (GEN) | 818 |
| 5962-8994002HXA | A | 10/01/2003 | 1 | MICRO NETWKS | | Y | MN346H/B | 818 |
| 5962-8994002HXC | A | 10/01/2003 | 1 | MICRO NETWKS | | Y | MN346H/B | 818 |
| 5962-8994201QA | A | 01/13/1993 | | (NONE) | | | 72103L120 (GEN) | 670 |
| 5962-8994201XA | A | 01/13/1993 | | (NONE) | | | 72103L120 (GEN) | 670 |
| 5962-8994202QA | A | 01/13/1993 | | (NONE) | | | 72103L80 (GEN) | 670 |
| 5962-8994202XA | A | 01/13/1993 | | (NONE) | | | 72103L80 (GEN) | 670 |
| 5962-8994203QA | A | 01/13/1993 | | (NONE) | | | 72103L65 (GEN) | 670 |
| 5962-8994203XA | A | 01/13/1993 | | (NONE) | | | 72103L65 (GEN) | 670 |
| 5962-8994204QA | A | 01/13/1993 | | (NONE) | 11/27/1996 | | 72103L50 (GEN) | 670 |
| 5962-8994204XA | A | 01/13/1993 | | (NONE) | | | 72103L50 (GEN) | 670 |
| 5962-8994205QA | A | 01/13/1993 | | (NONE) | 11/27/1996 | | 72103L40 (GEN) | 670 |
| 5962-8994205XA | A | 01/13/1993 | | (NONE) | | | 72103L40 (GEN) | 670 |
| 5962-8994301QA | A | 06/22/1994 | | (NONE) | | | 72104L120 (GEN) | 670 |
| 5962-8994301XA | A | 06/22/1994 | | (NONE) | | | 72104L120 (GEN) | 670 |
| 5962-8994302QA | A | 06/22/1994 | | (NONE) | | | 72104L80 (GEN) | 670 |
| 5962-8994302XA | A | 06/22/1994 | | (NONE) | | | 72104L80 (GEN) | 670 |
| 5962-8994303QA | A | 06/22/1994 | | (NONE) | | | 72104L65 (GEN) | 670 |
| 5962-8994303XA | A | 06/22/1994 | | (NONE) | | | 72104L65 (GEN) | 670 |
| 5962-8994304QA | A | 06/22/1994 | | (NONE) | 11/27/1996 | | 72104L50 (GEN) | 670 |
| 5962-8994304XA | A | 06/22/1994 | | (NONE) | | | 72104L50 (GEN) | 670 |
| 5962-8994305QA | A | 06/22/1994 | | (NONE) | 11/27/1996 | | 72104L40 (GEN) | 670 |
| 5962-89944012A | A | 02/21/1992 | | (NONE) | | | 54LS248 (GEN) | 291 |
| 5962-8994401EA | A | 02/21/1992 | | (NONE) | | | 54LS248 (GEN) | 291 |
| 5962-89945013A | A | 04/14/1992 | 2 | TI | | Y | SNJ54ALS996FK | 341 |
| 5962-8994501KA | A | 04/14/1992 | 2 | TI | | Y | SNJ54ALS996W | 341 |
| 5962-8994501LA | A | 04/14/1992 | 2 | TI | | Y | SNJ54ALS996JT | 341 |
| 5962-89946012A | | 08/10/1990 | | (NONE) | 05/31/1994 | | 54HC190 (GEN) | 301 |
| 5962-8994601EA | | 08/10/1990 | 1 | TI | | Y | CD54HC190F3A | 301 |
| 5962-8994701MEA | | 07/17/1991 | 1 | TI | | Y | CD54HCT4040F3A | 305 |
| 5962-8994801Q9A | F | 02/01/2002 | | (NONE) | | | 3020-50 (GEN) | 431 |
| 5962-8994801MMC | F | 02/01/2002 | | (NONE) | 01/15/2000 | | 3020-50 (GEN) | 431 |
| 5962-8994801MNC | F | 02/01/2002 | | (NONE) | 01/15/2000 | | 3020-50 (GEN) | 431 |
| 5962-8994801MTC | F | 02/01/2002 | | (NONE) | 01/15/2000 | | 3020-50 (GEN) | 431 |
| 5962-8994801QUA | F | 02/01/2002 | | (NONE) | | | 3020-50 (GEN) | 431 |
| 5962-8994801MXC | F | 02/01/2002 | | (NONE) | 01/15/2000 | | 3020-50 (GEN) | 431 |
| 5962-8994801XC | F | 02/01/2002 | | (NONE) | 01/15/2000 | | 3020-50 (GEN) | 431 |
| 5962-8994801MYC | F | 02/01/2002 | | (NONE) | 01/15/2000 | | 3020-50 (GEN) | 431 |
| 5962-8994801YC | F | 02/01/2002 | | (NONE) | 01/15/2000 | | 3020-50 (GEN) | 431 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-8994801MZA | F | 02/01/2002 | | (NONE) | | | 3020-50 (GEN) | 431 |
| 5962-8994801QZA | F | 02/01/2002 | | (NONE) | | | 3020-50 (GEN) | 431 |
| 5962-8994802Q9A | F | 02/01/2002 | | (NONE) | | | 3020-70 (GEN) | 431 |
| 5962-8994802MMC | F | 02/01/2002 | | (NONE) | 01/15/2000 | | 3020-70 (GEN) | 431 |
| 5962-8994802MNC | F | 02/01/2002 | | (NONE) | 01/15/2000 | | 3020-70 (GEN) | 431 |
| 5962-8994802MTC | F | 02/01/2002 | | (NONE) | 01/15/2000 | | 3020-70 (GEN) | 431 |
| 5962-8994802QUA | F | 02/01/2002 | | (NONE) | | | 3020-70 (GEN) | 431 |
| 5962-8994802MXC | F | 02/01/2002 | | (NONE) | 01/15/2000 | | 3020-70 (GEN) | 431 |
| 5962-8994802XC | F | 02/01/2002 | | (NONE) | 01/15/2000 | | 3020-70 (GEN) | 431 |
| 5962-8994802MYC | F | 02/01/2002 | | (NONE) | 01/15/2000 | | 3020-70 (GEN) | 431 |
| 5962-8994802YC | F | 02/01/2002 | | (NONE) | 01/15/2000 | | 3020-70 (GEN) | 431 |
| 5962-8994802MZA | F | 02/01/2002 | | (NONE) | | | 3020-70 (GEN) | 431 |
| 5962-8994802QZA | F | 02/01/2002 | | (NONE) | | | 3020-70 (GEN) | 431 |
| 5962-8994803Q9A | F | 02/01/2002 | | (NONE) | | | 3020-100 (GEN) | 431 |
| 5962-8994803MMC | F | 02/01/2002 | 1 | XILINX | | Y | XC3020-100CB100B | 431 |
| 5962-8994803MNC | F | 02/01/2002 | 1 | XILINX | | Y | XC3020-100CB100B | 431 |
| 5962-8994803MTC | F | 02/01/2002 | 1 | XILINX | | Y | XC3020-100CQ100B | 431 |
| 5962-8994803QUA | F | 02/01/2002 | | (NONE) | | | 3020-100 (GEN) | 431 |
| 5962-8994803MXC | F | 02/01/2002 | 1 | XILINX | | Y | XC3020-100PG84B | 431 |
| 5962-8994803MYC | F | 02/01/2002 | 1 | XILINX | | Y | XC3020-100CQ100B | 431 |
| 5962-8994803QZA | F | 02/01/2002 | | (NONE) | | | 3020-100 (GEN) | 431 |
| 5962-8994804Q9A | F | 02/01/2002 | | (NONE) | | | 3020-125 (GEN) | 431 |
| 5962-8994804QUA | F | 02/01/2002 | | (NONE) | | | 3020-125 (GEN) | 431 |
| 5962-8994804QZA | F | 02/01/2002 | | (NONE) | | | 3020-125 (GEN) | 431 |
| 5962-8995001B2A | | 01/19/1993 | 3 | NATIONAL | | Y | JM54ACT112B2A | 156 |
| 5962-8995001M2A | | 01/19/1993 | 3 | NATIONAL | | Y | 54ACT112LMQB | 156 |
| 5962-8995001S2A | | 01/19/1993 | 3 | NATIONAL | | Y | JM54ACT112S2A | 156 |
| 5962-8995001BEA | | 01/19/1993 | 3 | NATIONAL | | Y | JM54ACT112BEA | 156 |
| 5962-8995001MEA | | 01/19/1993 | 3 | NATIONAL | | Y | 54ACT112DMQB | 156 |
| 5962-8995001SEA | | 01/19/1993 | 3 | NATIONAL | | Y | JM54ACT112SEA | 156 |
| 5962-8995001BFA | | 01/19/1993 | 3 | NATIONAL | | Y | JM54ACT112BFA | 156 |
| 5962-8995001MFA | | 01/19/1993 | 3 | NATIONAL | | Y | 54ACT112FMQB | 156 |
| 5962-8995001SFA | | 01/19/1993 | 3 | NATIONAL | | Y | JM54ACT112SFA | 156 |
| 5962-8995101VA | | 12/21/1990 | | (NONE) | | | | 608 |
| 5962-8995102VA | | 12/21/1990 | | (NONE) | | | | 608 |
| 5962-8995103VA | | 12/21/1990 | | (NONE) | | | | 608 |
| 5962-8995301EA | | 02/01/1993 | 1 | TI | | Y | CD54HC4015F3A | 226 |
| 5962-8995401EA | | 02/05/1993 | 1 | TI | | Y | CD54HC4520F3A | 319 |
| 5962-89956013A | B | 06/10/2002 | 3 | TI | | Y | SNJ54ALS646FK | 590 |
| 5962-8995601KA | B | 06/10/2002 | 3 | TI | | Y | SNJ54ALS646W | 590 |
| 5962-8995601LA | B | 06/10/2002 | 3 | TI | | Y | SNJ54ALS646JT | 590 |
| 5962-89957012A | C | 06/17/2003 | 1 | TI | | Y | UC1637L/883 | 899 |
| 5962-8995701VA | C | 06/17/2003 | 1 | TI | | Y | UC1637J/883 | 899 |
| 5962-8995901XA | C | 02/02/1996 | | (NONE) | 04/01/2000 | | L4C381-45 (GEN) | 205 |
| 5962-8995901YA | C | 02/02/1996 | | (NONE) | 04/01/2000 | | L4C381-45 (GEN) | 205 |
| 5962-8995901ZA | C | 02/02/1996 | | (NONE) | 04/01/2000 | | L4C381-45 (GEN) | 205 |
| 5962-8995902YA | C | 02/02/1996 | | (NONE) | 04/01/2000 | | L4C381-30 (GEN) | 205 |
| 5962-8995902ZA | C | 02/02/1996 | | (NONE) | 04/01/2000 | | L4C381-30 (GEN) | 205 |
| 5962-8995903YA | C | 02/02/1996 | | (NONE) | 04/01/2000 | | L4C381-25 (GEN) | 205 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-8995903ZA | C | 02/02/1996 | | (NONE) | 04/01/2000 | | L4C381-25 (GEN) | 205 |
| 5962-89961012A | A | 11/20/2002 | 1 | SILICONIX | | Y | DG405AZ/883 | 188 |
| 5962-89961012C | A | 11/20/2002 | 1 | MAXIM INTEG. | | | DG405AZ/883B | 188 |
| 5962-8996101EA | A | 11/20/2002 | 1 | MAXIM INTEG. | | | DG405AK/883B | 188 |
| 5962-8996101EA | A | 11/20/2002 | 1 | SILICONIX | | Y | DG405AK/883 | 188 |
| 5962-8996701M3A | | 02/10/1993 | 3 | QP SEMI | | Y | CY7C265-60LMB | 660 |
| 5962-8996701MXA | | 02/10/1993 | 3 | QP SEMI | | Y | CY7C265-60DMB | 660 |
| 5962-8996701MYA | | 02/10/1993 | 3 | QP SEMI | | Y | CY7C265-60KMB | 660 |
| 5962-8996702M3A | | 02/10/1993 | 3 | QP SEMI | | Y | CY7C265-50LMB | 660 |
| 5962-8996702MXA | | 02/10/1993 | 3 | QP SEMI | | Y | CY7C265-50DMB | 660 |
| 5962-8996702MYA | | 02/10/1993 | 3 | QP SEMI | | Y | CY7C265-50KMB | 660 |
| 5962-8996703M3A | | 02/10/1993 | 3 | QP SEMI | | Y | CY7C265-25LMB | 660 |
| 5962-8996703MXA | | 02/10/1993 | 3 | QP SEMI | | Y | CY7C265-25DMB | 660 |
| 5962-8996703MYA | | 02/10/1993 | 3 | QP SEMI | | Y | CY7C265-25KMB | 660 |
| 5962-8996704M3A | | 02/10/1993 | 3 | QP SEMI | | Y | CY7C265-18LMB | 660 |
| 5962-8996704MXA | | 02/10/1993 | 3 | QP SEMI | | Y | CY7C265-18DMB | 660 |
| 5962-8996704MYA | | 02/10/1993 | 3 | QP SEMI | | Y | CY7C265-18KMB | 660 |
| 5962-89969012A | A | 11/15/1991 | | (NONE) | 09/30/1995 | | 35074M (GEN) | 713 |
| 5962-8996901CA | A | 11/15/1991 | | (NONE) | 09/30/1995 | | 35074 (GEN) | 713 |
| 5962-89969022A | A | 11/15/1991 | | (NONE) | 09/30/1995 | | 35074A (GEN) | 713 |
| 5962-8996902CA | A | 11/15/1991 | | (NONE) | 09/30/1995 | | 35074A (GEN) | 713 |
| 5962-89970012A | E | 11/26/2003 | 1 | NATIONAL | | Y | CLC400AE-QML | 755 |
| 5962-8997001PA | E | 11/26/2003 | 1 | NATIONAL | | Y | CLC400AJ-QML | 755 |
| 5962-8997101MQA | | 05/22/1992 | | (NONE) | 10/15/1995 | | 8744H10 (GEN) | 599 |
| 5962-8997201HXA | C | 05/30/2001 | | (NONE) | | | MSK-1902B-0 (GEN) | 760 |
| 5962-8997201HXC | C | 05/30/2001 | | (NONE) | | | MSK-1902B-0 (GEN) | 760 |
| 5962-8997202HXA | C | 05/30/2001 | | (NONE) | | | MSK-1902B-2 (GEN) | 760 |
| 5962-8997202HXC | C | 05/30/2001 | | (NONE) | | | MSK-1902B-2 (GEN) | 760 |
| 5962-89973012A | G | 04/03/2003 | | (NONE) | | | CLC401A (GEN) | 755 |
| 5962-8997301PA | G | 04/03/2003 | 1 | NATIONAL | | Y | CLC401AJ-QML | 755 |
| 5962-8997302PA | G | 04/03/2003 | | (NONE) | | | EL2171 (GEN) | 755 |
| 5962-89974012A | C | 01/16/2001 | | (NONE) | 06/03/2003 | | CLC501 (GEN) | 702 |
| 5962-8997401PA | C | 01/16/2001 | | (NONE) | 06/03/2003 | | CLC501 (GEN) | 702 |
| 5962-8997501PA | C | 01/16/2001 | 1 | NATIONAL | | Y | CLC110AJ-QML | 755 |
| 5962-8997502PA | C | 01/16/2001 | | (NONE) | 09/30/1993 | | EL2072 (GEN) | 755 |
| 5962-8997601GA | A | 11/25/1992 | | (NONE) | 03/30/2001 | | LT1055A (GEN) | 703 |
| 5962-8997602GA | A | 11/25/1992 | | (NONE) | 03/30/2001 | | LT1056A (GEN) | 703 |
| 5962-8997603GA | A | 11/25/1992 | | (NONE) | 03/30/2001 | | LT1055 (GEN) | 703 |
| 5962-8997604GA | A | 11/25/1992 | | (NONE) | 03/30/2001 | | LT1056 (GEN) | 703 |
| 5962-8997901XA | A | 01/26/1993 | | (NONE) | 09/01/2000 | | SP1078B (GEN) | 592 |
| 5962-8998101MA | E | 02/21/2002 | 1 | INTER. RECT. | | | OM1860SRM/883B | 780 |
| 5962-8998101TA | E | 02/21/2002 | 1 | INTER. RECT. | | | OM1860N5M/883B | 780 |
| 5962-8998101UA | E | 02/21/2002 | 1 | INTER. RECT. | | | OM186ST/883B | 780 |
| 5962-8998101UA | E | 02/21/2002 | 1 | SOLITRON | | | SDP1086UMD | 780 |
| 5962-8998101XA | E | 02/21/2002 | 1 | INTER. RECT. | | | OM1860NKM/883B | 780 |
| 5962-8998101XA | E | 02/21/2002 | 1 | SOLITRON | | | SDP1086XMD | 780 |
| 5962-8998101YA | E | 02/21/2002 | 1 | INTER. RECT. | | | OM1860NHM/883B | 780 |
| 5962-8998101YA | E | 02/21/2002 | 1 | SOLITRON | | | SDP1086YMD | 780 |
| 5962-8998101ZA | E | 02/21/2002 | 1 | INTER. RECT. | | | OM186STZM/883B | 780 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-8998101ZA | E | 02/21/2002 | 1 | SOLITRON | | | SDP1086ZMD | 780 |
| 5962-8998201YA | B | 06/14/2004 | | (NONE) | | | 80C196KB (GEN) | 420 |
| 5962-8998201ZA | B | 06/14/2004 | | (NONE) | | | 80C196KB (GEN) | 420 |
| 5962-8998202YA | B | 06/14/2004 | 1 | ROCHESTER | | Y | MQ80C196KB-12/BYA | 420 |
| 5962-8998202YC | B | 06/14/2004 | 1 | ROCHESTER | | Y | MQ80C196KB-12/BYC | 420 |
| 5962-8998202ZA | B | 06/14/2004 | 1 | ROCHESTER | | Y | MQ80C196KB-12/BZA | 420 |
| 5962-8998202ZC | B | 06/14/2004 | 1 | ROCHESTER | | Y | MQ80C196KB-12/BZC | 420 |
| 5962-8998601HXA | C | 04/23/2004 | 1 | DDC | | Y | DSC-11520-142 | 594 |
| 5962-8998601HXA | C | 04/23/2004 | 1 | DDC IRELAND | | Y | DSC-11520-142 | 594 |
| 5962-8998601HXC | C | 04/23/2004 | 1 | DDC | | Y | DSC-11520-112 | 594 |
| 5962-8998601HXC | C | 04/23/2004 | 1 | DDC IRELAND | | Y | DSC-11520-112 | 594 |
| 5962-8998602HXA | C | 04/23/2004 | 1 | DDC | | Y | DSC-11520-143 | 594 |
| 5962-8998602HXA | C | 04/23/2004 | 1 | DDC IRELAND | | Y | DSC-11520-143 | 594 |
| 5962-8998602HXC | C | 04/23/2004 | 1 | DDC | | Y | DSC-11520-113 | 594 |
| 5962-8998602HXC | C | 04/23/2004 | 1 | DDC IRELAND | | Y | DSC-11520-113 | 594 |
| 5962-8998603HXA | C | 04/23/2004 | 1 | DDC | | Y | DSC-11520-144 | 594 |
| 5962-8998603HXA | C | 04/23/2004 | 1 | DDC IRELAND | | Y | DSC-11520-144 | 594 |
| 5962-8998603HXC | C | 04/23/2004 | 1 | DDC | | Y | DSC-11520-114 | 594 |
| 5962-8998603HXC | C | 04/23/2004 | 1 | DDC IRELAND | | Y | DSC-11520-114 | 594 |
| 5962-8998604HXA | C | 04/23/2004 | 1 | DDC | | Y | DSC-11520-145 | 594 |
| 5962-8998604HXA | C | 04/23/2004 | 1 | DDC IRELAND | | Y | DSC-11520-145 | 594 |
| 5962-8998604HXC | C | 04/23/2004 | 1 | DDC | | Y | DSC-11520-115 | 594 |
| 5962-8998604HXC | C | 04/23/2004 | 1 | DDC IRELAND | | Y | DSC-11520-115 | 594 |
| 5962-89989012A | | 07/31/1990 | | (NONE) | | | 54HC623 (GEN) | 590 |
| 5962-8998901RA | | 07/31/1990 | | (NONE) | | | 54HC623 (GEN) | 590 |
| 5962-8999001EA | | 09/03/1991 | 1 | TI | | Y | CD54HC297F/3A | 805 |
| 5962-9049701HXA | | 04/26/1994 | 1 | MICRO NETWKS | | Y | MN5140H/B | 592 |
| 5962-9049701HXC | | 04/26/1994 | 1 | MICRO NETWKS | | Y | MN5140H/B | 592 |
| 5962-9049702HXA | | 04/26/1994 | 1 | MICRO NETWKS | | Y | MN5141H/B | 592 |
| 5962-9049702HXC | | 04/26/1994 | 1 | MICRO NETWKS | | Y | MN5141H/B | 592 |
| 5962-9049703HXA | | 04/26/1994 | 1 | MICRO NETWKS | | Y | MN5142H/B | 592 |
| 5962-9049703HXC | | 04/26/1994 | 1 | MICRO NETWKS | | Y | MN5142H/B | 592 |
| 5962-9049704HXA | | 04/26/1994 | 1 | MICRO NETWKS | | Y | MN5143H/B | 592 |
| 5962-9049704HXC | | 04/26/1994 | 1 | MICRO NETWKS | | Y | MN5143H/B | 592 |
| 5962-9050001HXA | B | 06/19/2002 | 1 | MS KENNEDY | | Y | MSK1461B | 739 |
| 5962-9050001HXC | B | 06/19/2002 | 1 | MS KENNEDY | | Y | MSK1461B | 739 |
| 5962-9050101Q2A | | 12/15/1994 | 2 | TI | | Y | SNJ54HC166FK | 228 |
| 5962-9050101QEA | | 12/15/1994 | 2 | TI | | Y | SNJ54HC166J | 228 |
| 5962-90502013A | | 02/05/1990 | | (NONE) | 09/01/1997 | | 54F198 (GEN) | 228 |
| 5962-9050201KA | | 02/05/1990 | | (NONE) | 09/01/1997 | | 54F198 (GEN) | 228 |
| 5962-9050201LA | | 02/05/1990 | | (NONE) | 09/01/1997 | | 54F198 (GEN) | 228 |
| 5962-90503012A | C | 08/23/2004 | 1 | TI | | Y | SNJ54LS396FK | 226 |
| 5962-9050301EA | C | 08/23/2004 | 1 | TI | 07/15/2005 | Y | SNJ54LS396J | 226 |
| 5962-9050401MXC | C | 05/19/1997 | | (NONE) | | | L64230-12 (GEN) | 399 |
| 5962-9050401MYA | C | 05/19/1997 | | (NONE) | 04/01/2000 | | L64230-75 (GEN) | 399 |
| 5962-9050402MXC | C | 05/19/1997 | | (NONE) | | | L64230-16 (GEN) | 399 |
| 5962-9050402MYA | C | 05/19/1997 | | (NONE) | 04/01/2000 | | L64230-60 (GEN) | 399 |
| 5962-9050501MEA | | 04/19/1991 | 1 | TI | | Y | CD54HCT153F3A | 273 |
| 5962-90506012A | | 05/08/1991 | | (NONE) | 12/31/2001 | | 54F623 (GEN) | 590 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9050601RA | | 05/08/1991 | | (NONE) | 12/31/2001 | | 54F623 (GEN) | 590 |
| 5962-9050601SA | | 05/08/1991 | 0 | TI | | Y | SNJ54F623W | 590 |
| 5962-90506022A | | 05/08/1991 | | (NONE) | 06/01/2001 | | 54F621 (GEN) | 590 |
| 5962-9050602RA | | 05/08/1991 | | (NONE) | 06/01/2001 | | 54F621 (GEN) | 590 |
| 5962-9050602SA | | 05/08/1991 | | (NONE) | 06/01/2001 | | 54F621 (GEN) | 590 |
| 5962-9050701XA | A | 07/18/2000 | | (NONE) | 03/30/2001 | | LM134 (GEN) | 899 |
| 5962-9050702XA | A | 07/18/2000 | | (NONE) | 03/30/2001 | | LM134-3 (GEN) | 899 |
| 5962-9050703XA | A | 07/18/2000 | | (NONE) | 03/30/2001 | | LM134-6 (GEN) | 899 |
| 5962-9050801M3A | D | 05/03/2004 | 1 | ANALOG (4) | | Y | AD9002SE/883B | 592 |
| 5962-9050801MXA | D | 05/03/2004 | 1 | ANALOG (4) | | Y | AD9002SD/883B | 592 |
| 5962-9050802M3A | D | 05/03/2004 | 1 | ANALOG (4) | | Y | AD9002TE/883B | 592 |
| 5962-9050802MXA | D | 05/03/2004 | 1 | ANALOG (4) | | Y | AD9002TD/883B | 592 |
| 5962-90509012A | | 01/20/1993 | | (NONE) | 09/30/1993 | | EL2002A (GEN) | 899 |
| 5962-9050901PA | | 01/20/1993 | | (NONE) | 09/30/1993 | | EL2002A (GEN) | 899 |
| 5962-90509022A | | 01/20/1993 | | (NONE) | 09/30/1993 | | EL2002 (GEN) | 899 |
| 5962-9050902PA | | 01/20/1993 | | (NONE) | 09/30/1993 | | EL2002 (GEN) | 899 |
| 5962-9051001XA | | 03/30/1992 | | (NONE) | 09/30/1995 | | 68HC11A0 (GEN) | 420 |
| 5962-9051001YC | | 03/30/1992 | | (NONE) | 09/30/1995 | | 68HC11A0 (GEN) | 420 |
| 5962-9051002XA | | 03/30/1992 | 1 | ATMEL GREN. | | | TS68HC11A1MC1B/C | 420 |
| 5962-9051002XC | | 03/30/1992 | 1 | ATMEL GREN. | | | TS68HC11A1MCB/C | 420 |
| 5962-9051002YA | | 03/30/1992 | 1 | ATMEL GREN. | | | TS68HC11A1MF1B/C | 420 |
| 5962-9051002YC | | 03/30/1992 | 1 | ATMEL GREN. | | | TS68HC11A1MFB/C | 420 |
| 5962-9051201MQA | | 12/07/1992 | | (NONE) | 06/15/1996 | | 8748H (GEN) | 410 |
| 5962-90513013A | | 04/27/1990 | | (NONE) | | | 29833A (GEN) | 590 |
| 5962-9051301KA | | 04/27/1990 | | (NONE) | | | 29833A (GEN) | 590 |
| 5962-9051301LA | | 04/27/1990 | | (NONE) | | | 29833A (GEN) | 590 |
| 5962-90513023A | | 04/27/1990 | | (NONE) | | | 29853A (GEN) | 590 |
| 5962-9051302KA | | 04/27/1990 | | (NONE) | | | 29853A (GEN) | 590 |
| 5962-9051302LA | | 04/27/1990 | | (NONE) | | | 29853A (GEN) | 590 |
| 5962-90513033A | | 04/27/1990 | | (NONE) | | | 29855A (GEN) | 590 |
| 5962-9051303KA | | 04/27/1990 | | (NONE) | | | 29855A (GEN) | 590 |
| 5962-9051303LA | | 04/27/1990 | | (NONE) | | | 29855A (GEN) | 590 |
| 5962-9051401M2A | | 09/21/1990 | 3 | TI | | Y | SNJ54BCT245FK | 590 |
| 5962-9051401MRA | | 09/21/1990 | 0 | TI | | Y | SNJ54BCT245J | 590 |
| 5962-9051401MSA | | 09/21/1990 | 3 | TI | | Y | SNJ54BCT245W | 590 |
| 5962-90515013A | C | 09/03/1996 | | (NONE) | | | 29C818-30 (GEN) | 249 |
| 5962-9051501LA | C | 09/03/1996 | | (NONE) | | | 29C818-30 (GEN) | 249 |
| 5962-9051501XA | C | 09/03/1996 | | (NONE) | | | 29C818-30 (GEN) | 249 |
| 5962-9051601M2A | A | 08/05/1992 | 3 | TI | | Y | SNJ54BCT374FK | 159 |
| 5962-9051601MRA | A | 08/05/1992 | 3 | TI | | Y | SNJ54BCT374J | 159 |
| 5962-9051601MSA | A | 08/05/1992 | 3 | TI | | Y | SNJ54BCT374W | 159 |
| 5962-9051801MEA | A | 12/11/1992 | | (NONE) | 03/25/2001 | | HD-4702 (GEN) | 399 |
| 5962-9051901XA | A | 07/17/2000 | | (NONE) | 03/30/2001 | | LT1029A (GEN) | 785 |
| 5962-9051902XA | A | 07/17/2000 | | (NONE) | 03/30/2001 | | LT1029 (GEN) | 785 |
| 5962-9052001XA | | 08/23/1993 | | (NONE) | 06/30/1996 | | SL560AC (GEN) | 760 |
| 5962-9052101XA | | 06/16/1993 | | (NONE) | 06/30/1996 | | SL532AC (GEN) | 755 |
| 5962-9052201GA | B | 08/21/2002 | 1 | QP SEMI | | Y | QP1632/GA | 581 |
| 5962-9052201GC | B | 08/21/2002 | 1 | QP SEMI | | Y | QP1632/GC | 581 |
| 5962-9052201PA | B | 08/21/2002 | 1 | QP SEMI | | Y | QP1632/PA | 581 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9052201PA | B | 08/21/2002 | 3 | SARNOFF | | Y | GEM34301QPA | 581 |
| 5962-9052201PC | B | 08/21/2002 | 3 | SARNOFF | | Y | GEM34301QPC | 581 |
| 5962-9052201XA | B | 08/21/2002 | 1 | QP SEMI | | Y | QP1632/XA | 581 |
| 5962-9052201XA | B | 08/21/2002 | 3 | SARNOFF | | Y | GEM34301QXA | 581 |
| 5962-9052201XC | B | 08/21/2002 | 1 | QP SEMI | | Y | QP1632/XC | 581 |
| 5962-9052201XC | B | 08/21/2002 | 3 | SARNOFF | | Y | GEM34301QXC | 581 |
| 5962-90523013A | B | 04/23/2003 | 2 | TI | | Y | SNJ54ALS648FK | 590 |
| 5962-9052301KA | B | 04/23/2003 | 2 | TI | | Y | SNJ54ALS648W | 590 |
| 5962-9052301LA | B | 04/23/2003 | 2 | TI | | Y | SNJ54ALS648JT | 590 |
| 5962-9052401MEA | | 04/25/1991 | 1 | TI | | Y | CD54HCT251F3A | 272 |
| 5962-9052501MQA | B | 08/04/2003 | | (NONE) | 03/25/2001 | | HD-6402R (GEN) | 590 |
| 5962-9052502MQA | B | 08/04/2003 | 1 | INTERSIL | | Y | HD1-6402B/883 | 590 |
| 5962-9052601MUA | M | 08/27/2004 | | (NONE) | | | 320C30 (GEN) | 432 |
| 5962-9052601MXA | M | 08/27/2004 | | (NONE) | | | 320C30 (GEN) | 432 |
| 5962-9052601MYA | M | 08/27/2004 | | (NONE) | | | 320C30 (GEN) | 432 |
| 5962-9052601MZA | M | 08/27/2004 | | (NONE) | | | 320C30 (GEN) | 432 |
| 5962-9052602MUA | M | 08/27/2004 | | (NONE) | | | 320C30 (GEN) | 432 |
| 5962-9052602MXA | M | 08/27/2004 | | (NONE) | | | 320C30 (GEN) | 432 |
| 5962-9052602MYA | M | 08/27/2004 | | (NONE) | | | 320C30 (GEN) | 432 |
| 5962-9052602MZA | M | 08/27/2004 | | (NONE) | | | 320C30 (GEN) | 432 |
| 5962-9052603QMC | M | 08/27/2004 | | (NONE) | 05/01/1998 | | 320C30 (GEN) | 432 |
| 5962-9052603QTC | M | 08/27/2004 | | (NONE) | 05/01/1998 | | 320C30 (GEN) | 432 |
| 5962-9052603MUA | M | 08/27/2004 | | (NONE) | 05/01/1998 | | 320C30 (GEN) | 432 |
| 5962-9052603MXA | M | 08/27/2004 | | (NONE) | 05/01/1998 | | 320C30 (GEN) | 432 |
| 5962-9052604Q9A | M | 08/27/2004 | | (NONE) | 04/30/2001 | | 320C30 (GEN) | 432 |
| 5962-9052604MUA | M | 08/27/2004 | 1 | TI | | Y | SMJ320C30HFGM40 | 432 |
| 5962-9052604MXA | M | 08/27/2004 | 1 | TI | | Y | SMJ320C30GBM40 | 432 |
| 5962-9052605Q9A | M | 08/27/2004 | 1 | TI | | Y | SMJ320C30KGDM50B | 432 |
| 5962-9052605MUA | M | 08/27/2004 | 1 | TI | | Y | SMJ320C30HFGM50 | 432 |
| 5962-9052605MXA | M | 08/27/2004 | 1 | TI | | Y | SMJ320C30GBM50 | 432 |
| 5962-9052605QXC | M | 08/27/2004 | 1 | TI | | Y | SMJ320C30GBM50 | 432 |
| 5962-9052701M3A | | 02/18/1993 | 3 | AUSTIN SEMI. | | Y | AS7968 | 599 |
| 5962-9052701MXA | | 02/18/1993 | | (NONE) | 08/02/1996 | | 7968-125V (GEN) | 599 |
| 5962-9052701QXA | | 02/18/1993 | 1 | AUSTIN SEMI. | | Y | AS796802BCA | 599 |
| 5962-9052801M3A | B | 06/19/1998 | 1 | AUSTIN SEMI. | | Y | AS7969EC28/883C | 590 |
| 5962-9052801Q7A | B | 06/19/1998 | 1 | AUSTIN SEMI. | | Y | AS7969ECJ28/883C | 590 |
| 5962-9052801MXA | B | 06/19/1998 | | (NONE) | 08/02/1996 | | 7969-125V (GEN) | 590 |
| 5962-9052801QXA | B | 06/19/1998 | 1 | AUSTIN SEMI. | | Y | AS796902BCA | 590 |
| 5962-90535012A | A | 10/27/2000 | | (NONE) | | | OP64A (GEN) | 702 |
| 5962-9053501GA | A | 10/27/2000 | | (NONE) | | | OP64A (GEN) | 702 |
| 5962-9053501PA | A | 10/27/2000 | | (NONE) | | | OP64A (GEN) | 702 |
| 5962-90536012A | A | 06/20/2001 | | (NONE) | 10/15/2003 | | OP260A (GEN) | 710 |
| 5962-9053601GA | A | 06/20/2001 | | (NONE) | 10/15/2003 | | OP260A (GEN) | 710 |
| 5962-9053601PA | A | 06/20/2001 | | (NONE) | 10/15/2003 | | OP260A (GEN) | 710 |
| 5962-9053701VCA | C | 04/03/2003 | 1 | ANALOG (5) | | Y | AD534TD/QMLV | 899 |
| 5962-9053701VIA | C | 04/03/2003 | 1 | ANALOG (5) | | Y | AD534TH/QMLV | 899 |
| 5962-90538012A | D | 06/11/2003 | 1 | TI | | Y | UC1611L/883B | 791 |
| 5962-9053801V2A | D | 06/11/2003 | 1 | TI | | Y | UC1611LQMLV | 791 |
| 5962-9053801PA | D | 06/11/2003 | 1 | TI | | Y | UC1611J/883B | 791 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9053801VPA | D | 06/11/2003 | 1 | TI | | Y | UC1611JQMLV | 791 |
| 5962-90541012A | A | 08/25/2004 | | (NONE) | | | 54LS183 (GEN) | 204 |
| 5962-9054101CA | A | 08/25/2004 | 1 | AUSTIN SEMI. | | Y | AS54LS183C/883C | 204 |
| 5962-9054101DA | A | 08/25/2004 | | (NONE) | | | 54LS183 (GEN) | 204 |
| 5962-9054301MQA | B | 02/17/1995 | | (NONE) | 03/25/2001 | | 82C37A-5 (GEN) | 423 |
| 5962-9054301MXA | B | 02/17/1995 | | (NONE) | | | 82C37A-5 (GEN) | 423 |
| 5962-9054302MQA | B | 02/17/1995 | 1 | INTERSIL | | Y | MD82C37A | 423 |
| 5962-9054302MXA | B | 02/17/1995 | | (NONE) | 03/25/2001 | | 82C37A (GEN) | 423 |
| 5962-9054303MQA | B | 02/17/1995 | | (NONE) | 03/25/2001 | | 82C37A-12 (GEN) | 423 |
| 5962-9054303MXA | B | 02/17/1995 | | (NONE) | | | 82C37A-12 (GEN) | 423 |
| 5962-9054304MQA | B | 02/17/1995 | | (NONE) | | | 82C237 (GEN) | 423 |
| 5962-9054304MXA | B | 02/17/1995 | | (NONE) | | | 82C237 (GEN) | 423 |
| 5962-9054305MQA | B | 02/17/1995 | | (NONE) | | | 82C237-12 (GEN) | 423 |
| 5962-9054305MXA | B | 02/17/1995 | | (NONE) | 03/25/2001 | | 82C237-12 (GEN) | 423 |
| 5962-9054401MXA | A | 10/07/2003 | | (NONE) | | | HPC16003 (GEN) | 420 |
| 5962-9054401MYC | A | 10/07/2003 | | (NONE) | | | HPC16003 (GEN) | 420 |
| 5962-9054402MXA | A | 10/07/2003 | | (NONE) | | | HPC16083 (GEN) | 420 |
| 5962-9054402MYC | A | 10/07/2003 | | (NONE) | | | HPC16083 (GEN) | 420 |
| 5962-9054501RA | | 07/21/1992 | | (NONE) | 03/30/2001 | | LTC1045MJ/883 | 599 |
| 5962-9054801MQA | A | 02/10/1995 | | (NONE) | | | L5380 (GEN) | 420 |
| 5962-9054801MXA | A | 02/10/1995 | | (NONE) | | | L5380 (GEN) | 420 |
| 5962-9054802MXA | A | 02/10/1995 | | (NONE) | | | L53C80 (GEN) | 420 |
| 5962-9054802MYA | A | 02/10/1995 | | (NONE) | | | L53C80 (GEN) | 420 |
| 5962-9054901MQA | B | 08/05/2003 | 2 | INTERSIL | | Y | HD1-15531/883 | 441 |
| 5962-9054902MQA | B | 08/05/2003 | | (NONE) | | | HD1-15531B (GEN) | 441 |
| 5962-9055101XA | D | 11/06/2002 | 1 | DDC | | Y | SDC14567-141 | 594 |
| 5962-9055101XA | D | 11/06/2002 | 1 | DDC IRELAND | | Y | SDC14567-141 | 594 |
| 5962-9055101XC | D | 11/06/2002 | 1 | DDC | | Y | SDC14567-111 | 594 |
| 5962-9055101XC | D | 11/06/2002 | 1 | DDC IRELAND | | Y | SDC14567-111 | 594 |
| 5962-9055101YA | D | 11/06/2002 | | (NONE) | | | SDC14567 (GEN) | 594 |
| 5962-9055102XA | D | 11/06/2002 | 1 | DDC | | Y | SDC14567-142 | 594 |
| 5962-9055102XA | D | 11/06/2002 | 1 | DDC IRELAND | | Y | SDC14567-142 | 594 |
| 5962-9055102XC | D | 11/06/2002 | 1 | DDC | | Y | SDC14567-112 | 594 |
| 5962-9055102XC | D | 11/06/2002 | 1 | DDC IRELAND | | Y | SDC14567-112 | 594 |
| 5962-9055102YA | D | 11/06/2002 | | (NONE) | | | SDC14567 (GEN) | 594 |
| 5962-9055103XA | D | 11/06/2002 | 1 | DDC | | Y | SDC14567-144 | 594 |
| 5962-9055103XA | D | 11/06/2002 | 1 | DDC IRELAND | | Y | SDC14567-144 | 594 |
| 5962-9055103XC | D | 11/06/2002 | 1 | DDC | | Y | SDC14567-114 | 594 |
| 5962-9055103XC | D | 11/06/2002 | 1 | DDC IRELAND | | Y | SDC14567-114 | 594 |
| 5962-9055103YA | D | 11/06/2002 | | (NONE) | | | SDC14567 (GEN) | 594 |
| 5962-9055104XA | D | 11/06/2002 | 1 | DDC | | Y | SDC14567-145 | 594 |
| 5962-9055104XA | D | 11/06/2002 | 1 | DDC IRELAND | | Y | SDC14567-145 | 594 |
| 5962-9055104XC | D | 11/06/2002 | 1 | DDC | | Y | SDC14567-115 | 594 |
| 5962-9055104XC | D | 11/06/2002 | 1 | DDC IRELAND | | Y | SDC14567-115 | 594 |
| 5962-9055104YA | D | 11/06/2002 | | (NONE) | | | SDC14567 (GEN) | 594 |
| 5962-9055105XA | D | 11/06/2002 | 1 | DDC | | Y | SDC14569-141 | 594 |
| 5962-9055105XA | D | 11/06/2002 | 1 | DDC IRELAND | | Y | SDC14569-141 | 594 |
| 5962-9055105XC | D | 11/06/2002 | 1 | DDC | | Y | SDC14569-111 | 594 |
| 5962-9055105XC | D | 11/06/2002 | 1 | DDC IRELAND | | Y | SDC14569-111 | 594 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9055105YA | D | 11/06/2002 | | (NONE) | | | SDC14569 (GEN) | 594 |
| 5962-9055106XA | D | 11/06/2002 | 1 | DDC | | Y | SDC14569-142 | 594 |
| 5962-9055106XA | D | 11/06/2002 | 1 | DDC IRELAND | | Y | SDC14569-142 | 594 |
| 5962-9055106XC | D | 11/06/2002 | 1 | DDC | | Y | SDC14569-112 | 594 |
| 5962-9055106XC | D | 11/06/2002 | 1 | DDC IRELAND | | Y | SDC14569-112 | 594 |
| 5962-9055106YA | D | 11/06/2002 | | (NONE) | | | SDC14569 (GEN) | 594 |
| 5962-9055107XA | D | 11/06/2002 | 1 | DDC | | Y | SDC14569-144 | 594 |
| 5962-9055107XA | D | 11/06/2002 | 1 | DDC IRELAND | | Y | SDC14569-144 | 594 |
| 5962-9055107XC | D | 11/06/2002 | 1 | DDC | | Y | SDC14569-114 | 594 |
| 5962-9055107XC | D | 11/06/2002 | 1 | DDC IRELAND | | Y | SDC14569-114 | 594 |
| 5962-9055107YA | D | 11/06/2002 | | (NONE) | | | SDC14569 (GEN) | 594 |
| 5962-9055108XA | D | 11/06/2002 | 1 | DDC | | Y | SDC14569-145 | 594 |
| 5962-9055108XA | D | 11/06/2002 | 1 | DDC IRELAND | | Y | SDC14569-145 | 594 |
| 5962-9055108XC | D | 11/06/2002 | 1 | DDC | | Y | SDC14569-115 | 594 |
| 5962-9055108XC | D | 11/06/2002 | 1 | DDC IRELAND | | Y | SDC14569-115 | 594 |
| 5962-9055108YA | D | 11/06/2002 | | (NONE) | | | SDC14569 (GEN) | 594 |
| 5962-9055301EA | | 10/23/1990 | 1 | TI | | Y | CD54HC40103F3A | 304 |
| 5962-9055401XA | C | 12/20/1996 | | (NONE) | | | HSDC-8915A (GEN) | 711 |
| 5962-9055401YA | C | 12/20/1996 | | (NONE) | | | XDC14507-628 (GEN) | 711 |
| 5962-9055402XA | C | 12/20/1996 | | (NONE) | | | HSDC-8915 (GEN) | 711 |
| 5962-9055402YA | C | 12/20/1996 | | (NONE) | | | XDC14507-627 (GEN) | 711 |
| 5962-90555013A | A | 02/21/2002 | | (NONE) | | | C20RA10-35 (GEN) | 431 |
| 5962-9055501KA | A | 02/21/2002 | | (NONE) | | | C20RA10-35 (GEN) | 431 |
| 5962-9055501LA | A | 02/21/2002 | | (NONE) | 08/05/2002 | | C20RA10-35 (GEN) | 431 |
| 5962-9055501XA | A | 02/21/2002 | | (NONE) | | | CG1690BA (GEN) | 431 |
| 5962-90555023A | A | 02/21/2002 | 2 | CYPRESS | 05/03/2004 | Y | PLDC20RA10-25LMB | 431 |
| 5962-9055502KA | A | 02/21/2002 | | (NONE) | | | C20RA10-25 (GEN) | 431 |
| 5962-9055502LA | A | 02/21/2002 | 2 | CYPRESS | 05/03/2004 | Y | PLDC20RA10-25DMB | 431 |
| 5962-9055502XA | A | 02/21/2002 | | (NONE) | | | CG1690AA (GEN) | 431 |
| 5962-90555033A | A | 02/21/2002 | 2 | CYPRESS | 05/03/2004 | Y | PLDC20RA10-20LMB | 431 |
| 5962-9055503KA | A | 02/21/2002 | | (NONE) | | | C20RA10-20 (GEN) | 431 |
| 5962-9055503LA | A | 02/21/2002 | 2 | CYPRESS | 05/03/2004 | Y | PLDC20RA10-20DMB | 431 |
| 5962-9055503XA | A | 02/21/2002 | | (NONE) | | | CG1690CA (GEN) | 431 |
| 5962-9055701EA | B | 08/22/2003 | 1 | TI | | Y | CD14538BF3A | 166 |
| 5962-9055702EA | B | 08/22/2003 | | (NONE) | 09/30/1995 | | 14538B (GEN) | 166 |
| 5962-9056101M2A | A | 08/13/1993 | | (NONE) | 09/30/1995 | | 10565 (GEN) | 345 |
| 5962-9056101MEA | A | 08/13/1993 | | (NONE) | 09/30/1995 | | 10565 (GEN) | 345 |
| 5962-9056101MFA | A | 08/13/1993 | | (NONE) | 09/30/1995 | | 10565 (GEN) | 345 |
| 5962-90562013A | | 02/26/1991 | 0 | TI | | | SNJ54AS250AFK | 270 |
| 5962-9056201KA | | 02/26/1991 | 0 | TI | | | SNJ54AS250AW | 270 |
| 5962-9056201LA | | 02/26/1991 | 0 | TI | | | SNJ54AS250AJT | 270 |
| 5962-90563012A | A | 04/14/1992 | 3 | TI | | | SNJ54AS756FK | 519 |
| 5962-9056301RA | A | 04/14/1992 | 3 | TI | | | SNJ54AS756J | 519 |
| 5962-9056301SA | A | 04/14/1992 | 3 | TI | | | SNJ54AS756W | 519 |
| 5962-9056401MA | C | 09/14/1994 | 3 | QP SEMI | | Y | 87C51RB/BMA | 420 |
| 5962-9056401TA | C | 09/14/1994 | | (NONE) | 04/15/1996 | | 87C51FB (GEN) | 420 |
| 5962-9056401UA | C | 09/14/1994 | | (NONE) | 12/24/1997 | | 87C51FB (GEN) | 420 |
| 5962-9056401XA | C | 09/14/1994 | 3 | QP SEMI | | Y | 87C51RB/BQA | 420 |
| 5962-9056401ZA | C | 09/14/1994 | | (NONE) | 04/15/1996 | | 87C51FB (GEN) | 420 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9056402MA | C | 09/14/1994 | 3 | QP SEMI | | Y | 87C51RB-16/BMA | 420 |
| 5962-9056402TA | C | 09/14/1994 | | (NONE) | 04/15/1996 | | 87C51FB (GEN) | 420 |
| 5962-9056402UA | C | 09/14/1994 | | (NONE) | 12/24/1997 | | 87C51FB (GEN) | 420 |
| 5962-9056402XA | C | 09/14/1994 | 3 | QP SEMI | | Y | 87C51RB-16/BQA | 420 |
| 5962-9056402ZA | C | 09/14/1994 | | (NONE) | 04/15/1996 | | 87C51FB (GEN) | 420 |
| 5962-9056403MA | C | 09/14/1994 | 1 | QP SEMI | | Y | 87C654/BMA | 420 |
| 5962-9056403XA | C | 09/14/1994 | 1 | QP SEMI | | Y | 87C654/BQA | 420 |
| 5962-9056404MA | C | 09/14/1994 | 1 | QP SEMI | | Y | 87C654-16/BMA | 420 |
| 5962-9056404XA | C | 09/14/1994 | 1 | QP SEMI | | Y | 87C654-16/BQA | 420 |
| 5962-9056405MA | C | 09/14/1994 | | (NONE) | | | 87C654OT (GEN) | 420 |
| 5962-9056405XA | C | 09/14/1994 | | (NONE) | | | 87C654OT (GEN) | 420 |
| 5962-9056406MA | C | 09/14/1994 | | (NONE) | 09/01/1997 | | 87C654-16 (GEN) | 420 |
| 5962-9056406XA | C | 09/14/1994 | | (NONE) | 09/01/1997 | | 87C654-16 (GEN) | 420 |
| 5962-90565012A | A | 11/22/1991 | | (NONE) | | | 54F3037 (GEN) | 500 |
| 5962-9056501EA | A | 11/22/1991 | | (NONE) | 09/01/1997 | | 54F3037 (GEN) | 500 |
| 5962-9056501FA | A | 11/22/1991 | | (NONE) | | | 54F3037 (GEN) | 500 |
| 5962-9056701MPA | | 12/16/1994 | | (NONE) | 12/31/2000 | | SP8804 (GEN) | 219 |
| 5962-9056801CA | B | 07/17/2000 | | (NONE) | 03/30/2001 | | OP-237A (GEN) | 710 |
| 5962-9056802CA | B | 07/17/2000 | | (NONE) | 03/30/2001 | | OP-237C (GEN) | 710 |
| 5962-90569012A | A | 07/05/2001 | 1 | SILICONIX | | Y | DG401AZ/883 | 181 |
| 5962-9056901EA | A | 07/05/2001 | 1 | SILICONIX | | Y | DG401AK/883 | 181 |
| 5962-9057001HXA | A | 02/09/1993 | | (NONE) | 01/31/2003 | | MN3860 (GEN) | 591 |
| 5962-9057101HXA | | 05/11/1993 | 1 | MICRO NETWKS | | Y | MN7130H/B | 818 |
| 5962-9057101HXC | | 05/11/1993 | 1 | MICRO NETWKS | | Y | MN7130H/B | 818 |
| 5962-9057301LA | | 08/23/1991 | | (NONE) | | | 10E301 (GEN) | 431 |
| 5962-9057301XA | | 08/23/1991 | | (NONE) | | | 10E301 (GEN) | 431 |
| 5962-9057302LA | | 08/23/1991 | | (NONE) | | | 10E302 (GEN) | 431 |
| 5962-9057302XA | | 08/23/1991 | | (NONE) | | | 10E302 (GEN) | 431 |
| 5962-9057401EA | | 09/20/1990 | 1 | TI | | Y | CD54HCT40102BF3A | 301 |
| 5962-9057701MEA | | 01/10/1994 | | (NONE) | 06/30/1996 | | SP8720 (GEN) | 319 |
| 5962-90582012A | | 12/15/1992 | | NATIONAL | | Y | 54F191LMQB | 304 |
| 5962-9058201EA | | 12/15/1992 | | NATIONAL | | Y | 54F191DMQB | 304 |
| 5962-9058201FA | | 12/15/1992 | | NATIONAL | | Y | 54F191FMQB | 304 |
| 5962-90585013A | A | 04/06/1992 | | (NONE) | | | 54F432 (GEN) | 342 |
| 5962-9058501KA | A | 04/06/1992 | | (NONE) | | | 54F432 (GEN) | 342 |
| 5962-9058501LA | A | 04/06/1992 | | (NONE) | | | 54F432 (GEN) | 342 |
| 5962-9058801M2A | | 08/31/1992 | | (NONE) | 09/30/1995 | | 10H750 (GEN) | 549 |
| 5962-9058801MEA | | 08/31/1992 | | (NONE) | 09/30/1995 | | 10H750 (GEN) | 549 |
| 5962-9058801MFA | | 08/31/1992 | | (NONE) | 09/30/1995 | | 10H750 (GEN) | 549 |
| 5962-9059001B2A | B | 08/09/2002 | | (NONE) | | | 54AC05 (GEN) | 143 |
| 5962-9059001M2A | B | 08/09/2002 | 3 | NATIONAL | | Y | 54AC05LMQB | 143 |
| 5962-9059001S2A | B | 08/09/2002 | | (NONE) | | | 54AC05 (GEN) | 143 |
| 5962R9059001B2A | B | 08/09/2002 | 3 | NATIONAL | | Y | JM54AC05B2A-RH | 143 |
| 5962R9059001S2A | B | 08/09/2002 | 3 | NATIONAL | | Y | JM54AC05S2A-RH | 143 |
| 5962-9059001BCA | B | 08/09/2002 | | (NONE) | | | 54AC05 (GEN) | 143 |
| 5962-9059001MCA | B | 08/09/2002 | 3 | NATIONAL | | Y | 54AC05DMQB | 143 |
| 5962-9059001SCA | B | 08/09/2002 | | (NONE) | | | 54AC05 (GEN) | 143 |
| 5962R9059001BCA | B | 08/09/2002 | 3 | NATIONAL | | Y | JM54AC05BCA-RH | 143 |
| 5962R9059001SCA | B | 08/09/2002 | 3 | NATIONAL | | Y | JM54AC05SCA-RH | 143 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9059001BDA | B | 08/09/2002 | | (NONE) | | | 54AC05 (GEN) | 143 |
| 5962-9059001MDA | B | 08/09/2002 | 3 | NATIONAL | | Y | 54AC05FMQB | 143 |
| 5962-9059001SDA | B | 08/09/2002 | | (NONE) | | | 54AC05 (GEN) | 143 |
| 5962R9059001BDA | B | 08/09/2002 | 3 | NATIONAL | | Y | JM54AC05BDA-RH | 143 |
| 5962R9059001SDA | B | 08/09/2002 | 3 | NATIONAL | | Y | JM54AC05SDA-RH | 143 |
| 5962R9059001SZA | B | 08/09/2002 | 3 | NATIONAL | | Y | JM54AC05SZA-RH | 143 |
| 5962-9059301M2A | | 02/06/1992 | | (NONE) | | | 54F402 (GEN) | 219 |
| 5962-9059301MEA | | 02/06/1992 | | (NONE) | | | 54F402 (GEN) | 219 |
| 5962-9059301MFA | | 02/06/1992 | | (NONE) | | | 54F402 (GEN) | 219 |
| 5962-9059401UA | A | 08/25/1995 | | (NONE) | | | | 620 |
| 5962-9059401XA | A | 08/25/1995 | | (NONE) | | | | 620 |
| 5962-9059401YA | A | 08/25/1995 | | (NONE) | | | | 620 |
| 5962-9059401ZA | A | 08/25/1995 | | (NONE) | | | | 620 |
| 5962-9059402UA | A | 08/25/1995 | | (NONE) | | | | 620 |
| 5962-9059402XA | A | 08/25/1995 | | (NONE) | 05/31/1998 | | 7C161A-35 (GEN) | 620 |
| 5962-9059402YA | A | 08/25/1995 | | (NONE) | | | | 620 |
| 5962-9059402ZA | A | 08/25/1995 | | (NONE) | | | | 620 |
| 5962-9059403UA | A | 08/25/1995 | | (NONE) | | | | 620 |
| 5962-9059403XA | A | 08/25/1995 | | (NONE) | 05/31/1998 | | 7C161A-25 (GEN) | 620 |
| 5962-9059403YA | A | 08/25/1995 | | (NONE) | | | | 620 |
| 5962-9059403ZA | A | 08/25/1995 | | (NONE) | | | | 620 |
| 5962-9059404UA | A | 08/25/1995 | | (NONE) | | | | 620 |
| 5962-9059404XA | A | 08/25/1995 | | (NONE) | 05/31/1998 | | 7C161A-20 (GEN) | 620 |
| 5962-9059404YA | A | 08/25/1995 | | (NONE) | | | | 620 |
| 5962-9059404ZA | A | 08/25/1995 | | (NONE) | | | | 620 |
| 5962-9059501GA | C | 11/14/2002 | | (NONE) | 03/30/2001 | | LT1019A-10 (GEN) | 782 |
| 5962-9059502GA | C | 11/14/2002 | | (NONE) | 12/31/2001 | | LT1019A-5 (GEN) | 785 |
| 5962-9059503GA | C | 11/14/2002 | | (NONE) | 03/30/2001 | | LT1019A-4.5 (GEN) | 785 |
| 5962-9059504GA | C | 11/14/2002 | 1 | MINCO | | Y | MTL1019A-2.5BCX | 785 |
| 5962-9059505GA | C | 11/14/2002 | | (NONE) | 03/30/2001 | | LT1019-10 (GEN) | 785 |
| 5962-9059506GA | C | 11/14/2002 | | (NONE) | 12/31/2001 | | LT1019-5 (GEN) | 785 |
| 5962-9059507GA | C | 11/14/2002 | | (NONE) | 03/30/2001 | | LT1019-4.5 (GEN) | 785 |
| 5962-9059508GA | C | 11/14/2002 | | (NONE) | 12/31/2001 | | LT1019-2.5 (GEN) | 785 |
| 5962-90596013A | | 10/03/1991 | | (NONE) | | | TDC1012 (GEN) | 591 |
| 5962-9059601JA | | 10/03/1991 | | (NONE) | | | TDC1012 (GEN) | 591 |
| 5962-90596023A | | 10/03/1991 | | (NONE) | | | TDC1012 (GEN) | 591 |
| 5962-9059602JA | | 10/03/1991 | | (NONE) | | | TDC1012 (GEN) | 591 |
| 5962-9059701MEA | | 04/25/1991 | | (NONE) | 06/01/2001 | | 54HCT4017 (GEN) | 319 |
| 5962-9060001PA | E | 04/16/2003 | 1 | NATIONAL | | Y | CLC410AJ-QML | 755 |
| 5962-9060201MRA | A | 07/18/2001 | 1 | SILICONIX | | Y | DG534AAP/883 | 199 |
| 5962-90603012A | A | 01/11/2000 | | (NONE) | | | REF43B (GEN) | 785 |
| 5962-9060301GA | A | 01/11/2000 | | (NONE) | | | REF43B (GEN) | 785 |
| 5962-9060301PA | A | 01/11/2000 | | (NONE) | | | REF43B (GEN) | 785 |
| 5962-90604012A | B | 06/03/1994 | | (NONE) | | | TLC274 (GEN) | 713 |
| 5962-9060401CA | B | 06/03/1994 | | (NONE) | | | TLC274 (GEN) | 713 |
| 5962-9060401DA | B | 06/03/1994 | | (NONE) | | | TLC274 (GEN) | 713 |
| 5962-90604022A | B | 06/03/1994 | | (NONE) | | | TLC279 (GEN) | 713 |
| 5962-9060402CA | B | 06/03/1994 | | (NONE) | | | TLC279 (GEN) | 713 |
| 5962-9060402DA | B | 06/03/1994 | | (NONE) | | | TLC279 (GEN) | 713 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-90604032A | B | 06/03/1994 | | (NONE) | | | TLC27M4 (GEN) | 713 |
| 5962-9060403CA | B | 06/03/1994 | | (NONE) | | | TLC27M4 (GEN) | 713 |
| 5962-9060403DA | B | 06/03/1994 | | (NONE) | | | TLC27M4 (GEN) | 713 |
| 5962-90604042A | B | 06/03/1994 | | (NONE) | | | TLC27M9 (GEN) | 713 |
| 5962-9060404CA | B | 06/03/1994 | | (NONE) | | | TLC27M9 (GEN) | 713 |
| 5962-9060404DA | B | 06/03/1994 | | (NONE) | | | TLC27M9 (GEN) | 713 |
| 5962-90604052A | B | 06/03/1994 | | (NONE) | | | TLC27L4 (GEN) | 713 |
| 5962-9060405CA | B | 06/03/1994 | | (NONE) | | | TLC27L4 (GEN) | 713 |
| 5962-9060405DA | B | 06/03/1994 | | (NONE) | | | TLC27L4 (GEN) | 713 |
| 5962-90604062A | B | 06/03/1994 | | (NONE) | | | TLC27L9 (GEN) | 713 |
| 5962-9060406CA | B | 06/03/1994 | | (NONE) | | | TLC27L9 (GEN) | 713 |
| 5962-9060406DA | B | 06/03/1994 | | (NONE) | | | TLC27L9 (GEN) | 713 |
| 5962-90606012A | A | 05/24/2000 | | (NONE) | | | 54F113 (GEN) | 156 |
| 5962-9060601CA | A | 05/24/2000 | | (NONE) | | | 54F113 (GEN) | 156 |
| 5962-9060601DA | A | 05/24/2000 | | (NONE) | | | 54F113 (GEN) | 156 |
| 5962-90606022A | A | 05/24/2000 | 1 | QP SEMI | | Y | 54F112/2A | 156 |
| 5962-9060602EA | A | 05/24/2000 | 1 | QP SEMI | | Y | 54F112/EA | 156 |
| 5962-9060602FA | A | 05/24/2000 | 1 | QP SEMI | | Y | 54F112/FA | 156 |
| 5962-9061101XA | A | 03/30/1992 | 1 | QP SEMI | | Y | CY7C344-35WMB | 431 |
| 5962-9061101YA | A | 03/30/1992 | 1 | QP SEMI | | Y | CY7C344-35HMB | 431 |
| 5962-9061102XA | A | 03/30/1992 | 1 | CYPRESS | 05/03/2004 | Y | CY7C344-25WMB | 431 |
| 5962-9061102XA | A | 03/30/1992 | 1 | QP SEMI | | Y | CY7C344-25WMB | 431 |
| 5962-9061102YA | A | 03/30/1992 | 1 | CYPRESS | 05/03/2004 | Y | CY7C344-25HMB | 431 |
| 5962-9061102YA | A | 03/30/1992 | 1 | QP SEMI | | Y | CY7C344-25HMB | 431 |
| 5962-90613012A | | 08/08/1990 | 1 | SARNOFF | | Y | GEM22601Q2A | 282 |
| 5962-90613012C | | 08/08/1990 | 1 | SARNOFF | | Y | GEM22601Q2C | 282 |
| 5962-9061301EA | | 08/08/1990 | 1 | SARNOFF | | Y | GEM22601QEA | 282 |
| 5962-9061301EC | | 08/08/1990 | 1 | SARNOFF | | Y | GEM22601QEC | 282 |
| 5962-9061301FA | | 08/08/1990 | 1 | SARNOFF | | Y | GEM22601QFA | 282 |
| 5962-9061301FC | | 08/08/1990 | 1 | SARNOFF | | Y | GEM22601QFC | 282 |
| 5962-9061601LA | A | 08/25/2004 | 3 | TI | | Y | SNJ54ALS29821JT | 164 |
| 5962-9061701MNA | B | 10/02/1998 | | (NONE) | | | MT4C4256 (GEN) | 625 |
| 5962-9061701MRA | B | 10/02/1998 | 3 | AUSTIN SEMI. | | Y | SMJ44C256-15JDM | 625 |
| 5962-9061701MTA | B | 10/02/1998 | | (NONE) | | | MT4C4256 (GEN) | 625 |
| 5962-9061701MUA | B | 10/02/1998 | 3 | AUSTIN SEMI. | | Y | SMJ44C256-15HKM | 625 |
| 5962-9061701MXA | B | 10/02/1998 | 3 | AUSTIN SEMI. | | Y | SMJ44C256-15HJM | 625 |
| 5962-9061701MYA | B | 10/02/1998 | 3 | AUSTIN SEMI. | | Y | SMJ44C256-15FQM | 625 |
| 5962-9061701MZA | B | 10/02/1998 | | (NONE) | | | | 625 |
| 5962-9061702MNA | B | 10/02/1998 | | (NONE) | | | MT4C4256 (GEN) | 625 |
| 5962-9061702MRA | B | 10/02/1998 | 3 | AUSTIN SEMI. | | Y | SMJ44C256-12JDM | 625 |
| 5962-9061702MTA | B | 10/02/1998 | | (NONE) | | | MT4C4256 (GEN) | 625 |
| 5962-9061702MUA | B | 10/02/1998 | 3 | AUSTIN SEMI. | | Y | SMJ44C256-12HKM | 625 |
| 5962-9061702MXA | B | 10/02/1998 | 3 | AUSTIN SEMI. | | Y | SMJ44C256-12HJM | 625 |
| 5962-9061702MYA | B | 10/02/1998 | 3 | AUSTIN SEMI. | | Y | SMJ44C256-12FQM | 625 |
| 5962-9061702MZA | B | 10/02/1998 | | (NONE) | | | | 625 |
| 5962-9061703MNA | B | 10/02/1998 | | (NONE) | | | MT4C4256 (GEN) | 625 |
| 5962-9061703MRA | B | 10/02/1998 | 3 | AUSTIN SEMI. | | Y | SMJ44C256-10JDM | 625 |
| 5962-9061703MTA | B | 10/02/1998 | | (NONE) | | | MT4C4256 (GEN) | 625 |
| 5962-9061703MUA | B | 10/02/1998 | 3 | AUSTIN SEMI. | | Y | SMJ44C256-10HKM | 625 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9061703MXA | B | 10/02/1998 | 3 | AUSTIN SEMI. | | Y | SMJ44C256-10HJM | 625 |
| 5962-9061703MYA | B | 10/02/1998 | 3 | AUSTIN SEMI. | | Y | SMJ44C256-10FQM | 625 |
| 5962-9061703MZA | B | 10/02/1998 | | (NONE) | | | | 625 |
| 5962-9061704MNA | B | 10/02/1998 | | (NONE) | | | MT4C4256 (GEN) | 625 |
| 5962-9061704MRA | B | 10/02/1998 | 3 | AUSTIN SEMI. | | Y | SMJ44C256-80JDM | 625 |
| 5962-9061704MTA | B | 10/02/1998 | | (NONE) | | | MT4C4256 (GEN) | 625 |
| 5962-9061704MUA | B | 10/02/1998 | 3 | AUSTIN SEMI. | | Y | SJM44C256-80HKM | 625 |
| 5962-9061704MXA | B | 10/02/1998 | 3 | AUSTIN SEMI. | | Y | SJM44C256-80HJM | 625 |
| 5962-9061704MYA | B | 10/02/1998 | 3 | AUSTIN SEMI. | | Y | SMJ44C256-80FQM | 625 |
| 5962-9061704MZA | B | 10/02/1998 | | (NONE) | | | 44C256-80 (GEN) | 625 |
| 5962-9061705MNA | B | 10/02/1998 | | (NONE) | | | MT4C4256 (GEN) | 625 |
| 5962-9061705MRA | B | 10/02/1998 | 3 | AUSTIN SEMI. | | Y | SMJ44C256-70JDM | 625 |
| 5962-9061705MTA | B | 10/02/1998 | | (NONE) | | | MT4C4256 (GEN) | 625 |
| 5962-9061705MUA | B | 10/02/1998 | 3 | AUSTIN SEMI. | | Y | SJM44C256-70HKM | 625 |
| 5962-9061705MXA | B | 10/02/1998 | 3 | AUSTIN SEMI. | | Y | SMJ44C256-70HJM | 625 |
| 5962-9061705MYA | B | 10/02/1998 | 3 | AUSTIN SEMI. | | Y | SMJ44C256-70FQM | 625 |
| 5962-9061705MZA | B | 10/02/1998 | | (NONE) | | | | 625 |
| 5962-9061706MNA | B | 10/02/1998 | 1 | AUSTIN SEMI. | | Y | AS4C4256F-15/883C | 625 |
| 5962-9061706MRA | B | 10/02/1998 | 1 | AUSTIN SEMI. | | Y | AS4C4256C-15/883C | 625 |
| 5962-9061706MYA | B | 10/02/1998 | 1 | AUSTIN SEMI. | | Y | AS4C4256EC-15/883C | 625 |
| 5962-9061707MNA | B | 10/02/1998 | 1 | AUSTIN SEMI. | | Y | AS4C4256F-12/883C | 625 |
| 5962-9061707MRA | B | 10/02/1998 | 1 | AUSTIN SEMI. | | Y | AS4C4256C-12/883C | 625 |
| 5962-9061707MYA | B | 10/02/1998 | 1 | AUSTIN SEMI. | | Y | AS4C4256EC-12/883C | 625 |
| 5962-9061708MNA | B | 10/02/1998 | 1 | AUSTIN SEMI. | | Y | AS4C4256F-10/883C | 625 |
| 5962-9061708MRA | B | 10/02/1998 | 1 | AUSTIN SEMI. | | Y | AS4C4256C-10/883C | 625 |
| 5962-9061708MYA | B | 10/02/1998 | 1 | AUSTIN SEMI. | | Y | AS4C4256EC-10/883C | 625 |
| 5962-9061709MNA | B | 10/02/1998 | 1 | AUSTIN SEMI. | | Y | AS4C4256F-80/883C | 625 |
| 5962-9061709MRA | B | 10/02/1998 | 1 | AUSTIN SEMI. | | Y | AS4C4256C-80/883C | 625 |
| 5962-9061709MYA | B | 10/02/1998 | 1 | AUSTIN SEMI. | | Y | AS4C4256EC-80/883C | 625 |
| 5962-9061710MNA | B | 10/02/1998 | 1 | AUSTIN SEMI. | | Y | AS4C4256F-70883C | 625 |
| 5962-9061710MRA | B | 10/02/1998 | 1 | AUSTIN SEMI. | | Y | AS4C4256C-70883C | 625 |
| 5962-9061710MYA | B | 10/02/1998 | 1 | AUSTIN SEMI. | | Y | AS4C4256EC-70883C | 625 |
| 5962-9061801MEA | | 11/06/1992 | | (NONE) | 06/30/1996 | | SP8647 (GEN) | 319 |
| 5962-9062001MUA | | 03/11/1993 | 2 | QP SEMI | | Y | CY7C132-55FMB | 616 |
| 5962-9062001MYA | | 03/11/1993 | 2 | QP SEMI | | Y | CY7C132-55DMB | 616 |
| 5962-9062001MZA | | 03/11/1993 | 2 | QP SEMI | | Y | CY7C132-55LMB | 616 |
| 5962-9062002MUA | | 03/11/1993 | 2 | QP SEMI | | Y | CY7C132-45FMB | 616 |
| 5962-9062002MYA | | 03/11/1993 | 2 | QP SEMI | | Y | CY7C132-45DMB | 616 |
| 5962-9062002MZA | | 03/11/1993 | 2 | QP SEMI | | Y | CY7C132-45LMB | 616 |
| 5962-9062003MUA | | 03/11/1993 | 2 | QP SEMI | | Y | CY7C132-35FMB | 616 |
| 5962-9062003MYA | | 03/11/1993 | 2 | QP SEMI | | Y | CY7C132-35DMB | 616 |
| 5962-9062003MZA | | 03/11/1993 | 2 | QP SEMI | | Y | CY7C132-35LMB | 616 |
| 5962-9062004MUA | | 03/11/1993 | | (NONE) | | | 7C142 (GEN) | 616 |
| 5962-9062004MYA | | 03/11/1993 | | (NONE) | 05/31/1998 | | 7C142-55 (GEN) | 616 |
| 5962-9062004MZA | | 03/11/1993 | | (NONE) | | | 7C142 (GEN) | 616 |
| 5962-9062005MUA | | 03/11/1993 | | (NONE) | | | 7C142 (GEN) | 616 |
| 5962-9062005MYA | | 03/11/1993 | | (NONE) | 05/31/1998 | | 7C142-45 (GEN) | 616 |
| 5962-9062005MZA | | 03/11/1993 | | (NONE) | | | 7C142 (GEN) | 616 |
| 5962-9062006MUA | | 03/11/1993 | | (NONE) | | | 7C142 (GEN) | 616 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9062006MYA | | 03/11/1993 | | (NONE) | 05/31/1998 | | 7C142-35 (GEN) | 616 |
| 5962-9062006MZA | | 03/11/1993 | | (NONE) | | | 7C142 (GEN) | 616 |
| 5962-9062007MXA | | 03/11/1993 | 2 | QP SEMI | | Y | CY7C136-55LMB | 616 |
| 5962-9062008MXA | | 03/11/1993 | 2 | QP SEMI | | Y | CY7C136-45LMB | 616 |
| 5962-9062009MXA | | 03/11/1993 | 2 | QP SEMI | | Y | CY7C136-35LMB | 616 |
| 5962-9062010MXA | | 03/11/1993 | | (NONE) | | | 7C146-55 (GEN) | 616 |
| 5962-9062011MXA | | 03/11/1993 | | (NONE) | | | 7C146-45 (GEN) | 616 |
| 5962-9062012MXA | | 03/11/1993 | | (NONE) | | | 7C146-35 (GEN) | 616 |
| 5962-9062201MMA | C | 07/20/1998 | 1 | AUSTIN SEMI. | | Y | MT4C1004JF-12 | 629 |
| 5962-9062201MNA | C | 07/20/1998 | 1 | AUSTIN SEMI. | | Y | MT4C1004JCZ-12 | 629 |
| 5962-9062201MTA | C | 07/20/1998 | 1 | AUSTIN SEMI. | | Y | MT4C1004JC-12 | 629 |
| 5962-9062201MUA | C | 07/20/1998 | 1 | AUSTIN SEMI. | | Y | MT4C1004JECN-12 | 629 |
| 5962-9062201MVA | C | 07/20/1998 | 1 | AUSTIN SEMI. | | Y | MT4C1004JCN-12 | 629 |
| 5962-9062201MXA | C | 07/20/1998 | | (NONE) | 11/01/1997 | | 44100-12HR (GEN) | 629 |
| 5962-9062201MYA | C | 07/20/1998 | 1 | AUSTIN SEMI. | | Y | MT4C1004JEC-12 | 629 |
| 5962-9062201MZA | C | 07/20/1998 | | (NONE) | | | | 629 |
| 5962-9062202MMA | C | 07/20/1998 | 1 | AUSTIN SEMI. | | Y | MT4C1004JF-10 | 629 |
| 5962-9062202MNA | C | 07/20/1998 | 1 | AUSTIN SEMI. | | Y | MT4C1004JCZ-10 | 629 |
| 5962-9062202MTA | C | 07/20/1998 | 3 | AUSTIN SEMI. | | Y | MT4C1004JC-10 | 629 |
| 5962-9062202MUA | C | 07/20/1998 | 1 | AUSTIN SEMI. | | Y | MT4C1004JECN-10 | 629 |
| 5962-9062202MVA | C | 07/20/1998 | 1 | AUSTIN SEMI. | | Y | MT4C1004JCN-10 | 629 |
| 5962-9062202MXA | C | 07/20/1998 | | (NONE) | 11/01/1997 | | 44100-10HR (GEN) | 629 |
| 5962-9062202MYA | C | 07/20/1998 | 1 | AUSTIN SEMI. | | Y | MT4C1004JEC-10 | 629 |
| 5962-9062202MZA | C | 07/20/1998 | | (NONE) | | | | 629 |
| 5962-9062203MMA | C | 07/20/1998 | 1 | AUSTIN SEMI. | | Y | MT4C1004JCZ-8 | 629 |
| 5962-9062203MNA | C | 07/20/1998 | 1 | AUSTIN SEMI. | | Y | MT4C1004JF-8 | 629 |
| 5962-9062203MTA | C | 07/20/1998 | 1 | AUSTIN SEMI. | | Y | MT4C1004JC-8 | 629 |
| 5962-9062203MUA | C | 07/20/1998 | 1 | AUSTIN SEMI. | | Y | MT4C1004JECN-8 | 629 |
| 5962-9062203MVA | C | 07/20/1998 | 1 | AUSTIN SEMI. | | Y | MT4C1004JCN-8 | 629 |
| 5962-9062203MXA | C | 07/20/1998 | | (NONE) | 11/01/1997 | | 44100-80HR (GEN) | 629 |
| 5962-9062203MYA | C | 07/20/1998 | 1 | AUSTIN SEMI. | | Y | MT4C1004JEC-8 | 629 |
| 5962-9062203MZA | C | 07/20/1998 | | (NONE) | | | | 629 |
| 5962-9062501M2A | | 10/11/1990 | 3 | TI | | Y | SNJ54BCT244FK | 529 |
| 5962-9062501MRA | | 10/11/1990 | 0 | TI | | Y | SNJ54BCT244J | 529 |
| 5962-9062501MSA | | 10/11/1990 | 3 | TI | | Y | SNJ54BCT244W | 529 |
| 5962-9062701GA | C | 04/17/2003 | 1 | MINCO | | Y | MTL1011AMH | 779 |
| 5962-9062701PA | C | 04/17/2003 | 1 | MINCO | | Y | MTL1011AMD8 | 779 |
| 5962-9062702GA | C | 04/17/2003 | 1 | MINCO | | Y | MTL1011MH | 779 |
| 5962-9062702PA | C | 04/17/2003 | 1 | MINCO | | Y | MTL1011MD8 | 779 |
| 5962-9062801RA | A | 05/06/1994 | | (NONE) | 09/15/1995 | | 55ALS056 (GEN) | 590 |
| 5962-9062801SA | A | 05/06/1994 | | (NONE) | 09/15/1995 | | 55ALS056 (GEN) | 590 |
| 5962-90629012A | A | 12/23/1991 | | (NONE) | 09/15/1995 | | 55ALS057 (GEN) | 590 |
| 5962-9062901RA | A | 12/23/1991 | | (NONE) | 09/15/1995 | | 55ALS057 (GEN) | 590 |
| 5962-9062901SA | A | 12/23/1991 | | (NONE) | 09/15/1995 | | 55ALS057 (GEN) | 590 |
| 5962-9063001HXA | | 02/03/1991 | | (NONE) | 09/01/2000 | | SP9760 (GEN) | 818 |
| 5962-9063101HXA | | 02/10/1992 | | (NONE) | 09/01/2000 | | SP9588 (GEN) | 592 |
| 5962-9063201M3A | A | 07/10/2001 | 1 | ANALOG (3) | | Y | AD7870TE/883B | 592 |
| 5962-9063201MLA | A | 07/10/2001 | 1 | ANALOG (3) | | Y | AD7870TQ/883B | 592 |
| 5962-9063301MCA | | 08/30/1991 | 1 | ANALOG (5) | | Y | AD713SQ/883B | 713 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9063302MCA | | 08/30/1991 | | (NONE) | | | AD713T (GEN) | 713 |
| 5962-9063401HXA | B | 04/23/2004 | 1 | DDC | | Y | DAC-02200II-609 | 591 |
| 5962-9063401HXC | B | 04/23/2004 | 1 | DDC | | Y | ADH-030II-12-1 | 591 |
| 5962-9063501M2A | A | 07/10/2001 | | (NONE) | | | ADG528A (GEN) | 193 |
| 5962-9063501MVA | A | 07/10/2001 | 1 | ANALOG (4) | | Y | ADG528ATQ/883B | 193 |
| 5962-9063502M2A | A | 07/10/2001 | 1 | ANALOG (3) | | Y | ADG529ATE/883B | 192 |
| 5962-9063502MVA | A | 07/10/2001 | 1 | ANALOG (3) | | Y | ADG529ATQ/883B | 192 |
| 5962-9063601HXA | | 01/28/1991 | | (NONE) | | | CT1820 (GEN) | 399 |
| 5962-9063601HYA | | 01/28/1991 | | (NONE) | | | CT1820 (GEN) | 399 |
| 5962-9063602HXA | | 01/28/1991 | | (NONE) | | | CT1820-2 (GEN) | 399 |
| 5962-9063602HYA | | 01/28/1991 | | (NONE) | | | CT1820-2 (GEN) | 399 |
| 5962-9063603HXA | | 01/28/1991 | 1 | AEROFLEX | | Y | ARX2410 | 399 |
| 5962-9063603HXC | | 01/28/1991 | 1 | AEROFLEX | | Y | ARX2410 | 399 |
| 5962-9063604HXA | | 01/28/1991 | 1 | AEROFLEX | | Y | ARX3410 | 399 |
| 5962-9063604HXC | | 01/28/1991 | 1 | AEROFLEX | | Y | ARX3410 | 399 |
| 5962-9063801HXA | C | 02/02/2001 | 1 | APEX MICRO. | | Y | PA07M/883 | 724 |
| 5962-9063901M3A | | 12/14/1993 | | (NONE) | 06/01/1997 | | 54F543 (GEN) | 590 |
| 5962-9063901MKA | | 12/14/1993 | | (NONE) | 09/01/1997 | | 54F543 (GEN) | 590 |
| 5962-9063901MLA | | 12/14/1993 | | (NONE) | 06/01/1997 | | 54F543 (GEN) | 590 |
| 5962-9064001CA | C | 08/22/2003 | 1 | TI | | Y | CD4016BF3A | 199 |
| 5962-9064002CA | C | 08/22/2003 | | (NONE) | | | 14016B (GEN) | 199 |
| 5962-9064201Q2A | A | 05/22/2002 | | (NONE) | 09/15/1995 | | TLC1541 (GEN) | 592 |
| 5962-9064201QRA | A | 05/22/2002 | | (NONE) | 09/15/1995 | | TLC1541 (GEN) | 592 |
| 5962-9064202Q2A | A | 05/22/2002 | 2 | TI | 06/30/2004 | Y | TLC1542MFKB | 592 |
| 5962-9064202QRA | A | 05/22/2002 | 2 | TI | 06/30/2004 | Y | TLC1542MJB | 592 |
| 5962-9064401MRA | A | 01/23/1996 | | (NONE) | 09/01/1997 | | 605 (GEN) | 899 |
| 5962-9064401MXA | A | 01/23/1996 | | (NONE) | 09/01/1997 | | 605 (GEN) | 899 |
| 5962-9064401NYA | A | 01/23/1996 | | (NONE) | | | 605 (GEN) | 899 |
| 5962-9064402NYA | A | 01/23/1996 | | (NONE) | | | 605 (GEN) | 899 |
| 5962-90649012A | B | 05/30/1995 | | (NONE) | | | LTC1064-4 (GEN) | 805 |
| 5962-9064901CA | B | 05/30/1995 | | (NONE) | 03/30/2001 | | LTC1064-4 (GEN) | 805 |
| 5962-9064901XA | B | 05/30/1995 | | (NONE) | 03/30/2001 | | LTC1064-4 (GEN) | 805 |
| 5962-90650012A | B | 01/07/2003 | | (NONE) | 12/31/2001 | | UC1835 (GEN) | 899 |
| 5962-9065001PA | B | 01/07/2003 | | (NONE) | 12/31/2001 | | UC1835 (GEN) | 899 |
| 5962-90650022A | B | 01/07/2003 | 1 | TI | | Y | UC1836L/883BC | 899 |
| 5962-9065002PA | B | 01/07/2003 | 1 | TI | | Y | UC1836J/883BC | 899 |
| 5962-9065101MCA | | 04/24/1991 | 1 | TI | | Y | CD54HCT126F3A | 520 |
| 5962-9065201MEA | | 04/19/1991 | 1 | TI | | Y | CD54HCT151F3A | 272 |
| 5962-9065401MEA | | 12/30/1991 | | TI | | Y | CD54HCT4051F3A | 193 |
| 5962-9065601MQA | | 11/04/1991 | | (NONE) | 12/24/1997 | | 80C28710 (GEN) | 409 |
| 5962-9065701MXC | | 05/19/1993 | 1 | QP SEMI | | | Z16C3010GMB | 420 |
| 5962-90658013A | | 09/11/1992 | 1 | QP SEMI | | | WS57C43C-70-CMB | 659 |
| 5962-90658013C | | 09/11/1992 | 1 | QP SEMI | | | WS57C43C-70-CMB | 659 |
| 5962-9065801JA | | 09/11/1992 | 1 | QP SEMI | | | WS57C43C-70-DMB | 659 |
| 5962-9065801JC | | 09/11/1992 | 1 | QP SEMI | | | WS57C43C-70-DMB | 659 |
| 5962-9065801KA | | 09/11/1992 | 1 | QP SEMI | | | WS57C43C-70-FMB | 659 |
| 5962-9065801KC | | 09/11/1992 | 1 | QP SEMI | | | WS57C43C-70-FMB | 659 |
| 5962-9065801LA | | 09/11/1992 | 1 | QP SEMI | | | WS57C43C-70-TMB | 659 |
| 5962-9065801LC | | 09/11/1992 | 1 | QP SEMI | | | WS57C43C-70-TMB | 659 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-90658023A | | 09/11/1992 | 1 | QP SEMI | | | WS57C43C-55-CMB | 659 |
| 5962-90658023C | | 09/11/1992 | 1 | QP SEMI | | | WS57C43C-55-CMB | 659 |
| 5962-9065802JA | | 09/11/1992 | 1 | QP SEMI | | | WS57C43C-55-DMB | 659 |
| 5962-9065802JC | | 09/11/1992 | 1 | QP SEMI | | | WS57C43C-55-DMB | 659 |
| 5962-9065802KA | | 09/11/1992 | 1 | QP SEMI | | | WS57C43C-55-FMB | 659 |
| 5962-9065802KC | | 09/11/1992 | 1 | QP SEMI | | | WS57C43C-55-FMB | 659 |
| 5962-9065802LA | | 09/11/1992 | 1 | QP SEMI | | | WS57C43C-55-TMB | 659 |
| 5962-9065802LC | | 09/11/1992 | 1 | QP SEMI | | | WS57C43C-55-TMB | 659 |
| 5962-90658033A | | 09/11/1992 | 1 | QP SEMI | | | WS57C43C-45-CMB | 659 |
| 5962-90658033C | | 09/11/1992 | 1 | QP SEMI | | | WS57C43C-45-CMB | 659 |
| 5962-9065803JA | | 09/11/1992 | 1 | QP SEMI | | | WS57C43C-45-DMB | 659 |
| 5962-9065803JC | | 09/11/1992 | 1 | QP SEMI | | | WS57C43C-45-DMB | 659 |
| 5962-9065803KA | | 09/11/1992 | 1 | QP SEMI | | | WS57C43C-45-FMB | 659 |
| 5962-9065803KC | | 09/11/1992 | 1 | QP SEMI | | | WS57C43C-45-FMB | 659 |
| 5962-9065803LA | | 09/11/1992 | 1 | QP SEMI | | | WS57C43C-45-TMB | 659 |
| 5962-9065803LC | | 09/11/1992 | 1 | QP SEMI | | | WS57C43C-45-TMB | 659 |
| 5962-90658043A | | 09/11/1992 | 1 | QP SEMI | | | WS57C43C-35-CMB | 659 |
| 5962-90658043C | | 09/11/1992 | 1 | QP SEMI | | | WS57C43C-35-CMB | 659 |
| 5962-9065804JA | | 09/11/1992 | 1 | QP SEMI | | | WS57C43C-35-DMB | 659 |
| 5962-9065804JC | | 09/11/1992 | 1 | QP SEMI | | | WS57C43C-35-DMB | 659 |
| 5962-9065804KA | | 09/11/1992 | 1 | QP SEMI | | | WS57C43C-35-FMB | 659 |
| 5962-9065804KC | | 09/11/1992 | 1 | QP SEMI | | | WS57C43C-35-FMB | 659 |
| 5962-9065804LA | | 09/11/1992 | 1 | QP SEMI | | | WS57C43C-35-TMB | 659 |
| 5962-9065804LC | | 09/11/1992 | 1 | QP SEMI | | | WS57C43C-35-TMB | 659 |
| 5962-9065901HXA | E | 05/20/2002 | 1 | APEX MICRO. | | Y | PA12M/883 | 724 |
| 5962-9065901HXA | E | 05/20/2002 | 1 | MICROPAC | | Y | MIOP42109/883 | 724 |
| 5962-9065901HXC | E | 05/20/2002 | 1 | MICROPAC | | Y | MIOP42109/883 | 724 |
| 5962-9066101MPA | | 01/18/1994 | | (NONE) | 12/31/2000 | | SP8802 (GEN) | 309 |
| 5962-9066401MXA | | 12/09/1992 | | (NONE) | | | 7C191-45 (GEN) | 623 |
| 5962-9066401MYA | | 12/09/1992 | | (NONE) | | | 7C191-45 (GEN) | 623 |
| 5962-9066401MZA | | 12/09/1992 | | (NONE) | | | 7C191-45 (GEN) | 623 |
| 5962-9066402MXA | | 12/09/1992 | | (NONE) | | | 7C191-35 (GEN) | 623 |
| 5962-9066402MYA | | 12/09/1992 | | (NONE) | | | 7C191-35 (GEN) | 623 |
| 5962-9066402MZA | | 12/09/1992 | | (NONE) | | | 7C191-35 (GEN) | 623 |
| 5962-9066403MXA | | 12/09/1992 | | (NONE) | | | 7C191-25 (GEN) | 623 |
| 5962-9066403MYA | | 12/09/1992 | | (NONE) | | | 7C191-25 (GEN) | 623 |
| 5962-9066403MZA | | 12/09/1992 | | (NONE) | | | 7C191-25 (GEN) | 623 |
| 5962-9066501M2A | | 03/06/1992 | 0 | TI | | Y | SNJ54ALS137AFK | 282 |
| 5962-9066501MEA | | 03/06/1992 | 0 | TI | | Y | SNJ54ALS137AJ | 282 |
| 5962-9066501MFA | | 03/06/1992 | 0 | TI | | Y | SNJ54ALS137AW | 282 |
| 5962-9066601HXA | A | 01/12/1994 | | (NONE) | | | AD9005B (GEN) | 592 |
| 5962-9066901M2A | | 04/07/1992 | | (NONE) | 09/01/1996 | | 54FCT193 (GEN) | 304 |
| 5962-9066901MEA | | 04/07/1992 | | (NONE) | 09/01/1996 | | 54FCT193 (GEN) | 304 |
| 5962-9066901MFA | | 04/07/1992 | | (NONE) | 09/01/1996 | | 54FCT193 (GEN) | 304 |
| 5962-9066902M2A | | 04/07/1992 | | (NONE) | 09/01/1996 | | 54FCT193A (GEN) | 304 |
| 5962-9066902MEA | | 04/07/1992 | | (NONE) | 09/01/1996 | | 54FCT193A (GEN) | 304 |
| 5962-9066902MFA | | 04/07/1992 | | (NONE) | 09/01/1996 | | 54FCT193A (GEN) | 304 |
| 5962-9067101MRA | B | 04/25/2003 | 1 | ANALOG (2) | | Y | AD598SD/883B | 899 |
| 5962-9067501M3A | B | 09/02/2004 | 3 | TI | | | SNJ54ALS29823FK | 164 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9067501MKA | B | 09/02/2004 | 3 | TI | | | SNJ54ALS29823W | 164 |
| 5962-9067501MLA | B | 09/02/2004 | 3 | TI | | | SNJ54ALS29823JT | 164 |
| 5962-9067502M3A | B | 09/02/2004 | | (NONE) | | | 54ALS29824 (GEN) | 164 |
| 5962-9067502MKA | B | 09/02/2004 | | (NONE) | | | 54ALS29824 (GEN) | 164 |
| 5962-9067502MLA | B | 09/02/2004 | | (NONE) | | | 54ALS29824 (GEN) | 164 |
| 5962-9067801MXC | | 08/05/1992 | | (NONE) | 03/25/2001 | | 80C286-10 (GEN) | 403 |
| 5962-9067801MYA | | 08/05/1992 | | (NONE) | 12/24/1997 | | 80C286-10 (GEN) | 403 |
| 5962-9067802MXC | | 08/05/1992 | | (NONE) | 03/25/2001 | | 80C286-12 (GEN) | 403 |
| 5962-9067901HXA | C | 03/13/2001 | 1 | APEX MICRO. | | Y | PA02M/883 | 724 |
| 5962-9068601QCA | | 06/03/1999 | 1 | TI | | Y | CD54ACT05F3A | 143 |
| 5962-9068701Q2A | C | 02/25/2004 | 2 | TI | | Y | SNJ54ACT86FK | 140 |
| 5962-9068701QCA | C | 02/25/2004 | 2 | TI | | Y | SNJ54ACT86J | 140 |
| 5962-9068701QDA | C | 02/25/2004 | 2 | TI | | Y | SNJ54ACT86W | 140 |
| 5962-9068702QXA | C | 02/25/2004 | 2 | STMICRO | | Y | 54ACT86K02Q | 140 |
| 5962-9068702QXC | C | 02/25/2004 | 2 | STMICRO | | Y | 54ACT86K01Q | 140 |
| 5962-9068702VXA | C | 02/25/2004 | 2 | STMICRO | | Y | 54ACT86K02V | 140 |
| 5962-9068702VXC | C | 02/25/2004 | 2 | STMICRO | | Y | 54ACT86K01V | 140 |
| 5962F9068702QXA | C | 02/25/2004 | 2 | STMICRO | | Y | RHFACT86K02Q | 140 |
| 5962F9068702QXC | C | 02/25/2004 | 2 | STMICRO | | Y | RHFACT86K01Q | 140 |
| 5962F9068702VXA | C | 02/25/2004 | 2 | STMICRO | | Y | RHFACT86K02V | 140 |
| 5962F9068702VXC | C | 02/25/2004 | 2 | STMICRO | | Y | RHFACT86K01V | 140 |
| 5962-9068901MEA | A | 07/18/2001 | 1 | SILICONIX | | Y | DG189AP/883 | 186 |
| 5962-9069201MXA | C | 10/29/1996 | | (NONE) | 12/24/1997 | | 87C196KC (GEN) | 420 |
| 5962-9069201MYA | C | 10/29/1996 | | (NONE) | 12/24/1997 | | 87C196KC (GEN) | 420 |
| 5962-9069202QXA | C | 10/29/1996 | | (NONE) | 12/24/1997 | | 87C196KD (GEN) | 420 |
| 5962-9069202QYA | C | 10/29/1996 | | (NONE) | 12/24/1997 | | 87C196KD (GEN) | 420 |
| 5962-9069203QXA | C | 10/29/1996 | | (NONE) | 12/24/1997 | | 87C196KD (GEN) | 420 |
| 5962-9069203QYA | C | 10/29/1996 | | (NONE) | 12/24/1997 | | 87C196KD (GEN) | 420 |
| 5962-9069204QXA | C | 10/29/1996 | | (NONE) | 12/24/1997 | | 87C196KC (GEN) | 420 |
| 5962-9069204QYA | C | 10/29/1996 | | (NONE) | 12/24/1997 | | 87C196KC (GEN) | 420 |
| 5962-9069301MCA | C | 08/30/2000 | | (NONE) | 03/30/2001 | | LTC1064-1 (GEN) | 805 |
| 5962-9069302MCA | C | 08/30/2000 | | (NONE) | 03/30/2001 | | LTC1064-1A (GEN) | 805 |
| 5962-9069501M3A | | 03/19/1991 | | (NONE) | | | 54ALS29825 (GEN) | 421 |
| 5962-9069501MKA | | 03/19/1991 | | (NONE) | | | 54ALS29825 (GEN) | 421 |
| 5962-9069501MLA | | 03/19/1991 | | (NONE) | | | 54ALS29825 (GEN) | 421 |
| 5962-9069601MKA | | 03/04/1993 | | (NONE) | | | 7C123 (GEN) | 608 |
| 5962-9069601MLA | | 03/04/1993 | | (NONE) | | | 7C123-15 (GEN) | 608 |
| 5962-9069601MXA | | 03/04/1993 | | (NONE) | | | 7C123 (GEN) | 608 |
| 5962-9069602MKA | | 03/04/1993 | | (NONE) | | | 7C123 (GEN) | 608 |
| 5962-9069602MLA | | 03/04/1993 | | (NONE) | | | 7C123-12 (GEN) | 608 |
| 5962-9069602MXA | | 03/04/1993 | | (NONE) | | | 7C123 (GEN) | 608 |
| 5962-9069603MKA | | 03/04/1993 | | (NONE) | | | 7C123 (GEN) | 608 |
| 5962-9069603MLA | | 03/04/1993 | | (NONE) | | | 7C123-10 (GEN) | 608 |
| 5962-9069603MXA | | 03/04/1993 | | (NONE) | | | 7C123 (GEN) | 608 |
| 5962-9070101MEA | | 04/25/1991 | 1 | TI | | Y | CD54HCT109F3A | 152 |
| 5962-9070201MEA | | 04/25/1991 | 1 | TI | | Y | CD54HCT157F3A | 275 |
| 5962-9070301MEA | | 04/24/1991 | 1 | TI | | Y | CD54HCT158F3A | 275 |
| 5962-9070401QXA | | 05/15/1990 | | (NONE) | | | WEDSP-16 (GEN) | 432 |
| 5962-9070501MEA | | 04/30/1991 | 1 | TI | | Y | CD54HCT160F3A | 300 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9070601MEA | | 04/24/1991 | 1 | TI | | Y | CD54HCT367F3A | 590 |
| 5962-9070701HXA | F | 12/20/1996 | | (NONE) | | | SDC14500-635 (GEN) | 594 |
| 5962-9070701HYA | F | 12/20/1996 | | (NONE) | | | HSDC-8917II-1A (GEN) | 594 |
| 5962-9070702HXA | F | 12/20/1996 | | (NONE) | | | SDC14500-636 (GEN) | 594 |
| 5962-9070702HYA | F | 12/20/1996 | | (NONE) | | | HSDC-8917II-1 (GEN) | 594 |
| 5962-9070703HXA | F | 12/20/1996 | | (NONE) | | | SDC14502-605 (GEN) | 594 |
| 5962-9070703HYA | F | 12/20/1996 | | (NONE) | | | HSDC-8919II-1A (GEN) | 594 |
| 5962-9070704HXA | F | 12/20/1996 | | (NONE) | | | SDC14502-606 (GEN) | 594 |
| 5962-9070704HYA | F | 12/20/1996 | | (NONE) | | | HSDC-8919II-1 (GEN) | 594 |
| 5962-9070705HXC | F | 12/20/1996 | | (NONE) | | | 1024-C672H/2 (GEN) | 594 |
| 5962-9070706HXC | F | 12/20/1996 | | (NONE) | | | 1024-C673H/2 (GEN) | 594 |
| 5962-9070707HXC | F | 12/20/1996 | | (NONE) | | | 1024-C674H/2 (GEN) | 594 |
| 5962-9070708HXC | F | 12/20/1996 | | (NONE) | | | 1024-C675H/2 (GEN) | 594 |
| 5962-9070801XA | A | 09/25/1996 | | (NONE) | | | TMC2208 (GEN) | 208 |
| 5962-9071001M3A | | 03/09/1992 | | (NONE) | | | 54ALS29842 (GEN) | 342 |
| 5962-9071001MKA | | 03/09/1992 | | (NONE) | | | 54ALS29842 (GEN) | 342 |
| 5962-9071001MLA | | 03/09/1992 | | (NONE) | | | 54ALS29842 (GEN) | 342 |
| 5962-9071101M2C | A | 06/29/2004 | 1 | MAXIM INTEG. | | | MAX691MLP/883B | 429 |
| 5962-9071101MEA | A | 06/29/2004 | 1 | MAXIM INTEG. | | | MAX691MJE/883B | 429 |
| 5962-9071102M2C | A | 06/29/2004 | 1 | MAXIM INTEG. | | | MAX693MLP/883B | 429 |
| 5962-9071102MEA | A | 06/29/2004 | 1 | MAXIM INTEG. | | | MAX693MJE/883B | 429 |
| 5962-9071103MEA | A | 06/29/2004 | 1 | MAXIM INTEG. | | | MAX695MJE/883B | 429 |
| 5962-9071201M2C | D | 07/19/2004 | 1 | MAXIM INTEG. | | | MAX690MLP/883B | 429 |
| 5962-9071201MHA | D | 07/19/2004 | | (NONE) | | | MAX690 (GEN) | 429 |
| 5962-9071201MPA | D | 07/19/2004 | 1 | MAXIM INTEG. | | | MAX690MJA/883B | 429 |
| 5962-9071201MXC | D | 07/19/2004 | 1 | MAXIM INTEG. | | | MAX690MFB/883B | 429 |
| 5962-9071202M2C | D | 07/19/2004 | 1 | MAXIM INTEG. | | | MAX692MLP/883B | 429 |
| 5962-9071202MHA | D | 07/19/2004 | | (NONE) | | | MAX692 (GEN) | 429 |
| 5962-9071202MPA | D | 07/19/2004 | 1 | MAXIM INTEG. | | | MAX692MJA/883B | 429 |
| 5962-9071202MXC | D | 07/19/2004 | 1 | MAXIM INTEG. | | | MAX692MFB/883B | 429 |
| 5962-9071203M2C | D | 07/19/2004 | 1 | MAXIM INTEG. | | | MAX694MLP/883B | 429 |
| 5962-9071203MHA | D | 07/19/2004 | | (NONE) | | | MAX694 (GEN) | 429 |
| 5962-9071203MPA | D | 07/19/2004 | 1 | MAXIM INTEG. | | | MAX694MJA/883B | 429 |
| 5962-9071203MXC | D | 07/19/2004 | 1 | MAXIM INTEG. | | | MAX694MFB/883B | 429 |
| 5962-9071501MUA | A | 02/12/2001 | 3 | QP SEMI | | Y | CY7C433-120DMB | 670 |
| 5962-9071501MXA | A | 02/12/2001 | 3 | QP SEMI | | Y | CY7C432-120DMB | 670 |
| 5962-9071501MYA | A | 02/12/2001 | 3 | QP SEMI | | Y | CY7C433-120KMB | 670 |
| 5962-9071501MZA | A | 02/12/2001 | 3 | QP SEMI | | Y | CY7C433-120LMB | 670 |
| 5962-9071502MUA | A | 02/12/2001 | 3 | QP SEMI | | Y | CY7C433-80DMB | 670 |
| 5962-9071502MXA | A | 02/12/2001 | 3 | QP SEMI | | Y | CY7C432-80DMB | 670 |
| 5962-9071502MYA | A | 02/12/2001 | 3 | QP SEMI | | Y | CY7C433-80KMB | 670 |
| 5962-9071502MZA | A | 02/12/2001 | 3 | QP SEMI | | Y | CY7C433-80LMB | 670 |
| 5962-9071503MUA | A | 02/12/2001 | 3 | QP SEMI | | Y | CY7C433-65DMB | 670 |
| 5962-9071503MXA | A | 02/12/2001 | 3 | QP SEMI | | Y | CY7C432-65DMB | 670 |
| 5962-9071503MYA | A | 02/12/2001 | 3 | QP SEMI | | Y | CY7C433-65KMB | 670 |
| 5962-9071503MZA | A | 02/12/2001 | 3 | QP SEMI | | Y | CY7C433-65LMB | 670 |
| 5962-9071504MUA | A | 02/12/2001 | 3 | QP SEMI | | Y | CY7C433-50DMB | 670 |
| 5962-9071504MXA | A | 02/12/2001 | 3 | QP SEMI | | Y | CY7C432-50DMB | 670 |
| 5962-9071504MYA | A | 02/12/2001 | 3 | QP SEMI | | Y | CY7C433-50KMB | 670 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9071504MZA | A | 02/12/2001 | 3 | QP SEMI | | Y | CY7C433-50LMB | 670 |
| 5962-9071505MUA | A | 02/12/2001 | 3 | QP SEMI | | Y | CY7C433-40DMB | 670 |
| 5962-9071505MXA | A | 02/12/2001 | 3 | QP SEMI | | Y | CY7C432-40DMB | 670 |
| 5962-9071505MYA | A | 02/12/2001 | 3 | QP SEMI | | Y | CY7C433-40KMB | 670 |
| 5962-9071505MZA | A | 02/12/2001 | 3 | QP SEMI | | Y | CY7C433-40LMB | 670 |
| 5962-9071506MUA | A | 02/12/2001 | 3 | QP SEMI | | Y | CY7C433-30DMB | 670 |
| 5962-9071506MXA | A | 02/12/2001 | 3 | QP SEMI | | Y | CY7C432-30DMB | 670 |
| 5962-9071506MYA | A | 02/12/2001 | 3 | QP SEMI | | Y | CY7C433-30KMB | 670 |
| 5962-9071506MZA | A | 02/12/2001 | 3 | QP SEMI | | Y | CY7C433-30LMB | 670 |
| 5962-9071507MUA | A | 02/12/2001 | 3 | QP SEMI | | Y | CY7C433-20DMB | 670 |
| 5962-9071507MXA | A | 02/12/2001 | 3 | QP SEMI | | Y | CY7C432-30DMB | 670 |
| 5962-9071507MYA | A | 02/12/2001 | 3 | QP SEMI | | Y | CY7C433-20KMB | 670 |
| 5962-9071507MZA | A | 02/12/2001 | 3 | QP SEMI | | Y | CY7C433-20LMB | 670 |
| 5962-9071901MXA | A | 01/11/1996 | | (NONE) | | | EF4442 (GEN) | 579 |
| 5962-9072001M3A | A | 10/05/1992 | | (NONE) | | | 54ALS29843 (GEN) | 342 |
| 5962-9072001MKA | A | 10/05/1992 | | (NONE) | | | 54ALS29843 (GEN) | 342 |
| 5962-9072001MLA | A | 10/05/1992 | | (NONE) | | | 54ALS29843 (GEN) | 342 |
| 5962-9072301HXA | B | 02/02/2001 | 1 | APEX MICRO. | | Y | PA08M/883 | 724 |
| 5962-9072701MXA | A | 11/04/1993 | | (NONE) | | | 34010-40 (GEN) | 439 |
| 5962-9072701MYA | A | 11/04/1993 | | (NONE) | | | 34010-40 (GEN) | 439 |
| 5962-9072702MXA | A | 11/04/1993 | | (NONE) | 10/31/2002 | | 34010-50 (GEN) | 439 |
| 5962-9072702MYA | A | 11/04/1993 | | (NONE) | | | 34010-50 (GEN) | 439 |
| 5962-9073001HXA | B | 06/22/1993 | 1 | MICRO NETWKS | | Y | MN376H/B | 818 |
| 5962-9073001HXC | B | 06/22/1993 | 1 | MICRO NETWKS | | Y | MN376H/B | 818 |
| 5962-9073001HYC | B | 06/22/1993 | | (NONE) | 04/14/2001 | | HTC-0300A (GEN) | 818 |
| 5962-9073101M2A | D | 03/24/1995 | 1 | SILICONIX | | Y | DG411AZ/883 | 183 |
| 5962-9073101M2C | D | 03/24/1995 | 1 | MAXIM INTEG. | | | DG411AZ/883B | 183 |
| 5962-9073101MEA | D | 03/24/1995 | 2 | INTERSIL | 10/05/2004 | Y | DG411AK/883 | 183 |
| 5962-9073101MEA | D | 03/24/1995 | 1 | MAXIM INTEG. | | | DG411AK/883B | 183 |
| 5962-9073101MEA | D | 03/24/1995 | 1 | SILICONIX | | Y | DG411AK/883 | 183 |
| 5962-9073101MFA | D | 03/24/1995 | | (NONE) | | | DG411 (GEN) | 183 |
| 5962-9073101MXC | D | 03/24/1995 | 1 | MAXIM INTEG. | | | DG411AL/883B | 183 |
| 5962-9073102M2A | D | 03/24/1995 | 1 | SILICONIX | | Y | DG411AZ/883 | 183 |
| 5962-9073102M2C | D | 03/24/1995 | 1 | MAXIM INTEG. | | | DG412AZ/883B | 183 |
| 5962-9073102MEA | D | 03/24/1995 | 1 | MAXIM INTEG. | | | DG412AK/883B | 183 |
| 5962-9073102MEA | D | 03/24/1995 | 1 | SILICONIX | | Y | DG412AK/883 | 183 |
| 5962-9073102MFA | D | 03/24/1995 | | (NONE) | | | DG412 (GEN) | 183 |
| 5962-9073102MXC | D | 03/24/1995 | 1 | MAXIM INTEG. | | | DG412AL/883B | 183 |
| 5962-9073103M2A | D | 03/24/1995 | 1 | SILICONIX | | Y | DG412AZ/883 | 183 |
| 5962-9073103M2C | D | 03/24/1995 | 1 | MAXIM INTEG. | | | DG413AZ/883B | 183 |
| 5962-9073103MEA | D | 03/24/1995 | 1 | MAXIM INTEG. | | | DG413AK/883B | 183 |
| 5962-9073103MEA | D | 03/24/1995 | 1 | SILICONIX | | Y | DG413AK/883 | 183 |
| 5962-9073103MFA | D | 03/24/1995 | | (NONE) | | | DG413 (GEN) | 183 |
| 5962-9073103MXC | D | 03/24/1995 | 1 | MAXIM INTEG. | | | DG413AL/883B | 183 |
| 5962-9073201MPA | | 05/09/1994 | | (NONE) | | | 602A (GEN) | 801 |
| 5962-9073601HXA | A | 03/28/2002 | 1 | APEX MICRO. | | Y | PA84M/883 | 719 |
| 5962-9073701MHA | C | 10/02/2001 | | (NONE) | | | DG417 (GEN) | 180 |
| 5962-9073701MPA | C | 10/02/2001 | 1 | MAXIM INTEG. | | | DG417AK/883B | 180 |
| 5962-9073701MPA | C | 10/02/2001 | 1 | SILICONIX | | Y | DG417AK/883 | 180 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9073701MXC | C | 10/02/2001 | 1 | MAXIM INTEG. | | | DG417AL/883B | 180 |
| 5962-9073702MHA | C | 10/02/2001 | | (NONE) | | | DG418 (GEN) | 180 |
| 5962-9073702MPA | C | 10/02/2001 | 1 | MAXIM INTEG. | | | DG418AK/883B | 180 |
| 5962-9073702MPA | C | 10/02/2001 | 1 | SILICONIX | | Y | DG418AK/883 | 180 |
| 5962-9073702MXC | C | 10/02/2001 | 1 | MAXIM INTEG. | | | DG418AL/883B | 180 |
| 5962-9073703MHA | C | 10/02/2001 | | (NONE) | | | DG419 (GEN) | 185 |
| 5962-9073703MPA | C | 10/02/2001 | 1 | MAXIM INTEG. | | | DG419AK/883B | 185 |
| 5962-9073703MPA | C | 10/02/2001 | 1 | SILICONIX | | Y | DG419AK/883 | 185 |
| 5962-9073703MXC | C | 10/02/2001 | 1 | MAXIM INTEG. | | | DG419AL/883B | 185 |
| 5962-9073901MXA | D | 08/21/2000 | | (NONE) | | | LT1083-5 (GEN) | 782 |
| 5962-9073902MXA | D | 08/21/2000 | | (NONE) | 03/30/2001 | | LT1084-5 (GEN) | 782 |
| 5962-9073903MXA | D | 08/21/2000 | | (NONE) | 03/30/2001 | | LT1085-5 (GEN) | 782 |
| 5962-9073904MXA | D | 08/21/2000 | | (NONE) | 03/30/2001 | | LT1086-5 (GEN) | 782 |
| 5962-9073905MXA | D | 08/21/2000 | | (NONE) | 03/30/2001 | | LT1084-12 (GEN) | 782 |
| 5962-9073906MXA | D | 08/21/2000 | | (NONE) | 03/30/2001 | | LT1085-12 (GEN) | 782 |
| 5962-9074101M2A | A | 08/28/1992 | 1 | TI | | Y | SNJ54BCT2244FK | 529 |
| 5962-9074101MRA | A | 08/28/1992 | 1 | TI | | Y | SNJ54BCT2244J | 529 |
| 5962-9074101MSA | A | 08/28/1992 | 1 | TI | | Y | SNJ54BCT2244W | 529 |
| 5962-9074201M2A | | 10/31/1990 | 3 | TI | | Y | SNJ54BCT240FK | 529 |
| 5962-9074201MRA | | 10/31/1990 | 3 | TI | | Y | SNJ54BCT240J | 529 |
| 5962-9074201MSA | | 10/31/1990 | 3 | TI | | Y | SNJ54BCT240W | 529 |
| 5962-9074301M2A | | 11/07/1990 | 3 | TI | | Y | SNJ54BCT241FK | 529 |
| 5962-9074301MRA | | 11/07/1990 | 3 | TI | | Y | SNJ54BCT241J | 529 |
| 5962-9074301MSA | | 11/07/1990 | 3 | TI | | Y | SNJ54BCT241W | 529 |
| 5962-9074401M3A | A | 09/08/1992 | 3 | TI | | Y | SNJ54BCT2827AFK | 584 |
| 5962-9074401MKA | A | 09/08/1992 | 3 | TI | | Y | SNJ54BCT2827AW | 584 |
| 5962-9074401MLA | A | 09/08/1992 | 3 | TI | | Y | SNJ54BCT2827AJT | 584 |
| 5962-9074501M3A | A | 09/08/1992 | | (NONE) | 05/01/1998 | | 54BCT2828A (GEN) | 584 |
| 5962-9074501MKA | A | 09/08/1992 | | (NONE) | 05/01/1998 | | 54BCT2828A (GEN) | 584 |
| 5962-9074501MLA | A | 09/08/1992 | | (NONE) | 05/01/1998 | | 54BCT2828A (GEN) | 584 |
| 5962-9074601M2A | A | 08/29/1992 | 3 | TI | | Y | SNJ54BCT373FK | 341 |
| 5962-9074601MRA | A | 08/29/1992 | 3 | TI | | Y | SNJ54BCT373J | 341 |
| 5962-9074601MSA | A | 08/29/1992 | 3 | TI | | Y | SNJ54BCT373W | 341 |
| 5962-9074701M2A | B | 08/18/1995 | | (NONE) | 09/15/1995 | | 54BCT534 (GEN) | 159 |
| 5962-9074701MRA | B | 08/18/1995 | | (NONE) | 09/15/1995 | | 54BCT534 (GEN) | 159 |
| 5962-9074701MSA | B | 08/18/1995 | | (NONE) | 09/15/1995 | | 54BCT534 (GEN) | 159 |
| 5962-9074801M2A | | 10/04/1990 | 3 | TI | | Y | SNJ54BCT540FK | 529 |
| 5962-9074801MRA | | 10/04/1990 | 3 | TI | | Y | SNJ54BCT540J | 529 |
| 5962-9074801MSA | | 10/04/1990 | 3 | TI | | Y | SNJ54BCT540W | 529 |
| 5962-9074901M2A | | 10/10/1990 | 3 | TI | | Y | SNJ54BCT541FK | 529 |
| 5962-9074901MRA | | 10/10/1990 | 3 | TI | | Y | SNJ54BCT541J | 529 |
| 5962-9074901MSA | | 10/10/1990 | 3 | TI | | Y | SNJ54BCT541W | 529 |
| 5962-9075001M2A | | 10/01/1990 | 3 | TI | | Y | SNJ54BCT620AFK | 590 |
| 5962-9075001MRA | | 10/01/1990 | 3 | TI | | Y | SNJ54BCT620AJ | 590 |
| 5962-9075001MSA | | 10/01/1990 | 3 | TI | | Y | SNJ54BCT620AW | 590 |
| 5962-9075201M2A | | 10/11/1990 | 3 | TI | | Y | SNJ54BCT640FK | 590 |
| 5962-9075201MRA | | 10/11/1990 | 3 | TI | | Y | SNJ54BCT640J | 590 |
| 5962-9075201MSA | | 10/11/1990 | 3 | TI | | Y | SNJ54BCT640W | 590 |
| 5962-9075401M3A | A | 06/09/1992 | | (NONE) | | | | 431 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9075401MXA | A | 06/09/1992 | | (NONE) | | | | 431 |
| 5962-9075401MYA | A | 06/09/1992 | | (NONE) | | | 7C331-40 (GEN) | 431 |
| 5962-9075401MZA | A | 06/09/1992 | | (NONE) | | | 7C331-40 (GEN) | 431 |
| 5962-9075402M3A | A | 06/09/1992 | | (NONE) | | | 7C331-30 (GEN) | 431 |
| 5962-9075402MXA | A | 06/09/1992 | | (NONE) | | | | 431 |
| 5962-9075402MYA | A | 06/09/1992 | | (NONE) | | | 7C331-30 (GEN) | 431 |
| 5962-9075402MZA | A | 06/09/1992 | | (NONE) | | | 7C331-30 (GEN) | 431 |
| 5962-9075403M3A | A | 06/09/1992 | | (NONE) | | | 7C331-25 (GEN) | 431 |
| 5962-9075403MXA | A | 06/09/1992 | | (NONE) | | | 7C331-25 (GEN) | 431 |
| 5962-9075403MYA | A | 06/09/1992 | | (NONE) | | | 7C331-25 (GEN) | 431 |
| 5962-9075403MZA | A | 06/09/1992 | | (NONE) | | | 7C331-25 (GEN) | 431 |
| 5962-9075701MPA | A | 11/05/1992 | | (NONE) | 09/30/1995 | | 35063 (GEN) | 594 |
| 5962-9075801MEA | | 04/24/1991 | 1 | TI | | Y | CD54HCT75F3A | 340 |
| 5962-9076001HXA | B | 04/23/2004 | 1 | DDC | | Y | DSC-10510-143 | 594 |
| 5962-9076001HXA | B | 04/23/2004 | 1 | DDC IRELAND | | Y | DSC-10510-143 | 594 |
| 5962-9076001HXC | B | 04/23/2004 | 1 | DDC | | Y | DSC-10510-113 | 594 |
| 5962-9076001HXC | B | 04/23/2004 | 1 | DDC IRELAND | | Y | DSC-10510-113 | 594 |
| 5962-9076002HXA | B | 04/23/2004 | 1 | DDC | | Y | DSC-10510-144 | 594 |
| 5962-9076002HXA | B | 04/23/2004 | 1 | DDC IRELAND | | Y | DSC-10510-144 | 594 |
| 5962-9076002HXC | B | 04/23/2004 | 1 | DDC | | Y | DSC-10510-114 | 594 |
| 5962-9076002HXC | B | 04/23/2004 | 1 | DDC IRELAND | | Y | DSC-10510-114 | 594 |
| 5962-9076401MEA | A | 10/23/2001 | 1 | SILICONIX | | Y | DG541AP/883 | 183 |
| 5962-9076501M2A | B | 04/12/1995 | 1 | NATIONAL | | Y | DS96F172ME/883 | 569 |
| 5962-9076501MEA | B | 04/12/1995 | 1 | NATIONAL | | Y | DS96F172MJ/883 | 569 |
| 5962-9076501VEA | B | 04/12/1995 | 1 | NATIONAL | | Y | DS96F172MJ-QMLV | 569 |
| 5962-9076501MFA | B | 04/12/1995 | | (NONE) | | | 96F172 (GEN) | 569 |
| 5962-9076502M2A | B | 04/12/1995 | 1 | NATIONAL | | Y | DS96F174ME/883 | 569 |
| 5962-9076502MEA | B | 04/12/1995 | 1 | NATIONAL | | Y | DS96F174MJ/883 | 569 |
| 5962-9076502VEA | B | 04/12/1995 | 1 | NATIONAL | | Y | DS96F174MJ-QMLV | 569 |
| 5962-9076502MFA | B | 04/12/1995 | 1 | NATIONAL | | Y | DS96F174MW/883 | 569 |
| 5962-9076503Q2A | B | 04/12/1995 | 2 | TI | | Y | SNJ55LBC172FK | 569 |
| 5962-9076503QEA | B | 04/12/1995 | 2 | TI | | Y | SNJ55LBC172J | 569 |
| 5962-9076503QFA | B | 04/12/1995 | 2 | TI | | Y | SNJ55LBC172W | 569 |
| 5962-9076504Q2A | B | 04/12/1995 | 2 | TI | | Y | SNJ55LBC174FK | 569 |
| 5962-9076504QEA | B | 04/12/1995 | 2 | TI | | Y | SNJ55LBC174J | 569 |
| 5962-9076504QFA | B | 04/12/1995 | 2 | TI | | Y | SNJ55LBC174W | 569 |
| 5962-9076601M2A | D | 04/14/2004 | 1 | NATIONAL | | Y | DS96F175ME/883 | 575 |
| 5962-9076601MEA | D | 04/14/2004 | 1 | NATIONAL | | Y | DS96F175MJ/883 | 575 |
| 5962-9076601VEA | D | 04/14/2004 | 1 | NATIONAL | | Y | DS96F175MJ-QMLV | 575 |
| 5962-9076601MFA | D | 04/14/2004 | 1 | NATIONAL | | Y | DS96F175MW/883 | 575 |
| 5962-9076602M2A | D | 04/14/2004 | 1 | NATIONAL | | Y | DS96F173ME/883 | 575 |
| 5962-9076602MEA | D | 04/14/2004 | 1 | NATIONAL | | Y | DS96F173MJ/883 | 575 |
| 5962-9076602VEA | D | 04/14/2004 | 1 | NATIONAL | | Y | DS96F173MJ-QMLV | 575 |
| 5962-9076602MFA | D | 04/14/2004 | 1 | NATIONAL | | Y | DS96F173MW/883 | 575 |
| 5962-9076603Q2A | D | 04/14/2004 | 3 | TI | | Y | SNJ55LBC175FK | 575 |
| 5962-9076603QEA | D | 04/14/2004 | 3 | TI | | Y | SNJ55LBC175J | 575 |
| 5962-9076603QFA | D | 04/14/2004 | 3 | TI | | Y | SNJ55LBC175W | 575 |
| 5962-9076604Q2A | D | 04/14/2004 | 3 | TI | | Y | SNJ55LBC173FK | 575 |
| 5962-9076604QEA | D | 04/14/2004 | 3 | TI | | Y | SNJ55LBC173J | 575 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9076604QFA | D | 04/14/2004 | 3 | TI | | Y | SNJ55LBC173W | 575 |
| 5962-9077201Q2A | C | 05/06/2004 | 2 | TI | | Y | SNJ54ACT11FK | 112 |
| 5962-9077201QCA | C | 05/06/2004 | 2 | TI | | Y | SNJ54ACT11J | 112 |
| 5962-9077201QDA | C | 05/06/2004 | 2 | TI | | Y | SNJ54ACT11W | 112 |
| 5962-9077202QXA | C | 05/06/2004 | 2 | STMICRO | | Y | 54ACT11K02Q | 112 |
| 5962-9077202QXC | C | 05/06/2004 | 2 | STMICRO | | Y | 54ACT11K01Q | 112 |
| 5962-9077202VXA | C | 05/06/2004 | 2 | STMICRO | | Y | 54ACT11K02V | 112 |
| 5962-9077202VXC | C | 05/06/2004 | 2 | STMICRO | | Y | 54ACT11K01V | 112 |
| 5962F9077202QXA | C | 05/06/2004 | 2 | STMICRO | | Y | RHFACT11K02Q | 112 |
| 5962F9077202QXC | C | 05/06/2004 | 2 | STMICRO | | Y | RHFACT11K01Q | 112 |
| 5962F9077202VXA | C | 05/06/2004 | 2 | STMICRO | | Y | RHFACT11K02V | 112 |
| 5962F9077202VXC | C | 05/06/2004 | 2 | STMICRO | | Y | RHFACT11K01V | 112 |
| 5962-9078001M3A | B | 09/07/2004 | 3 | TI | | Y | SNJ54AS821AFK | 599 |
| 5962-9078001MKA | B | 09/07/2004 | 3 | TI | | Y | SNJ54AS821AW | 599 |
| 5962-9078001MLA | B | 09/07/2004 | 3 | TI | | Y | SNJ54AS821AJT | 599 |
| 5962-9078002M3A | B | 09/07/2004 | 1 | ROCHESTER | | | 54AS822/B3A | 599 |
| 5962-9078002MKA | B | 09/07/2004 | 1 | ROCHESTER | | | 54AS822/BKA | 599 |
| 5962-9078002MLA | B | 09/07/2004 | 1 | ROCHESTER | | | 54AS822/BLA | 599 |
| 5962-9078003M3A | B | 09/07/2004 | 3 | TI | | Y | SNJ54AS825AFK | 599 |
| 5962-9078003MKA | B | 09/07/2004 | 3 | TI | | Y | SNJ54AS825AW | 599 |
| 5962-9078003MLA | B | 09/07/2004 | 3 | TI | | Y | SNJ54AS825AJT | 599 |
| 5962-9078004M3A | B | 09/07/2004 | 1 | ROCHESTER | | | 54AS826/B3A | 599 |
| 5962-9078004MKA | B | 09/07/2004 | 1 | ROCHESTER | | | 54AS826/BKA | 599 |
| 5962-9078004MLA | B | 09/07/2004 | 1 | ROCHESTER | | | 54AS826/BLA | 599 |
| 5962-9078101M2A | A | 10/22/1999 | | (NONE) | 06/01/1997 | | 54F125 (GEN) | 520 |
| 5962-9078101MCA | A | 10/22/1999 | 2 | QP SEMI | | Y | 54F125/MCA | 520 |
| 5962-9078101MDA | A | 10/22/1999 | | (NONE) | 06/01/1997 | | 54F125 (GEN) | 520 |
| 5962-9078501MLA | | 05/27/1999 | 2 | ANALOG (3) | | Y | AD7247ATQ/QML | 591 |
| 5962-9078502MLA | | 05/27/1999 | 2 | ANALOG (3) | | Y | AD7237ATQ/QML | 591 |
| 5962-9079201MXA | | 04/22/1992 | | (NONE) | 06/30/1996 | | SL521 (GEN) | 800 |
| 5962-9079501HXA | B | 06/28/1999 | | (NONE) | 09/01/2000 | | HS9576S (GEN) | 592 |
| 5962-9079502HXA | B | 06/28/1999 | | (NONE) | 09/01/2000 | | HS9576T (GEN) | 592 |
| 5962-9079503HXA | B | 06/28/1999 | | (NONE) | 09/01/2000 | | HS9576S (GEN) | 592 |
| 5962-9079504HXA | B | 06/28/1999 | | (NONE) | 09/01/2000 | | HS9576T (GEN) | 592 |
| 5962-9079701HXA | | 05/14/1992 | 1 | MICRO NETWKS | | Y | MN7140H/B | 433 |
| 5962-9079701HXC | | 05/14/1992 | 1 | MICRO NETWKS | | Y | MN7140H/B | 433 |
| 5962-9079801MLA | | 04/21/1992 | | (NONE) | | | 54FCT480 (GEN) | 210 |
| 5962-9079802MLA | | 04/21/1992 | | (NONE) | | | 54FCT480A (GEN) | 210 |
| 5962-9079803MLA | | 04/21/1992 | | (NONE) | | | 54FCT480 (GEN) | 210 |
| 5962-9079901MQA | | 11/19/1993 | | (NONE) | 06/30/1995 | | EP910-30 (GEN) | 431 |
| 5962-9079902MQA | | 11/19/1993 | | (NONE) | 06/30/1995 | | EP910-25 (GEN) | 431 |
| 5962-9079903MQA | | 11/19/1993 | | (NONE) | 06/30/1995 | | EP910-20 (GEN) | 431 |
| 5962-9080001MEA | A | 09/13/2004 | 0 | NATIONAL | 06/07/2005 | Y | DM54LS502J/883 | 249 |
| 5962-9080001MFA | A | 09/13/2004 | | (NONE) | 09/09/1998 | | DM54LS502 (GEN) | 249 |
| 5962-9080301M3A | A | 02/15/2001 | 1 | QP SEMI | | | WS57C49C-55ZMB | 660 |
| 5962-9080301M3C | A | 02/15/2001 | 1 | QP SEMI | | | WS57C49C-55ZMB | 660 |
| 5962-9080301MKA | A | 02/15/2001 | 1 | QP SEMI | | | WS57C49C-55HMB | 660 |
| 5962-9080301MLA | A | 02/15/2001 | 1 | QP SEMI | | | WS57C49C-55KMB | 660 |
| 5962-9080302M3A | A | 02/15/2001 | 1 | QP SEMI | | | WS57C49C-45ZMB | 660 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9080302M3C | A | 02/15/2001 | 1 | QP SEMI | | | WS57C49C-45ZMB | 660 |
| 5962-9080302MKA | A | 02/15/2001 | 1 | QP SEMI | | | WS57C49C-45HMB | 660 |
| 5962-9080302MLA | A | 02/15/2001 | 1 | QP SEMI | | | WS57C49C-45KMB | 660 |
| 5962-9080303M3A | A | 02/15/2001 | 1 | QP SEMI | | | WS57C49C-35ZMB | 660 |
| 5962-9080303M3C | A | 02/15/2001 | 1 | QP SEMI | | | WS57C49C-35ZMB | 660 |
| 5962-9080303MKA | A | 02/15/2001 | 1 | QP SEMI | | | WS57C49C-35HMB | 660 |
| 5962-9080303MLA | A | 02/15/2001 | 2 | CYPRESS | | Y | CY7C261-35DMB | 660 |
| 5962-9080303MLA | A | 02/15/2001 | 1 | QP SEMI | | | WS57C49C-35KMB | 660 |
| 5962-9080303MLA | A | 02/15/2001 | 2 | QP SEMI | | Y | CY7C261-35DMB | 660 |
| 5962-9080304M3A | A | 02/15/2001 | 2 | QP SEMI | | Y | CY7C261-25LMB | 660 |
| 5962-9080304MKA | A | 02/15/2001 | 2 | QP SEMI | | Y | CY7C261-25KMB | 660 |
| 5962-9080304MLA | A | 02/15/2001 | 2 | CYPRESS | 06/28/2005 | Y | CY7C261-25DMB | 660 |
| 5962-9080305M3A | A | 02/15/2001 | 1 | QP SEMI | | | WS57C49C-55ZMB | 660 |
| 5962-9080305M3C | A | 02/15/2001 | 1 | QP SEMI | | | WS57C49C-55ZMB | 660 |
| 5962-9080305MJA | A | 02/15/2001 | 1 | QP SEMI | | | WS57C49C-55YMB | 660 |
| 5962-9080305MKA | A | 02/15/2001 | 1 | QP SEMI | | | WS57C49C-55HMB | 660 |
| 5962-9080305MLA | A | 02/15/2001 | 1 | QP SEMI | | | WS57C49C-55KMB | 660 |
| 5962-9080306M3A | A | 02/15/2001 | 1 | QP SEMI | | | WS57C49C-45ZMB | 660 |
| 5962-9080306M3C | A | 02/15/2001 | 1 | QP SEMI | | | WS57C49C-45ZMB | 660 |
| 5962-9080306MJA | A | 02/15/2001 | 1 | QP SEMI | | | WS57C49C-45YMB | 660 |
| 5962-9080306MKA | A | 02/15/2001 | 1 | QP SEMI | | | WS57C49C-45HMB | 660 |
| 5962-9080306MLA | A | 02/15/2001 | 1 | QP SEMI | | | WS57C49C-45KMB | 660 |
| 5962-9080307M3A | A | 02/15/2001 | 1 | QP SEMI | | | WS57C49C-35ZMB | 660 |
| 5962-9080307M3C | A | 02/15/2001 | 1 | QP SEMI | | | WS57C49C-35ZMB | 660 |
| 5962-9080307MJA | A | 02/15/2001 | 1 | QP SEMI | | | WS57C49C-35YMB | 660 |
| 5962-9080307MKA | A | 02/15/2001 | 1 | QP SEMI | | | WS57C49C-35HMB | 660 |
| 5962-9080307MLA | A | 02/15/2001 | 1 | QP SEMI | | | WS57C49C-35KMB | 660 |
| 5962-9080308M3A | A | 02/15/2001 | 2 | QP SEMI | | Y | CY7C263-25LMB | 660 |
| 5962-9080308MJA | A | 02/15/2001 | 2 | QP SEMI | | Y | CY7C264-25DMB | 660 |
| 5962-9080308MKA | A | 02/15/2001 | 2 | QP SEMI | | Y | CY7C263-25KMB | 660 |
| 5962-9080308MLA | A | 02/15/2001 | 2 | QP SEMI | | Y | CY7C263-25DMB | 660 |
| 5962-9080701M2A | D | 12/05/2002 | 1 | TI | | Y | TLE2061MFKB | 701 |
| 5962-9080701MGA | D | 12/05/2002 | | (NONE) | | | TLE2061M (GEN) | 701 |
| 5962-9080701MHA | D | 12/05/2002 | 1 | TI | | Y | TLE2061MUB | 701 |
| 5962-9080701MPA | D | 12/05/2002 | 1 | TI | | Y | TLE2061MJGB | 701 |
| 5962-9080702Q2A | D | 12/05/2002 | 1 | TI | | Y | TLE2061AMFKB | 701 |
| 5962-9080702QHA | D | 12/05/2002 | 1 | TI | | Y | TLE2061AMUB | 701 |
| 5962-9080702QPA | D | 12/05/2002 | 1 | TI | | Y | TLE2061AMJGB | 701 |
| 5962-9080703QPA | D | 12/05/2002 | 1 | TI | | Y | TLE2061BMJGB | 701 |
| 5962-9080801M2A | C | 12/17/2002 | 1 | TI | | Y | TLE2062MFKB | 710 |
| 5962-9080801MGA | C | 12/17/2002 | | (NONE) | | | TLE2062M (GEN) | 710 |
| 5962-9080801MHA | C | 12/17/2002 | | TI | | Y | TLE2062MUB | 710 |
| 5962-9080801MPA | C | 12/17/2002 | 1 | TI | | Y | TLE2062MJGB | 710 |
| 5962-9080802Q2A | C | 12/17/2002 | 1 | TI | | Y | TLE2062AMFKB | 710 |
| 5962-9080802QHA | C | 12/17/2002 | 1 | TI | | Y | TLE2062AMUB | 710 |
| 5962-9080802QPA | C | 12/17/2002 | 1 | TI | | Y | TLE2062AMJGB | 710 |
| 5962-9080803QPA | C | 12/17/2002 | 1 | TI | | Y | TLE2062BMJGB | 710 |
| 5962-9080901M2A | D | 08/27/2001 | 1 | TI | | Y | TLE2064MFKB | 713 |
| 5962-9080901BCA | D | 08/27/2001 | | (NONE) | | | TLE2064 (GEN) | 713 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9080901MCA | D | 08/27/2001 | 1 | TI | | Y | TLE2064MJB | 713 |
| 5962-9080901MDA | D | 08/27/2001 | 1 | TI | | Y | TLE2064MWB | 713 |
| 5962-9080902M2A | D | 08/27/2001 | 1 | TI | | Y | TLE2064AMFKB | 713 |
| 5962-9080902MCA | D | 08/27/2001 | 1 | TI | | Y | TLE2064AMJB | 713 |
| 5962-9080902MDA | D | 08/27/2001 | 1 | TI | | Y | TLE2064AMWB | 713 |
| 5962-9080903Q2A | D | 08/27/2001 | 1 | TI | | Y | TLE2064BMFKB | 739 |
| 5962-9080903QCA | D | 08/27/2001 | 1 | TI | | Y | TLE2064BMJB | 739 |
| 5962-9081101MGC | D | 03/11/2003 | 1 | MAXIM INTEG. | | | MAX8211MTV/883B | 899 |
| 5962-9081101MHA | D | 03/11/2003 | | (NONE) | | | 8211 (GEN) | 899 |
| 5962-9081101MPA | D | 03/11/2003 | 1 | MAXIM INTEG. | | | MAX8211MJA/883B | 899 |
| 5962-9081101MXC | D | 03/11/2003 | 1 | MAXIM INTEG. | | | MAX8211MFB/883B | 899 |
| 5962-9081102MGC | D | 03/11/2003 | 1 | MAXIM INTEG. | | | MAX8212MTV/883B | 899 |
| 5962-9081102MHA | D | 03/11/2003 | | (NONE) | | | 8212 (GEN) | 899 |
| 5962-9081102MPA | D | 03/11/2003 | 1 | MAXIM INTEG. | | | MAX8212MJA/883B | 899 |
| 5962-9081102MXC | D | 03/11/2003 | 1 | MAXIM INTEG. | | | MAX8212MFB/883B | 899 |
| 5962-9081201MGA | D | 03/13/2003 | | (NONE) | 12/02/2003 | | LM6121 (GEN) | 899 |
| 5962-9081201MPA | D | 03/13/2003 | | (NONE) | 12/02/2003 | | LM6121 (GEN) | 899 |
| 5962-9081301MXA | B | 12/16/1993 | | (NONE) | 05/31/1994 | | 55563A (GEN) | 599 |
| 5962-9081302MXA | B | 12/16/1993 | | (NONE) | 05/31/1994 | | 55564A (GEN) | 599 |
| 5962-9081501MGA | B | 11/13/2001 | | (NONE) | 03/04/2003 | | LM6125 (GEN) | 899 |
| 5962-9081701MGA | B | 12/13/2002 | 1 | MINCO | | Y | MTL1057AMH | 710 |
| 5962-9081701MPA | B | 12/13/2002 | | (NONE) | 12/31/2001 | | LT1057A (GEN) | 710 |
| 5962-9081701MXA | B | 12/13/2002 | | (NONE) | 12/31/2001 | | LT1057A (GEN) | 710 |
| 5962-9081702MGA | B | 12/13/2002 | 1 | MINCO | | Y | MTL1057MH | 710 |
| 5962-9081702MPA | B | 12/13/2002 | | (NONE) | 12/31/2001 | | LT1057 (GEN) | 710 |
| 5962-9081702MXA | B | 12/13/2002 | | (NONE) | 12/31/2001 | | LT1057 (GEN) | 710 |
| 5962-9081801M2A | A | 03/22/1994 | | (NONE) | | | EL2030 (GEN) | 899 |
| 5962-9081801MCA | A | 03/22/1994 | | (NONE) | | | EL2030 (GEN) | 899 |
| 5962-9081802MPA | A | 03/22/1994 | | (NONE) | 09/09/1999 | | LM6181 (GEN) | 899 |
| 5962-9082001HXA | G | 06/18/2004 | 1 | DDC | | Y | SD-14531-145 | 594 |
| 5962-9082001HXA | G | 06/18/2004 | 1 | DDC IRELAND | | Y | SD-14531-145 | 594 |
| 5962-9082001HXC | G | 06/18/2004 | 1 | DDC | | Y | SD-14531-115 | 594 |
| 5962-9082001HXC | G | 06/18/2004 | 1 | DDC IRELAND | | Y | SD-14531-115 | 594 |
| 5962-9082002HXA | G | 06/18/2004 | | (NONE) | | | SDC14531-631 (GEN) | 594 |
| 5962-9082002HXC | G | 06/18/2004 | | (NONE) | | | SDC14531-631 (GEN) | 594 |
| 5962-9082003HXC | G | 06/18/2004 | | (NONE) | | | 1006148 (GEN) | 594 |
| 5962-9082004HXC | G | 06/18/2004 | | (NONE) | | | 1006148A (GEN) | 594 |
| 5962-9082005HXC | G | 06/18/2004 | | (NONE) | | | 1056775 (GEN) | 594 |
| 5962-9082006HXA | G | 06/18/2004 | 1 | DDC | | Y | SD-14531D1-144 | 594 |
| 5962-9082006HXA | G | 06/18/2004 | 1 | DDC IRELAND | | Y | SD-14531D1-144 | 594 |
| 5962-9082006HXC | G | 06/18/2004 | 1 | DDC | | Y | SD-14531D1-114 | 594 |
| 5962-9082006HXC | G | 06/18/2004 | 1 | DDC IRELAND | | Y | SD-14531D1-114 | 594 |
| 5962-9082007HXA | G | 06/18/2004 | 1 | DDC | | Y | SD-14531D1-142 | 594 |
| 5962-9082007HXA | G | 06/18/2004 | 1 | DDC IRELAND | | Y | SD-14531D1-142 | 594 |
| 5962-9082007HXC | G | 06/18/2004 | 1 | DDC | | Y | SD-14531D1-112 | 594 |
| 5962-9082007HXC | G | 06/18/2004 | 1 | DDC IRELAND | | Y | SD-14531D1-112 | 594 |
| 5962-9082501MYA | C | 08/29/2000 | | (NONE) | | | LT1070 (GEN) | 786 |
| 5962-9082502MYA | C | 08/29/2000 | | (NONE) | | | LT1071 (GEN) | 786 |
| 5962-9082503MPA | C | 08/29/2000 | | (NONE) | 03/30/2001 | | LT1072 (GEN) | 786 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9082503MYA | C | 08/29/2000 | | (NONE) | | | LT1072 (GEN) | 786 |
| 5962-9082504MYA | C | 08/29/2000 | | (NONE) | | | LT1070HV (GEN) | 786 |
| 5962-9082505MYA | C | 08/29/2000 | | (NONE) | | | LT1071HV (GEN) | 786 |
| 5962-9082506MYA | C | 08/29/2000 | | (NONE) | | | LT1072HV (GEN) | 786 |
| 5962-9082801HXA | D | 06/03/2003 | 1 | APEX MICRO. | | Y | PA10M/883 | 724 |
| 5962-9082801HXA | D | 06/03/2003 | 1 | MICROPAC | | Y | MIOP42115/883 | 724 |
| 5962-9082801HXC | D | 06/03/2003 | 1 | MICROPAC | | Y | MIOP42115/883 | 724 |
| 5962-9082901HTA | A | 03/10/1992 | 1 | CMAC MICRO. | | Y | FC155371FP | 590 |
| 5962-9082901HTC | A | 03/10/1992 | 1 | CMAC MICRO. | | Y | FC155371FP | 590 |
| 5962-9082901HXA | A | 03/10/1992 | 1 | CMAC MICRO. | | Y | FC155371 | 590 |
| 5962-9082901HXC | A | 03/10/1992 | 1 | CMAC MICRO. | | Y | FC155371 | 590 |
| 5962-9082901HYA | A | 03/10/1992 | 1 | CMAC MICRO. | | Y | FC155371SSW | 590 |
| 5962-9082901HYC | A | 03/10/1992 | 1 | CMAC MICRO. | | Y | FC155371SSW | 590 |
| 5962-9082902HXA | A | 03/10/1992 | 1 | CMAC MICRO. | | Y | FC155372 | 590 |
| 5962-9082902HXC | A | 03/10/1992 | 1 | CMAC MICRO. | | Y | FC155372 | 590 |
| 5962-9082903HUA | A | 03/10/1992 | 1 | AEROFLEX | | Y | ARX3420 | 590 |
| 5962-9082903HUC | A | 03/10/1992 | 1 | AEROFLEX | | Y | ARX3420 | 590 |
| 5962-9082904HUA | A | 03/10/1992 | 1 | AEROFLEX | | Y | ARX3424 | 590 |
| 5962-9082904HUC | A | 03/10/1992 | 1 | AEROFLEX | | Y | ARX3424 | 590 |
| 5962-9082905HTA | A | 03/10/1992 | 1 | NATIONAL HYB | | Y | NHI-1531FP | 590 |
| 5962-9082905HTC | A | 03/10/1992 | 1 | NATIONAL HYB | | Y | NHI-1531FP | 590 |
| 5962-9082905HYA | A | 03/10/1992 | 1 | NATIONAL HYB | | Y | NHI-1531 | 590 |
| 5962-9082905HYC | A | 03/10/1992 | 1 | NATIONAL HYB | | Y | NHI-1531 | 590 |
| 5962-9082906HTA | A | 03/10/1992 | 1 | NATIONAL HYB | | Y | NHI-1545FP | 590 |
| 5962-9082906HTC | A | 03/10/1992 | 1 | NATIONAL HYB | | Y | NHI-1545FP | 590 |
| 5962-9082906HYA | A | 03/10/1992 | 1 | NATIONAL HYB | | Y | NHI-1545 | 590 |
| 5962-9082906HYC | A | 03/10/1992 | 1 | NATIONAL HYB | | Y | NHI-1545 | 590 |
| 5962-9082907HTA | A | 03/10/1992 | | (NONE) | | | CT1589M (GEN) | 590 |
| 5962-9082907HXA | A | 03/10/1992 | | (NONE) | | | CT1589M (GEN) | 590 |
| 5962-9082907HYA | A | 03/10/1992 | | (NONE) | | | CT1589M (GEN) | 590 |
| 5962-9082908HTA | A | 03/10/1992 | | (NONE) | | | CT1589MI (GEN) | 590 |
| 5962-9082908HXA | A | 03/10/1992 | | (NONE) | | | CT1589MI (GEN) | 590 |
| 5962-9082908HYA | A | 03/10/1992 | | (NONE) | | | CT1589MIP (GEN) | 590 |
| 5962-9083101M3A | | 01/13/1993 | 3 | QP SEMI | | Y | CY7C269-60LMB | 660 |
| 5962-9083101MXA | | 01/13/1993 | 3 | QP SEMI | | Y | CY7C269-60DMB | 660 |
| 5962-9083101MYA | | 01/13/1993 | 3 | QP SEMI | | Y | CY7C269-60KMB | 660 |
| 5962-9083102M3A | | 01/13/1993 | 3 | QP SEMI | | Y | CY7C269-50LMB | 660 |
| 5962-9083102MXA | | 01/13/1993 | 3 | QP SEMI | | Y | CY7C269-50DMB | 660 |
| 5962-9083102MYA | | 01/13/1993 | 3 | QP SEMI | | Y | CY7C269-50KMB | 660 |
| 5962-9083103M3A | | 01/13/1993 | 3 | QP SEMI | | Y | CY7C269-25LMB | 660 |
| 5962-9083103MXA | | 01/13/1993 | 3 | QP SEMI | | Y | CY7C269-25DMB | 660 |
| 5962-9083103MYA | | 01/13/1993 | 3 | QP SEMI | | Y | CY7C269-25KMB | 660 |
| 5962-9083104M3A | | 01/13/1993 | 3 | QP SEMI | | Y | CY7C269-18LMB | 660 |
| 5962-9083104MXA | | 01/13/1993 | 3 | QP SEMI | | Y | CY7C269-18DMB | 660 |
| 5962-9083104MYA | | 01/13/1993 | 3 | QP SEMI | | Y | CY7C269-18KMB | 660 |
| 5962-9083301HXA | | 07/02/1991 | | (NONE) | | | CLC201A (GEN) | 755 |
| 5962-9083501HXA | D | 06/03/2003 | | (NONE) | 09/27/2002 | | CLC205A (GEN) | 755 |
| 5962-9083601HXA | | 09/18/1991 | | (NONE) | | | CLC221A (GEN) | 755 |
| 5962-9083801HXA | A | 06/09/1995 | 1 | INTER. RECT. | | Y | OMA2541SKB | 710 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9083801HXC | A | 06/09/1995 | 1 | MS KENNEDY | | Y | MSK2541B | 710 |
| 5962-9083801HYA | A | 06/09/1995 | 1 | INTER. RECT. | | Y | OMA2541SBD | 710 |
| 5962-9083802HXA | A | 06/09/1995 | 1 | INTER. RECT. | | Y | OMA2541SKCB | 710 |
| 5962-9084101MCA | B | 09/27/2000 | | (NONE) | 03/30/2001 | | LT1020 (GEN) | 789 |
| 5962-9084201MGA | B | 09/15/2000 | | (NONE) | 03/30/2001 | | LT1012 (GEN) | 701 |
| 5962-9084201MPA | B | 09/15/2000 | | (NONE) | 03/30/2001 | | LT1012 (GEN) | 701 |
| 5962-9084202MGA | B | 09/15/2000 | | (NONE) | 03/30/2001 | | LT1012A (GEN) | 701 |
| 5962-9084202MPA | B | 09/15/2000 | | (NONE) | 03/30/2001 | | LT1012A (GEN) | 701 |
| 5962-9084501M2A | A | 06/19/1992 | | (NONE) | 09/15/1995 | | TLC548 (GEN) | 592 |
| 5962-9084501MPA | A | 06/19/1992 | | (NONE) | 09/15/1995 | | TLC548 (GEN) | 592 |
| 5962-9084502M2A | A | 06/19/1992 | | (NONE) | 09/15/1995 | | TLC549 (GEN) | 592 |
| 5962-9084502MPA | A | 06/19/1992 | | (NONE) | 09/15/1995 | | TLC549 (GEN) | 592 |
| 5962-9084701MMA | E | 07/20/1998 | 2 | AUSTIN SEMI. | | Y | MT4C4001JF-12 | 629 |
| 5962-9084701MNA | E | 07/20/1998 | 2 | AUSTIN SEMI. | | Y | MT4C4001JCZ-12 | 629 |
| 5962-9084701MRA | E | 07/20/1998 | 2 | AUSTIN SEMI. | | Y | MT4C4001JCN-12 | 629 |
| 5962-9084701MTA | E | 07/20/1998 | 2 | AUSTIN SEMI. | | Y | MT4C4001JECN-12 | 629 |
| 5962-9084701MUA | E | 07/20/1998 | 2 | AUSTIN SEMI. | | Y | MT4C4001JC-12 | 629 |
| 5962-9084701MUA | E | 07/20/1998 | 2 | AUSTIN SEMI. | | Y | SMJ44400-12JDM | 629 |
| 5962-9084701MXA | E | 07/20/1998 | 2 | AUSTIN SEMI. | | Y | SMJ44400-12HRM | 629 |
| 5962-9084701MYA | E | 07/20/1998 | 2 | AUSTIN SEMI. | | Y | MT4C4001JEC-12 | 629 |
| 5962-9084701MZA | E | 07/20/1998 | | (NONE) | | | | 629 |
| 5962-9084702MMA | E | 07/20/1998 | 2 | AUSTIN SEMI. | | Y | MT4C4001JF-10 | 629 |
| 5962-9084702MNA | E | 07/20/1998 | 2 | AUSTIN SEMI. | | Y | MT4C4001JCZ-10 | 629 |
| 5962-9084702MRA | E | 07/20/1998 | 2 | AUSTIN SEMI. | | Y | MT4C4001JCN-10 | 629 |
| 5962-9084702MTA | E | 07/20/1998 | 2 | AUSTIN SEMI. | | Y | MT4C4001JECN-10 | 629 |
| 5962-9084702MUA | E | 07/20/1998 | 2 | AUSTIN SEMI. | | Y | SMJ44400-10JDM | 629 |
| 5962-9084702MUA | E | 07/20/1998 | 2 | AUSTIN SEMI. | | Y | MT4C4001JC-10 | 629 |
| 5962-9084702MXA | E | 07/20/1998 | 2 | AUSTIN SEMI. | | Y | SMJ44400-10HRM | 629 |
| 5962-9084702MYA | E | 07/20/1998 | 2 | AUSTIN SEMI. | | Y | MT4C4001JEC-10 | 629 |
| 5962-9084702MZA | E | 07/20/1998 | | (NONE) | | | | 629 |
| 5962-9084703MMA | E | 07/20/1998 | 2 | AUSTIN SEMI. | | Y | MT4C4001JF-8 | 629 |
| 5962-9084703MNA | E | 07/20/1998 | 2 | AUSTIN SEMI. | | Y | MT4C4001JCZ-8 | 629 |
| 5962-9084703MRA | E | 07/20/1998 | 2 | AUSTIN SEMI. | | Y | MT4C4001JCN-8 | 629 |
| 5962-9084703MTA | E | 07/20/1998 | 2 | AUSTIN SEMI. | | Y | MT4C4001JECN-8 | 629 |
| 5962-9084703MUA | E | 07/20/1998 | 2 | AUSTIN SEMI. | | Y | SMJ44400-80JDM | 629 |
| 5962-9084703MUA | E | 07/20/1998 | 2 | AUSTIN SEMI. | | Y | MT4C4001JC-8 | 629 |
| 5962-9084703MXA | E | 07/20/1998 | 2 | AUSTIN SEMI. | | Y | SMJ44400-80HRM | 629 |
| 5962-9084703MYA | E | 07/20/1998 | 2 | AUSTIN SEMI. | | Y | MT4C4001JEC-8 | 629 |
| 5962-9084703MZA | E | 07/20/1998 | | (NONE) | | | | 629 |
| 5962-9084801MEA | | 11/26/1991 | 1 | TI | | Y | CD54HCT193F3A | 304 |
| 5962-9084901MCA | | 04/24/1991 | 1 | TI | | Y | CD54HCT107F3A | 156 |
| 5962-9085401HPA | F | 07/31/2003 | 1 | AGILENT | | Y | HCPL-5501#200 | 460 |
| 5962-9085401HPA | F | 07/31/2003 | 1 | MICROPAC | | Y | 66126-105 | 460 |
| 5962-9085401HPC | F | 07/31/2003 | 1 | AGILENT | | Y | HCPL-5501 | 460 |
| 5962-9085401HPC | F | 07/31/2003 | 1 | MICROPAC | | Y | 66126-105 | 460 |
| 5962-9085401KPA | F | 07/31/2003 | 1 | AGILENT | | Y | HCPL-550K#200 | 460 |
| 5962-9085401KPA | F | 07/31/2003 | 1 | MICROPAC | | Y | 66126-300 | 460 |
| 5962-9085401KPC | F | 07/31/2003 | 1 | AGILENT | | Y | HCPL-550K | 460 |
| 5962-9085401KPC | F | 07/31/2003 | 1 | MICROPAC | | Y | 66126-300 | 460 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9085401HXA | F | 07/31/2003 | 1 | AGILENT | | Y | HCPL-5501#300 | 460 |
| 5962-9085401HXA | F | 07/31/2003 | 1 | MICROPAC | | Y | 66126-105J | 460 |
| 5962-9085401HXC | F | 07/31/2003 | 1 | MICROPAC | | Y | 66126-105J | 460 |
| 5962-9085401KXA | F | 07/31/2003 | 1 | AGILENT | | Y | HCPL-550K#300 | 460 |
| 5962-9085401KXA | F | 07/31/2003 | 1 | MICROPAC | | Y | 66126-300J | 460 |
| 5962-9085401KXC | F | 07/31/2003 | 1 | MICROPAC | | Y | 66126-300J | 460 |
| 5962-9085401HYA | F | 07/31/2003 | 1 | AGILENT | | Y | HCPL-5501#100 | 460 |
| 5962-9085401HYC | F | 07/31/2003 | 1 | AGILENT | | Y | HCPL-5501#100 | 460 |
| 5962-9085401KYA | F | 07/31/2003 | 1 | AGILENT | | Y | HCPL-550K#100 | 460 |
| 5962-9085401KYC | F | 07/31/2003 | 1 | AGILENT | | Y | HCPL-550K#100 | 460 |
| 5962-9085501HPA | C | 03/24/1998 | 1 | AGILENT | | Y | HCPL-5601#200 | 460 |
| 5962-9085501HPA | C | 03/24/1998 | 1 | MICROPAC | | Y | 66056-005 | 460 |
| 5962-9085501HPC | C | 03/24/1998 | 1 | AGILENT | | Y | HCPL-5601 | 460 |
| 5962-9085501HPC | C | 03/24/1998 | 1 | MICROPAC | | Y | 66056-005 | 460 |
| 5962-9085501KPA | C | 03/24/1998 | 1 | AGILENT | | Y | HCPL-560K#200 | 460 |
| 5962-9085501KPA | C | 03/24/1998 | 1 | MICROPAC | | Y | 66056-301 | 460 |
| 5962-9085501KPC | C | 03/24/1998 | 1 | AGILENT | | Y | HCPL-560K | 460 |
| 5962-9085501KPC | C | 03/24/1998 | 1 | MICROPAC | | Y | 66056-301 | 460 |
| 5962-9085501HXA | C | 03/24/1998 | 1 | AGILENT | | Y | HCPL-5601#300 | 460 |
| 5962-9085501HXA | C | 03/24/1998 | 1 | MICROPAC | | Y | 66056-005J | 460 |
| 5962-9085501HXC | C | 03/24/1998 | 1 | MICROPAC | | Y | 66056-005J | 460 |
| 5962-9085501KXA | C | 03/24/1998 | 1 | AGILENT | | Y | HCPL-560K#300 | 460 |
| 5962-9085501KXA | C | 03/24/1998 | 1 | MICROPAC | | Y | 66056-301J | 460 |
| 5962-9085501KXC | C | 03/24/1998 | 1 | MICROPAC | | Y | 66056-301J | 460 |
| 5962-9085501HYA | C | 03/24/1998 | 1 | AGILENT | | Y | HCPL-5601#100 | 460 |
| 5962-9085501HYC | C | 03/24/1998 | 1 | AGILENT | | Y | HCPL-5601#100 | 460 |
| 5962-9085501KYA | C | 03/24/1998 | 1 | AGILENT | | Y | HCPL-560K#100 | 460 |
| 5962-9085501KYC | C | 03/24/1998 | 1 | AGILENT | | Y | HCPL-560K#100 | 460 |
| 5962-9085801MQA | | 01/29/1991 | | (NONE) | | | | 625 |
| 5962-9085802MQA | | 01/29/1991 | | (NONE) | | | | 625 |
| 5962-9085803MQA | | 01/29/1991 | | (NONE) | | | | 625 |
| 5962-9085804MQA | | 01/29/1991 | | (NONE) | | | | 625 |
| 5962-9085805MQA | | 01/29/1991 | | (NONE) | | | | 625 |
| 5962-9085806MQA | | 01/29/1991 | | (NONE) | | | | 625 |
| 5962-9085807MQA | | 01/29/1991 | | (NONE) | | | | 625 |
| 5962-9085808MQA | | 01/29/1991 | | (NONE) | | | | 625 |
| 5962-9086101Q2A | A | 10/17/1996 | | (NONE) | 09/15/1995 | | TL031 (GEN) | 703 |
| 5962-9086101QPA | A | 10/17/1996 | | (NONE) | 09/15/1995 | | TL031 (GEN) | 703 |
| 5962-9086102Q2A | A | 10/17/1996 | | (NONE) | 05/01/1998 | | TL032 (GEN) | 703 |
| 5962-9086102QPA | A | 10/17/1996 | | (NONE) | 05/01/1998 | | TL032 (GEN) | 703 |
| 5962-9086103Q2A | A | 10/17/1996 | | (NONE) | 05/01/1998 | | TL034 (GEN) | 703 |
| 5962-9086103QCA | A | 10/17/1996 | | (NONE) | 05/01/1998 | | TL034 (GEN) | 703 |
| 5962-9086201MGA | | 04/27/1993 | | (NONE) | | | LM759 (GEN) | 724 |
| 5962-9086301M3A | C | 05/07/2002 | | (NONE) | 09/15/1995 | | TLC32040 (GEN) | 899 |
| 5962-9086301MXA | C | 05/07/2002 | | (NONE) | 09/15/1995 | | TLC32040 (GEN) | 899 |
| 5962-9086302M3A | C | 05/07/2002 | | (NONE) | 05/01/2003 | | TLC32044 (GEN) | 899 |
| 5962-9086302MXA | C | 05/07/2002 | | (NONE) | 05/01/2003 | | TLC32044 (GEN) | 899 |
| 5962-9086303M3A | C | 05/07/2002 | | (NONE) | 10/31/2002 | | TLC32046M (GEN) | 899 |
| 5962-9086303MXA | C | 05/07/2002 | | (NONE) | 10/31/2002 | | TLC32046M (GEN) | 899 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9086401MUA | A | 10/25/1993 | | (NONE) | 06/29/2001 | | 68C901-4 (GEN) | 429 |
| 5962-9086401MXA | A | 10/25/1993 | | (NONE) | 06/29/2001 | | 68C901-4 (GEN) | 429 |
| 5962-9086401MYA | A | 10/25/1993 | | (NONE) | 06/29/2001 | | 68C901-4 (GEN) | 429 |
| 5962-9086401MZA | A | 10/25/1993 | | (NONE) | 06/29/2001 | | 68C901-4 (GEN) | 429 |
| 5962-9086402MUA | A | 10/25/1993 | | (NONE) | 06/29/2001 | | 68C901-5 (GEN) | 429 |
| 5962-9086402MXA | A | 10/25/1993 | | (NONE) | 06/29/2001 | | 68C901-5 (GEN) | 429 |
| 5962-9086402MYA | A | 10/25/1993 | | (NONE) | 06/29/2001 | | 68C901-5 (GEN) | 429 |
| 5962-9086402MZA | A | 10/25/1993 | | (NONE) | 06/29/2001 | | 68C901-5 (GEN) | 429 |
| 5962-9086403MUA | A | 10/25/1993 | | (NONE) | 06/29/2001 | | 68C901-8 (GEN) | 429 |
| 5962-9086403MXA | A | 10/25/1993 | | (NONE) | 06/29/2001 | | 68C901-8 (GEN) | 429 |
| 5962-9086403MYA | A | 10/25/1993 | | (NONE) | 06/29/2001 | | 68C901-8 (GEN) | 429 |
| 5962-9086403MZA | A | 10/25/1993 | | (NONE) | 06/29/2001 | | 68C901-8 (GEN) | 429 |
| 5962-9086801MPA | C | 02/24/2000 | | (NONE) | | | AD9617S (GEN) | 701 |
| 5962-9086801MXC | C | 02/24/2000 | | (NONE) | | | AD9617S (GEN) | 701 |
| 5962-9086802MPA | C | 02/24/2000 | | (NONE) | | | AD9617T (GEN) | 701 |
| 5962-9086802MXC | C | 02/24/2000 | | (NONE) | | | AD9617T (GEN) | 701 |
| 5962-9086803MPA | C | 02/24/2000 | | (NONE) | | | AD9618S (GEN) | 701 |
| 5962-9086803MXC | C | 02/24/2000 | | (NONE) | | | AD9618S (GEN) | 701 |
| 5962-9086804MPA | C | 02/24/2000 | | (NONE) | | | AD9618T (GEN) | 701 |
| 5962-9086804MXC | C | 02/24/2000 | | (NONE) | | | AD9618T (GEN) | 701 |
| 5962-9086901MUC | B | 08/06/1998 | | (NONE) | 03/31/2001 | | 28C512-25 (GEN) | 662 |
| 5962-9086901MXA | B | 08/06/1998 | | (NONE) | 03/31/2001 | | 28C512-25 (GEN) | 662 |
| 5962-9086901MYA | B | 08/06/1998 | | (NONE) | 03/31/2001 | | 28C512-25 (GEN) | 662 |
| 5962-9086901MZC | B | 08/06/1998 | | (NONE) | 03/31/2001 | | 28C512-25 (GEN) | 662 |
| 5962-9086902MUC | B | 08/06/1998 | | (NONE) | 03/31/2001 | | 28C512-25 (GEN) | 662 |
| 5962-9086902MXA | B | 08/06/1998 | | (NONE) | 12/15/1999 | | 28C512-25 (GEN) | 662 |
| 5962-9086902MYA | B | 08/06/1998 | | (NONE) | 03/31/2001 | | 28C512-25 (GEN) | 662 |
| 5962-9086902MZC | B | 08/06/1998 | | (NONE) | 03/31/2001 | | 28C512-25 (GEN) | 662 |
| 5962-9086903MUC | B | 08/06/1998 | 3 | XICOR | | | X28C512KMB-20 | 662 |
| 5962-9086903MXA | B | 08/06/1998 | 3 | XICOR | | | X28C512DMB-20 | 662 |
| 5962-9086903MYA | B | 08/06/1998 | | (NONE) | 03/31/2001 | | 28C512-20 (GEN) | 662 |
| 5962-9086903MZC | B | 08/06/1998 | | (NONE) | 03/31/2001 | | 28C512-20 (GEN) | 662 |
| 5962-9086904MUC | B | 08/06/1998 | | (NONE) | 03/31/2001 | | 28C512-20 (GEN) | 662 |
| 5962-9086904MXA | B | 08/06/1998 | | (NONE) | 12/15/1999 | | 28C512-20 (GEN) | 662 |
| 5962-9086904MYA | B | 08/06/1998 | | (NONE) | 03/31/2001 | | 28C512-20 (GEN) | 662 |
| 5962-9086904MZC | B | 08/06/1998 | | (NONE) | 03/31/2001 | | 28C512-20 (GEN) | 662 |
| 5962-9086905MUC | B | 08/06/1998 | | (NONE) | 03/31/2001 | | 28C512-15 (GEN) | 662 |
| 5962-9086905MXA | B | 08/06/1998 | | (NONE) | 03/31/2001 | | 28C512-15 (GEN) | 662 |
| 5962-9086905MYA | B | 08/06/1998 | | (NONE) | 03/31/2001 | | 28C512-15 (GEN) | 662 |
| 5962-9086905MZC | B | 08/06/1998 | | (NONE) | 03/31/2001 | | 28C512-15 (GEN) | 662 |
| 5962-9086906MUC | B | 08/06/1998 | | (NONE) | 03/31/2001 | | 28C512-15 (GEN) | 662 |
| 5962-9086906MXA | B | 08/06/1998 | | (NONE) | 03/31/2001 | | 28C512-15 (GEN) | 662 |
| 5962-9086906MYA | B | 08/06/1998 | | (NONE) | 03/31/2001 | | 28C512-15 (GEN) | 662 |
| 5962-9086906MZC | B | 08/06/1998 | | (NONE) | 03/31/2001 | | 28C512-15 (GEN) | 662 |
| 5962-9086907MUC | B | 08/06/1998 | | (NONE) | 03/31/2001 | | 28C512-12 (GEN) | 662 |
| 5962-9086907MXA | B | 08/06/1998 | | (NONE) | 03/31/2001 | | 28C512-12 (GEN) | 662 |
| 5962-9086907MYA | B | 08/06/1998 | | (NONE) | 03/31/2001 | | 28C512-12 (GEN) | 662 |
| 5962-9086907MZC | B | 08/06/1998 | | (NONE) | 03/31/2001 | | 28C512-12 (GEN) | 662 |
| 5962-9086908MUC | B | 08/06/1998 | | (NONE) | 03/31/2001 | | 28C512-12 (GEN) | 662 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9086908MXA | B | 08/06/1998 | | (NONE) | 03/31/2001 | | 28C512-12 (GEN) | 662 |
| 5962-9086908MYA | B | 08/06/1998 | | (NONE) | 03/31/2001 | | 28C512-12 (GEN) | 662 |
| 5962-9086908MZC | B | 08/06/1998 | | (NONE) | 03/31/2001 | | 28C512-12 (GEN) | 662 |
| 5962-9086909MYA | B | 08/06/1998 | | (NONE) | 03/31/2001 | | 28C513-25 (GEN) | 662 |
| 5962-9086910MYA | B | 08/06/1998 | | (NONE) | 03/31/2001 | | 28C513-25 (GEN) | 662 |
| 5962-9086911MYA | B | 08/06/1998 | | (NONE) | 03/31/2001 | | 28C513-20 (GEN) | 662 |
| 5962-9086912MYA | B | 08/06/1998 | | (NONE) | 03/31/2001 | | 28C513-20 (GEN) | 662 |
| 5962-9086913MYA | B | 08/06/1998 | | (NONE) | 03/31/2001 | | 28C513-15 (GEN) | 662 |
| 5962-9086914MYA | B | 08/06/1998 | | (NONE) | 03/31/2001 | | 28C513-15 (GEN) | 662 |
| 5962-9086915MYA | B | 08/06/1998 | 3 | XICOR | | | X28C513EMB-12 | 662 |
| 5962-9086916MYA | B | 08/06/1998 | | (NONE) | 03/31/2001 | | 28C513-12 (GEN) | 662 |
| 5962-9087001M3A | | 10/31/1990 | 3 | TI | | Y | SNJ54BCT543FK | 590 |
| 5962-9087001MKA | | 10/31/1990 | 3 | TI | | Y | SNJ54BCT543W | 590 |
| 5962-9087001MLA | | 10/31/1990 | 3 | TI | | Y | SNJ54BCT543JT | 590 |
| 5962-9087801MCA | | 09/11/1990 | | (NONE) | | | AH5010J (GEN) | 183 |
| 5962-9087901MVA | A | 01/15/1992 | | (NONE) | 09/01/1997 | | 5521 (GEN) | 899 |
| 5962-9088001MEA | | 09/11/1990 | | (NONE) | | | AH5012 (GEN) | 183 |
| 5962-9088101M2A | D | 01/16/2003 | 1 | TI | | Y | TLE2021MFKB | 701 |
| 5962-9088101MGA | D | 01/16/2003 | | (NONE) | | | TLE2021 (GEN) | 701 |
| 5962-9088101MPA | D | 01/16/2003 | 1 | TI | | Y | TLE2021MJGB | 701 |
| 5962-9088102M2A | D | 01/16/2003 | 1 | TI | | Y | TLE2022MFKB | 710 |
| 5962-9088102MGA | D | 01/16/2003 | | (NONE) | | | TLE2022 (GEN) | 710 |
| 5962-9088102BPA | D | 01/16/2003 | | (NONE) | | | TLE2022 (GEN) | 710 |
| 5962-9088102MPA | D | 01/16/2003 | 1 | TI | | Y | TLE2022MJGB | 710 |
| 5962-9088103M2A | D | 01/16/2003 | 1 | TI | | Y | TLE2024MFKB | 701 |
| 5962-9088103BCA | D | 01/16/2003 | | (NONE) | | | TLE2024 (GEN) | 701 |
| 5962-9088103MCA | D | 01/16/2003 | 1 | TI | | Y | TLE2024MJB | 701 |
| 5962-9088104Q2A | D | 01/16/2003 | 1 | TI | | Y | TLE2021AMFKB | 713 |
| 5962-9088104QPA | D | 01/16/2003 | 1 | TI | | Y | TLE2021AMJGB | 713 |
| 5962-9088105Q2A | D | 01/16/2003 | 1 | TI | | Y | TLE2022AMFKB | 713 |
| 5962-9088105QPA | D | 01/16/2003 | 1 | TI | | Y | TLE2022AMJGB | 713 |
| 5962-9088106Q2A | D | 01/16/2003 | 1 | TI | | Y | TLE2024AMFKB | 713 |
| 5962-9088106QCA | D | 01/16/2003 | 1 | TI | | Y | TLE2024AMJB | 713 |
| 5962-9088107Q2A | D | 01/16/2003 | 1 | TI | | Y | TLE2021BMFKB | 713 |
| 5962-9088107QPA | D | 01/16/2003 | 1 | TI | | Y | TLE2021BMJGB | 713 |
| 5962-9088108Q2A | D | 01/16/2003 | 1 | TI | | Y | TLE2022BMFKB | 713 |
| 5962-9088108QPA | D | 01/16/2003 | 1 | TI | | Y | TLE2022BMJGB | 713 |
| 5962-9088109Q2A | D | 01/16/2003 | 1 | TI | | Y | TLE2024BMFKB | 713 |
| 5962-9088109QCA | D | 01/16/2003 | 1 | TI | | Y | TLE2024BMJB | 713 |
| 5962-9088201M2A | C | 03/14/2003 | 3 | TI | | Y | TLC2201MFKB | 700 |
| 5962-9088201MGA | C | 03/14/2003 | | (NONE) | | | TLC2201M (GEN) | 700 |
| 5962-9088201MPA | C | 03/14/2003 | 3 | TI | | Y | TLC2201MJGB | 700 |
| 5962-9088202M2A | C | 03/14/2003 | 3 | TI | | Y | TLC2202MFKB | 710 |
| 5962-9088202MGA | C | 03/14/2003 | | (NONE) | | | TLC2202M (GEN) | 710 |
| 5962-9088202MPA | C | 03/14/2003 | 3 | TI | | Y | TLC2202MJGB | 710 |
| 5962-9088203Q2A | C | 03/14/2003 | 3 | TI | | Y | TLC2201AMFKB | 710 |
| 5962-9088203QPA | C | 03/14/2003 | 3 | TI | | Y | TLC2201AMJGB | 710 |
| 5962-9088204Q2A | C | 03/14/2003 | 3 | TI | | Y | TLC2202AMFKB | 710 |
| 5962-9088204QPA | C | 03/14/2003 | 3 | TI | | Y | TLC2202AMJGB | 710 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9088301QEA | C | 03/18/2003 | | (NONE) | | | LM2940-8 (GEN) | 782 |
| 5962-9088301MYA | C | 03/18/2003 | | (NONE) | 09/09/1999 | | LM2940-8 (GEN) | 782 |
| 5962-9088401QEA | G | 03/20/2002 | 3 | NATIONAL | | Y | LM2940J-12/883 | 782 |
| 5962-9088401MMA | G | 03/20/2002 | 1 | INTER. RECT. | | | OM2940-12SRM/883B | 782 |
| 5962-9088401MNA | G | 03/20/2002 | 1 | INTER. RECT. | | | OM2940-12N5M/883B | 782 |
| 5962-9088401MUA | G | 03/20/2002 | 1 | INTER. RECT. | | | OM2940-12STM | 782 |
| 5962-9088401QXA | G | 03/20/2002 | 3 | NATIONAL | | Y | LM2940WG-12/883 | 782 |
| 5962-9088401MYA | G | 03/20/2002 | | (NONE) | 09/09/1999 | | LM2940-12 (GEN) | 782 |
| 5962-9088501QEA | F | 03/29/2002 | 3 | NATIONAL | | Y | LM2940J-15/883 | 782 |
| 5962-9088501MMA | F | 03/29/2002 | 1 | INTER. RECT. | | | OM2940-15SRM/883B | 782 |
| 5962-9088501MNA | F | 03/29/2002 | 1 | INTER. RECT. | | | OM2940-15N5M/883B | 782 |
| 5962-9088501MUA | F | 03/29/2002 | 1 | INTER. RECT. | | | OM2940-15STM | 782 |
| 5962-9088501QXA | F | 03/29/2002 | 3 | NATIONAL | | Y | LM2940WG-15/883 | 782 |
| 5962-9088501MYA | F | 03/29/2002 | | (NONE) | 12/07/1999 | | LM2940-15 (GEN) | 782 |
| 5962-9088801M2A | | 05/21/1993 | | (NONE) | | | 6409 (GEN) | 441 |
| 5962-9088801MRA | | 05/21/1993 | | (NONE) | 03/25/2001 | | HD-6409 (GEN) | 441 |
| 5962-9088901M2A | B | 09/07/1995 | 2 | TI | | Y | SNJ54BCT126FK | 520 |
| 5962-9088901MCA | B | 09/07/1995 | 2 | TI | | Y | SNJ54BCT126J | 520 |
| 5962-9088901MDA | B | 09/07/1995 | 2 | TI | | Y | SNJ54BCT126W | 520 |
| 5962-9089101M2A | A | 01/29/2002 | 1 | SILICONIX | | Y | DG601AZ/883 | 183 |
| 5962-9089101MEA | A | 01/29/2002 | 1 | SILICONIX | | Y | DG601AK/883 | 183 |
| 5962-9089401MEA | A | 08/30/2001 | 0 | ANALOG (2) | | Y | AD526SD/883 | 751 |
| 5962-9089501M2A | E | 01/22/2003 | 3 | TI | | Y | TLC2652MFKB | 701 |
| 5962-9089501MCA | E | 01/22/2003 | 3 | TI | | Y | TLC2652MJB | 701 |
| 5962-9089501MGA | E | 01/22/2003 | | (NONE) | | | TLC2652MLB (GEN) | 701 |
| 5962-9089501BPA | E | 01/22/2003 | | (NONE) | | | TLC2652M (GEN) | 701 |
| 5962-9089501MPA | E | 01/22/2003 | 3 | TI | | Y | TLC2652MJGB | 701 |
| 5962-9089502M2A | E | 01/22/2003 | 3 | TI | | Y | TLC2654MFKB | 701 |
| 5962-9089502MCA | E | 01/22/2003 | 3 | TI | | Y | TLC2654MJB | 701 |
| 5962-9089502MGA | E | 01/22/2003 | | (NONE) | | | TLC2654M (GEN) | 701 |
| 5962-9089502BPA | E | 01/22/2003 | | (NONE) | | | TLC2654M (GEN) | 701 |
| 5962-9089502MPA | E | 01/22/2003 | 3 | TI | | Y | TLC2654MJGB | 701 |
| 5962-9089503M2A | E | 01/22/2003 | 3 | TI | | Y | TLC2652AMFKB | 701 |
| 5962-9089503MCA | E | 01/22/2003 | 3 | TI | | Y | TLC2652AMJB | 701 |
| 5962-9089503MGA | E | 01/22/2003 | | (NONE) | | | TLC2652A (GEN) | 701 |
| 5962-9089503MPA | E | 01/22/2003 | 3 | TI | | Y | TLC2652AMJGB | 701 |
| 5962-9089504Q2A | E | 01/22/2003 | 3 | TI | | Y | TLC2654AMFKB | 701 |
| 5962-9089504QCA | E | 01/22/2003 | 1 | TI | | Y | TLC2654AMJB | 701 |
| 5962-9089504QPA | E | 01/22/2003 | 1 | TI | | Y | TLC2654AMJGB | 701 |
| 5962-9089601M2A | D | 01/14/2003 | 3 | TI | | Y | TLE2027MFKB | 701 |
| 5962-9089601MGA | D | 01/14/2003 | | (NONE) | | | TLE2027M (GEN) | 701 |
| 5962-9089601BPA | D | 01/14/2003 | | (NONE) | | | TLE2027M (GEN) | 701 |
| 5962-9089601MPA | D | 01/14/2003 | 3 | TI | | Y | TLE2027MJGB | 701 |
| 5962-9089602M2A | D | 01/14/2003 | | (NONE) | 06/30/2000 | | TLE2037M (GEN) | 701 |
| 5962-9089602MGA | D | 01/14/2003 | | (NONE) | | | TLE2037M (GEN) | 701 |
| 5962-9089602MPA | D | 01/14/2003 | | (NONE) | 06/30/2000 | | TLE2037M (GEN) | 701 |
| 5962-9089603Q2A | D | 01/14/2003 | 2 | TI | | Y | TLE2027AMFKB | 701 |
| 5962-9089603QPA | D | 01/14/2003 | 2 | TI | | Y | TLE2027AMJGB | 701 |
| 5962-9089604QPA | D | 01/14/2003 | | (NONE) | 06/30/2000 | | TLE2037AM (GEN) | 701 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9089901MTA | C | 11/16/1999 | | (NONE) | 04/15/1996 | | 28F010 (GEN) | 669 |
| 5962-9089901MUA | C | 11/16/1999 | | (NONE) | 12/24/1997 | | 28F010 (GEN) | 669 |
| 5962-9089901QUA | C | 11/16/1999 | 3 | AUSTIN SEMI. | | Y | SMJ28F010B-25HKM | 669 |
| 5962-9089901MXA | C | 11/16/1999 | | (NONE) | 12/24/1997 | | 28F010 (GEN) | 669 |
| 5962-9089901QXA | C | 11/16/1999 | 3 | AUSTIN SEMI. | | Y | SMJ28F010B-25JDDM | 669 |
| 5962-9089901MYA | C | 11/16/1999 | | (NONE) | 12/24/1997 | | 28F010 (GEN) | 669 |
| 5962-9089901QYA | C | 11/16/1999 | 3 | AUSTIN SEMI. | | Y | SMJ28F010B-25FEM | 669 |
| 5962-9089901MZA | C | 11/16/1999 | | (NONE) | | | 28F010 (GEN) | 669 |
| 5962-9089902MTA | C | 11/16/1999 | | (NONE) | 04/15/1996 | | 28F010 (GEN) | 669 |
| 5962-9089902MUA | C | 11/16/1999 | | (NONE) | 12/24/1997 | | 28F010 (GEN) | 669 |
| 5962-9089902QUA | C | 11/16/1999 | 3 | AUSTIN SEMI. | | Y | SMJ28F010B-20HKM | 669 |
| 5962-9089902MXA | C | 11/16/1999 | | (NONE) | 12/24/1997 | | 28F010 (GEN) | 669 |
| 5962-9089902QXA | C | 11/16/1999 | 3 | AUSTIN SEMI. | | Y | SMJ28F010B-20JDDM | 669 |
| 5962-9089902MYA | C | 11/16/1999 | | (NONE) | 12/24/1997 | | 28F010 (GEN) | 669 |
| 5962-9089902QYA | C | 11/16/1999 | 3 | AUSTIN SEMI. | | Y | SMJ28F010B-20FEM | 669 |
| 5962-9089902MZA | C | 11/16/1999 | | (NONE) | | | 28F010 (GEN) | 669 |
| 5962-9089903MTA | C | 11/16/1999 | | (NONE) | 04/15/1996 | | 28F010 (GEN) | 669 |
| 5962-9089903MUA | C | 11/16/1999 | | (NONE) | 12/24/1997 | | 28F010 (GEN) | 669 |
| 5962-9089903QUA | C | 11/16/1999 | 3 | AUSTIN SEMI. | | Y | SMJ28F010B-15HKM | 669 |
| 5962-9089903MXA | C | 11/16/1999 | | (NONE) | 12/24/1997 | | 28F010 (GEN) | 669 |
| 5962-9089903QXA | C | 11/16/1999 | 3 | AUSTIN SEMI. | | Y | SMJ28F010B-15JDDM | 669 |
| 5962-9089903MYA | C | 11/16/1999 | | (NONE) | 12/24/1997 | | 28F010 (GEN) | 669 |
| 5962-9089903QYA | C | 11/16/1999 | 3 | AUSTIN SEMI. | | Y | SMJ28F010B-15FEM | 669 |
| 5962-9089903MZA | C | 11/16/1999 | | (NONE) | | | 28F010 (GEN) | 669 |
| 5962-9089904MTA | C | 11/16/1999 | | (NONE) | 04/15/1996 | | 28F010 (GEN) | 669 |
| 5962-9089904MUA | C | 11/16/1999 | | (NONE) | 12/24/1997 | | 28F010 (GEN) | 669 |
| 5962-9089904QUA | C | 11/16/1999 | 3 | AUSTIN SEMI. | | Y | SMJ28F010B-12HKM | 669 |
| 5962-9089904MXA | C | 11/16/1999 | | (NONE) | 12/24/1997 | | 28F010 (GEN) | 669 |
| 5962-9089904QXA | C | 11/16/1999 | 3 | AUSTIN SEMI. | | Y | SMJ28F010B-12JDDM | 669 |
| 5962-9089904MYA | C | 11/16/1999 | | (NONE) | 12/24/1997 | | 28F010 (GEN) | 669 |
| 5962-9089904QYA | C | 11/16/1999 | 3 | AUSTIN SEMI. | | Y | SMJ28F010B-12FEM | 669 |
| 5962-9089904MZA | C | 11/16/1999 | | (NONE) | | | 28F010 (GEN) | 669 |
| 5962-9089905MTA | C | 11/16/1999 | | (NONE) | | | 28F010 (GEN) | 669 |
| 5962-9089905MUA | C | 11/16/1999 | | (NONE) | | | 28F010 (GEN) | 669 |
| 5962-9089905QUA | C | 11/16/1999 | 3 | AUSTIN SEMI. | | Y | SMJ28F010B-25HKM | 669 |
| 5962-9089905MXA | C | 11/16/1999 | | (NONE) | | | 28F010 (GEN) | 669 |
| 5962-9089905QXA | C | 11/16/1999 | 3 | AUSTIN SEMI. | | Y | SMJ28F010B-25JDDM | 669 |
| 5962-9089905MYA | C | 11/16/1999 | | (NONE) | | | 28F010 (GEN) | 669 |
| 5962-9089905QYA | C | 11/16/1999 | 3 | AUSTIN SEMI. | | Y | SMJ28F010B-25FEM | 669 |
| 5962-9089905MZA | C | 11/16/1999 | | (NONE) | | | 28F010 (GEN) | 669 |
| 5962-9089906MTA | C | 11/16/1999 | | (NONE) | | | 28F010 (GEN) | 669 |
| 5962-9089906MUA | C | 11/16/1999 | | (NONE) | | | 28F010 (GEN) | 669 |
| 5962-9089906QUA | C | 11/16/1999 | 3 | AUSTIN SEMI. | | Y | SMJ28F010B-20HKM | 669 |
| 5962-9089906MXA | C | 11/16/1999 | | (NONE) | | | 28F010 (GEN) | 669 |
| 5962-9089906QXA | C | 11/16/1999 | 3 | AUSTIN SEMI. | | Y | SMJ28F010B-20JDDM | 669 |
| 5962-9089906MYA | C | 11/16/1999 | | (NONE) | | | 28F010 (GEN) | 669 |
| 5962-9089906QYA | C | 11/16/1999 | 3 | AUSTIN SEMI. | | Y | SMJ28F010B-20FEM | 669 |
| 5962-9089906MZA | C | 11/16/1999 | | (NONE) | | | 28F010 (GEN) | 669 |
| 5962-9089907MTA | C | 11/16/1999 | | (NONE) | | | 28F010 (GEN) | 669 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9089907MUA | C | 11/16/1999 | | (NONE) | | | 28F010 (GEN) | 669 |
| 5962-9089907QUA | C | 11/16/1999 | 3 | AUSTIN SEMI. | | Y | SMJ28F010B-15HKM | 669 |
| 5962-9089907MXA | C | 11/16/1999 | | (NONE) | | | 28F010 (GEN) | 669 |
| 5962-9089907QXA | C | 11/16/1999 | 3 | AUSTIN SEMI. | | Y | SMJ28F010B-15JDDM | 669 |
| 5962-9089907MYA | C | 11/16/1999 | | (NONE) | | | 28F010 (GEN) | 669 |
| 5962-9089907QYA | C | 11/16/1999 | 3 | AUSTIN SEMI. | | Y | SMJ28F010B-15FEM | 669 |
| 5962-9089907MZA | C | 11/16/1999 | | (NONE) | | | 28F010 (GEN) | 669 |
| 5962-9089908MTA | C | 11/16/1999 | | (NONE) | | | 28F010 (GEN) | 669 |
| 5962-9089908MUA | C | 11/16/1999 | | (NONE) | | | 28F010 (GEN) | 669 |
| 5962-9089908QUA | C | 11/16/1999 | 3 | AUSTIN SEMI. | | Y | SMJ28F010B-12HKM | 669 |
| 5962-9089908MXA | C | 11/16/1999 | | (NONE) | | | 28F010 (GEN) | 669 |
| 5962-9089908QXA | C | 11/16/1999 | 3 | AUSTIN SEMI. | | Y | SMJ28F010B-12JDDM | 669 |
| 5962-9089908MYA | C | 11/16/1999 | | (NONE) | | | 28F010 (GEN) | 669 |
| 5962-9089908QYA | C | 11/16/1999 | 3 | AUSTIN SEMI. | | Y | SMJ28F010B-12FEM | 669 |
| 5962-9089908MZA | C | 11/16/1999 | | (NONE) | | | 28F010 (GEN) | 669 |
| 5962-9089909MTA | C | 11/16/1999 | | (NONE) | 04/15/1996 | | 28F010 (GEN) | 669 |
| 5962-9089909MUA | C | 11/16/1999 | | (NONE) | 12/24/1997 | | 28F010 (GEN) | 669 |
| 5962-9089909MXA | C | 11/16/1999 | | (NONE) | 12/24/1997 | | 28F010 (GEN) | 669 |
| 5962-9089909MYA | C | 11/16/1999 | | (NONE) | 12/24/1997 | | 28F010 (GEN) | 669 |
| 5962-9089909MZA | C | 11/16/1999 | | (NONE) | | | 28F010 (GEN) | 669 |
| 5962-9089910QUA | C | 11/16/1999 | 3 | AUSTIN SEMI. | | Y | SMJ28F010B-25HKM | 669 |
| 5962-9089910MXA | C | 11/16/1999 | | (NONE) | | | 28F010A (GEN) | 669 |
| 5962-9089910QXA | C | 11/16/1999 | 3 | AUSTIN SEMI. | | Y | SMJ28F010B-25JDDM | 669 |
| 5962-9089910MYA | C | 11/16/1999 | | (NONE) | | | 28F010A (GEN) | 669 |
| 5962-9089910QYA | C | 11/16/1999 | 3 | AUSTIN SEMI. | | Y | SMJ28F010B-25FEM | 669 |
| 5962-9089911QUA | C | 11/16/1999 | 3 | AUSTIN SEMI. | | Y | SMJ28F010B-20HKM | 669 |
| 5962-9089911MXA | C | 11/16/1999 | | (NONE) | | | 28F010A (GEN) | 669 |
| 5962-9089911QXA | C | 11/16/1999 | 3 | AUSTIN SEMI. | | Y | SMJ28F010B-20JDDM | 669 |
| 5962-9089911MYA | C | 11/16/1999 | | (NONE) | | | 28F010A (GEN) | 669 |
| 5962-9089911QYA | C | 11/16/1999 | 3 | AUSTIN SEMI. | | Y | SMJ28F010B-20FEM | 669 |
| 5962-9089912QUA | C | 11/16/1999 | 3 | AUSTIN SEMI. | | Y | SMJ28F010B-15HKM | 669 |
| 5962-9089912MXA | C | 11/16/1999 | | (NONE) | | | 28F010A (GEN) | 669 |
| 5962-9089912QXA | C | 11/16/1999 | 3 | AUSTIN SEMI. | | Y | SMJ28F010B-15JDDM | 669 |
| 5962-9089912MYA | C | 11/16/1999 | | (NONE) | | | 28F010A (GEN) | 669 |
| 5962-9089912QYA | C | 11/16/1999 | 3 | AUSTIN SEMI. | | Y | SMJ28F010B-15FEM | 669 |
| 5962-9089913QUA | C | 11/16/1999 | 3 | AUSTIN SEMI. | | Y | SMJ28F010B-12HKM | 669 |
| 5962-9089913MXA | C | 11/16/1999 | | (NONE) | | | 28F010A (GEN) | 669 |
| 5962-9089913QXA | C | 11/16/1999 | 3 | AUSTIN SEMI. | | Y | SMJ28F010B-12JDDM | 669 |
| 5962-9089913MYA | C | 11/16/1999 | | (NONE) | | | 28F010A (GEN) | 669 |
| 5962-9089913QYA | C | 11/16/1999 | 3 | AUSTIN SEMI. | | Y | SMJ28F010B-12FEM | 669 |
| 5962-9090101M3A | | 10/26/1992 | | (NONE) | 04/27/1998 | | 29FCT52A (GEN) | 590 |
| 5962-9090101MKA | | 10/26/1992 | | (NONE) | 04/27/1998 | | 29FCT52A (GEN) | 590 |
| 5962-9090101MLA | | 10/26/1992 | | (NONE) | 04/27/1998 | | 29FCT52A (GEN) | 590 |
| 5962-9090102M3A | | 10/26/1992 | | (NONE) | 04/27/1998 | | 29FCT52B (GEN) | 590 |
| 5962-9090102MKA | | 10/26/1992 | | (NONE) | 04/27/1998 | | 29FCT52B (GEN) | 590 |
| 5962-9090102MLA | | 10/26/1992 | | (NONE) | 04/27/1998 | | 29FCT52B (GEN) | 590 |
| 5962-9090103M3A | | 10/26/1992 | | (NONE) | 04/27/1998 | | 29FCT52C (GEN) | 590 |
| 5962-9090103MKA | | 10/26/1992 | | (NONE) | 04/27/1998 | | 29FCT52C (GEN) | 590 |
| 5962-9090103MLA | | 10/26/1992 | | (NONE) | 04/27/1998 | | 29FCT52C (GEN) | 590 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9090201HXC | A | 04/29/2002 | | (NONE) | | | MSK332B-12 (GEN) | 899 |
| 5962-9090202HXC | A | 04/29/2002 | | (NONE) | | | MSK332B-15 (GEN) | 899 |
| 5962-9090501M2A | A | 08/29/2001 | 3 | ANALOG (5) | | Y | OP160ARC/883 | 702 |
| 5962-9090501MPA | A | 08/29/2001 | 3 | ANALOG (5) | | Y | OP160AZ/883 | 702 |
| 5962-9090601M2A | | 10/01/1990 | 1 | ROCHESTER | | Y | 54ACT11353/B2A | 273 |
| 5962-9090601MEA | | 10/01/1990 | 1 | ROCHESTER | | Y | 54ACT11353/BEA | 273 |
| 5962-9090801M2A | A | 01/28/2003 | 1 | ANALOG (3) | | Y | AD7224UE/883B | 591 |
| 5962-9090801MVA | A | 01/28/2003 | 1 | ANALOG (3) | | Y | AD7224UQ/883B | 591 |
| 5962-9091001M2A | | 08/26/1991 | 3 | NATIONAL | | Y | 54F377LMQB | 159 |
| 5962-9091001MRA | | 08/26/1991 | 3 | NATIONAL | | Y | 54F377DMQB | 159 |
| 5962-9091001MSA | | 08/26/1991 | 3 | NATIONAL | | Y | 54F377FMQB | 159 |
| 5962-9091101M3A | B | 03/28/2002 | | (NONE) | 09/30/2000 | | AD9712BS (GEN) | 591 |
| 5962-9091101MXA | B | 03/28/2002 | | (NONE) | 09/30/2000 | | AD9712BS (GEN) | 591 |
| 5962-9091102M3A | B | 03/28/2002 | | (NONE) | 09/30/2000 | | AD9712BT (GEN) | 591 |
| 5962-9091102MXA | B | 03/28/2002 | | (NONE) | 09/30/2000 | | AD9712BT (GEN) | 591 |
| 5962-9091103M3A | B | 03/28/2002 | | (NONE) | 09/30/2000 | | AD9713BS (GEN) | 591 |
| 5962-9091103MXA | B | 03/28/2002 | | (NONE) | 09/30/2000 | | AD9713BS (GEN) | 591 |
| 5962-9091104M3A | B | 03/28/2002 | | (NONE) | 09/30/2000 | | AD9713BTE (GEN) | 591 |
| 5962-9091104MXA | B | 03/28/2002 | 1 | AUSTIN SEMI. | | Y | AS9713BC28/883C | 591 |
| 5962-9091201MXA | | 11/06/1992 | | (NONE) | 08/02/1996 | | 27C020-250 (GEN) | 669 |
| 5962-9091201MYA | | 11/06/1992 | | (NONE) | 08/02/1996 | | 27C020-250 (GEN) | 669 |
| 5962-9091202MXA | | 11/06/1992 | | (NONE) | 08/02/1996 | | 27C020-200 (GEN) | 669 |
| 5962-9091202MYA | | 11/06/1992 | | (NONE) | 08/02/1996 | | 27C020-200 (GEN) | 669 |
| 5962-9091203MXA | | 11/06/1992 | | (NONE) | 08/02/1996 | | 27C020-150 (GEN) | 669 |
| 5962-9091203MYA | | 11/06/1992 | | (NONE) | 08/02/1996 | | 27C020-150 (GEN) | 669 |
| 5962-9091301MXA | | 02/19/1993 | 2 | QP SEMI | | Y | CY7C287-65WMB | 663 |
| 5962-9091301MYA | | 02/19/1993 | 2 | QP SEMI | | Y | CY7C287-65QMB | 663 |
| 5962-9091302MXA | | 02/19/1993 | 2 | QP SEMI | | Y | CY7C287-55WMB | 663 |
| 5962-9091302MYA | | 02/19/1993 | 2 | QP SEMI | | Y | CY7C287-55QMB | 663 |
| 5962-9091401M2A | D | 03/26/2003 | | (NONE) | | | LM185B (GEN) | 785 |
| 5962-9091401MXA | D | 03/26/2003 | 1 | NATIONAL | | Y | LM185BYH/883 | 785 |
| 5962-9091601B2A | A | 05/06/1998 | | (NONE) | | | 54AC520 (GEN) | 209 |
| 5962-9091601M2A | A | 05/06/1998 | 3 | NATIONAL | | Y | 54AC520LMQB | 209 |
| 5962-9091601S2A | A | 05/06/1998 | | (NONE) | | | 54AC520 (GEN) | 209 |
| 5962R9091601B2A | A | 05/06/1998 | 3 | NATIONAL | | Y | JM54AC520B2A-RH | 209 |
| 5962R9091601S2A | A | 05/06/1998 | 3 | NATIONAL | | Y | JM54AC520S2A-RH | 209 |
| 5962-9091601BRA | A | 05/06/1998 | | (NONE) | | | 54AC520 (GEN) | 209 |
| 5962-9091601MRA | A | 05/06/1998 | 3 | NATIONAL | | Y | 54AC520DMQB | 209 |
| 5962-9091601SRA | A | 05/06/1998 | | (NONE) | | | 54AC520 (GEN) | 209 |
| 5962R9091601BRA | A | 05/06/1998 | 3 | NATIONAL | | Y | JM54AC520BRA-RH | 209 |
| 5962R9091601SRA | A | 05/06/1998 | 3 | NATIONAL | | Y | JM54AC520SRA-RH | 209 |
| 5962-9091601BSA | A | 05/06/1998 | 3 | NATIONAL | | Y | JM54AC520BSA | 209 |
| 5962-9091601MSA | A | 05/06/1998 | 3 | NATIONAL | | Y | 54AC520FMQB | 209 |
| 5962-9091601SSA | A | 05/06/1998 | | (NONE) | | | 54AC520 (GEN) | 209 |
| 5962R9091601BSA | A | 05/06/1998 | 3 | NATIONAL | | Y | JM54AC520BSA-RH | 209 |
| 5962R9091601SSA | A | 05/06/1998 | 3 | NATIONAL | | Y | JM54AC520SSA-RH | 209 |
| 5962-9091602M2A | A | 05/06/1998 | | (NONE) | 09/15/1995 | | 54AC11520 (GEN) | 209 |
| 5962-9091602MRA | A | 05/06/1998 | | (NONE) | 09/15/1995 | | 54AC11520 (GEN) | 209 |
| 5962-9092501MCA | A | 06/07/1993 | | (NONE) | | | CLC500 (GEN) | 702 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9092701M3A | F | 01/03/2000 | 1 | ANALOG (4) | | Y | AD9048TE/883B | 592 |
| 5962-9092701MXA | F | 01/03/2000 | 1 | ANALOG (4) | | Y | AD9048TQ/883B | 592 |
| 5962-9092702M3A | F | 01/03/2000 | 1 | ANALOG (4) | | Y | AD9048SE/883B | 592 |
| 5962-9092702MXA | F | 01/03/2000 | 1 | ANALOG (4) | | Y | AD9048SQ/883B | 592 |
| 5962-9092703M3A | F | 01/03/2000 | 1 | ATMEL GREN. | | | TS83048ME1B/C | 592 |
| 5962-9092703MXA | F | 01/03/2000 | 1 | ATMEL GREN. | | | TS83048MCB/C | 592 |
| 5962-9093001M3A | | 05/07/1993 | 3 | QP SEMI | | Y | CY7C269-50QMB | 660 |
| 5962-9093001MXA | | 05/07/1993 | 3 | QP SEMI | | Y | CY7C269-50WMB | 660 |
| 5962-9093001MYA | | 05/07/1993 | | (NONE) | | | 7C269-50 (GEN) | 660 |
| 5962-9093002M3A | | 05/07/1993 | 3 | QP SEMI | | Y | CY7C269-25QMB | 660 |
| 5962-9093002MXA | | 05/07/1993 | 3 | QP SEMI | | Y | CY7C269-25WMB | 660 |
| 5962-9093002MYA | | 05/07/1993 | | (NONE) | | | 7C269-25 (GEN) | 660 |
| 5962-9093003M3A | | 05/07/1993 | 3 | QP SEMI | | Y | CY7C269-15QMB | 660 |
| 5962-9093003MXA | | 05/07/1993 | 3 | QP SEMI | | Y | CY7C269-15WMB | 660 |
| 5962-9093003MYA | | 05/07/1993 | | (NONE) | | | 7C269-15 (GEN) | 660 |
| 5962-9093201M2A | B | 04/14/2003 | 1 | QP SEMI | | Y | TL7770-5/M2A | 787 |
| 5962-9093201MEA | B | 04/14/2003 | 1 | QP SEMI | | Y | TL7770-5/MEA | 787 |
| 5962-9093202M2A | B | 04/14/2003 | | (NONE) | 05/01/1998 | | TL7770-12 (GEN) | 787 |
| 5962-9093202MEA | B | 04/14/2003 | | (NONE) | 05/01/1998 | | TL7770-12 (GEN) | 787 |
| 5962-9093203M2A | B | 04/14/2003 | | (NONE) | | | TL7770-15 (GEN) | 787 |
| 5962-9093203MEA | B | 04/14/2003 | | (NONE) | | | TL7770-15 (GEN) | 787 |
| 5962-9093401M2A | A | 05/06/1999 | | (NONE) | | | 54ACT399 (GEN) | 249 |
| 5962-9093401Q2A | A | 05/06/1999 | 3 | NATIONAL | | Y | 54ACT399LMQB | 249 |
| 5962R9093401Q2A | A | 05/06/1999 | 3 | NATIONAL | | Y | 54ACT399LMQB-RH | 249 |
| 5962R9093401V2A | A | 05/06/1999 | 3 | NATIONAL | | Y | 54ACT399ERQMLV | 249 |
| 5962-9093401MEA | A | 05/06/1999 | | (NONE) | | | 54ACT399 (GEN) | 249 |
| 5962-9093401QEA | A | 05/06/1999 | 3 | NATIONAL | | Y | 54ACT399DMQB | 249 |
| 5962R9093401QEA | A | 05/06/1999 | 3 | NATIONAL | | Y | 54ACT399DMQB-RH | 249 |
| 5962R9093401VEA | A | 05/06/1999 | 3 | NATIONAL | | Y | 54ACT399JRQMLV | 249 |
| 5962-9093401MFA | A | 05/06/1999 | | (NONE) | | | 54ACT399 (GEN) | 249 |
| 5962-9093401QFA | A | 05/06/1999 | 3 | NATIONAL | | Y | 54ACT399FMQB | 249 |
| 5962R9093401QFA | A | 05/06/1999 | 3 | NATIONAL | | Y | 54ACT399FMQB-RH | 249 |
| 5962R9093401VFA | A | 05/06/1999 | 3 | NATIONAL | | Y | 54ACT399WRQMLV | 249 |
| 5962-9093501M2A | | 08/28/1992 | | (NONE) | 09/30/1995 | | 10538 (GEN) | 319 |
| 5962-9093501MEA | | 08/28/1992 | | (NONE) | 09/30/1995 | | 10538 (GEN) | 319 |
| 5962-9093501MFA | | 08/28/1992 | | (NONE) | 09/30/1995 | | 10538 (GEN) | 319 |
| 5962-9093701M2A | B | 09/07/1995 | 1 | TI | | Y | SNJ54BCT125FK | 520 |
| 5962-9093701MCA | B | 09/07/1995 | 1 | TI | | Y | SNJ54BCT125J | 520 |
| 5962-9093701MDA | B | 09/07/1995 | 1 | TI | | Y | SNJ54BCT125W | 520 |
| 5962-9093801M2A | A | 11/19/1991 | 3 | TI | | Y | SNJ54BCT760FK | 519 |
| 5962-9093801MRA | A | 11/19/1991 | 3 | TI | | Y | SNJ54BCT760J | 519 |
| 5962-9093801MSA | A | 11/19/1991 | 3 | TI | | Y | SNJ54BCT760W | 519 |
| 5962-9093901M2A | B | 10/16/1992 | 1 | TI | | Y | SNJ54BCT2240FK | 529 |
| 5962-9093901MRA | B | 10/16/1992 | 1 | TI | | Y | SNJ54BCT2240J | 529 |
| 5962-9093901MSA | B | 10/16/1992 | 1 | TI | | Y | SNJ54BCT2240W | 529 |
| 5962-9094001M2A | | 10/02/1990 | 3 | TI | | Y | SNJ54BCT623FK | 590 |
| 5962-9094001MRA | | 10/02/1990 | 3 | TI | | Y | SNJ54BCT623J | 590 |
| 5962-9094001MSA | | 10/02/1990 | 3 | TI | | Y | SNJ54BCT623W | 590 |
| 5962-9094301H3A | | 11/30/1994 | 1 | SATCON | | Y | HC9172 | 785 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9094301H3C | | 11/30/1994 | 1 | SATCON | | Y | HC9172 | 785 |
| 5962-9094601MXA | D | 06/18/1996 | | (NONE) | 12/24/1997 | | 80960MC16 (GEN) | 404 |
| 5962-9094601MYA | D | 06/18/1996 | | (NONE) | 12/24/1997 | | 80960MC16 (GEN) | 404 |
| 5962-9094602MXA | D | 06/18/1996 | | (NONE) | 12/24/1997 | | 80960MC20 (GEN) | 404 |
| 5962-9094602MYA | D | 06/18/1996 | | (NONE) | 12/24/1997 | | 80960MC20 (GEN) | 404 |
| 5962-9094603MXA | D | 06/18/1996 | | (NONE) | 12/24/1997 | | 80960MC25 (GEN) | 404 |
| 5962-9094603MYA | D | 06/18/1996 | | (NONE) | 12/24/1997 | | 80960MC25 (GEN) | 404 |
| 5962-9094604MXA | D | 06/18/1996 | | (NONE) | 12/24/1997 | | 80960XA16 (GEN) | 404 |
| 5962-9094604MYA | D | 06/18/1996 | | (NONE) | 12/24/1997 | | 80960XA16 (GEN) | 404 |
| 5962-9094605MXA | D | 06/18/1996 | | (NONE) | 12/24/1997 | | 80960XA20 (GEN) | 404 |
| 5962-9094605MYA | D | 06/18/1996 | | (NONE) | 12/24/1997 | | 80960XA20 (GEN) | 404 |
| 5962-9094606MXA | D | 06/18/1996 | | (NONE) | 12/24/1997 | | 80960XA25 (GEN) | 404 |
| 5962-9094606MYA | D | 06/18/1996 | | (NONE) | 12/24/1997 | | 80960XA25 (GEN) | 404 |
| 5962-9095401HXA | B | 07/31/2003 | 1 | ADV. ANALOG | | Y | ATO2815T/CH | 594 |
| 5962-9095401HZA | B | 07/31/2003 | 1 | ADV. ANALOG | | Y | ATO2815TF/CH | 594 |
| 5962-9095501M2A | A | 07/25/2001 | 1 | ANALOG (2) | | Y | AD640TE/883B | 800 |
| 5962-9095501MRA | A | 07/25/2001 | 1 | ANALOG (2) | | Y | AD640TD/883B | 800 |
| 5962-9095701MQA | A | 03/24/1994 | | (NONE) | | | 5412-T (GEN) | 592 |
| 5962-9095701MXA | A | 03/24/1994 | | (NONE) | | | 5412-T (GEN) | 592 |
| 5962-9095702MQA | A | 03/24/1994 | | (NONE) | | | 5412-S (GEN) | 592 |
| 5962-9095702MXA | A | 03/24/1994 | | (NONE) | | | 5412-S (GEN) | 592 |
| 5962-9095801Q2A | B | 02/21/2003 | 1 | TI | | Y | TLE2161MFKB | 703 |
| 5962-9095801QPA | B | 02/21/2003 | 1 | TI | | Y | TLE2161MJGB | 703 |
| 5962-9095802Q2A | B | 02/21/2003 | 1 | TI | | Y | TLE2161AMFKB | 703 |
| 5962-9095802QPA | B | 02/21/2003 | 1 | TI | | Y | TLE2161AMJGB | 703 |
| 5962-9095803Q2A | B | 02/21/2003 | 1 | TI | | Y | TLE2161BMFKB | 703 |
| 5962-9095803QPA | B | 02/21/2003 | 1 | TI | | Y | TLE2161BMJGB | 703 |
| 5962-9096201MQA | A | 11/15/2001 | 2 | ANALOG (4) | | Y | AD2S80ATD/883B | 594 |
| 5962-9096201MXA | A | 11/15/2001 | 2 | ANALOG (4) | | Y | AD2S80ATE/883B | 594 |
| 5962-9096301MXA | | 07/23/1992 | | (NONE) | | | TMC2310V (GEN) | 420 |
| 5962-9096301MYA | | 07/23/1992 | | (NONE) | | | TMC2310V (GEN) | 420 |
| 5962-9096302MXA | | 07/23/1992 | | (NONE) | | | TMC2310V1 (GEN) | 420 |
| 5962-9096302MYA | | 07/23/1992 | | (NONE) | | | TMC2310V1 (GEN) | 420 |
| 5962-9096401MXA | A | 06/30/1994 | | (NONE) | | | 1010A (GEN) | 431 |
| 5962-9096401MYA | A | 06/30/1994 | | (NONE) | | | 1010A (GEN) | 431 |
| 5962-9096401MZA | A | 06/30/1994 | | (NONE) | | | 1010A (GEN) | 431 |
| 5962-9096402MXA | A | 06/30/1994 | | (NONE) | | | 1010A-1 (GEN) | 431 |
| 5962-9096403MXA | A | 06/30/1994 | 1 | ACTEL | | Y | A1010B-PG84B | 431 |
| 5962-9096403MXC | A | 06/30/1994 | 1 | ACTEL | | Y | A1010B-PG84B | 431 |
| 5962-9096404MXA | A | 06/30/1994 | 1 | ACTEL | | Y | A1010B-1PG84B | 431 |
| 5962-9096404MXC | A | 06/30/1994 | 1 | ACTEL | | Y | A1010B-1PG84B | 431 |
| 5962-9096501MMC | F | 03/08/2004 | | (NONE) | | | 1020A (GEN) | 431 |
| 5962-9096501MTC | F | 03/08/2004 | | (NONE) | | | 1020 (GEN) | 431 |
| 5962-9096501MUC | F | 03/08/2004 | | (NONE) | | | 1020 (GEN) | 431 |
| 5962-9096501MXA | F | 03/08/2004 | | (NONE) | | | 1020 (GEN) | 431 |
| 5962-9096501MYA | F | 03/08/2004 | | (NONE) | | | 1020 (GEN) | 431 |
| 5962-9096501MZA | F | 03/08/2004 | | (NONE) | | | 1020 (GEN) | 431 |
| 5962-9096502MMC | F | 03/08/2004 | | (NONE) | | | 1020A-1 (GEN) | 431 |
| 5962-9096502MTC | F | 03/08/2004 | | (NONE) | | | 1020A-1 (GEN) | 431 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9096502MUC | F | 03/08/2004 | | (NONE) | | | 1020A-1 (GEN) | 431 |
| 5962-9096502MXA | F | 03/08/2004 | | (NONE) | | | 1020-1 (GEN) | 431 |
| 5962-9096502MYA | F | 03/08/2004 | | (NONE) | | | 1020A-1 (GEN) | 431 |
| 5962-9096502MZA | F | 03/08/2004 | | (NONE) | | | 1020A-1 (GEN) | 431 |
| 5962-9096503Q9A | F | 03/08/2004 | 1 | ACTEL | | Y | A1020B-DIE | 431 |
| 5962-9096503MMC | F | 03/08/2004 | | (NONE) | | | 1020B (GEN) | 431 |
| 5962-9096503MTC | F | 03/08/2004 | 1 | ACTEL | | Y | A1020B-CQ84B | 431 |
| 5962-9096503MUC | F | 03/08/2004 | 1 | ACTEL | | Y | A1020B-PG84B | 431 |
| 5962-9096504MMC | F | 03/08/2004 | | (NONE) | | | 1020-1 (GEN) | 431 |
| 5962-9096504MTC | F | 03/08/2004 | 1 | ACTEL | | Y | A1020B-1CQ84B | 431 |
| 5962-9096504MUC | F | 03/08/2004 | 1 | ACTEL | | Y | A1020B-1PG84B | 431 |
| 5962F9096505Q9B | F | 03/08/2004 | 1 | ACTEL | | Y | RH1020-DIE | 431 |
| 5962F9096505QTC | F | 03/08/2004 | 1 | ACTEL | | Y | RH1020-CQ84V | 431 |
| 5962-9096601MRA | A | 04/09/1992 | | (NONE) | 09/09/1998 | | ADC0802 (GEN) | 592 |
| 5962-9096701MCA | | 12/17/1991 | | (NONE) | | | LMF60-100 (GEN) | 805 |
| 5962-9096702MCA | | 12/17/1991 | | (NONE) | | | LMF60-50 (GEN) | 805 |
| 5962-9096801MCA | | 10/03/1991 | | (NONE) | 09/09/1998 | | LMF90 (GEN) | 805 |
| 5962-9096901M2A | A | 07/25/2001 | 1 | TI | | Y | TLC3704MFKB | 776 |
| 5962-9096901MCA | A | 07/25/2001 | 1 | TI | | Y | TLC3704MJB | 776 |
| 5962-9097001MCA | | 01/19/1993 | | (NONE) | 06/30/1996 | | SP8620 (GEN) | 319 |
| 5962-9097601MTA | | 11/04/1992 | | (NONE) | 04/15/1996 | | 80C51FB (GEN) | 420 |
| 5962-9097601MUA | | 11/04/1992 | | (NONE) | 12/24/1997 | | 80C51FB (GEN) | 420 |
| 5962-9097601MXA | | 11/04/1992 | | (NONE) | 12/24/1997 | | 80C51FB (GEN) | 420 |
| 5962-9097601MZA | | 11/04/1992 | | (NONE) | 04/15/1996 | | 80C51FB (GEN) | 420 |
| 5962-9097602MTA | | 11/04/1992 | | (NONE) | 04/15/1996 | | 80C51FB (GEN) | 420 |
| 5962-9097602MUA | | 11/04/1992 | | (NONE) | 12/24/1997 | | 80C51FB (GEN) | 420 |
| 5962-9097602MXA | | 11/04/1992 | | (NONE) | 12/24/1997 | | 80C51FB (GEN) | 420 |
| 5962-9097602MZA | | 11/04/1992 | | (NONE) | 04/15/1996 | | 80C51FB (GEN) | 420 |
| 5962-9097701HXA | B | 05/24/2000 | | (NONE) | 09/27/2002 | | CLC207A (GEN) | 755 |
| 5962-9097801HXC | | 06/24/1994 | | (NONE) | | | 1250A (GEN) | 591 |
| 5962-9097901M2A | A | 09/15/2000 | | (NONE) | 09/30/2000 | | AD9901T (GEN) | 899 |
| 5962-9097901MCA | A | 09/15/2000 | | (NONE) | 09/30/2000 | | AD9901T (GEN) | 899 |
| 5962-9098001M2A | C | 03/21/2003 | 1 | ANALOG (2) | | Y | AD843SE/883B | 702 |
| 5962-9098001MPA | C | 03/21/2003 | 1 | ANALOG (2) | | Y | AD843SQ/883B | 702 |
| 5962-9098001MXA | C | 03/21/2003 | 1 | ANALOG (2) | | Y | AD843SH/883B | 702 |
| 5962-9098301MCA | A | 01/30/2002 | 1 | SILICONIX | | Y | D469AAP/883 | 899 |
| 5962-9098401MEA | | 03/08/1993 | 1 | TI | | Y | CD54HCT390F3A | 300 |
| 5962-9098501B2A | A | 02/08/1993 | 3 | NATIONAL | | Y | JM54AC521B2A | 209 |
| 5962-9098501M2A | A | 02/08/1993 | 3 | NATIONAL | | Y | 54AC521LMQB | 209 |
| 5962-9098501S2A | A | 02/08/1993 | | (NONE) | | | 54AC521 (GEN) | 209 |
| 5962R9098501B2A | A | 02/08/1993 | 3 | NATIONAL | | Y | JM54AC521B2A-RH | 209 |
| 5962R9098501S2A | A | 02/08/1993 | 3 | NATIONAL | | Y | JM54AC521S2A-RH | 209 |
| 5962-9098501BRA | A | 02/08/1993 | | (NONE) | | | 54AC521 (GEN) | 209 |
| 5962-9098501MRA | A | 02/08/1993 | 3 | NATIONAL | | Y | 54AC521DMQB | 209 |
| 5962-9098501SRA | A | 02/08/1993 | | (NONE) | | | 54AC521 (GEN) | 209 |
| 5962R9098501BRA | A | 02/08/1993 | 3 | NATIONAL | | Y | JM54AC521BRA-RH | 209 |
| 5962R9098501SRA | A | 02/08/1993 | 3 | NATIONAL | | Y | JM54AC521SRA-RH | 209 |
| 5962-9098501BSA | A | 02/08/1993 | 3 | NATIONAL | | Y | JM54AC521BSA | 209 |
| 5962-9098501MSA | A | 02/08/1993 | 3 | NATIONAL | | Y | 54AC521FMQB | 209 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9098501SSA | A | 02/08/1993 | | (NONE) | | | 54AC521 (GEN) | 209 |
| 5962R9098501BSA | A | 02/08/1993 | 3 | NATIONAL | | Y | JM54AC521BSA-RH | 209 |
| 5962R9098501SSA | A | 02/08/1993 | 3 | NATIONAL | | Y | JM54AC521SSA-RH | 209 |
| 5962-9098502M2A | A | 02/08/1993 | | (NONE) | 09/15/1995 | | 54AC11521 (GEN) | 209 |
| 5962-9098502MRA | A | 02/08/1993 | | (NONE) | 09/15/1995 | | 54AC11521 (GEN) | 209 |
| 5962-9098601MXA | | 11/09/1992 | | (NONE) | | | | 625 |
| 5962-9098601MYA | | 11/09/1992 | | (NONE) | | | | 625 |
| 5962-9098601MZA | | 11/09/1992 | | (NONE) | | | | 625 |
| 5962-9098602MXA | | 11/09/1992 | | (NONE) | | | | 625 |
| 5962-9098602MYA | | 11/09/1992 | | (NONE) | | | | 625 |
| 5962-9098602MZA | | 11/09/1992 | | (NONE) | | | | 625 |
| 5962-9098701MEA | | 04/17/1992 | | (NONE) | | | UC1633 (GEN) | 899 |
| 5962-9098901MLA | | 03/01/1994 | | (NONE) | | | C20RA10-35 (GEN) | 431 |
| 5962-9098902M3A | | 03/01/1994 | | (NONE) | | | C20RA10-25 (GEN) | 431 |
| 5962-9098902MLA | | 03/01/1994 | | (NONE) | 11/05/2001 | | C20RA10-25 (GEN) | 431 |
| 5962-9098903M3A | | 03/01/1994 | | (NONE) | | | C20RA10-20 (GEN) | 431 |
| 5962-9098903MLA | | 03/01/1994 | | (NONE) | 08/05/2002 | | C20RA10-20 (GEN) | 431 |
| 5962-9099301MPA | F | 02/20/2003 | 1 | NATIONAL | | Y | CLC505AJ-QML | 702 |
| 5962-9099401MPA | E | 12/11/2003 | 1 | NATIONAL | | Y | CLC404AJ-QML | 755 |
| 5962-9099501HXC | B | 06/24/1994 | | (NONE) | | | CLC925B (GEN) | 592 |
| 5962-9099601MXA | B | 09/27/1996 | | (NONE) | | | TMC2009 (GEN) | 208 |
| 5962-9099601MYA | B | 09/27/1996 | | (NONE) | | | TMC2009 (GEN) | 208 |
| 5962-9099601MZA | B | 09/27/1996 | | (NONE) | | | TMC2009 (GEN) | 208 |
| 5962-9099602MUA | B | 09/27/1996 | | (NONE) | 04/01/2000 | | LMA1009-95 (GEN) | 208 |
| 5962-9099602MXA | B | 09/27/1996 | | (NONE) | 04/01/2000 | | LMA1009-95 (GEN) | 208 |
| 5962-9099602MYA | B | 09/27/1996 | | (NONE) | 04/01/2000 | | LMA2009-95 (GEN) | 208 |
| 5962-9099603MUA | B | 09/27/1996 | | (NONE) | 04/01/2000 | | LMA1009-65 (GEN) | 208 |
| 5962-9099603MXA | B | 09/27/1996 | | (NONE) | 04/01/2000 | | LMA1009-65 (GEN) | 208 |
| 5962-9099603MYA | B | 09/27/1996 | | (NONE) | 04/01/2000 | | LMA2009-65 (GEN) | 208 |
| 5962-9099604MUA | B | 09/27/1996 | | (NONE) | 04/01/2000 | | LMA1009-55 (GEN) | 208 |
| 5962-9099604MXA | B | 09/27/1996 | | (NONE) | 04/01/2000 | | LMA1009-55 (GEN) | 208 |
| 5962-9099604MYA | B | 09/27/1996 | | (NONE) | 04/01/2000 | | LMA2009-55 (GEN) | 208 |
| 5962-9099701MRA | | 10/22/1991 | | (NONE) | 12/24/1997 | | 82C2886 (GEN) | 420 |
| 5962-9099702MRA | | 10/22/1991 | | (NONE) | 12/24/1997 | | 82C2888 (GEN) | 420 |
| 5962-9099703MRA | | 10/22/1991 | | (NONE) | 12/24/1997 | | 82C28810 (GEN) | 420 |
| 5962-9150101MXA | C | 07/01/1998 | 1 | ATMEL GREN. | | Y | TS68332MAB/C16 | 420 |
| 5962-9150101MYA | C | 07/01/1998 | | (NONE) | | | 68332-16 (GEN) | 420 |
| 5962-9150101QYC | C | 07/01/1998 | | (NONE) | 09/30/1995 | | 68332-16 (GEN) | 420 |
| 5962-9150101MZA | C | 07/01/1998 | 1 | ATMEL GREN. | | Y | TS68332MR1B/C16 | 420 |
| 5962-9150101MZC | C | 07/01/1998 | 1 | ATMEL GREN. | | Y | TS68332MRB/C16 | 420 |
| 5962-9150101QZA | C | 07/01/1998 | | (NONE) | 09/30/1995 | | 68332-16 (GEN) | 420 |
| 5962-9150102MXA | C | 07/01/1998 | 1 | ATMEL GREN. | | Y | TS68332MAB/C20 | 420 |
| 5962-9150102MZA | C | 07/01/1998 | 1 | ATMEL GREN. | | Y | TS68332MR1B/C20 | 420 |
| 5962-9150102MZC | C | 07/01/1998 | 1 | ATMEL GREN. | | Y | TS68332MRB/C20 | 420 |
| 5962-9150501MPA | B | 09/15/2000 | | (NONE) | 04/16/2002 | | AD790S (GEN) | 770 |
| 5962-9150801MXA | B | 01/17/1997 | 0 | IDT | | Y | IDT7006S70GB | 622 |
| 5962-9150801MYA | B | 01/17/1997 | 0 | IDT | | Y | IDT7006S70FB | 622 |
| 5962-9150802MXA | B | 01/17/1997 | 0 | IDT | | Y | IDT7006L70GB | 622 |
| 5962-9150802MYA | B | 01/17/1997 | 0 | IDT | | Y | IDT7006L70FB | 622 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9150803MXA | B | 01/17/1997 | 0 | IDT | | Y | IDT7006S55GB | 622 |
| 5962-9150803MYA | B | 01/17/1997 | 0 | IDT | | Y | IDT7006S55FB | 622 |
| 5962-9150804MXA | B | 01/17/1997 | 0 | IDT | | Y | IDT7006L55GB | 622 |
| 5962-9150804MYA | B | 01/17/1997 | 0 | IDT | | Y | IDT7006L55FB | 622 |
| 5962-9150805MXA | B | 01/17/1997 | 0 | IDT | | Y | IDT7006S45GB | 622 |
| 5962-9150805MYA | B | 01/17/1997 | 0 | IDT | | Y | IDT7006S45FB | 622 |
| 5962-9150806MXA | B | 01/17/1997 | 0 | IDT | | Y | IDT7006L45GB | 622 |
| 5962-9150806MYA | B | 01/17/1997 | 0 | IDT | | Y | IDT7006L45FB | 622 |
| 5962-9150807MXA | B | 01/17/1997 | 2 | IDT | | Y | IDT7006S35GB | 622 |
| 5962-9150807MYA | B | 01/17/1997 | 2 | IDT | | Y | IDT7006S35FB | 622 |
| 5962-9150808MXA | B | 01/17/1997 | 2 | IDT | | Y | IDT7006L35GB | 622 |
| 5962-9150808MYA | B | 01/17/1997 | 2 | IDT | | Y | IDT7006L35FB | 622 |
| 5962-9150809MXA | B | 01/17/1997 | 2 | IDT | | Y | IDT7006S25GB | 616 |
| 5962-9150809MYA | B | 01/17/1997 | 2 | IDT | | Y | IDT7006S25FB | 616 |
| 5962-9150810MXA | B | 01/17/1997 | 2 | IDT | | Y | IDT7006L25GB | 616 |
| 5962-9150810MYA | B | 01/17/1997 | 2 | IDT | | Y | IDT7006L25FB | 616 |
| 5962-9150811MXA | B | 01/17/1997 | 2 | IDT | | Y | IDT7006S20GB | 616 |
| 5962-9150811MYA | B | 01/17/1997 | 2 | IDT | | Y | IDT7006S20FB | 616 |
| 5962-9150812MXA | B | 01/17/1997 | 2 | IDT | | Y | IDT7006L20GB | 616 |
| 5962-9150812MYA | B | 01/17/1997 | 2 | IDT | | Y | IDT7006L20FB | 616 |
| 5962-9151301M2A | | 03/05/1993 | 1 | ROCHESTER | | Y | 54HC51/B2A | 130 |
| 5962-9151301MCA | | 03/05/1993 | 1 | ROCHESTER | | Y | 54HC51/BCA | 130 |
| 5962-9151601QEA | A | 10/03/1997 | 1 | SARNOFF | | Y | GEM11101QEA | 282 |
| 5962-9151601QEC | A | 10/03/1997 | 1 | SARNOFF | | Y | GEM11101QEC | 282 |
| 5962-9151801MXA | | 03/19/1993 | | (NONE) | 05/10/1995 | | 10E474L-7 (GEN) | 612 |
| 5962-9151801MYA | | 03/19/1993 | | (NONE) | | | 10E474L-7 (GEN) | 612 |
| 5962-9151801MZA | | 03/19/1993 | | (NONE) | | | 10E474L-7 (GEN) | 612 |
| 5962-9151802MXA | | 03/19/1993 | | (NONE) | 05/10/1995 | | 10E474L-5 (GEN) | 612 |
| 5962-9151802MYA | | 03/19/1993 | | (NONE) | | | 10E474L-5 (GEN) | 612 |
| 5962-9151802MZA | | 03/19/1993 | | (NONE) | | | 10E474L-5 (GEN) | 612 |
| 5962-9151901M2A | B | 02/24/2004 | 3 | ANALOG (5) | | Y | OP249ARC/883 | 710 |
| 5962-9151901MGA | B | 02/24/2004 | 3 | ANALOG (5) | 05/28/2005 | Y | OP249AJ/883 | 710 |
| 5962-9151901MPA | B | 02/24/2004 | 3 | ANALOG (5) | | Y | OP249AZ/883 | 710 |
| 5962-9152101M3A | B | 12/20/1996 | 1 | ANALOG (3) | | Y | AD7874SE/883B | 433 |
| 5962-9152101MXA | B | 12/20/1996 | 1 | ANALOG (3) | | Y | AD7874SQ/883B | 433 |
| 5962-9152301MUA | B | 05/03/2004 | 1 | MICROSEMI | | Y | SG7820AIG/883B | 782 |
| 5962-9152301MXA | B | 05/03/2004 | 1 | MICROSEMI | | Y | SG7820AT/883B | 782 |
| 5962-9152301MYA | B | 05/03/2004 | 1 | MICROSEMI | | Y | SG7820AK/883B | 782 |
| 5962-9152301MZA | B | 05/03/2004 | 1 | MICROSEMI | | Y | SG7820AR/883B | 782 |
| 5962-9152801MXA | A | 04/26/1996 | | (NONE) | 12/02/2003 | | 100301 (GEN) | 149 |
| 5962-9152801VXA | A | 04/26/1996 | | (NONE) | 12/02/2003 | | 100301 (GEN) | 149 |
| 5962-9152801MYA | A | 04/26/1996 | 2 | NATIONAL | | Y | 100301FMQB | 149 |
| 5962-9152801VYA | A | 04/26/1996 | 2 | NATIONAL | | Y | 100301W-QMLV | 149 |
| 5962-9152802MXA | A | 04/26/1996 | | NATIONAL | | Y | 100302DMQB | 149 |
| 5962-9152802VXA | A | 04/26/1996 | 2 | NATIONAL | | Y | 100302J-QMLV | 149 |
| 5962-9152802MYA | A | 04/26/1996 | | NATIONAL | | Y | 100302FMQB | 149 |
| 5962-9152802VYA | A | 04/26/1996 | 2 | NATIONAL | | Y | 100302W-QMLV | 149 |
| 5962-9152901M3A | | 01/16/1992 | | (NONE) | | | 54AS874 (GEN) | 158 |
| 5962-9152901MJA | | 01/16/1992 | | (NONE) | | | 54AS874 (GEN) | 158 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9152901MKA | | 01/16/1992 | | (NONE) | | | 54AS874 (GEN) | 158 |
| 5962-9152901MLA | | 01/16/1992 | | (NONE) | | | 54AS874 (GEN) | 158 |
| 5962-9153001MXA | | 05/21/1992 | 2 | NATIONAL | | Y | 100324DMQB | 547 |
| 5962-9153001VXA | | 05/21/1992 | 2 | NATIONAL | | Y | 100324J-QMLV | 547 |
| 5962-9153001MYA | | 05/21/1992 | 2 | NATIONAL | | Y | 100324FMQB | 547 |
| 5962-9153001VYA | | 05/21/1992 | 2 | NATIONAL | | Y | 100324W-QMLV | 547 |
| 5962-9153101MXA | A | 01/29/2004 | 3 | NATIONAL | | Y | 100325DMQB | 549 |
| 5962-9153101VXA | A | 01/29/2004 | 3 | NATIONAL | | Y | 100325J-QMLV | 549 |
| 5962-9153101MYA | A | 01/29/2004 | 3 | NATIONAL | | Y | 100325FMQB | 549 |
| 5962-9153101VYA | A | 01/29/2004 | 3 | NATIONAL | | Y | 100325W-QMLV | 549 |
| 5962F9153101VYA | A | 01/29/2004 | 3 | NATIONAL | | Y | 100325WFQMLV | 549 |
| 5962-9153201Q2A | B | 08/01/1997 | 2 | TI | | Y | TLC3702MFKB | 773 |
| 5962-9153201QHA | B | 08/01/1997 | | (NONE) | | | TLC3702 (GEN) | 773 |
| 5962-9153201QPA | B | 08/01/1997 | 2 | TI | | Y | TLC3702MJGB | 773 |
| 5962-9153202Q2A | B | 08/01/1997 | 2 | TI | | Y | TLC3702MFKB | 773 |
| 5962-9153202QHA | B | 08/01/1997 | 2 | TI | | Y | TLC3702MUB | 773 |
| 5962-9153202QPA | B | 08/01/1997 | 2 | TI | | Y | TLC3702MJGB | 773 |
| 5962-9153301M2A | A | 08/10/1994 | | (NONE) | 09/09/1998 | | LMF100A (GEN) | 805 |
| 5962-9153301MRA | A | 08/10/1994 | | (NONE) | 09/09/1998 | | LMF100A (GEN) | 805 |
| 5962-9153401M2A | A | 12/02/1994 | | (NONE) | | | EL2001A (GEN) | 750 |
| 5962-9153401MPA | A | 12/02/1994 | | (NONE) | | | EL2001A (GEN) | 750 |
| 5962-9153402M2A | A | 12/02/1994 | | (NONE) | | | EL2001 (GEN) | 750 |
| 5962-9153402MPA | A | 12/02/1994 | | (NONE) | | | EL2001 (GEN) | 750 |
| 5962-9153501M2A | A | 02/02/1993 | | (NONE) | | | EL2038 (GEN) | 755 |
| 5962-9153501MCA | A | 02/02/1993 | | (NONE) | | | EL2038 (GEN) | 755 |
| 5962-9153601MXA | A | 01/29/2004 | 2 | NATIONAL | | Y | 100331DMQB | 158 |
| 5962-9153601VXA | A | 01/29/2004 | 2 | NATIONAL | | Y | 100331J-QMLV | 158 |
| 5962-9153601MYA | A | 01/29/2004 | 2 | NATIONAL | | Y | 100331FMQB | 158 |
| 5962-9153601VYA | A | 01/29/2004 | 2 | NATIONAL | | Y | 100331W-QMLV | 158 |
| 5962F9153601VYA | A | 01/29/2004 | 2 | NATIONAL | | Y | 100331WFQMLV | 158 |
| 5962-9153701MXA | | 01/22/1993 | | NATIONAL | | Y | 100304DMQB | 149 |
| 5962-9153701VXA | | 01/22/1993 | 3 | NATIONAL | | Y | 100304J-QMLV | 149 |
| 5962-9153701MYA | | 01/22/1993 | | NATIONAL | | Y | 100304FMQB | 149 |
| 5962-9153701VYA | | 01/22/1993 | 3 | NATIONAL | | Y | 100304W-QMLV | 149 |
| 5962-9154201MMA | D | 04/24/1996 | 3 | QP SEMI | | Y | 87C451/BMA | 420 |
| 5962-9154201MXA | D | 04/24/1996 | | (NONE) | | | 87C451 (GEN) | 420 |
| 5962-9154501MQA | E | 04/02/2002 | | (NONE) | | | V2500-35 (GEN) | 431 |
| 5962-9154501MXA | E | 04/02/2002 | | (NONE) | | | V2500-35 (GEN) | 431 |
| 5962-9154501MYA | E | 04/02/2002 | | (NONE) | | | V2500-35 (GEN) | 431 |
| 5962-9154502MQA | E | 04/02/2002 | | (NONE) | 09/30/1999 | | V2500-25 (GEN) | 431 |
| 5962-9154502MXA | E | 04/02/2002 | | (NONE) | 09/30/1999 | | V2500-25 (GEN) | 431 |
| 5962-9154502MYA | E | 04/02/2002 | | (NONE) | 09/30/1999 | | V2500-25 (GEN) | 431 |
| 5962-9154503MQA | E | 04/02/2002 | | (NONE) | 09/30/1999 | | V2500-30 (GEN) | 431 |
| 5962-9154503MXA | E | 04/02/2002 | | (NONE) | 09/30/1999 | | V2500-30 (GEN) | 431 |
| 5962-9154503MYA | E | 04/02/2002 | | (NONE) | 09/30/1999 | | V2500-30 (GEN) | 431 |
| 5962-9154504MXA | E | 04/02/2002 | 1 | ATMEL | 03/31/2005 | | ATV2500B-15LM/883 | 431 |
| 5962-9154504MYA | E | 04/02/2002 | 1 | ATMEL | 03/31/2005 | | ATV2500B-15KM/883 | 431 |
| 5962-9154505MXA | E | 04/02/2002 | 1 | ATMEL | 03/31/2005 | | ATV2500BL-20LM/883 | 431 |
| 5962-9154505MYA | E | 04/02/2002 | 1 | ATMEL | 03/31/2005 | | ATV2500BL-20KM/883 | 431 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9154506MQA | E | 04/02/2002 | 1 | ATMEL | 03/31/2005 | | ATV2500BQ-25DM/883 | 431 |
| 5962-9154506MXA | E | 04/02/2002 | 1 | ATMEL | 03/31/2005 | | ATV2500BQ-25LM/883 | 431 |
| 5962-9154506MYA | E | 04/02/2002 | 1 | ATMEL | 03/31/2005 | | ATV2500BQ-25KM/883 | 431 |
| 5962-9154507MQA | E | 04/02/2002 | 1 | ATMEL | 03/31/2005 | | ATV2500BQL-30DM/88 | 431 |
| 5962-9154507MXA | E | 04/02/2002 | 1 | ATMEL | 03/31/2005 | | ATV2500BQL-30LM/88 | 431 |
| 5962-9154507MYA | E | 04/02/2002 | 1 | ATMEL | 03/31/2005 | | ATV2500BQL-30KM/88 | 431 |
| 5962-9154601MQA | A | 01/11/1993 | 2 | ATMEL | | | ATV2500H-35GM/883 | 431 |
| 5962-9154601MXA | A | 01/11/1993 | | (NONE) | | | V2500H (GEN) | 431 |
| 5962-9154601MYA | A | 01/11/1993 | | (NONE) | | | V2500H (GEN) | 431 |
| 5962-9154602MQA | A | 01/11/1993 | 2 | ATMEL | | | ATV2500H-25GM/883 | 431 |
| 5962-9154602MXA | A | 01/11/1993 | | (NONE) | | | V2500H (GEN) | 431 |
| 5962-9154602MYA | A | 01/11/1993 | | (NONE) | | | V2500H (GEN) | 431 |
| 5962-9154603MQA | A | 01/11/1993 | 2 | ATMEL | | | ATV2500L-35GM/883 | 431 |
| 5962-9154603MXA | A | 01/11/1993 | | (NONE) | | | V2500L (GEN) | 431 |
| 5962-9154603MYA | A | 01/11/1993 | | (NONE) | | | V2500L (GEN) | 431 |
| 5962-9154901MPA | | 08/16/1991 | | (NONE) | | | 93CS66 (GEN) | 656 |
| 5962-9155201MEA | A | 11/29/1993 | 1 | SILICONIX | | Y | DG542AP/883 | 899 |
| 5962-9155301M3A | | 01/30/1991 | 3 | TI | | Y | SNJ54BCT652FK | 590 |
| 5962-9155301MKA | | 01/30/1991 | 3 | TI | | Y | SNJ54BCT652W | 590 |
| 5962-9155301MLA | | 01/30/1991 | 3 | TI | | Y | SNJ54BCT652JT | 590 |
| 5962-9155401M3A | A | 08/28/1992 | | (NONE) | | | 54BCT544 (GEN) | 590 |
| 5962-9155401MKA | A | 08/28/1992 | | (NONE) | | | 54BCT544 (GEN) | 590 |
| 5962-9155401MLA | A | 08/28/1992 | | (NONE) | | | 54BCT544 (GEN) | 590 |
| 5962-9155501M3A | A | 03/13/1992 | 3 | TI | | Y | SNJ54BCT646FK | 590 |
| 5962-9155501MKA | A | 03/13/1992 | 3 | TI | | Y | SNJ54BCT646W | 590 |
| 5962-9155501MLA | A | 03/13/1992 | 3 | TI | | Y | SNJ54BCT646JT | 590 |
| 5962-9155901HXC | | 01/21/1993 | | (NONE) | | | 2056P-34VR/2 (GEN) | 594 |
| 5962-9155902HXC | | 01/21/1993 | | (NONE) | | | 2056P-34VS/2 (GEN) | 594 |
| 5962-9155903HXC | | 01/21/1993 | | (NONE) | | | 2056P-34H/2 (GEN) | 594 |
| 5962-9155904HXC | | 01/21/1993 | | (NONE) | | | 2056P-34S/2 (GEN) | 594 |
| 5962-9156001HXC | | 01/19/1993 | | (NONE) | | | 1046-341V/2 (GEN) | 594 |
| 5962-9156002HXC | | 01/19/1993 | | (NONE) | | | 1046-341H/2 (GEN) | 594 |
| 5962-9156003HXC | | 01/19/1993 | | (NONE) | | | 1046-341S/2 (GEN) | 594 |
| 5962-9156501M2A | A | 04/19/1994 | | (NONE) | 03/08/2000 | | LM6118 (GEN) | 710 |
| 5962-9156501MPA | A | 04/19/1994 | | (NONE) | 03/08/2000 | | LM6118 (GEN) | 710 |
| 5962-9156601M3A | C | 06/28/1996 | | (NONE) | | | 87C751 (GEN) | 420 |
| 5962-9156601MLA | C | 06/28/1996 | 3 | QP SEMI | | Y | 87C751/BLA | 420 |
| 5962-9156602M3A | C | 06/28/1996 | | (NONE) | | | 87C751 (GEN) | 420 |
| 5962-9156602MLA | C | 06/28/1996 | 3 | QP SEMI | | Y | 87C751/BLA OT | 420 |
| 5962-9156603M3A | C | 06/28/1996 | | (NONE) | | | 87C751-16 (GEN) | 420 |
| 5962-9156603MLA | C | 06/28/1996 | 3 | QP SEMI | | Y | 87C751-16/BLA | 420 |
| 5962-9156604MLA | C | 06/28/1996 | 3 | QP SEMI | | Y | 87C751-16?BLA OT | 420 |
| 5962-9156605NXA | C | 06/28/1996 | | (NONE) | | | 87C571 (GEN) | 420 |
| 5962-9156606NXA | C | 06/28/1996 | | (NONE) | | | 87C571-16 (GEN) | 420 |
| 5962-9156607NXA | C | 06/28/1996 | | (NONE) | | | 87C571 (GEN) | 420 |
| 5962-9156608NXA | C | 06/28/1996 | | (NONE) | | | 87C571-16 (GEN) | 420 |
| 5962-9156801MRA | A | 09/20/1993 | | (NONE) | | | | 431 |
| 5962-9156801MSA | A | 09/20/1993 | | (NONE) | | | | 431 |
| 5962-9156801MXA | A | 09/20/1993 | | (NONE) | | | | 431 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9156802MRA | A | 09/20/1993 | | (NONE) | | | | 431 |
| 5962-9156802MSA | A | 09/20/1993 | | (NONE) | | | | 431 |
| 5962-9156802MXA | A | 09/20/1993 | | (NONE) | | | | 431 |
| 5962-9156901M2A | A | 02/10/1994 | | (NONE) | 09/30/1995 | | 10H751 (GEN) | 594 |
| 5962-9156901MRA | A | 02/10/1994 | | (NONE) | 09/30/1995 | | 10H751 (GEN) | 594 |
| 5962-9156901MSA | A | 02/10/1994 | | (NONE) | 09/30/1995 | | 10H751 (GEN) | 594 |
| 5962-9157001MPA | | 12/16/1994 | | (NONE) | 12/31/2000 | | SP8808 (GEN) | 219 |
| 5962-9157201MPA | | 03/30/1994 | | (NONE) | 09/30/2000 | | SP8830AC (GEN) | 319 |
| 5962-9157401HXA | B | 08/23/2004 | 1 | MS KENNEDY | | Y | MSK801B | 712 |
| 5962-9157401HXC | B | 08/23/2004 | 1 | MS KENNEDY | | Y | MSK801B | 712 |
| 5962-9157501HXA | B | 04/22/2002 | 1 | ADV. ANALOG | | Y | AHE2815D/CH | 594 |
| 5962-9157501HZA | B | 04/22/2002 | 1 | ADV. ANALOG | | Y | AHE2815DF/CH | 594 |
| 5962-9157502HXA | B | 04/22/2002 | 1 | ADV. ANALOG | | Y | AHE2815D/CH-SLV | 594 |
| 5962-9157502HZA | B | 04/22/2002 | 1 | ADV. ANALOG | | Y | AHE2815DF/CH-SLV | 594 |
| 5962-9157503HXA | B | 04/22/2002 | 1 | ADV. ANALOG | | Y | AHE2815D/CH-MSTR | 594 |
| 5962-9157503HZA | B | 04/22/2002 | 1 | ADV. ANALOG | | Y | AHE2815DF/CH-MSTR | 594 |
| 5962-9157601MMA | A | 03/09/1992 | 1 | QP SEMI | | Y | 87C52/BMA | 420 |
| 5962-9157601MQA | A | 03/09/1992 | 1 | QP SEMI | | Y | 87C52/BQA | 420 |
| 5962-9157601MUA | A | 03/09/1992 | | (NONE) | | | 87C52 (GEN) | 420 |
| 5962-9157602MMA | A | 03/09/1992 | 1 | QP SEMI | | Y | 87C52-16/BMA | 420 |
| 5962-9157602MQA | A | 03/09/1992 | 1 | QP SEMI | | Y | 87C52-16/BQA | 420 |
| 5962-9157602MUA | A | 03/09/1992 | | (NONE) | | | 87C52-16 (GEN) | 420 |
| 5962-9157603MMA | A | 03/09/1992 | 1 | QP SEMI | | Y | 87C52/BMA OT | 420 |
| 5962-9157603MQA | A | 03/09/1992 | 1 | QP SEMI | | Y | 87C52/BQA OT | 420 |
| 5962-9157603MUA | A | 03/09/1992 | | (NONE) | | | 87C52 (GEN) | 420 |
| 5962-9157603NXA | A | 03/09/1992 | | (NONE) | | | 87C52 (GEN) | 420 |
| 5962-9157603NYA | A | 03/09/1992 | | (NONE) | | | 87C52 (GEN) | 420 |
| 5962-9157604MMA | A | 03/09/1992 | 1 | QP SEMI | | Y | 87C52-16/BMA OT | 420 |
| 5962-9157604MQA | A | 03/09/1992 | 1 | QP SEMI | | Y | 87C52-16/BQA OT | 420 |
| 5962-9157604MUA | A | 03/09/1992 | | (NONE) | | | 87C52-16 (GEN) | 420 |
| 5962-9157604NXA | A | 03/09/1992 | | (NONE) | | | 87C52-16 (GEN) | 420 |
| 5962-9157604NYA | A | 03/09/1992 | | (NONE) | | | 87C52-16 (GEN) | 420 |
| 5962-9157605NXA | A | 03/09/1992 | | (NONE) | | | 87C52 (GEN) | 420 |
| 5962-9157605NYA | A | 03/09/1992 | | (NONE) | | | 87C52 (GEN) | 420 |
| 5962-9157606NXA | A | 03/09/1992 | | (NONE) | | | 87C52-16 (GEN) | 420 |
| 5962-9157606NYA | A | 03/09/1992 | | (NONE) | | | 87C52-16 (GEN) | 420 |
| 5962-9157701MXA | B | 12/07/1993 | 3 | QP SEMI | | Y | 87C752/BXA | 420 |
| 5962-9157702MXA | B | 12/07/1993 | 3 | QP SEMI | | Y | 87C752-16/BXA | 420 |
| 5962-9157703MXA | B | 12/07/1993 | 3 | QP SEMI | | Y | 87C752/BXA OT | 420 |
| 5962-9157704MXA | B | 12/07/1993 | 3 | QP SEMI | | Y | 87C752-16/BXA OT | 420 |
| 5962-9157801MXA | B | 12/11/1996 | | (NONE) | 09/09/1998 | | ADC1241 (GEN) | 592 |
| 5962-9157802MXA | B | 12/11/1996 | | (NONE) | | | ADC12441 (GEN) | 592 |
| 5962-9157803QJA | B | 12/11/1996 | | (NONE) | 03/08/2000 | | ADC1251 (GEN) | 592 |
| 5962-9157804QJA | B | 12/11/1996 | | (NONE) | | | ADC12451 (GEN) | 592 |
| 5962-9157901HZA | B | 06/12/2003 | 1 | ADV. ANALOG | | Y | 7870-01 | 594 |
| 5962-9157902HZA | B | 06/12/2003 | 1 | ADV. ANALOG | | Y | 7870-02 | 594 |
| 5962-9157903HZA | B | 06/12/2003 | 1 | ADV. ANALOG | | Y | 7870-03 | 594 |
| 5962-9157904HZA | B | 06/12/2003 | 1 | ADV. ANALOG | | Y | ATW2805S/CH | 594 |
| 5962-9157905HZA | B | 06/12/2003 | 1 | ADV. ANALOG | | Y | ATW2805S/CH-SLV | 594 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9157906HZA | B | 06/12/2003 | 1 | ADV. ANALOG | | Y | ATW2805S/CH-MSTR | 594 |
| 5962-9158001HXA | B | 04/05/2001 | 1 | ADV. ANALOG | | Y | AHE2812S/CH | 594 |
| 5962-9158001HXC | B | 04/05/2001 | 1 | ADV. ANALOG | | Y | AHE2812S/CH | 594 |
| 5962-9158001HZA | B | 04/05/2001 | 1 | ADV. ANALOG | | Y | AHE2812SF/CH | 594 |
| 5962-9158001HZC | B | 04/05/2001 | 1 | ADV. ANALOG | | Y | AHE2812SF/CH | 594 |
| 5962-9158002HXA | B | 04/05/2001 | 1 | ADV. ANALOG | | Y | AHE2812S/CH-SLV | 594 |
| 5962-9158002HXC | B | 04/05/2001 | 1 | ADV. ANALOG | | Y | AHE2812S/CH-SLV | 594 |
| 5962-9158002HZA | B | 04/05/2001 | 1 | ADV. ANALOG | | Y | AHE2812SF/CH-SLV | 594 |
| 5962-9158002HZC | B | 04/05/2001 | 1 | ADV. ANALOG | | Y | AHE2812SF/CH-SLV | 594 |
| 5962-9158003HXA | B | 04/05/2001 | 1 | ADV. ANALOG | | Y | AHE2812S/CH-MSTR | 594 |
| 5962-9158003HXC | B | 04/05/2001 | 1 | ADV. ANALOG | | Y | AHE2812S/CH-MSTR | 594 |
| 5962-9158003HZA | B | 04/05/2001 | 1 | ADV. ANALOG | | Y | AHE2812SF/CH-MSTR | 594 |
| 5962-9158003HZC | B | 04/05/2001 | 1 | ADV. ANALOG | | Y | AHE2812SF/CH-MSTR | 594 |
| 5962-9158101MXC | A | 11/07/2002 | | (NONE) | | | AD9060S (GEN) | 592 |
| 5962-9158101MYA | A | 11/07/2002 | | (NONE) | | | AD9060S (GEN) | 592 |
| 5962-9158102MXC | A | 11/07/2002 | | (NONE) | | | AD9060T (GEN) | 592 |
| 5962-9158102MYA | A | 11/07/2002 | | (NONE) | | | AD9060T (GEN) | 592 |
| 5962-9158401M3A | | 10/20/1992 | | (NONE) | | | 7C332-25 (GEN) | 431 |
| 5962-9158401MXA | | 10/20/1992 | | (NONE) | | | | 431 |
| 5962-9158401MYA | | 10/20/1992 | | (NONE) | | | 7C332-25 (GEN) | 431 |
| 5962-9158401MZA | | 10/20/1992 | | (NONE) | | | 7C332-25 (GEN) | 431 |
| 5962-9158402M3A | | 10/20/1992 | | (NONE) | | | | 431 |
| 5962-9158402MXA | | 10/20/1992 | | (NONE) | | | | 431 |
| 5962-9158402MYA | | 10/20/1992 | | (NONE) | | | 7C332-20 (GEN) | 431 |
| 5962-9158402MZA | | 10/20/1992 | | (NONE) | | | 7C332-20 (GEN) | 431 |
| 5962-9158501MUA | B | 02/26/2001 | 3 | QP SEMI | | Y | CY7C425-120LMB | 670 |
| 5962-9158501MXA | B | 02/26/2001 | 3 | QP SEMI | | Y | CY7C425-120DMB | 670 |
| 5962-9158501MYA | B | 02/26/2001 | 3 | QP SEMI | | Y | CY7C424-120DMB | 670 |
| 5962-9158501MZA | B | 02/26/2001 | 3 | QP SEMI | | Y | CY7C425-120KMB | 670 |
| 5962-9158502MUA | B | 02/26/2001 | 3 | QP SEMI | | Y | CY7C425-80LMB | 670 |
| 5962-9158502MXA | B | 02/26/2001 | 3 | QP SEMI | | Y | CY7C425-80DMB | 670 |
| 5962-9158502MYA | B | 02/26/2001 | 3 | QP SEMI | | Y | CY7C424-80DMB | 670 |
| 5962-9158502MZA | B | 02/26/2001 | 3 | QP SEMI | | Y | CY7C425-80KMB | 670 |
| 5962-9158503MUA | B | 02/26/2001 | 3 | QP SEMI | | Y | CY7C425-65LMB | 670 |
| 5962-9158503MXA | B | 02/26/2001 | 3 | QP SEMI | | Y | CY7C425-65DMB | 670 |
| 5962-9158503MYA | B | 02/26/2001 | 3 | QP SEMI | | Y | CY7C424-65DMB | 670 |
| 5962-9158503MZA | B | 02/26/2001 | 3 | QP SEMI | | Y | CY7C425-65KMB | 670 |
| 5962-9158504MUA | B | 02/26/2001 | 3 | QP SEMI | | Y | CY7C425-50LMB | 670 |
| 5962-9158504MXA | B | 02/26/2001 | 3 | QP SEMI | | Y | CY7C425-50DMB | 670 |
| 5962-9158504MYA | B | 02/26/2001 | 3 | QP SEMI | | Y | CY7C424-50DMB | 670 |
| 5962-9158504MZA | B | 02/26/2001 | 3 | QP SEMI | | Y | CY7C425-50KMB | 670 |
| 5962-9158505MUA | B | 02/26/2001 | 3 | QP SEMI | | Y | CY7C425-40LMB | 670 |
| 5962-9158505MXA | B | 02/26/2001 | 3 | QP SEMI | | Y | CY7C425-40DMB | 670 |
| 5962-9158505MYA | B | 02/26/2001 | 3 | QP SEMI | | Y | CY7C424-40DMB | 670 |
| 5962-9158505MZA | B | 02/26/2001 | 3 | QP SEMI | | Y | CY7C425-40KMB | 670 |
| 5962-9158506MUA | B | 02/26/2001 | 3 | QP SEMI | | Y | CY7C425-30LMB | 670 |
| 5962-9158506MXA | B | 02/26/2001 | 3 | QP SEMI | | Y | CY7C425-30DMB | 670 |
| 5962-9158506MYA | B | 02/26/2001 | 3 | QP SEMI | | Y | CY7C424-30DMB | 670 |
| 5962-9158506MZA | B | 02/26/2001 | 3 | QP SEMI | | Y | CY7C425-30KMB | 670 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9158601Q2A | A | 07/15/1999 | 1 | ROCHESTER | | Y | 54LS147/B2A | 345 |
| 5962-9158601Q2A | A | 07/15/1999 | 2 | SARNOFF | | Y | GEM31201Q2A | 345 |
| 5962-9158601Q2C | A | 07/15/1999 | 2 | SARNOFF | | Y | GEM31201Q2C | 345 |
| 5962-9158601QEA | A | 07/15/1999 | 1 | ROCHESTER | | Y | 54LS147/BEA | 345 |
| 5962-9158601QEA | A | 07/15/1999 | 2 | SARNOFF | | Y | GEM31201QEA | 345 |
| 5962-9158601QEC | A | 07/15/1999 | 2 | SARNOFF | | Y | GEM31201QEC | 345 |
| 5962-9158601QFA | A | 07/15/1999 | 1 | ROCHESTER | | Y | 54LS147/BFA | 345 |
| 5962-9158601QFA | A | 07/15/1999 | 2 | SARNOFF | | Y | GEM31201QFA | 345 |
| 5962-9158601QFC | A | 07/15/1999 | 2 | SARNOFF | | Y | GEM31201QFC | 345 |
| 5962-9159001MEA | | 10/27/1992 | | (NONE) | 06/30/1996 | | SP8741 (GEN) | 319 |
| 5962-9159301MKA | | 05/13/1993 | | (NONE) | 05/10/1995 | | 7B164 (GEN) | 620 |
| 5962-9159301MYA | | 05/13/1993 | | (NONE) | 05/10/1995 | | 7B164 (GEN) | 620 |
| 5962-9159301MZA | | 05/13/1993 | | (NONE) | 05/10/1995 | | 7B164 (GEN) | 620 |
| 5962-9159302MKA | | 05/13/1993 | | (NONE) | 05/10/1995 | | 7B164 (GEN) | 620 |
| 5962-9159302MYA | | 05/13/1993 | | (NONE) | 05/10/1995 | | 7B164 (GEN) | 620 |
| 5962-9159302MZA | | 05/13/1993 | | (NONE) | 05/10/1995 | | 7B164 (GEN) | 620 |
| 5962-9159303MKA | | 05/13/1993 | | (NONE) | 05/10/1995 | | 7B164 (GEN) | 620 |
| 5962-9159303MYA | | 05/13/1993 | | (NONE) | 05/10/1995 | | 7B164 (GEN) | 620 |
| 5962-9159303MZA | | 05/13/1993 | | (NONE) | 05/10/1995 | | 7B164 (GEN) | 620 |
| 5962-9159304MKA | | 05/13/1993 | | (NONE) | 05/10/1995 | | 7B166 (GEN) | 620 |
| 5962-9159304MLA | | 05/13/1993 | | (NONE) | 05/10/1995 | | 7B166 (GEN) | 620 |
| 5962-9159304MXA | | 05/13/1993 | | (NONE) | 05/10/1995 | | 7B166 (GEN) | 620 |
| 5962-9159305MKA | | 05/13/1993 | | (NONE) | 05/10/1995 | | 7B166 (GEN) | 620 |
| 5962-9159305MLA | | 05/13/1993 | | (NONE) | 05/10/1995 | | 7B166 (GEN) | 620 |
| 5962-9159305MXA | | 05/13/1993 | | (NONE) | 05/10/1995 | | 7B166 (GEN) | 620 |
| 5962-9159306MKA | | 05/13/1993 | | (NONE) | 05/10/1995 | | 7B166 (GEN) | 620 |
| 5962-9159306MLA | | 05/13/1993 | | (NONE) | 05/10/1995 | | 7B166 (GEN) | 620 |
| 5962-9159306MXA | | 05/13/1993 | | (NONE) | 05/10/1995 | | 7B166 (GEN) | 620 |
| 5962-9159401MTA | | 06/28/1994 | | (NONE) | | | 7B185-15 (GEN) | 620 |
| 5962-9159401MYA | | 06/28/1994 | | (NONE) | 03/05/1996 | | 7B185-15 (GEN) | 620 |
| 5962-9159401MZA | | 06/28/1994 | | (NONE) | 03/05/1996 | | 7B185-15 (GEN) | 620 |
| 5962-9159402MTA | | 06/28/1994 | | (NONE) | 05/10/1995 | | 7B185-12 (GEN) | 620 |
| 5962-9159402MYA | | 06/28/1994 | | (NONE) | 03/05/1996 | | 7B185-12 (GEN) | 620 |
| 5962-9159402MZA | | 06/28/1994 | | (NONE) | 03/05/1996 | | 7B185-12 (GEN) | 620 |
| 5962-9159403MTA | | 06/28/1994 | | (NONE) | 05/10/1995 | | 7B185-10 (GEN) | 620 |
| 5962-9159403MYA | | 06/28/1994 | | (NONE) | | | 7B185-10 (GEN) | 620 |
| 5962-9159403MZA | | 06/28/1994 | | (NONE) | | | 7B185-10 (GEN) | 620 |
| 5962-9159501MPA | C | 09/20/2000 | 1 | MAXIM INTEG. | | | MXL1062MJ8/883B | 805 |
| 5962-9159502MPA | C | 09/20/2000 | 1 | MAXIM INTEG. | | | MAX280MJA/883B | 805 |
| 5962-9159701M2A | | 02/08/1993 | | (NONE) | 09/01/1997 | | 54F777 (GEN) | 590 |
| 5962-9159701MRA | | 02/08/1993 | | (NONE) | 09/01/1997 | | 54F777 (GEN) | 590 |
| 5962-9159701MSA | | 02/08/1993 | | (NONE) | 09/01/1997 | | 54F777 (GEN) | 590 |
| 5962-9159901HZA | A | 06/12/2003 | 1 | ADV. ANALOG | | Y | 7892-01 | 594 |
| 5962-9159902HZA | A | 06/12/2003 | 1 | ADV. ANALOG | | Y | 7892-02 | 594 |
| 5962-9159903HZA | A | 06/12/2003 | 1 | ADV. ANALOG | | Y | 7892-03 | 594 |
| 5962-9159904HZA | A | 06/12/2003 | 1 | ADV. ANALOG | | Y | ATW2815S/CH | 594 |
| 5962-9159905HZA | A | 06/12/2003 | 1 | ADV. ANALOG | | Y | ATW2815S/CH-SLV | 594 |
| 5962-9159906HZA | A | 06/12/2003 | 1 | ADV. ANALOG | | Y | ATW2815S/CH-MSTR | 594 |
| 5962-9160001HXA | B | 02/03/1999 | 1 | ADV. ANALOG | | Y | AHF2805S/CH | 594 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9160001HZA | B | 02/03/1999 | 1 | ADV. ANALOG | | Y | AHF2805SF/CH | 594 |
| 5962-9160101HXA | J | 08/23/2004 | 1 | INTERPOINT | | Y | MHF+2815S/883 | 594 |
| 5962-9160101HXC | J | 08/23/2004 | 1 | INTERPOINT | | Y | MHF+2815S/883 | 594 |
| 5962-9160101HZA | J | 08/23/2004 | 1 | INTERPOINT | | Y | MHF+2815SF/883 | 594 |
| 5962-9160101HZC | J | 08/23/2004 | 1 | INTERPOINT | | Y | MHF+2815SF/883 | 594 |
| 5962-9160102HXA | J | 08/23/2004 | 1 | INTERPOINT | | Y | SMHF2815S/HO | 594 |
| 5962-9160102HXC | J | 08/23/2004 | 1 | INTERPOINT | | Y | SMHF2815S/HO | 594 |
| 5962L9160102HXA | J | 08/23/2004 | 1 | INTERPOINT | | Y | SMHF2815S/HL | 594 |
| 5962L9160102HXC | J | 08/23/2004 | 1 | INTERPOINT | | Y | SMHF2815S/HL | 594 |
| 5962L9160102KXA | J | 08/23/2004 | 1 | INTERPOINT | | Y | SMHF2815S/KL | 594 |
| 5962L9160102KXC | J | 08/23/2004 | 1 | INTERPOINT | | Y | SMHF2815S/KL | 594 |
| 5962R9160102HXA | J | 08/23/2004 | 1 | INTERPOINT | | Y | SMHF2815S/HR | 594 |
| 5962R9160102HXC | J | 08/23/2004 | 1 | INTERPOINT | | Y | SMHF2815S/HR | 594 |
| 5962R9160102KXA | J | 08/23/2004 | 1 | INTERPOINT | | Y | SMHF2815S/KR | 594 |
| 5962R9160102KXC | J | 08/23/2004 | 1 | INTERPOINT | | Y | SMHF2815S/KR | 594 |
| 5962-9160102HZA | J | 08/23/2004 | 1 | INTERPOINT | | Y | SMHF2815SF/HO | 594 |
| 5962-9160102HZC | J | 08/23/2004 | 1 | INTERPOINT | | Y | SMHF2815SF/HO | 594 |
| 5962L9160102HZA | J | 08/23/2004 | 1 | INTERPOINT | | Y | SMHF2815SF/HL | 594 |
| 5962L9160102HZC | J | 08/23/2004 | 1 | INTERPOINT | | Y | SMHF2815SF/HL | 594 |
| 5962L9160102KZA | J | 08/23/2004 | 1 | INTERPOINT | | Y | SMHF2815SF/KL | 594 |
| 5962L9160102KZC | J | 08/23/2004 | 1 | INTERPOINT | | Y | SMHF2815SF/KL | 594 |
| 5962R9160102HZA | J | 08/23/2004 | 1 | INTERPOINT | | Y | SMHF2815SF/HR | 594 |
| 5962R9160102HZC | J | 08/23/2004 | 1 | INTERPOINT | | Y | SMHF2815SF/HR | 594 |
| 5962R9160102KZA | J | 08/23/2004 | 1 | INTERPOINT | | Y | SMHF2815SF/KR | 594 |
| 5962R9160102KZC | J | 08/23/2004 | 1 | INTERPOINT | | Y | SMHF2815SF/KR | 594 |
| 5962-9160201HXA | B | 03/12/1999 | 1 | ADV. ANALOG | | Y | ATO2812T/CH | 594 |
| 5962-9160201HZA | B | 03/12/1999 | 1 | ADV. ANALOG | | Y | ATO2812TF/CH | 594 |
| 5962-9160301M2A | A | 02/04/1998 | 3 | NATIONAL | | Y | 54AC169LMQB | 304 |
| 5962R9160301M2A | A | 02/04/1998 | 3 | NATIONAL | | Y | 54AC169LMQB-RH | 304 |
| 5962R9160301V2A | A | 02/04/1998 | 3 | NATIONAL | | Y | 54AC169ERQMLV | 304 |
| 5962-9160301MEA | A | 02/04/1998 | 3 | NATIONAL | | Y | 54AC169DMQB | 304 |
| 5962R9160301MEA | A | 02/04/1998 | 3 | NATIONAL | | Y | 54AC169DMQB-RH | 304 |
| 5962R9160301VEA | A | 02/04/1998 | 3 | NATIONAL | | Y | 54AC169JRQMLV | 304 |
| 5962-9160301MFA | A | 02/04/1998 | 3 | NATIONAL | | Y | 54AC169FMQB | 304 |
| 5962R9160301MFA | A | 02/04/1998 | 3 | NATIONAL | | Y | 54AC169FMQB-RH | 304 |
| 5962R9160301VFA | A | 02/04/1998 | 3 | NATIONAL | | Y | 54AC169WRQMLV | 304 |
| 5962-9160401M2A | | 10/29/1991 | 3 | NATIONAL | | Y | 54AC258LMQB | 276 |
| 5962-9160401MEA | | 10/29/1991 | 3 | NATIONAL | | Y | 54AC258DMQB | 276 |
| 5962-9160401MFA | | 10/29/1991 | 3 | NATIONAL | | Y | 54AC258FMQB | 276 |
| 5962-9160501M2A | | 04/17/1992 | | (NONE) | | | 54AC378 (GEN) | 159 |
| 5962-9160501MEA | | 04/17/1992 | | (NONE) | | | 54AC378 (GEN) | 159 |
| 5962-9160501MFA | | 04/17/1992 | | (NONE) | | | 54AC378 (GEN) | 159 |
| 5962-9160601M3A | | 11/01/1991 | | NATIONAL | | Y | 54AC821LMQB | 159 |
| 5962-9160601MKA | | 11/01/1991 | | NATIONAL | | Y | 54AC821FMQB | 159 |
| 5962-9160601MLA | | 11/01/1991 | | NATIONAL | | Y | 54AC821SDMQB | 159 |
| 5962-9160701M2A | | 04/20/1992 | 3 | NATIONAL | | Y | 54ACT323LMQB | 228 |
| 5962-9160701MRA | | 04/20/1992 | 3 | NATIONAL | | Y | 54ACT323DMQB | 228 |
| 5962-9160701MSA | | 04/20/1992 | 3 | NATIONAL | | Y | 54ACT323FMQB | 228 |
| 5962-9160901M3A | | 04/07/1992 | 3 | NATIONAL | | Y | 54ACT818LMQB | 228 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9160901MKA | | 04/07/1992 | 3 | NATIONAL | | Y | 54ACT818FMQB | 228 |
| 5962-9160901MLA | | 04/07/1992 | 3 | NATIONAL | | Y | 54ACT818SDMQB | 228 |
| 5962-9161001M3A | | 11/01/1991 | | NATIONAL | | Y | 54ACT823LMQB | 159 |
| 5962-9161001MKA | | 11/01/1991 | | NATIONAL | | Y | 54ACT823FMQB | 159 |
| 5962-9161001MLA | | 11/01/1991 | | NATIONAL | | Y | 54ACT823SDMQB | 159 |
| 5962-9161101M3A | A | 07/18/2000 | 1 | NATIONAL | | Y | 54ACT825LMQB | 159 |
| 5962-9161101MKA | A | 07/18/2000 | 1 | NATIONAL | | Y | 54ACT825FMQB | 159 |
| 5962-9161101MLA | A | 07/18/2000 | 1 | NATIONAL | | Y | 54ACT825DMQB | 159 |
| 5962-9161201MTA | A | 11/29/1995 | | (NONE) | | | 84256LPS45 (GEN) | 625 |
| 5962-9161201MUA | A | 11/29/1995 | | (NONE) | | | 84256LPS45 (GEN) | 625 |
| 5962-9161201MXA | A | 11/29/1995 | | (NONE) | | | 84256LPS45 (GEN) | 625 |
| 5962-9161201MYA | A | 11/29/1995 | | (NONE) | | | 84256LPS45 (GEN) | 625 |
| 5962-9161201MZA | A | 11/29/1995 | | (NONE) | | | 84256LPS45 (GEN) | 625 |
| 5962-9161202MTA | A | 11/29/1995 | | (NONE) | | | 84256CS45 (GEN) | 625 |
| 5962-9161202MUA | A | 11/29/1995 | | (NONE) | | | 84256CS45 (GEN) | 625 |
| 5962-9161202MXA | A | 11/29/1995 | | (NONE) | | | 84256CS45 (GEN) | 625 |
| 5962-9161202MYA | A | 11/29/1995 | | (NONE) | | | 84256CS45 (GEN) | 625 |
| 5962-9161202MZA | A | 11/29/1995 | | (NONE) | | | 84256CS45 (GEN) | 625 |
| 5962-9161203MTA | A | 11/29/1995 | | (NONE) | | | 84256LPS35 (GEN) | 625 |
| 5962-9161203MUA | A | 11/29/1995 | | (NONE) | | | 84256LPS35 (GEN) | 625 |
| 5962-9161203MXA | A | 11/29/1995 | | (NONE) | | | 84256LPS35 (GEN) | 625 |
| 5962-9161203MYA | A | 11/29/1995 | | (NONE) | | | 84256LPS35 (GEN) | 625 |
| 5962-9161203MZA | A | 11/29/1995 | | (NONE) | | | 84256LPS35 (GEN) | 625 |
| 5962-9161204MTA | A | 11/29/1995 | | (NONE) | | | 84256CS35 (GEN) | 625 |
| 5962-9161204MUA | A | 11/29/1995 | | (NONE) | | | 84256CS35 (GEN) | 625 |
| 5962-9161204MXA | A | 11/29/1995 | | (NONE) | | | 84256CS35 (GEN) | 625 |
| 5962-9161204MYA | A | 11/29/1995 | | (NONE) | | | 84256CS35 (GEN) | 625 |
| 5962-9161204MZA | A | 11/29/1995 | | (NONE) | | | 84256CS35 (GEN) | 625 |
| 5962-9161205MTA | A | 11/29/1995 | | (NONE) | | | 84256LPS25 (GEN) | 625 |
| 5962-9161205MUA | A | 11/29/1995 | | (NONE) | | | 84256LPS25 (GEN) | 625 |
| 5962-9161205MXA | A | 11/29/1995 | | (NONE) | | | 84256LPS25 (GEN) | 625 |
| 5962-9161205MYA | A | 11/29/1995 | | (NONE) | | | 84256LPS25 (GEN) | 625 |
| 5962-9161205MZA | A | 11/29/1995 | | (NONE) | | | 84256LPS25 (GEN) | 625 |
| 5962-9161206MTA | A | 11/29/1995 | | (NONE) | | | 84256CS25 (GEN) | 625 |
| 5962-9161206MUA | A | 11/29/1995 | | (NONE) | | | 84256CS25 (GEN) | 625 |
| 5962-9161206MXA | A | 11/29/1995 | | (NONE) | | | 84256CS25 (GEN) | 625 |
| 5962-9161206MYA | A | 11/29/1995 | | (NONE) | | | 84256CS25 (GEN) | 625 |
| 5962-9161206MZA | A | 11/29/1995 | | (NONE) | | | 84256CS25 (GEN) | 625 |
| 5962-9161207MMA | A | 11/29/1995 | 1 | AUSTIN SEMI. | | Y | MT5C1005DCJ-20L/883 | 625 |
| 5962-9161207MTA | A | 11/29/1995 | | (NONE) | | | 84256LPS20 (GEN) | 625 |
| 5962-9161207MUA | A | 11/29/1995 | 1 | AUSTIN SEMI. | | Y | MT5C1005F-20L/883C | 625 |
| 5962-9161207MXA | A | 11/29/1995 | 1 | AUSTIN SEMI. | | Y | MT5C1005C-20L/883C | 625 |
| 5962-9161207MYA | A | 11/29/1995 | | (NONE) | | | 84256LPS20 (GEN) | 625 |
| 5962-9161207MZA | A | 11/29/1995 | | (NONE) | | | 84256LPS20 (GEN) | 625 |
| 5962-9161208MMA | A | 11/29/1995 | 1 | AUSTIN SEMI. | | Y | MT5C1005DCJ-20/883C | 625 |
| 5962-9161208MTA | A | 11/29/1995 | | (NONE) | | | 84256CS20 (GEN) | 625 |
| 5962-9161208MUA | A | 11/29/1995 | 1 | AUSTIN SEMI. | | Y | MT5C1005F-20/883C | 625 |
| 5962-9161208MXA | A | 11/29/1995 | 1 | AUSTIN SEMI. | | Y | MT5C1005C-20/883C | 625 |
| 5962-9161208MYA | A | 11/29/1995 | | (NONE) | | | 84256CS20 (GEN) | 625 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9161208MZA | A | 11/29/1995 | | (NONE) | | | 84256CS20 (GEN) | 625 |
| 5962-9161209MMA | A | 11/29/1995 | 1 | AUSTIN SEMI. | | Y | MT5C1005DCJ-15L/883 | 625 |
| 5962-9161209MUA | A | 11/29/1995 | 1 | AUSTIN SEMI. | | Y | MT5C1005F-15L/883C | 625 |
| 5962-9161209MXA | A | 11/29/1995 | 1 | AUSTIN SEMI. | | Y | MT5C1005C-15L/883C | 625 |
| 5962-9161210MMA | A | 11/29/1995 | 1 | AUSTIN SEMI. | | Y | MT5C1005DCJ-15/883C | 625 |
| 5962-9161210MUA | A | 11/29/1995 | 1 | AUSTIN SEMI. | | Y | MT5C1005F-15/883C | 625 |
| 5962-9161210MXA | A | 11/29/1995 | 1 | AUSTIN SEMI. | | Y | MT5C1005C-15/883C | 625 |
| 5962-9161301HZA | A | 06/16/2003 | 1 | ADV. ANALOG | | Y | ATW2815D/CH | 594 |
| 5962-9161302HZA | A | 06/16/2003 | 1 | ADV. ANALOG | | Y | ATW2815D/CH-SLV | 594 |
| 5962-9161303HZA | A | 06/16/2003 | 1 | ADV. ANALOG | | Y | ATW2815D/CH-MSTR | 594 |
| 5962-9161401HXA | J | 08/23/2004 | 1 | INTERPOINT | | Y | MHF+2815D/883 | 594 |
| 5962-9161401HXC | J | 08/23/2004 | 1 | INTERPOINT | | Y | MHF+2815D/883 | 594 |
| 5962-9161401HZA | J | 08/23/2004 | 1 | INTERPOINT | | Y | MHF+2815DF/883 | 594 |
| 5962-9161401HZC | J | 08/23/2004 | 1 | INTERPOINT | | Y | MHF+2815DF/883 | 594 |
| 5962-9161402HXA | J | 08/23/2004 | 1 | INTERPOINT | | Y | SMHF2815D/HO | 594 |
| 5962-9161402HXC | J | 08/23/2004 | 1 | INTERPOINT | | Y | SMHF2815D/HO | 594 |
| 5962L9161402HXA | J | 08/23/2004 | 1 | INTERPOINT | | Y | SMHF2815D/HL | 594 |
| 5962L9161402HXC | J | 08/23/2004 | 1 | INTERPOINT | | Y | SMHF2815D/HL | 594 |
| 5962L9161402KXA | J | 08/23/2004 | 1 | INTERPOINT | | Y | SMHF2815D/KL | 594 |
| 5962L9161402KXC | J | 08/23/2004 | 1 | INTERPOINT | | Y | SMHF2815D/KL | 594 |
| 5962R9161402HXA | J | 08/23/2004 | 1 | INTERPOINT | | Y | SMHF2815D/HR | 594 |
| 5962R9161402HXC | J | 08/23/2004 | 1 | INTERPOINT | | Y | SMHF2815D/HR | 594 |
| 5962R9161402KXA | J | 08/23/2004 | 1 | INTERPOINT | | Y | SMHF2815D/KR | 594 |
| 5962R9161402KXC | J | 08/23/2004 | 1 | INTERPOINT | | Y | SMHF2815D/KR | 594 |
| 5962-9161402HZA | J | 08/23/2004 | 1 | INTERPOINT | | Y | SMHF2815DF/HO | 594 |
| 5962-9161402HZC | J | 08/23/2004 | 1 | INTERPOINT | | Y | SMHF2815DF/HO | 594 |
| 5962L9161402HZA | J | 08/23/2004 | 1 | INTERPOINT | | Y | SMHF2815DF/HL | 594 |
| 5962L9161402HZC | J | 08/23/2004 | 1 | INTERPOINT | | Y | SMHF2815DF/HL | 594 |
| 5962L9161402KZA | J | 08/23/2004 | 1 | INTERPOINT | | Y | SMHF2815DF/KL | 594 |
| 5962L9161402KZC | J | 08/23/2004 | 1 | INTERPOINT | | Y | SMHF2815DF/KL | 594 |
| 5962R9161402HZA | J | 08/23/2004 | 1 | INTERPOINT | | Y | SMHF2815DF/HR | 594 |
| 5962R9161402HZC | J | 08/23/2004 | 1 | INTERPOINT | | Y | SMHF2815DF/HR | 594 |
| 5962R9161402KZA | J | 08/23/2004 | 1 | INTERPOINT | | Y | SMHF2815DF/KR | 594 |
| 5962R9161402KZC | J | 08/23/2004 | 1 | INTERPOINT | | Y | SMHF2815DF/KR | 594 |
| 5962-9161501HXC | B | 03/28/1994 | | (NONE) | | | 1510-369/2 (GEN) | 594 |
| 5962-9161701MXA | D | 05/02/2002 | 2 | IDT | | Y | IDT7025S70GB | 622 |
| 5962-9161701MYA | D | 05/02/2002 | 2 | IDT | | Y | IDT7025S70FB | 622 |
| 5962-9161702MXA | D | 05/02/2002 | 2 | IDT | | Y | IDT7025L70GB | 622 |
| 5962-9161702MYA | D | 05/02/2002 | 2 | IDT | | Y | IDT7025L70FB | 622 |
| 5962-9161703MXA | D | 05/02/2002 | 2 | IDT | | Y | IDT7025S55GB | 622 |
| 5962-9161703MYA | D | 05/02/2002 | 2 | IDT | | Y | IDT7025S55FB | 622 |
| 5962-9161704MXA | D | 05/02/2002 | 2 | IDT | | Y | IDT7025L55GB | 622 |
| 5962-9161704MYA | D | 05/02/2002 | 2 | IDT | | Y | IDT7025L55FB | 622 |
| 5962-9161705MXA | D | 05/02/2002 | 2 | IDT | | Y | IDT7025S45GB | 622 |
| 5962-9161705MYA | D | 05/02/2002 | 2 | IDT | | Y | IDT7025S45FB | 622 |
| 5962-9161706MXA | D | 05/02/2002 | 2 | IDT | | Y | IDT7025L45GB | 622 |
| 5962-9161706MYA | D | 05/02/2002 | 2 | IDT | | Y | IDT7025L45FB | 622 |
| 5962-9161706QZC | D | 05/02/2002 | 2 | ATMEL NANTES | | Y | MMK2-67025EV-45MQ | 622 |
| 5962-9161706VZC | D | 05/02/2002 | 2 | ATMEL NANTES | | Y | SMK2-67025EV-45SV | 622 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9161707MXA | D | 05/02/2002 | 2 | IDT | | Y | IDT7025S35GB | 622 |
| 5962-9161707MYA | D | 05/02/2002 | 2 | IDT | | Y | IDT7025S35FB | 622 |
| 5962-9161708MXA | D | 05/02/2002 | 2 | IDT | | Y | IDT7025L35GB | 622 |
| 5962-9161708MYA | D | 05/02/2002 | 2 | IDT | | Y | IDT7025L35FB | 622 |
| 5962-9161709Q9A | D | 05/02/2002 | 2 | ATMEL NANTES | | Y | MM0-67025EV-30MQ | 622 |
| 5962-9161709V9A | D | 05/02/2002 | 2 | ATMEL NANTES | | Y | SM0-67025EV-30SV | 622 |
| 5962-9161709QZC | D | 05/02/2002 | 2 | ATMEL NANTES | | Y | MMK2-67025EV-30MQ | 622 |
| 5962-9161709VZC | D | 05/02/2002 | 2 | ATMEL NANTES | | Y | SMK2-67025EV-30SV | 622 |
| 5962-9161801MXA | | 03/18/1994 | | (NONE) | 04/28/1998 | | 72031 (GEN) | 670 |
| 5962-9161802MXA | | 03/18/1994 | | (NONE) | 04/28/1998 | | 72031 (GEN) | 670 |
| 5962-9161901MPA | A | 09/28/2000 | | (NONE) | 03/30/2001 | | LTC1042 (GEN) | 779 |
| 5962-9162101HXA | B | 03/13/2001 | 1 | APEX MICRO. | | Y | PA83M/883 | 724 |
| 5962-9162301MXA | E | 11/15/1999 | | (NONE) | | | 34020-28 (GEN) | 429 |
| 5962-9162301MYA | E | 11/15/1999 | | (NONE) | | | 34020-28 (GEN) | 429 |
| 5962-9162302MXA | E | 11/15/1999 | | (NONE) | | | 34020-30 (GEN) | 429 |
| 5962-9162302MYA | E | 11/15/1999 | | (NONE) | | | 34020-30 (GEN) | 429 |
| 5962-9162303MXA | E | 11/15/1999 | 3 | TI | | Y | SMJ34020AGBM32 | 429 |
| 5962-9162303MXC | E | 11/15/1999 | 3 | TI | | Y | SMJ34020AGBM32 | 429 |
| 5962-9162303MYA | E | 11/15/1999 | 3 | TI | | Y | SMJ34020AHTM32 | 429 |
| 5962-9162304MXA | E | 11/15/1999 | 3 | TI | | Y | SMJ34020AGBM40 | 429 |
| 5962-9162304MXC | E | 11/15/1999 | 3 | TI | | Y | SMJ34020AGBM40 | 429 |
| 5962-9162304MYA | E | 11/15/1999 | 3 | TI | | Y | SMJ34020AHTM40 | 429 |
| 5962-9162401MXA | | 05/14/1993 | | (NONE) | | | 7C266-45 (GEN) | 660 |
| 5962-9162401MYA | | 05/14/1993 | | (NONE) | | | 7C266-45 (GEN) | 660 |
| 5962-9162402MXA | | 05/14/1993 | | (NONE) | | | 7C266-25 (GEN) | 660 |
| 5962-9162402MYA | | 05/14/1993 | | (NONE) | | | 7C266-25 (GEN) | 660 |
| 5962-9162501HXA | B | 04/09/2001 | 1 | ADV. ANALOG | | Y | AHE2815S/CH | 594 |
| 5962-9162501HXC | B | 04/09/2001 | 1 | ADV. ANALOG | | Y | AHE2815S/CH | 594 |
| 5962-9162501HZA | B | 04/09/2001 | 1 | ADV. ANALOG | | Y | AHE2815SF/CH | 594 |
| 5962-9162501HZC | B | 04/09/2001 | 1 | ADV. ANALOG | | Y | AHE2815SF/CH | 594 |
| 5962-9162502HXA | B | 04/09/2001 | 1 | ADV. ANALOG | | Y | AHE2815S/CH-SLV | 594 |
| 5962-9162502HXC | B | 04/09/2001 | 1 | ADV. ANALOG | | Y | AHE2815S/CH-SLV | 594 |
| 5962-9162502HZA | B | 04/09/2001 | 1 | ADV. ANALOG | | Y | AHE2815SF/CH-SLV | 594 |
| 5962-9162502HZC | B | 04/09/2001 | 1 | ADV. ANALOG | | Y | AHE2815SF/CH-SLV | 594 |
| 5962-9162503HXA | B | 04/09/2001 | 1 | ADV. ANALOG | | Y | AHE2815S/CH-MSTR | 594 |
| 5962-9162503HXC | B | 04/09/2001 | 1 | ADV. ANALOG | | Y | AHE2815S/CH-MSTR | 594 |
| 5962-9162503HZA | B | 04/09/2001 | 1 | ADV. ANALOG | | Y | AHE2815SF/CH-MSTR | 594 |
| 5962-9162503HZC | B | 04/09/2001 | 1 | ADV. ANALOG | | Y | AHE2815SF/CH-MSTR | 594 |
| 5962-9162701M2A | A | 09/14/2004 | 0 | TI | | Y | SNJ54AS1000AFK | 500 |
| 5962-9162701MCA | A | 09/14/2004 | 0 | TI | | Y | SNJ54AS1000AJ | 500 |
| 5962-9162701MDA | A | 09/14/2004 | 0 | TI | | Y | SNJ54AS1000AW | 500 |
| 5962-9162901MXA | | 05/21/1992 | 3 | NATIONAL | | Y | 100314DMQB | 579 |
| 5962-9162901VXA | | 05/21/1992 | 3 | NATIONAL | | Y | 100314J-QMLV | 579 |
| 5962-9162901MYA | | 05/21/1992 | 3 | NATIONAL | | Y | 100314FMQB | 579 |
| 5962-9162901VYA | | 05/21/1992 | 3 | NATIONAL | | Y | 100314W-QMLV | 579 |
| 5962-9163001MEA | | 12/31/1991 | | TI | | Y | CD54HCT4052F3A | 192 |
| 5962-9163101MIA | | 05/27/1992 | | (NONE) | | | LM122 (GEN) | 814 |
| 5962-9163201MCA | B | 06/30/1995 | | (NONE) | 12/31/2001 | | LT1079 (GEN) | 713 |
| 5962-9163202MCA | B | 06/30/1995 | | (NONE) | 03/30/2001 | | LT1079A (GEN) | 713 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9163203MGA | B | 06/30/1995 | | (NONE) | | | LT1078 (GEN) | 713 |
| 5962-9163203MPA | B | 06/30/1995 | | (NONE) | 03/30/2001 | | LT1078 (GEN) | 713 |
| 5962-9163203MXA | B | 06/30/1995 | | (NONE) | 03/30/2001 | | LT1078 (GEN) | 713 |
| 5962-9163204MGA | B | 06/30/1995 | | (NONE) | | | LT1078A (GEN) | 713 |
| 5962-9163204MPA | B | 06/30/1995 | | (NONE) | 12/31/2001 | | LT1078A (GEN) | 713 |
| 5962-9163204MXA | B | 06/30/1995 | | (NONE) | 12/31/2001 | | LT1078A (GEN) | 713 |
| 5962-9163401M2A | | 01/26/1993 | | (NONE) | 09/24/2000 | | HA-5221 (GEN) | 701 |
| 5962-9163401MPA | | 01/26/1993 | | (NONE) | 09/24/2000 | | HA-5221 (GEN) | 701 |
| 5962-9163402M2A | | 01/26/1993 | | (NONE) | | | HA-5222 (GEN) | 710 |
| 5962-9163402MPA | | 01/26/1993 | | (NONE) | | | HA-5222 (GEN) | 710 |
| 5962-9163901M2A | B | 02/20/1998 | 1 | NATIONAL | | Y | DS26C31ME/883 | 569 |
| 5962-9163901Q2A | B | 02/20/1998 | 2 | TI | | Y | AM26C31MFKB | 569 |
| 5962-9163901MEA | B | 02/20/1998 | 1 | NATIONAL | | Y | DS26C31MJ/883 | 569 |
| 5962-9163901QEA | B | 02/20/1998 | 2 | TI | | Y | AM26C31MJB | 569 |
| 5962-9163901MFA | B | 02/20/1998 | 1 | NATIONAL | | Y | DS26C31MW/883 | 569 |
| 5962-9163901QFA | B | 02/20/1998 | 2 | TI | | Y | AM26C31MWB | 569 |
| 5962-9163901MXA | B | 02/20/1998 | 1 | NATIONAL | | Y | DS26C31MWG/883 | 569 |
| 5962-9164001M2A | B | 02/19/1998 | 1 | NATIONAL | | Y | DS26C32AME/883 | 575 |
| 5962-9164001Q2A | B | 02/19/1998 | 2 | TI | | Y | AM26C32MFKB | 575 |
| 5962-9164001MEA | B | 02/19/1998 | 1 | NATIONAL | | Y | DS26C32AMJ/883 | 575 |
| 5962-9164001QEA | B | 02/19/1998 | 2 | TI | | Y | AM26C32MJB | 575 |
| 5962-9164001MFA | B | 02/19/1998 | 1 | NATIONAL | | Y | DS26C32AMW/883 | 575 |
| 5962-9164001QFA | B | 02/19/1998 | 2 | TI | | Y | AM26C32MWB | 575 |
| 5962-9164001MXA | B | 02/19/1998 | 1 | NATIONAL | | Y | DS26C32MWG/883 | 575 |
| 5962-9164101MJA | | 08/18/1992 | 1 | ROCHESTER | | Y | DP8572AMD/883 | 422 |
| 5962-9164701MLA | A | 07/25/2001 | 1 | ANALOG (2) | | Y | AD7244SQ/883B | 591 |
| 5962-9165201M3A | B | 06/14/1993 | 1 | QP SEMI | | | TDC1112 | 591 |
| 5962-9165201MJA | B | 06/14/1993 | 1 | QP SEMI | | | TDC1112 | 591 |
| 5962-9165202M3A | B | 06/14/1993 | 1 | QP SEMI | | | TDC1112 | 591 |
| 5962-9165202MJA | B | 06/14/1993 | 1 | QP SEMI | | | TDC1112 | 591 |
| 5962-9165301M2A | C | 02/27/2003 | 2 | MICROSEMI | | Y | SG1644L/883B | 899 |
| 5962-9165301MCA | C | 02/27/2003 | 2 | MICROSEMI | | Y | SG1644J/883B | 899 |
| 5962-9165301MGA | C | 02/27/2003 | 2 | MICROSEMI | | Y | SG1644T/883B | 899 |
| 5962-9165301MPA | C | 02/27/2003 | 2 | MICROSEMI | | Y | SG1644Y/883B | 899 |
| 5962-9165401MXA | | 05/04/1992 | | NATIONAL | | Y | 100355DMQB | 399 |
| 5962-9165401VXA | | 05/04/1992 | 3 | NATIONAL | | Y | 100355J-QMLV | 399 |
| 5962-9165401MYA | | 05/04/1992 | | NATIONAL | | Y | 100355FMQB | 399 |
| 5962-9165401VYA | | 05/04/1992 | 3 | NATIONAL | | Y | 100355W-QMLV | 399 |
| 5962-9165501MXA | A | 06/25/1999 | 3 | NATIONAL | | Y | 100363DMQB | 279 |
| 5962-9165501MYA | A | 06/25/1999 | 3 | NATIONAL | | Y | 100363FMQB | 279 |
| 5962-9166101M2A | | 07/02/1993 | | (NONE) | | | 54LS442 (GEN) | 590 |
| 5962-9166101MRA | | 07/02/1993 | | (NONE) | | | 54LS442 (GEN) | 590 |
| 5962-9166101MSA | | 07/02/1993 | | (NONE) | | | 54LS442 (GEN) | 590 |
| 5962-9166201MXA | A | 04/19/1999 | 2 | IDT | | Y | IDT7024S70GB | 620 |
| 5962-9166201MYA | A | 04/19/1999 | 2 | IDT | | Y | IDT7024S70FB | 620 |
| 5962-9166202MXA | A | 04/19/1999 | 2 | IDT | | Y | IDT7024L70GB | 620 |
| 5962-9166202MYA | A | 04/19/1999 | 2 | IDT | | Y | IDT7024L70FB | 620 |
| 5962-9166203MXA | A | 04/19/1999 | 2 | IDT | | Y | IDT7024S55GB | 620 |
| 5962-9166203MYA | A | 04/19/1999 | 2 | IDT | | Y | IDT7024S55FB | 620 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9166204MXA | A | 04/19/1999 | 2 | IDT | | Y | IDT7024L55GB | 620 |
| 5962-9166204MYA | A | 04/19/1999 | 2 | IDT | | Y | IDT7024L55FB | 620 |
| 5962-9166205MXA | A | 04/19/1999 | 2 | IDT | | Y | IDT7024S45GB | 620 |
| 5962-9166205MYA | A | 04/19/1999 | 2 | IDT | | Y | IDT7024S45FB | 620 |
| 5962-9166206MXA | A | 04/19/1999 | 2 | IDT | | Y | IDT7024L45GB | 620 |
| 5962-9166206MYA | A | 04/19/1999 | 2 | IDT | | Y | IDT7024L45FB | 620 |
| 5962-9166207MXA | A | 04/19/1999 | 2 | IDT | | Y | IDT7024S35GB | 620 |
| 5962-9166207MYA | A | 04/19/1999 | 2 | IDT | | Y | IDT7024S35FB | 620 |
| 5962-9166208MXA | A | 04/19/1999 | 2 | IDT | | Y | IDT7024L35GB | 620 |
| 5962-9166208MYA | A | 04/19/1999 | 2 | IDT | | Y | IDT7024L35FB | 620 |
| 5962-9166209MXA | A | 04/19/1999 | 2 | IDT | | Y | IDT7024S25GB | 620 |
| 5962-9166209MYA | A | 04/19/1999 | 2 | IDT | | Y | IDT7024S25FB | 620 |
| 5962-9166210MXA | A | 04/19/1999 | 2 | IDT | | Y | IDT7024L25GB | 620 |
| 5962-9166210MYA | A | 04/19/1999 | 2 | IDT | | Y | IDT7024L25FB | 620 |
| 5962-9166211MXA | A | 04/19/1999 | 2 | IDT | | Y | IDT7024S20GB | 620 |
| 5962-9166211MYA | A | 04/19/1999 | 2 | IDT | | Y | IDT7024S20FB | 620 |
| 5962-9166212MXA | A | 04/19/1999 | 2 | IDT | | Y | IDT7024L20GB | 620 |
| 5962-9166212MYA | A | 04/19/1999 | 2 | IDT | | Y | IDT7024L20FB | 620 |
| 5962-9166401HXA | C | 08/31/2004 | 1 | INTERPOINT | | Y | MHF+2812S/883 | 594 |
| 5962-9166401HXC | C | 08/31/2004 | 1 | INTERPOINT | | Y | MHF+2812S/883 | 594 |
| 5962-9166401HZA | C | 08/31/2004 | 1 | INTERPOINT | | Y | MHF+2812SF/883 | 594 |
| 5962-9166401HZC | C | 08/31/2004 | 1 | INTERPOINT | | Y | MHF+2812SF/883 | 594 |
| 5962-9166402HXA | C | 08/31/2004 | 1 | INTERPOINT | | Y | SMHF2812S/HO | 594 |
| 5962-9166402HXC | C | 08/31/2004 | 1 | INTERPOINT | | Y | SMHF2812S/HO | 594 |
| 5962L9166402HXA | C | 08/31/2004 | 1 | INTERPOINT | | Y | SMHF2812S/HL | 594 |
| 5962L9166402HXC | C | 08/31/2004 | 1 | INTERPOINT | | Y | SMHF2812S/HL | 594 |
| 5962L9166402KXA | C | 08/31/2004 | 1 | INTERPOINT | | Y | SMHF2812S/KL | 594 |
| 5962L9166402KXC | C | 08/31/2004 | 1 | INTERPOINT | | Y | SMHF2812S/KL | 594 |
| 5962R9166402HXA | C | 08/31/2004 | 1 | INTERPOINT | | Y | SMHF2812S/HR | 594 |
| 5962R9166402HXC | C | 08/31/2004 | 1 | INTERPOINT | | Y | SMHF2812S/HR | 594 |
| 5962R9166402KXA | C | 08/31/2004 | 1 | INTERPOINT | | Y | SMHF2812S/KR | 594 |
| 5962R9166402KXC | C | 08/31/2004 | 1 | INTERPOINT | | Y | SMHF2812S/KR | 594 |
| 5962-9166402HZA | C | 08/31/2004 | 1 | INTERPOINT | | Y | SMHF2812SF/HO | 594 |
| 5962-9166402HZC | C | 08/31/2004 | 1 | INTERPOINT | | Y | SMHF2812SF/HO | 594 |
| 5962L9166402HZA | C | 08/31/2004 | 1 | INTERPOINT | | Y | SMHF2812SF/HL | 594 |
| 5962L9166402HZC | C | 08/31/2004 | 1 | INTERPOINT | | Y | SMHF2812SF/HL | 594 |
| 5962L9166402KZA | C | 08/31/2004 | 1 | INTERPOINT | | Y | SMHF2812SF/KL | 594 |
| 5962L9166402KZC | C | 08/31/2004 | 1 | INTERPOINT | | Y | SMHF2812SF/KL | 594 |
| 5962R9166402HZA | C | 08/31/2004 | 1 | INTERPOINT | | Y | SMHF2812SF/HR | 594 |
| 5962R9166402HZC | C | 08/31/2004 | 1 | INTERPOINT | | Y | SMHF2812SF/HR | 594 |
| 5962R9166402KZA | C | 08/31/2004 | 1 | INTERPOINT | | Y | SMHF2812SF/KR | 594 |
| 5962R9166402KZC | C | 08/31/2004 | 1 | INTERPOINT | | Y | SMHF2812SF/KR | 594 |
| 5962-9166501HXA | B | 05/24/2000 | | (NONE) | 09/27/2002 | | CLC232A (GEN) | 755 |
| 5962-9166601MPA | | 12/13/1994 | | (NONE) | | | CLC422 (GEN) | 719 |
| 5962-9166701QEA | D | 05/01/2001 | 1 | NATIONAL | | Y | LM2941J/883 | 780 |
| 5962-9166701VEA | D | 05/01/2001 | 1 | NATIONAL | | Y | LM2941J-QMLV | 780 |
| 5962-9166701QXA | D | 05/01/2001 | | (NONE) | 09/09/1999 | | LM2941 (GEN) | 780 |
| 5962-9166701QYA | D | 05/01/2001 | 1 | NATIONAL | | Y | LM2941WG/883 | 780 |
| 5962-9166701VYA | D | 05/01/2001 | 1 | NATIONAL | | Y | LM2941WG-QMLV | 780 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9166801Q2A | | 11/06/1995 | | (NONE) | 08/15/1999 | | TL598 (GEN) | 787 |
| 5962-9166801QEA | | 11/06/1995 | | (NONE) | 08/15/1999 | | TL598 (GEN) | 787 |
| 5962-9166901Q2A | | 11/03/1995 | | (NONE) | 08/15/1999 | | TL751L05 (GEN) | 782 |
| 5962-9166901QPA | | 11/03/1995 | | (NONE) | 08/15/1999 | | TL751L05 (GEN) | 782 |
| 5962-9167001Q2A | | 10/30/1995 | | (NONE) | 08/15/1999 | | TL751L12 (GEN) | 782 |
| 5962-9167001QPA | | 10/30/1995 | | (NONE) | 08/15/1999 | | TL751L12 (GEN) | 782 |
| 5962-9167101MEA | C | 04/01/2003 | 2 | NATIONAL | | Y | LM1575J-ADJ-QML | 786 |
| 5962-9167101MXA | C | 04/01/2003 | 2 | NATIONAL | | Y | LM1575K-ADJ-QML | 786 |
| 5962-9167101QYA | C | 04/01/2003 | | (NONE) | | | LM1575ADJ (GEN) | 786 |
| 5962-9167101QZA | C | 04/01/2003 | 2 | NATIONAL | | Y | LM1575WGADJ-QML | 786 |
| 5962-9167102QXA | C | 04/01/2003 | | (NONE) | 06/07/2001 | | LM1575ADJ (GEN) | 786 |
| 5962-9167201QEA | C | 07/20/2000 | 2 | NATIONAL | | Y | LM1575J-5.0-QML | 782 |
| 5962-9167201MXA | C | 07/20/2000 | 2 | NATIONAL | | Y | LM1575K-5.0-QML | 782 |
| 5962-9167201QYA | C | 07/20/2000 | | (NONE) | | | LM15755.0 (GEN) | 782 |
| 5962-9167201QZA | C | 07/20/2000 | 2 | NATIONAL | | Y | LM1575WG5.0-QML | 782 |
| 5962-9167202QXA | C | 07/20/2000 | | (NONE) | | | LM15755 (GEN) | 782 |
| 5962-9167301QEA | A | 07/06/2000 | 2 | NATIONAL | | Y | LM1575J-12-QML | 789 |
| 5962-9167301QXA | A | 07/06/2000 | | (NONE) | | | LM157512 (GEN) | 789 |
| 5962-9167301QYA | A | 07/06/2000 | | (NONE) | | | LM157512 (GEN) | 789 |
| 5962-9167301QZA | A | 07/06/2000 | 2 | NATIONAL | | Y | LM1575WG12-QML | 789 |
| 5962-9167302QXA | A | 07/06/2000 | | (NONE) | 06/07/2001 | | LM157512 (GEN) | 789 |
| 5962-9167401QEA | A | 07/06/2000 | 2 | NATIONAL | | Y | LM1575J-15-QML | 789 |
| 5962-9167401QXA | A | 07/06/2000 | | (NONE) | | | LM157515 (GEN) | 789 |
| 5962-9167401QYA | A | 07/06/2000 | | (NONE) | | | LM157515 (GEN) | 789 |
| 5962-9167401QZA | A | 07/06/2000 | 2 | NATIONAL | | Y | LM1575WG15-QML | 789 |
| 5962-9167402QXA | A | 07/06/2000 | | (NONE) | | | LM157515 (GEN) | 789 |
| 5962-9167501MPA | | 07/29/1992 | | (NONE) | 09/30/1993 | | EL2232 (GEN) | 710 |
| 5962-9167601HXA | C | 04/09/1998 | 1 | MICROPAC | | Y | 66079-001 | 460 |
| 5962-9167601HXC | C | 04/09/1998 | 1 | MICROPAC | | Y | 66079-001 | 460 |
| 5962-9167601KXA | C | 04/09/1998 | 1 | MICROPAC | | Y | 66079-300 | 460 |
| 5962-9167601KXC | C | 04/09/1998 | 1 | MICROPAC | | Y | 66079-300 | 460 |
| 5962-9167601HYA | C | 04/09/1998 | 1 | MICROPAC | | Y | 66079-000 | 460 |
| 5962-9167601HYC | C | 04/09/1998 | 1 | MICROPAC | | Y | 66079-000 | 460 |
| 5962-9167601KYA | C | 04/09/1998 | 1 | MICROPAC | | Y | 66079-301 | 460 |
| 5962-9167601KYC | C | 04/09/1998 | 1 | MICROPAC | | Y | 66079-301 | 460 |
| 5962-9167701MXA | | 09/25/1992 | 3 | QP SEMI | | Y | CY7C460A-80DMB | 670 |
| 5962-9167701MYA | | 09/25/1992 | 3 | QP SEMI | | Y | CY7C460A-80/MYA | 670 |
| 5962-9167701MZA | | 09/25/1992 | 3 | QP SEMI | | Y | CY7C460A-80LMB | 670 |
| 5962-9167702MXA | | 09/25/1992 | 1 | IDT | | Y | IDT7205L50DB | 670 |
| 5962-9167702MXA | | 09/25/1992 | 3 | QP SEMI | | Y | CY7C460A-50DMB | 670 |
| 5962-9167702MYA | | 09/25/1992 | 1 | IDT | | Y | IDT7205L50TDB | 670 |
| 5962-9167702MYA | | 09/25/1992 | 3 | QP SEMI | | Y | CY7C460A-50/MYA | 670 |
| 5962-9167702MZA | | 09/25/1992 | 1 | IDT | | Y | IDT7205L50LB | 670 |
| 5962-9167702MZA | | 09/25/1992 | 3 | QP SEMI | | Y | CY7C460A-50LMB | 670 |
| 5962-9167703MXA | | 09/25/1992 | 1 | IDT | | Y | IDT7205L30DB | 670 |
| 5962-9167703MXA | | 09/25/1992 | 3 | QP SEMI | | Y | CY7C460A-30DMB | 670 |
| 5962-9167703MYA | | 09/25/1992 | 1 | IDT | | Y | IDT7205L30TDB | 670 |
| 5962-9167703MYA | | 09/25/1992 | 3 | QP SEMI | | Y | CY7C460A-30/MYA | 670 |
| 5962-9167703MZA | | 09/25/1992 | 1 | IDT | | Y | IDT7205L30LB | 670 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9167703MZA | | 09/25/1992 | 3 | QP SEMI | | Y | CY7C460A-30LMB | 670 |
| 5962-9168201MXA | | 08/05/1993 | | (NONE) | | | 29C010 (GEN) | 669 |
| 5962-9168201MYA | | 08/05/1993 | | (NONE) | | | 29C010 (GEN) | 669 |
| 5962-9168202MXA | | 08/05/1993 | | (NONE) | | | 29C010 (GEN) | 669 |
| 5962-9168202MYA | | 08/05/1993 | | (NONE) | | | 29C010 (GEN) | 669 |
| 5962-9168203MXA | | 08/05/1993 | | (NONE) | | | 29C010 (GEN) | 669 |
| 5962-9168203MYA | | 08/05/1993 | | (NONE) | | | 29C010 (GEN) | 669 |
| 5962-9168701HXA | D | 08/27/2002 | 1 | NATIONAL HYB | | Y | NHI-1553RT | 590 |
| 5962-9168701HXC | D | 08/27/2002 | 1 | NATIONAL HYB | | Y | NHI-1553RT | 590 |
| 5962-9168701HYA | D | 08/27/2002 | 1 | NATIONAL HYB | | Y | NHI-1553RTFP | 590 |
| 5962-9168701HYC | D | 08/27/2002 | 1 | NATIONAL HYB | | Y | NHI-1553RTFP | 590 |
| 5962-9168702HXA | D | 08/27/2002 | 1 | NATIONAL HYB | | Y | NHI-1554RT | 590 |
| 5962-9168702HXC | D | 08/27/2002 | 1 | NATIONAL HYB | | Y | NHI-1554RT | 590 |
| 5962-9168702HYA | D | 08/27/2002 | 1 | NATIONAL HYB | | Y | NHI-1554RTFP | 590 |
| 5962-9168702HYC | D | 08/27/2002 | 1 | NATIONAL HYB | | Y | NHI-1554RTFP | 590 |
| 5962-9168703HUA | D | 08/27/2002 | 1 | NATIONAL HYB | | Y | NHI-1561RTFP | 590 |
| 5962-9168703HUC | D | 08/27/2002 | 1 | NATIONAL HYB | | Y | NHI-1561RTFP | 590 |
| 5962-9168703HZA | D | 08/27/2002 | 1 | NATIONAL HYB | | Y | NHI-1561RT | 590 |
| 5962-9168703HZC | D | 08/27/2002 | 1 | NATIONAL HYB | | Y | NHI-1561RT | 590 |
| 5962-9168704HUA | D | 08/27/2002 | 1 | NATIONAL HYB | | Y | NHI-1562RTFP | 590 |
| 5962-9168704HUC | D | 08/27/2002 | 1 | NATIONAL HYB | | Y | NHI-1562RTFP | 590 |
| 5962-9168704HZA | D | 08/27/2002 | 1 | NATIONAL HYB | | Y | NHI-1562RT | 590 |
| 5962-9168704HZC | D | 08/27/2002 | 1 | NATIONAL HYB | | Y | NHI-1562RT | 590 |
| 5962-9168705HXA | D | 08/27/2002 | 1 | NATIONAL HYB | | Y | NHI-1572RT | 590 |
| 5962-9168705HXC | D | 08/27/2002 | 1 | NATIONAL HYB | | Y | NHI-1572RT | 590 |
| 5962-9168705HYA | D | 08/27/2002 | 1 | NATIONAL HYB | | Y | NHI-1572RT | 590 |
| 5962-9168705HYC | D | 08/27/2002 | 1 | NATIONAL HYB | | Y | NHI-1572RT | 590 |
| 5962-9168706HXA | D | 08/27/2002 | 1 | NATIONAL HYB | | Y | NHI-1576RT | 590 |
| 5962-9168706HXC | D | 08/27/2002 | 1 | NATIONAL HYB | | Y | NHI-1576RT | 590 |
| 5962-9168706HYA | D | 08/27/2002 | 1 | NATIONAL HYB | | Y | NHI-1576RT | 590 |
| 5962-9168706HYC | D | 08/27/2002 | 1 | NATIONAL HYB | | Y | NHI-1576RT | 590 |
| 5962-9168707HUA | D | 08/27/2002 | 1 | NATIONAL HYB | | Y | NHI-1591RTFP | 590 |
| 5962-9168707HUC | D | 08/27/2002 | 1 | NATIONAL HYB | | Y | NHI-1591RTFP | 590 |
| 5962-9168707HZA | D | 08/27/2002 | 1 | NATIONAL HYB | | Y | NHI-1591RT | 590 |
| 5962-9168707HZC | D | 08/27/2002 | 1 | NATIONAL HYB | | Y | NHI-1591RT | 590 |
| 5962-9168708HUA | D | 08/27/2002 | 1 | NATIONAL HYB | | Y | NHI-1592RTFP | 590 |
| 5962-9168708HUC | D | 08/27/2002 | 1 | NATIONAL HYB | | Y | NHI-1592RTFP | 590 |
| 5962-9168708HZA | D | 08/27/2002 | 1 | NATIONAL HYB | | Y | NHI-1592RT | 590 |
| 5962-9168708HZC | D | 08/27/2002 | 1 | NATIONAL HYB | | Y | NHI-1592RT | 590 |
| 5962-9168709HUA | D | 08/27/2002 | 1 | NATIONAL HYB | | Y | NHI-15101RTFP | 590 |
| 5962-9168709HUC | D | 08/27/2002 | 1 | NATIONAL HYB | | Y | NHI-15101RTFP | 590 |
| 5962-9168709HZA | D | 08/27/2002 | 1 | NATIONAL HYB | | Y | NHI-15101RT | 590 |
| 5962-9168709HZC | D | 08/27/2002 | 1 | NATIONAL HYB | | Y | NHI-15101RT | 590 |
| 5962-9168710HUA | D | 08/27/2002 | 1 | NATIONAL HYB | | Y | NHI-15102RTFP | 590 |
| 5962-9168710HUC | D | 08/27/2002 | 1 | NATIONAL HYB | | Y | NHI-15102RTFP | 590 |
| 5962-9168710HZA | D | 08/27/2002 | 1 | NATIONAL HYB | | Y | NHI-15102RT | 590 |
| 5962-9168710HZC | D | 08/27/2002 | 1 | NATIONAL HYB | | Y | NHI-15102RT | 590 |
| 5962-9168901MXA | A | 10/23/2000 | | (NONE) | 12/31/2001 | | UC1625 (GEN) | 899 |
| 5962-9169001M3A | E | 10/31/2002 | | (NONE) | | | 674ZA (GEN) | 592 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9169001MXC | E | 10/31/2002 | | (NONE) | | | 674ZA (GEN) | 592 |
| 5962-9169002M3A | E | 10/31/2002 | | (NONE) | | | 674ZB (GEN) | 592 |
| 5962-9169002MXC | E | 10/31/2002 | | (NONE) | | | 674ZB (GEN) | 592 |
| 5962-9169003M3A | E | 10/31/2002 | 1 | ANALOG (2) | | Y | AD674BTE/883B | 592 |
| 5962-9169003MXA | E | 10/31/2002 | 1 | ANALOG (2) | | Y | AD674BTD/883 | 592 |
| 5962-9169004M3C | E | 10/31/2002 | | (NONE) | | | SP674AT (GEN) | 592 |
| 5962-9169004MXC | E | 10/31/2002 | | (NONE) | | | SP674AT (GEN) | 592 |
| 5962-9169005M3A | E | 10/31/2002 | 1 | ANALOG (2) | | Y | AD674BTE/883B | 592 |
| 5962-9169101M3A | A | 07/03/2002 | 1 | MAXWELL | | Y | SEI5101A-SE8B | 592 |
| 5962-9169101Q3C | A | 07/03/2002 | 1 | MAXWELL | | Y | SEI5101A-SE8B | 592 |
| 5962-9169101MXA | A | 07/03/2002 | 1 | MAXWELL | | Y | SEI5101A-SD8B | 592 |
| 5962-9169101QXC | A | 07/03/2002 | 1 | MAXWELL | | Y | SEI5101A-SD8B | 592 |
| 5962-9169102M3A | A | 07/03/2002 | 1 | MAXWELL | | Y | SEI5101A-TE8B | 592 |
| 5962-9169102Q3C | A | 07/03/2002 | 1 | MAXWELL | | Y | SEI5101A-TE8B | 592 |
| 5962-9169102MXA | A | 07/03/2002 | 1 | MAXWELL | | Y | SEI5101A-TD8B | 592 |
| 5962-9169102QXC | A | 07/03/2002 | 1 | MAXWELL | | Y | SEI5101A-TD8B | 592 |
| 5962-9169201M3A | A | 04/18/2002 | 1 | MAXWELL | | Y | SEI5102A-SEB | 592 |
| 5962-9169201Q3C | A | 04/18/2002 | 1 | MAXWELL | | Y | SEI5102A-SEB | 592 |
| 5962-9169201MXA | A | 04/18/2002 | 1 | MAXWELL | | Y | SEI5102A-SDB | 592 |
| 5962-9169201QXC | A | 04/18/2002 | 1 | MAXWELL | | Y | SEI5102A-SDB | 592 |
| 5962-9169202M3A | A | 04/18/2002 | 1 | MAXWELL | | Y | SEI5102A-TEB | 592 |
| 5962-9169202Q3C | A | 04/18/2002 | 1 | MAXWELL | | Y | SEI5102A-TEB | 592 |
| 5962-9169202MXA | A | 04/18/2002 | 1 | MAXWELL | | Y | SEI5102A-TDB | 592 |
| 5962-9169202QXC | A | 04/18/2002 | 1 | MAXWELL | | Y | SEI5102A-TDB | 592 |
| 5962-9169301M2A | C | 05/04/2001 | | (NONE) | 03/04/2003 | | CLC414A (GEN) | 713 |
| 5962-9169301MCA | C | 05/04/2001 | | (NONE) | 03/04/2003 | | CLC414A (GEN) | 713 |
| 5962-9169401M2A | D | 12/08/1997 | | (NONE) | | | CLC520A (GEN) | 751 |
| 5962-9169401MCA | D | 12/08/1997 | 1 | NATIONAL | | Y | CLC520AJ-QML | 751 |
| 5962-9169501M3A | | 01/15/1992 | | (NONE) | 08/04/1995 | | PALCE610H-20 (GEN) | 431 |
| 5962-9169501MLA | | 01/15/1992 | | (NONE) | 08/04/1995 | | PALCE610H-20 (GEN) | 431 |
| 5962-9169601M3C | A | 04/19/1996 | | (NONE) | 04/01/2000 | | 29C525-25 (GEN) | 249 |
| 5962-9169601MUA | A | 04/19/1996 | | (NONE) | | | 29C525-25 (GEN) | 249 |
| 5962-9169601MXC | A | 04/19/1996 | | (NONE) | 04/01/2000 | | 29C525-25 (GEN) | 249 |
| 5962-9169601MYA | A | 04/19/1996 | | (NONE) | 04/01/2000 | | 29C525-25 (GEN) | 249 |
| 5962-9169602M3C | A | 04/19/1996 | | (NONE) | 04/01/2000 | | 29C525-20 (GEN) | 249 |
| 5962-9169602MUA | A | 04/19/1996 | | (NONE) | | | 29C525-20 (GEN) | 249 |
| 5962-9169602MXC | A | 04/19/1996 | | (NONE) | 04/01/2000 | | 29C525-20 (GEN) | 249 |
| 5962-9169602MYA | A | 04/19/1996 | | (NONE) | 04/01/2000 | | 29C525-20 (GEN) | 249 |
| 5962-9169701M4A | D | 06/06/2003 | 3 | QP SEMI | | Y | 87C51RC/B4A | 420 |
| 5962-9169701MMA | D | 06/06/2003 | 3 | QP SEMI | | Y | 87C51RC/BMA | 420 |
| 5962-9169701NNA | D | 06/06/2003 | | (NONE) | | | 87C51FC (GEN) | 420 |
| 5962-9169701MTA | D | 06/06/2003 | | (NONE) | 04/15/1996 | | 87C51FC (GEN) | 420 |
| 5962-9169701MUA | D | 06/06/2003 | | (NONE) | 12/24/1997 | | 87C51FC (GEN) | 420 |
| 5962-9169701MXA | D | 06/06/2003 | 3 | QP SEMI | | Y | 87C51RC/BQA | 420 |
| 5962-9169701NYA | D | 06/06/2003 | | (NONE) | | | 87C51FC (GEN) | 420 |
| 5962-9169701MZA | D | 06/06/2003 | | (NONE) | 04/15/1996 | | 87C51FC (GEN) | 420 |
| 5962-9169702M4A | D | 06/06/2003 | 3 | QP SEMI | | Y | 87C51RC-16/B4A | 420 |
| 5962-9169702MMA | D | 06/06/2003 | 3 | QP SEMI | | Y | 87C51RC-16/BMA | 420 |
| 5962-9169702NNA | D | 06/06/2003 | | (NONE) | | | 87C51FC-16 (GEN) | 420 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9169702MTA | D | 06/06/2003 | | (NONE) | 04/15/1996 | | 87C51FC-16 (GEN) | 420 |
| 5962-9169702MUA | D | 06/06/2003 | | (NONE) | 12/24/1997 | | 87C51FC-16 (GEN) | 420 |
| 5962-9169702MXA | D | 06/06/2003 | 3 | QP SEMI | | Y | 87C51RC-16/BQA | 420 |
| 5962-9169702NYA | D | 06/06/2003 | | (NONE) | | | 87C51FC-16 (GEN) | 420 |
| 5962-9169702MZA | D | 06/06/2003 | | (NONE) | 04/15/1996 | | 87C51FC-16 (GEN) | 420 |
| 5962-9169703NNA | D | 06/06/2003 | | (NONE) | | | 87C51FC (GEN) | 420 |
| 5962-9169703NYA | D | 06/06/2003 | | (NONE) | | | 87C51FC (GEN) | 420 |
| 5962-9169704NNA | D | 06/06/2003 | | (NONE) | | | 87C51FC-16 (GEN) | 420 |
| 5962-9169704NYA | D | 06/06/2003 | | (NONE) | | | 87C51FC-16 (GEN) | 420 |
| 5962-9170001HXA | B | 04/21/2004 | 1 | APEX MICRO. | | Y | PA09M/883 | 724 |
| 5962-9170001HXC | B | 04/21/2004 | 1 | APEX MICRO. | | Y | PA09M/883 | 724 |
| 5962-9171201HXA | | 03/10/1992 | | (NONE) | | | AD1385T (GEN) | 592 |
| 5962-9171601M2A | | 05/18/1994 | | (NONE) | 09/30/1995 | | 54F803 (GEN) | 159 |
| 5962-9171601MCA | | 05/18/1994 | | (NONE) | 09/30/1995 | | 54F803 (GEN) | 159 |
| 5962-9171601MDA | | 05/18/1994 | | (NONE) | 09/30/1995 | | 54F803 (GEN) | 159 |
| 5962-9172201M2A | C | 07/18/2002 | 3 | NATIONAL | | Y | 54ACT161LMQB | 304 |
| 5962R9172201M2A | C | 07/18/2002 | 3 | NATIONAL | | Y | 54ACT161LMQB-RH | 304 |
| 5962R9172201V2A | C | 07/18/2002 | 3 | NATIONAL | | Y | 54ACT161ERQMLV | 304 |
| 5962-9172201MEA | C | 07/18/2002 | 3 | NATIONAL | | Y | 54ACT161DMQB | 304 |
| 5962R9172201MEA | C | 07/18/2002 | 3 | NATIONAL | | Y | 54ACT161DMQB-RH | 304 |
| 5962R9172201VEA | C | 07/18/2002 | 3 | NATIONAL | | Y | 54ACT161JRQMLV | 304 |
| 5962-9172201MFA | C | 07/18/2002 | 3 | NATIONAL | | Y | 54ACT161FMQB | 304 |
| 5962R9172201MFA | C | 07/18/2002 | 3 | NATIONAL | | Y | 54ACT161FMQB-RH | 304 |
| 5962R9172201VFA | C | 07/18/2002 | 3 | NATIONAL | | Y | 54ACT161WRQMLV | 304 |
| 5962R9172201VZA | C | 07/18/2002 | 3 | NATIONAL | | Y | 54ACT161WGRQMLV | 304 |
| 5962-9172202QXA | C | 07/18/2002 | 2 | STMICRO | | Y | 54ACT161K02Q | 304 |
| 5962-9172202QXC | C | 07/18/2002 | 2 | STMICRO | | Y | 54ACT161K01Q | 304 |
| 5962-9172202VXA | C | 07/18/2002 | 2 | STMICRO | | Y | 54ACT161K02V | 304 |
| 5962-9172202VXC | C | 07/18/2002 | 2 | STMICRO | | Y | 54ACT161K01V | 304 |
| 5962-9172301M2A | B | 03/07/2003 | 3 | NATIONAL | | Y | 54ACT163LMQB | 304 |
| 5962R9172301M2A | B | 03/07/2003 | 3 | NATIONAL | | Y | 54ACT163LMQB-RH | 304 |
| 5962R9172301V2A | B | 03/07/2003 | 3 | NATIONAL | | Y | 54ACT163ERQMLV | 304 |
| 5962-9172301MEA | B | 03/07/2003 | 3 | NATIONAL | | Y | 54ACT163DMQB | 304 |
| 5962R9172301MEA | B | 03/07/2003 | 3 | NATIONAL | | Y | 54ACT163DMQB-RH | 304 |
| 5962R9172301VEA | B | 03/07/2003 | 3 | NATIONAL | | Y | 54ACT163JRQMLV | 304 |
| 5962-9172301MFA | B | 03/07/2003 | 3 | NATIONAL | | Y | 54ACT163FMQB | 304 |
| 5962R9172301MFA | B | 03/07/2003 | 3 | NATIONAL | | Y | 54ACT163FMQB-RH | 304 |
| 5962R9172301VFA | B | 03/07/2003 | 3 | NATIONAL | | Y | 54ACT163WRQMLV | 304 |
| 5962-9172302QXA | B | 03/07/2003 | 2 | STMICRO | | Y | 54ACT163K02Q | 304 |
| 5962-9172302QXC | B | 03/07/2003 | 2 | STMICRO | | Y | 54ACT163K01Q | 304 |
| 5962-9172302VXA | B | 03/07/2003 | 2 | STMICRO | | Y | 54ACT163K02V | 304 |
| 5962-9172302VXC | B | 03/07/2003 | 2 | STMICRO | | Y | 54ACT163K01V | 304 |
| 5962-9172401M3A | | 11/18/1993 | 1 | ROCHESTER | | | 54BCT648/B3A | 590 |
| 5962-9172401MKA | | 11/18/1993 | 1 | ROCHESTER | | | 54BCT648/BKA | 590 |
| 5962-9172401MLA | | 11/18/1993 | 1 | ROCHESTER | | | 54BCT648/BLA | 590 |
| 5962-9172501M3A | | 01/06/1994 | 2 | TI | | Y | SNJ54BCT8373AFK | 399 |
| 5962-9172501MLA | | 01/06/1994 | 2 | TI | | Y | SNJ54BCT8373AJT | 399 |
| 5962-9172601M3A | | 01/06/1994 | 2 | TI | | Y | SNJ54BCT8244AFK | 399 |
| 5962-9172601MLA | | 01/06/1994 | 2 | TI | | Y | SNJ54BCT8244AJT | 399 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9172701M3A | A | 05/02/1994 | | (NONE) | | | 54BCT8374A (GEN) | 399 |
| 5962-9172701Q3A | A | 05/02/1994 | 2 | TI | | Y | SNJ54BCT8374AFK | 399 |
| 5962-9172701MLA | A | 05/02/1994 | | (NONE) | | | 54BCT8374A (GEN) | 399 |
| 5962-9172701QLA | A | 05/02/1994 | 2 | TI | | Y | SNJ54BCT8374AJT | 399 |
| 5962-9172801M3A | A | 05/02/1994 | | (NONE) | | | 54BCT8245A (GEN) | 399 |
| 5962-9172801Q3A | A | 05/02/1994 | 2 | TI | | Y | SNJ54BCT8245AFK | 399 |
| 5962-9172801MLA | A | 05/02/1994 | | (NONE) | | | 54BCT8245A (GEN) | 399 |
| 5962-9172801QLA | A | 05/02/1994 | 2 | TI | | Y | SNJ54BCT8245AJT | 399 |
| 5962-9172901MVA | A | 11/09/1993 | | (NONE) | 03/30/2001 | | LT1180 (GEN) | 590 |
| 5962-9172902MEA | A | 11/09/1993 | 1 | MINCO | | Y | MTL1181MD16 | 590 |
| 5962-9172903MVA | A | 11/09/1993 | | (NONE) | 03/30/2001 | | LT1280 (GEN) | 590 |
| 5962-9172904MEA | A | 11/09/1993 | | (NONE) | 03/30/2001 | | LT1281 (GEN) | 590 |
| 5962-9173201M2A | | 03/31/1993 | | (NONE) | | | 54HCT137 (GEN) | 282 |
| 5962-9173201MEA | | 03/31/1993 | | (NONE) | | | 54HCT137 (GEN) | 282 |
| 5962-9173401HXA | B | 04/27/1995 | | (NONE) | | | BUS61559 (GEN) | 899 |
| 5962-9173401HYA | B | 04/27/1995 | | (NONE) | | | BUS61569 (GEN) | 899 |
| 5962-9173401HZA | B | 04/27/1995 | | (NONE) | | | BUS61569 (GEN) | 899 |
| 5962-9173402HXA | B | 04/27/1995 | | (NONE) | | | BUS61560 (GEN) | 899 |
| 5962-9173402HYA | B | 04/27/1995 | | (NONE) | | | BUS61570 (GEN) | 899 |
| 5962-9173402HZA | B | 04/27/1995 | | (NONE) | | | BUS61570 (GEN) | 899 |
| 5962-9173403HXA | B | 04/27/1995 | | (NONE) | | | BUS61561 (GEN) | 899 |
| 5962-9173403HYA | B | 04/27/1995 | | (NONE) | | | BUS61571 (GEN) | 899 |
| 5962-9173403HZA | B | 04/27/1995 | | (NONE) | | | BUS61571 (GEN) | 899 |
| 5962-9173404HXA | B | 04/27/1995 | | (NONE) | | | BUS61559 (GEN) | 899 |
| 5962-9173404HYA | B | 04/27/1995 | | (NONE) | | | BUS61569 (GEN) | 899 |
| 5962-9173404HZA | B | 04/27/1995 | | (NONE) | | | BUS61569 (GEN) | 899 |
| 5962-9173601HXA | C | 02/27/2004 | 1 | DDC | | Y | SDC14600-112 | 594 |
| 5962-9173601HXA | C | 02/27/2004 | 1 | DDC IRELAND | | Y | SDC14600-112 | 594 |
| 5962-9173601HXC | C | 02/27/2004 | 1 | DDC | | Y | SDC14600-112 | 594 |
| 5962-9173601HXC | C | 02/27/2004 | 1 | DDC IRELAND | | Y | SDC14600-112 | 594 |
| 5962-9173602HXA | C | 02/27/2004 | 1 | DDC | | Y | SDC14600T-112 | 594 |
| 5962-9173602HXA | C | 02/27/2004 | 1 | DDC IRELAND | | Y | SDC14600T-112 | 594 |
| 5962-9173602HXC | C | 02/27/2004 | 1 | DDC | | Y | SDC14600T-112 | 594 |
| 5962-9173602HXC | C | 02/27/2004 | 1 | DDC IRELAND | | Y | SDC14600T-112 | 594 |
| 5962-9173603HXA | C | 02/27/2004 | 1 | DDC | | Y | SDC14601-112 | 594 |
| 5962-9173603HXA | C | 02/27/2004 | 1 | DDC IRELAND | | Y | SDC14601-112 | 594 |
| 5962-9173603HXC | C | 02/27/2004 | 1 | DDC | | Y | SDC14601-112 | 594 |
| 5962-9173603HXC | C | 02/27/2004 | 1 | DDC IRELAND | | Y | SDC14601-112 | 594 |
| 5962-9173604HXA | C | 02/27/2004 | 1 | DDC | | Y | SDC14601T-112 | 594 |
| 5962-9173604HXA | C | 02/27/2004 | 1 | DDC IRELAND | | Y | SDC14601T-112 | 594 |
| 5962-9173604HXC | C | 02/27/2004 | 1 | DDC | | Y | SDC14601T-112 | 594 |
| 5962-9173604HXC | C | 02/27/2004 | 1 | DDC IRELAND | | Y | SDC14601T-112 | 594 |
| 5962-9173605HXA | C | 02/27/2004 | 1 | DDC | | Y | SDC14605-112 | 594 |
| 5962-9173605HXA | C | 02/27/2004 | 1 | DDC IRELAND | | Y | SDC14605-112 | 594 |
| 5962-9173605HXC | C | 02/27/2004 | 1 | DDC | | Y | SDC14605-112 | 594 |
| 5962-9173605HXC | C | 02/27/2004 | 1 | DDC IRELAND | | Y | SDC14605-112 | 594 |
| 5962-9173606HXA | C | 02/27/2004 | 1 | DDC | | Y | SDC14605T-112 | 594 |
| 5962-9173606HXA | C | 02/27/2004 | 1 | DDC IRELAND | | Y | SDC14605T-112 | 594 |
| 5962-9173606HXC | C | 02/27/2004 | 1 | DDC | | Y | SDC14605T-112 | 594 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9173606HXC | C | 02/27/2004 | 1 | DDC IRELAND | | Y | SDC14605T-112 | 594 |
| 5962-9173607HXA | C | 02/27/2004 | 1 | DDC | | Y | SDC14606-112 | 594 |
| 5962-9173607HXA | C | 02/27/2004 | 1 | DDC IRELAND | | Y | SDC14606-112 | 594 |
| 5962-9173607HXC | C | 02/27/2004 | 1 | DDC | | Y | SDC14606-112 | 594 |
| 5962-9173607HXC | C | 02/27/2004 | 1 | DDC IRELAND | | Y | SDC14606-112 | 594 |
| 5962-9173608HXA | C | 02/27/2004 | 1 | DDC | | Y | SDC14606T-112 | 594 |
| 5962-9173608HXA | C | 02/27/2004 | 1 | DDC IRELAND | | Y | SDC14606T-112 | 594 |
| 5962-9173608HXC | C | 02/27/2004 | 1 | DDC | | Y | SDC14606T-112 | 594 |
| 5962-9173608HXC | C | 02/27/2004 | 1 | DDC IRELAND | | Y | SDC14606T-112 | 594 |
| 5962-9173609HXA | C | 02/27/2004 | 1 | DDC | | Y | SDC14605-114 | 594 |
| 5962-9173609HXA | C | 02/27/2004 | 1 | DDC IRELAND | | Y | SDC14605-114 | 594 |
| 5962-9173609HXC | C | 02/27/2004 | 1 | DDC | | Y | SDC14605-114 | 594 |
| 5962-9173609HXC | C | 02/27/2004 | 1 | DDC IRELAND | | Y | SDC14605-114 | 594 |
| 5962-9173610HXA | C | 02/27/2004 | 1 | DDC | | Y | SDC14605T-114 | 594 |
| 5962-9173610HXA | C | 02/27/2004 | 1 | DDC IRELAND | | Y | SDC14605T-114 | 594 |
| 5962-9173610HXC | C | 02/27/2004 | 1 | DDC | | Y | SDC14605T-114 | 594 |
| 5962-9173610HXC | C | 02/27/2004 | 1 | DDC IRELAND | | Y | SDC14605T-114 | 594 |
| 5962-9173611HXA | C | 02/27/2004 | 1 | DDC | | Y | SDC14606-114 | 594 |
| 5962-9173611HXA | C | 02/27/2004 | 1 | DDC IRELAND | | Y | SDC14606-114 | 594 |
| 5962-9173611HXC | C | 02/27/2004 | 1 | DDC | | Y | SDC14606-114 | 594 |
| 5962-9173611HXC | C | 02/27/2004 | 1 | DDC IRELAND | | Y | SDC14606-114 | 594 |
| 5962-9173612HXA | C | 02/27/2004 | 1 | DDC | | Y | SDC14606T-114 | 594 |
| 5962-9173612HXA | C | 02/27/2004 | 1 | DDC IRELAND | | Y | SDC14606T-114 | 594 |
| 5962-9173612HXC | C | 02/27/2004 | 1 | DDC | | Y | SDC14606T-114 | 594 |
| 5962-9173612HXC | C | 02/27/2004 | 1 | DDC IRELAND | | Y | SDC14606T-114 | 594 |
| 5962-9173613HXA | C | 02/27/2004 | 1 | DDC | | Y | SDC14601-603 | 594 |
| 5962-9173613HXA | C | 02/27/2004 | 1 | DDC IRELAND | | Y | SDC14601-603 | 594 |
| 5962-9173613HXC | C | 02/27/2004 | 1 | DDC | | Y | SDC14601-603 | 594 |
| 5962-9173613HXC | C | 02/27/2004 | 1 | DDC IRELAND | | Y | SDC14601-603 | 594 |
| 5962-9173801M2A | | 11/15/1993 | 3 | NATIONAL | | Y | 54F573LMQB | 341 |
| 5962-9173801MRA | | 11/15/1993 | 3 | NATIONAL | | Y | 54F573DMQB | 341 |
| 5962-9173801MSA | | 11/15/1993 | | (NONE) | 09/09/1998 | | 54F573 (GEN) | 341 |
| 5962-9174001MRA | | 10/15/1992 | | (NONE) | 06/30/1995 | | 7636AT (GEN) | 591 |
| 5962-9174002MRA | | 10/15/1992 | | (NONE) | 06/30/1995 | | 7636AS (GEN) | 591 |
| 5962-9174301M2A | C | 11/07/2000 | 1 | NATIONAL | | Y | CLC502AE-QML | 739 |
| 5962-9174301MPA | C | 11/07/2000 | 1 | NATIONAL | | Y | CLC502AJ-QML | 739 |
| 5962-9174401MXA | A | 03/07/2001 | 2 | QP SEMI | | Y | CY7C277-50WMB | 662 |
| 5962-9174401MYA | A | 03/07/2001 | 2 | QP SEMI | | Y | CY7C277-50QMB | 662 |
| 5962-9174401MZA | A | 03/07/2001 | 2 | QP SEMI | | Y | CY7C277-50TMB | 662 |
| 5962-9174402MXA | A | 03/07/2001 | 2 | CYPRESS | | Y | CY7C277-40WMB | 662 |
| 5962-9174402MYA | A | 03/07/2001 | 2 | QP SEMI | | Y | CY7C277-40QMB | 662 |
| 5962-9174402MZA | A | 03/07/2001 | 2 | QP SEMI | | Y | CY7C277-40TMB | 662 |
| 5962-9174601Q3A | | 06/10/1994 | | TI | | Y | SNJ54BCT8240AFK | 399 |
| 5962-9174601QLA | | 06/10/1994 | | TI | | Y | SNJ54BCT8240AJT | 399 |
| 5962-9174801MJA | A | 11/01/1995 | | (NONE) | | | 1018A (GEN) | 591 |
| 5962-9174802MJA | A | 11/01/1995 | | (NONE) | | | 1018B (GEN) | 591 |
| 5962-9174901HXA | B | 03/25/2004 | 1 | NATIONAL HYB | | Y | NHI-1514 | 590 |
| 5962-9174901HXC | B | 03/25/2004 | 1 | NATIONAL HYB | | Y | NHI-1514 | 590 |
| 5962-9174901HYA | B | 03/25/2004 | 1 | NATIONAL HYB | | Y | NHI-1514FP | 590 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9174901HYC | B | 03/25/2004 | 1 | NATIONAL HYB | | Y | NHI-1514FP | 590 |
| 5962-9174902HXA | B | 03/25/2004 | 1 | NATIONAL HYB | | Y | NHI-1513 | 590 |
| 5962-9174902HXC | B | 03/25/2004 | 1 | NATIONAL HYB | | Y | NHI-1513 | 590 |
| 5962-9174902HYA | B | 03/25/2004 | 1 | NATIONAL HYB | | Y | NHI-1513FP | 590 |
| 5962-9174902HYC | B | 03/25/2004 | 1 | NATIONAL HYB | | Y | NHI-1513FP | 590 |
| 5962-9174903HXA | B | 03/25/2004 | 1 | DDC | | Y | BUS-63102II-140 | 590 |
| 5962-9174903HXA | B | 03/25/2004 | 1 | DDC | | Y | BUS-63102II-150 | 590 |
| 5962-9174903HXA | B | 03/25/2004 | 1 | DDC IRELAND | | Y | BUS-63102II-140 | 590 |
| 5962-9174903HXA | B | 03/25/2004 | 1 | DDC IRELAND | | Y | BUS-63102II-150 | 590 |
| 5962-9174903HXC | B | 03/25/2004 | 1 | DDC | | Y | BUS-63102II-110 | 590 |
| 5962-9174903HXC | B | 03/25/2004 | 1 | DDC | | Y | BUS-63102II-130 | 590 |
| 5962-9174903HXC | B | 03/25/2004 | 1 | DDC IRELAND | | Y | BUS-63102II-110 | 590 |
| 5962-9174903HXC | B | 03/25/2004 | 1 | DDC IRELAND | | Y | BUS-63102II-130 | 590 |
| 5962-9174903HYA | B | 03/25/2004 | | (NONE) | | | BUS63102II (GEN) | 590 |
| 5962-9174904HXA | B | 03/25/2004 | | (NONE) | | | BUS63104II (GEN) | 590 |
| 5962-9174904HYA | B | 03/25/2004 | | (NONE) | | | BUS63104II (GEN) | 590 |
| 5962-9174905HUA | B | 03/25/2004 | | (NONE) | | | 3231 (GEN) | 590 |
| 5962-9174905HZA | B | 03/25/2004 | | (NONE) | | | 3231 (GEN) | 590 |
| 5962-9174906HUA | B | 03/25/2004 | | (NONE) | | | 3232 (GEN) | 590 |
| 5962-9174906HZA | B | 03/25/2004 | | (NONE) | | | 3232 (GEN) | 590 |
| 5962-9174907HUA | B | 03/25/2004 | | (NONE) | | | 3232 (GEN) | 590 |
| 5962-9174907HZA | B | 03/25/2004 | | (NONE) | | | 3232 (GEN) | 590 |
| 5962-9174908HTA | B | 03/25/2004 | 1 | AEROFLEX | | Y | ARX4407LPFP | 590 |
| 5962-9174908HTA | B | 03/25/2004 | 1 | NATIONAL HYB | | Y | NHI-1514FP/883 | 590 |
| 5962-9174908HTC | B | 03/25/2004 | 1 | AEROFLEX | | Y | ARX4407LPFP | 590 |
| 5962-9174908HTC | B | 03/25/2004 | 1 | NATIONAL HYB | | Y | NHI-1514FP/883 | 590 |
| 5962-9174908HXA | B | 03/25/2004 | 1 | AEROFLEX | | Y | ARX4407 | 590 |
| 5962-9174908HXA | B | 03/25/2004 | 1 | NATIONAL HYB | | Y | NHI-1514/883 | 590 |
| 5962-9174908HXC | B | 03/25/2004 | 1 | AEROFLEX | | Y | ARX4407 | 590 |
| 5962-9174908HXC | B | 03/25/2004 | 1 | NATIONAL HYB | | Y | NHI-1514/883 | 590 |
| 5962-9174908HYA | B | 03/25/2004 | 1 | AEROFLEX | | Y | ARX4407FP | 590 |
| 5962-9174908HYA | B | 03/25/2004 | 1 | NATIONAL HYB | | Y | NHI-1514FP/883 | 590 |
| 5962-9174908HYC | B | 03/25/2004 | 1 | AEROFLEX | | Y | ARX4407FP | 590 |
| 5962-9174908HYC | B | 03/25/2004 | 1 | NATIONAL HYB | | Y | NHI-1514FP/883 | 590 |
| 5962-9174909HTA | B | 03/25/2004 | 1 | AEROFLEX | | Y | ARX4404LPFP | 590 |
| 5962-9174909HTA | B | 03/25/2004 | 1 | NATIONAL HYB | | Y | NHI-1513FP/883 | 590 |
| 5962-9174909HTC | B | 03/25/2004 | 1 | AEROFLEX | | Y | ARX4404LPFP | 590 |
| 5962-9174909HTC | B | 03/25/2004 | 1 | NATIONAL HYB | | Y | NHI-1513FP/883 | 590 |
| 5962-9174909HXA | B | 03/25/2004 | 1 | AEROFLEX | | Y | ARX4404 | 590 |
| 5962-9174909HXA | B | 03/25/2004 | 1 | NATIONAL HYB | | Y | NHI-1513/883 | 590 |
| 5962-9174909HXC | B | 03/25/2004 | 1 | AEROFLEX | | Y | ARX4404 | 590 |
| 5962-9174909HXC | B | 03/25/2004 | 1 | NATIONAL HYB | | Y | NHI-1513/883 | 590 |
| 5962-9174909HYA | B | 03/25/2004 | 1 | AEROFLEX | | Y | ARX4404FP | 590 |
| 5962-9174909HYA | B | 03/25/2004 | 1 | NATIONAL HYB | | Y | NHI-1513FP/883 | 590 |
| 5962-9174909HYC | B | 03/25/2004 | 1 | AEROFLEX | | Y | ARX4404FP | 590 |
| 5962-9174909HYC | B | 03/25/2004 | 1 | NATIONAL HYB | | Y | NHI-1513FP/883 | 590 |
| 5962-9175201MXA | A | 03/09/2001 | | (NONE) | 08/02/1996 | | 27C040-250 (GEN) | 669 |
| 5962-9175201MYA | A | 03/09/2001 | | (NONE) | 08/02/1996 | | 27C040-250 (GEN) | 669 |
| 5962-9175202MXA | A | 03/09/2001 | | (NONE) | 08/02/1996 | | 27C040-200 (GEN) | 669 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9175202MYA | A | 03/09/2001 | | (NONE) | 08/02/1996 | | 27C040-200 (GEN) | 669 |
| 5962-9175203MXA | A | 03/09/2001 | | (NONE) | 10/27/1995 | | 27C040-17 (GEN) | 669 |
| 5962-9175203MYA | A | 03/09/2001 | | (NONE) | 10/27/1995 | | 27C040-17 (GEN) | 669 |
| 5962-9175204MXA | A | 03/09/2001 | 2 | AUSTIN SEMI. | | Y | SMJ27C040-15JM | 669 |
| 5962-9175204MYA | A | 03/09/2001 | | (NONE) | 08/02/1996 | | 27C040-150 (GEN) | 669 |
| 5962-9175205MXA | A | 03/09/2001 | 2 | AUSTIN SEMI. | | Y | SMJ27C040-12JM | 669 |
| 5962-9175205MYA | A | 03/09/2001 | | (NONE) | 10/27/1995 | | 27C040-12 (GEN) | 669 |
| 5962-9175301M2A | | 10/30/1992 | | TI | | Y | SNJ54F541FK | 529 |
| 5962-9175301MRA | | 10/30/1992 | | TI | | Y | SNJ54F541J | 529 |
| 5962-9175301MSA | | 10/30/1992 | | TI | | Y | SNJ54F541W | 529 |
| 5962-9175501MGA | | 12/23/1992 | | (NONE) | | | EL2018 (GEN) | 779 |
| 5962-9175501MPA | | 12/23/1992 | | (NONE) | | | EL2018 (GEN) | 779 |
| 5962-9175701MXA | A | 03/14/2001 | | (NONE) | 10/29/2001 | | 72200L20 (GEN) | 670 |
| 5962-9175801M2A | F | 06/14/2001 | 2 | NATIONAL | | Y | CLC420AE-QML | 701 |
| 5962-9175801MPA | F | 06/14/2001 | 2 | NATIONAL | | Y | CLC420AJ-QML | 701 |
| 5962F9175801MPA | F | 06/14/2001 | 2 | NATIONAL | 03/08/2005 | Y | CLC420AJFQML | 701 |
| 5962-9175801MXA | F | 06/14/2001 | 2 | NATIONAL | | Y | CLC420AWG-QML | 701 |
| 5962F9175801MXA | F | 06/14/2001 | 2 | NATIONAL | 03/08/2005 | Y | CLC420AWGFQML | 701 |
| 5962-9175802M2A | F | 06/14/2001 | | (NONE) | | | CLC420B (GEN) | 701 |
| 5962-9175802MPA | F | 06/14/2001 | | (NONE) | 03/03/2004 | | CLC420B (GEN) | 701 |
| 5962-9176001M3A | C | 04/30/1996 | | (NONE) | 03/05/1996 | | 22V10G-15 (GEN) | 431 |
| 5962-9176002M3A | C | 04/30/1996 | | (NONE) | 03/05/1996 | | 22V10G-12 (GEN) | 431 |
| 5962-9176003M3A | C | 04/30/1996 | | (NONE) | | | 22V10G-10 (GEN) | 431 |
| 5962-9176004M3A | C | 04/30/1996 | | (NONE) | 03/05/1996 | | 22VP10G-15 (GEN) | 431 |
| 5962-9176005M3A | C | 04/30/1996 | | (NONE) | 03/05/1996 | | 22VP10G-12 (GEN) | 431 |
| 5962-9176006M3A | C | 04/30/1996 | | (NONE) | 03/05/1996 | | 22VP10G-10 (GEN) | 431 |
| 5962-9176007M3A | C | 04/30/1996 | | (NONE) | | | 22V10A (GEN) | 431 |
| 5962-9176007MLA | C | 04/30/1996 | 2 | QP SEMI | | Y | ABT22V10A/BLA | 431 |
| 5962-9176008M3A | C | 04/30/1996 | | (NONE) | | | 22V10B (GEN) | 431 |
| 5962-9176008MLA | C | 04/30/1996 | 2 | QP SEMI | | Y | ABT22V10B/BLA | 431 |
| 5962-9176009M3A | C | 04/30/1996 | | (NONE) | 03/05/1996 | | 22V10G-7 (GEN) | 431 |
| 5962-9176010M3A | C | 04/30/1996 | | (NONE) | 03/05/1996 | | 22VP10G-7 (GEN) | 431 |
| 5962-9176011NXA | C | 04/30/1996 | | (NONE) | | | 22V10A (GEN) | 431 |
| 5962-9176012NXA | C | 04/30/1996 | | (NONE) | | | 22V10A (GEN) | 431 |
| 5962-9176013NXA | C | 04/30/1996 | | (NONE) | | | 22V10B (GEN) | 431 |
| 5962-9176014NXA | C | 04/30/1996 | | (NONE) | | | 22V10B (GEN) | 431 |
| 5962-9176101MPA | | 12/09/1994 | | (NONE) | 06/30/1996 | | SP8799 (GEN) | 219 |
| 5962-9176201M3A | B | 01/15/1993 | | (NONE) | 04/01/2000 | | 29C520-30 (GEN) | 249 |
| 5962-9176201MKA | B | 01/15/1993 | | (NONE) | 04/01/2000 | | 29C520-30 (GEN) | 249 |
| 5962-9176201MLA | B | 01/15/1993 | | (NONE) | 04/01/2000 | | 29C520-30 (GEN) | 249 |
| 5962-9176202M3A | B | 01/15/1993 | | (NONE) | 04/01/2000 | | 29C520-24 (GEN) | 249 |
| 5962-9176202MKA | B | 01/15/1993 | | (NONE) | 04/01/2000 | | 29C520-24 (GEN) | 249 |
| 5962-9176202MLA | B | 01/15/1993 | | (NONE) | 04/01/2000 | | 29C520-24 (GEN) | 249 |
| 5962-9176203M3A | B | 01/15/1993 | | (NONE) | 04/01/2000 | | 29C520-16 (GEN) | 249 |
| 5962-9176203MKA | B | 01/15/1993 | | (NONE) | 04/01/2000 | | 29C520-16 (GEN) | 249 |
| 5962-9176203MLA | B | 01/15/1993 | | (NONE) | 04/01/2000 | | 29C520-16 (GEN) | 249 |
| 5962-9176204M3A | B | 01/15/1993 | | (NONE) | 04/01/2000 | | 29C521-30 (GEN) | 249 |
| 5962-9176204MKA | B | 01/15/1993 | | (NONE) | 04/01/2000 | | 29C521-30 (GEN) | 249 |
| 5962-9176204MLA | B | 01/15/1993 | | (NONE) | 04/01/2000 | | 29C521-30 (GEN) | 249 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9176205M3A | B | 01/15/1993 | | (NONE) | 04/01/2000 | | 29C521-24 (GEN) | 249 |
| 5962-9176205MKA | B | 01/15/1993 | | (NONE) | 04/01/2000 | | 29C521-24 (GEN) | 249 |
| 5962-9176205MLA | B | 01/15/1993 | | (NONE) | 04/01/2000 | | 29C521-24 (GEN) | 249 |
| 5962-9176206M3A | B | 01/15/1993 | | (NONE) | 07/31/1995 | | 29C521-16 (GEN) | 249 |
| 5962-9176206M3C | B | 01/15/1993 | | (NONE) | 07/31/1995 | | 29C521-16 (GEN) | 249 |
| 5962-9176206MKA | B | 01/15/1993 | | (NONE) | 07/31/1995 | | 29C521-16 (GEN) | 249 |
| 5962-9176206MLA | B | 01/15/1993 | | (NONE) | 04/01/2000 | | 29C521-16 (GEN) | 249 |
| 5962-9176301M2A | A | 08/28/1997 | | (NONE) | | | TL441AM (GEN) | 800 |
| 5962-9176301MEA | A | 08/28/1997 | | (NONE) | | | TL441AM (GEN) | 800 |
| 5962-9176301QEA | A | 08/28/1997 | 1 | TI | | Y | TL441AMJB | 800 |
| 5962-9176401MXA | A | 06/05/2001 | 1 | ANALOG (5) | | Y | DAC8412AT/883 | 591 |
| 5962-9176402M3A | A | 06/05/2001 | 1 | ANALOG (5) | | Y | DAC8412BTC/883 | 591 |
| 5962-9176402MXA | A | 06/05/2001 | 1 | ANALOG (5) | | Y | DAC8412BT/883 | 591 |
| 5962-9176403MXA | A | 06/05/2001 | 1 | ANALOG (5) | | Y | DAC8413AT/883 | 591 |
| 5962-9176404M3A | A | 06/05/2001 | 1 | ANALOG (5) | | Y | DAC8413BTC/883 | 591 |
| 5962-9176404MXA | A | 06/05/2001 | 1 | ANALOG (5) | | Y | DAC8413BT/883 | 591 |
| 5962-9177001HXA | B | 07/22/1999 | | (NONE) | | | MN6400T (GEN) | 592 |
| 5962-9177002HXA | B | 07/22/1999 | | (NONE) | | | MN6400S (GEN) | 592 |
| 5962-9177201MLA | | 02/01/1993 | | (NONE) | | | | 431 |
| 5962-9177301HZA | B | 06/16/2003 | 1 | ADV. ANALOG | | Y | AHV2805SF/CH | 594 |
| 5962-9177401HZA | B | 06/18/2003 | 1 | ADV. ANALOG | | Y | AHV2815DF/CH | 594 |
| 5962-9200301MCA | | 10/27/1992 | | (NONE) | 06/30/1996 | | SP8630 (GEN) | 319 |
| 5962-9200401M2A | C | 11/07/2000 | | (NONE) | | | CLC406 (GEN) | 755 |
| 5962-9200401MPA | C | 11/07/2000 | 1 | NATIONAL | | Y | CLC406AJ-QML | 755 |
| 5962-9200901MXC | B | 03/30/1995 | | (NONE) | 08/05/2002 | | VAC068A (GEN) | 420 |
| 5962-9200901MYA | B | 03/30/1995 | | (NONE) | 05/30/1999 | | VAC068A (GEN) | 420 |
| 5962-9201001MXC | B | 02/23/2001 | | (NONE) | 03/08/2003 | | VIC068A (GEN) | 420 |
| 5962-9201001MYC | B | 02/23/2001 | | (NONE) | 04/10/2001 | | VIC068A (GEN) | 420 |
| 5962-9201201MLA | A | 02/22/2002 | 1 | QP SEMI | | Y | PLS168/BLA | 431 |
| 5962-9201301MEA | A | 11/17/2000 | 1 | ANALOG (2) | | Y | AD684SQ/883B | 818 |
| 5962-9201401M2A | | 02/25/1993 | | (NONE) | | | AD9300 (GEN) | 199 |
| 5962-9201401MEA | | 02/25/1993 | | (NONE) | 09/30/2000 | | AD9300 (GEN) | 199 |
| 5962-9201601MEA | A | 07/18/2001 | 1 | ANALOG (2) | | Y | AD766SD/883B | 591 |
| 5962-9201801MXA | | 02/08/1993 | 2 | TI | | Y | SNJ54ACT16240WD | 569 |
| 5962-9202201MXA | A | 05/24/2004 | 2 | TI | | Y | SNJ54ACT16244WD | 569 |
| 5962-9202201QYA | A | 05/24/2004 | 2 | STMICRO | | Y | 54ACT16244K02Q | 569 |
| 5962-9202201QYC | A | 05/24/2004 | 2 | STMICRO | | Y | 54ACT16244K01Q | 569 |
| 5962-9202201VYA | A | 05/24/2004 | 2 | STMICRO | | Y | 54ACT16244K02V | 569 |
| 5962-9202201VYC | A | 05/24/2004 | 2 | STMICRO | | Y | 54ACT16244K01V | 569 |
| 5962F9202201QYA | A | 05/24/2004 | 2 | STMICRO | | Y | RHFACT16244K02Q | 569 |
| 5962F9202201QYC | A | 05/24/2004 | 2 | STMICRO | | Y | RHFACT16244K01Q | 569 |
| 5962F9202201VYA | A | 05/24/2004 | 2 | STMICRO | | Y | RHFACT16244K02V | 569 |
| 5962F9202201VYC | A | 05/24/2004 | 2 | STMICRO | | Y | RHFACT16244K01V | 569 |
| 5962-9202301MXA | A | 05/24/2004 | 2 | TI | | Y | SNJ54ACT16245WD | 590 |
| 5962-9202301QYA | A | 05/24/2004 | 2 | STMICRO | | Y | 54ACT16245K02Q | 590 |
| 5962-9202301QYC | A | 05/24/2004 | 2 | STMICRO | | Y | 54ACT16245K01Q | 590 |
| 5962-9202301VYA | A | 05/24/2004 | 2 | STMICRO | | Y | 54ACT16245K02V | 590 |
| 5962-9202301VYC | A | 05/24/2004 | 2 | STMICRO | | Y | 54ACT16245K01V | 590 |
| 5962F9202301QYA | A | 05/24/2004 | 2 | STMICRO | | Y | RHFACT16245K02Q | 590 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962F9202301QYC | A | 05/24/2004 | 2 | STMICRO | | Y | RHFACT16245K01Q | 590 |
| 5962F9202301VYA | A | 05/24/2004 | 2 | STMICRO | | Y | RHFACT16245K02V | 590 |
| 5962F9202301VYC | A | 05/24/2004 | 2 | STMICRO | | Y | RHFACT16245K01V | 590 |
| 5962-9202401MXA | A | 05/12/2004 | 3 | TI | | Y | SNJ54ACT16373WD | 342 |
| 5962-9202402QYA | A | 05/12/2004 | 2 | STMICRO | | Y | 54ACT16373K02Q | 342 |
| 5962-9202402QYC | A | 05/12/2004 | 2 | STMICRO | | Y | 54ACT16373K01Q | 342 |
| 5962-9202402VYA | A | 05/12/2004 | 2 | STMICRO | | Y | 54ACT16373K02V | 342 |
| 5962-9202402VYC | A | 05/12/2004 | 2 | STMICRO | | Y | 54ACT16373K01V | 342 |
| 5962F9202402QYA | A | 05/12/2004 | 2 | STMICRO | | Y | RHFACT16373K02Q | 342 |
| 5962F9202402QYC | A | 05/12/2004 | 2 | STMICRO | | Y | RHFACT16373K01Q | 342 |
| 5962F9202402VYA | A | 05/12/2004 | 2 | STMICRO | | Y | RHFACT16373K02V | 342 |
| 5962F9202402VYC | A | 05/12/2004 | 2 | STMICRO | | Y | RHFACT16373K01V | 342 |
| 5962-9202501MXA | A | 05/12/2004 | 3 | TI | | Y | SNJ54ACT16374WD | 159 |
| 5962-9202502QYA | A | 05/12/2004 | 2 | STMICRO | | Y | 54ACT16374K02Q | 159 |
| 5962-9202502QYC | A | 05/12/2004 | 2 | STMICRO | | Y | 54ACT16374K01Q | 159 |
| 5962-9202502VYA | A | 05/12/2004 | 2 | STMICRO | | Y | 54ACT16374K02V | 159 |
| 5962-9202502VYC | A | 05/12/2004 | 2 | STMICRO | | Y | 54ACT16374K01V | 159 |
| 5962F9202502QYA | A | 05/12/2004 | 2 | STMICRO | | Y | RHFACT16374K02Q | 159 |
| 5962F9202502QYC | A | 05/12/2004 | 2 | STMICRO | | Y | RHFACT16374K01Q | 159 |
| 5962F9202502VYA | A | 05/12/2004 | 2 | STMICRO | | Y | RHFACT16374K02V | 159 |
| 5962F9202502VYC | A | 05/12/2004 | 2 | STMICRO | | Y | RHFACT16374K01V | 159 |
| 5962-9202601QZC | | 10/14/1992 | | (NONE) | 12/20/2001 | | FXPC-49F (GEN) | 409 |
| 5962-9202601VZC | | 10/14/1992 | | (NONE) | 12/20/2001 | | FXPC-49F (GEN) | 409 |
| 5962-9203001M2A | D | 07/09/2003 | 3 | NATIONAL | 03/08/2005 | Y | CLC430AE-QML | 700 |
| 5962-9203001MPA | D | 07/09/2003 | 3 | NATIONAL | 03/08/2005 | Y | CLC430AJ-QML | 700 |
| 5962-9203001MXA | D | 07/09/2003 | 3 | NATIONAL | 03/08/2005 | Y | CLC430AWG-QML | 700 |
| 5962-9203101M2A | B | 02/22/2001 | | (NONE) | 12/31/2001 | | UC1864 (GEN) | 787 |
| 5962-9203101MEA | B | 02/22/2001 | | (NONE) | 12/31/2001 | | UC1864 (GEN) | 787 |
| 5962-9203102MEA | B | 02/22/2001 | | (NONE) | | | UC1865 (GEN) | 787 |
| 5962-9203103Q2A | B | 02/22/2001 | 1 | TI | | Y | UC1863L/883 | 787 |
| 5962-9203103V2A | B | 02/22/2001 | 1 | TI | | Y | UC1863LQMLV | 787 |
| 5962-9203103QEA | B | 02/22/2001 | 1 | TI | | Y | UC1863J/883 | 787 |
| 5962-9203103VEA | B | 02/22/2001 | 1 | TI | | Y | UC1863JQMLV | 787 |
| 5962-9203301M2A | B | 05/28/2003 | | (NONE) | | | CLC402A (GEN) | 702 |
| 5962-9203301MPA | B | 05/28/2003 | | (NONE) | 12/02/2003 | | CLC402A (GEN) | 702 |
| 5962F9203301MPA | B | 05/28/2003 | | (NONE) | 06/03/2003 | | CLC402 (GEN) | 702 |
| 5962-9203401M2A | E | 02/26/1999 | 1 | NATIONAL | | Y | CLC409AE-QML | 755 |
| 5962-9203401MPA | E | 02/26/1999 | 1 | NATIONAL | | Y | CLC409AJ-QML | 755 |
| 5962-9203501M2A | C | 07/13/2004 | 1 | NATIONAL | | Y | CLC532AE-QML | 199 |
| 5962-9203501MCA | C | 07/13/2004 | 1 | NATIONAL | | Y | CLC532AJ-QML | 199 |
| 5962-9203901HXA | | 11/22/1995 | | (NONE) | 02/27/1998 | | CLC935B (GEN) | 592 |
| 5962-9204001HXA | A | 02/20/2002 | 1 | ADV. ANALOG | | Y | AHE2812D/CH | 594 |
| 5962-9204001HZA | A | 02/20/2002 | 1 | ADV. ANALOG | | Y | AHE2812DF/CH | 594 |
| 5962-9204002HXA | A | 02/20/2002 | 1 | ADV. ANALOG | | Y | AHE2812D/CH-SLV | 594 |
| 5962-9204002HZA | A | 02/20/2002 | 1 | ADV. ANALOG | | Y | AHE2812DF/CH-SLV | 594 |
| 5962-9204003HXA | A | 02/20/2002 | 1 | ADV. ANALOG | | Y | AHE2812D/CH-MSTR | 594 |
| 5962-9204003HZA | A | 02/20/2002 | 1 | ADV. ANALOG | | Y | AHE2812DF/CH-MSTR | 594 |
| 5962-9204101M2A | B | 07/06/2001 | 1 | SILICONIX | | Y | DG441AZ/883 | 183 |
| 5962-9204101M2C | B | 07/06/2001 | 1 | MAXIM INTEG. | | | DG441AZ/883B | 183 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9204101MEA | B | 07/06/2001 | 1 | MAXIM INTEG. | | | DG441AK/883B | 183 |
| 5962-9204101MEA | B | 07/06/2001 | 1 | SILICONIX | | Y | DG441AK/883 | 183 |
| 5962-9204102M2A | B | 07/06/2001 | 1 | SILICONIX | | Y | DG442AZ/883 | 183 |
| 5962-9204102M2C | B | 07/06/2001 | 1 | MAXIM INTEG. | | | DG442AZ/883B | 183 |
| 5962-9204102MEA | B | 07/06/2001 | 1 | MAXIM INTEG. | | | DG442AK/883B | 183 |
| 5962-9204102MEA | B | 07/06/2001 | 1 | SILICONIX | | Y | DG442AK/883 | 183 |
| 5962-9204201M2A | E | 06/11/1998 | 1 | SILICONIX | | Y | DG408AZ/883 | 193 |
| 5962-9204201M2C | E | 06/11/1998 | 1 | MAXIM INTEG. | | | DG408AZ/883B | 193 |
| 5962-9204201MEA | E | 06/11/1998 | 2 | INTERSIL | | Y | DG408AK/883 | 193 |
| 5962-9204201MEA | E | 06/11/1998 | 1 | MAXIM INTEG. | | | DG408AK/883B | 193 |
| 5962-9204201MEA | E | 06/11/1998 | 1 | SILICONIX | | Y | DG408AK/883 | 193 |
| 5962-9204201MFA | E | 06/11/1998 | | (NONE) | | | DG408A (GEN) | 193 |
| 5962-9204201MXA | E | 06/11/1998 | 1 | SILICONIX | | Y | DG408AL/883 | 193 |
| 5962-9204201MXC | E | 06/11/1998 | 1 | MAXIM INTEG. | | | DG408AL/883B | 193 |
| 5962-9204201MXC | E | 06/11/1998 | 1 | SILICONIX | | Y | DG408AL/883 | 193 |
| 5962-9204202M2A | E | 06/11/1998 | 1 | SILICONIX | | Y | DG409AZ/883 | 192 |
| 5962-9204202M2C | E | 06/11/1998 | 1 | MAXIM INTEG. | | | DG409AZ/883B | 192 |
| 5962-9204202MEA | E | 06/11/1998 | 1 | MAXIM INTEG. | | | DG409AK/883B | 192 |
| 5962-9204202MEA | E | 06/11/1998 | 1 | SILICONIX | | Y | DG409AK/883 | 192 |
| 5962-9204202MFA | E | 06/11/1998 | | (NONE) | | | DG409A (GEN) | 192 |
| 5962-9204202MXA | E | 06/11/1998 | 1 | SILICONIX | | Y | DG409AL/883 | 192 |
| 5962-9204202MXC | E | 06/11/1998 | 1 | MAXIM INTEG. | | | DG409AL/883B | 192 |
| 5962-9204202MXC | E | 06/11/1998 | 1 | SILICONIX | | Y | DG409AL/883 | 192 |
| 5962-9204203M2A | E | 06/11/1998 | 2 | ANALOG (3) | | Y | ADG408TE/883B | 193 |
| 5962-9204203MEA | E | 06/11/1998 | 2 | ANALOG (3) | | Y | ADG408TQ/883B | 193 |
| 5962-9204204M2A | E | 06/11/1998 | 2 | ANALOG (3) | | Y | ADG409TE/883B | 192 |
| 5962-9204204MEA | E | 06/11/1998 | 2 | ANALOG (3) | | Y | ADG409TQ/883B | 192 |
| 5962-9204601M2A | | 04/12/1993 | 0 | TI | | Y | SNJ54LS628FK | 815 |
| 5962-9204601MCA | | 04/12/1993 | 0 | TI | | Y | SNJ54LS628J | 815 |
| 5962-9204801HXA | B | 06/18/2004 | 1 | DDC | | Y | SDC14570-142 | 594 |
| 5962-9204801HXA | B | 06/18/2004 | 1 | DDC | | Y | SDC14570-152 | 594 |
| 5962-9204801HXC | B | 06/18/2004 | 1 | DDC | | Y | SDC14570-132 | 594 |
| 5962-9204801HXC | B | 06/18/2004 | 1 | DDC | | Y | SDC14570-112 | 594 |
| 5962-9204802HXA | B | 06/18/2004 | 1 | DDC | | Y | SDC14571-142 | 594 |
| 5962-9204802HXA | B | 06/18/2004 | 1 | DDC | | Y | SDC14571-152 | 594 |
| 5962-9204802HXC | B | 06/18/2004 | 1 | DDC | | Y | SDC14571-132 | 594 |
| 5962-9204802HXC | B | 06/18/2004 | 1 | DDC | | Y | SDC14571-112 | 594 |
| 5962-9204803HXA | B | 06/18/2004 | 1 | DDC | | Y | SDC14575-142 | 594 |
| 5962-9204803HXA | B | 06/18/2004 | 1 | DDC | | Y | SDC14575-152 | 594 |
| 5962-9204803HXC | B | 06/18/2004 | 1 | DDC | | Y | SDC14575-132 | 594 |
| 5962-9204803HXC | B | 06/18/2004 | 1 | DDC | | Y | SDC14575-112 | 594 |
| 5962-9204804HXA | B | 06/18/2004 | 1 | DDC | | Y | SDC14576-142 | 594 |
| 5962-9204804HXA | B | 06/18/2004 | 1 | DDC | | Y | SDC14576-152 | 594 |
| 5962-9204804HXC | B | 06/18/2004 | 1 | DDC | | Y | SDC14576-132 | 594 |
| 5962-9204804HXC | B | 06/18/2004 | 1 | DDC | | Y | SDC14576-112 | 594 |
| 5962-9204805HXA | B | 06/18/2004 | 1 | DDC | | Y | SDC14575-144 | 594 |
| 5962-9204805HXA | B | 06/18/2004 | 1 | DDC | | Y | SDC14575-154 | 594 |
| 5962-9204805HXC | B | 06/18/2004 | 1 | DDC | | Y | SDC14575-134 | 594 |
| 5962-9204805HXC | B | 06/18/2004 | 1 | DDC | | Y | SDC14575-114 | 594 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9204806HXA | B | 06/18/2004 | 1 | DDC | | Y | SDC14576-144 | 594 |
| 5962-9204806HXA | B | 06/18/2004 | 1 | DDC | | Y | SDC14576-154 | 594 |
| 5962-9204806HXC | B | 06/18/2004 | 1 | DDC | | Y | SDC14576-134 | 594 |
| 5962-9204806HXC | B | 06/18/2004 | 1 | DDC | | Y | SDC14576-114 | 594 |
| 5962-9204901HXA | C | 06/18/2004 | 1 | DDC | | Y | SDC14572-142 | 594 |
| 5962-9204901HXA | C | 06/18/2004 | 1 | DDC | | Y | SDC14572-152 | 594 |
| 5962-9204901HXC | C | 06/18/2004 | 1 | DDC | | Y | SDC14572-132 | 594 |
| 5962-9204901HXC | C | 06/18/2004 | 1 | DDC | | Y | SDC14572-112 | 594 |
| 5962-9204902HXA | C | 06/18/2004 | 1 | DDC | | Y | SDC14574-142 | 594 |
| 5962-9204902HXA | C | 06/18/2004 | 1 | DDC | | Y | SDC14574-152 | 594 |
| 5962-9204902HXC | C | 06/18/2004 | 1 | DDC | | Y | SDC14574-132 | 594 |
| 5962-9204902HXC | C | 06/18/2004 | 1 | DDC | | Y | SDC14574-112 | 594 |
| 5962-9204903HXA | C | 06/18/2004 | 1 | DDC | | Y | SDC14577-142 | 594 |
| 5962-9204903HXA | C | 06/18/2004 | 1 | DDC | | Y | SDC14577-152 | 594 |
| 5962-9204903HXC | C | 06/18/2004 | 1 | DDC | | Y | SDC14577-132 | 594 |
| 5962-9204903HXC | C | 06/18/2004 | 1 | DDC | | Y | SDC14577-112 | 594 |
| 5962-9204904HXA | C | 06/18/2004 | 1 | DDC | | Y | SDC14579-142 | 594 |
| 5962-9204904HXA | C | 06/18/2004 | 1 | DDC | | Y | SDC14579-152 | 594 |
| 5962-9204904HXC | C | 06/18/2004 | 1 | DDC | | Y | SDC14579-132 | 594 |
| 5962-9204904HXC | C | 06/18/2004 | 1 | DDC | | Y | SDC14579-112 | 594 |
| 5962-9204905HXA | C | 06/18/2004 | 1 | DDC | | Y | SDC14577-144 | 594 |
| 5962-9204905HXA | C | 06/18/2004 | 1 | DDC | | Y | SDC14577-154 | 594 |
| 5962-9204905HXC | C | 06/18/2004 | 1 | DDC | | Y | SDC14577-134 | 594 |
| 5962-9204905HXC | C | 06/18/2004 | 1 | DDC | | Y | SDC14577-114 | 594 |
| 5962-9204906HXA | C | 06/18/2004 | 1 | DDC | | Y | SDC14579-144 | 594 |
| 5962-9204906HXA | C | 06/18/2004 | 1 | DDC | | Y | SDC14579-154 | 594 |
| 5962-9204906HXC | C | 06/18/2004 | 1 | DDC | | Y | SDC14579-134 | 594 |
| 5962-9204906HXC | C | 06/18/2004 | 1 | DDC | | Y | SDC14579-114 | 594 |
| 5962-9205001HXA | B | 06/18/2004 | 1 | DDC | | Y | SDC14573-152 | 594 |
| 5962-9205001HXA | B | 06/18/2004 | 1 | DDC | | Y | SDC14573-142 | 594 |
| 5962-9205001HXC | B | 06/18/2004 | 1 | DDC | | Y | SDC14573-132 | 594 |
| 5962-9205001HXC | B | 06/18/2004 | 1 | DDC | | Y | SDC14573-112 | 594 |
| 5962-9205002HXA | B | 06/18/2004 | 1 | DDC | | Y | SDC14578-152 | 594 |
| 5962-9205002HXA | B | 06/18/2004 | 1 | DDC | | Y | SDC14578-142 | 594 |
| 5962-9205002HXC | B | 06/18/2004 | 1 | DDC | | Y | SDC14578-132 | 594 |
| 5962-9205002HXC | B | 06/18/2004 | 1 | DDC | | Y | SDC14578-112 | 594 |
| 5962-9205003HXA | B | 06/18/2004 | 1 | DDC | | Y | SDC14578-154 | 594 |
| 5962-9205003HXA | B | 06/18/2004 | 1 | DDC | | Y | SDC14578-144 | 594 |
| 5962-9205003HXC | B | 06/18/2004 | 1 | DDC | | Y | SDC14578-134 | 594 |
| 5962-9205003HXC | B | 06/18/2004 | 1 | DDC | | Y | SDC14578-114 | 594 |
| 5962-9205101HXA | C | 06/18/2004 | 1 | DDC | | Y | SDC14602-142 | 594 |
| 5962-9205101HXA | C | 06/18/2004 | 1 | DDC | | Y | SDC14602-152 | 594 |
| 5962-9205101HXA | C | 06/18/2004 | 1 | DDC IRELAND | | Y | SDC14602-152 | 594 |
| 5962-9205101HXA | C | 06/18/2004 | 1 | DDC IRELAND | | Y | SDC14602-142 | 594 |
| 5962-9205101HXC | C | 06/18/2004 | 1 | DDC | | Y | SDC14602-132 | 594 |
| 5962-9205101HXC | C | 06/18/2004 | 1 | DDC | | Y | SDC14602-112 | 594 |
| 5962-9205101HXC | C | 06/18/2004 | 1 | DDC IRELAND | | Y | SDC14602-112 | 594 |
| 5962-9205101HXC | C | 06/18/2004 | 1 | DDC IRELAND | | Y | SDC14602-132 | 594 |
| 5962-9205102HXA | C | 06/18/2004 | 1 | DDC | | Y | SDC14602T-142 | 594 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9205102HXA | C | 06/18/2004 | 1 | DDC | | Y | SDC14602T-152 | 594 |
| 5962-9205102HXA | C | 06/18/2004 | 1 | DDC IRELAND | | Y | SDC14602T-152 | 594 |
| 5962-9205102HXA | C | 06/18/2004 | 1 | DDC IRELAND | | Y | SDC14602T-142 | 594 |
| 5962-9205102HXC | C | 06/18/2004 | 1 | DDC | | Y | SDC14602T-132 | 594 |
| 5962-9205102HXC | C | 06/18/2004 | 1 | DDC | | Y | SDC14602T-112 | 594 |
| 5962-9205102HXC | C | 06/18/2004 | 1 | DDC IRELAND | | Y | SDC14602T-132 | 594 |
| 5962-9205102HXC | C | 06/18/2004 | 1 | DDC IRELAND | | Y | SDC14602T-112 | 594 |
| 5962-9205103HXA | C | 06/18/2004 | 1 | DDC | | Y | SDC14604-142 | 594 |
| 5962-9205103HXA | C | 06/18/2004 | 1 | DDC | | Y | SDC14604-152 | 594 |
| 5962-9205103HXA | C | 06/18/2004 | 1 | DDC IRELAND | | Y | SDC14604-152 | 594 |
| 5962-9205103HXA | C | 06/18/2004 | 1 | DDC IRELAND | | Y | SDC14604-142 | 594 |
| 5962-9205103HXC | C | 06/18/2004 | 1 | DDC | | Y | SDC14604-132 | 594 |
| 5962-9205103HXC | C | 06/18/2004 | 1 | DDC | | Y | SDC14604-112 | 594 |
| 5962-9205103HXC | C | 06/18/2004 | 1 | DDC IRELAND | | Y | SDC14604-132 | 594 |
| 5962-9205103HXC | C | 06/18/2004 | 1 | DDC IRELAND | | Y | SDC14604-112 | 594 |
| 5962-9205104HXA | C | 06/18/2004 | 1 | DDC | | Y | SDC14604T-142 | 594 |
| 5962-9205104HXA | C | 06/18/2004 | 1 | DDC | | Y | SDC14604T-152 | 594 |
| 5962-9205104HXA | C | 06/18/2004 | 1 | DDC IRELAND | | Y | SDC14604T-152 | 594 |
| 5962-9205104HXA | C | 06/18/2004 | 1 | DDC IRELAND | | Y | SDC14604T-142 | 594 |
| 5962-9205104HXC | C | 06/18/2004 | 1 | DDC | | Y | SDC14604T-112 | 594 |
| 5962-9205104HXC | C | 06/18/2004 | 1 | DDC | | Y | SDC14604T-132 | 594 |
| 5962-9205104HXC | C | 06/18/2004 | 1 | DDC IRELAND | | Y | SDC14604T-112 | 594 |
| 5962-9205104HXC | C | 06/18/2004 | 1 | DDC IRELAND | | Y | SDC14604T-132 | 594 |
| 5962-9205105HXA | C | 06/18/2004 | 1 | DDC | | Y | SDC14607-142 | 594 |
| 5962-9205105HXA | C | 06/18/2004 | 1 | DDC | | Y | SDC14607-152 | 594 |
| 5962-9205105HXA | C | 06/18/2004 | 1 | DDC IRELAND | | Y | SDC14607-152 | 594 |
| 5962-9205105HXA | C | 06/18/2004 | 1 | DDC IRELAND | | Y | SDC14607-142 | 594 |
| 5962-9205105HXC | C | 06/18/2004 | 1 | DDC | | Y | SDC14607-132 | 594 |
| 5962-9205105HXC | C | 06/18/2004 | 1 | DDC | | Y | SDC14607-112 | 594 |
| 5962-9205105HXC | C | 06/18/2004 | 1 | DDC IRELAND | | Y | SDC14607-132 | 594 |
| 5962-9205105HXC | C | 06/18/2004 | 1 | DDC IRELAND | | Y | SDC14607-112 | 594 |
| 5962-9205106HXA | C | 06/18/2004 | 1 | DDC | | Y | SDC14607T-142 | 594 |
| 5962-9205106HXA | C | 06/18/2004 | 1 | DDC | | Y | SDC14607T-152 | 594 |
| 5962-9205106HXA | C | 06/18/2004 | 1 | DDC IRELAND | | Y | SDC14607T-142 | 594 |
| 5962-9205106HXA | C | 06/18/2004 | 1 | DDC IRELAND | | Y | SDC14607T-152 | 594 |
| 5962-9205106HXC | C | 06/18/2004 | 1 | DDC | | Y | SDC14607T-132 | 594 |
| 5962-9205106HXC | C | 06/18/2004 | 1 | DDC | | Y | SDC14607T-112 | 594 |
| 5962-9205106HXC | C | 06/18/2004 | 1 | DDC IRELAND | | Y | SDC14607T-132 | 594 |
| 5962-9205106HXC | C | 06/18/2004 | 1 | DDC IRELAND | | Y | SDC14607T-112 | 594 |
| 5962-9205107HXA | C | 06/18/2004 | 1 | DDC | | Y | SDC14609-142 | 594 |
| 5962-9205107HXA | C | 06/18/2004 | 1 | DDC | | Y | SDC14609-152 | 594 |
| 5962-9205107HXA | C | 06/18/2004 | 1 | DDC IRELAND | | Y | SDC14609-142 | 594 |
| 5962-9205107HXA | C | 06/18/2004 | 1 | DDC IRELAND | | Y | SDC14609-152 | 594 |
| 5962-9205107HXC | C | 06/18/2004 | 1 | DDC | | Y | SDC14609-132 | 594 |
| 5962-9205107HXC | C | 06/18/2004 | 1 | DDC | | Y | SDC14609-112 | 594 |
| 5962-9205107HXC | C | 06/18/2004 | 1 | DDC IRELAND | | Y | SDC14609-112 | 594 |
| 5962-9205107HXC | C | 06/18/2004 | 1 | DDC IRELAND | | Y | SDC14609-132 | 594 |
| 5962-9205108HXA | C | 06/18/2004 | 1 | DDC | | Y | SDC14609T-142 | 594 |
| 5962-9205108HXA | C | 06/18/2004 | 1 | DDC | | Y | SDC14609T-152 | 594 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9205108HXA | C | 06/18/2004 | 1 | DDC IRELAND | | Y | SDC14609T-142 | 594 |
| 5962-9205108HXA | C | 06/18/2004 | 1 | DDC IRELAND | | Y | SDC14609T-152 | 594 |
| 5962-9205108HXC | C | 06/18/2004 | 1 | DDC | | Y | SDC14609T-112 | 594 |
| 5962-9205108HXC | C | 06/18/2004 | 1 | DDC | | Y | SDC14609T-132 | 594 |
| 5962-9205108HXC | C | 06/18/2004 | 1 | DDC IRELAND | | Y | SDC14609T-112 | 594 |
| 5962-9205108HXC | C | 06/18/2004 | 1 | DDC IRELAND | | Y | SDC14609T-132 | 594 |
| 5962-9205109HXA | C | 06/18/2004 | 1 | DDC | | Y | SDC14607-144 | 594 |
| 5962-9205109HXA | C | 06/18/2004 | 1 | DDC | | Y | SDC14607-154 | 594 |
| 5962-9205109HXA | C | 06/18/2004 | 1 | DDC IRELAND | | Y | SDC14607-154 | 594 |
| 5962-9205109HXA | C | 06/18/2004 | 1 | DDC IRELAND | | Y | SDC14607-144 | 594 |
| 5962-9205109HXC | C | 06/18/2004 | 1 | DDC | | Y | SDC14607-134 | 594 |
| 5962-9205109HXC | C | 06/18/2004 | 1 | DDC | | Y | SDC14607-114 | 594 |
| 5962-9205109HXC | C | 06/18/2004 | 1 | DDC IRELAND | | Y | SDC14607-134 | 594 |
| 5962-9205109HXC | C | 06/18/2004 | 1 | DDC IRELAND | | Y | SDC14607-114 | 594 |
| 5962-9205110HXA | C | 06/18/2004 | 1 | DDC | | Y | SDC14607T-154 | 594 |
| 5962-9205110HXA | C | 06/18/2004 | 1 | DDC | | Y | SDC14607T-144 | 594 |
| 5962-9205110HXA | C | 06/18/2004 | 1 | DDC IRELAND | | Y | SDC14607T-144 | 594 |
| 5962-9205110HXA | C | 06/18/2004 | 1 | DDC IRELAND | | Y | SDC14607T-154 | 594 |
| 5962-9205110HXC | C | 06/18/2004 | 1 | DDC | | Y | SDC14607T-134 | 594 |
| 5962-9205110HXC | C | 06/18/2004 | 1 | DDC | | Y | SDC14607T-114 | 594 |
| 5962-9205110HXC | C | 06/18/2004 | 1 | DDC IRELAND | | Y | SDC14607T-114 | 594 |
| 5962-9205110HXC | C | 06/18/2004 | 1 | DDC IRELAND | | Y | SDC14607T-134 | 594 |
| 5962-9205111HXA | C | 06/18/2004 | 1 | DDC | | Y | SDC14609-144 | 594 |
| 5962-9205111HXA | C | 06/18/2004 | 1 | DDC | | Y | SDC14609-154 | 594 |
| 5962-9205111HXA | C | 06/18/2004 | 1 | DDC IRELAND | | Y | SDC14609-144 | 594 |
| 5962-9205111HXA | C | 06/18/2004 | 1 | DDC IRELAND | | Y | SDC14609-154 | 594 |
| 5962-9205111HXC | C | 06/18/2004 | 1 | DDC | | Y | SDC14609-134 | 594 |
| 5962-9205111HXC | C | 06/18/2004 | 1 | DDC | | Y | SDC14609-114 | 594 |
| 5962-9205111HXC | C | 06/18/2004 | 1 | DDC IRELAND | | Y | SDC14609-134 | 594 |
| 5962-9205111HXC | C | 06/18/2004 | 1 | DDC IRELAND | | Y | SDC14609-114 | 594 |
| 5962-9205112HXA | C | 06/18/2004 | 1 | DDC | | Y | SDC14609T-144 | 594 |
| 5962-9205112HXA | C | 06/18/2004 | 1 | DDC | | Y | SDC14609T-154 | 594 |
| 5962-9205112HXA | C | 06/18/2004 | 1 | DDC IRELAND | | Y | SDC14609T-144 | 594 |
| 5962-9205112HXA | C | 06/18/2004 | 1 | DDC IRELAND | | Y | SDC14609T-154 | 594 |
| 5962-9205112HXC | C | 06/18/2004 | 1 | DDC | | Y | SDC14609T-134 | 594 |
| 5962-9205112HXC | C | 06/18/2004 | 1 | DDC | | Y | SDC14609T-114 | 594 |
| 5962-9205112HXC | C | 06/18/2004 | 1 | DDC IRELAND | | Y | SDC14609T-134 | 594 |
| 5962-9205112HXC | C | 06/18/2004 | 1 | DDC IRELAND | | Y | SDC14609T-114 | 594 |
| 5962-9205201HXA | B | 06/18/2004 | 1 | DDC | | Y | SDC14603-142 | 594 |
| 5962-9205201HXA | B | 06/18/2004 | 1 | DDC | | Y | SDC14603-152 | 594 |
| 5962-9205201HXA | B | 06/18/2004 | 1 | DDC IRELAND | | Y | SDC14603-152 | 594 |
| 5962-9205201HXA | B | 06/18/2004 | 1 | DDC IRELAND | | Y | SDC14603-142 | 594 |
| 5962-9205201HXC | B | 06/18/2004 | 1 | DDC | | Y | SDC14603-132 | 594 |
| 5962-9205201HXC | B | 06/18/2004 | 1 | DDC | | Y | SDC14603-112 | 594 |
| 5962-9205201HXC | B | 06/18/2004 | 1 | DDC IRELAND | | Y | SDC14603-132 | 594 |
| 5962-9205201HXC | B | 06/18/2004 | 1 | DDC IRELAND | | Y | SDC14603-112 | 594 |
| 5962-9205202HXA | B | 06/18/2004 | 1 | DDC | | Y | SDC14603T-142 | 594 |
| 5962-9205202HXA | B | 06/18/2004 | 1 | DDC | | Y | SDC14603T-152 | 594 |
| 5962-9205202HXA | B | 06/18/2004 | 1 | DDC IRELAND | | Y | SDC14603T-152 | 594 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9205202HXA | B | 06/18/2004 | 1 | DDC IRELAND | | Y | SDC14603T-142 | 594 |
| 5962-9205202HXC | B | 06/18/2004 | 1 | DDC | | Y | SDC14603T-132 | 594 |
| 5962-9205202HXC | B | 06/18/2004 | 1 | DDC | | Y | SDC14603T-112 | 594 |
| 5962-9205202HXC | B | 06/18/2004 | 1 | DDC IRELAND | | Y | SDC14603T-112 | 594 |
| 5962-9205202HXC | B | 06/18/2004 | 1 | DDC IRELAND | | Y | SDC14603T-132 | 594 |
| 5962-9205203HXA | B | 06/18/2004 | 1 | DDC | | Y | SDC14608-142 | 594 |
| 5962-9205203HXA | B | 06/18/2004 | 1 | DDC | | Y | SDC14608-152 | 594 |
| 5962-9205203HXA | B | 06/18/2004 | 1 | DDC IRELAND | | Y | SDC14608-152 | 594 |
| 5962-9205203HXA | B | 06/18/2004 | 1 | DDC IRELAND | | Y | SDC14608-142 | 594 |
| 5962-9205203HXC | B | 06/18/2004 | 1 | DDC | | Y | SDC14608-132 | 594 |
| 5962-9205203HXC | B | 06/18/2004 | 1 | DDC | | Y | SDC14608-112 | 594 |
| 5962-9205203HXC | B | 06/18/2004 | 1 | DDC IRELAND | | Y | SDC14608-132 | 594 |
| 5962-9205203HXC | B | 06/18/2004 | 1 | DDC IRELAND | | Y | SDC14608-112 | 594 |
| 5962-9205204HXA | B | 06/18/2004 | 1 | DDC | | Y | SDC14608T-142 | 594 |
| 5962-9205204HXA | B | 06/18/2004 | 1 | DDC | | Y | SDC14608T-152 | 594 |
| 5962-9205204HXA | B | 06/18/2004 | 1 | DDC IRELAND | | Y | SDC14608T-142 | 594 |
| 5962-9205204HXA | B | 06/18/2004 | 1 | DDC IRELAND | | Y | SDC14608T-152 | 594 |
| 5962-9205204HXC | B | 06/18/2004 | 1 | DDC | | Y | SDC14608T-132 | 594 |
| 5962-9205204HXC | B | 06/18/2004 | 1 | DDC | | Y | SDC14608T-112 | 594 |
| 5962-9205204HXC | B | 06/18/2004 | 1 | DDC IRELAND | | Y | SDC14608T-132 | 594 |
| 5962-9205204HXC | B | 06/18/2004 | 1 | DDC IRELAND | | Y | SDC14608T-112 | 594 |
| 5962-9205205HXA | B | 06/18/2004 | 1 | DDC | | Y | SDC14608-144 | 594 |
| 5962-9205205HXA | B | 06/18/2004 | 1 | DDC | | Y | SDC14608-154 | 594 |
| 5962-9205205HXA | B | 06/18/2004 | 1 | DDC IRELAND | | Y | SDC14608-154 | 594 |
| 5962-9205205HXA | B | 06/18/2004 | 1 | DDC IRELAND | | Y | SDC14608-144 | 594 |
| 5962-9205205HXC | B | 06/18/2004 | 1 | DDC | | Y | SDC14608-134 | 594 |
| 5962-9205205HXC | B | 06/18/2004 | 1 | DDC | | Y | SDC14608-114 | 594 |
| 5962-9205205HXC | B | 06/18/2004 | 1 | DDC IRELAND | | Y | SDC14608-114 | 594 |
| 5962-9205205HXC | B | 06/18/2004 | 1 | DDC IRELAND | | Y | SDC14608-134 | 594 |
| 5962-9205206HXA | B | 06/18/2004 | 1 | DDC | | Y | SDC14608T-144 | 594 |
| 5962-9205206HXA | B | 06/18/2004 | 1 | DDC | | Y | SDC14608T-154 | 594 |
| 5962-9205206HXA | B | 06/18/2004 | 1 | DDC IRELAND | | Y | SDC14608T-154 | 594 |
| 5962-9205206HXA | B | 06/18/2004 | 1 | DDC IRELAND | | Y | SDC14608T-144 | 594 |
| 5962-9205206HXC | B | 06/18/2004 | 1 | DDC | | Y | SDC14608T-134 | 594 |
| 5962-9205206HXC | B | 06/18/2004 | 1 | DDC | | Y | SDC14608T-114 | 594 |
| 5962-9205206HXC | B | 06/18/2004 | 1 | DDC IRELAND | | Y | SDC14608T-134 | 594 |
| 5962-9205206HXC | B | 06/18/2004 | 1 | DDC IRELAND | | Y | SDC14608T-114 | 594 |
| 5962-9205301HXA | B | 06/18/2004 | 1 | DDC | | Y | SDC-14610II-142 | 594 |
| 5962-9205301HXA | B | 06/18/2004 | 1 | DDC | | Y | SDC-14610II-152 | 594 |
| 5962-9205301HXA | B | 06/18/2004 | 1 | DDC IRELAND | | Y | SDC-14610II-142 | 594 |
| 5962-9205301HXA | B | 06/18/2004 | 1 | DDC IRELAND | | Y | SDC-14610II-152 | 594 |
| 5962-9205301HXC | B | 06/18/2004 | 1 | DDC | | Y | SDC-14610II-132 | 594 |
| 5962-9205301HXC | B | 06/18/2004 | 1 | DDC | | Y | SDC-14610II-112 | 594 |
| 5962-9205301HXC | B | 06/18/2004 | 1 | DDC IRELAND | | Y | SDC-14610II-132 | 594 |
| 5962-9205301HXC | B | 06/18/2004 | 1 | DDC IRELAND | | Y | SDC-14610II-112 | 594 |
| 5962-9205302HXA | B | 06/18/2004 | 1 | DDC | | Y | SDC-14610IIT-142 | 594 |
| 5962-9205302HXA | B | 06/18/2004 | 1 | DDC | | Y | SDC-14610IIT-152 | 594 |
| 5962-9205302HXA | B | 06/18/2004 | 1 | DDC IRELAND | | Y | SDC-14610IIT-142 | 594 |
| 5962-9205302HXA | B | 06/18/2004 | 1 | DDC IRELAND | | Y | SDC-14610IIT-152 | 594 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9205302HXC | B | 06/18/2004 | 1 | DDC | | Y | SDC-14610IIT-132 | 594 |
| 5962-9205302HXC | B | 06/18/2004 | 1 | DDC | | Y | SDC-14610IIT-112 | 594 |
| 5962-9205302HXC | B | 06/18/2004 | 1 | DDC IRELAND | | Y | SDC-14610IIT-132 | 594 |
| 5962-9205302HXC | B | 06/18/2004 | 1 | DDC IRELAND | | Y | SDC-14610IIT-112 | 594 |
| 5962-9205303HXA | B | 06/18/2004 | 1 | DDC | | Y | SDC-14611II-142 | 594 |
| 5962-9205303HXA | B | 06/18/2004 | 1 | DDC | | Y | SDC-14611II-152 | 594 |
| 5962-9205303HXA | B | 06/18/2004 | 1 | DDC IRELAND | | Y | SDC-14611II-142 | 594 |
| 5962-9205303HXA | B | 06/18/2004 | 1 | DDC IRELAND | | Y | SDC-14611II-152 | 594 |
| 5962-9205303HXC | B | 06/18/2004 | 1 | DDC | | Y | SDC-14611II-132 | 594 |
| 5962-9205303HXC | B | 06/18/2004 | 1 | DDC | | Y | SDC-14611II-112 | 594 |
| 5962-9205303HXC | B | 06/18/2004 | 1 | DDC IRELAND | | Y | SDC-14611II-132 | 594 |
| 5962-9205303HXC | B | 06/18/2004 | 1 | DDC IRELAND | | Y | SDC-14611II-112 | 594 |
| 5962-9205304HXA | B | 06/18/2004 | 1 | DDC | | Y | SDC-14611IIT-142 | 594 |
| 5962-9205304HXA | B | 06/18/2004 | 1 | DDC | | Y | SDC-14611IIT-152 | 594 |
| 5962-9205304HXA | B | 06/18/2004 | 1 | DDC IRELAND | | Y | SDC-14611IIT-142 | 594 |
| 5962-9205304HXA | B | 06/18/2004 | 1 | DDC IRELAND | | Y | SDC-14611IIT-152 | 594 |
| 5962-9205304HXC | B | 06/18/2004 | 1 | DDC | | Y | SDC-14611IIT-132 | 594 |
| 5962-9205304HXC | B | 06/18/2004 | 1 | DDC | | Y | SDC-14611IIT-112 | 594 |
| 5962-9205304HXC | B | 06/18/2004 | 1 | DDC IRELAND | | Y | SDC-14611IIT-132 | 594 |
| 5962-9205304HXC | B | 06/18/2004 | 1 | DDC IRELAND | | Y | SDC-14611IIT-112 | 594 |
| 5962-9205305HXA | B | 06/18/2004 | 1 | DDC | | Y | SDC-14615II-142 | 594 |
| 5962-9205305HXA | B | 06/18/2004 | 1 | DDC | | Y | SDC-14615II-152 | 594 |
| 5962-9205305HXA | B | 06/18/2004 | 1 | DDC IRELAND | | Y | SDC-14615II-152 | 594 |
| 5962-9205305HXA | B | 06/18/2004 | 1 | DDC IRELAND | | Y | SDC-14615II-142 | 594 |
| 5962-9205305HXC | B | 06/18/2004 | 1 | DDC | | Y | SDC-14615II-132 | 594 |
| 5962-9205305HXC | B | 06/18/2004 | 1 | DDC | | Y | SDC-14615II-112 | 594 |
| 5962-9205305HXC | B | 06/18/2004 | 1 | DDC IRELAND | | Y | SDC-14615II-112 | 594 |
| 5962-9205305HXC | B | 06/18/2004 | 1 | DDC IRELAND | | Y | SDC-14615II-132 | 594 |
| 5962-9205306HXA | B | 06/18/2004 | 1 | DDC | | Y | SDC-14615IIT-142 | 594 |
| 5962-9205306HXA | B | 06/18/2004 | 1 | DDC | | Y | SDC-14615IIT-152 | 594 |
| 5962-9205306HXA | B | 06/18/2004 | 1 | DDC IRELAND | | Y | SDC-14615IIT-142 | 594 |
| 5962-9205306HXA | B | 06/18/2004 | 1 | DDC IRELAND | | Y | SDC-14615IIT-152 | 594 |
| 5962-9205306HXC | B | 06/18/2004 | 1 | DDC | | Y | SDC-14615IIT-132 | 594 |
| 5962-9205306HXC | B | 06/18/2004 | 1 | DDC | | Y | SDC-14615IIT-112 | 594 |
| 5962-9205306HXC | B | 06/18/2004 | 1 | DDC IRELAND | | Y | SDC-14615IIT-132 | 594 |
| 5962-9205306HXC | B | 06/18/2004 | 1 | DDC IRELAND | | Y | SDC-14615IIT-112 | 594 |
| 5962-9205307HXA | B | 06/18/2004 | 1 | DDC | | Y | SDC-14616II-142 | 594 |
| 5962-9205307HXA | B | 06/18/2004 | 1 | DDC | | Y | SDC-14616II-152 | 594 |
| 5962-9205307HXA | B | 06/18/2004 | 1 | DDC IRELAND | | Y | SDC-14616II-152 | 594 |
| 5962-9205307HXA | B | 06/18/2004 | 1 | DDC IRELAND | | Y | SDC-14616II-142 | 594 |
| 5962-9205307HXC | B | 06/18/2004 | 1 | DDC | | Y | SDC-14616II-132 | 594 |
| 5962-9205307HXC | B | 06/18/2004 | 1 | DDC | | Y | SDC-14616II-112 | 594 |
| 5962-9205307HXC | B | 06/18/2004 | 1 | DDC IRELAND | | Y | SDC-14616II-112 | 594 |
| 5962-9205307HXC | B | 06/18/2004 | 1 | DDC IRELAND | | Y | SDC-14616II-132 | 594 |
| 5962-9205308HXA | B | 06/18/2004 | 1 | DDC | | Y | SDC-14616IIT-142 | 594 |
| 5962-9205308HXA | B | 06/18/2004 | 1 | DDC | | Y | SDC-14616IIT-152 | 594 |
| 5962-9205308HXA | B | 06/18/2004 | 1 | DDC IRELAND | | Y | SDC-14616IIT-152 | 594 |
| 5962-9205308HXA | B | 06/18/2004 | 1 | DDC IRELAND | | Y | SDC-14616IIT-142 | 594 |
| 5962-9205308HXC | B | 06/18/2004 | 1 | DDC | | Y | SDC-14616IIT-132 | 594 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9205308HXC | B | 06/18/2004 | 1 | DDC | | Y | SDC-14616IIT-112 | 594 |
| 5962-9205308HXC | B | 06/18/2004 | 1 | DDC IRELAND | | Y | SDC-14616IIT-112 | 594 |
| 5962-9205308HXC | B | 06/18/2004 | 1 | DDC IRELAND | | Y | SDC-14616IIT-132 | 594 |
| 5962-9205309HXA | B | 06/18/2004 | 1 | DDC | | Y | SDC-14615II-144 | 594 |
| 5962-9205309HXA | B | 06/18/2004 | 1 | DDC | | Y | SDC-14615II-154 | 594 |
| 5962-9205309HXA | B | 06/18/2004 | 1 | DDC IRELAND | | Y | SDC-14615II-154 | 594 |
| 5962-9205309HXA | B | 06/18/2004 | 1 | DDC IRELAND | | Y | SDC-14615II-144 | 594 |
| 5962-9205309HXC | B | 06/18/2004 | 1 | DDC | | Y | SDC-14615II-134 | 594 |
| 5962-9205309HXC | B | 06/18/2004 | 1 | DDC | | Y | SDC-14615II-114 | 594 |
| 5962-9205309HXC | B | 06/18/2004 | 1 | DDC IRELAND | | Y | SDC-14615II-114 | 594 |
| 5962-9205309HXC | B | 06/18/2004 | 1 | DDC IRELAND | | Y | SDC-14615II-134 | 594 |
| 5962-9205310HXA | B | 06/18/2004 | 1 | DDC | | Y | SDC-14615IIT-144 | 594 |
| 5962-9205310HXA | B | 06/18/2004 | 1 | DDC | | Y | SDC-14615IIT-154 | 594 |
| 5962-9205310HXA | B | 06/18/2004 | 1 | DDC IRELAND | | Y | SDC-14615IIT-144 | 594 |
| 5962-9205310HXA | B | 06/18/2004 | 1 | DDC IRELAND | | Y | SDC-14615IIT-154 | 594 |
| 5962-9205310HXC | B | 06/18/2004 | 1 | DDC | | Y | SDC-14615IIT-134 | 594 |
| 5962-9205310HXC | B | 06/18/2004 | 1 | DDC | | Y | SDC-14615IIT-114 | 594 |
| 5962-9205310HXC | B | 06/18/2004 | 1 | DDC IRELAND | | Y | SDC-14615IIT-114 | 594 |
| 5962-9205310HXC | B | 06/18/2004 | 1 | DDC IRELAND | | Y | SDC-14615IIT-134 | 594 |
| 5962-9205311HXA | B | 06/18/2004 | 1 | DDC | | Y | SDC-14616II-144 | 594 |
| 5962-9205311HXA | B | 06/18/2004 | 1 | DDC | | Y | SDC-14616II-154 | 594 |
| 5962-9205311HXA | B | 06/18/2004 | 1 | DDC IRELAND | | Y | SDC-14616II-154 | 594 |
| 5962-9205311HXA | B | 06/18/2004 | 1 | DDC IRELAND | | Y | SDC-14616II-144 | 594 |
| 5962-9205311HXC | B | 06/18/2004 | 1 | DDC | | Y | SDC-14616II-134 | 594 |
| 5962-9205311HXC | B | 06/18/2004 | 1 | DDC | | Y | SDC-14616II-114 | 594 |
| 5962-9205311HXC | B | 06/18/2004 | 1 | DDC IRELAND | | Y | SDC-14616II-134 | 594 |
| 5962-9205311HXC | B | 06/18/2004 | 1 | DDC IRELAND | | Y | SDC-14616II-114 | 594 |
| 5962-9205312HXA | B | 06/18/2004 | 1 | DDC | | Y | SDC-14616IIT-154 | 594 |
| 5962-9205312HXA | B | 06/18/2004 | 1 | DDC | | Y | SDC-14616IIT-144 | 594 |
| 5962-9205312HXA | B | 06/18/2004 | 1 | DDC IRELAND | | Y | SDC-14616IIT-154 | 594 |
| 5962-9205312HXA | B | 06/18/2004 | 1 | DDC IRELAND | | Y | SDC-14616IIT-144 | 594 |
| 5962-9205312HXC | B | 06/18/2004 | 1 | DDC | | Y | SDC-14616IIT-134 | 594 |
| 5962-9205312HXC | B | 06/18/2004 | 1 | DDC | | Y | SDC-14616IIT-114 | 594 |
| 5962-9205312HXC | B | 06/18/2004 | 1 | DDC IRELAND | | Y | SDC-14616IIT-114 | 594 |
| 5962-9205312HXC | B | 06/18/2004 | 1 | DDC IRELAND | | Y | SDC-14616IIT-134 | 594 |
| 5962-9205401HXA | B | 06/18/2004 | 1 | DDC | | Y | SDC-14612II-142 | 594 |
| 5962-9205401HXA | B | 06/18/2004 | 1 | DDC | | Y | SDC-14612II-152 | 594 |
| 5962-9205401HXA | B | 06/18/2004 | 1 | DDC IRELAND | | Y | SDC-14612II-142 | 594 |
| 5962-9205401HXA | B | 06/18/2004 | 1 | DDC IRELAND | | Y | SDC-14612II-152 | 594 |
| 5962-9205401HXC | B | 06/18/2004 | 1 | DDC | | Y | SDC-14612II-132 | 594 |
| 5962-9205401HXC | B | 06/18/2004 | 1 | DDC | | Y | SDC-14612II-112 | 594 |
| 5962-9205401HXC | B | 06/18/2004 | 1 | DDC IRELAND | | Y | SDC-14612II-132 | 594 |
| 5962-9205401HXC | B | 06/18/2004 | 1 | DDC IRELAND | | Y | SDC-14612II-112 | 594 |
| 5962-9205402HXA | B | 06/18/2004 | 1 | DDC | | Y | SDC-14612IIT-142 | 594 |
| 5962-9205402HXA | B | 06/18/2004 | 1 | DDC | | Y | SDC-14612IIT-152 | 594 |
| 5962-9205402HXA | B | 06/18/2004 | 1 | DDC IRELAND | | Y | SDC-14612IIT-142 | 594 |
| 5962-9205402HXA | B | 06/18/2004 | 1 | DDC IRELAND | | Y | SDC-14612IIT-152 | 594 |
| 5962-9205402HXC | B | 06/18/2004 | 1 | DDC | | Y | SDC-14612IIT-132 | 594 |
| 5962-9205402HXC | B | 06/18/2004 | 1 | DDC | | Y | SDC-14612IIT-112 | 594 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9205402HXC | B | 06/18/2004 | 1 | DDC IRELAND | | Y | SDC-14612IIT-112 | 594 |
| 5962-9205402HXC | B | 06/18/2004 | 1 | DDC IRELAND | | Y | SDC-14612IIT-132 | 594 |
| 5962-9205403HXA | B | 06/18/2004 | 1 | DDC | | Y | SDC-14614II-142 | 594 |
| 5962-9205403HXA | B | 06/18/2004 | 1 | DDC | | Y | SDC-14614II-152 | 594 |
| 5962-9205403HXA | B | 06/18/2004 | 1 | DDC IRELAND | | Y | SDC-14614II-152 | 594 |
| 5962-9205403HXA | B | 06/18/2004 | 1 | DDC IRELAND | | Y | SDC-14614II-142 | 594 |
| 5962-9205403HXC | B | 06/18/2004 | 1 | DDC | | Y | SDC-14614II-132 | 594 |
| 5962-9205403HXC | B | 06/18/2004 | 1 | DDC | | Y | SDC-14614II-112 | 594 |
| 5962-9205403HXC | B | 06/18/2004 | 1 | DDC IRELAND | | Y | SDC-14614II-112 | 594 |
| 5962-9205403HXC | B | 06/18/2004 | 1 | DDC IRELAND | | Y | SDC-14614II-132 | 594 |
| 5962-9205404HXA | B | 06/18/2004 | 1 | DDC | | Y | SDC-14614IIT-142 | 594 |
| 5962-9205404HXA | B | 06/18/2004 | 1 | DDC | | Y | SDC-14614IIT-152 | 594 |
| 5962-9205404HXA | B | 06/18/2004 | 1 | DDC IRELAND | | Y | SDC-14614IIT-152 | 594 |
| 5962-9205404HXA | B | 06/18/2004 | 1 | DDC IRELAND | | Y | SDC-14614IIT-142 | 594 |
| 5962-9205404HXC | B | 06/18/2004 | 1 | DDC | | Y | SDC-14614IIT-132 | 594 |
| 5962-9205404HXC | B | 06/18/2004 | 1 | DDC | | Y | SDC-14614IIT-112 | 594 |
| 5962-9205404HXC | B | 06/18/2004 | 1 | DDC IRELAND | | Y | SDC-14614IIT-112 | 594 |
| 5962-9205404HXC | B | 06/18/2004 | 1 | DDC IRELAND | | Y | SDC-14614IIT-132 | 594 |
| 5962-9205405HXA | B | 06/18/2004 | 1 | DDC | | Y | SDC-14617II-142 | 594 |
| 5962-9205405HXA | B | 06/18/2004 | 1 | DDC | | Y | SDC-14617II-152 | 594 |
| 5962-9205405HXA | B | 06/18/2004 | 1 | DDC IRELAND | | Y | SDC-14617II-142 | 594 |
| 5962-9205405HXA | B | 06/18/2004 | 1 | DDC IRELAND | | Y | SDC-14617II-152 | 594 |
| 5962-9205405HXC | B | 06/18/2004 | 1 | DDC | | Y | SDC-14617II-132 | 594 |
| 5962-9205405HXC | B | 06/18/2004 | 1 | DDC | | Y | SDC-14617II-112 | 594 |
| 5962-9205405HXC | B | 06/18/2004 | 1 | DDC IRELAND | | Y | SDC-14617II-132 | 594 |
| 5962-9205405HXC | B | 06/18/2004 | 1 | DDC IRELAND | | Y | SDC-14617II-112 | 594 |
| 5962-9205406HXA | B | 06/18/2004 | 1 | DDC | | Y | SDC-14617IIT-142 | 594 |
| 5962-9205406HXA | B | 06/18/2004 | 1 | DDC | | Y | SDC-14617IIT-152 | 594 |
| 5962-9205406HXA | B | 06/18/2004 | 1 | DDC IRELAND | | Y | SDC-14617IIT-142 | 594 |
| 5962-9205406HXA | B | 06/18/2004 | 1 | DDC IRELAND | | Y | SDC-14617IIT-152 | 594 |
| 5962-9205406HXC | B | 06/18/2004 | 1 | DDC | | Y | SDC-14617IIT-132 | 594 |
| 5962-9205406HXC | B | 06/18/2004 | 1 | DDC | | Y | SDC-14617IIT-112 | 594 |
| 5962-9205406HXC | B | 06/18/2004 | 1 | DDC IRELAND | | Y | SDC-14617IIT-112 | 594 |
| 5962-9205406HXC | B | 06/18/2004 | 1 | DDC IRELAND | | Y | SDC-14617IIT-132 | 594 |
| 5962-9205407HXA | B | 06/18/2004 | 1 | DDC | | Y | SDC-14619II-142 | 594 |
| 5962-9205407HXA | B | 06/18/2004 | 1 | DDC | | Y | SDC-14619II-152 | 594 |
| 5962-9205407HXA | B | 06/18/2004 | 1 | DDC IRELAND | | Y | SDC-14619II-152 | 594 |
| 5962-9205407HXA | B | 06/18/2004 | 1 | DDC IRELAND | | Y | SDC-14619II-142 | 594 |
| 5962-9205407HXC | B | 06/18/2004 | 1 | DDC | | Y | SDC-14619II-132 | 594 |
| 5962-9205407HXC | B | 06/18/2004 | 1 | DDC | | Y | SDC-14619II-112 | 594 |
| 5962-9205407HXC | B | 06/18/2004 | 1 | DDC IRELAND | | Y | SDC-14619II-112 | 594 |
| 5962-9205407HXC | B | 06/18/2004 | 1 | DDC IRELAND | | Y | SDC-14619II-132 | 594 |
| 5962-9205408HXA | B | 06/18/2004 | 1 | DDC | | Y | SDC-14619IIT-142 | 594 |
| 5962-9205408HXA | B | 06/18/2004 | 1 | DDC | | Y | SDC-14619IIT-152 | 594 |
| 5962-9205408HXA | B | 06/18/2004 | 1 | DDC IRELAND | | Y | SDC-14619IIT-152 | 594 |
| 5962-9205408HXA | B | 06/18/2004 | 1 | DDC IRELAND | | Y | SDC-14619IIT-142 | 594 |
| 5962-9205408HXC | B | 06/18/2004 | 1 | DDC | | Y | SDC-14619IIT-132 | 594 |
| 5962-9205408HXC | B | 06/18/2004 | 1 | DDC | | Y | SDC-14619IIT-112 | 594 |
| 5962-9205408HXC | B | 06/18/2004 | 1 | DDC IRELAND | | Y | SDC-14619IIT-132 | 594 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9205408HXC | B | 06/18/2004 | 1 | DDC IRELAND | | Y | SDC-14619IIT-112 | 594 |
| 5962-9205409HXA | B | 06/18/2004 | 1 | DDC | | Y | SDC-14617II-144 | 594 |
| 5962-9205409HXA | B | 06/18/2004 | 1 | DDC | | Y | SDC-14617II-154 | 594 |
| 5962-9205409HXA | B | 06/18/2004 | 1 | DDC IRELAND | | Y | SDC-14617II-154 | 594 |
| 5962-9205409HXA | B | 06/18/2004 | 1 | DDC IRELAND | | Y | SDC-14617II-144 | 594 |
| 5962-9205409HXC | B | 06/18/2004 | 1 | DDC | | Y | SDC-14617II-134 | 594 |
| 5962-9205409HXC | B | 06/18/2004 | 1 | DDC | | Y | SDC-14617II-114 | 594 |
| 5962-9205409HXC | B | 06/18/2004 | 1 | DDC IRELAND | | Y | SDC-14617II-114 | 594 |
| 5962-9205409HXC | B | 06/18/2004 | 1 | DDC IRELAND | | Y | SDC-14617II-134 | 594 |
| 5962-9205410HXA | B | 06/18/2004 | 1 | DDC | | Y | SDC-14617IIT-144 | 594 |
| 5962-9205410HXA | B | 06/18/2004 | 1 | DDC | | Y | SDC-14617IIT-154 | 594 |
| 5962-9205410HXA | B | 06/18/2004 | 1 | DDC IRELAND | | Y | SDC-14617IIT-154 | 594 |
| 5962-9205410HXA | B | 06/18/2004 | 1 | DDC IRELAND | | Y | SDC-14617IIT-144 | 594 |
| 5962-9205410HXC | B | 06/18/2004 | 1 | DDC | | Y | SDC-14617IIT-134 | 594 |
| 5962-9205410HXC | B | 06/18/2004 | 1 | DDC | | Y | SDC-14617IIT-114 | 594 |
| 5962-9205410HXC | B | 06/18/2004 | 1 | DDC IRELAND | | Y | SDC-14617IIT-114 | 594 |
| 5962-9205410HXC | B | 06/18/2004 | 1 | DDC IRELAND | | Y | SDC-14617IIT-134 | 594 |
| 5962-9205411HXA | B | 06/18/2004 | 1 | DDC | | Y | SDC-14619II-144 | 594 |
| 5962-9205411HXA | B | 06/18/2004 | 1 | DDC | | Y | SDC-14619II-154 | 594 |
| 5962-9205411HXA | B | 06/18/2004 | 1 | DDC IRELAND | | Y | SDC-14619II-154 | 594 |
| 5962-9205411HXA | B | 06/18/2004 | 1 | DDC IRELAND | | Y | SDC-14619II-144 | 594 |
| 5962-9205411HXC | B | 06/18/2004 | 1 | DDC | | Y | SDC-14619II-134 | 594 |
| 5962-9205411HXC | B | 06/18/2004 | 1 | DDC | | Y | SDC-14619II-114 | 594 |
| 5962-9205411HXC | B | 06/18/2004 | 1 | DDC IRELAND | | Y | SDC-14619II-114 | 594 |
| 5962-9205411HXC | B | 06/18/2004 | 1 | DDC IRELAND | | Y | SDC-14619II-134 | 594 |
| 5962-9205412HXA | B | 06/18/2004 | 1 | DDC | | Y | SDC-14619IIT-144 | 594 |
| 5962-9205412HXA | B | 06/18/2004 | 1 | DDC | | Y | SDC-14619IIT-154 | 594 |
| 5962-9205412HXA | B | 06/18/2004 | 1 | DDC IRELAND | | Y | SDC-14619IIT-144 | 594 |
| 5962-9205412HXA | B | 06/18/2004 | 1 | DDC IRELAND | | Y | SDC-14619IIT-154 | 594 |
| 5962-9205412HXC | B | 06/18/2004 | 1 | DDC | | Y | SDC-14619IIT-134 | 594 |
| 5962-9205412HXC | B | 06/18/2004 | 1 | DDC | | Y | SDC-14619IIT-114 | 594 |
| 5962-9205412HXC | B | 06/18/2004 | 1 | DDC IRELAND | | Y | SDC-14619IIT-114 | 594 |
| 5962-9205412HXC | B | 06/18/2004 | 1 | DDC IRELAND | | Y | SDC-14619IIT-134 | 594 |
| 5962-9205501HXA | B | 06/18/2004 | 1 | DDC | | Y | SDC-14613II-142 | 594 |
| 5962-9205501HXA | B | 06/18/2004 | 1 | DDC | | Y | SDC-14613II-152 | 594 |
| 5962-9205501HXA | B | 06/18/2004 | 1 | DDC IRELAND | | Y | SDC-14613II-142 | 594 |
| 5962-9205501HXA | B | 06/18/2004 | 1 | DDC IRELAND | | Y | SDC-14613II-152 | 594 |
| 5962-9205501HXC | B | 06/18/2004 | 1 | DDC | | Y | SDC-14613II-132 | 594 |
| 5962-9205501HXC | B | 06/18/2004 | 1 | DDC | | Y | SDC-14613II-112 | 594 |
| 5962-9205501HXC | B | 06/18/2004 | 1 | DDC IRELAND | | Y | SDC-14613II-112 | 594 |
| 5962-9205501HXC | B | 06/18/2004 | 1 | DDC IRELAND | | Y | SDC-14613II-132 | 594 |
| 5962-9205502HXA | B | 06/18/2004 | 1 | DDC | | Y | SDC-14613IIT-142 | 594 |
| 5962-9205502HXA | B | 06/18/2004 | 1 | DDC | | Y | SDC-14613IIT-152 | 594 |
| 5962-9205502HXA | B | 06/18/2004 | 1 | DDC IRELAND | | Y | SDC-14613IIT-142 | 594 |
| 5962-9205502HXA | B | 06/18/2004 | 1 | DDC IRELAND | | Y | SDC-14613IIT-152 | 594 |
| 5962-9205502HXC | B | 06/18/2004 | 1 | DDC | | Y | SDC-14613IIT-132 | 594 |
| 5962-9205502HXC | B | 06/18/2004 | 1 | DDC | | Y | SDC-14613IIT-112 | 594 |
| 5962-9205502HXC | B | 06/18/2004 | 1 | DDC IRELAND | | Y | SDC-14613IIT-112 | 594 |
| 5962-9205502HXC | B | 06/18/2004 | 1 | DDC IRELAND | | Y | SDC-14613IIT-132 | 594 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9205503HXA | B | 06/18/2004 | 1 | DDC | | Y | SDC-14618II-142 | 594 |
| 5962-9205503HXA | B | 06/18/2004 | 1 | DDC | | Y | SDC-14618II-152 | 594 |
| 5962-9205503HXA | B | 06/18/2004 | 1 | DDC IRELAND | | Y | SDC-14618II-152 | 594 |
| 5962-9205503HXA | B | 06/18/2004 | 1 | DDC IRELAND | | Y | SDC-14618II-142 | 594 |
| 5962-9205503HXC | B | 06/18/2004 | 1 | DDC | | Y | SDC-14618II-132 | 594 |
| 5962-9205503HXC | B | 06/18/2004 | 1 | DDC | | Y | SDC-14618II-112 | 594 |
| 5962-9205503HXC | B | 06/18/2004 | 1 | DDC IRELAND | | Y | SDC-14618II-112 | 594 |
| 5962-9205503HXC | B | 06/18/2004 | 1 | DDC IRELAND | | Y | SDC-14618II-132 | 594 |
| 5962-9205504HXA | B | 06/18/2004 | 1 | DDC | | Y | SDC-14618IIT-142 | 594 |
| 5962-9205504HXA | B | 06/18/2004 | 1 | DDC | | Y | SDC-14618IIT-152 | 594 |
| 5962-9205504HXA | B | 06/18/2004 | 1 | DDC IRELAND | | Y | SDC-14618IIT-152 | 594 |
| 5962-9205504HXA | B | 06/18/2004 | 1 | DDC IRELAND | | Y | SDC-14618IIT-142 | 594 |
| 5962-9205504HXC | B | 06/18/2004 | 1 | DDC | | Y | SDC-14618IIT-132 | 594 |
| 5962-9205504HXC | B | 06/18/2004 | 1 | DDC | | Y | SDC-14618IIT-112 | 594 |
| 5962-9205504HXC | B | 06/18/2004 | 1 | DDC IRELAND | | Y | SDC-14618IIT-132 | 594 |
| 5962-9205504HXC | B | 06/18/2004 | 1 | DDC IRELAND | | Y | SDC-14618IIT-112 | 594 |
| 5962-9205505HXA | B | 06/18/2004 | 1 | DDC | | Y | SDC-14618II-144 | 594 |
| 5962-9205505HXA | B | 06/18/2004 | 1 | DDC | | Y | SDC-14618II-154 | 594 |
| 5962-9205505HXA | B | 06/18/2004 | 1 | DDC IRELAND | | Y | SDC-14618II-144 | 594 |
| 5962-9205505HXA | B | 06/18/2004 | 1 | DDC IRELAND | | Y | SDC-14618II-154 | 594 |
| 5962-9205505HXC | B | 06/18/2004 | 1 | DDC | | Y | SDC-14618II-134 | 594 |
| 5962-9205505HXC | B | 06/18/2004 | 1 | DDC | | Y | SDC-14618II-114 | 594 |
| 5962-9205505HXC | B | 06/18/2004 | 1 | DDC IRELAND | | Y | SDC-14618II-134 | 594 |
| 5962-9205505HXC | B | 06/18/2004 | 1 | DDC IRELAND | | Y | SDC-14618II-114 | 594 |
| 5962-9205506HXA | B | 06/18/2004 | 1 | DDC | | Y | SDC-14618IIT-144 | 594 |
| 5962-9205506HXA | B | 06/18/2004 | 1 | DDC | | Y | SDC-14618IIT-154 | 594 |
| 5962-9205506HXA | B | 06/18/2004 | 1 | DDC IRELAND | | Y | SDC-14618IIT-154 | 594 |
| 5962-9205506HXA | B | 06/18/2004 | 1 | DDC IRELAND | | Y | SDC-14618IIT-144 | 594 |
| 5962-9205506HXC | B | 06/18/2004 | 1 | DDC | | Y | SDC-14618IIT-134 | 594 |
| 5962-9205506HXC | B | 06/18/2004 | 1 | DDC | | Y | SDC-14618IIT-114 | 594 |
| 5962-9205506HXC | B | 06/18/2004 | 1 | DDC IRELAND | | Y | SDC-14618IIT-114 | 594 |
| 5962-9205506HXC | B | 06/18/2004 | 1 | DDC IRELAND | | Y | SDC-14618IIT-134 | 594 |
| 5962-9205701MXA | | 07/30/1993 | | (NONE) | 10/28/1997 | | 72225LB50 (GEN) | 670 |
| 5962-9205701MYA | | 07/30/1993 | | (NONE) | 10/28/1997 | | 72225LB50 (GEN) | 670 |
| 5962-9205702MXA | | 07/30/1993 | | (NONE) | 10/28/1997 | | 72225LB35 (GEN) | 670 |
| 5962-9205702MYA | | 07/30/1993 | | (NONE) | 10/28/1997 | | 72225LB35 (GEN) | 670 |
| 5962-9205703MXA | | 07/30/1993 | | (NONE) | 10/28/1997 | | 72225LB25 (GEN) | 670 |
| 5962-9205703MYA | | 07/30/1993 | | (NONE) | 10/28/1997 | | 72225LB25 (GEN) | 670 |
| 5962-9205801MXA | L | 02/26/2002 | | (NONE) | | | 320C31-27 (GEN) | 432 |
| 5962-9205801MYA | L | 02/26/2002 | | (NONE) | | | 320C31-27 (GEN) | 432 |
| 5962-9205802QUC | L | 02/26/2002 | | (NONE) | 05/01/1998 | | 320C31 (GEN) | 432 |
| 5962-9205802MXA | L | 02/26/2002 | | (NONE) | 05/01/1998 | | 320C31 (GEN) | 432 |
| 5962-9205802MYA | L | 02/26/2002 | | (NONE) | 05/01/1998 | | 320C31 (GEN) | 432 |
| 5962-9205802QZC | L | 02/26/2002 | | (NONE) | 05/01/1998 | | 320C31 (GEN) | 432 |
| 5962-9205803Q9A | L | 02/26/2002 | | (NONE) | | | 320C31 (GEN) | 432 |
| 5962-9205803MXA | L | 02/26/2002 | 2 | TI | | Y | SMJ320C31GFAM40 | 432 |
| 5962-9205803MXC | L | 02/26/2002 | 2 | TI | | Y | SMJ320C31GFAM40 | 432 |
| 5962-9205803MYA | L | 02/26/2002 | 2 | TI | | Y | SMJ320C31HFGM40 | 432 |
| 5962-9205803QZC | L | 02/26/2002 | | (NONE) | | | 320C31 (GEN) | 432 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9205804MXA | L | 02/26/2002 | 2 | TI | | Y | SMJ320C31GFAM50 | 432 |
| 5962-9205804MXC | L | 02/26/2002 | 2 | TI | | Y | SMJ320C31GFAM50 | 432 |
| 5962-9205804MYA | L | 02/26/2002 | 2 | TI | | Y | SMJ320C31HFGM50 | 432 |
| 5962-9205805QXA | L | 02/26/2002 | 2 | TI | | Y | SMJ320C31GFAS60 | 432 |
| 5962-9205805QYA | L | 02/26/2002 | 2 | TI | | Y | SMJ320C31HFGS60 | 432 |
| 5962-9205901MXA | | 06/30/1992 | | (NONE) | 06/30/1996 | | SP8602 (GEN) | 319 |
| 5962-9206101HXA | F | 12/19/2003 | | (NONE) | | | MR63147M (GEN) | 590 |
| 5962-9206101HYA | F | 12/19/2003 | | (NONE) | | | MR63147M (GEN) | 590 |
| 5962-9206101HZA | F | 12/19/2003 | | (NONE) | | | MR63147M (GEN) | 590 |
| 5962-9206102HXA | F | 12/19/2003 | | (NONE) | | | MR63147M-2 (GEN) | 590 |
| 5962-9206102HYA | F | 12/19/2003 | | (NONE) | | | MR63147M-2 (GEN) | 590 |
| 5962-9206102HZA | F | 12/19/2003 | | (NONE) | | | MR63147M-2 (GEN) | 590 |
| 5962-9206103H4A | F | 12/19/2003 | 1 | NATIONAL HYB | | Y | NHI-1579/883 | 590 |
| 5962-9206103H4C | F | 12/19/2003 | 1 | NATIONAL HYB | | Y | NHI-1579/883 | 590 |
| 5962-9206103H5A | F | 12/19/2003 | 1 | NATIONAL HYB | | Y | NHI-1579FP/883 | 590 |
| 5962-9206103H5C | F | 12/19/2003 | 1 | NATIONAL HYB | | Y | NHI-1579FP/883 | 590 |
| 5962-9206103HMA | F | 12/19/2003 | 1 | NATIONAL HYB | | Y | NHI-1567/883 | 590 |
| 5962-9206103HMC | F | 12/19/2003 | 1 | NATIONAL HYB | | Y | NHI-1567/883 | 590 |
| 5962-9206103HNA | F | 12/19/2003 | 1 | NATIONAL HYB | | Y | NHI-1567FP/883 | 590 |
| 5962-9206103HNC | F | 12/19/2003 | 1 | NATIONAL HYB | | Y | NHI-1567FP/883 | 590 |
| 5962-9206103HTA | F | 12/19/2003 | 1 | NATIONAL HYB | | Y | NHI-1559/883 | 590 |
| 5962-9206103HTC | F | 12/19/2003 | 1 | NATIONAL HYB | | Y | NHI-1559/883 | 590 |
| 5962-9206103HUA | F | 12/19/2003 | 1 | NATIONAL HYB | | Y | NHI-1559FP/883 | 590 |
| 5962-9206103HUC | F | 12/19/2003 | 1 | NATIONAL HYB | | Y | NHI-1559FP/883 | 590 |
| 5962-9206103HZA | F | 12/19/2003 | 1 | NATIONAL HYB | | Y | NHI-1573FP/883 | 590 |
| 5962-9206103HZC | F | 12/19/2003 | 1 | NATIONAL HYB | | Y | NHI-1573FP/883 | 590 |
| 5962-9206104H4A | F | 12/19/2003 | 1 | NATIONAL HYB | | Y | NHI-1580/883 | 590 |
| 5962-9206104H4C | F | 12/19/2003 | 1 | NATIONAL HYB | | Y | NHI-1580/883 | 590 |
| 5962-9206104H5A | F | 12/19/2003 | 1 | NATIONAL HYB | | Y | NHI-1580FP/883 | 590 |
| 5962-9206104H5C | F | 12/19/2003 | 1 | NATIONAL HYB | | Y | NHI-1580FP/883 | 590 |
| 5962-9206104HMA | F | 12/19/2003 | 1 | NATIONAL HYB | | Y | NHI-1568/883 | 590 |
| 5962-9206104HMC | F | 12/19/2003 | 1 | NATIONAL HYB | | Y | NHI-1568/883 | 590 |
| 5962-9206104HNA | F | 12/19/2003 | 1 | NATIONAL HYB | | Y | NHI-1568FP/883 | 590 |
| 5962-9206104HNC | F | 12/19/2003 | 1 | NATIONAL HYB | | Y | NHI-1568FP/883 | 590 |
| 5962-9206104HTA | F | 12/19/2003 | 1 | NATIONAL HYB | | Y | NHI-1560/883 | 590 |
| 5962-9206104HTC | F | 12/19/2003 | 1 | NATIONAL HYB | | Y | NHI-1560/883 | 590 |
| 5962-9206104HUA | F | 12/19/2003 | 1 | NATIONAL HYB | | Y | NHI-1560FP/883 | 590 |
| 5962-9206104HUC | F | 12/19/2003 | 1 | NATIONAL HYB | | Y | NHI-1560FP/883 | 590 |
| 5962-9206104HZA | F | 12/19/2003 | 1 | NATIONAL HYB | | Y | NHI-1574FP/883 | 590 |
| 5962-9206104HZC | F | 12/19/2003 | 1 | NATIONAL HYB | | Y | NHI-1574FP/883 | 590 |
| 5962-9206105H4A | F | 12/19/2003 | 1 | NATIONAL HYB | | Y | NHI-1578/883 | 590 |
| 5962-9206105H4C | F | 12/19/2003 | 1 | NATIONAL HYB | | Y | NHI-1578/883 | 590 |
| 5962-9206105H5A | F | 12/19/2003 | 1 | NATIONAL HYB | | Y | NHI-1578FP/883 | 590 |
| 5962-9206105H5C | F | 12/19/2003 | 1 | NATIONAL HYB | | Y | NHI-1578FP/883 | 590 |
| 5962-9206105HMA | F | 12/19/2003 | 1 | NATIONAL HYB | | Y | NHI-1569/883 | 590 |
| 5962-9206105HMC | F | 12/19/2003 | 1 | NATIONAL HYB | | Y | NHI-1569/883 | 590 |
| 5962-9206105HNA | F | 12/19/2003 | 1 | NATIONAL HYB | | Y | NHI-1569FP/883 | 590 |
| 5962-9206105HNC | F | 12/19/2003 | 1 | NATIONAL HYB | | Y | NHI-1569FP/883 | 590 |
| 5962-9206105HTA | F | 12/19/2003 | 1 | NATIONAL HYB | | Y | NHI-1563/883 | 590 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9206105HTC | F | 12/19/2003 | 1 | NATIONAL HYB | | Y | NHI-1563/883 | 590 |
| 5962-9206105HUA | F | 12/19/2003 | 1 | NATIONAL HYB | | Y | NHI-1563FP/883 | 590 |
| 5962-9206105HUC | F | 12/19/2003 | 1 | NATIONAL HYB | | Y | NHI-1563FP/883 | 590 |
| 5962-9206105HZA | F | 12/19/2003 | 1 | NATIONAL HYB | | Y | NHI-1593FP/883 | 590 |
| 5962-9206105HZC | F | 12/19/2003 | 1 | NATIONAL HYB | | Y | NHI-1593FP/883 | 590 |
| 5962-9206106H4A | F | 12/19/2003 | 1 | NATIONAL HYB | | Y | NHI-1581/883 | 590 |
| 5962-9206106H4C | F | 12/19/2003 | 1 | NATIONAL HYB | | Y | NHI-1581/883 | 590 |
| 5962-9206106H5A | F | 12/19/2003 | 1 | NATIONAL HYB | | Y | NHI-1581FP/883 | 590 |
| 5962-9206106H5C | F | 12/19/2003 | 1 | NATIONAL HYB | | Y | NHI-1581FP/883 | 590 |
| 5962-9206106HMA | F | 12/19/2003 | 1 | NATIONAL HYB | | Y | NHI-1570/883 | 590 |
| 5962-9206106HMC | F | 12/19/2003 | 1 | NATIONAL HYB | | Y | NHI-1570/883 | 590 |
| 5962-9206106HNA | F | 12/19/2003 | 1 | NATIONAL HYB | | Y | NHI-1570FP/883 | 590 |
| 5962-9206106HNC | F | 12/19/2003 | 1 | NATIONAL HYB | | Y | NHI-1570FP/883 | 590 |
| 5962-9206106HTA | F | 12/19/2003 | 1 | NATIONAL HYB | | Y | NHI-1577/883 | 590 |
| 5962-9206106HTC | F | 12/19/2003 | 1 | NATIONAL HYB | | Y | NHI-1577/883 | 590 |
| 5962-9206106HUA | F | 12/19/2003 | 1 | NATIONAL HYB | | Y | NHI-1577FP/883 | 590 |
| 5962-9206106HUC | F | 12/19/2003 | 1 | NATIONAL HYB | | Y | NHI-1577FP/883 | 590 |
| 5962-9206106HZA | F | 12/19/2003 | 1 | NATIONAL HYB | | Y | NHI-1594FP/883 | 590 |
| 5962-9206106HZC | F | 12/19/2003 | 1 | NATIONAL HYB | | Y | NHI-1594FP/883 | 590 |
| 5962-9206107HZA | F | 12/19/2003 | 1 | AEROFLEX | | Y | ACT4458-201-2 | 590 |
| 5962-9206107HZC | F | 12/19/2003 | 1 | AEROFLEX | | Y | ACT4458-201-1 | 590 |
| 5962-9206108HZA | F | 12/19/2003 | 1 | AEROFLEX | | Y | ACT4464-201-2 | 590 |
| 5962-9206108HZC | F | 12/19/2003 | 1 | AEROFLEX | | Y | ACT4464-201-1 | 590 |
| 5962-9206109HZA | F | 12/19/2003 | 1 | AEROFLEX | | Y | ACT4460-201-2 | 590 |
| 5962-9206109HZC | F | 12/19/2003 | 1 | AEROFLEX | | Y | ACT4460-201-1 | 590 |
| 5962-9206110HZA | F | 12/19/2003 | 1 | AEROFLEX | | Y | ACT4454-201-2 | 590 |
| 5962-9206110HZC | F | 12/19/2003 | 1 | AEROFLEX | | Y | ACT4454-201-1 | 590 |
| 5962-9206201MXA | A | 08/10/1994 | 1 | QP SEMI | | Y | CY7C341-40HMB | 431 |
| 5962-9206201MYC | A | 08/10/1994 | 1 | QP SEMI | | Y | CY7C341-40RMB | 431 |
| 5962-9206201MZA | A | 08/10/1994 | | (NONE) | | | | 431 |
| 5962-9206202MXA | A | 08/10/1994 | 1 | QP SEMI | | Y | CY7C341-30HMB | 431 |
| 5962-9206202MYC | A | 08/10/1994 | 1 | CYPRESS | 05/03/2004 | Y | CY7C341-30RMB | 431 |
| 5962-9206202MYC | A | 08/10/1994 | 1 | QP SEMI | | Y | CY7C341-30RMB | 431 |
| 5962-9206202MZA | A | 08/10/1994 | | (NONE) | | | | 431 |
| 5962-9206203MXA | A | 08/10/1994 | 1 | CYPRESS | | Y | CY7C341-35HMB | 431 |
| 5962-9206203MXA | A | 08/10/1994 | 1 | QP SEMI | | Y | CY7C341-35HMB | 431 |
| 5962-9206203MYC | A | 08/10/1994 | 1 | QP SEMI | | Y | CY7C341-35RMB | 431 |
| 5962-9206501MXA | | 04/08/1994 | 2 | QP SEMI | | Y | CY7C287-65DMB | 663 |
| 5962-9206501MYA | | 04/08/1994 | 2 | QP SEMI | | Y | CY7C287-65LMB | 663 |
| 5962-9206502MXA | | 04/08/1994 | 2 | QP SEMI | | Y | CY7C287-55DMB | 663 |
| 5962-9206502MYA | | 04/08/1994 | 2 | QP SEMI | | Y | CY7C287-55LMB | 663 |
| 5962-9206601MXA | | 06/14/1993 | | NATIONAL | | Y | 100329DMQB | 547 |
| 5962-9206601MYA | | 06/14/1993 | | NATIONAL | | Y | 100329FMQB | 547 |
| 5962-9206901MXA | | 08/31/1993 | | (NONE) | | | | 670 |
| 5962-9206901MYA | | 08/31/1993 | | (NONE) | | | | 670 |
| 5962-9206902MXA | | 08/31/1993 | | (NONE) | | | | 670 |
| 5962-9206902MYA | | 08/31/1993 | | (NONE) | | | | 670 |
| 5962-9206903MXA | | 08/31/1993 | | (NONE) | | | | 670 |
| 5962-9206903MYA | | 08/31/1993 | | (NONE) | | | | 670 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9206904MXA | | 08/31/1993 | | (NONE) | | | | 670 |
| 5962-9206904MYA | | 08/31/1993 | | (NONE) | | | | 670 |
| 5962-9206905MXA | | 08/31/1993 | | (NONE) | | | | 670 |
| 5962-9206905MYA | | 08/31/1993 | | (NONE) | | | | 670 |
| 5962-9207101MXA | | 05/27/1994 | | (NONE) | | | 7C286-70 (GEN) | 663 |
| 5962-9207101MYA | | 05/27/1994 | | (NONE) | | | 7C286-70 (GEN) | 663 |
| 5962-9207102MXA | | 05/27/1994 | | (NONE) | | | 7C286-60 (GEN) | 663 |
| 5962-9207102MYA | | 05/27/1994 | | (NONE) | | | 7C286-60 (GEN) | 663 |
| 5962-9207301HXA | | 12/21/1992 | 1 | MICRO NETWKS | | Y | MN5100H/B | 592 |
| 5962-9207301HXC | | 12/21/1992 | 1 | MICRO NETWKS | | Y | MN5100H/B | 592 |
| 5962-9207302HXA | | 12/21/1992 | 1 | MICRO NETWKS | | Y | MN5101H/B | 592 |
| 5962-9207302HXC | | 12/21/1992 | 1 | MICRO NETWKS | | Y | MN5101H/B | 592 |
| 5962-9207501MXA | A | 09/08/1999 | 1 | AUSTIN SEMI. | | D | AS10H1042Q28/883C | 599 |
| 5962-9207501MYA | A | 09/08/1999 | | (NONE) | 09/30/1995 | | 10H1042 (GEN) | 599 |
| 5962-9207502MYA | A | 09/08/1999 | | (NONE) | | | 100H1042 (GEN) | 599 |
| 5962-9207801HTA | H | 04/09/2001 | 1 | WHITE ELEC. | | Y | WS512K8-120CQA | 629 |
| 5962-9207801HTC | H | 04/09/2001 | 1 | WHITE ELEC. | | Y | WS512K8-120CQ | 629 |
| 5962-9207801HXA | H | 04/09/2001 | 1 | WHITE ELEC. | | Y | WS-512K8-120CQA | 629 |
| 5962-9207801HXC | H | 04/09/2001 | 1 | WHITE ELEC. | | Y | WS-512K8-120CQ | 629 |
| 5962-9207801HYA | H | 04/09/2001 | | (NONE) | | | 512K8-120 (GEN) | 629 |
| 5962-9207802HTA | H | 04/09/2001 | 1 | WHITE ELEC. | | Y | WS512K8-100CQA | 629 |
| 5962-9207802HTC | H | 04/09/2001 | 1 | WHITE ELEC. | | Y | WS512K8-100CQ | 629 |
| 5962-9207802HXA | H | 04/09/2001 | 1 | WHITE ELEC. | | Y | WS-512K8-100CQA | 629 |
| 5962-9207802HXC | H | 04/09/2001 | 1 | WHITE ELEC. | | Y | WS-512K8-100CQ | 629 |
| 5962-9207802HYA | H | 04/09/2001 | | (NONE) | | | 512K8-100 (GEN) | 629 |
| 5962-9207803HTA | H | 04/09/2001 | 1 | WHITE ELEC. | | Y | WS512K8-85CQA | 629 |
| 5962-9207803HTC | H | 04/09/2001 | 1 | WHITE ELEC. | | Y | WS512K8-85CQ | 629 |
| 5962-9207803HXA | H | 04/09/2001 | 1 | WHITE ELEC. | | Y | WS-512K8-85CQA | 629 |
| 5962-9207803HXC | H | 04/09/2001 | 1 | WHITE ELEC. | | Y | WS-512K8-85CQ | 629 |
| 5962-9207803HYA | H | 04/09/2001 | | (NONE) | | | 512K8-85 (GEN) | 629 |
| 5962-9207804HTA | H | 04/09/2001 | 1 | WHITE ELEC. | | Y | WS512K8-70CQA | 629 |
| 5962-9207804HTC | H | 04/09/2001 | 1 | WHITE ELEC. | | Y | WS512K8-70CQ | 629 |
| 5962-9207804HXA | H | 04/09/2001 | 1 | WHITE ELEC. | | Y | WS-512K8-70CQA | 629 |
| 5962-9207804HXC | H | 04/09/2001 | 1 | WHITE ELEC. | | Y | WS-512K8-70CQ | 629 |
| 5962-9207804HYA | H | 04/09/2001 | | (NONE) | | | 512K8-70 (GEN) | 629 |
| 5962-9207805HTA | H | 04/09/2001 | 1 | WHITE ELEC. | | Y | WS512K8-55CQA | 629 |
| 5962-9207805HTC | H | 04/09/2001 | 1 | WHITE ELEC. | | Y | WS512K8-55CQ | 629 |
| 5962-9207805HXA | H | 04/09/2001 | 1 | WHITE ELEC. | | Y | WS-512K8-55CQA | 629 |
| 5962-9207805HXC | H | 04/09/2001 | 1 | WHITE ELEC. | | Y | WS-512K8-55CQ | 629 |
| 5962-9207805HYA | H | 04/09/2001 | | (NONE) | | | 512K8-55 (GEN) | 629 |
| 5962-9207806HTA | H | 04/09/2001 | 1 | WHITE ELEC. | | Y | WS512K8-45CQA | 629 |
| 5962-9207806HTC | H | 04/09/2001 | 1 | WHITE ELEC. | | Y | WS512K8-45CQ | 629 |
| 5962-9207806HXA | H | 04/09/2001 | 1 | WHITE ELEC. | | Y | WS-512K8-45CQA | 629 |
| 5962-9207806HXC | H | 04/09/2001 | 1 | WHITE ELEC. | | Y | WS-512K8-45CQ | 629 |
| 5962-9207806HYA | H | 04/09/2001 | | (NONE) | | | 512K8-45 (GEN) | 629 |
| 5962-9207807HTA | H | 04/09/2001 | 1 | WHITE ELEC. | | Y | WS512K8-35CQA | 629 |
| 5962-9207807HTC | H | 04/09/2001 | 1 | WHITE ELEC. | | Y | WS512K8-35CQ | 629 |
| 5962-9207807HXA | H | 04/09/2001 | 1 | WHITE ELEC. | | Y | WS-512K8-35CQA | 629 |
| 5962-9207807HXC | H | 04/09/2001 | 1 | WHITE ELEC. | | Y | WS-512K8-35CQ | 629 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9207807HYA | H | 04/09/2001 | | (NONE) | | | 512K8-35 (GEN) | 629 |
| 5962-9207808HTA | H | 04/09/2001 | 1 | WHITE ELEC. | | Y | WS512K8-25CQA | 629 |
| 5962-9207808HTC | H | 04/09/2001 | 1 | WHITE ELEC. | | Y | WS512K8-25CQ | 629 |
| 5962-9207808HXA | H | 04/09/2001 | 1 | WHITE ELEC. | | Y | WS-512K8-25CQA | 629 |
| 5962-9207808HXC | H | 04/09/2001 | 1 | WHITE ELEC. | | Y | WS-512K8-25CQ | 629 |
| 5962-9207808HYA | H | 04/09/2001 | | (NONE) | | | 512K8-25 (GEN) | 629 |
| 5962-9207809HTA | H | 04/09/2001 | 1 | WHITE ELEC. | | Y | WS512K8-20CQA | 529 |
| 5962-9207809HTC | H | 04/09/2001 | 1 | WHITE ELEC. | | Y | WS512K8-20CQ | 529 |
| 5962-9207809HXA | H | 04/09/2001 | 1 | WHITE ELEC. | | Y | WS-512K8-20CQA | 529 |
| 5962-9207809HXC | H | 04/09/2001 | 1 | WHITE ELEC. | | Y | WS-512K8-20CQ | 529 |
| 5962-9207809HYA | H | 04/09/2001 | | (NONE) | | | 512K8-20 (GEN) | 529 |
| 5962-9207901MPA | A | 02/24/1994 | | (NONE) | 12/31/2001 | | LT1172 (GEN) | 786 |
| 5962-9208001MPA | A | 12/14/2001 | | (NONE) | 12/31/2001 | | LTC485 (GEN) | 590 |
| 5962-9208401MXA | | 11/25/1992 | | (NONE) | 06/30/1996 | | SL531 (GEN) | 800 |
| 5962-9208501HXA | A | 03/17/1995 | 1 | NATIONAL HYB | | Y | NHI-1551 | 590 |
| 5962-9208501HXC | A | 03/17/1995 | 1 | NATIONAL HYB | | Y | NHI-1551 | 590 |
| 5962-9208501HYA | A | 03/17/1995 | 1 | NATIONAL HYB | | Y | NHI-1551FP | 590 |
| 5962-9208501HYC | A | 03/17/1995 | 1 | NATIONAL HYB | | Y | NHI-1551FP | 590 |
| 5962-9208502HXA | A | 03/17/1995 | 1 | AEROFLEX | | Y | ARX4451 | 590 |
| 5962-9208502HXC | A | 03/17/1995 | 1 | AEROFLEX | | Y | ARX4451 | 590 |
| 5962-9208502HYA | A | 03/17/1995 | 1 | AEROFLEX | | Y | ARX4451FP | 590 |
| 5962-9208502HYC | A | 03/17/1995 | 1 | AEROFLEX | | Y | ARX4451FP | 590 |
| 5962-9208503HXA | A | 03/17/1995 | 1 | AEROFLEX | | Y | ARX4418 | 590 |
| 5962-9208503HXC | A | 03/17/1995 | 1 | AEROFLEX | | Y | ARX4418 | 590 |
| 5962-9208503HYA | A | 03/17/1995 | 1 | AEROFLEX | | Y | ARX4418FP | 590 |
| 5962-9208503HYC | A | 03/17/1995 | 1 | AEROFLEX | | Y | ARX4418FP | 590 |
| 5962-9208504HXA | A | 03/17/1995 | 1 | NATIONAL HYB | | Y | NHI-1515 | 590 |
| 5962-9208504HXC | A | 03/17/1995 | 1 | NATIONAL HYB | | Y | NHI-1515 | 590 |
| 5962-9208504HYA | A | 03/17/1995 | 1 | NATIONAL HYB | | Y | NHI-1515FP | 590 |
| 5962-9208504HYC | A | 03/17/1995 | 1 | NATIONAL HYB | | Y | NHI-1515FP | 590 |
| 5962-9208505HXA | A | 03/17/1995 | 1 | CMAC MICRO. | | Y | FC155377 | 590 |
| 5962-9208505HXC | A | 03/17/1995 | 1 | CMAC MICRO. | | Y | FC155377 | 590 |
| 5962-9208505HYA | A | 03/17/1995 | 1 | CMAC MICRO. | | Y | FC155377FP | 590 |
| 5962-9208505HYC | A | 03/17/1995 | 1 | CMAC MICRO. | | Y | FC155377FP | 590 |
| 5962-9208801MCA | | 10/27/1992 | | (NONE) | 06/30/1996 | | SP8670 (GEN) | 319 |
| 5962-9208901MPA | | 04/28/1994 | | (NONE) | 12/31/2000 | | SP8782 (GEN) | 319 |
| 5962-9209001M3A | | 03/29/1993 | 2 | NATIONAL | | Y | 54F827LMQB | 529 |
| 5962-9209001MKA | | 03/29/1993 | | (NONE) | | | 54F827 (GEN) | 529 |
| 5962-9209001MLA | | 03/29/1993 | 2 | NATIONAL | 12/01/2004 | Y | 54F827SDMQB | 529 |
| 5962-9209301MCA | B | 09/03/1997 | | (NONE) | 09/06/2000 | | LMC660 (GEN) | 713 |
| 5962-9209302MCA | B | 09/03/1997 | | (NONE) | 03/09/1999 | | LPC660 (GEN) | 713 |
| 5962-9209303MCA | B | 09/03/1997 | 1 | NATIONAL | | Y | LMC6064AMJ/883 | 713 |
| 5962-9209401MPA | C | 02/10/2004 | | (NONE) | 03/09/1999 | | LMC662 (GEN) | 710 |
| 5962-9209402MPA | C | 02/10/2004 | | (NONE) | | | LPC662 (GEN) | 710 |
| 5962-9209403MPA | C | 02/10/2004 | 2 | NATIONAL | | Y | LMC6062AMJ/883 | 710 |
| 5962-9209701MXC | B | 03/30/1995 | | (NONE) | | | 43891GM-20 (GEN) | 805 |
| 5962-9209701MYA | B | 03/30/1995 | | (NONE) | | | 43891GM-20 (GEN) | 805 |
| 5962-9209702MXC | B | 03/30/1995 | | (NONE) | | | 43891GM-25 (GEN) | 805 |
| 5962-9209702MYA | B | 03/30/1995 | | (NONE) | | | 43981GM-25 (GEN) | 805 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9210101MXA | A | 01/11/1995 | | (NONE) | 10/28/1997 | | 72215LB50 (GEN) | 670 |
| 5962-9210101MYA | A | 01/11/1995 | | (NONE) | 10/28/1997 | | 72215LB50 (GEN) | 670 |
| 5962-9210102MXA | A | 01/11/1995 | | (NONE) | 10/28/1997 | | 72215LB35 (GEN) | 670 |
| 5962-9210102MYA | A | 01/11/1995 | | (NONE) | 10/28/1997 | | 72215LB35 (GEN) | 670 |
| 5962-9210103MXA | A | 01/11/1995 | | (NONE) | 10/28/1997 | | 72215LB25 (GEN) | 670 |
| 5962-9210103MYA | A | 01/11/1995 | | (NONE) | 10/28/1997 | | 72215LB25 (GEN) | 670 |
| 5962H9210301QZC | | 11/12/1992 | | (NONE) | 12/20/2001 | | FLP (GEN) | 409 |
| 5962H9210301VZC | | 11/12/1992 | | (NONE) | 12/20/2001 | | FLP (GEN) | 409 |
| 5962H9210401QZC | | 02/02/1993 | | (NONE) | 12/20/2001 | | AP1C-47 (GEN) | 429 |
| 5962H9210401VZC | | 02/02/1993 | | (NONE) | 12/20/2001 | | AP1C-47 (GEN) | 429 |
| 5962-9210501MLA | | 10/13/1992 | | (NONE) | 06/30/1995 | | EP224-15 (GEN) | 431 |
| 5962-9210502MLA | | 10/13/1992 | | (NONE) | 06/30/1995 | | EP224-12 (GEN) | 431 |
| 5962H9210601QZC | | 03/17/1993 | | (NONE) | 12/20/2001 | | IBMAP2-45 (GEN) | 429 |
| 5962H9210601VZC | | 03/17/1993 | | (NONE) | 12/20/2001 | | IBMAP2-45 (GEN) | 429 |
| 5962-9210901HZA | B | 08/27/2002 | 1 | ADV. ANALOG | | Y | ATW2812D/CH | 594 |
| 5962-9210902HZA | B | 08/27/2002 | 1 | ADV. ANALOG | | Y | ATW2812D/CH-SLV | 594 |
| 5962-9210903HZA | B | 08/27/2002 | 1 | ADV. ANALOG | | Y | ATW2812D/CH-MSTR | 594 |
| 5962-9211001HZA | A | 08/27/2002 | 1 | ADV. ANALOG | | Y | ATW2812S/CH | 594 |
| 5962-9211002HZA | A | 08/27/2002 | 1 | ADV. ANALOG | | Y | ATW2812S/CH-SLV | 594 |
| 5962-9211003HZA | A | 08/27/2002 | 1 | ADV. ANALOG | | Y | ATW2812S/CH-MSTR | 594 |
| 5962-9211101HXA | B | 05/25/2000 | 1 | ADV. ANALOG | | Y | AHF2812D/CH | 594 |
| 5962-9211101HXC | B | 05/25/2000 | 1 | ADV. ANALOG | | Y | AHF2812D/CH | 594 |
| 5962-9211101HZA | B | 05/25/2000 | 1 | ADV. ANALOG | | Y | AHF2812DF/CH | 594 |
| 5962-9211101HZC | B | 05/25/2000 | 1 | ADV. ANALOG | | Y | AHF2812DF/CH | 594 |
| 5962-9211201HZA | B | 08/28/2002 | 1 | ADV. ANALOG | | Y | AHV2812SF/CH | 594 |
| 5962-9211301HZA | B | 08/28/2002 | 1 | ADV. ANALOG | | Y | AHV2815SF/CH | 594 |
| 5962-9211401HZA | B | 08/30/2002 | 1 | ADV. ANALOG | | Y | AHV2812DF/CH | 594 |
| 5962-9211501HZA | C | 09/03/2002 | 1 | ADV. ANALOG | | Y | AHV2812TF/CH | 594 |
| 5962-9211601HZA | C | 03/16/1999 | 1 | ADV. ANALOG | | Y | AHV2815TF/CH | 594 |
| 5962-9211701M2A | C | 09/10/2001 | 1 | ANALOG (2) | | Y | AD827SE/883B | 710 |
| 5962-9211701MPA | C | 09/10/2001 | 1 | ANALOG (2) | | Y | AD827SQ/883B | 710 |
| 5962-9211801MXA | J | 03/15/2001 | | (NONE) | | | UT69151 (GEN) | 420 |
| 5962-9211801MYA | J | 03/15/2001 | | (NONE) | | | UT69151 (GEN) | 420 |
| 5962H9211802Q9A | J | 03/15/2001 | | (NONE) | | | UT69151E (GEN) | 420 |
| 5962H9211802V9A | J | 03/15/2001 | | (NONE) | | | UT69151E (GEN) | 420 |
| 5962H9211802QXA | J | 03/15/2001 | | (NONE) | | | UT69151E (GEN) | 420 |
| 5962H9211802VXA | J | 03/15/2001 | | (NONE) | | | UT69151E (GEN) | 420 |
| 5962H9211802QYA | J | 03/15/2001 | | (NONE) | | | UT69151E (GEN) | 420 |
| 5962H9211802VYA | J | 03/15/2001 | | (NONE) | | | UT69151E (GEN) | 420 |
| 5962H9211802QZA | J | 03/15/2001 | | (NONE) | | | UT69151E (GEN) | 420 |
| 5962H9211802VZA | J | 03/15/2001 | | (NONE) | | | UT69151E (GEN) | 420 |
| 5962-9211803QXA | J | 03/15/2001 | 1 | UTMC | | Y | UT69151EGBA | 420 |
| 5962-9211803QXC | J | 03/15/2001 | 1 | UTMC | | Y | UT69151EGBC | 420 |
| 5962-9211803QYA | J | 03/15/2001 | 1 | UTMC | | Y | UT69151EWBA | 420 |
| 5962-9211803QYC | J | 03/15/2001 | 1 | UTMC | | Y | UT69151EWBC | 420 |
| 5962-9211803QZA | J | 03/15/2001 | 1 | UTMC | | Y | UT69151EFBA | 420 |
| 5962-9211803QZC | J | 03/15/2001 | 1 | UTMC | | Y | UT69151EFBC | 420 |
| 5962F9211804Q9B | J | 03/15/2001 | 1 | UTMC | | Y | UT69151EQ-DIEF | 420 |
| 5962F9211804V9B | J | 03/15/2001 | 1 | UTMC | | Y | UT69151EV-DIEF | 420 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962R9211804Q9B | J | 03/15/2001 | 1 | UTMC | | Y | UT69151EQ-DIER | 420 |
| 5962R9211804V9B | J | 03/15/2001 | 1 | UTMC | | Y | UT69151EV-DIER | 420 |
| 5962F9211804QYA | J | 03/15/2001 | 1 | UTMC | | Y | UT69151EWCAF | 420 |
| 5962F9211804QYC | J | 03/15/2001 | 1 | UTMC | | Y | UT69151EWCCF | 420 |
| 5962F9211804VYA | J | 03/15/2001 | 1 | UTMC | | Y | UT69151EWCAF | 420 |
| 5962F9211804VYC | J | 03/15/2001 | 1 | UTMC | | Y | UT69151EWCCF | 420 |
| 5962R9211804QYA | J | 03/15/2001 | 1 | UTMC | | Y | UT69151EWCAR | 420 |
| 5962R9211804QYC | J | 03/15/2001 | 1 | UTMC | | Y | UT69151EWCCR | 420 |
| 5962R9211804VYA | J | 03/15/2001 | 1 | UTMC | | Y | UT69151EWCAR | 420 |
| 5962R9211804VYC | J | 03/15/2001 | 1 | UTMC | | Y | UT69151EWCCR | 420 |
| 5962-9212101M3A | | 11/24/1992 | | (NONE) | | | 20RA10 (GEN) | 431 |
| 5962-9212101MLA | | 11/24/1992 | | (NONE) | | | 20RA10 (GEN) | 431 |
| 5962-9212102M3A | | 11/24/1992 | | (NONE) | | | 20RA10 (GEN) | 431 |
| 5962-9212102MLA | | 11/24/1992 | | (NONE) | | | 20RA10 (GEN) | 431 |
| 5962-9212201MXA | B | 10/12/1993 | | (NONE) | 08/05/1996 | | 49C465A (GEN) | 355 |
| 5962-9212202MXA | B | 10/12/1993 | | (NONE) | 08/05/1996 | | 49C465 (GEN) | 355 |
| 5962-9212401MPA | A | 02/10/2004 | 1 | MAXIM INTEG. | | | MAX634MJA/883B | 786 |
| 5962-9212601MPA | C | 05/06/2004 | 1 | MAXIM INTEG. | | | MAX663MJA/883B | 789 |
| 5962-9212602MPA | C | 05/06/2004 | 1 | MAXIM INTEG. | | | MAX664MJA/883B | 789 |
| 5962-9212603MPA | C | 05/06/2004 | 1 | MAXIM INTEG. | | | MAX666MJA/883B | 789 |
| 5962-9212604MPA | C | 05/06/2004 | 1 | MAXIM INTEG. | | | MAX667MJA/883B | 789 |
| 5962-9212701MPA | B | 11/17/2000 | 1 | MAXIM INTEG. | | | MAX638AMJA/883B | 786 |
| 5962-9212702MPA | B | 11/17/2000 | 1 | MAXIM INTEG. | | | MAX638BMJA/883B | 786 |
| 5962-9212801MGA | | 12/23/1992 | | (NONE) | | | EL2019 (GEN) | 779 |
| 5962-9212801MPA | | 12/23/1992 | | (NONE) | | | EL2019 (GEN) | 779 |
| 5962-9212901MPA | A | 03/10/1994 | | (NONE) | 09/01/1997 | | 5212A (GEN) | 899 |
| 5962-9213201MVA | C | 07/28/1999 | | (NONE) | | | 4C4067-10 (GEN) | 623 |
| 5962-9213201MXA | C | 07/28/1999 | | (NONE) | | | 4C4067-10 (GEN) | 623 |
| 5962-9213201MYA | C | 07/28/1999 | | (NONE) | | | 4C4067-10 (GEN) | 623 |
| 5962-9213202MVA | C | 07/28/1999 | | (NONE) | | | 4C4067-12 (GEN) | 623 |
| 5962-9213202MXA | C | 07/28/1999 | | (NONE) | | | 4C4067-12 (GEN) | 623 |
| 5962-9213202MYA | C | 07/28/1999 | | (NONE) | | | 4C4067-12 (GEN) | 623 |
| 5962-9213203MVA | C | 07/28/1999 | | (NONE) | | | 4C4067-15 (GEN) | 623 |
| 5962-9213203MXA | C | 07/28/1999 | | (NONE) | | | 4C4067-15 (GEN) | 623 |
| 5962-9213203MYA | C | 07/28/1999 | | (NONE) | | | 4C4067-15 (GEN) | 623 |
| 5962-9213204MVA | C | 07/28/1999 | 1 | AUSTIN SEMI. | | Y | AS4C4067C-10/883C | 623 |
| 5962-9213204MXA | C | 07/28/1999 | 1 | AUSTIN SEMI. | | Y | AS4C4067EC-10/883C | 623 |
| 5962-9213204MYA | C | 07/28/1999 | 1 | AUSTIN SEMI. | | Y | AS4C4067EA-10/883C | 623 |
| 5962-9213205MVA | C | 07/28/1999 | 1 | AUSTIN SEMI. | | Y | AS4C4067C-12/883C | 623 |
| 5962-9213205MXA | C | 07/28/1999 | 1 | AUSTIN SEMI. | | Y | AS4C4067EC-12/883C | 623 |
| 5962-9213205MYA | C | 07/28/1999 | 1 | AUSTIN SEMI. | | Y | AS4C4067EA-12/883C | 623 |
| 5962-9213206MVA | C | 07/28/1999 | 1 | AUSTIN SEMI. | | Y | AS4C4067C-15/883C | 623 |
| 5962-9213206MXA | C | 07/28/1999 | 1 | AUSTIN SEMI. | | Y | AS4C4067EC-15/883C | 623 |
| 5962-9213206MYA | C | 07/28/1999 | 1 | AUSTIN SEMI. | | Y | AS4C4067EA-15/883C | 623 |
| 5962-9213801HXC | | 06/01/1993 | | (NONE) | | | 1006-341VR/2 (GEN) | 594 |
| 5962-9213802HXC | | 06/01/1993 | | (NONE) | | | 1006-341VS/2 (GEN) | 594 |
| 5962-9213803HXC | | 06/01/1993 | | (NONE) | | | 1006-341H/2 (GEN) | 594 |
| 5962-9213804HXC | | 06/01/1993 | | (NONE) | | | 1006-341S/2 (GEN) | 594 |
| 5962-9213901HXA | F | 08/23/2004 | 1 | INTERPOINT | | Y | MHF+2805S/883 | 594 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9213901HXC | F | 08/23/2004 | 1 | INTERPOINT | | Y | MHF+2805S/883 | 594 |
| 5962-9213901HZA | F | 08/23/2004 | 1 | INTERPOINT | | Y | MHF+2805SF/883 | 594 |
| 5962-9213901HZC | F | 08/23/2004 | 1 | INTERPOINT | | Y | MHF+2805SF/883 | 594 |
| 5962-9213902HXA | F | 08/23/2004 | 1 | INTERPOINT | | Y | SMHF2805S/HO | 594 |
| 5962-9213902HXC | F | 08/23/2004 | 1 | INTERPOINT | | Y | SMHF2805S/HO | 594 |
| 5962L9213902HXA | F | 08/23/2004 | 1 | INTERPOINT | | Y | SMHF2805S/HL | 594 |
| 5962L9213902HXC | F | 08/23/2004 | 1 | INTERPOINT | | Y | SMHF2805S/HL | 594 |
| 5962L9213902KXA | F | 08/23/2004 | 1 | INTERPOINT | | Y | SMHF2805S/KL | 594 |
| 5962L9213902KXC | F | 08/23/2004 | 1 | INTERPOINT | | Y | SMHF2805S/KL | 594 |
| 5962R9213902HXA | F | 08/23/2004 | 1 | INTERPOINT | | Y | SMHF2805S/HR | 594 |
| 5962R9213902HXC | F | 08/23/2004 | 1 | INTERPOINT | | Y | SMHF2805S/HR | 594 |
| 5962R9213902KXA | F | 08/23/2004 | 1 | INTERPOINT | | Y | SMHF2805S/KR | 594 |
| 5962R9213902KXC | F | 08/23/2004 | 1 | INTERPOINT | | Y | SMHF2805S/KR | 594 |
| 5962-9213902HZA | F | 08/23/2004 | 1 | INTERPOINT | | Y | SMHF2805SF/HO | 594 |
| 5962-9213902HZC | F | 08/23/2004 | 1 | INTERPOINT | | Y | SMHF2805SF/HO | 594 |
| 5962L9213902HZA | F | 08/23/2004 | 1 | INTERPOINT | | Y | SMHF2805SF/HL | 594 |
| 5962L9213902HZC | F | 08/23/2004 | 1 | INTERPOINT | | Y | SMHF2805SF/HL | 594 |
| 5962L9213902KZA | F | 08/23/2004 | 1 | INTERPOINT | | Y | SMHF2805SF/KL | 594 |
| 5962L9213902KZC | F | 08/23/2004 | 1 | INTERPOINT | | Y | SMHF2805SF/KL | 594 |
| 5962R9213902HZA | F | 08/23/2004 | 1 | INTERPOINT | | Y | SMHF2805SF/HR | 594 |
| 5962R9213902HZC | F | 08/23/2004 | 1 | INTERPOINT | | Y | SMHF2805SF/HR | 594 |
| 5962R9213902KZA | F | 08/23/2004 | 1 | INTERPOINT | | Y | SMHF2805SF/KR | 594 |
| 5962R9213902KZC | F | 08/23/2004 | 1 | INTERPOINT | | Y | SMHF2805SF/KR | 594 |
| 5962-9214001MQA | | 12/15/1992 | | (NONE) | | | 27C2048 (GEN) | 669 |
| 5962-9214001MXA | | 12/15/1992 | | (NONE) | | | 27C2048 (GEN) | 669 |
| 5962-9214002MQA | | 12/15/1992 | | (NONE) | | | 27C2048 (GEN) | 669 |
| 5962-9214002MXA | | 12/15/1992 | | (NONE) | | | 27C2048 (GEN) | 669 |
| 5962-9214003MQA | | 12/15/1992 | | (NONE) | | | 27C2048 (GEN) | 669 |
| 5962-9214003MXA | | 12/15/1992 | | (NONE) | | | 27C2048 (GEN) | 669 |
| 5962-9214101MPA | A | 09/10/2001 | 1 | MAXIM INTEG. | | | MAX631AMJA/883B | 786 |
| 5962-9214102MPA | A | 09/10/2001 | 1 | MAXIM INTEG. | | | MAX631BMJA/883B | 786 |
| 5962-9214103MPA | A | 09/10/2001 | 1 | MAXIM INTEG. | | | MAX632AMJA/883B | 786 |
| 5962-9214104MPA | A | 09/10/2001 | 1 | MAXIM INTEG. | | | MAX632BMJA/883B | 786 |
| 5962-9214105MPA | A | 09/10/2001 | 1 | MAXIM INTEG. | | | MAX633AMJA/883B | 786 |
| 5962-9214106MPA | A | 09/10/2001 | 1 | MAXIM INTEG. | | | MAX633BMJA/883B | 786 |
| 5962-9214401HXA | J | 11/06/2003 | 1 | INTERPOINT | | Y | MHF+2812D/883 | 594 |
| 5962-9214401HXC | J | 11/06/2003 | 1 | INTERPOINT | | Y | MHF+2812D/883 | 594 |
| 5962-9214401HYA | J | 11/06/2003 | | (NONE) | | | MHF+2812D (GEN) | 594 |
| 5962-9214401HZA | J | 11/06/2003 | 1 | INTERPOINT | | Y | MHF+2812DF/883 | 594 |
| 5962-9214401HZC | J | 11/06/2003 | 1 | INTERPOINT | | Y | MHF+2812DF/883 | 594 |
| 5962-9214402HXA | J | 11/06/2003 | 1 | INTERPOINT | | Y | SMHF2812D/HO | 594 |
| 5962-9214402HXC | J | 11/06/2003 | 1 | INTERPOINT | | Y | SMHF2812D/HO | 594 |
| 5962L9214402HXA | J | 11/06/2003 | 1 | INTERPOINT | | Y | SMHF2812D/HL | 594 |
| 5962L9214402HXC | J | 11/06/2003 | 1 | INTERPOINT | | Y | SMHF2812D/HL | 594 |
| 5962L9214402KXA | J | 11/06/2003 | 1 | INTERPOINT | | Y | SMHF2812D/KL | 594 |
| 5962L9214402KXC | J | 11/06/2003 | 1 | INTERPOINT | | Y | SMHF2812D/KL | 594 |
| 5962R9214402HXA | J | 11/06/2003 | 1 | INTERPOINT | | Y | SMHF2812D/HR | 594 |
| 5962R9214402HXC | J | 11/06/2003 | 1 | INTERPOINT | | Y | SMHF2812D/HR | 594 |
| 5962R9214402KXA | J | 11/06/2003 | 1 | INTERPOINT | | Y | SMHF2812D/KR | 594 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962R9214402KXC | J | 11/06/2003 | 1 | INTERPOINT | | Y | SMHF2812D/KR | 594 |
| 5962-9214402HZA | J | 11/06/2003 | 1 | INTERPOINT | | Y | SMHF2812DF/HO | 594 |
| 5962-9214402HZC | J | 11/06/2003 | 1 | INTERPOINT | | Y | SMHF2812DF/HO | 594 |
| 5962L9214402HZA | J | 11/06/2003 | 1 | INTERPOINT | | Y | SMHF2812DF/HL | 594 |
| 5962L9214402HZC | J | 11/06/2003 | 1 | INTERPOINT | | Y | SMHF2812DF/HL | 594 |
| 5962L9214402KZA | J | 11/06/2003 | 1 | INTERPOINT | | Y | SMHF2812DF/KL | 594 |
| 5962L9214402KZC | J | 11/06/2003 | 1 | INTERPOINT | | Y | SMHF2812DF/KL | 594 |
| 5962R9214402HZA | J | 11/06/2003 | 1 | INTERPOINT | | Y | SMHF2812DF/HR | 594 |
| 5962R9214402HZC | J | 11/06/2003 | 1 | INTERPOINT | | Y | SMHF2812DF/HR | 594 |
| 5962R9214402KZA | J | 11/06/2003 | 1 | INTERPOINT | | Y | SMHF2812DF/KR | 594 |
| 5962R9214402KZC | J | 11/06/2003 | 1 | INTERPOINT | | Y | SMHF2812DF/KR | 594 |
| 5962-9214701M2A | B | 09/09/1998 | 3 | TI | | Y | SNJ54ABT244FK | 529 |
| 5962-9214701Q2A | B | 09/09/1998 | 2 | NATIONAL | | Y | 54ABT244E-QML | 529 |
| 5962-9214701V2A | B | 09/09/1998 | 1 | NATIONAL | | Y | 54ABT244E-QMLV | 529 |
| 5962-9214701MRA | B | 09/09/1998 | 3 | TI | | Y | SNJ54ABT244J | 529 |
| 5962-9214701QRA | B | 09/09/1998 | 2 | NATIONAL | | Y | 54ABT244J-QML | 529 |
| 5962-9214701VRA | B | 09/09/1998 | 1 | NATIONAL | | Y | 54ABT244J-QMLV | 529 |
| 5962-9214701MSA | B | 09/09/1998 | 3 | TI | | Y | SNJ54ABT244W | 529 |
| 5962-9214701QSA | B | 09/09/1998 | 2 | NATIONAL | | Y | 54ABT244W-QML | 529 |
| 5962-9214701VSA | B | 09/09/1998 | 1 | NATIONAL | | Y | 54ABT244W-QMLV | 529 |
| 5962-9214801M2A | D | 11/24/1999 | | (NONE) | 06/01/1997 | | 54ABT245 (GEN) | 590 |
| 5962-9214801Q2A | D | 11/24/1999 | 2 | NATIONAL | | Y | 54ABT245E-QML | 590 |
| 5962-9214801MRA | D | 11/24/1999 | | (NONE) | 06/01/1997 | | 54ABT245 (GEN) | 590 |
| 5962-9214801QRA | D | 11/24/1999 | 2 | NATIONAL | | Y | 54ABT245J-QML | 590 |
| 5962-9214801MSA | D | 11/24/1999 | | (NONE) | | | 54ABT245 (GEN) | 590 |
| 5962-9214801QSA | D | 11/24/1999 | 2 | NATIONAL | | Y | 54ABT245W-QML | 590 |
| 5962-9214802Q2A | D | 11/24/1999 | 2 | TI | | Y | SNJ54ABT245AFK | 590 |
| 5962-9214802QRA | D | 11/24/1999 | 2 | TI | | Y | SNJ54ABT245AJ | 590 |
| 5962-9214802QSA | D | 11/24/1999 | 2 | TI | | Y | SNJ54ABT245AW | 590 |
| 5962-9215201HXA | B | 05/28/2004 | | (NONE) | | | PA21 (GEN) | 710 |
| 5962-9215202GXA | B | 05/28/2004 | 1 | MS KENNEDY | | Y | MSK 184G | 710 |
| 5962-9215202GXC | B | 05/28/2004 | 1 | MS KENNEDY | | Y | MSK 184G | 710 |
| 5962H9215301QNC | L | 10/17/2000 | 2 | BAE SYSTEMS | | Y | LOR2568C-Q60I | 623 |
| 5962H9215301VNC | L | 10/17/2000 | 2 | BAE SYSTEMS | | Y | LOR2568C-V60I | 623 |
| 5962H9215301QXC | L | 10/17/2000 | 2 | BAE SYSTEMS | | Y | LOR2568C-Q60X | 623 |
| 5962H9215301VXC | L | 10/17/2000 | 2 | BAE SYSTEMS | | Y | LOR2568C-V60X | 623 |
| 5962H9215301QYC | L | 10/17/2000 | 2 | BAE SYSTEMS | | Y | LOR2568C-Q60Y | 623 |
| 5962H9215301VYC | L | 10/17/2000 | 2 | BAE SYSTEMS | | Y | LOR2568C-V60Y | 623 |
| 5962H9215302QNC | L | 10/17/2000 | 2 | BAE SYSTEMS | | Y | LOR2568T-Q60I | 623 |
| 5962H9215302VNC | L | 10/17/2000 | 2 | BAE SYSTEMS | | Y | LOR2568T-V60I | 623 |
| 5962H9215302QXC | L | 10/17/2000 | 2 | BAE SYSTEMS | | Y | LOR2568T-Q60X | 623 |
| 5962H9215302VXC | L | 10/17/2000 | 2 | BAE SYSTEMS | | Y | LOR2568T-V60X | 623 |
| 5962H9215302QYC | L | 10/17/2000 | 2 | BAE SYSTEMS | | Y | LOR2568T-Q60Y | 623 |
| 5962H9215302VYC | L | 10/17/2000 | 2 | BAE SYSTEMS | | Y | LOR2568T-V60Y | 623 |
| 5962H9215302QZA | L | 10/17/2000 | | (NONE) | | | 2568T60 (GEN) | 623 |
| 5962H9215302VZA | L | 10/17/2000 | | (NONE) | | | 2568T60 (GEN) | 623 |
| 5962H9215303QMA | L | 10/17/2000 | 2 | UTMC | | Y | UT7156C40PCAH | 623 |
| 5962H9215303QMC | L | 10/17/2000 | 2 | UTMC | | Y | UT7156C40PCCH | 623 |
| 5962H9215303VMA | L | 10/17/2000 | 2 | UTMC | | Y | UT7156C40PCAH | 623 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962H9215303VMC | L | 10/17/2000 | 2 | UTMC | | Y | UT7156C40PCCH | 623 |
| 5962H9215303QNC | L | 10/17/2000 | 2 | BAE SYSTEMS | | Y | LOR2568C-Q40I | 623 |
| 5962H9215303VNC | L | 10/17/2000 | 2 | BAE SYSTEMS | | Y | LOR2568C-V40I | 623 |
| 5962H9215303QTA | L | 10/17/2000 | 2 | UTMC | | Y | UT7156C40WCAH | 623 |
| 5962H9215303QTC | L | 10/17/2000 | 2 | UTMC | | Y | UT7156C40WCCH | 623 |
| 5962H9215303VTA | L | 10/17/2000 | 2 | UTMC | | Y | UT7156C40WCAH | 623 |
| 5962H9215303VTC | L | 10/17/2000 | 2 | UTMC | | Y | UT7156C40WCCH | 623 |
| 5962H9215303QXC | L | 10/17/2000 | 2 | BAE SYSTEMS | | Y | LOR2568C-Q40X | 623 |
| 5962H9215303VXC | L | 10/17/2000 | 2 | BAE SYSTEMS | | Y | LOR2568C-V40X | 623 |
| 5962H9215303QYC | L | 10/17/2000 | 2 | BAE SYSTEMS | | Y | LOR2568C-Q40Y | 623 |
| 5962H9215303VYC | L | 10/17/2000 | 2 | BAE SYSTEMS | | Y | LOR2568C-V40Y | 623 |
| 5962H9215303QZA | L | 10/17/2000 | | (NONE) | | | 2568C40 (GEN) | 623 |
| 5962H9215303VZA | L | 10/17/2000 | | (NONE) | | | 2568C40 (GEN) | 623 |
| 5962H9215304QNC | L | 10/17/2000 | 2 | BAE SYSTEMS | | Y | LOR2568T-Q40I | 623 |
| 5962H9215304VNC | L | 10/17/2000 | 2 | BAE SYSTEMS | | Y | LOR2568T-V40I | 623 |
| 5962H9215304QXC | L | 10/17/2000 | 2 | BAE SYSTEMS | | Y | LOR2568T-Q40X | 623 |
| 5962H9215304VXC | L | 10/17/2000 | 2 | BAE SYSTEMS | | Y | LOR2568T-V40X | 623 |
| 5962H9215304QYC | L | 10/17/2000 | 2 | BAE SYSTEMS | | Y | LOR2568T-Q40Y | 623 |
| 5962H9215304VYC | L | 10/17/2000 | 2 | BAE SYSTEMS | | Y | LOR2568T-V40Y | 623 |
| 5962H9215304QZA | L | 10/17/2000 | | (NONE) | | | 2568T40 (GEN) | 623 |
| 5962H9215304VZA | L | 10/17/2000 | | (NONE) | | | 2568T40 (GEN) | 623 |
| 5962H9215305Q4C | L | 10/17/2000 | | (NONE) | 06/30/1999 | | 6856 (GEN) | 623 |
| 5962H9215305V4C | L | 10/17/2000 | | (NONE) | 06/30/1999 | | 6856 (GEN) | 623 |
| 5962R9215305Q4C | L | 10/17/2000 | | (NONE) | 06/30/1999 | | 6856 (GEN) | 623 |
| 5962R9215305V4C | L | 10/17/2000 | | (NONE) | 06/30/1999 | | 6856 (GEN) | 623 |
| 5962H9215305Q9C | L | 10/17/2000 | | (NONE) | 06/30/1999 | | 6856 (GEN) | 623 |
| 5962H9215305V9C | L | 10/17/2000 | | (NONE) | 06/30/1999 | | 6856 (GEN) | 623 |
| 5962H9215305QMC | L | 10/17/2000 | | (NONE) | 06/30/1999 | | 6856 (GEN) | 623 |
| 5962H9215305VMC | L | 10/17/2000 | | (NONE) | 06/30/1999 | | 6856 (GEN) | 623 |
| 5962H9215305QUC | L | 10/17/2000 | | (NONE) | 06/30/1999 | | 6856 (GEN) | 623 |
| 5962H9215305VUC | L | 10/17/2000 | | (NONE) | 06/30/1999 | | 6856 (GEN) | 623 |
| 5962R9215305QUC | L | 10/17/2000 | | (NONE) | 06/30/1999 | | 6856 (GEN) | 623 |
| 5962R9215305VUC | L | 10/17/2000 | | (NONE) | 06/30/1999 | | 6856 (GEN) | 623 |
| 5962H9215305QZC | L | 10/17/2000 | | (NONE) | 06/30/1999 | | 6856 (GEN) | 623 |
| 5962H9215305VZC | L | 10/17/2000 | | (NONE) | 06/30/1999 | | 6856 (GEN) | 623 |
| 5962R9215305QZC | L | 10/17/2000 | | (NONE) | 06/30/1999 | | 6856 (GEN) | 623 |
| 5962R9215305VZC | L | 10/17/2000 | | (NONE) | 06/30/1999 | | 6856 (GEN) | 623 |
| 5962H9215306Q9C | L | 10/17/2000 | | (NONE) | 06/30/1999 | | 6856 (GEN) | 623 |
| 5962H9215306V9C | L | 10/17/2000 | | (NONE) | 06/30/1999 | | 6856 (GEN) | 623 |
| 5962H9215306QMC | L | 10/17/2000 | | (NONE) | 06/30/1999 | | 6856 (GEN) | 623 |
| 5962H9215306VMC | L | 10/17/2000 | | (NONE) | 06/30/1999 | | 6856 (GEN) | 623 |
| 5962H9215306QUC | L | 10/17/2000 | | (NONE) | 06/30/1999 | | 6856 (GEN) | 623 |
| 5962H9215306VUC | L | 10/17/2000 | | (NONE) | 06/30/1999 | | 6856 (GEN) | 623 |
| 5962R9215306QUC | L | 10/17/2000 | | (NONE) | 06/30/1999 | | 6856 (GEN) | 623 |
| 5962R9215306VUC | L | 10/17/2000 | | (NONE) | 06/30/1999 | | 6856 (GEN) | 623 |
| 5962H9215306QZC | L | 10/17/2000 | | (NONE) | 06/30/1999 | | 6856 (GEN) | 623 |
| 5962H9215306VZC | L | 10/17/2000 | | (NONE) | 06/30/1999 | | 6856 (GEN) | 623 |
| 5962R9215306QZC | L | 10/17/2000 | | (NONE) | 06/30/1999 | | 6856 (GEN) | 623 |
| 5962R9215306VZC | L | 10/17/2000 | | (NONE) | 06/30/1999 | | 6856 (GEN) | 623 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962H9215307Q4C | L | 10/17/2000 | | (NONE) | 06/30/1999 | | 6856 (GEN) | 623 |
| 5962H9215307V4C | L | 10/17/2000 | | (NONE) | 06/30/1999 | | 6856 (GEN) | 623 |
| 5962R9215307Q4C | L | 10/17/2000 | | (NONE) | 06/30/1999 | | 6856 (GEN) | 623 |
| 5962R9215307V4C | L | 10/17/2000 | | (NONE) | 06/30/1999 | | 6856 (GEN) | 623 |
| 5962H9215307Q9C | L | 10/17/2000 | | (NONE) | 06/30/1999 | | 6856 (GEN) | 623 |
| 5962H9215307V9C | L | 10/17/2000 | | (NONE) | 06/30/1999 | | 6856 (GEN) | 623 |
| 5962H9215307QMC | L | 10/17/2000 | | (NONE) | 06/30/1999 | | 6856 (GEN) | 623 |
| 5962H9215307VMC | L | 10/17/2000 | | (NONE) | 06/30/1999 | | 6856 (GEN) | 623 |
| 5962H9215307QUC | L | 10/17/2000 | | (NONE) | 06/30/1999 | | 6856 (GEN) | 623 |
| 5962H9215307VUC | L | 10/17/2000 | | (NONE) | 06/30/1999 | | 6856 (GEN) | 623 |
| 5962R9215307QUC | L | 10/17/2000 | | (NONE) | 06/30/1999 | | 6856 (GEN) | 623 |
| 5962R9215307VUC | L | 10/17/2000 | | (NONE) | 06/30/1999 | | 6856 (GEN) | 623 |
| 5962H9215307QZC | L | 10/17/2000 | | (NONE) | 06/30/1999 | | 6856 (GEN) | 623 |
| 5962H9215307VZC | L | 10/17/2000 | | (NONE) | 06/30/1999 | | 6856 (GEN) | 623 |
| 5962R9215307QZC | L | 10/17/2000 | | (NONE) | 06/30/1999 | | 6856 (GEN) | 623 |
| 5962R9215307VZC | L | 10/17/2000 | | (NONE) | 06/30/1999 | | 6856 (GEN) | 623 |
| 5962H9215308Q9C | L | 10/17/2000 | | (NONE) | 06/30/1999 | | 6856 (GEN) | 623 |
| 5962H9215308V9C | L | 10/17/2000 | | (NONE) | 06/30/1999 | | 6856 (GEN) | 623 |
| 5962H9215308QMC | L | 10/17/2000 | | (NONE) | 06/30/1999 | | 6856 (GEN) | 623 |
| 5962H9215308VMC | L | 10/17/2000 | | (NONE) | 06/30/1999 | | 6856 (GEN) | 623 |
| 5962H9215308QUC | L | 10/17/2000 | | (NONE) | 06/30/1999 | | 6856 (GEN) | 623 |
| 5962H9215308VUC | L | 10/17/2000 | | (NONE) | 06/30/1999 | | 6856 (GEN) | 623 |
| 5962R9215308QUC | L | 10/17/2000 | | (NONE) | 06/30/1999 | | 6856 (GEN) | 623 |
| 5962R9215308VUC | L | 10/17/2000 | | (NONE) | 06/30/1999 | | 6856 (GEN) | 623 |
| 5962H9215308QZC | L | 10/17/2000 | | (NONE) | 06/30/1999 | | 6856 (GEN) | 623 |
| 5962H9215308VZC | L | 10/17/2000 | | (NONE) | 06/30/1999 | | 6856 (GEN) | 623 |
| 5962R9215308QZC | L | 10/17/2000 | | (NONE) | 06/30/1999 | | 6856 (GEN) | 623 |
| 5962R9215308VZC | L | 10/17/2000 | | (NONE) | 06/30/1999 | | 6856 (GEN) | 623 |
| 5962H9215309QMA | L | 10/17/2000 | 2 | UTMC | | Y | UT7156C55PBAH | 623 |
| 5962H9215309QMC | L | 10/17/2000 | 2 | UTMC | | Y | UT7156C55PBCH | 623 |
| 5962R9215309QMA | L | 10/17/2000 | 1 | UTMC | | Y | UT7156C55PBAR | 623 |
| 5962R9215309QMC | L | 10/17/2000 | 1 | UTMC | | Y | UT7156C55PBCR | 623 |
| 5962H9215310QMA | L | 10/17/2000 | 2 | UTMC | | Y | UT7156T55PBAH | 623 |
| 5962H9215310QMC | L | 10/17/2000 | 2 | UTMC | | Y | UT7156T55PBCH | 623 |
| 5962R9215310QMA | L | 10/17/2000 | 1 | UTMC | | Y | UT7156T55PBAR | 623 |
| 5962R9215310QMC | L | 10/17/2000 | 1 | UTMC | | Y | UT7156T55PBCR | 623 |
| 5962H9215311QTA | L | 10/17/2000 | 2 | UTMC | | Y | UT7156C55WBAH | 623 |
| 5962H9215311QTC | L | 10/17/2000 | 2 | UTMC | | Y | UT7156C55WBCH | 623 |
| 5962R9215311QTA | L | 10/17/2000 | 1 | UTMC | | Y | UT7156C55WBAR | 623 |
| 5962R9215311QTC | L | 10/17/2000 | 1 | UTMC | | Y | UT7156C55WBCR | 623 |
| 5962H9215312QTA | L | 10/17/2000 | 2 | UTMC | | Y | UT7156T55WBAH | 623 |
| 5962H9215312QTC | L | 10/17/2000 | 2 | UTMC | | Y | UT7156T55WBCH | 623 |
| 5962R9215312QTA | L | 10/17/2000 | 1 | UTMC | | Y | UT7156T55WBAR | 623 |
| 5962R9215312QTC | L | 10/17/2000 | 1 | UTMC | | Y | UT7156T55WBCR | 623 |
| 5962H9215313QNC | L | 10/17/2000 | 2 | BAE SYSTEMS | | Y | LOR2568C-Q30I | 623 |
| 5962H9215313VNC | L | 10/17/2000 | 2 | BAE SYSTEMS | | Y | LOR2568C-V30I | 623 |
| 5962H9215313QXC | L | 10/17/2000 | 2 | BAE SYSTEMS | | Y | LOR2568C-Q30X | 623 |
| 5962H9215313VXC | L | 10/17/2000 | 2 | BAE SYSTEMS | | Y | LOR2568C-V30X | 623 |
| 5962H9215313QYC | L | 10/17/2000 | 2 | BAE SYSTEMS | | Y | LOR2568C-Q30Y | 623 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962H9215313VYC | L | 10/17/2000 | 2 | BAE SYSTEMS | | Y | LOR2568C-V30Y | 623 |
| 5962H9215314QNC | L | 10/17/2000 | 2 | BAE SYSTEMS | | Y | LOR2568T-Q30I | 623 |
| 5962H9215314VNC | L | 10/17/2000 | 2 | BAE SYSTEMS | | Y | LOR2568T-V30I | 623 |
| 5962H9215314QXC | L | 10/17/2000 | 2 | BAE SYSTEMS | | Y | LOR2568T-Q30X | 623 |
| 5962H9215314VXC | L | 10/17/2000 | 2 | BAE SYSTEMS | | Y | LOR2568T-V30X | 623 |
| 5962H9215314QYC | L | 10/17/2000 | 2 | BAE SYSTEMS | | Y | LOR2568T-Q30Y | 623 |
| 5962H9215314VYC | L | 10/17/2000 | 2 | BAE SYSTEMS | | Y | LOR2568T-V30Y | 623 |
| 5962R9215315QMA | L | 10/17/2000 | 1 | UTMC | | Y | UT7156C70PBAR | 623 |
| 5962R9215315QMC | L | 10/17/2000 | 1 | UTMC | | Y | UT7156C70PBCR | 623 |
| 5962R9215316QMA | L | 10/17/2000 | 1 | UTMC | | Y | UT7156T70PBAR | 623 |
| 5962R9215316QMC | L | 10/17/2000 | 1 | UTMC | | Y | UT7156T70PBCR | 623 |
| 5962R9215317QTA | L | 10/17/2000 | 1 | UTMC | | Y | UT7156C70WBAR | 623 |
| 5962R9215317QTC | L | 10/17/2000 | 1 | UTMC | | Y | UT7156C70WBCR | 623 |
| 5962R9215318QTA | L | 10/17/2000 | 1 | UTMC | | Y | UT7156T70WBAR | 623 |
| 5962R9215318QTC | L | 10/17/2000 | 1 | UTMC | | Y | UT7156T70WBCR | 623 |
| 5962H9215319QZC | L | 10/17/2000 | 2 | HONEYWELL (1) | | Y | HC6856/1XQHCC | 623 |
| 5962H9215319VZC | L | 10/17/2000 | 2 | HONEYWELL (1) | | Y | HC6856/1XVHCC | 623 |
| 5962H9215401QXC | A | 07/05/2001 | | (NONE) | 12/20/2001 | | IBM6401C-55 (GEN) | 620 |
| 5962H9215401VXC | A | 07/05/2001 | | (NONE) | 12/20/2001 | | IBM6401C-55 (GEN) | 620 |
| 5962H9215401QYC | A | 07/05/2001 | | (NONE) | 12/20/2001 | | IBM6401C-55 (GEN) | 620 |
| 5962H9215401VYC | A | 07/05/2001 | | (NONE) | 12/20/2001 | | IBM6401C-55 (GEN) | 620 |
| 5962H9215402QXC | A | 07/05/2001 | | (NONE) | 12/20/2001 | | IBM6401T-55 (GEN) | 620 |
| 5962H9215402VXC | A | 07/05/2001 | | (NONE) | 12/20/2001 | | IBM6401T-55 (GEN) | 620 |
| 5962H9215402QYC | A | 07/05/2001 | | (NONE) | 12/20/2001 | | IBM6401T-55 (GEN) | 620 |
| 5962H9215402VYC | A | 07/05/2001 | | (NONE) | 12/20/2001 | | IBM6401T-55 (GEN) | 620 |
| 5962-9215501MXA | | 03/19/1993 | 2 | QP SEMI | | Y | CY7C277-50DMB | 662 |
| 5962-9215501MYA | | 03/19/1993 | 2 | QP SEMI | | Y | CY7C277-50LMB | 662 |
| 5962-9215501MZA | | 03/19/1993 | 2 | QP SEMI | | Y | CY7C277-50KMB | 662 |
| 5962-9215502MXA | | 03/19/1993 | 2 | QP SEMI | | Y | CY7C277-40DMB | 662 |
| 5962-9215502MYA | | 03/19/1993 | 2 | QP SEMI | | Y | CY7C277-40LMB | 662 |
| 5962-9215502MZA | | 03/19/1993 | 2 | QP SEMI | | Y | CY7C277-40KMB | 662 |
| 5962-9215601Q9A | H | 04/28/2000 | 1 | ACTEL | | Y | A1280A-DIE | 431 |
| 5962-9215601Q9B | H | 04/28/2000 | 1 | ACTEL | | Y | A1280A-DIE | 431 |
| 5962-9215601MUC | H | 04/28/2000 | | (NONE) | | | 1280 (GEN) | 431 |
| 5962-9215601MXA | H | 04/28/2000 | 1 | ACTEL | | Y | A1280A-PG176B | 431 |
| 5962-9215601MXC | H | 04/28/2000 | 1 | ACTEL | | Y | A1280A-PG176B | 431 |
| 5962-9215601MYA | H | 04/28/2000 | 1 | ACTEL | | Y | A1280A-CQ172B | 431 |
| 5962-9215601MYC | H | 04/28/2000 | 1 | ACTEL | | Y | A1280A-CQ172B | 431 |
| 5962-9215601MZA | H | 04/28/2000 | | (NONE) | | | 1280 (GEN) | 431 |
| 5962-9215602MUC | H | 04/28/2000 | | (NONE) | | | 1280-1 (GEN) | 431 |
| 5962-9215602MXA | H | 04/28/2000 | 1 | ACTEL | | Y | A1280A-1PG176B | 431 |
| 5962-9215602MXC | H | 04/28/2000 | 1 | ACTEL | | Y | A1280A-1PG176B | 431 |
| 5962-9215602MYA | H | 04/28/2000 | 1 | ACTEL | | Y | A1280A-1CQ172B | 431 |
| 5962-9215602MYC | H | 04/28/2000 | 1 | ACTEL | | Y | A1280A-1CQ172B | 431 |
| 5962-9215602MZA | H | 04/28/2000 | | (NONE) | | | 1280-1 (GEN) | 431 |
| 5962F9215603Q9C | H | 04/28/2000 | 1 | ACTEL | | Y | RH1280-DIE | 431 |
| 5962F9215603QYC | H | 04/28/2000 | 1 | ACTEL | | Y | RH1280-CQ172V | 431 |
| 5962-9215604Q9D | H | 04/28/2000 | 1 | ACTEL | | Y | A1280XL-DIE | 431 |
| 5962-9215604QXC | H | 04/28/2000 | 1 | ACTEL | | Y | A1280XL-PG176B | 431 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9215604QYC | H | 04/28/2000 | 1 | ACTEL | | Y | A1280XL-CQ172B | 431 |
| 5962-9215605QXC | H | 04/28/2000 | 1 | ACTEL | | Y | A1280XL-1PG176B | 431 |
| 5962-9215605QYC | H | 04/28/2000 | 1 | ACTEL | | Y | A1280XL-1CQ172B | 431 |
| 5962-9215701M2A | A | 06/07/1996 | | (NONE) | 05/27/1997 | | 49FCT805 (GEN) | 529 |
| 5962-9215701MRA | A | 06/07/1996 | | (NONE) | 05/27/1997 | | 49FCT805 (GEN) | 529 |
| 5962-9215701MSA | A | 06/07/1996 | | (NONE) | 05/27/1997 | | 49FCT805 (GEN) | 529 |
| 5962-9215702M2A | A | 06/07/1996 | | (NONE) | 05/27/1997 | | 49FCT805A (GEN) | 529 |
| 5962-9215702MRA | A | 06/07/1996 | | (NONE) | 05/27/1997 | | 49FCT805A (GEN) | 529 |
| 5962-9215702MSA | A | 06/07/1996 | | (NONE) | 05/27/1997 | | 49FCT805A (GEN) | 529 |
| 5962-9215703M2A | A | 06/07/1996 | | (NONE) | 05/27/1997 | | 49FCT806 (GEN) | 529 |
| 5962-9215703MRA | A | 06/07/1996 | | (NONE) | 05/27/1997 | | 49FCT806 (GEN) | 529 |
| 5962-9215703MSA | A | 06/07/1996 | | (NONE) | 05/27/1997 | | 49FCT806 (GEN) | 529 |
| 5962-9215704M2A | A | 06/07/1996 | | (NONE) | 05/27/1997 | | 49FCT806A (GEN) | 529 |
| 5962-9215704MRA | A | 06/07/1996 | | (NONE) | 05/27/1997 | | 49FCT806A (GEN) | 529 |
| 5962-9215704MSA | A | 06/07/1996 | | (NONE) | 05/27/1997 | | 49FCT806A (GEN) | 529 |
| 5962-9215801MXA | B | 03/07/2002 | | (NONE) | | | | 431 |
| 5962-9215802MXA | B | 03/07/2002 | 1 | CYPRESS | 05/03/2004 | Y | CY7C343-30HMB | 431 |
| 5962-9215901HXA | B | 05/19/2003 | 1 | ADV. ANALOG | | Y | ATR2815T/CH | 594 |
| 5962-9215901HZA | B | 05/19/2003 | 1 | ADV. ANALOG | | Y | ATR2815TF/CH | 594 |
| 5962-9216201HXA | C | 07/16/2004 | 1 | DDC | | Y | BUS-65153II-140 | 599 |
| 5962-9216201HXC | C | 07/16/2004 | 1 | DDC | | Y | BUS-65153II-110 | 599 |
| 5962-9216201HYA | C | 07/16/2004 | 1 | DDC | | Y | BUS-65163II-140 | 599 |
| 5962-9216201HYC | C | 07/16/2004 | 1 | DDC | | Y | BUS-65163II-110 | 599 |
| 5962-9216202HXA | C | 07/16/2004 | 1 | DDC | | Y | BUS-65154II-140 | 599 |
| 5962-9216202HXC | C | 07/16/2004 | 1 | DDC | | Y | BUS-65154II-110 | 599 |
| 5962-9216202HYA | C | 07/16/2004 | 1 | DDC | | Y | BUS-65164II-140 | 599 |
| 5962-9216202HYC | C | 07/16/2004 | 1 | DDC | | Y | BUS-65164II-110 | 599 |
| 5962-9216501M2A | D | 05/07/2004 | | (NONE) | | | LM6162 (GEN) | 702 |
| 5962-9216501MHA | D | 05/07/2004 | | (NONE) | | | LM6162 (GEN) | 702 |
| 5962-9216501MPA | D | 05/07/2004 | 1 | NATIONAL | | Y | LM6162J/883 | 702 |
| 5962-9216501VPA | D | 05/07/2004 | | (NONE) | 03/04/2003 | | LM6162 (GEN) | 702 |
| 5962-9216501MXA | D | 05/07/2004 | 1 | NATIONAL | | Y | LM6162WG/883 | 702 |
| 5962-9216501VXA | D | 05/07/2004 | | (NONE) | 03/04/2003 | | LM6162 (GEN) | 702 |
| 5962-9216601MXA | B | 09/18/2001 | 3 | NATIONAL | | Y | LM1577K-ADJ/883 | 789 |
| 5962-9216601QYA | B | 09/18/2001 | | (NONE) | | | LM1577ADJ (GEN) | 789 |
| 5962-9216701MXA | A | 10/16/2001 | 3 | NATIONAL | | Y | LM1577K-12/883 | 782 |
| 5962-9216801MXA | | 04/06/1993 | | (NONE) | | | LM1577 (GEN) | 782 |
| 5962-9217101MXC | | 12/22/1993 | | (NONE) | | | L64710-33 (GEN) | 399 |
| 5962-9217102MXC | | 12/22/1993 | | (NONE) | | | L64710-25 (GEN) | 399 |
| 5962-9217201MXA | | 05/20/1993 | | (NONE) | 05/10/1995 | | 7B162-15 (GEN) | 620 |
| 5962-9217201MYA | | 05/20/1993 | | (NONE) | 05/10/1995 | | 7B162-15 (GEN) | 620 |
| 5962-9217202MXA | | 05/20/1993 | | (NONE) | 05/10/1995 | | 7B162-12 (GEN) | 620 |
| 5962-9217202MYA | | 05/20/1993 | | (NONE) | 05/10/1995 | | 7B162-12 (GEN) | 620 |
| 5962-9217203MXA | | 05/20/1993 | | (NONE) | 05/10/1995 | | 7B162-10 (GEN) | 620 |
| 5962-9217203MYA | | 05/20/1993 | | (NONE) | 05/10/1995 | | 7B162-10 (GEN) | 620 |
| 5962-9217401M2A | B | 09/22/2003 | 3 | NATIONAL | | Y | 54AC2525LMQB | 399 |
| 5962-9217401MCA | B | 09/22/2003 | 3 | NATIONAL | | Y | 54AC2525DMQB | 399 |
| 5962-9217401MDA | B | 09/22/2003 | 3 | NATIONAL | | Y | 54AC2525FMQB | 399 |
| 5962F9217401VDA | B | 09/22/2003 | 3 | NATIONAL | | Y | 54AC2525WFQMLV | 399 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962R9217401VDA | B | 09/22/2003 | 3 | NATIONAL | | Y | 54AC2525WRQMLV | 399 |
| 5962-9217601M2A | A | 11/13/1995 | 3 | NATIONAL | | Y | 54ACQ244LMQB | 529 |
| 5962-9217601MRA | A | 11/13/1995 | 3 | NATIONAL | | Y | 54ACQ244DMQB | 529 |
| 5962-9217601MSA | A | 11/13/1995 | 3 | NATIONAL | | Y | 54ACQ244FMQB | 529 |
| 5962-9217701M2A | A | 11/05/1998 | 3 | NATIONAL | | Y | 54ACQ245LMQB | 590 |
| 5962-9217701MRA | A | 11/05/1998 | 3 | NATIONAL | | Y | 54ACQ245DMQB | 590 |
| 5962-9217701MSA | A | 11/05/1998 | 3 | NATIONAL | | Y | 54ACQ245FMQB | 590 |
| 5962-9217801M2A | | 06/08/1994 | | NATIONAL | | Y | 54ACQ373LMQB | 341 |
| 5962-9217801MRA | | 06/08/1994 | | NATIONAL | | Y | 54ACQ373DMQB | 341 |
| 5962-9217801MSA | | 06/08/1994 | | NATIONAL | | Y | 54ACQ373FMQB | 341 |
| 5962-9217901M2A | | 06/08/1994 | | NATIONAL | | Y | 54ACQ374LMQB | 159 |
| 5962-9217901MRA | | 06/08/1994 | | NATIONAL | | Y | 54ACQ374DMQB | 159 |
| 5962-9217901MSA | | 06/08/1994 | | NATIONAL | | Y | 54ACQ374FMQB | 159 |
| 5962-9218001M2A | | 02/18/1994 | 3 | NATIONAL | | Y | 54ACQ573LMQB | 341 |
| 5962-9218001MRA | | 02/18/1994 | 3 | NATIONAL | | Y | 54ACQ573DMQB | 341 |
| 5962-9218001MSA | | 02/18/1994 | 3 | NATIONAL | | Y | 54ACQ573FMQB | 341 |
| 5962-9218101M2A | | 06/07/1993 | | NATIONAL | | Y | 54ACTQ02LMQB | 120 |
| 5962-9218101MCA | | 06/07/1993 | | NATIONAL | | Y | 54ACTQ02DMQB | 120 |
| 5962-9218101MDA | | 06/07/1993 | | NATIONAL | | Y | 54ACTQ02FMQB | 120 |
| 5962-9218201M2A | B | 03/30/2004 | 2 | NATIONAL | | Y | 54ACTQ10LMQB | 102 |
| 5962-9218201M2A | B | 03/30/2004 | 2 | TI | | Y | SNJ54ACT10FK | 102 |
| 5962-9218201MCA | B | 03/30/2004 | 2 | NATIONAL | | Y | 54ACTQ10DMQB | 102 |
| 5962-9218201MCA | B | 03/30/2004 | 2 | TI | | Y | SNJ54ACT10J | 102 |
| 5962-9218201MDA | B | 03/30/2004 | 2 | NATIONAL | | Y | 54ACTQ10FMQB | 102 |
| 5962-9218201MDA | B | 03/30/2004 | 2 | TI | | Y | SNJ54ACT10W | 102 |
| 5962-9218202QXA | B | 03/30/2004 | 2 | STMICRO | | Y | 54ACT10K02Q | 102 |
| 5962-9218202QXC | B | 03/30/2004 | 2 | STMICRO | | Y | 54ACT10K01Q | 102 |
| 5962-9218202VXA | B | 03/30/2004 | 2 | STMICRO | | Y | 54ACT10K02V | 102 |
| 5962-9218202VXC | B | 03/30/2004 | 2 | STMICRO | | Y | 54ACT10K01V | 102 |
| 5962F9218202QXA | B | 03/30/2004 | 2 | STMICRO | | Y | RHFACT10K02Q | 102 |
| 5962F9218202QXC | B | 03/30/2004 | 2 | STMICRO | | Y | RHFACT10K01Q | 102 |
| 5962F9218202VXA | B | 03/30/2004 | 2 | STMICRO | | Y | RHFACT10K02V | 102 |
| 5962F9218202VXC | B | 03/30/2004 | 2 | STMICRO | | Y | RHFACT10K01V | 102 |
| 5962-9218301M2A | C | 10/28/2003 | | NATIONAL | | Y | 54ACTQ14LMQB | 143 |
| 5962-9218301M2A | C | 10/28/2003 | 3 | TI | | Y | SNJ54ACT14FK | 143 |
| 5962-9218301MCA | C | 10/28/2003 | | NATIONAL | | Y | 54ACTQ14DMQB | 143 |
| 5962-9218301MCA | C | 10/28/2003 | 3 | TI | | Y | SNJ54ACT14J | 143 |
| 5962-9218301MDA | C | 10/28/2003 | | NATIONAL | | Y | 54ACTQ14FMQB | 143 |
| 5962-9218301MDA | C | 10/28/2003 | 3 | TI | | Y | SNJ54ACT14W | 143 |
| 5962-9218401M2A | A | 03/26/1993 | 3 | NATIONAL | | Y | 54ACTQ240LMQB | 529 |
| 5962-9218401MRA | A | 03/26/1993 | 3 | NATIONAL | | Y | 54ACTQ240DMQB | 529 |
| 5962-9218401MSA | A | 03/26/1993 | 3 | NATIONAL | | Y | 54ACTQ240FMQB | 529 |
| 5962-9218501M2A | | 06/08/1994 | 3 | NATIONAL | | Y | 54ACTQ241LMQB | 529 |
| 5962-9218501V2A | | 06/08/1994 | 3 | NATIONAL | | Y | 54ACTQ241E-QMLV | 529 |
| 5962-9218501MRA | | 06/08/1994 | 3 | NATIONAL | | Y | 54ACTQ241DMQB | 529 |
| 5962-9218501VRA | | 06/08/1994 | 3 | NATIONAL | | Y | 54ACTQ241J-QMLV | 529 |
| 5962-9218501MSA | | 06/08/1994 | 3 | NATIONAL | | Y | 54ACTQ241FMQB | 529 |
| 5962-9218501VSA | | 06/08/1994 | 3 | NATIONAL | | Y | 54ACTQ241W-QMLV | 529 |
| 5962-9218601M2A | A | 03/10/1999 | 3 | NATIONAL | | Y | 54ACTQ244LMQB | 529 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9218601V2A | A | 03/10/1999 | 3 | NATIONAL | | Y | 54ACTQ244E-QMLV | 529 |
| 5962R9218601M2A | A | 03/10/1999 | 3 | NATIONAL | | Y | 54ACTQ244LMQB-R | 529 |
| 5962R9218601V2A | A | 03/10/1999 | 3 | NATIONAL | | Y | 54ACTQ244ERQMLV | 529 |
| 5962-9218601MRA | A | 03/10/1999 | 3 | NATIONAL | | Y | 54ACTQ244DMQB | 529 |
| 5962-9218601VRA | A | 03/10/1999 | 3 | NATIONAL | | Y | 54ACTQ244J-QMLV | 529 |
| 5962R9218601MRA | A | 03/10/1999 | 3 | NATIONAL | | Y | 54ACTQ244DMQB-R | 529 |
| 5962R9218601VRA | A | 03/10/1999 | 3 | NATIONAL | | Y | 54ACTQ244JRQMLV | 529 |
| 5962-9218601MSA | A | 03/10/1999 | 3 | NATIONAL | | Y | 54ACTQ244FMQB | 529 |
| 5962-9218601VSA | A | 03/10/1999 | 3 | NATIONAL | | Y | 54ACTQ244W-QMLV | 529 |
| 5962R9218601MSA | A | 03/10/1999 | 3 | NATIONAL | | Y | 54ACTQ244FMQB-R | 529 |
| 5962R9218601VSA | A | 03/10/1999 | 3 | NATIONAL | | Y | 54ACTQ244WRQMLV | 529 |
| 5962-9218701M2A | A | 05/29/1998 | 3 | NATIONAL | | Y | 54ACTQ245LMQB | 590 |
| 5962R9218701M2A | A | 05/29/1998 | 3 | NATIONAL | | Y | 54ACTQ245LMQB-R | 590 |
| 5962R9218701V2A | A | 05/29/1998 | 3 | NATIONAL | | Y | 54ACTQ245ERQMLV | 590 |
| 5962-9218701MRA | A | 05/29/1998 | 3 | NATIONAL | | Y | 54ACTQ245DMQB | 590 |
| 5962R9218701MRA | A | 05/29/1998 | 3 | NATIONAL | | Y | 54ACTQ245DMQB-R | 590 |
| 5962R9218701VRA | A | 05/29/1998 | 3 | NATIONAL | | Y | 54ACTQ245JRQMLV | 590 |
| 5962-9218701MSA | A | 05/29/1998 | 3 | NATIONAL | | Y | 54ACTQ245FMQB | 590 |
| 5962R9218701MSA | A | 05/29/1998 | 3 | NATIONAL | | Y | 54ACTQ245FMQB-R | 590 |
| 5962R9218701VSA | A | 05/29/1998 | 3 | NATIONAL | | Y | 54ACTQ245WRQMLV | 590 |
| 5962-9218801M2A | A | 02/11/1997 | | NATIONAL | | Y | 54ACTQ373LMQB | 341 |
| 5962-9218801MRA | A | 02/11/1997 | | NATIONAL | | Y | 54ACTQ373DMQB | 341 |
| 5962-9218801MSA | A | 02/11/1997 | | NATIONAL | | Y | 54ACTQ373FMQB | 341 |
| 5962-9218901M2A | A | 04/07/1998 | | NATIONAL | | Y | 54ACTQ374LMQB | 159 |
| 5962R9218901M2A | A | 04/07/1998 | 3 | NATIONAL | | Y | 54ACTQ374LMQB-R | 159 |
| 5962R9218901V2A | A | 04/07/1998 | 3 | NATIONAL | | Y | 54ACTQ374ERQMLV | 159 |
| 5962-9218901MRA | A | 04/07/1998 | | NATIONAL | | Y | 54ACTQ374DMQB | 159 |
| 5962R9218901MRA | A | 04/07/1998 | 3 | NATIONAL | | Y | 54ACTQ374DMQB-R | 159 |
| 5962R9218901VRA | A | 04/07/1998 | 3 | NATIONAL | | Y | 54ACTQ374JRQMLV | 159 |
| 5962-9218901MSA | A | 04/07/1998 | | NATIONAL | | Y | 54ACTQ374FMQB | 159 |
| 5962R9218901MSA | A | 04/07/1998 | 3 | NATIONAL | | Y | 54ACTQ374FMQB-R | 159 |
| 5962R9218901VSA | A | 04/07/1998 | 3 | NATIONAL | | Y | 54ACTQ374WRQMLV | 159 |
| 5962-9219001M2A | A | 06/06/2000 | 3 | NATIONAL | | Y | 54ACTQ377LMQB | 159 |
| 5962-9219001MRA | A | 06/06/2000 | 3 | NATIONAL | | Y | 54ACTQ377DMQB | 159 |
| 5962-9219001MSA | A | 06/06/2000 | 3 | NATIONAL | | Y | 54ACTQ377FMQB | 159 |
| 5962-9219401M2A | | 09/28/1993 | | NATIONAL | | Y | 54ACTQ573LMQB | 341 |
| 5962-9219401MRA | | 09/28/1993 | | NATIONAL | | Y | 54ACTQ573DMQB | 341 |
| 5962-9219401MSA | | 09/28/1993 | | NATIONAL | | Y | 54ACTQ573FMQB | 341 |
| 5962-9219601M3A | | 09/28/1994 | 3 | NATIONAL | | Y | 54ACTQ646LMQB | 590 |
| 5962-9219601MKA | | 09/28/1994 | 3 | NATIONAL | | Y | 54ACTQ646FMQB | 590 |
| 5962-9219601MLA | | 09/28/1994 | 3 | NATIONAL | | Y | 54ACTQ646SDMQB | 590 |
| 5962-9219701M3A | | 04/20/1993 | 2 | NATIONAL | | Y | 54ACTQ657LMQB | 590 |
| 5962-9219701MKA | | 04/20/1993 | 2 | NATIONAL | | Y | 54ACTQ657FMQB | 590 |
| 5962-9219701MLA | | 04/20/1993 | 2 | NATIONAL | | Y | 54ACTQ657SDMQB | 590 |
| 5962-9219901M3A | | 01/27/1994 | 3 | NATIONAL | | Y | 54ACTQ827LMQB | 569 |
| 5962-9219901MKA | | 01/27/1994 | | (NONE) | 03/09/1999 | | 54ACTQ827 (GEN) | 569 |
| 5962-9219901MLA | | 01/27/1994 | 3 | NATIONAL | | Y | 54ACTQ827SDMQB | 569 |
| 5962-9220001M3A | | 06/28/1993 | | NATIONAL | | Y | 54ACTQ841LMQB | 342 |
| 5962-9220001MKA | | 06/28/1993 | | NATIONAL | | Y | 54ACTQ841FMQB | 342 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9220001MLA | | 06/28/1993 | | NATIONAL | | Y | 54ACTQ841SDMQB | 342 |
| 5962-9220101M2A | A | 04/17/2003 | 3 | NATIONAL | | Y | 54AC280LMQB | 210 |
| 5962-9220101MCA | A | 04/17/2003 | 3 | NATIONAL | | Y | 54AC280DMQB | 210 |
| 5962-9220101MDA | A | 04/17/2003 | 3 | NATIONAL | | Y | 54AC280FMQB | 210 |
| 5962-9220102QXA | A | 04/17/2003 | 2 | STMICRO | | Y | 54AC280K02Q | 210 |
| 5962-9220102QXC | A | 04/17/2003 | 2 | STMICRO | | Y | 54AC280K01Q | 210 |
| 5962-9220102VXA | A | 04/17/2003 | 2 | STMICRO | | Y | 54AC280K02V | 210 |
| 5962-9220102VXC | A | 04/17/2003 | 2 | STMICRO | | Y | 54AC280K01V | 210 |
| 5962-9220201M2A | B | 09/30/1996 | | (NONE) | | | 54FCT139T (GEN) | 283 |
| 5962-9220201MEA | B | 09/30/1996 | | (NONE) | | | 54FCT139T (GEN) | 283 |
| 5962-9220202M2A | B | 09/30/1996 | 1 | IDT | | Y | IDT54FCT139TLB | 283 |
| 5962-9220202MEA | B | 09/30/1996 | 1 | IDT | | Y | IDT54FCT139TDB | 283 |
| 5962-9220202MFA | B | 09/30/1996 | | (NONE) | 04/29/2002 | | 54FCT139T (GEN) | 283 |
| 5962-9220203M2A | B | 09/30/1996 | | (NONE) | | | 54FCT139AT (GEN) | 283 |
| 5962-9220203MEA | B | 09/30/1996 | | (NONE) | | | 54FCT139AT (GEN) | 283 |
| 5962-9220204M2A | B | 09/30/1996 | 1 | IDT | | Y | IDT54FCT139ATLB | 283 |
| 5962-9220204MEA | B | 09/30/1996 | 1 | IDT | | Y | IDT54FCT139ATDB | 283 |
| 5962-9220204MFA | B | 09/30/1996 | | (NONE) | 04/29/2002 | | 54FCT139AT (GEN) | 283 |
| 5962-9220205M2A | B | 09/30/1996 | | (NONE) | | | 54FCT139CT (GEN) | 283 |
| 5962-9220205MEA | B | 09/30/1996 | | (NONE) | | | 54FCT139CT (GEN) | 283 |
| 5962-9220206M2A | B | 09/30/1996 | 1 | IDT | | Y | IDT54FCT139CTLB | 283 |
| 5962-9220206MEA | B | 09/30/1996 | 1 | IDT | | Y | IDT54FCT139CTDB | 283 |
| 5962-9220206MFA | B | 09/30/1996 | | (NONE) | 04/29/2002 | | 54FCT139CT (GEN) | 283 |
| 5962-9220301M2A | B | 09/03/1996 | 2 | IDT | | Y | IDT54FCT244TLB | 529 |
| 5962-9220301M2A | B | 09/03/1996 | 2 | TI | | Y | CY54FCT244TLMB | 529 |
| 5962-9220301MRA | B | 09/03/1996 | 2 | IDT | | Y | IDT54FCT244TDB | 529 |
| 5962-9220301MRA | B | 09/03/1996 | 2 | TI | | Y | CY54FCT244TDMB | 529 |
| 5962-9220301MSA | B | 09/03/1996 | 2 | TI | | Y | CY54FCT244TW | 529 |
| 5962-9220302M2A | B | 09/03/1996 | 2 | IDT | | Y | IDT54FCT244ATLB | 529 |
| 5962-9220302M2A | B | 09/03/1996 | 2 | TI | | Y | CY54FCT244ATLMB | 529 |
| 5962-9220302MRA | B | 09/03/1996 | 2 | IDT | | Y | IDT54FCT244ATDB | 529 |
| 5962-9220302MRA | B | 09/03/1996 | 2 | TI | | Y | CY54FCT244ATDMB | 529 |
| 5962-9220302MSA | B | 09/03/1996 | 2 | TI | | Y | CY54FCT244ATW | 529 |
| 5962-9220303M2A | B | 09/03/1996 | 2 | IDT | | Y | IDT54FCT244CTLB | 529 |
| 5962-9220303M2A | B | 09/03/1996 | 2 | TI | | Y | CY54FCT244CTLMB | 529 |
| 5962-9220303MRA | B | 09/03/1996 | 2 | IDT | | Y | IDT54FCT244CTDB | 529 |
| 5962-9220303MRA | B | 09/03/1996 | 2 | TI | | Y | CY54FCT244CTDMB | 529 |
| 5962-9220303MSA | B | 09/03/1996 | 2 | TI | | Y | CY54FCT244CTW | 529 |
| 5962-9220304M2A | B | 09/03/1996 | | (NONE) | | | 54FCT244T (GEN) | 529 |
| 5962-9220304MRA | B | 09/03/1996 | | (NONE) | | | 54FCT244T (GEN) | 529 |
| 5962-9220305M2A | B | 09/03/1996 | | (NONE) | | | 54FCT244AT (GEN) | 529 |
| 5962-9220305MRA | B | 09/03/1996 | | (NONE) | | | 54FCT244AT (GEN) | 529 |
| 5962-9220306M2A | B | 09/03/1996 | | (NONE) | | | 54FCT244CT (GEN) | 529 |
| 5962-9220306MRA | B | 09/03/1996 | | (NONE) | | | 54FCT244CT (GEN) | 529 |
| 5962-9220401M3A | A | 09/06/1996 | | (NONE) | 04/27/1998 | | 29FCT52AT (GEN) | 590 |
| 5962-9220401MKA | A | 09/06/1996 | | (NONE) | 04/27/1998 | | 29FCT52AT (GEN) | 590 |
| 5962-9220401MLA | A | 09/06/1996 | | (NONE) | 04/27/1998 | | 29FCT52AT (GEN) | 590 |
| 5962-9220402M3A | A | 09/06/1996 | | (NONE) | 04/27/1998 | | 29FCT52BT (GEN) | 590 |
| 5962-9220402MKA | A | 09/06/1996 | | (NONE) | 04/27/1998 | | 29FCT52BT (GEN) | 590 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9220402MLA | A | 09/06/1996 | | (NONE) | 04/27/1998 | | 29FCT52BT (GEN) | 590 |
| 5962-9220403M3A | A | 09/06/1996 | | (NONE) | 04/28/1997 | | 29FCT52CT (GEN) | 590 |
| 5962-9220403MKA | A | 09/06/1996 | | (NONE) | 04/27/1998 | | 29FCT52CT (GEN) | 590 |
| 5962-9220403MLA | A | 09/06/1996 | | (NONE) | 04/27/1998 | | 29FCT52CT (GEN) | 590 |
| 5962-9220501M3A | B | 09/16/1997 | | (NONE) | | | 29FCT520AT (GEN) | 249 |
| 5962-9220501MLA | B | 09/16/1997 | | (NONE) | | | 29FCT520AT (GEN) | 249 |
| 5962-9220502M3A | B | 09/16/1997 | | (NONE) | 04/27/1998 | | 29FCT520AT (GEN) | 249 |
| 5962-9220502MKA | B | 09/16/1997 | | (NONE) | 04/27/1998 | | 29FCT520AT (GEN) | 249 |
| 5962-9220502MLA | B | 09/16/1997 | 2 | TI | | Y | CY29FCT520ATDMB | 249 |
| 5962-9220503M3A | B | 09/16/1997 | | (NONE) | | | 29FCT520BT (GEN) | 249 |
| 5962-9220503MLA | B | 09/16/1997 | | (NONE) | | | 29FCT520BT (GEN) | 249 |
| 5962-9220504M3A | B | 09/16/1997 | | (NONE) | 04/27/1998 | | 29FCT520BT (GEN) | 249 |
| 5962-9220504MKA | B | 09/16/1997 | | (NONE) | 04/27/1998 | | 29FCT520BT (GEN) | 249 |
| 5962-9220504MLA | B | 09/16/1997 | 2 | TI | | Y | CY29FCT520BTDMB | 249 |
| 5962-9220505M3A | B | 09/16/1997 | | (NONE) | | | 29FCT520CT (GEN) | 249 |
| 5962-9220505MLA | B | 09/16/1997 | | (NONE) | | | 29FCT520CT (GEN) | 249 |
| 5962-9220506M3A | B | 09/16/1997 | | (NONE) | 04/27/1998 | | 29FCT520CT (GEN) | 249 |
| 5962-9220506MKA | B | 09/16/1997 | | (NONE) | 04/27/1998 | | 29FCT520CT (GEN) | 249 |
| 5962-9220506MLA | B | 09/16/1997 | | (NONE) | 04/27/1998 | | 29FCT520CT (GEN) | 249 |
| 5962-9220601M2A | | 10/06/1994 | | (NONE) | 04/27/1998 | | 54FCT151T (GEN) | 271 |
| 5962-9220601MEA | | 10/06/1994 | | (NONE) | 04/27/1998 | | 54FCT151T (GEN) | 271 |
| 5962-9220601MFA | | 10/06/1994 | | (NONE) | 04/27/1998 | | 54FCT151T (GEN) | 271 |
| 5962-9220602M2A | | 10/06/1994 | | (NONE) | | | 54FCT151T (GEN) | 271 |
| 5962-9220602MEA | | 10/06/1994 | | (NONE) | | | 54FCT151T (GEN) | 271 |
| 5962-9220602MFA | | 10/06/1994 | | (NONE) | | | 54FCT151T (GEN) | 271 |
| 5962-9220603M2A | | 10/06/1994 | | (NONE) | 04/27/1998 | | 54FCT151AT (GEN) | 271 |
| 5962-9220603MEA | | 10/06/1994 | | (NONE) | 04/27/1998 | | 54FCT151AT (GEN) | 271 |
| 5962-9220603MFA | | 10/06/1994 | | (NONE) | 04/27/1998 | | 54FCT151AT (GEN) | 271 |
| 5962-9220604M2A | | 10/06/1994 | | (NONE) | | | 54FCT151AT (GEN) | 271 |
| 5962-9220604MEA | | 10/06/1994 | | (NONE) | | | 54FCT151AT (GEN) | 271 |
| 5962-9220604MFA | | 10/06/1994 | | (NONE) | | | 54FCT151AT (GEN) | 271 |
| 5962-9220605M2A | | 10/06/1994 | | (NONE) | 04/27/1998 | | 54FCT151CT (GEN) | 271 |
| 5962-9220605MEA | | 10/06/1994 | | (NONE) | 04/27/1998 | | 54FCT151CT (GEN) | 271 |
| 5962-9220605MFA | | 10/06/1994 | | (NONE) | 04/27/1998 | | 54FCT151CT (GEN) | 271 |
| 5962-9220606M2A | | 10/06/1994 | | (NONE) | | | 54FCT151CT (GEN) | 271 |
| 5962-9220606MEA | | 10/06/1994 | | (NONE) | | | 54FCT151CT (GEN) | 271 |
| 5962-9220606MFA | | 10/06/1994 | | (NONE) | | | 54FCT151CT (GEN) | 271 |
| 5962-9220801M2A | C | 11/09/2000 | 1 | QP SEMI | | Y | 54FCT157T/M2A | 276 |
| 5962-9220801MEA | C | 11/09/2000 | 1 | QP SEMI | | Y | 54FCT157T/MEA | 276 |
| 5962-9220801MFA | C | 11/09/2000 | 1 | QP SEMI | | Y | 54FCT157T/MFA | 276 |
| 5962-9220802M2A | C | 11/09/2000 | | (NONE) | | | 54FCT157T (GEN) | 276 |
| 5962-9220802MEA | C | 11/09/2000 | | (NONE) | | | 54FCT157T (GEN) | 276 |
| 5962-9220803M2A | C | 11/09/2000 | 2 | TI | | Y | CY54FCT157ATLMB | 276 |
| 5962-9220803MEA | C | 11/09/2000 | | (NONE) | 04/27/1998 | | 54FCT157AT (GEN) | 276 |
| 5962-9220803MFA | C | 11/09/2000 | | (NONE) | 04/27/1998 | | 54FCT157AT (GEN) | 276 |
| 5962-9220804M2A | C | 11/09/2000 | | (NONE) | | | 54FCT157AT (GEN) | 276 |
| 5962-9220804MEA | C | 11/09/2000 | | (NONE) | | | 54FCT157AT (GEN) | 276 |
| 5962-9220805M2A | C | 11/09/2000 | | (NONE) | 04/27/1998 | | 54FCT157CT (GEN) | 276 |
| 5962-9220805MEA | C | 11/09/2000 | | (NONE) | 04/27/1998 | | 54FCT157CT (GEN) | 276 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9220805MFA | C | 11/09/2000 | | (NONE) | 04/27/1998 | | 54FCT157CT (GEN) | 276 |
| 5962-9220806M2A | C | 11/09/2000 | | (NONE) | | | 54FCT157CT (GEN) | 276 |
| 5962-9220806MEA | C | 11/09/2000 | | (NONE) | | | 54FCT157CT (GEN) | 276 |
| 5962-9220901M2A | C | 09/30/1996 | | (NONE) | | | 54FCT161T (GEN) | 304 |
| 5962-9220901MEA | C | 09/30/1996 | | (NONE) | | | 54FCT161T (GEN) | 304 |
| 5962-9220902M2A | C | 09/30/1996 | | (NONE) | 04/27/1998 | | 54FCT161T (GEN) | 304 |
| 5962-9220902MEA | C | 09/30/1996 | | (NONE) | 04/27/1998 | | 54FCT161T (GEN) | 304 |
| 5962-9220902MFA | C | 09/30/1996 | | (NONE) | 04/27/1998 | | 54FCT161T (GEN) | 304 |
| 5962-9220903M2A | C | 09/30/1996 | | (NONE) | | | 54FCT161AT (GEN) | 304 |
| 5962-9220903MEA | C | 09/30/1996 | | (NONE) | | | 54FCT161AT (GEN) | 304 |
| 5962-9220904M2A | C | 09/30/1996 | | (NONE) | 04/27/1998 | | 54FCT161AT (GEN) | 304 |
| 5962-9220904MEA | C | 09/30/1996 | | (NONE) | 04/27/1998 | | 54FCT161AT (GEN) | 304 |
| 5962-9220904MFA | C | 09/30/1996 | | (NONE) | 04/27/1998 | | 54FCT161AT (GEN) | 304 |
| 5962-9220905M2A | C | 09/30/1996 | | (NONE) | | | 54FCT161CT (GEN) | 304 |
| 5962-9220905MEA | C | 09/30/1996 | | (NONE) | | | 54FCT161CT (GEN) | 304 |
| 5962-9220906M2A | C | 09/30/1996 | | (NONE) | 04/27/1998 | | 54FCT161CT (GEN) | 304 |
| 5962-9220906MEA | C | 09/30/1996 | | (NONE) | 04/27/1998 | | 54FCT161CT (GEN) | 304 |
| 5962-9220906MFA | C | 09/30/1996 | | (NONE) | 04/27/1998 | | 54FCT161CT (GEN) | 304 |
| 5962-9221001M2A | C | 09/30/1996 | | (NONE) | | | 54FCT163T (GEN) | 304 |
| 5962-9221001MEA | C | 09/30/1996 | | (NONE) | | | 54FCT163T (GEN) | 304 |
| 5962-9221002M2A | C | 09/30/1996 | 1 | IDT | | Y | IDT54FCT163TLB | 304 |
| 5962-9221002MEA | C | 09/30/1996 | 1 | IDT | | Y | IDT54FCT163TDB | 304 |
| 5962-9221002MFA | C | 09/30/1996 | | (NONE) | 04/29/2002 | | 54FCT163T (GEN) | 304 |
| 5962-9221003M2A | C | 09/30/1996 | | (NONE) | | | 54FCT163AT (GEN) | 304 |
| 5962-9221003MEA | C | 09/30/1996 | | (NONE) | | | 54FCT163AT (GEN) | 304 |
| 5962-9221004M2A | C | 09/30/1996 | 1 | IDT | | Y | IDT54FCT163ATLB | 304 |
| 5962-9221004MEA | C | 09/30/1996 | 1 | IDT | | Y | IDT54FCT163ATDB | 304 |
| 5962-9221004MFA | C | 09/30/1996 | | (NONE) | 04/29/2002 | | 54FCT163AT (GEN) | 304 |
| 5962-9221005M2A | C | 09/30/1996 | | (NONE) | | | 54FCT163CT (GEN) | 304 |
| 5962-9221005MEA | C | 09/30/1996 | | (NONE) | | | 54FCT163CT (GEN) | 304 |
| 5962-9221006M2A | C | 09/30/1996 | 1 | IDT | | Y | IDT54FCT163CTLB | 304 |
| 5962-9221006MEA | C | 09/30/1996 | 1 | IDT | | Y | IDT54FCT163CTDB | 304 |
| 5962-9221006MFA | C | 09/30/1996 | | (NONE) | 04/29/2002 | | 54FCT163CT (GEN) | 304 |
| 5962-9221101M2A | A | 09/30/1996 | | (NONE) | | | 54FCT257T (GEN) | 276 |
| 5962-9221101MEA | A | 09/30/1996 | | (NONE) | | | 54FCT257T (GEN) | 276 |
| 5962-9221102M2A | A | 09/30/1996 | 2 | IDT | | Y | IDT54FCT257TLB | 276 |
| 5962-9221102MEA | A | 09/30/1996 | 2 | IDT | | Y | IDT54FCT257TDB | 276 |
| 5962-9221102MFA | A | 09/30/1996 | | (NONE) | 04/29/2002 | | 54FCT257T (GEN) | 276 |
| 5962-9221103M2A | A | 09/30/1996 | | (NONE) | | | 54FCT257AT (GEN) | 276 |
| 5962-9221103MEA | A | 09/30/1996 | | (NONE) | | | 54FCT257AT (GEN) | 276 |
| 5962-9221104M2A | A | 09/30/1996 | 2 | IDT | | Y | IDT54FCT257ATLB | 276 |
| 5962-9221104MEA | A | 09/30/1996 | 2 | IDT | | Y | IDT54FCT257ATDB | 276 |
| 5962-9221104MFA | A | 09/30/1996 | | (NONE) | 04/29/2002 | | 54FCT257AT (GEN) | 276 |
| 5962-9221105M2A | A | 09/30/1996 | | (NONE) | | | 54FCT257CT (GEN) | 276 |
| 5962-9221105MEA | A | 09/30/1996 | | (NONE) | | | 54FCT257CT (GEN) | 276 |
| 5962-9221106M2A | A | 09/30/1996 | 2 | IDT | | Y | IDT54FCT257CTLB | 276 |
| 5962-9221106MEA | A | 09/30/1996 | 2 | IDT | | Y | IDT54FCT257CTDB | 276 |
| 5962-9221106MFA | A | 09/30/1996 | | (NONE) | 04/29/2002 | | 54FCT257CT (GEN) | 276 |
| 5962-9221201M2A | A | 09/30/1996 | | (NONE) | | | 54FCT399T (GEN) | 249 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9221201MEA | A | 09/30/1996 | | (NONE) | | | 54FCT399T (GEN) | 249 |
| 5962-9221202M2A | A | 09/30/1996 | | (NONE) | 09/01/1996 | | 54FCT399T (GEN) | 249 |
| 5962-9221202MEA | A | 09/30/1996 | | (NONE) | 09/01/1996 | | 54FCT399T (GEN) | 249 |
| 5962-9221202MFA | A | 09/30/1996 | | (NONE) | 09/01/1996 | | 54FCT399T (GEN) | 249 |
| 5962-9221203M2A | A | 09/30/1996 | | (NONE) | | | 54FCT399AT (GEN) | 249 |
| 5962-9221203MEA | A | 09/30/1996 | | (NONE) | | | 54FCT399AT (GEN) | 249 |
| 5962-9221204M2A | A | 09/30/1996 | | (NONE) | 09/01/1996 | | 54FCT399AT (GEN) | 249 |
| 5962-9221204MEA | A | 09/30/1996 | | (NONE) | 09/01/1996 | | 54FCT399AT (GEN) | 249 |
| 5962-9221204MFA | A | 09/30/1996 | | (NONE) | 09/01/1996 | | 54FCT399AT (GEN) | 249 |
| 5962-9221205M2A | A | 09/30/1996 | | (NONE) | | | 54FCT399CT (GEN) | 249 |
| 5962-9221205MEA | A | 09/30/1996 | | (NONE) | | | 54FCT399CT (GEN) | 249 |
| 5962-9221206M2A | A | 09/30/1996 | | (NONE) | 09/01/1996 | | 54FCT399CT (GEN) | 249 |
| 5962-9221206MEA | A | 09/30/1996 | | (NONE) | 09/01/1996 | | 54FCT399CT (GEN) | 249 |
| 5962-9221206MFA | A | 09/30/1996 | | (NONE) | 09/01/1996 | | 54FCT399CT (GEN) | 249 |
| 5962-9221301M2A | B | 09/03/1996 | 2 | IDT | | Y | IDT54FCT240TLB | 529 |
| 5962-9221301MRA | B | 09/03/1996 | 2 | IDT | | Y | IDT54FCT240TDB | 529 |
| 5962-9221301MRA | B | 09/03/1996 | 2 | TI | | Y | CY54FCT240TDMB | 529 |
| 5962-9221301MSA | B | 09/03/1996 | | (NONE) | 04/29/2002 | | 54FCT240T (GEN) | 529 |
| 5962-9221302M2A | B | 09/03/1996 | | (NONE) | | | 54FCT240T (GEN) | 529 |
| 5962-9221302MRA | B | 09/03/1996 | | (NONE) | | | 54FCT240T (GEN) | 529 |
| 5962-9221303M2A | B | 09/03/1996 | 2 | IDT | | Y | IDT54FCT240ATLB | 529 |
| 5962-9221303M2A | B | 09/03/1996 | 2 | TI | | Y | CY54FCT240ATLMB | 529 |
| 5962-9221303MRA | B | 09/03/1996 | 2 | IDT | | Y | IDT54FCT240ATDB | 529 |
| 5962-9221303MRA | B | 09/03/1996 | 2 | TI | | Y | CY54FCT240ATDMB | 529 |
| 5962-9221303MSA | B | 09/03/1996 | | (NONE) | 04/29/2002 | | 54FCT240AT (GEN) | 529 |
| 5962-9221304M2A | B | 09/03/1996 | | (NONE) | | | 54FCT240AT (GEN) | 529 |
| 5962-9221304MRA | B | 09/03/1996 | | (NONE) | | | 54FCT240AT (GEN) | 529 |
| 5962-9221305M2A | B | 09/03/1996 | 2 | IDT | | Y | IDT54FCT240CTLB | 529 |
| 5962-9221305MRA | B | 09/03/1996 | 2 | IDT | | Y | IDT54FCT240CTDB | 529 |
| 5962-9221305MRA | B | 09/03/1996 | 2 | TI | | Y | CY54FCT240CTDMB | 529 |
| 5962-9221305MSA | B | 09/03/1996 | | (NONE) | 04/29/2002 | | 54FCT240CT (GEN) | 529 |
| 5962-9221306M2A | B | 09/03/1996 | | (NONE) | | | 54FCT240CT (GEN) | 529 |
| 5962-9221306MRA | B | 09/03/1996 | | (NONE) | | | 54FCT240CT (GEN) | 529 |
| 5962-9221401M2A | B | 06/28/1996 | 2 | IDT | | Y | IDT54FCT245TLB | 590 |
| 5962-9221401M2A | B | 06/28/1996 | 2 | TI | | Y | CY54FCT245TLMB | 590 |
| 5962-9221401MRA | B | 06/28/1996 | 2 | IDT | | Y | IDT54FCT245TDB | 590 |
| 5962-9221401MRA | B | 06/28/1996 | 2 | TI | | Y | CY54FCT245TDMB | 590 |
| 5962-9221401MSA | B | 06/28/1996 | | (NONE) | 04/29/2002 | | 54FCT245T (GEN) | 590 |
| 5962-9221402M2A | B | 06/28/1996 | | (NONE) | | | 54FCT245T (GEN) | 590 |
| 5962-9221402MRA | B | 06/28/1996 | | (NONE) | | | 54FCT245T (GEN) | 590 |
| 5962-9221403M2A | B | 06/28/1996 | 2 | IDT | | Y | IDT54FCT245ATLB | 590 |
| 5962-9221403M2A | B | 06/28/1996 | 2 | TI | | Y | CY54FCT245ATLMB | 590 |
| 5962-9221403MRA | B | 06/28/1996 | 2 | IDT | | Y | IDT54FCT245ATDB | 590 |
| 5962-9221403MRA | B | 06/28/1996 | 2 | TI | | Y | CY54FCT245ATDMB | 590 |
| 5962-9221403MSA | B | 06/28/1996 | | (NONE) | 04/29/2002 | | 54FCT245AT (GEN) | 590 |
| 5962-9221404M2A | B | 06/28/1996 | | (NONE) | | | 54FCT245AT (GEN) | 590 |
| 5962-9221404MRA | B | 06/28/1996 | | (NONE) | | | 54FCT245AT (GEN) | 590 |
| 5962-9221405M2A | B | 06/28/1996 | 2 | IDT | | Y | IDT54FCT245CTLB | 590 |
| 5962-9221405M2A | B | 06/28/1996 | 2 | TI | | Y | CY54FCT245CTLMB | 590 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9221405MRA | B | 06/28/1996 | 2 | IDT | | Y | IDT54FCT245CTDB | 590 |
| 5962-9221405MRA | B | 06/28/1996 | 2 | TI | | Y | CY54FCT245CTDMB | 590 |
| 5962-9221405MSA | B | 06/28/1996 | | (NONE) | 04/29/2002 | | 54FCT245CT (GEN) | 590 |
| 5962-9221406M2A | B | 06/28/1996 | | (NONE) | | | 54FCT245CT (GEN) | 590 |
| 5962-9221406MRA | B | 06/28/1996 | | (NONE) | | | 54FCT245CT (GEN) | 590 |
| 5962-9221501M2A | C | 10/28/1996 | 1 | IDT | | Y | IDT54FCT273TLB | 159 |
| 5962-9221501MRA | C | 10/28/1996 | 1 | IDT | | Y | IDT54FCT273TDB | 159 |
| 5962-9221501MSA | C | 10/28/1996 | | (NONE) | 04/29/2002 | | 54FCT273T (GEN) | 159 |
| 5962-9221502M2A | C | 10/28/1996 | | (NONE) | | | 54FCT273T (GEN) | 159 |
| 5962-9221502MRA | C | 10/28/1996 | | (NONE) | | | 54FCT273T (GEN) | 159 |
| 5962-9221503M2A | C | 10/28/1996 | 1 | IDT | | Y | IDT54FCT273ATLB | 159 |
| 5962-9221503M2A | C | 10/28/1996 | 2 | TI | | Y | CY54FCT273ATLMB | 159 |
| 5962-9221503MRA | C | 10/28/1996 | 1 | IDT | | Y | IDT54FCT273ATDB | 159 |
| 5962-9221503MRA | C | 10/28/1996 | 2 | TI | | Y | CY54FCT273ATDMB | 159 |
| 5962-9221503MSA | C | 10/28/1996 | | (NONE) | 04/29/2002 | | 54FCT273AT (GEN) | 159 |
| 5962-9221504M2A | C | 10/28/1996 | | (NONE) | | | 54FCT273AT (GEN) | 159 |
| 5962-9221504MRA | C | 10/28/1996 | | (NONE) | | | 54FCT273AT (GEN) | 159 |
| 5962-9221505M2A | C | 10/28/1996 | 1 | IDT | | Y | IDT54FCT273CTLB | 159 |
| 5962-9221505MRA | C | 10/28/1996 | 1 | IDT | | Y | IDT54FCT273CTDB | 159 |
| 5962-9221505MSA | C | 10/28/1996 | | (NONE) | 04/29/2002 | | 54FCT273CT (GEN) | 159 |
| 5962-9221506M2A | C | 10/28/1996 | | (NONE) | | | 54FCT273CT (GEN) | 159 |
| 5962-9221506MRA | C | 10/28/1996 | | (NONE) | | | 54FCT273CT (GEN) | 159 |
| 5962-9221601M2A | A | 09/30/1996 | | (NONE) | | | 54FCT299T (GEN) | 228 |
| 5962-9221601MRA | A | 09/30/1996 | | (NONE) | | | 54FCT299T (GEN) | 228 |
| 5962-9221602M2A | A | 09/30/1996 | 1 | IDT | | Y | IDT54FCT299TLB | 228 |
| 5962-9221602MRA | A | 09/30/1996 | 1 | IDT | | Y | IDT54FCT299TDB | 228 |
| 5962-9221602MSA | A | 09/30/1996 | | (NONE) | 04/29/2002 | | 54FCT299T (GEN) | 228 |
| 5962-9221603M2A | A | 09/30/1996 | | (NONE) | | | 54FCT299AT (GEN) | 228 |
| 5962-9221603MRA | A | 09/30/1996 | | (NONE) | | | 54FCT299AT (GEN) | 228 |
| 5962-9221604M2A | A | 09/30/1996 | 1 | IDT | | Y | IDT54FCT299ATLB | 228 |
| 5962-9221604MRA | A | 09/30/1996 | 1 | IDT | | Y | IDT54FCT299ATDB | 228 |
| 5962-9221604MSA | A | 09/30/1996 | | (NONE) | 04/29/2002 | | 54FCT299AT (GEN) | 228 |
| 5962-9221605M2A | A | 09/30/1996 | | (NONE) | | | 54FCT299CT (GEN) | 228 |
| 5962-9221605MRA | A | 09/30/1996 | | (NONE) | | | 54FCT299CT (GEN) | 228 |
| 5962-9221606M2A | A | 09/30/1996 | 1 | IDT | | Y | IDT54FCT299CTLB | 228 |
| 5962-9221606MRA | A | 09/30/1996 | 1 | IDT | | Y | IDT54FCT299CTDB | 228 |
| 5962-9221606MSA | A | 09/30/1996 | | (NONE) | 04/29/2002 | | 54FCT299CT (GEN) | 228 |
| 5962-9221701M2A | B | 07/15/1996 | 2 | IDT | | Y | IDT54FCT373TLB | 341 |
| 5962-9221701MRA | B | 07/15/1996 | 2 | IDT | | Y | IDT54FCT373TDB | 341 |
| 5962-9221701MRA | B | 07/15/1996 | 2 | TI | | Y | CY54FCT373TDMB | 341 |
| 5962-9221701MSA | B | 07/15/1996 | | (NONE) | 04/29/2002 | | 54FCT373T (GEN) | 341 |
| 5962-9221702M2A | B | 07/15/1996 | 2 | IDT | | Y | IDT54FCT373ATLB | 341 |
| 5962-9221702MRA | B | 07/15/1996 | 2 | IDT | | Y | IDT54FCT373ATDB | 341 |
| 5962-9221702MRA | B | 07/15/1996 | 2 | TI | | Y | CY54FCT373ATDMB | 341 |
| 5962-9221702MSA | B | 07/15/1996 | | (NONE) | 04/29/2002 | | 54FCT373AT (GEN) | 341 |
| 5962-9221703M2A | B | 07/15/1996 | 2 | IDT | | Y | IDT54FCT373CTLB | 341 |
| 5962-9221703M2A | B | 07/15/1996 | 2 | TI | | Y | CY54FCT373CTLMB | 341 |
| 5962-9221703MRA | B | 07/15/1996 | 2 | IDT | | Y | IDT54FCT373CTDB | 341 |
| 5962-9221703MSA | B | 07/15/1996 | | (NONE) | 04/29/2002 | | 54FCT373CT (GEN) | 341 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9221704M2A | B | 07/15/1996 | | (NONE) | | | 54FCT373T (GEN) | 341 |
| 5962-9221704MRA | B | 07/15/1996 | | (NONE) | | | 54FCT373T (GEN) | 341 |
| 5962-9221705M2A | B | 07/15/1996 | | (NONE) | | | 54FCT373AT (GEN) | 341 |
| 5962-9221705MRA | B | 07/15/1996 | | (NONE) | | | 54FCT373AT (GEN) | 341 |
| 5962-9221706M2A | B | 07/15/1996 | | (NONE) | | | 54FCT373CT (GEN) | 341 |
| 5962-9221706MRA | B | 07/15/1996 | | (NONE) | | | 54FCT373CT (GEN) | 341 |
| 5962-9221801M2A | A | 08/09/1996 | | (NONE) | | | 54FCT374T (GEN) | 159 |
| 5962-9221801MRA | A | 08/09/1996 | | (NONE) | | | 54FCT374T (GEN) | 159 |
| 5962-9221802M2A | A | 08/09/1996 | 2 | IDT | | Y | IDT54FCT374TLB | 159 |
| 5962-9221802M2A | A | 08/09/1996 | 2 | TI | | Y | CY54FCT374TLMB | 159 |
| 5962-9221802MRA | A | 08/09/1996 | 2 | IDT | | Y | IDT54FCT374TDB | 159 |
| 5962-9221802MRA | A | 08/09/1996 | 2 | TI | | Y | CY54FCT374TDMB | 159 |
| 5962-9221802MSA | A | 08/09/1996 | | (NONE) | 04/29/2002 | | 54FCT374T (GEN) | 159 |
| 5962-9221803M2A | A | 08/09/1996 | | (NONE) | | | 54FCT374AT (GEN) | 159 |
| 5962-9221803MRA | A | 08/09/1996 | | (NONE) | | | 54FCT374AT (GEN) | 159 |
| 5962-9221804M2A | A | 08/09/1996 | 2 | IDT | | Y | IDT54FCT374ATLB | 159 |
| 5962-9221804M2A | A | 08/09/1996 | 2 | TI | | Y | CY54FCT374ATLMB | 159 |
| 5962-9221804MRA | A | 08/09/1996 | 2 | IDT | | Y | IDT54FCT374ATDB | 159 |
| 5962-9221804MRA | A | 08/09/1996 | 2 | TI | | Y | CY54FCT374ATDMB | 159 |
| 5962-9221804MSA | A | 08/09/1996 | | (NONE) | 04/29/2002 | | 54FCT374AT (GEN) | 159 |
| 5962-9221805M2A | A | 08/09/1996 | | (NONE) | | | 54FCT374CT (GEN) | 159 |
| 5962-9221805MRA | A | 08/09/1996 | | (NONE) | | | 54FCT374CT (GEN) | 159 |
| 5962-9221806M2A | A | 08/09/1996 | 2 | IDT | | Y | IDT54FCT374CTLB | 159 |
| 5962-9221806M2A | A | 08/09/1996 | 2 | TI | | Y | CY54FCT374CTLMB | 159 |
| 5962-9221806MRA | A | 08/09/1996 | 2 | IDT | | Y | IDT54FCT374CTDB | 159 |
| 5962-9221806MRA | A | 08/09/1996 | 2 | TI | | Y | CY54FCT374CTDMB | 159 |
| 5962-9221806MSA | A | 08/09/1996 | | (NONE) | 04/29/2002 | | 54FCT374CT (GEN) | 159 |
| 5962-9221901M2A | A | 04/16/1996 | 2 | IDT | | Y | IDT54FCT377TLB | 159 |
| 5962-9221901MRA | A | 04/16/1996 | 2 | IDT | | Y | IDT54FCT377TDB | 159 |
| 5962-9221901MSA | A | 04/16/1996 | | (NONE) | 04/29/2002 | | 54FCT377T (GEN) | 159 |
| 5962-9221902M2A | A | 04/16/1996 | 2 | IDT | | Y | IDT54FCT377ATLB | 159 |
| 5962-9221902M2A | A | 04/16/1996 | 2 | TI | | Y | CY54FCT377ATLMB | 159 |
| 5962-9221902MRA | A | 04/16/1996 | 2 | IDT | | Y | IDT54FCT377ATDB | 159 |
| 5962-9221902MSA | A | 04/16/1996 | | (NONE) | 04/29/2002 | | 54FCT377AT (GEN) | 159 |
| 5962-9221903M2A | A | 04/16/1996 | 2 | IDT | | Y | IDT54FCT377CTLB | 159 |
| 5962-9221903M2A | A | 04/16/1996 | 2 | TI | | Y | CY54FCT377CTLMB | 159 |
| 5962-9221903MRA | A | 04/16/1996 | 2 | IDT | | Y | IDT54FCT377CTDB | 159 |
| 5962-9221903MSA | A | 04/16/1996 | | (NONE) | 04/29/2002 | | 54FCT377CT (GEN) | 159 |
| 5962-9221904M2A | A | 04/16/1996 | | (NONE) | | | 54FCT377T (GEN) | 159 |
| 5962-9221904MRA | A | 04/16/1996 | | (NONE) | | | 54FCT377T (GEN) | 159 |
| 5962-9221905M2A | A | 04/16/1996 | | (NONE) | | | 54FCT377AT (GEN) | 159 |
| 5962-9221905MRA | A | 04/16/1996 | | (NONE) | | | 54FCT377AT (GEN) | 159 |
| 5962-9221906M2A | A | 04/16/1996 | | (NONE) | | | 54FCT377CT (GEN) | 159 |
| 5962-9221906MRA | A | 04/16/1996 | | (NONE) | | | 54FCT377CT (GEN) | 159 |
| 5962-9222001M2A | C | 10/15/1996 | | (NONE) | | | 54FCT540T (GEN) | 529 |
| 5962-9222001MRA | C | 10/15/1996 | | (NONE) | | | 54FCT540T (GEN) | 529 |
| 5962-9222002M2A | C | 10/15/1996 | | (NONE) | 04/27/1998 | | 54FCT540T (GEN) | 529 |
| 5962-9222002MRA | C | 10/15/1996 | | (NONE) | 04/27/1998 | | 54FCT540T (GEN) | 529 |
| 5962-9222002MSA | C | 10/15/1996 | | (NONE) | 04/27/1998 | | 54FCT540T (GEN) | 529 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9222003M2A | C | 10/15/1996 | | (NONE) | | | 54FCT540AT (GEN) | 529 |
| 5962-9222003MRA | C | 10/15/1996 | | (NONE) | | | 54FCT540AT (GEN) | 529 |
| 5962-9222004M2A | C | 10/15/1996 | | (NONE) | 04/27/1998 | | 54FCT540AT (GEN) | 529 |
| 5962-9222004MRA | C | 10/15/1996 | | (NONE) | 04/27/1998 | | 54FCT540AT (GEN) | 529 |
| 5962-9222004MSA | C | 10/15/1996 | | (NONE) | 04/27/1998 | | 54FCT540AT (GEN) | 529 |
| 5962-9222005M2A | C | 10/15/1996 | | (NONE) | | | 54FCT540CT (GEN) | 529 |
| 5962-9222005MRA | C | 10/15/1996 | | (NONE) | | | 54FCT540CT (GEN) | 529 |
| 5962-9222006M2A | C | 10/15/1996 | 2 | TI | | Y | CY54FCT540CTLMB | 529 |
| 5962-9222006MRA | C | 10/15/1996 | 2 | TI | | Y | CY54FCT540CTDMB | 529 |
| 5962-9222006MSA | C | 10/15/1996 | | (NONE) | 04/27/1998 | | 54FCT540CT (GEN) | 529 |
| 5962-9222101M3A | C | 09/06/1996 | 2 | IDT | | Y | IDT54FCT543TLB | 590 |
| 5962-9222101M3A | C | 09/06/1996 | 2 | TI | | Y | CY54FCT543TLMB | 590 |
| 5962-9222101MKA | C | 09/06/1996 | | (NONE) | 04/29/2002 | | 54FCT543T (GEN) | 590 |
| 5962-9222101MLA | C | 09/06/1996 | 2 | IDT | | Y | IDT54FCT543TDB | 590 |
| 5962-9222101MLA | C | 09/06/1996 | 2 | TI | | Y | CY54FCT543TDMB | 590 |
| 5962-9222102M3A | C | 09/06/1996 | 2 | IDT | | Y | IDT54FCT543ATLB | 590 |
| 5962-9222102MKA | C | 09/06/1996 | | (NONE) | 04/29/2002 | | 54FCT543AT (GEN) | 590 |
| 5962-9222102MLA | C | 09/06/1996 | 2 | IDT | | Y | IDT54FCT543ATDB | 590 |
| 5962-9222103M3A | C | 09/06/1996 | 2 | IDT | | Y | IDT54FCT543CTLB | 590 |
| 5962-9222103MKA | C | 09/06/1996 | | (NONE) | 04/29/2002 | | 54FCT543CT (GEN) | 590 |
| 5962-9222103MLA | C | 09/06/1996 | 2 | IDT | | Y | IDT54FCT543CTDB | 590 |
| 5962-9222104M3A | C | 09/06/1996 | | (NONE) | | | 54FCT543T (GEN) | 590 |
| 5962-9222104MLA | C | 09/06/1996 | | (NONE) | | | 54FCT543T (GEN) | 590 |
| 5962-9222105M3A | C | 09/06/1996 | | (NONE) | | | 54FCT543AT (GEN) | 590 |
| 5962-9222105MLA | C | 09/06/1996 | | (NONE) | | | 54FCT543AT (GEN) | 590 |
| 5962-9222106M3A | C | 09/06/1996 | | (NONE) | | | 54FCT543CT (GEN) | 590 |
| 5962-9222106MLA | C | 09/06/1996 | | (NONE) | | | 54FCT543CT (GEN) | 590 |
| 5962-9222201M2A | B | 08/09/1996 | 2 | IDT | | Y | IDT54FCT574TLB | 159 |
| 5962-9222201MRA | B | 08/09/1996 | 2 | IDT | | Y | IDT54FCT574TDB | 159 |
| 5962-9222201MSA | B | 08/09/1996 | | (NONE) | 04/29/2002 | | 54FCT574T (GEN) | 159 |
| 5962-9222202M2A | B | 08/09/1996 | | (NONE) | | | 54FCT574T (GEN) | 159 |
| 5962-9222202MRA | B | 08/09/1996 | | (NONE) | | | 54FCT574T (GEN) | 159 |
| 5962-9222203M2A | B | 08/09/1996 | 2 | IDT | | Y | IDT54FCT574ATLB | 159 |
| 5962-9222203M2A | B | 08/09/1996 | 2 | TI | | Y | CY54FCT574ATLMB | 159 |
| 5962-9222203MRA | B | 08/09/1996 | 2 | IDT | | Y | IDT54FCT574ATDB | 159 |
| 5962-9222203MRA | B | 08/09/1996 | 2 | TI | | Y | CY54FCT574ATDMB | 159 |
| 5962-9222203MSA | B | 08/09/1996 | | (NONE) | 04/29/2002 | | 54FCT574AT (GEN) | 159 |
| 5962-9222204M2A | B | 08/09/1996 | | (NONE) | | | 54FCT574AT (GEN) | 159 |
| 5962-9222204MRA | B | 08/09/1996 | | (NONE) | | | 54FCT574AT (GEN) | 159 |
| 5962-9222205M2A | B | 08/09/1996 | 2 | IDT | | Y | IDT54FCT574CTLB | 159 |
| 5962-9222205MRA | B | 08/09/1996 | 2 | IDT | | Y | IDT54FCT574CTDB | 159 |
| 5962-9222205MRA | B | 08/09/1996 | 2 | TI | | Y | CY54FCT574CTDMB | 159 |
| 5962-9222205MSA | B | 08/09/1996 | | (NONE) | 04/29/2002 | | 54FCT574CT (GEN) | 159 |
| 5962-9222206M2A | B | 08/09/1996 | | (NONE) | | | 54FCT574CT (GEN) | 159 |
| 5962-9222206MRA | B | 08/09/1996 | | (NONE) | | | 54FCT574CT (GEN) | 159 |
| 5962-9222301M3A | C | 06/28/1996 | 2 | IDT | | Y | IDT54FCT646TLB | 590 |
| 5962-9222301M3A | C | 06/28/1996 | 2 | TI | | Y | CY54FCT646TLMB | 590 |
| 5962-9222301MKA | C | 06/28/1996 | | (NONE) | 04/29/2002 | | 54FCT646T (GEN) | 590 |
| 5962-9222301MLA | C | 06/28/1996 | 2 | IDT | | Y | IDT54FCT646TDB | 590 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9222302M3A | C | 06/28/1996 | | (NONE) | | | 54FCT646T (GEN) | 590 |
| 5962-9222302MLA | C | 06/28/1996 | | (NONE) | | | 54FCT646T (GEN) | 590 |
| 5962-9222303M3A | C | 06/28/1996 | 2 | IDT | | Y | IDT54FCT646ATLB | 590 |
| 5962-9222303M3A | C | 06/28/1996 | 2 | TI | | Y | CY54FCT646ATLMB | 590 |
| 5962-9222303MKA | C | 06/28/1996 | | (NONE) | 04/29/2002 | | 54FCT646AT (GEN) | 590 |
| 5962-9222303MLA | C | 06/28/1996 | 2 | IDT | | Y | IDT54FCT646ATDB | 590 |
| 5962-9222303MLA | C | 06/28/1996 | 2 | TI | | Y | CY54FCT646ATDMB | 590 |
| 5962-9222304M3A | C | 06/28/1996 | | (NONE) | | | 54FCT646AT (GEN) | 590 |
| 5962-9222304MLA | C | 06/28/1996 | | (NONE) | | | 54FCT646AT (GEN) | 590 |
| 5962-9222305M3A | C | 06/28/1996 | 2 | IDT | | Y | IDT54FCT646CTLB | 590 |
| 5962-9222305M3A | C | 06/28/1996 | 2 | TI | | Y | CY54FCT646CTLMB | 590 |
| 5962-9222305MKA | C | 06/28/1996 | | (NONE) | 04/29/2002 | | 54FCT646CT (GEN) | 590 |
| 5962-9222305MLA | C | 06/28/1996 | 2 | IDT | | Y | IDT54FCT646CTDB | 590 |
| 5962-9222306M3A | C | 06/28/1996 | | (NONE) | | | 54FCT646CT (GEN) | 590 |
| 5962-9222306MLA | C | 06/28/1996 | | (NONE) | | | 54FCT646CT (GEN) | 590 |
| 5962-9222501M3A | B | 09/03/1996 | 1 | IDT | | Y | IDT54FCT821ATLB | 421 |
| 5962-9222501MKA | B | 09/03/1996 | | (NONE) | 04/29/2002 | | 54FCT821AT (GEN) | 421 |
| 5962-9222501MLA | B | 09/03/1996 | 1 | IDT | | Y | IDT54FCT821ATDB | 421 |
| 5962-9222502M3A | B | 09/03/1996 | | (NONE) | | | 54FCT821AT (GEN) | 421 |
| 5962-9222502MLA | B | 09/03/1996 | | (NONE) | | | 54FCT821AT (GEN) | 421 |
| 5962-9222503M3A | B | 09/03/1996 | 1 | IDT | | Y | IDT54FCT821BTLB | 421 |
| 5962-9222503MKA | B | 09/03/1996 | | (NONE) | 04/29/2002 | | 54FCT821BT (GEN) | 421 |
| 5962-9222503MLA | B | 09/03/1996 | 1 | IDT | | Y | IDT54FCT821BTDB | 421 |
| 5962-9222504M3A | B | 09/03/1996 | | (NONE) | | | 54FCT821BT (GEN) | 421 |
| 5962-9222504MLA | B | 09/03/1996 | | (NONE) | | | 54FCT821BT (GEN) | 421 |
| 5962-9222505M3A | B | 09/03/1996 | 1 | IDT | | Y | IDT54FCT821CTLB | 421 |
| 5962-9222505MKA | B | 09/03/1996 | | (NONE) | 04/29/2002 | | 54FCT821CT (GEN) | 421 |
| 5962-9222505MLA | B | 09/03/1996 | 1 | IDT | | Y | IDT54FCT821CTDB | 421 |
| 5962-9222506M3A | B | 09/03/1996 | | (NONE) | | | 54FCT821CT (GEN) | 421 |
| 5962-9222506MLA | B | 09/03/1996 | | (NONE) | | | 54FCT821CT (GEN) | 421 |
| 5962-9222801M3A | | 10/18/1994 | | (NONE) | 04/27/1998 | | 54FCT841AT (GEN) | 342 |
| 5962-9222801MKA | | 10/18/1994 | | (NONE) | 04/27/1998 | | 54FCT841AT (GEN) | 342 |
| 5962-9222801MLA | | 10/18/1994 | | (NONE) | 04/27/1998 | | 54FCT841AT (GEN) | 342 |
| 5962-9222802M3A | | 10/18/1994 | | (NONE) | 04/27/1998 | | 54FCT841BT (GEN) | 342 |
| 5962-9222802MKA | | 10/18/1994 | | (NONE) | 04/27/1998 | | 54FCT841BT (GEN) | 342 |
| 5962-9222802MLA | | 10/18/1994 | | (NONE) | 04/27/1998 | | 54FCT841BT (GEN) | 342 |
| 5962-9222803M3A | | 10/18/1994 | | (NONE) | 04/27/1998 | | 54FCT841CT (GEN) | 342 |
| 5962-9222803MKA | | 10/18/1994 | | (NONE) | 04/27/1998 | | 54FCT841CT (GEN) | 342 |
| 5962-9222803MLA | | 10/18/1994 | | (NONE) | 04/27/1998 | | 54FCT841CT (GEN) | 342 |
| 5962-9222901M3A | B | 09/03/1996 | | (NONE) | 04/27/1998 | | 54FCT823AT (GEN) | 229 |
| 5962-9222901MKA | B | 09/03/1996 | | (NONE) | 04/27/1998 | | 54FCT823AT (GEN) | 229 |
| 5962-9222901MLA | B | 09/03/1996 | | (NONE) | 04/27/1998 | | 54FCT823AT (GEN) | 229 |
| 5962-9222902M3A | B | 09/03/1996 | | (NONE) | | | 54FCT823AT (GEN) | 229 |
| 5962-9222902MLA | B | 09/03/1996 | | (NONE) | | | 54FCT823AT (GEN) | 229 |
| 5962-9222903M3A | B | 09/03/1996 | | (NONE) | 04/27/1998 | | 54FCT823BT (GEN) | 229 |
| 5962-9222903MKA | B | 09/03/1996 | | (NONE) | 04/27/1998 | | 54FCT823BT (GEN) | 229 |
| 5962-9222903MLA | B | 09/03/1996 | | (NONE) | 04/27/1998 | | 54FCT823BT (GEN) | 229 |
| 5962-9222904M3A | B | 09/03/1996 | | (NONE) | | | 54FCT823BT (GEN) | 229 |
| 5962-9222904MLA | B | 09/03/1996 | | (NONE) | | | 54FCT823BT (GEN) | 229 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9222905M3A | B | 09/03/1996 | | (NONE) | 04/27/1998 | | 54FCT823CT (GEN) | 229 |
| 5962-9222905MKA | B | 09/03/1996 | | (NONE) | 04/27/1998 | | 54FCT823CT (GEN) | 229 |
| 5962-9222905MLA | B | 09/03/1996 | | (NONE) | 04/27/1998 | | 54FCT823CT (GEN) | 229 |
| 5962-9222906M3A | B | 09/03/1996 | | (NONE) | | | 54FCT823CT (GEN) | 229 |
| 5962-9222906MLA | B | 09/03/1996 | | (NONE) | | | 54FCT823CT (GEN) | 229 |
| 5962-9223001M3A | A | 09/06/1996 | | (NONE) | 05/31/1998 | | 54FCT825AT (GEN) | 421 |
| 5962-9223001MKA | A | 09/06/1996 | | (NONE) | 04/27/1998 | | 54FCT825AT (GEN) | 421 |
| 5962-9223001MLA | A | 09/06/1996 | | (NONE) | 05/31/1998 | | 54FCT825AT (GEN) | 421 |
| 5962-9223002M3A | A | 09/06/1996 | | (NONE) | | | 54FCT825AT (GEN) | 421 |
| 5962-9223002MLA | A | 09/06/1996 | | (NONE) | | | 54FCT825AT (GEN) | 421 |
| 5962-9223003M3A | A | 09/06/1996 | | (NONE) | 05/31/1998 | | 54FCT825BT (GEN) | 421 |
| 5962-9223003MKA | A | 09/06/1996 | | (NONE) | 04/27/1998 | | 54FCT825BT (GEN) | 421 |
| 5962-9223003MLA | A | 09/06/1996 | | (NONE) | 05/31/1998 | | 54FCT825BT (GEN) | 421 |
| 5962-9223004M3A | A | 09/06/1996 | | (NONE) | | | 54FCT825BT (GEN) | 421 |
| 5962-9223004MLA | A | 09/06/1996 | | (NONE) | | | 54FCT825BT (GEN) | 421 |
| 5962-9223005M3A | A | 09/06/1996 | | (NONE) | 05/31/1998 | | 54FCT825CT (GEN) | 421 |
| 5962-9223005MKA | A | 09/06/1996 | | (NONE) | 04/27/1998 | | 54FCT825CT (GEN) | 421 |
| 5962-9223005MLA | A | 09/06/1996 | | (NONE) | 05/31/1998 | | 54FCT825CT (GEN) | 421 |
| 5962-9223006M3A | A | 09/06/1996 | | (NONE) | | | 54FCT825CT (GEN) | 421 |
| 5962-9223006MLA | A | 09/06/1996 | | (NONE) | | | 54FCT825CT (GEN) | 421 |
| 5962-9223201M2A | | 08/27/1993 | | (NONE) | 07/31/1995 | | 54FCT241T (GEN) | 529 |
| 5962-9223201MRA | | 08/27/1993 | | (NONE) | 07/31/1995 | | 54FCT241T (GEN) | 529 |
| 5962-9223201MSA | | 08/27/1993 | | (NONE) | 07/31/1995 | | 54FCT241T (GEN) | 529 |
| 5962-9223202M2A | | 08/27/1993 | | (NONE) | | | 54FCT241T (GEN) | 529 |
| 5962-9223202MRA | | 08/27/1993 | | (NONE) | | | 54FCT241T (GEN) | 529 |
| 5962-9223203M2A | | 08/27/1993 | | (NONE) | 07/31/1995 | | 54FCT241AT (GEN) | 529 |
| 5962-9223203MRA | | 08/27/1993 | | (NONE) | 07/31/1995 | | 54FCT241AT (GEN) | 529 |
| 5962-9223203MSA | | 08/27/1993 | | (NONE) | 07/31/1995 | | 54FCT241AT (GEN) | 529 |
| 5962-9223204M2A | | 08/27/1993 | | (NONE) | | | 54FCT241AT (GEN) | 529 |
| 5962-9223204MRA | | 08/27/1993 | | (NONE) | | | 54FCT241AT (GEN) | 529 |
| 5962-9223205M2A | | 08/27/1993 | | (NONE) | 07/31/1995 | | 54FCT241CT (GEN) | 529 |
| 5962-9223205MRA | | 08/27/1993 | | (NONE) | 07/31/1995 | | 54FCT241CT (GEN) | 529 |
| 5962-9223205MSA | | 08/27/1993 | | (NONE) | 07/31/1995 | | 54FCT241CT (GEN) | 529 |
| 5962-9223206M2A | | 08/27/1993 | | (NONE) | | | 54FCT241CT (GEN) | 529 |
| 5962-9223206MRA | | 08/27/1993 | | (NONE) | | | 54FCT241CT (GEN) | 529 |
| 5962-9223301M2A | | 06/29/1993 | | (NONE) | | | 54FCT138T (GEN) | 282 |
| 5962-9223301MEA | | 06/29/1993 | | (NONE) | | | 54FCT138T (GEN) | 282 |
| 5962-9223302M2A | | 06/29/1993 | 1 | IDT | | Y | IDT54FCT138TLB | 282 |
| 5962-9223302M2A | | 06/29/1993 | 2 | TI | | Y | CY54FCT138TLMB | 282 |
| 5962-9223302MEA | | 06/29/1993 | 1 | IDT | | Y | IDT54FCT138TDB | 282 |
| 5962-9223302MEA | | 06/29/1993 | 2 | TI | | Y | CY54FCT138TDMB | 282 |
| 5962-9223302MFA | | 06/29/1993 | | (NONE) | 04/29/2002 | | 54FCT138T (GEN) | 282 |
| 5962-9223303M2A | | 06/29/1993 | | (NONE) | | | 54FCT138AT (GEN) | 282 |
| 5962-9223303MEA | | 06/29/1993 | | (NONE) | | | 54FCT138AT (GEN) | 282 |
| 5962-9223304M2A | | 06/29/1993 | 1 | IDT | | Y | IDT54FCT138ATLB | 282 |
| 5962-9223304MEA | | 06/29/1993 | 1 | IDT | | Y | IDT54FCT138ATDB | 282 |
| 5962-9223304MFA | | 06/29/1993 | | (NONE) | 04/29/2002 | | 54FCT138AT (GEN) | 282 |
| 5962-9223305M2A | | 06/29/1993 | | (NONE) | | | 54FCT138CT (GEN) | 282 |
| 5962-9223305MEA | | 06/29/1993 | | (NONE) | | | 54FCT138CT (GEN) | 282 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9223306M2A | | 06/29/1993 | 1 | IDT | | Y | IDT54FCT138CTLB | 282 |
| 5962-9223306M2A | | 06/29/1993 | 2 | TI | | Y | CY54FCT138CTLMB | 282 |
| 5962-9223306MEA | | 06/29/1993 | 1 | IDT | | Y | IDT54FCT138CTDB | 282 |
| 5962-9223306MEA | | 06/29/1993 | 2 | TI | | Y | CY54FCT138CTDMB | 282 |
| 5962-9223306MFA | | 06/29/1993 | | (NONE) | 04/29/2002 | | 54FCT138CT (GEN) | 282 |
| 5962-9223401M2A | | 06/28/1993 | | (NONE) | | | 54FCT521T (GEN) | 209 |
| 5962-9223401MRA | | 06/28/1993 | | (NONE) | | | 54FCT521T (GEN) | 209 |
| 5962-9223402M2A | | 06/28/1993 | 2 | IDT | | Y | IDT54FCT521TLB | 209 |
| 5962-9223402MRA | | 06/28/1993 | 2 | IDT | | Y | IDT54FCT521TDB | 209 |
| 5962-9223402MSA | | 06/28/1993 | | (NONE) | 04/29/2002 | | 54FCT521T (GEN) | 209 |
| 5962-9223403M2A | | 06/28/1993 | | (NONE) | | | 54FCT521AT (GEN) | 209 |
| 5962-9223403MRA | | 06/28/1993 | | (NONE) | | | 54FCT521AT (GEN) | 209 |
| 5962-9223404M2A | | 06/28/1993 | 2 | IDT | | Y | IDT54FCT521ATLB | 209 |
| 5962-9223404MRA | | 06/28/1993 | 2 | IDT | | Y | IDT54FCT521ATDB | 209 |
| 5962-9223404MSA | | 06/28/1993 | | (NONE) | 04/29/2002 | | 54FCT521AT (GEN) | 209 |
| 5962-9223405M2A | | 06/28/1993 | | (NONE) | | | 54FCT521BT (GEN) | 209 |
| 5962-9223405MRA | | 06/28/1993 | | (NONE) | | | 54FCT521BT (GEN) | 209 |
| 5962-9223406M2A | | 06/28/1993 | 2 | IDT | | Y | IDT54FCT521BTLB | 209 |
| 5962-9223406MRA | | 06/28/1993 | 2 | IDT | | Y | IDT54FCT521BTDB | 209 |
| 5962-9223406MSA | | 06/28/1993 | | (NONE) | 04/29/2002 | | 54FCT521BT (GEN) | 209 |
| 5962-9223407M2A | | 06/28/1993 | | (NONE) | | | 54FCT521CT (GEN) | 209 |
| 5962-9223407MRA | | 06/28/1993 | | (NONE) | | | 54FCT521CT (GEN) | 209 |
| 5962-9223408M2A | | 06/28/1993 | 2 | IDT | | Y | IDT54FCT521CTLB | 209 |
| 5962-9223408MRA | | 06/28/1993 | 2 | IDT | | Y | IDT54FCT521CTDB | 209 |
| 5962-9223408MSA | | 06/28/1993 | | (NONE) | 04/29/2002 | | 54FCT521CT (GEN) | 209 |
| 5962-9223601M2A | B | 10/28/1996 | | (NONE) | 04/27/1998 | | 54FCT534T (GEN) | 249 |
| 5962-9223601MRA | B | 10/28/1996 | | (NONE) | 04/27/1998 | | 54FCT534T (GEN) | 249 |
| 5962-9223601MSA | B | 10/28/1996 | | (NONE) | 04/27/1998 | | 54FCT534T (GEN) | 249 |
| 5962-9223602M2A | B | 10/28/1996 | | (NONE) | 04/27/1998 | | 54FCT534AT (GEN) | 249 |
| 5962-9223602MRA | B | 10/28/1996 | | (NONE) | 04/27/1998 | | 54FCT534AT (GEN) | 249 |
| 5962-9223602MSA | B | 10/28/1996 | | (NONE) | 04/27/1998 | | 54FCT534AT (GEN) | 249 |
| 5962-9223603M2A | B | 10/28/1996 | | (NONE) | 04/27/1998 | | 54FCT534CT (GEN) | 249 |
| 5962-9223603MRA | B | 10/28/1996 | | (NONE) | 04/27/1998 | | 54FCT534CT (GEN) | 249 |
| 5962-9223603MSA | B | 10/28/1996 | | (NONE) | 04/27/1998 | | 54FCT534CT (GEN) | 249 |
| 5962-9223604M2A | B | 10/28/1996 | | (NONE) | | | 54FCT534T (GEN) | 249 |
| 5962-9223604MRA | B | 10/28/1996 | | (NONE) | | | 54FCT534T (GEN) | 249 |
| 5962-9223605M2A | B | 10/28/1996 | | (NONE) | | | 54FCT534AT (GEN) | 249 |
| 5962-9223605MRA | B | 10/28/1996 | | (NONE) | | | 54FCT534AT (GEN) | 249 |
| 5962-9223606M2A | B | 10/28/1996 | | (NONE) | | | 54FCT534CT (GEN) | 249 |
| 5962-9223606MRA | B | 10/28/1996 | | (NONE) | | | 54FCT534CT (GEN) | 249 |
| 5962-9223701M2A | B | 03/09/1994 | 1 | IDT | | Y | IDT54FCT541TDB | 529 |
| 5962-9223701M2A | B | 03/09/1994 | 2 | TI | | Y | CY54FCT541TLMB | 529 |
| 5962-9223701MRA | B | 03/09/1994 | 1 | IDT | | Y | IDT54FCT541TDB | 529 |
| 5962-9223701MRA | B | 03/09/1994 | 2 | TI | | Y | CY54FCT541TDMB | 529 |
| 5962-9223701MSA | B | 03/09/1994 | | (NONE) | 04/29/2002 | | 54FCT541T (GEN) | 529 |
| 5962-9223702M2A | B | 03/09/1994 | | (NONE) | | | 54FCT541T (GEN) | 529 |
| 5962-9223702MRA | B | 03/09/1994 | | (NONE) | | | 54FCT541T (GEN) | 529 |
| 5962-9223703M2A | B | 03/09/1994 | 1 | IDT | | Y | IDT54FCT541ATLB | 529 |
| 5962-9223703MRA | B | 03/09/1994 | 1 | IDT | | Y | IDT54FCT541ATDB | 529 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9223703MSA | B | 03/09/1994 | | (NONE) | 04/29/2002 | | 54FCT541AT (GEN) | 529 |
| 5962-9223704M2A | B | 03/09/1994 | | (NONE) | | | 54FCT541AT (GEN) | 529 |
| 5962-9223704MRA | B | 03/09/1994 | | (NONE) | | | 54FCT541AT (GEN) | 529 |
| 5962-9223705M2A | B | 03/09/1994 | 1 | IDT | | Y | IDT54FCT541CTLB | 529 |
| 5962-9223705MRA | B | 03/09/1994 | 1 | IDT | | Y | IDT54FCT541CTDB | 529 |
| 5962-9223705MRA | B | 03/09/1994 | 2 | TI | | Y | CY54FCT541CTDMB | 529 |
| 5962-9223705MSA | B | 03/09/1994 | | (NONE) | 04/29/2002 | | 54FCT541CT (GEN) | 529 |
| 5962-9223706M2A | B | 03/09/1994 | | (NONE) | | | 54FCT541CT (GEN) | 529 |
| 5962-9223706MRA | B | 03/09/1994 | | (NONE) | | | 54FCT541CT (GEN) | 529 |
| 5962-9223801M2A | C | 10/28/1996 | 2 | IDT | | Y | IDT54FCT573TLB | 341 |
| 5962-9223801MRA | C | 10/28/1996 | 2 | IDT | | Y | IDT54FCT573TDB | 341 |
| 5962-9223801MRA | C | 10/28/1996 | 2 | TI | | Y | CY54FCT573TDMB | 341 |
| 5962-9223801MSA | C | 10/28/1996 | | (NONE) | 04/29/2002 | | 54FCT573T (GEN) | 341 |
| 5962-9223802M2A | C | 10/28/1996 | 2 | IDT | | Y | IDT54FCT573ATLB | 341 |
| 5962-9223802M2A | C | 10/28/1996 | 2 | TI | | Y | CY54FCT573ATLMB | 341 |
| 5962-9223802MRA | C | 10/28/1996 | 2 | IDT | | Y | IDT54FCT573ATDB | 341 |
| 5962-9223802MSA | C | 10/28/1996 | | (NONE) | 04/29/2002 | | 54FCT573AT (GEN) | 341 |
| 5962-9223803M2A | C | 10/28/1996 | 2 | IDT | | Y | IDT54FCT573CTLB | 341 |
| 5962-9223803MRA | C | 10/28/1996 | 2 | IDT | | Y | IDT54FCT573CTDB | 341 |
| 5962-9223803MSA | C | 10/28/1996 | | (NONE) | 04/29/2002 | | 54FCT573CT (GEN) | 341 |
| 5962-9223804M2A | C | 10/28/1996 | | (NONE) | | | 54FCT573T (GEN) | 341 |
| 5962-9223804MRA | C | 10/28/1996 | | (NONE) | | | 54FCT573T (GEN) | 341 |
| 5962-9223805M2A | C | 10/28/1996 | | (NONE) | | | 54FCT573AT (GEN) | 341 |
| 5962-9223805MRA | C | 10/28/1996 | | (NONE) | | | 54FCT573AT (GEN) | 341 |
| 5962-9223806M2A | C | 10/28/1996 | | (NONE) | | | 54FCT573CT (GEN) | 341 |
| 5962-9223806MRA | C | 10/28/1996 | | (NONE) | | | 54FCT573CT (GEN) | 341 |
| 5962-9224001M2A | A | 09/06/1996 | | (NONE) | 04/27/1998 | | 54FCT621T (GEN) | 590 |
| 5962-9224001MRA | A | 09/06/1996 | | (NONE) | 04/27/1998 | | 54FCT621T (GEN) | 590 |
| 5962-9224001MSA | A | 09/06/1996 | | (NONE) | 04/27/1998 | | 54FCT621T (GEN) | 590 |
| 5962-9224002M2A | A | 09/06/1996 | | (NONE) | 04/27/1998 | | 54FCT621AT (GEN) | 590 |
| 5962-9224002MRA | A | 09/06/1996 | | (NONE) | 04/27/1998 | | 54FCT621AT (GEN) | 590 |
| 5962-9224002MSA | A | 09/06/1996 | | (NONE) | 04/27/1998 | | 54FCT621AT (GEN) | 590 |
| 5962-9224201M2A | A | 09/06/1996 | | (NONE) | 04/27/1998 | | 54FCT623T (GEN) | 590 |
| 5962-9224201MRA | A | 09/06/1996 | | (NONE) | 04/27/1998 | | 54FCT623T (GEN) | 590 |
| 5962-9224201MSA | A | 09/06/1996 | | (NONE) | 04/27/1998 | | 54FCT623T (GEN) | 590 |
| 5962-9224202M2A | A | 09/06/1996 | | (NONE) | 04/27/1998 | | 54FCT623AT (GEN) | 590 |
| 5962-9224202MRA | A | 09/06/1996 | | (NONE) | 04/27/1998 | | 54FCT623AT (GEN) | 590 |
| 5962-9224202MSA | A | 09/06/1996 | | (NONE) | 04/27/1998 | | 54FCT623AT (GEN) | 590 |
| 5962-9224203M2A | A | 09/06/1996 | | (NONE) | 04/27/1998 | | 54FCT623CT (GEN) | 590 |
| 5962-9224203MRA | A | 09/06/1996 | | (NONE) | 04/27/1998 | | 54FCT623CT (GEN) | 590 |
| 5962-9224203MSA | A | 09/06/1996 | | (NONE) | 04/27/1998 | | 54FCT623CT (GEN) | 590 |
| 5962-9224301M2A | | 06/29/1993 | | (NONE) | | | 54FCT640T (GEN) | 590 |
| 5962-9224301MRA | | 06/29/1993 | | (NONE) | | | 54FCT640T (GEN) | 590 |
| 5962-9224302M2A | | 06/29/1993 | | (NONE) | 09/01/1996 | | 54FCT640T (GEN) | 590 |
| 5962-9224302MRA | | 06/29/1993 | | (NONE) | 09/01/1996 | | 54FCT640T (GEN) | 590 |
| 5962-9224302MSA | | 06/29/1993 | | (NONE) | 09/01/1996 | | 54FCT640T (GEN) | 590 |
| 5962-9224303M2A | | 06/29/1993 | | (NONE) | | | 54FCT640AT (GEN) | 590 |
| 5962-9224303MRA | | 06/29/1993 | | (NONE) | | | 54FCT640AT (GEN) | 590 |
| 5962-9224304M2A | | 06/29/1993 | | (NONE) | 09/01/1996 | | 54FCT640AT (GEN) | 590 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9224304MRA | | 06/29/1993 | | (NONE) | 09/01/1996 | | 54FCT640AT (GEN) | 590 |
| 5962-9224304MSA | | 06/29/1993 | | (NONE) | 09/01/1996 | | 54FCT640AT (GEN) | 590 |
| 5962-9224305M2A | | 06/29/1993 | | (NONE) | | | 54FCT640CT (GEN) | 590 |
| 5962-9224305MRA | | 06/29/1993 | | (NONE) | | | 54FCT640CT (GEN) | 590 |
| 5962-9224306M2A | | 06/29/1993 | | (NONE) | 09/01/1996 | | 54FCT640CT (GEN) | 590 |
| 5962-9224306MRA | | 06/29/1993 | | (NONE) | 09/01/1996 | | 54FCT640CT (GEN) | 590 |
| 5962-9224306MSA | | 06/29/1993 | | (NONE) | 09/01/1996 | | 54FCT640CT (GEN) | 590 |
| 5962-9224401M2A | C | 09/06/1996 | | (NONE) | 04/27/1998 | | 54FCT645T (GEN) | 590 |
| 5962-9224401MRA | C | 09/06/1996 | | (NONE) | 04/27/1998 | | 54FCT645T (GEN) | 590 |
| 5962-9224401MSA | C | 09/06/1996 | | (NONE) | 04/27/1998 | | 54FCT645T (GEN) | 590 |
| 5962-9224402M2A | C | 09/06/1996 | | (NONE) | 04/27/1998 | | 54FCT645AT (GEN) | 590 |
| 5962-9224402MRA | C | 09/06/1996 | | (NONE) | 04/27/1998 | | 54FCT645AT (GEN) | 590 |
| 5962-9224402MSA | C | 09/06/1996 | | (NONE) | 04/27/1998 | | 54FCT645AT (GEN) | 590 |
| 5962-9224403M2A | C | 09/06/1996 | | (NONE) | 04/27/1998 | | 54FCT645CT (GEN) | 590 |
| 5962-9224403MRA | C | 09/06/1996 | | (NONE) | 04/27/1998 | | 54FCT645CT (GEN) | 590 |
| 5962-9224403MSA | C | 09/06/1996 | | (NONE) | 04/27/1998 | | 54FCT645CT (GEN) | 590 |
| 5962-9224404M2A | C | 09/06/1996 | | (NONE) | | | 54FCT645T (GEN) | 590 |
| 5962-9224404MRA | C | 09/06/1996 | | (NONE) | | | 54FCT645T (GEN) | 590 |
| 5962-9224405M2A | C | 09/06/1996 | | (NONE) | | | 54FCT645AT (GEN) | 590 |
| 5962-9224405MRA | C | 09/06/1996 | | (NONE) | | | 54FCT645AT (GEN) | 590 |
| 5962-9224406M2A | C | 09/06/1996 | | (NONE) | | | 54FCT645CT (GEN) | 590 |
| 5962-9224406MRA | C | 09/06/1996 | | (NONE) | | | 54FCT645CT (GEN) | 590 |
| 5962-9224601M3A | B | 09/06/1996 | | (NONE) | 04/29/2002 | | 54FCT652T (GEN) | 590 |
| 5962-9224601MKA | B | 09/06/1996 | | (NONE) | 04/29/2002 | | 54FCT652T (GEN) | 590 |
| 5962-9224601MLA | B | 09/06/1996 | | (NONE) | 04/29/2002 | | 54FCT652T (GEN) | 590 |
| 5962-9224602M3A | B | 09/06/1996 | | (NONE) | 04/29/2002 | | 54FCT652AT (GEN) | 590 |
| 5962-9224602MKA | B | 09/06/1996 | | (NONE) | 04/29/2002 | | 54FCT652AT (GEN) | 590 |
| 5962-9224602MLA | B | 09/06/1996 | | (NONE) | 04/29/2002 | | 54FCT652AT (GEN) | 590 |
| 5962-9224603M3A | B | 09/06/1996 | | (NONE) | 04/29/2002 | | 54FCT652CT (GEN) | 590 |
| 5962-9224603MKA | B | 09/06/1996 | | (NONE) | 04/29/2002 | | 54FCT652CT (GEN) | 590 |
| 5962-9224603MLA | B | 09/06/1996 | | (NONE) | 04/29/2002 | | 54FCT652CT (GEN) | 590 |
| 5962-9224604M3A | B | 09/06/1996 | | (NONE) | | | 54FCT652T (GEN) | 590 |
| 5962-9224604MLA | B | 09/06/1996 | | (NONE) | | | 54FCT652T (GEN) | 590 |
| 5962-9224605M3A | B | 09/06/1996 | | (NONE) | | | 54FCT652AT (GEN) | 590 |
| 5962-9224605MLA | B | 09/06/1996 | | (NONE) | | | 54FCT652AT (GEN) | 590 |
| 5962-9224606M3A | B | 09/06/1996 | | (NONE) | | | 54FCT652CT (GEN) | 590 |
| 5962-9224606MLA | B | 09/06/1996 | | (NONE) | | | 54FCT652CT (GEN) | 590 |
| 5962-9224701M3A | C | 09/06/1996 | 2 | IDT | | Y | IDT54FCT827ATLB | 569 |
| 5962-9224701M3A | C | 09/06/1996 | 2 | TI | | Y | CY54FCT827ATLMB | 569 |
| 5962-9224701MKA | C | 09/06/1996 | | (NONE) | 04/29/2002 | | 54FCT827AT (GEN) | 569 |
| 5962-9224701MLA | C | 09/06/1996 | 2 | IDT | | Y | IDT54FCT827ATDB | 569 |
| 5962-9224702M3A | C | 09/06/1996 | | (NONE) | | | 54FCT827AT (GEN) | 569 |
| 5962-9224702MLA | C | 09/06/1996 | | (NONE) | | | 54FCT827AT (GEN) | 569 |
| 5962-9224703M3A | C | 09/06/1996 | 2 | IDT | | Y | IDT54FCT827BTLB | 569 |
| 5962-9224703MKA | C | 09/06/1996 | | (NONE) | 04/29/2002 | | 54FCT827BT (GEN) | 569 |
| 5962-9224703MLA | C | 09/06/1996 | 2 | IDT | | Y | IDT54FCT827BTDB | 569 |
| 5962-9224704M3A | C | 09/06/1996 | | (NONE) | | | 54FCT827BT (GEN) | 569 |
| 5962-9224704MLA | C | 09/06/1996 | | (NONE) | | | 54FCT827BT (GEN) | 569 |
| 5962-9224705M3A | C | 09/06/1996 | 2 | IDT | | Y | IDT54FCT827CTLB | 569 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9224705MKA | C | 09/06/1996 | | (NONE) | 04/29/2002 | | 54FCT827CT (GEN) | 569 |
| 5962-9224705MLA | C | 09/06/1996 | 2 | IDT | | Y | IDT54FCT827CTDB | 569 |
| 5962-9224706M3A | C | 09/06/1996 | | (NONE) | | | 54FCT827CT (GEN) | 569 |
| 5962-9224706MLA | C | 09/06/1996 | | (NONE) | | | 54FCT827CT (GEN) | 569 |
| 5962-9225201MXC | D | 03/13/2002 | | (NONE) | 01/15/2000 | | 4005-10 (GEN) | 431 |
| 5962-9225201MYC | D | 03/13/2002 | | (NONE) | 01/15/2000 | | 4005-10 (GEN) | 431 |
| 5962-9225201MZC | D | 03/13/2002 | | (NONE) | 01/15/2000 | | 4005-10 (GEN) | 431 |
| 5962-9225202MXC | D | 03/13/2002 | | (NONE) | 01/15/2000 | | 4005-6 (GEN) | 431 |
| 5962-9225202MYC | D | 03/13/2002 | | (NONE) | 01/15/2000 | | 4005-6 (GEN) | 431 |
| 5962-9225202MZC | D | 03/13/2002 | | (NONE) | 01/15/2000 | | 4005-6 (GEN) | 431 |
| 5962-9225203MXC | D | 03/13/2002 | 3 | XILINX | | Y | XC4005-5PG156B | 431 |
| 5962-9225203MYC | D | 03/13/2002 | 3 | XILINX | | Y | XC4005-5CB164B | 431 |
| 5962-9225203MZC | D | 03/13/2002 | 3 | XILINX | | Y | XC4005-5CB164B | 431 |
| 5962-9225301HXA | B | 07/22/1999 | | (NONE) | | | MN6450T (GEN) | 592 |
| 5962-9225301HXC | B | 07/22/1999 | | (NONE) | | | MN6450T (GEN) | 592 |
| 5962-9225302HXA | B | 07/22/1999 | 1 | MICRO NETWKS | | Y | MN6450S/B CH | 592 |
| 5962-9225302HXC | B | 07/22/1999 | 1 | MICRO NETWKS | | Y | MN6450S/B CH | 592 |
| 5962-9225701MXA | A | 10/17/1996 | 2 | IDT | | Y | IDT54FCT16244TEB | 529 |
| 5962-9225702MXA | A | 10/17/1996 | 2 | IDT | | Y | IDT54FCT16244ATEB | 529 |
| 5962-9225703MXA | A | 10/17/1996 | 2 | IDT | | Y | IDT54FCT16244CTEB | 529 |
| 5962-9225801MXA | A | 10/17/1996 | 2 | IDT | | Y | IDT54FCT16245TEB | 590 |
| 5962-9225802MXA | A | 10/17/1996 | 2 | IDT | | Y | IDT54FCT16245ATEB | 590 |
| 5962-9225803MXA | A | 10/17/1996 | 2 | IDT | | Y | IDT54FCT16245CTEB | 590 |
| 5962-9225901MXA | A | 10/17/1996 | | (NONE) | 01/28/2002 | | 54FCT16373 (GEN) | 342 |
| 5962-9225902MXA | A | 10/17/1996 | | (NONE) | 01/28/2002 | | 54FCT16373A (GEN) | 342 |
| 5962-9225903MXA | A | 10/17/1996 | | (NONE) | 01/28/2002 | | 54FCT16373C (GEN) | 342 |
| 5962-9226001MXA | A | 10/17/1996 | | (NONE) | 01/28/2002 | | 54FCT16374 (GEN) | 159 |
| 5962-9226002MXA | A | 10/17/1996 | | (NONE) | 01/28/2002 | | 54FCT16374A (GEN) | 159 |
| 5962-9226003MXA | A | 10/17/1996 | | (NONE) | 01/28/2002 | | 54FCT16374C (GEN) | 159 |
| 5962-9226301MXA | A | 10/17/1996 | | (NONE) | 04/29/2002 | | 54FCT16543T (GEN) | 590 |
| 5962-9226302MXA | A | 10/17/1996 | | (NONE) | 04/29/2002 | | 54FCT16543AT (GEN) | 590 |
| 5962-9226303MXA | A | 10/17/1996 | | (NONE) | 04/29/2002 | | 54FCT16543CT (GEN) | 590 |
| 5962-9226401MXA | A | 10/17/1996 | | (NONE) | 04/29/2002 | | 54FCT16646T (GEN) | 590 |
| 5962-9226402MXA | A | 10/17/1996 | | (NONE) | 04/29/2002 | | 54FCT16646AT (GEN) | 590 |
| 5962-9226403MXA | A | 10/17/1996 | | (NONE) | 04/29/2002 | | 54FCT16646CT (GEN) | 590 |
| 5962-9226701MXA | B | 10/17/1996 | | (NONE) | 01/28/2002 | | 54FCT16827A (GEN) | 529 |
| 5962-9226702MXA | B | 10/17/1996 | | (NONE) | 01/28/2002 | | 54FCT16827B (GEN) | 529 |
| 5962-9226703MXA | B | 10/17/1996 | | (NONE) | 01/28/2002 | | 54FCT16827C (GEN) | 529 |
| 5962-9226801MXA | A | 10/17/1996 | | (NONE) | 01/28/2002 | | 54FCT16841A (GEN) | 341 |
| 5962-9226802MXA | A | 10/17/1996 | | (NONE) | 01/28/2002 | | 54FCT16841B (GEN) | 341 |
| 5962-9226803MXA | A | 10/17/1996 | | (NONE) | 01/28/2002 | | 54FCT16841C (GEN) | 341 |
| 5962-9227001MXA | D | 11/08/1996 | | (NONE) | 10/20/2001 | | 54FCT162240 (GEN) | 509 |
| 5962-9227002MXA | D | 11/08/1996 | | (NONE) | 10/20/2001 | | 54FCT162240A (GEN) | 509 |
| 5962-9227003MXA | D | 11/08/1996 | | (NONE) | 10/20/2001 | | 54FCT162240C (GEN) | 509 |
| 5962-9227101MXA | B | 11/08/1996 | 2 | IDT | | Y | IDT54FCT162244TEB | 529 |
| 5962-9227102MXA | B | 11/08/1996 | 2 | IDT | | Y | IDT54FCT162244ATEB | 529 |
| 5962-9227103MXA | B | 11/08/1996 | 2 | IDT | | Y | IDT54FCT162244CTEB | 529 |
| 5962-9227201MXA | C | 11/08/1996 | 2 | IDT | | Y | IDT54FCT162245TEB | 590 |
| 5962-9227202MXA | C | 11/08/1996 | 2 | IDT | | Y | IDT54FCT162245ATEB | 590 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9227203MXA | C | 11/08/1996 | 2 | IDT | | Y | IDT54FCT162245CTEB | 590 |
| 5962-9227301MXA | B | 11/08/1996 | | (NONE) | 04/29/2002 | | 54FCT162373T (GEN) | 342 |
| 5962-9227302MXA | B | 11/08/1996 | | (NONE) | 04/29/2002 | | 54FCT162373AT (GEN) | 342 |
| 5962-9227303MXA | B | 11/08/1996 | | (NONE) | 04/29/2002 | | 54FCT162373CT (GEN) | 342 |
| 5962-9227401MXA | B | 11/08/1996 | | (NONE) | 04/29/2002 | | 54FCT162374T (GEN) | 159 |
| 5962-9227402MXA | B | 11/08/1996 | | (NONE) | 04/29/2002 | | 54FCT162374AT (GEN) | 159 |
| 5962-9227403MXA | B | 11/08/1996 | | (NONE) | 04/29/2002 | | 54FCT162374CT (GEN) | 159 |
| 5962-9227601MXA | C | 11/08/1996 | | (NONE) | 10/20/2001 | | 54FCT162501A (GEN) | 421 |
| 5962-9227602MXA | C | 11/08/1996 | | (NONE) | 10/20/2001 | | 54FCT162501C (GEN) | 421 |
| 5962-9227801MXA | C | 11/08/1996 | | (NONE) | 10/20/2001 | | 54FCT162646 (GEN) | 590 |
| 5962-9227802MXA | C | 11/08/1996 | | (NONE) | 10/20/2001 | | 54FCT162646A (GEN) | 590 |
| 5962-9227803MXA | C | 11/08/1996 | | (NONE) | 10/20/2001 | | 54FCT162646C (GEN) | 590 |
| 5962-9228001MXA | C | 11/08/1996 | | (NONE) | 01/28/2002 | | 54FCT162823A (GEN) | 421 |
| 5962-9228002MXA | C | 11/08/1996 | | (NONE) | 01/28/2002 | | 54FCT162823B (GEN) | 421 |
| 5962-9228003MXA | C | 11/08/1996 | | (NONE) | 01/28/2002 | | 54FCT162823C (GEN) | 421 |
| 5962-9228101MXA | | 06/12/1996 | | (NONE) | 10/20/2001 | | 54FCT162827A (GEN) | 569 |
| 5962-9228102MXA | | 06/12/1996 | | (NONE) | 10/20/2001 | | 54FCT162827B (GEN) | 569 |
| 5962-9228103MXA | | 06/12/1996 | | (NONE) | 10/20/2001 | | 54FCT162827C (GEN) | 569 |
| 5962-9228201MXA | | 06/12/1996 | | (NONE) | 01/28/2002 | | 54FCT162841A (GEN) | 342 |
| 5962-9228202MXA | | 06/12/1996 | | (NONE) | 01/28/2002 | | 54FCT162841B (GEN) | 342 |
| 5962-9228203MXA | | 06/12/1996 | | (NONE) | 01/28/2002 | | 54FCT162841C (GEN) | 342 |
| 5962-9228301MXA | B | 11/08/1996 | | (NONE) | 10/20/2001 | | 54FCT162952A (GEN) | 590 |
| 5962-9228302MXA | B | 11/08/1996 | | (NONE) | 10/20/2001 | | 54FCT162952B (GEN) | 590 |
| 5962-9228303MXA | B | 11/08/1996 | | (NONE) | 10/20/2001 | | 54FCT162952C (GEN) | 590 |
| 5962-9228401MZC | | 03/18/1993 | | (NONE) | 08/02/1996 | | 29000-20 (GEN) | 404 |
| 5962-9228402MZC | | 03/18/1993 | | (NONE) | 08/02/1996 | | 29000-16 (GEN) | 404 |
| 5962-9230401HXA | | 11/10/1992 | | (NONE) | | | | 590 |
| 5962-9230401HYA | | 11/10/1992 | | (NONE) | | | | 590 |
| 5962-9230501MXC | E | 03/15/2002 | | (NONE) | 01/15/2000 | | 4010-10 (GEN) | 431 |
| 5962-9230501MYC | E | 03/15/2002 | | (NONE) | 01/15/2000 | | 4010-10 (GEN) | 431 |
| 5962-9230501MZC | E | 03/15/2002 | | (NONE) | 01/15/2000 | | 4010-10 (GEN) | 431 |
| 5962-9230502MXC | E | 03/15/2002 | | (NONE) | 01/15/2000 | | 4010-6 (GEN) | 431 |
| 5962-9230502MYC | E | 03/15/2002 | | (NONE) | 01/15/2000 | | 4010-6 (GEN) | 431 |
| 5962-9230502MZC | E | 03/15/2002 | | (NONE) | 01/15/2000 | | 4010-6 (GEN) | 431 |
| 5962-9230503MXC | E | 03/15/2002 | 3 | XILINX | | Y | XC4010-5PG191B | 431 |
| 5962-9230503MYC | E | 03/15/2002 | 3 | XILINX | | Y | XC4010-5CB196B | 431 |
| 5962-9230503MZC | E | 03/15/2002 | 3 | XILINX | | Y | XC4010-5CB196B | 431 |
| 5962-9230601MXA | | 01/26/1993 | 2 | NATIONAL | | Y | 100336DMQB | 149 |
| 5962-9230601VXA | | 01/26/1993 | 2 | NATIONAL | | Y | 100336J-QMLV | 149 |
| 5962-9230601MYA | | 01/26/1993 | 2 | NATIONAL | | Y | 100336FMQB | 149 |
| 5962-9230601VYA | | 01/26/1993 | 2 | NATIONAL | | Y | 100336W-QMLV | 149 |
| 5962-9231201MXA | | 10/18/1994 | 1 | AUSTIN SEMI. | | Y | SMJ416400-10HKB | 629 |
| 5962-9231201MYA | | 10/18/1994 | 1 | AUSTIN SEMI. | | Y | SMJ416400-10FNC | 629 |
| 5962-9231201MZA | | 10/18/1994 | 1 | AUSTIN SEMI. | | Y | SMJ416400-10SVM | 629 |
| 5962-9231202MXA | | 10/18/1994 | 1 | AUSTIN SEMI. | | Y | SMJ416400-80HKB | 629 |
| 5962-9231202MYA | | 10/18/1994 | 1 | AUSTIN SEMI. | | Y | SMJ416400-80FNC | 629 |
| 5962-9231202MZA | | 10/18/1994 | 1 | AUSTIN SEMI. | | Y | SMJ416400-80SVM | 629 |
| 5962-9231203MXA | | 10/18/1994 | 1 | AUSTIN SEMI. | | Y | SMJ416400-70HKB | 629 |
| 5962-9231203MYA | | 10/18/1994 | 1 | AUSTIN SEMI. | | Y | SMJ416400-70FNC | 629 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9231203MZA | | 10/18/1994 | 1 | AUSTIN SEMI. | | Y | SMJ416400-70SVM | 629 |
| 5962-9231301MXA | A | 12/06/1993 | | (NONE) | | | 145152-2 (GEN) | 809 |
| 5962-9231401M3A | C | 03/31/1997 | | (NONE) | | | 54ABT543 (GEN) | 590 |
| 5962-9231401Q3A | C | 03/31/1997 | 3 | NATIONAL | | Y | 54ABT543E-QML | 590 |
| 5962-9231401MKA | C | 03/31/1997 | | (NONE) | | | 54ABT543 (GEN) | 590 |
| 5962-9231401QKA | C | 03/31/1997 | 3 | NATIONAL | | Y | 54ABT543W-QML | 590 |
| 5962-9231401MLA | C | 03/31/1997 | | (NONE) | | | 54ABT543 (GEN) | 590 |
| 5962-9231401QLA | C | 03/31/1997 | 3 | NATIONAL | | Y | 54ABT543J-QML | 590 |
| 5962-9231402Q3A | C | 03/31/1997 | 2 | TI | | Y | SNJ54ABT543AFK | 590 |
| 5962-9231402QKA | C | 03/31/1997 | 2 | TI | | Y | SNJ54ABT543AW | 590 |
| 5962-9231402QLA | C | 03/31/1997 | 2 | TI | | Y | SNJ54ABT543AJT | 590 |
| 5962-9231501M2C | A | 10/15/1998 | | (NONE) | 09/30/2000 | | SL2524 (GEN) | 800 |
| 5962-9231601MTA | C | 10/25/1999 | 1 | AUSTIN SEMI. | | Y | MT5C1001C-45/883C | 625 |
| 5962-9231601MUA | C | 10/25/1999 | 1 | AUSTIN SEMI. | | Y | MT5C1001DCJ-45/883C | 625 |
| 5962-9231601MXA | C | 10/25/1999 | | (NONE) | | | 5C1001-45 (GEN) | 625 |
| 5962-9231601MYA | C | 10/25/1999 | 1 | AUSTIN SEMI. | | Y | MT5C1001EC-45/883C | 625 |
| 5962-9231601MZA | C | 10/25/1999 | 1 | AUSTIN SEMI. | | Y | MT5C1001F-45/883C | 625 |
| 5962-9231602MTA | C | 10/25/1999 | 1 | AUSTIN SEMI. | | Y | MT5C1001C-35/883C | 625 |
| 5962-9231602MUA | C | 10/25/1999 | 1 | AUSTIN SEMI. | | Y | MT5C1001DCJ-35/883C | 625 |
| 5962-9231602MXA | C | 10/25/1999 | | (NONE) | | | 5C1001-35 (GEN) | 625 |
| 5962-9231602MYA | C | 10/25/1999 | 1 | AUSTIN SEMI. | | Y | MT5C1001EC-35/883C | 625 |
| 5962-9231602MZA | C | 10/25/1999 | 1 | AUSTIN SEMI. | | Y | MT5C1001F-35/883C | 625 |
| 5962-9231603MTA | C | 10/25/1999 | 1 | AUSTIN SEMI. | | Y | MT5C1001C-25/883C | 625 |
| 5962-9231603MUA | C | 10/25/1999 | 1 | AUSTIN SEMI. | | Y | MT5C1001DCJ-25/883C | 625 |
| 5962-9231603MXA | C | 10/25/1999 | | (NONE) | | | 5C1001-25 (GEN) | 625 |
| 5962-9231603MYA | C | 10/25/1999 | 1 | AUSTIN SEMI. | | Y | MT5C1001EC-25/883C | 625 |
| 5962-9231603MZA | C | 10/25/1999 | 1 | AUSTIN SEMI. | | Y | MT5C1001F-25/883C | 625 |
| 5962-9231604MTA | C | 10/25/1999 | 1 | AUSTIN SEMI. | | Y | MT5C1001C-20/883C | 625 |
| 5962-9231604MUA | C | 10/25/1999 | 1 | AUSTIN SEMI. | | Y | MT5C1001DCJ-20/883C | 625 |
| 5962-9231604MXA | C | 10/25/1999 | | (NONE) | | | 5C1001-20 (GEN) | 625 |
| 5962-9231604MYA | C | 10/25/1999 | 1 | AUSTIN SEMI. | | Y | MT5C1001EC-20/883C | 625 |
| 5962-9231604MZA | C | 10/25/1999 | 1 | AUSTIN SEMI. | | Y | MT5C1001F-20/883C | 625 |
| 5962-9231605MTA | C | 10/25/1999 | 1 | AUSTIN SEMI. | | Y | MT5C1001C-45L/883C | 625 |
| 5962-9231605MUA | C | 10/25/1999 | 1 | AUSTIN SEMI. | | Y | MT5C1001DCJ-45L/883 | 625 |
| 5962-9231605MXA | C | 10/25/1999 | | (NONE) | | | 5C1001-45L (GEN) | 625 |
| 5962-9231605MYA | C | 10/25/1999 | 1 | AUSTIN SEMI. | | Y | MT5C1001EC-45L/883C | 625 |
| 5962-9231605MZA | C | 10/25/1999 | 1 | AUSTIN SEMI. | | Y | MT5C1001F-45L/883C | 625 |
| 5962-9231606MTA | C | 10/25/1999 | 1 | AUSTIN SEMI. | | Y | MT5C1001C-35L/883C | 625 |
| 5962-9231606MUA | C | 10/25/1999 | 1 | AUSTIN SEMI. | | Y | MT5C1001DCJ-35L/883 | 625 |
| 5962-9231606MXA | C | 10/25/1999 | | (NONE) | | | 5C1001-35L (GEN) | 625 |
| 5962-9231606MYA | C | 10/25/1999 | 1 | AUSTIN SEMI. | | Y | MT5C1001EC-35L/883C | 625 |
| 5962-9231606MZA | C | 10/25/1999 | 1 | AUSTIN SEMI. | | Y | MT5C1001F-35L/883C | 625 |
| 5962-9231607MTA | C | 10/25/1999 | 1 | AUSTIN SEMI. | | Y | MT5C1001C-25L/883C | 625 |
| 5962-9231607MUA | C | 10/25/1999 | 1 | AUSTIN SEMI. | | Y | MT5C1001DCJ-25L/883 | 625 |
| 5962-9231607MXA | C | 10/25/1999 | | (NONE) | | | 5C1001-25L (GEN) | 625 |
| 5962-9231607MYA | C | 10/25/1999 | 1 | AUSTIN SEMI. | | Y | MT5C1001EC-25L/883C | 625 |
| 5962-9231607MZA | C | 10/25/1999 | 1 | AUSTIN SEMI. | | Y | MT5C1001F-25L/883C | 625 |
| 5962-9231608MTA | C | 10/25/1999 | 1 | AUSTIN SEMI. | | Y | MT5C1001C-20L/883C | 625 |
| 5962-9231608MUA | C | 10/25/1999 | 1 | AUSTIN SEMI. | | Y | MT5C1001DCJ-20L/883 | 625 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9231608MXA | C | 10/25/1999 | | (NONE) | | | 5C1001-20L (GEN) | 625 |
| 5962-9231608MYA | C | 10/25/1999 | 1 | AUSTIN SEMI. | | Y | MT5C1001EC-20L/883C | 625 |
| 5962-9231608MZA | C | 10/25/1999 | 1 | AUSTIN SEMI. | | Y | MT5C1001F-20L/883C | 625 |
| 5962-9231701M3A | E | 12/21/2000 | 1 | NATIONAL | | Y | DS1776E/883 | 590 |
| 5962-9231701MXA | E | 12/21/2000 | | (NONE) | | | DS1776 (GEN) | 590 |
| 5962-9231801MPA | | 11/30/1992 | | (NONE) | 09/30/1995 | | 35164 (GEN) | 899 |
| 5962-9231901M2A | | 03/01/1993 | 0 | TI | | Y | SNJ54LS136FK | 140 |
| 5962-9231901MCA | | 03/01/1993 | 0 | TI | | Y | SNJ54LS136J | 140 |
| 5962-9231901MDA | | 03/01/1993 | 0 | TI | | Y | SNJ54LS136W | 140 |
| 5962-9232101MXA | B | 05/15/2002 | | (NONE) | 05/31/1998 | | 7C439-65 (GEN) | 670 |
| 5962-9232101MYA | B | 05/15/2002 | | (NONE) | | | 7C439-65 (GEN) | 670 |
| 5962-9232101MZA | B | 05/15/2002 | | (NONE) | | | 7C439-65 (GEN) | 670 |
| 5962-9232102MXA | B | 05/15/2002 | 1 | QP SEMI | | Y | 7C439/MXA | 670 |
| 5962-9232102MYA | B | 05/15/2002 | 1 | QP SEMI | | Y | 7C439/MYA | 670 |
| 5962-9232102MZA | B | 05/15/2002 | 1 | QP SEMI | | Y | 7C439/MZA | 670 |
| 5962-9232103MXA | B | 05/15/2002 | | (NONE) | 05/31/1998 | | 7C439-30 (GEN) | 670 |
| 5962-9232103MYA | B | 05/15/2002 | | (NONE) | | | 7C439-30 (GEN) | 670 |
| 5962-9232103MZA | B | 05/15/2002 | | (NONE) | | | 7C439-30 (GEN) | 670 |
| 5962-9232201MXA | | 06/17/1993 | | (NONE) | 05/10/1995 | | 7C285 (GEN) | 663 |
| 5962-9232201MYA | | 06/17/1993 | | (NONE) | | | 7C285 (GEN) | 663 |
| 5962-9232201MZA | | 06/17/1993 | | (NONE) | 05/10/1995 | | 7C285 (GEN) | 663 |
| 5962-9232202MXA | | 06/17/1993 | | (NONE) | 05/10/1995 | | 7C285 (GEN) | 663 |
| 5962-9232202MYA | | 06/17/1993 | | (NONE) | | | 7C285 (GEN) | 663 |
| 5962-9232202MZA | | 06/17/1993 | | (NONE) | 05/10/1995 | | 7C285 (GEN) | 663 |
| 5962-9232401MXA | A | 05/01/2001 | | (NONE) | | | 11C68 (GEN) | 620 |
| 5962-9232401MYA | A | 05/01/2001 | | (NONE) | | | 11C68 (GEN) | 620 |
| 5962-9232402MXA | A | 05/01/2001 | | (NONE) | | | 11C68 (GEN) | 620 |
| 5962-9232402MYA | A | 05/01/2001 | | (NONE) | | | 11C68 (GEN) | 620 |
| 5962-9232403MXA | A | 05/01/2001 | | (NONE) | | | 11C68 (GEN) | 620 |
| 5962-9232403MYA | A | 05/01/2001 | | (NONE) | | | 11C68 (GEN) | 620 |
| 5962-9232404MXA | A | 05/01/2001 | 1 | SIMTEK | | | STK11C68-5C55M | 620 |
| 5962-9232404MXC | A | 05/01/2001 | 1 | SIMTEK | | | STK11C68-5C55M | 620 |
| 5962-9232404MYA | A | 05/01/2001 | 1 | SIMTEK | | | STK11C68-5L55M | 620 |
| 5962-9232405MXA | A | 05/01/2001 | 1 | SIMTEK | | | STK11C68-5C45M | 620 |
| 5962-9232405MXC | A | 05/01/2001 | 1 | SIMTEK | | | STK11C68-5C45M | 620 |
| 5962-9232405MYA | A | 05/01/2001 | 1 | SIMTEK | | | STK11C68-5L45M | 620 |
| 5962-9232406MXA | A | 05/01/2001 | 1 | SIMTEK | | | STK11C68-5C35M | 620 |
| 5962-9232406MXC | A | 05/01/2001 | 1 | SIMTEK | | | STK11C68-5C35M | 620 |
| 5962-9232406MYA | A | 05/01/2001 | 1 | SIMTEK | | | STK11C68-5C35M | 620 |
| 5962-9232501MXA | B | 05/06/2004 | 1 | NATIONAL | | Y | LMD18200-2D/883 | 899 |
| 5962-9232501VXA | B | 05/06/2004 | 1 | NATIONAL | | Y | LMD18200-2D-QV | 899 |
| 5962-9232701MYA | A | 08/30/1994 | | (NONE) | 09/30/1995 | | 10E511 (GEN) | 599 |
| 5962-9232702MYA | A | 08/30/1994 | | (NONE) | 09/30/1995 | | 100E511 (GEN) | 599 |
| 5962-9232901QRA | | 04/21/1995 | | (NONE) | | | ADC10061 (GEN) | 592 |
| 5962-9232902QJA | | 04/21/1995 | | (NONE) | | | ADC10062 (GEN) | 592 |
| 5962-9232903QXA | | 04/21/1995 | | (NONE) | | | ADC10064 (GEN) | 592 |
| 5962-9233101MXA | | 10/18/1993 | | (NONE) | | | TMC2330 (GEN) | 399 |
| 5962-9233101MYA | | 10/18/1993 | | (NONE) | | | TMC2330 (GEN) | 399 |
| 5962-9233102MXA | | 10/18/1993 | | (NONE) | | | TMC2330 (GEN) | 339 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9233102MYA | | 10/18/1993 | | (NONE) | | | TMC2330 (GEN) | 339 |
| 5962-9233301MMA | B | 09/05/1996 | 3 | QP SEMI | | Y | 87C552/BMA | 420 |
| 5962-9233302MMA | B | 09/05/1996 | | (NONE) | | | 87C552 (GEN) | 420 |
| 5962-9233303NYA | B | 09/05/1996 | | (NONE) | | | 87C552 (GEN) | 420 |
| 5962-9233304NYA | B | 09/05/1996 | | (NONE) | | | 87C552 (GEN) | 420 |
| 5962-9233501MXA | | 04/16/1993 | | (NONE) | | | 2936 (GEN) | 899 |
| 5962-9233601MEA | D | 05/08/2003 | 2 | NATIONAL | | Y | LP2953AMJ/883 | 789 |
| 5962-9233601VEA | D | 05/08/2003 | 2 | NATIONAL | | Y | LP2953AMJ-QMLV | 789 |
| 5962-9233601QXA | D | 05/08/2003 | 2 | NATIONAL | | Y | LP2953AMWG/883 | 789 |
| 5962-9233601VXA | D | 05/08/2003 | 2 | NATIONAL | | Y | LP2953AMWG-QMLV | 789 |
| 5962-9233801MRA | | 02/12/1993 | | (NONE) | 03/05/1996 | | 16L8-10 (GEN) | 431 |
| 5962-9233801MSA | | 02/12/1993 | | (NONE) | | | 16L8-10 (GEN) | 431 |
| 5962-9233801MXA | | 02/12/1993 | | (NONE) | 03/05/1996 | | 16L8-10 (GEN) | 431 |
| 5962-9233802MRA | | 02/12/1993 | | (NONE) | 03/05/1996 | | 16R8-10 (GEN) | 431 |
| 5962-9233802MSA | | 02/12/1993 | | (NONE) | | | 16R8-10 (GEN) | 431 |
| 5962-9233802MXA | | 02/12/1993 | | (NONE) | 03/05/1996 | | 16R8-10 (GEN) | 431 |
| 5962-9233803MRA | | 02/12/1993 | | (NONE) | 03/05/1996 | | 16R6-10 (GEN) | 431 |
| 5962-9233803MSA | | 02/12/1993 | | (NONE) | | | 16R6-10 (GEN) | 431 |
| 5962-9233803MXA | | 02/12/1993 | | (NONE) | 03/05/1996 | | 16R6-10 (GEN) | 431 |
| 5962-9233804MRA | | 02/12/1993 | | (NONE) | 03/05/1996 | | 16R4-10 (GEN) | 431 |
| 5962-9233804MSA | | 02/12/1993 | | (NONE) | | | 16R4-10 (GEN) | 431 |
| 5962-9233804MXA | | 02/12/1993 | | (NONE) | 03/05/1996 | | 16R4-10 (GEN) | 431 |
| 5962-9233805MRA | | 02/12/1993 | | (NONE) | 03/05/1996 | | 16L8-7 (GEN) | 431 |
| 5962-9233805MSA | | 02/12/1993 | | (NONE) | | | 16L8-7 (GEN) | 431 |
| 5962-9233805MXA | | 02/12/1993 | | (NONE) | 03/05/1996 | | 16L8-7 (GEN) | 431 |
| 5962-9233806MRA | | 02/12/1993 | | (NONE) | 03/05/1996 | | 16R8-7 (GEN) | 431 |
| 5962-9233806MSA | | 02/12/1993 | | (NONE) | | | 16R8-7 (GEN) | 431 |
| 5962-9233806MXA | | 02/12/1993 | | (NONE) | | | 16R8-7 (GEN) | 431 |
| 5962-9233807MRA | | 02/12/1993 | | (NONE) | 03/05/1996 | | 16R6-7 (GEN) | 431 |
| 5962-9233807MSA | | 02/12/1993 | | (NONE) | | | 16R6-7 (GEN) | 431 |
| 5962-9233807MXA | | 02/12/1993 | | (NONE) | 03/05/1996 | | 16R6-7 (GEN) | 431 |
| 5962-9233808MRA | | 02/12/1993 | | (NONE) | 03/05/1996 | | 16R4-7 (GEN) | 431 |
| 5962-9233808MSA | | 02/12/1993 | | (NONE) | | | 16R4-7 (GEN) | 431 |
| 5962-9233808MXA | | 02/12/1993 | | (NONE) | 03/05/1996 | | 16R4-7 (GEN) | 431 |
| 5962-9233901M2A | E | 10/07/2003 | 1 | NATIONAL | | Y | CLC114AE-QML | 760 |
| 5962-9233901MCA | E | 10/07/2003 | 1 | NATIONAL | | Y | CLC114AJ-QML | 760 |
| 5962-9234301MYA | B | 07/14/1994 | | (NONE) | 09/30/1995 | | 10E516 (GEN) | 579 |
| 5962-9234301MZA | B | 07/14/1994 | | (NONE) | 09/30/1995 | | 10E516 (GEN) | 579 |
| 5962-9234302MYA | B | 07/14/1994 | | (NONE) | 09/30/1995 | | 100E516 (GEN) | 579 |
| 5962-9234302MZA | B | 07/14/1994 | | (NONE) | 09/30/1995 | | 100E516 (GEN) | 579 |
| 5962-9234401MXA | | 12/16/1993 | | (NONE) | 05/06/1997 | | 71B74S20 (GEN) | 621 |
| 5962-9234501M2C | B | 07/25/2001 | 1 | MAXIM INTEG. | | | MAX543AMLP/883B | 591 |
| 5962-9234501MPA | B | 07/25/2001 | 1 | MAXIM INTEG. | | | MAX543AMJA/883B | 591 |
| 5962-9234502M2C | B | 07/25/2001 | 1 | MAXIM INTEG. | | | MAX543BMLP/883B | 591 |
| 5962-9234502MPA | B | 07/25/2001 | 1 | MAXIM INTEG. | | | MAX543BMJA/883B | 591 |
| 5962-9234701MIA | C | 06/27/1997 | | (NONE) | | | AD9696 (GEN) | 770 |
| 5962-9234701MPA | C | 06/27/1997 | | (NONE) | | | AD9696 (GEN) | 770 |
| 5962-9234701MXC | C | 06/27/1997 | | (NONE) | | | AD9696 (GEN) | 770 |
| 5962-9234702MEA | C | 06/27/1997 | | (NONE) | | | AD9698 (GEN) | 773 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9234702MYC | C | 06/27/1997 | | (NONE) | | | AD9698 (GEN) | 773 |
| 5962-9234703VHA | C | 06/27/1997 | | (NONE) | 09/05/2001 | | AD9696T (GEN) | 773 |
| 5962-9234703VPA | C | 06/27/1997 | | (NONE) | 09/05/2001 | | AD9696T (GEN) | 773 |
| 5962-9235001MXA | | 02/26/1993 | | (NONE) | | | L293D (GEN) | 899 |
| 5962-9235101HXA | B | 05/25/2000 | 1 | ADV. ANALOG | | Y | AHF2815D/CH | 594 |
| 5962-9235101HXC | B | 05/25/2000 | 1 | ADV. ANALOG | | Y | AHF2815D/CH | 594 |
| 5962-9235101HZA | B | 05/25/2000 | 1 | ADV. ANALOG | | Y | AHF2815DF/CH | 594 |
| 5962-9235101HZC | B | 05/25/2000 | 1 | ADV. ANALOG | | Y | AHF2815DF/CH | 594 |
| 5962H92A0101QYC | | 07/09/1992 | | (NONE) | | | 1HK84 (GEN) | 420 |
| 5962-92A0201QYC | B | 04/21/1994 | | (NONE) | | | 1056A2 (GEN) | 420 |
| 5962-92A0301QYC | B | 04/21/1994 | | (NONE) | | | 1056B2 (GEN) | 421 |
| 5962-92A0401QYC | B | 04/21/1994 | | (NONE) | | | 1056C (GEN) | 421 |
| 5962-92A0501QYC | B | 04/21/1994 | | (NONE) | | | 1056D2 (GEN) | 420 |
| 5962-92A0601QYC | B | 04/21/1994 | | (NONE) | | | 1056E (GEN) | 699 |
| 5962-92A0701QYC | B | 04/21/1994 | | (NONE) | | | 1056F (GEN) | 429 |
| 5962-92A0801QYC | B | 04/21/1994 | | (NONE) | | | 1056G (GEN) | 420 |
| 5962-92A0901QYC | B | 04/21/1994 | | (NONE) | | | 1056H2 (GEN) | 399 |
| 5962-92A1001QYC | B | 04/21/1994 | | (NONE) | | | 1056J (GEN) | 205 |
| 5962-92A1101QYC | B | 04/21/1994 | | (NONE) | | | 1056K2 (GEN) | 429 |
| 5962-92A1201QYC | B | 04/21/1994 | | (NONE) | | | 1056L (GEN) | 420 |
| 5962-92A1301QYC | B | 04/21/1994 | | (NONE) | | | 1056T (GEN) | 399 |
| 5962-92A1401QYC | B | 04/21/1994 | | (NONE) | | | 1056S (GEN) | 420 |
| 5962-92A1501QYC | B | 04/21/1994 | | (NONE) | | | 1056W (GEN) | 423 |
| 5962-92A1601QYC | A | 04/21/1994 | | (NONE) | | | 1056U (GEN) | 399 |
| 5962-92A1701QYC | B | 04/21/1994 | | (NONE) | | | 1057A3 (GEN) | 399 |
| 5962-92A1801QYC | B | 04/21/1994 | | (NONE) | | | 1057C (GEN) | 399 |
| 5962-92A1901QYC | B | 04/21/1994 | | (NONE) | | | 1057D (GEN) | 355 |
| 5962-92A2001QYC | B | 04/21/1994 | | (NONE) | | | 1057E (GEN) | 429 |
| 5962-92A2101QYC | B | 04/21/1994 | | (NONE) | | | 1057F2 (GEN) | 591 |
| 5962-92A2201QYC | B | 04/21/1994 | | (NONE) | | | 1057G (GEN) | 420 |
| 5962-9300201MPA | | 04/08/1993 | | (NONE) | 12/08/1998 | | LM612A (GEN) | 779 |
| 5962-9300301M2A | B | 11/13/2001 | 1 | QP SEMI | | Y | LM613/M2A | 710 |
| 5962-9300301MEA | B | 11/13/2001 | 1 | NATIONAL | | Y | LM613AMJ/883 | 710 |
| 5962-9300401MEA | | 06/22/1994 | | (NONE) | 03/09/1999 | | LM614A (GEN) | 713 |
| 5962-9300601MXA | B | 09/23/1999 | | (NONE) | 10/31/2002 | | 320E14 (GEN) | 432 |
| 5962-9300601MYA | B | 09/23/1999 | | (NONE) | 10/31/2002 | | 320E14 (GEN) | 432 |
| 5962-9300701MXC | D | 11/05/1996 | | (NONE) | | | 48908-20 (GEN) | 399 |
| 5962-9300701MYA | D | 11/05/1996 | | (NONE) | 04/01/2000 | | 48908-50 (GEN) | 399 |
| 5962-9300702MXA | D | 11/05/1996 | | (NONE) | 04/01/2000 | | 48908-37 (GEN) | 399 |
| 5962-9300702MYA | D | 11/05/1996 | | (NONE) | 04/01/2000 | | 48908-37 (GEN) | 399 |
| 5962-9300703MXA | D | 11/05/1996 | | (NONE) | 04/01/2000 | | 48908-25 (GEN) | 399 |
| 5962-9300703MYA | D | 11/05/1996 | | (NONE) | 04/01/2000 | | 48908-25 (GEN) | 399 |
| 5962-9300801MXA | | 10/25/1994 | | (NONE) | | | 7C462-40 (GEN) | 670 |
| 5962-9300801MYA | | 10/25/1994 | | (NONE) | | | 7C462-40 (GEN) | 670 |
| 5962-9300802MXA | | 10/25/1994 | | (NONE) | | | 7C462-25 (GEN) | 670 |
| 5962-9300802MYA | | 10/25/1994 | | (NONE) | | | 7C462-25 (GEN) | 670 |
| 5962-9300803MXA | | 10/25/1994 | | (NONE) | | | 7C462-20 (GEN) | 670 |
| 5962-9300803MYA | | 10/25/1994 | | (NONE) | | | 7C462-20 (GEN) | 670 |
| 5962-9301901M2A | | 01/05/1996 | | (NONE) | 10/20/2001 | | 54FCT2244 (GEN) | 529 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9301901MRA | | 01/05/1996 | | (NONE) | 10/20/2001 | | I54FCT2244 (GEN) | 529 |
| 5962-9301901MSA | | 01/05/1996 | | (NONE) | 10/20/2001 | | 54FCT2244 (GEN) | 529 |
| 5962-9301902M2A | | 01/05/1996 | | (NONE) | 10/20/2001 | | 54FCT2244A (GEN) | 529 |
| 5962-9301902MRA | | 01/05/1996 | | (NONE) | 10/20/2001 | | 54FCT2244A (GEN) | 529 |
| 5962-9301902MSA | | 01/05/1996 | | (NONE) | 10/20/2001 | | 54FCT2244A (GEN) | 529 |
| 5962-9301903M2A | | 01/05/1996 | | (NONE) | 10/20/2001 | | 54FCT2244C (GEN) | 529 |
| 5962-9301903MRA | | 01/05/1996 | | (NONE) | 10/20/2001 | | 54FCT2244C (GEN) | 529 |
| 5962-9301903MSA | | 01/05/1996 | | (NONE) | 10/20/2001 | | 54FCT2244C (GEN) | 529 |
| 5962-9302001M2A | | 11/28/1995 | | (NONE) | 10/20/2001 | | 54FCT2245 (GEN) | 590 |
| 5962-9302001MRA | | 11/28/1995 | | (NONE) | 10/20/2001 | | 54FCT2245 (GEN) | 590 |
| 5962-9302001MSA | | 11/28/1995 | | (NONE) | 10/20/2001 | | 54FCT2245 (GEN) | 590 |
| 5962-9302002M2A | | 11/28/1995 | | (NONE) | 10/20/2001 | | 54FCT2245A (GEN) | 590 |
| 5962-9302002MRA | | 11/28/1995 | | (NONE) | 10/20/2001 | | 54FCT2245A (GEN) | 590 |
| 5962-9302002MSA | | 11/28/1995 | | (NONE) | 10/20/2001 | | 54FCT2245A (GEN) | 590 |
| 5962-9302003M2A | | 11/28/1995 | | (NONE) | 10/20/2001 | | 54FCT2245C (GEN) | 590 |
| 5962-9302003MRA | | 11/28/1995 | | (NONE) | 10/20/2001 | | 54FCT2245C (GEN) | 590 |
| 5962-9302003MSA | | 11/28/1995 | | (NONE) | 10/20/2001 | | 54FCT2245C (GEN) | 590 |
| 5962-9302501M2A | | 01/05/1996 | | (NONE) | 10/20/2001 | | 54FCT2373 (GEN) | 341 |
| 5962-9302501MRA | | 01/05/1996 | | (NONE) | 10/20/2001 | | 54FCT2373 (GEN) | 341 |
| 5962-9302501MSA | | 01/05/1996 | | (NONE) | 10/20/2001 | | 54FCT2373 (GEN) | 341 |
| 5962-9302502M2A | | 01/05/1996 | | (NONE) | 10/20/2001 | | 54FCT2373A (GEN) | 341 |
| 5962-9302502MRA | | 01/05/1996 | | (NONE) | 10/20/2001 | | 54FCT2373A (GEN) | 341 |
| 5962-9302502MSA | | 01/05/1996 | | (NONE) | 10/20/2001 | | 54FCT2373A (GEN) | 341 |
| 5962-9302503M2A | | 01/05/1996 | | (NONE) | 10/20/2001 | | 54FCT2373C (GEN) | 341 |
| 5962-9302503MRA | | 01/05/1996 | | (NONE) | 10/20/2001 | | 54FCT2373C (GEN) | 341 |
| 5962-9302503MSA | | 01/05/1996 | | (NONE) | 10/20/2001 | | 54FCT2373C (GEN) | 341 |
| 5962-9302601M2A | | 11/28/1995 | | (NONE) | 10/20/2001 | | 54FCT2374 (GEN) | 159 |
| 5962-9302601MRA | | 11/28/1995 | | (NONE) | 10/20/2001 | | 54FCT2374 (GEN) | 159 |
| 5962-9302601MSA | | 11/28/1995 | | (NONE) | 10/20/2001 | | 54FCT2374 (GEN) | 159 |
| 5962-9302602M2A | | 11/28/1995 | | (NONE) | 10/20/2001 | | 54FCT2374A (GEN) | 159 |
| 5962-9302602MRA | | 11/28/1995 | | (NONE) | 10/20/2001 | | 54FCT2374A (GEN) | 159 |
| 5962-9302602MSA | | 11/28/1995 | | (NONE) | 10/20/2001 | | 54FCT2374A (GEN) | 159 |
| 5962-9302603M2A | | 11/28/1995 | | (NONE) | 10/20/2001 | | 54FCT2374C (GEN) | 159 |
| 5962-9302603MRA | | 11/28/1995 | | (NONE) | 10/20/2001 | | 54FCT2374C (GEN) | 159 |
| 5962-9302603MSA | | 11/28/1995 | | (NONE) | 10/20/2001 | | 54FCT2374C (GEN) | 159 |
| 5962-9305501M2A | E | 12/12/2003 | 1 | NATIONAL | | Y | CLC415AE-QML | 713 |
| 5962-9305501MCA | E | 12/12/2003 | 1 | NATIONAL | | Y | CLC415AJ-QML | 713 |
| 5962-9305601MXA | A | 05/01/2001 | | (NONE) | | | 10C68 (GEN) | 620 |
| 5962-9305601MYA | A | 05/01/2001 | | (NONE) | | | 10C68 (GEN) | 620 |
| 5962-9305602MXA | A | 05/01/2001 | | (NONE) | | | 10C68 (GEN) | 620 |
| 5962-9305602MYA | A | 05/01/2001 | | (NONE) | | | 10C68 (GEN) | 620 |
| 5962-9305603MXA | A | 05/01/2001 | | (NONE) | | | 10C68 (GEN) | 620 |
| 5962-9305603MYA | A | 05/01/2001 | | (NONE) | | | 10C68 (GEN) | 620 |
| 5962-9305604MXA | A | 05/01/2001 | 1 | SIMTEK | | | STK10C68-5C55M | 620 |
| 5962-9305604MXC | A | 05/01/2001 | 1 | SIMTEK | | | STK10C68-5C55M | 620 |
| 5962-9305604MYA | A | 05/01/2001 | 1 | SIMTEK | | | STK10C68-5L55M | 620 |
| 5962-9305605MXA | A | 05/01/2001 | 1 | SIMTEK | | | STK10C68-5C45M | 620 |
| 5962-9305605MXC | A | 05/01/2001 | 1 | SIMTEK | | | STK10C68-5C45M | 620 |
| 5962-9305605MYA | A | 05/01/2001 | 1 | SIMTEK | | | STK10C68-5L45M | 620 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9305606MXA | A | 05/01/2001 | 1 | SIMTEK | | | STK10C68-5C35M | 620 |
| 5962-9305606MXC | A | 05/01/2001 | 1 | SIMTEK | | | STK10C68-5C35M | 620 |
| 5962-9305606MYA | A | 05/01/2001 | 1 | SIMTEK | | | STK10C68-5L35M | 620 |
| 5962-9305701MPA | A | 03/20/1995 | 1 | MINCO | | Y | MTL1291MJ8/883 | 433 |
| 5962-9305702MPA | A | 03/20/1995 | | (NONE) | 03/30/2001 | | LTC1292B (GEN) | 433 |
| 5962-9305703MEA | A | 03/20/1995 | | (NONE) | 03/30/2001 | | LTC1293B (GEN) | 433 |
| 5962-9305704MRA | A | 03/20/1995 | | (NONE) | 03/30/2001 | | LTC1294B (GEN) | 433 |
| 5962-9305705MPA | A | 03/20/1995 | | (NONE) | 03/30/2001 | | LTC1291C (GEN) | 433 |
| 5962-9305706MPA | A | 03/20/1995 | | (NONE) | 03/30/2001 | | LTC1292C (GEN) | 433 |
| 5962-9305707MEA | A | 03/20/1995 | | (NONE) | 03/30/2001 | | LTC1293C (GEN) | 433 |
| 5962-9305708MRA | A | 03/20/1995 | | (NONE) | 03/30/2001 | | LTC1294C (GEN) | 433 |
| 5962-9305709MPA | A | 03/20/1995 | | (NONE) | 03/30/2001 | | LTC1291D (GEN) | 433 |
| 5962-9305710MPA | A | 03/20/1995 | | (NONE) | 03/30/2001 | | LTC1292D (GEN) | 433 |
| 5962-9305711MEA | A | 03/20/1995 | | (NONE) | 03/30/2001 | | LTC1293D (GEN) | 433 |
| 5962-9305712MRA | A | 03/20/1995 | | (NONE) | 03/30/2001 | | LTC1294D (GEN) | 433 |
| 5962-9306001MXA | E | 05/03/2001 | 1 | ANALOG (2) | | Y | AD872ASD/883B | 592 |
| 5962-9306002MYA | E | 05/03/2001 | 1 | ANALOG (2) | 05/28/2005 | Y | AD872ASE/883B | 592 |
| 5962-9306003MXA | E | 05/03/2001 | 1 | ANALOG (2) | | Y | AD872ASD/883B | 592 |
| 5962-9306004MYA | E | 05/03/2001 | 1 | ANALOG (2) | | Y | AD872ASE/883B | 592 |
| 5962-9306201M3A | | 11/29/1993 | | (NONE) | 09/30/2000 | | AD9720 (GEN) | 591 |
| 5962-9306201MXA | | 11/29/1993 | | (NONE) | 09/30/2000 | | AD9720 (GEN) | 591 |
| 5962-9306202M3A | | 11/29/1993 | | (NONE) | 09/30/2000 | | AD9721 (GEN) | 592 |
| 5962-9306202MXA | | 11/29/1993 | | (NONE) | 09/30/2000 | | AD9721 (GEN) | 592 |
| 5962-9306301M2A | B | 10/16/2001 | 1 | INTERSIL | | Y | HA4-5340/883 | 818 |
| 5962-9306301MCA | B | 10/16/2001 | 1 | INTERSIL | 10/03/2004 | Y | HA1-5340/883 | 818 |
| 5962-9306302M2A | B | 10/16/2001 | 1 | INTERSIL | 07/02/2004 | Y | HA4-5320/883 | 818 |
| 5962-9306302MCA | B | 10/16/2001 | 1 | INTERSIL | 10/03/2004 | Y | HA1-5320/883 | 818 |
| 5962-9306501HXA | K | 07/16/2004 | 1 | DDC | | Y | BU-65170S1-140 | 590 |
| 5962-9306501HXA | K | 07/16/2004 | 1 | DDC | | Y | BU-65170BS1-150 | 590 |
| 5962-9306501HXA | K | 07/16/2004 | 1 | DDC | | Y | BU-65170BS1-140 | 590 |
| 5962-9306501HXA | K | 07/16/2004 | 1 | DDC | | Y | BU-65170S1-150 | 590 |
| 5962-9306501HXA | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-65170BS1-140 | 590 |
| 5962-9306501HXA | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-65170BS1-150 | 590 |
| 5962-9306501HXA | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-65170S1-140 | 590 |
| 5962-9306501HXA | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-65170S1-150 | 590 |
| 5962-9306501HXC | K | 07/16/2004 | 1 | DDC | | Y | BU-65170BS1-130 | 590 |
| 5962-9306501HXC | K | 07/16/2004 | 1 | DDC | | Y | BU-65170BS1-110 | 590 |
| 5962-9306501HXC | K | 07/16/2004 | 1 | DDC | | Y | BU-65170S1-130 | 590 |
| 5962-9306501HXC | K | 07/16/2004 | 1 | DDC | | Y | BU-65170S1-110 | 590 |
| 5962-9306501HXC | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-65170BS1-110 | 590 |
| 5962-9306501HXC | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-65170BS1-130 | 590 |
| 5962-9306501HXC | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-65170S1-110 | 590 |
| 5962-9306501HXC | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-65170S1-130 | 590 |
| 5962-9306501HYA | K | 07/16/2004 | 1 | DDC | | Y | BU-65170BV1-150 | 590 |
| 5962-9306501HYA | K | 07/16/2004 | 1 | DDC | | Y | BU-65170BV1-140 | 590 |
| 5962-9306501HYA | K | 07/16/2004 | 1 | DDC | | Y | BU-65170V1-140 | 590 |
| 5962-9306501HYA | K | 07/16/2004 | 1 | DDC | | Y | BU-65170V1-150 | 590 |
| 5962-9306501HYA | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-65170BV1-140 | 590 |
| 5962-9306501HYA | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-65170BV1-150 | 590 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9306501HYA | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-65170V1-150 | 590 |
| 5962-9306501HYA | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-65170V1-140 | 590 |
| 5962-9306501HYC | K | 07/16/2004 | 1 | DDC | | Y | BU-65170BV1-110 | 590 |
| 5962-9306501HYC | K | 07/16/2004 | 1 | DDC | | Y | BU-65170BV1-130 | 590 |
| 5962-9306501HYC | K | 07/16/2004 | 1 | DDC | | Y | BU-65170V1-130 | 590 |
| 5962-9306501HYC | K | 07/16/2004 | 1 | DDC | | Y | BU-65170V1-110 | 590 |
| 5962-9306501HYC | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-65170BV1-130 | 590 |
| 5962-9306501HYC | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-65170BV1-110 | 590 |
| 5962-9306501HYC | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-65170V1-110 | 590 |
| 5962-9306501HYC | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-65170V1-130 | 590 |
| 5962-9306501HZC | K | 07/16/2004 | 1 | DDC | | Y | BU-65170J1-130 | 590 |
| 5962-9306501HZC | K | 07/16/2004 | 1 | DDC | | Y | BU-65170J1-110 | 590 |
| 5962-9306502HXA | K | 07/16/2004 | 1 | DDC | | Y | BU-65170BS2-140 | 590 |
| 5962-9306502HXA | K | 07/16/2004 | 1 | DDC | | Y | BU-65170BS2-150 | 590 |
| 5962-9306502HXA | K | 07/16/2004 | 1 | DDC | | Y | BU-65170S2-140 | 590 |
| 5962-9306502HXA | K | 07/16/2004 | 1 | DDC | | Y | BU-65170S2-150 | 590 |
| 5962-9306502HXA | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-65170BS2-140 | 590 |
| 5962-9306502HXA | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-65170BS2-150 | 590 |
| 5962-9306502HXA | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-65170S2-150 | 590 |
| 5962-9306502HXA | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-65170S2-140 | 590 |
| 5962-9306502HXC | K | 07/16/2004 | 1 | DDC | | Y | BU-65170S2-130 | 590 |
| 5962-9306502HXC | K | 07/16/2004 | 1 | DDC | | Y | BU-65170BS2-130 | 590 |
| 5962-9306502HXC | K | 07/16/2004 | 1 | DDC | | Y | BU-65170BS2-110 | 590 |
| 5962-9306502HXC | K | 07/16/2004 | 1 | DDC | | Y | BU-65170S2-110 | 590 |
| 5962-9306502HXC | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-65170BS2-110 | 590 |
| 5962-9306502HXC | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-65170BS2-130 | 590 |
| 5962-9306502HXC | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-65170S2-110 | 590 |
| 5962-9306502HXC | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-65170S2-130 | 590 |
| 5962-9306502HYA | K | 07/16/2004 | 1 | DDC | | Y | BU-65170BV2-140 | 590 |
| 5962-9306502HYA | K | 07/16/2004 | 1 | DDC | | Y | BU-65170BV2-150 | 590 |
| 5962-9306502HYA | K | 07/16/2004 | 1 | DDC | | Y | BU-65170V2-140 | 590 |
| 5962-9306502HYA | K | 07/16/2004 | 1 | DDC | | Y | BU-65170V2-150 | 590 |
| 5962-9306502HYA | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-65170BV2-140 | 590 |
| 5962-9306502HYA | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-65170BV2-150 | 590 |
| 5962-9306502HYA | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-65170V2-140 | 590 |
| 5962-9306502HYA | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-65170V2-150 | 590 |
| 5962-9306502HYC | K | 07/16/2004 | 1 | DDC | | Y | BU-65170BV2-110 | 590 |
| 5962-9306502HYC | K | 07/16/2004 | 1 | DDC | | Y | BU-65170BV2-130 | 590 |
| 5962-9306502HYC | K | 07/16/2004 | 1 | DDC | | Y | BU-65170V2-110 | 590 |
| 5962-9306502HYC | K | 07/16/2004 | 1 | DDC | | Y | BU-65170V2-130 | 590 |
| 5962-9306502HYC | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-65170BV2-110 | 590 |
| 5962-9306502HYC | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-65170BV2-130 | 590 |
| 5962-9306502HYC | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-65170V2-130 | 590 |
| 5962-9306502HYC | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-65170V2-110 | 590 |
| 5962-9306502HZC | K | 07/16/2004 | 1 | DDC | | Y | BU-65170J2-110 | 590 |
| 5962-9306502HZC | K | 07/16/2004 | 1 | DDC | | Y | BU-65170J2-130 | 590 |
| 5962-9306503HXA | K | 07/16/2004 | 1 | DDC | | Y | BU-61580BS1-150 | 590 |
| 5962-9306503HXA | K | 07/16/2004 | 1 | DDC | | Y | BU-61580BS1-140 | 590 |
| 5962-9306503HXA | K | 07/16/2004 | 1 | DDC | | Y | BU-61580S1-140 | 590 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9306503HXA | K | 07/16/2004 | 1 | DDC | | Y | BU-61580S1-150 | 590 |
| 5962-9306503HXA | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61580BS1-140 | 590 |
| 5962-9306503HXA | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61580BS1-150 | 590 |
| 5962-9306503HXA | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61580S1-140 | 590 |
| 5962-9306503HXA | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61580S1-150 | 590 |
| 5962-9306503HXC | K | 07/16/2004 | 1 | DDC | | Y | BU-61580BS1-130 | 590 |
| 5962-9306503HXC | K | 07/16/2004 | 1 | DDC | | Y | BU-61580S1-130 | 590 |
| 5962-9306503HXC | K | 07/16/2004 | 1 | DDC | | Y | BU-61580BS1-110 | 590 |
| 5962-9306503HXC | K | 07/16/2004 | 1 | DDC | | Y | BU-61580S1-110 | 590 |
| 5962-9306503HXC | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61580BS1-130 | 590 |
| 5962-9306503HXC | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61580BS1-110 | 590 |
| 5962-9306503HXC | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61580S1-110 | 590 |
| 5962-9306503HXC | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61580S1-130 | 590 |
| 5962-9306503HYA | K | 07/16/2004 | 1 | DDC | | Y | BU-61580V1-140 | 590 |
| 5962-9306503HYA | K | 07/16/2004 | 1 | DDC | | Y | BU-61580BV1-150 | 590 |
| 5962-9306503HYA | K | 07/16/2004 | 1 | DDC | | Y | BU-61580BV1-140 | 590 |
| 5962-9306503HYA | K | 07/16/2004 | 1 | DDC | | Y | BU-61580V1-150 | 590 |
| 5962-9306503HYA | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61580BV1-150 | 590 |
| 5962-9306503HYA | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61580BV1-140 | 590 |
| 5962-9306503HYA | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61580V1-150 | 590 |
| 5962-9306503HYA | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61580V1-140 | 590 |
| 5962-9306503HYC | K | 07/16/2004 | 1 | DDC | | Y | BU-61580BV1-110 | 590 |
| 5962-9306503HYC | K | 07/16/2004 | 1 | DDC | | Y | BU-61580V1-130 | 590 |
| 5962-9306503HYC | K | 07/16/2004 | 1 | DDC | | Y | BU-61580BV1-130 | 590 |
| 5962-9306503HYC | K | 07/16/2004 | 1 | DDC | | Y | BU-61580V1-110 | 590 |
| 5962-9306503HYC | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61580BV1-110 | 590 |
| 5962-9306503HYC | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61580BV1-130 | 590 |
| 5962-9306503HYC | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61580V1-130 | 590 |
| 5962-9306503HYC | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61580V1-110 | 590 |
| 5962-9306503HZC | K | 07/16/2004 | 1 | DDC | | Y | BU-61580J1-110 | 590 |
| 5962-9306503HZC | K | 07/16/2004 | 1 | DDC | | Y | BU-61580J1-130 | 590 |
| 5962-9306504HXA | K | 07/16/2004 | 1 | DDC | | Y | BU-61580S2-140 | 590 |
| 5962-9306504HXA | K | 07/16/2004 | 1 | DDC | | Y | BU-61580BS2-150 | 590 |
| 5962-9306504HXA | K | 07/16/2004 | 1 | DDC | | Y | BU-61580BS2-140 | 590 |
| 5962-9306504HXA | K | 07/16/2004 | 1 | DDC | | Y | BU-61580S2-150 | 590 |
| 5962-9306504HXA | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61580BS2-140 | 590 |
| 5962-9306504HXA | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61580BS2-150 | 590 |
| 5962-9306504HXA | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61580S2-140 | 590 |
| 5962-9306504HXA | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61580S2-150 | 590 |
| 5962-9306504HXC | K | 07/16/2004 | 1 | DDC | | Y | BU-61580BS2-130 | 590 |
| 5962-9306504HXC | K | 07/16/2004 | 1 | DDC | | Y | BU-61580BS2-110 | 590 |
| 5962-9306504HXC | K | 07/16/2004 | 1 | DDC | | Y | BU-61580S2-110 | 590 |
| 5962-9306504HXC | K | 07/16/2004 | 1 | DDC | | Y | BU-61580S2-130 | 590 |
| 5962-9306504HXC | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61580BS2-110 | 590 |
| 5962-9306504HXC | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61580BS2-130 | 590 |
| 5962-9306504HXC | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61580S2-110 | 590 |
| 5962-9306504HXC | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61580S2-130 | 590 |
| 5962-9306504HYA | K | 07/16/2004 | 1 | DDC | | Y | BU-61580BV2-140 | 590 |
| 5962-9306504HYA | K | 07/16/2004 | 1 | DDC | | Y | BU-61580BV2-150 | 590 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9306504HYA | K | 07/16/2004 | 1 | DDC | | Y | BU-61580V2-140 | 590 |
| 5962-9306504HYA | K | 07/16/2004 | 1 | DDC | | Y | BU-61580V2-150 | 590 |
| 5962-9306504HYA | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61580BV2-140 | 590 |
| 5962-9306504HYA | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61580BV2-150 | 590 |
| 5962-9306504HYA | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61580V2-140 | 590 |
| 5962-9306504HYA | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61580V2-150 | 590 |
| 5962-9306504HYC | K | 07/16/2004 | 1 | DDC | | Y | BU-61580V2-110 | 590 |
| 5962-9306504HYC | K | 07/16/2004 | 1 | DDC | | Y | BU-61580BV2-130 | 590 |
| 5962-9306504HYC | K | 07/16/2004 | 1 | DDC | | Y | BU-61580BV2-110 | 590 |
| 5962-9306504HYC | K | 07/16/2004 | 1 | DDC | | Y | BU-61580V2-130 | 590 |
| 5962-9306504HYC | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61580BV2-130 | 590 |
| 5962-9306504HYC | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61580BV2-110 | 590 |
| 5962-9306504HYC | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61580V2-110 | 590 |
| 5962-9306504HYC | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61580V2-130 | 590 |
| 5962-9306504HZC | K | 07/16/2004 | 1 | DDC | | Y | BU-61580J2-110 | 590 |
| 5962-9306504HZC | K | 07/16/2004 | 1 | DDC | | Y | BU-61580J2-130 | 590 |
| 5962-9306505HXA | K | 07/16/2004 | 1 | DDC | | Y | BU-65171BS1-140 | 590 |
| 5962-9306505HXA | K | 07/16/2004 | 1 | DDC | | Y | BU-65171BS1-150 | 590 |
| 5962-9306505HXA | K | 07/16/2004 | 1 | DDC | | Y | BU-65171S1-140 | 590 |
| 5962-9306505HXA | K | 07/16/2004 | 1 | DDC | | Y | BU-65171S1-150 | 590 |
| 5962-9306505HXA | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-65171BS1-140 | 590 |
| 5962-9306505HXA | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-65171BS1-150 | 590 |
| 5962-9306505HXA | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-65171S1-140 | 590 |
| 5962-9306505HXA | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-65171S1-150 | 590 |
| 5962-9306505HXC | K | 07/16/2004 | 1 | DDC | | Y | BU-65171BS1-110 | 590 |
| 5962-9306505HXC | K | 07/16/2004 | 1 | DDC | | Y | BU-65171S1-110 | 590 |
| 5962-9306505HXC | K | 07/16/2004 | 1 | DDC | | Y | BU-65171BS1-130 | 590 |
| 5962-9306505HXC | K | 07/16/2004 | 1 | DDC | | Y | BU-65171S1-130 | 590 |
| 5962-9306505HXC | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-65171BS1-110 | 590 |
| 5962-9306505HXC | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-65171BS1-130 | 590 |
| 5962-9306505HXC | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-65171S1-110 | 590 |
| 5962-9306505HXC | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-65171S1-130 | 590 |
| 5962-9306505HYA | K | 07/16/2004 | 1 | DDC | | Y | BU-65171BV1-140 | 590 |
| 5962-9306505HYA | K | 07/16/2004 | 1 | DDC | | Y | BU-65171V1-140 | 590 |
| 5962-9306505HYA | K | 07/16/2004 | 1 | DDC | | Y | BU-65171BV1-150 | 590 |
| 5962-9306505HYA | K | 07/16/2004 | 1 | DDC | | Y | BU-65171V1-150 | 590 |
| 5962-9306505HYA | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-65171BV1-150 | 590 |
| 5962-9306505HYA | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-65171BV1-140 | 590 |
| 5962-9306505HYA | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-65171V1-150 | 590 |
| 5962-9306505HYA | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-65171V1-140 | 590 |
| 5962-9306505HYC | K | 07/16/2004 | 1 | DDC | | Y | BU-65171BV1-110 | 590 |
| 5962-9306505HYC | K | 07/16/2004 | 1 | DDC | | Y | BU-65171BV1-130 | 590 |
| 5962-9306505HYC | K | 07/16/2004 | 1 | DDC | | Y | BU-65171V1-110 | 590 |
| 5962-9306505HYC | K | 07/16/2004 | 1 | DDC | | Y | BU-65171V1-130 | 590 |
| 5962-9306505HYC | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-65171BV1-110 | 590 |
| 5962-9306505HYC | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-65171BV1-130 | 590 |
| 5962-9306505HYC | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-65171V1-130 | 590 |
| 5962-9306505HYC | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-65171V1-110 | 590 |
| 5962-9306505HZC | K | 07/16/2004 | 1 | DDC | | Y | BU-65171J1-130 | 590 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9306505HZC | K | 07/16/2004 | 1 | DDC | | Y | BU-65171J1-110 | 590 |
| 5962-9306506HXA | K | 07/16/2004 | 1 | DDC | | Y | BU-65171BS2-140 | 590 |
| 5962-9306506HXA | K | 07/16/2004 | 1 | DDC | | Y | BU-65171BS2-150 | 590 |
| 5962-9306506HXA | K | 07/16/2004 | 1 | DDC | | Y | BU-65171S2-140 | 590 |
| 5962-9306506HXA | K | 07/16/2004 | 1 | DDC | | Y | BU-65171S2-150 | 590 |
| 5962-9306506HXA | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-65171BS2-150 | 590 |
| 5962-9306506HXA | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-65171BS2-140 | 590 |
| 5962-9306506HXA | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-65171S2-150 | 590 |
| 5962-9306506HXA | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-65171S2-140 | 590 |
| 5962-9306506HXC | K | 07/16/2004 | 1 | DDC | | Y | BU-65171BS2-110 | 590 |
| 5962-9306506HXC | K | 07/16/2004 | 1 | DDC | | Y | BU-65171BS2-130 | 590 |
| 5962-9306506HXC | K | 07/16/2004 | 1 | DDC | | Y | BU-65171S2-110 | 590 |
| 5962-9306506HXC | K | 07/16/2004 | 1 | DDC | | Y | BU-65171S2-130 | 590 |
| 5962-9306506HXC | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-65171BS2-110 | 590 |
| 5962-9306506HXC | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-65171BS2-130 | 590 |
| 5962-9306506HXC | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-65171S2-130 | 590 |
| 5962-9306506HXC | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-65171S2-110 | 590 |
| 5962-9306506HYA | K | 07/16/2004 | 1 | DDC | | Y | BU-65171BV2-140 | 590 |
| 5962-9306506HYA | K | 07/16/2004 | 1 | DDC | | Y | BU-65171BV2-150 | 590 |
| 5962-9306506HYA | K | 07/16/2004 | 1 | DDC | | Y | BU-65171V2-140 | 590 |
| 5962-9306506HYA | K | 07/16/2004 | 1 | DDC | | Y | BU-65171V2-150 | 590 |
| 5962-9306506HYA | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-65171BV2-140 | 590 |
| 5962-9306506HYA | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-65171BV2-150 | 590 |
| 5962-9306506HYA | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-65171V2-140 | 590 |
| 5962-9306506HYA | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-65171V2-150 | 590 |
| 5962-9306506HYC | K | 07/16/2004 | 1 | DDC | | Y | BU-65171V2-110 | 590 |
| 5962-9306506HYC | K | 07/16/2004 | 1 | DDC | | Y | BU-65171BV2-110 | 590 |
| 5962-9306506HYC | K | 07/16/2004 | 1 | DDC | | Y | BU-65171BV2-130 | 590 |
| 5962-9306506HYC | K | 07/16/2004 | 1 | DDC | | Y | BU-65171V2-130 | 590 |
| 5962-9306506HYC | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-65171BV2-110 | 590 |
| 5962-9306506HYC | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-65171BV2-130 | 590 |
| 5962-9306506HYC | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-65171V2-110 | 590 |
| 5962-9306506HYC | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-65171V2-130 | 590 |
| 5962-9306506HZC | K | 07/16/2004 | 1 | DDC | | Y | BU-65171J2-130 | 590 |
| 5962-9306506HZC | K | 07/16/2004 | 1 | DDC | | Y | BU-65171J2-110 | 590 |
| 5962-9306507HXA | K | 07/16/2004 | 1 | DDC | | Y | BU-61581BS1-140 | 590 |
| 5962-9306507HXA | K | 07/16/2004 | 1 | DDC | | Y | BU-61581BS1-150 | 590 |
| 5962-9306507HXA | K | 07/16/2004 | 1 | DDC | | Y | BU-61581S1-140 | 590 |
| 5962-9306507HXA | K | 07/16/2004 | 1 | DDC | | Y | BU-61581S1-150 | 590 |
| 5962-9306507HXA | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61581BS1-140 | 590 |
| 5962-9306507HXA | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61581BS1-150 | 590 |
| 5962-9306507HXA | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61581S1-140 | 590 |
| 5962-9306507HXA | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61581S1-150 | 590 |
| 5962-9306507HXC | K | 07/16/2004 | 1 | DDC | | Y | BU-61581BS1-130 | 590 |
| 5962-9306507HXC | K | 07/16/2004 | 1 | DDC | | Y | BU-61581BS1-110 | 590 |
| 5962-9306507HXC | K | 07/16/2004 | 1 | DDC | | Y | BU-61581S1-110 | 590 |
| 5962-9306507HXC | K | 07/16/2004 | 1 | DDC | | Y | BU-61581S1-130 | 590 |
| 5962-9306507HXC | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61581BS1-110 | 590 |
| 5962-9306507HXC | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61581BS1-130 | 590 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9306507HXC | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61581S1-110 | 590 |
| 5962-9306507HXC | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61581S1-130 | 590 |
| 5962-9306507HYA | K | 07/16/2004 | 1 | DDC | | Y | BU-61581V1-140 | 590 |
| 5962-9306507HYA | K | 07/16/2004 | 1 | DDC | | Y | BU-61581BV1-150 | 590 |
| 5962-9306507HYA | K | 07/16/2004 | 1 | DDC | | Y | BU-61581BV1-140 | 590 |
| 5962-9306507HYA | K | 07/16/2004 | 1 | DDC | | Y | BU-61581V1-150 | 590 |
| 5962-9306507HYA | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61581BV1-150 | 590 |
| 5962-9306507HYA | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61581BV1-140 | 590 |
| 5962-9306507HYA | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61581V1-140 | 590 |
| 5962-9306507HYA | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61581V1-150 | 590 |
| 5962-9306507HYC | K | 07/16/2004 | 1 | DDC | | Y | BU-61581V1-110 | 590 |
| 5962-9306507HYC | K | 07/16/2004 | 1 | DDC | | Y | BU-61581BV1-110 | 590 |
| 5962-9306507HYC | K | 07/16/2004 | 1 | DDC | | Y | BU-61581BV1-130 | 590 |
| 5962-9306507HYC | K | 07/16/2004 | 1 | DDC | | Y | BU-61581V1-130 | 590 |
| 5962-9306507HYC | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61581BV1-130 | 590 |
| 5962-9306507HYC | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61581BV1-110 | 590 |
| 5962-9306507HYC | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61581V1-130 | 590 |
| 5962-9306507HYC | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61581V1-110 | 590 |
| 5962-9306507HZC | K | 07/16/2004 | 1 | DDC | | Y | BU-61581J1-110 | 590 |
| 5962-9306507HZC | K | 07/16/2004 | 1 | DDC | | Y | BU-61581J1-130 | 590 |
| 5962-9306508HXA | K | 07/16/2004 | 1 | DDC | | Y | BU-61581BS2-150 | 590 |
| 5962-9306508HXA | K | 07/16/2004 | 1 | DDC | | Y | BU-61581BS2-140 | 590 |
| 5962-9306508HXA | K | 07/16/2004 | 1 | DDC | | Y | BU-61581S2-140 | 590 |
| 5962-9306508HXA | K | 07/16/2004 | 1 | DDC | | Y | BU-61581S2-150 | 590 |
| 5962-9306508HXA | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61581BS2-150 | 590 |
| 5962-9306508HXA | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61581BS2-140 | 590 |
| 5962-9306508HXA | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61581S2-150 | 590 |
| 5962-9306508HXA | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61581S2-140 | 590 |
| 5962-9306508HXC | K | 07/16/2004 | 1 | DDC | | Y | BU-61581BS2-130 | 590 |
| 5962-9306508HXC | K | 07/16/2004 | 1 | DDC | | Y | BU-61581BS2-110 | 590 |
| 5962-9306508HXC | K | 07/16/2004 | 1 | DDC | | Y | BU-61581S2-110 | 590 |
| 5962-9306508HXC | K | 07/16/2004 | 1 | DDC | | Y | BU-61581S2-130 | 590 |
| 5962-9306508HXC | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61581BS2-110 | 590 |
| 5962-9306508HXC | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61581BS2-130 | 590 |
| 5962-9306508HXC | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61581S2-130 | 590 |
| 5962-9306508HXC | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61581S2-110 | 590 |
| 5962-9306508HYA | K | 07/16/2004 | 1 | DDC | | Y | BU-61581BV2-140 | 590 |
| 5962-9306508HYA | K | 07/16/2004 | 1 | DDC | | Y | BU-61581V2-140 | 590 |
| 5962-9306508HYA | K | 07/16/2004 | 1 | DDC | | Y | BU-61581BV2-150 | 590 |
| 5962-9306508HYA | K | 07/16/2004 | 1 | DDC | | Y | BU-61581V2-150 | 590 |
| 5962-9306508HYA | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61581BV2-150 | 590 |
| 5962-9306508HYA | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61581BV2-140 | 590 |
| 5962-9306508HYA | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61581V2-150 | 590 |
| 5962-9306508HYA | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61581V2-140 | 590 |
| 5962-9306508HYC | K | 07/16/2004 | 1 | DDC | | Y | BU-61581BV2-110 | 590 |
| 5962-9306508HYC | K | 07/16/2004 | 1 | DDC | | Y | BU-61581BV2-130 | 590 |
| 5962-9306508HYC | K | 07/16/2004 | 1 | DDC | | Y | BU-61581V2-110 | 590 |
| 5962-9306508HYC | K | 07/16/2004 | 1 | DDC | | Y | BU-61581V2-130 | 590 |
| 5962-9306508HYC | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61581BV2-110 | 590 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9306508HYC | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61581BV2-130 | 590 |
| 5962-9306508HYC | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61581V2-130 | 590 |
| 5962-9306508HYC | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61581V2-110 | 590 |
| 5962-9306508HZC | K | 07/16/2004 | 1 | DDC | | Y | BU-61581J2-130 | 590 |
| 5962-9306508HZC | K | 07/16/2004 | 1 | DDC | | Y | BU-61581J2-110 | 590 |
| 5962-9306509HXA | K | 07/16/2004 | | (NONE) | | | BU-65170 (GEN) | 590 |
| 5962-9306509HYA | K | 07/16/2004 | | (NONE) | | | BU-65170 (GEN) | 590 |
| 5962-9306510HXA | K | 07/16/2004 | | (NONE) | | | BU-65170 (GEN) | 590 |
| 5962-9306510HYA | K | 07/16/2004 | | (NONE) | | | BU-65170 (GEN) | 590 |
| 5962-9306511HXA | K | 07/16/2004 | | (NONE) | | | BU-61580 (GEN) | 590 |
| 5962-9306511HYA | K | 07/16/2004 | | (NONE) | | | BU-61580 (GEN) | 590 |
| 5962-9306512HXA | K | 07/16/2004 | | (NONE) | | | BU-61580 (GEN) | 590 |
| 5962-9306512HYA | K | 07/16/2004 | | (NONE) | | | BU-61580 (GEN) | 590 |
| 5962-9306513HXA | K | 07/16/2004 | | (NONE) | | | BU-65171 (GEN) | 590 |
| 5962-9306513HYA | K | 07/16/2004 | | (NONE) | | | BU-61581 (GEN) | 590 |
| 5962-9306514HXA | K | 07/16/2004 | | (NONE) | | | BU-61581 (GEN) | 590 |
| 5962-9306514HYA | K | 07/16/2004 | | (NONE) | | | BU-61581 (GEN) | 590 |
| 5962-9306515HXA | K | 07/16/2004 | | (NONE) | | | BU-61581 (GEN) | 590 |
| 5962-9306515HYA | K | 07/16/2004 | | (NONE) | | | BU-61581 (GEN) | 590 |
| 5962-9306516HXA | K | 07/16/2004 | | (NONE) | | | BU-61581 (GEN) | 590 |
| 5962-9306516HYA | K | 07/16/2004 | | (NONE) | | | BU-61581 (GEN) | 590 |
| 5962-9306517HXA | K | 07/16/2004 | 1 | DDC | | Y | BU-61585S1-140 | 590 |
| 5962-9306517HXA | K | 07/16/2004 | 1 | DDC | | Y | BU-61585S1-150 | 590 |
| 5962-9306517HXA | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61585S1-140 | 590 |
| 5962-9306517HXA | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61585S1-150 | 590 |
| 5962-9306517HXC | K | 07/16/2004 | 1 | DDC | | Y | BU-61585S1-130 | 590 |
| 5962-9306517HXC | K | 07/16/2004 | 1 | DDC | | Y | BU-61585S1-110 | 590 |
| 5962-9306517HXC | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61585S1-110 | 590 |
| 5962-9306517HXC | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61585S1-130 | 590 |
| 5962-9306517HYA | K | 07/16/2004 | 1 | DDC | | Y | BU-61585V1-140 | 590 |
| 5962-9306517HYA | K | 07/16/2004 | 1 | DDC | | Y | BU-61585V1-150 | 590 |
| 5962-9306517HYA | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61585V1-140 | 590 |
| 5962-9306517HYA | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61585V1-150 | 590 |
| 5962-9306517HYC | K | 07/16/2004 | 1 | DDC | | Y | BU-61585V1-130 | 590 |
| 5962-9306517HYC | K | 07/16/2004 | 1 | DDC | | Y | BU-61585V1-110 | 590 |
| 5962-9306517HYC | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61585V1-110 | 590 |
| 5962-9306517HYC | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61585V1-130 | 590 |
| 5962-9306517HZC | K | 07/16/2004 | | (NONE) | | | BU-61585 (GEN) | 590 |
| 5962-9306518HXA | K | 07/16/2004 | 1 | DDC | | Y | BU-61585S2-140 | 590 |
| 5962-9306518HXA | K | 07/16/2004 | 1 | DDC | | Y | BU-61585S2-150 | 590 |
| 5962-9306518HXA | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61585S2-140 | 590 |
| 5962-9306518HXA | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61585S2-150 | 590 |
| 5962-9306518HXC | K | 07/16/2004 | 1 | DDC | | Y | BU-61585S2-130 | 590 |
| 5962-9306518HXC | K | 07/16/2004 | 1 | DDC | | Y | BU-61585S2-110 | 590 |
| 5962-9306518HXC | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61585S2-130 | 590 |
| 5962-9306518HXC | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61585S2-110 | 590 |
| 5962-9306518HYA | K | 07/16/2004 | 1 | DDC | | Y | BU-61585V2-140 | 590 |
| 5962-9306518HYA | K | 07/16/2004 | 1 | DDC | | Y | BU-61585V2-150 | 590 |
| 5962-9306518HYA | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61585V2-150 | 590 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9306518HYA | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61585V2-140 | 590 |
| 5962-9306518HYC | K | 07/16/2004 | 1 | DDC | | Y | BU-61585V2-110 | 590 |
| 5962-9306518HYC | K | 07/16/2004 | 1 | DDC | | Y | BU-61585V2-130 | 590 |
| 5962-9306518HYC | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61585V2-130 | 590 |
| 5962-9306518HYC | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61585V2-110 | 590 |
| 5962-9306518HZC | K | 07/16/2004 | | (NONE) | | | BU-61585 (GEN) | 590 |
| 5962-9306519HXA | K | 07/16/2004 | 1 | DDC | | Y | BU-61586S1-140 | 590 |
| 5962-9306519HXA | K | 07/16/2004 | 1 | DDC | | Y | BU-61586S1-150 | 590 |
| 5962-9306519HXA | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61586S1-150 | 590 |
| 5962-9306519HXA | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61586S1-140 | 590 |
| 5962-9306519HXC | K | 07/16/2004 | 1 | DDC | | Y | BU-61586S1-110 | 590 |
| 5962-9306519HXC | K | 07/16/2004 | 1 | DDC | | Y | BU-61586S1-130 | 590 |
| 5962-9306519HXC | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61586S1-130 | 590 |
| 5962-9306519HXC | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61586S1-110 | 590 |
| 5962-9306519HYA | K | 07/16/2004 | 1 | DDC | | Y | BU-61586V1-140 | 590 |
| 5962-9306519HYA | K | 07/16/2004 | 1 | DDC | | Y | BU-61586V1-150 | 590 |
| 5962-9306519HYA | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61586V1-150 | 590 |
| 5962-9306519HYA | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61586V1-140 | 590 |
| 5962-9306519HYC | K | 07/16/2004 | 1 | DDC | | Y | BU-61586V1-110 | 590 |
| 5962-9306519HYC | K | 07/16/2004 | 1 | DDC | | Y | BU-61586V1-130 | 590 |
| 5962-9306519HYC | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61586V1-110 | 590 |
| 5962-9306519HYC | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61586V1-130 | 590 |
| 5962-9306519HZC | K | 07/16/2004 | | (NONE) | | | BU-61586 (GEN) | 590 |
| 5962-9306520HXA | K | 07/16/2004 | 1 | DDC | | Y | BU-61586S2-140 | 590 |
| 5962-9306520HXA | K | 07/16/2004 | 1 | DDC | | Y | BU-61586S2-150 | 590 |
| 5962-9306520HXA | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61586S2-150 | 590 |
| 5962-9306520HXA | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61586S2-140 | 590 |
| 5962-9306520HXC | K | 07/16/2004 | 1 | DDC | | Y | BU-61586S2-110 | 590 |
| 5962-9306520HXC | K | 07/16/2004 | 1 | DDC | | Y | BU-61586S2-130 | 590 |
| 5962-9306520HXC | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61586S2-130 | 590 |
| 5962-9306520HXC | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61586S2-110 | 590 |
| 5962-9306520HYA | K | 07/16/2004 | 1 | DDC | | Y | BU-61586V2-140 | 590 |
| 5962-9306520HYA | K | 07/16/2004 | 1 | DDC | | Y | BU-61586V2-150 | 590 |
| 5962-9306520HYA | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61586V2-140 | 590 |
| 5962-9306520HYA | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61586V2-150 | 590 |
| 5962-9306520HYC | K | 07/16/2004 | 1 | DDC | | Y | BU-61586V2-110 | 590 |
| 5962-9306520HYC | K | 07/16/2004 | 1 | DDC | | Y | BU-61586V2-130 | 590 |
| 5962-9306520HYC | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61585V2-130 | 590 |
| 5962-9306520HYC | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61585V2-110 | 590 |
| 5962-9306520HZC | K | 07/16/2004 | | (NONE) | | | BU-61585 (GEN) | 590 |
| 5962-9306521HXA | K | 07/16/2004 | | (NONE) | | | BU-61585 (GEN) | 590 |
| 5962-9306521HYA | K | 07/16/2004 | | (NONE) | | | BU-61585 (GEN) | 590 |
| 5962-9306522HXA | K | 07/16/2004 | | (NONE) | | | BU-61586 (GEN) | 590 |
| 5962-9306522HYA | K | 07/16/2004 | | (NONE) | | | BU-61586 (GEN) | 590 |
| 5962-9306523HXA | K | 07/16/2004 | | (NONE) | | | BU-61586 (GEN) | 590 |
| 5962-9306523HYA | K | 07/16/2004 | | (NONE) | | | BU-61586 (GEN) | 590 |
| 5962-9306524HXA | K | 07/16/2004 | | (NONE) | | | BU-61588 (GEN) | 590 |
| 5962-9306524HYA | K | 07/16/2004 | | (NONE) | | | BU-61588 (GEN) | 590 |
| 5962-9306525HTA | K | 07/16/2004 | | (NONE) | | | BU-61588 (GEN) | 590 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9306525HUA | K | 07/16/2004 | | (NONE) | | | BU-61588 (GEN) | 590 |
| 5962-9306525HUC | K | 07/16/2004 | | (NONE) | | | BU-61588 (GEN) | 590 |
| 5962-9306526HTA | K | 07/16/2004 | | (NONE) | | | BU-65178 (GEN) | 590 |
| 5962-9306526HUA | K | 07/16/2004 | | (NONE) | | | BU-65178 (GEN) | 590 |
| 5962-9306527HMA | K | 07/16/2004 | | (NONE) | | | BU-65179 (GEN) | 590 |
| 5962-9306527HTA | K | 07/16/2004 | | (NONE) | | | BU-65179 (GEN) | 590 |
| 5962-9306527HUA | K | 07/16/2004 | | (NONE) | | | BU-65179 (GEN) | 590 |
| 5962-9306528HMA | K | 07/16/2004 | | (NONE) | | | BU-61688 (GEN) | 590 |
| 5962-9306528HTA | K | 07/16/2004 | | (NONE) | | | BU-61688 (GEN) | 590 |
| 5962-9306528HUA | K | 07/16/2004 | | (NONE) | | | BU-61688 (GEN) | 590 |
| 5962-9306529HMA | K | 07/16/2004 | | (NONE) | | | BU-61689 (GEN) | 590 |
| 5962-9306529HMA | K | 07/16/2004 | | (NONE) | | | BU-61689 (GEN) | 590 |
| 5962-9306529HTA | K | 07/16/2004 | | (NONE) | | | BU-61689 (GEN) | 590 |
| 5962-9306530HNA | K | 07/16/2004 | 1 | DDC | | Y | BU-65170DG3-140 | 590 |
| 5962-9306530HNA | K | 07/16/2004 | 1 | DDC | | Y | BU-65170DG3-150 | 590 |
| 5962-9306530HNA | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-65170DG3-150 | 590 |
| 5962-9306530HNA | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-65170DG3-140 | 590 |
| 5962-9306530HNC | K | 07/16/2004 | 1 | DDC | | Y | BU-65170DG3-130 | 590 |
| 5962-9306530HNC | K | 07/16/2004 | 1 | DDC | | Y | BU-65170DG3-110 | 590 |
| 5962-9306530HNC | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-65170DG3-130 | 590 |
| 5962-9306530HNC | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-65170DG3-110 | 590 |
| 5962-9306530HXA | K | 07/16/2004 | 1 | DDC | | Y | BU-65170DS3-150 | 590 |
| 5962-9306530HXA | K | 07/16/2004 | 1 | DDC | | Y | BU-65170DS3-140 | 590 |
| 5962-9306530HXA | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-65170DS3-140 | 590 |
| 5962-9306530HXA | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-65170DS3-150 | 590 |
| 5962-9306530HXC | K | 07/16/2004 | 1 | DDC | | Y | BU-65170DS3-110 | 590 |
| 5962-9306530HXC | K | 07/16/2004 | 1 | DDC | | Y | BU-65170DS3-130 | 590 |
| 5962-9306530HXC | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-65170DS3-110 | 590 |
| 5962-9306530HXC | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-65170DS3-130 | 590 |
| 5962-9306530HYA | K | 07/16/2004 | 1 | DDC | | Y | BU-65170DV3-150 | 590 |
| 5962-9306530HYA | K | 07/16/2004 | 1 | DDC | | Y | BU-65170DV3-140 | 590 |
| 5962-9306530HYA | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-65170DV3-140 | 590 |
| 5962-9306530HYA | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-65170DV3-150 | 590 |
| 5962-9306530HYC | K | 07/16/2004 | 1 | DDC | | Y | BU-65170DV3-130 | 590 |
| 5962-9306530HYC | K | 07/16/2004 | 1 | DDC | | Y | BU-65170DV3-110 | 590 |
| 5962-9306530HYC | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-65170DV3-130 | 590 |
| 5962-9306530HYC | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-65170DV3-110 | 590 |
| 5962-9306531HNA | K | 07/16/2004 | 1 | DDC | | Y | BU-65170DG6-150 | 590 |
| 5962-9306531HNA | K | 07/16/2004 | 1 | DDC | | Y | BU-65170DG6-140 | 590 |
| 5962-9306531HNA | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-65170DG6-150 | 590 |
| 5962-9306531HNA | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-65170DG6-140 | 590 |
| 5962-9306531HNC | K | 07/16/2004 | 1 | DDC | | Y | BU-65170DG6-110 | 590 |
| 5962-9306531HNC | K | 07/16/2004 | 1 | DDC | | Y | BU-65170DG6-130 | 590 |
| 5962-9306531HNC | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-65170DG6-110 | 590 |
| 5962-9306531HNC | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-65170DG6-130 | 590 |
| 5962-9306531HXA | K | 07/16/2004 | 1 | DDC | | Y | BU-65170DS6-150 | 590 |
| 5962-9306531HXA | K | 07/16/2004 | 1 | DDC | | Y | BU-65170DS6-140 | 590 |
| 5962-9306531HXA | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-65170DS6-150 | 590 |
| 5962-9306531HXA | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-65170DS6-140 | 590 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9306531HXC | K | 07/16/2004 | 1 | DDC | | Y | BU-65170DS6-110 | 590 |
| 5962-9306531HXC | K | 07/16/2004 | 1 | DDC | | Y | BU-65170DS6-130 | 590 |
| 5962-9306531HXC | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-65170DS6-130 | 590 |
| 5962-9306531HXC | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-65170DS6-110 | 590 |
| 5962-9306531HYA | K | 07/16/2004 | 1 | DDC | | Y | BU-65170DV6-140 | 590 |
| 5962-9306531HYA | K | 07/16/2004 | 1 | DDC | | Y | BU-65170DV6-150 | 590 |
| 5962-9306531HYA | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-65170DV6-140 | 590 |
| 5962-9306531HYA | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-65170DV6-150 | 590 |
| 5962-9306531HYC | K | 07/16/2004 | 1 | DDC | | Y | BU-65170DV6-110 | 590 |
| 5962-9306531HYC | K | 07/16/2004 | 1 | DDC | | Y | BU-65170DV6-130 | 590 |
| 5962-9306531HYC | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-65170DV6-110 | 590 |
| 5962-9306531HYC | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-65170DV6-130 | 590 |
| 5962-9306532HNA | K | 07/16/2004 | 1 | DDC | | Y | BU-61580DG3-150 | 590 |
| 5962-9306532HNA | K | 07/16/2004 | 1 | DDC | | Y | BU-61580DG3-140 | 590 |
| 5962-9306532HNA | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61580DG3-140 | 590 |
| 5962-9306532HNA | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61580DG3-150 | 590 |
| 5962-9306532HNC | K | 07/16/2004 | 1 | DDC | | Y | BU-61580DG3-130 | 590 |
| 5962-9306532HNC | K | 07/16/2004 | 1 | DDC | | Y | BU-61580DG3-110 | 590 |
| 5962-9306532HNC | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61580DG3-110 | 590 |
| 5962-9306532HNC | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61580DG3-130 | 590 |
| 5962-9306532HXA | K | 07/16/2004 | 1 | DDC | | Y | BU-61580DS3-140 | 590 |
| 5962-9306532HXA | K | 07/16/2004 | 1 | DDC | | Y | BU-61580DS3-150 | 590 |
| 5962-9306532HXA | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61580DS3-140 | 590 |
| 5962-9306532HXA | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61580DS3-150 | 590 |
| 5962-9306532HXC | K | 07/16/2004 | 1 | DDC | | Y | BU-61580DS3-130 | 590 |
| 5962-9306532HXC | K | 07/16/2004 | 1 | DDC | | Y | BU-61580DS3-110 | 590 |
| 5962-9306532HXC | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61580DS3-130 | 590 |
| 5962-9306532HXC | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61580DS3-110 | 590 |
| 5962-9306532HYA | K | 07/16/2004 | 1 | DDC | | Y | BU-61580DV3-140 | 590 |
| 5962-9306532HYA | K | 07/16/2004 | 1 | DDC | | Y | BU-61580DV3-150 | 590 |
| 5962-9306532HYA | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61580DV3-140 | 590 |
| 5962-9306532HYA | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61580DV3-150 | 590 |
| 5962-9306532HYC | K | 07/16/2004 | 1 | DDC | | Y | BU-61580DV3-130 | 590 |
| 5962-9306532HYC | K | 07/16/2004 | 1 | DDC | | Y | BU-61580DV3-110 | 590 |
| 5962-9306532HYC | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61580DV3-110 | 590 |
| 5962-9306532HYC | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61580DV3-130 | 590 |
| 5962-9306533HNA | K | 07/16/2004 | 1 | DDC | | Y | BU-61580DG6-140 | 590 |
| 5962-9306533HNA | K | 07/16/2004 | 1 | DDC | | Y | BU-61580DG6-150 | 590 |
| 5962-9306533HNA | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61580DG6-150 | 590 |
| 5962-9306533HNA | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61580DG6-140 | 590 |
| 5962-9306533HNC | K | 07/16/2004 | 1 | DDC | | Y | BU-61580DG6-130 | 590 |
| 5962-9306533HNC | K | 07/16/2004 | 1 | DDC | | Y | BU-61580DG6-110 | 590 |
| 5962-9306533HNC | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61580DG6-110 | 590 |
| 5962-9306533HNC | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61580DG6-130 | 590 |
| 5962-9306533HXA | K | 07/16/2004 | 1 | DDC | | Y | BU-61580DS6-140 | 590 |
| 5962-9306533HXA | K | 07/16/2004 | 1 | DDC | | Y | BU-61580DS6-150 | 590 |
| 5962-9306533HXA | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61580DS6-140 | 590 |
| 5962-9306533HXA | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61580DS6-150 | 590 |
| 5962-9306533HXC | K | 07/16/2004 | 1 | DDC | | Y | BU-61580DS6-130 | 590 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9306533HXC | K | 07/16/2004 | 1 | DDC | | Y | BU-61580DS6-110 | 590 |
| 5962-9306533HXC | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61580DS6-110 | 590 |
| 5962-9306533HXC | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61580DS6-130 | 590 |
| 5962-9306533HYA | K | 07/16/2004 | 1 | DDC | | Y | BU-61580DV6-140 | 590 |
| 5962-9306533HYA | K | 07/16/2004 | 1 | DDC | | Y | BU-61580DV6-150 | 590 |
| 5962-9306533HYA | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61580DV6-150 | 590 |
| 5962-9306533HYA | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61580DV6-140 | 590 |
| 5962-9306533HYC | K | 07/16/2004 | 1 | DDC | | Y | BU-61580DV6-110 | 590 |
| 5962-9306533HYC | K | 07/16/2004 | 1 | DDC | | Y | BU-61580DV6-130 | 590 |
| 5962-9306533HYC | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61580DV6-130 | 590 |
| 5962-9306533HYC | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61580DV6-110 | 590 |
| 5962-9306534HNA | K | 07/16/2004 | 1 | DDC | | Y | BU-65171DG3-150 | 590 |
| 5962-9306534HNA | K | 07/16/2004 | 1 | DDC | | Y | BU-65171DG3-140 | 590 |
| 5962-9306534HNA | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-65171DG3-140 | 590 |
| 5962-9306534HNA | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-65171DG3-150 | 590 |
| 5962-9306534HNC | K | 07/16/2004 | 1 | DDC | | Y | BU-65171DG3-110 | 590 |
| 5962-9306534HNC | K | 07/16/2004 | 1 | DDC | | Y | BU-65171DG3-130 | 590 |
| 5962-9306534HNC | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-65171DG3-130 | 590 |
| 5962-9306534HNC | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-65171DG3-110 | 590 |
| 5962-9306534HXA | K | 07/16/2004 | 1 | DDC | | Y | BU-65171DS3-150 | 590 |
| 5962-9306534HXA | K | 07/16/2004 | 1 | DDC | | Y | BU-65171DS3-140 | 590 |
| 5962-9306534HXA | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-65171DS3-140 | 590 |
| 5962-9306534HXA | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-65171DS3-150 | 590 |
| 5962-9306534HXC | K | 07/16/2004 | 1 | DDC | | Y | BU-65171DS3-130 | 590 |
| 5962-9306534HXC | K | 07/16/2004 | 1 | DDC | | Y | BU-65171DS3-110 | 590 |
| 5962-9306534HXC | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-65171DS3-110 | 590 |
| 5962-9306534HXC | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-65171DS3-130 | 590 |
| 5962-9306534HYA | K | 07/16/2004 | 1 | DDC | | Y | BU-65171DV3-150 | 590 |
| 5962-9306534HYA | K | 07/16/2004 | 1 | DDC | | Y | BU-65171DV3-140 | 590 |
| 5962-9306534HYA | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-65171DV3-150 | 590 |
| 5962-9306534HYA | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-65171DV3-140 | 590 |
| 5962-9306534HYC | K | 07/16/2004 | 1 | DDC | | Y | BU-65171DV3-130 | 590 |
| 5962-9306534HYC | K | 07/16/2004 | 1 | DDC | | Y | BU-65171DV3-110 | 590 |
| 5962-9306534HYC | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-65171DV3-130 | 590 |
| 5962-9306534HYC | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-65171DV3-110 | 590 |
| 5962-9306535HNA | K | 07/16/2004 | 1 | DDC | | Y | BU-65171DG6-150 | 590 |
| 5962-9306535HNA | K | 07/16/2004 | 1 | DDC | | Y | BU-65171DG6-140 | 590 |
| 5962-9306535HNA | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-65171DG6-150 | 590 |
| 5962-9306535HNA | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-65171DG6-140 | 590 |
| 5962-9306535HNC | K | 07/16/2004 | 1 | DDC | | Y | BU-65171DG6-130 | 590 |
| 5962-9306535HNC | K | 07/16/2004 | 1 | DDC | | Y | BU-65171DG6-110 | 590 |
| 5962-9306535HNC | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-65171DG6-110 | 590 |
| 5962-9306535HNC | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-65171DG6-130 | 590 |
| 5962-9306535HXA | K | 07/16/2004 | 1 | DDC | | Y | BU-65171DS6-140 | 590 |
| 5962-9306535HXA | K | 07/16/2004 | 1 | DDC | | Y | BU-65171DS6-150 | 590 |
| 5962-9306535HXA | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-65171DS6-150 | 590 |
| 5962-9306535HXA | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-65171DS6-140 | 590 |
| 5962-9306535HXC | K | 07/16/2004 | 1 | DDC | | Y | BU-65171DS6-130 | 590 |
| 5962-9306535HXC | K | 07/16/2004 | 1 | DDC | | Y | BU-65171DS6-110 | 590 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9306535HXC | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-65171DS6-130 | 590 |
| 5962-9306535HXC | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-65171DS6-110 | 590 |
| 5962-9306535HYA | K | 07/16/2004 | 1 | DDC | | Y | BU-65171DV6-150 | 590 |
| 5962-9306535HYA | K | 07/16/2004 | 1 | DDC | | Y | BU-65171DV6-140 | 590 |
| 5962-9306535HYA | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-65171DV6-140 | 590 |
| 5962-9306535HYA | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-65171DV6-150 | 590 |
| 5962-9306535HYC | K | 07/16/2004 | 1 | DDC | | Y | BU-65171DV6-110 | 590 |
| 5962-9306535HYC | K | 07/16/2004 | 1 | DDC | | Y | BU-65171DV6-130 | 590 |
| 5962-9306535HYC | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-65171DV6-110 | 590 |
| 5962-9306535HYC | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-65171DV6-130 | 590 |
| 5962-9306536HNA | K | 07/16/2004 | 1 | DDC | | Y | BU-61581DG3-140 | 590 |
| 5962-9306536HNA | K | 07/16/2004 | 1 | DDC | | Y | BU-61581DG3-150 | 590 |
| 5962-9306536HNA | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61581DG3-150 | 590 |
| 5962-9306536HNA | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61581DG3-140 | 590 |
| 5962-9306536HNC | K | 07/16/2004 | 1 | DDC | | Y | BU-61581DG3-110 | 590 |
| 5962-9306536HNC | K | 07/16/2004 | 1 | DDC | | Y | BU-61581DG3-130 | 590 |
| 5962-9306536HNC | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61581DG3-130 | 590 |
| 5962-9306536HNC | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61581DG3-110 | 590 |
| 5962-9306536HXA | K | 07/16/2004 | 1 | DDC | | Y | BU-61581DS3-150 | 590 |
| 5962-9306536HXA | K | 07/16/2004 | 1 | DDC | | Y | BU-61581DS3-140 | 590 |
| 5962-9306536HXA | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61581DS3-150 | 590 |
| 5962-9306536HXA | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61581DS3-140 | 590 |
| 5962-9306536HXC | K | 07/16/2004 | 1 | DDC | | Y | BU-61581DS3-130 | 590 |
| 5962-9306536HXC | K | 07/16/2004 | 1 | DDC | | Y | BU-61581DS3-110 | 590 |
| 5962-9306536HXC | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61581DS3-130 | 590 |
| 5962-9306536HXC | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61581DS3-110 | 590 |
| 5962-9306536HYA | K | 07/16/2004 | 1 | DDC | | Y | BU-61581DV3-150 | 590 |
| 5962-9306536HYA | K | 07/16/2004 | 1 | DDC | | Y | BU-61581DV3-140 | 590 |
| 5962-9306536HYA | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61581DV3-150 | 590 |
| 5962-9306536HYA | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61581DV3-140 | 590 |
| 5962-9306536HYC | K | 07/16/2004 | 1 | DDC | | Y | BU-61581DV3-110 | 590 |
| 5962-9306536HYC | K | 07/16/2004 | 1 | DDC | | Y | BU-61581DV3-130 | 590 |
| 5962-9306536HYC | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61581DV3-110 | 590 |
| 5962-9306536HYC | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61581DV3-130 | 590 |
| 5962-9306537HNA | K | 07/16/2004 | 1 | DDC | | Y | BU-61581DG6-150 | 590 |
| 5962-9306537HNA | K | 07/16/2004 | 1 | DDC | | Y | BU-61581DG6-140 | 590 |
| 5962-9306537HNA | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61581DG6-140 | 590 |
| 5962-9306537HNA | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61581DG6-150 | 590 |
| 5962-9306537HNC | K | 07/16/2004 | 1 | DDC | | Y | BU-61581DG6-110 | 590 |
| 5962-9306537HNC | K | 07/16/2004 | 1 | DDC | | Y | BU-61581DG6-130 | 590 |
| 5962-9306537HNC | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61581DG6-130 | 590 |
| 5962-9306537HNC | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61581DG6-110 | 590 |
| 5962-9306537HXA | K | 07/16/2004 | 1 | DDC | | Y | BU-61581DS6-140 | 590 |
| 5962-9306537HXA | K | 07/16/2004 | 1 | DDC | | Y | BU-61581DS6-150 | 590 |
| 5962-9306537HXA | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61581DS6-140 | 590 |
| 5962-9306537HXA | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61581DS6-150 | 590 |
| 5962-9306537HXC | K | 07/16/2004 | 1 | DDC | | Y | BU-61581DS6-110 | 590 |
| 5962-9306537HXC | K | 07/16/2004 | 1 | DDC | | Y | BU-61581DS6-130 | 590 |
| 5962-9306537HXC | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61581DS6-130 | 590 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9306537HXC | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61581DS6-110 | 590 |
| 5962-9306537HYA | K | 07/16/2004 | 1 | DDC | | Y | BU-61581DV6-150 | 590 |
| 5962-9306537HYA | K | 07/16/2004 | 1 | DDC | | Y | BU-61581DV6-140 | 590 |
| 5962-9306537HYA | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61581DV6-150 | 590 |
| 5962-9306537HYA | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61581DV6-140 | 590 |
| 5962-9306537HYC | K | 07/16/2004 | 1 | DDC | | Y | BU-61581DV6-130 | 590 |
| 5962-9306537HYC | K | 07/16/2004 | 1 | DDC | | Y | BU-61581DV6-110 | 590 |
| 5962-9306537HYC | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61581DV6-130 | 590 |
| 5962-9306537HYC | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61581DV6-110 | 590 |
| 5962-9306538HNA | K | 07/16/2004 | 1 | DDC | | Y | BU-61585DG3-140 | 590 |
| 5962-9306538HNA | K | 07/16/2004 | 1 | DDC | | Y | BU-61585DG3-150 | 590 |
| 5962-9306538HNA | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61585DG3-140 | 590 |
| 5962-9306538HNA | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61585DG3-150 | 590 |
| 5962-9306538HNC | K | 07/16/2004 | 1 | DDC | | Y | BU-61585DG3-130 | 590 |
| 5962-9306538HNC | K | 07/16/2004 | 1 | DDC | | Y | BU-61585DG3-110 | 590 |
| 5962-9306538HNC | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61585DG3-130 | 590 |
| 5962-9306538HNC | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61585DG3-110 | 590 |
| 5962-9306538HXA | K | 07/16/2004 | 1 | DDC | | Y | BU-61585DS3-150 | 590 |
| 5962-9306538HXA | K | 07/16/2004 | 1 | DDC | | Y | BU-61585DS3-140 | 590 |
| 5962-9306538HXA | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61585DS3-140 | 590 |
| 5962-9306538HXA | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61585DS3-150 | 590 |
| 5962-9306538HXC | K | 07/16/2004 | 1 | DDC | | Y | BU-61585DS3-110 | 590 |
| 5962-9306538HXC | K | 07/16/2004 | 1 | DDC | | Y | BU-61585DS3-130 | 590 |
| 5962-9306538HXC | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61585DS3-110 | 590 |
| 5962-9306538HXC | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61585DS3-130 | 590 |
| 5962-9306538HYA | K | 07/16/2004 | 1 | DDC | | Y | BU-61585DV3-150 | 590 |
| 5962-9306538HYA | K | 07/16/2004 | 1 | DDC | | Y | BU-61585DV3-140 | 590 |
| 5962-9306538HYA | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61585DV3-140 | 590 |
| 5962-9306538HYA | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61585DV3-150 | 590 |
| 5962-9306538HYC | K | 07/16/2004 | 1 | DDC | | Y | BU-61585DV3-110 | 590 |
| 5962-9306538HYC | K | 07/16/2004 | 1 | DDC | | Y | BU-61585DV3-130 | 590 |
| 5962-9306538HYC | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61585DV3-110 | 590 |
| 5962-9306538HYC | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61585DV3-130 | 590 |
| 5962-9306539HNA | K | 07/16/2004 | 1 | DDC | | Y | BU-61585DG6-150 | 590 |
| 5962-9306539HNA | K | 07/16/2004 | 1 | DDC | | Y | BU-61585DG6-140 | 590 |
| 5962-9306539HNA | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61585DG6-150 | 590 |
| 5962-9306539HNA | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61585DG6-140 | 590 |
| 5962-9306539HNC | K | 07/16/2004 | 1 | DDC | | Y | BU-61585DG6-110 | 590 |
| 5962-9306539HNC | K | 07/16/2004 | 1 | DDC | | Y | BU-61585DG6-130 | 590 |
| 5962-9306539HNC | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61585DG6-110 | 590 |
| 5962-9306539HNC | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61585DG6-130 | 590 |
| 5962-9306539HXA | K | 07/16/2004 | 1 | DDC | | Y | BU-61585DS6-150 | 590 |
| 5962-9306539HXA | K | 07/16/2004 | 1 | DDC | | Y | BU-61585DS6-140 | 590 |
| 5962-9306539HXA | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61585DS6-150 | 590 |
| 5962-9306539HXA | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61585DS6-140 | 590 |
| 5962-9306539HXC | K | 07/16/2004 | 1 | DDC | | Y | BU-61585DS6-130 | 590 |
| 5962-9306539HXC | K | 07/16/2004 | 1 | DDC | | Y | BU-61585DS6-110 | 590 |
| 5962-9306539HXC | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61585DS6-130 | 590 |
| 5962-9306539HXC | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61585DS6-110 | 590 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9306539HYA | K | 07/16/2004 | 1 | DDC | | Y | BU-61585DV6-150 | 590 |
| 5962-9306539HYA | K | 07/16/2004 | 1 | DDC | | Y | BU-61585DV6-140 | 590 |
| 5962-9306539HYA | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61585DV6-140 | 590 |
| 5962-9306539HYA | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61585DV6-150 | 590 |
| 5962-9306539HYC | K | 07/16/2004 | 1 | DDC | | Y | BU-61585DV6-110 | 590 |
| 5962-9306539HYC | K | 07/16/2004 | 1 | DDC | | Y | BU-61585DV6-130 | 590 |
| 5962-9306539HYC | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61585DV6-130 | 590 |
| 5962-9306539HYC | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61585DV6-110 | 590 |
| 5962-9306540HNA | K | 07/16/2004 | 1 | DDC | | Y | BU-61586DG3-150 | 590 |
| 5962-9306540HNA | K | 07/16/2004 | 1 | DDC | | Y | BU-61586DG3-140 | 590 |
| 5962-9306540HNA | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61586DG3-140 | 590 |
| 5962-9306540HNA | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61586DG3-150 | 590 |
| 5962-9306540HNC | K | 07/16/2004 | 1 | DDC | | Y | BU-61586DG3-130 | 590 |
| 5962-9306540HNC | K | 07/16/2004 | 1 | DDC | | Y | BU-61586DG3-110 | 590 |
| 5962-9306540HNC | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61586DG3-130 | 590 |
| 5962-9306540HNC | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61586DG3-110 | 590 |
| 5962-9306540HXA | K | 07/16/2004 | 1 | DDC | | Y | BU-61586DS3-150 | 590 |
| 5962-9306540HXA | K | 07/16/2004 | 1 | DDC | | Y | BU-61586DS3-140 | 590 |
| 5962-9306540HXA | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61586DS3-150 | 590 |
| 5962-9306540HXA | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61586DS3-140 | 590 |
| 5962-9306540HXC | K | 07/16/2004 | 1 | DDC | | Y | BU-61586DS3-110 | 590 |
| 5962-9306540HXC | K | 07/16/2004 | 1 | DDC | | Y | BU-61586DS3-130 | 590 |
| 5962-9306540HXC | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61586DS3-130 | 590 |
| 5962-9306540HXC | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61586DS3-110 | 590 |
| 5962-9306540HYA | K | 07/16/2004 | 1 | DDC | | Y | BU-61586DV3-150 | 590 |
| 5962-9306540HYA | K | 07/16/2004 | 1 | DDC | | Y | BU-61586DV3-140 | 590 |
| 5962-9306540HYA | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61586DV3-150 | 590 |
| 5962-9306540HYA | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61586DV3-140 | 590 |
| 5962-9306540HYC | K | 07/16/2004 | 1 | DDC | | Y | BU-61586DV3-110 | 590 |
| 5962-9306540HYC | K | 07/16/2004 | 1 | DDC | | Y | BU-61586DV3-130 | 590 |
| 5962-9306540HYC | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61586DV3-110 | 590 |
| 5962-9306540HYC | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61586DV3-130 | 590 |
| 5962-9306541HNA | K | 07/16/2004 | 1 | DDC | | Y | BU-61586DG6-140 | 590 |
| 5962-9306541HNA | K | 07/16/2004 | 1 | DDC | | Y | BU-61586DG6-150 | 590 |
| 5962-9306541HNA | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61586DG6-140 | 590 |
| 5962-9306541HNA | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61586DG6-150 | 590 |
| 5962-9306541HNC | K | 07/16/2004 | 1 | DDC | | Y | BU-61586DG6-110 | 590 |
| 5962-9306541HNC | K | 07/16/2004 | 1 | DDC | | Y | BU-61586DG6-130 | 590 |
| 5962-9306541HNC | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61586DG6-130 | 590 |
| 5962-9306541HNC | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61586DG6-110 | 590 |
| 5962-9306541HXA | K | 07/16/2004 | 1 | DDC | | Y | BU-61586DS6-150 | 590 |
| 5962-9306541HXA | K | 07/16/2004 | 1 | DDC | | Y | BU-61586DS6-140 | 590 |
| 5962-9306541HXA | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61586DS6-150 | 590 |
| 5962-9306541HXA | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61586DS6-140 | 590 |
| 5962-9306541HXC | K | 07/16/2004 | 1 | DDC | | Y | BU-61586DS6-110 | 590 |
| 5962-9306541HXC | K | 07/16/2004 | 1 | DDC | | Y | BU-61586DS6-130 | 590 |
| 5962-9306541HXC | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61586DS6-130 | 590 |
| 5962-9306541HXC | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61586DS6-110 | 590 |
| 5962-9306541HYA | K | 07/16/2004 | 1 | DDC | | Y | BU-61586DV6-150 | 590 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9306541HYA | K | 07/16/2004 | 1 | DDC | | Y | BU-61586DV6-140 | 590 |
| 5962-9306541HYA | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61586DV6-140 | 590 |
| 5962-9306541HYA | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61586DV6-150 | 590 |
| 5962-9306541HYC | K | 07/16/2004 | 1 | DDC | | Y | BU-61586DV6-130 | 590 |
| 5962-9306541HYC | K | 07/16/2004 | 1 | DDC | | Y | BU-61586DV6-110 | 590 |
| 5962-9306541HYC | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61586DV6-130 | 590 |
| 5962-9306541HYC | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61586DV6-110 | 590 |
| 5962-9306542HMA | K | 07/16/2004 | 1 | DDC | | Y | BU-61588CG3-150 | 590 |
| 5962-9306542HMA | K | 07/16/2004 | 1 | DDC | | Y | BU-61588CG3-140 | 590 |
| 5962-9306542HMA | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61588CG3-150 | 590 |
| 5962-9306542HMA | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61588CG3-140 | 590 |
| 5962-9306542HMC | K | 07/16/2004 | 1 | DDC | | Y | BU-61588CG3-110 | 590 |
| 5962-9306542HMC | K | 07/16/2004 | 1 | DDC | | Y | BU-61588CG3-130 | 590 |
| 5962-9306542HMC | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61588CG3-130 | 590 |
| 5962-9306542HMC | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61588CG3-110 | 590 |
| 5962-9306542HTA | K | 07/16/2004 | 1 | DDC | | Y | BU-61588CF3-150 | 590 |
| 5962-9306542HTA | K | 07/16/2004 | 1 | DDC | | Y | BU-61588CF3-140 | 590 |
| 5962-9306542HTA | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61588CF3-150 | 590 |
| 5962-9306542HTA | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61588CF3-140 | 590 |
| 5962-9306542HTC | K | 07/16/2004 | 1 | DDC | | Y | BU-61588CF3-130 | 590 |
| 5962-9306542HTC | K | 07/16/2004 | 1 | DDC | | Y | BU-61588CF3-110 | 590 |
| 5962-9306542HTC | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61588CF3-110 | 590 |
| 5962-9306542HTC | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61588CF3-130 | 590 |
| 5962-9306542HUA | K | 07/16/2004 | 1 | DDC | | Y | BU-61588CP3-150 | 590 |
| 5962-9306542HUA | K | 07/16/2004 | 1 | DDC | | Y | BU-61588CP3-140 | 590 |
| 5962-9306542HUA | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61588CP3-150 | 590 |
| 5962-9306542HUA | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61588CP3-140 | 590 |
| 5962-9306542HUC | K | 07/16/2004 | 1 | DDC | | Y | BU-61588CP3-130 | 590 |
| 5962-9306542HUC | K | 07/16/2004 | 1 | DDC | | Y | BU-61588CP3-110 | 590 |
| 5962-9306542HUC | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61588CP3-130 | 590 |
| 5962-9306542HUC | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61588CP3-110 | 590 |
| 5962-9306543HMA | K | 07/16/2004 | 1 | DDC | | Y | BU-65178CG3-150 | 590 |
| 5962-9306543HMA | K | 07/16/2004 | 1 | DDC | | Y | BU-65178CG3-140 | 590 |
| 5962-9306543HMA | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-65178CG3-140 | 590 |
| 5962-9306543HMA | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-65178CG3-150 | 590 |
| 5962-9306543HMC | K | 07/16/2004 | 1 | DDC | | Y | BU-65178CG3-130 | 590 |
| 5962-9306543HMC | K | 07/16/2004 | 1 | DDC | | Y | BU-65178CG3-110 | 590 |
| 5962-9306543HMC | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-65178CG3-130 | 590 |
| 5962-9306543HMC | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-65178CG3-110 | 590 |
| 5962-9306543HTA | K | 07/16/2004 | 1 | DDC | | Y | BU-65178CF3-150 | 590 |
| 5962-9306543HTA | K | 07/16/2004 | 1 | DDC | | Y | BU-65178CF3-140 | 590 |
| 5962-9306543HTA | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-65178CF3-150 | 590 |
| 5962-9306543HTA | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-65178CF3-140 | 590 |
| 5962-9306543HTC | K | 07/16/2004 | 1 | DDC | | Y | BU-65178CF3-130 | 590 |
| 5962-9306543HTC | K | 07/16/2004 | 1 | DDC | | Y | BU-65178CF3-110 | 590 |
| 5962-9306543HTC | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-65178CF3-130 | 590 |
| 5962-9306543HTC | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-65178CF3-110 | 590 |
| 5962-9306543HUA | K | 07/16/2004 | 1 | DDC | | Y | BU-65178CP3-140 | 590 |
| 5962-9306543HUA | K | 07/16/2004 | 1 | DDC | | Y | BU-65178CP3-150 | 590 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9306543HUA | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-65178CP3-150 | 590 |
| 5962-9306543HUA | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-65178CP3-140 | 590 |
| 5962-9306543HUC | K | 07/16/2004 | 1 | DDC | | Y | BU-65178CP3-130 | 590 |
| 5962-9306543HUC | K | 07/16/2004 | 1 | DDC | | Y | BU-65178CP3-110 | 590 |
| 5962-9306543HUC | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-65178CP3-130 | 590 |
| 5962-9306543HUC | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-65178CP3-110 | 590 |
| 5962-9306544HMA | K | 07/16/2004 | 1 | DDC | | Y | BU-65179CG3-150 | 590 |
| 5962-9306544HMA | K | 07/16/2004 | 1 | DDC | | Y | BU-65179CG3-140 | 590 |
| 5962-9306544HMA | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-65179CG3-150 | 590 |
| 5962-9306544HMA | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-65179CG3-140 | 590 |
| 5962-9306544HMC | K | 07/16/2004 | 1 | DDC | | Y | BU-65179CG3-130 | 590 |
| 5962-9306544HMC | K | 07/16/2004 | 1 | DDC | | Y | BU-65179CG3-110 | 590 |
| 5962-9306544HMC | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-65179CG3-130 | 590 |
| 5962-9306544HMC | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-65179CG3-110 | 590 |
| 5962-9306544HTA | K | 07/16/2004 | 1 | DDC | | Y | BU-65179CF3-140 | 590 |
| 5962-9306544HTA | K | 07/16/2004 | 1 | DDC | | Y | BU-65179CF3-150 | 590 |
| 5962-9306544HTA | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-65179CF3-150 | 590 |
| 5962-9306544HTA | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-65179CF3-140 | 590 |
| 5962-9306544HTC | K | 07/16/2004 | 1 | DDC | | Y | BU-65179CF3-130 | 590 |
| 5962-9306544HTC | K | 07/16/2004 | 1 | DDC | | Y | BU-65179CF3-110 | 590 |
| 5962-9306544HTC | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-65179CF3-130 | 590 |
| 5962-9306544HTC | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-65179CF3-110 | 590 |
| 5962-9306544HUA | K | 07/16/2004 | 1 | DDC | | Y | BU-65179CP3-150 | 590 |
| 5962-9306544HUA | K | 07/16/2004 | 1 | DDC | | Y | BU-65179CP3-140 | 590 |
| 5962-9306544HUA | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-65179CP3-140 | 590 |
| 5962-9306544HUA | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-65179CP3-150 | 590 |
| 5962-9306544HUC | K | 07/16/2004 | 1 | DDC | | Y | BU-65179CP3-110 | 590 |
| 5962-9306544HUC | K | 07/16/2004 | 1 | DDC | | Y | BU-65179CP3-130 | 590 |
| 5962-9306544HUC | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-65179CP3-110 | 590 |
| 5962-9306544HUC | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-65179CP3-130 | 590 |
| 5962-9306545HMA | K | 07/16/2004 | 1 | DDC | | Y | BU-61688CG3-140 | 590 |
| 5962-9306545HMA | K | 07/16/2004 | 1 | DDC | | Y | BU-61688CG3-150 | 590 |
| 5962-9306545HMA | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61688CG3-140 | 590 |
| 5962-9306545HMA | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61688CG3-150 | 590 |
| 5962-9306545HMC | K | 07/16/2004 | 1 | DDC | | Y | BU-61688CG3-110 | 590 |
| 5962-9306545HMC | K | 07/16/2004 | 1 | DDC | | Y | BU-61688CG3-130 | 590 |
| 5962-9306545HMC | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61688CG3-130 | 590 |
| 5962-9306545HMC | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61688CG3-110 | 590 |
| 5962-9306545HTA | K | 07/16/2004 | 1 | DDC | | Y | BU-61688CF3-140 | 590 |
| 5962-9306545HTA | K | 07/16/2004 | 1 | DDC | | Y | BU-61688CF3-150 | 590 |
| 5962-9306545HTA | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61688CF3-150 | 590 |
| 5962-9306545HTA | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61688CF3-140 | 590 |
| 5962-9306545HTC | K | 07/16/2004 | 1 | DDC | | Y | BU-61688CF3-130 | 590 |
| 5962-9306545HTC | K | 07/16/2004 | 1 | DDC | | Y | BU-61688CF3-110 | 590 |
| 5962-9306545HTC | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61688CF3-130 | 590 |
| 5962-9306545HTC | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61688CF3-110 | 590 |
| 5962-9306545HUA | K | 07/16/2004 | 1 | DDC | | Y | BU-61688CP3-140 | 590 |
| 5962-9306545HUA | K | 07/16/2004 | 1 | DDC | | Y | BU-61688CP3-150 | 590 |
| 5962-9306545HUA | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61688CP3-140 | 590 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9306545HUA | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61688CP3-150 | 590 |
| 5962-9306545HUC | K | 07/16/2004 | 1 | DDC | | Y | BU-61688CP3-130 | 590 |
| 5962-9306545HUC | K | 07/16/2004 | 1 | DDC | | Y | BU-61688CP3-110 | 590 |
| 5962-9306545HUC | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61688CP3-110 | 590 |
| 5962-9306545HUC | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61688CP3-130 | 590 |
| 5962-9306546HMA | K | 07/16/2004 | 1 | DDC | | Y | BU-61689CG3-140 | 590 |
| 5962-9306546HMA | K | 07/16/2004 | 1 | DDC | | Y | BU-61689CG3-150 | 590 |
| 5962-9306546HMA | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61689CG3-150 | 590 |
| 5962-9306546HMA | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61689CG3-140 | 590 |
| 5962-9306546HMC | K | 07/16/2004 | 1 | DDC | | Y | BU-61689CG3-130 | 590 |
| 5962-9306546HMC | K | 07/16/2004 | 1 | DDC | | Y | BU-61689CG3-110 | 590 |
| 5962-9306546HMC | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61689CG3-110 | 590 |
| 5962-9306546HMC | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61689CG3-130 | 590 |
| 5962-9306546HTA | K | 07/16/2004 | 1 | DDC | | Y | BU-61689CF3-140 | 590 |
| 5962-9306546HTA | K | 07/16/2004 | 1 | DDC | | Y | BU-61689CF3-150 | 590 |
| 5962-9306546HTA | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61689CF3-140 | 590 |
| 5962-9306546HTA | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61689CF3-150 | 590 |
| 5962-9306546HTC | K | 07/16/2004 | 1 | DDC | | Y | BU-61689CF3-110 | 590 |
| 5962-9306546HTC | K | 07/16/2004 | 1 | DDC | | Y | BU-61689CF3-130 | 590 |
| 5962-9306546HTC | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61689CF3-130 | 590 |
| 5962-9306546HTC | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61689CF3-110 | 590 |
| 5962-9306546HUA | K | 07/16/2004 | 1 | DDC | | Y | BU-61689CP3-150 | 590 |
| 5962-9306546HUA | K | 07/16/2004 | 1 | DDC | | Y | BU-61689CP3-140 | 590 |
| 5962-9306546HUA | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61689CP3-150 | 590 |
| 5962-9306546HUA | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61689CP3-140 | 590 |
| 5962-9306546HUC | K | 07/16/2004 | 1 | DDC | | Y | BU-61689CP3-110 | 590 |
| 5962-9306546HUC | K | 07/16/2004 | 1 | DDC | | Y | BU-61689CP3-130 | 590 |
| 5962-9306546HUC | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61689CP3-130 | 590 |
| 5962-9306546HUC | K | 07/16/2004 | 1 | DDC IRELAND | | Y | BU-61689CP3-110 | 590 |
| 5962-9306801HXA | C | 04/26/2000 | 1 | INTERPOINT | | Y | MTR2805S/883 | 594 |
| 5962-9306801HXC | C | 04/26/2000 | 1 | INTERPOINT | | Y | MTR2805S/883 | 594 |
| 5962-9306801HZA | C | 04/26/2000 | 1 | INTERPOINT | | Y | MTR2805SF/883 | 594 |
| 5962-9306801HZC | C | 04/26/2000 | 1 | INTERPOINT | | Y | MTR2805SF/883 | 594 |
| 5962-9306802HXA | C | 04/26/2000 | 1 | INTERPOINT | | Y | SMTR2805S/HO | 594 |
| 5962-9306802HXC | C | 04/26/2000 | 1 | INTERPOINT | | Y | SMTR2805S/HO | 594 |
| 5962L9306802HXA | C | 04/26/2000 | 1 | INTERPOINT | | Y | SMTR2805S/HL | 594 |
| 5962L9306802HXC | C | 04/26/2000 | 1 | INTERPOINT | | Y | SMTR2805S/HL | 594 |
| 5962L9306802KXA | C | 04/26/2000 | 1 | INTERPOINT | | Y | SMTR2805S/KL | 594 |
| 5962L9306802KXC | C | 04/26/2000 | 1 | INTERPOINT | | Y | SMTR2805S/KL | 594 |
| 5962R9306802HXA | C | 04/26/2000 | 1 | INTERPOINT | | Y | SMTR2805S/HR | 594 |
| 5962R9306802HXC | C | 04/26/2000 | 1 | INTERPOINT | | Y | SMTR2805S/HR | 594 |
| 5962R9306802KXA | C | 04/26/2000 | 1 | INTERPOINT | | Y | SMTR2805S/KR | 594 |
| 5962R9306802KXC | C | 04/26/2000 | 1 | INTERPOINT | | Y | SMTR2805S/KR | 594 |
| 5962-9306802HZA | C | 04/26/2000 | 1 | INTERPOINT | | Y | SMTR2805SF/HO | 594 |
| 5962-9306802HZC | C | 04/26/2000 | 1 | INTERPOINT | | Y | SMTR2805SF/HO | 594 |
| 5962L9306802HZA | C | 04/26/2000 | 1 | INTERPOINT | | Y | SMTR2805SF/HL | 594 |
| 5962L9306802HZC | C | 04/26/2000 | 1 | INTERPOINT | | Y | SMTR2805SF/HL | 594 |
| 5962L9306802KZA | C | 04/26/2000 | 1 | INTERPOINT | | Y | SMTR2805SF/KL | 594 |
| 5962L9306802KZC | C | 04/26/2000 | 1 | INTERPOINT | | Y | SMTR2805SF/KL | 594 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962R9306802HZA | C | 04/26/2000 | 1 | INTERPOINT | | Y | SMTR2805SF/HR | 594 |
| 5962R9306802HZC | C | 04/26/2000 | 1 | INTERPOINT | | Y | SMTR2805SF/HR | 594 |
| 5962R9306802KZA | C | 04/26/2000 | 1 | INTERPOINT | | Y | SMTR2805SF/KR | 594 |
| 5962R9306802KZC | C | 04/26/2000 | 1 | INTERPOINT | | Y | SMTR2805SF/KR | 594 |
| 5962-9306901HXA | D | 06/21/2000 | 1 | INTERPOINT | | Y | MTR2812S/883 | 594 |
| 5962-9306901HXC | D | 06/21/2000 | 1 | INTERPOINT | | Y | MTR2812S/883 | 594 |
| 5962-9306901HZA | D | 06/21/2000 | 1 | INTERPOINT | | Y | MTR2812SF/883 | 594 |
| 5962-9306901HZC | D | 06/21/2000 | 1 | INTERPOINT | | Y | MTR2812SF/883 | 594 |
| 5962-9306902HXA | D | 06/21/2000 | 1 | INTERPOINT | | Y | SMTR2812S/HO | 594 |
| 5962-9306902HXC | D | 06/21/2000 | 1 | INTERPOINT | | Y | SMTR2812S/HO | 594 |
| 5962L9306902HXA | D | 06/21/2000 | 1 | INTERPOINT | | Y | SMTR2812S/HL | 594 |
| 5962L9306902HXC | D | 06/21/2000 | 1 | INTERPOINT | | Y | SMTR2812S/HL | 594 |
| 5962L9306902KXA | D | 06/21/2000 | 1 | INTERPOINT | | Y | SMTR2812S/KL | 594 |
| 5962L9306902KXC | D | 06/21/2000 | 1 | INTERPOINT | | Y | SMTR2812S/KL | 594 |
| 5962R9306902HXA | D | 06/21/2000 | 1 | INTERPOINT | | Y | SMTR2812S/HR | 594 |
| 5962R9306902HXC | D | 06/21/2000 | 1 | INTERPOINT | | Y | SMTR2812S/HR | 594 |
| 5962R9306902KXA | D | 06/21/2000 | 1 | INTERPOINT | | Y | SMTR2812S/KR | 594 |
| 5962R9306902KXC | D | 06/21/2000 | 1 | INTERPOINT | | Y | SMTR2812S/KR | 594 |
| 5962-9306902HZA | D | 06/21/2000 | 1 | INTERPOINT | | Y | SMTR2812SF/HO | 594 |
| 5962-9306902HZC | D | 06/21/2000 | 1 | INTERPOINT | | Y | SMTR2812SF/HO | 594 |
| 5962L9306902HZA | D | 06/21/2000 | 1 | INTERPOINT | | Y | SMTR2812SF/HL | 594 |
| 5962L9306902HZC | D | 06/21/2000 | 1 | INTERPOINT | | Y | SMTR2812SF/HL | 594 |
| 5962L9306902KZA | D | 06/21/2000 | 1 | INTERPOINT | | Y | SMTR2812SF/KL | 594 |
| 5962L9306902KZC | D | 06/21/2000 | 1 | INTERPOINT | | Y | SMTR2812SF/KL | 594 |
| 5962R9306902HZA | D | 06/21/2000 | 1 | INTERPOINT | | Y | SMTR2812SF/HR | 594 |
| 5962R9306902HZC | D | 06/21/2000 | 1 | INTERPOINT | | Y | SMTR2812SF/HR | 594 |
| 5962R9306902KZA | D | 06/21/2000 | 1 | INTERPOINT | | Y | SMTR2812SF/KR | 594 |
| 5962R9306902KZC | D | 06/21/2000 | 1 | INTERPOINT | | Y | SMTR2812SF/KR | 594 |
| 5962-9307001HXA | C | 06/22/2000 | 1 | INTERPOINT | | Y | MTR2815S/883 | 594 |
| 5962-9307001HXC | C | 06/22/2000 | 1 | INTERPOINT | | Y | MTR2815S/883 | 594 |
| 5962-9307001HZA | C | 06/22/2000 | 1 | INTERPOINT | | Y | MTR2815SF/883 | 594 |
| 5962-9307001HZC | C | 06/22/2000 | 1 | INTERPOINT | | Y | MTR2815SF/883 | 594 |
| 5962-9307002HXA | C | 06/22/2000 | 1 | INTERPOINT | | Y | SMTR2815S/HO | 594 |
| 5962-9307002HXC | C | 06/22/2000 | 1 | INTERPOINT | | Y | SMTR2815S/HO | 594 |
| 5962L9307002HXA | C | 06/22/2000 | 1 | INTERPOINT | | Y | SMTR2815S/HL | 594 |
| 5962L9307002HXC | C | 06/22/2000 | 1 | INTERPOINT | | Y | SMTR2815S/HL | 594 |
| 5962L9307002KXA | C | 06/22/2000 | 1 | INTERPOINT | | Y | SMTR2815S/KL | 594 |
| 5962L9307002KXC | C | 06/22/2000 | 1 | INTERPOINT | | Y | SMTR2815S/KL | 594 |
| 5962R9307002HXA | C | 06/22/2000 | 1 | INTERPOINT | | Y | SMTR2815S/HR | 594 |
| 5962R9307002HXC | C | 06/22/2000 | 1 | INTERPOINT | | Y | SMTR2815S/HR | 594 |
| 5962R9307002KXA | C | 06/22/2000 | 1 | INTERPOINT | | Y | SMTR2815S/KR | 594 |
| 5962R9307002KXC | C | 06/22/2000 | 1 | INTERPOINT | | Y | SMTR2815S/KR | 594 |
| 5962-9307002HZA | C | 06/22/2000 | 1 | INTERPOINT | | Y | SMTR2815SF/HO | 594 |
| 5962-9307002HZC | C | 06/22/2000 | 1 | INTERPOINT | | Y | SMTR2815SF/HO | 594 |
| 5962L9307002HZA | C | 06/22/2000 | 1 | INTERPOINT | | Y | SMTR2815SF/HL | 594 |
| 5962L9307002HZC | C | 06/22/2000 | 1 | INTERPOINT | | Y | SMTR2815SF/HL | 594 |
| 5962L9307002KZA | C | 06/22/2000 | 1 | INTERPOINT | | Y | SMTR2815SF/KL | 594 |
| 5962L9307002KZC | C | 06/22/2000 | 1 | INTERPOINT | | Y | SMTR2815SF/KL | 594 |
| 5962R9307002HZA | C | 06/22/2000 | 1 | INTERPOINT | | Y | SMTR2815SF/HR | 594 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962R9307002HZC | C | 06/22/2000 | 1 | INTERPOINT | | Y | SMTR2815SF/HR | 594 |
| 5962R9307002KZA | C | 06/22/2000 | 1 | INTERPOINT | | Y | SMTR2815SF/KR | 594 |
| 5962R9307002KZC | C | 06/22/2000 | 1 | INTERPOINT | | Y | SMTR2815SF/KR | 594 |
| 5962-9307101HXA | C | 07/18/2003 | 1 | INTERPOINT | | Y | MTR2812D/883 | 594 |
| 5962-9307101HXC | C | 07/18/2003 | 1 | INTERPOINT | | Y | MTR2812D/883 | 594 |
| 5962-9307101HZA | C | 07/18/2003 | 1 | INTERPOINT | | Y | MTR2812DF/883 | 594 |
| 5962-9307101HZC | C | 07/18/2003 | 1 | INTERPOINT | | Y | MTR2812DF/883 | 594 |
| 5962-9307201HXA | C | 07/18/2003 | 1 | INTERPOINT | | Y | MTR2815D/883 | 594 |
| 5962-9307201HXC | C | 07/18/2003 | 1 | INTERPOINT | | Y | MTR2815D/883 | 594 |
| 5962-9307201HZA | C | 07/18/2003 | 1 | INTERPOINT | | Y | MTR2815DF/883 | 594 |
| 5962-9307201HZC | C | 07/18/2003 | 1 | INTERPOINT | | Y | MTR2815DF/883 | 594 |
| 5962-9307301HXA | E | 07/18/2003 | 1 | INTERPOINT | | Y | MTR28512T/883 | 594 |
| 5962-9307301HXC | E | 07/18/2003 | 1 | INTERPOINT | | Y | MTR28512T/883 | 594 |
| 5962-9307301HZA | E | 07/18/2003 | 1 | INTERPOINT | | Y | MTR28512TF/883 | 594 |
| 5962-9307301HZC | E | 07/18/2003 | 1 | INTERPOINT | | Y | MTR28512TF/883 | 594 |
| 5962-9307401HXA | F | 07/18/2003 | 1 | INTERPOINT | | Y | MTR28515T/883 | 594 |
| 5962-9307401HXC | F | 07/18/2003 | 1 | INTERPOINT | | Y | MTR28515T/883 | 594 |
| 5962-9307401HZA | F | 07/18/2003 | 1 | INTERPOINT | | Y | MTR28515TF/883 | 594 |
| 5962-9307401HZC | F | 07/18/2003 | 1 | INTERPOINT | | Y | MTR28515TF/883 | 594 |
| 5962-9308301MCA | | 09/14/1993 | | (NONE) | | | OP-09 (GEN) | 713 |
| 5962-9308501MXC | A | 03/21/2002 | 2 | LATTICE SEMI | | | ISPLSI1032-60LG/88 | 431 |
| 5962-9308601M3A | A | 03/01/1996 | | (NONE) | | | 54ABT2952 (GEN) | 590 |
| 5962-9308601MKA | A | 03/01/1996 | | (NONE) | | | 54ABT2952 (GEN) | 590 |
| 5962-9308601MLA | A | 03/01/1996 | | (NONE) | | | 54ABT2952 (GEN) | 590 |
| 5962-9308602Q3A | A | 03/01/1996 | 2 | TI | | Y | SNJ54ABT2952AFK | 590 |
| 5962-9308602QKA | A | 03/01/1996 | 2 | TI | | Y | SNJ54ABT2952AW | 590 |
| 5962-9308602QLA | A | 03/01/1996 | 2 | TI | | Y | SNJ54ABT2952AJT | 590 |
| 5962-9308701MXA | A | 07/13/1993 | | (NONE) | 08/04/1995 | | MACH110-20 (GEN) | 431 |
| 5962-9308901HXA | D | 05/21/2001 | 1 | INTERPOINT | | Y | MSA2812D/883 | 594 |
| 5962-9308901HXC | D | 05/21/2001 | 1 | INTERPOINT | | Y | MSA2812D/883 | 594 |
| 5962-9308901HYA | D | 05/21/2001 | 1 | INTERPOINT | | Y | MGA2812DY/883 | 594 |
| 5962-9308901HYC | D | 05/21/2001 | 1 | INTERPOINT | | Y | MGA2812DY/883 | 594 |
| 5962-9308901HZA | D | 05/21/2001 | 1 | INTERPOINT | | Y | MGA2812DZ/883 | 594 |
| 5962-9308902HXA | D | 05/21/2001 | 1 | INTERPOINT | | Y | SMSA2812D/HO | 594 |
| 5962-9308902HXC | D | 05/21/2001 | 1 | INTERPOINT | | Y | SMSA2812D/HO | 594 |
| 5962L9308902HXA | D | 05/21/2001 | 1 | INTERPOINT | | Y | SMSA2812D/HL | 594 |
| 5962L9308902HXC | D | 05/21/2001 | 1 | INTERPOINT | | Y | SMSA2812D/HL | 594 |
| 5962L9308902KXA | D | 05/21/2001 | 1 | INTERPOINT | | Y | SMSA2812D/KL | 594 |
| 5962L9308902KXC | D | 05/21/2001 | 1 | INTERPOINT | | Y | SMSA2812D/KL | 594 |
| 5962R9308902HXA | D | 05/21/2001 | 1 | INTERPOINT | | Y | SMSA2812D/HR | 594 |
| 5962R9308902HXC | D | 05/21/2001 | 1 | INTERPOINT | | Y | SMSA2812D/HR | 594 |
| 5962R9308902KXA | D | 05/21/2001 | 1 | INTERPOINT | | Y | SMSA2812D/KR | 594 |
| 5962R9308902KXC | D | 05/21/2001 | 1 | INTERPOINT | | Y | SMSA2812D/KR | 594 |
| 5962-9309001HXA | C | 07/10/2001 | 1 | INTERPOINT | | Y | MSA2815D/883 | 594 |
| 5962-9309001HXC | C | 07/10/2001 | 1 | INTERPOINT | | Y | MSA2815D/883 | 594 |
| 5962-9309001HYA | C | 07/10/2001 | 1 | INTERPOINT | | Y | MGA2815DY/883 | 594 |
| 5962-9309001HYC | C | 07/10/2001 | 1 | INTERPOINT | | Y | MGA2815DY/883 | 594 |
| 5962-9309001HZA | C | 07/10/2001 | 1 | INTERPOINT | | Y | MGA2815DZ883 | 594 |
| 5962-9309002HXA | C | 07/10/2001 | 1 | INTERPOINT | | Y | SMSA2815D/HO | 594 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9309002HXC | C | 07/10/2001 | 1 | INTERPOINT | | Y | SMSA2815D/HO | 594 |
| 5962L9309002HXA | C | 07/10/2001 | 1 | INTERPOINT | | Y | SMSA2815D/HL | 594 |
| 5962L9309002HXC | C | 07/10/2001 | 1 | INTERPOINT | | Y | SMSA2815D/HL | 594 |
| 5962L9309002KXA | C | 07/10/2001 | 1 | INTERPOINT | | Y | SMSA2815D/KL | 594 |
| 5962L9309002KXC | C | 07/10/2001 | 1 | INTERPOINT | | Y | SMSA2815D/KL | 594 |
| 5962R9309002HXA | C | 07/10/2001 | 1 | INTERPOINT | | Y | SMSA2815D/HR | 594 |
| 5962R9309002HXC | C | 07/10/2001 | 1 | INTERPOINT | | Y | SMSA2815D/HR | 594 |
| 5962R9309002KXA | C | 07/10/2001 | 1 | INTERPOINT | | Y | SMSA2815D/KR | 594 |
| 5962R9309002KXC | C | 07/10/2001 | 1 | INTERPOINT | | Y | SMSA2815D/KR | 594 |
| 5962-9309101HXA | C | 06/24/1996 | 1 | WHITE ELEC. | | Y | WE-512K8-150CQ | 669 |
| 5962-9309101HXC | C | 06/24/1996 | 1 | WHITE ELEC. | | Y | WE-512K8-150CQ | 669 |
| 5962-9309101HYA | C | 06/24/1996 | 1 | AUSTIN SEMI. | | Y | AS8E512K8CW-150/HQ | 669 |
| 5962-9309101HYA | C | 06/24/1996 | 1 | WHITE ELEC. | | Y | WE-512K8-150CQ | 669 |
| 5962-9309101HYC | C | 06/24/1996 | 1 | AUSTIN SEMI. | | Y | AS8E512K8CW-150/HQ | 669 |
| 5962-9309101HYC | C | 06/24/1996 | 1 | WHITE ELEC. | | Y | WE-512K8-150CQ | 669 |
| 5962-9309102HXA | C | 06/24/1996 | 1 | WHITE ELEC. | | Y | WE-512K8-300CQ | 669 |
| 5962-9309102HXC | C | 06/24/1996 | 1 | WHITE ELEC. | | Y | WE-512K8-300CQ | 669 |
| 5962-9309102HYA | C | 06/24/1996 | 1 | AUSTIN SEMI. | | Y | AS8E512K8CW-300/HQ | 669 |
| 5962-9309102HYA | C | 06/24/1996 | 1 | WHITE ELEC. | | Y | WE-512K8-300CQ | 669 |
| 5962-9309102HYC | C | 06/24/1996 | 1 | AUSTIN SEMI. | | Y | AS8E512K8CW-300/HQ | 669 |
| 5962-9309102HYC | C | 06/24/1996 | 1 | WHITE ELEC. | | Y | WE-512K8-300CQ | 669 |
| 5962-9309103HXA | C | 06/24/1996 | 1 | WHITE ELEC. | | Y | WE-512K8-250CQ | 669 |
| 5962-9309103HXC | C | 06/24/1996 | 1 | WHITE ELEC. | | Y | WE-512K8-250CQ | 669 |
| 5962-9309103HYA | C | 06/24/1996 | 1 | AUSTIN SEMI. | | Y | AS8E512K8CW-250/HQ | 669 |
| 5962-9309103HYA | C | 06/24/1996 | 1 | WHITE ELEC. | | Y | WE-512K8-250CQ | 669 |
| 5962-9309103HYC | C | 06/24/1996 | 1 | AUSTIN SEMI. | | Y | AS8E512K8CW-250/HQ | 669 |
| 5962-9309103HYC | C | 06/24/1996 | 1 | WHITE ELEC. | | Y | WE-512K8-250CQ | 669 |
| 5962-9309104HXA | C | 06/24/1996 | 1 | WHITE ELEC. | | Y | WE-512K8-200CQ | 669 |
| 5962-9309104HXC | C | 06/24/1996 | 1 | WHITE ELEC. | | Y | WE-512K8-200CQ | 669 |
| 5962-9309104HYA | C | 06/24/1996 | 1 | AUSTIN SEMI. | | Y | AS8E512K8CW-200/HQ | 669 |
| 5962-9309104HYA | C | 06/24/1996 | 1 | WHITE ELEC. | | Y | WE-512K8-200CQ | 669 |
| 5962-9309104HYC | C | 06/24/1996 | 1 | AUSTIN SEMI. | | Y | AS8E512K8CW-200/HQ | 669 |
| 5962-9309104HYC | C | 06/24/1996 | 1 | WHITE ELEC. | | Y | WE-512K8-200CQ | 669 |
| 5962-9309105HYA | C | 06/24/1996 | 1 | WHITE ELEC. | | Y | WE-512K8-200CQ | 669 |
| 5962-9309105HYC | C | 06/24/1996 | 1 | WHITE ELEC. | | Y | WE-512K8-200CQ | 669 |
| 5962-9309201HXA | E | 04/02/2004 | 1 | INTERPOINT | | Y | MSA2805S/883 | 594 |
| 5962-9309201HXC | E | 04/02/2004 | 1 | INTERPOINT | | Y | MSA2805S/883 | 594 |
| 5962-9309201HYA | E | 04/02/2004 | 1 | INTERPOINT | | Y | MGA2805SY/883 | 594 |
| 5962-9309201HYC | E | 04/02/2004 | 1 | INTERPOINT | | Y | MGA2805SY/883 | 594 |
| 5962-9309201HZA | E | 04/02/2004 | 1 | INTERPOINT | | Y | MGA2805SZ/883 | 594 |
| 5962-9309202HXA | E | 04/02/2004 | 1 | INTERPOINT | | Y | SMSA2805S/HO | 594 |
| 5962-9309202HXC | E | 04/02/2004 | 1 | INTERPOINT | | Y | SMSA2805S/HO | 594 |
| 5962L9309202HXA | E | 04/02/2004 | 1 | INTERPOINT | | Y | SMSA2805S/HL | 594 |
| 5962L9309202HXC | E | 04/02/2004 | 1 | INTERPOINT | | Y | SMSA2805S/HL | 594 |
| 5962L9309202KXA | E | 04/02/2004 | 1 | INTERPOINT | | Y | SMSA2805S/KL | 594 |
| 5962L9309202KXC | E | 04/02/2004 | 1 | INTERPOINT | | Y | SMSA2805S/KL | 594 |
| 5962R9309202HXA | E | 04/02/2004 | 1 | INTERPOINT | | Y | SMSA2805S/HR | 594 |
| 5962R9309202HXC | E | 04/02/2004 | 1 | INTERPOINT | | Y | SMSA2805S/HR | 594 |
| 5962R9309202KXA | E | 04/02/2004 | 1 | INTERPOINT | | Y | SMSA2805S/KR | 594 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962R9309202KXC | E | 04/02/2004 | 1 | INTERPOINT | | Y | SMSA2805S/KR | 594 |
| 5962-9309203HUA | E | 04/02/2004 | 1 | MS KENNEDY | | Y | DHC2805SH | 594 |
| 5962-9309203HUC | E | 04/02/2004 | 1 | MS KENNEDY | | Y | DHC2805SH | 594 |
| 5962-9309301HXA | D | 08/23/2004 | 1 | INTERPOINT | | Y | MSA2812S/883 | 594 |
| 5962-9309301HXC | D | 08/23/2004 | 1 | INTERPOINT | | Y | MSA2812S/883 | 594 |
| 5962-9309301HYA | D | 08/23/2004 | 1 | INTERPOINT | | Y | MGA2812SY/883 | 594 |
| 5962-9309301HYC | D | 08/23/2004 | 1 | INTERPOINT | | Y | MGA2812SY/883 | 594 |
| 5962-9309301HZA | D | 08/23/2004 | 1 | INTERPOINT | | Y | MGA2812SZ/883 | 594 |
| 5962-9309302HXA | D | 08/23/2004 | 1 | INTERPOINT | | Y | SMSA2812S/HO | 594 |
| 5962-9309302HXC | D | 08/23/2004 | 1 | INTERPOINT | | Y | SMSA2812S/HO | 594 |
| 5962L9309302HXA | D | 08/23/2004 | 1 | INTERPOINT | | Y | SMSA2812S/HL | 594 |
| 5962L9309302HXC | D | 08/23/2004 | 1 | INTERPOINT | | Y | SMSA2812S/HL | 594 |
| 5962L9309302KXA | D | 08/23/2004 | 1 | INTERPOINT | | Y | SMSA2812S/KL | 594 |
| 5962L9309302KXC | D | 08/23/2004 | 1 | INTERPOINT | | Y | SMSA2812S/KL | 594 |
| 5962R9309302HXA | D | 08/23/2004 | 1 | INTERPOINT | | Y | SMSA2812S/HR | 594 |
| 5962R9309302HXC | D | 08/23/2004 | 1 | INTERPOINT | | Y | SMSA2812S/HR | 594 |
| 5962R9309302KXA | D | 08/23/2004 | 1 | INTERPOINT | | Y | SMSA2812S/KR | 594 |
| 5962R9309302KXC | D | 08/23/2004 | 1 | INTERPOINT | | Y | SMSA2812S/KR | 594 |
| 5962-9309303HUA | D | 08/23/2004 | 1 | MS KENNEDY | | Y | DAC2812SH | 594 |
| 5962-9309303HUC | D | 08/23/2004 | 1 | MS KENNEDY | | Y | DAC2812SH | 594 |
| 5962-9309401HXA | C | 02/06/2001 | 1 | INTERPOINT | | Y | MSA2815S/883 | 594 |
| 5962-9309401HXC | C | 02/06/2001 | 1 | INTERPOINT | | Y | MSA2815S/883 | 594 |
| 5962-9309401HYA | C | 02/06/2001 | 1 | INTERPOINT | | Y | MGA2815SY/883 | 594 |
| 5962-9309401HYC | C | 02/06/2001 | 1 | INTERPOINT | | Y | MGA2815SY/883 | 594 |
| 5962-9309401HZA | C | 02/06/2001 | 1 | INTERPOINT | | Y | MGA2815SZ/883 | 594 |
| 5962-9309402HXA | C | 02/06/2001 | 1 | INTERPOINT | | Y | SMSA2815S/HO | 594 |
| 5962-9309402HXC | C | 02/06/2001 | 1 | INTERPOINT | | Y | SMSA2815S/HO | 594 |
| 5962L9309402HXA | C | 02/06/2001 | 1 | INTERPOINT | | Y | SMSA2815S/HL | 594 |
| 5962L9309402HXC | C | 02/06/2001 | 1 | INTERPOINT | | Y | SMSA2815S/HL | 594 |
| 5962L9309402KXA | C | 02/06/2001 | 1 | INTERPOINT | | Y | SMSA2815S/KL | 594 |
| 5962L9309402KXC | C | 02/06/2001 | 1 | INTERPOINT | | Y | SMSA2815S/KL | 594 |
| 5962R9309402HXA | C | 02/06/2001 | 1 | INTERPOINT | | Y | SMSA2815S/HR | 594 |
| 5962R9309402HXC | C | 02/06/2001 | 1 | INTERPOINT | | Y | SMSA2815S/HR | 594 |
| 5962R9309402KXA | C | 02/06/2001 | 1 | INTERPOINT | | Y | SMSA2815S/KR | 594 |
| 5962R9309402KXC | C | 02/06/2001 | 1 | INTERPOINT | | Y | SMSA2815S/KR | 594 |
| 5962-9309501MEA | | 04/22/1993 | | (NONE) | 12/24/2000 | | HA-2444 (GEN) | 760 |
| 5962-9309701M2A | | 06/06/1994 | 2 | NATIONAL | | Y | 54ACT715LMQB | 399 |
| 5962-9309701MRA | | 06/06/1994 | 2 | NATIONAL | | Y | 54ACT715DMQB | 399 |
| 5962-9309702M2A | | 06/06/1994 | 3 | NATIONAL | | Y | 54ACT715-RLMQB | 399 |
| 5962-9309702MRA | | 06/06/1994 | 3 | NATIONAL | | Y | 54ACT715-RDMQB | 399 |
| 5962-9309801MYA | | 06/17/1993 | | (NONE) | 09/30/1995 | | 10E416 (GEN) | 304 |
| 5962-9309802MYA | | 06/17/1993 | | (NONE) | 09/30/1995 | | 100E416 (GEN) | 304 |
| 5962-9309901MYA | | 07/08/1993 | | (NONE) | 09/30/1995 | | 10E501 (GEN) | 149 |
| 5962-9309902MYA | | 07/08/1993 | | (NONE) | 09/30/1995 | | 100E501 (GEN) | 149 |
| 5962-9310001MYA | | 07/12/1993 | | (NONE) | 09/30/1995 | | 10E504 (GEN) | 149 |
| 5962-9310002MYA | | 07/12/1993 | | (NONE) | 09/30/1995 | | 100E504 (GEN) | 149 |
| 5962-9310101MYA | | 07/12/1993 | | (NONE) | 09/30/1995 | | 10E507 (GEN) | 149 |
| 5962-9310102MYA | | 07/12/1993 | | (NONE) | 09/30/1995 | | 100E507 (GEN) | 149 |
| 5962-9310201MYA | | 10/13/1993 | | (NONE) | 09/30/1995 | | 10E531 (GEN) | 158 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9310202MYA | | 10/13/1993 | | (NONE) | 09/30/1995 | | 100E531 (GEN) | 158 |
| 5962-9310401MYA | | 07/21/1993 | | (NONE) | 09/30/1995 | | 10E551 (GEN) | 249 |
| 5962-9310402MYA | | 07/21/1993 | | (NONE) | | | 100E551 (GEN) | 249 |
| 5962-9310501MXA | C | 10/23/1996 | | (NONE) | 12/24/1997 | | 80486 (GEN) | 404 |
| 5962-9310501MYA | C | 10/23/1996 | | (NONE) | 12/24/1997 | | 80486 (GEN) | 404 |
| 5962-9310502MXA | C | 10/23/1996 | | (NONE) | 12/24/1997 | | 80486 (GEN) | 404 |
| 5962-9310502MYA | C | 10/23/1996 | | (NONE) | 12/24/1997 | | 80486 (GEN) | 404 |
| 5962-9310503QXA | C | 10/23/1996 | | (NONE) | 12/24/1997 | | 80486 (GEN) | 404 |
| 5962-9310503QYA | C | 10/23/1996 | | (NONE) | 12/24/1997 | | 80486 (GEN) | 404 |
| 5962-9310504QXA | C | 10/23/1996 | | (NONE) | 12/24/1997 | | 80486 (GEN) | 404 |
| 5962-9310504QYA | C | 10/23/1996 | | (NONE) | 12/24/1997 | | 80486 (GEN) | 404 |
| 5962-9310505QXA | C | 10/23/1996 | | (NONE) | 12/24/1997 | | 80486 (GEN) | 404 |
| 5962-9310506QXA | C | 10/23/1996 | | (NONE) | 12/24/1997 | | 80486 (GEN) | 404 |
| 5962-9310507QXA | C | 10/23/1996 | | (NONE) | | | 80486 (GEN) | 404 |
| 5962-9310507QYA | C | 10/23/1996 | | (NONE) | | | 80486 (GEN) | 404 |
| 5962-9310508QXA | C | 10/23/1996 | | (NONE) | | | 80486 (GEN) | 404 |
| 5962-9310508QYA | C | 10/23/1996 | | (NONE) | | | 80486 (GEN) | 404 |
| 5962-9310509NXA | C | 10/23/1996 | | (NONE) | | | 80486 (GEN) | 404 |
| 5962-9310509NYA | C | 10/23/1996 | | (NONE) | | | 80486 (GEN) | 404 |
| 5962-9310510NXA | C | 10/23/1996 | | (NONE) | | | 80486 (GEN) | 404 |
| 5962-9310510NYA | C | 10/23/1996 | | (NONE) | | | 80486 (GEN) | 404 |
| 5962-9310901MXA | | 05/12/1993 | | (NONE) | 12/24/1997 | | 80C186 (GEN) | 403 |
| 5962-9310902MXA | | 05/12/1993 | | (NONE) | 12/24/1997 | | 80C186 (GEN) | 403 |
| 5962-9310903MXA | | 05/12/1993 | | (NONE) | 12/24/1997 | | 80C186 (GEN) | 403 |
| 5962-9311101M2A | A | 05/16/1997 | 1 | LANSDALE | | Y | SL10592/M2A | 569 |
| 5962-9311101M2C | A | 05/16/1997 | 1 | LANSDALE | | Y | SL10592/M2C | 569 |
| 5962-9311101MEA | A | 05/16/1997 | 1 | LANSDALE | | Y | SL10592/MEA | 569 |
| 5962-9311101MFA | A | 05/16/1997 | 1 | LANSDALE | | Y | SL10592/MFA | 569 |
| 5962-9311201MXA | | 09/13/1994 | 3 | CYPRESS | | Y | CY7B992-7LMB | 509 |
| 5962-9311501MXA | A | 12/30/1993 | 3 | NATIONAL | | Y | SCAN18245TFMQB | 590 |
| 5962-9311601MXA | A | 12/30/1993 | 3 | NATIONAL | | Y | SCAN18541TFMQB | 569 |
| 5962-9311701M2A | | 04/27/1993 | | (NONE) | 09/15/1995 | | TL040 (GEN) | 760 |
| 5962-9311701MEA | | 04/27/1993 | | (NONE) | 09/15/1995 | | TL040 (GEN) | 760 |
| 5962-9311801MXA | B | 07/14/1994 | 3 | NATIONAL | | Y | SCAN18373TFMQB | 342 |
| 5962-9311901MYA | | 02/22/1994 | | (NONE) | | | LT1076 (GEN) | 786 |
| 5962-9311902MYA | | 02/22/1994 | | (NONE) | | | LT1076HV (GEN) | 786 |
| 5962-9312001MPA | A | 10/03/2001 | 1 | MAXIM INTEG. | | | MAX680MJA/883B | 899 |
| 5962-9312101MPA | B | 12/12/2003 | 1 | MAXIM INTEG. | | | MAX738AMJA/883B | 789 |
| 5962-9312201M3A | | 03/26/1993 | | (NONE) | 05/10/1995 | | 7C258-15 (GEN) | 659 |
| 5962-9312201MXA | | 03/26/1993 | | (NONE) | 05/10/1995 | | 7C258-15 (GEN) | 659 |
| 5962-9312201MYA | | 03/26/1993 | | (NONE) | 05/10/1995 | | 7C258-15 (GEN) | 659 |
| 5962-9312202M3A | | 03/26/1993 | | (NONE) | 05/10/1995 | | 7C258-12 (GEN) | 659 |
| 5962-9312202MXA | | 03/26/1993 | | (NONE) | 05/10/1995 | | 7C258-12 (GEN) | 659 |
| 5962-9312202MYA | | 03/26/1993 | | (NONE) | 05/10/1995 | | 7C258-12 (GEN) | 659 |
| 5962-9312203MUA | | 03/26/1993 | | (NONE) | 05/10/1995 | | 7C259-15 (GEN) | 659 |
| 5962-9312203MZA | | 03/26/1993 | | (NONE) | 05/10/1995 | | 7C259-15 (GEN) | 659 |
| 5962-9312204MUA | | 03/26/1993 | | (NONE) | 05/10/1995 | | 7C259-12 (GEN) | 659 |
| 5962-9312204MZA | | 03/26/1993 | | (NONE) | 05/10/1995 | | 7C259-12 (GEN) | 659 |
| 5962-9312301M3A | | 03/26/1993 | | (NONE) | | | 7C258-15 (GEN) | 659 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9312301MXA | | 03/26/1993 | | (NONE) | | | 7C258-15 (GEN) | 659 |
| 5962-9312301MYA | | 03/26/1993 | | (NONE) | | | 7C258-15 (GEN) | 659 |
| 5962-9312302M3A | | 03/26/1993 | | (NONE) | | | 7C258-12 (GEN) | 659 |
| 5962-9312302MXA | | 03/26/1993 | | (NONE) | | | 7C258-12 (GEN) | 659 |
| 5962-9312302MYA | | 03/26/1993 | | (NONE) | | | 7C258-12 (GEN) | 659 |
| 5962-9312303MUA | | 03/26/1993 | | (NONE) | | | 7C259-15 (GEN) | 659 |
| 5962-9312303MZA | | 03/26/1993 | | (NONE) | | | 7C259-15 (GEN) | 659 |
| 5962-9312304MUA | | 03/26/1993 | | (NONE) | | | 7C259-12 (GEN) | 659 |
| 5962-9312304MZA | | 03/26/1993 | | (NONE) | | | 7C259-12 (GEN) | 659 |
| 5962-9312401MXA | A | 05/04/2001 | | (NONE) | | | 7C453-30 (GEN) | 670 |
| 5962-9312401MYA | A | 05/04/2001 | | (NONE) | | | 7C453-30 (GEN) | 670 |
| 5962-9312402MXA | A | 05/04/2001 | | (NONE) | | | 7C453-20 (GEN) | 670 |
| 5962-9312402MYA | A | 05/04/2001 | | (NONE) | | | 7C453-20 (GEN) | 670 |
| 5962-9312403MXA | A | 05/04/2001 | 1 | QP SEMI | | Y | 7C453-14/MXA | 670 |
| 5962-9312403MYA | A | 05/04/2001 | 1 | QP SEMI | | Y | 7C453-14/MYA | 670 |
| 5962-9312501M2C | B | 03/28/1996 | 1 | MAXIM INTEG. | | | MAX697MLP/883B | 429 |
| 5962-9312501MEA | B | 03/28/1996 | 1 | MAXIM INTEG. | | | MAX697MJE/883B | 429 |
| 5962-9312502M2C | B | 03/28/1996 | 1 | MAXIM INTEG. | | | MAX696MLP/883B | 429 |
| 5962-9312502MEA | B | 03/28/1996 | 1 | MAXIM INTEG. | | | MAX696MJE/883B | 429 |
| 5962-9312601MXA | B | 08/22/1995 | 1 | ANALOG (2) | | Y | AD1671SQ/883B | 592 |
| 5962-9312701MXA | A | 12/30/1993 | 3 | NATIONAL | | Y | SCAN18540TFMQB | 569 |
| 5962H9312801QXC | A | 06/20/1995 | | (NONE) | 12/20/2001 | | LOR2561C-60 (GEN) | 623 |
| 5962H9312801VXC | A | 06/20/1995 | | (NONE) | 12/20/2001 | | LOR2561C-60 (GEN) | 623 |
| 5962H9312801QYC | A | 06/20/1995 | | (NONE) | 12/20/2001 | | LOR2561C-60 (GEN) | 623 |
| 5962H9312801VYC | A | 06/20/1995 | | (NONE) | 12/20/2001 | | LOR2561C-60 (GEN) | 623 |
| 5962H9312801QZC | A | 06/20/1995 | | (NONE) | 12/20/2001 | | LOR2561C-60 (GEN) | 623 |
| 5962H9312801VZC | A | 06/20/1995 | | (NONE) | 12/20/2001 | | LOR2561C-60 (GEN) | 623 |
| 5962H9312802QXC | A | 06/20/1995 | | (NONE) | 12/20/2001 | | LOR2561T-60 (GEN) | 623 |
| 5962H9312802VXC | A | 06/20/1995 | | (NONE) | 12/20/2001 | | LOR2561T-60 (GEN) | 623 |
| 5962H9312802QYC | A | 06/20/1995 | | (NONE) | 12/20/2001 | | LOR2561T-60 (GEN) | 623 |
| 5962H9312802VYC | A | 06/20/1995 | | (NONE) | 12/20/2001 | | LOR2561T-60 (GEN) | 623 |
| 5962H9312802QZC | A | 06/20/1995 | | (NONE) | 12/20/2001 | | LOR2561T-60 (GEN) | 623 |
| 5962H9312802VZC | A | 06/20/1995 | | (NONE) | 12/20/2001 | | LOR2561T-60 (GEN) | 623 |
| 5962H9312803QXC | A | 06/20/1995 | | (NONE) | 12/20/2001 | | LOR2561C-40 (GEN) | 623 |
| 5962H9312803VXC | A | 06/20/1995 | | (NONE) | 12/20/2001 | | LOR2561C-40 (GEN) | 623 |
| 5962H9312803QYC | A | 06/20/1995 | | (NONE) | 12/20/2001 | | LOR2561C-40 (GEN) | 623 |
| 5962H9312803VYC | A | 06/20/1995 | | (NONE) | 12/20/2001 | | LOR2561C-40 (GEN) | 623 |
| 5962H9312803QZC | A | 06/20/1995 | | (NONE) | 12/20/2001 | | LOR2561C-40 (GEN) | 623 |
| 5962H9312803VZC | A | 06/20/1995 | | (NONE) | 12/20/2001 | | LOR2561C-40 (GEN) | 623 |
| 5962H9312804QXA | A | 06/20/1995 | | (NONE) | | | | 623 |
| 5962H9312804VXA | A | 06/20/1995 | | (NONE) | | | | 623 |
| 5962H9312804QYA | A | 06/20/1995 | | (NONE) | | | | 623 |
| 5962H9312804VYA | A | 06/20/1995 | | (NONE) | | | | 623 |
| 5962H9312805QXC | A | 06/20/1995 | | (NONE) | 12/20/2001 | | LOR2561T-50 (GEN) | 623 |
| 5962H9312805VXC | A | 06/20/1995 | | (NONE) | 12/20/2001 | | LOR2561T-50 (GEN) | 623 |
| 5962H9312805QYC | A | 06/20/1995 | | (NONE) | 12/20/2001 | | LOR2561T-50 (GEN) | 623 |
| 5962H9312805VYC | A | 06/20/1995 | | (NONE) | 12/20/2001 | | LOR2561T-50 (GEN) | 623 |
| 5962H9312805QZC | A | 06/20/1995 | | (NONE) | 12/20/2001 | | LOR2561T-50 (GEN) | 623 |
| 5962H9312805VZC | A | 06/20/1995 | | (NONE) | 12/20/2001 | | LOR2561T-50 (GEN) | 623 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9312901M2A | A | 10/18/2001 | 2 | ANALOG (2) | | Y | AD829SE/883B | 760 |
| 5962-9312901MPA | A | 10/18/2001 | 2 | ANALOG (2) | | Y | AD829SQ/883B | 760 |
| 5962-9313001MPA | C | 12/12/2003 | 2 | ANALOG (2) | | Y | AD830SQ/883B | 760 |
| 5962-9313101M2A | A | 01/08/2002 | 2 | ANALOG (2) | | Y | AD811SE/883B | 760 |
| 5962-9313101MPA | A | 01/08/2002 | 2 | ANALOG (2) | | Y | AD811SQ/883B | 760 |
| 5962-9313201MPA | A | 10/18/2001 | 1 | ANALOG (2) | | Y | AD810SQ/883B | 760 |
| 5962-9313301MPA | A | 12/17/2001 | | (NONE) | 04/16/2002 | | AD797S (GEN) | 701 |
| 5962-9313401HXA | A | 11/30/1993 | 1 | AEROFLEX | | Y | ARX5006 | 789 |
| 5962-9313401HXC | A | 11/30/1993 | 1 | AEROFLEX | | Y | ARX5006 | 789 |
| 5962-9313401HXC | A | 11/30/1993 | 1 | SOLITRON | | Y | CJSE298 | 789 |
| 5962-9313402HXA | A | 11/30/1993 | 1 | AEROFLEX | | Y | ARX5007 | 789 |
| 5962-9313402HXC | A | 11/30/1993 | 1 | AEROFLEX | | Y | ARX5007 | 789 |
| 5962-9313402HXC | A | 11/30/1993 | 1 | SOLITRON | | Y | CJSE299 | 789 |
| 5962-9313403HXA | A | 11/30/1993 | 1 | AEROFLEX | | Y | ARX5008 | 789 |
| 5962-9313403HXC | A | 11/30/1993 | 1 | AEROFLEX | | Y | ARX5008 | 789 |
| 5962-9313403HXC | A | 11/30/1993 | 1 | SOLITRON | | Y | CJSE300 | 789 |
| 5962-9313404HXA | A | 11/30/1993 | 1 | AEROFLEX | | Y | ARX5009 | 789 |
| 5962-9313404HXC | A | 11/30/1993 | 1 | AEROFLEX | | Y | ARX5009 | 789 |
| 5962-9313404HXC | A | 11/30/1993 | 1 | SOLITRON | | Y | CJSE301 | 789 |
| 5962-9313405HXA | A | 11/30/1993 | 1 | AEROFLEX | | Y | ARX5010 | 789 |
| 5962-9313405HXC | A | 11/30/1993 | 1 | AEROFLEX | | Y | ARX5010 | 789 |
| 5962-9313405HXC | A | 11/30/1993 | 1 | SOLITRON | | Y | CJSE321 | 789 |
| 5962-9313406HXA | A | 11/30/1993 | 1 | AEROFLEX | | Y | ARX5011 | 789 |
| 5962-9313406HXC | A | 11/30/1993 | 1 | AEROFLEX | | Y | ARX5011 | 789 |
| 5962-9313406HXC | A | 11/30/1993 | 1 | SOLITRON | | Y | CJSE322 | 789 |
| 5962-9313801MXA | C | 05/14/2001 | | (NONE) | 10/29/2001 | | 72220L50 (GEN) | 670 |
| 5962-9313801MYA | C | 05/14/2001 | | (NONE) | | | 72220L50 (GEN) | 670 |
| 5962-9313802MXA | C | 05/14/2001 | | (NONE) | 10/29/2001 | | 72220L35 (GEN) | 670 |
| 5962-9313802MYA | C | 05/14/2001 | | (NONE) | | | 72220L35 (GEN) | 670 |
| 5962-9313803MXA | C | 05/14/2001 | | (NONE) | 10/29/2001 | | 72220L25 (GEN) | 670 |
| 5962-9313803MYA | C | 05/14/2001 | | (NONE) | | | 72220L25 (GEN) | 670 |
| 5962-9313901MPA | | 04/13/1993 | | (NONE) | 03/31/1998 | | MIC5011 (GEN) | 899 |
| 5962-9313902MCA | | 04/13/1993 | | (NONE) | 03/31/1998 | | MIC5012 (GEN) | 899 |
| 5962-9314001EPA | F | 08/22/2003 | 2 | AGILENT | | Y | HSSR-711E-200 | 460 |
| 5962-9314001EPC | F | 08/22/2003 | 2 | AGILENT | | Y | HSSR-711E | 460 |
| 5962-9314001HPA | F | 08/22/2003 | 2 | AGILENT | | Y | HSSR-7111#200 | 460 |
| 5962-9314001HPA | F | 08/22/2003 | 1 | MICROPAC | | Y | 53111-1P | 460 |
| 5962-9314001HPC | F | 08/22/2003 | 2 | AGILENT | | Y | HSSR-7111 | 460 |
| 5962-9314001HPC | F | 08/22/2003 | 1 | MICROPAC | | Y | 53111-1P | 460 |
| 5962-9314001HXA | F | 08/22/2003 | 2 | AGILENT | | Y | HSSR-7111#300 | 460 |
| 5962-9314001HXA | F | 08/22/2003 | 1 | MICROPAC | | Y | 53111-1X | 460 |
| 5962-9314001HXC | F | 08/22/2003 | 1 | MICROPAC | | Y | 53111-1X | 460 |
| 5962-9314001HYA | F | 08/22/2003 | 2 | AGILENT | | Y | HSSR-7111#100 | 460 |
| 5962-9314001HYA | F | 08/22/2003 | 1 | MICROPAC | | Y | 53111-1Y | 460 |
| 5962-9314001HYC | F | 08/22/2003 | 2 | AGILENT | | Y | HSSR-7111#100 | 460 |
| 5962-9314001HYC | F | 08/22/2003 | 1 | MICROPAC | | Y | 53111-1Y | 460 |
| 5962-9314001HZA | F | 08/22/2003 | 2 | AGILENT | | Y | HSSR-7111#600 | 460 |
| 5962-9314001HZA | F | 08/22/2003 | 1 | MICROPAC | | Y | 53111-1Z | 460 |
| 5962-9314001HZC | F | 08/22/2003 | 2 | AGILENT | | Y | HSSR-7111#600 | 460 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9314001HZC | F | 08/22/2003 | 1 | MICROPAC | | Y | 53111-1Z | 460 |
| 5962-9314002HPA | F | 08/22/2003 | 2 | AGILENT | | Y | HSSR-7112-200 | 460 |
| 5962-9314002HPA | F | 08/22/2003 | 1 | MICROPAC | | Y | 53111-2P | 460 |
| 5962-9314002HPC | F | 08/22/2003 | 2 | AGILENT | | Y | HSSR-7112 | 460 |
| 5962-9314002HPC | F | 08/22/2003 | 1 | MICROPAC | | Y | 53111-2P | 460 |
| 5962-9314002HXA | F | 08/22/2003 | 2 | AGILENT | | Y | HSSR-7112-300 | 460 |
| 5962-9314002HXA | F | 08/22/2003 | 1 | MICROPAC | | Y | 53111-2X | 460 |
| 5962-9314002HXC | F | 08/22/2003 | 1 | MICROPAC | | Y | 53111-2X | 460 |
| 5962-9314002HYA | F | 08/22/2003 | 2 | AGILENT | | Y | HSSR-7112-100 | 460 |
| 5962-9314002HYA | F | 08/22/2003 | 1 | MICROPAC | | Y | 53111-2Y | 460 |
| 5962-9314002HYC | F | 08/22/2003 | 2 | AGILENT | | Y | HSSR-7112-100 | 460 |
| 5962-9314002HYC | F | 08/22/2003 | 1 | MICROPAC | | Y | 53111-2Y | 460 |
| 5962-9314002HZA | F | 08/22/2003 | 2 | AGILENT | | Y | HSSR-7112-600 | 460 |
| 5962-9314002HZA | F | 08/22/2003 | 1 | MICROPAC | | Y | 53111-2Z | 460 |
| 5962-9314002HZC | F | 08/22/2003 | 2 | AGILENT | | Y | HSSR-7112-600 | 460 |
| 5962-9314002HZC | F | 08/22/2003 | 1 | MICROPAC | | Y | 53111-2Z | 460 |
| 5962-9314003HPA | F | 08/22/2003 | 1 | MICROPAC | | Y | 53111-3P | 460 |
| 5962-9314003HPC | F | 08/22/2003 | 1 | MICROPAC | | Y | 53111-3P | 460 |
| 5962-9314003HXA | F | 08/22/2003 | 1 | MICROPAC | | Y | 53111-3X | 460 |
| 5962-9314003HXC | F | 08/22/2003 | 1 | MICROPAC | | Y | 53111-3X | 460 |
| 5962-9314101M3A | | 04/16/1993 | 3 | NATIONAL | | Y | 54ACT899LMQB | 590 |
| 5962-9314101MXA | | 04/16/1993 | | (NONE) | 09/02/2003 | | 54ACT899 (GEN) | 590 |
| 5962-9314301MXA | B | 05/22/1998 | 1 | ATMEL GREN. | | Y | TS68040MR1B/C25 | 404 |
| 5962-9314301MXC | B | 05/22/1998 | 1 | ATMEL GREN. | | Y | TS68040MRB/C25 | 404 |
| 5962-9314301MYC | B | 05/22/1998 | 1 | ATMEL GREN. | | Y | TS68040MFTB/C25 | 404 |
| 5962-9314301MZA | B | 05/22/1998 | 1 | ATMEL GREN. | | Y | TS68040MF1B/C25 | 404 |
| 5962-9314301MZC | B | 05/22/1998 | 1 | ATMEL GREN. | | Y | TS68040MFB/C25 | 404 |
| 5962-9314302MXA | B | 05/22/1998 | 1 | ATMEL GREN. | | Y | TS68040MR1B/C33 | 404 |
| 5962-9314302MXC | B | 05/22/1998 | 1 | ATMEL GREN. | | Y | TS68040MRB/C33 | 404 |
| 5962-9314302MYC | B | 05/22/1998 | 1 | ATMEL GREN. | | Y | TS68040MFTB/C33 | 404 |
| 5962-9314302MZA | B | 05/22/1998 | 1 | ATMEL GREN. | | Y | TS68040MF1B/C33 | 404 |
| 5962-9314302MZC | B | 05/22/1998 | 1 | ATMEL GREN. | | Y | TS68040MFB/C33 | 404 |
| 5962-9314401MUA | A | 01/18/1994 | 2 | QP SEMI | | Y | CY7C346-35HMB | 431 |
| 5962-9314401MXB | A | 01/18/1994 | | (NONE) | 10/31/1996 | | 5130 (GEN) | 431 |
| 5962-9314401MYA | A | 01/18/1994 | | (NONE) | | | | 431 |
| 5962-9314401MZC | A | 01/18/1994 | 2 | QP SEMI | | Y | CY7C346-35RMB | 431 |
| 5962-9314402MUA | A | 01/18/1994 | 2 | CYPRESS | 05/03/2004 | Y | CY7C346-30HMB | 431 |
| 5962-9314402MUA | A | 01/18/1994 | 2 | QP SEMI | | Y | CY7C346-30HMB | 431 |
| 5962-9314402MXA | A | 01/18/1994 | | (NONE) | 10/31/1996 | | 5130 (GEN) | 431 |
| 5962-9314402MYA | A | 01/18/1994 | | (NONE) | | | | 431 |
| 5962-9314402MZC | A | 01/18/1994 | 2 | CYPRESS | 05/03/2004 | Y | CY7C346-30RMB | 431 |
| 5962-9314402MZC | A | 01/18/1994 | 2 | QP SEMI | | Y | CY7C346-30RMB | 431 |
| 5962-9314701Q2A | | 05/31/1995 | 3 | TI | | Y | SNJ54ABT534FK | 159 |
| 5962-9314701QRA | | 05/31/1995 | 3 | TI | | Y | SNJ54ABT534J | 159 |
| 5962-9314701QSA | | 05/31/1995 | 3 | TI | | Y | SNJ54ABT534W | 159 |
| 5962-9314801M2A | A | 12/18/1995 | | (NONE) | 06/01/1997 | | 54ABT377 (GEN) | 159 |
| 5962-9314801Q2A | A | 12/18/1995 | 3 | NATIONAL | | Y | 54ABT377E-QML | 159 |
| 5962-9314801Q2A | A | 12/18/1995 | 3 | TI | | Y | SNJ54ABT377FK | 159 |
| 5962-9314801MRA | A | 12/18/1995 | | (NONE) | 06/01/1997 | | 54ABT377 (GEN) | 159 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9314801QRA | A | 12/18/1995 | 3 | NATIONAL | | Y | 54ABT377J-QML | 159 |
| 5962-9314801QRA | A | 12/18/1995 | 3 | TI | | Y | SNJ54ABT377J | 159 |
| 5962-9314801MSA | A | 12/18/1995 | | (NONE) | | | 54ABT377 (GEN) | 159 |
| 5962-9314801QSA | A | 12/18/1995 | 3 | NATIONAL | | Y | 54ABT377W-QML | 159 |
| 5962-9314801QSA | A | 12/18/1995 | 3 | TI | | Y | SNJ54ABT377W | 159 |
| 5962-9314901M2A | B | 07/21/1994 | | (NONE) | 06/01/1997 | | 54ABT374 (GEN) | 159 |
| 5962-9314901Q2A | B | 07/21/1994 | 2 | NATIONAL | | Y | 54ABT374E-QML | 159 |
| 5962-9314901Q2A | B | 07/21/1994 | 3 | TI | | Y | SNJ54ABT374FK | 159 |
| 5962-9314901MRA | B | 07/21/1994 | | (NONE) | 06/01/1997 | | 54ABT374 (GEN) | 159 |
| 5962-9314901QRA | B | 07/21/1994 | 2 | NATIONAL | | Y | 54ABT374J-QML | 159 |
| 5962-9314901QRA | B | 07/21/1994 | 3 | TI | | Y | SNJ54ABT374J | 159 |
| 5962-9314901MSA | B | 07/21/1994 | | (NONE) | | | 54ABT374 (GEN) | 159 |
| 5962-9314901QSA | B | 07/21/1994 | 2 | NATIONAL | | Y | 54ABT374W-QML | 159 |
| 5962-9314901QSA | B | 07/21/1994 | 3 | TI | | Y | SNJ54ABT374W | 159 |
| 5962-9315001MXA | A | 07/07/1994 | | (NONE) | 09/30/1995 | | 96002-33 (GEN) | 409 |
| 5962-9315201MXA | A | 08/02/1999 | | (NONE) | | | 7C464-40 (GEN) | 670 |
| 5962-9315201MYA | A | 08/02/1999 | | (NONE) | | | 7C464-40 (GEN) | 670 |
| 5962-9315202MXA | A | 08/02/1999 | | (NONE) | | | 7C464-25 (GEN) | 670 |
| 5962-9315202MYA | A | 08/02/1999 | | (NONE) | 05/30/1999 | | 7C464-25 (GEN) | 670 |
| 5962-9315203MXA | A | 08/02/1999 | | (NONE) | 05/30/1999 | | 7C464-20 (GEN) | 670 |
| 5962-9315203MYA | A | 08/02/1999 | | (NONE) | | | 7C464-20 (GEN) | 670 |
| 5962-9315204QXA | A | 08/02/1999 | 3 | QP SEMI | | Y | CY7C464A-40DMB | 670 |
| 5962-9315204QYA | A | 08/02/1999 | 3 | QP SEMI | | Y | CY7C464A-40LMB | 670 |
| 5962-9315205QXA | A | 08/02/1999 | 3 | QP SEMI | | Y | CY7C464A-25DMB | 670 |
| 5962-9315205QYA | A | 08/02/1999 | 3 | QP SEMI | | Y | CY7C464A-25LMB | 670 |
| 5962-9315206QXA | A | 08/02/1999 | 3 | QP SEMI | | Y | CY7C464A-20DMB | 670 |
| 5962-9315206QYA | A | 08/02/1999 | 3 | QP SEMI | | Y | CY7C464A-20LMB | 670 |
| 5962-9315207QXA | A | 08/02/1999 | 3 | QP SEMI | | Y | CY7C464A-15DMB | 670 |
| 5962-9315207QYA | A | 08/02/1999 | 3 | QP SEMI | | Y | CY7C464A-15LMB | 670 |
| 5962-9315301MXA | A | 05/15/2001 | 1 | IDT | | Y | IDT7014S35XLB | 629 |
| 5962-9315302MXA | A | 05/15/2001 | 1 | IDT | | Y | IDT7014S25XLB | 629 |
| 5962-9315303MXA | A | 05/15/2001 | 1 | IDT | | Y | IDT7014S20XLB | 629 |
| 5962-9315401HXA | | 03/23/1993 | 1 | WHITE ELEC. | | Y | WE-128K8-200CQ | 669 |
| 5962-9315401HXC | | 03/23/1993 | 1 | WHITE ELEC. | | Y | WE-128K8-200CQ | 669 |
| 5962-9315402HXA | | 03/23/1993 | 1 | WHITE ELEC. | | Y | WE-128K8-150CQ | 669 |
| 5962-9315402HXC | | 03/23/1993 | 1 | WHITE ELEC. | | Y | WE-128K8-150CQ | 669 |
| 5962-9315501HXA | A | 01/14/1997 | | (NONE) | | | 256K8-200 (GEN) | 669 |
| 5962-9315501HXC | A | 01/14/1997 | | (NONE) | | | 256K8-200 (GEN) | 669 |
| 5962-9315501HYA | A | 01/14/1997 | 1 | WHITE ELEC. | | Y | WE-256K8-200CQ | 669 |
| 5962-9315501HYC | A | 01/14/1997 | 1 | WHITE ELEC. | | Y | WE-256K8-200CQ | 669 |
| 5962-9315502HXA | A | 01/14/1997 | | (NONE) | | | 256K8-150 (GEN) | 669 |
| 5962-9315502HXC | A | 01/14/1997 | | (NONE) | | | 256K8-150 (GEN) | 669 |
| 5962-9315502HYA | A | 01/14/1997 | 1 | WHITE ELEC. | | Y | WE-256K8-150CQ | 669 |
| 5962-9315502HYC | A | 01/14/1997 | 1 | WHITE ELEC. | | Y | WE-256K8-150CQ | 669 |
| 5962-9315601HXA | B | 07/10/2000 | | (NONE) | | | WS-128K8-120 (GEN) | 625 |
| 5962-9315601HYA | B | 07/10/2000 | 1 | WHITE ELEC. | | Y | WS-128K8-120CQ | 625 |
| 5962-9315601HYC | B | 07/10/2000 | 1 | WHITE ELEC. | | Y | WS-128K8-120CQ | 625 |
| 5962-9315602HXA | B | 07/10/2000 | | (NONE) | | | WS-128K8-100 (GEN) | 625 |
| 5962-9315602HYA | B | 07/10/2000 | 1 | WHITE ELEC. | | Y | WS-128K8-100CQ | 625 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9315602HYC | B | 07/10/2000 | 1 | WHITE ELEC. | | Y | WS-128K8-100CQ | 625 |
| 5962-9315603HXA | B | 07/10/2000 | | (NONE) | | | WS-128K8-85 (GEN) | 625 |
| 5962-9315603HYA | B | 07/10/2000 | 1 | WHITE ELEC. | | Y | WS-128K8-85CQ | 625 |
| 5962-9315603HYC | B | 07/10/2000 | 1 | WHITE ELEC. | | Y | WS-128K8-85CQ | 625 |
| 5962-9315604HXA | B | 07/10/2000 | | (NONE) | | | WS-128K8-70 (GEN) | 625 |
| 5962-9315604HYA | B | 07/10/2000 | 1 | WHITE ELEC. | | Y | WS-128K8-70CQ | 625 |
| 5962-9315604HYC | B | 07/10/2000 | 1 | WHITE ELEC. | | Y | WS-128K8-70CQ | 625 |
| 5962-9315605HXA | B | 07/10/2000 | | (NONE) | | | WS-128K8-55 (GEN) | 625 |
| 5962-9315605HYA | B | 07/10/2000 | 1 | WHITE ELEC. | | Y | WS-128K8-55CQ | 625 |
| 5962-9315605HYC | B | 07/10/2000 | 1 | WHITE ELEC. | | Y | WS-128K8-55CQ | 625 |
| 5962-9315606HXA | B | 07/10/2000 | | (NONE) | | | WS-128K8-45 (GEN) | 625 |
| 5962-9315606HYA | B | 07/10/2000 | 1 | WHITE ELEC. | | Y | WS-128K8-45CQ | 625 |
| 5962-9315606HYC | B | 07/10/2000 | 1 | WHITE ELEC. | | Y | WS-128K8-45CQ | 625 |
| 5962-9315607HXA | B | 07/10/2000 | | (NONE) | | | WS-128K8-35 (GEN) | 625 |
| 5962-9315607HYA | B | 07/10/2000 | 1 | WHITE ELEC. | | Y | WS-128K8-35CQ | 625 |
| 5962-9315607HYC | B | 07/10/2000 | 1 | WHITE ELEC. | | Y | WS-128K8-35CQ | 625 |
| 5962-9315608HXA | B | 07/10/2000 | | (NONE) | | | WS-128K8-25 (GEN) | 625 |
| 5962-9315608HYA | B | 07/10/2000 | 1 | WHITE ELEC. | | Y | WS-128K8-25CQ | 625 |
| 5962-9315608HYC | B | 07/10/2000 | 1 | WHITE ELEC. | | Y | WS-128K8-25CQ | 625 |
| 5962-9315701HXA | G | 04/02/2002 | 1 | WHITE ELEC. | | Y | WS256K8-120CQA | 629 |
| 5962-9315701HXC | G | 04/02/2002 | 1 | WHITE ELEC. | | Y | WS256K8-120CQ | 629 |
| 5962-9315701HYA | G | 04/02/2002 | 1 | WHITE ELEC. | | Y | WS256K8-120CQA | 629 |
| 5962-9315701HYC | G | 04/02/2002 | 1 | WHITE ELEC. | | Y | WS256K8-120CQ | 629 |
| 5962-9315702HXA | G | 04/02/2002 | 1 | WHITE ELEC. | | Y | WS256K8-100CQA | 629 |
| 5962-9315702HXC | G | 04/02/2002 | 1 | WHITE ELEC. | | Y | WS256K8-100CQ | 629 |
| 5962-9315702HYA | G | 04/02/2002 | 1 | WHITE ELEC. | | Y | WS256K8-100CQA | 629 |
| 5962-9315702HYC | G | 04/02/2002 | 1 | WHITE ELEC. | | Y | WS256K8-100CQ | 629 |
| 5962-9315703HXA | G | 04/02/2002 | 1 | WHITE ELEC. | | Y | WS256K8-85CQA | 629 |
| 5962-9315703HXC | G | 04/02/2002 | 1 | WHITE ELEC. | | Y | WS256K8-85CQ | 629 |
| 5962-9315703HYA | G | 04/02/2002 | 1 | WHITE ELEC. | | Y | WS256K8-85CQA | 629 |
| 5962-9315703HYC | G | 04/02/2002 | 1 | WHITE ELEC. | | Y | WS256K8-85CQ | 629 |
| 5962-9315704HXA | G | 04/02/2002 | 1 | WHITE ELEC. | | Y | WS256K8-70CQA | 629 |
| 5962-9315704HXC | G | 04/02/2002 | 1 | WHITE ELEC. | | Y | WS256K8-70CQ | 629 |
| 5962-9315704HYA | G | 04/02/2002 | 1 | WHITE ELEC. | | Y | WS256K8-70CQA | 629 |
| 5962-9315704HYC | G | 04/02/2002 | 1 | WHITE ELEC. | | Y | WS256K8-70CQ | 629 |
| 5962-9315705HXA | G | 04/02/2002 | 1 | WHITE ELEC. | | Y | WS256K8-55CQA | 629 |
| 5962-9315705HXC | G | 04/02/2002 | 1 | WHITE ELEC. | | Y | WS256K8-55CQ | 629 |
| 5962-9315705HYA | G | 04/02/2002 | 1 | AUSTIN SEMI. | | Y | AS5C2008CW-55/HQ | 629 |
| 5962-9315705HYA | G | 04/02/2002 | 1 | WHITE ELEC. | | Y | WS256K8-55CQA | 629 |
| 5962-9315705HYC | G | 04/02/2002 | 1 | AUSTIN SEMI. | | Y | AS5C2008CW-55/HQ | 629 |
| 5962-9315705HYC | G | 04/02/2002 | 1 | WHITE ELEC. | | Y | WS256K8-55CQ | 629 |
| 5962-9315706HXA | G | 04/02/2002 | 1 | WHITE ELEC. | | Y | WS256K8-45CQA | 629 |
| 5962-9315706HXC | G | 04/02/2002 | 1 | WHITE ELEC. | | Y | WS256K8-45CQ | 629 |
| 5962-9315706HYA | G | 04/02/2002 | 1 | AUSTIN SEMI. | | Y | AS5C2008CW-45/HQ | 629 |
| 5962-9315706HYA | G | 04/02/2002 | 1 | WHITE ELEC. | | Y | WS256K8-45CQA | 629 |
| 5962-9315706HYC | G | 04/02/2002 | 1 | AUSTIN SEMI. | | Y | AS5C2008CW-45/HQ | 629 |
| 5962-9315706HYC | G | 04/02/2002 | 1 | WHITE ELEC. | | Y | WS256K8-45CQ | 629 |
| 5962-9315707HXA | G | 04/02/2002 | 1 | WHITE ELEC. | | Y | WS256K8-35CQA | 629 |
| 5962-9315707HXC | G | 04/02/2002 | 1 | WHITE ELEC. | | Y | WS256K8-35CQ | 629 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9315707HYA | G | 04/02/2002 | 1 | AUSTIN SEMI. | | Y | AS5C2008CW-35/HQ | 629 |
| 5962-9315707HYA | G | 04/02/2002 | 1 | WHITE ELEC. | | Y | WS256K8-35CQA | 629 |
| 5962-9315707HYC | G | 04/02/2002 | 1 | AUSTIN SEMI. | | Y | AS5C2008CW-35/HQ | 629 |
| 5962-9315707HYC | G | 04/02/2002 | 1 | WHITE ELEC. | | Y | WS256K8-35CQ | 629 |
| 5962-9315708HXA | G | 04/02/2002 | 1 | WHITE ELEC. | | Y | WS256K8-25CQA | 629 |
| 5962-9315708HXC | G | 04/02/2002 | 1 | WHITE ELEC. | | Y | WS256K8-25CQ | 629 |
| 5962-9315708HYA | G | 04/02/2002 | 1 | AUSTIN SEMI. | | Y | AS5C2008CW-25/HQ | 629 |
| 5962-9315708HYA | G | 04/02/2002 | 1 | WHITE ELEC. | | Y | WS256K8-25CQA | 629 |
| 5962-9315708HYC | G | 04/02/2002 | 1 | AUSTIN SEMI. | | Y | AS5C2008CW-25/HQ | 629 |
| 5962-9315708HYC | G | 04/02/2002 | 1 | WHITE ELEC. | | Y | WS256K8-25CQ | 629 |
| 5962-9315709HXA | G | 04/02/2002 | 1 | WHITE ELEC. | | Y | WS256K8-20CQA | 629 |
| 5962-9315709HXC | G | 04/02/2002 | 1 | WHITE ELEC. | | Y | WS256K8-20CQ | 629 |
| 5962-9315709HYA | G | 04/02/2002 | 1 | WHITE ELEC. | | Y | WS256K8-20CQA | 629 |
| 5962-9315709HYC | G | 04/02/2002 | 1 | WHITE ELEC. | | Y | WS256K8-20CQ | 629 |
| 5962-9315801HXA | A | 10/24/2000 | 1 | ADV. ANALOG | | Y | ATR2812T/CH | 594 |
| 5962-9315801HZA | A | 10/24/2000 | 1 | ADV. ANALOG | | Y | ATR2812TF/CH | 594 |
| 5962-9315901QXA | | 12/11/1998 | 1 | ATMEL GREN. | | Y | TS68302MR1B/C16 | 439 |
| 5962-9315901QXC | | 12/11/1998 | 1 | ATMEL GREN. | | Y | TS68302MRB/C16 | 439 |
| 5962-9315901QYA | | 12/11/1998 | 1 | ATMEL GREN. | | Y | TS68302MAB/C16 | 439 |
| 5962-9316101HTA | D | 07/28/2004 | 1 | INTERPOINT | | Y | MFL2815SW/883 | 594 |
| 5962-9316101HTC | D | 07/28/2004 | 1 | INTERPOINT | | Y | MFL2815SW/883 | 594 |
| 5962-9316101HUA | D | 07/28/2004 | 1 | INTERPOINT | | Y | MFL2815SV/883 | 594 |
| 5962-9316101HUC | D | 07/28/2004 | 1 | INTERPOINT | | Y | MFL2815SV/883 | 594 |
| 5962-9316101HXA | D | 07/28/2004 | 1 | INTERPOINT | | Y | MFL2815S/883 | 594 |
| 5962-9316101HXC | D | 07/28/2004 | 1 | INTERPOINT | | Y | MFL2815S/883 | 594 |
| 5962-9316101HYA | D | 07/28/2004 | 1 | INTERPOINT | | Y | MFL2815SY/883 | 594 |
| 5962-9316101HYC | D | 07/28/2004 | 1 | INTERPOINT | | Y | MFL2815SY/883 | 594 |
| 5962-9316101HZA | D | 07/28/2004 | 1 | INTERPOINT | | Y | MFL2815SZ/883 | 594 |
| 5962-9316101HZC | D | 07/28/2004 | 1 | INTERPOINT | | Y | MFL2815SZ/883 | 594 |
| 5962-9316201HTA | D | 07/28/2004 | 1 | INTERPOINT | | Y | MFL2812SW/883 | 594 |
| 5962-9316201HTC | D | 07/28/2004 | 1 | INTERPOINT | | Y | MFL2812SW/883 | 594 |
| 5962-9316201HUA | D | 07/28/2004 | 1 | INTERPOINT | | Y | MFL2812SV/883 | 594 |
| 5962-9316201HUC | D | 07/28/2004 | 1 | INTERPOINT | | Y | MFL2812SV/883 | 594 |
| 5962-9316201HXA | D | 07/28/2004 | 1 | INTERPOINT | | Y | MFL2812S/883 | 594 |
| 5962-9316201HXC | D | 07/28/2004 | 1 | INTERPOINT | | Y | MFL2812S/883 | 594 |
| 5962-9316201HYA | D | 07/28/2004 | 1 | INTERPOINT | | Y | MFL2812SY/883 | 594 |
| 5962-9316201HYC | D | 07/28/2004 | 1 | INTERPOINT | | Y | MFL2812SY/883 | 594 |
| 5962-9316201HZA | D | 07/28/2004 | 1 | INTERPOINT | | Y | MFL2812SZ/883 | 594 |
| 5962-9316201HZC | D | 07/28/2004 | 1 | INTERPOINT | | Y | MFL2812SZ/883 | 594 |
| 5962-9316301HTA | C | 06/21/2002 | 1 | INTERPOINT | | Y | MFL2805SW/883 | 594 |
| 5962-9316301HTC | C | 06/21/2002 | 1 | INTERPOINT | | Y | MFL2805SW/883 | 594 |
| 5962-9316301HUA | C | 06/21/2002 | 1 | INTERPOINT | | Y | MFL2805SV/883 | 594 |
| 5962-9316301HUC | C | 06/21/2002 | 1 | INTERPOINT | | Y | MFL2805SV/883 | 594 |
| 5962-9316301HXA | C | 06/21/2002 | 1 | INTERPOINT | | Y | MFL2805S/883 | 594 |
| 5962-9316301HXC | C | 06/21/2002 | 1 | INTERPOINT | | Y | MFL2805S/883 | 594 |
| 5962-9316301HYA | C | 06/21/2002 | 1 | INTERPOINT | | Y | MFL2805SY/883 | 594 |
| 5962-9316301HYC | C | 06/21/2002 | 1 | INTERPOINT | | Y | MFL2805SY/883 | 594 |
| 5962-9316301HZA | C | 06/21/2002 | 1 | INTERPOINT | | Y | MFL2805SZ/883 | 594 |
| 5962-9316301HZC | C | 06/21/2002 | 1 | INTERPOINT | | Y | MFL2805SZ/883 | 594 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9316302HTA | C | 06/21/2002 | 1 | INTERPOINT | | Y | SMFL2805SW/HO | 594 |
| 5962-9316302HTC | C | 06/21/2002 | 1 | INTERPOINT | | Y | SMFL2805SW/HO | 594 |
| 5962R9316302HTA | C | 06/21/2002 | 1 | INTERPOINT | | Y | SMFL2805SW/HR | 594 |
| 5962R9316302HTC | C | 06/21/2002 | 1 | INTERPOINT | | Y | SMFL2805SW/HR | 594 |
| 5962R9316302KTA | C | 06/21/2002 | 1 | INTERPOINT | | Y | SMFL2805SW/KR | 594 |
| 5962R9316302KTC | C | 06/21/2002 | 1 | INTERPOINT | | Y | SMFL2805SW/KR | 594 |
| 5962-9316302HUA | C | 06/21/2002 | 1 | INTERPOINT | | Y | SMFL2805SV/HO | 594 |
| 5962-9316302HUC | C | 06/21/2002 | 1 | INTERPOINT | | Y | SMFL2805SV/HO | 594 |
| 5962R9316302HUA | C | 06/21/2002 | 1 | INTERPOINT | | Y | SMFL2805SV/HR | 594 |
| 5962R9316302HUC | C | 06/21/2002 | 1 | INTERPOINT | | Y | SMFL2805SV/HR | 594 |
| 5962R9316302KUA | C | 06/21/2002 | 1 | INTERPOINT | | Y | SMFL2805SV/KR | 594 |
| 5962R9316302KUC | C | 06/21/2002 | 1 | INTERPOINT | | Y | SMFL2805SV/KR | 594 |
| 5962-9316302HXA | C | 06/21/2002 | 1 | INTERPOINT | | Y | SMFL2805S/HO | 594 |
| 5962-9316302HXC | C | 06/21/2002 | 1 | INTERPOINT | | Y | SMFL2805S/HO | 594 |
| 5962R9316302HXA | C | 06/21/2002 | 1 | INTERPOINT | | Y | SMFL2805S/HR | 594 |
| 5962R9316302HXC | C | 06/21/2002 | 1 | INTERPOINT | | Y | SMFL2805S/HR | 594 |
| 5962R9316302KXA | C | 06/21/2002 | 1 | INTERPOINT | | Y | SMFL2805S/KR | 594 |
| 5962R9316302KXC | C | 06/21/2002 | 1 | INTERPOINT | | Y | SMFL2805S/KR | 594 |
| 5962-9316302HYA | C | 06/21/2002 | 1 | INTERPOINT | | Y | SMFL2805SY/HO | 594 |
| 5962-9316302HYC | C | 06/21/2002 | 1 | INTERPOINT | | Y | SMFL2805SY/HO | 594 |
| 5962R9316302HYA | C | 06/21/2002 | 1 | INTERPOINT | | Y | SMFL2805SY/HR | 594 |
| 5962R9316302HYC | C | 06/21/2002 | 1 | INTERPOINT | | Y | SMFL2805SY/HR | 594 |
| 5962R9316302KYA | C | 06/21/2002 | 1 | INTERPOINT | | Y | SMFL2805SY/KR | 594 |
| 5962R9316302KYC | C | 06/21/2002 | 1 | INTERPOINT | | Y | SMFL2805SY/KR | 594 |
| 5962-9316302HZA | C | 06/21/2002 | 1 | INTERPOINT | | Y | SMFL2805SZ/HO | 594 |
| 5962-9316302HZC | C | 06/21/2002 | 1 | INTERPOINT | | Y | SMFL2805SZ/HO | 594 |
| 5962R9316302HZA | C | 06/21/2002 | 1 | INTERPOINT | | Y | SMFL2805SZ/HR | 594 |
| 5962R9316302HZC | C | 06/21/2002 | 1 | INTERPOINT | | Y | SMFL2805SZ/HR | 594 |
| 5962R9316302KZA | C | 06/21/2002 | 1 | INTERPOINT | | Y | SMFL2805SZ/KR | 594 |
| 5962R9316302KZC | C | 06/21/2002 | 1 | INTERPOINT | | Y | SMFL2805SZ/KR | 594 |
| 5962-9316401MXA | A | 03/07/2002 | 1 | ANALOG (2) | | Y | AD1674TD/883B | 592 |
| 5962-9316601MXA | A | 11/05/1993 | | (NONE) | | | 7C271-55 (GEN) | 662 |
| 5962-9316601MYA | A | 11/05/1993 | | (NONE) | 05/10/1995 | | 7C271-55 (GEN) | 662 |
| 5962-9316601MZA | A | 11/05/1993 | | (NONE) | | | | 662 |
| 5962-9316602MXA | A | 11/05/1993 | | (NONE) | 04/10/2001 | | 7C271-45 (GEN) | 662 |
| 5962-9316602MYA | A | 11/05/1993 | | (NONE) | 05/10/1995 | | 7C271-45 (GEN) | 662 |
| 5962-9316602MZA | A | 11/05/1993 | | (NONE) | | | | 662 |
| 5962-9316603MXA | A | 11/05/1993 | | (NONE) | 04/10/2001 | | 7C271-35 (GEN) | 662 |
| 5962-9316603MYA | A | 11/05/1993 | | (NONE) | 05/10/1995 | | 7C271-35 (GEN) | 662 |
| 5962-9316603MZA | A | 11/05/1993 | | (NONE) | | | | 662 |
| 5962-9316604MUA | A | 11/05/1993 | | (NONE) | 05/10/1995 | | 7C274-55 (GEN) | 662 |
| 5962-9316604MZA | A | 11/05/1993 | | (NONE) | 05/10/1995 | | 7C274-55 (GEN) | 662 |
| 5962-9316605MUA | A | 11/05/1993 | | (NONE) | 05/10/1995 | | 7C274-45 (GEN) | 662 |
| 5962-9316605MZA | A | 11/05/1993 | | (NONE) | 05/10/1995 | | 7C274-45 (GEN) | 662 |
| 5962-9316606MUA | A | 11/05/1993 | | (NONE) | 05/10/1995 | | 7C274-35 (GEN) | 662 |
| 5962-9316606MZA | A | 11/05/1993 | | (NONE) | 05/10/1995 | | 7C274-35 (GEN) | 662 |
| 5962-9316801MXC | A | 02/03/1995 | | (NONE) | 10/31/1996 | | 7192 (GEN) | 431 |
| 5962-9316802MXC | A | 02/03/1995 | | (NONE) | 10/31/1996 | | 7192 (GEN) | 431 |
| 5962-9317001MXC | A | 02/02/1996 | | (NONE) | 06/29/2001 | | 68230-8 (GEN) | 420 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9317001MYA | A | 02/02/1996 | | (NONE) | 06/29/2001 | | 68230-8 (GEN) | 420 |
| 5962-9317002MXC | A | 02/02/1996 | | (NONE) | 06/29/2001 | | 68230-10 (GEN) | 420 |
| 5962-9317002MYA | A | 02/02/1996 | | (NONE) | 06/29/2001 | | 68230-10 (GEN) | 420 |
| 5962-9317301MXA | | 10/29/1993 | | (NONE) | | | 7C451-30 (GEN) | 670 |
| 5962-9317301MYA | | 10/29/1993 | | (NONE) | | | 7C451-30 (GEN) | 670 |
| 5962-9317302MXA | | 10/29/1993 | | (NONE) | | | 7C451-20 (GEN) | 670 |
| 5962-9317302MYA | | 10/29/1993 | | (NONE) | | | 7C451-20 (GEN) | 670 |
| 5962-9317303MXA | | 10/29/1993 | | (NONE) | | | 7C451-14 (GEN) | 670 |
| 5962-9317303MYA | | 10/29/1993 | | (NONE) | | | 7C451-14 (GEN) | 670 |
| 5962-9317401MXA | D | 02/18/2003 | 3 | TI | | Y | SNJ54ABT16244WD | 529 |
| 5962-9317402QXA | D | 02/18/2003 | 2 | NATIONAL | | Y | 54ABT16244W-QML | 529 |
| 5962-9317501MXA | B | 04/12/1999 | 1 | TI | | Y | SNJ54ABT16245WD | 590 |
| 5962-9317502QXA | B | 04/12/1999 | 2 | NATIONAL | | Y | 54ABT16245W-QML | 590 |
| 5962-9317601QCA | A | 07/14/1994 | | (NONE) | 09/30/1995 | | 88914 (GEN) | 550 |
| 5962-9317601QDA | A | 07/14/1994 | | (NONE) | 09/30/1995 | | 88914 (GEN) | 550 |
| 5962-9317701MUA | E | 10/02/2003 | 3 | QP SEMI | | Y | CY7C462A-50/MUA | 670 |
| 5962-9317701MXA | E | 10/02/2003 | 3 | QP SEMI | | Y | CY7C462A-50DMB | 670 |
| 5962-9317701MYA | E | 10/02/2003 | 3 | QP SEMI | | Y | CY7C462A-50LMB | 670 |
| 5962-9317701MZA | E | 10/02/2003 | 3 | QP SEMI | | Y | CY7C462A-50KMB | 670 |
| 5962-9317702QNC | E | 10/02/2003 | 2 | ATMEL NANTES | | Y | MMDP-67206FV-30MQ | 670 |
| 5962-9317702VNC | E | 10/02/2003 | 2 | ATMEL NANTES | | Y | SMDP-67206FV-30SV | 670 |
| 5962D9317702VNC | E | 10/02/2003 | 2 | ATMEL NANTES | | Y | SMDP-67206FV-30SR | 670 |
| 5962-9317702QTC | E | 10/02/2003 | 2 | ATMEL NANTES | | Y | MMCP-67206FV-30MQ | 670 |
| 5962-9317702VTC | E | 10/02/2003 | 2 | ATMEL NANTES | | Y | SMCP-67206FV-30SV | 670 |
| 5962D9317702VTC | E | 10/02/2003 | 2 | ATMEL NANTES | | Y | SMCP-67206FV-30SR | 670 |
| 5962-9317702MUA | E | 10/02/2003 | 3 | QP SEMI | | Y | CY7C462A-30/MUA | 670 |
| 5962-9317702QUC | E | 10/02/2003 | | (NONE) | | | 67206-30 (GEN) | 670 |
| 5962-9317702VUC | E | 10/02/2003 | | (NONE) | | | 67206-30 (GEN) | 670 |
| 5962-9317702MXA | E | 10/02/2003 | 1 | IDT | | Y | IDT7206L30DB | 670 |
| 5962-9317702MXA | E | 10/02/2003 | 3 | QP SEMI | | Y | CY7C462A-30DMB | 670 |
| 5962-9317702MYA | E | 10/02/2003 | 1 | IDT | | Y | IDT7206L30LB | 670 |
| 5962-9317702MYA | E | 10/02/2003 | 3 | QP SEMI | | Y | CY7C462A-30LMB | 670 |
| 5962-9317702MZA | E | 10/02/2003 | 3 | QP SEMI | | Y | CY7C462A-30KMB | 670 |
| 5962-9317702QZC | E | 10/02/2003 | | (NONE) | | | 67206-30 (GEN) | 670 |
| 5962-9317702VZC | E | 10/02/2003 | | (NONE) | | | 67206-30 (GEN) | 670 |
| 5962-9317703MUA | E | 10/02/2003 | 3 | QP SEMI | | Y | CY7C462A-20/MUA | 670 |
| 5962-9317703MXA | E | 10/02/2003 | 1 | IDT | | Y | IDT7206L20DB | 670 |
| 5962-9317703MXA | E | 10/02/2003 | 3 | QP SEMI | | Y | CY7C462A-20DMB | 670 |
| 5962-9317703MYA | E | 10/02/2003 | 1 | IDT | | Y | IDT7206L20LB | 670 |
| 5962-9317703MYA | E | 10/02/2003 | 3 | QP SEMI | | Y | CY7C462A-20LMB | 670 |
| 5962-9317703MZA | E | 10/02/2003 | 3 | QP SEMI | | Y | CY7C462A-20KMB | 670 |
| 5962-9317704QNC | E | 10/02/2003 | 2 | ATMEL NANTES | | Y | MMDP-67206FV-15MQ | 670 |
| 5962-9317704VNC | E | 10/02/2003 | 2 | ATMEL NANTES | | Y | SMDP-67206FV-15SV | 670 |
| 5962D9317704VNC | E | 10/02/2003 | 2 | ATMEL NANTES | | Y | SMDP-67206FV-15SR | 670 |
| 5962-9317704QTC | E | 10/02/2003 | 2 | ATMEL NANTES | | Y | MMCP-67206FV-15MQ | 670 |
| 5962-9317704VTC | E | 10/02/2003 | 2 | ATMEL NANTES | | Y | SMCP-67206FV-15SV | 670 |
| 5962D9317704VTC | E | 10/02/2003 | 2 | ATMEL NANTES | | Y | SMCP-67206FV-15SR | 670 |
| 5962-9317704QUC | E | 10/02/2003 | | (NONE) | | | 67206-15 (GEN) | 670 |
| 5962-9317704VUC | E | 10/02/2003 | | (NONE) | | | 67206-15 (GEN) | 670 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9317704QZC | E | 10/02/2003 | | (NONE) | | | 67206-15 (GEN) | 670 |
| 5962-9317704VZC | E | 10/02/2003 | | (NONE) | | | 67206-15 (GEN) | 670 |
| 5962-9317705QNC | E | 10/02/2003 | 2 | ATMEL NANTES | | Y | MMDP-672061FV-30MQ | 670 |
| 5962-9317705VNC | E | 10/02/2003 | 2 | ATMEL NANTES | | Y | SMDP-672061FV-30SV | 670 |
| 5962D9317705VNC | E | 10/02/2003 | 2 | ATMEL NANTES | | Y | SMDP-672061FV-30SR | 670 |
| 5962-9317705QTC | E | 10/02/2003 | 2 | ATMEL NANTES | | Y | MMCP-672061FV-30MQ | 670 |
| 5962-9317705VTC | E | 10/02/2003 | 2 | ATMEL NANTES | | Y | SMCP-672061FV-30SV | 670 |
| 5962D9317705VTC | E | 10/02/2003 | 2 | ATMEL NANTES | | Y | SMCP-672061FV-30SR | 670 |
| 5962-9317705QUC | E | 10/02/2003 | | (NONE) | | | 672061-30 (GEN) | 670 |
| 5962-9317705VUC | E | 10/02/2003 | | (NONE) | | | 672061-30 (GEN) | 670 |
| 5962-9317705QZC | E | 10/02/2003 | | (NONE) | | | 672061-30 (GEN) | 670 |
| 5962-9317705VZC | E | 10/02/2003 | | (NONE) | | | 672061-30 (GEN) | 670 |
| 5962-9317706QNC | E | 10/02/2003 | 2 | ATMEL NANTES | | Y | MMDP-672061FV-15MQ | 670 |
| 5962-9317706VNC | E | 10/02/2003 | 2 | ATMEL NANTES | | Y | SMDP-672061FV-15SV | 670 |
| 5962D9317706VNC | E | 10/02/2003 | 2 | ATMEL NANTES | | Y | SMDP-672061FV-15SR | 670 |
| 5962-9317706QTC | E | 10/02/2003 | 2 | ATMEL NANTES | | Y | MMCP-672061FV-15MQ | 670 |
| 5962-9317706VTC | E | 10/02/2003 | 2 | ATMEL NANTES | | Y | SMCP-672061FV-15SV | 670 |
| 5962D9317706VTC | E | 10/02/2003 | 2 | ATMEL NANTES | | Y | SMCP-672061FV-15SR | 670 |
| 5962-9317706QUC | E | 10/02/2003 | | (NONE) | | | 672061-15 (GEN) | 670 |
| 5962-9317706VUC | E | 10/02/2003 | | (NONE) | | | 672061-15 (GEN) | 670 |
| 5962-9317706QZC | E | 10/02/2003 | | (NONE) | | | 672061-15 (GEN) | 670 |
| 5962-9317706VZC | E | 10/02/2003 | | (NONE) | | | 672061-15 (GEN) | 670 |
| 5962-9317707QNC | E | 10/02/2003 | 2 | ATMEL NANTES | | Y | MMDP-67206HV-30MQ | 670 |
| 5962-9317707VNC | E | 10/02/2003 | 2 | ATMEL NANTES | | Y | SMDP-67206HV-30SV | 670 |
| 5962D9317707VNC | E | 10/02/2003 | 2 | ATMEL NANTES | | Y | SMDP-67206HV-30SR | 670 |
| 5962-9317707QTC | E | 10/02/2003 | 2 | ATMEL NANTES | | Y | MMCP-67206HV-30MQ | 670 |
| 5962-9317707VTC | E | 10/02/2003 | 2 | ATMEL NANTES | | Y | SMCP-67206HV-30SV | 670 |
| 5962D9317707VTC | E | 10/02/2003 | 2 | ATMEL NANTES | | Y | SMCP-67206HV-30SR | 670 |
| 5962-9317708QNC | E | 10/02/2003 | 2 | ATMEL NANTES | | Y | MMDP-67206HV-15MQ | 670 |
| 5962-9317708VNC | E | 10/02/2003 | 2 | ATMEL NANTES | | Y | SMDP-67206HV-15SV | 670 |
| 5962D9317708VNC | E | 10/02/2003 | 2 | ATMEL NANTES | | Y | SMDP-67206HV-15SR | 670 |
| 5962-9317708QTC | E | 10/02/2003 | 2 | ATMEL NANTES | | Y | MMCP-67206HV-15MQ | 670 |
| 5962-9317708VTC | E | 10/02/2003 | 2 | ATMEL NANTES | | Y | SMCP-67206HV-15SV | 670 |
| 5962D9317708VTC | E | 10/02/2003 | 2 | ATMEL NANTES | | Y | SMCP-67206HV-15SR | 670 |
| 5962-9317709QNC | E | 10/02/2003 | 2 | ATMEL NANTES | | Y | MMDP-672061HV-30M | 670 |
| 5962-9317709VNC | E | 10/02/2003 | 2 | ATMEL NANTES | | Y | SMDP-672061HV-30SV | 670 |
| 5962D9317709VNC | E | 10/02/2003 | 2 | ATMEL NANTES | | Y | SMDP-672061HV-30SR | 670 |
| 5962-9317709QTC | E | 10/02/2003 | 2 | ATMEL NANTES | | Y | MMCP-672061HV-30M | 670 |
| 5962-9317709VTC | E | 10/02/2003 | 2 | ATMEL NANTES | | Y | SMCP-672061HV-30SV | 670 |
| 5962D9317709VTC | E | 10/02/2003 | 2 | ATMEL NANTES | | Y | SMCP-672061HV-30SR | 670 |
| 5962-9317710QNC | E | 10/02/2003 | 2 | ATMEL NANTES | | Y | MMDP-672061HV-15M | 670 |
| 5962-9317710VNC | E | 10/02/2003 | 2 | ATMEL NANTES | | Y | SMDP-672061HV-15SV | 670 |
| 5962D9317710VNC | E | 10/02/2003 | 2 | ATMEL NANTES | | Y | SMDP-672061HV-15SR | 670 |
| 5962-9317710QTC | E | 10/02/2003 | 2 | ATMEL NANTES | | Y | MMCP-672061HV-15M | 670 |
| 5962-9317710VTC | E | 10/02/2003 | 2 | ATMEL NANTES | | Y | SMCP-672061HV-15SV | 670 |
| 5962D9317710VTC | E | 10/02/2003 | 2 | ATMEL NANTES | | Y | SMCP-672061HV-15SR | 670 |
| 5962-9317801MZA | A | 01/10/1995 | | (NONE) | | | MRG064-128 (GEN) | 899 |
| 5962-9317901MLA | B | 04/11/2002 | 1 | ANALOG (3) | | Y | AD7876TQ/883B | 592 |
| 5962-9318001MRA | A | 04/15/2002 | 1 | MAXIM INTEG. | | | MAX333MJP/883B | 199 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9318201M2A | D | 01/08/2003 | 3 | TI | | Y | TLC2274MFKB | 713 |
| 5962-9318201MCA | D | 01/08/2003 | 3 | TI | | Y | TLC2274MJB | 713 |
| 5962-9318201QDA | D | 01/08/2003 | 3 | TI | | Y | TLC2274MWB | 713 |
| 5962-9318202Q2A | D | 01/08/2003 | 3 | TI | | Y | TLC2274AMFKB | 713 |
| 5962-9318202QCA | D | 01/08/2003 | 3 | TI | | Y | TLC2274AMJB | 713 |
| 5962-9318202QDA | D | 01/08/2003 | 3 | TI | | Y | TLC2274AMWB | 713 |
| 5962-9318301Q2A | C | 04/30/2002 | 2 | TI | | Y | SNJ55LBC176FK | 590 |
| 5962-9318301QPA | C | 04/30/2002 | 2 | TI | | Y | SNJ55LBC176JG | 590 |
| 5962-9318401MPA | A | 11/18/1993 | | (NONE) | 03/30/2001 | | LT1229 (GEN) | 752 |
| 5962-9318402MCA | A | 11/18/1993 | | (NONE) | 03/30/2001 | | LT1230 (GEN) | 752 |
| 5962-9318601M3A | A | 03/11/1994 | 1 | TI | | Y | SNJ54ABT8245FK | 399 |
| 5962-9318601MLA | A | 03/11/1994 | 1 | TI | | Y | SNJ54ABT8245JT | 399 |
| 5962-9318701H4C | K | 11/13/2001 | 1 | WHITE ELEC. | | Y | WS128K32N-120H1Q | 629 |
| 5962-9318701H5A | K | 11/13/2001 | 1 | WHITE ELEC. | | Y | WS128K32-120H1Q | 629 |
| 5962-9318701H5C | K | 11/13/2001 | 1 | WHITE ELEC. | | Y | WS128K32-120H1Q | 629 |
| 5962-9318701HTA | K | 11/13/2001 | | (NONE) | | | 128K32-120 (GEN) | 629 |
| 5962-9318701HUA | K | 11/13/2001 | | (NONE) | | | 128K32-120 (GEN) | 629 |
| 5962-9318701HXA | K | 11/13/2001 | | (NONE) | | | 128K32-120 (GEN) | 629 |
| 5962-9318701HYA | K | 11/13/2001 | | (NONE) | | | 128K32-120 (GEN) | 629 |
| 5962-9318702H4A | K | 11/13/2001 | 1 | WHITE ELEC. | | Y | WS128K32N-100H1Q | 629 |
| 5962-9318702H4C | K | 11/13/2001 | 1 | WHITE ELEC. | | Y | WS128K32N-100H1Q | 629 |
| 5962-9318702H5A | K | 11/13/2001 | 1 | WHITE ELEC. | | Y | WS128K32-100H1Q | 629 |
| 5962-9318702H5C | K | 11/13/2001 | 1 | WHITE ELEC. | | Y | WS128K32-100H1Q | 629 |
| 5962-9318702HTA | K | 11/13/2001 | | (NONE) | | | 128K32-100 (GEN) | 629 |
| 5962-9318702HUA | K | 11/13/2001 | | (NONE) | | | 128K32-100 (GEN) | 629 |
| 5962-9318702HXA | K | 11/13/2001 | | (NONE) | | | 128K32-100 (GEN) | 629 |
| 5962-9318702HYA | K | 11/13/2001 | | (NONE) | | | 128K32-100 (GEN) | 629 |
| 5962-9318703H4A | K | 11/13/2001 | 1 | WHITE ELEC. | | Y | WS128K32N-85H1Q | 629 |
| 5962-9318703H4C | K | 11/13/2001 | 1 | WHITE ELEC. | | Y | WS128K32N-85H1Q | 629 |
| 5962-9318703H5A | K | 11/13/2001 | 1 | WHITE ELEC. | | Y | WS128K32-85H1Q | 629 |
| 5962-9318703H5C | K | 11/13/2001 | 1 | WHITE ELEC. | | Y | WS128K32-85H1Q | 629 |
| 5962-9318703HTA | K | 11/13/2001 | | (NONE) | | | 128K32-85 (GEN) | 629 |
| 5962-9318703HUA | K | 11/13/2001 | | (NONE) | | | 128K32-85 (GEN) | 629 |
| 5962-9318703HXA | K | 11/13/2001 | | (NONE) | | | 128K32-85 (GEN) | 629 |
| 5962-9318703HYA | K | 11/13/2001 | | (NONE) | | | 128K32-85 (GEN) | 629 |
| 5962-9318704H4A | K | 11/13/2001 | 1 | WHITE ELEC. | | Y | WS128K32N-70H1Q | 629 |
| 5962-9318704H4C | K | 11/13/2001 | 1 | WHITE ELEC. | | Y | WS128K32N-70H1Q | 629 |
| 5962-9318704H5A | K | 11/13/2001 | 1 | WHITE ELEC. | | Y | WS128K32-70H1Q | 629 |
| 5962-9318704H5C | K | 11/13/2001 | 1 | WHITE ELEC. | | Y | WS128K32-70H1Q | 629 |
| 5962-9318704HTA | K | 11/13/2001 | | (NONE) | | | 128K32-70 (GEN) | 629 |
| 5962-9318704HUA | K | 11/13/2001 | | (NONE) | | | 128K32-70 (GEN) | 629 |
| 5962-9318704HXA | K | 11/13/2001 | | (NONE) | | | 128K32-70 (GEN) | 629 |
| 5962-9318704HYA | K | 11/13/2001 | | (NONE) | | | 128K32-70 (GEN) | 629 |
| 5962-9318705H4A | K | 11/13/2001 | 1 | AUSTIN SEMI. | | Y | AS8S128K32PN-55/883 | 629 |
| 5962-9318705H4A | K | 11/13/2001 | 1 | WHITE ELEC. | | Y | WS128K32N-55H1Q | 629 |
| 5962-9318705H4C | K | 11/13/2001 | 1 | AUSTIN SEMI. | | Y | AS8S128K32PN-55/883 | 629 |
| 5962-9318705H4C | K | 11/13/2001 | 1 | WHITE ELEC. | | Y | WS128K32N-55H1Q | 629 |
| 5962-9318705H5A | K | 11/13/2001 | 1 | AUSTIN SEMI. | | Y | AS8S128K32P-55/883C | 629 |
| 5962-9318705H5A | K | 11/13/2001 | 1 | WHITE ELEC. | | Y | WS128K32-55H1Q | 629 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9318705H5C | K | 11/13/2001 | 1 | AUSTIN SEMI. | | Y | AS8S128K32P-55/883C | 629 |
| 5962-9318705H5C | K | 11/13/2001 | 1 | WHITE ELEC. | | Y | WS128K32-55H1Q | 629 |
| 5962-9318705HMA | K | 11/13/2001 | | (NONE) | | | 128K32-55 (GEN) | 629 |
| 5962-9318705HNA | K | 11/13/2001 | | (NONE) | | | 128K32-55 (GEN) | 629 |
| 5962-9318705HTA | K | 11/13/2001 | | (NONE) | | | 128K32-55 (GEN) | 629 |
| 5962-9318705HUA | K | 11/13/2001 | | (NONE) | | | 128K32-55 (GEN) | 629 |
| 5962-9318705HXA | K | 11/13/2001 | | (NONE) | | | 128K32-55 (GEN) | 629 |
| 5962-9318705HYA | K | 11/13/2001 | | (NONE) | | | 128K32-55 (GEN) | 629 |
| 5962-9318706H4A | K | 11/13/2001 | 1 | AUSTIN SEMI. | | Y | AS8S128K32PN-45/883 | 629 |
| 5962-9318706H4A | K | 11/13/2001 | 1 | WHITE ELEC. | | Y | WS128K32N-45H1Q | 629 |
| 5962-9318706H4C | K | 11/13/2001 | 1 | AUSTIN SEMI. | | Y | AS8S128K32PN-45/883 | 629 |
| 5962-9318706H4C | K | 11/13/2001 | 1 | WHITE ELEC. | | Y | WS128K32N-45H1Q | 629 |
| 5962-9318706H5A | K | 11/13/2001 | 1 | AUSTIN SEMI. | | Y | AS8S128K32P-45/883C | 629 |
| 5962-9318706H5A | K | 11/13/2001 | 1 | WHITE ELEC. | | Y | WS128K32-45H1Q | 629 |
| 5962-9318706H5C | K | 11/13/2001 | 1 | AUSTIN SEMI. | | Y | AS8S128K32P-45/883C | 629 |
| 5962-9318706H5C | K | 11/13/2001 | 1 | WHITE ELEC. | | Y | WS128K32-45H1Q | 629 |
| 5962-9318706HMA | K | 11/13/2001 | | (NONE) | | | 128K32-45 (GEN) | 629 |
| 5962-9318706HNA | K | 11/13/2001 | | (NONE) | | | 128K32-45 (GEN) | 629 |
| 5962-9318706HTA | K | 11/13/2001 | | (NONE) | | | 128K32-45 (GEN) | 629 |
| 5962-9318706HUA | K | 11/13/2001 | | (NONE) | | | 128K32-45 (GEN) | 629 |
| 5962-9318706HXA | K | 11/13/2001 | | (NONE) | | | 128K32-45 (GEN) | 629 |
| 5962-9318706HYA | K | 11/13/2001 | | (NONE) | | | 128K32-45 (GEN) | 629 |
| 5962-9318707H4A | K | 11/13/2001 | 1 | AUSTIN SEMI. | | Y | AS8S128K32PN-35/883 | 629 |
| 5962-9318707H4A | K | 11/13/2001 | 1 | WHITE ELEC. | | Y | WS128K32N-35H1Q | 629 |
| 5962-9318707H4C | K | 11/13/2001 | 1 | AUSTIN SEMI. | | Y | AS8S128K32PN-35/883 | 629 |
| 5962-9318707H4C | K | 11/13/2001 | 1 | WHITE ELEC. | | Y | WS128K32N-35H1Q | 629 |
| 5962-9318707H5A | K | 11/13/2001 | 1 | AUSTIN SEMI. | | Y | AS8S128K32P-35/883C | 629 |
| 5962-9318707H5A | K | 11/13/2001 | 1 | WHITE ELEC. | | Y | WS128K32-35H1Q | 629 |
| 5962-9318707H5C | K | 11/13/2001 | 1 | AUSTIN SEMI. | | Y | AS8S128K32P-35/883C | 629 |
| 5962-9318707H5C | K | 11/13/2001 | 1 | WHITE ELEC. | | Y | WS128K32-35H1Q | 629 |
| 5962-9318707HMA | K | 11/13/2001 | | (NONE) | | | 128K32-35 (GEN) | 629 |
| 5962-9318707HNA | K | 11/13/2001 | | (NONE) | | | 128K32-35 (GEN) | 629 |
| 5962-9318707HTA | K | 11/13/2001 | | (NONE) | | | 128K32-35 (GEN) | 629 |
| 5962-9318707HUA | K | 11/13/2001 | | (NONE) | | | 128K32-35 (GEN) | 629 |
| 5962-9318707HXA | K | 11/13/2001 | | (NONE) | | | 128K32-35 (GEN) | 629 |
| 5962-9318707HYA | K | 11/13/2001 | | (NONE) | | | 128K32-35 (GEN) | 629 |
| 5962-9318708H4A | K | 11/13/2001 | 1 | AUSTIN SEMI. | | Y | AS8S128K32PN-25/883 | 629 |
| 5962-9318708H4A | K | 11/13/2001 | 1 | WHITE ELEC. | | Y | WS128K32N-25H1Q | 629 |
| 5962-9318708H4C | K | 11/13/2001 | 1 | AUSTIN SEMI. | | Y | AS8S128K32PN-25/883 | 629 |
| 5962-9318708H4C | K | 11/13/2001 | 1 | WHITE ELEC. | | Y | WS128K32N-25H1Q | 629 |
| 5962-9318708H5A | K | 11/13/2001 | 1 | AUSTIN SEMI. | | Y | AS8S128K32P-25/883C | 629 |
| 5962-9318708H5A | K | 11/13/2001 | 1 | WHITE ELEC. | | Y | WS128K32-25H1Q | 629 |
| 5962-9318708H5C | K | 11/13/2001 | 1 | AUSTIN SEMI. | | Y | AS8S128K32P-25/883C | 629 |
| 5962-9318708H5C | K | 11/13/2001 | 1 | WHITE ELEC. | | Y | WS128K32-25H1Q | 629 |
| 5962-9318708HMA | K | 11/13/2001 | | (NONE) | | | 128K32-25 (GEN) | 629 |
| 5962-9318708HNA | K | 11/13/2001 | | (NONE) | | | 128K32-25 (GEN) | 629 |
| 5962-9318708HTC | K | 11/13/2001 | | (NONE) | | | 128K32-25 (GEN) | 629 |
| 5962-9318708HUA | K | 11/13/2001 | | (NONE) | | | 128K32-25 (GEN) | 629 |
| 5962-9318708HXA | K | 11/13/2001 | | (NONE) | | | 128K32-25 (GEN) | 629 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9318708HYA | K | 11/13/2001 | | (NONE) | | | 128K32-25 (GEN) | 629 |
| 5962-9318709H4A | K | 11/13/2001 | 1 | AUSTIN SEMI. | | Y | AS8S128K32PN-20/883 | 629 |
| 5962-9318709H4A | K | 11/13/2001 | 1 | WHITE ELEC. | | Y | WS128K32N-20H1Q | 629 |
| 5962-9318709H4C | K | 11/13/2001 | 1 | AUSTIN SEMI. | | Y | AS8S128K32PN-20/883 | 629 |
| 5962-9318709H4C | K | 11/13/2001 | 1 | WHITE ELEC. | | Y | WS128K32N-20H1Q | 629 |
| 5962-9318709H5A | K | 11/13/2001 | 1 | AUSTIN SEMI. | | Y | AS8S128K32P-20/883C | 629 |
| 5962-9318709H5A | K | 11/13/2001 | 1 | WHITE ELEC. | | Y | WS128K32-20H1Q | 629 |
| 5962-9318709H5C | K | 11/13/2001 | 1 | AUSTIN SEMI. | | Y | AS8S128K32P-20/883C | 629 |
| 5962-9318709H5C | K | 11/13/2001 | 1 | WHITE ELEC. | | Y | WS128K32-20H1Q | 629 |
| 5962-9318709HMA | K | 11/13/2001 | | (NONE) | | | 128K32-20 (GEN) | 629 |
| 5962-9318709HNA | K | 11/13/2001 | | (NONE) | | | 128K32-20 (GEN) | 629 |
| 5962-9318709HTA | K | 11/13/2001 | | (NONE) | | | 128K32-20 (GEN) | 629 |
| 5962-9318709HUA | K | 11/13/2001 | | (NONE) | | | 128K32-20 (GEN) | 629 |
| 5962-9318709HXA | K | 11/13/2001 | | (NONE) | | | 128K32-20 (GEN) | 629 |
| 5962-9318709HYA | K | 11/13/2001 | | (NONE) | | | 128K32-20 (GEN) | 629 |
| 5962-9318710H4A | K | 11/13/2001 | 1 | AUSTIN SEMI. | | Y | AS8S128K32PN-17/883 | 629 |
| 5962-9318710H4A | K | 11/13/2001 | 1 | WHITE ELEC. | | Y | WS128K32N-17H1Q | 629 |
| 5962-9318710H4C | K | 11/13/2001 | 1 | AUSTIN SEMI. | | Y | AS8S128K32PN-17/883 | 629 |
| 5962-9318710H4C | K | 11/13/2001 | 1 | WHITE ELEC. | | Y | WS128K32N-17H1Q | 629 |
| 5962-9318710H5A | K | 11/13/2001 | 1 | AUSTIN SEMI. | | Y | AS8S128K32P-17/883C | 629 |
| 5962-9318710H5A | K | 11/13/2001 | 1 | WHITE ELEC. | | Y | WS128K32-17H1Q | 629 |
| 5962-9318710H5C | K | 11/13/2001 | 1 | AUSTIN SEMI. | | Y | AS8S128K32P-17/883C | 629 |
| 5962-9318710H5C | K | 11/13/2001 | 1 | WHITE ELEC. | | Y | WS128K32-17H1Q | 629 |
| 5962-9318710HMA | K | 11/13/2001 | | (NONE) | | | 128K32-17 (GEN) | 629 |
| 5962-9318710HNA | K | 11/13/2001 | | (NONE) | | | 128K32-17 (GEN) | 629 |
| 5962-9318710HTA | K | 11/13/2001 | | (NONE) | | | 128K32-17 (GEN) | 629 |
| 5962-9318710HUA | K | 11/13/2001 | | (NONE) | | | 128K32-17 (GEN) | 629 |
| 5962-9318710HXA | K | 11/13/2001 | | (NONE) | | | 128K32-17 (GEN) | 629 |
| 5962-9318710HYA | K | 11/13/2001 | | (NONE) | | | 128K32-17 (GEN) | 629 |
| 5962-9318711H4A | K | 11/13/2001 | 1 | WHITE ELEC. | | Y | WS128K32N-15H1Q | 629 |
| 5962-9318711H4C | K | 11/13/2001 | 1 | WHITE ELEC. | | Y | WS128K32N-15H1Q | 629 |
| 5962-9318711H5A | K | 11/13/2001 | 1 | WHITE ELEC. | | Y | WS128K32-15H1Q | 629 |
| 5962-9318711H5C | K | 11/13/2001 | 1 | WHITE ELEC. | | Y | WS128K32-15H1Q | 629 |
| 5962-9318712H4A | K | 11/13/2001 | 1 | AEROFLEX | | Y | ACT-S128K32N-055P7 | 629 |
| 5962-9318712H4A | K | 11/13/2001 | 1 | AUSTIN SEMI. | | Y | AS8S128K32PN-55/883 | 629 |
| 5962-9318712H4A | K | 11/13/2001 | 1 | WHITE ELEC. | | Y | WS128K32NH-55H1Q | 629 |
| 5962-9318712H4C | K | 11/13/2001 | 1 | AEROFLEX | | Y | ACT-S128K32N-055P7 | 629 |
| 5962-9318712H4C | K | 11/13/2001 | 1 | AUSTIN SEMI. | | Y | AS8S128K32PN-55/883 | 629 |
| 5962-9318712H4C | K | 11/13/2001 | 1 | WHITE ELEC. | | Y | WS128K32NH-55H1Q | 629 |
| 5962-9318712H5A | K | 11/13/2001 | 1 | AEROFLEX | | Y | ACT-S128K32C-055P7 | 629 |
| 5962-9318712H5A | K | 11/13/2001 | 1 | AUSTIN SEMI. | | Y | AS8S128K32P-55/883C | 629 |
| 5962-9318712H5A | K | 11/13/2001 | 1 | WHITE ELEC. | | Y | WS128K32H-55H1Q | 629 |
| 5962-9318712H5C | K | 11/13/2001 | 1 | AEROFLEX | | Y | ACT-S128K32C-055P7 | 629 |
| 5962-9318712H5C | K | 11/13/2001 | 1 | AUSTIN SEMI. | | Y | AS8S128K32P-55/883C | 629 |
| 5962-9318712H5C | K | 11/13/2001 | 1 | WHITE ELEC. | | Y | WS128K32H-55H1Q | 629 |
| 5962-9318712HMA | K | 11/13/2001 | 1 | AEROFLEX | | Y | ACT-S128K32N-055P3 | 629 |
| 5962-9318712HMC | K | 11/13/2001 | 1 | AEROFLEX | | Y | ACT-S128K32N-055P3 | 629 |
| 5962-9318712HNA | K | 11/13/2001 | 1 | AEROFLEX | | Y | ACT-S128K32C-055P3 | 629 |
| 5962-9318712HNC | K | 11/13/2001 | 1 | AEROFLEX | | Y | ACT-S128K32C-055P3 | 629 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9318712HTA | K | 11/13/2001 | 1 | AEROFLEX | | Y | ACT-S128K32N-055P2 | 629 |
| 5962-9318712HTC | K | 11/13/2001 | 1 | AEROFLEX | | Y | ACT-S128K32N-055P2 | 629 |
| 5962-9318712HUA | K | 11/13/2001 | 1 | AEROFLEX | | Y | ACT-S128K32N-055P6 | 629 |
| 5962-9318712HUC | K | 11/13/2001 | 1 | AEROFLEX | | Y | ACT-S128K32N-055P6 | 629 |
| 5962-9318712HXA | K | 11/13/2001 | 1 | AEROFLEX | | Y | ACT-S128K32C-055P2 | 629 |
| 5962-9318712HXC | K | 11/13/2001 | 1 | AEROFLEX | | Y | ACT-S128K32C-055P2 | 629 |
| 5962-9318713H4A | K | 11/13/2001 | 1 | AEROFLEX | | Y | ACT-S128K32N-045P7 | 629 |
| 5962-9318713H4A | K | 11/13/2001 | 1 | AUSTIN SEMI. | | Y | AS8S128K32P-45/883C | 629 |
| 5962-9318713H4A | K | 11/13/2001 | 1 | WHITE ELEC. | | Y | WS128K32NH-45H1Q | 629 |
| 5962-9318713H4C | K | 11/13/2001 | 1 | AEROFLEX | | Y | ACT-S128K32N-045P7 | 629 |
| 5962-9318713H4C | K | 11/13/2001 | 1 | AUSTIN SEMI. | | Y | AS8S128K32P-45/883C | 629 |
| 5962-9318713H4C | K | 11/13/2001 | 1 | WHITE ELEC. | | Y | WS128K32NH-45H1Q | 629 |
| 5962-9318713H5A | K | 11/13/2001 | 1 | AEROFLEX | | Y | ACT-S128K32C-045P7 | 629 |
| 5962-9318713H5A | K | 11/13/2001 | 1 | AUSTIN SEMI. | | Y | AS8S128K32P-45/883C | 629 |
| 5962-9318713H5A | K | 11/13/2001 | 1 | WHITE ELEC. | | Y | WS128K32H-45H1Q | 629 |
| 5962-9318713H5C | K | 11/13/2001 | 1 | AEROFLEX | | Y | ACT-S128K32C-045P7 | 629 |
| 5962-9318713H5C | K | 11/13/2001 | 1 | AUSTIN SEMI. | | Y | AS8S128K32P-45/883C | 629 |
| 5962-9318713H5C | K | 11/13/2001 | 1 | WHITE ELEC. | | Y | WS128K32H-45H1Q | 629 |
| 5962-9318713HMA | K | 11/13/2001 | 1 | AEROFLEX | | Y | ACT-S128K32N-045P3 | 629 |
| 5962-9318713HMC | K | 11/13/2001 | 1 | AEROFLEX | | Y | ACT-S128K32N-045P3 | 629 |
| 5962-9318713HNA | K | 11/13/2001 | 1 | AEROFLEX | | Y | ACT-S128K32C-045P3 | 629 |
| 5962-9318713HNC | K | 11/13/2001 | 1 | AEROFLEX | | Y | ACT-S128K32C-045P3 | 629 |
| 5962-9318713HTA | K | 11/13/2001 | 1 | AEROFLEX | | Y | ACT-S128K32N-045P2 | 629 |
| 5962-9318713HTC | K | 11/13/2001 | 1 | AEROFLEX | | Y | ACT-S128K32N-045P2 | 629 |
| 5962-9318713HUA | K | 11/13/2001 | 1 | AEROFLEX | | Y | ACT-S128K32N-045P6 | 629 |
| 5962-9318713HUC | K | 11/13/2001 | 1 | AEROFLEX | | Y | ACT-S128K32N-045P6 | 629 |
| 5962-9318713HXA | K | 11/13/2001 | 1 | AEROFLEX | | Y | ACT-S128K32C-045P2 | 629 |
| 5962-9318713HXC | K | 11/13/2001 | 1 | AEROFLEX | | Y | ACT-S128K32C-045P2 | 629 |
| 5962-9318713HYA | K | 11/13/2001 | 1 | AEROFLEX | | Y | ACT-S128K32C-045P6 | 629 |
| 5962-9318713HYC | K | 11/13/2001 | 1 | AEROFLEX | | Y | ACT-S128K32C-045P6 | 629 |
| 5962-9318714H4A | K | 11/13/2001 | 1 | AEROFLEX | | Y | ACT-S128K32N-035P7 | 629 |
| 5962-9318714H4A | K | 11/13/2001 | 1 | AUSTIN SEMI. | | Y | AS8S128K32PN-35/883 | 629 |
| 5962-9318714H4A | K | 11/13/2001 | 1 | WHITE ELEC. | | Y | WS128K32NH-35H1Q | 629 |
| 5962-9318714H4C | K | 11/13/2001 | 1 | AEROFLEX | | Y | ACT-S128K32N-035P7 | 629 |
| 5962-9318714H4C | K | 11/13/2001 | 1 | AUSTIN SEMI. | | Y | AS8S128K32PN-35/883 | 629 |
| 5962-9318714H4C | K | 11/13/2001 | 1 | WHITE ELEC. | | Y | WS128K32NH-35H1Q | 629 |
| 5962-9318714H5A | K | 11/13/2001 | 1 | AEROFLEX | | Y | ACT-S128K32C-035P7 | 629 |
| 5962-9318714H5A | K | 11/13/2001 | 1 | AUSTIN SEMI. | | Y | AS8S128K32P-35/883C | 629 |
| 5962-9318714H5A | K | 11/13/2001 | 1 | WHITE ELEC. | | Y | WS128K32H-35H1Q | 629 |
| 5962-9318714H5C | K | 11/13/2001 | 1 | AEROFLEX | | Y | ACT-S128K32C-035P7 | 629 |
| 5962-9318714H5C | K | 11/13/2001 | 1 | AUSTIN SEMI. | | Y | AS8S128K32P-35/883C | 629 |
| 5962-9318714H5C | K | 11/13/2001 | 1 | WHITE ELEC. | | Y | WS128K32H-35H1Q | 629 |
| 5962-9318714HMA | K | 11/13/2001 | 1 | AEROFLEX | | Y | ACT-S128K32N-035P3 | 629 |
| 5962-9318714HMC | K | 11/13/2001 | 1 | AEROFLEX | | Y | ACT-S128K32N-035P3 | 629 |
| 5962-9318714HNA | K | 11/13/2001 | 1 | AEROFLEX | | Y | ACT-S128K32C-035P3 | 629 |
| 5962-9318714HNC | K | 11/13/2001 | 1 | AEROFLEX | | Y | ACT-S128K32C-035P3 | 629 |
| 5962-9318714HTA | K | 11/13/2001 | 1 | AEROFLEX | | Y | ACT-S128K32N-035P2 | 629 |
| 5962-9318714HTC | K | 11/13/2001 | 1 | AEROFLEX | | Y | ACT-S128K32N-035P2 | 629 |
| 5962-9318714HUA | K | 11/13/2001 | 1 | AEROFLEX | | Y | ACT-S128K32N-035P6 | 629 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9318714HUC | K | 11/13/2001 | 1 | AEROFLEX | | Y | ACT-S128K32N-035P6 | 629 |
| 5962-9318714HXA | K | 11/13/2001 | 1 | AEROFLEX | | Y | ACT-S128K32C-035P2 | 629 |
| 5962-9318714HXC | K | 11/13/2001 | 1 | AEROFLEX | | Y | ACT-S128K32C-035P2 | 629 |
| 5962-9318714HYA | K | 11/13/2001 | 1 | AEROFLEX | | Y | ACT-S128K32C-035P6 | 629 |
| 5962-9318714HYC | K | 11/13/2001 | 1 | AEROFLEX | | Y | ACT-S128K32C-035P6 | 629 |
| 5962-9318715H4A | K | 11/13/2001 | 1 | AEROFLEX | | Y | ACT-S128K32N-025P7 | 629 |
| 5962-9318715H4A | K | 11/13/2001 | 1 | AUSTIN SEMI. | | Y | AS8S128K32PN-25/883 | 629 |
| 5962-9318715H4A | K | 11/13/2001 | 1 | WHITE ELEC. | | Y | WS128K32NH-25H1Q | 629 |
| 5962-9318715H4C | K | 11/13/2001 | 1 | AEROFLEX | | Y | ACT-S128K32N-025P7 | 629 |
| 5962-9318715H4C | K | 11/13/2001 | 1 | AUSTIN SEMI. | | Y | AS8S128K32PN-25/883 | 629 |
| 5962-9318715H4C | K | 11/13/2001 | 1 | WHITE ELEC. | | Y | WS128K32NH-25H1Q | 629 |
| 5962-9318715H5A | K | 11/13/2001 | 1 | AEROFLEX | | Y | ACT-S128K32C-025P7 | 629 |
| 5962-9318715H5A | K | 11/13/2001 | 1 | AUSTIN SEMI. | | Y | AS8S128K32P-25/883C | 629 |
| 5962-9318715H5A | K | 11/13/2001 | 1 | WHITE ELEC. | | Y | WS128K32H-25H1Q | 629 |
| 5962-9318715H5C | K | 11/13/2001 | 1 | AEROFLEX | | Y | ACT-S128K32C-025P7 | 629 |
| 5962-9318715H5C | K | 11/13/2001 | 1 | AUSTIN SEMI. | | Y | AS8S128K32P-25/883C | 629 |
| 5962-9318715H5C | K | 11/13/2001 | 1 | WHITE ELEC. | | Y | WS128K32H-25H1Q | 629 |
| 5962-9318715HMA | K | 11/13/2001 | 1 | AEROFLEX | | Y | ACT-S128K32N-025P3 | 629 |
| 5962-9318715HMC | K | 11/13/2001 | 1 | AEROFLEX | | Y | ACT-S128K32N-025P3 | 629 |
| 5962-9318715HNA | K | 11/13/2001 | 1 | AEROFLEX | | Y | ACT-S128K32C-025P3 | 629 |
| 5962-9318715HNC | K | 11/13/2001 | 1 | AEROFLEX | | Y | ACT-S128K32C-025P3 | 629 |
| 5962-9318715HTA | K | 11/13/2001 | 1 | AEROFLEX | | Y | ACT-S128K32N-025P2 | 629 |
| 5962-9318715HTC | K | 11/13/2001 | 1 | AEROFLEX | | Y | ACT-S128K32N-025P2 | 629 |
| 5962-9318715HUA | K | 11/13/2001 | 1 | AEROFLEX | | Y | ACT-S128K32N-025P6 | 629 |
| 5962-9318715HUC | K | 11/13/2001 | 1 | AEROFLEX | | Y | ACT-S128K32N-025P6 | 629 |
| 5962-9318715HXA | K | 11/13/2001 | 1 | AEROFLEX | | Y | ACT-S128K32C-025P2 | 629 |
| 5962-9318715HXC | K | 11/13/2001 | 1 | AEROFLEX | | Y | ACT-S128K32C-025P2 | 629 |
| 5962-9318715HYA | K | 11/13/2001 | 1 | AEROFLEX | | Y | ACT-S128K32C-025P6 | 629 |
| 5962-9318715HYC | K | 11/13/2001 | 1 | AEROFLEX | | Y | ACT-S128K32C-025P6 | 629 |
| 5962-9318716H4A | K | 11/13/2001 | 1 | AEROFLEX | | Y | ACT-S128K32N-020P7 | 629 |
| 5962-9318716H4A | K | 11/13/2001 | 1 | AUSTIN SEMI. | | Y | AS8S128K32PN-20/883 | 629 |
| 5962-9318716H4A | K | 11/13/2001 | 1 | WHITE ELEC. | | Y | WS128K32NH-20H1Q | 629 |
| 5962-9318716H4C | K | 11/13/2001 | 1 | AEROFLEX | | Y | ACT-S128K32N-020P7 | 629 |
| 5962-9318716H4C | K | 11/13/2001 | 1 | AUSTIN SEMI. | | Y | AS8S128K32PN-20/883 | 629 |
| 5962-9318716H4C | K | 11/13/2001 | 1 | WHITE ELEC. | | Y | WS128K32NH-20H1Q | 629 |
| 5962-9318716H5A | K | 11/13/2001 | 1 | AEROFLEX | | Y | ACT-S128K32C-020P7 | 629 |
| 5962-9318716H5A | K | 11/13/2001 | 1 | AUSTIN SEMI. | | Y | AS8S128K32P-20/883C | 629 |
| 5962-9318716H5A | K | 11/13/2001 | 1 | WHITE ELEC. | | Y | WS128K32H-20H1Q | 629 |
| 5962-9318716H5C | K | 11/13/2001 | 1 | AEROFLEX | | Y | ACT-S128K32C-020P7 | 629 |
| 5962-9318716H5C | K | 11/13/2001 | 1 | AUSTIN SEMI. | | Y | AS8S128K32P-20/883C | 629 |
| 5962-9318716H5C | K | 11/13/2001 | 1 | WHITE ELEC. | | Y | WS128K32H-20H1Q | 629 |
| 5962-9318716HMA | K | 11/13/2001 | 1 | AEROFLEX | | Y | ACT-S128K32N-020P3 | 629 |
| 5962-9318716HMC | K | 11/13/2001 | 1 | AEROFLEX | | Y | ACT-S128K32N-020P3 | 629 |
| 5962-9318716HNA | K | 11/13/2001 | 1 | AEROFLEX | | Y | ACT-S128K32C-020P3 | 629 |
| 5962-9318716HNC | K | 11/13/2001 | 1 | AEROFLEX | | Y | ACT-S128K32C-020P3 | 629 |
| 5962-9318716HTA | K | 11/13/2001 | 1 | AEROFLEX | | Y | ACT-S128K32N-020P2 | 629 |
| 5962-9318716HTC | K | 11/13/2001 | 1 | AEROFLEX | | Y | ACT-S128K32N-020P2 | 629 |
| 5962-9318716HUA | K | 11/13/2001 | 1 | AEROFLEX | | Y | ACT-S128K32N-020P6 | 629 |
| 5962-9318716HUC | K | 11/13/2001 | 1 | AEROFLEX | | Y | ACT-S128K32N-020P6 | 629 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9318716HXA | K | 11/13/2001 | 1 | AEROFLEX | | Y | ACT-S128K32C-020P2 | 629 |
| 5962-9318716HXC | K | 11/13/2001 | 1 | AEROFLEX | | Y | ACT-S128K32C-020P2 | 629 |
| 5962-9318716HYA | K | 11/13/2001 | 1 | AEROFLEX | | Y | ACT-S128K32C-020P6 | 629 |
| 5962-9318716HYC | K | 11/13/2001 | 1 | AEROFLEX | | Y | ACT-S128K32C-020P6 | 629 |
| 5962-9318717H4A | K | 11/13/2001 | 1 | AEROFLEX | | Y | ACT-S128K32N-017P7 | 629 |
| 5962-9318717H4A | K | 11/13/2001 | 1 | AUSTIN SEMI. | | Y | AS8S128K32PN-17/883 | 629 |
| 5962-9318717H4A | K | 11/13/2001 | 1 | WHITE ELEC. | | Y | WS128K32NH-17H1Q | 629 |
| 5962-9318717H4C | K | 11/13/2001 | 1 | AEROFLEX | | Y | ACT-S128K32N-017P7 | 629 |
| 5962-9318717H4C | K | 11/13/2001 | 1 | AUSTIN SEMI. | | Y | AS8S128K32PN-17/883 | 629 |
| 5962-9318717H4C | K | 11/13/2001 | 1 | WHITE ELEC. | | Y | WS128K32NH-17H1Q | 629 |
| 5962-9318717H5A | K | 11/13/2001 | 1 | AEROFLEX | | Y | ACT-S128K32C-017P7 | 629 |
| 5962-9318717H5A | K | 11/13/2001 | 1 | AUSTIN SEMI. | | Y | AS8S128K32P-17/883C | 629 |
| 5962-9318717H5A | K | 11/13/2001 | 1 | WHITE ELEC. | | Y | WS128K32H-17H1Q | 629 |
| 5962-9318717H5C | K | 11/13/2001 | 1 | AEROFLEX | | Y | ACT-S128K32C-017P7 | 629 |
| 5962-9318717H5C | K | 11/13/2001 | 1 | AUSTIN SEMI. | | Y | AS8S128K32P-17/883C | 629 |
| 5962-9318717H5C | K | 11/13/2001 | 1 | WHITE ELEC. | | Y | WS128K32H-17H1Q | 629 |
| 5962-9318717HMA | K | 11/13/2001 | 1 | AEROFLEX | | Y | ACT-S128K32N-017P3 | 629 |
| 5962-9318717HMC | K | 11/13/2001 | 1 | AEROFLEX | | Y | ACT-S128K32N-017P3 | 629 |
| 5962-9318717HNA | K | 11/13/2001 | 1 | AEROFLEX | | Y | ACT-S128K32C-017P3 | 629 |
| 5962-9318717HNC | K | 11/13/2001 | 1 | AEROFLEX | | Y | ACT-S128K32C-017P3 | 629 |
| 5962-9318717HTA | K | 11/13/2001 | 1 | AEROFLEX | | Y | ACT-S128K32N-017P2 | 629 |
| 5962-9318717HTC | K | 11/13/2001 | 1 | AEROFLEX | | Y | ACT-S128K32N-017P2 | 629 |
| 5962-9318717HUA | K | 11/13/2001 | 1 | AEROFLEX | | Y | ACT-S128K32N-017P6 | 629 |
| 5962-9318717HUC | K | 11/13/2001 | 1 | AEROFLEX | | Y | ACT-S128K32N-017P6 | 629 |
| 5962-9318717HXA | K | 11/13/2001 | 1 | AEROFLEX | | Y | ACT-S128K32C-017P2 | 629 |
| 5962-9318717HXC | K | 11/13/2001 | 1 | AEROFLEX | | Y | ACT-S128K32C-017P2 | 629 |
| 5962-9318717HYA | K | 11/13/2001 | 1 | AEROFLEX | | Y | ACT-S128K32C-017P6 | 629 |
| 5962-9318717HYC | K | 11/13/2001 | 1 | AEROFLEX | | Y | ACT-S128K32C-017P6 | 629 |
| 5962-9318718H4A | K | 11/13/2001 | 1 | WHITE ELEC. | | Y | WS128K32NH-15H1Q | 629 |
| 5962-9318718H4C | K | 11/13/2001 | 1 | WHITE ELEC. | | Y | WS128K32NH-15H1Q | 629 |
| 5962-9318718H5A | K | 11/13/2001 | 1 | WHITE ELEC. | | Y | WS128K32H-15H1Q | 629 |
| 5962-9318718H5C | K | 11/13/2001 | 1 | WHITE ELEC. | | Y | WS128K32H-15H1Q | 629 |
| 5962-9318801M2A | B | 11/22/1995 | 2 | TI | | Y | SNJ54ABT240FK | 529 |
| 5962-9318801Q2A | B | 11/22/1995 | 3 | NATIONAL | | Y | 54ABT240E-QML | 529 |
| 5962-9318801MRA | B | 11/22/1995 | 2 | TI | | Y | SNJ54ABT240J | 529 |
| 5962-9318801QRA | B | 11/22/1995 | 3 | NATIONAL | | Y | 54ABT240J-QML | 529 |
| 5962-9318801MSA | B | 11/22/1995 | 2 | TI | | Y | SNJ54ABT240W | 529 |
| 5962-9318801QSA | B | 11/22/1995 | 3 | NATIONAL | | Y | 54ABT240W-QML | 529 |
| 5962-9318901MXA | C | 08/02/1995 | | (NONE) | 10/26/1998 | | 7224550 (GEN) | 670 |
| 5962-9318901MYA | C | 08/02/1995 | | (NONE) | 10/26/1998 | | 7224550 (GEN) | 670 |
| 5962-9318902MXA | C | 08/02/1995 | | (NONE) | 10/26/1998 | | 7224535 (GEN) | 670 |
| 5962-9318902MYA | C | 08/02/1995 | | (NONE) | 10/26/1998 | | 7224535 (GEN) | 670 |
| 5962-9318903MXA | C | 08/02/1995 | | (NONE) | 10/26/1998 | | 7224525 (GEN) | 670 |
| 5962-9318903MYA | C | 08/02/1995 | | (NONE) | 10/26/1998 | | 7224525 (GEN) | 670 |
| 5962-9319001MPA | | 10/28/1993 | | (NONE) | 03/30/2001 | | LT1241 (GEN) | 787 |
| 5962-9319002MPA | | 10/28/1993 | | (NONE) | 03/30/2001 | | LT1242 (GEN) | 787 |
| 5962-9319003MPA | | 10/28/1993 | | (NONE) | 03/30/2001 | | LT1243 (GEN) | 787 |
| 5962-9319004MPA | | 10/28/1993 | | (NONE) | 03/30/2001 | | LT1244 (GEN) | 787 |
| 5962-9319005MPA | | 10/28/1993 | | (NONE) | 03/30/2001 | | LT1245 (GEN) | 787 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9319101HTA | C | 07/28/2004 | 1 | INTERPOINT | | Y | MFL2805DW/883 | 594 |
| 5962-9319101HTC | C | 07/28/2004 | 1 | INTERPOINT | | Y | MFL2805DW/883 | 594 |
| 5962-9319101HUA | C | 07/28/2004 | 1 | INTERPOINT | | Y | MFL2805DV/883 | 594 |
| 5962-9319101HUC | C | 07/28/2004 | 1 | INTERPOINT | | Y | MFL2805DV/883 | 594 |
| 5962-9319101HXA | C | 07/28/2004 | 1 | INTERPOINT | | Y | MFL2805D/883 | 594 |
| 5962-9319101HXC | C | 07/28/2004 | 1 | INTERPOINT | | Y | MFL2805D/883 | 594 |
| 5962-9319101HYA | C | 07/28/2004 | 1 | INTERPOINT | | Y | MFL2805DY/883 | 594 |
| 5962-9319101HYC | C | 07/28/2004 | 1 | INTERPOINT | | Y | MFL2805DY/883 | 594 |
| 5962-9319101HZA | C | 07/28/2004 | 1 | INTERPOINT | | Y | MFL2805DZ/883 | 594 |
| 5962-9319101HZC | C | 07/28/2004 | 1 | INTERPOINT | | Y | MFL2805DZ/883 | 594 |
| 5962-9319201HTA | C | 07/28/2004 | 1 | INTERPOINT | | Y | MFL2812DW/883 | 594 |
| 5962-9319201HTC | C | 07/28/2004 | 1 | INTERPOINT | | Y | MFL2812DW/883 | 594 |
| 5962-9319201HUA | C | 07/28/2004 | 1 | INTERPOINT | | Y | MFL2812DV/883 | 594 |
| 5962-9319201HUC | C | 07/28/2004 | 1 | INTERPOINT | | Y | MFL2812DV/883 | 594 |
| 5962-9319201HXA | C | 07/28/2004 | 1 | INTERPOINT | | Y | MFL2812D/883 | 594 |
| 5962-9319201HXC | C | 07/28/2004 | 1 | INTERPOINT | | Y | MFL2812D/883 | 594 |
| 5962-9319201HYA | C | 07/28/2004 | 1 | INTERPOINT | | Y | MFL2812DY/883 | 594 |
| 5962-9319201HYC | C | 07/28/2004 | 1 | INTERPOINT | | Y | MFL2812DY/883 | 594 |
| 5962-9319201HZA | C | 07/28/2004 | 1 | INTERPOINT | | Y | MFL2812DZ/883 | 594 |
| 5962-9319201HZC | C | 07/28/2004 | 1 | INTERPOINT | | Y | MFL2812DZ/883 | 594 |
| 5962-9319301HTA | C | 06/21/2002 | 1 | INTERPOINT | | Y | MFL2815DW/883 | 594 |
| 5962-9319301HTC | C | 06/21/2002 | 1 | INTERPOINT | | Y | MFL2815DW/883 | 594 |
| 5962-9319301HUA | C | 06/21/2002 | 1 | INTERPOINT | | Y | MFL2815DV/883 | 594 |
| 5962-9319301HUC | C | 06/21/2002 | 1 | INTERPOINT | | Y | MFL2815DV/883 | 594 |
| 5962-9319301HXA | C | 06/21/2002 | 1 | INTERPOINT | | Y | MFL2815D/883 | 594 |
| 5962-9319301HXC | C | 06/21/2002 | 1 | INTERPOINT | | Y | MFL2815D/883 | 594 |
| 5962-9319301HYA | C | 06/21/2002 | 1 | INTERPOINT | | Y | MFL2815DY/883 | 594 |
| 5962-9319301HYC | C | 06/21/2002 | 1 | INTERPOINT | | Y | MFL2815DY/883 | 594 |
| 5962-9319301HZA | C | 06/21/2002 | 1 | INTERPOINT | | Y | MFL2815DZ/883 | 594 |
| 5962-9319301HZC | C | 06/21/2002 | 1 | INTERPOINT | | Y | MFL2815DZ/883 | 594 |
| 5962-9319302HTA | C | 06/21/2002 | 1 | INTERPOINT | | Y | SMFL2815DW/HO | 594 |
| 5962-9319302HTC | C | 06/21/2002 | 1 | INTERPOINT | | Y | SMFL2815DW/HO | 594 |
| 5962R9319302HTA | C | 06/21/2002 | 1 | INTERPOINT | | Y | SMFL2815DW/HR | 594 |
| 5962R9319302HTC | C | 06/21/2002 | 1 | INTERPOINT | | Y | SMFL2815DW/HR | 594 |
| 5962R9319302KTA | C | 06/21/2002 | 1 | INTERPOINT | | Y | SMFL2815DW/KR | 594 |
| 5962R9319302KTC | C | 06/21/2002 | 1 | INTERPOINT | | Y | SMFL2815DW/KR | 594 |
| 5962-9319302HUA | C | 06/21/2002 | 1 | INTERPOINT | | Y | SMFL2815DV/HO | 594 |
| 5962-9319302HUC | C | 06/21/2002 | 1 | INTERPOINT | | Y | SMFL2815DV/HO | 594 |
| 5962R9319302HUA | C | 06/21/2002 | 1 | INTERPOINT | | Y | SMFL2815DV/HR | 594 |
| 5962R9319302HUC | C | 06/21/2002 | 1 | INTERPOINT | | Y | SMFL2815DV/HR | 594 |
| 5962R9319302KUA | C | 06/21/2002 | 1 | INTERPOINT | | Y | SMFL2815DV/KR | 594 |
| 5962R9319302KUC | C | 06/21/2002 | 1 | INTERPOINT | | Y | SMFL2815DV/KR | 594 |
| 5962-9319302HXA | C | 06/21/2002 | 1 | INTERPOINT | | Y | SMFL2815D/HO | 594 |
| 5962-9319302HXC | C | 06/21/2002 | 1 | INTERPOINT | | Y | SMFL2815D/HO | 594 |
| 5962R9319302HXA | C | 06/21/2002 | 1 | INTERPOINT | | Y | SMFL2815D/HR | 594 |
| 5962R9319302HXC | C | 06/21/2002 | 1 | INTERPOINT | | Y | SMFL2815D/HR | 594 |
| 5962R9319302KXA | C | 06/21/2002 | 1 | INTERPOINT | | Y | SMFL2815D/KR | 594 |
| 5962R9319302KXC | C | 06/21/2002 | 1 | INTERPOINT | | Y | SMFL2815D/KR | 594 |
| 5962-9319302HYA | C | 06/21/2002 | 1 | INTERPOINT | | Y | SMFL2815DY/HO | 594 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9319302HYC | C | 06/21/2002 | 1 | INTERPOINT | | Y | SMFL2815DY/HO | 594 |
| 5962R9319302HYA | C | 06/21/2002 | 1 | INTERPOINT | | Y | SMFL2815DY/HR | 594 |
| 5962R9319302HYC | C | 06/21/2002 | 1 | INTERPOINT | | Y | SMFL2815DY/HR | 594 |
| 5962R9319302KYA | C | 06/21/2002 | 1 | INTERPOINT | | Y | SMFL2815DY/KR | 594 |
| 5962R9319302KYC | C | 06/21/2002 | 1 | INTERPOINT | | Y | SMFL2815DY/KR | 594 |
| 5962-9319302HZA | C | 06/21/2002 | 1 | INTERPOINT | | Y | SMFL2815DZ/HO | 594 |
| 5962-9319302HZC | C | 06/21/2002 | 1 | INTERPOINT | | Y | SMFL2815DZ/HO | 594 |
| 5962R9319302HZA | C | 06/21/2002 | 1 | INTERPOINT | | Y | SMFL2815DZ/HR | 594 |
| 5962R9319302HZC | C | 06/21/2002 | 1 | INTERPOINT | | Y | SMFL2815DZ/HR | 594 |
| 5962R9319302KZA | C | 06/21/2002 | 1 | INTERPOINT | | Y | SMFL2815DZ/KR | 594 |
| 5962R9319302KZC | C | 06/21/2002 | 1 | INTERPOINT | | Y | SMFL2815DZ/KR | 594 |
| 5962-9319401M2A | A | 08/31/1993 | | (NONE) | 05/31/1994 | | 3550 (GEN) | 575 |
| 5962-9319401MEA | A | 08/31/1993 | | (NONE) | 05/31/1994 | | 3550 (GEN) | 575 |
| 5962-9319501MXC | B | 07/21/1999 | | (NONE) | | | LM12458 (GEN) | 433 |
| 5962-9319501MYA | B | 07/21/1999 | | (NONE) | | | LM12458 (GEN) | 433 |
| 5962-9319502MXC | B | 07/21/1999 | 2 | NATIONAL | | Y | LM12H458MEL/883 | 433 |
| 5962-9319502MYA | B | 07/21/1999 | | (NONE) | | | LM12H458 (GEN) | 433 |
| 5962-9319502QZA | B | 07/21/1999 | 2 | NATIONAL | | Y | LM12H458MWG/883 | 433 |
| 5962-9319601QYA | | 03/03/1994 | | (NONE) | 09/30/1995 | | 88915-55 (GEN) | 550 |
| 5962-9319601QZA | | 03/03/1994 | | (NONE) | 09/30/1995 | | 88915-55 (GEN) | 550 |
| 5962-9319801HXA | B | 07/31/2002 | 1 | DATEL | | Y | ADS-944/883 | 592 |
| 5962-9319801HXC | B | 07/31/2002 | 1 | DATEL | | Y | ADS-944/883 | 592 |
| 5962-9319802HXA | B | 07/31/2002 | | (NONE) | | | ADS-30189 (GEN) | 592 |
| 5962-9319803HXA | B | 07/31/2002 | 1 | DATEL | | Y | ADS-30214 | 592 |
| 5962-9319803HXC | B | 07/31/2002 | 1 | DATEL | | Y | ADS-30214 | 592 |
| 5962-9319901MXA | B | 01/21/1999 | 1 | TI | | Y | SNJ54ABT16240WD | 529 |
| 5962-9320001QXA | C | 01/21/1997 | 2 | NATIONAL | | Y | 54ABT16373W-QML | 342 |
| 5962-9320001QXA | C | 01/21/1997 | 2 | TI | | Y | SNJ54ABT16373AWD | 342 |
| 5962-9320101MXA | B | 11/21/1997 | 3 | TI | | Y | SNJ54ABT16374AWD | 159 |
| 5962-9320101QXA | B | 11/21/1997 | 2 | NATIONAL | | Y | 54ABT16374W-QML | 159 |
| 5962-9320201HXA | D | 05/25/2004 | 1 | INTERPOINT | | Y | MTR2818S/883 | 594 |
| 5962-9320201HXC | D | 05/25/2004 | 1 | INTERPOINT | | Y | MTR2818S/883 | 594 |
| 5962-9320201HZA | D | 05/25/2004 | 1 | INTERPOINT | | Y | MTR2818SF/883 | 594 |
| 5962-9320201HZC | D | 05/25/2004 | 1 | INTERPOINT | | Y | MTR2818SF/883 | 594 |
| 5962-9320301M2A | C | 07/07/1997 | | (NONE) | 12/06/2000 | | CLC533 (GEN) | 192 |
| 5962-9320301MEA | C | 07/07/1997 | | (NONE) | 12/06/2000 | | CLC533 (GEN) | 192 |
| 5962-9320401MEA | A | 08/25/2000 | 1 | ANALOG (3) | | Y | AD7243SQ/883B | 899 |
| 5962-9320501HXA | C | 05/25/2004 | 1 | INTERPOINT | | Y | MTR2805D/883 | 594 |
| 5962-9320501HXC | C | 05/25/2004 | 1 | INTERPOINT | | Y | MTR2805D/883 | 594 |
| 5962-9320501HZA | C | 05/25/2004 | 1 | INTERPOINT | | Y | MTR2805DF/883 | 594 |
| 5962-9320501HZC | C | 05/25/2004 | 1 | INTERPOINT | | Y | MTR2805DF/883 | 594 |
| 5962-9320601M2A | | 10/05/1993 | | (NONE) | 12/31/2001 | | UC1907 (GEN) | 899 |
| 5962-9320601MEA | | 10/05/1993 | | (NONE) | 12/31/2001 | | UC1907 (GEN) | 899 |
| 5962-9320701MXA | B | 07/14/1994 | 3 | NATIONAL | | Y | SCAN18374TFMQB | 159 |
| 5962-9320901MPA | B | 01/07/2002 | | (NONE) | 04/16/2002 | | AD822S (GEN) | 703 |
| 5962-9321001MCA | A | 06/18/2002 | 1 | NATIONAL | | Y | MM78C29J/883 | 569 |
| 5962-9321001MCA | A | 06/18/2002 | 1 | ROCHESTER | | Y | MM78C29J/883 | 569 |
| 5962-9321101MCA | A | 07/03/2002 | 1 | NATIONAL | | Y | DS78C20J/883 | 573 |
| 5962-9321201MPA | | 08/23/1993 | | (NONE) | 03/30/2001 | | LT1111 (GEN) | 594 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9321401MEA | A | 01/11/2002 | 1 | ANALOG (2) | | Y | AD688SQ/883B | 785 |
| 5962-9321501M2A | A | 02/06/2004 | 1 | TI | | Y | UC1517L/883BC | 899 |
| 5962-9321501MEA | A | 02/06/2004 | 1 | TI | | Y | UC1517J/883BC | 899 |
| 5962-9321601Q2A | B | 02/13/2002 | 1 | TI | | Y | TLE2141MFKB | 702 |
| 5962-9321601QPA | B | 02/13/2002 | 1 | TI | | Y | TLE2141MJGB | 702 |
| 5962-9321602Q2A | B | 02/13/2002 | 1 | TI | | Y | TLE2141AMFKB | 702 |
| 5962-9321602QPA | B | 02/13/2002 | 1 | TI | | Y | TLE2141AMJGB | 702 |
| 5962-9321603Q2A | B | 02/13/2002 | 1 | TI | | Y | TLE2142MFKB | 710 |
| 5962-9321603QHA | B | 02/13/2002 | 1 | TI | | Y | TLE2142MUB | 710 |
| 5962-9321603QPA | B | 02/13/2002 | 1 | TI | | Y | TLE2142MJGB | 710 |
| 5962-9321604Q2A | B | 02/13/2002 | 1 | TI | | Y | TLE2142AMFKB | 710 |
| 5962-9321604QHA | B | 02/13/2002 | 1 | TI | | Y | TLE2142AMUB | 710 |
| 5962-9321604QPA | B | 02/13/2002 | 1 | TI | | Y | TLE2142AMJGB | 710 |
| 5962-9321605Q2A | B | 02/13/2002 | 1 | TI | | Y | TLE2144MFKB | 713 |
| 5962-9321605QCA | B | 02/13/2002 | 1 | TI | | Y | TLE2144MJB | 713 |
| 5962-9321606Q2A | B | 02/13/2002 | 1 | TI | | Y | TLE2144AMFKB | 713 |
| 5962-9321606QCA | B | 02/13/2002 | 1 | TI | | Y | TLE2144AMJB | 713 |
| 5962-9321701M2A | B | 11/06/1995 | | (NONE) | | | 54ABT273 (GEN) | 159 |
| 5962-9321701Q2A | B | 11/06/1995 | 3 | NATIONAL | | Y | 54ABT273E-QML | 159 |
| 5962-9321701Q2A | B | 11/06/1995 | 2 | TI | | Y | SNJ54ABT273FK | 159 |
| 5962-9321701MRA | B | 11/06/1995 | | (NONE) | | | 54ABT273 (GEN) | 159 |
| 5962-9321701QRA | B | 11/06/1995 | 3 | NATIONAL | | Y | 54ABT273J-QML | 159 |
| 5962-9321701QRA | B | 11/06/1995 | 2 | TI | | Y | SNJ54ABT273J | 159 |
| 5962-9321701MSA | B | 11/06/1995 | | (NONE) | | | 54ABT273 (GEN) | 159 |
| 5962-9321701QSA | B | 11/06/1995 | 3 | NATIONAL | | Y | 54ABT273W-QML | 159 |
| 5962-9321701QSA | B | 11/06/1995 | 2 | TI | | Y | SNJ54ABT273W | 159 |
| 5962-9321801M2A | B | 11/21/2000 | | (NONE) | 06/01/1997 | | 54ABT373 (GEN) | 341 |
| 5962-9321801Q2A | B | 11/21/2000 | 3 | NATIONAL | | Y | 54ABT373E-QML | 341 |
| 5962-9321801Q2A | B | 11/21/2000 | 2 | TI | | Y | SNJ54ABT373FK | 341 |
| 5962-9321801MRA | B | 11/21/2000 | | (NONE) | 06/01/1997 | | 54ABT373 (GEN) | 341 |
| 5962-9321801QRA | B | 11/21/2000 | 3 | NATIONAL | | Y | 54ABT373J-QML | 341 |
| 5962-9321801QRA | B | 11/21/2000 | 2 | TI | | Y | SNJ54ABT373J | 341 |
| 5962-9321801MSA | B | 11/21/2000 | | (NONE) | | | 54ABT373 (GEN) | 341 |
| 5962-9321801QSA | B | 11/21/2000 | 3 | NATIONAL | | Y | 54ABT373W-QML | 341 |
| 5962-9321801QSA | B | 11/21/2000 | 2 | TI | | Y | SNJ54ABT373W | 341 |
| 5962-9321901Q2A | B | 11/20/2000 | 3 | NATIONAL | | Y | 54ABT573E-QML | 341 |
| 5962-9321901Q2A | B | 11/20/2000 | 3 | TI | | Y | SNJ54ABT573FK | 341 |
| 5962-9321901QRA | B | 11/20/2000 | 3 | NATIONAL | | Y | 54ABT573J-QML | 341 |
| 5962-9321901QRA | B | 11/20/2000 | 3 | TI | | Y | SNJ54ABT573J | 341 |
| 5962-9321901QSA | B | 11/20/2000 | 3 | NATIONAL | | Y | 54ABT573W-QML | 341 |
| 5962-9321901QSA | B | 11/20/2000 | 3 | TI | | Y | SNJ54ABT573W | 341 |
| 5962-9322001M2A | C | 11/29/2000 | | (NONE) | 06/01/1997 | | 54ABT574 (GEN) | 159 |
| 5962-9322001Q2A | C | 11/29/2000 | 3 | NATIONAL | | Y | 54ABT574E-QML | 159 |
| 5962-9322001Q2A | C | 11/29/2000 | 3 | TI | | Y | SNJ54ABT574FK | 159 |
| 5962-9322001MRA | C | 11/29/2000 | | (NONE) | 06/01/1997 | | 54ABT574 (GEN) | 159 |
| 5962-9322001QRA | C | 11/29/2000 | 3 | NATIONAL | | Y | 54ABT574J-QML | 159 |
| 5962-9322001QRA | C | 11/29/2000 | 3 | TI | | Y | SNJ54ABT574J | 159 |
| 5962-9322001MSA | C | 11/29/2000 | | (NONE) | | | 54ABT574 (GEN) | 159 |
| 5962-9322001QSA | C | 11/29/2000 | 3 | NATIONAL | | Y | 54ABT574W-QML | 159 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9322001QSA | C | 11/29/2000 | 3 | TI | | Y | SNJ54ABT574W | 159 |
| 5962-9322101MXA | | 11/19/1993 | 1 | ACTEL | | Y | A1240A-PG132B | 431 |
| 5962-9322101MXC | | 11/19/1993 | 1 | ACTEL | | Y | A1240A-PG132B | 431 |
| 5962-9322102MXA | | 11/19/1993 | 1 | ACTEL | | Y | A1240A-1PG132B | 431 |
| 5962-9322102MXC | | 11/19/1993 | 1 | ACTEL | | Y | A1240A-1PG132B | 431 |
| 5962-9322201MEA | B | 01/08/2002 | 1 | ANALOG (2) | | Y | AD652SQ/883B | 594 |
| 5962-9322401MPA | | 10/26/1993 | | (NONE) | 03/30/2001 | | LT1120 (GEN) | 789 |
| 5962-9322501MXA | | 04/08/1994 | | (NONE) | | | 7C196-45 (GEN) | 623 |
| 5962-9322501MYA | | 04/08/1994 | | (NONE) | | | 7C196-45 (GEN) | 623 |
| 5962-9322501MZA | | 04/08/1994 | | (NONE) | 05/10/1995 | | 7C196-45 (GEN) | 623 |
| 5962-9322502MXA | | 04/08/1994 | | (NONE) | | | 7C196-35 (GEN) | 623 |
| 5962-9322502MYA | | 04/08/1994 | | (NONE) | | | 7C196-35 (GEN) | 623 |
| 5962-9322502MZA | | 04/08/1994 | | (NONE) | 05/10/1995 | | 7C196-35 (GEN) | 623 |
| 5962-9322503MXA | | 04/08/1994 | | (NONE) | | | 7C196-25 (GEN) | 623 |
| 5962-9322503MYA | | 04/08/1994 | | (NONE) | | | 7C196-25 (GEN) | 623 |
| 5962-9322503MZA | | 04/08/1994 | | (NONE) | 05/10/1995 | | 7C196-25 (GEN) | 623 |
| 5962-9322504MXA | | 04/08/1994 | | (NONE) | | | 7C196-20 (GEN) | 623 |
| 5962-9322504MYA | | 04/08/1994 | | (NONE) | | | 7C196-20 (GEN) | 623 |
| 5962-9322504MZA | | 04/08/1994 | | (NONE) | 05/10/1995 | | 7C196-20 (GEN) | 623 |
| 5962-9322601MXA | G | 10/21/2003 | 1 | UTMC | | Y | UT63M147BBX | 590 |
| 5962-9322601MZA | G | 10/21/2003 | 1 | UTMC | | Y | UT63M147CBX | 590 |
| 5962-9322602MXA | G | 10/21/2003 | | (NONE) | | | UT63M149 (GEN) | 590 |
| 5962-9322602MZA | G | 10/21/2003 | | (NONE) | | | UT63M149 (GEN) | 590 |
| 5962-9322603Q9A | G | 10/21/2003 | | (NONE) | | | UT63M147E (GEN) | 590 |
| 5962-9322603V9A | G | 10/21/2003 | | (NONE) | | | UT63M147E(GEN) | 590 |
| 5962H9322603Q9A | G | 10/21/2003 | 1 | UTMC | | Y | UT63M147E-Q DIE | 590 |
| 5962H9322603V9A | G | 10/21/2003 | 1 | UTMC | | Y | UT63M147E-V DIE | 590 |
| 5962-9322603QXA | G | 10/21/2003 | 1 | UTMC | | Y | UT63M147EBQA | 590 |
| 5962-9322603QXC | G | 10/21/2003 | 1 | UTMC | | Y | UT63M147EBQC | 590 |
| 5962H9322603VXA | G | 10/21/2003 | 1 | UTMC | | Y | UT63M147EBVA | 590 |
| 5962H9322603VXC | G | 10/21/2003 | 1 | UTMC | | Y | UT63M147EBVC | 590 |
| 5962-9322603QZA | G | 10/21/2003 | 1 | UTMC | | Y | UT63M147ECQA | 590 |
| 5962-9322603QZC | G | 10/21/2003 | 1 | UTMC | | Y | UT63M147ECQC | 590 |
| 5962H9322603VZA | G | 10/21/2003 | 1 | UTMC | | Y | UT63M147ECVA | 590 |
| 5962H9322603VZC | G | 10/21/2003 | 1 | UTMC | | Y | UT63M147ECVC | 590 |
| 5962-9322604QXA | G | 10/21/2003 | 1 | UTMC | | Y | UT63M145BQA | 590 |
| 5962-9322604QXC | G | 10/21/2003 | 1 | UTMC | | Y | UT63M145BQC | 590 |
| 5962H9322604VXA | G | 10/21/2003 | 1 | UTMC | | Y | UT63M145BVA | 590 |
| 5962H9322604VXC | G | 10/21/2003 | 1 | UTMC | | Y | UT63M145BVC | 590 |
| 5962-9322604QZA | G | 10/21/2003 | 1 | UTMC | | Y | UT63M145CQA | 590 |
| 5962-9322604QZC | G | 10/21/2003 | 1 | UTMC | | Y | UT63M145CQC | 590 |
| 5962H9322604VZA | G | 10/21/2003 | 1 | UTMC | | Y | UT63M145CVA | 590 |
| 5962H9322604VZC | G | 10/21/2003 | 1 | UTMC | | Y | UT63M145CVC | 590 |
| 5962-9322701M2A | D | 12/06/2000 | | (NONE) | | | 54ABT241 (GEN) | 529 |
| 5962-9322701Q2A | D | 12/06/2000 | 2 | NATIONAL | | Y | 54ABT241E-QML | 529 |
| 5962-9322701Q2A | D | 12/06/2000 | 2 | TI | | Y | SNJ54ABT241FK | 529 |
| 5962-9322701MRA | D | 12/06/2000 | | (NONE) | | | 54ABT241 (GEN) | 529 |
| 5962-9322701QRA | D | 12/06/2000 | 2 | NATIONAL | | Y | 54ABT241J-QML | 529 |
| 5962-9322701QRA | D | 12/06/2000 | 2 | TI | | Y | SNJ54ABT241J | 529 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9322701MSA | D | 12/06/2000 | | (NONE) | | | 54ABT241 (GEN) | 529 |
| 5962-9322701QSA | D | 12/06/2000 | 2 | NATIONAL | | Y | 54ABT241W-QML | 529 |
| 5962-9322701QSA | D | 12/06/2000 | 2 | TI | | Y | SNJ54ABT241W | 529 |
| 5962-9322801MXA | A | 10/07/1994 | 1 | TI | | | SNJ54ACT8990HV | 420 |
| 5962-9322801MYA | A | 10/07/1994 | 1 | TI | | | SNJ54ACT8990GB | 420 |
| 5962-9323501MUA | | 03/25/1994 | | (NONE) | 12/24/1997 | | 28F020 (GEN) | 669 |
| 5962-9323501MXA | | 03/25/1994 | | (NONE) | 12/24/1997 | | 28F020 (GEN) | 669 |
| 5962-9323502MUA | | 03/25/1994 | | (NONE) | 12/24/1997 | | 28F020 (GEN) | 669 |
| 5962-9323502MXA | | 03/25/1994 | | (NONE) | 12/24/1997 | | 28F020 (GEN) | 669 |
| 5962-9323503MUA | | 03/25/1994 | | (NONE) | 12/24/1997 | | 28F020 (GEN) | 669 |
| 5962-9323503MXA | | 03/25/1994 | | (NONE) | 12/24/1997 | | 28F020 (GEN) | 669 |
| 5962-9323504MUA | | 03/25/1994 | | (NONE) | 12/24/1997 | | 28F020 (GEN) | 669 |
| 5962-9323504MXA | | 03/25/1994 | | (NONE) | 12/24/1997 | | 28F020 (GEN) | 669 |
| 5962-9323505MXA | | 03/25/1994 | | (NONE) | | | 28F020A (GEN) | 669 |
| 5962-9323506MXA | | 03/25/1994 | | (NONE) | | | 28F010A (GEN) | 669 |
| 5962-9323507MXA | | 03/25/1994 | | (NONE) | | | 28F020A (GEN) | 669 |
| 5962-9323508MXA | | 03/25/1994 | | (NONE) | | | 28F020A (GEN) | 669 |
| 5962-9323801MCA | A | 04/09/1999 | | (NONE) | 03/30/2001 | | LT1125 (GEN) | 713 |
| 5962-9323802MPA | A | 04/09/1999 | | (NONE) | 03/30/2001 | | LT1124 (GEN) | 710 |
| 5962-9323803MCA | A | 04/09/1999 | | (NONE) | 03/30/2001 | | LT1125A (GEN) | 713 |
| 5962-9323804MPA | A | 04/09/1999 | | (NONE) | 03/30/2001 | | LT1124A (GEN) | 710 |
| 5962-9323901M3A | A | 03/24/1994 | | (NONE) | | | 54ACT8997 (GEN) | 399 |
| 5962-9323901Q3A | A | 03/24/1994 | 1 | TI | | Y | SNJ54ACT8997FK | 399 |
| 5962-9323901MXA | A | 03/24/1994 | | (NONE) | | | 54ACT8997 (GEN) | 399 |
| 5962-9323901QXA | A | 03/24/1994 | 1 | TI | | Y | SNJ54ACT8997JT | 399 |
| 5962-9324101MXA | B | 12/04/2000 | 3 | TI | | Y | SNJ54ABT16543WD | 590 |
| 5962-9324201M3A | B | 01/05/2001 | | (NONE) | | | 54ABT652 (GEN) | 590 |
| 5962-9324201Q3A | B | 01/05/2001 | | (NONE) | | | 54ABT652 (GEN) | 590 |
| 5962-9324201MKA | B | 01/05/2001 | | (NONE) | | | 54ABT652 (GEN) | 590 |
| 5962-9324201QKA | B | 01/05/2001 | | (NONE) | | | 54ABT652 (GEN) | 590 |
| 5962-9324201MLA | B | 01/05/2001 | | (NONE) | | | 54ABT652 (GEN) | 590 |
| 5962-9324201QLA | B | 01/05/2001 | | (NONE) | | | 54ABT652 (GEN) | 590 |
| 5962-9324202Q3A | B | 01/05/2001 | 2 | TI | | Y | SNJ54ABT652AFK | 590 |
| 5962-9324202QKA | B | 01/05/2001 | 2 | TI | | Y | SNJ54ABT652AW | 590 |
| 5962-9324202QLA | B | 01/05/2001 | 2 | TI | | Y | SNJ54ABT652AJ | 590 |
| 5962-9324301HXA | C | 05/30/2001 | | (NONE) | | | MSK-1903B-0 (GEN) | 760 |
| 5962-9324302HXA | C | 05/30/2001 | | (NONE) | | | MSK-1903B-2 (GEN) | 760 |
| 5962-9324401MXA | | 12/08/1993 | | (NONE) | | | 29C040 (GEN) | 669 |
| 5962-9324401MYA | | 12/08/1993 | | (NONE) | | | 29C040 (GEN) | 669 |
| 5962-9324402MXA | | 12/08/1993 | | (NONE) | | | 29C040 (GEN) | 669 |
| 5962-9324402MYA | | 12/08/1993 | | (NONE) | | | 29C040 (GEN) | 669 |
| 5962-9324501M3A | | 10/08/1993 | | (NONE) | | | 22LV10 (GEN) | 431 |
| 5962-9324501MKA | | 10/08/1993 | | (NONE) | | | 22LV10 (GEN) | 431 |
| 5962-9324501MLA | | 10/08/1993 | | (NONE) | | | 22LV10 (GEN) | 431 |
| 5962-9324502M3A | | 10/08/1993 | | (NONE) | 12/03/1994 | | 22LV10 (GEN) | 431 |
| 5962-9324502MKA | | 10/08/1993 | | (NONE) | | | 22LV10 (GEN) | 431 |
| 5962-9324502MLA | | 10/08/1993 | | (NONE) | 12/03/1994 | | 22LV10 (GEN) | 431 |
| 5962-9324503M3A | | 10/08/1993 | | (NONE) | | | 22LV10L (GEN) | 431 |
| 5962-9324503MKA | | 10/08/1993 | | (NONE) | | | 22LV10 (GEN) | 431 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9324503MLA | | 10/08/1993 | | (NONE) | | | 22LV10L (GEN) | 431 |
| 5962-9324504M3A | | 10/08/1993 | | (NONE) | 12/03/1994 | | 22LV10 (GEN) | 431 |
| 5962-9324504MKA | | 10/08/1993 | | (NONE) | | | 22LV10 (GEN) | 431 |
| 5962-9324504MLA | | 10/08/1993 | | (NONE) | 12/03/1994 | | 22LV10 (GEN) | 431 |
| 5962-9324601HXA | B | 05/21/2001 | 1 | MS KENNEDY | | Y | MSK1901B | 760 |
| 5962-9324601HXC | B | 05/21/2001 | 1 | MS KENNEDY | | Y | MSK1901B | 760 |
| 5962-9324701MXC | A | 05/30/1995 | | (NONE) | 10/31/1996 | | 7256-20 (GEN) | 431 |
| 5962-9324701MYA | A | 05/30/1995 | | (NONE) | 10/31/1996 | | 7256-20 (GEN) | 431 |
| 5962-9324702MXC | A | 05/30/1995 | | (NONE) | 10/31/1996 | | 7256-15 (GEN) | 431 |
| 5962-9324702MYA | A | 05/30/1995 | | (NONE) | 10/31/1996 | | 7256-15 (GEN) | 431 |
| 5962-9324801MXA | | 10/22/1993 | | (NONE) | 03/31/1996 | | ATV5000-25 (GEN) | 431 |
| 5962-9324801MYA | | 10/22/1993 | | (NONE) | 03/31/1996 | | ATV5000-25 (GEN) | 431 |
| 5962-9324802MXA | | 10/22/1993 | | (NONE) | 03/31/1996 | | ATV5000-35 (GEN) | 431 |
| 5962-9324802MYA | | 10/22/1993 | | (NONE) | 03/31/1996 | | ATV5000-35 (GEN) | 431 |
| 5962-9324803MXA | | 10/22/1993 | | (NONE) | 03/31/1996 | | ATV5000L-35 (GEN) | 431 |
| 5962-9324803MYA | | 10/22/1993 | | (NONE) | 03/31/1996 | | ATV5000L-35 (GEN) | 431 |
| 5962-9324901MXA | A | 06/05/2001 | 1 | IDT | | Y | IDT72211L50LB | 670 |
| 5962-9324902MXA | A | 06/05/2001 | 1 | IDT | | Y | IDT72211L35LB | 670 |
| 5962-9324903MXA | A | 06/05/2001 | 1 | IDT | | Y | IDT72211L25LB | 670 |
| 5962-9325001M2A | | 08/01/1994 | | (NONE) | | | 54F2244 (GEN) | 529 |
| 5962-9325001MRA | | 08/01/1994 | 3 | NATIONAL | | Y | 54F2244DMQB | 529 |
| 5962-9325001MSA | | 08/01/1994 | 3 | NATIONAL | | Y | 54F2244FMQB | 529 |
| 5962-9325101M2A | A | 10/17/1994 | | (NONE) | 12/24/2000 | | HA-2546 (GEN) | 810 |
| 5962-9325101MEA | A | 10/17/1994 | 1 | INTERSIL | 10/03/2004 | Y | HA1-2546/883 | 810 |
| 5962-9325201QFA | | 11/17/1995 | | (NONE) | | | 54AC2526 (GEN) | 399 |
| 5962-9325201VFA | | 11/17/1995 | | (NONE) | | | 54AC2526 (GEN) | 399 |
| 5962-9325301B2A | C | 07/10/2002 | 1 | NATIONAL | | Y | JM54AC125B2A | 520 |
| 5962-9325301S2A | C | 07/10/2002 | | (NONE) | | | 54AC125 (GEN) | 520 |
| 5962R9325301B2A | C | 07/10/2002 | 1 | NATIONAL | | Y | JM54AC125B2A-RH | 520 |
| 5962R9325301S2A | C | 07/10/2002 | 1 | NATIONAL | | Y | JM54AC125S2A-RH | 520 |
| 5962-9325301BCA | C | 07/10/2002 | 1 | NATIONAL | | Y | JM54AC125BCA | 520 |
| 5962-9325301SCA | C | 07/10/2002 | | (NONE) | | | 54AC125 (GEN) | 520 |
| 5962R9325301BCA | C | 07/10/2002 | 1 | NATIONAL | | Y | JM54AC125BCA-RH | 520 |
| 5962R9325301SCA | C | 07/10/2002 | 1 | NATIONAL | | Y | JM54AC125SCA-RH | 520 |
| 5962-9325301BDA | C | 07/10/2002 | 1 | NATIONAL | | Y | JM54AC125BDA | 520 |
| 5962-9325301SDA | C | 07/10/2002 | | (NONE) | | | 54AC125 (GEN) | 520 |
| 5962R9325301BDA | C | 07/10/2002 | 1 | NATIONAL | | Y | JM54AC125BDA-RH | 520 |
| 5962R9325301SDA | C | 07/10/2002 | 1 | NATIONAL | | Y | JM54AC125SDA-RH | 520 |
| 5962-9325302QXA | C | 07/10/2002 | 2 | STMICRO | | Y | 54AC125K02Q | 520 |
| 5962-9325302QXC | C | 07/10/2002 | 2 | STMICRO | | Y | 54AC125K01Q | 520 |
| 5962-9325302VXA | C | 07/10/2002 | 2 | STMICRO | | Y | 54AC125K02V | 520 |
| 5962-9325302VXC | C | 07/10/2002 | 2 | STMICRO | | Y | 54AC125K01V | 520 |
| 5962-9325401MPA | B | 03/12/2001 | 1 | MAXIM INTEG. | | | MAX641AMJA/883B | 786 |
| 5962-9325501M2A | A | 10/29/2002 | 1 | SILICONIX | | Y | DG611AZ/883 | 183 |
| 5962-9325501MEA | A | 10/29/2002 | 1 | SILICONIX | | Y | DG611AK/883 | 183 |
| 5962-9325502M2A | A | 10/29/2002 | 1 | SILICONIX | | Y | DG612AZ/883 | 183 |
| 5962-9325502MEA | A | 10/29/2002 | 1 | SILICONIX | | Y | DG612AK/883 | 183 |
| 5962-9325503M2A | A | 10/29/2002 | 1 | SILICONIX | | Y | DG613AZ/883 | 183 |
| 5962-9325503MEA | A | 10/29/2002 | 1 | SILICONIX | | Y | DG613AK/883 | 183 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9325801M2A | E | 03/11/2003 | 1 | ANALOG (5) | | Y | OP467ARC/883 | 713 |
| 5962-9325801V2A | E | 03/11/2003 | 2 | ANALOG (5) | | Y | OP467ARC/QMLV | 713 |
| 5962-9325801MCA | E | 03/11/2003 | 1 | ANALOG (5) | | Y | OP467AY/883 | 713 |
| 5962-9325801VCA | E | 03/11/2003 | 2 | ANALOG (5) | | Y | OP467AY/QMLV | 713 |
| 5962R9325801VCA | E | 03/11/2003 | 2 | ANALOG (5) | | Y | OP467AY/QMLR | 713 |
| 5962R9325801VDA | E | 03/11/2003 | 2 | ANALOG (5) | | Y | OP467AM/QMLR | 713 |
| 5962-9325901MPA | B | 02/06/2004 | 1 | NATIONAL | | Y | CLC425AJ-QML | 755 |
| 5962-9326001MXA | B | 03/22/1996 | | (NONE) | | | 2250GM (GEN) | 208 |
| 5962-9326001MYA | B | 03/22/1996 | | (NONE) | | | 2250GM (GEN) | 208 |
| 5962-9326101M2A | E | 04/02/2001 | | (NONE) | | | UC1854 (GEN) | 789 |
| 5962-9326101MEA | E | 04/02/2001 | 2 | TI | | Y | UC1854J/883BC | 789 |
| 5962-9326102M2A | E | 04/02/2001 | | (NONE) | | | UC1854B (GEN) | 789 |
| 5962-9326102MEA | E | 04/02/2001 | 3 | TI | | Y | UC1854BJ/883BC | 789 |
| 5962-9326103M2A | E | 04/02/2001 | | (NONE) | | | UC1854A (GEN) | 789 |
| 5962-9326103MEA | E | 04/02/2001 | | (NONE) | 12/31/2001 | | UC1854A (GEN) | 789 |
| 5962-9326201MVA | C | 07/16/1999 | 1 | MICRO NETWKS | | | MN5906CD/883 | 592 |
| 5962-9326201MVC | C | 07/16/1999 | 1 | MICRO NETWKS | | | MN5906CD/883 | 592 |
| 5962-9326401M2C | B | 01/28/2002 | 1 | MAXIM INTEG. | | | MAX1259MLP/883B | 899 |
| 5962-9326401MEA | B | 01/28/2002 | 1 | MAXIM INTEG. | | | MAX1259MJE/883B | 899 |
| 5962-9326501M2A | D | 02/04/2002 | 1 | TI | | Y | UC1832L/883BC | 899 |
| 5962-9326501V2A | D | 02/04/2002 | 1 | TI | | Y | UC1832LQMLV | 899 |
| 5962-9326501MCA | D | 02/04/2002 | 1 | TI | | Y | UC1832J/883BC | 899 |
| 5962-9326501VCA | D | 02/04/2002 | 1 | TI | | Y | UC1832JQMLV | 899 |
| 5962-9326502M2A | D | 02/04/2002 | | (NONE) | 12/31/2001 | | UC1833 (GEN) | 899 |
| 5962-9326502MPA | D | 02/04/2002 | | (NONE) | 12/31/2001 | | UC1833 (GEN) | 899 |
| 5962-9326701M2C | B | 10/22/2002 | 1 | MAXIM INTEG. | | | MAX705MLP/883B | 429 |
| 5962-9326701MPA | B | 10/22/2002 | 1 | MAXIM INTEG. | | | MAX705MJA/883B | 429 |
| 5962-9326702M2C | B | 10/22/2002 | 1 | MAXIM INTEG. | | | MAX706MLP/883B | 429 |
| 5962-9326702MPA | B | 10/22/2002 | 1 | MAXIM INTEG. | | | MAX706MJA/883B | 429 |
| 5962-9326703M2C | B | 10/22/2002 | 1 | MAXIM INTEG. | | | MAX707MLP/883B | 429 |
| 5962-9326703MPA | B | 10/22/2002 | 1 | MAXIM INTEG. | | | MAX707MJA/883B | 429 |
| 5962-9326704M2C | B | 10/22/2002 | 1 | MAXIM INTEG. | | | MAX708MLP/883B | 429 |
| 5962-9326704MPA | B | 10/22/2002 | 1 | MAXIM INTEG. | | | MAX708MJA/883B | 429 |
| 5962-9326705M2C | B | 10/22/2002 | 1 | MAXIM INTEG. | | | MAX813LMLP/883B | 429 |
| 5962-9326705MPA | B | 10/22/2002 | 1 | MAXIM INTEG. | | | MAX813LMJA/883B | 429 |
| 5962R93A0101QYC | | 01/25/1993 | | (NONE) | | | 1HL08 (GEN) | 365 |
| 5962-93A0201MXA | A | 03/05/1996 | | (NONE) | | | CF98700JD (GEN) | 399 |
| 5962-93A0301MXA | C | 05/09/1996 | | (NONE) | | | CF98702JD (GEN) | 399 |
| 5962H93A0501QXC | | 02/14/1995 | | (NONE) | | | ST12154 (GEN) | 365 |
| 5962R93A0601QYC | | 04/14/1994 | | (NONE) | | | ST12155 (GEN) | 599 |
| 5962H93A0701VYC | A | 12/27/1995 | | (NONE) | | | ST12156 (GEN) | 365 |
| 5962H93A0801VYA | | 12/05/1995 | | (NONE) | | | ST12157 (GEN) | 429 |
| 5962H93A0901VYC | | 02/14/1995 | | (NONE) | | | ST12158 (GEN) | 365 |
| 5962R93A1001VYC | | 06/09/1994 | | (NONE) | | | ST12159 (GEN) | 399 |
| 5962H93A1101VYC | | 02/14/1995 | | (NONE) | | | ST12169 (GEN) | 365 |
| 5962R93A1201VYC | | 02/15/1994 | | (NONE) | | | ST12171 (GEN) | 399 |
| 5962H93A1301VYC | | 02/14/1995 | | (NONE) | | | ST12237 (GEN) | 365 |
| 5962H93A1601VYC | | 09/15/1994 | | (NONE) | | | 22017351 (GEN) | 365 |
| 5962-93A2101MYC | | 05/03/1994 | | (NONE) | | | L1A8171 (GEN) | 399 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-93A2201MYC | | 05/03/1994 | | (NONE) | | | L1A8155 (GEN) | 599 |
| 5962-93A2301MXA | A | 05/31/1994 | | TI | | | CF68016GB | 439 |
| 5962-93A2301MYA | A | 05/31/1994 | | TI | | | CF68105HFG | 439 |
| 5962-93A2401MXA | A | 05/31/1994 | | TI | | | CF68017GB | 429 |
| 5962-93A2401MYA | A | 05/31/1994 | | TI | | | CF68006HFG | 429 |
| 5962-93A2501MYA | A | 03/03/1999 | 2 | TI | | | CF68010HFG | 365 |
| 5962-93A2601MYA | A | 06/28/1995 | 2 | TI | | | CF68014BHFG | 365 |
| 5962-93A2701MYA | A | 06/28/1995 | 2 | TI | | | CF68107BHFG | 421 |
| 5962-93A2801MYA | | 09/13/1994 | 2 | TI | | | CF68115HFG | 365 |
| 5962-9450101QXA | A | 11/24/1998 | 3 | TI | | Y | SNJ54ABT16241AWD | 529 |
| 5962-9450201QXA | A | 05/23/1997 | 3 | TI | | Y | SNJ54ABT16646WD | 590 |
| 5962-9450202QXA | A | 05/23/1997 | 2 | NATIONAL | | Y | 54ABT16646W-QML | 590 |
| 5962-9450301MZA | | 08/09/1994 | | (NONE) | | | MRG002160A (GEN) | 830 |
| 5962-9450302MYA | | 08/09/1994 | | (NONE) | | | MRG002160B (GEN) | 830 |
| 5962-9450601HXC | B | 06/19/2003 | 1 | DATEL | | Y | MX-826/883 | 199 |
| 5962-9450801Q3A | A | 12/20/2000 | 2 | TI | | Y | SNJ54ABT823FK | 164 |
| 5962-9450801QKA | A | 12/20/2000 | 2 | TI | | Y | SNJ54ABT823W | 164 |
| 5962-9450801QLA | A | 12/20/2000 | 2 | TI | | Y | SNJ54ABT823J | 164 |
| 5962-9450901Q3A | A | 01/12/2001 | 1 | TI | | Y | SNJ54ABT827FK | 569 |
| 5962-9450901QKA | A | 01/12/2001 | 1 | TI | | Y | SNJ54ABT827W | 569 |
| 5962-9450901QLA | A | 01/12/2001 | 1 | TI | | Y | SNJ54ABT827JT | 569 |
| 5962-9451001MXA | | 04/21/1994 | 2 | QP SEMI | | Y | CY7C335-50WMB | 431 |
| 5962-9451001MYA | | 04/21/1994 | 2 | QP SEMI | | Y | CY7C335-50HMB | 431 |
| 5962-9451001MZA | | 04/21/1994 | 2 | QP SEMI | | Y | CY7C335-50QMB | 431 |
| 5962-9451002MXA | | 04/21/1994 | 2 | QP SEMI | | Y | CY7C335-66WMB | 431 |
| 5962-9451002MYA | | 04/21/1994 | 2 | QP SEMI | | Y | CY7C335-66HMB | 431 |
| 5962-9451002MZA | | 04/21/1994 | 2 | CYPRESS | 05/03/2004 | Y | CY7C335-66QMB | 431 |
| 5962-9451002MZA | | 04/21/1994 | 2 | QP SEMI | | Y | CY7C335-66QMB | 431 |
| 5962-9451003MXA | | 04/21/1994 | 2 | QP SEMI | | Y | CY7C335-83WMB | 431 |
| 5962-9451003MYA | | 04/21/1994 | 2 | QP SEMI | | Y | CY7C335-83HMB | 431 |
| 5962-9451003MZA | | 04/21/1994 | 2 | QP SEMI | | Y | CY7C335-83QMB | 431 |
| 5962-9451101MXA | A | 11/20/1996 | | (NONE) | 10/29/2001 | | 72241L50 (GEN) | 670 |
| 5962-9451102MXA | A | 11/20/1996 | | (NONE) | 10/29/2001 | | 72241L35 (GEN) | 670 |
| 5962-9451103MXA | A | 11/20/1996 | | (NONE) | 10/29/2001 | | 72241L25 (GEN) | 670 |
| 5962-9451104MXA | A | 11/20/1996 | | (NONE) | 10/29/2001 | | 72241L20 (GEN) | 670 |
| 5962-9451201M2C | C | 05/13/2004 | 1 | MAXIM INTEG. | | | MAX453MLP/883B | 899 |
| 5962-9451201MPA | C | 05/13/2004 | 1 | MAXIM INTEG. | | | MAX453MJA/883B | 899 |
| 5962-9451202M2C | C | 05/13/2004 | 1 | MAXIM INTEG. | | | MAX455MLP/883B | 899 |
| 5962-9451202MRA | C | 05/13/2004 | 1 | MAXIM INTEG. | | | MAX455MJP/883B | 899 |
| 5962-9451203M2C | C | 05/13/2004 | 1 | MAXIM INTEG. | | | MAX452MLP/883B | 760 |
| 5962-9451203MPA | C | 05/13/2004 | 1 | MAXIM INTEG. | | | MAX452MJA/883B | 760 |
| 5962-9451204M2C | C | 05/13/2004 | 1 | MAXIM INTEG. | | | MAX454MLP/883B | 899 |
| 5962-9451204MCA | C | 05/13/2004 | 1 | MAXIM INTEG. | | | MAX454MJD/883B | 899 |
| 5962-9451301MPA | B | 02/28/2001 | 1 | TI | | Y | UCC1801J/883BC | 787 |
| 5962-9451302MPA | B | 02/28/2001 | 1 | TI | | Y | UCC1802J/883BC | 787 |
| 5962-9451303MPA | B | 02/28/2001 | 1 | TI | | Y | UCC1803J/883BC | 787 |
| 5962-9451304MPA | B | 02/28/2001 | 1 | TI | | Y | UCC1804J/883BC | 787 |
| 5962-9451305MPA | B | 02/28/2001 | 1 | TI | | Y | UCC1805J/883BC | 787 |
| 5962-9451401M2C | B | 05/13/2004 | 1 | MAXIM INTEG. | | | MAX1232MLP/883B | 420 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9451401MPA | B | 05/13/2004 | 1 | MAXIM INTEG. | | | MAX1232MJA/883B | 420 |
| 5962-9451601MPA | | 02/09/1994 | | (NONE) | 03/30/2001 | | LT118A (GEN) | 702 |
| 5962-9451701M2A | C | 01/23/2004 | 1 | NATIONAL | | Y | CLC522AE-QML | 755 |
| 5962-9451701MCA | C | 01/23/2004 | 1 | NATIONAL | | Y | CLC522AJ-QML | 755 |
| 5962-9451801MLA | A | 01/07/2002 | 1 | ANALOG (3) | | Y | AD7837SQ/883B | 591 |
| 5962-9451802MLA | A | 01/07/2002 | 1 | ANALOG (3) | | Y | AD7847SQ/883B | 591 |
| 5962-9452001HXA | A | 07/28/2004 | 1 | INTER. RECT. | | Y | OM3894SFB | 700 |
| 5962-9452001HXC | A | 07/28/2004 | 1 | INTER. RECT. | | Y | OM3894SFC | 700 |
| 5962-9452001HYA | A | 07/28/2004 | 1 | INTER. RECT. | | Y | OM3894SXB | 700 |
| 5962-9452001HYC | A | 07/28/2004 | 1 | INTER. RECT. | | Y | OM3894SXC | 700 |
| 5962-9452101M2A | A | 02/04/2002 | 1 | ANALOG (5) | | Y | OP497BRC/883B | 713 |
| 5962-9452101MCA | A | 02/04/2002 | | (NONE) | 04/16/2002 | | OP497B (GEN) | 713 |
| 5962-9452201MXA | A | 02/06/2001 | 2 | CYPRESS | | Y | CY7B991-7LMB | 509 |
| 5962-9452301MXA | A | 09/25/1996 | | (NONE) | | | U18GM (GEN) | 208 |
| 5962-9452401M3A | | 01/21/1994 | 2 | ATMEL | | | ATV750-35NM/883 | 431 |
| 5962-9452401MLA | | 01/21/1994 | 2 | ATMEL | | | ATV750-35GM/883 | 431 |
| 5962-9452402M3A | | 01/21/1994 | | (NONE) | | | V750-25 (GEN) | 431 |
| 5962-9452402MLA | | 01/21/1994 | | (NONE) | | | V750-25 (GEN) | 431 |
| 5962-9452403M3A | | 01/21/1994 | | (NONE) | | | V750-20 (GEN) | 431 |
| 5962-9452403MLA | | 01/21/1994 | | (NONE) | | | V750-20 (GEN) | 431 |
| 5962-9452404M3A | | 01/21/1994 | 2 | ATMEL | | | ATV750L-30NM/883 | 431 |
| 5962-9452404MLA | | 01/21/1994 | 2 | ATMEL | | | ATV750L-30GM/883 | 431 |
| 5962-9452405M3A | | 01/21/1994 | | (NONE) | | | V750L-25 (GEN) | 431 |
| 5962-9452405MLA | | 01/21/1994 | | (NONE) | | | V750L-25 (GEN) | 431 |
| 5962-9452601M2A | E | 01/29/2004 | | (NONE) | | | LM193 (GEN) | 774 |
| 5962-9452601Q2A | E | 01/29/2004 | 1 | TI | | Y | LM193FKB | 774 |
| 5962-9452601QPA | E | 01/29/2004 | 1 | TI | | Y | LM193JGB | 774 |
| 5962-9452602MGA | E | 01/29/2004 | 1 | NATIONAL | | Y | LM193AH/883 | 774 |
| 5962-9452602VGA | E | 01/29/2004 | 1 | NATIONAL | | Y | LM193AH-QMLV | 774 |
| 5962-9452602MPA | E | 01/29/2004 | 1 | NATIONAL | | Y | LM193AJ/883 | 774 |
| 5962-9452602VPA | E | 01/29/2004 | 1 | NATIONAL | | Y | LM193AJ-QMLV | 774 |
| 5962-9452701M2A | E | 05/25/2004 | | (NONE) | | | MAX500A (GEN) | 591 |
| 5962-9452701MEA | E | 05/25/2004 | | (NONE) | | | MAX500A (GEN) | 591 |
| 5962-9452702M2C | E | 05/25/2004 | 1 | MAXIM INTEG. | | | MAX500BMLP/883B | 591 |
| 5962-9452702MEA | E | 05/25/2004 | 1 | MAXIM INTEG. | | | MAX500BMJE/883B | 591 |
| 5962-9452801QXA | B | 07/28/2003 | 2 | NATIONAL | | Y | 54ACTQ16374FMQB | 158 |
| 5962-9452801VXA | B | 07/28/2003 | 2 | NATIONAL | | Y | 54ACTQ16374W-QV | 158 |
| 5962-9453001M2A | C | 04/14/2004 | 3 | TI | | Y | UC1856L20883B | 787 |
| 5962-9453001MEA | C | 04/14/2004 | 3 | TI | | Y | UC1856J883B | 787 |
| 5962-9453201MXA | | 04/15/1994 | | (NONE) | 12/24/1997 | | 80860 (GEN) | 409 |
| 5962-9453201MYA | | 04/15/1994 | | (NONE) | 12/24/1997 | | 80860 (GEN) | 409 |
| 5962-9453202MXA | | 04/15/1994 | | (NONE) | 12/24/1997 | | 80860 (GEN) | 409 |
| 5962-9453202MYA | | 04/15/1994 | | (NONE) | 12/24/1997 | | 80860 (GEN) | 409 |
| 5962-9453203MXA | | 04/15/1994 | | (NONE) | 12/24/1997 | | 80860 (GEN) | 409 |
| 5962-9453203MYA | | 04/15/1994 | | (NONE) | 12/24/1997 | | 80860 (GEN) | 409 |
| 5962-9453301MXA | | 06/20/1994 | | (NONE) | 12/24/1997 | | 80386SX (GEN) | 404 |
| 5962-9453302MXA | | 06/20/1994 | | (NONE) | 12/24/1997 | | 80386SX (GEN) | 404 |
| 5962-9453401MPA | D | 03/10/2003 | 2 | NATIONAL | | Y | LMC6482AMJ/883 | 710 |
| 5962-9453402MCA | D | 03/10/2003 | 2 | NATIONAL | | Y | LMC6484AMJ/883 | 713 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9453402QXA | D | 03/10/2003 | 2 | NATIONAL | | Y | LMC6484AMWG/883 | 713 |
| 5962-9453402VXA | D | 03/10/2003 | 2 | NATIONAL | | Y | LMC6484AMWG-QV | 713 |
| 5962-9453501HXA | | 03/24/1994 | | (NONE) | | | AD9100SD (GEN) | 818 |
| 5962-9453601HXA | C | 07/16/2004 | 1 | DDC | | Y | SD-14620DX-142 | 594 |
| 5962-9453601HXA | C | 07/16/2004 | 1 | DDC | | Y | SD-14620DX-152 | 594 |
| 5962-9453601HXA | C | 07/16/2004 | 1 | DDC IRELAND | | Y | SD-14620DX-152 | 594 |
| 5962-9453601HXA | C | 07/16/2004 | 1 | DDC IRELAND | | Y | SD-14620DX-142 | 594 |
| 5962-9453601HXC | C | 07/16/2004 | 1 | DDC | | Y | SD-14620DX-132 | 594 |
| 5962-9453601HXC | C | 07/16/2004 | 1 | DDC | | Y | SD-14620DX-112 | 594 |
| 5962-9453601HXC | C | 07/16/2004 | 1 | DDC IRELAND | | Y | SD-14620DX-112 | 594 |
| 5962-9453601HXC | C | 07/16/2004 | 1 | DDC IRELAND | | Y | SD-14620DX-132 | 594 |
| 5962-9453601HYA | C | 07/16/2004 | 1 | DDC | | Y | SD-14620FX-142 | 594 |
| 5962-9453601HYA | C | 07/16/2004 | 1 | DDC | | Y | SD-14620FX-152 | 594 |
| 5962-9453601HYA | C | 07/16/2004 | 1 | DDC IRELAND | | Y | SD-14620FX-152 | 594 |
| 5962-9453601HYA | C | 07/16/2004 | 1 | DDC IRELAND | | Y | SD-14620FX-142 | 594 |
| 5962-9453601HYC | C | 07/16/2004 | 1 | DDC | | Y | SD-14620FX-112 | 594 |
| 5962-9453601HYC | C | 07/16/2004 | 1 | DDC | | Y | SD-14620FX-132 | 594 |
| 5962-9453601HYC | C | 07/16/2004 | 1 | DDC IRELAND | | Y | SD-14620FX-132 | 594 |
| 5962-9453601HYC | C | 07/16/2004 | 1 | DDC IRELAND | | Y | SD-14620FX-112 | 594 |
| 5962-9453602HXA | C | 07/16/2004 | 1 | DDC | | Y | SD-14621DX-152 | 594 |
| 5962-9453602HXA | C | 07/16/2004 | 1 | DDC | | Y | SD-14621DX-142 | 594 |
| 5962-9453602HXA | C | 07/16/2004 | 1 | DDC IRELAND | | Y | SD-14621DX-142 | 594 |
| 5962-9453602HXA | C | 07/16/2004 | 1 | DDC IRELAND | | Y | SD-14621DX-152 | 594 |
| 5962-9453602HXC | C | 07/16/2004 | 1 | DDC | | Y | SD-14621DX-132 | 594 |
| 5962-9453602HXC | C | 07/16/2004 | 1 | DDC | | Y | SD-14621DX-112 | 594 |
| 5962-9453602HXC | C | 07/16/2004 | 1 | DDC IRELAND | | Y | SD-14621DX-112 | 594 |
| 5962-9453602HXC | C | 07/16/2004 | 1 | DDC IRELAND | | Y | SD-14621DX-132 | 594 |
| 5962-9453602HYA | C | 07/16/2004 | 1 | DDC | | Y | SD-14621FX-142 | 594 |
| 5962-9453602HYA | C | 07/16/2004 | 1 | DDC | | Y | SD-14621FX-152 | 594 |
| 5962-9453602HYA | C | 07/16/2004 | 1 | DDC IRELAND | | Y | SD-14621FX-142 | 594 |
| 5962-9453602HYA | C | 07/16/2004 | 1 | DDC IRELAND | | Y | SD-14621FX-152 | 594 |
| 5962-9453602HYC | C | 07/16/2004 | 1 | DDC | | Y | SD-14621FX-132 | 594 |
| 5962-9453602HYC | C | 07/16/2004 | 1 | DDC | | Y | SD-14621FX-112 | 594 |
| 5962-9453602HYC | C | 07/16/2004 | 1 | DDC IRELAND | | Y | SD-14621FX-112 | 594 |
| 5962-9453602HYC | C | 07/16/2004 | 1 | DDC IRELAND | | Y | SD-14621FX-132 | 594 |
| 5962-9453603HXA | C | 07/16/2004 | 1 | DDC | | Y | SD-14620DX-144 | 594 |
| 5962-9453603HXA | C | 07/16/2004 | 1 | DDC | | Y | SD-14620DX-154 | 594 |
| 5962-9453603HXA | C | 07/16/2004 | 1 | DDC IRELAND | | Y | SD-14620DX-154 | 594 |
| 5962-9453603HXA | C | 07/16/2004 | 1 | DDC IRELAND | | Y | SD-14620DX-144 | 594 |
| 5962-9453603HXC | C | 07/16/2004 | 1 | DDC | | Y | SD-14620DX-134 | 594 |
| 5962-9453603HXC | C | 07/16/2004 | 1 | DDC | | Y | SD-14620DX-114 | 594 |
| 5962-9453603HXC | C | 07/16/2004 | 1 | DDC IRELAND | | Y | SD-14620DX-114 | 594 |
| 5962-9453603HXC | C | 07/16/2004 | 1 | DDC IRELAND | | Y | SD-14620DX-134 | 594 |
| 5962-9453603HYA | C | 07/16/2004 | 1 | DDC | | Y | SD-14620FX-154 | 594 |
| 5962-9453603HYA | C | 07/16/2004 | 1 | DDC | | Y | SD-14620FX-144 | 594 |
| 5962-9453603HYA | C | 07/16/2004 | 1 | DDC IRELAND | | Y | SD-14620FX-144 | 594 |
| 5962-9453603HYA | C | 07/16/2004 | 1 | DDC IRELAND | | Y | SD-14620FX-154 | 594 |
| 5962-9453603HYC | C | 07/16/2004 | 1 | DDC | | Y | SD-14620FX-134 | 594 |
| 5962-9453603HYC | C | 07/16/2004 | 1 | DDC | | Y | SD-14620FX-114 | 594 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9453603HYC | C | 07/16/2004 | 1 | DDC IRELAND | | Y | SD-14620FX-114 | 594 |
| 5962-9453603HYC | C | 07/16/2004 | 1 | DDC IRELAND | | Y | SD-14620FX-134 | 594 |
| 5962-9453604HXA | C | 07/16/2004 | 1 | DDC | | Y | SD-14621DX-144 | 594 |
| 5962-9453604HXA | C | 07/16/2004 | 1 | DDC | | Y | SD-14621DX-154 | 594 |
| 5962-9453604HXA | C | 07/16/2004 | 1 | DDC IRELAND | | Y | SD-14621DX-144 | 594 |
| 5962-9453604HXA | C | 07/16/2004 | 1 | DDC IRELAND | | Y | SD-14621DX-154 | 594 |
| 5962-9453604HXC | C | 07/16/2004 | 1 | DDC | | Y | SD-14621DX-114 | 594 |
| 5962-9453604HXC | C | 07/16/2004 | 1 | DDC | | Y | SD-14621DX-134 | 594 |
| 5962-9453604HXC | C | 07/16/2004 | 1 | DDC IRELAND | | Y | SD-14621DX-114 | 594 |
| 5962-9453604HXC | C | 07/16/2004 | 1 | DDC IRELAND | | Y | SD-14621DX-134 | 594 |
| 5962-9453604HYA | C | 07/16/2004 | 1 | DDC | | Y | SD-14621FX-154 | 594 |
| 5962-9453604HYA | C | 07/16/2004 | 1 | DDC | | Y | SD-14621FX-144 | 594 |
| 5962-9453604HYA | C | 07/16/2004 | 1 | DDC IRELAND | | Y | SD-14621FX-144 | 594 |
| 5962-9453604HYA | C | 07/16/2004 | 1 | DDC IRELAND | | Y | SD-14621FX-154 | 594 |
| 5962-9453604HYC | C | 07/16/2004 | 1 | DDC | | Y | SD-14621FX-114 | 594 |
| 5962-9453604HYC | C | 07/16/2004 | 1 | DDC | | Y | SD-14621FX-134 | 594 |
| 5962-9453604HYC | C | 07/16/2004 | 1 | DDC IRELAND | | Y | SD-14621FX-114 | 594 |
| 5962-9453604HYC | C | 07/16/2004 | 1 | DDC IRELAND | | Y | SD-14621FX-134 | 594 |
| 5962-9453605HXA | C | 07/16/2004 | | (NONE) | | | SDC-14621 (GEN) | 594 |
| 5962-9453701MXA | | 09/28/1994 | | (NONE) | | | Z8018008 (GEN) | 429 |
| 5962-9454001MHA | B | 12/13/2000 | | (NONE) | | | MAX630 (GEN) | 786 |
| 5962-9454001MPA | B | 12/13/2000 | 1 | MAXIM INTEG. | | | MAX630MJA/883B | 786 |
| 5962-9454001MXC | B | 12/13/2000 | 1 | MAXIM INTEG. | | | MAX630MFB/883B | 786 |
| 5962-9454201QYA | | 10/12/1994 | | (NONE) | 12/24/1997 | | 82596 (GEN) | 809 |
| 5962-9454301HXA | B | 07/16/2004 | 1 | DDC | | Y | SD-14550DX-142 | 594 |
| 5962-9454301HXA | B | 07/16/2004 | 1 | DDC | | Y | SD-14550DX-152 | 594 |
| 5962-9454301HXA | B | 07/16/2004 | 1 | DDC IRELAND | | Y | SD-14550DX-142 | 594 |
| 5962-9454301HXA | B | 07/16/2004 | 1 | DDC IRELAND | | Y | SD-14550DX-152 | 594 |
| 5962-9454301HXC | B | 07/16/2004 | 1 | DDC | | Y | SD-14550DX-132 | 594 |
| 5962-9454301HXC | B | 07/16/2004 | 1 | DDC | | Y | SD-14550DX-112 | 594 |
| 5962-9454301HXC | B | 07/16/2004 | 1 | DDC IRELAND | | Y | SD-14550DX-132 | 594 |
| 5962-9454301HXC | B | 07/16/2004 | 1 | DDC IRELAND | | Y | SD-14550DX-112 | 594 |
| 5962-9454302HXA | B | 07/16/2004 | 1 | DDC | | Y | SD-14551DX-142 | 594 |
| 5962-9454302HXA | B | 07/16/2004 | 1 | DDC | | Y | SD-14551DX-152 | 594 |
| 5962-9454302HXA | B | 07/16/2004 | 1 | DDC IRELAND | | Y | SD-14551DX-142 | 594 |
| 5962-9454302HXA | B | 07/16/2004 | 1 | DDC IRELAND | | Y | SD-14551DX-152 | 594 |
| 5962-9454302HXC | B | 07/16/2004 | 1 | DDC | | Y | SD-14551DX-132 | 594 |
| 5962-9454302HXC | B | 07/16/2004 | 1 | DDC | | Y | SD-14551DX-112 | 594 |
| 5962-9454302HXC | B | 07/16/2004 | 1 | DDC IRELAND | | Y | SD-14551DX-112 | 594 |
| 5962-9454302HXC | B | 07/16/2004 | 1 | DDC IRELAND | | Y | SD-14551DX-132 | 594 |
| 5962-9454303HXA | B | 07/16/2004 | 1 | DDC | | Y | SD-14550DX-144 | 594 |
| 5962-9454303HXA | B | 07/16/2004 | 1 | DDC | | Y | SD-14550DX-154 | 594 |
| 5962-9454303HXA | B | 07/16/2004 | 1 | DDC IRELAND | | Y | SD-14550DX-154 | 594 |
| 5962-9454303HXA | B | 07/16/2004 | 1 | DDC IRELAND | | Y | SD-14550DX-144 | 594 |
| 5962-9454303HXC | B | 07/16/2004 | 1 | DDC | | Y | SD-14550DX-134 | 594 |
| 5962-9454303HXC | B | 07/16/2004 | 1 | DDC | | Y | SD-14550DX-114 | 594 |
| 5962-9454303HXC | B | 07/16/2004 | 1 | DDC IRELAND | | Y | SD-14550DX-114 | 594 |
| 5962-9454303HXC | B | 07/16/2004 | 1 | DDC IRELAND | | Y | SD-14550DX-134 | 594 |
| 5962-9454304HXA | B | 07/16/2004 | 1 | DDC | | Y | SD-14551DX-144 | 594 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9454304HXA | B | 07/16/2004 | 1 | DDC | | Y | SD-14551DX-154 | 594 |
| 5962-9454304HXA | B | 07/16/2004 | 1 | DDC IRELAND | | Y | SD-14551DX-154 | 594 |
| 5962-9454304HXA | B | 07/16/2004 | 1 | DDC IRELAND | | Y | SD-14551DX-144 | 594 |
| 5962-9454304HXC | B | 07/16/2004 | 1 | DDC | | Y | SD-14551DX-114 | 594 |
| 5962-9454305HXC | B | 07/16/2004 | 1 | DDC | | Y | SD-14551DX-601 | 594 |
| 5962-9454305HXC | B | 07/16/2004 | 1 | DDC IRELAND | | Y | SD-14551DX-601 | 594 |
| 5962-9454401HXA | C | 07/16/2004 | 1 | DDC | | Y | SD-14552DX-142 | 594 |
| 5962-9454401HXA | C | 07/16/2004 | 1 | DDC | | Y | SD-14552DX-152 | 594 |
| 5962-9454401HXA | C | 07/16/2004 | 1 | DDC IRELAND | | Y | SD-14552DX-142 | 594 |
| 5962-9454401HXA | C | 07/16/2004 | 1 | DDC IRELAND | | Y | SD-14552DX-152 | 594 |
| 5962-9454401HXC | C | 07/16/2004 | 1 | DDC | | Y | SD-14552DX-132 | 594 |
| 5962-9454401HXC | C | 07/16/2004 | 1 | DDC | | Y | SD-14552DX-112 | 594 |
| 5962-9454401HXC | C | 07/16/2004 | 1 | DDC IRELAND | | Y | SD-14552DX-112 | 594 |
| 5962-9454401HXC | C | 07/16/2004 | 1 | DDC IRELAND | | Y | SD-14552DX-132 | 594 |
| 5962-9454402HXA | C | 07/16/2004 | 1 | DDC | | Y | SD-14554DX-142 | 594 |
| 5962-9454402HXA | C | 07/16/2004 | 1 | DDC | | Y | SD-14554DX-152 | 594 |
| 5962-9454402HXA | C | 07/16/2004 | 1 | DDC IRELAND | | Y | SD-14554DX-142 | 594 |
| 5962-9454402HXA | C | 07/16/2004 | 1 | DDC IRELAND | | Y | SD-14554DX-152 | 594 |
| 5962-9454402HXC | C | 07/16/2004 | 1 | DDC | | Y | SD-14554DX-132 | 594 |
| 5962-9454402HXC | C | 07/16/2004 | 1 | DDC | | Y | SD-14554DX-112 | 594 |
| 5962-9454402HXC | C | 07/16/2004 | 1 | DDC IRELAND | | Y | SD-14554DX-112 | 594 |
| 5962-9454402HXC | C | 07/16/2004 | 1 | DDC IRELAND | | Y | SD-14554DX-132 | 594 |
| 5962-9454403HXA | C | 07/16/2004 | 1 | DDC | | Y | SD-14552DX-144 | 594 |
| 5962-9454403HXA | C | 07/16/2004 | 1 | DDC | | Y | SD-14552DX-154 | 594 |
| 5962-9454403HXA | C | 07/16/2004 | 1 | DDC IRELAND | | Y | SD-14552DX-154 | 594 |
| 5962-9454403HXA | C | 07/16/2004 | 1 | DDC IRELAND | | Y | SD-14552DX-144 | 594 |
| 5962-9454403HXC | C | 07/16/2004 | 1 | DDC | | Y | SD-14552DX-134 | 594 |
| 5962-9454403HXC | C | 07/16/2004 | 1 | DDC | | Y | SD-14552DX-114 | 594 |
| 5962-9454403HXC | C | 07/16/2004 | 1 | DDC IRELAND | | Y | SD-14552DX-114 | 594 |
| 5962-9454403HXC | C | 07/16/2004 | 1 | DDC IRELAND | | Y | SD-14552DX-134 | 594 |
| 5962-9454404HXA | C | 07/16/2004 | 1 | DDC | | Y | SD-14554DX-144 | 594 |
| 5962-9454404HXA | C | 07/16/2004 | 1 | DDC | | Y | SD-14554DX-154 | 594 |
| 5962-9454404HXA | C | 07/16/2004 | 1 | DDC IRELAND | | Y | SD-14554DX-144 | 594 |
| 5962-9454404HXA | C | 07/16/2004 | 1 | DDC IRELAND | | Y | SD-14554DX-154 | 594 |
| 5962-9454404HXC | C | 07/16/2004 | 1 | DDC | | Y | SD-14554DX-134 | 594 |
| 5962-9454404HXC | C | 07/16/2004 | 1 | DDC | | Y | SD-14554DX-114 | 594 |
| 5962-9454404HXC | C | 07/16/2004 | 1 | DDC IRELAND | | Y | SD-14554DX-114 | 594 |
| 5962-9454404HXC | C | 07/16/2004 | 1 | DDC IRELAND | | Y | SD-14554DX-134 | 594 |
| 5962-9454501HXA | B | 07/16/2004 | 1 | DDC | | Y | SD-14553DX-142 | 594 |
| 5962-9454501HXA | B | 07/16/2004 | 1 | DDC | | Y | SD-14553DX-152 | 594 |
| 5962-9454501HXA | B | 07/16/2004 | 1 | DDC IRELAND | | Y | SD-14553DX-142 | 594 |
| 5962-9454501HXA | B | 07/16/2004 | 1 | DDC IRELAND | | Y | SD-14553DX-152 | 594 |
| 5962-9454501HXC | B | 07/16/2004 | 1 | DDC | | Y | SD-14553DX-132 | 594 |
| 5962-9454501HXC | B | 07/16/2004 | 1 | DDC | | Y | SD-14553DX-112 | 594 |
| 5962-9454501HXC | B | 07/16/2004 | 1 | DDC IRELAND | | Y | SD-14553DX-112 | 594 |
| 5962-9454501HXC | B | 07/16/2004 | 1 | DDC IRELAND | | Y | SD-14553DX-132 | 594 |
| 5962-9454502HXA | B | 07/16/2004 | 1 | DDC | | Y | SD-14553DX-144 | 594 |
| 5962-9454502HXA | B | 07/16/2004 | 1 | DDC | | Y | SD-14553DX-154 | 594 |
| 5962-9454502HXA | B | 07/16/2004 | 1 | DDC IRELAND | | Y | SD-14553DX-154 | 594 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9454502HXA | B | 07/16/2004 | 1 | DDC IRELAND | | Y | SD-14553DX-144 | 594 |
| 5962-9454502HXC | B | 07/16/2004 | 1 | DDC | | Y | SD-14553DX-134 | 594 |
| 5962-9454502HXC | B | 07/16/2004 | 1 | DDC | | Y | SD-14553DX-114 | 594 |
| 5962-9454502HXC | B | 07/16/2004 | 1 | DDC IRELAND | | Y | SD-14553DX-134 | 594 |
| 5962-9454502HXC | B | 07/16/2004 | 1 | DDC IRELAND | | Y | SD-14553DX-114 | 594 |
| 5962-9454701HXA | D | 07/16/2004 | 1 | DDC | | Y | SD-14622DX-152 | 594 |
| 5962-9454701HXA | D | 07/16/2004 | 1 | DDC | | Y | SD-14622DX-142 | 594 |
| 5962-9454701HXA | D | 07/16/2004 | 1 | DDC IRELAND | | Y | SD-14622DX-152 | 594 |
| 5962-9454701HXA | D | 07/16/2004 | 1 | DDC IRELAND | | Y | SD-14622DX-142 | 594 |
| 5962-9454701HXC | D | 07/16/2004 | 1 | DDC | | Y | SD-14622DX-112 | 594 |
| 5962-9454701HXC | D | 07/16/2004 | 1 | DDC | | Y | SD-14622DX-132 | 594 |
| 5962-9454701HXC | D | 07/16/2004 | 1 | DDC IRELAND | | Y | SD-14622DX-112 | 594 |
| 5962-9454701HXC | D | 07/16/2004 | 1 | DDC IRELAND | | Y | SD-14622DX-132 | 594 |
| 5962-9454701HYA | D | 07/16/2004 | 1 | DDC | | Y | SD-14622FX-142 | 594 |
| 5962-9454701HYA | D | 07/16/2004 | 1 | DDC | | Y | SD-14622FX-152 | 594 |
| 5962-9454701HYC | D | 07/16/2004 | 1 | DDC | | Y | SD-14622FX-112 | 594 |
| 5962-9454701HYC | D | 07/16/2004 | 1 | DDC | | Y | SD-14622FX-132 | 594 |
| 5962-9454702HXA | D | 07/16/2004 | 1 | DDC | | Y | SD-14624DX-142 | 594 |
| 5962-9454702HXA | D | 07/16/2004 | 1 | DDC | | Y | SD-14624DX-152 | 594 |
| 5962-9454702HXA | D | 07/16/2004 | 1 | DDC IRELAND | | Y | SD-14624DX-142 | 594 |
| 5962-9454702HXA | D | 07/16/2004 | 1 | DDC IRELAND | | Y | SD-14624DX-152 | 594 |
| 5962-9454702HXC | D | 07/16/2004 | 1 | DDC | | Y | SD-14624DX-132 | 594 |
| 5962-9454702HXC | D | 07/16/2004 | 1 | DDC | | Y | SD-14624DX-112 | 594 |
| 5962-9454702HXC | D | 07/16/2004 | 1 | DDC IRELAND | | Y | SD-14624DX-132 | 594 |
| 5962-9454702HXC | D | 07/16/2004 | 1 | DDC IRELAND | | Y | SD-14624DX-112 | 594 |
| 5962-9454702HYA | D | 07/16/2004 | 1 | DDC | | Y | SD-14624FX-142 | 594 |
| 5962-9454702HYA | D | 07/16/2004 | 1 | DDC | | Y | SD-14624FX-152 | 594 |
| 5962-9454702HYC | D | 07/16/2004 | 1 | DDC | | Y | SD-14624FX-112 | 594 |
| 5962-9454702HYC | D | 07/16/2004 | 1 | DDC | | Y | SD-14624FX-132 | 594 |
| 5962-9454703HXA | D | 07/16/2004 | 1 | DDC | | Y | SD-14622DX-154 | 594 |
| 5962-9454703HXA | D | 07/16/2004 | 1 | DDC | | Y | SD-14622DX-144 | 594 |
| 5962-9454703HXA | D | 07/16/2004 | 1 | DDC IRELAND | | Y | SD-14622DX-154 | 594 |
| 5962-9454703HXA | D | 07/16/2004 | 1 | DDC IRELAND | | Y | SD-14622DX-144 | 594 |
| 5962-9454703HXC | D | 07/16/2004 | 1 | DDC | | Y | SD-14622DX-134 | 594 |
| 5962-9454703HXC | D | 07/16/2004 | 1 | DDC | | Y | SD-14622DX-114 | 594 |
| 5962-9454703HXC | D | 07/16/2004 | 1 | DDC IRELAND | | Y | SD-14622DX-112 | 594 |
| 5962-9454703HXC | D | 07/16/2004 | 1 | DDC IRELAND | | Y | SD-14622DX-134 | 594 |
| 5962-9454703HYA | D | 07/16/2004 | 1 | DDC | | Y | SD-14622FX-154 | 594 |
| 5962-9454703HYA | D | 07/16/2004 | 1 | DDC | | Y | SD-14622FX-144 | 594 |
| 5962-9454703HYC | D | 07/16/2004 | 1 | DDC | | Y | SD-14622FX-114 | 594 |
| 5962-9454703HYC | D | 07/16/2004 | 1 | DDC | | Y | SD-14622FX-134 | 594 |
| 5962-9454704HXA | D | 07/16/2004 | 1 | DDC | | Y | SD-14624DX-144 | 594 |
| 5962-9454704HXA | D | 07/16/2004 | 1 | DDC | | Y | SD-14624DX-154 | 594 |
| 5962-9454704HXA | D | 07/16/2004 | 1 | DDC IRELAND | | Y | SD-14624DX-144 | 594 |
| 5962-9454704HXA | D | 07/16/2004 | 1 | DDC IRELAND | | Y | SD-14624DX-154 | 594 |
| 5962-9454704HXC | D | 07/16/2004 | 1 | DDC | | Y | SD-14624DX-134 | 594 |
| 5962-9454704HXC | D | 07/16/2004 | 1 | DDC | | Y | SD-14624DX-114 | 594 |
| 5962-9454704HXC | D | 07/16/2004 | 1 | DDC IRELAND | | Y | SD-14624DX-114 | 594 |
| 5962-9454704HXC | D | 07/16/2004 | 1 | DDC IRELAND | | Y | SD-14624DX-134 | 594 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9454704HYA | D | 07/16/2004 | 1 | DDC | | Y | SD-14624FX-154 | 594 |
| 5962-9454704HYA | D | 07/16/2004 | 1 | DDC | | Y | SD-14624FX-144 | 594 |
| 5962-9454704HYC | D | 07/16/2004 | 1 | DDC | | Y | SD-14624FX-114 | 594 |
| 5962-9454704HYC | D | 07/16/2004 | 1 | DDC | | Y | SD-14624FX-134 | 594 |
| 5962-9454801HXA | C | 07/16/2004 | 1 | DDC | | Y | SD-14623DX-142 | 594 |
| 5962-9454801HXA | C | 07/16/2004 | 1 | DDC | | Y | SD-14623DX-152 | 594 |
| 5962-9454801HXA | C | 07/16/2004 | 1 | DDC IRELAND | | Y | SD-14623DX-152 | 594 |
| 5962-9454801HXA | C | 07/16/2004 | 1 | DDC IRELAND | | Y | SD-14623DX-142 | 594 |
| 5962-9454801HXC | C | 07/16/2004 | 1 | DDC | | Y | SD-14623DX-132 | 594 |
| 5962-9454801HXC | C | 07/16/2004 | 1 | DDC | | Y | SD-14623DX-112 | 594 |
| 5962-9454801HXC | C | 07/16/2004 | 1 | DDC IRELAND | | Y | SD-14623DX-132 | 594 |
| 5962-9454801HXC | C | 07/16/2004 | 1 | DDC IRELAND | | Y | SD-14623DX-112 | 594 |
| 5962-9454801HYA | C | 07/16/2004 | 1 | DDC | | Y | SD-14623FX-142 | 594 |
| 5962-9454801HYA | C | 07/16/2004 | 1 | DDC | | Y | SD-14623FX-152 | 594 |
| 5962-9454801HYA | C | 07/16/2004 | 1 | DDC IRELAND | | Y | SD-14623FX-142 | 594 |
| 5962-9454801HYA | C | 07/16/2004 | 1 | DDC IRELAND | | Y | SD-14623FX-152 | 594 |
| 5962-9454801HYC | C | 07/16/2004 | 1 | DDC | | Y | SD-14623FX-112 | 594 |
| 5962-9454801HYC | C | 07/16/2004 | 1 | DDC | | Y | SD-14623FX-132 | 594 |
| 5962-9454801HYC | C | 07/16/2004 | 1 | DDC IRELAND | | Y | SD-14623FX-132 | 594 |
| 5962-9454801HYC | C | 07/16/2004 | 1 | DDC IRELAND | | Y | SD-14623FX-112 | 594 |
| 5962-9454802HXA | C | 07/16/2004 | 1 | DDC | | Y | SD-14623DX-154 | 594 |
| 5962-9454802HXA | C | 07/16/2004 | 1 | DDC | | Y | SD-14623DX-144 | 594 |
| 5962-9454802HXA | C | 07/16/2004 | 1 | DDC IRELAND | | Y | SD-14623DX-144 | 594 |
| 5962-9454802HXA | C | 07/16/2004 | 1 | DDC IRELAND | | Y | SD-14623DX-154 | 594 |
| 5962-9454802HXC | C | 07/16/2004 | 1 | DDC | | Y | SD-14623DX-114 | 594 |
| 5962-9454802HXC | C | 07/16/2004 | 1 | DDC | | Y | SD-14623DX-134 | 594 |
| 5962-9454802HXC | C | 07/16/2004 | 1 | DDC IRELAND | | Y | SD-14623DX-114 | 594 |
| 5962-9454802HXC | C | 07/16/2004 | 1 | DDC IRELAND | | Y | SD-14623DX-134 | 594 |
| 5962-9454802HYA | C | 07/16/2004 | 1 | DDC | | Y | SD-14623FX-144 | 594 |
| 5962-9454802HYA | C | 07/16/2004 | 1 | DDC | | Y | SD-14623FX-154 | 594 |
| 5962-9454802HYA | C | 07/16/2004 | 1 | DDC IRELAND | | Y | SD-14623FX-154 | 594 |
| 5962-9454802HYA | C | 07/16/2004 | 1 | DDC IRELAND | | Y | SD-14623FX-144 | 594 |
| 5962-9454802HYC | C | 07/16/2004 | 1 | DDC | | Y | SD-14623FX-134 | 594 |
| 5962-9454802HYC | C | 07/16/2004 | 1 | DDC | | Y | SD-14623FX-114 | 594 |
| 5962-9454802HYC | C | 07/16/2004 | 1 | DDC IRELAND | | Y | SD-14623FX-114 | 594 |
| 5962-9454802HYC | C | 07/16/2004 | 1 | DDC IRELAND | | Y | SD-14623FX-134 | 594 |
| 5962-9454901MXA | C | 03/26/1997 | 1 | AUSTIN SEMI. | | Y | SMJ55161-80GBM | 629 |
| 5962-9454901MYC | C | 03/26/1997 | 1 | AUSTIN SEMI. | | Y | SMJ55161-80HKCM | 629 |
| 5962-9454902MXA | C | 03/26/1997 | | (NONE) | | | 55161-70 (GEN) | 629 |
| 5962-9454902MYA | C | 03/26/1997 | | (NONE) | | | 55161-70 (GEN) | 629 |
| 5962-9454903QXA | C | 03/26/1997 | 1 | AUSTIN SEMI. | | Y | SMJ55161-75GBM | 629 |
| 5962-9454903QYC | C | 03/26/1997 | 1 | AUSTIN SEMI. | | Y | SMJ55161-75HKCM | 629 |
| 5962-9455001MXC | | 06/30/1995 | | (NONE) | | | 79R3081E-25 (GEN) | 404 |
| 5962-9455301M2A | | 02/14/1994 | | (NONE) | 12/24/2000 | | HA-5134 (GEN) | 713 |
| 5962-9455301MCA | | 02/14/1994 | | (NONE) | 09/29/2001 | | HA-5134 (GEN) | 713 |
| 5962-9455401M3A | | 03/14/1994 | | (NONE) | 09/01/1997 | | 54F154 (GEN) | 280 |
| 5962-9455401MKA | | 03/14/1994 | | (NONE) | | | 54F154 (GEN) | 280 |
| 5962-9455401MLA | | 03/14/1994 | | (NONE) | 09/01/1997 | | 54F154 (GEN) | 280 |
| 5962-9455501M3A | K | 01/10/2003 | 1 | TI | | Y | UC1875L/883BC | 899 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9455501V3A | K | 01/10/2003 | 1 | TI | | Y | UC1875LQMLV | 899 |
| 5962-9455501MRA | K | 01/10/2003 | 1 | TI | | Y | UC1875J/883BC | 899 |
| 5962-9455501VRA | K | 01/10/2003 | 1 | TI | | Y | UC1875JQMLV | 899 |
| 5962-9455501MXA | K | 01/10/2003 | | (NONE) | | | UC1875 (GEN) | 899 |
| 5962-9455601M2C | B | 03/10/2004 | 1 | MAXIM INTEG. | | | MAX310MLP/883B | 899 |
| 5962-9455601MEA | B | 03/10/2004 | 1 | MAXIM INTEG. | | | MAX310MJE/883B | 899 |
| 5962-9455602M2C | B | 03/10/2004 | 1 | MAXIM INTEG. | | | MAX311MLP/883B | 899 |
| 5962-9455602MEA | B | 03/10/2004 | 1 | MAXIM INTEG. | | | MAX311MJE/883B | 899 |
| 5962-9455701QQA | A | 11/21/1994 | | (NONE) | 12/24/1997 | | 28F008 (GEN) | 669 |
| 5962-9455701QXA | A | 11/21/1994 | | (NONE) | 12/24/1997 | | 28F008 (GEN) | 669 |
| 5962-9455702QQA | A | 11/21/1994 | | (NONE) | 12/24/1997 | | 28F008 (GEN) | 669 |
| 5962-9455702QXA | A | 11/21/1994 | | (NONE) | 12/24/1997 | | 28F008 (GEN) | 669 |
| 5962-9455801QXA | D | 11/15/1999 | | (NONE) | | | 320C50A40 (GEN) | 432 |
| 5962-9455801QYA | D | 11/15/1999 | | (NONE) | | | 320C50A40 (GEN) | 432 |
| 5962-9455802QXA | D | 11/15/1999 | | (NONE) | | | 320C50A50 (GEN) | 432 |
| 5962-9455802QYA | D | 11/15/1999 | | (NONE) | | | 320C50A50 (GEN) | 432 |
| 5962-9455803Q9A | D | 11/15/1999 | 2 | TI | | Y | SMJ320C50KGDM50B | 432 |
| 5962-9455803QXA | D | 11/15/1999 | 2 | TI | | Y | SMJ320C50GFAM50 | 432 |
| 5962-9455803QYA | D | 11/15/1999 | 2 | TI | | Y | SMJ320C50HFGM50 | 432 |
| 5962-9455804Q9A | D | 11/15/1999 | 2 | TI | | Y | SMJ320C50KGDM66B | 432 |
| 5962-9455804QXA | D | 11/15/1999 | 2 | TI | | Y | SMJ320C50GFAM66 | 432 |
| 5962-9455804QYA | D | 11/15/1999 | 2 | TI | | Y | SMJ320C50HFGM66 | 432 |
| 5962-9455804NZB | D | 11/15/1999 | 2 | TI | | Y | SMJ320C50PQM66 | 432 |
| 5962-9455805Q9A | D | 11/15/1999 | 2 | TI | | Y | SMJ320C50KGDM40B | 432 |
| 5962-9455901Q2A | A | 06/02/1994 | | (NONE) | 09/30/1995 | | 54F13 (GEN) | 104 |
| 5962-9455901QCA | A | 06/02/1994 | | (NONE) | 09/30/1995 | | 54F13 (GEN) | 104 |
| 5962-9455901QDA | A | 06/02/1994 | | (NONE) | 09/30/1995 | | 54F13 (GEN) | 104 |
| 5962-9456101MGA | A | 01/02/1996 | | (NONE) | 09/09/1998 | | LM169 (GEN) | 785 |
| 5962-9456201M2A | | 03/31/1994 | | (NONE) | 12/24/2000 | | HI-0222 (GEN) | 899 |
| 5962-9456201MCA | | 03/31/1994 | | (NONE) | | | HI-0222 (GEN) | 899 |
| 5962-9456301HXA | C | 02/17/2004 | 1 | ADV. ANALOG | | Y | AHF2815S/CH | 594 |
| 5962-9456301HXC | C | 02/17/2004 | 1 | ADV. ANALOG | | Y | AHF2815S/CH | 594 |
| 5962-9456301HZA | C | 02/17/2004 | 1 | ADV. ANALOG | | Y | AHF2815SF/CH | 594 |
| 5962-9456301HZC | C | 02/17/2004 | 1 | ADV. ANALOG | | Y | AHF2815SF/CH | 594 |
| 5962-9456401QXA | | 04/20/1994 | | (NONE) | 09/30/1995 | | 56002-40 (GEN) | 432 |
| 5962-9456501M2C | A | 03/26/2002 | 1 | MAXIM INTEG. | | | MAX220MLP/883B | 590 |
| 5962-9456501MEA | A | 03/26/2002 | 1 | MAXIM INTEG. | | | MAX220MJE/883B | 590 |
| 5962-9456502M2C | A | 03/26/2002 | 1 | MAXIM INTEG. | | | MAX222MLP/883B | 590 |
| 5962-9456502MVA | A | 03/26/2002 | 1 | MAXIM INTEG. | | | MAX222MJN/883B | 590 |
| 5962-9456503M2C | A | 03/26/2002 | 1 | MAXIM INTEG. | | | MAX232AMLP/883B | 590 |
| 5962-9456503MEA | A | 03/26/2002 | 1 | MAXIM INTEG. | | | MAX232AMJE/883B | 590 |
| 5962-9456504M2C | A | 03/26/2002 | 1 | MAXIM INTEG. | | | MAX242MLP/883B | 590 |
| 5962-9456504MVA | A | 03/26/2002 | 1 | MAXIM INTEG. | | | MAX242MJN/883B | 590 |
| 5962-9456505M2C | A | 03/26/2002 | 1 | MAXIM INTEG. | | | MAX243MLP/883B | 590 |
| 5962-9456505MEA | A | 03/26/2002 | 1 | MAXIM INTEG. | | | MAX243MJE/883B | 590 |
| 5962-9456601MPA | A | 10/23/2001 | 1 | NATIONAL | | Y | CLC411AJ-QML | 760 |
| 5962-9456701QXA | | 02/20/1996 | | (NONE) | | | 7C443-30 (GEN) | 670 |
| 5962-9456701QYA | | 02/20/1996 | | (NONE) | | | 7C443-30 (GEN) | 670 |
| 5962-9456702QXA | | 02/20/1996 | | (NONE) | | | 7C443-20 (GEN) | 670 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9456702QYA | | 02/20/1996 | | (NONE) | | | 7C443-20 (GEN) | 670 |
| 5962-9456703QXA | | 02/20/1996 | | (NONE) | | | 7C443-14 (GEN) | 670 |
| 5962-9456703QYA | | 02/20/1996 | | (NONE) | | | 7C443-14 (GEN) | 670 |
| 5962-9456704QXA | | 02/20/1996 | | (NONE) | | | 7C441-30 (GEN) | 670 |
| 5962-9456704QYA | | 02/20/1996 | | (NONE) | | | 7C441-30 (GEN) | 670 |
| 5962-9456705QXA | | 02/20/1996 | | (NONE) | | | 7C441-20 (GEN) | 670 |
| 5962-9456705QYA | | 02/20/1996 | | (NONE) | | | 7C441-20 (GEN) | 670 |
| 5962-9456706QXA | | 02/20/1996 | | (NONE) | | | 7C441-14 (GEN) | 670 |
| 5962-9456706QYA | | 02/20/1996 | | (NONE) | | | 7C441-14 (GEN) | 670 |
| 5962-9456801HXA | C | 02/18/2004 | 1 | ADV. ANALOG | | Y | AHF2812S/CH | 594 |
| 5962-9456801HXC | C | 02/18/2004 | 1 | ADV. ANALOG | | Y | AHF2812S/CH | 594 |
| 5962-9456801HZA | C | 02/18/2004 | 1 | ADV. ANALOG | | Y | AHF2812SF/CH | 594 |
| 5962-9456801HZC | C | 02/18/2004 | 1 | ADV. ANALOG | | Y | AHF2812SF/CH | 594 |
| 5962-9456901HUA | A | 02/23/2004 | 1 | ADV. ANALOG | | Y | AFL27005SW/CH | 594 |
| 5962-9456901HUC | A | 02/23/2004 | 1 | ADV. ANALOG | | Y | AFL27005SW/CH | 594 |
| 5962-9456901HXA | A | 02/23/2004 | 1 | ADV. ANALOG | | Y | AFL27005SX/CH | 594 |
| 5962-9456901HXC | A | 02/23/2004 | 1 | ADV. ANALOG | | Y | AFL27005SX/CH | 594 |
| 5962-9456901HYA | A | 02/23/2004 | 1 | ADV. ANALOG | | Y | AFL27005SY/CH | 594 |
| 5962-9456901HYC | A | 02/23/2004 | 1 | ADV. ANALOG | | Y | AFL27005SY/CH | 594 |
| 5962-9456901HZA | A | 02/23/2004 | 1 | ADV. ANALOG | | Y | AFL27005SZ/CH | 594 |
| 5962-9456901HZC | A | 02/23/2004 | 1 | ADV. ANALOG | | Y | AFL27005SZ/CH | 594 |
| 5962-9457001HUA | A | 04/23/2004 | 1 | ADV. ANALOG | | Y | AFL27015SW/CH | 594 |
| 5962-9457001HUC | A | 04/23/2004 | 1 | ADV. ANALOG | | Y | AFL27015SW/CH | 594 |
| 5962-9457001HXA | A | 04/23/2004 | 1 | ADV. ANALOG | | Y | AFL27015SX/CH | 594 |
| 5962-9457001HXC | A | 04/23/2004 | 1 | ADV. ANALOG | | Y | AFL27015SX/CH | 594 |
| 5962-9457001HYA | A | 04/23/2004 | 1 | ADV. ANALOG | | Y | AFL27015SY/CH | 594 |
| 5962-9457001HYC | A | 04/23/2004 | 1 | ADV. ANALOG | | Y | AFL27015SY/CH | 594 |
| 5962-9457001HZA | A | 04/23/2004 | 1 | ADV. ANALOG | | Y | AFL27015SZ/CH | 594 |
| 5962-9457001HZC | A | 04/23/2004 | 1 | ADV. ANALOG | | Y | AFL27015SZ/CH | 594 |
| 5962-9457201MEA | A | 01/11/2002 | 2 | ANALOG (2) | | Y | AD600SQ/883B | 750 |
| 5962-9457202MEA | A | 01/11/2002 | 1 | ANALOG (2) | | Y | AD602SQ/883B | 750 |
| 5962-9457203MPA | A | 01/11/2002 | 2 | ANALOG (2) | | Y | AD603SQ/883B | 750 |
| 5962-9457301MXC | A | 07/13/1994 | | (NONE) | 09/29/1999 | | 48410-25 (GEN) | 399 |
| 5962-9457301MYA | A | 07/13/1994 | | (NONE) | | | 48410-39 (GEN) | 399 |
| 5962-9457302MXC | A | 07/13/1994 | | (NONE) | 09/29/1999 | | 48410-33 (GEN) | 399 |
| 5962-9457302MYA | A | 07/13/1994 | | (NONE) | | | 48410-30 (GEN) | 399 |
| 5962-9457401QXA | A | 02/06/2002 | | (NONE) | 12/31/2001 | | 54FB2033 (GEN) | 590 |
| 5962-9457501Q2A | E | 03/31/2004 | 1 | TI | | Y | UCC1806L/883BC | 787 |
| 5962-9457501V2A | E | 03/31/2004 | 1 | TI | | Y | UCC1806LQMLV | 787 |
| 5962-9457501MEA | E | 03/31/2004 | 1 | TI | | Y | UCC1806J/883BC | 787 |
| 5962-9457501VEA | E | 03/31/2004 | 1 | TI | | Y | UCC1806JQMLV | 787 |
| 5962-9457601MYA | A | 09/23/1994 | | (NONE) | | | LT1074 (GEN) | 786 |
| 5962-9457602MYA | A | 09/23/1994 | | (NONE) | | | LT1074HV (GEN) | 786 |
| 5962-9457701M3A | B | 03/14/1997 | | (NONE) | | | 54ABT646 (GEN) | 590 |
| 5962-9457701Q3A | B | 03/14/1997 | 3 | NATIONAL | | Y | 54ABT646E-QML | 590 |
| 5962-9457701MKA | B | 03/14/1997 | | (NONE) | | | 54ABT646 (GEN) | 590 |
| 5962-9457701QKA | B | 03/14/1997 | 3 | NATIONAL | | Y | 54ABT646W-QML | 590 |
| 5962-9457701MLA | B | 03/14/1997 | | (NONE) | | | 54ABT646 (GEN) | 590 |
| 5962-9457701QLA | B | 03/14/1997 | 3 | NATIONAL | | Y | 54ABT646J-QML | 590 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9457702Q3A | B | 03/14/1997 | 3 | TI | | Y | SNJ54ABT646AFK | 590 |
| 5962-9457702QKA | B | 03/14/1997 | 3 | TI | | Y | SNJ54ABT646AW | 590 |
| 5962-9457702QLA | B | 03/14/1997 | 3 | TI | | Y | SNJ54ABT646AJT | 590 |
| 5962-9457801QXC | | 02/05/1997 | | (NONE) | 12/24/1997 | | 8050250 (GEN) | 404 |
| 5962-9457802NXC | | 02/05/1997 | | (NONE) | 12/24/1997 | | 8050250 (GEN) | 404 |
| 5962-9457803NXC | | 02/05/1997 | | (NONE) | 12/24/1997 | | 8050250 (GEN) | 404 |
| 5962-9457804QXC | | 02/05/1997 | | (NONE) | 12/24/1997 | | 8050260 (GEN) | 404 |
| 5962-9457805NXC | | 02/05/1997 | | (NONE) | 12/24/1997 | | 8050260 (GEN) | 404 |
| 5962-9457806NXC | | 02/05/1997 | | (NONE) | 12/24/1997 | | 8050260 (GEN) | 404 |
| 5962-9457807QXC | | 02/05/1997 | | (NONE) | 12/24/1997 | | 8050266 (GEN) | 404 |
| 5962-9457808NXC | | 02/05/1997 | | (NONE) | 12/24/1997 | | 8050266 (GEN) | 404 |
| 5962-9457809NXC | | 02/05/1997 | | (NONE) | 12/24/1997 | | 8050266 (GEN) | 404 |
| 5962-9457901MXA | A | 01/29/2004 | 3 | NATIONAL | | Y | 100351DMQB | 159 |
| 5962-9457901VXA | A | 01/29/2004 | 3 | NATIONAL | | Y | 100351J-QMLV | 159 |
| 5962-9457901MYA | A | 01/29/2004 | 3 | NATIONAL | | Y | 100351FMQB | 159 |
| 5962-9457901VYA | A | 01/29/2004 | 3 | NATIONAL | | Y | 100351W-QMLV | 159 |
| 5962R9457901VYA | A | 01/29/2004 | 3 | NATIONAL | | Y | 100351WRQMLV | 159 |
| 5962-9458101M2A | A | 02/02/2001 | | (NONE) | 04/16/2002 | | OP482A (GEN) | 702 |
| 5962-9458101MCA | A | 02/02/2001 | | (NONE) | 04/16/2002 | | OP482A (GEN) | 702 |
| 5962-9458201MRA | | 04/18/1994 | | (NONE) | 09/01/1997 | | 568A (GEN) | 803 |
| 5962-9458501H4A | J | 10/06/2003 | 1 | AEROFLEX | | Y | ACT-E128K32N-300P7 | 669 |
| 5962-9458501H4A | J | 10/06/2003 | 1 | AUSTIN SEMI. | | Y | AS8E128K32PN-300/88 | 669 |
| 5962-9458501H4A | J | 10/06/2003 | 1 | WHITE ELEC. | | Y | WE128K32N-300H1Q | 669 |
| 5962-9458501H4C | J | 10/06/2003 | 1 | AEROFLEX | | Y | ACT-E128K32N-300P7 | 669 |
| 5962-9458501H4C | J | 10/06/2003 | 1 | AUSTIN SEMI. | | Y | AS8E128K32PN-300/88 | 669 |
| 5962-9458501H4C | J | 10/06/2003 | 1 | WHITE ELEC. | | Y | WE128K32N-300H1Q | 669 |
| 5962-9458501H5A | J | 10/06/2003 | 1 | AEROFLEX | | Y | ACT-E128K32C-300P7 | 669 |
| 5962-9458501H5A | J | 10/06/2003 | 1 | AUSTIN SEMI. | | Y | AS8E128K32P-300/883 | 669 |
| 5962-9458501H5A | J | 10/06/2003 | 1 | WHITE ELEC. | | Y | WE128K32-300H1Q | 669 |
| 5962-9458501H5C | J | 10/06/2003 | 1 | AEROFLEX | | Y | ACT-E128K32C-300P7 | 669 |
| 5962-9458501H5C | J | 10/06/2003 | 1 | AUSTIN SEMI. | | Y | AS8E128K32P-300/883 | 669 |
| 5962-9458501H5C | J | 10/06/2003 | 1 | WHITE ELEC. | | Y | WE128K32-300H1Q | 669 |
| 5962-9458501H6A | J | 10/06/2003 | 1 | WHITE ELEC. | | Y | WE128K32NP-300H1Q | 669 |
| 5962-9458501H6C | J | 10/06/2003 | 1 | WHITE ELEC. | | Y | WE128K32NP-300H1Q | 669 |
| 5962-9458501H9A | J | 10/06/2003 | 1 | WHITE ELEC. | | Y | WE128K32-300G1UQ | 669 |
| 5962-9458501H9C | J | 10/06/2003 | 1 | WHITE ELEC. | | Y | WE128K32-300G1UQ | 669 |
| 5962-9458501HBA | J | 10/06/2003 | 1 | WHITE ELEC. | | Y | WE128K32-300G1TQ | 669 |
| 5962-9458501HBC | J | 10/06/2003 | 1 | WHITE ELEC. | | Y | WE128K32-300G1TQ | 669 |
| 5962-9458501HMA | J | 10/06/2003 | 1 | AEROFLEX | | Y | ACT-E128K32N-300F2 | 669 |
| 5962-9458501HMA | J | 10/06/2003 | 1 | AUSTIN SEMI. | | Y | AS8E128K32Q-300/883 | 669 |
| 5962-9458501HMA | J | 10/06/2003 | 1 | WHITE ELEC. | | Y | WE128K32-300G2Q | 669 |
| 5962-9458501HMC | J | 10/06/2003 | 1 | AEROFLEX | | Y | ACT-E128K32N-300F2 | 669 |
| 5962-9458501HMC | J | 10/06/2003 | 1 | AUSTIN SEMI. | | Y | AS8E128K32Q-300/883 | 669 |
| 5962-9458501HMC | J | 10/06/2003 | 1 | WHITE ELEC. | | Y | WE128K32-300G2Q | 669 |
| 5962-9458501HNC | J | 10/06/2003 | 1 | WHITE ELEC. | | Y | WE128K32-300G4Q | 669 |
| 5962-9458501HTA | J | 10/06/2003 | 1 | WHITE ELEC. | | Y | WE128K32N-300HQ | 669 |
| 5962-9458501HTC | J | 10/06/2003 | 1 | WHITE ELEC. | | Y | WE128K32N-300HQ | 669 |
| 5962-9458501HUA | J | 10/06/2003 | 1 | WHITE ELEC. | | Y | WE128K32N-300HQ | 669 |
| 5962-9458501HUC | J | 10/06/2003 | 1 | WHITE ELEC. | | Y | WE128K32N-300HQ | 669 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9458501HXA | J | 10/06/2003 | 1 | WHITE ELEC. | | Y | WE128K32-300HQ | 669 |
| 5962-9458501HXC | J | 10/06/2003 | 1 | WHITE ELEC. | | Y | WE128K32-300HQ | 669 |
| 5962-9458501HYA | J | 10/06/2003 | 1 | WHITE ELEC. | | Y | WE128K32-300HQ | 669 |
| 5962-9458501HYC | J | 10/06/2003 | 1 | WHITE ELEC. | | Y | WE128K32-300HQ | 669 |
| 5962-9458502H4A | J | 10/06/2003 | 1 | AEROFLEX | | Y | ACT-E128K32N-250P7 | 669 |
| 5962-9458502H4A | J | 10/06/2003 | 1 | AUSTIN SEMI. | | Y | AS8E128K32PN-250/88 | 669 |
| 5962-9458502H4A | J | 10/06/2003 | 1 | WHITE ELEC. | | Y | WE128K32N-250H1Q | 669 |
| 5962-9458502H4C | J | 10/06/2003 | 1 | AEROFLEX | | Y | ACT-E128K32N-250P7 | 669 |
| 5962-9458502H4C | J | 10/06/2003 | 1 | AUSTIN SEMI. | | Y | AS8E128K32PN-250/88 | 669 |
| 5962-9458502H4C | J | 10/06/2003 | 1 | WHITE ELEC. | | Y | WE128K32N-250H1Q | 669 |
| 5962-9458502H5A | J | 10/06/2003 | 1 | AEROFLEX | | Y | ACT-E128K32C-250P7 | 669 |
| 5962-9458502H5A | J | 10/06/2003 | 1 | AUSTIN SEMI. | | Y | AS8E128K32P-250/883 | 669 |
| 5962-9458502H5A | J | 10/06/2003 | 1 | WHITE ELEC. | | Y | WE128K32-250H1Q | 669 |
| 5962-9458502H5C | J | 10/06/2003 | 1 | AEROFLEX | | Y | ACT-E128K32C-250P7 | 669 |
| 5962-9458502H5C | J | 10/06/2003 | 1 | AUSTIN SEMI. | | Y | AS8E128K32P-250/883 | 669 |
| 5962-9458502H5C | J | 10/06/2003 | 1 | WHITE ELEC. | | Y | WE128K32-250H1Q | 669 |
| 5962-9458502H6A | J | 10/06/2003 | 1 | WHITE ELEC. | | Y | WE128K32NP-250H1Q | 669 |
| 5962-9458502H6C | J | 10/06/2003 | 1 | WHITE ELEC. | | Y | WE128K32NP-250H1Q | 669 |
| 5962-9458502H9A | J | 10/06/2003 | 1 | WHITE ELEC. | | Y | WE128K32-250G1UQ | 669 |
| 5962-9458502H9C | J | 10/06/2003 | 1 | WHITE ELEC. | | Y | WE128K32-250G1UQ | 669 |
| 5962-9458502HBA | J | 10/06/2003 | 1 | WHITE ELEC. | | Y | WE128K32-250G1TQ | 669 |
| 5962-9458502HBC | J | 10/06/2003 | 1 | WHITE ELEC. | | Y | WE128K32-250G1TQ | 669 |
| 5962-9458502HMA | J | 10/06/2003 | 1 | AEROFLEX | | Y | ACT-E128K32N-250F2 | 669 |
| 5962-9458502HMA | J | 10/06/2003 | 1 | AUSTIN SEMI. | | Y | AS8E128K32Q-250/883 | 669 |
| 5962-9458502HMA | J | 10/06/2003 | 1 | WHITE ELEC. | | Y | WE128K32-250G2Q | 669 |
| 5962-9458502HMC | J | 10/06/2003 | 1 | AEROFLEX | | Y | ACT-E128K32N-250F2 | 669 |
| 5962-9458502HMC | J | 10/06/2003 | 1 | AUSTIN SEMI. | | Y | AS8E128K32Q-250/883 | 669 |
| 5962-9458502HMC | J | 10/06/2003 | 1 | WHITE ELEC. | | Y | WE128K32-250G2Q | 669 |
| 5962-9458502HNC | J | 10/06/2003 | 1 | WHITE ELEC. | | Y | WE128K32-250G4Q | 669 |
| 5962-9458502HTA | J | 10/06/2003 | 1 | WHITE ELEC. | | Y | WE128K32N-250HQ | 669 |
| 5962-9458502HTC | J | 10/06/2003 | 1 | WHITE ELEC. | | Y | WE128K32N-250HQ | 669 |
| 5962-9458502HUA | J | 10/06/2003 | 1 | WHITE ELEC. | | Y | WE128K32N-250HQ | 669 |
| 5962-9458502HUC | J | 10/06/2003 | 1 | WHITE ELEC. | | Y | WE128K32N-250HQ | 669 |
| 5962-9458502HXA | J | 10/06/2003 | 1 | WHITE ELEC. | | Y | WE128K32-250HQ | 669 |
| 5962-9458502HXC | J | 10/06/2003 | 1 | WHITE ELEC. | | Y | WE128K32-250HQ | 669 |
| 5962-9458502HYA | J | 10/06/2003 | 1 | WHITE ELEC. | | Y | WE128K32-250HQ | 669 |
| 5962-9458502HYC | J | 10/06/2003 | 1 | WHITE ELEC. | | Y | WE128K32-250HQ | 669 |
| 5962-9458503H4A | J | 10/06/2003 | 1 | AEROFLEX | | Y | ACT-E128K32N-200P7 | 669 |
| 5962-9458503H4A | J | 10/06/2003 | 1 | AUSTIN SEMI. | | Y | AS8E128K32PN-200/88 | 669 |
| 5962-9458503H4A | J | 10/06/2003 | 1 | WHITE ELEC. | | Y | WE128K32N-200H1Q | 669 |
| 5962-9458503H4C | J | 10/06/2003 | 1 | AEROFLEX | | Y | ACT-E128K32N-200P7 | 669 |
| 5962-9458503H4C | J | 10/06/2003 | 1 | AUSTIN SEMI. | | Y | AS8E128K32PN-200/88 | 669 |
| 5962-9458503H4C | J | 10/06/2003 | 1 | WHITE ELEC. | | Y | WE128K32N-200H1Q | 669 |
| 5962-9458503H5A | J | 10/06/2003 | 1 | AEROFLEX | | Y | ACT-E128K32C-200P7 | 669 |
| 5962-9458503H5A | J | 10/06/2003 | 1 | AUSTIN SEMI. | | Y | AS8E128K32P-200/883 | 669 |
| 5962-9458503H5A | J | 10/06/2003 | 1 | WHITE ELEC. | | Y | WE128K32-200H1Q | 669 |
| 5962-9458503H5C | J | 10/06/2003 | 1 | AEROFLEX | | Y | ACT-E128K32C-200P7 | 669 |
| 5962-9458503H5C | J | 10/06/2003 | 1 | AUSTIN SEMI. | | Y | AS8E128K32P-200/883 | 669 |
| 5962-9458503H5C | J | 10/06/2003 | 1 | WHITE ELEC. | | Y | WE128K32-200H1Q | 669 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9458503H6A | J | 10/06/2003 | 1 | WHITE ELEC. | | Y | WE128K32NP-200H1Q | 669 |
| 5962-9458503H6C | J | 10/06/2003 | 1 | WHITE ELEC. | | Y | WE128K32NP-200H1Q | 669 |
| 5962-9458503H9A | J | 10/06/2003 | 1 | WHITE ELEC. | | Y | WE128K32-200G1UQ | 669 |
| 5962-9458503H9C | J | 10/06/2003 | 1 | WHITE ELEC. | | Y | WE128K32-200G1UQ | 669 |
| 5962-9458503HBA | J | 10/06/2003 | 1 | WHITE ELEC. | | Y | WE128K32-200G1TQ | 669 |
| 5962-9458503HBC | J | 10/06/2003 | 1 | WHITE ELEC. | | Y | WE128K32-200G1TQ | 669 |
| 5962-9458503HMA | J | 10/06/2003 | 1 | AEROFLEX | | Y | ACT-E128K32N-200F2 | 669 |
| 5962-9458503HMA | J | 10/06/2003 | 1 | AUSTIN SEMI. | | Y | AS8E128K32Q-200/883 | 669 |
| 5962-9458503HMA | J | 10/06/2003 | 1 | WHITE ELEC. | | Y | WE128K32-200G2Q | 669 |
| 5962-9458503HMC | J | 10/06/2003 | 1 | AEROFLEX | | Y | ACT-E128K32N-200F2 | 669 |
| 5962-9458503HMC | J | 10/06/2003 | 1 | AUSTIN SEMI. | | Y | AS8E128K32Q-200/883 | 669 |
| 5962-9458503HMC | J | 10/06/2003 | 1 | WHITE ELEC. | | Y | WE128K32-200G2Q | 669 |
| 5962-9458503HNC | J | 10/06/2003 | 1 | WHITE ELEC. | | Y | WE128K32-200G4Q | 669 |
| 5962-9458503HTA | J | 10/06/2003 | 1 | WHITE ELEC. | | Y | WE128K32N-200HQ | 669 |
| 5962-9458503HTC | J | 10/06/2003 | 1 | WHITE ELEC. | | Y | WE128K32N-200HQ | 669 |
| 5962-9458503HUA | J | 10/06/2003 | 1 | WHITE ELEC. | | Y | WE-128K32N-200HQ | 669 |
| 5962-9458503HUC | J | 10/06/2003 | 1 | WHITE ELEC. | | Y | WE128K32N-200HQ | 669 |
| 5962-9458503HXA | J | 10/06/2003 | 1 | WHITE ELEC. | | Y | WE128K32-200HQ | 669 |
| 5962-9458503HXC | J | 10/06/2003 | 1 | WHITE ELEC. | | Y | WE128K32-200HQ | 669 |
| 5962-9458503HYA | J | 10/06/2003 | 1 | WHITE ELEC. | | Y | WE128K32-200HQ | 669 |
| 5962-9458503HYC | J | 10/06/2003 | 1 | WHITE ELEC. | | Y | WE128K32-200HQ | 669 |
| 5962-9458504H4A | J | 10/06/2003 | 1 | AEROFLEX | | Y | ACT-E128K32N-150P7 | 669 |
| 5962-9458504H4A | J | 10/06/2003 | 1 | AUSTIN SEMI. | | Y | AS8E128K32PN-150/88 | 669 |
| 5962-9458504H4A | J | 10/06/2003 | 1 | WHITE ELEC. | | Y | WE128K32N-150H1Q | 669 |
| 5962-9458504H4C | J | 10/06/2003 | 1 | AEROFLEX | | Y | ACT-E128K32N-150P7 | 669 |
| 5962-9458504H4C | J | 10/06/2003 | 1 | AUSTIN SEMI. | | Y | AS8E128K32PN-150/88 | 669 |
| 5962-9458504H4C | J | 10/06/2003 | 1 | WHITE ELEC. | | Y | WE128K32N-150H1Q | 669 |
| 5962-9458504H5A | J | 10/06/2003 | 1 | AEROFLEX | | Y | ACT-E128K32C-150P7 | 669 |
| 5962-9458504H5A | J | 10/06/2003 | 1 | AUSTIN SEMI. | | Y | AS8E128K32P-150/883 | 669 |
| 5962-9458504H5A | J | 10/06/2003 | 1 | WHITE ELEC. | | Y | WE128K32-150H1Q | 669 |
| 5962-9458504H5C | J | 10/06/2003 | 1 | AEROFLEX | | Y | ACT-E128K32C-150P7 | 669 |
| 5962-9458504H5C | J | 10/06/2003 | 1 | AUSTIN SEMI. | | Y | AS8E128K32P-150/883 | 669 |
| 5962-9458504H5C | J | 10/06/2003 | 1 | WHITE ELEC. | | Y | WE128K32-150H1Q | 669 |
| 5962-9458504H6A | J | 10/06/2003 | 1 | WHITE ELEC. | | Y | WE128K32NP-150H1Q | 669 |
| 5962-9458504H6C | J | 10/06/2003 | 1 | WHITE ELEC. | | Y | WE128K32NP-150H1Q | 669 |
| 5962-9458504H9A | J | 10/06/2003 | 1 | WHITE ELEC. | | Y | WE128K32-150G1UQ | 669 |
| 5962-9458504H9C | J | 10/06/2003 | 1 | WHITE ELEC. | | Y | WE128K32-150G1UQ | 669 |
| 5962-9458504HBA | J | 10/06/2003 | 1 | WHITE ELEC. | | Y | WE128K32-150G1TQ | 669 |
| 5962-9458504HBC | J | 10/06/2003 | 1 | WHITE ELEC. | | Y | WE128K32-150G1TQ | 669 |
| 5962-9458504HMA | J | 10/06/2003 | 1 | AEROFLEX | | Y | ACT-E128K32N-150F2 | 669 |
| 5962-9458504HMA | J | 10/06/2003 | 1 | AUSTIN SEMI. | | Y | AS8E128K32Q-150/883 | 669 |
| 5962-9458504HMA | J | 10/06/2003 | 1 | WHITE ELEC. | | Y | WE128K32-150G2Q | 669 |
| 5962-9458504HMC | J | 10/06/2003 | 1 | AEROFLEX | | Y | ACT-E128K32N-150F2 | 669 |
| 5962-9458504HMC | J | 10/06/2003 | 1 | AUSTIN SEMI. | | Y | AS8E128K32Q-150/883 | 669 |
| 5962-9458504HMC | J | 10/06/2003 | 1 | WHITE ELEC. | | Y | WE128K32-150G2Q | 669 |
| 5962-9458504HNC | J | 10/06/2003 | 1 | WHITE ELEC. | | Y | WE128K32-150G4Q | 669 |
| 5962-9458504HTA | J | 10/06/2003 | 1 | WHITE ELEC. | | Y | WE128K32N-150HQ | 669 |
| 5962-9458504HTC | J | 10/06/2003 | 1 | WHITE ELEC. | | Y | WE128K32N-150HQ | 669 |
| 5962-9458504HUA | J | 10/06/2003 | 1 | WHITE ELEC. | | Y | WE128K32N-150HQ | 669 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9458504HUC | J | 10/06/2003 | 1 | WHITE ELEC. | | Y | WE128K32N-150HQ | 669 |
| 5962-9458504HXA | J | 10/06/2003 | 1 | WHITE ELEC. | | Y | WE128K32-150HQ | 669 |
| 5962-9458504HXC | J | 10/06/2003 | 1 | WHITE ELEC. | | Y | WE128K32-150HQ | 669 |
| 5962-9458504HYA | J | 10/06/2003 | 1 | WHITE ELEC. | | Y | WE128K32-150HQ | 669 |
| 5962-9458504HYC | J | 10/06/2003 | 1 | WHITE ELEC. | | Y | WE128K32-150HQ | 669 |
| 5962-9458505H4A | J | 10/06/2003 | 1 | AEROFLEX | | Y | ACT-E128K32N-140P7 | 669 |
| 5962-9458505H4A | J | 10/06/2003 | 1 | AUSTIN SEMI. | | Y | AS8E128K32PN-140/88 | 669 |
| 5962-9458505H4A | J | 10/06/2003 | 1 | WHITE ELEC. | | Y | WE128K32N-140H1Q | 669 |
| 5962-9458505H4C | J | 10/06/2003 | 1 | AEROFLEX | | Y | ACT-E128K32N-140P7 | 669 |
| 5962-9458505H4C | J | 10/06/2003 | 1 | AUSTIN SEMI. | | Y | AS8E128K32PN-140/88 | 669 |
| 5962-9458505H4C | J | 10/06/2003 | 1 | WHITE ELEC. | | Y | WE128K32N-140H1Q | 669 |
| 5962-9458505H5A | J | 10/06/2003 | 1 | AEROFLEX | | Y | ACT-E128K32C-140P7 | 669 |
| 5962-9458505H5A | J | 10/06/2003 | 1 | AUSTIN SEMI. | | Y | AS8E128K32P-140/883 | 669 |
| 5962-9458505H5A | J | 10/06/2003 | 1 | WHITE ELEC. | | Y | WE128K32-140H1Q | 669 |
| 5962-9458505H5C | J | 10/06/2003 | 1 | AEROFLEX | | Y | ACT-E128K32C-140P7 | 669 |
| 5962-9458505H5C | J | 10/06/2003 | 1 | AUSTIN SEMI. | | Y | AS8E128K32P-140/883 | 669 |
| 5962-9458505H5C | J | 10/06/2003 | 1 | WHITE ELEC. | | Y | WE128K32-140H1Q | 669 |
| 5962-9458505H6A | J | 10/06/2003 | 1 | WHITE ELEC. | | Y | WE128K32NP-140H1Q | 669 |
| 5962-9458505H6C | J | 10/06/2003 | 1 | WHITE ELEC. | | Y | WE128K32NP-140H1Q | 669 |
| 5962-9458505H9A | J | 10/06/2003 | 1 | WHITE ELEC. | | Y | WE128K32-140G1UQ | 669 |
| 5962-9458505H9C | J | 10/06/2003 | 1 | WHITE ELEC. | | Y | WE128K32-140G1UQ | 669 |
| 5962-9458505HBA | J | 10/06/2003 | 1 | WHITE ELEC. | | Y | WE128K32-140G1TQ | 669 |
| 5962-9458505HBC | J | 10/06/2003 | 1 | WHITE ELEC. | | Y | WE128K32-140G1TQ | 669 |
| 5962-9458505HMA | J | 10/06/2003 | 1 | AEROFLEX | | Y | ACT-E128K32N-140F2 | 669 |
| 5962-9458505HMA | J | 10/06/2003 | 1 | AUSTIN SEMI. | | Y | AS8E128K32Q-140/883 | 669 |
| 5962-9458505HMA | J | 10/06/2003 | 1 | WHITE ELEC. | | Y | WE128K32-140G2Q | 669 |
| 5962-9458505HMC | J | 10/06/2003 | 1 | AEROFLEX | | Y | ACT-E128K32N-140F2 | 669 |
| 5962-9458505HMC | J | 10/06/2003 | 1 | AUSTIN SEMI. | | Y | AS8E128K32Q-140/883 | 669 |
| 5962-9458505HMC | J | 10/06/2003 | 1 | WHITE ELEC. | | Y | WE128K32-140G2Q | 669 |
| 5962-9458505HNC | J | 10/06/2003 | 1 | WHITE ELEC. | | Y | WE128K32-140G4Q | 669 |
| 5962-9458505HTA | J | 10/06/2003 | 1 | WHITE ELEC. | | Y | WE128K32N-140HQ | 669 |
| 5962-9458505HTC | J | 10/06/2003 | 1 | WHITE ELEC. | | Y | WE128K32N-140HQ | 669 |
| 5962-9458505HUA | J | 10/06/2003 | 1 | WHITE ELEC. | | Y | WE128K32N-140HQ | 669 |
| 5962-9458505HUC | J | 10/06/2003 | 1 | WHITE ELEC. | | Y | WE128K32N-140HQ | 669 |
| 5962-9458505HXA | J | 10/06/2003 | 1 | WHITE ELEC. | | Y | WE128K32-140HQ | 669 |
| 5962-9458505HXC | J | 10/06/2003 | 1 | WHITE ELEC. | | Y | WE128K32-140HQ | 669 |
| 5962-9458505HYA | J | 10/06/2003 | 1 | WHITE ELEC. | | Y | WE128K32-140HQ | 669 |
| 5962-9458505HYC | J | 10/06/2003 | 1 | WHITE ELEC. | | Y | WE128K32-140HQ | 669 |
| 5962-9458506H4A | J | 10/06/2003 | 1 | AEROFLEX | | Y | ACT-E128K32N-120P7 | 669 |
| 5962-9458506H4A | J | 10/06/2003 | 1 | AUSTIN SEMI. | | Y | AS8E128K32PN-120/88 | 669 |
| 5962-9458506H4A | J | 10/06/2003 | 1 | WHITE ELEC. | | Y | WE128K32N-120H1Q | 669 |
| 5962-9458506H4C | J | 10/06/2003 | 1 | AEROFLEX | | Y | ACT-E128K32N-120P7 | 669 |
| 5962-9458506H4C | J | 10/06/2003 | 1 | AUSTIN SEMI. | | Y | AS8E128K32PN-120/88 | 669 |
| 5962-9458506H4C | J | 10/06/2003 | 1 | WHITE ELEC. | | Y | WE128K32N-120H1Q | 669 |
| 5962-9458506H5A | J | 10/06/2003 | 1 | AEROFLEX | | Y | ACT-E128K32C-120P7 | 669 |
| 5962-9458506H5A | J | 10/06/2003 | 1 | AUSTIN SEMI. | | Y | AS8E128K32P-120/883 | 669 |
| 5962-9458506H5A | J | 10/06/2003 | 1 | WHITE ELEC. | | Y | WE128K32-120H1Q | 669 |
| 5962-9458506H5C | J | 10/06/2003 | 1 | AEROFLEX | | Y | ACT-E128K32C-120P7 | 669 |
| 5962-9458506H5C | J | 10/06/2003 | 1 | AUSTIN SEMI. | | Y | AS8E128K32P-120/883 | 669 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9458506H5C | J | 10/06/2003 | 1 | WHITE ELEC. | | Y | WE128K32-120H1Q | 669 |
| 5962-9458506H6A | J | 10/06/2003 | 1 | WHITE ELEC. | | Y | WE128K32NP-120H1Q | 669 |
| 5962-9458506H6C | J | 10/06/2003 | 1 | WHITE ELEC. | | Y | WE128K32NP-120H1Q | 669 |
| 5962-9458506H9A | J | 10/06/2003 | 1 | WHITE ELEC. | | Y | WE128K32-120G1UQ | 669 |
| 5962-9458506H9C | J | 10/06/2003 | 1 | WHITE ELEC. | | Y | WE128K32-120G1UQ | 669 |
| 5962-9458506HBA | J | 10/06/2003 | 1 | WHITE ELEC. | | Y | WE128K32-120G1TQ | 669 |
| 5962-9458506HBC | J | 10/06/2003 | 1 | WHITE ELEC. | | Y | WE128K32-120G1TQ | 669 |
| 5962-9458506HMA | J | 10/06/2003 | 1 | AEROFLEX | | Y | ACT-E128K32N-120F2 | 669 |
| 5962-9458506HMA | J | 10/06/2003 | 1 | AUSTIN SEMI. | | Y | AS8E128K32Q-120/883 | 669 |
| 5962-9458506HMA | J | 10/06/2003 | 1 | WHITE ELEC. | | Y | WE128K32-120G2Q | 669 |
| 5962-9458506HMC | J | 10/06/2003 | 1 | AEROFLEX | | Y | ACT-E128K32N-120F2 | 669 |
| 5962-9458506HMC | J | 10/06/2003 | 1 | AUSTIN SEMI. | | Y | AS8E128K32Q-120/883 | 669 |
| 5962-9458506HMC | J | 10/06/2003 | 1 | WHITE ELEC. | | Y | WE128K32-120G2Q | 669 |
| 5962-9458506HNC | J | 10/06/2003 | 1 | WHITE ELEC. | | Y | WE128K32-120G4Q | 669 |
| 5962-9458506HTA | J | 10/06/2003 | 1 | WHITE ELEC. | | Y | WE128K32N-120HQ | 669 |
| 5962-9458506HTC | J | 10/06/2003 | 1 | WHITE ELEC. | | Y | WE128K32N-120HQ | 669 |
| 5962-9458506HUA | J | 10/06/2003 | 1 | WHITE ELEC. | | Y | WE128K32N-120HQ | 669 |
| 5962-9458506HUC | J | 10/06/2003 | 1 | WHITE ELEC. | | Y | WE128K32N-120HQ | 669 |
| 5962-9458506HXA | J | 10/06/2003 | 1 | WHITE ELEC. | | Y | WE128K32-120HQ | 669 |
| 5962-9458506HXC | J | 10/06/2003 | 1 | WHITE ELEC. | | Y | WE128K32-120HQ | 669 |
| 5962-9458506HYA | J | 10/06/2003 | 1 | WHITE ELEC. | | Y | WE128K32-120HQ | 669 |
| 5962-9458506HYC | J | 10/06/2003 | 1 | WHITE ELEC. | | Y | WE128K32-120HQ | 669 |
| 5962-9458507HMA | J | 10/06/2003 | 1 | AUSTIN SEMI. | | Y | AS8ER128K32Q-250/88 | 669 |
| 5962-9458507HMC | J | 10/06/2003 | 1 | AUSTIN SEMI. | | Y | AS8ER128K32Q-250/88 | 669 |
| 5962-9458507HZC | J | 10/06/2003 | 1 | AUSTIN SEMI. | | Y | AS8ER128K32QB-250/ | 669 |
| 5962-9458508HMA | J | 10/06/2003 | 1 | AUSTIN SEMI. | | Y | AS8ER128K32Q-200/88 | 669 |
| 5962-9458508HMC | J | 10/06/2003 | 1 | AUSTIN SEMI. | | Y | AS8ER128K32Q-200/88 | 669 |
| 5962-9458508HZC | J | 10/06/2003 | 1 | AUSTIN SEMI. | | Y | AS8ER128K32QB-200/ | 669 |
| 5962-9458509HMA | J | 10/06/2003 | 1 | AUSTIN SEMI. | | Y | AS8ER128K32Q-150/88 | 669 |
| 5962-9458509HMC | J | 10/06/2003 | 1 | AUSTIN SEMI. | | Y | AS8ER128K32Q-150/88 | 669 |
| 5962-9458509HZC | J | 10/06/2003 | 1 | AUSTIN SEMI. | | Y | AS8ER128K32QB-150/ | 669 |
| 5962-9458601Q3A | | 04/22/1994 | 3 | TI | | Y | SNJ54ABT8646FK | 399 |
| 5962-9458601QXA | | 04/22/1994 | 3 | TI | | Y | SNJ54ABT8646JT | 399 |
| 5962-9458701QXA | B | 07/15/1999 | 3 | TI | | Y | SNJ54ABT162244WD | 529 |
| 5962-9458801MXA | | 02/23/1995 | | (NONE) | | | 7C474-40 (GEN) | 670 |
| 5962-9458801MYA | | 02/23/1995 | | (NONE) | | | 7C474-40 (GEN) | 670 |
| 5962-9458802MXA | | 02/23/1995 | | (NONE) | | | 7C474-25 (GEN) | 670 |
| 5962-9458802MYA | | 02/23/1995 | | (NONE) | | | 7C474-25 (GEN) | 670 |
| 5962-9458803MXA | | 02/23/1995 | | (NONE) | | | 7C474-20 (GEN) | 670 |
| 5962-9458803MYA | | 02/23/1995 | | (NONE) | | | 7C474-20 (GEN) | 670 |
| 5962-9459001MXA | | 04/22/1994 | 3 | NATIONAL | | Y | 100307DMQB | 149 |
| 5962-9459001VXA | | 04/22/1994 | 3 | NATIONAL | | Y | 100307J-QMLV | 149 |
| 5962-9459001MYA | | 04/22/1994 | 3 | NATIONAL | | Y | 100307FMQB | 149 |
| 5962-9459001VYA | | 04/22/1994 | 3 | NATIONAL | | Y | 100307W-QMLV | 149 |
| 5962-9459101MXA | A | 03/15/2004 | 3 | NATIONAL | | Y | 100341DMQB | 228 |
| 5962-9459101VXA | A | 03/15/2004 | 3 | NATIONAL | | Y | 100341J-QMLV | 228 |
| 5962-9459101MYA | A | 03/15/2004 | 3 | NATIONAL | | Y | 100341FMQB | 228 |
| 5962-9459101VYA | A | 03/15/2004 | 3 | NATIONAL | | Y | 100341W-QMLV | 228 |
| 5962F9459101VYA | A | 03/15/2004 | 3 | NATIONAL | | Y | 100341WFQMLV | 228 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9459201MXA | | 04/28/1994 | 3 | NATIONAL | | Y | 100364DMQB | 270 |
| 5962-9459201VXA | | 04/28/1994 | 3 | NATIONAL | | Y | 100364J-QMLV | 270 |
| 5962-9459201MYA | | 04/28/1994 | 3 | NATIONAL | | Y | 100364FMQB | 270 |
| 5962-9459201VYA | | 04/28/1994 | 3 | NATIONAL | | Y | 100364W-QMLV | 270 |
| 5962-9459301VHA | C | 07/31/2002 | 1 | ANALOG (5) | | Y | AD8001SL/QMLV | 701 |
| 5962R9459301VHA | C | 07/31/2002 | 1 | ANALOG (5) | | Y | AD8001SL/QMLR | 701 |
| 5962-9459301MPA | C | 07/31/2002 | 1 | ANALOG (2) | | Y | AD8001SQ | 701 |
| 5962-9459301VPA | C | 07/31/2002 | 1 | ANALOG (5) | | Y | AD8001SQ/QMLV | 701 |
| 5962R9459301VPA | C | 07/31/2002 | 1 | ANALOG (5) | | Y | AD8001SQ/QMLR | 701 |
| 5962-9459401MCA | A | 03/05/2002 | | (NONE) | 03/31/1998 | | MIC4467 (GEN) | 500 |
| 5962-9459402MCA | A | 03/05/2002 | | (NONE) | 03/31/1998 | | MIC4468 (GEN) | 502 |
| 5962-9459403MCA | A | 03/05/2002 | 2 | MICREL | | | MIC4469AJB | 502 |
| 5962-9459701MPA | A | 12/15/2000 | 1 | NATIONAL | | Y | CLC426AJ-QML | 719 |
| 5962-9459801HXA | | 08/06/1998 | 1 | MS KENNEDY | | Y | MSK1348B | 809 |
| 5962-9459801HXC | | 08/06/1998 | 1 | MS KENNEDY | | Y | MSK1348B | 809 |
| 5962-9459901MXA | A | 05/16/2001 | 2 | SIMTEK | | | STK12C68-5C55M | 620 |
| 5962-9459901MXC | A | 05/16/2001 | 2 | SIMTEK | | | STK12C68-5C55M | 620 |
| 5962-9459901MYA | A | 05/16/2001 | 2 | SIMTEK | | | STK12C68-5L55M | 620 |
| 5962-9459902MXA | A | 05/16/2001 | 2 | SIMTEK | | | STK12C68-5C45M | 620 |
| 5962-9459902MXC | A | 05/16/2001 | 2 | SIMTEK | | | STK12C68-5C45M | 620 |
| 5962-9459902MYA | A | 05/16/2001 | 2 | SIMTEK | | | STK12C68-5L45M | 620 |
| 5962-9459903MXA | A | 05/16/2001 | 2 | SIMTEK | | | STK12C68-5C35M | 620 |
| 5962-9459903MXC | A | 05/16/2001 | 2 | SIMTEK | | | STK12C68-5C35M | 620 |
| 5962-9459903MYA | A | 05/16/2001 | 2 | SIMTEK | | | STK12C68-5L35M | 620 |
| 5962-9460001MGA | C | 11/26/2001 | | (NONE) | | | LTC1051 (GEN) | 710 |
| 5962-9460001MPA | C | 11/26/2001 | | (NONE) | 12/31/2001 | | LTC1051 (GEN) | 710 |
| 5962-9460001MXA | C | 11/26/2001 | | (NONE) | 12/31/2001 | | LTC1051 (GEN) | 710 |
| 5962-9460002MGA | C | 11/26/2001 | | (NONE) | | | LTC1051A (GEN) | 710 |
| 5962-9460002MPA | C | 11/26/2001 | | (NONE) | 12/31/2001 | | LTC1051A (GEN) | 710 |
| 5962-9460002MXA | C | 11/26/2001 | | (NONE) | 12/31/2001 | | LTC1051A (GEN) | 710 |
| 5962-9460101QXA | B | 06/14/1996 | | (NONE) | 05/27/1998 | | 54ABT18245 (GEN) | 399 |
| 5962-9460102QXA | B | 06/14/1996 | 2 | TI | | Y | SNJ54ABT18245AWD | 399 |
| 5962-9460201Q2A | B | 01/08/2004 | 1 | TI | | Y | TLE2071MFKB | 703 |
| 5962-9460201QHA | B | 01/08/2004 | 1 | TI | | Y | TLE2071MUB | 703 |
| 5962-9460201QPA | B | 01/08/2004 | 1 | TI | | Y | TLE2071MJGB | 703 |
| 5962-9460202Q2A | B | 01/08/2004 | 1 | TI | | Y | TLE2072MFKB | 710 |
| 5962-9460202QHA | B | 01/08/2004 | 1 | TI | | Y | TLE2072MUB | 710 |
| 5962-9460202QPA | B | 01/08/2004 | 1 | TI | | Y | TLE2072MJGB | 710 |
| 5962-9460203Q2A | B | 01/08/2004 | 1 | TI | | Y | TLE2074MFKB | 713 |
| 5962-9460203QCA | B | 01/08/2004 | 1 | TI | | Y | TLE2074MJB | 713 |
| 5962-9460203QDA | B | 01/08/2004 | 1 | TI | | Y | TLE2074MWB | 713 |
| 5962-9460204Q2A | B | 01/08/2004 | 1 | TI | | Y | TLE2071AMFKB | 703 |
| 5962-9460204QDA | B | 01/08/2004 | 1 | TI | | Y | TLE2071AMWB | 703 |
| 5962-9460204QHA | B | 01/08/2004 | 1 | TI | | Y | TLE2071AMUB | 703 |
| 5962-9460204QPA | B | 01/08/2004 | 1 | TI | | Y | TLE2071AMJGB | 703 |
| 5962-9460205Q2A | B | 01/08/2004 | 1 | TI | | Y | TLE2072AMFKB | 710 |
| 5962-9460205QHA | B | 01/08/2004 | 1 | TI | | Y | TLE2072AMUB | 710 |
| 5962-9460205QPA | B | 01/08/2004 | 1 | TI | | Y | TLE2072AMJGB | 710 |
| 5962-9460206Q2A | B | 01/08/2004 | 1 | TI | | Y | TLE2074AMFKB | 713 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9460206QCA | B | 01/08/2004 | 1 | TI | | Y | TLE2074AMJB | 713 |
| 5962-9460206QDA | B | 01/08/2004 | 1 | TI | | Y | TLE2074AMWB | 713 |
| 5962-9460301MCA | | 05/16/1994 | | (NONE) | 09/09/1998 | | LM6182A (GEN) | 899 |
| 5962-9460401MPA | A | 02/21/2002 | 2 | NATIONAL | | Y | LMC6061AMJ/883 | 710 |
| 5962-9460801MXA | | 07/28/1994 | | (NONE) | 04/01/2000 | | 12-65 (GEN) | 208 |
| 5962-9460802MXA | | 07/28/1994 | | (NONE) | 04/01/2000 | | 12-50 (GEN) | 208 |
| 5962-9461001H4A | B | 07/08/1998 | 1 | WHITE ELEC. | | Y | WF128K32N-200H1Q | 669 |
| 5962-9461001H4C | B | 07/08/1998 | 1 | WHITE ELEC. | | Y | WF128K32N-200H1Q | 669 |
| 5962-9461001H5A | B | 07/08/1998 | 1 | WHITE ELEC. | | Y | WF128K32NA-200H1Q | 669 |
| 5962-9461001H5C | B | 07/08/1998 | 1 | WHITE ELEC. | | Y | WF128K32NA-200H1Q | 669 |
| 5962-9461001HMA | B | 07/08/1998 | 1 | WHITE ELEC. | | Y | WF128K32-200G2Q | 669 |
| 5962-9461001HMC | B | 07/08/1998 | 1 | WHITE ELEC. | | Y | WF128K32-200G2Q | 669 |
| 5962-9461001HNC | B | 07/08/1998 | 1 | WHITE ELEC. | | Y | WF128K32-200G4Q | 669 |
| 5962-9461001HWA | B | 07/08/1998 | 1 | WHITE ELEC. | | Y | WF128K32-200HSQ | 669 |
| 5962-9461001HWC | B | 07/08/1998 | 1 | WHITE ELEC. | | Y | WF128K32-200HSQ | 669 |
| 5962-9461001HXA | B | 07/08/1998 | 1 | WHITE ELEC. | | Y | WF128K32-200HQ | 669 |
| 5962-9461001HXC | B | 07/08/1998 | 1 | WHITE ELEC. | | Y | WF128K32-200HQ | 669 |
| 5962-9461001HYA | B | 07/08/1998 | 1 | WHITE ELEC. | | Y | WF128K32N-200HSQ | 669 |
| 5962-9461001HYC | B | 07/08/1998 | 1 | WHITE ELEC. | | Y | WF128K32N-200HSQ | 669 |
| 5962-9461001HZA | B | 07/08/1998 | 1 | WHITE ELEC. | | Y | WF128K32N-200HQ | 669 |
| 5962-9461001HZC | B | 07/08/1998 | 1 | WHITE ELEC. | | Y | WF128K32N-200HQ | 669 |
| 5962-9461002H4A | B | 07/08/1998 | 1 | WHITE ELEC. | | Y | WF128K32N-150H1Q | 669 |
| 5962-9461002H4C | B | 07/08/1998 | 1 | WHITE ELEC. | | Y | WF128K32N-150H1Q | 669 |
| 5962-9461002H5A | B | 07/08/1998 | 1 | WHITE ELEC. | | Y | WF128K32NA-150H1Q | 669 |
| 5962-9461002H5C | B | 07/08/1998 | 1 | WHITE ELEC. | | Y | WF128K32NA-150H1Q | 669 |
| 5962-9461002HMA | B | 07/08/1998 | 1 | WHITE ELEC. | | Y | WF128K32-150G2Q | 669 |
| 5962-9461002HMC | B | 07/08/1998 | 1 | WHITE ELEC. | | Y | WF128K32-150G2Q | 669 |
| 5962-9461002HNC | B | 07/08/1998 | 1 | WHITE ELEC. | | Y | WF128K32-150G4Q | 669 |
| 5962-9461002HWA | B | 07/08/1998 | 1 | WHITE ELEC. | | Y | WF128K32-150HSQ | 669 |
| 5962-9461002HWC | B | 07/08/1998 | 1 | WHITE ELEC. | | Y | WF128K32-150HSQ | 669 |
| 5962-9461002HXA | B | 07/08/1998 | 1 | WHITE ELEC. | | Y | WF128K32-150HQ | 669 |
| 5962-9461002HXC | B | 07/08/1998 | 1 | WHITE ELEC. | | Y | WF128K32-150HQ | 669 |
| 5962-9461002HYA | B | 07/08/1998 | 1 | WHITE ELEC. | | Y | WF128K32N-150HSQ | 669 |
| 5962-9461002HYC | B | 07/08/1998 | 1 | WHITE ELEC. | | Y | WF128K32N-150HSQ | 669 |
| 5962-9461002HZA | B | 07/08/1998 | 1 | WHITE ELEC. | | Y | WF128K32N-150HQ | 669 |
| 5962-9461002HZC | B | 07/08/1998 | 1 | WHITE ELEC. | | Y | WF128K32N-150HQ | 669 |
| 5962-9461003H4A | B | 07/08/1998 | 1 | WHITE ELEC. | | Y | WF128K32N-120H1Q | 669 |
| 5962-9461003H4C | B | 07/08/1998 | 1 | WHITE ELEC. | | Y | WF128K32N-120H1Q | 669 |
| 5962-9461003H5A | B | 07/08/1998 | 1 | WHITE ELEC. | | Y | WF128K32NA-120H1Q | 669 |
| 5962-9461003H5C | B | 07/08/1998 | 1 | WHITE ELEC. | | Y | WF128K32NA-120H1Q | 669 |
| 5962-9461003HMA | B | 07/08/1998 | 1 | WHITE ELEC. | | Y | WF128K32-120G2Q | 669 |
| 5962-9461003HMC | B | 07/08/1998 | 1 | WHITE ELEC. | | Y | WF128K32-120G2Q | 669 |
| 5962-9461003HNC | B | 07/08/1998 | 1 | WHITE ELEC. | | Y | WF128K32-120G4Q | 669 |
| 5962-9461003HWA | B | 07/08/1998 | 1 | WHITE ELEC. | | Y | WF128K32-120HSQ | 669 |
| 5962-9461003HWC | B | 07/08/1998 | 1 | WHITE ELEC. | | Y | WF128K32-120HSQ | 669 |
| 5962-9461003HXA | B | 07/08/1998 | 1 | WHITE ELEC. | | Y | WF128K32-120HQ | 669 |
| 5962-9461003HXC | B | 07/08/1998 | 1 | WHITE ELEC. | | Y | WF128K32-120HQ | 669 |
| 5962-9461003HYA | B | 07/08/1998 | 1 | WHITE ELEC. | | Y | WF128K32N-120HSQ | 669 |
| 5962-9461003HYC | B | 07/08/1998 | 1 | WHITE ELEC. | | Y | WF128K32N-120HSQ | 669 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9461003HZA | B | 07/08/1998 | 1 | WHITE ELEC. | | Y | WF128K32N-120HQ | 669 |
| 5962-9461003HZC | B | 07/08/1998 | 1 | WHITE ELEC. | | Y | WF128K32N-120HQ | 669 |
| 5962-9461101HMA | R | 05/03/2004 | 1 | WHITE ELEC. | | Y | WS512K32-120G2Q | 629 |
| 5962-9461101HMC | R | 05/03/2004 | 1 | WHITE ELEC. | | Y | WS512K32-120G2Q | 629 |
| 5962-9461101HUA | R | 05/03/2004 | 1 | WHITE ELEC. | | Y | WS512K32N-120HQ | 629 |
| 5962-9461101HUC | R | 05/03/2004 | 1 | WHITE ELEC. | | Y | WS512K32N-120HQ | 629 |
| 5962-9461101HXA | R | 05/03/2004 | | (NONE) | | | 512K32-120 (GEN) | 629 |
| 5962-9461101HYC | R | 05/03/2004 | 1 | WHITE ELEC. | | Y | WS512K32-120G4Q | 629 |
| 5962-9461102HMA | R | 05/03/2004 | 1 | WHITE ELEC. | | Y | WS512K32-100G2Q | 629 |
| 5962-9461102HMC | R | 05/03/2004 | 1 | WHITE ELEC. | | Y | WS512K32-100G2Q | 629 |
| 5962-9461102HUA | R | 05/03/2004 | 1 | WHITE ELEC. | | Y | WS512K32N-100HQ | 629 |
| 5962-9461102HUC | R | 05/03/2004 | 1 | WHITE ELEC. | | Y | WS512K32N-100HQ | 629 |
| 5962-9461102HXA | R | 05/03/2004 | | (NONE) | | | 512K32-100 (GEN) | 629 |
| 5962-9461102HYC | R | 05/03/2004 | 1 | WHITE ELEC. | | Y | WS512K32-100G4Q | 629 |
| 5962-9461103HMA | R | 05/03/2004 | 1 | WHITE ELEC. | | Y | WS512K32-85G2Q | 629 |
| 5962-9461103HMC | R | 05/03/2004 | 1 | WHITE ELEC. | | Y | WS512K32-85G2Q | 629 |
| 5962-9461103HUA | R | 05/03/2004 | 1 | WHITE ELEC. | | Y | WS512K32N-85HQ | 629 |
| 5962-9461103HUC | R | 05/03/2004 | 1 | WHITE ELEC. | | Y | WS512K32N-85HQ | 629 |
| 5962-9461103HXA | R | 05/03/2004 | | (NONE) | | | 512K32-85 (GEN) | 629 |
| 5962-9461103HYC | R | 05/03/2004 | 1 | WHITE ELEC. | | Y | WS512K32-85G4Q | 629 |
| 5962-9461104HMA | R | 05/03/2004 | 1 | WHITE ELEC. | | Y | WS512K32-70G2Q | 629 |
| 5962-9461104HMC | R | 05/03/2004 | 1 | WHITE ELEC. | | Y | WS512K32-70G2Q | 629 |
| 5962-9461104HUA | R | 05/03/2004 | 1 | WHITE ELEC. | | Y | WS512K32N-70HQ | 629 |
| 5962-9461104HUC | R | 05/03/2004 | 1 | WHITE ELEC. | | Y | WS512K32N-70HQ | 629 |
| 5962-9461104HXA | R | 05/03/2004 | | (NONE) | | | 512K32-70 (GEN) | 629 |
| 5962-9461104HYC | R | 05/03/2004 | 1 | WHITE ELEC. | | Y | WS512K32-70G4Q | 629 |
| 5962-9461105H9A | R | 05/03/2004 | 1 | WHITE ELEC. | | Y | WS512K32-55G1UQ | 629 |
| 5962-9461105H9C | R | 05/03/2004 | 1 | WHITE ELEC. | | Y | WS512K32-55G1UQ | 629 |
| 5962-9461105HAA | R | 05/03/2004 | 1 | AUSTIN SEMI. | | Y | AS8S512K32Q1-55L/88 | 629 |
| 5962-9461105HAA | R | 05/03/2004 | 1 | WHITE ELEC. | | Y | WS512K32-55G2LQ | 629 |
| 5962-9461105HAC | R | 05/03/2004 | 1 | AUSTIN SEMI. | | Y | AS8S512K32Q1-55L/88 | 629 |
| 5962-9461105HAC | R | 05/03/2004 | 1 | WHITE ELEC. | | Y | WS512K32-55G2LQ | 629 |
| 5962-9461105HBA | R | 05/03/2004 | 1 | WHITE ELEC. | | Y | WS512K32-55G1TQ | 629 |
| 5962-9461105HBC | R | 05/03/2004 | 1 | WHITE ELEC. | | Y | WS512K32-55G1TQ | 629 |
| 5962-9461105HMA | R | 05/03/2004 | 1 | AEROFLEX | | Y | ACT-S512K32N-055F2 | 629 |
| 5962-9461105HMA | R | 05/03/2004 | 1 | AUSTIN SEMI. | | Y | AS8S512K32Q-55L/Q | 629 |
| 5962-9461105HMA | R | 05/03/2004 | 1 | WHITE ELEC. | | Y | WS512K32-55G2Q | 629 |
| 5962-9461105HMC | R | 05/03/2004 | 1 | AEROFLEX | | Y | ACT-S512K32N-055F2 | 629 |
| 5962-9461105HMC | R | 05/03/2004 | 1 | AUSTIN SEMI. | | Y | AS8S512K32Q-55L/Q | 629 |
| 5962-9461105HMC | R | 05/03/2004 | 1 | WHITE ELEC. | | Y | WS512K32-55G2Q | 629 |
| 5962-9461105HTA | R | 05/03/2004 | 1 | AEROFLEX | | Y | ACT-S512K32N-055P7 | 629 |
| 5962-9461105HTA | R | 05/03/2004 | 1 | AUSTIN SEMI. | | Y | AS8S512K32P-55L/Q | 629 |
| 5962-9461105HTA | R | 05/03/2004 | 1 | WHITE ELEC. | | Y | WS512K32N-55H1Q | 629 |
| 5962-9461105HTC | R | 05/03/2004 | 1 | AEROFLEX | | Y | ACT-S512K32N-055P7 | 629 |
| 5962-9461105HTC | R | 05/03/2004 | 1 | AUSTIN SEMI. | | Y | AS8S512K32P-55L/Q | 629 |
| 5962-9461105HTC | R | 05/03/2004 | 1 | WHITE ELEC. | | Y | WS512K32N-55H1Q | 629 |
| 5962-9461105HXA | R | 05/03/2004 | 1 | AEROFLEX | | Y | ACT-S512K32N-055P1 | 629 |
| 5962-9461105HXC | R | 05/03/2004 | 1 | AEROFLEX | | Y | ACT-S512K32N-055P1 | 629 |
| 5962-9461105HYA | R | 05/03/2004 | 1 | AEROFLEX | | Y | ACT-S512K32N-055F1 | 629 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9461105HYC | R | 05/03/2004 | 1 | AEROFLEX | | Y | ACT-S512K32N-055F1 | 629 |
| 5962-9461105HYC | R | 05/03/2004 | 1 | WHITE ELEC. | | Y | WS512K32-55G4TQ | 629 |
| 5962-9461106H9A | R | 05/03/2004 | 1 | WHITE ELEC. | | Y | WS512K32-45G1UQ | 629 |
| 5962-9461106H9C | R | 05/03/2004 | 1 | WHITE ELEC. | | Y | WS512K32-45G1UQ | 629 |
| 5962-9461106HAA | R | 05/03/2004 | 1 | AUSTIN SEMI. | | Y | AS8S512K32Q1-45L/88 | 629 |
| 5962-9461106HAA | R | 05/03/2004 | 1 | WHITE ELEC. | | Y | WS512K32-45G2LQ | 629 |
| 5962-9461106HAC | R | 05/03/2004 | 1 | AUSTIN SEMI. | | Y | AS8S512K32Q1-45L/88 | 629 |
| 5962-9461106HAC | R | 05/03/2004 | 1 | WHITE ELEC. | | Y | WS512K32-45G2LQ | 629 |
| 5962-9461106HBA | R | 05/03/2004 | 1 | WHITE ELEC. | | Y | WS512K32-45G1TQ | 629 |
| 5962-9461106HBC | R | 05/03/2004 | 1 | WHITE ELEC. | | Y | WS512K32-45G1TQ | 629 |
| 5962-9461106HMA | R | 05/03/2004 | 1 | AEROFLEX | | Y | ACT-S512K32N-045F2 | 629 |
| 5962-9461106HMA | R | 05/03/2004 | 1 | AUSTIN SEMI. | | Y | AS8S512K32Q-45L/Q | 629 |
| 5962-9461106HMA | R | 05/03/2004 | 1 | WHITE ELEC. | | Y | WS512K32-45G2Q | 629 |
| 5962-9461106HMC | R | 05/03/2004 | 1 | AEROFLEX | | Y | ACT-S512K32N-045F2 | 629 |
| 5962-9461106HMC | R | 05/03/2004 | 1 | AUSTIN SEMI. | | Y | AS8S512K32Q-45L/Q | 629 |
| 5962-9461106HMC | R | 05/03/2004 | 1 | WHITE ELEC. | | Y | WS512K32-45G2Q | 629 |
| 5962-9461106HTA | R | 05/03/2004 | 1 | AEROFLEX | | Y | ACT-S512K32N-045P7 | 629 |
| 5962-9461106HTA | R | 05/03/2004 | 1 | AUSTIN SEMI. | | Y | AS8S512K32P-45L/Q | 629 |
| 5962-9461106HTA | R | 05/03/2004 | 1 | WHITE ELEC. | | Y | WS512K32N-45H1Q | 629 |
| 5962-9461106HTC | R | 05/03/2004 | 1 | AEROFLEX | | Y | ACT-S512K32N-045P7 | 629 |
| 5962-9461106HTC | R | 05/03/2004 | 1 | AUSTIN SEMI. | | Y | AS8S512K32P-45L/Q | 629 |
| 5962-9461106HTC | R | 05/03/2004 | 1 | WHITE ELEC. | | Y | WS512K32N-45H1Q | 629 |
| 5962-9461106HXA | R | 05/03/2004 | 1 | AEROFLEX | | Y | ACT-S512K32N-045P1 | 629 |
| 5962-9461106HXC | R | 05/03/2004 | 1 | AEROFLEX | | Y | ACT-S512K32N-045P1 | 629 |
| 5962-9461106HYA | R | 05/03/2004 | 1 | AEROFLEX | | Y | ACT-S512K32N-045F1 | 629 |
| 5962-9461106HYC | R | 05/03/2004 | 1 | AEROFLEX | | Y | ACT-S512K32N-045F1 | 629 |
| 5962-9461106HYC | R | 05/03/2004 | 1 | WHITE ELEC. | | Y | WS512K32-45G4TQ | 629 |
| 5962-9461107H9A | R | 05/03/2004 | 1 | WHITE ELEC. | | Y | WS512K32-35G1UQ | 629 |
| 5962-9461107H9C | R | 05/03/2004 | 1 | WHITE ELEC. | | Y | WS512K32-35G1UQ | 629 |
| 5962-9461107HAA | R | 05/03/2004 | 1 | AUSTIN SEMI. | | Y | AS8S512K32Q1-35L/88 | 629 |
| 5962-9461107HAA | R | 05/03/2004 | 1 | WHITE ELEC. | | Y | WS512K32-35G2LQ | 629 |
| 5962-9461107HAC | R | 05/03/2004 | 1 | AUSTIN SEMI. | | Y | AS8S512K32Q1-35L/88 | 629 |
| 5962-9461107HAC | R | 05/03/2004 | 1 | WHITE ELEC. | | Y | WS512K32-35G2LQ | 629 |
| 5962-9461107HBA | R | 05/03/2004 | 1 | WHITE ELEC. | | Y | WS512K32-35G1TQ | 629 |
| 5962-9461107HBC | R | 05/03/2004 | 1 | WHITE ELEC. | | Y | WS512K32-35G1TQ | 629 |
| 5962-9461107HMA | R | 05/03/2004 | 1 | AEROFLEX | | Y | ACT-S512K32N-035F2 | 629 |
| 5962-9461107HMA | R | 05/03/2004 | 1 | AUSTIN SEMI. | | Y | AS8S512K32Q-35L/Q | 629 |
| 5962-9461107HMA | R | 05/03/2004 | 1 | WHITE ELEC. | | Y | WS512K32-35G2Q | 629 |
| 5962-9461107HMC | R | 05/03/2004 | 1 | AEROFLEX | | Y | ACT-S512K32N-035F2 | 629 |
| 5962-9461107HMC | R | 05/03/2004 | 1 | AUSTIN SEMI. | | Y | AS8S512K32Q-35L/Q | 629 |
| 5962-9461107HMC | R | 05/03/2004 | 1 | WHITE ELEC. | | Y | WS512K32-35G2Q | 629 |
| 5962-9461107HTA | R | 05/03/2004 | 1 | AEROFLEX | | Y | ACT-S512K32N-035P7 | 629 |
| 5962-9461107HTA | R | 05/03/2004 | 1 | AUSTIN SEMI. | | Y | AS8S512K32P-35L/Q | 629 |
| 5962-9461107HTA | R | 05/03/2004 | 1 | WHITE ELEC. | | Y | WS512K32N-35H1Q | 629 |
| 5962-9461107HTC | R | 05/03/2004 | 1 | AEROFLEX | | Y | ACT-S512K32N-035P7 | 629 |
| 5962-9461107HTC | R | 05/03/2004 | 1 | AUSTIN SEMI. | | Y | AS8S512K32P-35L/Q | 629 |
| 5962-9461107HTC | R | 05/03/2004 | 1 | WHITE ELEC. | | Y | WS512K32N-35H1Q | 629 |
| 5962-9461107HXA | R | 05/03/2004 | 1 | AEROFLEX | | Y | ACT-S512K32N-035P1 | 629 |
| 5962-9461107HXC | R | 05/03/2004 | 1 | AEROFLEX | | Y | ACT-S512K32N-035P1 | 629 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9461107HYA | R | 05/03/2004 | 1 | AEROFLEX | | Y | ACT-S512K32N-035F1 | 629 |
| 5962-9461107HYC | R | 05/03/2004 | 1 | AEROFLEX | | Y | ACT-S512K32N-035F1 | 629 |
| 5962-9461107HYC | R | 05/03/2004 | 1 | WHITE ELEC. | | Y | WS512K32-35G4TQ | 629 |
| 5962-9461108H9A | R | 05/03/2004 | 1 | WHITE ELEC. | | Y | WS512K32-25G1UQ | 629 |
| 5962-9461108H9C | R | 05/03/2004 | 1 | WHITE ELEC. | | Y | WS512K32-25G1UQ | 629 |
| 5962-9461108HAA | R | 05/03/2004 | 1 | AUSTIN SEMI. | | Y | AS8S512K32Q1-25L/88 | 629 |
| 5962-9461108HAA | R | 05/03/2004 | 1 | WHITE ELEC. | | Y | WS512K32-25G2LQ | 629 |
| 5962-9461108HAC | R | 05/03/2004 | 1 | AUSTIN SEMI. | | Y | AS8S512K32Q1-25L/88 | 629 |
| 5962-9461108HAC | R | 05/03/2004 | 1 | WHITE ELEC. | | Y | WS512K32-25G2LQ | 629 |
| 5962-9461108HBA | R | 05/03/2004 | 1 | WHITE ELEC. | | Y | WS512K32-25G1TQ | 629 |
| 5962-9461108HBC | R | 05/03/2004 | 1 | WHITE ELEC. | | Y | WS512K32-25G1TQ | 629 |
| 5962-9461108HMA | R | 05/03/2004 | 1 | AEROFLEX | | Y | ACT-S512K32N-025F2 | 629 |
| 5962-9461108HMA | R | 05/03/2004 | 1 | AUSTIN SEMI. | | Y | AS8S512K32Q-25L/Q | 629 |
| 5962-9461108HMA | R | 05/03/2004 | 1 | WHITE ELEC. | | Y | WS512K32-25G2Q | 629 |
| 5962-9461108HMC | R | 05/03/2004 | 1 | AEROFLEX | | Y | ACT-S512K32N-025F2 | 629 |
| 5962-9461108HMC | R | 05/03/2004 | 1 | AUSTIN SEMI. | | Y | AS8S512K32Q-25L/Q | 629 |
| 5962-9461108HMC | R | 05/03/2004 | 1 | WHITE ELEC. | | Y | WS512K32-25G2Q | 629 |
| 5962-9461108HTA | R | 05/03/2004 | 1 | AEROFLEX | | Y | ACT-S512K32N-025P7 | 629 |
| 5962-9461108HTA | R | 05/03/2004 | 1 | AUSTIN SEMI. | | Y | AS8S512K32P-25L/Q | 629 |
| 5962-9461108HTA | R | 05/03/2004 | 1 | WHITE ELEC. | | Y | WS512K32N-25H1Q | 629 |
| 5962-9461108HTC | R | 05/03/2004 | 1 | AEROFLEX | | Y | ACT-S512K32N-025P7 | 629 |
| 5962-9461108HTC | R | 05/03/2004 | 1 | AUSTIN SEMI. | | Y | AS8S512K32P-25L/Q | 629 |
| 5962-9461108HTC | R | 05/03/2004 | 1 | WHITE ELEC. | | Y | WS512K32N-25H1Q | 629 |
| 5962-9461108HXA | R | 05/03/2004 | 1 | AEROFLEX | | Y | ACT-S512K32N-025P1 | 629 |
| 5962-9461108HXC | R | 05/03/2004 | 1 | AEROFLEX | | Y | ACT-S512K32N-025P1 | 629 |
| 5962-9461108HYA | R | 05/03/2004 | 1 | AEROFLEX | | Y | ACT-S512K32N-025F1 | 629 |
| 5962-9461108HYC | R | 05/03/2004 | 1 | AEROFLEX | | Y | ACT-S512K32N-025F1 | 629 |
| 5962-9461108HYC | R | 05/03/2004 | 1 | WHITE ELEC. | | Y | WS512K32-25G4TQ | 629 |
| 5962-9461109H9A | R | 05/03/2004 | 1 | WHITE ELEC. | | Y | WS512K32-20G1UQ | 629 |
| 5962-9461109H9C | R | 05/03/2004 | 1 | WHITE ELEC. | | Y | WS512K32-20G1UQ | 629 |
| 5962-9461109HAA | R | 05/03/2004 | 1 | AUSTIN SEMI. | | Y | AS8S512K32Q1-20L/88 | 629 |
| 5962-9461109HAA | R | 05/03/2004 | 1 | WHITE ELEC. | | Y | WS512K32-20G2LQ | 629 |
| 5962-9461109HAC | R | 05/03/2004 | 1 | AUSTIN SEMI. | | Y | AS8S512K32Q1-20L/88 | 629 |
| 5962-9461109HAC | R | 05/03/2004 | 1 | WHITE ELEC. | | Y | WS512K32-20G2LQ | 629 |
| 5962-9461109HBA | R | 05/03/2004 | 1 | WHITE ELEC. | | Y | WS512K32-20G1TQ | 629 |
| 5962-9461109HBC | R | 05/03/2004 | 1 | WHITE ELEC. | | Y | WS512K32-20G1TQ | 629 |
| 5962-9461109HMA | R | 05/03/2004 | 1 | AEROFLEX | | Y | ACT-S512K32N-020F2 | 629 |
| 5962-9461109HMA | R | 05/03/2004 | 1 | AUSTIN SEMI. | | Y | AS8S512K32Q-20L/Q | 629 |
| 5962-9461109HMA | R | 05/03/2004 | 1 | WHITE ELEC. | | Y | WS512K32-20G2Q | 629 |
| 5962-9461109HMC | R | 05/03/2004 | 1 | AEROFLEX | | Y | ACT-S512K32N-020F2 | 629 |
| 5962-9461109HMC | R | 05/03/2004 | 1 | AUSTIN SEMI. | | Y | AS8S512K32Q-20L/Q | 629 |
| 5962-9461109HMC | R | 05/03/2004 | 1 | WHITE ELEC. | | Y | WS512K32-20G2Q | 629 |
| 5962-9461109HTA | R | 05/03/2004 | 1 | AEROFLEX | | Y | ACT-S512K32N-020P7 | 629 |
| 5962-9461109HTA | R | 05/03/2004 | 1 | AUSTIN SEMI. | | Y | AS8S512K32P-20L/Q | 629 |
| 5962-9461109HTA | R | 05/03/2004 | 1 | WHITE ELEC. | | Y | WS512K32N-20H1Q | 629 |
| 5962-9461109HTC | R | 05/03/2004 | 1 | AEROFLEX | | Y | ACT-S512K32N-020P7 | 629 |
| 5962-9461109HTC | R | 05/03/2004 | 1 | AUSTIN SEMI. | | Y | AS8S512K32P-20L/Q | 629 |
| 5962-9461109HTC | R | 05/03/2004 | 1 | WHITE ELEC. | | Y | WS512K32N-20H1Q | 629 |
| 5962-9461109HXA | R | 05/03/2004 | 1 | AEROFLEX | | Y | ACT-S512K32N-020P1 | 629 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9461109HXC | R | 05/03/2004 | 1 | AEROFLEX | | Y | ACT-S512K32N-020P1 | 629 |
| 5962-9461109HYA | R | 05/03/2004 | 1 | AEROFLEX | | Y | ACT-S512K32N-020F1 | 629 |
| 5962-9461109HYC | R | 05/03/2004 | 1 | AEROFLEX | | Y | ACT-S512K32N-020F1 | 629 |
| 5962-9461109HYC | R | 05/03/2004 | 1 | WHITE ELEC. | | Y | WS512K32-20G4TQ | 629 |
| 5962-9461110H9A | R | 05/03/2004 | 1 | WHITE ELEC. | | Y | WS512K32-17G1UQ | 629 |
| 5962-9461110H9C | R | 05/03/2004 | 1 | WHITE ELEC. | | Y | WS512K32-17G1UQ | 629 |
| 5962-9461110HAA | R | 05/03/2004 | 1 | AUSTIN SEMI. | | Y | AS8S512K32Q1-17L/88 | 629 |
| 5962-9461110HAA | R | 05/03/2004 | 1 | WHITE ELEC. | | Y | WS512K32-17G2LQ | 629 |
| 5962-9461110HAC | R | 05/03/2004 | 1 | AUSTIN SEMI. | | Y | AS8S512K32Q1-17L/88 | 629 |
| 5962-9461110HAC | R | 05/03/2004 | 1 | WHITE ELEC. | | Y | WS512K32-17G2LQ | 629 |
| 5962-9461110HBA | R | 05/03/2004 | 1 | WHITE ELEC. | | Y | WS512K32-17G1TQ | 629 |
| 5962-9461110HBC | R | 05/03/2004 | 1 | WHITE ELEC. | | Y | WS512K32-17G1TQ | 629 |
| 5962-9461110HMA | R | 05/03/2004 | 1 | AEROFLEX | | Y | ACT-S512K32N-017F2 | 629 |
| 5962-9461110HMA | R | 05/03/2004 | 1 | AUSTIN SEMI. | | Y | AS8S512K32Q-17L/Q | 629 |
| 5962-9461110HMA | R | 05/03/2004 | 1 | WHITE ELEC. | | Y | WS512K32-17G2Q | 629 |
| 5962-9461110HMC | R | 05/03/2004 | 1 | AEROFLEX | | Y | ACT-S512K32N-017F2 | 629 |
| 5962-9461110HMC | R | 05/03/2004 | 1 | AUSTIN SEMI. | | Y | AS8S512K32Q-17L/Q | 629 |
| 5962-9461110HMC | R | 05/03/2004 | 1 | WHITE ELEC. | | Y | WS512K32-17G2Q | 629 |
| 5962-9461110HTA | R | 05/03/2004 | 1 | AEROFLEX | | Y | ACT-S512K32N-017P7 | 629 |
| 5962-9461110HTA | R | 05/03/2004 | 1 | AUSTIN SEMI. | | Y | AS8S512K32P-17L/Q | 629 |
| 5962-9461110HTA | R | 05/03/2004 | 1 | WHITE ELEC. | | Y | WS512K32N-17H1Q | 629 |
| 5962-9461110HTC | R | 05/03/2004 | 1 | AEROFLEX | | Y | ACT-S512K32N-017P7 | 629 |
| 5962-9461110HTC | R | 05/03/2004 | 1 | AUSTIN SEMI. | | Y | AS8S512K32P-17L/Q | 629 |
| 5962-9461110HTC | R | 05/03/2004 | 1 | WHITE ELEC. | | Y | WS512K32N-17H1Q | 629 |
| 5962-9461110HXA | R | 05/03/2004 | 1 | AEROFLEX | | Y | ACT-S512K32N-017P1 | 629 |
| 5962-9461110HXC | R | 05/03/2004 | 1 | AEROFLEX | | Y | ACT-S512K32N-017P1 | 629 |
| 5962-9461110HYA | R | 05/03/2004 | 1 | AEROFLEX | | Y | ACT-S512K32N-017F1 | 629 |
| 5962-9461110HYC | R | 05/03/2004 | 1 | AEROFLEX | | Y | ACT-S512K32N-017F1 | 629 |
| 5962-9461110HYC | R | 05/03/2004 | 1 | WHITE ELEC. | | Y | WS512K32-17G4TQ | 629 |
| 5962-9461111H9A | R | 05/03/2004 | 1 | WHITE ELEC. | | Y | WS512K32D-55G1UQ | 629 |
| 5962-9461111H9C | R | 05/03/2004 | 1 | WHITE ELEC. | | Y | WS512K32D-55G1UQ | 629 |
| 5962-9461111HAA | R | 05/03/2004 | 1 | AUSTIN SEMI. | | Y | AS8S512K32Q1-55/883 | 629 |
| 5962-9461111HAA | R | 05/03/2004 | 1 | WHITE ELEC. | | Y | WS512K32D-55G2LQ | 629 |
| 5962-9461111HAC | R | 05/03/2004 | 1 | AUSTIN SEMI. | | Y | AS8S512K32Q1-55/883 | 629 |
| 5962-9461111HAC | R | 05/03/2004 | 1 | WHITE ELEC. | | Y | WS512K32D-55G2LQ | 629 |
| 5962-9461111HBA | R | 05/03/2004 | 1 | WHITE ELEC. | | Y | WS512K32D-55G1TQ | 629 |
| 5962-9461111HBC | R | 05/03/2004 | 1 | WHITE ELEC. | | Y | WS512K32D-55G1TQ | 629 |
| 5962-9461111HMA | R | 05/03/2004 | 1 | AUSTIN SEMI. | | Y | AS8S512K32Q-55/Q | 629 |
| 5962-9461111HMA | R | 05/03/2004 | 1 | WHITE ELEC. | | Y | WS512K32D-55G2Q | 629 |
| 5962-9461111HMC | R | 05/03/2004 | 1 | AUSTIN SEMI. | | Y | AS8S512K32Q-55/Q | 629 |
| 5962-9461111HMC | R | 05/03/2004 | 1 | WHITE ELEC. | | Y | WS512K32D-55G2Q | 629 |
| 5962-9461111HTA | R | 05/03/2004 | 1 | AUSTIN SEMI. | | Y | AS8S512K32P-55/Q | 629 |
| 5962-9461111HTA | R | 05/03/2004 | 1 | WHITE ELEC. | | Y | WS512K32ND-55H1Q | 629 |
| 5962-9461111HTC | R | 05/03/2004 | 1 | AUSTIN SEMI. | | Y | AS8S512K32P-55/Q | 629 |
| 5962-9461111HTC | R | 05/03/2004 | 1 | WHITE ELEC. | | Y | WS512K32ND-55H1Q | 629 |
| 5962-9461111HXA | R | 05/03/2004 | | (NONE) | | | 512K32-55 (GEN) | 629 |
| 5962-9461111HYC | R | 05/03/2004 | 1 | WHITE ELEC. | | Y | WS512K32D-55G4TQ | 629 |
| 5962-9461112H9A | R | 05/03/2004 | 1 | WHITE ELEC. | | Y | WS512K32D-45G1UQ | 629 |
| 5962-9461112H9C | R | 05/03/2004 | 1 | WHITE ELEC. | | Y | WS512K32D-45G1UQ | 629 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9461112HAA | R | 05/03/2004 | 1 | AUSTIN SEMI. | | Y | AS8S512K32Q1-45/883 | 629 |
| 5962-9461112HAA | R | 05/03/2004 | 1 | WHITE ELEC. | | Y | WS512K32D-45G2LQ | 629 |
| 5962-9461112HAC | R | 05/03/2004 | 1 | AUSTIN SEMI. | | Y | AS8S512K32Q1-45/883 | 629 |
| 5962-9461112HAC | R | 05/03/2004 | 1 | WHITE ELEC. | | Y | WS512K32D-45G2LQ | 629 |
| 5962-9461112HBA | R | 05/03/2004 | 1 | WHITE ELEC. | | Y | WS512K32D-45G1TQ | 629 |
| 5962-9461112HBC | R | 05/03/2004 | 1 | WHITE ELEC. | | Y | WS512K32D-45G1TQ | 629 |
| 5962-9461112HMA | R | 05/03/2004 | 1 | AUSTIN SEMI. | | Y | AS8S512K32Q-45/Q | 629 |
| 5962-9461112HMA | R | 05/03/2004 | 1 | WHITE ELEC. | | Y | WS512K32D-45G2Q | 629 |
| 5962-9461112HMC | R | 05/03/2004 | 1 | AUSTIN SEMI. | | Y | AS8S512K32Q-45/Q | 629 |
| 5962-9461112HMC | R | 05/03/2004 | 1 | WHITE ELEC. | | Y | WS512K32D-45G2Q | 629 |
| 5962-9461112HTA | R | 05/03/2004 | 1 | AUSTIN SEMI. | | Y | AS8S512K32P-45/Q | 629 |
| 5962-9461112HTA | R | 05/03/2004 | 1 | WHITE ELEC. | | Y | WS512K32ND-45H1Q | 629 |
| 5962-9461112HTC | R | 05/03/2004 | 1 | AUSTIN SEMI. | | Y | AS8S512K32P-45/Q | 629 |
| 5962-9461112HTC | R | 05/03/2004 | 1 | WHITE ELEC. | | Y | WS512K32ND-45H1Q | 629 |
| 5962-9461112HXA | R | 05/03/2004 | | (NONE) | | | 512K32-45 (GEN) | 629 |
| 5962-9461112HYC | R | 05/03/2004 | 1 | WHITE ELEC. | | Y | WS512K32D-45G4TQ | 629 |
| 5962-9461113H9A | R | 05/03/2004 | 1 | WHITE ELEC. | | Y | WS512K32D-35G1UQ | 629 |
| 5962-9461113H9C | R | 05/03/2004 | 1 | WHITE ELEC. | | Y | WS512K32D-35G1UQ | 629 |
| 5962-9461113HAA | R | 05/03/2004 | 1 | AUSTIN SEMI. | | Y | AS8S512K32Q1-35/883 | 629 |
| 5962-9461113HAA | R | 05/03/2004 | 1 | WHITE ELEC. | | Y | WS512K32D-35G2LQ | 629 |
| 5962-9461113HAC | R | 05/03/2004 | 1 | AUSTIN SEMI. | | Y | AS8S512K32Q1-35/883 | 629 |
| 5962-9461113HAC | R | 05/03/2004 | 1 | WHITE ELEC. | | Y | WS512K32D-35G2LQ | 629 |
| 5962-9461113HBA | R | 05/03/2004 | 1 | WHITE ELEC. | | Y | WS512K32D-35G1TQ | 629 |
| 5962-9461113HBC | R | 05/03/2004 | 1 | WHITE ELEC. | | Y | WS512K32D-35G1TQ | 629 |
| 5962-9461113HMA | R | 05/03/2004 | 1 | AUSTIN SEMI. | | Y | AS8S512K32Q-35/Q | 629 |
| 5962-9461113HMA | R | 05/03/2004 | 1 | WHITE ELEC. | | Y | WS512K32D-35G2Q | 629 |
| 5962-9461113HMC | R | 05/03/2004 | 1 | AUSTIN SEMI. | | Y | AS8S512K32Q-35/Q | 629 |
| 5962-9461113HMC | R | 05/03/2004 | 1 | WHITE ELEC. | | Y | WS512K32D-35G2Q | 629 |
| 5962-9461113HTA | R | 05/03/2004 | 1 | AUSTIN SEMI. | | Y | AS8S512K32P-35/Q | 629 |
| 5962-9461113HTA | R | 05/03/2004 | 1 | WHITE ELEC. | | Y | WS512K32ND-35H1Q | 629 |
| 5962-9461113HTC | R | 05/03/2004 | 1 | AUSTIN SEMI. | | Y | AS8S512K32P-35/Q | 629 |
| 5962-9461113HTC | R | 05/03/2004 | 1 | WHITE ELEC. | | Y | WS512K32ND-35H1Q | 629 |
| 5962-9461113HXA | R | 05/03/2004 | | (NONE) | | | 512K32-35 (GEN) | 629 |
| 5962-9461113HYC | R | 05/03/2004 | 1 | WHITE ELEC. | | Y | WS512K32D-35G4TQ | 629 |
| 5962-9461114H9A | R | 05/03/2004 | 1 | WHITE ELEC. | | Y | WS512K32D-25G1UQ | 629 |
| 5962-9461114H9C | R | 05/03/2004 | 1 | WHITE ELEC. | | Y | WS512K32D-25G1UQ | 629 |
| 5962-9461114HAA | R | 05/03/2004 | 1 | AUSTIN SEMI. | | Y | AS8S512K32Q1-25/883 | 629 |
| 5962-9461114HAA | R | 05/03/2004 | 1 | WHITE ELEC. | | Y | WS512K32D-25G2LQ | 629 |
| 5962-9461114HAA | R | 05/03/2004 | 1 | WHITE ELEC. | | Y | WS512K32D-25G2LQ | 629 |
| 5962-9461114HAC | R | 05/03/2004 | 1 | AUSTIN SEMI. | | Y | AS8S512K32Q1-25/883 | 629 |
| 5962-9461114HBA | R | 05/03/2004 | 1 | WHITE ELEC. | | Y | WS512K32D-25G1TQ | 629 |
| 5962-9461114HBC | R | 05/03/2004 | 1 | WHITE ELEC. | | Y | WS512K32D-25G1TQ | 629 |
| 5962-9461114HMA | R | 05/03/2004 | 1 | AUSTIN SEMI. | | Y | AS8S512K32Q-25/Q | 629 |
| 5962-9461114HMA | R | 05/03/2004 | 1 | WHITE ELEC. | | Y | WS512K32D-25G2Q | 629 |
| 5962-9461114HMC | R | 05/03/2004 | 1 | AUSTIN SEMI. | | Y | AS8S512K32Q-25/Q | 629 |
| 5962-9461114HMC | R | 05/03/2004 | 1 | WHITE ELEC. | | Y | WS512K32D-25G2Q | 629 |
| 5962-9461114HTA | R | 05/03/2004 | 1 | AUSTIN SEMI. | | Y | AS8S512K32P-25/Q | 629 |
| 5962-9461114HTA | R | 05/03/2004 | 1 | WHITE ELEC. | | Y | WS512K32ND-25H1Q | 629 |
| 5962-9461114HTC | R | 05/03/2004 | 1 | AUSTIN SEMI. | | Y | AS8S512K32P-25/Q | 629 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9461114HTC | R | 05/03/2004 | 1 | WHITE ELEC. | | Y | WS512K32ND-25H1Q | 629 |
| 5962-9461114HXA | R | 05/03/2004 | | (NONE) | | | 512K32-25 (GEN) | 629 |
| 5962-9461114HYC | R | 05/03/2004 | 1 | WHITE ELEC. | | Y | WS512K32D-25G4TQ | 629 |
| 5962-9461115H9A | R | 05/03/2004 | 1 | WHITE ELEC. | | Y | WS512K32D-20G1UQ | 629 |
| 5962-9461115H9C | R | 05/03/2004 | 1 | WHITE ELEC. | | Y | WS512K32D-20G1UQ | 629 |
| 5962-9461115HAA | R | 05/03/2004 | 1 | AUSTIN SEMI. | | Y | AS8S512K32Q1-20/883 | 629 |
| 5962-9461115HAA | R | 05/03/2004 | 1 | WHITE ELEC. | | Y | WS512K32D-20G2LQ | 629 |
| 5962-9461115HAC | R | 05/03/2004 | 1 | AUSTIN SEMI. | | Y | AS8S512K32Q1-20/883 | 629 |
| 5962-9461115HAC | R | 05/03/2004 | 1 | WHITE ELEC. | | Y | WS512K32D-20G2LQ | 629 |
| 5962-9461115HBA | R | 05/03/2004 | 1 | WHITE ELEC. | | Y | WS512K32D-20G1TQ | 629 |
| 5962-9461115HBC | R | 05/03/2004 | 1 | WHITE ELEC. | | Y | WS512K32D-20G1TQ | 629 |
| 5962-9461115HMA | R | 05/03/2004 | 1 | AUSTIN SEMI. | | Y | AS8S512K32Q-20/Q | 629 |
| 5962-9461115HMA | R | 05/03/2004 | 1 | WHITE ELEC. | | Y | WS512K32D-20G2Q | 629 |
| 5962-9461115HMC | R | 05/03/2004 | 1 | AUSTIN SEMI. | | Y | AS8S512K32Q-20/Q | 629 |
| 5962-9461115HMC | R | 05/03/2004 | 1 | WHITE ELEC. | | Y | WS512K32D-20G2Q | 629 |
| 5962-9461115HTA | R | 05/03/2004 | 1 | AUSTIN SEMI. | | Y | AS8S512K32P-20/Q | 629 |
| 5962-9461115HTA | R | 05/03/2004 | 1 | WHITE ELEC. | | Y | WS512K32ND-20H1Q | 629 |
| 5962-9461115HTC | R | 05/03/2004 | 1 | AUSTIN SEMI. | | Y | AS8S512K32P-20/Q | 629 |
| 5962-9461115HTC | R | 05/03/2004 | 1 | WHITE ELEC. | | Y | WS512K32ND-20H1Q | 629 |
| 5962-9461115HXA | R | 05/03/2004 | | (NONE) | | | 512K32-20 (GEN) | 629 |
| 5962-9461115HYC | R | 05/03/2004 | 1 | WHITE ELEC. | | Y | WS512K32D-20G4TQ | 629 |
| 5962-9461116H9A | R | 05/03/2004 | 1 | WHITE ELEC. | | Y | WS512K32D-17G1UQ | 629 |
| 5962-9461116H9C | R | 05/03/2004 | 1 | WHITE ELEC. | | Y | WS512K32D-17G1UQ | 629 |
| 5962-9461116HAA | R | 05/03/2004 | 1 | AUSTIN SEMI. | | Y | AS8S512K32Q1-17/883 | 629 |
| 5962-9461116HAA | R | 05/03/2004 | 1 | WHITE ELEC. | | Y | WS512K32D-17G2LQ | 629 |
| 5962-9461116HAC | R | 05/03/2004 | 1 | AUSTIN SEMI. | | Y | AS8S512K32Q1-17/883 | 629 |
| 5962-9461116HAC | R | 05/03/2004 | 1 | WHITE ELEC. | | Y | WS512K32D-17G2LQ | 629 |
| 5962-9461116HBA | R | 05/03/2004 | 1 | WHITE ELEC. | | Y | WS512K32D-17G1TQ | 629 |
| 5962-9461116HBC | R | 05/03/2004 | 1 | WHITE ELEC. | | Y | WS512K32D-17G1TQ | 629 |
| 5962-9461116HMA | R | 05/03/2004 | 1 | AUSTIN SEMI. | | Y | AS8S512K32Q-17/Q | 629 |
| 5962-9461116HMA | R | 05/03/2004 | 1 | WHITE ELEC. | | Y | WS512K32D-17G2Q | 629 |
| 5962-9461116HMC | R | 05/03/2004 | 1 | AUSTIN SEMI. | | Y | AS8S512K32Q-17/Q | 629 |
| 5962-9461116HMC | R | 05/03/2004 | 1 | WHITE ELEC. | | Y | WS512K32D-17G2Q | 629 |
| 5962-9461116HTA | R | 05/03/2004 | 1 | AUSTIN SEMI. | | Y | AS8S512K32P-17/Q | 629 |
| 5962-9461116HTA | R | 05/03/2004 | 1 | WHITE ELEC. | | Y | WS512K32ND-17H1Q | 629 |
| 5962-9461116HTC | R | 05/03/2004 | 1 | AUSTIN SEMI. | | Y | AS8S512K32P-17/Q | 629 |
| 5962-9461116HTC | R | 05/03/2004 | 1 | WHITE ELEC. | | Y | WS512K32ND-17H1Q | 629 |
| 5962-9461116HXA | R | 05/03/2004 | | (NONE) | | | 512K32-17 (GEN) | 629 |
| 5962-9461116HYC | R | 05/03/2004 | 1 | WHITE ELEC. | | Y | WS512K32D-17G4TQ | 629 |
| 5962-9461117H9A | R | 05/03/2004 | 1 | WHITE ELEC. | | Y | WS512K32D-15G1UQ | 629 |
| 5962-9461117H9C | R | 05/03/2004 | 1 | WHITE ELEC. | | Y | WS512K32D-15G1UQ | 629 |
| 5962-9461117HAA | R | 05/03/2004 | 1 | AUSTIN SEMI. | | Y | AS8S512K32Q1-15/883 | 629 |
| 5962-9461117HAA | R | 05/03/2004 | 1 | WHITE ELEC. | | Y | WS512K32D-15G2LQ | 629 |
| 5962-9461117HAC | R | 05/03/2004 | 1 | AUSTIN SEMI. | | Y | AS8S512K32Q1-15/883 | 629 |
| 5962-9461117HAC | R | 05/03/2004 | 1 | WHITE ELEC. | | Y | WS512K32D-15G2LQ | 629 |
| 5962-9461117HBA | R | 05/03/2004 | 1 | WHITE ELEC. | | Y | WS512K32D-15G1TQ | 629 |
| 5962-9461117HBC | R | 05/03/2004 | 1 | WHITE ELEC. | | Y | WS512K32D-15G1TQ | 629 |
| 5962-9461117HMA | R | 05/03/2004 | 1 | AUSTIN SEMI. | | Y | AS8S512K32Q-15/Q | 629 |
| 5962-9461117HMA | R | 05/03/2004 | 1 | WHITE ELEC. | | Y | WS512K32D-15G2Q | 629 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9461117HMC | R | 05/03/2004 | 1 | AUSTIN SEMI. | | Y | AS8S512K32Q-15/Q | 629 |
| 5962-9461117HMC | R | 05/03/2004 | 1 | WHITE ELEC. | | Y | WS512K32D-15G2Q | 629 |
| 5962-9461117HTA | R | 05/03/2004 | 1 | AUSTIN SEMI. | | Y | AS8S512K32P-15/Q | 629 |
| 5962-9461117HTA | R | 05/03/2004 | 1 | WHITE ELEC. | | Y | WS512K32ND-15H1Q | 629 |
| 5962-9461117HTC | R | 05/03/2004 | 1 | AUSTIN SEMI. | | Y | AS8S512K32P-15/Q | 629 |
| 5962-9461117HTC | R | 05/03/2004 | 1 | WHITE ELEC. | | Y | WS512K32ND-15H1Q | 629 |
| 5962-9461118H9A | R | 05/03/2004 | 1 | WHITE ELEC. | | Y | WS512K32D-12G1UQ | 629 |
| 5962-9461118H9C | R | 05/03/2004 | 1 | WHITE ELEC. | | Y | WS512K32D-12G1UQ | 629 |
| 5962-9461118HAA | R | 05/03/2004 | 1 | AUSTIN SEMI. | | Y | AS8S512K32Q1-12/883 | 629 |
| 5962-9461118HAA | R | 05/03/2004 | 1 | WHITE ELEC. | | Y | WS512K32D-12G2LQ | 629 |
| 5962-9461118HAC | R | 05/03/2004 | 1 | AUSTIN SEMI. | | Y | AS8S512K32Q1-12/883 | 629 |
| 5962-9461118HAC | R | 05/03/2004 | 1 | WHITE ELEC. | | Y | WS512K32D-12G2LQ | 629 |
| 5962-9461118HBA | R | 05/03/2004 | 1 | WHITE ELEC. | | Y | WS512K32D-12G1TQ | 629 |
| 5962-9461118HBC | R | 05/03/2004 | 1 | WHITE ELEC. | | Y | WS512K32D-12G1TQ | 629 |
| 5962-9461118HMA | R | 05/03/2004 | 1 | AUSTIN SEMI. | | Y | AS8S512K32Q-12/Q | 629 |
| 5962-9461118HMA | R | 05/03/2004 | 1 | WHITE ELEC. | | Y | WS512K32D-12G2Q | 629 |
| 5962-9461118HMC | R | 05/03/2004 | 1 | AUSTIN SEMI. | | Y | AS8S512K32Q-12/Q | 629 |
| 5962-9461118HMC | R | 05/03/2004 | 1 | WHITE ELEC. | | Y | WS512K32D-12G2Q | 629 |
| 5962-9461118HTA | R | 05/03/2004 | 1 | AUSTIN SEMI. | | Y | AS8S512K32P-12/Q | 629 |
| 5962-9461118HTA | R | 05/03/2004 | 1 | WHITE ELEC. | | Y | WS512K32ND-12H1Q | 629 |
| 5962-9461118HTC | R | 05/03/2004 | 1 | AUSTIN SEMI. | | Y | AS8S512K32P-12/Q | 629 |
| 5962-9461118HTC | R | 05/03/2004 | 1 | WHITE ELEC. | | Y | WS512K32ND-12H1Q | 629 |
| 5962-9461119H9A | R | 05/03/2004 | 1 | WHITE ELEC. | | Y | WS512K32-15G1UQ | 629 |
| 5962-9461119H9C | R | 05/03/2004 | 1 | WHITE ELEC. | | Y | WS512K32-15G1UQ | 629 |
| 5962-9461119HAA | R | 05/03/2004 | 1 | AUSTIN SEMI. | | Y | AS8S512K32Q1-15L/88 | 629 |
| 5962-9461119HAA | R | 05/03/2004 | 1 | WHITE ELEC. | | Y | WS512K32-15G2LQ | 629 |
| 5962-9461119HAC | R | 05/03/2004 | 1 | AUSTIN SEMI. | | Y | AS8S512K32Q1-15L/88 | 629 |
| 5962-9461119HAC | R | 05/03/2004 | 1 | WHITE ELEC. | | Y | WS512K32-15G2LQ | 629 |
| 5962-9461119HBA | R | 05/03/2004 | 1 | WHITE ELEC. | | Y | WS512K32-15G1TQ | 629 |
| 5962-9461119HBC | R | 05/03/2004 | 1 | WHITE ELEC. | | Y | WS512K32-15G1TQ | 629 |
| 5962-9461119HMA | R | 05/03/2004 | 1 | AUSTIN SEMI. | | Y | AS8S512K32Q-15L/Q | 629 |
| 5962-9461119HMA | R | 05/03/2004 | 1 | WHITE ELEC. | | Y | WS512K32-15G2Q | 629 |
| 5962-9461119HMC | R | 05/03/2004 | 1 | AUSTIN SEMI. | | Y | AS8S512K32Q-15L/Q | 629 |
| 5962-9461119HMC | R | 05/03/2004 | 1 | WHITE ELEC. | | Y | WS512K32-15G2Q | 629 |
| 5962-9461119HTA | R | 05/03/2004 | 1 | AUSTIN SEMI. | | Y | AS8S512K32P-15L/Q | 629 |
| 5962-9461119HTA | R | 05/03/2004 | 1 | WHITE ELEC. | | Y | WS512K32N-15H1Q | 629 |
| 5962-9461119HTC | R | 05/03/2004 | 1 | AUSTIN SEMI. | | Y | AS8S512K32P-15L/Q | 629 |
| 5962-9461119HTC | R | 05/03/2004 | 1 | WHITE ELEC. | | Y | WS512K32N-15H1Q | 629 |
| 5962-9461120H9A | R | 05/03/2004 | 1 | WHITE ELEC. | | Y | WS512K32-12G1UQ | 629 |
| 5962-9461120H9C | R | 05/03/2004 | 1 | WHITE ELEC. | | Y | WS512K32-12G1UQ | 629 |
| 5962-9461120HAA | R | 05/03/2004 | 1 | AUSTIN SEMI. | | Y | AS8S512K32Q1-12L/88 | 629 |
| 5962-9461120HAA | R | 05/03/2004 | 1 | WHITE ELEC. | | Y | WS512K32-12G2LQ | 629 |
| 5962-9461120HAC | R | 05/03/2004 | 1 | AUSTIN SEMI. | | Y | AS8S512K32Q1-12L/88 | 629 |
| 5962-9461120HAC | R | 05/03/2004 | 1 | WHITE ELEC. | | Y | WS512K32-12G2LQ | 629 |
| 5962-9461120HBA | R | 05/03/2004 | 1 | WHITE ELEC. | | Y | WS512K32-12G1TQ | 629 |
| 5962-9461120HBC | R | 05/03/2004 | 1 | WHITE ELEC. | | Y | WS512K32-12G1TQ | 629 |
| 5962-9461120HMA | R | 05/03/2004 | 1 | AUSTIN SEMI. | | Y | AS8S512K32Q-12L/Q | 629 |
| 5962-9461120HMA | R | 05/03/2004 | 1 | WHITE ELEC. | | Y | WS512K32-12G2Q | 629 |
| 5962-9461120HMC | R | 05/03/2004 | 1 | AUSTIN SEMI. | | Y | AS8S512K32Q-12L/Q | 629 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9461120HMC | R | 05/03/2004 | 1 | WHITE ELEC. | | Y | WS512K32-12G2Q | 629 |
| 5962-9461120HTA | R | 05/03/2004 | 1 | AUSTIN SEMI. | | Y | AS8S512K32P-12L/Q | 629 |
| 5962-9461120HTA | R | 05/03/2004 | 1 | WHITE ELEC. | | Y | WS512K32N-12H1Q | 629 |
| 5962-9461120HTC | R | 05/03/2004 | 1 | AUSTIN SEMI. | | Y | AS8S512K32P-12L/Q | 629 |
| 5962-9461120HTC | R | 05/03/2004 | 1 | WHITE ELEC. | | Y | WS512K32N-12H1Q | 629 |
| 5962-9461201H4A | G | 10/10/2003 | 1 | AEROFLEX | | Y | ACT-F512K32A-150P7 | 669 |
| 5962-9461201H4A | G | 10/10/2003 | 1 | AUSTIN SEMI. | | Y | AS8F512K32P-150/883 | 669 |
| 5962-9461201H4A | G | 10/10/2003 | 1 | WHITE ELEC. | | Y | WF512K32N-150H1Q5 | 669 |
| 5962-9461201H4C | G | 10/10/2003 | 1 | AEROFLEX | | Y | ACT-F512K32A-150P7 | 669 |
| 5962-9461201H4C | G | 10/10/2003 | 1 | AUSTIN SEMI. | | Y | AS8F512K32P-150/883 | 669 |
| 5962-9461201H4C | G | 10/10/2003 | 1 | WHITE ELEC. | | Y | WF512K32N-150H1Q5 | 669 |
| 5962-9461201H9A | G | 10/10/2003 | 1 | WHITE ELEC. | | Y | WF512K32-150G1UQ5 | 669 |
| 5962-9461201H9C | G | 10/10/2003 | 1 | WHITE ELEC. | | Y | WF512K32-150G1UQ5 | 669 |
| 5962-9461201HAA | G | 10/10/2003 | 1 | AUSTIN SEMI. | | Y | AS8F512K32Q1-150/88 | 669 |
| 5962-9461201HAA | G | 10/10/2003 | 1 | WHITE ELEC. | | Y | WF512K32-150G2LQ5 | 669 |
| 5962-9461201HAC | G | 10/10/2003 | 1 | AUSTIN SEMI. | | Y | AS8F512K32Q1-150/88 | 669 |
| 5962-9461201HAC | G | 10/10/2003 | 1 | WHITE ELEC. | | Y | WF512K32-150G2LQ5 | 669 |
| 5962-9461201HBA | G | 10/10/2003 | 1 | WHITE ELEC. | | Y | WF512K32-150G1TQ5 | 669 |
| 5962-9461201HBC | G | 10/10/2003 | 1 | WHITE ELEC. | | Y | WF512K32-150G1TQ5 | 669 |
| 5962-9461201HMA | G | 10/10/2003 | 1 | AEROFLEX | | Y | ACT-F512K32N-150F5 | 669 |
| 5962-9461201HMA | G | 10/10/2003 | 1 | AUSTIN SEMI. | | Y | AS8F512K32Q-150/883 | 669 |
| 5962-9461201HMA | G | 10/10/2003 | 1 | WHITE ELEC. | | Y | WF512K32-150G2Q5 | 669 |
| 5962-9461201HMC | G | 10/10/2003 | 1 | AEROFLEX | | Y | ACT-F512K32N-150F5 | 669 |
| 5962-9461201HMC | G | 10/10/2003 | 1 | AUSTIN SEMI. | | Y | AS8F512K32Q-150/883 | 669 |
| 5962-9461201HMC | G | 10/10/2003 | 1 | WHITE ELEC. | | Y | WF512K32-150G2QG | 669 |
| 5962-9461201HNA | G | 10/10/2003 | 1 | WHITE ELEC. | | Y | WF512K32F-150G4Q5 | 669 |
| 5962-9461201HNC | G | 10/10/2003 | 1 | WHITE ELEC. | | Y | WF512K32F-150G4Q5 | 669 |
| 5962-9461201HTC | G | 10/10/2003 | 1 | WHITE ELEC. | | Y | WF512K32-150G4TQ5 | 669 |
| 5962-9461201HUA | G | 10/10/2003 | 1 | AEROFLEX | | Y | ACT-F512K32N-150P7 | 669 |
| 5962-9461201HUA | G | 10/10/2003 | 1 | WHITE ELEC. | | Y | WF512K32N-150HQ5 | 669 |
| 5962-9461201HUC | G | 10/10/2003 | 1 | AEROFLEX | | Y | ACT-F512K32N-150P7 | 669 |
| 5962-9461201HUC | G | 10/10/2003 | 1 | WHITE ELEC. | | Y | WF512K32N-150HQ5 | 669 |
| 5962-9461201HXA | G | 10/10/2003 | 1 | AEROFLEX | | Y | ACT-F512K32N-150P3 | 669 |
| 5962-9461201HXC | G | 10/10/2003 | 1 | AEROFLEX | | Y | ACT-F512K32N-150P3 | 669 |
| 5962-9461201HYC | G | 10/10/2003 | 1 | AEROFLEX | | Y | ACT-F512K32N-150F5U | 669 |
| 5962-9461201HZA | G | 10/10/2003 | 1 | WHITE ELEC. | | Y | WF512K32-150G2UQ5 | 669 |
| 5962-9461201HZC | G | 10/10/2003 | 1 | WHITE ELEC. | | Y | WF512K32-150G2UQ5 | 669 |
| 5962-9461202H4A | G | 10/10/2003 | 1 | AEROFLEX | | Y | ACT-F512K32A-120P7 | 669 |
| 5962-9461202H4A | G | 10/10/2003 | 1 | AUSTIN SEMI. | | Y | AS8F512K32P-120/883 | 669 |
| 5962-9461202H4A | G | 10/10/2003 | 1 | WHITE ELEC. | | Y | WF512K32N-120H1Q5 | 669 |
| 5962-9461202H4C | G | 10/10/2003 | 1 | AEROFLEX | | Y | ACT-F512K32A-120P7 | 669 |
| 5962-9461202H4C | G | 10/10/2003 | 1 | AUSTIN SEMI. | | Y | AS8F512K32P-120/883 | 669 |
| 5962-9461202H4C | G | 10/10/2003 | 1 | WHITE ELEC. | | Y | WF512K32N-120H1Q5 | 669 |
| 5962-9461202H9A | G | 10/10/2003 | 1 | WHITE ELEC. | | Y | WF512K32-120G1UQ5 | 669 |
| 5962-9461202H9C | G | 10/10/2003 | 1 | WHITE ELEC. | | Y | WF512K32-120G1UQ5 | 669 |
| 5962-9461202HAA | G | 10/10/2003 | 1 | AUSTIN SEMI. | | Y | AS8F512K32Q1-120/88 | 669 |
| 5962-9461202HAA | G | 10/10/2003 | 1 | WHITE ELEC. | | Y | WF512K32-120G2LQ5 | 669 |
| 5962-9461202HAC | G | 10/10/2003 | 1 | AUSTIN SEMI. | | Y | AS8F512K32Q1-120/88 | 669 |
| 5962-9461202HAC | G | 10/10/2003 | 1 | WHITE ELEC. | | Y | WF512K32-120G2LQ5 | 669 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9461202HBA | G | 10/10/2003 | 1 | WHITE ELEC. | | Y | WF512K32-120G1TQ5 | 669 |
| 5962-9461202HBC | G | 10/10/2003 | 1 | WHITE ELEC. | | Y | WF512K32-120G1TQ5 | 669 |
| 5962-9461202HMA | G | 10/10/2003 | 1 | AEROFLEX | | Y | ACT-F512K32N-120F5 | 669 |
| 5962-9461202HMA | G | 10/10/2003 | 1 | AUSTIN SEMI. | | Y | AS8F512K32Q-120/883 | 669 |
| 5962-9461202HMA | G | 10/10/2003 | 1 | WHITE ELEC. | | Y | WF512K32-120G2Q5 | 669 |
| 5962-9461202HMC | G | 10/10/2003 | 1 | AEROFLEX | | Y | ACT-F512K32N-120F5 | 669 |
| 5962-9461202HMC | G | 10/10/2003 | 1 | AUSTIN SEMI. | | Y | AS8F512K32Q-120/883 | 669 |
| 5962-9461202HMC | G | 10/10/2003 | 1 | WHITE ELEC. | | Y | WF512K32-120G2Q5 | 669 |
| 5962-9461202HNA | G | 10/10/2003 | 1 | WHITE ELEC. | | Y | WF512K32F-120G4Q5 | 669 |
| 5962-9461202HNC | G | 10/10/2003 | 1 | WHITE ELEC. | | Y | WF512K32F-120G4Q5 | 669 |
| 5962-9461202HTC | G | 10/10/2003 | 1 | WHITE ELEC. | | Y | WF512K32-120G4TQ5 | 669 |
| 5962-9461202HUA | G | 10/10/2003 | 1 | AEROFLEX | | Y | ACT-F512K32N-120P7 | 669 |
| 5962-9461202HUA | G | 10/10/2003 | 1 | WHITE ELEC. | | Y | WF512K32N-120HQ5 | 669 |
| 5962-9461202HUC | G | 10/10/2003 | 1 | AEROFLEX | | Y | ACT-F512K32N-120P7 | 669 |
| 5962-9461202HUC | G | 10/10/2003 | 1 | WHITE ELEC. | | Y | WF512K32N-120HQ5 | 669 |
| 5962-9461202HXA | G | 10/10/2003 | 1 | AEROFLEX | | Y | ACT-F512K32N-120P3 | 669 |
| 5962-9461202HXC | G | 10/10/2003 | 1 | AEROFLEX | | Y | ACT-F512K32N-120P3 | 669 |
| 5962-9461202HYC | G | 10/10/2003 | 1 | AEROFLEX | | Y | ACT-F512K32N-120F5U | 669 |
| 5962-9461202HZA | G | 10/10/2003 | 1 | WHITE ELEC. | | Y | WF512K32-120G2UQ5 | 669 |
| 5962-9461202HZC | G | 10/10/2003 | 1 | WHITE ELEC. | | Y | WF512K32-120G2UQ5 | 669 |
| 5962-9461203H4A | G | 10/10/2003 | 1 | AEROFLEX | | Y | ACT-F512K32A-090P7 | 669 |
| 5962-9461203H4A | G | 10/10/2003 | 1 | AUSTIN SEMI. | | Y | AS8F512K32P-90/883C | 669 |
| 5962-9461203H4A | G | 10/10/2003 | 1 | WHITE ELEC. | | Y | WF512K32N-90H1Q5 | 669 |
| 5962-9461203H4C | G | 10/10/2003 | 1 | AEROFLEX | | Y | ACT-F512K32A-090P7 | 669 |
| 5962-9461203H4C | G | 10/10/2003 | 1 | AUSTIN SEMI. | | Y | AS8F512K32P-90/883C | 669 |
| 5962-9461203H4C | G | 10/10/2003 | 1 | WHITE ELEC. | | Y | WF512K32N-90H1Q5 | 669 |
| 5962-9461203H9A | G | 10/10/2003 | 1 | WHITE ELEC. | | Y | WF512K32-90G1UQ5 | 669 |
| 5962-9461203H9C | G | 10/10/2003 | 1 | WHITE ELEC. | | Y | WF512K32-90G1UQ5 | 669 |
| 5962-9461203HAA | G | 10/10/2003 | 1 | AUSTIN SEMI. | | Y | AS8F512K32Q1-90/883 | 669 |
| 5962-9461203HAA | G | 10/10/2003 | 1 | WHITE ELEC. | | Y | WF512K32-90G2LQ5 | 669 |
| 5962-9461203HAC | G | 10/10/2003 | 1 | AUSTIN SEMI. | | Y | AS8F512K32Q1-90/883 | 669 |
| 5962-9461203HAC | G | 10/10/2003 | 1 | WHITE ELEC. | | Y | WF512K32-90G2LQ5 | 669 |
| 5962-9461203HBA | G | 10/10/2003 | 1 | WHITE ELEC. | | Y | WF512K32-90G1TQ5 | 669 |
| 5962-9461203HBC | G | 10/10/2003 | 1 | WHITE ELEC. | | Y | WF512K32-90G1TQ5 | 669 |
| 5962-9461203HMA | G | 10/10/2003 | 1 | AEROFLEX | | Y | ACT-F512K32N-090F5 | 669 |
| 5962-9461203HMA | G | 10/10/2003 | 1 | AUSTIN SEMI. | | Y | AS8F512K32Q-90/883C | 669 |
| 5962-9461203HMA | G | 10/10/2003 | 1 | WHITE ELEC. | | Y | WF512K32-90G2Q5 | 669 |
| 5962-9461203HMC | G | 10/10/2003 | 1 | AEROFLEX | | Y | ACT-F512K32N-090F5 | 669 |
| 5962-9461203HMC | G | 10/10/2003 | 1 | AUSTIN SEMI. | | Y | AS8F512K32Q-90/883C | 669 |
| 5962-9461203HMC | G | 10/10/2003 | 1 | WHITE ELEC. | | Y | WF512K32-90G2Q5 | 669 |
| 5962-9461203HNA | G | 10/10/2003 | 1 | WHITE ELEC. | | Y | WF512K32F-90G4Q5 | 669 |
| 5962-9461203HNC | G | 10/10/2003 | 1 | WHITE ELEC. | | Y | WF512K32F-90G4Q5 | 669 |
| 5962-9461203HTC | G | 10/10/2003 | 1 | WHITE ELEC. | | Y | WF512K32-90G4TQ5 | 669 |
| 5962-9461203HUA | G | 10/10/2003 | 1 | AEROFLEX | | Y | ACT-F512K32N-090P7 | 669 |
| 5962-9461203HUA | G | 10/10/2003 | 1 | WHITE ELEC. | | Y | WF512K32N-90HQ5 | 669 |
| 5962-9461203HUC | G | 10/10/2003 | 1 | AEROFLEX | | Y | ACT-F512K32N-090P7 | 669 |
| 5962-9461203HUC | G | 10/10/2003 | 1 | WHITE ELEC. | | Y | WF512K32N-90HQ5 | 669 |
| 5962-9461203HXA | G | 10/10/2003 | 1 | AEROFLEX | | Y | ACT-F512K32N-090P3 | 669 |
| 5962-9461203HXC | G | 10/10/2003 | 1 | AEROFLEX | | Y | ACT-F512K32N-090P3 | 669 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9461203HYC | G | 10/10/2003 | 1 | AEROFLEX | | Y | ACT-F512K32N-090F5U | 669 |
| 5962-9461203HZA | G | 10/10/2003 | 1 | WHITE ELEC. | | Y | WF512K32-90G2UQ5 | 669 |
| 5962-9461203HZC | G | 10/10/2003 | 1 | WHITE ELEC. | | Y | WF512K32-90G2UQ5 | 669 |
| 5962-9461204H4A | G | 10/10/2003 | 1 | AEROFLEX | | Y | ACT-F512K32A-070P7 | 669 |
| 5962-9461204H4A | G | 10/10/2003 | 1 | AUSTIN SEMI. | | Y | AS8F512K32P-70/883C | 669 |
| 5962-9461204H4A | G | 10/10/2003 | 1 | WHITE ELEC. | | Y | WF512K32N-70H1Q5 | 669 |
| 5962-9461204H4C | G | 10/10/2003 | 1 | AEROFLEX | | Y | ACT-F512K32A-070P7 | 669 |
| 5962-9461204H4C | G | 10/10/2003 | 1 | AUSTIN SEMI. | | Y | AS8F512K32P-70/883C | 669 |
| 5962-9461204H4C | G | 10/10/2003 | 1 | WHITE ELEC. | | Y | WF512K32N-70H1Q5 | 669 |
| 5962-9461204H9A | G | 10/10/2003 | 1 | WHITE ELEC. | | Y | WF512K32-70G1UQ5 | 669 |
| 5962-9461204H9C | G | 10/10/2003 | 1 | WHITE ELEC. | | Y | WF512K32-70G1UQ5 | 669 |
| 5962-9461204HAA | G | 10/10/2003 | 1 | AUSTIN SEMI. | | Y | AS8F512K32Q1-70/883 | 669 |
| 5962-9461204HAA | G | 10/10/2003 | 1 | WHITE ELEC. | | Y | WF512K32-70G2LQ5 | 669 |
| 5962-9461204HAC | G | 10/10/2003 | 1 | AUSTIN SEMI. | | Y | AS8F512K32Q1-70/883 | 669 |
| 5962-9461204HAC | G | 10/10/2003 | 1 | WHITE ELEC. | | Y | WF512K32-70G2LQ5 | 669 |
| 5962-9461204HBA | G | 10/10/2003 | 1 | WHITE ELEC. | | Y | WF512K32-70G1TQ5 | 669 |
| 5962-9461204HBC | G | 10/10/2003 | 1 | WHITE ELEC. | | Y | WF512K32-70G1TQ5 | 669 |
| 5962-9461204HMA | G | 10/10/2003 | 1 | AEROFLEX | | Y | ACT-F512K32N-070F5 | 669 |
| 5962-9461204HMA | G | 10/10/2003 | 1 | AUSTIN SEMI. | | Y | AS8F512K32Q-70/883C | 669 |
| 5962-9461204HMA | G | 10/10/2003 | 1 | WHITE ELEC. | | Y | WF512K32-70G2Q5 | 669 |
| 5962-9461204HMC | G | 10/10/2003 | 1 | AEROFLEX | | Y | ACT-F512K32N-070F5 | 669 |
| 5962-9461204HMC | G | 10/10/2003 | 1 | AUSTIN SEMI. | | Y | AS8F512K32Q-70/883C | 669 |
| 5962-9461204HMC | G | 10/10/2003 | 1 | WHITE ELEC. | | Y | WF512K32-70G2Q5 | 669 |
| 5962-9461204HNA | G | 10/10/2003 | 1 | WHITE ELEC. | | Y | WF512K32F-70G4Q5 | 669 |
| 5962-9461204HNC | G | 10/10/2003 | 1 | WHITE ELEC. | | Y | WF512K32F-70G4Q5 | 669 |
| 5962-9461204HTC | G | 10/10/2003 | 1 | WHITE ELEC. | | Y | WF512K32-70G4TQ5 | 669 |
| 5962-9461204HUA | G | 10/10/2003 | 1 | AEROFLEX | | Y | ACT-F512K32N-070P7 | 669 |
| 5962-9461204HUA | G | 10/10/2003 | 1 | WHITE ELEC. | | Y | WF512K32N-70HQ5 | 669 |
| 5962-9461204HUC | G | 10/10/2003 | 1 | AEROFLEX | | Y | ACT-F512K32N-070P7 | 669 |
| 5962-9461204HUC | G | 10/10/2003 | 1 | WHITE ELEC. | | Y | WF512K32N-70HQ5 | 669 |
| 5962-9461204HXA | G | 10/10/2003 | 1 | AEROFLEX | | Y | ACT-F512K32N-070P3 | 669 |
| 5962-9461204HXC | G | 10/10/2003 | 1 | AEROFLEX | | Y | ACT-F512K32N-070P3 | 669 |
| 5962-9461204HYC | G | 10/10/2003 | 1 | AEROFLEX | | Y | ACT-F512K32N-070F5U | 669 |
| 5962-9461204HZA | G | 10/10/2003 | 1 | WHITE ELEC. | | Y | WF512K32-70G2UQ5 | 669 |
| 5962-9461204HZC | G | 10/10/2003 | 1 | WHITE ELEC. | | Y | WF512K32-70G2UQ5 | 669 |
| 5962-9461205H4A | G | 10/10/2003 | 1 | AEROFLEX | | Y | ACT-F512K32A-060P7 | 669 |
| 5962-9461205H4A | G | 10/10/2003 | 1 | WHITE ELEC. | | Y | WF512K32N-60H1Q5 | 669 |
| 5962-9461205H4C | G | 10/10/2003 | 1 | AEROFLEX | | Y | ACT-F512K32A-060P7 | 669 |
| 5962-9461205H4C | G | 10/10/2003 | 1 | WHITE ELEC. | | Y | WF512K32N-60H1Q5 | 669 |
| 5962-9461205H9A | G | 10/10/2003 | 1 | WHITE ELEC. | | Y | WF512K32-60G1UQ5 | 669 |
| 5962-9461205H9C | G | 10/10/2003 | 1 | WHITE ELEC. | | Y | WF512K32-60G1UQ5 | 669 |
| 5962-9461205HAA | G | 10/10/2003 | 1 | AUSTIN SEMI. | | Y | AS8F512K32Q1-60/883 | 669 |
| 5962-9461205HAA | G | 10/10/2003 | 1 | WHITE ELEC. | | Y | WF512K32-60G2LQ5 | 669 |
| 5962-9461205HAC | G | 10/10/2003 | 1 | AUSTIN SEMI. | | Y | AS8F512K32Q1-60/883 | 669 |
| 5962-9461205HAC | G | 10/10/2003 | 1 | WHITE ELEC. | | Y | WF512K32-60G2LQ5 | 669 |
| 5962-9461205HBA | G | 10/10/2003 | 1 | WHITE ELEC. | | Y | WF512K32-60G1TQ5 | 669 |
| 5962-9461205HBC | G | 10/10/2003 | 1 | WHITE ELEC. | | Y | WF512K32-60G1TQ5 | 669 |
| 5962-9461205HMA | G | 10/10/2003 | 1 | AEROFLEX | | Y | ACT-F512K32N-060F5 | 669 |
| 5962-9461205HMA | G | 10/10/2003 | 1 | AUSTIN SEMI. | | Y | AS8F512K32Q-60/883C | 669 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9461205HMA | G | 10/10/2003 | 1 | WHITE ELEC. | | Y | WF512K32-60G2Q5 | 669 |
| 5962-9461205HMC | G | 10/10/2003 | 1 | AEROFLEX | | Y | ACT-F512K32N-060F5 | 669 |
| 5962-9461205HMC | G | 10/10/2003 | 1 | AUSTIN SEMI. | | Y | AS8F512K32Q-60/883C | 669 |
| 5962-9461205HMC | G | 10/10/2003 | 1 | WHITE ELEC. | | Y | WF512K32-60G2Q5 | 669 |
| 5962-9461205HNA | G | 10/10/2003 | 1 | WHITE ELEC. | | Y | WF512K32F-60G4Q5 | 669 |
| 5962-9461205HNC | G | 10/10/2003 | 1 | WHITE ELEC. | | Y | WF512K32F-60G4Q5 | 669 |
| 5962-9461205HTC | G | 10/10/2003 | 1 | WHITE ELEC. | | Y | WF512K32-60G4TQ5 | 669 |
| 5962-9461205HUA | G | 10/10/2003 | 1 | AEROFLEX | | Y | ACT-F512K32N-060P7 | 669 |
| 5962-9461205HUA | G | 10/10/2003 | 1 | WHITE ELEC. | | Y | WF512K32N-60HQ5 | 669 |
| 5962-9461205HUC | G | 10/10/2003 | 1 | AEROFLEX | | Y | ACT-F512K32N-060P7 | 669 |
| 5962-9461205HUC | G | 10/10/2003 | 1 | WHITE ELEC. | | Y | WF512K32N-60HQ5 | 669 |
| 5962-9461205HXA | G | 10/10/2003 | 1 | AEROFLEX | | Y | ACT-F512K32N-060P3 | 669 |
| 5962-9461205HXC | G | 10/10/2003 | 1 | AEROFLEX | | Y | ACT-F512K32N-060P3 | 669 |
| 5962-9461205HYC | G | 10/10/2003 | 1 | AEROFLEX | | Y | ACT-F512K32N-060F5U | 669 |
| 5962-9461205HZA | G | 10/10/2003 | 1 | WHITE ELEC. | | Y | WF512K32-60G2UQ5 | 669 |
| 5962-9461205HZC | G | 10/10/2003 | 1 | WHITE ELEC. | | Y | WF512K32-60G2UQ5 | 669 |
| 5962-9461301HXA | A | 10/12/1995 | | (NONE) | | | 1024K32-150 (GEN) | 669 |
| 5962-9461301HYA | A | 10/12/1995 | | (NONE) | | | 1024K32-150 (GEN) | 669 |
| 5962-9461301HZA | A | 10/12/1995 | | (NONE) | | | 1024K32-150 (GEN) | 669 |
| 5962-9461302HXA | A | 10/12/1995 | | (NONE) | | | 1024K32-100 (GEN) | 669 |
| 5962-9461302HYA | A | 10/12/1995 | | (NONE) | | | 1024K32-100 (GEN) | 669 |
| 5962-9461302HZA | A | 10/12/1995 | | (NONE) | | | 1024K32-100 (GEN) | 669 |
| 5962-9461401H9A | E | 10/20/2003 | 1 | WHITE ELEC. | | Y | WE32K32-150G1UQ | 664 |
| 5962-9461401H9C | E | 10/20/2003 | 1 | WHITE ELEC. | | Y | WE32K32-150G1UQ | 664 |
| 5962-9461401HBA | E | 10/20/2003 | 1 | WHITE ELEC. | | Y | WE32K32-150G1TQ | 664 |
| 5962-9461401HBC | E | 10/20/2003 | 1 | WHITE ELEC. | | Y | WE32K32-150G1TQ | 664 |
| 5962-9461401HMA | E | 10/20/2003 | 1 | AUSTIN SEMI. | | Y | AS8E32K32Q-150/883C | 664 |
| 5962-9461401HMA | E | 10/20/2003 | 1 | WHITE ELEC. | | Y | WE32K32-150G2Q | 664 |
| 5962-9461401HMC | E | 10/20/2003 | 1 | AUSTIN SEMI. | | Y | AS8E32K32Q-150/883C | 664 |
| 5962-9461401HMC | E | 10/20/2003 | 1 | WHITE ELEC. | | Y | WE32K32-150G2Q | 664 |
| 5962-9461401HUA | E | 10/20/2003 | 1 | AUSTIN SEMI. | | Y | AS8E32K32P-150/883C | 664 |
| 5962-9461401HUA | E | 10/20/2003 | 1 | WHITE ELEC. | | Y | WE32K32N-150H1Q | 664 |
| 5962-9461401HUC | E | 10/20/2003 | 1 | AUSTIN SEMI. | | Y | AS8E32K32P-150/883C | 664 |
| 5962-9461401HUC | E | 10/20/2003 | 1 | WHITE ELEC. | | Y | WE32K32N-150H1Q | 664 |
| 5962-9461401HXA | E | 10/20/2003 | 1 | WHITE ELEC. | | Y | WE32K32N-150HQ | 664 |
| 5962-9461401HXC | E | 10/20/2003 | 1 | WHITE ELEC. | | Y | WE32K32N-150HQ | 664 |
| 5962-9461401HYA | E | 10/20/2003 | | (NONE) | | | 32K32-150 (GEN) | 664 |
| 5962-9461401HZA | E | 10/20/2003 | 1 | WHITE ELEC. | | Y | WE32K32-150G2UQ | 664 |
| 5962-9461401HZC | E | 10/20/2003 | 1 | WHITE ELEC. | | Y | WE32K32-150G2UQ | 664 |
| 5962-9461402H9A | E | 10/20/2003 | 1 | WHITE ELEC. | | Y | WE32K32-120G1UQ | 664 |
| 5962-9461402H9C | E | 10/20/2003 | 1 | WHITE ELEC. | | Y | WE32K32-120G1UQ | 664 |
| 5962-9461402HBA | E | 10/20/2003 | 1 | WHITE ELEC. | | Y | WE32K32-120G1TQ | 664 |
| 5962-9461402HBC | E | 10/20/2003 | 1 | WHITE ELEC. | | Y | WE32K32-120G1TQ | 664 |
| 5962-9461402HMA | E | 10/20/2003 | 1 | AUSTIN SEMI. | | Y | AS8E32K32Q-120/883C | 664 |
| 5962-9461402HMA | E | 10/20/2003 | 1 | WHITE ELEC. | | Y | WE32K32-120G2Q | 664 |
| 5962-9461402HMC | E | 10/20/2003 | 1 | AUSTIN SEMI. | | Y | AS8E32K32Q-120/883C | 664 |
| 5962-9461402HMC | E | 10/20/2003 | 1 | WHITE ELEC. | | Y | WE32K32-120G2Q | 664 |
| 5962-9461402HUA | E | 10/20/2003 | 1 | AUSTIN SEMI. | | Y | AS8E32K32P-120/883C | 664 |
| 5962-9461402HUA | E | 10/20/2003 | 1 | WHITE ELEC. | | Y | WE32K32N-120H1Q | 664 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9461402HUC | E | 10/20/2003 | 1 | AUSTIN SEMI. | | Y | AS8E32K32P-120/883C | 664 |
| 5962-9461402HUC | E | 10/20/2003 | 1 | WHITE ELEC. | | Y | WE32K32N-120H1Q | 664 |
| 5962-9461402HXA | E | 10/20/2003 | 1 | WHITE ELEC. | | Y | WE32K32N-120HQ | 664 |
| 5962-9461402HXC | E | 10/20/2003 | 1 | WHITE ELEC. | | Y | WE32K32N-120HQ | 664 |
| 5962-9461402HYA | E | 10/20/2003 | | (NONE) | | | 32K32-120 (GEN) | 664 |
| 5962-9461402HZA | E | 10/20/2003 | 1 | WHITE ELEC. | | Y | WE32K32-120G2UQ | 664 |
| 5962-9461402HZC | E | 10/20/2003 | 1 | WHITE ELEC. | | Y | WE32K32-120G2UQ | 664 |
| 5962-9461403H9A | E | 10/20/2003 | 1 | WHITE ELEC. | | Y | WE32K32-90G1UQ | 664 |
| 5962-9461403H9C | E | 10/20/2003 | 1 | WHITE ELEC. | | Y | WE32K32-90G1UQ | 664 |
| 5962-9461403HBA | E | 10/20/2003 | 1 | WHITE ELEC. | | Y | WE32K32-90G1TQ | 664 |
| 5962-9461403HBC | E | 10/20/2003 | 1 | WHITE ELEC. | | Y | WE32K32-90G1TQ | 664 |
| 5962-9461403HMA | E | 10/20/2003 | 1 | AUSTIN SEMI. | | Y | AS8E32K32Q-90/883C | 664 |
| 5962-9461403HMA | E | 10/20/2003 | 1 | WHITE ELEC. | | Y | WE32K32-90G2Q | 664 |
| 5962-9461403HMC | E | 10/20/2003 | 1 | AUSTIN SEMI. | | Y | AS8E32K32Q-90/883C | 664 |
| 5962-9461403HMC | E | 10/20/2003 | 1 | WHITE ELEC. | | Y | WE32K32-90G2Q | 664 |
| 5962-9461403HUA | E | 10/20/2003 | 1 | AUSTIN SEMI. | | Y | AS8E32K32P-90/883C | 664 |
| 5962-9461403HUA | E | 10/20/2003 | 1 | WHITE ELEC. | | Y | WE32K32N-90H1Q | 664 |
| 5962-9461403HUC | E | 10/20/2003 | 1 | AUSTIN SEMI. | | Y | AS8E32K32P-90/883C | 664 |
| 5962-9461403HUC | E | 10/20/2003 | 1 | WHITE ELEC. | | Y | WE32K32N-90H1Q | 664 |
| 5962-9461403HXA | E | 10/20/2003 | 1 | WHITE ELEC. | | Y | WE32K32-90HQ | 664 |
| 5962-9461403HXC | E | 10/20/2003 | 1 | WHITE ELEC. | | Y | WE32K32-90HQ | 664 |
| 5962-9461403HYA | E | 10/20/2003 | | (NONE) | | | 32K32-90 (GEN) | 664 |
| 5962-9461403HZA | E | 10/20/2003 | 1 | WHITE ELEC. | | Y | WE32K32-90G2UQ | 664 |
| 5962-9461403HZC | E | 10/20/2003 | 1 | WHITE ELEC. | | Y | WE32K32-90G2UQ | 664 |
| 5962-9461501Q3A | | 04/19/1994 | 3 | TI | | Y | SNJ54ABT8543FK | 399 |
| 5962-9461501QXA | | 04/19/1994 | 3 | TI | | Y | SNJ54ABT8543JT | 399 |
| 5962-9461601Q3A | | 04/26/1994 | 3 | TI | | Y | SNJ54ABT8652FK | 399 |
| 5962-9461601QXA | | 04/26/1994 | 3 | TI | | Y | SNJ54ABT8652JT | 399 |
| 5962-9461801Q2A | | 04/26/1994 | 3 | TI | | Y | SNJ54ABT623AFK | 590 |
| 5962-9461801QRA | | 04/26/1994 | 3 | TI | | Y | SNJ54ABT623AJ | 590 |
| 5962-9461801QSA | | 04/26/1994 | 3 | TI | | Y | SNJ54ABT623AW | 590 |
| 5962-9462101M2C | B | 12/18/2000 | 1 | MAXIM INTEG. | | | MAX731MLP/883B | 787 |
| 5962-9462101MPA | B | 12/18/2000 | 1 | MAXIM INTEG. | | | MAX731MJA/883B | 787 |
| 5962-9462102M2C | B | 12/18/2000 | 1 | MAXIM INTEG. | | | MAX732MLP/883B | 787 |
| 5962-9462102MPA | B | 12/18/2000 | 1 | MAXIM INTEG. | | | MAX732MJA/883B | 787 |
| 5962-9462103M2C | B | 12/18/2000 | 1 | MAXIM INTEG. | | | MAX733MLP/883B | 787 |
| 5962-9462103MPA | B | 12/18/2000 | 1 | MAXIM INTEG. | | | MAX733MJA/883B | 787 |
| 5962-9462201M2A | | 12/01/1994 | | (NONE) | | | UC1871 (GEN) | 589 |
| 5962-9462201MVA | | 12/01/1994 | | (NONE) | | | UC1871 (GEN) | 589 |
| 5962-9462301HXA | B | 02/24/2004 | 1 | ADV. ANALOG | | Y | AHF2815T/CH | 899 |
| 5962-9462301HXC | B | 02/24/2004 | 1 | ADV. ANALOG | | Y | AHF2815T/CH | 899 |
| 5962-9462301HZA | B | 02/24/2004 | 1 | ADV. ANALOG | | Y | AHF2815TF/CH | 899 |
| 5962-9462301HZC | B | 02/24/2004 | 1 | ADV. ANALOG | | Y | AHF2815TF/CH | 899 |
| 5962-9462401HXA | A | 05/29/2003 | 1 | ADV. ANALOG | | Y | ATR2805S/CH | 594 |
| 5962-9462401HZA | A | 05/29/2003 | 1 | ADV. ANALOG | | Y | ATR2805SF/CH | 594 |
| 5962-9462501HXA | A | 05/29/2003 | 1 | ADV. ANALOG | | Y | ATR2812S/CH | 594 |
| 5962-9462501HZA | A | 05/29/2003 | 1 | ADV. ANALOG | | Y | ATR2812SF/CH | 594 |
| 5962-9462601HXA | A | 06/02/2003 | 1 | ADV. ANALOG | | Y | ATR2815S/CH | 594 |
| 5962-9462601HZA | A | 06/02/2003 | 1 | ADV. ANALOG | | Y | ATR2815SF/CH | 594 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9462701HXA | A | 06/02/2003 | 1 | ADV. ANALOG | | Y | ATR2812D/CH | 594 |
| 5962-9462701HZA | A | 06/02/2003 | 1 | ADV. ANALOG | | Y | ATR2812DF/CH | 594 |
| 5962-9462801HXA | A | 06/02/2003 | 1 | ADV. ANALOG | | Y | ATR2815D/CH | 594 |
| 5962-9462801HZA | A | 06/02/2003 | 1 | ADV. ANALOG | | Y | ATR2815DF/CH | 594 |
| 5962-9462901HXA | C | 04/02/2004 | 1 | ADV. ANALOG | | Y | ASA2805S/CH | 594 |
| 5962-9462902HYA | C | 04/02/2004 | 1 | MS KENNEDY | | Y | DHC2805SH | 594 |
| 5962-9462902HYC | C | 04/02/2004 | 1 | MS KENNEDY | | Y | DHC2805SH | 594 |
| 5962-9463001HXA | A | 11/09/1998 | 1 | ADV. ANALOG | | Y | ASA2815S/CH | 594 |
| 5962-9463101HXA | C | 08/23/2004 | 1 | ADV. ANALOG | | Y | ASA2812S/CH | 594 |
| 5962-9463102HYA | C | 08/23/2004 | 1 | MS KENNEDY | | Y | DAC2812SH | 594 |
| 5962-9463102HYC | C | 08/23/2004 | 1 | MS KENNEDY | | Y | DAC2812SH | 594 |
| 5962-9463201M2C | A | 01/29/2004 | 1 | MAXIM INTEG. | | | MAX660MLP/883B | 899 |
| 5962-9463201MPA | A | 01/29/2004 | 1 | MAXIM INTEG. | | | MAX660MJA/883B | 899 |
| 5962-9463301MLA | A | 01/11/2002 | 2 | ANALOG (2) | | Y | AD660SQ/883B | 591 |
| 5962-9463401MXC | | 06/23/1995 | | (NONE) | 10/31/1996 | | EPF8820 (GEN) | 431 |
| 5962-9463401MYA | | 06/23/1995 | | (NONE) | 10/31/1996 | | EPF8820 (GEN) | 431 |
| 5962-9463601MPA | | 05/31/1994 | | (NONE) | 04/14/2001 | | AD780S (GEN) | 785 |
| 5962-9463701MXC | B | 05/25/2004 | 1 | ANALOG (4) | | Y | AD9020SZ/883 | 592 |
| 5962-9463701MYA | B | 05/25/2004 | | (NONE) | | | 9020 (GEN) | 592 |
| 5962-9463702MXC | B | 05/25/2004 | 1 | ANALOG (4) | | Y | AD9020TZ/883 | 592 |
| 5962-9463702MYA | B | 05/25/2004 | | (NONE) | | | 9020 (GEN) | 592 |
| 5962-9464001MPA | | 08/12/1994 | | (NONE) | | | HV400 (GEN) | 519 |
| 5962-9464101QRA | | 09/07/1994 | | (NONE) | | | 145146 (GEN) | 803 |
| 5962-9464201QYC | | 06/24/1994 | | (NONE) | | | 68902A (GEN) | 429 |
| 5962-9464201QZA | | 06/24/1994 | | (NONE) | | | 68902A (GEN) | 429 |
| 5962-9464201QZC | | 06/24/1994 | | (NONE) | | | 68902A (GEN) | 429 |
| 5962-9464601HXC | | 07/08/1994 | | (NONE) | | | HDSR2006-34V/S/2 | 594 |
| 5962-9464602HXC | | 07/08/1994 | | (NONE) | | | HDSR2006-34V/R/2 | 594 |
| 5962-9464603HXC | | 07/08/1994 | | (NONE) | | | HDSR2006-34H/2 | 594 |
| 5962-9464604HXC | | 07/08/1994 | | (NONE) | | | HDSR2006-34S/2 | 594 |
| 5962-9464605HXC | | 07/08/1994 | | (NONE) | | | HDSR2056-34V/S/2 | 594 |
| 5962-9464606HXC | | 07/08/1994 | | (NONE) | | | HDSR2056-34V/R/2 | 594 |
| 5962-9464607HXC | | 07/08/1994 | | (NONE) | | | HDSR2056-34H/2 | 594 |
| 5962-9464608HXC | | 07/08/1994 | | (NONE) | | | HDSR2056-34S/2 | 594 |
| 5962-9464901HXA | A | 02/03/1999 | 1 | ADV. ANALOG | | Y | ASA2815D/CH | 594 |
| 5962-9465501HXA | D | 06/06/2001 | 1 | INTERPOINT | | Y | MHD2805S/883 | 594 |
| 5962-9465501HXC | D | 06/06/2001 | 1 | INTERPOINT | | Y | MHD2805S/883 | 594 |
| 5962-9465501HZA | D | 06/06/2001 | 1 | INTERPOINT | | Y | MHD2805SF/883 | 594 |
| 5962-9465501HZC | D | 06/06/2001 | 1 | INTERPOINT | | Y | MHD2805SF/883 | 594 |
| 5962-9465601HXA | D | 07/10/2003 | 1 | INTERPOINT | | Y | MHD2812S/883 | 594 |
| 5962-9465601HXC | D | 07/10/2003 | 1 | INTERPOINT | | Y | MHD2812S/883 | 594 |
| 5962-9465601HZA | D | 07/10/2003 | 1 | INTERPOINT | | Y | MHD2812SF/883 | 594 |
| 5962-9465601HZC | D | 07/10/2003 | 1 | INTERPOINT | | Y | MHD2812SF/883 | 594 |
| 5962-9465701HXA | D | 07/10/2003 | 1 | INTERPOINT | | Y | MHD2815S/883 | 594 |
| 5962-9465701HXC | D | 07/10/2003 | 1 | INTERPOINT | | Y | MHD2815S/883 | 594 |
| 5962-9465701HZA | D | 07/10/2003 | 1 | INTERPOINT | | Y | MHD2815SF/883 | 594 |
| 5962-9465701HZC | D | 07/10/2003 | 1 | INTERPOINT | | Y | MHD2815SF/883 | 594 |
| 5962-9465801HXA | D | 07/10/2003 | 1 | INTERPOINT | | Y | MHD2818S/883 | 594 |
| 5962-9465801HXC | D | 07/10/2003 | 1 | INTERPOINT | | Y | MHD2818S/883 | 594 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9465801HZA | D | 07/10/2003 | 1 | INTERPOINT | | Y | MHD2818SF/883 | 594 |
| 5962-9465801HZC | D | 07/10/2003 | 1 | INTERPOINT | | Y | MHD2818SF/883 | 594 |
| 5962-9465901HXA | C | 07/16/2003 | 1 | INTERPOINT | | Y | MHD2805D/883 | 594 |
| 5962-9465901HXC | C | 07/16/2003 | 1 | INTERPOINT | | Y | MHD2805D/883 | 594 |
| 5962-9465901HZA | C | 07/16/2003 | 1 | INTERPOINT | | Y | MHD2805DF/883 | 594 |
| 5962-9465901HZC | C | 07/16/2003 | 1 | INTERPOINT | | Y | MHD2805DF/883 | 594 |
| 5962-9466001HXA | C | 07/16/2003 | 1 | INTERPOINT | | Y | MHD2812D/883 | 594 |
| 5962-9466001HXC | C | 07/16/2003 | 1 | INTERPOINT | | Y | MHD2812D/883 | 594 |
| 5962-9466001HZA | C | 07/16/2003 | 1 | INTERPOINT | | Y | MHD2812DF/883 | 594 |
| 5962-9466001HZC | C | 07/16/2003 | 1 | INTERPOINT | | Y | MHD2812DF/883 | 594 |
| 5962-9466101HXA | C | 07/16/2003 | 1 | INTERPOINT | | Y | MHD2815D/883 | 594 |
| 5962-9466101HXC | C | 07/16/2003 | 1 | INTERPOINT | | Y | MHD2815D/883 | 594 |
| 5962-9466101HZA | C | 07/16/2003 | 1 | INTERPOINT | | Y | MHD2815DF/883 | 594 |
| 5962-9466101HZC | C | 07/16/2003 | 1 | INTERPOINT | | Y | MHD2815DF/883 | 594 |
| 5962-9466201QJA | | 09/05/1995 | | (NONE) | | | DAC1054 (GEN) | 591 |
| 5962-9466301QXA | G | 10/28/2003 | | (NONE) | | | 69151LX15 (GEN) | 599 |
| 5962-9466301QYA | G | 10/28/2003 | | (NONE) | | | 69151LX15 (GEN) | 599 |
| 5962-9466302QXA | G | 10/28/2003 | | (NONE) | | | 69151DX (GEN) | 599 |
| 5962-9466302QYA | G | 10/28/2003 | | (NONE) | | | 69151DX (GEN) | 599 |
| 5962-9466303QXA | G | 10/28/2003 | | (NONE) | | | 69151LX12 (GEN) | 599 |
| 5962-9466303QYA | G | 10/28/2003 | | (NONE) | | | 69151LX12 (GEN) | 599 |
| 5962-9466304QXA | G | 10/28/2003 | | (NONE) | | | 69151LXE15 (GEN) | 599 |
| 5962R9466304QXA | G | 10/28/2003 | | (NONE) | | | 69151LXE15 (GEN) | 599 |
| 5962R9466304VXA | G | 10/28/2003 | | (NONE) | | | 69151LXE15 (GEN) | 599 |
| 5962-9466304QYA | G | 10/28/2003 | | (NONE) | | | 69151LXE15 (GEN) | 599 |
| 5962R9466304QYA | G | 10/28/2003 | | (NONE) | | | 69151LXE15 (GEN) | 599 |
| 5962R9466304VYA | G | 10/28/2003 | | (NONE) | | | 69151LXE15 (GEN) | 599 |
| 5962-9466305QXA | G | 10/28/2003 | | (NONE) | | | 69151DXE (GEN) | 599 |
| 5962H9466305QXA | G | 10/28/2003 | | (NONE) | | | 69151DXE (GEN) | 599 |
| 5962H9466305VXA | G | 10/28/2003 | | (NONE) | | | 69151DXE (GEN) | 599 |
| 5962-9466305QYA | G | 10/28/2003 | | (NONE) | | | 69151DXE (GEN) | 599 |
| 5962H9466305QYA | G | 10/28/2003 | | (NONE) | | | 69151DXE (GEN) | 599 |
| 5962H9466305VYA | G | 10/28/2003 | | (NONE) | | | 69151DXE (GEN) | 599 |
| 5962-9466306QXA | G | 10/28/2003 | | (NONE) | | | 69151LX12 (GEN) | 599 |
| 5962-9466306QYA | G | 10/28/2003 | | (NONE) | | | 69151LX12 (GEN) | 599 |
| 5962-9466307QXA | G | 10/28/2003 | 1 | UTMC | | Y | UT69151LXE15/GQA | 599 |
| 5962-9466307QXC | G | 10/28/2003 | 1 | UTMC | | Y | UT69151LXE15/GQC | 599 |
| 5962-9466307QYA | G | 10/28/2003 | 1 | UTMC | | Y | UT69151LXE15/WQA | 599 |
| 5962-9466307QYC | G | 10/28/2003 | 1 | UTMC | | Y | UT69151LXE15/WQC | 599 |
| 5962-9466308QXA | G | 10/28/2003 | 1 | UTMC | | Y | UT69151DXE/GQA | 599 |
| 5962-9466308QXC | G | 10/28/2003 | 1 | UTMC | | Y | UT69151DXE/GQC | 599 |
| 5962-9466308QYA | G | 10/28/2003 | 1 | UTMC | | Y | UT69151DXE/WQA | 599 |
| 5962-9466308QYC | G | 10/28/2003 | 1 | UTMC | | Y | UT69151DXE/WQC | 599 |
| 5962-9466309QXA | G | 10/28/2003 | 1 | UTMC | | Y | UT69151LXE12/GQA | 599 |
| 5962-9466309QXC | G | 10/28/2003 | 1 | UTMC | | Y | UT69151LXE12/GQC | 599 |
| 5962-9466309QYA | G | 10/28/2003 | 1 | UTMC | | Y | UT69151LXE12/WQA | 599 |
| 5962-9466309QYC | G | 10/28/2003 | 1 | UTMC | | Y | UT69151LXE12/WQC | 599 |
| 5962R9466310QYA | G | 10/28/2003 | 1 | UTMC | | Y | UT69151LXE15/WQAR | 599 |
| 5962R9466310QYC | G | 10/28/2003 | 1 | UTMC | | Y | UT69151LXE15/WQCR | 599 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962R9466310VYA | G | 10/28/2003 | 1 | UTMC | | Y | UT69151LXE15/WVAR | 599 |
| 5962R9466310VYC | G | 10/28/2003 | 1 | UTMC | | Y | UT69151LXE15/WVCR | 599 |
| 5962F9466311QYA | G | 10/28/2003 | 1 | UTMC | | Y | UT69151DXE/WQAF | 599 |
| 5962F9466311QYC | G | 10/28/2003 | 1 | UTMC | | Y | UT69151DXE/WQCF | 599 |
| 5962F9466311VYA | G | 10/28/2003 | 1 | UTMC | | Y | UT69151DXE/WVAF | 599 |
| 5962F9466311VYC | G | 10/28/2003 | 1 | UTMC | | Y | UT69151DXE/WVCF | 599 |
| 5962R9466311QYA | G | 10/28/2003 | 1 | UTMC | | Y | UT69151DXE/WQAR | 599 |
| 5962R9466311QYC | G | 10/28/2003 | 1 | UTMC | | Y | UT69151DXE/WQCR | 599 |
| 5962R9466311VYA | G | 10/28/2003 | 1 | UTMC | | Y | UT69151DXE/WVAR | 599 |
| 5962R9466311VYC | G | 10/28/2003 | 1 | UTMC | | Y | UT69151DXE/WVCR | 599 |
| 5962-9466401MEA | | 11/10/1994 | 1 | TI | | Y | CD4046BF3A | 803 |
| 5962H9466701QYC | | 06/12/1995 | | (NONE) | | | 34096956-005 (GEN) | 403 |
| 5962H9466701VYC | | 06/12/1995 | | (NONE) | | | 34096956-005 (GEN) | 403 |
| 5962H9466702QYC | | 06/12/1995 | | (NONE) | | | 34096956-002 (GEN) | 403 |
| 5962H9466703QYC | | 06/12/1995 | | (NONE) | | | 34096956-003 (GEN) | 403 |
| 5962H9466704QYC | | 06/12/1995 | | (NONE) | | | 34096956-004 (GEN) | 403 |
| 5962-9466801MXC | A | 03/21/2002 | 2 | LATTICE SEMI | | | PLSI1032-60LG/883 | 431 |
| 5962-9466901QXA | M | 02/15/2002 | | (NONE) | 05/01/1998 | | 320C40-33 (GEN) | 432 |
| 5962-9466901QYC | M | 02/15/2002 | | (NONE) | 05/01/1998 | | 320C40-33 (GEN) | 432 |
| 5962-9466902Q9A | M | 02/15/2002 | | (NONE) | | | 320C40-40 (GEN) | 432 |
| 5962-9466902Q9B | M | 02/15/2002 | | (NONE) | | | 320C40-40 (GEN) | 432 |
| 5962-9466902Q9C | M | 02/15/2002 | | (NONE) | | | 320C40-40 (GEN) | 432 |
| 5962-9466902Q9D | M | 02/15/2002 | 2 | TI | | Y | SMJ320C40KGDM40D | 432 |
| 5962-9466902QUC | M | 02/15/2002 | | (NONE) | 10/31/2002 | | 320C40-40 (GEN) | 432 |
| 5962-9466902QXA | M | 02/15/2002 | 2 | TI | | Y | SMJ320C40GFM40 | 432 |
| 5962-9466902QXC | M | 02/15/2002 | 2 | TI | | Y | SMJ320C40GFM40 | 432 |
| 5962-9466902QYC | M | 02/15/2002 | 2 | TI | | Y | SMJ320C40HFHM40 | 432 |
| 5962-9466902QZC | M | 02/15/2002 | | (NONE) | | | 320C40-40 (GEN) | 432 |
| 5962-9466903Q9A | M | 02/15/2002 | | (NONE) | | | 320C40-50 (GEN) | 432 |
| 5962-9466903Q9B | M | 02/15/2002 | | (NONE) | | | 320C40-50 (GEN) | 432 |
| 5962-9466903Q9C | M | 02/15/2002 | | (NONE) | | | 320C40-50 (GEN) | 432 |
| 5962-9466903Q9D | M | 02/15/2002 | 2 | TI | | Y | SMJ320C40KGDM50D | 432 |
| 5962-9466903QUC | M | 02/15/2002 | | (NONE) | 10/31/2002 | | 320C40-50 (GEN) | 432 |
| 5962-9466903QXA | M | 02/15/2002 | 2 | TI | | Y | SMJ320C40GFM50 | 432 |
| 5962-9466903QXC | M | 02/15/2002 | 2 | TI | | Y | SMJ320C40GFM50 | 432 |
| 5962-9466903QYC | M | 02/15/2002 | 2 | TI | | Y | SMJ320C40HFHM50 | 432 |
| 5962-9466903QZC | M | 02/15/2002 | | (NONE) | | | 320C40-50 (GEN) | 432 |
| 5962-9466904Q9A | M | 02/15/2002 | | (NONE) | | | 320C40-60 (GEN) | 432 |
| 5962-9466904QUC | M | 02/15/2002 | | (NONE) | 10/31/2002 | | 320C40-60 (GEN) | 432 |
| 5962-9466904QXA | M | 02/15/2002 | 2 | TI | | Y | SMJ320C40GFS60 | 432 |
| 5962-9466904QYC | M | 02/15/2002 | 2 | TI | | Y | SMJ320C40HFHS60 | 432 |
| 5962-9466904QZC | M | 02/15/2002 | | (NONE) | | | 320C40-60 (GEN) | 432 |
| 5962-9467001MJA | | 09/08/1995 | | (NONE) | | | 5140 (GEN) | 591 |
| 5962-9467101QXA | | 08/18/1994 | 2 | TI | | Y | SNJ54ABT16601WD | 590 |
| 5962-9467201QXA | | 06/08/1994 | 3 | TI | | Y | SNJ54ABT18502HV | 399 |
| 5962-9467301Q2A | | 06/02/1994 | 2 | TI | | Y | SNJ54ABT2244FK | 529 |
| 5962-9467301QRA | | 06/02/1994 | 2 | TI | | Y | SNJ54ABT2244J | 529 |
| 5962-9467301QSA | | 06/02/1994 | 2 | TI | | Y | SNJ54ABT2244W | 529 |
| 5962-9467601MPA | E | 04/07/2004 | 1 | INTERSIL | 10/03/2004 | Y | HFA1100MJ/883 | 752 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962F9467602V9A | E | 04/07/2004 | 1 | INTERSIL | | Y | HS0-1100RH-Q | 752 |
| 5962F9467602VPC | E | 04/07/2004 | 1 | INTERSIL | | Y | HS7B-1100RH-Q | 752 |
| 5962-9467701M2A | A | 02/25/2002 | 1 | INTERSIL | | Y | HFA1130ML/883 | 752 |
| 5962-9467701MPA | A | 02/25/2002 | | (NONE) | 12/24/2000 | | HFA1130 (GEN) | 752 |
| 5962-9467801MXA | | 05/25/1994 | | (NONE) | | | HI-5700S (GEN) | 592 |
| 5962-9467901MPA | | 07/12/1994 | | (NONE) | | | HA7-2840 (GEN) | 755 |
| 5962-9468001M2A | B | 09/02/1998 | | (NONE) | 04/16/2002 | | OP27B (GEN) | 702 |
| 5962R9468002V2A | B | 09/02/1998 | 3 | ANALOG (5) | | Y | OP27ARC/QMLR | 702 |
| 5962R9468002VGA | B | 09/02/1998 | 3 | ANALOG (5) | | Y | OP27AJ/QMLR | 702 |
| 5962R9468002VHA | B | 09/02/1998 | 3 | ANALOG (5) | | Y | OP27AL/QMLR | 702 |
| 5962R9468002VPA | B | 09/02/1998 | 3 | ANALOG (5) | | Y | OP27AZ/QMLR | 702 |
| 5962-9468101M2C | A | 02/02/2001 | | (NONE) | | | 674 (GEN) | 785 |
| 5962-9468101MGC | A | 02/02/2001 | | (NONE) | | | 674 (GEN) | 785 |
| 5962-9468101MPA | A | 02/02/2001 | | (NONE) | | | 674 (GEN) | 785 |
| 5962-9468102M2C | A | 02/02/2001 | 1 | MAXIM INTEG. | | | MAX674MLP/883B | 785 |
| 5962-9468102MGC | A | 02/02/2001 | 1 | MAXIM INTEG. | | | MAX674MTV/883B | 785 |
| 5962-9468102MPA | A | 02/02/2001 | 1 | MAXIM INTEG. | | | MAX674MJA/883B | 785 |
| 5962-9468201M2A | | 07/18/1994 | | (NONE) | | | 1113 (GEN) | 751 |
| 5962-9468201MPA | | 07/18/1994 | | (NONE) | | | 1113 (GEN) | 751 |
| 5962-9468301MPA | A | 05/13/1998 | | (NONE) | | | 1110 (GEN) | 738 |
| 5962-9468401QXA | | 03/14/1996 | | (NONE) | | | 7C371-66 (GEN) | 431 |
| 5962-9468402QXA | | 03/14/1996 | | (NONE) | | | 7C371-83 (GEN) | 431 |
| 5962-9468501MPA | | 07/08/1994 | | (NONE) | | | 1120 (GEN) | 752 |
| 5962-9468601MXA | A | 12/06/2001 | 1 | ANALOG (2) | | Y | AD871SD/883B | 592 |
| 5962-9468602MYA | A | 12/06/2001 | 1 | ANALOG (2) | | Y | AD871SE/883B | 592 |
| 5962-9468801QXA | A | 10/04/1996 | | (NONE) | | | 7C372-66 (GEN) | 431 |
| 5962-9468802QXA | A | 10/04/1996 | | (NONE) | | | 7C372-83 (GEN) | 431 |
| 5962-9469001MXA | | 02/08/1995 | | (NONE) | | | 5336-T (GEN) | 592 |
| 5962-9469101M3A | | 06/28/1994 | | (NONE) | | | 54ABT821 (GEN) | 159 |
| 5962-9469101Q3A | | 06/28/1994 | 2 | TI | | Y | SNJ54ABT821FK | 159 |
| 5962-9469101MKA | | 06/28/1994 | | (NONE) | | | 54ABT821 (GEN) | 159 |
| 5962-9469101QKA | | 06/28/1994 | 2 | TI | | Y | SNJ54ABT821W | 159 |
| 5962-9469101MLA | | 06/28/1994 | | (NONE) | | | 54ABT821 (GEN) | 159 |
| 5962-9469101QLA | | 06/28/1994 | 2 | TI | | Y | SNJ54ABT821JT | 159 |
| 5962-9469201Q2A | B | 02/01/2001 | 3 | TI | | Y | TLC2262MFKB | 710 |
| 5962-9469201QHA | B | 02/01/2001 | 3 | TI | | Y | TLC2262MUB | 710 |
| 5962-9469201QPA | B | 02/01/2001 | 3 | TI | | Y | TLC2262MJGB | 710 |
| 5962-9469202Q2A | B | 02/01/2001 | 3 | TI | | Y | TLC2264MFKB | 713 |
| 5962-9469202QCA | B | 02/01/2001 | 3 | TI | | Y | TLC2264MJB | 713 |
| 5962-9469202QDA | B | 02/01/2001 | 3 | TI | | Y | TLC2264MWB | 713 |
| 5962-9469203Q2A | B | 02/01/2001 | 3 | TI | | Y | TLC2262AMFKB | 710 |
| 5962-9469203QHA | B | 02/01/2001 | 3 | TI | | Y | TLC2262AMUB | 710 |
| 5962-9469203QPA | B | 02/01/2001 | 3 | TI | | Y | TLC2262AMJGB | 710 |
| 5962-9469204Q2A | B | 02/01/2001 | 3 | TI | | Y | TLC2264AMFKB | 713 |
| 5962-9469204QCA | B | 02/01/2001 | 3 | TI | | Y | TLC2264AMJB | 713 |
| 5962-9469204QDA | B | 02/01/2001 | 3 | TI | | Y | TLC2264AMWB | 713 |
| 5962-9469301Q2A | | 06/16/1994 | | (NONE) | | | TLC5602 (GEN) | 591 |
| 5962-9469301QRA | | 06/16/1994 | | (NONE) | 05/01/1998 | | TLC5602 (GEN) | 591 |
| 5962-9469401MPA | B | 03/04/2002 | 1 | INTERSIL | 07/02/2004 | Y | HA7-2842/883 | 755 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9469501MXA | A | 02/20/2002 | 1 | MINCO | | Y | MTL1185MK/883 | 783 |
| 5962-9469501MXC | A | 02/20/2002 | 1 | MINCO | | Y | MTL1185MK/883 | 783 |
| 5962-9469601MFA | A | 07/13/1994 | 2 | NATIONAL | | Y | 100315FMQB | 399 |
| 5962-9469601VFA | A | 07/13/1994 | 2 | NATIONAL | | Y | 100315W-QMLV | 399 |
| 5962-9469701Q2A | C | 12/18/1998 | 3 | TI | | Y | SNJ54ABT2240AFK | 529 |
| 5962-9469701QRA | C | 12/18/1998 | 3 | TI | | Y | SNJ54ABT2240AJ | 529 |
| 5962-9469701QSA | C | 12/18/1998 | 3 | TI | | Y | SNJ54ABT2240AW | 529 |
| 5962-9469801QXA | | 02/09/1996 | 2 | TI | | Y | SNJ54ABT18646HV | 590 |
| 5962-9470301MXA | B | 06/27/2002 | 1 | ANALOG (4) | | Y | AD9058ATD/883B | 592 |
| 5962-9470301MYA | B | 06/27/2002 | 1 | ANALOG (4) | | Y | AD9058ATJ/883B | 592 |
| 5962-9470401QXA | B | 05/18/2001 | 2 | TI | | Y | SNJ54ABT7819GB | 670 |
| 5962-9470701MXA | A | 06/05/2001 | | (NONE) | 10/29/2001 | | 72231L50 (GEN) | 670 |
| 5962-9470702MXA | A | 06/05/2001 | | (NONE) | 10/29/2001 | | 72231L35 (GEN) | 670 |
| 5962-9470703MXA | A | 06/05/2001 | | (NONE) | 10/29/2001 | | 72231L25 (GEN) | 670 |
| 5962-9470801MPA | A | 02/25/2002 | 1 | NATIONAL | | Y | CLC428AJ-QML | 710 |
| 5962-9470901MPA | | 09/13/1994 | | (NONE) | 03/30/2001 | | LTC1041 (GEN) | 839 |
| 5962-9471001MXA | | 11/01/1994 | | (NONE) | | | 26C94 (GEN) | 590 |
| 5962-9471101NXD | A | 03/21/1996 | | (NONE) | | | LM139A (GEN) | 776 |
| 5962-9471102NXD | A | 03/21/1996 | | (NONE) | | | LM139A (GEN) | 776 |
| 5962-9471201MXC | B | 10/04/1996 | | (NONE) | 07/01/2000 | | 4003A-10 (GEN) | 431 |
| 5962-9471201MYC | B | 10/04/1996 | | (NONE) | 07/01/2000 | | 4003A-10 (GEN) | 431 |
| 5962-9471201MZC | B | 10/04/1996 | | (NONE) | 07/01/2000 | | 4003A-10 (GEN) | 431 |
| 5962-9471202MXC | B | 10/04/1996 | | (NONE) | 07/01/2000 | | 4003A-6 (GEN) | 431 |
| 5962-9471202MYC | B | 10/04/1996 | | (NONE) | 07/01/2000 | | 4003A-6 (GEN) | 431 |
| 5962-9471202MZC | B | 10/04/1996 | | (NONE) | 07/01/2000 | | 4003A-6 (GEN) | 431 |
| 5962-9471301QXC | | 03/14/1996 | | (NONE) | | | 7C374-66 (GEN) | 431 |
| 5962-9471301QYA | | 03/14/1996 | | (NONE) | | | 7C374-66 (GEN) | 431 |
| 5962-9471302QXC | | 03/14/1996 | | (NONE) | | | 7C374-83 (GEN) | 431 |
| 5962-9471302QYA | | 03/14/1996 | | (NONE) | | | 7C374-83 (GEN) | 431 |
| 5962-9471601H4C | F | 11/10/2003 | 1 | WHITE ELEC. | | Y | WF128K32-150G4Q5 | 669 |
| 5962-9471601H5A | F | 11/10/2003 | 1 | WHITE ELEC. | | Y | WF128K32A-150H1Q5 | 669 |
| 5962-9471601H5C | F | 11/10/2003 | 1 | WHITE ELEC. | | Y | WF128K32A-150H1Q5 | 669 |
| 5962-9471601H6A | F | 11/10/2003 | 1 | WHITE ELEC. | | Y | WF128K32-150H1Q5 | 669 |
| 5962-9471601H6C | F | 11/10/2003 | 1 | WHITE ELEC. | | Y | WF128K32-150H1Q5 | 669 |
| 5962-9471601H7A | F | 11/10/2003 | 1 | WHITE ELEC. | | Y | WF128K32NA-150H1Q | 669 |
| 5962-9471601H7C | F | 11/10/2003 | 1 | WHITE ELEC. | | Y | WF128K32NA-150H1Q | 669 |
| 5962-9471601H8A | F | 11/10/2003 | 1 | AEROFLEX | | Y | ACT-F128K32N-150P7 | 669 |
| 5962-9471601H8A | F | 11/10/2003 | 1 | WHITE ELEC. | | Y | WF128K32N-150H1Q5 | 669 |
| 5962-9471601H8C | F | 11/10/2003 | 1 | AEROFLEX | | Y | ACT-F128K32N-150P7 | 669 |
| 5962-9471601H8C | F | 11/10/2003 | 1 | WHITE ELEC. | | Y | WF128K32N-150H1Q5 | 669 |
| 5962-9471601H9A | F | 11/10/2003 | 1 | WHITE ELEC. | | Y | WF128K32-150G1UQ5 | 669 |
| 5962-9471601H9C | F | 11/10/2003 | 1 | WHITE ELEC. | | Y | WF128K32-150G1UQ5 | 669 |
| 5962-9471601HAA | F | 11/10/2003 | 1 | AUSTIN SEMI. | | Y | AS8F128K32Q1-150/Q | 669 |
| 5962-9471601HAA | F | 11/10/2003 | 1 | WHITE ELEC. | | Y | WF128K32-150G2LQ5 | 669 |
| 5962-9471601HAC | F | 11/10/2003 | 1 | AUSTIN SEMI. | | Y | AS8F128K32Q1-150/Q | 669 |
| 5962-9471601HAC | F | 11/10/2003 | 1 | WHITE ELEC. | | Y | WF128K32-150G2LQ5 | 669 |
| 5962-9471601HBA | F | 11/10/2003 | 1 | WHITE ELEC. | | Y | WF128K32-150G1TQ5 | 669 |
| 5962-9471601HBC | F | 11/10/2003 | 1 | WHITE ELEC. | | Y | WF128K32-150G1TQ5 | 669 |
| 5962-9471601HMA | F | 11/10/2003 | 1 | AEROFLEX | | Y | ACT-F128K32N-150F5 | 669 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9471601HMA | F | 11/10/2003 | 1 | AUSTIN SEMI. | | Y | AS8F128K32Q-150/Q | 669 |
| 5962-9471601HMA | F | 11/10/2003 | 1 | WHITE ELEC. | | Y | WF128K32-150G2Q5 | 669 |
| 5962-9471601HMC | F | 11/10/2003 | 1 | AEROFLEX | | Y | ACT-F128K32N-150F5 | 669 |
| 5962-9471601HMC | F | 11/10/2003 | 1 | AUSTIN SEMI. | | Y | AS8F128K32Q-150/Q | 669 |
| 5962-9471601HMC | F | 11/10/2003 | 1 | WHITE ELEC. | | Y | WF128K32-150G2Q5 | 669 |
| 5962-9471601HNA | F | 11/10/2003 | 1 | AEROFLEX | | Y | ACT-F128K32N-150F5 | 669 |
| 5962-9471601HNA | F | 11/10/2003 | 1 | AUSTIN SEMI. | | Y | AS8F128K32Q-150/Q | 669 |
| 5962-9471601HNA | F | 11/10/2003 | 1 | WHITE ELEC. | | Y | WF128K32-150G2UQ5 | 669 |
| 5962-9471601HNC | F | 11/10/2003 | 1 | AEROFLEX | | Y | ACT-F128K32N-150F5 | 669 |
| 5962-9471601HNC | F | 11/10/2003 | 1 | AUSTIN SEMI. | | Y | AS8F128K32Q-150/Q | 669 |
| 5962-9471601HNC | F | 11/10/2003 | 1 | WHITE ELEC. | | Y | WF128K32-150G2UQ5 | 669 |
| 5962-9471601HSA | F | 11/10/2003 | 1 | WHITE ELEC. | | Y | WF128K32A-150HQ5 | 669 |
| 5962-9471601HSC | F | 11/10/2003 | 1 | WHITE ELEC. | | Y | WF128K32A-150HQ5 | 669 |
| 5962-9471601HTA | F | 11/10/2003 | 1 | WHITE ELEC. | | Y | WF128K32A-150HSQ5 | 669 |
| 5962-9471601HTC | F | 11/10/2003 | 1 | WHITE ELEC. | | Y | WF128K32A-150HSQ5 | 669 |
| 5962-9471601HUA | F | 11/10/2003 | 1 | WHITE ELEC. | | Y | WF128K32-150HQ5 | 669 |
| 5962-9471601HUC | F | 11/10/2003 | 1 | WHITE ELEC. | | Y | WF128K32-150HQ5 | 669 |
| 5962-9471601HVA | F | 11/10/2003 | 1 | WHITE ELEC. | | Y | WF128K32-150HSQ5 | 669 |
| 5962-9471601HVC | F | 11/10/2003 | 1 | WHITE ELEC. | | Y | WF128K32-150HSQ5 | 669 |
| 5962-9471601HWA | F | 11/10/2003 | 1 | WHITE ELEC. | | Y | WF128K32NA-150HQ5 | 669 |
| 5962-9471601HWC | F | 11/10/2003 | 1 | WHITE ELEC. | | Y | WF128K32NA-150HQ5 | 669 |
| 5962-9471601HXA | F | 11/10/2003 | 1 | WHITE ELEC. | | Y | WF128K32NA-150HSQ | 669 |
| 5962-9471601HXC | F | 11/10/2003 | 1 | WHITE ELEC. | | Y | WF128K32NA-150HSQ | 669 |
| 5962-9471601HYA | F | 11/10/2003 | 1 | WHITE ELEC. | | Y | WF128K32N-150HQ5 | 669 |
| 5962-9471601HYC | F | 11/10/2003 | 1 | WHITE ELEC. | | Y | WF128K32N-150HQ5 | 669 |
| 5962-9471601HZA | F | 11/10/2003 | 1 | AEROFLEX | | Y | ACT-F128K32N-150P3 | 669 |
| 5962-9471601HZA | F | 11/10/2003 | 1 | WHITE ELEC. | | Y | WF128K32N-150HSQ5 | 669 |
| 5962-9471601HZC | F | 11/10/2003 | 1 | AEROFLEX | | Y | ACT-F128K32N-150P3 | 669 |
| 5962-9471601HZC | F | 11/10/2003 | 1 | WHITE ELEC. | | Y | WF128K32N-150HSQ5 | 669 |
| 5962-9471602H4C | F | 11/10/2003 | 1 | WHITE ELEC. | | Y | WF128K32-120G4Q5 | 669 |
| 5962-9471602H5A | F | 11/10/2003 | 1 | WHITE ELEC. | | Y | WF128K32A-120H1Q5 | 669 |
| 5962-9471602H5C | F | 11/10/2003 | 1 | WHITE ELEC. | | Y | WF128K32A-120H1Q5 | 669 |
| 5962-9471602H6A | F | 11/10/2003 | 1 | WHITE ELEC. | | Y | WF128K32-120H1Q5 | 669 |
| 5962-9471602H6C | F | 11/10/2003 | 1 | WHITE ELEC. | | Y | WF128K32-120H1Q5 | 669 |
| 5962-9471602H7A | F | 11/10/2003 | 1 | WHITE ELEC. | | Y | WF128K32NA-120H1Q | 669 |
| 5962-9471602H7C | F | 11/10/2003 | 1 | WHITE ELEC. | | Y | WF128K32NA-120H1Q | 669 |
| 5962-9471602H8A | F | 11/10/2003 | 1 | AEROFLEX | | Y | ACT-F128K32N-120P7 | 669 |
| 5962-9471602H8A | F | 11/10/2003 | 1 | WHITE ELEC. | | Y | WF128K32N-120H1Q5 | 669 |
| 5962-9471602H8C | F | 11/10/2003 | 1 | AEROFLEX | | Y | ACT-F128K32N-120P7 | 669 |
| 5962-9471602H8C | F | 11/10/2003 | 1 | WHITE ELEC. | | Y | WF128K32N-120H1Q5 | 669 |
| 5962-9471602H9A | F | 11/10/2003 | 1 | WHITE ELEC. | | Y | WF128K32-120G1UQ5 | 669 |
| 5962-9471602H9C | F | 11/10/2003 | 1 | WHITE ELEC. | | Y | WF128K32-120G1UQ5 | 669 |
| 5962-9471602HAA | F | 11/10/2003 | 1 | AUSTIN SEMI. | | Y | AS8F128K32Q1-120/Q | 669 |
| 5962-9471602HAA | F | 11/10/2003 | 1 | WHITE ELEC. | | Y | WF128K32-120G2LQ5 | 669 |
| 5962-9471602HAC | F | 11/10/2003 | 1 | AUSTIN SEMI. | | Y | AS8F128K32Q1-120/Q | 669 |
| 5962-9471602HAC | F | 11/10/2003 | 1 | WHITE ELEC. | | Y | WF128K32-120G2LQ5 | 669 |
| 5962-9471602HBA | F | 11/10/2003 | 1 | WHITE ELEC. | | Y | WF128K32-120G1TQ5 | 669 |
| 5962-9471602HBC | F | 11/10/2003 | 1 | WHITE ELEC. | | Y | WF128K32-120G1TQ5 | 669 |
| 5962-9471602HMA | F | 11/10/2003 | 1 | AEROFLEX | | Y | ACT-F128K32N-120F5 | 669 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9471602HMA | F | 11/10/2003 | 1 | AUSTIN SEMI. | | Y | AS8F128K32Q-120/Q | 669 |
| 5962-9471602HMA | F | 11/10/2003 | 1 | WHITE ELEC. | | Y | WF128K32-120G2Q5 | 669 |
| 5962-9471602HMC | F | 11/10/2003 | 1 | AEROFLEX | | Y | ACT-F128K32N-120F5 | 669 |
| 5962-9471602HMC | F | 11/10/2003 | 1 | AUSTIN SEMI. | | Y | AS8F128K32Q-120/Q | 669 |
| 5962-9471602HMC | F | 11/10/2003 | 1 | WHITE ELEC. | | Y | WF128K32-120G2Q5 | 669 |
| 5962-9471602HNA | F | 11/10/2003 | 1 | AEROFLEX | | Y | ACT-F128K32N-120F5 | 669 |
| 5962-9471602HNA | F | 11/10/2003 | 1 | AUSTIN SEMI. | | Y | AS8F128K32Q-120/Q | 669 |
| 5962-9471602HNA | F | 11/10/2003 | 1 | WHITE ELEC. | | Y | WF128K32-120G2UQ5 | 669 |
| 5962-9471602HNC | F | 11/10/2003 | 1 | AEROFLEX | | Y | ACT-F128K32N-120F5 | 669 |
| 5962-9471602HNC | F | 11/10/2003 | 1 | AUSTIN SEMI. | | Y | AS8F128K32Q-120/Q | 669 |
| 5962-9471602HNC | F | 11/10/2003 | 1 | WHITE ELEC. | | Y | WF128K32-120G2UQ5 | 669 |
| 5962-9471602HSA | F | 11/10/2003 | 1 | WHITE ELEC. | | Y | WF128K32A-120HQ5 | 669 |
| 5962-9471602HSC | F | 11/10/2003 | 1 | WHITE ELEC. | | Y | WF128K32A-120HQ5 | 669 |
| 5962-9471602HTA | F | 11/10/2003 | 1 | WHITE ELEC. | | Y | WF128K32A-120HSQ5 | 669 |
| 5962-9471602HTC | F | 11/10/2003 | 1 | WHITE ELEC. | | Y | WF128K32A-120HSQ5 | 669 |
| 5962-9471602HUA | F | 11/10/2003 | 1 | WHITE ELEC. | | Y | WF128K32-120HQ5 | 669 |
| 5962-9471602HUC | F | 11/10/2003 | 1 | WHITE ELEC. | | Y | WF128K32-120HQ5 | 669 |
| 5962-9471602HVA | F | 11/10/2003 | 1 | WHITE ELEC. | | Y | WF128K32-120HSQ5 | 669 |
| 5962-9471602HVC | F | 11/10/2003 | 1 | WHITE ELEC. | | Y | WF128K32-120HSQ5 | 669 |
| 5962-9471602HWA | F | 11/10/2003 | 1 | WHITE ELEC. | | Y | WF128K32NA-120HQ5 | 669 |
| 5962-9471602HWC | F | 11/10/2003 | 1 | WHITE ELEC. | | Y | WF128K32NA-120HQ5 | 669 |
| 5962-9471602HXA | F | 11/10/2003 | 1 | WHITE ELEC. | | Y | WF128K32NA-120HSQ | 669 |
| 5962-9471602HXC | F | 11/10/2003 | 1 | WHITE ELEC. | | Y | WF128K32NA-120HSQ | 669 |
| 5962-9471602HYA | F | 11/10/2003 | 1 | WHITE ELEC. | | Y | WF128K32N-120HQ5 | 669 |
| 5962-9471602HYC | F | 11/10/2003 | 1 | WHITE ELEC. | | Y | WF128K32N-120HQ5 | 669 |
| 5962-9471602HZA | F | 11/10/2003 | 1 | AEROFLEX | | Y | ACT-F128K32N-120P3 | 669 |
| 5962-9471602HZA | F | 11/10/2003 | 1 | WHITE ELEC. | | Y | WF128K32N-120HSQ5 | 669 |
| 5962-9471602HZC | F | 11/10/2003 | 1 | AEROFLEX | | Y | ACT-F128K32N-120P3 | 669 |
| 5962-9471602HZC | F | 11/10/2003 | 1 | WHITE ELEC. | | Y | WF128K32N-120HSQ5 | 669 |
| 5962-9471603H4C | F | 11/10/2003 | 1 | WHITE ELEC. | | Y | WF128K32-90G4Q5 | 669 |
| 5962-9471603H5A | F | 11/10/2003 | 1 | WHITE ELEC. | | Y | WF128K32A-90H1Q5 | 669 |
| 5962-9471603H5C | F | 11/10/2003 | 1 | WHITE ELEC. | | Y | WF128K32A-90H1Q5 | 669 |
| 5962-9471603H6A | F | 11/10/2003 | 1 | WHITE ELEC. | | Y | WF128K32-90H1Q5 | 669 |
| 5962-9471603H6C | F | 11/10/2003 | 1 | WHITE ELEC. | | Y | WF128K32-90H1Q5 | 669 |
| 5962-9471603H7A | F | 11/10/2003 | 1 | WHITE ELEC. | | Y | WF128K32NA-90H1Q5 | 669 |
| 5962-9471603H7C | F | 11/10/2003 | 1 | WHITE ELEC. | | Y | WF128K32NA-90H1Q5 | 669 |
| 5962-9471603H8A | F | 11/10/2003 | 1 | AEROFLEX | | Y | ACT-F128K32N-090P7 | 669 |
| 5962-9471603H8A | F | 11/10/2003 | 1 | WHITE ELEC. | | Y | WF128K32N-90H1Q5 | 669 |
| 5962-9471603H8C | F | 11/10/2003 | 1 | AEROFLEX | | Y | ACT-F128K32N-090P7 | 669 |
| 5962-9471603H8C | F | 11/10/2003 | 1 | WHITE ELEC. | | Y | WF128K32N-90H1Q5 | 669 |
| 5962-9471603H9A | F | 11/10/2003 | 1 | WHITE ELEC. | | Y | WF128K32-90G1UQ5 | 669 |
| 5962-9471603H9C | F | 11/10/2003 | 1 | WHITE ELEC. | | Y | WF128K32-90G1UQ5 | 669 |
| 5962-9471603HAA | F | 11/10/2003 | 1 | AUSTIN SEMI. | | Y | AS8F128K32Q1-90/Q | 669 |
| 5962-9471603HAA | F | 11/10/2003 | 1 | WHITE ELEC. | | Y | WF128K32-90G2LQ5 | 669 |
| 5962-9471603HAC | F | 11/10/2003 | 1 | AUSTIN SEMI. | | Y | AS8F128K32Q1-90/Q | 669 |
| 5962-9471603HAC | F | 11/10/2003 | 1 | WHITE ELEC. | | Y | WF128K32-90G2LQ5 | 669 |
| 5962-9471603HBA | F | 11/10/2003 | 1 | WHITE ELEC. | | Y | WF128K32-90G1TQ5 | 669 |
| 5962-9471603HBC | F | 11/10/2003 | 1 | WHITE ELEC. | | Y | WF128K32-90G1TQ5 | 669 |
| 5962-9471603HMA | F | 11/10/2003 | 1 | AEROFLEX | | Y | ACT-F128K32N-090F5 | 669 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9471603HMA | F | 11/10/2003 | 1 | AUSTIN SEMI. | | Y | AS8F128K32Q-90/Q | 669 |
| 5962-9471603HMA | F | 11/10/2003 | 1 | WHITE ELEC. | | Y | WF128K32-90G2Q5 | 669 |
| 5962-9471603HMC | F | 11/10/2003 | 1 | AEROFLEX | | Y | ACT-F128K32N-090F5 | 669 |
| 5962-9471603HMC | F | 11/10/2003 | 1 | AUSTIN SEMI. | | Y | AS8F128K32Q-90/Q | 669 |
| 5962-9471603HMC | F | 11/10/2003 | 1 | WHITE ELEC. | | Y | WF128K32-90G2Q5 | 669 |
| 5962-9471603HNA | F | 11/10/2003 | 1 | AEROFLEX | | Y | ACT-F128K32N-090F5 | 669 |
| 5962-9471603HNA | F | 11/10/2003 | 1 | AUSTIN SEMI. | | Y | AS8F128K32Q-90/Q | 669 |
| 5962-9471603HNA | F | 11/10/2003 | 1 | WHITE ELEC. | | Y | WF128K32-90G2UQ5 | 669 |
| 5962-9471603HNC | F | 11/10/2003 | 1 | AEROFLEX | | Y | ACT-F128K32N-090F5 | 669 |
| 5962-9471603HNC | F | 11/10/2003 | 1 | AUSTIN SEMI. | | Y | AS8F128K32Q-90/Q | 669 |
| 5962-9471603HNC | F | 11/10/2003 | 1 | WHITE ELEC. | | Y | WF128K32-90G2UQ5 | 669 |
| 5962-9471603HSA | F | 11/10/2003 | 1 | WHITE ELEC. | | Y | WF128K32A-90HQ5 | 669 |
| 5962-9471603HSC | F | 11/10/2003 | 1 | WHITE ELEC. | | Y | WF128K32A-90HQ5 | 669 |
| 5962-9471603HTA | F | 11/10/2003 | 1 | WHITE ELEC. | | Y | WF128K32A-90HSQ5 | 669 |
| 5962-9471603HTC | F | 11/10/2003 | 1 | WHITE ELEC. | | Y | WF128K32A-90HSQ5 | 669 |
| 5962-9471603HUA | F | 11/10/2003 | 1 | WHITE ELEC. | | Y | WF128K32-90HQ5 | 669 |
| 5962-9471603HUC | F | 11/10/2003 | 1 | WHITE ELEC. | | Y | WF128K32-90HQ5 | 669 |
| 5962-9471603HVA | F | 11/10/2003 | 1 | WHITE ELEC. | | Y | WF128K32-90HSQ5 | 669 |
| 5962-9471603HVC | F | 11/10/2003 | 1 | WHITE ELEC. | | Y | WF128K32-90HSQ5 | 669 |
| 5962-9471603HWA | F | 11/10/2003 | 1 | WHITE ELEC. | | Y | WF128K32NA-90HQ5 | 669 |
| 5962-9471603HWC | F | 11/10/2003 | 1 | WHITE ELEC. | | Y | WF128K32NA-90HQ5 | 669 |
| 5962-9471603HXA | F | 11/10/2003 | 1 | WHITE ELEC. | | Y | WF128K32NA-90HSQ5 | 669 |
| 5962-9471603HXC | F | 11/10/2003 | 1 | WHITE ELEC. | | Y | WF128K32NA-90HSQ5 | 669 |
| 5962-9471603HYA | F | 11/10/2003 | 1 | WHITE ELEC. | | Y | WF128K32N-90HQ5 | 669 |
| 5962-9471603HYC | F | 11/10/2003 | 1 | WHITE ELEC. | | Y | WF128K32N-90HQ5 | 669 |
| 5962-9471603HZA | F | 11/10/2003 | 1 | AEROFLEX | | Y | ACT-F128K32N-090P3 | 669 |
| 5962-9471603HZA | F | 11/10/2003 | 1 | WHITE ELEC. | | Y | WF128K32N-90HSQ5 | 669 |
| 5962-9471603HZC | F | 11/10/2003 | 1 | AEROFLEX | | Y | ACT-F128K32N-090P3 | 669 |
| 5962-9471603HZC | F | 11/10/2003 | 1 | WHITE ELEC. | | Y | WF128K32N-90HSQ5 | 669 |
| 5962-9471604H4C | F | 11/10/2003 | 1 | WHITE ELEC. | | Y | WF128K32-70G4Q5 | 669 |
| 5962-9471604H5A | F | 11/10/2003 | 1 | WHITE ELEC. | | Y | WF128K32A-70H1Q5 | 669 |
| 5962-9471604H5C | F | 11/10/2003 | 1 | WHITE ELEC. | | Y | WF128K32A-70H1Q5 | 669 |
| 5962-9471604H6A | F | 11/10/2003 | 1 | WHITE ELEC. | | Y | WF128K32-70H1Q5 | 669 |
| 5962-9471604H6C | F | 11/10/2003 | 1 | WHITE ELEC. | | Y | WF128K32-70H1Q5 | 669 |
| 5962-9471604H7A | F | 11/10/2003 | 1 | WHITE ELEC. | | Y | WF128K32NA-70H1Q5 | 669 |
| 5962-9471604H7C | F | 11/10/2003 | 1 | WHITE ELEC. | | Y | WF128K32NA-70H1Q5 | 669 |
| 5962-9471604H8A | F | 11/10/2003 | 1 | AEROFLEX | | Y | ACT-F128K32N-070P7 | 669 |
| 5962-9471604H8A | F | 11/10/2003 | 1 | WHITE ELEC. | | Y | WF128K32N-70H1Q5 | 669 |
| 5962-9471604H8C | F | 11/10/2003 | 1 | AEROFLEX | | Y | ACT-F128K32N-070P7 | 669 |
| 5962-9471604H8C | F | 11/10/2003 | 1 | WHITE ELEC. | | Y | WF128K32N-70H1Q5 | 669 |
| 5962-9471604H9A | F | 11/10/2003 | 1 | WHITE ELEC. | | Y | WF128K32-70G1UQ5 | 669 |
| 5962-9471604H9C | F | 11/10/2003 | 1 | WHITE ELEC. | | Y | WF128K32-70G1UQ5 | 669 |
| 5962-9471604HAA | F | 11/10/2003 | 1 | AUSTIN SEMI. | | Y | AS8F128K32Q1-70/Q | 669 |
| 5962-9471604HAA | F | 11/10/2003 | 1 | WHITE ELEC. | | Y | WF128K32-70G2LQ5 | 669 |
| 5962-9471604HAC | F | 11/10/2003 | 1 | AUSTIN SEMI. | | Y | AS8F128K32Q1-70/Q | 669 |
| 5962-9471604HAC | F | 11/10/2003 | 1 | WHITE ELEC. | | Y | WF128K32-70G2LQ5 | 669 |
| 5962-9471604HBA | F | 11/10/2003 | 1 | WHITE ELEC. | | Y | WF128K32-70G1TQ5 | 669 |
| 5962-9471604HBC | F | 11/10/2003 | 1 | WHITE ELEC. | | Y | WF128K32-70G1TQ5 | 669 |
| 5962-9471604HMA | F | 11/10/2003 | 1 | AEROFLEX | | Y | ACT-F128K32N-070F5 | 669 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9471604HMA | F | 11/10/2003 | 1 | AUSTIN SEMI. | | Y | AS8F128K32Q-70/Q | 669 |
| 5962-9471604HMA | F | 11/10/2003 | 1 | WHITE ELEC. | | Y | WF128K32-70G2Q5 | 669 |
| 5962-9471604HMC | F | 11/10/2003 | 1 | AEROFLEX | | Y | ACT-F128K32N-070F5 | 669 |
| 5962-9471604HMC | F | 11/10/2003 | 1 | AUSTIN SEMI. | | Y | AS8F128K32Q-70/Q | 669 |
| 5962-9471604HMC | F | 11/10/2003 | 1 | WHITE ELEC. | | Y | WF128K32-70G2Q5 | 669 |
| 5962-9471604HNA | F | 11/10/2003 | 1 | AEROFLEX | | Y | ACT-F128K32N-070F5 | 669 |
| 5962-9471604HNA | F | 11/10/2003 | 1 | AUSTIN SEMI. | | Y | AS8F128K32Q-70/Q | 669 |
| 5962-9471604HNA | F | 11/10/2003 | 1 | WHITE ELEC. | | Y | WF128K32-70G2UQ5 | 669 |
| 5962-9471604HNC | F | 11/10/2003 | 1 | AEROFLEX | | Y | ACT-F128K32N-070F5 | 669 |
| 5962-9471604HNC | F | 11/10/2003 | 1 | AUSTIN SEMI. | | Y | AS8F128K32Q-70/Q | 669 |
| 5962-9471604HNC | F | 11/10/2003 | 1 | WHITE ELEC. | | Y | WF128K32-70G2UQ5 | 669 |
| 5962-9471604HSA | F | 11/10/2003 | 1 | WHITE ELEC. | | Y | WF128K32A-70HQ5 | 669 |
| 5962-9471604HSC | F | 11/10/2003 | 1 | WHITE ELEC. | | Y | WF128K32A-70HQ5 | 669 |
| 5962-9471604HTA | F | 11/10/2003 | 1 | WHITE ELEC. | | Y | WF128K32A-70HSQ5 | 669 |
| 5962-9471604HTC | F | 11/10/2003 | 1 | WHITE ELEC. | | Y | WF128K32A-70HSQ5 | 669 |
| 5962-9471604HUA | F | 11/10/2003 | 1 | WHITE ELEC. | | Y | WF128K32-70HQ5 | 669 |
| 5962-9471604HUC | F | 11/10/2003 | 1 | WHITE ELEC. | | Y | WF128K32-70HQ5 | 669 |
| 5962-9471604HVA | F | 11/10/2003 | 1 | WHITE ELEC. | | Y | WF128K32-70HSQ5 | 669 |
| 5962-9471604HVC | F | 11/10/2003 | 1 | WHITE ELEC. | | Y | WF128K32-70HSQ5 | 669 |
| 5962-9471604HWA | F | 11/10/2003 | 1 | WHITE ELEC. | | Y | WF128K32NA-70HQ5 | 669 |
| 5962-9471604HWC | F | 11/10/2003 | 1 | WHITE ELEC. | | Y | WF128K32NA-70HQ5 | 669 |
| 5962-9471604HXA | F | 11/10/2003 | 1 | WHITE ELEC. | | Y | WF128K32NA-70HSQ5 | 669 |
| 5962-9471604HXC | F | 11/10/2003 | 1 | WHITE ELEC. | | Y | WF128K32NA-70HSQ5 | 669 |
| 5962-9471604HYA | F | 11/10/2003 | 1 | WHITE ELEC. | | Y | WF128K32N-70HQ5 | 669 |
| 5962-9471604HYC | F | 11/10/2003 | 1 | WHITE ELEC. | | Y | WF128K32N-70HQ5 | 669 |
| 5962-9471604HZA | F | 11/10/2003 | 1 | AEROFLEX | | Y | ACT-F128K32N-070P3 | 669 |
| 5962-9471604HZA | F | 11/10/2003 | 1 | WHITE ELEC. | | Y | WF128K32N-70HSQ5 | 669 |
| 5962-9471604HZC | F | 11/10/2003 | 1 | AEROFLEX | | Y | ACT-F128K32N-070P3 | 669 |
| 5962-9471604HZC | F | 11/10/2003 | 1 | WHITE ELEC. | | Y | WF128K32N-70HSQ5 | 669 |
| 5962-9471605H4C | F | 11/10/2003 | 1 | WHITE ELEC. | | Y | WF128K32-60G4Q5 | 669 |
| 5962-9471605H5A | F | 11/10/2003 | 1 | WHITE ELEC. | | Y | WF128K32A-60H1Q5 | 669 |
| 5962-9471605H5C | F | 11/10/2003 | 1 | WHITE ELEC. | | Y | WF128K32A-60H1Q5 | 669 |
| 5962-9471605H6A | F | 11/10/2003 | 1 | WHITE ELEC. | | Y | WF128K32-60H1Q5 | 669 |
| 5962-9471605H6C | F | 11/10/2003 | 1 | WHITE ELEC. | | Y | WF128K32-60H1Q5 | 669 |
| 5962-9471605H7A | F | 11/10/2003 | 1 | WHITE ELEC. | | Y | WF128K32NA-60H1Q5 | 669 |
| 5962-9471605H7C | F | 11/10/2003 | 1 | WHITE ELEC. | | Y | WF128K32NA-60H1Q5 | 669 |
| 5962-9471605H8A | F | 11/10/2003 | 1 | AEROFLEX | | Y | ACT-F128K32N-060P7 | 669 |
| 5962-9471605H8A | F | 11/10/2003 | 1 | WHITE ELEC. | | Y | WF128K32N-60H1Q5 | 669 |
| 5962-9471605H8C | F | 11/10/2003 | 1 | AEROFLEX | | Y | ACT-F128K32N-060P7 | 669 |
| 5962-9471605H8C | F | 11/10/2003 | 1 | WHITE ELEC. | | Y | WF128K32N-60H1Q5 | 669 |
| 5962-9471605H9A | F | 11/10/2003 | 1 | WHITE ELEC. | | Y | WF128K32-60G1UQ5 | 669 |
| 5962-9471605H9C | F | 11/10/2003 | 1 | WHITE ELEC. | | Y | WF128K32-60G1UQ5 | 669 |
| 5962-9471605HAA | F | 11/10/2003 | 1 | AUSTIN SEMI. | | Y | AS8F128K32Q1-60/Q | 669 |
| 5962-9471605HAA | F | 11/10/2003 | 1 | WHITE ELEC. | | Y | WF128K32-60G2LQ5 | 669 |
| 5962-9471605HAC | F | 11/10/2003 | 1 | AUSTIN SEMI. | | Y | AS8F128K32Q1-60/Q | 669 |
| 5962-9471605HAC | F | 11/10/2003 | 1 | WHITE ELEC. | | Y | WF128K32-60G2LQ5 | 669 |
| 5962-9471605HBA | F | 11/10/2003 | 1 | WHITE ELEC. | | Y | WF128K32-60G1TQ5 | 669 |
| 5962-9471605HBC | F | 11/10/2003 | 1 | WHITE ELEC. | | Y | WF128K32-60G1TQ5 | 669 |
| 5962-9471605HMA | F | 11/10/2003 | 1 | AEROFLEX | | Y | ACT-F128K32N-060F5 | 669 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9471605HMA | F | 11/10/2003 | 1 | AUSTIN SEMI. | | Y | AS8F128K32Q-60/Q | 669 |
| 5962-9471605HMA | F | 11/10/2003 | 1 | WHITE ELEC. | | Y | WF128K32-60G2Q5 | 669 |
| 5962-9471605HMC | F | 11/10/2003 | 1 | AEROFLEX | | Y | ACT-F128K32N-060F5 | 669 |
| 5962-9471605HMC | F | 11/10/2003 | 1 | AUSTIN SEMI. | | Y | AS8F128K32Q-60/Q | 669 |
| 5962-9471605HMC | F | 11/10/2003 | 1 | WHITE ELEC. | | Y | WF128K32-60G2Q5 | 669 |
| 5962-9471605HNA | F | 11/10/2003 | 1 | AEROFLEX | | Y | ACT-F128K32N-060F5 | 669 |
| 5962-9471605HNA | F | 11/10/2003 | 1 | AUSTIN SEMI. | | Y | AS8F128K32Q-60/Q | 669 |
| 5962-9471605HNA | F | 11/10/2003 | 1 | WHITE ELEC. | | Y | WF128K32-60G2UQ5 | 669 |
| 5962-9471605HNC | F | 11/10/2003 | 1 | AEROFLEX | | Y | ACT-F128K32N-060F5 | 669 |
| 5962-9471605HNC | F | 11/10/2003 | 1 | AUSTIN SEMI. | | Y | AS8F128K32Q-60/Q | 669 |
| 5962-9471605HNC | F | 11/10/2003 | 1 | WHITE ELEC. | | Y | WF128K32-60G2UQ5 | 669 |
| 5962-9471605HSA | F | 11/10/2003 | 1 | WHITE ELEC. | | Y | WF128K32A-60HQ5 | 669 |
| 5962-9471605HSC | F | 11/10/2003 | 1 | WHITE ELEC. | | Y | WF128K32A-60HQ5 | 669 |
| 5962-9471605HTA | F | 11/10/2003 | 1 | WHITE ELEC. | | Y | WF128K32A-60HSQ5 | 669 |
| 5962-9471605HTC | F | 11/10/2003 | 1 | WHITE ELEC. | | Y | WF128K32A-60HSQ5 | 669 |
| 5962-9471605HUA | F | 11/10/2003 | 1 | WHITE ELEC. | | Y | WF128K32-60HQ5 | 669 |
| 5962-9471605HUC | F | 11/10/2003 | 1 | WHITE ELEC. | | Y | WF128K32-60HQ5 | 669 |
| 5962-9471605HVA | F | 11/10/2003 | 1 | WHITE ELEC. | | Y | WF128K32-60HSQ5 | 669 |
| 5962-9471605HVC | F | 11/10/2003 | 1 | WHITE ELEC. | | Y | WF128K32-60HSQ5 | 669 |
| 5962-9471605HWA | F | 11/10/2003 | 1 | WHITE ELEC. | | Y | WF128K32NA-60HQ5 | 669 |
| 5962-9471605HWC | F | 11/10/2003 | 1 | WHITE ELEC. | | Y | WF128K32NA-60HQ5 | 669 |
| 5962-9471605HXA | F | 11/10/2003 | 1 | WHITE ELEC. | | Y | WF128K32NA-60HSQ5 | 669 |
| 5962-9471605HXC | F | 11/10/2003 | 1 | WHITE ELEC. | | Y | WF128K32NA-60HSQ5 | 669 |
| 5962-9471605HYA | F | 11/10/2003 | 1 | WHITE ELEC. | | Y | WF128K32N-60HQ5 | 669 |
| 5962-9471605HYC | F | 11/10/2003 | 1 | WHITE ELEC. | | Y | WF128K32N-60HQ5 | 669 |
| 5962-9471605HZA | F | 11/10/2003 | 1 | AEROFLEX | | Y | ACT-F128K32N-060P3 | 669 |
| 5962-9471605HZA | F | 11/10/2003 | 1 | WHITE ELEC. | | Y | WF128K32N-60HSQ5 | 669 |
| 5962-9471605HZC | F | 11/10/2003 | 1 | AEROFLEX | | Y | ACT-F128K32N-060P3 | 669 |
| 5962-9471605HZC | F | 11/10/2003 | 1 | WHITE ELEC. | | Y | WF128K32N-60HSQ5 | 669 |
| 5962-9471701MPA | A | 05/16/2001 | 3 | XILINX | | Y | XC1765DDD8B | 660 |
| 5962-9471801Q2A | B | 03/14/1997 | 2 | TI | | Y | SNJ54ABT541FK | 529 |
| 5962-9471801QRA | B | 03/14/1997 | 2 | TI | | Y | SNJ54ABT541J | 529 |
| 5962-9471801QSA | B | 03/14/1997 | 2 | TI | | Y | SNJ54ABT541W | 529 |
| 5962-9471901M2A | C | 06/12/2003 | 1 | NATIONAL | | Y | CLC412AE-QML | 760 |
| 5962-9471901MPA | C | 06/12/2003 | 1 | NATIONAL | | Y | CLC412AJ-QML | 760 |
| 5962-9472101HUA | A | 03/05/2004 | 1 | ADV. ANALOG | | Y | AFL2805SW/CH | 594 |
| 5962-9472101HUC | A | 03/05/2004 | 1 | ADV. ANALOG | | Y | AFL2805SW/CH | 594 |
| 5962-9472101HXA | A | 03/05/2004 | 1 | ADV. ANALOG | | Y | AFL2805SX/CH | 594 |
| 5962-9472101HXC | A | 03/05/2004 | 1 | ADV. ANALOG | | Y | AFL2805SX/CH | 594 |
| 5962-9472101HYA | A | 03/05/2004 | 1 | ADV. ANALOG | | Y | AFL2805SY/CH | 594 |
| 5962-9472101HYC | A | 03/05/2004 | 1 | ADV. ANALOG | | Y | AFL2805SY/CH | 594 |
| 5962-9472101HZA | A | 03/05/2004 | 1 | ADV. ANALOG | | Y | AFL2805SZ/CH | 594 |
| 5962-9472101HZC | A | 03/05/2004 | 1 | ADV. ANALOG | | Y | AFL2805SZ/CH | 594 |
| 5962-9472201HUA | A | 03/05/2004 | 1 | ADV. ANALOG | | Y | AFL2812SW/CH | 594 |
| 5962-9472201HUC | A | 03/05/2004 | 1 | ADV. ANALOG | | Y | AFL2812SW/CH | 594 |
| 5962-9472201HXA | A | 03/05/2004 | 1 | ADV. ANALOG | | Y | AFL2812SX/CH | 594 |
| 5962-9472201HXC | A | 03/05/2004 | 1 | ADV. ANALOG | | Y | AFL2812SX/CH | 594 |
| 5962-9472201HYA | A | 03/05/2004 | 1 | ADV. ANALOG | | Y | AFL2812SY/CH | 594 |
| 5962-9472201HYC | A | 03/05/2004 | 1 | ADV. ANALOG | | Y | AFL2812SY/CH | 594 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9472201HZA | A | 03/05/2004 | 1 | ADV. ANALOG | | Y | AFL2812SZ/CH | 594 |
| 5962-9472201HZC | A | 03/05/2004 | 1 | ADV. ANALOG | | Y | AFL2812SZ/CH | 594 |
| 5962-9472301HUA | A | 03/08/2004 | 1 | ADV. ANALOG | | Y | AFL2815SW/CH | 594 |
| 5962-9472301HUC | A | 03/08/2004 | 1 | ADV. ANALOG | | Y | AFL2815SW/CH | 594 |
| 5962-9472301HXA | A | 03/08/2004 | 1 | ADV. ANALOG | | Y | AFL2815SX/CH | 594 |
| 5962-9472301HXC | A | 03/08/2004 | 1 | ADV. ANALOG | | Y | AFL2815SX/CH | 594 |
| 5962-9472301HYA | A | 03/08/2004 | 1 | ADV. ANALOG | | Y | AFL2815SY/CH | 594 |
| 5962-9472301HYC | A | 03/08/2004 | 1 | ADV. ANALOG | | Y | AFL2815SY/CH | 594 |
| 5962-9472301HZA | A | 03/08/2004 | 1 | ADV. ANALOG | | Y | AFL2815SZ/CH | 594 |
| 5962-9472301HZC | A | 03/08/2004 | 1 | ADV. ANALOG | | Y | AFL2815SZ/CH | 594 |
| 5962-9472401HUA | A | 03/08/2004 | 1 | ADV. ANALOG | | Y | AFL2815DW/CH | 594 |
| 5962-9472401HUC | A | 03/08/2004 | 1 | ADV. ANALOG | | Y | AFL2815DW/CH | 594 |
| 5962-9472401HXA | A | 03/08/2004 | 1 | ADV. ANALOG | | Y | AFL2815DX/CH | 594 |
| 5962-9472401HXC | A | 03/08/2004 | 1 | ADV. ANALOG | | Y | AFL2815DX/CH | 594 |
| 5962-9472401HYA | A | 03/08/2004 | 1 | ADV. ANALOG | | Y | AFL2815DY/CH | 594 |
| 5962-9472401HYC | A | 03/08/2004 | 1 | ADV. ANALOG | | Y | AFL2815DY/CH | 594 |
| 5962-9472401HZA | A | 03/08/2004 | 1 | ADV. ANALOG | | Y | AFL2815DZ/CH | 594 |
| 5962-9472401HZC | A | 03/08/2004 | 1 | ADV. ANALOG | | Y | AFL2815DZ/CH | 594 |
| 5962-9472501M2A | C | 03/29/2004 | 3 | NATIONAL | | Y | CLC431AE-QML | 710 |
| 5962-9472501MCA | C | 03/29/2004 | 3 | NATIONAL | | Y | CLC431AJ-QML | 710 |
| 5962-9472502M2A | C | 03/29/2004 | | (NONE) | | | CLC432A (GEN) | 710 |
| 5962-9472502MPA | C | 03/29/2004 | 1 | NATIONAL | | Y | CLC432AJ-QML | 710 |
| 5962-9472601Q2A | A | 10/14/1994 | | (NONE) | 05/01/1998 | | TL052 (GEN) | 710 |
| 5962-9472601QPA | A | 10/14/1994 | | (NONE) | 05/01/1998 | | TL052 (GEN) | 710 |
| 5962-9472701HXA | A | 05/21/2001 | | (NONE) | | | MSK640B (GEN) | 760 |
| 5962-9472702HXA | A | 05/21/2001 | | (NONE) | | | MSK641B (GEN) | 760 |
| 5962-9472801QXA | | 08/24/1994 | 2 | TI | | Y | SNJ54ABTH16260WD | 342 |
| 5962-9472901QEA | | 07/20/1995 | | (NONE) | 12/24/2000 | | HA-2556 (GEN) | 810 |
| 5962-9473001MXC | D | 04/16/2002 | | (NONE) | 01/15/2000 | | 4013-10 (GEN) | 431 |
| 5962-9473001MYC | D | 04/16/2002 | | (NONE) | 01/15/2000 | | 4013-10 (GEN) | 431 |
| 5962-9473001MZC | D | 04/16/2002 | | (NONE) | 01/15/2000 | | 4013-10 (GEN) | 431 |
| 5962-9473002MXC | D | 04/16/2002 | 3 | XILINX | | Y | XC4013-6PG223B | 431 |
| 5962-9473002MYC | D | 04/16/2002 | 3 | XILINX | | Y | XC4013-6CB228B | 431 |
| 5962-9473002MZC | D | 04/16/2002 | 3 | XILINX | | Y | XC4013-6CB228B | 431 |
| 5962-9473201M2A | | 10/07/1994 | | (NONE) | 08/15/1999 | | TL-SCSI285 (GEN) | 782 |
| 5962-9473201MCA | | 10/07/1994 | | (NONE) | 08/15/1999 | | TL-SCSI285 (GEN) | 782 |
| 5962-9473301MXC | | 02/16/1995 | | (NONE) | 10/31/1996 | | 81188 (GEN) | 431 |
| 5962-9473401MXA | | 04/03/1995 | | (NONE) | 11/01/1997 | | 416100-10 (GEN) | 629 |
| 5962-9473401MYA | | 04/03/1995 | | (NONE) | 11/01/1997 | | 416100-10 (GEN) | 629 |
| 5962-9473402MXA | | 04/03/1995 | | (NONE) | 11/01/1997 | | 416100-80 (GEN) | 629 |
| 5962-9473402MYA | | 04/03/1995 | | (NONE) | 11/01/1997 | | 416100-80 (GEN) | 629 |
| 5962-9473403MXA | | 04/03/1995 | | (NONE) | 11/01/1997 | | 416100-70 (GEN) | 629 |
| 5962-9473403MYA | | 04/03/1995 | | (NONE) | 11/01/1997 | | 416100-70 (GEN) | 629 |
| 5962-9474301MXA | A | 06/15/2004 | 2 | ANALOG (2) | | Y | AD676TD/883B | 592 |
| 5962-9474401MXA | B | 11/08/1996 | 2 | IDT | 07/26/2004 | Y | IDT54FCT162511ATEB | 590 |
| 5962-9474402MXA | B | 11/08/1996 | 2 | IDT | 07/26/2004 | Y | IDT54FCT162511CTEB | 590 |
| 5962-9474501MPA | | 02/17/1995 | | (NONE) | 10/31/1996 | | EPC1213 (GEN) | 662 |
| 5962-9474601M2A | | 02/15/1995 | | (NONE) | 12/31/2001 | | UC1717 (GEN) | 899 |
| 5962-9474601MEA | | 02/15/1995 | | (NONE) | 12/31/2001 | | UC1717 (GEN) | 899 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9474801QXC | | 11/21/1994 | | (NONE) | 02/29/2000 | | TLC34076-135 (GEN) | 591 |
| 5962-9474901MEA | B | 12/03/2001 | 1 | INTERSIL | 10/03/2004 | Y | HFA3127MJ/883 | 790 |
| 5962-9475001Q3A | | 03/06/1995 | 3 | NATIONAL | | Y | SCANPSC100FLMQB | 809 |
| 5962-9475001QXA | | 03/06/1995 | | (NONE) | 09/02/2003 | | SCANPSC100F (GEN) | 809 |
| 5962-9475001QYA | | 03/06/1995 | 3 | NATIONAL | | Y | SCANPSC100FFMQB | 809 |
| 5962-9475301HUA | A | 03/08/2004 | 1 | ADV. ANALOG | | Y | AFL27012SW/CH | 594 |
| 5962-9475301HUC | A | 03/08/2004 | 1 | ADV. ANALOG | | Y | AFL27012SW/CH | 594 |
| 5962-9475301HXA | A | 03/08/2004 | 1 | ADV. ANALOG | | Y | AFL27012SX/CH | 594 |
| 5962-9475301HXC | A | 03/08/2004 | 1 | ADV. ANALOG | | Y | AFL27012SX/CH | 594 |
| 5962-9475301HYA | A | 03/08/2004 | 1 | ADV. ANALOG | | Y | AFL27012SY/CH | 594 |
| 5962-9475301HYC | A | 03/08/2004 | 1 | ADV. ANALOG | | Y | AFL27012SY/CH | 594 |
| 5962-9475301HZA | A | 03/08/2004 | 1 | ADV. ANALOG | | Y | AFL27012SZ/CH | 594 |
| 5962-9475301HZC | A | 03/08/2004 | 1 | ADV. ANALOG | | Y | AFL27012SZ/CH | 594 |
| 5962H9475401Q3A | E | 09/08/2004 | | (NONE) | | | 22VP10C (GEN) | 431 |
| 5962H9475401Q3C | E | 09/08/2004 | | (NONE) | | | 22VP10C (GEN) | 431 |
| 5962H9475401V3A | E | 09/08/2004 | | (NONE) | | | 22VP10C (GEN) | 431 |
| 5962H9475401V3C | E | 09/08/2004 | | (NONE) | | | 22VP10C (GEN) | 431 |
| 5962H9475401QKA | E | 09/08/2004 | | (NONE) | | | 22VP10C (GEN) | 431 |
| 5962H9475401QKC | E | 09/08/2004 | | (NONE) | | | 22VP10C (GEN) | 431 |
| 5962H9475401VKA | E | 09/08/2004 | | (NONE) | | | 22VP10C (GEN) | 431 |
| 5962H9475401VKC | E | 09/08/2004 | | (NONE) | | | 22VP10C (GEN) | 431 |
| 5962H9475401QLA | E | 09/08/2004 | 1 | UTMC | | Y | UT22VP10C-25PCA | 431 |
| 5962H9475401QLC | E | 09/08/2004 | 1 | UTMC | | Y | UT22VP10C-25PCC | 431 |
| 5962H9475401VLA | E | 09/08/2004 | 1 | UTMC | | Y | UT22VP10C-25PCA | 431 |
| 5962H9475401VLC | E | 09/08/2004 | 1 | UTMC | | Y | UT22VP10C-25PCC | 431 |
| 5962H9475401QXA | E | 09/08/2004 | 1 | UTMC | | Y | UT22VP10C-25UCA | 431 |
| 5962H9475401QXC | E | 09/08/2004 | 1 | UTMC | | Y | UT22VP10C-25UCC | 431 |
| 5962H9475401VXA | E | 09/08/2004 | 1 | UTMC | | Y | UT22VP10C-25UCA | 431 |
| 5962H9475401VXC | E | 09/08/2004 | 1 | UTMC | | Y | UT22VP10C-25UCC | 431 |
| 5962H9475401QYA | E | 09/08/2004 | 1 | UTMC | | Y | UT22VP10C-25WCA | 431 |
| 5962H9475401QYC | E | 09/08/2004 | 1 | UTMC | | Y | UT22VP10C-25WCC | 431 |
| 5962H9475401VYA | E | 09/08/2004 | 1 | UTMC | | Y | UT22VP10C-25WCA | 431 |
| 5962H9475401VYC | E | 09/08/2004 | 1 | UTMC | | Y | UT22VP10C-25WCC | 431 |
| 5962H9475402Q3A | E | 09/08/2004 | | (NONE) | | | 22VP10T (GEN) | 431 |
| 5962H9475402Q3C | E | 09/08/2004 | | (NONE) | | | 22VP10T (GEN) | 431 |
| 5962H9475402V3A | E | 09/08/2004 | | (NONE) | | | 22VP10T (GEN) | 431 |
| 5962H9475402V3C | E | 09/08/2004 | | (NONE) | | | 22VP10T (GEN) | 431 |
| 5962H9475402QKA | E | 09/08/2004 | | (NONE) | | | 22VP10T (GEN) | 431 |
| 5962H9475402QKC | E | 09/08/2004 | | (NONE) | | | 22VP10T (GEN) | 431 |
| 5962H9475402VKA | E | 09/08/2004 | | (NONE) | | | 22VP10T (GEN) | 431 |
| 5962H9475402VKC | E | 09/08/2004 | | (NONE) | | | 22VP10T (GEN) | 431 |
| 5962H9475402QLA | E | 09/08/2004 | 1 | UTMC | | Y | UT22VP10T-25PCA | 431 |
| 5962H9475402QLC | E | 09/08/2004 | 1 | UTMC | | Y | UT22VP10T-25PCC | 431 |
| 5962H9475402VLA | E | 09/08/2004 | 1 | UTMC | | Y | UT22VP10T-25PCA | 431 |
| 5962H9475402VLC | E | 09/08/2004 | 1 | UTMC | | Y | UT22VP10T-25PCC | 431 |
| 5962H9475402QXA | E | 09/08/2004 | 1 | UTMC | | Y | UT22VP10T-25UCA | 431 |
| 5962H9475402QXC | E | 09/08/2004 | 1 | UTMC | | Y | UT22VP10T-25UCC | 431 |
| 5962H9475402VXA | E | 09/08/2004 | 1 | UTMC | | Y | UT22VP10T-25UCA | 431 |
| 5962H9475402VXC | E | 09/08/2004 | 1 | UTMC | | Y | UT22VP10T-25UCC | 431 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962H9475402QYA | E | 09/08/2004 | 1 | UTMC | | Y | UT22VP10T-25WCA | 431 |
| 5962H9475402QYC | E | 09/08/2004 | 1 | UTMC | | Y | UT22VP10T-25WCC | 431 |
| 5962H9475402VYA | E | 09/08/2004 | 1 | UTMC | | Y | UT22VP10T-25WCA | 431 |
| 5962H9475402VYC | E | 09/08/2004 | 1 | UTMC | | Y | UT22VP10T-25WCC | 431 |
| 5962H9475403QLA | E | 09/08/2004 | 1 | UTMC | | Y | UT22VP10C-20PCA | 431 |
| 5962H9475403QLC | E | 09/08/2004 | 1 | UTMC | | Y | UT22VP10C-20PCC | 431 |
| 5962H9475403VLA | E | 09/08/2004 | 1 | UTMC | | Y | UT22VP10C-20PCA | 431 |
| 5962H9475403VLC | E | 09/08/2004 | 1 | UTMC | | Y | UT22VP10C-20PCC | 431 |
| 5962H9475403QXA | E | 09/08/2004 | 1 | UTMC | | Y | UT22VP10C-20UCA | 431 |
| 5962H9475403QXC | E | 09/08/2004 | 1 | UTMC | | Y | UT22VP10C-20UCC | 431 |
| 5962H9475403VXA | E | 09/08/2004 | 1 | UTMC | | Y | UT22VP10C-20UCA | 431 |
| 5962H9475403VXC | E | 09/08/2004 | 1 | UTMC | | Y | UT22VP10C-20UCC | 431 |
| 5962H9475403QYA | E | 09/08/2004 | 1 | UTMC | | Y | UT22VP10C-20WCA | 431 |
| 5962H9475403QYC | E | 09/08/2004 | 1 | UTMC | | Y | UT22VP10C-20WCC | 431 |
| 5962H9475403VYA | E | 09/08/2004 | 1 | UTMC | | Y | UT22VP10C-20WCA | 431 |
| 5962H9475403VYC | E | 09/08/2004 | 1 | UTMC | | Y | UT22VP10C-20WCC | 431 |
| 5962H9475404QLA | E | 09/08/2004 | 1 | UTMC | | Y | UT22VP10T-20PCA | 431 |
| 5962H9475404QLC | E | 09/08/2004 | 1 | UTMC | | Y | UT22VP10T-20PCC | 431 |
| 5962H9475404VLA | E | 09/08/2004 | 1 | UTMC | | Y | UT22VP10T-20PCA | 431 |
| 5962H9475404VLC | E | 09/08/2004 | 1 | UTMC | | Y | UT22VP10T-20PCC | 431 |
| 5962H9475404QXA | E | 09/08/2004 | 1 | UTMC | | Y | UT22VP10T-20UCA | 431 |
| 5962H9475404QXC | E | 09/08/2004 | 1 | UTMC | | Y | UT22VP10T-20UCC | 431 |
| 5962H9475404VXA | E | 09/08/2004 | 1 | UTMC | | Y | UT22VP10T-20UCA | 431 |
| 5962H9475404VXC | E | 09/08/2004 | 1 | UTMC | | Y | UT22VP10T-20UCC | 431 |
| 5962H9475404QYA | E | 09/08/2004 | 1 | UTMC | | Y | UT22VP10T-20WCA | 431 |
| 5962H9475404QYC | E | 09/08/2004 | 1 | UTMC | | Y | UT22VP10T-20WCC | 431 |
| 5962H9475404VYA | E | 09/08/2004 | 1 | UTMC | | Y | UT22VP10T-20WCA | 431 |
| 5962H9475404VYC | E | 09/08/2004 | 1 | UTMC | | Y | UT22VP10T-20WCC | 431 |
| 5962H9475405QLA | E | 09/08/2004 | 1 | UTMC | | Y | UT22VP10E-25PCA | 431 |
| 5962H9475405QLC | E | 09/08/2004 | 1 | UTMC | | Y | UT22VP10E-25PCC | 431 |
| 5962H9475405VLA | E | 09/08/2004 | 1 | UTMC | | Y | UT22VP10E-25PCA | 431 |
| 5962H9475405VLC | E | 09/08/2004 | 1 | UTMC | | Y | UT22VP10E-25PCC | 431 |
| 5962H9475405QXA | E | 09/08/2004 | 1 | UTMC | | Y | UT22VP10E-25UCA | 431 |
| 5962H9475405QXC | E | 09/08/2004 | 1 | UTMC | | Y | UT22VP10E-25UCC | 431 |
| 5962H9475405VXA | E | 09/08/2004 | 1 | UTMC | | Y | UT22VP10E-25UCA | 431 |
| 5962H9475405VXC | E | 09/08/2004 | 1 | UTMC | | Y | UT22VP10E-25UCC | 431 |
| 5962H9475405QYA | E | 09/08/2004 | 1 | UTMC | | Y | UT22VP10E-25WCA | 431 |
| 5962H9475405QYC | E | 09/08/2004 | 1 | UTMC | | Y | UT22VP10E-25WCC | 431 |
| 5962H9475405VYA | E | 09/08/2004 | 1 | UTMC | | Y | UT22VP10E-25WCA | 431 |
| 5962H9475405VYC | E | 09/08/2004 | 1 | UTMC | | Y | UT22VP10E-25WCC | 431 |
| 5962H9475406QLA | E | 09/08/2004 | 1 | UTMC | | Y | UT22VP10E-20PCA | 431 |
| 5962H9475406QLC | E | 09/08/2004 | 1 | UTMC | | Y | UT22VP10E-20PCC | 431 |
| 5962H9475406VLA | E | 09/08/2004 | 1 | UTMC | | Y | UT22VP10E-20PCA | 431 |
| 5962H9475406VLC | E | 09/08/2004 | 1 | UTMC | | Y | UT22VP10E-20PCC | 431 |
| 5962H9475406QXA | E | 09/08/2004 | 1 | UTMC | | Y | UT22VP10E-20UCA | 431 |
| 5962H9475406QXC | E | 09/08/2004 | 1 | UTMC | | Y | UT22VP10E-20UCC | 431 |
| 5962H9475406VXA | E | 09/08/2004 | 1 | UTMC | | Y | UT22VP10E-20UCA | 431 |
| 5962H9475406VXC | E | 09/08/2004 | 1 | UTMC | | Y | UT22VP10E-20UCC | 431 |
| 5962H9475406QYA | E | 09/08/2004 | 1 | UTMC | | Y | UT22VP10E-20WCA | 431 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962H9475406QYC | E | 09/08/2004 | 1 | UTMC | | Y | UT22VP10E-20WCC | 431 |
| 5962H9475406VYA | E | 09/08/2004 | 1 | UTMC | | Y | UT22VP10E-20WCA | 431 |
| 5962H9475406VYC | E | 09/08/2004 | 1 | UTMC | | Y | UT22VP10E-20WCC | 431 |
| 5962H9475407QLA | E | 09/08/2004 | 1 | UTMC | | Y | UT22VP10E-15PCA | 431 |
| 5962H9475407QLC | E | 09/08/2004 | 1 | UTMC | | Y | UT22VP10E-15PCC | 431 |
| 5962H9475407VLA | E | 09/08/2004 | 1 | UTMC | | Y | UT22VP10E-15PCA | 431 |
| 5962H9475407VLC | E | 09/08/2004 | 1 | UTMC | | Y | UT22VP10E-15PCC | 431 |
| 5962H9475407QXA | E | 09/08/2004 | 1 | UTMC | | Y | UT22VP10E-15UCA | 431 |
| 5962H9475407QXC | E | 09/08/2004 | 1 | UTMC | | Y | UT22VP10E-15UCC | 431 |
| 5962H9475407VXA | E | 09/08/2004 | 1 | UTMC | | Y | UT22VP10E-15UCA | 431 |
| 5962H9475407VXC | E | 09/08/2004 | 1 | UTMC | | Y | UT22VP10E-15UCC | 431 |
| 5962H9475407QYA | E | 09/08/2004 | 1 | UTMC | | Y | UT22VP10E-15WCA | 431 |
| 5962H9475407QYC | E | 09/08/2004 | 1 | UTMC | | Y | UT22VP10E-15WCC | 431 |
| 5962H9475407VYA | E | 09/08/2004 | 1 | UTMC | | Y | UT22VP10E-15WCA | 431 |
| 5962H9475407VYC | E | 09/08/2004 | 1 | UTMC | | Y | UT22VP10E-15WCC | 431 |
| 5962H9475408QLA | E | 09/08/2004 | 1 | UTMC | | Y | UT22VP10T-15PCA | 431 |
| 5962H9475408QLC | E | 09/08/2004 | 1 | UTMC | | Y | UT22VP10T-15PCC | 431 |
| 5962H9475408VLA | E | 09/08/2004 | 1 | UTMC | | Y | UT22VP10T-15PCA | 431 |
| 5962H9475408VLC | E | 09/08/2004 | 1 | UTMC | | Y | UT22VP10T-15PCC | 431 |
| 5962H9475408QXA | E | 09/08/2004 | 1 | UTMC | | Y | UT22VP10T-15UCA | 431 |
| 5962H9475408QXC | E | 09/08/2004 | 1 | UTMC | | Y | UT22VP10T-15UCC | 431 |
| 5962H9475408VXA | E | 09/08/2004 | 1 | UTMC | | Y | UT22VP10T-15UCA | 431 |
| 5962H9475408VXC | E | 09/08/2004 | 1 | UTMC | | Y | UT22VP10T-15UCC | 431 |
| 5962H9475408QYA | E | 09/08/2004 | 1 | UTMC | | Y | UT22VP10T-15WCA | 431 |
| 5962H9475408QYC | E | 09/08/2004 | 1 | UTMC | | Y | UT22VP10T-15WCC | 431 |
| 5962H9475408VYA | E | 09/08/2004 | 1 | UTMC | | Y | UT22VP10T-15WCA | 431 |
| 5962H9475408VYC | E | 09/08/2004 | 1 | UTMC | | Y | UT22VP10T-15WCA | 431 |
| 5962-9475501MPA | B | 11/15/2001 | 1 | ANALOG (3) | | Y | AD7893SQ-10/883B | 592 |
| 5962-9475502MPA | B | 11/15/2001 | 1 | ANALOG (3) | | Y | AD7893SQ-2/883B | 592 |
| 5962-9475601M2A | | 09/09/1994 | | (NONE) | 12/24/2000 | | HFA1135 (GEN) | 751 |
| 5962-9475601MPA | | 09/09/1994 | | (NONE) | 12/24/2000 | | HFA1135 (GEN) | 751 |
| 5962-9475701HXA | A | 06/24/2003 | 1 | DATEL | | Y | ADS-927/883 | 592 |
| 5962-9475701HXC | A | 06/24/2003 | 1 | DATEL | | Y | ADS-927/883 | 592 |
| 5962-9475801QXC | D | 04/11/2001 | | (NONE) | | | 69151XT15 (GEN) | 599 |
| 5962-9475801QYC | D | 04/11/2001 | | (NONE) | | | 69151XT15 (GEN) | 599 |
| 5962-9475802QXC | D | 04/11/2001 | | (NONE) | | | 69151XT5 (GEN) | 599 |
| 5962-9475802QYC | D | 04/11/2001 | | (NONE) | | | 69151XT5 (GEN) | 599 |
| 5962-9475803QXC | D | 04/11/2001 | | (NONE) | | | 69151XT12 (GEN) | 599 |
| 5962-9475803QYC | D | 04/11/2001 | | (NONE) | | | 69151XT12 (GEN) | 599 |
| 5962-9475804QXC | D | 04/11/2001 | | (NONE) | | | 69151XTE15 (GEN) | 599 |
| 5962-9475804QYC | D | 04/11/2001 | | (NONE) | | | 69151XTE15 (GEN) | 599 |
| 5962-9475805QXC | D | 04/11/2001 | | (NONE) | | | 69151XTE5 (GEN) | 599 |
| 5962-9475805QYC | D | 04/11/2001 | | (NONE) | | | 69151XTE5 (GEN) | 599 |
| 5962-9475806QXC | D | 04/11/2001 | | (NONE) | | | 69151XTE12 (GEN) | 599 |
| 5962-9475806QYC | D | 04/11/2001 | | (NONE) | | | 69151XTE12 (GEN) | 599 |
| 5962-9475807QXA | D | 04/11/2001 | 1 | UTMC | | Y | UT69151XTE15/GCA | 599 |
| 5962-9475807QXC | D | 04/11/2001 | 1 | UTMC | | Y | UT69151XTE15/GCC | 599 |
| 5962-9475807QYA | D | 04/11/2001 | 1 | UTMC | | Y | UT69151XTE15/WCA | 599 |
| 5962-9475807QYC | D | 04/11/2001 | 1 | UTMC | | Y | UT69151XTE15/WCC | 599 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9475808QXA | D | 04/11/2001 | 1 | UTMC | | Y | UT69151XTE5/GCA | 599 |
| 5962-9475808QXC | D | 04/11/2001 | 1 | UTMC | | Y | UT69151XTE5/GCC | 599 |
| 5962-9475808QYA | D | 04/11/2001 | 1 | UTMC | | Y | UT69151XTE5/WCA | 599 |
| 5962-9475808QYC | D | 04/11/2001 | 1 | UTMC | | Y | UT69151XTE5/WCC | 599 |
| 5962-9475809QXA | D | 04/11/2001 | 1 | UTMC | | Y | UT69151XTE12/GCA | 599 |
| 5962-9475809QXC | D | 04/11/2001 | 1 | UTMC | | Y | UT69151XTE12/GCC | 599 |
| 5962-9475809QYA | D | 04/11/2001 | 1 | UTMC | | Y | UT69151XTE12/WCA | 599 |
| 5962-9475809QYC | D | 04/11/2001 | 1 | UTMC | | Y | UT69151XTE12/WCC | 599 |
| 5962-9475901MXA | B | 03/04/2002 | 1 | ANALOG (4) | | Y | AD9040ATQ/883B | 592 |
| 5962-9475901MYC | B | 03/04/2002 | | (NONE) | 09/30/2000 | | AD9040A (GEN) | 592 |
| 5962-9476001MXC | A | 04/17/2002 | 2 | LATTICE SEMI | | | PLSI1024-60LH/883 | 431 |
| 5962-9476101MXC | A | 04/17/2002 | 2 | LATTICE SEMI | | | ISPLSI1024-60LH/88 | 431 |
| 5962-9476201MXC | A | 04/18/2002 | 2 | LATTICE SEMI | | | ISPLSI1016-60LH/88 | 431 |
| 5962-9476301MXC | A | 04/22/2002 | 2 | LATTICE SEMI | | | PLSI1016-60LH/883 | 431 |
| 5962-9477101MXB | B | 01/24/2002 | | (NONE) | 01/31/2001 | | SPT7710AM (GEN) | 592 |
| 5962-9477101MYC | B | 01/24/2002 | | (NONE) | 01/31/2001 | | SPT7710AM (GEN) | 592 |
| 5962-9477102MXB | B | 01/24/2002 | | (NONE) | 01/31/2001 | | SPT7710BM (GEN) | 592 |
| 5962-9477102MYC | B | 01/24/2002 | | (NONE) | 01/31/2001 | | SPT7710BM (GEN) | 592 |
| 5962-9477103MXB | B | 01/24/2002 | | (NONE) | 01/31/2001 | | SPT7725AM (GEN) | 592 |
| 5962-9477103MYC | B | 01/24/2002 | | (NONE) | 01/31/2001 | | SPT7725AM (GEN) | 592 |
| 5962-9477104MXB | B | 01/24/2002 | | (NONE) | 01/31/2001 | | SPT7725BM (GEN) | 592 |
| 5962-9477104MYC | B | 01/24/2002 | | (NONE) | 01/31/2001 | | SPT7725BM (GEN) | 592 |
| 5962-9477201HXA | | 07/21/1995 | | (NONE) | | | MHP27005 (GEN) | 594 |
| 5962-9477201HXC | | 07/21/1995 | | (NONE) | | | MHP27005 (GEN) | 594 |
| 5962-9477301QXA | | 01/26/1995 | | (NONE) | 12/31/2001 | | 54FB2031 (GEN) | 429 |
| 5962-9477401HXA | | 12/15/1994 | | (NONE) | | | MN91254 (GEN) | 591 |
| 5962-9477401HXC | | 12/15/1994 | | (NONE) | | | MN91254 (GEN) | 591 |
| 5962-9477402HXA | | 12/15/1994 | | (NONE) | | | MN91253 (GEN) | 591 |
| 5962-9477402HXC | | 12/15/1994 | | (NONE) | | | MN91253 (GEN) | 591 |
| 5962-9477501HXA | | 11/08/1994 | 1 | AEROFLEX | | Y | CT1990-1-20 | 420 |
| 5962-9477501HXC | | 11/08/1994 | 1 | AEROFLEX | | Y | CT1990-1-20 | 420 |
| 5962-94A0201MYC | A | 09/30/1994 | | (NONE) | | | L1A8274 (GEN) | 365 |
| 5962H94A0301QTC | C | 04/02/1998 | | (NONE) | 06/30/1999 | | HR2125 (GEN) | 365 |
| 5962H94A0301VTC | C | 04/02/1998 | | (NONE) | 06/30/1999 | | HR2125 (GEN) | 365 |
| 5962H94A0301QUC | C | 04/02/1998 | | (NONE) | 06/30/1999 | | HR2125 (GEN) | 365 |
| 5962H94A0301VUC | C | 04/02/1998 | | (NONE) | 06/30/1999 | | HR2125 (GEN) | 365 |
| 5962H94A0301QYC | C | 04/02/1998 | | (NONE) | 06/30/1999 | | HR2125 (GEN) | 365 |
| 5962H94A0301VYC | C | 04/02/1998 | | (NONE) | 06/30/1999 | | HR2125 (GEN) | 365 |
| 5962H94A0302QTC | C | 04/02/1998 | | (NONE) | 06/30/1999 | | HR2210 (GEN) | 365 |
| 5962H94A0302VTC | C | 04/02/1998 | | (NONE) | 06/30/1999 | | HR2210 (GEN) | 365 |
| 5962H94A0302QUC | C | 04/02/1998 | | (NONE) | 06/30/1999 | | HR2210 (GEN) | 365 |
| 5962H94A0302VUC | C | 04/02/1998 | | (NONE) | 06/30/1999 | | HR2210 (GEN) | 365 |
| 5962H94A0302QXC | C | 04/02/1998 | | (NONE) | 06/30/1999 | | HR2210 (GEN) | 365 |
| 5962H94A0302VXC | C | 04/02/1998 | | (NONE) | 06/30/1999 | | HR2210 (GEN) | 365 |
| 5962H94A0302QYC | C | 04/02/1998 | | (NONE) | 06/30/1999 | | HR2210 (GEN) | 365 |
| 5962H94A0302VYC | C | 04/02/1998 | | (NONE) | 06/30/1999 | | HR2210 (GEN) | 365 |
| 5962H94A0303QMC | C | 04/02/1998 | | (NONE) | 06/30/1999 | | HR2340 (GEN) | 365 |
| 5962H94A0303VMC | C | 04/02/1998 | | (NONE) | 06/30/1999 | | HR2340 (GEN) | 365 |
| 5962H94A0303QTC | C | 04/02/1998 | | (NONE) | 06/30/1999 | | HR2340 (GEN) | 365 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962H94A0303VTC | C | 04/02/1998 | | (NONE) | 06/30/1999 | | HR2340 (GEN) | 365 |
| 5962H94A0304Q5C | C | 04/02/1998 | | (NONE) | 06/30/1999 | | HR2010 (GEN) | 365 |
| 5962H94A0304V5C | C | 04/02/1998 | | (NONE) | 06/30/1999 | | HR2010 (GEN) | 365 |
| 5962H94A0304Q7C | C | 04/02/1998 | | (NONE) | 06/30/1999 | | HR2010 (GEN) | 365 |
| 5962H94A0304V7C | C | 04/02/1998 | | (NONE) | 06/30/1999 | | HR2010 (GEN) | 365 |
| 5962H94A0304QNC | C | 04/02/1998 | | (NONE) | 06/30/1999 | | HR2010 (GEN) | 365 |
| 5962H94A0304VNC | C | 04/02/1998 | | (NONE) | 06/30/1999 | | HR2010 (GEN) | 365 |
| 5962H94A0305Q4C | C | 04/02/1998 | | (NONE) | 06/30/1999 | | HR2065 (GEN) | 365 |
| 5962H94A0305V4C | C | 04/02/1998 | | (NONE) | 06/30/1999 | | HR2065 (GEN) | 365 |
| 5962H94A0305Q6C | C | 04/02/1998 | | (NONE) | 06/30/1999 | | HR2065 (GEN) | 365 |
| 5962H94A0305V6C | C | 04/02/1998 | | (NONE) | 06/30/1999 | | HR2065 (GEN) | 365 |
| 5962H94A0305Q8C | C | 04/02/1998 | | (NONE) | 06/30/1999 | | HR2065 (GEN) | 365 |
| 5962H94A0305V8C | C | 04/02/1998 | | (NONE) | 06/30/1999 | | HR2065 (GEN) | 365 |
| 5962H94A0305QZC | C | 04/02/1998 | | (NONE) | 06/30/1999 | | HR2065 (GEN) | 365 |
| 5962H94A0305VZC | C | 04/02/1998 | | (NONE) | 06/30/1999 | | HR2065 (GEN) | 365 |
| 5962H94A0306QTC | C | 04/02/1998 | | (NONE) | 06/30/1999 | | HR2090 (GEN) | 365 |
| 5962H94A0306VTC | C | 04/02/1998 | | (NONE) | 06/30/1999 | | HR2090 (GEN) | 365 |
| 5962H94A0901QYC | | 07/12/1994 | | (NONE) | | | 22009751-007 (GEN) | 421 |
| 5962H94A0901VYC | | 07/12/1994 | | (NONE) | | | 22009751-007 (GEN) | 421 |
| 5962-94A1101QXC | | 06/21/1994 | 1 | AMI | | Y | 9866-055 | 421 |
| 5962-94A1201MYA | A | 02/02/1995 | | TI | | | CF99004HFG | 365 |
| 5962-94A1401MXA | | 10/03/1995 | | (NONE) | 02/28/1998 | | 66111 (GEN) | 432 |
| 5962-94A1501MXA | | 10/03/1995 | | (NONE) | 02/28/1998 | | 66212 (GEN) | 420 |
| 5962-94A1601MXA | | 10/04/1995 | | (NONE) | 02/28/1998 | | 66311 (GEN) | 429 |
| 5962-94A1701QXC | A | 02/07/1995 | 1 | AMI | | Y | 9862-079 | 399 |
| 5962-94A1801QXA | A | 11/14/1994 | 1 | AMI | | Y | 9862-075 | 365 |
| 5962-94A1901QXA | B | 10/10/1996 | 1 | AMI | | Y | 9862-076 | 365 |
| 5962H94A2001QXC | | 11/02/1994 | | (NONE) | | | 22017140-005 (GEN) | 599 |
| 5962H94A2101QYC | | 11/16/1994 | | (NONE) | | | 22017253-008 (GEN) | 365 |
| 5962-94B0201MTA | B | 03/07/1995 | | (NONE) | | | 5341-035 (GEN) | 365 |
| 5962-94B0201QTA | B | 03/07/1995 | 1 | AMI | | Y | 5341-035 | 365 |
| 5962-94B0201MUA | B | 03/07/1995 | | (NONE) | | | 5352-037 (GEN) | 365 |
| 5962-94B0201QUA | B | 03/07/1995 | 1 | AMI | | Y | 5352-037 | 365 |
| 5962-94B0201QXA | B | 03/07/1995 | | (NONE) | | | 500/700J (GEN) | 365 |
| 5962-94B0201MYA | B | 03/07/1995 | | (NONE) | | | 6580-502 (GEN) | 365 |
| 5962-94B0201MYA | B | 03/07/1995 | | (NONE) | | | 5342-031 (GEN) | 365 |
| 5962-94B0201QYA | B | 03/07/1995 | 1 | AMI | | Y | 6580-502 | 365 |
| 5962-94B0201QYA | B | 03/07/1995 | 1 | AMI | | Y | 5342-031 | 365 |
| 5962-94B0201MZA | B | 03/07/1995 | | (NONE) | | | 5344-021 (GEN) | 365 |
| 5962-94B0201QZA | B | 03/07/1995 | 1 | AMI | | Y | 5344-021 | 365 |
| 5962-94B0301M4C | | 08/31/1994 | | (NONE) | | | LCA100 (GEN) | 365 |
| 5962-94B0301M5C | | 08/31/1994 | | (NONE) | | | LCA100 (GEN) | 365 |
| 5962-94B0301M6C | | 08/31/1994 | | (NONE) | | | LCA100 (GEN) | 365 |
| 5962-94B0301M7C | | 08/31/1994 | | (NONE) | | | LCA100 (GEN) | 365 |
| 5962-94B0301M8C | | 08/31/1994 | | (NONE) | | | LCA100 (GEN) | 365 |
| 5962-94B0301M9C | | 08/31/1994 | | (NONE) | | | LCA100 (GEN) | 365 |
| 5962-94B0301MCC | | 08/31/1994 | | (NONE) | | | LCA100 (GEN) | 365 |
| 5962-94B0301MMC | | 08/31/1994 | | (NONE) | | | LCA100 (GEN) | 365 |
| 5962-94B0301MNC | | 08/31/1994 | | (NONE) | | | LCA100 (GEN) | 365 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-94B0301MTC | | 08/31/1994 | | (NONE) | | | LCA100 (GEN) | 365 |
| 5962-94B0301MUC | | 08/31/1994 | | (NONE) | | | LCA100 (GEN) | 365 |
| 5962-94B0301MXC | | 08/31/1994 | | (NONE) | | | LCA100 (GEN) | 365 |
| 5962-94B0301MYC | | 08/31/1994 | | (NONE) | | | LCA100 (GEN) | 365 |
| 5962-94B0301MZC | | 08/31/1994 | | (NONE) | | | LCA100 (GEN) | 365 |
| 5962-94B0302M4C | | 08/31/1994 | | (NONE) | | | LCB007 (GEN) | 365 |
| 5962-94B0302M5C | | 08/31/1994 | | (NONE) | | | LCB007 (GEN) | 365 |
| 5962-94B0302M6C | | 08/31/1994 | | (NONE) | | | LCB007 (GEN) | 365 |
| 5962-94B0302M7C | | 08/31/1994 | | (NONE) | | | LCB007 (GEN) | 365 |
| 5962-94B0302M8C | | 08/31/1994 | | (NONE) | | | LCB007 (GEN) | 365 |
| 5962-94B0302M9C | | 08/31/1994 | | (NONE) | | | LCB007 (GEN) | 365 |
| 5962-94B0302MCC | | 08/31/1994 | | (NONE) | | | LCB007 (GEN) | 365 |
| 5962-94B0302MMC | | 08/31/1994 | | (NONE) | | | LCB007 (GEN) | 365 |
| 5962-94B0302MNC | | 08/31/1994 | | (NONE) | | | LCB007 (GEN) | 365 |
| 5962-94B0302MTC | | 08/31/1994 | | (NONE) | | | LCB007 (GEN) | 365 |
| 5962-94B0302MUC | | 08/31/1994 | | (NONE) | | | LCB007 (GEN) | 365 |
| 5962-94B0302MXC | | 08/31/1994 | | (NONE) | | | LCB007 (GEN) | 365 |
| 5962-94B0302MYC | | 08/31/1994 | | (NONE) | | | LCB007 (GEN) | 365 |
| 5962-94B0302MZC | | 08/31/1994 | | (NONE) | | | LCB007 (GEN) | 365 |
| 5962-94B0303M4C | | 08/31/1994 | | (NONE) | | | LEA100 (GEN) | 365 |
| 5962-94B0303M5C | | 08/31/1994 | | (NONE) | | | LEA100 (GEN) | 365 |
| 5962-94B0303M6C | | 08/31/1994 | | (NONE) | | | LEA100 (GEN) | 365 |
| 5962-94B0303M7C | | 08/31/1994 | | (NONE) | | | LEA100 (GEN) | 365 |
| 5962-94B0303M8C | | 08/31/1994 | | (NONE) | | | LEA100 (GEN) | 365 |
| 5962-94B0303M9C | | 08/31/1994 | | (NONE) | | | LEA100 (GEN) | 365 |
| 5962-94B0303MCC | | 08/31/1994 | | (NONE) | | | LEA100 (GEN) | 365 |
| 5962-94B0303MMC | | 08/31/1994 | | (NONE) | | | LEA100 (GEN) | 365 |
| 5962-94B0303MNC | | 08/31/1994 | | (NONE) | | | LEA100 (GEN) | 365 |
| 5962-94B0303MTC | | 08/31/1994 | | (NONE) | | | LEA100 (GEN) | 365 |
| 5962-94B0303MUC | | 08/31/1994 | | (NONE) | | | LEA100 (GEN) | 365 |
| 5962-94B0303MXC | | 08/31/1994 | | (NONE) | | | LEA100 (GEN) | 365 |
| 5962-94B0303MYC | | 08/31/1994 | | (NONE) | | | LEA100 (GEN) | 365 |
| 5962-94B0303MZC | | 08/31/1994 | | (NONE) | | | LEA100 (GEN) | 365 |
| 5962-94B0406MXA | | 10/11/1994 | | (NONE) | 05/20/1997 | | VGC450 (GEN) | 367 |
| 5962-94B0407MMA | | 10/11/1994 | | (NONE) | 05/20/1997 | | VGC450 (GEN) | 367 |
| 5962-94B0407MXA | | 10/11/1994 | | (NONE) | 05/20/1997 | | VGC450 (GEN) | 367 |
| 5962-94B0408MMA | | 10/11/1994 | | (NONE) | 05/20/1997 | | VGC450 (GEN) | 367 |
| 5962-94B0408MYA | | 10/11/1994 | | (NONE) | 05/20/1997 | | VGC450 (GEN) | 367 |
| 5962-94B0409MYA | | 10/11/1994 | | (NONE) | 05/20/1997 | | VGC450 (GEN) | 367 |
| 5962-94B0410MXA | | 10/11/1994 | | (NONE) | 05/20/1997 | | VGC450 (GEN) | 367 |
| 5962-94B0410MYA | | 10/11/1994 | | (NONE) | 05/20/1997 | | VGC450 (GEN) | 367 |
| 5962-94B0411MXA | | 10/11/1994 | | (NONE) | 05/20/1997 | | VGC450 (GEN) | 367 |
| 5962-94B0411MYA | | 10/11/1994 | | (NONE) | 05/20/1997 | | VGC450 (GEN) | 367 |
| 5962-94B0411MZA | | 10/11/1994 | | (NONE) | 05/20/1997 | | VGC450 (GEN) | 367 |
| 5962-94B0412MMA | | 10/11/1994 | | (NONE) | 05/20/1997 | | VGC450 (GEN) | 367 |
| 5962-94B0412MYA | | 10/11/1994 | | (NONE) | 05/20/1997 | | VGC450 (GEN) | 367 |
| 5962-94B0412MZA | | 10/11/1994 | | (NONE) | 05/20/1997 | | VGC450 (GEN) | 367 |
| 5962-94B0413M9C | | 10/11/1994 | | (NONE) | 05/20/1997 | | VGC450 (GEN) | 367 |
| 5962-94B0413MMA | | 10/11/1994 | | (NONE) | 05/20/1997 | | VGC450 (GEN) | 367 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-94B0413MNC | | 10/11/1994 | | (NONE) | 05/20/1997 | | VGC450 (GEN) | 367 |
| 5962-94B0413MTA | | 10/11/1994 | | (NONE) | 05/20/1997 | | VGC450 (GEN) | 367 |
| 5962-94B0413MYA | | 10/11/1994 | | (NONE) | 05/20/1997 | | VGC450 (GEN) | 367 |
| 5962-94B0414M9C | | 10/11/1994 | | (NONE) | 05/20/1997 | | VGC450 (GEN) | 367 |
| 5962-94B0414MTA | | 10/11/1994 | | (NONE) | 05/20/1997 | | VGC450 (GEN) | 367 |
| 5962-94B0414MXA | | 10/11/1994 | | (NONE) | 05/20/1997 | | VGC450 (GEN) | 367 |
| 5962-94B0414MYA | | 10/11/1994 | | (NONE) | 05/20/1997 | | VGC450 (GEN) | 367 |
| 5962-94B0414MZA | | 10/11/1994 | | (NONE) | 05/20/1997 | | VGC450 (GEN) | 367 |
| 5962-94B0415MUC | | 10/11/1994 | | (NONE) | 05/20/1997 | | VGC450 (GEN) | 367 |
| 5962-94B0416MTA | | 10/11/1994 | | (NONE) | 05/20/1997 | | VGC450 (GEN) | 367 |
| 5962-94B0416MUC | | 10/11/1994 | | (NONE) | 05/20/1997 | | VGC450 (GEN) | 367 |
| 5962-94B0416MXA | | 10/11/1994 | | (NONE) | 05/20/1997 | | VGC450 (GEN) | 367 |
| 5962-94B0416MYA | | 10/11/1994 | | (NONE) | 05/20/1997 | | VGC450 (GEN) | 367 |
| 5962-94B0416MZA | | 10/11/1994 | | (NONE) | 05/20/1997 | | VGC450 (GEN) | 367 |
| 5962-94B0422MXA | | 10/11/1994 | | (NONE) | 05/20/1997 | | VGC453 (GEN) | 367 |
| 5962-94B0423MMA | | 10/11/1994 | | (NONE) | 05/20/1997 | | VGC453 (GEN) | 367 |
| 5962-94B0423MXA | | 10/11/1994 | | (NONE) | 05/20/1997 | | VGC453 (GEN) | 367 |
| 5962-94B0424MMA | | 10/11/1994 | | (NONE) | 05/20/1997 | | VGC453 (GEN) | 367 |
| 5962-94B0424MYA | | 10/11/1994 | | (NONE) | 05/20/1997 | | VGC453 (GEN) | 367 |
| 5962-94B0425MYA | | 10/11/1994 | | (NONE) | 05/20/1997 | | VGC453 (GEN) | 367 |
| 5962-94B0426MXA | | 10/11/1994 | | (NONE) | 05/20/1997 | | VGC453 (GEN) | 367 |
| 5962-94B0426MYA | | 10/11/1994 | | (NONE) | 05/20/1997 | | VGC453 (GEN) | 367 |
| 5962-94B0427MXA | | 10/11/1994 | | (NONE) | 05/20/1997 | | VGC453 (GEN) | 367 |
| 5962-94B0427MYA | | 10/11/1994 | | (NONE) | 05/20/1997 | | VGC453 (GEN) | 367 |
| 5962-94B0427MZA | | 10/11/1994 | | (NONE) | 05/20/1997 | | VGC453 (GEN) | 367 |
| 5962-94B0428MMA | | 10/11/1994 | | (NONE) | 05/20/1997 | | VGC453 (GEN) | 367 |
| 5962-94B0428MYA | | 10/11/1994 | | (NONE) | 05/20/1997 | | VGC453 (GEN) | 367 |
| 5962-94B0428MZA | | 10/11/1994 | | (NONE) | 05/20/1997 | | VGC453 (GEN) | 367 |
| 5962-94B0429M9C | | 10/11/1994 | | (NONE) | 05/20/1997 | | VGC453 (GEN) | 367 |
| 5962-94B0429MMA | | 10/11/1994 | | (NONE) | 05/20/1997 | | VGC453 (GEN) | 367 |
| 5962-94B0429MNC | | 10/11/1994 | | (NONE) | 05/20/1997 | | VGC453 (GEN) | 367 |
| 5962-94B0429MTA | | 10/11/1994 | | (NONE) | 05/20/1997 | | VGC453 (GEN) | 367 |
| 5962-94B0429MYA | | 10/11/1994 | | (NONE) | 05/20/1997 | | VGC453 (GEN) | 367 |
| 5962-94B0430M9C | | 10/11/1994 | | (NONE) | 05/20/1997 | | VGC453 (GEN) | 367 |
| 5962-94B0430MTA | | 10/11/1994 | | (NONE) | 05/20/1997 | | VGC453 (GEN) | 367 |
| 5962-94B0430MXA | | 10/11/1994 | | (NONE) | 05/20/1997 | | VGC453 (GEN) | 367 |
| 5962-94B0430MYA | | 10/11/1994 | | (NONE) | 05/20/1997 | | VGC453 (GEN) | 367 |
| 5962-94B0430MZA | | 10/11/1994 | | (NONE) | 05/20/1997 | | VGC453 (GEN) | 367 |
| 5962-94B0431MUC | | 10/11/1994 | | (NONE) | 05/20/1997 | | VGC453 (GEN) | 367 |
| 5962-94B0432MTA | | 10/11/1994 | | (NONE) | 05/20/1997 | | VGC453 (GEN) | 367 |
| 5962-94B0432MUC | | 10/11/1994 | | (NONE) | 05/20/1997 | | VGC453 (GEN) | 367 |
| 5962-94B0432MXA | | 10/11/1994 | | (NONE) | 05/20/1997 | | VGC453 (GEN) | 367 |
| 5962-94B0432MYA | | 10/11/1994 | | (NONE) | 05/20/1997 | | VGC453 (GEN) | 367 |
| 5962-94B0432MZA | | 10/11/1994 | | (NONE) | 05/20/1997 | | VGC453 (GEN) | 367 |
| 5962-94B0501Q4A | C | 03/06/1997 | | TI | | Y | TGC1010 | 365 |
| 5962-94B0501Q5A | C | 03/06/1997 | | TI | | Y | TGC1010 | 365 |
| 5962-94B0501Q6A | C | 03/06/1997 | | TI | | Y | TGC1010 | 365 |
| 5962-94B0501QMA | C | 03/06/1997 | | TI | | Y | TGC1010 | 365 |
| 5962-94B0501QNA | C | 03/06/1997 | | TI | | Y | TGC1010 | 365 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-94B0501QTA | C | 03/06/1997 | | TI | | Y | TGC1010 | 365 |
| 5962-94B0501QUA | C | 03/06/1997 | | TI | | Y | TGC1010 | 365 |
| 5962-94B0501QXA | C | 03/06/1997 | | TI | | Y | TGC1010 | 365 |
| 5962-94B0501QYA | C | 03/06/1997 | | TI | | Y | TGC1010 | 365 |
| 5962-94B0501QZA | C | 03/06/1997 | | TI | | Y | TGC1010 | 365 |
| 5962-94B0502Q4A | C | 03/06/1997 | | TI | | Y | TGC1016 | 365 |
| 5962-94B0502Q5A | C | 03/06/1997 | | TI | | Y | TGC1016 | 365 |
| 5962-94B0502Q6A | C | 03/06/1997 | | TI | | Y | TGC1016 | 365 |
| 5962-94B0502QMA | C | 03/06/1997 | | TI | | Y | TGC1016 | 365 |
| 5962-94B0502QNA | C | 03/06/1997 | | TI | | Y | TGC1016 | 365 |
| 5962-94B0502QTA | C | 03/06/1997 | | TI | | Y | TGC1016 | 365 |
| 5962-94B0502QUA | C | 03/06/1997 | | TI | | Y | TGC1016 | 365 |
| 5962-94B0502QXA | C | 03/06/1997 | | TI | | Y | TGC1016 | 365 |
| 5962-94B0502QYA | C | 03/06/1997 | | TI | | Y | TGC1016 | 365 |
| 5962-94B0502QZA | C | 03/06/1997 | | TI | | Y | TGC1016 | 365 |
| 5962-94B0503Q4A | C | 03/06/1997 | | TI | | Y | TGC1019 | 365 |
| 5962-94B0503Q5A | C | 03/06/1997 | | TI | | Y | TGC1019 | 365 |
| 5962-94B0503Q6A | C | 03/06/1997 | | TI | | Y | TGC1019 | 365 |
| 5962-94B0503QMA | C | 03/06/1997 | | TI | | Y | TGC1019 | 365 |
| 5962-94B0503QNA | C | 03/06/1997 | | TI | | Y | TGC1019 | 365 |
| 5962-94B0503QTA | C | 03/06/1997 | | TI | | Y | TGC1019 | 365 |
| 5962-94B0503QUA | C | 03/06/1997 | | TI | | Y | TGC1019 | 365 |
| 5962-94B0503QXA | C | 03/06/1997 | | TI | | Y | TGC1019 | 365 |
| 5962-94B0503QYA | C | 03/06/1997 | | TI | | Y | TGC1019 | 365 |
| 5962-94B0503QZA | C | 03/06/1997 | | TI | | Y | TGC1019 | 365 |
| 5962-94B0504Q4A | C | 03/06/1997 | | TI | | Y | TGC1030 | 365 |
| 5962-94B0504Q5A | C | 03/06/1997 | | TI | | Y | TGC1030 | 365 |
| 5962-94B0504Q6A | C | 03/06/1997 | | TI | | Y | TGC1030 | 365 |
| 5962-94B0504QMA | C | 03/06/1997 | | TI | | Y | TGC1030 | 365 |
| 5962-94B0504QNA | C | 03/06/1997 | | TI | | Y | TGC1030 | 365 |
| 5962-94B0504QTA | C | 03/06/1997 | | TI | | Y | TGC1030 | 365 |
| 5962-94B0504QUA | C | 03/06/1997 | | TI | | Y | TGC1030 | 365 |
| 5962-94B0504QXA | C | 03/06/1997 | | TI | | Y | TGC1030 | 365 |
| 5962-94B0504QYA | C | 03/06/1997 | | TI | | Y | TGC1030 | 365 |
| 5962-94B0504QZA | C | 03/06/1997 | | TI | | Y | TGC1030 | 365 |
| 5962-94B0505Q4A | C | 03/06/1997 | | TI | | Y | TGC1036 | 365 |
| 5962-94B0505Q5A | C | 03/06/1997 | | TI | | Y | TGC1036 | 365 |
| 5962-94B0505Q6A | C | 03/06/1997 | | TI | | Y | TGC1036 | 365 |
| 5962-94B0505QMA | C | 03/06/1997 | | TI | | Y | TGC1036 | 365 |
| 5962-94B0505QNA | C | 03/06/1997 | | TI | | Y | TGC1036 | 365 |
| 5962-94B0505QTA | C | 03/06/1997 | | TI | | Y | TGC1036 | 365 |
| 5962-94B0505QUA | C | 03/06/1997 | | TI | | Y | TGC1036 | 365 |
| 5962-94B0505QXA | C | 03/06/1997 | | TI | | Y | TGC1036 | 365 |
| 5962-94B0505QYA | C | 03/06/1997 | | TI | | Y | TGC1036 | 365 |
| 5962-94B0505QZA | C | 03/06/1997 | | TI | | Y | TGC1036 | 365 |
| 5962-94B0506Q4A | C | 03/06/1997 | | TI | | Y | TGC1046 | 365 |
| 5962-94B0506Q5A | C | 03/06/1997 | | TI | | Y | TGC1046 | 365 |
| 5962-94B0506Q6A | C | 03/06/1997 | | TI | | Y | TGC1046 | 365 |
| 5962-94B0506QMA | C | 03/06/1997 | | TI | | Y | TGC1046 | 365 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-94B0506QNA | C | 03/06/1997 | | TI | | Y | TGC1046 | 365 |
| 5962-94B0506QTA | C | 03/06/1997 | | TI | | Y | TGC1046 | 365 |
| 5962-94B0506QUA | C | 03/06/1997 | | TI | | Y | TGC1046 | 365 |
| 5962-94B0506QXA | C | 03/06/1997 | | TI | | Y | TGC1046 | 365 |
| 5962-94B0506QYA | C | 03/06/1997 | | TI | | Y | TGC1046 | 365 |
| 5962-94B0506QZA | C | 03/06/1997 | | TI | | Y | TGC1046 | 365 |
| 5962-94B0507Q4A | C | 03/06/1997 | | TI | | Y | TGC1053 | 365 |
| 5962-94B0507Q5A | C | 03/06/1997 | | TI | | Y | TGC1053 | 365 |
| 5962-94B0507Q6A | C | 03/06/1997 | | TI | | Y | TGC1053 | 365 |
| 5962-94B0507QMA | C | 03/06/1997 | | TI | | Y | TGC1053 | 365 |
| 5962-94B0507QNA | C | 03/06/1997 | | TI | | Y | TGC1053 | 365 |
| 5962-94B0507QTA | C | 03/06/1997 | | TI | | Y | TGC1053 | 365 |
| 5962-94B0507QUA | C | 03/06/1997 | | TI | | Y | TGC1053 | 365 |
| 5962-94B0507QXA | C | 03/06/1997 | | TI | | Y | TGC1053 | 365 |
| 5962-94B0507QYA | C | 03/06/1997 | | TI | | Y | TGC1053 | 365 |
| 5962-94B0507QZA | C | 03/06/1997 | | TI | | Y | TGC1053 | 365 |
| 5962-94B0508Q4A | C | 03/06/1997 | | TI | | Y | TGC1068 | 365 |
| 5962-94B0508Q5A | C | 03/06/1997 | | TI | | Y | TGC1068 | 365 |
| 5962-94B0508Q6A | C | 03/06/1997 | | TI | | Y | TGC1068 | 365 |
| 5962-94B0508QMA | C | 03/06/1997 | | TI | | Y | TGC1068 | 365 |
| 5962-94B0508QNA | C | 03/06/1997 | | TI | | Y | TGC1068 | 365 |
| 5962-94B0508QTA | C | 03/06/1997 | | TI | | Y | TGC1068 | 365 |
| 5962-94B0508QUA | C | 03/06/1997 | | TI | | Y | TGC1068 | 365 |
| 5962-94B0508QXA | C | 03/06/1997 | | TI | | Y | TGC1068 | 365 |
| 5962-94B0508QYA | C | 03/06/1997 | | TI | | Y | TGC1068 | 365 |
| 5962-94B0508QZA | C | 03/06/1997 | | TI | | Y | TGC1068 | 365 |
| 5962-94B0509Q4A | C | 03/06/1997 | | TI | | Y | TGC1086 | 365 |
| 5962-94B0509Q5A | C | 03/06/1997 | | TI | | Y | TGC1086 | 365 |
| 5962-94B0509Q6A | C | 03/06/1997 | | TI | | Y | TGC1086 | 365 |
| 5962-94B0509QMA | C | 03/06/1997 | | TI | | Y | TGC1086 | 365 |
| 5962-94B0509QNA | C | 03/06/1997 | | TI | | Y | TGC1086 | 365 |
| 5962-94B0509QTA | C | 03/06/1997 | | TI | | Y | TGC1086 | 365 |
| 5962-94B0509QUA | C | 03/06/1997 | | TI | | Y | TGC1086 | 365 |
| 5962-94B0509QXA | C | 03/06/1997 | | TI | | Y | TGC1086 | 365 |
| 5962-94B0509QYA | C | 03/06/1997 | | TI | | Y | TGC1086 | 365 |
| 5962-94B0509QZA | C | 03/06/1997 | | TI | | Y | TGC1086 | 365 |
| 5962-94B0510Q4A | C | 03/06/1997 | | TI | | Y | TGC1113 | 365 |
| 5962-94B0510Q5A | C | 03/06/1997 | | TI | | Y | TGC1113 | 365 |
| 5962-94B0510Q6A | C | 03/06/1997 | | TI | | Y | TGC1113 | 365 |
| 5962-94B0510QMA | C | 03/06/1997 | | TI | | Y | TGC1113 | 365 |
| 5962-94B0510QNA | C | 03/06/1997 | | TI | | Y | TGC1113 | 365 |
| 5962-94B0510QTA | C | 03/06/1997 | | TI | | Y | TGC1113 | 365 |
| 5962-94B0510QUA | C | 03/06/1997 | | TI | | Y | TGC1113 | 365 |
| 5962-94B0510QXA | C | 03/06/1997 | | TI | | Y | TGC1113 | 365 |
| 5962-94B0510QYA | C | 03/06/1997 | | TI | | Y | TGC1113 | 365 |
| 5962-94B0510QZA | C | 03/06/1997 | | TI | | Y | TGC1113 | 365 |
| 5962-94B0511Q4A | C | 03/06/1997 | | TI | | Y | TGC1154 | 365 |
| 5962-94B0511Q5A | C | 03/06/1997 | | TI | | Y | TGC1154 | 365 |
| 5962-94B0511Q6A | C | 03/06/1997 | | TI | | Y | TGC1154 | 365 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-94B0511QMA | C | 03/06/1997 | | TI | | Y | TGC1154 | 365 |
| 5962-94B0511QNA | C | 03/06/1997 | | TI | | Y | TGC1154 | 365 |
| 5962-94B0511QTA | C | 03/06/1997 | | TI | | Y | TGC1154 | 365 |
| 5962-94B0511QUA | C | 03/06/1997 | | TI | | Y | TGC1154 | 365 |
| 5962-94B0511QXA | C | 03/06/1997 | | TI | | Y | TGC1154 | 365 |
| 5962-94B0511QYA | C | 03/06/1997 | | TI | | Y | TGC1154 | 365 |
| 5962-94B0511QZA | C | 03/06/1997 | | TI | | Y | TGC1154 | 365 |
| 5962-94B0512Q4A | C | 03/06/1997 | | TI | | Y | TGC1191 | 365 |
| 5962-94B0512Q5A | C | 03/06/1997 | | TI | | Y | TGC1191 | 365 |
| 5962-94B0512Q6A | C | 03/06/1997 | | TI | | Y | TGC1191 | 365 |
| 5962-94B0512QMA | C | 03/06/1997 | | TI | | Y | TGC1191 | 365 |
| 5962-94B0512QNA | C | 03/06/1997 | | TI | | Y | TGC1191 | 365 |
| 5962-94B0512QTA | C | 03/06/1997 | | TI | | Y | TGC1191 | 365 |
| 5962-94B0512QUA | C | 03/06/1997 | | TI | | Y | TGC1191 | 365 |
| 5962-94B0512QXA | C | 03/06/1997 | | TI | | Y | TGC1191 | 365 |
| 5962-94B0512QYA | C | 03/06/1997 | | TI | | Y | TGC1191 | 365 |
| 5962-94B0512QZA | C | 03/06/1997 | | TI | | Y | TGC1191 | 365 |
| 5962-94B0513Q4A | C | 03/06/1997 | | TI | | Y | TGC1245 | 365 |
| 5962-94B0513Q5A | C | 03/06/1997 | | TI | | Y | TGC1245 | 365 |
| 5962-94B0513Q6A | C | 03/06/1997 | | TI | | Y | TGC1245 | 365 |
| 5962-94B0513QMA | C | 03/06/1997 | | TI | | Y | TGC1245 | 365 |
| 5962-94B0513QNA | C | 03/06/1997 | | TI | | Y | TGC1245 | 365 |
| 5962-94B0513QTA | C | 03/06/1997 | | TI | | Y | TGC1245 | 365 |
| 5962-94B0513QUA | C | 03/06/1997 | | TI | | Y | TGC1245 | 365 |
| 5962-94B0513QXA | C | 03/06/1997 | | TI | | Y | TGC1245 | 365 |
| 5962-94B0513QYA | C | 03/06/1997 | | TI | | Y | TGC1245 | 365 |
| 5962-94B0513QZA | C | 03/06/1997 | | TI | | Y | TGC1245 | 365 |
| 5962-94B0601M4C | | 09/14/1994 | | (NONE) | | | LCA300 (GEN) | 365 |
| 5962-94B0601M5C | | 09/14/1994 | | (NONE) | | | LCA300 (GEN) | 365 |
| 5962-94B0601M6C | | 09/14/1994 | | (NONE) | | | LCA300 (GEN) | 365 |
| 5962-94B0601M7C | | 09/14/1994 | | (NONE) | | | LCA300 (GEN) | 365 |
| 5962-94B0601M8C | | 09/14/1994 | | (NONE) | | | LCA300 (GEN) | 365 |
| 5962-94B0601M9C | | 09/14/1994 | | (NONE) | | | LCA300 (GEN) | 365 |
| 5962-94B0601MCC | | 09/14/1994 | | (NONE) | | | LCA300 (GEN) | 365 |
| 5962-94B0601MMC | | 09/14/1994 | | (NONE) | | | LCA300 (GEN) | 365 |
| 5962-94B0601MNC | | 09/14/1994 | | (NONE) | | | LCA300 (GEN) | 365 |
| 5962-94B0601MTC | | 09/14/1994 | | (NONE) | | | LCA300 (GEN) | 365 |
| 5962-94B0601MUC | | 09/14/1994 | | (NONE) | | | LCA300 (GEN) | 365 |
| 5962-94B0601MXC | | 09/14/1994 | | (NONE) | | | LCA300 (GEN) | 365 |
| 5962-94B0601MYC | | 09/14/1994 | | (NONE) | | | LCA300 (GEN) | 365 |
| 5962-94B0601MZC | | 09/14/1994 | | (NONE) | | | LCA300 (GEN) | 365 |
| 5962-94B0602M4C | | 09/14/1994 | | (NONE) | | | LCA310 (GEN) | 365 |
| 5962-94B0602M5C | | 09/14/1994 | | (NONE) | | | LCA310 (GEN) | 365 |
| 5962-94B0602M6C | | 09/14/1994 | | (NONE) | | | LCA310 (GEN) | 365 |
| 5962-94B0602M7C | | 09/14/1994 | | (NONE) | | | LCA310 (GEN) | 365 |
| 5962-94B0602M8C | | 09/14/1994 | | (NONE) | | | LCA310 (GEN) | 365 |
| 5962-94B0602M9C | | 09/14/1994 | | (NONE) | | | LCA310 (GEN) | 365 |
| 5962-94B0602MCC | | 09/14/1994 | | (NONE) | | | LCA310 (GEN) | 365 |
| 5962-94B0602MMC | | 09/14/1994 | | (NONE) | | | LCA310 (GEN) | 365 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-94B0602MNC | | 09/14/1994 | | (NONE) | | | LCA310 (GEN) | 365 |
| 5962-94B0602MTC | | 09/14/1994 | | (NONE) | | | LCA310 (GEN) | 365 |
| 5962-94B0602MUC | | 09/14/1994 | | (NONE) | | | LCA310 (GEN) | 365 |
| 5962-94B0602MXC | | 09/14/1994 | | (NONE) | | | LCA310 (GEN) | 365 |
| 5962-94B0602MYC | | 09/14/1994 | | (NONE) | | | LCA310 (GEN) | 365 |
| 5962-94B0602MZC | | 09/14/1994 | | (NONE) | | | LCA310 (GEN) | 365 |
| 5962-94B0603M4C | | 09/14/1994 | | (NONE) | | | LCB300 (GEN) | 365 |
| 5962-94B0603M5C | | 09/14/1994 | | (NONE) | | | LCB300 (GEN) | 365 |
| 5962-94B0603M6C | | 09/14/1994 | | (NONE) | | | LCB300 (GEN) | 365 |
| 5962-94B0603M7C | | 09/14/1994 | | (NONE) | | | LCB300 (GEN) | 365 |
| 5962-94B0603M8C | | 09/14/1994 | | (NONE) | | | LCB300 (GEN) | 365 |
| 5962-94B0603M9C | | 09/14/1994 | | (NONE) | | | LCB300 (GEN) | 365 |
| 5962-94B0603MCC | | 09/14/1994 | | (NONE) | | | LCB300 (GEN) | 365 |
| 5962-94B0603MMC | | 09/14/1994 | | (NONE) | | | LCB300 (GEN) | 365 |
| 5962-94B0603MNC | | 09/14/1994 | | (NONE) | | | LCB300 (GEN) | 365 |
| 5962-94B0603MTC | | 09/14/1994 | | (NONE) | | | LCB300 (GEN) | 365 |
| 5962-94B0603MUC | | 09/14/1994 | | (NONE) | | | LCB300 (GEN) | 365 |
| 5962-94B0603MXC | | 09/14/1994 | | (NONE) | | | LCB300 (GEN) | 365 |
| 5962-94B0603MYC | | 09/14/1994 | | (NONE) | | | LCB300 (GEN) | 365 |
| 5962-94B0603MZC | | 09/14/1994 | | (NONE) | | | LCB300 (GEN) | 365 |
| 5962-94B0604M4C | | 09/14/1994 | | (NONE) | | | LCB310 (GEN) | 365 |
| 5962-94B0604M5C | | 09/14/1994 | | (NONE) | | | LCB310 (GEN) | 365 |
| 5962-94B0604M6C | | 09/14/1994 | | (NONE) | | | LCB310 (GEN) | 365 |
| 5962-94B0604M7C | | 09/14/1994 | | (NONE) | | | LCB310 (GEN) | 365 |
| 5962-94B0604M8C | | 09/14/1994 | | (NONE) | | | LCB310 (GEN) | 365 |
| 5962-94B0604M9C | | 09/14/1994 | | (NONE) | | | LCB310 (GEN) | 365 |
| 5962-94B0604MCC | | 09/14/1994 | | (NONE) | | | LCB310 (GEN) | 365 |
| 5962-94B0604MMC | | 09/14/1994 | | (NONE) | | | LCB310 (GEN) | 365 |
| 5962-94B0604MNC | | 09/14/1994 | | (NONE) | | | LCB310 (GEN) | 365 |
| 5962-94B0604MTC | | 09/14/1994 | | (NONE) | | | LCB310 (GEN) | 365 |
| 5962-94B0604MUC | | 09/14/1994 | | (NONE) | | | LCB310 (GEN) | 365 |
| 5962-94B0604MXC | | 09/14/1994 | | (NONE) | | | LCB310 (GEN) | 365 |
| 5962-94B0604MYC | | 09/14/1994 | | (NONE) | | | LCB310 (GEN) | 365 |
| 5962-94B0604MZC | | 09/14/1994 | | (NONE) | | | LCB310 (GEN) | 365 |
| 5962-94B0605M4C | | 09/14/1994 | | (NONE) | | | LEA300 (GEN) | 365 |
| 5962-94B0605M5C | | 09/14/1994 | | (NONE) | | | LEA300 (GEN) | 365 |
| 5962-94B0605M6C | | 09/14/1994 | | (NONE) | | | LEA300 (GEN) | 365 |
| 5962-94B0605M7C | | 09/14/1994 | | (NONE) | | | LEA300 (GEN) | 365 |
| 5962-94B0605M8C | | 09/14/1994 | | (NONE) | | | LEA300 (GEN) | 365 |
| 5962-94B0605M9C | | 09/14/1994 | | (NONE) | | | LEA300 (GEN) | 365 |
| 5962-94B0605MCC | | 09/14/1994 | | (NONE) | | | LEA300 (GEN) | 365 |
| 5962-94B0605MMC | | 09/14/1994 | | (NONE) | | | LEA300 (GEN) | 365 |
| 5962-94B0605MNC | | 09/14/1994 | | (NONE) | | | LEA300 (GEN) | 365 |
| 5962-94B0605MTC | | 09/14/1994 | | (NONE) | | | LEA300 (GEN) | 365 |
| 5962-94B0605MUC | | 09/14/1994 | | (NONE) | | | LEA300 (GEN) | 365 |
| 5962-94B0605MXC | | 09/14/1994 | | (NONE) | | | LEA300 (GEN) | 365 |
| 5962-94B0605MYC | | 09/14/1994 | | (NONE) | | | LEA300 (GEN) | 365 |
| 5962-94B0605MZC | | 09/14/1994 | | (NONE) | | | LEA300 (GEN) | 365 |
| 5962-94B0606M4C | | 09/14/1994 | | (NONE) | | | LEA310 (GEN) | 365 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-94B0606M5C | | 09/14/1994 | | (NONE) | | | LEA310 (GEN) | 365 |
| 5962-94B0606M6C | | 09/14/1994 | | (NONE) | | | LEA310 (GEN) | 365 |
| 5962-94B0606M7C | | 09/14/1994 | | (NONE) | | | LEA310 (GEN) | 365 |
| 5962-94B0606M8C | | 09/14/1994 | | (NONE) | | | LEA310 (GEN) | 365 |
| 5962-94B0606M9C | | 09/14/1994 | | (NONE) | | | LEA310 (GEN) | 365 |
| 5962-94B0606MCC | | 09/14/1994 | | (NONE) | | | LEA310 (GEN) | 365 |
| 5962-94B0606MMC | | 09/14/1994 | | (NONE) | | | LEA310 (GEN) | 365 |
| 5962-94B0606MNC | | 09/14/1994 | | (NONE) | | | LEA310 (GEN) | 365 |
| 5962-94B0606MTC | | 09/14/1994 | | (NONE) | | | LEA310 (GEN) | 365 |
| 5962-94B0606MUC | | 09/14/1994 | | (NONE) | | | LEA310 (GEN) | 365 |
| 5962-94B0606MXC | | 09/14/1994 | | (NONE) | | | LEA310 (GEN) | 365 |
| 5962-94B0606MYC | | 09/14/1994 | | (NONE) | | | LEA310 (GEN) | 365 |
| 5962-94B0606MZC | | 09/14/1994 | | (NONE) | | | LEA310 (GEN) | 365 |
| 5962-9550101HUA | | 12/16/1998 | 1 | ADV. ANALOG | | Y | AFL27005DW/CH | 594 |
| 5962-9550101HUC | | 12/16/1998 | 1 | ADV. ANALOG | | Y | AFL27005DW/CH | 594 |
| 5962-9550101HXA | | 12/16/1998 | 1 | ADV. ANALOG | | Y | AFL27005DX/CH | 594 |
| 5962-9550101HXC | | 12/16/1998 | 1 | ADV. ANALOG | | Y | AFL27005DX/CH | 594 |
| 5962-9550101HYA | | 12/16/1998 | 1 | ADV. ANALOG | | Y | AFL27005DY/CH | 594 |
| 5962-9550101HYC | | 12/16/1998 | 1 | ADV. ANALOG | | Y | AFL27005DY/CH | 594 |
| 5962-9550101HZA | | 12/16/1998 | 1 | ADV. ANALOG | | Y | AFL27005DZ/CH | 594 |
| 5962-9550101HZC | | 12/16/1998 | 1 | ADV. ANALOG | | Y | AFL27005DZ/CH | 594 |
| 5962-9550201HUA | | 04/22/1999 | 1 | ADV. ANALOG | | Y | AFL27018.2DW/CH | 594 |
| 5962-9550201HUC | | 04/22/1999 | 1 | ADV. ANALOG | | Y | AFL27018.2DW/CH | 594 |
| 5962-9550201HXA | | 04/22/1999 | 1 | ADV. ANALOG | | Y | AFL27018.2DX/CH | 594 |
| 5962-9550201HXC | | 04/22/1999 | 1 | ADV. ANALOG | | Y | AFL27018.2DX/CH | 594 |
| 5962-9550201HYA | | 04/22/1999 | 1 | ADV. ANALOG | | Y | AFL27018.2DY/CH | 594 |
| 5962-9550201HYC | | 04/22/1999 | 1 | ADV. ANALOG | | Y | AFL27018.2DY/CH | 594 |
| 5962-9550201HZA | | 04/22/1999 | 1 | ADV. ANALOG | | Y | AFL27018.2DZ/CH | 594 |
| 5962-9550201HZC | | 04/22/1999 | 1 | ADV. ANALOG | | Y | AFL27018.2DZ/CH | 594 |
| 5962-9550301QPA | D | 04/08/2004 | 2 | NATIONAL | | Y | LM6142AMJ/883 | 702 |
| 5962-9550401Q2A | C | 01/31/2001 | 3 | TI | | Y | TLV2262MFKB | 710 |
| 5962-9550401QHA | C | 01/31/2001 | 3 | TI | | Y | TLV2262MUB | 710 |
| 5962-9550401QPA | C | 01/31/2001 | 3 | TI | | Y | TLV2262MJGB | 710 |
| 5962-9550402Q2A | C | 01/31/2001 | 3 | TI | | Y | TLV2264MFKB | 710 |
| 5962-9550402QCA | C | 01/31/2001 | 3 | TI | | Y | TLV2264MJB | 710 |
| 5962-9550402QDA | C | 01/31/2001 | 3 | TI | | Y | TLV2264MWB | 710 |
| 5962-9550403Q2A | C | 01/31/2001 | 3 | TI | | Y | TLV2262AMFKB | 710 |
| 5962-9550403QHA | C | 01/31/2001 | 3 | TI | | Y | TLV2262AMUB | 710 |
| 5962-9550403QPA | C | 01/31/2001 | 3 | TI | | Y | TLV2262AMJGB | 710 |
| 5962-9550404Q2A | C | 01/31/2001 | 3 | TI | | Y | TLV2264AMFKB | 710 |
| 5962-9550404QCA | C | 01/31/2001 | 3 | TI | | Y | TLV2264AMJB | 710 |
| 5962-9550404QDA | C | 01/31/2001 | 3 | TI | | Y | TLV2264AMWB | 710 |
| 5962-9550501HXA | B | 09/15/1998 | 1 | AEROFLEX | | Y | ARX4810-201-2 | 590 |
| 5962-9550501HXA | B | 09/15/1998 | 1 | AEROFLEX | | Y | ARX4810-201-3 | 590 |
| 5962-9550501HXC | B | 09/15/1998 | 1 | AEROFLEX | | Y | ARX4810-201-1 | 590 |
| 5962-9550501HXC | B | 09/15/1998 | 1 | AEROFLEX | | Y | ARX4810-201-3 | 590 |
| 5962-9550501HYA | B | 09/15/1998 | 1 | AEROFLEX | | Y | ARX4810-203-3 | 590 |
| 5962-9550501HYA | B | 09/15/1998 | 1 | AEROFLEX | | Y | ARX4810-203-2 | 590 |
| 5962-9550501HYC | B | 09/15/1998 | 1 | AEROFLEX | | Y | ARX4810-203-1 | 590 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9550501HYC | B | 09/15/1998 | 1 | AEROFLEX | | Y | ARX4810-203-3 | 590 |
| 5962-9550601MXA | A | 06/05/2001 | | (NONE) | 10/29/2001 | | 72240L50 (GEN) | 670 |
| 5962-9550602MXA | A | 06/05/2001 | | (NONE) | 10/29/2001 | | 72240L35 (GEN) | 670 |
| 5962-9550603MXA | A | 06/05/2001 | | (NONE) | 10/29/2001 | | 72240L25 (GEN) | 670 |
| 5962-9550801MXA | A | 05/01/2002 | 1 | ACTEL | | Y | A1460A-PG207B | 381 |
| 5962-9550801MXC | A | 05/01/2002 | 1 | ACTEL | | Y | A1460A-PG207B | 381 |
| 5962-9550801MYC | A | 05/01/2002 | 1 | ACTEL | | Y | A1460A-CQ196B | 381 |
| 5962-9550802MXA | A | 05/01/2002 | 1 | ACTEL | | Y | A1460A-1PG207B | 381 |
| 5962-9550802MXC | A | 05/01/2002 | 1 | ACTEL | | Y | A1460A-1PG207B | 381 |
| 5962-9550802MYC | A | 05/01/2002 | 1 | ACTEL | | Y | A1460A-1CQ196B | 381 |
| 5962-9551201QRA | | 12/05/1995 | | (NONE) | | | DAC0854C (GEN) | 591 |
| 5962-9551301QEA | | 12/05/1995 | | (NONE) | 12/08/1998 | | ADC0851 (GEN) | 433 |
| 5962-9551302QRA | | 12/05/1995 | | (NONE) | 12/08/1998 | | ADC0858 (GEN) | 433 |
| 5962-9551401QRA | | 01/10/1996 | | (NONE) | | | ADC08061 (GEN) | 592 |
| 5962-9551801MXC | | 10/04/1995 | 1 | ATMEL GREN. | | | TS68C429AMRB/C | 590 |
| 5962-9551801MYC | | 10/04/1995 | 1 | ATMEL GREN. | | | TS68C429AMFB/C | 590 |
| 5962-9551901MLA | | 11/04/1994 | | (NONE) | | | AD671S-500 (GEN) | 592 |
| 5962-9551902MLA | | 11/04/1994 | | (NONE) | | | AD671S-750 (GEN) | 592 |
| 5962-9552001MXC | B | 05/02/2002 | | (NONE) | 04/01/2002 | | 1425A (GEN) | 431 |
| 5962-9552001MYC | B | 05/02/2002 | 1 | ACTEL | | Y | A1425A-CQ132B | 431 |
| 5962-9552002MXC | B | 05/02/2002 | | (NONE) | 04/01/2002 | | 1425A-1 (GEN) | 431 |
| 5962-9552002MYC | B | 05/02/2002 | 1 | ACTEL | | Y | A1425A-1CQ132B | 431 |
| 5962-9552101MXC | A | 04/09/1999 | 1 | ACTEL | | Y | A14100A-PG257B | 381 |
| 5962-9552101MYC | A | 04/09/1999 | 1 | ACTEL | | Y | A14100A-CQ256B | 381 |
| 5962-9552102MXC | A | 04/09/1999 | 1 | ACTEL | | Y | A14100A-1PG257B | 381 |
| 5962-9552102MYC | A | 04/09/1999 | 1 | ACTEL | | Y | A14100A-1CQ256B | 381 |
| 5962-9552501MRA | | 02/10/1995 | | (NONE) | 05/31/2000 | | 9241Y (GEN) | 839 |
| 5962-9552502MRA | | 02/10/1995 | | (NONE) | 05/31/2000 | | 9241W (GEN) | 839 |
| 5962-9552503MRA | | 02/10/1995 | | (NONE) | 05/31/2000 | | 9241U (GEN) | 839 |
| 5962-9552504MRA | | 02/10/1995 | | (NONE) | 05/31/2000 | | 9241M (GEN) | 839 |
| 5962-9552701QJA | | 11/28/1994 | | (NONE) | 06/30/2000 | | 2701 (GEN) | 790 |
| 5962-9552901MGA | A | 03/29/2004 | 1 | NATIONAL | | Y | LM725H/883 | 754 |
| 5962-9553001MEA | | 01/25/1995 | | (NONE) | 03/31/1998 | | MPD8032 (GEN) | 589 |
| 5962-9553002MEA | | 01/25/1995 | | (NONE) | 03/31/1998 | | MPD8032 (GEN) | 589 |
| 5962-9553201HUA | | 12/16/1998 | 1 | ADV. ANALOG | | Y | AFL27015DW/CH | 594 |
| 5962-9553201HUC | | 12/16/1998 | 1 | ADV. ANALOG | | Y | AFL27015DW/CH | 594 |
| 5962-9553201HXA | | 12/16/1998 | 1 | ADV. ANALOG | | Y | AFL27015DX/CH | 594 |
| 5962-9553201HXC | | 12/16/1998 | 1 | ADV. ANALOG | | Y | AFL27015DX/CH | 594 |
| 5962-9553201HYA | | 12/16/1998 | 1 | ADV. ANALOG | | Y | AFL27015DY/CH | 594 |
| 5962-9553201HYC | | 12/16/1998 | 1 | ADV. ANALOG | | Y | AFL27015DY/CH | 594 |
| 5962-9553201HZA | | 12/16/1998 | 1 | ADV. ANALOG | | Y | AFL27015DZ/CH | 594 |
| 5962-9553201HZC | | 12/16/1998 | 1 | ADV. ANALOG | | Y | AFL27015DZ/CH | 594 |
| 5962-9553401HUA | | 11/25/1998 | 1 | ADV. ANALOG | | Y | AFL27006SW/CH | 594 |
| 5962-9553401HUC | | 11/25/1998 | 1 | ADV. ANALOG | | Y | AFL27006SW/CH | 594 |
| 5962-9553401HXA | | 11/25/1998 | 1 | ADV. ANALOG | | Y | AFL27006SX/CH | 594 |
| 5962-9553401HXC | | 11/25/1998 | 1 | ADV. ANALOG | | Y | AFL27006SX/CH | 594 |
| 5962-9553401HYA | | 11/25/1998 | 1 | ADV. ANALOG | | Y | AFL27006SY/CH | 594 |
| 5962-9553401HYC | | 11/25/1998 | 1 | ADV. ANALOG | | Y | AFL27006SY/CH | 594 |
| 5962-9553401HZA | | 11/25/1998 | 1 | ADV. ANALOG | | Y | AFL27006SZ/CH | 594 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9553401HZC | | 11/25/1998 | 1 | ADV. ANALOG | | Y | AFL27006SZ/CH | 594 |
| 5962-9553501HUA | | 11/25/1998 | 1 | ADV. ANALOG | | Y | AFL27009SW/CH | 594 |
| 5962-9553501HUC | | 11/25/1998 | 1 | ADV. ANALOG | | Y | AFL27009SW/CH | 594 |
| 5962-9553501HXA | | 11/25/1998 | 1 | ADV. ANALOG | | Y | AFL27009SX/CH | 594 |
| 5962-9553501HXC | | 11/25/1998 | 1 | ADV. ANALOG | | Y | AFL27009SX/CH | 594 |
| 5962-9553501HYA | | 11/25/1998 | 1 | ADV. ANALOG | | Y | AFL27009SY/CH | 594 |
| 5962-9553501HYC | | 11/25/1998 | 1 | ADV. ANALOG | | Y | AFL27009SY/CH | 594 |
| 5962-9553501HZA | | 11/25/1998 | 1 | ADV. ANALOG | | Y | AFL27009SZ/CH | 594 |
| 5962-9553501HZC | | 11/25/1998 | 1 | ADV. ANALOG | | Y | AFL27009SZ/CH | 594 |
| 5962-9553601QHA | G | 02/26/2003 | 2 | NATIONAL | | Y | LM7171AMW-QML | 701 |
| 5962-9553601VHA | G | 02/26/2003 | 2 | NATIONAL | | Y | LM7171AMW-QMLV | 701 |
| 5962F9553601VHA | G | 02/26/2003 | 2 | NATIONAL | | Y | LM7171AMWFQMLV | 701 |
| 5962-9553601QPA | G | 02/26/2003 | 2 | NATIONAL | | Y | LM7171AMJ-QML | 701 |
| 5962-9553601VPA | G | 02/26/2003 | 2 | NATIONAL | | Y | LM7171AMJ-QMLV | 701 |
| 5962F9553601QPA | G | 02/26/2003 | 2 | NATIONAL | | Y | LM7171AMJFQML | 701 |
| 5962F9553601VPA | G | 02/26/2003 | 2 | NATIONAL | | Y | LM7171AMJFQMLV | 701 |
| 5962-9553601QXA | G | 02/26/2003 | 2 | NATIONAL | | Y | LM7171AMWG-QML | 701 |
| 5962-9553601VXA | G | 02/26/2003 | 2 | NATIONAL | | Y | LM7171AMWG-QMLV | 701 |
| 5962F9553601QXA | G | 02/26/2003 | 2 | NATIONAL | | Y | LM7171AMWGFQML | 701 |
| 5962F9553601VXA | G | 02/26/2003 | 2 | NATIONAL | | Y | LM7171AMWGFQMLV | 701 |
| 5962-9553701Q2A | A | 07/10/2001 | 2 | TI | | Y | SNJ54AS175BFK | 159 |
| 5962-9553701QEA | A | 07/10/2001 | 2 | TI | | Y | SNJ54AS175BJ | 159 |
| 5962-9553701QFA | A | 07/10/2001 | | (NONE) | | | 54AS175 (GEN) | 159 |
| 5962-9553801HXA | | 12/09/1996 | | (NONE) | | | 128K32-150 (GEN) | 661 |
| 5962-9553801HYA | | 12/09/1996 | | (NONE) | | | 128K32-150 (GEN) | 661 |
| 5962-9553802HXA | | 12/09/1996 | | (NONE) | | | 128K32-120 (GEN) | 661 |
| 5962-9553802HYA | | 12/09/1996 | | (NONE) | | | 128K32-120 (GEN) | 661 |
| 5962-9553901HYC | | 08/06/1998 | 1 | CMAC MICRO. | | Y | RTM1760-PGA | 590 |
| 5962-9553902HYC | | 08/06/1998 | 1 | CMAC MICRO. | | Y | RTS1760-PGA | 590 |
| 5962-9554001QXA | | 01/26/1995 | | (NONE) | 06/09/1998 | | DS3884 (GEN) | 429 |
| 5962-9554101QXA | | 01/06/1995 | | (NONE) | | | DS3885 (GEN) | 429 |
| 5962-9554201QXA | | 01/06/1995 | | (NONE) | 06/09/1998 | | DS3886 (GEN) | 429 |
| 5962-9554301QXA | | 03/15/1995 | | (NONE) | | | DS3875 (GEN) | 420 |
| 5962-9554401MJC | | 06/05/1995 | | (NONE) | | | UC1620 (GEN) | 899 |
| 5962-9554701QEA | A | 03/19/2002 | 2 | NATIONAL | | Y | LP2956AMJ/883B | 780 |
| 5962-9554901NXD | A | 03/01/2001 | 1 | TI | | Y | TLC372MDQ | 779 |
| 5962-9555001NXD | | 12/27/1994 | 1 | TI | | Y | TLC139MDQ | 776 |
| 5962-9555101QPA | B | 01/29/2001 | 1 | TI | | Y | TLC193MJGB | 779 |
| 5962-9555101NXD | B | 01/29/2001 | 0 | TI | | Y | TLC193MDQ | 779 |
| 5962-9555201Q2A | D | 05/21/2003 | 3 | TI | | Y | TLC2272MFKB | 710 |
| 5962-9555201QHA | D | 05/21/2003 | 3 | TI | | Y | TLC2272MUB | 710 |
| 5962-9555201QPA | D | 05/21/2003 | 3 | TI | | Y | TLC2272MJGB | 710 |
| 5962-9555201NXD | D | 05/21/2003 | 3 | TI | | Y | TLC2272MDQ | 710 |
| 5962-9555202Q2A | D | 05/21/2003 | 3 | TI | | Y | TLC2272AMFKB | 710 |
| 5962-9555202QHA | D | 05/21/2003 | 3 | TI | | Y | TLC2272AMUB | 710 |
| 5962-9555202QPA | D | 05/21/2003 | 3 | TI | | Y | TLC2272AMJGB | 710 |
| 5962-9555301NXD | A | 03/14/2003 | 0 | TI | | Y | TLC27L7MDQ | 710 |
| 5962-9555401NXD | A | 04/14/2004 | 0 | TI | | Y | TLC27L9MDQ | 713 |
| 5962-9555601Q2A | | 12/20/1994 | | (NONE) | 06/30/2000 | | TLE2425 (GEN) | 785 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9555601QPA | | 12/20/1994 | | (NONE) | 06/30/2000 | | TLE2425 (GEN) | 785 |
| 5962-9555602Q2A | | 12/20/1994 | | (NONE) | 06/30/2000 | | TLE2426 (GEN) | 785 |
| 5962-9555602QPA | | 12/20/1994 | | (NONE) | 06/30/2000 | | TLE2426 (GEN) | 785 |
| 5962-9555701QXC | A | 02/21/1997 | | (NONE) | | | 7C375-66 (GEN) | 431 |
| 5962-9555701QYC | A | 02/21/1997 | | (NONE) | | | 7C375-66 (GEN) | 431 |
| 5962-9555701QZC | A | 02/21/1997 | | (NONE) | | | 7C375-66 (GEN) | 431 |
| 5962-9555702QXC | A | 02/21/1997 | | (NONE) | | | 7C375-83 (GEN) | 431 |
| 5962-9555702QYC | A | 02/21/1997 | | (NONE) | | | 7C375-83 (GEN) | 431 |
| 5962-9555702QZC | A | 02/21/1997 | | (NONE) | | | 7C375-83 (GEN) | 431 |
| 5962-9555801HXA | | 06/30/1997 | 1 | NATIONAL HYB | | Y | NHI-1582ET/883 | 399 |
| 5962-9555801HXC | | 06/30/1997 | 1 | NATIONAL HYB | | Y | NHI-1582ET/883 | 399 |
| 5962-9555801HYA | | 06/30/1997 | 1 | NATIONAL HYB | | Y | NHI-1582ETFP/883 | 399 |
| 5962-9555801HYC | | 06/30/1997 | 1 | NATIONAL HYB | | Y | NHI-1582ETFP/883 | 399 |
| 5962-9555802HXA | | 06/30/1997 | 1 | NATIONAL HYB | | Y | NHI-1583ET/883 | 399 |
| 5962-9555802HXC | | 06/30/1997 | 1 | NATIONAL HYB | | Y | NHI-1583ET/883 | 399 |
| 5962-9555802HYA | | 06/30/1997 | 1 | NATIONAL HYB | | Y | NHI-1583ETFP/883 | 399 |
| 5962-9555802HYC | | 06/30/1997 | 1 | NATIONAL HYB | | Y | NHI-1583ETFP/883 | 399 |
| 5962-9555803HXA | | 06/30/1997 | 1 | NATIONAL HYB | | Y | NHI-1598ET/883 | 399 |
| 5962-9555803HXC | | 06/30/1997 | 1 | NATIONAL HYB | | Y | NHI-1598ET/883 | 399 |
| 5962-9555803HYA | | 06/30/1997 | 1 | NATIONAL HYB | | Y | NHI-1598ETFP/883 | 399 |
| 5962-9555803HYC | | 06/30/1997 | 1 | NATIONAL HYB | | Y | NHI-1598ETFP/883 | 399 |
| 5962-9555804HXA | | 06/30/1997 | 1 | NATIONAL HYB | | Y | NHI-1599ET/883 | 399 |
| 5962-9555804HXC | | 06/30/1997 | 1 | NATIONAL HYB | | Y | NHI-1599ET/883 | 399 |
| 5962-9555804HYA | | 06/30/1997 | 1 | NATIONAL HYB | | Y | NHI-1599ETFP/883 | 399 |
| 5962-9555804HYC | | 06/30/1997 | 1 | NATIONAL HYB | | Y | NHI-1599ETFP/883 | 399 |
| 5962-9555805HXA | | 06/30/1997 | 1 | NATIONAL HYB | | Y | NHI-15103ET/883 | 399 |
| 5962-9555805HXC | | 06/30/1997 | 1 | NATIONAL HYB | | Y | NHI-15103ET/883 | 399 |
| 5962-9555805HYA | | 06/30/1997 | 1 | NATIONAL HYB | | Y | NHI-15103ETFP/883 | 399 |
| 5962-9555805HYC | | 06/30/1997 | 1 | NATIONAL HYB | | Y | NHI-15103ETFP/883 | 399 |
| 5962-9555806HXA | | 06/30/1997 | 1 | NATIONAL HYB | | Y | NHI-15104ET/883 | 399 |
| 5962-9555806HXC | | 06/30/1997 | 1 | NATIONAL HYB | | Y | NHI-15104ET/883 | 399 |
| 5962-9555806HYA | | 06/30/1997 | 1 | NATIONAL HYB | | Y | NHI-15104ETFP/883 | 399 |
| 5962-9555806HYC | | 06/30/1997 | 1 | NATIONAL HYB | | Y | NHI-15104ETFP/883 | 399 |
| 5962-9555901HXA | E | 08/19/2004 | 1 | INTERPOINT | | Y | MHF+2805D/883 | 594 |
| 5962-9555901HXC | E | 08/19/2004 | 1 | INTERPOINT | | Y | MHF+2805D/883 | 594 |
| 5962-9555901HZA | E | 08/19/2004 | 1 | INTERPOINT | | Y | MHF+2805DF/883 | 594 |
| 5962-9555901HZC | E | 08/19/2004 | 1 | INTERPOINT | | Y | MHF+2805DF/883 | 594 |
| 5962-9555902HXA | E | 08/19/2004 | 1 | INTERPOINT | | Y | SMHF2805D/HO | 594 |
| 5962-9555902HXC | E | 08/19/2004 | 1 | INTERPOINT | | Y | SMHF2805D/HO | 594 |
| 5962L9555902HXA | E | 08/19/2004 | 1 | INTERPOINT | | Y | SMHF2805D/HL | 594 |
| 5962L9555902HXC | E | 08/19/2004 | 1 | INTERPOINT | | Y | SMHF2805D/HL | 594 |
| 5962L9555902KXA | E | 08/19/2004 | 1 | INTERPOINT | | Y | SMHF2805D/KL | 594 |
| 5962L9555902KXC | E | 08/19/2004 | 1 | INTERPOINT | | Y | SMHF2805D/KL | 594 |
| 5962R9555902HXA | E | 08/19/2004 | 1 | INTERPOINT | | Y | SMHF2805D/HR | 594 |
| 5962R9555902HXC | E | 08/19/2004 | 1 | INTERPOINT | | Y | SMHF2805D/HR | 594 |
| 5962R9555902KXA | E | 08/19/2004 | 1 | INTERPOINT | | Y | SMHF2805D/KR | 594 |
| 5962R9555902KXC | E | 08/19/2004 | 1 | INTERPOINT | | Y | SMHF2805D/KR | 594 |
| 5962-9555902HZA | E | 08/19/2004 | 1 | INTERPOINT | | Y | SMHF2805DF/HO | 594 |
| 5962-9555902HZC | E | 08/19/2004 | 1 | INTERPOINT | | Y | SMHF2805DF/HO | 594 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962L9555902HZA | E | 08/19/2004 | 1 | INTERPOINT | | Y | SMHF2805DF/HL | 594 |
| 5962L9555902HZC | E | 08/19/2004 | 1 | INTERPOINT | | Y | SMHF2805DF/HL | 594 |
| 5962L9555902KZA | E | 08/19/2004 | 1 | INTERPOINT | | Y | SMHF2805DF/KL | 594 |
| 5962L9555902KZC | E | 08/19/2004 | 1 | INTERPOINT | | Y | SMHF2805DF/KL | 594 |
| 5962R9555902HZA | E | 08/19/2004 | 1 | INTERPOINT | | Y | SMHF2805DF/HR | 594 |
| 5962R9555902HZC | E | 08/19/2004 | 1 | INTERPOINT | | Y | SMHF2805DF/HR | 594 |
| 5962R9555902KZA | E | 08/19/2004 | 1 | INTERPOINT | | Y | SMHF2805DF/KR | 594 |
| 5962R9555902KZC | E | 08/19/2004 | 1 | INTERPOINT | | Y | SMHF2805DF/KR | 594 |
| 5962-9556001HXA | | 07/21/1995 | | (NONE) | | | MHP27012S (GEN) | 594 |
| 5962-9556001HXC | | 07/21/1995 | | (NONE) | | | MHP27012S (GEN) | 594 |
| 5962-9556101HXA | | 07/21/1995 | | (NONE) | | | MHP27015S (GEN) | 594 |
| 5962-9556101HXC | | 07/21/1995 | | (NONE) | | | MHP27015S (GEN) | 594 |
| 5962-9556201HXA | | 07/21/1995 | | (NONE) | | | MHP27028S (GEN) | 594 |
| 5962-9556201HXC | | 07/21/1995 | | (NONE) | | | MHP27028S (GEN) | 594 |
| 5962-9556301HXA | | 07/21/1995 | | (NONE) | | | MHP27012D (GEN) | 594 |
| 5962-9556301HXC | | 07/21/1995 | | (NONE) | | | MHP27012D (GEN) | 594 |
| 5962-9556401HXA | | 07/21/1995 | | (NONE) | | | MHP27015D (GEN) | 594 |
| 5962-9556401HXC | | 07/21/1995 | | (NONE) | | | MHP27015D (GEN) | 594 |
| 5962-9556501HUA | A | 11/29/2001 | 1 | ADV. ANALOG | | Y | AFL27028SW/CH | 594 |
| 5962-9556501HUC | A | 11/29/2001 | 1 | ADV. ANALOG | | Y | AFL27028SW/CH | 594 |
| 5962-9556501HXA | A | 11/29/2001 | 1 | ADV. ANALOG | | Y | AFL27028SX/CH | 594 |
| 5962-9556501HXC | A | 11/29/2001 | 1 | ADV. ANALOG | | Y | AFL27028SX/CH | 594 |
| 5962-9556501HYA | A | 11/29/2001 | 1 | ADV. ANALOG | | Y | AFL27028SY/CH | 594 |
| 5962-9556501HYC | A | 11/29/2001 | 1 | ADV. ANALOG | | Y | AFL27028SY/CH | 594 |
| 5962-9556501HZA | A | 11/29/2001 | 1 | ADV. ANALOG | | Y | AFL27028SZ/CH | 594 |
| 5962-9556501HZC | A | 11/29/2001 | 1 | ADV. ANALOG | | Y | AFL27028SZ/CH | 594 |
| 5962-9556701M2A | A | 03/19/2002 | | (NONE) | 10/15/2003 | | BUF04 (GEN) | 711 |
| 5962-9556701MPA | A | 03/19/2002 | | (NONE) | 10/15/2003 | | BUF04 (GEN) | 711 |
| 5962-9556901QYA | | 03/31/1995 | | (NONE) | 12/24/1997 | | 80960MX (GEN) | 404 |
| 5962-9557001QXA | B | 10/02/1995 | | (NONE) | 12/24/1997 | | 80386EX (GEN) | 404 |
| 5962-9557001QYA | B | 10/02/1995 | | (NONE) | 12/24/1997 | | 80386EX (GEN) | 404 |
| 5962-9557002NXA | B | 10/02/1995 | | (NONE) | 12/24/1997 | | 80386EX (GEN) | 404 |
| 5962-9557002NYA | B | 10/02/1995 | | (NONE) | 12/24/1997 | | 80386EX (GEN) | 404 |
| 5962-9557401QCA | | 01/19/1995 | 1 | TI | | Y | SNJ5432J | 125 |
| 5962-9557401QDA | | 01/19/1995 | 1 | TI | | Y | SNJ5432W | 125 |
| 5962-9557501QEA | A | 11/06/2000 | 1 | TI | | Y | SNJ5476J | 156 |
| 5962-9557501QFA | A | 11/06/2000 | 1 | TI | | Y | SNJ5476W | 156 |
| 5962-9557601NXD | A | 05/22/1996 | 1 | TI | | Y | 54ABTH32501PZ | 590 |
| 5962-9557701NXD | A | 05/22/1996 | 1 | TI | | Y | 54ABTH32245PZ | 590 |
| 5962-9557801NXD | A | 05/22/1996 | 1 | TI | | Y | 54ABTH32543PZ | 590 |
| 5962-9557901MLA | A | 12/03/2001 | 1 | ANALOG (2) | | Y | AD668SQ/883B | 591 |
| 5962-9558001QJA | A | 10/30/2000 | 1 | TI | | Y | SNJ54150J | 270 |
| 5962-9558001QKA | A | 10/30/2000 | 1 | TI | | Y | SNJ54150W | 270 |
| 5962-9558101QJA | A | 11/06/2000 | 1 | LANSDALE | | Y | SL54154/BJA | 280 |
| 5962-9558101QJA | A | 11/06/2000 | 1 | TI | | Y | SNJ54154J | 280 |
| 5962-9558101QKA | A | 11/06/2000 | 1 | LANSDALE | | Y | SL54154/BKA | 280 |
| 5962-9558101QKA | A | 11/06/2000 | 1 | TI | | Y | SNJ54154W | 280 |
| 5962-9558201QEA | A | 10/03/2000 | 1 | LANSDALE | | Y | SL54155/BEA | 283 |
| 5962-9558201QFA | A | 10/03/2000 | 1 | LANSDALE | | Y | SL54155/BFA | 283 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9558301QEA | A | 10/17/2000 | 1 | TI | | Y | SNJ54166J | 224 |
| 5962-9558301QFA | A | 10/17/2000 | 1 | TI | | Y | SNJ54166W | 224 |
| 5962-9558401QEA | B | 03/07/1997 | | LANSDALE | | Y | SL54192/BEA | 301 |
| 5962-9558401QEA | B | 03/07/1997 | 1 | TI | | Y | SNJ54192J | 301 |
| 5962-9558401QFA | B | 03/07/1997 | | LANSDALE | | Y | SL54192/BFA | 301 |
| 5962-9558401QFA | B | 03/07/1997 | 1 | TI | | Y | SNJ54192W | 301 |
| 5962-9558501QEA | | 01/26/1995 | | (NONE) | 12/02/2003 | | DM9328 (GEN) | 230 |
| 5962-9558601M2A | A | 09/03/2003 | 2 | TI | | Y | UC1851L/883BC | 787 |
| 5962-9558601MVA | A | 09/03/2003 | | (NONE) | 12/31/2001 | | UC1851 (GEN) | 787 |
| 5962-9558701MXC | A | 05/03/2002 | 2 | LATTICE SEMI | | | ISPLSI1048C-50LG/8 | 431 |
| 5962-9558801MXC | A | 05/08/2002 | 2 | LATTICE SEMI | | | PLSI1048C-50LG/883 | 431 |
| 5962-9559001QXA | A | 04/12/1996 | 1 | TI | | Y | SNJ54ABT16640WD | 590 |
| 5962-9559201MEA | A | 11/16/2001 | 1 | ANALOG (2) | | Y | AD677TD/883B | 592 |
| 5962-9559301QXA | | 03/21/1995 | | (NONE) | | | ADC12062 (GEN) | 592 |
| 5962-9559501H9A | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32-120G1UQ | 629 |
| 5962-9559501H9C | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32-120G1UQ | 629 |
| 5962-9559501HBA | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32-120G1TQ | 629 |
| 5962-9559501HBC | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32-120G1TQ | 629 |
| 5962-9559501HMA | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32-120G2Q | 629 |
| 5962-9559501HMC | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32-120G2Q | 629 |
| 5962-9559501HNA | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32-120G2UQ | 629 |
| 5962-9559501HNC | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32-120G2UQ | 629 |
| 5962-9559501HXC | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32-120G4Q | 629 |
| 5962-9559501HYC | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32-120G4TQ | 629 |
| 5962-9559502H9A | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32-100G1UQ | 629 |
| 5962-9559502H9C | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32-100G1UQ | 629 |
| 5962-9559502HBA | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32-100G1TQ | 629 |
| 5962-9559502HBC | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32-100G1TQ | 629 |
| 5962-9559502HMA | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32-100G2Q | 629 |
| 5962-9559502HMC | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32-100G2Q | 629 |
| 5962-9559502HNA | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32-100G2UQ | 629 |
| 5962-9559502HNC | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32-100G2UQ | 629 |
| 5962-9559502HXC | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32-100G4Q | 629 |
| 5962-9559502HYC | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32-100G4TQ | 629 |
| 5962-9559503H9A | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32-85G1UQ | 629 |
| 5962-9559503H9C | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32-85G1UQ | 629 |
| 5962-9559503HBA | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32-85G1TQ | 629 |
| 5962-9559503HBC | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32-85G1TQ | 629 |
| 5962-9559503HMA | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32-85G2Q | 629 |
| 5962-9559503HMC | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32-85G2Q | 629 |
| 5962-9559503HNA | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32-85G2UQ | 629 |
| 5962-9559503HNC | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32-85G2UQ | 629 |
| 5962-9559503HXC | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32-85G4Q | 629 |
| 5962-9559503HYC | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32-85G4TQ | 629 |
| 5962-9559504H9A | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32-70G1UQ | 629 |
| 5962-9559504H9C | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32-70G1UQ | 629 |
| 5962-9559504HBA | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32-70G1TQ | 629 |
| 5962-9559504HBC | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32-70G1TQ | 629 |
| 5962-9559504HMA | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32-70G2Q | 629 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9559504HMC | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32-70G2Q | 629 |
| 5962-9559504HNA | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32-70G2UQ | 629 |
| 5962-9559504HNC | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32-70G2UQ | 629 |
| 5962-9559504HXC | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32-70G4Q | 629 |
| 5962-9559504HYC | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32-70G4TQ | 629 |
| 5962-9559505H9A | N | 01/07/2004 | 1 | AEROFLEX | | Y | ACT-S128K32N-055F18 | 629 |
| 5962-9559505H9A | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32-55G1UQ | 629 |
| 5962-9559505H9C | N | 01/07/2004 | 1 | AEROFLEX | | Y | ACT-S128K32N-055F18 | 629 |
| 5962-9559505H9C | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32-55G1UQ | 629 |
| 5962-9559505HAA | N | 01/07/2004 | 1 | AUSTIN SEMI. | | Y | AS8S128K32Q1-55/883 | 629 |
| 5962-9559505HAA | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32-55G2LQ | 629 |
| 5962-9559505HAC | N | 01/07/2004 | 1 | AUSTIN SEMI. | | Y | AS8S128K32Q1-55/883 | 629 |
| 5962-9559505HAC | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32-55G2LQ | 629 |
| 5962-9559505HBA | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32-55G1TQ | 629 |
| 5962-9559505HBC | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32-55G1TQ | 629 |
| 5962-9559505HMA | N | 01/07/2004 | 1 | AEROFLEX | | Y | ACT-S128K32N-055F2 | 629 |
| 5962-9559505HMA | N | 01/07/2004 | 1 | AUSTIN SEMI. | | Y | AS8S128K32Q-55/883C | 629 |
| 5962-9559505HMA | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32-55G2Q | 629 |
| 5962-9559505HMC | N | 01/07/2004 | 1 | AEROFLEX | | Y | ACT-S128K32N-055F2 | 629 |
| 5962-9559505HMC | N | 01/07/2004 | 1 | AUSTIN SEMI. | | Y | AS8S128K32Q-55/883C | 629 |
| 5962-9559505HMC | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32-55G2Q | 629 |
| 5962-9559505HNA | N | 01/07/2004 | 1 | AUSTIN SEMI. | | Y | AS8S128K32QT-55/883 | 629 |
| 5962-9559505HNA | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32-55G2UQ | 629 |
| 5962-9559505HNC | N | 01/07/2004 | 1 | AUSTIN SEMI. | | Y | AS8S128K32QT-55/883 | 629 |
| 5962-9559505HNC | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32-55G2UQ | 629 |
| 5962-9559505HXA | N | 01/07/2004 | 1 | AEROFLEX | | Y | ACT-S128K32N-055F1 | 629 |
| 5962-9559505HXC | N | 01/07/2004 | 1 | AEROFLEX | | Y | ACT-S128K32N-055F1 | 629 |
| 5962-9559505HXC | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32-55G4Q | 629 |
| 5962-9559505HYA | N | 01/07/2004 | 1 | AEROFLEX | | Y | ACT-S128K32N-055F1 | 629 |
| 5962-9559505HYC | N | 01/07/2004 | 1 | AEROFLEX | | Y | ACT-S128K32N-055F1 | 629 |
| 5962-9559505HYC | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32-55G4TQ | 629 |
| 5962-9559505HZA | N | 01/07/2004 | 1 | AEROFLEX | | Y | ACT-S128K32N-055F2 | 629 |
| 5962-9559505HZC | N | 01/07/2004 | 1 | AEROFLEX | | Y | ACT-S128K32N-055F2 | 629 |
| 5962-9559506H9A | N | 01/07/2004 | 1 | AEROFLEX | | Y | ACT-S128K32N-045F18 | 629 |
| 5962-9559506H9A | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32-45G1UQ | 629 |
| 5962-9559506H9C | N | 01/07/2004 | 1 | AEROFLEX | | Y | ACT-S128K32N-045F18 | 629 |
| 5962-9559506H9C | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32-45G1UQ | 629 |
| 5962-9559506HAA | N | 01/07/2004 | 1 | AUSTIN SEMI. | | Y | AS8S128K32Q1-45/883 | 629 |
| 5962-9559506HAA | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32-45G2LQ | 629 |
| 5962-9559506HAC | N | 01/07/2004 | 1 | AUSTIN SEMI. | | Y | AS8S128K32Q1-45/883 | 629 |
| 5962-9559506HAC | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32-45G2LQ | 629 |
| 5962-9559506HBA | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32-45G1TQ | 629 |
| 5962-9559506HBC | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32-45G1TQ | 629 |
| 5962-9559506HMA | N | 01/07/2004 | 1 | AEROFLEX | | Y | ACT-S128K32N-045F2 | 629 |
| 5962-9559506HMA | N | 01/07/2004 | 1 | AUSTIN SEMI. | | Y | AS8S128K32Q-45/883C | 629 |
| 5962-9559506HMA | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32-45G2UQ | 629 |
| 5962-9559506HMC | N | 01/07/2004 | 1 | AEROFLEX | | Y | ACT-S128K32N-045F2 | 629 |
| 5962-9559506HMC | N | 01/07/2004 | 1 | AUSTIN SEMI. | | Y | AS8S128K32Q-45/883C | 629 |
| 5962-9559506HMC | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32-45G2UQ | 629 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9559506HNA | N | 01/07/2004 | 1 | AUSTIN SEMI. | | Y | AS8S128K32QT-45/883 | 629 |
| 5962-9559506HNA | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32-45G2UQ | 629 |
| 5962-9559506HNC | N | 01/07/2004 | 1 | AUSTIN SEMI. | | Y | AS8S128K32QT-45/883 | 629 |
| 5962-9559506HNC | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32-45G2UQ | 629 |
| 5962-9559506HXA | N | 01/07/2004 | 1 | AEROFLEX | | Y | ACT-S128K32N-045F1 | 629 |
| 5962-9559506HXC | N | 01/07/2004 | 1 | AEROFLEX | | Y | ACT-S128K32N-045F1 | 629 |
| 5962-9559506HXC | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32-45G4Q | 629 |
| 5962-9559506HYA | N | 01/07/2004 | 1 | AEROFLEX | | Y | ACT-S128K32N-045F1 | 629 |
| 5962-9559506HYC | N | 01/07/2004 | 1 | AEROFLEX | | Y | ACT-S128K32N-045F1 | 629 |
| 5962-9559506HYC | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32-45G4TQ | 629 |
| 5962-9559506HZA | N | 01/07/2004 | 1 | AEROFLEX | | Y | ACT-S128K32N-045F2 | 629 |
| 5962-9559506HZC | N | 01/07/2004 | 1 | AEROFLEX | | Y | ACT-S128K32N-045F2 | 629 |
| 5962-9559507H9A | N | 01/07/2004 | 1 | AEROFLEX | | Y | ACT-S128K32N-035F18 | 629 |
| 5962-9559507H9A | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32-35G1UQ | 629 |
| 5962-9559507H9C | N | 01/07/2004 | 1 | AEROFLEX | | Y | ACT-S128K32N-035F18 | 629 |
| 5962-9559507H9C | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32-35G1UQ | 629 |
| 5962-9559507HAA | N | 01/07/2004 | 1 | AUSTIN SEMI. | | Y | AS8S128K32Q1-35/883 | 629 |
| 5962-9559507HAA | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32-35G2LQ | 629 |
| 5962-9559507HAC | N | 01/07/2004 | 1 | AUSTIN SEMI. | | Y | AS8S128K32Q1-35/883 | 629 |
| 5962-9559507HAC | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32-35G2LQ | 629 |
| 5962-9559507HBA | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32-35G1TQ | 629 |
| 5962-9559507HBC | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32-35G1TQ | 629 |
| 5962-9559507HMA | N | 01/07/2004 | 1 | AEROFLEX | | Y | ACT-S128K32N-035F2 | 629 |
| 5962-9559507HMA | N | 01/07/2004 | 1 | AUSTIN SEMI. | | Y | AS8S128K32Q-35/883C | 629 |
| 5962-9559507HMA | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32-35G2UQ | 629 |
| 5962-9559507HMC | N | 01/07/2004 | 1 | AEROFLEX | | Y | ACT-S128K32N-035F2 | 629 |
| 5962-9559507HMC | N | 01/07/2004 | 1 | AUSTIN SEMI. | | Y | AS8S128K32Q-35/883C | 629 |
| 5962-9559507HMC | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32-35G2UQ | 629 |
| 5962-9559507HNA | N | 01/07/2004 | 1 | AUSTIN SEMI. | | Y | AS8S128K32QT-35/883 | 629 |
| 5962-9559507HNA | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32-35G2UQ | 629 |
| 5962-9559507HNC | N | 01/07/2004 | 1 | AUSTIN SEMI. | | Y | AS8S128K32QT-35/883 | 629 |
| 5962-9559507HNC | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32-35G2UQ | 629 |
| 5962-9559507HXA | N | 01/07/2004 | 1 | AEROFLEX | | Y | ACT-S128K32N-035F1 | 629 |
| 5962-9559507HXC | N | 01/07/2004 | 1 | AEROFLEX | | Y | ACT-S128K32N-035F1 | 629 |
| 5962-9559507HXC | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32-35G4Q | 629 |
| 5962-9559507HYA | N | 01/07/2004 | 1 | AEROFLEX | | Y | ACT-S128K32N-035F1 | 629 |
| 5962-9559507HYC | N | 01/07/2004 | 1 | AEROFLEX | | Y | ACT-S128K32N-035F1 | 629 |
| 5962-9559507HYC | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32-35G4TQ | 629 |
| 5962-9559507HZA | N | 01/07/2004 | 1 | AEROFLEX | | Y | ACT-S128K32N-035F2 | 629 |
| 5962-9559507HZC | N | 01/07/2004 | 1 | AEROFLEX | | Y | ACT-S128K32N-035F2 | 629 |
| 5962-9559508H9A | N | 01/07/2004 | 1 | AEROFLEX | | Y | ACT-S128K32N-025F18 | 629 |
| 5962-9559508H9A | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32-25G1UQ | 629 |
| 5962-9559508H9C | N | 01/07/2004 | 1 | AEROFLEX | | Y | ACT-S128K32N-025F18 | 629 |
| 5962-9559508H9C | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32-25G1UQ | 629 |
| 5962-9559508HAA | N | 01/07/2004 | 1 | AUSTIN SEMI. | | Y | AS8S128K32Q1-25/883 | 629 |
| 5962-9559508HAA | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32-25G2LQ | 629 |
| 5962-9559508HAC | N | 01/07/2004 | 1 | AUSTIN SEMI. | | Y | AS8S128K32Q1-25/883 | 629 |
| 5962-9559508HAC | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32-25G2LQ | 629 |
| 5962-9559508HBA | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32-25G1TQ | 629 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9559508HBC | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32-25G1TQ | 629 |
| 5962-9559508HMA | N | 01/07/2004 | 1 | AEROFLEX | | Y | ACT-S128K32N-025F2 | 629 |
| 5962-9559508HMA | N | 01/07/2004 | 1 | AUSTIN SEMI. | | Y | AS8S128K32Q-25/883C | 629 |
| 5962-9559508HMA | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32-25G2UQ | 629 |
| 5962-9559508HMC | N | 01/07/2004 | 1 | AEROFLEX | | Y | ACT-S128K32N-025F2 | 629 |
| 5962-9559508HMC | N | 01/07/2004 | 1 | AUSTIN SEMI. | | Y | AS8S128K32Q-25/883C | 629 |
| 5962-9559508HMC | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32-25G2UQ | 629 |
| 5962-9559508HNA | N | 01/07/2004 | 1 | AUSTIN SEMI. | | Y | AS8S128K32QT-25/883 | 629 |
| 5962-9559508HNA | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32-25G2UQ | 629 |
| 5962-9559508HNC | N | 01/07/2004 | 1 | AUSTIN SEMI. | | Y | AS8S128K32QT-25/883 | 629 |
| 5962-9559508HNC | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32-25G2UQ | 629 |
| 5962-9559508HXA | N | 01/07/2004 | 1 | AEROFLEX | | Y | ACT-S128K32N-025F1 | 629 |
| 5962-9559508HXC | N | 01/07/2004 | 1 | AEROFLEX | | Y | ACT-S128K32N-025F1 | 629 |
| 5962-9559508HXC | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32-25G4Q | 629 |
| 5962-9559508HYA | N | 01/07/2004 | 1 | AEROFLEX | | Y | ACT-S128K32N-025F1 | 629 |
| 5962-9559508HYC | N | 01/07/2004 | 1 | AEROFLEX | | Y | ACT-S128K32N-025F1 | 629 |
| 5962-9559508HYC | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32-25G4TQ | 629 |
| 5962-9559508HZA | N | 01/07/2004 | 1 | AEROFLEX | | Y | ACT-S128K32N-025F2 | 629 |
| 5962-9559508HZC | N | 01/07/2004 | 1 | AEROFLEX | | Y | ACT-S128K32N-025F2 | 629 |
| 5962-9559509H9A | N | 01/07/2004 | 1 | AEROFLEX | | Y | ACT-S128K32N-020F18 | 629 |
| 5962-9559509H9A | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32-20G1UQ | 629 |
| 5962-9559509H9C | N | 01/07/2004 | 1 | AEROFLEX | | Y | ACT-S128K32N-020F18 | 629 |
| 5962-9559509H9C | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32-20G1UQ | 629 |
| 5962-9559509HAA | N | 01/07/2004 | 1 | AUSTIN SEMI. | | Y | AS8S128K32Q1-20/883 | 629 |
| 5962-9559509HAA | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32-20G2LQ | 629 |
| 5962-9559509HAC | N | 01/07/2004 | 1 | AUSTIN SEMI. | | Y | AS8S128K32Q1-20/883 | 629 |
| 5962-9559509HAC | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32-20G2LQ | 629 |
| 5962-9559509HBA | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32-20G1TQ | 629 |
| 5962-9559509HBC | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32-20G1TQ | 629 |
| 5962-9559509HMA | N | 01/07/2004 | 1 | AEROFLEX | | Y | ACT-S128K32N-020F2 | 629 |
| 5962-9559509HMA | N | 01/07/2004 | 1 | AUSTIN SEMI. | | Y | AS8S128K32Q-20/883C | 629 |
| 5962-9559509HMA | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32-20G2UQ | 629 |
| 5962-9559509HMC | N | 01/07/2004 | 1 | AEROFLEX | | Y | ACT-S128K32N-020F2 | 629 |
| 5962-9559509HMC | N | 01/07/2004 | 1 | AUSTIN SEMI. | | Y | AS8S128K32Q-20/883C | 629 |
| 5962-9559509HMC | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32-20G2UQ | 629 |
| 5962-9559509HNA | N | 01/07/2004 | 1 | AUSTIN SEMI. | | Y | AS8S128K32QT-20/883 | 629 |
| 5962-9559509HNA | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32-20G2UQ | 629 |
| 5962-9559509HNC | N | 01/07/2004 | 1 | AUSTIN SEMI. | | Y | AS8S128K32QT-20/883 | 629 |
| 5962-9559509HNC | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32-20G2UQ | 629 |
| 5962-9559509HXA | N | 01/07/2004 | 1 | AEROFLEX | | Y | ACT-S128K32N-020F1 | 629 |
| 5962-9559509HXC | N | 01/07/2004 | 1 | AEROFLEX | | Y | ACT-S128K32N-020F1 | 629 |
| 5962-9559509HXC | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32-20G4Q | 629 |
| 5962-9559509HYA | N | 01/07/2004 | 1 | AEROFLEX | | Y | ACT-S128K32N-020F1 | 629 |
| 5962-9559509HYC | N | 01/07/2004 | 1 | AEROFLEX | | Y | ACT-S128K32N-020F1 | 629 |
| 5962-9559509HYC | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32-20G4TQ | 629 |
| 5962-9559509HZA | N | 01/07/2004 | 1 | AEROFLEX | | Y | ACT-S128K32N-020F2 | 629 |
| 5962-9559509HZC | N | 01/07/2004 | 1 | AEROFLEX | | Y | ACT-S128K32N-020F2 | 629 |
| 5962-9559510H9A | N | 01/07/2004 | 1 | AEROFLEX | | Y | ACT-S128K32N-017F18 | 629 |
| 5962-9559510H9A | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32-17G1UQ | 629 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9559510H9C | N | 01/07/2004 | 1 | AEROFLEX | | Y | ACT-S128K32N-017F18 | 629 |
| 5962-9559510H9C | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32-17G1UQ | 629 |
| 5962-9559510HAA | N | 01/07/2004 | 1 | AUSTIN SEMI. | | Y | AS8S128K32Q1-17/883 | 629 |
| 5962-9559510HAA | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32-17G2LQ | 629 |
| 5962-9559510HAC | N | 01/07/2004 | 1 | AUSTIN SEMI. | | Y | AS8S128K32Q1-17/883 | 629 |
| 5962-9559510HAC | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32-17G2LQ | 629 |
| 5962-9559510HBA | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32-17G1TQ | 629 |
| 5962-9559510HBC | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32-17G1TQ | 629 |
| 5962-9559510HMA | N | 01/07/2004 | 1 | AEROFLEX | | Y | ACT-S128K32N-017F2 | 629 |
| 5962-9559510HMA | N | 01/07/2004 | 1 | AUSTIN SEMI. | | Y | AS8S128K32Q-17/883C | 629 |
| 5962-9559510HMA | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32-17G2UQ | 629 |
| 5962-9559510HMC | N | 01/07/2004 | 1 | AEROFLEX | | Y | ACT-S128K32N-017F2 | 629 |
| 5962-9559510HMC | N | 01/07/2004 | 1 | AUSTIN SEMI. | | Y | AS8S128K32Q-17/883C | 629 |
| 5962-9559510HMC | N | 01/07/2004 | 1 | AUSTIN SEMI. | | Y | AS8S128K32QT-17/883 | 629 |
| 5962-9559510HMC | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32-17G2UQ | 629 |
| 5962-9559510HNA | N | 01/07/2004 | 1 | AUSTIN SEMI. | | Y | AS8S128K32QT-17/883 | 629 |
| 5962-9559510HNA | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32-17G2UQ | 629 |
| 5962-9559510HNC | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32-17G2UQ | 629 |
| 5962-9559510HXA | N | 01/07/2004 | 1 | AEROFLEX | | Y | ACT-S128K32N-017F1 | 629 |
| 5962-9559510HXC | N | 01/07/2004 | 1 | AEROFLEX | | Y | ACT-S128K32N-017F1 | 629 |
| 5962-9559510HXC | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32-17G4Q | 629 |
| 5962-9559510HYA | N | 01/07/2004 | 1 | AEROFLEX | | Y | ACT-S128K32N-017F1 | 629 |
| 5962-9559510HYC | N | 01/07/2004 | 1 | AEROFLEX | | Y | ACT-S128K32N-017F1 | 629 |
| 5962-9559510HYC | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32-17G4TQ | 629 |
| 5962-9559510HZA | N | 01/07/2004 | 1 | AEROFLEX | | Y | ACT-S128K32N-017F2 | 629 |
| 5962-9559510HZC | N | 01/07/2004 | 1 | AEROFLEX | | Y | ACT-S128K32N-017F2 | 629 |
| 5962-9559511H9A | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32-15G1UQ | 629 |
| 5962-9559511H9C | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32-15G1UQ | 629 |
| 5962-9559511HAA | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32-15G2LQ | 629 |
| 5962-9559511HAC | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32-15G2LQ | 629 |
| 5962-9559511HBA | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32-15G1TQ | 629 |
| 5962-9559511HBC | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32-15G1TQ | 629 |
| 5962-9559511HMA | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32-15G2UQ | 629 |
| 5962-9559511HMC | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32-15G2UQ | 629 |
| 5962-9559511HNA | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32-15G2UQ | 629 |
| 5962-9559511HNC | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32-15G2UQ | 629 |
| 5962-9559511HXA | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32-15G4Q | 629 |
| 5962-9559511HXC | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32-15G4Q | 629 |
| 5962-9559511HYA | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32-15G4TQ | 629 |
| 5962-9559511HYC | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32-15G4TQ | 629 |
| 5962-9559512H9A | N | 01/07/2004 | 1 | AEROFLEX | | Y | ACTS128K32N-055F18 | 629 |
| 5962-9559512H9A | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32H-55G1UQ | 629 |
| 5962-9559512H9C | N | 01/07/2004 | 1 | AEROFLEX | | Y | ACTS128K32N-055F18 | 629 |
| 5962-9559512H9C | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32H-55G1UQ | 629 |
| 5962-9559512HAA | N | 01/07/2004 | 1 | AUSTIN SEMI. | | Y | AS8S128K32Q1-55/883 | 629 |
| 5962-9559512HAA | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32H-55G2LQ | 629 |
| 5962-9559512HAC | N | 01/07/2004 | 1 | AUSTIN SEMI. | | Y | AS8S128K32Q1-55/883 | 629 |
| 5962-9559512HAC | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32H-55G2LQ | 629 |
| 5962-9559512HBA | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32H-55G1TQ | 629 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9559512HBC | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32H-55G1TQ | 629 |
| 5962-9559512HMA | N | 01/07/2004 | 1 | AUSTIN SEMI. | | Y | AS8S128K32Q-55/883C | 629 |
| 5962-9559512HMA | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32H-55G2Q | 629 |
| 5962-9559512HMC | N | 01/07/2004 | 1 | AUSTIN SEMI. | | Y | AS8S128K32Q-55/883C | 629 |
| 5962-9559512HMC | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32H-55G2UQ | 629 |
| 5962-9559512HNA | N | 01/07/2004 | 1 | AUSTIN SEMI. | | Y | AS8S128K32QT-55/883 | 629 |
| 5962-9559512HNA | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32H-55G2UQ | 629 |
| 5962-9559512HNC | N | 01/07/2004 | 1 | AUSTIN SEMI. | | Y | AS8S128K32QT-55/883 | 629 |
| 5962-9559512HNC | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32H-55G2UQ | 629 |
| 5962-9559512HXC | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32H-55G4Q | 629 |
| 5962-9559512HYC | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32H-55G4TQ | 629 |
| 5962-9559513H9A | N | 01/07/2004 | 1 | AEROFLEX | | Y | ACTS128K32N-045F18 | 629 |
| 5962-9559513H9A | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32H-45G1UQ | 629 |
| 5962-9559513H9C | N | 01/07/2004 | 1 | AEROFLEX | | Y | ACTS128K32N-045F18 | 629 |
| 5962-9559513H9C | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32H-45G1UQ | 629 |
| 5962-9559513HAA | N | 01/07/2004 | 1 | AUSTIN SEMI. | | Y | AS8S128K32Q1-45/883 | 629 |
| 5962-9559513HAA | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32H-45G2LQ | 629 |
| 5962-9559513HAC | N | 01/07/2004 | 1 | AUSTIN SEMI. | | Y | AS8S128K32Q1-45/883 | 629 |
| 5962-9559513HAC | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32H-45G2LQ | 629 |
| 5962-9559513HBA | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32H-45G1TQ | 629 |
| 5962-9559513HBC | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32H-45G1TQ | 629 |
| 5962-9559513HMA | N | 01/07/2004 | 1 | AUSTIN SEMI. | | Y | AS8S128K32Q-45/883C | 629 |
| 5962-9559513HMA | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32H-45G2UQ | 629 |
| 5962-9559513HMC | N | 01/07/2004 | 1 | AUSTIN SEMI. | | Y | AS8S128K32Q-45/883C | 629 |
| 5962-9559513HMC | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32H-45G2UQ | 629 |
| 5962-9559513HNA | N | 01/07/2004 | 1 | AUSTIN SEMI. | | Y | AS8S128K32QT-45/883 | 629 |
| 5962-9559513HNA | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32H-45G2UQ | 629 |
| 5962-9559513HNC | N | 01/07/2004 | 1 | AUSTIN SEMI. | | Y | AS8S128K32QT-45/883 | 629 |
| 5962-9559513HNC | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32H-45G2UQ | 629 |
| 5962-9559513HXC | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32H-45G4Q | 629 |
| 5962-9559513HYC | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32H-45G4TQ | 629 |
| 5962-9559514H9A | N | 01/07/2004 | 1 | AEROFLEX | | Y | ACTS128K32N-035F18 | 629 |
| 5962-9559514H9A | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32H-35G1UQ | 629 |
| 5962-9559514H9C | N | 01/07/2004 | 1 | AEROFLEX | | Y | ACTS128K32N-035F18 | 629 |
| 5962-9559514H9C | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32H-35G1UQ | 629 |
| 5962-9559514HAA | N | 01/07/2004 | 1 | AUSTIN SEMI. | | Y | AS8S128K32Q1-35/883 | 629 |
| 5962-9559514HAA | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32H-35G2LQ | 629 |
| 5962-9559514HAC | N | 01/07/2004 | 1 | AUSTIN SEMI. | | Y | AS8S128K32Q1-35/883 | 629 |
| 5962-9559514HAC | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32H-35G2LQ | 629 |
| 5962-9559514HBA | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32H-35G1TQ | 629 |
| 5962-9559514HBC | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32H-35G1TQ | 629 |
| 5962-9559514HMA | N | 01/07/2004 | 1 | AUSTIN SEMI. | | Y | AS8S128K32Q-35/883C | 629 |
| 5962-9559514HMA | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32H-35G2UQ | 629 |
| 5962-9559514HMC | N | 01/07/2004 | 1 | AUSTIN SEMI. | | Y | AS8S128K32Q-35/883C | 629 |
| 5962-9559514HMC | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32H-35G2UQ | 629 |
| 5962-9559514HNA | N | 01/07/2004 | 1 | AUSTIN SEMI. | | Y | AS8S128K32QT-25/883 | 629 |
| 5962-9559514HNA | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32H-35G2UQ | 629 |
| 5962-9559514HNC | N | 01/07/2004 | 1 | AUSTIN SEMI. | | Y | AS8S128K32QT-25/883 | 629 |
| 5962-9559514HNC | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32H-35G2UQ | 629 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9559514HXC | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32H-35G4Q | 629 |
| 5962-9559514HYC | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32H-35G4TQ | 629 |
| 5962-9559515H9A | N | 01/07/2004 | 1 | AEROFLEX | | Y | ACTS128K32N-025F18 | 629 |
| 5962-9559515H9A | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32H-25G1UQ | 629 |
| 5962-9559515H9C | N | 01/07/2004 | 1 | AEROFLEX | | Y | ACTS128K32N-025F18 | 629 |
| 5962-9559515H9C | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32H-25G1UQ | 629 |
| 5962-9559515HAA | N | 01/07/2004 | 1 | AUSTIN SEMI. | | Y | AS8S128K32Q1-25/883 | 629 |
| 5962-9559515HAA | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32H-25G2LQ | 629 |
| 5962-9559515HAC | N | 01/07/2004 | 1 | AUSTIN SEMI. | | Y | AS8S128K32Q1-25/883 | 629 |
| 5962-9559515HAC | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32H-25G2LQ | 629 |
| 5962-9559515HBA | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32H-25G1TQ | 629 |
| 5962-9559515HBC | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32H-25G1TQ | 629 |
| 5962-9559515HMA | N | 01/07/2004 | 1 | AUSTIN SEMI. | | Y | AS8S128K32Q-25/883C | 629 |
| 5962-9559515HMA | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32H-25G2UQ | 629 |
| 5962-9559515HMC | N | 01/07/2004 | 1 | AUSTIN SEMI. | | Y | AS8S128K32Q-25/883C | 629 |
| 5962-9559515HMC | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32H-25G2UQ | 629 |
| 5962-9559515HNA | N | 01/07/2004 | 1 | AUSTIN SEMI. | | Y | AS8S128K32QT-25/883 | 629 |
| 5962-9559515HNA | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32H-25G2UQ | 629 |
| 5962-9559515HNC | N | 01/07/2004 | 1 | AUSTIN SEMI. | | Y | AS8S128K32QT-25/883 | 629 |
| 5962-9559515HNC | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32H-25G2UQ | 629 |
| 5962-9559515HXC | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32H-25G4Q | 629 |
| 5962-9559515HYC | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32H-25G4TQ | 629 |
| 5962-9559516H9A | N | 01/07/2004 | 1 | AEROFLEX | | Y | ACTS128K32N-020F18 | 629 |
| 5962-9559516H9A | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32H-20G1UQ | 629 |
| 5962-9559516H9C | N | 01/07/2004 | 1 | AEROFLEX | | Y | ACTS128K32N-020F18 | 629 |
| 5962-9559516H9C | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32H-20G1UQ | 629 |
| 5962-9559516HAA | N | 01/07/2004 | 1 | AUSTIN SEMI. | | Y | AS8S128K32Q1-20/883 | 629 |
| 5962-9559516HAA | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32H-20G2LQ | 629 |
| 5962-9559516HAC | N | 01/07/2004 | 1 | AUSTIN SEMI. | | Y | AS8S128K32Q1-20/883 | 629 |
| 5962-9559516HAC | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32H-20G2LQ | 629 |
| 5962-9559516HBA | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32H-20G1TQ | 629 |
| 5962-9559516HBC | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32H-20G1TQ | 629 |
| 5962-9559516HMA | N | 01/07/2004 | 1 | AUSTIN SEMI. | | Y | AS8S128K32Q-20/883C | 629 |
| 5962-9559516HMA | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32H-20G2UQ | 629 |
| 5962-9559516HMC | N | 01/07/2004 | 1 | AUSTIN SEMI. | | Y | AS8S128K32Q-20/883C | 629 |
| 5962-9559516HMC | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32H-20G2UQ | 629 |
| 5962-9559516HNA | N | 01/07/2004 | 1 | AUSTIN SEMI. | | Y | AS8S128K32QT-20/883 | 629 |
| 5962-9559516HNA | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32H-20G2UQ | 629 |
| 5962-9559516HNC | N | 01/07/2004 | 1 | AUSTIN SEMI. | | Y | AS8S128K32QT-20/883 | 629 |
| 5962-9559516HNC | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32H-20G2UQ | 629 |
| 5962-9559516HXC | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32H-20G4Q | 629 |
| 5962-9559516HYC | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32H-20G4TQ | 629 |
| 5962-9559517H9A | N | 01/07/2004 | 1 | AEROFLEX | | Y | ACTS128K32N-017F18 | 629 |
| 5962-9559517H9A | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32H-17G1UQ | 629 |
| 5962-9559517H9C | N | 01/07/2004 | 1 | AEROFLEX | | Y | ACTS128K32N-017F18 | 629 |
| 5962-9559517H9C | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32H-17G1UQ | 629 |
| 5962-9559517HAA | N | 01/07/2004 | 1 | AUSTIN SEMI. | | Y | AS8S128K32Q1-17/883 | 629 |
| 5962-9559517HAA | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32H-17G2LQ | 629 |
| 5962-9559517HAC | N | 01/07/2004 | 1 | AUSTIN SEMI. | | Y | AS8S128K32Q1-17/883 | 629 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9559517HAC | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32H-17G2LQ | 629 |
| 5962-9559517HBA | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32H-17G1TQ | 629 |
| 5962-9559517HBC | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32H-17G1TQ | 629 |
| 5962-9559517HMA | N | 01/07/2004 | 1 | AUSTIN SEMI. | | Y | AS8S128K32Q-17/883C | 629 |
| 5962-9559517HMA | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32H-17G2UQ | 629 |
| 5962-9559517HMC | N | 01/07/2004 | 1 | AUSTIN SEMI. | | Y | AS8S128K32Q-17/883C | 629 |
| 5962-9559517HMC | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32H-17G2UQ | 629 |
| 5962-9559517HNA | N | 01/07/2004 | 1 | AUSTIN SEMI. | | Y | AS8S128K32QT-17/883 | 629 |
| 5962-9559517HNA | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32H-17G2UQ | 629 |
| 5962-9559517HNC | N | 01/07/2004 | 1 | AUSTIN SEMI. | | Y | AS8S128K32QT-17/883 | 629 |
| 5962-9559517HNC | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32H-17G2UQ | 629 |
| 5962-9559517HXC | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32H-17G4Q | 629 |
| 5962-9559517HYC | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32H-17G4TQ | 629 |
| 5962-9559518H9A | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32H-15G1UQ | 629 |
| 5962-9559518H9C | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32H-15G1UQ | 629 |
| 5962-9559518HAA | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32H-15G2LQ | 629 |
| 5962-9559518HAC | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32H-15G2LQ | 629 |
| 5962-9559518HBA | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32H-15G1TQ | 629 |
| 5962-9559518HBC | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32H-15G1TQ | 629 |
| 5962-9559518HMA | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32H-15G2UQ | 629 |
| 5962-9559518HMC | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32H-15G2UQ | 629 |
| 5962-9559518HNA | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32H-15G2UQ | 629 |
| 5962-9559518HNC | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32H-15G2UQ | 629 |
| 5962-9559518HXC | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32H-15G4Q | 629 |
| 5962-9559518HYC | N | 01/07/2004 | 1 | WHITE ELEC. | | Y | WS128K32H-15G4TQ | 629 |
| 5962-9559601M2A | A | 03/18/2002 | 1 | ANALOG (2) | | Y | AD813SE | 760 |
| 5962-9559701MPA | D | 06/20/2003 | 1 | ANALOG (2) | | Y | AD8036SQ | 719 |
| 5962-9559801MRA | A | 03/18/2002 | 1 | ANALOG (2) | | Y | AD641SQ | 719 |
| 5962-9559901QXC | B | 06/16/1999 | | (NONE) | | | CY7C386A (GEN) | 431 |
| 5962-9559902MXC | B | 06/16/1999 | | (NONE) | | | 16X24B (GEN) | 431 |
| 5962-9559902QXC | B | 06/16/1999 | | (NONE) | | | CY7C386A (GEN) | 431 |
| 5962-9559902MYC | B | 06/16/1999 | 2 | QUICKLOGIC | | | QL16X24B-0CG144M/8 | 431 |
| 5962-9559903MXC | B | 06/16/1999 | | (NONE) | | | 16X24B (GEN) | 431 |
| 5962-9559903QXC | B | 06/16/1999 | | (NONE) | | | CY7C386A (GEN) | 431 |
| 5962-9559903MYC | B | 06/16/1999 | 2 | QUICKLOGIC | | | QL16X24B-1CG144M/8 | 431 |
| 5962-9560001M9A | H | 05/25/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008F-45 | 629 |
| 5962-9560001M9A | H | 05/25/2004 | 1 | WHITE ELEC. | | Y | EDI88512CA45F32B | 629 |
| 5962-9560001MMA | H | 05/25/2004 | 1 | AUSTIN SEMI. | | Y | AS5C512K8ECJ-45 | 629 |
| 5962-9560001MMA | H | 05/25/2004 | 1 | WHITE ELEC. | | Y | EDI88512CA45N36B | 629 |
| 5962-9560001MNA | H | 05/25/2004 | 1 | AUSTIN SEMI. | | Y | AS5C512K8EC-45 | 629 |
| 5962-9560001MTA | H | 05/25/2004 | 1 | AUSTIN SEMI. | | Y | AS5C512K8F-45 | 629 |
| 5962-9560001MTA | H | 05/25/2004 | 1 | WHITE ELEC. | | Y | EDI88512CA45F36B | 629 |
| 5962-9560001MUA | H | 05/25/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008ECJ-45 | 629 |
| 5962-9560001MUA | H | 05/25/2004 | 1 | WHITE ELEC. | | Y | EDI88512CA45NB | 629 |
| 5962-9560001MXA | H | 05/25/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008CW-45 | 629 |
| 5962-9560001MXA | H | 05/25/2004 | 1 | WHITE ELEC. | | Y | EDI88512CA45CB | 629 |
| 5962-9560001MYA | H | 05/25/2004 | 1 | WHITE ELEC. | | Y | EDI88512CA45B32B | 629 |
| 5962-9560001MZA | H | 05/25/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008EC-45 | 629 |
| 5962-9560001MZA | H | 05/25/2004 | 1 | WHITE ELEC. | | Y | EDI88512CA45L32B | 629 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9560002M8A | H | 05/25/2004 | | (NONE) | | | 684002-35 (GEN) | 629 |
| 5962-9560002M9A | H | 05/25/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008F-35 | 629 |
| 5962-9560002M9A | H | 05/25/2004 | 1 | WHITE ELEC. | | Y | EDI88512CA35F32B | 629 |
| 5962-9560002MMA | H | 05/25/2004 | 1 | AUSTIN SEMI. | | Y | AS5C512K8ECJ-35 | 629 |
| 5962-9560002MMA | H | 05/25/2004 | 1 | WHITE ELEC. | | Y | EDI88512CA35N36B | 629 |
| 5962-9560002MNA | H | 05/25/2004 | 1 | AUSTIN SEMI. | | Y | AS5C512K8EC-35 | 629 |
| 5962-9560002MTA | H | 05/25/2004 | 1 | AUSTIN SEMI. | | Y | AS5C512K8F-35 | 629 |
| 5962-9560002MTA | H | 05/25/2004 | 1 | WHITE ELEC. | | Y | EDI88512CA35F36B | 629 |
| 5962-9560002MUA | H | 05/25/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008ECJ-35 | 629 |
| 5962-9560002MUA | H | 05/25/2004 | 1 | WHITE ELEC. | | Y | EDI88512CA35NB | 629 |
| 5962-9560002MXA | H | 05/25/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008CW-35 | 629 |
| 5962-9560002MXA | H | 05/25/2004 | 1 | WHITE ELEC. | | Y | EDI88512CA35CB | 629 |
| 5962-9560002MYA | H | 05/25/2004 | 1 | WHITE ELEC. | | Y | EDI88512CA35B32B | 629 |
| 5962-9560002MZA | H | 05/25/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008EC-35 | 629 |
| 5962-9560002MZA | H | 05/25/2004 | 1 | WHITE ELEC. | | Y | EDI88512CA35L32B | 629 |
| 5962-9560003M8A | H | 05/25/2004 | | (NONE) | | | 684002-25 (GEN) | 629 |
| 5962-9560003M9A | H | 05/25/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008F-25 | 629 |
| 5962-9560003M9A | H | 05/25/2004 | 1 | WHITE ELEC. | | Y | EDI88512CA25F32B | 629 |
| 5962-9560003MMA | H | 05/25/2004 | 1 | AUSTIN SEMI. | | Y | AS5C512K8ECJ-25 | 629 |
| 5962-9560003MMA | H | 05/25/2004 | 1 | WHITE ELEC. | | Y | EDI88512CA25N36B | 629 |
| 5962-9560003MNA | H | 05/25/2004 | 1 | AUSTIN SEMI. | | Y | AS5C512K8EC-25 | 629 |
| 5962-9560003MTA | H | 05/25/2004 | 1 | AUSTIN SEMI. | | Y | AS5C512K8F-25 | 629 |
| 5962-9560003MTA | H | 05/25/2004 | 1 | WHITE ELEC. | | Y | EDI88512CA25F36B | 629 |
| 5962-9560003MUA | H | 05/25/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008ECJ-25 | 629 |
| 5962-9560003MUA | H | 05/25/2004 | 1 | WHITE ELEC. | | Y | EDI88512CA25NB | 629 |
| 5962-9560003MXA | H | 05/25/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008CW-25 | 629 |
| 5962-9560003MXA | H | 05/25/2004 | 1 | WHITE ELEC. | | Y | EDI88512CA25CB | 629 |
| 5962-9560003MYA | H | 05/25/2004 | 1 | WHITE ELEC. | | Y | EDI88512CA25B32B | 629 |
| 5962-9560003MZA | H | 05/25/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008EC-25 | 629 |
| 5962-9560003MZA | H | 05/25/2004 | 1 | WHITE ELEC. | | Y | EDI88512CA25L32B | 629 |
| 5962-9560004M8A | H | 05/25/2004 | | (NONE) | | | 684002-20 (GEN) | 629 |
| 5962-9560004M9A | H | 05/25/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008F-20 | 629 |
| 5962-9560004M9A | H | 05/25/2004 | 1 | WHITE ELEC. | | Y | EDI88512CA20F32B | 629 |
| 5962-9560004MMA | H | 05/25/2004 | 1 | AUSTIN SEMI. | | Y | AS5C512K8ECJ-20 | 629 |
| 5962-9560004MMA | H | 05/25/2004 | 1 | WHITE ELEC. | | Y | EDI88512CA20N36B | 629 |
| 5962-9560004MNA | H | 05/25/2004 | 1 | AUSTIN SEMI. | | Y | AS5C512K8EC-20 | 629 |
| 5962-9560004MTA | H | 05/25/2004 | 1 | AUSTIN SEMI. | | Y | AS5C512K8F-20 | 629 |
| 5962-9560004MTA | H | 05/25/2004 | 1 | WHITE ELEC. | | Y | EDI88512CA20F36B | 629 |
| 5962-9560004MUA | H | 05/25/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008ECJ-20 | 629 |
| 5962-9560004MUA | H | 05/25/2004 | 1 | WHITE ELEC. | | Y | EDI88512CA20NB | 629 |
| 5962-9560004MXA | H | 05/25/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008CW-20 | 629 |
| 5962-9560004MXA | H | 05/25/2004 | 1 | WHITE ELEC. | | Y | EDI88512CA20CB | 629 |
| 5962-9560004MYA | H | 05/25/2004 | 1 | WHITE ELEC. | | Y | EDI88512CA20B32B | 629 |
| 5962-9560004MZA | H | 05/25/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008EC-20 | 629 |
| 5962-9560004MZA | H | 05/25/2004 | 1 | WHITE ELEC. | | Y | EDI88512CA20L32B | 629 |
| 5962-9560005M9A | H | 05/25/2004 | 1 | WHITE ELEC. | | Y | EDI88512LPA45F32B | 629 |
| 5962-9560005MMA | H | 05/25/2004 | 1 | WHITE ELEC. | | Y | EDI88512LPA45N36B | 629 |
| 5962-9560005MNA | H | 05/25/2004 | | (NONE) | | | 5C512K8-45L (GEN) | 629 |
| 5962-9560005MTA | H | 05/25/2004 | 1 | WHITE ELEC. | | Y | EDI88512LPA45F36B | 629 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9560005MUA | H | 05/25/2004 | 1 | WHITE ELEC. | | Y | EDI88512LPA45NB | 629 |
| 5962-9560005MXA | H | 05/25/2004 | 1 | WHITE ELEC. | | Y | EDI88512LPA45CB | 629 |
| 5962-9560005MYA | H | 05/25/2004 | 1 | WHITE ELEC. | | Y | EDI88512LPA45B32B | 629 |
| 5962-9560005MZA | H | 05/25/2004 | 1 | WHITE ELEC. | | Y | EDI88512LPA45L32B | 629 |
| 5962-9560006M8A | H | 05/25/2004 | | (NONE) | | | 684002-35 (GEN) | 629 |
| 5962-9560006M9A | H | 05/25/2004 | 1 | WHITE ELEC. | | Y | EDI88512LPA35F32B | 629 |
| 5962-9560006MMA | H | 05/25/2004 | 1 | WHITE ELEC. | | Y | EDI88512LPA35N36B | 629 |
| 5962-9560006MNA | H | 05/25/2004 | | (NONE) | | | 5C512K8-35L (GEN) | 629 |
| 5962-9560006MTA | H | 05/25/2004 | 1 | WHITE ELEC. | | Y | EDI88512LPA35F36B | 629 |
| 5962-9560006MUA | H | 05/25/2004 | 1 | WHITE ELEC. | | Y | EDI88512LPA35NB | 629 |
| 5962-9560006MXA | H | 05/25/2004 | 1 | WHITE ELEC. | | Y | EDI88512LPA35CB | 629 |
| 5962-9560006MYA | H | 05/25/2004 | 1 | WHITE ELEC. | | Y | EDI88512LPA35B32B | 629 |
| 5962-9560006MZA | H | 05/25/2004 | 1 | WHITE ELEC. | | Y | EDI88512LPA35L32B | 629 |
| 5962-9560007M8A | H | 05/25/2004 | | (NONE) | | | 684002-25 (GEN) | 629 |
| 5962-9560007M9A | H | 05/25/2004 | 1 | WHITE ELEC. | | Y | EDI88512LPA25F32B | 629 |
| 5962-9560007MMA | H | 05/25/2004 | 1 | WHITE ELEC. | | Y | EDI88512LPA25N36B | 629 |
| 5962-9560007MNA | H | 05/25/2004 | | (NONE) | | | 5C512K8-25L (GEN) | 629 |
| 5962-9560007MTA | H | 05/25/2004 | 1 | WHITE ELEC. | | Y | EDI88512LPA25F36B | 629 |
| 5962-9560007MUA | H | 05/25/2004 | 1 | WHITE ELEC. | | Y | EDI88512LPA25NB | 629 |
| 5962-9560007MXA | H | 05/25/2004 | 1 | WHITE ELEC. | | Y | EDI88512LPA25CB | 629 |
| 5962-9560007MYA | H | 05/25/2004 | 1 | WHITE ELEC. | | Y | EDI88512LPA25B32B | 629 |
| 5962-9560007MZA | H | 05/25/2004 | 1 | WHITE ELEC. | | Y | EDI88512LPA25L32B | 629 |
| 5962-9560008M8A | H | 05/25/2004 | | (NONE) | | | 684002-20 (GEN) | 629 |
| 5962-9560008M9A | H | 05/25/2004 | 1 | WHITE ELEC. | | Y | EDI88512LPA20F32B | 629 |
| 5962-9560008MMA | H | 05/25/2004 | 1 | WHITE ELEC. | | Y | EDI88512LPA20N36B | 629 |
| 5962-9560008MNA | H | 05/25/2004 | | (NONE) | | | 5C512K8-20L (GEN) | 629 |
| 5962-9560008MTA | H | 05/25/2004 | 1 | WHITE ELEC. | | Y | EDI88512LPA20F36B | 629 |
| 5962-9560008MUA | H | 05/25/2004 | 1 | WHITE ELEC. | | Y | EDI88512LPA20NB | 629 |
| 5962-9560008MXA | H | 05/25/2004 | 1 | WHITE ELEC. | | Y | EDI88512LPA20CB | 629 |
| 5962-9560008MYA | H | 05/25/2004 | 1 | WHITE ELEC. | | Y | EDI88512LPA20B32B | 629 |
| 5962-9560008MZA | H | 05/25/2004 | 1 | WHITE ELEC. | | Y | EDI88512LPA20L32B | 629 |
| 5962-9560009Q9A | H | 05/25/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008F-45L | 629 |
| 5962-9560009Q9A | H | 05/25/2004 | 1 | WHITE ELEC. | | Y | EDI88512LPA45F32B | 629 |
| 5962-9560009QMA | H | 05/25/2004 | 1 | AUSTIN SEMI. | | Y | AS5C512K8ECJ-45L | 629 |
| 5962-9560009QMA | H | 05/25/2004 | 1 | WHITE ELEC. | | Y | EDI88512LPA45N36B | 629 |
| 5962-9560009QNA | H | 05/25/2004 | 1 | AUSTIN SEMI. | | Y | AS5C512K8EC-45L | 629 |
| 5962-9560009QTA | H | 05/25/2004 | 1 | AUSTIN SEMI. | | Y | AS5C512K8F-45L | 629 |
| 5962-9560009QTA | H | 05/25/2004 | 1 | WHITE ELEC. | | Y | EDI88512LPA45F36B | 629 |
| 5962-9560009QUA | H | 05/25/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008ECJ-45L | 629 |
| 5962-9560009QUA | H | 05/25/2004 | 1 | WHITE ELEC. | | Y | EDI88512LPA45NB | 629 |
| 5962-9560009QXA | H | 05/25/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008CW-45L | 629 |
| 5962-9560009QXA | H | 05/25/2004 | 1 | WHITE ELEC. | | Y | EDI88512LPA45CB | 629 |
| 5962-9560009QZA | H | 05/25/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008EC-45L | 629 |
| 5962-9560009QZA | H | 05/25/2004 | 1 | WHITE ELEC. | | Y | EDI88512LPA45L32B | 629 |
| 5962-9560010Q9A | H | 05/25/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008F-35L | 629 |
| 5962-9560010Q9A | H | 05/25/2004 | 1 | WHITE ELEC. | | Y | EDI88512LPA35F32B | 629 |
| 5962-9560010QMA | H | 05/25/2004 | 1 | AUSTIN SEMI. | | Y | AS5C512K8ECJ-35L | 629 |
| 5962-9560010QMA | H | 05/25/2004 | 1 | WHITE ELEC. | | Y | EDI88512LPA35N36B | 629 |
| 5962-9560010QNA | H | 05/25/2004 | 1 | AUSTIN SEMI. | | Y | AS5C512K8EC-35L | 629 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9560010QTA | H | 05/25/2004 | 1 | AUSTIN SEMI. | | Y | AS5C512K8F-35L | 629 |
| 5962-9560010QTA | H | 05/25/2004 | 1 | WHITE ELEC. | | Y | EDI88512LPA35F36B | 629 |
| 5962-9560010QUA | H | 05/25/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008ECJ-35L | 629 |
| 5962-9560010QUA | H | 05/25/2004 | 1 | WHITE ELEC. | | Y | EDI88512LPA35NB | 629 |
| 5962-9560010QXA | H | 05/25/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008CW-35L | 629 |
| 5962-9560010QXA | H | 05/25/2004 | 1 | WHITE ELEC. | | Y | EDI88512LPA35CB | 629 |
| 5962-9560010QZA | H | 05/25/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008EC-35L | 629 |
| 5962-9560010QZA | H | 05/25/2004 | 1 | WHITE ELEC. | | Y | EDI88512LPA35L32B | 629 |
| 5962-9560011Q9A | H | 05/25/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008F-25L | 629 |
| 5962-9560011Q9A | H | 05/25/2004 | 1 | WHITE ELEC. | | Y | EDI88512LPA25F32B | 629 |
| 5962-9560011QMA | H | 05/25/2004 | 1 | AUSTIN SEMI. | | Y | AS5C512K8ECJ-25L | 629 |
| 5962-9560011QMA | H | 05/25/2004 | 1 | WHITE ELEC. | | Y | EDI88512LPA25N36B | 629 |
| 5962-9560011QNA | H | 05/25/2004 | 1 | AUSTIN SEMI. | | Y | AS5C512K8EC-25L | 629 |
| 5962-9560011QTA | H | 05/25/2004 | 1 | AUSTIN SEMI. | | Y | AS5C512K8F-25L | 629 |
| 5962-9560011QTA | H | 05/25/2004 | 1 | WHITE ELEC. | | Y | EDI88512LPA25F36B | 629 |
| 5962-9560011QUA | H | 05/25/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008ECJ-25L | 629 |
| 5962-9560011QUA | H | 05/25/2004 | 1 | WHITE ELEC. | | Y | EDI88512LPA25NB | 629 |
| 5962-9560011QXA | H | 05/25/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008CW-25L | 629 |
| 5962-9560011QXA | H | 05/25/2004 | 1 | WHITE ELEC. | | Y | EDI88512LPA25CB | 629 |
| 5962-9560011QZA | H | 05/25/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008EC-25L | 629 |
| 5962-9560011QZA | H | 05/25/2004 | 1 | WHITE ELEC. | | Y | EDI88512LPA25L32B | 629 |
| 5962-9560012Q9A | H | 05/25/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008F-20L | 629 |
| 5962-9560012Q9A | H | 05/25/2004 | 1 | WHITE ELEC. | | Y | EDI88512LPA20F32B | 629 |
| 5962-9560012QMA | H | 05/25/2004 | 1 | AUSTIN SEMI. | | Y | AS5C512K8ECJ-20L | 629 |
| 5962-9560012QMA | H | 05/25/2004 | 1 | WHITE ELEC. | | Y | EDI88512LPA20N36B | 629 |
| 5962-9560012QNA | H | 05/25/2004 | 1 | AUSTIN SEMI. | | Y | AS5C512K8EC-20L | 629 |
| 5962-9560012QTA | H | 05/25/2004 | 1 | AUSTIN SEMI. | | Y | AS5C512K8F-20L | 629 |
| 5962-9560012QTA | H | 05/25/2004 | 1 | WHITE ELEC. | | Y | EDI88512LPA20F36B | 629 |
| 5962-9560012QUA | H | 05/25/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008ECJ-20L | 629 |
| 5962-9560012QUA | H | 05/25/2004 | 1 | WHITE ELEC. | | Y | EDI88512LPA20NB | 629 |
| 5962-9560012QXA | H | 05/25/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008CW-20L | 629 |
| 5962-9560012QXA | H | 05/25/2004 | 1 | WHITE ELEC. | | Y | EDI88512LPA20CB | 629 |
| 5962-9560012QZA | H | 05/25/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008EC-20L | 629 |
| 5962-9560012QZA | H | 05/25/2004 | 1 | WHITE ELEC. | | Y | EDI88512LPA20L32B | 629 |
| 5962-9560013Q9A | H | 05/25/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008F-15L | 629 |
| 5962-9560013Q9A | H | 05/25/2004 | 1 | WHITE ELEC. | | Y | EDI88512LPA15F32B | 629 |
| 5962-9560013QMA | H | 05/25/2004 | 1 | AUSTIN SEMI. | | Y | AS5C512K8ECJ-15L | 629 |
| 5962-9560013QMA | H | 05/25/2004 | 1 | WHITE ELEC. | | Y | EDI88512LPA15N36B | 629 |
| 5962-9560013QNA | H | 05/25/2004 | 1 | AUSTIN SEMI. | | Y | AS5C512K8EC-15L | 629 |
| 5962-9560013QTA | H | 05/25/2004 | 1 | AUSTIN SEMI. | | Y | AS5C512K8F-15L | 629 |
| 5962-9560013QTA | H | 05/25/2004 | 1 | WHITE ELEC. | | Y | EDI88512LPA15F36B | 629 |
| 5962-9560013QUA | H | 05/25/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008ECJ-15L | 629 |
| 5962-9560013QUA | H | 05/25/2004 | 1 | WHITE ELEC. | | Y | EDI88512LPA15NB | 629 |
| 5962-9560013QXA | H | 05/25/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008CW-15L | 629 |
| 5962-9560013QXA | H | 05/25/2004 | 1 | WHITE ELEC. | | Y | EDI88512LPA15CB | 629 |
| 5962-9560013QZA | H | 05/25/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008EC-15L | 629 |
| 5962-9560013QZA | H | 05/25/2004 | 1 | WHITE ELEC. | | Y | EDI88512LPA15L32B | 629 |
| 5962-9560014Q9A | H | 05/25/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008F-15 | 629 |
| 5962-9560014Q9A | H | 05/25/2004 | 1 | WHITE ELEC. | | Y | EDI88512CA15F32B | 629 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9560014QMA | H | 05/25/2004 | 1 | AUSTIN SEMI. | | Y | AS5C512K8ECJ-15 | 629 |
| 5962-9560014QMA | H | 05/25/2004 | 1 | WHITE ELEC. | | Y | EDI88512CA15N36B | 629 |
| 5962-9560014QNA | H | 05/25/2004 | 1 | AUSTIN SEMI. | | Y | AS5C512K8EC-15 | 629 |
| 5962-9560014QTA | H | 05/25/2004 | 1 | AUSTIN SEMI. | | Y | AS5C512K8F-15 | 629 |
| 5962-9560014QTA | H | 05/25/2004 | 1 | WHITE ELEC. | | Y | EDI88512CA15F36B | 629 |
| 5962-9560014QUA | H | 05/25/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008ECJ-15 | 629 |
| 5962-9560014QUA | H | 05/25/2004 | 1 | WHITE ELEC. | | Y | EDI88512CA15NB | 629 |
| 5962-9560014QXA | H | 05/25/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008CW-15 | 629 |
| 5962-9560014QXA | H | 05/25/2004 | 1 | WHITE ELEC. | | Y | EDI88512CA15CB | 629 |
| 5962-9560014QZA | H | 05/25/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008EC-15 | 629 |
| 5962-9560014QZA | H | 05/25/2004 | 1 | WHITE ELEC. | | Y | EDI88512CA15L32B | 629 |
| 5962-9560015Q9A | H | 05/25/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008F-12L | 629 |
| 5962-9560015Q9A | H | 05/25/2004 | 1 | WHITE ELEC. | | Y | EDI88512LPA12F32B | 629 |
| 5962-9560015QMA | H | 05/25/2004 | 1 | AUSTIN SEMI. | | Y | AS5C512K8ECJ-12L | 629 |
| 5962-9560015QMA | H | 05/25/2004 | 1 | WHITE ELEC. | | Y | EDI88512LPA12N36B | 629 |
| 5962-9560015QNA | H | 05/25/2004 | 1 | AUSTIN SEMI. | | Y | AS5C512K8EC-12L | 629 |
| 5962-9560015QTA | H | 05/25/2004 | 1 | AUSTIN SEMI. | | Y | AS5C512K8F-12L | 629 |
| 5962-9560015QTA | H | 05/25/2004 | 1 | WHITE ELEC. | | Y | EDI88512LPA12F36B | 629 |
| 5962-9560015QUA | H | 05/25/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008ECJ-12L | 629 |
| 5962-9560015QUA | H | 05/25/2004 | 1 | WHITE ELEC. | | Y | EDI88512LPA12NB | 629 |
| 5962-9560015QXA | H | 05/25/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008CW-12L | 629 |
| 5962-9560015QXA | H | 05/25/2004 | 1 | WHITE ELEC. | | Y | EDI88512LPA12CB | 629 |
| 5962-9560015QZA | H | 05/25/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008EC-12L | 629 |
| 5962-9560015QZA | H | 05/25/2004 | 1 | WHITE ELEC. | | Y | EDI88512LPA12L32B | 629 |
| 5962-9560016Q9A | H | 05/25/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008F-12 | 629 |
| 5962-9560016Q9A | H | 05/25/2004 | 1 | WHITE ELEC. | | Y | EDI88512CA12F32B | 629 |
| 5962-9560016QMA | H | 05/25/2004 | 1 | AUSTIN SEMI. | | Y | AS5C512K8ECJ-12 | 629 |
| 5962-9560016QMA | H | 05/25/2004 | 1 | WHITE ELEC. | | Y | EDI88512CA12N36B | 629 |
| 5962-9560016QNA | H | 05/25/2004 | 1 | AUSTIN SEMI. | | Y | AS5C512K8EC-12 | 629 |
| 5962-9560016QTA | H | 05/25/2004 | 1 | AUSTIN SEMI. | | Y | AS5C512K8F-12 | 629 |
| 5962-9560016QTA | H | 05/25/2004 | 1 | WHITE ELEC. | | Y | EDI88512CA12F36B | 629 |
| 5962-9560016QUA | H | 05/25/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008ECJ-12 | 629 |
| 5962-9560016QUA | H | 05/25/2004 | 1 | WHITE ELEC. | | Y | EDI88512CA12NB | 629 |
| 5962-9560016QXA | H | 05/25/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008CW-12 | 629 |
| 5962-9560016QXA | H | 05/25/2004 | 1 | WHITE ELEC. | | Y | EDI88512CA12CB | 629 |
| 5962-9560016QZA | H | 05/25/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008EC-12 | 629 |
| 5962-9560016QZA | H | 05/25/2004 | 1 | WHITE ELEC. | | Y | EDI88512CA12L32B | 629 |
| 5962-9560101HXA | B | 09/11/1998 | 1 | INTERPOINT | | Y | MHF+28512T/883 | 594 |
| 5962-9560101HXC | B | 09/11/1998 | 1 | INTERPOINT | | Y | MHF+28512T/883 | 594 |
| 5962-9560101HZA | B | 09/11/1998 | 1 | INTERPOINT | | Y | MHF+28512TF/883 | 594 |
| 5962-9560101HZC | B | 09/11/1998 | 1 | INTERPOINT | | Y | MHF+28512TF/883 | 594 |
| 5962-9560201HXA | B | 09/11/1998 | 1 | INTERPOINT | | Y | MHF+28515T/883 | 594 |
| 5962-9560201HXC | B | 09/11/1998 | 1 | INTERPOINT | | Y | MHF+28515T/883 | 594 |
| 5962-9560201HZA | B | 09/11/1998 | 1 | INTERPOINT | | Y | MHF+28515TF/883 | 594 |
| 5962-9560201HZC | B | 09/11/1998 | 1 | INTERPOINT | | Y | MHF+28515TF/883 | 594 |
| 5962-9560301QPA | C | 09/03/2003 | 2 | NATIONAL | | Y | LMC6462AMJ-QML | 710 |
| 5962-9560302QCA | C | 09/03/2003 | 2 | NATIONAL | | Y | LMC6464AMJ-QML | 713 |
| 5962-9560302QXA | C | 09/03/2003 | 2 | NATIONAL | | Y | LMC6464AMWG-QML | 713 |
| 5962-9560401QPA | C | 08/07/2001 | 3 | NATIONAL | | Y | LM6172AMJ-QML | 710 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9560401VPA | C | 08/07/2001 | 3 | NATIONAL | | Y | LM6172AMJ-QMLV | 710 |
| 5962F9560401QPA | C | 08/07/2001 | 3 | NATIONAL | | Y | LM6172AMJFQML | 710 |
| 5962F9560401VPA | C | 08/07/2001 | 3 | NATIONAL | | Y | LM6172AMJFQMLV | 710 |
| 5962-9560401QXA | C | 08/07/2001 | 3 | NATIONAL | | Y | LM6172AMWG-QML | 710 |
| 5962-9560401VXA | C | 08/07/2001 | 3 | NATIONAL | | Y | LM6172AMWG-QMLV | 710 |
| 5962F9560401QXA | C | 08/07/2001 | 3 | NATIONAL | | Y | LM6172AMWGFQML | 710 |
| 5962F9560401VXA | C | 08/07/2001 | 3 | NATIONAL | | Y | LM6172AMWGFQMLV | 710 |
| 5962-9560501HXA | | 09/14/1995 | | (NONE) | 05/31/2002 | | 21002 (GEN) | 787 |
| 5962-9560502HXA | | 09/14/1995 | | (NONE) | 05/31/2002 | | 21005 (GEN) | 787 |
| 5962-9560503HXA | | 09/14/1995 | | (NONE) | 05/31/2002 | | 21007 (GEN) | 787 |
| 5962-9560504HXA | | 09/14/1995 | | (NONE) | 05/31/2002 | | 21010 (GEN) | 787 |
| 5962-9560505HXA | | 09/14/1995 | | (NONE) | 05/31/2002 | | 21015 (GEN) | 787 |
| 5962-9560506HXA | | 09/14/1995 | | (NONE) | 05/31/2002 | | 21020 (GEN) | 787 |
| 5962-9560507HXA | | 09/14/1995 | | (NONE) | 05/31/2002 | | 21025 (GEN) | 787 |
| 5962-9560601Q2A | | 07/12/1995 | 2 | TI | | Y | SNJ54ABT2245FK | 590 |
| 5962-9560601QRA | | 07/12/1995 | 2 | TI | | Y | SNJ54ABT2245J | 590 |
| 5962-9560601QSA | | 07/12/1995 | 2 | TI | | Y | SNJ54ABT2245W | 590 |
| 5962-9560701HXC | A | 11/13/1998 | 1 | ANALOG (6) | | Y | ADDC02805SATV/QML | 594 |
| 5962-9560801NXD | A | 03/18/1997 | 1 | TI | | Y | ACT3641PCB | 670 |
| 5962-9560801QYA | A | 03/18/1997 | | (NONE) | | | 54ACT3641 (GEN) | 670 |
| 5962-9560901NXD | D | 03/28/2002 | 2 | TI | | Y | ABT3614PCB | 670 |
| 5962-9560901QYA | D | 03/28/2002 | | (NONE) | | | 54ABT3614 (GEN) | 670 |
| 5962-9561001MUC | A | 10/04/1996 | | (NONE) | 07/01/2000 | | 3142A-5 (GEN) | 431 |
| 5962-9561001MXC | A | 10/04/1996 | | (NONE) | 07/01/2000 | | 3142A-5 (GEN) | 431 |
| 5962-9561001MYC | A | 10/04/1996 | | (NONE) | 07/01/2000 | | 3142A-5 (GEN) | 431 |
| 5962-9561001MZC | A | 10/04/1996 | | (NONE) | 07/01/2000 | | 3142A-5 (GEN) | 431 |
| 5962-9561002MUC | A | 10/04/1996 | | (NONE) | 07/01/2000 | | 3142A-4 (GEN) | 431 |
| 5962-9561002MXC | A | 10/04/1996 | | (NONE) | 07/01/2000 | | 3142A-4 (GEN) | 431 |
| 5962-9561002MYC | A | 10/04/1996 | | (NONE) | 07/01/2000 | | 3142A-4 (GEN) | 431 |
| 5962-9561002MZC | A | 10/04/1996 | | (NONE) | 07/01/2000 | | 3142A-4 (GEN) | 431 |
| 5962-9561101MXC | A | 10/04/1996 | | (NONE) | 07/01/2000 | | 3190A-5 (GEN) | 431 |
| 5962-9561101MYC | A | 10/04/1996 | | (NONE) | 07/01/2000 | | 3190A-5 (GEN) | 431 |
| 5962-9561101MZC | A | 10/04/1996 | | (NONE) | 07/01/2000 | | 3190A-5 (GEN) | 431 |
| 5962-9561102MXC | A | 10/04/1996 | | (NONE) | 07/01/2000 | | 3190A-4 (GEN) | 431 |
| 5962-9561102MYC | A | 10/04/1996 | | (NONE) | 07/01/2000 | | 3190A-4 (GEN) | 431 |
| 5962-9561102MZC | A | 10/04/1996 | | (NONE) | 07/01/2000 | | 3190A-4 (GEN) | 431 |
| 5962-9561201MXC | A | 10/04/1996 | | (NONE) | 07/01/2000 | | 3195A-5 (GEN) | 431 |
| 5962-9561201MYC | A | 10/04/1996 | | (NONE) | 07/01/2000 | | 3195A-5 (GEN) | 431 |
| 5962-9561201MZC | A | 10/04/1996 | | (NONE) | 07/01/2000 | | 3195A-5 (GEN) | 431 |
| 5962-9561202MXC | A | 10/04/1996 | | (NONE) | 07/01/2000 | | 3195A-4 (GEN) | 431 |
| 5962-9561202MYC | A | 10/04/1996 | | (NONE) | 07/01/2000 | | 3195A-4 (GEN) | 431 |
| 5962-9561202MZC | A | 10/04/1996 | | (NONE) | 07/01/2000 | | 3195A-4 (GEN) | 431 |
| 5962-9561301HTA | H | 05/28/2004 | 1 | WHITE ELEC. | | Y | WMS512K8-120DE | 629 |
| 5962-9561301HTC | H | 05/28/2004 | 1 | WHITE ELEC. | | Y | WMS512K8-120DE | 629 |
| 5962-9561301HYA | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4009CW-120/H | 629 |
| 5962-9561301HYA | H | 05/28/2004 | 1 | WHITE ELEC. | | Y | WMS512K8-120C | 629 |
| 5962-9561301HYC | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4009CW-120/H | 629 |
| 5962-9561301HYC | H | 05/28/2004 | 1 | WHITE ELEC. | | Y | WMS512K8-120C | 629 |
| 5962-9561302HTA | H | 05/28/2004 | 1 | WHITE ELEC. | | Y | WMS512K8-100DE | 629 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9561302HTC | H | 05/28/2004 | 1 | WHITE ELEC. | | Y | WMS512K8-100DE | 629 |
| 5962-9561302HYA | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4009CW-100/H | 629 |
| 5962-9561302HYA | H | 05/28/2004 | 1 | WHITE ELEC. | | Y | WMS512K8-100C | 629 |
| 5962-9561302HYC | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4009CW-100/H | 629 |
| 5962-9561302HYC | H | 05/28/2004 | 1 | WHITE ELEC. | | Y | WMS512K8-100C | 629 |
| 5962-9561303HTA | H | 05/28/2004 | 1 | WHITE ELEC. | | Y | WMS512K8-85DE | 629 |
| 5962-9561303HTC | H | 05/28/2004 | 1 | WHITE ELEC. | | Y | WMS512K8-85DE | 629 |
| 5962-9561303HYA | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4009CW-85/H | 629 |
| 5962-9561303HYA | H | 05/28/2004 | 1 | WHITE ELEC. | | Y | WMS512K8-85C | 629 |
| 5962-9561303HYC | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4009CW-85/H | 629 |
| 5962-9561303HYC | H | 05/28/2004 | 1 | WHITE ELEC. | | Y | WMS512K8-85C | 629 |
| 5962-9561304HTA | H | 05/28/2004 | 1 | WHITE ELEC. | | Y | WMS512K8-70DE | 629 |
| 5962-9561304HTC | H | 05/28/2004 | 1 | WHITE ELEC. | | Y | WMS512K8-70DE | 629 |
| 5962-9561304HYA | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4009CW-70/H | 629 |
| 5962-9561304HYA | H | 05/28/2004 | 1 | WHITE ELEC. | | Y | WMS512K8-70C | 629 |
| 5962-9561304HYC | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4009CW-70/H | 629 |
| 5962-9561304HYC | H | 05/28/2004 | 1 | WHITE ELEC. | | Y | WMS512K8-70C | 629 |
| 5962-9561305H9A | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008F-55/H | 629 |
| 5962-9561305H9C | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008F-55/H | 629 |
| 5962-9561305HMA | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008EC-55/H | 629 |
| 5962-9561305HMC | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008EC-55/H | 629 |
| 5962-9561305HNA | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C512K8EC-55/H | 629 |
| 5962-9561305HNC | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C512K8EC-55/H | 629 |
| 5962-9561305HTA | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008ECJ-55/H | 629 |
| 5962-9561305HTA | H | 05/28/2004 | 1 | WHITE ELEC. | | Y | WMS512K8-55DE | 629 |
| 5962-9561305HTC | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008ECJ-55/H | 629 |
| 5962-9561305HTC | H | 05/28/2004 | 1 | WHITE ELEC. | | Y | WMS512K8-55DE | 629 |
| 5962-9561305HUA | H | 05/28/2004 | 1 | AEROFLEX | | Y | ACT-S512K8N-055F3Q | 629 |
| 5962-9561305HUA | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C512K8F-55/H | 629 |
| 5962-9561305HUA | H | 05/28/2004 | 1 | WHITE ELEC. | | Y | WMS512K8-55FT | 629 |
| 5962-9561305HUC | H | 05/28/2004 | 1 | AEROFLEX | | Y | ACT-S512K8N-055F3Q | 629 |
| 5962-9561305HUC | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C512K8F-55/H | 629 |
| 5962-9561305HUC | H | 05/28/2004 | 1 | WHITE ELEC. | | Y | WMS512K8-55FT | 629 |
| 5962-9561305HXC | H | 05/28/2004 | 1 | WHITE ELEC. | | Y | WMS512K8-55F | 629 |
| 5962-9561305HYA | H | 05/28/2004 | 1 | AEROFLEX | | Y | ACT-S512K8N-055P4Q | 629 |
| 5962-9561305HYA | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008CW-55/H | 629 |
| 5962-9561305HYA | H | 05/28/2004 | 1 | WHITE ELEC. | | Y | WMS512K8-55C | 629 |
| 5962-9561305HYC | H | 05/28/2004 | 1 | AEROFLEX | | Y | ACT-S512K8N-055P4Q | 629 |
| 5962-9561305HYC | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008CW-55/H | 629 |
| 5962-9561305HYC | H | 05/28/2004 | 1 | WHITE ELEC. | | Y | WMS512K8-55C | 629 |
| 5962-9561305HZA | H | 05/28/2004 | 1 | AEROFLEX | | Y | ACT-S512K8N-055F4Q | 629 |
| 5962-9561305HZA | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C512K8ECJ-55/H | 629 |
| 5962-9561305HZA | H | 05/28/2004 | 1 | WHITE ELEC. | | Y | WMS512K8-55DJ | 629 |
| 5962-9561305HZC | H | 05/28/2004 | 1 | AEROFLEX | | Y | ACT-S512K8N-055F4Q | 629 |
| 5962-9561305HZC | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C512K8ECJ-55/H | 629 |
| 5962-9561305HZC | H | 05/28/2004 | 1 | WHITE ELEC. | | Y | WMS512K8-55DJ | 629 |
| 5962-9561306H9A | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008F-45/H | 629 |
| 5962-9561306H9C | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008F-45/H | 629 |
| 5962-9561306HMA | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008EC-45/H | 629 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9561306HMC | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008EC-45/H | 629 |
| 5962-9561306HNA | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C512K8EC-45/H | 629 |
| 5962-9561306HNC | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C512K8EC-45/H | 629 |
| 5962-9561306HTA | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008ECJ-45/H | 629 |
| 5962-9561306HTA | H | 05/28/2004 | 1 | WHITE ELEC. | | Y | WMS512K8-45DE | 629 |
| 5962-9561306HTC | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008ECJ-45/H | 629 |
| 5962-9561306HTC | H | 05/28/2004 | 1 | WHITE ELEC. | | Y | WMS512K8-45DE | 629 |
| 5962-9561306HUA | H | 05/28/2004 | 1 | AEROFLEX | | Y | ACT-S512K8N-045F3Q | 629 |
| 5962-9561306HUA | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C512K8F-45/H | 629 |
| 5962-9561306HUA | H | 05/28/2004 | 1 | WHITE ELEC. | | Y | WMS512K8-45FT | 629 |
| 5962-9561306HUC | H | 05/28/2004 | 1 | AEROFLEX | | Y | ACT-S512K8N-045F3Q | 629 |
| 5962-9561306HUC | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C512K8F-45/H | 629 |
| 5962-9561306HUC | H | 05/28/2004 | 1 | WHITE ELEC. | | Y | WMS512K8-45FT | 629 |
| 5962-9561306HXC | H | 05/28/2004 | 1 | WHITE ELEC. | | Y | WMS512K8-45F | 629 |
| 5962-9561306HYA | H | 05/28/2004 | 1 | AEROFLEX | | Y | ACT-S512K8N-045P4Q | 629 |
| 5962-9561306HYA | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008CW-45/H | 629 |
| 5962-9561306HYA | H | 05/28/2004 | 1 | WHITE ELEC. | | Y | WMS512K8-45C | 629 |
| 5962-9561306HYC | H | 05/28/2004 | 1 | AEROFLEX | | Y | ACT-S512K8N-045P4Q | 629 |
| 5962-9561306HYC | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008CW-45/H | 629 |
| 5962-9561306HYC | H | 05/28/2004 | 1 | WHITE ELEC. | | Y | WMS512K8-45C | 629 |
| 5962-9561306HZA | H | 05/28/2004 | 1 | AEROFLEX | | Y | ACT-S512K8N-045F4Q | 629 |
| 5962-9561306HZA | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C512K8ECJ-45/H | 629 |
| 5962-9561306HZA | H | 05/28/2004 | 1 | WHITE ELEC. | | Y | WMS512K8-45DJ | 629 |
| 5962-9561306HZC | H | 05/28/2004 | 1 | AEROFLEX | | Y | ACT-S512K8N-045F4Q | 629 |
| 5962-9561306HZC | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C512K8ECJ-45/H | 629 |
| 5962-9561306HZC | H | 05/28/2004 | 1 | WHITE ELEC. | | Y | WMS512K8-45DJ | 629 |
| 5962-9561307H9A | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008F-35/H | 629 |
| 5962-9561307H9C | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008F-35/H | 629 |
| 5962-9561307HMA | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008EC-35/H | 629 |
| 5962-9561307HMC | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008EC-35/H | 629 |
| 5962-9561307HNA | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C512K8EC-35/H | 629 |
| 5962-9561307HNC | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C512K8EC-35/H | 629 |
| 5962-9561307HTA | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008ECJ-35/H | 629 |
| 5962-9561307HTA | H | 05/28/2004 | 1 | WHITE ELEC. | | Y | WMS512K8-35DE | 629 |
| 5962-9561307HTC | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008ECJ-35/H | 629 |
| 5962-9561307HTC | H | 05/28/2004 | 1 | WHITE ELEC. | | Y | WMS512K8-35DE | 629 |
| 5962-9561307HUA | H | 05/28/2004 | 1 | AEROFLEX | | Y | ACT-S512K8N-035F3Q | 629 |
| 5962-9561307HUA | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C512K8F-35/H | 629 |
| 5962-9561307HUA | H | 05/28/2004 | 1 | WHITE ELEC. | | Y | WMS512K8-35FT | 629 |
| 5962-9561307HUC | H | 05/28/2004 | 1 | AEROFLEX | | Y | ACT-S512K8N-035F3Q | 629 |
| 5962-9561307HUC | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C512K8F-35/H | 629 |
| 5962-9561307HUC | H | 05/28/2004 | 1 | WHITE ELEC. | | Y | WMS512K8-35FT | 629 |
| 5962-9561307HXC | H | 05/28/2004 | 1 | WHITE ELEC. | | Y | WMS512K8-35F | 629 |
| 5962-9561307HYA | H | 05/28/2004 | 1 | AEROFLEX | | Y | ACT-S512K8N-035P4Q | 629 |
| 5962-9561307HYA | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008CW-35/H | 629 |
| 5962-9561307HYA | H | 05/28/2004 | 1 | WHITE ELEC. | | Y | WMS512K8-35C | 629 |
| 5962-9561307HYC | H | 05/28/2004 | 1 | AEROFLEX | | Y | ACT-S512K8N-035P4Q | 629 |
| 5962-9561307HYC | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008CW-35/H | 629 |
| 5962-9561307HYC | H | 05/28/2004 | 1 | WHITE ELEC. | | Y | WMS512K8-35C | 629 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9561307HZA | H | 05/28/2004 | 1 | AEROFLEX | | Y | ACT-S512K8N-035F4Q | 629 |
| 5962-9561307HZA | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C512K8ECJ-35/H | 629 |
| 5962-9561307HZA | H | 05/28/2004 | 1 | WHITE ELEC. | | Y | WMS512K8-35DJ | 629 |
| 5962-9561307HZC | H | 05/28/2004 | 1 | AEROFLEX | | Y | ACT-S512K8N-035F4Q | 629 |
| 5962-9561307HZC | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C512K8ECJ-35/H | 629 |
| 5962-9561307HZC | H | 05/28/2004 | 1 | WHITE ELEC. | | Y | WMS512K8-35DJ | 629 |
| 5962-9561308H9A | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008F-25/H | 629 |
| 5962-9561308H9C | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008F-25/H | 629 |
| 5962-9561308HMA | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008EC-25/H | 629 |
| 5962-9561308HMC | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008EC-25/H | 629 |
| 5962-9561308HNA | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C512K8EC-25/H | 629 |
| 5962-9561308HNC | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C512K8EC-25/H | 629 |
| 5962-9561308HTA | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008ECJ-25/H | 629 |
| 5962-9561308HTA | H | 05/28/2004 | 1 | WHITE ELEC. | | Y | WMS512K8-25DE | 629 |
| 5962-9561308HTC | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008ECJ-25/H | 629 |
| 5962-9561308HTC | H | 05/28/2004 | 1 | WHITE ELEC. | | Y | WMS512K8-25DE | 629 |
| 5962-9561308HUA | H | 05/28/2004 | 1 | AEROFLEX | | Y | ACT-S512K8N-025F3Q | 629 |
| 5962-9561308HUA | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C512K8F-25/H | 629 |
| 5962-9561308HUA | H | 05/28/2004 | 1 | WHITE ELEC. | | Y | WMS512K8-25FT | 629 |
| 5962-9561308HUC | H | 05/28/2004 | 1 | AEROFLEX | | Y | ACT-S512K8N-025F3Q | 629 |
| 5962-9561308HUC | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C512K8F-25/H | 629 |
| 5962-9561308HUC | H | 05/28/2004 | 1 | WHITE ELEC. | | Y | WMS512K8-25FT | 629 |
| 5962-9561308HXC | H | 05/28/2004 | 1 | WHITE ELEC. | | Y | WMS512K8-25F | 629 |
| 5962-9561308HYA | H | 05/28/2004 | 1 | AEROFLEX | | Y | ACT-S512K8N-025P4Q | 629 |
| 5962-9561308HYA | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008CW-25/H | 629 |
| 5962-9561308HYA | H | 05/28/2004 | 1 | WHITE ELEC. | | Y | WMS512K8-25C | 629 |
| 5962-9561308HYC | H | 05/28/2004 | 1 | AEROFLEX | | Y | ACT-S512K8N-025P4Q | 629 |
| 5962-9561308HYC | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008CW-25/H | 629 |
| 5962-9561308HYC | H | 05/28/2004 | 1 | WHITE ELEC. | | Y | WMS512K8-25C | 629 |
| 5962-9561308HZA | H | 05/28/2004 | 1 | AEROFLEX | | Y | ACT-S512K8N-025F4Q | 629 |
| 5962-9561308HZA | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C512K8ECJ-25/H | 629 |
| 5962-9561308HZA | H | 05/28/2004 | 1 | WHITE ELEC. | | Y | WMS512K8-25DJ | 629 |
| 5962-9561308HZC | H | 05/28/2004 | 1 | AEROFLEX | | Y | ACT-S512K8N-025F4Q | 629 |
| 5962-9561308HZC | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C512K8ECJ-25/H | 629 |
| 5962-9561308HZC | H | 05/28/2004 | 1 | WHITE ELEC. | | Y | WMS512K8-25DJ | 629 |
| 5962-9561309H9A | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008F-20/H | 629 |
| 5962-9561309H9C | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008F-20/H | 629 |
| 5962-9561309HMA | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008EC-20/H | 629 |
| 5962-9561309HMC | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008EC-20/H | 629 |
| 5962-9561309HNA | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C512K8EC-20/H | 629 |
| 5962-9561309HNC | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C512K8EC-20/H | 629 |
| 5962-9561309HTA | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008ECJ-20/H | 629 |
| 5962-9561309HTA | H | 05/28/2004 | 1 | WHITE ELEC. | | Y | WMS512K8-20DE | 629 |
| 5962-9561309HTC | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008ECJ-20/H | 629 |
| 5962-9561309HTC | H | 05/28/2004 | 1 | WHITE ELEC. | | Y | WMS512K8-20DE | 629 |
| 5962-9561309HUA | H | 05/28/2004 | 1 | AEROFLEX | | Y | ACT-S512K8N-020F3Q | 629 |
| 5962-9561309HUA | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C512K8F-20/H | 629 |
| 5962-9561309HUA | H | 05/28/2004 | 1 | WHITE ELEC. | | Y | WMS512K8-20FT | 629 |
| 5962-9561309HUC | H | 05/28/2004 | 1 | AEROFLEX | | Y | ACT-S512K8N-020F3Q | 629 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9561309HUC | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C512K8F-20/H | 629 |
| 5962-9561309HUC | H | 05/28/2004 | 1 | WHITE ELEC. | | Y | WMS512K8-20FT | 629 |
| 5962-9561309HXC | H | 05/28/2004 | 1 | WHITE ELEC. | | Y | WMS512K8-20F | 629 |
| 5962-9561309HYA | H | 05/28/2004 | 1 | AEROFLEX | | Y | ACT-S512K8N-020P4Q | 629 |
| 5962-9561309HYA | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008CW-20/H | 629 |
| 5962-9561309HYA | H | 05/28/2004 | 1 | WHITE ELEC. | | Y | WMS512K8-20C | 629 |
| 5962-9561309HYC | H | 05/28/2004 | 1 | AEROFLEX | | Y | ACT-S512K8N-020P4Q | 629 |
| 5962-9561309HYC | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008CW-20/H | 629 |
| 5962-9561309HYC | H | 05/28/2004 | 1 | WHITE ELEC. | | Y | WMS512K8-20C | 629 |
| 5962-9561309HZA | H | 05/28/2004 | 1 | AEROFLEX | | Y | ACT-S512K8N-020F4Q | 629 |
| 5962-9561309HZA | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C512K8ECJ-20/H | 629 |
| 5962-9561309HZA | H | 05/28/2004 | 1 | WHITE ELEC. | | Y | WMS512K8-20DJ | 629 |
| 5962-9561309HZC | H | 05/28/2004 | 1 | AEROFLEX | | Y | ACT-S512K8N-020F4Q | 629 |
| 5962-9561309HZC | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C512K8ECJ-20/H | 629 |
| 5962-9561309HZC | H | 05/28/2004 | 1 | WHITE ELEC. | | Y | WMS512K8-20DJ | 629 |
| 5962-9561310H9A | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008F-17/H | 629 |
| 5962-9561310H9C | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008F-17/H | 629 |
| 5962-9561310HMA | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008EC-17/H | 629 |
| 5962-9561310HMC | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008EC-17/H | 629 |
| 5962-9561310HNA | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C512K8EC-17/H | 629 |
| 5962-9561310HNC | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C512K8EC-17/H | 629 |
| 5962-9561310HTA | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008ECJ-17/H | 629 |
| 5962-9561310HTA | H | 05/28/2004 | 1 | WHITE ELEC. | | Y | WMS512K8-17DE | 629 |
| 5962-9561310HTC | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008ECJ-17/H | 629 |
| 5962-9561310HTC | H | 05/28/2004 | 1 | WHITE ELEC. | | Y | WMS512K8-17DE | 629 |
| 5962-9561310HUA | H | 05/28/2004 | 1 | AEROFLEX | | Y | ACT-S512K8N-017F3Q | 629 |
| 5962-9561310HUA | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C512K8F-17/H | 629 |
| 5962-9561310HUA | H | 05/28/2004 | 1 | WHITE ELEC. | | Y | WMS512K8-17FT | 629 |
| 5962-9561310HUC | H | 05/28/2004 | 1 | AEROFLEX | | Y | ACT-S512K8N-017F3Q | 629 |
| 5962-9561310HUC | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C512K8F-17/H | 629 |
| 5962-9561310HUC | H | 05/28/2004 | 1 | WHITE ELEC. | | Y | WMS512K8-17FT | 629 |
| 5962-9561310HXC | H | 05/28/2004 | 1 | WHITE ELEC. | | Y | WMS512K8-17F | 629 |
| 5962-9561310HYA | H | 05/28/2004 | 1 | AEROFLEX | | Y | ACT-S512K8N-017P4Q | 629 |
| 5962-9561310HYA | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008CW-17/H | 629 |
| 5962-9561310HYA | H | 05/28/2004 | 1 | WHITE ELEC. | | Y | WMS512K8-17C | 629 |
| 5962-9561310HYC | H | 05/28/2004 | 1 | AEROFLEX | | Y | ACT-S512K8N-017P4Q | 629 |
| 5962-9561310HYC | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008CW-17/H | 629 |
| 5962-9561310HYC | H | 05/28/2004 | 1 | WHITE ELEC. | | Y | WMS512K8-17C | 629 |
| 5962-9561310HZA | H | 05/28/2004 | 1 | AEROFLEX | | Y | ACT-S512K8N-017F4Q | 629 |
| 5962-9561310HZA | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C512K8ECJ-17/H | 629 |
| 5962-9561310HZA | H | 05/28/2004 | 1 | WHITE ELEC. | | Y | WMS512K8-17DJ | 629 |
| 5962-9561310HZC | H | 05/28/2004 | 1 | AEROFLEX | | Y | ACT-S512K8N-017F4Q | 629 |
| 5962-9561310HZC | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C512K8ECJ-17/H | 629 |
| 5962-9561310HZC | H | 05/28/2004 | 1 | WHITE ELEC. | | Y | WMS512K8-17DJ | 629 |
| 5962-9561311H9A | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008F-45/H | 629 |
| 5962-9561311H9C | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008F-45/H | 629 |
| 5962-9561311HMA | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008EC-45/H | 629 |
| 5962-9561311HMC | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008EC-45/H | 629 |
| 5962-9561311HNA | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C512K8EC-45/H | 629 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9561311HNC | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C512K8EC-45/H | 629 |
| 5962-9561311HTA | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008ECJ-45/H | 629 |
| 5962-9561311HTA | H | 05/28/2004 | 1 | WHITE ELEC. | | Y | WMS512K8M-45DE | 629 |
| 5962-9561311HTC | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008ECJ-45/H | 629 |
| 5962-9561311HTC | H | 05/28/2004 | 1 | WHITE ELEC. | | Y | WMS512K8M-45DE | 629 |
| 5962-9561311HUA | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C512K8F-45/H | 629 |
| 5962-9561311HUC | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C512K8F-45/H | 629 |
| 5962-9561311HYA | H | 05/28/2004 | 1 | AEROFLEX | | Y | ACT-S512K8M-045P4Q | 629 |
| 5962-9561311HYA | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008CW-45/H | 629 |
| 5962-9561311HYA | H | 05/28/2004 | 1 | WHITE ELEC. | | Y | WMS512K8M-45C | 629 |
| 5962-9561311HYC | H | 05/28/2004 | 1 | AEROFLEX | | Y | ACT-S512K8M-045P4Q | 629 |
| 5962-9561311HYC | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008CW-45/H | 629 |
| 5962-9561311HYC | H | 05/28/2004 | 1 | WHITE ELEC. | | Y | WMS512K8M-45C | 629 |
| 5962-9561311HZA | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C512K8ECJ-45/H | 629 |
| 5962-9561311HZC | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C512K8ECJ-45/H | 629 |
| 5962-9561312H9A | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008F-35/H | 629 |
| 5962-9561312H9C | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008F-35/H | 629 |
| 5962-9561312HMA | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008EC-35/H | 629 |
| 5962-9561312HMC | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008EC-35/H | 629 |
| 5962-9561312HNA | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C512K8EC-35/H | 629 |
| 5962-9561312HNC | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C512K8EC-35/H | 629 |
| 5962-9561312HTA | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008ECJ-35/H | 629 |
| 5962-9561312HTA | H | 05/28/2004 | 1 | WHITE ELEC. | | Y | WMS512K8M-35DE | 629 |
| 5962-9561312HTC | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008ECJ-35/H | 629 |
| 5962-9561312HTC | H | 05/28/2004 | 1 | WHITE ELEC. | | Y | WMS512K8M-35DE | 629 |
| 5962-9561312HUA | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C512K8F-35/H | 629 |
| 5962-9561312HUC | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C512K8F-35/H | 629 |
| 5962-9561312HYA | H | 05/28/2004 | 1 | AEROFLEX | | Y | ACT-S512K8M-035P4Q | 629 |
| 5962-9561312HYA | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008CW-35/H | 629 |
| 5962-9561312HYA | H | 05/28/2004 | 1 | WHITE ELEC. | | Y | WMS512K8M-35C | 629 |
| 5962-9561312HYC | H | 05/28/2004 | 1 | AEROFLEX | | Y | ACT-S512K8M-035P4Q | 629 |
| 5962-9561312HYC | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008CW-35/H | 629 |
| 5962-9561312HYC | H | 05/28/2004 | 1 | WHITE ELEC. | | Y | WMS512K8M-35C | 629 |
| 5962-9561312HZA | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C512K8ECJ-35/H | 629 |
| 5962-9561312HZC | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C512K8ECJ-35/H | 629 |
| 5962-9561313H9A | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008F-25/H | 629 |
| 5962-9561313H9C | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008F-25/H | 629 |
| 5962-9561313HMA | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008EC-25/H | 629 |
| 5962-9561313HMC | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008EC-25/H | 629 |
| 5962-9561313HNA | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C512K8EC-25/H | 629 |
| 5962-9561313HNC | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C512K8EC-25/H | 629 |
| 5962-9561313HTA | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008ECJ-25/H | 629 |
| 5962-9561313HTA | H | 05/28/2004 | 1 | WHITE ELEC. | | Y | WMS512K8M-25DE | 629 |
| 5962-9561313HTC | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008ECJ-25/H | 629 |
| 5962-9561313HTC | H | 05/28/2004 | 1 | WHITE ELEC. | | Y | WMS512K8M-25DE | 629 |
| 5962-9561313HUA | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C512K8F-25/H | 629 |
| 5962-9561313HUC | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C512K8F-25/H | 629 |
| 5962-9561313HYA | H | 05/28/2004 | 1 | AEROFLEX | | Y | ACT-S512K8M-025P4Q | 629 |
| 5962-9561313HYA | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008CW-25/H | 629 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9561313HYA | H | 05/28/2004 | 1 | WHITE ELEC. | | Y | WMS512K8M-25C | 629 |
| 5962-9561313HYC | H | 05/28/2004 | 1 | AEROFLEX | | Y | ACT-S512K8M-025P4Q | 629 |
| 5962-9561313HYC | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008CW-25/H | 629 |
| 5962-9561313HYC | H | 05/28/2004 | 1 | WHITE ELEC. | | Y | WMS512K8M-25C | 629 |
| 5962-9561313HZA | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C512K8ECJ-25/H | 629 |
| 5962-9561313HZC | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C512K8ECJ-25/H | 629 |
| 5962-9561314HTA | H | 05/28/2004 | 1 | WHITE ELEC. | | Y | WMS512K8M-15DE | 629 |
| 5962-9561314HTC | H | 05/28/2004 | 1 | WHITE ELEC. | | Y | WMS512K8M-15DE | 629 |
| 5962-9561314HYA | H | 05/28/2004 | 1 | WHITE ELEC. | | Y | WMS512K8M-15C | 629 |
| 5962-9561314HYC | H | 05/28/2004 | 1 | WHITE ELEC. | | Y | WMS512K8M-15C | 629 |
| 5962-9561315HTA | H | 05/28/2004 | 1 | WHITE ELEC. | | Y | WMS512K8L-120DE | 629 |
| 5962-9561315HTC | H | 05/28/2004 | 1 | WHITE ELEC. | | Y | WMS512K8L-120DE | 629 |
| 5962-9561315HYA | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4009CW-120L/H | 629 |
| 5962-9561315HYA | H | 05/28/2004 | 1 | WHITE ELEC. | | Y | WMS512K8L-120C | 629 |
| 5962-9561315HYC | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4009CW-120L/H | 629 |
| 5962-9561315HYC | H | 05/28/2004 | 1 | WHITE ELEC. | | Y | WMS512K8L-120C | 629 |
| 5962-9561316HTA | H | 05/28/2004 | 1 | WHITE ELEC. | | Y | WMS512K8L-100DE | 629 |
| 5962-9561316HTC | H | 05/28/2004 | 1 | WHITE ELEC. | | Y | WMS512K8L-100DE | 629 |
| 5962-9561316HYA | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4009CW-100L/H | 629 |
| 5962-9561316HYA | H | 05/28/2004 | 1 | WHITE ELEC. | | Y | WMS512K8L-100C | 629 |
| 5962-9561316HYC | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4009CW-100L/H | 629 |
| 5962-9561316HYC | H | 05/28/2004 | 1 | WHITE ELEC. | | Y | WMS512K8L-100C | 629 |
| 5962-9561317HTA | H | 05/28/2004 | 1 | WHITE ELEC. | | Y | WMS512K8L-85DE | 629 |
| 5962-9561317HTC | H | 05/28/2004 | 1 | WHITE ELEC. | | Y | WMS512K8L-85DE | 629 |
| 5962-9561317HYA | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4009CW-85L/H | 629 |
| 5962-9561317HYA | H | 05/28/2004 | 1 | WHITE ELEC. | | Y | WMS512K8L-85C | 629 |
| 5962-9561317HYC | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4009CW-85L/H | 629 |
| 5962-9561317HYC | H | 05/28/2004 | 1 | WHITE ELEC. | | Y | WMS512K8L-85C | 629 |
| 5962-9561318HTA | H | 05/28/2004 | 1 | WHITE ELEC. | | Y | WMS512K8L-70DE | 629 |
| 5962-9561318HTC | H | 05/28/2004 | 1 | WHITE ELEC. | | Y | WMS512K8L-70DE | 629 |
| 5962-9561318HYA | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4009CW-70L/H | 629 |
| 5962-9561318HYA | H | 05/28/2004 | 1 | WHITE ELEC. | | Y | WMS512K8L-70C | 629 |
| 5962-9561318HYC | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4009CW-70L/H | 629 |
| 5962-9561318HYC | H | 05/28/2004 | 1 | WHITE ELEC. | | Y | WMS512K8L-70C | 629 |
| 5962-9561319H9A | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008F-55L/H | 629 |
| 5962-9561319H9C | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008F-55L/H | 629 |
| 5962-9561319HMA | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008EC-55L/H | 629 |
| 5962-9561319HMC | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008EC-55L/H | 629 |
| 5962-9561319HNA | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C512K8EC-55L/H | 629 |
| 5962-9561319HNC | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C512K8EC-55L/H | 629 |
| 5962-9561319HTA | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008ECJ-55L/H | 629 |
| 5962-9561319HTA | H | 05/28/2004 | 1 | WHITE ELEC. | | Y | WMS512K8L-55DE | 629 |
| 5962-9561319HTC | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008ECJ-55L/H | 629 |
| 5962-9561319HTC | H | 05/28/2004 | 1 | WHITE ELEC. | | Y | WMS512K8L-55DE | 629 |
| 5962-9561319HUA | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C512K8F-55L/H | 629 |
| 5962-9561319HUA | H | 05/28/2004 | 1 | WHITE ELEC. | | Y | WMS512K8L-55FT | 629 |
| 5962-9561319HUC | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C512K8F-55L/H | 629 |
| 5962-9561319HUC | H | 05/28/2004 | 1 | WHITE ELEC. | | Y | WMS512K8L-55FT | 629 |
| 5962-9561319HXC | H | 05/28/2004 | 1 | WHITE ELEC. | | Y | WMS512K8L-55F | 629 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9561319HYA | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008CW-55L/H | 629 |
| 5962-9561319HYA | H | 05/28/2004 | 1 | WHITE ELEC. | | Y | WMS512K8L-55C | 629 |
| 5962-9561319HYC | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008CW-55L/H | 629 |
| 5962-9561319HYC | H | 05/28/2004 | 1 | WHITE ELEC. | | Y | WMS512K8L-55C | 629 |
| 5962-9561319HZA | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C512K8ECJ-55L/H | 629 |
| 5962-9561319HZA | H | 05/28/2004 | 1 | WHITE ELEC. | | Y | WMS512K8L-55DJ | 629 |
| 5962-9561319HZC | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C512K8ECJ-55L/H | 629 |
| 5962-9561319HZC | H | 05/28/2004 | 1 | WHITE ELEC. | | Y | WMS512K8L-55DJ | 629 |
| 5962-9561320H9A | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008F-45L/H | 629 |
| 5962-9561320H9C | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008F-45L/H | 629 |
| 5962-9561320HMA | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008EC-45L/H | 629 |
| 5962-9561320HMC | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008EC-45L/H | 629 |
| 5962-9561320HNA | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C512K8EC-45L/H | 629 |
| 5962-9561320HNC | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C512K8EC-45L/H | 629 |
| 5962-9561320HTA | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008ECJ-45L/H | 629 |
| 5962-9561320HTA | H | 05/28/2004 | 1 | WHITE ELEC. | | Y | WMS512K8L-45DE | 629 |
| 5962-9561320HTC | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008ECJ-45L/H | 629 |
| 5962-9561320HTC | H | 05/28/2004 | 1 | WHITE ELEC. | | Y | WMS512K8L-45DE | 629 |
| 5962-9561320HUA | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C512K8F-45L/H | 629 |
| 5962-9561320HUA | H | 05/28/2004 | 1 | WHITE ELEC. | | Y | WMS512K8L-45FT | 629 |
| 5962-9561320HUC | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C512K8F-45L/H | 629 |
| 5962-9561320HUC | H | 05/28/2004 | 1 | WHITE ELEC. | | Y | WMS512K8L-45FT | 629 |
| 5962-9561320HXC | H | 05/28/2004 | 1 | WHITE ELEC. | | Y | WMS512K8L-45F | 629 |
| 5962-9561320HYA | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008CW-45L/H | 629 |
| 5962-9561320HYA | H | 05/28/2004 | 1 | WHITE ELEC. | | Y | WMS512K8L-45C | 629 |
| 5962-9561320HYC | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008CW-45L/H | 629 |
| 5962-9561320HYC | H | 05/28/2004 | 1 | WHITE ELEC. | | Y | WMS512K8L-45C | 629 |
| 5962-9561320HZA | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C512K8ECJ-45L/H | 629 |
| 5962-9561320HZA | H | 05/28/2004 | 1 | WHITE ELEC. | | Y | WMS512K8L-45DJ | 629 |
| 5962-9561320HZC | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C512K8ECJ-45L/H | 629 |
| 5962-9561320HZC | H | 05/28/2004 | 1 | WHITE ELEC. | | Y | WMS512K8L-45DJ | 629 |
| 5962-9561321H9A | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008F-35L/H | 629 |
| 5962-9561321H9C | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008F-35L/H | 629 |
| 5962-9561321HMA | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008EC-35L/H | 629 |
| 5962-9561321HMC | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008EC-35L/H | 629 |
| 5962-9561321HNA | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C512K8EC-35L/H | 629 |
| 5962-9561321HNC | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C512K8EC-35L/H | 629 |
| 5962-9561321HTA | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008ECJ-35L/H | 629 |
| 5962-9561321HTA | H | 05/28/2004 | 1 | WHITE ELEC. | | Y | WMS512K8L-35DE | 629 |
| 5962-9561321HTC | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008ECJ-35L/H | 629 |
| 5962-9561321HTC | H | 05/28/2004 | 1 | WHITE ELEC. | | Y | WMS512K8L-35DE | 629 |
| 5962-9561321HUA | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C512K8F-35L/H | 629 |
| 5962-9561321HUA | H | 05/28/2004 | 1 | WHITE ELEC. | | Y | WMS512K8L-35FT | 629 |
| 5962-9561321HUC | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C512K8F-35L/H | 629 |
| 5962-9561321HUC | H | 05/28/2004 | 1 | WHITE ELEC. | | Y | WMS512K8L-35FT | 629 |
| 5962-9561321HXC | H | 05/28/2004 | 1 | WHITE ELEC. | | Y | WMS512K8L-35F | 629 |
| 5962-9561321HYA | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008CW-35L/H | 629 |
| 5962-9561321HYA | H | 05/28/2004 | 1 | WHITE ELEC. | | Y | WMS512K8L-35C | 629 |
| 5962-9561321HYC | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008CW-35L/H | 629 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9561321HYC | H | 05/28/2004 | 1 | WHITE ELEC. | | Y | WMS512K8L-35C | 629 |
| 5962-9561321HZA | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C512K8ECJ-35L/H | 629 |
| 5962-9561321HZA | H | 05/28/2004 | 1 | WHITE ELEC. | | Y | WMS512K8L-35DJ | 629 |
| 5962-9561321HZC | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C512K8ECJ-35L/H | 629 |
| 5962-9561321HZC | H | 05/28/2004 | 1 | WHITE ELEC. | | Y | WMS512K8L-35DJ | 629 |
| 5962-9561322H9A | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008F-25L/H | 629 |
| 5962-9561322H9C | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008F-25L/H | 629 |
| 5962-9561322HMA | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008EC-25L/H | 629 |
| 5962-9561322HMC | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008EC-25L/H | 629 |
| 5962-9561322HNA | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C512K8EC-25L/H | 629 |
| 5962-9561322HNC | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C512K8EC-25L/H | 629 |
| 5962-9561322HTA | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008ECJ-25L/H | 629 |
| 5962-9561322HTA | H | 05/28/2004 | 1 | WHITE ELEC. | | Y | WMS512K8L-25DE | 629 |
| 5962-9561322HTC | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008ECJ-25L/H | 629 |
| 5962-9561322HTC | H | 05/28/2004 | 1 | WHITE ELEC. | | Y | WMS512K8L-25DE | 629 |
| 5962-9561322HUA | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C512K8F-25L/H | 629 |
| 5962-9561322HUA | H | 05/28/2004 | 1 | WHITE ELEC. | | Y | WMS512K8L-25FT | 629 |
| 5962-9561322HUC | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C512K8F-25L/H | 629 |
| 5962-9561322HUC | H | 05/28/2004 | 1 | WHITE ELEC. | | Y | WMS512K8L-25FT | 629 |
| 5962-9561322HXC | H | 05/28/2004 | 1 | WHITE ELEC. | | Y | WMS512K8L-25F | 629 |
| 5962-9561322HYA | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008CW-25L/H | 629 |
| 5962-9561322HYA | H | 05/28/2004 | 1 | WHITE ELEC. | | Y | WMS512K8L-25C | 629 |
| 5962-9561322HYC | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008CW-25L/H | 629 |
| 5962-9561322HYC | H | 05/28/2004 | 1 | WHITE ELEC. | | Y | WMS512K8L-25C | 629 |
| 5962-9561322HZA | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C512K8ECJ-25L/H | 629 |
| 5962-9561322HZA | H | 05/28/2004 | 1 | WHITE ELEC. | | Y | WMS512K8L-25DJ | 629 |
| 5962-9561322HZC | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C512K8ECJ-25L/H | 629 |
| 5962-9561322HZC | H | 05/28/2004 | 1 | WHITE ELEC. | | Y | WMS512K8L-25DJ | 629 |
| 5962-9561323H9A | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008F-20L/H | 629 |
| 5962-9561323H9C | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008F-20L/H | 629 |
| 5962-9561323HMA | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008EC-20L/H | 629 |
| 5962-9561323HMC | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008EC-20L/H | 629 |
| 5962-9561323HNA | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C512K8EC-20L/H | 629 |
| 5962-9561323HNC | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C512K8EC-20L/H | 629 |
| 5962-9561323HTA | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008ECJ-20L/H | 629 |
| 5962-9561323HTA | H | 05/28/2004 | 1 | WHITE ELEC. | | Y | WMS512K8L-20DE | 629 |
| 5962-9561323HTC | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008ECJ-20L/H | 629 |
| 5962-9561323HTC | H | 05/28/2004 | 1 | WHITE ELEC. | | Y | WMS512K8L-20DE | 629 |
| 5962-9561323HUA | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C512K8F-20L/H | 629 |
| 5962-9561323HUA | H | 05/28/2004 | 1 | WHITE ELEC. | | Y | WMS512K8L-20FT | 629 |
| 5962-9561323HUC | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C512K8F-20L/H | 629 |
| 5962-9561323HUC | H | 05/28/2004 | 1 | WHITE ELEC. | | Y | WMS512K8L-20FT | 629 |
| 5962-9561323HXC | H | 05/28/2004 | 1 | WHITE ELEC. | | Y | WMS512K8L-20F | 629 |
| 5962-9561323HYA | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008CW-20L/H | 629 |
| 5962-9561323HYA | H | 05/28/2004 | 1 | WHITE ELEC. | | Y | WMS512K8L-20C | 629 |
| 5962-9561323HYC | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008CW-20L/H | 629 |
| 5962-9561323HYC | H | 05/28/2004 | 1 | WHITE ELEC. | | Y | WMS512K8L-20C | 629 |
| 5962-9561323HZA | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C512K8ECJ-20L/H | 629 |
| 5962-9561323HZA | H | 05/28/2004 | 1 | WHITE ELEC. | | Y | WMS512K8L-20DJ | 629 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9561323HZC | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C512K8ECJ-20L/H | 629 |
| 5962-9561323HZC | H | 05/28/2004 | 1 | WHITE ELEC. | | Y | WMS512K8L-20DJ | 629 |
| 5962-9561324H9A | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008F-17L/H | 629 |
| 5962-9561324H9C | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008F-17L/H | 629 |
| 5962-9561324HMA | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008EC-17L/H | 629 |
| 5962-9561324HMC | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008EC-17L/H | 629 |
| 5962-9561324HNA | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C512K8EC-17L/H | 629 |
| 5962-9561324HNC | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C512K8EC-17L/H | 629 |
| 5962-9561324HTA | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008ECJ-17L/H | 629 |
| 5962-9561324HTA | H | 05/28/2004 | 1 | WHITE ELEC. | | Y | WMS512K8L-17DE | 629 |
| 5962-9561324HTC | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008ECJ-17L/H | 629 |
| 5962-9561324HTC | H | 05/28/2004 | 1 | WHITE ELEC. | | Y | WMS512K8L-17DE | 629 |
| 5962-9561324HUA | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C512K8F-17L/H | 629 |
| 5962-9561324HUA | H | 05/28/2004 | 1 | WHITE ELEC. | | Y | WMS512K8L-17FT | 629 |
| 5962-9561324HUC | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C512K8F-17L/H | 629 |
| 5962-9561324HUC | H | 05/28/2004 | 1 | WHITE ELEC. | | Y | WMS512K8L-17FT | 629 |
| 5962-9561324HXC | H | 05/28/2004 | 1 | WHITE ELEC. | | Y | WMS512K8L-17F | 629 |
| 5962-9561324HYA | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008CW-17L/H | 629 |
| 5962-9561324HYA | H | 05/28/2004 | 1 | WHITE ELEC. | | Y | WMS512K8L-17C | 629 |
| 5962-9561324HYC | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008CW-17L/H | 629 |
| 5962-9561324HYC | H | 05/28/2004 | 1 | WHITE ELEC. | | Y | WMS512K8L-17C | 629 |
| 5962-9561324HZA | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C512K8ECJ-17L/H | 629 |
| 5962-9561324HZA | H | 05/28/2004 | 1 | WHITE ELEC. | | Y | WMS512K8L-17DJ | 629 |
| 5962-9561324HZC | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C512K8ECJ-17L/H | 629 |
| 5962-9561324HZC | H | 05/28/2004 | 1 | WHITE ELEC. | | Y | WMS512K8L-17DJ | 629 |
| 5962-9561325H9A | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008F-45L/H | 629 |
| 5962-9561325H9C | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008F-45L/H | 629 |
| 5962-9561325HMA | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008EC-45L/H | 629 |
| 5962-9561325HMC | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008EC-45L/H | 629 |
| 5962-9561325HNA | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C512K8EC-45L/H | 629 |
| 5962-9561325HNC | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C512K8EC-45L/H | 629 |
| 5962-9561325HTA | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008ECJ-45L/H | 629 |
| 5962-9561325HTC | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008ECJ-45L/H | 629 |
| 5962-9561325HUA | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C512K8F-45L/H | 629 |
| 5962-9561325HUC | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C512K8F-45L/H | 629 |
| 5962-9561325HYA | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008CW-45L/H | 629 |
| 5962-9561325HYC | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008CW-45L/H | 629 |
| 5962-9561325HZA | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C512K8ECJ-45L/H | 629 |
| 5962-9561325HZC | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C512K8ECJ-45L/H | 629 |
| 5962-9561326H9A | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008F-35L/H | 629 |
| 5962-9561326H9C | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008F-35L/H | 629 |
| 5962-9561326HMA | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008EC-35L/H | 629 |
| 5962-9561326HMC | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008EC-35L/H | 629 |
| 5962-9561326HNA | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C512K8EC-35L/H | 629 |
| 5962-9561326HNC | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C512K8EC-35L/H | 629 |
| 5962-9561326HTA | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008ECJ-35L/H | 629 |
| 5962-9561326HTC | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008ECJ-35L/H | 629 |
| 5962-9561326HUA | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C512K8F-35L/H | 629 |
| 5962-9561326HUC | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C512K8F-35L/H | 629 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9561326HYA | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008CW-35L/H | 629 |
| 5962-9561326HYC | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008CW-35L/H | 629 |
| 5962-9561326HZA | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C512K8ECJ-35L/H | 629 |
| 5962-9561326HZC | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C512K8ECJ-35L/H | 629 |
| 5962-9561327H9A | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008F-25L/H | 629 |
| 5962-9561327H9C | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008F-25L/H | 629 |
| 5962-9561327HMA | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008EC-25L/H | 629 |
| 5962-9561327HMC | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008EC-25L/H | 629 |
| 5962-9561327HNA | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C512K8EC-25L/H | 629 |
| 5962-9561327HNC | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C512K8EC-25L/H | 629 |
| 5962-9561327HTA | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008ECJ-25L/H | 629 |
| 5962-9561327HTC | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008ECJ-25L/H | 629 |
| 5962-9561327HUA | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C512K8F-25L/H | 629 |
| 5962-9561327HUC | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C512K8F-25L/H | 629 |
| 5962-9561327HYA | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008CW-25L/H | 629 |
| 5962-9561327HYC | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008CW-25L/H | 629 |
| 5962-9561327HZA | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C512K8ECJ-25L/H | 629 |
| 5962-9561327HZC | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C512K8ECJ-25L/H | 629 |
| 5962-9561328H9A | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008F-12L/H | 629 |
| 5962-9561328H9C | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008F-12L/H | 629 |
| 5962-9561328HMA | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008EC-12L/H | 629 |
| 5962-9561328HMC | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008EC-12L/H | 629 |
| 5962-9561328HNA | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C512K8EC-12L/H | 629 |
| 5962-9561328HNC | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C512K8EC-12L/H | 629 |
| 5962-9561328HTA | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008ECJ-12L/H | 629 |
| 5962-9561328HTA | H | 05/28/2004 | 1 | WHITE ELEC. | | Y | WMS512K8L-12DE | 629 |
| 5962-9561328HTC | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008ECJ-12L/H | 629 |
| 5962-9561328HTC | H | 05/28/2004 | 1 | WHITE ELEC. | | Y | WMS512K8L-12DE | 629 |
| 5962-9561328HUA | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C512K8F-12L/H | 629 |
| 5962-9561328HUA | H | 05/28/2004 | 1 | WHITE ELEC. | | Y | WMS512K8L-12FT | 629 |
| 5962-9561328HUC | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C512K8F-12L/H | 629 |
| 5962-9561328HUC | H | 05/28/2004 | 1 | WHITE ELEC. | | Y | WMS512K8L-12FT | 629 |
| 5962-9561328HXC | H | 05/28/2004 | 1 | WHITE ELEC. | | Y | WMS512K8L-12F | 629 |
| 5962-9561328HYA | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008CW-12L/H | 629 |
| 5962-9561328HYA | H | 05/28/2004 | 1 | WHITE ELEC. | | Y | WMS512K8L-12C | 629 |
| 5962-9561328HYC | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008CW-12L/H | 629 |
| 5962-9561328HYC | H | 05/28/2004 | 1 | WHITE ELEC. | | Y | WMS512K8L-12C | 629 |
| 5962-9561328HZA | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C512K8ECJ-12L/H | 629 |
| 5962-9561328HZA | H | 05/28/2004 | 1 | WHITE ELEC. | | Y | WMS512K8L-12DJ | 629 |
| 5962-9561328HZC | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C512K8ECJ-12L/H | 629 |
| 5962-9561328HZC | H | 05/28/2004 | 1 | WHITE ELEC. | | Y | WMS512K8L-12DJ | 629 |
| 5962-9561329H9A | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008F-12/H | 629 |
| 5962-9561329H9C | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008F-12/H | 629 |
| 5962-9561329HMA | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008EC-12/H | 629 |
| 5962-9561329HMC | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008EC-12/H | 629 |
| 5962-9561329HNA | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C512K8EC-12/H | 629 |
| 5962-9561329HNC | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C512K8EC-12/H | 629 |
| 5962-9561329HTA | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008ECJ-12/H | 629 |
| 5962-9561329HTA | H | 05/28/2004 | 1 | WHITE ELEC. | | Y | WMS512K8-12DE | 629 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9561329HTC | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008ECJ-12/H | 629 |
| 5962-9561329HTC | H | 05/28/2004 | 1 | WHITE ELEC. | | Y | WMS512K8-12DE | 629 |
| 5962-9561329HUA | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C512K8F-12/H | 629 |
| 5962-9561329HUA | H | 05/28/2004 | 1 | WHITE ELEC. | | Y | WMS512K8-12FT | 629 |
| 5962-9561329HUC | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C512K8F-12/H | 629 |
| 5962-9561329HUC | H | 05/28/2004 | 1 | WHITE ELEC. | | Y | WMS512K8-12FT | 629 |
| 5962-9561329HXC | H | 05/28/2004 | 1 | WHITE ELEC. | | Y | WMS512K8-12F | 629 |
| 5962-9561329HYA | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008CW-12/H | 629 |
| 5962-9561329HYA | H | 05/28/2004 | 1 | WHITE ELEC. | | Y | WMS512K8-12C | 629 |
| 5962-9561329HYC | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C4008CW-12/H | 629 |
| 5962-9561329HYC | H | 05/28/2004 | 1 | WHITE ELEC. | | Y | WMS512K8-12C | 629 |
| 5962-9561329HZA | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C512K8ECJ-12/H | 629 |
| 5962-9561329HZA | H | 05/28/2004 | 1 | WHITE ELEC. | | Y | WMS512K8-12DJ | 629 |
| 5962-9561329HZC | H | 05/28/2004 | 1 | AUSTIN SEMI. | | Y | AS5C512K8ECJ-12/H | 629 |
| 5962-9561329HZC | H | 05/28/2004 | 1 | WHITE ELEC. | | Y | WMS512K8-12DJ | 629 |
| 5962-9561330HTA | H | 05/28/2004 | 1 | WHITE ELEC. | | Y | WMS512K8U-12DE | 629 |
| 5962-9561330HTC | H | 05/28/2004 | 1 | WHITE ELEC. | | Y | WMS512K8U-12DE | 629 |
| 5962-9561330HUA | H | 05/28/2004 | 1 | WHITE ELEC. | | Y | WMS512K8U-12FT | 629 |
| 5962-9561330HUC | H | 05/28/2004 | 1 | WHITE ELEC. | | Y | WMS512K8U-12FT | 629 |
| 5962-9561330HXC | H | 05/28/2004 | 1 | WHITE ELEC. | | Y | WMS512K8U-12F | 629 |
| 5962-9561330HYA | H | 05/28/2004 | 1 | WHITE ELEC. | | Y | WMS512K8U-12C | 629 |
| 5962-9561330HYC | H | 05/28/2004 | 1 | WHITE ELEC. | | Y | WMS512K8U-12C | 629 |
| 5962-9561330HZA | H | 05/28/2004 | 1 | WHITE ELEC. | | Y | WMS512K8U-12DJ | 629 |
| 5962-9561330HZC | H | 05/28/2004 | 1 | WHITE ELEC. | | Y | WMS512K8U-12DJ | 629 |
| 5962-9561401QXA | | 10/13/1995 | 2 | TI | | Y | SNJ54ABTH18502AHV | 590 |
| 5962-9561501MJA | C | 09/20/2001 | | (NONE) | | | 7890S-10 (GEN) | 433 |
| 5962-9561501MLA | C | 09/20/2001 | 1 | ANALOG (3) | | Y | AD7890SQ-10/QML | 433 |
| 5962-9561601MXA | | 12/15/1995 | | (NONE) | | | SP9320 (GEN) | 591 |
| 5962-9561701MPA | A | 05/18/2001 | 3 | XILINX | | Y | XC17256DDD8B | 662 |
| 5962-9561801QXA | | 05/11/1995 | 1 | NATIONAL | | Y | 54ACTQ16373FMQB | 342 |
| 5962-9561901QXA | B | 04/12/2002 | 3 | NATIONAL | | Y | 54ACTQ16244FMQB | 529 |
| 5962-9561901VXA | B | 04/12/2002 | 3 | NATIONAL | | Y | 54ACTQ16244W-QV | 529 |
| 5962R9561901QXA | B | 04/12/2002 | | (NONE) | | | 54ACTQ16244 (GEN) | 529 |
| 5962R9561901VXA | B | 04/12/2002 | | (NONE) | | | 54ACTQ16244 (GEN) | 529 |
| 5962-9562001QXA | D | 05/08/2003 | 1 | NATIONAL | | Y | 54ACTQ16245FMQB | 590 |
| 5962-9562001VXA | D | 05/08/2003 | 1 | NATIONAL | | Y | 54ACTQ16245W-QV | 590 |
| 5962R9562001QXA | D | 05/08/2003 | | (NONE) | | | 54ACTQ16245 (GEN) | 590 |
| 5962R9562001VXA | D | 05/08/2003 | | (NONE) | | | 54ACTQ16245 (GEN) | 590 |
| 5962R9562101V9A | C | 09/12/2003 | 1 | INTERSIL | | Y | CD4029BHSR | 319 |
| 5962R9562101VEC | C | 09/12/2003 | 1 | INTERSIL | | Y | CD4029BDMSR | 319 |
| 5962R9562101VXC | C | 09/12/2003 | 1 | INTERSIL | | Y | CD4029BKMSR | 319 |
| 5962R9562102V9A | C | 09/12/2003 | 1 | INTERSIL | | Y | CD4029BHNSR | 319 |
| 5962R9562102VEC | C | 09/12/2003 | | (NONE) | | | 4029BN (GEN) | 319 |
| 5962R9562102VXC | C | 09/12/2003 | | (NONE) | | | 4029BN (GEN) | 319 |
| 5962-9562301Q3A | B | 10/15/2001 | 1 | SILICONIX | | Y | DG406AZ/883 | 195 |
| 5962-9562301QXA | B | 10/15/2001 | 1 | SILICONIX | | Y | DG406AP/883 | 195 |
| 5962-9562301QXA | B | 10/15/2001 | 1 | SILICONIX | | Y | DG406AK/883 | 195 |
| 5962-9562302Q3A | B | 10/15/2001 | 1 | SILICONIX | | Y | DG407AZ/883 | 195 |
| 5962-9562302QXA | B | 10/15/2001 | 1 | SILICONIX | | Y | DG407AK/883 | 195 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9562302QXA | B | 10/15/2001 | 1 | SILICONIX | | Y | DG407AP/883 | 195 |
| 5962-9562401HNC | B | 03/29/2004 | 1 | WHITE ELEC. | | Y | WS512K32F-120G4Q | 629 |
| 5962-9562402HNC | B | 03/29/2004 | 1 | WHITE ELEC. | | Y | WS512K32F-100G4Q | 629 |
| 5962-9562403HNC | B | 03/29/2004 | 1 | WHITE ELEC. | | Y | WS512K32F-85G4Q | 629 |
| 5962-9562404HNC | B | 03/29/2004 | 1 | WHITE ELEC. | | Y | WS512K32F-70G4Q | 629 |
| 5962-9562405HNC | B | 03/29/2004 | 1 | WHITE ELEC. | | Y | WS512K32F-55G4Q | 629 |
| 5962-9562406HNC | B | 03/29/2004 | 1 | WHITE ELEC. | | Y | WS512K32F-45G4Q | 629 |
| 5962-9562407HNC | B | 03/29/2004 | 1 | WHITE ELEC. | | Y | WS512K32F-35G4Q | 629 |
| 5962-9562408HNC | B | 03/29/2004 | 1 | WHITE ELEC. | | Y | WS512K32F-25G4Q | 629 |
| 5962-9562409HNC | B | 03/29/2004 | 1 | WHITE ELEC. | | Y | WS512K32F-20G4Q | 629 |
| 5962-9562410HNC | B | 03/29/2004 | 1 | WHITE ELEC. | | Y | WS512K32M-45G4Q | 629 |
| 5962-9562411HNC | B | 03/29/2004 | 1 | WHITE ELEC. | | Y | WS512K32M-35G4Q | 629 |
| 5962-9562412HNC | B | 03/29/2004 | 1 | WHITE ELEC. | | Y | WS512K32M-25G4Q | 629 |
| 5962-9562501NXB | A | 08/23/1996 | | (NONE) | 12/24/1997 | | 28F016SV (GEN) | 669 |
| 5962-9562502NXB | A | 08/23/1996 | | (NONE) | 12/24/1997 | | 28F016SV (GEN) | 669 |
| 5962-9562503NXB | A | 08/23/1996 | | (NONE) | 12/24/1997 | | 28F016SV (GEN) | 669 |
| 5962-9562504NXB | A | 08/23/1996 | | (NONE) | 12/24/1997 | | 28F016SV (GEN) | 669 |
| 5962F9562601QXC | E | 02/12/2004 | 1 | INTERSIL | | Y | HS1-6664RH-8 | 660 |
| 5962F9562601VXC | E | 02/12/2004 | 1 | INTERSIL | | Y | HS1-6664RH-Q | 660 |
| 5962R9562601TXC | E | 02/12/2004 | 1 | INTERSIL | | Y | HS1-6664RH-T | 660 |
| 5962F9562601QYC | E | 02/12/2004 | 1 | INTERSIL | | Y | HS9-6664RH-8 | 660 |
| 5962F9562601VYC | E | 02/12/2004 | 1 | INTERSIL | | Y | HS9-6664RH-Q | 660 |
| 5962R9562601TYC | E | 02/12/2004 | 1 | INTERSIL | | Y | HS9-6664RH-T | 660 |
| 5962-9562701NXD | C | 11/18/1997 | 1 | TI | | Y | ACT7881PN | 670 |
| 5962-9562701QYA | C | 11/18/1997 | | (NONE) | | | 54ACT7881 (GEN) | 670 |
| 5962-9562801QYA | | 01/06/1998 | | (NONE) | | | 54ACT3632 (GEN) | 670 |
| 5962-9562901QCA | A | 09/26/2001 | 1 | SILICONIX | | Y | DG200AAK/883 | 181 |
| 5962-9562901QIA | A | 09/26/2001 | | (NONE) | | | DG200A (GEN) | 181 |
| 5962R9563001QXC | F | 06/25/2004 | | (NONE) | | | 1840 (GEN) | 195 |
| 5962R9563001VXC | F | 06/25/2004 | | (NONE) | | | 1840 (GEN) | 195 |
| 5962R9563001QYC | F | 06/25/2004 | | (NONE) | | | 1840 (GEN) | 195 |
| 5962R9563001VYC | F | 06/25/2004 | | (NONE) | | | 1840 (GEN) | 195 |
| 5962F9563002V9A | F | 06/25/2004 | 1 | INTERSIL | | Y | HS0-1840ARH-Q | 195 |
| 5962F9563002QXC | F | 06/25/2004 | 1 | INTERSIL | | Y | HS1-1840ARH-8 | 195 |
| 5962F9563002VXC | F | 06/25/2004 | 1 | INTERSIL | | Y | HS1-1840ARH-Q | 195 |
| 5962R9563002TXC | F | 06/25/2004 | 1 | INTERSIL | | Y | HS1-1840ARH-T | 195 |
| 5962F9563002QYC | F | 06/25/2004 | 1 | INTERSIL | | Y | HS9-1840ARH-8 | 195 |
| 5962F9563002VYC | F | 06/25/2004 | 1 | INTERSIL | | Y | HS9-1840ARH-Q | 195 |
| 5962R9563002TYC | F | 06/25/2004 | 1 | INTERSIL | | Y | HS9-1840ARH-T | 195 |
| 5962F9563101V9A | D | 11/27/2002 | 1 | INTERSIL | | Y | HS0-26CT32RH-Q | 575 |
| 5962F9563101QEC | D | 11/27/2002 | 1 | INTERSIL | | Y | HS1-26CT32RH-8 | 575 |
| 5962F9563101VEC | D | 11/27/2002 | 1 | INTERSIL | | Y | HS1-26CT32RH-Q | 575 |
| 5962P9563101QEA | D | 11/27/2002 | 1 | STMICRO | | Y | RHP26CT32D09Q | 575 |
| 5962P9563101QEC | D | 11/27/2002 | 1 | STMICRO | | Y | RHP26CT32D08Q | 575 |
| 5962P9563101VEA | D | 11/27/2002 | 1 | STMICRO | | Y | RHP26CT32D09V | 575 |
| 5962P9563101VEC | D | 11/27/2002 | 1 | STMICRO | | Y | RHP26CT32D08V | 575 |
| 5962R9563101TEC | D | 11/27/2002 | 1 | INTERSIL | | Y | HS1-26CT32RH-T | 575 |
| 5962F9563101QXC | D | 11/27/2002 | 1 | INTERSIL | | Y | HS9-26CT32RH-8 | 575 |
| 5962F9563101VXC | D | 11/27/2002 | 1 | INTERSIL | | Y | HS9-26CT32RH-Q | 575 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962P9563101QXA | D | 11/27/2002 | 1 | STMICRO | | Y | RHP26CT32K02Q | 575 |
| 5962P9563101QXC | D | 11/27/2002 | 1 | STMICRO | | Y | RHP26CT32K01Q | 575 |
| 5962P9563101VXA | D | 11/27/2002 | 1 | STMICRO | | Y | RHP26CT32K02V | 575 |
| 5962P9563101VXC | D | 11/27/2002 | 1 | STMICRO | | Y | RHP26CT32K01V | 575 |
| 5962R9563101TXC | D | 11/27/2002 | 1 | INTERSIL | | Y | HS9-26CT32RH-T | 575 |
| 5962F9563201V9A | C | 11/27/2002 | 1 | INTERSIL | | Y | HS0-26CT31RH-Q | 569 |
| 5962D9563201QEA | C | 11/27/2002 | 1 | STMICRO | | Y | RHD26CT31D09Q | 569 |
| 5962D9563201QEC | C | 11/27/2002 | 1 | STMICRO | | Y | RHD26CT31D08Q | 569 |
| 5962D9563201VEA | C | 11/27/2002 | 1 | STMICRO | | Y | RHD26CT31D09V | 569 |
| 5962D9563201VEC | C | 11/27/2002 | 1 | STMICRO | | Y | RHD26CT31D08V | 569 |
| 5962F9563201QEC | C | 11/27/2002 | 1 | INTERSIL | | Y | HS1-26CT31RH-8 | 569 |
| 5962F9563201VEC | C | 11/27/2002 | 1 | INTERSIL | | Y | HS1-26CT31RH-Q | 569 |
| 5962R9563201TEC | C | 11/27/2002 | 1 | INTERSIL | | Y | HS1-26CT31RH-T | 569 |
| 5962D9563201QXA | C | 11/27/2002 | 1 | STMICRO | | Y | RHD26CT31K02Q | 569 |
| 5962D9563201QXC | C | 11/27/2002 | 1 | STMICRO | | Y | RHD26CT31K01Q | 569 |
| 5962D9563201VXA | C | 11/27/2002 | 1 | STMICRO | | Y | RHD26CT31K02V | 569 |
| 5962D9563201VXC | C | 11/27/2002 | 1 | STMICRO | | Y | RHD26CT31K01V | 569 |
| 5962F9563201QXC | C | 11/27/2002 | 1 | INTERSIL | | Y | HS9-26CT31RH-8 | 569 |
| 5962F9563201VXC | C | 11/27/2002 | 1 | INTERSIL | | Y | HS9-26CT31RH-Q | 569 |
| 5962R9563201TXC | C | 11/27/2002 | 1 | INTERSIL | | Y | HS9-26CT31RH-T | 569 |
| 5962-9563301Q2A | A | 07/20/2001 | 1 | TI | | Y | SNJ55453BFK | 582 |
| 5962-9563301QPA | A | 07/20/2001 | 1 | TI | | Y | SNJ55453BJG | 582 |
| 5962F9563501V9A | D | 06/01/1999 | | (NONE) | 03/23/2003 | | HS-RTX2010 (GEN) | 420 |
| 5962F9563501QXC | D | 06/01/1999 | | (NONE) | 09/23/2001 | | HS-RTX2010 (GEN) | 420 |
| 5962F9563501VXC | D | 06/01/1999 | | (NONE) | 09/23/2001 | | HS-RTX2010 (GEN) | 420 |
| 5962F9563501QYC | D | 06/01/1999 | | (NONE) | 03/23/2003 | | HS-RTX2010 (GEN) | 420 |
| 5962F9563501VYC | D | 06/01/1999 | | (NONE) | 03/23/2003 | | HS-RTX2010 (GEN) | 420 |
| 5962F9563601V9A | B | 10/16/1998 | | (NONE) | | | ACTS00 (GEN) | 100 |
| 5962F9563601VCC | B | 10/16/1998 | | (NONE) | | | ACTS00 (GEN) | 100 |
| 5962F9563601VXC | B | 10/16/1998 | | (NONE) | | | ACTS00 (GEN) | 100 |
| 5962F9563602V9A | B | 10/16/1998 | | (NONE) | | | ACTS00-02 (GEN) | 100 |
| 5962F9563602VCC | B | 10/16/1998 | | (NONE) | | | ACTS00-02 (GEN) | 100 |
| 5962F9563602VXC | B | 10/16/1998 | | (NONE) | | | ACTS00-02 (GEN) | 100 |
| 5962R9563701V9A | B | 02/02/2004 | | (NONE) | | | HCTS00 (GEN) | 100 |
| 5962R9563701VCC | B | 02/02/2004 | 1 | INTERSIL | | Y | HCTS00DMSR | 100 |
| 5962R9563701VXC | B | 02/02/2004 | 1 | INTERSIL | | Y | HCTS00KMSR | 100 |
| 5962H9563801Q9A | F | 06/12/2003 | 1 | UTMC | | Y | UT69RH051-Q DIE | 420 |
| 5962H9563801V9A | F | 06/12/2003 | 1 | UTMC | | Y | UT69RH051-V DIE | 420 |
| 5962H9563801QQA | F | 06/12/2003 | 1 | UTMC | | Y | UT69RH051PCA | 420 |
| 5962H9563801QQC | F | 06/12/2003 | 1 | UTMC | | Y | UT69RH051PCC | 420 |
| 5962H9563801VQA | F | 06/12/2003 | 1 | UTMC | | Y | UT69RH051PCA | 420 |
| 5962H9563801VQC | F | 06/12/2003 | 1 | UTMC | | Y | UT69RH051PCC | 420 |
| 5962H9563801QYA | F | 06/12/2003 | 1 | UTMC | | Y | UT69RH051WCA | 420 |
| 5962H9563801QYC | F | 06/12/2003 | 1 | UTMC | | Y | UT69RH051WCC | 420 |
| 5962H9563801VYA | F | 06/12/2003 | 1 | UTMC | | Y | UT69RH051WCA | 420 |
| 5962H9563801VYC | F | 06/12/2003 | 1 | UTMC | | Y | UT69RH051WCC | 420 |
| 5962-9563901MGA | A | 03/27/2002 | 1 | ANALOG (5) | | Y | AMP03BJ/883 | 712 |
| 5962-9564001Q2A | E | 01/31/2001 | 2 | TI | | Y | TLC2252MFKB | 710 |
| 5962-9564001QHA | E | 01/31/2001 | 2 | TI | | Y | TLC2252MUB | 710 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9564001QPA | E | 01/31/2001 | 2 | TI | | Y | TLC2252MJGB | 710 |
| 5962-9564001NXD | E | 01/31/2001 | 2 | TI | | Y | TLC2252MDQ | 710 |
| 5962-9564002Q2A | E | 01/31/2001 | 2 | TI | | Y | TLC2254MFKB | 713 |
| 5962-9564002QCA | E | 01/31/2001 | 2 | TI | | Y | TLC2254MJB | 713 |
| 5962-9564002QDA | E | 01/31/2001 | 2 | TI | | Y | TLC2254MWB | 713 |
| 5962-9564002NYD | E | 01/31/2001 | 2 | TI | | Y | TLC2254MDQ | 713 |
| 5962-9564003Q2A | E | 01/31/2001 | 2 | TI | | Y | TLC2252AMFKB | 710 |
| 5962-9564003QHA | E | 01/31/2001 | 2 | TI | | Y | TLC2252AMUB | 710 |
| 5962-9564003QPA | E | 01/31/2001 | 2 | TI | | Y | TLC2252AMJGB | 710 |
| 5962-9564003NXD | E | 01/31/2001 | 2 | TI | | Y | TLC2252AMDQ | 710 |
| 5962-9564004Q2A | E | 01/31/2001 | 2 | TI | | Y | TLC2254AMFKB | 713 |
| 5962-9564004QCA | E | 01/31/2001 | 2 | TI | | Y | TLC2254AMJB | 713 |
| 5962-9564004QDA | E | 01/31/2001 | 2 | TI | | Y | TLC2254AMWB | 713 |
| 5962-9564004NYD | E | 01/31/2001 | 2 | TI | | Y | TLC2254AMDQ | 713 |
| 5962-9564101MPA | | 06/20/1996 | | (NONE) | 03/30/2001 | | LT1215 (GEN) | 710 |
| 5962-9564102MPA | | 06/20/1996 | | (NONE) | 03/30/2001 | | LT1215A (GEN) | 710 |
| 5962-9564201Q2A | C | 08/22/2003 | 2 | TI | | Y | SNJ54LVTH245AFK | 590 |
| 5962-9564201QRA | C | 08/22/2003 | 2 | TI | | Y | SNJ54LVTH245AJ | 590 |
| 5962-9564201VRA | C | 08/22/2003 | 2 | TI | | Y | SNV54LVTH245AJ | 590 |
| 5962-9564201QSA | C | 08/22/2003 | 2 | TI | | Y | SNJ54LVTH245AW | 590 |
| 5962-9564201VSA | C | 08/22/2003 | 2 | TI | | Y | SNV54LVTH245AW | 590 |
| 5962-9564301QXA | C | 03/26/1997 | 1 | AUSTIN SEMI. | | Y | SMJ55166-80GBM | 629 |
| 5962-9564301QYC | C | 03/26/1997 | 1 | AUSTIN SEMI. | | Y | SMJ55166-80HKCM | 629 |
| 5962-9564302QXA | C | 03/26/1997 | | (NONE) | | | SMJ55166 (GEN) | 629 |
| 5962-9564302QYC | C | 03/26/1997 | | (NONE) | | | SMJ55166 (GEN) | 629 |
| 5962-9564303QXA | C | 03/26/1997 | 1 | AUSTIN SEMI. | | Y | SMJ55166-75GBM | 629 |
| 5962-9564303QYC | C | 03/26/1997 | 1 | AUSTIN SEMI. | | Y | SMJ55166-75HKCM | 629 |
| 5962-9564601QXA | A | 06/14/1996 | 2 | TI | | Y | SNJ54ABT16841WD | 341 |
| 5962-9564701QXA | B | 04/21/1998 | 1 | TI | | Y | SNJ54LVTH16374WD | 159 |
| 5962-9564801HXA | B | 03/29/2004 | 1 | ADV. ANALOG | | Y | ASA2812D/CH | 594 |
| 5962F9565001V9A | C | 07/17/2000 | | (NONE) | | | ACS00 (GEN) | 100 |
| 5962F9565001VCC | C | 07/17/2000 | | (NONE) | | | ACS00 (GEN) | 100 |
| 5962F9565001VXC | C | 07/17/2000 | | (NONE) | | | ACS00 (GEN) | 100 |
| 5962F9565002V9A | C | 07/17/2000 | | (NONE) | 03/26/2000 | | ACS00-02 (GEN) | 100 |
| 5962F9565002VCC | C | 07/17/2000 | 1 | INTERSIL | | Y | ACS00DMSR-02 | 100 |
| 5962F9565002VXC | C | 07/17/2000 | | (NONE) | | | ACS00-02 (GEN) | 100 |
| 5962F9565101V9A | C | 07/17/2000 | | (NONE) | | | ACS08 (GEN) | 110 |
| 5962F9565101VCC | C | 07/17/2000 | 1 | INTERSIL | | Y | ACS08DMSR | 110 |
| 5962F9565101VXC | C | 07/17/2000 | 1 | INTERSIL | | Y | ACS08KMSR | 110 |
| 5962F9565102V9A | C | 07/17/2000 | | (NONE) | 03/26/2000 | | ACS08-02 (GEN) | 110 |
| 5962F9565102VCC | C | 07/17/2000 | | (NONE) | | | ACS08-02 (GEN) | 110 |
| 5962F9565102VXC | C | 07/17/2000 | | (NONE) | | | ACS08-02 (GEN) | 110 |
| 5962F9565201VCC | C | 07/20/2000 | | (NONE) | | | ACS10 (GEN) | 102 |
| 5962F9565201VXC | C | 07/20/2000 | | (NONE) | | | ACS10 (GEN) | 102 |
| 5962F9565202V9A | C | 07/20/2000 | | (NONE) | | | ACS10 (GEN) | 102 |
| 5962F9565202VCC | C | 07/20/2000 | | (NONE) | | | ACS10 (GEN) | 102 |
| 5962F9565202VXC | C | 07/20/2000 | | (NONE) | | | ACS10 (GEN) | 102 |
| 5962F9565301VCC | C | 08/01/2000 | | (NONE) | | | ACS20 (GEN) | 104 |
| 5962F9565301VXC | C | 08/01/2000 | | (NONE) | 09/24/2000 | | ACS20 (GEN) | 104 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962F9565302V9A | C | 08/01/2000 | | (NONE) | | | ACS20 (GEN) | 104 |
| 5962F9565302VCC | C | 08/01/2000 | | (NONE) | | | ACS20 (GEN) | 104 |
| 5962F9565302VXC | C | 08/01/2000 | | (NONE) | | | ACS20 (GEN) | 104 |
| 5962F9565401VCC | C | 08/01/2000 | | (NONE) | | | ACS86 (GEN) | 140 |
| 5962F9565401VXC | C | 08/01/2000 | | (NONE) | | | ACS86 (GEN) | 140 |
| 5962F9565402V9A | C | 08/01/2000 | | (NONE) | | | ACS86 (GEN) | 140 |
| 5962F9565402VCC | C | 08/01/2000 | | (NONE) | | | ACS86 (GEN) | 140 |
| 5962F9565402VXC | C | 08/01/2000 | | (NONE) | | | ACS86 (GEN) | 140 |
| 5962F9565501V9A | C | 08/01/2000 | | (NONE) | | | ACS373 (GEN) | 341 |
| 5962F9565501VRC | C | 08/01/2000 | 1 | INTERSIL | | Y | ACS373DMSR | 341 |
| 5962F9565501VXC | C | 08/01/2000 | 1 | INTERSIL | | Y | ACS373KMSR | 341 |
| 5962F9565502V9A | C | 08/01/2000 | | (NONE) | | | ACS373-02 (GEN) | 341 |
| 5962F9565502VRC | C | 08/01/2000 | | (NONE) | | | ACS373-02 (GEN) | 341 |
| 5962F9565502VXC | C | 08/01/2000 | | (NONE) | | | ACS373-02 (GEN) | 341 |
| 5962F9565601V9A | C | 08/01/2000 | | (NONE) | | | ACS374 (GEN) | 159 |
| 5962F9565601VRC | C | 08/01/2000 | 1 | INTERSIL | | Y | ACS374DMSR | 159 |
| 5962F9565601VXC | C | 08/01/2000 | 1 | INTERSIL | | Y | ACS374KMSR | 159 |
| 5962F9565602V9A | C | 08/01/2000 | | (NONE) | | | ACS374-02 (GEN) | 159 |
| 5962F9565602VRC | C | 08/01/2000 | | (NONE) | | | ACS374-02 (GEN) | 159 |
| 5962F9565602VXC | C | 08/01/2000 | | (NONE) | | | ACS374-02 (GEN) | 159 |
| 5962F9565701VCC | C | 08/01/2000 | | (NONE) | | | ACTS08 (GEN) | 110 |
| 5962F9565701VXC | C | 08/01/2000 | | (NONE) | | | ACTS08 (GEN) | 110 |
| 5962F9565702V9A | C | 08/01/2000 | | (NONE) | | | ACTS08 (GEN) | 110 |
| 5962F9565702VCC | C | 08/01/2000 | 1 | INTERSIL | | Y | ACTS08DMSR-02 | 110 |
| 5962F9565702VXC | C | 08/01/2000 | 1 | INTERSIL | | Y | ACTS08KMSR-02 | 110 |
| 5962F9565801VCC | C | 08/10/2000 | | (NONE) | | | ACTS10 (GEN) | 102 |
| 5962F9565801VXC | C | 08/10/2000 | | (NONE) | | | ACTS10 (GEN) | 102 |
| 5962F9565802V9A | C | 08/10/2000 | | (NONE) | | | ACTS10 (GEN) | 102 |
| 5962F9565802VCC | C | 08/10/2000 | | (NONE) | | | ACTS10 (GEN) | 102 |
| 5962F9565802VXC | C | 08/10/2000 | | (NONE) | | | ACTS10 (GEN) | 102 |
| 5962F9565901VCC | C | 08/10/2000 | | (NONE) | | | ACTS20 (GEN) | 104 |
| 5962F9565901VXC | C | 08/10/2000 | | (NONE) | | | ACTS20 (GEN) | 104 |
| 5962F9565902V9A | C | 08/10/2000 | | (NONE) | | | ACTS20 (GEN) | 104 |
| 5962F9565902VCC | C | 08/10/2000 | | (NONE) | | | ACTS20 (GEN) | 104 |
| 5962F9565902VXC | C | 08/10/2000 | | (NONE) | | | ACTS20 (GEN) | 104 |
| 5962F9566001VCC | C | 08/10/2000 | | (NONE) | | | ACTS86 (GEN) | 140 |
| 5962F9566001VXC | C | 08/10/2000 | | (NONE) | | | ACTS86 (GEN) | 140 |
| 5962F9566002V9A | C | 08/10/2000 | | (NONE) | | | ACTS86 (GEN) | 140 |
| 5962F9566002VCC | C | 08/10/2000 | | (NONE) | | | ACTS86 (GEN) | 140 |
| 5962F9566002VXC | C | 08/10/2000 | | (NONE) | | | ACTS86 (GEN) | 140 |
| 5962F9566101VRC | C | 08/10/2000 | | (NONE) | | | ACTS373 (GEN) | 341 |
| 5962F9566101VXC | C | 08/10/2000 | | (NONE) | | | ACTS373 (GEN) | 341 |
| 5962F9566102V9A | C | 08/10/2000 | | (NONE) | | | ACTS373 (GEN) | 341 |
| 5962F9566102VRC | C | 08/10/2000 | 1 | INTERSIL | | Y | ACTS373DMSR-02 | 341 |
| 5962F9566102VXC | C | 08/10/2000 | 1 | INTERSIL | | Y | ACTS373KMSR-02 | 341 |
| 5962F9566201V9A | B | 10/16/1998 | | (NONE) | | | ACTS374 (GEN) | 159 |
| 5962F9566201VRC | B | 10/16/1998 | | (NONE) | | | ACTS374 (GEN) | 159 |
| 5962F9566201VXC | B | 10/16/1998 | | (NONE) | | | ACTS374 (GEN) | 159 |
| 5962F9566202V9A | B | 10/16/1998 | | (NONE) | | | ACTS374-02 (GEN) | 159 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962F9566202VRC | B | 10/16/1998 | | (NONE) | | | ACTS374-02 (GEN) | 159 |
| 5962F9566202VXC | B | 10/16/1998 | | (NONE) | | | ACTS374-02 (GEN) | 159 |
| 5962R9566301V9A | C | 08/14/2000 | | (NONE) | | | HCTS164 (GEN) | 226 |
| 5962R9566301VCC | C | 08/14/2000 | 1 | INTERSIL | | Y | HCTS164DMSR | 226 |
| 5962R9566301VXC | C | 08/14/2000 | 1 | INTERSIL | | Y | HCTS164KMSR | 226 |
| 5962-9566501MPA | | 01/19/1996 | | (NONE) | 03/30/2001 | | LT1213 (GEN) | 710 |
| 5962-9566601Q2A | C | 02/26/2001 | 2 | TI | | Y | TLV2252MFKB | 710 |
| 5962-9566601QHA | C | 02/26/2001 | 2 | TI | | Y | TLV2252MUB | 710 |
| 5962-9566601QPA | C | 02/26/2001 | 2 | TI | | Y | TLV2252MJGB | 710 |
| 5962-9566602Q2A | C | 02/26/2001 | 2 | TI | | Y | TLV2254MFKB | 713 |
| 5962-9566602QCA | C | 02/26/2001 | 2 | TI | | Y | TLV2254MJB | 713 |
| 5962-9566602QDA | C | 02/26/2001 | 2 | TI | | Y | TLV2254MWB | 713 |
| 5962-9566603Q2A | C | 02/26/2001 | 2 | TI | | Y | TLV2252AMFKB | 710 |
| 5962-9566603QHA | C | 02/26/2001 | 2 | TI | | Y | TLV2252AMUB | 710 |
| 5962-9566603QPA | C | 02/26/2001 | 2 | TI | | Y | TLV2252AMJGB | 710 |
| 5962-9566604Q2A | C | 02/26/2001 | 2 | TI | | Y | TLV2254AMFKB | 713 |
| 5962-9566604QCA | C | 02/26/2001 | 2 | TI | | Y | TLV2254AMJB | 713 |
| 5962-9566604QDA | C | 02/26/2001 | 2 | TI | | Y | TLV2254AMWB | 713 |
| 5962-9566701MEA | A | 08/13/2001 | 1 | MAXIM INTEG. | | | MAX532AMJE/883B | 591 |
| 5962-9566702MEA | A | 08/13/2001 | 1 | MAXIM INTEG. | | | MAX532BMJE/883B | 591 |
| 5962-9566801HXA | A | 04/27/2001 | 1 | MS KENNEDY | | Y | MSK1259B | 739 |
| 5962-9566801HXC | A | 04/27/2001 | 1 | MS KENNEDY | | Y | MSK1259B | 739 |
| 5962R9566901VCC | A | 04/04/1997 | 1 | INTERSIL | | Y | HS1B-2420RH-Q | 818 |
| 5962D9567001VCA | C | 09/24/2003 | | (NONE) | | | 2700A (GEN) | 701 |
| 5962D9567001VGA | C | 09/24/2003 | | (NONE) | | | 2700A (GEN) | 701 |
| 5962D9567002VCC | C | 09/24/2003 | 1 | INTERSIL | | Y | HS1B-2700RH-Q | 701 |
| 5962D9567002VGA | C | 09/24/2003 | 1 | INTERSIL | | Y | HS2-2700RH-Q | 701 |
| 5962D9567101VPC | A | 06/24/1999 | | (NONE) | | | HS-2600 (GEN) | 755 |
| 5962R9567901V9A | C | 08/23/2000 | 1 | INTERSIL | | Y | HCS02HMSR | 120 |
| 5962R9567901VCC | C | 08/23/2000 | | (NONE) | | | HCS02 (GEN) | 120 |
| 5962R9567901VXC | C | 08/23/2000 | 1 | INTERSIL | | Y | HCS02KMSR | 120 |
| 5962R9568001V9A | B | 09/15/2000 | 1 | INTERSIL | | Y | HCS08HMSR | 110 |
| 5962R9568001VCC | B | 09/15/2000 | 1 | INTERSIL | | Y | HCS08DMSR | 110 |
| 5962R9568001VXC | B | 09/15/2000 | 1 | INTERSIL | | Y | HCS08KMSR | 110 |
| 5962R9568101V9A | B | 08/23/2000 | 1 | INTERSIL | 07/12/2004 | Y | HCS14HMSR | 143 |
| 5962R9568101VCC | B | 08/23/2000 | 1 | INTERSIL | 07/12/2004 | Y | HCS14DMSR | 143 |
| 5962R9568101VXC | B | 08/23/2000 | 1 | INTERSIL | 07/12/2004 | Y | HCS14KMSR | 143 |
| 5962R9568201V9A | C | 08/25/2000 | | (NONE) | | | HCTS02 (GEN) | 120 |
| 5962R9568201VCC | C | 08/25/2000 | | (NONE) | 12/28/2003 | | HCTS02 (GEN) | 120 |
| 5962R9568201VXC | C | 08/25/2000 | | (NONE) | 12/28/2003 | | HCTS02 (GEN) | 120 |
| 5962R9568301V9A | B | 08/25/2000 | 1 | INTERSIL | | Y | HCTS08HMSR | 110 |
| 5962R9568301VCC | B | 08/25/2000 | 1 | INTERSIL | | Y | HCTS08DMSR | 110 |
| 5962R9568301VXC | B | 08/25/2000 | 1 | INTERSIL | | Y | HCTS08KMSR | 110 |
| 5962D9568401VEC | B | 06/15/1999 | 1 | INTERSIL | | Y | HS1B-2400RH-Q | 739 |
| 5962D9568501V9A | D | 07/27/2001 | | (NONE) | 01/07/2003 | | HS-2520 (GEN) | 702 |
| 5962D9568501VGA | D | 07/27/2001 | 1 | INTERSIL | | Y | HS2-2520RH-Q | 702 |
| 5962D9568501VPC | D | 07/27/2001 | 1 | INTERSIL | | Y | HS7B-2520RH-Q | 702 |
| 5962D9568601VPC | B | 10/03/2003 | 1 | INTERSIL | | Y | HS7B-2510RH-Q | 719 |
| 5962D9568601VXC | B | 10/03/2003 | 1 | INTERSIL | | Y | HS9-2510RH-Q | 719 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962F9568701V9A | C | 10/03/2003 | 1 | INTERSIL | | Y | HSO-3530ARH-Q | 700 |
| 5962F9568701QGA | C | 10/03/2003 | 1 | INTERSIL | | Y | HS2-3530ARH-8 | 700 |
| 5962F9568701VGA | C | 10/03/2003 | 1 | INTERSIL | | Y | HS2-3530ARH-Q | 700 |
| 5962F9568701VXC | C | 10/03/2003 | 1 | INTERSIL | | Y | HS9-3530ARH-Q | 700 |
| 5962D9568801VGA | C | 03/14/2003 | | (NONE) | | | HS-2620 (GEN) | 755 |
| 5962D9568801VPC | C | 03/14/2003 | | (NONE) | 01/07/2003 | | HS-2620 (GEN) | 755 |
| 5962D9568802VGC | C | 03/14/2003 | | (NONE) | | | HS-2622 (GEN) | 755 |
| 5962D9568802VPC | C | 03/14/2003 | 1 | INTERSIL | | Y | HS7B-2622RH-Q | 755 |
| 5962F9568901V9A | F | 11/27/2002 | 1 | INTERSIL | | Y | HS0-26C32RH-Q | 575 |
| 5962F9568901QEC | F | 11/27/2002 | 1 | INTERSIL | | Y | HS1-26C32RH-8 | 575 |
| 5962F9568901VEC | F | 11/27/2002 | 1 | INTERSIL | | Y | HS1-26C32RH-Q | 575 |
| 5962P9568901QEA | F | 11/27/2002 | 1 | STMICRO | | Y | RHP26C32D09Q | 575 |
| 5962P9568901QEC | F | 11/27/2002 | 1 | STMICRO | | Y | RHP26C32D08Q | 575 |
| 5962P9568901VEA | F | 11/27/2002 | 1 | STMICRO | | Y | RHP26C32D09V | 575 |
| 5962P9568901VEC | F | 11/27/2002 | 1 | STMICRO | | Y | RHP26C32D08V | 575 |
| 5962R9568901TEC | F | 11/27/2002 | 1 | INTERSIL | | Y | HS1-26C32RH-T | 575 |
| 5962F9568901QXC | F | 11/27/2002 | 1 | INTERSIL | | Y | HS9-26C32RH-8 | 575 |
| 5962F9568901VXC | F | 11/27/2002 | 1 | INTERSIL | | Y | HS9-26C32RH-Q | 575 |
| 5962P9568901QXA | F | 11/27/2002 | 1 | STMICRO | | Y | RHP26C32K02Q | 575 |
| 5962P9568901QXC | F | 11/27/2002 | 1 | STMICRO | | Y | RHP26C32K01Q | 575 |
| 5962P9568901VXA | F | 11/27/2002 | 1 | STMICRO | | Y | RHP26C32K02V | 575 |
| 5962P9568901VXC | F | 11/27/2002 | 1 | STMICRO | | Y | RHP26C32K01V | 575 |
| 5962R9568901TXC | F | 11/27/2002 | 1 | INTERSIL | | Y | HS9-26C32RH-T | 575 |
| 5962F9568902V9A | F | 11/27/2002 | 1 | INTERSIL | | Y | HS0-26CLV32RH-Q | 575 |
| 5962F9568902QEC | F | 11/27/2002 | 1 | INTERSIL | | Y | HS1-26CLV32RH-8 | 575 |
| 5962F9568902VEC | F | 11/27/2002 | 1 | INTERSIL | | Y | HS1-26CLV32RH-Q | 575 |
| 5962R9568902TEC | F | 11/27/2002 | 1 | INTERSIL | | Y | HS1-26CLV32RH-T | 575 |
| 5962F9568902QXC | F | 11/27/2002 | 1 | INTERSIL | | Y | HS9-26CLV32RH-8 | 575 |
| 5962F9568902VXC | F | 11/27/2002 | 1 | INTERSIL | | Y | HS9-26CLV32RH-Q | 575 |
| 5962R9568902TXC | F | 11/27/2002 | 1 | INTERSIL | | Y | HS9-26CLV32RH-T | 575 |
| 5962R9569001V9A | E | 04/13/1999 | 1 | INTERSIL | | Y | HS0-5104ARH-Q | 713 |
| 5962R9569001TCC | E | 04/13/1999 | 1 | INTERSIL | | Y | HS1-5104ARH-T | 713 |
| 5962R9569001VCC | E | 04/13/1999 | 1 | INTERSIL | | Y | HS1-5104ARH-Q | 713 |
| 5962R9569001TXC | E | 04/13/1999 | 1 | INTERSIL | | Y | HS9-5104ARH-T | 713 |
| 5962R9569001VXC | E | 04/13/1999 | 1 | INTERSIL | | Y | HS9-5104ARH-Q | 713 |
| 5962D9569101VXA | B | 08/04/1999 | | (NONE) | 03/25/2001 | | HS-506 (GEN) | 195 |
| 5962D9569102VXA | B | 08/04/1999 | | (NONE) | 03/25/2001 | | HS-507 (GEN) | 194 |
| 5962D9569201VEA | A | 07/12/1999 | | (NONE) | 03/25/2001 | | HS-0508RH (GEN) | 193 |
| 5962D9569202VEA | A | 07/12/1999 | | (NONE) | 03/25/2001 | | HS-0509RH (GEN) | 192 |
| 5962D9569301V9A | D | 07/19/2000 | 1 | INTERSIL | | Y | HS0-0546RH-Q | 195 |
| 5962D9569301VXA | D | 07/19/2000 | | (NONE) | 01/07/2003 | | HS-0546 (GEN) | 195 |
| 5962D9569301VXC | D | 07/19/2000 | 1 | INTERSIL | | Y | HS1B-0546RH-Q | 195 |
| 5962D9569302V9A | D | 07/19/2000 | 1 | INTERSIL | | Y | HS0-0547RH-Q | 194 |
| 5962D9569302VXC | D | 07/19/2000 | 1 | INTERSIL | | Y | HS1B-0547RH-Q | 194 |
| 5962D9569401VEC | C | 06/29/2000 | 1 | INTERSIL | 10/03/2004 | Y | HS1B-0548RH-Q | 194 |
| 5962D9569402VEA | C | 06/29/2000 | | (NONE) | 01/07/2003 | | HS-0549 (GEN) | 192 |
| 5962D9569402VEC | C | 06/29/2000 | 1 | INTERSIL | | Y | HS1B-0549RH-Q | 192 |
| 5962-9569601HXA | C | 03/30/2004 | 1 | INTERPOINT | | Y | MCH2805S/883 | 594 |
| 5962-9569601HXC | C | 03/30/2004 | 1 | INTERPOINT | | Y | MCH2805S/883 | 594 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9569601HYA | C | 03/30/2004 | 1 | INTERPOINT | | Y | MGH2805S/883 | 594 |
| 5962-9569601HYC | C | 03/30/2004 | 1 | INTERPOINT | | Y | MGH2805S/883 | 594 |
| 5962-9569601HZA | C | 03/30/2004 | 1 | INTERPOINT | | Y | MGH2805SZ/883 | 594 |
| 5962-9569701HXA | C | 07/27/2004 | 1 | INTERPOINT | | Y | MCH2812S/883 | 594 |
| 5962-9569701HXC | C | 07/27/2004 | 1 | INTERPOINT | | Y | MCH2812S/883 | 594 |
| 5962-9569701HYA | C | 07/27/2004 | 1 | INTERPOINT | | Y | MGH2812SY/883 | 594 |
| 5962-9569701HYC | C | 07/27/2004 | 1 | INTERPOINT | | Y | MGH2812SY/883 | 594 |
| 5962-9569701HZA | C | 07/27/2004 | 1 | INTERPOINT | | Y | MGH2812SZ/883 | 594 |
| 5962-9569801HXA | C | 07/27/2004 | 1 | INTERPOINT | | Y | MCH2815S/883 | 594 |
| 5962-9569801HXC | C | 07/27/2004 | 1 | INTERPOINT | | Y | MCH2815S/883 | 594 |
| 5962-9569801HYA | C | 07/27/2004 | 1 | INTERPOINT | | Y | MGH2815SY/883 | 594 |
| 5962-9569801HYC | C | 07/27/2004 | 1 | INTERPOINT | | Y | MGH2815SY/883 | 594 |
| 5962-9569801HZA | C | 07/27/2004 | 1 | INTERPOINT | | Y | MGH2815SZ/883 | 594 |
| 5962-9569901HXA | | 08/13/1996 | | (NONE) | | | 2805SN (GEN) | 594 |
| 5962-9570001HXA | | 08/14/1996 | | (NONE) | | | 2812SN (GEN) | 594 |
| 5962-9570101HXA | | 08/14/1996 | | (NONE) | | | 2815SN (GEN) | 594 |
| 5962-9570201HXA | C | 07/27/2004 | 1 | INTERPOINT | | Y | MCH2805D/883 | 594 |
| 5962-9570201HXC | C | 07/27/2004 | 1 | INTERPOINT | | Y | MCH2805D/883 | 594 |
| 5962-9570201HYA | C | 07/27/2004 | 1 | INTERPOINT | | Y | MGH2805DY/883 | 594 |
| 5962-9570201HYC | C | 07/27/2004 | 1 | INTERPOINT | | Y | MGH2805DY/883 | 594 |
| 5962-9570201HZA | C | 07/27/2004 | 1 | INTERPOINT | | Y | MGH2805DZ/883 | 594 |
| 5962-9570301HXA | C | 07/27/2004 | 1 | INTERPOINT | | Y | MCH2812D/883 | 594 |
| 5962-9570301HXC | C | 07/27/2004 | 1 | INTERPOINT | | Y | MCH2812D/883 | 594 |
| 5962-9570301HYA | C | 07/27/2004 | 1 | INTERPOINT | | Y | MGH2812DY/883 | 594 |
| 5962-9570301HYC | C | 07/27/2004 | 1 | INTERPOINT | | Y | MGH2812DY/883 | 594 |
| 5962-9570301HZA | C | 07/27/2004 | 1 | INTERPOINT | | Y | MGH2812DZ/883 | 594 |
| 5962-9570401HXA | C | 07/27/2004 | 1 | INTERPOINT | | Y | MCH2815D/883 | 594 |
| 5962-9570401HXC | C | 07/27/2004 | 1 | INTERPOINT | | Y | MCH2815D/883 | 594 |
| 5962-9570401HYA | C | 07/27/2004 | 1 | INTERPOINT | | Y | MGH2815DY/883 | 594 |
| 5962-9570401HYC | C | 07/27/2004 | 1 | INTERPOINT | | Y | MGH2815DY/883 | 594 |
| 5962-9570401HZA | C | 07/27/2004 | 1 | INTERPOINT | | Y | MGH2815DZ/883 | 594 |
| 5962-9570501HXA | | 06/28/1996 | | (NONE) | | | 2805DN (GEN) | 594 |
| 5962-9570601HXA | | 06/28/1996 | | (NONE) | | | 2812DN (GEN) | 594 |
| 5962-9570701HXA | | 06/28/1996 | | (NONE) | | | 2815DN (GEN) | 594 |
| 5962R9570801QJC | D | 06/11/1999 | | (NONE) | 06/29/2002 | | HS-6617 (GEN) | 616 |
| 5962R9570801TJC | D | 06/11/1999 | | (NONE) | 06/29/2002 | | HS-6617 (GEN) | 616 |
| 5962R9570801VJC | D | 06/11/1999 | | (NONE) | 06/29/2002 | | HS-6617 (GEN) | 616 |
| 5962R9570801QXC | D | 06/11/1999 | | (NONE) | 06/29/2002 | | HS-6617 (GEN) | 616 |
| 5962R9570801TXC | D | 06/11/1999 | | (NONE) | 06/29/2002 | | HS-6617 (GEN) | 616 |
| 5962R9570801VXC | D | 06/11/1999 | | (NONE) | 06/29/2002 | | HS-6617 (GEN) | 616 |
| 5962-9570901M2A | C | 05/02/2002 | | (NONE) | | | 2990-15 (GEN) | 783 |
| 5962-9570901M4A | C | 05/02/2002 | 1 | INTER. RECT. | | | OM2990-15SRM/883B | 783 |
| 5962-9570901QEA | C | 05/02/2002 | 2 | NATIONAL | | Y | LM2990J-15-QML | 783 |
| 5962-9570901MMA | C | 05/02/2002 | | (NONE) | | | 2990-15 (GEN) | 783 |
| 5962-9570901MNA | C | 05/02/2002 | | (NONE) | | | 2990-15 (GEN) | 783 |
| 5962-9570901MTA | C | 05/02/2002 | | (NONE) | | | 2990-15 (GEN) | 783 |
| 5962-9570901MUA | C | 05/02/2002 | 1 | INTER. RECT. | | | OM2990-15STM | 783 |
| 5962-9570901QXA | C | 05/02/2002 | 2 | NATIONAL | | Y | LM2990WG-15-QML | 783 |
| 5962-9570901MYA | C | 05/02/2002 | | (NONE) | | | 2990-15 (GEN) | 783 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9570901MZA | C | 05/02/2002 | 1 | INTER. RECT. | | | OM2990-15N5M/883B | 783 |
| 5962-9571001QEA | B | 03/20/2002 | 2 | NATIONAL | | Y | LM2990J-12-QML | 783 |
| 5962-9571001MMA | B | 03/20/2002 | 1 | INTER. RECT. | | | OM2990-12SRM/883B | 783 |
| 5962-9571001MNA | B | 03/20/2002 | 1 | INTER. RECT. | | | OM2990-12N5M/883B | 783 |
| 5962-9571001MUA | B | 03/20/2002 | 1 | INTER. RECT. | | | OM2990-12STM | 783 |
| 5962-9571001QXA | B | 03/20/2002 | 2 | NATIONAL | | Y | LM2990WG-12-QML | 783 |
| 5962-9571101QEA | C | 05/01/2002 | 2 | NATIONAL | | Y | LM2990J-5.0-QML | 783 |
| 5962-9571101MMA | C | 05/01/2002 | 1 | INTER. RECT. | | | OM2990-5SRM/883B | 783 |
| 5962-9571101MNA | C | 05/01/2002 | 1 | INTER. RECT. | | | OM2990-5N5M/883B | 783 |
| 5962-9571101MUA | C | 05/01/2002 | 1 | INTER. RECT. | | | OM2990-5STM | 783 |
| 5962-9571101QXA | C | 05/01/2002 | 2 | NATIONAL | | Y | LM2990WG-5.0-QML | 783 |
| 5962-9571102MMA | C | 05/01/2002 | 1 | INTER. RECT. | | | OM2990-5.2SRM/883B | 783 |
| 5962-9571102MNA | C | 05/01/2002 | 1 | INTER. RECT. | | | OM2990-5.2N5M/883B | 783 |
| 5962-9571102MUA | C | 05/01/2002 | 1 | INTER. RECT. | | | OM2990-5.2STM | 783 |
| 5962-9571201Q3A | | 07/31/1995 | 2 | TI | | Y | SNJ54ABT843FK | 342 |
| 5962-9571201QKA | | 07/31/1995 | 2 | TI | | Y | SNJ54ABT843W | 342 |
| 5962-9571201QLA | | 07/31/1995 | 2 | TI | | Y | SNJ54ABT843JT | 342 |
| 5962R9571301QJC | A | 07/08/1998 | 0 | INTERSIL | | Y | HS1-82C54RH-8 | 424 |
| 5962R9571301VJC | A | 07/08/1998 | 0 | INTERSIL | | Y | HS1-82C54RH-Q | 424 |
| 5962R9571301QXC | A | 07/08/1998 | 0 | INTERSIL | | Y | HS9-82C54RH-8 | 424 |
| 5962R9571301VXC | A | 07/08/1998 | 0 | INTERSIL | | Y | HS9-82C54RH-Q | 424 |
| 5962R9571401QRC | A | 01/31/1996 | | (NONE) | | | HS-82C08 (GEN) | 590 |
| 5962R9571401VRC | A | 01/31/1996 | | (NONE) | | | HS-82C08 (GEN) | 590 |
| 5962R9571401QXC | A | 01/31/1996 | | (NONE) | | | HS-82C08 (GEN) | 590 |
| 5962R9571401VXC | A | 01/31/1996 | | (NONE) | | | HS-82C08 (GEN) | 590 |
| 5962-9571501VVC | | 01/11/1996 | | (NONE) | 01/07/2003 | | 82C84A/7 (GEN) | 422 |
| 5962-9571601VRC | | 12/28/1995 | | (NONE) | 01/07/2003 | | 82C82/7 (GEN) | 569 |
| 5962-9571701VRC | | 11/24/1995 | | (NONE) | | | 82C86 (GEN) | 590 |
| 5962-9571801VXC | A | 07/27/1998 | 1 | INTERSIL | | Y | MD82C59A/7 | 420 |
| 5962R9571901V9A | C | 02/02/2004 | 1 | INTERSIL | 09/26/2004 | Y | HCTS14HMSR | 143 |
| 5962R9571901VCC | C | 02/02/2004 | 1 | INTERSIL | 09/26/2004 | Y | HCTS14DMSR | 143 |
| 5962R9571901VXC | C | 02/02/2004 | 1 | INTERSIL | 09/26/2004 | Y | HCTS14KMSR | 143 |
| 5962R9572001V9A | B | 08/25/2000 | | (NONE) | | | HCS11 (GEN) | 112 |
| 5962R9572001VCC | B | 08/25/2000 | 1 | INTERSIL | | Y | HCS11DMSR | 112 |
| 5962R9572001VXC | B | 08/25/2000 | 1 | INTERSIL | | Y | HCS11KMSR | 112 |
| 5962R9572101V9A | B | 09/01/2000 | | (NONE) | | | HCTS11 (GEN) | 112 |
| 5962R9572101VCC | B | 09/01/2000 | | (NONE) | | | HCTS11 (GEN) | 112 |
| 5962R9572101VXC | B | 09/01/2000 | | (NONE) | | | HCTS11 (GEN) | 112 |
| 5962R9572201QQC | A | 04/05/1996 | 0 | INTERSIL | | Y | HS1-80C86RH-8 | 403 |
| 5962R9572201VQC | A | 04/05/1996 | | (NONE) | | | HS-80C86 (GEN) | 403 |
| 5962R9572201QXC | A | 04/05/1996 | 0 | INTERSIL | | Y | HS9-80C86RH-8 | 403 |
| 5962R9572201VXC | A | 04/05/1996 | 0 | INTERSIL | | Y | HS9-80C86RH-Q | 403 |
| 5962R9572401V9A | B | 09/01/2000 | 1 | INTERSIL | | Y | HCS00HMSR | 100 |
| 5962R9572401VCC | B | 09/01/2000 | 1 | INTERSIL | | Y | HCS00DMSR | 100 |
| 5962R9572401VXC | B | 09/01/2000 | 1 | INTERSIL | | Y | HCS00KMSR | 100 |
| 5962R9572501V9A | B | 09/01/2000 | | (NONE) | 03/01/2004 | | HCS04 (GEN) | 143 |
| 5962R9572501VCC | B | 09/01/2000 | | (NONE) | 03/01/2004 | | HCS04 (GEN) | 143 |
| 5962R9572501VXC | B | 09/01/2000 | | (NONE) | 03/01/2004 | | HCS04 (GEN) | 143 |
| 5962R9572601V9A | B | 09/01/2000 | 1 | INTERSIL | | Y | HCS132HMSR | 109 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962R9572601VCC | B | 09/01/2000 | 1 | INTERSIL | | Y | HCS132DMSR | 109 |
| 5962R9572601VXC | B | 09/01/2000 | 1 | INTERSIL | | Y | HCS132KMSR | 109 |
| 5962R9572701V9A | C | 04/29/1999 | | (NONE) | | | HCS138 (GEN) | 282 |
| 5962R9572701TEC | C | 04/29/1999 | | (NONE) | | | HCS138 (GEN) | 282 |
| 5962R9572701VEC | C | 04/29/1999 | 1 | INTERSIL | | Y | HCS138DMSR | 282 |
| 5962R9572701TXC | C | 04/29/1999 | | (NONE) | | | HCS138 (GEN) | 282 |
| 5962R9572701VXC | C | 04/29/1999 | 1 | INTERSIL | | Y | HCS138KMSR | 282 |
| 5962R9572801V9A | C | 09/01/2000 | | (NONE) | | | HCS151 (GEN) | 271 |
| 5962R9572801VEC | C | 09/01/2000 | | (NONE) | 09/23/2001 | | HCS151 (GEN) | 271 |
| 5962R9572801VXC | C | 09/01/2000 | 1 | INTERSIL | | Y | HCS151KMSR | 271 |
| 5962R9572901V9A | B | 09/14/2000 | | (NONE) | | | HCS154 (GEN) | 280 |
| 5962R9572901VJC | B | 09/14/2000 | 1 | INTERSIL | | Y | HCS154DMSR | 280 |
| 5962R9572901VXC | B | 09/14/2000 | 1 | INTERSIL | | Y | HCS154KMSR | 280 |
| 5962R9573001V9A | B | 09/14/2000 | 1 | INTERSIL | | Y | HCS161HMSR | 304 |
| 5962R9573001VEC | B | 09/14/2000 | 1 | INTERSIL | | Y | HCS161DMSR | 304 |
| 5962R9573001VXC | B | 09/14/2000 | 1 | INTERSIL | | Y | HCS161KMSR | 304 |
| 5962R9573101V9A | C | 04/29/1999 | | (NONE) | | | HCS244 (GEN) | 529 |
| 5962R9573101TRC | C | 04/29/1999 | | (NONE) | 03/23/2001 | | HCS244 (GEN) | 529 |
| 5962R9573101VRC | C | 04/29/1999 | 1 | INTERSIL | 05/01/2004 | Y | HCS244DMSR | 529 |
| 5962R9573101TXC | C | 04/29/1999 | | (NONE) | 03/23/2001 | | HCS244 (GEN) | 529 |
| 5962R9573101VXC | C | 04/29/1999 | 1 | INTERSIL | 05/01/2004 | Y | HCS244KMSR | 529 |
| 5962R9573201V9A | B | 09/15/2000 | 1 | INTERSIL | | Y | HCTS04HMSR | 143 |
| 5962R9573201VCC | B | 09/15/2000 | 1 | INTERSIL | | Y | HCTS04DMSR | 143 |
| 5962R9573201VXC | B | 09/15/2000 | 1 | INTERSIL | | Y | HCTS04KMSR | 143 |
| 5962R9573301V9A | B | 09/15/2000 | | (NONE) | | | HCTS20 (GEN) | 104 |
| 5962R9573301VCC | B | 09/15/2000 | | (NONE) | 09/23/2001 | | HCTS20 (GEN) | 104 |
| 5962R9573301VXC | B | 09/15/2000 | 1 | INTERSIL | | Y | HCTS20KMSR | 104 |
| 5962R9573401V9A | B | 09/15/2000 | | (NONE) | | | HCTS27 (GEN) | 122 |
| 5962R9573401VCC | B | 09/15/2000 | | (NONE) | | | HCTS27 (GEN) | 122 |
| 5962R9573401VXC | B | 09/15/2000 | | (NONE) | | | HCTS27 (GEN) | 122 |
| 5962R9573501V9A | B | 09/15/2000 | | (NONE) | | | HCTS30 (GEN) | 106 |
| 5962R9573501VCC | B | 09/15/2000 | 1 | INTERSIL | | Y | HCTS30DMSR | 106 |
| 5962R9573501VXC | B | 09/15/2000 | 1 | INTERSIL | | Y | HCTS30KMSR | 106 |
| 5962R9573601V9A | B | 09/22/2000 | 1 | INTERSIL | | Y | HCTS32HMSR | 125 |
| 5962R9573601VCC | B | 09/22/2000 | 1 | INTERSIL | | Y | HCTS32DMSR | 125 |
| 5962R9573601VXC | B | 09/22/2000 | 1 | INTERSIL | | Y | HCTS32KMSR | 125 |
| 5962R9573701V9A | A | 01/28/1998 | | (NONE) | | | HCTS93 (GEN) | 303 |
| 5962R9573701VCC | A | 01/28/1998 | | (NONE) | | | HCTS93 (GEN) | 303 |
| 5962R9573701VXC | A | 01/28/1998 | | (NONE) | | | HCTS93 (GEN) | 303 |
| 5962R9573801V9A | B | 09/22/2000 | | (NONE) | | | HCTS112 (GEN) | 152 |
| 5962R9573801VEC | B | 09/22/2000 | | (NONE) | | | HCTS112 (GEN) | 152 |
| 5962R9573801VXC | B | 09/22/2000 | | (NONE) | | | HCTS112 (GEN) | 152 |
| 5962R9573901V9A | B | 09/22/2000 | | (NONE) | | | HCTS132 (GEN) | 109 |
| 5962R9573901VCC | B | 09/22/2000 | | (NONE) | | | HCTS132 (GEN) | 109 |
| 5962R9573901VXC | B | 09/22/2000 | | (NONE) | | | HCTS132 (GEN) | 109 |
| 5962R9574001V9A | B | 09/22/2000 | 1 | INTERSIL | | Y | HCTS138HMSR | 282 |
| 5962R9574001VEC | B | 09/22/2000 | 1 | INTERSIL | | Y | HCTS138DMSR | 282 |
| 5962R9574001VXC | B | 09/22/2000 | 1 | INTERSIL | | Y | HCTS138KMSR | 282 |
| 5962R9574101V9A | B | 08/22/2000 | | (NONE) | | | HCTS147 (GEN) | 345 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962R9574101VEC | B | 08/22/2000 | | (NONE) | | | HCTS147 (GEN) | 345 |
| 5962R9574101VXC | B | 08/22/2000 | | (NONE) | | | HCTS147 (GEN) | 345 |
| 5962R9574201V9A | C | 04/29/1999 | | (NONE) | | | HCTS160 (GEN) | 300 |
| 5962R9574201TEC | C | 04/29/1999 | | (NONE) | | | HCTS160 (GEN) | 300 |
| 5962R9574201VEC | C | 04/29/1999 | | (NONE) | | | HCTS160 (GEN) | 300 |
| 5962R9574201TXC | C | 04/29/1999 | | (NONE) | | | HCTS160 (GEN) | 300 |
| 5962R9574201VXC | C | 04/29/1999 | | (NONE) | | | HCTS160 (GEN) | 300 |
| 5962R9574301V9A | A | 03/19/1998 | | (NONE) | | | HCTS163 (GEN) | 304 |
| 5962R9574301VEC | A | 03/19/1998 | | (NONE) | | | HCTS163 (GEN) | 304 |
| 5962R9574301VXC | A | 03/19/1998 | | (NONE) | | | HCTS163 (GEN) | 304 |
| 5962R9574401V9A | C | 04/29/1999 | | (NONE) | | | HCTS244 (GEN) | 529 |
| 5962R9574401TRC | C | 04/29/1999 | | (NONE) | | | HCTS244 (GEN) | 529 |
| 5962R9574401VRC | C | 04/29/1999 | 1 | INTERSIL | | Y | HCTS244DMSR | 529 |
| 5962R9574401TXC | C | 04/29/1999 | | (NONE) | | | HCTS244 (GEN) | 529 |
| 5962R9574401VXC | C | 04/29/1999 | 1 | INTERSIL | | Y | HCTS244KMSR | 529 |
| 5962R9574501V9A | D | 03/29/2004 | | (NONE) | | | HCTS245 (GEN) | 590 |
| 5962R9574501TRC | D | 03/29/2004 | | (NONE) | | | HCTS245 (GEN) | 590 |
| 5962R9574501VRC | D | 03/29/2004 | 1 | INTERSIL | | Y | HCTS245DMSR | 590 |
| 5962R9574501TXC | D | 03/29/2004 | | (NONE) | | | HCTS245 (GEN) | 590 |
| 5962R9574501VXC | D | 03/29/2004 | 1 | INTERSIL | | Y | HCTS245KMSR | 590 |
| 5962R9574601V9A | B | 10/05/2000 | | (NONE) | | | HCTS299 (GEN) | 228 |
| 5962R9574601VRC | B | 10/05/2000 | | (NONE) | | | HCTS299 (GEN) | 228 |
| 5962R9574601VXC | B | 10/05/2000 | 1 | INTERSIL | | Y | HCTS299KMSR | 228 |
| 5962R9574701V9A | C | 04/28/1999 | | (NONE) | | | HCTS373 (GEN) | 341 |
| 5962R9574701TRC | C | 04/28/1999 | | (NONE) | | | HCTS373 (GEN) | 341 |
| 5962R9574701VRC | C | 04/28/1999 | | (NONE) | | | HCTS373 (GEN) | 341 |
| 5962R9574701TXC | C | 04/28/1999 | | (NONE) | | | HCTS373 (GEN) | 341 |
| 5962R9574701VXC | C | 04/28/1999 | | (NONE) | | | HCTS373 (GEN) | 341 |
| 5962R9574801V9A | C | 04/29/1999 | | (NONE) | | | HCTS374 (GEN) | 159 |
| 5962R9574801TRC | C | 04/29/1999 | | (NONE) | | | HCTS374 (GEN) | 159 |
| 5962R9574801VRC | C | 04/29/1999 | | (NONE) | | | HCTS374 (GEN) | 159 |
| 5962R9574801TXC | C | 04/29/1999 | | (NONE) | | | HCTS374 (GEN) | 159 |
| 5962R9574801VXC | C | 04/29/1999 | | (NONE) | | | HCTS374 (GEN) | 159 |
| 5962R9574901V9A | B | 10/05/2000 | | (NONE) | | | HCTS390 (GEN) | 300 |
| 5962R9574901VEC | B | 10/05/2000 | | (NONE) | | | HCTS390 (GEN) | 300 |
| 5962R9574901VXC | B | 10/05/2000 | | (NONE) | | | HCTS390 (GEN) | 300 |
| 5962R9575001V9A | B | 10/05/2000 | 1 | INTERSIL | | Y | HCTS393HMSR | 305 |
| 5962R9575001VCC | B | 10/05/2000 | | (NONE) | | | HCTS393 (GEN) | 305 |
| 5962R9575001VXC | B | 10/05/2000 | 1 | INTERSIL | | Y | HCTS393KMSR | 305 |
| 5962R9575101V9A | B | 10/05/2000 | 1 | INTERSIL | | Y | HCTS541HMSR | 529 |
| 5962R9575101VRC | B | 10/05/2000 | 1 | INTERSIL | | Y | HCTS541DMSR | 529 |
| 5962R9575101VXC | B | 10/05/2000 | 1 | INTERSIL | | Y | HCTS541KMSR | 529 |
| 5962R9575201V9A | B | 08/23/2000 | | (NONE) | | | HCTS7266 (GEN) | 141 |
| 5962R9575201VCC | B | 08/23/2000 | | (NONE) | | | HCTS7266 (GEN) | 141 |
| 5962R9575201VXC | B | 08/23/2000 | | (NONE) | | | HCTS7266 (GEN) | 141 |
| 5962R9575301V9A | B | 10/06/2000 | | (NONE) | | | HCTS139 (GEN) | 283 |
| 5962R9575301VEC | B | 10/06/2000 | 1 | INTERSIL | | Y | HCTS139DMSR | 283 |
| 5962R9575301VXC | B | 10/06/2000 | 1 | INTERSIL | | Y | HCTS139KMSR | 283 |
| 5962R9575401V9A | B | 10/06/2000 | | (NONE) | | | HCTS153 (GEN) | 273 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962R9575401VEC | B | 10/06/2000 | | (NONE) | 09/23/2001 | | HCTS153 (GEN) | 273 |
| 5962R9575401VXC | B | 10/06/2000 | 1 | INTERSIL | | Y | HCTS153KMSR | 273 |
| 5962R9575501V9A | B | 10/06/2000 | | (NONE) | 09/23/2001 | | HCTS157 (GEN) | 275 |
| 5962R9575501VEC | B | 10/06/2000 | 1 | INTERSIL | | Y | HCTS157DMSR | 275 |
| 5962R9575501VXC | B | 10/06/2000 | 1 | INTERSIL | | Y | HCTS157KMSR | 275 |
| 5962R9575601V9A | B | 10/06/2000 | | (NONE) | | | HCTS191 (GEN) | 304 |
| 5962R9575601VEC | B | 10/06/2000 | 1 | INTERSIL | | Y | HCTS191DMSR | 304 |
| 5962R9575601VXC | B | 10/06/2000 | 1 | INTERSIL | | Y | HCTS191KMSR | 304 |
| 5962R9575701V9A | B | 10/16/2000 | | (NONE) | 09/23/2001 | | HCTS193 (GEN) | 304 |
| 5962R9575701VEC | B | 10/16/2000 | | (NONE) | 09/23/2001 | | HCTS193 (GEN) | 304 |
| 5962R9575701VXC | B | 10/16/2000 | 1 | INTERSIL | | Y | HCTS193KMSR | 304 |
| 5962R9575801V9A | B | 10/16/2000 | | (NONE) | | | HCTS574 (GEN) | 159 |
| 5962R9575801VRC | B | 10/16/2000 | 1 | INTERSIL | | Y | HCTS574DMSR | 159 |
| 5962R9575801VXC | B | 10/16/2000 | 1 | INTERSIL | | Y | HCTS574KMSR | 159 |
| 5962R9575901V9A | B | 10/16/2000 | | (NONE) | | | HCTS646 (GEN) | 590 |
| 5962R9575901VJC | B | 10/16/2000 | | (NONE) | | | HCTS646 (GEN) | 590 |
| 5962R9575901VXC | B | 10/16/2000 | | (NONE) | | | HCTS646 (GEN) | 590 |
| 5962R9576001V9A | B | 10/16/2000 | | (NONE) | | | HCTS4002 (GEN) | 123 |
| 5962R9576001VCC | B | 10/16/2000 | | (NONE) | 09/23/2001 | | HCTS4002 (GEN) | 123 |
| 5962R9576001VXC | B | 10/16/2000 | | (NONE) | 09/23/2001 | | HCTS4002 (GEN) | 123 |
| 5962-9576101M2A | | 11/08/1995 | 2 | IDT | | Y | IDT49FCT805BTLB | 529 |
| 5962-9576101MRA | | 11/08/1995 | 2 | IDT | | Y | IDT49FCT805BTDB | 529 |
| 5962-9576101MSA | | 11/08/1995 | | (NONE) | 04/29/2002 | | 49FCT805B (GEN) | 529 |
| 5962-9576102M2A | | 11/08/1995 | 2 | IDT | | Y | IDT49FCT805CTLB | 529 |
| 5962-9576102MRA | | 11/08/1995 | 2 | IDT | | Y | IDT49FCT805CTDB | 529 |
| 5962-9576102MSA | | 11/08/1995 | | (NONE) | 04/29/2002 | | IDT49FCT805C (GEN) | 529 |
| 5962-9576201M2A | | 11/08/1995 | 2 | IDT | | Y | IDT49FCT806BTLB | 529 |
| 5962-9576201MRA | | 11/08/1995 | 2 | IDT | | Y | IDT49FCT806BTDB | 529 |
| 5962-9576201MSA | | 11/08/1995 | | (NONE) | 04/29/2002 | | 49FCT806B (GEN) | 529 |
| 5962-9576202M2A | | 11/08/1995 | 2 | IDT | | Y | IDT49FCT806CTLB | 529 |
| 5962-9576202MRA | | 11/08/1995 | 2 | IDT | | Y | IDT49FCT806CTDB | 529 |
| 5962-9576202MSA | | 11/08/1995 | | (NONE) | 04/29/2002 | | 49FCT806C (GEN) | 529 |
| 5962R9576301V9A | D | 06/02/1999 | | (NONE) | | | HCTS74 (GEN) | 158 |
| 5962R9576301TCC | D | 06/02/1999 | | (NONE) | | | HCTS74 (GEN) | 158 |
| 5962R9576301VCC | D | 06/02/1999 | 1 | INTERSIL | | Y | HCTS74DMSR | 158 |
| 5962R9576301TXC | D | 06/02/1999 | | (NONE) | | | HCTS74 (GEN) | 158 |
| 5962R9576301VXC | D | 06/02/1999 | 1 | INTERSIL | | Y | HCTS74KMSR | 158 |
| 5962R9576401V9A | B | 10/16/2000 | | (NONE) | | | HCTS273 (GEN) | 159 |
| 5962R9576401VRC | B | 10/16/2000 | 1 | INTERSIL | | Y | HCTS273DMSR | 159 |
| 5962R9576401VXC | B | 10/16/2000 | 1 | INTERSIL | | Y | HCTS273KMSR | 159 |
| 5962R9576501V9A | B | 10/16/2000 | 1 | INTERSIL | | Y | HCTS10HMSR | 102 |
| 5962R9576501VCC | B | 10/16/2000 | | (NONE) | | | HCTS10 (GEN) | 102 |
| 5962R9576501VXC | B | 10/16/2000 | | (NONE) | | | HCTS10 (GEN) | 102 |
| 5962R9576601V9A | A | 01/28/1998 | | (NONE) | | | HCTS21 (GEN) | 114 |
| 5962R9576601VCC | A | 01/28/1998 | | (NONE) | | | HCTS21 (GEN) | 114 |
| 5962R9576601VXC | A | 01/28/1998 | | (NONE) | | | HCTS21 (GEN) | 114 |
| 5962R9576701V9A | A | 01/28/1998 | | (NONE) | | | HCTS75 (GEN) | 340 |
| 5962R9576701VEC | A | 01/28/1998 | | (NONE) | | | HCTS75 (GEN) | 340 |
| 5962R9576701VXC | A | 01/28/1998 | | (NONE) | | | HCTS75 (GEN) | 340 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962R9576801V9A | B | 10/16/2000 | | (NONE) | | | HCTS85 (GEN) | 209 |
| 5962R9576801VEC | B | 10/16/2000 | 1 | INTERSIL | | Y | HCTS85DMSR | 209 |
| 5962R9576801VXC | B | 10/16/2000 | | (NONE) | 12/28/2003 | | HCTS85 (GEN) | 209 |
| 5962R9576901V9A | C | 04/29/1999 | | (NONE) | | | HCTS109 (GEN) | 152 |
| 5962R9576901TEC | C | 04/29/1999 | | (NONE) | | | HCTS109 (GEN) | 152 |
| 5962R9576901VEC | C | 04/29/1999 | | (NONE) | | | HCTS109 (GEN) | 152 |
| 5962R9576901TXC | C | 04/29/1999 | | (NONE) | | | HCTS109 (GEN) | 152 |
| 5962R9576901VXC | C | 04/29/1999 | | (NONE) | | | HCTS109 (GEN) | 152 |
| 5962R9577001V9A | A | 03/13/1998 | | (NONE) | 09/21/2003 | | HCTS161A (GEN) | 304 |
| 5962R9577001VEC | A | 03/13/1998 | | (NONE) | 09/23/2001 | | HCTS161A (GEN) | 304 |
| 5962R9577001VXC | A | 03/13/1998 | | (NONE) | 09/21/2003 | | HCTS161A (GEN) | 304 |
| 5962R9577101V9A | A | 03/25/1998 | | (NONE) | | | HCTS190 (GEN) | 301 |
| 5962R9577101VEC | A | 03/25/1998 | | (NONE) | | | HCTS190 (GEN) | 301 |
| 5962R9577101VXC | A | 03/25/1998 | | (NONE) | | | HCTS190 (GEN) | 301 |
| 5962R9577201V9A | B | 08/17/2004 | 1 | INTERSIL | | Y | HCTS240AHMSR | 529 |
| 5962R9577201VRC | B | 08/17/2004 | 1 | INTERSIL | | Y | HCTS240ADMSR | 529 |
| 5962R9577201VXC | B | 08/17/2004 | 1 | INTERSIL | | Y | HCTS240AKMSR | 529 |
| 5962R9577401V9A | B | 06/18/2004 | | (NONE) | | | HCTS283 (GEN) | 202 |
| 5962R9577401VEC | B | 06/18/2004 | 1 | INTERSIL | | Y | HCTS283DMSR | 202 |
| 5962R9577401VXC | B | 06/18/2004 | 1 | INTERSIL | | Y | HCTS283KMSR | 202 |
| 5962R9577501V9A | A | 03/27/1998 | | (NONE) | 09/23/2001 | | HCTS365 (GEN) | 522 |
| 5962R9577501VEC | A | 03/27/1998 | | (NONE) | | | HCTS365 (GEN) | 522 |
| 5962R9577501VXC | A | 03/27/1998 | | (NONE) | | | HCTS365 (GEN) | 522 |
| 5962R9577601V9A | B | 08/17/2004 | | (NONE) | | | HCTS540 (GEN) | 590 |
| 5962R9577601VRC | B | 08/17/2004 | | (NONE) | | | HCTS540 (GEN) | 590 |
| 5962R9577601VXC | B | 08/17/2004 | 1 | INTERSIL | | Y | HCTS540KMSR | 590 |
| 5962R9577701V9A | A | 06/12/1998 | | (NONE) | | | HCS10 (GEN) | 102 |
| 5962R9577701VCC | A | 06/12/1998 | | (NONE) | | | HCS10 (GEN) | 102 |
| 5962R9577701VXC | A | 06/12/1998 | | (NONE) | | | HCS10 (GEN) | 102 |
| 5962R9577801V9A | A | 06/12/1998 | | (NONE) | | | HCS20 (GEN) | 104 |
| 5962R9577801VCC | A | 06/12/1998 | | (NONE) | | | HCS20 (GEN) | 104 |
| 5962R9577801VXC | A | 06/12/1998 | | (NONE) | | | HCS20 (GEN) | 104 |
| 5962R9577901V9A | B | 04/05/1999 | | (NONE) | | | HCS21 (GEN) | 114 |
| 5962R9577901VCC | B | 04/05/1999 | | (NONE) | 12/28/2003 | | HCS21 (GEN) | 114 |
| 5962R9577901VXC | B | 04/05/1999 | | (NONE) | 12/28/2003 | | HCS21 (GEN) | 114 |
| 5962R9578001V9A | B | 02/26/2004 | 1 | INTERSIL | | Y | HCS27HMSR | 122 |
| 5962R9578001VCC | B | 02/26/2004 | 1 | INTERSIL | | Y | HCS27DMSR | 122 |
| 5962R9578001VXC | B | 02/26/2004 | 1 | INTERSIL | | Y | HCS27KMSR | 122 |
| 5962R9578101V9A | B | 02/26/2004 | 1 | INTERSIL | | Y | HCS32HMSR | 125 |
| 5962R9578101VCC | B | 02/26/2004 | 1 | INTERSIL | | Y | HCS32DMSR | 125 |
| 5962R9578101VXC | B | 02/26/2004 | 1 | INTERSIL | | Y | HCS32KMSR | 125 |
| 5962R9578201V9A | D | 06/17/1999 | 1 | INTERSIL | | Y | HCS74HMSR | 158 |
| 5962R9578201TCC | D | 06/17/1999 | | (NONE) | | | HCS74 (GEN) | 158 |
| 5962R9578201VCC | D | 06/17/1999 | 1 | INTERSIL | | Y | HCS74DMSR | 158 |
| 5962R9578201TXC | D | 06/17/1999 | | (NONE) | | | HCS74 (GEN) | 158 |
| 5962R9578201VXC | D | 06/17/1999 | 1 | INTERSIL | | Y | HCS74KMSR | 158 |
| 5962R9578301V9A | B | 02/26/2004 | | (NONE) | | | HCS86 (GEN) | 140 |
| 5962R9578301VCC | B | 02/26/2004 | 1 | INTERSIL | | Y | HCS86DMSR | 140 |
| 5962R9578301VXC | B | 02/26/2004 | 1 | INTERSIL | | Y | HCS86KMSR | 140 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962R9578401V9A | B | 02/26/2004 | 1 | INTERSIL | | Y | HCS109HMSR | 152 |
| 5962R9578401VEC | B | 02/26/2004 | 1 | INTERSIL | | Y | HCS109DMSR | 152 |
| 5962R9578401VXC | B | 02/26/2004 | 1 | INTERSIL | | Y | HCS109KMSR | 152 |
| 5962R9578501V9A | B | 03/23/2004 | | (NONE) | | | HCS164 (GEN) | 226 |
| 5962R9578501VCC | B | 03/23/2004 | 1 | INTERSIL | | Y | HCS164DMSR | 226 |
| 5962R9578501VXC | B | 03/23/2004 | | (NONE) | | | HCS164 (GEN) | 226 |
| 5962R9578601V9A | B | 03/23/2004 | | (NONE) | | | HCS165 (GEN) | 225 |
| 5962R9578601VEC | B | 03/23/2004 | 1 | INTERSIL | | Y | HCS165DMSR | 225 |
| 5962R9578601VXC | B | 03/23/2004 | 1 | INTERSIL | | Y | HCS165KMSR | 225 |
| 5962R9578701V9A | B | 02/26/2004 | | (NONE) | | | HCS166 (GEN) | 228 |
| 5962R9578701VEC | B | 02/26/2004 | 1 | INTERSIL | | Y | HCS166DMSR | 228 |
| 5962R9578701VXC | B | 02/26/2004 | 1 | INTERSIL | | Y | HCS166KMSR | 228 |
| 5962R9578801V9A | A | 07/31/1998 | | (NONE) | 06/22/2003 | | HCS193 (GEN) | 304 |
| 5962R9578801VEC | A | 07/31/1998 | | (NONE) | 06/22/2003 | | HCS193 (GEN) | 304 |
| 5962R9578801VXC | A | 07/31/1998 | | (NONE) | 06/22/2003 | | HCS193 (GEN) | 304 |
| 5962R9578901V9A | A | 07/31/1998 | | (NONE) | | | HCS195 (GEN) | 220 |
| 5962R9578901VEC | A | 07/31/1998 | | (NONE) | | | HCS195 (GEN) | 220 |
| 5962R9578901VXC | A | 07/31/1998 | | (NONE) | | | HCS195 (GEN) | 220 |
| 5962R9579001V9A | A | 07/31/1998 | | (NONE) | | | HCS253 (GEN) | 273 |
| 5962R9579001VEC | A | 07/31/1998 | | (NONE) | | | HCS253 (GEN) | 273 |
| 5962R9579001VXC | A | 07/31/1998 | | (NONE) | | | HCS253 (GEN) | 273 |
| 5962R9579101V9A | B | 08/16/1999 | 1 | INTERSIL | | Y | HCS273HMSR | 159 |
| 5962R9579101VRC | B | 08/16/1999 | 1 | INTERSIL | | Y | HCS273DMSR | 159 |
| 5962R9579101VXC | B | 08/16/1999 | 1 | INTERSIL | | Y | HCS273KMSR | 159 |
| 5962R9579201V9A | C | 04/28/1999 | | (NONE) | | | HCS373 (GEN) | 341 |
| 5962R9579201TRC | C | 04/28/1999 | | (NONE) | | | HCS373 (GEN) | 341 |
| 5962R9579201VRC | C | 04/28/1999 | 1 | INTERSIL | | Y | HCS373DMSR | 341 |
| 5962R9579201TXC | C | 04/28/1999 | | (NONE) | | | HCS373 (GEN) | 341 |
| 5962R9579201VXC | C | 04/28/1999 | 1 | INTERSIL | | Y | HCS373KMSR | 341 |
| 5962R9579301V9A | B | 03/29/2004 | 1 | INTERSIL | | Y | HCS374HMSR | 159 |
| 5962R9579301VRC | B | 03/29/2004 | 1 | INTERSIL | | Y | HCS374DMSR | 159 |
| 5962R9579301VXC | B | 03/29/2004 | 1 | INTERSIL | | Y | HCS374KMSR | 159 |
| 5962R9579401V9A | B | 04/15/2004 | | (NONE) | | | HCS573 (GEN) | 341 |
| 5962R9579401VRC | B | 04/15/2004 | | (NONE) | 09/23/2001 | | HCS573 (GEN) | 341 |
| 5962R9579401VXC | B | 04/15/2004 | 1 | INTERSIL | | Y | HCS573KMSR | 341 |
| 5962-9579501HUA | | 12/17/1998 | 1 | ADV. ANALOG | | Y | AFL2805DW/CH | 594 |
| 5962-9579501HUC | | 12/17/1998 | 1 | ADV. ANALOG | | Y | AFL2805DW/CH | 594 |
| 5962-9579501HXA | | 12/17/1998 | 1 | ADV. ANALOG | | Y | AFL2805DX/CH | 594 |
| 5962-9579501HXC | | 12/17/1998 | 1 | ADV. ANALOG | | Y | AFL2805DX/CH | 594 |
| 5962-9579501HYA | | 12/17/1998 | 1 | ADV. ANALOG | | Y | AFL2805DY/CH | 594 |
| 5962-9579501HYC | | 12/17/1998 | 1 | ADV. ANALOG | | Y | AFL2805DY/CH | 594 |
| 5962-9579501HZA | | 12/17/1998 | 1 | ADV. ANALOG | | Y | AFL2805DZ/CH | 594 |
| 5962-9579501HZC | | 12/17/1998 | 1 | ADV. ANALOG | | Y | AFL2805DZ/CH | 594 |
| 5962-9579601HUA | | 12/17/1998 | 1 | ADV. ANALOG | | Y | AFL2812DW/CH | 594 |
| 5962-9579601HUC | | 12/17/1998 | 1 | ADV. ANALOG | | Y | AFL2812DW/CH | 594 |
| 5962-9579601HXA | | 12/17/1998 | 1 | ADV. ANALOG | | Y | AFL2812DX/CH | 594 |
| 5962-9579601HXC | | 12/17/1998 | 1 | ADV. ANALOG | | Y | AFL2812DX/CH | 594 |
| 5962-9579601HYA | | 12/17/1998 | 1 | ADV. ANALOG | | Y | AFL2812DY/CH | 594 |
| 5962-9579601HYC | | 12/17/1998 | 1 | ADV. ANALOG | | Y | AFL2812DY/CH | 594 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9579601HZA | | 12/17/1998 | 1 | ADV. ANALOG | | Y | AFL2812DZ/CH | 594 |
| 5962-9579601HZC | | 12/17/1998 | 1 | ADV. ANALOG | | Y | AFL2812DZ/CH | 594 |
| 5962-9579801M2A | A | 05/25/2000 | 2 | TI | | Y | UC1705L/883BC | 539 |
| 5962-9579801MPA | A | 05/25/2000 | 2 | TI | | Y | UC1705J/883BC | 539 |
| 5962-9579801VPA | A | 05/25/2000 | 2 | TI | | Y | UC1705JQMLV | 539 |
| 5962-9579901HXA | A | 04/04/1997 | | (NONE) | 09/01/2000 | | SP9462 (GEN) | 433 |
| 5962-9579902HXA | A | 04/04/1997 | | (NONE) | 09/01/2000 | | SP9463 (GEN) | 433 |
| 5962-9579903HXA | A | 04/04/1997 | | (NONE) | 09/01/2000 | | SP9472 (GEN) | 433 |
| 5962-9579904HXA | A | 04/04/1997 | | (NONE) | 09/01/2000 | | SP9473 (GEN) | 433 |
| 5962R9580101V9A | B | 05/07/2004 | | (NONE) | | | HCS05 (GEN) | 144 |
| 5962R9580101VCC | B | 05/07/2004 | | (NONE) | | | HCS05 (GEN) | 144 |
| 5962R9580101VXC | B | 05/07/2004 | 1 | INTERSIL | | Y | HCS05KMSR | 144 |
| 5962R9580201V9A | A | 07/14/1998 | | (NONE) | | | HCS112 (GEN) | 156 |
| 5962R9580201VEC | A | 07/14/1998 | | (NONE) | | | HCS112 (GEN) | 156 |
| 5962R9580201VXC | A | 07/14/1998 | | (NONE) | | | HCS112 (GEN) | 156 |
| 5962R9580301V9A | A | 07/14/1998 | | (NONE) | | | HCS125 (GEN) | 520 |
| 5962R9580301VCC | A | 07/14/1998 | | (NONE) | | | HCS125 (GEN) | 520 |
| 5962R9580301VXC | A | 07/14/1998 | | (NONE) | 09/23/2001 | | HCS125 (GEN) | 520 |
| 5962R9580401V9A | A | 07/14/1998 | | (NONE) | | | HCS139 (GEN) | 283 |
| 5962R9580401VEC | A | 07/14/1998 | 1 | INTERSIL | | Y | HCS139DMSR | 283 |
| 5962R9580401VXC | A | 07/14/1998 | 1 | INTERSIL | | Y | HCS139KMSR | 283 |
| 5962R9580501V9A | B | 02/26/2004 | | (NONE) | | | HCS157 (GEN) | 275 |
| 5962R9580501VEC | B | 02/26/2004 | 1 | INTERSIL | | Y | HCS157DMSR | 275 |
| 5962R9580501VXC | B | 02/26/2004 | 1 | INTERSIL | | Y | HCS157KMSR | 275 |
| 5962R9580601V9A | A | 07/14/1998 | | (NONE) | | | HCS160 (GEN) | 301 |
| 5962R9580601VEC | A | 07/14/1998 | | (NONE) | 10/04/2002 | | HCS160 (GEN) | 301 |
| 5962R9580601VXC | A | 07/14/1998 | | (NONE) | 10/04/2002 | | HCS160 (GEN) | 301 |
| 5962R9580701V9A | B | 03/23/2004 | | (NONE) | | | HCS163 (GEN) | 304 |
| 5962R9580701VEC | B | 03/23/2004 | 1 | INTERSIL | | Y | HCS163DMSR | 304 |
| 5962R9580701VXC | B | 03/23/2004 | 1 | INTERSIL | | Y | HCS163KMSR | 304 |
| 5962R9580801V9A | A | 07/31/1998 | | (NONE) | | | HCS190 (GEN) | 301 |
| 5962R9580801VEC | A | 07/31/1998 | | (NONE) | | | HCS190 (GEN) | 301 |
| 5962R9580801VXC | A | 07/31/1998 | | (NONE) | | | HCS190 (GEN) | 301 |
| 5962R9580901V9A | B | 04/15/2004 | | (NONE) | | | HCS240 (GEN) | 529 |
| 5962R9580901VRC | B | 04/15/2004 | 1 | INTERSIL | | Y | HCS240DMSR | 529 |
| 5962R9580901VXC | B | 04/15/2004 | 1 | INTERSIL | | Y | HCS240KMSR | 529 |
| 5962R9581001V9A | A | 07/31/1998 | | (NONE) | | | HCS241 (GEN) | 529 |
| 5962R9581001VRC | A | 07/31/1998 | | (NONE) | | | HCS241 (GEN) | 529 |
| 5962R9581001VXC | A | 07/31/1998 | | (NONE) | | | HCS241 (GEN) | 529 |
| 5962R9581101V9A | A | 07/31/1998 | | (NONE) | | | HCS283 (GEN) | 202 |
| 5962R9581101VEC | A | 07/31/1998 | | (NONE) | | | HCS283 (GEN) | 202 |
| 5962R9581101VXC | A | 07/31/1998 | | (NONE) | | | HCS283 (GEN) | 202 |
| 5962R9581201V9A | A | 12/21/1997 | 1 | INTERSIL | | Y | HS0-302RH-Q | 188 |
| 5962R9581201QCC | A | 12/21/1997 | 1 | INTERSIL | | Y | HS1-302RH-8 | 188 |
| 5962R9581201TCC | A | 12/21/1997 | | (NONE) | 03/23/2003 | | HS-302 (GEN) | 188 |
| 5962R9581201VCC | A | 12/21/1997 | 1 | INTERSIL | | Y | HS1-302RH-Q | 188 |
| 5962R9581201QXC | A | 12/21/1997 | 1 | INTERSIL | | Y | HS9-302RH-8 | 188 |
| 5962R9581201TXC | A | 12/21/1997 | | (NONE) | 03/23/2003 | | HS-302 (GEN) | 188 |
| 5962R9581201VXC | A | 12/21/1997 | 1 | INTERSIL | | Y | HS9-302RH-Q | 188 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962R9581202VCA | A | 12/21/1997 | | (NONE) | | | HS306RH (GEN) | 188 |
| 5962R9581202VXA | A | 12/21/1997 | | (NONE) | | | HS306RH (GEN) | 188 |
| 5962R9581203VEA | A | 12/21/1997 | | (NONE) | | | HS384RH (GEN) | 188 |
| 5962R9581203VYA | A | 12/21/1997 | | (NONE) | | | HS384RH (GEN) | 188 |
| 5962R9581301V9A | C | 01/07/2003 | 1 | INTERSIL | | Y | HS0-303RH-Q | 186 |
| 5962R9581301QCC | C | 01/07/2003 | 1 | INTERSIL | | Y | HS1-303RH-8 | 186 |
| 5962R9581301TCC | C | 01/07/2003 | | (NONE) | 03/23/2003 | | HS-303 (GEN) | 186 |
| 5962R9581301VCC | C | 01/07/2003 | 1 | INTERSIL | | Y | HS1-303RH-Q | 186 |
| 5962R9581301QXC | C | 01/07/2003 | 1 | INTERSIL | | Y | HS9-303RH-8 | 186 |
| 5962R9581301TXC | C | 01/07/2003 | | (NONE) | 03/23/2003 | | HS-303 (GEN) | 186 |
| 5962R9581301VXC | C | 01/07/2003 | 1 | INTERSIL | | Y | HS9-303RH-Q | 186 |
| 5962R9581302V9A | C | 01/07/2003 | 1 | INTERSIL | | Y | HS0-307RH-Q | 186 |
| 5962R9581302QCC | C | 01/07/2003 | | (NONE) | 03/23/2003 | | HS-307 (GEN) | 186 |
| 5962R9581302VCC | C | 01/07/2003 | | (NONE) | 03/23/2003 | | HS-307 (GEN) | 186 |
| 5962R9581302QXC | C | 01/07/2003 | | (NONE) | 03/23/2003 | | HS-307 (GEN) | 186 |
| 5962R9581302VXC | C | 01/07/2003 | | (NONE) | 03/23/2003 | | HS-307 (GEN) | 186 |
| 5962R9581303V9A | C | 01/07/2003 | 1 | INTERSIL | | Y | HS0-390RH-Q | 186 |
| 5962R9581303QEC | C | 01/07/2003 | 1 | INTERSIL | | Y | HS1-390RH-8 | 186 |
| 5962R9581303TEC | C | 01/07/2003 | | (NONE) | 03/23/2003 | | HS-390 (GEN) | 186 |
| 5962R9581303VEC | C | 01/07/2003 | 1 | INTERSIL | | Y | HS1-390RH-Q | 186 |
| 5962R9581303QYC | C | 01/07/2003 | 1 | INTERSIL | | Y | HS9-390RH-8 | 186 |
| 5962R9581303TYC | C | 01/07/2003 | 1 | INTERSIL | | Y | HS9-390RH-T | 186 |
| 5962R9581303VYC | C | 01/07/2003 | 1 | INTERSIL | | Y | HS9-390RH-Q | 186 |
| 5962R9581401V9A | A | 02/06/1998 | | (NONE) | | | HCTS86 (GEN) | 140 |
| 5962R9581401VCC | A | 02/06/1998 | | (NONE) | 12/28/2003 | | HCTS86 (GEN) | 140 |
| 5962R9581401VXC | A | 02/06/1998 | | (NONE) | 12/28/2003 | | HCTS86 (GEN) | 140 |
| 5962-9581501HXA | A | 06/11/2002 | 1 | ANALOG (6) | | Y | AD10242TZ/883B | 592 |
| 5962-9581601QXA | | 10/20/1995 | 1 | NATIONAL | | Y | 54ACTQ16646FMQB | 590 |
| 5962-9581701VXC | A | 02/01/1996 | 1 | INTERSIL | | Y | MD85C52/7 | 421 |
| 5962R9581801V9A | A | 02/10/1998 | | (NONE) | | | HS-82C12 (GEN) | 421 |
| 5962R9581801QJC | A | 02/10/1998 | | (NONE) | | | HS-82C12 (GEN) | 421 |
| 5962R9581801VJC | A | 02/10/1998 | | (NONE) | | | HS-82C12 (GEN) | 421 |
| 5962R9581801QXC | A | 02/10/1998 | | (NONE) | | | HS-82C12 (GEN) | 421 |
| 5962R9581801VXC | A | 02/10/1998 | | (NONE) | | | HS-82C12 (GEN) | 421 |
| 5962R9581901QQC | A | 11/13/1996 | 1 | INTERSIL | | Y | HS1-82C55ARH-8 | 421 |
| 5962R9581901VQC | A | 11/13/1996 | 1 | INTERSIL | | Y | HS1-82C55ARH-Q | 421 |
| 5962R9582001QJC | | 01/05/1996 | 0 | INTERSIL | | Y | HS1-82C85RH-8 | 422 |
| 5962R9582001VJC | | 01/05/1996 | 0 | INTERSIL | | Y | HS1-82C85RH-Q | 422 |
| 5962R9582001QXC | | 01/05/1996 | 0 | INTERSIL | | Y | HS9-82C85RH-8 | 422 |
| 5962R9582001VXC | | 01/05/1996 | 0 | INTERSIL | | Y | HS9-82C85RH-Q | 422 |
| 5962R9582101QQC | | 01/10/1996 | | (NONE) | | | HS-82C37A (GEN) | 423 |
| 5962R9582101VQC | | 01/10/1996 | | (NONE) | | | HS-82C37A (GEN) | 423 |
| 5962R9582101QXC | | 01/10/1996 | | (NONE) | 09/23/2001 | | HS-82C37A (GEN) | 423 |
| 5962R9582101VXC | | 01/10/1996 | | (NONE) | 09/23/2001 | | HS-82C37A (GEN) | 423 |
| 5962F9582201VXC | A | 10/02/1998 | | (NONE) | 03/23/2003 | | HS-65643A (GEN) | 603 |
| 5962F9582301QXC | A | 09/18/1997 | | (NONE) | 03/23/2003 | | HS-65647 (GEN) | 616 |
| 5962F9582301VXC | A | 09/18/1997 | | (NONE) | 03/23/2003 | | HS-65647 (GEN) | 616 |
| 5962F9582301QYC | A | 09/18/1997 | | (NONE) | 03/23/2003 | | HS-65647 (GEN) | 616 |
| 5962F9582301VYC | A | 09/18/1997 | | (NONE) | 03/23/2003 | | HS-65647 (GEN) | 616 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962R9582401QQC | | 01/10/1996 | | (NONE) | | | HS-80C85RH (GEN) | 402 |
| 5962R9582401VQC | | 01/10/1996 | | (NONE) | | | HS-80C85 (GEN) | 402 |
| 5962R9582401QXC | | 01/10/1996 | | (NONE) | | | HS-80C85 (GEN) | 402 |
| 5962R9582401VXC | | 01/10/1996 | | (NONE) | | | HS-80C85 (GEN) | 402 |
| 5962R9582501V9A | A | 02/10/1998 | | (NONE) | | | HS-54C138 (GEN) | 282 |
| 5962R9582501QEC | A | 02/10/1998 | | (NONE) | | | 54C138 (GEN) | 282 |
| 5962R9582501VEC | A | 02/10/1998 | | (NONE) | | | HS-54C138 (GEN) | 282 |
| 5962R9582501QXC | A | 02/10/1998 | | (NONE) | | | HS-54C138 (GEN) | 282 |
| 5962R9582501VXC | A | 02/10/1998 | | (NONE) | | | HS-54C138 (GEN) | 282 |
| 5962R9582601V9A | C | 11/18/2003 | | (NONE) | | | 4000B (GEN) | 124 |
| 5962R9582601VCC | C | 11/18/2003 | | (NONE) | | | 4000B (GEN) | 124 |
| 5962R9582601VXC | C | 11/18/2003 | | (NONE) | | | 4000B (GEN) | 124 |
| 5962R9582602V9A | C | 11/18/2003 | 1 | INTERSIL | | Y | CD4001BHSR | 120 |
| 5962R9582602VCC | C | 11/18/2003 | 1 | INTERSIL | | Y | CD4001BDMSR | 120 |
| 5962R9582602VXC | C | 11/18/2003 | 1 | INTERSIL | | Y | CD4001BKMSR | 120 |
| 5962R9582603V9A | C | 11/18/2003 | | (NONE) | | | 4002B (GEN) | 124 |
| 5962R9582603VCC | C | 11/18/2003 | | (NONE) | | | 4002B (GEN) | 124 |
| 5962R9582603VXC | C | 11/18/2003 | | (NONE) | | | 4002B (GEN) | 124 |
| 5962R9582604V9A | C | 11/18/2003 | | (NONE) | | | 4025B (GEN) | 122 |
| 5962R9582604VCC | C | 11/18/2003 | 1 | INTERSIL | | Y | CD4025BDMSR | 122 |
| 5962R9582604VXC | C | 11/18/2003 | 1 | INTERSIL | | Y | CD4025BKMSR | 122 |
| 5962R9582605V9A | C | 11/18/2003 | | (NONE) | | | 4001BN (GEN) | 120 |
| 5962R9582605VCC | C | 11/18/2003 | | (NONE) | | | 4001BN (GEN) | 120 |
| 5962R9582605VXC | C | 11/18/2003 | 1 | INTERSIL | | Y | CD4001BKNSR | 120 |
| 5962R9582606V9A | C | 11/18/2003 | | (NONE) | | | 4002BN (GEN) | 124 |
| 5962R9582606VCC | C | 11/18/2003 | | (NONE) | | | 4002BN (GEN) | 124 |
| 5962R9582606VXC | C | 11/18/2003 | | (NONE) | | | 4002BN (GEN) | 124 |
| 5962R9582607VCC | C | 11/18/2003 | | (NONE) | | | 4025BN (GEN) | 122 |
| 5962R9582607VXC | C | 11/18/2003 | | (NONE) | | | 4025BN (GEN) | 122 |
| 5962R9582901V9A | B | 07/24/1997 | | (NONE) | | | 4010B (GEN) | 540 |
| 5962R9582901VEC | B | 07/24/1997 | | (NONE) | | | 4010B (GEN) | 540 |
| 5962R9582901VXC | B | 07/24/1997 | | (NONE) | | | 4010B (GEN) | 540 |
| 5962-9583101Q2A | C | 06/25/1998 | 3 | TI | | Y | SNJ54LVTH573FK | 341 |
| 5962-9583101QRA | C | 06/25/1998 | 3 | TI | | Y | SNJ54LVTH573J | 341 |
| 5962-9583101QSA | C | 06/25/1998 | 3 | TI | | Y | SNJ54LVTH573W | 341 |
| 5962-9583201Q2A | C | 08/19/2003 | 2 | TI | | Y | SNJ54LVTH574AFK | 159 |
| 5962-9583201QRA | C | 08/19/2003 | 2 | TI | | Y | SNJ54LVTH574AJ | 159 |
| 5962-9583201VRA | C | 08/19/2003 | 2 | TI | | Y | SNV54LVTH574AJ | 159 |
| 5962-9583201QSA | C | 08/19/2003 | 2 | TI | | Y | SNJ54LVTH574AW | 159 |
| 5962-9583201VSA | C | 08/19/2003 | 2 | TI | | Y | SNV54LVTH574AW | 159 |
| 5962-9583301Q2A | L | 07/28/2003 | 2 | NATIONAL | | Y | DS90C031E-QML | 569 |
| 5962-9583301QFA | L | 07/28/2003 | 2 | NATIONAL | | Y | DS90C031W-QML | 569 |
| 5962-9583301VFA | L | 07/28/2003 | 2 | NATIONAL | | Y | DS90C031W-QMLV | 569 |
| 5962R9583301VFA | L | 07/28/2003 | 2 | NATIONAL | | Y | DS90C031WRQMLV | 569 |
| 5962-9583301QZA | L | 07/28/2003 | 2 | NATIONAL | | Y | DS90C031WG-QML | 569 |
| 5962-9583301VZA | L | 07/28/2003 | 2 | NATIONAL | | Y | DS90C031WG-QMLV | 569 |
| 5962R9583301VZA | L | 07/28/2003 | 2 | NATIONAL | | Y | DS90C031WGRQMLV | 569 |
| 5962H9583302QXA | L | 07/28/2003 | 1 | UTMC | | Y | UT54LVDS031UCA | 569 |
| 5962H9583302QXC | L | 07/28/2003 | 1 | UTMC | | Y | UT54LVDS031UCC | 569 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962H9583302VXA | L | 07/28/2003 | 1 | UTMC | | Y | UT54LVDS031UCA | 569 |
| 5962H9583302VXC | L | 07/28/2003 | 1 | UTMC | | Y | UT54LVDS031UCC | 569 |
| 5962F9583303QXA | L | 07/28/2003 | 1 | UTMC | | Y | UT54LVDSC031UCA | 569 |
| 5962F9583303QXC | L | 07/28/2003 | 1 | UTMC | | Y | UT54LVDSC031UCC | 569 |
| 5962F9583303VXA | L | 07/28/2003 | 1 | UTMC | | Y | UT54LVDSC031UCA | 569 |
| 5962F9583303VXC | L | 07/28/2003 | 1 | UTMC | | Y | UT54LVDSC031UCC | 569 |
| 5962-9583401Q2A | H | 04/19/2004 | 2 | NATIONAL | | Y | DS90C032E-QML | 575 |
| 5962-9583401QFA | H | 04/19/2004 | 2 | NATIONAL | | Y | DS90C032W-QML | 575 |
| 5962-9583401VFA | H | 04/19/2004 | 2 | NATIONAL | | Y | DS90C032W-QMLV | 575 |
| 5962L9583401VFA | H | 04/19/2004 | 2 | NATIONAL | | Y | DS90C032WLQMLV | 575 |
| 5962-9583401QZA | H | 04/19/2004 | 2 | NATIONAL | | Y | DS90C032WG-QMLV | 575 |
| 5962-9583401VZA | H | 04/19/2004 | 2 | NATIONAL | | Y | DS90C032WG-QMLV | 575 |
| 5962L9583401VZA | H | 04/19/2004 | 2 | NATIONAL | | Y | DS90C032WGLQMLV | 575 |
| 5962H9583402Q9A | H | 04/19/2004 | 1 | UTMC | | Y | UT54LVDS032-QDIE | 575 |
| 5962H9583402V9A | H | 04/19/2004 | 1 | UTMC | | Y | UT54LVDS032-VDIE | 575 |
| 5962H9583402QXA | H | 04/19/2004 | 1 | UTMC | | Y | UT54LVDS032UCA | 575 |
| 5962H9583402QXC | H | 04/19/2004 | 1 | UTMC | | Y | UT54LVDS032UCC | 575 |
| 5962H9583402VXA | H | 04/19/2004 | 1 | UTMC | | Y | UT54LVDS032UCA | 575 |
| 5962H9583402VXC | H | 04/19/2004 | 1 | UTMC | | Y | UT54LVDS032UCC | 575 |
| 5962F9583403Q9A | H | 04/19/2004 | 1 | UTMC | | Y | UT54LVDS032-QDIE | 575 |
| 5962F9583403V9A | H | 04/19/2004 | 1 | UTMC | | Y | UT54LVDS032-VDIE | 575 |
| 5962F9583403QXA | H | 04/19/2004 | 1 | UTMC | | Y | UT54LVDSC032UCA | 575 |
| 5962F9583403QXC | H | 04/19/2004 | 1 | UTMC | | Y | UT54LVDSC032UCC | 575 |
| 5962F9583403VXA | H | 04/19/2004 | 1 | UTMC | | Y | UT54LVDSC032UCA | 575 |
| 5962F9583403VXC | H | 04/19/2004 | 1 | UTMC | | Y | UT54LVDSC032UCC | 575 |
| 5962-9583501Q2A | | 10/12/1995 | 3 | TI | | Y | SNJ54BCT573FK | 341 |
| 5962-9583501QRA | | 10/12/1995 | 3 | TI | | Y | SNJ54BCT573J | 341 |
| 5962-9583501QSA | | 10/12/1995 | 3 | TI | | Y | SNJ54BCT573W | 341 |
| 5962-9583601Q2A | | 10/12/1995 | 3 | TI | | Y | SNJ54BCT574FK | 159 |
| 5962-9583601QRA | | 10/12/1995 | 3 | TI | | Y | SNJ54BCT574J | 159 |
| 5962-9583601QSA | | 10/12/1995 | 3 | TI | | Y | SNJ54BCT574W | 159 |
| 5962-9583701QXA | | 11/22/1995 | | (NONE) | 12/24/1997 | | 80486DX (GEN) | 404 |
| 5962-9583701QYA | | 11/22/1995 | | (NONE) | 12/24/1997 | | 80486DX (GEN) | 404 |
| 5962-9583702QXA | | 11/22/1995 | | (NONE) | 12/24/1997 | | 80486DX (GEN) | 404 |
| 5962-9583702QYA | | 11/22/1995 | | (NONE) | 12/24/1997 | | 80486DX (GEN) | 404 |
| 5962-9583703NXA | | 11/22/1995 | | (NONE) | 12/24/1997 | | 80486DX (GEN) | 404 |
| 5962-9583703NYA | | 11/22/1995 | | (NONE) | 12/24/1997 | | 80486DX (GEN) | 404 |
| 5962-9583704NXA | | 11/22/1995 | | (NONE) | 12/24/1997 | | 80486DX (GEN) | 404 |
| 5962-9583704NYA | | 11/22/1995 | | (NONE) | 12/24/1997 | | 80486DX (GEN) | 404 |
| 5962-9583705NXA | | 11/22/1995 | | (NONE) | 12/24/1997 | | 80486DX (GEN) | 404 |
| 5962-9583705NYA | | 11/22/1995 | | (NONE) | 12/24/1997 | | 80486DX (GEN) | 404 |
| 5962-9583706NXA | | 11/22/1995 | | (NONE) | 12/24/1997 | | 80486DX (GEN) | 404 |
| 5962-9583706NYA | | 11/22/1995 | | (NONE) | 12/24/1997 | | 80486DX (GEN) | 404 |
| 5962-9583801Q2A | | 10/04/1995 | | (NONE) | 08/15/1999 | | TLV2217-33 (GEN) | 782 |
| 5962-9583801QCA | | 10/04/1995 | | (NONE) | 08/15/1999 | | TLV2217-33 (GEN) | 782 |
| 5962-9583901Q2A | B | 11/05/1996 | | (NONE) | 08/15/1999 | | TL751M05 (GEN) | 782 |
| 5962-9583901QPA | B | 11/05/1996 | | (NONE) | 08/15/1999 | | TL751M05 (GEN) | 782 |
| 5962-9584001Q2A | A | 08/21/1996 | | (NONE) | 08/15/1999 | | TL751M12 (GEN) | 782 |
| 5962-9584001QPA | A | 08/21/1996 | | (NONE) | 08/15/1999 | | TL751M12 (GEN) | 782 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9584101QXA | | 01/27/1996 | 2 | TI | | Y | SNJ54ABT16652WD | 590 |
| 5962-9584201QXA | | 01/26/1996 | 2 | TI | | Y | SNJ54ABT16823WD | 164 |
| 5962-9584301Q2A | | 11/02/1995 | 3 | TI | | Y | SNJ54ABT533FK | 341 |
| 5962-9584301QRA | | 11/02/1995 | 3 | TI | | Y | SNJ54ABT533J | 341 |
| 5962-9584301QSA | | 11/02/1995 | 3 | TI | | Y | SNJ54ABT533W | 341 |
| 5962-9584401Q2A | F | 07/14/2003 | 2 | TI | | Y | SNJ54LVTH244AFK | 529 |
| 5962-9584401QRA | F | 07/14/2003 | 2 | TI | | Y | SNJ54LVTH244AJ | 529 |
| 5962-9584401VRA | F | 07/14/2003 | 2 | TI | | Y | SNV54LVTH244AJ | 529 |
| 5962-9584401QSA | F | 07/14/2003 | 2 | TI | | Y | SNJ54LVTH244AW | 529 |
| 5962-9584401VSA | F | 07/14/2003 | 2 | TI | | Y | SNV54LVTH244AW | 529 |
| 5962F9584501QXC | C | 04/08/2002 | 2 | HONEYWELL (1) | | Y | HX6256/RQFC | 623 |
| 5962F9584501VXC | C | 04/08/2002 | 2 | HONEYWELL (1) | | Y | HX6256/RVFC | 623 |
| 5962H9584501QXC | C | 04/08/2002 | 2 | HONEYWELL (1) | | Y | HX6256/RQHC | 623 |
| 5962H9584501VXC | C | 04/08/2002 | 2 | HONEYWELL (1) | | Y | HX6256/RVHC | 623 |
| 5962R9584501QXC | C | 04/08/2002 | 2 | HONEYWELL (1) | | Y | HX6256/RQRC | 623 |
| 5962R9584501VXC | C | 04/08/2002 | 2 | HONEYWELL (1) | | Y | HX6256/RVRC | 623 |
| 5962F9584501QYC | C | 04/08/2002 | 2 | HONEYWELL (1) | | Y | HX6256/NQFC | 623 |
| 5962F9584501VYC | C | 04/08/2002 | 2 | HONEYWELL (1) | | Y | HX6256/NVFC | 623 |
| 5962H9584501QYC | C | 04/08/2002 | 2 | HONEYWELL (1) | | Y | HX6256/NQHC | 623 |
| 5962H9584501VYC | C | 04/08/2002 | 2 | HONEYWELL (1) | | Y | HX6256/NVHC | 623 |
| 5962R9584501QYC | C | 04/08/2002 | 2 | HONEYWELL (1) | | Y | HX6256/NQRC | 623 |
| 5962R9584501VYC | C | 04/08/2002 | 2 | HONEYWELL (1) | | Y | HX6256/NVRC | 623 |
| 5962F9584501QZC | C | 04/08/2002 | 2 | HONEYWELL (1) | | Y | HX6256/XQFC | 623 |
| 5962F9584501VZC | C | 04/08/2002 | 2 | HONEYWELL (1) | | Y | HX6256/XVFC | 623 |
| 5962H9584501QZC | C | 04/08/2002 | 2 | HONEYWELL (1) | | Y | HX6256/XQHC | 623 |
| 5962H9584501VZC | C | 04/08/2002 | 2 | HONEYWELL (1) | | Y | HX6256/XVHC | 623 |
| 5962R9584501QZC | C | 04/08/2002 | 2 | HONEYWELL (1) | | Y | HX6256/XQRC | 623 |
| 5962R9584501VZC | C | 04/08/2002 | 2 | HONEYWELL (1) | | Y | HX6256/XVRC | 623 |
| 5962F9584502QUC | C | 04/08/2002 | 2 | HONEYWELL (1) | | Y | HX6256/PQFT | 623 |
| 5962F9584502VUC | C | 04/08/2002 | 2 | HONEYWELL (1) | | Y | HX6256/PVFT | 623 |
| 5962H9584502QUC | C | 04/08/2002 | 2 | HONEYWELL (1) | | Y | HX6256/PQHT | 623 |
| 5962H9584502VUC | C | 04/08/2002 | 2 | HONEYWELL (1) | | Y | HX6256/PVHT | 623 |
| 5962R9584502QUC | C | 04/08/2002 | 2 | HONEYWELL (1) | | Y | HX6256/PQRT | 623 |
| 5962R9584502VUC | C | 04/08/2002 | 2 | HONEYWELL (1) | | Y | HX6256/PVRT | 623 |
| 5962F9584502QXC | C | 04/08/2002 | 2 | HONEYWELL (1) | | Y | HX6256/RQFT | 623 |
| 5962F9584502VXC | C | 04/08/2002 | 2 | HONEYWELL (1) | | Y | HX6256/RVFT | 623 |
| 5962H9584502QXC | C | 04/08/2002 | 2 | HONEYWELL (1) | | Y | HX6256/RQHT | 623 |
| 5962H9584502VXC | C | 04/08/2002 | 2 | HONEYWELL (1) | | Y | HX6256/RVHT | 623 |
| 5962R9584502QXC | C | 04/08/2002 | 2 | HONEYWELL (1) | | Y | HX6256/RQRT | 623 |
| 5962R9584502VXC | C | 04/08/2002 | 2 | HONEYWELL (1) | | Y | HX6256/RVRT | 623 |
| 5962F9584502QYC | C | 04/08/2002 | 2 | HONEYWELL (1) | | Y | HX6256/NQFT | 623 |
| 5962F9584502VYC | C | 04/08/2002 | 2 | HONEYWELL (1) | | Y | HX6256/NVFT | 623 |
| 5962H9584502QYC | C | 04/08/2002 | 2 | HONEYWELL (1) | | Y | HX6256/NQHT | 623 |
| 5962H9584502VYC | C | 04/08/2002 | 2 | HONEYWELL (1) | | Y | HX6256/NVHT | 623 |
| 5962R9584502QYC | C | 04/08/2002 | 2 | HONEYWELL (1) | | Y | HX6256/NQRT | 623 |
| 5962R9584502VYC | C | 04/08/2002 | 2 | HONEYWELL (1) | | Y | HX6256/NVRT | 623 |
| 5962F9584502QZC | C | 04/08/2002 | | (NONE) | | | 6256 (GEN) | 623 |
| 5962F9584502VZC | C | 04/08/2002 | | (NONE) | | | 6256 (GEN) | 623 |
| 5962H9584502QZC | C | 04/08/2002 | 2 | HONEYWELL (1) | | Y | HX6256/XQHT | 623 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962H9584502VZC | C | 04/08/2002 | 2 | HONEYWELL (1) | | Y | HX6256/XVHT | 623 |
| 5962R9584502QZC | C | 04/08/2002 | | (NONE) | | | 6256 (GEN) | 623 |
| 5962R9584502VZC | C | 04/08/2002 | | (NONE) | | | 6256 (GEN) | 623 |
| 5962F9584503QZC | C | 04/08/2002 | 2 | HONEYWELL (1) | | Y | HX6356/XQFC | 623 |
| 5962F9584503VZC | C | 04/08/2002 | 2 | HONEYWELL (1) | | Y | HX6356/XVFC | 623 |
| 5962H9584503QZC | C | 04/08/2002 | 2 | HONEYWELL (1) | | Y | HX6356/XQHC | 623 |
| 5962H9584503VZC | C | 04/08/2002 | 2 | HONEYWELL (1) | | Y | HX6356/XVHC | 623 |
| 5962R9584503QZC | C | 04/08/2002 | 2 | HONEYWELL (1) | | Y | HX6356/XQRC | 623 |
| 5962R9584503VZC | C | 04/08/2002 | 2 | HONEYWELL (1) | | Y | HX6356/XVRC | 623 |
| 5962F9584504QUC | C | 04/08/2002 | 2 | HONEYWELL (1) | | Y | HX6356/PQFT | 623 |
| 5962F9584504VUC | C | 04/08/2002 | 2 | HONEYWELL (1) | | Y | HX6356/PVFT | 623 |
| 5962H9584504QUC | C | 04/08/2002 | 2 | HONEYWELL (1) | | Y | HX6356/PQHT | 623 |
| 5962H9584504VUC | C | 04/08/2002 | 2 | HONEYWELL (1) | | Y | HX6356/PVHT | 623 |
| 5962R9584504QUC | C | 04/08/2002 | 2 | HONEYWELL (1) | | Y | HX6356/PQRT | 623 |
| 5962R9584504VUC | C | 04/08/2002 | 2 | HONEYWELL (1) | | Y | HX6356/PVRT | 623 |
| 5962F9584504QZC | C | 04/08/2002 | | (NONE) | | | 6356 (GEN) | 623 |
| 5962F9584504VZC | C | 04/08/2002 | | (NONE) | | | 6356 (GEN) | 623 |
| 5962H9584504QZC | C | 04/08/2002 | | (NONE) | | | 6356 (GEN) | 623 |
| 5962H9584504VZC | C | 04/08/2002 | | (NONE) | | | 6356 (GEN) | 623 |
| 5962R9584504QZC | C | 04/08/2002 | | (NONE) | | | 6356 (GEN) | 623 |
| 5962R9584504VZC | C | 04/08/2002 | | (NONE) | | | 6356 (GEN) | 623 |
| 5962F9584505QXC | C | 04/08/2002 | | (NONE) | | | 6256 (GEN) | 623 |
| 5962F9584505VXC | C | 04/08/2002 | | (NONE) | | | 6256 (GEN) | 623 |
| 5962H9584505QXC | C | 04/08/2002 | | (NONE) | | | 6256 (GEN) | 623 |
| 5962H9584505VXC | C | 04/08/2002 | | (NONE) | | | 6256 (GEN) | 623 |
| 5962R9584505QXC | C | 04/08/2002 | | (NONE) | | | 6256 (GEN) | 623 |
| 5962R9584505VXC | C | 04/08/2002 | | (NONE) | | | 6256 (GEN) | 623 |
| 5962F9584505QYC | C | 04/08/2002 | | (NONE) | | | 6256 (GEN) | 623 |
| 5962F9584505VYC | C | 04/08/2002 | | (NONE) | | | 6256 (GEN) | 623 |
| 5962H9584505QYC | C | 04/08/2002 | | (NONE) | | | 6256 (GEN) | 623 |
| 5962H9584505VYC | C | 04/08/2002 | | (NONE) | | | 6256 (GEN) | 623 |
| 5962R9584505QYC | C | 04/08/2002 | | (NONE) | | | 6256 (GEN) | 623 |
| 5962R9584505VYC | C | 04/08/2002 | | (NONE) | | | 6256 (GEN) | 623 |
| 5962F9584505QZC | C | 04/08/2002 | | (NONE) | | | 6256 (GEN) | 623 |
| 5962F9584505VZC | C | 04/08/2002 | | (NONE) | | | 6256 (GEN) | 623 |
| 5962H9584505QZC | C | 04/08/2002 | | (NONE) | | | 6256 (GEN) | 623 |
| 5962H9584505VZC | C | 04/08/2002 | | (NONE) | | | 6256 (GEN) | 623 |
| 5962R9584505QZC | C | 04/08/2002 | | (NONE) | | | 6256 (GEN) | 623 |
| 5962R9584505VZC | C | 04/08/2002 | | (NONE) | | | 6256 (GEN) | 623 |
| 5962F9584506QXC | C | 04/08/2002 | | (NONE) | | | 6256 (GEN) | 623 |
| 5962F9584506VXC | C | 04/08/2002 | | (NONE) | | | 6256 (GEN) | 623 |
| 5962H9584506QXC | C | 04/08/2002 | | (NONE) | | | 6256 (GEN) | 623 |
| 5962H9584506VXC | C | 04/08/2002 | | (NONE) | | | 6256 (GEN) | 623 |
| 5962R9584506QXC | C | 04/08/2002 | | (NONE) | | | 6256 (GEN) | 623 |
| 5962R9584506VXC | C | 04/08/2002 | | (NONE) | | | 6256 (GEN) | 623 |
| 5962F9584506QYC | C | 04/08/2002 | | (NONE) | | | 6256 (GEN) | 623 |
| 5962F9584506VYC | C | 04/08/2002 | | (NONE) | | | 6256 (GEN) | 623 |
| 5962H9584506QYC | C | 04/08/2002 | | (NONE) | | | 6256 (GEN) | 623 |
| 5962H9584506VYC | C | 04/08/2002 | | (NONE) | | | 6256 (GEN) | 623 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962R9584506QYC | C | 04/08/2002 | | (NONE) | | | 6256 (GEN) | 623 |
| 5962R9584506VYC | C | 04/08/2002 | | (NONE) | | | 6256 (GEN) | 623 |
| 5962F9584506QZC | C | 04/08/2002 | | (NONE) | | | 6256 (GEN) | 623 |
| 5962F9584506VZC | C | 04/08/2002 | | (NONE) | | | 6256 (GEN) | 623 |
| 5962H9584506QZC | C | 04/08/2002 | | (NONE) | | | 6256 (GEN) | 623 |
| 5962H9584506VZC | C | 04/08/2002 | | (NONE) | | | 6256 (GEN) | 623 |
| 5962R9584506QZC | C | 04/08/2002 | | (NONE) | | | 6256 (GEN) | 623 |
| 5962R9584506VZC | C | 04/08/2002 | | (NONE) | | | 6256 (GEN) | 623 |
| 5962-95A0101MXA | | 07/11/1995 | | (NONE) | | | 6559-008 (GEN) | 429 |
| 5962-95A0101QXA | | 07/11/1995 | 1 | AMI | | Y | 6559-008 | 429 |
| 5962-95A0301M3A | A | 05/20/1998 | | (NONE) | | | 6553-018 (GEN) | 365 |
| 5962-95A0301Q3A | A | 05/20/1998 | 1 | AMI | | Y | 6553-018 | 365 |
| 5962M95A0501QXA | | 06/06/1995 | 1 | INTERSIL | | Y | HS4-51472AR3808 | 365 |
| 5962M95A0501QYA | | 06/06/1995 | 1 | INTERSIL | | Y | HS1-51472AR3808 | 365 |
| 5962-95B0101M4C | | 10/27/1994 | | (NONE) | | | LCA10K (GEN) | 367 |
| 5962-95B0101M5C | | 10/27/1994 | | (NONE) | | | LCA10K (GEN) | 367 |
| 5962-95B0101M6C | | 10/27/1994 | | (NONE) | | | LCA10K (GEN) | 367 |
| 5962-95B0101M7C | | 10/27/1994 | | (NONE) | | | LCA10K (GEN) | 367 |
| 5962-95B0101M8C | | 10/27/1994 | | (NONE) | | | LCA10K (GEN) | 367 |
| 5962-95B0101M9C | | 10/27/1994 | | (NONE) | | | LCA10K (GEN) | 367 |
| 5962-95B0101MCC | | 10/27/1994 | | (NONE) | | | LCA10K (GEN) | 367 |
| 5962-95B0101MMC | | 10/27/1994 | | (NONE) | | | LCA10K (GEN) | 367 |
| 5962-95B0101MNC | | 10/27/1994 | | (NONE) | | | LCA10K (GEN) | 367 |
| 5962-95B0101MTC | | 10/27/1994 | | (NONE) | | | LCA10K (GEN) | 367 |
| 5962-95B0101MUC | | 10/27/1994 | | (NONE) | | | LCA10K (GEN) | 367 |
| 5962-95B0101MXC | | 10/27/1994 | | (NONE) | | | LCA10K (GEN) | 367 |
| 5962-95B0101MYC | | 10/27/1994 | | (NONE) | | | LCA10K (GEN) | 367 |
| 5962-95B0101MZC | | 10/27/1994 | | (NONE) | | | LCA10K (GEN) | 367 |
| 5962-95B0102M4C | | 10/27/1994 | | (NONE) | | | LMA9K (GEN) | 367 |
| 5962-95B0102M5C | | 10/27/1994 | | (NONE) | | | LMA9K (GEN) | 367 |
| 5962-95B0102M6C | | 10/27/1994 | | (NONE) | | | LMA9K (GEN) | 367 |
| 5962-95B0102M7C | | 10/27/1994 | | (NONE) | | | LMA9K (GEN) | 367 |
| 5962-95B0102M8C | | 10/27/1994 | | (NONE) | | | LMA9K (GEN) | 367 |
| 5962-95B0102M9C | | 10/27/1994 | | (NONE) | | | LMA9K (GEN) | 367 |
| 5962-95B0102MCC | | 10/27/1994 | | (NONE) | | | LMA9K (GEN) | 367 |
| 5962-95B0102MMC | | 10/27/1994 | | (NONE) | | | LMA9K (GEN) | 367 |
| 5962-95B0102MNC | | 10/27/1994 | | (NONE) | | | LMA9K (GEN) | 367 |
| 5962-95B0102MTC | | 10/27/1994 | | (NONE) | | | LMA9K (GEN) | 367 |
| 5962-95B0102MUC | | 10/27/1994 | | (NONE) | | | LMA9K (GEN) | 367 |
| 5962-95B0102MXC | | 10/27/1994 | | (NONE) | | | LMA9K (GEN) | 367 |
| 5962-95B0102MYC | | 10/27/1994 | | (NONE) | | | LMA9K (GEN) | 367 |
| 5962-95B0102MZC | | 10/27/1994 | | (NONE) | | | LMA9K (GEN) | 367 |
| 5962-95B0103M4C | | 10/27/1994 | | (NONE) | | | LCB15K (GEN) | 367 |
| 5962-95B0103M5C | | 10/27/1994 | | (NONE) | | | LCB15K (GEN) | 367 |
| 5962-95B0103M6C | | 10/27/1994 | | (NONE) | | | LCB15K (GEN) | 367 |
| 5962-95B0103M7C | | 10/27/1994 | | (NONE) | | | LCB15K (GEN) | 367 |
| 5962-95B0103M8C | | 10/27/1994 | | (NONE) | | | LCB15K (GEN) | 367 |
| 5962-95B0103M9C | | 10/27/1994 | | (NONE) | | | LCB15K (GEN) | 367 |
| 5962-95B0103MCC | | 10/27/1994 | | (NONE) | | | LCB15K (GEN) | 367 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-95B0103MMC | | 10/27/1994 | | (NONE) | | | LCB15K (GEN) | 367 |
| 5962-95B0103MNC | | 10/27/1994 | | (NONE) | | | LCB15K (GEN) | 367 |
| 5962-95B0103MTC | | 10/27/1994 | | (NONE) | | | LCB15K (GEN) | 367 |
| 5962-95B0103MUC | | 10/27/1994 | | (NONE) | | | LCB15K (GEN) | 367 |
| 5962-95B0103MXC | | 10/27/1994 | | (NONE) | | | LCB15K (GEN) | 367 |
| 5962-95B0103MYC | | 10/27/1994 | | (NONE) | | | LCB15K (GEN) | 367 |
| 5962-95B0103MZC | | 10/27/1994 | | (NONE) | | | LCB15K (GEN) | 367 |
| 5962H95B0401QTC | | 12/09/1997 | | (NONE) | | | HX1060 (GEN) | 365 |
| 5962H95B0401VTC | | 12/09/1997 | | (NONE) | | | HX1060 (GEN) | 365 |
| 5962H95B0401QXC | | 12/09/1997 | | (NONE) | | | HX1060 (GEN) | 365 |
| 5962H95B0401VXC | | 12/09/1997 | | (NONE) | | | HX1060 (GEN) | 365 |
| 5962-9650101HUA | A | 11/29/2001 | 1 | ADV. ANALOG | | Y | AFL27025SW/CH | 594 |
| 5962-9650101HUC | A | 11/29/2001 | 1 | ADV. ANALOG | | Y | AFL27025SW/CH | 594 |
| 5962-9650101HXA | A | 11/29/2001 | 1 | ADV. ANALOG | | Y | AFL27025SX/CH | 594 |
| 5962-9650101HXC | A | 11/29/2001 | 1 | ADV. ANALOG | | Y | AFL27025SX/CH | 594 |
| 5962-9650101HYA | A | 11/29/2001 | 1 | ADV. ANALOG | | Y | AFL27025SY/CH | 594 |
| 5962-9650101HYC | A | 11/29/2001 | 1 | ADV. ANALOG | | Y | AFL27025SY/CH | 594 |
| 5962-9650101HZA | A | 11/29/2001 | 1 | ADV. ANALOG | | Y | AFL27025SZ/CH | 594 |
| 5962-9650101HZC | A | 11/29/2001 | 1 | ADV. ANALOG | | Y | AFL27025SZ/CH | 594 |
| 5962-9650201QEA | A | 06/16/1998 | | (NONE) | 09/04/2001 | | LM2595J-12 (GEN) | 782 |
| 5962-9650301QEA | | 04/08/1997 | | (NONE) | | | LM2595J-5 (GEN) | 782 |
| 5962-9650401QEA | | 11/27/1996 | | (NONE) | 09/04/2001 | | LM2595J-ADJ (GEN) | 789 |
| 5962-9650501QEA | B | 12/31/2002 | 1 | NATIONAL | | Y | LM2991J-QML | 781 |
| 5962-9650501VEA | B | 12/31/2002 | 1 | NATIONAL | | Y | LM2991J-QMLV | 781 |
| 5962-9650501QXA | B | 12/31/2002 | 1 | NATIONAL | | Y | LM2991WG-QML | 781 |
| 5962-9650801QEA | | 12/08/1995 | | (NONE) | | | 604A (GEN) | 820 |
| 5962-9650801NXA | | 12/08/1995 | | (NONE) | | | 604A (GEN) | 820 |
| 5962-9650802NXA | | 12/08/1995 | | (NONE) | | | 604A (GEN) | 820 |
| 5962-9650901QXA | | 11/09/1995 | 2 | TI | | Y | SNJ54ABT7820GB | 670 |
| 5962H9651201Q9A | C | 06/04/2001 | 1 | UTMC | | Y | UT54ACS00-QDIE | 100 |
| 5962H9651201V9A | C | 06/04/2001 | 1 | UTMC | | Y | UT54ACS00-VDIE | 100 |
| 5962H9651201QCA | C | 06/04/2001 | 1 | UTMC | | Y | UT54ACS00PQAH | 100 |
| 5962H9651201QCC | C | 06/04/2001 | 1 | UTMC | | Y | UT54ACS00PQCH | 100 |
| 5962H9651201VCA | C | 06/04/2001 | 1 | UTMC | | Y | UT54ACS00PVAH | 100 |
| 5962H9651201VCC | C | 06/04/2001 | 1 | UTMC | | Y | UT54ACS00PVCH | 100 |
| 5962H9651201QXA | C | 06/04/2001 | 1 | UTMC | | Y | UT54ACS00UQAH | 100 |
| 5962H9651201QXC | C | 06/04/2001 | 1 | UTMC | | Y | UT54ACS00UQCH | 100 |
| 5962H9651201VXA | C | 06/04/2001 | 1 | UTMC | | Y | UT54ACS00UVAH | 100 |
| 5962H9651201VXC | C | 06/04/2001 | 1 | UTMC | | Y | UT54ACS00UVCH | 100 |
| 5962H9651301QCA | B | 06/11/2001 | 1 | UTMC | | Y | UT54ACTS00PQAH | 100 |
| 5962H9651301QCC | B | 06/11/2001 | 1 | UTMC | | Y | UT54ACTS00PQCH | 100 |
| 5962H9651301VCA | B | 06/11/2001 | 1 | UTMC | | Y | UT54ACTS00PVAH | 100 |
| 5962H9651301VCC | B | 06/11/2001 | 1 | UTMC | | Y | UT54ACTS00PVCH | 100 |
| 5962H9651301QXA | B | 06/11/2001 | 1 | UTMC | | Y | UT54ACTS00UQAH | 100 |
| 5962H9651301QXC | B | 06/11/2001 | 1 | UTMC | | Y | UT54ACTS00UQCH | 100 |
| 5962H9651301VXA | B | 06/11/2001 | 1 | UTMC | | Y | UT54ACTS00UVAH | 100 |
| 5962H9651301VXC | B | 06/11/2001 | 1 | UTMC | | Y | UT54ACTS00UVCH | 100 |
| 5962H9651401QCA | B | 06/11/2001 | 1 | UTMC | | Y | UT54ACS02PQAH | 120 |
| 5962H9651401QCC | B | 06/11/2001 | 1 | UTMC | | Y | UT54ACS02PQCH | 120 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962H9651401VCA | B | 06/11/2001 | 1 | UTMC | | Y | UT54ACS02PVAH | 120 |
| 5962H9651401VCC | B | 06/11/2001 | 1 | UTMC | | Y | UT54ACS02PVCH | 120 |
| 5962H9651401QXA | B | 06/11/2001 | 1 | UTMC | | Y | UT54ACS02UQAH | 120 |
| 5962H9651401QXC | B | 06/11/2001 | 1 | UTMC | | Y | UT54ACS02UQCH | 120 |
| 5962H9651401VXA | B | 06/11/2001 | 1 | UTMC | | Y | UT54ACS02UVAH | 120 |
| 5962H9651401VXC | B | 06/11/2001 | 1 | UTMC | | Y | UT54ACS02UVCH | 120 |
| 5962H9651501QCA | B | 06/11/2001 | 1 | UTMC | | Y | UT54ACTS02PQAH | 120 |
| 5962H9651501QCC | B | 06/11/2001 | 1 | UTMC | | Y | UT54ACTS02PQCH | 120 |
| 5962H9651501VCA | B | 06/11/2001 | 1 | UTMC | | Y | UT54ACTS02PVAH | 120 |
| 5962H9651501VCC | B | 06/11/2001 | 1 | UTMC | | Y | UT54ACTS02PVCH | 120 |
| 5962H9651501QXA | B | 06/11/2001 | 1 | UTMC | | Y | UT54ACTS02UQAH | 120 |
| 5962H9651501QXC | B | 06/11/2001 | 1 | UTMC | | Y | UT54ACTS02UQCH | 120 |
| 5962H9651501VXA | B | 06/11/2001 | 1 | UTMC | | Y | UT54ACTS02UVAH | 120 |
| 5962H9651501VXC | B | 06/11/2001 | 1 | UTMC | | Y | UT54ACTS02UVCH | 120 |
| 5962H9651601Q9A | C | 06/11/2001 | 1 | UTMC | | Y | UT54ACS04-QDIE | 143 |
| 5962H9651601V9A | C | 06/11/2001 | 1 | UTMC | | Y | UT54ACS04-VDIE | 143 |
| 5962H9651601QCA | C | 06/11/2001 | 1 | UTMC | | Y | UT54ACS04PQAH | 143 |
| 5962H9651601QCC | C | 06/11/2001 | 1 | UTMC | | Y | UT54ACS04PQCH | 143 |
| 5962H9651601VCA | C | 06/11/2001 | 1 | UTMC | | Y | UT54ACS04PVAH | 143 |
| 5962H9651601VCC | C | 06/11/2001 | 1 | UTMC | | Y | UT54ACS04PVCH | 143 |
| 5962H9651601QXA | C | 06/11/2001 | 1 | UTMC | | Y | UT54ACS04UQAH | 143 |
| 5962H9651601QXC | C | 06/11/2001 | 1 | UTMC | | Y | UT54ACS04UQCH | 143 |
| 5962H9651601VXA | C | 06/11/2001 | 1 | UTMC | | Y | UT54ACS04UVAH | 143 |
| 5962H9651601VXC | C | 06/11/2001 | 1 | UTMC | | Y | UT54ACS04UVCH | 143 |
| 5962H9651701QCA | B | 06/11/2001 | 1 | UTMC | | Y | UT54ACTS04PQAH | 143 |
| 5962H9651701QCC | B | 06/11/2001 | 1 | UTMC | | Y | UT54ACTS04PQCH | 143 |
| 5962H9651701VCA | B | 06/11/2001 | 1 | UTMC | | Y | UT54ACTS04PVAH | 143 |
| 5962H9651701VCC | B | 06/11/2001 | 1 | UTMC | | Y | UT54ACTS04PVCH | 143 |
| 5962H9651701QXA | B | 06/11/2001 | 1 | UTMC | | Y | UT54ACTS04UQAH | 143 |
| 5962H9651701QXC | B | 06/11/2001 | 1 | UTMC | | Y | UT54ACTS04UQCH | 143 |
| 5962H9651701VXA | B | 06/11/2001 | 1 | UTMC | | Y | UT54ACTS04UVAH | 143 |
| 5962H9651701VXC | B | 06/11/2001 | 1 | UTMC | | Y | UT54ACTS04UVCH | 143 |
| 5962H9651801QCA | B | 06/11/2001 | 1 | UTMC | | Y | UT54ACS08PQAH | 110 |
| 5962H9651801QCC | B | 06/11/2001 | 1 | UTMC | | Y | UT54ACS08PQCH | 110 |
| 5962H9651801VCA | B | 06/11/2001 | 1 | UTMC | | Y | UT54ACS08PVAH | 110 |
| 5962H9651801VCC | B | 06/11/2001 | 1 | UTMC | | Y | UT54ACS08PVCH | 110 |
| 5962H9651801QXA | B | 06/11/2001 | 1 | UTMC | | Y | UT54ACS08UQAH | 110 |
| 5962H9651801QXC | B | 06/11/2001 | 1 | UTMC | | Y | UT54ACS08UQCH | 110 |
| 5962H9651801VXA | B | 06/11/2001 | 1 | UTMC | | Y | UT54ACS08UVAH | 110 |
| 5962H9651801VXC | B | 06/11/2001 | 1 | UTMC | | Y | UT54ACS08UVCH | 110 |
| 5962H9651901QCA | C | 05/27/2004 | 1 | UTMC | | Y | UT54ACTS08PQAH | 110 |
| 5962H9651901QCC | C | 05/27/2004 | 1 | UTMC | | Y | UT54ACTS08PQCH | 110 |
| 5962H9651901VCA | C | 05/27/2004 | 1 | UTMC | | Y | UT54ACTS08PVAH | 110 |
| 5962H9651901VCC | C | 05/27/2004 | 1 | UTMC | | Y | UT54ACTS08PVCH | 110 |
| 5962H9651901QXA | C | 05/27/2004 | 1 | UTMC | | Y | UT54ACTS08UQAH | 110 |
| 5962H9651901QXC | C | 05/27/2004 | 1 | UTMC | | Y | UT54ACTS08UQCH | 110 |
| 5962H9651901VXA | C | 05/27/2004 | 1 | UTMC | | Y | UT54ACTS08UVAH | 110 |
| 5962H9651901VXC | C | 05/27/2004 | 1 | UTMC | | Y | UT54ACTS08UVCH | 110 |
| 5962H9651902QXA | C | 05/27/2004 | 1 | UTMC | | Y | UT54ACTS08EUQAH | 110 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962H9651902QXC | C | 05/27/2004 | 1 | UTMC | | Y | UT54ACTS08EUQCH | 110 |
| 5962H9651902VXA | C | 05/27/2004 | 1 | UTMC | | Y | UT54ACTS08EUVAH | 110 |
| 5962H9651902VXC | C | 05/27/2004 | 1 | UTMC | | Y | UT54ACTS08EUVCH | 110 |
| 5962G9651903QXA | C | 05/27/2004 | 1 | UTMC | | Y | UT54ACTS08EUQAG | 110 |
| 5962G9651903QXC | C | 05/27/2004 | 1 | UTMC | | Y | UT54ACTS08EUQCG | 110 |
| 5962G9651903VXA | C | 05/27/2004 | 1 | UTMC | | Y | UT54ACTS08EUVAG | 110 |
| 5962G9651903VXC | C | 05/27/2004 | 1 | UTMC | | Y | UT54ACTS08EUVCG | 110 |
| 5962H9652001QCA | B | 06/11/2001 | 1 | UTMC | | Y | UT54ACS10PQAH | 102 |
| 5962H9652001QCC | B | 06/11/2001 | 1 | UTMC | | Y | UT54ACS10PQCH | 102 |
| 5962H9652001VCA | B | 06/11/2001 | 1 | UTMC | | Y | UT54ACS10PVAH | 102 |
| 5962H9652001VCC | B | 06/11/2001 | 1 | UTMC | | Y | UT54ACS10PVCH | 102 |
| 5962H9652001QXA | B | 06/11/2001 | 1 | UTMC | | Y | UT54ACS10UQAH | 102 |
| 5962H9652001QXC | B | 06/11/2001 | 1 | UTMC | | Y | UT54ACS10UQCH | 102 |
| 5962H9652001VXA | B | 06/11/2001 | 1 | UTMC | | Y | UT54ACS10UVAH | 102 |
| 5962H9652001VXC | B | 06/11/2001 | 1 | UTMC | | Y | UT54ACS10UVCH | 102 |
| 5962H9652101QCA | A | 11/25/1996 | 1 | UTMC | | Y | UT54ACTS10PQAH | 102 |
| 5962H9652101QCC | A | 11/25/1996 | 1 | UTMC | | Y | UT54ACTS10PQCH | 102 |
| 5962H9652101VCA | A | 11/25/1996 | 1 | UTMC | | Y | UT54ACTS10PVAH | 102 |
| 5962H9652101VCC | A | 11/25/1996 | 1 | UTMC | | Y | UT54ACTS10PVCH | 102 |
| 5962H9652101QXA | A | 11/25/1996 | 1 | UTMC | | Y | UT54ACTS10UQAH | 102 |
| 5962H9652101QXC | A | 11/25/1996 | 1 | UTMC | | Y | UT54ACTS10UQCH | 102 |
| 5962H9652101VXA | A | 11/25/1996 | 1 | UTMC | | Y | UT54ACTS10UVAH | 102 |
| 5962H9652101VXC | A | 11/25/1996 | 1 | UTMC | | Y | UT54ACTS10UVCH | 102 |
| 5962H9652201QCA | A | 11/25/1996 | 1 | UTMC | | Y | UT54ACS11PQAH | 112 |
| 5962H9652201QCC | A | 11/25/1996 | 1 | UTMC | | Y | UT54ACS11PQCH | 112 |
| 5962H9652201VCA | A | 11/25/1996 | 1 | UTMC | | Y | UT54ACS11PVAH | 112 |
| 5962H9652201VCC | A | 11/25/1996 | 1 | UTMC | | Y | UT54ACS11PVCH | 112 |
| 5962H9652201QXA | A | 11/25/1996 | 1 | UTMC | | Y | UT54ACS11UQAH | 112 |
| 5962H9652201QXC | A | 11/25/1996 | 1 | UTMC | | Y | UT54ACS11UQCH | 112 |
| 5962H9652201VXA | A | 11/25/1996 | 1 | UTMC | | Y | UT54ACS11UVAH | 112 |
| 5962H9652201VXC | A | 11/25/1996 | 1 | UTMC | | Y | UT54ACS11UVCH | 112 |
| 5962H9652301QCA | A | 11/25/1996 | 1 | UTMC | | Y | UT54ACTS11PQAH | 112 |
| 5962H9652301QCC | A | 11/25/1996 | 1 | UTMC | | Y | UT54ACTS11PQCH | 112 |
| 5962H9652301VCA | A | 11/25/1996 | 1 | UTMC | | Y | UT54ACTS11PVAH | 112 |
| 5962H9652301VCC | A | 11/25/1996 | 1 | UTMC | | Y | UT54ACTS11PVCH | 112 |
| 5962H9652301QXA | A | 11/25/1996 | 1 | UTMC | | Y | UT54ACTS11UQAH | 112 |
| 5962H9652301QXC | A | 11/25/1996 | 1 | UTMC | | Y | UT54ACTS11UQCH | 112 |
| 5962H9652301VXA | A | 11/25/1996 | 1 | UTMC | | Y | UT54ACTS11UVAH | 112 |
| 5962H9652301VXC | A | 11/25/1996 | 1 | UTMC | | Y | UT54ACTS11UVCH | 112 |
| 5962G9652401Q9B | E | 01/29/2004 | 1 | UTMC | | Y | UT54ACS14-Q-DIE | 143 |
| 5962G9652401V9B | E | 01/29/2004 | 1 | UTMC | | Y | UT54ACS14-V-DIE | 143 |
| 5962H9652401Q9A | E | 01/29/2004 | | (NONE) | | | 54ACS14 (GEN) | 143 |
| 5962H9652401Q9B | E | 01/29/2004 | | (NONE) | | | 54ACS14 (GEN) | 143 |
| 5962H9652401V9A | E | 01/29/2004 | | (NONE) | | | 54ACS14 (GEN) | 143 |
| 5962H9652401V9B | E | 01/29/2004 | | (NONE) | | | 54ACS14 (GEN) | 143 |
| 5962H9652401QCA | E | 01/29/2004 | | (NONE) | | | 54ACS14 (GEN) | 143 |
| 5962H9652401VCA | E | 01/29/2004 | | (NONE) | | | 54ACS14 (GEN) | 143 |
| 5962G9652401QXA | E | 01/29/2004 | 1 | UTMC | | Y | UT54ACS14UQAG | 143 |
| 5962G9652401QXC | E | 01/29/2004 | 1 | UTMC | | Y | UT54ACS14UQCG | 143 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962G9652401VXA | E | 01/29/2004 | 1 | UTMC | | Y | UT54ACS14UVAG | 143 |
| 5962G9652401VXC | E | 01/29/2004 | 1 | UTMC | | Y | UT54ACS14UVCG | 143 |
| 5962H9652401QXA | E | 01/29/2004 | | (NONE) | | | 54ACS14 (GEN) | 143 |
| 5962H9652401QXC | E | 01/29/2004 | | (NONE) | | | 54ACS14 (GEN) | 143 |
| 5962H9652401VXA | E | 01/29/2004 | | (NONE) | | | 54ACS14 (GEN) | 143 |
| 5962H9652401VXC | E | 01/29/2004 | | (NONE) | | | 54ACS14 (GEN) | 143 |
| 5962H9652402Q9B | E | 01/29/2004 | 1 | UTMC | | Y | UT54ACS14E-Q-DIE | 143 |
| 5962H9652402V9B | E | 01/29/2004 | 1 | UTMC | | Y | UT54ACS14E-V-DIE | 143 |
| 5962H9652402QXA | E | 01/29/2004 | 1 | UTMC | | Y | UT54ACS14EUQAH | 143 |
| 5962H9652402QXC | E | 01/29/2004 | 1 | UTMC | | Y | UT54ACS14EUQCH | 143 |
| 5962H9652402VXA | E | 01/29/2004 | 1 | UTMC | | Y | UT54ACS14EUVAH | 143 |
| 5962H9652402VXC | E | 01/29/2004 | 1 | UTMC | | Y | UT54ACS14EUVCH | 143 |
| 5962G9652403Q9B | E | 01/29/2004 | 1 | UTMC | | Y | UT54ACS14E-Q-DIE | 143 |
| 5962G9652403V9B | E | 01/29/2004 | 1 | UTMC | | Y | UT54ACS14E-V-DIE | 143 |
| 5962G9652403QXA | E | 01/29/2004 | 1 | UTMC | | Y | UT54ACS14EUQAG | 143 |
| 5962G9652403QXC | E | 01/29/2004 | 1 | UTMC | | Y | UT54ACS14EUQCG | 143 |
| 5962G9652403VXA | E | 01/29/2004 | 1 | UTMC | | Y | UT54ACS14EUVAG | 143 |
| 5962G9652403VXC | E | 01/29/2004 | 1 | UTMC | | Y | UT54ACS14EUVCG | 143 |
| 5962H9652501QCA | C | 09/10/1999 | 1 | UTMC | | Y | UT54ACTS14PQAH | 143 |
| 5962H9652501QCC | C | 09/10/1999 | 1 | UTMC | | Y | UT54ACTS14PQCH | 143 |
| 5962H9652501VCA | C | 09/10/1999 | 1 | UTMC | | Y | UT54ACTS14PVAH | 143 |
| 5962H9652501VCC | C | 09/10/1999 | 1 | UTMC | | Y | UT54ACTS14PVCH | 143 |
| 5962H9652501QXA | C | 09/10/1999 | 1 | UTMC | | Y | UT54ACTS14UQAH | 143 |
| 5962H9652501QXC | C | 09/10/1999 | 1 | UTMC | | Y | UT54ACTS14UQCH | 143 |
| 5962H9652501VXA | C | 09/10/1999 | 1 | UTMC | | Y | UT54ACTS14UVAH | 143 |
| 5962H9652501VXC | C | 09/10/1999 | 1 | UTMC | | Y | UT54ACTS14UVCH | 143 |
| 5962H9652601Q9A | B | 03/31/1998 | 1 | UTMC | | Y | UT54ACS20-QDIE | 104 |
| 5962H9652601V9A | B | 03/31/1998 | 1 | UTMC | | Y | UT54ACS20-VDIE | 104 |
| 5962H9652601QCA | B | 03/31/1998 | 1 | UTMC | | Y | UT54ACS20PQAH | 104 |
| 5962H9652601QCC | B | 03/31/1998 | 1 | UTMC | | Y | UT54ACS20PQCH | 104 |
| 5962H9652601VCA | B | 03/31/1998 | 1 | UTMC | | Y | UT54ACS20PVAH | 104 |
| 5962H9652601VCC | B | 03/31/1998 | 1 | UTMC | | Y | UT54ACS20PVCH | 104 |
| 5962H9652601QXA | B | 03/31/1998 | 1 | UTMC | | Y | UT54ACS20UQAH | 104 |
| 5962H9652601QXC | B | 03/31/1998 | 1 | UTMC | | Y | UT54ACS20UQCH | 104 |
| 5962H9652601VXA | B | 03/31/1998 | 1 | UTMC | | Y | UT54ACS20UVAH | 104 |
| 5962H9652601VXC | B | 03/31/1998 | 1 | UTMC | | Y | UT54ACS20UVCH | 104 |
| 5962H9652701QCA | A | 12/10/1996 | 1 | UTMC | | Y | UT54ACTS20PQAH | 104 |
| 5962H9652701QCC | A | 12/10/1996 | 1 | UTMC | | Y | UT54ACTS20PQCH | 104 |
| 5962H9652701VCA | A | 12/10/1996 | 1 | UTMC | | Y | UT54ACTS20PVAH | 104 |
| 5962H9652701VCC | A | 12/10/1996 | 1 | UTMC | | Y | UT54ACTS20PVCH | 104 |
| 5962H9652701QXA | A | 12/10/1996 | 1 | UTMC | | Y | UT54ACTS20UQAH | 104 |
| 5962H9652701QXC | A | 12/10/1996 | 1 | UTMC | | Y | UT54ACTS20UQCH | 104 |
| 5962H9652701VXA | A | 12/10/1996 | 1 | UTMC | | Y | UT54ACTS20UVAH | 104 |
| 5962H9652701VXC | A | 12/10/1996 | 1 | UTMC | | Y | UT54ACTS20UVCH | 104 |
| 5962H9652801QCA | A | 12/12/1996 | 1 | UTMC | | Y | UT54ACS27PQAH | 122 |
| 5962H9652801QCC | A | 12/12/1996 | 1 | UTMC | | Y | UT54ACS27PQCH | 122 |
| 5962H9652801VCA | A | 12/12/1996 | 1 | UTMC | | Y | UT54ACS27PVAH | 122 |
| 5962H9652801VCC | A | 12/12/1996 | 1 | UTMC | | Y | UT54ACS27PVCH | 122 |
| 5962H9652801QXA | A | 12/12/1996 | 1 | UTMC | | Y | UT54ACS27UQAH | 122 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962H9652801QXC | A | 12/12/1996 | 1 | UTMC | | Y | UT54ACS27UQCH | 122 |
| 5962H9652801VXA | A | 12/12/1996 | 1 | UTMC | | Y | UT54ACS27UVAH | 122 |
| 5962H9652801VXC | A | 12/12/1996 | 1 | UTMC | | Y | UT54ACS27UVCH | 122 |
| 5962H9652901QCA | A | 12/12/1996 | 1 | UTMC | | Y | UT54ACTS27PQAH | 122 |
| 5962H9652901QCC | A | 12/12/1996 | 1 | UTMC | | Y | UT54ACTS27PQCH | 122 |
| 5962H9652901VCA | A | 12/12/1996 | 1 | UTMC | | Y | UT54ACTS27PVAH | 122 |
| 5962H9652901VCC | A | 12/12/1996 | 1 | UTMC | | Y | UT54ACTS27PVCH | 122 |
| 5962H9652901QXA | A | 12/12/1996 | 1 | UTMC | | Y | UT54ACTS27UQAH | 122 |
| 5962H9652901QXC | A | 12/12/1996 | 1 | UTMC | | Y | UT54ACTS27UQCH | 122 |
| 5962H9652901VXA | A | 12/12/1996 | 1 | UTMC | | Y | UT54ACTS27UVAH | 122 |
| 5962H9652901VXC | A | 12/12/1996 | 1 | UTMC | | Y | UT54ACTS27UVCH | 122 |
| 5962H9653001QCA | A | 12/12/1996 | 1 | UTMC | | Y | UT54ACS34PQAH | 513 |
| 5962H9653001QCC | A | 12/12/1996 | 1 | UTMC | | Y | UT54ACS34PQCH | 513 |
| 5962H9653001VCA | A | 12/12/1996 | 1 | UTMC | | Y | UT54ACS34PVAH | 513 |
| 5962H9653001VCC | A | 12/12/1996 | 1 | UTMC | | Y | UT54ACS34PVCH | 513 |
| 5962H9653001QXA | A | 12/12/1996 | 1 | UTMC | | Y | UT54ACS34UQAH | 513 |
| 5962H9653001QXC | A | 12/12/1996 | 1 | UTMC | | Y | UT54ACS34UQCH | 513 |
| 5962H9653001VXA | A | 12/12/1996 | 1 | UTMC | | Y | UT54ACS34UVAH | 513 |
| 5962H9653001VXC | A | 12/12/1996 | 1 | UTMC | | Y | UT54ACS34UVCH | 513 |
| 5962H9653101QCA | B | 09/04/2001 | 1 | UTMC | | Y | UT54ACTS34PQAH | 513 |
| 5962H9653101QCC | B | 09/04/2001 | 1 | UTMC | | Y | UT54ACTS34PQCH | 513 |
| 5962H9653101VCA | B | 09/04/2001 | 1 | UTMC | | Y | UT54ACTS34PVAH | 513 |
| 5962H9653101VCC | B | 09/04/2001 | 1 | UTMC | | Y | UT54ACTS34PVCH | 513 |
| 5962H9653101QXA | B | 09/04/2001 | 1 | UTMC | | Y | UT54ACTS34UQAH | 513 |
| 5962H9653101QXC | B | 09/04/2001 | 1 | UTMC | | Y | UT54ACTS34UQCH | 513 |
| 5962H9653101VXA | B | 09/04/2001 | 1 | UTMC | | Y | UT54ACTS34UVAH | 513 |
| 5962H9653101VXC | B | 09/04/2001 | 1 | UTMC | | Y | UT54ACTS34UVCH | 513 |
| 5962H9653201QCA | B | 09/04/2001 | 1 | UTMC | | Y | UT54ACS54PQAH | 131 |
| 5962H9653201QCC | B | 09/04/2001 | 1 | UTMC | | Y | UT54ACS54PQCH | 131 |
| 5962H9653201VCA | B | 09/04/2001 | 1 | UTMC | | Y | UT54ACS54PVAH | 131 |
| 5962H9653201VCC | B | 09/04/2001 | 1 | UTMC | | Y | UT54ACS54PVCH | 131 |
| 5962H9653201QXA | B | 09/04/2001 | 1 | UTMC | | Y | UT54ACS54UQAH | 131 |
| 5962H9653201QXC | B | 09/04/2001 | 1 | UTMC | | Y | UT54ACS54UQCH | 131 |
| 5962H9653201VXA | B | 09/04/2001 | 1 | UTMC | | Y | UT54ACS54UVAH | 131 |
| 5962H9653201VXC | B | 09/04/2001 | 1 | UTMC | | Y | UT54ACS54UVCH | 131 |
| 5962H9653301QCA | B | 09/04/2001 | 1 | UTMC | | Y | UT54ACTS54PQAH | 131 |
| 5962H9653301QCC | B | 09/04/2001 | 1 | UTMC | | Y | UT54ACTS54PQCH | 131 |
| 5962H9653301VCA | B | 09/04/2001 | 1 | UTMC | | Y | UT54ACTS54PVAH | 131 |
| 5962H9653301VCC | B | 09/04/2001 | 1 | UTMC | | Y | UT54ACTS54PVCH | 131 |
| 5962H9653301QXA | B | 09/04/2001 | 1 | UTMC | | Y | UT54ACTS54UQAH | 131 |
| 5962H9653301QXC | B | 09/04/2001 | 1 | UTMC | | Y | UT54ACTS54UQCH | 131 |
| 5962H9653301VXA | B | 09/04/2001 | 1 | UTMC | | Y | UT54ACTS54UVAH | 131 |
| 5962H9653301VXC | B | 09/04/2001 | 1 | UTMC | | Y | UT54ACTS54UVCH | 131 |
| 5962H9653401Q9A | C | 10/02/2001 | 1 | UTMC | | Y | UT54ACS74-QDIE | 158 |
| 5962H9653401V9A | C | 10/02/2001 | 1 | UTMC | | Y | UT54ACS74-VDIE | 158 |
| 5962H9653401QCA | C | 10/02/2001 | 1 | UTMC | | Y | UT54ACS74PQAH | 158 |
| 5962H9653401QCC | C | 10/02/2001 | 1 | UTMC | | Y | UT54ACS74PQCH | 158 |
| 5962H9653401VCA | C | 10/02/2001 | 1 | UTMC | | Y | UT54ACS74PVAH | 158 |
| 5962H9653401VCC | C | 10/02/2001 | 1 | UTMC | | Y | UT54ACS74PVCH | 158 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962H9653401QXA | C | 10/02/2001 | 1 | UTMC | | Y | UT54ACS74UQAH | 158 |
| 5962H9653401QXC | C | 10/02/2001 | 1 | UTMC | | Y | UT54ACS74UQCH | 158 |
| 5962H9653401VXA | C | 10/02/2001 | 1 | UTMC | | Y | UT54ACS74UVAH | 158 |
| 5962H9653401VXC | C | 10/02/2001 | 1 | UTMC | | Y | UT54ACS74UVCH | 158 |
| 5962H9653501QCA | B | 09/04/2001 | 1 | UTMC | | Y | UT54ACTS74PQAH | 158 |
| 5962H9653501QCC | B | 09/04/2001 | 1 | UTMC | | Y | UT54ACTS74PQCH | 158 |
| 5962H9653501VCA | B | 09/04/2001 | 1 | UTMC | | Y | UT54ACTS74PVAH | 158 |
| 5962H9653501VCC | B | 09/04/2001 | 1 | UTMC | | Y | UT54ACTS74PVCH | 158 |
| 5962H9653501QXA | B | 09/04/2001 | 1 | UTMC | | Y | UT54ACTS74UQAH | 158 |
| 5962H9653501QXC | B | 09/04/2001 | 1 | UTMC | | Y | UT54ACTS74UQCH | 158 |
| 5962H9653501VXA | B | 09/04/2001 | 1 | UTMC | | Y | UT54ACTS74UVAH | 158 |
| 5962H9653501VXC | B | 09/04/2001 | 1 | UTMC | | Y | UT54ACTS74UVCH | 158 |
| 5962H9653601QEA | B | 09/04/2001 | 1 | UTMC | | Y | UT54ACS85PQAH | 209 |
| 5962H9653601QEC | B | 09/04/2001 | 1 | UTMC | | Y | UT54ACS85PQCH | 209 |
| 5962H9653601VEA | B | 09/04/2001 | 1 | UTMC | | Y | UT54ACS85PVAH | 209 |
| 5962H9653601VEC | B | 09/04/2001 | 1 | UTMC | | Y | UT54ACS85PVCH | 209 |
| 5962H9653601QXA | B | 09/04/2001 | 1 | UTMC | | Y | UT54ACS85UQAH | 209 |
| 5962H9653601QXC | B | 09/04/2001 | 1 | UTMC | | Y | UT54ACS85UQCH | 209 |
| 5962H9653601VXA | B | 09/04/2001 | 1 | UTMC | | Y | UT54ACS85UVAH | 209 |
| 5962H9653601VXC | B | 09/04/2001 | 1 | UTMC | | Y | UT54ACS85UVCH | 209 |
| 5962H9653701QEA | B | 09/04/2001 | 1 | UTMC | | Y | UT54ACTS85PQAH | 209 |
| 5962H9653701QEC | B | 09/04/2001 | 1 | UTMC | | Y | UT54ACTS85PQCH | 209 |
| 5962H9653701VEA | B | 09/04/2001 | 1 | UTMC | | Y | UT54ACTS85PVAH | 209 |
| 5962H9653701VEC | B | 09/04/2001 | 1 | UTMC | | Y | UT54ACTS85PVCH | 209 |
| 5962H9653701QXA | B | 09/04/2001 | 1 | UTMC | | Y | UT54ACTS85UQAH | 209 |
| 5962H9653701QXC | B | 09/04/2001 | 1 | UTMC | | Y | UT54ACTS85UQCH | 209 |
| 5962H9653701VXA | B | 09/04/2001 | 1 | UTMC | | Y | UT54ACTS85UVAH | 209 |
| 5962H9653701VXC | B | 09/04/2001 | 1 | UTMC | | Y | UT54ACTS85UVCH | 209 |
| 5962H9653801QCA | B | 09/04/2001 | 1 | UTMC | | Y | UT54ACS86PQAH | 140 |
| 5962H9653801QCC | B | 09/04/2001 | 1 | UTMC | | Y | UT54ACS86PQCH | 140 |
| 5962H9653801VCA | B | 09/04/2001 | 1 | UTMC | | Y | UT54ACS86PVAH | 140 |
| 5962H9653801VCC | B | 09/04/2001 | 1 | UTMC | | Y | UT54ACS86PVCH | 140 |
| 5962H9653801QXA | B | 09/04/2001 | 1 | UTMC | | Y | UT54ACS86UQAH | 140 |
| 5962H9653801QXC | B | 09/04/2001 | 1 | UTMC | | Y | UT54ACS86UQCH | 140 |
| 5962H9653801VXA | B | 09/04/2001 | 1 | UTMC | | Y | UT54ACS86UVAH | 140 |
| 5962H9653801VXC | B | 09/04/2001 | 1 | UTMC | | Y | UT54ACS86UVCH | 140 |
| 5962H9653901QCA | B | 09/04/2001 | 1 | UTMC | | Y | UT54ACTS86PQAH | 140 |
| 5962H9653901QCC | B | 09/04/2001 | 1 | UTMC | | Y | UT54ACTS86PQCH | 140 |
| 5962H9653901VCA | B | 09/04/2001 | 1 | UTMC | | Y | UT54ACTS86PVAH | 140 |
| 5962H9653901VCC | B | 09/04/2001 | 1 | UTMC | | Y | UT54ACTS86PVCH | 140 |
| 5962H9653901QXA | B | 09/04/2001 | 1 | UTMC | | Y | UT54ACTS86UQAH | 140 |
| 5962H9653901QXC | B | 09/04/2001 | 1 | UTMC | | Y | UT54ACTS86UQCH | 140 |
| 5962H9653901VXA | B | 09/04/2001 | 1 | UTMC | | Y | UT54ACTS86UVAH | 140 |
| 5962H9653901VXC | B | 09/04/2001 | 1 | UTMC | | Y | UT54ACTS86UVCH | 140 |
| 5962H9654001Q9A | D | 05/26/2004 | | (NONE) | | | 54ACS109 (GEN) | 152 |
| 5962H9654001V9A | D | 05/26/2004 | | (NONE) | | | 54ACS109 (GEN) | 152 |
| 5962H9654001QEA | D | 05/26/2004 | | (NONE) | | | 54ACS109 (GEN) | 152 |
| 5962H9654001VEA | D | 05/26/2004 | | (NONE) | | | 54ACS109 (GEN) | 152 |
| 5962G9654001QXA | D | 05/26/2004 | 1 | UTMC | | Y | UT54ACS109UQAG | 152 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962G9654001QXC | D | 05/26/2004 | 1 | UTMC | | Y | UT54ACS109UQCG | 152 |
| 5962G9654001VXA | D | 05/26/2004 | 1 | UTMC | | Y | UT54ACS109UVAG | 152 |
| 5962G9654001VXC | D | 05/26/2004 | 1 | UTMC | | Y | UT54ACS109UVCG | 152 |
| 5962H9654001QXA | D | 05/26/2004 | | (NONE) | | | 54ACS109 (GEN) | 152 |
| 5962H9654001VXA | D | 05/26/2004 | | (NONE) | | | 54ACS109 (GEN) | 152 |
| 5962H9654002Q9B | D | 05/26/2004 | 1 | UTMC | | Y | UT54ACS109E-Q-DIE | 152 |
| 5962H9654002V9B | D | 05/26/2004 | 1 | UTMC | | Y | UT54ACS109E-V-DIE | 152 |
| 5962H9654002QXA | D | 05/26/2004 | 1 | UTMC | | Y | UT54ACS109EUQAH | 152 |
| 5962H9654002QXC | D | 05/26/2004 | 1 | UTMC | | Y | UT54ACS109EUQCH | 152 |
| 5962H9654002VXA | D | 05/26/2004 | 1 | UTMC | | Y | UT54ACS109EUVAH | 152 |
| 5962H9654002VXC | D | 05/26/2004 | 1 | UTMC | | Y | UT54ACS109EUVCH | 152 |
| 5962G9654003Q9B | D | 05/26/2004 | 1 | UTMC | | Y | UT54ACS109E-Q-DIE | 152 |
| 5962G9654003V9B | D | 05/26/2004 | 1 | UTMC | | Y | UT54ACS109E-V-DIE | 152 |
| 5962G9654003QXA | D | 05/26/2004 | 1 | UTMC | | Y | UT54ACS109EUQAG | 152 |
| 5962G9654003QXC | D | 05/26/2004 | 1 | UTMC | | Y | UT54ACS109EUQCG | 152 |
| 5962G9654003VXA | D | 05/26/2004 | 1 | UTMC | | Y | UT54ACS109EUVAG | 152 |
| 5962G9654003VXC | D | 05/26/2004 | 1 | UTMC | | Y | UT54ACS109EUVCG | 152 |
| 5962H9654101QEA | B | 09/04/2001 | 1 | UTMC | | Y | UT54ACTS109PQAH | 152 |
| 5962H9654101QEC | B | 09/04/2001 | 1 | UTMC | | Y | UT54ACTS109PQCH | 152 |
| 5962H9654101VEA | B | 09/04/2001 | 1 | UTMC | | Y | UT54ACTS109PVAH | 152 |
| 5962H9654101VEC | B | 09/04/2001 | 1 | UTMC | | Y | UT54ACTS109PVCH | 152 |
| 5962H9654101QXA | B | 09/04/2001 | 1 | UTMC | | Y | UT54ACTS109UQAH | 152 |
| 5962H9654101QXC | B | 09/04/2001 | 1 | UTMC | | Y | UT54ACTS109UQCH | 152 |
| 5962H9654101VXA | B | 09/04/2001 | 1 | UTMC | | Y | UT54ACTS109UVAH | 152 |
| 5962H9654101VXC | B | 09/04/2001 | 1 | UTMC | | Y | UT54ACTS109UVCH | 152 |
| 5962G9654201Q9B | F | 08/12/2004 | 1 | UTMC | | Y | UT54ACS132-Q-DIE | 109 |
| 5962G9654201V9B | F | 08/12/2004 | 1 | UTMC | | Y | UT54ACS132-V-DIE | 109 |
| 5962H9654201Q9A | F | 08/12/2004 | | (NONE) | | | 54ACS132 (GEN) | 109 |
| 5962H9654201Q9B | F | 08/12/2004 | | (NONE) | | | 54ACS132 (GEN) | 109 |
| 5962H9654201V9A | F | 08/12/2004 | | (NONE) | | | 54ACS132 (GEN) | 109 |
| 5962H9654201V9B | F | 08/12/2004 | | (NONE) | | | 54ACS132 (GEN) | 109 |
| 5962H9654201QCA | F | 08/12/2004 | | (NONE) | | | 54ACS132 (GEN) | 109 |
| 5962H9654201VCA | F | 08/12/2004 | | (NONE) | | | 54ACS132 (GEN) | 109 |
| 5962G9654201QXA | F | 08/12/2004 | 1 | UTMC | | Y | UT54ACS132UQAG | 109 |
| 5962G9654201QXC | F | 08/12/2004 | 1 | UTMC | | Y | UT54ACS132UQCG | 109 |
| 5962G9654201VXA | F | 08/12/2004 | 1 | UTMC | | Y | UT54ACS132UVAG | 109 |
| 5962G9654201VXC | F | 08/12/2004 | 1 | UTMC | | Y | UT54ACS132UVCG | 109 |
| 5962H9654201QXA | F | 08/12/2004 | | (NONE) | | | 54ACS132 (GEN) | 109 |
| 5962H9654201VXA | F | 08/12/2004 | | (NONE) | | | 54ACS132 (GEN) | 109 |
| 5962H9654202Q9B | F | 08/12/2004 | 1 | UTMC | | Y | UT54ACS132E-Q-DIE | 109 |
| 5962H9654202V9B | F | 08/12/2004 | 1 | UTMC | | Y | UT54ACS132E-V-DIE | 109 |
| 5962H9654202QXA | F | 08/12/2004 | 1 | UTMC | | Y | UT54ACS132EUQAH | 109 |
| 5962H9654202QXC | F | 08/12/2004 | 1 | UTMC | | Y | UT54ACS132EUQCH | 109 |
| 5962H9654202VXA | F | 08/12/2004 | 1 | UTMC | | Y | UT54ACS132EUVAH | 109 |
| 5962H9654202VXC | F | 08/12/2004 | 1 | UTMC | | Y | UT54ACS132EUVCH | 109 |
| 5962G9654203Q9B | F | 08/12/2004 | 1 | UTMC | | Y | UT54ACS132E-Q-DIE | 109 |
| 5962G9654203V9B | F | 08/12/2004 | 1 | UTMC | | Y | UT54ACS132E-V-DIE | 109 |
| 5962G9654203QXA | F | 08/12/2004 | 1 | UTMC | | Y | UT54ACS132EUQAG | 109 |
| 5962G9654203QXC | F | 08/12/2004 | 1 | UTMC | | Y | UT54ACS132EUQCG | 109 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962G9654203VXA | F | 08/12/2004 | 1 | UTMC | | Y | UT54ACS132EUVAG | 109 |
| 5962G9654203VXC | F | 08/12/2004 | 1 | UTMC | | Y | UT54ACS132EUVCG | 109 |
| 5962H9654301QCA | C | 09/10/1999 | 1 | UTMC | | Y | UT54ACTS132PQAH | 109 |
| 5962H9654301QCC | C | 09/10/1999 | 1 | UTMC | | Y | UT54ACTS132PQCH | 109 |
| 5962H9654301VCA | C | 09/10/1999 | 1 | UTMC | | Y | UT54ACTS132PVAH | 109 |
| 5962H9654301VCC | C | 09/10/1999 | 1 | UTMC | | Y | UT54ACTS132PVCH | 109 |
| 5962H9654301QXA | C | 09/10/1999 | 1 | UTMC | | Y | UT54ACTS132UQAH | 109 |
| 5962H9654301QXC | C | 09/10/1999 | 1 | UTMC | | Y | UT54ACTS132UQCH | 109 |
| 5962H9654301VXA | C | 09/10/1999 | 1 | UTMC | | Y | UT54ACTS132UVAH | 109 |
| 5962H9654301VXC | C | 09/10/1999 | 1 | UTMC | | Y | UT54ACTS132UVCH | 109 |
| 5962H9654401QEA | B | 10/02/2001 | 1 | UTMC | | Y | UT54ACS138PQAH | 282 |
| 5962H9654401QEC | B | 10/02/2001 | 1 | UTMC | | Y | UT54ACS138PQCH | 282 |
| 5962H9654401VEA | B | 10/02/2001 | 1 | UTMC | | Y | UT54ACS138PVAH | 282 |
| 5962H9654401VEC | B | 10/02/2001 | 1 | UTMC | | Y | UT54ACS138PVCH | 282 |
| 5962H9654401QXA | B | 10/02/2001 | 1 | UTMC | | Y | UT54ACS138UQAH | 282 |
| 5962H9654401QXC | B | 10/02/2001 | 1 | UTMC | | Y | UT54ACS138UQCH | 282 |
| 5962H9654401VXA | B | 10/02/2001 | 1 | UTMC | | Y | UT54ACS138UVAH | 282 |
| 5962H9654401VXC | B | 10/02/2001 | 1 | UTMC | | Y | UT54ACS138UVCH | 282 |
| 5962H9654501QEA | B | 10/02/2001 | 1 | UTMC | | Y | UT54ACTS138PQAH | 282 |
| 5962H9654501QEC | B | 10/02/2001 | 1 | UTMC | | Y | UT54ACTS138PQCH | 282 |
| 5962H9654501VEA | B | 10/02/2001 | 1 | UTMC | | Y | UT54ACTS138PVAH | 282 |
| 5962H9654501VEC | B | 10/02/2001 | 1 | UTMC | | Y | UT54ACTS138PVCH | 282 |
| 5962H9654501QXA | B | 10/02/2001 | 1 | UTMC | | Y | UT54ACTS138UQAH | 282 |
| 5962H9654501QXC | B | 10/02/2001 | 1 | UTMC | | Y | UT54ACTS138UQCH | 282 |
| 5962H9654501VXA | B | 10/02/2001 | 1 | UTMC | | Y | UT54ACTS138UVAH | 282 |
| 5962H9654501VXC | B | 10/02/2001 | 1 | UTMC | | Y | UT54ACTS138UVCH | 282 |
| 5962H9654601QEA | B | 10/02/2001 | 1 | UTMC | | Y | UT54ACS139PQAH | 283 |
| 5962H9654601QEC | B | 10/02/2001 | 1 | UTMC | | Y | UT54ACS139PQCH | 283 |
| 5962H9654601VEA | B | 10/02/2001 | 1 | UTMC | | Y | UT54ACS139PVAH | 283 |
| 5962H9654601VEC | B | 10/02/2001 | 1 | UTMC | | Y | UT54ACS139PVCH | 283 |
| 5962H9654601QXA | B | 10/02/2001 | 1 | UTMC | | Y | UT54ACS139UQAH | 283 |
| 5962H9654601QXC | B | 10/02/2001 | 1 | UTMC | | Y | UT54ACS139UQCH | 283 |
| 5962H9654601VXA | B | 10/02/2001 | 1 | UTMC | | Y | UT54ACS139UVAH | 283 |
| 5962H9654601VXC | B | 10/02/2001 | 1 | UTMC | | Y | UT54ACS139UVCH | 283 |
| 5962H9654701QEA | B | 10/02/2001 | 1 | UTMC | | Y | UT54ACTS139PQAH | 283 |
| 5962H9654701QEC | B | 10/02/2001 | 1 | UTMC | | Y | UT54ACTS139PQCH | 283 |
| 5962H9654701VEA | B | 10/02/2001 | 1 | UTMC | | Y | UT54ACTS139PVAH | 283 |
| 5962H9654701VEC | B | 10/02/2001 | 1 | UTMC | | Y | UT54ACTS139PVCH | 283 |
| 5962H9654701QXA | B | 10/02/2001 | 1 | UTMC | | Y | UT54ACTS139UQAH | 283 |
| 5962H9654701QXC | B | 10/02/2001 | 1 | UTMC | | Y | UT54ACTS139UQCH | 283 |
| 5962H9654701VXA | B | 10/02/2001 | 1 | UTMC | | Y | UT54ACTS139UVAH | 283 |
| 5962H9654701VXC | B | 10/02/2001 | 1 | UTMC | | Y | UT54ACTS139UVCH | 283 |
| 5962H9654801QEA | B | 10/02/2001 | 1 | UTMC | | Y | UT54ACS151PQAH | 271 |
| 5962H9654801QEC | B | 10/02/2001 | 1 | UTMC | | Y | UT54ACS151PQCH | 271 |
| 5962H9654801VEA | B | 10/02/2001 | 1 | UTMC | | Y | UT54ACS151PVAH | 271 |
| 5962H9654801VEC | B | 10/02/2001 | 1 | UTMC | | Y | UT54ACS151PVCH | 271 |
| 5962H9654801QXA | B | 10/02/2001 | 1 | UTMC | | Y | UT54ACS151UQAH | 271 |
| 5962H9654801QXC | B | 10/02/2001 | 1 | UTMC | | Y | UT54ACS151UQCH | 271 |
| 5962H9654801VXA | B | 10/02/2001 | 1 | UTMC | | Y | UT54ACS151UVAH | 271 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962H9654801VXC | B | 10/02/2001 | 1 | UTMC | | Y | UT54ACS151UVCH | 271 |
| 5962H9654901QEA | B | 09/14/2001 | 1 | UTMC | | Y | UT54ACTS151PQAH | 271 |
| 5962H9654901QEC | B | 09/14/2001 | 1 | UTMC | | Y | UT54ACTS151PQCH | 271 |
| 5962H9654901VEA | B | 09/14/2001 | 1 | UTMC | | Y | UT54ACTS151PVAH | 271 |
| 5962H9654901VEC | B | 09/14/2001 | 1 | UTMC | | Y | UT54ACTS151PVCH | 271 |
| 5962H9654901QXA | B | 09/14/2001 | 1 | UTMC | | Y | UT54ACTS151UQAH | 271 |
| 5962H9654901QXC | B | 09/14/2001 | 1 | UTMC | | Y | UT54ACTS151UQCH | 271 |
| 5962H9654901VXA | B | 09/14/2001 | 1 | UTMC | | Y | UT54ACTS151UVAH | 271 |
| 5962H9654901VXC | B | 09/14/2001 | 1 | UTMC | | Y | UT54ACTS151UVCH | 271 |
| 5962H9655001QEA | B | 09/14/2001 | 1 | UTMC | | Y | UT54ACS153PQAH | 273 |
| 5962H9655001QEC | B | 09/14/2001 | 1 | UTMC | | Y | UT54ACS153PQCH | 273 |
| 5962H9655001VEA | B | 09/14/2001 | 1 | UTMC | | Y | UT54ACS153PVAH | 273 |
| 5962H9655001VEC | B | 09/14/2001 | 1 | UTMC | | Y | UT54ACS153PVCH | 273 |
| 5962H9655001QXA | B | 09/14/2001 | 1 | UTMC | | Y | UT54ACS153UQAH | 273 |
| 5962H9655001QXC | B | 09/14/2001 | 1 | UTMC | | Y | UT54ACS153UQCH | 273 |
| 5962H9655001VXA | B | 09/14/2001 | 1 | UTMC | | Y | UT54ACS153UVAH | 273 |
| 5962H9655001VXC | B | 09/14/2001 | 1 | UTMC | | Y | UT54ACS153UVCH | 273 |
| 5962H9655101QEA | C | 03/22/2004 | 1 | UTMC | | Y | UT54ACTS153PQAH | 273 |
| 5962H9655101QEC | C | 03/22/2004 | 1 | UTMC | | Y | UT54ACTS153PQCH | 273 |
| 5962H9655101VEA | C | 03/22/2004 | 1 | UTMC | | Y | UT54ACTS153PVAH | 273 |
| 5962H9655101VEC | C | 03/22/2004 | 1 | UTMC | | Y | UT54ACTS153PVCH | 273 |
| 5962H9655101QXA | C | 03/22/2004 | 1 | UTMC | | Y | UT54ACTS153UQAH | 273 |
| 5962H9655101QXC | C | 03/22/2004 | 1 | UTMC | | Y | UT54ACTS153UQCH | 273 |
| 5962H9655101VXA | C | 03/22/2004 | 1 | UTMC | | Y | UT54ACTS153UVAH | 273 |
| 5962H9655101VXC | C | 03/22/2004 | 1 | UTMC | | Y | UT54ACTS153UVCH | 273 |
| 5962H9655102QXA | C | 03/22/2004 | 1 | UTMC | | Y | UT54ACTS153EUQAH | 273 |
| 5962H9655102QXC | C | 03/22/2004 | 1 | UTMC | | Y | UT54ACTS153EUQCH | 273 |
| 5962H9655102VXA | C | 03/22/2004 | 1 | UTMC | | Y | UT54ACTS153EUVAH | 273 |
| 5962H9655102VXC | C | 03/22/2004 | 1 | UTMC | | Y | UT54ACTS153EUVCH | 273 |
| 5962G9655103QXA | C | 03/22/2004 | 1 | UTMC | | Y | UT54ACTS153EUQAG | 273 |
| 5962G9655103QXC | C | 03/22/2004 | 1 | UTMC | | Y | UT54ACTS153EUQCG | 273 |
| 5962G9655103VXA | C | 03/22/2004 | 1 | UTMC | | Y | UT54ACTS153EUVAG | 273 |
| 5962G9655103VXC | C | 03/22/2004 | 1 | UTMC | | Y | UT54ACTS153EUVCG | 273 |
| 5962H9655201QEA | B | 09/14/2001 | 1 | UTMC | | Y | UT54ACS157PQAH | 275 |
| 5962H9655201QEC | B | 09/14/2001 | 1 | UTMC | | Y | UT54ACS157PQCH | 275 |
| 5962H9655201VEA | B | 09/14/2001 | 1 | UTMC | | Y | UT54ACS157PVAH | 275 |
| 5962H9655201VEC | B | 09/14/2001 | 1 | UTMC | | Y | UT54ACS157PVCH | 275 |
| 5962H9655201QXA | B | 09/14/2001 | 1 | UTMC | | Y | UT54ACS157UQAH | 275 |
| 5962H9655201QXC | B | 09/14/2001 | 1 | UTMC | | Y | UT54ACS157UQCH | 275 |
| 5962H9655201VXA | B | 09/14/2001 | 1 | UTMC | | Y | UT54ACS157UVAH | 275 |
| 5962H9655201VXC | B | 09/14/2001 | 1 | UTMC | | Y | UT54ACS157UVCH | 275 |
| 5962H9655301QEA | B | 09/14/2001 | 1 | UTMC | | Y | UT54ACTS157PQAH | 275 |
| 5962H9655301QEC | B | 09/14/2001 | 1 | UTMC | | Y | UT54ACTS157PQCH | 275 |
| 5962H9655301VEA | B | 09/14/2001 | 1 | UTMC | | Y | UT54ACTS157PVAH | 275 |
| 5962H9655301VEC | B | 09/14/2001 | 1 | UTMC | | Y | UT54ACTS157PVCH | 275 |
| 5962H9655301QXA | B | 09/14/2001 | 1 | UTMC | | Y | UT54ACTS157UQAH | 275 |
| 5962H9655301QXC | B | 09/14/2001 | 1 | UTMC | | Y | UT54ACTS157UQCH | 275 |
| 5962H9655301VXA | B | 09/14/2001 | 1 | UTMC | | Y | UT54ACTS157UVAH | 275 |
| 5962H9655301VXC | B | 09/14/2001 | 1 | UTMC | | Y | UT54ACTS157UVCH | 275 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962H9655401Q9A | C | 11/01/2001 | 1 | UTMC | | Y | UT54ACS163-QDIE | 304 |
| 5962H9655401V9A | C | 11/01/2001 | 1 | UTMC | | Y | UT54ACS163-VDIE | 304 |
| 5962H9655401QEA | C | 11/01/2001 | 1 | UTMC | | Y | UT54ACS163PQAH | 304 |
| 5962H9655401QEC | C | 11/01/2001 | 1 | UTMC | | Y | UT54ACS163PQCH | 304 |
| 5962H9655401VEA | C | 11/01/2001 | 1 | UTMC | | Y | UT54ACS163PVAH | 304 |
| 5962H9655401VEC | C | 11/01/2001 | 1 | UTMC | | Y | UT54ACS163PVCH | 304 |
| 5962H9655401QXA | C | 11/01/2001 | 1 | UTMC | | Y | UT54ACS163UQAH | 304 |
| 5962H9655401QXC | C | 11/01/2001 | 1 | UTMC | | Y | UT54ACS163UQCH | 304 |
| 5962H9655401VXA | C | 11/01/2001 | 1 | UTMC | | Y | UT54ACS163UVAH | 304 |
| 5962H9655401VXC | C | 11/01/2001 | 1 | UTMC | | Y | UT54ACS163UVCH | 304 |
| 5962H9655501QEA | B | 11/01/2001 | 1 | UTMC | | Y | UT54ACTS163PQAH | 304 |
| 5962H9655501QEC | B | 11/01/2001 | 1 | UTMC | | Y | UT54ACTS163PQCH | 304 |
| 5962H9655501VEA | B | 11/01/2001 | 1 | UTMC | | Y | UT54ACTS163PVAH | 304 |
| 5962H9655501VEC | B | 11/01/2001 | 1 | UTMC | | Y | UT54ACTS163PVCH | 304 |
| 5962H9655501QXA | B | 11/01/2001 | 1 | UTMC | | Y | UT54ACTS163UQAH | 304 |
| 5962H9655501QXC | B | 11/01/2001 | 1 | UTMC | | Y | UT54ACTS163UQCH | 304 |
| 5962H9655501VXA | B | 11/01/2001 | 1 | UTMC | | Y | UT54ACTS163UVAH | 304 |
| 5962H9655501VXC | B | 11/01/2001 | 1 | UTMC | | Y | UT54ACTS163UVCH | 304 |
| 5962H9655601Q9A | D | 08/02/2004 | 1 | UTMC | | Y | UT54ACS164-QDIE | 226 |
| 5962H9655601V9A | D | 08/02/2004 | 1 | UTMC | | Y | UT54ACS164-VDIE | 226 |
| 5962H9655601QCA | D | 08/02/2004 | 1 | UTMC | | Y | UT54ACS164PQAH | 226 |
| 5962H9655601QCC | D | 08/02/2004 | 1 | UTMC | | Y | UT54ACS164PQCH | 226 |
| 5962H9655601VCA | D | 08/02/2004 | 1 | UTMC | | Y | UT54ACS164PVAH | 226 |
| 5962H9655601VCC | D | 08/02/2004 | 1 | UTMC | | Y | UT54ACS164PVCH | 226 |
| 5962H9655601QXA | D | 08/02/2004 | 1 | UTMC | | Y | UT54ACS164UQAH | 226 |
| 5962H9655601QXC | D | 08/02/2004 | 1 | UTMC | | Y | UT54ACS164UQCH | 226 |
| 5962H9655601VXA | D | 08/02/2004 | 1 | UTMC | | Y | UT54ACS164UVAH | 226 |
| 5962H9655601VXC | D | 08/02/2004 | 1 | UTMC | | Y | UT54ACS164UVCH | 226 |
| 5962H9655602Q9B | D | 08/02/2004 | 1 | UTMC | | Y | UT54ACS164E-Q-DIE | 226 |
| 5962H9655602V9B | D | 08/02/2004 | 1 | UTMC | | Y | UT54ACS164E-V-DIE | 226 |
| 5962H9655602QXA | D | 08/02/2004 | 1 | UTMC | | Y | UT54ACS164EUQAH | 226 |
| 5962H9655602QXC | D | 08/02/2004 | 1 | UTMC | | Y | UT54ACS164EUQCH | 226 |
| 5962H9655602VXA | D | 08/02/2004 | 1 | UTMC | | Y | UT54ACS164EUVAH | 226 |
| 5962H9655602VXC | D | 08/02/2004 | 1 | UTMC | | Y | UT54ACS164EUVCH | 226 |
| 5962G9655603Q9B | D | 08/02/2004 | 1 | UTMC | | Y | UT54ACS164E-Q-DIE | 226 |
| 5962G9655603V9B | D | 08/02/2004 | 1 | UTMC | | Y | UT54ACS164E-V-DIE | 226 |
| 5962G9655603QXA | D | 08/02/2004 | 1 | UTMC | | Y | UT54ACS164EUQAG | 226 |
| 5962G9655603QXC | D | 08/02/2004 | 1 | UTMC | | Y | UT54ACS164EUQCG | 226 |
| 5962G9655603VXA | D | 08/02/2004 | 1 | UTMC | | Y | UT54ACS164EUVAG | 226 |
| 5962G9655603VXC | D | 08/02/2004 | 1 | UTMC | | Y | UT54ACS164EUVCG | 226 |
| 5962H9655701QCA | C | 08/02/2004 | 1 | UTMC | | Y | UT54ACTS164PQAH | 226 |
| 5962H9655701QCC | C | 08/02/2004 | 1 | UTMC | | Y | UT54ACTS164PQCH | 226 |
| 5962H9655701VCA | C | 08/02/2004 | 1 | UTMC | | Y | UT54ACTS164PVAH | 226 |
| 5962H9655701VCC | C | 08/02/2004 | 1 | UTMC | | Y | UT54ACTS164PVCH | 226 |
| 5962H9655701QXA | C | 08/02/2004 | 1 | UTMC | | Y | UT54ACTS164UQAH | 226 |
| 5962H9655701QXC | C | 08/02/2004 | 1 | UTMC | | Y | UT54ACTS164UQCH | 226 |
| 5962H9655701VXA | C | 08/02/2004 | 1 | UTMC | | Y | UT54ACTS164UVAH | 226 |
| 5962H9655701VXC | C | 08/02/2004 | 1 | UTMC | | Y | UT54ACTS164UVCH | 226 |
| 5962H9655702QXA | C | 08/02/2004 | 1 | UTMC | | Y | UT54ACTS164EUQAH | 226 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962H9655702QXC | C | 08/02/2004 | 1 | UTMC | | Y | UT54ACTS164EUQCH | 226 |
| 5962H9655702VXA | C | 08/02/2004 | 1 | UTMC | | Y | UT54ACTS164EUVAH | 226 |
| 5962H9655702VXC | C | 08/02/2004 | 1 | UTMC | | Y | UT54ACTS164EUVCH | 226 |
| 5962G9655703QXA | C | 08/02/2004 | 1 | UTMC | | Y | UT54ACTS164EUQAG | 226 |
| 5962G9655703QXC | C | 08/02/2004 | 1 | UTMC | | Y | UT54ACTS164EUQCG | 226 |
| 5962G9655703VXA | C | 08/02/2004 | 1 | UTMC | | Y | UT54ACTS164EUVAG | 226 |
| 5962G9655703VXC | C | 08/02/2004 | 1 | UTMC | | Y | UT54ACTS164EUVCG | 226 |
| 5962H9655801QEA | C | 05/26/2004 | 1 | UTMC | | Y | UT54ACS165PQAH | 225 |
| 5962H9655801QEC | C | 05/26/2004 | 1 | UTMC | | Y | UT54ACS165PQCH | 225 |
| 5962H9655801VEA | C | 05/26/2004 | 1 | UTMC | | Y | UT54ACS165PVAH | 225 |
| 5962H9655801VEC | C | 05/26/2004 | 1 | UTMC | | Y | UT54ACS165PVCH | 225 |
| 5962H9655801QXA | C | 05/26/2004 | 1 | UTMC | | Y | UT54ACS165UQAH | 225 |
| 5962H9655801QXC | C | 05/26/2004 | 1 | UTMC | | Y | UT54ACS165UQCH | 225 |
| 5962H9655801VXA | C | 05/26/2004 | 1 | UTMC | | Y | UT54ACS165UVAH | 225 |
| 5962H9655801VXC | C | 05/26/2004 | 1 | UTMC | | Y | UT54ACS165UVCH | 225 |
| 5962H9655802QXA | C | 05/26/2004 | 1 | UTMC | | Y | UT54ACS165EUQAH | 225 |
| 5962H9655802QXC | C | 05/26/2004 | 1 | UTMC | | Y | UT54ACS165EUQCH | 225 |
| 5962H9655802VXA | C | 05/26/2004 | 1 | UTMC | | Y | UT54ACS165EUVAH | 225 |
| 5962H9655802VXC | C | 05/26/2004 | 1 | UTMC | | Y | UT54ACS165EUVCH | 225 |
| 5962G9655803QXA | C | 05/26/2004 | 1 | UTMC | | Y | UT54ACS165EUQAG | 225 |
| 5962G9655803QXC | C | 05/26/2004 | 1 | UTMC | | Y | UT54ACS165EUQCG | 225 |
| 5962G9655803VXA | C | 05/26/2004 | 1 | UTMC | | Y | UT54ACS165EUVAG | 225 |
| 5962G9655803VXC | C | 05/26/2004 | 1 | UTMC | | Y | UT54ACS165EUVCG | 225 |
| 5962H9655901QEA | B | 11/01/2001 | 1 | UTMC | | Y | UT54ACTS165PQAH | 225 |
| 5962H9655901QEC | B | 11/01/2001 | 1 | UTMC | | Y | UT54ACTS165PQCH | 225 |
| 5962H9655901VEA | B | 11/01/2001 | 1 | UTMC | | Y | UT54ACTS165PVAH | 225 |
| 5962H9655901VEC | B | 11/01/2001 | 1 | UTMC | | Y | UT54ACTS165PVCH | 225 |
| 5962H9655901QXA | B | 11/01/2001 | 1 | UTMC | | Y | UT54ACTS165UQAH | 225 |
| 5962H9655901QXC | B | 11/01/2001 | 1 | UTMC | | Y | UT54ACTS165UQCH | 225 |
| 5962H9655901VXA | B | 11/01/2001 | 1 | UTMC | | Y | UT54ACTS165UVAH | 225 |
| 5962H9655901VXC | B | 11/01/2001 | 1 | UTMC | | Y | UT54ACTS165UVCH | 225 |
| 5962H9656001QEA | B | 11/01/2001 | 1 | UTMC | | Y | UT54ACS169PQAH | 304 |
| 5962H9656001QEC | B | 11/01/2001 | 1 | UTMC | | Y | UT54ACS169PQCH | 304 |
| 5962H9656001VEA | B | 11/01/2001 | 1 | UTMC | | Y | UT54ACS169PVAH | 304 |
| 5962H9656001VEC | B | 11/01/2001 | 1 | UTMC | | Y | UT54ACS169PVCH | 304 |
| 5962H9656001QXA | B | 11/01/2001 | 1 | UTMC | | Y | UT54ACS169UQAH | 304 |
| 5962H9656001QXC | B | 11/01/2001 | 1 | UTMC | | Y | UT54ACS169UQCH | 304 |
| 5962H9656001VXA | B | 11/01/2001 | 1 | UTMC | | Y | UT54ACS169UVAH | 304 |
| 5962H9656001VXC | B | 11/01/2001 | 1 | UTMC | | Y | UT54ACS169UVCH | 304 |
| 5962H9656101QEA | B | 11/01/2001 | 1 | UTMC | | Y | UT54ACTS169PQAH | 304 |
| 5962H9656101QEC | B | 11/01/2001 | 1 | UTMC | | Y | UT54ACTS169PQCH | 304 |
| 5962H9656101VEA | B | 11/01/2001 | 1 | UTMC | | Y | UT54ACTS169PVAH | 304 |
| 5962H9656101VEC | B | 11/01/2001 | 1 | UTMC | | Y | UT54ACTS169PVCH | 304 |
| 5962H9656101QXA | B | 11/01/2001 | 1 | UTMC | | Y | UT54ACTS169UQAH | 304 |
| 5962H9656101QXC | B | 11/01/2001 | 1 | UTMC | | Y | UT54ACTS169UQCH | 304 |
| 5962H9656101VXA | B | 11/01/2001 | 1 | UTMC | | Y | UT54ACTS169UVAH | 304 |
| 5962H9656101VXC | B | 11/01/2001 | 1 | UTMC | | Y | UT54ACTS169UVCH | 304 |
| 5962H9656201QEA | A | 11/01/2001 | 1 | UTMC | | Y | UT54ACS190PQAH | 301 |
| 5962H9656201QEC | A | 11/01/2001 | 1 | UTMC | | Y | UT54ACS190PQCH | 301 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962H9656201VEA | A | 11/01/2001 | 1 | UTMC | | Y | UT54ACS190PVAH | 301 |
| 5962H9656201VEC | A | 11/01/2001 | 1 | UTMC | | Y | UT54ACS190PVCH | 301 |
| 5962H9656201QXA | A | 11/01/2001 | 1 | UTMC | | Y | UT54ACS190UQAH | 301 |
| 5962H9656201QXC | A | 11/01/2001 | 1 | UTMC | | Y | UT54ACS190UQCH | 301 |
| 5962H9656201VXA | A | 11/01/2001 | 1 | UTMC | | Y | UT54ACS190UVAH | 301 |
| 5962H9656201VXC | A | 11/01/2001 | 1 | UTMC | | Y | UT54ACS190UVCH | 301 |
| 5962H9656301QEA | A | 11/01/2001 | 1 | UTMC | | Y | UT54ACTS190PQAH | 301 |
| 5962H9656301QEC | A | 11/01/2001 | 1 | UTMC | | Y | UT54ACTS190PQCH | 301 |
| 5962H9656301VEA | A | 11/01/2001 | 1 | UTMC | | Y | UT54ACTS190PVAH | 301 |
| 5962H9656301VEC | A | 11/01/2001 | 1 | UTMC | | Y | UT54ACTS190PVCH | 301 |
| 5962H9656301QXA | A | 11/01/2001 | 1 | UTMC | | Y | UT54ACTS190UQAH | 301 |
| 5962H9656301QXC | A | 11/01/2001 | 1 | UTMC | | Y | UT54ACTS190UQCH | 301 |
| 5962H9656301VXA | A | 11/01/2001 | 1 | UTMC | | Y | UT54ACTS190UVAH | 301 |
| 5962H9656301VXC | A | 11/01/2001 | 1 | UTMC | | Y | UT54ACTS190UVCH | 301 |
| 5962H9656401Q9A | B | 07/18/2002 | 1 | UTMC | | Y | UT54ACS191-Q-DIE | 304 |
| 5962H9656401V9A | B | 07/18/2002 | 1 | UTMC | | Y | UT54ACS191-V-DIE | 304 |
| 5962H9656401QEA | B | 07/18/2002 | 1 | UTMC | | Y | UT54ACS191PQAH | 304 |
| 5962H9656401QEC | B | 07/18/2002 | 1 | UTMC | | Y | UT54ACS191PQCH | 304 |
| 5962H9656401VEA | B | 07/18/2002 | 1 | UTMC | | Y | UT54ACS191PVAH | 304 |
| 5962H9656401VEC | B | 07/18/2002 | 1 | UTMC | | Y | UT54ACS191PVCH | 304 |
| 5962H9656401QXA | B | 07/18/2002 | 1 | UTMC | | Y | UT54ACS191UQAH | 304 |
| 5962H9656401QXC | B | 07/18/2002 | 1 | UTMC | | Y | UT54ACS191UQCH | 304 |
| 5962H9656401VXA | B | 07/18/2002 | 1 | UTMC | | Y | UT54ACS191UVAH | 304 |
| 5962H9656401VXC | B | 07/18/2002 | 1 | UTMC | | Y | UT54ACS191UVCH | 304 |
| 5962H9656501QEA | A | 12/03/2001 | 1 | UTMC | | Y | UT54ACTS191PQAH | 304 |
| 5962H9656501QEC | A | 12/03/2001 | 1 | UTMC | | Y | UT54ACTS191PQCH | 304 |
| 5962H9656501VEA | A | 12/03/2001 | 1 | UTMC | | Y | UT54ACTS191PVAH | 304 |
| 5962H9656501VEC | A | 12/03/2001 | 1 | UTMC | | Y | UT54ACTS191PVCH | 304 |
| 5962H9656501QXA | A | 12/03/2001 | 1 | UTMC | | Y | UT54ACTS191UQAH | 304 |
| 5962H9656501QXC | A | 12/03/2001 | 1 | UTMC | | Y | UT54ACTS191UQCH | 304 |
| 5962H9656501VXA | A | 12/03/2001 | 1 | UTMC | | Y | UT54ACTS191UVAH | 304 |
| 5962H9656501VXC | A | 12/03/2001 | 1 | UTMC | | Y | UT54ACTS191UVCH | 304 |
| 5962H9656601Q9A | C | 06/21/2004 | 1 | UTMC | | Y | UT54ACS193-QDIE | 304 |
| 5962H9656601V9A | C | 06/21/2004 | 1 | UTMC | | Y | UT54ACS193-VDIE | 304 |
| 5962H9656601QEA | C | 06/21/2004 | 1 | UTMC | | Y | UT54ACS193PQAH | 304 |
| 5962H9656601QEC | C | 06/21/2004 | 1 | UTMC | | Y | UT54ACS193PQCH | 304 |
| 5962H9656601VEA | C | 06/21/2004 | 1 | UTMC | | Y | UT54ACS193PVAH | 304 |
| 5962H9656601VEC | C | 06/21/2004 | 1 | UTMC | | Y | UT54ACS193PVCH | 304 |
| 5962H9656601QXA | C | 06/21/2004 | 1 | UTMC | | Y | UT54ACS193UQAH | 304 |
| 5962H9656601QXC | C | 06/21/2004 | 1 | UTMC | | Y | UT54ACS193UQCH | 304 |
| 5962H9656601VXA | C | 06/21/2004 | 1 | UTMC | | Y | UT54ACS193UVAH | 304 |
| 5962H9656601VXC | C | 06/21/2004 | 1 | UTMC | | Y | UT54ACS193UVCH | 304 |
| 5962H9656701QEA | A | 11/20/1996 | 1 | UTMC | | Y | UT54ACTS193PQAH | 304 |
| 5962H9656701QEC | A | 11/20/1996 | 1 | UTMC | | Y | UT54ACTS193PQCH | 304 |
| 5962H9656701VEA | A | 11/20/1996 | 1 | UTMC | | Y | UT54ACTS193PVAH | 304 |
| 5962H9656701VEC | A | 11/20/1996 | 1 | UTMC | | Y | UT54ACTS193PVCH | 304 |
| 5962H9656701QXA | A | 11/20/1996 | 1 | UTMC | | Y | UT54ACTS193UQAH | 304 |
| 5962H9656701QXC | A | 11/20/1996 | 1 | UTMC | | Y | UT54ACTS193UQCH | 304 |
| 5962H9656701VXA | A | 11/20/1996 | 1 | UTMC | | Y | UT54ACTS193UVAH | 304 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962H9656701VXC | A | 11/20/1996 | 1 | UTMC | | Y | UT54ACTS193UVCH | 304 |
| 5962H9656801QRA | A | 11/19/1996 | 1 | UTMC | | Y | UT54ACS240PQAH | 529 |
| 5962H9656801QRC | A | 11/19/1996 | 1 | UTMC | | Y | UT54ACS240PQCH | 529 |
| 5962H9656801VRA | A | 11/19/1996 | 1 | UTMC | | Y | UT54ACS240PVAH | 529 |
| 5962H9656801VRC | A | 11/19/1996 | 1 | UTMC | | Y | UT54ACS240PVCH | 529 |
| 5962H9656801QXA | A | 11/19/1996 | 1 | UTMC | | Y | UT54ACS240UQAH | 529 |
| 5962H9656801QXC | A | 11/19/1996 | 1 | UTMC | | Y | UT54ACS240UQCH | 529 |
| 5962H9656801VXA | A | 11/19/1996 | 1 | UTMC | | Y | UT54ACS240UVAH | 529 |
| 5962H9656801VXC | A | 11/19/1996 | 1 | UTMC | | Y | UT54ACS240UVCH | 529 |
| 5962H9656901QRA | A | 11/19/1996 | 1 | UTMC | | Y | UT54ACTS240PQAH | 529 |
| 5962H9656901QRC | A | 11/19/1996 | 1 | UTMC | | Y | UT54ACTS240PQCH | 529 |
| 5962H9656901VRA | A | 11/19/1996 | 1 | UTMC | | Y | UT54ACTS240PVAH | 529 |
| 5962H9656901VRC | A | 11/19/1996 | 1 | UTMC | | Y | UT54ACTS240PVCH | 529 |
| 5962H9656901QXA | A | 11/19/1996 | 1 | UTMC | | Y | UT54ACTS240UQAH | 529 |
| 5962H9656901QXC | A | 11/19/1996 | 1 | UTMC | | Y | UT54ACTS240UQCH | 529 |
| 5962H9656901VXA | A | 11/19/1996 | 1 | UTMC | | Y | UT54ACTS240UVAH | 529 |
| 5962H9656901VXC | A | 11/19/1996 | 1 | UTMC | | Y | UT54ACTS240UVCH | 529 |
| 5962H9657001QRA | B | 12/21/2001 | 1 | UTMC | | Y | UT54ACS244PQAH | 529 |
| 5962H9657001QRC | B | 12/21/2001 | 1 | UTMC | | Y | UT54ACS244PQCH | 529 |
| 5962H9657001VRA | B | 12/21/2001 | 1 | UTMC | | Y | UT54ACS244PVAH | 529 |
| 5962H9657001VRC | B | 12/21/2001 | 1 | UTMC | | Y | UT54ACS244PVCH | 529 |
| 5962H9657001QXA | B | 12/21/2001 | 1 | UTMC | | Y | UT54ACS244UQAH | 529 |
| 5962H9657001QXC | B | 12/21/2001 | 1 | UTMC | | Y | UT54ACS244UQCH | 529 |
| 5962H9657001VXA | B | 12/21/2001 | 1 | UTMC | | Y | UT54ACS244UVAH | 529 |
| 5962H9657001VXC | B | 12/21/2001 | 1 | UTMC | | Y | UT54ACS244UVCH | 529 |
| 5962H9657101Q9A | B | 06/19/1997 | 1 | UTMC | | Y | UT54ACTS244-QDIE | 529 |
| 5962H9657101V9A | B | 06/19/1997 | 1 | UTMC | | Y | UT54ACTS244-VDIE | 529 |
| 5962H9657101QRA | B | 06/19/1997 | 1 | UTMC | | Y | UT54ACTS244PQAH | 529 |
| 5962H9657101QRC | B | 06/19/1997 | 1 | UTMC | | Y | UT54ACTS244PQCH | 529 |
| 5962H9657101VRA | B | 06/19/1997 | 1 | UTMC | | Y | UT54ACTS244PVAH | 529 |
| 5962H9657101VRC | B | 06/19/1997 | 1 | UTMC | | Y | UT54ACTS244PVCH | 529 |
| 5962H9657101QXA | B | 06/19/1997 | 1 | UTMC | | Y | UT54ACTS244UQAH | 529 |
| 5962H9657101QXC | B | 06/19/1997 | 1 | UTMC | | Y | UT54ACTS244UQCH | 529 |
| 5962H9657101VXA | B | 06/19/1997 | 1 | UTMC | | Y | UT54ACTS244UVAH | 529 |
| 5962H9657101VXC | B | 06/19/1997 | 1 | UTMC | | Y | UT54ACTS244UVCH | 529 |
| 5962H9657201Q9A | C | 07/12/2000 | 1 | UTMC | | Y | UT54ACS245-QDIE | 590 |
| 5962H9657201V9A | C | 07/12/2000 | 1 | UTMC | | Y | UT54ACS245-VDIE | 590 |
| 5962H9657201QRA | C | 07/12/2000 | 1 | UTMC | | Y | UT54ACS245PQAH | 590 |
| 5962H9657201QRC | C | 07/12/2000 | 1 | UTMC | | Y | UT54ACS245PQCH | 590 |
| 5962H9657201VRA | C | 07/12/2000 | 1 | UTMC | | Y | UT54ACS245PVAH | 590 |
| 5962H9657201VRC | C | 07/12/2000 | 1 | UTMC | | Y | UT54ACS245PVCH | 590 |
| 5962H9657201QXA | C | 07/12/2000 | 1 | UTMC | | Y | UT54ACS245UQAH | 590 |
| 5962H9657201QXC | C | 07/12/2000 | 1 | UTMC | | Y | UT54ACS245UQCH | 590 |
| 5962H9657201VXA | C | 07/12/2000 | 1 | UTMC | | Y | UT54ACS245UVAH | 590 |
| 5962H9657201VXC | C | 07/12/2000 | 1 | UTMC | | Y | UT54ACS245UVCH | 590 |
| 5962H9657202Q9A | C | 07/12/2000 | 1 | UTMC | | Y | UT54ACS245S-QDIE | 590 |
| 5962H9657202V9A | C | 07/12/2000 | 1 | UTMC | | Y | UT54ACS245S-VDIE | 590 |
| 5962H9657202QRA | C | 07/12/2000 | 1 | UTMC | | Y | UT54ACS245SPQAH | 590 |
| 5962H9657202QRC | C | 07/12/2000 | 1 | UTMC | | Y | UT54ACS245SPQCH | 590 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962H9657202VRA | C | 07/12/2000 | 1 | UTMC | | Y | UT54ACS245SPVAH | 590 |
| 5962H9657202VRC | C | 07/12/2000 | 1 | UTMC | | Y | UT54ACS245SPVCH | 590 |
| 5962H9657202QXA | C | 07/12/2000 | 1 | UTMC | | Y | UT54ACS245SUQAH | 590 |
| 5962H9657202QXC | C | 07/12/2000 | 1 | UTMC | | Y | UT54ACS245SUQCH | 590 |
| 5962H9657202VXA | C | 07/12/2000 | 1 | UTMC | | Y | UT54ACS245SUVAH | 590 |
| 5962H9657202VXC | C | 07/12/2000 | 1 | UTMC | | Y | UT54ACS245SUVCH | 590 |
| 5962H9657301QRA | A | 11/19/1996 | 1 | UTMC | | Y | UT54ACTS245PQAH | 590 |
| 5962H9657301QRC | A | 11/19/1996 | 1 | UTMC | | Y | UT54ACTS245PQCH | 590 |
| 5962H9657301VRA | A | 11/19/1996 | 1 | UTMC | | Y | UT54ACTS245PVAH | 590 |
| 5962H9657301VRC | A | 11/19/1996 | 1 | UTMC | | Y | UT54ACTS245PVCH | 590 |
| 5962H9657301QXA | A | 11/19/1996 | 1 | UTMC | | Y | UT54ACTS245UQAH | 590 |
| 5962H9657301QXC | A | 11/19/1996 | 1 | UTMC | | Y | UT54ACTS245UQCH | 590 |
| 5962H9657301VXA | A | 11/19/1996 | 1 | UTMC | | Y | UT54ACTS245UVAH | 590 |
| 5962H9657301VXC | A | 11/19/1996 | 1 | UTMC | | Y | UT54ACTS245UVCH | 590 |
| 5962H9657401QCA | A | 11/19/1996 | 1 | UTMC | | Y | UT54ACS253PQAH | 274 |
| 5962H9657401QCC | A | 11/19/1996 | 1 | UTMC | | Y | UT54ACS253PQCH | 274 |
| 5962H9657401VCA | A | 11/19/1996 | 1 | UTMC | | Y | UT54ACS253PVAH | 274 |
| 5962H9657401VCC | A | 11/19/1996 | 1 | UTMC | | Y | UT54ACS253PVCH | 274 |
| 5962H9657401QXA | A | 11/19/1996 | 1 | UTMC | | Y | UT54ACS253UQAH | 274 |
| 5962H9657401QXC | A | 11/19/1996 | 1 | UTMC | | Y | UT54ACS253UQCH | 274 |
| 5962H9657401VXA | A | 11/19/1996 | 1 | UTMC | | Y | UT54ACS253UVAH | 274 |
| 5962H9657401VXC | A | 11/19/1996 | 1 | UTMC | | Y | UT54ACS253UVCH | 274 |
| 5962H9657501QCA | A | 11/19/1996 | 1 | UTMC | | Y | UT54ACTS253PQAH | 274 |
| 5962H9657501QCC | A | 11/19/1996 | 1 | UTMC | | Y | UT54ACTS253PQCH | 274 |
| 5962H9657501VCA | A | 11/19/1996 | 1 | UTMC | | Y | UT54ACTS253PVAH | 274 |
| 5962H9657501VCC | A | 11/19/1996 | 1 | UTMC | | Y | UT54ACTS253PVCH | 274 |
| 5962H9657501QXA | A | 11/19/1996 | 1 | UTMC | | Y | UT54ACTS253UQAH | 274 |
| 5962H9657501QXC | A | 11/19/1996 | 1 | UTMC | | Y | UT54ACTS253UQCH | 274 |
| 5962H9657501VXA | A | 11/19/1996 | 1 | UTMC | | Y | UT54ACTS253UVAH | 274 |
| 5962H9657501VXC | A | 11/19/1996 | 1 | UTMC | | Y | UT54ACTS253UVCH | 274 |
| 5962H9657601QEA | | 02/21/1997 | 1 | UTMC | | Y | UT54ACS264PQAH | 206 |
| 5962H9657601QEC | | 02/21/1997 | 1 | UTMC | | Y | UT54ACS264PQCH | 206 |
| 5962H9657601VEA | | 02/21/1997 | 1 | UTMC | | Y | UT54ACS264PVAH | 206 |
| 5962H9657601VEC | | 02/21/1997 | 1 | UTMC | | Y | UT54ACS264PVCH | 206 |
| 5962H9657601QXA | | 02/21/1997 | 1 | UTMC | | Y | UT54ACS264UQAH | 206 |
| 5962H9657601QXC | | 02/21/1997 | 1 | UTMC | | Y | UT54ACS264UQCH | 206 |
| 5962H9657601VXA | | 02/21/1997 | 1 | UTMC | | Y | UT54ACS264UVAH | 206 |
| 5962H9657601VXC | | 02/21/1997 | 1 | UTMC | | Y | UT54ACS264UVCH | 206 |
| 5962H9657701QEA | | 12/20/1996 | 1 | UTMC | | Y | UT54ACTS264PQAH | 206 |
| 5962H9657701QEC | | 12/20/1996 | 1 | UTMC | | Y | UT54ACTS264PQCH | 206 |
| 5962H9657701VEA | | 12/20/1996 | 1 | UTMC | | Y | UT54ACTS264PVAH | 206 |
| 5962H9657701VEC | | 12/20/1996 | 1 | UTMC | | Y | UT54ACTS264PVCH | 206 |
| 5962H9657701QXA | | 12/20/1996 | 1 | UTMC | | Y | UT54ACTS264UQAH | 206 |
| 5962H9657701QXC | | 12/20/1996 | 1 | UTMC | | Y | UT54ACTS264UQCH | 206 |
| 5962H9657701VXA | | 12/20/1996 | 1 | UTMC | | Y | UT54ACTS264UVAH | 206 |
| 5962H9657701VXC | | 12/20/1996 | 1 | UTMC | | Y | UT54ACTS264UVCH | 206 |
| 5962H9657801QRA | A | 11/18/1996 | 1 | UTMC | | Y | UT54ACS273PQAH | 159 |
| 5962H9657801QRC | A | 11/18/1996 | 1 | UTMC | | Y | UT54ACS273PQCH | 159 |
| 5962H9657801VRA | A | 11/18/1996 | 1 | UTMC | | Y | UT54ACS273PVAH | 159 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962H9657801VRC | A | 11/18/1996 | 1 | UTMC | | Y | UT54ACS273PVCH | 159 |
| 5962H9657801QXA | A | 11/18/1996 | 1 | UTMC | | Y | UT54ACS273UQAH | 159 |
| 5962H9657801QXC | A | 11/18/1996 | 1 | UTMC | | Y | UT54ACS273UQCH | 159 |
| 5962H9657801VXA | A | 11/18/1996 | 1 | UTMC | | Y | UT54ACS273UVAH | 159 |
| 5962H9657801VXC | A | 11/18/1996 | 1 | UTMC | | Y | UT54ACS273UVCH | 159 |
| 5962H9657901QRA | A | 11/18/1996 | 1 | UTMC | | Y | UT54ACTS273PQAH | 159 |
| 5962H9657901QRC | A | 11/18/1996 | 1 | UTMC | | Y | UT54ACTS273PQCH | 159 |
| 5962H9657901VRA | A | 11/18/1996 | 1 | UTMC | | Y | UT54ACTS273PVAH | 159 |
| 5962H9657901VRC | A | 11/18/1996 | 1 | UTMC | | Y | UT54ACTS273PVCH | 159 |
| 5962H9657901QXA | A | 11/18/1996 | 1 | UTMC | | Y | UT54ACTS273UQAH | 159 |
| 5962H9657901QXC | A | 11/18/1996 | 1 | UTMC | | Y | UT54ACTS273UQCH | 159 |
| 5962H9657901VXA | A | 11/18/1996 | 1 | UTMC | | Y | UT54ACTS273UVAH | 159 |
| 5962H9657901VXC | A | 11/18/1996 | 1 | UTMC | | Y | UT54ACTS273UVCH | 159 |
| 5962H9658001QEA | A | 11/18/1996 | 1 | UTMC | | Y | UT54ACS279PQAH | 340 |
| 5962H9658001QEC | A | 11/18/1996 | 1 | UTMC | | Y | UT54ACS279PQCH | 340 |
| 5962H9658001VEA | A | 11/18/1996 | 1 | UTMC | | Y | UT54ACS279PVAH | 340 |
| 5962H9658001VEC | A | 11/18/1996 | 1 | UTMC | | Y | UT54ACS279PVCH | 340 |
| 5962H9658001QXA | A | 11/18/1996 | 1 | UTMC | | Y | UT54ACS279UQAH | 340 |
| 5962H9658001QXC | A | 11/18/1996 | 1 | UTMC | | Y | UT54ACS279UQCH | 340 |
| 5962H9658001VXA | A | 11/18/1996 | 1 | UTMC | | Y | UT54ACS279UVAH | 340 |
| 5962H9658001VXC | A | 11/18/1996 | 1 | UTMC | | Y | UT54ACS279UVCH | 340 |
| 5962H9658101QEA | A | 11/18/1996 | 1 | UTMC | | Y | UT54ACTS279PQAH | 340 |
| 5962H9658101QEC | A | 11/18/1996 | 1 | UTMC | | Y | UT54ACTS279PQCH | 340 |
| 5962H9658101VEA | A | 11/18/1996 | 1 | UTMC | | Y | UT54ACTS279PVAH | 340 |
| 5962H9658101VEC | A | 11/18/1996 | 1 | UTMC | | Y | UT54ACTS279PVCH | 340 |
| 5962H9658101QXA | A | 11/18/1996 | 1 | UTMC | | Y | UT54ACTS279UQAH | 340 |
| 5962H9658101QXC | A | 11/18/1996 | 1 | UTMC | | Y | UT54ACTS279UQCH | 340 |
| 5962H9658101VXA | A | 11/18/1996 | 1 | UTMC | | Y | UT54ACTS279UVAH | 340 |
| 5962H9658101VXC | A | 11/18/1996 | 1 | UTMC | | Y | UT54ACTS279UVCH | 340 |
| 5962H9658201QCA | A | 11/18/1996 | 1 | UTMC | | Y | UT54ACS280PQAH | 210 |
| 5962H9658201QCC | A | 11/18/1996 | 1 | UTMC | | Y | UT54ACS280PQCH | 210 |
| 5962H9658201VCA | A | 11/18/1996 | 1 | UTMC | | Y | UT54ACS280PVAH | 210 |
| 5962H9658201VCC | A | 11/18/1996 | 1 | UTMC | | Y | UT54ACS280PVCH | 210 |
| 5962H9658201QXA | A | 11/18/1996 | 1 | UTMC | | Y | UT54ACS280UQAH | 210 |
| 5962H9658201QXC | A | 11/18/1996 | 1 | UTMC | | Y | UT54ACS280UQCH | 210 |
| 5962H9658201VXA | A | 11/18/1996 | 1 | UTMC | | Y | UT54ACS280UVAH | 210 |
| 5962H9658201VXC | A | 11/18/1996 | 1 | UTMC | | Y | UT54ACS280UVCH | 210 |
| 5962H9658301QCA | A | 11/18/1996 | 1 | UTMC | | Y | UT54ACTS280PQAH | 210 |
| 5962H9658301QCC | A | 11/18/1996 | 1 | UTMC | | Y | UT54ACTS280PQCH | 210 |
| 5962H9658301VCA | A | 11/18/1996 | 1 | UTMC | | Y | UT54ACTS280PVAH | 210 |
| 5962H9658301VCC | A | 11/18/1996 | 1 | UTMC | | Y | UT54ACTS280PVCH | 210 |
| 5962H9658301QXA | A | 11/18/1996 | 1 | UTMC | | Y | UT54ACTS280UQAH | 210 |
| 5962H9658301QXC | A | 11/18/1996 | 1 | UTMC | | Y | UT54ACTS280UQCH | 210 |
| 5962H9658301VXA | A | 11/18/1996 | 1 | UTMC | | Y | UT54ACTS280UVAH | 210 |
| 5962H9658301VXC | A | 11/18/1996 | 1 | UTMC | | Y | UT54ACTS280UVCH | 210 |
| 5962H9658401QEA | | 11/18/1996 | 1 | UTMC | | Y | UT54ACS283PQAH | 202 |
| 5962H9658401QEC | | 11/18/1996 | 1 | UTMC | | Y | UT54ACS283PQCH | 202 |
| 5962H9658401VEA | | 11/18/1996 | 1 | UTMC | | Y | UT54ACS283PVAH | 202 |
| 5962H9658401VEC | | 11/18/1996 | 1 | UTMC | | Y | UT54ACS283PVCH | 202 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962H9658401QXA | | 11/18/1996 | 1 | UTMC | | Y | UT54ACS283UQAH | 202 |
| 5962H9658401QXC | | 11/18/1996 | 1 | UTMC | | Y | UT54ACS283UQCH | 202 |
| 5962H9658401VXA | | 11/18/1996 | 1 | UTMC | | Y | UT54ACS283UVAH | 202 |
| 5962H9658401VXC | | 11/18/1996 | 1 | UTMC | | Y | UT54ACS283UVCH | 202 |
| 5962H9658501QEA | | 12/20/1996 | 1 | UTMC | | Y | UT54ACTS283PQAH | 202 |
| 5962H9658501QEC | | 12/20/1996 | 1 | UTMC | | Y | UT54ACTS283PQCH | 202 |
| 5962H9658501VEA | | 12/20/1996 | 1 | UTMC | | Y | UT54ACTS283PVAH | 202 |
| 5962H9658501VEC | | 12/20/1996 | 1 | UTMC | | Y | UT54ACTS283PVCH | 202 |
| 5962H9658501QXA | | 12/20/1996 | 1 | UTMC | | Y | UT54ACTS283UQAH | 202 |
| 5962H9658501QXC | | 12/20/1996 | 1 | UTMC | | Y | UT54ACTS283UQCH | 202 |
| 5962H9658501VXA | | 12/20/1996 | 1 | UTMC | | Y | UT54ACTS283UVAH | 202 |
| 5962H9658501VXC | | 12/20/1996 | 1 | UTMC | | Y | UT54ACTS283UVCH | 202 |
| 5962H9658601QEA | | 12/20/1996 | 1 | UTMC | | Y | UT54ACS365PQAH | 522 |
| 5962H9658601QEC | | 12/20/1996 | 1 | UTMC | | Y | UT54ACS365PQCH | 522 |
| 5962H9658601VEA | | 12/20/1996 | 1 | UTMC | | Y | UT54ACS365PVAH | 522 |
| 5962H9658601VEC | | 12/20/1996 | 1 | UTMC | | Y | UT54ACS365PVCH | 522 |
| 5962H9658601QXA | | 12/20/1996 | 1 | UTMC | | Y | UT54ACS365UQAH | 522 |
| 5962H9658601QXC | | 12/20/1996 | 1 | UTMC | | Y | UT54ACS365UQCH | 522 |
| 5962H9658601VXA | | 12/20/1996 | 1 | UTMC | | Y | UT54ACS365UVAH | 522 |
| 5962H9658601VXC | | 12/20/1996 | 1 | UTMC | | Y | UT54ACS365UVCH | 522 |
| 5962H9658701QEA | | 12/20/1996 | 1 | UTMC | | Y | UT54ACTS365PQAH | 522 |
| 5962H9658701QEC | | 12/20/1996 | 1 | UTMC | | Y | UT54ACTS365PQCH | 522 |
| 5962H9658701VEA | | 12/20/1996 | 1 | UTMC | | Y | UT54ACTS365PVAH | 522 |
| 5962H9658701VEC | | 12/20/1996 | 1 | UTMC | | Y | UT54ACTS365PVCH | 522 |
| 5962H9658701QXA | | 12/20/1996 | 1 | UTMC | | Y | UT54ACTS365UQAH | 522 |
| 5962H9658701QXC | | 12/20/1996 | 1 | UTMC | | Y | UT54ACTS365UQCH | 522 |
| 5962H9658701VXA | | 12/20/1996 | 1 | UTMC | | Y | UT54ACTS365UVAH | 522 |
| 5962H9658701VXC | | 12/20/1996 | 1 | UTMC | | Y | UT54ACTS365UVCH | 522 |
| 5962H9658801QRA | A | 11/19/1996 | 1 | UTMC | | Y | UT54ACS373PQAH | 341 |
| 5962H9658801QRC | A | 11/19/1996 | 1 | UTMC | | Y | UT54ACS373PQCH | 341 |
| 5962H9658801VRA | A | 11/19/1996 | 1 | UTMC | | Y | UT54ACS373PVAH | 341 |
| 5962H9658801VRC | A | 11/19/1996 | 1 | UTMC | | Y | UT54ACS373PVCH | 341 |
| 5962H9658801QXA | A | 11/19/1996 | 1 | UTMC | | Y | UT54ACS373UQAH | 341 |
| 5962H9658801QXC | A | 11/19/1996 | 1 | UTMC | | Y | UT54ACS373UQCH | 341 |
| 5962H9658801VXA | A | 11/19/1996 | 1 | UTMC | | Y | UT54ACS373UVAH | 341 |
| 5962H9658801VXC | A | 11/19/1996 | 1 | UTMC | | Y | UT54ACS373UVCH | 341 |
| 5962H9658901QRA | A | 11/19/1996 | 1 | UTMC | | Y | UT54ACTS373PQAH | 341 |
| 5962H9658901QRC | A | 11/19/1996 | 1 | UTMC | | Y | UT54ACTS373PQCH | 341 |
| 5962H9658901VRA | A | 11/19/1996 | 1 | UTMC | | Y | UT54ACTS373PVAH | 341 |
| 5962H9658901VRC | A | 11/19/1996 | 1 | UTMC | | Y | UT54ACTS373PVCH | 341 |
| 5962H9658901QXA | A | 11/19/1996 | 1 | UTMC | | Y | UT54ACTS373UQAH | 341 |
| 5962H9658901QXC | A | 11/19/1996 | 1 | UTMC | | Y | UT54ACTS373UQCH | 341 |
| 5962H9658901VXA | A | 11/19/1996 | 1 | UTMC | | Y | UT54ACTS373UVAH | 341 |
| 5962H9658901VXC | A | 11/19/1996 | 1 | UTMC | | Y | UT54ACTS373UVCH | 341 |
| 5962H9659001Q9A | B | 05/06/1997 | 1 | UTMC | | Y | UT54ACS374-QDIE | 159 |
| 5962H9659001V9A | B | 05/06/1997 | 1 | UTMC | | Y | UT54ACS374-VDIE | 159 |
| 5962H9659001QRA | B | 05/06/1997 | 1 | UTMC | | Y | UT54ACS374PQAH | 159 |
| 5962H9659001QRC | B | 05/06/1997 | 1 | UTMC | | Y | UT54ACS374PQCH | 159 |
| 5962H9659001VRA | B | 05/06/1997 | 1 | UTMC | | Y | UT54ACS374PVAH | 159 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962H9659001VRC | B | 05/06/1997 | 1 | UTMC | | Y | UT54ACS374PVCH | 159 |
| 5962H9659001QXA | B | 05/06/1997 | 1 | UTMC | | Y | UT54ACS374UQAH | 159 |
| 5962H9659001QXC | B | 05/06/1997 | 1 | UTMC | | Y | UT54ACS374UQCH | 159 |
| 5962H9659001VXA | B | 05/06/1997 | 1 | UTMC | | Y | UT54ACS374UVAH | 159 |
| 5962H9659001VXC | B | 05/06/1997 | 1 | UTMC | | Y | UT54ACS374UVCH | 159 |
| 5962H9659101QRA | A | 11/20/1996 | 1 | UTMC | | Y | UT54ACTS374PQAH | 159 |
| 5962H9659101QRC | A | 11/20/1996 | 1 | UTMC | | Y | UT54ACTS374PQCH | 159 |
| 5962H9659101VRA | A | 11/20/1996 | 1 | UTMC | | Y | UT54ACTS374PVAH | 159 |
| 5962H9659101VRC | A | 11/20/1996 | 1 | UTMC | | Y | UT54ACTS374PVCH | 159 |
| 5962H9659101QXA | A | 11/20/1996 | 1 | UTMC | | Y | UT54ACTS374UQAH | 159 |
| 5962H9659101QXC | A | 11/20/1996 | 1 | UTMC | | Y | UT54ACTS374UQCH | 159 |
| 5962H9659101VXA | A | 11/20/1996 | 1 | UTMC | | Y | UT54ACTS374UVAH | 159 |
| 5962H9659101VXC | A | 11/20/1996 | 1 | UTMC | | Y | UT54ACTS374UVCH | 159 |
| 5962H9659201QCA | A | 11/20/1996 | 1 | UTMC | | Y | UT54ACS540PQAH | 529 |
| 5962H9659201QCC | A | 11/20/1996 | 1 | UTMC | | Y | UT54ACS540PQCH | 529 |
| 5962H9659201VCA | A | 11/20/1996 | 1 | UTMC | | Y | UT54ACS540PVAH | 529 |
| 5962H9659201VCC | A | 11/20/1996 | 1 | UTMC | | Y | UT54ACS540PVCH | 529 |
| 5962H9659201QXA | A | 11/20/1996 | 1 | UTMC | | Y | UT54ACS540UQAH | 529 |
| 5962H9659201QXC | A | 11/20/1996 | 1 | UTMC | | Y | UT54ACS540UQCH | 529 |
| 5962H9659201VXA | A | 11/20/1996 | 1 | UTMC | | Y | UT54ACS540UVAH | 529 |
| 5962H9659201VXC | A | 11/20/1996 | 1 | UTMC | | Y | UT54ACS540UVCH | 529 |
| 5962H9659301QRA | A | 11/20/1996 | 1 | UTMC | | Y | UT54ACTS540PQAH | 529 |
| 5962H9659301QRC | A | 11/20/1996 | 1 | UTMC | | Y | UT54ACTS540PQCH | 529 |
| 5962H9659301VRA | A | 11/20/1996 | 1 | UTMC | | Y | UT54ACTS540PVAH | 529 |
| 5962H9659301VRC | A | 11/20/1996 | 1 | UTMC | | Y | UT54ACTS540PVCH | 529 |
| 5962H9659301QXA | A | 11/20/1996 | 1 | UTMC | | Y | UT54ACTS540UQAH | 529 |
| 5962H9659301QXC | A | 11/20/1996 | 1 | UTMC | | Y | UT54ACTS540UQCH | 529 |
| 5962H9659301VXA | A | 11/20/1996 | 1 | UTMC | | Y | UT54ACTS540UVAH | 529 |
| 5962H9659301VXC | A | 11/20/1996 | 1 | UTMC | | Y | UT54ACTS540UVCH | 529 |
| 5962H9659401QRA | A | 11/20/1996 | 1 | UTMC | | Y | UT54ACS541PQAH | 529 |
| 5962H9659401QRC | A | 11/20/1996 | 1 | UTMC | | Y | UT54ACS541PQCH | 529 |
| 5962H9659401VRA | A | 11/20/1996 | 1 | UTMC | | Y | UT54ACS541PVAH | 529 |
| 5962H9659401VRC | A | 11/20/1996 | 1 | UTMC | | Y | UT54ACS541PVCH | 529 |
| 5962H9659401QXA | A | 11/20/1996 | 1 | UTMC | | Y | UT54ACS541UQAH | 529 |
| 5962H9659401QXC | A | 11/20/1996 | 1 | UTMC | | Y | UT54ACS541UQCH | 529 |
| 5962H9659401VXA | A | 11/20/1996 | 1 | UTMC | | Y | UT54ACS541UVAH | 529 |
| 5962H9659401VXC | A | 11/20/1996 | 1 | UTMC | | Y | UT54ACS541UVCH | 529 |
| 5962H9659501QRA | C | 08/02/2004 | | (NONE) | | | 54ACTS541 (GEN) | 529 |
| 5962H9659501VRA | C | 08/02/2004 | | (NONE) | | | 54ACTS541 (GEN) | 529 |
| 5962G9659501QXA | C | 08/02/2004 | 1 | UTMC | | Y | UT54ACTS541UQAG | 529 |
| 5962G9659501QXC | C | 08/02/2004 | 1 | UTMC | | Y | UT54ACTS541UQCG | 529 |
| 5962G9659501VXA | C | 08/02/2004 | 1 | UTMC | | Y | UT54ACTS541UVAG | 529 |
| 5962G9659501VXC | C | 08/02/2004 | 1 | UTMC | | Y | UT54ACTS541UVCG | 529 |
| 5962H9659501QXA | C | 08/02/2004 | | (NONE) | | | 54ACTS541 (GEN) | 529 |
| 5962H9659501VXA | C | 08/02/2004 | | (NONE) | | | 54ACTS541 (GEN) | 529 |
| 5962H9659502QXA | C | 08/02/2004 | 1 | UTMC | | Y | UT54ACTS541EUQAH | 529 |
| 5962H9659502QXC | C | 08/02/2004 | 1 | UTMC | | Y | UT54ACTS541EUQCH | 529 |
| 5962H9659502VXA | C | 08/02/2004 | 1 | UTMC | | Y | UT54ACTS541EUVAH | 529 |
| 5962H9659502VXC | C | 08/02/2004 | 1 | UTMC | | Y | UT54ACTS541EUVCH | 529 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962G9659503QXA | C | 08/02/2004 | 1 | UTMC | | Y | UT54ACTS541EUQAG | 529 |
| 5962G9659503QXC | C | 08/02/2004 | 1 | UTMC | | Y | UT54ACTS541EUQCG | 529 |
| 5962G9659503VXA | C | 08/02/2004 | 1 | UTMC | | Y | UT54ACTS541EUVAG | 529 |
| 5962G9659503VXC | C | 08/02/2004 | 1 | UTMC | | Y | UT54ACTS541EUVCG | 529 |
| 5962H9659601QCA | A | 11/20/1996 | 1 | UTMC | | Y | UT54ACS4002PQAH | 123 |
| 5962H9659601QCC | A | 11/20/1996 | 1 | UTMC | | Y | UT54ACS4002PQCH | 123 |
| 5962H9659601VCA | A | 11/20/1996 | 1 | UTMC | | Y | UT54ACS4002PVAH | 123 |
| 5962H9659601VCC | A | 11/20/1996 | 1 | UTMC | | Y | UT54ACS4002PVCH | 123 |
| 5962H9659601QXA | A | 11/20/1996 | 1 | UTMC | | Y | UT54ACS4002UQAH | 123 |
| 5962H9659601QXC | A | 11/20/1996 | 1 | UTMC | | Y | UT54ACS4002UQCH | 123 |
| 5962H9659601VXA | A | 11/20/1996 | 1 | UTMC | | Y | UT54ACS4002UVAH | 123 |
| 5962H9659601VXC | A | 11/20/1996 | 1 | UTMC | | Y | UT54ACTS4002UVCH | 123 |
| 5962H9659601VXC | A | 11/20/1996 | 1 | UTMC | | Y | UT54ACS4002UVCH | 123 |
| 5962H9659701QCA | A | 11/20/1996 | 1 | UTMC | | Y | UT54ACTS4002PQAH | 123 |
| 5962H9659701QCC | A | 11/20/1996 | 1 | UTMC | | Y | UT54ACTS4002PQCH | 123 |
| 5962H9659701VCA | A | 11/20/1996 | 1 | UTMC | | Y | UT54ACTS4002PVAH | 123 |
| 5962H9659701VCC | A | 11/20/1996 | 1 | UTMC | | Y | UT54ACTS4002PVCH | 123 |
| 5962H9659701QXA | A | 11/20/1996 | 1 | UTMC | | Y | UT54ACTS4002UQAH | 123 |
| 5962H9659701QXC | A | 11/20/1996 | 1 | UTMC | | Y | UT54ACTS4002UQCH | 123 |
| 5962H9659701VXA | A | 11/20/1996 | 1 | UTMC | | Y | UT54ACTS4002UVAH | 123 |
| 5962R9659801V9A | C | 07/24/1997 | | (NONE) | | | 40100B (GEN) | 232 |
| 5962R9659801VEC | C | 07/24/1997 | | (NONE) | | | 40100B (GEN) | 232 |
| 5962R9659801VXC | C | 07/24/1997 | | (NONE) | | | 40100B (GEN) | 232 |
| 5962R9659901V9A | B | 07/24/1997 | | (NONE) | | | 40101B (GEN) | 210 |
| 5962R9659901VCC | B | 07/24/1997 | | (NONE) | | | 40101B (GEN) | 210 |
| 5962R9659901VXC | B | 07/24/1997 | | (NONE) | | | 40101B (GEN) | 210 |
| 5962R9660001V9A | A | 06/10/1998 | | (NONE) | | | 40102B (GEN) | 301 |
| 5962R9660001VEC | A | 06/10/1998 | | (NONE) | | | 40102B (GEN) | 301 |
| 5962R9660001VXC | A | 06/10/1998 | | (NONE) | | | 40102B (GEN) | 301 |
| 5962R9660002V9A | A | 06/10/1998 | | (NONE) | | | 40103B (GEN) | 304 |
| 5962R9660002VEC | A | 06/10/1998 | | (NONE) | | | 40103B (GEN) | 304 |
| 5962R9660002VXC | A | 06/10/1998 | | (NONE) | | | 40103B (GEN) | 304 |
| 5962R9660101V9A | A | 12/09/1997 | | (NONE) | | | 40104B (GEN) | 220 |
| 5962R9660101VEC | A | 12/09/1997 | | (NONE) | | | 40104B (GEN) | 220 |
| 5962R9660101VXC | A | 12/09/1997 | | (NONE) | | | 40104B (GEN) | 220 |
| 5962R9660102V9A | A | 12/09/1997 | | (NONE) | | | 40194B (GEN) | 220 |
| 5962R9660102VEC | A | 12/09/1997 | | (NONE) | | | 40194B (GEN) | 220 |
| 5962R9660102VXC | A | 12/09/1997 | | (NONE) | | | 40194B (GEN) | 220 |
| 5962R9660201V9A | C | 09/12/2003 | | (NONE) | | | 40105B (GEN) | 670 |
| 5962R9660201VEC | C | 09/12/2003 | 1 | INTERSIL | | Y | CD40105BDMSR | 670 |
| 5962R9660201VXC | C | 09/12/2003 | 1 | INTERSIL | | Y | CD40105BKMSR | 670 |
| 5962R9660202V9A | C | 09/12/2003 | | (NONE) | | | 40105BN (GEN) | 670 |
| 5962R9660202VEC | C | 09/12/2003 | | (NONE) | | | 40105BN (GEN) | 670 |
| 5962R9660202VXC | C | 09/12/2003 | | (NONE) | | | 40105BN (GEN) | 670 |
| 5962R9660301V9A | D | 04/15/2004 | | (NONE) | | | 40106B (GEN) | 541 |
| 5962R9660301VCC | D | 04/15/2004 | 1 | INTERSIL | | Y | CD40106BDMSR | 541 |
| 5962R9660301VXC | D | 04/15/2004 | 1 | INTERSIL | | Y | CD40106BKMSR | 541 |
| 5962R9660302V9A | D | 04/15/2004 | | (NONE) | | | 40106BN (GEN) | 541 |
| 5962R9660302VCC | D | 04/15/2004 | | (NONE) | | | 40106BN (GEN) | 541 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962R9660302VXC | D | 04/15/2004 | 1 | INTERSIL | | Y | CD40106BKNSR | 541 |
| 5962R9660401V9A | A | 03/13/1998 | | (NONE) | | | 40147B (GEN) | 345 |
| 5962R9660401VEC | A | 03/13/1998 | | (NONE) | | | 40147B (GEN) | 345 |
| 5962R9660401VXC | A | 03/13/1998 | | (NONE) | | | 40147B (GEN) | 345 |
| 5962R9660501V9A | C | 11/18/2003 | | (NONE) | | | 40174B (GEN) | 159 |
| 5962R9660501VEC | C | 11/18/2003 | 1 | INTERSIL | | Y | CD40174BDMSR | 159 |
| 5962R9660501VXC | C | 11/18/2003 | 1 | INTERSIL | | Y | CD40174BKMSR | 159 |
| 5962R9660502V9A | C | 11/18/2003 | | (NONE) | | | 40174BN (GEN) | 159 |
| 5962R9660502VEC | C | 11/18/2003 | | (NONE) | | | 40174BN (GEN) | 159 |
| 5962R9660502VXC | C | 11/18/2003 | | (NONE) | | | 40174BN (GEN) | 159 |
| 5962R9660601V9A | B | 08/18/1997 | | (NONE) | | | 40175B (GEN) | 159 |
| 5962R9660601VEC | B | 08/18/1997 | | (NONE) | | | 40175B (GEN) | 159 |
| 5962R9660601VXC | B | 08/18/1997 | | (NONE) | | | 40175B (GEN) | 159 |
| 5962R9660701V9A | B | 07/24/1997 | | (NONE) | | | 40182B (GEN) | 206 |
| 5962R9660701VEC | B | 07/24/1997 | | (NONE) | | | 40182B (GEN) | 206 |
| 5962R9660701VXC | B | 07/24/1997 | | (NONE) | | | 40182B (GEN) | 206 |
| 5962R9660801V9A | C | 10/16/2003 | | (NONE) | | | 40192B (GEN) | 301 |
| 5962R9660801VEC | C | 10/16/2003 | | (NONE) | | | 40192B (GEN) | 301 |
| 5962R9660801VXC | C | 10/16/2003 | | (NONE) | | | 40192B (GEN) | 301 |
| 5962R9660802V9A | C | 10/16/2003 | 1 | INTERSIL | | Y | CD40193BHSR | 304 |
| 5962R9660802VEC | C | 10/16/2003 | 1 | INTERSIL | | Y | CD40193BDMSR | 304 |
| 5962R9660802VXC | C | 10/16/2003 | 1 | INTERSIL | | Y | CD40193BKMSR | 304 |
| 5962R9660901V9A | C | 10/16/2003 | | (NONE) | | | 4060B (GEN) | 305 |
| 5962R9660901VEC | C | 10/16/2003 | 1 | INTERSIL | | Y | CD4060BDMSR | 305 |
| 5962R9660901VXC | C | 10/16/2003 | 1 | INTERSIL | | Y | CD4060BKMSR | 305 |
| 5962R9661001V9A | B | 07/25/1997 | | (NONE) | | | 4068B (GEN) | 106 |
| 5962R9661001VCC | B | 07/25/1997 | | (NONE) | | | 4068B (GEN) | 106 |
| 5962R9661001VXC | B | 07/25/1997 | | (NONE) | | | 4068B (GEN) | 106 |
| 5962R9661002V9A | B | 07/25/1997 | | (NONE) | | | 4068BN (GEN) | 106 |
| 5962R9661002VCC | B | 07/25/1997 | | (NONE) | | | 4068BN (GEN) | 106 |
| 5962R9661002VXC | B | 07/25/1997 | | (NONE) | | | 4068BN (GEN) | 106 |
| 5962R9661101V9A | C | 02/02/2004 | | (NONE) | | | 4070B (GEN) | 140 |
| 5962R9661101VCC | C | 02/02/2004 | 1 | INTERSIL | | Y | CD4070BDMSR | 140 |
| 5962R9661101VXC | C | 02/02/2004 | 1 | INTERSIL | | Y | CD4070BKMSR | 140 |
| 5962R9661102V9A | C | 02/02/2004 | | (NONE) | | | 4077B (GEN) | 141 |
| 5962R9661102VCC | C | 02/02/2004 | 1 | INTERSIL | | Y | CD4077BDMSR | 141 |
| 5962R9661102VXC | C | 02/02/2004 | 1 | INTERSIL | | Y | CD4077BKMSR | 141 |
| 5962R9661103V9A | C | 02/02/2004 | | (NONE) | | | 4070BN (GEN) | 140 |
| 5962R9661103VCC | C | 02/02/2004 | | (NONE) | | | 4070BN (GEN) | 140 |
| 5962R9661103VXC | C | 02/02/2004 | | (NONE) | | | 4070BN (GEN) | 140 |
| 5962R9661104V9A | C | 02/02/2004 | | (NONE) | | | 4077BN (GEN) | 141 |
| 5962R9661104VCC | C | 02/02/2004 | | (NONE) | | | 4077BN (GEN) | 141 |
| 5962R9661104VXC | C | 02/02/2004 | | (NONE) | | | 4077BN (GEN) | 141 |
| 5962R9661201V9A | B | 07/25/1997 | | (NONE) | | | 4089B (GEN) | 208 |
| 5962R9661201VEC | B | 07/25/1997 | | (NONE) | | | 4089B (GEN) | 208 |
| 5962R9661201VXC | B | 07/25/1997 | | (NONE) | | | 4089B (GEN) | 208 |
| 5962R9661301V9A | B | 07/25/1997 | | (NONE) | | | 4095B (GEN) | 150 |
| 5962R9661301VCC | B | 07/25/1997 | | (NONE) | | | 4095B (GEN) | 150 |
| 5962R9661301VXC | B | 07/25/1997 | | (NONE) | | | 4095B (GEN) | 150 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962R9661302V9A | B | 07/25/1997 | | (NONE) | | | 4096B (GEN) | 150 |
| 5962R9661302VCC | B | 07/25/1997 | | (NONE) | | | 4096B (GEN) | 150 |
| 5962R9661302VXC | B | 07/25/1997 | | (NONE) | | | 4096B (GEN) | 150 |
| 5962R9661401V9A | C | 10/16/2003 | | (NONE) | | | 4098B (GEN) | 166 |
| 5962R9661401VEC | C | 10/16/2003 | 1 | INTERSIL | | Y | CD4098BDMSR | 166 |
| 5962R9661401VXC | C | 10/16/2003 | 1 | INTERSIL | | Y | CD4098BKMSR | 166 |
| 5962R9661402V9A | C | 10/16/2003 | | (NONE) | | | 4098BN (GEN) | 166 |
| 5962R9661402VEC | C | 10/16/2003 | | (NONE) | | | 4098BN (GEN) | 166 |
| 5962R9661402VXC | C | 10/16/2003 | | (NONE) | | | 4098BN (GEN) | 166 |
| 5962R9661501V9A | C | 10/16/2003 | | (NONE) | | | 4099B (GEN) | 341 |
| 5962R9661501VEC | C | 10/16/2003 | 1 | INTERSIL | | Y | CD4099BDMSR | 341 |
| 5962R9661501VXC | C | 10/16/2003 | 1 | INTERSIL | | Y | CD4099BKMSR | 341 |
| 5962R9661601V9A | A | 01/29/1998 | | (NONE) | | | 4502B (GEN) | 541 |
| 5962R9661601VCC | A | 01/29/1998 | | (NONE) | | | 4502B (GEN) | 541 |
| 5962R9661601VXC | A | 01/29/1998 | | (NONE) | | | 4502B (GEN) | 541 |
| 5962R9661602V9A | A | 01/29/1998 | | (NONE) | | | 4502BN (GEN) | 541 |
| 5962R9661602VCC | A | 01/29/1998 | | (NONE) | | | 4502BN (GEN) | 541 |
| 5962R9661602VXC | A | 01/29/1998 | | (NONE) | | | 4502BN (GEN) | 541 |
| 5962R9661701V9A | B | 07/29/1997 | | (NONE) | | | 4006B (GEN) | 231 |
| 5962R9661701VCC | B | 07/29/1997 | | (NONE) | | | 4006B (GEN) | 231 |
| 5962R9661701VXC | B | 07/29/1997 | | (NONE) | | | 4006B (GEN) | 231 |
| 5962R9661702V9A | B | 07/29/1997 | | (NONE) | | | 4006BN (GEN) | 231 |
| 5962R9661702VCC | B | 07/29/1997 | | (NONE) | | | 4006BN (GEN) | 231 |
| 5962R9661702VXC | B | 07/29/1997 | | (NONE) | | | 4006BN (GEN) | 231 |
| 5962R9661801V9A | B | 07/29/1997 | | (NONE) | | | 4007UB (GEN) | 149 |
| 5962R9661801VCC | B | 07/29/1997 | | (NONE) | | | 4007UB (GEN) | 149 |
| 5962R9661801VXC | B | 07/29/1997 | | (NONE) | | | 4007UB (GEN) | 149 |
| 5962R9661901V9A | C | 10/16/2003 | | (NONE) | | | 4008B (GEN) | 202 |
| 5962R9661901VEC | C | 10/16/2003 | | (NONE) | | | 4008B (GEN) | 202 |
| 5962R9661901VXC | C | 10/16/2003 | 1 | INTERSIL | | Y | CD4008BKMSR | 202 |
| 5962R9661902V9A | C | 10/16/2003 | | (NONE) | | | 4008BN (GEN) | 202 |
| 5962R9661902VEC | C | 10/16/2003 | | (NONE) | | | 4008BN (GEN) | 202 |
| 5962R9661902VXC | C | 10/16/2003 | | (NONE) | | | 4008BN (GEN) | 202 |
| 5962R9662001V9A | B | 07/29/1997 | | (NONE) | | | 4009UB (GEN) | 541 |
| 5962R9662001VEC | B | 07/29/1997 | | (NONE) | | | 4009UB (GEN) | 541 |
| 5962R9662001VXC | B | 07/29/1997 | | (NONE) | | | 4009UB (GEN) | 541 |
| 5962R9662101V9A | D | 04/28/1999 | 1 | INTERSIL | | Y | CD4011BHSR | 100 |
| 5962R9662101TCC | D | 04/28/1999 | | (NONE) | | | 4011B (GEN) | 100 |
| 5962R9662101VCC | D | 04/28/1999 | 1 | INTERSIL | | Y | CD4011BDMSR | 100 |
| 5962R9662101TXC | D | 04/28/1999 | | (NONE) | | | 4011B (GEN) | 100 |
| 5962R9662101VXC | D | 04/28/1999 | 1 | INTERSIL | | Y | CD4011BKMSR | 100 |
| 5962R9662102V9A | D | 04/28/1999 | | (NONE) | | | 4012B (GEN) | 104 |
| 5962R9662102VCC | D | 04/28/1999 | | (NONE) | | | 4012B (GEN) | 104 |
| 5962R9662102VXC | D | 04/28/1999 | | (NONE) | | | 4012B (GEN) | 104 |
| 5962R9662103V9A | D | 04/28/1999 | 1 | INTERSIL | | Y | CD4023BHSR | 102 |
| 5962R9662103VCC | D | 04/28/1999 | 1 | INTERSIL | | Y | CD4023BDMSR | 102 |
| 5962R9662103VXC | D | 04/28/1999 | 1 | INTERSIL | | Y | CD4023BKMSR | 102 |
| 5962R9662104V9A | D | 04/28/1999 | | (NONE) | | | 4011BN (GEN) | 100 |
| 5962R9662104VCC | D | 04/28/1999 | | (NONE) | | | 4011BN (GEN) | 100 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962R9662104VXC | D | 04/28/1999 | | (NONE) | | | 4011BN (GEN) | 100 |
| 5962R9662105V9A | D | 04/28/1999 | | (NONE) | | | 4012BN (GEN) | 104 |
| 5962R9662105VCC | D | 04/28/1999 | | (NONE) | | | 4012BN (GEN) | 104 |
| 5962R9662105VXC | D | 04/28/1999 | | (NONE) | | | 4012BN (GEN) | 104 |
| 5962R9662106V9A | D | 04/28/1999 | | (NONE) | | | 4023BN (GEN) | 102 |
| 5962R9662106VCC | D | 04/28/1999 | | (NONE) | | | 4023BN (GEN) | 102 |
| 5962R9662106VXC | D | 04/28/1999 | | (NONE) | | | 4023BN (GEN) | 102 |
| 5962R9662201V9A | B | 09/19/2001 | 1 | INTERSIL | | Y | CD4013BHSR | 158 |
| 5962R9662201VCC | B | 09/19/2001 | 1 | INTERSIL | | Y | CD4013BDMSR | 158 |
| 5962R9662201VXC | B | 09/19/2001 | 1 | INTERSIL | | Y | CD4013BKMSR | 158 |
| 5962R9662202V9A | B | 09/19/2001 | | (NONE) | | | 4013BN (GEN) | 158 |
| 5962R9662202VCC | B | 09/19/2001 | | (NONE) | | | 4013BN (GEN) | 158 |
| 5962R9662202VXC | B | 09/19/2001 | 1 | INTERSIL | | Y | CD4013BKNSR | 158 |
| 5962R9662301V9A | C | 11/19/2003 | | (NONE) | | | 4014B (GEN) | 225 |
| 5962R9662301VEC | C | 11/19/2003 | | (NONE) | | | 4014B (GEN) | 225 |
| 5962R9662301VXC | C | 11/19/2003 | | (NONE) | | | 4014B (GEN) | 225 |
| 5962R9662302V9A | C | 11/19/2003 | | (NONE) | | | 4021B (GEN) | 225 |
| 5962R9662302VEC | C | 11/19/2003 | 1 | INTERSIL | | Y | CD4021BDMSR | 225 |
| 5962R9662302VXC | C | 11/19/2003 | 1 | INTERSIL | | Y | CD4021BKMSR | 225 |
| 5962R9662303V9A | C | 11/19/2003 | | (NONE) | | | 4014BN (GEN) | 225 |
| 5962R9662303VEC | C | 11/19/2003 | | (NONE) | | | 4014BN (GEN) | 225 |
| 5962R9662303VXC | C | 11/19/2003 | | (NONE) | | | 4014BN (GEN) | 225 |
| 5962R9662304V9A | C | 11/19/2003 | | (NONE) | | | 4021BN (GEN) | 225 |
| 5962R9662304VEC | C | 11/19/2003 | | (NONE) | | | 4021BN (GEN) | 225 |
| 5962R9662304VXC | C | 11/19/2003 | | (NONE) | | | 4021BN (GEN) | 225 |
| 5962R9662401V9A | D | 04/28/1999 | | (NONE) | | | 4015B (GEN) | 226 |
| 5962R9662401TEC | D | 04/28/1999 | | (NONE) | | | 4015B (GEN) | 226 |
| 5962R9662401VEC | D | 04/28/1999 | 1 | INTERSIL | | Y | CD4015BDMSR | 226 |
| 5962R9662401TXC | D | 04/28/1999 | | (NONE) | | | 4015B (GEN) | 226 |
| 5962R9662401VXC | D | 04/28/1999 | 1 | INTERSIL | | Y | CD4015BKMSR | 226 |
| 5962R9662402V9A | D | 04/28/1999 | | (NONE) | | | 4015BN (GEN) | 226 |
| 5962R9662402VEC | D | 04/28/1999 | | (NONE) | | | 4015BN (GEN) | 226 |
| 5962R9662402VXC | D | 04/28/1999 | 1 | INTERSIL | | Y | CD4015BKNSR | 226 |
| 5962R9662501V9A | C | 11/19/2003 | | (NONE) | | | 4017B (GEN) | 306 |
| 5962R9662501VEC | C | 11/19/2003 | | (NONE) | 02/24/2004 | | 4017B (GEN) | 306 |
| 5962R9662501VXC | C | 11/19/2003 | | (NONE) | 02/24/2004 | | 4017B (GEN) | 306 |
| 5962R9662502V9A | C | 11/19/2003 | | (NONE) | | | 4022B (GEN) | 307 |
| 5962R9662502VEC | C | 11/19/2003 | | (NONE) | | | 4022B (GEN) | 307 |
| 5962R9662502VXC | C | 11/19/2003 | | (NONE) | | | 4022B (GEN) | 307 |
| 5962R9662503V9A | C | 11/19/2003 | | (NONE) | | | 4017BN (GEN) | 306 |
| 5962R9662503VEC | C | 11/19/2003 | | (NONE) | | | 4017BN (GEN) | 306 |
| 5962R9662503VXC | C | 11/19/2003 | | (NONE) | | | 4017BN (GEN) | 306 |
| 5962R9662504V9A | C | 11/19/2003 | | (NONE) | | | 4022BN (GEN) | 307 |
| 5962R9662504VEC | C | 11/19/2003 | | (NONE) | | | 4022BN (GEN) | 307 |
| 5962R9662504VXC | C | 11/19/2003 | | (NONE) | | | 4022BN (GEN) | 307 |
| 5962R9662601V9A | B | 07/29/1997 | | (NONE) | | | 4018B (GEN) | 309 |
| 5962R9662601VEC | B | 07/29/1997 | | (NONE) | | | 4018B (GEN) | 309 |
| 5962R9662601VXC | B | 07/29/1997 | | (NONE) | | | 4018B (GEN) | 309 |
| 5962R9662602V9A | B | 07/29/1997 | | (NONE) | | | 4018BN (GEN) | 309 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962R9662602VEC | B | 07/29/1997 | | (NONE) | | | 4018BN (GEN) | 309 |
| 5962R9662602VXC | B | 07/29/1997 | | (NONE) | | | 4018BN (GEN) | 309 |
| 5962R9662701V9A | B | 07/29/1997 | | (NONE) | | | 4019B (GEN) | 149 |
| 5962R9662701VEC | B | 07/29/1997 | | (NONE) | | | 4019B (GEN) | 149 |
| 5962R9662701VXC | B | 07/29/1997 | | (NONE) | | | 4019B (GEN) | 149 |
| 5962R9662702V9A | B | 07/29/1997 | | (NONE) | | | 4019BN (GEN) | 149 |
| 5962R9662702VEC | B | 07/29/1997 | | (NONE) | | | 4019BN (GEN) | 149 |
| 5962R9662702VXC | B | 07/29/1997 | | (NONE) | | | 4019BN (GEN) | 149 |
| 5962R9662801V9A | C | 12/11/2003 | 1 | INTERSIL | | Y | CD4020BHSR | 305 |
| 5962R9662801VEC | C | 12/11/2003 | 1 | INTERSIL | | Y | CD4020BDMSR | 305 |
| 5962R9662801VYC | C | 12/11/2003 | 1 | INTERSIL | | Y | CD4020BKMSR | 305 |
| 5962R9662802V9A | C | 12/11/2003 | | (NONE) | | | 4020BN (GEN) | 305 |
| 5962R9662802VEC | C | 12/11/2003 | | (NONE) | | | 4020BN (GEN) | 305 |
| 5962R9662802VYC | C | 12/11/2003 | 1 | INTERSIL | | Y | CD4020BKNSR | 305 |
| 5962R9662803V9A | C | 12/11/2003 | | (NONE) | | | 4024B (GEN) | 305 |
| 5962R9662803VCC | C | 12/11/2003 | 1 | INTERSIL | | Y | CD4024BDMSR | 305 |
| 5962R9662803VXC | C | 12/11/2003 | 1 | INTERSIL | | Y | CD4024BKMSR | 305 |
| 5962R9662804V9A | C | 12/11/2003 | | (NONE) | | | 4024BN (GEN) | 305 |
| 5962R9662804VCC | C | 12/11/2003 | | (NONE) | | | 4024BN (GEN) | 305 |
| 5962R9662804VXC | C | 12/11/2003 | | (NONE) | | | 4024BN (GEN) | 305 |
| 5962R9662805V9A | C | 12/11/2003 | | (NONE) | | | 4040B (GEN) | 305 |
| 5962R9662805VEC | C | 12/11/2003 | 1 | INTERSIL | | Y | CD4040BDMSR | 305 |
| 5962R9662805VYC | C | 12/11/2003 | 1 | INTERSIL | | Y | CD4040BKMSR | 305 |
| 5962R9662806V9A | C | 12/11/2003 | | (NONE) | | | 4040BN (GEN) | 305 |
| 5962R9662806VEC | C | 12/11/2003 | | (NONE) | | | 4040BN (GEN) | 305 |
| 5962R9662806VYC | C | 12/11/2003 | 1 | INTERSIL | | Y | CD4040BKNSR | 305 |
| 5962R9662901V9A | C | 12/11/2003 | | (NONE) | 09/23/2001 | | 4027B (GEN) | 153 |
| 5962R9662901VEC | C | 12/11/2003 | | (NONE) | 09/23/2001 | | 4027B (GEN) | 153 |
| 5962R9662901VXC | C | 12/11/2003 | 1 | INTERSIL | | Y | CD4027BKMSR | 153 |
| 5962R9662902V9A | C | 12/11/2003 | | (NONE) | | | 4027BN (GEN) | 153 |
| 5962R9662902VEC | C | 12/11/2003 | | (NONE) | | | 4027BN (GEN) | 153 |
| 5962R9662902VXC | C | 12/11/2003 | | (NONE) | | | 4027BN (GEN) | 153 |
| 5962R9663001V9A | C | 07/02/2003 | | (NONE) | 09/23/2001 | | 4028B (GEN) | 281 |
| 5962R9663001VEC | C | 07/02/2003 | | (NONE) | | | 4028B (GEN) | 281 |
| 5962R9663001VXC | C | 07/02/2003 | 1 | INTERSIL | | Y | CD4028BKMSR | 281 |
| 5962R9663002V9A | C | 07/02/2003 | | (NONE) | | | 4028BN (GEN) | 281 |
| 5962R9663002VEC | C | 07/02/2003 | | (NONE) | 09/23/2001 | | 4028BN (GEN) | 281 |
| 5962R9663002VXC | C | 07/02/2003 | | (NONE) | | | 4028BN (GEN) | 281 |
| 5962R9663201V9A | C | 07/02/2003 | 1 | INTERSIL | 05/01/2004 | Y | CD4041UBHSR | 544 |
| 5962R9663201VCC | C | 07/02/2003 | 1 | INTERSIL | 05/01/2004 | Y | CD4041UBDMSR | 544 |
| 5962R9663201VXC | C | 07/02/2003 | 1 | INTERSIL | 05/01/2004 | Y | CD4041UBKMSR | 544 |
| 5962R9663202V9A | C | 07/02/2003 | | (NONE) | | | 4041UBN (GEN) | 544 |
| 5962R9663202VCC | C | 07/02/2003 | | (NONE) | | | 4041UBN (GEN) | 544 |
| 5962R9663202VXC | C | 07/02/2003 | | (NONE) | | | 4041UBN (GEN) | 544 |
| 5962R9663301V9A | C | 07/02/2003 | | (NONE) | | | 4042B (GEN) | 340 |
| 5962R9663301VEC | C | 07/02/2003 | 1 | INTERSIL | | Y | CD4042BDMSR | 340 |
| 5962R9663301VXC | C | 07/02/2003 | 1 | INTERSIL | | Y | CD4042BKMSR | 340 |
| 5962R9663302V9A | C | 07/02/2003 | | (NONE) | | | 4042BN (GEN) | 340 |
| 5962R9663302VEC | C | 07/02/2003 | | (NONE) | | | 4042BN (GEN) | 340 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962R9663302VXC | C | 07/02/2003 | | (NONE) | | | 4042BN (GEN) | 340 |
| 5962R9663401V9A | C | 07/02/2003 | | (NONE) | | | 4043B (GEN) | 340 |
| 5962R9663401VEC | C | 07/02/2003 | 1 | INTERSIL | | Y | CD4043BDMSR | 340 |
| 5962R9663401VXC | C | 07/02/2003 | 1 | INTERSIL | | Y | CD4043BKMSR | 340 |
| 5962R9663402V9A | C | 07/02/2003 | | (NONE) | | | 4044B (GEN) | 340 |
| 5962R9663402VEC | C | 07/02/2003 | | (NONE) | | | 4044B (GEN) | 340 |
| 5962R9663402VXC | C | 07/02/2003 | | (NONE) | | | 4044B (GEN) | 340 |
| 5962R9663403V9A | C | 07/02/2003 | | (NONE) | | | 4043BN (GEN) | 340 |
| 5962R9663403VEC | C | 07/02/2003 | | (NONE) | | | 4043BN (GEN) | 340 |
| 5962R9663403VXC | C | 07/02/2003 | | (NONE) | | | 4043BN (GEN) | 340 |
| 5962R9663501V9A | C | 07/02/2003 | | (NONE) | | | 4047B (GEN) | 165 |
| 5962R9663501VCC | C | 07/02/2003 | | (NONE) | | | 4047B (GEN) | 165 |
| 5962R9663501VXC | C | 07/02/2003 | 1 | INTERSIL | | Y | CD4047BKMSR | 165 |
| 5962R9663502V9A | C | 07/02/2003 | | (NONE) | | | 4047BN (GEN) | 165 |
| 5962R9663502VCC | C | 07/02/2003 | | (NONE) | | | 4047BN (GEN) | 165 |
| 5962R9663502VXC | C | 07/02/2003 | 1 | INTERSIL | | Y | CD4047BKNSR | 165 |
| 5962R9663601V9A | D | 04/28/1999 | 1 | INTERSIL | | Y | CD4049UBHSR | 541 |
| 5962R9663601TEC | D | 04/28/1999 | | (NONE) | | | 4049UB (GEN) | 541 |
| 5962R9663601VEC | D | 04/28/1999 | 1 | INTERSIL | | Y | CD4049UBDMSR | 541 |
| 5962R9663601TXC | D | 04/28/1999 | | (NONE) | | | 4049UB (GEN) | 541 |
| 5962R9663601VXC | D | 04/28/1999 | 1 | INTERSIL | | Y | CD4049UBKMSR | 541 |
| 5962R9663602V9A | D | 04/28/1999 | | (NONE) | | | 4049UB (GEN) | 541 |
| 5962R9663602VEC | D | 04/28/1999 | | (NONE) | | | 4049UB (GEN) | 541 |
| 5962R9663602VXC | D | 04/28/1999 | 1 | INTERSIL | | Y | CD4049UBKNSR | 541 |
| 5962R9663701V9A | C | 12/11/2003 | | (NONE) | 09/23/2001 | | 4050B (GEN) | 540 |
| 5962R9663701VEC | C | 12/11/2003 | 1 | INTERSIL | | Y | CD4050BDMSR | 540 |
| 5962R9663701VXC | C | 12/11/2003 | | (NONE) | 03/24/2002 | | 4050B (GEN) | 540 |
| 5962R9663702V9A | C | 12/11/2003 | | (NONE) | | | 4050BN (GEN) | 540 |
| 5962R9663702VEC | C | 12/11/2003 | | (NONE) | | | 4050BN (GEN) | 540 |
| 5962R9663702VXC | C | 12/11/2003 | | (NONE) | | | 4050BN (GEN) | 540 |
| 5962R9663801V9A | B | 08/04/1997 | | (NONE) | | | 4078B (GEN) | 124 |
| 5962R9663801VCC | B | 08/04/1997 | | (NONE) | 09/23/2001 | | 4078B (GEN) | 124 |
| 5962R9663801VXC | B | 08/04/1997 | 1 | INTERSIL | | Y | CD4078BKMSR | 124 |
| 5962R9663802V9A | B | 08/04/1997 | | (NONE) | | | 4078BN (GEN) | 124 |
| 5962R9663802VCC | B | 08/04/1997 | | (NONE) | | | 4078BN (GEN) | 124 |
| 5962R9663802VXC | B | 08/04/1997 | | (NONE) | | | 4078BN (GEN) | 124 |
| 5962R9663901V9A | A | 01/16/1998 | 1 | INTERSIL | | Y | CD4085BMSR | 130 |
| 5962R9663901VCC | A | 01/16/1998 | | (NONE) | | | 4085B (GEN) | 130 |
| 5962R9663901VXC | A | 01/16/1998 | | (NONE) | | | 4085B (GEN) | 130 |
| 5962R9664001V9A | A | 01/16/1998 | | (NONE) | | | 4086B (GEN) | 134 |
| 5962R9664001VCC | A | 01/16/1998 | | (NONE) | | | 4086B (GEN) | 134 |
| 5962R9664001VXC | A | 01/16/1998 | | (NONE) | | | 4086B (GEN) | 134 |
| 5962R9664101V9A | C | 07/02/2003 | 1 | INTERSIL | 02/10/2005 | Y | CD4093BHSR | 109 |
| 5962R9664101VCC | C | 07/02/2003 | 1 | INTERSIL | 02/10/2005 | Y | CD4093BDMSR | 109 |
| 5962R9664101VXC | C | 07/02/2003 | 1 | INTERSIL | 02/10/2005 | Y | CD4093BKMSR | 109 |
| 5962R9664102V9A | C | 07/02/2003 | | (NONE) | | | 4093BN (GEN) | 109 |
| 5962R9664102VCC | C | 07/02/2003 | | (NONE) | | | 4093BN (GEN) | 109 |
| 5962R9664102VXC | C | 07/02/2003 | 1 | INTERSIL | 02/10/2005 | Y | CD4093BKNSR | 109 |
| 5962R9664201V9A | B | 08/08/1997 | | (NONE) | 03/23/2003 | | CD4094B (GEN) | 249 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962R9664201VEC | B | 08/08/1997 | | (NONE) | 03/23/2003 | | CD4094B (GEN) | 249 |
| 5962R9664201VXC | B | 08/08/1997 | | (NONE) | 03/23/2003 | | CD4094B (GEN) | 249 |
| 5962R9664202V9A | B | 08/08/1997 | | (NONE) | | | 4094BN (GEN) | 249 |
| 5962R9664202VEC | B | 08/08/1997 | | (NONE) | | | 4094BN (GEN) | 249 |
| 5962R9664202VXC | B | 08/08/1997 | | (NONE) | | | 4094BN (GEN) | 249 |
| 5962R9664301V9A | B | 02/02/2004 | | (NONE) | | | 4503B (GEN) | 522 |
| 5962R9664301VEC | B | 02/02/2004 | 1 | INTERSIL | | Y | CD4503BDMSR | 522 |
| 5962R9664301VXC | B | 02/02/2004 | 1 | INTERSIL | | Y | CD4503BKMSR | 522 |
| 5962R9664302V9A | B | 02/02/2004 | | (NONE) | | | 4503BN (GEN) | 522 |
| 5962R9664302VEC | B | 02/02/2004 | | (NONE) | | | 4503BN (GEN) | 522 |
| 5962R9664302VXC | B | 02/02/2004 | 1 | INTERSIL | | Y | CD4503BKNSR | 522 |
| 5962R9664401V9A | C | 07/02/2003 | | (NONE) | | | 40107B (GEN) | 544 |
| 5962R9664401VCC | C | 07/02/2003 | | (NONE) | | | 40107B (GEN) | 544 |
| 5962R9664401VXC | C | 07/02/2003 | 1 | INTERSIL | | Y | CD40107BKMSR | 544 |
| 5962R9664402V9A | C | 07/02/2003 | | (NONE) | | | 40107BN (GEN) | 544 |
| 5962R9664402VCC | C | 07/02/2003 | | (NONE) | | | 40107BN (GEN) | 544 |
| 5962R9664402VXC | C | 07/02/2003 | | (NONE) | | | 40107BN (GEN) | 544 |
| 5962R9664501V9A | A | 01/16/1998 | | (NONE) | 09/23/2001 | | 40109B (GEN) | 545 |
| 5962R9664501VEC | A | 01/16/1998 | 1 | INTERSIL | | Y | CD40109BDMSR | 545 |
| 5962R9664501VXC | A | 01/16/1998 | 1 | INTERSIL | | Y | CD40109BKMSR | 545 |
| 5962R9664502V9A | A | 01/16/1998 | | (NONE) | | | 40109BN (GEN) | 545 |
| 5962R9664502VEC | A | 01/16/1998 | | (NONE) | | | 40109BN (GEN) | 545 |
| 5962R9664502VXC | A | 01/16/1998 | 1 | INTERSIL | | Y | CD40109BKNSR | 545 |
| 5962R9664601V9A | C | 07/02/2003 | | (NONE) | | | 4030B (GEN) | 140 |
| 5962R9664601VCC | C | 07/02/2003 | 1 | INTERSIL | | Y | CD4030BDMSR | 140 |
| 5962R9664601VXC | C | 07/02/2003 | | (NONE) | | | 4030B (GEN) | 140 |
| 5962R9664602V9A | C | 07/02/2003 | | (NONE) | | | 4030BN (GEN) | 140 |
| 5962R9664602VCC | C | 07/02/2003 | | (NONE) | | | 4030BN (GEN) | 140 |
| 5962R9664602VXC | C | 07/02/2003 | | (NONE) | | | 4030BN (GEN) | 140 |
| 5962R9664701V9A | B | 08/08/1997 | | (NONE) | | | 4031B (GEN) | 234 |
| 5962R9664701VEC | B | 08/08/1997 | | (NONE) | | | 4031B (GEN) | 234 |
| 5962R9664701VXC | B | 08/08/1997 | | (NONE) | | | 4031B (GEN) | 234 |
| 5962R9664702V9A | B | 08/08/1997 | | (NONE) | | | 4031BN (GEN) | 234 |
| 5962R9664702VEC | B | 08/08/1997 | | (NONE) | | | 4031BN (GEN) | 234 |
| 5962R9664702VXC | B | 08/08/1997 | | (NONE) | | | 4031BN (GEN) | 234 |
| 5962R9664801V9A | B | 08/08/1997 | | (NONE) | | | 4033B (GEN) | 319 |
| 5962R9664801VEC | B | 08/08/1997 | | (NONE) | | | 4033B (GEN) | 319 |
| 5962R9664801VXC | B | 08/08/1997 | | (NONE) | | | 4033B (GEN) | 319 |
| 5962R9664901V9A | B | 08/08/1997 | | (NONE) | | | 4035B (GEN) | 222 |
| 5962R9664901VEC | B | 08/08/1997 | | (NONE) | | | 4035B (GEN) | 222 |
| 5962R9664901VXC | B | 08/08/1997 | | (NONE) | | | 4035B (GEN) | 222 |
| 5962R9664902V9A | B | 08/08/1997 | | (NONE) | | | 4035BN (GEN) | 222 |
| 5962R9664902VEC | B | 08/08/1997 | | (NONE) | | | 4035BN (GEN) | 222 |
| 5962R9664902VXC | B | 08/08/1997 | | (NONE) | | | 4035BN (GEN) | 222 |
| 5962R9665001V9A | B | 08/08/1997 | | (NONE) | | | 4048B (GEN) | 149 |
| 5962R9665001VEC | B | 08/08/1997 | | (NONE) | | | 4048B (GEN) | 149 |
| 5962R9665001VXC | B | 08/08/1997 | | (NONE) | | | 4048B (GEN) | 149 |
| 5962R9665101V9A | C | 04/15/2004 | | (NONE) | 09/23/2001 | | 4051B (GEN) | 193 |
| 5962R9665101VEC | C | 04/15/2004 | 1 | INTERSIL | | Y | CD4051BDMSR | 193 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962R9665101VXC | C | 04/15/2004 | 1 | INTERSIL | | Y | CD4051BKMSR | 193 |
| 5962R9665102V9A | C | 04/15/2004 | 1 | INTERSIL | | Y | CD4052BHSR | 192 |
| 5962R9665102VEC | C | 04/15/2004 | 1 | INTERSIL | | Y | CD4052BDMSR | 192 |
| 5962R9665102VXC | C | 04/15/2004 | 1 | INTERSIL | | Y | CD4052BKMSR | 192 |
| 5962R9665103V9A | C | 04/15/2004 | 1 | INTERSIL | | Y | CD4053BHSR | 199 |
| 5962R9665103VEC | C | 04/15/2004 | 1 | INTERSIL | | Y | CD4053BDMSR | 199 |
| 5962R9665103VXC | C | 04/15/2004 | 1 | INTERSIL | | Y | CD4053BKMSR | 199 |
| 5962R9665104V9A | C | 04/15/2004 | | (NONE) | | | 4051BN (GEN) | 193 |
| 5962R9665104VEC | C | 04/15/2004 | | (NONE) | | | 4051BN (GEN) | 193 |
| 5962R9665104VXC | C | 04/15/2004 | 1 | INTERSIL | | Y | CD4051BKNSR | 193 |
| 5962R9665105V9A | C | 04/15/2004 | | (NONE) | | | 4052BN (GEN) | 192 |
| 5962R9665105VEC | C | 04/15/2004 | | (NONE) | | | 4052BN (GEN) | 192 |
| 5962R9665105VXC | C | 04/15/2004 | | (NONE) | | | 4052BN (GEN) | 192 |
| 5962R9665106V9A | C | 04/15/2004 | | (NONE) | | | 4053BN (GEN) | 199 |
| 5962R9665106VEC | C | 04/15/2004 | | (NONE) | | | 4053BN (GEN) | 199 |
| 5962R9665106VXC | C | 04/15/2004 | | (NONE) | | | 4053BN (GEN) | 199 |
| 5962R9665201V9A | C | 07/01/2003 | | (NONE) | 09/23/2001 | | 4066B (GEN) | 183 |
| 5962R9665201VCC | C | 07/01/2003 | 1 | INTERSIL | | Y | CD4066BDMSR | 183 |
| 5962R9665201VXC | C | 07/01/2003 | 1 | INTERSIL | | Y | CD4066BKMSR | 183 |
| 5962R9665202V9A | C | 07/01/2003 | | (NONE) | | | 4066BN (GEN) | 183 |
| 5962R9665202VCC | C | 07/01/2003 | | (NONE) | | | 4066BN (GEN) | 183 |
| 5962R9665202VXC | C | 07/01/2003 | | (NONE) | | | 4066BN (GEN) | 183 |
| 5962R9665301V9A | C | 09/22/2003 | | (NONE) | | | 4069UB (GEN) | 143 |
| 5962R9665301VCC | C | 09/22/2003 | 1 | INTERSIL | | Y | CD4069UBDMSR | 143 |
| 5962R9665301VXC | C | 09/22/2003 | 1 | INTERSIL | | Y | CD4069UBKMSR | 143 |
| 5962R9665302V9A | C | 09/22/2003 | | (NONE) | | | 4069UBN (GEN) | 143 |
| 5962R9665302VCC | C | 09/22/2003 | | (NONE) | | | 4069UBN (GEN) | 143 |
| 5962R9665302VXC | C | 09/22/2003 | | (NONE) | | | 4069UBN (GEN) | 143 |
| 5962R9665401V9A | C | 10/10/2003 | | (NONE) | | | 4071B (GEN) | 125 |
| 5962R9665401VCC | C | 10/10/2003 | 1 | INTERSIL | | Y | CD4071BDMSR | 125 |
| 5962R9665401VXC | C | 10/10/2003 | 1 | INTERSIL | | Y | CD4071BKMSR | 125 |
| 5962R9665402V9A | C | 10/10/2003 | | (NONE) | | | 4071BN (GEN) | 125 |
| 5962R9665402VCC | C | 10/10/2003 | | (NONE) | | | 4071BN (GEN) | 125 |
| 5962R9665402VXC | C | 10/10/2003 | | (NONE) | | | 4071BN (GEN) | 125 |
| 5962R9665403V9A | C | 10/10/2003 | | (NONE) | | | 4072B (GEN) | 125 |
| 5962R9665403VCC | C | 10/10/2003 | | (NONE) | | | 4072B (GEN) | 125 |
| 5962R9665403VXC | C | 10/10/2003 | | (NONE) | | | 4072B (GEN) | 125 |
| 5962R9665404V9A | C | 10/10/2003 | | (NONE) | | | 4072BN (GEN) | 125 |
| 5962R9665404VCC | C | 10/10/2003 | | (NONE) | | | 4072BN (GEN) | 125 |
| 5962R9665404VXC | C | 10/10/2003 | | (NONE) | | | 4072BN (GEN) | 125 |
| 5962R9665405V9A | C | 10/10/2003 | | (NONE) | | | 4075B (GEN) | 125 |
| 5962R9665405VCC | C | 10/10/2003 | | (NONE) | | | 4075B (GEN) | 125 |
| 5962R9665405VXC | C | 10/10/2003 | | (NONE) | | | 4075B (GEN) | 125 |
| 5962R9665406V9A | C | 10/10/2003 | | (NONE) | | | 4075BN (GEN) | 125 |
| 5962R9665406VCC | C | 10/10/2003 | | (NONE) | | | 4075BN (GEN) | 125 |
| 5962R9665406VXC | C | 10/10/2003 | | (NONE) | | | 4075BN (GEN) | 125 |
| 5962R9665501V9A | C | 10/10/2003 | | (NONE) | | | 4073B (GEN) | 112 |
| 5962R9665501VCC | C | 10/10/2003 | | (NONE) | | | 4073B (GEN) | 112 |
| 5962R9665501VXC | C | 10/10/2003 | | (NONE) | | | 4073B (GEN) | 112 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962R9665502V9A | C | 10/10/2003 | | (NONE) | | | 4081B (GEN) | 110 |
| 5962R9665502VCC | C | 10/10/2003 | 1 | INTERSIL | | Y | CD4081BDMSR | 110 |
| 5962R9665502VXC | C | 10/10/2003 | 1 | INTERSIL | | Y | CD4081BKMSR | 110 |
| 5962R9665503V9A | C | 10/10/2003 | | (NONE) | | | 4082B (GEN) | 114 |
| 5962R9665503VCC | C | 10/10/2003 | | (NONE) | | | 4082B (GEN) | 114 |
| 5962R9665503VXC | C | 10/10/2003 | | (NONE) | | | 4082B (GEN) | 114 |
| 5962R9665504V9A | C | 10/10/2003 | | (NONE) | | | 4073BN (GEN) | 112 |
| 5962R9665504VCC | C | 10/10/2003 | | (NONE) | | | 4073BN (GEN) | 112 |
| 5962R9665504VXC | C | 10/10/2003 | 1 | INTERSIL | | Y | CD4073BKNSR | 112 |
| 5962R9665505V9A | C | 10/10/2003 | | (NONE) | | | 4081BN (GEN) | 110 |
| 5962R9665505VCC | C | 10/10/2003 | | (NONE) | | | 4081BN (GEN) | 110 |
| 5962R9665505VXC | C | 10/10/2003 | 1 | INTERSIL | | Y | CD4081BKNSR | 110 |
| 5962R9665506V9A | C | 10/10/2003 | | (NONE) | | | 4082BN (GEN) | 114 |
| 5962R9665506VCC | C | 10/10/2003 | | (NONE) | | | 4082BN (GEN) | 114 |
| 5962R9665506VXC | C | 10/10/2003 | | (NONE) | | | 4082BN (GEN) | 114 |
| 5962R9665601V9A | C | 10/07/2003 | 1 | INTERSIL | | Y | CD4076BHSR | 222 |
| 5962R9665601VEC | C | 10/07/2003 | 1 | INTERSIL | | Y | CD4076BDMSR | 222 |
| 5962R9665601VXC | C | 10/07/2003 | 1 | INTERSIL | | Y | CD4076BKMSR | 222 |
| 5962R9665602V9A | C | 10/07/2003 | | (NONE) | | | 4076BN (GEN) | 222 |
| 5962R9665602VEC | C | 10/07/2003 | | (NONE) | | | 4076BN (GEN) | 222 |
| 5962R9665602VXC | C | 10/07/2003 | | (NONE) | | | 4076BN (GEN) | 222 |
| 5962R9665701V9A | A | 12/15/1997 | | (NONE) | | | 4510B (GEN) | 302 |
| 5962R9665701VEC | A | 12/15/1997 | | (NONE) | | | 4510B (GEN) | 302 |
| 5962R9665701VXC | A | 12/15/1997 | | (NONE) | | | 4510B (GEN) | 302 |
| 5962R9665702V9A | A | 12/15/1997 | | (NONE) | | | 4516B (GEN) | 301 |
| 5962R9665702VEC | A | 12/15/1997 | | (NONE) | | | 4516B (GEN) | 301 |
| 5962R9665702VXC | A | 12/15/1997 | | (NONE) | | | 4516B (GEN) | 301 |
| 5962R9665703V9A | A | 12/15/1997 | | (NONE) | | | 4516BN (GEN) | 301 |
| 5962R9665703VEC | A | 12/15/1997 | | (NONE) | | | 4516BN (GEN) | 301 |
| 5962R9665703VXC | A | 12/15/1997 | | (NONE) | | | 4516BN (GEN) | 301 |
| 5962-9665801Q2A | C | 12/16/2003 | 1 | LANSDALE | | Y | SL54LS14/B2A | 143 |
| 5962-9665801Q2A | C | 12/16/2003 | 2 | TI | | Y | SNJ54LS14FK | 143 |
| 5962-9665801Q2C | C | 12/16/2003 | 1 | LANSDALE | | Y | SL54LS14/B2C | 143 |
| 5962-9665801QCA | C | 12/16/2003 | 1 | LANSDALE | | Y | SL54LS14/BCA | 143 |
| 5962-9665801QCA | C | 12/16/2003 | 2 | TI | | Y | SNJ54LS14J | 143 |
| 5962-9665801VCA | C | 12/16/2003 | 2 | TI | | Y | SNV54LS14J | 143 |
| 5962-9665801QDA | C | 12/16/2003 | 1 | LANSDALE | | Y | SL54LS14/BDA | 143 |
| 5962-9665801QDA | C | 12/16/2003 | 2 | TI | | Y | SNJ54LS14W | 143 |
| 5962-9665801VDA | C | 12/16/2003 | 2 | TI | | Y | SNV54LS14W | 143 |
| 5962-9665901HUA | | 12/01/1998 | 1 | ADV. ANALOG | | Y | AFL2808SW/CH | 594 |
| 5962-9665901HUC | | 12/01/1998 | 1 | ADV. ANALOG | | Y | AFL2808SW/CH | 594 |
| 5962-9665901HXA | | 12/01/1998 | 1 | ADV. ANALOG | | Y | AFL2808SX/CH | 594 |
| 5962-9665901HXC | | 12/01/1998 | 1 | ADV. ANALOG | | Y | AFL2808SX/CH | 594 |
| 5962-9665901HYA | | 12/01/1998 | 1 | ADV. ANALOG | | Y | AFL2808SY/CH | 594 |
| 5962-9665901HYC | | 12/01/1998 | 1 | ADV. ANALOG | | Y | AFL2808SY/CH | 594 |
| 5962-9665901HZA | | 12/01/1998 | 1 | ADV. ANALOG | | Y | AFL2808SZ/CH | 594 |
| 5962-9665901HZC | | 12/01/1998 | 1 | ADV. ANALOG | | Y | AFL2808SZ/CH | 594 |
| 5962F9666301V9A | G | 11/27/2002 | 1 | INTERSIL | | Y | HS0-26C31RH-Q | 569 |
| 5962D9666301QEA | G | 11/27/2002 | 1 | STMICRO | | Y | RHD26C31D09Q | 569 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962D9666301QEC | G | 11/27/2002 | 1 | STMICRO | | Y | RHD26C31D08Q | 569 |
| 5962D9666301VEA | G | 11/27/2002 | 1 | STMICRO | | Y | RHD26C31D09V | 569 |
| 5962D9666301VEC | G | 11/27/2002 | 1 | STMICRO | | Y | RHD26C31D08V | 569 |
| 5962F9666301QEC | G | 11/27/2002 | 1 | INTERSIL | | Y | HS1-26C31RH-8 | 569 |
| 5962F9666301VEC | G | 11/27/2002 | 1 | INTERSIL | | Y | HS1-26C31RH-Q | 569 |
| 5962R9666301TEC | G | 11/27/2002 | 1 | INTERSIL | | Y | HS1-26C31RH-T | 569 |
| 5962D9666301QXA | G | 11/27/2002 | 1 | STMICRO | | Y | RHD26C31K02Q | 569 |
| 5962D9666301QXC | G | 11/27/2002 | 1 | STMICRO | | Y | RHD26C31K01Q | 569 |
| 5962D9666301VXA | G | 11/27/2002 | 1 | STMICRO | | Y | RHD26C31K02V | 569 |
| 5962D9666301VXC | G | 11/27/2002 | 1 | STMICRO | | Y | RHD26C31K01V | 569 |
| 5962F9666301QXC | G | 11/27/2002 | 1 | INTERSIL | | Y | HS9-26C31RH-8 | 569 |
| 5962F9666301VXC | G | 11/27/2002 | 1 | INTERSIL | | Y | HS9-26C31RH-Q | 569 |
| 5962R9666301TXC | G | 11/27/2002 | 1 | INTERSIL | | Y | HS9-26C31RH-T | 569 |
| 5962F9666302V9A | G | 11/27/2002 | 1 | INTERSIL | | Y | HS0-26CLV31RH-Q | 569 |
| 5962F9666302QEC | G | 11/27/2002 | 1 | INTERSIL | | Y | HS1-26CLV31RH-8 | 569 |
| 5962F9666302VEC | G | 11/27/2002 | 1 | INTERSIL | | Y | HS1-26CLV31RH-Q | 569 |
| 5962R9666302TEC | G | 11/27/2002 | 1 | INTERSIL | | Y | HS1-26CLV31RH-T | 569 |
| 5962F9666302QXC | G | 11/27/2002 | 1 | INTERSIL | | Y | HS9-26CLV31RH-8 | 569 |
| 5962F9666302VXC | G | 11/27/2002 | 1 | INTERSIL | | Y | HS9-26CLV31RH-Q | 569 |
| 5962R9666302TXC | G | 11/27/2002 | 1 | INTERSIL | | Y | HS9-26CLV31RH-T | 569 |
| 5962R9666401V9A | C | 04/19/2000 | | (NONE) | | | 4046B (GEN) | 803 |
| 5962R9666401VEC | C | 04/19/2000 | 1 | INTERSIL | 11/25/2004 | Y | CD4046BDMSR | 803 |
| 5962R9666401VXC | C | 04/19/2000 | | (NONE) | | | 4046B (GEN) | 803 |
| 5962R9666402V9A | C | 04/19/2000 | | (NONE) | | | 4046BN (GEN) | 803 |
| 5962R9666402VEC | C | 04/19/2000 | | (NONE) | | | 4046BN (GEN) | 803 |
| 5962R9666402VXC | C | 04/19/2000 | | (NONE) | | | 4046BN (GEN) | 803 |
| 5962R9666501V9A | C | 04/28/1999 | | (NONE) | | | 4504B (GEN) | 549 |
| 5962R9666501TEC | C | 04/28/1999 | | (NONE) | | | 4504B (GEN) | 549 |
| 5962R9666501VEC | C | 04/28/1999 | 1 | INTERSIL | | Y | CD4504BDMSR | 549 |
| 5962R9666501TXC | C | 04/28/1999 | | (NONE) | | | 4504B (GEN) | 549 |
| 5962R9666501VXC | C | 04/28/1999 | 1 | INTERSIL | | Y | CD4504BKMSR | 549 |
| 5962R9666601V9A | B | 04/21/2000 | | (NONE) | | | 4511B (GEN) | 291 |
| 5962R9666601VEC | B | 04/21/2000 | | (NONE) | | | CD4511BDMSR | 291 |
| 5962R9666601VXC | B | 04/21/2000 | | (NONE) | | | CD4511BKMSR | 291 |
| 5962R9666701V9A | B | 04/26/2000 | | (NONE) | | | 4512B (GEN) | 272 |
| 5962R9666701VEC | B | 04/26/2000 | 1 | INTERSIL | | Y | CD4512BDMSR | 272 |
| 5962R9666701VXC | B | 04/26/2000 | 1 | INTERSIL | | Y | CD4512BKMSR | 272 |
| 5962R9666702V9A | B | 04/26/2000 | | (NONE) | | | 4512BN (GEN) | 272 |
| 5962R9666702VEC | B | 04/26/2000 | | (NONE) | | | CD4512BDNSR | 272 |
| 5962R9666702VXC | B | 04/26/2000 | | (NONE) | | | CD4512BKNSR | 272 |
| 5962R9666801V9A | B | 05/09/2000 | | (NONE) | | | 4517B (GEN) | 234 |
| 5962R9666801VEC | B | 05/09/2000 | | (NONE) | | | 4517B (GEN) | 234 |
| 5962R9666801VXC | B | 05/09/2000 | | (NONE) | | | 4517B (GEN) | 234 |
| 5962R9666901V9A | B | 05/09/2000 | | (NONE) | | | 4518B (GEN) | 301 |
| 5962R9666901VEC | B | 05/09/2000 | | (NONE) | | | 4518B (GEN) | 301 |
| 5962R9666901VXC | B | 05/09/2000 | | (NONE) | | | 4518B (GEN) | 301 |
| 5962R9666902V9A | B | 05/09/2000 | 1 | INTERSIL | | Y | CD4520BHSR | 304 |
| 5962R9666902VEC | B | 05/09/2000 | | (NONE) | | | 4520B (GEN) | 304 |
| 5962R9666902VXC | B | 05/09/2000 | | (NONE) | | | 4520B (GEN) | 304 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962R9666903V9A | B | 05/09/2000 | | (NONE) | | | 4520BN (GEN) | 304 |
| 5962R9666903VEC | B | 05/09/2000 | | (NONE) | | | 4520BN (GEN) | 304 |
| 5962R9666903VXC | B | 05/09/2000 | | (NONE) | | | 4520BN (GEN) | 304 |
| 5962R9667001V9A | B | 05/10/2000 | | (NONE) | | | 4527B (GEN) | 208 |
| 5962R9667001VEC | B | 05/10/2000 | | (NONE) | | | 4527B (GEN) | 208 |
| 5962R9667001VXC | B | 05/10/2000 | | (NONE) | | | 4527B (GEN) | 208 |
| 5962R9667101V9A | B | 05/23/2000 | | (NONE) | | | 4532B (GEN) | 345 |
| 5962R9667101VEC | B | 05/23/2000 | | (NONE) | | | 4532B (GEN) | 345 |
| 5962R9667101VXC | B | 05/23/2000 | | (NONE) | | | 4532B (GEN) | 345 |
| 5962R9667102V9A | B | 05/23/2000 | | (NONE) | | | 4532BN (GEN) | 345 |
| 5962R9667102VEC | B | 05/23/2000 | | (NONE) | | | 4532BN (GEN) | 345 |
| 5962R9667102VXC | B | 05/23/2000 | | (NONE) | | | 4532BN (GEN) | 345 |
| 5962R9667201V9A | B | 05/25/2000 | | (NONE) | | | 4536B (GEN) | 424 |
| 5962R9667201VEC | B | 05/25/2000 | | (NONE) | | | 4536B (GEN) | 424 |
| 5962R9667201VXC | B | 05/25/2000 | | (NONE) | | | 4536B (GEN) | 424 |
| 5962R9667301V9A | C | 05/25/2000 | | (NONE) | | | 4555B (GEN) | 283 |
| 5962R9667301VEC | C | 05/25/2000 | 1 | INTERSIL | | Y | CD4555BDMSR | 283 |
| 5962R9667301VXC | C | 05/25/2000 | 1 | INTERSIL | | Y | CD4555BKMSR | 283 |
| 5962R9667302V9A | C | 05/25/2000 | | (NONE) | 12/28/2003 | | 4556B (GEN) | 283 |
| 5962R9667302VEC | C | 05/25/2000 | | (NONE) | | | 4556B (GEN) | 283 |
| 5962R9667302VXC | C | 05/25/2000 | | (NONE) | | | 4556B (GEN) | 283 |
| 5962R9667303V9A | C | 05/25/2000 | | (NONE) | | | 4555BN (GEN) | 283 |
| 5962R9667303VEC | C | 05/25/2000 | | (NONE) | | | 4555BN (GEN) | 283 |
| 5962R9667303VXC | C | 05/25/2000 | | (NONE) | | | 4555BN (GEN) | 283 |
| 5962R9667304VEC | C | 05/25/2000 | | (NONE) | | | 4556BN (GEN) | 283 |
| 5962R9667304VXC | C | 05/25/2000 | | (NONE) | | | 4556BN (GEN) | 283 |
| 5962R9667401V9A | C | 05/25/2000 | | (NONE) | | | 4585B (GEN) | 209 |
| 5962R9667401VEC | C | 05/25/2000 | 1 | INTERSIL | | Y | CD4585BDMSR | 209 |
| 5962R9667401VXC | C | 05/25/2000 | 1 | INTERSIL | | Y | CD4585BKMSR | 209 |
| 5962R9667501V9A | B | 05/25/2000 | | (NONE) | | | 4724B (GEN) | 341 |
| 5962R9667501VEC | B | 05/25/2000 | | (NONE) | | | 4724B (GEN) | 341 |
| 5962R9667501VXC | B | 05/25/2000 | | (NONE) | | | 4724B (GEN) | 341 |
| 5962R9667601V9A | C | 05/31/2000 | | (NONE) | | | CD40160BHSR | 301 |
| 5962R9667601VEC | C | 05/31/2000 | | (NONE) | | | CD40160BDMSR | 301 |
| 5962R9667601VXC | C | 05/31/2000 | | (NONE) | | | CD40160BKMSR | 301 |
| 5962R9667602V9A | C | 05/31/2000 | | (NONE) | | | 40161B (GEN) | 304 |
| 5962R9667602VEC | C | 05/31/2000 | | (NONE) | | | 40161B (GEN) | 304 |
| 5962R9667602VXC | C | 05/31/2000 | | (NONE) | | | 40161B (GEN) | 304 |
| 5962R9667603V9A | C | 05/31/2000 | | (NONE) | | | 40162B (GEN) | 301 |
| 5962R9667603VEC | C | 05/31/2000 | | (NONE) | | | 40162B (GEN) | 301 |
| 5962R9667603VXC | C | 05/31/2000 | | (NONE) | | | 40162B (GEN) | 301 |
| 5962R9667604V9A | C | 05/31/2000 | | (NONE) | | | 40163B (GEN) | 304 |
| 5962R9667604VEC | C | 05/31/2000 | | (NONE) | | | 40163B (GEN) | 304 |
| 5962R9667604VXC | C | 05/31/2000 | | (NONE) | | | 40163B (GEN) | 304 |
| 5962R9667605V9A | C | 05/31/2000 | | (NONE) | | | 40161B (GEN) | 304 |
| 5962R9667605VEC | C | 05/31/2000 | | (NONE) | | | 40161B (GEN) | 304 |
| 5962R9667605VXC | C | 05/31/2000 | | (NONE) | | | 40161B (GEN) | 304 |
| 5962R9667701V9A | B | 05/31/2000 | | (NONE) | | | 40257B (GEN) | 276 |
| 5962R9667701VEC | B | 05/31/2000 | | (NONE) | | | 40257B (GEN) | 276 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962R9667701VXC | B | 05/31/2000 | | (NONE) | | | 40257B (GEN) | 276 |
| 5962R9667702V9A | B | 05/31/2000 | | (NONE) | | | 40257BN (GEN) | 276 |
| 5962R9667702VEC | B | 05/31/2000 | | (NONE) | | | 40257BN (GEN) | 276 |
| 5962R9667702VXC | B | 05/31/2000 | | (NONE) | | | 40257BN (GEN) | 276 |
| 5962R9667801V9A | C | 06/02/2000 | | (NONE) | | | 4034B (GEN) | 249 |
| 5962R9667801VJC | C | 06/02/2000 | | (NONE) | | | 4034B (GEN) | 249 |
| 5962R9667801VXC | C | 06/02/2000 | | (NONE) | | | 4034B (GEN) | 249 |
| 5962R9667802VJA | C | 06/02/2000 | | (NONE) | | | 4034BN (GEN) | 249 |
| 5962R9667802VXA | C | 06/02/2000 | | (NONE) | | | 4034BN (GEN) | 249 |
| 5962R9667901V9A | C | 06/02/2000 | | (NONE) | | | 4067B (GEN) | 195 |
| 5962R9667901VLC | C | 06/02/2000 | | (NONE) | | | 4067B (GEN) | 195 |
| 5962R9667901VXC | C | 06/02/2000 | | (NONE) | | | 4067B (GEN) | 195 |
| 5962R9667902V9A | C | 06/02/2000 | | (NONE) | | | 4097B (GEN) | 194 |
| 5962R9667902VLC | C | 06/02/2000 | | (NONE) | | | 4097B (GEN) | 194 |
| 5962R9667902VXC | C | 06/02/2000 | | (NONE) | | | 4097B (GEN) | 194 |
| 5962R9668001V9A | C | 06/05/2000 | | (NONE) | | | 4508B (GEN) | 340 |
| 5962R9668001VLC | C | 06/05/2000 | | (NONE) | | | 4508B (GEN) | 340 |
| 5962R9668001VXC | C | 06/05/2000 | | (NONE) | | | 4508B (GEN) | 340 |
| 5962R9668002V9A | C | 06/05/2000 | | (NONE) | | | 4508BN (GEN) | 340 |
| 5962R9668002VLC | C | 06/05/2000 | | (NONE) | | | 4508BN (GEN) | 340 |
| 5962R9668002VXC | C | 06/05/2000 | | (NONE) | | | 4508BN (GEN) | 340 |
| 5962R9668101V9A | C | 04/13/2004 | 1 | INTERSIL | | Y | CD4514BHSR | 340 |
| 5962R9668101VJC | C | 04/13/2004 | 1 | INTERSIL | | Y | CD4514BDMSR | 340 |
| 5962R9668101VXC | C | 04/13/2004 | 1 | INTERSIL | | Y | CD4514BKMSR | 340 |
| 5962R9668102V9A | C | 04/13/2004 | | (NONE) | | | 4515B (GEN) | 280 |
| 5962R9668102VJC | C | 04/13/2004 | | (NONE) | | | 4515B (GEN) | 280 |
| 5962R9668102VXC | C | 04/13/2004 | | (NONE) | | | 4515B (GEN) | 280 |
| 5962R9668103V9A | C | 04/13/2004 | | (NONE) | | | 4014BN (GEN) | 340 |
| 5962R9668103VJC | C | 04/13/2004 | | (NONE) | | | 4514BN (GEN) | 340 |
| 5962R9668103VXC | C | 04/13/2004 | | (NONE) | | | 4514BN (GEN) | 340 |
| 5962R9668104V9A | C | 04/13/2004 | | (NONE) | | | 4015BN (GEN) | 280 |
| 5962R9668104VJC | C | 04/13/2004 | | (NONE) | | | 4515BN (GEN) | 280 |
| 5962R9668104VXC | C | 04/13/2004 | | (NONE) | | | 4515BN (GEN) | 280 |
| 5962R9668201V9A | C | 06/06/2000 | | (NONE) | | | 40108B (GEN) | 249 |
| 5962R9668201VJC | C | 06/06/2000 | | (NONE) | | | 40108B (GEN) | 249 |
| 5962R9668201VXC | C | 06/06/2000 | | (NONE) | | | 40108B (GEN) | 249 |
| 5962R9668301VJC | | 01/04/1996 | | (NONE) | | | 40181B (GEN) | 205 |
| 5962R9668301VXC | | 01/04/1996 | | (NONE) | | | 40181B (GEN) | 205 |
| 5962R9668401V9A | B | 06/06/2000 | | (NONE) | | | 40208B (GEN) | 249 |
| 5962R9668401VLC | B | 06/06/2000 | | (NONE) | | | CD40208B (GEN) | 249 |
| 5962R9668401VXC | B | 06/06/2000 | | (NONE) | | | CD40208B (GEN) | 249 |
| 5962-9668501QXA | C | 08/19/2003 | 2 | TI | | Y | SNJ54LVTH16244AWD | 529 |
| 5962-9668501VXA | C | 08/19/2003 | 2 | TI | | Y | SNV54LVTH16244AWD | 529 |
| 5962-9668601QXA | C | 09/05/2003 | 3 | TI | | Y | SNJ54LVTH16245AWD | 590 |
| 5962-9668601VXA | C | 09/05/2003 | 3 | TI | | Y | SNV54LVTH16245AWD | 590 |
| 5962-9668701HXA | A | 07/12/2002 | 1 | MS KENNEDY | | Y | MSK1120B | 899 |
| 5962-9668701HXC | A | 07/12/2002 | 1 | MS KENNEDY | | Y | MSK1120B | 899 |
| 5962-9668801QKA | A | 07/19/2002 | 2 | TI | | Y | SNJ54CBT3383W | 399 |
| 5962-9668801QLA | A | 07/19/2002 | 2 | TI | | Y | SNJ54CBT3383JT | 399 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9668901HXA | | 04/15/1997 | 1 | WHITE ELEC. | | Y | WE128K16-300CQA | 661 |
| 5962-9668901HXC | | 04/15/1997 | 1 | WHITE ELEC. | | Y | WE128K16-300CQ | 661 |
| 5962-9668902HXA | | 04/15/1997 | 1 | WHITE ELEC. | | Y | WE128K16-250CQA | 661 |
| 5962-9668902HXC | | 04/15/1997 | 1 | WHITE ELEC. | | Y | WE128K16-250CQ | 661 |
| 5962-9668903HXA | | 04/15/1997 | 1 | WHITE ELEC. | | Y | WE128K16-200CQA | 661 |
| 5962-9668903HXC | | 04/15/1997 | 1 | WHITE ELEC. | | Y | WE128K16-200CQ | 661 |
| 5962-9668904HXA | | 04/15/1997 | 1 | WHITE ELEC. | | Y | WE128K16-150CQA | 661 |
| 5962-9668904HXC | | 04/15/1997 | 1 | WHITE ELEC. | | Y | WE128K16-150CQ | 661 |
| 5962-9669001HTA | G | 04/21/2003 | 1 | AEROFLEX | | Y | ACT-F128K8N-150F6Q | 669 |
| 5962-9669001HTA | G | 04/21/2003 | 1 | AUSTIN SEMI. | | Y | AS29F010F-150/Q | 669 |
| 5962-9669001HTA | G | 04/21/2003 | 1 | WHITE ELEC. | | Y | WMF128K8-150FEQ5 | 669 |
| 5962-9669001HTC | G | 04/21/2003 | 1 | AEROFLEX | | Y | ACT-F128K8N-150F6Q | 669 |
| 5962-9669001HTC | G | 04/21/2003 | 1 | AUSTIN SEMI. | | Y | AS29F010F-150/Q | 669 |
| 5962-9669001HTC | G | 04/21/2003 | 1 | WHITE ELEC. | | Y | WMF128K8-150FEQ5 | 669 |
| 5962-9669001HUA | G | 04/21/2003 | 1 | AEROFLEX | | Y | ACT-F128K8N-150F7Q | 669 |
| 5962-9669001HUA | G | 04/21/2003 | 1 | AUSTIN SEMI. | | Y | AS29F010DCG-150/Q | 669 |
| 5962-9669001HUA | G | 04/21/2003 | 1 | WHITE ELEC. | | Y | WMF128K8-150FFQ5 | 669 |
| 5962-9669001HUC | G | 04/21/2003 | 1 | AEROFLEX | | Y | ACT-F128K8N-150F7Q | 669 |
| 5962-9669001HUC | G | 04/21/2003 | 1 | AUSTIN SEMI. | | Y | AS29F010DCG-150/Q | 669 |
| 5962-9669001HUC | G | 04/21/2003 | 1 | WHITE ELEC. | | Y | WMF128K8-150FFQ5 | 669 |
| 5962-9669001HXA | G | 04/21/2003 | 1 | WHITE ELEC. | | Y | WMF128K8-150DEQ5 | 669 |
| 5962-9669001HXC | G | 04/21/2003 | 1 | WHITE ELEC. | | Y | WMF128K8-150DEQ5 | 669 |
| 5962-9669001HYA | G | 04/21/2003 | 1 | AEROFLEX | | Y | ACT-F128K8N-150P4Q | 669 |
| 5962-9669001HYA | G | 04/21/2003 | 1 | AUSTIN SEMI. | | Y | AS29F010CW-150/Q | 669 |
| 5962-9669001HYA | G | 04/21/2003 | 1 | WHITE ELEC. | | Y | WMF128K8-150CQ5 | 669 |
| 5962-9669001HYC | G | 04/21/2003 | 1 | AEROFLEX | | Y | ACT-F128K8N-150P4Q | 669 |
| 5962-9669001HYC | G | 04/21/2003 | 1 | AUSTIN SEMI. | | Y | AS29F010CW-150/Q | 669 |
| 5962-9669001HYC | G | 04/21/2003 | 1 | WHITE ELEC. | | Y | WMF128K8-150CQ5 | 669 |
| 5962-9669002HTA | G | 04/21/2003 | 1 | AEROFLEX | | Y | ACT-F128K8N-120F6Q | 669 |
| 5962-9669002HTA | G | 04/21/2003 | 1 | AUSTIN SEMI. | | Y | AS29F010F-120/Q | 669 |
| 5962-9669002HTA | G | 04/21/2003 | 1 | WHITE ELEC. | | Y | WMF128K8-120FEQ5 | 669 |
| 5962-9669002HTC | G | 04/21/2003 | 1 | AEROFLEX | | Y | ACT-F128K8N-120F6Q | 669 |
| 5962-9669002HTC | G | 04/21/2003 | 1 | AUSTIN SEMI. | | Y | AS29F010F-120/Q | 669 |
| 5962-9669002HTC | G | 04/21/2003 | 1 | WHITE ELEC. | | Y | WMF128K8-120FEQ5 | 669 |
| 5962-9669002HUA | G | 04/21/2003 | 1 | AEROFLEX | | Y | ACT-F128K8N-120F7Q | 669 |
| 5962-9669002HUA | G | 04/21/2003 | 1 | AUSTIN SEMI. | | Y | AS29F010DCG-120/Q | 669 |
| 5962-9669002HUA | G | 04/21/2003 | 1 | WHITE ELEC. | | Y | WMF128K8-120FFQ5 | 669 |
| 5962-9669002HUC | G | 04/21/2003 | 1 | AEROFLEX | | Y | ACT-F128K8N-120F7Q | 669 |
| 5962-9669002HUC | G | 04/21/2003 | 1 | AUSTIN SEMI. | | Y | AS29F010DCG-120/Q | 669 |
| 5962-9669002HUC | G | 04/21/2003 | 1 | WHITE ELEC. | | Y | WMF128K8-120FFQ5 | 669 |
| 5962-9669002HXA | G | 04/21/2003 | 1 | WHITE ELEC. | | Y | WMF128K8-120DEQ5 | 669 |
| 5962-9669002HXC | G | 04/21/2003 | 1 | WHITE ELEC. | | Y | WMF128K8-120DEQ5 | 669 |
| 5962-9669002HYA | G | 04/21/2003 | 1 | AEROFLEX | | Y | ACT-F128K8N-120P4Q | 669 |
| 5962-9669002HYA | G | 04/21/2003 | 1 | AUSTIN SEMI. | | Y | AS29F010CW-120/Q | 669 |
| 5962-9669002HYA | G | 04/21/2003 | 1 | WHITE ELEC. | | Y | WMF128K8-120CQ5 | 669 |
| 5962-9669002HYC | G | 04/21/2003 | 1 | AEROFLEX | | Y | ACT-F128K8N-120P4Q | 669 |
| 5962-9669002HYC | G | 04/21/2003 | 1 | AUSTIN SEMI. | | Y | AS29F010CW-120/Q | 669 |
| 5962-9669002HYC | G | 04/21/2003 | 1 | WHITE ELEC. | | Y | WMF128K8-120CQ5 | 669 |
| 5962-9669003HTA | G | 04/21/2003 | 1 | AEROFLEX | | Y | ACT-F128K8N-090F6Q | 669 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9669003HTA | G | 04/21/2003 | 1 | AUSTIN SEMI. | | Y | AS29F010F-90/Q | 669 |
| 5962-9669003HTA | G | 04/21/2003 | 1 | WHITE ELEC. | | Y | WMF128K8-90FEQ5 | 669 |
| 5962-9669003HTC | G | 04/21/2003 | 1 | AEROFLEX | | Y | ACT-F128K8N-090F6Q | 669 |
| 5962-9669003HTC | G | 04/21/2003 | 1 | AUSTIN SEMI. | | Y | AS29F010F-90/Q | 669 |
| 5962-9669003HTC | G | 04/21/2003 | 1 | WHITE ELEC. | | Y | WMF128K8-90FEQ5 | 669 |
| 5962-9669003HUA | G | 04/21/2003 | 1 | AEROFLEX | | Y | ACT-F128K8N-090F7Q | 669 |
| 5962-9669003HUA | G | 04/21/2003 | 1 | AUSTIN SEMI. | | Y | AS29F010DCG-90/Q | 669 |
| 5962-9669003HUA | G | 04/21/2003 | 1 | WHITE ELEC. | | Y | WMF128K8-90FFQ5 | 669 |
| 5962-9669003HUC | G | 04/21/2003 | 1 | AEROFLEX | | Y | ACT-F128K8N-090F7Q | 669 |
| 5962-9669003HUC | G | 04/21/2003 | 1 | AUSTIN SEMI. | | Y | AS29F010DCG-90/Q | 669 |
| 5962-9669003HUC | G | 04/21/2003 | 1 | WHITE ELEC. | | Y | WMF128K8-90FFQ5 | 669 |
| 5962-9669003HXA | G | 04/21/2003 | 1 | WHITE ELEC. | | Y | WMF128K8-90DEQ5 | 669 |
| 5962-9669003HXC | G | 04/21/2003 | 1 | WHITE ELEC. | | Y | WMF128K8-90DEQ5 | 669 |
| 5962-9669003HYA | G | 04/21/2003 | 1 | AEROFLEX | | Y | ACT-F128K8N-090P4Q | 669 |
| 5962-9669003HYA | G | 04/21/2003 | 1 | AUSTIN SEMI. | | Y | AS29F010CW-90/Q | 669 |
| 5962-9669003HYA | G | 04/21/2003 | 1 | WHITE ELEC. | | Y | WMF128K8-90CQ5 | 669 |
| 5962-9669003HYC | G | 04/21/2003 | 1 | AEROFLEX | | Y | ACT-F128K8N-090P4Q | 669 |
| 5962-9669003HYC | G | 04/21/2003 | 1 | AUSTIN SEMI. | | Y | AS29F010CW-90/Q | 669 |
| 5962-9669003HYC | G | 04/21/2003 | 1 | WHITE ELEC. | | Y | WMF128K8-90CQ5 | 669 |
| 5962-9669004HTA | G | 04/21/2003 | 1 | AEROFLEX | | Y | ACT-F128K8N-070F6Q | 669 |
| 5962-9669004HTA | G | 04/21/2003 | 1 | AUSTIN SEMI. | | Y | AS29F010F-70/Q | 669 |
| 5962-9669004HTA | G | 04/21/2003 | 1 | WHITE ELEC. | | Y | WMF128K8-70FEQ5 | 669 |
| 5962-9669004HTC | G | 04/21/2003 | 1 | AEROFLEX | | Y | ACT-F128K8N-070F6Q | 669 |
| 5962-9669004HTC | G | 04/21/2003 | 1 | AUSTIN SEMI. | | Y | AS29F010F-70/Q | 669 |
| 5962-9669004HTC | G | 04/21/2003 | 1 | WHITE ELEC. | | Y | WMF128K8-70FEQ5 | 669 |
| 5962-9669004HUA | G | 04/21/2003 | 1 | AEROFLEX | | Y | ACT-F128K8N-070F7Q | 669 |
| 5962-9669004HUA | G | 04/21/2003 | 1 | AUSTIN SEMI. | | Y | AS29F010DCG-70/Q | 669 |
| 5962-9669004HUA | G | 04/21/2003 | 1 | WHITE ELEC. | | Y | WMF128K8-70FFQ5 | 669 |
| 5962-9669004HUC | G | 04/21/2003 | 1 | AEROFLEX | | Y | ACT-F128K8N-070F7Q | 669 |
| 5962-9669004HUC | G | 04/21/2003 | 1 | AUSTIN SEMI. | | Y | AS29F010DCG-70/Q | 669 |
| 5962-9669004HUC | G | 04/21/2003 | 1 | WHITE ELEC. | | Y | WMF128K8-70FFQ5 | 669 |
| 5962-9669004HXA | G | 04/21/2003 | 1 | WHITE ELEC. | | Y | WMF128K8-70DEQ5 | 669 |
| 5962-9669004HXC | G | 04/21/2003 | 1 | WHITE ELEC. | | Y | WMF128K8-70DEQ5 | 669 |
| 5962-9669004HYA | G | 04/21/2003 | 1 | AEROFLEX | | Y | ACT-F128K8N-070P4Q | 669 |
| 5962-9669004HYA | G | 04/21/2003 | 1 | AUSTIN SEMI. | | Y | AS29F010CW-70/Q | 669 |
| 5962-9669004HYA | G | 04/21/2003 | 1 | WHITE ELEC. | | Y | WMF128K8-70CQ5 | 669 |
| 5962-9669004HYC | G | 04/21/2003 | 1 | AEROFLEX | | Y | ACT-F128K8N-070P4Q | 669 |
| 5962-9669004HYC | G | 04/21/2003 | 1 | AUSTIN SEMI. | | Y | AS29F010CW-70/Q | 669 |
| 5962-9669004HYC | G | 04/21/2003 | 1 | WHITE ELEC. | | Y | WMF128K8-70CQ5 | 669 |
| 5962-9669005HTA | G | 04/21/2003 | 1 | AEROFLEX | | Y | ACT-F128K8N-060F6Q | 669 |
| 5962-9669005HTA | G | 04/21/2003 | 1 | AUSTIN SEMI. | | Y | AS29F010F-60/Q | 669 |
| 5962-9669005HTA | G | 04/21/2003 | 1 | WHITE ELEC. | | Y | WMF128K8-60FEQ5 | 669 |
| 5962-9669005HTC | G | 04/21/2003 | 1 | AEROFLEX | | Y | ACT-F128K8N-060F6Q | 669 |
| 5962-9669005HTC | G | 04/21/2003 | 1 | AUSTIN SEMI. | | Y | AS29F010F-60/Q | 669 |
| 5962-9669005HTC | G | 04/21/2003 | 1 | WHITE ELEC. | | Y | WMF128K8-60FEQ5 | 669 |
| 5962-9669005HUA | G | 04/21/2003 | 1 | AEROFLEX | | Y | ACT-F128K8N-060F7Q | 669 |
| 5962-9669005HUA | G | 04/21/2003 | 1 | AUSTIN SEMI. | | Y | AS29F010DCG-60/Q | 669 |
| 5962-9669005HUA | G | 04/21/2003 | 1 | WHITE ELEC. | | Y | WMF128K8-60FFQ5 | 669 |
| 5962-9669005HUC | G | 04/21/2003 | 1 | AEROFLEX | | Y | ACT-F128K8N-060F7Q | 669 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9669005HUC | G | 04/21/2003 | 1 | AUSTIN SEMI. | | Y | AS29F010DCG-60/Q | 669 |
| 5962-9669005HUC | G | 04/21/2003 | 1 | WHITE ELEC. | | Y | WMF128K8-60FFQ5 | 669 |
| 5962-9669005HXA | G | 04/21/2003 | 1 | WHITE ELEC. | | Y | WMF128K8-60DEQ5 | 669 |
| 5962-9669005HXC | G | 04/21/2003 | 1 | WHITE ELEC. | | Y | WMF128K8-60DEQ5 | 669 |
| 5962-9669005HYA | G | 04/21/2003 | 1 | AEROFLEX | | Y | ACT-F128K8N-060P4Q | 669 |
| 5962-9669005HYA | G | 04/21/2003 | 1 | AUSTIN SEMI. | | Y | AS29F010CW-60/Q | 669 |
| 5962-9669005HYA | G | 04/21/2003 | 1 | WHITE ELEC. | | Y | WMF128K8-60CQ5 | 669 |
| 5962-9669005HYC | G | 04/21/2003 | 1 | AEROFLEX | | Y | ACT-F128K8N-060P4Q | 669 |
| 5962-9669005HYC | G | 04/21/2003 | 1 | AUSTIN SEMI. | | Y | AS29F010CW-60/Q | 669 |
| 5962-9669005HYC | G | 04/21/2003 | 1 | WHITE ELEC. | | Y | WMF128K8-60CQ5 | 669 |
| 5962-9669101HNA | C | 03/21/2001 | 1 | WHITE ELEC. | | Y | WMS128K8-120FE | 629 |
| 5962-9669101HNC | C | 03/21/2001 | 1 | WHITE ELEC. | | Y | WMS128K8-120FE | 629 |
| 5962-9669101HTA | C | 03/21/2001 | 1 | WHITE ELEC. | | Y | WMS128K8-120DE | 629 |
| 5962-9669101HTC | C | 03/21/2001 | 1 | WHITE ELEC. | | Y | WMS128K8-120DE | 629 |
| 5962-9669101HUA | C | 03/21/2001 | 1 | WHITE ELEC. | | Y | WMS128K8-120DR | 629 |
| 5962-9669101HUC | C | 03/21/2001 | 1 | WHITE ELEC. | | Y | WMS128K8-120DR | 629 |
| 5962-9669101HYA | C | 03/21/2001 | 1 | WHITE ELEC. | | Y | WMS128K8-120C | 629 |
| 5962-9669101HYC | C | 03/21/2001 | 1 | WHITE ELEC. | | Y | WMS128K8-120C | 629 |
| 5962-9669102HNA | C | 03/21/2001 | 1 | WHITE ELEC. | | Y | WMS128K8-100FE | 629 |
| 5962-9669102HNC | C | 03/21/2001 | 1 | WHITE ELEC. | | Y | WMS128K8-100FE | 629 |
| 5962-9669102HTA | C | 03/21/2001 | 1 | WHITE ELEC. | | Y | WMS128K8-100DE | 629 |
| 5962-9669102HTC | C | 03/21/2001 | 1 | WHITE ELEC. | | Y | WMS128K8-100DE | 629 |
| 5962-9669102HUA | C | 03/21/2001 | 1 | WHITE ELEC. | | Y | WMS128K8-100DR | 629 |
| 5962-9669102HUC | C | 03/21/2001 | 1 | WHITE ELEC. | | Y | WMS128K8-100DR | 629 |
| 5962-9669102HYA | C | 03/21/2001 | 1 | WHITE ELEC. | | Y | WMS128K8-100C | 629 |
| 5962-9669102HYC | C | 03/21/2001 | 1 | WHITE ELEC. | | Y | WMS128K8-100C | 629 |
| 5962-9669103HNA | C | 03/21/2001 | 1 | WHITE ELEC. | | Y | WMS128K8-85FE | 629 |
| 5962-9669103HNC | C | 03/21/2001 | 1 | WHITE ELEC. | | Y | WMS128K8-85FE | 629 |
| 5962-9669103HTA | C | 03/21/2001 | 1 | WHITE ELEC. | | Y | WMS128K8-85DE | 629 |
| 5962-9669103HTC | C | 03/21/2001 | 1 | WHITE ELEC. | | Y | WMS128K8-85DE | 629 |
| 5962-9669103HUA | C | 03/21/2001 | 1 | WHITE ELEC. | | Y | WMS128K8-85DR | 629 |
| 5962-9669103HUC | C | 03/21/2001 | 1 | WHITE ELEC. | | Y | WMS128K8-85DR | 629 |
| 5962-9669103HYA | C | 03/21/2001 | 1 | WHITE ELEC. | | Y | WMS128K8-85C | 629 |
| 5962-9669103HYC | C | 03/21/2001 | 1 | WHITE ELEC. | | Y | WMS128K8-85C | 629 |
| 5962-9669104HNA | C | 03/21/2001 | 1 | WHITE ELEC. | | Y | WMS128K8-70FE | 629 |
| 5962-9669104HNC | C | 03/21/2001 | 1 | WHITE ELEC. | | Y | WMS128K8-70FE | 629 |
| 5962-9669104HTA | C | 03/21/2001 | 1 | WHITE ELEC. | | Y | WMS128K8-70DE | 629 |
| 5962-9669104HTC | C | 03/21/2001 | 1 | WHITE ELEC. | | Y | WMS128K8-70DE | 629 |
| 5962-9669104HUA | C | 03/21/2001 | 1 | WHITE ELEC. | | Y | WMS128K8-70DR | 629 |
| 5962-9669104HUC | C | 03/21/2001 | 1 | WHITE ELEC. | | Y | WMS128K8-70DR | 629 |
| 5962-9669104HYA | C | 03/21/2001 | 1 | WHITE ELEC. | | Y | WMS128K8-70C | 629 |
| 5962-9669104HYC | C | 03/21/2001 | 1 | WHITE ELEC. | | Y | WMS128K8-70C | 629 |
| 5962-9669105HTA | C | 03/21/2001 | 1 | AUSTIN SEMI. | | Y | MT5C1009CW-55/H | 629 |
| 5962-9669105HTA | C | 03/21/2001 | 1 | WHITE ELEC. | | Y | WMS128K8-55DE | 629 |
| 5962-9669105HTC | C | 03/21/2001 | 1 | AUSTIN SEMI. | | Y | MT5C1009CW-55/H | 629 |
| 5962-9669105HTC | C | 03/21/2001 | 1 | WHITE ELEC. | | Y | WMS128K8-55DE | 629 |
| 5962-9669105HUA | C | 03/21/2001 | 1 | WHITE ELEC. | | Y | WMS128K8-55DR | 629 |
| 5962-9669105HUC | C | 03/21/2001 | 1 | WHITE ELEC. | | Y | WMS128K8-55DR | 629 |
| 5962-9669105HXA | C | 03/21/2001 | 1 | AUSTIN SEMI. | | Y | MT5C128K8F-55/H | 629 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9669105HXC | C | 03/21/2001 | 1 | AUSTIN SEMI. | | Y | MT5C128K8F-55/H | 629 |
| 5962-9669105HXC | C | 03/21/2001 | 1 | WHITE ELEC. | | Y | WMS128K8-55F | 629 |
| 5962-9669105HYA | C | 03/21/2001 | 1 | AUSTIN SEMI. | | Y | MT5C1009DCJ-55/H | 629 |
| 5962-9669105HYA | C | 03/21/2001 | 1 | WHITE ELEC. | | Y | WMS128K8-55C | 629 |
| 5962-9669105HYC | C | 03/21/2001 | 1 | AUSTIN SEMI. | | Y | MT5C1009DCJ-55/H | 629 |
| 5962-9669105HYC | C | 03/21/2001 | 1 | WHITE ELEC. | | Y | WMS128K8-55C | 629 |
| 5962-9669105HZA | C | 03/21/2001 | 1 | AUSTIN SEMI. | | Y | MT5C128K8ECJ-55/H | 629 |
| 5962-9669105HZA | C | 03/21/2001 | 1 | WHITE ELEC. | | Y | WMS128K8-55DJ | 629 |
| 5962-9669105HZC | C | 03/21/2001 | 1 | AUSTIN SEMI. | | Y | MT5C128K8ECJ-55/H | 629 |
| 5962-9669105HZC | C | 03/21/2001 | 1 | WHITE ELEC. | | Y | WMS128K8-55DJ | 629 |
| 5962-9669106HTA | C | 03/21/2001 | 1 | AUSTIN SEMI. | | Y | MT5C1009CW-45/H | 629 |
| 5962-9669106HTA | C | 03/21/2001 | 1 | WHITE ELEC. | | Y | WMS128K8-45DE | 629 |
| 5962-9669106HTC | C | 03/21/2001 | 1 | AUSTIN SEMI. | | Y | MT5C1009CW-45/H | 629 |
| 5962-9669106HTC | C | 03/21/2001 | 1 | WHITE ELEC. | | Y | WMS128K8-45DE | 629 |
| 5962-9669106HUA | C | 03/21/2001 | 1 | WHITE ELEC. | | Y | WMS128K8-45DR | 629 |
| 5962-9669106HUC | C | 03/21/2001 | 1 | WHITE ELEC. | | Y | WMS128K8-45DR | 629 |
| 5962-9669106HXA | C | 03/21/2001 | 1 | AUSTIN SEMI. | | Y | MT5C128K8F-45/H | 629 |
| 5962-9669106HXC | C | 03/21/2001 | 1 | AUSTIN SEMI. | | Y | MT5C128K8F-45/H | 629 |
| 5962-9669106HXC | C | 03/21/2001 | 1 | WHITE ELEC. | | Y | WMS128K8-45F | 629 |
| 5962-9669106HYA | C | 03/21/2001 | 1 | AUSTIN SEMI. | | Y | MT5C1009DCJ-45/H | 629 |
| 5962-9669106HYA | C | 03/21/2001 | 1 | WHITE ELEC. | | Y | WMS128K8-45C | 629 |
| 5962-9669106HYC | C | 03/21/2001 | 1 | AUSTIN SEMI. | | Y | MT5C1009DCJ-45/H | 629 |
| 5962-9669106HYC | C | 03/21/2001 | 1 | WHITE ELEC. | | Y | WMS128K8-45C | 629 |
| 5962-9669106HZA | C | 03/21/2001 | 1 | AUSTIN SEMI. | | Y | MT5C128K8ECJ-45/H | 629 |
| 5962-9669106HZA | C | 03/21/2001 | 1 | WHITE ELEC. | | Y | WMS128K8-45DJ | 629 |
| 5962-9669106HZC | C | 03/21/2001 | 1 | AUSTIN SEMI. | | Y | MT5C128K8ECJ-45/H | 629 |
| 5962-9669106HZC | C | 03/21/2001 | 1 | WHITE ELEC. | | Y | WMS128K8-45DJ | 629 |
| 5962-9669107HTA | C | 03/21/2001 | 1 | AUSTIN SEMI. | | Y | MT5C1009CW-35/H | 629 |
| 5962-9669107HTA | C | 03/21/2001 | 1 | WHITE ELEC. | | Y | WMS128K8-35DE | 629 |
| 5962-9669107HTC | C | 03/21/2001 | 1 | AUSTIN SEMI. | | Y | MT5C1009CW-35/H | 629 |
| 5962-9669107HTC | C | 03/21/2001 | 1 | WHITE ELEC. | | Y | WMS128K8-35DE | 629 |
| 5962-9669107HUA | C | 03/21/2001 | 1 | WHITE ELEC. | | Y | WMS128K8-35DR | 629 |
| 5962-9669107HUC | C | 03/21/2001 | 1 | WHITE ELEC. | | Y | WMS128K8-35DR | 629 |
| 5962-9669107HXA | C | 03/21/2001 | 1 | AUSTIN SEMI. | | Y | MT5C128K8F-35/H | 629 |
| 5962-9669107HXC | C | 03/21/2001 | 1 | AUSTIN SEMI. | | Y | MT5C128K8F-35/H | 629 |
| 5962-9669107HXC | C | 03/21/2001 | 1 | WHITE ELEC. | | Y | WMS128K8-35F | 629 |
| 5962-9669107HYA | C | 03/21/2001 | 1 | AUSTIN SEMI. | | Y | MT5C1009DCJ-35/H | 629 |
| 5962-9669107HYA | C | 03/21/2001 | 1 | WHITE ELEC. | | Y | WMS128K8-35C | 629 |
| 5962-9669107HYC | C | 03/21/2001 | 1 | AUSTIN SEMI. | | Y | MT5C1009DCJ-35/H | 629 |
| 5962-9669107HYC | C | 03/21/2001 | 1 | WHITE ELEC. | | Y | WMS128K8-35C | 629 |
| 5962-9669107HZA | C | 03/21/2001 | 1 | AUSTIN SEMI. | | Y | MT5C128K8ECJ-35/H | 629 |
| 5962-9669107HZA | C | 03/21/2001 | 1 | WHITE ELEC. | | Y | WMS128K8-35DJ | 629 |
| 5962-9669107HZC | C | 03/21/2001 | 1 | AUSTIN SEMI. | | Y | MT5C128K8ECJ-35/H | 629 |
| 5962-9669107HZC | C | 03/21/2001 | 1 | WHITE ELEC. | | Y | WMS128K8-35DJ | 629 |
| 5962-9669108HTA | C | 03/21/2001 | 1 | AUSTIN SEMI. | | Y | MT5C1009CW-25/H | 629 |
| 5962-9669108HTA | C | 03/21/2001 | 1 | WHITE ELEC. | | Y | WMS128K8-25DE | 629 |
| 5962-9669108HTC | C | 03/21/2001 | 1 | AUSTIN SEMI. | | Y | MT5C1009CW-25/H | 629 |
| 5962-9669108HTC | C | 03/21/2001 | 1 | WHITE ELEC. | | Y | WMS128K8-25DE | 629 |
| 5962-9669108HUA | C | 03/21/2001 | 1 | WHITE ELEC. | | Y | WMS128K8-25DR | 629 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9669108HUC | C | 03/21/2001 | 1 | WHITE ELEC. | | Y | WMS128K8-25DR | 629 |
| 5962-9669108HXA | C | 03/21/2001 | 1 | AUSTIN SEMI. | | Y | MT5C128K8F-25/H | 629 |
| 5962-9669108HXC | C | 03/21/2001 | 1 | AUSTIN SEMI. | | Y | MT5C128K8F-25/H | 629 |
| 5962-9669108HXC | C | 03/21/2001 | 1 | WHITE ELEC. | | Y | WMS128K8-25F | 629 |
| 5962-9669108HYA | C | 03/21/2001 | 1 | AUSTIN SEMI. | | Y | MT5C1009DCJ-25/H | 629 |
| 5962-9669108HYA | C | 03/21/2001 | 1 | WHITE ELEC. | | Y | WMS128K8-25C | 629 |
| 5962-9669108HYC | C | 03/21/2001 | 1 | AUSTIN SEMI. | | Y | MT5C1009DCJ-25/H | 629 |
| 5962-9669108HYC | C | 03/21/2001 | 1 | WHITE ELEC. | | Y | WMS128K8-25C | 629 |
| 5962-9669108HZA | C | 03/21/2001 | 1 | AUSTIN SEMI. | | Y | MT5C128K8ECJ-25/H | 629 |
| 5962-9669108HZA | C | 03/21/2001 | 1 | WHITE ELEC. | | Y | WMS128K8-25DJ | 629 |
| 5962-9669108HZC | C | 03/21/2001 | 1 | AUSTIN SEMI. | | Y | MT5C128K8ECJ-25/H | 629 |
| 5962-9669108HZC | C | 03/21/2001 | 1 | WHITE ELEC. | | Y | WMS128K8-25DJ | 629 |
| 5962-9669109HTA | C | 03/21/2001 | 1 | AUSTIN SEMI. | | Y | MT5C1009CW-20/H | 629 |
| 5962-9669109HTA | C | 03/21/2001 | 1 | WHITE ELEC. | | Y | WMS128K8-20DE | 629 |
| 5962-9669109HTC | C | 03/21/2001 | 1 | AUSTIN SEMI. | | Y | MT5C1009CW-20/H | 629 |
| 5962-9669109HTC | C | 03/21/2001 | 1 | WHITE ELEC. | | Y | WMS128K8-20DE | 629 |
| 5962-9669109HUA | C | 03/21/2001 | 1 | WHITE ELEC. | | Y | WMS128K8-20DR | 629 |
| 5962-9669109HUC | C | 03/21/2001 | 1 | WHITE ELEC. | | Y | WMS128K8-20DR | 629 |
| 5962-9669109HXA | C | 03/21/2001 | 1 | AUSTIN SEMI. | | Y | MT5C128K8F-20/H | 629 |
| 5962-9669109HXC | C | 03/21/2001 | 1 | AUSTIN SEMI. | | Y | MT5C128K8F-20/H | 629 |
| 5962-9669109HXC | C | 03/21/2001 | 1 | WHITE ELEC. | | Y | WMS128K8-20F | 629 |
| 5962-9669109HYA | C | 03/21/2001 | 1 | AUSTIN SEMI. | | Y | MT5C1009DCJ-20/H | 629 |
| 5962-9669109HYA | C | 03/21/2001 | 1 | WHITE ELEC. | | Y | WMS128K8-20C | 629 |
| 5962-9669109HYC | C | 03/21/2001 | 1 | AUSTIN SEMI. | | Y | MT5C1009DCJ-20/H | 629 |
| 5962-9669109HYC | C | 03/21/2001 | 1 | WHITE ELEC. | | Y | WMS128K8-20C | 629 |
| 5962-9669109HZA | C | 03/21/2001 | 1 | AUSTIN SEMI. | | Y | MT5C128K8ECJ-20/H | 629 |
| 5962-9669109HZA | C | 03/21/2001 | 1 | WHITE ELEC. | | Y | WMS128K8-20DJ | 629 |
| 5962-9669109HZC | C | 03/21/2001 | 1 | AUSTIN SEMI. | | Y | MT5C128K8ECJ-20/H | 629 |
| 5962-9669109HZC | C | 03/21/2001 | 1 | WHITE ELEC. | | Y | WMS128K8-20DJ | 629 |
| 5962-9669110HTA | C | 03/21/2001 | 1 | AUSTIN SEMI. | | Y | MT5C1009CW-17/H | 629 |
| 5962-9669110HTA | C | 03/21/2001 | 1 | WHITE ELEC. | | Y | WMS128K8-17DE | 629 |
| 5962-9669110HTC | C | 03/21/2001 | 1 | AUSTIN SEMI. | | Y | MT5C1009CW-17/H | 629 |
| 5962-9669110HTC | C | 03/21/2001 | 1 | WHITE ELEC. | | Y | WMS128K8-17DE | 629 |
| 5962-9669110HUA | C | 03/21/2001 | 1 | WHITE ELEC. | | Y | WMS128K8-17DR | 629 |
| 5962-9669110HUC | C | 03/21/2001 | 1 | WHITE ELEC. | | Y | WMS128K8-17DR | 629 |
| 5962-9669110HXA | C | 03/21/2001 | 1 | AUSTIN SEMI. | | Y | MT5C128K8F-17/H | 629 |
| 5962-9669110HXC | C | 03/21/2001 | 1 | AUSTIN SEMI. | | Y | MT5C128K8F-17/H | 629 |
| 5962-9669110HXC | C | 03/21/2001 | 1 | WHITE ELEC. | | Y | WMS128K8-17F | 629 |
| 5962-9669110HYA | C | 03/21/2001 | 1 | AUSTIN SEMI. | | Y | MT5C1009DCJ-17/H | 629 |
| 5962-9669110HYA | C | 03/21/2001 | 1 | WHITE ELEC. | | Y | WMS128K8-17C | 629 |
| 5962-9669110HYC | C | 03/21/2001 | 1 | AUSTIN SEMI. | | Y | MT5C1009DCJ-17/H | 629 |
| 5962-9669110HYC | C | 03/21/2001 | 1 | WHITE ELEC. | | Y | WMS128K8-17C | 629 |
| 5962-9669110HZA | C | 03/21/2001 | 1 | AUSTIN SEMI. | | Y | MT5C128K8ECJ-17/H | 629 |
| 5962-9669110HZA | C | 03/21/2001 | 1 | WHITE ELEC. | | Y | WMS128K8-17DJ | 629 |
| 5962-9669110HZC | C | 03/21/2001 | 1 | AUSTIN SEMI. | | Y | MT5C128K8ECJ-17/H | 629 |
| 5962-9669110HZC | C | 03/21/2001 | 1 | WHITE ELEC. | | Y | WMS128K8-17DJ | 629 |
| 5962-9669111HTA | C | 03/21/2001 | 1 | WHITE ELEC. | | Y | WMS128K8-15DE | 629 |
| 5962-9669111HTC | C | 03/21/2001 | 1 | WHITE ELEC. | | Y | WMS128K8-15DE | 629 |
| 5962-9669111HUA | C | 03/21/2001 | 1 | WHITE ELEC. | | Y | WMS128K8-15DR | 629 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9669111HUC | C | 03/21/2001 | 1 | WHITE ELEC. | | Y | WMS128K8-15DR | 629 |
| 5962-9669111HXC | C | 03/21/2001 | 1 | WHITE ELEC. | | Y | WMS128K8-15F | 629 |
| 5962-9669111HYA | C | 03/21/2001 | 1 | WHITE ELEC. | | Y | WMS128K8-15C | 629 |
| 5962-9669111HYC | C | 03/21/2001 | 1 | WHITE ELEC. | | Y | WMS128K8-15C | 629 |
| 5962-9669111HZA | C | 03/21/2001 | 1 | WHITE ELEC. | | Y | WMS128K8-15DJ | 629 |
| 5962-9669111HZC | C | 03/21/2001 | 1 | WHITE ELEC. | | Y | WMS128K8-15DJ | 629 |
| 5962-9669112HTA | C | 03/21/2001 | 1 | AUSTIN SEMI. | | Y | MT5C1009CW-55L/H | 629 |
| 5962-9669112HTC | C | 03/21/2001 | 1 | AUSTIN SEMI. | | Y | MT5C1009CW-55L/H | 629 |
| 5962-9669112HXA | C | 03/21/2001 | 1 | AUSTIN SEMI. | | Y | MT5C128K8F-55L/H | 629 |
| 5962-9669112HXC | C | 03/21/2001 | 1 | AUSTIN SEMI. | | Y | MT5C128K8F-55L/H | 629 |
| 5962-9669112HYA | C | 03/21/2001 | 1 | AUSTIN SEMI. | | Y | MT5C1009DCJ-55L/H | 629 |
| 5962-9669112HYC | C | 03/21/2001 | 1 | AUSTIN SEMI. | | Y | MT5C1009DCJ-55L/H | 629 |
| 5962-9669112HZA | C | 03/21/2001 | 1 | AUSTIN SEMI. | | Y | MT5C128K8ECJ-55L/H | 629 |
| 5962-9669112HZC | C | 03/21/2001 | 1 | AUSTIN SEMI. | | Y | MT5C128K8ECJ-55L/H | 629 |
| 5962-9669113HTA | C | 03/21/2001 | 1 | AUSTIN SEMI. | | Y | MT5C1009CW-45L/H | 629 |
| 5962-9669113HTC | C | 03/21/2001 | 1 | AUSTIN SEMI. | | Y | MT5C1009CW-45L/H | 629 |
| 5962-9669113HXA | C | 03/21/2001 | 1 | AUSTIN SEMI. | | Y | MT5C128K8F-45L/H | 629 |
| 5962-9669113HXC | C | 03/21/2001 | 1 | AUSTIN SEMI. | | Y | MT5C128K8F-45L/H | 629 |
| 5962-9669113HYA | C | 03/21/2001 | 1 | AUSTIN SEMI. | | Y | MT5C1009DCJ-45L/H | 629 |
| 5962-9669113HYC | C | 03/21/2001 | 1 | AUSTIN SEMI. | | Y | MT5C1009DCJ-45L/H | 629 |
| 5962-9669113HZA | C | 03/21/2001 | 1 | AUSTIN SEMI. | | Y | MT5C128K8ECJ-45L/H | 629 |
| 5962-9669113HZC | C | 03/21/2001 | 1 | AUSTIN SEMI. | | Y | MT5C128K8ECJ-45L/H | 629 |
| 5962-9669114HTA | C | 03/21/2001 | 1 | AUSTIN SEMI. | | Y | MT5C1009CW-35L/H | 629 |
| 5962-9669114HTC | C | 03/21/2001 | 1 | AUSTIN SEMI. | | Y | MT5C1009CW-35L/H | 629 |
| 5962-9669114HXA | C | 03/21/2001 | 1 | AUSTIN SEMI. | | Y | MT5C128K8F-35L/H | 629 |
| 5962-9669114HXC | C | 03/21/2001 | 1 | AUSTIN SEMI. | | Y | MT5C128K8F-35L/H | 629 |
| 5962-9669114HYA | C | 03/21/2001 | 1 | AUSTIN SEMI. | | Y | MT5C1009DCJ-35L/H | 629 |
| 5962-9669114HYC | C | 03/21/2001 | 1 | AUSTIN SEMI. | | Y | MT5C1009DCJ-35L/H | 629 |
| 5962-9669114HZA | C | 03/21/2001 | 1 | AUSTIN SEMI. | | Y | MT5C128K8ECJ-35L/H | 629 |
| 5962-9669114HZC | C | 03/21/2001 | 1 | AUSTIN SEMI. | | Y | MT5C128K8ECJ-35L/H | 629 |
| 5962-9669115HTA | C | 03/21/2001 | 1 | AUSTIN SEMI. | | Y | MT5C1009CW-25L/H | 629 |
| 5962-9669115HTC | C | 03/21/2001 | 1 | AUSTIN SEMI. | | Y | MT5C1009CW-25L/H | 629 |
| 5962-9669115HXA | C | 03/21/2001 | 1 | AUSTIN SEMI. | | Y | MT5C128K8F-25L/H | 629 |
| 5962-9669115HXC | C | 03/21/2001 | 1 | AUSTIN SEMI. | | Y | MT5C128K8F-25L/H | 629 |
| 5962-9669115HYA | C | 03/21/2001 | 1 | AUSTIN SEMI. | | Y | MT5C1009DCJ-25L/H | 629 |
| 5962-9669115HYC | C | 03/21/2001 | 1 | AUSTIN SEMI. | | Y | MT5C1009DCJ-25L/H | 629 |
| 5962-9669115HZA | C | 03/21/2001 | 1 | AUSTIN SEMI. | | Y | MT5C128K8ECJ-25L/H | 629 |
| 5962-9669115HZC | C | 03/21/2001 | 1 | AUSTIN SEMI. | | Y | MT5C128K8ECJ-25L/H | 629 |
| 5962-9669116HTA | C | 03/21/2001 | 1 | AUSTIN SEMI. | | Y | MT5C1009CW-20L/H | 629 |
| 5962-9669116HTC | C | 03/21/2001 | 1 | AUSTIN SEMI. | | Y | MT5C1009CW-20L/H | 629 |
| 5962-9669116HXA | C | 03/21/2001 | 1 | AUSTIN SEMI. | | Y | MT5C128K8F-20L/H | 629 |
| 5962-9669116HXC | C | 03/21/2001 | 1 | AUSTIN SEMI. | | Y | MT5C128K8F-20L/H | 629 |
| 5962-9669116HYA | C | 03/21/2001 | 1 | AUSTIN SEMI. | | Y | MT5C1009DCJ-20L/H | 629 |
| 5962-9669116HYC | C | 03/21/2001 | 1 | AUSTIN SEMI. | | Y | MT5C1009DCJ-20L/H | 629 |
| 5962-9669116HZA | C | 03/21/2001 | 1 | AUSTIN SEMI. | | Y | MT5C128K8ECJ-20L/H | 629 |
| 5962-9669116HZC | C | 03/21/2001 | 1 | AUSTIN SEMI. | | Y | MT5C128K8ECJ-20L/H | 629 |
| 5962-9669117HTA | C | 03/21/2001 | 1 | AUSTIN SEMI. | | Y | MT5C1009CW-17L/H | 629 |
| 5962-9669117HTC | C | 03/21/2001 | 1 | AUSTIN SEMI. | | Y | MT5C1009CW-17L/H | 629 |
| 5962-9669117HXA | C | 03/21/2001 | 1 | AUSTIN SEMI. | | Y | MT5C128K8F-17L/H | 629 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9669117HXC | C | 03/21/2001 | 1 | AUSTIN SEMI. | | Y | MT5C128K8F-17L/H | 629 |
| 5962-9669117HYA | C | 03/21/2001 | 1 | AUSTIN SEMI. | | Y | MT5C1009DCJ-17L/H | 629 |
| 5962-9669117HYC | C | 03/21/2001 | 1 | AUSTIN SEMI. | | Y | MT5C1009DCJ-17L/H | 629 |
| 5962-9669117HZA | C | 03/21/2001 | 1 | AUSTIN SEMI. | | Y | MT5C128K8ECJ-17L/H | 629 |
| 5962-9669117HZC | C | 03/21/2001 | 1 | AUSTIN SEMI. | | Y | MT5C128K8ECJ-17L/H | 629 |
| 5962-9669201HTA | E | 03/17/2003 | 1 | AEROFLEX | | Y | ACT-F512K8N-150F7Q | 669 |
| 5962-9669201HTA | E | 03/17/2003 | 1 | AUSTIN SEMI. | | Y | AS29F040DCG-150/Q | 669 |
| 5962-9669201HTA | E | 03/17/2003 | 1 | WHITE ELEC. | | Y | WMF512K8-150FFQ5 | 669 |
| 5962-9669201HTC | E | 03/17/2003 | 1 | AEROFLEX | | Y | ACT-F512K8N-150F7Q | 669 |
| 5962-9669201HTC | E | 03/17/2003 | 1 | AUSTIN SEMI. | | Y | AS29F040DCG-150/Q | 669 |
| 5962-9669201HTC | E | 03/17/2003 | 1 | WHITE ELEC. | | Y | WMF512K8-150FFQ5 | 669 |
| 5962-9669201HUA | E | 03/17/2003 | 1 | AEROFLEX | | Y | ACT-F512K8N-150F6Q | 669 |
| 5962-9669201HUA | E | 03/17/2003 | 1 | AUSTIN SEMI. | | Y | AS29F040F-150/Q | 669 |
| 5962-9669201HUA | E | 03/17/2003 | 1 | WHITE ELEC. | | Y | WMF512K8-150FEQ5 | 669 |
| 5962-9669201HUC | E | 03/17/2003 | 1 | AEROFLEX | | Y | ACT-F512K8N-150F6Q | 669 |
| 5962-9669201HUC | E | 03/17/2003 | 1 | AUSTIN SEMI. | | Y | AS29F040F-150/Q | 669 |
| 5962-9669201HUC | E | 03/17/2003 | 1 | WHITE ELEC. | | Y | WMF512K8-150FEQ5 | 669 |
| 5962-9669201HXA | E | 03/17/2003 | 1 | AEROFLEX | | Y | ACT-F512K8N-150P4Q | 669 |
| 5962-9669201HXA | E | 03/17/2003 | 1 | AUSTIN SEMI. | | Y | AS29F040CW-150/Q | 669 |
| 5962-9669201HXA | E | 03/17/2003 | 1 | WHITE ELEC. | | Y | WMF512K8-150CQ5 | 669 |
| 5962-9669201HXC | E | 03/17/2003 | 1 | AEROFLEX | | Y | ACT-F512K8N-150P4Q | 669 |
| 5962-9669201HXC | E | 03/17/2003 | 1 | AUSTIN SEMI. | | Y | AS29F040CW-150/Q | 669 |
| 5962-9669201HXC | E | 03/17/2003 | 1 | WHITE ELEC. | | Y | WMF512K8-150CQ5 | 669 |
| 5962-9669201HYA | E | 03/17/2003 | 1 | WHITE ELEC. | | Y | WMF512K8-150DEQ5 | 669 |
| 5962-9669201HYC | E | 03/17/2003 | 1 | WHITE ELEC. | | Y | WMF512K8-150DEQ5 | 669 |
| 5962-9669202HTA | E | 03/17/2003 | 1 | AEROFLEX | | Y | ACT-F512K8N-120F7Q | 669 |
| 5962-9669202HTA | E | 03/17/2003 | 1 | AUSTIN SEMI. | | Y | AS29F040DCG-120/Q | 669 |
| 5962-9669202HTA | E | 03/17/2003 | 1 | WHITE ELEC. | | Y | WMF512K8-120FFQ5 | 669 |
| 5962-9669202HTC | E | 03/17/2003 | 1 | AEROFLEX | | Y | ACT-F512K8N-120F7Q | 669 |
| 5962-9669202HTC | E | 03/17/2003 | 1 | AUSTIN SEMI. | | Y | AS29F040DCG-120/Q | 669 |
| 5962-9669202HTC | E | 03/17/2003 | 1 | WHITE ELEC. | | Y | WMF512K8-120FFQ5 | 669 |
| 5962-9669202HUA | E | 03/17/2003 | 1 | AEROFLEX | | Y | ACT-F512K8N-120F6Q | 669 |
| 5962-9669202HUA | E | 03/17/2003 | 1 | AUSTIN SEMI. | | Y | AS29F040F-120/Q | 669 |
| 5962-9669202HUA | E | 03/17/2003 | 1 | WHITE ELEC. | | Y | WMF512K8-120FEQ5 | 669 |
| 5962-9669202HUC | E | 03/17/2003 | 1 | AEROFLEX | | Y | ACT-F512K8N-120F6Q | 669 |
| 5962-9669202HUC | E | 03/17/2003 | 1 | AUSTIN SEMI. | | Y | AS29F040F-120/Q | 669 |
| 5962-9669202HUC | E | 03/17/2003 | 1 | WHITE ELEC. | | Y | WMF512K8-120FEQ5 | 669 |
| 5962-9669202HXA | E | 03/17/2003 | 1 | AEROFLEX | | Y | ACT-F512K8N-120P4Q | 669 |
| 5962-9669202HXA | E | 03/17/2003 | 1 | AUSTIN SEMI. | | Y | AS29F040CW-120/Q | 669 |
| 5962-9669202HXA | E | 03/17/2003 | 1 | WHITE ELEC. | | Y | WMF512K8-120CQ5 | 669 |
| 5962-9669202HXC | E | 03/17/2003 | 1 | AEROFLEX | | Y | ACT-F512K8N-120P4Q | 669 |
| 5962-9669202HXC | E | 03/17/2003 | 1 | AUSTIN SEMI. | | Y | AS29F040CW-120/Q | 669 |
| 5962-9669202HXC | E | 03/17/2003 | 1 | WHITE ELEC. | | Y | WMF512K8-120CQ5 | 669 |
| 5962-9669202HYA | E | 03/17/2003 | 1 | WHITE ELEC. | | Y | WMF512K8-120DEQ5 | 669 |
| 5962-9669202HYC | E | 03/17/2003 | 1 | WHITE ELEC. | | Y | WMF512K8-120DEQ5 | 669 |
| 5962-9669203HTA | E | 03/17/2003 | 1 | AEROFLEX | | Y | ACT-F512K8N-090F7Q | 669 |
| 5962-9669203HTA | E | 03/17/2003 | 1 | AUSTIN SEMI. | | Y | AS29F040DCG-90/Q | 669 |
| 5962-9669203HTA | E | 03/17/2003 | 1 | WHITE ELEC. | | Y | WMF512K8-90FFQ5 | 669 |
| 5962-9669203HTC | E | 03/17/2003 | 1 | AEROFLEX | | Y | ACT-F512K8N-090F7Q | 669 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9669203HTC | E | 03/17/2003 | 1 | AUSTIN SEMI. | | Y | AS29F040DCG-90/Q | 669 |
| 5962-9669203HTC | E | 03/17/2003 | 1 | WHITE ELEC. | | Y | WMF512K8-90FFQ5 | 669 |
| 5962-9669203HUA | E | 03/17/2003 | 1 | AEROFLEX | | Y | ACT-F512K8N-090F6Q | 669 |
| 5962-9669203HUA | E | 03/17/2003 | 1 | AUSTIN SEMI. | | Y | AS29F040F-90/Q | 669 |
| 5962-9669203HUA | E | 03/17/2003 | 1 | WHITE ELEC. | | Y | WMF512K8-90FEQ5 | 669 |
| 5962-9669203HUC | E | 03/17/2003 | 1 | AEROFLEX | | Y | ACT-F512K8N-090F6Q | 669 |
| 5962-9669203HUC | E | 03/17/2003 | 1 | AUSTIN SEMI. | | Y | AS29F040F-90/Q | 669 |
| 5962-9669203HUC | E | 03/17/2003 | 1 | WHITE ELEC. | | Y | WMF512K8-90FEQ5 | 669 |
| 5962-9669203HXA | E | 03/17/2003 | 1 | AEROFLEX | | Y | ACT-F512K8N-090P4Q | 669 |
| 5962-9669203HXA | E | 03/17/2003 | 1 | AUSTIN SEMI. | | Y | AS29F040CW-90/Q | 669 |
| 5962-9669203HXA | E | 03/17/2003 | 1 | WHITE ELEC. | | Y | WMF512K8-90CQ5 | 669 |
| 5962-9669203HXC | E | 03/17/2003 | 1 | AEROFLEX | | Y | ACT-F512K8N-090P4Q | 669 |
| 5962-9669203HXC | E | 03/17/2003 | 1 | AUSTIN SEMI. | | Y | AS29F040CW-90/Q | 669 |
| 5962-9669203HXC | E | 03/17/2003 | 1 | WHITE ELEC. | | Y | WMF512K8-90CQ5 | 669 |
| 5962-9669203HYA | E | 03/17/2003 | 1 | WHITE ELEC. | | Y | WMF512K8-90DEQ5 | 669 |
| 5962-9669203HYC | E | 03/17/2003 | 1 | WHITE ELEC. | | Y | WMF512K8-90DEQ5 | 669 |
| 5962-9669204HTA | E | 03/17/2003 | 1 | AEROFLEX | | Y | ACT-F512K8N-070F7Q | 669 |
| 5962-9669204HTA | E | 03/17/2003 | 1 | AUSTIN SEMI. | | Y | AS29F040DCG-70/Q | 669 |
| 5962-9669204HTA | E | 03/17/2003 | 1 | WHITE ELEC. | | Y | WMF512K8-70FFQ5 | 669 |
| 5962-9669204HTC | E | 03/17/2003 | 1 | AEROFLEX | | Y | ACT-F512K8N-070F7Q | 669 |
| 5962-9669204HTC | E | 03/17/2003 | 1 | AUSTIN SEMI. | | Y | AS29F040DCG-70/Q | 669 |
| 5962-9669204HTC | E | 03/17/2003 | 1 | WHITE ELEC. | | Y | WMF512K8-70FFQ5 | 669 |
| 5962-9669204HUA | E | 03/17/2003 | 1 | AEROFLEX | | Y | ACT-F512K8N-070F6Q | 669 |
| 5962-9669204HUA | E | 03/17/2003 | 1 | AUSTIN SEMI. | | Y | AS29F040F-70/Q | 669 |
| 5962-9669204HUA | E | 03/17/2003 | 1 | WHITE ELEC. | | Y | WMF512K8-70FEQ5 | 669 |
| 5962-9669204HUC | E | 03/17/2003 | 1 | AEROFLEX | | Y | ACT-F512K8N-070F6Q | 669 |
| 5962-9669204HUC | E | 03/17/2003 | 1 | AUSTIN SEMI. | | Y | AS29F040F-70/Q | 669 |
| 5962-9669204HUC | E | 03/17/2003 | 1 | WHITE ELEC. | | Y | WMF512K8-70FEQ5 | 669 |
| 5962-9669204HXA | E | 03/17/2003 | 1 | AEROFLEX | | Y | ACT-F512K8N-070P4Q | 669 |
| 5962-9669204HXA | E | 03/17/2003 | 1 | AUSTIN SEMI. | | Y | AS29F040CW-70/Q | 669 |
| 5962-9669204HXA | E | 03/17/2003 | 1 | WHITE ELEC. | | Y | WMF512K8-70CQ5 | 669 |
| 5962-9669204HXC | E | 03/17/2003 | 1 | AEROFLEX | | Y | ACT-F512K8N-070P4Q | 669 |
| 5962-9669204HXC | E | 03/17/2003 | 1 | AUSTIN SEMI. | | Y | AS29F040CW-70/Q | 669 |
| 5962-9669204HXC | E | 03/17/2003 | 1 | WHITE ELEC. | | Y | WMF512K8-70CQ5 | 669 |
| 5962-9669204HYA | E | 03/17/2003 | 1 | WHITE ELEC. | | Y | WMF512K8-70DEQ5 | 669 |
| 5962-9669204HYC | E | 03/17/2003 | 1 | WHITE ELEC. | | Y | WMF512K8-70DEQ5 | 669 |
| 5962-9669205HTA | E | 03/17/2003 | 1 | WHITE ELEC. | | Y | WMF512K8-60FFQ5 | 669 |
| 5962-9669205HTC | E | 03/17/2003 | 1 | WHITE ELEC. | | Y | WMF512K8-60FFQ5 | 669 |
| 5962-9669205HUA | E | 03/17/2003 | 1 | WHITE ELEC. | | Y | WMF512K8-60FEQ5 | 669 |
| 5962-9669205HUC | E | 03/17/2003 | 1 | WHITE ELEC. | | Y | WMF512K8-60FEQ5 | 669 |
| 5962-9669205HXA | E | 03/17/2003 | 1 | AEROFLEX | | Y | ACT-F512K8N-060P4Q | 669 |
| 5962-9669205HXA | E | 03/17/2003 | 1 | WHITE ELEC. | | Y | WMF512K8-60CQ5 | 669 |
| 5962-9669205HXC | E | 03/17/2003 | 1 | AEROFLEX | | Y | ACT-F512K8N-060P4Q | 669 |
| 5962-9669205HXC | E | 03/17/2003 | 1 | WHITE ELEC. | | Y | WMF512K8-60CQ5 | 669 |
| 5962-9669205HYA | E | 03/17/2003 | 1 | WHITE ELEC. | | Y | WMF512K8-60DEQ5 | 669 |
| 5962-9669205HYC | E | 03/17/2003 | 1 | WHITE ELEC. | | Y | WMF512K8-60DEQ5 | 669 |
| 5962-9669401QVC | A | 06/10/1996 | | (NONE) | | | 5104 (GEN) | 612 |
| 5962D9669401VVC | A | 06/10/1996 | | (NONE) | | | 5104 (GEN) | 612 |
| 5962-9669401QXC | A | 06/10/1996 | | (NONE) | 06/27/1999 | | 5104 (GEN) | 612 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962D9669401VXC | A | 06/10/1996 | | (NONE) | 06/27/1999 | | 5104 (GEN) | 612 |
| 5962-9669501QVC | A | 06/10/1996 | | (NONE) | 06/27/1999 | | 5114 (GEN) | 612 |
| 5962D9669501VVC | A | 06/10/1996 | | (NONE) | 06/27/1999 | | 5114 (GEN) | 612 |
| 5962-9669501QXC | A | 06/10/1996 | | (NONE) | 06/27/1999 | | 5114 (GEN) | 612 |
| 5962D9669501VXC | A | 06/10/1996 | | (NONE) | 06/27/1999 | | 5114 (GEN) | 612 |
| 5962F9669601V9A | C | 07/28/2004 | 1 | INTERSIL | | Y | HS0-9008RH-Q | 592 |
| 5962F9669601QXC | C | 07/28/2004 | | (NONE) | | | HS-9008 (GEN) | 592 |
| 5962F9669601VXC | C | 07/28/2004 | | (NONE) | | | HS-9008 (GEN) | 592 |
| 5962F9669601QYC | C | 07/28/2004 | | (NONE) | | | HS-9008 (GEN) | 592 |
| 5962F9669601VYC | C | 07/28/2004 | | (NONE) | | | HS-9008 (GEN) | 592 |
| 5962-9669701QXA | | 01/26/1996 | 1 | TI | | Y | SNJ54CBT16209WD | 399 |
| 5962-9669801QXA | | 02/01/1996 | 2 | TI | | Y | SNJ54ABTH18646AHV | 590 |
| 5962-9669901MEA | A | 04/16/2002 | 1 | MICROSEMI | | Y | SG1731J/883B | 787 |
| 5962-9670001MPA | A | 04/04/1996 | | (NONE) | 03/30/2001 | | LT1193 (GEN) | 760 |
| 5962R9670101V9A | C | 06/06/2000 | | (NONE) | | | 4016B (GEN) | 199 |
| 5962R9670101VCC | C | 06/06/2000 | | (NONE) | | | 4016B (GEN) | 199 |
| 5962R9670101VXC | C | 06/06/2000 | | (NONE) | | | 4016B (GEN) | 199 |
| 5962R9670201V9A | B | 06/06/2000 | | (NONE) | | | 14538B (GEN) | 166 |
| 5962R9670201VEC | B | 06/06/2000 | 1 | INTERSIL | | Y | CD14538BDMSR | 166 |
| 5962R9670201VXC | B | 06/06/2000 | 1 | INTERSIL | | Y | CD14538BKMSR | 166 |
| 5962F9670301V9A | C | 06/07/2000 | 1 | INTERSIL | | Y | ACS03HMSR | 101 |
| 5962F9670301VCC | C | 06/07/2000 | 1 | INTERSIL | | Y | ACS03DMSR | 101 |
| 5962F9670301VXC | C | 06/07/2000 | 1 | INTERSIL | | Y | ACS03KMSR | 101 |
| 5962F9670302V9A | C | 06/07/2000 | | (NONE) | | | ACS03-02 (GEN) | 101 |
| 5962F9670302VCC | C | 06/07/2000 | | (NONE) | | | ACS03-02 (GEN) | 101 |
| 5962F9670302VXC | C | 06/07/2000 | | (NONE) | | | ACS03-02 (GEN) | 101 |
| 5962F9670401VEC | C | 06/07/2000 | | (NONE) | | | ACS112 (GEN) | 156 |
| 5962F9670401VXC | C | 06/07/2000 | | (NONE) | | | ACS112 (GEN) | 156 |
| 5962F9670402V9A | C | 06/07/2000 | | (NONE) | | | ACS112 (GEN) | 156 |
| 5962F9670402VEC | C | 06/07/2000 | | (NONE) | | | ACS112 (GEN) | 156 |
| 5962F9670402VFC | C | 06/07/2000 | | (NONE) | | | ACS112 (GEN) | 156 |
| 5962F9670501VCC | C | 06/13/2000 | | (NONE) | | | ACS125 (GEN) | 520 |
| 5962F9670501VXC | C | 06/13/2000 | | (NONE) | | | ACS125 (GEN) | 520 |
| 5962F9670502V9A | C | 06/13/2000 | | (NONE) | | | ACS125 (GEN) | 520 |
| 5962F9670502VCC | C | 06/13/2000 | | (NONE) | | | ACS125 (GEN) | 520 |
| 5962F9670502VXC | C | 06/13/2000 | | (NONE) | | | ACS125 (GEN) | 520 |
| 5962F9670601V9A | C | 06/14/2000 | | (NONE) | | | ACS161 (GEN) | 304 |
| 5962F9670601VEC | C | 06/14/2000 | | (NONE) | | | ACS161 (GEN) | 304 |
| 5962F9670601VXC | C | 06/14/2000 | | (NONE) | | | ACS161 (GEN) | 304 |
| 5962F9670602V9A | C | 06/14/2000 | | (NONE) | | | ACS161-02 (GEN) | 304 |
| 5962F9670602VEC | C | 06/14/2000 | | (NONE) | | | ACS161-02 (GEN) | 304 |
| 5962F9670602VXC | C | 06/14/2000 | | (NONE) | | | ACS161-02 (GEN) | 304 |
| 5962F9670701VRC | B | 06/14/2000 | 1 | INTERSIL | | Y | ACS245DMSR | 590 |
| 5962F9670701VXC | B | 06/14/2000 | 1 | INTERSIL | | Y | ACS245KMSR | 590 |
| 5962F9670702VRC | B | 06/14/2000 | | (NONE) | | | ACS245A (GEN) | 590 |
| 5962F9670702VXC | B | 06/14/2000 | | (NONE) | | | ACS245A (GEN) | 590 |
| 5962F9670703VRC | B | 06/14/2000 | | (NONE) | | | ACS245-02 (GEN) | 590 |
| 5962F9670703VXC | B | 06/14/2000 | | (NONE) | | | ACS245-02 (GEN) | 590 |
| 5962F9670704VRC | B | 06/14/2000 | | (NONE) | | | ACS245A (GEN) | 590 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962F9670704VXC | B | 06/14/2000 | | (NONE) | | | ACS245A (GEN) | 590 |
| 5962F9670801VCC | C | 06/14/2000 | | (NONE) | | | ACS280 (GEN) | 210 |
| 5962F9670801VXC | C | 06/14/2000 | | (NONE) | | | ACS280 (GEN) | 210 |
| 5962F9670802V9A | C | 06/14/2000 | | (NONE) | | | ACS280 (GEN) | 210 |
| 5962F9670802VCC | C | 06/14/2000 | | (NONE) | | | ACS280 (GEN) | 210 |
| 5962F9670802VXC | C | 06/14/2000 | | (NONE) | | | ACS280 (GEN) | 210 |
| 5962F9670901V9A | C | 06/15/2000 | | (NONE) | | | ACS521 (GEN) | 209 |
| 5962F9670901VRC | C | 06/15/2000 | | (NONE) | | | ACS521 (GEN) | 209 |
| 5962F9670901VXC | C | 06/15/2000 | | (NONE) | | | ACS521 (GEN) | 209 |
| 5962F9670902V9A | C | 06/15/2000 | | (NONE) | | | ACS521-02 (GEN) | 209 |
| 5962F9670902VRC | C | 06/15/2000 | | (NONE) | | | ACS521-02 (GEN) | 209 |
| 5962F9670902VXC | C | 06/15/2000 | | (NONE) | | | ACS521-02 (GEN) | 209 |
| 5962F9671001VRC | C | 06/20/2000 | | (NONE) | | | ACS541 (GEN) | 529 |
| 5962F9671001VXC | C | 06/20/2000 | | (NONE) | | | ACS541 (GEN) | 529 |
| 5962F9671002V9A | C | 06/20/2000 | 1 | INTERSIL | | Y | ACS541HMSR-02 | 529 |
| 5962F9671002VRC | C | 06/20/2000 | | (NONE) | | | ACS541 (GEN) | 529 |
| 5962F9671002VXC | C | 06/20/2000 | 1 | INTERSIL | | Y | ACS541KMSR-02 | 529 |
| 5962F9671101V9A | C | 06/21/2000 | | (NONE) | | | ACS630 (GEN) | 355 |
| 5962F9671101VXC | C | 06/21/2000 | 1 | INTERSIL | 04/01/2004 | Y | ACS630DMSR | 355 |
| 5962F9671101VYC | C | 06/21/2000 | 1 | INTERSIL | 04/01/2004 | Y | ACS630KMSR | 355 |
| 5962F9671102V9A | C | 06/21/2000 | | (NONE) | | | ACS630-02 (GEN) | 355 |
| 5962F9671102VXC | C | 06/21/2000 | | (NONE) | | | ACS630-02 (GEN) | 355 |
| 5962F9671102VYC | C | 06/21/2000 | | (NONE) | | | ACS630-02 (GEN) | 355 |
| 5962F9671201VCC | C | 07/03/2000 | | (NONE) | | | ACTS04 (GEN) | 143 |
| 5962F9671201VXC | C | 07/03/2000 | | (NONE) | | | ACTS04 (GEN) | 143 |
| 5962F9671202V9A | C | 07/03/2000 | | (NONE) | | | ACTS04 (GEN) | 143 |
| 5962F9671202VCC | C | 07/03/2000 | 1 | INTERSIL | | Y | ACTS04DMSR-02 | 143 |
| 5962F9671202VXC | C | 07/03/2000 | 1 | INTERSIL | | Y | ACTS04KMSR-02 | 143 |
| 5962F9671301VCC | C | 06/26/2000 | | (NONE) | | | ACTS74 (GEN) | 158 |
| 5962F9671301VXC | C | 06/26/2000 | | (NONE) | | | ACTS74 (GEN) | 158 |
| 5962F9671302V9C | C | 06/26/2000 | 1 | INTERSIL | | Y | ACTS74HMSR-02 | 158 |
| 5962F9671302VCC | C | 06/26/2000 | | (NONE) | | | ACTS74 (GEN) | 158 |
| 5962F9671302VXC | C | 06/26/2000 | | (NONE) | | | ACTS74 (GEN) | 158 |
| 5962F9671401VEC | C | 06/26/2000 | | (NONE) | | | ACTS112 (GEN) | 156 |
| 5962F9671401VXC | C | 06/26/2000 | | (NONE) | | | ACTS112 (GEN) | 156 |
| 5962F9671402V9A | C | 06/26/2000 | | (NONE) | | | ACTS112 (GEN) | 156 |
| 5962F9671402VEC | C | 06/26/2000 | | (NONE) | | | ACTS112 (GEN) | 156 |
| 5962F9671402VXC | C | 06/26/2000 | | (NONE) | | | ACTS112 (GEN) | 156 |
| 5962F9671501VCC | C | 07/03/2000 | | (NONE) | | | ACTS125 (GEN) | 520 |
| 5962F9671501VXC | C | 07/03/2000 | | (NONE) | | | ACTS125 (GEN) | 520 |
| 5962F9671502V9A | C | 07/03/2000 | | (NONE) | | | ACTS125 (GEN) | 520 |
| 5962F9671502VCC | C | 07/03/2000 | | (NONE) | | | ACTS125 (GEN) | 520 |
| 5962F9671502VXC | C | 07/03/2000 | | (NONE) | | | ACTS125 (GEN) | 520 |
| 5962F9671601V9A | C | 07/03/2000 | | (NONE) | | | ACTS161 (GEN) | 304 |
| 5962F9671601VEC | C | 07/03/2000 | 1 | INTERSIL | | Y | ACTS161DMSR | 304 |
| 5962F9671601VXC | C | 07/03/2000 | 1 | INTERSIL | | Y | ACTS161KMSR | 304 |
| 5962F9671602V9A | C | 07/03/2000 | | (NONE) | | | ACTS161-02 (GEN) | 304 |
| 5962F9671602VEC | C | 07/03/2000 | | (NONE) | | | ACTS161-02 (GEN) | 304 |
| 5962F9671602VXC | C | 07/03/2000 | | (NONE) | | | ACTS161-02 (GEN) | 304 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962F9671701V9A | D | 04/28/1999 | | (NONE) | | | ACTS240 (GEN) | 529 |
| 5962F9671701VRC | D | 04/28/1999 | 1 | INTERSIL | | Y | ACTS240DMSR | 529 |
| 5962R9671701TRC | D | 04/28/1999 | | (NONE) | | | ACTS240 (GEN) | 529 |
| 5962F9671701VXC | D | 04/28/1999 | 1 | INTERSIL | | Y | ACTS240KMSR | 529 |
| 5962R9671701TXC | D | 04/28/1999 | | (NONE) | | | ACTS240 (GEN) | 529 |
| 5962F9671702V9A | D | 04/28/1999 | | (NONE) | | | ACTS240-02 (GEN) | 529 |
| 5962F9671702VRC | D | 04/28/1999 | | (NONE) | | | ACTS240-02 (GEN) | 529 |
| 5962R9671702TRC | D | 04/28/1999 | 1 | INTERSIL | | Y | ACTS240DTR-02 | 529 |
| 5962F9671702VXC | D | 04/28/1999 | | (NONE) | | | ACTS240-02 (GEN) | 529 |
| 5962R9671702TXC | D | 04/28/1999 | 1 | INTERSIL | | Y | ACTS240KTR-02 | 529 |
| 5962F9671801VRC | C | 07/03/2000 | | (NONE) | | | ACTS244 (GEN) | 529 |
| 5962F9671801VXC | C | 07/03/2000 | | (NONE) | | | ACTS244 (GEN) | 529 |
| 5962F9671802V9A | C | 07/03/2000 | | (NONE) | | | ACTS244 (GEN) | 529 |
| 5962F9671802VRC | C | 07/03/2000 | 1 | INTERSIL | | Y | ACTS244DMSR-02 | 529 |
| 5962F9671802VXC | C | 07/03/2000 | 1 | INTERSIL | | Y | ACTS244KMSR-02 | 529 |
| 5962F9671901V9A | D | 04/28/1999 | | (NONE) | | | ACTS245 (GEN) | 590 |
| 5962F9671901VRC | D | 04/28/1999 | 1 | INTERSIL | | Y | ACTS245DMSR | 590 |
| 5962R9671901TRC | D | 04/28/1999 | | (NONE) | | | ACTS245 (GEN) | 590 |
| 5962F9671901VXC | D | 04/28/1999 | 1 | INTERSIL | | Y | ACTS245KMSR | 590 |
| 5962R9671901TXC | D | 04/28/1999 | | (NONE) | | | ACTS245 (GEN) | 590 |
| 5962F9671902V9A | D | 04/28/1999 | | (NONE) | | | ACTS245-02 (GEN) | 590 |
| 5962F9671902VRC | D | 04/28/1999 | | (NONE) | | | ACTS245-02 (GEN) | 590 |
| 5962R9671902TRC | D | 04/28/1999 | 1 | INTERSIL | | Y | ACTS245DTR-02 | 590 |
| 5962F9671902VXC | D | 04/28/1999 | | (NONE) | | | ACTS245-02 (GEN) | 590 |
| 5962R9671902TXC | D | 04/28/1999 | 1 | INTERSIL | | Y | ACTS245KTR-02 | 590 |
| 5962F9672001VCC | C | 07/03/2000 | | (NONE) | | | ACTS280 (GEN) | 210 |
| 5962F9672001VXC | C | 07/03/2000 | | (NONE) | | | ACTS280 (GEN) | 210 |
| 5962F9672002V9A | C | 07/03/2000 | | (NONE) | | | ACTS280 (GEN) | 210 |
| 5962F9672002VCC | C | 07/03/2000 | | (NONE) | | | ACTS280 (GEN) | 210 |
| 5962F9672002VXC | C | 07/03/2000 | | (NONE) | | | ACTS280 (GEN) | 210 |
| 5962F9672101V9A | C | 07/03/2000 | | (NONE) | | | ACTS630 (GEN) | 355 |
| 5962F9672101VXC | C | 07/03/2000 | | (NONE) | | | ACTS630 (GEN) | 355 |
| 5962F9672101VYC | C | 07/03/2000 | | (NONE) | | | ACTS630 (GEN) | 355 |
| 5962F9672102V9A | C | 07/03/2000 | | (NONE) | 06/29/2003 | | ACTS630-02 (GEN) | 355 |
| 5962F9672102VXC | C | 07/03/2000 | | (NONE) | 06/29/2003 | | ACTS630-02 (GEN) | 355 |
| 5962F9672102VYC | C | 07/03/2000 | | (NONE) | 06/22/2003 | | ACTS630-02 (GEN) | 355 |
| 5962R9672201QCC | A | 05/21/2001 | 0 | INTERSIL | | Y | HS1-245RH-8 | 563 |
| 5962R9672201VCC | A | 05/21/2001 | 0 | INTERSIL | | Y | HS1-245RH-Q | 563 |
| 5962R9672201QXC | A | 05/21/2001 | 0 | INTERSIL | | Y | HS9-245RH-8 | 563 |
| 5962R9672201VXC | A | 05/21/2001 | 0 | INTERSIL | | Y | HS9-245RH-Q | 563 |
| 5962R9672301QCC | C | 04/01/2003 | 1 | INTERSIL | | Y | HS1-246RH-8 | 579 |
| 5962R9672301VCC | C | 04/01/2003 | 1 | INTERSIL | | Y | HS1-246RH-Q | 579 |
| 5962R9672301QXC | C | 04/01/2003 | 1 | INTERSIL | | Y | HS9-246RH-8 | 579 |
| 5962R9672301VXC | C | 04/01/2003 | 1 | INTERSIL | | Y | HS9-246RH-Q | 579 |
| 5962R9672302QCC | C | 04/01/2003 | 1 | INTERSIL | | Y | HS1-248RH-8 | 579 |
| 5962R9672302VCC | C | 04/01/2003 | 1 | INTERSIL | | Y | HS1-248RH-Q | 579 |
| 5962R9672302QXC | C | 04/01/2003 | 1 | INTERSIL | | Y | HS9-248RH-8 | 579 |
| 5962R9672302VXC | C | 04/01/2003 | 1 | INTERSIL | | Y | HS9-248RH-Q | 579 |
| 5962F9672401VRC | C | 07/05/2000 | | (NONE) | | | ACS573 (GEN) | 341 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962F9672401VXC | C | 07/05/2000 | | (NONE) | | | ACS573KMSR | 341 |
| 5962F9672402V9A | C | 07/05/2000 | | (NONE) | | | ACS573 (GEN) | 341 |
| 5962F9672402VRC | C | 07/05/2000 | | (NONE) | | | ACS573 (GEN) | 341 |
| 5962F9672402VXC | C | 07/05/2000 | | (NONE) | | | ACS573 (GEN) | 341 |
| 5962F9672501VRC | D | 04/28/1999 | | (NONE) | | | ACTS573 (GEN) | 341 |
| 5962F9672501VXC | D | 04/28/1999 | | (NONE) | | | ACTS573 (GEN) | 341 |
| 5962F9672502V9A | D | 04/28/1999 | | (NONE) | | | ACTS573-02 (GEN) | 341 |
| 5962F9672502VRC | D | 04/28/1999 | | (NONE) | | | ACTS573-02 (GEN) | 341 |
| 5962R9672502TRC | D | 04/28/1999 | | (NONE) | | | ACTS573-02 (GEN) | 341 |
| 5962F9672502VXC | D | 04/28/1999 | | (NONE) | | | ACTS573-02 (GEN) | 341 |
| 5962R9672502TXC | D | 04/28/1999 | | (NONE) | | | ACTS573-02 (GEN) | 341 |
| 5962F9672601VRC | D | 04/28/1999 | | (NONE) | | | ACTS541 (GEN) | 529 |
| 5962F9672601VXC | D | 04/28/1999 | | (NONE) | | | ACTS541 (GEN) | 529 |
| 5962F9672602V9A | D | 04/28/1999 | | (NONE) | | | ACTS541-02 (GEN) | 529 |
| 5962F9672602VRC | D | 04/28/1999 | | (NONE) | | | ACTS541-02 (GEN) | 529 |
| 5962R9672602TRC | D | 04/28/1999 | | (NONE) | | | ACTS541-02 (GEN) | 529 |
| 5962F9672602VXC | D | 04/28/1999 | | (NONE) | | | ACTS541-02 (GEN) | 529 |
| 5962R9672602TXC | D | 04/28/1999 | | (NONE) | | | ACTS541-02 (GEN) | 529 |
| 5962-9672701VRC | B | 04/20/2001 | | (NONE) | 09/23/2001 | | 82C88 (GEN) | 420 |
| 5962-9672801VQC | A | 03/08/1996 | | (NONE) | 01/07/2003 | | 80C86/7 (GEN) | 403 |
| 5962-9672901QXA | A | 09/06/2000 | | (NONE) | | | 55LBC976 (GEN) | 590 |
| 5962-9673001HXA | A | 02/13/2002 | 1 | INTERPOINT | | Y | MHV28512T/883 | 594 |
| 5962-9673001HXC | A | 02/13/2002 | 1 | INTERPOINT | | Y | MHV28512T/883 | 594 |
| 5962-9673001HZA | A | 02/13/2002 | 1 | INTERPOINT | | Y | MHV28512TF/883 | 594 |
| 5962-9673001HZC | A | 02/13/2002 | 1 | INTERPOINT | | Y | MHV28512TF/883 | 594 |
| 5962-9673101HXA | A | 02/13/2002 | 1 | INTERPOINT | | Y | MHV28515T/883 | 594 |
| 5962-9673101HXC | A | 02/13/2002 | 1 | INTERPOINT | | Y | MHV28515T/883 | 594 |
| 5962-9673101HZA | A | 02/13/2002 | 1 | INTERPOINT | | Y | MHV28515TF/883 | 594 |
| 5962-9673101HZC | A | 02/13/2002 | 1 | INTERPOINT | | Y | MHV28515TF/883 | 594 |
| 5962-9673201QXA | | 01/04/1996 | 3 | NATIONAL | | Y | 100313DMQB | 539 |
| 5962-9673201QYA | | 01/04/1996 | 3 | NATIONAL | | Y | 100313FMQB | 539 |
| 5962-9673401MXC | | 07/16/1997 | | (NONE) | 03/31/2000 | | 3611077 (GEN) | 439 |
| 5962-9673401MYC | | 07/16/1997 | | (NONE) | 03/31/2000 | | 3611077 (GEN) | 439 |
| 5962-9673501HXA | B | 07/16/2004 | 1 | DDC | | Y | RD-14591D1-142 | 594 |
| 5962-9673501HXA | B | 07/16/2004 | 1 | DDC IRELAND | | Y | RD-14591D1-142 | 594 |
| 5962-9673501HXC | B | 07/16/2004 | 1 | DDC | | Y | RD-14591D1-112 | 594 |
| 5962-9673501HXC | B | 07/16/2004 | 1 | DDC IRELAND | | Y | RD-14591D1-112 | 594 |
| 5962-9673501HYA | B | 07/16/2004 | 1 | DDC | | Y | RD-14591F1-142 | 594 |
| 5962-9673501HYA | B | 07/16/2004 | 1 | DDC IRELAND | | Y | RD-14591F1-142 | 594 |
| 5962-9673501HYC | B | 07/16/2004 | 1 | DDC | | Y | RD-14591F1-112 | 594 |
| 5962-9673501HYC | B | 07/16/2004 | 1 | DDC IRELAND | | Y | RD-14591F1-112 | 594 |
| 5962-9673502HXA | B | 07/16/2004 | 1 | DDC | | Y | RD-14591D1-144 | 594 |
| 5962-9673502HXA | B | 07/16/2004 | 1 | DDC IRELAND | | Y | RD-14591D1-144 | 594 |
| 5962-9673502HXC | B | 07/16/2004 | 1 | DDC | | Y | RD-14591D1-114 | 594 |
| 5962-9673502HXC | B | 07/16/2004 | 1 | DDC IRELAND | | Y | RD-14591D1-114 | 594 |
| 5962-9673502HYA | B | 07/16/2004 | 1 | DDC | | Y | RD-14591F1-144 | 594 |
| 5962-9673502HYA | B | 07/16/2004 | 1 | DDC IRELAND | | Y | RD-14591F1-144 | 594 |
| 5962-9673502HYC | B | 07/16/2004 | 1 | DDC | | Y | RD-14591F1-114 | 594 |
| 5962-9673502HYC | B | 07/16/2004 | 1 | DDC IRELAND | | Y | RD-14591F1-114 | 594 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9673503HXA | B | 07/16/2004 | 1 | DDC | | Y | SD-14591D1-142 | 594 |
| 5962-9673503HXA | B | 07/16/2004 | 1 | DDC IRELAND | | Y | SD-14591D1-142 | 594 |
| 5962-9673503HXC | B | 07/16/2004 | 1 | DDC | | Y | SD-14591D1-112 | 594 |
| 5962-9673503HXC | B | 07/16/2004 | 1 | DDC IRELAND | | Y | SD-14591D1-112 | 594 |
| 5962-9673503HYA | B | 07/16/2004 | 1 | DDC | | Y | SD-14591F1-142 | 594 |
| 5962-9673503HYA | B | 07/16/2004 | 1 | DDC IRELAND | | Y | SD-14591F1-142 | 594 |
| 5962-9673503HYC | B | 07/16/2004 | 1 | DDC | | Y | SD-14591F1-112 | 594 |
| 5962-9673503HYC | B | 07/16/2004 | 1 | DDC IRELAND | | Y | SD-14591F1-112 | 594 |
| 5962-9673504HXA | B | 07/16/2004 | 1 | DDC | | Y | SD-14591D1-144 | 594 |
| 5962-9673504HXA | B | 07/16/2004 | 1 | DDC IRELAND | | Y | SD-14591D1-144 | 594 |
| 5962-9673504HXC | B | 07/16/2004 | 1 | DDC | | Y | SD-14591D1-114 | 594 |
| 5962-9673504HXC | B | 07/16/2004 | 1 | DDC IRELAND | | Y | SD-14591D1-114 | 594 |
| 5962-9673504HYA | B | 07/16/2004 | 1 | DDC | | Y | SD-14591F1-144 | 594 |
| 5962-9673504HYA | B | 07/16/2004 | 1 | DDC IRELAND | | Y | SD-14591F1-144 | 594 |
| 5962-9673504HYC | B | 07/16/2004 | 1 | DDC | | Y | SD-14591F1-114 | 594 |
| 5962-9673504HYC | B | 07/16/2004 | 1 | DDC IRELAND | | Y | SD-14591F1-114 | 594 |
| 5962-9673505HXA | B | 07/16/2004 | 1 | DDC | | Y | RD-14592D1-142 | 594 |
| 5962-9673505HXA | B | 07/16/2004 | 1 | DDC IRELAND | | Y | RD-14592D1-142 | 594 |
| 5962-9673505HXC | B | 07/16/2004 | 1 | DDC | | Y | RD-14592D1-112 | 594 |
| 5962-9673505HXC | B | 07/16/2004 | 1 | DDC IRELAND | | Y | RD-14592D1-112 | 594 |
| 5962-9673505HYA | B | 07/16/2004 | 1 | DDC | | Y | RD-14592F1-142 | 594 |
| 5962-9673505HYA | B | 07/16/2004 | 1 | DDC IRELAND | | Y | RD-14592F1-142 | 594 |
| 5962-9673505HYC | B | 07/16/2004 | 1 | DDC | | Y | RD-14592F1-112 | 594 |
| 5962-9673505HYC | B | 07/16/2004 | 1 | DDC IRELAND | | Y | RD-14592F1-112 | 594 |
| 5962-9673506HXA | B | 07/16/2004 | 1 | DDC | | Y | RD-14592D1-144 | 594 |
| 5962-9673506HXA | B | 07/16/2004 | 1 | DDC IRELAND | | Y | RD-14592D1-144 | 594 |
| 5962-9673506HXC | B | 07/16/2004 | 1 | DDC | | Y | RD-14592D1-114 | 594 |
| 5962-9673506HXC | B | 07/16/2004 | 1 | DDC IRELAND | | Y | RD-14592D1-114 | 594 |
| 5962-9673506HYA | B | 07/16/2004 | 1 | DDC | | Y | RD-14592F1-144 | 594 |
| 5962-9673506HYA | B | 07/16/2004 | 1 | DDC IRELAND | | Y | RD-14592F1-144 | 594 |
| 5962-9673506HYC | B | 07/16/2004 | 1 | DDC | | Y | RD-14592F1-114 | 594 |
| 5962-9673506HYC | B | 07/16/2004 | 1 | DDC IRELAND | | Y | RD-14592F1-114 | 594 |
| 5962-9673507HXA | B | 07/16/2004 | 1 | DDC | | Y | RD-14592D1-145 | 594 |
| 5962-9673507HXA | B | 07/16/2004 | 1 | DDC IRELAND | | Y | RD-14592D1-145 | 594 |
| 5962-9673507HXC | B | 07/16/2004 | 1 | DDC | | Y | RD-14592D1-115 | 594 |
| 5962-9673507HXC | B | 07/16/2004 | 1 | DDC IRELAND | | Y | RD-14592D1-115 | 594 |
| 5962-9673507HYA | B | 07/16/2004 | 1 | DDC | | Y | RD-14592F1-145 | 594 |
| 5962-9673507HYA | B | 07/16/2004 | 1 | DDC IRELAND | | Y | RD-14592F1-145 | 594 |
| 5962-9673507HYC | B | 07/16/2004 | 1 | DDC | | Y | RD-14592F1-115 | 594 |
| 5962-9673507HYC | B | 07/16/2004 | 1 | DDC IRELAND | | Y | RD-14592F1-115 | 594 |
| 5962-9673508HXA | B | 07/16/2004 | 1 | DDC | | Y | SD-14592D1-142 | 594 |
| 5962-9673508HXA | B | 07/16/2004 | 1 | DDC IRELAND | | Y | SD-14592D1-142 | 594 |
| 5962-9673508HXC | B | 07/16/2004 | 1 | DDC | | Y | SD-14592D1-112 | 594 |
| 5962-9673508HXC | B | 07/16/2004 | 1 | DDC IRELAND | | Y | SD-14592D1-112 | 594 |
| 5962-9673508HYA | B | 07/16/2004 | 1 | DDC | | Y | SD-14592F1-142 | 594 |
| 5962-9673508HYA | B | 07/16/2004 | 1 | DDC IRELAND | | Y | SD-14592F1-142 | 594 |
| 5962-9673508HYC | B | 07/16/2004 | 1 | DDC | | Y | SD-14592F1-112 | 594 |
| 5962-9673508HYC | B | 07/16/2004 | 1 | DDC IRELAND | | Y | SD-14592F1-112 | 594 |
| 5962-9673509HXA | B | 07/16/2004 | 1 | DDC | | Y | SD-14592D1-144 | 594 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9673509HXA | B | 07/16/2004 | 1 | DDC IRELAND | | Y | SD-14592D1-144 | 594 |
| 5962-9673509HXC | B | 07/16/2004 | 1 | DDC | | Y | SD-14592D1-114 | 594 |
| 5962-9673509HXC | B | 07/16/2004 | 1 | DDC IRELAND | | Y | SD-14592D1-114 | 594 |
| 5962-9673509HYA | B | 07/16/2004 | 1 | DDC | | Y | SD-14592F1-144 | 594 |
| 5962-9673509HYA | B | 07/16/2004 | 1 | DDC IRELAND | | Y | SD-14592F1-144 | 594 |
| 5962-9673509HYC | B | 07/16/2004 | 1 | DDC | | Y | SD-14592F1-114 | 594 |
| 5962-9673509HYC | B | 07/16/2004 | 1 | DDC IRELAND | | Y | SD-14592F1-114 | 594 |
| 5962-9673510HXA | B | 07/16/2004 | 1 | DDC | | Y | SD-14592D1-145 | 594 |
| 5962-9673510HXA | B | 07/16/2004 | 1 | DDC IRELAND | | Y | SD-14592D1-145 | 594 |
| 5962-9673510HXC | B | 07/16/2004 | 1 | DDC | | Y | SD-14592D1-115 | 594 |
| 5962-9673510HXC | B | 07/16/2004 | 1 | DDC IRELAND | | Y | SD-14592D1-115 | 594 |
| 5962-9673510HYA | B | 07/16/2004 | 1 | DDC | | Y | SD-14592F1-145 | 594 |
| 5962-9673510HYA | B | 07/16/2004 | 1 | DDC IRELAND | | Y | SD-14592F1-145 | 594 |
| 5962-9673510HYC | B | 07/16/2004 | 1 | DDC | | Y | SD-14592F1-115 | 594 |
| 5962-9673510HYC | B | 07/16/2004 | 1 | DDC IRELAND | | Y | SD-14592F1-115 | 594 |
| 5962R9673601VXC | | 01/16/1996 | | (NONE) | | | GP511 (GEN) | 594 |
| 5962-9673701QGC | | 01/31/1996 | | (NONE) | | | HA-2548 (GEN) | 755 |
| 5962-9673701QPC | | 01/31/1996 | | (NONE) | | | HA-2548 (GEN) | 755 |
| 5962-9673801VCA | J | 06/18/2004 | 1 | NATIONAL | | Y | LM139AJ-QMLV | 776 |
| 5962L9673801VCA | J | 06/18/2004 | 1 | NATIONAL | | Y | LM139AJLQMLV | 776 |
| 5962R9673801QCA | J | 06/18/2004 | | (NONE) | | | LM139A (GEN) | 776 |
| 5962R9673801VCA | J | 06/18/2004 | 1 | NATIONAL | | Y | LM139AJRQMLV | 776 |
| 5962-9673801VDA | J | 06/18/2004 | 1 | NATIONAL | | Y | LM139AW-QMLV | 776 |
| 5962L9673801VDA | J | 06/18/2004 | 1 | NATIONAL | | Y | LM139AWLQMLV | 776 |
| 5962R9673801QDA | J | 06/18/2004 | | (NONE) | | | LM139A (GEN) | 776 |
| 5962R9673801VDA | J | 06/18/2004 | 1 | NATIONAL | | Y | LM139AWRQMLV | 776 |
| 5962-9673801VXA | J | 06/18/2004 | 1 | NATIONAL | | Y | LM139AWG-QMLV | 776 |
| 5962L9673801VXA | J | 06/18/2004 | 1 | NATIONAL | | Y | LM139AWGLQMLV | 776 |
| 5962R9673801QXA | J | 06/18/2004 | | (NONE) | | | LM139A (GEN) | 776 |
| 5962R9673801VXA | J | 06/18/2004 | 1 | NATIONAL | | Y | LM139AWGRQMLV | 776 |
| 5962-9674101H3A | | 10/29/1997 | 1 | AEROFLEX | | Y | ACT4455 | 590 |
| 5962-9674101H3C | | 10/29/1997 | 1 | AEROFLEX | | Y | ACT4455 | 590 |
| 5962-9674102H3A | | 10/29/1997 | 1 | AEROFLEX | | Y | ACT4459 | 590 |
| 5962-9674102H3C | | 10/29/1997 | 1 | AEROFLEX | | Y | ACT4459 | 590 |
| 5962R9674201V9A | E | 01/03/2000 | | (NONE) | | | 508A (GEN) | 193 |
| 5962R9674201QEC | E | 01/03/2000 | | (NONE) | 09/24/2000 | | 508A (GEN) | 193 |
| 5962R9674201TEC | E | 01/03/2000 | | (NONE) | 09/24/2000 | | 508A (GEN) | 193 |
| 5962R9674201VEC | E | 01/03/2000 | | (NONE) | 09/24/2000 | | 508A (GEN) | 193 |
| 5962R9674201QXC | E | 01/03/2000 | | (NONE) | 09/24/2000 | | 508A (GEN) | 193 |
| 5962R9674201TXC | E | 01/03/2000 | | (NONE) | 09/24/2000 | | 508A (GEN) | 193 |
| 5962R9674201VXC | E | 01/03/2000 | | (NONE) | 09/24/2000 | | 508A (GEN) | 193 |
| 5962F9674202V9A | E | 01/03/2000 | 2 | INTERSIL | | Y | HS0-508BRH-Q | 193 |
| 5962F9674202QEC | E | 01/03/2000 | 2 | INTERSIL | | Y | HS1-508BRH-8 | 193 |
| 5962F9674202VEC | E | 01/03/2000 | 2 | INTERSIL | | Y | HS1-508BRH-Q | 193 |
| 5962R9674202TEC | E | 01/03/2000 | 2 | INTERSIL | | Y | HS1-508BRH-T | 193 |
| 5962F9674202QXC | E | 01/03/2000 | 2 | INTERSIL | | Y | HS9-508BRH-8 | 193 |
| 5962F9674202VXC | E | 01/03/2000 | 2 | INTERSIL | | Y | HS9-508BRH-Q | 193 |
| 5962R9674202TXC | E | 01/03/2000 | 2 | INTERSIL | | Y | HS9-508BRH-T | 193 |
| 5962-9674301QXA | | 02/28/1996 | 2 | AUSTIN SEMI. | | Y | SMJ416160-80HKDM | 629 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9674302QXA | | 02/28/1996 | 2 | AUSTIN SEMI. | | Y | SMJ416160-70HKDM | 629 |
| 5962-9674303QXA | | 02/28/1996 | 2 | AUSTIN SEMI. | | Y | SMJ418160-80HKDM | 629 |
| 5962-9674304QXA | | 02/28/1996 | 2 | AUSTIN SEMI. | | Y | SMJ418160-70HKDM | 629 |
| 5962-9674402QUC | A | 11/24/1999 | | (NONE) | | | ADSP21060L-148 (GEN | 432 |
| 5962-9674402QYC | A | 11/24/1999 | | (NONE) | | | ADSP21060L-148 (GEN | 432 |
| 5962-9674502QTC | A | 11/24/1999 | | (NONE) | | | ADSP21060-160 (GEN) | 432 |
| 5962-9674502QUC | A | 11/24/1999 | | (NONE) | | | ADSP21060-160 (GEN) | 432 |
| 5962-9674502QXC | A | 11/24/1999 | | (NONE) | | | ADSP21060-160 (GEN) | 432 |
| 5962-9674502QYC | A | 11/24/1999 | | (NONE) | | | ADSP21060-160 (GEN) | 432 |
| 5962-9674601Q3A | A | 01/24/2003 | 3 | TI | | Y | SNJ54ABT853FK | 590 |
| 5962-9674601QKA | A | 01/24/2003 | 3 | TI | | Y | SNJ54ABT853W | 590 |
| 5962-9674601QLA | A | 01/24/2003 | 3 | TI | | Y | SNJ54ABT853JT | 590 |
| 5962-9674701Q3A | | 03/18/1997 | 1 | TI | | Y | SNJ54ACT8999FK | 399 |
| 5962-9674801Q3A | D | 03/19/1999 | 3 | TI | | Y | SNJ54LVT646FK | 590 |
| 5962-9674801QKA | D | 03/19/1999 | 3 | TI | | Y | SNJ54LVT646W | 590 |
| 5962-9674801QLA | D | 03/19/1999 | 3 | TI | | Y | SNJ54LVT646JT | 590 |
| 5962-9675101QCA | A | 11/13/2003 | 1 | TI | | Y | SNJ54LS73AJ | 152 |
| 5962-9675101VCA | A | 11/13/2003 | 1 | TI | | Y | SNV54LS73AJ | 152 |
| 5962-9675101QDA | A | 11/13/2003 | 1 | TI | | Y | SNJ54LS73AW | 152 |
| 5962-9675101VDA | A | 11/13/2003 | 1 | TI | | Y | SNV54LS73AW | 152 |
| 5962H9675301QCA | A | 05/17/1999 | 1 | UTMC | | Y | UT54ACTS220PQAH | 422 |
| 5962H9675301QCC | A | 05/17/1999 | 1 | UTMC | | Y | UT54ACTS220PQCH | 422 |
| 5962H9675301VCA | A | 05/17/1999 | 1 | UTMC | | Y | UT54ACTS220PVAH | 422 |
| 5962H9675301VCC | A | 05/17/1999 | 1 | UTMC | | Y | UT54ACTS220PVCH | 422 |
| 5962H9675301QXA | A | 05/17/1999 | 1 | UTMC | | Y | UT54ACTS220UQAH | 422 |
| 5962H9675301QXC | A | 05/17/1999 | 1 | UTMC | | Y | UT54ACTS220UQCH | 422 |
| 5962H9675301VXA | A | 05/17/1999 | 1 | UTMC | | Y | UT54ACTS220UVAH | 422 |
| 5962H9675301VXC | A | 05/17/1999 | 1 | UTMC | | Y | UT54ACTS220UVCH | 422 |
| 5962R9675501V9A | D | 12/19/2002 | | (NONE) | | | HS-565A (GEN) | 591 |
| 5962R9675501TJC | D | 12/19/2002 | | (NONE) | 03/23/2003 | | HS-565A (GEN) | 591 |
| 5962R9675501VJC | D | 12/19/2002 | | (NONE) | | | HS-565A (GEN) | 591 |
| 5962R9675501TXC | D | 12/19/2002 | | (NONE) | | | HS-565A (GEN) | 591 |
| 5962R9675501VXC | D | 12/19/2002 | | (NONE) | | | HS-565A (GEN) | 591 |
| 5962R9675502V9A | D | 12/19/2002 | 1 | INTERSIL | | Y | HS0-565BRH-Q | 591 |
| 5962R9675502VJC | D | 12/19/2002 | 1 | INTERSIL | | Y | HS1-565BRH-Q | 591 |
| 5962R9675502VXC | D | 12/19/2002 | 1 | INTERSIL | | Y | HS9-565BRH-Q | 591 |
| 5962F9675601VPC | A | 08/06/1999 | 1 | INTERSIL | 10/03/2004 | Y | HS7B-1120RH-Q | 752 |
| 5962R9675701V9A | C | 07/13/2000 | | (NONE) | | | 4063B (GEN) | 209 |
| 5962R9675701VEC | C | 07/13/2000 | | (NONE) | | | 4063B (GEN) | 209 |
| 5962R9675701VXC | C | 07/13/2000 | 1 | INTERSIL | | Y | CD4063BKMSR | 209 |
| 5962-9675801QXA | B | 08/16/1996 | | (NONE) | 05/01/2003 | | TVP3026-175 (GEN) | 830 |
| 5962-9675801NYB | B | 08/16/1996 | | (NONE) | 05/01/2003 | | TVP3026-175 (GEN) | 830 |
| 5962-9675901QYA | A | 03/26/1998 | | (NONE) | 10/31/2002 | | TVP3010 (GEN) | 830 |
| 5962-9676001QGA | | 02/01/1996 | | (NONE) | | | LF412 (GEN) | 710 |
| 5962-9676001QPA | | 02/01/1996 | | (NONE) | 09/06/2000 | | LF412 (GEN) | 710 |
| 5962-9676101Q2A | | 01/30/1996 | 3 | TI | | Y | SNJ54CDC341FK | 399 |
| 5962-9676101QRA | | 01/30/1996 | 3 | TI | | Y | SNJ54CDC341J | 399 |
| 5962-9676101QSA | | 01/30/1996 | 3 | TI | | Y | SNJ54CDC341W | 399 |
| 5962-9676201QLA | A | 09/23/1999 | 1 | ANALOG (3) | 07/30/2005 | Y | AD7710SQ/QML | 592 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962R9676601QXC | A | 06/27/1996 | | (NONE) | | | HS-81C55 (GEN) | 610 |
| 5962R9676601VXC | A | 06/27/1996 | | (NONE) | | | HS-81C55 (GEN) | 610 |
| 5962R9676601QYC | A | 06/27/1996 | | (NONE) | | | HS-81C55 (GEN) | 610 |
| 5962R9676601VYC | A | 06/27/1996 | | (NONE) | | | HS-81C55 (GEN) | 610 |
| 5962R9676602QXC | A | 06/27/1996 | | (NONE) | | | HS-81C56 (GEN) | 610 |
| 5962R9676602VXC | A | 06/27/1996 | | (NONE) | | | HS-81C56 (GEN) | 610 |
| 5962R9676602QYC | A | 06/27/1996 | | (NONE) | | | HS-81C56 (GEN) | 610 |
| 5962R9676602VYC | A | 06/27/1996 | | (NONE) | | | HS-81C56 (GEN) | 610 |
| 5962F9676701V9A | B | 09/10/2001 | 1 | INTERSIL | | Y | HS0-1135RH-Q | 751 |
| 5962F9676701VPC | B | 09/10/2001 | 1 | INTERSIL | | Y | HS7B-1135RH-Q | 751 |
| 5962-9676801Q2A | A | 02/05/2003 | 1 | TI | | Y | SNJ54ABT125FK | 520 |
| 5962-9676801QCA | A | 02/05/2003 | 1 | TI | | Y | SNJ54ABT125J | 520 |
| 5962-9676801QDA | A | 02/05/2003 | 1 | TI | | Y | SNJ54ABT125W | 520 |
| 5962-9676901Q3A | A | 10/05/1998 | 2 | TI | | Y | SNJ54ABT841FK | 342 |
| 5962-9676901QKA | A | 10/05/1998 | 2 | TI | | Y | SNJ54ABT841W | 342 |
| 5962-9676901QLA | A | 10/05/1998 | 2 | TI | | Y | SNJ54ABT841JT | 342 |
| 5962-9677001QXA | | 06/12/1996 | | (NONE) | 06/01/2001 | | TSB12C01 (GEN) | 420 |
| 5962-9677101QXA | | 04/02/1999 | 1 | TI | | Y | TSB21LV03CMHVB | 590 |
| 5962-9677201QXA | B | 06/04/2003 | | (NONE) | | | TSB14C01 (GEN) | 590 |
| 5962-9677202QXA | B | 06/04/2003 | 1 | TI | | Y | TSB14C01AMHVB | 590 |
| 5962-9677301Q2A | B | 04/17/2003 | 3 | TI | | Y | SNJ54AC574FK | 159 |
| 5962-9677301QRA | B | 04/17/2003 | 3 | TI | | Y | SNJ54AC574J | 159 |
| 5962-9677301QSA | B | 04/17/2003 | 3 | TI | | Y | SNJ54AC574W | 159 |
| 5962-9677301QZA | B | 04/17/2003 | | (NONE) | | | 54AC574 (GEN) | 159 |
| 5962-9677302QXA | B | 04/17/2003 | 2 | STMICRO | | Y | 54AC574K02Q | 159 |
| 5962-9677302QXC | B | 04/17/2003 | 2 | STMICRO | | Y | 54AC574K01Q | 159 |
| 5962-9677302VXA | B | 04/17/2003 | 2 | STMICRO | | Y | 54AC574K02V | 159 |
| 5962-9677302VXC | B | 04/17/2003 | 2 | STMICRO | | Y | 54AC574K01V | 159 |
| 5962-9677401QXA | A | 04/23/1999 | 2 | TI | | Y | SNJ54ABT162245WD | 590 |
| 5962-9677501QXA | A | 02/04/2003 | 1 | TI | | Y | SNJ54ABTE16245WD | 590 |
| 5962-9677701QXA | B | 12/23/2002 | 3 | TI | | Y | SNJ54LVTH16501WD | 590 |
| 5962-9678001QXA | B | 04/29/2003 | 2 | TI | | Y | SNJ54LVTH162245WD | 590 |
| 5962-9678001VXA | B | 04/29/2003 | 2 | TI | | Y | SNV54LVTH162245WD | 590 |
| 5962-9678201Q2A | B | 11/14/2003 | 1 | TI | | Y | SNJ54AHC244FK | 529 |
| 5962-9678201QRA | B | 11/14/2003 | 1 | TI | | Y | SNJ54AHC244J | 529 |
| 5962-9678201VRA | B | 11/14/2003 | 1 | TI | | Y | SNV54AHC244J | 529 |
| 5962-9678201QSA | B | 11/14/2003 | 1 | TI | | Y | SNJ54AHC244W | 529 |
| 5962-9678201VSA | B | 11/14/2003 | 1 | TI | | Y | SNV54AHC244W | 529 |
| 5962-9678301Q2A | B | 09/12/1997 | 1 | TI | | Y | SNJ54AHCT244FK | 529 |
| 5962-9678301QRA | B | 09/12/1997 | 1 | TI | | Y | SNJ54AHCT244J | 529 |
| 5962-9678301QSA | B | 09/12/1997 | 1 | TI | | Y | SNJ54AHCT244W | 529 |
| 5962F9678501VPC | B | 09/03/2003 | 1 | INTERSIL | | Y | HS7B-1115RH-Q | 702 |
| 5962R9678601QWC | | 04/10/1996 | | (NONE) | | | HS-3374 (GEN) | 594 |
| 5962R9678601VWC | | 04/10/1996 | | (NONE) | | | HS-3374 (GEN) | 594 |
| 5962-9678801QEA | A | 03/27/2002 | 2 | SILICONIX | | Y | DG384AAK/883 | 188 |
| 5962-9678901QXC | D | 11/27/2001 | 1 | TI | | Y | SMJ320MCM42DHFNM | 409 |
| 5962-9678902QXC | D | 11/27/2001 | 1 | TI | | Y | SMJ320MCM42CHFNM | 409 |
| 5962-9678903QXC | D | 11/27/2001 | | (NONE) | | | 320MCM42-50 (GEN) | 409 |
| 5962-9678904QXC | D | 11/27/2001 | | (NONE) | | | 320MCM42-50 (GEN) | 409 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9679001NXB | D | 12/12/2001 | 2 | TI | | Y | SMQ320C32PCMM50 | 432 |
| 5962-9679002NXB | D | 12/12/2001 | 2 | TI | | Y | SMQ320C32PCMM60 | 432 |
| 5962-9679101QXA | A | 11/16/1999 | 3 | TI | | Y | SMJ320C80GFM50 | 399 |
| 5962-9679101QYC | A | 11/16/1999 | 3 | TI | | Y | SMJ320C80HFHM50 | 399 |
| 5962-9679201Q2A | | 11/29/1996 | 1 | TI | | Y | SNJ54S30FK | 106 |
| 5962-9679201QCA | | 11/29/1996 | 1 | TI | | Y | SNJ54S30J | 106 |
| 5962-9679201QDA | | 11/29/1996 | 1 | TI | | Y | SNJ54S30W | 106 |
| 5962-9679301M3A | A | 01/06/2000 | | (NONE) | 04/01/2000 | | 10C11-30 (GEN) | 228 |
| 5962-9679301MLA | A | 01/06/2000 | | (NONE) | 04/01/2000 | | 10C11-30 (GEN) | 228 |
| 5962-9679302M3A | A | 01/06/2000 | | (NONE) | 04/01/2000 | | 10C11-25 (GEN) | 228 |
| 5962-9679302MLA | A | 01/06/2000 | | (NONE) | 04/01/2000 | | 10C11-25 (GEN) | 228 |
| 5962-9679303M3A | A | 01/06/2000 | | (NONE) | 04/01/2000 | | 10C11-20 (GEN) | 228 |
| 5962-9679303MLA | A | 01/06/2000 | | (NONE) | 04/01/2000 | | 10C11-20 (GEN) | 228 |
| 5962-9679304M3A | A | 01/06/2000 | | (NONE) | 04/01/2000 | | 21C11-30 (GEN) | 228 |
| 5962-9679304MLA | A | 01/06/2000 | | (NONE) | 04/01/2000 | | 21C11-30 (GEN) | 228 |
| 5962-9679305M3A | A | 01/06/2000 | | (NONE) | 04/01/2000 | | 21C11-25 (GEN) | 228 |
| 5962-9679305MLA | A | 01/06/2000 | | (NONE) | 04/01/2000 | | 21C11-25 (GEN) | 228 |
| 5962-9679306M3A | A | 01/06/2000 | | (NONE) | 04/01/2000 | | 21C11-20 (GEN) | 228 |
| 5962-9679306MLA | A | 01/06/2000 | | (NONE) | 04/01/2000 | | 21C11-20 (GEN) | 228 |
| 5962-9679401HXA | | 02/05/1997 | | (NONE) | | | MSK1339B (GEN) | 591 |
| 5962-9679501MXA | B | 02/18/1998 | 1 | WHITE ELEC. | | Y | EDI816256CA35F44B | 629 |
| 5962-9679501MYA | B | 02/18/1998 | 1 | WHITE ELEC. | | Y | EDI816256CA35N44B | 629 |
| 5962-9679502MXA | B | 02/18/1998 | 1 | WHITE ELEC. | | Y | EDI816256CA25F44B | 629 |
| 5962-9679502MYA | B | 02/18/1998 | 1 | WHITE ELEC. | | Y | EDI816256CA25N44B | 629 |
| 5962-9679503MXA | B | 02/18/1998 | 1 | WHITE ELEC. | | Y | EDI816256CA20F44B | 629 |
| 5962-9679503MYA | B | 02/18/1998 | 1 | WHITE ELEC. | | Y | EDI816256CA20N44B | 629 |
| 5962-9679504MXA | B | 02/18/1998 | 1 | WHITE ELEC. | | Y | EDI816256LPA35F44B | 629 |
| 5962-9679504MYA | B | 02/18/1998 | 1 | WHITE ELEC. | | Y | EDI816256LPA35N44B | 629 |
| 5962-9679505MXA | B | 02/18/1998 | 1 | WHITE ELEC. | | Y | EDI816256LPA25F44B | 629 |
| 5962-9679505MYA | B | 02/18/1998 | 1 | WHITE ELEC. | | Y | EDI816256LPA25N44B | 629 |
| 5962-9679506MXA | B | 02/18/1998 | 1 | WHITE ELEC. | | Y | EDI816256LPA20F44B | 629 |
| 5962-9679506MYA | B | 02/18/1998 | 1 | WHITE ELEC. | | Y | EDI816256LPA20N44B | 629 |
| 5962-9679601HXA | C | 09/14/2001 | 1 | WHITE ELEC. | | Y | WME128K8-300DEQ | 669 |
| 5962-9679601HXC | C | 09/14/2001 | 1 | WHITE ELEC. | | Y | WME128K8-300DEQ | 669 |
| 5962-9679601HYA | C | 09/14/2001 | 1 | WHITE ELEC. | | Y | WME128K8-300CQ | 669 |
| 5962-9679601HYC | C | 09/14/2001 | 1 | WHITE ELEC. | | Y | WME128K8-300CQ | 669 |
| 5962-9679602HXA | C | 09/14/2001 | 1 | WHITE ELEC. | | Y | WME128K8-250DEQ | 669 |
| 5962-9679602HXC | C | 09/14/2001 | 1 | WHITE ELEC. | | Y | WME128K8-250DEQ | 669 |
| 5962-9679602HYA | C | 09/14/2001 | 1 | WHITE ELEC. | | Y | WME128K8-250CQ | 669 |
| 5962-9679602HYC | C | 09/14/2001 | 1 | WHITE ELEC. | | Y | WME128K8-250CQ | 669 |
| 5962-9679603HXA | C | 09/14/2001 | 1 | WHITE ELEC. | | Y | WME128K8-200DEQ | 669 |
| 5962-9679603HXC | C | 09/14/2001 | 1 | WHITE ELEC. | | Y | WME128K8-200DEQ | 669 |
| 5962-9679603HYA | C | 09/14/2001 | 1 | WHITE ELEC. | | Y | WME128K8-200CQ | 669 |
| 5962-9679603HYC | C | 09/14/2001 | 1 | WHITE ELEC. | | Y | WME128K8-200CQ | 669 |
| 5962-9679604HXA | C | 09/14/2001 | 1 | WHITE ELEC. | | Y | WME128K8-150DEQ | 669 |
| 5962-9679604HXC | C | 09/14/2001 | 1 | WHITE ELEC. | | Y | WME128K8-150DEQ | 669 |
| 5962-9679604HYA | C | 09/14/2001 | 1 | WHITE ELEC. | | Y | WME128K8-150CQ | 669 |
| 5962-9679604HYC | C | 09/14/2001 | 1 | WHITE ELEC. | | Y | WME128K8-150CQ | 669 |
| 5962-9679605HXA | C | 09/14/2001 | 1 | WHITE ELEC. | | Y | WME128K8-140DEQ | 669 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9679605HXC | C | 09/14/2001 | 1 | WHITE ELEC. | | Y | WME128K8-140DEQ | 669 |
| 5962-9679605HYA | C | 09/14/2001 | 1 | WHITE ELEC. | | Y | WME128K8-140CQ | 669 |
| 5962-9679605HYC | C | 09/14/2001 | 1 | WHITE ELEC. | | Y | WME128K8-140CQ | 669 |
| 5962-9679606HXA | C | 09/14/2001 | 1 | WHITE ELEC. | | Y | WME128K8-120DEQ | 669 |
| 5962-9679606HXC | C | 09/14/2001 | 1 | WHITE ELEC. | | Y | WME128K8-120DEQ | 669 |
| 5962-9679606HYA | C | 09/14/2001 | 1 | WHITE ELEC. | | Y | WME128K8-120CQ | 669 |
| 5962-9679606HYC | C | 09/14/2001 | 1 | WHITE ELEC. | | Y | WME128K8-120CQ | 669 |
| 5962R9679701V9A | C | 03/29/2004 | 1 | INTERSIL | 02/10/2005 | Y | HCS245HMSR | 590 |
| 5962R9679701VRC | C | 03/29/2004 | 1 | INTERSIL | 02/10/2005 | Y | HCS245DMSR | 590 |
| 5962R9679701VXC | C | 03/29/2004 | 1 | INTERSIL | 02/10/2005 | Y | HCS245KMSR | 590 |
| 5962-9679801VCA | C | 06/12/2001 | 1 | NATIONAL | | Y | LM119J-QMLV | 774 |
| 5962R9679801QCA | C | 06/12/2001 | | (NONE) | | | LM119 (GEN) | 774 |
| 5962R9679801VCA | C | 06/12/2001 | | (NONE) | | | LM119 (GEN) | 774 |
| 5962-9679801VHA | C | 06/12/2001 | 1 | NATIONAL | | Y | LM119W-QMLV | 774 |
| 5962R9679801QHA | C | 06/12/2001 | | (NONE) | | | LM119 (GEN) | 774 |
| 5962R9679801VHA | C | 06/12/2001 | | (NONE) | | | LM119 (GEN) | 774 |
| 5962-9679801VIA | C | 06/12/2001 | 1 | NATIONAL | | Y | LM119H-QMLV | 774 |
| 5962R9679801QIA | C | 06/12/2001 | | (NONE) | | | LM119 (GEN) | 774 |
| 5962R9679801VIA | C | 06/12/2001 | | (NONE) | | | LM119 (GEN) | 774 |
| 5962-9679801VXA | C | 06/12/2001 | 1 | NATIONAL | | Y | LM119WG-QMLV | 774 |
| 5962R9679801QXA | C | 06/12/2001 | | (NONE) | | | LM119 (GEN) | 774 |
| 5962R9679801VXA | C | 06/12/2001 | | (NONE) | | | LM119 (GEN) | 774 |
| 5962F9679901V9A | C | 07/17/2000 | 1 | INTERSIL | | Y | ACS74HMSR | 158 |
| 5962F9679901VCC | C | 07/17/2000 | 1 | INTERSIL | | Y | ACS74DMSR | 158 |
| 5962F9679901VXC | C | 07/17/2000 | 1 | INTERSIL | | Y | ACS74KMSR | 158 |
| 5962F9679902V9A | C | 07/17/2000 | | (NONE) | | | ACS74-02 (GEN) | 158 |
| 5962F9679902VCC | C | 07/17/2000 | | (NONE) | | | ACS74-02 (GEN) | 158 |
| 5962F9679902VXC | C | 07/17/2000 | | (NONE) | | | ACS74-02 (GEN) | 158 |
| 5962-9680101Q2A | B | 11/14/2003 | 1 | TI | | Y | SNJ54AHCT14FK | 143 |
| 5962-9680101QCA | B | 11/14/2003 | 1 | TI | | Y | SNJ54AHCT14J | 143 |
| 5962-9680101VCA | B | 11/14/2003 | 1 | TI | | Y | SNV54AHCT14J | 143 |
| 5962-9680101QDA | B | 11/14/2003 | 1 | TI | | Y | SNJ54AHCT14W | 143 |
| 5962-9680101VDA | B | 11/14/2003 | 1 | TI | | Y | SNV54AHCT14W | 143 |
| 5962-9680201Q2A | A | 04/01/1997 | 2 | TI | | Y | SNJ54AHC14FK | 143 |
| 5962-9680201QCA | A | 04/01/1997 | 2 | TI | | Y | SNJ54AHC14J | 143 |
| 5962-9680201QDA | A | 04/01/1997 | 2 | TI | | Y | SNJ54AHC14W | 143 |
| 5962-9680301Q2A | | 06/28/1996 | 2 | TI | | Y | SNJ54AHCU04FK | 143 |
| 5962-9680301QCA | | 06/28/1996 | 2 | TI | | Y | SNJ54AHCU04J | 143 |
| 5962-9680301QDA | | 06/28/1996 | 2 | TI | | Y | SNJ54AHCU04W | 143 |
| 5962-9680401Q2A | B | 09/03/1997 | 1 | TI | | Y | SNJ54AHCT04FK | 143 |
| 5962-9680401QCA | B | 09/03/1997 | 1 | TI | | Y | SNJ54AHCT04J | 143 |
| 5962-9680401QDA | B | 09/03/1997 | 1 | TI | | Y | SNJ54AHCT04W | 143 |
| 5962-9680501Q2A | | 06/28/1996 | 2 | TI | | Y | SNJ54AHC04FK | 143 |
| 5962-9680501QCA | | 06/28/1996 | 2 | TI | | Y | SNJ54AHC04J | 143 |
| 5962-9680501QDA | | 06/28/1996 | 2 | TI | | Y | SNJ54AHC04W | 143 |
| 5962-9680601Q2A | B | 09/12/1997 | 1 | TI | | Y | SNJ54AHCT240FK | 529 |
| 5962-9680601QRA | B | 09/12/1997 | 1 | TI | | Y | SNJ54AHCT240J | 529 |
| 5962-9680601QSA | B | 09/12/1997 | 1 | TI | | Y | SNJ54AHCT240W | 529 |
| 5962-9680701Q2A | | 05/07/1996 | 1 | TI | | Y | SNJ54AHC240FK | 529 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9680701QRA | | 05/07/1996 | 1 | TI | | Y | SNJ54AHC240J | 529 |
| 5962-9680701QSA | | 05/07/1996 | 1 | TI | | Y | SNJ54AHC240W | 529 |
| 5962-9680801QXA | B | 02/04/2003 | 1 | TI | | Y | SNJ54ABTH32316HT | 590 |
| 5962-9680901QXA | B | 04/29/2003 | 1 | TI | | Y | SNJ54LVTH162244WD | 529 |
| 5962-9680901VXA | B | 04/29/2003 | 1 | TI | | Y | SNV54LVTH162244WD | 529 |
| 5962-9681001QXA | B | 04/24/1998 | 2 | TI | | Y | SNJ54LVTH16373WD | 342 |
| 5962-9681101QXA | A | 03/12/1999 | 3 | TI | | Y | SNJ54LVTH18502AHV | 590 |
| 5962-9681201Q3A | A | 03/05/2003 | 2 | TI | | Y | SNL54ABT8996FK | 599 |
| 5962-9681201QKA | A | 03/05/2003 | 2 | TI | | Y | SNL54ABT8996W | 599 |
| 5962-9681201QLA | A | 03/05/2003 | 2 | TI | | Y | SNL54ABT8996JT | 599 |
| 5962-9681501QXA | A | 07/12/2000 | | (NONE) | 12/31/2001 | | 54FB2040 (GEN) | 590 |
| 5962-9681601Q2A | | 07/01/1996 | 1 | TI | | Y | SNJ54AHC86FK | 140 |
| 5962-9681601QCA | | 07/01/1996 | 1 | TI | | Y | SNJ54AHC86J | 140 |
| 5962-9681601QDA | | 07/01/1996 | 1 | TI | | Y | SNJ54AHC86W | 140 |
| 5962-9681701Q2A | B | 09/12/1997 | 2 | TI | | Y | SNJ54AHCT86FK | 140 |
| 5962-9681701QCA | B | 09/12/1997 | 2 | TI | | Y | SNJ54AHCT86J | 140 |
| 5962-9681701QDA | B | 09/12/1997 | 2 | TI | | Y | SNJ54AHCT86W | 140 |
| 5962-9681801Q2A | A | 11/14/2003 | 1 | TI | | Y | SNJ54AHC245FK | 590 |
| 5962-9681801QRA | A | 11/14/2003 | 1 | TI | | Y | SNJ54AHC245J | 590 |
| 5962-9681801VRA | A | 11/14/2003 | 1 | TI | | Y | SNV54AHC245J | 590 |
| 5962-9681801QSA | A | 11/14/2003 | 1 | TI | | Y | SNJ54AHC245W | 590 |
| 5962-9681801VSA | A | 11/14/2003 | 1 | TI | | Y | SNV54AHC245W | 590 |
| 5962-9681901Q2A | A | 06/27/1997 | 1 | TI | | Y | SNJ54AHCT245FK | 590 |
| 5962-9681901QRA | A | 06/27/1997 | 1 | TI | | Y | SNJ54AHCT245J | 590 |
| 5962-9681901QSA | A | 06/27/1997 | 1 | TI | | Y | SNJ54AHCT245W | 590 |
| 5962-9682001Q2A | B | 09/24/1999 | 1 | TI | | Y | SNJ54AHC08FK | 110 |
| 5962-9682001QCA | B | 09/24/1999 | 1 | TI | | Y | SNJ54AHC08J | 110 |
| 5962-9682001QDA | B | 09/24/1999 | 1 | TI | | Y | SNJ54AHC08W | 110 |
| 5962-9682101Q2A | C | 10/17/2003 | 1 | TI | | Y | SNJ54AHCT08FK | 110 |
| 5962-9682101QCA | C | 10/17/2003 | 1 | TI | | Y | SNJ54AHCT08J | 110 |
| 5962-9682101VCA | C | 10/17/2003 | 1 | TI | | Y | SNV54AHCT08J | 110 |
| 5962-9682101QDA | C | 10/17/2003 | 1 | TI | | Y | SNJ54AHCT08W | 110 |
| 5962-9682101VDA | C | 10/17/2003 | 1 | TI | | Y | SNV54AHCT08W | 110 |
| 5962-9682201Q2A | | 07/01/1996 | 1 | TI | | Y | SNJ54AHC00FK | 100 |
| 5962-9682201QCA | | 07/01/1996 | 1 | TI | | Y | SNJ54AHC00J | 100 |
| 5962-9682201QDA | | 07/01/1996 | 1 | TI | | Y | SNJ54AHC00W | 100 |
| 5962-9682301Q2A | A | 06/27/1997 | 1 | TI | | Y | SNJ54AHCT00FK | 100 |
| 5962-9682301QCA | A | 06/27/1997 | 1 | TI | | Y | SNJ54AHCT00J | 100 |
| 5962-9682301QDA | A | 06/27/1997 | 1 | TI | | Y | SNJ54AHCT00W | 100 |
| 5962-9682501Q2A | | 06/05/1996 | 1 | TI | | Y | SNJ54AHC32FK | 125 |
| 5962-9682501QCA | | 06/05/1996 | 1 | TI | | Y | SNJ54AHC32J | 125 |
| 5962-9682501QDA | | 06/05/1996 | 1 | TI | | Y | SNJ54AHC32W | 125 |
| 5962-9682601Q2A | A | 06/27/1997 | 2 | TI | | Y | SNJ54AHCT32FK | 125 |
| 5962-9682601QCA | A | 06/27/1997 | 2 | TI | | Y | SNJ54AHCT32J | 125 |
| 5962-9682601QDA | A | 06/27/1997 | 2 | TI | | Y | SNJ54AHCT32W | 125 |
| 5962-9682701Q3A | A | 02/11/2001 | 2 | TI | | Y | CY29FCT818ATLMB | 228 |
| 5962-9682701QLA | A | 02/11/2001 | 2 | TI | | Y | CY29FCT818ATDMB | 228 |
| 5962-9682801H2C | A | 08/02/2002 | 1 | MS KENNEDY | | Y | MSK1343B | 815 |
| 5962-9682901Q2A | A | 03/05/2003 | 2 | NATIONAL | | Y | 54ACTQ541LMQB | 529 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9682901V2A | A | 03/05/2003 | 2 | NATIONAL | | Y | 54ACTQ541E-QMLV | 529 |
| 5962-9682901QRA | A | 03/05/2003 | 2 | NATIONAL | | Y | 54ACTQ541DMQB | 529 |
| 5962-9682901VRA | A | 03/05/2003 | 2 | NATIONAL | | Y | 54ACTQ541J-QMLV | 529 |
| 5962-9682901QSA | A | 03/05/2003 | 2 | NATIONAL | | Y | 54ACTQ541FMQB | 529 |
| 5962-9682901VSA | A | 03/05/2003 | 2 | NATIONAL | | Y | 54ACTQ541W-QMLV | 529 |
| 5962F9683001VPC | B | 08/20/2003 | 1 | INTERSIL | | Y | HS7B-1145RH-Q | 760 |
| 5962F9683101VPA | B | 07/07/2003 | 1 | INTERSIL | | Y | HS7-1212RH-Q | 509 |
| 5962F9683101VPC | B | 07/07/2003 | 1 | INTERSIL | 10/03/2004 | Y | HS7B-1212RH-Q | 509 |
| 5962F9683201VCA | B | 06/04/2003 | | (NONE) | 01/07/2003 | | HS-1245 (GEN) | 760 |
| 5962F9683401VCA | B | 03/18/2003 | | (NONE) | 09/21/2003 | Y | HS-1412 (GEN) | 509 |
| 5962-9683601MXC | A | 05/08/2002 | 2 | QUICKLOGIC | | | QL12X16B-0C84M/883 | 381 |
| 5962-9683602MXC | A | 05/08/2002 | 2 | QUICKLOGIC | | | QL12X16B-1C84M/883 | 381 |
| 5962-9683701MXC | | 01/18/2000 | | (NONE) | 01/16/2002 | | 24X32B-0 (GEN) | 381 |
| 5962-9683702MXC | | 01/18/2000 | | (NONE) | 01/16/2002 | | 24X32B-1 (GEN) | 381 |
| 5962-9683901MPA | A | 04/18/2002 | 2 | ANALOG (2) | | Y | AD8041SQ | 719 |
| 5962H9684001VXC | | 10/07/1997 | 1 | HONEYWELL (1) | | Y | HX84050VHC | 618 |
| 5962-9684101HXC | A | 11/13/1998 | | (NONE) | | | ADDC02812DA (GEN) | 594 |
| 5962-9684201HXC | A | 11/13/1998 | | (NONE) | 08/29/2003 | | ADDC02815DA (GEN) | 594 |
| 5962-9684301VXA | C | 04/14/2000 | 3 | NATIONAL | | Y | LM113H-QMLV | 785 |
| 5962-9684301VZA | C | 04/14/2000 | 3 | NATIONAL | | Y | LM113WG-QMLV | 785 |
| 5962-9684302VXA | C | 04/14/2000 | 3 | NATIONAL | | Y | LM113-1H-QMLV | 785 |
| 5962-9684302VZA | C | 04/14/2000 | 3 | NATIONAL | | Y | LM113-1WG-QMLV | 785 |
| 5962-9684303VXA | C | 04/14/2000 | | (NONE) | | | LM113-2 (GEN) | 785 |
| 5962-9684401HXA | B | 07/16/2004 | 1 | DDC | | Y | SD-14591D2-142 | 594 |
| 5962-9684401HXA | B | 07/16/2004 | 1 | DDC IRELAND | | Y | SD-14591D2-142 | 594 |
| 5962-9684401HXC | B | 07/16/2004 | 1 | DDC | | Y | SD-14591D2-112 | 594 |
| 5962-9684401HXC | B | 07/16/2004 | 1 | DDC IRELAND | | Y | SD-14591D2-112 | 594 |
| 5962-9684401HYA | B | 07/16/2004 | 1 | DDC | | Y | SD-14591F2-142 | 594 |
| 5962-9684401HYA | B | 07/16/2004 | 1 | DDC IRELAND | | Y | SD-14591F2-142 | 594 |
| 5962-9684401HYC | B | 07/16/2004 | 1 | DDC | | Y | SD-14591F2-112 | 594 |
| 5962-9684401HYC | B | 07/16/2004 | 1 | DDC IRELAND | | Y | SD-14591F2-112 | 594 |
| 5962-9684402HXA | B | 07/16/2004 | 1 | DDC | | Y | SD-14591D2-144 | 594 |
| 5962-9684402HXA | B | 07/16/2004 | 1 | DDC IRELAND | | Y | SD-14591D2-144 | 594 |
| 5962-9684402HXC | B | 07/16/2004 | 1 | DDC | | Y | SD-14591D2-114 | 594 |
| 5962-9684402HXC | B | 07/16/2004 | 1 | DDC IRELAND | | Y | SD-14591D2-114 | 594 |
| 5962-9684402HYA | B | 07/16/2004 | 1 | DDC | | Y | SD-14591F2-144 | 594 |
| 5962-9684402HYA | B | 07/16/2004 | 1 | DDC IRELAND | | Y | SD-14591F2-144 | 594 |
| 5962-9684402HYC | B | 07/16/2004 | 1 | DDC | | Y | SD-14591F2-114 | 594 |
| 5962-9684402HYC | B | 07/16/2004 | 1 | DDC IRELAND | | Y | SD-14591F2-114 | 594 |
| 5962-9684403HXA | B | 07/16/2004 | 1 | DDC | | Y | SD-14591D3-142 | 594 |
| 5962-9684403HXA | B | 07/16/2004 | 1 | DDC IRELAND | | Y | SD-14591D3-142 | 594 |
| 5962-9684403HXC | B | 07/16/2004 | 1 | DDC | | Y | SD-14591D3-112 | 594 |
| 5962-9684403HXC | B | 07/16/2004 | 1 | DDC IRELAND | | Y | SD-14591D3-112 | 594 |
| 5962-9684403HYA | B | 07/16/2004 | 1 | DDC | | Y | SD-14591F3-142 | 594 |
| 5962-9684403HYA | B | 07/16/2004 | 1 | DDC IRELAND | | Y | SD-14591F3-142 | 594 |
| 5962-9684403HYC | B | 07/16/2004 | 1 | DDC | | Y | SD-14591F3-112 | 594 |
| 5962-9684403HYC | B | 07/16/2004 | 1 | DDC IRELAND | | Y | SD-14591F3-112 | 594 |
| 5962-9684404HXA | B | 07/16/2004 | 1 | DDC | | Y | SD-14591D3-144 | 594 |
| 5962-9684404HXA | B | 07/16/2004 | 1 | DDC IRELAND | | Y | SD-14591D3-144 | 594 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9684404HXC | B | 07/16/2004 | 1 | DDC | | Y | SD-14591D3-114 | 594 |
| 5962-9684404HXC | B | 07/16/2004 | 1 | DDC IRELAND | | Y | SD-14591D3-114 | 594 |
| 5962-9684404HYA | B | 07/16/2004 | 1 | DDC | | Y | SD-14591F3-144 | 594 |
| 5962-9684404HYA | B | 07/16/2004 | 1 | DDC IRELAND | | Y | SD-14591F3-144 | 594 |
| 5962-9684404HYC | B | 07/16/2004 | 1 | DDC | | Y | SD-14591F3-114 | 594 |
| 5962-9684404HYC | B | 07/16/2004 | 1 | DDC IRELAND | | Y | SD-14591F3-114 | 594 |
| 5962-9684405HXA | B | 07/16/2004 | 1 | DDC | | Y | SD-14592D2-142 | 594 |
| 5962-9684405HXA | B | 07/16/2004 | 1 | DDC IRELAND | | Y | SD-14592D2-142 | 594 |
| 5962-9684405HXC | B | 07/16/2004 | 1 | DDC | | Y | SD-14592D2-112 | 594 |
| 5962-9684405HXC | B | 07/16/2004 | 1 | DDC IRELAND | | Y | SD-14592D2-112 | 594 |
| 5962-9684405HYA | B | 07/16/2004 | 1 | DDC | | Y | SD-14592F2-142 | 594 |
| 5962-9684405HYA | B | 07/16/2004 | 1 | DDC IRELAND | | Y | SD-14592F2-142 | 594 |
| 5962-9684405HYC | B | 07/16/2004 | 1 | DDC | | Y | SD-14592F2-112 | 594 |
| 5962-9684405HYC | B | 07/16/2004 | 1 | DDC IRELAND | | Y | SD-14592F2-112 | 594 |
| 5962-9684406HXA | B | 07/16/2004 | 1 | DDC | | Y | SD-14592D2-144 | 594 |
| 5962-9684406HXA | B | 07/16/2004 | 1 | DDC IRELAND | | Y | SD-14592D2-144 | 594 |
| 5962-9684406HXC | B | 07/16/2004 | 1 | DDC | | Y | SD-14592D2-114 | 594 |
| 5962-9684406HXC | B | 07/16/2004 | 1 | DDC IRELAND | | Y | SD-14592D2-114 | 594 |
| 5962-9684406HYA | B | 07/16/2004 | 1 | DDC | | Y | SD-14592F2-144 | 594 |
| 5962-9684406HYA | B | 07/16/2004 | 1 | DDC IRELAND | | Y | SD-14592F2-144 | 594 |
| 5962-9684406HYC | B | 07/16/2004 | 1 | DDC | | Y | SD-14592F2-114 | 594 |
| 5962-9684406HYC | B | 07/16/2004 | 1 | DDC IRELAND | | Y | SD-14592F2-114 | 594 |
| 5962-9684407HXA | B | 07/16/2004 | 1 | DDC | | Y | SD-14592D2-145 | 594 |
| 5962-9684407HXA | B | 07/16/2004 | 1 | DDC IRELAND | | Y | SD-14592D2-145 | 594 |
| 5962-9684407HXC | B | 07/16/2004 | 1 | DDC | | Y | SD-14592D2-115 | 594 |
| 5962-9684407HXC | B | 07/16/2004 | 1 | DDC IRELAND | | Y | SD-14592D2-115 | 594 |
| 5962-9684407HYA | B | 07/16/2004 | 1 | DDC | | Y | SD-14592F2-145 | 594 |
| 5962-9684407HYA | B | 07/16/2004 | 1 | DDC IRELAND | | Y | SD-14592F2-145 | 594 |
| 5962-9684407HYC | B | 07/16/2004 | 1 | DDC | | Y | SD-14592F2-115 | 594 |
| 5962-9684407HYC | B | 07/16/2004 | 1 | DDC IRELAND | | Y | SD-14592F2-115 | 594 |
| 5962-9684408HXA | B | 07/16/2004 | 1 | DDC | | Y | SD-14592D3-142 | 594 |
| 5962-9684408HXA | B | 07/16/2004 | 1 | DDC IRELAND | | Y | SD-14592D3-142 | 594 |
| 5962-9684408HXC | B | 07/16/2004 | 1 | DDC | | Y | SD-14592D3-112 | 594 |
| 5962-9684408HXC | B | 07/16/2004 | 1 | DDC IRELAND | | Y | SD-14592D3-112 | 594 |
| 5962-9684408HYA | B | 07/16/2004 | 1 | DDC | | Y | SD-14592F3-142 | 594 |
| 5962-9684408HYA | B | 07/16/2004 | 1 | DDC IRELAND | | Y | SD1-4592F3-142 | 594 |
| 5962-9684408HYC | B | 07/16/2004 | 1 | DDC | | Y | SD-14592F3-112 | 594 |
| 5962-9684408HYC | B | 07/16/2004 | 1 | DDC IRELAND | | Y | SD-14592F3-112 | 594 |
| 5962-9684409HXA | B | 07/16/2004 | 1 | DDC | | Y | SD-14592D3-144 | 594 |
| 5962-9684409HXA | B | 07/16/2004 | 1 | DDC IRELAND | | Y | SD-14592D3-144 | 594 |
| 5962-9684409HXC | B | 07/16/2004 | 1 | DDC | | Y | SD-14592D3-114 | 594 |
| 5962-9684409HXC | B | 07/16/2004 | 1 | DDC IRELAND | | Y | SD-14592D3-114 | 594 |
| 5962-9684409HYA | B | 07/16/2004 | 1 | DDC | | Y | SD-14592F3-144 | 594 |
| 5962-9684409HYA | B | 07/16/2004 | 1 | DDC IRELAND | | Y | SD-14592F3-144 | 594 |
| 5962-9684409HYC | B | 07/16/2004 | 1 | DDC | | Y | SD-14592F3-114 | 594 |
| 5962-9684409HYC | B | 07/16/2004 | 1 | DDC IRELAND | | Y | SD-14592F3-114 | 594 |
| 5962-9684410HXA | B | 07/16/2004 | 1 | DDC | | Y | SD-14592D3-145 | 594 |
| 5962-9684410HXA | B | 07/16/2004 | 1 | DDC IRELAND | | Y | SD-14592D3-145 | 594 |
| 5962-9684410HXC | B | 07/16/2004 | 1 | DDC | | Y | SD-14592D3-115 | 594 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9684410HXC | B | 07/16/2004 | 1 | DDC IRELAND | | Y | SD-14592D3-115 | 594 |
| 5962-9684410HYA | B | 07/16/2004 | 1 | DDC | | Y | SD-14592F3-145 | 594 |
| 5962-9684410HYA | B | 07/16/2004 | 1 | DDC IRELAND | | Y | SD-14592F3-145 | 594 |
| 5962-9684410HYC | B | 07/16/2004 | 1 | DDC | | Y | SD-14592F3-115 | 594 |
| 5962-9684410HYC | B | 07/16/2004 | 1 | DDC IRELAND | | Y | SD-14592F3-115 | 594 |
| 5962H9684501Q9A | B | 02/27/2001 | 1 | UTMC | | Y | UT7C138C45_QDIE | 618 |
| 5962H9684501V9A | B | 02/27/2001 | 1 | UTMC | | Y | UT7C138C45_VDIE | 618 |
| 5962H9684501QXA | B | 02/27/2001 | 1 | UTMC | | Y | UT7C138C45GCAH | 618 |
| 5962H9684501QXC | B | 02/27/2001 | 1 | UTMC | | Y | UT7C138C45GCCH | 618 |
| 5962H9684501VXA | B | 02/27/2001 | 1 | UTMC | | Y | UT7C138C45GCAH | 618 |
| 5962H9684501VXC | B | 02/27/2001 | 1 | UTMC | | Y | UT7C138C45GCCH | 618 |
| 5962H9684501QYA | B | 02/27/2001 | 1 | UTMC | | Y | UT7C138C45WCAH | 618 |
| 5962H9684501QYC | B | 02/27/2001 | 1 | UTMC | | Y | UT7C138C45WCCH | 618 |
| 5962H9684501VYA | B | 02/27/2001 | 1 | UTMC | | Y | UT7C138C45WCAH | 618 |
| 5962H9684501VYC | B | 02/27/2001 | 1 | UTMC | | Y | UT7C138C45WCCH | 618 |
| 5962H9684502Q9A | B | 02/27/2001 | 1 | UTMC | | Y | UT7C139C45_QDIE | 629 |
| 5962H9684502V9A | B | 02/27/2001 | 1 | UTMC | | Y | UT7C139C45_VDIE | 629 |
| 5962H9684502QXA | B | 02/27/2001 | 1 | UTMC | | Y | UT7C139C45GCAH | 629 |
| 5962H9684502QXC | B | 02/27/2001 | 1 | UTMC | | Y | UT7C139C45GCCH | 629 |
| 5962H9684502VXA | B | 02/27/2001 | 1 | UTMC | | Y | UT7C139C45GCAH | 629 |
| 5962H9684502VXC | B | 02/27/2001 | 1 | UTMC | | Y | UT7C139C45GCCH | 629 |
| 5962H9684502QYA | B | 02/27/2001 | 1 | UTMC | | Y | UT7C139C45WCAH | 629 |
| 5962H9684502QYC | B | 02/27/2001 | 1 | UTMC | | Y | UT7C139C45WCCH | 629 |
| 5962H9684502VYA | B | 02/27/2001 | 1 | UTMC | | Y | UT7C139C45WCAH | 629 |
| 5962H9684502VYC | B | 02/27/2001 | 1 | UTMC | | Y | UT7C139C45WCCH | 629 |
| 5962H9684503QXA | B | 02/27/2001 | 1 | UTMC | | Y | UT7C138C55GCAH | 618 |
| 5962H9684503QXC | B | 02/27/2001 | 1 | UTMC | | Y | UT7C138C55GCCH | 618 |
| 5962H9684503VXA | B | 02/27/2001 | 1 | UTMC | | Y | UT7C138C55GCAH | 618 |
| 5962H9684503VXC | B | 02/27/2001 | 1 | UTMC | | Y | UT7C138C55GCCH | 618 |
| 5962H9684503QYA | B | 02/27/2001 | 1 | UTMC | | Y | UT7C138C55WCAH | 618 |
| 5962H9684503QYC | B | 02/27/2001 | 1 | UTMC | | Y | UT7C138C55WCCH | 618 |
| 5962H9684503VYA | B | 02/27/2001 | 1 | UTMC | | Y | UT7C138C55WCAH | 618 |
| 5962H9684503VYC | B | 02/27/2001 | 1 | UTMC | | Y | UT7C138C55WCCH | 618 |
| 5962H9684504QXA | B | 02/27/2001 | 1 | UTMC | | Y | UT7C139C55GCAH | 629 |
| 5962H9684504QXC | B | 02/27/2001 | 1 | UTMC | | Y | UT7C139C55GCCH | 629 |
| 5962H9684504VXA | B | 02/27/2001 | 1 | UTMC | | Y | UT7C139C55GCAH | 629 |
| 5962H9684504VXC | B | 02/27/2001 | 1 | UTMC | | Y | UT7C139C55GCCH | 629 |
| 5962H9684504QYA | B | 02/27/2001 | 1 | UTMC | | Y | UT7C139C55WCAH | 629 |
| 5962H9684504QYC | B | 02/27/2001 | 1 | UTMC | | Y | UT7C139C55WCCH | 629 |
| 5962H9684504VYA | B | 02/27/2001 | 1 | UTMC | | Y | UT7C139C55WCAH | 629 |
| 5962H9684504VYC | B | 02/27/2001 | 1 | UTMC | | Y | UT7C139C55WCCH | 629 |
| 5962-9684601QJA | A | 09/01/1999 | | (NONE) | | | AD7892S (GEN) | 592 |
| 5962-9684601QLA | A | 09/01/1999 | 2 | ANALOG (3) | | Y | AD7892SQ-1/QML | 592 |
| 5962H9684701QYC | A | 06/30/1998 | 1 | HONEYWELL (1) | | Y | RX1750-01 | 409 |
| 5962H9684702QYC | A | 06/30/1998 | 1 | HONEYWELL (1) | | Y | RX1750-02 | 409 |
| 5962-9684901QXA | A | 04/11/2000 | 3 | TI | | Y | SNJ54LVTH16952WD | 590 |
| 5962-9685001Q2A | A | 04/01/1997 | 1 | TI | | Y | SNJ54AHC540FK | 529 |
| 5962-9685001QRA | A | 04/01/1997 | 1 | TI | | Y | SNJ54AHC540J | 529 |
| 5962-9685001QSA | A | 04/01/1997 | 1 | TI | | Y | SNJ54AHC540W | 529 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9685101Q2A | B | 09/12/1997 | 1 | TI | | Y | SNJ54AHCT540FK | 529 |
| 5962-9685101QRA | B | 09/12/1997 | 1 | TI | | Y | SNJ54AHCT540J | 529 |
| 5962-9685101QSA | B | 09/12/1997 | 1 | TI | | Y | SNJ54AHCT540W | 529 |
| 5962-9685201HPA | A | 09/06/2002 | 1 | AGILENT | | Y | HCPL-5301#200 | 753 |
| 5962-9685201HPC | A | 09/06/2002 | 1 | AGILENT | | Y | HCPL-5301 | 753 |
| 5962-9685201KPA | A | 09/06/2002 | 1 | AGILENT | | Y | HCPL-530K#200 | 753 |
| 5962-9685201KPC | A | 09/06/2002 | 1 | AGILENT | | Y | HCPL-530K | 753 |
| 5962-9685201HXA | A | 09/06/2002 | 1 | AGILENT | | Y | HCPL-5301#300 | 753 |
| 5962-9685201HYA | A | 09/06/2002 | 1 | AGILENT | | Y | HCPL-5301#100 | 753 |
| 5962-9685201HYC | A | 09/06/2002 | 1 | AGILENT | | Y | HCPL-5301#100 | 753 |
| 5962-9685301Q2A | B | 09/16/1997 | 1 | TI | | Y | SNJ54AHCT574FK | 159 |
| 5962-9685301QRA | B | 09/16/1997 | 1 | TI | | Y | SNJ54AHCT574J | 159 |
| 5962-9685301QSA | B | 09/16/1997 | 1 | TI | | Y | SNJ54AHCT574W | 159 |
| 5962-9685401Q2A | | 08/07/1996 | 1 | TI | | Y | SNJ54AHC574FK | 159 |
| 5962-9685401QRA | | 08/07/1996 | 1 | TI | | Y | SNJ54AHC574J | 159 |
| 5962-9685401QSA | | 08/07/1996 | 1 | TI | | Y | SNJ54AHC574W | 159 |
| 5962-9685501Q2A | B | 09/16/1997 | 1 | TI | | Y | SNJ54AHCT573FK | 342 |
| 5962-9685501QRA | B | 09/16/1997 | 1 | TI | | Y | SNJ54AHCT573J | 342 |
| 5962-9685501QSA | B | 09/16/1997 | 1 | TI | | Y | SNJ54AHCT573W | 342 |
| 5962-9685601Q2A | | 07/02/1996 | 1 | TI | | Y | SNJ54AHC573FK | 342 |
| 5962-9685601QRA | | 07/02/1996 | 1 | TI | | Y | SNJ54AHC573J | 342 |
| 5962-9685601QSA | | 07/02/1996 | 1 | TI | | Y | SNJ54AHC573W | 342 |
| 5962-9685701Q2A | | 08/15/1996 | 1 | TI | | Y | SNJ54AHC541FK | 529 |
| 5962-9685701QRA | | 08/15/1996 | 1 | TI | | Y | SNJ54AHC541J | 529 |
| 5962-9685701QSA | | 08/15/1996 | 1 | TI | | Y | SNJ54AHC541W | 529 |
| 5962-9685801Q2A | B | 09/12/1997 | 1 | TI | | Y | SNJ54AHCT541FK | 529 |
| 5962-9685801QRA | B | 09/12/1997 | 1 | TI | | Y | SNJ54AHCT541J | 529 |
| 5962-9685801QSA | B | 09/12/1997 | 1 | TI | | Y | SNJ54AHCT541W | 529 |
| 5962-9686001Q2A | | 08/30/1996 | 2 | TI | | Y | SNJ54AHC74FK | 158 |
| 5962-9686001QCA | | 08/30/1996 | 2 | TI | | Y | SNJ54AHC74J | 158 |
| 5962-9686001QDA | | 08/30/1996 | 2 | TI | | Y | SNJ54AHC74W | 158 |
| 5962-9686101Q2A | A | 12/19/1997 | 2 | TI | | Y | SNJ54AHCT74FK | 158 |
| 5962-9686101QCA | A | 12/19/1997 | 2 | TI | | Y | SNJ54AHCT74J | 158 |
| 5962-9686101QDA | A | 12/19/1997 | 2 | TI | | Y | SNJ54AHCT74W | 158 |
| 5962-9686201Q2A | | 09/09/1996 | 1 | TI | | Y | SNJ54AHC126FK | 520 |
| 5962-9686201QCA | | 09/09/1996 | 1 | TI | | Y | SNJ54AHC126J | 520 |
| 5962-9686201QDA | | 09/09/1996 | 1 | TI | | Y | SNJ54AHC126W | 520 |
| 5962-9686301Q2A | B | 09/03/1997 | 2 | TI | | Y | SNJ54AHCT126W | 520 |
| 5962-9686301QCA | B | 09/03/1997 | 2 | TI | | Y | SNJ54AHCT126J | 520 |
| 5962-9686301QDA | B | 09/03/1997 | 2 | TI | | Y | SNJ54AHCT126W | 520 |
| 5962-9686401Q2A | | 08/30/1996 | 2 | TI | | Y | SNJ54AHC374FK | 159 |
| 5962-9686401QRA | | 08/30/1996 | 2 | TI | | Y | SNJ54AHC374J | 159 |
| 5962-9686401QSA | | 08/30/1996 | 2 | TI | | Y | SNJ54AHC374W | 159 |
| 5962-9686501Q2A | B | 09/03/1997 | 2 | TI | | Y | SNJ54AHCT374FK | 159 |
| 5962-9686501QRA | B | 09/03/1997 | 2 | TI | | Y | SNJ54AHCT374J | 159 |
| 5962-9686501QSA | B | 09/03/1997 | 2 | TI | | Y | SNJ54AHCT374W | 159 |
| 5962-9686601Q2A | | 09/06/1996 | 2 | TI | | Y | SNJ54AHC373FK | 159 |
| 5962-9686601QRA | | 09/06/1996 | 2 | TI | | Y | SNJ54AHC373J | 159 |
| 5962-9686601QSA | | 09/06/1996 | 2 | TI | | Y | SNJ54AHC373W | 159 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9686701Q2A | B | 09/03/1997 | 2 | TI | | Y | SNJ54AHCT373FK | 159 |
| 5962-9686701QRA | B | 09/03/1997 | 2 | TI | | Y | SNJ54AHCT373J | 159 |
| 5962-9686701QSA | B | 09/03/1997 | 2 | TI | | Y | SNJ54AHCT373W | 159 |
| 5962-9686801Q2A | | 10/14/1996 | 1 | TI | | Y | SNJ54AHC125FK | 569 |
| 5962-9686801QCA | | 10/14/1996 | 1 | TI | | Y | SNJ54AHC125J | 569 |
| 5962-9686801QDA | | 10/14/1996 | 1 | TI | | Y | SNJ54AHC125W | 569 |
| 5962-9686901Q2A | B | 09/03/1997 | 1 | TI | | Y | SNJ54AHCT125FK | 529 |
| 5962-9686901QCA | B | 09/03/1997 | 1 | TI | | Y | SNJ54AHCT125J | 529 |
| 5962-9686901QDA | B | 09/03/1997 | 1 | TI | | Y | SNJ54AHCT125W | 529 |
| 5962-9687001QXA | B | 01/21/2003 | 2 | NATIONAL | | Y | 54ABT16500W-QML | 590 |
| 5962H9687301QXA | | 10/02/1996 | 1 | UTMC | | Y | UT28F64T-35PCA | 659 |
| 5962H9687301QXC | | 10/02/1996 | 1 | UTMC | | Y | UT28F64T-35PCC | 659 |
| 5962H9687301VXA | | 10/02/1996 | 1 | UTMC | | Y | UT28F64T-35PCA | 659 |
| 5962H9687301VXC | | 10/02/1996 | 1 | UTMC | | Y | UT28F64T-35PCC | 659 |
| 5962H9687301QYA | | 10/02/1996 | 1 | UTMC | | Y | UT28F64T-35UCA | 659 |
| 5962H9687301QYC | | 10/02/1996 | 1 | UTMC | | Y | UT28F64T-35UCC | 659 |
| 5962H9687301VYA | | 10/02/1996 | 1 | UTMC | | Y | UT28F64T-35UCA | 659 |
| 5962H9687301VYC | | 10/02/1996 | 1 | UTMC | | Y | UT28F64T-35UCC | 659 |
| 5962H9687302QXA | | 10/02/1996 | 1 | UTMC | | Y | UT28F64T-45PCA | 659 |
| 5962H9687302QXC | | 10/02/1996 | 1 | UTMC | | Y | UT28F64T-45PCC | 659 |
| 5962H9687302VXA | | 10/02/1996 | 1 | UTMC | | Y | UT28F64T-45PCA | 659 |
| 5962H9687302VXC | | 10/02/1996 | 1 | UTMC | | Y | UT28F64T-45PCC | 659 |
| 5962H9687302QYA | | 10/02/1996 | 1 | UTMC | | Y | UT28F64T-45UCA | 659 |
| 5962H9687302QYC | | 10/02/1996 | 1 | UTMC | | Y | UT28F64T-45UCC | 659 |
| 5962H9687302VYA | | 10/02/1996 | 1 | UTMC | | Y | UT28F64T-45UCA | 659 |
| 5962H9687302VYC | | 10/02/1996 | 1 | UTMC | | Y | UT28F64T-45UCC | 659 |
| 5962-9687601MPA | | 09/24/1996 | | (NONE) | 03/06/2001 | | CLC111 (GEN) | 899 |
| 5962H9687701QXC | B | 04/20/1998 | 2 | BAE SYSTEMS | | Y | LM1M8CRH-Q40X | 625 |
| 5962H9687701VXC | B | 04/20/1998 | 2 | BAE SYSTEMS | | Y | LM1M8CRH-V40X | 625 |
| 5962H9687702QXC | B | 04/20/1998 | 2 | BAE SYSTEMS | | Y | LM1M8TRH-Q40X | 625 |
| 5962H9687702VXC | B | 04/20/1998 | 2 | BAE SYSTEMS | | Y | LM1M8TRH-V40X | 625 |
| 5962H9687703QXC | B | 04/20/1998 | 2 | BAE SYSTEMS | | Y | LM1M8CRH-Q30X | 625 |
| 5962H9687703VXC | B | 04/20/1998 | 2 | BAE SYSTEMS | | Y | LM1M8CRH-V30X | 625 |
| 5962H9687703QYC | B | 04/20/1998 | 2 | BAE SYSTEMS | | Y | LM1M8CRH-Q30Y | 625 |
| 5962H9687703VYC | B | 04/20/1998 | 2 | BAE SYSTEMS | | Y | LM1M8CRH-V30Y | 625 |
| 5962H9687704QXC | B | 04/20/1998 | 2 | BAE SYSTEMS | | Y | LM1M8TRH-Q30X | 625 |
| 5962H9687704VXC | B | 04/20/1998 | 2 | BAE SYSTEMS | | Y | LM1M8TRH-V30X | 625 |
| 5962H9687704QYC | B | 04/20/1998 | 2 | BAE SYSTEMS | | Y | LM1M8TRH-Q30Y | 625 |
| 5962H9687704VYC | B | 04/20/1998 | 2 | BAE SYSTEMS | | Y | LM1M8TRH-V30Y | 625 |
| 5962H9687705QXC | B | 04/20/1998 | 2 | BAE SYSTEMS | | Y | LM1M8CRH-Q25X | 625 |
| 5962H9687705VXC | B | 04/20/1998 | 2 | BAE SYSTEMS | | Y | LM1M8CRH-V25X | 625 |
| 5962H9687705QYC | B | 04/20/1998 | 2 | BAE SYSTEMS | | Y | LM1M8CRH-Q25Y | 625 |
| 5962H9687705VYC | B | 04/20/1998 | 2 | BAE SYSTEMS | | Y | LM1M8CRH-V25Y | 625 |
| 5962H9687706QXC | B | 04/20/1998 | 2 | BAE SYSTEMS | | Y | LM1M8TRH-Q25X | 625 |
| 5962H9687706VXC | B | 04/20/1998 | 2 | BAE SYSTEMS | | Y | LM1M8TRH-V25X | 625 |
| 5962H9687706QYC | B | 04/20/1998 | 2 | BAE SYSTEMS | | Y | LM1M8TRH-Q25Y | 625 |
| 5962H9687706VYC | B | 04/20/1998 | 2 | BAE SYSTEMS | | Y | LM1M8TRH-V25Y | 625 |
| 5962-9687801QEA | B | 01/24/1997 | | (NONE) | 12/31/2001 | | 54365 (GEN) | 522 |
| 5962-9687802QEA | B | 01/24/1997 | 1 | TI | | Y | SNJ54366AJ | 523 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9687802QFA | B | 01/24/1997 | 1 | TI | | Y | SNJ54366AW | 523 |
| 5962-9687803QEA | B | 01/24/1997 | | (NONE) | 12/31/2001 | | 54367A (GEN) | 522 |
| 5962-9687803QFA | B | 01/24/1997 | | (NONE) | 12/31/2001 | | 54367A (GEN) | 522 |
| 5962-9687804QEA | B | 01/24/1997 | | (NONE) | 12/31/2001 | | 54368A (GEN) | 523 |
| 5962-9687804QFA | B | 01/24/1997 | | (NONE) | 12/31/2001 | | 54368A (GEN) | 523 |
| 5962-9687901QEA | | 04/08/1997 | | (NONE) | 09/04/2001 | | LM2595J-3.3 (GEN) | 782 |
| 5962-9688001QXA | A | 02/11/2003 | 3 | NATIONAL | | Y | 54ACTQ16240W-QML | 529 |
| 5962-9688101Q2A | A | 04/18/2002 | 1 | TI | | Y | TLV2352MFKB | 776 |
| 5962-9688101QHA | A | 04/18/2002 | 1 | TI | | Y | TLV2352MUB | 776 |
| 5962-9688101QPA | A | 04/18/2002 | 1 | TI | | Y | TLV2352MJGB | 776 |
| 5962-9688201Q2A | A | 04/16/2002 | 1 | TI | | Y | TLV2354MFKB | 776 |
| 5962-9688201QCA | A | 04/16/2002 | 1 | TI | | Y | TLV2354MJB | 776 |
| 5962-9688201QDA | A | 04/16/2002 | 1 | TI | | Y | TLV2354MWB | 776 |
| 5962-9688401QEA | A | 06/13/2003 | 3 | NATIONAL | 12/01/2004 | Y | LM3940J-3.3-QML | 789 |
| 5962-9688401QXA | A | 06/13/2003 | 3 | NATIONAL | 12/01/2004 | Y | LM3940WG-3.3-QML | 789 |
| 5962-9688601QRA | B | 11/18/2002 | 1 | TI | | Y | TLC2543MJB | 592 |
| 5962-9688701HXA | D | 06/18/2003 | 1 | DDC | | Y | BU61582D1-140 | 599 |
| 5962-9688701HXC | D | 06/18/2003 | 1 | DDC | | Y | BU61582D1-110 | 599 |
| 5962-9688701HYA | D | 06/18/2003 | 1 | DDC | | Y | BU61582F1-140 | 599 |
| 5962-9688701HYC | D | 06/18/2003 | 1 | DDC | | Y | BU61582F1-110 | 599 |
| 5962-9688701HZA | D | 06/18/2003 | 1 | DDC | | Y | BU61582G1-140 | 599 |
| 5962-9688701HZC | D | 06/18/2003 | 1 | DDC | | Y | BU61582G1-110 | 599 |
| 5962-9688702HXA | D | 06/18/2003 | 1 | DDC | | Y | BU61582D2-140 | 599 |
| 5962-9688702HXC | D | 06/18/2003 | 1 | DDC | | Y | BU61582D2-110 | 599 |
| 5962-9688702HYA | D | 06/18/2003 | 1 | DDC | | Y | BU61582F2-140 | 599 |
| 5962-9688702HYC | D | 06/18/2003 | 1 | DDC | | Y | BU61582F2-110 | 599 |
| 5962-9688702HZA | D | 06/18/2003 | 1 | DDC | | Y | BU61582G2-140 | 599 |
| 5962-9688702HZC | D | 06/18/2003 | 1 | DDC | | Y | BU61582G2-110 | 599 |
| 5962-9688703HXA | D | 06/18/2003 | 1 | DDC | | Y | BU61583D1-140 | 599 |
| 5962-9688703HXC | D | 06/18/2003 | 1 | DDC | | Y | BU61583D1-110 | 599 |
| 5962-9688703HYA | D | 06/18/2003 | 1 | DDC | | Y | BU61583F1-140 | 599 |
| 5962-9688703HYC | D | 06/18/2003 | 1 | DDC | | Y | BU61583F1-110 | 599 |
| 5962-9688703HZA | D | 06/18/2003 | 1 | DDC | | Y | BU61583G1-140 | 599 |
| 5962-9688703HZC | D | 06/18/2003 | 1 | DDC | | Y | BU61583G1-110 | 599 |
| 5962-9688704HXA | D | 06/18/2003 | 1 | DDC | | Y | BU61583D2-140 | 599 |
| 5962-9688704HXC | D | 06/18/2003 | 1 | DDC | | Y | BU61583D2-110 | 599 |
| 5962-9688704HYA | D | 06/18/2003 | 1 | DDC | | Y | BU61583F2-140 | 599 |
| 5962-9688704HYC | D | 06/18/2003 | 1 | DDC | | Y | BU61583F2-110 | 599 |
| 5962-9688704HZA | D | 06/18/2003 | 1 | DDC | | Y | BU61583G2-140 | 599 |
| 5962-9688704HZC | D | 06/18/2003 | 1 | DDC | | Y | BU61583G2-110 | 599 |
| 5962-9688705HXA | D | 06/18/2003 | 1 | DDC | | Y | BU61582D0-140 | 599 |
| 5962-9688705HXC | D | 06/18/2003 | 1 | DDC | | Y | BU61582D0-110 | 599 |
| 5962-9688705HYA | D | 06/18/2003 | 1 | DDC | | Y | BU61582F0-140 | 599 |
| 5962-9688705HYC | D | 06/18/2003 | 1 | DDC | | Y | BU61582F0-110 | 599 |
| 5962-9688705HZA | D | 06/18/2003 | 1 | DDC | | Y | BU61582G0-140 | 599 |
| 5962-9688705HZC | D | 06/18/2003 | 1 | DDC | | Y | BU61582G0-110 | 599 |
| 5962-9688706HXA | D | 06/18/2003 | 1 | DDC | | Y | BU61583D0-140 | 599 |
| 5962-9688706HXC | D | 06/18/2003 | 1 | DDC | | Y | BU61583D0-110 | 599 |
| 5962-9688706HYA | D | 06/18/2003 | 1 | DDC | | Y | BU61583F0-140 | 599 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9688706HYC | D | 06/18/2003 | 1 | DDC | | Y | BU61583F0-110 | 599 |
| 5962-9688706HZA | D | 06/18/2003 | 1 | DDC | | Y | BU61583G0-140 | 599 |
| 5962-9688706HZC | D | 06/18/2003 | 1 | DDC | | Y | BU61583G0-110 | 599 |
| 5962-9688707HXA | D | 06/18/2003 | 1 | DDC | | Y | BU61582D3-140 | 599 |
| 5962-9688707HXC | D | 06/18/2003 | 1 | DDC | | Y | BU61582D3-110 | 599 |
| 5962-9688707HYA | D | 06/18/2003 | 1 | DDC | | Y | BU61582F3-140 | 599 |
| 5962-9688707HYC | D | 06/18/2003 | 1 | DDC | | Y | BU61582F3-110 | 599 |
| 5962-9688707HZA | D | 06/18/2003 | 1 | DDC | | Y | BU61582G3-140 | 599 |
| 5962-9688707HZC | D | 06/18/2003 | 1 | DDC | | Y | BU61582G3-110 | 599 |
| 5962-9688901Q9A | | 10/15/1996 | 2 | MICRON TECH. | | Y | MT4C1004JD22ADC3-6 | 629 |
| 5962-9688902Q9A | | 10/15/1996 | 2 | MICRON TECH. | | Y | MT4C1004JD22ADC3-7 | 629 |
| 5962-9689001QXA | A | 02/04/2003 | 1 | TI | | Y | SNJ54GTL16612WD | 590 |
| 5962R9689101QXC | B | 05/25/2004 | 1 | BAE SYSTEMS | | Y | LMP2568C-Q45X | 662 |
| 5962R9689101VXA | B | 05/25/2004 | 1 | BAE SYSTEMS | | Y | LMP2568C-V45X | 662 |
| 5962R9689102QXA | B | 05/25/2004 | 1 | BAE SYSTEMS | | Y | LMP2568T-Q45X | 662 |
| 5962R9689102VXA | B | 05/25/2004 | 1 | BAE SYSTEMS | | Y | LMP2568T-V45X | 662 |
| 5962H9689103QXA | B | 05/25/2004 | 1 | UTMC | | Y | UT28F256T-45UCAH | 662 |
| 5962H9689103QXC | B | 05/25/2004 | 1 | UTMC | | Y | UT28F256T-45UCCH | 662 |
| 5962H9689103VXA | B | 05/25/2004 | 1 | UTMC | | Y | UT28F256T-45UCAH | 662 |
| 5962H9689103VXC | B | 05/25/2004 | 1 | UTMC | | Y | UT28F256T-45UCCH | 662 |
| 5962H9689103QYA | B | 05/25/2004 | 1 | UTMC | | Y | UT28F256T-45PCAH | 662 |
| 5962H9689103QYC | B | 05/25/2004 | 1 | UTMC | | Y | UT28F256T-45PCAH | 662 |
| 5962H9689103VYA | B | 05/25/2004 | 1 | UTMC | | Y | UT28F256T-45PCAH | 662 |
| 5962H9689103VYC | B | 05/25/2004 | 1 | UTMC | | Y | UT28F256T-45PCCH | 662 |
| 5962H9689104QXA | B | 05/25/2004 | 1 | UTMC | | Y | UT28F256T-40UCAH | 662 |
| 5962H9689104QXC | B | 05/25/2004 | 1 | UTMC | | Y | UT28F256T-40UCCH | 662 |
| 5962H9689104VXA | B | 05/25/2004 | 1 | UTMC | | Y | UT28F256T-40UCAH | 662 |
| 5962H9689104VXC | B | 05/25/2004 | 1 | UTMC | | Y | UT28F256T-40UCCH | 662 |
| 5962H9689104QYA | B | 05/25/2004 | 1 | UTMC | | Y | UT28F256T-40PCAH | 662 |
| 5962H9689104QYC | B | 05/25/2004 | 1 | UTMC | | Y | UT28F256T-40PCCH | 662 |
| 5962H9689104VYA | B | 05/25/2004 | 1 | UTMC | | Y | UT28F256T-40PCAH | 662 |
| 5962H9689104VYC | B | 05/25/2004 | 1 | UTMC | | Y | UT28F256T-40PCCH | 662 |
| 5962H9689105QXA | B | 05/25/2004 | 1 | UTMC | | Y | UT28F256QLT-45UCAH | 662 |
| 5962H9689105QXC | B | 05/25/2004 | 1 | UTMC | | Y | UT28F256QLT-45UCCH | 662 |
| 5962H9689105VXA | B | 05/25/2004 | 1 | UTMC | | Y | UT28F256QLT-45UCAH | 662 |
| 5962H9689105VXC | B | 05/25/2004 | 1 | UTMC | | Y | UT28F256QLT-45UCCH | 662 |
| 5962H9689106QXA | B | 05/25/2004 | 1 | UTMC | | Y | UT28F256QLT-40UCAH | 662 |
| 5962H9689106QXC | B | 05/25/2004 | 1 | UTMC | | Y | UT28F256QLT-40UCCH | 662 |
| 5962H9689106VXA | B | 05/25/2004 | 1 | UTMC | | Y | UT28F256QLT-40UCAH | 662 |
| 5962H9689106VXC | B | 05/25/2004 | 1 | UTMC | | Y | UT28F256QLT-40UCCH | 662 |
| 5962F9689107QXA | B | 05/25/2004 | 1 | UTMC | | Y | UT28F256QLT-45UCAF | 662 |
| 5962F9689107QXC | B | 05/25/2004 | 1 | UTMC | | Y | UT28F256QLT-45UCCF | 662 |
| 5962F9689107VXA | B | 05/25/2004 | 1 | UTMC | | Y | UT28F256QLT-45UCAF | 662 |
| 5962F9689107VXC | B | 05/25/2004 | 1 | UTMC | | Y | UT28F256QLT-45UCCF | 662 |
| 5962F9689108QXA | B | 05/25/2004 | 1 | UTMC | | Y | UT28F256QLT-40UCAF | 662 |
| 5962F9689108QXC | B | 05/25/2004 | 1 | UTMC | | Y | UT28F256QLT-40UCCF | 662 |
| 5962F9689108VXA | B | 05/25/2004 | 1 | UTMC | | Y | UT28F256QLT-40UCAF | 662 |
| 5962F9689108VXC | B | 05/25/2004 | 1 | UTMC | | Y | UT28F256QLT-40UCCF | 662 |
| 5962-9689201VJA | B | 05/02/2003 | 2 | ANALOG (5) | | Y | AD565ASD/QMLV | 591 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9689201VKA | B | 05/02/2003 | | (NONE) | | | 565AS (GEN) | 591 |
| 5962-9689201VLA | B | 05/02/2003 | | (NONE) | | | 565AS (GEN) | 591 |
| 5962-9689202VJA | B | 05/02/2003 | 2 | ANALOG (5) | | Y | AD565ATD/QMLV | 591 |
| 5962-9689202VLA | B | 05/02/2003 | | (NONE) | | | 565AT (GEN) | 591 |
| 5962-9689301QXA | B | 04/11/2003 | 3 | TI | | Y | SNJ55976A1WD | 590 |
| 5962-9689301NYD | B | 04/11/2003 | | (NONE) | | | 55976A1 (GEN) | 590 |
| 5962-9689302QXA | B | 04/11/2003 | 3 | TI | | Y | SNJ55976A2WD | 590 |
| 5962-9689302NYD | B | 04/11/2003 | | (NONE) | | | 55976A2 (GEN) | 590 |
| 5962-9689401Q2A | | 09/18/1996 | 2 | TI | 06/30/2004 | Y | TLV1543MFKB | 592 |
| 5962-9689401QRA | | 09/18/1996 | 2 | TI | 06/30/2004 | Y | TLV1543MJB | 592 |
| 5962-9689501Q3A | | 05/06/1997 | | (NONE) | 03/08/2003 | | 7B923 (GEN) | 579 |
| 5962-9689601Q3A | | 05/06/1997 | | (NONE) | 03/08/2003 | | 7B933 (GEN) | 579 |
| 5962-9689701HXA | B | 08/30/2002 | 1 | MS KENNEDY | | Y | MSK167B | 739 |
| 5962-9689701HXC | B | 08/30/2002 | 1 | MS KENNEDY | | Y | MSK167B | 739 |
| 5962-9689703HXA | B | 08/30/2002 | | (NONE) | | | MSK167B (GEN) | 739 |
| 5962-9689703HXC | B | 08/30/2002 | | (NONE) | | | MSK167B (GEN) | 739 |
| 5962-9689801HXA | A | 08/19/2004 | 1 | INTERPOINT | | Y | MHF+2828S/883 | 594 |
| 5962-9689801HXC | A | 08/19/2004 | 1 | INTERPOINT | | Y | MHF+2828S/883 | 594 |
| 5962-9689801HZA | A | 08/19/2004 | 1 | INTERPOINT | | Y | MHF+2828SF/883 | 594 |
| 5962-9689801HZC | A | 08/19/2004 | 1 | INTERPOINT | | Y | MHF+2828SF/883 | 594 |
| 5962-9689901HUA | A | 11/29/2001 | 1 | ADV. ANALOG | | Y | AFL2828SW/CH | 594 |
| 5962-9689901HUC | A | 11/29/2001 | 1 | ADV. ANALOG | | Y | AFL2828SW/CH | 594 |
| 5962-9689901HXA | A | 11/29/2001 | 1 | ADV. ANALOG | | Y | AFL2828SX/CH | 594 |
| 5962-9689901HXC | A | 11/29/2001 | 1 | ADV. ANALOG | | Y | AFL2828SX/CH | 594 |
| 5962-9689901HYA | A | 11/29/2001 | 1 | ADV. ANALOG | | Y | AFL2828SY/CH | 594 |
| 5962-9689901HYC | A | 11/29/2001 | 1 | ADV. ANALOG | | Y | AFL2828SY/CH | 594 |
| 5962-9689901HZA | A | 11/29/2001 | 1 | ADV. ANALOG | | Y | AFL2828SZ/CH | 594 |
| 5962-9689901HZC | A | 11/29/2001 | 1 | ADV. ANALOG | | Y | AFL2828SZ/CH | 594 |
| 5962-9690001H9A | F | 11/10/2003 | 1 | WHITE ELEC. | | Y | WSF128K16-72G1UQ5 | 699 |
| 5962-9690001H9C | F | 11/10/2003 | 1 | WHITE ELEC. | | Y | WSF128K16-72G1UQ5 | 699 |
| 5962-9690001HBA | F | 11/10/2003 | 1 | WHITE ELEC. | | Y | WSF128K16-72G1TQA | 699 |
| 5962-9690001HBC | F | 11/10/2003 | 1 | WHITE ELEC. | | Y | WSF128K16-72G1TQ | 699 |
| 5962-9690001HMA | F | 11/10/2003 | 1 | WHITE ELEC. | | Y | WSF128K16-72G2QA | 699 |
| 5962-9690001HMC | F | 11/10/2003 | 1 | WHITE ELEC. | | Y | WSF128K16-72G2Q | 699 |
| 5962-9690001HXA | F | 11/10/2003 | 1 | WHITE ELEC. | | Y | WSF128K16-72HQA | 699 |
| 5962-9690001HXC | F | 11/10/2003 | 1 | WHITE ELEC. | | Y | WSF128K16-72HQ | 699 |
| 5962-9690001HYA | F | 11/10/2003 | 1 | WHITE ELEC. | | Y | WSF128K16-72H1QA | 699 |
| 5962-9690001HYC | F | 11/10/2003 | 1 | WHITE ELEC. | | Y | WSF128K16-72H1Q | 699 |
| 5962-9690002H9A | F | 11/10/2003 | 1 | WHITE ELEC. | | Y | WSF128K16-37G1UQ5 | 699 |
| 5962-9690002H9C | F | 11/10/2003 | 1 | WHITE ELEC. | | Y | WSF128K16-37G1UQ5 | 699 |
| 5962-9690002HBA | F | 11/10/2003 | 1 | WHITE ELEC. | | Y | WSF128K16-37G1TQA | 699 |
| 5962-9690002HBC | F | 11/10/2003 | 1 | WHITE ELEC. | | Y | WSF128K16-37G1TQ | 699 |
| 5962-9690002HMA | F | 11/10/2003 | 1 | WHITE ELEC. | | Y | WSF128K16-37G2QA | 699 |
| 5962-9690002HMC | F | 11/10/2003 | 1 | WHITE ELEC. | | Y | WSF128K16-37G2Q | 699 |
| 5962-9690002HXA | F | 11/10/2003 | 1 | WHITE ELEC. | | Y | WSF128K16-37HQA | 699 |
| 5962-9690002HXC | F | 11/10/2003 | 1 | WHITE ELEC. | | Y | WSF128K16-37HQ | 699 |
| 5962-9690002HYA | F | 11/10/2003 | 1 | WHITE ELEC. | | Y | WSF128K16-37H1QA | 699 |
| 5962-9690002HYC | F | 11/10/2003 | 1 | WHITE ELEC. | | Y | WSF128K16-37H1Q | 699 |
| 5962-9690101HMA | D | 04/29/2004 | 1 | WHITE ELEC. | | Y | WSF512K16-72G2QA | 600 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9690101HMC | D | 04/29/2004 | 1 | WHITE ELEC. | | Y | WSF512K16-72G2Q | 600 |
| 5962-9690101HXA | D | 04/29/2004 | 1 | WHITE ELEC. | | Y | WSF512K16-72H2QA | 600 |
| 5962-9690101HXC | D | 04/29/2004 | 1 | WHITE ELEC. | | Y | WSF512K16-72H2Q | 600 |
| 5962-9690102HMA | D | 04/29/2004 | 1 | WHITE ELEC. | | Y | WSF512K16-39G2QA | 600 |
| 5962-9690102HMC | D | 04/29/2004 | 1 | WHITE ELEC. | | Y | WSF512K16-39G2Q | 600 |
| 5962-9690102HXA | D | 04/29/2004 | 1 | WHITE ELEC. | | Y | WSF512K16-39H2QA | 600 |
| 5962-9690102HXC | D | 04/29/2004 | 1 | WHITE ELEC. | | Y | WSF512K16-39H2Q | 600 |
| 5962-9690201HMA | E | 12/22/2003 | 1 | WHITE ELEC. | | Y | WMS256K16-35DLQ | 600 |
| 5962-9690201HMC | E | 12/22/2003 | 1 | WHITE ELEC. | | Y | WMS256K16-35DLQ | 600 |
| 5962-9690201HNA | E | 12/22/2003 | 1 | WHITE ELEC. | | Y | WMS256K16-35FLQ | 600 |
| 5962-9690201HNC | E | 12/22/2003 | 1 | WHITE ELEC. | | Y | WMS256K16-35FLQ | 600 |
| 5962-9690201HTA | E | 12/22/2003 | 1 | WHITE ELEC. | | Y | WMS256K16-35FGQ | 600 |
| 5962-9690201HTC | E | 12/22/2003 | 1 | WHITE ELEC. | | Y | WMS256K16-35FGQ | 600 |
| 5962-9690202HMA | E | 12/22/2003 | 1 | WHITE ELEC. | | Y | WMS256K16-25DLQ | 600 |
| 5962-9690202HMC | E | 12/22/2003 | 1 | WHITE ELEC. | | Y | WMS256K16-25DLQ | 600 |
| 5962-9690202HNA | E | 12/22/2003 | 1 | WHITE ELEC. | | Y | WMS256K16-25FLQ | 600 |
| 5962-9690202HNC | E | 12/22/2003 | 1 | WHITE ELEC. | | Y | WMS256K16-25FLQ | 600 |
| 5962-9690202HTA | E | 12/22/2003 | 1 | WHITE ELEC. | | Y | WMS256K16-25FGQ | 600 |
| 5962-9690202HTC | E | 12/22/2003 | 1 | WHITE ELEC. | | Y | WMS256K16-25FGQ | 600 |
| 5962-9690203HMA | E | 12/22/2003 | 1 | WHITE ELEC. | | Y | WMS256K16-20DLQ | 600 |
| 5962-9690203HMC | E | 12/22/2003 | 1 | WHITE ELEC. | | Y | WMS256K16-20DLQ | 600 |
| 5962-9690203HNA | E | 12/22/2003 | 1 | WHITE ELEC. | | Y | WMS256K16-20FLQ | 600 |
| 5962-9690203HNC | E | 12/22/2003 | 1 | WHITE ELEC. | | Y | WMS256K16-20FLQ | 600 |
| 5962-9690203HTA | E | 12/22/2003 | 1 | WHITE ELEC. | | Y | WMS256K16-20FGQ | 600 |
| 5962-9690203HTC | E | 12/22/2003 | 1 | WHITE ELEC. | | Y | WMS256K16-20FGQ | 600 |
| 5962-9690204HMA | E | 12/22/2003 | 1 | WHITE ELEC. | | Y | WMS256K16-17DLQ | 600 |
| 5962-9690204HMC | E | 12/22/2003 | 1 | WHITE ELEC. | | Y | WMS256K16-17DLQ | 600 |
| 5962-9690204HNA | E | 12/22/2003 | 1 | WHITE ELEC. | | Y | WMS256K16-17FLQ | 600 |
| 5962-9690204HNC | E | 12/22/2003 | 1 | WHITE ELEC. | | Y | WMS256K16-17FLQ | 600 |
| 5962-9690204HTA | E | 12/22/2003 | 1 | WHITE ELEC. | | Y | WMS256K16-17FGQ | 600 |
| 5962-9690204HTC | E | 12/22/2003 | 1 | WHITE ELEC. | | Y | WMS256K16-17FGQ | 600 |
| 5962-9690301Q2A | A | 09/03/1997 | 1 | TI | | Y | SNJ55107AFK | 570 |
| 5962-9690301QCA | A | 09/03/1997 | 1 | TI | | Y | SNJ55107AJ | 570 |
| 5962-9690301QDA | A | 09/03/1997 | 1 | TI | | Y | SNJ55107AW | 570 |
| 5962-9690302Q2A | A | 09/03/1997 | | (NONE) | 05/01/1998 | | 55108A (GEN) | 570 |
| 5962-9690302QCA | A | 09/03/1997 | | (NONE) | 05/01/1998 | | 55108A (GEN) | 570 |
| 5962-9690302QDA | A | 09/03/1997 | | (NONE) | 05/01/1998 | | 55108A (GEN) | 570 |
| 5962-96A0101V9A | F | 10/17/2001 | 1 | INTERSIL | | Y | HS0-REF10RH-Q | 365 |
| 5962-96A0101VXC | F | 10/17/2001 | 1 | INTERSIL | | Y | HS9-REF10RH-Q | 365 |
| 5962-96A0201V9A | E | 10/16/2001 | 1 | INTERSIL | | Y | HS0-CMP05RH-Q | 365 |
| 5962-96A0201VXC | E | 10/16/2001 | 1 | INTERSIL | | Y | HS9-CMP05RH-Q | 365 |
| 5962-96A0301V9A | D | 10/16/2001 | 1 | INTERSIL | | Y | HS0-REF05RH-Q | 365 |
| 5962-96A0301VXC | D | 10/16/2001 | 1 | INTERSIL | | Y | HS9-REF05RH-Q | 365 |
| 5962-96A0401QXC | | 11/03/1999 | 1 | AMI | | Y | 9880-025 | 365 |
| 5962-96A0501QXC | | 08/20/1997 | 1 | AMI | | Y | 11110-001 | 365 |
| 5962-96A0601QXC | | 08/20/1997 | 1 | AMI | | Y | 6568-009 | 365 |
| 5962-96A0801QXA | A | 12/09/1996 | 2 | AMI | | Y | 9868-056 | 365 |
| 5962-96A0901QXA | | 08/20/1996 | 1 | AMI | | Y | 9868-062 | 365 |
| 5962-96A1001QXA | | 08/23/1996 | 1 | AMI | | Y | 9872-030 | 365 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962H96A1301QXC | | 12/01/1997 | | (NONE) | | | 22017396-006 (GEN) | 365 |
| 5962H96A1401QXC | A | 11/01/2001 | 1 | HONEYWELL (1) | | Y | 22017393-006 | 365 |
| 5962H96A1501QXC | B | 04/02/2001 | 2 | HONEYWELL (1) | | Y | 22017399-006 | 365 |
| 5962H96A1601QXC | A | 12/12/1997 | | (NONE) | | | 22017974-006 (GEN) | 365 |
| 5962-96A1701QXA | | 02/26/1997 | 3 | AMI | | Y | 6580-016 | 365 |
| 5962-96A1801QXA | A | 03/20/1998 | 2 | AMI | | Y | 8784-001 | 365 |
| 5962-96A1901QXA | | 03/03/1997 | 1 | AMI | | Y | 8731-001 | 365 |
| 5962-96B0101Q*A | B | 10/31/1996 | | TI | | Y | TGC2016 | 368 |
| 5962-96B0102Q*A | B | 10/31/1996 | | TI | | Y | TGC2019 | 368 |
| 5962-96B0103Q*A | B | 10/31/1996 | | TI | | Y | TGC2030 | 368 |
| 5962-96B0104Q*A | B | 10/31/1996 | | TI | | Y | TGC2036 | 368 |
| 5962-96B0105Q*A | B | 10/31/1996 | | TI | | Y | TGC2046 | 368 |
| 5962-96B0106Q*A | B | 10/31/1996 | | TI | | Y | TGC2053 | 368 |
| 5962-96B0107Q*A | B | 10/31/1996 | | TI | | Y | TGC2068 | 368 |
| 5962-96B0108Q*A | B | 10/31/1996 | | TI | | Y | TGC2086 | 368 |
| 5962-96B0109Q*A | B | 10/31/1996 | | TI | | Y | TGC2113 | 368 |
| 5962-96B0110Q*A | B | 10/31/1996 | | TI | | Y | TGC2154 | 368 |
| 5962-96B0111Q*A | B | 10/31/1996 | | TI | | Y | TGC2191 | 368 |
| 5962-96B0112Q*A | B | 10/31/1996 | | TI | | Y | TGC2245 | 368 |
| 5962H96B0201Q*A | C | 06/18/2001 | 1 | UTMC | | Y | UT25E/R*QCH | 368 |
| 5962H96B0201V*A | C | 06/18/2001 | 1 | UTMC | | Y | UT25E/R*VCH | 368 |
| 5962H96B0202Q*A | C | 06/18/2001 | 1 | UTMC | | Y | UT25E/R*QCH | 368 |
| 5962H96B0202V*A | C | 06/18/2001 | 1 | UTMC | | Y | UT25E/R*VCH | 368 |
| 5962H96B0203Q*A | C | 06/18/2001 | 1 | UTMC | | Y | UT25E/R*QCH | 368 |
| 5962H96B0203V*A | C | 06/18/2001 | 1 | UTMC | | Y | UT25E/R*VCH | 368 |
| 5962H96B0204Q*A | C | 06/18/2001 | 1 | UTMC | | Y | UT25E/R*QCH | 368 |
| 5962H96B0204V*A | C | 06/18/2001 | 1 | UTMC | | Y | UT25E/R*VCH | 368 |
| 5962H96B0205Q*A | C | 06/18/2001 | 1 | UTMC | | Y | UT25E/R*QCH | 368 |
| 5962H96B0205V*A | C | 06/18/2001 | 1 | UTMC | | Y | UT25E/R*VCH | 368 |
| 5962H96B0206Q*A | C | 06/18/2001 | 1 | UTMC | | Y | UT35E/R*QCH | 368 |
| 5962H96B0206V*A | C | 06/18/2001 | 1 | UTMC | | Y | UT35E/R*VCH | 368 |
| 5962H96B0206Q9A | C | 06/18/2001 | 1 | UTMC | | Y | UT35E/R*QDIE | 368 |
| 5962H96B0206V9A | C | 06/18/2001 | 1 | UTMC | | Y | UT35E/R*VDIE | 368 |
| 5962H96B0207Q*A | C | 06/18/2001 | 1 | UTMC | | Y | UT75E/R*QCH | 368 |
| 5962H96B0207V*A | C | 06/18/2001 | 1 | UTMC | | Y | UT75E/R*VCH | 368 |
| 5962H96B0208Q*A | C | 06/18/2001 | 1 | UTMC | | Y | UT100E/R*QCH | 368 |
| 5962H96B0208V*A | C | 06/18/2001 | 1 | UTMC | | Y | UT100E/R*VCH | 368 |
| 5962R96B0209Q*C | C | 06/18/2001 | 1 | UTMC | | Y | UT25*QCR | 368 |
| 5962R96B0209V*C | C | 06/18/2001 | 1 | UTMC | | Y | UT25*VCR | 368 |
| 5962R96B0210Q*C | C | 06/18/2001 | 1 | UTMC | | Y | UT25*QCR | 368 |
| 5962R96B0210V*C | C | 06/18/2001 | 1 | UTMC | | Y | UT25*VCR | 368 |
| 5962R96B0211Q*C | C | 06/18/2001 | 1 | UTMC | | Y | UT25*QCR | 368 |
| 5962R96B0211V*C | C | 06/18/2001 | 1 | UTMC | | Y | UT25*VCR | 368 |
| 5962R96B0212Q*C | C | 06/18/2001 | 1 | UTMC | | Y | UT25*QCR | 368 |
| 5962R96B0212V*C | C | 06/18/2001 | 1 | UTMC | | Y | UT25*VCR | 368 |
| 5962R96B0213Q*C | C | 06/18/2001 | 1 | UTMC | | Y | UT35*QCR | 368 |
| 5962R96B0213V*C | C | 06/18/2001 | 1 | UTMC | | Y | UT35*VCR | 368 |
| 5962R96B0214Q*C | C | 06/18/2001 | 1 | UTMC | | Y | UT75*QCR | 368 |
| 5962R96B0214V*C | C | 06/18/2001 | 1 | UTMC | | Y | UT75*VCR | 368 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962R96B0215Q*C | C | 06/18/2001 | 1 | UTMC | | Y | UT150*QCR | 368 |
| 5962R96B0215V*C | C | 06/18/2001 | 1 | UTMC | | Y | UT150*VCR | 368 |
| 5962R96B0216Q*C | C | 06/18/2001 | 1 | UTMC | | Y | UT200*QCR | 368 |
| 5962R96B0216V*C | C | 06/18/2001 | 1 | UTMC | | Y | UT200*VCR | 368 |
| 5962R96B0217Q*C | C | 06/18/2001 | 1 | UTMC | | Y | UT250*QCR | 368 |
| 5962R96B0217V*C | C | 06/18/2001 | 1 | UTMC | | Y | UT250*VCR | 368 |
| 5962R96B0218Q*C | C | 06/18/2001 | 1 | UTMC | | Y | UT300*QCR | 368 |
| 5962R96B0218V*C | C | 06/18/2001 | 1 | UTMC | | Y | UT300*VCR | 368 |
| 5962R96B0219Q*C | C | 06/18/2001 | 1 | UTMC | | Y | UT350*QCR | 368 |
| 5962R96B0219V*C | C | 06/18/2001 | 1 | UTMC | | Y | UT350*VCR | 368 |
| 5962R96B0220Q*C | C | 06/18/2001 | 1 | UTMC | | Y | UT400*QCR | 368 |
| 5962R96B0220V*C | C | 06/18/2001 | 1 | UTMC | | Y | UT400*VCR | 368 |
| 5962R96B0221Q*C | C | 06/18/2001 | 1 | UTMC | | Y | UT450*QCR | 368 |
| 5962R96B0221V*C | C | 06/18/2001 | 1 | UTMC | | Y | UT450*VCR | 368 |
| 5962R96B0222Q*C | C | 06/18/2001 | 1 | UTMC | | Y | UT500*QCR | 368 |
| 5962R96B0222V*C | C | 06/18/2001 | 1 | UTMC | | Y | UT500*VCR | 368 |
| 5962R96B0223Q*C | C | 06/18/2001 | 1 | UTMC | | Y | UT550*QCR | 368 |
| 5962R96B0223V*C | C | 06/18/2001 | 1 | UTMC | | Y | UT550*VCR | 368 |
| 5962R96B0224Q*C | C | 06/18/2001 | 1 | UTMC | | Y | UT600*QCR | 368 |
| 5962R96B0224V*C | C | 06/18/2001 | 1 | UTMC | | Y | UT600*VCR | 368 |
| 5962H96B0301V8C | G | 06/09/2004 | 1 | HONEYWELL (1) | | Y | HX2080 | 365 |
| 5962H96B0301QUC | G | 06/09/2004 | 1 | HONEYWELL (1) | | Y | HX2080 | 365 |
| 5962H96B0301VUC | G | 06/09/2004 | 1 | HONEYWELL (1) | | Y | HX2080 | 365 |
| 5962H96B0301QZC | G | 06/09/2004 | 1 | HONEYWELL (1) | | Y | HX2080 | 365 |
| 5962H96B0301VZC | G | 06/09/2004 | 1 | HONEYWELL (1) | | Y | HX2080 | 365 |
| 5962H96B0302Q4C | G | 06/09/2004 | 1 | HONEYWELL (1) | | Y | HX2160 | 365 |
| 5962H96B0302V4C | G | 06/09/2004 | 1 | HONEYWELL (1) | | Y | HX2160 | 365 |
| 5962H96B0302Q6C | G | 06/09/2004 | 1 | HONEYWELL (1) | | Y | HX2160 | 365 |
| 5962H96B0302V6C | G | 06/09/2004 | 1 | HONEYWELL (1) | | Y | HX2160 | 365 |
| 5962H96B0302QTC | G | 06/09/2004 | 1 | HONEYWELL (1) | | Y | HX2160 | 365 |
| 5962H96B0302VTC | G | 06/09/2004 | 1 | HONEYWELL (1) | | Y | HX2160 | 365 |
| 5962H96B0302QUC | G | 06/09/2004 | 1 | HONEYWELL (1) | | Y | HX2160 | 365 |
| 5962H96B0302VUC | G | 06/09/2004 | 1 | HONEYWELL (1) | | Y | HX2160 | 365 |
| 5962H96B0302QZC | G | 06/09/2004 | 1 | HONEYWELL (1) | | Y | HX2160 | 365 |
| 5962H96B0302VZC | G | 06/09/2004 | 1 | HONEYWELL (1) | | Y | HX2160 | 365 |
| 5962H96B0303Q6C | G | 06/09/2004 | 1 | HONEYWELL (1) | | Y | HX2300 | 365 |
| 5962H96B0303V6C | G | 06/09/2004 | 1 | HONEYWELL (1) | | Y | HX2300 | 365 |
| 5962H96B0303Q7C | G | 06/09/2004 | 1 | HONEYWELL (1) | | Y | HX2300 | 365 |
| 5962H96B0303V7C | G | 06/09/2004 | 1 | HONEYWELL (1) | | Y | HX2300 | 365 |
| 5962H96B0303QMC | G | 06/09/2004 | 1 | HONEYWELL (1) | | Y | HX2300 | 365 |
| 5962H96B0303VMC | G | 06/09/2004 | 1 | HONEYWELL (1) | | Y | HX2300 | 365 |
| 5962H96B0303QNC | G | 06/09/2004 | 1 | HONEYWELL (1) | | Y | HX2300 | 365 |
| 5962H96B0303VNC | G | 06/09/2004 | 1 | HONEYWELL (1) | | Y | HX2300 | 365 |
| 5962H96B0304Q5C | G | 06/09/2004 | 1 | HONEYWELL (1) | | Y | HX2400 | 365 |
| 5962H96B0304V5C | G | 06/09/2004 | 1 | HONEYWELL (1) | | Y | HX2400 | 365 |
| 5962H96B0304QTC | G | 06/09/2004 | 1 | HONEYWELL (1) | | Y | HX2400 | 365 |
| 5962H96B0304VTC | G | 06/09/2004 | 1 | HONEYWELL (1) | | Y | HX2400 | 365 |
| 5962H96B0305QXC | G | 06/09/2004 | 1 | HONEYWELL (1) | | Y | HX2040 | 365 |
| 5962H96B0305VXC | G | 06/09/2004 | 1 | HONEYWELL (1) | | Y | HX2040 | 365 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962H96B0306QUC | G | 06/09/2004 | 1 | HONEYWELL (1) | | Y | HX2080R | 365 |
| 5962H96B0306VUC | G | 06/09/2004 | 1 | HONEYWELL (1) | | Y | HX2080R | 365 |
| 5962H96B0306QZC | G | 06/09/2004 | 1 | HONEYWELL (1) | | Y | HX2080R | 365 |
| 5962H96B0306VZC | G | 06/09/2004 | 1 | HONEYWELL (1) | | Y | HX2080R | 365 |
| 5962H96B0307Q4C | G | 06/09/2004 | 1 | HONEYWELL (1) | | Y | HX2160R | 365 |
| 5962H96B0307V4C | G | 06/09/2004 | 1 | HONEYWELL (1) | | Y | HX2160R | 365 |
| 5962H96B0308Q6C | G | 06/09/2004 | 1 | HONEYWELL (1) | | Y | HX2300R | 365 |
| 5962H96B0308V6C | G | 06/09/2004 | 1 | HONEYWELL (1) | | Y | HX2300R | 365 |
| 5962H96B0308Q7C | G | 06/09/2004 | 1 | HONEYWELL (1) | | Y | HX2300R | 365 |
| 5962H96B0308V7C | G | 06/09/2004 | 1 | HONEYWELL (1) | | Y | HX2300R | 365 |
| 5962H96B0308QMC | G | 06/09/2004 | 1 | HONEYWELL (1) | | Y | HX2300R | 365 |
| 5962H96B0308VMC | G | 06/09/2004 | 1 | HONEYWELL (1) | | Y | HX2300R | 365 |
| 5962H96B0308QNC | G | 06/09/2004 | 1 | HONEYWELL (1) | | Y | HX2300R | 365 |
| 5962H96B0308VNC | G | 06/09/2004 | 1 | HONEYWELL (1) | | Y | HX2300R | 365 |
| 5962H96B0309Q5C | G | 06/09/2004 | 1 | HONEYWELL (1) | | Y | HX2400R | 365 |
| 5962H96B0309V5C | G | 06/09/2004 | 1 | HONEYWELL (1) | | Y | HX2400R | 365 |
| 5962H96B0309QTC | G | 06/09/2004 | 1 | HONEYWELL (1) | | Y | HX2400R | 365 |
| 5962H96B0309VTC | G | 06/09/2004 | 1 | HONEYWELL (1) | | Y | HX2400R | 365 |
| 5962H96B0310QXC | G | 06/09/2004 | 1 | HONEYWELL (1) | | Y | HX2040R | 365 |
| 5962H96B0310VXC | G | 06/09/2004 | 1 | HONEYWELL (1) | | Y | HX2040R | 365 |
| 5962-9750401MXA | | 01/15/1997 | | (NONE) | 04/01/2000 | | 43168-39 (GEN) | 399 |
| 5962-9750402MXA | | 01/15/1997 | | (NONE) | 04/01/2000 | | 43168-30 (GEN) | 399 |
| 5962-9750403MXA | | 01/15/1997 | | (NONE) | 04/01/2000 | | 43168-22 (GEN) | 399 |
| 5962-9750601HXC | C | 03/31/2003 | 1 | ANALOG (6) | | Y | AD14060BF/QML-4 | 432 |
| 5962-9750602HXC | C | 03/31/2003 | 1 | ANALOG (6) | | Y | AD14060TF/QML-4 | 432 |
| 5962-9750701HXC | A | 12/10/1998 | 1 | ANALOG (6) | | Y | AD14060LBF/QML-4 | 432 |
| 5962-9750702HXC | A | 12/10/1998 | 1 | ANALOG (6) | | Y | AD14060LTF/QML-4 | 432 |
| 5962-9750801Q2A | | 12/12/1996 | 1 | TI | | Y | SNJ54LS155AFK | 283 |
| 5962-9750801QEA | | 12/12/1996 | 1 | TI | | Y | SNJ54LS155AJ | 283 |
| 5962-9750801QFA | | 12/12/1996 | 1 | TI | | Y | SNJ54LS155AW | 283 |
| 5962-9750901Q2A | B | 02/13/2003 | 3 | TI | | Y | TLC7733MFKB | 789 |
| 5962-9750901QPA | B | 02/13/2003 | 3 | TI | | Y | TLC7733MJGB | 789 |
| 5962-9751001Q2A | B | 05/10/2002 | 2 | TI | | Y | TLV2432MFKB | 710 |
| 5962-9751001QHA | B | 05/10/2002 | 2 | TI | | Y | TLV2432MUB | 710 |
| 5962-9751001QPA | B | 05/10/2002 | 2 | TI | | Y | TLV2432MJGB | 710 |
| 5962-9751002Q2A | B | 05/10/2002 | 2 | TI | | Y | TLV2432AMFKB | 710 |
| 5962-9751002QHA | B | 05/10/2002 | 2 | TI | | Y | TLV2432AMUB | 710 |
| 5962-9751002QPA | B | 05/10/2002 | 2 | TI | | Y | TLV2432AMJGB | 710 |
| 5962-9751101Q2A | C | 05/09/2002 | 2 | TI | | Y | TLV2442MFKB | 710 |
| 5962-9751101QHA | C | 05/09/2002 | 2 | TI | | Y | TLV2442MUB | 710 |
| 5962-9751101QPA | C | 05/09/2002 | 2 | TI | | Y | TLV2442MJGB | 710 |
| 5962-9751102Q2A | C | 05/09/2002 | 2 | TI | | Y | TLV2442AMFKB | 710 |
| 5962-9751102QHA | C | 05/09/2002 | 2 | TI | | Y | TLV2442AMUB | 710 |
| 5962-9751102QPA | C | 05/09/2002 | 2 | TI | | Y | TLV2442AMJGB | 710 |
| 5962F9751201V9A | C | 01/16/2003 | 1 | INTERSIL | | Y | HS0-22620RH-Q | 730 |
| 5962F9751201VXC | C | 01/16/2003 | 1 | INTERSIL | | Y | HS9-22620RH-Q | 730 |
| 5962-9751301Q2A | C | 02/12/2003 | 3 | TI | | Y | TLC7705MFKB | 789 |
| 5962-9751301QHA | C | 02/12/2003 | 3 | TI | | Y | TLC7705MUB | 789 |
| 5962-9751301QPA | C | 02/12/2003 | 3 | TI | | Y | TLC7705MJGB | 789 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9751401Q2A | A | 05/10/2002 | 3 | TI | | Y | TLV2422MFKB | 739 |
| 5962-9751401QHA | A | 05/10/2002 | 3 | TI | | Y | TLV2422MUB | 739 |
| 5962-9751401QPA | A | 05/10/2002 | 3 | TI | | Y | TLV2422MJGB | 739 |
| 5962-9751402Q2A | A | 05/10/2002 | 3 | TI | | Y | TLV2422AMFKB | 739 |
| 5962-9751402QHA | A | 05/10/2002 | 3 | TI | | Y | TLV2422AMUB | 739 |
| 5962-9751402QPA | A | 05/10/2002 | 3 | TI | | Y | TLV2422AMJGB | 739 |
| 5962-9751601Q2A | A | 02/05/1997 | | (NONE) | 10/31/2002 | | 54S15 (GEN) | 113 |
| 5962-9751601QCA | A | 02/05/1997 | | (NONE) | 10/31/2002 | | 54S15 (GEN) | 113 |
| 5962-9751601QDA | A | 02/05/1997 | | (NONE) | 10/31/2002 | | 54S15 (GEN) | 113 |
| 5962H9751701QXC | | 05/30/1997 | | (NONE) | 06/30/1999 | | 6656 (GEN) | 650 |
| 5962H9751701VXC | | 05/30/1997 | | (NONE) | 06/30/1999 | | 6656 (GEN) | 650 |
| 5962H9751701QYC | | 05/30/1997 | | (NONE) | 06/30/1999 | | 6656 (GEN) | 650 |
| 5962H9751701VYC | | 05/30/1997 | | (NONE) | 06/30/1999 | | 6656 (GEN) | 650 |
| 5962H9751701QZC | | 05/30/1997 | | (NONE) | 06/30/1999 | | 6656 (GEN) | 650 |
| 5962H9751701VZC | | 05/30/1997 | | (NONE) | 06/30/1999 | | 6656 (GEN) | 650 |
| 5962H9751702QXC | | 05/30/1997 | | (NONE) | 06/30/1999 | | 6656 (GEN) | 650 |
| 5962H9751702VXC | | 05/30/1997 | | (NONE) | 06/30/1999 | | 6656 (GEN) | 650 |
| 5962H9751702QYC | | 05/30/1997 | | (NONE) | 06/30/1999 | | 6656 (GEN) | 650 |
| 5962H9751702VYC | | 05/30/1997 | | (NONE) | 06/30/1999 | | 6656 (GEN) | 650 |
| 5962H9751702QZC | | 05/30/1997 | | (NONE) | 06/30/1999 | | 6656 (GEN) | 650 |
| 5962H9751702VZC | | 05/30/1997 | | (NONE) | 06/30/1999 | | 6656 (GEN) | 650 |
| 5962-9751801MPA | A | 12/23/2002 | | (NONE) | 09/02/2003 | | CLC440A (GEN) | 702 |
| 5962-9751901MPA | A | 05/21/2002 | 1 | NATIONAL | | Y | CLC446AJ-QML | 702 |
| 5962-9752001MPA | A | 05/20/2002 | 1 | NATIONAL | | Y | CLC449AJ-QML | 739 |
| 5962-9752101MPA | A | 12/20/2002 | 1 | NATIONAL | | Y | CLC452AJ-QML | 752 |
| 5962-9752201QXC | A | 05/10/2002 | 3 | XILINX | | Y | XC4005E-4PG156B | 381 |
| 5962-9752201QYC | A | 05/10/2002 | 3 | XILINX | | Y | XC4005E-4B164B | 381 |
| 5962-9752201QZC | A | 05/10/2002 | 3 | XILINX | | Y | XC4005E-4B164B | 381 |
| 5962-9752301QXC | A | 05/10/2002 | 3 | XILINX | | Y | XC4010E-4PG191B | 431 |
| 5962-9752301QYC | A | 05/10/2002 | 3 | XILINX | | Y | XC4010E-4CB196B | 431 |
| 5962-9752301QZC | A | 05/10/2002 | 3 | XILINX | | Y | XC4010E-4CB196B | 431 |
| 5962-9752401QXC | A | 05/15/2002 | 3 | XILINX | | Y | XC4013E-4PG223B | 431 |
| 5962-9752401QYC | A | 05/15/2002 | 3 | XILINX | | Y | XC4013E-4CB228B | 431 |
| 5962-9752401QZC | A | 05/15/2002 | 3 | XILINX | | Y | XC4013E-4CB228B | 431 |
| 5962-9752501QXC | A | 05/17/2002 | 3 | XILINX | | Y | XC4025E-4PG299 | 669 |
| 5962-9752501QYC | A | 05/17/2002 | 3 | XILINX | | Y | XC4025E-4B228B | 669 |
| 5962-9752501QZC | A | 05/17/2002 | 3 | XILINX | | Y | XC4025E-4B228B | 669 |
| 5962-9752601Q2A | B | 04/05/2001 | 2 | TI | | Y | SNJ54LVC138AFK | 282 |
| 5962-9752601QEA | B | 04/05/2001 | 2 | TI | | Y | SNJ54LVC138AJ | 282 |
| 5962-9752601QFA | B | 04/05/2001 | 2 | TI | | Y | SNJ54LVC138AW | 282 |
| 5962-9752701Q3A | A | 01/08/2003 | 2 | TI | | Y | SNJ54CBTD3384FK | 399 |
| 5962-9752701QKA | A | 01/08/2003 | 2 | TI | | Y | SNJ54CBTD3384W | 399 |
| 5962-9752701QLA | A | 01/08/2003 | 2 | TI | | Y | SNJ54CBTD3384JT | 399 |
| 5962-9752801Q2A | | 03/27/1997 | 2 | TI | | Y | SNJ54AHC02FK | 120 |
| 5962-9752801QCA | | 03/27/1997 | 2 | TI | | Y | SNJ54AHC02J | 120 |
| 5962-9752801QDA | | 03/27/1997 | 2 | TI | | Y | SNJ54AHC02W | 120 |
| 5962-9752901NXB | | 04/17/1998 | | (NONE) | 06/01/2001 | | TSB12LV21 (GEN) | 590 |
| 5962-9753001QXA | | 04/20/1998 | | (NONE) | 06/01/2001 | | TSB12LV31 (GEN) | 899 |
| 5962-9753301Q2A | C | 08/19/2003 | 2 | TI | | Y | SNJ54LVC00AFK | 100 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9753301QCA | C | 08/19/2003 | 2 | TI | | Y | SNJ54LVC00AJ | 100 |
| 5962-9753301VCA | C | 08/19/2003 | 2 | TI | | Y | SNV54LVC00AJ | 100 |
| 5962-9753301QDA | C | 08/19/2003 | 2 | TI | | Y | SNJ54LVC00AW | 100 |
| 5962-9753301VDA | C | 08/19/2003 | 2 | TI | | Y | SNV54LVC00AW | 100 |
| 5962-9753401Q2A | B | 03/28/2001 | 2 | TI | | Y | SNJ54LVC08AFK | 110 |
| 5962-9753401QCA | B | 03/28/2001 | 2 | TI | | Y | SNJ54LVC08AJ | 110 |
| 5962-9753401QDA | B | 03/28/2001 | 2 | TI | | Y | SNJ54LVC08AW | 110 |
| 5962-9753501VGA | B | 04/29/2003 | 1 | ANALOG (5) | | Y | AD648SH/QMLV | 739 |
| 5962-9753501VPA | B | 04/29/2003 | 1 | ANALOG (5) | | Y | AD648SQ/QMLV | 739 |
| 5962-9753502VGA | B | 04/29/2003 | 1 | ANALOG (5) | | Y | AD648TH/QMLV | 739 |
| 5962-9753502VPA | B | 04/29/2003 | 1 | ANALOG (5) | | Y | AD648TQ/QMLV | 739 |
| 5962-9753601QXC | | 05/21/1997 | | (NONE) | 08/15/1999 | | 320MCM41 (GEN) | 409 |
| 5962-9753602QXC | | 05/21/1997 | | (NONE) | | | 320MCM41 (GEN) | 409 |
| 5962-9753701Q2A | A | 11/22/2002 | 2 | TI | | Y | TLC4502MFKB | 739 |
| 5962-9753701QHA | A | 11/22/2002 | 2 | TI | | Y | TLC4502MUB | 739 |
| 5962-9753701QPA | A | 11/22/2002 | 2 | TI | | Y | TLC4502MJGB | 739 |
| 5962-9753702Q2A | A | 11/22/2002 | 2 | TI | | Y | TLC4502AMFKB | 739 |
| 5962-9753702QHA | A | 11/22/2002 | 2 | TI | | Y | TLC4502AMUB | 739 |
| 5962-9753702QPA | A | 11/22/2002 | 2 | TI | | Y | TLC4502AMJGB | 739 |
| 5962-9754001QXA | A | 06/28/2002 | | (NONE) | 12/31/2001 | | 54CDC586 (GEN) | 803 |
| 5962-9754101Q2A | | 03/08/1997 | 1 | TI | | Y | SN54LS37FK | 500 |
| 5962-9754101QCA | | 03/08/1997 | 1 | TI | | Y | SN54LS37J | 500 |
| 5962-9754101QDA | | 03/08/1997 | 1 | TI | | Y | SN54LS37W | 500 |
| 5962-9754201Q2A | C | 07/14/2003 | 3 | TI | | Y | SNJ54LVCH244AFK | 529 |
| 5962-9754201QRA | C | 07/14/2003 | 3 | TI | | Y | SNJ54LVCH244AJ | 529 |
| 5962-9754201VRA | C | 07/14/2003 | 3 | TI | | Y | SNV54LVCH244AJ | 529 |
| 5962-9754201QSA | C | 07/14/2003 | 3 | TI | | Y | SNJ54LVCH244AW | 529 |
| 5962-9754301Q2A | C | 07/14/2003 | 3 | TI | | Y | SNJ54LVCH245AFK | 590 |
| 5962-9754301QRA | C | 07/14/2003 | 3 | TI | | Y | SNJ54LVCH245AJ | 590 |
| 5962-9754301VRA | C | 07/14/2003 | 3 | TI | | Y | SNV54LVCH245AJ | 590 |
| 5962-9754301QSA | C | 07/14/2003 | 3 | TI | | Y | SNJ54LVCH245AW | 590 |
| 5962-9754301VSA | C | 07/14/2003 | 3 | TI | | Y | SNV54LVCH245AW | 590 |
| 5962-9754301VSA | C | 07/14/2003 | 3 | TI | | Y | SNV54LVCH245AW | 590 |
| 5962-9754302Q2A | C | 07/14/2003 | | (NONE) | 03/04/2003 | | 54LCX245 (GEN) | 590 |
| 5962-9754302QRA | C | 07/14/2003 | | (NONE) | 03/04/2003 | | 54LCX245 (GEN) | 590 |
| 5962-9754302QSA | C | 07/14/2003 | | (NONE) | 03/04/2003 | | 54LCX245 (GEN) | 590 |
| 5962H9754401QZC | | 10/16/1997 | | (NONE) | 06/30/1999 | | 6664 (GEN) | 657 |
| 5962H9754401VZC | | 10/16/1997 | | (NONE) | 06/30/1999 | | 6664 (GEN) | 657 |
| 5962H9754402QZC | | 10/16/1997 | | (NONE) | 06/30/1999 | | 6664 (GEN) | 657 |
| 5962H9754402VZC | | 10/16/1997 | | (NONE) | 06/30/1999 | | 6664 (GEN) | 657 |
| 5962-9754501QXA | D | 04/02/2002 | 2 | AUSTIN SEMI. | | Y | SMJ626162-15HKDM | 629 |
| 5962-9754501NYB | D | 04/02/2002 | | (NONE) | 08/15/1998 | | SMJ626162-15 (GEN) | 629 |
| 5962-9754502QXA | D | 04/02/2002 | 2 | AUSTIN SEMI. | | Y | SMJ626162-20HKDM | 629 |
| 5962-9754502NYB | D | 04/02/2002 | | (NONE) | 08/15/1998 | | SMJ626162-20 (GEN) | 629 |
| 5962-9754503QXA | D | 04/02/2002 | 2 | AUSTIN SEMI. | | Y | SMJ626162-12HKDM | 629 |
| 5962-9754503NYB | D | 04/02/2002 | | (NONE) | 08/15/1998 | | SMJ626162-12 (GEN) | 629 |
| 5962-9754701Q2A | | 03/14/1997 | 1 | TI | | Y | SNJ54LS85FK | 209 |
| 5962-9754701QEA | | 03/14/1997 | 1 | TI | | Y | SNJ54LS85J | 209 |
| 5962-9754701QFA | | 03/14/1997 | 1 | TI | | Y | SNJ54LS85W | 209 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9754801QEA | | 05/30/1997 | 1 | TI | | Y | SNJ54163J | 304 |
| 5962-9754801QFA | | 05/30/1997 | 1 | TI | | Y | SNJ54163W | 304 |
| 5962-9754901Q3A | | 03/21/1997 | | (NONE) | 12/31/2001 | | 54AS575 (GEN) | 159 |
| 5962-9754901QKA | | 03/21/1997 | 1 | TI | | Y | SNJ54AS575W | 159 |
| 5962-9754901QLA | | 03/21/1997 | | (NONE) | 12/31/2001 | | 54AS575 (GEN) | 159 |
| 5962-9755001QXA | A | 02/06/2003 | 2 | TI | | Y | TLC16C552AMHVB | 599 |
| 5962-9755301QCA | | 05/30/1997 | 0 | TI | | Y | SNJ54121J | 165 |
| 5962-9755301QDA | | 05/30/1997 | 0 | TI | | Y | SNJ54121W | 165 |
| 5962-9755701HPA | A | 09/06/2002 | 1 | AGILENT | | Y | HCPL-7851#200 | 460 |
| 5962-9755701HPC | A | 09/06/2002 | 1 | AGILENT | | Y | HCPL-7851 | 460 |
| 5962-9755701HXA | A | 09/06/2002 | 1 | AGILENT | | Y | HCPL-7851#300 | 460 |
| 5962-9755701HYA | A | 09/06/2002 | 1 | AGILENT | | Y | HCPL-7851#100 | 460 |
| 5962-9755701HYC | A | 09/06/2002 | 1 | AGILENT | | Y | HCPL-7851#100 | 460 |
| 5962-9755801Q2A | | 04/04/1997 | 1 | TI | | Y | SNJ54AS30FK | 106 |
| 5962-9755801QCA | | 04/04/1997 | 1 | TI | | Y | SNJ54AS30J | 106 |
| 5962-9755901Q2A | | 07/30/1997 | 2 | TI | | Y | SNJ54AS244AFK | 529 |
| 5962-9755901QRA | | 07/30/1997 | 2 | TI | | Y | SNJ54AS244AJ | 529 |
| 5962-9755901QSA | | 07/30/1997 | 2 | TI | | Y | SNJ54AS244AW | 529 |
| 5962-9756001Q2A | | 05/30/1997 | 2 | TI | | Y | SNJ54AS32FK | 142 |
| 5962-9756001QCA | | 05/30/1997 | 2 | TI | | Y | SNJ54AS32J | 142 |
| 5962-9756101Q2A | | 05/30/1997 | 2 | TI | | Y | SNJ54AS11FK | 111 |
| 5962-9756101QCA | | 05/30/1997 | 2 | TI | | Y | SNJ54AS11J | 111 |
| 5962-9756201Q2A | | 03/28/1997 | 2 | TI | | Y | SNJ54AS374FK | 159 |
| 5962-9756201QRA | | 03/28/1997 | 2 | TI | | Y | SNJ54AS374J | 159 |
| 5962-9756201QSA | | 03/28/1997 | 2 | TI | | Y | SNJ54AS374W | 159 |
| 5962-9756301HXC | A | 04/15/1998 | | (NONE) | 04/14/2001 | | AD9070T (GEN) | 592 |
| 5962-9756401QXA | B | 01/10/2003 | 1 | ANALOG (2) | | Y | AD976ASD | 592 |
| 5962-9757101Q2A | | 06/13/1997 | 2 | TI | | Y | SNJ54AHCT02FK | 120 |
| 5962-9757101QCA | | 06/13/1997 | 2 | TI | | Y | SNJ54AHCT02J | 120 |
| 5962-9757101QDA | | 06/13/1997 | 2 | TI | | Y | SNJ54AHCT02W | 120 |
| 5962-9757201Q2A | | 04/18/1997 | 3 | TI | | Y | SNJ54AS86AFK | 140 |
| 5962-9757201QCA | | 04/18/1997 | 3 | TI | | Y | SNJ54AS86AJ | 140 |
| 5962-9757301Q2A | B | 04/08/2003 | 2 | TI | | Y | SNJ54LVC373AFK | 159 |
| 5962-9757301QRA | B | 04/08/2003 | 2 | TI | | Y | SNJ54LVC373AJ | 159 |
| 5962-9757301QSA | B | 04/08/2003 | 2 | TI | | Y | SNJ54LVC373AW | 159 |
| 5962-9757401Q2A | C | 07/14/2003 | 2 | TI | | Y | SNJ54LVC374AFK | 159 |
| 5962-9757401QRA | C | 07/14/2003 | 2 | TI | | Y | SNJ54LVC374AJ | 159 |
| 5962-9757401VRA | C | 07/14/2003 | 2 | TI | | Y | SNV54LVC374AJ | 159 |
| 5962-9757401QSA | C | 07/14/2003 | 2 | TI | | Y | SNJ54LVC374AW | 159 |
| 5962-9757401VSA | C | 07/14/2003 | 2 | TI | | Y | SNV54LVC374AW | 159 |
| 5962-9757501Q2A | B | 04/21/2003 | 2 | TI | | Y | SNJ54LVC573AFK | 159 |
| 5962-9757501QRA | B | 04/21/2003 | 2 | TI | | Y | SNJ54LVC573AJ | 159 |
| 5962-9757501QSA | B | 04/21/2003 | 2 | TI | | Y | SNJ54LVC573AW | 159 |
| 5962-9757601Q2A | B | 04/21/2003 | 3 | TI | | Y | SNJ54LVC574AFK | 159 |
| 5962-9757601QRA | B | 04/21/2003 | 3 | TI | | Y | SNJ54LVC574AJ | 159 |
| 5962-9757601QSA | B | 04/21/2003 | 3 | TI | | Y | SNJ54LVC574AW | 159 |
| 5962-9757701Q2A | | 04/23/1997 | 2 | TI | | Y | SNJ54F00FK | 100 |
| 5962-9757701QCA | | 04/23/1997 | 2 | TI | | Y | SNJ54F00J | 100 |
| 5962-9757701QDA | | 04/23/1997 | 2 | TI | | Y | SNJ54F00W | 100 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9757801Q2A | | 05/15/1997 | 0 | TI | | Y | SNJ54F02FK | 120 |
| 5962-9757801QCA | | 05/15/1997 | 0 | TI | | Y | SNJ54F02J | 120 |
| 5962-9757801QDA | | 05/15/1997 | 0 | TI | | Y | SNJ54F02W | 120 |
| 5962-9757901Q2A | | 08/14/1997 | 2 | TI | | Y | SNJ54F10FK | 102 |
| 5962-9757901QCA | | 08/14/1997 | 2 | TI | | Y | SNJ54F10J | 102 |
| 5962-9757901QDA | | 08/14/1997 | 2 | TI | | Y | SNJ54F10W | 102 |
| 5962-9758001Q2A | | 06/19/1997 | 2 | TI | | Y | SNJ54F109FK | 152 |
| 5962-9758001QEA | | 06/19/1997 | 2 | TI | | Y | SNJ54F109J | 152 |
| 5962-9758001QFA | | 06/19/1997 | 2 | TI | | Y | SNJ54F109W | 152 |
| 5962-9758101Q2A | | 05/15/1997 | 2 | TI | | Y | SNJ54F11FK | 110 |
| 5962-9758101QCA | | 05/15/1997 | 2 | TI | | Y | SNJ54F11J | 110 |
| 5962-9758101QDA | | 05/15/1997 | 2 | TI | | Y | SNJ54F11W | 110 |
| 5962-9758201Q2A | A | 07/18/1997 | 3 | NATIONAL | | Y | 54F138LMQB | 282 |
| 5962-9758201Q2A | A | 07/18/1997 | 2 | TI | | Y | SNJ54F138FK | 282 |
| 5962-9758201QEA | A | 07/18/1997 | 3 | NATIONAL | | Y | 54F138DMQB | 282 |
| 5962-9758201QEA | A | 07/18/1997 | 2 | TI | | Y | SNJ54F138J | 282 |
| 5962-9758201QFA | A | 07/18/1997 | 3 | NATIONAL | | Y | 54F138FMQB | 282 |
| 5962-9758201QFA | A | 07/18/1997 | 2 | TI | | Y | SNJ54F138W | 282 |
| 5962-9758301Q2A | A | 07/18/1997 | 3 | NATIONAL | | Y | 54F153LMQB | 273 |
| 5962-9758301Q2A | A | 07/18/1997 | 2 | TI | | Y | SNJ54F153FK | 273 |
| 5962-9758301QEA | A | 07/18/1997 | 3 | NATIONAL | | Y | 54F153DMQB | 273 |
| 5962-9758301QEA | A | 07/18/1997 | 2 | TI | | Y | SNJ54F153J | 273 |
| 5962-9758301QFA | A | 07/18/1997 | 3 | NATIONAL | | Y | 54F153FMQB | 273 |
| 5962-9758301QFA | A | 07/18/1997 | 2 | TI | | Y | SNJ54F153W | 273 |
| 5962-9758401Q2A | A | 07/18/1997 | 1 | NATIONAL | | Y | 54F20LMQB | 104 |
| 5962-9758401Q2A | A | 07/18/1997 | 1 | TI | | Y | SNJ54F20FK | 104 |
| 5962-9758401QCA | A | 07/18/1997 | 1 | NATIONAL | | Y | 54F20DMQB | 104 |
| 5962-9758401QCA | A | 07/18/1997 | 1 | TI | | Y | SNJ54F20J | 104 |
| 5962-9758401QDA | A | 07/18/1997 | 1 | NATIONAL | | Y | 54F20FMQB | 104 |
| 5962-9758401QDA | A | 07/18/1997 | 1 | TI | | Y | SNJ54F20W | 104 |
| 5962-9758501Q2A | | 04/30/1997 | 2 | TI | | Y | SNJ54F240FK | 529 |
| 5962-9758501QRA | | 04/30/1997 | 2 | TI | | Y | SNJ54F240J | 529 |
| 5962-9758501QSA | | 04/30/1997 | 2 | TI | | Y | SNJ54F240W | 529 |
| 5962-9758601Q2A | | 04/30/1997 | 2 | TI | | Y | SNJ54F244FK | 529 |
| 5962-9758601QRA | | 04/30/1997 | 2 | TI | | Y | SNJ54F244J | 529 |
| 5962-9758601QSA | | 04/30/1997 | 2 | TI | | Y | SNJ54F244W | 529 |
| 5962-9758701Q2A | | 05/08/1997 | 2 | TI | | Y | SNJ54F283FK | 202 |
| 5962-9758701QEA | | 05/08/1997 | 2 | TI | | Y | SNJ54F283J | 202 |
| 5962-9758701QFA | | 05/08/1997 | 2 | TI | | Y | SNJ54F283W | 202 |
| 5962-9758801Q2A | | 07/07/1997 | 2 | TI | | Y | SNJ54F32FK | 125 |
| 5962-9758801QCA | | 07/07/1997 | 2 | TI | | Y | SNJ54F32J | 125 |
| 5962-9758801QDA | | 07/07/1997 | 2 | TI | | Y | SNJ54F32W | 125 |
| 5962-9758901Q2A | | 06/24/1997 | 3 | TI | | Y | SNJ54F373FK | 341 |
| 5962-9758901QRA | | 06/24/1997 | 3 | TI | | Y | SNJ54F373J | 341 |
| 5962-9758901QSA | | 06/24/1997 | 3 | TI | | Y | SNJ54F373W | 341 |
| 5962-9759001Q2A | | 06/19/1997 | 2 | TI | | Y | SNJ54F374FK | 159 |
| 5962-9759001QRA | | 06/19/1997 | 2 | TI | | Y | SNJ54F374J | 159 |
| 5962-9759001QSA | | 06/19/1997 | 2 | TI | | Y | SNJ54F374W | 159 |
| 5962-9759101Q2A | | 05/15/1997 | 2 | TI | | Y | SNJ54F521FK | 209 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9759101QRA | | 05/15/1997 | 2 | TI | | Y | SNJ54F521J | 209 |
| 5962-9759101QSA | | 05/15/1997 | 2 | TI | | Y | SNJ54F521W | 209 |
| 5962-9759201Q2A | | 05/30/1997 | 3 | TI | | Y | SNJ54F74FK | 158 |
| 5962-9759201QCA | | 05/30/1997 | 3 | TI | | Y | SNJ54F74J | 158 |
| 5962-9759201QDA | | 05/30/1997 | 3 | TI | | Y | SNJ54F74W | 158 |
| 5962-9759301Q2A | A | 07/18/1997 | 3 | NATIONAL | | Y | 54F04LMQB | 143 |
| 5962-9759301Q2A | A | 07/18/1997 | 2 | TI | | Y | SNJ54F04FK | 143 |
| 5962-9759301QCA | A | 07/18/1997 | 3 | NATIONAL | | Y | 54F04DMQB | 143 |
| 5962-9759301QCA | A | 07/18/1997 | 2 | TI | | Y | SNJ54F04J | 143 |
| 5962-9759301QDA | A | 07/18/1997 | 3 | NATIONAL | | Y | 54F04FMQB | 143 |
| 5962-9759301QDA | A | 07/18/1997 | 2 | TI | | Y | SNJ54F04W | 143 |
| 5962-9759401Q2A | B | 05/23/2003 | 3 | TI | | Y | SNJ54LVC540AFK | 529 |
| 5962-9759401QRA | B | 05/23/2003 | 3 | TI | | Y | SNJ54LVC540AJ | 529 |
| 5962-9759401QSA | B | 05/23/2003 | 3 | TI | | Y | SNJ54LVC540AW | 529 |
| 5962-9759501Q2A | B | 03/17/2003 | 2 | TI | | Y | SNJ54LVC541AFK | 529 |
| 5962-9759501QRA | B | 03/17/2003 | 2 | TI | | Y | SNJ54LVC541AJ | 529 |
| 5962-9759501QSA | B | 03/17/2003 | 2 | TI | | Y | SNJ54LVC541AW | 529 |
| 5962-9759701QXA | A | 05/20/2002 | | (NONE) | 08/05/2002 | | 7C372I-66 (GEN) | 380 |
| 5962-9759702QXA | A | 05/20/2002 | | (NONE) | | | 7C372I-83 (GEN) | 380 |
| 5962-9759801QXC | A | 05/22/2002 | | (NONE) | 08/05/2002 | | 7C374I-66 (GEN) | 380 |
| 5962-9759801QYA | A | 05/22/2002 | 2 | CYPRESS | 05/03/2004 | Y | CY7C374I-66YMB | 380 |
| 5962-9759802QXC | A | 05/22/2002 | 2 | CYPRESS | 05/03/2004 | Y | CY7C374I-83GMB | 380 |
| 5962-9759802QYA | A | 05/22/2002 | 2 | CYPRESS | 05/03/2004 | Y | CY7C374I-83YMB | 380 |
| 5962-9759901QXC | A | 05/22/2002 | | (NONE) | 11/05/2001 | | 7C375I-66 (GEN) | 380 |
| 5962-9759901QYC | A | 05/22/2002 | | (NONE) | 05/30/1999 | | 7C375I-66 (GEN) | 380 |
| 5962-9759901QZC | A | 05/22/2002 | 3 | CYPRESS | 05/03/2004 | Y | CY7C375I-66UMB | 380 |
| 5962-9759902QXC | A | 05/22/2002 | 3 | CYPRESS | 05/03/2004 | Y | CY7C375I-83GMB | 380 |
| 5962-9759902QYC | A | 05/22/2002 | | (NONE) | 05/30/1999 | | 7C375I-83 (GEN) | 380 |
| 5962-9759902QZC | A | 05/22/2002 | 3 | CYPRESS | 05/03/2004 | Y | CY7C375I-83UMB | 380 |
| 5962-9760101HXC | A | 11/13/1998 | | (NONE) | | | ADDC02803SC (GEN) | 899 |
| 5962-9760201HXC | A | 11/19/1998 | | (NONE) | | | ADDC02809SA (GEN) | 594 |
| 5962-9760301Q2A | A | 01/10/2003 | 1 | TI | | Y | MC1558FKB | 739 |
| 5962-9760301QPA | A | 01/10/2003 | 1 | TI | | Y | MC1558JGB | 739 |
| 5962-9760401Q2A | A | 08/16/2000 | 2 | TI | | Y | SNJ54LVC02AFK | 120 |
| 5962-9760401QCA | A | 08/16/2000 | 2 | TI | | Y | SNJ54LVC02AJ | 120 |
| 5962-9760401QDA | A | 08/16/2000 | 2 | TI | | Y | SNJ54LVC02AW | 120 |
| 5962-9760501Q2A | A | 08/16/2000 | 2 | TI | | Y | SNJ54LVC04AFK | 143 |
| 5962-9760501QCA | A | 08/16/2000 | 2 | TI | | Y | SNJ54LVC04AJ | 143 |
| 5962-9760501QDA | A | 08/16/2000 | 2 | TI | | Y | SNJ54LVC04AW | 143 |
| 5962-9760601Q9A | E | 02/26/2002 | | (NONE) | | | 320LC31 (GEN) | 432 |
| 5962-9760601NXB | E | 02/26/2002 | 2 | TI | | Y | SMQ320LC31PQM40 | 432 |
| 5962-9760701MXA | | 07/01/1998 | 1 | ATMEL GREN. | | Y | TS68EN360MR1B/C25 | 420 |
| 5962-9760701MXC | | 07/01/1998 | 1 | ATMEL GREN. | | Y | TS68EN360MRB/C25 | 420 |
| 5962-9760701MYA | | 07/01/1998 | 1 | ATMEL GREN. | | Y | TS68EN360MAB/C25 | 420 |
| 5962-9760702MXA | | 07/01/1998 | 1 | ATMEL GREN. | | Y | TS68EN360MR1B/C33 | 420 |
| 5962-9760702MXC | | 07/01/1998 | 1 | ATMEL GREN. | | Y | TS68EN360MRB/C33 | 420 |
| 5962-9760702MYA | | 07/01/1998 | 1 | ATMEL GREN. | | Y | TS68EN360MAB/C33 | 420 |
| 5962-9760801QXA | A | 06/13/2000 | | (NONE) | 04/30/2001 | | TSPC603EMAB/C2L | 404 |
| 5962-9760802QXA | A | 06/13/2000 | | (NONE) | 04/30/2001 | | TSPC603EMAB/C3L | 404 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9760803QXA | A | 06/13/2000 | | (NONE) | 04/30/2001 | | TSPC603EMAB/C4L | 404 |
| 5962-9760804QXA | A | 06/13/2000 | | (NONE) | 04/30/2001 | | TSPC603EMAB/C5L | 404 |
| 5962-9760805QYA | A | 06/13/2000 | 1 | ATMEL GREN. | | Y | TSPC603RMGSB/Q6LC | 404 |
| 5962-9760806QYA | A | 06/13/2000 | 1 | ATMEL GREN. | | Y | TSPC603RMGSB/Q8LC | 404 |
| 5962-9760807QYA | A | 06/13/2000 | 1 | ATMEL GREN. | | Y | TSPC603RMGSB/Q10L | 404 |
| 5962-9760808QYA | A | 06/13/2000 | 1 | ATMEL GREN. | | Y | TSPC603RMGSB/Q12L | 404 |
| 5962-9760809QYA | A | 06/13/2000 | 1 | ATMEL GREN. | | Y | TSPC603RMGSB/Q14L | 404 |
| 5962-9760901HXA | A | 12/16/2003 | 1 | WHITE ELEC. | | Y | WMF2M8-150DAQ5 | 669 |
| 5962-9760901HXC | A | 12/16/2003 | 1 | WHITE ELEC. | | Y | WMF2M8-150DAQ5 | 669 |
| 5962-9760902HXA | A | 12/16/2003 | 1 | WHITE ELEC. | | Y | WMF2M8-120DAQ5 | 669 |
| 5962-9760902HXC | A | 12/16/2003 | 1 | WHITE ELEC. | | Y | WMF2M8-120DAQ5 | 669 |
| 5962-9760903HXA | A | 12/16/2003 | 1 | WHITE ELEC. | | Y | WMF2M8-90DAQ5 | 669 |
| 5962-9760903HXC | A | 12/16/2003 | 1 | WHITE ELEC. | | Y | WMF2M8-90DAQ5 | 669 |
| 5962-9760904HXA | A | 12/16/2003 | 1 | WHITE ELEC. | | Y | WMF2M8-150DAQE5 | 669 |
| 5962-9760904HXC | A | 12/16/2003 | 1 | WHITE ELEC. | | Y | WMF2M8-150DAQE5 | 669 |
| 5962-9760905HXA | A | 12/16/2003 | 1 | WHITE ELEC. | | Y | WMF2M8-120DAQE5 | 669 |
| 5962-9760905HXC | A | 12/16/2003 | 1 | WHITE ELEC. | | Y | WMF2M8-120DAQE5 | 669 |
| 5962-9760906HXA | A | 12/16/2003 | 1 | WHITE ELEC. | | Y | WMF2M8-90DAQE5 | 669 |
| 5962-9760906HXC | A | 12/16/2003 | 1 | WHITE ELEC. | | Y | WMF2M8-90DAQE5 | 669 |
| 5962-9761001HXA | B | 06/23/2004 | 1 | WHITE ELEC. | | Y | WF2M16-150DAQ5 | 699 |
| 5962-9761001HXC | B | 06/23/2004 | 1 | WHITE ELEC. | | Y | WF2M16-150DAQ5 | 699 |
| 5962-9761002HXA | B | 06/23/2004 | 1 | WHITE ELEC. | | Y | WF2M16-120DAQ5 | 699 |
| 5962-9761002HXC | B | 06/23/2004 | 1 | WHITE ELEC. | | Y | WF2M16-120DAQ5 | 699 |
| 5962-9761003HXA | B | 06/23/2004 | 1 | WHITE ELEC. | | Y | WF2M16-90DAQ5 | 699 |
| 5962-9761003HXC | B | 06/23/2004 | 1 | WHITE ELEC. | | Y | WF2M16-90DAQ5 | 699 |
| 5962-9761004HXA | B | 06/23/2004 | 1 | WHITE ELEC. | | Y | WF2M16-150DAQE5 | 699 |
| 5962-9761004HXC | B | 06/23/2004 | 1 | WHITE ELEC. | | Y | WF2M16-150DAQE5 | 699 |
| 5962-9761005HXA | B | 06/23/2004 | 1 | WHITE ELEC. | | Y | WF2M16-120DAQE5 | 699 |
| 5962-9761005HXC | B | 06/23/2004 | 1 | WHITE ELEC. | | Y | WF2M16-120DAQE5 | 699 |
| 5962-9761006HXA | B | 06/23/2004 | 1 | WHITE ELEC. | | Y | WF2M16-90DAQE5 | 699 |
| 5962-9761006HXC | B | 06/23/2004 | 1 | WHITE ELEC. | | Y | WF2M16-90DAQE5 | 699 |
| 5962-9761501Q2A | C | 07/01/2003 | 2 | TI | | Y | SNJ54LVC14AFK | 143 |
| 5962-9761501QCA | C | 07/01/2003 | 2 | TI | | Y | SNJ54LVC14AJ | 143 |
| 5962-9761501VCA | C | 07/01/2003 | 2 | TI | | Y | SNV54LVC14AJ | 143 |
| 5962-9761501QDA | C | 07/01/2003 | 2 | TI | | Y | SNJ54LVC14AW | 143 |
| 5962-9761501VDA | C | 07/01/2003 | 2 | TI | | Y | SNV54LVC14AW | 143 |
| 5962-9761601Q2A | B | 08/19/2003 | 2 | TI | | Y | SNJ54LVC74AFK | 158 |
| 5962-9761601QCA | B | 08/19/2003 | 2 | TI | | Y | SNJ54LVC74AJ | 158 |
| 5962-9761601VCA | B | 08/19/2003 | 2 | TI | | Y | SNV54LVC74AJ | 158 |
| 5962-9761601QDA | B | 08/19/2003 | 2 | TI | | Y | SNJ54LVC74AW | 158 |
| 5962-9761601VDA | B | 08/19/2003 | 2 | TI | | Y | SNV54LVC74AW | 158 |
| 5962-9761801Q2A | B | 04/05/2001 | 2 | TI | | Y | SNJ54LVC32AFK | 120 |
| 5962-9761801QCA | B | 04/05/2001 | 2 | TI | | Y | SNJ54LVC32AJ | 120 |
| 5962-9761801QDA | B | 04/05/2001 | 2 | TI | | Y | SNJ54LVC32AW | 120 |
| 5962-9761901Q2A | B | 04/05/2001 | 2 | TI | | Y | SNJ54LVC86AFK | 140 |
| 5962-9761901QCA | B | 04/05/2001 | 2 | TI | | Y | SNJ54LVC86AJ | 140 |
| 5962-9761901QDA | B | 04/05/2001 | 2 | TI | | Y | SNJ54LVC86AW | 140 |
| 5962-9762001Q2A | | 01/06/1998 | | (NONE) | 12/24/2000 | | HI-1828A (GEN) | 192 |
| 5962-9762001QEA | | 01/06/1998 | | (NONE) | 12/24/2000 | | HI-1828A (GEN) | 192 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9762101Q2A | A | 01/24/2003 | 3 | TI | | Y | SNJ55LVDS31FK | 569 |
| 5962-9762101QEA | A | 01/24/2003 | 3 | TI | | Y | SNJ55LVDS31J | 569 |
| 5962-9762101QFA | A | 01/24/2003 | 3 | TI | | Y | SNJ55LVDS31W | 569 |
| 5962-9762101VFA | A | 01/24/2003 | 3 | TI | | Y | SNV55LVDS31W | 569 |
| 5962-9762201Q2A | B | 12/30/2002 | 3 | TI | | Y | SNJ55LVDS32FK | 579 |
| 5962-9762201QEA | B | 12/30/2002 | 3 | TI | | Y | SNJ55LVDS32J | 579 |
| 5962-9762201QFA | B | 12/30/2002 | 3 | TI | | Y | SNJ55LVDS32W | 579 |
| 5962-9762201VFA | B | 12/30/2002 | 3 | TI | | Y | SNV55LVDS32W | 579 |
| 5962-9762202Q2A | B | 12/30/2002 | 3 | TI | | Y | SNJ55LVDS32FK | 579 |
| 5962-9762301Q2A | | 09/29/1999 | 1 | TI | | Y | SNJ54ABTH245FK | 590 |
| 5962-9762301QRA | | 09/29/1999 | 1 | TI | | Y | SNJ54ABTH245J | 590 |
| 5962-9762301QSA | | 09/29/1999 | 1 | TI | | Y | SNJ54ABTH245W | 590 |
| 5962-9762401QXA | A | 09/20/2001 | 3 | TI | | Y | SNJ54ABTH16244WD | 529 |
| 5962-9762501QXA | A | 01/19/2000 | 2 | TI | | Y | SNJ54ABTH16245WD | 590 |
| 5962-9762601Q3A | A | 12/23/2002 | 2 | TI | | Y | SNJ54LVC646AFK | 599 |
| 5962-9762601QKA | A | 12/23/2002 | 2 | TI | | Y | SNJ54LVC646AW | 599 |
| 5962-9762601QLA | A | 12/23/2002 | 2 | TI | | Y | SNJ54LVC646AJT | 599 |
| 5962-9762701Q3A | A | 01/22/2003 | 2 | TI | | Y | SNL54LVC652AFK | 599 |
| 5962-9762701QKA | A | 01/22/2003 | 2 | TI | | Y | SNL54LVC652AW | 599 |
| 5962-9762701QLA | A | 01/22/2003 | 2 | TI | | Y | SNL54LVC652AJT | 599 |
| 5962-9762801HXA | A | 03/03/2003 | | (NONE) | | | SA 50M (GEN) | 787 |
| 5962-9762802HXA | A | 03/03/2003 | 1 | MS KENNEDY | | Y | MSK 4200B | 787 |
| 5962-9762802HXC | A | 03/03/2003 | 1 | MS KENNEDY | | Y | MSK 4200B | 787 |
| 5962-9762901HXA | A | 02/28/2003 | | (NONE) | | | SA 51M (GEN) | 787 |
| 5962-9762902HXA | A | 02/28/2003 | 1 | MS KENNEDY | | Y | MSK 4201B | 787 |
| 5962-9762902HXC | A | 02/28/2003 | 1 | MS KENNEDY | | Y | MSK 4201B | 787 |
| 5962-9763001QPA | A | 01/07/2003 | 3 | TI | | Y | UC1852J/883B | 789 |
| 5962-9763101QXA | | 09/11/1998 | | (NONE) | 11/03/2003 | | 7C4271-15 (GEN) | 670 |
| 5962-9763201Q2A | | 08/22/1997 | | (NONE) | 06/01/2001 | | 54ALS352 (GEN) | 273 |
| 5962-9763201QEA | | 08/22/1997 | | (NONE) | 06/01/2001 | | 54ALS352 (GEN) | 273 |
| 5962-9763301QGA | A | 07/11/2001 | 1 | NATIONAL | | Y | LF442MH/883 | 739 |
| 5962-9763401HXC | | 08/25/1998 | | (NONE) | | | ADDC02808PB (GEN) | 594 |
| 5962-9763601QEA | | 09/22/1997 | 2 | TI | | Y | SNJ5423J | 123 |
| 5962-9763701VGA | A | 04/04/2003 | 1 | ANALOG (5) | | Y | OP43AJ/QMLV | 723 |
| 5962-9763801QXA | B | 04/30/2003 | 3 | TI | | Y | SNJ54LVTH162373WD | 158 |
| 5962-9763801VXA | B | 04/30/2003 | 3 | TI | | Y | SNV54LVTH162373WD | 158 |
| 5962F9763901V9A | A | 03/10/1999 | | (NONE) | | | ACS139 (GEN) | 283 |
| 5962F9763901VEC | A | 03/10/1999 | | (NONE) | | | ACS139 (GEN) | 283 |
| 5962F9763901VXC | A | 03/10/1999 | | (NONE) | | | ACS139 (GEN) | 283 |
| 5962F9764001V9A | B | 04/05/1999 | | (NONE) | | | ACS151 (GEN) | 271 |
| 5962F9764001VEA | B | 04/05/1999 | | (NONE) | | | ACS151 (GEN) | 271 |
| 5962F9764001VFA | B | 04/05/1999 | | (NONE) | | | ACS151 (GEN) | 271 |
| 5962F9764101VEC | A | 09/10/1998 | | (NONE) | 06/22/2003 | | HS-6254RH (GEN) | 790 |
| 5962F9764101VXC | A | 09/10/1998 | 1 | INTERSIL | | Y | HS9-6254RH-Q | 790 |
| 5962-9764201Q2A | | 03/12/1998 | 2 | TI | | Y | SNJ54AHC157FK | 275 |
| 5962-9764201QEA | | 03/12/1998 | 2 | TI | | Y | SNJ54AHC157J | 275 |
| 5962-9764201QFA | | 03/12/1998 | 2 | TI | | Y | SNJ54AHC157W | 275 |
| 5962-97A0101V9A | G | 10/17/2001 | 1 | INTERSIL | | Y | HAA0-51150R4551 | 365 |
| 5962-97A0101VXC | G | 10/17/2001 | 1 | INTERSIL | | Y | HAA9-51150R4551 | 365 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-97A0201V9A | E | 10/01/2001 | 1 | INTERSIL | | Y | HS0-SW06RH-Q | 365 |
| 5962-97A0201VXC | E | 10/01/2001 | 1 | INTERSIL | | Y | HS9-SW06RH-Q | 365 |
| 5962-97A0301V9A | E | 10/15/2001 | 1 | INTERSIL | | Y | HS0-2626RH-Q | 365 |
| 5962-97A0301VXC | E | 10/15/2001 | 1 | INTERSIL | | Y | HS9-2626RH-Q | 365 |
| 5962-97A0401V9A | D | 10/16/2001 | 1 | INTERSIL | | Y | HS0-11508RH-Q | 365 |
| 5962-97A0401VXC | D | 10/16/2001 | 1 | INTERSIL | | Y | HS9-11508RH-Q | 365 |
| 5962-97A0501V9A | D | 10/15/2001 | 1 | INTERSIL | | Y | HS0-2422RH-Q | 365 |
| 5962-97A0501VXC | D | 10/15/2001 | 1 | INTERSIL | | Y | HS9-2422RH-Q | 365 |
| 5962-97A0601V9A | F | 05/19/2003 | 1 | INTERSIL | | Y | HS0-7687RH-Q | 365 |
| 5962-97A0601VXC | F | 05/19/2003 | 1 | INTERSIL | | Y | HS9-7687RH-Q | 365 |
| 5962-97A0701V9A | G | 01/15/2004 | 1 | INTERSIL | | Y | HAA0-51155R4553 | 365 |
| 5962-97A0701VXC | G | 01/15/2004 | 1 | INTERSIL | | Y | HAA9-51155R4553 | 365 |
| 5962-97A0801V9A | E | 05/19/2003 | 1 | INTERSIL | | Y | HAA0-51156R4554 | 365 |
| 5962-97A0801VXC | E | 05/19/2003 | 1 | INTERSIL | | Y | HAA9-51156R4554 | 365 |
| 5962-97A0901V9A | G | 10/17/2001 | 1 | INTERSIL | | Y | HAA0-51159R4555 | 365 |
| 5962-97A0901VXC | G | 10/17/2001 | 1 | INTERSIL | | Y | HAA9-51159R4555 | 365 |
| 5962-97A1001V9A | H | 05/20/2003 | 1 | INTERSIL | | Y | HAA0-51154R4552 | 365 |
| 5962-97A1001VXC | H | 05/20/2003 | 1 | INTERSIL | | Y | HAA9-51154R4552 | 365 |
| 5962-97A1101VXC | C | 11/06/2000 | 1 | INTERSIL | | Y | HAA9-03180R4556 | 365 |
| 5962-97A1201QXC | A | 11/25/1998 | | (NONE) | | | 6580-020 (GEN) | 365 |
| 5962-97A1201QZC | A | 11/25/1998 | 3 | AMI | | Y | 6580-020 | 365 |
| 5962-97A1202QYC | A | 11/25/1998 | 3 | AMI | | Y | 6580-024 | 365 |
| 5962-97A1301QXC | | 06/16/1997 | 3 | AMI | | Y | 6580-025 | 365 |
| 5962-97A1401QXC | | 12/29/1997 | 3 | AMI | | Y | 6574-027 | 365 |
| 5962-97A1501QXC | | 06/16/1997 | 2 | AMI | | Y | 06550-022 | 365 |
| 5962-97A1601QXA | | 11/13/1997 | 1 | AMI | | Y | 5343-049 | 365 |
| 5962-97A1701QXC | | 10/22/1997 | 1 | AMI | | Y | 5343-050 | 365 |
| 5962-97B0101Q*A | | 08/04/1997 | | TI | | Y | TGC2016 | 365 |
| 5962-97B0102Q*A | | 08/04/1997 | | TI | | Y | TGC2019 | 365 |
| 5962-97B0103Q*A | | 08/04/1997 | | TI | | Y | TGC2030 | 365 |
| 5962-97B0104Q*A | | 08/04/1997 | | TI | | Y | TGC2036 | 365 |
| 5962-97B0105Q*A | | 08/04/1997 | | TI | | Y | TGC2046 | 365 |
| 5962-97B0106Q*A | | 08/04/1997 | | TI | | Y | TGC2053 | 365 |
| 5962-97B0107Q*A | | 08/04/1997 | | TI | | Y | TGC2068 | 365 |
| 5962-97B0108Q*A | | 08/04/1997 | | TI | | Y | TGC2086 | 365 |
| 5962-97B0109Q*A | | 08/04/1997 | | TI | | Y | TGC2113 | 365 |
| 5962-97B0110Q*A | | 08/04/1997 | | TI | | Y | TGC2154 | 365 |
| 5962-97B0111Q*A | | 08/04/1997 | | TI | | Y | TGC2191 | 365 |
| 5962-97B0112Q*A | | 08/04/1997 | | TI | | Y | TGC2245 | 365 |
| 5962H97B0301QMC | J | 06/09/2004 | 1 | HONEYWELL (1) | | Y | HX2080 | 365 |
| 5962H97B0301VMC | J | 06/09/2004 | 1 | HONEYWELL (1) | | Y | HX2080 | 365 |
| 5962H97B0301QXC | J | 06/09/2004 | 1 | HONEYWELL (1) | | Y | HX2080 | 365 |
| 5962H97B0301VXC | J | 06/09/2004 | 1 | HONEYWELL (1) | | Y | HX2080 | 365 |
| 5962H97B0301QZC | J | 06/09/2004 | 1 | HONEYWELL (1) | | Y | HX2080 | 365 |
| 5962H97B0301VZC | J | 06/09/2004 | 1 | HONEYWELL (1) | | Y | HX2080 | 365 |
| 5962H97B0302QXC | J | 06/09/2004 | 1 | HONEYWELL (1) | | Y | HX2160 | 365 |
| 5962H97B0302VXC | J | 06/09/2004 | 1 | HONEYWELL (1) | | Y | HX2160 | 365 |
| 5962H97B0302QZC | J | 06/09/2004 | 1 | HONEYWELL (1) | | Y | HX2160 | 365 |
| 5962H97B0302VZC | J | 06/09/2004 | 1 | HONEYWELL (1) | | Y | HX2160 | 365 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962H97B0303QXC | J | 06/09/2004 | 1 | HONEYWELL (1) | | Y | HX2300 | 365 |
| 5962H97B0303VXC | J | 06/09/2004 | 1 | HONEYWELL (1) | | Y | HX2300 | 365 |
| 5962H97B0303QZC | J | 06/09/2004 | 1 | HONEYWELL (1) | | Y | HX2300 | 365 |
| 5962H97B0303VZC | J | 06/09/2004 | 1 | HONEYWELL (1) | | Y | HX2300 | 365 |
| 5962H97B0304QXC | J | 06/09/2004 | 1 | HONEYWELL (1) | | Y | HX2400 | 365 |
| 5962H97B0304VXC | J | 06/09/2004 | 1 | HONEYWELL (1) | | Y | HX2400 | 365 |
| 5962H97B0304QZC | J | 06/09/2004 | 1 | HONEYWELL (1) | | Y | HX2400 | 365 |
| 5962H97B0304VZC | J | 06/09/2004 | 1 | HONEYWELL (1) | | Y | HX2400 | 365 |
| 5962H97B0305Q4C | J | 06/09/2004 | 1 | HONEYWELL (1) | | Y | HX2040 | 365 |
| 5962H97B0305V4C | J | 06/09/2004 | 1 | HONEYWELL (1) | | Y | HX2040 | 365 |
| 5962H97B0305QUC | J | 06/09/2004 | 1 | HONEYWELL (1) | | Y | HX2040 | 365 |
| 5962H97B0305VUC | J | 06/09/2004 | 1 | HONEYWELL (1) | | Y | HX2040 | 365 |
| 5962H97B0305QXC | J | 06/09/2004 | 1 | HONEYWELL (1) | | Y | HX2040 | 365 |
| 5962H97B0305VXC | J | 06/09/2004 | 1 | HONEYWELL (1) | | Y | HX2040 | 365 |
| 5962H97B0305QYC | J | 06/09/2004 | 1 | HONEYWELL (1) | | Y | HX2040 | 365 |
| 5962H97B0305VYC | J | 06/09/2004 | 1 | HONEYWELL (1) | | Y | HX2040 | 365 |
| 5962H97B0305QZC | J | 06/09/2004 | 1 | HONEYWELL (1) | | Y | HX2040 | 365 |
| 5962H97B0305VZC | J | 06/09/2004 | 1 | HONEYWELL (1) | | Y | HX2040 | 365 |
| 5962H97B0308QTC | J | 06/09/2004 | 1 | HONEYWELL (1) | | Y | HX2300r | 365 |
| 5962H97B0308VTC | J | 06/09/2004 | 1 | HONEYWELL (1) | | Y | HX2300r | 365 |
| 5962H97B0309QNA | J | 06/09/2004 | 1 | HONEYWELL (1) | | Y | HX2400r | 365 |
| 5962H97B0309VNA | J | 06/09/2004 | 1 | HONEYWELL (1) | | Y | HX2400r | 365 |
| 5962H97B0401QXC | C | 12/12/2001 | 1 | UTMC | | Y | UT25E/R_QCH | 368 |
| 5962H97B0401VXC | C | 12/12/2001 | 1 | UTMC | | Y | UT25E/R_VCH | 368 |
| 5962H97B0402QXC | C | 12/12/2001 | 1 | UTMC | | Y | UT25E/R_QCH | 368 |
| 5962H97B0402VXC | C | 12/12/2001 | 1 | UTMC | | Y | UT25E/R_VCH | 368 |
| 5962H97B0402QYA | C | 12/12/2001 | 1 | UTMC | | Y | UT25E/R_QCH | 368 |
| 5962H97B0402VYA | C | 12/12/2001 | 1 | UTMC | | Y | UT25E/R_VCH | 368 |
| 5962H97B0402QZA | C | 12/12/2001 | 1 | UTMC | | Y | UT25E/R_QCH | 368 |
| 5962H97B0402VZA | C | 12/12/2001 | 1 | UTMC | | Y | UT25E/R_VCH | 368 |
| 5962H97B0403QXC | C | 12/12/2001 | 1 | UTMC | | Y | UT25E/R_QCH | 368 |
| 5962H97B0403VXC | C | 12/12/2001 | 1 | UTMC | | Y | UT25E/R_VCH | 368 |
| 5962H97B0404QXC | C | 12/12/2001 | 1 | UTMC | | Y | UT25E/R_QCH | 368 |
| 5962H97B0404VXC | C | 12/12/2001 | 1 | UTMC | | Y | UT25E/R_VCH | 368 |
| 5962H97B0405QXC | C | 12/12/2001 | 1 | UTMC | | Y | UT25E/R_QCH | 368 |
| 5962H97B0405VXC | C | 12/12/2001 | 1 | UTMC | | Y | UT25E/R_VCH | 368 |
| 5962H97B0406QXC | C | 12/12/2001 | 1 | UTMC | | Y | UT35E/R_QCH | 368 |
| 5962H97B0406VXC | C | 12/12/2001 | 1 | UTMC | | Y | UT35E/R_VCH | 368 |
| 5962H97B0406QZC | C | 12/12/2001 | 1 | UTMC | | Y | UT35E/R_QCH | 368 |
| 5962H97B0406VZC | C | 12/12/2001 | 1 | UTMC | | Y | UT35E/R_VCH | 368 |
| 5962H97B0407QXC | C | 12/12/2001 | 1 | UTMC | | Y | UT75E/R_QCH | 368 |
| 5962H97B0407VXC | C | 12/12/2001 | 1 | UTMC | | Y | UT75E/R_VCH | 368 |
| 5962H97B0408QXC | C | 12/12/2001 | 1 | UTMC | | Y | UT100E/R_QCH | 368 |
| 5962H97B0408VXC | C | 12/12/2001 | 1 | UTMC | | Y | UT100E/R_VCH | 368 |
| 5962-9800101KEA | A | 07/24/2002 | 2 | AGILENT | | Y | HCPL-268K#200 | 460 |
| 5962-9800101KEA | A | 07/24/2002 | 1 | MICROPAC | | Y | 66013-301 | 460 |
| 5962-9800101KEC | A | 07/24/2002 | 2 | AGILENT | | Y | HCPL-268K | 460 |
| 5962-9800101KEC | A | 07/24/2002 | 1 | MICROPAC | | Y | 66013-301 | 460 |
| 5962-9800101KTA | A | 07/24/2002 | 2 | AGILENT | | Y | HCPL-268K#300 | 460 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9800101KUA | A | 07/24/2002 | 2 | AGILENT | | Y | HCPL-268K#100 | 460 |
| 5962-9800101KUC | A | 07/24/2002 | 2 | AGILENT | | Y | HCPL-268K#100 | 460 |
| 5962-9800101KXA | A | 07/24/2002 | 1 | MICROPAC | | Y | 66072-300 | 460 |
| 5962-9800101KXC | A | 07/24/2002 | 1 | MICROPAC | | Y | 66072-300 | 460 |
| 5962-9800102KPA | A | 07/24/2002 | 2 | AGILENT | | Y | HCPL-563K#200 | 460 |
| 5962-9800102KPA | A | 07/24/2002 | 1 | MICROPAC | | Y | 66056-300 | 460 |
| 5962-9800102KPC | A | 07/24/2002 | 2 | AGILENT | | Y | HCPL-563K | 460 |
| 5962-9800102KPC | A | 07/24/2002 | 1 | MICROPAC | | Y | 66056-300 | 460 |
| 5962-9800102KYA | A | 07/24/2002 | 2 | AGILENT | | Y | HCPL-563K#100 | 460 |
| 5962-9800102KYC | A | 07/24/2002 | 2 | AGILENT | | Y | HCPL-563K#100 | 460 |
| 5962-9800102KZA | A | 07/24/2002 | 2 | AGILENT | | Y | HCPL-563K#300 | 460 |
| 5962-9800103K2A | A | 07/24/2002 | 2 | AGILENT | | Y | HCPL-663K | 460 |
| 5962-9800103K2A | A | 07/24/2002 | 1 | MICROPAC | | Y | 66123-300 | 460 |
| 5962-9800103K2C | A | 07/24/2002 | 1 | MICROPAC | | Y | 66123-300 | 460 |
| 5962-9800104KFA | A | 07/24/2002 | 2 | AGILENT | | Y | HCPL-665K | 460 |
| 5962-9800201KEA | A | 08/08/2002 | 3 | AGILENT | | Y | HCPL-177K#200 | 460 |
| 5962-9800201KEA | A | 08/08/2002 | 1 | MICROPAC | | Y | 66012-300 | 460 |
| 5962-9800201KEC | A | 08/08/2002 | 3 | AGILENT | | Y | HCPL-177K | 460 |
| 5962-9800201KEC | A | 08/08/2002 | 1 | MICROPAC | | Y | 66012-300 | 460 |
| 5962-9800201KFC | A | 08/08/2002 | 3 | AGILENT | | Y | HCPL-675K | 460 |
| 5962-9800201KXA | A | 08/08/2002 | 3 | AGILENT | | Y | HCPL-177K#300 | 460 |
| 5962-9800201KXA | A | 08/08/2002 | 1 | MICROPAC | | Y | 66012-300J | 460 |
| 5962-9800201KXC | A | 08/08/2002 | 1 | MICROPAC | | Y | 66012-300J | 460 |
| 5962-9800201KYA | A | 08/08/2002 | 3 | AGILENT | | Y | HCPL-177K#100 | 460 |
| 5962-9800201KYC | A | 08/08/2002 | 3 | AGILENT | | Y | HCPL-177K#100 | 460 |
| 5962-9800201KZA | A | 08/08/2002 | 3 | AGILENT | | Y | HCPL-177K#600 | 460 |
| 5962-9800201KZC | A | 08/08/2002 | 3 | AGILENT | | Y | HCPL-177K#600 | 460 |
| 5962-9800302HXA | | 12/01/1999 | | (NONE) | 08/29/2003 | | AD14160 (GEN) | 432 |
| 5962F9800701V9A | A | 05/05/1999 | | (NONE) | | | ACS253 (GEN) | 276 |
| 5962F9800701VEC | A | 05/05/1999 | | (NONE) | | | ACS253 (GEN) | 276 |
| 5962F9800701VXC | A | 05/05/1999 | | (NONE) | | | ACS253 (GEN) | 276 |
| 5962F9800801V9A | A | 05/05/1999 | | (NONE) | | | ACS257 (GEN) | 276 |
| 5962F9800801VEC | A | 05/05/1999 | | (NONE) | | | ACS257 (GEN) | 276 |
| 5962F9800801VXC | A | 05/05/1999 | | (NONE) | | | ACS257 (GEN) | 276 |
| 5962-9850901NTB | | 11/06/1998 | 2 | XILINX | | Y | XQ4028EX-4HQ240N | 399 |
| 5962-9850901NUA | | 11/06/1998 | 2 | XILINX | | Y | XQ4028EX-4BG352N | 399 |
| 5962-9850901QXC | | 11/06/1998 | 3 | XILINX | | Y | XQ4028EX-4PG299B | 399 |
| 5962-9850901QYC | | 11/06/1998 | 3 | XILINX | | Y | XQ4028EX-4CB228B | 399 |
| 5962-9850901QZC | | 11/06/1998 | 3 | XILINX | | Y | XQ4028EX-4CB228B | 399 |
| 5962-9851001NTB | A | 04/09/1999 | 3 | XILINX | | Y | XQ4036XL-3NHQ240 | 399 |
| 5962-9851001NUA | A | 04/09/1999 | 3 | XILINX | | Y | XQ4036XL-3NBG352 | 399 |
| 5962-9851001QXC | A | 04/09/1999 | 3 | XILINX | | Y | XQ4036XL-3BPG411 | 399 |
| 5962-9851001QYC | A | 04/09/1999 | 3 | XILINX | | Y | XQ4036XL-3BCB228 | 399 |
| 5962-9851001QZC | A | 04/09/1999 | 3 | XILINX | | Y | XQ4036XL-3BCB228 | 399 |
| 5962-9851101NTB | | 11/23/1998 | 2 | XILINX | | Y | XQ4062XL-3NHQ240 | 399 |
| 5962-9851101NUA | | 11/23/1998 | 2 | XILINX | | Y | XQ4062XL-3NBG432 | 399 |
| 5962-9851101QXC | | 11/23/1998 | 2 | XILINX | | Y | XQ4062XL-3BPG475 | 399 |
| 5962-9851101QYC | | 11/23/1998 | 2 | XILINX | | Y | XQ4062XL-3BCB228 | 399 |
| 5962-9851101QZC | | 11/23/1998 | 2 | XILINX | | Y | XQ4062XL-3BCB228 | 399 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9851301NTB | | 12/16/1998 | 3 | XILINX | | Y | XQ4013XL-3PQ240N | 381 |
| 5962-9851301QXC | | 12/16/1998 | 3 | XILINX | | Y | XQ4013XL-3PG223B | 381 |
| 5962-9851301QYC | | 12/16/1998 | 3 | XILINX | | Y | XQ4013XL-3CB228B | 381 |
| 5962-9851301QZC | | 12/16/1998 | 3 | XILINX | | Y | XQ4013XL-3CB228B | 381 |
| 5962-9851401HIA | B | 10/26/2001 | 1 | MS KENNEDY | | Y | MSK1362B | 781 |
| 5962-9851401HIC | B | 10/26/2001 | 1 | MS KENNEDY | | Y | MSK1362B | 781 |
| 5962-9851501Q2A | B | 12/28/2001 | 1 | TI | | Y | TL082MFKB | 703 |
| 5962-9851501QPA | B | 12/28/2001 | 1 | TI | | Y | TL082MJGB | 703 |
| 5962-9851502Q2A | B | 12/28/2001 | 1 | TI | | Y | TL081MFKB | 703 |
| 5962-9851502QPA | B | 12/28/2001 | 1 | TI | | Y | TL081MJGB | 703 |
| 5962-9851503Q2A | B | 12/28/2001 | 1 | TI | | Y | TL084MFKB | 703 |
| 5962-9851503QCA | B | 12/28/2001 | 1 | TI | | Y | TL084MJB | 703 |
| 5962-9851601Q2A | | 02/22/1998 | 2 | TI | | Y | SNJ54AHC138FK | 282 |
| 5962-9851601QEA | | 02/22/1998 | 2 | TI | | Y | SNJ54AHC138J | 282 |
| 5962-9851601QFA | | 02/22/1998 | 2 | TI | | Y | SNJ54AHC138W | 282 |
| 5962-9851701Q2A | | 02/22/1998 | 2 | TI | | Y | SNJ54AHCT138FK | 282 |
| 5962-9851701QEA | | 02/22/1998 | 2 | TI | | Y | SNJ54AHCT138J | 282 |
| 5962-9851701QFA | | 02/22/1998 | 2 | TI | | Y | SNJ54AHCT138W | 282 |
| 5962F9851801VXC | | 11/10/1997 | | (NONE) | 12/28/2003 | | HS-1410RH (GEN) | 739 |
| 5962-9852101QXA | | 12/03/1998 | 2 | TI | | Y | SNJ54CBT16212AWD | 399 |
| 5962-9852201HXA | A | 07/18/2003 | 1 | INTERPOINT | | Y | MHV2805S/883 | 594 |
| 5962-9852201HXC | A | 07/18/2003 | 1 | INTERPOINT | | Y | MHV2805S/883 | 594 |
| 5962-9852201HZA | A | 07/18/2003 | 1 | INTERPOINT | | Y | MHV2805SF/883 | 594 |
| 5962-9852201HZC | A | 07/18/2003 | 1 | INTERPOINT | | Y | MHV2805SF/883 | 594 |
| 5962-9852301HXA | | 08/12/2003 | 1 | INTERPOINT | | Y | MHV2812S/883 | 594 |
| 5962-9852301HXC | | 08/12/2003 | 1 | INTERPOINT | | Y | MHV2812S/883 | 594 |
| 5962-9852301HZA | | 08/12/2003 | 1 | INTERPOINT | | Y | MHV2812SF/883 | 594 |
| 5962-9852301HZC | | 08/12/2003 | 1 | INTERPOINT | | Y | MHV2812SF/883 | 594 |
| 5962-9852401HXA | | 08/12/2003 | 1 | INTERPOINT | | Y | MHV2815S/883 | 594 |
| 5962-9852401HXC | | 08/12/2003 | 1 | INTERPOINT | | Y | MHV2815S/883 | 594 |
| 5962-9852401HZA | | 08/12/2003 | 1 | INTERPOINT | | Y | MHV2815SF/883 | 594 |
| 5962-9852401HZC | | 08/12/2003 | 1 | INTERPOINT | | Y | MHV2815SF/883 | 594 |
| 5962-9852501HXA | A | 08/04/2003 | 1 | INTERPOINT | | Y | MHV2805D/883 | 594 |
| 5962-9852501HXC | A | 08/04/2003 | 1 | INTERPOINT | | Y | MHV2805D/883 | 594 |
| 5962-9852501HZA | A | 08/04/2003 | 1 | INTERPOINT | | Y | MHV2805DF/883 | 594 |
| 5962-9852501HZC | A | 08/04/2003 | 1 | INTERPOINT | | Y | MHV2805DF/883 | 594 |
| 5962-9852601HXA | A | 08/04/2003 | 1 | INTERPOINT | | Y | MHV2812D/883 | 594 |
| 5962-9852601HXC | A | 08/04/2003 | 1 | INTERPOINT | | Y | MHV2812D/883 | 594 |
| 5962-9852601HZA | A | 08/04/2003 | 1 | INTERPOINT | | Y | MHV2812DF/883 | 594 |
| 5962-9852601HZC | A | 08/04/2003 | 1 | INTERPOINT | | Y | MHV2812DF/883 | 594 |
| 5962-9852701HXA | A | 08/04/2003 | 1 | INTERPOINT | | Y | MHV2815D/883 | 594 |
| 5962-9852701HXC | A | 08/04/2003 | 1 | INTERPOINT | | Y | MHV2815D/883 | 594 |
| 5962-9852701HZA | A | 08/04/2003 | 1 | INTERPOINT | | Y | MHV2815DF/883 | 594 |
| 5962-9852701HZC | A | 08/04/2003 | 1 | INTERPOINT | | Y | MHV2815DF/883 | 594 |
| 5962-9852801HXA | A | 09/18/2003 | 1 | INTERPOINT | | Y | MHV283R3S/883 | 594 |
| 5962-9852801HXC | A | 09/18/2003 | 1 | INTERPOINT | | Y | MHV283R3S/883 | 594 |
| 5962-9852801HZA | A | 09/18/2003 | 1 | INTERPOINT | | Y | MHV283R3SF/883 | 594 |
| 5962-9852801HZC | A | 09/18/2003 | 1 | INTERPOINT | | Y | MHV283R3SF/883 | 594 |
| 5962-9852901HXA | D | 02/07/2001 | 1 | INTERPOINT | | Y | SLH2815D/HO | 594 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9852901HXC | D | 02/07/2001 | 1 | INTERPOINT | | Y | SLH2815D/HO | 594 |
| 5962L9852901HXA | D | 02/07/2001 | 1 | INTERPOINT | | Y | SLH2815D/HL | 594 |
| 5962L9852901HXC | D | 02/07/2001 | 1 | INTERPOINT | | Y | SLH2815D/HL | 594 |
| 5962L9852901KXA | D | 02/07/2001 | 1 | INTERPOINT | | Y | SLH2815D/KL | 594 |
| 5962L9852901KXC | D | 02/07/2001 | 1 | INTERPOINT | | Y | SLH2815D/KL | 594 |
| 5962R9852901HXA | D | 02/07/2001 | 1 | INTERPOINT | | Y | SLH2815D/HR | 594 |
| 5962R9852901HXC | D | 02/07/2001 | 1 | INTERPOINT | | Y | SLH2815D/HR | 594 |
| 5962R9852901KXA | D | 02/07/2001 | 1 | INTERPOINT | | Y | SLH2815D/KR | 594 |
| 5962R9852901KXC | D | 02/07/2001 | 1 | INTERPOINT | | Y | SLH2815D/KR | 594 |
| 5962-9853001Q2A | A | 05/19/2000 | 2 | TI | | Y | SNJ54AHC273FK | 159 |
| 5962-9853001QRA | A | 05/19/2000 | 2 | TI | | Y | SNJ54AHC273J | 159 |
| 5962-9853001QSA | A | 05/19/2000 | 2 | TI | | Y | SNJ54AHC273W | 159 |
| 5962R9853301V9A | A | 06/09/1998 | 1 | INTERSIL | | Y | HS0-OP470ARH-Q | 713 |
| 5962R9853301VXC | A | 06/09/1998 | 1 | INTERSIL | | Y | HS9-OP470ARH-Q | 713 |
| 5962F9853401V9A | A | 03/10/1999 | | (NONE) | | | ACS138 (GEN) | 282 |
| 5962F9853401VEC | A | 03/10/1999 | 1 | INTERSIL | | Y | ACS138DMSR-03 | 282 |
| 5962F9853401VXC | A | 03/10/1999 | 1 | INTERSIL | | Y | ACS138KMSR-03 | 282 |
| 5962F9853501V9A | A | 09/02/1998 | | (NONE) | | | ACTS138 (GEN) | 282 |
| 5962F9853501VEC | A | 09/02/1998 | | (NONE) | | | ACTS138 (GEN) | 282 |
| 5962F9853501VXC | A | 09/02/1998 | | (NONE) | | | ACTS138 (GEN) | 282 |
| 5962F9853601V9A | A | 03/10/1999 | | (NONE) | | | ACS157-03 (GEN) | 276 |
| 5962F9853601VEC | A | 03/10/1999 | | (NONE) | | | ACS157-03 (GEN) | 276 |
| 5962F9853601VXC | A | 03/10/1999 | | (NONE) | | | ACS157-03 (GEN) | 276 |
| 5962H9853701Q9A | A | 05/01/2001 | 2 | HONEYWELL (1) | | Y | HX6228Die | 629 |
| 5962H9853701QXC | A | 05/01/2001 | 2 | HONEYWELL (1) | | Y | HX6228/TQHC | 629 |
| 5962H9853701VXC | A | 05/01/2001 | 2 | HONEYWELL (1) | | Y | HX6228/TVHC | 629 |
| 5962H9853701QYC | A | 05/01/2001 | 2 | HONEYWELL (1) | | Y | HX6228/AQHC | 629 |
| 5962H9853701VYC | A | 05/01/2001 | 2 | HONEYWELL (1) | | Y | HX6228/AVHC | 629 |
| 5962H9853702Q9A | A | 05/01/2001 | 2 | HONEYWELL (1) | | Y | HX6228Die | 629 |
| 5962H9853702QXC | A | 05/01/2001 | 2 | HONEYWELL (1) | | Y | HX6228/TQHT | 629 |
| 5962H9853702VXC | A | 05/01/2001 | 2 | HONEYWELL (1) | | Y | HX6228/TVHT | 629 |
| 5962H9853702QYC | A | 05/01/2001 | 2 | HONEYWELL (1) | | Y | HX6228/AQHT | 629 |
| 5962H9853702VYC | A | 05/01/2001 | 2 | HONEYWELL (1) | | Y | HX6228/AVHT | 629 |
| 5962-9853801Q2A | | 06/24/1998 | 2 | TI | 06/30/2004 | Y | TLV1548MFKB | 592 |
| 5962-9853801QRA | | 06/24/1998 | 2 | TI | 06/30/2004 | Y | TLV1548MJB | 592 |
| 5962P9853901QGA | | 05/26/2000 | | (NONE) | | | LM118 (GEN) | 722 |
| 5962P9853901VGA | | 05/26/2000 | | (NONE) | | | LM118 (GEN) | 722 |
| 5962P9853901QPA | | 05/26/2000 | | (NONE) | | | LM118 (GEN) | 722 |
| 5962P9853901VPA | | 05/26/2000 | | (NONE) | | | LM118 (GEN) | 722 |
| 5962P9853901QZA | | 05/26/2000 | | (NONE) | | | LM118 (GEN) | 722 |
| 5962P9853901VZA | | 05/26/2000 | | (NONE) | | | LM118 (GEN) | 722 |
| 5962F9854001V9A | B | 09/29/1999 | | (NONE) | | | ACS240 (GEN) | 529 |
| 5962F9854001VRC | B | 09/29/1999 | | (NONE) | | | ACS240 (GEN) | 529 |
| 5962F9854001VXC | B | 09/29/1999 | | (NONE) | | | ACS240 (GEN) | 529 |
| 5962F9854101V9A | B | 09/29/1999 | | (NONE) | | | ACS244 (GEN) | 529 |
| 5962F9854101VRC | B | 09/29/1999 | 1 | INTERSIL | | Y | ACS244DMSR-02 | 529 |
| 5962F9854101VXC | B | 09/29/1999 | 1 | INTERSIL | | Y | ACS244KMSR-02 | 529 |
| 5962-9854201QXA | A | 05/02/2003 | 3 | TI | | Y | SNJ54LVTH162374WD | 158 |
| 5962-9854201VXA | A | 05/02/2003 | 3 | TI | | Y | SNV54LVTH162374WD | 158 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9855001QXA | C | 11/18/2003 | 1 | NATIONAL | 09/01/2004 | Y | LMX2315WG-QML | 809 |
| 5962-9855002QXA | C | 11/18/2003 | 1 | NATIONAL | 09/01/2004 | Y | LMX2325WG-QML | 809 |
| 5962-9855003QXA | C | 11/18/2003 | 1 | NATIONAL | 09/01/2004 | Y | LMX2305WG-QML | 809 |
| 5962-9855201QXA | B | 02/02/2004 | 1 | UTMC | | Y | UT69R00012GCA | 420 |
| 5962-9855201QXC | B | 02/02/2004 | 1 | UTMC | | Y | UT69R00012GCC | 420 |
| 5962H9855201QXA | B | 02/02/2004 | 1 | UTMC | | Y | UT69R00012GCAH | 420 |
| 5962H9855201QXC | B | 02/02/2004 | 1 | UTMC | | Y | UT69R00012GCCH | 420 |
| 5962H9855201VXA | B | 02/02/2004 | 1 | UTMC | | Y | UT69R00012GCAH | 420 |
| 5962H9855201VXC | B | 02/02/2004 | 1 | UTMC | | Y | UT69R00012GCCH | 420 |
| 5962-9855201QYC | B | 02/02/2004 | 1 | UTMC | | Y | UT69R00012WCC | 420 |
| 5962H9855201QYC | B | 02/02/2004 | 1 | UTMC | | Y | UT69R00012WCCH | 420 |
| 5962H9855201VYC | B | 02/02/2004 | 1 | UTMC | | Y | UT69R00012WCCH | 420 |
| 5962-9855201QZA | B | 02/02/2004 | 1 | UTMC | | Y | UT69R00012FCA | 420 |
| 5962-9855201QZC | B | 02/02/2004 | 1 | UTMC | | Y | UT69R00012FCC | 420 |
| 5962H9855201QZA | B | 02/02/2004 | 1 | UTMC | | Y | UT69R00012FCAH | 420 |
| 5962H9855201QZC | B | 02/02/2004 | 1 | UTMC | | Y | UT69R00012FCCH | 420 |
| 5962H9855201VZA | B | 02/02/2004 | 1 | UTMC | | Y | UT69R00012FCAH | 420 |
| 5962H9855201VZC | B | 02/02/2004 | 1 | UTMC | | Y | UT69R00012FCCH | 420 |
| 5962-9855202QXA | B | 02/02/2004 | 1 | UTMC | | Y | UT69R00016GCA | 420 |
| 5962-9855202QXC | B | 02/02/2004 | 1 | UTMC | | Y | UT69R00016GCC | 420 |
| 5962H9855202QXA | B | 02/02/2004 | 1 | UTMC | | Y | UT69R00016GCAH | 420 |
| 5962H9855202QXC | B | 02/02/2004 | 1 | UTMC | | Y | UT69R00016GCCH | 420 |
| 5962H9855202VXA | B | 02/02/2004 | 1 | UTMC | | Y | UT69R00016GCAH | 420 |
| 5962H9855202VXC | B | 02/02/2004 | 1 | UTMC | | Y | UT69R00016GCCH | 420 |
| 5962-9855202QYC | B | 02/02/2004 | 1 | UTMC | | Y | UT69R00016WCC | 420 |
| 5962H9855202QYC | B | 02/02/2004 | 1 | UTMC | | Y | UT69R00016WCCH | 420 |
| 5962H9855202VYC | B | 02/02/2004 | 1 | UTMC | | Y | UT69R00016WCCH | 420 |
| 5962-9855202QZA | B | 02/02/2004 | 1 | UTMC | | Y | UT69R00016FCA | 420 |
| 5962-9855202QZC | B | 02/02/2004 | 1 | UTMC | | Y | UT69R00016FCC | 420 |
| 5962H9855202QZA | B | 02/02/2004 | 1 | UTMC | | Y | UT69R00016FCAH | 420 |
| 5962H9855202QZC | B | 02/02/2004 | 1 | UTMC | | Y | UT69R00016FCCH | 420 |
| 5962H9855202VZA | B | 02/02/2004 | 1 | UTMC | | Y | UT69R00016FCAH | 420 |
| 5962H9855202VZC | B | 02/02/2004 | 1 | UTMC | | Y | UT69R00016FCCH | 420 |
| 5962-9855301QXA | | 12/03/1998 | 2 | TI | | Y | SNJ54CBT16244WD | 399 |
| 5962-9856401QEA | | 03/31/1998 | 1 | TI | | Y | SNJ5447AJ | 291 |
| 5962-9856401QFA | | 03/31/1998 | 1 | TI | | Y | SNJ5447AW | 291 |
| 5962-9857801QXA | B | 04/13/2001 | 3 | TI | | Y | SMJ320C6201B | 432 |
| 5962-9857901Q9A | | 06/21/1999 | 1 | ACTEL | | Y | A32100DX-DIE | 381 |
| 5962-9857901QXC | | 06/21/1999 | 1 | ACTEL | | Y | A32100DX-CQ84B | 381 |
| 5962-9857902QXC | | 06/21/1999 | 1 | ACTEL | | Y | A32100DX-1CQ84B | 381 |
| 5962-9858001Q9A | E | 07/29/2004 | 1 | UTMC | | Y | UT54ACS164245S-QDI | 590 |
| 5962R9858001V9A | E | 07/29/2004 | 1 | UTMC | | Y | UT54ACS164245S-VDI | 590 |
| 5962-9858001QXC | E | 07/29/2004 | 1 | UTMC | | Y | UT54ACS164245SUCC | 590 |
| 5962R9858001VXC | E | 07/29/2004 | 1 | UTMC | | Y | UT54ACS164245SUCC | 590 |
| 5962-9858002Q9A | E | 07/29/2004 | 1 | UTMC | | Y | UT54ACS164245S-QDI | 590 |
| 5962R9858002V9A | E | 07/29/2004 | 1 | UTMC | | Y | UT54ACS164245S-VDI | 590 |
| 5962-9858002QXC | E | 07/29/2004 | 1 | UTMC | | Y | UT54ACS164245SUCC | 590 |
| 5962R9858002VXC | E | 07/29/2004 | 1 | UTMC | | Y | UT54ACS164245SUCC | 590 |
| 5962-9858003Q9A | E | 07/29/2004 | 1 | UTMC | | Y | UT54ACS164245S-QDI | 590 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962R9858003V9A | E | 07/29/2004 | 1 | UTMC | | Y | UT54ACS164245S-VDI | 590 |
| 5962-9858003QXC | E | 07/29/2004 | 1 | UTMC | | Y | UT54ACS164245SUCC | 590 |
| 5962R9858003VXC | E | 07/29/2004 | 1 | UTMC | | Y | UT54ACS164245SUCC | 590 |
| 5962-9858004Q9A | E | 07/29/2004 | 1 | UTMC | | Y | UT54ACS164245SE-QD | 590 |
| 5962R9858004V9A | E | 07/29/2004 | 1 | UTMC | | Y | UT54ACS164245SE-VD | 590 |
| 5962-9858004QXC | E | 07/29/2004 | 1 | UTMC | | Y | UT54ACS164245SEUC | 590 |
| 5962R9858004VXC | E | 07/29/2004 | 1 | UTMC | | Y | UT54ACS164245SEUC | 590 |
| 5962-9858005Q9A | E | 07/29/2004 | 1 | UTMC | | Y | UT54ACS164245SE-QD | 590 |
| 5962R9858005V9A | E | 07/29/2004 | 1 | UTMC | | Y | UT54ACS164245SE-VD | 590 |
| 5962-9858005QXC | E | 07/29/2004 | 1 | UTMC | | Y | UT54ACS164245SEUC | 590 |
| 5962R9858005VXC | E | 07/29/2004 | 1 | UTMC | | Y | UT54ACS164245SEUC | 590 |
| 5962R9858301Q9A | D | 07/18/2002 | 1 | UTMC | | Y | UT80CRH196KD_QDIE | 420 |
| 5962R9858301V9A | D | 07/18/2002 | 1 | UTMC | | Y | UT80CRH196KD_VDIE | 420 |
| 5962-9858301QXA | D | 07/18/2002 | 1 | UTMC | | Y | UT80C196KD-WCA | 420 |
| 5962-9858301QXC | D | 07/18/2002 | 1 | UTMC | | Y | UT80C196KD-WCC | 420 |
| 5962R9858301QXA | D | 07/18/2002 | 1 | UTMC | | Y | UT80CRH196KD-WCA | 420 |
| 5962R9858301QXC | D | 07/18/2002 | 1 | UTMC | | Y | UT80CRH196KD-WCC | 420 |
| 5962R9858301VXA | D | 07/18/2002 | 1 | UTMC | | Y | UT80CRH196KD-WCA | 420 |
| 5962R9858301VXC | D | 07/18/2002 | 1 | UTMC | | Y | UT80CRH196KD-WCC | 420 |
| 5962R9858302Q9A | D | 07/18/2002 | 1 | UTMC | | Y | UT80CRH196KD_QWDI | 420 |
| 5962R9858302V9A | D | 07/18/2002 | 1 | UTMC | | Y | UT80CRH196KD_VWDI | 420 |
| 5962-9858302QXA | D | 07/18/2002 | 1 | UTMC | | Y | UT80C196KD-WWA | 420 |
| 5962-9858302QXC | D | 07/18/2002 | 1 | UTMC | | Y | UT80C196KD-WWC | 420 |
| 5962R9858302QXA | D | 07/18/2002 | 1 | UTMC | | Y | UT80CRH196KD-WWA | 420 |
| 5962R9858302QXC | D | 07/18/2002 | 1 | UTMC | | Y | UT80CRH196KD-WWC | 420 |
| 5962R9858302VXA | D | 07/18/2002 | 1 | UTMC | | Y | UT80CRH196KD-WWA | 420 |
| 5962R9858302VXC | D | 07/18/2002 | 1 | UTMC | | Y | UT80CRH196KD-WWC | 420 |
| 5962-9858401QFA | A | 06/15/2004 | 2 | NATIONAL | | Y | DS26LV31W-QML | 569 |
| 5962-9858501QFA | A | 06/29/2004 | 2 | NATIONAL | | Y | DS26LV32AW-QML | 575 |
| 5962-9858601Q2A | A | 02/07/2001 | 2 | SARNOFF | | Y | GEM22401Q2A | 656 |
| 5962-9858601Q2C | A | 02/07/2001 | 2 | SARNOFF | | Y | GEM22401Q2C | 656 |
| 5962-9858601QRA | A | 02/07/2001 | 2 | SARNOFF | | Y | GEM22401QRA | 656 |
| 5962-9858601QRC | A | 02/07/2001 | 2 | SARNOFF | | Y | GEM22401QRC | 656 |
| 5962-9858601QSA | A | 02/07/2001 | 2 | SARNOFF | | Y | GEM22401QSA | 656 |
| 5962-9858601QSC | A | 02/07/2001 | 2 | SARNOFF | | Y | GEM22401QSC | 656 |
| 5962-9858701QXA | A | 04/05/2001 | 1 | UTMC | | Y | UT69151RTEGCA | 399 |
| 5962-9858701QXC | A | 04/05/2001 | 1 | UTMC | | Y | UT69151RTEGCC | 399 |
| 5962-9858701QYC | A | 04/05/2001 | 1 | UTMC | | Y | UT69151RTEWCC | 399 |
| 5962-9858701QZC | A | 04/05/2001 | 1 | UTMC | | Y | UT69151RTEFCC | 399 |
| 5962-9858801Q2A | C | 01/16/2001 | 2 | TI | | Y | TLV2772MFKB | 710 |
| 5962-9858801QHA | C | 01/16/2001 | 2 | TI | | Y | TLV2772MUB | 710 |
| 5962-9858801QPA | C | 01/16/2001 | 2 | TI | | Y | TLV2772MJGB | 710 |
| 5962-9858802Q2A | C | 01/16/2001 | 2 | TI | | Y | TLV2772AMFKB | 710 |
| 5962-9858802QHA | C | 01/16/2001 | 2 | TI | | Y | TLV2772AMUB | 710 |
| 5962-9858802QPA | C | 01/16/2001 | 2 | TI | | Y | TLV2772AMJGB | 710 |
| 5962-9859001MMA | B | 02/11/2002 | 1 | INTER. RECT. | | | OM3957SM/883B | 782 |
| 5962-9859001MNA | B | 02/11/2002 | 1 | INTER. RECT. | | | OM3957NM/883B | 782 |
| 5962-9859001MTA | B | 02/11/2002 | 1 | INTER. RECT. | | | OM3957SRM/883B | 782 |
| 5962-9859001MUA | B | 02/11/2002 | 1 | INTER. RECT. | | | OM3957ST/883B | 782 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962P9859001MUA | B | 02/11/2002 | 1 | INTER. RECT. | | | OMR3957STM/883B | 782 |
| 5962-9859001MXA | B | 02/11/2002 | 1 | INTER. RECT. | | | OM3957N5M/883B | 782 |
| 5962-9859101NXB | B | 05/14/2003 | | (NONE) | 06/28/2002 | | HI5905 (GEN) | 592 |
| 5962-9859301QXA | | 06/24/1998 | 3 | TI | | Y | SNJ54ABT162601WD | 590 |
| 5962F9860101V9A | A | 04/21/1999 | | (NONE) | | | ACS02 (GEN) | 120 |
| 5962F9860101VCC | A | 04/21/1999 | | (NONE) | | | ACS02-03 (GEN) | 120 |
| 5962F9860101VXC | A | 04/21/1999 | | (NONE) | | | ACS02 (GEN) | 120 |
| 5962F9860201V9A | A | 04/13/1999 | | (NONE) | | | ACS05 (GEN) | 143 |
| 5962F9860201VCC | A | 04/13/1999 | | (NONE) | | | ACS05 (GEN) | 143 |
| 5962F9860201VXC | A | 04/13/1999 | | (NONE) | | | ACS05 (GEN) | 143 |
| 5962F9860301V9A | A | 04/21/1999 | 1 | INTERSIL | | Y | ACS04HMSR-03 | 143 |
| 5962F9860301VCC | A | 04/21/1999 | 1 | INTERSIL | | Y | ACS04DMSR-03 | 143 |
| 5962F9860301VXC | A | 04/21/1999 | 1 | INTERSIL | | Y | ACS04KMSR-03 | 143 |
| 5962-9860501QKA | | 01/07/1999 | | (NONE) | 03/04/2003 | | 54LVX3245 (GEN) | 399 |
| 5962-9860501QLA | | 01/07/1999 | | (NONE) | 03/04/2003 | | 54LVX3245 (GEN) | 399 |
| 5962-9860601QKA | | 01/07/1999 | | (NONE) | 03/04/2003 | | 54LVX4245 (GEN) | 399 |
| 5962-9860601QLA | | 01/07/1999 | | (NONE) | 03/04/2003 | | 54LVX4245 (GEN) | 399 |
| 5962-9860801Q2A | A | 12/17/1999 | 2 | TI | | Y | SNJ54AHC123AFK | 166 |
| 5962-9860801QEA | A | 12/17/1999 | 2 | TI | | Y | SNJ54AHC123AJ | 166 |
| 5962-9860801QFA | A | 12/17/1999 | 2 | TI | | Y | SNJ54AHC123AW | 166 |
| 5962-9861101Q2A | | 05/15/1998 | 1 | TI | | Y | SNJ54128FK | 569 |
| 5962-9861101QCA | | 05/15/1998 | 1 | TI | | Y | SNJ54128J | 569 |
| 5962-9861101QDA | | 05/15/1998 | 1 | TI | | Y | SNJ54128W | 569 |
| 5962-9861201QXA | B | 03/18/2003 | 2 | TI | | Y | SMJ320F240HFPM40 | 432 |
| 5962F9861301V9A | E | 01/06/2004 | 2 | INTERSIL | | Y | HS0-139RH-Q | 776 |
| 5962F9861301QCC | E | 01/06/2004 | 2 | INTERSIL | | Y | HS1-139RH-8 | 776 |
| 5962F9861301VCC | E | 01/06/2004 | 2 | INTERSIL | | Y | HS1-139RH-Q | 776 |
| 5962R9861301TCC | E | 01/06/2004 | | (NONE) | 03/23/2003 | | HS-139 (GEN) | 776 |
| 5962F9861301QXC | E | 01/06/2004 | 2 | INTERSIL | | Y | HS9-139RH-8 | 776 |
| 5962F9861301VXC | E | 01/06/2004 | 2 | INTERSIL | | Y | HS9-139RH-Q | 776 |
| 5962R9861301TXC | E | 01/06/2004 | | (NONE) | 03/23/2003 | | HS-139 (GEN) | 776 |
| 5962F9861302V9A | E | 01/06/2004 | 2 | INTERSIL | | Y | HS0-139BRH-Q | 776 |
| 5962F9861302QCC | E | 01/06/2004 | 2 | INTERSIL | | Y | HS1-139BRH-8 | 776 |
| 5962F9861302VCC | E | 01/06/2004 | 2 | INTERSIL | | Y | HS1-139BRH-Q | 776 |
| 5962F9861302QXC | E | 01/06/2004 | 2 | INTERSIL | | Y | HS9-139BRH-8 | 776 |
| 5962F9861302VXC | E | 01/06/2004 | 2 | INTERSIL | | Y | HS9-139BRH-Q | 776 |
| 5962-9861401QRA | | 07/01/1998 | | (NONE) | | | AD977A (GEN) | 592 |
| 5962H9861501QXC | | 06/03/1998 | 3 | BAE SYSTEMS | | Y | LM1M8C3VRH-Q30X | 629 |
| 5962H9861501VXC | | 06/03/1998 | 3 | BAE SYSTEMS | | Y | LM1M8C3VRH-V30X | 629 |
| 5962H9861502QXC | | 06/03/1998 | 3 | BAE SYSTEMS | | Y | LM1M8C3VRH-Q35X | 629 |
| 5962H9861502VXC | | 06/03/1998 | 3 | BAE SYSTEMS | | Y | LM1M8C3VRH-V35X | 629 |
| 5962-9861601Q2A | | 12/20/1999 | 2 | TI | | Y | SNJ54AHCT123AFK | 166 |
| 5962-9861601QEA | | 12/20/1999 | 2 | TI | | Y | SNJ54AHCT123AJ | 166 |
| 5962-9861601QFA | | 12/20/1999 | 2 | TI | | Y | SNJ54AHCT123AW | 166 |
| 5962-9861701Q2A | | 06/15/1998 | 1 | TI | | Y | SNJ54LS06FK | 523 |
| 5962-9861701QCA | | 06/15/1998 | 1 | TI | | Y | SNJ54LS06J | 523 |
| 5962-9861901QKA | | 02/01/1999 | | (NONE) | 03/04/2003 | | 54LVXC3245 (GEN) | 399 |
| 5962-9861901QLA | | 02/01/1999 | | (NONE) | 03/04/2003 | | 54LVXC3245 (GEN) | 399 |
| 5962-9862001QKA | | 02/19/1999 | | (NONE) | 03/04/2003 | | 54LVXC4245 (GEN) | 590 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9862001QLA | | 02/19/1999 | | (NONE) | 03/04/2003 | | 54LVXC4245 (GEN) | 590 |
| 5962-9862101QFA | | 12/21/1998 | | (NONE) | | | 54ACT3301 (GEN) | 422 |
| 5962F9862201V9A | A | 04/13/1999 | | (NONE) | | | ACS11 (GEN) | 112 |
| 5962F9862201VCC | A | 04/13/1999 | | (NONE) | | | ACS11 (GEN) | 112 |
| 5962F9862201VXC | A | 04/13/1999 | | (NONE) | | | ACS11 (GEN) | 112 |
| 5962F9862301V9A | A | 04/05/1999 | | (NONE) | | | ACS14 (GEN) | 143 |
| 5962F9862301VCC | A | 04/05/1999 | 1 | INTERSIL | | Y | ACS14DMSR-03 | 143 |
| 5962F9862301VXC | A | 04/05/1999 | 1 | INTERSIL | | Y | ACS14KMSR-03 | 143 |
| 5962F9862401V9A | A | 04/13/1999 | | (NONE) | | | ACS32 (GEN) | 142 |
| 5962F9862401VCC | A | 04/13/1999 | | (NONE) | 09/14/2003 | | ACS32 (GEN) | 142 |
| 5962F9862401VXC | A | 04/13/1999 | | (NONE) | 09/14/2003 | | ACS32 (GEN) | 142 |
| 5962F9862501V9A | A | 04/05/1999 | | (NONE) | | | ACS132 (GEN) | 109 |
| 5962F9862501VCC | A | 04/05/1999 | | (NONE) | | | ACS132 (GEN) | 109 |
| 5962F9862501VXC | A | 04/05/1999 | | (NONE) | | | ACS132 (GEN) | 109 |
| 5962-9862701Q2A | | 06/30/1998 | 2 | TI | | Y | SNJ54AS74AFK | 158 |
| 5962-9862701QCA | | 06/30/1998 | 2 | TI | | Y | SNJ54AS74AJ | 158 |
| 5962-9862801QPA | | 10/22/1998 | | (NONE) | 03/30/2001 | | LT1126 (GEN) | 710 |
| 5962F9862901V9A | A | 09/13/1999 | | (NONE) | | | ACS21 (GEN) | 114 |
| 5962F9862901VCC | A | 09/13/1999 | | (NONE) | | | ACS21 (GEN) | 114 |
| 5962F9862901VXC | A | 09/13/1999 | | (NONE) | | | ACS21 (GEN) | 114 |
| 5962F9863001V9A | A | 09/13/1999 | | (NONE) | | | ACS27 (GEN) | 122 |
| 5962F9863001VCC | A | 09/13/1999 | | (NONE) | | | ACS27 (GEN) | 122 |
| 5962F9863001VXC | A | 09/13/1999 | | (NONE) | | | ACS27 (GEN) | 122 |
| 5962F9863101V9A | A | 09/13/1999 | | (NONE) | | | ACS30 (GEN) | 106 |
| 5962F9863101VCC | A | 09/13/1999 | | (NONE) | | | ACS30 (GEN) | 106 |
| 5962F9863101VXC | A | 09/13/1999 | | (NONE) | | | ACS30 (GEN) | 106 |
| 5962F9863201V9A | A | 09/13/1999 | | (NONE) | | | ACS109 (GEN) | 152 |
| 5962F9863201VEC | A | 09/13/1999 | | (NONE) | | | ACS109 (GEN) | 152 |
| 5962F9863201VXC | A | 09/13/1999 | | (NONE) | | | ACS109 (GEN) | 152 |
| 5962F9863301V9A | A | 09/13/1999 | | (NONE) | | | ACS147 (GEN) | 345 |
| 5962F9863301VEC | A | 09/13/1999 | | (NONE) | | | ACS147 (GEN) | 345 |
| 5962F9863301VXC | A | 09/13/1999 | | (NONE) | | | ACS147 (GEN) | 345 |
| 5962F9863401V9A | A | 09/13/1999 | | (NONE) | | | ACS174 (GEN) | 159 |
| 5962F9863401VEC | A | 09/13/1999 | | (NONE) | | | ACS174 (GEN) | 159 |
| 5962F9863401VXC | A | 09/13/1999 | | (NONE) | | | ACS174 (GEN) | 159 |
| 5962F9863501V9A | A | 09/13/1999 | | (NONE) | | | ACS175 (GEN) | 152 |
| 5962F9863501VEC | A | 09/13/1999 | | (NONE) | | | ACS175 (GEN) | 152 |
| 5962F9863501VXC | A | 09/13/1999 | | (NONE) | | | ACS175 (GEN) | 152 |
| 5962R9863601VGA | C | 03/07/2003 | 1 | ANALOG (5) | | Y | PM155AJ/QMLR | 703 |
| 5962R9863601VPA | C | 03/07/2003 | 1 | ANALOG (5) | | Y | PM155AZ/QMLR | 703 |
| 5962R9863602VGA | C | 03/07/2003 | 1 | ANALOG (5) | | Y | PM156AJ/QMLR | 703 |
| 5962R9863602VPA | C | 03/07/2003 | 1 | ANALOG (5) | | Y | PM156AZ/QMLR | 703 |
| 5962R9863701VGA | C | 02/28/2003 | 1 | ANALOG (5) | | Y | PM108AJ/QMLR | 721 |
| 5962R9863701VHA | C | 02/28/2003 | 1 | ANALOG (5) | | Y | PM108AL/QMLR | 721 |
| 5962R9863701VPA | C | 02/28/2003 | 1 | ANALOG (5) | | Y | PM108AZ/QMLR | 721 |
| 5962R9863702QCA | C | 02/28/2003 | 1 | NATIONAL | | Y | LM108AJRQML | 721 |
| 5962R9863702VCA | C | 02/28/2003 | 1 | NATIONAL | | Y | LM108AJRQMLV | 721 |
| 5962R9863702QGA | C | 02/28/2003 | 1 | NATIONAL | | Y | LM108AHRQML | 721 |
| 5962R9863702VGA | C | 02/28/2003 | 1 | NATIONAL | | Y | LM108AHRQMLV | 721 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962R9863702QHA | C | 02/28/2003 | 1 | NATIONAL | | Y | LM108AWRQML | 721 |
| 5962R9863702VHA | C | 02/28/2003 | 1 | NATIONAL | | Y | LM108AWRQMLV | 721 |
| 5962R9863702QPA | C | 02/28/2003 | 1 | NATIONAL | | Y | LM108AJ-8RQML | 721 |
| 5962R9863702VPA | C | 02/28/2003 | 1 | NATIONAL | | Y | LM108AJ-8RQMLV | 721 |
| 5962R9863702QZA | C | 02/28/2003 | 1 | NATIONAL | | Y | LM108AWGRQML | 721 |
| 5962R9863702VZA | C | 02/28/2003 | 1 | NATIONAL | | Y | LM108AWGRQMLV | 721 |
| 5962-9863801HUA | | 01/22/1999 | 1 | ADV. ANALOG | | Y | AFL2806.5DW/CH | 594 |
| 5962-9863801HUC | | 01/22/1999 | 1 | ADV. ANALOG | | Y | AFL2806.5DW/CH | 594 |
| 5962-9863801HXA | | 01/22/1999 | 1 | ADV. ANALOG | | Y | AFL2806.5DX/CH | 594 |
| 5962-9863801HXC | | 01/22/1999 | 1 | ADV. ANALOG | | Y | AFL2806.5DX/CH | 594 |
| 5962-9863801HYA | | 01/22/1999 | 1 | ADV. ANALOG | | Y | AFL2806.5DY/CH | 594 |
| 5962-9863801HYC | | 01/22/1999 | 1 | ADV. ANALOG | | Y | AFL2806.5DY/CH | 594 |
| 5962-9863801HZA | | 01/22/1999 | 1 | ADV. ANALOG | | Y | AFL2806.5DZ/CH | 594 |
| 5962-9863801HZC | | 01/22/1999 | 1 | ADV. ANALOG | | Y | AFL2806.5DZ/CH | 594 |
| 5962R9863901V2A | B | 02/20/2003 | 1 | ANALOG (5) | | Y | OP07ARC/QMLR | 701 |
| 5962R9863901VGA | B | 02/20/2003 | 1 | ANALOG (5) | | Y | OP07AJ/QMLR | 701 |
| 5962R9863901VHA | B | 02/20/2003 | 1 | ANALOG (5) | | Y | OP07AL/QMLR | 701 |
| 5962R9863901VPA | B | 02/20/2003 | 1 | ANALOG (5) | | Y | OP07AZ/QMLR | 701 |
| 5962-9864001HNA | | 07/30/1999 | 1 | SOLITRON | | Y | SDP7815ANHD | 782 |
| 5962-9864001HNC | | 07/30/1999 | 1 | SOLITRON | | Y | SDP7815ANHG | 782 |
| 5962-9864001HTA | | 07/30/1999 | 1 | SOLITRON | | Y | SDP7815ATHD | 782 |
| 5962-9864001HTC | | 07/30/1999 | 1 | SOLITRON | | Y | SDP7815ATHG | 782 |
| 5962-9864001HUA | | 07/30/1999 | 1 | SOLITRON | | Y | SDP7815AUHD | 782 |
| 5962-9864001HUC | | 07/30/1999 | 1 | SOLITRON | | Y | SDP7815AUHG | 782 |
| 5962-9864001HZA | | 07/30/1999 | 1 | SOLITRON | | Y | SDP7815AZHD | 782 |
| 5962-9864001HZC | | 07/30/1999 | 1 | SOLITRON | | Y | SDP7815AZHG | 782 |
| 5962-9864101HNA | | 07/30/1999 | 1 | SOLITRON | | Y | SDP7915ANHD | 783 |
| 5962-9864101HNC | | 07/30/1999 | 1 | SOLITRON | | Y | SDP7915ANHG | 783 |
| 5962-9864101HTA | | 07/30/1999 | 1 | SOLITRON | | Y | SDP7915ATHD | 783 |
| 5962-9864101HTC | | 07/30/1999 | 1 | SOLITRON | | Y | SDP7915ATHG | 783 |
| 5962-9864101HUA | | 07/30/1999 | 1 | SOLITRON | | Y | SDP7915AUHD | 783 |
| 5962-9864101HUC | | 07/30/1999 | 1 | SOLITRON | | Y | SDP7915AUHG | 783 |
| 5962-9864101HZA | | 07/30/1999 | 1 | SOLITRON | | Y | SDP7915AZHD | 783 |
| 5962-9864101HZC | | 07/30/1999 | 1 | SOLITRON | | Y | SDP7915AZHG | 783 |
| 5962-9864201HNA | | 07/30/1999 | 1 | SOLITRON | | Y | SDP7905ANHD | 783 |
| 5962-9864201HNC | | 07/30/1999 | 1 | SOLITRON | | Y | SDP7905ANHG | 783 |
| 5962-9864201HTA | | 07/30/1999 | 1 | SOLITRON | | Y | SDP7905ATHD | 783 |
| 5962-9864201HTC | | 07/30/1999 | 1 | SOLITRON | | Y | SDP7905ATHG | 783 |
| 5962-9864201HUA | | 07/30/1999 | 1 | SOLITRON | | Y | SDP7905AUHD | 783 |
| 5962-9864201HUC | | 07/30/1999 | 1 | SOLITRON | | Y | SDP7905AUHG | 783 |
| 5962-9864201HZA | | 07/30/1999 | 1 | SOLITRON | | Y | SDP7905AZHD | 783 |
| 5962-9864201HZC | | 07/30/1999 | 1 | SOLITRON | | Y | SDP7905AZHG | 783 |
| 5962-9864301HNA | | 07/14/1999 | 1 | SOLITRON | | Y | SDP7805ANHD | 782 |
| 5962-9864301HNC | | 07/14/1999 | 1 | SOLITRON | | Y | SDP7805ANHG | 782 |
| 5962-9864301HTA | | 07/14/1999 | 1 | SOLITRON | | Y | SDP7805ATHD | 782 |
| 5962-9864301HTC | | 07/14/1999 | 1 | SOLITRON | | Y | SDP7805ATHG | 782 |
| 5962-9864301HUA | | 07/14/1999 | 1 | SOLITRON | | Y | SDP7805AUHD | 782 |
| 5962-9864301HUC | | 07/14/1999 | 1 | SOLITRON | | Y | SDP7805AUHG | 782 |
| 5962-9864301HZA | | 07/14/1999 | 1 | SOLITRON | | Y | SDP7805AZHD | 782 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9864301HZC | | 07/14/1999 | 1 | SOLITRON | | Y | SDP7805AZHG | 782 |
| 5962H9864401QYC | | 09/03/1998 | 2 | HONEYWELL (1) | | Y | HX6656/NQHC | 659 |
| 5962H9864401VYC | | 09/03/1998 | 2 | HONEYWELL (1) | | Y | HX6656/NVHC | 659 |
| 5962H9864401QZC | | 09/03/1998 | 2 | HONEYWELL (1) | | Y | HX6656/XQHC | 659 |
| 5962H9864401VZC | | 09/03/1998 | 2 | HONEYWELL (1) | | Y | HX6656/XVHC | 659 |
| 5962H9864402QYC | | 09/03/1998 | 2 | HONEYWELL (1) | | Y | HX6656/NQHT | 659 |
| 5962H9864402VYC | | 09/03/1998 | 2 | HONEYWELL (1) | | Y | HX6656/NVHT | 659 |
| 5962H9864402QZC | | 09/03/1998 | 2 | HONEYWELL (1) | | Y | HX6656/XQHT | 659 |
| 5962H9864402VZC | | 09/03/1998 | 2 | HONEYWELL (1) | | Y | HX6656/XVHT | 659 |
| 5962-9864501QCA | A | 02/20/2003 | 1 | INTERSIL | 10/03/2004 | Y | HA1-4741/883 | 713 |
| 5962-9864601QEA | A | 02/10/2003 | 2 | ANALOG (2) | | Y | AD8306A/QML | 899 |
| 5962-9864701HNA | | 07/14/1999 | 1 | SOLITRON | | Y | SDP1083NHD | 780 |
| 5962-9864701HNC | | 07/14/1999 | 1 | SOLITRON | | Y | SDP1083NHG | 780 |
| 5962-9864701HTA | | 07/14/1999 | 1 | SOLITRON | | Y | SDP1083THD | 780 |
| 5962-9864701HTC | | 07/14/1999 | 1 | SOLITRON | | Y | SDP1083THG | 780 |
| 5962-9864701HUA | | 07/14/1999 | 1 | SOLITRON | | Y | SDP1083UHD | 780 |
| 5962-9864701HUC | | 07/14/1999 | 1 | SOLITRON | | Y | SDP1083UHG | 780 |
| 5962-9864701HZA | | 07/14/1999 | 1 | SOLITRON | | Y | SDP1083ZHD | 780 |
| 5962-9864701HZC | | 07/14/1999 | 1 | SOLITRON | | Y | SDP1083ZHG | 780 |
| 5962-9864801HNA | | 07/14/1999 | 1 | SOLITRON | | Y | SDP1084NHD | 780 |
| 5962-9864801HNC | | 07/14/1999 | 1 | SOLITRON | | Y | SDP1084NHG | 780 |
| 5962-9864801HTA | | 07/14/1999 | 1 | SOLITRON | | Y | SDP1084THD | 780 |
| 5962-9864801HTC | | 07/14/1999 | 1 | SOLITRON | | Y | SDP1084THG | 780 |
| 5962-9864801HUA | | 07/14/1999 | 1 | SOLITRON | | Y | SDP1084UHD | 780 |
| 5962-9864801HUC | | 07/14/1999 | 1 | SOLITRON | | Y | SDP1084UHG | 780 |
| 5962-9864801HZA | | 07/14/1999 | 1 | SOLITRON | | Y | SDP1084ZHD | 780 |
| 5962-9864801HZC | | 07/14/1999 | 1 | SOLITRON | | Y | SDP1084ZHG | 780 |
| 5962-9864901HNA | A | 08/27/2002 | 1 | SOLITRON | | Y | SDP1085NHD | 780 |
| 5962-9864901HNC | A | 08/27/2002 | 1 | SOLITRON | | Y | SDP1085NHG | 780 |
| 5962-9864901HTA | A | 08/27/2002 | 1 | SOLITRON | | Y | SDP1085THD | 780 |
| 5962-9864901HTC | A | 08/27/2002 | 1 | SOLITRON | | Y | SDP1085THG | 780 |
| 5962-9864901HUA | A | 08/27/2002 | 1 | SOLITRON | | Y | SDP1085UHD | 780 |
| 5962-9864901HUC | A | 08/27/2002 | 1 | SOLITRON | | Y | SDP1085UHG | 780 |
| 5962-9864901HZA | A | 08/27/2002 | 1 | SOLITRON | | Y | SDP1085ZHD | 780 |
| 5962-9864901HZC | A | 08/27/2002 | 1 | SOLITRON | | Y | SDP1085ZHG | 780 |
| 5962-9865001HNA | | 06/10/1999 | 1 | SOLITRON | | Y | SDP1086NHD | 780 |
| 5962-9865001HNC | | 06/10/1999 | 1 | SOLITRON | | Y | SDP1086NHG | 780 |
| 5962-9865001HTA | | 06/10/1999 | 1 | SOLITRON | | Y | SDP1086THD | 780 |
| 5962-9865001HTC | | 06/10/1999 | 1 | SOLITRON | | Y | SDP1086THG | 780 |
| 5962-9865001HUA | | 06/10/1999 | 1 | SOLITRON | | Y | SDP1086UHD | 780 |
| 5962-9865001HUC | | 06/10/1999 | 1 | SOLITRON | | Y | SDP1086UHG | 780 |
| 5962-9865001HZA | | 06/10/1999 | 1 | SOLITRON | | Y | SDP1086ZHD | 780 |
| 5962-9865001HZC | | 06/10/1999 | 1 | SOLITRON | | Y | SDP1086ZHG | 780 |
| 5962-9865101QFA | F | 08/25/2004 | 3 | NATIONAL | | Y | DS90LV031AW-QML | 564 |
| 5962-9865101QXA | F | 08/25/2004 | 3 | NATIONAL | | Y | DS90LV031AWGQML | 564 |
| 5962H9865102Q9A | F | 08/25/2004 | 1 | UTMC | | Y | UT54LVDS031LV_QDIE | 564 |
| 5962H9865102V9A | F | 08/25/2004 | 1 | UTMC | | Y | UT54LVDS031LV_VDIE | 564 |
| 5962H9865102QYA | F | 08/25/2004 | 1 | UTMC | | Y | UT54LVDS031LVUCA | 564 |
| 5962H9865102QYC | F | 08/25/2004 | 1 | UTMC | | Y | UT54LVDS031LVUCC | 564 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962H9865102VYA | F | 08/25/2004 | 1 | UTMC | | Y | UT54LVDS031LVUCA | 564 |
| 5962H9865102VYC | F | 08/25/2004 | 1 | UTMC | | Y | UT54LVDS031LVUCC | 564 |
| 5962R9865103Q9A | F | 08/25/2004 | 1 | UTMC | | Y | UT54LVDS031LV_QDIE | 564 |
| 5962R9865103V9A | F | 08/25/2004 | 1 | UTMC | | Y | UT54LVDS031LV_VDIE | 564 |
| 5962R9865103QYA | F | 08/25/2004 | 1 | UTMC | | Y | UT54LVDS031LVUCA | 564 |
| 5962R9865103QYC | F | 08/25/2004 | 1 | UTMC | | Y | UT54LVDS031LVUCC | 564 |
| 5962R9865103VYA | F | 08/25/2004 | 1 | UTMC | | Y | UT54LVDS031LVUCA | 564 |
| 5962R9865103VYC | F | 08/25/2004 | 1 | UTMC | | Y | UT54LVDS031LVUCC | 564 |
| 5962H9865104Q9A | F | 08/25/2004 | 1 | UTMC | | Y | UT54LVDS031LVE_QDI | 564 |
| 5962H9865104V9A | F | 08/25/2004 | 1 | UTMC | | Y | UT54LVDS031LVE_VDI | 564 |
| 5962H9865104QYA | F | 08/25/2004 | 1 | UTMC | | Y | UT54LVDS031LVEUCA | 564 |
| 5962H9865104QYC | F | 08/25/2004 | 1 | UTMC | | Y | UT54LVDS031LVEUCC | 564 |
| 5962H9865104VYA | F | 08/25/2004 | 1 | UTMC | | Y | UT54LVDS031LVEUCA | 564 |
| 5962H9865104VYC | F | 08/25/2004 | 1 | UTMC | | Y | UT54LVDS031LVEUCC | 564 |
| 5962R9865105Q9A | F | 08/25/2004 | 1 | UTMC | | Y | UT54LVDS031LVE_QDI | 564 |
| 5962R9865105V9A | F | 08/25/2004 | 1 | UTMC | | Y | UT54LVDS031LVE_VDI | 564 |
| 5962R9865105QYA | F | 08/25/2004 | 1 | UTMC | | Y | UT54LVDS031LVEUCA | 564 |
| 5962R9865105QYC | F | 08/25/2004 | 1 | UTMC | | Y | UT54LVDS031LVEUCC | 564 |
| 5962R9865105VYA | F | 08/25/2004 | 1 | UTMC | | Y | UT54LVDS031LVEUCA | 564 |
| 5962R9865105VYC | F | 08/25/2004 | 1 | UTMC | | Y | UT54LVDS031LVEUCC | 564 |
| 5962-9865201QFA | D | 08/25/2004 | 3 | NATIONAL | | Y | DS90LV032AW-QML | 575 |
| 5962-9865201QXA | D | 08/25/2004 | 3 | NATIONAL | | Y | DS90LV032AWGQML | 575 |
| 5962H9865202Q9A | D | 08/25/2004 | 1 | UTMC | | Y | UT54LVDS032LV_QDIE | 575 |
| 5962H9865202V9A | D | 08/25/2004 | 1 | UTMC | | Y | UT54LVDS032LV_VDIE | 575 |
| 5962H9865202QYA | D | 08/25/2004 | 1 | UTMC | | Y | UT54LVDS032LVUCA | 575 |
| 5962H9865202QYC | D | 08/25/2004 | 1 | UTMC | | Y | UT54LVDS032LVUCC | 575 |
| 5962H9865202VYA | D | 08/25/2004 | 1 | UTMC | | Y | UT54LVDS032LVUCA | 575 |
| 5962H9865202VYC | D | 08/25/2004 | 1 | UTMC | | Y | UT54LVDS032LVUCC | 575 |
| 5962R9865203Q9A | D | 08/25/2004 | 1 | UTMC | | Y | UT54LVDS032LV_QDIE | 575 |
| 5962R9865203V9A | D | 08/25/2004 | 1 | UTMC | | Y | UT54LVDS032LV_VDIE | 575 |
| 5962R9865203QYA | D | 08/25/2004 | 1 | UTMC | | Y | UT54LVDS032LVUCA | 575 |
| 5962R9865203QYC | D | 08/25/2004 | 1 | UTMC | | Y | UT54LVDS032LVUCC | 575 |
| 5962R9865203VYA | D | 08/25/2004 | 1 | UTMC | | Y | UT54LVDS032LVUCA | 575 |
| 5962R9865203VYC | D | 08/25/2004 | 1 | UTMC | | Y | UT54LVDS032LVUCC | 575 |
| 5962H9865204Q9A | D | 08/25/2004 | 1 | UTMC | | Y | UT54LVDS032LVE_QDI | 575 |
| 5962H9865204V9A | D | 08/25/2004 | 1 | UTMC | | Y | UT54LVDS032LVE_VDI | 575 |
| 5962H9865204QYA | D | 08/25/2004 | 1 | UTMC | | Y | UT54LVDS032LVEUCA | 575 |
| 5962H9865204QYC | D | 08/25/2004 | 1 | UTMC | | Y | UT54LVDS032LVEUCC | 575 |
| 5962H9865204VYA | D | 08/25/2004 | 1 | UTMC | | Y | UT54LVDS032LVEUCA | 575 |
| 5962H9865204VYC | D | 08/25/2004 | 1 | UTMC | | Y | UT54LVDS032LVEUCC | 575 |
| 5962R9865205Q9A | D | 08/25/2004 | 1 | UTMC | | Y | UT54LVDS032LVE_QDI | 575 |
| 5962R9865205V9A | D | 08/25/2004 | 1 | UTMC | | Y | UT54LVDS032LVE_VDI | 575 |
| 5962R9865205QYA | D | 08/25/2004 | 1 | UTMC | | Y | UT54LVDS032LVEUCA | 575 |
| 5962R9865205QYC | D | 08/25/2004 | 1 | UTMC | | Y | UT54LVDS032LVEUCC | 575 |
| 5962R9865205VYA | D | 08/25/2004 | 1 | UTMC | | Y | UT54LVDS032LVEUCA | 575 |
| 5962R9865205VYC | D | 08/25/2004 | 1 | UTMC | | Y | UT54LVDS032LVEUCC | 575 |
| 5962-9865501QJA | | 09/18/1998 | 1 | TI | | Y | CD54HC4514F3A | 280 |
| 5962-9865901HXA | | 06/18/2001 | | (NONE) | 08/29/2003 | | AD10265 (GEN) | 592 |
| 5962-9866101QXA | C | 07/06/2004 | 2 | TI | | Y | SMJ320C6701W14 | 432 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9866101VXA | C | 07/06/2004 | 2 | TI | | Y | SMV320C6701GLPW14 | 432 |
| 5962-9866102QXA | C | 07/06/2004 | | (NONE) | | | 320C6701 (GEN) | 432 |
| 5962-9866102VXA | C | 07/06/2004 | 2 | TI | | Y | SMV320C6701GLPM14 | 432 |
| 5962-98A0101QXC | | 12/05/1997 | 1 | AMI | | Y | 5353-035 | 365 |
| 5962-98A0201QXC | | 11/18/1997 | 3 | AMI | | Y | 6580-046 | 365 |
| 5962-98A0301QXC | A | 02/25/1998 | 3 | AMI | | Y | 6721-052 | 365 |
| 5962-98A0401QXC | | 12/29/1997 | 3 | AMI | | Y | 6580-045 | 365 |
| 5962-98A0501QXC | | 12/22/1997 | 1 | AMI | | Y | 5352-044 | 365 |
| 5962-98A0601QXC | | 02/10/1998 | 3 | AMI | | Y | 6580-028 | 365 |
| 5962-98A0701QXC | A | 10/14/1998 | 3 | AMI | | Y | 6580-063 | 365 |
| 5962-98A0801QXC | A | 09/29/1998 | 3 | AMI | | Y | 6565-041 | 365 |
| 5962-98A0901NXB | | 03/10/1998 | 3 | AMI | | Y | 6580-029 | 365 |
| 5962-98A1001QXC | | 03/11/1998 | 3 | AMI | | Y | 6580-530 | 365 |
| 5962-98A1101QXC | B | 05/17/1999 | 1 | AMI | | Y | 11155-001 | 365 |
| 5962-98A1201QXC | B | 12/08/1999 | 3 | AMI | | Y | 6580-057 | 365 |
| 5962-98A1301QXC | | 06/02/1998 | 3 | AMI | | Y | 6580-031 | 365 |
| 5962-98A1401QXC | | 06/01/1998 | 3 | AMI | | Y | 6580-032 | 365 |
| 5962-98A1501NXB | | 06/02/1998 | 3 | AMI | | Y | 6580-033 | 365 |
| 5962-98A1601VXA | | 10/22/1998 | | (NONE) | 03/31/2000 | | BXM-100 (GEN) | 365 |
| 5962-98A1701VXA | | 10/22/1998 | | (NONE) | 03/31/2000 | | BXM-300 (GEN) | 365 |
| 5962-98A1702VXA | | 10/22/1998 | | (NONE) | 03/31/2000 | | BXM-300A (GEN) | 365 |
| 5962-98A1801VXA | | 08/27/1999 | | (NONE) | 03/31/2000 | | BXM-400A (GEN) | 365 |
| 5962-98A1901QXC | | 08/27/1998 | 3 | AMI | | Y | 6580-050 | 365 |
| 5962-98A1901QYC | | 08/27/1998 | 3 | AMI | | Y | 6580-051 | 365 |
| 5962-98A2001QXC | | 08/18/1998 | 1 | AMI | | Y | 6580-526 | 365 |
| 5962-98A2101QXC | B | 06/23/2003 | 3 | AMI | | Y | 6583-508 | 365 |
| 5962-98A2102QXC | B | 06/23/2003 | 3 | AMI | | Y | 6583-512 | 365 |
| 5962-98A2201QXC | | 07/30/1998 | 1 | AMI | | Y | 9880-026 | 365 |
| 5962H98A2301QTC | A | 10/22/2002 | 1 | HONEYWELL (1) | | Y | 22021752-012 | 365 |
| 5962H98A2302QTC | A | 10/22/2002 | 1 | HONEYWELL (1) | | Y | 22021752-050 | 365 |
| 5962H98A2401QTC | A | 10/22/2002 | 1 | HONEYWELL (1) | | Y | 22021540-012 | 365 |
| 5962H98A2402QTC | A | 10/22/2002 | 1 | HONEYWELL (1) | | Y | 22021540-050 | 365 |
| 5962H98A2501QXC | B | 10/08/2003 | 1 | HONEYWELL (1) | | Y | 22021745-012 | 365 |
| 5962H98A2502QXC | B | 10/08/2003 | 1 | HONEYWELL (1) | | Y | 22021745-050 | 365 |
| 5962H98A2601QTC | B | 10/22/2002 | 1 | HONEYWELL (1) | | Y | 22022979-012 | 365 |
| 5962H98A2602QTC | B | 10/22/2002 | 1 | HONEYWELL (1) | | Y | 22022979-050 | 365 |
| 5962H98A2701QTC | A | 10/22/2002 | 1 | HONEYWELL (1) | | Y | 22021730-012 | 365 |
| 5962H98A2702QTC | A | 10/22/2002 | 1 | HONEYWELL (1) | | Y | 22021730-050 | 365 |
| 5962H98A2801QXC | A | 04/09/2001 | 1 | HONEYWELL (1) | | Y | 22021806-012 | 365 |
| 5962H98A2802QXC | A | 04/09/2001 | 1 | HONEYWELL (1) | | Y | 22021806-050 | 365 |
| 5962H98A2901QXC | A | 05/01/2002 | 1 | HONEYWELL (1) | | Y | 22021812-012 | 365 |
| 5962H98A2902QXC | A | 05/01/2002 | 1 | HONEYWELL (1) | | Y | 22021812-050 | 365 |
| 5962H98A3001QXC | | 06/03/1999 | 1 | HONEYWELL (1) | | Y | 22021718-012 | 365 |
| 5962H98A3002QXC | | 06/03/1999 | 1 | HONEYWELL (1) | | Y | 22021718-050 | 365 |
| 5962H98A3101QXC | A | 11/01/2001 | 1 | HONEYWELL (1) | | Y | 22021712-012 | 365 |
| 5962H98A3102QXC | A | 11/01/2001 | 1 | HONEYWELL (1) | | Y | 22021712-050 | 365 |
| 5962H98A3201QTC | C | 10/08/2003 | 1 | HONEYWELL (1) | | Y | 22022600-012 | 365 |
| 5962H98A3201QXC | C | 10/08/2003 | 1 | HONEYWELL (1) | | Y | 22022256-012 | 365 |
| 5962H98A3202QTC | C | 10/08/2003 | 1 | HONEYWELL (1) | | Y | 22022600-050 | 365 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962H98A3202QXC | C | 10/08/2003 | 1 | HONEYWELL (1) | | Y | 22022256-050 | 365 |
| 5962-98A3301QXC | | 08/19/1998 | 1 | AMI | | Y | 6580-527 | 365 |
| 5962-9950101QPA | A | 04/13/1999 | | (NONE) | 03/30/2001 | | LTC1150 (GEN) | 719 |
| 5962-9950201QGA | | 11/05/1998 | | (NONE) | 03/30/2001 | | LT1077 (GEN) | 701 |
| 5962-9950201QPA | | 11/05/1998 | | (NONE) | 03/30/2001 | | LT1077 (GEN) | 701 |
| 5962-9950301QPA | | 03/10/1999 | | (NONE) | 03/30/2001 | | LT1101 (GEN) | 754 |
| 5962L9950401VCA | D | 10/15/2003 | | (NONE) | | | LM124A (GEN) | 713 |
| 5962R9950401QCA | D | 10/15/2003 | | (NONE) | | | LM124A (GEN) | 713 |
| 5962R9950401VCA | D | 10/15/2003 | 1 | NATIONAL | | Y | LM124AJRQMLV | 713 |
| 5962L9950401VDA | D | 10/15/2003 | | (NONE) | | | LM124A (GEN) | 713 |
| 5962R9950401QDA | D | 10/15/2003 | | (NONE) | | | LM124A (GEN) | 713 |
| 5962R9950401VDA | D | 10/15/2003 | 1 | NATIONAL | | Y | LM124AWRQMLV | 713 |
| 5962L9950401VZA | D | 10/15/2003 | | (NONE) | | | LM124A (GEN) | 713 |
| 5962R9950401QZA | D | 10/15/2003 | | (NONE) | | | LM124A (GEN) | 713 |
| 5962R9950401VZA | D | 10/15/2003 | 1 | NATIONAL | | Y | LM124AWGRQMLV | 713 |
| 5962-9950501QXA | | 04/22/1999 | | (NONE) | 03/04/2003 | | 54LCX16244 (GEN) | 509 |
| 5962-9950601QKA | | 05/25/1999 | | (NONE) | 03/04/2003 | | 54LVX3383 (GEN) | 399 |
| 5962-9950601QLA | | 05/25/1999 | | (NONE) | 03/04/2003 | | 54LVX3383 (GEN) | 399 |
| 5962-9950701QKA | | 04/22/1999 | | (NONE) | 03/04/2003 | | 54LVX3384 (GEN) | 399 |
| 5962-9950701QLA | | 04/22/1999 | | (NONE) | 03/04/2003 | | 54LVX3384 (GEN) | 399 |
| 5962-9950801Q2A | | 03/25/1999 | 3 | TI | | Y | SNJ54LVTH240FK | 529 |
| 5962-9950801QRA | | 03/25/1999 | 3 | TI | | Y | SNJ54LVTH240J | 529 |
| 5962-9950801QSA | | 03/25/1999 | 3 | TI | | Y | SNJ54LVTH240W | 529 |
| 5962-9950901Q2A | | 05/04/2001 | 3 | TI | | Y | SNJ54LVTH373FK | 342 |
| 5962-9950901QRA | | 05/04/2001 | 3 | TI | | Y | SNJ54LVTH373J | 342 |
| 5962-9950901QSA | | 05/04/2001 | 3 | TI | | Y | SNJ54LVTH373W | 342 |
| 5962-9951001Q2A | | 05/01/2001 | 3 | TI | | Y | SNJ54LVTH374FK | 159 |
| 5962-9951001QRA | | 05/01/2001 | 3 | TI | | Y | SNJ54LVTH374J | 159 |
| 5962-9951001QSA | | 05/01/2001 | 3 | TI | | Y | SNJ54LVTH374W | 159 |
| 5962F9951101V9A | B | 06/02/1999 | 3 | INTERSIL | | Y | HS0-4423RH-Q | 519 |
| 5962F9951101QXC | B | 06/02/1999 | 3 | INTERSIL | | Y | HS9-4423RH-8 | 519 |
| 5962F9951101VXC | B | 06/02/1999 | 3 | INTERSIL | | Y | HS9-4423RH-Q | 519 |
| 5962R9951101TXC | B | 06/02/1999 | 3 | INTERSIL | | Y | HS9-4423RH-T | 519 |
| 5962F9951102V9A | B | 06/02/1999 | 3 | INTERSIL | | Y | HS0-4423BRH-Q | 519 |
| 5962F9951102QXC | B | 06/02/1999 | 3 | INTERSIL | | Y | HS9-4423BRH-8 | 519 |
| 5962F9951102VXC | B | 06/02/1999 | 3 | INTERSIL | | Y | HS9-4423BRH-Q | 519 |
| 5962R9951102TXC | B | 06/02/1999 | | (NONE) | 03/23/2003 | | HS-4423B (GEN) | 519 |
| 5962-9951401NXB | A | 09/04/2001 | 3 | XILINX | | Y | XQ1701L-SO20N | 669 |
| 5962-9951401QYA | A | 09/04/2001 | 3 | XILINX | | Y | XQ1701L-CC44B | 669 |
| 5962-9951501VGA | B | 07/18/2002 | 2 | NATIONAL | | Y | LM101AH-QMLV | 700 |
| 5962R9951501QGA | B | 07/18/2002 | | (NONE) | | | LM101A (GEN) | 700 |
| 5962R9951501VGA | B | 07/18/2002 | 2 | NATIONAL | | Y | LM101AHRQMLV | 700 |
| 5962-9951501VHA | B | 07/18/2002 | 2 | NATIONAL | | Y | LM101AW-QMLV | 700 |
| 5962R9951501QHA | B | 07/18/2002 | | (NONE) | | | LM101A (GEN) | 700 |
| 5962R9951501VHA | B | 07/18/2002 | 2 | NATIONAL | | Y | LM101AWRQMLV | 700 |
| 5962-9951501VPA | B | 07/18/2002 | 2 | NATIONAL | | Y | LM101AJ-QMLV | 700 |
| 5962R9951501QPA | B | 07/18/2002 | | (NONE) | | | LM101A (GEN) | 700 |
| 5962R9951501VPA | B | 07/18/2002 | | (NONE) | | | LM101A (GEN) | 700 |
| 5962P9951701QXA | G | 09/05/2002 | | (NONE) | | | LM137 (GEN) | 781 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962P9951701VXA | G | 09/05/2002 | 3 | NATIONAL | | Y | LM137HPQMLV | 781 |
| 5962-9951701VZA | G | 09/05/2002 | 3 | NATIONAL | | Y | LM137WG-QMLV | 781 |
| 5962P9951701QZA | G | 09/05/2002 | | (NONE) | | | LM137 (GEN) | 781 |
| 5962P9951701VZA | G | 09/05/2002 | | (NONE) | | | LM137 (GEN) | 781 |
| 5962P9951702QYA | G | 09/05/2002 | | (NONE) | | | LM137 (GEN) | 781 |
| 5962P9951702VYA | G | 09/05/2002 | 3 | NATIONAL | | Y | LM137KPQMLV | 781 |
| 5962R9951703QXA | G | 09/05/2002 | | (NONE) | | | LM117 (GEN) | 780 |
| 5962R9951703VXA | G | 09/05/2002 | 2 | NATIONAL | | Y | LM117HRQMLV | 780 |
| 5962-9951703VZA | G | 09/05/2002 | 2 | NATIONAL | | Y | LM117WG-QMLV | 780 |
| 5962R9951703QZA | G | 09/05/2002 | | (NONE) | | | LM117 (GEN) | 780 |
| 5962R9951703VZA | G | 09/05/2002 | 2 | NATIONAL | | Y | LM117WGRQMLV | 780 |
| 5962R9951704QYA | G | 09/05/2002 | | (NONE) | | | LM117 (GEN) | 780 |
| 5962R9951704VYA | G | 09/05/2002 | 2 | NATIONAL | | Y | LM117KRQMLV | 780 |
| 5962-9951801HUA | | 12/17/1998 | 1 | ADV. ANALOG | | Y | AFL27012DW/CH | 594 |
| 5962-9951801HUC | | 12/17/1998 | 1 | ADV. ANALOG | | Y | AFL27012DW/CH | 594 |
| 5962-9951801HXA | | 12/17/1998 | 1 | ADV. ANALOG | | Y | AFL27012DX/CH | 594 |
| 5962-9951801HXC | | 12/17/1998 | 1 | ADV. ANALOG | | Y | AFL27012DX/CH | 594 |
| 5962-9951801HYA | | 12/17/1998 | 1 | ADV. ANALOG | | Y | AFL27012DY/CH | 594 |
| 5962-9951801HYC | | 12/17/1998 | 1 | ADV. ANALOG | | Y | AFL27012DY/CH | 594 |
| 5962-9951801HZA | | 12/17/1998 | 1 | ADV. ANALOG | | Y | AFL27012DZ/CH | 594 |
| 5962-9951801HZC | | 12/17/1998 | 1 | ADV. ANALOG | | Y | AFL27012DZ/CH | 594 |
| 5962-9951901QYA | A | 08/27/2001 | | (NONE) | 08/03/2001 | | CY37064-125 (GEN) | 380 |
| 5962-9951902QYA | A | 08/27/2001 | 2 | CYPRESS | | Y | CY37064P44-154YMB | 380 |
| 5962-9952001QYA | A | 08/27/2001 | 2 | CYPRESS | | Y | CY37064VP44-100YMB | 380 |
| 5962-9952101QYA | A | 12/01/2000 | 2 | CYPRESS | | Y | CY37128P84-100YMB | 380 |
| 5962-9952102QYA | A | 12/01/2000 | 2 | CYPRESS | | Y | CY37128P84-125YMB | 380 |
| 5962-9952201QYA | A | 08/27/2001 | 2 | CYPRESS | | Y | CY37128VP84-83YMB | 380 |
| 5962-9952301QZC | A | 06/05/2001 | 2 | CYPRESS | | Y | CY37256P160-83UMB | 380 |
| 5962-9952302QZC | A | 06/05/2001 | 2 | CYPRESS | | Y | CY37256P160-125UMB | 380 |
| 5962-9952401QZC | A | 06/05/2001 | 2 | CYPRESS | | Y | CY37256VP160-66UMB | 380 |
| 5962-9952501QZC | B | 06/05/2001 | 2 | CYPRESS | | Y | CY37512P208-83UMB | 380 |
| 5962-9952502QZC | B | 06/05/2001 | 2 | CYPRESS | | Y | CY37512P208-100UMB | 380 |
| 5962-9952601QZC | | 12/04/2000 | 2 | CYPRESS | | Y | CY37512VP208-66UMB | 380 |
| 5962-9952701Q9A | | 01/22/1999 | 1 | ACTEL | | Y | A32200DX-DIE | 381 |
| 5962-9952701QXC | | 01/22/1999 | 1 | ACTEL | | Y | A32200DX-CQ256B | 381 |
| 5962-9952701QYC | | 01/22/1999 | 1 | ACTEL | | Y | A32200DX-CQ208B | 381 |
| 5962-9952702QXC | | 01/22/1999 | 1 | ACTEL | | Y | A32200DX-1CQ256B | 381 |
| 5962-9952702QYC | | 01/22/1999 | 1 | ACTEL | | Y | A32200DX-1CQ208B | 381 |
| 5962-9953101MMA | B | 02/11/2002 | 1 | INTER. RECT. | | | OM3958SM/883B | 782 |
| 5962-9953101MNA | B | 02/11/2002 | 1 | INTER. RECT. | | | OM3958NM/883B | 782 |
| 5962-9953101MTA | B | 02/11/2002 | 1 | INTER. RECT. | | | OM3958SRM | 782 |
| 5962-9953101MUA | B | 02/11/2002 | 1 | INTER. RECT. | | | OM3958ST/883B | 782 |
| 5962P9953101MUA | B | 02/11/2002 | 1 | INTER. RECT. | | | OMR3958STM/883B | 782 |
| 5962-9953101MXA | B | 02/11/2002 | 1 | INTER. RECT. | | | OM3958N5M | 782 |
| 5962-9953201QJA | | 07/15/1999 | 1 | SARNOFF | | Y | GEM24501QJA | 305 |
| 5962-9953201QJC | | 07/15/1999 | 1 | SARNOFF | | Y | GEM24501QJC | 305 |
| 5962-9953201QKA | | 07/15/1999 | 1 | SARNOFF | | Y | GEM24501QKA | 305 |
| 5962-9953201QKC | | 07/15/1999 | 1 | SARNOFF | | Y | GEM24501QKC | 305 |
| 5962-9953201QLA | | 07/15/1999 | 1 | SARNOFF | | Y | GEM24501QLA | 305 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9953201QLC | | 07/15/1999 | 1 | SARNOFF | | Y | GEM24501QLC | 305 |
| 5962-9953401QXA | | 06/04/1999 | | (NONE) | 03/04/2003 | | 54LCX16373 (GEN) | 342 |
| 5962-9953501QXA | | 06/17/1999 | | (NONE) | 03/04/2003 | | 54LCX16374 (GEN) | 158 |
| 5962F9953601V9A | E | 04/15/2003 | | (NONE) | | | HS0-2100 (GEN) | 599 |
| 5962F9953601QXC | E | 04/15/2003 | | (NONE) | 01/07/2003 | | HS9-2100 (GEN) | 599 |
| 5962F9953601VXC | E | 04/15/2003 | | (NONE) | 01/07/2003 | | HS9-2100 (GEN) | 599 |
| 5962R9953601TXC | E | 04/15/2003 | | (NONE) | | | HS9-2100 (GEN) | 599 |
| 5962F9953602V9A | E | 04/15/2003 | 1 | INTERSIL | | Y | IS0-2100ARH-Q | 599 |
| 5962F9953602QXC | E | 04/15/2003 | 1 | INTERSIL | | Y | IS9-2100ARH-8 | 599 |
| 5962F9953602VXC | E | 04/15/2003 | 1 | INTERSIL | | Y | IS9-2100ARH-Q | 599 |
| 5962-9953901QXC | A | 05/29/2002 | 2 | ATMEL NANTES | | Y | TSC21020F-20MBMQ | 432 |
| 5962-9953901VXC | A | 05/29/2002 | 2 | ATMEL NANTES | | Y | TSC21020F-20SBSV | 432 |
| 5962-9954001NXD | A | 05/10/2002 | 3 | TI | | Y | TLC876MDW | 592 |
| 5962H9954101QXC | | 05/26/1999 | 3 | BAE SYSTEMS | | Y | LM2M8CRH-Q40X | 629 |
| 5962H9954101VXC | | 05/26/1999 | 3 | BAE SYSTEMS | | Y | LM2M8CRH-V40X | 629 |
| 5962H9954102QXC | | 05/26/1999 | 3 | BAE SYSTEMS | | Y | LM2M8TRH-Q40X | 629 |
| 5962H9954102VXC | | 05/26/1999 | 3 | BAE SYSTEMS | | Y | LM2M8TRH-V40X | 629 |
| 5962H9954103QXC | | 05/26/1999 | 3 | BAE SYSTEMS | | Y | LM2M8CRH-Q30X | 629 |
| 5962H9954103VXC | | 05/26/1999 | 3 | BAE SYSTEMS | | Y | LM2M8CRH-V30X | 629 |
| 5962H9954104QXC | | 05/26/1999 | 3 | BAE SYSTEMS | | Y | LM2M8TRH-Q30X | 629 |
| 5962H9954104VXC | | 05/26/1999 | 3 | BAE SYSTEMS | | Y | LM2M8TRH-V30X | 629 |
| 5962H9954105QXC | | 05/26/1999 | 3 | BAE SYSTEMS | | Y | LM2M8CRH-Q25X | 629 |
| 5962H9954105VXC | | 05/26/1999 | 3 | BAE SYSTEMS | | Y | LM2M8CRH-V25X | 629 |
| 5962H9954106QXC | | 05/26/1999 | 3 | BAE SYSTEMS | | Y | LM2M8TRH-Q25X | 629 |
| 5962H9954106VXC | | 05/26/1999 | 3 | BAE SYSTEMS | | Y | LM2M8TRH-V25X | 629 |
| 5962-9954401HTA | A | 05/28/2003 | 1 | INTERPOINT | | Y | MOR283R3SW/883 | 594 |
| 5962-9954401HTC | A | 05/28/2003 | 1 | INTERPOINT | | Y | MOR283R3SW/883 | 594 |
| 5962-9954401HUA | A | 05/28/2003 | 1 | INTERPOINT | | Y | MOR283R3SV/883 | 594 |
| 5962-9954401HUC | A | 05/28/2003 | 1 | INTERPOINT | | Y | MOR283R3SV/883 | 594 |
| 5962-9954401HXA | A | 05/28/2003 | 1 | INTERPOINT | | Y | MOR283R3S/883 | 594 |
| 5962-9954401HXC | A | 05/28/2003 | 1 | INTERPOINT | | Y | MOR283R3S/883 | 594 |
| 5962-9954401HYA | A | 05/28/2003 | 1 | INTERPOINT | | Y | MOR283R3SY/883 | 594 |
| 5962-9954401HYC | A | 05/28/2003 | 1 | INTERPOINT | | Y | MOR283R3SY/883 | 594 |
| 5962-9954401HZA | A | 05/28/2003 | 1 | INTERPOINT | | Y | MOR283R3SZ/883 | 594 |
| 5962-9954401HZC | A | 05/28/2003 | 1 | INTERPOINT | | Y | MOR283R3SZ/883 | 594 |
| 5962-9954501HTA | A | 05/28/2003 | 1 | INTERPOINT | | Y | MOR286R3SW/883 | 594 |
| 5962-9954501HTC | A | 05/28/2003 | 1 | INTERPOINT | | Y | MOR286R3SW/883 | 594 |
| 5962-9954501HUA | A | 05/28/2003 | 1 | INTERPOINT | | Y | MOR286R3SV/883 | 594 |
| 5962-9954501HUC | A | 05/28/2003 | 1 | INTERPOINT | | Y | MOR286R3SV/883 | 594 |
| 5962-9954501HXA | A | 05/28/2003 | 1 | INTERPOINT | | Y | MOR286R3S/883 | 594 |
| 5962-9954501HXC | A | 05/28/2003 | 1 | INTERPOINT | | Y | MOR286R3S/883 | 594 |
| 5962-9954501HYA | A | 05/28/2003 | 1 | INTERPOINT | | Y | MOR286R3SY/883 | 594 |
| 5962-9954501HYC | A | 05/28/2003 | 1 | INTERPOINT | | Y | MOR286R3SY/883 | 594 |
| 5962-9954501HZA | A | 05/28/2003 | 1 | INTERPOINT | | Y | MOR286R3SZ/883 | 594 |
| 5962-9954501HZC | A | 05/28/2003 | 1 | INTERPOINT | | Y | MOR286R3SZ/883 | 594 |
| 5962-9954601HTA | A | 05/28/2003 | 1 | INTERPOINT | | Y | MOR289R5SW/883 | 594 |
| 5962-9954601HTC | A | 05/28/2003 | 1 | INTERPOINT | | Y | MOR289R5SW/883 | 594 |
| 5962-9954601HUA | A | 05/28/2003 | 1 | INTERPOINT | | Y | MOR289R5SV/883 | 594 |
| 5962-9954601HUC | A | 05/28/2003 | 1 | INTERPOINT | | Y | MOR289R5SV/883 | 594 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9954601HXA | A | 05/28/2003 | 1 | INTERPOINT | | Y | MOR289R5S/883 | 594 |
| 5962-9954601HXC | A | 05/28/2003 | 1 | INTERPOINT | | Y | MOR289R5S/883 | 594 |
| 5962-9954601HYA | A | 05/28/2003 | 1 | INTERPOINT | | Y | MOR289R5SY/883 | 594 |
| 5962-9954601HYC | A | 05/28/2003 | 1 | INTERPOINT | | Y | MOR289R5SY/883 | 594 |
| 5962-9954601HZA | A | 05/28/2003 | 1 | INTERPOINT | | Y | MOR289R5SZ/883 | 594 |
| 5962-9954601HZC | A | 05/28/2003 | 1 | INTERPOINT | | Y | MOR289R5SZ/883 | 594 |
| 5962F9954701V9A | G | 12/07/2000 | 1 | INTERSIL | | Y | HS0-117RH-Q | 780 |
| 5962F9954701QUC | G | 12/07/2000 | 1 | INTERSIL | | Y | HS2-117RH-8 | 780 |
| 5962F9954701VUC | G | 12/07/2000 | 1 | INTERSIL | | Y | HS2-117RH-Q | 780 |
| 5962F9954701QXC | G | 12/07/2000 | 1 | INTERSIL | | Y | HS9S-117RH-8 | 780 |
| 5962F9954701VXC | G | 12/07/2000 | 1 | INTERSIL | | Y | HS9S-117RH-Q | 780 |
| 5962R9954701TXC | G | 12/07/2000 | | (NONE) | 03/23/2003 | | HS-117 (GEN) | 780 |
| 5962F9954701QYC | G | 12/07/2000 | 1 | INTERSIL | | Y | HSYE-117RH-8 | 780 |
| 5962F9954701VYC | G | 12/07/2000 | 1 | INTERSIL | | Y | HSYE-117RH-Q | 780 |
| 5962R9954701TYC | G | 12/07/2000 | 1 | INTERSIL | | Y | HSYE-117RH-T | 780 |
| 5962-9954801HTA | B | 06/03/2004 | 1 | INTERPOINT | | Y | MOR2805SW/883 | 594 |
| 5962-9954801HTC | B | 06/03/2004 | 1 | INTERPOINT | | Y | MOR2805SW/883 | 594 |
| 5962-9954801HUA | B | 06/03/2004 | 1 | INTERPOINT | | Y | MOR2805SV/883 | 594 |
| 5962-9954801HUC | B | 06/03/2004 | 1 | INTERPOINT | | Y | MOR2805SV/883 | 594 |
| 5962-9954801HXA | B | 06/03/2004 | 1 | INTERPOINT | | Y | MOR2805S/883 | 594 |
| 5962-9954801HXC | B | 06/03/2004 | 1 | INTERPOINT | | Y | MOR2805S/883 | 594 |
| 5962-9954801HYA | B | 06/03/2004 | 1 | INTERPOINT | | Y | MOR2805SY/883 | 594 |
| 5962-9954801HYC | B | 06/03/2004 | 1 | INTERPOINT | | Y | MOR2805SY/883 | 594 |
| 5962-9954801HZA | B | 06/03/2004 | 1 | INTERPOINT | | Y | MOR2805SZ/883 | 594 |
| 5962-9954801HZC | B | 06/03/2004 | 1 | INTERPOINT | | Y | MOR2805SZ/883 | 594 |
| 5962-9954901HTA | A | 05/28/2003 | 1 | INTERPOINT | | Y | MOR2812SW/883 | 594 |
| 5962-9954901HTC | A | 05/28/2003 | 1 | INTERPOINT | | Y | MOR2812SW/883 | 594 |
| 5962-9954901HUA | A | 05/28/2003 | 1 | INTERPOINT | | Y | MOR2812SV/883 | 594 |
| 5962-9954901HUC | A | 05/28/2003 | 1 | INTERPOINT | | Y | MOR2812SV/883 | 594 |
| 5962-9954901HXA | A | 05/28/2003 | 1 | INTERPOINT | | Y | MOR2812S/883 | 594 |
| 5962-9954901HXC | A | 05/28/2003 | 1 | INTERPOINT | | Y | MOR2812S/883 | 594 |
| 5962-9954901HYA | A | 05/28/2003 | 1 | INTERPOINT | | Y | MOR2812SY/883 | 594 |
| 5962-9954901HYC | A | 05/28/2003 | 1 | INTERPOINT | | Y | MOR2812SY/883 | 594 |
| 5962-9954901HZA | A | 05/28/2003 | 1 | INTERPOINT | | Y | MOR2812SZ/883 | 594 |
| 5962-9954901HZC | A | 05/28/2003 | 1 | INTERPOINT | | Y | MOR2812SZ/883 | 594 |
| 5962-9955001HTA | A | 05/28/2003 | 1 | INTERPOINT | | Y | MOR2815SW/883 | 594 |
| 5962-9955001HTC | A | 05/28/2003 | 1 | INTERPOINT | | Y | MOR2815SW/883 | 594 |
| 5962-9955001HUA | A | 05/28/2003 | 1 | INTERPOINT | | Y | MOR2815SV/883 | 594 |
| 5962-9955001HUC | A | 05/28/2003 | 1 | INTERPOINT | | Y | MOR2815SV/883 | 594 |
| 5962-9955001HXA | A | 05/28/2003 | 1 | INTERPOINT | | Y | MOR2815S/883 | 594 |
| 5962-9955001HXC | A | 05/28/2003 | 1 | INTERPOINT | | Y | MOR2815S/883 | 594 |
| 5962-9955001HYA | A | 05/28/2003 | 1 | INTERPOINT | | Y | MOR2815SY/883 | 594 |
| 5962-9955001HYC | A | 05/28/2003 | 1 | INTERPOINT | | Y | MOR2815SY/883 | 594 |
| 5962-9955001HZA | A | 05/28/2003 | 1 | INTERPOINT | | Y | MOR2815SZ/883 | 594 |
| 5962-9955001HZC | A | 05/28/2003 | 1 | INTERPOINT | | Y | MOR2815SZ/883 | 594 |
| 5962R9955101QXA | A | 04/28/1999 | | (NONE) | | | LM140 (GEN) | 782 |
| 5962R9955101VXA | A | 04/28/1999 | | (NONE) | | | LM140 (GEN) | 782 |
| 5962R9955101QYA | A | 04/28/1999 | | (NONE) | | | LM140 (GEN) | 782 |
| 5962R9955101VYA | A | 04/28/1999 | | (NONE) | | | LM140 (GEN) | 782 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9955201HUA | | 07/14/1999 | 1 | ADV. ANALOG | | Y | AFL2803.3SW/CH | 594 |
| 5962-9955201HUC | | 07/14/1999 | 1 | ADV. ANALOG | | Y | AFL2803.3SW/CH | 594 |
| 5962-9955201HXA | | 07/14/1999 | 1 | ADV. ANALOG | | Y | AFL2803.3SX/CH | 594 |
| 5962-9955201HXC | | 07/14/1999 | 1 | ADV. ANALOG | | Y | AFL2803.3SX/CH | 594 |
| 5962-9955201HYA | | 07/14/1999 | 1 | ADV. ANALOG | | Y | AFL2803.3SY/CH | 594 |
| 5962-9955201HYC | | 07/14/1999 | 1 | ADV. ANALOG | | Y | AFL2803.3SY/CH | 594 |
| 5962-9955201HZA | | 07/14/1999 | 1 | ADV. ANALOG | | Y | AFL2803.3SZ/CH | 594 |
| 5962-9955201HZC | | 07/14/1999 | 1 | ADV. ANALOG | | Y | AFL2803.3SZ/CH | 594 |
| 5962-9955301HUA | | 07/15/1999 | 1 | ADV. ANALOG | | Y | AFL27003.3SW/CH | 594 |
| 5962-9955301HUC | | 07/15/1999 | 1 | ADV. ANALOG | | Y | AFL27003.3SW/CH | 594 |
| 5962-9955301HXA | | 07/15/1999 | 1 | ADV. ANALOG | | Y | AFL27003.3SX/CH | 594 |
| 5962-9955301HXC | | 07/15/1999 | 1 | ADV. ANALOG | | Y | AFL27003.3SX/CH | 594 |
| 5962-9955301HYA | | 07/15/1999 | 1 | ADV. ANALOG | | Y | AFL27003.3SY/CH | 594 |
| 5962-9955301HYC | | 07/15/1999 | 1 | ADV. ANALOG | | Y | AFL27003.3SY/CH | 594 |
| 5962-9955301HZA | | 07/15/1999 | 1 | ADV. ANALOG | | Y | AFL27003.3SZ/CH | 594 |
| 5962-9955301HZC | | 07/15/1999 | 1 | ADV. ANALOG | | Y | AFL27003.3SZ/CH | 594 |
| 5962-9955401QCA | | 04/19/1999 | | (NONE) | 03/30/2001 | | LT1024A (GEN) | 710 |
| 5962-9955501QCA | | 05/07/1999 | | (NONE) | 03/30/2001 | | LT1127A (GEN) | 713 |
| 5962-9955601HXA | | 08/04/2000 | 1 | INTERPOINT | | Y | SLH2812D/HO | 594 |
| 5962-9955601HXC | | 08/04/2000 | 1 | INTERPOINT | | Y | SLH2812D/HO | 594 |
| 5962L9955601HXA | | 08/04/2000 | 1 | INTERPOINT | | Y | SLH2812D/HL | 594 |
| 5962L9955601HXC | | 08/04/2000 | 1 | INTERPOINT | | Y | SLH2812D/HL | 594 |
| 5962L9955601KXA | | 08/04/2000 | 1 | INTERPOINT | | Y | SLH2812D/KL | 594 |
| 5962L9955601KXC | | 08/04/2000 | 1 | INTERPOINT | | Y | SLH2812D/KL | 594 |
| 5962R9955601HXA | | 08/04/2000 | 1 | INTERPOINT | | Y | SLH2812D/HR | 594 |
| 5962R9955601HXC | | 08/04/2000 | 1 | INTERPOINT | | Y | SLH2812D/HR | 594 |
| 5962R9955601KXA | | 08/04/2000 | 1 | INTERPOINT | | Y | SLH2812D/KR | 594 |
| 5962R9955601KXC | | 08/04/2000 | 1 | INTERPOINT | | Y | SLH2812D/KR | 594 |
| 5962-9955701Q2A | A | 05/22/2002 | 2 | TI | | Y | TLV5618AMFKB | 591 |
| 5962-9955701QPA | A | 05/22/2002 | 2 | TI | | Y | TLV5618AMJGB | 591 |
| 5962-9955702Q2A | A | 05/22/2002 | 2 | TI | | Y | TLC5618AMFKB | 591 |
| 5962-9955702QPA | A | 05/22/2002 | 2 | TI | | Y | TLC5618AMJGB | 591 |
| 5962F9955801Q2C | E | 10/10/2002 | 2 | INTERSIL | | Y | HS4-1825ARH-8 | 787 |
| 5962F9955801V2C | E | 10/10/2002 | 2 | INTERSIL | | Y | HS4-1825ARH-Q | 787 |
| 5962F9955801V9A | E | 10/10/2002 | 2 | INTERSIL | | Y | HS0-1825ARH-Q | 787 |
| 5962F9955801QEC | E | 10/10/2002 | 2 | INTERSIL | | Y | HS1-1825ARH-8 | 787 |
| 5962F9955801VEC | E | 10/10/2002 | 2 | INTERSIL | | Y | HS1-1825ARH-Q | 787 |
| 5962F9955801QXC | E | 10/10/2002 | 2 | INTERSIL | | Y | HS9-1825ARH-8 | 787 |
| 5962F9955801VXC | E | 10/10/2002 | 2 | INTERSIL | | Y | HS9-1825ARH-Q | 787 |
| 5962R9955801TXC | E | 10/10/2002 | | (NONE) | 03/23/2003 | | HS-1825A (GEN) | 787 |
| 5962F9956001V9A | A | 06/17/2002 | 3 | INTERSIL | | Y | HS0-4424RH-Q | 519 |
| 5962F9956001QXC | A | 06/17/2002 | 3 | INTERSIL | | Y | HS9-4424RH-8 | 519 |
| 5962F9956001VXC | A | 06/17/2002 | 3 | INTERSIL | | Y | HS9-4424RH-Q | 519 |
| 5962R9956001TXC | A | 06/17/2002 | | (NONE) | 03/23/2003 | | HS-4424 (GEN) | 519 |
| 5962F9956002V9A | A | 06/17/2002 | 3 | INTERSIL | | Y | HS0-4424BRH-Q | 519 |
| 5962F9956002QXC | A | 06/17/2002 | 3 | INTERSIL | | Y | HS9-4424BRH-8 | 519 |
| 5962F9956002VXC | A | 06/17/2002 | 3 | INTERSIL | | Y | HS9-4424BRH-Q | 519 |
| 5962R9956002TXC | A | 06/17/2002 | | (NONE) | 03/23/2003 | | HS-4424B (GEN) | 519 |
| 5962-9956101HTA | A | 06/03/2004 | 1 | INTERPOINT | | Y | MOR2805DW/883 | 594 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9956101HTC | A | 06/03/2004 | 1 | INTERPOINT | | Y | MOR2805DW/883 | 594 |
| 5962-9956101HUA | A | 06/03/2004 | 1 | INTERPOINT | | Y | MOR2805DV/883 | 594 |
| 5962-9956101HUC | A | 06/03/2004 | 1 | INTERPOINT | | Y | MOR2805DV/883 | 594 |
| 5962-9956101HXA | A | 06/03/2004 | 1 | INTERPOINT | | Y | MOR2805D/883 | 594 |
| 5962-9956101HXC | A | 06/03/2004 | 1 | INTERPOINT | | Y | MOR2805D/883 | 594 |
| 5962-9956101HYA | A | 06/03/2004 | 1 | INTERPOINT | | Y | MOR2805DY/883 | 594 |
| 5962-9956101HYC | A | 06/03/2004 | 1 | INTERPOINT | | Y | MOR2805DY/883 | 594 |
| 5962-9956101HZA | A | 06/03/2004 | 1 | INTERPOINT | | Y | MOR2805DZ/883 | 594 |
| 5962-9956101HZC | A | 06/03/2004 | 1 | INTERPOINT | | Y | MOR2805DZ/883 | 594 |
| 5962-9956201HTA | A | 05/28/2003 | 1 | INTERPOINT | | Y | MOR2812DW/883 | 594 |
| 5962-9956201HTC | A | 05/28/2003 | 1 | INTERPOINT | | Y | MOR2812DW/883 | 594 |
| 5962-9956201HUA | A | 05/28/2003 | 1 | INTERPOINT | | Y | MOR2812DV/883 | 594 |
| 5962-9956201HUC | A | 05/28/2003 | 1 | INTERPOINT | | Y | MOR2812DV/883 | 594 |
| 5962-9956201HXA | A | 05/28/2003 | 1 | INTERPOINT | | Y | MOR2812D/883 | 594 |
| 5962-9956201HXC | A | 05/28/2003 | 1 | INTERPOINT | | Y | MOR2812D/883 | 594 |
| 5962-9956201HYA | A | 05/28/2003 | 1 | INTERPOINT | | Y | MOR2812DY/883 | 594 |
| 5962-9956201HYC | A | 05/28/2003 | 1 | INTERPOINT | | Y | MOR2812DY/883 | 594 |
| 5962-9956201HZA | A | 05/28/2003 | 1 | INTERPOINT | | Y | MOR2812DZ/883 | 594 |
| 5962-9956201HZC | A | 05/28/2003 | 1 | INTERPOINT | | Y | MOR2812DZ/883 | 594 |
| 5962-9956301HTA | A | 12/18/2002 | 1 | INTERPOINT | | Y | MOR2815DW/883 | 594 |
| 5962-9956301HTC | A | 12/18/2002 | 1 | INTERPOINT | | Y | MOR2815DW/883 | 594 |
| 5962-9956301HUA | A | 12/18/2002 | 1 | INTERPOINT | | Y | MOR2815DV/883 | 594 |
| 5962-9956301HUC | A | 12/18/2002 | 1 | INTERPOINT | | Y | MOR2815DV/883 | 594 |
| 5962-9956301HXA | A | 12/18/2002 | 1 | INTERPOINT | | Y | MOR2815D/883 | 594 |
| 5962-9956301HXC | A | 12/18/2002 | 1 | INTERPOINT | | Y | MOR2815D/883 | 594 |
| 5962-9956301HYA | A | 12/18/2002 | 1 | INTERPOINT | | Y | MOR2815DY/883 | 594 |
| 5962-9956301HYC | A | 12/18/2002 | 1 | INTERPOINT | | Y | MOR2815DY/883 | 594 |
| 5962-9956301HZA | A | 12/18/2002 | 1 | INTERPOINT | | Y | MOR2815DZ/883 | 594 |
| 5962-9956301HZC | A | 12/18/2002 | 1 | INTERPOINT | | Y | MOR2815DZ/883 | 594 |
| 5962-9956401HTA | A | 06/03/2004 | 1 | INTERPOINT | | Y | MOR283R3DW/883 | 594 |
| 5962-9956401HTC | A | 06/03/2004 | 1 | INTERPOINT | | Y | MOR283R3DW/883 | 594 |
| 5962-9956401HUA | A | 06/03/2004 | 1 | INTERPOINT | | Y | MOR283R3DV/883 | 594 |
| 5962-9956401HUC | A | 06/03/2004 | 1 | INTERPOINT | | Y | MOR283R3DV/883 | 594 |
| 5962-9956401HXA | A | 06/03/2004 | 1 | INTERPOINT | | Y | MOR283R3D/883 | 594 |
| 5962-9956401HXC | A | 06/03/2004 | 1 | INTERPOINT | | Y | MOR283R3D/883 | 594 |
| 5962-9956401HYA | A | 06/03/2004 | 1 | INTERPOINT | | Y | MOR283R3DY/883 | 594 |
| 5962-9956401HYC | A | 06/03/2004 | 1 | INTERPOINT | | Y | MOR283R3DY/883 | 594 |
| 5962-9956401HZA | A | 06/03/2004 | 1 | INTERPOINT | | Y | MOR283R3DZ/883 | 594 |
| 5962-9956401HZC | A | 06/03/2004 | 1 | INTERPOINT | | Y | MOR283R3DZ/883 | 594 |
| 5962-9956501HTA | A | 05/28/2003 | 1 | INTERPOINT | | Y | MOR286R3DW/883 | 594 |
| 5962-9956501HTC | A | 05/28/2003 | 1 | INTERPOINT | | Y | MOR286R3DW/883 | 594 |
| 5962-9956501HUA | A | 05/28/2003 | 1 | INTERPOINT | | Y | MOR286R3DV/883 | 594 |
| 5962-9956501HUC | A | 05/28/2003 | 1 | INTERPOINT | | Y | MOR286R3DV/883 | 594 |
| 5962-9956501HXA | A | 05/28/2003 | 1 | INTERPOINT | | Y | MOR286R3D/883 | 594 |
| 5962-9956501HXC | A | 05/28/2003 | 1 | INTERPOINT | | Y | MOR286R3D/883 | 594 |
| 5962-9956501HYA | A | 05/28/2003 | 1 | INTERPOINT | | Y | MOR286R3DY/883 | 594 |
| 5962-9956501HYC | A | 05/28/2003 | 1 | INTERPOINT | | Y | MOR286R3DY/883 | 594 |
| 5962-9956501HZA | A | 05/28/2003 | 1 | INTERPOINT | | Y | MOR286R3DZ/883 | 594 |
| 5962-9956501HZC | A | 05/28/2003 | 1 | INTERPOINT | | Y | MOR286R3DZ/883 | 594 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9956601HTA | A | 05/28/2003 | 1 | INTERPOINT | | Y | MOR289R5DW/883 | 594 |
| 5962-9956601HTC | A | 05/28/2003 | 1 | INTERPOINT | | Y | MOR289R5DW/883 | 594 |
| 5962-9956601HUA | A | 05/28/2003 | 1 | INTERPOINT | | Y | MOR289R5DV/883 | 594 |
| 5962-9956601HUC | A | 05/28/2003 | 1 | INTERPOINT | | Y | MOR289R5DV/883 | 594 |
| 5962-9956601HXA | A | 05/28/2003 | 1 | INTERPOINT | | Y | MOR289R5D/883 | 594 |
| 5962-9956601HXC | A | 05/28/2003 | 1 | INTERPOINT | | Y | MOR289R5D/883 | 594 |
| 5962-9956601HYA | A | 05/28/2003 | 1 | INTERPOINT | | Y | MOR289R5DY/883 | 594 |
| 5962-9956601HYC | A | 05/28/2003 | 1 | INTERPOINT | | Y | MOR289R5DY/883 | 594 |
| 5962-9956601HZA | A | 05/28/2003 | 1 | INTERPOINT | | Y | MOR289R5DZ/883 | 594 |
| 5962-9956601HZC | A | 05/28/2003 | 1 | INTERPOINT | | Y | MOR289R5DZ/883 | 594 |
| 5962-9956901Q9A | B | 03/12/2001 | | (NONE) | | | RT54SX16 (GEN) | 381 |
| 5962-9956901QXC | B | 03/12/2001 | 1 | ACTEL | 06/30/2004 | Y | RT54SX16-CQ256B | 381 |
| 5962-9956901QYC | B | 03/12/2001 | 1 | ACTEL | 06/30/2004 | Y | RT54SX16-CQ208B | 381 |
| 5962-9956902QXC | B | 03/12/2001 | 1 | ACTEL | 06/30/2004 | Y | RT54SX16-1CQ256B | 381 |
| 5962-9956902QYC | B | 03/12/2001 | 1 | ACTEL | 06/30/2004 | Y | RT54SX16-1CQ208B | 381 |
| 5962-9956903Q9B | B | 03/12/2001 | | (NONE) | | | A54SX16 (GEN) | 381 |
| 5962-9956903QXC | B | 03/12/2001 | 1 | ACTEL | | Y | A54SX16-CQ256B | 381 |
| 5962-9956903QYC | B | 03/12/2001 | 1 | ACTEL | | Y | A54SX16-CQ208B | 381 |
| 5962-9956904QXC | B | 03/12/2001 | 1 | ACTEL | | Y | A54SX16-1CQ256B | 381 |
| 5962-9956904QYC | B | 03/12/2001 | 1 | ACTEL | | Y | A54SX16-1CQ208B | 381 |
| 5962-9957001Q2A | B | 09/06/2002 | 2 | TI | | Y | TLV2548MFKB | 592 |
| 5962-9957001QRA | B | 09/06/2002 | | (NONE) | | | TLV2548 (GEN) | 592 |
| 5962-9957201NTB | A | 08/28/2003 | 1 | XILINX | | Y | XQV300-4CPQ240 | 380 |
| 5962R9957201NTB | A | 08/28/2003 | 1 | XILINX | | Y | XQVR300-4CPQ240 | 380 |
| 5962-9957201NUA | A | 08/28/2003 | 1 | XILINX | | Y | XQV300-4CBG432 | 380 |
| 5962R9957201NUA | A | 08/28/2003 | 1 | XILINX | | Y | XQVR300-4CBG432 | 380 |
| 5962-9957201QYC | A | 08/28/2003 | 1 | XILINX | | Y | XQV300-4CB228 | 380 |
| 5962R9957201QYC | A | 08/28/2003 | 1 | XILINX | | Y | XQVR300-4CB228 | 380 |
| 5962-9957201QZC | A | 08/28/2003 | 1 | XILINX | | Y | XQV300-4CB228 | 380 |
| 5962R9957201QZC | A | 08/28/2003 | 1 | XILINX | | Y | XQVR300-4CB228 | 380 |
| 5962-9957301NTB | A | 08/28/2003 | 2 | XILINX | | Y | XQV600-4HQ240 | 380 |
| 5962R9957301NTB | A | 08/28/2003 | 2 | XILINX | | Y | XQVR600-4HQ240 | 380 |
| 5962-9957301NUA | A | 08/28/2003 | 2 | XILINX | | Y | XQV600-4BG432 | 380 |
| 5962R9957301NUA | A | 08/28/2003 | 2 | XILINX | | Y | XQVR600-4BG432 | 380 |
| 5962-9957301QYC | A | 08/28/2003 | 2 | XILINX | | Y | XQV600-4CB228 | 380 |
| 5962R9957301QYC | A | 08/28/2003 | 2 | XILINX | | Y | XQVR600-4CB228 | 380 |
| 5962-9957301QZC | A | 08/28/2003 | 2 | XILINX | | Y | XQV600-4CB228 | 380 |
| 5962R9957301QZC | A | 08/28/2003 | 2 | XILINX | | Y | XQVR600-4CB228 | 380 |
| 5962-9957401NUA | A | 08/28/2003 | 2 | XILINX | | Y | XQV1000-4BG560 | 380 |
| 5962R9957401NUA | A | 08/28/2003 | 2 | XILINX | | Y | XQVR1000-4BG560 | 380 |
| 5962-9957401QXA | A | 08/28/2003 | 2 | XILINX | | Y | XQV1000-4CG560 | 380 |
| 5962R9957401QXA | A | 08/28/2003 | 2 | XILINX | | Y | XQVR1000-4CG560 | 380 |
| 5962-9957501NTB | | 05/31/2000 | 2 | XILINX | | Y | XQ4085XL-1NHQ240 | 380 |
| 5962-9957501NUA | | 05/31/2000 | 2 | XILINX | | Y | XQ4085XL-1NBG432 | 380 |
| 5962-9957501QYC | | 05/31/2000 | 2 | XILINX | | Y | XQ4085XL-1CB228B | 380 |
| 5962-9957501QZC | | 05/31/2000 | 2 | XILINX | | Y | XQ4085XL-1CB228B | 380 |
| 5962-9957601Q2A | C | 11/05/2003 | 3 | TI | | Y | TLV5638MFKB | 591 |
| 5962-9957601QPA | C | 11/05/2003 | 3 | TI | | Y | TLV5638MJGB | 591 |
| 5962-9957701NXD | B | 07/10/2002 | 2 | TI | | Y | THS1206MDA | 592 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9958101QXC | | 06/16/1999 | 1 | NATIONAL | | Y | AR629AU9/883 | 599 |
| 5962-9958201QXC | A | 07/11/2002 | 1 | INTERSIL | 10/05/2004 | Y | HI1-774T/883 | 592 |
| 5962-9958301Q2A | A | 01/31/2002 | 1 | TI | | Y | TL5001MFKB | 787 |
| 5962-9958301QPA | A | 01/31/2002 | 1 | TI | | Y | TL5001MJGB | 787 |
| 5962-9958302Q2A | A | 01/31/2002 | 1 | TI | | Y | TL5001AMFKB | 787 |
| 5962-9958302QPA | A | 01/31/2002 | 1 | TI | | Y | TL5001AMJGB | 787 |
| 5962-9958401Q2A | A | 07/12/2002 | 1 | TI | 07/15/2005 | Y | TL1451AMFKB | 787 |
| 5962-9958401QEA | A | 07/12/2002 | 1 | TI | 07/15/2005 | Y | TL1451AMJB | 787 |
| 5962-9958501Q9A | | 07/13/1999 | 1 | ACTEL | | Y | A42MX36-DIE | 381 |
| 5962-9958501QXC | | 07/13/1999 | 1 | ACTEL | | Y | A42MX36-CQ256B | 381 |
| 5962-9958501QYC | | 07/13/1999 | 1 | ACTEL | | Y | A42MX36-CQ208B | 381 |
| 5962-9958502QXC | | 07/13/1999 | 1 | ACTEL | | Y | A42MX36-1CQ256B | 381 |
| 5962-9958502QYC | | 07/13/1999 | 1 | ACTEL | | Y | A42MX36-1CQ208B | 381 |
| 5962-9958601Q9A | B | 03/12/2001 | | (NONE) | | | A54SX32 (GEN) | 381 |
| 5962-9958601QXC | B | 03/12/2001 | 1 | ACTEL | | Y | A54SX32-CQ256B | 381 |
| 5962-9958601QYC | B | 03/12/2001 | 1 | ACTEL | | Y | A54SX32-CQ208B | 381 |
| 5962-9958602QXC | B | 03/12/2001 | 1 | ACTEL | | Y | A54SX32-1CQ256B | 381 |
| 5962-9958602QYC | B | 03/12/2001 | 1 | ACTEL | | Y | A54SX32-1CQ208B | 381 |
| 5962-9958603QXC | B | 03/12/2001 | | (NONE) | | | RT54SX32 (GEN) | 381 |
| 5962-9958603QYC | B | 03/12/2001 | | (NONE) | | | RT54SX32 (GEN) | 381 |
| 5962-9958604QXC | B | 03/12/2001 | | (NONE) | | | RT54SX32 (GEN) | 381 |
| 5962-9958604QYC | B | 03/12/2001 | | (NONE) | | | RT54SX32 (GEN) | 381 |
| 5962-9958901QXC | C | 11/28/2001 | 1 | TI | 08/01/2004 | Y | MPT57571 | 599 |
| 5962-9959001QXC | A | 02/06/2001 | 1 | TI | 08/01/2004 | Y | MPT57604 | 599 |
| 5962-9959101Q2A | | 10/16/2002 | 2 | TI | | Y | TPS3307-18 | 449 |
| 5962-9959101QPA | | 10/16/2002 | 2 | TI | | Y | TPS3307-18 | 449 |
| 5962-9959301Q2A | A | 07/18/2002 | 1 | TI | | Y | THS4011MFKB | 702 |
| 5962-9959301QPA | A | 07/18/2002 | 1 | TI | | Y | THS4011MJGB | 702 |
| 5962-9959501Q2A | A | 07/29/2002 | 1 | TI | | Y | THS4031MFKB | 702 |
| 5962-9959501QPA | A | 07/29/2002 | 1 | TI | | Y | THS4031MJGB | 702 |
| 5962-9959901Q2A | A | 08/01/2002 | 1 | TI | | Y | THS4051MFKB | 702 |
| 5962-9959901QPA | A | 08/01/2002 | 1 | TI | | Y | THS4051MJGB | 702 |
| 5962-9960101Q2A | A | 12/17/1999 | 1 | TI | | Y | THS4061MFKB | 702 |
| 5962-9960101QPA | A | 12/17/1999 | 1 | TI | | Y | THS4061MJGB | 702 |
| 5962D9960601QUA | F | 05/28/2002 | 2 | UTMC | | Y | UT7Q512-UCA | 629 |
| 5962D9960601QUC | F | 05/28/2002 | 2 | UTMC | | Y | UT7Q512-UCC | 629 |
| 5962D9960601TUA | F | 05/28/2002 | 2 | UTMC | | Y | UT7Q512-UCA | 629 |
| 5962D9960601TUC | F | 05/28/2002 | 2 | UTMC | | Y | UT7Q512-UCC | 629 |
| 5962D9960601QXA | F | 05/28/2002 | | (NONE) | | | 7Q512 (GEN) | 629 |
| 5962D9960601TXA | F | 05/28/2002 | | (NONE) | | | 7Q512 (GEN) | 629 |
| 5962D9960602QUA | F | 05/28/2002 | 2 | UTMC | | Y | UT7Q512-UCA | 629 |
| 5962D9960602QUC | F | 05/28/2002 | 2 | UTMC | | Y | UT7Q512-UCC | 629 |
| 5962D9960602TUA | F | 05/28/2002 | 2 | UTMC | | Y | UT7Q512-UCA | 629 |
| 5962D9960602TUC | F | 05/28/2002 | 2 | UTMC | | Y | UT7Q512-UCC | 629 |
| 5962D9960602QXA | F | 05/28/2002 | | (NONE) | | | 7Q512 (GEN) | 629 |
| 5962D9960602TXA | F | 05/28/2002 | | (NONE) | | | 7Q512 (GEN) | 629 |
| 5962D9960701T9A | G | 12/08/2002 | 2 | UTMC | | Y | UT8Q512TDIE | 629 |
| 5962L9960701Q9A | G | 12/08/2002 | 2 | UTMC | | Y | UT8Q512_QDIE | 629 |
| 5962L9960701T9A | G | 12/08/2002 | 2 | UTMC | | Y | UT8Q512_TDIE | 629 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962D9960701QUA | G | 12/08/2002 | 2 | UTMC | | Y | UT8Q512-UCA | 629 |
| 5962D9960701QUC | G | 12/08/2002 | 2 | UTMC | | Y | UT8Q512-UCC | 629 |
| 5962D9960701TUA | G | 12/08/2002 | 2 | UTMC | | Y | UT8Q512-UCA | 629 |
| 5962D9960701TUC | G | 12/08/2002 | 2 | UTMC | | Y | UT8Q512-UCC | 629 |
| 5962L9960701QUA | G | 12/08/2002 | 2 | UTMC | | Y | UT8Q512-UCA | 629 |
| 5962L9960701QUC | G | 12/08/2002 | 2 | UTMC | | Y | UT8Q512-UCC | 629 |
| 5962L9960701TUA | G | 12/08/2002 | 2 | UTMC | | Y | UT8Q512-UCA | 629 |
| 5962L9960701TUC | G | 12/08/2002 | 2 | UTMC | | Y | UT8Q512-UCC | 629 |
| 5962D9960701QXA | G | 12/08/2002 | 2 | UTMC | | Y | UT8Q512-ICA | 629 |
| 5962D9960701QXC | G | 12/08/2002 | 2 | UTMC | | Y | UT8Q512-ICC | 629 |
| 5962D9960701TXA | G | 12/08/2002 | 2 | UTMC | | Y | UT8Q512-ICA | 629 |
| 5962D9960701TXC | G | 12/08/2002 | 2 | UTMC | | Y | UT8Q512-ICC | 629 |
| 5962L9960701QXA | G | 12/08/2002 | 2 | UTMC | | Y | UT8Q512-ICA | 629 |
| 5962L9960701QXC | G | 12/08/2002 | 2 | UTMC | | Y | UT8Q512-ICC | 629 |
| 5962L9960701TXA | G | 12/08/2002 | 2 | UTMC | | Y | UT8Q512-ICA | 629 |
| 5962L9960701TXC | G | 12/08/2002 | 2 | UTMC | | Y | UT8Q512-ICC | 629 |
| 5962L9960702Q9A | G | 12/08/2002 | 2 | UTMC | | Y | UT8Q512_QDIE | 629 |
| 5962L9960702T9A | G | 12/08/2002 | 2 | UTMC | | Y | UT8Q512_TDIE | 629 |
| 5962L9960702QUA | G | 12/08/2002 | 2 | UTMC | | Y | UT8Q512-UWA | 629 |
| 5962L9960702QUC | G | 12/08/2002 | 2 | UTMC | | Y | UT8Q512-UWC | 629 |
| 5962L9960702TUA | G | 12/08/2002 | 2 | UTMC | | Y | UT8Q512-UWA | 629 |
| 5962L9960702TUC | G | 12/08/2002 | 2 | UTMC | | Y | UT8Q512-UWC | 629 |
| 5962L9960702QXA | G | 12/08/2002 | 2 | UTMC | | Y | UT8Q512-IWA | 629 |
| 5962L9960702QXC | G | 12/08/2002 | 2 | UTMC | | Y | UT8Q512-IWC | 629 |
| 5962L9960702TXA | G | 12/08/2002 | 2 | UTMC | | Y | UT8Q512-IWA | 629 |
| 5962L9960702TXC | G | 12/08/2002 | 2 | UTMC | | Y | UT8Q512-IWC | 629 |
| 5962L9960703Q9A | G | 12/08/2002 | 2 | UTMC | | Y | UT8Q512_QDIE | 629 |
| 5962L9960703T9A | G | 12/08/2002 | 2 | UTMC | | Y | UT8Q512_TDIE | 629 |
| 5962L9960703QUA | G | 12/08/2002 | 2 | UTMC | | Y | UT8Q512-UCA | 629 |
| 5962L9960703QUC | G | 12/08/2002 | 2 | UTMC | | Y | UT8Q512-UCC | 629 |
| 5962L9960703TUA | G | 12/08/2002 | 2 | UTMC | | Y | UT8Q512-UCA | 629 |
| 5962L9960703TUC | G | 12/08/2002 | 2 | UTMC | | Y | UT8Q512-UCC | 629 |
| 5962L9960703QXA | G | 12/08/2002 | 2 | UTMC | | Y | UT8Q512-ICA | 629 |
| 5962L9960703QXC | G | 12/08/2002 | 2 | UTMC | | Y | UT8Q512-ICC | 629 |
| 5962L9960703TXA | G | 12/08/2002 | 2 | UTMC | | Y | UT8Q512-ICA | 629 |
| 5962L9960703TXC | G | 12/08/2002 | 2 | UTMC | | Y | UT8Q512-ICC | 629 |
| 5962L9960704Q9A | G | 12/08/2002 | 2 | UTMC | | Y | UT8Q512_QDIE | 629 |
| 5962L9960704T9A | G | 12/08/2002 | 2 | UTMC | | Y | UT8Q512_TDIE | 629 |
| 5962L9960704QUA | G | 12/08/2002 | 2 | UTMC | | Y | UT8Q512-UWA | 629 |
| 5962L9960704QUC | G | 12/08/2002 | 2 | UTMC | | Y | UT8Q512-UWC | 629 |
| 5962L9960704TUA | G | 12/08/2002 | 2 | UTMC | | Y | UT8Q512-UWA | 629 |
| 5962L9960704TUC | G | 12/08/2002 | 2 | UTMC | | Y | UT8Q512-UWC | 629 |
| 5962L9960704QXA | G | 12/08/2002 | 2 | UTMC | | Y | UT8Q512-IWA | 629 |
| 5962L9960704QXC | G | 12/08/2002 | 2 | UTMC | | Y | UT8Q512-IWC | 629 |
| 5962L9960704TXA | G | 12/08/2002 | 2 | UTMC | | Y | UT8Q512-IWA | 629 |
| 5962L9960704TXC | G | 12/08/2002 | 2 | UTMC | | Y | UT8Q512-IWC | 629 |
| 5962-9960801HUA | | 08/09/2000 | 1 | ADV. ANALOG | | Y | AFL12005SW/CH | 594 |
| 5962-9960801HUC | | 08/09/2000 | 1 | ADV. ANALOG | | Y | AFL12005SW/CH | 594 |
| 5962-9960801HXA | | 08/09/2000 | 1 | ADV. ANALOG | | Y | AFL12005SX/CH | 594 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9960801HXC | | 08/09/2000 | 1 | ADV. ANALOG | | Y | AFL12005SX/CH | 594 |
| 5962-9960801HYA | | 08/09/2000 | 1 | ADV. ANALOG | | Y | AFL12005SY/CH | 594 |
| 5962-9960801HYC | | 08/09/2000 | 1 | ADV. ANALOG | | Y | AFL12005SY/CH | 594 |
| 5962-9960801HZA | | 08/09/2000 | 1 | ADV. ANALOG | | Y | AFL12005SZ/CH | 594 |
| 5962-9960801HZC | | 08/09/2000 | 1 | ADV. ANALOG | | Y | AFL12005SZ/CH | 594 |
| 5962-9960901HUA | | 08/09/2000 | 1 | ADV. ANALOG | | Y | AFL12012DW/CH | 594 |
| 5962-9960901HUC | | 08/09/2000 | 1 | ADV. ANALOG | | Y | AFL12012DW/CH | 594 |
| 5962-9960901HXA | | 08/09/2000 | 1 | ADV. ANALOG | | Y | AFL12012DX/CH | 594 |
| 5962-9960901HXC | | 08/09/2000 | 1 | ADV. ANALOG | | Y | AFL12012DX/CH | 594 |
| 5962-9960901HYA | | 08/09/2000 | 1 | ADV. ANALOG | | Y | AFL12012DY/CH | 594 |
| 5962-9960901HYC | | 08/09/2000 | 1 | ADV. ANALOG | | Y | AFL12012DY/CH | 594 |
| 5962-9960901HZA | | 08/09/2000 | 1 | ADV. ANALOG | | Y | AFL12012DZ/CH | 594 |
| 5962-9960901HZC | | 08/09/2000 | 1 | ADV. ANALOG | | Y | AFL12012DZ/CH | 594 |
| 5962-9961001HXA | A | 12/18/2002 | 1 | ANALOG (6) | | Y | AD10200TZ/QMLH | 592 |
| 5962-9961002HXA | A | 12/18/2002 | 1 | ANALOG (6) | | Y | AD10200BZ/QMLH | 592 |
| 5962-9961201HNA | A | 04/29/2004 | 1 | SOLITRON | | Y | SDP117NHD | 780 |
| 5962-9961201HNC | A | 04/29/2004 | 1 | SOLITRON | | Y | SDP117NHG | 780 |
| 5962-9961201HTA | A | 04/29/2004 | 1 | SOLITRON | | Y | SDP117THD | 780 |
| 5962-9961201HTC | A | 04/29/2004 | 1 | SOLITRON | | Y | SDP117THG | 780 |
| 5962-9961201HUA | A | 04/29/2004 | 1 | SOLITRON | | Y | SDP117UHD | 780 |
| 5962-9961201HUC | A | 04/29/2004 | 1 | SOLITRON | | Y | SDP117UHG | 780 |
| 5962-9961201HZA | A | 04/29/2004 | 1 | SOLITRON | | Y | SDP117ZHD | 780 |
| 5962-9961201HZC | A | 04/29/2004 | 1 | SOLITRON | | Y | SDP117ZHG | 780 |
| 5962-9961202HNA | A | 04/29/2004 | 1 | SOLITRON | | Y | SDP117HVNHD | 780 |
| 5962-9961202HNC | A | 04/29/2004 | 1 | SOLITRON | | Y | SDP117HVNHG | 780 |
| 5962-9961202HTA | A | 04/29/2004 | 1 | SOLITRON | | Y | SDP117HVTHD | 780 |
| 5962-9961202HTC | A | 04/29/2004 | 1 | SOLITRON | | Y | SDP117HVTHG | 780 |
| 5962-9961202HUA | A | 04/29/2004 | 1 | SOLITRON | | Y | SDP117HVUHD | 780 |
| 5962-9961202HUC | A | 04/29/2004 | 1 | SOLITRON | | Y | SDP117HVUHG | 780 |
| 5962-9961202HZA | A | 04/29/2004 | 1 | SOLITRON | | Y | SDP117HVZHD | 780 |
| 5962-9961202HZC | A | 04/29/2004 | 1 | SOLITRON | | Y | SDP117HVZHG | 780 |
| 5962-9961203HNA | A | 04/29/2004 | 1 | SOLITRON | | Y | SDP137NHD | 781 |
| 5962-9961203HNC | A | 04/29/2004 | 1 | SOLITRON | | Y | SDP137NHG | 781 |
| 5962-9961203HTA | A | 04/29/2004 | 1 | SOLITRON | | Y | SDP137THD | 781 |
| 5962-9961203HTC | A | 04/29/2004 | 1 | SOLITRON | | Y | SDP137THG | 781 |
| 5962-9961203HUA | A | 04/29/2004 | 1 | SOLITRON | | Y | SDP137UHD | 781 |
| 5962-9961203HUC | A | 04/29/2004 | 1 | SOLITRON | | Y | SDP137UHG | 781 |
| 5962-9961203HZA | A | 04/29/2004 | 1 | SOLITRON | | Y | SDP137ZHD | 781 |
| 5962-9961203HZC | A | 04/29/2004 | 1 | SOLITRON | | Y | SDP137ZHG | 781 |
| 5962-9961204HNA | A | 04/29/2004 | 1 | SOLITRON | | Y | SDP137HVNHD | 781 |
| 5962-9961204HNC | A | 04/29/2004 | 1 | SOLITRON | | Y | SDP137HVNHG | 781 |
| 5962-9961204HTA | A | 04/29/2004 | 1 | SOLITRON | | Y | SDP137HVTHD | 781 |
| 5962-9961204HTC | A | 04/29/2004 | 1 | SOLITRON | | Y | SDP137HVTHG | 781 |
| 5962-9961204HUA | A | 04/29/2004 | 1 | SOLITRON | | Y | SDP137HVUHD | 781 |
| 5962-9961204HUC | A | 04/29/2004 | 1 | SOLITRON | | Y | SDP137HVUHG | 781 |
| 5962-9961204HZA | A | 04/29/2004 | 1 | SOLITRON | | Y | SDP137HVZHD | 781 |
| 5962-9961204HZA | A | 04/29/2004 | 1 | SOLITRON | | Y | SDP137HVZHG | 781 |
| 5962-9961301HNA | A | 04/29/2004 | 1 | SOLITRON | | Y | SDP7812ANHD | 782 |
| 5962-9961301HNC | A | 04/29/2004 | 1 | SOLITRON | | Y | SDP7812ANHG | 782 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-9961301HTA | A | 04/29/2004 | 1 | SOLITRON | | Y | SDP7812ATHD | 782 |
| 5962-9961301HTC | A | 04/29/2004 | 1 | SOLITRON | | Y | SDP7812ATHG | 782 |
| 5962-9961301HUA | A | 04/29/2004 | 1 | SOLITRON | | Y | SDP7812AUHD | 782 |
| 5962-9961301HUC | A | 04/29/2004 | 1 | SOLITRON | | Y | SDP7812AUHG | 782 |
| 5962-9961301HZA | A | 04/29/2004 | 1 | SOLITRON | | Y | SDP7812AZHD | 782 |
| 5962-9961301HZC | A | 04/29/2004 | 1 | SOLITRON | | Y | SDP7812AZHG | 782 |
| 5962-9961401HNA | A | 04/29/2004 | 1 | SOLITRON | | Y | SDP7912ANHD | 783 |
| 5962-9961401HNC | A | 04/29/2004 | 1 | SOLITRON | | Y | SDP7912ANHG | 783 |
| 5962-9961401HTA | A | 04/29/2004 | 1 | SOLITRON | | Y | SDP7912ATHD | 783 |
| 5962-9961401HTC | A | 04/29/2004 | 1 | SOLITRON | | Y | SDP7912ATHG | 783 |
| 5962-9961401HUA | A | 04/29/2004 | 1 | SOLITRON | | Y | SDP7912AUHD | 783 |
| 5962-9961401HUC | A | 04/29/2004 | 1 | SOLITRON | | Y | SDP7912AUHG | 783 |
| 5962-9961401HZA | A | 04/29/2004 | 1 | SOLITRON | | Y | SDP7912AZHD | 783 |
| 5962-9961401HZC | A | 04/29/2004 | 1 | SOLITRON | | Y | SDP7912AZHG | 783 |
| 5962-9961501QYA | A | 03/19/2002 | 2 | CYPRESS | | Y | CY7C466A-25LMB | 670 |
| 5962-9961501QYA | A | 03/19/2002 | 3 | QP SEMI | | Y | CY7C466A-25LMB | 670 |
| 5962-9961502QYA | A | 03/19/2002 | 3 | QP SEMI | | Y | CY7C466A-15LMB | 670 |
| 5962-9961601HXA | | 02/02/2001 | 1 | ANALOG (6) | | Y | AD10465BZ/QMLH | 592 |
| 5962F9961701V9A | B | 08/30/2002 | 1 | INTERSIL | | Y | HS0-4080ARH-Q | 555 |
| 5962F9961701QSC | B | 08/30/2002 | 1 | INTERSIL | | Y | HS9-4080ARH-8 | 555 |
| 5962F9961701VSC | B | 08/30/2002 | 1 | INTERSIL | | Y | HS9-4080ARH-Q | 555 |
| 5962R9961701TSC | B | 08/30/2002 | 1 | INTERSIL | | Y | HS9-4080ARH-T | 555 |
| 5962F9961801V9A | B | 08/29/2002 | 1 | INTERSIL | | Y | HS0-201HSRH-Q | 183 |
| 5962F9961801QEC | B | 08/29/2002 | 1 | INTERSIL | | Y | HS1-201HSRH-8 | 183 |
| 5962F9961801VEC | B | 08/29/2002 | 1 | INTERSIL | | Y | HS1-201HSRH-Q | 183 |
| 5962R9961801TEC | B | 08/29/2002 | 1 | INTERSIL | | Y | HS1-201HSRH-T | 183 |
| 5962F9961801QXC | B | 08/29/2002 | 1 | INTERSIL | | Y | HS9-201HSRH-8 | 183 |
| 5962F9961801VXC | B | 08/29/2002 | 1 | INTERSIL | | Y | HS9-201HSRH-Q | 183 |
| 5962R9961801TXC | B | 08/29/2002 | 1 | INTERSIL | | Y | HS9-201HSRH-T | 183 |
| 5962-9961901Q3A | A | 08/21/2002 | 1 | TI | | Y | UC1827L-1883B | 787 |
| 5962-9961901QJA | A | 08/21/2002 | 1 | TI | | Y | UC1827J-1883B | 787 |
| 5962-9962001Q2A | A | 09/09/2002 | 3 | TI | | Y | TL1431MFKB | 785 |
| 5962-9962001V2A | A | 09/09/2002 | 3 | TI | | Y | TL1431MFKQMLV | 785 |
| 5962-9962001QPA | A | 09/09/2002 | 3 | TI | | Y | TL1431MJGB | 785 |
| 5962-9962001VPA | A | 09/09/2002 | 3 | TI | | Y | TL1431MJGQMLV | 785 |
| 5962-99A0101QXC | | 11/16/1998 | 3 | AMI | | Y | 6556-033 | 365 |
| 5962-99A0201NXB | B | 11/08/2002 | 2 | AMI | | Y | 11179-001 | 365 |
| 5962-99A0301QXC | A | 03/26/1999 | | (NONE) | | | 6901-011 (GEN) | 365 |
| 5962-99A0301QYC | A | 03/26/1999 | 2 | AMI | | Y | 6901-011 | 365 |
| 5962H99A0401QZC | A | 04/09/2001 | 2 | HONEYWELL (1) | | Y | HX6664/XQHC-1 | 365 |
| 5962H99A0402QZC | A | 04/09/2001 | 2 | HONEYWELL (1) | | Y | HX6664/XQHC-2 | 365 |
| 5962H99A0403QZC | A | 04/09/2001 | 2 | HONEYWELL (1) | | Y | HX6664/XQHC-3 | 365 |
| 5962H99A0404QZC | A | 04/09/2001 | 2 | HONEYWELL (1) | | Y | HX6664/XQHC-4 | 365 |
| 5962-99A0501QXC | | 01/13/2000 | 3 | AMI | | Y | 11496-501 | 365 |
| 5962-99A0502NYB | | 01/13/2000 | 3 | AMI | | Y | 11496-502 | 365 |
| 5962-99A0601NXB | | 10/19/1999 | 3 | AMI | | Y | 6577-525 | 365 |
| 5962-99A0602QYC | | 10/19/1999 | 3 | AMI | | Y | 6577-524 | 365 |
| 5962-99A0701NXB | A | 03/20/2000 | 3 | AMI | | Y | 6825-010 | 365 |
| 5962-99A0702QYC | A | 03/20/2000 | 3 | AMI | | Y | 6825-008 | 365 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962-99A0901NXB | C | 03/20/2000 | 3 | AMI | | Y | 6825-514 | 365 |
| 5962-99A0902QYC | C | 03/20/2000 | 3 | AMI | | Y | 6825-512 | 365 |
| 5962-99A1001NXB | | 10/20/1999 | 3 | AMI | | Y | 11508-002 | 365 |
| 5962-99A1002QYC | | 10/20/1999 | 3 | AMI | | Y | 11508-001 | 365 |
| 5962-99A1101NXB | B | 01/14/2000 | | (NONE) | | | 6580-064 (GEN) | 365 |
| 5962-99A1101NZB | B | 01/14/2000 | 2 | AMI | | Y | 6580-064 | 365 |
| 5962-99A1102QYC | B | 01/14/2000 | | (NONE) | | | 6580-062 (GEN) | 365 |
| 5962-99A1201QXC | A | 07/15/1999 | 2 | AMI | | Y | 5345-034 | 365 |
| 5962-99A1401QXC | | 03/15/1999 | 1 | AMI | | Y | 5345-005 | 365 |
| 5962H99A1501QZC | A | 04/09/2001 | 1 | HONEYWELL (1) | | Y | HX6356/XQHC | 365 |
| 5962-99A1601QXC | | 05/28/1999 | 2 | AMI | | Y | 5343-048 | 365 |
| 5962-99A1701QXC | | 05/17/1999 | 2 | AMI | | Y | 6559-055 | 365 |
| 5962-99A1801NXB | A | 12/22/1999 | 3 | AMI | | Y | 6580-533 | 365 |
| 5962-99A1901QXC | | 05/26/1999 | 2 | AMI | | Y | 5345-029 | 365 |
| 5962-99A2001QXC | | 05/26/1999 | 2 | AMI | | Y | 6577-024 | 365 |
| 5962-99A2101QXA | | 06/02/1999 | 3 | AMI | | Y | 6802-503 | 365 |
| 5962-99A2201QXC | A | 08/09/1999 | 3 | AMI | | Y | 6559-049 | 365 |
| 5962-99A2301QXC | | 08/06/1999 | 3 | AMI | | Y | 6571-026 | 365 |
| 5962-99A2401QXC | A | 12/23/1999 | | (NONE) | | | 6571-029 (GEN) | 365 |
| 5962-99A2402QXC | A | 12/23/1999 | 3 | AMI | | Y | 6571-031 | 365 |
| 5962-99A2501QXC | | 10/07/1999 | 3 | AMI | | Y | 6580-535 | 365 |
| 5962-99A2601QXC | | 12/22/1999 | 1 | AMI | | Y | 8513-001 | 365 |
| 5962-99B0101Q*C | F | 05/22/2002 | 2 | UTMC | | Y | UT06MRA010 | 365 |
| 5962R99B0101V*C | F | 05/22/2002 | 2 | UTMC | | Y | UT06MRA010 | 365 |
| 5962R99B0101Q9A | F | 05/22/2002 | 2 | UTMC | | Y | UT06MRA010_QDIE | 365 |
| 5962R99B0101V9A | F | 05/22/2002 | 2 | UTMC | | Y | UT06MRA010_VDIE | 365 |
| 5962-99B0102Q*C | F | 05/22/2002 | 2 | UTMC | | Y | UT06MRA025 | 365 |
| 5962R99B0102V*C | F | 05/22/2002 | 2 | UTMC | | Y | UT06MRA025 | 365 |
| 5962-99B0103Q*C | F | 05/22/2002 | 2 | UTMC | | Y | UT06MRA050 | 365 |
| 5962R99B0103V*C | F | 05/22/2002 | 2 | UTMC | | Y | UT06MRA050 | 365 |
| 5962-99B0104Q*C | F | 05/22/2002 | 2 | UTMC | | Y | UT06MRA075 | 365 |
| 5962R99B0104V*C | F | 05/22/2002 | 2 | UTMC | | Y | UT06MRA075 | 365 |
| 5962-99B0105Q*C | F | 05/22/2002 | 2 | UTMC | | Y | UT06MRA100 | 365 |
| 5962R99B0105V*C | F | 05/22/2002 | 2 | UTMC | | Y | UT06MRA100 | 365 |
| 5962-99B0106Q*C | F | 05/22/2002 | 2 | UTMC | | Y | UT06MRA150 | 365 |
| 5962R99B0106V*C | F | 05/22/2002 | 2 | UTMC | | Y | UT06MRA150 | 365 |
| 5962-99B0107Q*C | F | 05/22/2002 | 2 | UTMC | | Y | UT06MRA200 | 365 |
| 5962R99B0107V*C | F | 05/22/2002 | 2 | UTMC | | Y | UT06MRA200 | 365 |
| 5962-99B0108Q*C | F | 05/22/2002 | 2 | UTMC | | Y | UT06MRA250 | 365 |
| 5962R99B0108V*C | F | 05/22/2002 | 2 | UTMC | | Y | UT06MRA250 | 365 |
| 5962-99B0109Q*C | F | 05/22/2002 | 2 | UTMC | | Y | UT06MRA300 | 365 |
| 5962R99B0109V*C | F | 05/22/2002 | 2 | UTMC | | Y | UT06MRA300 | 365 |
| 5962-99B0110Q*C | F | 05/22/2002 | 2 | UTMC | | Y | UT06MRA350 | 365 |
| 5962R99B0110V*C | F | 05/22/2002 | 2 | UTMC | | Y | UT06MRA350 | 365 |
| 5962-99B0111Q*C | F | 05/22/2002 | 2 | UTMC | | Y | UT06MRA400 | 365 |
| 5962R99B0111V*C | F | 05/22/2002 | 2 | UTMC | | Y | UT06MRA400 | 365 |
| 5962-99B0112Q*C | F | 05/22/2002 | 2 | UTMC | | Y | UT06MRA450 | 365 |
| 5962R99B0112V*C | F | 05/22/2002 | 2 | UTMC | | Y | UT06MRA450 | 365 |
| 5962-99B0113Q*C | F | 05/22/2002 | 2 | UTMC | | Y | UT06MRA500 | 365 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART I, Listed By SMD PIN

| Drawing PIN 1/ | Rev | Date | ESD Status | Approved Source | Repl PIN or EOL Date 2/ | QML Source 3/ | Vendor Similar PIN 4/ | EIC |
|---|---|---|---|---|---|---|---|---|
| 5962R99B0113V*C | F | 05/22/2002 | 2 | UTMC | | Y | UT06MRA500 | 365 |
| 5962-99B0114Q*C | F | 05/22/2002 | 2 | UTMC | | Y | UT06MRA550 | 365 |
| 5962R99B0114V*C | F | 05/22/2002 | 2 | UTMC | | Y | UT06MRA550 | 365 |
| 5962-99B0115Q*C | F | 05/22/2002 | 2 | UTMC | | Y | UT06MRA600 | 365 |
| 5962R99B0115V*C | F | 05/22/2002 | 2 | UTMC | | Y | UT06MRA600 | 365 |
| 5962H99B0201QXC | | 04/23/1999 | | (NONE) | 06/30/1999 | | HR2125 (GEN) | 365 |
| 5962H99B0201VXC | | 04/23/1999 | | (NONE) | 06/30/1999 | | HR2125 (GEN) | 365 |
| 5962H99B0202QXC | | 04/23/1999 | | (NONE) | 06/30/1999 | | HR2210 (GEN) | 365 |
| 5962H99B0202VXC | | 04/23/1999 | | (NONE) | 06/30/1999 | | HR2210 (GEN) | 365 |
| 5962H99B0203QXC | | 04/23/1999 | | (NONE) | 06/30/1999 | | HR2340 (GEN) | 365 |
| 5962H99B0203VXC | | 04/23/1999 | | (NONE) | 06/30/1999 | | HR2340 (GEN) | 365 |
| 5962H99B0204QXC | | 04/23/1999 | | (NONE) | 06/30/1999 | | HR2010 (GEN) | 365 |
| 5962H99B0204VXC | | 04/23/1999 | | (NONE) | 06/30/1999 | | HR2010 (GEN) | 365 |
| 5962H99B0205QXC | | 04/23/1999 | | (NONE) | 06/30/1999 | | HR2065 (GEN) | 365 |
| 5962H99B0205VXC | | 04/23/1999 | | (NONE) | 06/30/1999 | | HR2065 (GEN) | 365 |
| 5962H99B0206QXC | | 04/23/1999 | | (NONE) | 06/30/1999 | | HR2090 (GEN) | 365 |
| 5962H99B0206VXC | | 04/23/1999 | | (NONE) | 06/30/1999 | | HR2090 (GEN) | 365 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

Notes:

1/ The lead finish shown for each PIN representing a hermetic package is the most readily available from the manufacturer listed for that part. If the desired lead finish is not listed, contact the vendor to determine its availability.

2/ Where a date is shown in this column, the approved source of supply listed for this PIN has issued an End-Of-Life notice for this product. According to this notice, last-time buys will be honored on or before the date shown.

3/ Where a "Y" appears in this column, one of the following applies:

a. The approved source listed has informed DSCC that the SMD part, designated by an SMD PIN with either a device class "M" identifier or without a device class identifier, is currently being processed on a DSCC approved QML flow, as allowed by paragraph 1.2 of MIL-STD-883. By maintaining the same PIN, the manufacturer listed as an approved source has certified that no changes affecting form, fit or function have occurred for the device.

b. The approved source is processing the SMD on a DSCC approved QML flow in accordance with MIL-PRF-38535, for those designated by an SMD PIN with device class "Q", "V", "T" or "N" identifiers, or in accordance with MIL-PRF-38534, for those designated by an SMD PIN with device class "H", "K", "D", "E" or "G" identifiers.

4/ Vendor similar PIN's that include "(GEN)*" are not valid part numbers. These are generic numbers, provided as references for those SMD parts that no longer have approved sources.



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

| Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN |
|---|---|---|---|---|---|
| ADC-HX/883B | 5962-8850801XA | MSK0033B | 8001401ZC | REF01Z/883B | 5962-8958104PA |
| ADC-HX/883B | 5962-8850801XC | FLH0041G/883 | 8508701ZA | FLH0101AK/883 | 8508901YA |
| ADC-HZ/883B | 5962-8850802XA | MSK0041B | 8508701ZA | FLH0101K/883 | 8508902YA |
| ADC-HZ/883B | 5962-8850802XC | MSK0041B | 8508701ZC | ACS02 (GEN) | 5962F9860101V9A |
| DAC-HKB/883B | 5962-8952801XA | 0056 (GEN) | 7800801CA | ACS02 (GEN) | 5962F9860101VXC |
| DAC-HKB/883B | 5962-8952801XC | 0056 (GEN) | 7800801GA | ACS02-03 (GEN) | 5962F9860101VCC |
| DAC-HPB/883B | 5962-8953101HXC | LCB007 (GEN) | 5962-94B0302M4C | HCS02 (GEN) | 5962R9567901VCC |
| FLP (GEN) | 5962H9210301QZC | LCB007 (GEN) | 5962-94B0302M5C | HCS02HMSR | 5962R9567901V9A |
| FLP (GEN) | 5962H9210301VZC | LCB007 (GEN) | 5962-94B0302M6C | HCS02KMSR | 5962R9567901VXC |
| PA21 (GEN) | 5962-9215201HXA | LCB007 (GEN) | 5962-94B0302M7C | HCTS02 (GEN) | 5962R9568201V9A |
| ACS00 (GEN) | 5962F9565001V9A | LCB007 (GEN) | 5962-94B0302M8C | HCTS02 (GEN) | 5962R9568201VCC |
| ACS00 (GEN) | 5962F9565001VCC | LCB007 (GEN) | 5962-94B0302M9C | HCTS02 (GEN) | 5962R9568201VXC |
| ACS00 (GEN) | 5962F9565001VXC | LCB007 (GEN) | 5962-94B0302MCC | PA02M/883 | 5962-9067901HXA |
| ACTS00 (GEN) | 5962F9563601V9A | LCB007 (GEN) | 5962-94B0302MMC | REF02 (GEN) | 85514022C |
| ACTS00 (GEN) | 5962F9563601VCC | LCB007 (GEN) | 5962-94B0302MNC | REF02 (GEN) | 8551402GC |
| ACTS00 (GEN) | 5962F9563601VXC | LCB007 (GEN) | 5962-94B0302MTC | REF02 (GEN) | 8551402PA |
| HCS00DMSR | 5962R9572401VCC | LCB007 (GEN) | 5962-94B0302MUC | REF02AJ/883 | 8551401GA |
| HCS00HMSR | 5962R9572401V9A | LCB007 (GEN) | 5962-94B0302MXC | REF02AJ/883B | 8551403GC |
| HCS00KMSR | 5962R9572401VXC | LCB007 (GEN) | 5962-94B0302MYC | REF02AJ/QMLR | 5962R8551401VGA |
| HCTS00 (GEN) | 5962R9563701V9A | LCB007 (GEN) | 5962-94B0302MZC | REF02AJ/QMLV | 5962-8551401VGA |
| HCTS00DMSR | 5962R9563701VCC | LH0070-0H/883 | 5962-8688201XA | REF02AL/QMLR | 5962R8551401VHA |
| HCTS00KMSR | 5962R9563701VXC | LH0070-1H/883 | 5962-8688202XA | REF02AL/QMLV | 5962-8551401VHA |
| ACS00-02 (GEN) | 5962F9565002V9A | LH0070-2H/883 | 5962-8688203XA | REF-02ARC/883 | 85514012A |
| ACS00-02 (GEN) | 5962F9565002VXC | AMP01AD/QMLV | 5962-8863001VVA | REF02ARC/QMLR | 5962R8551401V2A |
| ACS00DMSR-02 | 5962F9565002VCC | AMP01AN/QMLV | 5962-8863001VKA | REF02ARC/QMLV | 5962-8551401V2A |
| ACTS00-02 (GEN) | 5962F9563602V9A | AMP01ATC/QMLV | 5962-8863001V3A | REF-02AZ/883 | 8551401PA |
| ACTS00-02 (GEN) | 5962F9563602VCC | AMP-01AX/883 | 5962-8863001VA | REF02AZ/883B | 8551403PA |
| ACTS00-02 (GEN) | 5962F9563602VXC | AMP-01BTC/883 | 5962-88630023A | REF02AZ/QMLR | 5962R8551401VPA |
| CTS0002 (GEN) | 7801301GA | AMP-01BX/883 | 5962-8863002VA | REF02AZ/QMLV | 5962-8551401VPA |
| FLH0002H/883 | 7801301XA | AMP01D/QMLV | 5962-8863003VVA | REF02J/883B | 8551404GC |
| MSK0002H | 7801301XA | AMP01N/QMLV | 5962-8863003VKA | REF02RC/883B | 85514042C |
| MSK0002H | 7801301XC | AMP01TC/QMLV | 5962-8863003V3A | REF02Z/883B | 8551404PA |
| SEN-0002H | 7801301XA | CMP01 (GEN) | 5962-8987101GA | DAC-02200II-609 | 5962-9063401HXA |
| SEN-0002H | 7801301XC | CMP01 (GEN) | 5962-8987101PA | HI-0222 (GEN) | 5962-9456201M2A |
| MSK 0006H | 5962-8761701XA | REF01 (GEN) | 5962-89581022A | HI-0222 (GEN) | 5962-9456201MCA |
| MSK 0006H | 5962-8761701XC | REF01 (GEN) | 5962-8958102GA | DAC-02310-112 | 5962-8851701XA |
| MSK 0008H | 5962-8761702XA | REF01 (GEN) | 5962-8958102PA | DAC-02310-112 | 5962-8851701XC |
| MSK 0008H | 5962-8761702XC | REF01A (GEN) | 5962-89581012A | DAC-02310-113 | 5962-8851702XA |
| FLH0021K/883 | 8508801YA | REF01A (GEN) | 5962-8958101GA | DAC-02310-113 | 5962-8851702XC |
| MSK0021B | 8508801YA | REF01AJ/883B | 5962-8958103GC | DAC-02311-112 | 5962-8851701YA |
| MSK0021B | 8508801YC | REF01AJ/QMLR | 5962R8958101VGA | DAC-02311-112 | 5962-8851701YC |
| MRG002160A (GEN) | 5962-9450301MZA | REF01AJ/QMLV | 5962-8958101VGA | DAC-02311-113 | 5962-8851702YA |
| MRG002160B (GEN) | 5962-9450302MYA | REF01AL/QMLR | 5962R8958101VHA | DAC-02311-113 | 5962-8851702YC |
| 0026 (GEN) | 7800802PA | REF01AL/QMLV | 5962-8958101VHA | MOH0268D (GEN) | 5962-8858101EA |
| DS0026H/883 | 7800802GA | REF01ARC/883B | 5962-89581032C | MOH0268D (GEN) | 5962-8858101FA |
| DS0026J/883 | 7800802CA | REF01ARC/QMLR | 5962R8958101V2A | MOH0268D (GEN) | 5962-88581012A |
| ADC00300 (GEN) | 5962-8854201XA | REF01ARC/QMLV | 5962-8958101V2A | TL027 (GEN) | 84185032A |
| ADC00302 (GEN) | 5962-8854201YA | REF01AZ/883B | 5962-8958103PA | TL027 (GEN) | 8418503CA |
| FLH0032G/883 | 8001301ZA | REF01AZ/883C | 5962-8958101PA | ADDC02803SC (GEN) | 5962-9760101HXC |
| MSK0032B | 8001301ZA | REF01AZ/QMLR | 5962R8958101VPA | ADDC02805SATV/QML | 5962-9560701HXC |
| MSK0032B | 8001301ZC | REF01AZ/QMLV | 5962-8958101VPA | ADDC02808PB (GEN) | 5962-9763401HXC |
| FLH0033G/883 | 8001401ZA | REF01J/883B | 5962-8958104GC | ADDC02809SA (GEN) | 5962-9760201HXC |
| MSK0033B | 8001401ZA | REF01RC/883B | 5962-89581042C | ADDC02812DA (GEN) | 5962-9684101HXC |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

| Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN |
|---|---|---|---|---|---|
| ADDC02815DA (GEN) | 5962-9684201HXC | HS9-REF05RH-Q | 5962-96A0301VXC | UT06MRA500 | 5962-99B0113Q*C |
| GEM02901B2A | 5962-87542012A | REF05AJ/QMLR | 5962R0051601VGA | UT06MRA500 | 5962R99B0113V*C |
| GEM02901B2C | 5962-87542012C | REF05AJ/QMLV | 5962-0051601VGA | UT06MRA550 | 5962-99B0114Q*C |
| GEM02901BRA | 5962-8754201RA | REF05AL/QMLR | 5962R0051601VHA | UT06MRA550 | 5962R99B0114V*C |
| GEM02901BRC | 5962-8754201RC | REF05AL/QMLV | 5962-0051601VHA | UT06MRA600 | 5962-99B0115Q*C |
| GEM02901BSA | 5962-8754201SA | REF05ARC/QMLR | 5962R0051601V2A | UT06MRA600 | 5962R99B0115V*C |
| GEM02901BSC | 5962-8754201SC | REF05ARC/QMLV | 5962-0051601V2A | HOS-060S (GEN) | 5962-8857902XC |
| ACS03DMSR | 5962F9670301VCC | REF05AZ/QMLR | 5962R0051601VPA | UT06MRA010 | 5962-04B0101Q*C |
| ACS03HMSR | 5962F9670301V9A | REF05AZ/QMLV | 5962-0051601VPA | UT06MRA010 | 5962F04B0101V*C |
| ACS03KMSR | 5962F9670301VXC | HOS-050A (GEN) | 5962-8857901XC | UT06MRA025 | 5962-04B0102Q*C |
| AMP03BJ/883 | 5962-9563901MGA | GEM051012A | 76036012A | UT06MRA025 | 5962F04B0102V*C |
| ADH-030II-12-1 | 5962-9063401HXC | GEM051012C | 76036012C | UT06MRA050 | 5962-04B0103Q*C |
| HTC-0300A (GEN) | 5962-9073001HYC | GEM05101EA | 7603601EA | UT06MRA050 | 5962F04B0103V*C |
| ACS03-02 (GEN) | 5962F9670302V9A | GEM05101EC | 7603601EC | UT06MRA075 | 5962-04B0104Q*C |
| ACS03-02 (GEN) | 5962F9670302VCC | GEM05101FX | 7603601FA | UT06MRA075 | 5962F04B0104V*C |
| ACS03-02 (GEN) | 5962F9670302VXC | GEM05101FX | 7603601FC | TL061 (GEN) | 81023012A |
| TL031 (GEN) | 5962-9086101Q2A | HAA0-51154R4552 | 5962-97A1001V9A | TL061 (GEN) | 8102301GA |
| TL031 (GEN) | 5962-9086101QPA | HAA0-51156R4554 | 5962-97A0801V9A | TL061 (GEN) | 8102301HA |
| TL032 (GEN) | 5962-9086102Q2A | TL052 (GEN) | 5962-9472601Q2A | TL061 (GEN) | 8102301PA |
| TL032 (GEN) | 5962-9086102QPA | TL052 (GEN) | 5962-9472601QPA | UT06MRA100 | 5962-04B0105Q*C |
| TL034 (GEN) | 5962-9086103Q2A | ACS05 (GEN) | 5962F9860201V9A | UT06MRA100 | 5962R04B0105V*C |
| TL034 (GEN) | 5962-9086103QCA | ACS05 (GEN) | 5962F9860201VCC | UT06MRA150 | 5962-04B0106Q*C |
| GEM03701B2A | 76010012A | ACS05 (GEN) | 5962F9860201VXC | UT06MRA150 | 5962R04B0106V*C |
| GEM03701B2C | 76010012C | HS0-SW06RH-Q | 5962-97A0201V9A | TL062 (GEN) | 8102302CA |
| GEM03701BEA | 7601001EA | HS9-SW06RH-Q | 5962-97A0201VXC | TL062 (GEN) | 8102302GA |
| GEM03701BEC | 7601001EC | SW06BQ/883 | 5962-8966901EA | TL062MFKB | 81023022A |
| GEM03701BFA | 7601001FA | SW06BRC/883 | 5962-89669012A | TL062MJGB | 8102302PA |
| GEM03701BFC | 7601001FC | UT06MRA010 | 5962-99B0101Q*C | TL062MUB | 8102302HA |
| ACS04DMSR-03 | 5962F9860301VCC | UT06MRA010 | 5962R99B0101V*C | UT06MRA200 | 5962-04B0107Q*C |
| ACS04HMSR-03 | 5962F9860301V9A | UT06MRA010_QDIE | 5962R99B0101Q9A | UT06MRA200 | 5962R04B0107V*C |
| ACS04KMSR-03 | 5962F9860301VXC | UT06MRA010_VDIE | 5962R99B0101V9A | UT06MRA250 | 5962-04B0108Q*C |
| ACTS04 (GEN) | 5962F9671201VCC | UT06MRA025 | 5962-99B0102Q*C | UT06MRA250 | 5962R04B0108V*C |
| ACTS04 (GEN) | 5962F9671201VXC | UT06MRA025 | 5962R99B0102V*C | UT06MRA300 | 5962-04B0109Q*C |
| BUF04 (GEN) | 5962-9556701M2A | UT06MRA050 | 5962-99B0103Q*C | UT06MRA300 | 5962R04B0109V*C |
| BUF04 (GEN) | 5962-9556701MPA | UT06MRA050 | 5962R99B0103V*C | GEM06301Q2A | 5962-86890012A |
| CMP04B (GEN) | 5962-8990403CA | UT06MRA075 | 5962-99B0104Q*C | GEM06301Q2C | 5962-86890012C |
| HCS04 (GEN) | 5962R9572501V9A | UT06MRA075 | 5962R99B0104V*C | GEM06301QCA | 5962-8689001CA |
| HCS04 (GEN) | 5962R9572501VCC | UT06MRA100 | 5962-99B0105Q*C | GEM06301QCC | 5962-8689001CC |
| HCS04 (GEN) | 5962R9572501VXC | UT06MRA100 | 5962R99B0105V*C | GEM06301QDA | 5962-8689001DA |
| HCTS04DMSR | 5962R9573201VCC | UT06MRA150 | 5962-99B0106Q*C | GEM06301QDC | 5962-8689001DC |
| HCTS04HMSR | 5962R9573201V9A | UT06MRA150 | 5962R99B0106V*C | UT06MRA350 | 5962-04B0110Q*C |
| HCTS04KMSR | 5962R9573201VXC | UT06MRA200 | 5962-99B0107Q*C | UT06MRA350 | 5962R04B0110V*C |
| TL040 (GEN) | 5962-9311701M2A | UT06MRA200 | 5962R99B0107V*C | TL064MFKB | 81023032A |
| TL040 (GEN) | 5962-9311701MEA | UT06MRA250 | 5962-99B0108Q*C | TL064MJB | 8102303CA |
| ACTS04 (GEN) | 5962F9671202V9A | UT06MRA250 | 5962R99B0108V*C | TL064MWB | 8102303DA |
| ACTS04DMSR-02 | 5962F9671202VCC | UT06MRA300 | 5962-99B0109Q*C | UT06MRA400 | 5962-04B0111Q*C |
| ACTS04KMSR-02 | 5962F9671202VXC | UT06MRA300 | 5962R99B0109V*C | UT06MRA400 | 5962R04B0111V*C |
| HCS05 (GEN) | 5962R9580101V9A | UT06MRA350 | 5962-99B0110Q*C | MRG064-128 (GEN) | 5962-9317801MZA |
| HCS05 (GEN) | 5962R9580101VCC | UT06MRA350 | 5962R99B0110V*C | UT06MRA450 | 5962-04B0112Q*C |
| HCS05KMSR | 5962R9580101VXC | UT06MRA400 | 5962-99B0111Q*C | UT06MRA450 | 5962R04B0112V*C |
| HS0-CMP05RH-Q | 5962-96A0201V9A | UT06MRA400 | 5962R99B0111V*C | UT06MRA500 | 5962-04B0113Q*C |
| HS0-REF05RH-Q | 5962-96A0301V9A | UT06MRA450 | 5962-99B0112Q*C | UT06MRA500 | 5962R04B0113V*C |
| HS9-CMP05RH-Q | 5962-96A0201VXC | UT06MRA450 | 5962R99B0112V*C | UT06MRA550 | 5962-04B0114Q*C |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

| Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN |
|---|---|---|---|---|---|
| UT06MRA550 | 5962R04B0114V*C | ACS08KMSR | 5962F9565101VXC | GEM08501QEA | 7700401EA |
| 06550-022 | 5962-97A1501QXC | ACTS08 (GEN) | 5962F9565701VCC | GEM08501QEC | 7700401EC |
| 06580-044 | 5962-01A1401QXC | ACTS08 (GEN) | 5962F9565701VXC | GEM08501QFA | 7700401FA |
| 06583-011 | 5962-02A0301QXA | DAC08AF/QMLR | 5962R8993202VFA | GEM08501QFC | 7700401FC |
| 06583-014 | 5962-02A0401QXA | DAC08AQ/QMLR | 5962R8993202VEA | ADC0851 (GEN) | 5962-9551301QEA |
| UT06MRA600 | 5962-04B0115Q*C | DAC08ARC/QMLR | 5962R8993202V2A | Z0853004 (GEN) | 5962-8752702QA |
| UT06MRA600 | 5962R04B0115V*C | DAC08XF/QMLR | 5962R8993201VFA | Z0853004 (GEN) | 5962-8752702YA |
| VAC068A (GEN) | 5962-9200901MXC | DAC08XQ/QMLR | 5962R8993201VEA | Z0853006 (GEN) | 5962-8752701QA |
| VAC068A (GEN) | 5962-9200901MYA | DAC08XRC | 5962-89932012A | Z0853006 (GEN) | 5962-8752701YA |
| VIC068A (GEN) | 5962-9201001MXC | DAC08XRC/QMLR | 5962R8993201V2A | DAC0854C (GEN) | 5962-9551201QRA |
| VIC068A (GEN) | 5962-9201001MYC | HCS08DMSR | 5962R9568001VCC | ADC0858 (GEN) | 5962-9551302QRA |
| GEM06801QZA | 8405701ZA | HCS08HMSR | 5962R9568001V9A | Z0858106 (GEN) | 5962-87526022A |
| GEM06801QZC | 8405701ZC | HCS08KMSR | 5962R9568001VXC | Z0858106 (GEN) | 5962-8752602VA |
| GEM06803QQA | 7700703QA | HCTS08DMSR | 5962R9568301VCC | Z0858110 (GEN) | 5962-87526012A |
| GEM06803QQC | 7700703QC | HCTS08HMSR | 5962R9568301V9A | Z0858110 (GEN) | 5962-8752601VA |
| GEM06803QZA | 7700703ZA | HCTS08KMSR | 5962R9568301VXC | 08785-001 | 5962-02A0501QXA |
| GEM06803QZC | 7700703ZC | MUX-08AQ | 5962-8771601EA | GEM08801QEA | 8002301EA |
| 06817-539 | 5962-02A0601QXC | MUX-08BQ | 5962-8771602EA | GEM08801QEC | 8002301EC |
| OP07 (GEN) | 82036022A | MUX-08BRC | 5962-87716022A | GEM08801QFA | 8002301FA |
| OP07 (GEN) | 8203602GA | PA08M/883 | 5962-9072301HXA | GEM08801QFC | 8002301FC |
| OP07 (GEN) | 8203602PA | Z0800104CMB | 8000301XA | OP-09 (GEN) | 5962-9308301MCA |
| OP07A (GEN) | 82036012A | Z0800104LMB | 8000301UA | PA09M/883 | 5962-9170001HXA |
| OP07A (GEN) | 8203601GA | Z0800106LMB | 8000303UA | PA09M/883 | 5962-9170001HXC |
| OP07A (GEN) | 8203601PA | Z0800106LMB | 8000303XA | GEM09201QEA | 8602001EA |
| OP07AJ/QMLR | 5962R9863901VGA | Z0800110CMB | 8000304XA | GEM09201QEC | 8602001EC |
| OP07AL/QMLR | 5962R9863901VHA | Z0800110LMB | 8000304UA | GEM09201QFA | 8602001FA |
| OP07ARC/QMLR | 5962R9863901V2A | Z0800204CMB | 8000302QA | GEM09201QFC | 8602001FC |
| OP07AZ/QMLR | 5962R9863901VPA | Z0800204LMB | 8000302YA | GEM09202QEA | 8602002EA |
| PA07M/883 | 5962-9063801HXA | Z0800210CMB | 8000305QA | GEM09202QEC | 8602002EC |
| TL071 (GEN) | 81023042A | Z0800210LMB | 8000305YA | GEM09202QFA | 8602002FA |
| TL071 (GEN) | 8102304GA | ACS08-02 (GEN) | 5962F9565102V9A | GEM09202QFC | 8602002FC |
| TL071 (GEN) | 8102304HA | ACS08-02 (GEN) | 5962F9565102VCC | GEM09301EA | 5962-8672601EA |
| TL071 (GEN) | 8102304PA | ACS08-02 (GEN) | 5962F9565102VXC | GEM09301EC | 5962-8672601EC |
| TL072 (GEN) | 8102305CA | ACTS08 (GEN) | 5962F9565702V9A | GEM09301FA | 5962-8672601FA |
| TL072 (GEN) | 8102305GA | ACTS08DMSR-02 | 5962F9565702VCC | DAC-HPB-1/883 | 5962-8953102HXC |
| TL072MFKB | 81023052A | ACTS08KMSR-02 | 5962F9565702VXC | ACS10 (GEN) | 5962F9565201VCC |
| TL072MJGB | 8102305PA | ADC0802 (GEN) | 5962-9096601MRA | ACS10 (GEN) | 5962F9565201VXC |
| TL072MUB | 8102305HA | ADC08061 (GEN) | 5962-9551401QRA | ACTS10 (GEN) | 5962F9565801VCC |
| GEM07301Q2A | 5962-86702012A | TL081MFKB | 5962-9851502Q2A | ACTS10 (GEN) | 5962F9565801VXC |
| GEM07301Q2C | 5962-86702012C | TL081MJGB | 5962-9851502QPA | HCS10 (GEN) | 5962R9577701V9A |
| GEM07301QRA | 5962-8670201RA | TL082MFKB | 5962-9851501Q2A | HCS10 (GEN) | 5962R9577701VCC |
| GEM07301QRC | 5962-8670201RC | TL082MJGB | 5962-9851501QPA | HCS10 (GEN) | 5962R9577701VXC |
| GEM07301QSA | 5962-8670201SA | TL084MFKB | 5962-9851503Q2A | HCTS10 (GEN) | 5962R9576501VCC |
| GEM07301QSC | 5962-8670201SC | TL084MJB | 5962-9851503QCA | HCTS10 (GEN) | 5962R9576501VXC |
| TL074MFKB | 81023062A | Z08400 (GEN) | 5962-3848001MQA | HCTS10HMSR | 5962R9576501V9A |
| TL074MJB | 8102306CA | Z08400 (GEN) | 5962-3848001MXA | HS0-REF10RH-Q | 5962-96A0101V9A |
| TL074MWB | 8102306DA | Z08400 (GEN) | 5962-3848001MYA | HS9-REF10RH-Q | 5962-96A0101VXC |
| GEM07501Q2A | 5962-86723012A | Z08400 (GEN) | 5962-3848002MQA | LCA10K (GEN) | 5962-95B0101M4C |
| GEM07501Q2C | 5962-86723012C | Z08400 (GEN) | 5962-3848002MXA | LCA10K (GEN) | 5962-95B0101M5C |
| GEM07501QRA | 5962-8672301RA | Z08400 (GEN) | 5962-3848002MYA | LCA10K (GEN) | 5962-95B0101M6C |
| GEM07501QRC | 5962-8672301RC | Z08400 (GEN) | 5962-3848003MQA | LCA10K (GEN) | 5962-95B0101M7C |
| ACS08 (GEN) | 5962F9565101V9A | Z08400 (GEN) | 5962-3848003MXA | LCA10K (GEN) | 5962-95B0101M8C |
| ACS08DMSR | 5962F9565101VCC | Z08400 (GEN) | 5962-3848003MYA | LCA10K (GEN) | 5962-95B0101M9C |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

| Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN |
|---|---|---|---|---|---|
| LCA10K (GEN) | 5962-95B0101MCC | LEA100 (GEN) | 5962-94B0303MXC | 100324J-QMLV | 5962-9153001VXA |
| LCA10K (GEN) | 5962-95B0101MMC | LEA100 (GEN) | 5962-94B0303MYC | 100324W-QMLV | 5962-9153001VYA |
| LCA10K (GEN) | 5962-95B0101MNC | LEA100 (GEN) | 5962-94B0303MZC | 100325DMQB | 5962-9153101MXA |
| LCA10K (GEN) | 5962-95B0101MTC | LMF100A (GEN) | 5962-9153301M2A | 100325FMQB | 5962-9153101MYA |
| LCA10K (GEN) | 5962-95B0101MUC | LMF100A (GEN) | 5962-9153301MRA | 100325J-QMLV | 5962-9153101VXA |
| LCA10K (GEN) | 5962-95B0101MXC | SCANPSC100F (GEN) | 5962-9475001QXA | 100325WFQMLV | 5962F9153101VYA |
| LCA10K (GEN) | 5962-95B0101MYC | SCANPSC100FFMQB | 5962-9475001QYA | 100325W-QMLV | 5962-9153101VYA |
| LCA10K (GEN) | 5962-95B0101MZC | SCANPSC100FLMQB | 5962-9475001Q3A | 100329DMQB | 5962-9206601MXA |
| LM10H/883B | 5962-8760401GA | UT100E/R*QCH | 5962H96B0208Q*A | 100329FMQB | 5962-9206601MYA |
| PA10M/883 | 5962-9082801HXA | UT100E/R*VCH | 5962H96B0208V*A | 100331DMQB | 5962-9153601MXA |
| REF10A (GEN) | 5962-8947901GA | UT100E/R_QCH | 5962H97B0408QXC | 100331FMQB | 5962-9153601MYA |
| REF10AJ/QMLR | 5962R8947901VGA | UT100E/R_VCH | 5962H97B0408VXC | 100331J-QMLV | 5962-9153601VXA |
| REF10AJ/QMLV | 5962-8947901VGA | XQV1000-4BG560 | 5962-9957401NUA | 100331WFQMLV | 5962F9153601VYA |
| REF10AL/QMLR | 5962R8947901VHA | XQV1000-4CG560 | 5962-9957401QXA | 100331W-QMLV | 5962-9153601VYA |
| REF10AL/QMLV | 5962-8947901VHA | XQVR1000-4BG560 | 5962R9957401NUA | 100336DMQB | 5962-9230601MXA |
| REF10ARC/QMLR | 5962R8947901V2A | XQVR1000-4CG560 | 5962R9957401QXA | 100336FMQB | 5962-9230601MYA |
| REF10ARC/QMLV | 5962-8947901V2A | LT1001A (GEN) | 5962-8773803GA | 100336J-QMLV | 5962-9230601VXA |
| REF10AZ/QMLR | 5962R8947901VPA | LT1001A (GEN) | 5962-8773803PA | 100336W-QMLV | 5962-9230601VYA |
| REF10AZ/QMLV | 5962-8947901VPA | 100H1042 (GEN) | 5962-9207502MYA | 100341DMQB | 5962-9459101MXA |
| REF10B (GEN) | 5962-8947902GA | ACS10 (GEN) | 5962F9565202V9A | 100341FMQB | 5962-9459101MYA |
| RHFAC10K01Q | 5962F8761001XC | ACS10 (GEN) | 5962F9565202VCC | 100341J-QMLV | 5962-9459101VXA |
| RHFAC10K01V | 5962F8761001VXC | ACS10 (GEN) | 5962F9565202VXC | 100341WFQMLV | 5962F9459101VYA |
| RHFAC10K02Q | 5962F8761001XA | ACTS10 (GEN) | 5962F9565802V9A | 100341W-QMLV | 5962-9459101VYA |
| RHFAC10K02V | 5962F8761001VXA | ACTS10 (GEN) | 5962F9565802VCC | 100351DMQB | 5962-9457901MXA |
| SMP-10A (GEN) | 5962-8954103CA | ACTS10 (GEN) | 5962F9565802VXC | 100351FMQB | 5962-9457901MYA |
| SMP-10B (GEN) | 5962-89541042A | MTL1002AMJ/883 | 5962-8771501CA | 100351J-QMLV | 5962-9457901VXA |
| SMP-10B (GEN) | 5962-8954104CA | LT1003 (GEN) | 5962-8987301YA | 100351W-QMLV | 5962-9457901VYA |
| BXM-100 (GEN) | 5962-98A1601VXA | 100301 (GEN) | 5962-9152801MXA | 100351WRQMLV | 5962R9457901VYA |
| LCA100 (GEN) | 5962-94B0301M4C | 100301 (GEN) | 5962-9152801VXA | 100355DMQB | 5962-9165401MXA |
| LCA100 (GEN) | 5962-94B0301M5C | 100301FMQB | 5962-9152801MYA | 100355FMQB | 5962-9165401MYA |
| LCA100 (GEN) | 5962-94B0301M6C | 100301W-QMLV | 5962-9152801VYA | 100355J-QMLV | 5962-9165401VXA |
| LCA100 (GEN) | 5962-94B0301M7C | 100302DMQB | 5962-9152802MXA | 100355W-QMLV | 5962-9165401VYA |
| LCA100 (GEN) | 5962-94B0301M8C | 100302FMQB | 5962-9152802MYA | 100363DMQB | 5962-9165501MXA |
| LCA100 (GEN) | 5962-94B0301M9C | 100302J-QMLV | 5962-9152802VXA | 100363FMQB | 5962-9165501MYA |
| LCA100 (GEN) | 5962-94B0301MCC | 100302W-QMLV | 5962-9152802VYA | 100364DMQB | 5962-9459201MXA |
| LCA100 (GEN) | 5962-94B0301MMC | 100304DMQB | 5962-9153701MXA | 100364FMQB | 5962-9459201MYA |
| LCA100 (GEN) | 5962-94B0301MNC | 100304FMQB | 5962-9153701MYA | 100364J-QMLV | 5962-9459201VXA |
| LCA100 (GEN) | 5962-94B0301MTC | 100304J-QMLV | 5962-9153701VXA | 100364W-QMLV | 5962-9459201VYA |
| LCA100 (GEN) | 5962-94B0301MUC | 100304W-QMLV | 5962-9153701VYA | LT1004-1.2 (GEN) | 5962-8859701XA |
| LCA100 (GEN) | 5962-94B0301MXC | 100307DMQB | 5962-9459001MXA | 100E416 (GEN) | 5962-9309802MYA |
| LCA100 (GEN) | 5962-94B0301MYC | 100307FMQB | 5962-9459001MYA | LT1004-2.5 (GEN) | 5962-8859702XA |
| LCA100 (GEN) | 5962-94B0301MZC | 100307J-QMLV | 5962-9459001VXA | 100E501 (GEN) | 5962-9309902MYA |
| LEA100 (GEN) | 5962-94B0303M4C | 100307W-QMLV | 5962-9459001VYA | 100E504 (GEN) | 5962-9310002MYA |
| LEA100 (GEN) | 5962-94B0303M5C | 100313DMQB | 5962-9673201QXA | 100E507 (GEN) | 5962-9310102MYA |
| LEA100 (GEN) | 5962-94B0303M6C | 100313FMQB | 5962-9673201QYA | 100E511 (GEN) | 5962-9232702MYA |
| LEA100 (GEN) | 5962-94B0303M7C | 100314DMQB | 5962-9162901MXA | 100E516 (GEN) | 5962-9234302MYA |
| LEA100 (GEN) | 5962-94B0303M8C | 100314FMQB | 5962-9162901MYA | 100E516 (GEN) | 5962-9234302MZA |
| LEA100 (GEN) | 5962-94B0303M9C | 100314J-QMLV | 5962-9162901VXA | 100E531 (GEN) | 5962-9310202MYA |
| LEA100 (GEN) | 5962-94B0303MCC | 100314W-QMLV | 5962-9162901VYA | 100E551 (GEN) | 5962-9310402MYA |
| LEA100 (GEN) | 5962-94B0303MMC | 100315FMQB | 5962-9469601MFA | 1006 (GEN) | 5962-8993301GA |
| LEA100 (GEN) | 5962-94B0303MNC | 100315W-QMLV | 5962-9469601VFA | 1006 (GEN) | 5962-8993301PA |
| LEA100 (GEN) | 5962-94B0303MTC | 100324DMQB | 5962-9153001MXA | LT1006A (GEN) | 5962-8993302GA |
| LEA100 (GEN) | 5962-94B0303MUC | 100324FMQB | 5962-9153001MYA | LT1006A (GEN) | 5962-8993302PA |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

| Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN |
|---|---|---|---|---|---|
| ADC10061 (GEN) | 5962-9232901QRA | A1010B-PG84B | 5962-9096403MXC | MTL1013AMD8 | 5962-8876001PA |
| 1006148 (GEN) | 5962-9082003HXC | MTL1010MH | 5962-8856201XA | MTL1013MD8 | 5962-8876002PA |
| 1006148A (GEN) | 5962-9082004HXC | MTL1010MK | 5962-8856201YA | LT1014 (GEN) | 5962-8967702DA |
| ADC10062 (GEN) | 5962-9232902QJA | TGC1010 | 5962-94B0501Q4A | LT1014 (GEN) | 5962-8967702XA |
| 1006-341H/2 (GEN) | 5962-9213803HXC | TGC1010 | 5962-94B0501Q5A | LT1014AMFKB | 5962-89677012A |
| 1006-341S/2 (GEN) | 5962-9213804HXC | TGC1010 | 5962-94B0501Q6A | LT1014AMJB | 5962-8967701CA |
| 1006-341VR/2 (GEN) | 5962-9213801HXC | TGC1010 | 5962-94B0501QMA | LT1014MFKB | 5962-89677022A |
| 1006-341VS/2 (GEN) | 5962-9213802HXC | TGC1010 | 5962-94B0501QNA | LT1014MJB | 5962-8967702CA |
| ADC10064 (GEN) | 5962-9232903QXA | TGC1010 | 5962-94B0501QTA | MG1014 | 5962-00B0108Q*C |
| MTL1007AM2/883 | 5962-87578012A | TGC1010 | 5962-94B0501QUA | MG1014E | 5962-00B0101Q*C |
| MTL1007AM2/883 | 5962-87578012C | TGC1010 | 5962-94B0501QXA | MG1014E | 5962-00B0101V*C |
| MTL1007AM2/883 | 5962-87578022A | TGC1010 | 5962-94B0501QYA | MM0-G1014*MQ | 5962-00B0108Q9A |
| MTL1007AM2/883 | 5962-87578022C | TGC1010 | 5962-94B0501QZA | MM0-G1014EH*MQ | 5962-00B0101Q9A |
| MTL1007AMD8/883 | 5962-8757801PA | 1010A-1 (GEN) | 5962-9096402MXA | SM0-G1014EH*SV | 5962-00B0101V9A |
| MTL1007AMD8/883 | 5962-8757801PC | A1010B-1PG84B | 5962-9096404MXA | LT1016 (GEN) | 5962-8684501IA |
| MTL1007AMH/883 | 5962-8757801GA | A1010B-1PG84B | 5962-9096404MXC | TGC1016 | 5962-94B0502Q4A |
| MTL1007AMH/883 | 5962-8757801GC | 10H1042 (GEN) | 5962-9207501MYA | TGC1016 | 5962-94B0502Q5A |
| MTL1007AMJ8/883 | 5962-8757801PA | AS10H1042Q28/883C | 5962-9207501MXA | TGC1016 | 5962-94B0502Q6A |
| MTL1007AMJ8/883 | 5962-8757801PC | 1010-55 (GEN) | 5962-8873301UA | TGC1016 | 5962-94B0502QMA |
| MTL1007MD8/883 | 5962-8757802PA | 1010-55 (GEN) | 5962-8873301XA | TGC1016 | 5962-94B0502QNA |
| MTL1007MD8/883 | 5962-8757802PC | 1010-55 (GEN) | 5962-8873301ZA | TGC1016 | 5962-94B0502QTA |
| MTL1007MH/883 | 5962-8757802GA | 1010-65 (GEN) | 5962-8873302UA | TGC1016 | 5962-94B0502QUA |
| MTL1007MH/883 | 5962-8757802GC | 1010-65 (GEN) | 5962-8873302XA | TGC1016 | 5962-94B0502QXA |
| MTL1007MJ8/883 | 5962-8757802PA | 1010-65 (GEN) | 5962-8873302ZA | TGC1016 | 5962-94B0502QYA |
| MTL1007MJ8/883 | 5962-8757802PC | 1010-75 (GEN) | 5962-8873303UA | TGC1016 | 5962-94B0502QZA |
| IS0-1009RH-Q | 5962F0052301V9A | 1010-75 (GEN) | 5962-8873303XA | ISPLSI1016-60LH/88 | 5962-9476201MXC |
| IS2-1009RH-8 | 5962F0052301QXC | 1010-75 (GEN) | 5962-8873303ZA | PLSI1016-60LH/883 | 5962-9476301MXC |
| IS2-1009RH-Q | 5962F0052301VXC | MTL1011AMD8 | 5962-9062701PA | LT1016 (GEN) | 5962-8684501PA |
| ISYE-1009RH-8 | 5962F0052301QYC | MTL1011AMH | 5962-9062701GA | MTL1017MD8/883 | 5962-8950401PA |
| ISYE-1009RH-Q | 5962F0052301VYC | MTL1011MD8 | 5962-9062702PA | MTL1017MD8/883 | 5962-8950401PC |
| LMA1009-55 (GEN) | 5962-9099604MUA | MTL1011MH | 5962-9062702GA | MTL1017MH/883 | 5962-8950401GA |
| LMA1009-55 (GEN) | 5962-9099604MXA | 10C11-20 (GEN) | 5962-9679303M3A | MTL1017MH/883 | 5962-8950401GC |
| LMA1009-65 (GEN) | 5962-9099603MUA | 10C11-20 (GEN) | 5962-9679303MLA | MTL1017MJ8/883 | 5962-8950401PA |
| LMA1009-65 (GEN) | 5962-9099603MXA | 10C11-25 (GEN) | 5962-9679302M3A | MTL1017MJ8/883 | 5962-8950401PC |
| LMA1009-95 (GEN) | 5962-9099602MUA | 10C11-25 (GEN) | 5962-9679302MLA | 1018A (GEN) | 5962-9174801MJA |
| LMA1009-95 (GEN) | 5962-9099602MXA | 10C11-30 (GEN) | 5962-9679301M3A | 1018B (GEN) | 5962-9174802MJA |
| MTL1009MH | 5962-8961001XA | 10C11-30 (GEN) | 5962-9679301MLA | MTL1018MD8/883 | 5962-8950402PA |
| MTL1009MH | 5962-8961001XC | LT1012 (GEN) | 5962-9084201MGA | MTL1018MD8/883 | 5962-8950402PC |
| INA101 (GEN) | 5962-8778001CA | LT1012 (GEN) | 5962-9084201MPA | MTL1018MH/883 | 5962-8950402GA |
| INA101 (GEN) | 5962-8778002IA | LT1012A (GEN) | 5962-9084202MGA | MTL1018MH/883 | 5962-8950402GC |
| LM101A (GEN) | 5962R9951501QGA | LT1012A (GEN) | 5962-9084202MPA | MTL1018MJ8/883 | 5962-8950402PA |
| LM101A (GEN) | 5962R9951501QHA | TDC1012 (GEN) | 5962-90596013A | MTL1018MJ8/883 | 5962-8950402PC |
| LM101A (GEN) | 5962R9951501QPA | TDC1012 (GEN) | 5962-9059601JA | TGC1019 | 5962-94B0503Q4A |
| LM101A (GEN) | 5962R9951501VPA | TDC1012 (GEN) | 5962-90596023A | TGC1019 | 5962-94B0503Q5A |
| LM101AH-QMLV | 5962-9951501VGA | TDC1012 (GEN) | 5962-9059602JA | TGC1019 | 5962-94B0503Q6A |
| LM101AHRQMLV | 5962R9951501VGA | LT1013AMFKB | 5962-88760012A | TGC1019 | 5962-94B0503QMA |
| LM101AJ-QMLV | 5962-9951501VPA | LT1013AMJGB | 5962-8876001PA | TGC1019 | 5962-94B0503QNA |
| LM101AW-QMLV | 5962-9951501VHA | LT1013MFKB | 5962-88760022A | TGC1019 | 5962-94B0503QTA |
| LM101AWRQMLV | 5962R9951501VHA | LT1013MJGB | 5962-8876002PA | TGC1019 | 5962-94B0503QUA |
| 1010A (GEN) | 5962-9096401MXA | MTL1013AMH | 5962-8876001GA | TGC1019 | 5962-94B0503QXA |
| 1010A (GEN) | 5962-9096401MYA | MTL1013AML20 | 5962-88760012A | TGC1019 | 5962-94B0503QYA |
| 1010A (GEN) | 5962-9096401MZA | MTL1013MH | 5962-8876002GA | TGC1019 | 5962-94B0503QZA |
| A1010B-PG84B | 5962-9096403MXA | MTL1013ML20 | 5962-88760022A | LT1019-10 (GEN) | 5962-9059505GA |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

| Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN |
|---|---|---|---|---|---|
| LT1019A-10 (GEN) | 5962-9059501GA | 1024-C673H/2 (GEN) | 5962-9070706HXC | TGC1036 | 5962-94B0505QXA |
| LT1019-2.5 (GEN) | 5962-9059508GA | 1024-C674H/2 (GEN) | 5962-9070707HXC | TGC1036 | 5962-94B0505QYA |
| MTL1019A-2.5BCX | 5962-9059504GA | 1024-C675H/2 (GEN) | 5962-9070708HXC | TGC1036 | 5962-94B0505QZA |
| LT1019-4.5 (GEN) | 5962-9059507GA | AD10265 (GEN) | 5962-9865901HXA | LT1037A (GEN) | 5962-88567012A |
| LT1019A-4.5 (GEN) | 5962-9059503GA | LT1028 (GEN) | 5962-8862201GA | LT1037A (GEN) | 5962-8856701GA |
| LT1019-5 (GEN) | 5962-9059506GA | LT1028 (GEN) | 5962-8862201XA | LT1037A (GEN) | 5962-8856701PA |
| LT1019A-5 (GEN) | 5962-9059502GA | LT1028A (GEN) | 5962-8862202GA | LT1039 (GEN) | 5962-8875101VA |
| BT102 (GEN) | 5962-8965301LA | LT1028A (GEN) | 5962-8862202XA | LT1039 (GEN) | 5962-8875102EA |
| 1020 (GEN) | 5962-9096501MTC | LT1028 (GEN) | 5962-8862201PA | LM104 (GEN) | 5962-8760501IA |
| 1020 (GEN) | 5962-9096501MUC | LT1028A (GEN) | 5962-8862202PA | LTC1041 (GEN) | 5962-9470901MPA |
| 1020 (GEN) | 5962-9096501MXA | LT1029 (GEN) | 5962-9051902XA | 10E416 (GEN) | 5962-9309801MYA |
| 1020 (GEN) | 5962-9096501MYA | LT1029A (GEN) | 5962-9051901XA | 10H416 (GEN) | 5962-8759001EA |
| 1020 (GEN) | 5962-9096501MZA | TGC1030 | 5962-94B0504Q4A | 10H416 (GEN) | 5962-8759001FA |
| 1020A (GEN) | 5962-9096501MMC | TGC1030 | 5962-94B0504Q5A | 10H416 (GEN) | 5962-87590012A |
| 1020B (GEN) | 5962-9096503MMC | TGC1030 | 5962-94B0504Q6A | LTC1042 (GEN) | 5962-9161901MPA |
| A1020B-CQ84B | 5962-9096503MTC | TGC1030 | 5962-94B0504QMA | MG1042 | 5962-00B0109Q*C |
| A1020B-DIE | 5962-9096503Q9A | TGC1030 | 5962-94B0504QNA | MG1042E | 5962-00B0102Q*C |
| A1020B-PG84B | 5962-9096503MUC | TGC1030 | 5962-94B0504QTA | MG1042E | 5962-00B0102V*C |
| LT1020 (GEN) | 5962-9084101MCA | TGC1030 | 5962-94B0504QUA | MM0-G1042*MQ | 5962-00B0109Q9A |
| RH1020-CQ84V | 5962F9096505QTC | TGC1030 | 5962-94B0504QXA | MM0-G1042EH*MQ | 5962-00B0102Q9A |
| RH1020-DIE | 5962F9096505Q9B | TGC1030 | 5962-94B0504QYA | SM0-G1042EH*SV | 5962-00B0102V9A |
| AD10200BZ/QMLH | 5962-9961002HXA | TGC1030 | 5962-94B0504QZA | MAX1044MJA/883B | 5962-3870701MPA |
| AD10200TZ/QMLH | 5962-9961001HXA | 10E301 (GEN) | 5962-9057301LA | MAX1044MTV/883B | 5962-3870701MGC |
| 1020-1 (GEN) | 5962-9096502MXA | 10E301 (GEN) | 5962-9057301XA | TDC1044 (GEN) | 5962-8982801EA |
| 1020-1 (GEN) | 5962-9096504MMC | 10E302 (GEN) | 5962-9057302LA | LTC1045MJ/883 | 5962-9054501RA |
| 1020A-1 (GEN) | 5962-9096502MMC | 10E302 (GEN) | 5962-9057302XA | TGC1046 | 5962-94B0506Q4A |
| 1020A-1 (GEN) | 5962-9096502MTC | LT1031-BMH/883B | 5962-8980201XA | TGC1046 | 5962-94B0506Q5A |
| 1020A-1 (GEN) | 5962-9096502MUC | LT1031-CMH/883B | 5962-8980202XA | TGC1046 | 5962-94B0506Q6A |
| 1020A-1 (GEN) | 5962-9096502MYA | LT1031-DMH/883B | 5962-8980203XA | TGC1046 | 5962-94B0506QMA |
| 1020A-1 (GEN) | 5962-9096502MZA | MTL1031CMH | 5962-8980202XA | TGC1046 | 5962-94B0506QNA |
| A1020B-1CQ84B | 5962-9096504MTC | SG103Z-1.8 | 7702801XA | TGC1046 | 5962-94B0506QTA |
| A1020B-1PG84B | 5962-9096504MUC | LT1032 (GEN) | 5962-8944001CA | TGC1046 | 5962-94B0506QUA |
| LT1021BMH-10/883B | 5962-8860001GA | LM103H-2.0 (GEN) | 7702802XA | TGC1046 | 5962-94B0506QXA |
| LT1021CMH-10/883B | 5962-8860002GA | LM103H-2.2 (GEN) | 7702803XA | TGC1046 | 5962-94B0506QYA |
| LT1021DMH-10/883B | 5962-8860003GA | LM103H-2.4 (GEN) | 7702804XA | TGC1046 | 5962-94B0506QZA |
| LT1021BMH-5/883B | 5962-8876201GA | ISPLSI1032-60LG/88 | 5962-9308501MXC | 1046-341H/2 (GEN) | 5962-9156002HXC |
| LT1021CMH-5/883B | 5962-8876202GA | PLSI1032-60LG/883 | 5962-9466801MXC | 1046-341S/2 (GEN) | 5962-9156003HXC |
| LT1021DMH-5/883B | 5962-8876203GA | SG103Z-2.7 | 7702805XA | 1046-341V/2 (GEN) | 5962-9156001HXC |
| LT1021BM-7 (GEN) | 5962-8864701GA | LM103H-3.0 (GEN) | 7702806XA | AD10465BZ/QMLH | 5962-9961601HXA |
| LT1021DM-7 (GEN) | 5962-8864702GA | LM103-3.3 (GEN) | 7702807XA | TDC1046 | 5962-8778601VA |
| LT1022 (GEN) | 5962-8962202GA | LM103H-3.6 (GEN) | 7702808XA | 10E474L-5 (GEN) | 5962-9151802MXA |
| LT1022A (GEN) | 5962-8962201GA | LM103H-3.9 (GEN) | 7702809XA | 10E474L-5 (GEN) | 5962-9151802MYA |
| LT1024A (GEN) | 5962-9955401QCA | LM103H-4.3 (GEN) | 7702810XA | 10E474L-5 (GEN) | 5962-9151802MZA |
| AD10242TZ/883B | 5962-9581501HXA | SG103Z-4.7 | 7702811XA | 10E474L-7 (GEN) | 5962-9151801MXA |
| 1024K32-100 (GEN) | 5962-9461302HXA | LM103H-5.1 (GEN) | 7702812XA | 10E474L-7 (GEN) | 5962-9151801MYA |
| 1024K32-100 (GEN) | 5962-9461302HYA | LM103H-5.6 (GEN) | 7702813XA | 10E474L-7 (GEN) | 5962-9151801MZA |
| 1024K32-100 (GEN) | 5962-9461302HZA | TGC1036 | 5962-94B0505Q4A | TDC1048 (GEN) | 5962-87600013A |
| 1024K32-150 (GEN) | 5962-9461301HXA | TGC1036 | 5962-94B0505Q5A | ISPLSI1048C-50LG/8 | 5962-9558701MXC |
| 1024K32-150 (GEN) | 5962-9461301HYA | TGC1036 | 5962-94B0505Q6A | PLSI1048C-50LG/883 | 5962-9558801MXC |
| 1024K32-150 (GEN) | 5962-9461301HZA | TGC1036 | 5962-94B0505QMA | TDC1048 (GEN) | 5962-8760001XA |
| ISPLSI1024-60LH/88 | 5962-9476101MXC | TGC1036 | 5962-94B0505QNA | TDC1049/TC | 5962-8853201TC |
| PLSI1024-60LH/883 | 5962-9476001MXC | TGC1036 | 5962-94B0505QTA | TDC1049L1V | 5962-8853201UA |
| 1024-C672H/2 (GEN) | 5962-9070705HXC | TGC1036 | 5962-94B0505QUA | TDC1049J0V | 5962-8853201XA |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

| Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN |
|---|---|---|---|---|---|
| TDC1049C1V | 5962-8853201ZA | AS10H515F16/883C | 5962-8750101XA | AS10H531F16/883C | 5962-8756101XA |
| TDC1049J3V | 5962-8853201YA | MTL10H5152A | 5962-87501012A | 10H535 (GEN) | 5962-87505012A |
| LM105 (GEN) | 5962-8958801GA | MTL10H515EA | 5962-8750101EA | 10H535 (GEN) | 5962-8750501EA |
| 10E501 (GEN) | 5962-9309901MYA | MTL10H515FA | 5962-8750101FA | 10H535 (GEN) | 5962-8750501FA |
| 10H501 (GEN) | 5962-8750301FA | 10E516 (GEN) | 5962-9234301MYA | ML10H536/BEA | 5962-8700101EA |
| AS10H501C16/883C | 5962-8750301EA | 10E516 (GEN) | 5962-9234301MZA | ML10H536/BFA | 5962-8700101FA |
| AS10H501EC20/883C | 5962-87503012A | 10H516-2883C | 5962-87502012A | ML10H536/B2A | 5962-87001012A |
| AS10H501F16/883C | 5962-8750301XA | 10H516E883C | 5962-8750201EA | 10538 (GEN) | 5962-9093501M2A |
| 10H502 (GEN) | 5962-8755701FA | 10H516F883C | 5962-8750201FA | 10538 (GEN) | 5962-9093501MEA |
| AS10H502C16/883C | 5962-8755701EA | AS10H516C16/883C | 5962-8750201EA | 10538 (GEN) | 5962-9093501MFA |
| AS10H502EC20/883C | 5962-87557012A | AS10H516EC20/883C | 5962-87502012A | DAC1054 (GEN) | 5962-9466201QJA |
| AS10H502F16/883C | 5962-8755701XA | AS10H516F16/883C | 5962-8750201XA | LT1054 (GEN) | 5962-8956201GA |
| 10H503 (GEN) | 5962-87565012A | SL10516/B2A | 78009012A | MTL1054MH/883 | 5962-8956201XA |
| 10H503 (GEN) | 5962-8756501EA | SL10516/B2C | 78009012C | 10H541 (GEN) | 5962-87511012A |
| 10H503 (GEN) | 5962-8756501FA | SL10516/BEA | 7800901EA | 10H541 (GEN) | 5962-8751101EA |
| 10E504 (GEN) | 5962-9310001MYA | SL10516/BFA | 7800901FA | 10H541 (GEN) | 5962-8751101FA |
| 10H504 (GEN) | 5962-8750401FA | 10H518 (GEN) | 5962-87559012A | SL10541/B2A | 5962-88557012A |
| AS10H504C16/883C | 5962-8750401EA | 10H518 (GEN) | 5962-8755901EA | SL10541/B2C | 5962-88557012C |
| AS10H504EC20/883C | 5962-87504012A | 10H518 (GEN) | 5962-8755901FA | SL10541/BEA | 5962-8855701EA |
| AS10H504F16/883C | 5962-8750401XA | 10H519 (GEN) | 5962-87728012A | SL10541/BFA | 5962-8855701FA |
| 10H505 (GEN) | 5962-87507012A | 10H519 (GEN) | 5962-8772801EA | 10545 (GEN) | 5962-88560012A |
| 10H505 (GEN) | 5962-8750701EA | 10H519 (GEN) | 5962-8772801FA | 10545 (GEN) | 5962-8856001EA |
| 10H505 (GEN) | 5962-8750701FA | LTC1052 (GEN) | 5962-8978201CA | 10545 (GEN) | 5962-8856001FA |
| 10H506 (GEN) | 5962-87564012A | LTC1052 (GEN) | 5962-8978201GA | MTL1054MJ8/883 | 5962-8956201PA |
| 10H506 (GEN) | 5962-8756401EA | LTC1052 (GEN) | 5962-8978201PA | LT1055 (GEN) | 5962-8997603GA |
| 10H506 (GEN) | 5962-8756401FA | MG1052 | 5962-00B0110Q*C | LT1055A (GEN) | 5962-8997601GA |
| 10E507 (GEN) | 5962-9310101MYA | 10H521 (GEN) | 5962-87730012A | 10E551 (GEN) | 5962-9310401MYA |
| 10H507 (GEN) | 5962-8772701FA | 10H521 (GEN) | 5962-8773001EA | 10H558/2A | 5962-87566012A |
| AS10H507C16/883C | 5962-87727012A | 10H521 (GEN) | 5962-8773001FA | 10H558/EA | 5962-8756601EA |
| AS10H507EC16/883C | 5962-8772701EA | 10H524 (GEN) | 5962-8756001FA | 10H558/FA | 5962-8756601FA |
| 10H509 (GEN) | 5962-89856012A | AS10H524C16/883C | 5962-8756001EA | SL10558/B2A | 5962-87792012A |
| 10H509 (GEN) | 5962-8985601EA | AS10H524EC20/883C | 5962-87560012A | SL10558/B2C | 5962-87792012C |
| 10H509 (GEN) | 5962-8985601FA | AS10H524F16/883C | 5962-8756001XA | SL10558/BEA | 5962-8779201EA |
| LTC1051 (GEN) | 5962-9460001MGA | AS10H525C16/883C | 5962-8750801EA | SL10558/BFA | 5962-8779201FA |
| LTC1051 (GEN) | 5962-9460001MPA | AS10H525EC20/883C | 5962-87508012A | 1056C (GEN) | 5962-92A0401QYC |
| LTC1051 (GEN) | 5962-9460001MXA | AS10H525F16/883C | 5962-8750801XA | 1056E (GEN) | 5962-92A0601QYC |
| LTC1051A (GEN) | 5962-9460002MGA | MTL10H5252A | 5962-87508012A | 1056F (GEN) | 5962-92A0701QYC |
| LTC1051A (GEN) | 5962-9460002MPA | MTL10H525EA | 5962-8750801EA | 1056G (GEN) | 5962-92A0801QYC |
| LTC1051A (GEN) | 5962-9460002MXA | MTL10H525FA | 5962-8750801FA | 1056J (GEN) | 5962-92A1001QYC |
| DSC-10510-113 | 5962-9076001HXC | TGC1053 | 5962-94B0507Q4A | 1056K2 (GEN) | 5962-92A1101QYC |
| DSC-10510-113 | 5962-9076001HXC | TGC1053 | 5962-94B0507Q5A | 1056L (GEN) | 5962-92A1201QYC |
| DSC-10510-114 | 5962-9076002HXC | TGC1053 | 5962-94B0507Q6A | 1056S (GEN) | 5962-92A1401QYC |
| DSC-10510-114 | 5962-9076002HXC | TGC1053 | 5962-94B0507QMA | 1056T (GEN) | 5962-92A1301QYC |
| DSC-10510-143 | 5962-9076001HXA | TGC1053 | 5962-94B0507QNA | 1056U (GEN) | 5962-92A1601QYC |
| DSC-10510-143 | 5962-9076001HXA | TGC1053 | 5962-94B0507QTA | 1056W (GEN) | 5962-92A1501QYC |
| DSC-10510-144 | 5962-9076002HXA | TGC1053 | 5962-94B0507QUA | LT1056 (GEN) | 5962-8997604GA |
| DSC-10510-144 | 5962-9076002HXA | TGC1053 | 5962-94B0507QXA | LT1056A (GEN) | 5962-8997602GA |
| 10E511 (GEN) | 5962-9232701MYA | TGC1053 | 5962-94B0507QYA | 10H560 (GEN) | 5962-87562012A |
| 10H513/2A | 5962-87558012A | TGC1053 | 5962-94B0507QZA | 10H560 (GEN) | 5962-8756201EA |
| 10H513/EA | 5962-8755801EA | 10E531 (GEN) | 5962-9310201MYA | 10H560 (GEN) | 5962-8756201FA |
| 10H513/FA | 5962-8755801FA | 10H531 (GEN) | 5962-8756101FA | 10H561 (GEN) | 5962-8756701FA |
| AS10H515C16/883C | 5962-8750101EA | AS10H531C16/883C | 5962-8756101EA | AS10H561C16/883C | 5962-8756701EA |
| AS10H515EC20/883C | 5962-87501012A | AS10H531EC20/883C | 5962-87561012A | AS10H561EC20/883C | 5962-87567012A |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

| Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN |
|---|---|---|---|---|---|
| AS10H561F16/883C | 5962-8756701XA | SL10592/M2C | 5962-9311101M2C | 10C68 (GEN) | 5962-9305603MYA |
| 1056A2 (GEN) | 5962-92A0201QYC | SL10592/MEA | 5962-9311101MEA | 10C68 (GEN) | 5962-9305602MXA |
| 1056B2 (GEN) | 5962-92A0301QYC | SL10592/MFA | 5962-9311101MFA | 10C68 (GEN) | 5962-9305602MYA |
| 1056D2 (GEN) | 5962-92A0501QYC | 10598 (GEN) | 5962-87773012A | STK10C68-5C35M | 5962-9305606MXA |
| 1056H2 (GEN) | 5962-92A0901QYC | 10598 (GEN) | 5962-8777301EA | STK10C68-5C35M | 5962-9305606MXC |
| 10H564 (GEN) | 5962-8772901FA | 10598 (GEN) | 5962-8777301FA | STK10C68-5L35M | 5962-9305606MYA |
| AS10H564C16/883C | 5962-8772901EA | LM106 (GEN) | 8003701CA | STK10C68-5C45M | 5962-9305605MXA |
| AS10H564EC20/883C | 5962-87729012A | LM106 (GEN) | 8003701DA | STK10C68-5C45M | 5962-9305605MXC |
| AS10H564F16/883C | 5962-8772901XA | LM106 (GEN) | 8003701GA | STK10C68-5L45M | 5962-9305605MYA |
| SL10564/B2A | 5962-88527012A | LM106 (GEN) | 8003701PA | 10C68 (GEN) | 5962-9305601MXA |
| SL10564/B2C | 5962-88527012C | HX1060 (GEN) | 5962H95B0401QTC | 10C68 (GEN) | 5962-9305601MYA |
| SL10564/BEA | 5962-8852701EA | HX1060 (GEN) | 5962H95B0401QXC | STK10C68-5C55M | 5962-9305604MXA |
| SL10564/BFA | 5962-8852701FA | HX1060 (GEN) | 5962H95B0401VTC | STK10C68-5C55M | 5962-9305604MXC |
| 10565 (GEN) | 5962-9056101M2A | HX1060 (GEN) | 5962H95B0401VXC | STK10C68-5L55M | 5962-9305604MYA |
| 10565 (GEN) | 5962-9056101MEA | LTC1060 (GEN) | 5962-8864102RA | LM107 (GEN) | 5962-8958901PA |
| 10565 (GEN) | 5962-9056101MFA | MTL1060MJ20 | 5962-8864101RA | LM107H/883 | 5962-8958901GA |
| 1056775 (GEN) | 5962-9082005HXC | 10H609 (GEN) | 5962-87569012A | LT1070 (GEN) | 5962-9082501MYA |
| 1057C (GEN) | 5962-92A1801QYC | 10H609 (GEN) | 5962-8756901EA | LT1070HV (GEN) | 5962-9082504MYA |
| 1057D (GEN) | 5962-92A1901QYC | 10H609 (GEN) | 5962-8756901FA | GEM10702Q3A | 86025023A |
| 1057E (GEN) | 5962-92A2001QYC | 10H610 (GEN) | 5962-87541012A | GEM10702Q3C | 86025023C |
| 1057G (GEN) | 5962-92A2201QYC | 10H610 (GEN) | 5962-8754101EA | GEM10702QXA | 8602502XA |
| LT1057 (GEN) | 5962-9081702MPA | 10H610 (GEN) | 5962-8754101FA | GEM10702QXC | 8602502XC |
| LT1057 (GEN) | 5962-9081702MXA | 10612 (GEN) | 5962-87750012A | GEM10702QYA | 8602502YA |
| LT1057A (GEN) | 5962-9081701MPA | 10612 (GEN) | 5962-8775001EA | GEM10702QYC | 8602502YC |
| LT1057A (GEN) | 5962-9081701MXA | 10612 (GEN) | 5962-8775001FA | LT1071 (GEN) | 5962-9082502MYA |
| MTL1057AMH | 5962-9081701MGA | MXL1062MJ8/883B | 5962-9159501MPA | LT1071HV (GEN) | 5962-9082505MYA |
| MTL1057MH | 5962-9081702MGA | LTC1064 (GEN) | 5962-8948301LA | LM107 (GEN) | 5962-8958901CA |
| 10H571 (GEN) | 5962-87568012A | LTC1064-1 (GEN) | 5962-9069301MCA | LT1072 (GEN) | 5962-9082503MPA |
| 10H571 (GEN) | 5962-8756801EA | LTC1064-1A (GEN) | 5962-9069302MCA | LT1072 (GEN) | 5962-9082503MYA |
| 10H571 (GEN) | 5962-8756801FA | LTC1064-4 (GEN) | 5962-90649012A | LT1072HV (GEN) | 5962-9082506MYA |
| 1057F2 (GEN) | 5962-92A2101QYC | LTC1064-4 (GEN) | 5962-9064901CA | LT1074 (GEN) | 5962-9457601MYA |
| 1057A3 (GEN) | 5962-92A1701QYC | LTC1064-4 (GEN) | 5962-9064901XA | LT1074HV (GEN) | 5962-9457602MYA |
| 10H574 (GEN) | 5962-87506012A | 1066-341H/2 (GEN) | 5962-8949904XC | 10H750 (GEN) | 5962-9058801M2A |
| 10H574 (GEN) | 5962-8750601EA | 1066-341V/2 (GEN) | 5962-8949905XC | 10H750 (GEN) | 5962-9058801MEA |
| 10H574 (GEN) | 5962-8750601FA | HRD1066-341H (GEN) | 5962-8990806XC | 10H750 (GEN) | 5962-9058801MFA |
| 10H576 (GEN) | 5962-8751201FA | HRD1066-341V (GEN) | 5962-8990807XC | 10H751 (GEN) | 5962-9156901M2A |
| AS10H576C16/883C | 5962-8751201EA | 1066-349H/2 (GEN) | 5962-8949803XC | 10H751 (GEN) | 5962-9156901MRA |
| AS10H576EC20/883C | 5962-87512012A | 1066-349V/2 (GEN) | 5962-8949804XC | 10H751 (GEN) | 5962-9156901MSA |
| AS10H576F16/883C | 5962-8751201XA | 1066-C778H/2 (GEN) | 5962-8949906XC | LT1076 (GEN) | 5962-9311901MYA |
| LT1058 (GEN) | 5962-8989702CA | HRD1066-381H (GEN) | 5962-8990808XC | LT1076HV (GEN) | 5962-9311902MYA |
| LT1058 (GEN) | 5962-8989702XA | TSPC106AMGSB/Q66C | 5962-0053501QXA | LT1077 (GEN) | 5962-9950201QGA |
| LT1058A (GEN) | 5962-8989701XA | TGC1068 | 5962-94B0508Q4A | LT1077 (GEN) | 5962-9950201QPA |
| MTL1058AMJ/883 | 5962-8989701CA | TGC1068 | 5962-94B0508Q5A | LT1078 (GEN) | 5962-9163203MGA |
| 10H586 (GEN) | 5962-87563012A | TGC1068 | 5962-94B0508Q6A | LT1078 (GEN) | 5962-9163203MPA |
| 10H586 (GEN) | 5962-8756301EA | TGC1068 | 5962-94B0508QMA | LT1078 (GEN) | 5962-9163203MXA |
| 10H586 (GEN) | 5962-8756301FA | TGC1068 | 5962-94B0508QNA | LT1078A (GEN) | 5962-9163204MGA |
| 10H588 (GEN) | 5962-87509012A | TGC1068 | 5962-94B0508QTA | LT1078A (GEN) | 5962-9163204MPA |
| 10H588 (GEN) | 5962-8750901EA | TGC1068 | 5962-94B0508QUA | LT1078A (GEN) | 5962-9163204MXA |
| 10H588 (GEN) | 5962-8750901FA | TGC1068 | 5962-94B0508QXA | SP1078B (GEN) | 5962-8997901XA |
| 10H589 (GEN) | 5962-87510012A | TGC1068 | 5962-94B0508QYA | LT1079 (GEN) | 5962-9163201MCA |
| 10H589 (GEN) | 5962-8751001EA | TGC1068 | 5962-94B0508QZA | LT1079A (GEN) | 5962-9163202MCA |
| 10H589 (GEN) | 5962-8751001FA | TSPC106AMGSB/Q83C | 5962-0053502QXA | 1HL08 (GEN) | 5962R93A0101QYC |
| SL10592/M2A | 5962-9311101M2A | 10C68 (GEN) | 5962-9305603MXA | LM10 (GEN) | 5962-8760401PA |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

| Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN |
|---|---|---|---|---|---|
| LM108AHRQML | 5962R9863702QGA | LT1084-12 (GEN) | 5962-9073905MXA | LTC1090 (GEN) | 5962-8983001RA |
| LM108AHRQMLV | 5962R9863702VGA | LT1084-5 (GEN) | 5962-9073902MXA | MG1090 | 5962-00B0111Q*C |
| LM108AJ-8RQML | 5962R9863702QPA | MTL1085MK | 5962-8864601XA | MG1090E | 5962-00B0103Q*C |
| LM108AJ-8RQMLV | 5962R9863702VPA | MTL1085MP | 5962-8864601UA | MG1090E | 5962-00B0103V*C |
| LM108AJRQML | 5962R9863702QCA | SDP1085NHD | 5962-9864901HNA | MM0-G1090*MQ | 5962-00B0111Q9A |
| LM108AJRQMLV | 5962R9863702VCA | SDP1085NHG | 5962-9864901HNC | MM0-G1090EH*MQ | 5962-00B0103Q9A |
| LM108AWGRQML | 5962R9863702QZA | SDP1085NMD | 5962-8864601NA | SM0-G1090EH*SV | 5962-00B0103V9A |
| LM108AWGRQMLV | 5962R9863702VZA | SDP1085THD | 5962-9864901HTA | TH1099Rabc_MQ | 5962-01B0117Q_C |
| LM108AWRQML | 5962R9863702QHA | SDP1085THG | 5962-9864901HTC | TH1099RabcDDMQ | 5962-01B0117Q9A |
| LM108AWRQMLV | 5962R9863702VHA | SDP1085UHD | 5962-9864901HUA | TH1099RHabc*MQ | 5962-01B0101Q*C |
| PAL10H8 (GEN) | 81035012A | SDP1085UHG | 5962-9864901HUC | TH1099RHabc*SR | 5962R01B0101V*C |
| PAL10H8 (GEN) | 8103501RA | SDP1085UMD | 5962-8864601UA | TH1099RHabc*SV | 5962-01B0101V*C |
| PAL10H8 (GEN) | 8103501SA | SDP1085XMD | 5962-8864601XA | TH1099RHabcDDMQ | 5962-01B0101Q9A |
| PAL10H8A (GEN) | 8103510RA | SDP1085ZHD | 5962-9864901HZA | TH1099RHabcDDSV | 5962-01B0101V9A |
| PAL10L8 (GEN) | 81035062A | SDP1085ZHG | 5962-9864901HZC | TH1099Sabc_MQ | 5962-01B0121Q_C |
| PAL10L8 (GEN) | 8103506RA | LT1085-12 (GEN) | 5962-9073906MXA | TH1099SabcDDMQ | 5962-01B0121Q9A |
| PAL10L8 (GEN) | 8103506SA | LT1085-5 (GEN) | 5962-9073903MXA | TH1099SHabc*MQ | 5962-01B0105Q*C |
| PAL10L8A (GEN) | 8103514RA | OM1860NHM/883B | 5962-8998101YA | TH1099SHabc*SR | 5962R01B0105V*C |
| PM108AJ/QMLR | 5962R9863701VGA | SDP1086NHD | 5962-9865001HNA | TH1099SHabc*SV | 5962-01B0105V*C |
| PM108AL/QMLR | 5962R9863701VHA | SDP1086NHG | 5962-9865001HNC | TH1099SHabcDDMQ | 5962-01B0105Q9A |
| PM108AZ/QMLR | 5962R9863701VPA | SDP1086THD | 5962-9865001HTA | TH1099SHabcDDSV | 5962-01B0105V9A |
| LT1080 (GEN) | 5962-8766601VA | SDP1086THG | 5962-9865001HTC | TH1RDabc_MQ | 5962-01B0125Q_C |
| GEM10801B2A | 5962-86881012A | SDP1086UHD | 5962-9865001HUA | TH1RDabcDDMQ | 5962-01B0125Q9A |
| GEM10801B2C | 5962-86881012C | SDP1086UHG | 5962-9865001HUC | TH1REHabc_MQ | 5962-01B0109Q_C |
| GEM10801BRA | 5962-8688101RA | SDP1086UMD | 5962-8998101UA | TH1REHabc_SR | 5962R01B0109V_C |
| GEM10801BRC | 5962-8688101RC | SDP1086XMD | 5962-8998101XA | TH1REHabc_SV | 5962-01B0109V_C |
| GEM10801BSA | 5962-8688101SA | SDP1086YMD | 5962-8998101YA | TH1REHabcDDMQ | 5962-01B0109Q9A |
| GEM10801BSC | 5962-8688101SC | SDP1086ZHD | 5962-9865001HZA | TH1REHabcDDSV | 5962-01B0109V9A |
| LT1081 (GEN) | 5962-8766602EA | SDP1086ZHG | 5962-9865001HZC | TH1SDabc_MQ | 5962-01B0129Q_C |
| SDP1083NHD | 5962-9864701HNA | SDP1086ZMD | 5962-8998101ZA | TH1SDabcDDMQ | 5962-01B0129Q9A |
| SDP1083NHG | 5962-9864701HNC | TGC1086 | 5962-94B0509Q4A | TH1SEHabc_MQ | 5962-01B0113Q_C |
| SDP1083THD | 5962-9864701HTA | TGC1086 | 5962-94B0509Q5A | TH1SEHabc_SR | 5962R01B0113V_C |
| SDP1083THG | 5962-9864701HTC | TGC1086 | 5962-94B0509Q6A | TH1SEHabc_SV | 5962-01B0113V_C |
| SDP1083UHD | 5962-9864701HUA | TGC1086 | 5962-94B0509QMA | TH1SEHabcDDMQ | 5962-01B0113Q9A |
| SDP1083UHG | 5962-9864701HUC | TGC1086 | 5962-94B0509QNA | TH1SEHabcDDSV | 5962-01B0113V9A |
| SDP1083XMD | 5962-8952001XA | TGC1086 | 5962-94B0509QTA | HCS11 (GEN) | 5962R9572001V9A |
| SDP1083YMD | 5962-8952001YA | TGC1086 | 5962-94B0509QUA | HCS11DMSR | 5962R9572001VCC |
| SDP1083ZHD | 5962-9864701HZA | TGC1086 | 5962-94B0509QXA | HCS11KMSR | 5962R9572001VXC |
| SDP1083ZHG | 5962-9864701HZC | TGC1086 | 5962-94B0509QYA | HCTS11 (GEN) | 5962R9572101V9A |
| SDP1083ZMD | 5962-8952001ZA | TGC1086 | 5962-94B0509QZA | HCTS11 (GEN) | 5962R9572101VCC |
| LT1083-5 (GEN) | 5962-9073901MXA | LT1086-5 (GEN) | 5962-9073904MXA | HCTS11 (GEN) | 5962R9572101VXC |
| AS1084EC/883C | 5962-89521012A | ACS109 (GEN) | 5962F9863201V9A | OP11A (GEN) | 5962-8980101V2A |
| SDP1084NHD | 5962-9864801HNA | ACS109 (GEN) | 5962F9863201VEC | OP11AM/QMLV | 5962-8980101VCA |
| SDP1084NHG | 5962-9864801HNC | ACS109 (GEN) | 5962F9863201VXC | OP-11ARC | 5962-89801012A |
| SDP1084THD | 5962-9864801HTA | HCS109DMSR | 5962R9578401VEC | OP-11ARC | 5962-89801032A |
| SDP1084THG | 5962-9864801HTC | HCS109HMSR | 5962R9578401V9A | OP-11AY | 5962-8980101CA |
| SDP1084UHD | 5962-9864801HUA | HCS109KMSR | 5962R9578401VXC | OP-11AY | 5962-8980103CA |
| SDP1084UHG | 5962-9864801HUC | HCTS109 (GEN) | 5962R9576901TEC | OP11AY/QMLV | 5962-8980101VCA |
| SDP1084XMD | 5962-8952101XA | HCTS109 (GEN) | 5962R9576901TXC | OP-11B (GEN) | 5962-89801022A |
| SDP1084YMD | 5962-8952101YA | HCTS109 (GEN) | 5962R9576901V9A | OP-11BY | 5962-8980102CA |
| SDP1084ZDM | 5962-8952101ZA | HCTS109 (GEN) | 5962R9576901VEC | RHFAC11K01Q | 5962F8761101XC |
| SDP1084ZHD | 5962-9864801HZA | HCTS109 (GEN) | 5962R9576901VXC | RHFAC11K01V | 5962F8761101VXC |
| SDP1084ZHG | 5962-9864801HZC | LM109K-DESC | 5962-8777401YA | RHFAC11K02Q | 5962F8761101XA |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

| Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN |
|---|---|---|---|---|---|
| RHFAC11K02V | 5962F8761101VXA | GEM11101QEA | 5962-9151601QEA | ACS11 (GEN) | 5962F9862201VCC |
| SMP-11A (GEN) | 5962-8954101CA | GEM11101QEC | 5962-9151601QEC | ACS11 (GEN) | 5962F9862201VXC |
| SMP-11BRC/883 | 5962-89541022A | 11105-DESC | 5962-8761701YA | LM113H-QMLV | 5962-9684301VXA |
| SMP-11BY/883 | 5962-8954102CA | 11105-DESC | 5962-8761701YC | LM113H-SMD | 5962-8671101XA |
| CLC110AJ-QML | 5962-8997501PA | LT1111 (GEN) | 5962-9321201MPA | LM113WG-QMLV | 5962-9684301VZA |
| LM110H/883 | 5962-8760601GA | 11110-001 | 5962-96A0501QXC | LM113WG-SMD | 5962-8671101ZA |
| LM110J/883 | 5962-8760601CA | TDC1112 | 5962-9165201M3A | HFA1130 (GEN) | 5962-9467701MPA |
| LM110J-8/883 | 5962-8760601PA | TDC1112 | 5962-9165201MJA | HFA1130ML/883 | 5962-9467701M2A |
| HFA1100MJ/883 | 5962-9467601MPA | TDC1112 | 5962-9165202M3A | LM113-1H-QMLV | 5962-9684302VXA |
| HS0-1100RH-Q | 5962F9467602V9A | TDC1112 | 5962-9165202MJA | LM113-1H-SMD | 5962-8671102XA |
| HS7B-1100RH-Q | 5962F9467602VPC | 1113 (GEN) | 5962-9468201M2A | LM113-1WG-QMLV | 5962-9684302VZA |
| LT1101 (GEN) | 5962-9950301QPA | 1113 (GEN) | 5962-9468201MPA | LM113-1WG-SMD | 5962-8671102ZA |
| RHFACT11K01Q | 5962F9077202QXC | TGC1113 | 5962-94B0510Q4A | LM113-2 (GEN) | 5962-8671103XA |
| RHFACT11K01V | 5962F9077202VXC | TGC1113 | 5962-94B0510Q5A | LM113-2 (GEN) | 5962-9684303VXA |
| RHFACT11K02Q | 5962F9077202QXA | TGC1113 | 5962-94B0510Q6A | HFA1135 (GEN) | 5962-9475601M2A |
| RHFACT11K02V | 5962F9077202VXA | TGC1113 | 5962-94B0510QMA | HFA1135 (GEN) | 5962-9475601MPA |
| MACH110-20 (GEN) | 5962-9308701MXA | TGC1113 | 5962-94B0510QNA | HS0-1135RH-Q | 5962F9676701V9A |
| SD11081XHD | 5962-8949002XA | TGC1113 | 5962-94B0510QTA | HS7B-1135RH-Q | 5962F9676701VPC |
| SD11081XHG | 5962-8949002XC | TGC1113 | 5962-94B0510QUA | CLC114AE-QML | 5962-9233901M2A |
| SD11082XHD | 5962-8949003XA | TGC1113 | 5962-94B0510QXA | CLC114AJ-QML | 5962-9233901MCA |
| SD11082XHG | 5962-8949003XC | TGC1113 | 5962-94B0510QYA | MG1140 | 5962-00B0112Q*C |
| SD11083XHD | 5962-8949004XA | TGC1113 | 5962-94B0510QZA | MG1140E | 5962-00B0104Q*C |
| SD11083XHG | 5962-8949004XC | HS7B-1115RH-Q | 5962F9678501VPC | MG1140E | 5962-00B0104V*C |
| SD11084XHD | 5962-8949005XA | 11155-001 | 5962-98A1101QXC | MM0-G1140*MQ | 5962-00B0112Q9A |
| SD11084XHG | 5962-8949005XC | 11179-001 | 5962-99A0201NXB | MM0-G1140EH*MQ | 5962-00B0104Q9A |
| SD11085XHD | 5962-8949006XA | ACS112 (GEN) | 5962F9670401VEC | SM0-G1140EH*SV | 5962-00B0104V9A |
| SD11085XHG | 5962-8949006XC | ACS112 (GEN) | 5962F9670401VXC | HS7B-1145RH-Q | 5962F9683001VPC |
| SD11086XHD | 5962-8949007XA | ACTS112 (GEN) | 5962F9671401VEC | 11496-501 | 5962-99A0501QXC |
| SD11086XHG | 5962-8949007XC | ACTS112 (GEN) | 5962F9671401VXC | 11496-502 | 5962-99A0502NYB |
| SD11087XHD | 5962-8949008XA | HCS112 (GEN) | 5962R9580201V9A | LTC1150 (GEN) | 5962-9950101QPA |
| SD11087XHG | 5962-8949008XC | HCS112 (GEN) | 5962R9580201VEC | HS0-11508RH-Q | 5962-97A0401V9A |
| SD11088XHD | 5962-8949009XA | HCS112 (GEN) | 5962R9580201VXC | HS9-11508RH-Q | 5962-97A0401VXC |
| SD11088XHG | 5962-8949009XC | HCTS112 (GEN) | 5962R9573801V9A | 11508-001 | 5962-99A1002QYC |
| SD11089XHD | 5962-8949001XA | HCTS112 (GEN) | 5962R9573801VEC | 11508-002 | 5962-99A1001NXB |
| SD11089XHG | 5962-8949001XC | HCTS112 (GEN) | 5962R9573801VXC | DSC-11520-112 | 5962-8998601HXC |
| AS111C008/883C | 5962-8687701PA | 1120 (GEN) | 5962-9468501MPA | DSC-11520-112 | 5962-8998601HXC |
| AS111E020/883C | 5962-86877012A | HS7B-1120RH-Q | 5962F9675601VPC | DSC-11520-142 | 5962-8998601HXA |
| AS111T008/883C | 5962-8687701GA | LT1120 (GEN) | 5962-9322401MPA | DSC-11520-113 | 5962-8998602HXC |
| CLC111 (GEN) | 5962-9687601MPA | MSK1120B | 5962-9668701HXA | DSC-11520-113 | 5962-8998602HXC |
| LM111 (GEN) | 5962P0052401QGA | MSK1120B | 5962-9668701HXC | DSC-11520-143 | 5962-8998602HXA |
| LM111 (GEN) | 5962P0052401QPA | ACS112 (GEN) | 5962F9670402V9A | DSC-11520-114 | 5962-8998603HXC |
| LM111 (GEN) | 5962P0052401QZA | ACS112 (GEN) | 5962F9670402VEC | DSC-11520-114 | 5962-8998603HXC |
| LM111E-SMD | 5962-8687701Q2A | ACS112 (GEN) | 5962F9670402VFC | DSC-11520-144 | 5962-8998603HXA |
| LM111HPQMLV | 5962P0052401VGA | ACTS112 (GEN) | 5962F9671402V9A | DSC-11520-115 | 5962-8998604HXC |
| LM111H-SMD | 5962-8687701QGA | ACTS112 (GEN) | 5962F9671402VEC | DSC-11520-115 | 5962-8998604HXC |
| LM111J-8PQMLV | 5962P0052401VPA | ACTS112 (GEN) | 5962F9671402VXC | DSC-11520-145 | 5962-8998604HXA |
| LM111J-8-SMD | 5962-8687701QPA | LT1124 (GEN) | 5962-9323802MPA | DSC-11520-142 | 5962-8998601HXA |
| LM111WGPQMLV | 5962P0052401VZA | LT1124A (GEN) | 5962-9323804MPA | DSC-11520-143 | 5962-8998602HXA |
| LM111WG-SMD | 5962-8687701QZA | LT1125 (GEN) | 5962-9323801MCA | DSC-11520-144 | 5962-8998603HXA |
| LM111WPQMLV | 5962P0052401VHA | LT1125A (GEN) | 5962-9323803MCA | DSC-11520-145 | 5962-8998604HXA |
| LT111A (GEN) | 5962-8687702GA | LT1126 (GEN) | 5962-9862801QPA | TGC1154 | 5962-94B0511Q4A |
| LT111A (GEN) | 5962-8687702PA | LT1127A (GEN) | 5962-9955501QCA | TGC1154 | 5962-94B0511Q5A |
| 1110 (GEN) | 5962-9468301MPA | ACS11 (GEN) | 5962F9862201V9A | TGC1154 | 5962-94B0511Q6A |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

| Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN |
|---|---|---|---|---|---|
| TGC1154 | 5962-94B0511QMA | P4C116L-35L28MB | 5962-88740013A | LM117HRQMLV | 5962R9951703VXA |
| TGC1154 | 5962-94B0511QNA | P4C116L-35LMB | 5962-8874001YA | LM117KRQMLV | 5962R9951704VYA |
| TGC1154 | 5962-94B0511QTA | 11C68 (GEN) | 5962-9232403MXA | LM117WG-QMLV | 5962-9951703VZA |
| TGC1154 | 5962-94B0511QUA | 11C68 (GEN) | 5962-9232403MYA | LM117WGRQMLV | 5962R9951703VZA |
| TGC1154 | 5962-94B0511QXA | STK11C68-5C35M | 5962-9232406MXA | OM117AHVNT/883B | 7703407TA |
| TGC1154 | 5962-94B0511QYA | STK11C68-5C35M | 5962-9232406MXC | OM117AHVSM/883B | 7703407MA |
| TGC1154 | 5962-94B0511QZA | STK11C68-5C35M | 5962-9232406MYA | OM117AHVST/883B | 7703407UA |
| TH1156Rabc_MQ | 5962-01B0118Q_C | 11C68 (GEN) | 5962-9232402MXA | OM117ANT/883B | 7703405TA |
| TH1156RabcDDMQ | 5962-01B0118Q9A | 11C68 (GEN) | 5962-9232402MYA | OM117ASM/883B | 7703405MA |
| TH1156RHabc*MQ | 5962-01B0102Q*C | STK11C68-5C45M | 5962-9232405MXA | OM117AST/883B | 7703405UA |
| TH1156RHabc*SR | 5962R01B0102V*C | STK11C68-5C45M | 5962-9232405MXC | OM117HVNT/883B | 7703402TA |
| TH1156RHabc*SV | 5962-01B0102V*C | STK11C68-5L45M | 5962-9232405MYA | OM117HVSM/883B | 7703402MA |
| TH1156RHabcDDMQ | 5962-01B0102Q9A | 11C68 (GEN) | 5962-9232401MXA | OM117HVST/883B | 7703402UA |
| TH1156RHabcDDSV | 5962-01B0102V9A | 11C68 (GEN) | 5962-9232401MYA | OM117NT/883B | 7703401TA |
| TH1156Sabc_MQ | 5962-01B0122Q_C | STK11C68-5C55M | 5962-9232404MXA | OM117SM/883B | 7703401MA |
| TH1156SabcDDMQ | 5962-01B0122Q9A | STK11C68-5C55M | 5962-9232404MXC | OM117ST/883B | 7703401UA |
| TH1156SHabc*MQ | 5962-01B0106Q*C | STK11C68-5L55M | 5962-9232404MYA | SDP1172MD | 77034012A |
| TH1156SHabc*SR | 5962R01B0106V*C | HS0-117RH-Q | 5962F9954701V9A | SDP117A2MD | 77034052A |
| TH1156SHabc*SV | 5962-01B0106V*C | HS-117 (GEN) | 5962R9954701TXC | SDP117AHV2MD | 77034072A |
| TH1156SHabcDDMQ | 5962-01B0106Q9A | HS2-117RH-8 | 5962F9954701QUC | SDP117AHVMMD | 7703407MA |
| TH1156SHabcDDSV | 5962-01B0106V9A | HS2-117RH-Q | 5962F9954701VUC | SDP117AHVNMD | 7703407NA |
| TH1RDabc_MQ | 5962-01B0126Q_C | HS9S-117RH-8 | 5962F9954701QXC | SDP117AHVTMD | 7703407TA |
| TH1RDabcDDMQ | 5962-01B0126Q9A | HS9S-117RH-Q | 5962F9954701VXC | SDP117AHVUMD | 7703407UA |
| TH1REHabc_MQ | 5962-01B0110Q_C | HSYE-117RH-8 | 5962F9954701QYC | SDP117AHVXMD | 7703407XA |
| TH1REHabc_SR | 5962R01B0110V_C | HSYE-117RH-Q | 5962F9954701VYC | SDP117AHVYMD | 7703407YA |
| TH1REHabc_SV | 5962-01B0110V_C | HSYE-117RH-T | 5962R9954701TYC | SDP117AMMD | 7703405MA |
| TH1REHabcDDMQ | 5962-01B0110Q9A | IP117AE | 77034055A | SDP117ANMD | 7703405NA |
| TH1REHabcDDMQ | 5962-01B0111Q9A | IP117AG-DESC | 7703405TA | SDP117ATMD | 7703405TA |
| TH1REHabcDDSV | 5962-01B0110V9A | IP117AHVE | 77034075A | SDP117AUMD | 7703405UA |
| TH1SDabc_MQ | 5962-01B0130Q_C | IP117AHVG-DESC | 7703407TA | SDP117AXMD | 7703405XA |
| TH1SDabcDDMQ | 5962-01B0130Q9A | IP117AHVIG-DESC | 7703407UA | SDP117AYMD | 7703405YA |
| TH1SEHabc_MQ | 5962-01B0114Q_C | IP117AHVK-DESC | 7703407YA | SDP117HV2MD | 77034022A |
| TH1SEHabc_SR | 5962R01B0114V_C | IP117AHVR-DESC | 7703407ZA | SDP117HVMMD | 7703402MA |
| TH1SEHabc_SV | 5962-01B0114V_C | IP117AIG-DESC | 7703405UA | SDP117HVNHD | 5962-9961202HNA |
| TH1SEHabcDDMQ | 5962-01B0114Q9A | IP117AK-DESC | 7703405YA | SDP117HVNHG | 5962-9961202HNC |
| TH1SEHabcDDSV | 5962-01B0114V9A | IP117AR-DESC | 7703405ZA | SDP117HVNMD | 7703402NA |
| 11563-DESC | 5962-8761701XA | IP117E | 77034015A | SDP117HVTHD | 5962-9961202HTA |
| 11563-DESC | 5962-8761701XC | IP117G-DESC | 7703401TA | SDP117HVTHG | 5962-9961202HTC |
| P4C116-20DMB | 5962-8969002LA | IP117HVE | 77034025A | SDP117HVTMD | 7703402TA |
| P4C116-20FMB | 5962-8969002KA | IP117HVG-DESC | 7703402TA | SDP117HVUHD | 5962-9961202HUA |
| P4C116-20L28MB | 5962-89690023A | IP117HVIG-DESC | 7703402UA | SDP117HVUHG | 5962-9961202HUC |
| P4C116-20LMB | 5962-8969002YA | IP117HVK-DESC | 7703402YA | SDP117HVUMD | 7703402UA |
| 11624-001 | 5962-00A1701NXB | IP117HVR-DESC | 7703402ZA | SDP117HVXMD | 7703402XA |
| P4C116-25DMB | 5962-8969001LA | IP117IG-DESC | 7703401UA | SDP117HVYMD | 7703402YA |
| P4C116-25FMB | 5962-8969001KA | IP117K-DESC | 7703401YA | SDP117HVZHD | 5962-9961202HZA |
| P4C116-25L28MB | 5962-89690013A | IP117MAH-DESC | 7703405XA | SDP117HVZHG | 5962-9961202HZC |
| P4C116-25LMB | 5962-8969001YA | IP117MAHVH-DESC | 7703407XA | SDP117MMD | 7703401MA |
| P4C116L-25DMB | 5962-8874002LA | IP117MH-DESC | 7703401XA | SDP117NHD | 5962-9961201HNA |
| P4C116L-25FMB | 5962-8874002KA | IP117MHVH-DESC | 7703402XA | SDP117NHG | 5962-9961201HNC |
| P4C116L-25L28MB | 5962-88740023A | IP117R-DESC | 7703401ZA | SDP117NMD | 7703401NA |
| P4C116L-25LMB | 5962-8874002YA | LM117 (GEN) | 5962R9951703QXA | SDP117THD | 5962-9961201HTA |
| P4C116L-35DMB | 5962-8874001LA | LM117 (GEN) | 5962R9951703QZA | SDP117THG | 5962-9961201HTC |
| P4C116L-35FMB | 5962-8874001KA | LM117 (GEN) | 5962R9951704QYA | SDP117TMD | 7703401TA |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

| Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN |
|---|---|---|---|---|---|
| SDP117UHD | 5962-9961201HUA | TGC1191 | 5962-94B0512Q5A | AFL12009SZ/CH | 5962-0255001HZA |
| SDP117UHG | 5962-9961201HUC | TGC1191 | 5962-94B0512Q6A | AFL12009SZ/CH | 5962-0255001HZC |
| SDP117UMD | 7703401UA | TGC1191 | 5962-94B0512QMA | TSB12C01 (GEN) | 5962-9677001QXA |
| SDP117XMD | 7703401XA | TGC1191 | 5962-94B0512QNA | AFL12012DW/CH | 5962-9960901HUA |
| SDP117YMD | 7703401YA | TGC1191 | 5962-94B0512QTA | AFL12012DW/CH | 5962-9960901HUC |
| SDP117ZHD | 5962-9961201HZA | TGC1191 | 5962-94B0512QUA | AFL12012DX/CH | 5962-9960901HXA |
| SDP117ZHG | 5962-9961201HZC | TGC1191 | 5962-94B0512QXA | AFL12012DX/CH | 5962-9960901HXC |
| SDP137HV2MD | 77034042A | TGC1191 | 5962-94B0512QYA | AFL12012DY/CH | 5962-9960901HYA |
| SG117AIG/883B | 7703405UA | TGC1191 | 5962-94B0512QZA | AFL12012DY/CH | 5962-9960901HYC |
| SG117AK/883B | 7703405YA | LT1193 (GEN) | 5962-9670001MPA | AFL12012DZ/CH | 5962-9960901HZA |
| SG117AL/883B | 77034052A | PA12M/883 | 5962-9065901HXA | AFL12012DZ/CH | 5962-9960901HZC |
| SG117AR/883B | 7703405ZA | MG1200 | 5962-00B0113Q*C | AFL12012SW/CH | 5962-0255101HUA |
| SG117AT/883B | 7703405XA | MG1200E | 5962-00B0105Q*C | AFL12012SW/CH | 5962-0255101HUC |
| SG117IG/883B | 7703401UA | MG1200E | 5962-00B0105V*C | AFL12012SX/CH | 5962-0255101HXA |
| SG117K/883B | 7703401YA | MM0-G1200*MQ | 5962-00B0113Q9A | AFL12012SX/CH | 5962-0255101HXC |
| SG117L/883B | 77034012A | MM0-G1200EH*MQ | 5962-00B0105Q9A | AFL12012SY/CH | 5962-0255101HYA |
| SG117R/883B | 7703401ZA | SM0-G1200EH*SV | 5962-00B0105V9A | AFL12012SY/CH | 5962-0255101HYC |
| SG117T/883B | 7703401XA | GEM12001Q2A | 5962-86715012A | AFL12012SZ/CH | 5962-0255101HZA |
| LT1172 (GEN) | 5962-9207901MPA | GEM12001Q2C | 5962-86715012C | AFL12012SZ/CH | 5962-0255101HZC |
| ADC1175MW-QML | 5962-0420801QXA | GEM12001QEA | 5962-8671501EA | IP120K-12-DESC | 7704003YA |
| 11788-001 | 5962-03A0301NXB | GEM12001QEC | 5962-8671501EC | IP120MH-12-DESC | 7704003XA |
| LM118 (GEN) | 5962P9853901QGA | GEM12001QFA | 5962-8671501FA | AFL12015DW/CH | 5962-0255501HUA |
| LM118 (GEN) | 5962P9853901QPA | GEM12001QFC | 5962-8671501FC | AFL12015DW/CH | 5962-0255501HUC |
| LM118 (GEN) | 5962P9853901QZA | AFL12005DW/CH | 5962-0255401HUA | AFL12015DX/CH | 5962-0255501HXA |
| LM118 (GEN) | 5962P9853901VGA | AFL12005DW/CH | 5962-0255401HUC | AFL12015DX/CH | 5962-0255501HXC |
| LM118 (GEN) | 5962P9853901VPA | AFL12005DX/CH | 5962-0255401HXA | AFL12015DY/CH | 5962-0255501HYA |
| LM118 (GEN) | 5962P9853901VZA | AFL12005DX/CH | 5962-0255401HXC | AFL12015DY/CH | 5962-0255501HYC |
| LT118A (GEN) | 5962-9451601MPA | AFL12005DY/CH | 5962-0255401HYA | AFL12015DZ/CH | 5962-0255501HZA |
| LT1180 (GEN) | 5962-9172901MVA | AFL12005DY/CH | 5962-0255401HYC | AFL12015DZ/CH | 5962-0255501HZC |
| MTL1181MD16 | 5962-9172902MEA | AFL12005DZ/CH | 5962-0255401HZA | AFL12015SW/CH | 5962-0255201HUA |
| MTL1185MK/883 | 5962-9469501MXA | AFL12005DZ/CH | 5962-0255401HZC | AFL12015SW/CH | 5962-0255201HUC |
| MTL1185MK/883 | 5962-9469501MXC | AFL12005SW/CH | 5962-9960801HUA | AFL12015SX/CH | 5962-0255201HXA |
| LM119 (GEN) | 5962R9679801QCA | AFL12005SW/CH | 5962-9960801HUC | AFL12015SX/CH | 5962-0255201HXC |
| LM119 (GEN) | 5962R9679801QHA | AFL12005SX/CH | 5962-9960801HXA | AFL12015SY/CH | 5962-0255201HYA |
| LM119 (GEN) | 5962R9679801QIA | AFL12005SX/CH | 5962-9960801HXC | AFL12015SY/CH | 5962-0255201HYC |
| LM119 (GEN) | 5962R9679801QXA | AFL12005SY/CH | 5962-9960801HYA | AFL12015SZ/CH | 5962-0255201HZA |
| LM119 (GEN) | 5962R9679801VCA | AFL12005SY/CH | 5962-9960801HYC | AFL12015SZ/CH | 5962-0255201HZC |
| LM119 (GEN) | 5962R9679801VHA | AFL12005SZ/CH | 5962-9960801HZA | IP120K-15-DESC | 7704004YA |
| LM119 (GEN) | 5962R9679801VIA | AFL12005SZ/CH | 5962-9960801HZC | IP120MH-15-DESC | 7704004XA |
| LM119 (GEN) | 5962R9679801VXA | AFL12008SW/CH | 5962-0254901HUA | LM120H-24 (GEN) | 7704005XA |
| LM119 (GEN) | 8601401DA | AFL12008SW/CH | 5962-0254901HUC | LM120H-24 (GEN) | 7704005YA |
| LM119E-SMD | 86014012A | AFL12008SX/CH | 5962-0254901HXA | AFL12028SW/CH | 5962-0255301HUA |
| LM119H-QMLV | 5962-9679801VIA | AFL12008SX/CH | 5962-0254901HXC | AFL12028SW/CH | 5962-0255301HUC |
| LM119H-SMD | 8601401IA | AFL12008SY/CH | 5962-0254901HYA | AFL12028SX/CH | 5962-0255301HXA |
| LM119J-QMLV | 5962-9679801VCA | AFL12008SY/CH | 5962-0254901HYC | AFL12028SX/CH | 5962-0255301HXC |
| LM119J-SMD | 8601401CA | AFL12008SZ/CH | 5962-0254901HZA | AFL12028SY/CH | 5962-0255301HYA |
| LM119WG-QMLV | 5962-9679801VXA | AFL12008SZ/CH | 5962-0254901HZC | AFL12028SY/CH | 5962-0255301HYC |
| LM119WG-SMD | 8601401XA | AFL12009SW/CH | 5962-0255001HUA | AFL12028SZ/CH | 5962-0255301HZA |
| LM119W-QMLV | 5962-9679801VHA | AFL12009SW/CH | 5962-0255001HUC | AFL12028SZ/CH | 5962-0255301HZC |
| LM119W-SMD | 8601401HA | AFL12009SX/CH | 5962-0255001HXA | 120325 (GEN) | 5962-8751301VA |
| LT119A (GEN) | 8601402CA | AFL12009SX/CH | 5962-0255001HXC | 120325 (GEN) | 5962-8751301XA |
| LT119A (GEN) | 8601402IA | AFL12009SY/CH | 5962-0255001HYA | 12032-501 | 5962-01A1301QXC |
| TGC1191 | 5962-94B0512Q4A | AFL12009SY/CH | 5962-0255001HYC | AFL1203R3SW/CH | 5962-0254801HUA |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

| Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN |
|---|---|---|---|---|---|
| AFL1203R3SW/CH | 5962-0254801HUC | LM124A (GEN) | 5962L9950401VZA | TH1SEHabc_MQ | 5962-01B0115Q_C |
| AFL1203R3SX/CH | 5962-0254801HXA | LM124A (GEN) | 5962R9950401QCA | TH1SEHabc_SR | 5962R01B0115V_C |
| AFL1203R3SX/CH | 5962-0254801HXC | LM124A (GEN) | 5962R9950401QDA | TH1SEHabc_SV | 5962-01B0115V_C |
| AFL1203R3SY/CH | 5962-0254801HYA | LM124A (GEN) | 5962R9950401QZA | TH1SEHabcDDMQ | 5962-01B0115Q9A |
| AFL1203R3SY/CH | 5962-0254801HYC | LM124AE/883 | 77043022A | TH1SEHabcDDSV | 5962-01B0115V9A |
| AFL1203R3SZ/CH | 5962-0254801HZA | LM124AFKB | 77043022A | LT1243 (GEN) | 5962-9319003MPA |
| AFL1203R3SZ/CH | 5962-0254801HZC | LM124AJ/883 | 7704302CA | LT1244 (GEN) | 5962-9319004MPA |
| 120335 (GEN) | 5962-8751302VA | LM124AJB | 7704302CA | ADC12441 (GEN) | 5962-9157802MXA |
| 120335 (GEN) | 5962-8751302XA | LM124AJRQMLV | 5962R9950401VCA | HS-1245 (GEN) | 5962F9683201VCA |
| 120345 (GEN) | 5962-8751303VA | LM124AWB | 7704302DA | LT1245 (GEN) | 5962-9319005MPA |
| 120345 (GEN) | 5962-8751303XA | LM124AWG/883 | 7704302XA | TGC1245 | 5962-94B0513Q4A |
| THS1206MDA | 5962-9957701NXD | LM124AWGRQMLV | 5962R9950401VZA | TGC1245 | 5962-94B0513Q5A |
| ADC12062 (GEN) | 5962-9559301QXA | LM124AWRQMLV | 5962R9950401VDA | TGC1245 | 5962-94B0513Q6A |
| 12074-001 | 5962-01A2001NXB | LM124FKB | 77043012A | TGC1245 | 5962-94B0513QMA |
| PAL12L10 (GEN) | 5962-86804023A | LM124J/883 | 7704301CA | TGC1245 | 5962-94B0513QNA |
| PAL12L10 (GEN) | 5962-8680402KA | LM124JB | 7704301CA | TGC1245 | 5962-94B0513QTA |
| PAL12L10 (GEN) | 5962-8680402LA | LM124JQMLV | 5962-7704301VCA | TGC1245 | 5962-94B0513QUA |
| HS7-1212RH-Q | 5962F9683101VPA | LM124WB | 7704301DA | TGC1245 | 5962-94B0513QXA |
| HS7B-1212RH-Q | 5962F9683101VPC | A1240A-PG132B | 5962-9322101MXA | TGC1245 | 5962-94B0513QYA |
| EPC1213 (GEN) | 5962-9474501MPA | A1240A-PG132B | 5962-9322101MXC | TGC1245 | 5962-94B0513QZA |
| LT1213 (GEN) | 5962-9566501MPA | A1240A-1PG132B | 5962-9322102MXA | ADC12451 (GEN) | 5962-9157804QJA |
| LT1215 (GEN) | 5962-9564101MPA | A1240A-1PG132B | 5962-9322102MXC | LM12458 (GEN) | 5962-9319501MXC |
| LT1215A (GEN) | 5962-9564102MPA | GEM12401B2A | 5962-86713012A | LM12458 (GEN) | 5962-9319501MYA |
| ST12154 (GEN) | 5962H93A0501QXC | GEM12401B2C | 5962-86713012C | LM12H458 (GEN) | 5962-9319502MYA |
| ST12155 (GEN) | 5962R93A0601QYC | GEM12401BRA | 5962-8671301RA | LM12H458MEL/883 | 5962-9319502MXC |
| ST12156 (GEN) | 5962H93A0701VYC | GEM12401BRC | 5962-8671301RC | LM12H458MWG/883 | 5962-9319502QZA |
| ST12157 (GEN) | 5962H93A0801VYA | GEM12401BSA | 5962-8671301SA | ACS125 (GEN) | 5962F9670501VCC |
| ST12158 (GEN) | 5962H93A0901VYC | GEM12401BSC | 5962-8671301SC | ACS125 (GEN) | 5962F9670501VXC |
| ST12159 (GEN) | 5962R93A1001VYC | ADC1241 (GEN) | 5962-9157801MXA | ACTS125 (GEN) | 5962F9671501VCC |
| QL12X16B-0C84M/883 | 5962-9683601MXC | LT1241 (GEN) | 5962-9319001MPA | ACTS125 (GEN) | 5962F9671501VXC |
| QL12X16B-1C84M/883 | 5962-9683602MXC | LT1242 (GEN) | 5962-9319002MPA | HCS125 (GEN) | 5962R9580301V9A |
| ST12169 (GEN) | 5962H93A1101VYC | TH1242Rabc_MQ | 5962-01B0119Q_C | HCS125 (GEN) | 5962R9580301VCC |
| ST12171 (GEN) | 5962R93A1201VYC | TH1242RabcDDMQ | 5962-01B0119Q9A | HCS125 (GEN) | 5962R9580301VXC |
| LM122 (GEN) | 5962-9163101MIA | TH1242RHabc*MQ | 5962-01B0103Q*C | 12-50 (GEN) | 5962-9460802MXA |
| TSB12LV21 (GEN) | 5962-9752901NXB | TH1242RHabc*SR | 5962R01B0103V*C | 1250A (GEN) | 5962-9097801HXC |
| 122325 (GEN) | 5962-8751304VA | TH1242RHabc*SV | 5962-01B0103V*C | ACS125 (GEN) | 5962F9670502V9A |
| 122325 (GEN) | 5962-8751304XA | TH1242RHabcDDMQ | 5962-01B0103Q9A | ACS125 (GEN) | 5962F9670502VCC |
| 122325 (GEN) | 5962-8751305VA | TH1242RHabcDDSV | 5962-01B0103V9A | ACS125 (GEN) | 5962F9670502VXC |
| 122335 (GEN) | 5962-8751305XA | TH1242Sabc_MQ | 5962-01B0123Q_C | ACTS125 (GEN) | 5962F9671502V9A |
| 122345 (GEN) | 5962-8751306VA | TH1242SabcDDMQ | 5962-01B0123Q9A | ACTS125 (GEN) | 5962F9671502VCC |
| 122345 (GEN) | 5962-8751306XA | TH1242SHabc*MQ | 5962-01B0107Q*C | ACTS125 (GEN) | 5962F9671502VXC |
| ST12237 (GEN) | 5962H93A1301VYC | TH1242SHabc*SR | 5962R01B0107V*C | ML12509E1 | 5962-8774801MEA |
| LT1229 (GEN) | 5962-9318401MPA | TH1242SHabc*SV | 5962-01B0107V*C | ML12509F1 | 5962-8774801MFA |
| LT1230 (GEN) | 5962-9318402MCA | TH1242SHabcDDMQ | 5962-01B0107Q9A | ADC1251 (GEN) | 5962-9157803QJA |
| IP123AK-05-DESC | 5962-8777502YA | TH1242SHabcDDSV | 5962-01B0107V9A | SL12511E1 | 5962-8774301MEA |
| IP123K-05-DESC | 5962-8777501YA | TH1RDabc_MQ | 5962-01B0127Q_C | SL12511F1 | 5962-8774301MFA |
| TSB12LV31 (GEN) | 5962-9753001QXA | TH1RDabcDDMQ | 5962-01B0127Q9A | ML12513E1 | 5962-8774901MEA |
| MAX1232MJA/883B | 5962-9451401MPA | TH1REHabc_MQ | 5962-01B0111Q_C | 12514 (GEN) | 5962-8775101MEA |
| MAX1232MLP/883B | 5962-9451401M2C | TH1REHabc_SR | 5962R01B0111V_C | ML12540/B2A | 5962-87752012A |
| LM124 (GEN) | 7704301AA | TH1REHabc_SV | 5962-01B0111V_C | ML12540/BCA | 5962-8775201CA |
| LM124 (GEN) | 7704301XA | TH1REHabcDDSV | 5962-01B0111V9A | MAX1259MJE/883B | 5962-9326401MEA |
| LM124A (GEN) | 5962L9950401VCA | TH1SDabc_MQ | 5962-01B0131Q_C | MAX1259MLP/883B | 5962-9326401M2C |
| LM124A (GEN) | 5962L9950401VDA | TH1SDabcDDMQ | 5962-01B0131Q9A | MSK1259B | 5962-9566801HXA |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

| Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN |
|---|---|---|---|---|---|
| MSK1259B | 5962-9566801HXC | LT1281 (GEN) | 5962-9172904MEA | ACT-S128K32N-025F2 | 5962-9559508HZC |
| 1258-12 (GEN) | 8515203XA | WE128K16-150CQ | 5962-9668904HXC | ACT-S128K32N-020F18 | 5962-9559509H9A |
| 1259-15 (GEN) | 8515201XA | WE128K16-150CQA | 5962-9668904HXA | ACT-S128K32N-020F18 | 5962-9559509H9C |
| 1259-20 (GEN) | 8515202XA | WE128K16-200CQ | 5962-9668903HXC | ACTS128K32N-020F18 | 5962-9559516H9A |
| LM126/MIA | 5962-8993001MIA | WE128K16-200CQA | 5962-9668903HXA | ACTS128K32N-020F18 | 5962-9559516H9C |
| PAL12H6 (GEN) | 81035022A | WSF128K16-72H1Q | 5962-9690001HYC | ACT-S128K32N-020F2 | 5962-9559509HMA |
| PAL12H6 (GEN) | 8103502RA | WE128K16-250CQ | 5962-9668902HXC | ACT-S128K32N-020F2 | 5962-9559509HMC |
| PAL12H6 (GEN) | 8103502SA | WE128K16-250CQA | 5962-9668902HXA | ACT-S128K32N-035F1 | 5962-9559507HXA |
| PAL12H6A (GEN) | 8103511RA | WE128K16-300CQ | 5962-9668901HXC | ACT-S128K32N-035F1 | 5962-9559507HXC |
| PAL12L6 (GEN) | 81035072A | WE128K16-300CQA | 5962-9668901HXA | ACT-S128K32N-035F1 | 5962-9559507HYA |
| PAL12L6 (GEN) | 8103507RA | WSF128K16-37G1UQ5 | 5962-9690002H9A | ACT-S128K32N-035F1 | 5962-9559507HYC |
| PAL12L6 (GEN) | 8103507SA | WSF128K16-37G1UQ5 | 5962-9690002H9C | ACT-S128K32N-025F18 | 5962-9559508H9A |
| PAL12L6A (GEN) | 8103515RA | WSF128K16-37HQ | 5962-9690002HXC | ACT-S128K32N-025F18 | 5962-9559508H9C |
| 12-65 (GEN) | 5962-9460801MXA | WSF128K16-37HQA | 5962-9690002HXA | ACTS128K32N-025F18 | 5962-9559515H9A |
| MG1265 | 5962-00B0114Q*C | WSF128K16-37G1TQ | 5962-9690002HBC | ACTS128K32N-025F18 | 5962-9559515H9C |
| MG1265E | 5962-00B0106Q*C | WSF128K16-37G1TQA | 5962-9690002HBA | ACT-S128K32N-035F18 | 5962-9559507H9A |
| MG1265E | 5962-00B0106V*C | WSF128K16-37H1Q | 5962-9690002HYC | ACT-S128K32N-035F18 | 5962-9559507H9C |
| MM0-G1265*MQ | 5962-00B0114Q9A | WSF128K16-37H1QA | 5962-9690002HYA | ACTS128K32N-035F18 | 5962-9559514H9A |
| MM0-G1265EH*MQ | 5962-00B0106Q9A | WSF128K16-37G2Q | 5962-9690002HMC | ACTS128K32N-035F18 | 5962-9559514H9C |
| SM0-G1265EH*SV | 5962-00B0106V9A | WSF128K16-37G2QA | 5962-9690002HMA | ACT-S128K32N-025F2 | 5962-9559508HMA |
| STK12C68-5C35M | 5962-9459903MXA | WSF128K16-72G1UQ5 | 5962-9690001H9A | ACT-S128K32N-025F2 | 5962-9559508HMC |
| STK12C68-5C35M | 5962-9459903MXC | WSF128K16-72G1UQ5 | 5962-9690001H9C | ACT-S128K32N-035F2 | 5962-9559507HMA |
| STK12C68-5L35M | 5962-9459903MYA | WSF128K16-72HQ | 5962-9690001HXC | ACT-S128K32N-035F2 | 5962-9559507HMC |
| STK12C68-5C45M | 5962-9459902MXA | WSF128K16-72HQA | 5962-9690001HXA | ACT-S128K32N-035F2 | 5962-9559507HZA |
| STK12C68-5C45M | 5962-9459902MXC | WSF128K16-72G1TQ | 5962-9690001HBC | ACT-S128K32N-035F2 | 5962-9559507HZC |
| STK12C68-5L45M | 5962-9459902MYA | WSF128K16-72G1TQA | 5962-9690001HBA | ACT-S128K32N-045F1 | 5962-9559506HXA |
| STK12C68-5C55M | 5962-9459901MXA | WSF128K16-72H1QA | 5962-9690001HYA | ACT-S128K32N-045F1 | 5962-9559506HXC |
| STK12C68-5C55M | 5962-9459901MXC | WSF128K16-72G2Q | 5962-9690001HMC | ACT-S128K32N-045F1 | 5962-9559506HYA |
| STK12C68-5L55M | 5962-9459901MYA | WSF128K16-72G2QA | 5962-9690001HMA | ACT-S128K32N-045F1 | 5962-9559506HYC |
| 2700A (GEN) | 5962D9567001VCA | ACT-S128K32N-017F1 | 5962-9559510HXA | ACT-S128K32N-045F18 | 5962-9559506H9A |
| 2700A (GEN) | 5962D9567001VGA | ACT-S128K32N-017F1 | 5962-9559510HXC | ACT-S128K32N-045F18 | 5962-9559506H9C |
| 1280 (GEN) | 5962-9215601MUC | ACT-S128K32N-017F1 | 5962-9559510HYA | ACTS128K32N-045F18 | 5962-9559513H9A |
| 1280 (GEN) | 5962-9215601MZA | ACT-S128K32N-017F1 | 5962-9559510HYC | ACTS128K32N-045F18 | 5962-9559513H9C |
| A1280A-CQ172B | 5962-9215601MYA | ACT-S128K32N-017F18 | 5962-9559510H9A | ACT-S128K32N-045F2 | 5962-9559506HMA |
| A1280A-CQ172B | 5962-9215601MYC | ACT-S128K32N-017F18 | 5962-9559510H9C | ACT-S128K32N-045F2 | 5962-9559506HMC |
| A1280A-DIE | 5962-9215601Q9A | ACTS128K32N-017F18 | 5962-9559517H9A | ACT-S128K32N-045F2 | 5962-9559506HZA |
| A1280A-DIE | 5962-9215601Q9B | ACTS128K32N-017F18 | 5962-9559517H9C | ACT-S128K32N-045F2 | 5962-9559506HZC |
| A1280A-PG176B | 5962-9215601MXA | ACT-S128K32N-017F2 | 5962-9559510HMA | ACT-S128K32N-055F1 | 5962-9559505HYA |
| A1280A-PG176B | 5962-9215601MXC | ACT-S128K32N-017F2 | 5962-9559510HMC | ACT-S128K32N-055F1 | 5962-9559505HYC |
| A1280XL-CQ172B | 5962-9215604QYC | ACT-S128K32N-017F2 | 5962-9559510HZA | ACT-S128K32N-055F18 | 5962-9559505H9A |
| A1280XL-DIE | 5962-9215604Q9D | ACT-S128K32N-017F2 | 5962-9559510HZC | ACT-S128K32N-055F18 | 5962-9559505H9C |
| A1280XL-PG176B | 5962-9215604QXC | ACT-S128K32N-020P7 | 5962-9318716H4C | ACTS128K32N-055F18 | 5962-9559512H9A |
| LT1280 (GEN) | 5962-9172903MVA | ACT-S128K32N-020F1 | 5962-9559509HXA | ACTS128K32N-055F18 | 5962-9559512H9C |
| RH1280-CQ172V | 5962F9215603QYC | ACT-S128K32N-020F1 | 5962-9559509HXC | ACT-S128K32N-055F2 | 5962-9559505HMA |
| RH1280-DIE | 5962F9215603Q9C | ACT-S128K32N-020F1 | 5962-9559509HYA | ACT-S128K32N-055F2 | 5962-9559505HMC |
| 1280-1 (GEN) | 5962-9215602MUC | ACT-S128K32N-020F1 | 5962-9559509HYC | ACT-S128K32N-055F2 | 5962-9559505HZA |
| 1280-1 (GEN) | 5962-9215602MZA | ACT-S128K32N-020F2 | 5962-9559509HZA | ACT-S128K32N-055F2 | 5962-9559505HZC |
| A1280A-1CQ172B | 5962-9215602MYA | ACT-S128K32N-020F2 | 5962-9559509HZC | ACT-F128K32N-060F5 | 5962-9471605HMA |
| A1280A-1CQ172B | 5962-9215602MYC | ACT-S128K32N-025F1 | 5962-9559508HXA | ACT-F128K32N-060F5 | 5962-9471605HMC |
| A1280A-1PG176B | 5962-9215602MXA | ACT-S128K32N-025F1 | 5962-9559508HXC | ACT-F128K32N-060F5 | 5962-9471605HNA |
| A1280A-1PG176B | 5962-9215602MXC | ACT-S128K32N-025F1 | 5962-9559508HYA | ACT-F128K32N-060F5 | 5962-9471605HNC |
| A1280XL-1CQ172B | 5962-9215605QYC | ACT-S128K32N-025F1 | 5962-9559508HYC | ACT-F128K32N-060P3 | 5962-9471605HZA |
| A1280XL-1PG176B | 5962-9215605QXC | ACT-S128K32N-025F2 | 5962-9559508HZA | ACT-F128K32N-060P3 | 5962-9471605HZC |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART II, Listed By Generic PIN

| Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN |
|---|---|---|---|---|---|
| ACT-F128K32N-060P7 | 5962-9471605H8A | ACT-E128K32N-120P7 | 5962-9458506H4C | WF128K32-120G2UQ5 | 5962-9471602HNC |
| ACT-F128K32N-060P7 | 5962-9471605H8C | ACT-F128K32N-120F5 | 5962-9471602HMA | WF128K32-120G4Q5 | 5962-9471602H4C |
| ACT-F128K32N-070F5 | 5962-9471604HMA | ACT-F128K32N-120F5 | 5962-9471602HMC | WF128K32-120H1Q5 | 5962-9471602H6A |
| ACT-F128K32N-070F5 | 5962-9471604HMC | ACT-F128K32N-120F5 | 5962-9471602HNA | WF128K32-120H1Q5 | 5962-9471602H6C |
| ACT-F128K32N-070F5 | 5962-9471604HNA | ACT-F128K32N-120F5 | 5962-9471602HNC | WF128K32-120HQ | 5962-9461003HXA |
| ACT-F128K32N-070F5 | 5962-9471604HNC | ACT-F128K32N-120P3 | 5962-9471602HZA | WF128K32-120HQ | 5962-9461003HXC |
| ACT-F128K32N-070P3 | 5962-9471604HZA | ACT-F128K32N-120P3 | 5962-9471602HZC | WF128K32-120HQ5 | 5962-9471602HUA |
| ACT-F128K32N-070P3 | 5962-9471604HZC | ACT-F128K32N-120P7 | 5962-9471602H8A | WF128K32-120HQ5 | 5962-9471602HUC |
| ACT-F128K32N-070P7 | 5962-9471604H8A | ACT-F128K32N-120P7 | 5962-9471602H8C | WF128K32-120HSQ | 5962-9461003HWA |
| ACT-F128K32N-070P7 | 5962-9471604H8C | AS8E128K32P-120/883 | 5962-9458506H5A | WF128K32-120HSQ | 5962-9461003HWC |
| ACT-F128K32N-090F5 | 5962-9471603HMA | AS8E128K32P-120/883 | 5962-9458506H5C | WF128K32-120HSQ5 | 5962-9471602HVA |
| ACT-F128K32N-090F5 | 5962-9471603HMC | AS8E128K32PN-120/88 | 5962-9458506H4A | WF128K32-120HSQ5 | 5962-9471602HVC |
| ACT-F128K32N-090F5 | 5962-9471603HNA | AS8E128K32PN-120/88 | 5962-9458506H4C | WF128K32A-120H1Q5 | 5962-9471602H5A |
| ACT-F128K32N-090F5 | 5962-9471603HNC | AS8E128K32Q-120/883 | 5962-9458506HMA | WF128K32A-120H1Q5 | 5962-9471602H5C |
| ACT-F128K32N-090P3 | 5962-9471603HZA | AS8E128K32Q-120/883 | 5962-9458506HMC | WF128K32A-120HQ5 | 5962-9471602HSA |
| ACT-F128K32N-090P3 | 5962-9471603HZC | AS8F128K32Q-120/Q | 5962-9471602HMA | WF128K32A-120HQ5 | 5962-9471602HSC |
| ACT-F128K32N-090P7 | 5962-9471603H8A | AS8F128K32Q-120/Q | 5962-9471602HMC | WF128K32A-120HSQ5 | 5962-9471602HTA |
| ACT-F128K32N-090P7 | 5962-9471603H8C | AS8F128K32Q-120/Q | 5962-9471602HNA | WF128K32A-120HSQ5 | 5962-9471602HTC |
| 128K32-100 (GEN) | 5962-9318702HTA | AS8F128K32Q-120/Q | 5962-9471602HNC | WF128K32N-120H1Q5 | 5962-9471602H8A |
| 128K32-100 (GEN) | 5962-9318702HUA | AS8S128K32Q1-20/883 | 5962-9559509HAA | WF128K32N-120H1Q5 | 5962-9471602H8C |
| 128K32-100 (GEN) | 5962-9318702HXA | AS8S128K32Q1-20/883 | 5962-9559509HAC | WF128K32N-120HQ | 5962-9461003HZA |
| 128K32-100 (GEN) | 5962-9318702HYA | AS8S128K32Q1-20/883 | 5962-9559516HAA | WF128K32N-120HQ | 5962-9461003HZC |
| WS128K32-100H1Q | 5962-9318702H5A | AS8S128K32Q1-20/883 | 5962-9559516HAC | WF128K32N-120HQ5 | 5962-9471602HYA |
| WS128K32-100H1Q | 5962-9318702H5C | WE128K32-120G1TQ | 5962-9458506HBA | WF128K32N-120HQ5 | 5962-9471602HYC |
| WS128K32N-100H1Q | 5962-9318702H4A | WE128K32-120G1TQ | 5962-9458506HBC | WF128K32N-120HSQ | 5962-9461003HYA |
| WS128K32N-100H1Q | 5962-9318702H4C | WE128K32-120G1UQ | 5962-9458506H9A | WF128K32N-120HSQ | 5962-9461003HYC |
| WS128K32-100G1TQ | 5962-9559502HBA | WE128K32-120G1UQ | 5962-9458506H9C | WF128K32N-120HSQ5 | 5962-9471602HZA |
| WS128K32-100G1TQ | 5962-9559502HBC | WE128K32-120G2Q | 5962-9458506HMA | WF128K32N-120HSQ5 | 5962-9471602HZC |
| WS128K32-100G1UQ | 5962-9559502H9A | WE128K32-120G2Q | 5962-9458506HMC | WF128K32NA-120H1Q | 5962-9471602H7A |
| WS128K32-100G1UQ | 5962-9559502H9C | WE128K32-120G4Q | 5962-9458506HNC | WF128K32NA-120H1Q | 5962-9471602H7C |
| WS128K32-100G2Q | 5962-9559502HMA | WE128K32-120H1Q | 5962-9458506H5A | WF128K32NA-120HQ5 | 5962-9471602HWA |
| WS128K32-100G2Q | 5962-9559502HMC | WE128K32-120H1Q | 5962-9458506H5C | WF128K32NA-120HQ5 | 5962-9471602HWC |
| WS128K32-100G2UQ | 5962-9559502HNA | WE128K32-120HQ | 5962-9458506HXA | WF128K32NA-120HSQ | 5962-9471602HXA |
| WS128K32-100G2UQ | 5962-9559502HNC | WE128K32-120HQ | 5962-9458506HXC | WF128K32NA-120HSQ | 5962-9471602HXC |
| WS128K32-100G4Q | 5962-9559502HXC | WE128K32-120HQ | 5962-9458506HYA | WS128K32-120H1Q | 5962-9318701H5A |
| WS128K32-100G4TQ | 5962-9559502HYC | WE128K32-120HQ | 5962-9458506HYC | WS128K32-120H1Q | 5962-9318701H5C |
| AS8F128K32Q1-120/Q | 5962-9471602HAA | WE128K32N-120H1Q | 5962-9458506H4A | WS128K32N-120H1Q | 5962-9318701H4C |
| AS8F128K32Q1-120/Q | 5962-9471602HAC | WE128K32N-120H1Q | 5962-9458506H4C | WF128K32N-120H1Q | 5962-9461003H4A |
| AS8F128K32Q1-150/Q | 5962-9471601HAA | WE128K32N-120HQ | 5962-9458506HTA | WF128K32N-120H1Q | 5962-9461003H4C |
| AS8F128K32Q1-150/Q | 5962-9471601HAC | WE128K32N-120HQ | 5962-9458506HTC | WF128K32NA-120H1Q | 5962-9461003H5A |
| AS8S128K32Q1-17/883 | 5962-9559510HAA | WE128K32N-120HQ | 5962-9458506HUA | WF128K32NA-120H1Q | 5962-9461003H5C |
| AS8S128K32Q1-17/883 | 5962-9559510HAC | WE128K32N-120HQ | 5962-9458506HUC | WS128K32-120G1TQ | 5962-9559501HBA |
| AS8S128K32Q1-17/883 | 5962-9559517HAA | WE128K32NP-120H1Q | 5962-9458506H6A | WS128K32-120G1TQ | 5962-9559501HBC |
| AS8S128K32Q1-17/883 | 5962-9559517HAC | WE128K32NP-120H1Q | 5962-9458506H6C | WS128K32-120G1UQ | 5962-9559501H9A |
| 128K32-120 (GEN) | 5962-9318701HTA | WF128K32-120G1TQ5 | 5962-9471602HBA | WS128K32-120G1UQ | 5962-9559501H9C |
| 128K32-120 (GEN) | 5962-9318701HUA | WF128K32-120G1TQ5 | 5962-9471602HBC | WF128K32-120G2Q | 5962-9461003HMA |
| 128K32-120 (GEN) | 5962-9318701HXA | WF128K32-120G1UQ5 | 5962-9471602H9A | WF128K32-120G2Q | 5962-9461003HMC |
| 128K32-120 (GEN) | 5962-9318701HYA | WF128K32-120G1UQ5 | 5962-9471602H9C | WS128K32-120G2Q | 5962-9559501HMA |
| ACT-E128K32C-120P7 | 5962-9458506H5A | WF128K32-120G2LQ5 | 5962-9471602HAA | WS128K32-120G2Q | 5962-9559501HMC |
| ACT-E128K32C-120P7 | 5962-9458506H5C | WF128K32-120G2LQ5 | 5962-9471602HAC | WS128K32-120G2UQ | 5962-9559501HNA |
| ACT-E128K32N-120F2 | 5962-9458506HMA | WF128K32-120G2Q5 | 5962-9471602HMA | WS128K32-120G2UQ | 5962-9559501HNC |
| ACT-E128K32N-120F2 | 5962-9458506HMC | WF128K32-120G2Q5 | 5962-9471602HMC | WF128K32-120G4Q | 5962-9461003HNC |
| ACT-E128K32N-120P7 | 5962-9458506H4A | WF128K32-120G2UQ5 | 5962-9471602HNA | WS128K32-120G4Q | 5962-9559501HXC |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART II, Listed By Generic PIN

| Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN |
|---|---|---|---|---|---|
| WS128K32-120G4TQ | 5962-9559501HYC | WE128K32N-150HQ | 5962-9458504HTC | WF128K32-150G2Q5 | 5962-9471601HMA |
| 128K32-120 (GEN) | 5962-9553802HYA | WE128K32N-150HQ | 5962-9458504HUA | WF128K32-150G2Q5 | 5962-9471601HMC |
| 128K32-120 (GEN) | 5962-9553802HXA | WE128K32N-150HQ | 5962-9458504HUC | WF128K32-150G2UQ5 | 5962-9471601HNA |
| AS8S128K32Q1-25/883 | 5962-9559508HAA | WS128K32-15H1Q | 5962-9318711H5A | WF128K32-150G2UQ5 | 5962-9471601HNC |
| AS8S128K32Q1-25/883 | 5962-9559508HAC | WS128K32-15H1Q | 5962-9318711H5C | WF128K32-150G4Q5 | 5962-9471601H4C |
| AS8S128K32Q1-25/883 | 5962-9559515HAA | WS128K32H-15H1Q | 5962-9318718H5A | WF128K32-150H1Q5 | 5962-9471601H6A |
| AS8S128K32Q1-25/883 | 5962-9559515HAC | WS128K32H-15H1Q | 5962-9318718H5C | WF128K32-150H1Q5 | 5962-9471601H6C |
| AS8S128K32Q1-35/883 | 5962-9559507HAA | WS128K32N-15H1Q | 5962-9318711H4A | WF128K32-150HQ | 5962-9461002HXA |
| AS8S128K32Q1-35/883 | 5962-9559507HAC | WS128K32N-15H1Q | 5962-9318711H4C | WF128K32-150HQ | 5962-9461002HXC |
| AS8S128K32Q1-35/883 | 5962-9559514HAA | WS128K32NH-15H1Q | 5962-9318718H4A | WF128K32-150HQ5 | 5962-9471601HUA |
| AS8S128K32Q1-35/883 | 5962-9559514HAC | WS128K32NH-15H1Q | 5962-9318718H4C | WF128K32-150HQ5 | 5962-9471601HUC |
| ACT-E128K32C-140P7 | 5962-9458505H5A | ACT-E128K32N-150F2 | 5962-9458504HMA | WF128K32-150HSQ | 5962-9461002HWA |
| ACT-E128K32C-140P7 | 5962-9458505H5C | ACT-E128K32N-150F2 | 5962-9458504HMC | WF128K32-150HSQ | 5962-9461002HWC |
| ACT-E128K32N-140F2 | 5962-9458505HMA | ACT-F128K32N-150F5 | 5962-9471601HMA | WF128K32-150HSQ5 | 5962-9471601HVA |
| ACT-E128K32N-140F2 | 5962-9458505HMC | ACT-F128K32N-150F5 | 5962-9471601HMC | WF128K32-150HSQ5 | 5962-9471601HVC |
| ACT-E128K32N-140P7 | 5962-9458505H4A | ACT-F128K32N-150F5 | 5962-9471601HNA | WF128K32A-150H1Q5 | 5962-9471601H5A |
| ACT-E128K32N-140P7 | 5962-9458505H4C | ACT-F128K32N-150F5 | 5962-9471601HNC | WF128K32A-150H1Q5 | 5962-9471601H5C |
| AS8E128K32P-140/883 | 5962-9458505H5A | ACT-F128K32N-150P3 | 5962-9471601HZA | WF128K32A-150HQ5 | 5962-9471601HSA |
| AS8E128K32P-140/883 | 5962-9458505H5C | ACT-F128K32N-150P3 | 5962-9471601HZC | WF128K32A-150HQ5 | 5962-9471601HSC |
| AS8E128K32PN-140/88 | 5962-9458505H4A | ACT-F128K32N-150P7 | 5962-9471601H8A | WF128K32A-150HSQ5 | 5962-9471601HTA |
| AS8E128K32PN-140/88 | 5962-9458505H4C | ACT-F128K32N-150P7 | 5962-9471601H8C | WF128K32A-150HSQ5 | 5962-9471601HTC |
| AS8E128K32Q-140/883 | 5962-9458505HMA | AS8E128K32P-150/883 | 5962-9458504H5A | WF128K32N-150H1Q5 | 5962-9471601H8A |
| AS8E128K32Q-140/883 | 5962-9458505HMC | AS8E128K32P-150/883 | 5962-9458504H5C | WF128K32N-150H1Q5 | 5962-9471601H8C |
| WE128K32-140G1TQ | 5962-9458505HBA | AS8E128K32PN-150/88 | 5962-9458504H4A | WF128K32N-150HQ | 5962-9461002HZA |
| WE128K32-140G1TQ | 5962-9458505HBC | AS8E128K32PN-150/88 | 5962-9458504H4C | WF128K32N-150HQ | 5962-9461002HZC |
| WE128K32-140G1UQ | 5962-9458505H9A | AS8E128K32Q-150/883 | 5962-9458504HMA | WF128K32N-150HQ5 | 5962-9471601HYA |
| WE128K32-140G1UQ | 5962-9458505H9C | AS8E128K32Q-150/883 | 5962-9458504HMC | WF128K32N-150HQ5 | 5962-9471601HYC |
| WE128K32-140G2Q | 5962-9458505HMA | AS8ER128K32Q-150/88 | 5962-9458509HMA | WF128K32N-150HSQ | 5962-9461002HYA |
| WE128K32-140G2Q | 5962-9458505HMC | AS8ER128K32Q-150/88 | 5962-9458509HMC | WF128K32N-150HSQ | 5962-9461002HYC |
| WE128K32-140G4Q | 5962-9458505HNC | AS8ER128K32QB-150/ | 5962-9458509HZC | WF128K32N-150HSQ5 | 5962-9471601HZA |
| WE128K32-140H1Q | 5962-9458505H5A | AS8F128K32Q-150/Q | 5962-9471601HMA | WF128K32N-150HSQ5 | 5962-9471601HZC |
| WE128K32-140H1Q | 5962-9458505H5C | AS8F128K32Q-150/Q | 5962-9471601HMC | WF128K32NA-150H1Q | 5962-9471601H7A |
| WE128K32-140HQ | 5962-9458505HXA | AS8F128K32Q-150/Q | 5962-9471601HNA | WF128K32NA-150H1Q | 5962-9471601H7C |
| WE128K32-140HQ | 5962-9458505HXC | AS8F128K32Q-150/Q | 5962-9471601HNC | WF128K32NA-150HQ5 | 5962-9471601HWA |
| WE128K32-140HQ | 5962-9458505HYA | WE128K32-150G1TQ | 5962-9458504HBA | WF128K32NA-150HQ5 | 5962-9471601HWC |
| WE128K32-140HQ | 5962-9458505HYC | WE128K32-150G1TQ | 5962-9458504HBC | WF128K32NA-150HSQ | 5962-9471601HXA |
| WE128K32N-140H1Q | 5962-9458505H4A | WE128K32-150G1UQ | 5962-9458504H9A | WF128K32NA-150HSQ | 5962-9471601HXC |
| WE128K32N-140H1Q | 5962-9458505H4C | WE128K32-150G1UQ | 5962-9458504H9C | WF128K32N-150H1Q | 5962-9461002H4A |
| WE128K32N-140HQ | 5962-9458505HTA | WE128K32-150G2Q | 5962-9458504HMA | WF128K32N-150H1Q | 5962-9461002H4C |
| WE128K32N-140HQ | 5962-9458505HTC | WE128K32-150G2Q | 5962-9458504HMC | WF128K32NA-150H1Q | 5962-9461002H5A |
| WE128K32N-140HQ | 5962-9458505HUA | WE128K32-150G4Q | 5962-9458504HNC | WF128K32NA-150H1Q | 5962-9461002H5C |
| WE128K32N-140HQ | 5962-9458505HUC | WE128K32-150H1Q | 5962-9458504H5A | WF128K32-150G2Q | 5962-9461002HMA |
| WE128K32NP-140H1Q | 5962-9458505H6A | WE128K32-150H1Q | 5962-9458504H5C | WF128K32-150G2Q | 5962-9461002HMC |
| WE128K32NP-140H1Q | 5962-9458505H6C | WE128K32N-150H1Q | 5962-9458504H4A | WF128K32-150G4Q | 5962-9461002HNC |
| AS8S128K32Q1-45/883 | 5962-9559506HAA | WE128K32N-150H1Q | 5962-9458504H4C | 128K32-150 (GEN) | 5962-9553801HYA |
| AS8S128K32Q1-45/883 | 5962-9559506HAC | WE128K32NP-150H1Q | 5962-9458504H6A | 128K32-150 (GEN) | 5962-9553801HXA |
| AS8S128K32Q1-45/883 | 5962-9559513HAA | WE128K32NP-150H1Q | 5962-9458504H6C | ACT-E128K32C-150P7 | 5962-9458504H5A |
| AS8S128K32Q1-45/883 | 5962-9559513HAC | WF128K32-150G1TQ5 | 5962-9471601HBA | ACT-E128K32C-150P7 | 5962-9458504H5C |
| WE128K32-150HQ | 5962-9458504HXA | WF128K32-150G1TQ5 | 5962-9471601HBC | ACT-E128K32N-150P7 | 5962-9458504H4A |
| WE128K32-150HQ | 5962-9458504HXC | WF128K32-150G1UQ5 | 5962-9471601H9A | ACT-E128K32N-150P7 | 5962-9458504H4C |
| WE128K32-150HQ | 5962-9458504HYA | WF128K32-150G1UQ5 | 5962-9471601H9C | WS128K32-15G1TQ | 5962-9559511HBA |
| WE128K32-150HQ | 5962-9458504HYC | WF128K32-150G2LQ5 | 5962-9471601HAA | WS128K32-15G1TQ | 5962-9559511HBC |
| WE128K32N-150HQ | 5962-9458504HTA | WF128K32-150G2LQ5 | 5962-9471601HAC | WS128K32-15G1UQ | 5962-9559511H9A |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART II, Listed By Generic PIN

| Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN |
|---|---|---|---|---|---|
| WS128K32-15G1UQ | 5962-9559511H9C | AS8S128K32P-17/883C | 5962-9318717H5A | 128K32-20 (GEN) | 5962-9318709HUA |
| WS128K32H-15G1TQ | 5962-9559518HBA | AS8S128K32P-17/883C | 5962-9318717H5C | 128K32-20 (GEN) | 5962-9318709HXA |
| WS128K32H-15G1TQ | 5962-9559518HBC | AS8S128K32PN-17/883 | 5962-9318710H4A | 128K32-20 (GEN) | 5962-9318709HYA |
| WS128K32H-15G1UQ | 5962-9559518H9A | AS8S128K32PN-17/883 | 5962-9318710H4C | ACT-S128K32C-020P2 | 5962-9318716HXA |
| WS128K32H-15G1UQ | 5962-9559518H9C | AS8S128K32PN-17/883 | 5962-9318717H4A | ACT-S128K32C-020P2 | 5962-9318716HXC |
| WS128K32-15G2LQ | 5962-9559511HAA | AS8S128K32PN-17/883 | 5962-9318717H4C | ACT-S128K32C-020P3 | 5962-9318716HNA |
| WS128K32-15G2LQ | 5962-9559511HAC | AS8S128K32Q-17/883C | 5962-9559510HMA | ACT-S128K32C-020P3 | 5962-9318716HNC |
| WS128K32-15G2UQ | 5962-9559511HMA | AS8S128K32Q-17/883C | 5962-9559510HMC | ACT-S128K32C-020P6 | 5962-9318716HYA |
| WS128K32-15G2UQ | 5962-9559511HMC | AS8S128K32Q-17/883C | 5962-9559517HMA | ACT-S128K32C-020P6 | 5962-9318716HYC |
| WS128K32-15G2UQ | 5962-9559511HNA | AS8S128K32Q-17/883C | 5962-9559517HMC | ACT-S128K32C-020P7 | 5962-9318716H5A |
| WS128K32-15G2UQ | 5962-9559511HNC | AS8S128K32QT-17/883 | 5962-9559510HMC | ACT-S128K32C-020P7 | 5962-9318716H5C |
| WS128K32H-15G2LQ | 5962-9559518HAA | AS8S128K32QT-17/883 | 5962-9559510HNA | ACT-S128K32N-020P2 | 5962-9318716HTA |
| WS128K32H-15G2LQ | 5962-9559518HAC | AS8S128K32QT-17/883 | 5962-9559517HNA | ACT-S128K32N-020P2 | 5962-9318716HTC |
| WS128K32H-15G2UQ | 5962-9559518HMA | AS8S128K32QT-17/883 | 5962-9559517HNC | ACT-S128K32N-020P3 | 5962-9318716HMA |
| WS128K32H-15G2UQ | 5962-9559518HMC | WS128K32-17H1Q | 5962-9318710H5A | ACT-S128K32N-020P3 | 5962-9318716HMC |
| WS128K32H-15G2UQ | 5962-9559518HNA | WS128K32-17H1Q | 5962-9318710H5C | ACT-S128K32N-020P6 | 5962-9318716HUA |
| WS128K32H-15G2UQ | 5962-9559518HNC | WS128K32H-17H1Q | 5962-9318717H5A | ACT-S128K32N-020P6 | 5962-9318716HUC |
| WS128K32-15G4Q | 5962-9559511HXA | WS128K32H-17H1Q | 5962-9318717H5C | ACT-S128K32N-020P7 | 5962-9318716H4A |
| WS128K32-15G4Q | 5962-9559511HXC | WS128K32N-17H1Q | 5962-9318710H4A | AS8S128K32P-20/883C | 5962-9318709H5A |
| WS128K32-15G4TQ | 5962-9559511HYA | WS128K32N-17H1Q | 5962-9318710H4C | AS8S128K32P-20/883C | 5962-9318709H5C |
| WS128K32-15G4TQ | 5962-9559511HYC | WS128K32NH-17H1Q | 5962-9318717H4A | AS8S128K32P-20/883C | 5962-9318716H5A |
| WS128K32H-15G4Q | 5962-9559518HXC | WS128K32NH-17H1Q | 5962-9318717H4C | AS8S128K32P-20/883C | 5962-9318716H5C |
| WS128K32H-15G4TQ | 5962-9559518HYC | AS8F128K32Q1-70/Q | 5962-9471604HAA | AS8S128K32PN-20/883 | 5962-9318709H4A |
| AS8S128K32Q1-55/883 | 5962-9559505HAA | AS8F128K32Q1-70/Q | 5962-9471604HAC | AS8S128K32PN-20/883 | 5962-9318709H4C |
| AS8S128K32Q1-55/883 | 5962-9559505HAC | WS128K32-17G1TQ | 5962-9559510HBA | AS8S128K32PN-20/883 | 5962-9318716H4A |
| AS8S128K32Q1-55/883 | 5962-9559512HAA | WS128K32-17G1TQ | 5962-9559510HBC | AS8S128K32PN-20/883 | 5962-9318716H4C |
| AS8S128K32Q1-55/883 | 5962-9559512HAC | WS128K32-17G1UQ | 5962-9559510H9A | AS8S128K32Q-20/883C | 5962-9559509HMA |
| AS8F128K32Q1-60/Q | 5962-9471605HAA | WS128K32-17G1UQ | 5962-9559510H9C | AS8S128K32Q-20/883C | 5962-9559509HMC |
| AS8F128K32Q1-60/Q | 5962-9471605HAC | WS128K32H-17G1TQ | 5962-9559517HBA | AS8S128K32Q-20/883C | 5962-9559516HMA |
| 128K32-17 (GEN) | 5962-9318710HMA | WS128K32H-17G1TQ | 5962-9559517HBC | AS8S128K32Q-20/883C | 5962-9559516HMC |
| 128K32-17 (GEN) | 5962-9318710HNA | WS128K32H-17G1UQ | 5962-9559517H9A | AS8S128K32QT-20/883 | 5962-9559509HNA |
| 128K32-17 (GEN) | 5962-9318710HTA | WS128K32H-17G1UQ | 5962-9559517H9C | AS8S128K32QT-20/883 | 5962-9559509HNC |
| 128K32-17 (GEN) | 5962-9318710HUA | WS128K32-17G2LQ | 5962-9559510HAA | AS8S128K32QT-20/883 | 5962-9559516HNA |
| 128K32-17 (GEN) | 5962-9318710HXA | WS128K32-17G2LQ | 5962-9559510HAC | AS8S128K32QT-20/883 | 5962-9559516HNC |
| 128K32-17 (GEN) | 5962-9318710HYA | WS128K32-17G2UQ | 5962-9559510HMA | WE128K32-200HQ | 5962-9458503HXA |
| ACT-S128K32C-017P2 | 5962-9318717HXA | WS128K32-17G2UQ | 5962-9559510HMC | WE128K32-200HQ | 5962-9458503HXC |
| ACT-S128K32C-017P2 | 5962-9318717HXC | WS128K32-17G2UQ | 5962-9559510HNA | WE128K32-200HQ | 5962-9458503HYA |
| ACT-S128K32C-017P3 | 5962-9318717HNA | WS128K32-17G2UQ | 5962-9559510HNC | WE128K32-200HQ | 5962-9458503HYC |
| ACT-S128K32C-017P3 | 5962-9318717HNC | WS128K32H-17G2LQ | 5962-9559517HAA | WE-128K32N-200HQ | 5962-9458503HUA |
| ACT-S128K32C-017P6 | 5962-9318717HYA | WS128K32H-17G2LQ | 5962-9559517HAC | WE128K32N-200HQ | 5962-9458503HTA |
| ACT-S128K32C-017P6 | 5962-9318717HYC | WS128K32H-17G2UQ | 5962-9559517HMA | WE128K32N-200HQ | 5962-9458503HTC |
| ACT-S128K32C-017P7 | 5962-9318717H5A | WS128K32H-17G2UQ | 5962-9559517HMC | WE128K32N-200HQ | 5962-9458503HUC |
| ACT-S128K32C-017P7 | 5962-9318717H5C | WS128K32H-17G2UQ | 5962-9559517HNA | WS128K32-20H1Q | 5962-9318709H5A |
| ACT-S128K32N-017P2 | 5962-9318717HTA | WS128K32H-17G2UQ | 5962-9559517HNC | WS128K32-20H1Q | 5962-9318709H5C |
| ACT-S128K32N-017P2 | 5962-9318717HTC | WS128K32-17G4Q | 5962-9559510HXC | WS128K32H-20H1Q | 5962-9318716H5A |
| ACT-S128K32N-017P3 | 5962-9318717HMA | WS128K32-17G4TQ | 5962-9559510HYC | WS128K32H-20H1Q | 5962-9318716H5C |
| ACT-S128K32N-017P3 | 5962-9318717HMC | WS128K32H-17G4Q | 5962-9559517HXC | WS128K32N-20H1Q | 5962-9318709H4A |
| ACT-S128K32N-017P6 | 5962-9318717HUA | WS128K32H-17G4TQ | 5962-9559517HYC | WS128K32N-20H1Q | 5962-9318709H4C |
| ACT-S128K32N-017P6 | 5962-9318717HUC | AS8F128K32Q1-90/Q | 5962-9471603HAA | WS128K32NH-20H1Q | 5962-9318716H4A |
| ACT-S128K32N-017P7 | 5962-9318717H4A | AS8F128K32Q1-90/Q | 5962-9471603HAC | WS128K32NH-20H1Q | 5962-9318716H4C |
| ACT-S128K32N-017P7 | 5962-9318717H4C | 128K32-20 (GEN) | 5962-9318709HMA | ACT-E128K32N-200F2 | 5962-9458503HMA |
| AS8S128K32P-17/883C | 5962-9318710H5A | 128K32-20 (GEN) | 5962-9318709HNA | ACT-E128K32N-200F2 | 5962-9458503HMC |
| AS8S128K32P-17/883C | 5962-9318710H5C | 128K32-20 (GEN) | 5962-9318709HTA | AS8E128K32P-200/883 | 5962-9458503H5C |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

| Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN |
|---|---|---|---|---|---|
| AS8E128K32P-200/883 | 5962-9458503H5A | WS128K32-20G2UQ | 5962-9559509HNC | WE128K32-250HQ | 5962-9458502HYA |
| AS8E128K32PN-200/88 | 5962-9458503H4A | WS128K32H-20G2LQ | 5962-9559516HAA | WE128K32-250HQ | 5962-9458502HYC |
| AS8E128K32PN-200/88 | 5962-9458503H4C | WS128K32H-20G2LQ | 5962-9559516HAC | WE128K32N-250HQ | 5962-9458502HTA |
| AS8E128K32Q-200/883 | 5962-9458503HMA | WS128K32H-20G2UQ | 5962-9559516HMA | WE128K32N-250HQ | 5962-9458502HTC |
| AS8E128K32Q-200/883 | 5962-9458503HMC | WS128K32H-20G2UQ | 5962-9559516HMC | WE128K32N-250HQ | 5962-9458502HUA |
| AS8ER128K32Q-200/88 | 5962-9458508HMA | WS128K32H-20G2UQ | 5962-9559516HNA | WE128K32N-250HQ | 5962-9458502HUC |
| AS8ER128K32Q-200/88 | 5962-9458508HMC | WS128K32H-20G2UQ | 5962-9559516HNC | WS128K32-25H1Q | 5962-9318708H5A |
| AS8ER128K32QB-200/ | 5962-9458508HZC | WS128K32-20G4Q | 5962-9559509HXC | WS128K32-25H1Q | 5962-9318708H5C |
| WE128K32-200G1TQ | 5962-9458503HBA | WS128K32-20G4TQ | 5962-9559509HYC | WS128K32H-25H1Q | 5962-9318715H5A |
| WE128K32-200G1TQ | 5962-9458503HBC | WS128K32H-20G4Q | 5962-9559516HXC | WS128K32H-25H1Q | 5962-9318715H5C |
| WE128K32-200G1UQ | 5962-9458503H9A | WS128K32H-20G4TQ | 5962-9559516HYC | WS128K32N-25H1Q | 5962-9318708H4A |
| WE128K32-200G1UQ | 5962-9458503H9C | 128K32-25 (GEN) | 5962-9318708HMA | WS128K32N-25H1Q | 5962-9318708H4C |
| WE128K32-200G2Q | 5962-9458503HMA | 128K32-25 (GEN) | 5962-9318708HNA | WS128K32NH-25H1Q | 5962-9318715H4A |
| WE128K32-200G2Q | 5962-9458503HMC | 128K32-25 (GEN) | 5962-9318708HTC | WS128K32NH-25H1Q | 5962-9318715H4C |
| WE128K32-200G4Q | 5962-9458503HNC | 128K32-25 (GEN) | 5962-9318708HUA | ACT-E128K32N-250F2 | 5962-9458502HMA |
| WE128K32-200H1Q | 5962-9458503H5A | 128K32-25 (GEN) | 5962-9318708HXA | ACT-E128K32N-250F2 | 5962-9458502HMC |
| WE128K32-200H1Q | 5962-9458503H5C | 128K32-25 (GEN) | 5962-9318708HYA | AS8E128K32P-250/883 | 5962-9458502H5A |
| WE128K32N-200H1Q | 5962-9458503H4A | ACT-S128K32C-025P2 | 5962-9318715HXA | AS8E128K32P-250/883 | 5962-9458502H5C |
| WE128K32N-200H1Q | 5962-9458503H4C | ACT-S128K32C-025P2 | 5962-9318715HXC | AS8E128K32PN-250/88 | 5962-9458502H4A |
| WE128K32NP-200H1Q | 5962-9458503H6A | ACT-S128K32C-025P3 | 5962-9318715HNA | AS8E128K32PN-250/88 | 5962-9458502H4C |
| WE128K32NP-200H1Q | 5962-9458503H6C | ACT-S128K32C-025P3 | 5962-9318715HNC | AS8E128K32Q-250/883 | 5962-9458502HMA |
| WF128K32-200HQ | 5962-9461001HXA | ACT-S128K32C-025P6 | 5962-9318715HYA | AS8E128K32Q-250/883 | 5962-9458502HMC |
| WF128K32-200HQ | 5962-9461001HXC | ACT-S128K32C-025P6 | 5962-9318715HYC | AS8ER128K32Q-250/88 | 5962-9458507HMA |
| WF128K32-200HSQ | 5962-9461001HWA | ACT-S128K32C-025P7 | 5962-9318715H5A | AS8ER128K32Q-250/88 | 5962-9458507HMC |
| WF128K32-200HSQ | 5962-9461001HWC | ACT-S128K32C-025P7 | 5962-9318715H5C | AS8ER128K32QB-250/ | 5962-9458507HZC |
| WF128K32N-200HQ | 5962-9461001HZA | ACT-S128K32N-025P2 | 5962-9318715HTA | WE128K32-250G1TQ | 5962-9458502HBA |
| WF128K32N-200HQ | 5962-9461001HZC | ACT-S128K32N-025P2 | 5962-9318715HTC | WE128K32-250G1TQ | 5962-9458502HBC |
| WF128K32N-200HSQ | 5962-9461001HYA | ACT-S128K32N-025P3 | 5962-9318715HMA | WE128K32-250G1UQ | 5962-9458502H9A |
| WF128K32N-200HSQ | 5962-9461001HYC | ACT-S128K32N-025P3 | 5962-9318715HMC | WE128K32-250G1UQ | 5962-9458502H9C |
| WF128K32N-200H1Q | 5962-9461001H4A | ACT-S128K32N-025P6 | 5962-9318715HUA | WE128K32-250G2Q | 5962-9458502HMA |
| WF128K32N-200H1Q | 5962-9461001H4C | ACT-S128K32N-025P6 | 5962-9318715HUC | WE128K32-250G2Q | 5962-9458502HMC |
| WF128K32NA-200H1Q | 5962-9461001H5A | ACT-S128K32N-025P7 | 5962-9318715H4A | WE128K32-250G4Q | 5962-9458502HNC |
| WF128K32NA-200H1Q | 5962-9461001H5C | ACT-S128K32N-025P7 | 5962-9318715H4C | WE128K32-250H1Q | 5962-9458502H5A |
| WF128K32-200G2Q | 5962-9461001HMA | AS8S128K32P-25/883C | 5962-9318708H5A | WE128K32-250H1Q | 5962-9458502H5C |
| WF128K32-200G2Q | 5962-9461001HMC | AS8S128K32P-25/883C | 5962-9318708H5C | WE128K32N-250H1Q | 5962-9458502H4A |
| WF128K32-200G4Q | 5962-9461001HNC | AS8S128K32P-25/883C | 5962-9318715H5A | WE128K32N-250H1Q | 5962-9458502H4C |
| ACT-E128K32C-200P7 | 5962-9458503H5A | AS8S128K32P-25/883C | 5962-9318715H5C | WE128K32NP-250H1Q | 5962-9458502H6A |
| ACT-E128K32C-200P7 | 5962-9458503H5C | AS8S128K32PN-25/883 | 5962-9318708H4A | WE128K32NP-250H1Q | 5962-9458502H6C |
| ACT-E128K32N-200P7 | 5962-9458503H4A | AS8S128K32PN-25/883 | 5962-9318708H4C | ACT-E128K32C-250P7 | 5962-9458502H5A |
| ACT-E128K32N-200P7 | 5962-9458503H4C | AS8S128K32PN-25/883 | 5962-9318715H4A | ACT-E128K32C-250P7 | 5962-9458502H5C |
| WS128K32-20G1TQ | 5962-9559509HBA | AS8S128K32PN-25/883 | 5962-9318715H4C | ACT-E128K32N-250P7 | 5962-9458502H4A |
| WS128K32-20G1TQ | 5962-9559509HBC | AS8S128K32Q-25/883C | 5962-9559508HMA | ACT-E128K32N-250P7 | 5962-9458502H4C |
| WS128K32-20G1UQ | 5962-9559509H9A | AS8S128K32Q-25/883C | 5962-9559508HMC | WS128K32-25G1TQ | 5962-9559508HBA |
| WS128K32-20G1UQ | 5962-9559509H9C | AS8S128K32Q-25/883C | 5962-9559515HMA | WS128K32-25G1TQ | 5962-9559508HBC |
| WS128K32H-20G1TQ | 5962-9559516HBA | AS8S128K32Q-25/883C | 5962-9559515HMC | WS128K32-25G1UQ | 5962-9559508H9A |
| WS128K32H-20G1TQ | 5962-9559516HBC | AS8S128K32QT-25/883 | 5962-9559508HNA | WS128K32-25G1UQ | 5962-9559508H9C |
| WS128K32H-20G1UQ | 5962-9559516H9A | AS8S128K32QT-25/883 | 5962-9559508HNC | WS128K32H-25G1TQ | 5962-9559515HBA |
| WS128K32H-20G1UQ | 5962-9559516H9C | AS8S128K32QT-25/883 | 5962-9559514HNA | WS128K32H-25G1TQ | 5962-9559515HBC |
| WS128K32-20G2LQ | 5962-9559509HAA | AS8S128K32QT-25/883 | 5962-9559514HNC | WS128K32H-25G1UQ | 5962-9559515H9A |
| WS128K32-20G2LQ | 5962-9559509HAC | AS8S128K32QT-25/883 | 5962-9559515HNA | WS128K32H-25G1UQ | 5962-9559515H9C |
| WS128K32-20G2UQ | 5962-9559509HMA | AS8S128K32QT-25/883 | 5962-9559515HNC | WS128K32-25G2LQ | 5962-9559508HAA |
| WS128K32-20G2UQ | 5962-9559509HMC | WE128K32-250HQ | 5962-9458502HXA | WS128K32-25G2LQ | 5962-9559508HAC |
| WS128K32-20G2UQ | 5962-9559509HNA | WE128K32-250HQ | 5962-9458502HXC | WS128K32-25G2UQ | 5962-9559508HMA |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART II, Listed By Generic PIN

| Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN |
|---|---|---|---|---|---|
| WS128K32-25G2UQ | 5962-9559508HMC | ACT-S128K32C-035P2 | 5962-9318714HXC | WS128K32H-35G2UQ | 5962-9559514HMA |
| WS128K32-25G2UQ | 5962-9559508HNA | ACT-S128K32C-035P3 | 5962-9318714HNA | WS128K32H-35G2UQ | 5962-9559514HMC |
| WS128K32-25G2UQ | 5962-9559508HNC | ACT-S128K32C-035P3 | 5962-9318714HNC | WS128K32H-35G2UQ | 5962-9559514HNA |
| WS128K32H-25G2LQ | 5962-9559515HAA | ACT-S128K32C-035P6 | 5962-9318714HYA | WS128K32H-35G2UQ | 5962-9559514HNC |
| WS128K32H-25G2LQ | 5962-9559515HAC | ACT-S128K32C-035P6 | 5962-9318714HYC | WS128K32-35G4Q | 5962-9559507HXC |
| WS128K32H-25G2UQ | 5962-9559515HMA | ACT-S128K32C-035P7 | 5962-9318714H5A | WS128K32-35G4TQ | 5962-9559507HYC |
| WS128K32H-25G2UQ | 5962-9559515HMC | ACT-S128K32C-035P7 | 5962-9318714H5C | WS128K32H-35G4Q | 5962-9559514HXC |
| WS128K32H-25G2UQ | 5962-9559515HNA | ACT-S128K32N-035P2 | 5962-9318714HTA | WS128K32H-35G4TQ | 5962-9559514HYC |
| WS128K32H-25G2UQ | 5962-9559515HNC | ACT-S128K32N-035P2 | 5962-9318714HTC | 128K32-45 (GEN) | 5962-9318706HMA |
| WS128K32-25G4Q | 5962-9559508HXC | ACT-S128K32N-035P3 | 5962-9318714HMA | 128K32-45 (GEN) | 5962-9318706HNA |
| WS128K32-25G4TQ | 5962-9559508HYC | ACT-S128K32N-035P3 | 5962-9318714HMC | 128K32-45 (GEN) | 5962-9318706HTA |
| WS128K32H-25G4Q | 5962-9559515HXC | ACT-S128K32N-035P6 | 5962-9318714HUA | 128K32-45 (GEN) | 5962-9318706HUA |
| WS128K32H-25G4TQ | 5962-9559515HYC | ACT-S128K32N-035P6 | 5962-9318714HUC | 128K32-45 (GEN) | 5962-9318706HXA |
| WE128K32-300HQ | 5962-9458501HXA | ACT-S128K32N-035P7 | 5962-9318714H4A | 128K32-45 (GEN) | 5962-9318706HYA |
| WE128K32-300HQ | 5962-9458501HXC | ACT-S128K32N-035P7 | 5962-9318714H4C | ACT-S128K32C-045P2 | 5962-9318713HXA |
| WE128K32-300HQ | 5962-9458501HYA | AS8S128K32P-35/883C | 5962-9318707H5A | ACT-S128K32C-045P2 | 5962-9318713HXC |
| WE128K32-300HQ | 5962-9458501HYC | AS8S128K32P-35/883C | 5962-9318707H5C | ACT-S128K32C-045P3 | 5962-9318713HNA |
| WE128K32N-300HQ | 5962-9458501HTA | AS8S128K32P-35/883C | 5962-9318714H5A | ACT-S128K32C-045P3 | 5962-9318713HNC |
| WE128K32N-300HQ | 5962-9458501HTC | AS8S128K32P-35/883C | 5962-9318714H5C | ACT-S128K32C-045P6 | 5962-9318713HYA |
| WE128K32N-300HQ | 5962-9458501HUA | AS8S128K32PN-35/883 | 5962-9318707H4A | ACT-S128K32C-045P6 | 5962-9318713HYC |
| WE128K32N-300HQ | 5962-9458501HUC | AS8S128K32PN-35/883 | 5962-9318707H4C | ACT-S128K32C-045P7 | 5962-9318713H5A |
| ACT-E128K32N-300F2 | 5962-9458501HMA | AS8S128K32PN-35/883 | 5962-9318714H4A | ACT-S128K32C-045P7 | 5962-9318713H5C |
| ACT-E128K32N-300F2 | 5962-9458501HMC | AS8S128K32PN-35/883 | 5962-9318714H4C | ACT-S128K32N-045P2 | 5962-9318713HTA |
| AS8E128K32P-300/883 | 5962-9458501H5A | AS8S128K32Q-35/883C | 5962-9559507HMA | ACT-S128K32N-045P2 | 5962-9318713HTC |
| AS8E128K32P-300/883 | 5962-9458501H5C | AS8S128K32Q-35/883C | 5962-9559507HMC | ACT-S128K32N-045P3 | 5962-9318713HMA |
| AS8E128K32PN-300/88 | 5962-9458501H4A | AS8S128K32Q-35/883C | 5962-9559514HMA | ACT-S128K32N-045P3 | 5962-9318713HMC |
| AS8E128K32PN-300/88 | 5962-9458501H4C | AS8S128K32Q-35/883C | 5962-9559514HMC | ACT-S128K32N-045P6 | 5962-9318713HUA |
| AS8E128K32Q-300/883 | 5962-9458501HMA | AS8S128K32QT-35/883 | 5962-9559507HNA | ACT-S128K32N-045P6 | 5962-9318713HUC |
| AS8E128K32Q-300/883 | 5962-9458501HMC | AS8S128K32QT-35/883 | 5962-9559507HNC | ACT-S128K32N-045P7 | 5962-9318713H4A |
| WE128K32-300G1TQ | 5962-9458501HBA | WS128K32-35H1Q | 5962-9318707H5A | ACT-S128K32N-045P7 | 5962-9318713H4C |
| WE128K32-300G1TQ | 5962-9458501HBC | WS128K32-35H1Q | 5962-9318707H5C | AS8S128K32P-45/883C | 5962-9318706H5A |
| WE128K32-300G1UQ | 5962-9458501H9A | WS128K32H-35H1Q | 5962-9318714H5A | AS8S128K32P-45/883C | 5962-9318706H5C |
| WE128K32-300G1UQ | 5962-9458501H9C | WS128K32H-35H1Q | 5962-9318714H5C | AS8S128K32P-45/883C | 5962-9318713H4A |
| WE128K32-300G2Q | 5962-9458501HMA | WS128K32N-35H1Q | 5962-9318707H4A | AS8S128K32P-45/883C | 5962-9318713H4C |
| WE128K32-300G2Q | 5962-9458501HMC | WS128K32N-35H1Q | 5962-9318707H4C | AS8S128K32P-45/883C | 5962-9318713H5A |
| WE128K32-300G4Q | 5962-9458501HNC | WS128K32NH-35H1Q | 5962-9318714H4A | AS8S128K32P-45/883C | 5962-9318713H5C |
| WE128K32-300H1Q | 5962-9458501H5A | WS128K32NH-35H1Q | 5962-9318714H4C | AS8S128K32PN-45/883 | 5962-9318706H4A |
| WE128K32-300H1Q | 5962-9458501H5C | WS128K32-35G1TQ | 5962-9559507HBA | AS8S128K32PN-45/883 | 5962-9318706H4C |
| WE128K32N-300H1Q | 5962-9458501H4A | WS128K32-35G1TQ | 5962-9559507HBC | AS8S128K32Q-45/883C | 5962-9559506HMA |
| WE128K32N-300H1Q | 5962-9458501H4C | WS128K32-35G1UQ | 5962-9559507H9A | AS8S128K32Q-45/883C | 5962-9559506HMC |
| WE128K32NP-300H1Q | 5962-9458501H6A | WS128K32-35G1UQ | 5962-9559507H9C | AS8S128K32Q-45/883C | 5962-9559513HMA |
| WE128K32NP-300H1Q | 5962-9458501H6C | WS128K32H-35G1TQ | 5962-9559514HBA | AS8S128K32Q-45/883C | 5962-9559513HMC |
| ACT-E128K32C-300P7 | 5962-9458501H5A | WS128K32H-35G1TQ | 5962-9559514HBC | AS8S128K32QT-45/883 | 5962-9559506HNA |
| ACT-E128K32C-300P7 | 5962-9458501H5C | WS128K32H-35G1UQ | 5962-9559514H9A | AS8S128K32QT-45/883 | 5962-9559506HNC |
| ACT-E128K32N-300P7 | 5962-9458501H4A | WS128K32H-35G1UQ | 5962-9559514H9C | AS8S128K32QT-45/883 | 5962-9559513HNA |
| ACT-E128K32N-300P7 | 5962-9458501H4C | WS128K32-35G2LQ | 5962-9559507HAA | AS8S128K32QT-45/883 | 5962-9559513HNC |
| 128K32-35 (GEN) | 5962-9318707HMA | WS128K32-35G2LQ | 5962-9559507HAC | WS128K32-45H1Q | 5962-9318706H5A |
| 128K32-35 (GEN) | 5962-9318707HNA | WS128K32-35G2UQ | 5962-9559507HMA | WS128K32-45H1Q | 5962-9318706H5C |
| 128K32-35 (GEN) | 5962-9318707HTA | WS128K32-35G2UQ | 5962-9559507HMC | WS128K32H-45H1Q | 5962-9318713H5A |
| 128K32-35 (GEN) | 5962-9318707HUA | WS128K32-35G2UQ | 5962-9559507HNA | WS128K32H-45H1Q | 5962-9318713H5C |
| 128K32-35 (GEN) | 5962-9318707HXA | WS128K32-35G2UQ | 5962-9559507HNC | WS128K32N-45H1Q | 5962-9318706H4A |
| 128K32-35 (GEN) | 5962-9318707HYA | WS128K32H-35G2LQ | 5962-9559514HAA | WS128K32N-45H1Q | 5962-9318706H4C |
| ACT-S128K32C-035P2 | 5962-9318714HXA | WS128K32H-35G2LQ | 5962-9559514HAC | WS128K32NH-45H1Q | 5962-9318713H4A |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART II, Listed By Generic PIN

| Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN |
|---|---|---|---|---|---|
| WS128K32NH-45H1Q | 5962-9318713H4C | AS8S128K32Q-55/883C | 5962-9559505HMA | WF128K32-60G2Q5 | 5962-9471605HMC |
| WS128K32-45G1TQ | 5962-9559506HBA | AS8S128K32Q-55/883C | 5962-9559505HMC | WF128K32-60G2UQ5 | 5962-9471605HNA |
| WS128K32-45G1TQ | 5962-9559506HBC | AS8S128K32Q-55/883C | 5962-9559512HMA | WF128K32-60G2UQ5 | 5962-9471605HNC |
| WS128K32-45G1UQ | 5962-9559506H9A | AS8S128K32Q-55/883C | 5962-9559512HMC | WF128K32-60G4Q5 | 5962-9471605H4C |
| WS128K32-45G1UQ | 5962-9559506H9C | AS8S128K32QT-55/883 | 5962-9559505HNA | WF128K32-60H1Q5 | 5962-9471605H6A |
| WS128K32H-45G1TQ | 5962-9559513HBA | AS8S128K32QT-55/883 | 5962-9559505HNC | WF128K32-60H1Q5 | 5962-9471605H6C |
| WS128K32H-45G1TQ | 5962-9559513HBC | AS8S128K32QT-55/883 | 5962-9559512HNA | WF128K32-60HQ5 | 5962-9471605HUA |
| WS128K32H-45G1UQ | 5962-9559513H9A | AS8S128K32QT-55/883 | 5962-9559512HNC | WF128K32-60HQ5 | 5962-9471605HUC |
| WS128K32H-45G1UQ | 5962-9559513H9C | WS128K32-55H1Q | 5962-9318705H5A | WF128K32-60HSQ5 | 5962-9471605HVA |
| WS128K32-45G2LQ | 5962-9559506HAA | WS128K32-55H1Q | 5962-9318705H5C | WF128K32-60HSQ5 | 5962-9471605HVC |
| WS128K32-45G2LQ | 5962-9559506HAC | WS128K32H-55H1Q | 5962-9318712H5A | WF128K32A-60H1Q5 | 5962-9471605H5A |
| WS128K32-45G2UQ | 5962-9559506HMA | WS128K32H-55H1Q | 5962-9318712H5C | WF128K32A-60H1Q5 | 5962-9471605H5C |
| WS128K32-45G2UQ | 5962-9559506HMC | WS128K32N-55H1Q | 5962-9318705H4A | WF128K32A-60HQ5 | 5962-9471605HSA |
| WS128K32-45G2UQ | 5962-9559506HNA | WS128K32N-55H1Q | 5962-9318705H4C | WF128K32A-60HQ5 | 5962-9471605HSC |
| WS128K32-45G2UQ | 5962-9559506HNC | WS128K32NH-55H1Q | 5962-9318712H4A | WF128K32A-60HSQ5 | 5962-9471605HTA |
| WS128K32H-45G2LQ | 5962-9559513HAA | WS128K32NH-55H1Q | 5962-9318712H4C | WF128K32A-60HSQ5 | 5962-9471605HTC |
| WS128K32H-45G2LQ | 5962-9559513HAC | ACT-S128K32N-055F1 | 5962-9559505HXA | WF128K32N-60H1Q5 | 5962-9471605H8A |
| WS128K32H-45G2UQ | 5962-9559513HMA | ACT-S128K32N-055F1 | 5962-9559505HXC | WF128K32N-60H1Q5 | 5962-9471605H8C |
| WS128K32H-45G2UQ | 5962-9559513HMC | WS128K32-55G1TQ | 5962-9559505HBA | WF128K32N-60HQ5 | 5962-9471605HYA |
| WS128K32H-45G2UQ | 5962-9559513HNA | WS128K32-55G1TQ | 5962-9559505HBC | WF128K32N-60HQ5 | 5962-9471605HYC |
| WS128K32H-45G2UQ | 5962-9559513HNC | WS128K32-55G1UQ | 5962-9559505H9A | WF128K32N-60HSQ5 | 5962-9471605HZA |
| WS128K32-45G4Q | 5962-9559506HXC | WS128K32-55G1UQ | 5962-9559505H9C | WF128K32N-60HSQ5 | 5962-9471605HZC |
| WS128K32-45G4TQ | 5962-9559506HYC | WS128K32H-55G1TQ | 5962-9559512HBA | WF128K32NA-60H1Q5 | 5962-9471605H7A |
| WS128K32H-45G4Q | 5962-9559513HXC | WS128K32H-55G1TQ | 5962-9559512HBC | WF128K32NA-60H1Q5 | 5962-9471605H7C |
| WS128K32H-45G4TQ | 5962-9559513HYC | WS128K32H-55G1UQ | 5962-9559512H9A | WF128K32NA-60HQ5 | 5962-9471605HWA |
| 128K32-55 (GEN) | 5962-9318705HMA | WS128K32H-55G1UQ | 5962-9559512H9C | WF128K32NA-60HQ5 | 5962-9471605HWC |
| 128K32-55 (GEN) | 5962-9318705HNA | WS128K32-55G2LQ | 5962-9559505HAA | WF128K32NA-60HSQ5 | 5962-9471605HXA |
| 128K32-55 (GEN) | 5962-9318705HTA | WS128K32-55G2LQ | 5962-9559505HAC | WF128K32NA-60HSQ5 | 5962-9471605HXC |
| 128K32-55 (GEN) | 5962-9318705HUA | WS128K32-55G2Q | 5962-9559505HMA | 128K32-70 (GEN) | 5962-9318704HTA |
| 128K32-55 (GEN) | 5962-9318705HXA | WS128K32-55G2Q | 5962-9559505HMC | 128K32-70 (GEN) | 5962-9318704HUA |
| 128K32-55 (GEN) | 5962-9318705HYA | WS128K32-55G2UQ | 5962-9559505HNA | 128K32-70 (GEN) | 5962-9318704HXA |
| ACT-S128K32C-055P2 | 5962-9318712HXA | WS128K32-55G2UQ | 5962-9559505HNC | 128K32-70 (GEN) | 5962-9318704HYA |
| ACT-S128K32C-055P2 | 5962-9318712HXC | WS128K32H-55G2LQ | 5962-9559512HAA | AS8F128K32Q-70/Q | 5962-9471604HMA |
| ACT-S128K32C-055P3 | 5962-9318712HNA | WS128K32H-55G2LQ | 5962-9559512HAC | AS8F128K32Q-70/Q | 5962-9471604HMC |
| ACT-S128K32C-055P3 | 5962-9318712HNC | WS128K32H-55G2Q | 5962-9559512HMA | AS8F128K32Q-70/Q | 5962-9471604HNA |
| ACT-S128K32C-055P7 | 5962-9318712H5A | WS128K32H-55G2UQ | 5962-9559512HMC | AS8F128K32Q-70/Q | 5962-9471604HNC |
| ACT-S128K32C-055P7 | 5962-9318712H5C | WS128K32H-55G2UQ | 5962-9559512HNA | WF128K32-70G1TQ5 | 5962-9471604HBA |
| ACT-S128K32N-055P2 | 5962-9318712HTA | WS128K32H-55G2UQ | 5962-9559512HNC | WF128K32-70G1TQ5 | 5962-9471604HBC |
| ACT-S128K32N-055P2 | 5962-9318712HTC | WS128K32-55G4Q | 5962-9559505HXC | WF128K32-70G1UQ5 | 5962-9471604H9A |
| ACT-S128K32N-055P3 | 5962-9318712HMA | WS128K32-55G4TQ | 5962-9559505HYC | WF128K32-70G1UQ5 | 5962-9471604H9C |
| ACT-S128K32N-055P3 | 5962-9318712HMC | WS128K32H-55G4Q | 5962-9559512HXC | WF128K32-70G2LQ5 | 5962-9471604HAA |
| ACT-S128K32N-055P6 | 5962-9318712HUA | WS128K32H-55G4TQ | 5962-9559512HYC | WF128K32-70G2LQ5 | 5962-9471604HAC |
| ACT-S128K32N-055P6 | 5962-9318712HUC | AS8F128K32Q-60/Q | 5962-9471605HMA | WF128K32-70G2Q5 | 5962-9471604HMA |
| ACT-S128K32N-055P7 | 5962-9318712H4A | AS8F128K32Q-60/Q | 5962-9471605HMC | WF128K32-70G2Q5 | 5962-9471604HMC |
| ACT-S128K32N-055P7 | 5962-9318712H4C | AS8F128K32Q-60/Q | 5962-9471605HNA | WF128K32-70G2UQ5 | 5962-9471604HNA |
| AS8S128K32P-55/883C | 5962-9318705H5A | AS8F128K32Q-60/Q | 5962-9471605HNC | WF128K32-70G2UQ5 | 5962-9471604HNC |
| AS8S128K32P-55/883C | 5962-9318705H5C | WF128K32-60G1TQ5 | 5962-9471605HBA | WF128K32-70G4Q5 | 5962-9471604H4C |
| AS8S128K32P-55/883C | 5962-9318712H5A | WF128K32-60G1TQ5 | 5962-9471605HBC | WF128K32-70H1Q5 | 5962-9471604H6A |
| AS8S128K32P-55/883C | 5962-9318712H5C | WF128K32-60G1UQ5 | 5962-9471605H9A | WF128K32-70H1Q5 | 5962-9471604H6C |
| AS8S128K32PN-55/883 | 5962-9318705H4A | WF128K32-60G1UQ5 | 5962-9471605H9C | WF128K32-70HQ5 | 5962-9471604HUA |
| AS8S128K32PN-55/883 | 5962-9318705H4C | WF128K32-60G2LQ5 | 5962-9471605HAA | WF128K32-70HQ5 | 5962-9471604HUC |
| AS8S128K32PN-55/883 | 5962-9318712H4A | WF128K32-60G2LQ5 | 5962-9471605HAC | WF128K32-70HSQ5 | 5962-9471604HVA |
| AS8S128K32PN-55/883 | 5962-9318712H4C | WF128K32-60G2Q5 | 5962-9471605HMA | WF128K32-70HSQ5 | 5962-9471604HVC |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART II, Listed By Generic PIN

| Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN |
|---|---|---|---|---|---|
| WF128K32A-70H1Q5 | 5962-9471604H5A | AS8F128K32Q-90/Q | 5962-9471603HNC | ACT-F128K8N-090P4Q | 5962-9669003HYC |
| WF128K32A-70H1Q5 | 5962-9471604H5C | WF128K32-90G1TQ5 | 5962-9471603HBA | WMS128K8-100C | 5962-9669102HYA |
| WF128K32A-70HQ5 | 5962-9471604HSA | WF128K32-90G1TQ5 | 5962-9471603HBC | WMS128K8-100C | 5962-9669102HYC |
| WF128K32A-70HQ5 | 5962-9471604HSC | WF128K32-90G1UQ5 | 5962-9471603H9A | WMS128K8-100DE | 5962-9669102HTA |
| WF128K32A-70HSQ5 | 5962-9471604HTA | WF128K32-90G1UQ5 | 5962-9471603H9C | WMS128K8-100DE | 5962-9669102HTC |
| WF128K32A-70HSQ5 | 5962-9471604HTC | WF128K32-90G2LQ5 | 5962-9471603HAA | WMS128K8-100DR | 5962-9669102HUA |
| WF128K32N-70H1Q5 | 5962-9471604H8A | WF128K32-90G2LQ5 | 5962-9471603HAC | WMS128K8-100DR | 5962-9669102HUC |
| WF128K32N-70H1Q5 | 5962-9471604H8C | WF128K32-90G2Q5 | 5962-9471603HMA | WMS128K8-100FE | 5962-9669102HNA |
| WF128K32N-70HQ5 | 5962-9471604HYA | WF128K32-90G2Q5 | 5962-9471603HMC | WMS128K8-100FE | 5962-9669102HNC |
| WF128K32N-70HQ5 | 5962-9471604HYC | WF128K32-90G2UQ5 | 5962-9471603HNA | WS-128K8-100 (GEN) | 5962-9315602HXA |
| WF128K32N-70HSQ5 | 5962-9471604HZA | WF128K32-90G2UQ5 | 5962-9471603HNC | WS-128K8-100CQ | 5962-9315602HYA |
| WF128K32N-70HSQ5 | 5962-9471604HZC | WF128K32-90G4Q5 | 5962-9471603H4C | WS-128K8-100CQ | 5962-9315602HYC |
| WF128K32NA-70H1Q5 | 5962-9471604H7A | WF128K32-90H1Q5 | 5962-9471603H6A | ACT-F128K8N-120F6Q | 5962-9669002HTA |
| WF128K32NA-70H1Q5 | 5962-9471604H7C | WF128K32-90H1Q5 | 5962-9471603H6C | ACT-F128K8N-120F6Q | 5962-9669002HTC |
| WF128K32NA-70HQ5 | 5962-9471604HWA | WF128K32-90HQ5 | 5962-9471603HUA | ACT-F128K8N-120F7Q | 5962-9669002HUA |
| WF128K32NA-70HQ5 | 5962-9471604HWC | WF128K32-90HQ5 | 5962-9471603HUC | ACT-F128K8N-120F7Q | 5962-9669002HUC |
| WF128K32NA-70HSQ5 | 5962-9471604HXA | WF128K32-90HSQ5 | 5962-9471603HVA | ACT-F128K8N-120P4Q | 5962-9669002HYA |
| WF128K32NA-70HSQ5 | 5962-9471604HXC | WF128K32-90HSQ5 | 5962-9471603HVC | ACT-F128K8N-120P4Q | 5962-9669002HYC |
| WS128K32-70H1Q | 5962-9318704H5A | WF128K32A-90H1Q5 | 5962-9471603H5A | WMS128K8-120C | 5962-9669101HYA |
| WS128K32-70H1Q | 5962-9318704H5C | WF128K32A-90H1Q5 | 5962-9471603H5C | WMS128K8-120C | 5962-9669101HYC |
| WS128K32N-70H1Q | 5962-9318704H4A | WF128K32A-90HQ5 | 5962-9471603HSA | WMS128K8-120DE | 5962-9669101HTA |
| WS128K32N-70H1Q | 5962-9318704H4C | WF128K32A-90HQ5 | 5962-9471603HSC | WMS128K8-120DE | 5962-9669101HTC |
| WS128K32-70G1TQ | 5962-9559504HBA | WF128K32A-90HSQ5 | 5962-9471603HTA | WMS128K8-120DR | 5962-9669101HUA |
| WS128K32-70G1TQ | 5962-9559504HBC | WF128K32A-90HSQ5 | 5962-9471603HTC | WMS128K8-120DR | 5962-9669101HUC |
| WS128K32-70G1UQ | 5962-9559504H9A | WF128K32N-90H1Q5 | 5962-9471603H8A | WMS128K8-120FE | 5962-9669101HNA |
| WS128K32-70G1UQ | 5962-9559504H9C | WF128K32N-90H1Q5 | 5962-9471603H8C | WMS128K8-120FE | 5962-9669101HNC |
| WS128K32-70G2Q | 5962-9559504HMA | WF128K32N-90HQ5 | 5962-9471603HYA | WS-128K8-120 (GEN) | 5962-9315601HXA |
| WS128K32-70G2Q | 5962-9559504HMC | WF128K32N-90HQ5 | 5962-9471603HYC | WS-128K8-120CQ | 5962-9315601HYA |
| WS128K32-70G2UQ | 5962-9559504HNA | WF128K32N-90HSQ5 | 5962-9471603HZA | WS-128K8-120CQ | 5962-9315601HYC |
| WS128K32-70G2UQ | 5962-9559504HNC | WF128K32N-90HSQ5 | 5962-9471603HZC | WME128K8-120CQ | 5962-9679606HYA |
| WS128K32-70G4Q | 5962-9559504HXC | WF128K32NA-90H1Q5 | 5962-9471603H7A | WME128K8-120CQ | 5962-9679606HYC |
| WS128K32-70G4TQ | 5962-9559504HYC | WF128K32NA-90H1Q5 | 5962-9471603H7C | WME128K8-120DEQ | 5962-9679606HXA |
| 128K32-85 (GEN) | 5962-9318703HTA | WF128K32NA-90HQ5 | 5962-9471603HWA | WME128K8-120DEQ | 5962-9679606HXC |
| 128K32-85 (GEN) | 5962-9318703HUA | WF128K32NA-90HQ5 | 5962-9471603HWC | WMF128K8-120CQ5 | 5962-9669002HYA |
| 128K32-85 (GEN) | 5962-9318703HXA | WF128K32NA-90HSQ5 | 5962-9471603HXA | WMF128K8-120CQ5 | 5962-9669002HYC |
| 128K32-85 (GEN) | 5962-9318703HYA | WF128K32NA-90HSQ5 | 5962-9471603HXC | WMF128K8-120DEQ5 | 5962-9669002HXA |
| WS128K32-85H1Q | 5962-9318703H5A | ACT-F128K8N-060F6Q | 5962-9669005HTA | WMF128K8-120DEQ5 | 5962-9669002HXC |
| WS128K32-85H1Q | 5962-9318703H5C | ACT-F128K8N-060F6Q | 5962-9669005HTC | WMF128K8-120FEQ5 | 5962-9669002HTA |
| WS128K32N-85H1Q | 5962-9318703H4A | ACT-F128K8N-060F7Q | 5962-9669005HUA | WMF128K8-120FEQ5 | 5962-9669002HTC |
| WS128K32N-85H1Q | 5962-9318703H4C | ACT-F128K8N-060F7Q | 5962-9669005HUC | WMF128K8-120FFQ5 | 5962-9669002HUA |
| WS128K32-85G1TQ | 5962-9559503HBA | ACT-F128K8N-060P4Q | 5962-9669005HYA | WMF128K8-120FFQ5 | 5962-9669002HUC |
| WS128K32-85G1TQ | 5962-9559503HBC | ACT-F128K8N-060P4Q | 5962-9669005HYC | WME128K8-140CQ | 5962-9679605HYA |
| WS128K32-85G1UQ | 5962-9559503H9A | ACT-F128K8N-070F6Q | 5962-9669004HTA | WME128K8-140CQ | 5962-9679605HYC |
| WS128K32-85G1UQ | 5962-9559503H9C | ACT-F128K8N-070F6Q | 5962-9669004HTC | WME128K8-140DEQ | 5962-9679605HXA |
| WS128K32-85G2Q | 5962-9559503HMA | ACT-F128K8N-070F7Q | 5962-9669004HUA | WME128K8-140DEQ | 5962-9679605HXC |
| WS128K32-85G2Q | 5962-9559503HMC | ACT-F128K8N-070F7Q | 5962-9669004HUC | WMS128K8-15C | 5962-9669111HYA |
| WS128K32-85G2UQ | 5962-9559503HNA | ACT-F128K8N-070P4Q | 5962-9669004HYA | WMS128K8-15C | 5962-9669111HYC |
| WS128K32-85G2UQ | 5962-9559503HNC | ACT-F128K8N-070P4Q | 5962-9669004HYC | WMS128K8-15DE | 5962-9669111HTA |
| WS128K32-85G4Q | 5962-9559503HXC | ACT-F128K8N-090F6Q | 5962-9669003HTA | WMS128K8-15DE | 5962-9669111HTC |
| WS128K32-85G4TQ | 5962-9559503HYC | ACT-F128K8N-090F6Q | 5962-9669003HTC | WMS128K8-15DJ | 5962-9669111HZA |
| AS8F128K32Q-90/Q | 5962-9471603HMA | ACT-F128K8N-090F7Q | 5962-9669003HUA | WMS128K8-15DJ | 5962-9669111HZC |
| AS8F128K32Q-90/Q | 5962-9471603HMC | ACT-F128K8N-090F7Q | 5962-9669003HUC | WMS128K8-15DR | 5962-9669111HUA |
| AS8F128K32Q-90/Q | 5962-9471603HNA | ACT-F128K8N-090P4Q | 5962-9669003HYA | WMS128K8-15DR | 5962-9669111HUC |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART II, Listed By Generic PIN

| Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN |
|---|---|---|---|---|---|
| WMS128K8-15F | 5962-9669111HXC | WMS128K8-25F | 5962-9669108HXC | WMF128K8-60DEQ5 | 5962-9669005HXC |
| ACT-F128K8N-150F6Q | 5962-9669001HTA | WS-128K8-25 (GEN) | 5962-9315608HXA | WMF128K8-60FEQ5 | 5962-9669005HTA |
| ACT-F128K8N-150F6Q | 5962-9669001HTC | WS-128K8-25CQ | 5962-9315608HYA | WMF128K8-60FEQ5 | 5962-9669005HTC |
| ACT-F128K8N-150F7Q | 5962-9669001HUA | WS-128K8-25CQ | 5962-9315608HYC | WMF128K8-60FFQ5 | 5962-9669005HUA |
| ACT-F128K8N-150F7Q | 5962-9669001HUC | WME128K8-250CQ | 5962-9679602HYA | WMF128K8-60FFQ5 | 5962-9669005HUC |
| ACT-F128K8N-150P4Q | 5962-9669001HYA | WME128K8-250CQ | 5962-9679602HYC | WMS128K8-70C | 5962-9669104HYA |
| ACT-F128K8N-150P4Q | 5962-9669001HYC | WME128K8-250DEQ | 5962-9679602HXA | WMS128K8-70C | 5962-9669104HYC |
| WE-128K8-150CQ | 5962-9315402HXA | WME128K8-250DEQ | 5962-9679602HXC | WMS128K8-70DE | 5962-9669104HTA |
| WE-128K8-150CQ | 5962-9315402HXC | WME128K8-300CQ | 5962-9679601HYA | WMS128K8-70DE | 5962-9669104HTC |
| WME128K8-150CQ | 5962-9679604HYA | WME128K8-300CQ | 5962-9679601HYC | WMS128K8-70DR | 5962-9669104HUA |
| WME128K8-150CQ | 5962-9679604HYC | WME128K8-300DEQ | 5962-9679601HXA | WMS128K8-70DR | 5962-9669104HUC |
| WME128K8-150DEQ | 5962-9679604HXA | WME128K8-300DEQ | 5962-9679601HXC | WMS128K8-70FE | 5962-9669104HNA |
| WME128K8-150DEQ | 5962-9679604HXC | WMS128K8-35C | 5962-9669107HYA | WMS128K8-70FE | 5962-9669104HNC |
| WMF128K8-150CQ5 | 5962-9669001HYA | WMS128K8-35C | 5962-9669107HYC | WS-128K8-70 (GEN) | 5962-9315604HXA |
| WMF128K8-150CQ5 | 5962-9669001HYC | WMS128K8-35DE | 5962-9669107HTA | WS-128K8-70CQ | 5962-9315604HYA |
| WMF128K8-150DEQ5 | 5962-9669001HXA | WMS128K8-35DE | 5962-9669107HTC | WS-128K8-70CQ | 5962-9315604HYC |
| WMF128K8-150DEQ5 | 5962-9669001HXC | WMS128K8-35DJ | 5962-9669107HZA | WMF128K8-70CQ5 | 5962-9669004HYA |
| WMF128K8-150FEQ5 | 5962-9669001HTA | WMS128K8-35DJ | 5962-9669107HZC | WMF128K8-70CQ5 | 5962-9669004HYC |
| WMF128K8-150FEQ5 | 5962-9669001HTC | WMS128K8-35DR | 5962-9669107HUA | WMF128K8-70DEQ5 | 5962-9669004HXA |
| WMF128K8-150FFQ5 | 5962-9669001HUA | WMS128K8-35DR | 5962-9669107HUC | WMF128K8-70DEQ5 | 5962-9669004HXC |
| WMF128K8-150FFQ5 | 5962-9669001HUC | WMS128K8-35F | 5962-9669107HXC | WMF128K8-70FEQ5 | 5962-9669004HTA |
| WMS128K8-17C | 5962-9669110HYA | WS-128K8-35 (GEN) | 5962-9315607HXA | WMF128K8-70FEQ5 | 5962-9669004HTC |
| WMS128K8-17C | 5962-9669110HYC | WS-128K8-35CQ | 5962-9315607HYA | WMF128K8-70FFQ5 | 5962-9669004HUA |
| WMS128K8-17DE | 5962-9669110HTA | WS-128K8-35CQ | 5962-9315607HYC | WMF128K8-70FFQ5 | 5962-9669004HUC |
| WMS128K8-17DE | 5962-9669110HTC | SD128MX84 | 5962-0251701NXA | SD128MX88 | 5962-0251702NXA |
| WMS128K8-17DJ | 5962-9669110HZA | SD128MX84 | 5962-0251701NXB | SD128MX88 | 5962-0251702NXB |
| WMS128K8-17DJ | 5962-9669110HZC | WMS128K8-45C | 5962-9669106HYA | WMS128K8-85C | 5962-9669103HYA |
| WMS128K8-17DR | 5962-9669110HUA | WMS128K8-45C | 5962-9669106HYC | WMS128K8-85C | 5962-9669103HYC |
| WMS128K8-17DR | 5962-9669110HUC | WMS128K8-45DE | 5962-9669106HTA | WMS128K8-85DE | 5962-9669103HTA |
| WMS128K8-17F | 5962-9669110HXC | WMS128K8-45DE | 5962-9669106HTC | WMS128K8-85DE | 5962-9669103HTC |
| WMS128K8-20C | 5962-9669109HYA | WMS128K8-45DJ | 5962-9669106HZA | WMS128K8-85DR | 5962-9669103HUA |
| WMS128K8-20C | 5962-9669109HYC | WMS128K8-45DJ | 5962-9669106HZC | WMS128K8-85DR | 5962-9669103HUC |
| WMS128K8-20DE | 5962-9669109HTA | WMS128K8-45DR | 5962-9669106HUA | WMS128K8-85FE | 5962-9669103HNA |
| WMS128K8-20DE | 5962-9669109HTC | WMS128K8-45DR | 5962-9669106HUC | WMS128K8-85FE | 5962-9669103HNC |
| WMS128K8-20DJ | 5962-9669109HZA | WMS128K8-45F | 5962-9669106HXC | WS-128K8-85 (GEN) | 5962-9315603HXA |
| WMS128K8-20DJ | 5962-9669109HZC | WS-128K8-45 (GEN) | 5962-9315606HXA | WS-128K8-85CQ | 5962-9315603HYA |
| WMS128K8-20DR | 5962-9669109HUA | WS-128K8-45CQ | 5962-9315606HYA | WS-128K8-85CQ | 5962-9315603HYC |
| WMS128K8-20DR | 5962-9669109HUC | WS-128K8-45CQ | 5962-9315606HYC | WMF128K8-90CQ5 | 5962-9669003HYA |
| WMS128K8-20F | 5962-9669109HXC | WMS128K8-55C | 5962-9669105HYA | WMF128K8-90CQ5 | 5962-9669003HYC |
| WE-128K8-200CQ | 5962-9315401HXA | WMS128K8-55C | 5962-9669105HYC | WMF128K8-90DEQ5 | 5962-9669003HXA |
| WE-128K8-200CQ | 5962-9315401HXC | WMS128K8-55DE | 5962-9669105HTA | WMF128K8-90DEQ5 | 5962-9669003HXC |
| WME128K8-200CQ | 5962-9679603HYA | WMS128K8-55DE | 5962-9669105HTC | WMF128K8-90FEQ5 | 5962-9669003HTA |
| WME128K8-200CQ | 5962-9679603HYC | WMS128K8-55DJ | 5962-9669105HZA | WMF128K8-90FEQ5 | 5962-9669003HTC |
| WME128K8-200DEQ | 5962-9679603HXA | WMS128K8-55DJ | 5962-9669105HZC | WMF128K8-90FFQ5 | 5962-9669003HUA |
| WME128K8-200DEQ | 5962-9679603HXC | WMS128K8-55DR | 5962-9669105HUA | WMF128K8-90FFQ5 | 5962-9669003HUC |
| WMS128K8-25C | 5962-9669108HYA | WMS128K8-55DR | 5962-9669105HUC | DG129A (GEN) | 7801401AA |
| WMS128K8-25C | 5962-9669108HYC | WMS128K8-55F | 5962-9669105HXC | DG129AL/883 | 7801401XA |
| WMS128K8-25DE | 5962-9669108HTA | WS-128K8-55 (GEN) | 5962-9315605HXA | DG129AP/883 | 7801401CA |
| WMS128K8-25DE | 5962-9669108HTC | WS-128K8-55CQ | 5962-9315605HYA | LM129A (GEN) | 5962-8992101XA |
| WMS128K8-25DJ | 5962-9669108HZA | WS-128K8-55CQ | 5962-9315605HYC | LM129B (GEN) | 5962-8992102XA |
| WMS128K8-25DJ | 5962-9669108HZC | WMF128K8-60CQ5 | 5962-9669005HYA | LM129C (GEN) | 5962-8992103XA |
| WMS128K8-25DR | 5962-9669108HUA | WMF128K8-60CQ5 | 5962-9669005HYC | LTC1290B (GEN) | 5962-8983002RA |
| WMS128K8-25DR | 5962-9669108HUC | WMF128K8-60DEQ5 | 5962-9669005HXA | LTC1290C (GEN) | 5962-8983003RA |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

| Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN |
|---|---|---|---|---|---|
| LTC1290D (GEN) | 5962-8983004RA | OM1327NK/883B | 7703408YA | LM136A-2.5 (GEN) | 8418001XA |
| LTC1291C (GEN) | 5962-9305705MPA | OM1327NM/883B | 7703408NA | LM136AH-2.5/883 | 8418003XA |
| LTC1291D (GEN) | 5962-9305709MPA | AD13280BZ/QMLH | 5962-0053001HXA | LM136AH-2.5RQV | 5962R0050101VXA |
| MTL1291MJ8/883 | 5962-9305701MPA | GEM13302B2A | 5962-86723022A | LM136AH-2.5-SMD | 5962-0050101QXA |
| LTC1292B (GEN) | 5962-9305702MPA | GEM13302B2C | 5962-86723022C | LM136AH-5.0/883 | 8418002XA |
| LTC1292C (GEN) | 5962-9305706MPA | GEM13302BRA | 5962-8672302RA | IP137AE | 77034066A |
| LTC1292D (GEN) | 5962-9305710MPA | GEM13302BRC | 5962-8672302RC | IP137AG-DESC | 7703406TA |
| LTC1293B (GEN) | 5962-9305703MEA | TH1332Rabc_MQ | 5962-01B0120Q_C | IP137AH-DESC | 7703406XA |
| LTC1293C (GEN) | 5962-9305707MEA | TH1332RabcDDMQ | 5962-01B0120Q9A | IP137AHVE | 77034086A |
| LTC1293D (GEN) | 5962-9305711MEA | TH1332RHabc*MQ | 5962-01B0104Q*C | IP137AHVG-DESC | 7703408TA |
| LTC1294B (GEN) | 5962-9305704MRA | TH1332RHabcDDMQ | 5962-01B0104Q9A | IP137AHVH-DESC | 7703408XA |
| LTC1294C (GEN) | 5962-9305708MRA | TH1332Sabc_MQ | 5962-01B0124Q_C | IP137AHVIG-DESC | 7703408UA |
| LTC1294D (GEN) | 5962-9305712MRA | TH1332SabcDDMQ | 5962-01B0124Q9A | IP137AHVK-DESC | 7703408YA |
| MOF1305D | 5962-88583012A | TH1332SHabc*MQ | 5962-01B0108Q*C | IP137AHVR-DESC | 7703408ZA |
| MOF1305D (GEN) | 5962-8858301EA | TH1332SHabcDDMQ | 5962-01B0108Q9A | IP137AIG-DESC | 7703406UA |
| MOF1305D (GEN) | 5962-8858301FA | TH1RDabc_MQ | 5962-01B0128Q_C | IP137AK-DESC | 7703406YA |
| LM131A (GEN) | 5962-8760701GA | TH1RDabcDDMQ | 5962-01B0128Q9A | IP137AR-DESC | 7703406ZA |
| HCS132DMSR | 5962R9572601VCC | TH1REHabc_MQ | 5962-01B0112Q_C | IP137E | 77034036A |
| HCS132HMSR | 5962R9572601V9A | TH1REHabcDDMQ | 5962-01B0112Q9A | IP137G-DESC | 7703403TA |
| HCS132KMSR | 5962R9572601VXC | TH1SDabc_MQ | 5962-01B0132Q_C | IP137HVE | 77034046A |
| HCTS132 (GEN) | 5962R9573901V9A | TH1SDabcDDMQ | 5962-01B0132Q9A | IP137HVG-DESC | 7703404TA |
| HCTS132 (GEN) | 5962R9573901VCC | TH1SEHabc_MQ | 5962-01B0116Q_C | IP137HVH-DESC | 7703404XA |
| HCTS132 (GEN) | 5962R9573901VXC | TH1SEHabcDDMQ | 5962-01B0116Q9A | IP137HVIG-DESC | 7703404UA |
| OM1320N2/883B | 77034012A | MSK1339B (GEN) | 5962-9679401HXA | IP137HVK-DESC | 7703404YA |
| OM1320NK/883B | 7703401YA | LM134 (GEN) | 5962-9050701XA | IP137HVR-DESC | 7703404ZA |
| OM1320NM/883B | 7703401NA | GEM13404Q2A | 86051042A | IP137IG-DESC | 7703403UA |
| OM1321N2/883B | 77034022A | GEM13404Q2C | 86051042C | IP137K-DESC | 7703403YA |
| OM1321NH/883B | 7703402XA | GEM13404QEA | 8605104EA | IP137MH-DESC | 7703403XA |
| OM1321NK/883B | 7703402YA | GEM13404QEC | 8605104EC | IP137R-DESC | 7703403ZA |
| OM1321NM/883B | 7703402NA | GEM13404QFA | 8605104FA | LM137 (GEN) | 5962P9951701QXA |
| OMR1321STM/883B | 5962R7703402MUA | GEM13404QFC | 8605104FC | LM137 (GEN) | 5962P9951701QZA |
| OM1322N2/883B | 77034032A | LM134-3 (GEN) | 5962-9050702XA | LM137 (GEN) | 5962P9951701VZA |
| OM1322NK/883B | 7703403YA | MSK1343B | 5962-9682801H2C | LM137 (GEN) | 5962P9951702QYA |
| OM1322NM/883B | 7703403NA | LM134-6 (GEN) | 5962-9050703XA | LM137H/883B | 7703403XA |
| ACS132 (GEN) | 5962F9862501V9A | AD13465 (GEN) | 5962-0150601HXA | LM137HPQMLV | 5962P9951701VXA |
| ACS132 (GEN) | 5962F9862501VCC | MSK1348B | 5962-9459801HXA | LM137HV (GEN) | 5962-7703404VXA |
| ACS132 (GEN) | 5962F9862501VXC | MSK1348B | 5962-9459801HXC | LM137HVH/883 | 7703404XA |
| OM1323N2/883B | 77034042A | GEM13501Q2A | 78015012A | LM137HVK/883 | 7703404YA |
| OM1323NK/883B | 7703404YA | GEM13501Q2C | 78015012C | LM137HVK-QMLV | 5962-7703404VYA |
| OM1323NM/883B | 7703404NA | GEM13501QEA | 7801501EA | LM137K/883B | 7703403YA |
| OM1324N2/883B | 77034052A | GEM13501QEC | 7801501EC | LM137KPQMLV | 5962P9951702VYA |
| OM1324NK/883B | 7703405YA | GEM13501QFA | 7801501FA | LM137WG-QMLV | 5962-9951701VZA |
| OM1324NM/883B | 7703405NA | GEM13501QFC | 7801501FC | OM137AHVNT/883B | 7703408TA |
| OM1325N2/883B | 77034062A | GEM13503Q2A | 78015032A | OM137AHVSM/883B | 7703408MA |
| OM1325NK/883B | 7703406YA | GEM13503Q2C | 78015032C | OM137AHVST/883B | 7703408UA |
| OM1325NM/883B | 7703406NA | GEM13503QEA | 7801503EA | OM137ANT/883B | 7703406TA |
| OM1326N2/883B | 77034072A | GEM13503QEC | 7801503EC | OM137ASM/883B | 7703406MA |
| OM1326NH/883B | 7703407XA | GEM13503QFA | 7801503FA | OM137AST/883B | 7703406UA |
| OM1326NK/883B | 7703407YA | GEM13503QFC | 7801503FC | OM137HVNT/883B | 7703404TA |
| OM1326NM/883B | 7703407NA | 13612-501 | 5962-01A0501QXA | OM137HVSM/883B | 7703404MA |
| OM1326SRM/883B | 77034074A | MSK1362B | 5962-9851401HIA | OM137HVST/883B | 7703404UA |
| OMR1326STM/883B | 5962R7703407MUA | MSK1362B | 5962-9851401HIC | OM137NT/883B | 7703403TA |
| OM1327N2/883B | 77034082A | LM136A-2.5 (GEN) | 5962R0050101QXA | OM137SM/883B | 7703403MA |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART II, Listed By Generic PIN

| Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN |
|---|---|---|---|---|---|
| OM137ST/883B | 7703403UA | ACTS138 (GEN) | 5962F9853501VEC | LM139AJ-SMD | 5962-8773901CA |
| SDP1372MD | 77034032A | ACTS138 (GEN) | 5962F9853501VXC | LM139AWB | 5962-8773901DA |
| SDP137A2MD | 77034062A | HCS138 (GEN) | 5962R9572701TEC | LM139AWGLQMLV | 5962L9673801VXA |
| SDP137AHV2MD | 77034082A | HCS138 (GEN) | 5962R9572701TXC | LM139AWG-QMLV | 5962-9673801VXA |
| SDP137AHVMMD | 7703408MA | HCS138 (GEN) | 5962R9572701V9A | LM139AWGRQMLV | 5962R9673801VXA |
| SDP137AHVNMD | 7703408NA | HCS138DMSR | 5962R9572701VEC | LM139AWG-SMD | 5962-8773901XA |
| SDP137AHVTMD | 7703408TA | HCS138KMSR | 5962R9572701VXC | LM139AWLQMLV | 5962L9673801VDA |
| SDP137AHVUMD | 7703408UA | HCTS138DMSR | 5962R9574001VEC | LM139AW-QMLV | 5962-9673801VDA |
| SDP137AHVXMD | 7703408XA | HCTS138HMSR | 5962R9574001V9A | LM139AWRQMLV | 5962R9673801VDA |
| SDP137AHVYMD | 7703408YA | HCTS138KMSR | 5962R9574001VXC | LM139AW-SMD | 5962-8773901DA |
| SDP137AMMD | 7703406MA | IP138AK-DESC | 5962-8986801QYA | LM139FKB | 77008012A |
| SDP137ANMD | 7703406NA | RHFAC138K01Q | 5962F8762201XC | LM139JB | 7700801CA |
| SDP137ATMD | 7703406TA | RHFAC138K01V | 5962F8762201VXC | LM139JQMLV | 5962-7700801VCA |
| SDP137AUMD | 7703406UA | RHFAC138K02Q | 5962F8762201XA | LM139WB | 7700801DA |
| SDP137AXMD | 7703406XA | RHFAC138K02V | 5962F8762201VXA | PM139AM/QMLR | 5962R8773901VDA |
| SDP137AYMD | 7703406YA | RHFACT138K01Q | 5962F8755403QXC | PM139AM/QMLV | 5962-8773901VDA |
| SDP137HVMMD | 7703404MA | RHFACT138K01V | 5962F8755403VXC | PM139ARC/QMLR | 5962R8773901V2A |
| SDP137HVNHD | 5962-9961204HNA | RHFACT138K02Q | 5962F8755403QXA | PM139ARC/QMLV | 5962-8773901V2A |
| SDP137HVNHG | 5962-9961204HNC | RHFACT138K02V | 5962F8755403VXA | PM139AY/QMLR | 5962R8773901VCA |
| SDP137HVNMD | 7703404NA | AD1385T (GEN) | 5962-9171201HXA | PM139AY/QMLV | 5962-8773901VCA |
| SDP137HVTHD | 5962-9961204HTA | HCS139 (GEN) | 5962R9580401V9A | PM139M/QMLR | 5962R8773902VDA |
| SDP137HVTHG | 5962-9961204HTC | HCS139DMSR | 5962R9580401VEC | PM139RC/QMLR | 5962R8773902V2A |
| SDP137HVTMD | 7703404TA | HCS139KMSR | 5962R9580401VXC | PM139Y/QMLR | 5962R8773902VCA |
| SDP137HVUHD | 5962-9961204HUA | HCTS139 (GEN) | 5962R9575301V9A | RHFAC139K01Q | 5962F8762301XC |
| SDP137HVUHG | 5962-9961204HUC | HCTS139DMSR | 5962R9575301VEC | RHFAC139K01V | 5962F8762301VXC |
| SDP137HVUMD | 7703404UA | HCTS139KMSR | 5962R9575301VXC | RHFAC139K02Q | 5962F8762301XA |
| SDP137HVXMD | 7703404XA | HS0-139BRH-Q | 5962F9861302V9A | RHFAC139K02V | 5962F8762301VXA |
| SDP137HVYMD | 7703404YA | HS0-139RH-Q | 5962F9861301V9A | TLC139MDQ | 5962-9555001NXD |
| SDP137HVZHD | 5962-9961204HZA | HS1-139BRH-8 | 5962F9861302QCC | TLC139MFKB | 5962-87659022A |
| SDP137HVZHG | 5962-9961204HZA | HS1-139BRH-Q | 5962F9861302VCC | TLC139MJB | 5962-8765902CA |
| SDP137MMD | 7703403MA | HS1-139RH-8 | 5962F9861301QCC | ACS139 (GEN) | 5962F9763901V9A |
| SDP137NHD | 5962-9961203HNA | HS1-139RH-Q | 5962F9861301VCC | ACS139 (GEN) | 5962F9763901VEC |
| SDP137NHG | 5962-9961203HNC | HS-139 (GEN) | 5962R9861301TCC | ACS139 (GEN) | 5962F9763901VXC |
| SDP137NMD | 7703403NA | HS-139 (GEN) | 5962R9861301TXC | 13925-001 | 5962-03A0101NXC |
| SDP137THD | 5962-9961203HTA | HS9-139BRH-8 | 5962F9861302QXC | HCS14DMSR | 5962R9568101VCC |
| SDP137THG | 5962-9961203HTC | HS9-139BRH-Q | 5962F9861302VXC | HCS14HMSR | 5962R9568101V9A |
| SDP137TMD | 7703403TA | HS9-139RH-8 | 5962F9861301QXC | HCS14KMSR | 5962R9568101VXC |
| SDP137UHD | 5962-9961203HUA | HS9-139RH-Q | 5962F9861301VXC | HCTS14DMSR | 5962R9571901VCC |
| SDP137UHG | 5962-9961203HUC | IS0-139ASRH-Q | 5962F0151001V9A | HCTS14HMSR | 5962R9571901V9A |
| SDP137UMD | 7703403UA | IS9-139ASRH-8 | 5962F0151001QXC | HCTS14KMSR | 5962R9571901VXC |
| SDP137XMD | 7703403XA | IS9-139ASRH-Q | 5962F0151001VXC | OP-14A (GEN) | 5962-8771401GA |
| SDP137YMD | 7703403YA | LM139 (GEN) | 7700801AA | OP-14A (GEN) | 5962-8771401PA |
| SDP137ZHD | 5962-9961203HZA | LM139A (GEN) | 5962-9471101NXD | OP-14B (GEN) | 5962-8771402GA |
| SDP137ZHG | 5962-9961203HZC | LM139A (GEN) | 5962-9471102NXD | OP-14B (GEN) | 5962-8771402PA |
| SG137AL/883B | 77034062A | LM139A (GEN) | 5962R9673801QCA | LM140 (GEN) | 5962R9955101QXA |
| SG137AT/883B | 7703406XA | LM139A (GEN) | 5962R9673801QDA | LM140 (GEN) | 5962R9955101QYA |
| SG137L/883B | 77034032A | LM139A (GEN) | 5962R9673801QXA | LM140 (GEN) | 5962R9955101VXA |
| SG137T/883B | 7703403XA | LM139AE-SMD | 5962-87739012A | LM140 (GEN) | 5962R9955101VYA |
| 13755-502 | 5962-01A1501NXB | LM139AFKB | 5962-87739012A | TSB14C01 (GEN) | 5962-9677201QXA |
| ACS138 (GEN) | 5962F9853401V9A | LM139AJB | 5962-8773901CA | TSB14C01AMHVB | 5962-9677202QXA |
| ACS138DMSR-03 | 5962F9853401VEC | LM139AJLQMLV | 5962L9673801VCA | 14016B (GEN) | 5962-9064002CA |
| ACS138KMSR-03 | 5962F9853401VXC | LM139AJ-QMLV | 5962-9673801VCA | 14023B (GEN) | 7901302CA |
| ACTS138 (GEN) | 5962F9853501V9A | LM139AJRQMLV | 5962R9673801VCA | 14023B (GEN) | 7901302DA |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

| Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN |
|---|---|---|---|---|---|
| 14035B (GEN) | 8101702EA | XDC14507-628 (GEN) | 5962-9055401YA | SD-14551DX-154 | 5962-9454304HXA |
| 14050-501 | 5962-03A0201NXA | TL1451AMFKB | 5962-9958401Q2A | SD-14551DX-154 | 5962-9454304HXA |
| 14052B (GEN) | 7901503EA | TL1451AMJB | 5962-9958401QEA | SD-14551DX-601 | 5962-9454305HXC |
| AD14060BF/QML-4 | 5962-9750601HXC | 4514B (GEN) | 7703501JA | SD-14551DX-601 | 5962-9454305HXC |
| AD14060LBF/QML-4 | 5962-9750701HXC | 145146 (GEN) | 5962-9464101QRA | SD-14552DX-112 | 5962-9454401HXC |
| AD14060LTF/QML-4 | 5962-9750702HXC | 145152-2 (GEN) | 5962-9231301MXA | SD-14552DX-112 | 5962-9454401HXC |
| AD14060TF/QML-4 | 5962-9750602HXC | SD-14531D1-112 | 5962-9082007HXC | SD-14552DX-114 | 5962-9454403HXC |
| THS1408MPHP | 5962-0051101NXD | SD-14531D1-112 | 5962-9082007HXC | SD-14552DX-114 | 5962-9454403HXC |
| HS-1410RH (GEN) | 5962F9851801VXC | SD-14531D1-114 | 5962-9082006HXC | SD-14552DX-132 | 5962-9454401HXC |
| A14100A-CQ256B | 5962-9552101MYC | SD-14531D1-114 | 5962-9082006HXC | SD-14552DX-132 | 5962-9454401HXC |
| A14100A-PG257B | 5962-9552101MXC | SD-14531D1-142 | 5962-9082007HXA | SD-14552DX-134 | 5962-9454403HXC |
| A14100A-1CQ256B | 5962-9552102MYC | SD-14531D1-142 | 5962-9082007HXA | SD-14552DX-134 | 5962-9454403HXC |
| A14100A-1PG257B | 5962-9552102MXC | SD-14531D1-144 | 5962-9082006HXA | SD-14552DX-142 | 5962-9454401HXA |
| GEM14101Q3A | 86030013A | SD-14531D1-144 | 5962-9082006HXA | SD-14552DX-142 | 5962-9454401HXA |
| GEM14101Q3C | 86030013C | SDC14531-631 (GEN) | 5962-9082002HXA | SD-14552DX-144 | 5962-9454403HXA |
| HS-1412 (GEN) | 5962F9683401VCA | SDC14531-631 (GEN) | 5962-9082002HXC | SD-14552DX-144 | 5962-9454403HXA |
| AD14160 (GEN) | 5962-9800302HXA | SD-14531-115 | 5962-9082001HXC | SD-14552DX-152 | 5962-9454401HXA |
| 14174-501 | 5962-03A0501NXA | SD-14531-115 | 5962-9082001HXC | SD-14552DX-152 | 5962-9454401HXA |
| 1425A (GEN) | 5962-9552001MXC | SD-14531-145 | 5962-9082001HXA | SD-14552DX-154 | 5962-9454403HXA |
| 1425A-1 (GEN) | 5962-9552002MXC | SD-14531-145 | 5962-9082001HXA | SD-14552DX-154 | 5962-9454403HXA |
| A1425A-1CQ132B | 5962-9552002MYC | 14538B (GEN) | 5962-9055702EA | SD-14553DX-112 | 5962-9454501HXC |
| A1425A-CQ132B | 5962-9552001MYC | 14538B (GEN) | 5962R9670201V9A | SD-14553DX-112 | 5962-9454501HXC |
| ACS14 (GEN) | 5962F9862301V9A | CD14538BDMSR | 5962R9670201VEC | SD-14553DX-114 | 5962-9454502HXC |
| ACS14DMSR-03 | 5962F9862301VCC | CD14538BF3A | 5962-9055701EA | SD-14553DX-114 | 5962-9454502HXC |
| ACS14KMSR-03 | 5962F9862301VXC | CD14538BKMSR | 5962R9670201VXC | SD-14553DX-132 | 5962-9454501HXC |
| SG143T/883B | 7800303XA | SD-14550DX-112 | 5962-9454301HXC | SD-14553DX-132 | 5962-9454501HXC |
| SG143Y/883B | 7800303PA | SD-14550DX-112 | 5962-9454301HXC | SD-14553DX-134 | 5962-9454502HXC |
| TL1431MFKB | 5962-9962001Q2A | SD-14550DX-114 | 5962-9454303HXC | SD-14553DX-134 | 5962-9454502HXC |
| TL1431MFKQMLV | 5962-9962001V2A | SD-14550DX-114 | 5962-9454303HXC | SD-14553DX-142 | 5962-9454501HXA |
| TL1431MJGB | 5962-9962001QPA | SD-14550DX-132 | 5962-9454301HXC | SD-14553DX-142 | 5962-9454501HXA |
| TL1431MJGQMLV | 5962-9962001VPA | SD-14550DX-132 | 5962-9454301HXC | SD-14553DX-144 | 5962-9454502HXA |
| HC1437L/883 | 5962-89813013A | SD-14550DX-134 | 5962-9454303HXC | SD-14553DX-144 | 5962-9454502HXA |
| LM144H (GEN) | 7800301GA | SD-14550DX-134 | 5962-9454303HXC | SD-14553DX-152 | 5962-9454501HXA |
| PAL14H4 (GEN) | 81035032A | SD-14550DX-142 | 5962-9454301HXA | SD-14553DX-152 | 5962-9454501HXA |
| PAL14H4 (GEN) | 8103503RA | SD-14550DX-142 | 5962-9454301HXA | SD-14553DX-154 | 5962-9454502HXA |
| PAL14H4 (GEN) | 8103503SA | SD-14551DX-142 | 5962-9454302HXA | SD-14553DX-154 | 5962-9454502HXA |
| PAL14H4A (GEN) | 8103512RA | SD-14550DX-144 | 5962-9454303HXA | SD-14554DX-112 | 5962-9454402HXC |
| PAL14L4 (GEN) | 81035082A | SD-14550DX-144 | 5962-9454303HXA | SD-14554DX-112 | 5962-9454402HXC |
| PAL14L4 (GEN) | 8103508RA | SD-14550DX-152 | 5962-9454301HXA | SD-14554DX-114 | 5962-9454404HXC |
| PAL14L4 (GEN) | 8103508SA | SD-14550DX-152 | 5962-9454301HXA | SD-14554DX-114 | 5962-9454404HXC |
| PAL14L4A (GEN) | 8103516RA | SD-14550DX-154 | 5962-9454303HXA | SD-14554DX-132 | 5962-9454402HXC |
| 14490A (GEN) | 5962-8764601EA | SD-14550DX-154 | 5962-9454303HXA | SD-14554DX-132 | 5962-9454402HXC |
| MSK145B | 5962-8870101ZC | 14551B (GEN) | 5962-8775301EA | SD-14554DX-134 | 5962-9454404HXC |
| SDC14500-635 (GEN) | 5962-9070701HXA | SD-14551DX-112 | 5962-9454302HXC | SD-14554DX-134 | 5962-9454404HXC |
| SDC14500-636 (GEN) | 5962-9070702HXA | SD-14551DX-112 | 5962-9454302HXC | SD-14554DX-142 | 5962-9454402HXA |
| SDC14502-605 (GEN) | 5962-9070703HXA | SD-14551DX-114 | 5962-9454304HXC | SD-14554DX-142 | 5962-9454402HXA |
| SDC14502-606 (GEN) | 5962-9070704HXA | SD-14551DX-132 | 5962-9454302HXC | SD-14554DX-144 | 5962-9454404HXA |
| RDC14505-638C (GEN) | 5962-8768701YA | SD-14551DX-132 | 5962-9454302HXC | SD-14554DX-144 | 5962-9454404HXA |
| RDC14505-639 (GEN) | 5962-8768702XA | SD-14551DX-142 | 5962-9454302HXA | SD-14554DX-152 | 5962-9454402HXA |
| RDC14505-639C (GEN) | 5962-8768702YA | SD-14551DX-144 | 5962-9454304HXA | SD-14554DX-152 | 5962-9454402HXA |
| RDC14505-641 (GEN) | 5962-8768703XA | SD-14551DX-144 | 5962-9454304HXA | SD-14554DX-154 | 5962-9454404HXA |
| RDC14505-641C (GEN) | 5962-8768703YA | SD-14551DX-152 | 5962-9454302HXA | SD-14554DX-154 | 5962-9454404HXA |
| XDC14507-627 (GEN) | 5962-9055402YA | SD-14551DX-152 | 5962-9454302HXA | 14555B (GEN) | 7704702EA |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART II, Listed By Generic PIN

| Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN |
|---|---|---|---|---|---|
| 14555B (GEN) | 7704702FA | SDC14565-602 | 5962-8990809XC | SDC14569-111 | 5962-9055105XC |
| 14560 (GEN) | 5962-8949908YC | SDC14565-602 | 5962-8990809XC | SDC14569-111 | 5962-9055105XC |
| SDC-14560-111 | 5962-8949908XC | SDC14565-602 (GEN) | 5962-8990809ZC | SDC14569-112 | 5962-9055106XC |
| 14560-112 (GEN) | 5962-8949907YC | SDC14565-603 | 5962-8990810XC | SDC14569-112 | 5962-9055106XC |
| SDC-14560-112 | 5962-8949907XC | SDC14565-603 | 5962-8990810XC | SDC14569-114 | 5962-9055107XC |
| 14560-114 (GEN) | 5962-8949901YC | SDC14565-603 (GEN) | 5962-8990810ZC | SDC14569-114 | 5962-9055107XC |
| SDC14560-114 | 5962-8949901XA | SDC14565-616 | 5962-8990803XC | SDC14569-115 | 5962-9055108XC |
| SDC14560-114 | 5962-8949901XC | SDC14565-616 | 5962-8990803XC | SDC14569-115 | 5962-9055108XC |
| SDC14560-114 | 5962-8949901XC | SDC14565-616 (GEN) | 5962-8990803ZC | SDC14569-141 | 5962-9055105XA |
| 14560-115 (GEN) | 5962-8949902YC | SDC14565-618 (GEN) | 5962-8990805XC | SDC14569-141 | 5962-9055105XA |
| SDC14560-115 | 5962-8949902XA | SDC14565-618 (GEN) | 5962-8990805ZC | SDC14569-142 | 5962-9055106XA |
| SDC14560-115 | 5962-8949902XC | SDC14565-621 (GEN) | 5962-8990801ZC | SDC14569-142 | 5962-9055106XA |
| SDC14560-115 | 5962-8949902XC | SDC14565-622 (GEN) | 5962-8990802ZC | SDC14569-144 | 5962-9055107XA |
| 14560-141 (GEN) | 5962-8949908YA | SDC14565-629 (GEN) | 5962-8990801YC | SDC14569-144 | 5962-9055107XA |
| SDC-14560-141 | 5962-8949908XA | SDC14565-630 (GEN) | 5962-8990802YC | SDC14569-145 | 5962-9055108XA |
| 14560-142 (GEN) | 5962-8949907YA | SDC-14566-112 | 5962-8990812XC | SDC14569-145 | 5962-9055108XA |
| SDC-14560-142 | 5962-8949907XA | SDC-14566-112 | 5962-8990812XC | SDC14570-112 | 5962-9204801HXC |
| 14560-144 (GEN) | 5962-8949901YA | SDC-14566-114 | 5962-8990813XC | SDC14570-132 | 5962-9204801HXC |
| SDC14560-144 | 5962-8949901XA | SDC-14566-114 | 5962-8990813XC | SDC14570-142 | 5962-9204801HXA |
| 14560-145 (GEN) | 5962-8949902YA | SDC14566-115 | 5962-8990804XC | SDC14570-152 | 5962-9204801HXA |
| SDC14560-145 | 5962-8949902XA | SDC14566-115 | 5962-8990804XC | SDC14571-112 | 5962-9204802HXC |
| 14560III-605 (GEN) | 5962-8949903YA | SDC-14566-142 | 5962-8990812XA | SDC14571-132 | 5962-9204802HXC |
| 14560III-605 (GEN) | 5962-8949903YC | SDC-14566-142 | 5962-8990812XA | SDC14571-142 | 5962-9204802HXA |
| SDC14560-605 | 5962-8949903XA | SDC-14566-144 | 5962-8990813XA | SDC14571-152 | 5962-9204802HXA |
| SDC14560-605 | 5962-8949903XC | SDC-14566-144 | 5962-8990813XA | SDC14572-112 | 5962-9204901HXC |
| SDC14560-605 | 5962-8949903XC | SDC14566-145 | 5962-8990804XA | SDC14572-132 | 5962-9204901HXC |
| SDC-14561V-115 | 5962-8949802XC | SDC14566-145 | 5962-8990804XA | SDC14572-142 | 5962-9204901HXA |
| SDC-14561V-115 | 5962-8949802XC | SDC14566-608 (GEN) | 5962-8990804ZC | SDC14572-152 | 5962-9204901HXA |
| SDC-14561V-145 | 5962-8949802XA | SDC14566-609 (GEN) | 5962-8990804YC | SDC14573-112 | 5962-9205001HXC |
| SDC-14561V-145 | 5962-8949802XA | SDC14567 (GEN) | 5962-9055101YA | SDC14573-132 | 5962-9205001HXC |
| SDC-14561V-114 | 5962-8949801XC | SDC14567 (GEN) | 5962-9055102YA | SDC14573-142 | 5962-9205001HXA |
| SDC-14561V-114 | 5962-8949801XC | SDC14567 (GEN) | 5962-9055103YA | SDC14573-152 | 5962-9205001HXA |
| SDC-14561V-144 | 5962-8949801XA | SDC14567 (GEN) | 5962-9055104YA | SDC14574-112 | 5962-9204902HXC |
| SDC-14561V-144 | 5962-8949801XA | SDC14567-111 | 5962-9055101XC | SDC14574-132 | 5962-9204902HXC |
| 14561-603 (GEN) | 5962-8949801YA | SDC14567-111 | 5962-9055101XC | SDC14574-142 | 5962-9204902HXA |
| 14561-604 (GEN) | 5962-8949802YA | SDC14567-112 | 5962-9055102XC | SDC14574-152 | 5962-9204902HXA |
| 14562-114 (GEN) | 5962-8949805YA | SDC14567-112 | 5962-9055102XC | SDC14575-112 | 5962-9204803HXC |
| SDC-14562V-114 | 5962-8949805XC | SDC14567-114 | 5962-9055103XC | SDC14575-114 | 5962-9204805HXC |
| SDC-14562V-114 | 5962-8949805XC | SDC14567-114 | 5962-9055103XC | SDC14575-132 | 5962-9204803HXC |
| SDC-14562V-144 | 5962-8949805XA | SDC14567-115 | 5962-9055104XC | SDC14575-134 | 5962-9204805HXC |
| SDC-14562V-144 | 5962-8949805XA | SDC14567-115 | 5962-9055104XC | SDC14575-142 | 5962-9204803HXA |
| SDC-14565-112 | 5962-8990811XC | SDC14567-141 | 5962-9055101XA | SDC14575-144 | 5962-9204805HXA |
| SDC-14565-112 | 5962-8990811XC | SDC14567-141 | 5962-9055101XA | SDC14575-152 | 5962-9204803HXA |
| SDC14565-114 | 5962-8990801XC | SDC14567-142 | 5962-9055102XA | SDC14575-154 | 5962-9204805HXA |
| SDC14565-114 | 5962-8990801XC | SDC14567-142 | 5962-9055102XA | SDC14576-112 | 5962-9204804HXC |
| SDC14565-115 | 5962-8990802XC | SDC14567-144 | 5962-9055103XA | SDC14576-114 | 5962-9204806HXC |
| SDC14565-115 | 5962-8990802XC | SDC14567-144 | 5962-9055103XA | SDC14576-132 | 5962-9204804HXC |
| SDC-14565-142 | 5962-8990811XA | SDC14567-145 | 5962-9055104XA | SDC14576-134 | 5962-9204806HXC |
| SDC-14565-142 | 5962-8990811XA | SDC14567-145 | 5962-9055104XA | SDC14576-142 | 5962-9204804HXA |
| SDC14565-144 | 5962-8990801XA | SDC14569 (GEN) | 5962-9055105YA | SDC14576-144 | 5962-9204806HXA |
| SDC14565-144 | 5962-8990801XA | SDC14569 (GEN) | 5962-9055106YA | SDC14576-152 | 5962-9204804HXA |
| SDC14565-145 | 5962-8990802XA | SDC14569 (GEN) | 5962-9055107YA | SDC14576-154 | 5962-9204806HXA |
| SDC14565-145 | 5962-8990802XA | SDC14569 (GEN) | 5962-9055108YA | SDC14577-112 | 5962-9204903HXC |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART II, Listed By Generic PIN

| Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN |
|---|---|---|---|---|---|
| SDC14577-114 | 5962-9204905HXC | SD-14591D1-144 | 5962-9673504HXA | RD-14592F1-115 | 5962-9673507HYC |
| SDC14577-132 | 5962-9204903HXC | SD-14591F1-144 | 5962-9673504HYA | RD-14592F1-115 | 5962-9673507HYC |
| SDC14577-134 | 5962-9204905HXC | SD-14591F1-144 | 5962-9673504HYA | SD-14592D1-115 | 5962-9673510HXC |
| SDC14577-142 | 5962-9204903HXA | SD-14591D2-112 | 5962-9684401HXC | SD-14592D1-115 | 5962-9673510HXC |
| SDC14577-144 | 5962-9204905HXA | SD-14591D2-112 | 5962-9684401HXC | SD-14592F1-115 | 5962-9673510HYC |
| SDC14577-152 | 5962-9204903HXA | SD-14591F2-112 | 5962-9684401HYC | SD-14592F1-115 | 5962-9673510HYC |
| SDC14577-154 | 5962-9204905HXA | SD-14591F2-112 | 5962-9684401HYC | RD-14592D1-142 | 5962-9673505HXA |
| SDC14578-112 | 5962-9205002HXC | SD-14591D2-114 | 5962-9684402HXC | RD-14592D1-142 | 5962-9673505HXA |
| SDC14578-114 | 5962-9205003HXC | SD-14591D2-114 | 5962-9684402HXC | RD-14592F1-142 | 5962-9673505HYA |
| SDC14578-132 | 5962-9205002HXC | SD-14591F2-114 | 5962-9684402HYC | RD-14592F1-142 | 5962-9673505HYA |
| SDC14578-134 | 5962-9205003HXC | SD-14591F2-114 | 5962-9684402HYC | SD-14592D1-142 | 5962-9673508HXA |
| SDC14578-142 | 5962-9205002HXA | SD-14591D2-142 | 5962-9684401HXA | SD-14592D1-142 | 5962-9673508HXA |
| SDC14578-144 | 5962-9205003HXA | SD-14591D2-142 | 5962-9684401HXA | SD-14592F1-142 | 5962-9673508HYA |
| SDC14578-152 | 5962-9205002HXA | SD-14591F2-142 | 5962-9684401HYA | SD-14592F1-142 | 5962-9673508HYA |
| SDC14578-154 | 5962-9205003HXA | SD-14591F2-142 | 5962-9684401HYA | RD-14592D1-144 | 5962-9673506HXA |
| SDC14579-112 | 5962-9204904HXC | SD-14591D2-144 | 5962-9684402HXA | RD-14592D1-144 | 5962-9673506HXA |
| SDC14579-114 | 5962-9204906HXC | SD-14591D2-144 | 5962-9684402HXA | RD-14592F1-144 | 5962-9673506HYA |
| SDC14579-132 | 5962-9204904HXC | SD-14591F2-144 | 5962-9684402HYA | RD-14592F1-144 | 5962-9673506HYA |
| SDC14579-134 | 5962-9204906HXC | SD-14591F2-144 | 5962-9684402HYA | SD-14592D1-144 | 5962-9673509HXA |
| SDC14579-142 | 5962-9204904HXA | SD-14591D3-112 | 5962-9684403HXC | SD-14592D1-144 | 5962-9673509HXA |
| SDC14579-144 | 5962-9204906HXA | SD-14591D3-112 | 5962-9684403HXC | SD-14592F1-144 | 5962-9673509HYA |
| SDC14579-152 | 5962-9204904HXA | SD-14591F3-112 | 5962-9684403HYC | SD-14592F1-144 | 5962-9673509HYA |
| SDC14579-154 | 5962-9204906HXA | SD-14591F3-112 | 5962-9684403HYC | RD-14592D1-145 | 5962-9673507HXA |
| 14584B (GEN) | 5962-8550102CA | SD-14591D3-114 | 5962-9684404HXC | RD-14592D1-145 | 5962-9673507HXA |
| RD-14591D1-112 | 5962-9673501HXC | SD-14591D3-114 | 5962-9684404HXC | RD-14592F1-145 | 5962-9673507HYA |
| RD-14591D1-112 | 5962-9673501HXC | SD-14591F3-114 | 5962-9684404HYC | RD-14592F1-145 | 5962-9673507HYA |
| RD-14591F1-112 | 5962-9673501HYC | SD-14591F3-114 | 5962-9684404HYC | SD-14592D1-145 | 5962-9673510HXA |
| RD-14591F1-112 | 5962-9673501HYC | SD-14591D3-142 | 5962-9684403HXA | SD-14592D1-145 | 5962-9673510HXA |
| SD-14591D1-112 | 5962-9673503HXC | SD-14591D3-142 | 5962-9684403HXA | SD-14592F1-145 | 5962-9673510HYA |
| SD-14591D1-112 | 5962-9673503HXC | SD-14591F3-142 | 5962-9684403HYA | SD-14592F1-145 | 5962-9673510HYA |
| SD-14591F1-112 | 5962-9673503HYC | SD-14591F3-142 | 5962-9684403HYA | SD-14592D2-112 | 5962-9684405HXC |
| SD-14591F1-112 | 5962-9673503HYC | SD-14591D3-144 | 5962-9684404HXA | SD-14592D2-112 | 5962-9684405HXC |
| RD-14591D1-114 | 5962-9673502HXC | SD-14591D3-144 | 5962-9684404HXA | SD-14592F2-112 | 5962-9684405HYC |
| RD-14591D1-114 | 5962-9673502HXC | SD-14591F3-144 | 5962-9684404HYA | SD-14592F2-112 | 5962-9684405HYC |
| RD-14591F1-114 | 5962-9673502HYC | SD-14591F3-144 | 5962-9684404HYA | SD-14592D2-114 | 5962-9684406HXC |
| RD-14591F1-114 | 5962-9673502HYC | RD-14592D1-112 | 5962-9673505HXC | SD-14592D2-114 | 5962-9684406HXC |
| SD-14591D1-114 | 5962-9673504HXC | RD-14592D1-112 | 5962-9673505HXC | SD-14592F2-114 | 5962-9684406HYC |
| SD-14591D1-114 | 5962-9673504HXC | RD-14592F1-112 | 5962-9673505HYC | SD-14592F2-114 | 5962-9684406HYC |
| SD-14591F1-114 | 5962-9673504HYC | RD-14592F1-112 | 5962-9673505HYC | SD-14592D2-115 | 5962-9684407HXC |
| SD-14591F1-114 | 5962-9673504HYC | SD-14592D1-112 | 5962-9673508HXC | SD-14592D2-115 | 5962-9684407HXC |
| RD-14591D1-142 | 5962-9673501HXA | SD-14592D1-112 | 5962-9673508HXC | SD-14592F2-115 | 5962-9684407HYC |
| RD-14591D1-142 | 5962-9673501HXA | SD-14592F1-112 | 5962-9673508HYC | SD-14592F2-115 | 5962-9684407HYC |
| RD-14591F1-142 | 5962-9673501HYA | SD-14592F1-112 | 5962-9673508HYC | SD-14592D2-142 | 5962-9684405HXA |
| RD-14591F1-142 | 5962-9673501HYA | RD-14592D1-114 | 5962-9673506HXC | SD-14592D2-142 | 5962-9684405HXA |
| SD-14591D1-142 | 5962-9673503HXA | RD-14592D1-114 | 5962-9673506HXC | SD-14592F2-142 | 5962-9684405HYA |
| SD-14591D1-142 | 5962-9673503HXA | RD-14592F1-114 | 5962-9673506HYC | SD-14592F2-142 | 5962-9684405HYA |
| SD-14591F1-142 | 5962-9673503HYA | RD-14592F1-114 | 5962-9673506HYC | SD-14592D2-144 | 5962-9684406HXA |
| SD-14591F1-142 | 5962-9673503HYA | SD-14592D1-114 | 5962-9673509HXC | SD-14592D2-144 | 5962-9684406HXA |
| RD-14591D1-144 | 5962-9673502HXA | SD-14592D1-114 | 5962-9673509HXC | SD-14592F2-144 | 5962-9684406HYA |
| RD-14591D1-144 | 5962-9673502HXA | SD-14592F1-114 | 5962-9673509HYC | SD-14592F2-144 | 5962-9684406HYA |
| RD-14591F1-144 | 5962-9673502HYA | SD-14592F1-114 | 5962-9673509HYC | SD-14592D2-145 | 5962-9684407HXA |
| RD-14591F1-144 | 5962-9673502HYA | RD-14592D1-115 | 5962-9673507HXC | SD-14592D2-145 | 5962-9684407HXA |
| SD-14591D1-144 | 5962-9673504HXA | RD-14592D1-115 | 5962-9673507HXC | SD-14592F2-145 | 5962-9684407HYA |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART II, Listed By Generic PIN

| Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN |
|---|---|---|---|---|---|
| SD-14592F2-145 | 5962-9684407HYA | SDC14602-112 | 5962-9205101HXC | SDC14605T-112 | 5962-9173606HXA |
| SD-14592D3-112 | 5962-9684408HXC | SDC14602-112 | 5962-9205101HXC | SDC14605T-112 | 5962-9173606HXC |
| SD-14592D3-112 | 5962-9684408HXC | SDC14602T-112 | 5962-9205102HXC | SDC14605T-112 | 5962-9173606HXC |
| SD-14592F3-112 | 5962-9684408HYC | SDC14602T-112 | 5962-9205102HXC | SDC14605-114 | 5962-9173609HXA |
| SD-14592F3-112 | 5962-9684408HYC | SDC14602-132 | 5962-9205101HXC | SDC14605-114 | 5962-9173609HXA |
| SD-14592D3-114 | 5962-9684409HXC | SDC14602-132 | 5962-9205101HXC | SDC14605-114 | 5962-9173609HXC |
| SD-14592D3-114 | 5962-9684409HXC | SDC14602T-132 | 5962-9205102HXC | SDC14605-114 | 5962-9173609HXC |
| SD-14592F3-114 | 5962-9684409HYC | SDC14602T-132 | 5962-9205102HXC | SDC14605T-114 | 5962-9173610HXA |
| SD-14592F3-114 | 5962-9684409HYC | SDC14602-142 | 5962-9205101HXA | SDC14605T-114 | 5962-9173610HXA |
| SD-14592D3-115 | 5962-9684410HXC | SDC14602-142 | 5962-9205101HXA | SDC14605T-114 | 5962-9173610HXC |
| SD-14592D3-115 | 5962-9684410HXC | SDC14602T-142 | 5962-9205102HXA | SDC14605T-114 | 5962-9173610HXC |
| SD-14592F3-115 | 5962-9684410HYC | SDC14602T-142 | 5962-9205102HXA | SDC14606-112 | 5962-9173607HXA |
| SD-14592F3-115 | 5962-9684410HYC | SDC14602-152 | 5962-9205101HXA | SDC14606-112 | 5962-9173607HXA |
| SD-14592D3-142 | 5962-9684408HXA | SDC14602-152 | 5962-9205101HXA | SDC14606-112 | 5962-9173607HXC |
| SD-14592D3-142 | 5962-9684408HXA | SDC14602T-152 | 5962-9205102HXA | SDC14606-112 | 5962-9173607HXC |
| SD-14592F3-142 | 5962-9684408HYA | SDC14602T-152 | 5962-9205102HXA | SDC14606T-112 | 5962-9173608HXA |
| SD1-4592F3-142 | 5962-9684408HYA | SDC14603-112 | 5962-9205201HXC | SDC14606T-112 | 5962-9173608HXA |
| SD-14592D3-144 | 5962-9684409HXA | SDC14603-112 | 5962-9205201HXC | SDC14606T-112 | 5962-9173608HXC |
| SD-14592D3-144 | 5962-9684409HXA | SDC14603T-112 | 5962-9205202HXC | SDC14606T-112 | 5962-9173608HXC |
| SD-14592F3-144 | 5962-9684409HYA | SDC14603T-112 | 5962-9205202HXC | SDC14606-114 | 5962-9173611HXA |
| SD-14592F3-144 | 5962-9684409HYA | SDC14603-132 | 5962-9205201HXC | SDC14606-114 | 5962-9173611HXA |
| SD-14592D3-145 | 5962-9684410HXA | SDC14603-132 | 5962-9205201HXC | SDC14606-114 | 5962-9173611HXC |
| SD-14592D3-145 | 5962-9684410HXA | SDC14603T-132 | 5962-9205202HXC | SDC14606-114 | 5962-9173611HXC |
| SD-14592F3-145 | 5962-9684410HYA | SDC14603T-132 | 5962-9205202HXC | SDC14606T-114 | 5962-9173612HXA |
| SD-14592F3-145 | 5962-9684410HYA | SDC14603-142 | 5962-9205201HXA | SDC14606T-114 | 5962-9173612HXA |
| MSK146B | 5962-8870101YA | SDC14603-142 | 5962-9205201HXA | SDC14606T-114 | 5962-9173612HXC |
| MSK146B | 5962-8870101YC | SDC14603T-142 | 5962-9205202HXA | SDC14606T-114 | 5962-9173612HXC |
| SDC14600-112 | 5962-9173601HXA | SDC14603T-142 | 5962-9205202HXA | SDC14607-112 | 5962-9205105HXC |
| SDC14600-112 | 5962-9173601HXA | SDC14603-152 | 5962-9205201HXA | SDC14607-112 | 5962-9205105HXC |
| SDC14600-112 | 5962-9173601HXC | SDC14603-152 | 5962-9205201HXA | SDC14607T-112 | 5962-9205106HXC |
| SDC14600-112 | 5962-9173601HXC | SDC14603T-152 | 5962-9205202HXA | SDC14607T-112 | 5962-9205106HXC |
| SDC14600T-112 | 5962-9173602HXA | SDC14603T-152 | 5962-9205202HXA | SDC14607-114 | 5962-9205109HXC |
| SDC14600T-112 | 5962-9173602HXA | SDC14604-112 | 5962-9205103HXC | SDC14607-114 | 5962-9205109HXC |
| SDC14600T-112 | 5962-9173602HXC | SDC14604-112 | 5962-9205103HXC | SDC14607T-114 | 5962-9205110HXC |
| SDC14600T-112 | 5962-9173602HXC | SDC14604T-112 | 5962-9205104HXC | SDC14607T-114 | 5962-9205110HXC |
| SDC14601-112 | 5962-9173603HXA | SDC14604T-112 | 5962-9205104HXC | SDC14607-132 | 5962-9205105HXC |
| SDC14601-112 | 5962-9173603HXA | SDC14604-132 | 5962-9205103HXC | SDC14607-132 | 5962-9205105HXC |
| SDC14601-112 | 5962-9173603HXC | SDC14604-132 | 5962-9205103HXC | SDC14607T-132 | 5962-9205106HXC |
| SDC14601-112 | 5962-9173603HXC | SDC14604T-132 | 5962-9205104HXC | SDC14607T-132 | 5962-9205106HXC |
| SDC14601T-112 | 5962-9173604HXA | SDC14604T-132 | 5962-9205104HXC | SDC14607-134 | 5962-9205109HXC |
| SDC14601T-112 | 5962-9173604HXA | SDC14604-142 | 5962-9205103HXA | SDC14607-134 | 5962-9205109HXC |
| SDC14601T-112 | 5962-9173604HXC | SDC14604-142 | 5962-9205103HXA | SDC14607T-134 | 5962-9205110HXC |
| SDC14601T-112 | 5962-9173604HXC | SDC14604T-142 | 5962-9205104HXA | SDC14607T-134 | 5962-9205110HXC |
| A1460A-1CQ196B | 5962-9550802MYC | SDC14604T-142 | 5962-9205104HXA | SDC14607-142 | 5962-9205105HXA |
| A1460A-1PG207B | 5962-9550802MXA | SDC14604-152 | 5962-9205103HXA | SDC14607-142 | 5962-9205105HXA |
| A1460A-1PG207B | 5962-9550802MXC | SDC14604-152 | 5962-9205103HXA | SDC14607T-142 | 5962-9205106HXA |
| SDC14601-603 | 5962-9173613HXA | SDC14604T-152 | 5962-9205104HXA | SDC14607T-142 | 5962-9205106HXA |
| SDC14601-603 | 5962-9173613HXA | SDC14604T-152 | 5962-9205104HXA | SDC14607-144 | 5962-9205109HXA |
| SDC14601-603 | 5962-9173613HXC | SDC14605-112 | 5962-9173605HXA | SDC14607-144 | 5962-9205109HXA |
| SDC14601-603 | 5962-9173613HXC | SDC14605-112 | 5962-9173605HXA | SDC14607T-144 | 5962-9205110HXA |
| A1460A-CQ196B | 5962-9550801MYC | SDC14605-112 | 5962-9173605HXC | SDC14607T-144 | 5962-9205110HXA |
| A1460A-PG207B | 5962-9550801MXA | SDC14605-112 | 5962-9173605HXC | SDC14607-152 | 5962-9205105HXA |
| A1460A-PG207B | 5962-9550801MXC | SDC14605T-112 | 5962-9173606HXA | SDC14607-152 | 5962-9205105HXA |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART II, Listed By Generic PIN

| Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN |
|---|---|---|---|---|---|
| SDC14607T-152 | 5962-9205106HXA | SDC14609T-134 | 5962-9205112HXC | SDC-14612IIT-112 | 5962-9205402HXC |
| SDC14607T-152 | 5962-9205106HXA | SDC14609-142 | 5962-9205107HXA | SDC-14612IIT-112 | 5962-9205402HXC |
| SDC14607-154 | 5962-9205109HXA | SDC14609-142 | 5962-9205107HXA | SDC-14612II-132 | 5962-9205401HXC |
| SDC14607-154 | 5962-9205109HXA | SDC14609T-142 | 5962-9205108HXA | SDC-14612II-132 | 5962-9205401HXC |
| SDC14607T-154 | 5962-9205110HXA | SDC14609T-142 | 5962-9205108HXA | SDC-14612IIT-132 | 5962-9205402HXC |
| SDC14607T-154 | 5962-9205110HXA | SDC14609-144 | 5962-9205111HXA | SDC-14612IIT-132 | 5962-9205402HXC |
| SDC14608-112 | 5962-9205203HXC | SDC14609-144 | 5962-9205111HXA | SDC-14612II-142 | 5962-9205401HXA |
| SDC14608-112 | 5962-9205203HXC | SDC14609T-144 | 5962-9205112HXA | SDC-14612II-142 | 5962-9205401HXA |
| SDC14608T-112 | 5962-9205204HXC | SDC14609T-144 | 5962-9205112HXA | SDC-14612IIT-142 | 5962-9205402HXA |
| SDC14608T-112 | 5962-9205204HXC | SDC14609-152 | 5962-9205107HXA | SDC-14612IIT-142 | 5962-9205402HXA |
| SDC14608-114 | 5962-9205205HXC | SDC14609-152 | 5962-9205107HXA | SDC-14612II-152 | 5962-9205401HXA |
| SDC14608-114 | 5962-9205205HXC | SDC14609T-152 | 5962-9205108HXA | SDC-14612II-152 | 5962-9205401HXA |
| SDC14608T-114 | 5962-9205206HXC | SDC14609T-152 | 5962-9205108HXA | SDC-14612IIT-152 | 5962-9205402HXA |
| SDC14608T-114 | 5962-9205206HXC | SDC14609-154 | 5962-9205111HXA | SDC-14612IIT-152 | 5962-9205402HXA |
| SDC14608-132 | 5962-9205203HXC | SDC14609-154 | 5962-9205111HXA | SDC-14613II-112 | 5962-9205501HXC |
| SDC14608-132 | 5962-9205203HXC | SDC14609T-154 | 5962-9205112HXA | SDC-14613II-112 | 5962-9205501HXC |
| SDC14608T-132 | 5962-9205204HXC | SDC14609T-154 | 5962-9205112HXA | SDC-14613IIT-112 | 5962-9205502HXC |
| SDC14608T-132 | 5962-9205204HXC | MSK1461B | 5962-9050001HXA | SDC-14613IIT-112 | 5962-9205502HXC |
| SDC14608-134 | 5962-9205205HXC | MSK1461B | 5962-9050001HXC | SDC-14613II-132 | 5962-9205501HXC |
| SDC14608-134 | 5962-9205205HXC | SDC-14610II-112 | 5962-9205301HXC | SDC-14613II-132 | 5962-9205501HXC |
| SDC14608T-134 | 5962-9205206HXC | SDC-14610II-112 | 5962-9205301HXC | SDC-14613IIT-132 | 5962-9205502HXC |
| SDC14608T-134 | 5962-9205206HXC | SDC-14610IIT-112 | 5962-9205302HXC | SDC-14613IIT-132 | 5962-9205502HXC |
| SDC14608-142 | 5962-9205203HXA | SDC-14610IIT-112 | 5962-9205302HXC | SDC-14613II-142 | 5962-9205501HXA |
| SDC14608-142 | 5962-9205203HXA | SDC-14610II-132 | 5962-9205301HXC | SDC-14613II-142 | 5962-9205501HXA |
| SDC14608T-142 | 5962-9205204HXA | SDC-14610II-132 | 5962-9205301HXC | SDC-14613IIT-142 | 5962-9205502HXA |
| SDC14608T-142 | 5962-9205204HXA | SDC-14610IIT-132 | 5962-9205302HXC | SDC-14613IIT-142 | 5962-9205502HXA |
| SDC14608-144 | 5962-9205205HXA | SDC-14610IIT-132 | 5962-9205302HXC | SDC-14613II-152 | 5962-9205501HXA |
| SDC14608-144 | 5962-9205205HXA | SDC-14610II-142 | 5962-9205301HXA | SDC-14613II-152 | 5962-9205501HXA |
| SDC14608T-144 | 5962-9205206HXA | SDC-14610II-142 | 5962-9205301HXA | SDC-14613IIT-152 | 5962-9205502HXA |
| SDC14608T-144 | 5962-9205206HXA | SDC-14610IIT-142 | 5962-9205302HXA | SDC-14613IIT-152 | 5962-9205502HXA |
| SDC14608-152 | 5962-9205203HXA | SDC-14610IIT-142 | 5962-9205302HXA | SDC-14614II-112 | 5962-9205403HXC |
| SDC14608-152 | 5962-9205203HXA | SDC-14610II-152 | 5962-9205301HXA | SDC-14614II-112 | 5962-9205403HXC |
| SDC14608T-152 | 5962-9205204HXA | SDC-14610II-152 | 5962-9205301HXA | SDC-14614IIT-112 | 5962-9205404HXC |
| SDC14608T-152 | 5962-9205204HXA | SDC-14610IIT-152 | 5962-9205302HXA | SDC-14614IIT-112 | 5962-9205404HXC |
| SDC14608-154 | 5962-9205205HXA | SDC-14610IIT-152 | 5962-9205302HXA | SDC-14614II-132 | 5962-9205403HXC |
| SDC14608-154 | 5962-9205205HXA | SDC-14611II-112 | 5962-9205303HXC | SDC-14614II-132 | 5962-9205403HXC |
| SDC14608T-154 | 5962-9205206HXA | SDC-14611II-112 | 5962-9205303HXC | SDC-14614IIT-132 | 5962-9205404HXC |
| SDC14608T-154 | 5962-9205206HXA | SDC-14611IIT-112 | 5962-9205304HXC | SDC-14614IIT-132 | 5962-9205404HXC |
| SDC14609-112 | 5962-9205107HXC | SDC-14611IIT-112 | 5962-9205304HXC | SDC-14614II-142 | 5962-9205403HXA |
| SDC14609-112 | 5962-9205107HXC | SDC-14611II-132 | 5962-9205303HXC | SDC-14614II-142 | 5962-9205403HXA |
| SDC14609T-112 | 5962-9205108HXC | SDC-14611II-132 | 5962-9205303HXC | SDC-14614IIT-142 | 5962-9205404HXA |
| SDC14609T-112 | 5962-9205108HXC | SDC-14611IIT-132 | 5962-9205304HXC | SDC-14614IIT-142 | 5962-9205404HXA |
| SDC14609-114 | 5962-9205111HXC | SDC-14611IIT-132 | 5962-9205304HXC | SDC-14614II-152 | 5962-9205403HXA |
| SDC14609-114 | 5962-9205111HXC | SDC-14611II-142 | 5962-9205303HXA | SDC-14614II-152 | 5962-9205403HXA |
| SDC14609T-114 | 5962-9205112HXC | SDC-14611II-142 | 5962-9205303HXA | SDC-14614IIT-152 | 5962-9205404HXA |
| SDC14609T-114 | 5962-9205112HXC | SDC-14611IIT-142 | 5962-9205304HXA | SDC-14614IIT-152 | 5962-9205404HXA |
| SDC14609-132 | 5962-9205107HXC | SDC-14611IIT-142 | 5962-9205304HXA | SDC-14615II-112 | 5962-9205305HXC |
| SDC14609-132 | 5962-9205107HXC | SDC-14611II-152 | 5962-9205303HXA | SDC-14615II-112 | 5962-9205305HXC |
| SDC14609T-132 | 5962-9205108HXC | SDC-14611II-152 | 5962-9205303HXA | SDC-14615IIT-112 | 5962-9205306HXC |
| SDC14609T-132 | 5962-9205108HXC | SDC-14611IIT-152 | 5962-9205304HXA | SDC-14615IIT-112 | 5962-9205306HXC |
| SDC14609-134 | 5962-9205111HXC | SDC-14611IIT-152 | 5962-9205304HXA | SDC-14615II-114 | 5962-9205309HXC |
| SDC14609-134 | 5962-9205111HXC | SDC-14612II-112 | 5962-9205401HXC | SDC-14615II-114 | 5962-9205309HXC |
| SDC14609T-134 | 5962-9205112HXC | SDC-14612II-112 | 5962-9205401HXC | SDC-14615IIT-114 | 5962-9205310HXC |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART II, Listed By Generic PIN

| Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN |
|---|---|---|---|---|---|
| SDC-14615IIT-114 | 5962-9205310HXC | SDC-14616II-154 | 5962-9205311HXA | SDC-14618II-142 | 5962-9205503HXA |
| SDC-14615II-132 | 5962-9205305HXC | SDC-14616II-154 | 5962-9205311HXA | SDC-14618IIT-142 | 5962-9205504HXA |
| SDC-14615II-132 | 5962-9205305HXC | SDC-14616IIT-154 | 5962-9205312HXA | SDC-14618IIT-142 | 5962-9205504HXA |
| SDC-14615IIT-132 | 5962-9205306HXC | SDC-14616IIT-154 | 5962-9205312HXA | SDC-14618II-144 | 5962-9205505HXA |
| SDC-14615IIT-132 | 5962-9205306HXC | SDC-14617II-112 | 5962-9205405HXC | SDC-14618II-144 | 5962-9205505HXA |
| SDC-14615II-134 | 5962-9205309HXC | SDC-14617II-112 | 5962-9205405HXC | SDC-14618IIT-144 | 5962-9205506HXA |
| SDC-14615II-134 | 5962-9205309HXC | SDC-14617IIT-112 | 5962-9205406HXC | SDC-14618IIT-144 | 5962-9205506HXA |
| SDC-14615IIT-134 | 5962-9205310HXC | SDC-14617IIT-112 | 5962-9205406HXC | SDC-14618II-152 | 5962-9205503HXA |
| SDC-14615IIT-134 | 5962-9205310HXC | SDC-14617II-114 | 5962-9205409HXC | SDC-14618II-152 | 5962-9205503HXA |
| SDC-14615II-142 | 5962-9205305HXA | SDC-14617II-114 | 5962-9205409HXC | SDC-14618IIT-152 | 5962-9205504HXA |
| SDC-14615II-142 | 5962-9205305HXA | SDC-14617IIT-114 | 5962-9205410HXC | SDC-14618IIT-152 | 5962-9205504HXA |
| SDC-14615IIT-142 | 5962-9205306HXA | SDC-14617IIT-114 | 5962-9205410HXC | SDC-14618II-154 | 5962-9205505HXA |
| SDC-14615IIT-142 | 5962-9205306HXA | SDC-14617II-132 | 5962-9205405HXC | SDC-14618II-154 | 5962-9205505HXA |
| SDC-14615II-144 | 5962-9205309HXA | SDC-14617II-132 | 5962-9205405HXC | SDC-14618IIT-154 | 5962-9205506HXA |
| SDC-14615II-144 | 5962-9205309HXA | SDC-14617IIT-132 | 5962-9205406HXC | SDC-14618IIT-154 | 5962-9205506HXA |
| SDC-14615IIT-144 | 5962-9205310HXA | SDC-14617IIT-132 | 5962-9205406HXC | SDC-14619II-112 | 5962-9205407HXC |
| SDC-14615IIT-144 | 5962-9205310HXA | SDC-14617II-134 | 5962-9205409HXC | SDC-14619II-112 | 5962-9205407HXC |
| SDC-14615II-152 | 5962-9205305HXA | SDC-14617II-134 | 5962-9205409HXC | SDC-14619IIT-112 | 5962-9205408HXC |
| SDC-14615II-152 | 5962-9205305HXA | SDC-14617IIT-134 | 5962-9205410HXC | SDC-14619IIT-112 | 5962-9205408HXC |
| SDC-14615IIT-152 | 5962-9205306HXA | SDC-14617IIT-134 | 5962-9205410HXC | SDC-14619II-114 | 5962-9205411HXC |
| SDC-14615IIT-152 | 5962-9205306HXA | SDC-14617II-142 | 5962-9205405HXA | SDC-14619II-114 | 5962-9205411HXC |
| SDC-14615II-154 | 5962-9205309HXA | SDC-14617II-142 | 5962-9205405HXA | SDC-14619IIT-114 | 5962-9205412HXC |
| SDC-14615II-154 | 5962-9205309HXA | SDC-14617IIT-142 | 5962-9205406HXA | SDC-14619IIT-114 | 5962-9205412HXC |
| SDC-14615IIT-154 | 5962-9205310HXA | SDC-14617IIT-142 | 5962-9205406HXA | SDC-14619II-132 | 5962-9205407HXC |
| SDC-14615IIT-154 | 5962-9205310HXA | SDC-14617II-144 | 5962-9205409HXA | SDC-14619II-132 | 5962-9205407HXC |
| SDC-14616II-112 | 5962-9205307HXC | SDC-14617II-144 | 5962-9205409HXA | SDC-14619IIT-132 | 5962-9205408HXC |
| SDC-14616II-112 | 5962-9205307HXC | SDC-14617IIT-144 | 5962-9205410HXA | SDC-14619IIT-132 | 5962-9205408HXC |
| SDC-14616IIT-112 | 5962-9205308HXC | SDC-14617IIT-144 | 5962-9205410HXA | SDC-14619II-134 | 5962-9205411HXC |
| SDC-14616IIT-112 | 5962-9205308HXC | SDC-14617II-152 | 5962-9205405HXA | SDC-14619II-134 | 5962-9205411HXC |
| SDC-14616II-114 | 5962-9205311HXC | SDC-14617II-152 | 5962-9205405HXA | SDC-14619IIT-134 | 5962-9205412HXC |
| SDC-14616II-114 | 5962-9205311HXC | SDC-14617IIT-152 | 5962-9205406HXA | SDC-14619IIT-134 | 5962-9205412HXC |
| SDC-14616IIT-114 | 5962-9205312HXC | SDC-14617IIT-152 | 5962-9205406HXA | SDC-14619II-142 | 5962-9205407HXA |
| SDC-14616IIT-114 | 5962-9205312HXC | SDC-14617II-154 | 5962-9205409HXA | SDC-14619II-142 | 5962-9205407HXA |
| SDC-14616II-132 | 5962-9205307HXC | SDC-14617II-154 | 5962-9205409HXA | SDC-14619IIT-142 | 5962-9205408HXA |
| SDC-14616II-132 | 5962-9205307HXC | SDC-14617IIT-154 | 5962-9205410HXA | SDC-14619IIT-142 | 5962-9205408HXA |
| SDC-14616IIT-132 | 5962-9205308HXC | SDC-14617IIT-154 | 5962-9205410HXA | SDC-14619II-144 | 5962-9205411HXA |
| SDC-14616IIT-132 | 5962-9205308HXC | SDC-14618II-112 | 5962-9205503HXC | SDC-14619II-144 | 5962-9205411HXA |
| SDC-14616II-134 | 5962-9205311HXC | SDC-14618II-112 | 5962-9205503HXC | SDC-14619IIT-144 | 5962-9205412HXA |
| SDC-14616II-134 | 5962-9205311HXC | SDC-14618IIT-112 | 5962-9205504HXC | SDC-14619IIT-144 | 5962-9205412HXA |
| SDC-14616IIT-134 | 5962-9205312HXC | SDC-14618IIT-112 | 5962-9205504HXC | SDC-14619II-152 | 5962-9205407HXA |
| SDC-14616IIT-134 | 5962-9205312HXC | SDC-14618II-114 | 5962-9205505HXC | SDC-14619II-152 | 5962-9205407HXA |
| SDC-14616II-142 | 5962-9205307HXA | SDC-14618II-114 | 5962-9205505HXC | SDC-14619IIT-152 | 5962-9205408HXA |
| SDC-14616II-142 | 5962-9205307HXA | SDC-14618IIT-114 | 5962-9205506HXC | SDC-14619IIT-152 | 5962-9205408HXA |
| SDC-14616IIT-142 | 5962-9205308HXA | SDC-14618IIT-114 | 5962-9205506HXC | SDC-14619II-154 | 5962-9205411HXA |
| SDC-14616IIT-142 | 5962-9205308HXA | SDC-14618II-132 | 5962-9205503HXC | SDC-14619II-154 | 5962-9205411HXA |
| SDC-14616II-144 | 5962-9205311HXA | SDC-14618II-132 | 5962-9205503HXC | SDC-14619IIT-154 | 5962-9205412HXA |
| SDC-14616II-144 | 5962-9205311HXA | SDC-14618IIT-132 | 5962-9205504HXC | SDC-14619IIT-154 | 5962-9205412HXA |
| SDC-14616IIT-144 | 5962-9205312HXA | SDC-14618IIT-132 | 5962-9205504HXC | SD-14620DX-152 | 5962-9453601HXA |
| SDC-14616IIT-144 | 5962-9205312HXA | SDC-14618II-134 | 5962-9205505HXC | SD-14620DX-152 | 5962-9453601HXA |
| SDC-14616II-152 | 5962-9205307HXA | SDC-14618II-134 | 5962-9205505HXC | SD-14620FX-112 | 5962-9453601HYC |
| SDC-14616II-152 | 5962-9205307HXA | SDC-14618IIT-134 | 5962-9205506HXC | SD-14620FX-112 | 5962-9453601HYC |
| SDC-14616IIT-152 | 5962-9205308HXA | SDC-14618IIT-134 | 5962-9205506HXC | SD-14620DX-114 | 5962-9453603HXC |
| SDC-14616IIT-152 | 5962-9205308HXA | SDC-14618II-142 | 5962-9205503HXA | SD-14620DX-114 | 5962-9453603HXC |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART II, Listed By Generic PIN

| Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN |
|---|---|---|---|---|---|
| SD-14620FX-114 | 5962-9453603HYC | SD-14621FX-152 | 5962-9453602HYA | SD-14623FX-144 | 5962-9454802HYA |
| SD-14620FX-114 | 5962-9453603HYC | SD-14621FX-152 | 5962-9453602HYA | SD-14623DX-152 | 5962-9454801HXA |
| SD-14620DX-132 | 5962-9453601HXC | SD-14621DX-154 | 5962-9453604HXA | SD-14623DX-152 | 5962-9454801HXA |
| SD-14620DX-132 | 5962-9453601HXC | SD-14621DX-154 | 5962-9453604HXA | SD-14623FX-152 | 5962-9454801HYA |
| SD-14620FX-132 | 5962-9453601HYC | SD-14621FX-154 | 5962-9453604HYA | SD-14623FX-152 | 5962-9454801HYA |
| SD-14620FX-132 | 5962-9453601HYC | SD-14621FX-154 | 5962-9453604HYA | SD-14623DX-154 | 5962-9454802HXA |
| SD-14620DX-134 | 5962-9453603HXC | SD-14622DX-112 | 5962-9454701HXC | SD-14623DX-154 | 5962-9454802HXA |
| SD-14620DX-134 | 5962-9453603HXC | SD-14622DX-112 | 5962-9454701HXC | SD-14623FX-154 | 5962-9454802HYA |
| SD-14620FX-134 | 5962-9453603HYC | SD-14622DX-112 | 5962-9454703HXC | SD-14623FX-154 | 5962-9454802HYA |
| SD-14620FX-134 | 5962-9453603HYC | SD-14622FX-112 | 5962-9454701HYC | SD-14624DX-112 | 5962-9454702HXC |
| SD-14620DX-142 | 5962-9453601HXA | SD-14622DX-114 | 5962-9454703HXC | SD-14624DX-112 | 5962-9454702HXC |
| SD-14620DX-142 | 5962-9453601HXA | SD-14622FX-114 | 5962-9454703HYC | SD-14624FX-112 | 5962-9454702HYC |
| SD-14620FX-142 | 5962-9453601HYA | SD-14622DX-132 | 5962-9454701HXC | SD-14624DX-114 | 5962-9454704HXC |
| SD-14620FX-142 | 5962-9453601HYA | SD-14622DX-132 | 5962-9454701HXC | SD-14624DX-114 | 5962-9454704HXC |
| SD-14620DX-144 | 5962-9453603HXA | SD-14622FX-132 | 5962-9454701HYC | SD-14624FX-114 | 5962-9454704HYC |
| SD-14620DX-144 | 5962-9453603HXA | SD-14622DX-134 | 5962-9454703HXC | SD-14624DX-132 | 5962-9454702HXC |
| SD-14620FX-144 | 5962-9453603HYA | SD-14622DX-134 | 5962-9454703HXC | SD-14624DX-132 | 5962-9454702HXC |
| SD-14620FX-144 | 5962-9453603HYA | SD-14622FX-134 | 5962-9454703HYC | SD-14624FX-132 | 5962-9454702HYC |
| SD-14620DX-112 | 5962-9453601HXC | SD-14622DX-142 | 5962-9454701HXA | SD-14624DX-134 | 5962-9454704HXC |
| SD-14620DX-112 | 5962-9453601HXC | SD-14622DX-142 | 5962-9454701HXA | SD-14624DX-134 | 5962-9454704HXC |
| SD-14620FX-152 | 5962-9453601HYA | SD-14622FX-142 | 5962-9454701HYA | SD-14624FX-134 | 5962-9454704HYC |
| SD-14620FX-152 | 5962-9453601HYA | SD-14622DX-144 | 5962-9454703HXA | SD-14624DX-142 | 5962-9454702HXA |
| SD-14620DX-154 | 5962-9453603HXA | SD-14622DX-144 | 5962-9454703HXA | SD-14624DX-142 | 5962-9454702HXA |
| SD-14620DX-154 | 5962-9453603HXA | SD-14622FX-144 | 5962-9454703HYA | SD-14624FX-142 | 5962-9454702HYA |
| SD-14620FX-154 | 5962-9453603HYA | SD-14622DX-152 | 5962-9454701HXA | SD-14624DX-144 | 5962-9454704HXA |
| SD-14620FX-154 | 5962-9453603HYA | SD-14622DX-152 | 5962-9454701HXA | SD-14624DX-144 | 5962-9454704HXA |
| SDC-14621 (GEN) | 5962-9453605HXA | SD-14622FX-152 | 5962-9454701HYA | SD-14624FX-144 | 5962-9454704HYA |
| SD-14621DX-112 | 5962-9453602HXC | SD-14622DX-154 | 5962-9454703HXA | SD-14624DX-152 | 5962-9454702HXA |
| SD-14621DX-112 | 5962-9453602HXC | SD-14622DX-154 | 5962-9454703HXA | SD-14624DX-152 | 5962-9454702HXA |
| SD-14621FX-112 | 5962-9453602HYC | SD-14622FX-154 | 5962-9454703HYA | SD-14624FX-152 | 5962-9454702HYA |
| SD-14621FX-112 | 5962-9453602HYC | SD-14623DX-112 | 5962-9454801HXC | SD-14624DX-154 | 5962-9454704HXA |
| SD-14621DX-114 | 5962-9453604HXC | SD-14623DX-112 | 5962-9454801HXC | SD-14624DX-154 | 5962-9454704HXA |
| SD-14621DX-114 | 5962-9453604HXC | SD-14623FX-112 | 5962-9454801HYC | SD-14624FX-154 | 5962-9454704HYA |
| SD-14621FX-114 | 5962-9453604HYC | SD-14623FX-112 | 5962-9454801HYC | ACS147 (GEN) | 5962F9863301V9A |
| SD-14621FX-114 | 5962-9453604HYC | SD-14623DX-114 | 5962-9454802HXC | ACS147 (GEN) | 5962F9863301VEC |
| SD-14621DX-132 | 5962-9453602HXC | SD-14623DX-114 | 5962-9454802HXC | ACS147 (GEN) | 5962F9863301VXC |
| SD-14621DX-132 | 5962-9453602HXC | SD-14623FX-114 | 5962-9454802HYC | AP1C-47 (GEN) | 5962H9210401QZC |
| SD-14621FX-132 | 5962-9453602HYC | SD-14623FX-114 | 5962-9454802HYC | AP1C-47 (GEN) | 5962H9210401VZC |
| SD-14621FX-132 | 5962-9453602HYC | SD-14623DX-132 | 5962-9454801HXC | HCTS147 (GEN) | 5962R9574101V9A |
| SD-14621DX-134 | 5962-9453604HXC | SD-14623DX-132 | 5962-9454801HXC | HCTS147 (GEN) | 5962R9574101VEC |
| SD-14621DX-134 | 5962-9453604HXC | SD-14623FX-132 | 5962-9454801HYC | HCTS147 (GEN) | 5962R9574101VXC |
| SD-14621FX-134 | 5962-9453604HYC | SD-14623FX-132 | 5962-9454801HYC | LF147D/883 | 8102306CA |
| SD-14621FX-134 | 5962-9453604HYC | SD-14623DX-134 | 5962-9454802HXC | MSK147B | 5962-8870101UA |
| SD-14621DX-142 | 5962-9453602HXA | SD-14623DX-134 | 5962-9454802HXC | MSK147B | 5962-8870101UC |
| SD-14621DX-142 | 5962-9453602HXA | SD-14623FX-134 | 5962-9454802HYC | GEM14701QCA | 5962-8856401CA |
| SD-14621FX-142 | 5962-9453602HYA | SD-14623FX-134 | 5962-9454802HYC | GEM14701QCC | 5962-8856401CC |
| SD-14621FX-142 | 5962-9453602HYA | SD-14623DX-142 | 5962-9454801HXA | GEM14701QDA | 5962-8856401DA |
| SD-14621DX-144 | 5962-9453604HXA | SD-14623DX-142 | 5962-9454801HXA | GEM14701QDC | 5962-8856401DC |
| SD-14621DX-144 | 5962-9453604HXA | SD-14623FX-142 | 5962-9454801HYA | MSK1476H | 5962-0054101HGA |
| SD-14621FX-144 | 5962-9453604HYA | SD-14623FX-142 | 5962-9454801HYA | MSK1476H | 5962-0054101HGC |
| SD-14621FX-144 | 5962-9453604HYA | SD-14623DX-144 | 5962-9454802HXA | PAL14L8 (GEN) | 5962-86804033A |
| SD-14621DX-152 | 5962-9453602HXA | SD-14623DX-144 | 5962-9454802HXA | PAL14L8 (GEN) | 5962-8680403KA |
| SD-14621DX-152 | 5962-9453602HXA | SD-14623FX-144 | 5962-9454802HYA | PAL14L8 (GEN) | 5962-8680403LA |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

| Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN |
|---|---|---|---|---|---|
| MG1480 | 5962-00B0115Q*C | NHI-1502FP | 5962-8982603YC | NHI-1514FP | 5962-9174901HYC |
| MG1480E | 5962-00B0107Q*C | 15022-009 | 5962-01A0301QXC | NHI-1514FP/883 | 5962-9174908HTA |
| MM0-G1480*MQ | 5962-00B0115Q9A | 15022-512 | 5962-01A1901QXC | NHI-1514FP/883 | 5962-9174908HTC |
| MM0-G1480EH*MQ | 5962-00B0107Q9A | 15022-517 | 5962-02A1001QXC | NHI-1514FP/883 | 5962-9174908HYA |
| CT1487D (GEN) | 5962-8757907XA | 15028-505 | 5962-01A0101QXA | NHI-1514FP/883 | 5962-9174908HYC |
| CT1487D (GEN) | 5962-8757907YA | 15028-507 | 5962-01A1601QXC | NHI-1515 | 5962-9208504HXA |
| CT1487-DFI (GEN) | 5962-8944707HYA | 1503A (GEN) | 5962-8686102PA | NHI-1515 | 5962-9208504HXC |
| CT1487-DI (GEN) | 5962-8944705HXA | SG1503T/883B | 5962-8686101YA | NHI-1515FP | 5962-9208504HYA |
| LCB15K (GEN) | 5962-95B0103M4C | SG1503Y/883B | 5962-8686101PA | NHI-1515FP | 5962-9208504HYC |
| LCB15K (GEN) | 5962-95B0103M5C | HS-506 (GEN) | 5962D9569101VXA | UC1517J/883BC | 5962-9321501MEA |
| LCB15K (GEN) | 5962-95B0103M6C | HS-507 (GEN) | 5962D9569102VXA | UC1517L/883BC | 5962-9321501M2A |
| LCB15K (GEN) | 5962-95B0103M7C | NHI-1509 | 5962-8604906YA | GEM15201QEA | 7601901EA |
| LCB15K (GEN) | 5962-95B0103M8C | NHI-1509 | 5962-8604906YC | GEM15201QEC | 7601901EC |
| LCB15K (GEN) | 5962-95B0103M9C | NHI-1509FP | 5962-8604906TA | GEM15201QFA | 7601901FA |
| LCB15K (GEN) | 5962-95B0103MCC | NHI-1509FP | 5962-8604906TC | GEM15201QFC | 7601901FC |
| LCB15K (GEN) | 5962-95B0103MMC | HCS151 (GEN) | 5962R9572801V9A | NHI-1522/883 | 5962-8982610XA |
| LCB15K (GEN) | 5962-95B0103MNC | HCS151 (GEN) | 5962R9572801VEC | NHI-1522/883 | 5962-8982610XC |
| LCB15K (GEN) | 5962-95B0103MTC | HCS151KMSR | 5962R9572801VXC | NHI-1522FP/883 | 5962-8982610YA |
| LCB15K (GEN) | 5962-95B0103MUC | NHI-15101RT | 5962-9168709HZA | NHI-1522FP/883 | 5962-8982610YC |
| LCB15K (GEN) | 5962-95B0103MXC | NHI-15101RT | 5962-9168709HZC | NHI-1523 | 5962-8982604XA |
| LCB15K (GEN) | 5962-95B0103MYC | NHI-15101RTFP | 5962-9168709HUA | NHI-1523 | 5962-8982604XC |
| LCB15K (GEN) | 5962-95B0103MZC | NHI-15101RTFP | 5962-9168709HUC | NHI-1523FP | 5962-8982604YA |
| OP-15A (GEN) | 5962-8954201GA | ACS151 (GEN) | 5962F9764001V9A | NHI-1523FP | 5962-8982604YC |
| OP-15A (GEN) | 5962-8954201PA | ACS151 (GEN) | 5962F9764001VEA | IP1524BJ-DESC | 5962-8764501EA |
| OP-15AJ/QMLR | 5962R8954203VGA | ACS151 (GEN) | 5962F9764001VFA | SG1524BJ/883B | 5962-8764501EA |
| OP-15AJ/QMLV | 5962-8954203VGA | NHI-15102RT | 5962-9168710HZA | SG1524J/883B | 7802801EA |
| OP-15AL/QMLR | 5962R8954203VHA | NHI-15102RT | 5962-9168710HZC | UC1524AJ/883B | 5962-8764502EA |
| OP-15AL/QMLV | 5962-8954203VHA | NHI-15102RTFP | 5962-9168710HUA | IP1525AJ-DESC | 5962-8951101EA |
| OP-15AZ/QMLR | 5962R8954203VPA | NHI-15102RTFP | 5962-9168710HUC | SG1525AF/883B | 5962-8951101FA |
| OP-15AZ/QMLV | 5962-8954203VPA | NHI-15103ET/883 | 5962-9555805HXA | SG1525AJ/883B | 5962-8951101EA |
| OP-15B (GEN) | 5962-8954202GA | NHI-15103ET/883 | 5962-9555805HXC | UC1525AJ/883B | 5962-8951101EA |
| IP150AG-DESC | 5962-8767502TA | NHI-15103ETFP/883 | 5962-9555805HYA | UC1525AJ/883B | 5962-8951103EA |
| IP150AIG-DESC | 5962-8767502UA | NHI-15103ETFP/883 | 5962-9555805HYC | UC1525AJQMLV | 5962-8951103VEA |
| IP150AK-DESC | 5962-8767502XA | 1510-369/2 (GEN) | 5962-9161501HXC | UC1525AL/883B | 5962-89511012A |
| IP150G-DESC | 5962-8767501TA | NHI-15104ET/883 | 5962-9555806HXA | UC1525AL/883B | 5962-89511032A |
| IP150IG-DESC | 5962-8767501UA | NHI-15104ET/883 | 5962-9555806HXC | UC1525ALQMLV | 5962-8951103V2A |
| IP150K-DESC | 5962-8767501XA | NHI-15104ETFP/883 | 5962-9555806HYA | UC1525BJ/883B | 5962-8951105EA |
| LM150K/883 | 5962-8767501XA | NHI-15104ETFP/883 | 5962-9555806HYC | UC1525BJQMLV | 5962-8951105VEA |
| UT150*QCR | 5962R96B0215Q*C | NHI-1513 | 5962-9174902HXA | UC1525BL/883B | 5962-89511052A |
| UT150*VCR | 5962R96B0215V*C | NHI-1513 | 5962-9174902HXC | UC1525BLQMLV | 5962-8951105V2A |
| 1500 | 5962-0252501EXA | NHI-1513/883 | 5962-9174909HXA | SG1526BJ/883 | 8551501VA |
| NHI-1500 | 5962-8757905XA | NHI-1513/883 | 5962-9174909HXC | SG1526BL/883 | 85515012A |
| NHI-1500 | 5962-8757905XC | NHI-1513FP | 5962-9174902HYA | UC1526AJ/883 | 8551502VA |
| NHI-1500FP | 5962-8757905YA | NHI-1513FP | 5962-9174902HYC | UC1526AL/883B | 85515022A |
| NHI-1500FP | 5962-8757905YC | NHI-1513FP/883 | 5962-9174909HTA | UC1526J/883 | 8551501VA |
| 15004-022 | 5962-03A0401QQC | NHI-1513FP/883 | 5962-9174909HTC | UC1526L/883B | 85515012A |
| NHI-1501 | 5962-8944702HXA | NHI-1513FP/883 | 5962-9174909HYA | IP1527AJ-DESC | 5962-8951102EA |
| NHI-1501 | 5962-8944702HXC | NHI-1513FP/883 | 5962-9174909HYC | SG1527AJ/883B | 5962-8951102EA |
| NHI-1501FP | 5962-8944702HYA | NHI-1514 | 5962-9174901HXA | UC1527AJ/883B | 5962-8951102EA |
| NHI-1501FP | 5962-8944702HYC | NHI-1514 | 5962-9174901HXC | UC1527AJ/883B | 5962-8951104EA |
| NHI-1502 | 5962-8982603XA | NHI-1514/883 | 5962-9174908HXA | UC1527AL/883B | 5962-89511022A |
| NHI-1502 | 5962-8982603XC | NHI-1514/883 | 5962-9174908HXC | UC1527AL/883B | 5962-89511042A |
| NHI-1502FP | 5962-8982603YA | NHI-1514FP | 5962-9174901HYA | NHI-1529 | 5962-8952203XA |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

| Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN |
|---|---|---|---|---|---|
| NHI-1529 | 5962-8952203XC | TLV1548MJB | 5962-9853801QRA | UT1553BCRTVFAH | 5962H8862801VTA |
| NHI-1529/883 | 5962-8952202XA | SG1549Y/883B | 5962-8684901PA | UT1553BCRTVFCH | 5962H8862801VTC |
| NHI-1529/883 | 5962-8952202XC | PM155AJ/QMLR | 5962R9863601VGA | UT1553BCRTVGAH | 5962H8862801VXA |
| NHI-1529/883 | 5962-8952206XA | PM155AZ/QMLR | 5962R9863601VPA | UT1553BCRTVGCH | 5962H8862801VXC |
| NHI-1529/883 | 5962-8952206XC | NHI-1551 | 5962-9208501HXA | UT1553BCRTVWAH | 5962H8862801VYA |
| NHI-1529/883 | 5962-8952208XA | NHI-1551 | 5962-9208501HXC | UT1553BCRTVWCH | 5962H8862801VYC |
| NHI-1529/883 | 5962-8952208XC | NHI-1551FP | 5962-9208501HYA | UT1553BCRTWAH | 5962H8862801YA |
| NHI-1529/883 | 5962-8952208YA | NHI-1551FP | 5962-9208501HYC | UT1553BCRTWCH | 5962H8862801YC |
| NHI-1529/883 | 5962-8952208YC | NHI-1553RT | 5962-9168701HXA | UT1553BRTRAA | 5962-8957601ZA |
| NHI-1529/883 | 5962-8952209XA | NHI-1553RT | 5962-9168701HXC | UT1553BRTRAC | 5962-8957601ZC |
| NHI-1529/883 | 5962-8952209XC | NHI-1553RTFP | 5962-9168701HYA | UT1553BRTRGA | 5962-8957601XA |
| NHI-1529/883 | 5962-8952209YA | NHI-1553RTFP | 5962-9168701HYC | UT1553BRTRGC | 5962-8957601XC |
| NHI-1529/883 | 5962-8952209YC | UT1553BBCRTA | 5962-8862801ZA | UT1553BRTRWA | 5962-8957601YA |
| NHI-1529FP | 5962-8952203YA | UT1553BBCRTA | 5962-8862801ZC | UT1553BRTRWC | 5962-8957601YC |
| NHI-1529FP | 5962-8952203YC | UT1553BBCRTF | 5962-8862801TA | UT1553RTMPACA | 5962-8864501ZA |
| NHI-1529FP/883 | 5962-8952202YA | UT1553BBCRTF | 5962-8862801TC | UT1553RTMPGCA | 5962-8864501XA |
| NHI-1529FP/883 | 5962-8952202YC | UT1553BBCRTG | 5962-8862801XA | UT1553RTMPGCC | 5962-8864501XC |
| NHI-1529FP/883 | 5962-8952206YA | UT1553BBCRTG | 5962-8862801XC | UT1553RTMPWCA | 5962-8864501YA |
| NHI-1529FP/883 | 5962-8952206YC | UT1553BBCRTW | 5962-8862801YA | UT1553RTMPWCC | 5962-8864501YC |
| HCTS153 (GEN) | 5962R9575401V9A | UT1553BBCRTW | 5962-8862801YC | HD1-15530-8 | 7802901JA |
| HCTS153 (GEN) | 5962R9575401VEC | UT1553BCRTAAH | 5962H8862801ZA | HD4-15530-8 | 78029013A |
| HCTS153KMSR | 5962R9575401VXC | UT1553BCRTACH | 5962H8862801ZC | HD1-15531/883 | 5962-9054901MQA |
| NHI-1531 | 5962-9082905HYA | UT1553BCRTFAH | 5962H8862801TA | HD1-15531B (GEN) | 5962-9054902MQA |
| NHI-1531 | 5962-9082905HYC | UT1553BCRTFCH | 5962H8862801TC | FC155361 | 5962-8604907XA |
| NHI-1531FP | 5962-9082905HTA | UT1553BCRTGAH | 5962H8862801XA | FC155361 | 5962-8604907XC |
| NHI-1531FP | 5962-9082905HTC | UT1553BCRTGCH | 5962H8862801XC | FC155362 | 5962-8604908XA |
| SG1532J | 5962-8777001CA | UT1553BCRTMA | 5962-8957701ZA | FC155362 | 5962-8604908XC |
| SG1532L | 5962-87770012A | UT1553BCRTMA | 5962-8957701ZC | FC1553621 | 5962-8757909XA |
| SG1532T | 5962-8777001IA | UT1553BCRTMAAH | 5962H8957701ZA | FC1553621 | 5962-8757909XC |
| SG1536T/883B | 7800304XA | UT1553BCRTMACH | 5962H8957701ZC | FC1553621FP | 5962-8757909YA |
| SG1536Y/883B | 7800304PA | UT1553BCRTMG | 5962-8957701XA | FC1553621FP | 5962-8757909YC |
| HCS154 (GEN) | 5962R9572901V9A | UT1553BCRTMG | 5962-8957701XC | FC1553623 | 5962-8757906XA |
| HCS154DMSR | 5962R9572901VJC | UT1553BCRTMGAH | 5962H8957701XA | FC1553623 | 5962-8757906XC |
| HCS154KMSR | 5962R9572901VXC | UT1553BCRTMGCH | 5962H8957701XC | FC1553623FP | 5962-8757906YA |
| TLC1541 (GEN) | 5962-9064201Q2A | UT1553BCRTMPA | 5962-8950101YC | FC1553623FP | 5962-8757906YC |
| TLC1541 (GEN) | 5962-9064201QRA | UT1553BCRTMPG | 5962-8950101XA | FC1553622 | 5962-8944703HXA |
| TLC1542MFKB | 5962-9064202Q2A | UT1553BCRTMPG | 5962-8950101XC | FC1553622 | 5962-8944703HXC |
| TLC1542MJB | 5962-9064202QRA | UT1553BCRTM-QDIE | 5962-8957701Q9A | FC1553622FP | 5962-8944703HYA |
| IP1543J-DESC | 5962-8774001EA | UT1553BCRTM-QDIE | 5962H8957701Q9B | FC1553622FP | 5962-8944703HYC |
| SG1543J/883B | 5962-8774001EA | UT1553BCRTMVAAH | 5962H8957701VZA | FC155371 | 5962-9082901HXA |
| TLV1543MFKB | 5962-9689401Q2A | UT1553BCRTMVACH | 5962H8957701VZC | FC155371 | 5962-9082901HXC |
| TLV1543MJB | 5962-9689401QRA | UT1553BCRTM-VDIE | 5962-8957701V9A | FC155371FP | 5962-9082901HTA |
| UC1543J/883B | 5962-8774001EA | UT1553BCRTM-VDIE | 5962H8957701V9B | FC155371FP | 5962-9082901HTC |
| IP1544J-DESC | 5962-8774002VA | UT1553BCRTMVGAH | 5962H8957701VXA | FC155371SSW | 5962-9082901HYA |
| SG1544J/883B | 5962-8774002VA | UT1553BCRTMVGCH | 5962H8957701VXC | FC155371SSW | 5962-9082901HYC |
| 1545 (GEN) | 5962-8671201CA | UT1553BCRTMVWAH | 5962H8957701VYA | FC155372 | 5962-9082902HXA |
| 1545 (GEN) | 5962-8671201IA | UT1553BCRTMVWCH | 5962H8957701VYC | FC155372 | 5962-9082902HXC |
| NHI-1545 | 5962-9082906HYA | UT1553BCRTMW | 5962-8957701YA | FC1553721 | 5962-8982605XA |
| NHI-1545 | 5962-9082906HYC | UT1553BCRTMW | 5962-8957701YC | FC1553721 | 5962-8982605XC |
| NHI-1545FP | 5962-9082906HTA | UT1553BCRTMWAH | 5962H8957701YA | FC1553721FP | 5962-8982605YA |
| NHI-1545FP | 5962-9082906HTC | UT1553BCRTMWCH | 5962H8957701YC | FC1553721FP | 5962-8982605YC |
| SG1548J/883B | 5962-8987801EA | UT1553BCRTVAAH | 5962H8862801VZA | FC1553722 | 5962-8982607XA |
| TLV1548MFKB | 5962-9853801Q2A | UT1553BCRTVACH | 5962H8862801VZC | FC1553722 | 5962-8982607XC |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

| Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN |
|---|---|---|---|---|---|
| FC1553722FP | 5962-8982607YA | PM156AZ/QMLR | 5962R9863602VPA | LM1575ADJ (GEN) | 5962-9167102QXA |
| FC1553722FP | 5962-8982607YC | NHI-1560/883 | 5962-9206104HTA | LM1575J-ADJ-QML | 5962-9167101MEA |
| FC1553726 | 5962-8982608XA | NHI-1560/883 | 5962-9206104HTC | LM1575K-ADJ-QML | 5962-9167101MXA |
| FC1553726 | 5962-8982608XC | NHI-1560FP/883 | 5962-9206104HUA | LM1575WGADJ-QML | 5962-9167101QZA |
| FC1553726FP | 5962-8982608YA | NHI-1560FP/883 | 5962-9206104HUC | LM157512 (GEN) | 5962-9167301QXA |
| FC1553726FP | 5962-8982608YC | NHI-1561RT | 5962-9168703HZA | LM157512 (GEN) | 5962-9167301QYA |
| FC155377 | 5962-9208505HXA | NHI-1561RT | 5962-9168703HZC | LM157512 (GEN) | 5962-9167302QXA |
| FC155377 | 5962-9208505HXC | NHI-1561RTFP | 5962-9168703HUA | LM1575J-12-QML | 5962-9167301QEA |
| FC155377FP | 5962-9208505HYA | NHI-1561RTFP | 5962-9168703HUC | LM1575WG12-QML | 5962-9167301QZA |
| FC155377FP | 5962-9208505HYC | NHI-1562RT | 5962-9168704HZA | LM157515 (GEN) | 5962-9167401QXA |
| FC155391 | 5962-8979901XA | NHI-1562RT | 5962-9168704HZC | LM157515 (GEN) | 5962-9167401QYA |
| FC155391 | 5962-8979901XC | NHI-1562RTFP | 5962-9168704HUA | LM157515 (GEN) | 5962-9167402QXA |
| FC155392 | 5962-8979902XA | NHI-1562RTFP | 5962-9168704HUC | LM1575J-15-QML | 5962-9167401QEA |
| FC155392 | 5962-8979902XC | NHI-1563/883 | 5962-9206105HTA | LM1575WG15-QML | 5962-9167401QZA |
| FC1553921 | 5962-8952206XA | NHI-1563/883 | 5962-9206105HTC | LM15755 (GEN) | 5962-9167202QXA |
| FC1553921 | 5962-8952206XC | NHI-1563FP/883 | 5962-9206105HUA | LM1575K-5.0-QML | 5962-9167201MXA |
| FC1553921FP | 5962-8952206YA | NHI-1563FP/883 | 5962-9206105HUC | LM15755.0 (GEN) | 5962-9167201QYA |
| FC1553921FP | 5962-8952206YC | NHI-1567/883 | 5962-9206103HMA | LM1575J-5.0-QML | 5962-9167201QEA |
| FC1553922 | 5962-8952209XA | NHI-1567/883 | 5962-9206103HMC | LM1575WG5.0-QML | 5962-9167201QZA |
| FC1553922 | 5962-8952209XC | NHI-1567FP/883 | 5962-9206103HNA | NHI-1576RT | 5962-9168706HXA |
| FC1553923 | 5962-8952207XA | NHI-1567FP/883 | 5962-9206103HNC | NHI-1576RT | 5962-9168706HXC |
| FC1553923 | 5962-8952207XC | 1568 (GEN) | 5962-8876301IA | NHI-1576RT | 5962-9168706HYA |
| FC1553923 | 5962-8952207YA | 1568 (GEN) | 5962-8876302CA | NHI-1576RT | 5962-9168706HYC |
| FC1553923 | 5962-8952207YC | NHI-1568/883 | 5962-9206104HMA | LM1577ADJ (GEN) | 5962-9216601QYA |
| FC1553924 | 5962-8952210XA | NHI-1568/883 | 5962-9206104HMC | LM1577K-ADJ/883 | 5962-9216601MXA |
| FC1553924 | 5962-8952210XC | NHI-1568FP/883 | 5962-9206104HNA | NHI-1577/883 | 5962-9206106HTA |
| NHI-1554RT | 5962-9168702HXA | NHI-1568FP/883 | 5962-9206104HNC | NHI-1577/883 | 5962-9206106HTC |
| NHI-1554RT | 5962-9168702HXC | NHI-1569/883 | 5962-9206105HMA | NHI-1577FP/883 | 5962-9206106HUA |
| NHI-1554RTFP | 5962-9168702HYA | NHI-1569/883 | 5962-9206105HMC | NHI-1577FP/883 | 5962-9206106HUC |
| NHI-1554RTFP | 5962-9168702HYC | NHI-1569FP/883 | 5962-9206105HNA | LM1577K-12/883 | 5962-9216701MXA |
| MC1558FKB | 5962-9760301Q2A | NHI-1569FP/883 | 5962-9206105HNC | LM1577 (GEN) | 5962-9216801MXA |
| MC1558JGB | 5962-9760301QPA | ACS157-03 (GEN) | 5962F9853601V9A | LM1578 (GEN) | 5962-8958601GA |
| NHI-1559/883 | 5962-8952201XA | ACS157-03 (GEN) | 5962F9853601VEC | LM1578A (GEN) | 5962-8958602GA |
| NHI-1559/883 | 5962-8952201XC | ACS157-03 (GEN) | 5962F9853601VXC | NHI-1578/883 | 5962-9206105H4A |
| NHI-1559/883 | 5962-8952204XA | HCS157 (GEN) | 5962R9580501V9A | NHI-1578/883 | 5962-9206105H4C |
| NHI-1559/883 | 5962-8952204XC | HCS157DMSR | 5962R9580501VEC | NHI-1578FP/883 | 5962-9206105H5A |
| NHI-1559/883 | 5962-8952207XA | HCS157KMSR | 5962R9580501VXC | NHI-1578FP/883 | 5962-9206105H5C |
| NHI-1559/883 | 5962-8952207XC | HCTS157 (GEN) | 5962R9575501V9A | NHI-1579/883 | 5962-9206103H4A |
| NHI-1559/883 | 5962-8952210XA | HCTS157DMSR | 5962R9575501VEC | NHI-1579/883 | 5962-9206103H4C |
| NHI-1559/883 | 5962-8952210XC | HCTS157KMSR | 5962R9575501VXC | NHI-1579FP/883 | 5962-9206103H5A |
| NHI-1559/883 | 5962-8952210YA | NHI-1570/883 | 5962-9206106HMA | NHI-1579FP/883 | 5962-9206103H5C |
| NHI-1559/883 | 5962-8952210YC | NHI-1570/883 | 5962-9206106HMC | LM158A (GEN) | 5962L8771002QGA |
| NHI-1559/883 | 5962-9206103HTA | NHI-1570FP/883 | 5962-9206106HNA | LM158A (GEN) | 5962L8771002QXA |
| NHI-1559/883 | 5962-9206103HTC | NHI-1570FP/883 | 5962-9206106HNC | LM158AFKB | 5962-87710022A |
| NHI-1559FP/883 | 5962-8952201YA | NHI-1572RT | 5962-9168705HXA | LM158AH/883 | 5962-8771002GA |
| NHI-1559FP/883 | 5962-8952201YC | NHI-1572RT | 5962-9168705HXC | LM158AHLQMLV | 5962L8771002VGA |
| NHI-1559FP/883 | 5962-8952204YA | NHI-1572RT | 5962-9168705HYA | LM158AH-QMLV | 5962-8771002VGA |
| NHI-1559FP/883 | 5962-8952204YC | NHI-1572RT | 5962-9168705HYC | LM158AJ/883 | 5962-8771002PA |
| NHI-1559FP/883 | 5962-8952207YA | NHI-1573FP/883 | 5962-9206103HZA | LM158AJGB | 5962-8771002PA |
| NHI-1559FP/883 | 5962-8952207YC | NHI-1573FP/883 | 5962-9206103HZC | LM158AJLQML | 5962L8771002QPA |
| NHI-1559FP/883 | 5962-9206103HUA | NHI-1574FP/883 | 5962-9206104HZA | LM158AJLQMLV | 5962L8771002VPA |
| NHI-1559FP/883 | 5962-9206103HUC | NHI-1574FP/883 | 5962-9206104HZC | LM158AJ-QMLV | 5962-8771002VPA |
| PM156AJ/QMLR | 5962R9863602VGA | LM1575ADJ (GEN) | 5962-9167101QYA | LM158AWG/883 | 5962-8771002QXA |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

| Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN |
|---|---|---|---|---|---|
| LM158AWGLQMLV | 5962L8771002VXA | NHI-1599ETFP/883 | 5962-9555804HYC | PAL16C1 (GEN) | 8103505SA |
| LM158AWG-QMLV | 5962-8771002VXA | HDAS-16/883 | 5962-8851404XA | PLS161 (GEN) | 5962-8850401LA |
| LM158FKB | 5962-87710012A | HDAS-16/883 | 5962-8851404XC | ACS161-02 (GEN) | 5962F9670602V9A |
| LM158H/883 | 5962-8771001GA | MUX-16AT | 5962-8771701XA | ACS161-02 (GEN) | 5962F9670602VEC |
| LM158J/883 | 5962-8771001PA | MUX-16BT | 5962-8771702XA | ACS161-02 (GEN) | 5962F9670602VXC |
| LM158JGB | 5962-8771001PA | MUX-16BTC | 5962-87717023A | ACTS161-02 (GEN) | 5962F9671602V9A |
| NHI-1580/883 | 5962-9206104H4A | OP-16A (GEN) | 5962-8954301GA | ACTS161-02 (GEN) | 5962F9671602VEC |
| NHI-1580/883 | 5962-9206104H4C | OP-16A (GEN) | 5962-8954301PA | ACTS161-02 (GEN) | 5962F9671602VXC |
| NHI-1580FP/883 | 5962-9206104H5A | OP-16AJ/QMLR | 5962R8954304VGA | UC1611J/883B | 5962-9053801PA |
| NHI-1580FP/883 | 5962-9206104H5C | OP-16AJ/QMLV | 5962-8954304VGA | UC1611JQMLV | 5962-9053801VPA |
| NHI-1581/883 | 5962-9206106H4A | OP-16AZ/QMLR | 5962R8954304VPA | UC1611L/883B | 5962-90538012A |
| NHI-1581/883 | 5962-9206106H4C | OP-16AZ/QMLV | 5962-8954304VPA | UC1611LQMLV | 5962-9053801V2A |
| NHI-1581FP/883 | 5962-9206106H5A | OP-16B (GEN) | 5962-8954302GA | PAL16H2 (GEN) | 81035042A |
| NHI-1581FP/883 | 5962-9206106H5C | OP-16BZ/883 | 5962-8954302PA | PAL16H2 (GEN) | 8103504RA |
| NHI-1582ET/883 | 5962-9555801HXA | OP-16C (GEN) | 5962-8954303GA | PAL16H2 (GEN) | 8103504SA |
| NHI-1582ET/883 | 5962-9555801HXC | OP-16C (GEN) | 5962-8954303PA | PAL16H2A (GEN) | 8103513RA |
| NHI-1582ETFP/883 | 5962-9555801HYA | WEDSP-16 (GEN) | 5962-9070401QXA | PAL16L2 (GEN) | 81035092A |
| NHI-1582ETFP/883 | 5962-9555801HYC | HCS160 (GEN) | 5962R9580601V9A | PAL16L2 (GEN) | 8103509RA |
| NHI-1583ET/883 | 5962-9555802HXA | HCS160 (GEN) | 5962R9580601VEC | PAL16L2 (GEN) | 8103509SA |
| NHI-1583ET/883 | 5962-9555802HXC | HCS160 (GEN) | 5962R9580601VXC | PAL16L2A (GEN) | 8103517RA |
| NHI-1583ETFP/883 | 5962-9555802HYA | HCTS160 (GEN) | 5962R9574201TEC | UC1620 (GEN) | 5962-9554401MJC |
| NHI-1583ETFP/883 | 5962-9555802HYC | HCTS160 (GEN) | 5962R9574201TXC | 1620-35 (GEN) | 5962-8685924WA |
| CT1589 (GEN) | 5962-8982606XA | HCTS160 (GEN) | 5962R9574201V9A | 1620-45 (GEN) | 5962-8685922WA |
| CT1589 (GEN) | 5962-8982606YA | HCTS160 (GEN) | 5962R9574201VEC | 1620-55 (GEN) | 5962-8685920WA |
| CT1589M (GEN) | 5962-9082907HTA | HCTS160 (GEN) | 5962R9574201VXC | 1621-35 (GEN) | 5962-8685923WA |
| CT1589M (GEN) | 5962-9082907HXA | LM160 | 5962-8767401CA | 1621-45 (GEN) | 5962-8685921WA |
| CT1589M (GEN) | 5962-9082907HYA | LM160 | 5962-8767401PA | 1621-55 (GEN) | 5962-8685919WA |
| CT1589MI (GEN) | 5962-9082908HTA | LM160H/883 | 5962-8767401GA | RHRXH162245K01Q | 5962R0250801QXC |
| CT1589MI (GEN) | 5962-9082908HXA | OP160ARC/883 | 5962-9090501M2A | RHRXH162245K01V | 5962R0250801VXC |
| CT1589MIP (GEN) | 5962-9082908HYA | OP160AZ/883 | 5962-9090501MPA | RHRXH162245K02Q | 5962R0250801QXA |
| ML1590/BGA | 5962-8765701GA | HPC16003 (GEN) | 5962-9054401MXA | RHRXH162245K02V | 5962R0250801VXA |
| NHI-1591RT | 5962-9168707HZA | HPC16003 (GEN) | 5962-9054401MYC | MOR1623K | 5962-88584012A |
| NHI-1591RT | 5962-9168707HZC | HPC16083 (GEN) | 5962-9054402MXA | MOR1623K (GEN) | 5962-8858401EA |
| NHI-1591RTFP | 5962-9168707HUA | HPC16083 (GEN) | 5962-9054402MYC | MOR1623K (GEN) | 5962-8858401FA |
| NHI-1591RTFP | 5962-9168707HUC | ACS161 (GEN) | 5962F9670601V9A | QL16X24B-0CG144M/8 | 5962-9559902MYC |
| NHI-1592RT | 5962-9168708HZA | ACS161 (GEN) | 5962F9670601VEC | 16X24B (GEN) | 5962-9559902MXC |
| NHI-1592RT | 5962-9168708HZC | ACS161 (GEN) | 5962F9670601VXC | QL16X24B-1CG144M/8 | 5962-9559903MYC |
| NHI-1592RTFP | 5962-9168708HUA | ACTS161 (GEN) | 5962F9671601V9A | 16X24B (GEN) | 5962-9559903MXC |
| NHI-1592RTFP | 5962-9168708HUC | ACTS161DMSR | 5962F9671601VEC | RHFACT16244K01Q | 5962F9202201QYC |
| NHI-1593FP/883 | 5962-9206105HZA | ACTS161KMSR | 5962F9671601VXC | RHFACT16244K01V | 5962F9202201VYC |
| NHI-1593FP/883 | 5962-9206105HZC | HCS161DMSR | 5962R9573001VEC | RHFACT16244K02Q | 5962F9202201QYA |
| NHI-1594FP/883 | 5962-9206106HZA | HCS161HMSR | 5962R9573001V9A | RHFACT16244K02V | 5962F9202201VYA |
| NHI-1594FP/883 | 5962-9206106HZC | HCS161KMSR | 5962R9573001VXC | RHFAC16244K01Q | 5962F0421001QXC |
| 1595 (GEN) | 5962-8987501CA | HCTS161A (GEN) | 5962R9577001V9A | RHFAC16244K01V | 5962F0421001VXC |
| 1596 (GEN) | 5962-8857101CA | HCTS161A (GEN) | 5962R9577001VEC | RHFAC16244K02Q | 5962F0421001QXA |
| 1596 (GEN) | 5962-8857101IA | HCTS161A (GEN) | 5962R9577001VXC | RHFAC16244K02V | 5962F0421001VXA |
| NHI-1598ET/883 | 5962-9555803HXA | LM161/BA | 5962-8757203BA | RHFACT16245K01Q | 5962F9202301QYC |
| NHI-1598ET/883 | 5962-9555803HXC | LM161/CA | 5962-8757203CA | RHFACT16245K01V | 5962F9202301VYC |
| NHI-1598ETFP/883 | 5962-9555803HYA | LM161/IA | 5962-8757203IA | RHFACT16245K02Q | 5962F9202301QYA |
| NHI-1598ETFP/883 | 5962-9555803HYC | LM161H/883 | 5962-8757203IA | RHFACT16245K02V | 5962F9202301VYA |
| NHI-1599ET/883 | 5962-9555804HXA | LM161J/883 | 5962-8757203CA | RHFAC16245K01Q | 5962F0421101QXC |
| NHI-1599ET/883 | 5962-9555804HXC | PAL16C1 (GEN) | 81035052A | RHFAC16245K01V | 5962F0421101VXC |
| NHI-1599ETFP/883 | 5962-9555804HYA | PAL16C1 (GEN) | 8103505RA | RHFAC16245K02Q | 5962F0421101QXA |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

| Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN |
|---|---|---|---|---|---|
| RHFAC16245K02V | 5962F0421101VXA | 16R4-10 (GEN) | 5962-9233804MXA | 1648 (GEN) | 5962-8977801CA |
| UC1625 (GEN) | 5962-9168901MXA | TIBPAL16R4-10MFKB | 5962-85155202A | 1648 (GEN) | 5962-8977801DA |
| HS-6254RH (GEN) | 5962F9764101VEC | TIBPAL16R4-10MJB | 5962-8515520RA | 1648 (GEN) | 5962-89778012A |
| HS9-6254RH-Q | 5962F9764101VXC | TIBPAL16R4-10MWB | 5962-8515520SA | HCS165 (GEN) | 5962R9578601V9A |
| SG1626J/883B | 5962-8871601CA | TIBPAL16R4-12MFKB | 5962-85155162A | HCS165DMSR | 5962R9578601VEC |
| SG1626R/883B | 5962-8871601XA | TIBPAL16R4-12MJB | 5962-8515516RA | HCS165KMSR | 5962R9578601VXC |
| SG1626T/883B | 5962-8871601GA | TIBPAL16R4-12MWB | 5962-8515516SA | TLC16C552AMHVB | 5962-9755001QXA |
| SG1626Y/883B | 5962-8871601PA | TIBPAL16R4-15MFKB | 5962-85155122A | 65779 (GEN) | 5962-8988304XA |
| SNJ54ABT162601WD | 5962-9859301QXA | TIBPAL16R4-15MJB | 5962-8515512RA | HCS166 (GEN) | 5962R9578701V9A |
| HCS163 (GEN) | 5962R9580701V9A | TIBPAL16R4-15MWB | 5962-8515512SA | HCS166DMSR | 5962R9578701VEC |
| HCS163DMSR | 5962R9580701VEC | PAL16R4A-2MFKB | 81036142A | HCS166KMSR | 5962R9578701VXC |
| HCS163KMSR | 5962R9580701VXC | PAL16R4A-2MJB | 8103614RA | PAL16L6 (GEN) | 5962-86804043A |
| HCTS163 (GEN) | 5962R9574301V9A | PAL16R4A-2MWB | 8103614SA | PAL16L6 (GEN) | 5962-8680404KA |
| HCTS163 (GEN) | 5962R9574301VEC | C16R4-20 (GEN) | 5962-8867812RA | PAL16L6 (GEN) | 5962-8680404LA |
| HCTS163 (GEN) | 5962R9574301VXC | C16R4-20 (GEN) | 5962-8867812SA | PAL16R6 (GEN) | 81036032A |
| Z16C3010GMB | 5962-9065701MXC | C16R4-20 (GEN) | 5962-8867812XA | PAL16R6 (GEN) | 8103603RA |
| DS1631H/883 | 5962-8863101GA | C16R4-20 (GEN) | 5962-8871312RA | PAL16R6AMFKB | 81036092A |
| DS1631J-8/883 | 5962-8863101PA | C16R4-20 (GEN) | 5962-8871312SA | PAL16R6AMJB | 8103609RA |
| QP1632/GA | 5962-9052201GA | C16R4-20 (GEN) | 5962-8871312XA | PAL16R6AMWB | 8103609SA |
| QP1632/GC | 5962-9052201GC | TIBPAL16R4-20MFKB | 5962-85155042A | 16R6-10 (GEN) | 5962-9233803MRA |
| QP1632/PA | 5962-9052201PA | TIBPAL16R4-20MJB | 5962-8515504RA | 16R6-10 (GEN) | 5962-9233803MSA |
| QP1632/XA | 5962-9052201XA | TIBPAL16R4-20MWB | 5962-8515504SA | 16R6-10 (GEN) | 5962-9233803MXA |
| QP1632/XC | 5962-9052201XC | C16R4-30 (GEN) | 5962-8867808RA | TIBPAL16R6-10MFKB | 5962-85155192A |
| UC1633 (GEN) | 5962-9098701MEA | C16R4-30 (GEN) | 5962-8867808SA | TIBPAL16R6-10MJB | 5962-8515519RA |
| DS1634 (GEN) | 5962-8982101GA | C16R4-30 (GEN) | 5962-8867808XA | TIBPAL16R6-10MWB | 5962-8515519SA |
| DS1634 (GEN) | 5962-8982101PA | C16R4-30 (GEN) | 5962-8871308RA | TIBPAL16R6-12MFKB | 5962-85155152A |
| UC1637J/883 | 5962-8995701VA | C16R4-30 (GEN) | 5962-8871308SA | TIBPAL16R6-12MJB | 5962-8515515RA |
| UC1637L/883 | 5962-89957012A | C16R4-30 (GEN) | 5962-8871308XA | TIBPAL16R6-12MWB | 5962-8515515SA |
| RHFAC16373K01Q | 5962F0421201QXC | TIBPAL16R4-30MFKB | 5962-85155082A | TIBPAL16R6-15MFKB | 5962-85155112A |
| RHFAC16373K01V | 5962F0421201VXC | TIBPAL16R4-30MJB | 5962-8515508RA | TIBPAL16R6-15MJB | 5962-8515511RA |
| RHFAC16373K02Q | 5962F0421201QXA | TIBPAL16R4-30MWB | 5962-8515508SA | TIBPAL16R6-15MWB | 5962-8515511SA |
| RHFAC16373K02V | 5962F0421201VXA | PAL16R4A-4 (GEN) | 85065042A | PAL16R6A-2MFKB | 81036132A |
| RHFAC16374K01Q | 5962F0421301QXC | PAL16R4A-4 (GEN) | 8506504RA | PAL16R6A-2MJB | 8103613RA |
| RHFAC16374K01V | 5962F0421301VXC | PAL16R4A-4 (GEN) | 8506504SA | PAL16R6A-2MWB | 8103613SA |
| RHFAC16374K02Q | 5962F0421301QXA | PAL16R4B-4 (GEN) | 5962-88515042A | PALC16R6-20DMB | 5962-8871311RA |
| RHFAC16374K02V | 5962F0421301VXA | PAL16R4B-4 (GEN) | 5962-8851504RA | PALC16R6-20KMB | 5962-8871311SA |
| HCS164 (GEN) | 5962R9578501V9A | PAL16R4B-4 (GEN) | 5962-8851504SA | PALC16R6-20LMB | 5962-8871311XA |
| HCS164 (GEN) | 5962R9578501VXC | SG1644J/883B | 5962-9165301MCA | PALC16R6-20QMB | 5962-8867811XA |
| HCS164DMSR | 5962R9578501VCC | SG1644L/883B | 5962-9165301M2A | PALC16R6-20TMB | 5962-8867811SA |
| HCTS164 (GEN) | 5962R9566301V9A | SG1644T/883B | 5962-9165301MGA | PALC16R6-20WMB | 5962-8867811RA |
| HCTS164DMSR | 5962R9566301VCC | SG1644Y/883B | 5962-9165301MPA | TIBPAL16R6-20MFKB | 5962-85155032A |
| HCTS164KMSR | 5962R9566301VXC | C16R4-40 (GEN) | 5962-8867804RA | TIBPAL16R6-20MJB | 5962-8515503RA |
| PAL16A4 (GEN) | 81036062A | C16R4-40 (GEN) | 5962-8867804SA | TIBPAL16R6-20MWB | 5962-8515503SA |
| PAL16A4 (GEN) | 8103606RA | C16R4-40 (GEN) | 5962-8867804XA | PALC16R6-30 KMB | 5962-8871307SA |
| PAL16R4 (GEN) | 81036042A | C16R4-40 (GEN) | 5962-8871304RA | PALC16R6-30DMB | 5962-8871307RA |
| PAL16R4 (GEN) | 8103604RA | C16R4-40 (GEN) | 5962-8871304SA | PALC16R6-30LMB | 5962-8871307XA |
| PAL16R4AMFKB | 81036102A | C16R4-40 (GEN) | 5962-8871304XA | PALC16R6-30QMB | 5962-8867807XA |
| PAL16R4AMJB | 8103610RA | 16R4-7 (GEN) | 5962-9233808MRA | PALC16R6-30TMB | 5962-8867807SA |
| PAL16R4AMWB | 8103610SA | 16R4-7 (GEN) | 5962-9233808MSA | PALC16R6-30WMB | 5962-8867807RA |
| PAL16X4 (GEN) | 81036052A | 16R4-7 (GEN) | 5962-9233808MXA | TIBPAL16R6-30MFKB | 5962-85155072A |
| PAL16X4 (GEN) | 8103605RA | TIBPAL16R4-7MFKB | 5962-85155222A | TIBPAL16R6-30MJB | 5962-8515507RA |
| 16R4-10 (GEN) | 5962-9233804MRA | TIBPAL16R4-7MJB | 5962-8515522RA | TIBPAL16R6-30MWB | 5962-8515507SA |
| 16R4-10 (GEN) | 5962-9233804MSA | TIBPAL16R4-7MWB | 5962-8515522SA | PAL16R6A-4 (GEN) | 85065032A |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

| Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN |
|---|---|---|---|---|---|
| PAL16R6A-4 (GEN) | 8506503RA | 16V8 (GEN) | 5962-8983903SA | GAL16V8D-30LD/883C | 5962-8983901RA |
| PAL16R6A-4 (GEN) | 8506503SA | 16V815 (GEN) | 5962-89839092A | PALC16L8-30DMB | 5962-8871305RA |
| PAL16R6B-4 (GEN) | 5962-88515032A | 16V815 (GEN) | 5962-8983909RA | PALC16L8-30KMB | 5962-8871305SA |
| PAL16R6B-4 (GEN) | 5962-8851503RA | 16V8L15 (GEN) | 5962-89839102A | PALC16L8-30LMB | 5962-8871305XA |
| PAL16R6B-4 (GEN) | 5962-8851503SA | 16V8L15 (GEN) | 5962-8983910RA | PALC16L8-30QMB | 5962-8867805XA |
| PALC16R6-40DMB | 5962-8871303RA | 16V8L-15 (GEN) | 5962-89839142A | PALC16L8-30TMB | 5962-8867805SA |
| PALC16R6-40KMB | 5962-8871303SA | 16V8L-15 (GEN) | 5962-8983914RA | PALC16L8-30WMB | 5962-8867805RA |
| PALC16R6-40LMB | 5962-8871303XA | GAL16V8D-15LD/883C | 5962-8983903RA | PALC16R8-30DMB | 5962-8871306RA |
| PALC16R6-40QMB | 5962-8867803XA | GAL16V8D-15LR/883C | 5962-89839032A | PALC16R8-30KMB | 5962-8871306SA |
| PALC16R6-40TMB | 5962-8867803SA | PALCE16V8-15DMB | 5962-8983913RA | PALC16R8-30LMB | 5962-8871306XA |
| PALC16R6-40WMB | 5962-8867803RA | PALCE16V8-15LMB | 5962-89839132A | PALC16R8-30QMB | 5962-8867806XA |
| 16R6-7 (GEN) | 5962-9233807MRA | TIBPAL16L8-15MFKB | 5962-85155092A | PALC16R8-30TMB | 5962-8867806SA |
| 16R6-7 (GEN) | 5962-9233807MSA | TIBPAL16L8-15MJB | 5962-8515509RA | PALC16R8-30WMB | 5962-8867806RA |
| 16R6-7 (GEN) | 5962-9233807MXA | TIBPAL16L8-15MWB | 5962-8515509SA | TIBPAL16L8-30MFKB | 5962-85155052A |
| MSK167B | 5962-9689701HXA | TIBPAL16R8-15MFKB | 5962-85155102A | TIBPAL16L8-30MJB | 5962-8515505RA |
| MSK167B | 5962-9689701HXC | TIBPAL16R8-15MJB | 5962-8515510RA | TIBPAL16L8-30MWB | 5962-8515505SA |
| MSK167B (GEN) | 5962-9689703HXA | TIBPAL16R8-15MWB | 5962-8515510SA | TIBPAL16R8-30MFKB | 5962-85155062A |
| MSK167B (GEN) | 5962-9689703HXC | PAL16L8A-2MFKB | 81036112A | TIBPAL16R8-30MJB | 5962-8515506RA |
| AD1671SQ/883B | 5962-9312601MXA | PAL16L8A-2MJB | 8103611RA | TIBPAL16R8-30MWB | 5962-8515506SA |
| AD1674TD/883B | 5962-9316401MXA | PAL16L8A-2MWB | 8103611SA | PAL16L8A-4 (GEN) | 85065012A |
| PAL16L8 (GEN) | 81036012A | PAL16R8A-2MFKB | 81036122A | PAL16L8A-4 (GEN) | 8506501RA |
| PAL16L8 (GEN) | 8103601RA | PAL16R8A-2MJB | 8103612RA | PAL16L8A-4 (GEN) | 8506501SA |
| PAL16L8AMFKB | 81036072A | PAL16R8A-2MWB | 8103612SA | PAL16L8B-4 (GEN) | 5962-88515012A |
| PAL16L8AMJB | 8103607RA | 16V8 (GEN) | 5962-8983902SA | PAL16L8B-4 (GEN) | 5962-8851501RA |
| PAL16L8AMWB | 8103607SA | 16V8 (GEN) | 5962-89839062A | PAL16L8B-4 (GEN) | 5962-8851501SA |
| PAL16R8 (GEN) | 81036022A | 16V8 (GEN) | 5962-8983906RA | PAL16R8A-4 (GEN) | 85065022A |
| PAL16R8 (GEN) | 8103602RA | GAL16V8D-20LD/883C | 5962-8983902RA | PAL16R8A-4 (GEN) | 8506502RA |
| PAL16R8AMFKB | 81036082A | GAL16V8D-20LR/883C | 5962-89839022A | PAL16R8A-4 (GEN) | 8506502SA |
| PAL16R8AMJB | 8103608RA | PALC16L8-20DMB | 5962-8871309RA | PAL16R8B-4 (GEN) | 5962-88515022A |
| PAL16R8AMWB | 8103608SA | PALC16L8-20KMB | 5962-8871309SA | PAL16R8B-4 (GEN) | 5962-8851502RA |
| PLS168/BLA | 5962-9201201MLA | PALC16L8-20LMB | 5962-8871309XA | PAL16R8B-4 (GEN) | 5962-8851502SA |
| 16L8-10 (GEN) | 5962-9233801MRA | PALC16L8-20QMB | 5962-8867809XA | PALC16L8-40DMB | 5962-8871301RA |
| 16L8-10 (GEN) | 5962-9233801MSA | PALC16L8-20TMB | 5962-8867809SA | PALC16L8-40KMB | 5962-8871301SA |
| 16L8-10 (GEN) | 5962-9233801MXA | PALC16L8-20WMB | 5962-8867809RA | PALC16L8-40LMB | 5962-8871301XA |
| 16R8-10 (GEN) | 5962-9233802MRA | PALC16R8-20DMB | 5962-8871310RA | PALC16L8-40QMB | 5962-8867801XA |
| 16R8-10 (GEN) | 5962-9233802MSA | PALC16R8-20KMB | 5962-8871310SA | PALC16L8-40TMB | 5962-8867801SA |
| 16R8-10 (GEN) | 5962-9233802MXA | PALC16R8-20LMB | 5962-8871310XA | PALC16L8-40WMB | 5962-8867801RA |
| 16V8-10 (GEN) | 5962-89839112A | PALC16R8-20QMB | 5962-8867810XA | PALC16R8-40DMB | 5962-8871302RA |
| 16V8-10 (GEN) | 5962-8983911RA | PALC16R8-20TMB | 5962-8867810SA | PALC16R8-40KMB | 5962-8871302SA |
| GAL16V8D-10LD/883C | 5962-8983904RA | PALC16R8-20WMB | 5962-8867810RA | PALC16R8-40LMB | 5962-8871302XA |
| GAL16V8D-10LR/883C | 5962-89839042A | TIBPAL16L8-20MFKB | 5962-85155012A | PALC16R8-40QMB | 5962-8867802XA |
| TIBPAL16L8-10MFKB | 5962-85155172A | TIBPAL16L8-20MJB | 5962-8515501RA | PALC16R8-40TMB | 5962-8867802SA |
| TIBPAL16L8-10MJB | 5962-8515517RA | TIBPAL16L8-20MWB | 5962-8515501SA | PALC16R8-40WMB | 5962-8867802RA |
| TIBPAL16L8-10MWB | 5962-8515517SA | TIBPAL16R8-20MFKB | 5962-85155022A | 16L8-7 (GEN) | 5962-9233805MRA |
| TIBPAL16R8-10MFKB | 5962-85155182A | TIBPAL16R8-20MJB | 5962-8515502RA | 16L8-7 (GEN) | 5962-9233805MSA |
| TIBPAL16R8-10MJB | 5962-8515518RA | TIBPAL16R8-20MWB | 5962-8515502SA | 16L8-7 (GEN) | 5962-9233805MXA |
| TIBPAL16R8-10MWB | 5962-8515518SA | 16V8 (GEN) | 5962-89839052A | 16R8-7 (GEN) | 5962-9233806MRA |
| TIBPAL16L8-12MFKB | 5962-85155132A | 16V8 (GEN) | 5962-8983905RA | 16R8-7 (GEN) | 5962-9233806MSA |
| TIBPAL16L8-12MJB | 5962-8515513RA | 16V8H25E4 (GEN) | 5962-89839012A | 16R8-7 (GEN) | 5962-9233806MXA |
| TIBPAL16L8-12MWB | 5962-8515513SA | 16V8L25 (GEN) | 5962-89839082A | GAL16V8D-7LD/883 | 5962-8983907RA |
| TIBPAL16R8-12MFKB | 5962-85155142A | 16V8L25 (GEN) | 5962-8983908RA | GAL16V8D-7LR/883 | 5962-89839072A |
| TIBPAL16R8-12MJB | 5962-8515514RA | 16V8L-25 (GEN) | 5962-89839122A | TIBPAL16R8-7MFKB | 5962-85155212A |
| TIBPAL16R8-12MWB | 5962-8515514SA | 16V8L-25 (GEN) | 5962-8983912RA | TIBPAL16R8-7MJB | 5962-8515521RA |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

| Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN |
|---|---|---|---|---|---|
| TIBPAL16R8-7MWB | 5962-8515521SA | TSC171 (GEN) | 5962-8963802EA | P1750A-15QLMB | 5962-8766501UA |
| LM169 (GEN) | 5962-9456101MGA | UC1710J883B | 5962-0152001QPA | UT1750AR16GCA | 5962-0150202QXA |
| CG1690AA (GEN) | 5962-9055502XA | UC1710JQMLV | 5962-0152001VPA | UT1750AR16GCAH | 5962H0150202QXA |
| CG1690BA (GEN) | 5962-9055501XA | UC1710JQMLV | 5962-0152001VXA | UT1750AR16GCAH | 5962H0150202VXA |
| CG1690CA (GEN) | 5962-9055503XA | IS0-1715ARH-Q | 5962F0052101V9A | UT1750AR16GCC | 5962-0150202QXC |
| DS1691AJ/883 | 5962-8672101EA | IS9-1715ARH-8 | 5962F0052101QXC | UT1750AR16GCCH | 5962H0150202QXC |
| DS16F95E/883 | 5962-89615012A | IS9-1715ARH-Q | 5962F0052101VXC | UT1750AR16GCCH | 5962H0150202VXC |
| DS16F95J/883 | 5962-8961501PA | IS9-1715ARH-T | 5962R0052101TXC | UT1750AR16WCC | 5962-0150202QYC |
| DS16F95JFQML | 5962F8961501QPA | UC1717 (GEN) | 5962-9474601M2A | UT1750AR16WCCH | 5962H0150202QYC |
| DS16F95JFQMLV | 5962F8961501VPA | UC1717 (GEN) | 5962-9474601MEA | UT1750AR16WCCH | 5962H0150202VYC |
| DS16F95J-QMLV | 5962-8961501VPA | LMU17 (GEN) | 5962-8768604TA | P1750A-20CMB | 5962-8766502XA |
| DS16F95W/883 | 5962-8961501HA | LMU17 (GEN) | 5962-8768604XA | P1750A-20GMB | 5962-8766502TA |
| DS16F95WFQML | 5962F8961501QHA | XC17256DDD8B | 5962-9561701MPA | P1750A-20PGMB | 5962-8766502ZA |
| DS16F95WFQMLV | 5962F8961501VHA | ASPLS173C24/883C | 5962-8850402LA | P1750A-20QGMB | 5962-8766502YA |
| DS16F95WG/883 | 5962-8961501QXA | PLS173/BLA | 5962-8850402LA | P1750A-20QLMB | 5962-8766502UA |
| DS16F95WGFQML | 5962F8961501QXA | LMU17 (GEN) | 5962-8768605TA | P1750AE-20CMB | 5962-8766505XA |
| DS16F95WGFQMLV | 5962F8961501VXA | LMU17 (GEN) | 5962-8768605XA | P1750AE-20GMB | 5962-8766505TA |
| DS16F95WG-QMLV | 5962-8961501VXA | SG1731J/883B | 5962-9669901MEA | P1750AE-20PGMB | 5962-8766505ZA |
| DS16F95W-QMLV | 5962-8961501VHA | ACS174 (GEN) | 5962F9863401V9A | P1750AE-20QGMB | 5962-8766505YA |
| OP-17A (GEN) | 5962-8770601GA | ACS174 (GEN) | 5962F9863401VEC | P1750AE-20QLMB | 5962-8766505UA |
| OP-17A (GEN) | 5962-8770601PA | ACS174 (GEN) | 5962F9863401VXC | P1750A-30CMB | 5962-8766503XA |
| OP-17B (GEN) | 5962-8770602GA | LMU17 (GEN) | 5962-8768606TA | P1750A-30GMB | 5962-8766503TA |
| OP-17B (GEN) | 5962-8770602PA | LMU17 (GEN) | 5962-8768606XA | P1750A-30PGMB | 5962-8766503ZA |
| TSC170 (GEN) | 5962-89638012A | GEM17401Q2A | 5962-88557012A | P1750A-30QGMB | 5962-8766503YA |
| TSC170 (GEN) | 5962-8963801EA | GEM17401Q2C | 5962-88557012C | P1750A-30QLMB | 5962-8766503UA |
| GEM17001Q2A | 78009012A | GEM17401QEA | 5962-8855701EA | P1750AE-30PGMB | 5962-8766506ZA |
| GEM17001Q2C | 78009012C | GEM17401QEC | 5962-8855701EC | P1750AE-30QGMB | 5962-8766506YA |
| GEM17001QEA | 7800901EA | GEM17401QFA | 5962-8855701FA | P1750AE-30QLMB | 5962-8766506UA |
| GEM17001QEC | 7800901EC | GEM17401QFC | 5962-8855701FC | P1750A-40CMB | 5962-8766504XA |
| GEM17001QFA | 7800901FA | ACS175 (GEN) | 5962F9863501V9A | P1750A-40GMB | 5962-8766504TA |
| GEM17001QFC | 7800901FC | ACS175 (GEN) | 5962F9863501VEC | P1750A-40PGMB | 5962-8766504ZA |
| XQ1701L-CC44B | 5962-9951401QYA | ACS175 (GEN) | 5962F9863501VXC | P1750A-40QGMB | 5962-8766504YA |
| XQ1701L-SO20N | 5962-9951401NXB | BX1750A (GEN) | 5962-8951901MUA | P1750A-40QLMB | 5962-8766504UA |
| UC1705J/883BC | 5962-9579801MPA | BX1750A (GEN) | 5962-8951902MUA | P1750AE-40PGMB | 5962-8766507ZA |
| UC1705JQMLV | 5962-9579801VPA | BX1750A (GEN) | 5962-8951903MUA | P1750AE-40QGMB | 5962-8766507YA |
| UC1705L/883BC | 5962-9579801M2A | BX1750A (GEN) | 5962-8951991MTA | P1750AE-40QLMB | 5962-8766507UA |
| UC1706J/883B | 5962-8961101EA | BX1750A (GEN) | 5962-8951992MTA | P1753-20CMB | 5962-8950504XA |
| UC1706L/883BC | 5962-89611012A | BX1750A (GEN) | 5962-8951993MTA | P1753-20GMB | 5962-8950504TA |
| UC1707J/80900 | 5962-8761901EA | RX1750-01 | 5962H9684701QYC | P1753-20PGMB | 5962-8950501ZA |
| UC1707JQMLV | 5962-8761901VEA | RX1750-02 | 5962H9684702QYC | P1753-20QGMB | 5962-8950501YA |
| UC1707L/81032 | 5962-87619012A | UT1750AR12GCA | 5962-0150201QXA | P1753-20QLMB | 5962-8950501UA |
| UC1707LQMLV | 5962-8761901V2A | UT1750AR12GCAH | 5962H0150201QXA | P1753-30CMB | 5962-8950505XA |
| UC1708J883B | 5962-0051401QPA | UT1750AR12GCAH | 5962H0150201VXA | P1753-30GMB | 5962-8950505TA |
| UC1708JE883B | 5962-0051401QEA | UT1750AR12GCAH | 5962H0150201VXC | P1753-30PGMB | 5962-8950502ZA |
| UC1708JEQMLV | 5962-0051401VEA | UT1750AR12GCC | 5962-0150201QXC | P1753-30QGMB | 5962-8950502YA |
| UC1708JQMLV | 5962-0051401VPA | UT1750AR12GCCH | 5962H0150201QXC | P1753-30QLMB | 5962-8950502UA |
| UC1708L883B | 5962-0051401Q2A | UT1750AR12WCC | 5962-0150201QYC | P1753-40CMB | 5962-8950506XA |
| UC1708LQMLV | 5962-0051401V2A | UT1750AR12WCCH | 5962H0150201QYC | P1753-40GMB | 5962-8950506TA |
| UC1709J883B | 5962-0151201QPA | UT1750AR12WCCH | 5962H0150201VYC | P1753-40PGMB | 5962-8950503ZA |
| UC1709JQMLV | 5962-0151201VPA | P1750A-15CMB | 5962-8766501XA | P1753-40QGMB | 5962-8950503YA |
| UC1709L883B | 5962-0151201Q2A | P1750A-15GMB | 5962-8766501TA | P1753-40QLMB | 5962-8950503UA |
| UC1709LQMLV | 5962-0151201V2A | P1750A-15PGMB | 5962-8766501ZA | P1754-20CMB | 5962-8864204XA |
| TSC171 (GEN) | 5962-89638022A | P1750A-15QGMB | 5962-8766501YA | P1754-20GMB | 5962-8864204TA |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART II, Listed By Generic PIN

| Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN |
|---|---|---|---|---|---|
| P1754-20PGMB | 5962-8864201ZA | LM1M8CRH-Q40X | 5962H9687701QXC | 1823B (GEN) | 5962-8990503EA |
| P1754-20QGMB | 5962-8864201YA | LM1M8CRH-V25X | 5962H9687705VXC | UC1823AJ/883BC | 5962-8990502EA |
| P1754-20QLMB | 5962-8864201UA | LM1M8CRH-V25Y | 5962H9687705VYC | UC1823AJQMLV | 5962-8990502VEA |
| P1754-30CMB | 5962-8864205XA | LM1M8CRH-V30X | 5962H9687703VXC | UC1823AL/883BC | 5962-89905022A |
| P1754-30GMB | 5962-8864205TA | LM1M8CRH-V30Y | 5962H9687703VYC | UC1823J/883BC | 5962-8990501EA |
| P1754-30PGMB | 5962-8864202ZA | LM1M8CRH-V40X | 5962H9687701VXC | UC1823L/883BC | 5962-89905012A |
| P1754-30QGMB | 5962-8864202YA | LM1M8TRH-Q25X | 5962H9687706QXC | SCAN18245TFMQB | 5962-9311501MXA |
| P1754-30QLMB | 5962-8864202UA | LM1M8TRH-Q25Y | 5962H9687706QYC | 1825A (GEN) | 5962-8768102XA |
| P1754-40CMB | 5962-8864206XA | LM1M8TRH-Q30X | 5962H9687704QXC | 1825B (GEN) | 5962-87681032A |
| P1754-40GMB | 5962-8864206TA | LM1M8TRH-Q30Y | 5962H9687704QYC | 1825B (GEN) | 5962-8768103EA |
| P1754-40PGMB | 5962-8864203ZA | LM1M8TRH-Q40X | 5962H9687702QXC | 1825B (GEN) | 5962-8768103XA |
| P1754-40QGMB | 5962-8864203YA | LM1M8TRH-V25X | 5962H9687706VXC | HS0-1825ARH-Q | 5962F9955801V9A |
| P1754-40QLMB | 5962-8864203UA | LM1M8TRH-V25Y | 5962H9687706VYC | HS1-1825ARH-8 | 5962F9955801QEC |
| LMU17 (GEN) | 5962-8768602TA | LM1M8TRH-V30X | 5962H9687704VXC | HS1-1825ARH-Q | 5962F9955801VEC |
| LMU17 (GEN) | 5962-8768602XA | LM1M8TRH-V30Y | 5962H9687704VYC | HS-1825A (GEN) | 5962R9955801TXC |
| LMU17 (GEN) | 5962-8768602ZA | LM1M8TRH-V40X | 5962H9687702VXC | HS4-1825ARH-8 | 5962F9955801Q2C |
| RTM1760-PGA | 5962-9553901HYC | DG180A (GEN) | 5962-8767301AA | HS4-1825ARH-Q | 5962F9955801V2C |
| RTS1760-PGA | 5962-9553902HYC | DG180AA/883 | 5962-8767301IA | HS9-1825ARH-8 | 5962F9955801QXC |
| UT1760ARTS (GEN) | 5962-8957501YA | DG180AL/883 | 5962-8767301XA | HS9-1825ARH-Q | 5962F9955801VXC |
| UT1760ARTS (GEN) | 5962-8957501ZA | DG180AP/883 | 5962-8767301CA | IS0-1825ASRH-Q | 5962F0251101V9A |
| UT1760ARTSGA | 5962-8957501XA | 1800-90 (GEN) | 5962-8854901XA | IS1-1825ASRH-Q | 5962F0251101VEC |
| UT1760ARTSGC | 5962-8957501XC | UCC1801J/883BC | 5962-9451301MPA | IS9-1825ASRH-Q | 5962F0251101VXC |
| GEM17601Q2A | 5962-87792012A | UCC1802J/883BC | 5962-9451302MPA | SG1825CJ/883B | 5962-8768101EA |
| GEM17601Q2C | 5962-87792012C | UCC1803J/883BC | 5962-9451303MPA | SG1825CL/883B | 5962-87681012A |
| GEM17601QEA | 5962-8779201EA | UCC1804J/883BC | 5962-9451304MPA | UC1825AJ/883B | 5962-8768102EA |
| GEM17601QEC | 5962-8779201EC | OM1805-03N2M/883B | 5962-87782032A | UC1825AJ/QMLV | 5962-8768102VEA |
| GEM17601QFA | 5962-8779201FA | OM1805SM/883B | 5962-8778201MA | UC1825AL/883B | 5962-87681022A |
| GEM17601QFC | 5962-8779201FC | OMR1805STM/883B | 5962F8778201UA | UC1825AL/QMLV | 5962-8768102V2A |
| XC1765DDD8B | 5962-9471701MPA | UCC1805J/883BC | 5962-9451305MPA | UC1825J/883B | 5962-8768101EA |
| HCPL-177K | 5962-9800201KEC | UCC1806J/883BC | 5962-9457501MEA | UC1825J/QMLV | 5962-8768101VEA |
| GEM17701B2A | 5962-88527012A | UCC1806JQMLV | 5962-9457501VEA | UC1825L/883B | 5962-87681012A |
| GEM17701B2C | 5962-88527012C | UCC1806L/883BC | 5962-9457501Q2A | UC1825L/QMLV | 5962-8768101V2A |
| GEM17701BEA | 5962-8852701EA | UCC1806LQMLV | 5962-9457501V2A | UC1825W/883B | 5962-8768101QFA |
| GEM17701BEC | 5962-8852701EC | 1810 (GEN) | 5962-8946901YC | IS1-1825ASRH-8 | 5962F0251101QEC |
| GEM17701BFA | 5962-8852701FA | OM1812N2/883B | 5962-87776012A | IS9-1825ASRH-8 | 5962F0251101QXC |
| GEM17701BFC | 5962-8852701FC | OM1812N5M | 5962-87776015A | UC1827J-1883B | 5962-9961901QJA |
| HCPL-177K#100 | 5962-9800201KYA | OM1812NK/883B | 5962-8777601YA | UC1827L-1883B | 5962-9961901Q3A |
| HCPL-177K#100 | 5962-9800201KYC | OM1812NM/883B | 5962-8777601NA | L1A8274 (GEN) | 5962-94A0201MYC |
| HCPL-177K#200 | 5962-9800201KEA | OM1812SM/883B | 5962-8777601MA | HI-1828A (GEN) | 5962-9762001Q2A |
| HCPL-177K#300 | 5962-9800201KXA | OM1812SRM | 5962-87776014A | HI-1828A (GEN) | 5962-9762001QEA |
| LMU17 (GEN) | 5962-8768603TA | OMR1812STM/883B | 5962F8777601UA | LM1M8C3VRH-Q30X | 5962H9861501QXC |
| LMU17 (GEN) | 5962-8768603XA | 7815A (GEN) | 5962-88553015A | LM1M8C3VRH-Q35X | 5962H9861502QXC |
| LMU17 (GEN) | 5962-8768603ZA | 7815A (GEN) | 5962-8855301MA | LM1M8C3VRH-V30X | 5962H9861501VXC |
| DS1776 (GEN) | 5962-9231701MXA | L1A8155 (GEN) | 5962-93A2201MYC | LM1M8C3VRH-V35X | 5962H9861502VXC |
| DS1776E/883 | 5962-9231701M3A | L1A8171 (GEN) | 5962-93A2101MYC | OM183SCM/883 | 5962-8952001YA |
| HCPL-177K#600 | 5962-9800201KZA | CT1820 (GEN) | 5962-9063601HXA | OM1830NCM | 5962-8952001ZA |
| HCPL-177K#600 | 5962-9800201KZC | CT1820 (GEN) | 5962-9063601HYA | OMR1830SCM/883B | 5962R8952001YA |
| ASPLS179C24/883C | 5962-8850701LA | LMD18200-2D/883 | 5962-9232501MXA | UC1832J/883BC | 5962-9326501MCA |
| PLS179/BLA | 5962-8850701LA | LMD18200-2D-QV | 5962-9232501VXA | UC1832JQMLV | 5962-9326501VCA |
| LM1M8CRH-Q25X | 5962H9687705QXC | CT1820-2 (GEN) | 5962-9063602HXA | UC1832L/883BC | 5962-9326501M2A |
| LM1M8CRH-Q25Y | 5962H9687705QYC | CT1820-2 (GEN) | 5962-9063602HYA | UC1832LQMLV | 5962-9326501V2A |
| LM1M8CRH-Q30X | 5962H9687703QXC | 1823 (GEN) | 7901801JA | UC1833 (GEN) | 5962-9326502M2A |
| LM1M8CRH-Q30Y | 5962H9687703QYC | 1823B (GEN) | 5962-89905032A | UC1833 (GEN) | 5962-9326502MPA |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART II, Listed By Generic PIN

| Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN |
|---|---|---|---|---|---|
| UC1834J/883B | 5962-8774201EA | UC1842J/883B | 5962-8670401PA | SG1845F/883B | 5962-8670404HA |
| UC1834JQMLV | 5962-8774201VEA | UC1842JQMLV | 5962-8670401VPA | SG1845J/883B | 5962-8670404CA |
| UC1834L/883B | 5962-87742012A | UC1842L/883B | 5962-8670401XA | SG1845L/883B | 5962-86704042A |
| UC1834LQMLV | 5962-8774201V2A | UC1842LQMLV | 5962-8670401VXA | SG1845Y/883B | 5962-8670404PA |
| UC1835 (GEN) | 5962-90650012A | UC1842W/883B | 5962-8670401DA | U18GM (GEN) | 5962-9452301MXA |
| UC1835 (GEN) | 5962-9065001PA | 1843 (GEN) | 5962-8670402EA | UC1845AJ/883B | 5962-8670408PA |
| UC1836J/883BC | 5962-9065002PA | 1843 (GEN) | 5962-8670402FA | UC1845AJQMLV | 5962-8670408VPA |
| UC1836L/883BC | 5962-90650022A | 1843 (GEN) | 5962-8670402V2A | UC1845AL/883B | 5962-8670408XA |
| SCAN18373TFMQB | 5962-9311801MXA | 1843A (GEN) | 5962-8670406V2A | UC1845ALQMLV | 5962-8670408VXA |
| SCAN18374TFMQB | 5962-9320701MXA | IP1843J-DESC | 5962-8670402PA | UC1845AW/883B | 5962-8670408DA |
| UC1838A (GEN) | 5962-89899012A | SG1843F/883B | 5962-8670402HA | UC1845J/883B | 5962-8670404PA |
| UC1838A (GEN) | 5962-8989901EA | SG1843J/883B | 5962-8670402CA | UC1845JQMLV | 5962-8670404VPA |
| 1HK84 (GEN) | 5962H92A0101QYC | SG1843L/883B | 5962-86704022A | UC1845L/883B | 5962-8670404XA |
| MSK 184G | 5962-9215202GXA | SG1843Y/883B | 5962-8670402PA | UC1845LQMLV | 5962-8670404VXA |
| MSK 184G | 5962-9215202GXC | UC1843AJ/883B | 5962-8670406PA | UC1845W/883B | 5962-8670404DA |
| OM184SCM/883 | 5962-8952101YA | UC1843AJQMLV | 5962-8670406VPA | SG1846F/883B | 5962-8680601FA |
| OMR1840SCM/883B | 5962R8952101YA | UC1843AL/883B | 5962-8670406XA | SG1846J/883B | 5962-8680601EA |
| PAL18L4 (GEN) | 5962-86804013A | UC1843ALQMLV | 5962-8670406VXA | SG1846L/883B | 5962-86806012A |
| PAL18L4 (GEN) | 5962-8680401KA | UC1843AW/883B | 5962-8670406DA | UC1846J/883B | 5962-8680601EA |
| PAL18L4 (GEN) | 5962-8680401LA | UC1843J/883B | 5962-8670402PA | UC1846JQMLV | 5962-8680601VEA |
| 1840 (GEN) | 5962R9563001QXC | UC1843JQMLV | 5962-8670402VPA | UC1846L/883B | 5962-86806012A |
| 1840 (GEN) | 5962R9563001QYC | UC1843L/883B | 5962-8670402XA | UC1846LQMLV | 5962-8680601V2A |
| 1840 (GEN) | 5962R9563001VXC | UC1843LQMLV | 5962-8670402VXA | 1847 (GEN) | 5962-8680602FA |
| 1840 (GEN) | 5962R9563001VYC | UC1843W/883B | 5962-8670402DA | UC1847 (GEN) | 5962-86806022A |
| HS0-1840ARH-Q | 5962F9563002V9A | 1844 (GEN) | 5962-8670403EA | UC1847 (GEN) | 5962-8680602EA |
| HS1-1840ARH-8 | 5962F9563002QXC | 1844 (GEN) | 5962-8670403FA | LM185B (GEN) | 5962-9091401M2A |
| HS1-1840ARH-Q | 5962F9563002VXC | 1844 (GEN) | 5962-8670403V2A | LM185BYH/883 | 5962-9091401MXA |
| HS1-1840ARH-T | 5962R9563002TXC | 1844A (GEN) | 5962-8670407V2A | OM185STM/883 | 5962-8864601UA |
| HS1-1840RH (GEN) | 5962D8753801XA | IP1844J-DESC | 5962-8670403PA | OM1850N5M | 5962-8864601TA |
| HS9-1840ARH-8 | 5962F9563002QYC | SG1844F/883B | 5962-8670403HA | OM1850NKM/883B | 5962-8864601XA |
| HS9-1840ARH-Q | 5962F9563002VYC | SG1844J/883B | 5962-8670403CA | OM1850NMM | 5962-8864601NA |
| HS9-1840ARH-T | 5962R9563002TYC | SG1844L/883B | 5962-86704032A | OM1850NMM | 5962-8864601NB |
| HS9-1840RH (GEN) | 5962D8753801YA | SG1844Y/883B | 5962-8670403PA | OM1850SRM | 5962-8864601MA |
| OM1840NCM | 5962-8952101ZA | UC1844AJ/883B | 5962-8670407PA | OMR1850STM/883 | 5962L8864601UA |
| OM1840NKM/883B | 5962-8952101XA | UC1844AJQMLV | 5962-8670407VPA | UC1851 (GEN) | 5962-9558601MVA |
| UC1840J/883 | 5962-8992001VA | UC1844AL/883B | 5962-8670407XA | UC1851L/883BC | 5962-9558601M2A |
| UC1840L/883 | 5962-89920012A | UC1844ALQMLV | 5962-8670407VXA | LM185BX1.2 (GEN) | 5962-8759403XA |
| UC1841 (GEN) | 5962-89920022A | UC1844AW/883B | 5962-8670407DA | LM185BYH1.2/883 | 5962-8759405XA |
| UC1841 (GEN) | 5962-8992002VA | UC1844J/883B | 5962-8670403PA | LM185E1.2/883 | 5962-87594012A |
| 1842 (GEN) | 5962-8670401EA | UC1844JQMLV | 5962-8670403VPA | LM185H-1.2/883 | 5962-8759401XA |
| 1842 (GEN) | 5962-8670401FA | UC1844L/883B | 5962-8670403XA | LM185WG-1.2/883 | 5962-8759401YA |
| 1842 (GEN) | 5962-8670401V2A | UC1844LQMLV | 5962-8670403VXA | LM185WG-1.2-QV | 5962-8759401VYA |
| 1842A (GEN) | 5962-8670405V2A | UC1844W/883B | 5962-8670403DA | UC1852J/883B | 5962-9763001QPA |
| IP1842J-DESC | 5962-8670401PA | 1845 (GEN) | 5962-8670404EA | LM185-2.5 (GEN) | 5962-87594022A |
| SG1842F/883B | 5962-8670401HA | 1845 (GEN) | 5962-8670404FA | LM185BX2.5 (GEN) | 5962-8759404XA |
| SG1842J/883B | 5962-8670401CA | 1845 (GEN) | 5962-8670404V2A | LM185BYH2.5/883 | 5962-8759406XA |
| SG1842L/883B | 5962-86704012A | 1845A (GEN) | 5962-8670408V2A | LM185BYH2.5-QV | 5962-8759406VXA |
| SG1842Y/883B | 5962-8670401PA | IP1845J-DESC | 5962-8670404PA | LM185H-2.5/883 | 5962-8759402XA |
| UC1842AJ/883B | 5962-8670405PA | IS0-1845ASRH-Q | 5962F0150901V9A | LM185WG-2.5/883 | 5962-8759402YA |
| UC1842AJQMLV | 5962-8670405VPA | IS7-1845ASRH-8 | 5962F0150901QPC | LM185WG-2.5-QV | 5962-8759402VYA |
| UC1842AL/883B | 5962-8670405XA | IS7-1845ASRH-Q | 5962F0150901VPC | 1853 (GEN) | 7901901EA |
| UC1842ALQMLV | 5962-8670405VXA | IS9-1845ASRH-8 | 5962F0150901QXC | 1854 (GEN) | 7901701QA |
| UC1842AW/883B | 5962-8670405DA | IS9-1845ASRH-Q | 5962F0150901VXC | UC1854 (GEN) | 5962-9326101M2A |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

| Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN |
|---|---|---|---|---|---|
| UC1854A (GEN) | 5962-9326103M2A | GEM18902Q3C | 5962-88516023C | RDC-19222S-113 | 5962-0325104HYC |
| UC1854A (GEN) | 5962-9326103MEA | GEM18902QKA | 5962-8851602KA | RDC-19222-143 | 5962-0325102HYA |
| UC1854B (GEN) | 5962-9326102M2A | GEM18902QKC | 5962-8851602KC | RDC-19222S-143 | 5962-0325104HYA |
| UC1854BJ/883BC | 5962-9326102MEA | GEM18902QLA | 5962-8851602LA | HCS193 (GEN) | 5962R9578801V9A |
| UC1854J/883BC | 5962-9326101MEA | GEM18902QLC | 5962-8851602LC | HCS193 (GEN) | 5962R9578801VEC |
| SCAN18540TFMQB | 5962-9312701MXA | HCS190 (GEN) | 5962R9580801V9A | HCS193 (GEN) | 5962R9578801VXC |
| SCAN18541TFMQB | 5962-9311601MXA | HCS190 (GEN) | 5962R9580801VEC | HCTS193 (GEN) | 5962R9575701V9A |
| UC1856J883B | 5962-9453001MEA | HCS190 (GEN) | 5962R9580801VXC | HCTS193 (GEN) | 5962R9575701VEC |
| UC1856L20883B | 5962-9453001M2A | HCTS190 (GEN) | 5962R9577101V9A | HCTS193KMSR | 5962R9575701VXC |
| OM186ST/883B | 5962-8998101UA | HCTS190 (GEN) | 5962R9577101VEC | LM193 (GEN) | 5962-9452601M2A |
| OM186STZM/883B | 5962-8998101ZA | HCTS190 (GEN) | 5962R9577101VXC | LM193AH/883 | 5962-9452602MGA |
| OM1860N5M/883B | 5962-8998101TA | MSK1901B | 5962-9324601HXA | LM193AH-QMLV | 5962-9452602VGA |
| OM1860NKM/883B | 5962-8998101XA | MSK1901B | 5962-9324601HXC | LM193AJ/883 | 5962-9452602MPA |
| OM1860SRM/883B | 5962-8998101MA | UC1901J/883B | 5962-8944101CA | LM193AJ-QMLV | 5962-9452602VPA |
| UC1863J/883 | 5962-9203103QEA | UC1901JQMLV | 5962-8944101VCA | LM193FKB | 5962-9452601Q2A |
| UC1863JQMLV | 5962-9203103VEA | UC1901L/883B | 5962-89441012A | LM193JGB | 5962-9452601QPA |
| UC1863L/883 | 5962-9203103Q2A | MSK-1902B-0 (GEN) | 5962-8997201HXA | TLC193MDQ | 5962-9555101NXD |
| UC1863LQMLV | 5962-9203103V2A | MSK-1902B-0 (GEN) | 5962-8997201HXC | TLC193MJGB | 5962-9555101QPA |
| UC1864 (GEN) | 5962-9203101M2A | MSK-1902B-2 (GEN) | 5962-8997202HXA | GEM19303QKA | 5962-8860503QKA |
| UC1864 (GEN) | 5962-9203101MEA | MSK-1902B-2 (GEN) | 5962-8997202HXC | GEM19303QKC | 5962-8860503QKC |
| UC1865 (GEN) | 5962-9203102MEA | UC1903J/883B | 5962-8869701VA | GEM19303QLA | 5962-8860503QLA |
| UC1871 (GEN) | 5962-9462201M2A | UC1903L/883B | 5962-88697012A | GEM19303QLC | 5962-8860503QLC |
| UC1871 (GEN) | 5962-9462201MVA | MSK-1903B-0 (GEN) | 5962-9324301HXA | HCPL-1931 | 5962-8957201EC |
| UC1875 (GEN) | 5962-9455501MXA | MSK-1903B-2 (GEN) | 5962-9324302HXA | HCPL-1931#100 | 5962-8957201YA |
| UC1875J/883BC | 5962-9455501MRA | OM1905N2/883B | 5962-88746012A | HCPL-1931#100 | 5962-8957201YC |
| UC1875JQMLV | 5962-9455501VRA | OM1905SM/883B | 5962-8874601MA | HCPL-1931#200 | 5962-8957201EA |
| UC1875L/883BC | 5962-9455501M3A | OM1905STM/883B | 5962F8874601UA | HCPL-1931#300 | 5962-8957201XA |
| UC1875LQMLV | 5962-9455501V3A | UC1907 (GEN) | 5962-9320601M2A | HCPL-193K | 5962-8957202KEC |
| PAL18P8A (GEN) | 5962-87528012A | UC1907 (GEN) | 5962-9320601MEA | HCPL-193K#100 | 5962-8957202KYA |
| PAL18P8A (GEN) | 5962-8752801RA | HCTS191 (GEN) | 5962R9575601V9A | HCPL-193K#100 | 5962-8957202KYC |
| PAL18P8A (GEN) | 5962-8752801SA | HCTS191DMSR | 5962R9575601VEC | HCPL-193K#200 | 5962-8957202KEA |
| PAL18P8AL (GEN) | 5962-87528032A | HCTS191KMSR | 5962R9575601VXC | HCPL-193K#300 | 5962-8957202KXA |
| PAL18P8AL (GEN) | 5962-8752803RA | OM1912N2/883B | 5962-88747012A | LM194H/883 | 5962-8777701XA |
| PAL18P8AL (GEN) | 5962-8752803SA | OM1912N5M/883B | 5962-88747015A | GEM19401Q3A | 5962-88516013A |
| PAL18P8B (GEN) | 5962-87528022A | OM1912NK/883B | 5962-8874701YA | GEM19401Q3C | 5962-88516013C |
| PAL18P8B (GEN) | 5962-8752802RA | OM1912NMM/883B | 5962-8874701NA | GEM19401QKA | 5962-8851601KA |
| PAL18P8B (GEN) | 5962-8752802SA | OM1912SMM/883B | 5962-8874701MA | GEM19401QKC | 5962-8851601KC |
| PAL18P8L (GEN) | 5962-87528042A | OM1912SRM/883B | 5962-88747014A | GEM19401QLA | 5962-8851601LA |
| PAL18P8L (GEN) | 5962-8752804RA | OM1912STM/883B | 5962-8874701UA | GEM19401QLC | 5962-8851601LC |
| PAL18P8L (GEN) | 5962-8752804SA | OMR1912STM/883B | 5962F8874701UA | HCS195 (GEN) | 5962R9578901V9A |
| PAL18P8Q (GEN) | 5962-87528052A | SDP7912ANMD | 5962-8874701NA | HCS195 (GEN) | 5962R9578901VEC |
| PAL18P8Q (GEN) | 5962-8752805RA | OM1915N2/883B | 5962-88748012A | HCS195 (GEN) | 5962R9578901VXC |
| PAL18P8Q (GEN) | 5962-8752805SA | OM1915N5M/883B | 5962-88748015A | LM195H/883 | 5962-8777801XA |
| GEM18802Q2A | 85126022A | OM1915NK/883B | 5962-8874801YA | LM195K/883 | 5962-8777801YA |
| GEM18802Q2C | 85126022C | OM1915NM/883B | 5962-8874801NA | GEM19501Q2A | 5962-87534012A |
| GEM18802QBA | 8512602BA | OM1915SM/883B | 5962-8874801MA | GEM19501Q2C | 5962-87534012C |
| GEM18802QBC | 8512602BC | OM1915SRM/883B | 5962-88748014A | GEM19501QEA | 5962-8753401EA |
| GEM18802QCA | 8512602CA | OMR1915STM/883B | 5962F8874801UA | GEM19501QEC | 5962-8753401EC |
| GEM18802QCC | 8512602CC | RDC-19220-113 | 5962-0325101HXC | GEM19501QFA | 5962-8753401FA |
| GEM18802QDA | 8512602DA | RDC-19220S-113 | 5962-0325103HXC | GEM19501QFC | 5962-8753401FC |
| GEM18802QDC | 8512602DC | RDC-19220-143 | 5962-0325101HXA | LF198H/883 | 5962-8760801GA |
| DG189AP/883 | 5962-9068901MEA | RDC-19220S-143 | 5962-0325103HXA | LF198WG/883 | 5962-8760801QZA |
| GEM18902Q3A | 5962-88516023A | RDC-19222-113 | 5962-0325102HYC | LF198WG-QMLV | 5962-8760801VZA |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

| Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN |
|---|---|---|---|---|---|
| GEM19804Q2A | 78015042A | ACTS20 (GEN) | 5962F9565902VXC | PAL20C1 (GEN) | 5962-8680406LA |
| GEM19804Q2C | 78015042C | EL2002 (GEN) | 5962-90509022A | 2010 (GEN) | 5962-87530013A |
| GEM19804QEA | 7801504EA | EL2002 (GEN) | 5962-9050902PA | 20RA10 (GEN) | 5962-9212101M3A |
| GEM19804QEC | 7801504EC | EL2002A (GEN) | 5962-90509012A | 20RA10 (GEN) | 5962-9212101MLA |
| GEM19804QFA | 7801504FA | EL2002A (GEN) | 5962-9050901PA | 20RA10 (GEN) | 5962-9212102M3A |
| GEM19804QFC | 7801504FC | EL2003 (GEN) | 5962-89623012A | 20RA10 (GEN) | 5962-9212102MLA |
| P4C198A-15DMB | 5962-8989106LA | EL2003 (GEN) | 5962-8962301GA | HR2010 (GEN) | 5962H94A0304Q5C |
| P4C198A-15LMB | 5962-8989106XA | EL2003 (GEN) | 5962-8962301PA | HR2010 (GEN) | 5962H94A0304Q7C |
| P4C198AL-15DMB | 5962-8989105LA | 2004 (GEN) | 5962-8771202XA | HR2010 (GEN) | 5962H94A0304QNC |
| P4C198AL-15LMB | 5962-8989105XA | 2004 (GEN) | 5962-8771202YA | HR2010 (GEN) | 5962H94A0304V5C |
| P4C198A-20DMB | 5962-8989104LA | EL2004 (GEN) | 5962-8965901XA | HR2010 (GEN) | 5962H94A0304V7C |
| P4C198AL-20DMB | 5962-8989103LA | EL2004 (GEN) | 5962-8965901XC | HR2010 (GEN) | 5962H94A0304VNC |
| P4C198A-25DMB | 5962-8989102LA | EL2004 (GEN) | 5962-8965901YA | HR2010 (GEN) | 5962H99B0204QXC |
| P4C198AL-25DMB | 5962-8989101LA | 2004-25 (GEN) | 5962-8771201XA | HR2010 (GEN) | 5962H99B0204VXC |
| LM199 (GEN) | 5962-8856102XA | 2004-25 (GEN) | 5962-8771201YA | HS-RTX2010 (GEN) | 5962F9563501V9A |
| LM199AH/883 | 5962-8856101XA | HDSR2006-34H/2 | 5962-9464603HXC | HS-RTX2010 (GEN) | 5962F9563501VXC |
| CT1990-1-20 | 5962-9477501HXA | HDSR2006-34S/2 | 5962-9464604HXC | HS-RTX2010 (GEN) | 5962F9563501VYC |
| CT1990-1-20 | 5962-9477501HXC | HDSR2006-34V/R/2 | 5962-9464602HXC | PAL20L10A (GEN) | 84129053A |
| LM199A-20 (GEN) | 5962-8856103XA | HDSR2006-34V/S/2 | 5962-9464601HXC | PAL20L10A (GEN) | 8412905KA |
| DAC-HKB-2/883B | 5962-8952802XA | LMA2009-55 (GEN) | 5962-9099604MYA | PAL20L10A (GEN) | 8412905LA |
| DAC-HKB-2/883B | 5962-8952802XC | LMA2009-65 (GEN) | 5962-9099603MYA | PAL20L10A (GEN) | 8412905XA |
| MG2RTPL (GEN) | 5962-03B0101QXC | LMA2009-95 (GEN) | 5962-9099602MYA | PAL20RA10 (GEN) | 5962-86803013A |
| MG2RTPL (GEN) | 5962-03B0102QXC | TMC2009 (GEN) | 5962-9099601MXA | PAL20RA10 (GEN) | 5962-8680301KA |
| ACS20 (GEN) | 5962F9565301VCC | TMC2009 (GEN) | 5962-9099601MYA | PAL20RA10 (GEN) | 5962-8680301LA |
| ACS20 (GEN) | 5962F9565301VXC | TMC2009 (GEN) | 5962-9099601MZA | PAL20X10A (GEN) | 84129073A |
| ACTS20 (GEN) | 5962F9565901VCC | ADG201HST (GEN) | 5962-8671603VEA | PAL20X10A (GEN) | 8412907KA |
| ACTS20 (GEN) | 5962F9565901VXC | ADG201HSTE/883B | 5962-86716032A | PAL20X10A (GEN) | 8412907LA |
| HCS20 (GEN) | 5962R9577801V9A | ADG201HSTQ/883B | 5962-8671603EA | PAL20X10A (GEN) | 8412907XA |
| HCS20 (GEN) | 5962R9577801VCC | CLC201A (GEN) | 5962-9083301HXA | C20RA10-20 (GEN) | 5962-9055503KA |
| HCS20 (GEN) | 5962R9577801VXC | DG201A (GEN) | 7705301FA | C20RA10-20 (GEN) | 5962-9098903M3A |
| HCTS20 (GEN) | 5962R9573301V9A | DG201AAK/883 | 7705301EA | C20RA10-20 (GEN) | 5962-9098903MLA |
| HCTS20 (GEN) | 5962R9573301VCC | DG201AAK/883B | 7705301EA | PLDC20RA10-20DMB | 5962-9055503LA |
| HCTS20KMSR | 5962R9573301VXC | DG201AAL/883 | 7705301XA | PLDC20RA10-20LMB | 5962-90555033A |
| CLC200A (GEN) | 5962-8991001XA | DG201AAL/883B | 7705301XC | C20RA10-25 (GEN) | 5962-9055502KA |
| DG200A (GEN) | 5962-9562901QIA | DG201AAZ/883B | 77053012C | C20RA10-25 (GEN) | 5962-9098902M3A |
| DG200AAK/883 | 5962-9562901QCA | DG201HSAK/883 | 5962-8671601EA | C20RA10-25 (GEN) | 5962-9098902MLA |
| OP-200A (GEN) | 5962-88593012A | DG201HSAZ/883 | 5962-86716012A | PLDC20RA10-25DMB | 5962-9055502LA |
| OP-200A (GEN) | 5962-8859301PA | HI1-201/883B | 7705302EA | PLDC20RA10-25LMB | 5962-90555023A |
| OP-200ARC/883 | 5962-8859301M2A | HI1-201HS/883 | 5962-8671601EA | 20G10-30 (GEN) | 5962-8863702KA |
| OP-200AZ/883 | 5962-8859301MPA | HI4-201/883 | 77053022A | PLDC20G10-30DMB | 5962-8863702LA |
| OP200AZ/QML | 5962-8859301V2A | HI4-201/883B | 77053022C | PLDC20G10-30LMB | 5962-88637023A |
| OP200AZ/QML | 5962-8859301VPA | HI4-201HS/883 | 5962-86716012A | C20RA10-35 (GEN) | 5962-90555013A |
| UT200*QCR | 5962R96B0216Q*C | HS0-201HSRH-Q | 5962F9961801V9A | C20RA10-35 (GEN) | 5962-9055501KA |
| UT200*VCR | 5962R96B0216V*C | HS1-201HSRH-8 | 5962F9961801QEC | C20RA10-35 (GEN) | 5962-9055501LA |
| EL2001 (GEN) | 5962-9153402M2A | HS1-201HSRH-Q | 5962F9961801VEC | C20RA10-35 (GEN) | 5962-9098901MLA |
| EL2001 (GEN) | 5962-9153402MPA | HS1-201HSRH-T | 5962R9961801TEC | 20G10-40 (GEN) | 5962-88637013A |
| EL2001A (GEN) | 5962-9153401M2A | HS9-201HSRH-8 | 5962F9961801QXC | 20G10-40 (GEN) | 5962-8863701KA |
| EL2001A (GEN) | 5962-9153401MPA | HS9-201HSRH-Q | 5962F9961801VXC | 20G10-40 (GEN) | 5962-8863701LA |
| ACS20 (GEN) | 5962F9565302V9A | HS9-201HSRH-T | 5962R9961801TXC | 1010-55 (GEN) | 5962-8873301YA |
| ACS20 (GEN) | 5962F9565302VCC | MG2RTPL_M01 | 5962-00B0301Q*C | 1010-65 (GEN) | 5962-8873302YA |
| ACS20 (GEN) | 5962F9565302VXC | MG2RTPL_M01 | 5962-00B0301V*C | 1010-75 (GEN) | 5962-8873303YA |
| ACTS20 (GEN) | 5962F9565902V9A | PAL20C1 (GEN) | 5962-86804063A | HS-RTX2010 (GEN) | 5962F9563501QXC |
| ACTS20 (GEN) | 5962F9565902VCC | PAL20C1 (GEN) | 5962-8680406KA | HS-RTX2010 (GEN) | 5962F9563501QYC |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

| Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN |
|---|---|---|---|---|---|
| TMC2011V (GEN) | 5962-89446013A | TMC2023C3V3 | 5962-89711043A | EL2041 (GEN) | 5962-87785022A |
| TMC2011V (GEN) | 5962-8944601LA | TMC2023J2V3 | 5962-8971104LA | EL2041 (GEN) | 5962-8778502CA |
| EP2015 (GEN) | 5962-89775012A | TMC2023J7V3 | 5962-8971104JA | EL2041 (GEN) | 5962-8778502XA |
| EP2015 (GEN) | 5962-8977501CA | TLE2024 (GEN) | 5962-9088103BCA | TIBPAL20R4-10MFKB | 5962-87671183A |
| EP2015A (GEN) | 5962-89775022A | TLE2024AMFKB | 5962-9088106Q2A | TIBPAL20R4-10MJTB | 5962-8767118LA |
| EP2015A (GEN) | 5962-8977502CA | TLE2024AMJB | 5962-9088106QCA | TIBPAL20R4-10MWB | 5962-8767118KA |
| EN2016 (GEN) | 5962-89776012A | TLE2024BMFKB | 5962-9088109Q2A | PAL20R4-12 (GEN) | 5962-8767114LA |
| EN2016 (GEN) | 5962-8977601CA | TLE2024BMJB | 5962-9088109QCA | PAL20R4-12 (GEN) | 5962-87671143A |
| EN2016A (GEN) | 5962-89776022A | TLE2024MFKB | 5962-9088103M2A | PAL20L4-15 (GEN) | 5962-87671103A |
| EN2016A (GEN) | 5962-8977602CA | TLE2024MJB | 5962-9088103MCA | PAL20R4-15 (GEN) | 5962-8767110LA |
| TGC2016 | 5962-96B0101Q*A | TLE2027AMFKB | 5962-9089603Q2A | PAL20R4A-2 (GEN) | 84129123A |
| TGC2016 | 5962-97B0101Q*A | TLE2027AMJGB | 5962-9089603QPA | PAL20R4A-2 (GEN) | 8412912KA |
| EL2018 (GEN) | 5962-9175501MGA | TLE2027M (GEN) | 5962-9089601BPA | PAL20R4A-2 (GEN) | 8412912LA |
| EL2018 (GEN) | 5962-9175501MPA | TLE2027M (GEN) | 5962-9089601MGA | TIBPAL20R4-20MFDB | 5962-87671043A |
| 2018-100 (GEN) | 5962-8863805XC | TLE2027MFKB | 5962-9089601M2A | TIBPAL20R4-20MJTB | 5962-8767104LA |
| 2018-33 (GEN) | 5962-8863802XC | TLE2027MJGB | 5962-9089601MPA | TIBPAL20R4-20MJTB | 8412904LA |
| 2018-50 (GEN) | 5962-8863803XC | TLE2037AM (GEN) | 5962-9089604QPA | TIBPAL20R4-20MWB | 5962-8767104KA |
| 2018-70 (GEN) | 5962-8863804XC | EL2030 (GEN) | 5962-9081801M2A | TIBPAL20R4-20MWB | 8412904KA |
| EL2019 (GEN) | 5962-9212801MGA | EL2030 (GEN) | 5962-9081801MCA | TIBPAL20R4-20MXB | 8412904XA |
| EL2019 (GEN) | 5962-9212801MPA | TGC2030 | 5962-96B0103Q*A | MG2044 | 5962-00B0209Q*C |
| TGC2019 | 5962-96B0102Q*A | TGC2030 | 5962-97B0103Q*A | MG2044E | 5962-00B0201Q*C |
| TGC2019 | 5962-97B0102Q*A | EL2033 (GEN) | 5962-8962302PA | MG2044E | 5962-00B0201V*C |
| MG2RTPL_MB02 | 5962-00B0302Q*C | TGC2036 | 5962-96B0104Q*A | MG2044E | 5962-02B0101QXC |
| MG2RTPL_MB02 | 5962-00B0302V*C | TGC2036 | 5962-97B0104Q*A | MG2044E | 5962-02B0101VXC |
| PAL20L2 (GEN) | 5962-86804053A | TLE2037M (GEN) | 5962-9089602M2A | MG2044P | 5962-00B0303Q*C |
| PAL20L2 (GEN) | 5962-8680405KA | TLE2037M (GEN) | 5962-9089602MGA | MG2044P | 5962-00B0303V*C |
| PAL20L2 (GEN) | 5962-8680405LA | TLE2037M (GEN) | 5962-9089602MPA | MG2M044 | 5962-00B0223Q*C |
| TLE2021 (GEN) | 5962-9088101MGA | EL2038 (GEN) | 5962-9153501M2A | MG2M044E | 5962-00B0216Q*C |
| TLE2021AMFKB | 5962-9088104Q2A | EL2038 (GEN) | 5962-9153501MCA | MG2M044E | 5962-00B0216V*C |
| TLE2021AMJGB | 5962-9088104QPA | EL2039 (GEN) | 5962-87787022A | MM0-G2044*MQ | 5962-00B0209Q9A |
| TLE2021BMFKB | 5962-9088107Q2A | EL2039 (GEN) | 5962-8778702CA | MM0-G2044EH*MQ | 5962-00B0201Q9A |
| TLE2021BMJGB | 5962-9088107QPA | PAL20R4A (GEN) | 84129043A | MM0-G2044PH*MQ | 5962-00B0303Q9A |
| TLE2021MFKB | 5962-9088101M2A | PAL20R4A (GEN) | 8412904JA | MM0-G2M044*MQ | 5962-00B0223Q9A |
| TLE2021MJGB | 5962-9088101MPA | PAL20X4A (GEN) | 84129083A | MM0-G2M044EH*MQ | 5962-00B0216Q9A |
| TLE2022 (GEN) | 5962-9088102BPA | PAL20X4A (GEN) | 8412908KA | MMKN-MG2044PHxxxM | 5962-03B0103QYC |
| TLE2022 (GEN) | 5962-9088102MGA | PAL20X4A (GEN) | 8412908LA | MMKU-MG2044PHxxxM | 5962-03B0103QXC |
| TLE2022AMFKB | 5962-9088105Q2A | PAL20X4A (GEN) | 8412908XA | MMKW-G2044PHxxxM | 5962-03B0103QZC |
| TLE2022AMJGB | 5962-9088105QPA | EL-2040 (GEN) | 5962-89648022A | SM0-G2044EH*SV | 5962-00B0201V9A |
| TLE2022BMFKB | 5962-9088108Q2A | EL-2040 (GEN) | 5962-8964802CA | SM0-G2044PH*SV | 5962-00B0303V9A |
| TLE2022BMJGB | 5962-9088108QPA | HX2040 | 5962H96B0305QXC | SM0-G2M044EH*SV | 5962-00B0216V9A |
| TLE2022MFKB | 5962-9088102M2A | HX2040 | 5962H96B0305VXC | SMF7-G2044PHxxxSR | 5962R00B0303VNC |
| TLE2022MJGB | 5962-9088102MPA | HX2040 | 5962H97B0305Q4C | SMFW-G2044PHxxxSR | 5962R00B0303V4C |
| SG2023F/883B | 5962-8987601FA | HX2040 | 5962H97B0305QUC | SMKN-MG2044PHxxxS | 5962R03B0103VYC |
| SG2023J/883B | 5962-8987601EA | HX2040 | 5962H97B0305QXC | SMKN-MG2044PHxxxS | 5962-03B0103VYC |
| TMC2023C3V | 5962-89711013A | HX2040 | 5962H97B0305QYC | SMKU-MG2044PHxxxS | 5962R03B0103VXC |
| TMC2023C3V1 | 5962-89711023A | HX2040 | 5962H97B0305QZC | SMKU-MG2044PHxxxS | 5962-03B0103VXC |
| TMC2023J2V | 5962-8971101LA | HX2040 | 5962H97B0305V4C | SMKW-G2044PHxxxSR | 5962R03B0103VZC |
| TMC2023J2V1 | 5962-8971102LA | HX2040 | 5962H97B0305VUC | SMKW-G2044PHxxxSV | 5962-03B0103VZC |
| TMC2023J7V | 5962-8971101JA | HX2040 | 5962H97B0305VXC | TGC2046 | 5962-96B0105Q*A |
| TMC2023J7V1 | 5962-8971102JA | HX2040 | 5962H97B0305VYC | TGC2046 | 5962-97B0105Q*A |
| TMC2023C3V2 | 5962-89711033A | HX2040 | 5962H97B0305VZC | TLE2074MWB | 5962-9460203QDA |
| TMC2023J2V2 | 5962-8971103LA | HX2040R | 5962H96B0310QXC | CLC205A (GEN) | 5962-9083501HXA |
| TMC2023J7V2 | 5962-8971103JA | HX2040R | 5962H96B0310VXC | TGC2053 | 5962-96B0106Q*A |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

| Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN |
|---|---|---|---|---|---|
| TGC2053 | 5962-97B0106Q*A | HR2065 (GEN) | 5962H94A0305Q4C | TMC208K | 5962-8873905XA |
| HDSR2056-34H/2 | 5962-9464607HXC | HR2065 (GEN) | 5962H94A0305Q6C | TMC208K | 5962-8873906QA |
| HDSR2056-34S/2 | 5962-9464608HXC | HR2065 (GEN) | 5962H94A0305Q8C | TMC208K | 5962-8873906XA |
| HDSR2056-34V/R/2 | 5962-9464606HXC | HR2065 (GEN) | 5962H94A0305QZC | TMC208KU | 5962-8873903QA |
| HDSR2056-34V/S/2 | 5962-9464605HXC | HR2065 (GEN) | 5962H94A0305V4C | TMC208KU | 5962-8873903XA |
| 2056P-34H/2 (GEN) | 5962-9155903HXC | HR2065 (GEN) | 5962H94A0305V6C | TMC208KU | 5962-8873904QA |
| 2056P-34S/2 (GEN) | 5962-9155904HXC | HR2065 (GEN) | 5962H94A0305V8C | TMC208KU | 5962-8873904XA |
| 2056P-34VR/2 (GEN) | 5962-9155901HXC | HR2065 (GEN) | 5962H94A0305VZC | TMC208KU | 5962-8873907QA |
| 2056P-34VS/2 (GEN) | 5962-9155902HXC | HR2065 (GEN) | 5962H99B0205QXC | TMC208KU | 5962-8873907XA |
| CLC206A (GEN) | 5962-8985801XA | HR2065 (GEN) | 5962H99B0205VXC | TMC208KU | 5962-8873908QA |
| PAL20R6A (GEN) | 84129033A | TGC2068 | 5962-96B0107Q*A | TMC208KU | 5962-8873908XA |
| PAL20R6A (GEN) | 8412903JA | TGC2068 | 5962-97B0107Q*A | HX2080 | 5962H96B0301QUC |
| TLE2061AMFKB | 5962-9080702Q2A | 2069 (GEN) | 5962-8753201EA | HX2080 | 5962H96B0301QZC |
| TLE2061AMJGB | 5962-9080702QPA | SP-2069 | 5962-8877601XA | HX2080 | 5962H96B0301V8C |
| TLE2061AMUB | 5962-9080702QHA | SP-2069 | 5962-8877601XC | HX2080 | 5962H96B0301VUC |
| TLE2061BMJGB | 5962-9080703QPA | CLC207A (GEN) | 5962-9097701HXA | HX2080 | 5962H96B0301VZC |
| TLE2061M (GEN) | 5962-9080701MGA | 2070 (GEN) | 5962-8753202EA | HX2080 | 5962H97B0301QM |
| TLE2061MFKB | 5962-9080701M2A | TLE2071AMFKB | 5962-9460204Q2A | HX2080 | 5962H97B0301QXC |
| TLE2061MJGB | 5962-9080701MPA | TLE2071AMJGB | 5962-9460204QPA | HX2080 | 5962H97B0301QZC |
| TLE2061MUB | 5962-9080701MHA | TLE2071AMUB | 5962-9460204QHA | HX2080 | 5962H97B0301VMC |
| TIBPAL20R6-10MFKB | 5962-87671173A | TLE2071MFKB | 5962-9460201Q2A | HX2080 | 5962H97B0301VXC |
| TIBPAL20R6-10MJTB | 5962-8767117LA | TLE2071MJGB | 5962-9460201QPA | HX2080 | 5962H97B0301VZC |
| TIBPAL20R6-10MWB | 5962-8767117KA | TLE2071MUB | 5962-9460201QHA | HX2080R | 5962H96B0306QUC |
| PAL20R6-12 (GEN) | 5962-87671133A | EL2072 (GEN) | 5962-8997502PA | HX2080R | 5962H96B0306QZC |
| PAL20R6-12 (GEN) | 5962-8767113LA | TLE2072AMFKB | 5962-9460205Q2A | HX2080R | 5962H96B0306VUC |
| PAL20R6-15 (GEN) | 5962-87671093A | TLE2072AMJGB | 5962-9460205QPA | HX2080R | 5962H96B0306VZC |
| PAL20R6-15 (GEN) | 5962-8767109LA | TLE2072AMUB | 5962-9460205QHA | GAL20V8B-10LD/883C | 5962-8984004LA |
| PAL20L6A-2 (GEN) | 84129113A | TLE2072MFKB | 5962-9460202Q2A | GAL20V8B-10LR/883C | 5962-89840043A |
| PAL20R6A-2 (GEN) | 8412911KA | TLE2072MJGB | 5962-9460202QPA | TIBPAL20L8-10MFKB | 5962-87671153A |
| PAL20R6A-2 (GEN) | 8412911LA | TLE2072MUB | 5962-9460202QHA | TIBPAL20L8-10MWB | 5962-8767115KA |
| TLE2062AMFKB | 5962-9080802Q2A | TLE2071AMWB | 5962-9460204QDA | TIBPAL20R8-10MFKB | 5962-87671163A |
| TLE2062AMJGB | 5962-9080802QPA | TLE2074AMFKB | 5962-9460206Q2A | TIBPAL20R8-10MJTB | 5962-8767116LA |
| TLE2062AMUB | 5962-9080802QHA | TLE2074AMJB | 5962-9460206QCA | TIBPAL20R8-10MWB | 5962-8767116KA |
| TLE2062BMJGB | 5962-9080803QPA | TLE2074AMWB | 5962-9460206QDA | TIBPSL20L8-10MJTB | 5962-8767115LA |
| TLE2062M (GEN) | 5962-9080801MGA | TLE2074MFKB | 5962-9460203Q2A | PAL20L8-12 (GEN) | 5962-87671113A |
| TLE2062MFKB | 5962-9080801M2A | TLE2074MJB | 5962-9460203QCA | PAL20L8-12 (GEN) | 5962-8767111LA |
| TLE2062MJGB | 5962-9080801MPA | PAL20L8A (GEN) | 84129013A | PAL20R8-12 (GEN) | 5962-87671123A |
| TLE2062MUB | 5962-9080801MHA | PAL20L8A (GEN) | 8412901JA | PAL20R8-12 (GEN) | 5962-8767112LA |
| TIBPAL20R6-20MFDB | 5962-87671033A | PAL20R8A (GEN) | 84129023A | GAL20V8B-15LD/883C | 5962-8984003LA |
| TIBPAL20R6-20MJT | 8412903LA | PAL20R8A (GEN) | 8412902JA | GAL20V8B-15LR/883C | 5962-89840033A |
| TIBPAL20R6-20MJTB | 5962-8767103LA | PAL20X8A (GEN) | 84129063A | PAL20L8-15 (GEN) | 5962-87671073A |
| TIBPAL20R6-20MWB | 5962-8767103KA | PAL20X8A (GEN) | 8412906KA | PAL20L8-15 (GEN) | 5962-8767107LA |
| TIBPAL20R6-20MWB | 8412903KA | PAL20X8A (GEN) | 8412906LA | PAL20R8-15 (GEN) | 5962-87671083A |
| TIBPAL20R6-20MXB | 8412903XA | PAL20X8A (GEN) | 8412906XA | PAL20R8-15 (GEN) | 5962-8767108LA |
| TLE2064 (GEN) | 5962-9080901BCA | PLUS20L8 (GEN) | 5962-87671053A | PAL20L8A-2 (GEN) | 84129093A |
| TLE2064AMFKB | 5962-9080902M2A | PLUS20L8 (GEN) | 5962-8767105KA | PAL20L8A-2 (GEN) | 8412909KA |
| TLE2064AMJB | 5962-9080902MCA | PLUS20L8 (GEN) | 5962-8767105LA | PAL20L8A-2 (GEN) | 8412909LA |
| TLE2064AMWB | 5962-9080902MDA | PLUS20R8 (GEN) | 5962-87671063A | PAL20R8A-2 (GEN) | 84129103A |
| TLE2064BMFKB | 5962-9080903Q2A | PLUS20R8 (GEN) | 5962-8767106KA | PAL20R8A-2 (GEN) | 8412910KA |
| TLE2064BMJB | 5962-9080903QCA | PLUS20R8 (GEN) | 5962-8767106LA | PAL20R8A-2 (GEN) | 8412910LA |
| TLE2064MFKB | 5962-9080901M2A | TMC208K | 5962-8873901QA | TMC208KC2V | 5962-8873901XA |
| TLE2064MJB | 5962-9080901MCA | TMC208K | 5962-8873902QA | GAL20V8B-20LD/883C | 5962-8984002LA |
| TLE2064MWB | 5962-9080901MDA | TMC208K | 5962-8873905QA | GAL20V8B-20LR/883C | 5962-89840023A |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

| Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN |
|---|---|---|---|---|---|
| TIBPAL20L8-20MFDB | 5962-87671013A | HS9-2100 (GEN) | 5962F9953601QXC | TLE2141AMJGB | 5962-9321602QPA |
| TIBPAL20L8-20MJTB | 5962-8767101LA | HS9-2100 (GEN) | 5962F9953601VXC | TLE2141MFKB | 5962-9321601Q2A |
| TIBPAL20L8-20MJTB | 8412901LA | HS9-2100 (GEN) | 5962R9953601TXC | TLE2141MJGB | 5962-9321601QPA |
| TIBPAL20L8-20MWB | 5962-8767101KA | IS0-2100ARH-Q | 5962F9953602V9A | MG2142P | 5962-00B0304Q*C |
| TIBPAL20L8-20MWB | 8412901KA | IS9-2100ARH-8 | 5962F9953602QXC | MG2142P | 5962-00B0304V*C |
| TIBPAL20L8-20MXB | 8412901XA | IS9-2100ARH-Q | 5962F9953602VXC | MM0-G2142PH*MQ | 5962-00B0304Q9A |
| TIBPAL20R8-20MFDB | 5962-87671023A | 21002 (GEN) | 5962-9560501HXA | MMKN-G2142PHxxxMQ | 5962-03B0104QYC |
| TIBPAL20R8-20MJTB | 5962-8767102LA | 21005 (GEN) | 5962-9560502HXA | MMKW-G2142PHxxxM | 5962-03B0104QZC |
| TIBPAL20R8-20MJTB | 8412902LA | 21007 (GEN) | 5962-9560503HXA | SM0-G2142PH*SV | 5962-00B0304V9A |
| TIBPAL20R8-20MWB | 5962-8767102KA | 21010 (GEN) | 5962-9560504HXA | SMF7-G2142PHxxxSR | 5962R00B0304VNC |
| TIBPAL20R8-20MWB | 8412902KA | 21015 (GEN) | 5962-9560505HXA | SMF9-G2142PHxxxSR | 5962R00B0304V5C |
| TIBPAL20R8-20MXB | 8412902XA | 21020 (GEN) | 5962-9560506HXA | SMFW-G2142PHxxxSR | 5962R00B0304V4C |
| TMC208KC2V1 | 5962-8873902XA | TSC21020F-20MBMQ | 5962-9953901QXC | SMKN-G2142PHxxxSR | 5962R03B0104VYC |
| 20V8B-30 (GEN) | 5962-89840013A | TSC21020F-20SBSV | 5962-9953901VXC | SMKN-G2142PHxxxSV | 5962-03B0104VYC |
| 20V8B-30 (GEN) | 5962-8984001LA | 21025 (GEN) | 5962-9560507HXA | SMKW-G2142PHxxxSR | 5962R03B0104VZC |
| TGC2086 | 5962-96B0108Q*A | TSB21LV03CMHVB | 5962-9677101QXA | SMKW-G2142PHxxxSV | 5962-03B0104VZC |
| TGC2086 | 5962-97B0108Q*A | ADSP21060-160 (GEN) | 5962-9674502QTC | SMKZ-G2142PHxxxSR | 5962R00B0304V6C |
| TIBPAL20R8-7MFKB | 5962-87671193A | ADSP21060-160 (GEN) | 5962-9674502QUC | TLE2142AMFKB | 5962-9321604Q2A |
| TIBPAL20R8-7MJTB | 5962-8767119LA | ADSP21060-160 (GEN) | 5962-9674502QXC | TLE2142AMJGB | 5962-9321604QPA |
| TIBPAL20R8-7MWB | 5962-8767119KA | ADSP21060-160 (GEN) | 5962-9674502QYC | TLE2142AMUB | 5962-9321604QHA |
| HR2090 (GEN) | 5962H94A0306QTC | ADSP21060L-148 (GEN | 5962-9674402QUC | TLE2142MFKB | 5962-9321603Q2A |
| HR2090 (GEN) | 5962H94A0306VTC | ADSP21060L-148 (GEN | 5962-9674402QYC | TLE2142MJGB | 5962-9321603QPA |
| HR2090 (GEN) | 5962H99B0206QXC | TMC2111V (GEN) | 5962-89446023A | TLE2142MUB | 5962-9321603QHA |
| HR2090 (GEN) | 5962H99B0206VXC | TMC2111V (GEN) | 5962-8944602LA | TLE2144AMFKB | 5962-9321606Q2A |
| MG2091 | 5962-00B0210Q*C | 21C11-20 (GEN) | 5962-9679306M3A | TLE2144AMJB | 5962-9321606QCA |
| MG2091E | 5962-00B0202Q*C | 21C11-20 (GEN) | 5962-9679306MLA | TLE2144MFKB | 5962-9321605Q2A |
| MG2091E | 5962-00B0202V*C | 21C11-25 (GEN) | 5962-9679305M3A | TLE2144MJB | 5962-9321605QCA |
| MG2M091 | 5962-00B0224Q*C | 21C11-25 (GEN) | 5962-9679305MLA | OP215A (GEN) | 5962-8853801GA |
| MG2M091E | 5962-00B0217Q*C | 21C11-30 (GEN) | 5962-9679304M3A | OP215AJ/QMLR | 5962R8853801VGA |
| MG2M091E | 5962-00B0217V*C | 21C11-30 (GEN) | 5962-9679304MLA | OP215AJ/QMLV | 5962-8853801VGA |
| MM0-G2091*MQ | 5962-00B0210Q9A | TGC2113 | 5962-96B0109Q*A | OP215ARC/883C | 5962-88538012A |
| MM0-G2091EH*MQ | 5962-00B0202Q9A | TGC2113 | 5962-97B0109Q*A | OP215ARC/QMLR | 5962R8853801V2A |
| MM0-G2M091*MQ | 5962-00B0224Q9A | HR2125 (GEN) | 5962H94A0301QTC | OP215ARC/QMLV | 5962-8853801V2A |
| MM0-G2M091EH*MQ | 5962-00B0217Q9A | HR2125 (GEN) | 5962H94A0301QUC | OP215AZ/883 | 5962-8853801PA |
| SM0-G2091EH*SV | 5962-00B0202V9A | HR2125 (GEN) | 5962H94A0301QYC | OP215AZ/QMLR | 5962R8853801VPA |
| SM0-G2M091EH*SV | 5962-00B0217V9A | HR2125 (GEN) | 5962H94A0301VTC | OP215AZ/QMLV | 5962-8853801VPA |
| ACS21 (GEN) | 5962F9862901V9A | HR2125 (GEN) | 5962H94A0301VUC | OP215B (GEN) | 5962-8853802PA |
| ACS21 (GEN) | 5962F9862901VCC | HR2125 (GEN) | 5962H94A0301VYC | OP215BJ/883 | 5962-8853802GA |
| ACS21 (GEN) | 5962F9862901VXC | HR2125 (GEN) | 5962H99B0201QXC | OP215BR (GEN) | 5962-88538032A |
| HCS21 (GEN) | 5962R9577901V9A | HR2125 (GEN) | 5962H99B0201VXC | TGC2154 | 5962-96B0110Q*A |
| HCS21 (GEN) | 5962R9577901VCC | MG2140 | 5962-00B0211Q*C | TGC2154 | 5962-97B0110Q*A |
| HCS21 (GEN) | 5962R9577901VXC | MG2140E | 5962-00B0203Q*C | HX2160 | 5962H96B0302Q4C |
| HCTS21 (GEN) | 5962R9576601V9A | MG2140E | 5962-00B0203V*C | HX2160 | 5962H96B0302Q6C |
| HCTS21 (GEN) | 5962R9576601VCC | MG2M140 | 5962-00B0225Q*C | HX2160 | 5962H96B0302QTC |
| HCTS21 (GEN) | 5962R9576601VXC | MG2M140E | 5962-00B0218Q*C | HX2160 | 5962H96B0302QUC |
| DG201AAZ/883 | 77053012A | MG2M140E | 5962-00B0218V*C | HX2160 | 5962H96B0302QZC |
| 2100AS (GEN) | 5962-8773503XC | MM0-G2140*MQ | 5962-00B0211Q9A | HX2160 | 5962H96B0302V4C |
| 2100AT (GEN) | 5962-8773504XC | MM0-G2140EH*MQ | 5962-00B0203Q9A | HX2160 | 5962H96B0302V6C |
| 2100AU (GEN) | 5962-8773505XC | MM0-G2M140*MQ | 5962-00B0225Q9A | HX2160 | 5962H96B0302VTC |
| 2100AV (GEN) | 5962-8773506XC | MM0-G2M140EH*MQ | 5962-00B0218Q9A | HX2160 | 5962H96B0302VUC |
| 2100S (GEN) | 5962-8773501XC | SM0-G2140EH*SV | 5962-00B0203V9A | HX2160 | 5962H96B0302VZC |
| 2100T (GEN) | 5962-8773502XA | SM0-G2M140EH*SV | 5962-00B0218V9A | HX2160 | 5962H97B0302QXC |
| HS0-2100 (GEN) | 5962F9953601V9A | TLE2141AMFKB | 5962-9321602Q2A | HX2160 | 5962H97B0302QZC |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

| Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN |
|---|---|---|---|---|---|
| HX2160 | 5962H97B0302VXC | EL-2190 (GEN) | 5962-8778402XA | 22021812-012 | 5962H98A2901QXC |
| HX2160 | 5962H97B0302VZC | TGC2191 | 5962-96B0111Q*A | 22021812-050 | 5962H98A2902QXC |
| HX2160R | 5962H96B0307Q4C | TGC2191 | 5962-97B0111Q*A | 22022256-012 | 5962H98A3201QXC |
| HX2160R | 5962H96B0307V4C | MG2194 | 5962-00B0212Q*C | 22022256-050 | 5962H98A3202QXC |
| TLE2161AMFKB | 5962-9095802Q2A | MG2194E | 5962-00B0204Q*C | 22022600-012 | 5962H98A3201QTC |
| TLE2161AMJGB | 5962-9095802QPA | MG2194E | 5962-00B0204V*C | 22022600-050 | 5962H98A3202QTC |
| TLE2161BMFKB | 5962-9095803Q2A | MG2M194 | 5962-00B0226Q*C | 22022979-012 | 5962H98A2601QTC |
| TLE2161BMJGB | 5962-9095803QPA | MG2M194E | 5962-00B0219Q*C | 22022979-050 | 5962H98A2602QTC |
| TLE2161MFKB | 5962-9095801Q2A | MG2M194E | 5962-00B0219V*C | TMC2208 (GEN) | 5962-9070801XA |
| TLE2161MJGB | 5962-9095801QPA | MM0-G2194*MQ | 5962-00B0212Q9A | CLC221A (GEN) | 5962-9083601HXA |
| WF2M16-120DAQ5 | 5962-9761002HXA | MM0-G2194EH*MQ | 5962-00B0204Q9A | 22V10A (GEN) | 5962-9176007M3A |
| WF2M16-120DAQ5 | 5962-9761002HXC | MM0-G2M194*MQ | 5962-00B0226Q9A | 22V10B (GEN) | 5962-9176008M3A |
| WF2M16-120DAQE5 | 5962-9761005HXA | MM0-G2M194EH*MQ | 5962-00B0219Q9A | 22V10G-7 (GEN) | 5962-9176009M3A |
| WF2M16-120DAQE5 | 5962-9761005HXC | SM0-G2194EH*SV | 5962-00B0204V9A | 22VP10G-7 (GEN) | 5962-9176010M3A |
| WF2M16-150DAQ5 | 5962-9761001HXA | SM0-G2M194EH*SV | 5962-00B0219V9A | ABT22V10A/BLA | 5962-9176007MLA |
| WF2M16-150DAQ5 | 5962-9761001HXC | CLC220A (GEN) | 5962-8991101XA | ABT22V10B/BLA | 5962-9176008MLA |
| WF2M16-150DAQE5 | 5962-9761004HXA | MAX220MJE/883B | 5962-9456501MEA | C22V10L (GEN) | 5962-8872404KA |
| WF2M16-150DAQE5 | 5962-9761004HXC | MAX220MLP/883B | 5962-9456501M2C | HR2210 (GEN) | 5962H94A0302QTC |
| 2167-40 (GEN) | 8200704XA | 22009751-007 (GEN) | 5962H94A0901QYC | HR2210 (GEN) | 5962H94A0302QUC |
| 2167-45 (GEN) | 8200704RA | 22009751-007 (GEN) | 5962H94A0901VYC | HR2210 (GEN) | 5962H94A0302QXC |
| 2167-55 (GEN) | 8200703RA | TLC2201AMFKB | 5962-9088203Q2A | HR2210 (GEN) | 5962H94A0302QYC |
| 2167-55 (GEN) | 8200703XA | TLC2201AMJGB | 5962-9088203QPA | HR2210 (GEN) | 5962H94A0302VTC |
| 2167-70 (GEN) | 8200702RA | TLC2201M (GEN) | 5962-9088201MGA | HR2210 (GEN) | 5962H94A0302VUC |
| 2167-70 (GEN) | 8200702XA | TLC2201MFKB | 5962-9088201M2A | HR2210 (GEN) | 5962H94A0302VXC |
| 2168-45 (GEN) | 5962-8608105RA | TLC2201MJGB | 5962-9088201MPA | HR2210 (GEN) | 5962H94A0302VYC |
| 2168-45 (GEN) | 5962-8608105XA | EP220-12 (GEN) | 5962-8863503RA | HR2210 (GEN) | 5962H99B0202QXC |
| 2168-55 (GEN) | 5962-8608101RA | EP220-15 (GEN) | 5962-8863502RA | HR2210 (GEN) | 5962H99B0202VXC |
| 2168-55 (GEN) | 5962-8608101XA | 22017140-005 (GEN) | 5962H94A2001QXC | PAL22V10 (GEN) | 5962-86053023A |
| 2168-70 (GEN) | 5962-8608102RA | 22017253-008 (GEN) | 5962H94A2101QYC | PAL22V10 (GEN) | 5962-8605302KA |
| 2168-70 (GEN) | 5962-8608102XA | 22017351 (GEN) | 5962H93A1601VYC | PAL22V10 (GEN) | 5962-8605302LA |
| WF2M16-90DAQ5 | 5962-9761003HXA | 22017393-006 | 5962H96A1401QXC | PAL22V10AMJTB | 5962-8605301LA |
| WF2M16-90DAQ5 | 5962-9761003HXC | 22017396-006 (GEN) | 5962H96A1301QXC | PAL22V10AMWB | 5962-8605301KA |
| WF2M16-90DAQE5 | 5962-9761006HXA | 22017399-006 | 5962H96A1501QXC | TIBPAL22V10AMFKB | 5962-86053013A |
| WF2M16-90DAQE5 | 5962-9761006HXC | 22017974-006 (GEN) | 5962H96A1601QXC | UT22VP10E-15PCA | 5962H9475407QLA |
| 2169-40 (GEN) | 5962-8608106RA | TLC2202AMFKB | 5962-9088204Q2A | UT22VP10E-15PCA | 5962H9475407VLA |
| 2169-40 (GEN) | 5962-8608106XA | TLC2202AMJGB | 5962-9088204QPA | UT22VP10E-15PCC | 5962H9475407QLC |
| 2169-50 (GEN) | 5962-8608103RA | TLC2202M (GEN) | 5962-9088202MGA | UT22VP10E-15PCC | 5962H9475407VLC |
| 2169-50 (GEN) | 5962-8608103XA | TLC2202MFKB | 5962-9088202M2A | UT22VP10E-15UCA | 5962H9475407QXA |
| 2169-70 (GEN) | 5962-8608104RA | TLC2202MJGB | 5962-9088202MPA | UT22VP10E-15UCA | 5962H9475407VXA |
| 2169-70 (GEN) | 5962-8608104XA | 22021540-012 | 5962H98A2401QTC | UT22VP10E-15UCC | 5962H9475407QXC |
| EL2171 (GEN) | 5962-8997302PA | 22021540-050 | 5962H98A2402QTC | UT22VP10E-15UCC | 5962H9475407VXC |
| LMU17 (GEN) | 5962-8768604UA | 22021712-012 | 5962H98A3101QXC | UT22VP10E-15WCA | 5962H9475407QYA |
| LMU17 (GEN) | 5962-8768604YA | 22021712-050 | 5962H98A3102QXC | UT22VP10E-15WCA | 5962H9475407VYA |
| LMU17 (GEN) | 5962-8768605UA | 22021718-012 | 5962H98A3001QXC | UT22VP10E-15WCC | 5962H9475407QYC |
| LMU17 (GEN) | 5962-8768605YA | 22021718-050 | 5962H98A3002QXC | UT22VP10E-15WCC | 5962H9475407VYC |
| LMU17 (GEN) | 5962-8768606UA | 22021730-012 | 5962H98A2701QTC | UT22VP10E-20PCA | 5962H9475406QLA |
| LMU17 (GEN) | 5962-8768606YA | 22021730-050 | 5962H98A2702QTC | UT22VP10E-20PCA | 5962H9475406VLA |
| LMU17 (GEN) | 5962-8768602UA | 22021745-012 | 5962H98A2501QXC | UT22VP10E-20PCC | 5962H9475406QLC |
| LMU17 (GEN) | 5962-8768602YA | 22021745-050 | 5962H98A2502QXC | UT22VP10E-20PCC | 5962H9475406VLC |
| LMU17 (GEN) | 5962-8768603UA | 22021752-012 | 5962H98A2301QTC | UT22VP10E-20UCA | 5962H9475406QXA |
| LMU17 (GEN) | 5962-8768603YA | 22021752-050 | 5962H98A2302QTC | UT22VP10E-20UCA | 5962H9475406VXA |
| EL-2190 (GEN) | 5962-87784022A | 22021806-012 | 5962H98A2801QXC | UT22VP10E-20UCC | 5962H9475406QXC |
| EL-2190 (GEN) | 5962-8778402CA | 22021806-050 | 5962H98A2802QXC | UT22VP10E-20UCC | 5962H9475406VXC |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

| Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN |
|---|---|---|---|---|---|
| UT22VP10E-20WCA | 5962H9475406QYA | 22V10G-12 (GEN) | 5962-9176002M3A | C22V10L (GEN) | 5962-8975504KA |
| UT22VP10E-20WCA | 5962H9475406VYA | 22VP10G-12 (GEN) | 5962-9176005M3A | GAL22V10C-20LD/883 | 5962-8984102LA |
| UT22VP10E-20WCC | 5962H9475406QYC | PAL22V10-12 (GEN) | 5962-86053053A | GAL22V10C-20LR/883 | 5962-89841023A |
| UT22VP10E-20WCC | 5962H9475406VYC | PAL22V10-12 (GEN) | 5962-8605305KA | GAL22V10D-20LD/883 | 5962-8984102LA |
| UT22VP10E-25PCA | 5962H9475405QLA | PAL22V10-12 (GEN) | 5962-8605305LA | GAL22V10D-20LR/883 | 5962-89841023A |
| UT22VP10E-25PCA | 5962H9475405VLA | 22V10G-15 (GEN) | 5962-9176001M3A | PALC22V10B-20DMB | 5962-8867004LA |
| UT22VP10E-25PCC | 5962H9475405QLC | 22VP10G-15 (GEN) | 5962-9176004M3A | PALC22V10B-20DMB | 5962-8867004LA |
| UT22VP10E-25PCC | 5962H9475405VLC | ATF22V10B-15GM/883 | 5962-8984103LA | PALC22V10B-20KMB | 5962-8867004KA |
| UT22VP10E-25UCA | 5962H9475405QXA | ATF22V10B-15GM/883 | 5962-8984105LA | PALC22V10B-20KMB | 5962-8867004KA |
| UT22VP10E-25UCA | 5962H9475405VXA | ATF22V10B-15NM/883 | 5962-89841033A | PALC22V10B-20LMB | 5962-88670043A |
| UT22VP10E-25UCC | 5962H9475405QXC | ATF22V10B-15NM/883 | 5962-89841053A | PALC22V10B-20LMB | 5962-88670043A |
| UT22VP10E-25UCC | 5962H9475405VXC | DPA22V10-15LC | 5962-8984103LC | PALC22V10B-20QMB | 5962-87539043A |
| UT22VP10E-25WCA | 5962H9475405QYA | GAL22V10C-15LD/883 | 5962-8984103LA | PALC22V10B-20TMB | 5962-8753904KA |
| UT22VP10E-25WCA | 5962H9475405VYA | GAL22V10C-15LR/883 | 5962-89841033A | PALC22V10B-20WMB | 5962-8753904LA |
| UT22VP10E-25WCC | 5962H9475405QYC | GAL22V10D-15LD/883 | 5962-8984103LA | PALC22V10B-20WMB | 5962-8753904LA |
| UT22VP10E-25WCC | 5962H9475405VYC | GAL22V10D-15LR/883 | 5962-89841033A | PALC22V10D-20DMB | 5962-8984102LA |
| UT22VP10T-15PCA | 5962H9475408QLA | PALC22V10B-15DMB | 5962-8867005LA | PALC22V10D-20DMB | 5962-8984108LA |
| UT22VP10T-15PCA | 5962H9475408VLA | PALC22V10B-15DMB | 5962-8867005LA | PALC22V10D-20KMB | 5962-8984102KA |
| UT22VP10T-15PCC | 5962H9475408QLC | PALC22V10B-15KMB | 5962-8867005KA | PALC22V10D-20KMB | 5962-8984108KA |
| UT22VP10T-15PCC | 5962H9475408VLC | PALC22V10B-15KMB | 5962-8867005KA | PALC22V10D-20LMB | 5962-89841083A |
| UT22VP10T-15UCA | 5962H9475408QXA | PALC22V10B-15LMB | 5962-88670053A | PALCE22V10-20DMB | 5962-8984102LA |
| UT22VP10T-15UCA | 5962H9475408VXA | PALC22V10B-15LMB | 5962-88670053A | PALCE22V10-20DMB | 5962-8984108LA |
| UT22VP10T-15UCC | 5962H9475408QXC | PALC22V10B-15QMB | 5962-87539053A | PALCE22V10-20KMB | 5962-8984102KA |
| UT22VP10T-15UCC | 5962H9475408VXC | PALC22V10B-15TMB | 5962-8753905KA | PALCE22V10-20KMB | 5962-8984108KA |
| UT22VP10T-15WCA | 5962H9475408QYA | PALC22V10B-15WMB | 5962-8753905LA | PALCE22V10-20LMB | 5962-89841083A |
| UT22VP10T-15WCA | 5962H9475408VYA | PALC22V10D-15DMB | 5962-8984103LA | QPC22V10-20/B3A | 5962-89841023A |
| UT22VP10T-15WCA | 5962H9475408VYC | PALC22V10D-15DMB | 5962-8984105LA | QPC22V10-20/B3A | 5962-89841083A |
| UT22VP10T-15WCC | 5962H9475408QYC | PALC22V10D-15LMB | 5962-89841033A | QPC22V10-20/BKA | 5962-8984102KA |
| GEM22101QEA | 5962-0050701QEA | PALCE22V10-15DMB | 5962-8984103LA | QPC22V10-20/BKA | 5962-8984108KA |
| GEM22101QEC | 5962-0050701QEC | PALCE22V10-15DMB | 5962-8984105LA | QPC22V10-20/BLA | 5962-8984102LA |
| 22V10B (GEN) | 5962-87539063A | PALCE22V10-15LMB | 5962-89841033A | QPC22V10-20/BLA | 5962-8984108LA |
| 22V10B (GEN) | 5962-8753906LA | QPC22V10-15/B3A | 5962-89841033A | TIBPAL22V10-20MJTB | 5962-8605304LA |
| 22V10B (GEN) | 5962-8753906XA | QPC22V10-15/B3A | 5962-89841053A | TIBPAL22V10-20MKFB | 5962-86053043A |
| 22V10G-10 (GEN) | 5962-9176003M3A | QPC22V10-15/B3A | 5962-89841093A | TIBPAL22V10-20MWB | 5962-8605304KA |
| 22VP10G-10 (GEN) | 5962-9176006M3A | QPC22V10-15/B3A | 5962-89841113A | UT22VP10C-20PCA | 5962H9475403QLA |
| ATF22V10B-10GM/883 | 5962-8984106LA | QPC22V10-15/BKA | 5962-8984103KA | UT22VP10C-20PCA | 5962H9475403VLA |
| ATF22V10B-10NM/883 | 5962-89841063A | QPC22V10-15/BKA | 5962-8984105KA | UT22VP10C-20PCC | 5962H9475403QLC |
| GAL22V10C-10LD/883 | 5962-8984106LA | QPC22V10-15/BKA | 5962-8984109KA | UT22VP10C-20PCC | 5962H9475403VLC |
| GAL22V10C-10LR/883 | 5962-89841063A | QPC22V10-15/BKA | 5962-8984111KA | UT22VP10C-20UCA | 5962H9475403QXA |
| GAL22V10D-10LD/883 | 5962-8984106LA | QPC22V10-15/BLA | 5962-8984103LA | UT22VP10C-20UCA | 5962H9475403VXA |
| GAL22V10D-10LR/883 | 5962-89841063A | QPC22V10-15/BLA | 5962-8984105LA | UT22VP10C-20UCC | 5962H9475403QXC |
| PALC22V10D-10DMB | 5962-8984106LA | QPC22V10-15/BLA | 5962-8984109LA | UT22VP10C-20UCC | 5962H9475403VXC |
| PALC22V10D-10KMB | 5962-8984106KA | QPC22V10-15/BLA | 5962-8984111LA | UT22VP10C-20WCA | 5962H9475403QYA |
| PALC22V10D-10LMB | 5962-89841063A | 22V10-20 (GEN) | 5962-89841143A | UT22VP10C-20WCA | 5962H9475403VYA |
| PALCE22V10-10DMB | 5962-8984106LA | 22V10-20 (GEN) | 5962-8984114LA | UT22VP10C-20WCC | 5962H9475403QYC |
| PALCE22V10-10KMB | 5962-8984106KA | AT22V10L-20DM/883 | 5962-8872404LA | UT22VP10C-20WCC | 5962H9475403VYC |
| PALCE22V10-10LMB | 5962-89841063A | AT22V10L-20DM/883 | 5962-8872404LA | UT22VP10T-20PCA | 5962H9475404QLA |
| QPC22V10-10/B3A | 5962-89841063A | AT22V10L-20GM/883 | 5962-8975504LA | UT22VP10T-20PCA | 5962H9475404VLA |
| QPC22V10-10/B3A | 5962-89841123A | AT22V10L-20GM/883 | 5962-8975504LA | UT22VP10T-20PCC | 5962H9475404QLC |
| QPC22V10-10/BKA | 5962-8984106KA | AT22V10L-20LM/883 | 5962-88724043A | UT22VP10T-20PCC | 5962H9475404VLC |
| QPC22V10-10/BKA | 5962-8984112KA | AT22V10L-20LM/883 | 5962-88724043A | UT22VP10T-20UCA | 5962H9475404QXA |
| QPC22V10-10/BLA | 5962-8984106LA | AT22V10L-20NM/883 | 5962-89755043A | UT22VP10T-20UCA | 5962H9475404VXA |
| QPC22V10-10/BLA | 5962-8984112LA | AT22V10L-20NM/883 | 5962-89755043A | UT22VP10T-20UCC | 5962H9475404QXC |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

| Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN |
|---|---|---|---|---|---|
| UT22VP10T-20UCC | 5962H9475404VXC | PALC22V10D-25LMB | 5962-89841043A | PALC22V10-30DMB | 5962-8867002LA |
| UT22VP10T-20WCA | 5962H9475404QYA | PALC22V10D-25LMB | 5962-89841103A | PALC22V10-30DMB | 5962-8867002LA |
| UT22VP10T-20WCA | 5962H9475404VYA | PALCE22V10-25DMB | 5962-8984110LA | PALC22V10-30KMB | 5962-8867002KA |
| UT22VP10T-20WCC | 5962H9475404QYC | PALCE22V10-25KMB | 5962-8984110KA | PALC22V10-30LMB | 5962-88670023A |
| UT22VP10T-20WCC | 5962H9475404VYC | PALCE22V10-25LMB | 5962-89841043A | PALC22V10-30QMB | 5962-87539023A |
| 22V10A (GEN) | 5962-9176011NXA | PALCE22V10-25LMB | 5962-89841103A | PALC22V10-30TMB | 5962-8753902KA |
| 22V10A (GEN) | 5962-9176012NXA | QPC22V10-25/B3A | 5962-89841043A | PALC22V10-30WMB | 5962-8753902LA |
| 22V10B (GEN) | 5962-9176013NXA | QPC22V10-25/B3A | 5962-89841103A | QPC22V10-30/B3A | 5962-89841013A |
| 22V10B (GEN) | 5962-9176014NXA | QPC22V10-25/BKA | 5962-8984104KA | QPC22V10-30/B3A | 5962-89841073A |
| 22LV10 (GEN) | 5962-9324501M3A | QPC22V10-25/BKA | 5962-8984110KA | QPC22V10-30/BKA | 5962-8984101KA |
| 22LV10 (GEN) | 5962-9324501MKA | QPC22V10-25/BLA | 5962-8984104LA | QPC22V10-30/BKA | 5962-8984107KA |
| 22LV10 (GEN) | 5962-9324501MLA | QPC22V10-25/BLA | 5962-8984110LA | QPC22V10-30/BLA | 5962-8984101LA |
| 22V10-25 (GEN) | 5962-89841133A | TIBPAL22VP1025MFKB | 5962-86053033A | QPC22V10-30/BLA | 5962-8984107LA |
| 22V10-25 (GEN) | 5962-8984113LA | TIBPAL22VP1025MJTB | 5962-8605303LA | 22LV10 (GEN) | 5962-9324504M3A |
| 22VP10C (GEN) | 5962H9475401Q3A | TIBPAL22VP10-25MWB | 5962-8605303KA | 22LV10 (GEN) | 5962-9324504MKA |
| 22VP10C (GEN) | 5962H9475401Q3C | UT22VP10C-25PCA | 5962H9475401QLA | 22LV10 (GEN) | 5962-9324504MLA |
| 22VP10C (GEN) | 5962H9475401QKA | UT22VP10C-25PCA | 5962H9475401VLA | AT22V10L-40DM/883 | 5962-8872403LA |
| 22VP10C (GEN) | 5962H9475401QKC | UT22VP10C-25PCC | 5962H9475401QLC | AT22V10L-40GM/883 | 5962-8975503LA |
| 22VP10C (GEN) | 5962H9475401V3A | UT22VP10C-25PCC | 5962H9475401VLC | AT22V10L-40LM/883 | 5962-88724033A |
| 22VP10C (GEN) | 5962H9475401V3C | UT22VP10C-25UCA | 5962H9475401QXA | AT22V10L-40NM/883 | 5962-89755033A |
| 22VP10C (GEN) | 5962H9475401VKA | UT22VP10C-25UCA | 5962H9475401VXA | C22V10L (GEN) | 5962-8975503KA |
| 22VP10C (GEN) | 5962H9475401VKC | UT22VP10C-25UCC | 5962H9475401QXC | C22V10L-40 (GEN) | 5962-8872403KA |
| 22VP10T (GEN) | 5962H9475402Q3A | UT22VP10C-25UCC | 5962H9475401VXC | PALC22V10-40DMB | 5962-8867003LA |
| 22VP10T (GEN) | 5962H9475402Q3C | UT22VP10C-25WCA | 5962H9475401QYA | PALC22V10-40KMB | 5962-8867003KA |
| 22VP10T (GEN) | 5962H9475402QKA | UT22VP10C-25WCA | 5962H9475401VYA | PALC22V10-40LMB | 5962-88670033A |
| 22VP10T (GEN) | 5962H9475402QKC | UT22VP10C-25WCC | 5962H9475401QYC | PALC22V10-40QMB | 5962-87539033A |
| 22VP10T (GEN) | 5962H9475402V3A | UT22VP10C-25WCC | 5962H9475401VYC | PALC22V10-40TMB | 5962-8753903KA |
| 22VP10T (GEN) | 5962H9475402V3C | UT22VP10T-25PCA | 5962H9475402QLA | PALC22V10-40WMB | 5962-8753903LA |
| 22VP10T (GEN) | 5962H9475402VKA | UT22VP10T-25PCA | 5962H9475402VLA | RM2211 | 7705001CA |
| 22VP10T (GEN) | 5962H9475402VKC | UT22VP10T-25PCC | 5962H9475402QLC | TLV2217-33 (GEN) | 5962-9583801Q2A |
| AT22V10L-25DM/883 | 5962-8872401LA | UT22VP10T-25PCC | 5962H9475402VLC | TLV2217-33 (GEN) | 5962-9583801QCA |
| AT22V10L-25DM/883 | 5962-8872401LA | UT22VP10T-25UCA | 5962H9475402QXA | MAX222MJN/883B | 5962-9456502MVA |
| AT22V10L-25GM/883 | 5962-8975501LA | UT22VP10T-25UCA | 5962H9475402VXA | MAX222MLP/883B | 5962-9456502M2C |
| AT22V10L-25GM/883 | 5962-8975501LA | UT22VP10T-25UCC | 5962H9475402QXC | EL2232 (GEN) | 5962-9167501MPA |
| AT22V10L-25LM/883 | 5962-88724013A | UT22VP10T-25UCC | 5962H9475402VXC | GEM22401Q2A | 5962-9858601Q2A |
| AT22V10L-25LM/883 | 5962-88724013A | UT22VP10T-25WCA | 5962H9475402QYA | GEM22401Q2C | 5962-9858601Q2C |
| AT22V10L-25NM/883 | 5962-89755013A | UT22VP10T-25WCA | 5962H9475402VYA | GEM22401QRA | 5962-9858601QRA |
| AT22V10L-25NM/883 | 5962-89755013A | UT22VP10T-25WCC | 5962H9475402QYC | GEM22401QRC | 5962-9858601QRC |
| C22V10L (GEN) | 5962-8975501KA | UT22VP10T-25WCC | 5962H9475402VYC | GEM22401QSA | 5962-9858601QSA |
| C22V10L-25 (GEN) | 5962-8872401KA | 22LV10 (GEN) | 5962-9324502M3A | GEM22401QSC | 5962-9858601QSC |
| GAL22V10C-25LD/883 | 5962-8984104LA | 22LV10 (GEN) | 5962-9324502MKA | EP224-12 (GEN) | 5962-9210502MLA |
| GAL22V10D-25LD/883 | 5962-8984104LA | 22LV10 (GEN) | 5962-9324502MLA | EP224-15 (GEN) | 5962-9210501MLA |
| PALC22V10-25DMB | 5962-8867001LA | 22LV10 (GEN) | 5962-9324503MKA | TGC2245 | 5962-96B0112Q*A |
| PALC22V10-25DMB | 5962-8867001LA | 22LV10L (GEN) | 5962-9324503M3A | TGC2245 | 5962-97B0112Q*A |
| PALC22V10-25KMB | 5962-8867001KA | 22LV10L (GEN) | 5962-9324503MLA | 2250GM (GEN) | 5962-9326001MXA |
| PALC22V10-25LMB | 5962-88670013A | AT22V10L-30DM/883 | 5962-8872402LA | 2250GM (GEN) | 5962-9326001MYA |
| PALC22V10-25LMB | 5962-88670013A | AT22V10L-30GM/883 | 5962-8975502LA | TLC2252AMDQ | 5962-9564003NXD |
| PALC22V10-25QMB | 5962-87539013A | AT22V10L-30LM/883 | 5962-88724023A | TLC2252AMFKB | 5962-9564003Q2A |
| PALC22V10-25TMB | 5962-8753901KA | AY22V10L-30NM/883 | 5962-89755023A | TLC2252AMJGB | 5962-9564003QPA |
| PALC22V10-25WMB | 5962-8753901LA | C22V10L (GEN) | 5962-8975502KA | TLC2252AMUB | 5962-9564003QHA |
| PALC22V10-25WMB | 5962-8753901LA | C22V10L-30 (GEN) | 5962-8872402KA | TLC2252MDQ | 5962-9564001NXD |
| PALC22V10D-25DMB | 5962-8984110LA | GAL22V10C-30LD/883 | 5962-8984101LA | TLC2252MFKB | 5962-9564001Q2A |
| PALC22V10D-25KMB | 5962-8984110KA | GAL22V10D-30LD/883 | 5962-8984101LA | TLC2252MJGB | 5962-9564001QPA |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

| Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN |
|---|---|---|---|---|---|
| TLC2252MUB | 5962-9564001QHA | MG2265 | 5962-00B0213Q*C | HX2300 | 5962H96B0303QNC |
| TLV2252AMFKB | 5962-9566603Q2A | MG2265E | 5962-00B0205Q*C | HX2300 | 5962H96B0303V6C |
| TLV2252AMJGB | 5962-9566603QPA | MG2265E | 5962-00B0205V*C | HX2300 | 5962H96B0303V7C |
| TLV2252AMUB | 5962-9566603QHA | MG2M265 | 5962-00B0227Q*C | HX2300 | 5962H96B0303VMC |
| TLV2252MFKB | 5962-9566601Q2A | MG2M265E | 5962-00B0220Q*C | HX2300 | 5962H96B0303VNC |
| TLV2252MJGB | 5962-9566601QPA | MG2M265E | 5962-00B0220V*C | HX2300 | 5962H97B0303QXC |
| TLV2252MUB | 5962-9566601QHA | MM0-G2265*MQ | 5962-00B0213Q9A | HX2300 | 5962H97B0303QZC |
| TLC2254AMDQ | 5962-9564004NYD | MM0-G2265EH*MQ | 5962-00B0205Q9A | HX2300 | 5962H97B0303VXC |
| TLC2254AMFKB | 5962-9564004Q2A | MM0-G2M265*MQ | 5962-00B0227Q9A | HX2300 | 5962H97B0303VZC |
| TLC2254AMJB | 5962-9564004QCA | MM0-G2M265EH*MQ | 5962-00B0220Q9A | HX2300R | 5962H96B0308Q6C |
| TLC2254AMWB | 5962-9564004QDA | SM0-G2265EH*SV | 5962-00B0205V9A | HX2300R | 5962H96B0308Q7C |
| TLC2254MDQ | 5962-9564002NYD | SM0-G2M265EH*SV | 5962-00B0220V9A | HX2300R | 5962H96B0308QM |
| TLC2254MFKB | 5962-9564002Q2A | MTLOP-227AJ/883 | 5962-8688701CA | HX2300R | 5962H96B0308QNC |
| TLC2254MJB | 5962-9564002QCA | MTLOP-227AJ/883 | 5962-8688701CC | HX2300R | 5962H96B0308V6C |
| TLC2254MWB | 5962-9564002QDA | MG2270P | 5962-00B0305Q*C | HX2300R | 5962H96B0308V7C |
| TLV2254AMFKB | 5962-9566604Q2A | MG2270P | 5962-00B0305V*C | HX2300R | 5962H96B0308VMC |
| TLV2254AMJB | 5962-9566604QCA | MM0-G2270PH*MQ | 5962-00B0305Q9A | HX2300R | 5962H96B0308VNC |
| TLV2254AMWB | 5962-9566604QDA | MM2E-G2270PHxxxMQ | 5962-03B0105QUC | HX2300r | 5962H97B0308QTC |
| TLV2254MFKB | 5962-9566602Q2A | MMKN-G2270PHxxxMQ | 5962-03B0105QYC | HX2300r | 5962H97B0308VTC |
| TLV2254MJB | 5962-9566602QCA | MMKW-G2270PHxxxM | 5962-03B0105QZC | GEM23001Q2A | 85508012A |
| TLV2254MWB | 5962-9566602QDA | SM0-G2270PH*SV | 5962-00B0305V9A | GEM23001Q2C | 85508012C |
| GEM22601Q2A | 5962-90613012A | SM2E-G2270PHxxxSR | 5962R03B0105VUC | GEM23001QEA | 8550801EA |
| GEM22601Q2C | 5962-90613012C | SM2E-G2270PHxxxSV | 5962-03B0105VUC | GEM23001QEC | 8550801EC |
| GEM22601QEA | 5962-9061301EA | SMF7-G2270PHxxxSR | 5962R00B0305VNC | GEM23001QFA | 8550801FA |
| GEM22601QEC | 5962-9061301EC | SMF9-G2270PHxxxSR | 5962R00B0305V5C | GEM23001QFC | 8550801FC |
| GEM22601QFA | 5962-9061301FA | SMFW-G2270PHxxxSR | 5962R00B0305V4C | SL54LS353/B2A | 85508012A |
| GEM22601QFC | 5962-9061301FC | SMKN-G2270PHxxxSR | 5962R03B0105VYC | SL54LS353/BEA | 8550801EA |
| TLC2262AMFKB | 5962-9469203Q2A | SMKN-G2270PHxxxSV | 5962-03B0105VYC | SL54LS353/BFA | 8550801FA |
| TLC2262AMJGB | 5962-9469203QPA | SMKW-G2270PHxxxSR | 5962R03B0105VZC | LF2301-55 (GEN) | 5962-8971503XA |
| TLC2262AMUB | 5962-9469203QHA | SMKW-G2270PHxxxSV | 5962-03B0105VZC | LF2301-55 (GEN) | 5962-8971503YA |
| TLC2262MFKB | 5962-9469201Q2A | SMKZ-G2270PHxxxSR | 5962R00B0305V6C | TMC2301 (GEN) | 5962-8971501XC |
| TLC2262MJGB | 5962-9469201QPA | SMYC-G2270PHxxxSR | 5962R00B0305V7C | TMC2301 (GEN) | 5962-8971501YA |
| TLC2262MUB | 5962-9469201QHA | GEM22703QXA | 5962-8864303XA | TMC2301 (GEN) | 5962-8971502XC |
| TLV2262AMFKB | 5962-9550403Q2A | GEM22703QXC | 5962-8864303XC | TMC2301 (GEN) | 5962-8971502YA |
| TLV2262AMJGB | 5962-9550403QPA | GEM22703QYA | 5962-8864303YA | LMX2305WG-QML | 5962-9855003QXA |
| TLV2262AMUB | 5962-9550403QHA | GEM22703QYC | 5962-8864303YC | APT6040DN (GEN) | 5962-0150301DXA |
| TLV2262MFKB | 5962-9550401Q2A | TLC2272AMFKB | 5962-9555202Q2A | APT5020DN (GEN) | 5962-0150401DXA |
| TLV2262MJGB | 5962-9550401QPA | TLC2272AMJGB | 5962-9555202QPA | CLC231A (GEN) | 5962-8959401XA |
| TLV2262MUB | 5962-9550401QHA | TLC2272AMUB | 5962-9555202QHA | MAX231MJD/883B | 5962-8987703CA |
| HS0-22620RH-Q | 5962F9751201V9A | TLC2272MDQ | 5962-9555201NXD | TMC2310V (GEN) | 5962-9096301MXA |
| HS9-22620RH-Q | 5962F9751201VXC | TLC2272MFKB | 5962-9555201Q2A | TMC2310V (GEN) | 5962-9096301MYA |
| TLC2264AMFKB | 5962-9469204Q2A | TLC2272MJGB | 5962-9555201QPA | TMC2310V1 (GEN) | 5962-9096302MXA |
| TLC2264AMJB | 5962-9469204QCA | TLC2272MUB | 5962-9555201QHA | TMC2310V1 (GEN) | 5962-9096302MYA |
| TLC2264AMWB | 5962-9469204QDA | TLC2274AMFKB | 5962-9318202Q2A | LMX2315WG-QML | 5962-9855001QXA |
| TLC2264MFKB | 5962-9469202Q2A | TLC2274AMJB | 5962-9318202QCA | AS232F16/883C | 5962-8987701XA |
| TLC2264MJB | 5962-9469202QCA | TLC2274AMWB | 5962-9318202QDA | CLC232A (GEN) | 5962-9166501HXA |
| TLC2264MWB | 5962-9469202QDA | TLC2274MFKB | 5962-9318201M2A | MAX232AMJE/883B | 5962-9456503MEA |
| TLV2264AMFKB | 5962-9550404Q2A | TLC2274MJB | 5962-9318201MCA | MAX232AMLP/883B | 5962-9456503M2C |
| TLV2264AMJB | 5962-9550404QCA | TLC2274MWB | 5962-9318201QDA | MAX232MJE/883B | 5962-8987701EA |
| TLV2264AMWB | 5962-9550404QDA | MAX230MJP/883B | 5962-8987702RA | MAX232MLP/883B | 5962-89877012C |
| TLV2264MFKB | 5962-9550402Q2A | HX2300 | 5962H96B0303Q6C | LMX2325WG-QML | 5962-9855002QXA |
| TLV2264MJB | 5962-9550402QCA | HX2300 | 5962H96B0303Q7C | TMC2330 (GEN) | 5962-9233101MXA |
| TLV2264MWB | 5962-9550402QDA | HX2300 | 5962H96B0303QM | TMC2330 (GEN) | 5962-9233101MYA |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

| Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN |
|---|---|---|---|---|---|
| TMC2330 (GEN) | 5962-9233102MXA | HX2400 | 5962H96B0304Q5C | TLV2432AMFKB | 5962-9751002Q2A |
| TMC2330 (GEN) | 5962-9233102MYA | HX2400 | 5962H96B0304QTC | TLV2432AMJGB | 5962-9751002QPA |
| MAX234MJE/883B | 5962-8987704EA | HX2400 | 5962H96B0304V5C | TLV2432AMUB | 5962-9751002QHA |
| HR2340 (GEN) | 5962H94A0303QM | HX2400 | 5962H96B0304VTC | TLV2432MFKB | 5962-9751001Q2A |
| HR2340 (GEN) | 5962H94A0303QTC | HX2400 | 5962H97B0304QXC | TLV2432MJGB | 5962-9751001QPA |
| HR2340 (GEN) | 5962H94A0303VMC | HX2400 | 5962H97B0304QZC | TLV2432MUB | 5962-9751001QHA |
| HR2340 (GEN) | 5962H94A0303VTC | HX2400 | 5962H97B0304VXC | 24X32B-0 (GEN) | 5962-9683701MXC |
| HR2340 (GEN) | 5962H99B0203QXC | HX2400 | 5962H97B0304VZC | 24X32B-1 (GEN) | 5962-9683702MXC |
| HR2340 (GEN) | 5962H99B0203VXC | HX2400R | 5962H96B0309Q5C | ACS244 (GEN) | 5962F9854101V9A |
| TLV2352MFKB | 5962-9688101Q2A | HX2400R | 5962H96B0309QTC | ACS244DMSR-02 | 5962F9854101VRC |
| TLV2352MJGB | 5962-9688101QPA | HX2400R | 5962H96B0309V5C | ACS244KMSR-02 | 5962F9854101VXC |
| TLV2352MUB | 5962-9688101QHA | HX2400R | 5962H96B0309VTC | ACTS244 (GEN) | 5962F9671801VRC |
| TLV2354MFKB | 5962-9688201Q2A | HX2400r | 5962H97B0309QNA | ACTS244 (GEN) | 5962F9671801VXC |
| TLV2354MJB | 5962-9688201QCA | HX2400r | 5962H97B0309VNA | HCS244 (GEN) | 5962R9573101TRC |
| TLV2354MWB | 5962-9688201QDA | ACTS240-02 (GEN) | 5962F9671702V9A | HCS244 (GEN) | 5962R9573101TXC |
| AS5C2568EC-45L/883C | 5962-8855209MA | ACTS240-02 (GEN) | 5962F9671702VRC | HCS244 (GEN) | 5962R9573101V9A |
| MAX236MRG/883B | 5962-8987705JA | ACTS240-02 (GEN) | 5962F9671702VXC | HCS244DMSR | 5962R9573101VRC |
| MG2360 | 5962-00B0214Q*C | ACTS240DTR-02 | 5962R9671702TRC | HCS244KMSR | 5962R9573101VXC |
| MG2360E | 5962-00B0206Q*C | ACTS240KTR-02 | 5962R9671702TXC | HCTS244 (GEN) | 5962R9574401TRC |
| MG2360E | 5962-00B0206V*C | ARX2402 | 5962-8604903YA | HCTS244 (GEN) | 5962R9574401TXC |
| MG2M360 | 5962-00B0228Q*C | ARX2402 | 5962-8604903YC | HCTS244 (GEN) | 5962R9574401V9A |
| MG2M360E | 5962-00B0221Q*C | 24C04 (GEN) | 5962-8959001PA | HCTS244DMSR | 5962R9574401VRC |
| MG2M360E | 5962-00B0221V*C | HCS241 (GEN) | 5962R9581001V9A | HCTS244KMSR | 5962R9574401VXC |
| MM0-G2360*MQ | 5962-00B0214Q9A | HCS241 (GEN) | 5962R9581001VRC | ACTS244 (GEN) | 5962F9671802V9A |
| MM0-G2360EH*MQ | 5962-00B0206Q9A | HCS241 (GEN) | 5962R9581001VXC | ACTS244DMSR-02 | 5962F9671802VRC |
| MM0-G2M360*MQ | 5962-00B0228Q9A | ARX2410 | 5962-9063603HXA | ACTS244KMSR-02 | 5962F9671802VXC |
| MM0-G2M360EH*MQ | 5962-00B0221Q9A | ARX2410 | 5962-9063603HXC | TLV2442AMFKB | 5962-9751102Q2A |
| SM0-G2360EH*SV | 5962-00B0206V9A | ARX2411 (GEN) | 5962-8757903XA | TLV2442AMJGB | 5962-9751102QPA |
| SM0-G2M360EH*SV | 5962-00B0221V9A | ARX2411 (GEN) | 5962-8757903YA | TLV2442AMUB | 5962-9751102QHA |
| MAX237MRG/883B | 5962-8987706JA | 24C16 (GEN) | 5962-8966701PA | TLV2442MFKB | 5962-9751101Q2A |
| OP-237A (GEN) | 5962-9056801CA | MAX242MJN/883B | 5962-9456504MVA | TLV2442MJGB | 5962-9751101QPA |
| OP-237C (GEN) | 5962-9056802CA | MAX242MLP/883B | 5962-9456504M2C | TLV2442MUB | 5962-9751101QHA |
| MAX238MRG/883B | 5962-8987707JA | HA1-2420/883 | 8001601CA | HA-2444 (GEN) | 5962-9309501MEA |
| MAX239MRG/883B | 5962-8987708JA | HA4-2420/883 | 80016012A | ACS245A (GEN) | 5962F9670702VRC |
| MUX-24A (GEN) | 5962-8771801EA | HS1B-2420RH-Q | 5962R9566901VCC | ACS245A (GEN) | 5962F9670702VXC |
| MUX-24B (GEN) | 5962-8771802EA | GEM24202Q2A | 78015022A | ACS245DMSR | 5962F9670701VRC |
| ACS240 (GEN) | 5962F9854001V9A | GEM24202Q2C | 78015022C | ACS245KMSR | 5962F9670701VXC |
| ACS240 (GEN) | 5962F9854001VRC | GEM24202QEA | 7801502EA | ACTS245 (GEN) | 5962F9671901V9A |
| ACS240 (GEN) | 5962F9854001VXC | GEM24202QEC | 7801502EC | ACTS245 (GEN) | 5962R9671901TRC |
| ACTS240 (GEN) | 5962F9671701V9A | GEM24202QFA | 7801502FA | ACTS245 (GEN) | 5962R9671901TXC |
| ACTS240 (GEN) | 5962R9671701TRC | GEM24202QFC | 7801502FC | ACTS245DMSR | 5962F9671901VRC |
| ACTS240 (GEN) | 5962R9671701TXC | TLV2422AMFKB | 5962-9751402Q2A | ACTS245KMSR | 5962F9671901VXC |
| ACTS240DMSR | 5962F9671701VRC | TLV2422AMJGB | 5962-9751402QPA | HCS245DMSR | 5962R9679701VRC |
| ACTS240KMSR | 5962F9671701VXC | TLV2422AMUB | 5962-9751402QHA | HCS245HMSR | 5962R9679701V9A |
| HCS240 (GEN) | 5962R9580901V9A | TLV2422MFKB | 5962-9751401Q2A | HCS245KMSR | 5962R9679701VXC |
| HCS240DMSR | 5962R9580901VRC | TLV2422MJGB | 5962-9751401QPA | HCTS245 (GEN) | 5962R9574501TRC |
| HCS240KMSR | 5962R9580901VXC | TLV2422MUB | 5962-9751401QHA | HCTS245 (GEN) | 5962R9574501TXC |
| HCTS240ADMSR | 5962R9577201VRC | TLE2425 (GEN) | 5962-9555601Q2A | HCTS245DMSR | 5962R9574501VRC |
| HCTS240AHMSR | 5962R9577201V9A | TLE2425 (GEN) | 5962-9555601QPA | HCTS245KMSR | 5962R9574501VXC |
| HCTS240AKMSR | 5962R9577201VXC | TLE2426 (GEN) | 5962-9555602Q2A | IBMAP2-45 (GEN) | 5962H9210601QZC |
| HA1-2400/883 | 5962-8778301EA | TLE2426 (GEN) | 5962-9555602QPA | IBMAP2-45 (GEN) | 5962H9210601VZC |
| HA4-2400/883 | 5962-87783012A | MAX243MJE/883B | 5962-9456505MEA | GEM24501QJA | 5962-9953201QJA |
| HS1B-2400RH-Q | 5962D9568401VEC | MAX243MLP/883B | 5962-9456505M2C | GEM24501QJC | 5962-9953201QJC |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

| Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN |
|---|---|---|---|---|---|
| GEM24501QKA | 5962-9953201QKA | MG2480 | 5962-00B0215Q*C | ATV2500BQ-25DM/883 | 5962-9154506MQA |
| GEM24501QKC | 5962-9953201QKC | MG2480E | 5962-00B0207Q*C | ATV2500BQ-25KM/883 | 5962-9154506MYA |
| GEM24501QLA | 5962-9953201QLA | MG2M480 | 5962-00B0229Q*C | ATV2500BQ-25LM/883 | 5962-9154506MXA |
| GEM24501QLC | 5962-9953201QLC | MG2M480E | 5962-00B0222Q*C | ATV2500H-25GM/883 | 5962-9154602MQA |
| ACS245-02 (GEN) | 5962F9670703VRC | MG2M480E | 5962-00B0222V*C | V2500-25 (GEN) | 5962-9154502MQA |
| ACS245-02 (GEN) | 5962F9670703VXC | MM0-G2480*MQ | 5962-00B0215Q9A | V2500-25 (GEN) | 5962-9154502MXA |
| ACS245A (GEN) | 5962F9670704VRC | MM0-G2480EH*MQ | 5962-00B0207Q9A | V2500-25 (GEN) | 5962-9154502MYA |
| ACS245A (GEN) | 5962F9670704VXC | MM0-G2M480*MQ | 5962-00B0229Q9A | V2500H (GEN) | 5962-9154602MXA |
| ACTS245-02 (GEN) | 5962F9671902V9A | MM0-G2M480EH*MQ | 5962-00B0222Q9A | V2500H (GEN) | 5962-9154602MYA |
| ACTS245-02 (GEN) | 5962F9671902VRC | SM0-G2M480EH*SV | 5962-00B0222V9A | ATV2500BQL-30DM/88 | 5962-9154507MQA |
| ACTS245-02 (GEN) | 5962F9671902VXC | OP249AJ/883 | 5962-9151901MGA | ATV2500BQL-30KM/88 | 5962-9154507MYA |
| ACTS245DTR-02 | 5962R9671902TRC | OP249ARC/883 | 5962-9151901M2A | ATV2500BQL-30LM/88 | 5962-9154507MXA |
| ACTS245KTR-02 | 5962R9671902TXC | OP249AZ/883 | 5962-9151901MPA | V2500-30 (GEN) | 5962-9154503MQA |
| ARX2452-001-1 | 5962-8753502XC | UT25*QCR | 5962R96B0209Q*C | V2500-30 (GEN) | 5962-9154503MXA |
| ARX2452-001-2 | 5962-8753502XA | UT25*QCR | 5962R96B0210Q*C | V2500-30 (GEN) | 5962-9154503MYA |
| ARX2452-202-1 | 5962-8753502YC | UT25*QCR | 5962R96B0211Q*C | ATV2500H-35GM/883 | 5962-9154601MQA |
| ARX2452-202-2 | 5962-8753502YA | UT25*QCR | 5962R96B0212Q*C | ATV2500L-35GM/883 | 5962-9154603MQA |
| ARX-2453FP | 5962-8952202YA | UT25*VCR | 5962R96B0209V*C | V2500-35 (GEN) | 5962-9154501MQA |
| ARX-2453FP | 5962-8952202YC | UT25*VCR | 5962R96B0210V*C | V2500-35 (GEN) | 5962-9154501MXA |
| HS1-245RH-8 | 5962R9672201QCC | UT25*VCR | 5962R96B0211V*C | V2500-35 (GEN) | 5962-9154501MYA |
| HS1-245RH-Q | 5962R9672201VCC | UT25*VCR | 5962R96B0212V*C | V2500H (GEN) | 5962-9154601MXA |
| HS9-245RH-8 | 5962R9672201QXC | UT25E/R*QCH | 5962H96B0201Q*A | V2500H (GEN) | 5962-9154601MYA |
| HS9-245RH-Q | 5962R9672201VXC | UT25E/R*QCH | 5962H96B0202Q*A | 25S09/BEA | 5962-8672801EA |
| HS1-246RH-8 | 5962R9672301QCC | UT25E/R*QCH | 5962H96B0203Q*A | 25S09/BFA | 5962-8672801FA |
| HS1-246RH-Q | 5962R9672301VCC | UT25E/R*QCH | 5962H96B0204Q*A | 25S10/B2A | 5962-86718012A |
| HS9-246RH-8 | 5962R9672301QXC | UT25E/R*QCH | 5962H96B0205Q*A | 25S10/BEA | 5962-8671801EA |
| HS9-246RH-Q | 5962R9672301VXC | UT25E/R*VCH | 5962H96B0201V*A | 25S10/BFA | 5962-8671801FA |
| TLV2460AMFKB | 5962-0051202Q2A | UT25E/R*VCH | 5962H96B0202V*A | HS7B-2510RH-Q | 5962D9568601VPC |
| TLV2460AMJGB | 5962-0051202QPA | UT25E/R*VCH | 5962H96B0203V*A | HS9-2510RH-Q | 5962D9568601VXC |
| TLV2460AMUB | 5962-0051202QHA | UT25E/R*VCH | 5962H96B0204V*A | CT-2512-001-1 | 5962-8753503XC |
| TLV2460MFKB | 5962-0051201Q2A | UT25E/R*VCH | 5962H96B0205V*A | CT-2512-001-2 | 5962-8753503XA |
| TLV2460MJGB | 5962-0051201QPA | UT25E/R_QCH | 5962H97B0401QXC | CT-2512-201-1 | 5962-8753503ZC |
| TLV2460MUB | 5962-0051201QHA | UT25E/R_QCH | 5962H97B0402QXC | CT-2512-201-2 | 5962-8753503ZA |
| TLV2461AMFKB | 5962-0051204Q2A | UT25E/R_QCH | 5962H97B0402QYA | 25S18/B2A | 5962-86715012A |
| TLV2461AMJGB | 5962-0051204QPA | UT25E/R_QCH | 5962H97B0402QZA | 25S18/BEA | 5962-8671501EA |
| TLV2461AMUB | 5962-0051204QHA | UT25E/R_QCH | 5962H97B0403QXC | 25S18/BFA | 5962-8671501FA |
| TLV2461MFKB | 5962-0051203Q2A | UT25E/R_QCH | 5962H97B0404QXC | HA2-2520/883 | 5962-8988002GC |
| TLV2461MJGB | 5962-0051203QPA | UT25E/R_QCH | 5962H97B0405QXC | HA2520 (GEN) | 5962-89880022A |
| TLV2461MUB | 5962-0051203QHA | UT25E/R_VCH | 5962H97B0401VXC | HA7-2520/883 | 5962-8988002PA |
| TLV2462AMFKB | 5962-0051206Q2A | UT25E/R_VCH | 5962H97B0402VXC | HS2-2520RH-Q | 5962D9568501VGA |
| TLV2462AMJGB | 5962-0051206QPA | UT25E/R_VCH | 5962H97B0402VYA | HS-2520 (GEN) | 5962D9568501V9A |
| TLV2462AMUB | 5962-0051206QHA | UT25E/R_VCH | 5962H97B0402VZA | HS7B-2520RH-Q | 5962D9568501VPC |
| TLV2462MFKB | 5962-0051205Q2A | UT25E/R_VCH | 5962H97B0403VXC | CT2521 (GEN) | 5962-8952205UA |
| TLV2462MJGB | 5962-0051205QPA | UT25E/R_VCH | 5962H97B0404VXC | CT2521 (GEN) | 5962-8952205ZA |
| TLV2462MUB | 5962-0051205QHA | UT25E/R_VCH | 5962H97B0405VXC | HA2-2522/883 | 5962-8988001GC |
| TLV2463AMFKB | 5962-0051208Q2A | UT250*QCR | 5962R96B0217Q*C | HA-2522 (GEN) | 5962-89880012A |
| TLV2463AMUB | 5962-0051208QCA | UT250*VCR | 5962R96B0217V*C | HA-2522 (GEN) | 5962-8988001PA |
| TLV2463MFKB | 5962-0051207Q2A | V2500L (GEN) | 5962-9154603MXA | SL2524 (GEN) | 5962-9231501M2C |
| TLV2463MUB | 5962-0051207QCA | V2500L (GEN) | 5962-9154603MYA | 25S240 (GEN) | 5962-8672401RA |
| HS1-248RH-8 | 5962R9672302QCC | ATV2500B-15KM/883 | 5962-9154504MYA | 25S240 (GEN) | 5962-8672401SA |
| HS1-248RH-Q | 5962R9672302VCC | ATV2500B-15LM/883 | 5962-9154504MXA | 25S241 (GEN) | 5962-8672501RA |
| HS9-248RH-8 | 5962R9672302QXC | ATV2500BL-20KM/883 | 5962-9154505MYA | 25S241 (GEN) | 5962-8672501SA |
| HS9-248RH-Q | 5962R9672302VXC | ATV2500BL-20LM/883 | 5962-9154505MXA | 25S244 (GEN) | 5962-8753601RA |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART II, Listed By Generic PIN

| Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN |
|---|---|---|---|---|---|
| 25S244 (GEN) | 5962-8753601SA | HA-2548 (GEN) | 5962-9673701QGC | CT2565-001-1 | 5962-8858501XC |
| 25LS2521/B2A | 5962-86713012A | HA-2548 (GEN) | 5962-9673701QPC | CT2565-001-2 | 5962-8858501XA |
| 25LS2521/BRA | 5962-8671301RA | TLV2548 (GEN) | 5962-9957001QRA | CT2565-002-1 | 5962-8858502XC |
| 25LS2521/BSA | 5962-8671301SA | TLV2548MFKB | 5962-9957001Q2A | CT2565-002-2 | 5962-8858502XA |
| 25LS2569/B2A | 5962-87544012A | HA-2556 (GEN) | 5962-9472901QEA | CT2565-201-1 | 5962-8858501YC |
| 25LS2569/BRA | 5962-8754401RA | LOR2561C-40 (GEN) | 5962H9312803QXC | CT2565-201-2 | 5962-8858501YA |
| 25LS2569/BSA | 5962-8754401SA | LOR2561C-40 (GEN) | 5962H9312803QYC | CT2565-202-1 | 5962-8858502YC |
| HA2-2529/883 | 5962-8972101GC | LOR2561C-40 (GEN) | 5962H9312803QZC | CT2565-202-2 | 5962-8858502YA |
| HA-2529 (GEN) | 5962-89721012A | LOR2561C-40 (GEN) | 5962H9312803VXC | CT2566-001-1 | 5962-8858602XC |
| HA-2529 (GEN) | 5962-8972101PA | LOR2561C-40 (GEN) | 5962H9312803VYC | CT2566-001-2 | 5962-8858602XA |
| 25LS299 (GEN) | 7802402RA | LOR2561C-40 (GEN) | 5962H9312803VZC | CT2566-002-1 | 5962-8858603XC |
| 25LS299 (GEN) | 7802402SA | LOR2561T-50 (GEN) | 5962H9312805QXC | CT2566-002-2 | 5962-8858603XA |
| HCS253 (GEN) | 5962R9579001V9A | LOR2561T-50 (GEN) | 5962H9312805QYC | CT2566-201-1 | 5962-8858602YC |
| HCS253 (GEN) | 5962R9579001VEC | LOR2561T-50 (GEN) | 5962H9312805QZC | CT2566-201-2 | 5962-8858602YA |
| HCS253 (GEN) | 5962R9579001VXC | LOR2561T-50 (GEN) | 5962H9312805VXC | CT2566-202-1 | 5962-8858603YC |
| ACS253 (GEN) | 5962F9800701V9A | LOR2561T-50 (GEN) | 5962H9312805VYC | CT2566-202-2 | 5962-8858603YA |
| ACS253 (GEN) | 5962F9800701VEC | LOR2561T-50 (GEN) | 5962H9312805VZC | LMP2568C-Q45X | 5962R9689101QXC |
| ACS253 (GEN) | 5962F9800701VXC | WMS256K16-17DLQ | 5962-9690204HMA | WS256K8-100CQ | 5962-9315702HXC |
| HA1-2539/883 | 5962-8778701CA | WMS256K16-17DLQ | 5962-9690204HMC | WS256K8-100CQ | 5962-9315702HYC |
| HA2539 (GEN) | 5962-87787012A | WMS256K16-17FGQ | 5962-9690204HTA | WS256K8-100CQA | 5962-9315702HXA |
| 25LS399 (GEN) | 5962-8670801EA | WMS256K16-17FGQ | 5962-9690204HTC | WS256K8-100CQA | 5962-9315702HYA |
| 25LS399 (GEN) | 5962-8670801FA | WMS256K16-17FLQ | 5962-9690204HNA | WS256K8-120CQ | 5962-9315701HXC |
| HA1-2540/883 | 5962-8964801CA | WMS256K16-17FLQ | 5962-9690204HNC | WS256K8-120CQ | 5962-9315701HYC |
| HA2540 (GEN) | 5962-89648012A | WMS256K16-20DLQ | 5962-9690203HMA | WS256K8-120CQA | 5962-9315701HXA |
| GEM25402BEA | 5962-8969402EA | WMS256K16-20DLQ | 5962-9690203HMC | WS256K8-120CQA | 5962-9315701HYA |
| GEM25402BEC | 5962-8969402EC | WMS256K16-20FGQ | 5962-9690203HTA | 256K8-150 (GEN) | 5962-9315502HXA |
| GEM25402BFA | 5962-8969402FA | WMS256K16-20FGQ | 5962-9690203HTC | 256K8-150 (GEN) | 5962-9315502HXC |
| GEM25402BFC | 5962-8969402FC | WMS256K16-20FLQ | 5962-9690203HNA | WE-256K8-150CQ | 5962-9315502HYA |
| GEM25402BXA | 5962-8969402XA | WMS256K16-20FLQ | 5962-9690203HNC | WE-256K8-150CQ | 5962-9315502HYC |
| GEM25402BXC | 5962-8969402XC | WMS256K16-25DLQ | 5962-9690202HMA | WS256K8-20CQ | 5962-9315709HXC |
| GEM25402BYA | 5962-8969402YA | WMS256K16-25DLQ | 5962-9690202HMC | WS256K8-20CQ | 5962-9315709HYC |
| GEM25402BYC | 5962-8969402YC | WMS256K16-25FGQ | 5962-9690202HTA | WS256K8-20CQA | 5962-9315709HXA |
| HA1-2541/883 | 5962-8778501CA | WMS256K16-25FGQ | 5962-9690202HTC | WS256K8-20CQA | 5962-9315709HYA |
| HA2-2541/883 | 5962-8778501XC | WMS256K16-25FLQ | 5962-9690202HNA | 256K8-200 (GEN) | 5962-9315501HXA |
| MSK2541B | 5962-9083801HXC | WMS256K16-25FLQ | 5962-9690202HNC | 256K8-200 (GEN) | 5962-9315501HXC |
| OMA2541SBD | 5962-9083801HYA | WMS256K16-35DLQ | 5962-9690201HMA | WE-256K8-200CQ | 5962-9315501HYA |
| OMA2541SKB | 5962-9083801HXA | WMS256K16-35DLQ | 5962-9690201HMC | WE-256K8-200CQ | 5962-9315501HYC |
| OMA2541SKCB | 5962-9083802HXA | WMS256K16-35FGQ | 5962-9690201HTA | WS256K8-25CQ | 5962-9315708HXC |
| CT2542 | 5962-8979803XA | WMS256K16-35FGQ | 5962-9690201HTC | WS256K8-25CQ | 5962-9315708HYC |
| CT2542 | 5962-8979803XC | WMS256K16-35FLQ | 5962-9690201HNA | WS256K8-25CQA | 5962-9315708HXA |
| CT2542-FP | 5962-8979803YA | WMS256K16-35FLQ | 5962-9690201HNC | WS256K8-25CQA | 5962-9315708HYA |
| CT2542-FP | 5962-8979803YC | LOR2561C-60 (GEN) | 5962H9312801QXC | LOR2568C-Q30I | 5962H9215313QNC |
| HA-2542 (GEN) | 5962-8964301XC | LOR2561C-60 (GEN) | 5962H9312801QYC | LOR2568C-Q30X | 5962H9215313QXC |
| CT2543 | 5962-8979804XA | LOR2561C-60 (GEN) | 5962H9312801QZC | LOR2568C-Q30Y | 5962H9215313QYC |
| CT2543 | 5962-8979804XC | LOR2561C-60 (GEN) | 5962H9312801VXC | LOR2568C-V30I | 5962H9215313VNC |
| CT2543-FP | 5962-8979804YA | LOR2561C-60 (GEN) | 5962H9312801VYC | LOR2568C-V30X | 5962H9215313VXC |
| CT2543-FP | 5962-8979804YC | LOR2561C-60 (GEN) | 5962H9312801VZC | LOR2568C-V30Y | 5962H9215313VYC |
| TLC2543MJB | 5962-9688601QRA | LOR2561T-60 (GEN) | 5962H9312802QXC | LOR2568T-Q30I | 5962H9215314QNC |
| HA2-2544/883 | 5962-8950201GC | LOR2561T-60 (GEN) | 5962H9312802QYC | LOR2568T-Q30X | 5962H9215314QXC |
| HA4-2544/883 | 5962-89502012A | LOR2561T-60 (GEN) | 5962H9312802QZC | LOR2568T-Q30Y | 5962H9215314QYC |
| HA7-2544/883 | 5962-8950201PA | LOR2561T-60 (GEN) | 5962H9312802VXC | LOR2568T-V30I | 5962H9215314VNC |
| HA1-2546/883 | 5962-9325101MEA | LOR2561T-60 (GEN) | 5962H9312802VYC | LOR2568T-V30X | 5962H9215314VXC |
| HA-2546 (GEN) | 5962-9325101M2A | LOR2561T-60 (GEN) | 5962H9312802VZC | LOR2568T-V30Y | 5962H9215314VYC |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

| Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN |
|---|---|---|---|---|---|
| LMP2568T3V-Q10X | 5962G0250201QXC | SD256MX88 | 5962-0251802NXA | DS26LS31MJ/883 | 5962-7802301MEA |
| LMP2568T3V-V10X | 5962G0250201VXC | SD256MX88 | 5962-0251802NXB | DS26LS31MJFQML | 5962F7802301MEA |
| WS256K8-35CQ | 5962-9315707HXC | WS256K8-85CQ | 5962-9315703HXC | DS26LS31MJFQMLV | 5962F7802301VEA |
| WS256K8-35CQ | 5962-9315707HYC | WS256K8-85CQ | 5962-9315703HYC | DS26LS31MJ-QMLV | 5962-7802301VEA |
| WS256K8-35CQA | 5962-9315707HXA | WS256K8-85CQA | 5962-9315703HXA | DS26LS31MW/883 | 5962-7802301MFA |
| WS256K8-35CQA | 5962-9315707HYA | WS256K8-85CQA | 5962-9315703HYA | DS26LS31MWFQML | 5962F7802301MFA |
| 2568C40 (GEN) | 5962H9215303QZA | ACS257 (GEN) | 5962F9800801V9A | DS26LS31MWFQMLV | 5962F7802301VFA |
| 2568C40 (GEN) | 5962H9215303VZA | ACS257 (GEN) | 5962F9800801VEC | DS26LS31MW-QMLV | 5962-7802301VFA |
| 2568T40 (GEN) | 5962H9215304QZA | ACS257 (GEN) | 5962F9800801VXC | DS26LV31W-QML | 5962-9858401QFA |
| 2568T40 (GEN) | 5962H9215304VZA | LM2595J-ADJ (GEN) | 5962-9650401QEA | HS0-26C31RH-Q | 5962F9666301V9A |
| LOR2568C-Q40I | 5962H9215303QNC | LM2595J-12 (GEN) | 5962-9650201QEA | HS0-26CLV31RH-Q | 5962F9666302V9A |
| LOR2568C-Q40X | 5962H9215303QXC | LM2595J-3.3 (GEN) | 5962-9687901QEA | HS0-26CT31RH-Q | 5962F9563201V9A |
| LOR2568C-Q40Y | 5962H9215303QYC | LM2595J-5 (GEN) | 5962-9650301QEA | HS1-26C31RH-8 | 5962F9666301QEC |
| LOR2568C-V40I | 5962H9215303VNC | OP260A (GEN) | 5962-90536012A | HS1-26C31RH-Q | 5962F9666301VEC |
| LOR2568C-V40X | 5962H9215303VXC | OP260A (GEN) | 5962-9053601GA | HS1-26C31RH-T | 5962R9666301TEC |
| LOR2568C-V40Y | 5962H9215303VYC | OP260A (GEN) | 5962-9053601PA | HS1-26CLV31RH-8 | 5962F9666302QEC |
| LOR2568T-Q40I | 5962H9215304QNC | HS-2600 (GEN) | 5962D9567101VPC | HS1-26CLV31RH-Q | 5962F9666302VEC |
| LOR2568T-Q40X | 5962H9215304QXC | 26S02/BEA | 5962-8766201EA | HS1-26CLV31RH-T | 5962R9666302TEC |
| LOR2568T-Q40Y | 5962H9215304QYC | 26S02/BFA | 5962-8766201FA | HS1-26CT31RH-Q | 5962F9563201VEC |
| LOR2568T-V40I | 5962H9215304VNC | 26S10/B2A | 5962-86720012A | HS1-26CT31RH-T | 5962R9563201TEC |
| LOR2568T-V40X | 5962H9215304VXC | 26S10/BEA | 5962-8672001EA | HS9-26C31RH-8 | 5962F9666301QXC |
| LOR2568T-V40Y | 5962H9215304VYC | 26S10/BFA | 5962-8672001FA | HS9-26C31RH-Q | 5962F9666301VXC |
| WS256K8-45CQ | 5962-9315706HXC | 26S12A/B2A | 5962-87534022A | HS9-26C31RH-T | 5962R9666301TXC |
| WS256K8-45CQ | 5962-9315706HYC | 26S12A/BEA | 5962-8753402EA | HS9-26CLV31RH-8 | 5962F9666302QXC |
| WS256K8-45CQA | 5962-9315706HXA | 26S12A/BFA | 5962-8753402FA | HS9-26CLV31RH-Q | 5962F9666302VXC |
| WS256K8-45CQA | 5962-9315706HYA | HS-2620 (GEN) | 5962D9568801VGA | HS9-26CLV31RH-T | 5962R9666302TXC |
| LMP2568C-V45X | 5962R9689101VXA | HS-2620 (GEN) | 5962D9568801VPC | HS9-26CT31RH-Q | 5962F9563201VXC |
| LMP2568T-Q45X | 5962R9689102QXA | HS-2622 (GEN) | 5962D9568802VGC | HS9-26CT31RH-T | 5962R9563201TXC |
| LMP2568T-V45X | 5962R9689102VXA | HS7B-2622RH-Q | 5962D9568802VPC | QP26LS31/B2A | 5962-7802301M2A |
| MT5C2568ECW-55883 | 5962-8866203YA | 26LS29 (GEN) | 5962-8767001EA | QP26LS31/BEA | 5962-7802301MEA |
| MT5C2568F-55883C | 5962-8866203TA | 26LS29 (GEN) | 5962-8767001FA | QP26LS31/BFA | 5962-7802301MFA |
| WS256K8-55CQ | 5962-9315705HXC | 26LS30 (GEN) | 5962-86721012A | RHD26C31K01Q | 5962D9666301QXC |
| WS256K8-55CQ | 5962-9315705HYC | 26LS30 (GEN) | 5962-8672101FA | RHD26C31K01V | 5962D9666301VXC |
| WS256K8-55CQA | 5962-9315705HXA | 26LS31 (GEN) | 78023012A | RHD26CT31K01Q | 5962D9563201QXC |
| WS256K8-55CQA | 5962-9315705HYA | 26LS31 (GEN) | 7802301EA | RHD26CT31K01V | 5962D9563201VXC |
| 2568T60 (GEN) | 5962H9215302QZA | 26LS31 (GEN) | 7802301FA | RHD26C31K02Q | 5962D9666301QXA |
| 2568T60 (GEN) | 5962H9215302VZA | AM26C31MFKB | 5962-9163901Q2A | RHD26C31K02V | 5962D9666301VXA |
| LOR2568C-Q60I | 5962H9215301QNC | AM26C31MJB | 5962-9163901QEA | RHD26CT31K02Q | 5962D9563201QXA |
| LOR2568C-Q60X | 5962H9215301QXC | AM26C31MWB | 5962-9163901QFA | RHD26CT31K02V | 5962D9563201VXA |
| LOR2568C-Q60Y | 5962H9215301QYC | DS26C31ME/883 | 5962-9163901M2A | RHD26C31D08Q | 5962D9666301QEC |
| LOR2568C-V60I | 5962H9215301VNC | DS26C31MJ/883 | 5962-9163901MEA | RHD26C31D08V | 5962D9666301VEC |
| LOR2568C-V60X | 5962H9215301VXC | DS26C31MW/883 | 5962-9163901MFA | RHD26CT31D08Q | 5962D9563201QEC |
| LOR2568C-V60Y | 5962H9215301VYC | DS26C31MWG/883 | 5962-9163901MXA | RHD26CT31D08V | 5962D9563201VEC |
| LOR2568T-Q60I | 5962H9215302QNC | DS26F31ME/883 | 5962-7802302M2A | RHD26C31D09Q | 5962D9666301QEA |
| LOR2568T-Q60X | 5962H9215302QXC | DS26F31MJ/883 | 5962-7802302MEA | RHD26C31D09V | 5962D9666301VEA |
| LOR2568T-Q60Y | 5962H9215302QYC | DS26F31MJFQMLV | 5962F7802302VEA | RHD26CT31D09Q | 5962D9563201QEA |
| LOR2568T-V60I | 5962H9215302VNC | DS26F31MJ-QMLV | 5962-7802302VEA | RHD26CT31D09V | 5962D9563201VEA |
| LOR2568T-V60X | 5962H9215302VXC | DS26F31MW/883 | 5962-7802302MFA | HS1-26CT31RH-8 | 5962F9563201QEC |
| LOR2568T-V60Y | 5962H9215302VYC | DS26F31MWFQMLV | 5962F7802302VFA | HS9-26CT31RH-8 | 5962F9563201QXC |
| WS256K8-70CQ | 5962-9315704HXC | DS26F31MWG/883 | 5962-7802302MZA | DS26LS31ME/883 | 5962-7802301Q2A |
| WS256K8-70CQ | 5962-9315704HYC | DS26F31MWGFQMLV | 5962F7802302VZA | 26F32 (GEN) | 5962F7802005Q2A |
| WS256K8-70CQA | 5962-9315704HXA | DS26F31MW-QMLV | 5962-7802302VFA | 26F32 (GEN) | 5962F7802005QEA |
| WS256K8-70CQA | 5962-9315704HYA | DS26LS31MEFQML | 5962F7802301Q2A | 26F32 (GEN) | 5962F7802005QFA |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

| Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN |
|---|---|---|---|---|---|
| 26F32 (GEN) | 5962F7802005VEA | RHP26C32K02V | 5962P9568901VXA | TLC2652M (GEN) | 5962-9089501BPA |
| 26F32 (GEN) | 5962F7802005VFA | RHP26CT32K02Q | 5962P9563101QXA | TLC2652MFKB | 5962-9089501M2A |
| 26LS32 (GEN) | 78020012A | RHP26CT32K02V | 5962P9563101VXA | TLC2652MJB | 5962-9089501MCA |
| 26LS32 (GEN) | 7802001EA | RHP26C32D08Q | 5962P9568901QEC | TLC2652MJGB | 5962-9089501MPA |
| 26LS32 (GEN) | 7802001FA | RHP26C32D08V | 5962P9568901VEC | TLC2652MLB (GEN) | 5962-9089501MGA |
| 26LS32A (GEN) | 7802003FA | RHP26CT32D08Q | 5962P9563101QEC | TLC2654AMFKB | 5962-9089504Q2A |
| 26LS32B (GEN) | 5962-87616012A | RHP26CT32D08V | 5962P9563101VEC | TLC2654AMJB | 5962-9089504QCA |
| 26LS32B (GEN) | 5962-8761601EA | RHP26C32D09Q | 5962P9568901QEA | TLC2654AMJGB | 5962-9089504QPA |
| 26LS32B (GEN) | 5962-8761601FA | RHP26C32D09V | 5962P9568901VEA | TLC2654M (GEN) | 5962-9089502BPA |
| AM26C32MFKB | 5962-9164001Q2A | RHP26CT32D09Q | 5962P9563101QEA | TLC2654M (GEN) | 5962-9089502MGA |
| AM26C32MJB | 5962-9164001QEA | RHP26CT32D09V | 5962P9563101VEA | TLC2654MFKB | 5962-9089502M2A |
| AM26C32MWB | 5962-9164001QFA | HS0-26C32RH-Q | 5962F9568901V9A | TLC2654MJB | 5962-9089502MCA |
| AM26LS32AMFKB | 5962-7802003M2A | HS0-26CLV32RH-Q | 5962F9568902V9A | TLC2654MJGB | 5962-9089502MPA |
| AM26LS32AMFKB | 78020032A | HS1-26C32RH-8 | 5962F9568901QEC | HCPL-268K | 5962-9800101KEC |
| AM26LS32AMJB | 5962-7802003MEA | HS1-26C32RH-Q | 5962F9568901VEC | 2681 (GEN) | 5962-8856601XA |
| AM26LS32AMJB | 7802003EA | HS1-26C32RH-T | 5962R9568901TEC | 2681 (GEN) | 5962-8856602QA |
| AM26LS32AMWB | 5962-7802003MFA | HS1-26CLV32RH-8 | 5962F9568902QEC | 2681 (GEN) | 5962-8856602UA |
| DS26C32AME/883 | 5962-9164001M2A | HS1-26CLV32RH-Q | 5962F9568902VEC | 2681 (GEN) | 5962-8856602YA |
| DS26C32AMJ/883 | 5962-9164001MEA | HS1-26CLV32RH-T | 5962R9568902TEC | HCPL-268K#100 | 5962-9800101KUA |
| DS26C32AMW/883 | 5962-9164001MFA | HS9-26C32RH-8 | 5962F9568901QXC | HCPL-268K#100 | 5962-9800101KUC |
| DS26C32MWG/883 | 5962-9164001MXA | HS9-26C32RH-Q | 5962F9568901VXC | HCPL-268K#200 | 5962-9800101KEA |
| DS26F32ME/883 | 5962-7802005M2A | HS9-26C32RH-T | 5962R9568901TXC | HCPL-268K#300 | 5962-9800101KTA |
| DS26F32MER-QML | 5962R7802005Q2A | HS9-26CLV32RH-8 | 5962F9568902QXC | 2692/BQA | 5962-8953202QA |
| DS26F32MJ/883 | 5962-7802005MEA | HS9-26CLV32RH-Q | 5962F9568902VXC | 2692/BUA | 5962-8953202UA |
| DS26F32MJ-QMLV | 5962-7802005VEA | HS9-26CLV32RH-T | 5962R9568902TXC | 2692/BXA | 5962-8953201XA |
| DS26F32MJR-QML | 5962R7802005QEA | 26LS33 (GEN) | 78020022A | 2692/BYA | 5962-8953202YA |
| DS26F32MJRQMLV | 5962R7802005VEA | 26LS33 (GEN) | 7802002EA | 26C94 (GEN) | 5962-9471001MXA |
| DS26F32MW/883 | 5962-7802005MFA | 26LS33 (GEN) | 7802002FA | ACS27 (GEN) | 5962F9863001V9A |
| DS26F32MWG/883 | 5962-7802005MZA | 26LS33A (GEN) | 78020042A | ACS27 (GEN) | 5962F9863001VCC |
| DS26F32MWG-QMLV | 5962-7802005VZA | AM26LS33AMFKB | 5962-7802004M2A | ACS27 (GEN) | 5962F9863001VXC |
| DS26F32MWGRQMLV | 5962R7802005VZA | AM26LS33AMJB | 5962-7802004MEA | HCS27DMSR | 5962R9578001VCC |
| DS26F32MW-QMLV | 5962-7802005VFA | AM26LS33AMJB | 7802004EA | HCS27HMSR | 5962R9578001V9A |
| DS26F32MWR-QML | 5962R7802005QFA | AM26LS33AMWB | 5962-7802004MFA | HCS27KMSR | 5962R9578001VXC |
| DS26F32MWRQMLV | 5962R7802005VFA | AM26LS33AMWB | 7802004FA | HCTS27 (GEN) | 5962R9573401V9A |
| DS26LS32ME/883 | 5962-7802006Q2A | QP26LS33/B2A | 5962-7802002M2A | HCTS27 (GEN) | 5962R9573401VCC |
| DS26LS32MJ/883 | 5962-7802006QEA | QP26LS33/BEA | 5962-7802002MEA | HCTS27 (GEN) | 5962R9573401VXC |
| DS26LS32MW/883 | 5962-7802006QFA | QP26LS33/BFA | 5962-7802002MFA | OP27AJ/QMLR | 5962R9468002VGA |
| DS26LV32AW-QML | 5962-9858501QFA | 26LS34 (GEN) | 5962-87596012A | OP27AL/QMLR | 5962R9468002VHA |
| HS0-26CT32RH-Q | 5962F9563101V9A | 26LS34 (GEN) | 5962-8759601EA | OP27ARC/QMLR | 5962R9468002V2A |
| HS1-26CT32RH-8 | 5962F9563101QEC | 26LS34 (GEN) | 5962-8759601FA | OP27AZ/QMLR | 5962R9468002VPA |
| HS1-26CT32RH-Q | 5962F9563101VEC | 2640 (GEN) | 78003022A | OP27B (GEN) | 5962-9468001M2A |
| HS1-26CT32RH-T | 5962R9563101TEC | HA2-2640/883 | 7800302GC | OP-270A (GEN) | 5962-88721012A |
| HS9-26CT32RH-8 | 5962F9563101QXC | HA7-2640/883 | 7800302PA | OP-270AM/QMLR | 5962R8872101VDA |
| HS9-26CT32RH-Q | 5962F9563101VXC | GEM26401Q2A | 5962-88577012A | OP-270AM/QMLV | 5962-8872101VDA |
| HS9-26CT32RH-T | 5962R9563101TXC | GEM26401Q2C | 5962-88577012C | OP-270ARC/QMLR | 5962R8872101V2A |
| QP26LS32/B2A | 5962-7802001M2A | GEM26401QEA | 5962-8857701EA | OP-270ARC/QMLV | 5962-8872101V2A |
| QP26LS32/BEA | 5962-7802001MEA | GEM26401QEC | 5962-8857701EC | OP-270AZ/883C | 5962-8872101PA |
| QP26LS32/BFA | 5962-7802001MFA | GEM26401QFA | 5962-8857701FA | OP-270AZ/QMLR | 5962R8872101VPA |
| RHP26C32K01Q | 5962P9568901QXC | GEM26401QFC | 5962-8857701FC | OP-270AZ/QMLV | 5962-8872101VPA |
| RHP26C32K01V | 5962P9568901VXC | TLC2652A (GEN) | 5962-9089503MGA | 2700 (GEN) | 8503001CA |
| RHP26CT32K01Q | 5962P9563101QXC | TLC2652AMFKB | 5962-9089503M2A | 2700 (GEN) | 8503001XA |
| RHP26CT32K01V | 5962P9563101VXC | TLC2652AMJB | 5962-9089503MCA | 2700U (GEN) | 8503002CA |
| RHP26C32K02Q | 5962P9568901QXA | TLC2652AMJGB | 5962-9089503MPA | 2700U (GEN) | 8503002XC |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

| Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN |
|---|---|---|---|---|---|
| 27LS00/BEA | 8602001EA | AFL27009SZ/CH | 5962-9553501HZA | 27C010A-20 (GEN) | 5962-8961403QYA |
| 27LS00/BFA | 8602001FA | AFL27009SZ/CH | 5962-9553501HZC | AS27C010A-20ECAM | 5962-8961417QYA |
| 27LS00A/BEA | 8602002EA | 2701 (GEN) | 5962-9552701QJA | AT27C010-20CMB | 5962-8961403MYA |
| 27LS00A/BFA | 8602002FA | 2701 (GEN) | 8503005CA | AT27C010-20CMB | 5962-8961403MYC |
| AD2700SD/883B | 8503001YA | 2701 (GEN) | 8503006CA | AT27C010-20DMB | 5962-8961403MXA |
| AD2700UD/883B | 8503002YA | 27LS01 (GEN) | 8602003EA | AT27C010-20DMB | 5962-8961403XA |
| HC2700SD/883B | 8503001YA | 27LS01 (GEN) | 8602003FA | AT27C010-20LMB | 5962-8961403YA |
| HC2700SLCC/883B | 85030013A | 27LS01A (GEN) | 8602004EA | SMJ27C010A-20JM | 5962-8961417QXA |
| HC2700UD/883B | 8503002YA | 27LS01A (GEN) | 8602004FA | WS27C010L-20CMB | 5962-8961403MYA |
| HC2700ULCC/883B | 85030023A | HC2701SD/883B | 8503005YA | WS27C010L-20CMB | 5962-8961403MYC |
| HS1B-2700RH-Q | 5962D9567002VCC | HC2701SLCC/883B | 85030053A | WS27C010L-20DMB | 5962-8961403MXA |
| HS2-2700RH-Q | 5962D9567002VGA | HC2701UD/883B | 8503006YA | AT27C010-25CMB | 5962-8961402MYA |
| MG2700E | 5962-00B0208Q*C | HC2701ULCC/883B | 85030063A | AT27C010-25CMB | 5962-8961402MYC |
| AFL27003.3SW/CH | 5962-9955301HUA | 27C010A-12 (GEN) | 5962-8961406QXA | AT27C010-25DMB | 5962-8961402MXA |
| AFL27003.3SW/CH | 5962-9955301HUC | 27C010A-12 (GEN) | 5962-8961406QYA | AT27C010-25DMB | 5962-8961402XA |
| AFL27003.3SX/CH | 5962-9955301HXA | AS27C010A-12ECAM | 5962-8961420QYA | AT27C010-25LMB | 5962-8961402YA |
| AFL27003.3SX/CH | 5962-9955301HXC | AT27C010-12CMB | 5962-8961406MYA | WS27C010L-25CMB | 5962-8961402MYA |
| AFL27003.3SY/CH | 5962-9955301HYA | AT27C010-12CMB | 5962-8961406MYC | WS27C010L-25CMB | 5962-8961402MYC |
| AFL27003.3SY/CH | 5962-9955301HYC | AT27C010-12DMB | 5962-8961406MXA | WS27C010L-25DMB | 5962-8961402MXA |
| AFL27003.3SZ/CH | 5962-9955301HZA | AT27C010-12DMB | 5962-8961406XA | AT27C010-30CMB | 5962-8961401MYA |
| AFL27003.3SZ/CH | 5962-9955301HZC | AT27C010-12LMB | 5962-8961406YA | AT27C010-30CMB | 5962-8961401MYC |
| AFL27005DW/CH | 5962-9550101HUA | SMJ27C010A-12JM | 5962-8961420QXA | AT27C010-30DMB | 5962-8961401MXA |
| AFL27005DW/CH | 5962-9550101HUC | WS27C010L-12CMB | 5962-8961406MYA | AT27C010-30DMB | 5962-8961401XA |
| AFL27005DX/CH | 5962-9550101HXA | WS27C010L-12CMB | 5962-8961406MYC | AT27C010-30LMB | 5962-8961401YA |
| AFL27005DX/CH | 5962-9550101HXC | WS27C010L-12DMB | 5962-8961406MXA | WS27C010L-30CMB | 5962-8961401MYA |
| AFL27005DY/CH | 5962-9550101HYA | AT27C010L-12DMB | 5962-8961411MXA | WS27C010L-30CMB | 5962-8961401MYC |
| AFL27005DY/CH | 5962-9550101HYC | AT27C010L-12LMB | 5962-8961411MYA | WS27C010L-30DMB | 5962-8961401MXA |
| AFL27005DZ/CH | 5962-9550101HZA | 27C010A-15 (GEN) | 5962-8961405QXA | 27H010-35 (GEN) | 5962-8961416QXA |
| AFL27005DZ/CH | 5962-9550101HZC | 27C010A-15 (GEN) | 5962-8961405QYA | 27H010-35 (GEN) | 5962-8961416QYA |
| AFL27005SW/CH | 5962-9456901HUA | AS27C010A-15ECAM | 5962-8961419QYA | 27H010-45 (GEN) | 5962-8961415QXA |
| AFL27005SW/CH | 5962-9456901HUC | AT27C010-15CMB | 5962-8961405MYA | 27H010-45 (GEN) | 5962-8961415QYA |
| AFL27005SX/CH | 5962-9456901HXA | AT27C010-15CMB | 5962-8961405MYC | 27H010-55 (GEN) | 5962-8961414QXA |
| AFL27005SX/CH | 5962-9456901HXC | AT27C010-15DMB | 5962-8961405MXA | 27H010-55 (GEN) | 5962-8961414QYA |
| AFL27005SY/CH | 5962-9456901HYA | AT27C010-15DMB | 5962-8961405XA | 27H010-70 (GEN) | 5962-8961413QXA |
| AFL27005SY/CH | 5962-9456901HYC | AT27C010-15LMB | 5962-8961405YA | 27H010-70 (GEN) | 5962-8961413QYA |
| AFL27005SZ/CH | 5962-9456901HZA | SMJ27C010A-15JM | 5962-8961419QXA | AT27C010L-90DMB | 5962-8961412MXA |
| AFL27005SZ/CH | 5962-9456901HZC | WS27C010L-15CMB | 5962-8961405MYA | AT27C010L-90LMB | 5962-8961412MYA |
| MHP27005 (GEN) | 5962-9477201HXA | WS27C010L-15CMB | 5962-8961405MYC | AFL27012DW/CH | 5962-9951801HUA |
| MHP27005 (GEN) | 5962-9477201HXC | WS27C010L-15DMB | 5962-8961405MXA | AFL27012DW/CH | 5962-9951801HUC |
| AFL27006SW/CH | 5962-9553401HUA | AT27C010L-15DMB | 5962-8961410MXA | AFL27012DX/CH | 5962-9951801HXA |
| AFL27006SW/CH | 5962-9553401HUC | AT27C010L-15LMB | 5962-8961410MYA | AFL27012DX/CH | 5962-9951801HXC |
| AFL27006SX/CH | 5962-9553401HXA | 27C010A-17 (GEN) | 5962-8961404QYA | AFL27012DY/CH | 5962-9951801HYA |
| AFL27006SX/CH | 5962-9553401HXC | 27CT010-17 (GEN) | 5962-8961404MZA | AFL27012DY/CH | 5962-9951801HYC |
| AFL27006SY/CH | 5962-9553401HYA | AS27C010A-17ECAM | 5962-8961418QYA | AFL27012DZ/CH | 5962-9951801HZA |
| AFL27006SY/CH | 5962-9553401HYC | AT27C010-17CMB | 5962-8961404MYA | AFL27012DZ/CH | 5962-9951801HZC |
| AFL27006SZ/CH | 5962-9553401HZA | AT27C010-17CMB | 5962-8961404MYC | AFL27012SW/CH | 5962-9475301HUA |
| AFL27006SZ/CH | 5962-9553401HZC | AT27C010-17DMB | 5962-8961404MXA | AFL27012SW/CH | 5962-9475301HUC |
| AFL27009SW/CH | 5962-9553501HUA | AT27C010-17DMB | 5962-8961404XA | AFL27012SX/CH | 5962-9475301HXA |
| AFL27009SW/CH | 5962-9553501HUC | AT27C010-17LMB | 5962-8961404YA | AFL27012SX/CH | 5962-9475301HXC |
| AFL27009SX/CH | 5962-9553501HXA | WS27C010L-17CMB | 5962-8961404MYA | AFL27012SY/CH | 5962-9475301HYA |
| AFL27009SX/CH | 5962-9553501HXC | WS27C010L-17CMB | 5962-8961404MYC | AFL27012SY/CH | 5962-9475301HYC |
| AFL27009SY/CH | 5962-9553501HYA | WS27C010L-17DMB | 5962-8961404MXA | AFL27012SZ/CH | 5962-9475301HZA |
| AFL27009SY/CH | 5962-9553501HYC | 27C010A-20 (GEN) | 5962-8961403QXA | AFL27012SZ/CH | 5962-9475301HZC |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART II, Listed By Generic PIN

| Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN |
|---|---|---|---|---|---|
| MHP27012D (GEN) | 5962-9556301HXA | 27C020-150 (GEN) | 5962-9091203MXA | 27LS07-30 (GEN) | 7801506EA |
| MHP27012D (GEN) | 5962-9556301HXC | 27C020-150 (GEN) | 5962-9091203MYA | 27LS07-30 (GEN) | 7801506FA |
| MHP27012S (GEN) | 5962-9556001HXA | 27C020-200 (GEN) | 5962-9091202MXA | DG271AK/883 | 5962-8671602EA |
| MHP27012S (GEN) | 5962-9556001HXC | 27C020-200 (GEN) | 5962-9091202MYA | DG271AZ/883 | 5962-86716022A |
| AFL27015DW/CH | 5962-9553201HUA | 27C020-250 (GEN) | 5962-9091201MXA | OP-271A (GEN) | 5962-88721022A |
| AFL27015DW/CH | 5962-9553201HUC | 27C020-250 (GEN) | 5962-9091201MYA | OP-271A (GEN) | 5962-8872102PA |
| AFL27015DX/CH | 5962-9553201HXA | 27S02-20 (GEN) | 86051072A | AT27C1024-12/QA | 5962-8680506QA |
| AFL27015DX/CH | 5962-9553201HXC | 27S02-20 (GEN) | 8605107EA | AT27C1024-12/XA | 5962-8680506XA |
| AFL27015DY/CH | 5962-9553201HYA | 27S02-20 (GEN) | 8605107FA | AT27C1024-15/QA | 5962-8680505QA |
| AFL27015DY/CH | 5962-9553201HYC | AFL27025SW/CH | 5962-9650101HUA | AT27C1024-15/XA | 5962-8680505XA |
| AFL27015DZ/CH | 5962-9553201HZA | AFL27025SW/CH | 5962-9650101HUC | AT27C1024-17/QA | 5962-8680504QA |
| AFL27015DZ/CH | 5962-9553201HZC | AFL27025SX/CH | 5962-9650101HXA | AT27C1024-17/XA | 5962-8680504XA |
| AFL27015SW/CH | 5962-9457001HUA | AFL27025SX/CH | 5962-9650101HXC | AT27C1024-17/XC | 5962-8680504XC |
| AFL27015SW/CH | 5962-9457001HUC | AFL27025SY/CH | 5962-9650101HYA | AT27C1024-20/QA | 5962-8680503QA |
| AFL27015SX/CH | 5962-9457001HXA | AFL27025SY/CH | 5962-9650101HYC | AT27C1024-20/XA | 5962-8680503XA |
| AFL27015SX/CH | 5962-9457001HXC | AFL27025SZ/CH | 5962-9650101HZA | AT27C1024-25/QA | 5962-8680502QA |
| AFL27015SY/CH | 5962-9457001HYA | AFL27025SZ/CH | 5962-9650101HZC | AT27C1024-25/XA | 5962-8680502XA |
| AFL27015SY/CH | 5962-9457001HYC | AFL27028SW/CH | 5962-9556501HUA | AT27C1024-30/QA | 5962-8680501QA |
| AFL27015SZ/CH | 5962-9457001HZA | AFL27028SW/CH | 5962-9556501HUC | AT27C1024-30/XA | 5962-8680501XA |
| AFL27015SZ/CH | 5962-9457001HZC | AFL27028SX/CH | 5962-9556501HXA | AT27HC1024-70/QA | 5962-8680508QA |
| MHP27015D (GEN) | 5962-9556401HXA | AFL27028SX/CH | 5962-9556501HXC | AT27HC1024-70/XA | 5962-8680508XA |
| MHP27015D (GEN) | 5962-9556401HXC | AFL27028SY/CH | 5962-9556501HYA | AT27C1024-90/QA | 5962-8680507QA |
| MHP27015S (GEN) | 5962-9556101HXA | AFL27028SY/CH | 5962-9556501HYC | AT27C1024-90/XA | 5962-8680507XA |
| MHP27015S (GEN) | 5962-9556101HXC | AFL27028SZ/CH | 5962-9556501HZA | MC27128A-11/BYA | 8202507YA |
| AFL27018.2DW/CH | 5962-9550201HUA | AFL27028SZ/CH | 5962-9556501HZC | MR27128A-11/BZA | 8202507ZA |
| AFL27018.2DW/CH | 5962-9550201HUC | MHP27028S (GEN) | 5962-9556201HXA | 27C128-120 | 5962-8766102XA |
| AFL27018.2DX/CH | 5962-9550201HXA | MHP27028S (GEN) | 5962-9556201HXC | 27C128-120 | 5962-8766102YC |
| AFL27018.2DX/CH | 5962-9550201HXC | 27LS03 (GEN) | 86051062A | MC27128A-15/BYA | 8202506YA |
| AFL27018.2DY/CH | 5962-9550201HYA | 27S03A (GEN) | 86051052A | MR27128A-15/BZA | 8202506ZA |
| AFL27018.2DY/CH | 5962-9550201HYC | 27S03A (GEN) | 8605105EA | 27C128-150 | 5962-8766103XA |
| AFL27018.2DZ/CH | 5962-9550201HZA | 27S03A (GEN) | 8605105FA | 27C128-150 | 5962-8766103YC |
| AFL27018.2DZ/CH | 5962-9550201HZC | 27S03-20 (GEN) | 86051082A | 27C128-170 | 5962-8766104XA |
| 2702S (GEN) | 8503003CA | 27S03-20 (GEN) | 8605108EA | 27C128-170 | 5962-8766104YC |
| 2702S (GEN) | 8503003XA | 27S03-20 (GEN) | 8605108FA | MC27128A-20/BYA | 8202503YA |
| 2702U (GEN) | 8503004CA | 27LS03-30 (GEN) | 86051092A | MR27128A-20/BZA | 8202503ZA |
| 2702U (GEN) | 8503004XA | 27LS03-30 (GEN) | 8605109EA | 27128-200 (GEN) | 8202508YA |
| 27LS02 (GEN) | 86051032A | 27LS03-30 (GEN) | 8605109FA | 27128-200 (GEN) | 8202508ZA |
| 27LS02 (GEN) | 8605103EA | 27C040-12 (GEN) | 5962-9175205MYA | 27C128-200 | 5962-8766105XA |
| 27LS02 (GEN) | 8605103FA | SMJ27C040-12JM | 5962-9175205MXA | 27C128-200 | 5962-8766105YC |
| 27S02 (GEN) | 86051012A | SMJ27C040-15JM | 5962-9175204MXA | MC27128A-25/BYA | 8202505YA |
| 27S02 (GEN) | 8605101EA | 27C040-150 (GEN) | 5962-9175204MYA | MR27128A-25/BZA | 8202505ZA |
| 27S02 (GEN) | 8605101FA | 27C040-17 (GEN) | 5962-9175203MXA | 27128-250 (GEN) | 8202502YA |
| 27S02A (GEN) | 86051022A | 27C040-17 (GEN) | 5962-9175203MYA | 27128-250 (GEN) | 8202502ZA |
| 27S02A (GEN) | 8605102EA | 27C040-200 (GEN) | 5962-9175202MXA | 27C128-250 | 5962-8766106XA |
| 27S02A (GEN) | 8605102FA | 27C040-200 (GEN) | 5962-9175202MYA | 27C128-250 | 5962-8766106YC |
| AD2702S (GEN) | 8503003YC | 27C040-250 (GEN) | 5962-9175201MXA | MC27128A-30/BYA | 8202504YA |
| AD2702SD/883B | 8503003YA | 27C040-250 (GEN) | 5962-9175201MYA | MR27128A-30/BZA | 8202504ZA |
| AD2702UD/883B | 8503004YA | UC2707 (GEN) | 5962-8761902NXB | 27128-300 (GEN) | 8202509YA |
| AD2702UD/883B | 8503004YC | UC2707 (GEN) | 5962-8761902NYB | 27128-300 (GEN) | 8202509ZA |
| HC2702SD/883B | 8503003YA | 27S07-20 (GEN) | 78015052A | 27C128-300 | 5962-8766107XA |
| HC2702SLCC/883B | 85030033A | 27S07-20 (GEN) | 7801505EA | 27C128-300 | 5962-8766107YC |
| HC2702UD/883B | 8503004YA | 27S07-20 (GEN) | 7801505FA | 27128-450 (GEN) | 8202501YA |
| HC2702ULCC/883B | 85030043A | 27LS07-30 (GEN) | 78015062A | 27128-450 (GEN) | 8202501ZA |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART II, Listed By Generic PIN

| Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN |
|---|---|---|---|---|---|
| 27C128-70 | 5962-8766108XA | WS27C256L-12DMB | 5962-8606306XA | 27C256-25 (GEN) | 5962-8606302ZA |
| 27C128-70 | 5962-8766108YC | 27C256A-120 (GEN) | 5962-8606316QXA | AT27C256R-25/UA | 5962-8606302UA |
| 27C128-90 | 5962-8766101XA | 27C256A-120 (GEN) | 5962-8606316QYA | AT27C256R-25/UA | 5962-8606312UA |
| 27C128-90 | 5962-8766101YC | AT27C256R-15/UA | 5962-8606305UA | AT27C256R-25/XA | 5962-8606302XA |
| 27S13 (GEN) | 5962-88541022A | AT27C256R-15/UA | 5962-8606315UA | AT27C256R-25/XA | 5962-8606312XA |
| 27S13 (GEN) | 5962-8854102EA | AT27C256R-15/XA | 5962-8606305XA | AT27C256R-25/YA | 5962-8606302YA |
| 27S13 (GEN) | 5962-8854102FA | AT27C256R-15/XA | 5962-8606315XA | AT27C256R-25/YA | 5962-8606312YA |
| 27S13A (GEN) | 5962-88541012A | AT27C256R-15/YA | 5962-8606305YA | AT27C256R-25/YC | 5962-8606302YC |
| 27S13A (GEN) | 5962-8854101EA | AT27C256R-15/YA | 5962-8606315YA | SMJ27C256-25JM | 5962-8606302XA |
| 27S13A (GEN) | 5962-8854101FA | AT27C256R-15/YC | 5962-8606305YC | WS27C256L-25CMB | 5962-8606302YA |
| MC2716M/BJA | 7802201JA | SMJ27C256-15JM | 5962-8606305XA | WS27C256L-25CMB | 5962-8606302YC |
| 27S19 (GEN) | 5962-86703012A | WS27C256L-15CMB | 5962-8606305YA | WS27C256L-25DMB | 5962-8606302XA |
| 27S19A (GEN) | 5962-86703022A | WS27C256L-15CMB | 5962-8606305YC | WS27C256L-25TMB | 5962-8606302UA |
| 27PS191 (GEN) | 5962-85526013A | WS27C256L-15DMB | 5962-8606305XA | 27C256A-250 (GEN) | 5962-8606312QXA |
| 27PS191 (GEN) | 5962-8552601JA | WS27C256L-15TMB | 5962-8606305UA | 27C256A-250 (GEN) | 5962-8606312QYA |
| 27PS191 (GEN) | 5962-8552601KA | 27C256-150 (GEN) | 5962-8606305ZA | 27256-30 (GEN) | 8411105YA |
| 27PS191 (GEN) | 5962-8552601XA | 27C256A-150 (GEN) | 5962-8606315QXA | 27C256-30 (GEN) | 5962-8606303ZA |
| 27PS191A (GEN) | 5962-85526023A | 27C256A-150 (GEN) | 5962-8606315QYA | AT27C256R-30/UA | 5962-8606303UA |
| 27PS191A (GEN) | 5962-8552602JA | 27256-17 (GEN) | 8411104YA | AT27C256R-30/UA | 5962-8606313UA |
| 27PS191A (GEN) | 5962-8552602KA | 27C256-17(GEN) | 5962-8606304ZA | AT27C256R-30/XA | 5962-8606303XA |
| 27PS191A (GEN) | 5962-8552602XA | AT27C256R-17/UA | 5962-8606304UA | AT27C256R-30/XA | 5962-8606313XA |
| TLC272 (GEN) | 5962-89494012A | AT27C256R-17/UA | 5962-8606314UA | AT27C256R-30/YA | 5962-8606303YA |
| TLC272 (GEN) | 5962-8949401HA | AT27C256R-17/XA | 5962-8606304XA | AT27C256R-30/YA | 5962-8606313YA |
| TLC272 (GEN) | 5962-8949401PA | AT27C256R-17/XA | 5962-8606314XA | AT27C256R-30/YC | 5962-8606303YC |
| TLC27L2 (GEN) | 5962-89494032A | AT27C256R-17/YA | 5962-8606304YA | SMJ27C256-30JM | 5962-8606303XA |
| TLC27L2 (GEN) | 5962-8949403HA | AT27C256R-17/YA | 5962-8606314YA | WS27C256L-30CMB | 5962-8606303YA |
| TLC27L2 (GEN) | 5962-8949403PA | AT27C256R-17/YC | 5962-8606304YC | WS27C256L-30CMB | 5962-8606303YC |
| TLC27M2 (GEN) | 5962-89494052A | SMJ27C256-17JM | 5962-8606304XA | WS27C256L-30DMB | 5962-8606303XA |
| TLC27M2 (GEN) | 5962-8949405HA | WS27C256L-17CMB | 5962-8606304YA | WS27C256L-30TMB | 5962-8606303UA |
| TLC27M2 (GEN) | 5962-8949405PA | WS27C256L-17CMB | 5962-8606304YC | 27C256A-300 (GEN) | 5962-8606313QXA |
| 27C2048 (GEN) | 5962-9214003MQA | WS27C256L-17DMB | 5962-8606304XA | 27C256A-300 (GEN) | 5962-8606313QYA |
| 27C2048 (GEN) | 5962-9214003MXA | WS27C256L-17TMB | 5962-8606304UA | 27256-35 (GEN) | 8411101YA |
| 27C2048 (GEN) | 5962-9214002MQA | 27C256A-170 (GEN) | 5962-8606314QXA | 27256-35 (GEN) | 8411101ZA |
| 27C2048 (GEN) | 5962-9214002MXA | 27C256A-170 (GEN) | 5962-8606314QYA | 27C256A-35 (GEN) | 5962-8606321QXA |
| 27C2048 (GEN) | 5962-9214001MQA | 27256-20 (GEN) | 8411103YA | 27C256A-35 (GEN) | 5962-8606321QYA |
| 27C2048 (GEN) | 5962-9214001MXA | 27256-20 (GEN) | 8411103ZA | 27C256A-45 (GEN) | 5962-8606320QXA |
| 27S21 (GEN) | 5962-87788012A | 27C256-20 (GEN) | 5962-8606301ZA | 27C256A-45 (GEN) | 5962-8606320QYA |
| 27S21A (GEN) | 5962-87788022A | AT27C256R-20/UA | 5962-8606301UA | AT27C256F-45/YC | 5962-8606310YC |
| 27210 (GEN) | 5962-8774401QA | AT27C256R-20/UA | 5962-8606311UA | AT27C256R-45/XA | 5962-8606310XA |
| 27210 (GEN) | 5962-8774402QA | AT27C256R-20/XA | 5962-8606301XA | AT27C256R-45/YA | 5962-8606310YA |
| MOHO272C (GEN) | 5962-8858201EA | AT27C256R-20/XA | 5962-8606311XA | 27C256A-55 (GEN) | 5962-8606319QXA |
| MOHO272C (GEN) | 5962-8858201FA | AT27C256R-20/YA | 5962-8606301YA | 27C256A-55 (GEN) | 5962-8606319QYA |
| MOHO272C (GEN) | 5962-88582012A | AT27C256R-20/YA | 5962-8606311YA | AT27C256R-55/UA | 5962-8606309UA |
| 27C256-120 (GEN) | 5962-8606306ZA | AT27C256R-20/YC | 5962-8606301YC | AT27C256R-55/UA | 5962-8606319UA |
| AT27C256R-12/UA | 5962-8606306UA | SMJ27C256-20JM | 5962-8606301XA | AT27C256R-55/XA | 5962-8606319XA |
| AT27C256R-12/UA | 5962-8606316UA | WS27C256L-20CMB | 5962-8606301YA | AT27C256R-55/YA | 5962-8606319YA |
| AT27C256R-12/XA | 5962-8606306XA | WS27C256L-20CMB | 5962-8606301YC | 27C256-70 (GEN) | 5962-8606308ZA |
| AT27C256R-12/XA | 5962-8606316XA | WS27C256L-20DMB | 5962-8606301XA | 27C256A-70 (GEN) | 5962-8606318QXA |
| AT27C256R-12/YA | 5962-8606306YA | WS27C256L-20TMB | 5962-8606301UA | 27C256A-70 (GEN) | 5962-8606318QYA |
| AT27C256R-12/YA | 5962-8606316YA | 27C256A-200 (GEN) | 5962-8606311QXA | AT27C256R-70/UA | 5962-8606308UA |
| AT27C256R-12/YC | 5962-8606306YC | 27C256A-200 (GEN) | 5962-8606311QYA | AT27C256R-70/XA | 5962-8606308XA |
| WS27C256L-12CMB | 5962-8606306YA | 27256-25 (GEN) | 8411102YA | AT27C256R-70/XA | 5962-8606318UA |
| WS27C256L-12CMB | 5962-8606306YC | 27256-25 (GEN) | 8411102ZA | AT27C256R-70/XA | 5962-8606318XA |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART II, Listed By Generic PIN

| Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN |
|---|---|---|---|---|---|
| AT27C256R-70/YA | 5962-8606308YA | X-27S37-032-EC-03 | 5962-04A0103QXA | 27512-25 (GEN) | 5962-8513501YA |
| AT27C256R-70/YA | 5962-8606318YA | X-27S37-032-EC-04 | 5962-04A0104QXA | AS27C512-25ECAM | 5962-8764803YA |
| AT27C256R-70/YC | 5962-8606308YC | X-27S37-032-EC-05 | 5962-04A0105QXA | AS27C512-25ECAM | 5962-8764814QYA |
| 27C256-90 (GEN) | 5962-8606307ZA | X-27S37-032-EC-06 | 5962-04A0106QXA | AS27C512-25JM | 5962-8764814QXA |
| 27C256A-90 (GEN) | 5962-8606317QXA | X-27S37-032-EC-07 | 5962-04A0107QXA | SMJ27C512-25JM | 5962-8764803XA |
| 27C256A-90 (GEN) | 5962-8606317QYA | X-27S37-032-EC-08 | 5962-04A0108QXA | 27C512-250 (GEN) | 5962-8764803ZA |
| AT27C256R-90/UA | 5962-8606307UA | X-27S37-032-EC-09 | 5962-04A0109QXA | 27512-30 (GEN) | 5962-8513503YA |
| AT27C256R-90/UA | 5962-8606317UA | X-27S37-032-EC-10 | 5962-04A0110QXA | 27512-30 (GEN) | 5962-8513503ZA |
| AT27C256R-90/XA | 5962-8606307XA | TLC274 (GEN) | 5962-90604012A | 27512-35 (GEN) | 5962-8513502YA |
| AT27C256R-90/XA | 5962-8606317XA | TLC274 (GEN) | 5962-9060401CA | 27H512-35 (GEN) | 5962-8764809QXA |
| AT27C256R-90/YA | 5962-8606307YA | TLC274 (GEN) | 5962-9060401DA | 27H512-35 (GEN) | 5962-8764809QYA |
| AT27C256R-90/YA | 5962-8606317YA | TLC27L4 (GEN) | 5962-90604052A | 27512-45 (GEN) | 5962-8513504YA |
| AT27C256R-90/YC | 5962-8606307YC | TLC27L4 (GEN) | 5962-9060405CA | 27512-45 (GEN) | 5962-8513504ZA |
| 27S29 (GEN) | 5962-87690012A | TLC27L4 (GEN) | 5962-9060405DA | 27C512-45 (GEN) | 5962-8764808QXA |
| 27S29 (GEN) | 5962-8769001RA | TLC27M4 (GEN) | 5962-90604032A | 27C512-45 (GEN) | 5962-8764808QYA |
| 27S29 (GEN) | 5962-8769001SA | TLC27M4 (GEN) | 5962-9060403CA | 27C512-55 (GEN) | 5962-8764807QXA |
| 27S29A (GEN) | 5962-87690022A | TLC27M4 (GEN) | 5962-9060403DA | 27C512-55 (GEN) | 5962-8764807QYA |
| 27S29A (GEN) | 5962-8769002RA | 27S43A (GEN) | 8200802XA | 27C512-70 (GEN) | 5962-8764806QXA |
| 27S29A (GEN) | 5962-8769002SA | 27S45 (GEN) | 5962-85527013A | 27C512-70 (GEN) | 5962-8764806QYA |
| 27PS291 (GEN) | 5962-8552603LA | 27S45 (GEN) | 5962-8552701KA | 27C512-90 (GEN) | 5962-8764805XA |
| 27PS291A (GEN) | 5962-8552604LA | 27S45 (GEN) | 5962-8552701LA | 27C512-90 (GEN) | 5962-8764805YA |
| HCS273DMSR | 5962R9579101VRC | 27S45 (GEN) | 5962-8552701XA | 27C512-90 (GEN) | 5962-8764805ZA |
| HCS273HMSR | 5962R9579101V9A | 27S45A (GEN) | 5962-85527023A | 27C512-90 (GEN) | 5962-8764810QXA |
| HCS273KMSR | 5962R9579101VXC | 27S45A (GEN) | 5962-8552702KA | 27C512-90 (GEN) | 5962-8764810QYA |
| HCTS273 (GEN) | 5962R9576401V9A | 27S45A (GEN) | 5962-8552702LA | HCPL-275K | 5962-8767905KEC |
| HCTS273DMSR | 5962R9576401VRC | 27S45A (GEN) | 5962-8552702XA | HCPL-275K#100 | 5962-8767905KUA |
| HCTS273KMSR | 5962R9576401VXC | 27S47 (GEN) | 5962-85527033A | HCPL-275K#100 | 5962-8767905KUC |
| 27S31 (GEN) | 7801601UA | 27S47 (GEN) | 5962-8552703KA | HCPL-275K#200 | 5962-8767905KEA |
| 27S31A (GEN) | 78016023A | 27S47 (GEN) | 5962-8552703LA | HCPL-275K#300 | 5962-8767905KTA |
| 27S31A (GEN) | 7801602JA | 27S47 (GEN) | 5962-8552703XA | 27C64-12 (GEN) | 8510205YA |
| 27S31A (GEN) | 7801602KA | 27S47A (GEN) | 5962-85527043A | 27C64-12 (GEN) | 8510205ZA |
| 27S31A (GEN) | 7801602UA | 27S47A (GEN) | 5962-8552704KA | 27C64-15 (GEN) | 8510206YA |
| 2732 (GEN) | 8001201JA | 27S47A (GEN) | 5962-8552704LA | 27C64-15 (GEN) | 8510206ZA |
| 2732A25 (GEN) | 8001203JA | 27S47A (GEN) | 5962-8552704XA | 2764-150 (GEN) | 8200506YA |
| 2732A45 (GEN) | 8001204JA | 27S49A (GEN) | 8200902KA | 2764A-20 (GEN) | 8200505YA |
| 27S35 (GEN) | 5962-86706013A | 27S49A (GEN) | 8200902ZA | 2764A-20 (GEN) | 8200505ZA |
| 27S35 (GEN) | 5962-8670601KA | R29791 | 8200901KA | 27C64-20/YA | 8510203YA |
| 27S35 (GEN) | 5962-8670601LA | AS27C512-12ECAM | 5962-8764804YA | 27C64-20/ZA | 8510203ZA |
| 27S35 (GEN) | 5962-8670601XA | AS27C512-12ECAM | 5962-8764811QYA | MD27C64-20/BYA | 8510203YA |
| 27S35A (GEN) | 5962-86706023A | AS27C512-12JM | 5962-8764804XA | MR27C64-20/BZA | 8510203ZA |
| 27S35A (GEN) | 5962-8670602KA | AS27C512-12JM | 5962-8764811QXA | 2764-200 (GEN) | 8200507YA |
| 27S35A (GEN) | 5962-8670602LA | 27C512-120 (GEN) | 5962-8764804ZA | 2764A-25 (GEN) | 8200504YA |
| 27S35A (GEN) | 5962-8670602XA | AS27C512-15ECAM | 5962-8764801YA | 2764A-25 (GEN) | 8200504ZA |
| 27S37 (GEN) | 5962-86706033A | AS27C512-15ECAM | 5962-8764812QYA | MD27C64-25/BYA | 8510201YA |
| 27S37 (GEN) | 5962-8670603KA | AS27C512-15JM | 5962-8764812QXA | MR27C64-25/BZA | 8510201ZA |
| 27S37 (GEN) | 5962-8670603LA | SMJ27C512-15JM | 5962-8764801XA | 2764-250 (GEN) | 8200502YA |
| 27S37 (GEN) | 5962-8670603XA | 27C512-150 (GEN) | 5962-8764801ZA | 2764-250 (GEN) | 8200502ZA |
| 27S37A (GEN) | 5962-86706043A | 27512-20 (GEN) | 5962-8513505YA | 2764A-35 (GEN) | 8200503YA |
| 27S37A (GEN) | 5962-8670604KA | AS27C512-20ECAM | 5962-8764802YA | 2764A-35 (GEN) | 8200503ZA |
| 27S37A (GEN) | 5962-8670604LA | AS27C512-20ECAM | 5962-8764813QYA | MD27C64-35/BYA | 8510202YA |
| 27S37A (GEN) | 5962-8670604XA | AS27C512-20JM | 5962-8764813QXA | MR27C64-35/BZA | 8510202ZA |
| X-27S37-032-EC-01 | 5962-04A0101QXA | SMJ27C512-20JM | 5962-8764802XA | 2764-450 (GEN) | 8200501YA |
| X-27S37-032-EC-02 | 5962-04A0102QXA | 27C512-200 (GEN) | 5962-8764802ZA | 2764-450 (GEN) | 8200501ZA |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

| Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN |
|---|---|---|---|---|---|
| 27C64-90 (GEN) | 8510204YA | SMJ28F010B-12FEM | 5962-9089904QYA | AT28C010-15UM/883 | 5962-3826705MTA |
| 27C64-90 (GEN) | 8510204ZA | SMJ28F010B-12FEM | 5962-9089913QYA | SMJ28F010B-15HKM | 5962-9089903QUA |
| TLC277 (GEN) | 5962-89494022A | SMJ28F010B-12JDDM | 5962-9089904QXA | SMJ28F010B-15HKM | 5962-9089907QUA |
| TLC277 (GEN) | 5962-8949402HA | SMJ28F010B-12JDDM | 5962-9089913QXA | SMJ28F010B-15HKM | 5962-9089912QUA |
| TLC277 (GEN) | 5962-8949402PA | SMJ28F010B-15FEM | 5962-9089903QYA | X28C010DMB-15 | 5962-3826705MXA |
| TLC27L7 (GEN) | 5962-89494042A | SMJ28F010B-15FEM | 5962-9089907QYA | 28C010-150 (GEN) | 5962-3826706MWA |
| TLC27L7 (GEN) | 5962-8949404HA | SMJ28F010B-15JDDM | 5962-9089903QXA | 28C010-150 (GEN) | 5962-3826706MXA |
| TLC27L7 (GEN) | 5962-8949404PA | SMJ28F010B-15JDDM | 5962-9089907QXA | 28C010-150 (GEN) | 5962-3826706MYA |
| TLC27L7MDQ | 5962-9555301NXD | SMJ28F010B-20FEM | 5962-9089902QYA | 28C010-150 (GEN) | 5962-3826706MZA |
| TLC27M7 (GEN) | 5962-89494062A | SMJ28F010B-20FEM | 5962-9089906QYA | 28F010 (GEN) | 5962-9089907MXA |
| TLC27M7 (GEN) | 5962-8949406HA | SMJ28F010B-20FEM | 5962-9089911QYA | 28F010 (GEN) | 5962-9089907MYA |
| TLC27M7 (GEN) | 5962-8949406PA | SMJ28F010B-20JDDM | 5962-9089902QXA | 28F010A (GEN) | 5962-9089912MXA |
| TLV2772AMFKB | 5962-9858802Q2A | SMJ28F010B-20JDDM | 5962-9089906QXA | 28F010A (GEN) | 5962-9089912MYA |
| TLV2772AMJGB | 5962-9858802QPA | SMJ28F010B-20JDDM | 5962-9089911QXA | 28F010A (GEN) | 5962-9323506MXA |
| TLV2772AMUB | 5962-9858802QHA | SMJ28F010B-12FEM | 5962-9089908QYA | 28C010-20 (GEN) | 5962-3826703MWC |
| TLV2772MFKB | 5962-9858801Q2A | SMJ28F010B-12JDDM | 5962-9089908QXA | 28F010 (GEN) | 5962-9089902MTA |
| TLV2772MJGB | 5962-9858801QPA | SMJ28F010B-15FEM | 5962-9089912QYA | 28F010 (GEN) | 5962-9089902MUA |
| TLV2772MUB | 5962-9858801QHA | SMJ28F010B-15JDDM | 5962-9089912QXA | 28F010 (GEN) | 5962-9089902MXA |
| TLC279 (GEN) | 5962-90604022A | 28C010-12 (GEN) | 5962-3826707MWC | 28F010 (GEN) | 5962-9089902MYA |
| TLC279 (GEN) | 5962-9060402CA | 28F010 (GEN) | 5962-9089904MTA | 28F010 (GEN) | 5962-9089902MZA |
| TLC279 (GEN) | 5962-9060402DA | 28F010 (GEN) | 5962-9089904MUA | 28F010 (GEN) | 5962-9089906MTA |
| TLC27L9 (GEN) | 5962-90604062A | 28F010 (GEN) | 5962-9089904MXA | 28F010 (GEN) | 5962-9089906MUA |
| TLC27L9 (GEN) | 5962-9060406CA | 28F010 (GEN) | 5962-9089904MYA | 28F010 (GEN) | 5962-9089906MZA |
| TLC27L9 (GEN) | 5962-9060406DA | 28F010 (GEN) | 5962-9089904MZA | AT28C010-20EM/883 | 5962-3826703MUA |
| TLC27L9MDQ | 5962-9555401NXD | 28F010 (GEN) | 5962-9089908MTA | AT28C010-20FM/883 | 5962-3826703MZA |
| TLC27M9 (GEN) | 5962-90604042A | 28F010 (GEN) | 5962-9089908MUA | AT28C010-20LM/883 | 5962-3826703MYA |
| TLC27M9 (GEN) | 5962-9060404CA | 28F010 (GEN) | 5962-9089908MZA | AT28C010-20UM/883 | 5962-3826703MTA |
| TLC27M9 (GEN) | 5962-9060404DA | AT28C010-12DM/883 | 5962-3826707MXA | SMJ28F010B-20HKM | 5962-9089902QUA |
| ACS280 (GEN) | 5962F9670801VCC | AT28C010-12EM/883 | 5962-3826707MUA | SMJ28F010B-20HKM | 5962-9089906QUA |
| ACS280 (GEN) | 5962F9670801VXC | AT28C010-12FM/883 | 5962-3826707MZA | SMJ28F010B-20HKM | 5962-9089911QUA |
| ACTS280 (GEN) | 5962F9672001VCC | AT28C010-12LM/883 | 5962-3826707MYA | 28C010-200 (GEN) | 5962-3826704MWA |
| ACTS280 (GEN) | 5962F9672001VXC | AT28C010-12UM/883 | 5962-3826707MTA | 28C010-200 (GEN) | 5962-3826704MXA |
| AD2S80ATD/883B | 5962-9096201MQA | SMJ28F010B-12HKM | 5962-9089904QUA | 28C010-200 (GEN) | 5962-3826704MYA |
| AD2S80ATE/883B | 5962-9096201MXA | SMJ28F010B-12HKM | 5962-9089908QUA | 28C010-200 (GEN) | 5962-3826704MZA |
| MAX280MJA/883B | 5962-9159502MPA | SMJ28F010B-12HKM | 5962-9089913QUA | 28F010 (GEN) | 5962-9089906MXA |
| ACS280 (GEN) | 5962F9670802V9A | X28C010DMB-12 | 5962-3826707MXA | 28F010 (GEN) | 5962-9089906MYA |
| ACS280 (GEN) | 5962F9670802VCC | 28F010 (GEN) | 5962-9089908MXA | 28F010A (GEN) | 5962-9089911MXA |
| ACS280 (GEN) | 5962F9670802VXC | 28F010 (GEN) | 5962-9089908MYA | 28F010A (GEN) | 5962-9089911MYA |
| ACTS280 (GEN) | 5962F9672002V9A | 28F010A (GEN) | 5962-9089913MXA | 28C010-25 (GEN) | 5962-3826701MWC |
| ACTS280 (GEN) | 5962F9672002VCC | 28F010A (GEN) | 5962-9089913MYA | 28F010 (GEN) | 5962-9089901MTA |
| ACTS280 (GEN) | 5962F9672002VXC | 28C010-15 (GEN) | 5962-3826705MWC | 28F010 (GEN) | 5962-9089901MUA |
| 28F008 (GEN) | 5962-9455702QQA | 28F010 (GEN) | 5962-9089903MTA | 28F010 (GEN) | 5962-9089901MXA |
| 28F008 (GEN) | 5962-9455702QXA | 28F010 (GEN) | 5962-9089903MUA | 28F010 (GEN) | 5962-9089901MYA |
| 28F008 (GEN) | 5962-9455701QQA | 28F010 (GEN) | 5962-9089903MXA | 28F010 (GEN) | 5962-9089901MZA |
| 28F008 (GEN) | 5962-9455701QXA | 28F010 (GEN) | 5962-9089903MYA | 28F010 (GEN) | 5962-9089905MTA |
| 28C010TFB-12 | 5962-3826719QMC | 28F010 (GEN) | 5962-9089903MZA | 28F010 (GEN) | 5962-9089905MUA |
| 28C010TFB-15 | 5962-3826718QMC | 28F010 (GEN) | 5962-9089907MTA | 28F010 (GEN) | 5962-9089905MZA |
| 28C010TFB-20 | 5962-3826717QMC | 28F010 (GEN) | 5962-9089907MUA | AT28C010-25DM/883 | 5962-3826701MXA |
| 28C010TFB-25 | 5962-3826716QMC | 28F010 (GEN) | 5962-9089907MZA | AT28C010-25EM/883 | 5962-3826701MUA |
| 28C010TRPFB-12 | 5962-3826719Q6C | AT28C010-15DM/883 | 5962-3826705MXA | AT28C010-25FM/883 | 5962-3826701MZA |
| 28C010TRPFB-15 | 5962-3826718Q6C | AT28C010-15EM/883 | 5962-3826705MUA | AT28C010-25LM/883 | 5962-3826701MYA |
| 28C010TRPFB-20 | 5962-3826717Q6C | AT28C010-15FM/883 | 5962-3826705MZA | AT28C010-25UM/883 | 5962-3826701MTA |
| 28C010TRPFB-25 | 5962-3826716Q6C | AT28C010-15LM/883 | 5962-3826705MYA | SMJ28F010B-25FEM | 5962-9089901QYA |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

| Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN |
|---|---|---|---|---|---|
| SMJ28F010B-25FEM | 5962-9089905QYA | AFL2805DW/CH | 5962-9579501HUC | MFL2805DV/883 | 5962-9319101HUC |
| SMJ28F010B-25FEM | 5962-9089910QYA | AFL2805DX/CH | 5962-9579501HXA | MFL2805DW/883 | 5962-9319101HTA |
| SMJ28F010B-25HKM | 5962-9089901QUA | AFL2805DX/CH | 5962-9579501HXC | MFL2805DW/883 | 5962-9319101HTC |
| SMJ28F010B-25HKM | 5962-9089905QUA | AFL2805DY/CH | 5962-9579501HYA | MFL2805DY/883 | 5962-9319101HYA |
| SMJ28F010B-25HKM | 5962-9089910QUA | AFL2805DY/CH | 5962-9579501HYC | MFL2805DY/883 | 5962-9319101HYC |
| SMJ28F010B-25JDDM | 5962-9089901QXA | AFL2805DZ/CH | 5962-9579501HZA | MFL2805DZ/883 | 5962-9319101HZA |
| SMJ28F010B-25JDDM | 5962-9089905QXA | AFL2805DZ/CH | 5962-9579501HZC | MFL2805DZ/883 | 5962-9319101HZC |
| SMJ28F010B-25JDDM | 5962-9089910QXA | AFL2805SW/CH | 5962-9472101HUA | MFL2805S/883 | 5962-9316301HXA |
| 28C010-250 (GEN) | 5962-3826702MWA | AFL2805SW/CH | 5962-9472101HUC | MFL2805S/883 | 5962-9316301HXC |
| 28C010-250 (GEN) | 5962-3826702MXA | AFL2805SX/CH | 5962-9472101HXA | MFL2805SV/883 | 5962-9316301HUA |
| 28C010-250 (GEN) | 5962-3826702MYA | AFL2805SX/CH | 5962-9472101HXC | MFL2805SV/883 | 5962-9316301HUC |
| 28C010-250 (GEN) | 5962-3826702MZA | AFL2805SY/CH | 5962-9472101HYA | MFL2805SW/883 | 5962-9316301HTA |
| 28F010 (GEN) | 5962-9089905MXA | AFL2805SY/CH | 5962-9472101HYC | MFL2805SW/883 | 5962-9316301HTC |
| 28F010 (GEN) | 5962-9089905MYA | AFL2805SZ/CH | 5962-9472101HZA | MFL2805SY/883 | 5962-9316301HYA |
| 28F010A (GEN) | 5962-9089910MXA | AFL2805SZ/CH | 5962-9472101HZC | MFL2805SY/883 | 5962-9316301HYC |
| 28F010A (GEN) | 5962-9089910MYA | AHE2805S/CH | 5962-8968301HXA | MFL2805SZ/883 | 5962-9316301HZA |
| 28F010 (GEN) | 5962-9089909MTA | AHE2805S/CH-MSTR | 5962-8968303HXA | MFL2805SZ/883 | 5962-9316301HZC |
| 28F010 (GEN) | 5962-9089909MUA | AHE2805S/CH-SLV | 5962-8968302HXA | MGA2805D/883 | 5962-0052201HYA |
| 28F010 (GEN) | 5962-9089909MXA | AHE2805SF/CH | 5962-8968301HZA | MGA2805D/883 | 5962-0052201HYC |
| 28F010 (GEN) | 5962-9089909MYA | AHE2805SF/CH-MSTR | 5962-8968303HZA | MGA2805DZ/883 | 5962-0052201HZA |
| 28F010 (GEN) | 5962-9089909MZA | AHE2805SF/CH-SLV | 5962-8968302HZA | MGA2805SY/883 | 5962-9309201HYA |
| 28C011TRPFB-12 | 5962-3826719Q7C | AHF2805S/CH | 5962-9160001HXA | MGA2805SY/883 | 5962-9309201HYC |
| 28C011TRPFB-15 | 5962-3826718Q7C | AHF2805SF/CH | 5962-9160001HZA | MGA2805SZ/883 | 5962-9309201HZA |
| 28C011TRPFB-20 | 5962-3826717Q7C | AHV2805SF/CH | 5962-9177301HZA | MGH2805DY/883 | 5962-9570201HYA |
| 28C011TRPFB-25 | 5962-3826716Q7C | ASA2805S/CH | 5962-9462901HXA | MGH2805DY/883 | 5962-9570201HYC |
| 28F016SV (GEN) | 5962-9562502NXB | ATR2805S/CH | 5962-9462401HXA | MGH2805DZ/883 | 5962-9570201HZA |
| 28F016SV (GEN) | 5962-9562504NXB | ATR2805SF/CH | 5962-9462401HZA | MGH2805S/883 | 5962-9569601HYA |
| 28F016SV (GEN) | 5962-9562501NXB | ATW2805S/CH | 5962-9157904HZA | MGH2805S/883 | 5962-9569601HYC |
| 28F016SV (GEN) | 5962-9562503NXB | ATW2805S/CH-MSTR | 5962-9157906HZA | MGH2805SZ/883 | 5962-9569601HZA |
| 28F020 (GEN) | 5962-9323503MUA | ATW2805S/CH-SLV | 5962-9157905HZA | MHD2805D/883 | 5962-9465901HXA |
| 28F020 (GEN) | 5962-9323503MXA | DHC2805SH | 5962-9309203HUA | MHD2805D/883 | 5962-9465901HXC |
| 28F020A (GEN) | 5962-9323507MXA | DHC2805SH | 5962-9309203HUC | MHD2805DF/883 | 5962-9465901HZA |
| 28F020 (GEN) | 5962-9323502MUA | DHC2805SH | 5962-9462902HYA | MHD2805DF/883 | 5962-9465901HZC |
| 28F020 (GEN) | 5962-9323502MXA | DHC2805SH | 5962-9462902HYC | MHD2805S/883 | 5962-9465501HXA |
| 28F020 (GEN) | 5962-9323501MUA | DVHF2805D/H | 5962-0324401HXC | MHD2805S/883 | 5962-9465501HXC |
| 28F020 (GEN) | 5962-9323501MXA | DVHF2805D/H-E | 5962-0324401HXA | MHD2805SF/883 | 5962-9465501HZA |
| 28F020A (GEN) | 5962-9323505MXA | DVHF2805DF/H | 5962-0324401HYC | MHD2805SF/883 | 5962-9465501HZC |
| 28F020 (GEN) | 5962-9323504MUA | DVHF2805DF/H-E | 5962-0324401HYA | MHF+2805D/883 | 5962-9555901HXA |
| 28F020 (GEN) | 5962-9323504MXA | DVHF2805S/H | 5962-0324302HXC | MHF+2805D/883 | 5962-9555901HXC |
| 28F020A (GEN) | 5962-9323508MXA | DVHF2805S/H-E | 5962-0324302HXA | MHF+2805DF/883 | 5962-9555901HZA |
| SG2803J/883B | 5962-8605801VA | DVHF2805SF/H | 5962-0324302HYC | MHF+2805DF/883 | 5962-9555901HZC |
| SG2803L/883B | 5962-86058012A | DVHF2805SF/H-E | 5962-0324302HYA | MHF+2805S/883 | 5962-9213901HXA |
| AFL2803.3SW/CH | 5962-9955201HUA | DVSA2805D/H | 5962-0324201HXC | MHF+2805S/883 | 5962-9213901HXC |
| AFL2803.3SW/CH | 5962-9955201HUC | DVSA2805D/H-E | 5962-0324201HXA | MHF+2805SF/883 | 5962-9213901HZA |
| AFL2803.3SX/CH | 5962-9955201HXA | DVSA2805S/H | 5962-0324102HXC | MHF+2805SF/883 | 5962-9213901HZC |
| AFL2803.3SX/CH | 5962-9955201HXC | DVSA2805S/H-E | 5962-0324102HXA | MHV2805D/883 | 5962-9852501HXA |
| AFL2803.3SY/CH | 5962-9955201HYA | MCH2805D/883 | 5962-9570201HXA | MHV2805D/883 | 5962-9852501HXC |
| AFL2803.3SY/CH | 5962-9955201HYC | MCH2805D/883 | 5962-9570201HXC | MHV2805DF/883 | 5962-9852501HZA |
| AFL2803.3SZ/CH | 5962-9955201HZA | MCH2805S/883 | 5962-9569601HXA | MHV2805DF/883 | 5962-9852501HZC |
| AFL2803.3SZ/CH | 5962-9955201HZC | MCH2805S/883 | 5962-9569601HXC | MHV2805S/883 | 5962-9852201HXA |
| 2805DN (GEN) | 5962-9570501HXA | MFL2805D/883 | 5962-9319101HXA | MHV2805S/883 | 5962-9852201HXC |
| 2805SN (GEN) | 5962-9569901HXA | MFL2805D/883 | 5962-9319101HXC | MHV2805SF/883 | 5962-9852201HZA |
| AFL2805DW/CH | 5962-9579501HUA | MFL2805DV/883 | 5962-9319101HUA | MHV2805SF/883 | 5962-9852201HZC |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

| Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN |
|---|---|---|---|---|---|
| MOR2805D/883 | 5962-9956101HXA | SMFL2805S/KR | 5962R9316302KXC | SMHF2805S/KR | 5962R9213902KXA |
| MOR2805D/883 | 5962-9956101HXC | SMFL2805SV/HO | 5962-9316302HUA | SMHF2805S/KR | 5962R9213902KXC |
| MOR2805DV/883 | 5962-9956101HUA | SMFL2805SV/HO | 5962-9316302HUC | SMHF2805SF/HL | 5962L9213902HZA |
| MOR2805DV/883 | 5962-9956101HUC | SMFL2805SV/HR | 5962R9316302HUA | SMHF2805SF/HL | 5962L9213902HZC |
| MOR2805DW/883 | 5962-9956101HTA | SMFL2805SV/HR | 5962R9316302HUC | SMHF2805SF/HO | 5962-9213902HZA |
| MOR2805DW/883 | 5962-9956101HTC | SMFL2805SV/KR | 5962R9316302KUA | SMHF2805SF/HO | 5962-9213902HZC |
| MOR2805DY/883 | 5962-9956101HYA | SMFL2805SV/KR | 5962R9316302KUC | SMHF2805SF/HR | 5962R9213902HZA |
| MOR2805DY/883 | 5962-9956101HYC | SMFL2805SW/HO | 5962-9316302HTA | SMHF2805SF/HR | 5962R9213902HZC |
| MOR2805DZ/883 | 5962-9956101HZA | SMFL2805SW/HO | 5962-9316302HTC | SMHF2805SF/KL | 5962L9213902KZA |
| MOR2805DZ/883 | 5962-9956101HZC | SMFL2805SW/HR | 5962R9316302HTA | SMHF2805SF/KL | 5962L9213902KZC |
| MOR2805S/883 | 5962-9954801HXA | SMFL2805SW/HR | 5962R9316302HTC | SMHF2805SF/KR | 5962R9213902KZA |
| MOR2805S/883 | 5962-9954801HXC | SMFL2805SW/KR | 5962R9316302KTA | SMHF2805SF/KR | 5962R9213902KZC |
| MOR2805SV/883 | 5962-9954801HUA | SMFL2805SW/KR | 5962R9316302KTC | SMSA2805S/HL | 5962L9309202HXA |
| MOR2805SV/883 | 5962-9954801HUC | SMFL2805SY/HO | 5962-9316302HYA | SMSA2805S/HL | 5962L9309202HXC |
| MOR2805SW/883 | 5962-9954801HTA | SMFL2805SY/HO | 5962-9316302HYC | SMSA2805S/HO | 5962-9309202HXA |
| MOR2805SW/883 | 5962-9954801HTC | SMFL2805SY/HR | 5962R9316302HYA | SMSA2805S/HO | 5962-9309202HXC |
| MOR2805SY/883 | 5962-9954801HYA | SMFL2805SY/HR | 5962R9316302HYC | SMSA2805S/HR | 5962R9309202HXA |
| MOR2805SY/883 | 5962-9954801HYC | SMFL2805SY/KR | 5962R9316302KYA | SMSA2805S/HR | 5962R9309202HXC |
| MOR2805SZ/883 | 5962-9954801HZA | SMFL2805SY/KR | 5962R9316302KYC | SMSA2805S/KL | 5962L9309202KXA |
| MOR2805SZ/883 | 5962-9954801HZC | SMFL2805SZ/HO | 5962-9316302HZA | SMSA2805S/KL | 5962L9309202KXC |
| MSA2805D/883 | 5962-0052201HXA | SMFL2805SZ/HO | 5962-9316302HZC | SMSA2805S/KR | 5962R9309202KXA |
| MSA2805D/883 | 5962-0052201HXC | SMFL2805SZ/HR | 5962R9316302HZA | SMSA2805S/KR | 5962R9309202KXC |
| MSA2805S/883 | 5962-9309201HXA | SMFL2805SZ/HR | 5962R9316302HZC | SMTR2805S/HL | 5962L9306802HXA |
| MSA2805S/883 | 5962-9309201HXC | SMFL2805SZ/KR | 5962R9316302KZA | SMTR2805S/HL | 5962L9306802HXC |
| MTR2805D/883 | 5962-9320501HXA | SMFL2805SZ/KR | 5962R9316302KZC | SMTR2805S/HO | 5962-9306802HXA |
| MTR2805D/883 | 5962-9320501HXC | SMHF2805D/HL | 5962L9555902HXA | SMTR2805S/HO | 5962-9306802HXC |
| MTR2805DF/883 | 5962-9320501HZA | SMHF2805D/HL | 5962L9555902HXC | SMTR2805S/HR | 5962R9306802HXA |
| MTR2805DF/883 | 5962-9320501HZC | SMHF2805D/HO | 5962-9555902HXA | SMTR2805S/HR | 5962R9306802HXC |
| MTR2805S/883 | 5962-9306801HXA | SMHF2805D/HO | 5962-9555902HXC | SMTR2805S/KL | 5962L9306802KXA |
| MTR2805S/883 | 5962-9306801HXC | SMHF2805D/HR | 5962R9555902HXA | SMTR2805S/KL | 5962L9306802KXC |
| MTR2805SF/883 | 5962-9306801HZA | SMHF2805D/HR | 5962R9555902HXC | SMTR2805S/KR | 5962R9306802KXA |
| MTR2805SF/883 | 5962-9306801HZC | SMHF2805D/KL | 5962L9555902KXA | SMTR2805S/KR | 5962R9306802KXC |
| SLH2805D/HO | 5962-0250401HXA | SMHF2805D/KL | 5962L9555902KXC | SMTR2805SF/HL | 5962L9306802HZA |
| SLH2805D/HO | 5962-0250401HXC | SMHF2805D/KR | 5962R9555902KXA | SMTR2805SF/HL | 5962L9306802HZC |
| SLH2805D/HR | 5962R0250401HXA | SMHF2805D/KR | 5962R9555902KXC | SMTR2805SF/HO | 5962-9306802HZA |
| SLH2805D/HR | 5962R0250401HXC | SMHF2805DF/HL | 5962L9555902HZA | SMTR2805SF/HO | 5962-9306802HZC |
| SLH2805D/KR | 5962R0250401KXA | SMHF2805DF/HL | 5962L9555902HZC | SMTR2805SF/HR | 5962R9306802HZA |
| SLH2805D/KR | 5962R0250401KXC | SMHF2805DF/HO | 5962-9555902HZA | SMTR2805SF/HR | 5962R9306802HZC |
| SLH2805S/HL | 5962L0052601HXA | SMHF2805DF/HO | 5962-9555902HZC | SMTR2805SF/KL | 5962L9306802KZA |
| SLH2805S/HL | 5962L0052601HXC | SMHF2805DF/HR | 5962R9555902HZA | SMTR2805SF/KL | 5962L9306802KZC |
| SLH2805S/HO | 5962-0052601HXA | SMHF2805DF/HR | 5962R9555902HZC | SMTR2805SF/KR | 5962R9306802KZA |
| SLH2805S/HO | 5962-0052601HXC | SMHF2805DF/KL | 5962L9555902KZA | SMTR2805SF/KR | 5962R9306802KZC |
| SLH2805S/HR | 5962R0052601HXA | SMHF2805DF/KL | 5962L9555902KZC | AFL2806.5DW/CH | 5962-9863801HUA |
| SLH2805S/HR | 5962R0052601HXC | SMHF2805DF/KR | 5962R9555902KZA | AFL2806.5DW/CH | 5962-9863801HUC |
| SLH2805S/KL | 5962L0052601KXA | SMHF2805DF/KR | 5962R9555902KZC | AFL2806.5DX/CH | 5962-9863801HXA |
| SLH2805S/KL | 5962L0052601KXC | SMHF2805S/HL | 5962L9213902HXA | AFL2806.5DX/CH | 5962-9863801HXC |
| SLH2805S/KR | 5962R0052601KXA | SMHF2805S/HL | 5962L9213902HXC | AFL2806.5DY/CH | 5962-9863801HYA |
| SLH2805S/KR | 5962R0052601KXC | SMHF2805S/HO | 5962-9213902HXA | AFL2806.5DY/CH | 5962-9863801HYC |
| SMFL2805S/HO | 5962-9316302HXA | SMHF2805S/HO | 5962-9213902HXC | AFL2806.5DZ/CH | 5962-9863801HZA |
| SMFL2805S/HO | 5962-9316302HXC | SMHF2805S/HR | 5962R9213902HXA | AFL2806.5DZ/CH | 5962-9863801HZC |
| SMFL2805S/HR | 5962R9316302HXA | SMHF2805S/HR | 5962R9213902HXC | AFL2808SW/CH | 5962-9665901HUA |
| SMFL2805S/HR | 5962R9316302HXC | SMHF2805S/KL | 5962L9213902KXA | AFL2808SW/CH | 5962-9665901HUC |
| SMFL2805S/KR | 5962R9316302KXA | SMHF2805S/KL | 5962L9213902KXC | AFL2808SX/CH | 5962-9665901HXA |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

| Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN |
|---|---|---|---|---|---|
| AFL2808SX/CH | 5962-9665901HXC | AHV2812TF/CH | 5962-9211501HZA | MFL2812SY/883 | 5962-9316201HYA |
| AFL2808SY/CH | 5962-9665901HYA | ASA2812D/CH | 5962-9564801HXA | MFL2812SY/883 | 5962-9316201HYC |
| AFL2808SY/CH | 5962-9665901HYC | ASA2812S/CH | 5962-9463101HXA | MFL2812SZ/883 | 5962-9316201HZA |
| AFL2808SZ/CH | 5962-9665901HZA | ATO2812T/CH | 5962-9160201HXA | MFL2812SZ/883 | 5962-9316201HZC |
| AFL2808SZ/CH | 5962-9665901HZC | ATO2812TF/CH | 5962-9160201HZA | MGA2812DY/883 | 5962-9308901HYA |
| AT28C010-20DM/883 | 5962-3826703MXA | ATR2812D/CH | 5962-9462701HXA | MGA2812DY/883 | 5962-9308901HYC |
| 2812DN (GEN) | 5962-9570601HXA | ATR2812DF/CH | 5962-9462701HZA | MGA2812DZ/883 | 5962-9308901HZA |
| 2812SN (GEN) | 5962-9570001HXA | ATR2812S/CH | 5962-9462501HXA | MGA2812SY/883 | 5962-9309301HYA |
| 2815SN (GEN) | 5962-9570101HXA | ATR2812SF/CH | 5962-9462501HZA | MGA2812SY/883 | 5962-9309301HYC |
| AFL2812DW/CH | 5962-9579601HUA | ATR2812T/CH | 5962-9315801HXA | MGA2812SZ/883 | 5962-9309301HZA |
| AFL2812DW/CH | 5962-9579601HUC | ATR2812TF/CH | 5962-9315801HZA | MGH2812DY/883 | 5962-9570301HYA |
| AFL2812DX/CH | 5962-9579601HXA | ATW2812D/CH | 5962-9210901HZA | MGH2812DY/883 | 5962-9570301HYC |
| AFL2812DX/CH | 5962-9579601HXC | ATW2812D/CH-MSTR | 5962-9210903HZA | MGH2812DZ/883 | 5962-9570301HZA |
| AFL2812DY/CH | 5962-9579601HYA | ATW2812D/CH-SLV | 5962-9210902HZA | MGH2812SY/883 | 5962-9569701HYA |
| AFL2812DY/CH | 5962-9579601HYC | ATW2812S/CH | 5962-9211001HZA | MGH2812SY/883 | 5962-9569701HYC |
| AFL2812DZ/CH | 5962-9579601HZA | ATW2812S/CH-MSTR | 5962-9211003HZA | MGH2812SZ/883 | 5962-9569701HZA |
| AFL2812DZ/CH | 5962-9579601HZC | ATW2812S/CH-SLV | 5962-9211002HZA | MHD2812D/883 | 5962-9466001HXA |
| AFL2812SW/CH | 5962-9472201HUA | DAC2812SH | 5962-9309303HUA | MHD2812D/883 | 5962-9466001HXC |
| AFL2812SW/CH | 5962-9472201HUC | DAC2812SH | 5962-9309303HUC | MHD2812DF/883 | 5962-9466001HZA |
| AFL2812SX/CH | 5962-9472201HXA | DAC2812SH | 5962-9463102HYA | MHD2812DF/883 | 5962-9466001HZC |
| AFL2812SX/CH | 5962-9472201HXC | DAC2812SH | 5962-9463102HYC | MHD2812S/883 | 5962-9465601HXA |
| AFL2812SY/CH | 5962-9472201HYA | DVHF2812D/H | 5962-0324402HXC | MHD2812S/883 | 5962-9465601HXC |
| AFL2812SY/CH | 5962-9472201HYC | DVHF2812D/H-E | 5962-0324402HXA | MHD2812SF/883 | 5962-9465601HZA |
| AFL2812SZ/CH | 5962-9472201HZA | DVHF2812DF/H | 5962-0324402HYC | MHD2812SF/883 | 5962-9465601HZC |
| AFL2812SZ/CH | 5962-9472201HZC | DVHF2812DF/H-E | 5962-0324402HYA | MHF+2812D (GEN) | 5962-9214401HYA |
| AHE2812D/CH | 5962-9204001HXA | DVHF2812S/H | 5962-0324304HXC | MHF+2812D/883 | 5962-9214401HXA |
| AHE2812D/CH-MSTR | 5962-9204003HXA | DVHF2812S/H-E | 5962-0324304HXA | MHF+2812D/883 | 5962-9214401HXC |
| AHE2812D/CH-SLV | 5962-9204002HXA | DVHF2812SF/H | 5962-0324304HYC | MHF+2812DF/883 | 5962-9214401HZA |
| AHE2812DF/CH | 5962-9204001HZA | DVHF2812SF/H-E | 5962-0324304HYA | MHF+2812DF/883 | 5962-9214401HZC |
| AHE2812DF/CH-MSTR | 5962-9204003HZA | DVSA2812D/H | 5962-0324202HXC | MHF+2812S/883 | 5962-9166401HXA |
| AHE2812DF/CH-SLV | 5962-9204002HZA | DVSA2812D/H-E | 5962-0324202HXA | MHF+2812S/883 | 5962-9166401HXC |
| AHE2812S/CH | 5962-9158001HXA | DVSA2812S/H | 5962-0324104HXC | MHF+2812SF/883 | 5962-9166401HZA |
| AHE2812S/CH | 5962-9158001HXC | DVSA2812S/H-E | 5962-0324104HXA | MHF+2812SF/883 | 5962-9166401HZC |
| AHE2812S/CH-MSTR | 5962-9158003HXA | MCH2812D/883 | 5962-9570301HXA | MHV2812D/883 | 5962-9852601HXA |
| AHE2812S/CH-MSTR | 5962-9158003HXC | MCH2812D/883 | 5962-9570301HXC | MHV2812D/883 | 5962-9852601HXC |
| AHE2812S/CH-SLV | 5962-9158002HXA | MCH2812S/883 | 5962-9569701HXA | MHV2812DF/883 | 5962-9852601HZA |
| AHE2812S/CH-SLV | 5962-9158002HXC | MCH2812S/883 | 5962-9569701HXC | MHV2812DF/883 | 5962-9852601HZC |
| AHE2812SF/CH | 5962-9158001HZA | MFL2812D/883 | 5962-9319201HXA | MHV2812S/883 | 5962-9852301HXA |
| AHE2812SF/CH | 5962-9158001HZC | MFL2812D/883 | 5962-9319201HXC | MHV2812S/883 | 5962-9852301HXC |
| AHE2812SF/CH-MSTR | 5962-9158003HZA | MFL2812DV/883 | 5962-9319201HUA | MHV2812SF/883 | 5962-9852301HZA |
| AHE2812SF/CH-MSTR | 5962-9158003HZC | MFL2812DV/883 | 5962-9319201HUC | MHV2812SF/883 | 5962-9852301HZC |
| AHE2812SF/CH-SLV | 5962-9158002HZA | MFL2812DW/883 | 5962-9319201HTA | MOR2812D/883 | 5962-9956201HXA |
| AHE2812SF/CH-SLV | 5962-9158002HZC | MFL2812DW/883 | 5962-9319201HTC | MOR2812D/883 | 5962-9956201HXC |
| AHF2812D/CH | 5962-9211101HXA | MFL2812DY/883 | 5962-9319201HYA | MOR2812DV/883 | 5962-9956201HUA |
| AHF2812D/CH | 5962-9211101HXC | MFL2812DY/883 | 5962-9319201HYC | MOR2812DV/883 | 5962-9956201HUC |
| AHF2812DF/CH | 5962-9211101HZA | MFL2812DZ/883 | 5962-9319201HZA | MOR2812DW/883 | 5962-9956201HTA |
| AHF2812DF/CH | 5962-9211101HZC | MFL2812DZ/883 | 5962-9319201HZC | MOR2812DW/883 | 5962-9956201HTC |
| AHF2812S/CH | 5962-9456801HXA | MFL2812S/883 | 5962-9316201HXA | MOR2812DY/883 | 5962-9956201HYA |
| AHF2812S/CH | 5962-9456801HXC | MFL2812S/883 | 5962-9316201HXC | MOR2812DY/883 | 5962-9956201HYC |
| AHF2812SF/CH | 5962-9456801HZA | MFL2812SV/883 | 5962-9316201HUA | MOR2812DZ/883 | 5962-9956201HZA |
| AHF2812SF/CH | 5962-9456801HZC | MFL2812SV/883 | 5962-9316201HUC | MOR2812DZ/883 | 5962-9956201HZC |
| AHV2812DF/CH | 5962-9211401HZA | MFL2812SW/883 | 5962-9316201HTA | MOR2812S/883 | 5962-9954901HXA |
| AHV2812SF/CH | 5962-9211201HZA | MFL2812SW/883 | 5962-9316201HTC | MOR2812S/883 | 5962-9954901HXC |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

| Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN |
|---|---|---|---|---|---|
| MOR2812SV/883 | 5962-9954901HUA | SMHF2812DF/HO | 5962-9214402HZC | SMTR2812S/KL | 5962L9306902KXA |
| MOR2812SV/883 | 5962-9954901HUC | SMHF2812DF/HR | 5962R9214402HZA | SMTR2812S/KL | 5962L9306902KXC |
| MOR2812SW/883 | 5962-9954901HTA | SMHF2812DF/HR | 5962R9214402HZC | SMTR2812S/KR | 5962R9306902KXA |
| MOR2812SW/883 | 5962-9954901HTC | SMHF2812DF/KL | 5962L9214402KZA | SMTR2812S/KR | 5962R9306902KXC |
| MOR2812SY/883 | 5962-9954901HYA | SMHF2812DF/KL | 5962L9214402KZC | SMTR2812SF/HL | 5962L9306902HZA |
| MOR2812SY/883 | 5962-9954901HYC | SMHF2812DF/KR | 5962R9214402KZA | SMTR2812SF/HL | 5962L9306902HZC |
| MOR2812SZ/883 | 5962-9954901HZA | SMHF2812DF/KR | 5962R9214402KZC | SMTR2812SF/HO | 5962-9306902HZA |
| MOR2812SZ/883 | 5962-9954901HZC | SMHF2812S/HL | 5962L9166402HXA | SMTR2812SF/HO | 5962-9306902HZC |
| MSA2812D/883 | 5962-9308901HXA | SMHF2812S/HL | 5962L9166402HXC | SMTR2812SF/HR | 5962R9306902HZA |
| MSA2812D/883 | 5962-9308901HXC | SMHF2812S/HO | 5962-9166402HXA | SMTR2812SF/HR | 5962R9306902HZC |
| MSA2812S/883 | 5962-9309301HXA | SMHF2812S/HO | 5962-9166402HXC | SMTR2812SF/KL | 5962L9306902KZA |
| MSA2812S/883 | 5962-9309301HXC | SMHF2812S/HR | 5962R9166402HXA | SMTR2812SF/KL | 5962L9306902KZC |
| MTR2812D/883 | 5962-9307101HXA | SMHF2812S/HR | 5962R9166402HXC | SMTR2812SF/KR | 5962R9306902KZA |
| MTR2812D/883 | 5962-9307101HXC | SMHF2812S/KL | 5962L9166402KXA | SMTR2812SF/KR | 5962R9306902KZC |
| MTR2812DF/883 | 5962-9307101HZA | SMHF2812S/KL | 5962L9166402KXC | WMF2M8-120DAQ5 | 5962-9760902HXA |
| MTR2812DF/883 | 5962-9307101HZC | SMHF2812S/KR | 5962R9166402KXA | WMF2M8-120DAQ5 | 5962-9760902HXC |
| MTR2812S/883 | 5962-9306901HXA | SMHF2812S/KR | 5962R9166402KXC | WMF2M8-120DAQE5 | 5962-9760905HXA |
| MTR2812S/883 | 5962-9306901HXC | SMHF2812SF/HL | 5962L9166402HZA | WMF2M8-120DAQE5 | 5962-9760905HXC |
| MTR2812SF/883 | 5962-9306901HZA | SMHF2812SF/HL | 5962L9166402HZC | 2815DN (GEN) | 5962-9570701HXA |
| MTR2812SF/883 | 5962-9306901HZC | SMHF2812SF/HO | 5962-9166402HZA | AFL2815DW/CH | 5962-9472401HUA |
| SLH2812D/HL | 5962L9955601HXA | SMHF2812SF/HO | 5962-9166402HZC | AFL2815DW/CH | 5962-9472401HUC |
| SLH2812D/HL | 5962L9955601HXC | SMHF2812SF/HR | 5962R9166402HZA | AFL2815DX/CH | 5962-9472401HXA |
| SLH2812D/HO | 5962-9955601HXA | SMHF2812SF/HR | 5962R9166402HZC | AFL2815DX/CH | 5962-9472401HXC |
| SLH2812D/HO | 5962-9955601HXC | SMHF2812SF/KL | 5962L9166402KZA | AFL2815DY/CH | 5962-9472401HYA |
| SLH2812D/HR | 5962R9955601HXA | SMHF2812SF/KL | 5962L9166402KZC | AFL2815DY/CH | 5962-9472401HYC |
| SLH2812D/HR | 5962R9955601HXC | SMHF2812SF/KR | 5962R9166402KZA | AFL2815DZ/CH | 5962-9472401HZA |
| SLH2812D/KL | 5962L9955601KXA | SMHF2812SF/KR | 5962R9166402KZC | AFL2815DZ/CH | 5962-9472401HZC |
| SLH2812D/KL | 5962L9955601KXC | SMSA2812D/HL | 5962L9308902HXA | AFL2815SW/CH | 5962-9472301HUA |
| SLH2812D/KR | 5962R9955601KXA | SMSA2812D/HL | 5962L9308902HXC | AFL2815SW/CH | 5962-9472301HUC |
| SLH2812D/KR | 5962R9955601KXC | SMSA2812D/HO | 5962-9308902HXA | AFL2815SX/CH | 5962-9472301HXA |
| SLH2812S/HL | 5962L0052701HXA | SMSA2812D/HO | 5962-9308902HXC | AFL2815SX/CH | 5962-9472301HXC |
| SLH2812S/HL | 5962L0052701HXC | SMSA2812D/HR | 5962R9308902HXA | AFL2815SY/CH | 5962-9472301HYA |
| SLH2812S/HO | 5962-0052701HXA | SMSA2812D/HR | 5962R9308902HXC | AFL2815SY/CH | 5962-9472301HYC |
| SLH2812S/HO | 5962-0052701HXC | SMSA2812D/KL | 5962L9308902KXA | AFL2815SZ/CH | 5962-9472301HZA |
| SLH2812S/HR | 5962R0052701HXA | SMSA2812D/KL | 5962L9308902KXC | AFL2815SZ/CH | 5962-9472301HZC |
| SLH2812S/HR | 5962R0052701HXC | SMSA2812D/KR | 5962R9308902KXA | AHE2815D/CH | 5962-9157501HXA |
| SLH2812S/KL | 5962L0052701KXA | SMSA2812D/KR | 5962R9308902KXC | AHE2815D/CH-MSTR | 5962-9157503HXA |
| SLH2812S/KL | 5962L0052701KXC | SMSA2812S/HL | 5962L9309302HXA | AHE2815D/CH-SLV | 5962-9157502HXA |
| SLH2812S/KR | 5962R0052701KXA | SMSA2812S/HL | 5962L9309302HXC | AHE2815DF/CH | 5962-9157501HZA |
| SLH2812S/KR | 5962R0052701KXC | SMSA2812S/HO | 5962-9309302HXA | AHE2815DF/CH-MSTR | 5962-9157503HZA |
| SMHF2812D/HL | 5962L9214402HXA | SMSA2812S/HO | 5962-9309302HXC | AHE2815DF/CH-SLV | 5962-9157502HZA |
| SMHF2812D/HL | 5962L9214402HXC | SMSA2812S/HR | 5962R9309302HXA | AHE2815S/CH | 5962-9162501HXA |
| SMHF2812D/HO | 5962-9214402HXA | SMSA2812S/HR | 5962R9309302HXC | AHE2815S/CH | 5962-9162501HXC |
| SMHF2812D/HO | 5962-9214402HXC | SMSA2812S/KL | 5962L9309302KXA | AHE2815S/CH-MSTR | 5962-9162503HXA |
| SMHF2812D/HR | 5962R9214402HXA | SMSA2812S/KL | 5962L9309302KXC | AHE2815S/CH-MSTR | 5962-9162503HXC |
| SMHF2812D/HR | 5962R9214402HXC | SMSA2812S/KR | 5962R9309302KXA | AHE2815S/CH-SLV | 5962-9162502HXA |
| SMHF2812D/KL | 5962L9214402KXA | SMSA2812S/KR | 5962R9309302KXC | AHE2815S/CH-SLV | 5962-9162502HXC |
| SMHF2812D/KL | 5962L9214402KXC | SMTR2812S/HL | 5962L9306902HXA | AHE2815SF/CH | 5962-9162501HZA |
| SMHF2812D/KR | 5962R9214402KXA | SMTR2812S/HL | 5962L9306902HXC | AHE2815SF/CH | 5962-9162501HZC |
| SMHF2812D/KR | 5962R9214402KXC | SMTR2812S/HO | 5962-9306902HXA | AHE2815SF/CH-MSTR | 5962-9162503HZA |
| SMHF2812DF/HL | 5962L9214402HZA | SMTR2812S/HO | 5962-9306902HXC | AHE2815SF/CH-MSTR | 5962-9162503HZC |
| SMHF2812DF/HL | 5962L9214402HZC | SMTR2812S/HR | 5962R9306902HXA | AHE2815SF/CH-SLV | 5962-9162502HZA |
| SMHF2812DF/HO | 5962-9214402HZA | SMTR2812S/HR | 5962R9306902HXC | AHE2815SF/CH-SLV | 5962-9162502HZC |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART II, Listed By Generic PIN

| Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN |
|---|---|---|---|---|---|
| AHF2815D/CH | 5962-9235101HXA | MFL2815DY/883 | 5962-9319301HYA | MOR2815DV/883 | 5962-9956301HUC |
| AHF2815D/CH | 5962-9235101HXC | MFL2815DY/883 | 5962-9319301HYC | MOR2815DW/883 | 5962-9956301HTA |
| AHF2815DF/CH | 5962-9235101HZA | MFL2815DZ/883 | 5962-9319301HZA | MOR2815DW/883 | 5962-9956301HTC |
| AHF2815DF/CH | 5962-9235101HZC | MFL2815DZ/883 | 5962-9319301HZC | MOR2815DY/883 | 5962-9956301HYA |
| AHF2815S/CH | 5962-9456301HXA | MFL2815S/883 | 5962-9316101HXA | MOR2815DY/883 | 5962-9956301HYC |
| AHF2815S/CH | 5962-9456301HXC | MFL2815S/883 | 5962-9316101HXC | MOR2815DZ/883 | 5962-9956301HZA |
| AHF2815SF/CH | 5962-9456301HZA | MFL2815SV/883 | 5962-9316101HUA | MOR2815DZ/883 | 5962-9956301HZC |
| AHF2815SF/CH | 5962-9456301HZC | MFL2815SV/883 | 5962-9316101HUC | MOR2815S/883 | 5962-9955001HXA |
| AHF2815T/CH | 5962-9462301HXA | MFL2815SW/883 | 5962-9316101HTA | MOR2815S/883 | 5962-9955001HXC |
| AHF2815T/CH | 5962-9462301HXC | MFL2815SW/883 | 5962-9316101HTC | MOR2815SV/883 | 5962-9955001HUA |
| AHF2815TF/CH | 5962-9462301HZA | MFL2815SY/883 | 5962-9316101HYA | MOR2815SV/883 | 5962-9955001HUC |
| AHF2815TF/CH | 5962-9462301HZC | MFL2815SY/883 | 5962-9316101HYC | MOR2815SW/883 | 5962-9955001HTA |
| AHV2815DF/CH | 5962-9177401HZA | MFL2815SZ/883 | 5962-9316101HZA | MOR2815SW/883 | 5962-9955001HTC |
| AHV2815SF/CH | 5962-9211301HZA | MFL2815SZ/883 | 5962-9316101HZC | MOR2815SY/883 | 5962-9955001HYA |
| AHV2815TF/CH | 5962-9211601HZA | MGA2815DY/883 | 5962-9309001HYA | MOR2815SY/883 | 5962-9955001HYC |
| ASA2815D/CH | 5962-9464901HXA | MGA2815DY/883 | 5962-9309001HYC | MOR2815SZ/883 | 5962-9955001HZA |
| ASA2815S/CH | 5962-9463001HXA | MGA2815DZ883 | 5962-9309001HZA | MOR2815SZ/883 | 5962-9955001HZC |
| ATO2815T/CH | 5962-9095401HXA | MGA2815SY/883 | 5962-9309401HYA | MSA2815D/883 | 5962-9309001HXA |
| ATO2815TF/CH | 5962-9095401HZA | MGA2815SY/883 | 5962-9309401HYC | MSA2815D/883 | 5962-9309001HXC |
| ATR2815D/CH | 5962-9462801HXA | MGA2815SZ/883 | 5962-9309401HZA | MSA2815S/883 | 5962-9309401HXA |
| ATR2815DF/CH | 5962-9462801HZA | MGH2815DY/883 | 5962-9570401HYA | MSA2815S/883 | 5962-9309401HXC |
| ATR2815S/CH | 5962-9462601HXA | MGH2815DY/883 | 5962-9570401HYC | MTR2815D/883 | 5962-9307201HXA |
| ATR2815SF/CH | 5962-9462601HZA | MGH2815DZ/883 | 5962-9570401HZA | MTR2815D/883 | 5962-9307201HXC |
| ATR2815T/CH | 5962-9215901HXA | MGH2815SY/883 | 5962-9569801HYA | MTR2815DF/883 | 5962-9307201HZA |
| ATR2815TF/CH | 5962-9215901HZA | MGH2815SY/883 | 5962-9569801HYC | MTR2815DF/883 | 5962-9307201HZC |
| ATW2815D/CH | 5962-9161301HZA | MGH2815SZ/883 | 5962-9569801HZA | MTR2815S/883 | 5962-9307001HXA |
| ATW2815D/CH-MSTR | 5962-9161303HZA | MHD2815D/883 | 5962-9466101HXA | MTR2815S/883 | 5962-9307001HXC |
| ATW2815D/CH-SLV | 5962-9161302HZA | MHD2815D/883 | 5962-9466101HXC | MTR2815SF/883 | 5962-9307001HZA |
| ATW2815S/CH | 5962-9159904HZA | MHD2815DF/883 | 5962-9466101HZA | MTR2815SF/883 | 5962-9307001HZC |
| ATW2815S/CH-MSTR | 5962-9159906HZA | MHD2815DF/883 | 5962-9466101HZC | SLH2815D/HL | 5962L9852901HXA |
| ATW2815S/CH-SLV | 5962-9159905HZA | MHD2815S/883 | 5962-9465701HXA | SLH2815D/HL | 5962L9852901HXC |
| DVHF2815D/H | 5962-0324403HXC | MHD2815S/883 | 5962-9465701HXC | SLH2815D/HO | 5962-9852901HXA |
| DVHF2815D/H-E | 5962-0324403HXA | MHD2815SF/883 | 5962-9465701HZA | SLH2815D/HO | 5962-9852901HXC |
| DVHF2815DF/H | 5962-0324403HYC | MHD2815SF/883 | 5962-9465701HZC | SLH2815D/HR | 5962R9852901HXA |
| DVHF2815DF/H-E | 5962-0324403HYA | MHF+2815D/883 | 5962-9161401HXA | SLH2815D/HR | 5962R9852901HXC |
| DVHF2815S/H | 5962-0324305HXC | MHF+2815D/883 | 5962-9161401HXC | SLH2815D/KL | 5962L9852901KXA |
| DVHF2815S/H-E | 5962-0324305HXA | MHF+2815DF/883 | 5962-9161401HZA | SLH2815D/KL | 5962L9852901KXC |
| DVHF2815SF/H | 5962-0324305HYC | MHF+2815DF/883 | 5962-9161401HZC | SLH2815D/KR | 5962R9852901KXA |
| DVHF2815SF/H-E | 5962-0324305HYA | MHF+2815S/883 | 5962-9160101HXA | SLH2815D/KR | 5962R9852901KXC |
| DVSA2815D/H | 5962-0324203HXC | MHF+2815S/883 | 5962-9160101HXC | SLH2815S/HL | 5962L0052801HXA |
| DVSA2815D/H-E | 5962-0324203HXA | MHF+2815SF/883 | 5962-9160101HZA | SLH2815S/HL | 5962L0052801HXC |
| DVSA2815S/H | 5962-0324105HXC | MHF+2815SF/883 | 5962-9160101HZC | SLH2815S/HO | 5962-0052801HXA |
| DVSA2815S/H-E | 5962-0324105HXA | MHV2815D/883 | 5962-9852701HXA | SLH2815S/HO | 5962-0052801HXC |
| MCH2815D/883 | 5962-9570401HXA | MHV2815D/883 | 5962-9852701HXC | SLH2815S/HR | 5962R0052801HXA |
| MCH2815D/883 | 5962-9570401HXC | MHV2815DF/883 | 5962-9852701HZA | SLH2815S/HR | 5962R0052801HXC |
| MCH2815S/883 | 5962-9569801HXA | MHV2815DF/883 | 5962-9852701HZC | SLH2815S/KL | 5962L0052801KXA |
| MCH2815S/883 | 5962-9569801HXC | MHV2815S/883 | 5962-9852401HXA | SLH2815S/KL | 5962L0052801KXC |
| MFL2815D/883 | 5962-9319301HXA | MHV2815S/883 | 5962-9852401HXC | SLH2815S/KR | 5962R0052801KXA |
| MFL2815D/883 | 5962-9319301HXC | MHV2815SF/883 | 5962-9852401HZA | SLH2815S/KR | 5962R0052801KXC |
| MFL2815DV/883 | 5962-9319301HUA | MHV2815SF/883 | 5962-9852401HZC | SMFL2815D/HO | 5962-9319302HXA |
| MFL2815DV/883 | 5962-9319301HUC | MOR2815D/883 | 5962-9956301HXA | SMFL2815D/HO | 5962-9319302HXC |
| MFL2815DW/883 | 5962-9319301HTA | MOR2815D/883 | 5962-9956301HXC | SMFL2815D/HR | 5962R9319302HXA |
| MFL2815DW/883 | 5962-9319301HTC | MOR2815DV/883 | 5962-9956301HUA | SMFL2815D/HR | 5962R9319302HXC |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART II, Listed By Generic PIN

| Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN |
|---|---|---|---|---|---|
| SMFL2815D/KR | 5962R9319302KXA | SMHF2815S/KL | 5962L9160102KXC | WMF2M8-150DAQ5 | 5962-9760901HXA |
| SMFL2815D/KR | 5962R9319302KXC | SMHF2815S/KR | 5962R9160102KXA | WMF2M8-150DAQ5 | 5962-9760901HXC |
| SMFL2815DV/HO | 5962-9319302HUA | SMHF2815S/KR | 5962R9160102KXC | WMF2M8-150DAQE5 | 5962-9760904HXA |
| SMFL2815DV/HO | 5962-9319302HUC | SMHF2815SF/HL | 5962L9160102HZA | WMF2M8-150DAQE5 | 5962-9760904HXC |
| SMFL2815DV/HR | 5962R9319302HUA | SMHF2815SF/HL | 5962L9160102HZC | MHD2818S/883 | 5962-9465801HXA |
| SMFL2815DV/HR | 5962R9319302HUC | SMHF2815SF/HO | 5962-9160102HZA | MHD2818S/883 | 5962-9465801HXC |
| SMFL2815DV/KR | 5962R9319302KUA | SMHF2815SF/HO | 5962-9160102HZC | MHD2818SF/883 | 5962-9465801HZA |
| SMFL2815DV/KR | 5962R9319302KUC | SMHF2815SF/HR | 5962R9160102HZA | MHD2818SF/883 | 5962-9465801HZC |
| SMFL2815DW/HO | 5962-9319302HTA | SMHF2815SF/HR | 5962R9160102HZC | MTR2818S/883 | 5962-9320201HXA |
| SMFL2815DW/HO | 5962-9319302HTC | SMHF2815SF/KL | 5962L9160102KZA | MTR2818S/883 | 5962-9320201HXC |
| SMFL2815DW/HR | 5962R9319302HTA | SMHF2815SF/KL | 5962L9160102KZC | MTR2818SF/883 | 5962-9320201HZA |
| SMFL2815DW/HR | 5962R9319302HTC | SMHF2815SF/KR | 5962R9160102KZA | MTR2818SF/883 | 5962-9320201HZC |
| SMFL2815DW/KR | 5962R9319302KTA | SMHF2815SF/KR | 5962R9160102KZC | SG2821J/883B | 5962-8968401VA |
| SMFL2815DW/KR | 5962R9319302KTC | SMSA2815D/HL | 5962L9309002HXA | SG2821L/883B | 5962-89684012A |
| SMFL2815DY/HO | 5962-9319302HYA | SMSA2815D/HL | 5962L9309002HXC | SG2823J/883B | 5962-8968501VA |
| SMFL2815DY/HO | 5962-9319302HYC | SMSA2815D/HO | 5962-9309002HXA | SG2823L/883B | 5962-89685012A |
| SMFL2815DY/HR | 5962R9319302HYA | SMSA2815D/HO | 5962-9309002HXC | SG2824J/883B | 5962-8968601VA |
| SMFL2815DY/HR | 5962R9319302HYC | SMSA2815D/HR | 5962R9309002HXA | SG2824L/883B | 5962-89686012A |
| SMFL2815DY/KR | 5962R9319302KYA | SMSA2815D/HR | 5962R9309002HXC | LM2M8CRH-Q25X | 5962H9954105QXC |
| SMFL2815DY/KR | 5962R9319302KYC | SMSA2815D/KL | 5962L9309002KXA | LM2M8CRH-V25X | 5962H9954105VXC |
| SMFL2815DZ/HO | 5962-9319302HZA | SMSA2815D/KL | 5962L9309002KXC | LM2M8TRH-Q25X | 5962H9954106QXC |
| SMFL2815DZ/HO | 5962-9319302HZC | SMSA2815D/KR | 5962R9309002KXA | LM2M8TRH-V25X | 5962H9954106VXC |
| SMFL2815DZ/HR | 5962R9319302HZA | SMSA2815D/KR | 5962R9309002KXC | AT28HC256-12DM/883 | 5962-8863401XA |
| SMFL2815DZ/HR | 5962R9319302HZC | SMSA2815S/HL | 5962L9309402HXA | AT28HC256-12FM/883 | 5962-8863401ZA |
| SMFL2815DZ/KR | 5962R9319302KZA | SMSA2815S/HL | 5962L9309402HXC | AT28HC256-12LM/883 | 5962-8863401YA |
| SMFL2815DZ/KR | 5962R9319302KZC | SMSA2815S/HO | 5962-9309402HXA | AT28HC256-12UM/883 | 5962-8863401UA |
| SMHF2815D/HL | 5962L9161402HXA | SMSA2815S/HO | 5962-9309402HXC | AT28HC256F-12DM/88 | 5962-8863402XA |
| SMHF2815D/HL | 5962L9161402HXC | SMSA2815S/HR | 5962R9309402HXA | AT28HC256F-12FM/8 | 5962-8863402ZA |
| SMHF2815D/HO | 5962-9161402HXA | SMSA2815S/HR | 5962R9309402HXC | AT28HC256F-12LM/88 | 5962-8863402YA |
| SMHF2815D/HO | 5962-9161402HXC | SMSA2815S/KL | 5962L9309402KXA | AT28HC256F-12UM/88 | 5962-8863402UA |
| SMHF2815D/HR | 5962R9161402HXA | SMSA2815S/KL | 5962L9309402KXC | X28HC256DMB-12 | 5962-8863401XA |
| SMHF2815D/HR | 5962R9161402HXC | SMSA2815S/KR | 5962R9309402KXA | X28HC256FMB-12 | 5962-8863401ZC |
| SMHF2815D/KL | 5962L9161402KXA | SMSA2815S/KR | 5962R9309402KXC | X28HC256KMB-12 | 5962-8863401UC |
| SMHF2815D/KL | 5962L9161402KXC | SMTR2815S/HL | 5962L9307002HXA | AT28C256-15DM/883 | 5962-8852506XA |
| SMHF2815D/KR | 5962R9161402KXA | SMTR2815S/HL | 5962L9307002HXC | AT28C256-15DM/883 | 5962-8852514XA |
| SMHF2815D/KR | 5962R9161402KXC | SMTR2815S/HO | 5962-9307002HXA | AT28C256-15FM/883 | 5962-8852506ZA |
| SMHF2815DF/HL | 5962L9161402HZA | SMTR2815S/HO | 5962-9307002HXC | AT28C256-15FM/883 | 5962-8852514ZA |
| SMHF2815DF/HL | 5962L9161402HZC | SMTR2815S/HR | 5962R9307002HXA | AT28C256-15LM/883 | 5962-8852506YA |
| SMHF2815DF/HO | 5962-9161402HZA | SMTR2815S/HR | 5962R9307002HXC | AT28C256-15LM/883 | 5962-8852514YA |
| SMHF2815DF/HO | 5962-9161402HZC | SMTR2815S/KL | 5962L9307002KXA | AT28C256-15UM/883 | 5962-8852506UA |
| SMHF2815DF/HR | 5962R9161402HZA | SMTR2815S/KL | 5962L9307002KXC | AT28C256-15UM/883 | 5962-8852514UA |
| SMHF2815DF/HR | 5962R9161402HZC | SMTR2815S/KR | 5962R9307002KXA | AT28C256E-15DM/883 | 5962-8852516XA |
| SMHF2815DF/KL | 5962L9161402KZA | SMTR2815S/KR | 5962R9307002KXC | AT28C256E-15FM/883 | 5962-8852508ZA |
| SMHF2815DF/KL | 5962L9161402KZC | SMTR2815SF/HL | 5962L9307002HZA | AT28C256E-15FM/883 | 5962-8852516ZA |
| SMHF2815DF/KR | 5962R9161402KZA | SMTR2815SF/HL | 5962L9307002HZC | AT28C256E-15LM/883 | 5962-8852508YA |
| SMHF2815DF/KR | 5962R9161402KZC | SMTR2815SF/HO | 5962-9307002HZA | AT28C256E-15LM/883 | 5962-8852516YA |
| SMHF2815S/HL | 5962L9160102HXA | SMTR2815SF/HO | 5962-9307002HZC | AT28C256E-15UM/883 | 5962-8852508UA |
| SMHF2815S/HL | 5962L9160102HXC | SMTR2815SF/HR | 5962R9307002HZA | AT28C256E-15UM/883 | 5962-8852516UA |
| SMHF2815S/HO | 5962-9160102HXA | SMTR2815SF/HR | 5962R9307002HZC | AT28C256F-15DM/883 | 5962-8852507XA |
| SMHF2815S/HO | 5962-9160102HXC | SMTR2815SF/KL | 5962L9307002KZA | AT28C256F-15DM/883 | 5962-8852515XA |
| SMHF2815S/HR | 5962R9160102HXA | SMTR2815SF/KL | 5962L9307002KZC | AT28C256F-15FM/883 | 5962-8852507ZA |
| SMHF2815S/HR | 5962R9160102HXC | SMTR2815SF/KR | 5962R9307002KZA | AT28C256F-15FM/883 | 5962-8852515ZA |
| SMHF2815S/KL | 5962L9160102KXA | SMTR2815SF/KR | 5962R9307002KZC | AT28C256F-15LM/883 | 5962-8852507YA |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

| Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN |
|---|---|---|---|---|---|
| AT28C256F-15LM/883 | 5962-8852515YA | UT28F256T-40PCAH | 5962H9689104VYA | AFL2828SX/CH | 5962-9689901HXA |
| AT28C256F-15UM/883 | 5962-8852507UA | UT28F256T-40PCCH | 5962H9689104QYC | AFL2828SX/CH | 5962-9689901HXC |
| AT28C256F-15UM/883 | 5962-8852515UA | UT28F256T-40PCCH | 5962H9689104VYC | AFL2828SY/CH | 5962-9689901HYA |
| AT28C256-20DM/883 | 5962-8852504XA | UT28F256T-40UCAH | 5962H9689104QXA | AFL2828SY/CH | 5962-9689901HYC |
| AT28C256-20DM/883 | 5962-8852512XA | UT28F256T-40UCAH | 5962H9689104VXA | AFL2828SZ/CH | 5962-9689901HZA |
| AT28C256-20FM/883 | 5962-8852504ZA | UT28F256T-40UCCH | 5962H9689104QXC | AFL2828SZ/CH | 5962-9689901HZC |
| AT28C256-20FM/883 | 5962-8852512ZA | UT28F256T-40UCCH | 5962H9689104VXC | MHF+2828S/883 | 5962-9689801HXA |
| AT28C256-20LM/883 | 5962-8852504YA | UT28F256QLT-45UCAF | 5962F9689107QXA | MHF+2828S/883 | 5962-9689801HXC |
| AT28C256-20LM/883 | 5962-8852512YA | UT28F256QLT-45UCAF | 5962F9689107VXA | MHF+2828SF/883 | 5962-9689801HZA |
| AT28C256-20UM/883 | 5962-8852504UA | UT28F256QLT-45UCAH | 5962H9689105QXA | MHF+2828SF/883 | 5962-9689801HZC |
| AT28C256-20UM/883 | 5962-8852512UA | UT28F256QLT-45UCAH | 5962H9689105VXA | HCS283 (GEN) | 5962R9581101V9A |
| AT28C256-25DM/883 | 5962-8852503XA | UT28F256QLT-45UCCF | 5962F9689107QXC | HCS283 (GEN) | 5962R9581101VEC |
| AT28C256-25DM/883 | 5962-8852511XA | UT28F256QLT-45UCCF | 5962F9689107VXC | HCS283 (GEN) | 5962R9581101VXC |
| AT28C256-25FM/883 | 5962-8852503ZA | UT28F256QLT-45UCCH | 5962H9689105QXC | HCTS283 (GEN) | 5962R9577401V9A |
| AT28C256-25FM/883 | 5962-8852511ZA | UT28F256QLT-45UCCH | 5962H9689105VXC | HCTS283DMSR | 5962R9577401VEC |
| AT28C256-25LM/883 | 5962-8852503YA | UT28F256T-45PCAH | 5962H9689103QYA | HCTS283KMSR | 5962R9577401VXC |
| AT28C256-25LM/883 | 5962-8852511YA | UT28F256T-45PCAH | 5962H9689103QYC | LM2M8CRH-Q30X | 5962H9954103QXC |
| AT28C256-25UM/883 | 5962-8852503UA | UT28F256T-45PCAH | 5962H9689103VYA | LM2M8CRH-V30X | 5962H9954103VXC |
| AT28C256-25UM/883 | 5962-8852511UA | UT28F256T-45PCCH | 5962H9689103VYC | LM2M8TRH-Q30X | 5962H9954104QXC |
| AT28C256E-15DM/883 | 5962-8852508XA | UT28F256T-45UCAH | 5962H9689103QXA | LM2M8TRH-V30X | 5962H9954104VXC |
| AT28C256E-25DM/883 | 5962-8852505XA | UT28F256T-45UCAH | 5962H9689103VXA | DVHF283R3S/H | 5962-0324301HXC |
| AT28C256E-25DM/883 | 5962-8852513XA | UT28F256T-45UCCH | 5962H9689103QXC | DVHF283R3S/H-E | 5962-0324301HXA |
| AT28C256E-25FM/883 | 5962-8852505ZA | UT28F256T-45UCCH | 5962H9689103VXC | DVHF283R3SF/H | 5962-0324301HYC |
| AT28C256E-25FM/883 | 5962-8852513ZA | UT28F256LVC-65PCA | 5962H0151701QYA | DVHF283R3SF/H-E | 5962-0324301HYA |
| AT28C256E-25LM/883 | 5962-8852505YA | UT28F256LVC-65PCA | 5962H0151701VYA | DVSA283R3S/H | 5962-0324101HXC |
| AT28C256E-25LM/883 | 5962-8852513YA | UT28F256LVC-65PCC | 5962H0151701QYC | DVSA283R3S/H-E | 5962-0324101HXA |
| AT28C256E-25UM/883 | 5962-8852505UA | UT28F256LVC-65PCC | 5962H0151701VYC | MHF+283R3S/883 | 5962-0251001HXA |
| AT28C256E-25UM/883 | 5962-8852513UA | UT28F256LVC-65UCA | 5962H0151701QXA | MHF+283R3S/883 | 5962-0251001HXC |
| AT28C256-30DM/883 | 5962-8852502XA | UT28F256LVC-65UCA | 5962H0151701VXA | MHF+283R3SF/883 | 5962-0251001HZA |
| AT28C256-30FM/883 | 5962-8852502ZA | UT28F256LVC-65UCC | 5962H0151701QXC | MHF+283R3SF/883 | 5962-0251001HZC |
| AT28C256-30FM/883 | 5962-8852510ZA | UT28F256LVC-65UCC | 5962H0151701VXC | MHV283R3S/883 | 5962-9852801HXA |
| AT28C256-30LM/883 | 5962-8852502YA | UT28F256LVQLC-65UC | 5962F0151703QXA | MHV283R3S/883 | 5962-9852801HXC |
| AT28C256-30LM/883 | 5962-8852510YA | UT28F256LVQLC-65UC | 5962F0151703VXA | MHV283R3SF/883 | 5962-9852801HZA |
| AT28C256-30UM/883 | 5962-8852502UA | UT28F256LVQLC-65UC | 5962H0151702QXA | MHV283R3SF/883 | 5962-9852801HZC |
| AT28C256-30UM/883 | 5962-8852510UA | UT28F256LVQLC-65UC | 5962H0151702VXA | MOR283R3D/883 | 5962-9956401HXA |
| AT28C256-300DM/883 | 5962-8852510XA | UT28F256LVQLC-65UC | 5962F0151703QXC | MOR283R3D/883 | 5962-9956401HXC |
| AT28C256-35DM/883 | 5962-8852501XA | UT28F256LVQLC-65UC | 5962F0151703VXC | MOR283R3DV/883 | 5962-9956401HUA |
| AT28C256-35DM/883 | 5962-8852509XA | UT28F256LVQLC-65UC | 5962H0151702QXC | MOR283R3DV/883 | 5962-9956401HUC |
| AT28C256-35FM/883 | 5962-8852501ZA | UT28F256LVQLC-65UC | 5962H0151702VXC | MOR283R3DW/883 | 5962-9956401HTA |
| AT28C256-35FM/883 | 5962-8852509ZA | AT28HC256-70DM/883 | 5962-8863405XA | MOR283R3DW/883 | 5962-9956401HTC |
| AT28C256-35LM/883 | 5962-8852501YA | AT28HC256-70FM/883 | 5962-8863405ZA | MOR283R3DY/883 | 5962-9956401HYA |
| AT28C256-35LM/883 | 5962-8852509YA | AT28HC256-70LM/883 | 5962-8863405YA | MOR283R3DY/883 | 5962-9956401HYC |
| AT28C256-35UM/883 | 5962-8852501UA | AT28HC256-70UM/883 | 5962-8863405UA | MOR283R3DZ/883 | 5962-9956401HZA |
| AT28C256-35UM/883 | 5962-8852509UA | AT28HC256-90DM/883 | 5962-8863403XA | MOR283R3DZ/883 | 5962-9956401HZC |
| UT28F256QLT-40UCAF | 5962F9689108QXA | AT28HC256-90FM/883 | 5962-8863403ZA | MOR283R3S/883 | 5962-9954401HXA |
| UT28F256QLT-40UCAF | 5962F9689108VXA | AT28HC256-90LM/883 | 5962-8863403YA | MOR283R3S/883 | 5962-9954401HXC |
| UT28F256QLT-40UCAH | 5962H9689106QXA | AT28HC256-90UM/883 | 5962-8863403UA | MOR283R3SV/883 | 5962-9954401HUA |
| UT28F256QLT-40UCAH | 5962H9689106VXA | AT28HC256F-90DM/88 | 5962-8863404XA | MOR283R3SV/883 | 5962-9954401HUC |
| UT28F256QLT-40UCCF | 5962F9689108QXC | AT28HC256F-90FM/88 | 5962-8863404ZA | MOR283R3SW/883 | 5962-9954401HTA |
| UT28F256QLT-40UCCF | 5962F9689108VXC | AT28HC256F-90LM/88 | 5962-8863404YA | MOR283R3SW/883 | 5962-9954401HTC |
| UT28F256QLT-40UCCH | 5962H9689106QXC | AT28HC256F-90UM/88 | 5962-8863404UA | MOR283R3SY/883 | 5962-9954401HYA |
| UT28F256QLT-40UCCH | 5962H9689106VXC | AFL2828SW/CH | 5962-9689901HUA | MOR283R3SY/883 | 5962-9954401HYC |
| UT28F256T-40PCAH | 5962H9689104QYA | AFL2828SW/CH | 5962-9689901HUC | MOR283R3SZ/883 | 5962-9954401HZA |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART II, Listed By Generic PIN

| Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN |
|---|---|---|---|---|---|
| MOR283R3SZ/883 | 5962-9954401HZC | MHV28512TF/883 | 5962-9673001HZA | MHV28515TF/883 | 5962-9673101HZC |
| MTR283R3S/883 | 5962-0150101HXA | MHV28512TF/883 | 5962-9673001HZC | MTR28515T/883 | 5962-9307401HXA |
| MTR283R3S/883 | 5962-0150101HXC | MTR28512T/883 | 5962-9307301HXA | MTR28515T/883 | 5962-9307401HXC |
| MTR283R3SF/883 | 5962-0150101HZA | MTR28512T/883 | 5962-9307301HXC | MTR28515TF/883 | 5962-9307401HZA |
| MTR283R3SF/883 | 5962-0150101HZC | MTR28512TF/883 | 5962-9307301HZA | MTR28515TF/883 | 5962-9307401HZC |
| SMHF283R3S/HL | 5962L0251002HXA | MTR28512TF/883 | 5962-9307301HZC | DVHF285R2S/H | 5962-0324303HXC |
| SMHF283R3S/HL | 5962L0251002HXC | 28C512-12 (GEN) | 5962-9086907MUC | DVHF285R2S/H-E | 5962-0324303HXA |
| SMHF283R3S/HO | 5962-0251002HXA | 28C512-12 (GEN) | 5962-9086907MXA | DVHF285R2SF/H | 5962-0324303HYC |
| SMHF283R3S/HO | 5962-0251002HXC | 28C512-12 (GEN) | 5962-9086907MYA | DVHF285R2SF/H-E | 5962-0324303HYA |
| SMHF283R3S/HR | 5962R0251002HXA | 28C512-12 (GEN) | 5962-9086907MZC | DVSA285R2S/H | 5962-0324103HXC |
| SMHF283R3S/HR | 5962R0251002HXC | 28C512-12 (GEN) | 5962-9086908MUC | DVSA285R2S/H-E | 5962-0324103HXA |
| SMHF283R3S/KL | 5962L0251002KXA | 28C512-12 (GEN) | 5962-9086908MXA | MSA285R2S/883 | 5962-0251301HXA |
| SMHF283R3S/KL | 5962L0251002KXC | 28C512-12 (GEN) | 5962-9086908MYA | MHF+285R2S/883 | 5962-0325301HXA |
| SMHF283R3S/KR | 5962R0251002KXA | 28C512-12 (GEN) | 5962-9086908MZC | MHF+285R2S/883 | 5962-0325301HXC |
| SMHF283R3S/KR | 5962R0251002KXC | 28C512-15 (GEN) | 5962-9086905MUC | MHF+285R2SF/883 | 5962-0325301HZA |
| SMHF283R3SF/HL | 5962L0251002HZA | 28C512-15 (GEN) | 5962-9086905MXA | MHF+285R2SF/883 | 5962-0325301HZC |
| SMHF283R3SF/HL | 5962L0251002HZC | 28C512-15 (GEN) | 5962-9086905MYA | MOR286R3D/883 | 5962-9956501HXA |
| SMHF283R3SF/HO | 5962-0251002HZA | 28C512-15 (GEN) | 5962-9086905MZC | MOR286R3D/883 | 5962-9956501HXC |
| SMHF283R3SF/HO | 5962-0251002HZC | 28C512-15 (GEN) | 5962-9086906MUC | MOR286R3DV/883 | 5962-9956501HUA |
| SMHF283R3SF/HR | 5962R0251002HZA | 28C512-15 (GEN) | 5962-9086906MXA | MOR286R3DV/883 | 5962-9956501HUC |
| SMHF283R3SF/HR | 5962R0251002HZC | 28C512-15 (GEN) | 5962-9086906MYA | MOR286R3DW/883 | 5962-9956501HTA |
| SMHF283R3SF/KL | 5962L0251002KZA | 28C512-15 (GEN) | 5962-9086906MZC | MOR286R3DW/883 | 5962-9956501HTC |
| SMHF283R3SF/KL | 5962L0251002KZC | 28C512-20 (GEN) | 5962-9086903MYA | MOR286R3DY/883 | 5962-9956501HYA |
| SMHF283R3SF/KR | 5962R0251002KZA | 28C512-20 (GEN) | 5962-9086903MZC | MOR286R3DY/883 | 5962-9956501HYC |
| SMHF283R3SF/KR | 5962R0251002KZC | 28C512-20 (GEN) | 5962-9086904MUC | MOR286R3DZ/883 | 5962-9956501HZA |
| SMTR283R3S/HO | 5962-0150102HXA | 28C512-20 (GEN) | 5962-9086904MXA | MOR286R3DZ/883 | 5962-9956501HZC |
| SMTR283R3S/HO | 5962-0150102HXC | 28C512-20 (GEN) | 5962-9086904MYA | MOR286R3S/883 | 5962-9954501HXA |
| SMTR283R3S/HR | 5962R0150102HXA | 28C512-20 (GEN) | 5962-9086904MZC | MOR286R3S/883 | 5962-9954501HXC |
| SMTR283R3S/HR | 5962R0150102HXC | X28C512DMB-20 | 5962-9086903MXA | MOR286R3SV/883 | 5962-9954501HUA |
| SMTR283R3S/KR | 5962R0150102KXA | X28C512KMB-20 | 5962-9086903MUC | MOR286R3SV/883 | 5962-9954501HUC |
| SMTR283R3S/KR | 5962R0150102KXC | 28C512-25 (GEN) | 5962-9086901MUC | MOR286R3SW/883 | 5962-9954501HTA |
| SMTR283R3SF/HO | 5962-0150102HZA | 28C512-25 (GEN) | 5962-9086901MXA | MOR286R3SW/883 | 5962-9954501HTC |
| SMTR283R3SF/HO | 5962-0150102HZC | 28C512-25 (GEN) | 5962-9086901MYA | MOR286R3SY/883 | 5962-9954501HYA |
| SMTR283R3SF/HR | 5962R0150102HZA | 28C512-25 (GEN) | 5962-9086901MZC | MOR286R3SY/883 | 5962-9954501HYC |
| SMTR283R3SF/HR | 5962R0150102HZC | 28C512-25 (GEN) | 5962-9086902MUC | MOR286R3SZ/883 | 5962-9954501HZA |
| SMTR283R3SF/KR | 5962R0150102KZA | 28C512-25 (GEN) | 5962-9086902MXA | MOR286R3SZ/883 | 5962-9954501HZC |
| SMTR283R3SF/KR | 5962R0150102KZC | 28C512-25 (GEN) | 5962-9086902MYA | 2864 (GEN) | 5962-8683010XA |
| HA7-2840 (GEN) | 5962-9467901MPA | 28C512-25 (GEN) | 5962-9086902MZC | 2864 (GEN) | 5962-8683010YA |
| LM2M8CRH-Q40X | 5962H9954101QXC | 28C513-12 (GEN) | 5962-9086916MYA | 2864 (GEN) | 5962-8683010ZA |
| LM2M8CRH-V40X | 5962H9954101VXC | X28C513EMB-12 | 5962-9086915MYA | 286412 (GEN) | 5962-8751410UA |
| LM2M8TRH-Q40X | 5962H9954102QXC | 28C513-15 (GEN) | 5962-9086913MYA | 286412 (GEN) | 5962-8751410XA |
| LM2M8TRH-V40X | 5962H9954102VXC | 28C513-15 (GEN) | 5962-9086914MYA | 286412 (GEN) | 5962-8751410YA |
| HA1-2841/883 | 5962-8778503CA | 28C513-20 (GEN) | 5962-9086911MYA | 286415 (GEN) | 5962-8751417UA |
| HA7-2841 (GEN) | 5962-8778503PA | 28C513-20 (GEN) | 5962-9086912MYA | 286415 (GEN) | 5962-8751417XA |
| HA7-2842/883 | 5962-9469401MPA | 28C513-25 (GEN) | 5962-9086909MYA | 286415 (GEN) | 5962-8751417YA |
| TL-SCSI285 (GEN) | 5962-9473201M2A | 28C513-25 (GEN) | 5962-9086910MYA | 286415 (GEN) | 5962-8751422UA |
| TL-SCSI285 (GEN) | 5962-9473201MCA | MHF+28515T/883 | 5962-9560201HXA | 286415 (GEN) | 5962-8751422XA |
| MHF+28512T/883 | 5962-9560101HXA | MHF+28515T/883 | 5962-9560201HXC | 286415 (GEN) | 5962-8751422YA |
| MHF+28512T/883 | 5962-9560101HXC | MHF+28515TF/883 | 5962-9560201HZA | 286420 (GEN) | 5962-8751409UA |
| MHF+28512TF/883 | 5962-9560101HZA | MHF+28515TF/883 | 5962-9560201HZC | 286420 (GEN) | 5962-8751409XA |
| MHF+28512TF/883 | 5962-9560101HZC | MHV28515T/883 | 5962-9673101HXA | 286420 (GEN) | 5962-8751409YA |
| MHV28512T/883 | 5962-9673001HXA | MHV28515T/883 | 5962-9673101HXC | 286420 (GEN) | 5962-8751416UA |
| MHV28512T/883 | 5962-9673001HXC | MHV28515TF/883 | 5962-9673101HZA | 286420 (GEN) | 5962-8751416XA |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

| Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN |
|---|---|---|---|---|---|
| 286420 (GEN) | 5962-8751416YA | 2864-300 (GEN) | 5962-8683009XA | 2865200 (GEN) | 5962-8751426YA |
| 286420 (GEN) | 5962-8751421UA | 2864-300 (GEN) | 5962-8683009YA | 2865200 (GEN) | 5962-8751426ZA |
| 286420 (GEN) | 5962-8751421XA | 2864-300 (GEN) | 5962-8683009ZA | 2865250 (GEN) | 5962-8751425XA |
| 286420 (GEN) | 5962-8751421YA | 286435 (GEN) | 5962-8751406UA | 2865250 (GEN) | 5962-8751425YA |
| 286420 (GEN) | 5962-8751428XA | 286435 (GEN) | 5962-8751406XA | 2865250 (GEN) | 5962-8751425ZA |
| 286420 (GEN) | 5962-8751428YA | 286435 (GEN) | 5962-8751406YA | 2865300 (GEN) | 5962-8751424XA |
| 28C64-20 (GEN) | 5962-8751404XA | 286435 (GEN) | 5962-8751413UA | 2865300 (GEN) | 5962-8751424YA |
| 28C64-20 (GEN) | 5962-8751404YA | 286435 (GEN) | 5962-8751413XA | 2865300 (GEN) | 5962-8751424ZA |
| 28C64-20 (GEN) | 5962-8751404ZC | 286435 (GEN) | 5962-8751413YA | 2865350 (GEN) | 5962-8751423XA |
| 286425 (GEN) | 5962-8751408UA | 286435 (GEN) | 5962-8751413ZA | 2865350 (GEN) | 5962-8751423YA |
| 286425 (GEN) | 5962-8751408XA | 286435 (GEN) | 5962-8751418UA | 2865350 (GEN) | 5962-8751423ZA |
| 286425 (GEN) | 5962-8751408YA | 286435 (GEN) | 5962-8751418XA | WMF2M8-90DAQ5 | 5962-9760903HXA |
| 286425 (GEN) | 5962-8751415UA | 286435 (GEN) | 5962-8751418YA | WMF2M8-90DAQ5 | 5962-9760903HXC |
| 286425 (GEN) | 5962-8751415XA | 2864-35 (GEN) | 5962-8683007XA | WMF2M8-90DAQE5 | 5962-9760906HXA |
| 286425 (GEN) | 5962-8751415YA | 2864-35 (GEN) | 5962-8683007YA | WMF2M8-90DAQE5 | 5962-9760906HXC |
| 286425 (GEN) | 5962-8751415ZA | 2864-35 (GEN) | 5962-8683007ZA | MOR289R5D/883 | 5962-9956601HXA |
| 286425 (GEN) | 5962-8751420UA | 28C64-35 (GEN) | 5962-8751401XA | MOR289R5D/883 | 5962-9956601HXC |
| 286425 (GEN) | 5962-8751420XA | 28C64-35 (GEN) | 5962-8751401YA | MOR289R5DV/883 | 5962-9956601HUA |
| 286425 (GEN) | 5962-8751420YA | 28C64-35 (GEN) | 5962-8751401ZC | MOR289R5DV/883 | 5962-9956601HUC |
| 286425 (GEN) | 5962-8751420ZA | UT28F64T-35PCA | 5962H9687301QXA | MOR289R5DW/883 | 5962-9956601HTA |
| 2864-25 (GEN) | 5962-8683006XA | UT28F64T-35PCA | 5962H9687301VXA | MOR289R5DW/883 | 5962-9956601HTC |
| 2864-25 (GEN) | 5962-8683006YA | UT28F64T-35PCC | 5962H9687301QXC | MOR289R5DY/883 | 5962-9956601HYA |
| 2864-25 (GEN) | 5962-8683006ZA | UT28F64T-35PCC | 5962H9687301VXC | MOR289R5DY/883 | 5962-9956601HYC |
| 2864-25 (GEN) | 5962-8683008XA | UT28F64T-35UCA | 5962H9687301QYA | MOR289R5DZ/883 | 5962-9956601HZA |
| 2864-25 (GEN) | 5962-8683008YA | UT28F64T-35UCA | 5962H9687301VYA | MOR289R5DZ/883 | 5962-9956601HZC |
| 2864-25 (GEN) | 5962-8683008ZA | UT28F64T-35UCC | 5962H9687301QYC | MOR289R5S/883 | 5962-9954601HXA |
| 28C64-25 (GEN) | 5962-8751403XA | UT28F64T-35UCC | 5962H9687301VYC | MOR289R5S/883 | 5962-9954601HXC |
| 28C64-25 (GEN) | 5962-8751403YA | 2864-350 (GEN) | 5962-8683002XA | MOR289R5SV/883 | 5962-9954601HUA |
| 28C64-25 (GEN) | 5962-8751403ZC | 2864-350 (GEN) | 5962-8683002YA | MOR289R5SV/883 | 5962-9954601HUC |
| 28C64-25 (GEN) | 5962-8751405XA | 2864-350 (GEN) | 5962-8683002ZA | MOR289R5SW/883 | 5962-9954601HTA |
| 28C64-25 (GEN) | 5962-8751405YA | UT28F64T-45PCA | 5962H9687302QXA | MOR289R5SW/883 | 5962-9954601HTC |
| 28C64-25 (GEN) | 5962-8751405ZC | UT28F64T-45PCA | 5962H9687302VXA | MOR289R5SY/883 | 5962-9954601HYA |
| 2864-250 (GEN) | 5962-8683001XA | UT28F64T-45PCC | 5962H9687302QXC | MOR289R5SY/883 | 5962-9954601HYC |
| 2864-250 (GEN) | 5962-8683001YA | UT28F64T-45PCC | 5962H9687302VXC | MOR289R5SZ/883 | 5962-9954601HZA |
| 2864-250 (GEN) | 5962-8683001ZA | UT28F64T-45UCA | 5962H9687302QYA | MOR289R5SZ/883 | 5962-9954601HZC |
| 2864-250 (GEN) | 5962-8683005XA | UT28F64T-45UCA | 5962H9687302VYA | OP290A (GEN) | 5962-89783012A |
| 2864-250 (GEN) | 5962-8683005YA | UT28F64T-45UCC | 5962H9687302QYC | OP290A (GEN) | 5962-8978301PA |
| 2864-250 (GEN) | 5962-8683005ZA | UT28F64T-45UCC | 5962H9687302VYC | 29000-16 (GEN) | 5962-9228402MZC |
| 286430 (GEN) | 5962-8751407UA | UT28F64LVC-55PCA | 5962H0151601QXA | 29000-20 (GEN) | 5962-9228401MZC |
| 286430 (GEN) | 5962-8751407XA | UT28F64LVC-55PCA | 5962H0151601VXA | 2901 (GEN) | 7700702QA |
| 286430 (GEN) | 5962-8751407YA | UT28F64LVC-55PCC | 5962H0151601QXC | 2901A (GEN) | 7700701QA |
| 286430 (GEN) | 5962-8751414UA | UT28F64LVC-55PCC | 5962H0151601VXC | 2901A (GEN) | 7700701ZA |
| 286430 (GEN) | 5962-8751414XA | UT28F64LVC-55UCA | 5962H0151601QYA | 2901C (GEN) | 8405701QA |
| 286430 (GEN) | 5962-8751414YA | UT28F64LVC-55UCA | 5962H0151601VYA | 29C010 (GEN) | 5962-9168203MXA |
| 286430 (GEN) | 5962-8751419UA | UT28F64LVC-55UCC | 5962H0151601QYC | 29C010 (GEN) | 5962-9168203MYA |
| 286430 (GEN) | 5962-8751419XA | UT28F64LVC-55UCC | 5962H0151601VYC | AS29F010CW-120/Q | 5962-9669002HYA |
| 286430 (GEN) | 5962-8751419YA | 286470 (GEN) | 5962-8751412UA | AS29F010CW-120/Q | 5962-9669002HYC |
| 28C64-30 (GEN) | 5962-8751402XA | 286470 (GEN) | 5962-8751412XA | AS29F010DCG-120/Q | 5962-9669002HUA |
| 28C64-30 (GEN) | 5962-8751402YA | 286470 (GEN) | 5962-8751412YA | AS29F010DCG-120/Q | 5962-9669002HUC |
| 28C64-30 (GEN) | 5962-8751402ZC | 286490 (GEN) | 5962-8751411UA | AS29F010F-120/Q | 5962-9669002HTA |
| 2864-300 (GEN) | 5962-8683003XA | 286490 (GEN) | 5962-8751411XA | AS29F010F-120/Q | 5962-9669002HTC |
| 2864-300 (GEN) | 5962-8683003YA | 286490 (GEN) | 5962-8751411YA | 29C010 (GEN) | 5962-9168202MXA |
| 2864-300 (GEN) | 5962-8683003ZA | 2865200 (GEN) | 5962-8751426XA | 29C010 (GEN) | 5962-9168202MYA |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART II, Listed By Generic PIN

| Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN |
|---|---|---|---|---|---|
| AS29F010CW-150/Q | 5962-9669001HYA | AS29F040DCG-70/Q | 5962-9669204HTC | 2936 (GEN) | 5962-9233501MXA |
| AS29F010CW-150/Q | 5962-9669001HYC | AS29F040F-70/Q | 5962-9669204HUA | 2940/B3A | 86030013A |
| AS29F010DCG-150/Q | 5962-9669001HUA | AS29F040F-70/Q | 5962-9669204HUC | 2940/BXA | 8603001XA |
| AS29F010DCG-150/Q | 5962-9669001HUC | AS29F040CW-90/Q | 5962-9669203HXA | 2940/BYA | 8603001YA |
| AS29F010F-150/Q | 5962-9669001HTA | AS29F040CW-90/Q | 5962-9669203HXC | GEM14101QXA | 8603001XA |
| AS29F010F-150/Q | 5962-9669001HTC | AS29F040DCG-90/Q | 5962-9669203HTA | GEM14101QXC | 8603001XC |
| 29C010 (GEN) | 5962-9168201MXA | AS29F040DCG-90/Q | 5962-9669203HTC | GEM14101QYA | 8603001YA |
| 29C010 (GEN) | 5962-9168201MYA | AS29F040F-90/Q | 5962-9669203HUA | GEM14101QYC | 8603001YC |
| AS29F010CW-60/Q | 5962-9669005HYA | AS29F040F-90/Q | 5962-9669203HUC | LM2940-12 (GEN) | 5962-9088401MYA |
| AS29F010CW-60/Q | 5962-9669005HYC | 2907/B2A | 5962-87707012A | LM2940J-12/883 | 5962-9088401QEA |
| AS29F010DCG-60/Q | 5962-9669005HUA | 2907/BRA | 5962-8770701RA | LM2940WG-12/883 | 5962-9088401QXA |
| AS29F010DCG-60/Q | 5962-9669005HUC | 2907/BSA | 5962-8770701SA | OM2940-12N5M/883B | 5962-9088401MNA |
| AS29F010F-60/Q | 5962-9669005HTA | 2909A (GEN) | 86027013A | OM2940-12SRM/883B | 5962-9088401MMA |
| AS29F010F-60/Q | 5962-9669005HTC | 2909A (GEN) | 8602701XA | OM2940-12STM | 5962-9088401MUA |
| AS29F010CW-70/Q | 5962-9669004HYA | 2909A (GEN) | 8602701YA | LM2940-15 (GEN) | 5962-9088501MYA |
| AS29F010CW-70/Q | 5962-9669004HYC | 2909A (GEN) | 8602701ZA | LM2940J-15/883 | 5962-9088501QEA |
| AS29F010DCG-70/Q | 5962-9669004HUA | 2910 (GEN) | 7801701QA | LM2940WG-15/883 | 5962-9088501QXA |
| AS29F010DCG-70/Q | 5962-9669004HUC | 2910 (GEN) | 7801701QA | OM2940-15N5M/883B | 5962-9088501MNA |
| AS29F010F-70/Q | 5962-9669004HTA | 2910 (GEN) | 7801701ZA | OM2940-15SRM/883B | 5962-9088501MMA |
| AS29F010F-70/Q | 5962-9669004HTC | 2910A/BQA | 7801702QA | OM2940-15STM | 5962-9088501MUA |
| AS29F010CW-90/Q | 5962-9669003HYA | 2910A/BZA | 7801702ZA | OM2940-5N5M/883B | 5962-8958701NA |
| AS29F010CW-90/Q | 5962-9669003HYC | 2910A/BZC | 7801702ZC | OM2940-5SRM/883B | 5962-8958701MA |
| AS29F010DCG-90/Q | 5962-9669003HUA | 29C10A (GEN) | 5962-8770801QA | OM2940-5STM | 5962-8958701UA |
| AS29F010DCG-90/Q | 5962-9669003HUC | 29C10A (GEN) | 5962-8770801UA | LM2940-5.0 (GEN) | 5962-8958701YA |
| AS29F010F-90/Q | 5962-9669003HTA | 2911A (GEN) | 8602801RA | LM2940J-5.0/883 | 5962-8958701EA |
| AS29F010F-90/Q | 5962-9669003HTC | 29116 (GEN) | 5962-8686301XA | LM2940WG5.0/883 | 5962-8958701XA |
| 2903A/BXA | 5962-8867701XA | 29C116 (GEN) | 5962-8861201XC | LM2940-8 (GEN) | 5962-9088301MYA |
| 2903A/BYA | 5962-8867701YA | 29C116 (GEN) | 5962-8861201YC | LM2940-8 (GEN) | 5962-9088301QEA |
| 2903A/BYC | 5962-8867701YC | 29C116 (GEN) | 5962-8861201ZA | LM2941 (GEN) | 5962-9166701QXA |
| 2903A/BZA | 5962-8867701ZA | 29C116-1 (GEN) | 5962-8861202XC | LM2941J/883 | 5962-9166701QEA |
| 2903A/BZC | 5962-8867701ZC | 29C116-1 (GEN) | 5962-8861202YC | LM2941J-QMLV | 5962-9166701VEA |
| 2904/BQA | 8601701QA | 29C116-1 (GEN) | 5962-8861202ZA | LM2941WG/883 | 5962-9166701QYA |
| 2904/BYA | 8601701YA | 29C116-2 (GEN) | 5962-8861203XC | LM2941WG-QMLV | 5962-9166701VYA |
| 2904/BYC | 8601701YC | 29C116-2 (GEN) | 5962-8861203YC | 2942 (GEN) | 5962-86801013A |
| AS29F040CW-120/Q | 5962-9669202HXA | 29C116-2 (GEN) | 5962-8861203ZA | 2942 (GEN) | 5962-8680101WA |
| AS29F040CW-120/Q | 5962-9669202HXC | 2914 (GEN) | 8602901QA | 2946/B2A | 5962-86723022A |
| AS29F040DCG-120/Q | 5962-9669202HTA | 2914 (GEN) | 8602901UA | 2946/BRA | 5962-8672302RA |
| AS29F040DCG-120/Q | 5962-9669202HTC | 2914 (GEN) | 8602901YA | 2947/B2A | 5962-86723012A |
| AS29F040F-120/Q | 5962-9669202HUA | 2917A/B2A | 5962-86714012A | 2947/BRA | 5962-8672301RA |
| AS29F040F-120/Q | 5962-9669202HUC | 2917A/BRA | 5962-8671401RA | LP295 (GEN) | 5962-3870501BGA |
| 29C040 (GEN) | 5962-9324402MXA | 2917A/BSA | 5962-8671401SA | LP2951 (GEN) | 5962-3870501SGA |
| 29C040 (GEN) | 5962-9324402MYA | 29LS18 (GEN) | 5962-86719012A | LP2951E | 5962-3870501S2A |
| AS29F040CW-150/Q | 5962-9669201HXA | 29LS18 (GEN) | 5962-8671901EA | LP2951E/883 | 5962-3870501M2A |
| AS29F040CW-150/Q | 5962-9669201HXC | 29LS18 (GEN) | 5962-8671901FA | LP2951H/883 | 5962-3870501MGA |
| AS29F040DCG-150/Q | 5962-9669201HTA | 2925 (GEN) | 5962-88598013A | LP2951J | 5962-3870501BPA |
| AS29F040DCG-150/Q | 5962-9669201HTC | 2925 (GEN) | 5962-8859801LA | LP2951J | 5962-3870501SPA |
| AS29F040F-150/Q | 5962-9669201HUA | 2925A (GEN) | 5962-88598023A | LP2951J/883 | 5962-3870501MPA |
| AS29F040F-150/Q | 5962-9669201HUC | 2925A (GEN) | 5962-8859802LA | LP2951WG/883 | 5962-3870501MXA |
| 29C040 (GEN) | 5962-9324401MXA | L293D (GEN) | 5962-9235001MXA | 29C516E (GEN) | 5962-01A1801QXC |
| 29C040 (GEN) | 5962-9324401MYA | 2930 (GEN) | 5962-87573013A | 29C516E (GEN) | 5962-01A1801VXC |
| AS29F040CW-70/Q | 5962-9669204HXA | 2930 (GEN) | 5962-8757301XA | MMFR-29C516EMQ | 5962-01A1801QYC |
| AS29F040CW-70/Q | 5962-9669204HXC | 2930 (GEN) | 5962-8757301YA | MMKR-29C516EMQ | 5962-01A1801QZC |
| AS29F040DCG-70/Q | 5962-9669204HTA | 2932 (GEN) | 8605001RA | SMFR-29C516ESV | 5962-01A1801VYC |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART II, Listed By Generic PIN

| Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN |
|---|---|---|---|---|---|
| SMKR-29C516ESV | 5962-01A1801VZC | 29FCT521B (GEN) | 5962-88736043A | 29705/XA | 8602501XA |
| 2952A (GEN) | 5962-8777201LA | 29FCT521B (GEN) | 5962-8873604KA | 29705/YA | 8602501YA |
| 29FCT52A (GEN) | 5962-9090101M3A | 29FCT521B (GEN) | 5962-8873604LA | 29705A (GEN) | 86025013A |
| 29FCT52A (GEN) | 5962-9090101MKA | 29C521-16 (GEN) | 5962-9176206M3A | 29771 (GEN) | 8200804KC |
| 29FCT52A (GEN) | 5962-9090101MLA | 29C521-16 (GEN) | 5962-9176206M3C | R29771 | 82008013A |
| 29FCT52AT (GEN) | 5962-9220401M3A | 29C521-16 (GEN) | 5962-9176206MKA | R29771 | 8200801JA |
| 29FCT52AT (GEN) | 5962-9220401MKA | 29C521-16 (GEN) | 5962-9176206MLA | R29771 | 8200801LA |
| 29FCT52AT (GEN) | 5962-9220401MLA | 29C521-24 (GEN) | 5962-9176205M3A | R29771 | 8200801XA |
| 29FCT52B (GEN) | 5962-9090102M3A | 29C521-24 (GEN) | 5962-9176205MKA | SL82HS32131 | 82008013A |
| 29FCT52B (GEN) | 5962-9090102MKA | 29C521-24 (GEN) | 5962-9176205MLA | R29791 | 8200901JA |
| 29FCT52B (GEN) | 5962-9090102MLA | 29C521-30 (GEN) | 5962-9176204M3A | R29791 | 8200901LA |
| 29FCT52BT (GEN) | 5962-9220402M3A | 29C521-30 (GEN) | 5962-9176204MKA | R29791 | 8200901LC |
| 29FCT52BT (GEN) | 5962-9220402MKA | 29C521-30 (GEN) | 5962-9176204MLA | R29791 | 8200901XA |
| 29FCT52BT (GEN) | 5962-9220402MLA | 29C525-20 (GEN) | 5962-9169602M3C | R29791 | 8200901XC |
| 29FCT52C (GEN) | 5962-9090103M3A | 29C525-20 (GEN) | 5962-9169602MUA | R29791 | 8200901ZA |
| 29FCT52C (GEN) | 5962-9090103MKA | 29C525-20 (GEN) | 5962-9169602MXC | CJSE298 | 5962-9313401HXC |
| 29FCT52C (GEN) | 5962-9090103MLA | 29C525-20 (GEN) | 5962-9169602MYA | 2981 (GEN) | 5962-8851901VA |
| 29FCT52CT (GEN) | 5962-9220403M3A | 29C525-25 (GEN) | 5962-9169601M3C | IS0-2981RH-Q | 5962R0052001V9A |
| 29FCT52CT (GEN) | 5962-9220403MKA | 29C525-25 (GEN) | 5962-9169601MUA | IS1-2981RH-8 | 5962R0052001QVC |
| 29FCT52CT (GEN) | 5962-9220403MLA | 29C525-25 (GEN) | 5962-9169601MXC | IS1-2981RH-Q | 5962R0052001VVC |
| 29FCT520A (GEN) | 5962-88736013A | 29C525-25 (GEN) | 5962-9169601MYA | IS1-2981RH-T | 5962R0052001TVC |
| 29FCT520A (GEN) | 5962-8873601KA | 2953A (GEN) | 5962-8777202LA | 29818A (GEN) | 5962-89549013A |
| 29FCT520A (GEN) | 5962-8873601LA | LP2953AMJ/883 | 5962-9233601MEA | 29818A (GEN) | 5962-8954901KA |
| 29FCT520AT (GEN) | 5962-9220501M3A | LP2953AMJ-QMLV | 5962-9233601VEA | 29818A (GEN) | 5962-8954901LA |
| 29FCT520AT (GEN) | 5962-9220501MLA | LP2953AMWG/883 | 5962-9233601QXA | CY29FCT818ATDMB | 5962-9682701QLA |
| 29FCT520AT (GEN) | 5962-9220502M3A | LP2953AMWG-QMLV | 5962-9233601VXA | CY29FCT818ATLMB | 5962-9682701Q3A |
| 29FCT520AT (GEN) | 5962-9220502MKA | LP2956AMJ/883B | 5962-9554701QEA | 29C818-30 (GEN) | 5962-90515013A |
| 29FCT520B (GEN) | 5962-88736033A | 2960 (GEN) | 5962-8760201UA | 29C818-30 (GEN) | 5962-9051501LA |
| 29FCT520B (GEN) | 5962-8873603KA | 2960 (GEN) | 5962-8760201XA | 29C818-30 (GEN) | 5962-9051501XA |
| 29FCT520B (GEN) | 5962-8873603LA | 2960 (GEN) | 5962-8760201YA | 29821A (GEN) | 5962-87755013A |
| 29FCT520BT (GEN) | 5962-9220503M3A | 2960 (GEN) | 5962-8760201ZA | 29821A (GEN) | 5962-8775501KA |
| 29FCT520BT (GEN) | 5962-9220503MLA | 29C60A (GEN) | 5962-8861303UA | 29821A (GEN) | 5962-8775501LA |
| 29FCT520BT (GEN) | 5962-9220504M3A | 29C60A (GEN) | 5962-8861303XA | 29C821A (GEN) | 5962-88516053A |
| 29FCT520BT (GEN) | 5962-9220504MKA | 29C60A (GEN) | 5962-8861303YA | 29C821A (GEN) | 5962-8851605KA |
| 29FCT520CT (GEN) | 5962-9220505M3A | 29C60A (GEN) | 5962-8861303ZA | 29C821A (GEN) | 5962-8851605LA |
| 29FCT520CT (GEN) | 5962-9220505MLA | R29633 | 7902401JA | 29823A (GEN) | 5962-87755023A |
| 29FCT520CT (GEN) | 5962-9220506M3A | R29633 | 79024023A | 29823A (GEN) | 5962-8775502KA |
| 29FCT520CT (GEN) | 5962-9220506MKA | R29633 | 7902402JA | 29823A (GEN) | 5962-8775502LA |
| 29FCT520CT (GEN) | 5962-9220506MLA | R29633 | 7902402KA | 29C823A (GEN) | 5962-88516063A |
| CY29FCT520ATDMB | 5962-9220502MLA | R29633 | 7902402LA | 29C823A (GEN) | 5962-8851606KA |
| CY29FCT520BTDMB | 5962-9220504MLA | R29633 | 7902402XA | 29C823A (GEN) | 5962-8851606LA |
| 29C520-16 (GEN) | 5962-9176203M3A | 2964B/BQA | 5962-8757401QA | 29825A (GEN) | 5962-87755033A |
| 29C520-16 (GEN) | 5962-9176203MKA | 2964B/BUA | 5962-8757401UA | 29825A (GEN) | 5962-8775503KA |
| 29C520-16 (GEN) | 5962-9176203MLA | 2965 (GEN) | 5962-86707012A | 29825A (GEN) | 5962-8775503LA |
| 29C520-24 (GEN) | 5962-9176202M3A | 2965 (GEN) | 5962-8670701RA | 29827A (GEN) | 5962-88605013A |
| 29C520-24 (GEN) | 5962-9176202MKA | 2966 (GEN) | 5962-86707022A | 29827A (GEN) | 5962-8860501KA |
| 29C520-24 (GEN) | 5962-9176202MLA | 2966 (GEN) | 5962-8670702RA | 29827A (GEN) | 5962-8860501LA |
| 29C520-30 (GEN) | 5962-9176201M3A | 29C660A (GEN) | 5962-8853303UA | 29C827 (GEN) | 5962-87667013A |
| 29C520-30 (GEN) | 5962-9176201MKA | 29C660B (GEN) | 5962-8853304UA | 29C827 (GEN) | 5962-8766701KA |
| 29C520-30 (GEN) | 5962-9176201MLA | 29C660C (GEN) | 5962-8853305UA | 29C827 (GEN) | 5962-8766701LA |
| 29FCT521A (GEN) | 5962-88736023A | 29771 (GEN) | 8200804LA | 29C827A (GEN) | 5962-87667053A |
| 29FCT521A (GEN) | 5962-8873602KA | 2968A (GEN) | 5962-8869601XA | 29C827A (GEN) | 5962-8766705KA |
| 29FCT521A (GEN) | 5962-8873602LA | 2968A (GEN) | 5962-8869602YA | 29C827A (GEN) | 5962-8766705LA |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

| Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN |
|---|---|---|---|---|---|
| 29828A (GEN) | 5962-88605023A | 29863A (GEN) | 5962-8860402KA | HCTS30DMSR | 5962R9573501VCC |
| 29828A (GEN) | 5962-8860502KA | 29863A (GEN) | 5962-8860402LA | HCTS30KMSR | 5962R9573501VXC |
| 29828A (GEN) | 5962-8860502LA | 29C863 (GEN) | 5962-87704023A | BXM-300 (GEN) | 5962-98A1701VXA |
| 29C828 (GEN) | 5962-87667023A | 29C863 (GEN) | 5962-8770402KA | BXM-300A (GEN) | 5962-98A1702VXA |
| 29C828 (GEN) | 5962-8766702KA | 29C863 (GEN) | 5962-8770402LA | CJSE300 | 5962-9313403HXC |
| 29C828 (GEN) | 5962-8766702LA | 29C863A (GEN) | 5962-87704063A | LCA300 (GEN) | 5962-94B0601M4C |
| 29C828A (GEN) | 5962-87667063A | 29C863A (GEN) | 5962-8770406KA | LCA300 (GEN) | 5962-94B0601M5C |
| 29C828A (GEN) | 5962-8766706KA | 29C863A (GEN) | 5962-8770406LA | LCA300 (GEN) | 5962-94B0601M6C |
| 29C828A (GEN) | 5962-8766706LA | CJSE299 | 5962-9313402HXC | LCA300 (GEN) | 5962-94B0601M7C |
| 2983 (GEN) | 5962-8851902VA | HCTS299 (GEN) | 5962R9574601V9A | LCA300 (GEN) | 5962-94B0601M8C |
| 29833A (GEN) | 5962-90513013A | HCTS299 (GEN) | 5962R9574601VRC | LCA300 (GEN) | 5962-94B0601M9C |
| 29833A (GEN) | 5962-9051301KA | HCTS299KMSR | 5962R9574601VXC | LCA300 (GEN) | 5962-94B0601MCC |
| 29833A (GEN) | 5962-9051301LA | LM2990J-12-QML | 5962-9571001QEA | LCA300 (GEN) | 5962-94B0601MMC |
| 29C833A (GEN) | 5962-88573043A | LM2990WG-12-QML | 5962-9571001QXA | LCA300 (GEN) | 5962-94B0601MNC |
| 29C833A (GEN) | 5962-8857304KA | OM2990-12N5M/883B | 5962-9571001MNA | LCA300 (GEN) | 5962-94B0601MTC |
| 29C833A (GEN) | 5962-8857304LA | OM2990-12SRM/883B | 5962-9571001MMA | LCA300 (GEN) | 5962-94B0601MUC |
| 29C841 (GEN) | 5962-87603013A | OM2990-12STM | 5962-9571001MUA | LCA300 (GEN) | 5962-94B0601MXC |
| 29C841 (GEN) | 5962-8760301KA | 2990-15 (GEN) | 5962-9570901M2A | LCA300 (GEN) | 5962-94B0601MYC |
| 29C841 (GEN) | 5962-8760301LA | 2990-15 (GEN) | 5962-9570901MMA | LCA300 (GEN) | 5962-94B0601MZC |
| 29C841A (GEN) | 5962-87603053A | 2990-15 (GEN) | 5962-9570901MNA | LCA310 (GEN) | 5962-94B0602M4C |
| 29C841A (GEN) | 5962-8760305KA | 2990-15 (GEN) | 5962-9570901MTA | LCA310 (GEN) | 5962-94B0602M5C |
| 29C841A (GEN) | 5962-8760305LA | 2990-15 (GEN) | 5962-9570901MYA | LCA310 (GEN) | 5962-94B0602M6C |
| 29C843 (GEN) | 5962-87603023A | LM2990J-15-QML | 5962-9570901QEA | LCA310 (GEN) | 5962-94B0602M7C |
| 29C843 (GEN) | 5962-8760302KA | LM2990WG-15-QML | 5962-9570901QXA | LCA310 (GEN) | 5962-94B0602M8C |
| 29C843 (GEN) | 5962-8760302LA | OM2990-15N5M/883B | 5962-9570901MZA | LCA310 (GEN) | 5962-94B0602M9C |
| 29C843A (GEN) | 5962-87603063A | OM2990-15SRM/883B | 5962-9570901M4A | LCA310 (GEN) | 5962-94B0602MCC |
| 29C843A (GEN) | 5962-8760306KA | OM2990-15STM | 5962-9570901MUA | LCA310 (GEN) | 5962-94B0602MMC |
| 29C843A (GEN) | 5962-8760306LA | OM2990-5N5M/883B | 5962-9571101MNA | LCA310 (GEN) | 5962-94B0602MNC |
| 29853A (GEN) | 5962-90513023A | OM2990-5SRM/883B | 5962-9571101MMA | LCA310 (GEN) | 5962-94B0602MTC |
| 29853A (GEN) | 5962-9051302KA | LM2990J-5.0-QML | 5962-9571101QEA | LCA310 (GEN) | 5962-94B0602MUC |
| 29853A (GEN) | 5962-9051302LA | LM2990WG-5.0-QML | 5962-9571101QXA | LCA310 (GEN) | 5962-94B0602MXC |
| 29C853 (GEN) | 5962-88573013A | OM2990-5STM | 5962-9571101MUA | LCA310 (GEN) | 5962-94B0602MYC |
| 29C853 (GEN) | 5962-8857301KA | OM2990-5.2N5M/883B | 5962-9571102MNA | LCA310 (GEN) | 5962-94B0602MZC |
| 29C853 (GEN) | 5962-8857301LA | OM2990-5.2SRM/883B | 5962-9571102MMA | LCB300 (GEN) | 5962-94B0603M4C |
| 29C853A (GEN) | 5962-88573033A | OM2990-5.2STM | 5962-9571102MUA | LCB300 (GEN) | 5962-94B0603M5C |
| 29C853A (GEN) | 5962-8857303KA | LM2991J-QML | 5962-9650501QEA | LCB300 (GEN) | 5962-94B0603M6C |
| 29C853A (GEN) | 5962-8857303LA | LM2991J-QMLV | 5962-9650501VEA | LCB300 (GEN) | 5962-94B0603M7C |
| 29855A (GEN) | 5962-90513033A | LM2991WG-QML | 5962-9650501QXA | LCB300 (GEN) | 5962-94B0603M8C |
| 29855A (GEN) | 5962-9051303KA | 29921A (GEN) | 5962-8775504LA | LCB300 (GEN) | 5962-94B0603M9C |
| 29855A (GEN) | 5962-9051303LA | 29C921 (GEN) | 5962-8851603LA | LCB300 (GEN) | 5962-94B0603MCC |
| 29C855 (GEN) | 5962-88573023A | 29923A (GEN) | 5962-8775505LA | LCB300 (GEN) | 5962-94B0603MMC |
| 29C855 (GEN) | 5962-8857302KA | 29C923 (GEN) | 5962-8851604LA | LCB300 (GEN) | 5962-94B0603MNC |
| 29C855 (GEN) | 5962-8857302LA | 29925A (GEN) | 5962-8775506LA | LCB300 (GEN) | 5962-94B0603MTC |
| 29861A (GEN) | 5962-88604013A | 29C927 (GEN) | 5962-8766703LA | LCB300 (GEN) | 5962-94B0603MUC |
| 29861A (GEN) | 5962-8860401KA | 29C928 (GEN) | 5962-8766704LA | LCB300 (GEN) | 5962-94B0603MXC |
| 29861A (GEN) | 5962-8860401LA | 29C941 (GEN) | 5962-8760303LA | LCB300 (GEN) | 5962-94B0603MYC |
| 29C861 (GEN) | 5962-87704013A | 29C943 (GEN) | 5962-8760304LA | LCB300 (GEN) | 5962-94B0603MZC |
| 29C861 (GEN) | 5962-8770401KA | 29C961 (GEN) | 5962-8770403LA | LCB310 (GEN) | 5962-94B0604M4C |
| 29C861 (GEN) | 5962-8770401LA | 29C963 (GEN) | 5962-8770404LA | LCB310 (GEN) | 5962-94B0604M5C |
| 29C861A (GEN) | 5962-87704053A | ACS30 (GEN) | 5962F9863101V9A | LCB310 (GEN) | 5962-94B0604M6C |
| 29C861A (GEN) | 5962-8770405KA | ACS30 (GEN) | 5962F9863101VCC | LCB310 (GEN) | 5962-94B0604M7C |
| 29C861A (GEN) | 5962-8770405LA | ACS30 (GEN) | 5962F9863101VXC | LCB310 (GEN) | 5962-94B0604M8C |
| 29863A (GEN) | 5962-88604023A | HCTS30 (GEN) | 5962R9573501V9A | LCB310 (GEN) | 5962-94B0604M9C |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART II, Listed By Generic PIN

| Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN |
|---|---|---|---|---|---|
| LCB310 (GEN) | 5962-94B0604MCC | TVP3010 (GEN) | 5962-9675901QYA | HS1-303RH-8 | 5962R9581301QCC |
| LCB310 (GEN) | 5962-94B0604MMC | ADS-30189 (GEN) | 5962-9319802HXA | HS9-303RH-8 | 5962R9581301QXC |
| LCB310 (GEN) | 5962-94B0604MNC | HS0-302RH-Q | 5962R9581201V9A | 3042-100 (GEN) | 5962-8971303Q8A |
| LCB310 (GEN) | 5962-94B0604MTC | HS1-302RH-8 | 5962R9581201QCC | 3042-100 (GEN) | 5962-8971303QTA |
| LCB310 (GEN) | 5962-94B0604MUC | HS1-302RH-Q | 5962R9581201VCC | 3042-100 (GEN) | 5962-8971303QUA |
| LCB310 (GEN) | 5962-94B0604MXC | HS-302 (GEN) | 5962R9581201TCC | 3042-100 (GEN) | 5962-8971303QZA |
| LCB310 (GEN) | 5962-94B0604MYC | HS9-302RH-Q | 5962R9581201VXC | XC3042-100CB100B | 5962-8971303M9C |
| LCB310 (GEN) | 5962-94B0604MZC | MN3020H/B | 5962-8971801XA | XC3042-100CQ100B | 5962-8971303MMC |
| LEA300 (GEN) | 5962-94B0605M4C | MN3020H/B | 5962-8971801XC | XC3042-100CQ100B | 5962-8971303MNC |
| LEA300 (GEN) | 5962-94B0605M5C | 3020-100 (GEN) | 5962-8994803Q9A | XC3042-100CQ100B | 5962-8971303MYC |
| LEA300 (GEN) | 5962-94B0605M6C | 3020-100 (GEN) | 5962-8994803QUA | XC3042-100PG132B | 5962-8971303MZC |
| LEA300 (GEN) | 5962-94B0605M7C | 3020-100 (GEN) | 5962-8994803QZA | XC3042-100PG84B | 5962-8971303MXC |
| LEA300 (GEN) | 5962-94B0605M8C | XC3020-100CB100B | 5962-8994803MMC | 3042-125 (GEN) | 5962-8971304Q8A |
| LEA300 (GEN) | 5962-94B0605M9C | XC3020-100CB100B | 5962-8994803MNC | 3042-125 (GEN) | 5962-8971304QTA |
| LEA300 (GEN) | 5962-94B0605MCC | XC3020-100CQ100B | 5962-8994803MTC | 3042-125 (GEN) | 5962-8971304QUA |
| LEA300 (GEN) | 5962-94B0605MMC | XC3020-100CQ100B | 5962-8994803MYC | 3042-125 (GEN) | 5962-8971304QZA |
| LEA300 (GEN) | 5962-94B0605MNC | XC3020-100PG84B | 5962-8994803MXC | 3042-50 (GEN) | 5962-8971301M9C |
| LEA300 (GEN) | 5962-94B0605MTC | 3020-125 (GEN) | 5962-8994804Q9A | 3042-50 (GEN) | 5962-8971301MMC |
| LEA300 (GEN) | 5962-94B0605MUC | 3020-125 (GEN) | 5962-8994804QUA | 3042-50 (GEN) | 5962-8971301MNC |
| LEA300 (GEN) | 5962-94B0605MXC | 3020-125 (GEN) | 5962-8994804QZA | 3042-50 (GEN) | 5962-8971301MXC |
| LEA300 (GEN) | 5962-94B0605MYC | 3020-50 (GEN) | 5962-8994801MMC | 3042-50 (GEN) | 5962-8971301MYC |
| LEA300 (GEN) | 5962-94B0605MZC | 3020-50 (GEN) | 5962-8994801MNC | 3042-50 (GEN) | 5962-8971301MZC |
| LEA310 (GEN) | 5962-94B0606M4C | 3020-50 (GEN) | 5962-8994801MTC | 3042-50 (GEN) | 5962-8971301Q8A |
| LEA310 (GEN) | 5962-94B0606M5C | 3020-50 (GEN) | 5962-8994801MXC | 3042-50 (GEN) | 5962-8971301QTA |
| LEA310 (GEN) | 5962-94B0606M6C | 3020-50 (GEN) | 5962-8994801MYC | 3042-50 (GEN) | 5962-8971301QUA |
| LEA310 (GEN) | 5962-94B0606M7C | 3020-50 (GEN) | 5962-8994801MZA | 3042-50 (GEN) | 5962-8971301QZA |
| LEA310 (GEN) | 5962-94B0606M8C | 3020-50 (GEN) | 5962-8994801Q9A | 3042-50 (GEN) | 5962-8971301XC |
| LEA310 (GEN) | 5962-94B0606M9C | 3020-50 (GEN) | 5962-8994801QUA | 3042-50 (GEN) | 5962-8971301YC |
| LEA310 (GEN) | 5962-94B0606MCC | 3020-50 (GEN) | 5962-8994801QZA | 3042-50 (GEN) | 5962-8971301ZC |
| LEA310 (GEN) | 5962-94B0606MMC | 3020-50 (GEN) | 5962-8994801XC | 3042-70 (GEN) | 5962-8971302M9C |
| LEA310 (GEN) | 5962-94B0606MNC | 3020-50 (GEN) | 5962-8994801YC | 3042-70 (GEN) | 5962-8971302MMC |
| LEA310 (GEN) | 5962-94B0606MTC | 3020-70 (GEN) | 5962-8994802MMC | 3042-70 (GEN) | 5962-8971302MNC |
| LEA310 (GEN) | 5962-94B0606MUC | 3020-70 (GEN) | 5962-8994802MNC | 3042-70 (GEN) | 5962-8971302MXC |
| LEA310 (GEN) | 5962-94B0606MXC | 3020-70 (GEN) | 5962-8994802MTC | 3042-70 (GEN) | 5962-8971302MYC |
| LEA310 (GEN) | 5962-94B0606MYC | 3020-70 (GEN) | 5962-8994802MXC | 3042-70 (GEN) | 5962-8971302MZC |
| LEA310 (GEN) | 5962-94B0606MZC | 3020-70 (GEN) | 5962-8994802MYC | 3042-70 (GEN) | 5962-8971302Q8A |
| UT300*QCR | 5962R96B0218Q*C | 3020-70 (GEN) | 5962-8994802MZA | 3042-70 (GEN) | 5962-8971302QTA |
| UT300*VCR | 5962R96B0218V*C | 3020-70 (GEN) | 5962-8994802Q9A | 3042-70 (GEN) | 5962-8971302QUA |
| XQV300-4CB228 | 5962-9957201QYC | 3020-70 (GEN) | 5962-8994802QUA | 3042-70 (GEN) | 5962-8971302QZA |
| XQV300-4CB228 | 5962-9957201QZC | 3020-70 (GEN) | 5962-8994802QZA | 3042-70 (GEN) | 5962-8971302XC |
| XQVR300-4CB228 | 5962R9957201QYC | 3020-70 (GEN) | 5962-8994802XC | 3042-70 (GEN) | 5962-8971302YC |
| XQVR300-4CB228 | 5962R9957201QZC | 3020-70 (GEN) | 5962-8994802YC | 3042-70 (GEN) | 5962-8971302ZC |
| XQV300-4CPQ240 | 5962-9957201NTB | ADS-30214 | 5962-9319803HXA | HS306RH (GEN) | 5962R9581202VCA |
| XQVR300-4CPQ240 | 5962R9957201NTB | ADS-30214 | 5962-9319803HXC | HS306RH (GEN) | 5962R9581202VXA |
| XQV300-4CBG432 | 5962-9957201NUA | TVP3026-175 (GEN) | 5962-9675801NYB | HS0-307RH-Q | 5962R9581302V9A |
| XQVR300-4CBG432 | 5962R9957201NUA | TVP3026-175 (GEN) | 5962-9675801QXA | HS-307 (GEN) | 5962R9581302VCC |
| MN3008 (GEN) | 5962-8768801YA | HS-302 (GEN) | 5962R9581201TXC | HS-307 (GEN) | 5962R9581302VXC |
| MN3008H/B | 5962-8768801XA | HS9-302RH-8 | 5962R9581201QXC | HS-307 (GEN) | 5962R9581302QCC |
| MN3008H/B | 5962-8768801XC | HS0-303RH-Q | 5962R9581301V9A | HS-307 (GEN) | 5962R9581302QXC |
| MN3009 (GEN) | 5962-8768802YA | HS1-303RH-Q | 5962R9581301VCC | SG3081J/883B | 5962-8866401EA |
| MN3009H/B | 5962-8768802XA | HS-303 (GEN) | 5962R9581301TCC | 3090-100 (GEN) | 5962-8982303QXA |
| MN3009H/B | 5962-8768802XC | HS-303 (GEN) | 5962R9581301TXC | 3090-100 (GEN) | 5962-8982303QZA |
| CJSE301 | 5962-9313404HXC | HS9-303RH-Q | 5962R9581301VXC | XC3090-100CB164B | 5962-8982303MTC |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART II, Listed By Generic PIN

| Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN |
|---|---|---|---|---|---|
| XC3090-100CB164B | 5962-8982303MZC | GEM31701Q2C | 5962-0150701Q2C | SMJ320C15-25JDM | 5962-8763308QA |
| XC3090-100PG175B | 5962-8982303MXC | GEM31701QEA | 5962-0150701QEA | SMJ320F240HFPM40 | 5962-9861201QXA |
| 3090-125 (GEN) | 5962-8982304QXA | GEM31701QEC | 5962-0150701QEC | SMJ320C25FBM | 5962-8861901YA |
| 3090-125 (GEN) | 5962-8982304QZA | HS1-3182/883 | 5962-8687901EA | SMJ320C25FJM | 5962-8861901ZA |
| 3090-50 (GEN) | 5962-8982301MTC | 3183A (GEN) | 5962-8759801EA | SMJ320C25GBM | 5962-8861901XA |
| 3090-50 (GEN) | 5962-8982301MUA | 3190A-4 (GEN) | 5962-9561102MYC | SMJ320C25-50FJM | 5962-8861902ZA |
| 3090-50 (GEN) | 5962-8982301MXC | 3190A-4 (GEN) | 5962-9561102MZC | SMJ320C25-50GBM | 5962-8861902XA |
| 3090-50 (GEN) | 5962-8982301MYA | 3190A-4 (GEN) | 5962-9561102MXC | SMJ320C26BFDM | 5962-8861903YA |
| 3090-50 (GEN) | 5962-8982301MZC | 3190A-5 (GEN) | 5962-9561101MYC | SMJ320C26BGBM | 5962-8861903XA |
| 3090-50 (GEN) | 5962-8982301QXA | 3190A-5 (GEN) | 5962-9561101MZC | 320C30 (GEN) | 5962-9052601MXA |
| 3090-50 (GEN) | 5962-8982301QZA | 3190A-5 (GEN) | 5962-9561101MXC | 320C30 (GEN) | 5962-9052601MYA |
| 3090-50 (GEN) | 5962-8982301XC | 3195A-4 (GEN) | 5962-9561202MYC | 320C30 (GEN) | 5962-9052601MZA |
| 3090-50 (GEN) | 5962-8982301YA | 3195A-4 (GEN) | 5962-9561202MZC | 320C30 (GEN) | 5962-9052602MXA |
| 3090-50 (GEN) | 5962-8982301ZC | 3195A-4 (GEN) | 5962-9561202MXC | 320C30 (GEN) | 5962-9052602MYA |
| 3090-70 (GEN) | 5962-8982302MTC | 3195A-5 (GEN) | 5962-9561201MYC | 320C30 (GEN) | 5962-9052602MZA |
| 3090-70 (GEN) | 5962-8982302MUA | 3195A-5 (GEN) | 5962-9561201MZC | 320C30 (GEN) | 5962-9052602MUA |
| 3090-70 (GEN) | 5962-8982302MXC | 3195A-5 (GEN) | 5962-9561201MXC | 320C30 (GEN) | 5962-9052601MUA |
| 3090-70 (GEN) | 5962-8982302MYA | HCS32DMSR | 5962R9578101VCC | 320C30 (GEN) | 5962-9052603MUA |
| 3090-70 (GEN) | 5962-8982302MZC | HCS32HMSR | 5962R9578101V9A | 320C30 (GEN) | 5962-9052603MXA |
| 3090-70 (GEN) | 5962-8982302QXA | HCS32KMSR | 5962R9578101VXC | 320C30 (GEN) | 5962-9052603QMC |
| 3090-70 (GEN) | 5962-8982302QZA | HCTS32DMSR | 5962R9573601VCC | 320C30 (GEN) | 5962-9052603QTC |
| 3090-70 (GEN) | 5962-8982302XC | HCTS32HMSR | 5962R9573601V9A | 320C30 (GEN) | 5962-9052604Q9A |
| 3090-70 (GEN) | 5962-8982302YA | HCTS32KMSR | 5962R9573601VXC | SMJ320C30GBM40 | 5962-9052604MXA |
| 3090-70 (GEN) | 5962-8982302ZC | RHFAC32K01Q | 5962F8761401XC | SMJ320C30HFGM40 | 5962-9052604MUA |
| MAX310MJE/883B | 5962-9455601MEA | RHFAC32K01V | 5962F8761401VXC | SMJ320C30GBM50 | 5962-9052605MXA |
| MAX310MLP/883B | 5962-9455601M2C | RHFAC32K02Q | 5962F8761401XA | SMJ320C30GBM50 | 5962-9052605QXC |
| GEM31001QCA | 7701001CA | RHFAC32K02V | 5962F8761401VXA | SMJ320C30HFGM50 | 5962-9052605MUA |
| GEM31001QCC | 7701001CC | GEM32003QQA | 5962-8853503QA | SMJ320C30KGDM50B | 5962-9052605Q9A |
| GEM31001QDA | 7701001DA | GEM32003QQC | 5962-8853503QC | 320C31-27 (GEN) | 5962-9205801MXA |
| GEM31001QDC | 7701001DC | GEM32003QXA | 5962-8853503XA | 320C31-27 (GEN) | 5962-9205801MYA |
| MAX311MJE/883B | 5962-9455602MEA | GEM32003QXC | 5962-8853503XC | 320C31 (GEN) | 5962-9205802MXA |
| MAX311MLP/883B | 5962-9455602M2C | GEM32003QYA | 5962-8853503YA | 320C31 (GEN) | 5962-9205802MYA |
| GEM31201Q2A | 5962-9158601Q2A | GEM32003QYC | 5962-8853503YC | 320C31 (GEN) | 5962-9205802QUC |
| GEM31201Q2C | 5962-9158601Q2C | 32010 (GEN) | 8405301QA | 320C31 (GEN) | 5962-9205802QZC |
| GEM31201QEA | 5962-9158601QEA | 32010 (GEN) | 8405301ZA | 320C31 (GEN) | 5962-9205803Q9A |
| GEM31201QEC | 5962-9158601QEC | 320C10 (GEN) | 5962-8763301QA | 320C31 (GEN) | 5962-9205803QZC |
| GEM31201QFA | 5962-9158601QFA | 320C10 (GEN) | 5962-8763301XA | 320LC31 (GEN) | 5962-9760601Q9A |
| GEM31201QFC | 5962-9158601QFC | 320CM10 (GEN) | 5962-8763303QA | SMJ320C31GFAM40 | 5962-9205803MXA |
| HFA3127MJ/883 | 5962-9474901MEA | 320CM10 (GEN) | 5962-8763303XA | SMJ320C31GFAM40 | 5962-9205803MXC |
| CA3130 (GEN) | 7703301GA | 320C10-25 (GEN) | 5962-8763302QA | SMJ320C31HFGM40 | 5962-9205803MYA |
| 3142A-4 (GEN) | 5962-9561002MYC | 320C10-25 (GEN) | 5962-8763302XA | SMQ320LC31PQM40 | 5962-9760601NXB |
| 3142A-4 (GEN) | 5962-9561002MZC | 320C10-25 (GEN) | 5962-8763305QA | SMJ320C31GFAM50 | 5962-9205804MXA |
| 3142A-4 (GEN) | 5962-9561002MUC | 320C10-25 (GEN) | 5962-8763305XA | SMJ320C31GFAM50 | 5962-9205804MXC |
| 3142A-4 (GEN) | 5962-9561002MXC | 320CM10-25 (GEN) | 5962-8763304QA | SMJ320C31GFAS60 | 5962-9205805QXA |
| 3142A-5 (GEN) | 5962-9561001MYC | 320CM10-25 (GEN) | 5962-8763304XA | SMJ320C31HFGM50 | 5962-9205804MYA |
| 3142A-5 (GEN) | 5962-9561001MZC | 320E14 (GEN) | 5962-9300601MXA | SMJ320C31HFGS60 | 5962-9205805QYA |
| 3142A-5 (GEN) | 5962-9561001MUC | 320E14 (GEN) | 5962-9300601MYA | SMQ320C32PCMM50 | 5962-9679001NXB |
| 3142A-5 (GEN) | 5962-9561001MXC | 320C15 (GEN) | 5962-8763307QA | SMQ320C32PCMM60 | 5962-9679002NXB |
| GEM31606QEA | 8605106EA | 320C15 (GEN) | 5962-8763307XA | SMJ320VC33HFGM | 5962-0053902QYA |
| GEM31606QEC | 8605106EC | 320C15 (GEN) | 5962-8763307YA | SMJ320VC33HFGM | 5962-0053902QYC |
| GEM31606QFA | 8605106FA | 320E15 (GEN) | 5962-8763306QA | 320VC33 (GEN) | 5962-0053901QXA |
| GEM31606QFC | 8605106FC | 320C15-25 (GEN) | 5962-8763308XA | SMJ320VC33HFGM150 | 5962-0053901QYA |
| GEM31701Q2A | 5962-0150701Q2A | SMJ320C15-25FJM | 5962-8763308YA | SMJ320VC33HFGM150 | 5962-0053901QYC |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

| Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN |
|---|---|---|---|---|---|
| TLC32040 (GEN) | 5962-9086301M3A | SMJ320C6415DGADW | 5962-0324501QXA | WE32K32N-120HQ | 5962-9461402HXC |
| TLC32040 (GEN) | 5962-9086301MXA | 320C6701 (GEN) | 5962-9866102QXA | WE32K32-120G1TQ | 5962-9461402HBA |
| 320C40-33 (GEN) | 5962-9466901QXA | SMJ320C6701W14 | 5962-9866101QXA | WE32K32-120G1TQ | 5962-9461402HBC |
| 320C40-33 (GEN) | 5962-9466901QYC | SMV320C6701GLPM14 | 5962-9866102VXA | WE32K32-120G1UQ | 5962-9461402H9A |
| 320C40-40 (GEN) | 5962-9466902Q9A | SMV320C6701GLPW14 | 5962-9866101VXA | WE32K32-120G1UQ | 5962-9461402H9C |
| 320C40-40 (GEN) | 5962-9466902Q9B | SMJ320C80GFM50 | 5962-9679101QXA | WE32K32N-120H1Q | 5962-9461402HUA |
| 320C40-40 (GEN) | 5962-9466902Q9C | SMJ320C80HFHM50 | 5962-9679101QYC | WE32K32N-120H1Q | 5962-9461402HUC |
| 320C40-40 (GEN) | 5962-9466902QUC | CJSE321 | 5962-9313405HXC | WE32K32-120G2Q | 5962-9461402HMA |
| 320C40-40 (GEN) | 5962-9466902QZC | A32100DX-CQ84B | 5962-9857901QXC | WE32K32-120G2Q | 5962-9461402HMC |
| SMJ320C40GFM40 | 5962-9466902QXA | A32100DX-DIE | 5962-9857901Q9A | WE32K32-120G2UQ | 5962-9461402HZA |
| SMJ320C40GFM40 | 5962-9466902QXC | A32100DX-1CQ84B | 5962-9857902QXC | WE32K32-120G2UQ | 5962-9461402HZC |
| SMJ320C40HFHM40 | 5962-9466902QYC | RTSX32SU-1CQ208B | 5962-0150806QYC | 32K32-150 (GEN) | 5962-9461401HYA |
| SMJ320C40KGDM40D | 5962-9466902Q9D | RTSX32SU-1CQ208E | 5962-0150808QYC | AS8E32K32P-150/883C | 5962-9461401HUA |
| 320C40-50 (GEN) | 5962-9466903Q9A | RTSX32SU-1CQ256B | 5962-0150806QXC | AS8E32K32P-150/883C | 5962-9461401HUC |
| 320C40-50 (GEN) | 5962-9466903Q9B | RTSX32SU-1CQ256E | 5962-0150808QXC | AS8E32K32Q-150/883C | 5962-9461401HMA |
| 320C40-50 (GEN) | 5962-9466903Q9C | CJSE322 | 5962-9313406HXC | AS8E32K32Q-150/883C | 5962-9461401HMC |
| 320C40-50 (GEN) | 5962-9466903QUC | A32200DX-CQ208B | 5962-9952701QYC | WE32K32N-150HQ | 5962-9461401HXA |
| 320C40-50 (GEN) | 5962-9466903QZC | A32200DX-CQ256B | 5962-9952701QXC | WE32K32N-150HQ | 5962-9461401HXC |
| SMJ320C40GFM50 | 5962-9466903QXA | A32200DX-DIE | 5962-9952701Q9A | WE32K32-150G1TQ | 5962-9461401HBA |
| SMJ320C40GFM50 | 5962-9466903QXC | A32200DX-1CQ208B | 5962-9952702QYC | WE32K32-150G1TQ | 5962-9461401HBC |
| SMJ320C40HFHM50 | 5962-9466903QYC | A32200DX-1CQ256B | 5962-9952702QXC | WE32K32-150G1UQ | 5962-9461401H9A |
| SMJ320C40KGDM50D | 5962-9466903Q9D | 32C201-10 (GEN) | 5962-8859901JA | WE32K32-150G1UQ | 5962-9461401H9C |
| 320C40-60 (GEN) | 5962-9466904Q9A | RTSX32SU-CQ208B | 5962-0150805QYC | WE32K32N-150H1Q | 5962-9461401HUA |
| 320C40-60 (GEN) | 5962-9466904QUC | RTSX32SU-CQ208E | 5962-0150807QYC | WE32K32N-150H1Q | 5962-9461401HUC |
| 320C40-60 (GEN) | 5962-9466904QZC | RTSX32SU-CQ256B | 5962-0150805QXC | WE32K32-150G2Q | 5962-9461401HMA |
| SMJ320C40GFS60 | 5962-9466904QXA | RTSX32SU-CQ256E | 5962-0150807QXC | WE32K32-150G2Q | 5962-9461401HMC |
| SMJ320C40HFHS60 | 5962-9466904QYC | ACS32 (GEN) | 5962F9862401V9A | WE32K32-150G2UQ | 5962-9461401HZA |
| 320MCM41 (GEN) | 5962-9753601QXC | ACS32 (GEN) | 5962F9862401VCC | WE32K32-150G2UQ | 5962-9461401HZC |
| 320MCM41 (GEN) | 5962-9753602QXC | ACS32 (GEN) | 5962F9862401VXC | 32K32-90 (GEN) | 5962-9461403HYA |
| SMJ320MCM42CHFNM | 5962-9678902QXC | 29823A (GEN) | 5962-8775507QLA | AS8E32K32P-90/883C | 5962-9461403HUA |
| SMJ320MCM42DHFNM | 5962-9678901QXC | GEM32307Q3A | 5962-8775507Q3A | AS8E32K32P-90/883C | 5962-9461403HUC |
| 320MCM42-50 (GEN) | 5962-9678903QXC | GEM32307Q3C | 5962-8775507Q3C | AS8E32K32Q-90/883C | 5962-9461403HMA |
| 320MCM42-50 (GEN) | 5962-9678904QXC | GEM32307QKA | 5962-8775507QKA | AS8E32K32Q-90/883C | 5962-9461403HMC |
| TLC32044 (GEN) | 5962-9086302M3A | GEM32307QKC | 5962-8775507QKC | WE32K32-90HQ | 5962-9461403HXA |
| TLC32044 (GEN) | 5962-9086302MXA | 29825A (GEN) | 5962-8775508QLA | WE32K32-90HQ | 5962-9461403HXC |
| TLC32046M (GEN) | 5962-9086303M3A | GEM32208Q3A | 5962-8775508Q3A | WE32K32-90G1TQ | 5962-9461403HBA |
| TLC32046M (GEN) | 5962-9086303MXA | GEM32208Q3C | 5962-8775508Q3C | WE32K32-90G1TQ | 5962-9461403HBC |
| 320C50A40 (GEN) | 5962-9455801QXA | GEM32208QKA | 5962-8775508QKA | WE32K32-90G1UQ | 5962-9461403H9A |
| 320C50A40 (GEN) | 5962-9455801QYA | GEM32208QKC | 5962-8775508QKC | WE32K32-90G1UQ | 5962-9461403H9C |
| SMJ320C50KGDM40B | 5962-9455805Q9A | GEM32109QLA | 5962-8775509QLA | WE32K32N-90H1Q | 5962-9461403HUA |
| 320C50A50 (GEN) | 5962-9455802QXA | GEM32109QLC | 5962-8775509QLC | WE32K32N-90H1Q | 5962-9461403HUC |
| 320C50A50 (GEN) | 5962-9455802QYA | 3231 (GEN) | 5962-9174905HUA | WE32K32-90G2Q | 5962-9461403HMA |
| SMJ320C50GFAM50 | 5962-9455803QXA | 3231 (GEN) | 5962-9174905HZA | WE32K32-90G2Q | 5962-9461403HMC |
| SMJ320C50HFGM50 | 5962-9455803QYA | 3232 (GEN) | 5962-9174906HUA | WE32K32-90G2UQ | 5962-9461403HZA |
| SMJ320C50KGDM50B | 5962-9455803Q9A | 3232 (GEN) | 5962-9174906HZA | WE32K32-90G2UQ | 5962-9461403HZC |
| SMJ320C50GFAM66 | 5962-9455804QXA | 3232 (GEN) | 5962-9174907HUA | HCTS245 (GEN) | 5962R9574501V9A |
| SMJ320C50HFGM66 | 5962-9455804QYA | 3232 (GEN) | 5962-9174907HZA | LSH32-40 (GEN) | 5962-8971702MXA |
| SMJ320C50KGDM66B | 5962-9455804Q9A | 32K32-120 (GEN) | 5962-9461402HYA | LSH32-40 (GEN) | 5962-8971702MYA |
| SMJ320C50PQM66 | 5962-9455804NZB | AS8E32K32P-120/883C | 5962-9461402HUA | GEM32401Q2A | 5962-87793012A |
| SMJ320VC5416HFG | 5962-0153001QXA | AS8E32K32P-120/883C | 5962-9461402HUC | GEM32401Q2C | 5962-87793012C |
| SMJ320LC549HFGW60 | 5962-0251201QXA | AS8E32K32Q-120/883C | 5962-9461402HMA | GEM32401QEA | 5962-8779301EA |
| SMJ320C6201B | 5962-9857801QXA | AS8E32K32Q-120/883C | 5962-9461402HMC | GEM32401QEC | 5962-8779301EC |
| SMJ320C6203 | 5962-0051001QXA | WE32K32N-120HQ | 5962-9461402HXA | GEM32401QFA | 5962-8779301FA |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

| Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN |
|---|---|---|---|---|---|
| GEM32401QFC | 5962-8779301FC | ARX3410 | 5962-9063604HXA | 35063 (GEN) | 5962-9075701MPA |
| LSH32-50 (GEN) | 5962-8971701MXA | ARX3410 | 5962-9063604HXC | 35074 (GEN) | 5962-8996901CA |
| LSH32-50 (GEN) | 5962-8971701MYA | ARX3411 (GEN) | 5962-8757904XA | 35074A (GEN) | 5962-89969022A |
| HS1-3282/883 | 5962-8688001QA | ARX3411 (GEN) | 5962-8757904YA | 35074A (GEN) | 5962-8996902CA |
| HS4-3282/883 | 5962-8688001XA | ARX3416 (GEN) | 5962-8944701HXA | 35074M (GEN) | 5962-89969012A |
| MN3290 (GEN) | 5962-8953103HYA | ARX3416 (GEN) | 5962-8944701HYA | 35164 (GEN) | 5962-9231801MPA |
| MN3291 (GEN) | 5962-8953104HYA | 3416-511 | 5962-8944706HXA | 3517 (GEN) | 5962-87643012A |
| MN3292 (GEN) | 5962-8953102HYA | 3416-511 | 5962-8944706HXC | 3517 (GEN) | 5962-8764301EA |
| TPS3307-18 | 5962-9959101Q2A | ARX3419 | 5962-8982602XA | 3523 (GEN) | 5962-8978001PA |
| TPS3307-18 | 5962-9959101QPA | ARX3419 | 5962-8982602XC | HS9-3530ARH-Q | 5962F9568701VXC |
| MSK332B-12 (GEN) | 5962-9090201HXC | ARX3419FP | 5962-8982602YA | HSO-3530ARH-Q | 5962F9568701V9A |
| MSK332B-15 (GEN) | 5962-9090202HXC | ARX3419FP | 5962-8982602YC | HS2-3530ARH-8 | 5962F9568701QGA |
| MAX333MJP/883B | 5962-9318001MRA | ARX3420 | 5962-9082903HUA | HS2-3530ARH-Q | 5962F9568701VGA |
| HS-3374 (GEN) | 5962R9678601QW | ARX3420 | 5962-9082903HUC | 3550 (GEN) | 5962-9319401M2A |
| HS-3374 (GEN) | 5962R9678601VW | ARX3424 | 5962-9082904HUA | 3550 (GEN) | 5962-9319401MEA |
| 34010-40 (GEN) | 5962-9072701MXA | ARX3424 | 5962-9082904HUC | MAX358MJE/883B | 7705203EA |
| 34010-40 (GEN) | 5962-9072701MYA | GEM34301QPA | 5962-9052201PA | MAX358MLP/883B | 77052032C |
| 34010-50 (GEN) | 5962-9072702MXA | GEM34301QPC | 5962-9052201PC | MAX359MJE/883B | 5962-8513106EA |
| 34010-50 (GEN) | 5962-9072702MYA | GEM34301QXA | 5962-9052201XA | MAX359MLP/883B | 5962-85131062C |
| ARX3402 | 5962-8604904UA | GEM34301QXC | 5962-9052201XC | 3611023 (GEN) | 5962-8951901MXC |
| ARX3402 | 5962-8604904UC | ARX3411 (GEN) | 5962-8757904UA | 3611023 (GEN) | 5962-8951901MYA |
| 34020-28 (GEN) | 5962-9162301MXA | ARX3431 (GEN) | 5962-8757904ZA | 3611023 (GEN) | 5962-8951901XC |
| 34020-28 (GEN) | 5962-9162301MYA | ACT3433-001-1 | 5962-8982609UA | 3611023 (GEN) | 5962-8951901YA |
| 34020-30 (GEN) | 5962-9162302MXA | ACT3433-001-2 | 5962-8982609UC | 3611023 (GEN) | 5962-8951902MXC |
| 34020-30 (GEN) | 5962-9162302MYA | ACT3433-201-1 | 5962-8982609ZA | 3611023 (GEN) | 5962-8951902MYA |
| SMJ34020AGBM32 | 5962-9162303MXA | ACT3433-201-2 | 5962-8982609ZC | 3611023 (GEN) | 5962-8951903MXC |
| SMJ34020AGBM32 | 5962-9162303MXC | ARX3436 (GEN) | 5962-8944701HUA | 3611023 (GEN) | 5962-8951903MYA |
| SMJ34020AHTM32 | 5962-9162303MYA | ARX3436 (GEN) | 5962-8944701HZA | 3611023 (GEN) | 5962-8951991MZC |
| SMJ34020AGBM40 | 5962-9162304MXA | ARX-3453FP | 5962-8952208YA | 3611023 (GEN) | 5962-8951991ZC |
| SMJ34020AGBM40 | 5962-9162304MXC | ARX-3453FP | 5962-8952208YC | 3611023 (GEN) | 5962-8951992MZC |
| SMJ34020AHTM40 | 5962-9162304MYA | AD346S (GEN) | 5962-8994001HXC | 3611023 (GEN) | 5962-8951993MZC |
| ARX3404 | 5962-8959202XA | MN346H/B | 5962-8994002HXA | 3611077 (GEN) | 5962-9673401MXC |
| ARX3404 | 5962-8959202XC | MN346H/B | 5962-8994002HXC | 3611077 (GEN) | 5962-9673401MYC |
| ARX3404FP | 5962-8959202YA | ARX3464 | 5962-8959206XA | 3611143 (GEN) | 8102408VA |
| ARX3404FP | 5962-8959202YC | ARX3464 | 5962-8959206XC | 3611150 (GEN) | 8102409VA |
| ARX3404-001 | 5962-8959204XA | ARX3464FP | 5962-8959206YA | ABT3614PCB | 5962-9560901NXD |
| ARX3404-001 | 5962-8959204XC | ARX3464FP | 5962-8959206YC | HS362 (GEN) | 5962-8956501XA |
| ARX3404-001FP | 5962-8959204YA | ARX3467 | 5962-8959205XA | ACT3641PCB | 5962-9560801NXD |
| ARX3404-001FP | 5962-8959204YC | ARX3467 | 5962-8959205XC | HCTS365 (GEN) | 5962R9577501V9A |
| ARX3407 | 5962-8959201XA | ARX3467FP | 5962-8959205YA | HCTS365 (GEN) | 5962R9577501VEC |
| ARX3407 | 5962-8959201XC | ARX3467FP | 5962-8959205YC | HCTS365 (GEN) | 5962R9577501VXC |
| ARX3407FP | 5962-8959201YA | UT35*QCR | 5962R96B0213Q*C | OP-37A (GEN) | 5962-88537012A |
| ARX3407FP | 5962-8959201YC | UT35*VCR | 5962R96B0213V*C | OP-37A (GEN) | 5962-8853701GA |
| ARX3407-001 | 5962-8959203XA | UT35E/R*QCH | 5962H96B0206Q*A | OP-37A (GEN) | 5962-8853701PA |
| ARX3407-001 | 5962-8959203XC | UT35E/R*QDIE | 5962H96B0206Q9A | OP37AJ/QMLV | 5962-8853701VGA |
| ARX3407-001FP | 5962-8959203YA | UT35E/R*VCH | 5962H96B0206V*A | OP37AL/QMLV | 5962-8853701VHA |
| ARX3407-001FP | 5962-8959203YC | UT35E/R*VDIE | 5962H96B0206V9A | OP37ARC/QMLV | 5962-8853701V2A |
| TLC34076-135 (GEN) | 5962-9474801QXC | UT35E/R_QCH | 5962H97B0406QXC | OP37AZ/QMLV | 5962-8853701VPA |
| 34096956-002 (GEN) | 5962H9466702QYC | UT35E/R_QCH | 5962H97B0406QZC | OP-37B (GEN) | 5962-88537022A |
| 34096956-003 (GEN) | 5962H9466703QYC | UT35E/R_VCH | 5962H97B0406VXC | OP-37BJ/883 | 5962-8853702GA |
| 34096956-004 (GEN) | 5962H9466704QYC | UT35E/R_VCH | 5962H97B0406VZC | OP-37BZ/883 | 5962-8853702PA |
| 34096956-005 (GEN) | 5962H9466701QYC | UT350*QCR | 5962R96B0219Q*C | OP-37C (GEN) | 5962-88537032A |
| 34096956-005 (GEN) | 5962H9466701VYC | UT350*VCR | 5962R96B0219V*C | OP-37C (GEN) | 5962-8853703GA |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

| Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN |
|---|---|---|---|---|---|
| TLC3702 (GEN) | 5962-9153201QHA | HCTS374 (GEN) | 5962R9574801VRC | OMR3911STM/883B | 5962R8767502UA |
| TLC3702MFKB | 5962-9153201Q2A | HCTS374 (GEN) | 5962R9574801VXC | OM3914NKM/883B | 5962-8774101XA |
| TLC3702MFKB | 5962-9153202Q2A | TLC374MFKB | 5962-87659012A | OM3914NT/883B | 5962-8774101TA |
| TLC3702MJGB | 5962-9153201QPA | TLC374MJB | 5962-8765901CA | OM3914SRM/883B | 5962-8774101YA |
| TLC3702MJGB | 5962-9153202QPA | ACS374-02 (GEN) | 5962F9565602V9A | OM3914ST/883B | 5962-8774101UA |
| TLC3702MUB | 5962-9153202QHA | ACS374-02 (GEN) | 5962F9565602VRC | OMR3914STM/883B | 5962P8774101UA |
| TLC3704MFKB | 5962-9096901M2A | ACS374-02 (GEN) | 5962F9565602VXC | HCTS393 (GEN) | 5962R9575001VCC |
| TLC3704MJB | 5962-9096901MCA | ACTS374-02 (GEN) | 5962F9566202V9A | HCTS393HMSR | 5962R9575001V9A |
| CY37064-125 (GEN) | 5962-9951901QYA | ACTS374-02 (GEN) | 5962F9566202VRC | HCTS393KMSR | 5962R9575001VXC |
| CY37064P44-154YMB | 5962-9951902QYA | ACTS374-02 (GEN) | 5962F9566202VXC | AD394S (GEN) | 5962-8851001XA |
| CY37064VP44-100YMB | 5962-9952001QYA | CY37512VP208-66UMB | 5962-9952601QZC | AD394T (GEN) | 5962-8851002XA |
| CY37128VP84-83YMB | 5962-9952201QYA | CY37512P208-100UMB | 5962-9952502QZC | LM3940J-3.3-QML | 5962-9688401QEA |
| CY37128P84-100YMB | 5962-9952101QYA | CY37512P208-83UMB | 5962-9952501QZC | LM3940WG-3.3-QML | 5962-9688401QXA |
| CY37128P84-125YMB | 5962-9952102QYA | MN376H/B | 5962-9073001HXA | AD395S (GEN) | 5962-8851003XA |
| TLC372MDQ | 5962-9554901NXD | MN376H/B | 5962-9073001HXC | AD395T (GEN) | 5962-8851004XA |
| TLC372MFKB | 5962-87658012A | OP-37C (GEN) | 5962-8853703PA | OM3957N5M/883B | 5962-9859001MXA |
| TLC372MJGB | 5962-8765801PA | RGBDAC3808H/B | 5962-8950901XA | OM3957NM/883B | 5962-9859001MNA |
| CY37256VP160-66UMB | 5962-9952401QZC | DG384AAK/883 | 5962-9678801QEA | OM3957SM/883B | 5962-9859001MMA |
| CY37256P160-125UMB | 5962-9952302QZC | HS384RH (GEN) | 5962R9581203VEA | OM3957SRM/883B | 5962-9859001MTA |
| CY37256P160-83UMB | 5962-9952301QZC | HS384RH (GEN) | 5962R9581203VYA | OM3957ST/883B | 5962-9859001MUA |
| ACS373 (GEN) | 5962F9565501V9A | MN3860 (GEN) | 5962-9057001HXA | OMR3957STM/883B | 5962P9859001MUA |
| ACS373DMSR | 5962F9565501VRC | DS3875 (GEN) | 5962-9554301QXA | OM3958N5M | 5962-9953101MXA |
| ACS373KMSR | 5962F9565501VXC | DS3884 (GEN) | 5962-9554001QXA | OM3958NM/883B | 5962-9953101MNA |
| ACTS373 (GEN) | 5962F9566101VRC | DS3885 (GEN) | 5962-9554101QXA | OM3958SM/883B | 5962-9953101MMA |
| ACTS373 (GEN) | 5962F9566101VXC | DS3886 (GEN) | 5962-9554201QXA | OM3958SRM | 5962-9953101MTA |
| HCS373 (GEN) | 5962R9579201TRC | OM3894SFB | 5962-9452001HXA | OM3958ST/883B | 5962-9953101MUA |
| HCS373 (GEN) | 5962R9579201TXC | OM3894SFC | 5962-9452001HXC | OMR3958STM/883B | 5962P9953101MUA |
| HCS373 (GEN) | 5962R9579201V9A | OM3894SXB | 5962-9452001HYA | 39C60 (GEN) | 5962-8861302TA |
| HCS373DMSR | 5962R9579201VRC | OM3894SXC | 5962-9452001HYC | 39C60 (GEN) | 5962-8861302UA |
| HCS373KMSR | 5962R9579201VXC | AD390S (GEN) | 5962-8850901XA | 39C60 (GEN) | 5962-8861302XA |
| HCTS373 (GEN) | 5962R9574701TRC | AD390S (GEN) | 5962-8850901XC | 39C60A (GEN) | 5962-8861301TA |
| HCTS373 (GEN) | 5962R9574701TXC | AD390T (GEN) | 5962-8850902XC | 39C60A (GEN) | 5962-8861301UA |
| HCTS373 (GEN) | 5962R9574701V9A | AD390TD/883B | 5962-8850902XA | 39C60A (GEN) | 5962-8861301XA |
| HCTS373 (GEN) | 5962R9574701VRC | HCTS390 (GEN) | 5962R9574901V9A | BXM-400A (GEN) | 5962-98A1801VXA |
| HCTS373 (GEN) | 5962R9574701VXC | HCTS390 (GEN) | 5962R9574901VEC | CLC400AE-QML | 5962-89970012A |
| ACS373-02 (GEN) | 5962F9565502V9A | HCTS390 (GEN) | 5962R9574901VXC | CLC400AJ-QML | 5962-8997001PA |
| ACS373-02 (GEN) | 5962F9565502VRC | HS0-390RH-Q | 5962R9581303V9A | HV400 (GEN) | 5962-9464001MPA |
| ACS373-02 (GEN) | 5962F9565502VXC | HS1-390RH-8 | 5962R9581303QEC | OP-400A (GEN) | 5962-87771013A |
| ACTS373 (GEN) | 5962F9566102V9A | HS1-390RH-Q | 5962R9581303VEC | OP-400A (GEN) | 5962-8777101CA |
| ACTS373DMSR-02 | 5962F9566102VRC | HS-390 (GEN) | 5962R9581303TEC | OP400AN/QML | 5962-8777101VKA |
| ACTS373KMSR-02 | 5962F9566102VXC | HS9-390RH-8 | 5962R9581303QYC | OP400ATC/883 | 5962-8777101M3A |
| ACS374 (GEN) | 5962F9565601V9A | HS9-390RH-Q | 5962R9581303VYC | OP400ATC/QML | 5962-8777101V3A |
| ACS374DMSR | 5962F9565601VRC | HS9-390RH-T | 5962R9581303TYC | OP400AY/883 | 5962-8777101MCA |
| ACS374KMSR | 5962F9565601VXC | 39C10B (GEN) | 5962-8770802QA | OP400AY/QML | 5962-8777101VCA |
| ACTS374 (GEN) | 5962F9566201V9A | 39C10B (GEN) | 5962-8770802UA | UT400*QCR | 5962R96B0220Q*C |
| ACTS374 (GEN) | 5962F9566201VRC | 39C10C (GEN) | 5962-8770803QA | UT400*VCR | 5962R96B0220V*C |
| ACTS374 (GEN) | 5962F9566201VXC | 39C10C (GEN) | 5962-8770803UA | 4000B (GEN) | 5962R9582601V9A |
| HCS374DMSR | 5962R9579301VRC | OM3910N5M/883B | 5962-8767501ZA | 4000B (GEN) | 5962R9582601VCC |
| HCS374HMSR | 5962R9579301V9A | OM3910NT/883B | 5962-8767501TA | 4000B (GEN) | 5962R9582601VXC |
| HCS374KMSR | 5962R9579301VXC | OM3910SRM/883B | 5962-8767501YA | 4001BN (GEN) | 5962R9582605V9A |
| HCTS374 (GEN) | 5962R9574801TRC | OM3910ST/883B | 5962-8767501UA | 4001BN (GEN) | 5962R9582605VCC |
| HCTS374 (GEN) | 5962R9574801TXC | OM3911NT/883B | 5962-8767502TA | CD4001BDMSR | 5962R9582602VCC |
| HCTS374 (GEN) | 5962R9574801V9A | OM3911ST/883B | 5962-8767502UA | CD4001BHSR | 5962R9582602V9A |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

| Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN |
|---|---|---|---|---|---|
| CD4001BKMSR | 5962R9582602VXC | CLC401AJ-QML | 5962-8997301PA | 4010B (GEN) | 5962R9582901VEC |
| CD4001BKNSR | 5962R9582605VXC | DG401AK/883 | 5962-9056901EA | 4010B (GEN) | 5962R9582901VXC |
| 4002B (GEN) | 5962R9582603V9A | DG401AZ/883 | 5962-90569012A | 40109B (GEN) | 5962R9664501V9A |
| 4002B (GEN) | 5962R9582603VCC | 4010B (GEN) | 5962R9582901V9A | 40109BN (GEN) | 5962R9664502V9A |
| 4002B (GEN) | 5962R9582603VXC | 40100B (GEN) | 5962R9659801V9A | 40109BN (GEN) | 5962R9664502VEC |
| 4002BN (GEN) | 5962R9582606V9A | 40100B (GEN) | 5962R9659801VEC | CD40109BDMSR | 5962R9664501VEC |
| 4002BN (GEN) | 5962R9582606VCC | 40100B (GEN) | 5962R9659801VXC | CD40109BKMSR | 5962R9664501VXC |
| 4002BN (GEN) | 5962R9582606VXC | 40101B (GEN) | 5962R9659901V9A | CD40109BKNSR | 5962R9664502VXC |
| CD4002BF3A | 7704403CA | 40101B (GEN) | 5962R9659901VCC | 4011B (GEN) | 5962R9662101TCC |
| HCTS4002 (GEN) | 5962R9576001V9A | 40101B (GEN) | 5962R9659901VXC | 4011B (GEN) | 5962R9662101TXC |
| HCTS4002 (GEN) | 5962R9576001VCC | 4010-10 (GEN) | 5962-9230501MXC | 4011BN (GEN) | 5962R9662104V9A |
| HCTS4002 (GEN) | 5962R9576001VXC | 4010-10 (GEN) | 5962-9230501MYC | 4011BN (GEN) | 5962R9662104VCC |
| 4003A-10 (GEN) | 5962-9471201MYC | 4010-10 (GEN) | 5962-9230501MZC | 4011BN (GEN) | 5962R9662104VXC |
| 4003A-10 (GEN) | 5962-9471201MZC | 40102B (GEN) | 5962R9660001V9A | CD4011BDMSR | 5962R9662101VCC |
| 4003A-10 (GEN) | 5962-9471201MXC | 40102B (GEN) | 5962R9660001VEC | CD4011BHSR | 5962R9662101V9A |
| 4003A-6 (GEN) | 5962-9471202MYC | 40102B (GEN) | 5962R9660001VXC | CD4011BKMSR | 5962R9662101VXC |
| 4003A-6 (GEN) | 5962-9471202MZC | 40103B (GEN) | 5962R9660002V9A | THS4011MFKB | 5962-9959301Q2A |
| 4003A-6 (GEN) | 5962-9471202MXC | 40103B (GEN) | 5962R9660002VEC | THS4011MJGB | 5962-9959301QPA |
| AT40KEL040KW1MQ | 5962-0325001QXA | 40103B (GEN) | 5962R9660002VXC | 4012B (GEN) | 5962R9662102V9A |
| AT40KEL040KW1SV | 5962-0325001VXA | 40104B (GEN) | 5962R9660101V9A | 4012B (GEN) | 5962R9662102VCC |
| AT40KEL040KZ1MQ | 5962-0325001QYA | 40104B (GEN) | 5962R9660101VEC | 4012B (GEN) | 5962R9662102VXC |
| AT40KEL040KZ1SV | 5962-0325001VYA | 40104B (GEN) | 5962R9660101VXC | 4012BN (GEN) | 5962R9662105V9A |
| 4005-10 (GEN) | 5962-9225201MXC | XC4010E-4PG191B | 5962-9752301QXC | 4012BN (GEN) | 5962R9662105VCC |
| 4005-10 (GEN) | 5962-9225201MYC | XC4010E-4CB196B | 5962-9752301QYC | 4012BN (GEN) | 5962R9662105VXC |
| 4005-10 (GEN) | 5962-9225201MZC | XC4010E-4CB196B | 5962-9752301QZC | 4013B (GEN) | 7901101CA |
| XC4005E-4PG156B | 5962-9752201QXC | 40105B (GEN) | 5962R9660201V9A | 4013B (GEN) | 7901102CA |
| XC4005E-4B164B | 5962-9752201QYC | 40105BN (GEN) | 5962R9660202V9A | 4013B (GEN) | 7901102DA |
| XC4005E-4B164B | 5962-9752201QZC | 40105BN (GEN) | 5962R9660202VEC | 4013B (GEN) | 7901103CA |
| XC4005-5CB164B | 5962-9225203MYC | 40105BN (GEN) | 5962R9660202VXC | 4013BN (GEN) | 5962R9662202V9A |
| XC4005-5CB164B | 5962-9225203MZC | CD40105BDMSR | 5962R9660201VEC | 4013BN (GEN) | 5962R9662202VCC |
| XC4005-5PG156B | 5962-9225203MXC | CD40105BKMSR | 5962R9660201VXC | CD4013BDMSR | 5962R9662201VCC |
| 4005-6 (GEN) | 5962-9225202MXC | XC4010-5PG191B | 5962-9230503MXC | CD4013BHSR | 5962R9662201V9A |
| 4005-6 (GEN) | 5962-9225202MYC | XC4010-5CB196B | 5962-9230503MYC | CD4013BKMSR | 5962R9662201VXC |
| 4005-6 (GEN) | 5962-9225202MZC | XC4010-5CB196B | 5962-9230503MZC | CD4013BKNSR | 5962R9662202VXC |
| 4006B (GEN) | 5962R9661701V9A | 4010-6 (GEN) | 5962-9230502MXC | CD4013BMW/883 | 7901101DA |
| 4006B (GEN) | 5962R9661701VCC | 4010-6 (GEN) | 5962-9230502MYC | 4013-10 (GEN) | 5962-9473001MXC |
| 4006B (GEN) | 5962R9661701VXC | 4010-6 (GEN) | 5962-9230502MZC | 4013-10 (GEN) | 5962-9473001MYC |
| 4006BN (GEN) | 5962R9661702V9A | 40106B (GEN) | 5962R9660301V9A | 4013-10 (GEN) | 5962-9473001MZC |
| 4006BN (GEN) | 5962R9661702VCC | 40106BN (GEN) | 5962R9660302V9A | XQ4013XL-3CB228B | 5962-9851301QYC |
| 4006BN (GEN) | 5962R9661702VXC | 40106BN (GEN) | 5962R9660302VCC | XQ4013XL-3CB228B | 5962-9851301QZC |
| 4007UB (GEN) | 5962R9661801V9A | CD40106BDMSR | 5962R9660301VCC | XQ4013XL-3PG223B | 5962-9851301QXC |
| 4007UB (GEN) | 5962R9661801VCC | CD40106BKMSR | 5962R9660301VXC | XQ4013XL-3PQ240N | 5962-9851301NTB |
| 4007UB (GEN) | 5962R9661801VXC | CD40106BKNSR | 5962R9660302VXC | XC4013E-4PG223B | 5962-9752401QXC |
| 4008B (GEN) | 5962R9661901V9A | CD40106BMJ/883 | 5962-8550101CA | XC4013E-4CB228B | 5962-9752401QYC |
| 4008B (GEN) | 5962R9661901VEC | 40107B (GEN) | 5962R9664401V9A | XC4013E-4CB228B | 5962-9752401QZC |
| 4008BN (GEN) | 5962R9661902V9A | 40107B (GEN) | 5962R9664401VCC | XC4013-6PG223B | 5962-9473002MXC |
| 4008BN (GEN) | 5962R9661902VEC | 40107BN (GEN) | 5962R9664402V9A | XC4013-6CB228B | 5962-9473002MYC |
| 4008BN (GEN) | 5962R9661902VXC | 40107BN (GEN) | 5962R9664402VCC | XC4013-6CB228B | 5962-9473002MZC |
| CD4008BKMSR | 5962R9661901VXC | 40107BN (GEN) | 5962R9664402VXC | 4014B (GEN) | 5962R9662301V9A |
| 4009UB (GEN) | 5962R9662001V9A | CD40107BKMSR | 5962R9664401VXC | 4014B (GEN) | 5962R9662301VEC |
| 4009UB (GEN) | 5962R9662001VEC | 40108B (GEN) | 5962R9668201V9A | 4014B (GEN) | 5962R9662301VXC |
| 4009UB (GEN) | 5962R9662001VXC | 40108B (GEN) | 5962R9668201VJC | 4014BN (GEN) | 5962R9662303V9A |
| CLC401A (GEN) | 5962-89973012A | 40108B (GEN) | 5962R9668201VXC | 4014BN (GEN) | 5962R9662303VEC |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

| Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN |
|---|---|---|---|---|---|
| 4014BN (GEN) | 5962R9662303VXC | 4018BN (GEN) | 5962R9662602V9A | CD4023BDMSR | 5962R9662103VCC |
| 4014BN (GEN) | 5962R9668103V9A | 4018BN (GEN) | 5962R9662602VEC | CD4023BHSR | 5962R9662103V9A |
| 40147B (GEN) | 5962R9660401V9A | 4018BN (GEN) | 5962R9662602VXC | CD4023BKMSR | 5962R9662103VXC |
| 40147B (GEN) | 5962R9660401VEC | 40181B (GEN) | 5962R9668301VJC | CD4023BMJ/883B | 7901301CA |
| 40147B (GEN) | 5962R9660401VXC | 40181B (GEN) | 5962R9668301VXC | 4024B (GEN) | 5962R9662803V9A |
| 4015B (GEN) | 5962R9662401TEC | 40182B (GEN) | 5962R9660701V9A | 4024BN (GEN) | 5962R9662804V9A |
| 4015B (GEN) | 5962R9662401TXC | 40182B (GEN) | 5962R9660701VEC | 4024BN (GEN) | 5962R9662804VCC |
| 4015B (GEN) | 5962R9662401V9A | 40182B (GEN) | 5962R9660701VXC | 4024BN (GEN) | 5962R9662804VXC |
| 4015BN (GEN) | 5962R9662402V9A | 4019B (GEN) | 5962R9662701V9A | CD4024BDMSR | 5962R9662803VCC |
| 4015BN (GEN) | 5962R9662402VEC | 4019B (GEN) | 5962R9662701VEC | CD4024BKMSR | 5962R9662803VXC |
| 4015BN (GEN) | 5962R9668104V9A | 4019B (GEN) | 5962R9662701VXC | 4025B (GEN) | 5962R9582604V9A |
| CD4015BDMSR | 5962R9662401VEC | 4019BN (GEN) | 5962R9662702V9A | 4025BN (GEN) | 5962R9582607VCC |
| CD4015BKMSR | 5962R9662401VXC | 4019BN (GEN) | 5962R9662702VEC | 4025BN (GEN) | 5962R9582607VXC |
| CD4015BKNSR | 5962R9662402VXC | 4019BN (GEN) | 5962R9662702VXC | CD4025BDMSR | 5962R9582604VCC |
| 4016B (GEN) | 5962R9670101V9A | 40192B (GEN) | 5962R9660801V9A | CD4025BKMSR | 5962R9582604VXC |
| 4016B (GEN) | 5962R9670101VCC | 40192B (GEN) | 5962R9660801VEC | XC4025E-4B228B | 5962-9752501QYC |
| 4016B (GEN) | 5962R9670101VXC | 40192B (GEN) | 5962R9660801VXC | XC4025E-4B228B | 5962-9752501QZC |
| CD4016BF3A | 5962-9064001CA | CD40193BDMSR | 5962R9660802VEC | XC4025E-4PG299 | 5962-9752501QXC |
| CD40160BDMSR | 5962R9667601VEC | CD40193BKMSR | 5962R9660802VXC | 40257B (GEN) | 5962R9667701V9A |
| CD40160BHSR | 5962R9667601V9A | CD40193BHSR | 5962R9660802V9A | 40257B (GEN) | 5962R9667701VEC |
| CD40160BKMSR | 5962R9667601VXC | 40194B (GEN) | 5962R9660102V9A | 40257B (GEN) | 5962R9667701VXC |
| 40161B (GEN) | 5962R9667602V9A | 40194B (GEN) | 5962R9660102VEC | 40257BN (GEN) | 5962R9667702V9A |
| 40161B (GEN) | 5962R9667602VEC | 40194B (GEN) | 5962R9660102VXC | 40257BN (GEN) | 5962R9667702VEC |
| 40161B (GEN) | 5962R9667602VXC | CLC402 (GEN) | 5962F9203301MPA | 40257BN (GEN) | 5962R9667702VXC |
| 40161B (GEN) | 5962R9667605V9A | CLC402A (GEN) | 5962-9203301M2A | 4027B (GEN) | 5962R9662901V9A |
| 40161B (GEN) | 5962R9667605VEC | CLC402A (GEN) | 5962-9203301MPA | 4027B (GEN) | 5962R9662901VEC |
| 40161B (GEN) | 5962R9667605VXC | 4020BN (GEN) | 5962R9662802V9A | 4027BN (GEN) | 5962R9662902V9A |
| 40162B (GEN) | 5962R9667603V9A | 4020BN (GEN) | 5962R9662802VEC | 4027BN (GEN) | 5962R9662902VEC |
| 40162B (GEN) | 5962R9667603VEC | CD4020BDMSR | 5962R9662801VEC | 4027BN (GEN) | 5962R9662902VXC |
| 40162B (GEN) | 5962R9667603VXC | CD4020BHSR | 5962R9662801V9A | CD4027BKMSR | 5962R9662901VXC |
| 40163B (GEN) | 5962R9667604V9A | CD4020BKMSR | 5962R9662801VYC | 4028B (GEN) | 5962R9663001V9A |
| 40163B (GEN) | 5962R9667604VEC | CD4020BKNSR | 5962R9662802VYC | 4028B (GEN) | 5962R9663001VEC |
| 40163B (GEN) | 5962R9667604VXC | 40208B (GEN) | 5962R9668401V9A | 4028BN (GEN) | 5962R9663002V9A |
| 4017B (GEN) | 5962R9662501V9A | CD40208B (GEN) | 5962R9668401VLC | 4028BN (GEN) | 5962R9663002VEC |
| 4017B (GEN) | 5962R9662501VEC | CD40208B (GEN) | 5962R9668401VXC | 4028BN (GEN) | 5962R9663002VXC |
| 4017B (GEN) | 5962R9662501VXC | 4021B (GEN) | 5962R9662302V9A | CD4028BKMSR | 5962R9663001VXC |
| 4017BN (GEN) | 5962R9662503V9A | 4021B (GEN) | 7901201EA | XQ4028EX-4BG352N | 5962-9850901NUA |
| 4017BN (GEN) | 5962R9662503VEC | 4021B (GEN) | 7901201FA | XQ4028EX-4CB228B | 5962-9850901QYC |
| 4017BN (GEN) | 5962R9662503VXC | 4021BN (GEN) | 5962R9662304V9A | XQ4028EX-4CB228B | 5962-9850901QZC |
| 40174B (GEN) | 5962R9660501V9A | 4021BN (GEN) | 5962R9662304VEC | XQ4028EX-4HQ240N | 5962-9850901NTB |
| 40174B (GEN) | 8202201EA | 4021BN (GEN) | 5962R9662304VXC | XQ4028EX-4PG299B | 5962-9850901QXC |
| 40174B (GEN) | 8202201FA | CD4021BDMSR | 5962R9662302VEC | 4029B (GEN) | 8101601EA |
| 40174BN (GEN) | 5962R9660502V9A | CD4021BKMSR | 5962R9662302VXC | 4029B (GEN) | 8101601FA |
| 40174BN (GEN) | 5962R9660502VEC | 4022B (GEN) | 5962R9662502V9A | 4029BN (GEN) | 5962R9562102VEC |
| 40174BN (GEN) | 5962R9660502VXC | 4022B (GEN) | 5962R9662502VEC | 4029BN (GEN) | 5962R9562102VXC |
| CD40174BDMSR | 5962R9660501VEC | 4022B (GEN) | 5962R9662502VXC | CD4029BDMSR | 5962R9562101VEC |
| CD40174BKMSR | 5962R9660501VXC | 4022BN (GEN) | 5962R9662504V9A | CD4029BF3A | 8101602EA |
| 40175B (GEN) | 5962R9660601V9A | 4022BN (GEN) | 5962R9662504VEC | CD4029BHNSR | 5962R9562102V9A |
| 40175B (GEN) | 5962R9660601VEC | 4022BN (GEN) | 5962R9662504VXC | CD4029BHSR | 5962R9562101V9A |
| 40175B (GEN) | 5962R9660601VXC | 4023B (GEN) | 7901301DA | CD4029BKMSR | 5962R9562101VXC |
| 4018B (GEN) | 5962R9662601V9A | 4023BN (GEN) | 5962R9662106V9A | DG403AK/883 | 5962-8976301EA |
| 4018B (GEN) | 5962R9662601VEC | 4023BN (GEN) | 5962R9662106VCC | DG403AK/883 | 5962-8976301MEA |
| 4018B (GEN) | 5962R9662601VXC | 4023BN (GEN) | 5962R9662106VXC | DG403AK/883 | 5962-8976301MEA |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART II, Listed By Generic PIN

| Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN |
|---|---|---|---|---|---|
| DG403AK/883B | 5962-8976301MEA | CD4041UBDMSR | 5962R9663201VCC | DG405AK/883B | 5962-8996101EA |
| DG403AZ/883 | 5962-89763012A | CD4041UBHSR | 5962R9663201V9A | DG405AZ/883 | 5962-89961012A |
| DG403AZ/883 | 5962-8976301M2A | CD4041UBKMSR | 5962R9663201VXC | DG405AZ/883B | 5962-89961012C |
| DG403AZ/883B | 5962-8976301M2C | AS404F10 | 5962-8850310XA | 4050B (GEN) | 5962R9663701V9A |
| 4030B (GEN) | 5962R9664601V9A | 4042B (GEN) | 5962R9663301V9A | 4050B (GEN) | 5962R9663701VXC |
| 4030B (GEN) | 5962R9664601VXC | 4042B (GEN) | 8101901EA | 4050BN (GEN) | 5962R9663702V9A |
| 4030BN (GEN) | 5962R9664602V9A | 4042BN (GEN) | 5962R9663302V9A | 4050BN (GEN) | 5962R9663702VEC |
| 4030BN (GEN) | 5962R9664602VCC | 4042BN (GEN) | 5962R9663302VEC | 4050BN (GEN) | 5962R9663702VXC |
| 4030BN (GEN) | 5962R9664602VXC | 4042BN (GEN) | 5962R9663302VXC | CD4050BDMSR | 5962R9663701VEC |
| CD4030BDMSR | 5962R9664601VCC | CD4042BDMSR | 5962R9663301VEC | 4051B (GEN) | 5962R9665101V9A |
| 4031B (GEN) | 5962R9664701V9A | CD4042BKMSR | 5962R9663301VXC | 4051BN (GEN) | 5962R9665104V9A |
| 4031B (GEN) | 5962R9664701VEC | 4043B (GEN) | 5962R9663401V9A | 4051BN (GEN) | 5962R9665104VEC |
| 4031B (GEN) | 5962R9664701VXC | 4043BN (GEN) | 5962R9663403V9A | CD4051BDMSR | 5962R9665101VEC |
| 4031BN (GEN) | 5962R9664702V9A | 4043BN (GEN) | 5962R9663403VEC | CD4051BKMSR | 5962R9665101VXC |
| 4031BN (GEN) | 5962R9664702VEC | 4043BN (GEN) | 5962R9663403VXC | CD4051BKNSR | 5962R9665104VXC |
| 4031BN (GEN) | 5962R9664702VXC | CD4043BDMSR | 5962R9663401VEC | THS4051MFKB | 5962-9959901Q2A |
| THS4031MFKB | 5962-9959501Q2A | CD4043BKMSR | 5962R9663401VXC | THS4051MJGB | 5962-9959901QPA |
| THS4031MJGB | 5962-9959501QPA | 4044B (GEN) | 5962R9663402V9A | 4052B (GEN) | 7901501FA |
| 4033B (GEN) | 5962R9664801V9A | 4044B (GEN) | 5962R9663402VEC | 4052BN (GEN) | 5962R9665105V9A |
| 4033B (GEN) | 5962R9664801VEC | 4044B (GEN) | 5962R9663402VXC | 4052BN (GEN) | 5962R9665105VEC |
| 4033B (GEN) | 5962R9664801VXC | 4044B (GEN) | 7702601EA | 4052BN (GEN) | 5962R9665105VXC |
| 4034B (GEN) | 5962R9667801V9A | 4044B (GEN) | 7702601FA | CD4052BDMSR | 5962R9665102VEC |
| 4034B (GEN) | 5962R9667801VJC | 4046B (GEN) | 5962R9666401V9A | CD4052BF3A | 7901502EA |
| 4034B (GEN) | 5962R9667801VXC | 4046B (GEN) | 5962R9666401VXC | CD4052BHSR | 5962R9665102V9A |
| 4034BN (GEN) | 5962R9667802VJA | 4046BN (GEN) | 5962R9666402V9A | CD4052BKMSR | 5962R9665102VXC |
| 4034BN (GEN) | 5962R9667802VXA | 4046BN (GEN) | 5962R9666402VEC | CD4052BMJ/883 | 7901501EA |
| 4035B (GEN) | 5962R9664901V9A | 4046BN (GEN) | 5962R9666402VXC | 4053B (GEN) | 8101801FA |
| 4035B (GEN) | 5962R9664901VEC | CD4046BDMSR | 5962R9666401VEC | 4053B (GEN) | 8101802EA |
| 4035B (GEN) | 5962R9664901VXC | CD4046BF3A | 5962-9466401MEA | 4053B (GEN) | 8101803EA |
| 4035B (GEN) | 8101701FA | 4047B (GEN) | 5962R9663501V9A | 4053B (GEN) | 8101803FA |
| 4035BN (GEN) | 5962R9664902V9A | 4047B (GEN) | 5962R9663501VCC | 4053BN (GEN) | 5962R9665106V9A |
| 4035BN (GEN) | 5962R9664902VEC | 4047B (GEN) | 8102001DA | 4053BN (GEN) | 5962R9665106VEC |
| 4035BN (GEN) | 5962R9664902VXC | 4047B (GEN) | 8102002CA | 4053BN (GEN) | 5962R9665106VXC |
| CD4035BF3A | 8101701EA | 4047B (GEN) | 8102002DA | CD4053BDMSR | 5962R9665103VEC |
| XQ4036XL-3BCB228 | 5962-9851001QYC | 4047BN (GEN) | 5962R9663502V9A | CD4053BF3A | 8101801EA |
| XQ4036XL-3BCB228 | 5962-9851001QZC | 4047BN (GEN) | 5962R9663502VCC | CD4053BHSR | 5962R9665103V9A |
| XQ4036XL-3BPG411 | 5962-9851001QXC | CD4047BKMSR | 5962R9663501VXC | CD4053BKMSR | 5962R9665103VXC |
| XQ4036XL-3NBG352 | 5962-9851001NUA | CD4047BKNSR | 5962R9663502VXC | CLC406 (GEN) | 5962-9200401M2A |
| XQ4036XL-3NHQ240 | 5962-9851001NTB | CD4047BF3A | 8102001CA | CLC406AJ-QML | 5962-9200401MPA |
| CLC404AJ-QML | 5962-9099401MPA | 4048B (GEN) | 5962R9665001V9A | DG406AK/883 | 5962-9562301QXA |
| CMP404AY | 5962-8990401CA | 4048B (GEN) | 5962R9665001VEC | DG406AP/883 | 5962-9562301QXA |
| CMP404B (GEN) | 5962-8990402CA | 4048B (GEN) | 5962R9665001VXC | DG406AZ/883 | 5962-9562301Q3A |
| 4040B (GEN) | 5962R9662805V9A | 4049UB (GEN) | 5962R9663601TEC | 4060A (GEN) | 7703101EA |
| 4040B (GEN) | 7705801FA | 4049UB (GEN) | 5962R9663601TXC | 4060A (GEN) | 7703101FA |
| 4040BN (GEN) | 5962R9662806V9A | 4049UB (GEN) | 5962R9663602V9A | 4060B (GEN) | 5962R9660901V9A |
| 4040BN (GEN) | 5962R9662806VEC | 4049UB (GEN) | 5962R9663602VEC | CD4060BDMSR | 5962R9660901VEC |
| CD4040BDMSR | 5962R9662805VEC | 4049UB (GEN) | 7901401EA | CD4060BKMSR | 5962R9660901VXC |
| CD4040BKMSR | 5962R9662805VYC | 4049UB (GEN) | 7901401FA | THS4061MFKB | 5962-9960101Q2A |
| CD4040BKNSR | 5962R9662806VYC | CD4049UBDMSR | 5962R9663601VEC | THS4061MJGB | 5962-9960101QPA |
| CD4040BMJ/883 | 7705801EA | CD4049UBHSR | 5962R9663601V9A | XQ4062XL-3BCB228 | 5962-9851101QYC |
| 4041UBN (GEN) | 5962R9663202V9A | CD4049UBKMSR | 5962R9663601VXC | XQ4062XL-3BCB228 | 5962-9851101QZC |
| 4041UBN (GEN) | 5962R9663202VCC | CD4049UBKNSR | 5962R9663602VXC | XQ4062XL-3BPG475 | 5962-9851101QXC |
| 4041UBN (GEN) | 5962R9663202VXC | DG405AK/883 | 5962-8996101EA | XQ4062XL-3NBG432 | 5962-9851101NUA |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

| Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN |
|---|---|---|---|---|---|
| XQ4062XL-3NHQ240 | 5962-9851101NTB | 4072B (GEN) | 7706001CA | HS0-4080ARH-Q | 5962F9961701V9A |
| 4063B (GEN) | 5962R9675701V9A | 4072B (GEN) | 7706001DA | HS9-4080ARH-8 | 5962F9961701QSC |
| 4063B (GEN) | 5962R9675701VEC | 4072BN (GEN) | 5962R9665404V9A | HS9-4080ARH-Q | 5962F9961701VSC |
| CD4063BKMSR | 5962R9675701VXC | 4072BN (GEN) | 5962R9665404VCC | HS9-4080ARH-T | 5962R9961701TSC |
| 4066B (GEN) | 5962R9665201V9A | 4072BN (GEN) | 5962R9665404VXC | 4081B (GEN) | 5962R9665502V9A |
| 4066BN (GEN) | 5962R9665202V9A | CD4072BF3A | 7706002CA | 4081B (GEN) | 7702401CA |
| 4066BN (GEN) | 5962R9665202VCC | 4073B (GEN) | 5962R9665501V9A | 4081B (GEN) | 7702401DA |
| 4066BN (GEN) | 5962R9665202VXC | 4073B (GEN) | 5962R9665501VCC | 4081BN (GEN) | 5962R9665505V9A |
| CD4066BDMSR | 5962R9665201VCC | 4073B (GEN) | 5962R9665501VXC | 4081BN (GEN) | 5962R9665505VCC |
| CD4066BKMSR | 5962R9665201VXC | 4073B (GEN) | 7705101CA | CD4081BDMSR | 5962R9665502VCC |
| 4067B (GEN) | 5962R9667901V9A | 4073B (GEN) | 7705101DA | CD4081BF3A | 7702402CA |
| 4067B (GEN) | 5962R9667901VLC | 4073BN (GEN) | 5962R9665504V9A | CD4081BKMSR | 5962R9665502VXC |
| 4067B (GEN) | 5962R9667901VXC | 4073BN (GEN) | 5962R9665504VCC | CD4081BKNSR | 5962R9665505VXC |
| MT4067-10 (GEN) | 5962-8767604VA | CD4073BF3A | 7705102CA | 4082B (GEN) | 5962R9665503V9A |
| MT4067-10 (GEN) | 5962-8767604XA | CD4073BKNSR | 5962R9665504VXC | 4082B (GEN) | 5962R9665503VCC |
| MT4067-12 (GEN) | 5962-8767601VA | 4075B (GEN) | 5962R9665405V9A | 4082B (GEN) | 5962R9665503VXC |
| MT4067-12 (GEN) | 5962-8767601XA | 4075B (GEN) | 5962R9665405VCC | 4082B (GEN) | 7705901CA |
| MT4067-15 (GEN) | 5962-8767602VA | 4075B (GEN) | 5962R9665405VXC | 4082B (GEN) | 7705901DA |
| MT4067-15 (GEN) | 5962-8767602XA | 4075BN (GEN) | 5962R9665406V9A | 4082BN (GEN) | 5962R9665506V9A |
| MT4067-20 (GEN) | 5962-8767603VA | 4075BN (GEN) | 5962R9665406VCC | 4082BN (GEN) | 5962R9665506VCC |
| MT4067-20 (GEN) | 5962-8767603XA | 4075BN (GEN) | 5962R9665406VXC | 4082BN (GEN) | 5962R9665506VXC |
| 4068B (GEN) | 5962R9661001V9A | 4076BN (GEN) | 5962R9665602V9A | CD4082BF3A | 7705902CA |
| 4068B (GEN) | 5962R9661001VCC | 4076BN (GEN) | 5962R9665602VEC | 4085B (GEN) | 5962R9663901VCC |
| 4068B (GEN) | 5962R9661001VXC | 4076BN (GEN) | 5962R9665602VXC | 4085B (GEN) | 5962R9663901VXC |
| 4068BN (GEN) | 5962R9661002V9A | CD4076BDMSR | 5962R9665601VEC | CD4085BMSR | 5962R9663901V9A |
| 4068BN (GEN) | 5962R9661002VCC | CD4076BHSR | 5962R9665601V9A | XQ4085XL-1CB228B | 5962-9957501QYC |
| 4068BN (GEN) | 5962R9661002VXC | CD4076BKMSR | 5962R9665601VXC | XQ4085XL-1CB228B | 5962-9957501QZC |
| 4069UB (GEN) | 5962R9665301V9A | 4077B (GEN) | 5962R9661102V9A | XQ4085XL-1NBG432 | 5962-9957501NUA |
| 4069UB (GEN) | 7702701CX | 4077BN (GEN) | 5962R9661104V9A | XQ4085XL-1NHQ240 | 5962-9957501NTB |
| 4069UB (GEN) | 7702701DX | 4077BN (GEN) | 5962R9661104VCC | 4086B (GEN) | 5962R9664001V9A |
| 4069UBN (GEN) | 5962R9665302V9A | 4077BN (GEN) | 5962R9661104VXC | 4086B (GEN) | 5962R9664001VCC |
| 4069UBN (GEN) | 5962R9665302VCC | CD4077BDMSR | 5962R9661102VCC | 4086B (GEN) | 5962R9664001VXC |
| 4069UBN (GEN) | 5962R9665302VXC | CD4077BKMSR | 5962R9661102VXC | 4089B (GEN) | 5962R9661201V9A |
| CD4069UBDMSR | 5962R9665301VCC | 4078B (GEN) | 5962R9663801V9A | 4089B (GEN) | 5962R9661201VEC |
| CD4069UBKMSR | 5962R9665301VXC | 4078B (GEN) | 5962R9663801VCC | 4089B (GEN) | 5962R9661201VXC |
| DG407AK/883 | 5962-9562302QXA | 4078B (GEN) | 7704401AA | ADG409TE/883B | 5962-9204204M2A |
| DG407AP/883 | 5962-9562302QXA | 4078B (GEN) | 7704401CA | ADG409TQ/883B | 5962-9204204MEA |
| DG407AZ/883 | 5962-9562302Q3A | 4078BN (GEN) | 5962R9663802V9A | CLC409AE-QML | 5962-9203401M2A |
| 4070B (GEN) | 5962R9661101V9A | 4078BN (GEN) | 5962R9663802VCC | CLC409AJ-QML | 5962-9203401MPA |
| 4070BN (GEN) | 5962R9661103V9A | 4078BN (GEN) | 5962R9663802VXC | DG409A (GEN) | 5962-9204202MFA |
| 4070BN (GEN) | 5962R9661103VCC | CD4078BF3A | 7704402CA | DG409AK/883 | 5962-9204202MEA |
| 4070BN (GEN) | 5962R9661103VXC | CD4078BKMSR | 5962R9663801VXC | DG409AK/883B | 5962-9204202MEA |
| CD4070BDMSR | 5962R9661101VCC | ADG408TE/883B | 5962-9204203M2A | DG409AL/883 | 5962-9204202MXA |
| CD4070BKMSR | 5962R9661101VXC | ADG408TQ/883B | 5962-9204203MEA | DG409AL/883 | 5962-9204202MXC |
| 4071B (GEN) | 5962R9665401V9A | DG408A (GEN) | 5962-9204201MFA | DG409AL/883B | 5962-9204202MXC |
| 4071BN (GEN) | 5962R9665402V9A | DG408AK/883 | 5962-9204201MEA | DG409AZ/883 | 5962-9204202M2A |
| 4071BN (GEN) | 5962R9665402VCC | DG408AK/883 | 5962-9204201MEA | DG409AZ/883B | 5962-9204202M2C |
| 4071BN (GEN) | 5962R9665402VXC | DG408AK/883B | 5962-9204201MEA | 4093BN (GEN) | 5962R9664102V9A |
| CD4071BDMSR | 5962R9665401VCC | DG408AL/883 | 5962-9204201MXA | 4093BN (GEN) | 5962R9664102VCC |
| CD4071BKMSR | 5962R9665401VXC | DG408AL/883 | 5962-9204201MXC | CD4093B (GEN) | 7704601DA |
| 4072B (GEN) | 5962R9665403V9A | DG408AL/883B | 5962-9204201MXC | CD4093BDMSR | 5962R9664101VCC |
| 4072B (GEN) | 5962R9665403VCC | DG408AZ/883 | 5962-9204201M2A | CD4093BF3A | 7704602CA |
| 4072B (GEN) | 5962R9665403VXC | DG408AZ/883B | 5962-9204201M2C | CD4093BHSR | 5962R9664101V9A |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

| Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN |
|---|---|---|---|---|---|
| CD4093BKMSR | 5962R9664101VXC | CLC411AJ-QML | 5962-9456601MPA | P4C1256-25L32MB | 5962-8866206YA |
| CD4093BKNSR | 5962R9664102VXC | DG411 (GEN) | 5962-9073101MFA | P4C1256-35CMB | 5962-8866205NC |
| CD4093BMJ/883 | 7704601CA | DG411AK/883 | 5962-9073101MEA | P4C1256-35DMB | 5962-8866205NA |
| 4094B (GEN) | 7702501FA | DG411AK/883 | 5962-9073101MEA | P4C1256-35DWMB | 5962-8866205XA |
| 4094B (GEN) | 7702502EA | DG411AK/883B | 5962-9073101MEA | P4C1256-35FMB | 5962-8866205MA |
| 4094BN (GEN) | 5962R9664202V9A | DG411AL/883B | 5962-9073101MXC | P4C1256-35L28MB | 5962-8866205UA |
| 4094BN (GEN) | 5962R9664202VEC | DG411AZ/883 | 5962-9073101M2A | P4C1256-35L32MB | 5962-8866205YA |
| 4094BN (GEN) | 5962R9664202VXC | DG411AZ/883 | 5962-9073102M2A | P4C1256-45CMB | 5962-8866204NC |
| CD4094B (GEN) | 5962R9664201V9A | DG411AZ/883B | 5962-9073101M2C | P4C1256-45DMB | 5962-8866204NA |
| CD4094B (GEN) | 5962R9664201VEC | P4C116-35DMB | 8403614LA | P4C1256-45DWMB | 5962-8866204XA |
| CD4094B (GEN) | 5962R9664201VXC | P4C116-35FMB | 8403614KA | P4C1256-45FMB | 5962-8866204MA |
| CD4094BF3A | 7702501EA | P4C116-35L28MB | 84036143A | P4C1256-45L28MB | 5962-8866204UA |
| 4095B (GEN) | 5962R9661301V9A | P4C116-35LMB | 8403614YA | P4C1256-45L32MB | 5962-8866204YA |
| 4095B (GEN) | 5962R9661301VCC | P4C116-45DMB | 8403609LA | P4C1256-55CMB | 5962-8866203NC |
| 4095B (GEN) | 5962R9661301VXC | P4C116-45FMB | 8403609KA | P4C1256-55DMB | 5962-8866203NA |
| 4096B (GEN) | 5962R9661302V9A | P4C116-45L28MB | 84036093A | P4C1256-55DWMB | 5962-8866203XA |
| 4096B (GEN) | 5962R9661302VCC | P4C116-45LMB | 8403609YA | P4C1256-55FMB | 5962-8866203MA |
| 4096B (GEN) | 5962R9661302VXC | P4C116-55DMB | 8403611LA | P4C1256-55L28MB | 5962-8866203UA |
| 4097B (GEN) | 5962R9667902V9A | P4C116-55FMB | 8403611KA | P4C1256-55L32MB | 5962-8866203YA |
| 4097B (GEN) | 5962R9667902VLC | P4C116-55L28MB | 84036113A | P4C1256-70CMB | 5962-8866202NC |
| 4097B (GEN) | 5962R9667902VXC | P4C116-55LMB | 8403611YA | P4C1256-70DMB | 5962-8866202NA |
| 4098B (GEN) | 5962R9661401V9A | CLC412AE-QML | 5962-9471901M2A | P4C1256-70DWMB | 5962-8866202XA |
| 4098B (GEN) | 7705501EA | CLC412AJ-QML | 5962-9471901MPA | P4C1256-70FMB | 5962-8866202MA |
| 4098B (GEN) | 7705501FA | DG412 (GEN) | 5962-9073102MFA | P4C1256-70L28MB | 5962-8866202UA |
| 4098BN (GEN) | 5962R9661402V9A | DG412AK/883 | 5962-9073102MEA | P4C1256-70L32MB | 5962-8866202YA |
| 4098BN (GEN) | 5962R9661402VEC | DG412AK/883B | 5962-9073102MEA | DG413 (GEN) | 5962-9073103MFA |
| 4098BN (GEN) | 5962R9661402VXC | DG412AL/883B | 5962-9073102MXC | DG413AK/883 | 5962-9073103MEA |
| CD4098BDMSR | 5962R9661401VEC | DG412AZ/883 | 5962-9073103M2A | DG413AK/883B | 5962-9073103MEA |
| CD4098BKMSR | 5962R9661401VXC | DG412AZ/883B | 5962-9073102M2C | DG413AL/883B | 5962-9073103MXC |
| 4099B (GEN) | 5962R9661501V9A | LF412 (GEN) | 5962-9676001QGA | DG413AZ/883B | 5962-9073103M2C |
| CD4099BDMSR | 5962R9661501VEC | LF412 (GEN) | 5962-9676001QPA | CLC414A (GEN) | 5962-9169301M2A |
| CD4099BKMSR | 5962R9661501VXC | P4C1256-100CMB | 5962-8866201NC | CLC414A (GEN) | 5962-9169301MCA |
| CLC410AJ-QML | 5962-9060001PA | P4C1256-100DMB | 5962-8866201NA | P4C147-35DMB | 5962-8858703VA |
| MT4C1004JC-10 | 5962-9062202MTA | P4C1256-100DWMB | 5962-8866201XA | P4C147-35FMB | 5962-8858703XA |
| MT4C1004JCN-10 | 5962-9062202MVA | P4C1256-100FMB | 5962-8866201MA | P4C147-35LMB | 5962-8858703YA |
| MT4C1004JCZ-10 | 5962-9062202MNA | P4C1256-100L28MB | 5962-8866201UA | P4C148-35DMB | 5962-8751310VA |
| MT4C1004JEC-10 | 5962-9062202MYA | P4C1256-100L32MB | 5962-8866201YA | CLC415AE-QML | 5962-9305501M2A |
| MT4C1004JECN-10 | 5962-9062202MUA | P4C1256-15DMB | 5962-8866208NA | CLC415AJ-QML | 5962-9305501MCA |
| MT4C1004JF-10 | 5962-9062202MMA | P4C1256-15DWMB | 5962-8866208XA | P4C150-15DMB | 5962-8858806LA |
| MT4C1004JC-12 | 5962-9062201MTA | P4C1256-15FMB | 5962-8866208MA | P4C150-15FMB | 5962-8858806KA |
| MT4C1004JCN-12 | 5962-9062201MVA | P4C1256-15L28MB | 5962-8866208UA | P4C150-15FMB | 5962-8858807KA |
| MT4C1004JCZ-12 | 5962-9062201MNA | P4C1256-15L32MB | 5962-8866208YA | P4C150-15LMB | 5962-8858806XA |
| MT4C1004JEC-12 | 5962-9062201MYA | P4C1256-20CMB | 5962-8866207NC | P4C150-25DMB | 5962-8858805LA |
| MT4C1004JECN-12 | 5962-9062201MUA | P4C1256-20DMB | 5962-8866207NA | P4C150-25FMB | 5962-8858805KA |
| MT4C1004JF-12 | 5962-9062201MMA | P4C1256-20DWMB | 5962-8866207XA | P4C150-25LMB | 5962-8858805XA |
| MT4C1004JD22ADC3-6 | 5962-9688901Q9A | P4C1256-20FMB | 5962-8866207MA | P4C150-35DMB | 5962-8858804LA |
| MT4C1004JD22ADC3-7 | 5962-9688902Q9A | P4C1256-20L28MB | 5962-8866207UA | P4C150-35FMB | 5962-8858804KA |
| MT4C1004JC-8 | 5962-9062203MTA | P4C1256-20L32MB | 5962-8866207YA | P4C150-35LMB | 5962-8858804XA |
| MT4C1004JCN-8 | 5962-9062203MVA | P4C1256-25CMB | 5962-8866206NC | 416100-10 (GEN) | 5962-9473401MXA |
| MT4C1004JCZ-8 | 5962-9062203MMA | P4C1256-25DMB | 5962-8866206NA | 416100-10 (GEN) | 5962-9473401MYA |
| MT4C1004JEC-8 | 5962-9062203MYA | P4C1256-25DWMB | 5962-8866206XA | 416100-70 (GEN) | 5962-9473403MXA |
| MT4C1004JECN-8 | 5962-9062203MUA | P4C1256-25FMB | 5962-8866206MA | 416100-70 (GEN) | 5962-9473403MYA |
| MT4C1004JF-8 | 5962-9062203MNA | P4C1256-25L28MB | 5962-8866206UA | 416100-80 (GEN) | 5962-9473402MXA |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART II, Listed By Generic PIN

| Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN |
|---|---|---|---|---|---|
| 416100-80 (GEN) | 5962-9473402MYA | P4C164-15DWMB | 5962-8969106XA | P4C164L-25DWMB | 5962-3829455MXA |
| SMJ416160-70HKDM | 5962-9674302QXA | P4C164-15FMB | 5962-3829419MTA | P4C164L-25DWMB | 5962-8969101XA |
| SMJ416160-80HKDM | 5962-9674301QXA | P4C164-15FMB | 5962-8969106TA | P4C164L-25FMB | 5962-3829455MTA |
| P4C163L-25 (GEN) | 5962-8868303UA | P4C164-15FSMB | 5962-3829419MMA | P4C164L-25FMB | 5962-8969101TA |
| P4C163L-25 (GEN) | 5962-8868303XA | P4C164-15LSMB | 5962-3829419MUA | P4C164L-25FSMB | 5962-3829455MMA |
| P4C163L-25 (GEN) | 5962-8868303YA | P4C164L-15DMB | 5962-3829418MZA | P4C164L-25L32MB | 5962-3829455MYA |
| P4C163L-25 (GEN) | 5962-8868303ZA | P4C164L-15DWMB | 5962-3829418MXA | P4C164L-25LMB | 5962-3829428MUA |
| P4C163L-25CMB | 5962-8868306YA | P4C164L-15FSMB | 5962-3829418MMA | P4C164L-25LMB | 5962-3829466MUA |
| P4C163L-25DWMB | 5962-8868306XA | P4C164L-15L32MB | 5962-3829418MYA | P4C164L-25LMB | 5962-8969101UA |
| P4C163L-25FMB | 5962-8868306ZA | P4C164L-15L32MB | 5962-3829419MYA | P4C164L-25LSMB | 5962-3829455MUA |
| P4C163L-25LMB | 5962-8868306UA | P4C164L-15LMB | 5962-3829418MUA | P4C164-35DMB | 5962-3829454MZA |
| P4C163L-35 (GEN) | 5962-8868302UA | 4164-20 (GEN) | 8201007ZA | P4C164-35DWMB | 5962-3829413MXA |
| P4C163L-35 (GEN) | 5962-8868302XA | 4164-20JDS/BEA | 8201007EA | P4C164-35DWMB | 5962-3829454MXA |
| P4C163L-35 (GEN) | 5962-8868302YA | P4C164-20CMB | 5962-8969104ZA | P4C164-35DWMB | 5962-8552507XA |
| P4C163L-35 (GEN) | 5962-8868302ZA | P4C164-20DMB | 5962-3829458MZA | P4C164-35FMB | 5962-3829454MTA |
| P4C163L-35CMB | 5962-8868305YA | P4C164-20DWMB | 5962-3829417MXA | P4C164-35FSMB | 5962-3829454MMA |
| P4C163L-35DWMB | 5962-8868305XA | P4C164-20DWMB | 5962-3829458MXA | P4C164-35L32MB | 5962-3829454MYA |
| P4C163L-35FMB | 5962-8868305ZA | P4C164-20DWMB | 5962-8969104XA | P4C164-35LMB | 5962-3829427MUA |
| P4C163L-35LMB | 5962-8868305UA | P4C164-20FMB | 5962-3829458MTA | P4C164-35LMB | 5962-3829465MUA |
| P4C163L-45 (GEN) | 5962-8868301UA | P4C164-20FMB | 5962-8969104TA | P4C164-35LSMB | 5962-3829454MUA |
| P4C163L-45 (GEN) | 5962-8868301XA | P4C164-20FSMB | 5962-3829458MMA | P4C164L-35DMB | 5962-3829453MZA |
| P4C163L-45 (GEN) | 5962-8868301YA | P4C164-20L32MB | 5962-3829458MYA | P4C164L-35DWMB | 5962-3829412MXA |
| P4C163L-45 (GEN) | 5962-8868301ZA | P4C164-20LMB | 5962-3829430MUA | P4C164L-35DWMB | 5962-3829453MXA |
| P4C163L-45CMB | 5962-8868304YA | P4C164-20LMB | 5962-3829468MUA | P4C164L-35DWMB | 5962-8552508XA |
| P4C163L-45DWMB | 5962-8868304XA | P4C164-20LMB | 5962-8969104UA | P4C164L-35FMB | 5962-3829453MTA |
| P4C163L-45FMB | 5962-8868304ZA | P4C164-20LSMB | 5962-3829458MUA | P4C164L-35FSMB | 5962-3829453MMA |
| P4C163L-45LMB | 5962-8868304UA | P4C164L-20DMB | 5962-3829457MZA | P4C164L-35L32MB | 5962-3829453MYA |
| SMJ416400-10FNC | 5962-9231201MYA | P4C164L-20DWMB | 5962-3829416MXA | P4C164L-35LMB | 5962-3829426MUA |
| SMJ416400-10HKB | 5962-9231201MXA | P4C164L-20DWMB | 5962-3829457MXA | P4C164L-35LMB | 5962-3829464MUA |
| SMJ416400-10SVM | 5962-9231201MZA | P4C164L-20FMB | 5962-3829457MTA | P4C164L-35LSMB | 5962-3829453MUA |
| SMJ416400-70FNC | 5962-9231203MYA | P4C164L-20FSMB | 5962-3829457MMA | P4C164-45DMB | 5962-3829452MZA |
| SMJ416400-70HKB | 5962-9231203MXA | P4C164L-20L32MB | 5962-3829457MYA | P4C164-45DWMB | 5962-3829411MXA |
| SMJ416400-70SVM | 5962-9231203MZA | P4C164L-20LSMB | 5962-3829457MUA | P4C164-45DWMB | 5962-3829452MXA |
| SMJ416400-80FNC | 5962-9231202MYA | P4C164-25CMB | 5962-8969102ZA | P4C164-45DWMB | 5962-8552506XA |
| SMJ416400-80HKB | 5962-9231202MXA | P4C164-25DMB | 5962-3829456MZA | P4C164-45FMB | 5962-3829452MTA |
| SMJ416400-80SVM | 5962-9231202MZA | P4C164-25DWMB | 5962-3829415MXA | P4C164-45FSMB | 5962-3829452MMA |
| P4C164-100DWMB | 5962-8552503XA | P4C164-25DWMB | 5962-3829456MXA | P4C164-45L32MB | 5962-3829452MYA |
| P4C164L-100DWMB | 5962-8552512XA | P4C164-25DWMB | 5962-8969102XA | P4C164-45LMB | 5962-3829425MUA |
| 4164-12 (GEN) | 8201008ZA | P4C164-25FMB | 5962-3829414MTA | P4C164-45LMB | 5962-3829463MUA |
| 4164-12JDS/BEA | 8201008EA | P4C164-25FMB | 5962-3829415MTA | P4C164-45LSMB | 5962-3829452MUA |
| P4C164-12DMB | 5962-3829447MZA | P4C164-25FMB | 5962-3829456MTA | P4C164L-45DMB | 5962-3829451MZA |
| P4C164-12FSMB | 5962-3829447MMA | P4C164-25FMB | 5962-8969102TA | P4C164L-45DWMB | 5962-3829410MXA |
| P4C164-12LSMB | 5962-3829447MUA | P4C164-25FSMB | 5962-3829414MMA | P4C164L-45DWMB | 5962-3829434MXA |
| P4C164L-12DMB | 5962-3829446MZA | P4C164-25FSMB | 5962-3829415MMA | P4C164L-45DWMB | 5962-3829451MXA |
| P4C164L-12FSMB | 5962-3829446MMA | P4C164-25FSMB | 5962-3829456MMA | P4C164L-45DWMB | 5962-8552509XA |
| P4C164L-12LSMB | 5962-3829446MUA | P4C164-25L32MB | 5962-3829456MYA | P4C164L-45FMB | 5962-3829451MTA |
| P4C164-120DWMB | 5962-8552502XA | P4C164-25LMB | 5962-3829429MUA | P4C164L-45FSMB | 5962-3829451MMA |
| P4C164L-120DWMB | 5962-8552513XA | P4C164-25LMB | 5962-3829467MUA | P4C164L-45L32MB | 5962-3829451MYA |
| 4164-15 (GEN) | 8201006ZA | P4C164-25LMB | 5962-8969102UA | P4C164L-45LMB | 5962-3829424MUA |
| 4164-15JDS/BEA | 8201006EA | P4C164-25LSMB | 5962-3829456MUA | P4C164L-45LMB | 5962-3829462MUA |
| P4C164-15CMB | 5962-8969106ZA | P4C164L-25CMB | 5962-8969101ZA | P4C164L-45LSMB | 5962-3829451MUA |
| P4C164-15DMB | 5962-3829419MZA | P4C164L-25DMB | 5962-3829455MZA | P4C164-55DMB | 5962-3829409MZA |
| P4C164-15DWMB | 5962-3829419MXA | P4C164L-25DWMB | 5962-3829414MXA | P4C164-55DMB | 5962-3829450MZA |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART II, Listed By Generic PIN

| Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN |
|---|---|---|---|---|---|
| P4C164-55DWMB | 5962-3829409MXA | P4C168-45FMB | 5962-8670505YA | P4C187L-20CMB | 5962-8969604XA |
| P4C164-55DWMB | 5962-3829450MXA | P4C168-45FSMB | 5962-8670513ZA | P4C187L-20LMB | 5962-8969604ZA |
| P4C164-55FMB | 5962-3829450MTA | P4C168-45LMB | 5962-8670505UA | P4C187-25CMB | 5962-8969607XA |
| P4C164-55L32MB | 5962-3829450MYA | P4C168-45LMB | 5962-8670505XA | P4C187-25LMB | 5962-8969607ZA |
| P4C164-55LMB | 5962-3829423MUA | P4C168-45LMB | 5962-8670513UA | P4C187L-25CMB | 5962-8969602XA |
| P4C164-55LMB | 5962-3829461MUA | P4C168-45LMB | 5962-8670513XA | P4C187L-25LMB | 5962-8969602ZA |
| P4C164-55LSMB | 5962-3829450MUA | P4C168L-45DMB | 5962-8670506RA | P4C188-15CMB | 5962-8969206XA |
| P4C164L-55DMB | 5962-3829449MZA | P4C168L-45FMB | 5962-8670506YA | P4C188-15DMB | 5962-8969206YA |
| P4C164L-55DWMB | 5962-3829408MXA | P4C168L-45LMB | 5962-8670506UA | P4C188-15FMB | 5962-8969206KA |
| P4C164L-55DWMB | 5962-3829433MXA | P4C168L-45LMB | 5962-8670506XA | P4C188-15LMB | 5962-8969206ZA |
| P4C164L-55DWMB | 5962-3829449MXA | P4C168-55DMB | 5962-8670507RA | P4C188L-15CMB | 5962-8969205XA |
| P4C164L-55DWMB | 5962-8552510XA | P4C168-55DMB | 5962-8670514RA | P4C188L-15DMB | 5962-8969205YA |
| P4C164L-55FMB | 5962-3829449MTA | P4C168-55FMB | 5962-8670507YA | P4C188L-15FMB | 5962-8969205KA |
| P4C164L-55FSMB | 5962-3829449MMA | P4C168-55FSMB | 5962-8670514ZA | P4C188L-15LMB | 5962-8969205ZA |
| P4C164L-55L32MB | 5962-3829449MYA | P4C168-55LMB | 5962-8670507UA | P4C188-20CMB | 5962-8969204XA |
| P4C164L-55LMB | 5962-3829422MUA | P4C168-55LMB | 5962-8670507XA | P4C188-20DMB | 5962-8969204YA |
| P4C164L-55LMB | 5962-3829460MUA | P4C168-55LMB | 5962-8670514UA | P4C188-20FMB | 5962-8969204KA |
| P4C164L-55LSMB | 5962-3829449MUA | P4C168-55LMB | 5962-8670514XA | P4C188-20LMB | 5962-8969204ZA |
| P4C164-70DMB | 5962-3829448MZA | P4C168L-55DMB | 5962-8670508RA | P4C188L-20CMB | 5962-8969203XA |
| P4C164-70DWMB | 5962-3829407MXA | P4C168L-55FMB | 5962-8670508YA | P4C188L-20DMB | 5962-8969203YA |
| P4C164-70DWMB | 5962-3829448MXA | P4C168L-55LMB | 5962-8670508UA | P4C188L-20FMB | 5962-8969203KA |
| P4C164-70DWMB | 5962-8552504XA | P4C168L-55LMB | 5962-8670508XA | P4C188L-20LMB | 5962-8969203ZA |
| P4C164-70FSMB | 5962-3829448MMA | P4C168-70DMB | 5962-8670509RA | P4C188-25CMB | 5962-8969202XA |
| P4C164-70L32MB | 5962-3829448MYA | P4C168-70DMB | 5962-8670515RA | P4C188-25DMB | 5962-8969202YA |
| P4C164-70LMB | 5962-3829421MUA | P4C168-70FMB | 5962-8670509YA | P4C188-25FMB | 5962-8969202KA |
| P4C164-70LMB | 5962-3829459MUA | P4C168-70FSMB | 5962-8670515ZA | P4C188-25LMB | 5962-8969202ZA |
| P4C164-70LSMB | 5962-3829448MUA | P4C168-70LMB | 5962-8670509XA | P4C188L-25CMB | 5962-8969201XA |
| P4C164L-70DWMB | 5962-8552511XA | P4C168-70LMB | 5962-8670515UA | P4C188L-25DMB | 5962-8969201YA |
| 4167 (GEN) | 8200701RA | P4C168-70LMB | 5962-8670515XA | P4C188L-25FMB | 5962-8969201KA |
| P4C167-45L20MB | 5962-0152901MYA | P4C168L-70DMB | 5962-8670510RA | P4C188L-25LMB | 5962-8969201ZA |
| P4C168-25DMB | 5962-8670501RA | P4C168L-70FMB | 5962-8670510YA | P4C188-35CMB | 5962-8685924TA |
| P4C168-25DMB | 5962-8670511RA | P4C168L-70LMB | 5962-8670510UA | P4C188-35LMB | 5962-8685924ZA |
| P4C168-25FSMB | 5962-8670511ZA | P4C168L-70LMB | 5962-8670510XA | P4C188L-35CMB | 5962-8685923TA |
| P4C168-25LMB | 5962-8670501UA | DG417 (GEN) | 5962-9073701MHA | P4C188L-35LMB | 5962-8685923ZA |
| P4C168-25LMB | 5962-8670501XA | DG417AK/883 | 5962-9073701MPA | P4C188-45 (GEN) | 5962-8685922ZA |
| P4C168-25LMB | 5962-8670511UA | DG417AK/883B | 5962-9073701MPA | P4C188L-45 (GEN) | 5962-8685921ZA |
| P4C168-25LMB | 5962-8670511XA | DG417AL/883B | 5962-9073701MXC | P4C188-55 (GEN) | 5962-8685920ZA |
| P4C168L-25DMB | 5962-8670502RA | DG418 (GEN) | 5962-9073702MHA | P4C188L-55 (GEN) | 5962-8685919ZA |
| P4C168L-25LMB | 5962-8670502UA | DG418AK/883 | 5962-9073702MPA | DG419 (GEN) | 5962-9073703MHA |
| P4C168L-25LMB | 5962-8670502XA | DG418AK/883B | 5962-9073702MPA | DG419AK/883 | 5962-9073703MPA |
| P4C168-35DMB | 5962-8670503RA | DG418AL/883B | 5962-9073702MXC | DG419AK/883B | 5962-9073703MPA |
| P4C168-35DMB | 5962-8670512RA | SMJ418160-70HKDM | 5962-9674304QXA | DG419AL/883B | 5962-9073703MXC |
| P4C168-35FMB | 5962-8670503YA | SMJ418160-80HKDM | 5962-9674303QXA | RM4194DC | 7705401CA |
| P4C168-35FSMB | 5962-8670512ZA | P4C187-12CMB | 5962-8969609XA | RM4194DC | 7705401CA |
| P4C168-35LMB | 5962-8670503UA | P4C187-12LMB | 5962-8969609ZA | RM4194DC | 7705401RA |
| P4C168-35LMB | 5962-8670503XA | P4C187L-12CMB | 5962-8969610XA | P4C198-15DMB | 5962-8989206LA |
| P4C168-35LMB | 5962-8670512XA | P4C187L-12LMB | 5962-8969610ZA | P4C198-15FMB | 5962-8989206KA |
| P4C168L-35DMB | 5962-8670504RA | P4C187-15CMB | 5962-8969605XA | P4C198-15L1MB | 5962-8989206YA |
| P4C168L-35FMB | 5962-8670504YA | P4C187-15LMB | 5962-8969605ZA | P4C198-15LMB | 5962-8989206XA |
| P4C168L-35LMB | 5962-8670504UA | P4C187L-15CMB | 5962-8969606XA | P4C198L-15DMB | 5962-8989205LA |
| P4C168L-35LMB | 5962-8670504XA | P4C187L-15LMB | 5962-8969606ZA | P4C198L-15FMB | 5962-8989205KA |
| P4C168-45DMB | 5962-8670505RA | P4C187-20CMB | 5962-8969608XA | P4C198L-15L1MB | 5962-8989205YA |
| P4C168-45DMB | 5962-8670513RA | P4C187-20LMB | 5962-8969608ZA | P4C198L-15LMB | 5962-8989205XA |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

| Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN |
|---|---|---|---|---|---|
| P4C198-20DMB | 5962-8989204LA | P4C198L-55 (GEN) | 5962-8685913XA | CLC425AJ-QML | 5962-9325901MPA |
| P4C198-20FMB | 5962-8989204KA | P4C198A-70DMB | 5962-8685903LA | 4250 (GEN) | 7703901GA |
| P4C198-20L1MB | 5962-8989204YA | P4C198A-70LMB | 5962-8685903XA | 4250 (GEN) | 7703901HA |
| P4C198-20LMB | 5962-8989204XA | P4C198AL-70DMB | 5962-8685904LA | 4250 (GEN) | 7703901PA |
| P4C198L-20DMB | 5962-8989203LA | P4C198AL-70LMB | 5962-8685904XA | 4256-12 (GEN) | 8515203EA |
| P4C198L-20FMB | 5962-8989203KA | P4C198A-85DMB | 5962-8685901LA | 4256-12 (GEN) | 8515203YA |
| P4C198L-20L1MB | 5962-8989203YA | P4C198A-85LMB | 5962-8685901XA | 4256-15 (GEN) | 8515201EA |
| P4C198L-20LMB | 5962-8989203XA | P4C198AL-85DMB | 5962-8685902LA | 4256-15 (GEN) | 8515201YA |
| P4C1982-20CMB | 5962-8971204XA | P4C198AL-85LMB | 5962-8685902XA | 4256-20 (GEN) | 8515202EA |
| P4C1982-20FMB | 5962-8971204YA | OP-42AJ/883 | 5962-8851301GA | 4256-20 (GEN) | 8515202YA |
| P4C1982-20LMB | 5962-8971204UA | OP-42AJ/QMLV | 5962-8851301VGA | CLC426AJ-QML | 5962-9459701MPA |
| P4C1982-20LMB | 5962-8971204ZA | OP-42ARC/883 | 5962-88513012A | TSC426MJA/883B | 5962-8850301PA |
| P4C1982-25CMB | 5962-8971203XA | OP-42ARC/QMLV | 5962-8851301V2A | TSC426MNP/883B | 5962-88503012C |
| P4C1982-25FMB | 5962-8971203YA | OP-42AZ/883 | 5962-8851301PA | 4264-15 (GEN) | 8201004EA |
| P4C1982-25LMB | 5962-8971203UA | OP-42AZ/QMLV | 5962-8851301VPA | 4264-15 (GEN) | 8201004ZA |
| P4C1982-25LMB | 5962-8971203ZA | OP-42BL/883 | 5962-8851302HA | 4264-20 (GEN) | 8201005EA |
| P4C1982-35CMB | 5962-8971202XA | CLC420AE-QML | 5962-9175801M2A | 4264-20 (GEN) | 8201005ZA |
| P4C1982-35FMB | 5962-8971202YA | CLC420AJFQML | 5962F9175801MPA | TSC427MJA/883B | 5962-8850302PA |
| P4C1982-35LMB | 5962-8971202UA | CLC420AJ-QML | 5962-9175801MPA | TSC427MNP/883B | 5962-88503022C |
| P4C1982-35LMB | 5962-8971202ZA | CLC420AWGFQML | 5962F9175801MXA | CLC428AJ-QML | 5962-9470801MPA |
| P4C1982-45CMB | 5962-8971201XA | CLC420AWG-QML | 5962-9175801MXA | TSC428MJA/883B | 5962-8850303PA |
| P4C1982-45FMB | 5962-8971201YA | CLC420B (GEN) | 5962-9175802M2A | TSC428MNP/883B | 5962-88503032C |
| P4C1982-45LMB | 5962-8971201UA | CLC420B (GEN) | 5962-9175802MPA | MIC429 (GEN) | 5962-8877001HA |
| P4C1982-45LMB | 5962-8971201ZA | MSK 4200B | 5962-9762802HXA | MIC429 (GEN) | 5962-8877001PA |
| P4C198-25DMB | 5962-8989202LA | MSK 4200B | 5962-9762802HXC | TSC429 (GEN) | 5962-88770012A |
| P4C198-25FMB | 5962-8989202KA | MSK 4201B | 5962-9762902HXA | OP43AJ/QMLV | 5962-9763701VGA |
| P4C198-25L1MB | 5962-8989202YA | MSK 4201B | 5962-9762902HXC | REF43B (GEN) | 5962-90603012A |
| P4C198-25LMB | 5962-8989202XA | OP421B (GEN) | 5962-8855901CA | REF43B (GEN) | 5962-9060301GA |
| P4C198L-25DMB | 5962-8989201LA | OP421CY | 5962-8855902CA | REF43B (GEN) | 5962-9060301PA |
| P4C198L-25FMB | 5962-8989201KA | 42106 | 5962-8762001XA | CLC430AE-QML | 5962-9203001M2A |
| P4C198L-25L1MB | 5962-8989201YA | 42106 | 5962-8762001XC | CLC430AJ-QML | 5962-9203001MPA |
| P4C198L-25LMB | 5962-8989201XA | 42106-1 | 5962-8762002XA | CLC430AWG-QML | 5962-9203001MXA |
| P4C198-35CMB | 5962-8685918LA | 42106-1 | 5962-8762002XC | CLC431AE-QML | 5962-9472501M2A |
| P4C198-35LMB | 5962-8685918UA | MIOP42109/883 | 5962-9065901HXA | CLC431AJ-QML | 5962-9472501MCA |
| P4C198-35LMB | 5962-8685918XA | MIOP42109/883 | 5962-9065901HXC | TL431 (GEN) | 84109012A |
| P4C198A-35CMB | 5962-8685909LA | MIOP42115/883 | 5962-9082801HXA | TL431 (GEN) | 8410901PA |
| P4C198A-35LMB | 5962-8685909XA | MIOP42115/883 | 5962-9082801HXC | 43168-22 (GEN) | 5962-9750403MXA |
| P4C198AL-35CMB | 5962-8685910LA | CLC422 (GEN) | 5962-9166601MPA | 43168-30 (GEN) | 5962-9750402MXA |
| P4C198AL-35LMB | 5962-8685910XA | A42MX36-CQ208B | 5962-9958501QYC | 43168-39 (GEN) | 5962-9750401MXA |
| P4C198L-35CMB | 5962-8685917LA | A42MX36-CQ256B | 5962-9958501QXC | CLC432A (GEN) | 5962-9472502M2A |
| P4C198L-35LMB | 5962-8685917UA | A42MX36-DIE | 5962-9958501Q9A | CLC432AJ-QML | 5962-9472502MPA |
| P4C198L-35LMB | 5962-8685917XA | A42MX36-1CQ208B | 5962-9958502QYC | UHC432/883 | 5962-8960401DA |
| P4C198-45 (GEN) | 5962-8685916XA | A42MX36-1CQ256B | 5962-9958502QXC | UHD432/883 | 5962-8960401CA |
| P4C198A-45CMB | 5962-8685907LA | MT42C4256C-10/883C | 5962-8949704MXA | UHC432-1/883 | 5962-8960402DA |
| P4C198A-45LMB | 5962-8685907XA | MT42C4256CZ-10/883C | 5962-8949704MMA | UHD432-1/883 | 5962-8960402CA |
| P4C198AL-45CMB | 5962-8685908LA | MT42C4256DCJ-10/883 | 5962-8949704MTA | 4344 (GEN) | 5962-8780301AA |
| P4C198AL-45LMB | 5962-8685908XA | MT42C4256EC-10/883C | 5962-8949704MZA | ML4344/BCA | 5962-8780301CA |
| P4C198L-45 (GEN) | 5962-8685915XA | MT42C4256F-10/883C | 5962-8949704MUA | ML4344/BDA | 5962-8780301DA |
| P4C198-55 (GEN) | 5962-8685914XA | MT42C4256C-12/883C | 5962-8949703MXA | MSK437B | 5962-8981301GA |
| P4C198A-55CMB | 5962-8685905LA | MT42C4256CZ-12/883C | 5962-8949703MMA | MSK437B | 5962-8981301GC |
| P4C198A-55LMB | 5962-8685905XA | MT42C4256DCJ-12/883 | 5962-8949703MTA | MSK438B | 5962-8981302GA |
| P4C198AL-55CMB | 5962-8685906LA | MT42C4256EC-12/883C | 5962-8949703MZA | MSK438B | 5962-8981302GC |
| P4C198AL-55LMB | 5962-8685906XA | MT42C4256F-12/883C | 5962-8949703MUA | L4C381-25 (GEN) | 5962-8995903YA |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

| Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN |
|---|---|---|---|---|---|
| L4C381-25 (GEN) | 5962-8995903ZA | AS4C4067EC-15/883C | 5962-9213206MXA | HS0-4424BRH-Q | 5962F9956002V9A |
| L4C381-30 (GEN) | 5962-8995902YA | ARX4407 | 5962-9174908HXA | HS0-4424RH-Q | 5962F9956001V9A |
| L4C381-30 (GEN) | 5962-8995902ZA | ARX4407 | 5962-9174908HXC | HS-4424 (GEN) | 5962R9956001TXC |
| L4C381-45 (GEN) | 5962-8995901XA | ARX4407FP | 5962-9174908HYA | HS-4424B (GEN) | 5962R9956002TXC |
| L4C381-45 (GEN) | 5962-8995901YA | ARX4407FP | 5962-9174908HYC | HS9-4424BRH-8 | 5962F9956002QXC |
| L4C381-45 (GEN) | 5962-8995901ZA | ARX4407LPFP | 5962-9174908HTA | HS9-4424BRH-Q | 5962F9956002VXC |
| 43891GM-20 (GEN) | 5962-9209701MXC | ARX4407LPFP | 5962-9174908HTC | HS9-4424RH-8 | 5962F9956001QXC |
| 43891GM-20 (GEN) | 5962-9209701MYA | CLC440A (GEN) | 5962-9751801MPA | HS9-4424RH-Q | 5962F9956001VXC |
| 43891GM-25 (GEN) | 5962-9209702MXC | DG441AK/883 | 5962-9204101MEA | MIC4424AJBQ | 5962-8850305PA |
| 43981GM-25 (GEN) | 5962-9209702MYA | DG441AK/883B | 5962-9204101MEA | TSC4424 (GEN) | 5962-88503052A |
| OP44A (GEN) | 5962-89804012A | DG441AZ/883 | 5962-9204101M2A | MIC4425 (GEN) | 5962-8850306HA |
| OP44A (GEN) | 5962-8980401GA | DG441AZ/883B | 5962-9204101M2C | MIC4425 (GEN) | 5962-8850306PA |
| OP44A (GEN) | 5962-8980401PA | TL441AM (GEN) | 5962-9176301M2A | TSC4425 (GEN) | 5962-88503062A |
| MT4C4001JC-10 | 5962-9084702MUA | TL441AM (GEN) | 5962-9176301MEA | SMJ44C251B-10HJM | 5962-8949704MYA |
| MT4C4001JCN-10 | 5962-9084702MRA | TL441AMJB | 5962-9176301QEA | SMJ44C251B-10HMM | 5962-8949704MZA |
| MT4C4001JCZ-10 | 5962-9084702MNA | 44100-10HR (GEN) | 5962-9062202MXA | SMJ44C251B-10JDM | 5962-8949704MXA |
| MT4C4001JEC-10 | 5962-9084702MYA | 44100-12HR (GEN) | 5962-9062201MXA | SMJ44C251B-10SVM | 5962-8949704MMA |
| MT4C4001JF-10 | 5962-9084702MMA | 44100-80HR (GEN) | 5962-9062203MXA | SMJ44C251B-12HJM | 5962-8949703MYA |
| MT4C4001JC-12 | 5962-9084701MUA | ARX4418 | 5962-9208503HXA | SMJ44C251B-12HMM | 5962-8949703MZA |
| MT4C4001JCN-12 | 5962-9084701MRA | ARX4418 | 5962-9208503HXC | SMJ44C251B-12JDM | 5962-8949703MXA |
| MT4C4001JCZ-12 | 5962-9084701MNA | ARX4418FP | 5962-9208503HYA | SMJ44C251B-12SVM | 5962-8949703MMA |
| MT4C4001JEC-12 | 5962-9084701MYA | ARX4418FP | 5962-9208503HYC | AS4C4256C-80/883C | 5962-9061709MRA |
| MT4C4001JECN-12 | 5962-9084701MTA | DG442AK/883 | 5962-9204102MEA | AS4C4256EC-80/883C | 5962-9061709MYA |
| MT4C4001JF-12 | 5962-9084701MMA | DG442AK/883B | 5962-9204102MEA | AS4C4256F-80/883C | 5962-9061709MNA |
| MT4C4001JC-8 | 5962-9084703MUA | DG442AZ/883 | 5962-9204102M2A | MT4C4256 (GEN) | 5962-9061704MNA |
| MT4C4001JCN-8 | 5962-9084703MRA | DG442AZ/883B | 5962-9204102M2C | MT4C4256 (GEN) | 5962-9061704MTA |
| MT4C4001JCZ-8 | 5962-9084703MNA | LF442MH/883 | 5962-9763301QGA | AS4C4256C-10/883C | 5962-9061708MRA |
| MT4C4001JEC-8 | 5962-9084703MYA | MAX4420MJA/883B | 5962-8877003PA | AS4C4256EC-10/883C | 5962-9061708MYA |
| MT4C4001JECN-8 | 5962-9084703MTA | MAX4420MLP/883B | 5962-88770032C | AS4C4256F-10/883C | 5962-9061708MNA |
| MT4C4001JF-8 | 5962-9084703MMA | MIC4420 (GEN) | 5962-8877003HA | MT4C4256 (GEN) | 5962-9061703MNA |
| ARX4404 | 5962-9174909HXA | MIC4420AJBQ | 5962-8877003PA | MT4C4256 (GEN) | 5962-9061703MTA |
| ARX4404 | 5962-9174909HXC | MIC44R21 (GEN) | 5962-8877006HA | SMJ44C256-10FQM | 5962-9061703MYA |
| ARX4404FP | 5962-9174909HYA | MIC44R21 (GEN) | 5962-8877006PA | SMJ44C256-10HJM | 5962-9061703MXA |
| ARX4404FP | 5962-9174909HYC | MIC44R22 (GEN) | 5962-8877007PA | SMJ44C256-10HKM | 5962-9061703MUA |
| ARX4404LPFP | 5962-9174909HTA | P4C422-15DMB | 5962-8859401WA | SMJ44C256-10JDM | 5962-9061703MRA |
| ARX4404LPFP | 5962-9174909HTC | P4C422-15FMB | 5962-8859401KA | AS4C4256C-12/883C | 5962-9061707MRA |
| 4C4067-10 (GEN) | 5962-9213201MVA | P4C422-15LMB | 5962-8859401XA | AS4C4256EC-12/883C | 5962-9061707MYA |
| 4C4067-10 (GEN) | 5962-9213201MXA | P4C422-25FMB | 5962-8859403KA | AS4C4256F-12/883C | 5962-9061707MNA |
| 4C4067-10 (GEN) | 5962-9213201MYA | P4C422-25LMB | 5962-8859403XA | MT4C4256 (GEN) | 5962-9061702MNA |
| AS4C4067C-10/883C | 5962-9213204MVA | P4C422-35DMB | 5962-8859402WA | MT4C4256 (GEN) | 5962-9061702MTA |
| AS4C4067EA-10/883C | 5962-9213204MYA | P4C422-25DMB | 5962-8859403WA | SMJ44C256-12FQM | 5962-9061702MYA |
| AS4C4067EC-10/883C | 5962-9213204MXA | P4C422-35FMB | 5962-8859402KA | SMJ44C256-12HJM | 5962-9061702MXA |
| 4C4067-12 (GEN) | 5962-9213202MVA | P4C422-35LMB | 5962-8859402XA | SMJ44C256-12HKM | 5962-9061702MUA |
| 4C4067-12 (GEN) | 5962-9213202MXA | HS0-4423BRH-Q | 5962F9951102V9A | SMJ44C256-12JDM | 5962-9061702MRA |
| 4C4067-12 (GEN) | 5962-9213202MYA | HS0-4423RH-Q | 5962F9951101V9A | AS4C4256C-15/883C | 5962-9061706MRA |
| AS4C4067C-12/883C | 5962-9213205MVA | HS-4423B (GEN) | 5962R9951102TXC | AS4C4256EC-15/883C | 5962-9061706MYA |
| AS4C4067EA-12/883C | 5962-9213205MYA | HS9-4423BRH-8 | 5962F9951102QXC | AS4C4256F-15/883C | 5962-9061706MNA |
| AS4C4067EC-12/883C | 5962-9213205MXA | HS9-4423BRH-Q | 5962F9951102VXC | MT4C4256 (GEN) | 5962-9061701MNA |
| 4C4067-15 (GEN) | 5962-9213203MVA | HS9-4423RH-8 | 5962F9951101QXC | MT4C4256 (GEN) | 5962-9061701MTA |
| 4C4067-15 (GEN) | 5962-9213203MXA | HS9-4423RH-Q | 5962F9951101VXC | SMJ44C256-15FQM | 5962-9061701MYA |
| 4C4067-15 (GEN) | 5962-9213203MYA | HS9-4423RH-T | 5962R9951101TXC | SMJ44C256-15HJM | 5962-9061701MXA |
| AS4C4067C-15/883C | 5962-9213206MVA | MIC4423 (GEN) | 5962-8850304PA | SMJ44C256-15HKM | 5962-9061701MUA |
| AS4C4067EA-15/883C | 5962-9213206MYA | TSC4423 (GEN) | 5962-88503042A | SMJ44C256-15JDM | 5962-9061701MRA |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

| Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN |
|---|---|---|---|---|---|
| AS4C4256C-70883C | 5962-9061710MRA | ACT4454-201-2 | 5962-9206110HZA | VGC450 (GEN) | 5962-94B0416MUC |
| AS4C4256EC-70883C | 5962-9061710MYA | ACT4455 | 5962-9674101H3A | VGC450 (GEN) | 5962-94B0416MXA |
| AS4C4256F-70883C | 5962-9061710MNA | ACT4455 | 5962-9674101H3C | VGC450 (GEN) | 5962-94B0416MYA |
| MT4C4256 (GEN) | 5962-9061705MNA | ACT4458-201-1 | 5962-9206107HZC | VGC450 (GEN) | 5962-94B0416MZA |
| MT4C4256 (GEN) | 5962-9061705MTA | ACT4458-201-2 | 5962-9206107HZA | 4502B (GEN) | 5962R9661601V9A |
| SJM44C256-70HKM | 5962-9061705MUA | ACT4459 | 5962-9674102H3A | 4502B (GEN) | 5962R9661601VCC |
| SMJ44C256-70FQM | 5962-9061705MYA | ACT4459 | 5962-9674102H3C | 4502B (GEN) | 5962R9661601VXC |
| SMJ44C256-70HJM | 5962-9061705MXA | ACT4460-201-1 | 5962-9206109HZC | 4502B (GEN) | 7702001EA |
| SMJ44C256-70JDM | 5962-9061705MRA | ACT4460-201-2 | 5962-9206109HZA | 4502B (GEN) | 7702001FA |
| 44C256-80 (GEN) | 5962-9061704MZA | 4461 (GEN) | 5962-8956001XA | 4502BN (GEN) | 5962R9661602V9A |
| SJM44C256-80HJM | 5962-9061704MXA | ACT4464-201-1 | 5962-9206108HZC | 4502BN (GEN) | 5962R9661602VCC |
| SJM44C256-80HKM | 5962-9061704MUA | ACT4464-201-2 | 5962-9206108HZA | 4502BN (GEN) | 5962R9661602VXC |
| SMJ44C256-80FQM | 5962-9061704MYA | MIC4467 (GEN) | 5962-9459401MCA | CD4502BF3A | 7702002EA |
| SMJ44C256-80JDM | 5962-9061704MRA | CLC446AJ-QML | 5962-9751901MPA | TLC4502AMFKB | 5962-9753702Q2A |
| MIC4426AJBQ | 5962-8850307PA | MIC4468 (GEN) | 5962-9459402MCA | TLC4502AMJGB | 5962-9753702QPA |
| TSC4426 (GEN) | 5962-88503072A | MIC4469AJB | 5962-9459403MCA | TLC4502AMUB | 5962-9753702QHA |
| MIC4427 (GEN) | 5962-8850308HA | ACT4487-D | 5962-8757910XA | TLC4502MFKB | 5962-9753701Q2A |
| MIC4427AJBQ | 5962-8850308PA | ACT4487-D | 5962-8757910XC | TLC4502MJGB | 5962-9753701QPA |
| TSC4427 (GEN) | 5962-88503082A | ACT4487-DF | 5962-8757910YA | TLC4502MUB | 5962-9753701QHA |
| MIC4428AJBQ | 5962-8850309PA | ACT4487-DF | 5962-8757910YC | 4503B (GEN) | 5962R9664301V9A |
| TSC4428 (GEN) | 5962-88503092A | ACT4487-DFI | 5962-8944708HYA | 4503BN (GEN) | 5962R9664302V9A |
| MAX4429MJA/883B | 5962-8877002PA | ACT4487-DFI | 5962-8944708HYC | 4503BN (GEN) | 5962R9664302VEC |
| MAX4429MLP/883B | 5962-88770022C | ACT4487-DI | 5962-8944708HXA | CD4503BDMSR | 5962R9664301VEC |
| MIC4429 (GEN) | 5962-8877002HA | ACT4487-DI | 5962-8944708HXC | CD4503BKMSR | 5962R9664301VXC |
| ACT4436-DFI | 5962-8944708HZA | CLC449AJ-QML | 5962-9752001MPA | CD4503BKNSR | 5962R9664302VXC |
| ACT4436-DFI | 5962-8944708HZC | UT450*QCR | 5962R96B0221Q*C | 4504B (GEN) | 5962R9666501TEC |
| ACT4436-DI | 5962-8944708HUA | UT450*VCR | 5962R96B0221V*C | 4504B (GEN) | 5962R9666501TXC |
| ACT4436-DI | 5962-8944708HUC | VGC450 (GEN) | 5962-94B0406MXA | 4504B (GEN) | 5962R9666501V9A |
| MT4C4001JECN-10 | 5962-9084702MTA | VGC450 (GEN) | 5962-94B0407MMA | CD4504BDMSR | 5962R9666501VEC |
| SMJ44400-10HRM | 5962-9084702MXA | VGC450 (GEN) | 5962-94B0407MXA | CD4504BKMSR | 5962R9666501VXC |
| SMJ44400-10JDM | 5962-9084702MUA | VGC450 (GEN) | 5962-94B0408MMA | 4508B (GEN) | 5962R9668001V9A |
| SMJ44400-12HRM | 5962-9084701MXA | VGC450 (GEN) | 5962-94B0408MYA | 4508B (GEN) | 5962R9668001VLC |
| SMJ44400-12JDM | 5962-9084701MUA | VGC450 (GEN) | 5962-94B0409MYA | 4508B (GEN) | 5962R9668001VXC |
| SMJ44400-80HRM | 5962-9084703MXA | VGC450 (GEN) | 5962-94B0410MXA | 4508BN (GEN) | 5962R9668002V9A |
| SMJ44400-80JDM | 5962-9084703MUA | VGC450 (GEN) | 5962-94B0410MYA | 4508BN (GEN) | 5962R9668002VLC |
| EF4442 (GEN) | 5962-9071901MXA | VGC450 (GEN) | 5962-94B0411MXA | 4508BN (GEN) | 5962R9668002VXC |
| ARX4451 | 5962-9208502HXA | VGC450 (GEN) | 5962-94B0411MYA | 4510B (GEN) | 5962R9665701V9A |
| ARX4451 | 5962-9208502HXC | VGC450 (GEN) | 5962-94B0411MZA | 4510B (GEN) | 5962R9665701VEC |
| ARX4451FP | 5962-9208502HYA | VGC450 (GEN) | 5962-94B0412MMA | 4510B (GEN) | 5962R9665701VXC |
| ARX4451FP | 5962-9208502HYC | VGC450 (GEN) | 5962-94B0412MYA | 4511B (GEN) | 5962R9666601V9A |
| MIC4451 (GEN) | 5962-8877004HA | VGC450 (GEN) | 5962-94B0412MZA | CD4511BDMSR | 5962R9666601VEC |
| MIC4451 (GEN) | 5962-8877004PA | VGC450 (GEN) | 5962-94B0413M9C | CD4511BKMSR | 5962R9666601VXC |
| MIC4452 (GEN) | 5962-8877005HA | VGC450 (GEN) | 5962-94B0413MMA | 4512B (GEN) | 5962R9666701V9A |
| MIC4452 (GEN) | 5962-8877005PA | VGC450 (GEN) | 5962-94B0413MNC | 4512BN (GEN) | 5962R9666702V9A |
| 4453-001-3 | 5962-8952212XA | VGC450 (GEN) | 5962-94B0413MTA | CD4512BDMSR | 5962R9666701VEC |
| 4453-001-3 | 5962-8952212XC | VGC450 (GEN) | 5962-94B0413MYA | CD4512BDNSR | 5962R9666702VEC |
| 4453-001-6 | 5962-8952211XA | VGC450 (GEN) | 5962-94B0414M9C | CD4512BKMSR | 5962R9666701VXC |
| 4453-001-6 | 5962-8952211XC | VGC450 (GEN) | 5962-94B0414MTA | CD4512BKNSR | 5962R9666702VXC |
| 4453-201-3 | 5962-8952212YA | VGC450 (GEN) | 5962-94B0414MXA | 4514B (GEN) | 7703501ZA |
| 4453-201-3 | 5962-8952212YC | VGC450 (GEN) | 5962-94B0414MYA | 4514BN (GEN) | 5962R9668103VJC |
| 4453-201-6 | 5962-8952211YA | VGC450 (GEN) | 5962-94B0414MZA | 4514BN (GEN) | 5962R9668103VXC |
| 4453-201-6 | 5962-8952211YC | VGC450 (GEN) | 5962-94B0415MUC | CD4514BDMSR | 5962R9668101VJC |
| ACT4454-201-1 | 5962-9206110HZC | VGC450 (GEN) | 5962-94B0416MTA | CD4514BHSR | 5962R9668101V9A |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

| Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN |
|---|---|---|---|---|---|
| CD4514BKMSR | 5962R9668101VXC | VGC453 (GEN) | 5962-94B0428MZA | MKB4564P-83 | 8201003EA |
| CD54HC4514F3A | 5962-9865501QJA | VGC453 (GEN) | 5962-94B0429M9C | TLC34058-110 (GEN) | 5962-8992801XA |
| 4515B (GEN) | 5962R9668102V9A | VGC453 (GEN) | 5962-94B0429MMA | 4585B (GEN) | 5962R9667401V9A |
| 4515B (GEN) | 5962R9668102VJC | VGC453 (GEN) | 5962-94B0429MNC | 4585B (GEN) | 7703702FA |
| 4515B (GEN) | 5962R9668102VXC | VGC453 (GEN) | 5962-94B0429MTA | CD4585BDMSR | 5962R9667401VEC |
| 4515B (GEN) | 7703201ZA | VGC453 (GEN) | 5962-94B0429MYA | CD4585BF3A | 7703702EA |
| 4515BN (GEN) | 5962R9668104VJC | VGC453 (GEN) | 5962-94B0430M9C | CD4585BKMSR | 5962R9667401VXC |
| 4515BN (GEN) | 5962R9668104VXC | VGC453 (GEN) | 5962-94B0430MTA | OP467AM/QMLR | 5962R9325801VDA |
| CD4515BF3A | 7703201JA | VGC453 (GEN) | 5962-94B0430MXA | OP467ARC/883 | 5962-9325801M2A |
| 4516B (GEN) | 5962R9665702V9A | VGC453 (GEN) | 5962-94B0430MYA | OP467ARC/QMLV | 5962-9325801V2A |
| 4516B (GEN) | 5962R9665702VEC | VGC453 (GEN) | 5962-94B0430MZA | OP467AY/883 | 5962-9325801MCA |
| 4516B (GEN) | 5962R9665702VXC | VGC453 (GEN) | 5962-94B0431MUC | OP467AY/QMLR | 5962R9325801VCA |
| 4516BN (GEN) | 5962R9665703V9A | VGC453 (GEN) | 5962-94B0432MTA | OP467AY/QMLV | 5962-9325801VCA |
| 4516BN (GEN) | 5962R9665703VEC | VGC453 (GEN) | 5962-94B0432MUC | D469AAP/883 | 5962-9098301MCA |
| 4516BN (GEN) | 5962R9665703VXC | VGC453 (GEN) | 5962-94B0432MXA | HS0-OP470ARH-Q | 5962R9853301V9A |
| 4517B (GEN) | 5962R9666801V9A | VGC453 (GEN) | 5962-94B0432MYA | HS9-OP470ARH-Q | 5962R9853301VXC |
| 4517B (GEN) | 5962R9666801VEC | VGC453 (GEN) | 5962-94B0432MZA | OP-470A (GEN) | 5962-88565013A |
| 4517B (GEN) | 5962R9666801VXC | 4532B (GEN) | 5962R9667101V9A | OP-470AN/QMLR | 5962R8856501VKA |
| 4518B (GEN) | 5962R9666901V9A | 4532B (GEN) | 5962R9667101VEC | OP-470AN/QMLV | 5962-8856501VKA |
| 4518B (GEN) | 5962R9666901VEC | 4532B (GEN) | 5962R9667101VXC | OP-470ARC/883C | 5962-88565012A |
| 4518B (GEN) | 5962R9666901VXC | 4532BN (GEN) | 5962R9667102V9A | OP-470ARC/QMLR | 5962R8856501V2A |
| MAX452MJA/883B | 5962-9451203MPA | 4532BN (GEN) | 5962R9667102VEC | OP-470ARC/QMLV | 5962-8856501V2A |
| MAX452MLP/883B | 5962-9451203M2C | 4532BN (GEN) | 5962R9667102VXC | OP-470AY/883C | 5962-8856501CA |
| 4520B (GEN) | 5962R9666902VEC | 4536B (GEN) | 5962R9667201V9A | OP-470AY/QMLR | 5962R8856501VCA |
| 4520B (GEN) | 5962R9666902VXC | 4536B (GEN) | 5962R9667201VEC | OP-470AY/QMLV | 5962-8856501VCA |
| 4520B (GEN) | 7702301FA | 4536B (GEN) | 5962R9667201VXC | HD-4702 (GEN) | 5962-9051801MEA |
| 4520BN (GEN) | 5962R9666903V9A | MAX454MJD/883B | 5962-9451204MCA | OP-471AM/QMLR | 5962R8856502VDA |
| 4520BN (GEN) | 5962R9666903VEC | MAX454MLP/883B | 5962-9451204M2C | OP-471AM/QMLV | 5962-8856502VDA |
| 4520BN (GEN) | 5962R9666903VXC | 4N55/883B | 5962-8767901EC | OP-471AN/QMLR | 5962R8856502VKA |
| CD4520BF3A | 7702301EA | 4N55/883B#100 | 5962-8767901UA | OP-471AN/QMLV | 5962-8856502VKA |
| CD4520BHSR | 5962R9666902V9A | 4N55/883B#100 | 5962-8767901UC | OP-471ARC/883C | 5962-88565022A |
| 4527B (GEN) | 5962R9667001V9A | 4N55/883B#200 | 5962-8767901EA | OP-471ARC/QMLR | 5962R8856502V2A |
| 4527B (GEN) | 5962R9667001VEC | 4N55/883B#300 | 5962-8767901TA | OP-471ARC/QMLV | 5962-8856502V2A |
| 4527B (GEN) | 5962R9667001VXC | MAX455MJP/883B | 5962-9451202MRA | OP-471ATC/883C | 5962-88565023A |
| 4528B (GEN) | 7704501EA | MAX455MLP/883B | 5962-9451202M2C | OP-471AY/883C | 5962-8856502CA |
| 4528B (GEN) | 7704501FA | 4555B (GEN) | 5962R9667301V9A | OP-471AY/QMLR | 5962R8856502VCA |
| 4528B (GEN) | 7704502EA | 4555BN (GEN) | 5962R9667303V9A | OP-471AY/QMLV | 5962-8856502VCA |
| CLC452AJ-QML | 5962-9752101MPA | 4555BN (GEN) | 5962R9667303VEC | 4724B (GEN) | 5962R9667501V9A |
| MAX453MJA/883B | 5962-9451201MPA | 4555BN (GEN) | 5962R9667303VXC | 4724B (GEN) | 5962R9667501VEC |
| MAX453MLP/883B | 5962-9451201M2C | CD4555BDMSR | 5962R9667301VEC | 4724B (GEN) | 5962R9667501VXC |
| VGC453 (GEN) | 5962-94B0422MXA | CD4555BF3A | 7704701EA | HA1-4741/883 | 5962-9864501QCA |
| VGC453 (GEN) | 5962-94B0423MMA | CD4555BKMSR | 5962R9667301VXC | ARX4810-201-1 | 5962-9550501HXC |
| VGC453 (GEN) | 5962-94B0423MXA | 4556B (GEN) | 5962R9667302V9A | ARX4810-201-2 | 5962-9550501HXA |
| VGC453 (GEN) | 5962-94B0424MMA | 4556B (GEN) | 5962R9667302VEC | ARX4810-201-3 | 5962-9550501HXA |
| VGC453 (GEN) | 5962-94B0424MYA | 4556B (GEN) | 5962R9667302VXC | ARX4810-201-3 | 5962-9550501HXC |
| VGC453 (GEN) | 5962-94B0425MYA | 4556B (GEN) | 7704801FA | ARX4810-203-1 | 5962-9550501HYC |
| VGC453 (GEN) | 5962-94B0426MXA | 4556BN (GEN) | 5962R9667304VEC | ARX4810-203-2 | 5962-9550501HYA |
| VGC453 (GEN) | 5962-94B0426MYA | 4556BN (GEN) | 5962R9667304VXC | ARX4810-203-3 | 5962-9550501HYA |
| VGC453 (GEN) | 5962-94B0427MXA | CD4556BF3A | 7704801EA | ARX4810-203-3 | 5962-9550501HYC |
| VGC453 (GEN) | 5962-94B0427MYA | 4557B (GEN) | 7901601EA | OP482A (GEN) | 5962-9458101M2A |
| VGC453 (GEN) | 5962-94B0427MZA | 4557B (GEN) | 7901601FA | OP482A (GEN) | 5962-9458101MCA |
| VGC453 (GEN) | 5962-94B0428MMA | MKB4564P-82 | 8201001EA | OP484AM/QMLR | 5962R0051701VDA |
| VGC453 (GEN) | 5962-94B0428MYA | MKB4564P-82 | 8201002EA | OP484AM/QMLV | 5962-0051701VDA |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

| Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN |
|---|---|---|---|---|---|
| OP484AY/QMLR | 5962R0051701VCA | 49C410A (GEN) | 5962-8864302YA | UT500*QCR | 5962R96B0222Q*C |
| OP484AY/QMLV | 5962-0051701VCA | 49C410A (GEN) | 5962-8864302ZA | UT500*VCR | 5962R96B0222V*C |
| 48410-25 (GEN) | 5962-9457301MXC | 49C460A (GEN) | 5962-8853301TA | ATV5000-25 (GEN) | 5962-9324801MXA |
| 48410-30 (GEN) | 5962-9457302MYA | 49C460A (GEN) | 5962-8853301UA | ATV5000-25 (GEN) | 5962-9324801MYA |
| 48410-33 (GEN) | 5962-9457302MXC | 49C460A (GEN) | 5962-8853301XA | ATV5000-35 (GEN) | 5962-9324802MXA |
| 48410-39 (GEN) | 5962-9457301MYA | 49C460A (GEN) | 5962-8853301YA | ATV5000-35 (GEN) | 5962-9324802MYA |
| LTC485 (GEN) | 5962-9208001MPA | 49C460A (GEN) | 5962-8853301ZA | ATV5000L-35 (GEN) | 5962-9324803MXA |
| 48908-20 (GEN) | 5962-9300701MXC | 49C460B (GEN) | 5962-8853302TA | ATV5000L-35 (GEN) | 5962-9324803MYA |
| 48908-25 (GEN) | 5962-9300703MXA | 49C460B (GEN) | 5962-8853302UA | TL5001AMFKB | 5962-9958302Q2A |
| 48908-25 (GEN) | 5962-9300703MYA | 49C460B (GEN) | 5962-8853302XA | TL5001AMJGB | 5962-9958302QPA |
| 48908-37 (GEN) | 5962-9300702MXA | 49C460B (GEN) | 5962-8853302YA | TL5001MFKB | 5962-9958301Q2A |
| 48908-37 (GEN) | 5962-9300702MYA | 49C460B (GEN) | 5962-8853302ZA | TL5001MJGB | 5962-9958301QPA |
| 48908-50 (GEN) | 5962-9300701MYA | 49C460C (GEN) | 5962-8853306TA | HA2-5002/883 | 5962-8963601GC |
| FXPC-49F (GEN) | 5962-9202601QZC | 49C460C (GEN) | 5962-8853306UA | HA4-5002/883 | 5962-89636012A |
| FXPC-49F (GEN) | 5962-9202601VZC | 49C460C (GEN) | 5962-8853306XA | HA7-5002/883 | 5962-8963601PA |
| OP490A (GEN) | 5962-89670013A | 49C460C (GEN) | 5962-8853306YA | AFL5005DW/CH | 5962-0256301HUA |
| OP490A (GEN) | 5962-8967001CA | 49C460D (GEN) | 5962-8853307TA | AFL5005DW/CH | 5962-0256301HUC |
| HA1-4902/883 | 5962-8686001EA | 49C460D (GEN) | 5962-8853307UA | AFL5005DX/CH | 5962-0256301HXA |
| HA4-4902/883 | 5962-86860012A | 49C465 (GEN) | 5962-9212202MXA | AFL5005DX/CH | 5962-0256301HXC |
| RHFL4913KPA-01V | 5962F0252401VXC | 49C465A (GEN) | 5962-9212201MXA | AFL5005DY/CH | 5962-0256301HYA |
| RHFL4913KPA-02V | 5962F0252401VXA | OP497B (GEN) | 5962-9452101MCA | AFL5005DY/CH | 5962-0256301HYC |
| RHFL4913SOA-03V | 5962F0252402VYC | OP497BRC/883B | 5962-9452101M2A | AFL5005DZ/CH | 5962-0256301HZA |
| RHFL4913SOA-04V | 5962F0252402VYA | 49FCT805 (GEN) | 5962-9215701M2A | AFL5005DZ/CH | 5962-0256301HZC |
| RHFL4913KA-05V | 5962F0252402VZC | 49FCT805 (GEN) | 5962-9215701MRA | AFL5005SW/CH | 5962-0255701HUA |
| RHFL4913KA-06V | 5962F0252402VZA | 49FCT805 (GEN) | 5962-9215701MSA | AFL5005SW/CH | 5962-0255701HUC |
| RHFL4913KP25-01V | 5962F0253401VXC | 49FCT805A (GEN) | 5962-9215702M2A | AFL5005SX/CH | 5962-0255701HXA |
| RHFL4913KP25-02V | 5962F0253401VXA | 49FCT805A (GEN) | 5962-9215702MRA | AFL5005SX/CH | 5962-0255701HXC |
| RHFL4913S25-03V | 5962F0253402VYC | 49FCT805A (GEN) | 5962-9215702MSA | AFL5005SY/CH | 5962-0255701HYA |
| RHFL4913S25-04V | 5962F0253402VYA | 49FCT805B (GEN) | 5962-9576101MSA | AFL5005SY/CH | 5962-0255701HYC |
| RHFL4913ESY2505V | 5962F0253402VZC | IDT49FCT805BTDB | 5962-9576101MRA | AFL5005SZ/CH | 5962-0255701HZA |
| RHFL4913ESY2506V | 5962F0253402VZA | IDT49FCT805BTLB | 5962-9576101M2A | AFL5005SZ/CH | 5962-0255701HZC |
| RHFL4913KP30-01V | 5962F0320101VXC | IDT49FCT805C (GEN) | 5962-9576102MSA | ARX5006 | 5962-9313401HXA |
| RHFL4913KP30-02V | 5962F0320101VXA | IDT49FCT805CTDB | 5962-9576102MRA | ARX5006 | 5962-9313401HXC |
| RHFL4913S30-03V | 5962F0320102VYC | IDT49FCT805CTLB | 5962-9576102M2A | ARX5007 | 5962-9313402HXA |
| RHFL4913S30-04V | 5962F0320102VYA | 49FCT806 (GEN) | 5962-9215703M2A | ARX5007 | 5962-9313402HXC |
| RHFL4913ESY3005V | 5962F0320102VZC | 49FCT806 (GEN) | 5962-9215703MRA | 500/700J (GEN) | 5962-94B0201QXA |
| RHFL4913ESY3006V | 5962F0320102VZA | 49FCT806 (GEN) | 5962-9215703MSA | AFL5008SW/CH | 5962-0255801HUA |
| RHFL4913KP33-01V | 5962F0253501VXC | 49FCT806A (GEN) | 5962-9215704M2A | AFL5008SW/CH | 5962-0255801HUC |
| RHFL4913KP33-02V | 5962F0253501VXA | 49FCT806A (GEN) | 5962-9215704MRA | AFL5008SX/CH | 5962-0255801HXA |
| RHFL4913S33-03V | 5962F0253502VYC | 49FCT806A (GEN) | 5962-9215704MSA | AFL5008SX/CH | 5962-0255801HXC |
| RHFL4913S33-04V | 5962F0253502VYA | 49FCT806B (GEN) | 5962-9576201MSA | AFL5008SY/CH | 5962-0255801HYA |
| RHFL4913ESY3305V | 5962F0253502VZC | 49FCT806C (GEN) | 5962-9576202MSA | AFL5008SY/CH | 5962-0255801HYC |
| RHFL4913ESY5005V | 5962F0253602VZC | IDT49FCT806BTDB | 5962-9576201MRA | AFL5008SZ/CH | 5962-0255801HZA |
| RHFL4913ESY3306V | 5962F0253502VZA | IDT49FCT806BTLB | 5962-9576201M2A | AFL5008SZ/CH | 5962-0255801HZC |
| RHFL4913KP50-01V | 5962F0253601VXC | IDT49FCT806CTDB | 5962-9576202MRA | ARX5008 | 5962-9313403HXA |
| RHFL4913KP50-02V | 5962F0253601VXA | IDT49FCT806CTLB | 5962-9576202M2A | ARX5008 | 5962-9313403HXC |
| RHFL4913S50-03V | 5962F0253602VYC | OP-50A (GEN) | 5962-8967301CA | AFL5009SW/CH | 5962-0255901HUA |
| RHFL4913S50-04V | 5962F0253602VYA | OP-50B (GEN) | 5962-8967302CA | AFL5009SW/CH | 5962-0255901HUC |
| RHFL4913ESY5006V | 5962F0253602VZA | CLC500 (GEN) | 5962-9092501MCA | AFL5009SX/CH | 5962-0255901HXA |
| 49C410 (GEN) | 5962-8864301XA | MAX500A (GEN) | 5962-9452701M2A | AFL5009SX/CH | 5962-0255901HXC |
| 49C410 (GEN) | 5962-8864301YA | MAX500A (GEN) | 5962-9452701MEA | AFL5009SY/CH | 5962-0255901HYA |
| 49C410 (GEN) | 5962-8864301ZA | MAX500BMJE/883B | 5962-9452702MEA | AFL5009SY/CH | 5962-0255901HYC |
| 49C410A (GEN) | 5962-8864302XA | MAX500BMLP/883B | 5962-9452702M2C | AFL5009SZ/CH | 5962-0255901HZA |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

| Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN |
|---|---|---|---|---|---|
| AFL5009SZ/CH | 5962-0255901HZC | SEI5016-TD16B | 5962-8967602QA | HI4-5051/883 | 81006222A |
| ARX5009 | 5962-9313404HXA | SEI5016-TE16B | 5962-8967602XA | DG506AAZ/883B | 5962-85131073C |
| ARX5009 | 5962-9313404HXC | CLC502AE-QML | 5962-9174301M2A | HI1-506/883 | 5962-8513107XA |
| CLC501 (GEN) | 5962-89974012A | CLC502AJ-QML | 5962-9174301MPA | HI4-506/883 | 5962-85131073A |
| CLC501 (GEN) | 5962-8997401PA | MAX502AMRG/883B | 5962-8876701LA | DG507AAZ/883B | 5962-85131083C |
| AH5010J (GEN) | 5962-9087801MCA | MAX502BMRG/883B | 5962-8876702LA | HI1-507/883 | 5962-8513108XA |
| ARX5010 | 5962-9313405HXA | HA4-5020/883 | 5962-89620012A | HI4-507/883 | 5962-85131083A |
| ARX5010 | 5962-9313405HXC | HA7-5020/883 | 5962-8962001PA | UH507 (GEN) | 5962-8986701CA |
| ARX5011 | 5962-9313406HXA | AFL5028SW/CH | 5962-0256201HUA | 508A (GEN) | 5962R9674201QEC |
| ARX5011 | 5962-9313406HXC | AFL5028SW/CH | 5962-0256201HUC | 508A (GEN) | 5962R9674201QXC |
| MIC5011 (GEN) | 5962-9313901MPA | AFL5028SX/CH | 5962-0256201HXA | 508A (GEN) | 5962R9674201TEC |
| AFL5012DW/CH | 5962-0256401HUA | AFL5028SX/CH | 5962-0256201HXC | 508A (GEN) | 5962R9674201TXC |
| AFL5012DW/CH | 5962-0256401HUC | AFL5028SY/CH | 5962-0256201HYA | 508A (GEN) | 5962R9674201V9A |
| AFL5012DX/CH | 5962-0256401HXA | AFL5028SY/CH | 5962-0256201HYC | 508A (GEN) | 5962R9674201VEC |
| AFL5012DX/CH | 5962-0256401HXC | AFL5028SZ/CH | 5962-0256201HZA | 508A (GEN) | 5962R9674201VXC |
| AFL5012DY/CH | 5962-0256401HYA | AFL5028SZ/CH | 5962-0256201HZC | ADG508ATE/883B | 77052012A |
| AFL5012DY/CH | 5962-0256401HYC | UH503 (GEN) | 5962-8855101CA | ADG508ATQ/883B | 7705201EA |
| AFL5012DZ/CH | 5962-0256401HZA | UH503 (GEN) | 5962-8855101DA | DG508A (GEN) | 7705201FA |
| AFL5012DZ/CH | 5962-0256401HZC | AFL503R3SW/CH | 5962-0255601HUA | DG508A (GEN) | 7705201XA |
| AFL5012SW/CH | 5962-0256001HUA | AFL503R3SW/CH | 5962-0255601HUC | DG508AAK/883B | 7705201EA |
| AFL5012SW/CH | 5962-0256001HUC | AFL503R3SX/CH | 5962-0255601HXA | DG508AAL/883B | 7705201XC |
| AFL5012SX/CH | 5962-0256001HXA | AFL503R3SX/CH | 5962-0255601HXC | DG508AAZ/883B | 77052012C |
| AFL5012SX/CH | 5962-0256001HXC | AFL503R3SY/CH | 5962-0255601HYA | HI1-508/883 | 7705201EA |
| AFL5012SY/CH | 5962-0256001HYA | AFL503R3SY/CH | 5962-0255601HYC | HI4-508/883 | 77052012A |
| AFL5012SY/CH | 5962-0256001HYC | AFL503R3SZ/CH | 5962-0255601HZA | HS0-508BRH-Q | 5962F9674202V9A |
| AFL5012SZ/CH | 5962-0256001HZA | AFL503R3SZ/CH | 5962-0255601HZC | HS-0508RH (GEN) | 5962D9569201VEA |
| AFL5012SZ/CH | 5962-0256001HZC | HA5033 (GEN) | 5962-8963301XC | HS1-508BRH-8 | 5962F9674202QEC |
| AH5012 (GEN) | 5962-9088001MEA | HI5040 (GEN) | 8100601AA | HS1-508BRH-Q | 5962F9674202VEC |
| MIC5012 (GEN) | 5962-9313902MCA | IH5040MJE/883B | 8100601EA | HS1-508BRH-T | 5962R9674202TEC |
| SEI5012-TD12B | 5962-8967901QC | IH5041 (GEN) | 8100602AA | HS9-508BRH-8 | 5962F9674202QXC |
| SEI5012-TE12B | 5962-8967901XC | IH5041MJE/883B | 8100602EA | HS9-508BRH-Q | 5962F9674202VXC |
| SEI5014-SD14B | 5962-8967401QC | IH5042 (GEN) | 8100603AA | HS9-508BRH-T | 5962R9674202TXC |
| SEI5014-SE14B | 5962-8967401XC | IH5042MJE/883B | 8100603EA | UH508 (GEN) | 8550001DA |
| SEI5014-TD14B | 5962-8967402QC | HI4-5043/883 | 81006122A | UHD508R/883C | 8550001CA |
| SEI5014-TE14B | 5962-8967402XC | IH5043 (GEN) | 8100604AA | SA 50M (GEN) | 5962-9762801HXA |
| AFL5015DW/CH | 5962-0256501HUA | IH5043MJE/883B | 8100604EA | DG509AAZ/883B | 5962-85131092C |
| AFL5015DW/CH | 5962-0256501HUC | IH5044 (GEN) | 8100605AA | HI1-509/883 | 5962-8513109EA |
| AFL5015DX/CH | 5962-0256501HXA | IH5044MJE/883B | 8100605EA | HI4-509/883 | 5962-85131092A |
| AFL5015DX/CH | 5962-0256501HXC | HI5045 (GEN) | 81006142A | HS-0509RH (GEN) | 5962D9569202VEA |
| AFL5015DY/CH | 5962-0256501HYA | IH5045 (GEN) | 8100606AA | PA51M/883 | 5962-8762001YA |
| AFL5015DY/CH | 5962-0256501HYC | IH5045MFD/883B | 8100606XC | PA51M/883 | 5962-8762002YA |
| AFL5015DZ/CH | 5962-0256501HZA | IH5045MJE/883B | 8100606EA | MN5100H/B | 5962-9207301HXA |
| AFL5015DZ/CH | 5962-0256501HZC | HI1-5046A/883 | 8100617EA | MN5100H/B | 5962-9207301HXC |
| AFL5015SW/CH | 5962-0256101HUA | HI-5046 (GEN) | 8100615EA | 5C1001-20 (GEN) | 5962-9231604MXA |
| AFL5015SW/CH | 5962-0256101HUC | IH5046 (GEN) | 8100607AA | 5C1001-20L (GEN) | 5962-9231608MXA |
| AFL5015SX/CH | 5962-0256101HXA | IH5046 (GEN) | 8100607EA | MT5C1001C-20/883C | 5962-9231604MTA |
| AFL5015SX/CH | 5962-0256101HXC | HI-5047A (GEN) | 8100618EA | MT5C1001C-20L/883C | 5962-9231608MTA |
| AFL5015SY/CH | 5962-0256101HYA | IH5047 (GEN) | 8100608AA | MT5C1001DCJ-20/883C | 5962-9231604MUA |
| AFL5015SY/CH | 5962-0256101HYC | IH5047MJE/883B | 8100608EA | MT5C1001DCJ-20L/883 | 5962-9231608MUA |
| AFL5015SZ/CH | 5962-0256101HZA | IH5047MJE/883B | 8100616EA | MT5C1001EC-20/883C | 5962-9231604MYA |
| AFL5015SZ/CH | 5962-0256101HZC | HI5049 (GEN) | 81006202A | MT5C1001EC-20L/883C | 5962-9231608MYA |
| SEI5016-SD16B | 5962-8967601QA | CLC505AJ-QML | 5962-9099301MPA | MT5C1001F-20/883C | 5962-9231604MZA |
| SEI5016-SE16B | 5962-8967601XA | HI1-5051/883 | 8100622EA | MT5C1001F-20L/883C | 5962-9231608MZA |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART II, Listed By Generic PIN

| Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN |
|---|---|---|---|---|---|
| 5C1001-25 (GEN) | 5962-9231603MXA | MT5C1008F-100L883C | 5962-8959814MTA | MT5C1008ECA-35L883 | 5962-8959819MMA |
| 5C1001-25L (GEN) | 5962-9231607MXA | MT5C1008SOJ-100883 | 5962-8959831MYA | MT5C1008ECA-35L883 | 5962-8959836MMA |
| MT5C1001C-25/883C | 5962-9231603MTA | MT5C1008SOJ-100L88 | 5962-8959814MYA | MT5C1008F-35883C | 5962-8959836MTA |
| MT5C1001C-25L/883C | 5962-9231607MTA | MT5C1008C-120883C | 5962-8959830MZA | MT5C1008F-35L883C | 5962-8959819MTA |
| MT5C1001DCJ-25/883C | 5962-9231603MUA | MT5C1008C-120L883C | 5962-8959813MZA | MT5C1008SOJ-35883C | 5962-8959836MYA |
| MT5C1001DCJ-25L/883 | 5962-9231607MUA | MT5C1008CW-120883C | 5962-8959830MXA | MT5C1008SOJ-35L883 | 5962-8959819MYA |
| MT5C1001EC-25/883C | 5962-9231603MYA | MT5C1008CW-120L883 | 5962-8959813MXA | MT5C1008C-45883C | 5962-8959835MZA |
| MT5C1001EC-25L/883C | 5962-9231607MYA | MT5C1008DCJ-120883 | 5962-8959830M7A | MT5C1008C-45L883C | 5962-8959818MZA |
| MT5C1001F-25/883C | 5962-9231603MZA | MT5C1008DCJ-120L88 | 5962-8959813M7A | MT5C1008CW-45883C | 5962-8959835MXA |
| MT5C1001F-25L/883C | 5962-9231607MZA | MT5C1008EC-120883C | 5962-8959830MUA | MT5C1008CW-45L883C | 5962-8959818MXA |
| 5C1001-35 (GEN) | 5962-9231602MXA | MT5C1008EC-120L883 | 5962-8959813MUA | MT5C1008DCJ-45883C | 5962-8959835M7A |
| 5C1001-35L (GEN) | 5962-9231606MXA | MT5C1008ECA-120L88 | 5962-8959813MMA | MT5C1008DCJ-45L883 | 5962-8959818M7A |
| MT5C1001C-35/883C | 5962-9231602MTA | MT5C1008ECA-120L88 | 5962-8959830MMA | MT5C1008EC-45883C | 5962-8959835MUA |
| MT5C1001C-35L/883C | 5962-9231606MTA | MT5C1008F-120883C | 5962-8959830MTA | MT5C1008EC-45L883C | 5962-8959818MUA |
| MT5C1001DCJ-35/883C | 5962-9231602MUA | MT5C1008F-120L883C | 5962-8959813MTA | MT5C1008ECA-45L883 | 5962-8959818MMA |
| MT5C1001DCJ-35L/883 | 5962-9231606MUA | MT5C1008SOJ-120883 | 5962-8959830MYA | MT5C1008ECA-45L883 | 5962-8959835MMA |
| MT5C1001EC-35/883C | 5962-9231602MYA | MT5C1008SOJ-120L88 | 5962-8959813MYA | MT5C1008F-45883C | 5962-8959835MTA |
| MT5C1001EC-35L/883C | 5962-9231606MYA | MT5C1008C-20883C | 5962-8959838MZA | MT5C1008F-45L883C | 5962-8959818MTA |
| MT5C1001F-35/883C | 5962-9231602MZA | MT5C1008C-20L883C | 5962-8959821MZA | MT5C1008SOJ-45883C | 5962-8959835MYA |
| MT5C1001F-35L/883C | 5962-9231606MZA | MT5C1008CW-20883C | 5962-8959838MXA | MT5C1008SOJ-45L883 | 5962-8959818MYA |
| 5C1001-45 (GEN) | 5962-9231601MXA | MT5C1008CW-20L883C | 5962-8959821MXA | MT5C1008C-55883C | 5962-8959834MZA |
| 5C1001-45L (GEN) | 5962-9231605MXA | MT5C1008DCJ-20883C | 5962-8959838M7A | MT5C1008C-55L883C | 5962-8959817MZA |
| MT5C1001C-45/883C | 5962-9231601MTA | MT5C1008DCJ-20L883 | 5962-8959821M7A | MT5C1008CW-55883C | 5962-8959834MXA |
| MT5C1001C-45L/883C | 5962-9231605MTA | MT5C1008EC-20883C | 5962-8959838MUA | MT5C1008CW-55L883C | 5962-8959817MXA |
| MT5C1001DCJ-45/883C | 5962-9231601MUA | MT5C1008EC-20L883C | 5962-8959821MUA | MT5C1008DCJ-55883C | 5962-8959834M7A |
| MT5C1001DCJ-45L/883 | 5962-9231605MUA | MT5C1008ECA-20L883 | 5962-8959821MMA | MT5C1008DCJ-55L883 | 5962-8959817M7A |
| MT5C1001EC-45/883C | 5962-9231601MYA | MT5C1008ECA-20L883 | 5962-8959838MMA | MT5C1008EC-55883C | 5962-8959834MUA |
| MT5C1001EC-45L/883C | 5962-9231605MYA | MT5C1008F-20883C | 5962-8959838MTA | MT5C1008EC-55L883C | 5962-8959817MUA |
| MT5C1001F-45/883C | 5962-9231601MZA | MT5C1008F-20L883C | 5962-8959821MTA | MT5C1008ECA-55L883 | 5962-8959817MMA |
| MT5C1001F-45L/883C | 5962-9231605MZA | MT5C1008SOJ-20883C | 5962-8959838MYA | MT5C1008ECA-55L883 | 5962-8959834MMA |
| MT5C1005C-15/883C | 5962-9161210MXA | MT5C1008SOJ-20L883 | 5962-8959821MYA | MT5C1008F-55883C | 5962-8959834MTA |
| MT5C1005C-15L/883C | 5962-9161209MXA | MT5C1008C-25883C | 5962-8959837MZA | MT5C1008F-55L883C | 5962-8959817MTA |
| MT5C1005DCJ-15/883C | 5962-9161210MMA | MT5C1008C-25L883C | 5962-8959820MZA | MT5C1008SOJ-55883C | 5962-8959834MYA |
| MT5C1005DCJ-15L/883 | 5962-9161209MMA | MT5C1008CW-25883C | 5962-8959837MXA | MT5C1008SOJ-55L883 | 5962-8959817MYA |
| MT5C1005F-15/883C | 5962-9161210MUA | MT5C1008CW-25L883C | 5962-8959820MXA | MT5C1008C-70883C | 5962-8959833MZA |
| MT5C1005F-15L/883C | 5962-9161209MUA | MT5C1008DCJ-25883C | 5962-8959837M7A | MT5C1008C-70L883C | 5962-8959816MZA |
| MT5C1005C-20/883C | 5962-9161208MXA | MT5C1008DCJ-25L883 | 5962-8959820M7A | MT5C1008CW-70883C | 5962-8959833MXA |
| MT5C1005C-20L/883C | 5962-9161207MXA | MT5C1008EC-25883C | 5962-8959837MUA | MT5C1008CW-70L883C | 5962-8959816MXA |
| MT5C1005DCJ-20/883C | 5962-9161208MMA | MT5C1008EC-25L883C | 5962-8959820MUA | MT5C1008DCJ-70883C | 5962-8959833M7A |
| MT5C1005DCJ-20L/883 | 5962-9161207MMA | MT5C1008ECA-25883C | 5962-8959837MMA | MT5C1008DCJ-70L883 | 5962-8959816M7A |
| MT5C1005F-20/883C | 5962-9161208MUA | MT5C1008ECA-25L883 | 5962-8959820MMA | MT5C1008EC-70883C | 5962-8959833MUA |
| MT5C1005F-20L/883C | 5962-9161207MUA | MT5C1008F-25883C | 5962-8959837MTA | MT5C1008EC-70L883C | 5962-8959816MUA |
| MT5C1008C-100883C | 5962-8959831MZA | MT5C1008F-25L883C | 5962-8959820MTA | MT5C1008ECA-70L883 | 5962-8959816MMA |
| MT5C1008C-100L883C | 5962-8959814MZA | MT5C1008SOJ-25883C | 5962-8959837MYA | MT5C1008ECA-70L883 | 5962-8959833MMA |
| MT5C1008CW-100883C | 5962-8959831MXA | MT5C1008SOJ-25L883 | 5962-8959820MYA | MT5C1008F-70883C | 5962-8959833MTA |
| MT5C1008CW-100L883 | 5962-8959814MXA | MT5C1008C-35883C | 5962-8959836MZA | MT5C1008F-70L883C | 5962-8959816MTA |
| MT5C1008DCJ-100883 | 5962-8959831M7A | MT5C1008C-35L883C | 5962-8959819MZA | MT5C1008SOJ-70883C | 5962-8959833MYA |
| MT5C1008DCJ-100L88 | 5962-8959814M7A | MT5C1008CW-35883C | 5962-8959836MXA | MT5C1008SOJ-70L883 | 5962-8959816MYA |
| MT5C1008EC-100883C | 5962-8959831MUA | MT5C1008CW-35L883C | 5962-8959819MXA | MT5C1008C-85883C | 5962-8959832MZA |
| MT5C1008EC-100L883 | 5962-8959814MUA | MT5C1008DCJ-35883C | 5962-8959836M7A | MT5C1008C-85L883C | 5962-8959815MZA |
| MT5C1008ECA-100L88 | 5962-8959814MMA | MT5C1008DCJ-35L883 | 5962-8959819M7A | MT5C1008CW-85883C | 5962-8959832MXA |
| MT5C1008ECA-100L88 | 5962-8959831MMA | MT5C1008EC-35883C | 5962-8959836MUA | MT5C1008CW-85L883C | 5962-8959815MXA |
| MT5C1008F-100883C | 5962-8959831MTA | MT5C1008EC-35L883C | 5962-8959819MUA | MT5C1008DCJ-85883C | 5962-8959832M7A |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

| Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN |
|---|---|---|---|---|---|
| MT5C1008DCJ-85L883 | 5962-8959815M7A | MT5C1009DCJ-20/H | 5962-9669109HYA | MT5C1009ECA-35L883 | 5962-8959828MMA |
| MT5C1008EC-85883C | 5962-8959832MUA | MT5C1009DCJ-20/H | 5962-9669109HYC | MT5C1009F-35883C | 5962-8959828MTA |
| MT5C1008EC-85L883C | 5962-8959815MUA | MT5C1009DCJ-20883C | 5962-8959839M7A | MT5C1009F-35L883C | 5962-8959811MTA |
| MT5C1008ECA-85L883 | 5962-8959815MMA | MT5C1009DCJ-20L/H | 5962-9669116HYA | MT5C1009SOJ-35883C | 5962-8959828MYA |
| MT5C1008ECA-85L883 | 5962-8959832MMA | MT5C1009DCJ-20L/H | 5962-9669116HYC | MT5C1009SOJ-35L883 | 5962-8959811MYA |
| MT5C1008F-85883C | 5962-8959832MTA | MT5C1009DCJ-20L883 | 5962-8959840M7A | MT5C1009C-45883C | 5962-8959827MZA |
| MT5C1008F-85L883C | 5962-8959815MTA | MT5C1009EC-20883C | 5962-8959839MUA | MT5C1009C-45L883C | 5962-8959810MZA |
| MT5C1008SOJ-85883C | 5962-8959832MYA | MT5C1009EC-20L883C | 5962-8959840MUA | MT5C1009CW-45/H | 5962-9669106HTA |
| MT5C1008SOJ-85L883 | 5962-8959815MYA | MT5C1009ECA-20883C | 5962-8959839MMA | MT5C1009CW-45/H | 5962-9669106HTC |
| MT5C1009C-100883C | 5962-8959823MZA | MT5C1009ECA-20L883 | 5962-8959840MMA | MT5C1009CW-45883C | 5962-8959827MXA |
| MT5C1009C-100L883C | 5962-8959806MZA | MT5C1009F-20883C | 5962-8959839MTA | MT5C1009CW-45L/H | 5962-9669113HTA |
| MT5C1009CW-100883C | 5962-8959823MXA | MT5C1009F-20L883C | 5962-8959840MTA | MT5C1009CW-45L/H | 5962-9669113HTC |
| MT5C1009CW-100L883 | 5962-8959806MXA | MT5C1009SOJ-20883C | 5962-8959839MYA | MT5C1009CW-45L883C | 5962-8959810MXA |
| MT5C1009DCJ-100883 | 5962-8959823M7A | MT5C1009SOJ-20L883 | 5962-8959840MYA | MT5C1009DCJ-45/H | 5962-9669106HYA |
| MT5C1009DCJ-100L88 | 5962-8959806M7A | MT5C1009C-25883C | 5962-8959829MZA | MT5C1009DCJ-45/H | 5962-9669106HYC |
| MT5C1009EC-100883C | 5962-8959823MUA | MT5C1009C-25L883C | 5962-8959812MZA | MT5C1009DCJ-45883C | 5962-8959827M7A |
| MT5C1009EC-100L883 | 5962-8959806MUA | MT5C1009CW-25/H | 5962-9669108HTA | MT5C1009DCJ-45L/H | 5962-9669113HYA |
| MT5C1009ECA-100L88 | 5962-8959806MMA | MT5C1009CW-25/H | 5962-9669108HTC | MT5C1009DCJ-45L/H | 5962-9669113HYC |
| MT5C1009ECA-100L88 | 5962-8959823MMA | MT5C1009CW-25883C | 5962-8959829MXA | MT5C1009DCJ-45L883 | 5962-8959810M7A |
| MT5C1009F-100883C | 5962-8959823MTA | MT5C1009CW-25L/H | 5962-9669115HTA | MT5C1009EC-45883C | 5962-8959827MUA |
| MT5C1009F-100L883C | 5962-8959806MTA | MT5C1009CW-25L/H | 5962-9669115HTC | MT5C1009EC-45L883C | 5962-8959810MUA |
| MT5C1009SOJ-100883 | 5962-8959823MYA | MT5C1009CW-25L883C | 5962-8959812MXA | MT5C1009ECA-45L883 | 5962-8959810MMA |
| MT5C1009SOJ-100L88 | 5962-8959806MYA | MT5C1009DCJ-25/H | 5962-9669108HYA | MT5C1009ECA-45L883 | 5962-8959827MMA |
| MT5C1009C-120883C | 5962-8959822MZA | MT5C1009DCJ-25/H | 5962-9669108HYC | MT5C1009F-45883C | 5962-8959827MTA |
| MT5C1009C-120L883C | 5962-8959805MZA | MT5C1009DCJ-25883C | 5962-8959829M7A | MT5C1009F-45L883C | 5962-8959810MTA |
| MT5C1009CW-120883C | 5962-8959822MXA | MT5C1009DCJ-25L/H | 5962-9669115HYA | MT5C1009SOJ-45883C | 5962-8959827MYA |
| MT5C1009CW-120L883 | 5962-8959805MXA | MT5C1009DCJ-25L/H | 5962-9669115HYC | MT5C1009SOJ-45L883 | 5962-8959810MYA |
| MT5C1009DCJ-120883 | 5962-8959822M7A | MT5C1009DCJ-25L883 | 5962-8959812M7A | MT5C1009C-55883C | 5962-8959826MZA |
| MT5C1009DCJ-120L88 | 5962-8959805M7A | MT5C1009EC-25883C | 5962-8959829MUA | MT5C1009C-55L883C | 5962-8959809MZA |
| MT5C1009EC-120883C | 5962-8959822MUA | MT5C1009EC-25L883C | 5962-8959812MUA | MT5C1009CW-55/H | 5962-9669105HTA |
| MT5C1009EC-120L883 | 5962-8959805MUA | MT5C1009ECA-25L883 | 5962-8959812MMA | MT5C1009CW-55/H | 5962-9669105HTC |
| MT5C1009ECA-120L88 | 5962-8959805MMA | MT5C1009ECA-25L883 | 5962-8959829MMA | MT5C1009CW-55883C | 5962-8959826MXA |
| MT5C1009ECA-120L88 | 5962-8959822MMA | MT5C1009F-25883C | 5962-8959829MTA | MT5C1009CW-55L/H | 5962-9669112HTA |
| MT5C1009F-120883C | 5962-8959822MTA | MT5C1009F-25L883C | 5962-8959812MTA | MT5C1009CW-55L/H | 5962-9669112HTC |
| MT5C1009F-120L883C | 5962-8959805MTA | MT5C1009SOJ-25883C | 5962-8959829MYA | MT5C1009CW-55L883C | 5962-8959809MXA |
| MT5C1009SOJ-120883 | 5962-8959822MYA | MT5C1009SOJ-25L883 | 5962-8959812MYA | MT5C1009DCJ-55/H | 5962-9669105HYA |
| MT5C1009SOJ-120L88 | 5962-8959805MYA | MT5C1009C-35883C | 5962-8959828MZA | MT5C1009DCJ-55/H | 5962-9669105HYC |
| MT5C1009CW-17/H | 5962-9669110HTA | MT5C1009C-35L883C | 5962-8959811MZA | MT5C1009DCJ-55883C | 5962-8959826M7A |
| MT5C1009CW-17/H | 5962-9669110HTC | MT5C1009CW-35/H | 5962-9669107HTA | MT5C1009DCJ-55L | 5962-8959809M7A |
| MT5C1009CW-17L/H | 5962-9669117HTA | MT5C1009CW-35/H | 5962-9669107HTC | MT5C1009DCJ-55L/H | 5962-9669112HYA |
| MT5C1009CW-17L/H | 5962-9669117HTC | MT5C1009CW-35883C | 5962-8959828MXA | MT5C1009DCJ-55L/H | 5962-9669112HYC |
| MT5C1009DCJ-17/H | 5962-9669110HYA | MT5C1009CW-35L/H | 5962-9669114HTA | MT5C1009EC-55883C | 5962-8959826MUA |
| MT5C1009DCJ-17/H | 5962-9669110HYC | MT5C1009CW-35L/H | 5962-9669114HTC | MT5C1009EC-55L883C | 5962-8959809MUA |
| MT5C1009DCJ-17L/H | 5962-9669117HYA | MT5C1009CW-35L883C | 5962-8959811MXA | MT5C1009ECA-55L883 | 5962-8959809MMA |
| MT5C1009DCJ-17L/H | 5962-9669117HYC | MT5C1009DCJ-35/H | 5962-9669107HYA | MT5C1009ECA-55L883 | 5962-8959826MMA |
| MT5C1009C-20883C | 5962-8959839MZA | MT5C1009DCJ-35/H | 5962-9669107HYC | MT5C1009F-55883C | 5962-8959826MTA |
| MT5C1009C-20L883C | 5962-8959840MZA | MT5C1009DCJ-35883C | 5962-8959828M7A | MT5C1009F-55L883C | 5962-8959809MTA |
| MT5C1009CW-20/H | 5962-9669109HTA | MT5C1009DCJ-35L/H | 5962-9669114HYA | MT5C1009SOJ-55883C | 5962-8959826MYA |
| MT5C1009CW-20/H | 5962-9669109HTC | MT5C1009DCJ-35L/H | 5962-9669114HYC | MT5C1009SOJ-55L883 | 5962-8959809MYA |
| MT5C1009CW-20883C | 5962-8959839MXA | MT5C1009DCJ-35L883 | 5962-8959811M7A | MT5C1009C-70883C | 5962-8959825MZA |
| MT5C1009CW-20L/H | 5962-9669116HTA | MT5C1009EC-35883C | 5962-8959828MUA | MT5C1009C-70L883C | 5962-8959808MZA |
| MT5C1009CW-20L/H | 5962-9669116HTC | MT5C1009EC-35L883C | 5962-8959811MUA | MT5C1009CW-70883C | 5962-8959825MXA |
| MT5C1009CW-20L883C | 5962-8959840MXA | MT5C1009ECA-35L883 | 5962-8959811MMA | MT5C1009CW-70L883C | 5962-8959808MXA |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

| Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN |
|---|---|---|---|---|---|
| MT5C1009DCJ-70883C | 5962-8959825M7A | HS1-5104ARH-Q | 5962R9569001VCC | ACT-S512K32N-025F2 | 5962-9461108HMA |
| MT5C1009DCJ-70L883 | 5962-8959808M7A | HS1-5104ARH-T | 5962R9569001TCC | ACT-S512K32N-025F2 | 5962-9461108HMC |
| MT5C1009EC-70883C | 5962-8959825MUA | HS9-5104ARH-Q | 5962R9569001VXC | ACT-S512K32N-025P7 | 5962-9461108HTA |
| MT5C1009EC-70L883C | 5962-8959808MUA | HS9-5104ARH-T | 5962R9569001TXC | ACT-S512K32N-025P7 | 5962-9461108HTC |
| MT5C1009ECA-70L883 | 5962-8959808MMA | 5104 (GEN) | 5962-9669401QVC | ACT-S512K32N-025F1 | 5962-9461108HYA |
| MT5C1009ECA-70L883 | 5962-8959825MMA | 5104 (GEN) | 5962-9669401QXC | ACT-S512K32N-025F1 | 5962-9461108HYC |
| MT5C1009F-70883C | 5962-8959825MTA | GP511 (GEN) | 5962R9673601VXC | ACT-S512K32N-025P1 | 5962-9461108HXA |
| MT5C1009F-70L883C | 5962-8959808MTA | HA5111 (GEN) | 5962-89631012A | ACT-S512K32N-025P1 | 5962-9461108HXC |
| MT5C1009SOJ-70883C | 5962-8959825MYA | HA5111 (GEN) | 5962-8963101GC | ACT-S512K32N-035F2 | 5962-9461107HMA |
| MT5C1009SOJ-70L883 | 5962-8959808MYA | HA5111 (GEN) | 5962-8963101PA | ACT-S512K32N-035F2 | 5962-9461107HMC |
| MT5C1009C-85883C | 5962-8959824MZA | HA5112 (GEN) | 5962-89632012A | ACT-S512K32N-035P7 | 5962-9461107HTA |
| MT5C1009C-85L883C | 5962-8959807MZA | HA5112 (GEN) | 5962-8963201GC | ACT-S512K32N-035P7 | 5962-9461107HTC |
| MT5C1009CW-85883C | 5962-8959824MXA | HA5112 (GEN) | 5962-8963201PA | ACT-S512K32N-035F1 | 5962-9461107HYA |
| MT5C1009CW-85L883C | 5962-8959807MXA | 5114 (GEN) | 5962D9669501VVC | ACT-S512K32N-035F1 | 5962-9461107HYC |
| MT5C1009DCJ-85883C | 5962-8959824M7A | 5114 (GEN) | 5962D9669501VXC | ACT-S512K32N-035P1 | 5962-9461107HXA |
| MT5C1009DCJ-85L883 | 5962-8959807M7A | HA1-5114/883 | 5962-8963401CA | ACT-S512K32N-035P1 | 5962-9461107HXC |
| MT5C1009EC-85883C | 5962-8959824MUA | HA4-5114/883 | 5962-89634012A | ACT-S512K32N-045P7 | 5962-9461106HTA |
| MT5C1009EC-85L883C | 5962-8959807MUA | 5114 (GEN) | 5962-9669501QVC | ACT-S512K32N-045P7 | 5962-9461106HTC |
| MT5C1009ECA-85L883 | 5962-8959824MMA | 5114 (GEN) | 5962-9669501QXC | ACT-S512K32N-045F1 | 5962-9461106HYA |
| MT5C1009ECA-85L883 | 5962-8959807MMA | HAA0-51150R4551 | 5962-97A0101V9A | ACT-S512K32N-045F1 | 5962-9461106HYC |
| MT5C1009F-85883C | 5962-8959824MTA | HAA0-51155R4553 | 5962-97A0701V9A | ACT-S512K32N-045P1 | 5962-9461106HXA |
| MT5C1009F-85L883C | 5962-8959807MTA | HAA0-51159R4555 | 5962-97A0901V9A | ACT-S512K32N-045P1 | 5962-9461106HXC |
| MT5C1009SOJ-85883C | 5962-8959824MYA | HAA9-51159R4555 | 5962-97A0901VXC | ACT-S512K32N-045F2 | 5962-9461106HMA |
| MT5C1009SOJ-85L883 | 5962-8959807MYA | IH5116 (GEN) | 5962-8513104XA | ACT-S512K32N-045F2 | 5962-9461106HMC |
| HA4-5101/883 | 5962-89635012A | HCPL-5121 | 5962-0420401HPC | ACT-S512K32N-055P7 | 5962-9461105HTA |
| HA5101 (GEN) | 5962-8963501GA | HCPL-5121-100 | 5962-0420401HYA | ACT-S512K32N-055P7 | 5962-9461105HTC |
| HA7-5101/883 | 5962-8963501PA | HCPL-5121-100 | 5962-0420401HYC | ACT-S512K32N-055F1 | 5962-9461105HYA |
| MN5101H/B | 5962-9207302HXA | HCPL-5121-200 | 5962-0420401HPA | ACT-S512K32N-055F1 | 5962-9461105HYC |
| MN5101H/B | 5962-9207302HXC | HCPL-5121-300 | 5962-0420401HXA | ACT-S512K32N-055P1 | 5962-9461105HXA |
| SEI5101A-SD8B | 5962-9169101MXA | WSF512K16-39G2Q | 5962-9690102HMC | ACT-S512K32N-055P1 | 5962-9461105HXC |
| SEI5101A-SD8B | 5962-9169101QXC | WSF512K16-39G2QA | 5962-9690102HMA | ACT-S512K32N-055F2 | 5962-9461105HMA |
| SEI5101A-SE8B | 5962-9169101M3A | WSF512K16-39H2Q | 5962-9690102HXC | ACT-S512K32N-055F2 | 5962-9461105HMC |
| SEI5101A-SE8B | 5962-9169101Q3C | WSF512K16-39H2QA | 5962-9690102HXA | ACT-F512K32A-060P7 | 5962-9461205H4A |
| SEI5101A-TD8B | 5962-9169102MXA | WSF512K16-72G2Q | 5962-9690101HMC | ACT-F512K32A-060P7 | 5962-9461205H4C |
| SEI5101A-TD8B | 5962-9169102QXC | WSF512K16-72G2QA | 5962-9690101HMA | ACT-F512K32N-060F5 | 5962-9461205HMA |
| SEI5101A-TE8B | 5962-9169102M3A | WSF512K16-72H2Q | 5962-9690101HXC | ACT-F512K32N-060F5 | 5962-9461205HMC |
| SEI5101A-TE8B | 5962-9169102Q3C | WSF512K16-72H2QA | 5962-9690101HXA | ACT-F512K32N-060F5U | 5962-9461205HYC |
| HA2-5102/883 | 5962-8954801GC | ACT-S512K32N-017F1 | 5962-9461110HYA | ACT-F512K32N-060P3 | 5962-9461205HXA |
| HA4-5102/883 | 5962-89548012A | ACT-S512K32N-017F1 | 5962-9461110HYC | ACT-F512K32N-060P3 | 5962-9461205HXC |
| HA7-5102/883 | 5962-8954801PA | ACT-S512K32N-017F2 | 5962-9461110HMA | ACT-F512K32N-060P7 | 5962-9461205HUA |
| SEI5102A-SDB | 5962-9169201MXA | ACT-S512K32N-017F2 | 5962-9461110HMC | ACT-F512K32N-060P7 | 5962-9461205HUC |
| SEI5102A-SDB | 5962-9169201QXC | ACT-S512K32N-017P1 | 5962-9461110HXA | ACT-F512K32A-070P7 | 5962-9461204H4A |
| SEI5102A-SEB | 5962-9169201M3A | ACT-S512K32N-017P1 | 5962-9461110HXC | ACT-F512K32A-070P7 | 5962-9461204H4C |
| SEI5102A-SEB | 5962-9169201Q3C | ACT-S512K32N-017P7 | 5962-9461110HTA | ACT-F512K32N-070F5 | 5962-9461204HMA |
| SEI5102A-TDB | 5962-9169202MXA | ACT-S512K32N-017P7 | 5962-9461110HTC | ACT-F512K32N-070F5 | 5962-9461204HMC |
| SEI5102A-TDB | 5962-9169202QXC | ACT-S512K32N-020F2 | 5962-9461109HMA | ACT-F512K32N-070F5U | 5962-9461204HYC |
| SEI5102A-TEB | 5962-9169202M3A | ACT-S512K32N-020F2 | 5962-9461109HMC | ACT-F512K32N-070P3 | 5962-9461204HXA |
| SEI5102A-TEB | 5962-9169202Q3C | ACT-S512K32N-020P7 | 5962-9461109HTA | ACT-F512K32N-070P3 | 5962-9461204HXC |
| 5104 (GEN) | 5962D9669401VVC | ACT-S512K32N-020P7 | 5962-9461109HTC | ACT-F512K32N-070P7 | 5962-9461204HUA |
| 5104 (GEN) | 5962D9669401VXC | ACT-S512K32N-020F1 | 5962-9461109HYA | ACT-F512K32N-070P7 | 5962-9461204HUC |
| HA1-5104/883 | 5962-8850201CA | ACT-S512K32N-020F1 | 5962-9461109HYC | ACT-F512K32A-090P7 | 5962-9461203H4A |
| HA4-5104/883 | 5962-88502012A | ACT-S512K32N-020P1 | 5962-9461109HXA | ACT-F512K32A-090P7 | 5962-9461203H4C |
| HS0-5104ARH-Q | 5962R9569001V9A | ACT-S512K32N-020P1 | 5962-9461109HXC | ACT-F512K32N-090F5 | 5962-9461203HMA |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART II, Listed By Generic PIN

| Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN |
|---|---|---|---|---|---|
| ACT-F512K32N-090F5 | 5962-9461203HMC | WF512K32-120G1TQ5 | 5962-9461202HBC | AS8F512K32P-150/883 | 5962-9461201H4C |
| ACT-F512K32N-090F5U | 5962-9461203HYC | WF512K32-120G1UQ5 | 5962-9461202H9A | AS8F512K32Q-150/883 | 5962-9461201HMA |
| ACT-F512K32N-090P3 | 5962-9461203HXA | WF512K32-120G1UQ5 | 5962-9461202H9C | AS8F512K32Q-150/883 | 5962-9461201HMC |
| ACT-F512K32N-090P3 | 5962-9461203HXC | WF512K32-120G2LQ5 | 5962-9461202HAA | WF512K32-150G1TQ5 | 5962-9461201HBA |
| ACT-F512K32N-090P7 | 5962-9461203HUA | WF512K32-120G2LQ5 | 5962-9461202HAC | WF512K32-150G1TQ5 | 5962-9461201HBC |
| ACT-F512K32N-090P7 | 5962-9461203HUC | WF512K32-120G2Q5 | 5962-9461202HMA | WF512K32-150G1UQ5 | 5962-9461201H9A |
| WF512K32-90G2LQ5 | 5962-9461203HAA | WF512K32-120G2Q5 | 5962-9461202HMC | WF512K32-150G1UQ5 | 5962-9461201H9C |
| WF512K32-90G2LQ5 | 5962-9461203HAC | WF512K32-120G2UQ5 | 5962-9461202HZA | WF512K32-150G2LQ5 | 5962-9461201HAA |
| 512K32-100 (GEN) | 5962-9461102HXA | WF512K32-120G2UQ5 | 5962-9461202HZC | WF512K32-150G2LQ5 | 5962-9461201HAC |
| WS512K32-100G2Q | 5962-9461102HMA | WF512K32-120G4TQ5 | 5962-9461202HTC | WF512K32-150G2Q5 | 5962-9461201HMA |
| WS512K32-100G2Q | 5962-9461102HMC | WF512K32F-120G4Q5 | 5962-9461202HNA | WF512K32-150G2QG | 5962-9461201HMC |
| WS512K32-100G4Q | 5962-9461102HYC | WF512K32F-120G4Q5 | 5962-9461202HNC | WF512K32-150G2UQ5 | 5962-9461201HZA |
| WS512K32F-100G4Q | 5962-9562402HNC | WF512K32N-120H1Q5 | 5962-9461202H4A | WF512K32-150G2UQ5 | 5962-9461201HZC |
| WS512K32N-100HQ | 5962-9461102HUA | WF512K32N-120H1Q5 | 5962-9461202H4C | WF512K32-150G4TQ5 | 5962-9461201HTC |
| WS512K32N-100HQ | 5962-9461102HUC | WF512K32N-120HQ5 | 5962-9461202HUA | WF512K32F-150G4Q5 | 5962-9461201HNA |
| AS8F512K32Q1-120/88 | 5962-9461202HAA | WF512K32N-120HQ5 | 5962-9461202HUC | WF512K32F-150G4Q5 | 5962-9461201HNC |
| AS8F512K32Q1-120/88 | 5962-9461202HAC | WS512K32-120G2Q | 5962-9461101HMA | WF512K32N-150H1Q5 | 5962-9461201H4A |
| AS8F512K32Q1-150/88 | 5962-9461201HAA | WS512K32-120G2Q | 5962-9461101HMC | WF512K32N-150H1Q5 | 5962-9461201H4C |
| AS8F512K32Q1-150/88 | 5962-9461201HAC | WS512K32-120G4Q | 5962-9461101HYC | WF512K32N-150HQ5 | 5962-9461201HUA |
| WS512K32-12G1TQ | 5962-9461120HBA | WS512K32F-120G4Q | 5962-9562401HNC | WF512K32N-150HQ5 | 5962-9461201HUC |
| WS512K32-12G1TQ | 5962-9461120HBC | WS512K32N-120HQ | 5962-9461101HUA | AS8F512K32Q1-60/883 | 5962-9461205HAA |
| WS512K32-12G1UQ | 5962-9461120H9A | WS512K32N-120HQ | 5962-9461101HUC | AS8F512K32Q1-60/883 | 5962-9461205HAC |
| WS512K32-12G1UQ | 5962-9461120H9C | WS512K32-15G1TQ | 5962-9461119HBA | 512K32-17 (GEN) | 5962-9461116HXA |
| WS512K32-12G2LQ | 5962-9461120HAA | WS512K32-15G1TQ | 5962-9461119HBC | WS512K32-17G1TQ | 5962-9461110HBA |
| WS512K32-12G2LQ | 5962-9461120HAC | WS512K32-15G1UQ | 5962-9461119H9A | WS512K32-17G1TQ | 5962-9461110HBC |
| WS512K32-12G2Q | 5962-9461120HMA | WS512K32-15G1UQ | 5962-9461119H9C | WS512K32-17G1UQ | 5962-9461110H9A |
| WS512K32-12G2Q | 5962-9461120HMC | WS512K32-15G2LQ | 5962-9461119HAA | WS512K32-17G1UQ | 5962-9461110H9C |
| WS512K32D-12G1TQ | 5962-9461118HBA | WS512K32-15G2LQ | 5962-9461119HAC | WS512K32-17G2LQ | 5962-9461110HAA |
| WS512K32D-12G1TQ | 5962-9461118HBC | WS512K32-15G2Q | 5962-9461119HMA | WS512K32-17G2LQ | 5962-9461110HAC |
| WS512K32D-12G1UQ | 5962-9461118H9A | WS512K32-15G2Q | 5962-9461119HMC | WS512K32-17G2Q | 5962-9461110HMA |
| WS512K32D-12G1UQ | 5962-9461118H9C | WS512K32D-15G1TQ | 5962-9461117HBA | WS512K32-17G2Q | 5962-9461110HMC |
| WS512K32D-12G2LQ | 5962-9461118HAA | WS512K32D-15G1TQ | 5962-9461117HBC | WS512K32-17G4TQ | 5962-9461110HYC |
| WS512K32D-12G2LQ | 5962-9461118HAC | WS512K32D-15G1UQ | 5962-9461117H9A | WS512K32D-17G1TQ | 5962-9461116HBA |
| WS512K32D-12G2Q | 5962-9461118HMA | WS512K32D-15G1UQ | 5962-9461117H9C | WS512K32D-17G1TQ | 5962-9461116HBC |
| WS512K32D-12G2Q | 5962-9461118HMC | WS512K32D-15G2LQ | 5962-9461117HAA | WS512K32D-17G1UQ | 5962-9461116H9A |
| WS512K32N-12H1Q | 5962-9461120HTA | WS512K32D-15G2LQ | 5962-9461117HAC | WS512K32D-17G1UQ | 5962-9461116H9C |
| WS512K32N-12H1Q | 5962-9461120HTC | WS512K32D-15G2Q | 5962-9461117HMA | WS512K32D-17G2LQ | 5962-9461116HAA |
| WS512K32ND-12H1Q | 5962-9461118HTA | WS512K32D-15G2Q | 5962-9461117HMC | WS512K32D-17G2LQ | 5962-9461116HAC |
| WS512K32ND-12H1Q | 5962-9461118HTC | WS512K32N-15H1Q | 5962-9461119HTA | WS512K32D-17G2Q | 5962-9461116HMA |
| 512K32-120 (GEN) | 5962-9461101HXA | WS512K32N-15H1Q | 5962-9461119HTC | WS512K32D-17G2Q | 5962-9461116HMC |
| ACT-F512K32A-120P7 | 5962-9461202H4A | WS512K32ND-15H1Q | 5962-9461117HTA | WS512K32D-17G4TQ | 5962-9461116HYC |
| ACT-F512K32A-120P7 | 5962-9461202H4C | WS512K32ND-15H1Q | 5962-9461117HTC | WS512K32N-17H1Q | 5962-9461110HTA |
| ACT-F512K32N-120F5 | 5962-9461202HMA | ACT-F512K32A-150P7 | 5962-9461201H4A | WS512K32N-17H1Q | 5962-9461110HTC |
| ACT-F512K32N-120F5 | 5962-9461202HMC | ACT-F512K32A-150P7 | 5962-9461201H4C | WS512K32ND-17H1Q | 5962-9461116HTA |
| ACT-F512K32N-120P3 | 5962-9461202HXA | ACT-F512K32N-120F5U | 5962-9461202HYC | WS512K32ND-17H1Q | 5962-9461116HTC |
| ACT-F512K32N-120P3 | 5962-9461202HXC | ACT-F512K32N-150F5 | 5962-9461201HMA | AS8F512K32Q1-70/883 | 5962-9461204HAA |
| ACT-F512K32N-120P7 | 5962-9461202HUA | ACT-F512K32N-150F5 | 5962-9461201HMC | AS8F512K32Q1-70/883 | 5962-9461204HAC |
| ACT-F512K32N-120P7 | 5962-9461202HUC | ACT-F512K32N-150F5U | 5962-9461201HYC | AS8F512K32Q1-90/883 | 5962-9461203HAA |
| AS8F512K32P-120/883 | 5962-9461202H4A | ACT-F512K32N-150P3 | 5962-9461201HXA | AS8F512K32Q1-90/883 | 5962-9461203HAC |
| AS8F512K32P-120/883 | 5962-9461202H4C | ACT-F512K32N-150P3 | 5962-9461201HXC | 512K32-20 (GEN) | 5962-9461115HXA |
| AS8F512K32Q-120/883 | 5962-9461202HMA | ACT-F512K32N-150P7 | 5962-9461201HUA | WS512K32-20G1TQ | 5962-9461109HBA |
| AS8F512K32Q-120/883 | 5962-9461202HMC | ACT-F512K32N-150P7 | 5962-9461201HUC | WS512K32-20G1TQ | 5962-9461109HBC |
| WF512K32-120G1TQ5 | 5962-9461202HBA | AS8F512K32P-150/883 | 5962-9461201H4A | WS512K32-20G1UQ | 5962-9461109H9A |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART II, Listed By Generic PIN

| Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN |
|---|---|---|---|---|---|
| WS512K32-20G1UQ | 5962-9461109H9C | WS512K32-35G2Q | 5962-9461107HMC | WS512K32D-55G1TQ | 5962-9461111HBC |
| WS512K32-20G2LQ | 5962-9461109HAA | WS512K32-35G4TQ | 5962-9461107HYC | WS512K32D-55G1UQ | 5962-9461111H9A |
| WS512K32-20G2LQ | 5962-9461109HAC | WS512K32D-35G1TQ | 5962-9461113HBA | WS512K32D-55G1UQ | 5962-9461111H9C |
| WS512K32-20G2Q | 5962-9461109HMA | WS512K32D-35G1TQ | 5962-9461113HBC | WS512K32D-55G2LQ | 5962-9461111HAA |
| WS512K32-20G2Q | 5962-9461109HMC | WS512K32D-35G1UQ | 5962-9461113H9A | WS512K32D-55G2LQ | 5962-9461111HAC |
| WS512K32-20G4TQ | 5962-9461109HYC | WS512K32D-35G1UQ | 5962-9461113H9C | WS512K32D-55G2Q | 5962-9461111HMA |
| WS512K32D-20G1TQ | 5962-9461115HBA | WS512K32D-35G2LQ | 5962-9461113HAA | WS512K32D-55G2Q | 5962-9461111HMC |
| WS512K32D-20G1TQ | 5962-9461115HBC | WS512K32D-35G2LQ | 5962-9461113HAC | WS512K32D-55G4TQ | 5962-9461111HYC |
| WS512K32D-20G1UQ | 5962-9461115H9A | WS512K32D-35G2Q | 5962-9461113HMA | WS512K32F-55G4Q | 5962-9562405HNC |
| WS512K32D-20G1UQ | 5962-9461115H9C | WS512K32D-35G2Q | 5962-9461113HMC | WS512K32N-55H1Q | 5962-9461105HTA |
| WS512K32D-20G2LQ | 5962-9461115HAA | WS512K32D-35G4TQ | 5962-9461113HYC | WS512K32N-55H1Q | 5962-9461105HTC |
| WS512K32D-20G2LQ | 5962-9461115HAC | WS512K32F-35G4Q | 5962-9562407HNC | WS512K32ND-55H1Q | 5962-9461111HTA |
| WS512K32D-20G2Q | 5962-9461115HMA | WS512K32M-35G4Q | 5962-9562411HNC | WS512K32ND-55H1Q | 5962-9461111HTC |
| WS512K32D-20G2Q | 5962-9461115HMC | WS512K32N-35H1Q | 5962-9461107HTA | AS8F512K32Q-60/883C | 5962-9461205HMA |
| WS512K32D-20G4TQ | 5962-9461115HYC | WS512K32N-35H1Q | 5962-9461107HTC | AS8F512K32Q-60/883C | 5962-9461205HMC |
| WS512K32F-20G4Q | 5962-9562409HNC | WS512K32ND-35H1Q | 5962-9461113HTA | WF512K32-60G1TQ5 | 5962-9461205HBA |
| WS512K32N-20H1Q | 5962-9461109HTA | WS512K32ND-35H1Q | 5962-9461113HTC | WF512K32-60G1TQ5 | 5962-9461205HBC |
| WS512K32N-20H1Q | 5962-9461109HTC | 512K32-45 (GEN) | 5962-9461112HXA | WF512K32-60G1UQ5 | 5962-9461205H9A |
| WS512K32ND-20H1Q | 5962-9461115HTA | WS512K32-45G1TQ | 5962-9461106HBA | WF512K32-60G1UQ5 | 5962-9461205H9C |
| WS512K32ND-20H1Q | 5962-9461115HTC | WS512K32-45G1TQ | 5962-9461106HBC | WF512K32-60G2LQ5 | 5962-9461205HAA |
| 512K32-25 (GEN) | 5962-9461114HXA | WS512K32-45G1UQ | 5962-9461106H9A | WF512K32-60G2LQ5 | 5962-9461205HAC |
| WS512K32-25G1TQ | 5962-9461108HBA | WS512K32-45G1UQ | 5962-9461106H9C | WF512K32-60G2Q5 | 5962-9461205HMA |
| WS512K32-25G1TQ | 5962-9461108HBC | WS512K32-45G2LQ | 5962-9461106HAA | WF512K32-60G2Q5 | 5962-9461205HMC |
| WS512K32-25G1UQ | 5962-9461108H9A | WS512K32-45G2LQ | 5962-9461106HAC | WF512K32-60G2UQ5 | 5962-9461205HZA |
| WS512K32-25G1UQ | 5962-9461108H9C | WS512K32-45G2Q | 5962-9461106HMA | WF512K32-60G2UQ5 | 5962-9461205HZC |
| WS512K32-25G2LQ | 5962-9461108HAA | WS512K32-45G2Q | 5962-9461106HMC | WF512K32-60G4TQ5 | 5962-9461205HTC |
| WS512K32-25G2LQ | 5962-9461108HAC | WS512K32-45G4TQ | 5962-9461106HYC | WF512K32F-60G4Q5 | 5962-9461205HNA |
| WS512K32-25G2Q | 5962-9461108HMA | WS512K32D-45G1TQ | 5962-9461112HBA | WF512K32F-60G4Q5 | 5962-9461205HNC |
| WS512K32-25G2Q | 5962-9461108HMC | WS512K32D-45G1TQ | 5962-9461112HBC | WF512K32N-60H1Q5 | 5962-9461205H4A |
| WS512K32-25G4TQ | 5962-9461108HYC | WS512K32D-45G1UQ | 5962-9461112H9A | WF512K32N-60H1Q5 | 5962-9461205H4C |
| WS512K32D-25G1TQ | 5962-9461114HBA | WS512K32D-45G1UQ | 5962-9461112H9C | WF512K32N-60HQ5 | 5962-9461205HUA |
| WS512K32D-25G1TQ | 5962-9461114HBC | WS512K32D-45G2LQ | 5962-9461112HAA | WF512K32N-60HQ5 | 5962-9461205HUC |
| WS512K32D-25G1UQ | 5962-9461114H9A | WS512K32D-45G2LQ | 5962-9461112HAC | 512K32-70 (GEN) | 5962-9461104HXA |
| WS512K32D-25G1UQ | 5962-9461114H9C | WS512K32D-45G2Q | 5962-9461112HMA | AS8F512K32P-70/883C | 5962-9461204H4A |
| WS512K32D-25G2LQ | 5962-9461114HAA | WS512K32D-45G2Q | 5962-9461112HMC | AS8F512K32P-70/883C | 5962-9461204H4C |
| WS512K32D-25G2LQ | 5962-9461114HAA | WS512K32D-45G4TQ | 5962-9461112HYC | AS8F512K32Q-70/883C | 5962-9461204HMA |
| WS512K32D-25G2Q | 5962-9461114HMA | WS512K32F-45G4Q | 5962-9562406HNC | AS8F512K32Q-70/883C | 5962-9461204HMC |
| WS512K32D-25G2Q | 5962-9461114HMC | WS512K32M-45G4Q | 5962-9562410HNC | WF512K32-70G1TQ5 | 5962-9461204HBA |
| WS512K32D-25G4TQ | 5962-9461114HYC | WS512K32N-45H1Q | 5962-9461106HTA | WF512K32-70G1TQ5 | 5962-9461204HBC |
| WS512K32F-25G4Q | 5962-9562408HNC | WS512K32N-45H1Q | 5962-9461106HTC | WF512K32-70G1UQ5 | 5962-9461204H9A |
| WS512K32M-25G4Q | 5962-9562412HNC | WS512K32ND-45H1Q | 5962-9461112HTA | WF512K32-70G1UQ5 | 5962-9461204H9C |
| WS512K32N-25H1Q | 5962-9461108HTA | WS512K32ND-45H1Q | 5962-9461112HTC | WF512K32-70G2LQ5 | 5962-9461204HAA |
| WS512K32N-25H1Q | 5962-9461108HTC | 512K32-55 (GEN) | 5962-9461111HXA | WF512K32-70G2LQ5 | 5962-9461204HAC |
| WS512K32ND-25H1Q | 5962-9461114HTA | WS512K32-55G1TQ | 5962-9461105HBA | WF512K32-70G2Q5 | 5962-9461204HMA |
| WS512K32ND-25H1Q | 5962-9461114HTC | WS512K32-55G1TQ | 5962-9461105HBC | WF512K32-70G2Q5 | 5962-9461204HMC |
| 512K32-35 (GEN) | 5962-9461113HXA | WS512K32-55G1UQ | 5962-9461105H9A | WF512K32-70G2UQ5 | 5962-9461204HZA |
| WS512K32-35G1TQ | 5962-9461107HBA | WS512K32-55G1UQ | 5962-9461105H9C | WF512K32-70G2UQ5 | 5962-9461204HZC |
| WS512K32-35G1TQ | 5962-9461107HBC | WS512K32-55G2LQ | 5962-9461105HAA | WF512K32-70G4TQ5 | 5962-9461204HTC |
| WS512K32-35G1UQ | 5962-9461107H9A | WS512K32-55G2LQ | 5962-9461105HAC | WF512K32F-70G4Q5 | 5962-9461204HNA |
| WS512K32-35G1UQ | 5962-9461107H9C | WS512K32-55G2Q | 5962-9461105HMA | WF512K32F-70G4Q5 | 5962-9461204HNC |
| WS512K32-35G2LQ | 5962-9461107HAA | WS512K32-55G2Q | 5962-9461105HMC | WF512K32N-70H1Q5 | 5962-9461204H4A |
| WS512K32-35G2LQ | 5962-9461107HAC | WS512K32-55G4TQ | 5962-9461105HYC | WF512K32N-70H1Q5 | 5962-9461204H4C |
| WS512K32-35G2Q | 5962-9461107HMA | WS512K32D-55G1TQ | 5962-9461111HBA | WF512K32N-70HQ5 | 5962-9461204HUA |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

| Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN |
|---|---|---|---|---|---|
| WF512K32N-70HQ5 | 5962-9461204HUC | ACT-S512K8N-025F4Q | 5962-9561308HZC | WMS512K8-12C | 5962-9561329HYC |
| WS512K32-70G2Q | 5962-9461104HMA | ACT-S512K8N-025P4Q | 5962-9561308HYA | WMS512K8-12DE | 5962-9561329HTA |
| WS512K32-70G2Q | 5962-9461104HMC | ACT-S512K8N-025P4Q | 5962-9561308HYC | WMS512K8-12DE | 5962-9561329HTC |
| WS512K32-70G4Q | 5962-9461104HYC | ACT-S512K8M-035P4Q | 5962-9561312HYA | WMS512K8-12DJ | 5962-9561329HZA |
| WS512K32F-70G4Q | 5962-9562404HNC | ACT-S512K8M-035P4Q | 5962-9561312HYC | WMS512K8-12DJ | 5962-9561329HZC |
| WS512K32N-70HQ | 5962-9461104HUA | ACT-S512K8N-035F3Q | 5962-9561307HUA | WMS512K8-12F | 5962-9561329HXC |
| WS512K32N-70HQ | 5962-9461104HUC | ACT-S512K8N-035F3Q | 5962-9561307HUC | WMS512K8-12FT | 5962-9561329HUA |
| 512K32-85 (GEN) | 5962-9461103HXA | ACT-S512K8N-035F4Q | 5962-9561307HZA | WMS512K8-12FT | 5962-9561329HUC |
| WS512K32-85G2Q | 5962-9461103HMA | ACT-S512K8N-035F4Q | 5962-9561307HZC | WMS512K8L-12C | 5962-9561328HYA |
| WS512K32-85G2Q | 5962-9461103HMC | ACT-S512K8N-035P4Q | 5962-9561307HYA | WMS512K8L-12C | 5962-9561328HYC |
| WS512K32-85G4Q | 5962-9461103HYC | ACT-S512K8N-035P4Q | 5962-9561307HYC | WMS512K8L-12DE | 5962-9561328HTA |
| WS512K32F-85G4Q | 5962-9562403HNC | ACT-S512K8M-045P4Q | 5962-9561311HYA | WMS512K8L-12DE | 5962-9561328HTC |
| WS512K32N-85HQ | 5962-9461103HUA | ACT-S512K8M-045P4Q | 5962-9561311HYC | WMS512K8L-12DJ | 5962-9561328HZA |
| WS512K32N-85HQ | 5962-9461103HUC | ACT-S512K8N-045F3Q | 5962-9561306HUA | WMS512K8L-12DJ | 5962-9561328HZC |
| AS8F512K32P-90/883C | 5962-9461203H4A | ACT-S512K8N-045F3Q | 5962-9561306HUC | WMS512K8L-12F | 5962-9561328HXC |
| AS8F512K32P-90/883C | 5962-9461203H4C | ACT-S512K8N-045F4Q | 5962-9561306HZA | WMS512K8L-12FT | 5962-9561328HUA |
| AS8F512K32Q-90/883C | 5962-9461203HMA | ACT-S512K8N-045F4Q | 5962-9561306HZC | WMS512K8L-12FT | 5962-9561328HUC |
| AS8F512K32Q-90/883C | 5962-9461203HMC | ACT-S512K8N-045P4Q | 5962-9561306HYA | WMS512K8U-12C | 5962-9561330HYA |
| WF512K32-90G1TQ5 | 5962-9461203HBA | ACT-S512K8N-045P4Q | 5962-9561306HYC | WMS512K8U-12C | 5962-9561330HYC |
| WF512K32-90G1TQ5 | 5962-9461203HBC | ACT-S512K8N-055F3Q | 5962-9561305HUA | WMS512K8U-12DE | 5962-9561330HTA |
| WF512K32-90G1UQ5 | 5962-9461203H9A | ACT-S512K8N-055F3Q | 5962-9561305HUC | WMS512K8U-12DE | 5962-9561330HTC |
| WF512K32-90G1UQ5 | 5962-9461203H9C | ACT-S512K8N-055F4Q | 5962-9561305HZA | WMS512K8U-12DJ | 5962-9561330HZA |
| WF512K32-90G2Q5 | 5962-9461203HMA | ACT-S512K8N-055F4Q | 5962-9561305HZC | WMS512K8U-12DJ | 5962-9561330HZC |
| WF512K32-90G2Q5 | 5962-9461203HMC | ACT-S512K8N-055P4Q | 5962-9561305HYA | WMS512K8U-12F | 5962-9561330HXC |
| WF512K32-90G2UQ5 | 5962-9461203HZA | ACT-S512K8N-055P4Q | 5962-9561305HYC | WMS512K8U-12FT | 5962-9561330HUA |
| WF512K32-90G2UQ5 | 5962-9461203HZC | ACT-F512K8N-060P4Q | 5962-9669205HXA | WMS512K8U-12FT | 5962-9561330HUC |
| WF512K32-90G4TQ5 | 5962-9461203HTC | ACT-F512K8N-060P4Q | 5962-9669205HXC | 512K8-120 (GEN) | 5962-9207801HYA |
| WF512K32F-90G4Q5 | 5962-9461203HNA | ACT-F512K8N-070F6Q | 5962-9669204HUA | ACT-F512K8N-120F6Q | 5962-9669202HUA |
| WF512K32F-90G4Q5 | 5962-9461203HNC | ACT-F512K8N-070F6Q | 5962-9669204HUC | ACT-F512K8N-120F6Q | 5962-9669202HUC |
| WF512K32N-90H1Q5 | 5962-9461203H4A | ACT-F512K8N-070F7Q | 5962-9669204HTA | ACT-F512K8N-120F7Q | 5962-9669202HTA |
| WF512K32N-90H1Q5 | 5962-9461203H4C | ACT-F512K8N-070F7Q | 5962-9669204HTC | ACT-F512K8N-120F7Q | 5962-9669202HTC |
| WF512K32N-90HQ5 | 5962-9461203HUA | ACT-F512K8N-070P4Q | 5962-9669204HXA | ACT-F512K8N-120P4Q | 5962-9669202HXA |
| WF512K32N-90HQ5 | 5962-9461203HUC | ACT-F512K8N-070P4Q | 5962-9669204HXC | ACT-F512K8N-120P4Q | 5962-9669202HXC |
| HA-5127 (GEN) | 5962-89627012A | ACT-F512K8N-090F6Q | 5962-9669203HUA | WMS512K8-120C | 5962-9561301HYA |
| HA-5127 (GEN) | 5962-8962701GC | ACT-F512K8N-090F6Q | 5962-9669203HUC | WMS512K8-120C | 5962-9561301HYC |
| HA7-5127/883 | 5962-8962701PA | ACT-F512K8N-090F7Q | 5962-9669203HTA | WMS512K8-120DE | 5962-9561301HTA |
| ACT-S512K8N-017F3Q | 5962-9561310HUA | ACT-F512K8N-090F7Q | 5962-9669203HTC | WMS512K8-120DE | 5962-9561301HTC |
| ACT-S512K8N-017F3Q | 5962-9561310HUC | ACT-F512K8N-090P4Q | 5962-9669203HXA | WMS512K8L-120C | 5962-9561315HYA |
| ACT-S512K8N-017F4Q | 5962-9561310HZA | ACT-F512K8N-090P4Q | 5962-9669203HXC | WMS512K8L-120C | 5962-9561315HYC |
| ACT-S512K8N-017F4Q | 5962-9561310HZC | 512K8-100 (GEN) | 5962-9207802HYA | WMS512K8L-120DE | 5962-9561315HTA |
| ACT-S512K8N-017P4Q | 5962-9561310HYA | WMS512K8-100C | 5962-9561302HYA | WMS512K8L-120DE | 5962-9561315HTC |
| ACT-S512K8N-017P4Q | 5962-9561310HYC | WMS512K8-100C | 5962-9561302HYC | WS-512K8-120CQ | 5962-9207801HXC |
| ACT-S512K8N-020F3Q | 5962-9561309HUA | WMS512K8-100DE | 5962-9561302HTA | WS512K8-120CQ | 5962-9207801HTC |
| ACT-S512K8N-020F3Q | 5962-9561309HUC | WMS512K8-100DE | 5962-9561302HTC | WS-512K8-120CQA | 5962-9207801HXA |
| ACT-S512K8N-020F4Q | 5962-9561309HZA | WMS512K8L-100C | 5962-9561316HYA | WS512K8-120CQA | 5962-9207801HTA |
| ACT-S512K8N-020F4Q | 5962-9561309HZC | WMS512K8L-100C | 5962-9561316HYC | WMF512K8-120CQ5 | 5962-9669202HXA |
| ACT-S512K8N-020P4Q | 5962-9561309HYA | WMS512K8L-100DE | 5962-9561316HTA | WMF512K8-120CQ5 | 5962-9669202HXC |
| ACT-S512K8N-020P4Q | 5962-9561309HYC | WMS512K8L-100DE | 5962-9561316HTC | WMF512K8-120DEQ5 | 5962-9669202HYA |
| ACT-S512K8M-025P4Q | 5962-9561313HYA | WS-512K8-100CQ | 5962-9207802HXC | WMF512K8-120DEQ5 | 5962-9669202HYC |
| ACT-S512K8M-025P4Q | 5962-9561313HYC | WS512K8-100CQ | 5962-9207802HTC | WMF512K8-120FEQ5 | 5962-9669202HUA |
| ACT-S512K8N-025F3Q | 5962-9561308HUA | WS-512K8-100CQA | 5962-9207802HXA | WMF512K8-120FEQ5 | 5962-9669202HUC |
| ACT-S512K8N-025F3Q | 5962-9561308HUC | WS512K8-100CQA | 5962-9207802HTA | WMF512K8-120FFQ5 | 5962-9669202HTA |
| ACT-S512K8N-025F4Q | 5962-9561308HZA | WMS512K8-12C | 5962-9561329HYA | WMF512K8-120FFQ5 | 5962-9669202HTC |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART II, Listed By Generic PIN

| Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN |
|---|---|---|---|---|---|
| WMS512K8M-15C | 5962-9561314HYA | WMS512K8L-20DE | 5962-9561323HTC | WMS512K8-35DE | 5962-9561307HTA |
| WMS512K8M-15C | 5962-9561314HYC | WMS512K8L-20DJ | 5962-9561323HZA | WMS512K8-35DE | 5962-9561307HTC |
| WMS512K8M-15DE | 5962-9561314HTA | WMS512K8L-20DJ | 5962-9561323HZC | WMS512K8-35DJ | 5962-9561307HZA |
| WMS512K8M-15DE | 5962-9561314HTC | WMS512K8L-20F | 5962-9561323HXC | WMS512K8-35DJ | 5962-9561307HZC |
| ACT-F512K8N-150F6Q | 5962-9669201HUA | WMS512K8L-20FT | 5962-9561323HUA | WMS512K8-35F | 5962-9561307HXC |
| ACT-F512K8N-150F6Q | 5962-9669201HUC | WMS512K8L-20FT | 5962-9561323HUC | WMS512K8-35FT | 5962-9561307HUA |
| ACT-F512K8N-150F7Q | 5962-9669201HTA | WS-512K8-20CQ | 5962-9207809HXC | WMS512K8-35FT | 5962-9561307HUC |
| ACT-F512K8N-150F7Q | 5962-9669201HTC | WS512K8-20CQ | 5962-9207809HTC | WMS512K8L-35C | 5962-9561321HYA |
| ACT-F512K8N-150P4Q | 5962-9669201HXA | WS-512K8-20CQA | 5962-9207809HXA | WMS512K8L-35C | 5962-9561321HYC |
| ACT-F512K8N-150P4Q | 5962-9669201HXC | WS512K8-20CQA | 5962-9207809HTA | WMS512K8L-35DE | 5962-9561321HTA |
| WE-512K8-150CQ | 5962-9309101HXA | WE-512K8-200CQ | 5962-9309104HXA | WMS512K8L-35DE | 5962-9561321HTC |
| WE-512K8-150CQ | 5962-9309101HXC | WE-512K8-200CQ | 5962-9309104HXC | WMS512K8L-35DJ | 5962-9561321HZA |
| WE-512K8-150CQ | 5962-9309101HYA | WE-512K8-200CQ | 5962-9309104HYA | WMS512K8L-35DJ | 5962-9561321HZC |
| WE-512K8-150CQ | 5962-9309101HYC | WE-512K8-200CQ | 5962-9309104HYC | WMS512K8L-35F | 5962-9561321HXC |
| WMF512K8-150CQ5 | 5962-9669201HXA | WE-512K8-200CQ | 5962-9309105HYA | WMS512K8L-35FT | 5962-9561321HUA |
| WMF512K8-150CQ5 | 5962-9669201HXC | WE-512K8-200CQ | 5962-9309105HYC | WMS512K8L-35FT | 5962-9561321HUC |
| WMF512K8-150DEQ5 | 5962-9669201HYA | 512K8-25 (GEN) | 5962-9207808HYA | WMS512K8M-35C | 5962-9561312HYA |
| WMF512K8-150DEQ5 | 5962-9669201HYC | WMS512K8-25C | 5962-9561308HYA | WMS512K8M-35C | 5962-9561312HYC |
| WMF512K8-150FEQ5 | 5962-9669201HUA | WMS512K8-25C | 5962-9561308HYC | WMS512K8M-35DE | 5962-9561312HTA |
| WMF512K8-150FEQ5 | 5962-9669201HUC | WMS512K8-25DE | 5962-9561308HTA | WMS512K8M-35DE | 5962-9561312HTC |
| WMF512K8-150FFQ5 | 5962-9669201HTA | WMS512K8-25DE | 5962-9561308HTC | WS-512K8-35CQ | 5962-9207807HXC |
| WMF512K8-150FFQ5 | 5962-9669201HTC | WMS512K8-25DJ | 5962-9561308HZA | WS512K8-35CQ | 5962-9207807HTC |
| WMS512K8-17C | 5962-9561310HYA | WMS512K8-25DJ | 5962-9561308HZC | WS-512K8-35CQA | 5962-9207807HXA |
| WMS512K8-17C | 5962-9561310HYC | WMS512K8-25F | 5962-9561308HXC | WS512K8-35CQA | 5962-9207807HTA |
| WMS512K8-17DE | 5962-9561310HTA | WMS512K8-25FT | 5962-9561308HUA | 512K8-45 (GEN) | 5962-9207806HYA |
| WMS512K8-17DE | 5962-9561310HTC | WMS512K8-25FT | 5962-9561308HUC | WMS512K8-45C | 5962-9561306HYA |
| WMS512K8-17DJ | 5962-9561310HZA | WMS512K8L-25C | 5962-9561322HYA | WMS512K8-45C | 5962-9561306HYC |
| WMS512K8-17DJ | 5962-9561310HZC | WMS512K8L-25C | 5962-9561322HYC | WMS512K8-45DE | 5962-9561306HTA |
| WMS512K8-17F | 5962-9561310HXC | WMS512K8L-25DE | 5962-9561322HTA | WMS512K8-45DE | 5962-9561306HTC |
| WMS512K8-17FT | 5962-9561310HUA | WMS512K8L-25DE | 5962-9561322HTC | WMS512K8-45DJ | 5962-9561306HZA |
| WMS512K8-17FT | 5962-9561310HUC | WMS512K8L-25DJ | 5962-9561322HZA | WMS512K8-45DJ | 5962-9561306HZC |
| WMS512K8L-17C | 5962-9561324HYA | WMS512K8L-25DJ | 5962-9561322HZC | WMS512K8-45F | 5962-9561306HXC |
| WMS512K8L-17C | 5962-9561324HYC | WMS512K8L-25F | 5962-9561322HXC | WMS512K8-45FT | 5962-9561306HUA |
| WMS512K8L-17DE | 5962-9561324HTA | WMS512K8L-25FT | 5962-9561322HUA | WMS512K8-45FT | 5962-9561306HUC |
| WMS512K8L-17DE | 5962-9561324HTC | WMS512K8M-25C | 5962-9561313HYA | WMS512K8L-45C | 5962-9561320HYA |
| WMS512K8L-17DJ | 5962-9561324HZA | WMS512K8M-25C | 5962-9561313HYC | WMS512K8L-45C | 5962-9561320HYC |
| WMS512K8L-17DJ | 5962-9561324HZC | WMS512K8M-25DE | 5962-9561313HTA | WMS512K8L-45DE | 5962-9561320HTA |
| WMS512K8L-17F | 5962-9561324HXC | WMS512K8M-25DE | 5962-9561313HTC | WMS512K8L-45DE | 5962-9561320HTC |
| WMS512K8L-17FT | 5962-9561324HUA | WS-512K8-25CQ | 5962-9207808HXC | WMS512K8L-45DJ | 5962-9561320HZA |
| WMS512K8L-17FT | 5962-9561324HUC | WS512K8-25CQ | 5962-9207808HTC | WMS512K8L-45DJ | 5962-9561320HZC |
| 512K8-20 (GEN) | 5962-9207809HYA | WS-512K8-25CQA | 5962-9207808HXA | WMS512K8L-45F | 5962-9561320HXC |
| WMS512K8-20C | 5962-9561309HYA | WS512K8-25CQA | 5962-9207808HTA | WMS512K8L-45FT | 5962-9561320HUA |
| WMS512K8-20C | 5962-9561309HYC | WE-512K8-250CQ | 5962-9309103HXA | WMS512K8L-45FT | 5962-9561320HUC |
| WMS512K8-20DE | 5962-9561309HTA | WE-512K8-250CQ | 5962-9309103HXC | WMS512K8M-45C | 5962-9561311HYA |
| WMS512K8-20DE | 5962-9561309HTC | WE-512K8-250CQ | 5962-9309103HYA | WMS512K8M-45C | 5962-9561311HYC |
| WMS512K8-20DJ | 5962-9561309HZA | WE-512K8-250CQ | 5962-9309103HYC | WMS512K8M-45DE | 5962-9561311HTA |
| WMS512K8-20DJ | 5962-9561309HZC | WE-512K8-300CQ | 5962-9309102HXA | WMS512K8M-45DE | 5962-9561311HTC |
| WMS512K8-20F | 5962-9561309HXC | WE-512K8-300CQ | 5962-9309102HXC | WS-512K8-45CQ | 5962-9207806HXC |
| WMS512K8-20FT | 5962-9561309HUA | WE-512K8-300CQ | 5962-9309102HYA | WS512K8-45CQ | 5962-9207806HTC |
| WMS512K8-20FT | 5962-9561309HUC | WE-512K8-300CQ | 5962-9309102HYC | WS-512K8-45CQA | 5962-9207806HXA |
| WMS512K8L-20C | 5962-9561323HYA | 512K8-35 (GEN) | 5962-9207807HYA | WS512K8-45CQA | 5962-9207806HTA |
| WMS512K8L-20C | 5962-9561323HYC | WMS512K8-35C | 5962-9561307HYA | 512K8-55 (GEN) | 5962-9207805HYA |
| WMS512K8L-20DE | 5962-9561323HTA | WMS512K8-35C | 5962-9561307HYC | WMS512K8-55C | 5962-9561305HYA |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

| Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN |
|---|---|---|---|---|---|
| WMS512K8-55C | 5962-9561305HYC | MT5C128K8ECJ-17L/H | 5962-9669117HZC | MT5C128K8ECJ-55L/H | 5962-9669112HZC |
| WMS512K8-55DE | 5962-9561305HTA | MT5C128K8F-17/H | 5962-9669110HXA | MT5C128K8F-55/H | 5962-9669105HXA |
| WMS512K8-55DE | 5962-9561305HTC | MT5C128K8F-17/H | 5962-9669110HXC | MT5C128K8F-55/H | 5962-9669105HXC |
| WMS512K8-55DJ | 5962-9561305HZA | MT5C128K8F-17L/H | 5962-9669117HXA | MT5C128K8F-55L/H | 5962-9669112HXA |
| WMS512K8-55DJ | 5962-9561305HZC | MT5C128K8F-17L/H | 5962-9669117HXC | MT5C128K8F-55L/H | 5962-9669112HXC |
| WMS512K8-55F | 5962-9561305HXC | MT5C128K8ECJ-20/H | 5962-9669109HZA | WMF512K8-90CQ5 | 5962-9669203HXA |
| WMS512K8-55FT | 5962-9561305HUA | MT5C128K8ECJ-20/H | 5962-9669109HZC | WMF512K8-90CQ5 | 5962-9669203HXC |
| WMS512K8-55FT | 5962-9561305HUC | MT5C128K8ECJ-20L/H | 5962-9669116HZA | WMF512K8-90DEQ5 | 5962-9669203HYA |
| WMS512K8L-55C | 5962-9561319HYA | MT5C128K8ECJ-20L/H | 5962-9669116HZC | WMF512K8-90DEQ5 | 5962-9669203HYC |
| WMS512K8L-55C | 5962-9561319HYC | MT5C128K8F-20/H | 5962-9669109HXA | WMF512K8-90FEQ5 | 5962-9669203HUA |
| WMS512K8L-55DE | 5962-9561319HTA | MT5C128K8F-20/H | 5962-9669109HXC | WMF512K8-90FEQ5 | 5962-9669203HUC |
| WMS512K8L-55DE | 5962-9561319HTC | MT5C128K8F-20L/H | 5962-9669116HXA | WMF512K8-90FFQ5 | 5962-9669203HTA |
| WMS512K8L-55DJ | 5962-9561319HZA | MT5C128K8F-20L/H | 5962-9669116HXC | WMF512K8-90FFQ5 | 5962-9669203HTC |
| WMS512K8L-55DJ | 5962-9561319HZC | MT5C128K8ECJ-25/H | 5962-9669108HZA | 5130 (GEN) | 5962-9314401MXB |
| WMS512K8L-55F | 5962-9561319HXC | MT5C128K8ECJ-25/H | 5962-9669108HZC | 5130 (GEN) | 5962-9314402MXA |
| WMS512K8L-55FT | 5962-9561319HUA | MT5C128K8ECJ-25L/H | 5962-9669115HZA | HA-5134 (GEN) | 5962-9455301M2A |
| WMS512K8L-55FT | 5962-9561319HUC | MT5C128K8ECJ-25L/H | 5962-9669115HZC | HA-5134 (GEN) | 5962-9455301MCA |
| WS-512K8-55CQ | 5962-9207805HXC | MT5C128K8F-25/H | 5962-9669108HXA | HA5137 (GEN) | 5962-89627022A |
| WS512K8-55CQ | 5962-9207805HTC | MT5C128K8F-25/H | 5962-9669108HXC | HA5137 (GEN) | 5962-8962702GC |
| WS-512K8-55CQA | 5962-9207805HXA | MT5C128K8F-25L/H | 5962-9669115HXA | HA5137 (GEN) | 5962-8962702PA |
| WS512K8-55CQA | 5962-9207805HTA | MT5C128K8F-25L/H | 5962-9669115HXC | TL514 (GEN) | 5962-8687801CA |
| WMF512K8-60CQ5 | 5962-9669205HXA | MT5C128K8ECJ-35/H | 5962-9669107HZA | 5140 (GEN) | 5962-9467001MJA |
| WMF512K8-60CQ5 | 5962-9669205HXC | MT5C128K8ECJ-35/H | 5962-9669107HZC | DG5140 (GEN) | 8100609IA |
| WMF512K8-60DEQ5 | 5962-9669205HYA | MT5C128K8ECJ-35L/H | 5962-9669114HZA | IH5140MJE/883B | 8100609EA |
| WMF512K8-60DEQ5 | 5962-9669205HYC | MT5C128K8ECJ-35L/H | 5962-9669114HZC | MN5140H/B | 5962-9049701HXA |
| WMF512K8-60FEQ5 | 5962-9669205HUA | MT5C128K8F-35/H | 5962-9669107HXA | MN5140H/B | 5962-9049701HXC |
| WMF512K8-60FEQ5 | 5962-9669205HUC | MT5C128K8F-35/H | 5962-9669107HXC | DG5141 (GEN) | 8100602IA |
| WMF512K8-60FFQ5 | 5962-9669205HTA | MT5C128K8F-35L/H | 5962-9669114HXA | DG5141 (GEN) | 8100610IA |
| WMF512K8-60FFQ5 | 5962-9669205HTC | MT5C128K8F-35L/H | 5962-9669114HXC | HA-5141 (GEN) | 5962-89656012A |
| 512K8-70 (GEN) | 5962-9207804HYA | MT5C128K8ECJ-45/H | 5962-9669106HZA | HA-5141 (GEN) | 5962-8965601GA |
| WMS512K8-70C | 5962-9561304HYA | MT5C128K8ECJ-45/H | 5962-9669106HZC | HA-5141 (GEN) | 5962-8965601PA |
| WMS512K8-70C | 5962-9561304HYC | MT5C128K8ECJ-45L/H | 5962-9669113HZA | IH5141MJE/883B | 8100610EA |
| WMS512K8-70DE | 5962-9561304HTA | MT5C128K8ECJ-45L/H | 5962-9669113HZC | MN5141H/B | 5962-9049702HXA |
| WMS512K8-70DE | 5962-9561304HTC | MT5C128K8F-45/H | 5962-9669106HXA | MN5141H/B | 5962-9049702HXC |
| WMS512K8L-70C | 5962-9561318HYA | MT5C128K8F-45/H | 5962-9669106HXC | HA-5142 (GEN) | 5962-89656022A |
| WMS512K8L-70C | 5962-9561318HYC | MT5C128K8F-45L/H | 5962-9669113HXA | HA-5142 (GEN) | 5962-8965602GC |
| WMS512K8L-70DE | 5962-9561318HTA | MT5C128K8F-45L/H | 5962-9669113HXC | HA-5142 (GEN) | 5962-8965602PA |
| WMS512K8L-70DE | 5962-9561318HTC | 512K8-85 (GEN) | 5962-9207803HYA | IH5142MJE/883B | 8100611EA |
| WS-512K8-70CQ | 5962-9207804HXC | WMS512K8-85C | 5962-9561303HYA | MN5142H/B | 5962-9049703HXA |
| WS512K8-70CQ | 5962-9207804HTC | WMS512K8-85C | 5962-9561303HYC | MN5142H/B | 5962-9049703HXC |
| WS-512K8-70CQA | 5962-9207804HXA | WMS512K8-85DE | 5962-9561303HTA | IH5143MJE/883B | 8100612EA |
| WS512K8-70CQA | 5962-9207804HTA | WMS512K8-85DE | 5962-9561303HTC | MN5143H/B | 5962-9049704HXA |
| WMF512K8-70CQ5 | 5962-9669204HXA | WMS512K8L-85C | 5962-9561317HYA | MN5143H/B | 5962-9049704HXC |
| WMF512K8-70CQ5 | 5962-9669204HXC | WMS512K8L-85C | 5962-9561317HYC | DG5144 (GEN) | 8100605IA |
| WMF512K8-70DEQ5 | 5962-9669204HYA | WMS512K8L-85DE | 5962-9561317HTA | DG5144 (GEN) | 8100613IA |
| WMF512K8-70DEQ5 | 5962-9669204HYC | WMS512K8L-85DE | 5962-9561317HTC | HA1-5144/883 | 5962-8965603CA |
| WMF512K8-70FEQ5 | 5962-9669204HUA | WS-512K8-85CQ | 5962-9207803HXC | HA-5144 (GEN) | 5962-89656032A |
| WMF512K8-70FEQ5 | 5962-9669204HUC | WS512K8-85CQ | 5962-9207803HTC | IH5144MJE/883B | 8100613EA |
| WMF512K8-70FFQ5 | 5962-9669204HTA | WS-512K8-85CQA | 5962-9207803HXA | IH5145MJE/883B | 8100614EA |
| WMF512K8-70FFQ5 | 5962-9669204HTC | WS512K8-85CQA | 5962-9207803HTA | HA-5147 (GEN) | 5962-89627032A |
| MT5C128K8ECJ-17/H | 5962-9669110HZA | MT5C128K8ECJ-55/H | 5962-9669105HZA | HA-5147 (GEN) | 5962-8962703GC |
| MT5C128K8ECJ-17/H | 5962-9669110HZC | MT5C128K8ECJ-55/H | 5962-9669105HZC | HA-5147 (GEN) | 5962-8962703PA |
| MT5C128K8ECJ-17L/H | 5962-9669117HZA | MT5C128K8ECJ-55L/H | 5962-9669112HZA | HS1-51472AR3808 | 5962M95A0501QY |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

| Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN |
|---|---|---|---|---|---|
| HS4-51472AR3808 | 5962M95A0501QXA | MN5203 (GEN) | 5962-8958302YA | MN5216MXC | 5962-8958407XC |
| IH5148 (GEN) | 8100619EA | LPR520 (GEN) | 5962-8971601MQC | MN5216MYA | 5962-8958407YA |
| IH5149MJE/883B | 8100620EA | LPR520 (GEN) | 5962-8971601MXC | MN5216MYC | 5962-8958407YC |
| IH5150MJE/883B | 8100621EA | MN5204 (GEN) | 5962-8958304XA | 522 (GEN) | 5962-8751602CA |
| HCPL-5151 | 5962-0420501HPC | MN5204 (GEN) | 5962-8958304YA | 522 (GEN) | 5962-8751602DA |
| IH5151MJE/883B | 8100622EA | MN5205 (GEN) | 5962-8958306XA | CLC522AE-QML | 5962-9451701M2A |
| HCPL-5151-100 | 5962-0420501HYA | MN5205MYA | 5962-8958306YA | CLC522AJ-QML | 5962-9451701MCA |
| HCPL-5151-100 | 5962-0420501HYC | MN5205MYC | 5962-8958306YC | HA-5221 (GEN) | 5962-9163401M2A |
| HCPL-5151-200 | 5962-0420501HPA | MN5206 (GEN) | 5962-8958307XA | HA-5221 (GEN) | 5962-9163401MPA |
| HCPL-5151-300 | 5962-0420501HXA | MN5206 (GEN) | 5962-8958307YA | HA-5222 (GEN) | 5962-9163402M2A |
| HI516 (GEN) | 5962-88699013A | HCPL-520K | 5962-8876802KPC | HA-5222 (GEN) | 5962-9163402MPA |
| HI516 (GEN) | 5962-8869901XA | HCPL-520K#100 | 5962-8876802KYA | HCPL-523K | 5962-8876904KPC |
| 5165228 (GEN) | 5962-8951904VYA | HCPL-520K#100 | 5962-8876802KYC | HCPL-523K#100 | 5962-8876904KYA |
| 5165228 (GEN) | 5962-8951905VYA | HCPL-520K#200 | 5962-8876802KPA | HCPL-523K#100 | 5962-8876904KYC |
| SMC51675/2 | 5962-0254001EXA | HCPL-520K#300 | 5962-8876802KXA | HCPL-523K#200 | 5962-8876904KPA |
| SMC51676/2 | 5962-0252201EXA | 521/BCA | 5962-8751601CA | HCPL-523K#300 | 5962-8876904KXA |
| SMC51677/2 | 5962-0252501EXA | 521/BDA | 5962-8751601DA | SL523AC (GEN) | 5962-8980301XA |
| 5C180-90 (GEN) | 5962-8854901ZA | ACS521 (GEN) | 5962F9670901V9A | HCPL-5231 | 5962-8876901PC |
| SA 51M (GEN) | 5962-9762901HXA | ACS521 (GEN) | 5962F9670901VRC | HCPL-5231#100 | 5962-8876901YA |
| HA1-5190/883 | 5962-8778401CA | ACS521 (GEN) | 5962F9670901VXC | HCPL-5231#100 | 5962-8876901YC |
| HA4-5190/883 | 5962-87784012A | SL521 (GEN) | 5962-9079201MXA | HCPL-5231#200 | 5962-8876901PA |
| HA-5190 (GEN) | 5962-8778401XC | MN5210 (GEN) | 5962-8958401XA | HCPL-5231#300 | 5962-8876901XA |
| 51992 | 5962-8761701XA | MN5210 (GEN) | 5962-8958401YA | 5233-250 (GEN) | 5962-8683004XA |
| 51992 | 5962-8761701XC | ACS521-02 (GEN) | 5962F9670902V9A | 5233-250 (GEN) | 5962-8683004YA |
| CLC520A (GEN) | 5962-9169401M2A | ACS521-02 (GEN) | 5962F9670902VRC | 5233-250 (GEN) | 5962-8683004ZA |
| CLC520AJ-QML | 5962-9169401MCA | ACS521-02 (GEN) | 5962F9670902VXC | AD524 (GEN) | 5962-88539012A |
| MN5200 (GEN) | 5962-8958301XA | MN5211MXA | 5962-8958403XA | AD524SD/883B | 5962-8853901EA |
| MN5200 (GEN) | 5962-8958301YA | MN5211MXC | 5962-8958403XC | AD524SD/QMLR | 5962R8853901VEA |
| AS5C2008CW-25/HQ | 5962-9315708HYA | MN5211MYA | 5962-8958403YA | AD524SD/QMLV | 5962-8853901VEA |
| AS5C2008CW-25/HQ | 5962-9315708HYC | MN5211MYC | 5962-8958403YC | AD524SE/QMLR | 5962R8853901V2A |
| AS5C2008CW-35/HQ | 5962-9315707HYA | LPR521 (GEN) | 5962-8971606MQC | AD524SE/QMLV | 5962-8853901V2A |
| AS5C2008CW-35/HQ | 5962-9315707HYC | LPR521 (GEN) | 5962-8971606MXC | HI-524 (GEN) | 5962-8761801VA |
| AS5C2008CW-45/HQ | 5962-9315706HYA | 5212A (GEN) | 5962-9212901MPA | 52445 | 5962-0250502HXA |
| AS5C2008CW-45/HQ | 5962-9315706HYC | MN5212MXA | 5962-8958405XA | 52445 | 5962-0250502HXC |
| AS5C2008CW-55/HQ | 5962-9315705HYA | MN5212MXC | 5962-8958405XC | 52446 | 5962-0250503HXA |
| AS5C2008CW-55/HQ | 5962-9315705HYC | MN5212MYA | 5962-8958405YA | 52446 | 5962-0250503HXC |
| HCPL-5201 | 5962-8876801PC | MN5212MYC | 5962-8958405YC | 52447 | 5962-0250601HXA |
| HCPL-5201#100 | 5962-8876801YA | LPR521 (GEN) | 5962-8971605MQC | 52447 | 5962-0250601HXC |
| HCPL-5201#100 | 5962-8876801YC | LPR521 (GEN) | 5962-8971605MXC | MN5245 (GEN) | 5962-8959501YA |
| HCPL-5201#200 | 5962-8876801PA | MN5213 (GEN) | 5962-8958402XA | MN5245A (GEN) | 5962-8959502YA |
| MN5201 (GEN) | 5962-8958303XA | MN5213MYA | 5962-8958402YA | MN5245AH/B | 5962-8959502XA |
| MN5201MYA | 5962-8958303YA | MN5213MYC | 5962-8958402YC | MN5245AH/B | 5962-8959502XC |
| MN5201MYC | 5962-8958303YC | LPR521 (GEN) | 5962-8971604MQC | MN5245H/B | 5962-8959501XA |
| HCPL-5201#300 | 5962-8876801XA | LPR521 (GEN) | 5962-8971604MXC | MN5245H/B | 5962-8959501XC |
| LPR520 (GEN) | 5962-8971603MQC | MN5214 (GEN) | 5962-8958404XA | MN5246 (GEN) | 5962-8959503YA |
| LPR520 (GEN) | 5962-8971603MXC | MN5214MYA | 5962-8958404YA | MN5246A (GEN) | 5962-8959504YA |
| MN5202MXA | 5962-8958305XA | MN5214MYC | 5962-8958404YC | MN5246AH/B | 5962-8959504XA |
| MN5202MXC | 5962-8958305XC | MN5215MXA | 5962-8958406XA | MN5246AH/B | 5962-8959504XC |
| MN5202MYA | 5962-8958305YA | MN5215MXC | 5962-8958406XC | MN5246H/B | 5962-8959503XA |
| MN5202MYC | 5962-8958305YC | MN5215MYA | 5962-8958406YA | MN5246H/B | 5962-8959503XC |
| LPR520 (GEN) | 5962-8971602MQC | MN5215MYC | 5962-8958406YC | MT5C2561C-25 | 5962-8872505LA |
| LPR520 (GEN) | 5962-8971602MXC | IH5216 (GEN) | 5962-8513105XA | MT5C2561EC-25 | 5962-8872505XA |
| MN5203 (GEN) | 5962-8958302XA | MN5216MXA | 5962-8958407XA | MT5C2561C-35 | 5962-8872501LA |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART II, Listed By Generic PIN

| Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN |
|---|---|---|---|---|---|
| MT5C2561C35L883C | 5962-8854401LA | MT5C2565EC-45 | 5962-8952403YA | MT5C2568C-25883C | 5962-8866206NA |
| MT5C2561EC-35 | 5962-8872501XA | MT5C256C-55 | 5962-8872503LA | MT5C2568CW-25883C | 5962-8866206XA |
| MT5C2561EC35L883C | 5962-8854401XA | MT5C2565C-55 | 5962-8952402XA | MT5C2568EC-25883C | 5962-8866206UA |
| MT5C2561C-45 | 5962-8872502LA | MT5C2565EC-55 | 5962-8952402YA | MT5C2568ECW-25883 | 5962-8866206YA |
| MT5C2561C45L883C | 5962-8854402LA | MT5C2565C-70 | 5962-8952401XA | MT5C2568F-25883C | 5962-8866206TA |
| MT5C2561EC-45 | 5962-8872502XA | MT5C2565EC-70 | 5962-8952401YA | AS5C2568C-35L/883C | 5962-8855205UA |
| MT5C2561EC45L883C | 5962-8854402XA | AS5C2566C-25 | 5962-8993503XA | AS5C2568CW-35L/883 | 5962-8855205XA |
| MT5C2561C55L883C | 5962-8854403LA | AS5C2566C-35 | 5962-8993502XA | AS5C2568EC-35L/883C | 5962-8855205MA |
| MT5C2561EC-55 | 5962-8872503XA | AS5C2566C-45 | 5962-8993501XA | AS5C2568ECW-35L/88 | 5962-8855205YA |
| MT5C2561EC55L883C | 5962-8854403XA | MT5C2568CW-100883C | 5962-8866201XA | AS5C2568F-35L/883C | 5962-8855205TA |
| MT5C2561C-70 | 5962-8872504LA | MT5C2568EC-100883C | 5962-8866201UA | MT5C2568C-35883C | 5962-8866205NA |
| MT5C2561C70L883C | 5962-8854404LA | MT5C2568ECW-100883 | 5962-8866201YA | MT5C2568CW-35883C | 5962-8866205XA |
| MT5C2561EC-70 | 5962-8872504XA | MT5C2568F-100883C | 5962-8866201TA | MT5C2568EC-35883C | 5962-8866205UA |
| MT5C2561EC70L883C | 5962-8854404XA | AS5C2568C-12L/883C | 5962-8855213UA | MT5C2568ECW-35883 | 5962-8866205YA |
| MT5C2564C-20/883C | 5962-8868106LA | AS5C2568CW-12L/883 | 5962-8855213XA | MT5C2568F-35883C | 5962-8866205TA |
| MT5C2564EC-20/883C | 5962-8868106XA | AS5C2568EC-12L/883C | 5962-8855213MA | AS5C2568C-45L/883C | 5962-8855209UA |
| MT5C2564F-20/883C | 5962-8868106YA | AS5C2568ECW-12L/88 | 5962-8855213YA | AS5C2568CW-45L/883 | 5962-8855209XA |
| MT5C2564C-25/883C | 5962-8868105LA | AS5C2568F-12L/883C | 5962-8855213TA | AS5C2568ECW-45L/88 | 5962-8855209YA |
| MT5C2564EC-25/883C | 5962-8868105XA | MT5C2568C-12883C | 5962-8866209NA | AS5C2568F-45L/883C | 5962-8855209TA |
| MT5C2564F-25/883C | 5962-8868105YA | MT5C2568CW-12883C | 5962-8866209XA | MT5C2568C-45883C | 5962-8866204NA |
| MT5C2564C-35/883C | 5962-8868101LA | MT5C2568EC-12883C | 5962-8866209UA | MT5C2568CW-45883C | 5962-8866204XA |
| MT5C2564C-35L/883C | 5962-8854501LA | MT5C2568ECW-12883 | 5962-8866209YA | MT5C2568EC-45883C | 5962-8866204UA |
| MT5C2564EC-35/883C | 5962-8868101XA | MT5C2568F-12883C | 5962-8866209TA | MT5C2568ECW-45883 | 5962-8866204YA |
| MT5C2564EC-35L/883C | 5962-8854501XA | AS5C2568C-15L/883C | 5962-8855212UA | MT5C2568F-45883C | 5962-8866204TA |
| MT5C2564F-35/883C | 5962-8868101YA | AS5C2568CW-15L/883 | 5962-8855212XA | AS5C2568C-55L/883C | 5962-8855208UA |
| MT5C2564F-35L/883C | 5962-8854501YA | AS5C2568EC-15L/883C | 5962-8855212MA | AS5C2568CW-55L/883 | 5962-8855208XA |
| MT5C2564C-45/883C | 5962-8868102LA | AS5C2568ECW-15L/88 | 5962-8855212YA | AS5C2568EC-55L/883C | 5962-8855208MA |
| MT5C2564C-45L/883C | 5962-8854502LA | AS5C2568F-15L/883C | 5962-8855212TA | AS5C2568ECW-55L/88 | 5962-8855208YA |
| MT5C2564EC-45/883C | 5962-8868102XA | MT5C2568C-15883C | 5962-8866208NA | AS5C2568F-55L/883C | 5962-8855208TA |
| MT5C2564EC-45L/883C | 5962-8854502XA | MT5C2568CW-15883C | 5962-8866208XA | MT5C2568C-55883C | 5962-8866203NA |
| MT5C2564F-45/883C | 5962-8868102YA | MT5C2568EC-15883C | 5962-8866208UA | MT5C2568CW-55883C | 5962-8866203XA |
| MT5C2564F-45L/883C | 5962-8854502YA | MT5C2568ECW-15883 | 5962-8866208YA | MT5C2568EC-55883C | 5962-8866203UA |
| MT5C2564C-55/883C | 5962-8868103LA | MT5C2568F-15883C | 5962-8866208TA | AS5C2568C-70L/883C | 5962-8855207UA |
| MT5C2564C-55L/883C | 5962-8854503LA | AS5C2568C-17L/883C | 5962-8855211UA | AS5C2568CW-70L/883 | 5962-8855207XA |
| MT5C2564EC-55/883C | 5962-8868103XA | AS5C2568CW-17L/883 | 5962-8855211XA | AS5C2568EC-70L/883C | 5962-8855207MA |
| MT5C2564EC-55L/883C | 5962-8854503XA | AS5C2568EC-17L/883C | 5962-8855211MA | AS5C2568ECW-70L/88 | 5962-8855207YA |
| MT5C2564F-55/883C | 5962-8868103YA | AS5C2568ECW-17L/88 | 5962-8855211YA | AS5C2568F-70L/883C | 5962-8855207TA |
| MT5C2564F-55L/883C | 5962-8854503YA | AS5C2568F-17L/883C | 5962-8855211TA | MT5C2568C-70883C | 5962-8866201NA |
| M5C2564C-70/883C | 5962-8868104LA | AS5C2568C-20L/883C | 5962-8855210UA | MT5C2568C-70883C | 5962-8866202NA |
| MT5C2564C-70L/883C | 5962-8854504LA | AS5C2568CW-20L/883 | 5962-8855210XA | MT5C2568CW-70883C | 5962-8866202XA |
| MT5C2564EC-70/883C | 5962-8868104XA | AS5C2568EC-20L/883C | 5962-8855210MA | MT5C2568EC-70883C | 5962-8866202UA |
| MT5C2564EC-70L/883C | 5962-8854504XA | AS5C2568ECW-20L/88 | 5962-8855210YA | MT5C2568ECW-70883 | 5962-8866202YA |
| MT5C2564F-70/883C | 5962-8868104YA | AS5C2568F-20L/883C | 5962-8855210TA | MT5C2568F-70883C | 5962-8866202TA |
| MT5C2564F-70L/883C | 5962-8854504YA | MT5C2568C-20883C | 5962-8866207NA | AD526SD/883 | 5962-9089401MEA |
| MT5C2565C-15 | 5962-8952407XA | MT5C2568CW-20883C | 5962-8866207XA | ADG526ATE/883B | 5962-89710013A |
| MT5C2565EC-15 | 5962-8952407YA | MT5C2568EC-20883C | 5962-8866207UA | ADG526ATQ/883B | 5962-8971001XA |
| MT5C2565C-20 | 5962-8952406XA | MT5C2568ECW-20883 | 5962-8866207YA | 527 (GEN) | 5962-8757201CA |
| MT5C2565EC-20 | 5962-8952406YA | MT5C2568F-20883C | 5962-8866207TA | 527 (GEN) | 5962-8757201DA |
| MT5C2565C-25 | 5962-8952405XA | AS5C2568C-25L/883C | 5962-8855206UA | ADG527ATE/883B | 5962-89710023A |
| MT5C2565EC-25 | 5962-8952405YA | AS5C2568CW-25L/883 | 5962-8855206XA | ADG527ATQ/883B | 5962-8971002XA |
| MT5C2565C-35 | 5962-8952404XA | AS5C2568EC-25L/883C | 5962-8855206MA | MSK5275-12H | 5962-0323209HXA |
| MT5C2565EC-35 | 5962-8952404YA | AS5C2568ECW-25L/88 | 5962-8855206YA | MSK5275-12H | 5962-0323209HXC |
| MT5C2565C-45 | 5962-8952403XA | AS5C2568F-25L/883C | 5962-8855206TA | MSK5275-1.5H | 5962-0323201HXA |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART II, Listed By Generic PIN

| Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN |
|---|---|---|---|---|---|
| MSK5275-1.5H | 5962-0323201HXC | 53111-3P | 5962-9314003HPA | L5380 (GEN) | 5962-9054801MXA |
| MSK5275-1.7H | 5962-0323202HXA | 53111-3P | 5962-9314003HPC | L53C80 (GEN) | 5962-9054802MXA |
| MSK5275-1.7H | 5962-0323202HXC | 53111-3X | 5962-9314003HXA | L53C80 (GEN) | 5962-9054802MYA |
| MSK5275-1.8H | 5962-0323203HXA | 53111-3X | 5962-9314003HXC | AD539SD/883B | 5962-8980901EA |
| MSK5275-1.8H | 5962-0323203HXC | CLC532AE-QML | 5962-9203501M2A | AD539SE/883B | 5962-89809012A |
| MSK5275-1.9H | 5962-0323204HXA | CLC532AJ-QML | 5962-9203501MCA | HCTS540 (GEN) | 5962R9577601V9A |
| MSK5275-1.9H | 5962-0323204HXC | MAX532AMJE/883B | 5962-9566701MEA | HCTS540 (GEN) | 5962R9577601VRC |
| MSK5275-2.5H | 5962-0323205HXA | MAX532BMJE/883B | 5962-9566702MEA | HCTS540KMSR | 5962R9577601VXC |
| MSK5275-2.5H | 5962-0323205HXC | SL532AC (GEN) | 5962-9052101XA | 54AC00 (GEN) | 5962-8754901VXA |
| MSK5275-3.3H | 5962-0323206HXA | UHC532/883 | 5962-8960403DA | 54AC00 (GEN) | 5962-8754901XA |
| MSK5275-3.3H | 5962-0323206HXC | UHD532/883 | 5962-8960403CA | 54AC00DMQB | 5962-8754901CA |
| MSK5275-3.4H | 5962-0323207HXA | HA1-5320/883 | 5962-9306302MCA | 54AC00FMQB | 5962-8754901DA |
| MSK5275-3.4H | 5962-0323207HXC | HA4-5320/883 | 5962-9306302M2A | 54AC00LMQB | 5962-87549012A |
| MSK5275-5.0H | 5962-0323208HXA | 53252-107 | 5962-0324701HYA | 54ACT00 (GEN) | 5962-87699012A |
| MSK5275-5.0H | 5962-0323208HXC | 53252-108 | 5962-0324701HYC | 54ACT00 (GEN) | 5962-8769901CA |
| ADG528A (GEN) | 5962-9063501M2A | 53252-117 | 5962-0324701HXA | 54ACT00 (GEN) | 5962-8769901DA |
| ADG528ATQ/883B | 5962-9063501MVA | 53252-118 | 5962-0324701HXC | 54ACT00 (GEN) | 5962-8769901S2A |
| DG528AK/883 | 5962-8768901VA | CLC533 (GEN) | 5962-9320301M2A | 54ACT00 (GEN) | 5962-8769901SCA |
| DG528AK/883B | 5962-8768901VA | CLC533 (GEN) | 5962-9320301MEA | 54ACT00 (GEN) | 5962-8769901SDA |
| 529/BCA | 5962-8757202CA | HA1-5330/883 | 5962-8767701CA | 54ACT00DMQB | 5962-8769901MCA |
| 529/BDA | 5962-8757202DA | HA4-5330/883 | 5962-87677012A | 54ACT00FMQB | 5962-8769901MDA |
| ADG529ATE/883B | 5962-9063502M2A | 5336-T (GEN) | 5962-9469001MXA | 54ACT00K01Q | 5962-8769903QXC |
| ADG529ATQ/883B | 5962-9063502MVA | AD534TD/QMLV | 5962-9053701VCA | 54ACT00K01V | 5962-8769903VXC |
| MN5290H/B | 5962-8956301HXA | AD534TH/QMLV | 5962-9053701VIA | 54ACT00K02Q | 5962-8769903QXA |
| MN5290H/B | 5962-8956301HXC | DG534AAP/883 | 5962-9060201MRA | 54ACT00K02V | 5962-8769903VXA |
| MN5291H/B | 5962-8956302HXA | HA1-5340/883 | 5962-9306301MCA | 54ACT00LMQB | 5962-8769901M2A |
| MN5291H/B | 5962-8956302HXC | HA4-5340/883 | 5962-9306301M2A | 54HC00 (GEN) | 8403701AA |
| MN5295H/B | 5962-8956901HXA | 5341-035 | 5962-94B0201QTA | 54HC00 (GEN) | 8403701BA |
| MN5295H/B | 5962-8956901HXC | 5341-035 (GEN) | 5962-94B0201MTA | 54HC00K01Q | 8403701XC |
| HCPL-5301 | 5962-9685201HPC | 5342-031 | 5962-94B0201QYA | 54HC00K01V | 5962-8403701VXC |
| HCPL-5301#100 | 5962-9685201HYA | 5342-031 (GEN) | 5962-94B0201MYA | 54HC00K02Q | 8403701XA |
| HCPL-5301#100 | 5962-9685201HYC | 5343-048 | 5962-99A1601QXC | 54HC00K02V | 5962-8403701VXA |
| HCPL-5301#200 | 5962-9685201HPA | 5343-049 | 5962-97A1601QXA | CD54HC00F3A | 8403701CA |
| HCPL-5301#300 | 5962-9685201HXA | 5343-050 | 5962-97A1701QXC | CD54HCT00F3A | 5962-8683101CA |
| HCPL-530K | 5962-9685201KPC | 5344-021 | 5962-94B0201QZA | JM54ACT00B2A | 5962-8769901B2A |
| HCPL-530K#200 | 5962-9685201KPA | 5344-021 (GEN) | 5962-94B0201MZA | JM54ACT00B2A-RH | 5962R8769901B2A |
| SL531 (GEN) | 5962-9208401MXA | 5345-005 | 5962-99A1401QXC | JM54ACT00BCA | 5962-8769901BCA |
| 53111-1P | 5962-9314001HPA | 5345-029 | 5962-99A1901QXC | JM54ACT00BCA-RH | 5962R8769901BCA |
| 53111-1P | 5962-9314001HPC | 5345-034 | 5962-99A1201QXC | JM54ACT00BDA | 5962-8769901BDA |
| 53111-1X | 5962-9314001HXA | IH5352 (GEN) | 5962-8875001EA | JM54ACT00BDA-RH | 5962R8769901BDA |
| 53111-1X | 5962-9314001HXC | 5352-037 | 5962-94B0201QUA | JM54ACT00S2A-RH | 5962R8769901S2A |
| 53111-1Y | 5962-9314001HYA | 5352-037 (GEN) | 5962-94B0201MUA | JM54ACT00SCA-RH | 5962R8769901SCA |
| 53111-1Y | 5962-9314001HYC | 5352-044 | 5962-98A0501QXC | JM54ACT00SDA-RH | 5962R8769901SDA |
| 53111-1Z | 5962-9314001HZA | 5353-035 | 5962-98A0101QXC | JM54ACT00SZA-RH | 5962R8769901SZA |
| 53111-1Z | 5962-9314001HZC | AD536ASD/883B | 5962-8980501CA | RHFAC00K01Q | 5962F8754901XC |
| 53111-2P | 5962-9314002HPA | AD536ASE/883B | 5962-89805012A | RHFAC00K01V | 5962F8754901VXC |
| 53111-2P | 5962-9314002HPC | AD536ASH/883B | 5962-8980501IA | RHFAC00K02Q | 5962F8754901XA |
| 53111-2X | 5962-9314002HXA | MX536ASD/883B | 5962-8980501CC | RHFAC00K02V | 5962F8754901VXA |
| 53111-2X | 5962-9314002HXC | MX536ASE/883B | 5962-89805012C | RHFACT00K01Q | 5962F8769903QXC |
| 53111-2Y | 5962-9314002HYA | MX536ASH/883B | 5962-8980501IC | RHFACT00K01V | 5962F8769903VXC |
| 53111-2Y | 5962-9314002HYC | MX536ASQ/883B | 5962-8980501CA | RHFACT00K02Q | 5962F8769903QXA |
| 53111-2Z | 5962-9314002HZA | DG538AAP/883 | 5962-8976001MXA | RHFACT00K02V | 5962F8769903VXA |
| 53111-2Z | 5962-9314002HZC | L5380 (GEN) | 5962-9054801MQA | SNJ54AC00FK | 5962-87549012A |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

| Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN |
|---|---|---|---|---|---|
| SNJ54AC00J | 5962-8754901CA | AS5C4008ECJ-12/H | 5962-9561329HTA | AS5C4008CW-25/H | 5962-9561308HYC |
| SNJ54AC00W | 5962-8754901DA | AS5C4008ECJ-12/H | 5962-9561329HTC | AS5C4008CW-25/H | 5962-9561313HYA |
| SNJ54ACT00FK | 5962-8769901M2A | AS5C4008ECJ-12L | 5962-9560015QUA | AS5C4008CW-25/H | 5962-9561313HYC |
| SNJ54ACT00J | 5962-8769901MCA | AS5C4008ECJ-12L/H | 5962-9561328HTA | AS5C4008CW-25L | 5962-9560011QXA |
| SNJ54ACT00W | 5962-8769901MDA | AS5C4008ECJ-12L/H | 5962-9561328HTC | AS5C4008CW-25L/H | 5962-9561322HYA |
| SNJ54AHC00FK | 5962-9682201Q2A | AS5C4008F-12 | 5962-9560016Q9A | AS5C4008CW-25L/H | 5962-9561322HYC |
| SNJ54AHC00J | 5962-9682201QCA | AS5C4008F-12/H | 5962-9561329H9A | AS5C4008CW-25L/H | 5962-9561327HYA |
| SNJ54AHC00W | 5962-9682201QDA | AS5C4008F-12/H | 5962-9561329H9C | AS5C4008CW-25L/H | 5962-9561327HYC |
| SNJ54AHCT00FK | 5962-9682301Q2A | AS5C4008F-12L | 5962-9560015Q9A | AS5C4008EC-25 | 5962-9560003MZA |
| SNJ54AHCT00J | 5962-9682301QCA | AS5C4008F-12L/H | 5962-9561328H9A | AS5C4008EC-25L | 5962-9560011QZA |
| SNJ54AHCT00W | 5962-9682301QDA | AS5C4008F-12L/H | 5962-9561328H9C | AS5C4008ECJ-25 | 5962-9560003MUA |
| SNJ54ALS00AFK | 5962-86833012A | AS5C4008CW-15 | 5962-9560014QXA | AS5C4008ECJ-25/H | 5962-9561308HTA |
| SNJ54ALS00AW | 5962-8683301DA | AS5C4008CW-15L | 5962-9560013QXA | AS5C4008ECJ-25/H | 5962-9561308HTC |
| SNJ54F00FK | 5962-9757701Q2A | AS5C4008EC-15 | 5962-9560014QZA | AS5C4008ECJ-25/H | 5962-9561313HTA |
| SNJ54F00J | 5962-9757701QCA | AS5C4008EC-15L | 5962-9560013QZA | AS5C4008ECJ-25/H | 5962-9561313HTC |
| SNJ54F00W | 5962-9757701QDA | AS5C4008ECJ-15 | 5962-9560014QUA | AS5C4008ECJ-25L | 5962-9560011QUA |
| SNJ54HC00FK | 84037012A | AS5C4008ECJ-15L | 5962-9560013QUA | AS5C4008ECJ-25L/H | 5962-9561322HTA |
| SNJ54HC00J | 8403701CA | AS5C4008F-15 | 5962-9560014Q9A | AS5C4008ECJ-25L/H | 5962-9561322HTC |
| SNJ54HC00W | 8403701DA | AS5C4008F-15L | 5962-9560013Q9A | AS5C4008ECJ-25L/H | 5962-9561327HTA |
| SNJ54LVC00AFK | 5962-9753301Q2A | AS5C4008CW-17/H | 5962-9561310HYA | AS5C4008ECJ-25L/H | 5962-9561327HTC |
| SNJ54LVC00AJ | 5962-9753301QCA | AS5C4008CW-17/H | 5962-9561310HYC | AS5C4008F-25 | 5962-9560003M9A |
| SNJ54LVC00AW | 5962-9753301QDA | AS5C4008CW-17L/H | 5962-9561324HYA | AS5C4008F-25/H | 5962-9561308H9A |
| SNV54HC00J | 5962-8403701VCA | AS5C4008CW-17L/H | 5962-9561324HYC | AS5C4008F-25/H | 5962-9561308H9C |
| SNV54HC00W | 5962-8403701VDA | AS5C4008ECJ-17/H | 5962-9561310HTA | AS5C4008F-25/H | 5962-9561313H9A |
| SNV54LVC00AJ | 5962-9753301VCA | AS5C4008ECJ-17/H | 5962-9561310HTC | AS5C4008F-25/H | 5962-9561313H9C |
| SNV54LVC00AW | 5962-9753301VDA | AS5C4008ECJ-17L/H | 5962-9561324HTA | AS5C4008F-25L | 5962-9560011Q9A |
| UT54ACS00PQAH | 5962H9651201QCA | AS5C4008ECJ-17L/H | 5962-9561324HTC | AS5C4008F-25L/H | 5962-9561322H9A |
| UT54ACS00PQCH | 5962H9651201QCC | AS5C4008F-17/H | 5962-9561310H9A | AS5C4008F-25L/H | 5962-9561322H9C |
| UT54ACS00PVAH | 5962H9651201VCA | AS5C4008F-17/H | 5962-9561310H9C | AS5C4008F-25L/H | 5962-9561327H9A |
| UT54ACS00PVCH | 5962H9651201VCC | AS5C4008F-17L/H | 5962-9561324H9A | AS5C4008F-25L/H | 5962-9561327H9C |
| UT54ACS00-QDIE | 5962H9651201Q9A | AS5C4008F-17L/H | 5962-9561324H9C | AS5C4008CW-35 | 5962-9560002MXA |
| UT54ACS00UQAH | 5962H9651201QXA | AS5C4008CW-20 | 5962-9560004MXA | AS5C4008CW-35/H | 5962-9561307HYA |
| UT54ACS00UQCH | 5962H9651201QXC | AS5C4008CW-20/H | 5962-9561309HYA | AS5C4008CW-35/H | 5962-9561307HYC |
| UT54ACS00UVAH | 5962H9651201VXA | AS5C4008CW-20/H | 5962-9561309HYC | AS5C4008CW-35/H | 5962-9561312HYA |
| UT54ACS00UVCH | 5962H9651201VXC | AS5C4008CW-20L | 5962-9560012QXA | AS5C4008CW-35/H | 5962-9561312HYC |
| UT54ACS00-VDIE | 5962H9651201V9A | AS5C4008CW-20L/H | 5962-9561323HYA | AS5C4008CW-35L | 5962-9560010QXA |
| UT54ACTS00PQAH | 5962H9651301QCA | AS5C4008CW-20L/H | 5962-9561323HYC | AS5C4008CW-35L/H | 5962-9561321HYA |
| UT54ACTS00PQCH | 5962H9651301QCC | AS5C4008EC-20 | 5962-9560004MZA | AS5C4008CW-35L/H | 5962-9561321HYC |
| UT54ACTS00PVAH | 5962H9651301VCA | AS5C4008EC-20L | 5962-9560012QZA | AS5C4008CW-35L/H | 5962-9561326HYA |
| UT54ACTS00PVCH | 5962H9651301VCC | AS5C4008ECJ-20 | 5962-9560004MUA | AS5C4008CW-35L/H | 5962-9561326HYC |
| UT54ACTS00UQAH | 5962H9651301QXA | AS5C4008ECJ-20/H | 5962-9561309HTA | AS5C4008EC-35 | 5962-9560002MZA |
| UT54ACTS00UQCH | 5962H9651301QXC | AS5C4008ECJ-20/H | 5962-9561309HTC | AS5C4008EC-35L | 5962-9560010QZA |
| UT54ACTS00UVAH | 5962H9651301VXA | AS5C4008ECJ-20L | 5962-9560012QUA | AS5C4008ECJ-35 | 5962-9560002MUA |
| UT54ACTS00UVCH | 5962H9651301VXC | AS5C4008ECJ-20L/H | 5962-9561323HTA | AS5C4008ECJ-35/H | 5962-9561307HTA |
| AS5C4008CW-12 | 5962-9560016QXA | AS5C4008ECJ-20L/H | 5962-9561323HTC | AS5C4008ECJ-35/H | 5962-9561307HTC |
| AS5C4008CW-12/H | 5962-9561329HYA | AS5C4008F-20 | 5962-9560004M9A | AS5C4008ECJ-35/H | 5962-9561312HTA |
| AS5C4008CW-12/H | 5962-9561329HYC | AS5C4008F-20/H | 5962-9561309H9A | AS5C4008ECJ-35/H | 5962-9561312HTC |
| AS5C4008CW-12L | 5962-9560015QXA | AS5C4008F-20/H | 5962-9561309H9C | AS5C4008ECJ-35L | 5962-9560010QUA |
| AS5C4008CW-12L/H | 5962-9561328HYA | AS5C4008F-20L | 5962-9560012Q9A | AS5C4008ECJ-35L/H | 5962-9561321HTA |
| AS5C4008CW-12L/H | 5962-9561328HYC | AS5C4008F-20L/H | 5962-9561323H9A | AS5C4008ECJ-35L/H | 5962-9561321HTC |
| AS5C4008EC-12 | 5962-9560016QZA | AS5C4008F-20L/H | 5962-9561323H9C | AS5C4008ECJ-35L/H | 5962-9561326HTA |
| AS5C4008EC-12L | 5962-9560015QZA | AS5C4008CW-25 | 5962-9560003MXA | AS5C4008ECJ-35L/H | 5962-9561326HTC |
| AS5C4008ECJ-12 | 5962-9560016QUA | AS5C4008CW-25/H | 5962-9561308HYA | AS5C4008F-35 | 5962-9560002M9A |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART II, Listed By Generic PIN

| Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN |
|---|---|---|---|---|---|
| AS5C4008F-35/H | 5962-9561307H9A | AS5C4009CW-100/H | 5962-9561302HYA | AS5C4009CW-85/H | 5962-9561303HYC |
| AS5C4008F-35/H | 5962-9561307H9C | AS5C4009CW-100/H | 5962-9561302HYC | AS5C4009CW-85L/H | 5962-9561317HYA |
| AS5C4008F-35/H | 5962-9561312H9A | AS5C4009CW-100L/H | 5962-9561316HYA | AS5C4009CW-85L/H | 5962-9561317HYC |
| AS5C4008F-35/H | 5962-9561312H9C | AS5C4009CW-100L/H | 5962-9561316HYC | HCPL-5401 | 5962-8957001PC |
| AS5C4008F-35L | 5962-9560010Q9A | AS5C4008EC-12/H | 5962-9561329HMA | HCPL-5401#100 | 5962-8957001YA |
| AS5C4008F-35L/H | 5962-9561321H9A | AS5C4008EC-12/H | 5962-9561329HMC | HCPL-5401#100 | 5962-8957001YC |
| AS5C4008F-35L/H | 5962-9561321H9C | AS5C4008EC-12L/H | 5962-9561328HMA | HCPL-5401#200 | 5962-8957001PA |
| AS5C4008F-35L/H | 5962-9561326H9A | AS5C4008EC-12L/H | 5962-9561328HMC | HCPL-5401#300 | 5962-8957001XA |
| AS5C4008F-35L/H | 5962-9561326H9C | AS5C4009CW-120/H | 5962-9561301HYA | 54AC02DMQB | 5962-8761201CA |
| AS5C4008CW-45 | 5962-9560001MXA | AS5C4009CW-120/H | 5962-9561301HYC | 54AC02FMQB | 5962-8761201DA |
| AS5C4008CW-45/H | 5962-9561306HYA | AS5C4009CW-120L/H | 5962-9561315HYA | 54AC02K01Q | 5962-8761201XC |
| AS5C4008CW-45/H | 5962-9561306HYC | AS5C4009CW-120L/H | 5962-9561315HYC | 54AC02K01V | 5962-8761201VXC |
| AS5C4008CW-45/H | 5962-9561311HYA | AS5C4008EC-17/H | 5962-9561310HMA | 54AC02K02Q | 5962-8761201XA |
| AS5C4008CW-45/H | 5962-9561311HYC | AS5C4008EC-17/H | 5962-9561310HMC | 54AC02K02V | 5962-8761201VXA |
| AS5C4008CW-45L | 5962-9560009QXA | AS5C4008EC-17L/H | 5962-9561324HMA | 54AC02LMQB | 5962-87612012A |
| AS5C4008CW-45L/H | 5962-9561320HYA | AS5C4008EC-17L/H | 5962-9561324HMC | 54ACT02K01Q | 5962-8979101QXC |
| AS5C4008CW-45L/H | 5962-9561320HYC | AS5C4008EC-20/H | 5962-9561309HMA | 54ACT02K01V | 5962-8979101VXC |
| AS5C4008CW-45L/H | 5962-9561325HYA | AS5C4008EC-20/H | 5962-9561309HMC | 54ACT02K02Q | 5962-8979101QXA |
| AS5C4008CW-45L/H | 5962-9561325HYC | AS5C4008EC-20L/H | 5962-9561323HMA | 54ACT02K02V | 5962-8979101VXA |
| AS5C4008EC-45 | 5962-9560001MZA | AS5C4008EC-20L/H | 5962-9561323HMC | 54ACTQ02DMQB | 5962-9218101MCA |
| AS5C4008EC-45L | 5962-9560009QZA | AS5C4008EC-25/H | 5962-9561308HMA | 54ACTQ02FMQB | 5962-9218101MDA |
| AS5C4008ECJ-45 | 5962-9560001MUA | AS5C4008EC-25/H | 5962-9561308HMC | 54ACTQ02LMQB | 5962-9218101M2A |
| AS5C4008ECJ-45/H | 5962-9561306HTA | AS5C4008EC-25/H | 5962-9561313HMA | 54HC02 (GEN) | 8404101AA |
| AS5C4008ECJ-45/H | 5962-9561306HTC | AS5C4008EC-25/H | 5962-9561313HMC | 54HC02 (GEN) | 8404101BA |
| AS5C4008ECJ-45/H | 5962-9561311HTA | AS5C4008EC-25L/H | 5962-9561322HMA | 54HC02K01Q | 8404101XC |
| AS5C4008ECJ-45/H | 5962-9561311HTC | AS5C4008EC-25L/H | 5962-9561322HMC | 54HC02K01V | 5962-8404101VXC |
| AS5C4008ECJ-45L | 5962-9560009QUA | AS5C4008EC-25L/H | 5962-9561327HMA | 54HC02K02Q | 8404101XA |
| AS5C4008ECJ-45L/H | 5962-9561320HTA | AS5C4008EC-25L/H | 5962-9561327HMC | 54HC02K02V | 5962-8404101VXA |
| AS5C4008ECJ-45L/H | 5962-9561320HTC | AS5C4008EC-35/H | 5962-9561307HMA | CD54HC02F3A | 8404101CA |
| AS5C4008ECJ-45L/H | 5962-9561325HTA | AS5C4008EC-35/H | 5962-9561307HMC | CD54HCT02F3A | 5962-8975101CA |
| AS5C4008ECJ-45L/H | 5962-9561325HTC | AS5C4008EC-35/H | 5962-9561312HMA | IDT72404 (GEN) | 5962-8684401DA |
| AS5C4008F-45 | 5962-9560001M9A | AS5C4008EC-35/H | 5962-9561312HMC | SNJ54AHC02FK | 5962-9752801Q2A |
| AS5C4008F-45/H | 5962-9561306H9A | AS5C4008EC-35L/H | 5962-9561321HMA | SNJ54AHC02J | 5962-9752801QCA |
| AS5C4008F-45/H | 5962-9561306H9C | AS5C4008EC-35L/H | 5962-9561321HMC | SNJ54AHC02W | 5962-9752801QDA |
| AS5C4008F-45/H | 5962-9561311H9A | AS5C4008EC-35L/H | 5962-9561326HMA | SNJ54AHCT02FK | 5962-9757101Q2A |
| AS5C4008F-45/H | 5962-9561311H9C | AS5C4008EC-35L/H | 5962-9561326HMC | SNJ54AHCT02J | 5962-9757101QCA |
| AS5C4008F-45L | 5962-9560009Q9A | AS5C4008EC-45/H | 5962-9561306HMA | SNJ54AHCT02W | 5962-9757101QDA |
| AS5C4008F-45L/H | 5962-9561320H9A | AS5C4008EC-45/H | 5962-9561306HMC | SNJ54ALS02AFK | 5962-86844012A |
| AS5C4008F-45L/H | 5962-9561320H9C | AS5C4008EC-45/H | 5962-9561311HMA | SNJ54F02FK | 5962-9757801Q2A |
| AS5C4008F-45L/H | 5962-9561325H9A | AS5C4008EC-45/H | 5962-9561311HMC | SNJ54F02J | 5962-9757801QCA |
| AS5C4008F-45L/H | 5962-9561325H9C | AS5C4008EC-45L/H | 5962-9561320HMA | SNJ54F02W | 5962-9757801QDA |
| AS5C4008CW-55/H | 5962-9561305HYA | AS5C4008EC-45L/H | 5962-9561320HMC | SNJ54HC02FK | 84041012A |
| AS5C4008CW-55/H | 5962-9561305HYC | AS5C4008EC-45L/H | 5962-9561325HMA | SNJ54HC02J | 8404101CA |
| AS5C4008CW-55L/H | 5962-9561319HYA | AS5C4008EC-45L/H | 5962-9561325HMC | SNJ54HC02W | 8404101DA |
| AS5C4008CW-55L/H | 5962-9561319HYC | AS5C4008EC-55/H | 5962-9561305HMA | SNJ54LVC02AFK | 5962-9760401Q2A |
| AS5C4008ECJ-55/H | 5962-9561305HTA | AS5C4008EC-55/H | 5962-9561305HMC | SNJ54LVC02AJ | 5962-9760401QCA |
| AS5C4008ECJ-55/H | 5962-9561305HTC | AS5C4008EC-55L/H | 5962-9561319HMA | SNJ54LVC02AW | 5962-9760401QDA |
| AS5C4008ECJ-55L/H | 5962-9561319HTA | AS5C4008EC-55L/H | 5962-9561319HMC | SNV54HC02J | 5962-8404101VCA |
| AS5C4008ECJ-55L/H | 5962-9561319HTC | AS5C4009CW-70/H | 5962-9561304HYA | SNV54HC02W | 5962-8404101VDA |
| AS5C4008F-55/H | 5962-9561305H9A | AS5C4009CW-70/H | 5962-9561304HYC | UT54ACS02PQAH | 5962H9651401QCA |
| AS5C4008F-55/H | 5962-9561305H9C | AS5C4009CW-70L/H | 5962-9561318HYA | UT54ACS02PQCH | 5962H9651401QCC |
| AS5C4008F-55L/H | 5962-9561319H9A | AS5C4009CW-70L/H | 5962-9561318HYC | UT54ACS02PVAH | 5962H9651401VCA |
| AS5C4008F-55L/H | 5962-9561319H9C | AS5C4009CW-85/H | 5962-9561303HYA | UT54ACS02PVCH | 5962H9651401VCC |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

| Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN |
|---|---|---|---|---|---|
| UT54ACS02UQAH | 5962H9651401QXA | UT54LVDS032LVE_VDI | 5962R9865205V9A | 54ACTQ04W-QMLV | 5962-8973401VDA |
| UT54ACS02UQCH | 5962H9651401QXC | UT54LVDS032LVEUCA | 5962H9865204QYA | 54F04DMQB | 5962-9759301QCA |
| UT54ACS02UVAH | 5962H9651401VXA | UT54LVDS032LVEUCA | 5962H9865204VYA | 54F04FMQB | 5962-9759301QDA |
| UT54ACS02UVCH | 5962H9651401VXC | UT54LVDS032LVEUCA | 5962R9865205QYA | 54F04LMQB | 5962-9759301Q2A |
| UT54ACTS02PQAH | 5962H9651501QCA | UT54LVDS032LVEUCA | 5962R9865205VYA | 54HC04 (GEN) | 8409801BA |
| UT54ACTS02PQCH | 5962H9651501QCC | UT54LVDS032LVEUCC | 5962H9865204QYC | 54HC04K01Q | 8409801XC |
| UT54ACTS02PVAH | 5962H9651501VCA | UT54LVDS032LVEUCC | 5962H9865204VYC | 54HC04K01V | 5962-8409801VXC |
| UT54ACTS02PVCH | 5962H9651501VCC | UT54LVDS032LVEUCC | 5962R9865205QYC | 54HC04K02Q | 8409801XA |
| UT54ACTS02UQAH | 5962H9651501QXA | UT54LVDS032LVEUCC | 5962R9865205VYC | 54HC04K02V | 5962-8409801VXA |
| UT54ACTS02UQCH | 5962H9651501QXC | UT54LVDS032LVTUCA | 5962H0420101QYA | RHFAC04K01Q | 5962F8760901XC |
| UT54ACTS02UVAH | 5962H9651501VXA | UT54LVDS032LVTUCA | 5962H0420101VYA | RHFAC04K01V | 5962F8760901VXC |
| UT54ACTS02UVCH | 5962H9651501VXC | UT54LVDS032LVTUCA | 5962R0420102QYA | RHFAC04K02Q | 5962F8760901XA |
| SNJ54HC03FK | 5962-87647012A | UT54LVDS032LVTUCA | 5962R0420102VYA | RHFAC04K02V | 5962F8760901VXA |
| SNJ54HC03J | 5962-8764701CA | UT54LVDS032LVTUCC | 5962H0420101QYC | SNJ54AC04FK | 5962-87609012A |
| UT54LVDS031LV_QDIE | 5962H9865102Q9A | UT54LVDS032LVTUCC | 5962H0420101VYC | SNJ54AC04J | 5962-8760901CA |
| UT54LVDS031LV_QDIE | 5962R9865103Q9A | UT54LVDS032LVTUCC | 5962R0420102QYC | SNJ54AC04W | 5962-8760901DA |
| UT54LVDS031LV_VDIE | 5962H9865102V9A | UT54LVDS032LVTUCC | 5962R0420102VYC | SNJ54ACT04FK | 5962-89734012A |
| UT54LVDS031LV_VDIE | 5962R9865103V9A | UT54LVDS032LVUCA | 5962H9865202QYA | SNJ54ACT04J | 5962-8973401CA |
| UT54LVDS031LVE_QDI | 5962H9865104Q9A | UT54LVDS032LVUCA | 5962H9865202VYA | SNJ54ACT04W | 5962-8973401DA |
| UT54LVDS031LVE_QDI | 5962R9865105Q9A | UT54LVDS032LVUCA | 5962R9865203QYA | SNJ54AHC04FK | 5962-9680501Q2A |
| UT54LVDS031LVE_VDI | 5962H9865104V9A | UT54LVDS032LVUCA | 5962R9865203VYA | SNJ54AHC04J | 5962-9680501QCA |
| UT54LVDS031LVE_VDI | 5962R9865105V9A | UT54LVDS032LVUCC | 5962H9865202QYC | SNJ54AHC04W | 5962-9680501QDA |
| UT54LVDS031LVEUCA | 5962H9865104QYA | UT54LVDS032LVUCC | 5962H9865202VYC | SNJ54AHCT04FK | 5962-9680401Q2A |
| UT54LVDS031LVEUCA | 5962H9865104VYA | UT54LVDS032LVUCC | 5962R9865203QYC | SNJ54AHCT04J | 5962-9680401QCA |
| UT54LVDS031LVEUCA | 5962R9865105QYA | UT54LVDS032LVUCC | 5962R9865203VYC | SNJ54AHCT04W | 5962-9680401QDA |
| UT54LVDS031LVEUCA | 5962R9865105VYA | UT54LVDS032-QDIE | 5962F9583403Q9A | SNJ54AHCU04FK | 5962-9680301Q2A |
| UT54LVDS031LVEUCC | 5962H9865104QYC | UT54LVDS032-QDIE | 5962H9583402Q9A | SNJ54AHCU04J | 5962-9680301QCA |
| UT54LVDS031LVEUCC | 5962H9865104VYC | UT54LVDS032UCA | 5962H9583402QXA | SNJ54AHCU04W | 5962-9680301QDA |
| UT54LVDS031LVEUCC | 5962R9865105QYC | UT54LVDS032UCA | 5962H9583402VXA | SNJ54ALS04BFK | 5962-86843012A |
| UT54LVDS031LVEUCC | 5962R9865105VYC | UT54LVDS032UCC | 5962H9583402QXC | SNJ54ALS04BW | 5962-8684301DA |
| UT54LVDS031LVUCA | 5962H9865102QYA | UT54LVDS032UCC | 5962H9583402VXC | SNJ54F04FK | 5962-9759301Q2A |
| UT54LVDS031LVUCA | 5962H9865102VYA | UT54LVDS032-VDIE | 5962F9583403V9A | SNJ54F04J | 5962-9759301QCA |
| UT54LVDS031LVUCA | 5962R9865103QYA | UT54LVDS032-VDIE | 5962H9583402V9A | SNJ54F04W | 5962-9759301QDA |
| UT54LVDS031LVUCA | 5962R9865103VYA | UT54LVDSC032UCA | 5962F9583403QXA | SNJ54HC04FK | 84098012A |
| UT54LVDS031LVUCC | 5962H9865102QYC | UT54LVDSC032UCA | 5962F9583403VXA | SNJ54HC04J | 8409801CA |
| UT54LVDS031LVUCC | 5962H9865102VYC | UT54LVDSC032UCC | 5962F9583403QXC | SNJ54HC04W | 8409801DA |
| UT54LVDS031LVUCC | 5962R9865103QYC | UT54LVDSC032UCC | 5962F9583403VXC | SNJ54HCT04FK | 5962-89747012A |
| UT54LVDS031LVUCC | 5962R9865103VYC | 54AC04DMQB | 5962-8760901CA | SNJ54HCT04J | 5962-8974701CA |
| UT54LVDS031UCA | 5962H9583302QXA | 54AC04FMQB | 5962-8760901DA | SNJ54HCU04FK | 86010012A |
| UT54LVDS031UCA | 5962H9583302VXA | 54AC04K01Q | 5962-8760901XC | SNJ54HCU04J | 8601001CA |
| UT54LVDS031UCC | 5962H9583302QXC | 54AC04K01V | 5962-8760901VXC | SNJ54LVC04AFK | 5962-9760501Q2A |
| UT54LVDS031UCC | 5962H9583302VXC | 54AC04K02Q | 5962-8760901XA | SNJ54LVC04AJ | 5962-9760501QCA |
| UT54LVDSC031UCA | 5962F9583303QXA | 54AC04K02V | 5962-8760901VXA | SNJ54LVC04AW | 5962-9760501QDA |
| UT54LVDSC031UCA | 5962F9583303VXA | 54AC04LMQB | 5962-87609012A | SNV54ACT04J | 5962-8973401VCA |
| UT54LVDSC031UCC | 5962F9583303QXC | 54ACT04K01Q | 5962-8973403XC | SNV54ACT04W | 5962-8973401VDA |
| UT54LVDSC031UCC | 5962F9583303VXC | 54ACT04K01V | 5962-8973403VXC | SNV54HC04J | 5962-8409801VCA |
| UT54LVDS032LV_QDIE | 5962H9865202Q9A | 54ACT04K02Q | 5962-8973403XA | SNV54HC04W | 5962-8409801VDA |
| UT54LVDS032LV_QDIE | 5962R9865203Q9A | 54ACT04K02V | 5962-8973403VXA | SNV54HCT04J | 5962-8974701VCA |
| UT54LVDS032LV_VDIE | 5962H9865202V9A | 54ACTQ04DMQB | 5962-8973401CA | SNV54HCT04W | 5962-8974701VDA |
| UT54LVDS032LV_VDIE | 5962R9865203V9A | 54ACTQ04E-QMLV | 5962-8973401V2A | UT54ACS04PQAH | 5962H9651601QCA |
| UT54LVDS032LVE_QDI | 5962H9865204Q9A | 54ACTQ04FMQB | 5962-8973401DA | UT54ACS04PQCH | 5962H9651601QCC |
| UT54LVDS032LVE_QDI | 5962R9865205Q9A | 54ACTQ04J-QMLV | 5962-8973401VCA | UT54ACS04PVAH | 5962H9651601VCA |
| UT54LVDS032LVE_VDI | 5962H9865204V9A | 54ACTQ04LMQB | 5962-89734012A | UT54ACS04PVCH | 5962H9651601VCC |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

| Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN |
|---|---|---|---|---|---|
| UT54ACS04-QDIE | 5962H9651601Q9A | 54ACTQ08DMQB-RH | 5962R8954702CA | UT54ACS08PVAH | 5962H9651801VCA |
| UT54ACS04UQAH | 5962H9651601QXA | 54ACTQ08ERQMLV | 5962R8954702V2A | UT54ACS08PVCH | 5962H9651801VCC |
| UT54ACS04UQCH | 5962H9651601QXC | 54ACTQ08FMQB | 5962-8954702DA | UT54ACS08UQAH | 5962H9651801QXA |
| UT54ACS04UVAH | 5962H9651601VXA | 54ACTQ08FMQB-RH | 5962R8954702DA | UT54ACS08UQCH | 5962H9651801QXC |
| UT54ACS04UVCH | 5962H9651601VXC | 54ACTQ08JRQMLV | 5962R8954702VCA | UT54ACS08UVAH | 5962H9651801VXA |
| UT54ACS04-VDIE | 5962H9651601V9A | 54ACTQ08LMQB | 5962-89547022A | UT54ACS08UVCH | 5962H9651801VXC |
| UT54ACTS04PQAH | 5962H9651701QCA | 54ACTQ08LMQB-RH | 5962R89547022A | UT54ACTS08EUQAG | 5962G9651903QXA |
| UT54ACTS04PQCH | 5962H9651701QCC | 54ACTQ08WRQMLV | 5962R8954702VDA | UT54ACTS08EUQAH | 5962H9651902QXA |
| UT54ACTS04PVAH | 5962H9651701VCA | 54C08 (GEN) | 7703601AA | UT54ACTS08EUQCG | 5962G9651903QXC |
| UT54ACTS04PVCH | 5962H9651701VCC | 54C08 (GEN) | 7703601DA | UT54ACTS08EUQCH | 5962H9651902QXC |
| UT54ACTS04UQAH | 5962H9651701QXA | 54HC08 (GEN) | 8404701BA | UT54ACTS08EUVAG | 5962G9651903VXA |
| UT54ACTS04UQCH | 5962H9651701QXC | 54HC08K01Q | 8404701XC | UT54ACTS08EUVAH | 5962H9651902VXA |
| UT54ACTS04UVAH | 5962H9651701VXA | 54HC08K01V | 5962-8404701VXC | UT54ACTS08EUVCG | 5962G9651903VXC |
| UT54ACTS04UVCH | 5962H9651701VXC | 54HC08K02Q | 8404701XA | UT54ACTS08EUVCH | 5962H9651902VXC |
| 54AC05 (GEN) | 5962-9059001B2A | 54HC08K02V | 5962-8404701VXA | UT54ACTS08PQAH | 5962H9651901QCA |
| 54AC05 (GEN) | 5962-9059001BCA | 72404L10 (GEN) | 5962-8684201DA | UT54ACTS08PQCH | 5962H9651901QCC |
| 54AC05 (GEN) | 5962-9059001BDA | CD54HC08F3A | 8404701CA | UT54ACTS08PVAH | 5962H9651901VCA |
| 54AC05 (GEN) | 5962-9059001S2A | CD54HCT08F3A | 5962-8688301CA | UT54ACTS08PVCH | 5962H9651901VCC |
| 54AC05 (GEN) | 5962-9059001SCA | MM54C08J/883B | 7703601CA | UT54ACTS08UQAH | 5962H9651901QXA |
| 54AC05 (GEN) | 5962-9059001SDA | RHFAC08K01Q | 5962F8761501XC | UT54ACTS08UQCH | 5962H9651901QXC |
| 54AC05DMQB | 5962-9059001MCA | RHFAC08K01V | 5962F8761501VXC | UT54ACTS08UVAH | 5962H9651901VXA |
| 54AC05FMQB | 5962-9059001MDA | RHFAC08K02Q | 5962F8761501XA | UT54ACTS08UVCH | 5962H9651901VXC |
| 54AC05LMQB | 5962-9059001M2A | RHFAC08K02V | 5962F8761501VXA | 54F09 (GEN) | 5962-88723012A |
| SNJ54ALS05AFK | 5962-88540012A | RHFACT08K01Q | 5962F8954703XC | 54F09 (GEN) | 5962-8872301CA |
| SNJ54ALS05AJ | 5962-8854001CA | RHFACT08K01V | 5962F8954703VXC | 54F09 (GEN) | 5962-8872301DA |
| SNJ54ALS05AW | 5962-8854001DA | RHFACT08K02Q | 5962F8954703XA | 54HC09 (GEN) | 5962-88620012A |
| SNJ54HC05FK | 5962-88718012A | RHFACT08K02V | 5962F8954703VXA | 54HC09 (GEN) | 5962-8862001CA |
| SNJ54HC05J | 5962-8871801CA | SNJ54AC08FK | 5962-87615012A | SL54LS09/B2A | 80019012A |
| JM54AC05B2A-RH | 5962R9059001B2A | SNJ54AC08J | 5962-8761501CA | SL54LS09/B2C | 80019012C |
| JM54AC05BCA-RH | 5962R9059001BCA | SNJ54AC08W | 5962-8761501DA | SL54LS09/BCA | 8001901CA |
| JM54AC05BDA-RH | 5962R9059001BDA | SNJ54ACT08FK | 5962-89547022A | SL54LS09/BDA | 8001901DA |
| JM54AC05S2A-RH | 5962R9059001S2A | SNJ54ACT08J | 5962-8954702CA | SNJ54ALS09FK | 84142012A |
| JM54AC05SCA-RH | 5962R9059001SCA | SNJ54ACT08W | 5962-8954702DA | SNJ54ALS09J | 8414201CA |
| JM54AC05SDA-RH | 5962R9059001SDA | SNJ54AHC08FK | 5962-9682001Q2A | SNJ54ALS09W | 8414201DA |
| JM54AC05SZA-RH | 5962R9059001SZA | SNJ54AHC08J | 5962-9682001QCA | SNJ54ALS09WA | 8414201BA |
| CD54ACT05F3A | 5962-9068601QCA | SNJ54AHC08W | 5962-9682001QDA | SNJ54LS09FK | 80019012A |
| SNJ54LS06FK | 5962-9861701Q2A | SNJ54AHCT08FK | 5962-9682101Q2A | SNJ54LS09J | 8001901CA |
| SNJ54LS06J | 5962-9861701QCA | SNJ54AHCT08J | 5962-9682101QCA | SNJ54LS09W | 8001901DA |
| 54AC08DMQB | 5962-8761501CA | SNJ54AHCT08W | 5962-9682101QDA | HCPL-540K | 5962-8957002KPC |
| 54AC08FMQB | 5962-8761501DA | SNJ54ALS08FK | 5962-86842012A | HCPL-540K#100 | 5962-8957002KYA |
| 54AC08K01Q | 5962-8761501XC | SNJ54ALS08J | 5962-8684201CA | HCPL-540K#100 | 5962-8957002KYC |
| 54AC08K01V | 5962-8761501VXC | SNJ54HC08FK | 84047012A | HCPL-540K#200 | 5962-8957002KPA |
| 54AC08K02Q | 5962-8761501XA | SNJ54HC08J | 8404701CA | HCPL-540K#300 | 5962-8957002KXA |
| 54AC08K02V | 5962-8761501VXA | SNJ54HC08W | 8404701DA | ACS541 (GEN) | 5962F9671001VRC |
| 54AC08LMQB | 5962-87615012A | SNJ54LVC08AFK | 5962-9753401Q2A | ACS541 (GEN) | 5962F9671001VXC |
| 54ACT08K01Q | 5962-8954703XC | SNJ54LVC08AJ | 5962-9753401QCA | ACTS541 (GEN) | 5962F9672601VRC |
| 54ACT08K01V | 5962-8954703VXC | SNJ54LVC08AW | 5962-9753401QDA | ACTS541 (GEN) | 5962F9672601VXC |
| 54ACT08K02Q | 5962-8954703XA | SNV54AHCT08J | 5962-9682101VCA | DG541AP/883 | 5962-9076401MEA |
| 54ACT08K02V | 5962-8954703VXA | SNV54AHCT08W | 5962-9682101VDA | HCTS541DMSR | 5962R9575101VRC |
| 54ACTQ08 (GEN) | 5962-8954702V2A | SNV54HC08J | 5962-8404701VCA | HCTS541HMSR | 5962R9575101V9A |
| 54ACTQ08 (GEN) | 5962-8954702VCA | SNV54HC08W | 5962-8404701VDA | HCTS541KMSR | 5962R9575101VXC |
| 54ACTQ08 (GEN) | 5962-8954702VDA | UT54ACS08PQAH | 5962H9651801QCA | MSK541B | 5962-8870101XA |
| 54ACTQ08DMQB | 5962-8954702CA | UT54ACS08PQCH | 5962H9651801QCC | MSK541B | 5962-8870101XC |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

| Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN |
|---|---|---|---|---|---|
| OMA541SDB | 5962-8870101YA | UT54ACTS10PQCH | 5962H9652101QCC | CD54HCT107F3A | 5962-9084901MCA |
| OMA541SDZB | 5962-8870101UA | UT54ACTS10PVAH | 5962H9652101VCA | 54AC109DMQB | 5962-8955101EA |
| OMA541SKB | 5962-8870101XA | UT54ACTS10PVCH | 5962H9652101VCC | 54AC109FMQB | 5962-8955101FA |
| OMA541SKCB | 5962-8870102XA | UT54ACTS10UQAH | 5962H9652101QXA | 54AC109K01Q | 5962-8955101XC |
| 54AC10DMQB | 5962-8761001CA | UT54ACTS10UQCH | 5962H9652101QXC | 54AC109K01V | 5962-8955101VXC |
| 54AC10FMQB | 5962-8761001DA | UT54ACTS10UVAH | 5962H9652101VXA | 54AC109K02Q | 5962-8955101XA |
| 54AC10K01Q | 5962-8761001XC | UT54ACTS10UVCH | 5962H9652101VXC | 54AC109K02V | 5962-8955101VXA |
| 54AC10K01V | 5962-8761001VXC | 54ALS1000A (GEN) | 84059012A | 54AC109LMQB | 5962-89551012A |
| 54AC10K02Q | 5962-8761001XA | 54ALS1000A (GEN) | 8405901BA | 54ACS109 (GEN) | 5962H9654001Q9A |
| 54AC10K02V | 5962-8761001VXA | 54ALS1000A (GEN) | 8405901CA | 54ACS109 (GEN) | 5962H9654001QEA |
| 54AC10LMQB | 5962-87610012A | 54ALS1000A (GEN) | 8405901DA | 54ACS109 (GEN) | 5962H9654001QXA |
| 54ACT10K01Q | 5962-9218202QXC | SNJ54AS1000AFK | 5962-9162701M2A | 54ACS109 (GEN) | 5962H9654001V9A |
| 54ACT10K01V | 5962-9218202VXC | SNJ54AS1000AJ | 5962-9162701MCA | 54ACS109 (GEN) | 5962H9654001VEA |
| 54ACT10K02Q | 5962-9218202QXA | SNJ54AS1000AW | 5962-9162701MDA | 54ACS109 (GEN) | 5962H9654001VXA |
| 54ACT10K02V | 5962-9218202VXA | 54ALS1004 (GEN) | 84061012A | 54ACT109DMQB | 5962-8853401EA |
| 54ACTQ10DMQB | 5962-9218201MCA | 54ALS1004 (GEN) | 8406101BA | 54ACT109DMQB-RH | 5962R8853401EA |
| 54ACTQ10FMQB | 5962-9218201MDA | 54ALS1004 (GEN) | 8406101CA | 54ACT109ERQMLV | 5962R8853401V2A |
| 54ACTQ10LMQB | 5962-9218201M2A | 54ALS1004 (GEN) | 8406101DA | 54ACT109FMQB | 5962-8853401FA |
| 54HC10 (GEN) | 8403801AA | SNJ54AS1004AFK | 5962-88729012A | 54ACT109FMQB-RH | 5962R8853401FA |
| 54HC10 (GEN) | 8403801BA | SNJ54AS1004AJ | 5962-8872901CA | 54ACT109JRQMLV | 5962R8853401VEA |
| 54HC10K01Q | 8403801XC | SNJ54AS1004AW | 5962-8872901DA | 54ACT109K01Q | 5962-8853401XC |
| 54HC10K01V | 5962-8403801VXC | 54ALS1008A (GEN) | 84097012A | 54ACT109K01V | 5962-8853401VXA |
| 54HC10K02Q | 8403801XA | 54ALS1008A (GEN) | 8409701BA | 54ACT109K02Q | 5962-8853401XA |
| 54HC10K02V | 5962-8403801VXA | 54ALS1008A (GEN) | 8409701CA | 54ACT109K02V | 5962-8853401VXA |
| CD54HC10F3A | 8403801CA | 54ALS1008A (GEN) | 8409701DA | 54ACT109LMQB | 5962-88534012A |
| RHFACT10K01Q | 5962F9218202QXC | 54ALS1010A (GEN) | 84060012A | 54ACT109LMQB-RH | 5962R88534012A |
| RHFACT10K01V | 5962F9218202VXC | 54ALS1010A (GEN) | 8406001BA | 54ACT109WRQMLV | 5962R8853401VFA |
| RHFACT10K02Q | 5962F9218202QXA | 54ALS1010A (GEN) | 8406001CA | 54HC109K01Q | 8415001XC |
| RHFACT10K02V | 5962F9218202VXA | 54ALS1010A (GEN) | 8406001DA | 54HC109K01V | 5962-8415001VXC |
| SNJ54AC10FK | 5962-87610012A | ACS541 (GEN) | 5962F9671002VRC | 54HC109K02Q | 8415001XA |
| SNJ54AC10J | 5962-8761001CA | ACS541HMSR-02 | 5962F9671002V9A | 54HC109K02V | 5962-8415001VXA |
| SNJ54AC10W | 5962-8761001DA | ACS541KMSR-02 | 5962F9671002VXC | CD54HC109F3A | 8415001EA |
| SNJ54ACT10FK | 5962-9218201M2A | ACTS541-02 (GEN) | 5962F9672602V9A | CD54HCT109F3A | 5962-9070101MEA |
| SNJ54ACT10J | 5962-9218201MCA | ACTS541-02 (GEN) | 5962F9672602VRC | SNJ54ALS109AFK | 84000012A |
| SNJ54ACT10W | 5962-9218201MDA | ACTS541-02 (GEN) | 5962F9672602VXC | SNJ54ALS109AJ | 8400001EA |
| SNJ54ALS10AFK | 5962-86865012A | ACTS541-02 (GEN) | 5962R9672602TRC | SNJ54ALS109AW | 8400001FA |
| SNJ54ALS10AJ | 5962-8686501CA | ACTS541-02 (GEN) | 5962R9672602TXC | SNJ54F109FK | 5962-9758001Q2A |
| SNJ54ALS10AW | 5962-8686501DA | CD54HCT10F3A | 5962-8984301CA | SNJ54F109J | 5962-9758001QEA |
| SNJ54F10FK | 5962-9757901Q2A | 54AS1032A (GEN) | 5962-8873001CA | SNJ54F109W | 5962-9758001QFA |
| SNJ54F10J | 5962-9757901QCA | SNJ54AS1032AFK | 5962-88730012A | SNJ54HC109FK | 84150012A |
| SNJ54F10W | 5962-9757901QDA | SNJ54AS1032AW | 5962-8873001DA | SNJ54HC109J | 8415001EA |
| SNJ54HC10FK | 84038012A | SNJ54ALS1034FK | 84031012A | SNJ54HC109W | 8415001FA |
| SNJ54HC10J | 8403801CA | SNJ54ALS1034J | 8403101CA | UT54ACS109E-Q-DIE | 5962G9654003Q9B |
| SNJ54HC10W | 8403801DA | SNJ54ALS1034W | 8403101DA | UT54ACS109E-Q-DIE | 5962H9654002Q9B |
| UT54ACS10PQAH | 5962H9652001QCA | SNJ54ALS1034WA | 8403101BA | UT54ACS109EUQAG | 5962G9654003QXA |
| UT54ACS10PQCH | 5962H9652001QCC | SNJ54AS1034AFK | 5962-88731012A | UT54ACS109EUQAH | 5962H9654002QXA |
| UT54ACS10PVAH | 5962H9652001VCA | SNJ54AS1034AJ | 5962-8873101CA | UT54ACS109EUQCG | 5962G9654003QXC |
| UT54ACS10PVCH | 5962H9652001VCC | SNJ54AS1034AW | 5962-8873101DA | UT54ACS109EUQCH | 5962H9654002QXC |
| UT54ACS10UQAH | 5962H9652001QXA | SNJ54ALS1035FK | 5962-88742012A | UT54ACS109EUVAG | 5962G9654003VXA |
| UT54ACS10UQCH | 5962H9652001QXC | SNJ54ALS1035J | 5962-8874201CA | UT54ACS109EUVAH | 5962H9654002VXA |
| UT54ACS10UVAH | 5962H9652001VXA | SNJ54ALS1035W | 5962-8874201DA | UT54ACS109EUVCG | 5962G9654003VXC |
| UT54ACS10UVCH | 5962H9652001VXC | 54HC107 (GEN) | 5962-85154012A | UT54ACS109EUVCH | 5962H9654002VXC |
| UT54ACTS10PQAH | 5962H9652101QCA | CD54HC107F3A | 5962-8515401CA | UT54ACS109E-V-DIE | 5962G9654003V9B |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

| Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN |
|---|---|---|---|---|---|
| UT54ACS109E-V-DIE | 5962H9654002V9B | UT54ACTS11PQAH | 5962H9652301QCA | 54ACT11138/BEA | 5962-8755402MEA |
| UT54ACS109UQAG | 5962G9654001QXA | UT54ACTS11PQCH | 5962H9652301QCC | 54ACT112DMQB | 5962-8995001MEA |
| UT54ACS109UQCG | 5962G9654001QXC | UT54ACTS11PVAH | 5962H9652301VCA | 54ACT112FMQB | 5962-8995001MFA |
| UT54ACS109UVAG | 5962G9654001VXA | UT54ACTS11PVCH | 5962H9652301VCC | 54ACT112LMQB | 5962-8995001M2A |
| UT54ACS109UVCG | 5962G9654001VXC | UT54ACTS11UQAH | 5962H9652301QXA | 54F112/2A | 5962-90606022A |
| UT54ACTS109PQAH | 5962H9654101QEA | UT54ACTS11UQCH | 5962H9652301QXC | 54F112/EA | 5962-9060602EA |
| UT54ACTS109PQCH | 5962H9654101QEC | UT54ACTS11UVAH | 5962H9652301VXA | 54F112/FA | 5962-9060602FA |
| UT54ACTS109PVAH | 5962H9654101VEA | UT54ACTS11UVCH | 5962H9652301VXC | CD54HCT112F3A | 5962-8970201EA |
| UT54ACTS109PVCH | 5962H9654101VEC | 54AC11000 (GEN) | 5962-87549022A | JM54ACT112B2A | 5962-8995001B2A |
| UT54ACTS109UQAH | 5962H9654101QXA | 54AC11000 (GEN) | 5962-8754902EA | JM54ACT112BEA | 5962-8995001BEA |
| UT54ACTS109UQCH | 5962H9654101QXC | 54AC11000 (GEN) | 5962-8754902FA | JM54ACT112BFA | 5962-8995001BFA |
| UT54ACTS109UVAH | 5962H9654101VXA | 54ACT11000 (GEN) | 5962-87699022A | JM54ACT112S2A | 5962-8995001S2A |
| UT54ACTS109UVCH | 5962H9654101VXC | 54ACT11000 (GEN) | 5962-8769902EA | JM54ACT112SEA | 5962-8995001SEA |
| 54AC11DMQB | 5962-8761101CA | 54ACT11000/B2A | 5962-8769902M2A | JM54ACT112SFA | 5962-8995001SFA |
| 54AC11FMQB | 5962-8761101DA | 54ACT11000/BEA | 5962-8769902MEA | SNJ54ALS112AFK | 84000022A |
| 54AC11K01Q | 5962-8761101XC | 54AC11002 (GEN) | 5962-87612022A | SNJ54ALS112AJ | 8400002EA |
| 54AC11K01V | 5962-8761101VXC | 54AC11002 (GEN) | 5962-8761202EA | SNJ54ALS112AW | 8400002FA |
| 54AC11K02Q | 5962-8761101XA | 54AC11002 (GEN) | 5962-8761202FA | SNJ54HC112FK | 84088012A |
| 54AC11K02V | 5962-8761101VXA | 54AC11004/B2A | 5962-87609022A | SNJ54HC112J | 8408801EA |
| 54AC11LMQB | 5962-87611012A | 54AC11004/BRA | 5962-8760902RA | SNJ54HC112W | 8408801FA |
| 54ACT11K01Q | 5962-9077202QXC | 54AC11004/BSA | 5962-8760902SA | 54AC11240/B3A | 5962-87550023A |
| 54ACT11K01V | 5962-9077202VXC | 54ACT11004/B2A | 5962-89734022A | 54AC11240/BJA | 5962-8755002JA |
| 54ACT11K02Q | 5962-9077202QXA | 54ACT11004/BRA | 5962-8973402RA | 54AC11240/BKA | 5962-8755002KA |
| 54ACT11K02V | 5962-9077202VXA | 54AC11008 (GEN) | 5962-87615022A | 54ACT11240 (GEN) | 5962-87759023A |
| 54HC11 (GEN) | 8404801AA | 54AC11008 (GEN) | 5962-8761502EA | 54ACT11240 (GEN) | 5962-8775902LA |
| 54HC11 (GEN) | 8404801BA | 54ACT11008 (GEN) | 5962-89547012A | 54ACT11240 (GEN) | 5962-8775902M3A |
| CD54HC11F3A | 8404801CA | 54ACT11008 (GEN) | 5962-8954701EA | 54ACT11240 (GEN) | 5962-8775902MLA |
| CD54HCT11F3A | 5962-8970901CA | 54AC11010 (GEN) | 5962-87610022A | 54AC11241/B3A | 5962-87551023A |
| SNJ54AC11FK | 5962-87611012A | 54AC11010 (GEN) | 5962-8761002EA | 54AC11241/BLA | 5962-8755102LA |
| SNJ54AC11J | 5962-8761101CA | 54AC11010 (GEN) | 5962-8761002FA | 54ACT11241/B3A | 5962-89847023A |
| SNJ54AC11W | 5962-8761101DA | 54AC11011/B2A | 5962-87611022A | 54ACT11241/BLA | 5962-8984702LA |
| SNJ54ACT11FK | 5962-9077201Q2A | 54AC11011/BEA | 5962-8761102EA | 54AC11244 (GEN) | 5962-87552023A |
| SNJ54ACT11J | 5962-9077201QCA | 54AC11011/BFA | 5962-8761102FA | 54AC11244 (GEN) | 5962-8755202JA |
| SNJ54ACT11W | 5962-9077201QDA | 54AC11020 (GEN) | 5962-87613022A | 54AC11244 (GEN) | 5962-8755202KA |
| SNJ54ALS11AFK | 5962-86841012A | 54AC11020 (GEN) | 5962-8761302CA | 54AC11244 (GEN) | 5962-8755202LA |
| SNJ54ALS11AJ | 5962-8684101CA | 54AC11020 (GEN) | 5962-8761302DA | 54ACT11244 (GEN) | 5962-87760023A |
| SNJ54ALS11AW | 5962-8684101DA | 54AC11032 (GEN) | 5962-87614022A | 54ACT11244 (GEN) | 5962-8776002LA |
| SNJ54AS11FK | 5962-9756101Q2A | 54AC11032 (GEN) | 5962-8761402EA | 54ACT11244 (GEN) | 5962-8776002M3A |
| SNJ54AS11J | 5962-9756101QCA | 54ACT11032 (GEN) | 5962-89736022A | 54ACT11244 (GEN) | 5962-8776002MLA |
| SNJ54F11FK | 5962-9758101Q2A | 54ACT11032 (GEN) | 5962-8973602EA | 54ACT11245/B3A | 5962-8766302M3A |
| SNJ54F11J | 5962-9758101QCA | 54AC11074 (GEN) | 5962-88520022A | 54ACT11245/BLA | 5962-8766302MLA |
| SNJ54F11W | 5962-9758101QDA | 54AC11074 (GEN) | 5962-8852002CA | 54F113 (GEN) | 5962-90606012A |
| SNJ54HC11FK | 84048012A | 54AC11074 (GEN) | 5962-8852002DA | 54F113 (GEN) | 5962-9060601CA |
| SNJ54HC11J | 8404801CA | 54ACT11074 (GEN) | 5962-87525022A | 54F113 (GEN) | 5962-9060601DA |
| SNJ54HC11W | 8404801DA | 54ACT11074 (GEN) | 5962-8752502CA | 54HC113 (GEN) | 5962-89695012A |
| UT54ACS11PQAH | 5962H9652201QCA | 54ACT11074 (GEN) | 5962-8752502DA | 54HC113 (GEN) | 5962-8969501CA |
| UT54ACS11PQCH | 5962H9652201QCC | 54ACT11074/B2A | 5962-8752502M2A | 54ACT11353/B2A | 5962-9090601M2A |
| UT54ACS11PVAH | 5962H9652201VCA | 54ACT11074/BCA | 5962-8752502MCA | 54ACT11353/BEA | 5962-9090601MEA |
| UT54ACS11PVCH | 5962H9652201VCC | 54ACT11074/BDA | 5962-8752502MDA | 54AC11373 (GEN) | 5962-87555023A |
| UT54ACS11UQAH | 5962H9652201QXA | 54ACT11109/B2A | 5962-88534022A | 54AC11373 (GEN) | 5962-8755502LA |
| UT54ACS11UQCH | 5962H9652201QXC | 54ACT11109/BEA | 5962-8853402EA | 54ACT11373 (GEN) | 5962-87556023A |
| UT54ACS11UVAH | 5962H9652201VXA | 54ACT11109/BFA | 5962-8853402FA | 54ACT11373 (GEN) | 5962-8755602LA |
| UT54ACS11UVCH | 5962H9652201VXC | 54ACT11138/B2A | 5962-8755402M2A | 54ACT11374/B3A | 5962-87631023A |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

| Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN |
|---|---|---|---|---|---|
| 54ACT11374/BLA | 5962-8763102LA | JM54AC125BCA-RH | 5962R9325301BCA | 54HC132K02V | 5962-8984502VXA |
| 54AC11520 (GEN) | 5962-9091602M2A | JM54AC125BDA | 5962-9325301BDA | CD54HCT132F3A | 5962-8984501CA |
| 54AC11520 (GEN) | 5962-9091602MRA | JM54AC125BDA-RH | 5962R9325301BDA | SNJ54HC132FK | 5962-89845022A |
| 54ACT11520 (GEN) | 5962-89793032A | JM54AC125S2A-RH | 5962R9325301S2A | SNJ54HC132J | 5962-8984502CA |
| 54ACT11520 (GEN) | 5962-8979303RA | JM54AC125SCA-RH | 5962R9325301SCA | SNJ54HC132W | 5962-8984502DA |
| 54AC11521 (GEN) | 5962-9098502M2A | JM54AC125SDA-RH | 5962R9325301SDA | SNJ54LS132J | 7600401CA |
| 54AC11521 (GEN) | 5962-9098502MRA | SNJ54ABT125FK | 5962-9676801Q2A | SNJ54LS132W | 7600401DA |
| 54ACT11521/B2A | 5962-89793042A | SNJ54ABT125J | 5962-9676801QCA | SNV54HC132J | 5962-8984502VCA |
| 54ACT11521/BRA | 5962-8979304RA | SNJ54ABT125W | 5962-9676801QDA | SNV54HC132W | 5962-8984502VDA |
| 54ACT11534/B3A | 5962-89658023A | SNJ54AHC125FK | 5962-9686801Q2A | UT54ACS132E-Q-DIE | 5962G9654203Q9B |
| 54ACT11534/BLA | 5962-8965802LA | SNJ54AHC125J | 5962-9686801QCA | UT54ACS132E-Q-DIE | 5962H9654202Q9B |
| 5412-S (GEN) | 5962-9095702MQA | SNJ54AHC125W | 5962-9686801QDA | UT54ACS132EUQAG | 5962G9654203QXA |
| 5412-S (GEN) | 5962-9095702MXA | SNJ54AHCT125FK | 5962-9686901Q2A | UT54ACS132EUQAH | 5962H9654202QXA |
| 5412-T (GEN) | 5962-9095701MQA | SNJ54AHCT125J | 5962-9686901QCA | UT54ACS132EUQCG | 5962G9654203QXC |
| 5412-T (GEN) | 5962-9095701MXA | SNJ54AHCT125W | 5962-9686901QDA | UT54ACS132EUQCH | 5962H9654202QXC |
| SNJ54121J | 5962-9755301QCA | SNJ54BCT125FK | 5962-9093701M2A | UT54ACS132EUVAG | 5962G9654203VXA |
| SNJ54121W | 5962-9755301QDA | SNJ54BCT125J | 5962-9093701MCA | UT54ACS132EUVAH | 5962H9654202VXA |
| 54LS122 (GEN) | 76003012A | SNJ54BCT125W | 5962-9093701MDA | UT54ACS132EUVCG | 5962G9654203VXC |
| 54LS122 (GEN) | 7600301CA | SNJ54HC125FK | 5962-87721012A | UT54ACS132EUVCH | 5962H9654202VXC |
| 54LS122 (GEN) | 7600301DA | SNJ54HC125J | 5962-8772101CA | UT54ACS132E-V-DIE | 5962G9654203V9B |
| CD54HC123F3A | 5962-8684701EA | 54AC125 (GEN) | 5962-9325301S2A | UT54ACS132E-V-DIE | 5962H9654202V9B |
| CD54HCT123F3A | 5962-8970001EA | CD54HCT126F3A | 5962-9065101MCA | UT54ACS132-Q-DIE | 5962G9654201Q9B |
| MM54HC123AE/883 | 5962-86847022A | SNJ54AHC126FK | 5962-9686201Q2A | UT54ACS132UQAG | 5962G9654201QXA |
| MM54HC123AJ/883 | 5962-8684702EA | SNJ54AHC126J | 5962-9686201QCA | UT54ACS132UQCG | 5962G9654201QXC |
| SNJ54AHC123AFK | 5962-9860801Q2A | SNJ54AHC126W | 5962-9686201QDA | UT54ACS132UVAG | 5962G9654201VXA |
| SNJ54AHC123AJ | 5962-9860801QEA | SNJ54AHCT126J | 5962-9686301QCA | UT54ACS132UVCG | 5962G9654201VXC |
| SNJ54AHC123AW | 5962-9860801QFA | SNJ54AHCT126W | 5962-9686301Q2A | UT54ACS132-V-DIE | 5962G9654201V9B |
| SNJ54AHCT123AFK | 5962-9861601Q2A | SNJ54AHCT126W | 5962-9686301QDA | UT54ACTS132PQAH | 5962H9654301QCA |
| SNJ54AHCT123AJ | 5962-9861601QEA | SNJ54BCT126FK | 5962-9088901M2A | UT54ACTS132PQCH | 5962H9654301QCC |
| SNJ54AHCT123AW | 5962-9861601QFA | SNJ54BCT126J | 5962-9088901MCA | UT54ACTS132PVAH | 5962H9654301VCA |
| SNJ54LS123J | 7603901EA | SNJ54BCT126W | 5962-9088901MDA | UT54ACTS132PVCH | 5962H9654301VCC |
| SNJ54LS123W | 7603901FA | SNJ54HC126FK | 5962-86848012A | UT54ACTS132UQAH | 5962H9654301QXA |
| SNV54LS123J | 5962-7603901VEA | SNJ54HC126J | 5962-8684801CA | UT54ACTS132UQCH | 5962H9654301QXC |
| SNV54LS123W | 5962-7603901VFA | SNJ54128FK | 5962-9861101Q2A | UT54ACTS132UVAH | 5962H9654301VXA |
| 54LS124 (GEN) | 7704101EA | SNJ54128J | 5962-9861101QCA | UT54ACTS132UVCH | 5962H9654301VXC |
| 54LS124 (GEN) | 7704101FA | SNJ54128W | 5962-9861101QDA | 54HC133/B2A | 5962-87723012A |
| SNJ54ALS1244AFK | 5962-88738012A | 54F13 (GEN) | 5962-9455901Q2A | 54HC133/BEA | 5962-8772301EA |
| SNJ54ALS1244AJ | 5962-8873801RA | 54F13 (GEN) | 5962-9455901QCA | SNJ54ALS133W | 5962-8859001FA |
| SNJ54ALS1245AFK | 5962-88737012A | 54F13 (GEN) | 5962-9455901QDA | SNJ54LS136FK | 5962-9231901M2A |
| SNJ54ALS1245AJ | 5962-8873701RA | 54ACS132 (GEN) | 5962H9654201Q9A | SNJ54LS136J | 5962-9231901MCA |
| 54AC125 (GEN) | 5962-9325301SCA | 54ACS132 (GEN) | 5962H9654201Q9B | SNJ54LS136W | 5962-9231901MDA |
| 54AC125 (GEN) | 5962-9325301SDA | 54ACS132 (GEN) | 5962H9654201QCA | 54HCT137 (GEN) | 5962-9173201M2A |
| 54AC125K01Q | 5962-9325302QXC | 54ACS132 (GEN) | 5962H9654201QXA | 54HCT137 (GEN) | 5962-9173201MEA |
| 54AC125K01V | 5962-9325302VXC | 54ACS132 (GEN) | 5962H9654201V9A | SNJ54ALS137AFK | 5962-9066501M2A |
| 54AC125K02Q | 5962-9325302QXA | 54ACS132 (GEN) | 5962H9654201V9B | SNJ54ALS137AJ | 5962-9066501MEA |
| 54AC125K02V | 5962-9325302VXA | 54ACS132 (GEN) | 5962H9654201VCA | SNJ54ALS137AW | 5962-9066501MFA |
| 54F125 (GEN) | 5962-9078101M2A | 54ACS132 (GEN) | 5962H9654201VXA | 54AC138DMQB | 5962-8762201EA |
| 54F125 (GEN) | 5962-9078101MDA | 54F132 (GEN) | 5962-8948701DA | 54AC138FMQB | 5962-8762201FA |
| 54F125/MCA | 5962-9078101MCA | 54F132DMQB | 5962-8948701CA | 54AC138K01Q | 5962-8762201XC |
| 54HC125 (GEN) | 5962-8772101DA | 54F132LMQB | 5962-89487012A | 54AC138K01V | 5962-8762201VXC |
| JM54AC125B2A | 5962-9325301B2A | 54HC132K01Q | 5962-8984502XC | 54AC138K02Q | 5962-8762201XA |
| JM54AC125B2A-RH | 5962R9325301B2A | 54HC132K01V | 5962-8984502VXC | 54AC138K02V | 5962-8762201VXA |
| JM54AC125BCA | 5962-9325301BCA | 54HC132K02Q | 5962-8984502XA | 54AC138LMQB | 5962-87622012A |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

| Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN |
|---|---|---|---|---|---|
| 54ACT138 (GEN) | 5962-87554012A | SNJ54AHC138FK | 5962-9851601Q2A | 54C138 (GEN) | 5962R9582501QEC |
| 54ACT138 (GEN) | 5962-8755401B2A | SNJ54AHC138J | 5962-9851601QEA | HS-54C138 (GEN) | 5962R9582501QXC |
| 54ACT138 (GEN) | 5962-8755401BFA | SNJ54AHC138W | 5962-9851601QFA | 54AC139DMQB | 5962-8762301EA |
| 54ACT138 (GEN) | 5962-8755401EA | SNJ54AHCT138FK | 5962-9851701Q2A | 54AC139FMQB | 5962-8762301FA |
| 54ACT138 (GEN) | 5962-8755401FA | SNJ54AHCT138J | 5962-9851701QEA | 54AC139K01Q | 5962-8762301XC |
| 54ACT138 (GEN) | 5962-8755401S2A | SNJ54AHCT138W | 5962-9851701QFA | 54AC139K01V | 5962-8762301VXC |
| 54ACT138 (GEN) | 5962-8755401SEA | SNJ54ALS138AFK | 5962-86866012A | 54AC139K02Q | 5962-8762301XA |
| 54ACT138 (GEN) | 5962-8755401SFA | SNJ54ALS138AW | 5962-8686601FA | 54AC139K02V | 5962-8762301VXA |
| 54ACT138DMQB | 5962-8755401MEA | SNJ54F138FK | 5962-9758201Q2A | 54AC139LMQB | 5962-87623012A |
| 54ACT138FMQB | 5962-8755401MFA | SNJ54F138J | 5962-9758201QEA | 54ACT139DMQB | 5962-8755301EA |
| 54ACT138LMQB | 5962-8755401M2A | SNJ54F138W | 5962-9758201QFA | 54ACT139FMQB | 5962-8755301FA |
| 54F138DMQB | 5962-9758201QEA | SNJ54HC138FK | 84062012A | 54ACT139LMQB | 5962-87553012A |
| 54F138FMQB | 5962-9758201QFA | SNJ54HC138J | 8406201EA | 54FCT139 (GEN) | 5962-89508012A |
| 54F138LMQB | 5962-9758201Q2A | SNJ54HC138W | 8406201FA | 54FCT139 (GEN) | 5962-8950801EA |
| 54FCT138A (GEN) | 5962-87654022A | SNJ54HCT138FK | 85504012A | 54FCT139 (GEN) | 5962-8950801FA |
| 54FCT138A (GEN) | 5962-8765402EA | SNJ54HCT138J | 8550401EA | 54FCT139A (GEN) | 5962-89508022A |
| 54FCT138A (GEN) | 5962-8765402FA | SNJ54HCT138W | 8550401FA | 54FCT139A (GEN) | 5962-8950802EA |
| 54FCT138AT (GEN) | 5962-9223303M2A | SNJ54LS138FK | 76005012A | 54FCT139A (GEN) | 5962-8950802FA |
| 54FCT138AT (GEN) | 5962-9223303MEA | SNJ54LS138W | 7600501FA | 54FCT139AT (GEN) | 5962-9220203M2A |
| 54FCT138AT (GEN) | 5962-9223304MFA | SNJ54LVC138AFK | 5962-9752601Q2A | 54FCT139AT (GEN) | 5962-9220203MEA |
| 54FCT138CT (GEN) | 5962-9223305M2A | SNJ54LVC138AJ | 5962-9752601QEA | 54FCT139AT (GEN) | 5962-9220204MFA |
| 54FCT138CT (GEN) | 5962-9223305MEA | SNJ54LVC138AW | 5962-9752601QFA | 54FCT139CT (GEN) | 5962-9220205M2A |
| 54FCT138CT (GEN) | 5962-9223306MFA | SNJ54S138FK | 76041012A | 54FCT139CT (GEN) | 5962-9220205MEA |
| 54FCT138DMQB | 5962-8765401EA | SNJ54S138J | 7604101EA | 54FCT139CT (GEN) | 5962-9220206MFA |
| 54FCT138FMQB | 5962-8765401FA | SNJ54S138W | 7604101FA | 54FCT139T (GEN) | 5962-9220201M2A |
| 54FCT138LMQB | 5962-87654012A | SNV54HC138J | 5962-8406201VEA | 54FCT139T (GEN) | 5962-9220201MEA |
| 54FCT138T (GEN) | 5962-9223301M2A | SNV54HC138W | 5962-8406201VFA | 54FCT139T (GEN) | 5962-9220202MFA |
| 54FCT138T (GEN) | 5962-9223301MEA | UT54ACS138PQAH | 5962H9654401QEA | 54HC139K01Q | 8409201XC |
| 54FCT138T (GEN) | 5962-9223302MFA | UT54ACS138PQCH | 5962H9654401QEC | 54HC139K01V | 5962-8409201VXC |
| 54HC138K01Q | 8406201XC | UT54ACS138PVAH | 5962H9654401VEA | 54HC139K02Q | 8409201XA |
| 54HC138K01V | 5962-8406201VXC | UT54ACS138PVCH | 5962H9654401VEC | 54HC139K02V | 5962-8409201VXA |
| 54HC138K02Q | 8406201XA | UT54ACS138UQAH | 5962H9654401QXA | CD54HC139F3A | 8409201EA |
| 54HC138K02V | 5962-8406201VXA | UT54ACS138UQCH | 5962H9654401QXC | IDT54FCT139ATDB | 5962-9220204MEA |
| CD54HC138F3A | 8406201EA | UT54ACS138UVAH | 5962H9654401VXA | IDT54FCT139ATLB | 5962-9220204M2A |
| CY54FCT138CTDMB | 5962-9223306MEA | UT54ACS138UVCH | 5962H9654401VXC | IDT54FCT139CTDB | 5962-9220206MEA |
| CY54FCT138CTLMB | 5962-9223306M2A | UT54ACTS138PQAH | 5962H9654501QEA | IDT54FCT139CTLB | 5962-9220206M2A |
| CY54FCT138TDMB | 5962-9223302MEA | UT54ACTS138PQCH | 5962H9654501QEC | IDT54FCT139TDB | 5962-9220202MEA |
| CY54FCT138TLMB | 5962-9223302M2A | UT54ACTS138PVAH | 5962H9654501VEA | IDT54FCT139TLB | 5962-9220202M2A |
| HS-54C138 (GEN) | 5962R9582501V9A | UT54ACTS138PVCH | 5962H9654501VEC | SL54LS139/BEA | 7600701EA |
| HS-54C138 (GEN) | 5962R9582501VEC | UT54ACTS138UQAH | 5962H9654501QXA | SL54LS139/BFA | 7600701FA |
| HS-54C138 (GEN) | 5962R9582501VXC | UT54ACTS138UQCH | 5962H9654501QXC | SNJ54ALS139FK | 5962-87683012A |
| IDT54FCT138ATDB | 5962-9223304MEA | UT54ACTS138UVAH | 5962H9654501VXA | SNJ54ALS139J | 5962-8768301EA |
| IDT54FCT138ATLB | 5962-9223304M2A | UT54ACTS138UVCH | 5962H9654501VXC | SNJ54ALS139W | 5962-8768301FA |
| IDT54FCT138CTDB | 5962-9223306MEA | 54ACT138K01Q | 5962-8755403QXC | SNJ54HC139FK | 84092012A |
| IDT54FCT138CTLB | 5962-9223306M2A | 54ACT138K01V | 5962-8755403VXC | SNJ54HC139J | 8409201EA |
| IDT54FCT138TDB | 5962-9223302MEA | 54ACT138K02Q | 5962-8755403QXA | SNJ54HC139W | 8409201FA |
| IDT54FCT138TLB | 5962-9223302M2A | 54ACT138K02V | 5962-8755403VXA | SNJ54LS139AFK | 76007012A |
| JM54ACT138BEA | 5962-8755401BEA | JM54ACT138B2A-R | 5962R8755401B2A | SNJ54LS139AJ | 7600701EA |
| SL54LS138/B2A | 76005012A | JM54ACT138BEA-R | 5962R8755401BEA | SNJ54LS139AW | 7600701FA |
| SL54LS138/B2C | 76005012C | JM54ACT138BFA-R | 5962R8755401BFA | SNJ54S139J | 7700401EA |
| SL54LS138/BEA | 7600501EA | JM54ACT138S2A-R | 5962R8755401S2A | SNJ54S139W | 7700401FA |
| SL54LS138/BFA | 7600501FA | JM54ACT138SEA-R | 5962R8755401SEA | UT54ACS139PQAH | 5962H9654601QEA |
| SN54LS138J | 7600501EA | JM54ACT138SFA-R | 5962R8755401SFA | UT54ACS139PQCH | 5962H9654601QEC |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART II, Listed By Generic PIN

| Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN |
|---|---|---|---|---|---|
| UT54ACS139PVAH | 5962H9654601VEA | SNJ54AHC14FK | 5962-9680201Q2A | UT54ACTS14UVCH | 5962H9652501VXC |
| UT54ACS139PVCH | 5962H9654601VEC | SNJ54AHC14J | 5962-9680201QCA | SNJ54LS145FK | 85084012A |
| UT54ACS139UQAH | 5962H9654601QXA | SNJ54AHC14W | 5962-9680201QDA | SNJ54LS145J | 8508401EA |
| UT54ACS139UQCH | 5962H9654601QXC | SNJ54AHCT14FK | 5962-9680101Q2A | SNJ54LS145W | 8508401FA |
| UT54ACS139UVAH | 5962H9654601VXA | SNJ54AHCT14J | 5962-9680101QCA | 54HC147 (GEN) | 84064012A |
| UT54ACS139UVCH | 5962H9654601VXC | SNJ54AHCT14W | 5962-9680101QDA | 54HC147 (GEN) | 8406401FA |
| UT54ACTS139PQAH | 5962H9654701QEA | SNJ54HC14FK | 84091012A | 54LS147/B2A | 5962-9158601Q2A |
| UT54ACTS139PQCH | 5962H9654701QEC | SNJ54HC14J | 8409101CA | 54LS147/BEA | 5962-9158601QEA |
| UT54ACTS139PVAH | 5962H9654701VEA | SNJ54HC14W | 8409101DA | 54LS147/BFA | 5962-9158601QFA |
| UT54ACTS139PVCH | 5962H9654701VEC | SNJ54HCT14FK | 5962-86890012A | CD54HC147F3A | 8406401EA |
| UT54ACTS139UQAH | 5962H9654701QXA | SNJ54HCT14J | 5962-8689001CA | 54F148 (GEN) | 5962-86070012A |
| UT54ACTS139UQCH | 5962H9654701QXC | SNJ54HCT14W | 5962-8689001DA | 54F148 (GEN) | 5962-8607001FA |
| UT54ACTS139UVAH | 5962H9654701VXA | SNJ54LS14FK | 5962-9665801Q2A | 54F148/BEA | 5962-8607001EA |
| UT54ACTS139UVCH | 5962H9654701VXC | SNJ54LS14J | 5962-9665801QCA | SNJ54LS148FK | 78027012A |
| 54AC14DMQB | 5962-8762401CA | SNJ54LS14W | 5962-9665801QDA | SNJ54LS148J | 7802701EA |
| 54AC14FMQB | 5962-8762401DA | SNJ54LVC14AFK | 5962-9761501Q2A | SNJ54LS148W | 7802701FA |
| 54AC14K01Q | 5962-8762401VXC | SNJ54LVC14AJ | 5962-9761501QCA | 54S15 (GEN) | 5962-9751601Q2A |
| 54AC14K01Q | 5962-8762401XC | SNJ54LVC14AW | 5962-9761501QDA | 54S15 (GEN) | 5962-9751601QCA |
| 54AC14K02Q | 5962-8762401VXA | SNV54AC14J | 5962-8762401VCA | 54S15 (GEN) | 5962-9751601QDA |
| 54AC14K02Q | 5962-8762401XA | SNV54AC14W | 5962-8762401VDA | SNJ54150J | 5962-9558001QJA |
| 54AC14LMQB | 5962-87624012A | SNV54AHCT14J | 5962-9680101VCA | SNJ54150W | 5962-9558001QKA |
| 54ACS14 (GEN) | 5962H9652401Q9A | SNV54AHCT14W | 5962-9680101VDA | 54AC151DMQB | 5962-8769101EA |
| 54ACS14 (GEN) | 5962H9652401Q9B | SNV54HC14J | 5962-8409101VCA | 54AC151FMQB | 5962-8769101FA |
| 54ACS14 (GEN) | 5962H9652401QCA | SNV54HC14W | 5962-8409101VDA | 54AC151LMQB | 5962-87691012A |
| 54ACS14 (GEN) | 5962H9652401QXA | SNV54LS14J | 5962-9665801VCA | 54ACT151 (GEN) | 5962-88756012A |
| 54ACS14 (GEN) | 5962H9652401QXC | SNV54LS14W | 5962-9665801VDA | 54ACT151 (GEN) | 5962-8875601B2A |
| 54ACS14 (GEN) | 5962H9652401V9A | SNV54LVC14AJ | 5962-9761501VCA | 54ACT151 (GEN) | 5962-8875601BEA |
| 54ACS14 (GEN) | 5962H9652401V9B | SNV54LVC14AW | 5962-9761501VDA | 54ACT151 (GEN) | 5962-8875601BFA |
| 54ACS14 (GEN) | 5962H9652401VCA | UT54ACS14E-Q-DIE | 5962G9652403Q9B | 54ACT151 (GEN) | 5962-8875601EA |
| 54ACS14 (GEN) | 5962H9652401VXA | UT54ACS14E-Q-DIE | 5962H9652402Q9B | 54ACT151 (GEN) | 5962-8875601FA |
| 54ACS14 (GEN) | 5962H9652401VXC | UT54ACS14EUQAG | 5962G9652403QXA | 54ACT151 (GEN) | 5962-8875601S2A |
| 54ACTQ14DMQB | 5962-9218301MCA | UT54ACS14EUQAH | 5962H9652402QXA | 54ACT151 (GEN) | 5962-8875601SEA |
| 54ACTQ14FMQB | 5962-9218301MDA | UT54ACS14EUQCG | 5962G9652403QXC | 54ACT151 (GEN) | 5962-8875601SFA |
| 54ACTQ14LMQB | 5962-9218301M2A | UT54ACS14EUQCH | 5962H9652402QXC | 54ACT151DMQB | 5962-8875601MEA |
| 54F14DMQB | 5962-8875201CA | UT54ACS14EUVAG | 5962G9652403VXA | 54ACT151FMQB | 5962-8875601MFA |
| 54F14FMQB | 5962-8875201DA | UT54ACS14EUVAH | 5962H9652402VXA | 54ACT151LMQB | 5962-8875601M2A |
| 54F14LMQB | 5962-88752012A | UT54ACS14EUVCG | 5962G9652403VXC | 54FCT151AT (GEN) | 5962-9220603M2A |
| 54HC14 (GEN) | 8409101BA | UT54ACS14EUVCH | 5962H9652402VXC | 54FCT151AT (GEN) | 5962-9220603MEA |
| 54HC14K01Q | 8409101XC | UT54ACS14E-V-DIE | 5962G9652403V9B | 54FCT151AT (GEN) | 5962-9220603MFA |
| 54HC14K01V | 5962-8409101VXC | UT54ACS14E-V-DIE | 5962H9652402V9B | 54FCT151AT (GEN) | 5962-9220604M2A |
| 54HC14K02Q | 8409101XA | UT54ACS14-Q-DIE | 5962G9652401Q9B | 54FCT151AT (GEN) | 5962-9220604MEA |
| 54HC14K02V | 5962-8409101VXA | UT54ACS14UQAG | 5962G9652401QXA | 54FCT151AT (GEN) | 5962-9220604MFA |
| CD54HC14F3A | 8409101CA | UT54ACS14UQCG | 5962G9652401QXC | 54FCT151CT (GEN) | 5962-9220605M2A |
| SL54LS14/B2A | 5962-9665801Q2A | UT54ACS14UVAG | 5962G9652401VXA | 54FCT151CT (GEN) | 5962-9220605MEA |
| SL54LS14/B2C | 5962-9665801Q2C | UT54ACS14UVCG | 5962G9652401VXC | 54FCT151CT (GEN) | 5962-9220605MFA |
| SL54LS14/BCA | 5962-9665801QCA | UT54ACS14-V-DIE | 5962G9652401V9B | 54FCT151CT (GEN) | 5962-9220606M2A |
| SL54LS14/BDA | 5962-9665801QDA | UT54ACTS14PQAH | 5962H9652501QCA | 54FCT151CT (GEN) | 5962-9220606MEA |
| SNJ54AC14FK | 5962-87624012A | UT54ACTS14PQCH | 5962H9652501QCC | 54FCT151CT (GEN) | 5962-9220606MFA |
| SNJ54AC14J | 5962-8762401CA | UT54ACTS14PVAH | 5962H9652501VCA | 54FCT151T (GEN) | 5962-9220601M2A |
| SNJ54AC14W | 5962-8762401DA | UT54ACTS14PVCH | 5962H9652501VCC | 54FCT151T (GEN) | 5962-9220601MEA |
| SNJ54ACT14FK | 5962-9218301M2A | UT54ACTS14UQAH | 5962H9652501QXA | 54FCT151T (GEN) | 5962-9220601MFA |
| SNJ54ACT14J | 5962-9218301MCA | UT54ACTS14UQCH | 5962H9652501QXC | 54FCT151T (GEN) | 5962-9220602M2A |
| SNJ54ACT14W | 5962-9218301MDA | UT54ACTS14UVAH | 5962H9652501VXA | 54FCT151T (GEN) | 5962-9220602MEA |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

| Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN |
|---|---|---|---|---|---|
| 54FCT151T (GEN) | 5962-9220602MFA | SNJ54F153W | 5962-9758301QFA | SNJ54LS155AW | 5962-9750801QFA |
| CD54HC151F3A | 8412801EA | SNJ54HC153FK | 84093012A | 54AC157DMQB | 5962-8953901EA |
| CD54HCT151F3A | 5962-9065201MEA | SNJ54HC153J | 8409301EA | 54AC157FMQB | 5962-8953901FA |
| JM54ACT151B2A-R | 5962R8875601B2A | SNJ54HC153W | 8409301FA | 54AC157K01Q | 5962-8953901XC |
| JM54ACT151BEA-R | 5962R8875601BEA | SNJ54LS153FK | 76011012A | 54AC157K01V | 5962-8953901VXC |
| JM54ACT151BFA-R | 5962R8875601BFA | SNJ54LS153J | 7601101EA | 54AC157K02Q | 5962-8953901XA |
| JM54ACT151S2A-R | 5962R8875601S2A | SNJ54LS153W | 7601101FA | 54AC157K02V | 5962-8953901VXA |
| JM54ACT151SEA-R | 5962R8875601SEA | UT54ACS153PQAH | 5962H9655001QEA | 54AC157LMQB | 5962-89539012A |
| JM54ACT151SFA-R | 5962R8875601SFA | UT54ACS153PQCH | 5962H9655001QEC | 54ACT157DMQB | 5962-8968801EA |
| SNJ54ALS151FK | 84141012A | UT54ACS153PVAH | 5962H9655001VEA | 54ACT157DMQB-RH | 5962R8968801EA |
| SNJ54ALS151J | 8414101EA | UT54ACS153PVCH | 5962H9655001VEC | 54ACT157ERQMLV | 5962R8968801V2A |
| SNJ54ALS151W | 8414101FA | UT54ACS153UQAH | 5962H9655001QXA | 54ACT157FMQB | 5962-8968801FA |
| SNJ54HC151FK | 84128012A | UT54ACS153UQCH | 5962H9655001QXC | 54ACT157FMQB-RH | 5962R8968801FA |
| SNJ54HC151J | 8412801EA | UT54ACS153UVAH | 5962H9655001VXA | 54ACT157JRQMLV | 5962R8968801VEA |
| SNJ54LS151FK | 76010012A | UT54ACS153UVCH | 5962H9655001VXC | 54ACT157K01Q | 5962-8968802XC |
| SNJ54LS151J | 7601001EA | UT54ACTS153EUQAG | 5962G9655103QXA | 54ACT157K01V | 5962-8968802VXC |
| SNJ54LS151W | 7601001FA | UT54ACTS153EUQAH | 5962H9655102QXA | 54ACT157K02Q | 5962-8968802XA |
| UT54ACS151PQAH | 5962H9654801QEA | UT54ACTS153EUQCG | 5962G9655103QXC | 54ACT157K02V | 5962-8968802VXA |
| UT54ACS151PQCH | 5962H9654801QEC | UT54ACTS153EUQCH | 5962H9655102QXC | 54ACT157LMQB | 5962-89688012A |
| UT54ACS151PVAH | 5962H9654801VEA | UT54ACTS153EUVAG | 5962G9655103VXA | 54ACT157LMQB-RH | 5962R89688012A |
| UT54ACS151PVCH | 5962H9654801VEC | UT54ACTS153EUVAH | 5962H9655102VXA | 54ACT157WGRQMLV | 5962R8968801VZA |
| UT54ACS151UQAH | 5962H9654801QXA | UT54ACTS153EUVCG | 5962G9655103VXC | 54ACT157WRQMLV | 5962R8968801VFA |
| UT54ACS151UQCH | 5962H9654801QXC | UT54ACTS153EUVCH | 5962H9655102VXC | 54FCT157AT (GEN) | 5962-9220803MEA |
| UT54ACS151UVAH | 5962H9654801VXA | UT54ACTS153PQAH | 5962H9655101QEA | 54FCT157AT (GEN) | 5962-9220803MFA |
| UT54ACS151UVCH | 5962H9654801VXC | UT54ACTS153PQCH | 5962H9655101QEC | 54FCT157AT (GEN) | 5962-9220804M2A |
| UT54ACTS151PQAH | 5962H9654901QEA | UT54ACTS153PVAH | 5962H9655101VEA | 54FCT157AT (GEN) | 5962-9220804MEA |
| UT54ACTS151PQCH | 5962H9654901QEC | UT54ACTS153PVCH | 5962H9655101VEC | 54FCT157CT (GEN) | 5962-9220805M2A |
| UT54ACTS151PVAH | 5962H9654901VEA | UT54ACTS153UQAH | 5962H9655101QXA | 54FCT157CT (GEN) | 5962-9220805MEA |
| UT54ACTS151PVCH | 5962H9654901VEC | UT54ACTS153UQCH | 5962H9655101QXC | 54FCT157CT (GEN) | 5962-9220805MFA |
| UT54ACTS151UQAH | 5962H9654901QXA | UT54ACTS153UVAH | 5962H9655101VXA | 54FCT157CT (GEN) | 5962-9220806M2A |
| UT54ACTS151UQCH | 5962H9654901QXC | UT54ACTS153UVCH | 5962H9655101VXC | 54FCT157CT (GEN) | 5962-9220806MEA |
| UT54ACTS151UVAH | 5962H9654901VXA | 54F154 (GEN) | 5962-9455401M3A | 54FCT157T (GEN) | 5962-9220802M2A |
| UT54ACTS151UVCH | 5962H9654901VXC | 54F154 (GEN) | 5962-9455401MKA | 54FCT157T (GEN) | 5962-9220802MEA |
| 54AC153DMQB | 5962-8762501EA | 54F154 (GEN) | 5962-9455401MLA | 54FCT157T/M2A | 5962-9220801M2A |
| 54AC153FMQB | 5962-8762501FA | 54HC154 (GEN) | 5962-86822013A | 54FCT157T/MEA | 5962-9220801MEA |
| 54AC153LMQB | 5962-87625012A | 54HC154 (GEN) | 5962-8682201LA | 54FCT157T/MFA | 5962-9220801MFA |
| 54ACT153DMQB | 5962-8769801EA | 54HCT154 (GEN) | 5962-86701013A | 54HC157K01Q | 5962-8606101XC |
| 54ACT153FMQB | 5962-8769801FA | 54HCT154 (GEN) | 5962-8670101KA | 54HC157K01V | 5962-8606101VXC |
| 54ACT153LMQB | 5962-87698012A | 54HCT154 (GEN) | 5962-8670101LA | 54HC157K02Q | 5962-8606101XA |
| 54F153DMQB | 5962-9758301QEA | CD54HC154F3A | 5962-8682201JA | 54HC157K02V | 5962-8606101VXA |
| 54F153FMQB | 5962-9758301QFA | CD54HCT154F3A | 5962-8670101JA | CD54HC157F3A | 5962-8606101EA |
| 54F153LMQB | 5962-9758301Q2A | SL54154/BJA | 5962-9558101QJA | CD54HCT157F3A | 5962-9070201MEA |
| CD54HC153F3A | 8409301EA | SL54154/BKA | 5962-9558101QKA | CY54FCT157ATLMB | 5962-9220803M2A |
| CD54HCT153F3A | 5962-9050501MEA | SL54LS154/B2C | 83017013C | SL54LS157/B2A | 76002012A |
| SL54LS153/B2A | 76011012A | SL54LS154/B3A | 83017013A | SL54LS157/B2C | 76002012C |
| SL54LS153/B2C | 76011012C | SL54LS154/BJA | 8301701JA | SL54LS157/BEA | 7600201EA |
| SL54LS153/BEA | 7601101EA | SL54LS154/BKA | 8301701KA | SL54LS157/BFA | 7600201FA |
| SL54LS153/BFA | 7601101FA | SNJ54154J | 5962-9558101QJA | SNJ54AHC157FK | 5962-9764201Q2A |
| SNJ54ALS153FK | 84134012A | SNJ54154W | 5962-9558101QKA | SNJ54AHC157J | 5962-9764201QEA |
| SNJ54ALS153J | 8413401EA | SL54155/BEA | 5962-9558201QEA | SNJ54AHC157W | 5962-9764201QFA |
| SNJ54ALS153W | 8413401FA | SL54155/BFA | 5962-9558201QFA | SNJ54ALS157AFK | 5962-86869012A |
| SNJ54F153FK | 5962-9758301Q2A | SNJ54LS155AFK | 5962-9750801Q2A | SNJ54ALS157AJ | 5962-8686901EA |
| SNJ54F153J | 5962-9758301QEA | SNJ54LS155AJ | 5962-9750801QEA | SNJ54ALS157AW | 5962-8686901FA |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

| Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN |
|---|---|---|---|---|---|
| SNJ54HC157FK | 5962-86061012A | SL54LS158/BFA | 7603301FA | 54FCT161AT (GEN) | 5962-9220904MFA |
| SNJ54HC157J | 5962-8606101EA | SNJ54ALS158FK | 5962-88625012A | 54FCT161CT (GEN) | 5962-9220905M2A |
| SNJ54LS157FK | 76002012A | SNJ54ALS158J | 5962-8862501EA | 54FCT161CT (GEN) | 5962-9220905MEA |
| SNJ54LS157J | 7600201EA | SNJ54ALS158W | 5962-8862501FA | 54FCT161CT (GEN) | 5962-9220906M2A |
| SNJ54LS157W | 7600201FA | SNJ54LS158FK | 76033012A | 54FCT161CT (GEN) | 5962-9220906MEA |
| SNJ54LVC157AFK | 5962-0050601Q2A | SNJ54LS158J | 7603301EA | 54FCT161CT (GEN) | 5962-9220906MFA |
| SNJ54LVC157AJ | 5962-0050601QEA | SNJ54LS158W | 7603301FA | 54FCT161T (GEN) | 5962-9220901M2A |
| SNJ54LVC157AW | 5962-0050601QFA | A54SX16 (GEN) | 5962-9956903Q9B | 54FCT161T (GEN) | 5962-9220901MEA |
| UT54ACS157PQAH | 5962H9655201QEA | A54SX16-CQ208B | 5962-9956903QYC | 54FCT161T (GEN) | 5962-9220902M2A |
| UT54ACS157PQCH | 5962H9655201QEC | A54SX16-CQ256B | 5962-9956903QXC | 54FCT161T (GEN) | 5962-9220902MEA |
| UT54ACS157PVAH | 5962H9655201VEA | RT54SX16 (GEN) | 5962-9956901Q9A | 54FCT161T (GEN) | 5962-9220902MFA |
| UT54ACS157PVCH | 5962H9655201VEC | RT54SX16-CQ208B | 5962-9956901QYC | 54HC161K01Q | 8407501XC |
| UT54ACS157UQAH | 5962H9655201QXA | RT54SX16-CQ256B | 5962-9956901QXC | 54HC161K01V | 5962-8407501VXC |
| UT54ACS157UQCH | 5962H9655201QXC | 54HC160 (GEN) | 5962-86824012A | 54HC161K02Q | 8407501XA |
| UT54ACS157UVAH | 5962H9655201VXA | 54HC160 (GEN) | 5962-8682401EA | 54HC161K02V | 5962-8407501VXA |
| UT54ACS157UVCH | 5962H9655201VXC | 54HC160 (GEN) | 5962-8682401FA | 54HCT161 (GEN) | 5962-8685401EA |
| UT54ACTS157PQAH | 5962H9655301QEA | CD54HCT160F3A | 5962-9070501MEA | A54SX16-1CQ208B | 5962-9956904QYC |
| UT54ACTS157PQCH | 5962H9655301QEC | SL54LS160A/BEA | 7700901EA | A54SX16-1CQ256B | 5962-9956904QXC |
| UT54ACTS157PVAH | 5962H9655301VEA | SL54LS160A/BFA | 7700901FA | CD54HC161F3A | 8407501EA |
| UT54ACTS157PVCH | 5962H9655301VEC | 54AC161DMQB | 5962-8956101EA | RT54SX16-1CQ208B | 5962-9956902QYC |
| UT54ACTS157UQAH | 5962H9655301QXA | 54AC161FMQB | 5962-8956101FA | RT54SX16-1CQ256B | 5962-9956902QXC |
| UT54ACTS157UQCH | 5962H9655301QXC | 54AC161K01Q | 5962-8956101XC | SL54LS161/B2A | 76008012A |
| UT54ACTS157UVAH | 5962H9655301VXA | 54AC161K01V | 5962-8956101VXC | SL54LS161/B2C | 76008012C |
| UT54ACTS157UVCH | 5962H9655301VXC | 54AC161K02Q | 5962-8956101XA | SL54LS161/BEA | 7600801EA |
| 54AC158 (GEN) | 5962-8972901V2A | 54AC161K02V | 5962-8956101VXA | SL54LS161/BFA | 7600801FA |
| 54AC158 (GEN) | 5962R8972901Q2A | 54AC161LMQB | 5962-89561012A | SNJ54ALS161BFK | 83022012A |
| 54AC158 (GEN) | 5962R8972901QEA | 54ACT161DMQB | 5962-9172201MEA | SNJ54ALS161BJ | 8302201EA |
| 54AC158 (GEN) | 5962R8972901QFA | 54ACT161DMQB-RH | 5962R9172201MEA | SNJ54ALS161BW | 8302201FA |
| 54AC158DMQB | 5962-8972901EA | 54ACT161ERQMLV | 5962R9172201V2A | SNJ54HC161FK | 84075012A |
| 54AC158ERQMLV | 5962R8972901V2A | 54ACT161FMQB | 5962-9172201MFA | SNJ54HC161J | 8407501EA |
| 54AC158FMQB | 5962-8972901FA | 54ACT161FMQB-RH | 5962R9172201MFA | SNJ54HC161W | 8407501FA |
| 54AC158J-QMLV | 5962-8972901VEA | 54ACT161JRQMLV | 5962R9172201VEA | SNJ54LS161AFK | 76008012A |
| 54AC158JRQMLV | 5962R8972901VEA | 54ACT161K01Q | 5962-9172202QXC | SNJ54LS161AJ | 7600801EA |
| 54AC158K01Q | 5962-8972901XC | 54ACT161K01V | 5962-9172202VXC | SNJ54LS161AW | 7600801FA |
| 54AC158K01V | 5962-8972901VXC | 54ACT161K02Q | 5962-9172202QXA | SNV54LS161AJ | 5962-7600801VEA |
| 54AC158K02Q | 5962-8972901XA | 54ACT161K02V | 5962-9172202VXA | SNV54LS161AW | 5962-7600801VFA |
| 54AC158K02V | 5962-8972901VXA | 54ACT161LMQB | 5962-9172201M2A | 54ALS162B/B2A | 84079012A |
| 54AC158LMQB | 5962-89729012A | 54ACT161LMQB-RH | 5962R9172201M2A | 54ALS162B/BEA | 8407901EA |
| 54AC158W-QMLV | 5962-8972901VFA | 54ACT161WGRQMLV | 5962R9172201VZA | 54ALS162B/BFA | 8407901FA |
| 54AC158WRQMLV | 5962R8972901VFA | 54ACT161WRQMLV | 5962R9172201VFA | 54HC162 (GEN) | 84094012A |
| 54ACT158DMQB | 5962-8875501EA | 54FCT161 (GEN) | 5962-88640012A | 54HC162 (GEN) | 8409401EA |
| 54ACT158FMQB | 5962-8875501FA | 54FCT161 (GEN) | 5962-8864001EA | 54HC162 (GEN) | 8409401FA |
| 54ACT158K01Q | 5962-8875502XC | 54FCT161 (GEN) | 5962-8864001FA | AS54ALS162C16/883C | 8407901EA |
| 54ACT158K01V | 5962-8875502VXC | 54FCT161 (GEN) | 5962-88640022A | CD54HCT162BF3A | 5962-8970701EA |
| 54ACT158K02Q | 5962-8875502XA | 54FCT161 (GEN) | 5962-8864002EA | SNJ54CBT16209WD | 5962-9669701QXA |
| 54ACT158K02V | 5962-8875502VXA | 54FCT161 (GEN) | 5962-8864002FA | SNJ54CBT16212AWD | 5962-9852101QXA |
| 54ACT158LMQB | 5962-88755012A | 54FCT161A (GEN) | 5962-88640032A | 54FCT162240 (GEN) | 5962-9227001MXA |
| 54HC158 (GEN) | 5962-86823012A | 54FCT161A (GEN) | 5962-8864003EA | 54FCT162240A (GEN) | 5962-9227002MXA |
| 54HC158 (GEN) | 5962-8682301EA | 54FCT161A (GEN) | 5962-8864003FA | 54FCT162240C (GEN) | 5962-9227003MXA |
| CD54HCT158F3A | 5962-9070301MEA | 54FCT161AT (GEN) | 5962-9220903M2A | IDT54FCT162244ATEB | 5962-9227102MXA |
| SL54LS158/B2A | 76033012A | 54FCT161AT (GEN) | 5962-9220903MEA | IDT54FCT162244CTEB | 5962-9227103MXA |
| SL54LS158/B2C | 76033012C | 54FCT161AT (GEN) | 5962-9220904M2A | IDT54FCT162244TEB | 5962-9227101MXA |
| SL54LS158/BEA | 7603301EA | 54FCT161AT (GEN) | 5962-9220904MEA | SNJ54ABT162244WD | 5962-9458701QXA |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

| Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN |
|---|---|---|---|---|---|
| SNJ54LVTH162244WD | 5962-9680901QXA | 54ABT16245W-QML | 5962-9317502QXA | 54ACT163DMQB | 5962-9172301MEA |
| SNV54LVTH162244WD | 5962-9680901VXA | 54ACT16245K01Q | 5962-9202301QYC | 54ACT163DMQB-RH | 5962R9172301MEA |
| IDT54FCT162245ATEB | 5962-9227202MXA | 54ACT16245K01V | 5962-9202301VYC | 54ACT163ERQMLV | 5962R9172301V2A |
| IDT54FCT162245CTEB | 5962-9227203MXA | 54ACT16245K02Q | 5962-9202301QYA | 54ACT163FMQB | 5962-9172301MFA |
| IDT54FCT162245TEB | 5962-9227201MXA | 54ACT16245K02V | 5962-9202301VYA | 54ACT163FMQB-RH | 5962R9172301MFA |
| SNJ54ABT162245WD | 5962-9677401QXA | 54ACTQ16245 (GEN) | 5962R9562001QXA | 54ACT163JRQMLV | 5962R9172301VEA |
| SNJ54LVTH162245WD | 5962-9678001QXA | 54ACTQ16245 (GEN) | 5962R9562001VXA | 54ACT163LMQB | 5962-9172301M2A |
| SNV54LVTH162245WD | 5962-9678001VXA | 54ACTQ16245FMQB | 5962-9562001QXA | 54ACT163LMQB-RH | 5962R9172301M2A |
| UT54ACS162245SUCA | 5962H0254301QXA | 54ACTQ16245W-QV | 5962-9562001VXA | 54ACT163WRQMLV | 5962R9172301VFA |
| UT54ACS162245SUCA | 5962H0254301VXA | IDT54FCT16245ATEB | 5962-9225802MXA | 54FCT163 (GEN) | 5962-88657012A |
| UT54ACS162245SUCC | 5962H0254301QXC | IDT54FCT16245CTEB | 5962-9225803MXA | 54FCT163 (GEN) | 5962-8865701EA |
| UT54ACS162245SUCC | 5962H0254301VXC | IDT54FCT16245TEB | 5962-9225801MXA | 54FCT163 (GEN) | 5962-8865701FA |
| RHPX162245K01Q | 5962P0250801QXC | SNJ54ABT16245WD | 5962-9317501MXA | 54FCT163 (GEN) | 5962-88657032A |
| RHPX162245K01V | 5962P0250801VXC | SNJ54ABTE16245WD | 5962-9677501QXA | 54FCT163 (GEN) | 5962-8865703EA |
| RHPX162245K02Q | 5962P0250801QXA | SNJ54ABTH16245WD | 5962-9762501QXA | 54FCT163 (GEN) | 5962-8865703FA |
| RHPX162245K02V | 5962P0250801VXA | SNJ54ACT16245WD | 5962-9202301MXA | 54FCT163A (GEN) | 5962-88657022A |
| 54FCT162373AT (GEN) | 5962-9227302MXA | SNJ54LVTH16245AWD | 5962-9668601QXA | 54FCT163A (GEN) | 5962-8865702EA |
| 54FCT162373CT (GEN) | 5962-9227303MXA | SNV54LVTH16245AWD | 5962-9668601VXA | 54FCT163A (GEN) | 5962-8865702FA |
| 54FCT162373T (GEN) | 5962-9227301MXA | RHPX16245K01Q | 5962P0250701QXC | 54FCT163A (GEN) | 5962-88657042A |
| SNJ54LVTH162373WD | 5962-9763801QXA | RHPX16245K01V | 5962P0250701VXC | 54FCT163A (GEN) | 5962-8865704EA |
| SNV54LVTH162373WD | 5962-9763801VXA | RHPX16245K02Q | 5962P0250701QXA | 54FCT163A (GEN) | 5962-8865704FA |
| 54FCT162374AT (GEN) | 5962-9227402MXA | RHPX16245K02V | 5962P0250701VXA | 54FCT163AT (GEN) | 5962-9221003M2A |
| 54FCT162374CT (GEN) | 5962-9227403MXA | 54AC16245K01Q | 5962-0421101QXC | 54FCT163AT (GEN) | 5962-9221003MEA |
| 54FCT162374T (GEN) | 5962-9227401MXA | 54AC16245K01V | 5962-0421101VXC | 54FCT163AT (GEN) | 5962-9221004MFA |
| SNJ54LVTH162374WD | 5962-9854201QXA | 54AC16245K02Q | 5962-0421101QXA | 54FCT163CT (GEN) | 5962-9221005M2A |
| SNV54LVTH162374WD | 5962-9854201VXA | 54AC16245K02V | 5962-0421101VXA | 54FCT163CT (GEN) | 5962-9221005MEA |
| 54ACTQ16240W-QML | 5962-9688001QXA | 54FCT162501A (GEN) | 5962-9227601MXA | 54FCT163CT (GEN) | 5962-9221006MFA |
| SNJ54ABT16240WD | 5962-9319901MXA | 54FCT162501C (GEN) | 5962-9227602MXA | 54FCT163T (GEN) | 5962-9221001M2A |
| SNJ54ACT16240WD | 5962-9201801MXA | IDT54FCT162511ATEB | 5962-9474401MXA | 54FCT163T (GEN) | 5962-9221001MEA |
| SNJ54ABT16241AWD | 5962-9450101QXA | IDT54FCT162511CTEB | 5962-9474402MXA | 54FCT163T (GEN) | 5962-9221002MFA |
| 54ABT16244W-QML | 5962-9317402QXA | SNJ54ABTH16260WD | 5962-9472801QXA | 54HC163K01Q | 8607601XC |
| 54ACT16244K01Q | 5962-9202201QYC | 54FCT162646 (GEN) | 5962-9227801MXA | 54HC163K01V | 5962-8607601VXC |
| 54ACT16244K01V | 5962-9202201VYC | 54FCT162646A (GEN) | 5962-9227802MXA | 54HC163K02Q | 8607601XA |
| 54ACT16244K02Q | 5962-9202201QYA | 54FCT162646C (GEN) | 5962-9227803MXA | 54HC163K02V | 5962-8607601VXA |
| 54ACT16244K02V | 5962-9202201VYA | 54FCT162823A (GEN) | 5962-9228001MXA | CD54HC163F3A | 8607601EA |
| 54ACTQ16244 (GEN) | 5962R9561901QXA | 54FCT162823B (GEN) | 5962-9228002MXA | IDT54FCT163ATDB | 5962-9221004MEA |
| 54ACTQ16244 (GEN) | 5962R9561901VXA | 54FCT162823C (GEN) | 5962-9228003MXA | IDT54FCT163ATLB | 5962-9221004M2A |
| 54ACTQ16244FMQB | 5962-9561901QXA | 54FCT162827A (GEN) | 5962-9228101MXA | IDT54FCT163CTDB | 5962-9221006MEA |
| 54ACTQ16244W-QV | 5962-9561901VXA | 54FCT162827B (GEN) | 5962-9228102MXA | IDT54FCT163CTLB | 5962-9221006M2A |
| 54LCX16244 (GEN) | 5962-9950501QXA | 54FCT162827C (GEN) | 5962-9228103MXA | IDT54FCT163TDB | 5962-9221002MEA |
| IDT54FCT16244ATEB | 5962-9225702MXA | 54FCT162841A (GEN) | 5962-9228201MXA | IDT54FCT163TLB | 5962-9221002M2A |
| IDT54FCT16244CTEB | 5962-9225703MXA | 54FCT162841B (GEN) | 5962-9228202MXA | SL54LS163A/B2A | 76034012A |
| IDT54FCT16244TEB | 5962-9225701MXA | 54FCT162841C (GEN) | 5962-9228203MXA | SL54LS163A/B2C | 76034012C |
| SNJ54ABT16244WD | 5962-9317401MXA | 54FCT162952A (GEN) | 5962-9228301MXA | SL54LS163A/BEA | 7603401EA |
| SNJ54ABTH16244WD | 5962-9762401QXA | 54FCT162952B (GEN) | 5962-9228302MXA | SL54LS163A/BFA | 7603401FA |
| SNJ54ACT16244WD | 5962-9202201MXA | 54FCT162952C (GEN) | 5962-9228303MXA | SNJ54163J | 5962-9754801QEA |
| SNJ54CBT16244WD | 5962-9855301QXA | 54AC163DMQB | 5962-8958201EA | SNJ54163W | 5962-9754801QFA |
| SNJ54LVTH16244AWD | 5962-9668501QXA | 54AC163FMQB | 5962-8958201FA | SNJ54ALS163BFK | 83022022A |
| SNV54LVTH16244AWD | 5962-9668501VXA | 54AC163K01Q | 5962-8958201XC | SNJ54ALS163BJ | 8302202EA |
| 54AC16244K01Q | 5962-0421001QXC | 54AC163K01V | 5962-8958201VXC | SNJ54ALS163BW | 8302202FA |
| 54AC16244K01V | 5962-0421001VXC | 54AC163K02Q | 5962-8958201XA | SNJ54HC163FK | 86076012A |
| 54AC16244K02Q | 5962-0421001QXA | 54AC163K02V | 5962-8958201VXA | SNJ54HC163J | 8607601EA |
| 54AC16244K02V | 5962-0421001VXA | 54AC163LMQB | 5962-89582012A | SNJ54HC163W | 8607601FA |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

| Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN |
|---|---|---|---|---|---|
| SNJ54LS163AJ | 7603401EA | 54FCT16374A (GEN) | 5962-9226002MXA | UT54ACTS164EUQAG | 5962G9655703QXA |
| SNJ54LS163AW | 7603401FA | 54FCT16374C (GEN) | 5962-9226003MXA | UT54ACTS164EUQAH | 5962H9655702QXA |
| UT54ACS163PQAH | 5962H9655401QEA | 54LCX16374 (GEN) | 5962-9953501QXA | UT54ACTS164EUQCG | 5962G9655703QXC |
| UT54ACS163PQCH | 5962H9655401QEC | RHFACT16374K01Q | 5962F9202502QYC | UT54ACTS164EUQCH | 5962H9655702QXC |
| UT54ACS163PVAH | 5962H9655401VEA | RHFACT16374K01V | 5962F9202502VYC | UT54ACTS164EUVAG | 5962G9655703VXA |
| UT54ACS163PVCH | 5962H9655401VEC | RHFACT16374K02Q | 5962F9202502QYA | UT54ACTS164EUVAH | 5962H9655702VXA |
| UT54ACS163-QDIE | 5962H9655401Q9A | RHFACT16374K02V | 5962F9202502VYA | UT54ACTS164EUVCG | 5962G9655703VXC |
| UT54ACS163UQAH | 5962H9655401QXA | SNJ54ABT16374AWD | 5962-9320101MXA | UT54ACTS164EUVCH | 5962H9655702VXC |
| UT54ACS163UQCH | 5962H9655401QXC | SNJ54ACT16374WD | 5962-9202501MXA | UT54ACTS164PQAH | 5962H9655701QCA |
| UT54ACS163UVAH | 5962H9655401VXA | SNJ54LVTH16374WD | 5962-9564701QXA | UT54ACTS164PQCH | 5962H9655701QCC |
| UT54ACS163UVCH | 5962H9655401VXC | 54AC16374K01Q | 5962-0421301QXC | UT54ACTS164PVAH | 5962H9655701VCA |
| UT54ACS163-VDIE | 5962H9655401V9A | 54AC16374K01V | 5962-0421301VXC | UT54ACTS164PVCH | 5962H9655701VCC |
| UT54ACTS163PQAH | 5962H9655501QEA | 54AC16374K02Q | 5962-0421301QXA | UT54ACTS164UQAH | 5962H9655701QXA |
| UT54ACTS163PQCH | 5962H9655501QEC | 54AC16374K02V | 5962-0421301VXA | UT54ACTS164UQCH | 5962H9655701QXC |
| UT54ACTS163PVAH | 5962H9655501VEA | 54ALS164 (GEN) | 5962-86870012A | UT54ACTS164UVAH | 5962H9655701VXA |
| UT54ACTS163PVCH | 5962H9655501VEC | 54ALS164 (GEN) | 5962-8687001DA | UT54ACTS164UVCH | 5962H9655701VXC |
| UT54ACTS163UQAH | 5962H9655501QXA | 54F164ADMQB | 5962-8607101CA | UT54ACS164245SE-QD | 5962-9858004Q9A |
| UT54ACTS163UQCH | 5962H9655501QXC | 54F164AFMQB | 5962-8607101DA | UT54ACS164245SE-QD | 5962-9858005Q9A |
| UT54ACTS163UVAH | 5962H9655501VXA | 54F164ALMQB | 5962-86071012A | UT54ACS164245SEUC | 5962-9858004QXC |
| UT54ACTS163UVCH | 5962H9655501VXC | 54HC164 (GEN) | 8416201BA | UT54ACS164245SEUC | 5962-9858005QXC |
| 54ACT163K01Q | 5962-9172302QXC | 54HC164 (GEN) | 8416201DA | UT54ACS164245SEUC | 5962R9858004VXC |
| 54ACT163K01V | 5962-9172302VXC | 54HC164K01Q | 8416201XC | UT54ACS164245SEUC | 5962R9858005VXC |
| 54ACT163K02Q | 5962-9172302QXA | 54HC164K01V | 5962-8416201VXC | UT54ACS164245SE-VD | 5962R9858004V9A |
| 54ACT163K02V | 5962-9172302VXA | 54HC164K02Q | 8416201XA | UT54ACS164245SE-VD | 5962R9858005V9A |
| 54ABT16373W-QML | 5962-9320001QXA | 54HC164K02V | 5962-8416201VXA | UT54ACS164245S-QDI | 5962-9858001Q9A |
| 54ACT16373K01Q | 5962-9202402QYC | CD54HC164F3A | 8416201CA | UT54ACS164245S-QDI | 5962-9858002Q9A |
| 54ACT16373K01V | 5962-9202402VYC | CD54HCT164F3A | 5962-8970401CA | UT54ACS164245S-QDI | 5962-9858003Q9A |
| 54ACT16373K02Q | 5962-9202402QYA | SNJ54HC164FK | 84162012A | UT54ACS164245SUCC | 5962-9858001QXC |
| 54ACT16373K02V | 5962-9202402VYA | SNJ54HC164J | 8416201CA | UT54ACS164245SUCC | 5962-9858002QXC |
| 54ACTQ16373FMQB | 5962-9561801QXA | SNV54HC164J | 5962-8416201VCA | UT54ACS164245SUCC | 5962-9858003QXC |
| 54FCT16373 (GEN) | 5962-9225901MXA | SNV54HC164W | 5962-8416201VDA | UT54ACS164245SUCC | 5962R9858001VXC |
| 54FCT16373A (GEN) | 5962-9225902MXA | UT54ACS164E-Q-DIE | 5962G9655603Q9B | UT54ACS164245SUCC | 5962R9858002VXC |
| 54FCT16373C (GEN) | 5962-9225903MXA | UT54ACS164E-Q-DIE | 5962H9655602Q9B | UT54ACS164245SUCC | 5962R9858003VXC |
| 54LCX16373 (GEN) | 5962-9953401QXA | UT54ACS164EUQAG | 5962G9655603QXA | UT54ACS164245S-VDI | 5962R9858001V9A |
| RHFACT16373K01Q | 5962F9202402QYC | UT54ACS164EUQAH | 5962H9655602QXA | UT54ACS164245S-VDI | 5962R9858002V9A |
| RHFACT16373K01V | 5962F9202402VYC | UT54ACS164EUQCG | 5962G9655603QXC | UT54ACS164245S-VDI | 5962R9858003V9A |
| RHFACT16373K02Q | 5962F9202402QYA | UT54ACS164EUQCH | 5962H9655602QXC | 54ALS165 (GEN) | 5962-89574012A |
| RHFACT16373K02V | 5962F9202402VYA | UT54ACS164EUVAG | 5962G9655603VXA | 54ALS165 (GEN) | 5962-8957401EA |
| SNJ54ABT16373AWD | 5962-9320001QXA | UT54ACS164EUVAH | 5962H9655602VXA | 54ALS165 (GEN) | 5962-8957401FA |
| SNJ54ACT16373WD | 5962-9202401MXA | UT54ACS164EUVCG | 5962G9655603VXC | 54HC165K01Q | 8409501XC |
| SNJ54LVTH16373WD | 5962-9681001QXA | UT54ACS164EUVCH | 5962H9655602VXC | 54HC165K01V | 5962-8409501VXC |
| 54AC16373K01Q | 5962-0421201QXC | UT54ACS164E-V-DIE | 5962G9655603V9B | 54HC165K02Q | 8409501XA |
| 54AC16373K01V | 5962-0421201VXC | UT54ACS164E-V-DIE | 5962H9655602V9B | 54HC165K02V | 5962-8409501VXA |
| 54AC16373K02Q | 5962-0421201QXA | UT54ACS164PQAH | 5962H9655601QCA | CD54HC165F3A | 8409501EA |
| 54AC16373K02V | 5962-0421201VXA | UT54ACS164PQCH | 5962H9655601QCC | CD54HCT165F3A | 5962-8685501EA |
| 54ABT16374W-QML | 5962-9320101QXA | UT54ACS164PVAH | 5962H9655601VCA | SNJ54HC165FK | 84095012A |
| 54ACT16374K01Q | 5962-9202502QYC | UT54ACS164PVCH | 5962H9655601VCC | SNJ54HC165J | 8409501EA |
| 54ACT16374K01V | 5962-9202502VYC | UT54ACS164-QDIE | 5962H9655601Q9A | SNJ54HC165W | 8409501FA |
| 54ACT16374K02Q | 5962-9202502QYA | UT54ACS164UQAH | 5962H9655601QXA | SNJ54LS165AJ | 7700601EA |
| 54ACT16374K02V | 5962-9202502VYA | UT54ACS164UQCH | 5962H9655601QXC | SNJ54LS165AW | 7700601FA |
| 54ACTQ16374FMQB | 5962-9452801QXA | UT54ACS164UVAH | 5962H9655601VXA | SNV54LS165AJ | 5962-7700601VEA |
| 54ACTQ16374W-QV | 5962-9452801VXA | UT54ACS164UVCH | 5962H9655601VXC | SNV54LS165AW | 5962-7700601VFA |
| 54FCT16374 (GEN) | 5962-9226001MXA | UT54ACS164-VDIE | 5962H9655601V9A | UT54ACS165EUQAG | 5962G9655803QXA |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

| Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN |
|---|---|---|---|---|---|
| UT54ACS165EUQAH | 5962H9655802QXA | 54FCT16841B (GEN) | 5962-9226802MXA | 54AC174K02V | 5962-8762602VXA |
| UT54ACS165EUQCG | 5962G9655803QXC | 54FCT16841C (GEN) | 5962-9226803MXA | 54AC174LMQB | 5962-87626012A |
| UT54ACS165EUQCH | 5962H9655802QXC | SNJ54ABT16841WD | 5962-9564601QXA | 54ACT174DMQB | 5962-8775701EA |
| UT54ACS165EUVAG | 5962G9655803VXA | 54AC169DMQB | 5962-9160301MEA | 54ACT174FMQB | 5962-8775701FA |
| UT54ACS165EUVAH | 5962H9655802VXA | 54AC169DMQB-RH | 5962R9160301MEA | 54ACT174K01Q | 5962-8775701XC |
| UT54ACS165EUVCG | 5962G9655803VXC | 54AC169ERQMLV | 5962R9160301V2A | 54ACT174K01V | 5962-8775701VXC |
| UT54ACS165EUVCH | 5962H9655802VXC | 54AC169FMQB | 5962-9160301MFA | 54ACT174K02Q | 5962-8775701XA |
| UT54ACS165PQAH | 5962H9655801QEA | 54AC169FMQB-RH | 5962R9160301MFA | 54ACT174K02V | 5962-8775701VXA |
| UT54ACS165PQCH | 5962H9655801QEC | 54AC169JRQMLV | 5962R9160301VEA | 54ACT174LMQB | 5962-87757012A |
| UT54ACS165PVAH | 5962H9655801VEA | 54AC169LMQB | 5962-9160301M2A | 54HCT174F3A | 5962-8974301EA |
| UT54ACS165PVCH | 5962H9655801VEC | 54AC169LMQB-RH | 5962R9160301M2A | SNJ54ALS174FK | 83019012A |
| UT54ACS165UQAH | 5962H9655801QXA | 54AC169WRQMLV | 5962R9160301VFA | SNJ54ALS174J | 8301901EA |
| UT54ACS165UQCH | 5962H9655801QXC | 54F169DMQB | 5962-8607201EA | SNJ54ALS174W | 8301901FA |
| UT54ACS165UVAH | 5962H9655801VXA | 54F169FMQB | 5962-8607201FA | SNJ54HC174FK | 84073012A |
| UT54ACS165UVCH | 5962H9655801VXC | 54F169LMQB | 5962-86072012A | SNJ54HC174J | 8407301EA |
| UT54ACTS165PQAH | 5962H9655901QEA | SL54LS169/B2A | 80018022A | SNJ54HC174W | 8407301FA |
| UT54ACTS165PQCH | 5962H9655901QEC | SL54LS169/B2C | 80018022C | 54AC175DMQB | 5962-8955201EA |
| UT54ACTS165PVAH | 5962H9655901VEA | SL54LS169/BEA | 8001802EA | 54AC175ERQMLV | 5962R8955201V2A |
| UT54ACTS165PVCH | 5962H9655901VEC | SL54LS169/BFA | 8001802FA | 54AC175FMQB | 5962-8955201FA |
| UT54ACTS165UQAH | 5962H9655901QXA | SNJ54ALS169BFK | 83025012A | 54AC175JRQMLV | 5962R8955201VEA |
| UT54ACTS165UQCH | 5962H9655901QXC | SNJ54ALS169BJ | 8302501EA | 54AC175LMQB | 5962-89552012A |
| UT54ACTS165UVAH | 5962H9655901VXA | SNJ54ALS169BW | 8302501FA | 54AC175WRQMLV | 5962R8955201VFA |
| UT54ACTS165UVCH | 5962H9655901VXC | SNJ54LS169BJ | 8001802EA | 54ACT175DMQB | 5962-8969301EA |
| 54ABT16500W-QML | 5962-9687001QXA | SNJ54LS169BW | 8001802FA | 54ACT175DMQB-RH | 5962R8969301EA |
| SNJ54LVTH16501WD | 5962-9677701QXA | SNJ54LS169FK | 80018022A | 54ACT175E-QMLV | 5962-8969301V2A |
| 54ACTQ16541FMQB | 5962-0052901QXA | UT54ACS169PQAH | 5962H9656001QEA | 54ACT175ERQMLV | 5962R8969301V2A |
| 54FCT16543AT (GEN) | 5962-9226302MXA | UT54ACS169PQCH | 5962H9656001QEC | 54ACT175FMQB | 5962-8969301FA |
| 54FCT16543CT (GEN) | 5962-9226303MXA | UT54ACS169PVAH | 5962H9656001VEA | 54ACT175FMQB-RH | 5962R8969301FA |
| 54FCT16543T (GEN) | 5962-9226301MXA | UT54ACS169PVCH | 5962H9656001VEC | 54ACT175J-QMLV | 5962-8969301VEA |
| SNJ54ABT16543WD | 5962-9324101MXA | UT54ACS169UQAH | 5962H9656001QXA | 54ACT175JRQMLV | 5962R8969301VEA |
| SNJ54166J | 5962-9558301QEA | UT54ACS169UQCH | 5962H9656001QXC | 54ACT175LMQB | 5962-89693012A |
| SNJ54166W | 5962-9558301QFA | UT54ACS169UVAH | 5962H9656001VXA | 54ACT175LMQB-RH | 5962R89693012A |
| SNJ54HC166FK | 5962-9050101Q2A | UT54ACS169UVCH | 5962H9656001VXC | 54ACT175W-QMLV | 5962-8969301VFA |
| SNJ54HC166J | 5962-9050101QEA | UT54ACTS169PQAH | 5962H9656101QEA | 54ACT175WRQMLV | 5962R8969301VFA |
| SNJ54LS166AJ | 8001701EA | UT54ACTS169PQCH | 5962H9656101QEC | 54AS175 (GEN) | 5962-9553701QFA |
| SNJ54LS166AW | 8001701FA | UT54ACTS169PVAH | 5962H9656101VEA | 54HC175K01Q | 8408901XC |
| SNJ54ABT16601WD | 5962-9467101QXA | UT54ACTS169PVCH | 5962H9656101VEC | 54HC175K01V | 5962-8408901VXC |
| SNJ54GTL16612WD | 5962-9689001QXA | UT54ACTS169UQAH | 5962H9656101QXA | 54HC175K02Q | 8408901XA |
| SNJ54ABT16640WD | 5962-9559001QXA | UT54ACTS169UQCH | 5962H9656101QXC | 54HC175K02V | 5962-8408901VXA |
| 54ABT16646W-QML | 5962-9450202QXA | UT54ACTS169UVAH | 5962H9656101VXA | CD54HC175F3A | 8408901EA |
| 54ACTQ16646FMQB | 5962-9581601QXA | UT54ACTS169UVCH | 5962H9656101VXC | CD54HCT175F3A | 5962-8970101EA |
| 54FCT16646AT (GEN) | 5962-9226402MXA | SNJ54LVTH16952WD | 5962-9684901QXA | SNJ54ALS175FK | 83019022A |
| 54FCT16646CT (GEN) | 5962-9226403MXA | SL54LS170/BEA | 8002501EA | SNJ54ALS175J | 8301902EA |
| 54FCT16646T (GEN) | 5962-9226401MXA | SL54LS170/BFA | 8002501FA | SNJ54ALS175W | 8301902FA |
| SNJ54ABT16646WD | 5962-9450201QXA | SNJ54LS170W | 8002501FA | SNJ54AS175BFK | 5962-9553701Q2A |
| SNJ54ABT16652WD | 5962-9584101QXA | 54HC173/B2A | 5962-86825012A | SNJ54AS175BJ | 5962-9553701QEA |
| 54LS168 (GEN) | 8001801EA | CD54HC173F3A | 5962-8682501EA | SNJ54HC175FK | 84089012A |
| 54LS168 (GEN) | 8001801FA | CD54HCT173F3A | 5962-8875901EA | SNJ54HC175J | 8408901EA |
| SNJ54ABT16823WD | 5962-9584201QXA | 54AC174DMQB | 5962-8762601EA | SNJ54HC175W | 8408901FA |
| 54FCT16827A (GEN) | 5962-9226701MXA | 54AC174FMQB | 5962-8762601FA | 54F181DMQB | 5962-8671002JA |
| 54FCT16827B (GEN) | 5962-9226702MXA | 54AC174K01Q | 5962-8762602XC | 54F181LMQB | 5962-86710023A |
| 54FCT16827C (GEN) | 5962-9226703MXA | 54AC174K01V | 5962-8762602VXC | 54FCT182 (GEN) | 5962-88652012A |
| 54FCT16841A (GEN) | 5962-9226801MXA | 54AC174K02Q | 5962-8762602XA | 54FCT182 (GEN) | 5962-8865201EA |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

| Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN |
|---|---|---|---|---|---|
| 54FCT182 (GEN) | 5962-8865201FA | 54FCT191 (GEN) | 5962-8973303FA | 54HC193K02Q | 5962-8772401XA |
| 54FCT182A (GEN) | 5962-88652022A | 54FCT191A (GEN) | 5962-89733022A | 54HC193K02V | 5962-8772401VXA |
| 54FCT182A (GEN) | 5962-8865202EA | 54FCT191A (GEN) | 5962-8973302EA | CD54HC193F3A | 5962-8772401EA |
| 54FCT182A (GEN) | 5962-8865202FA | 54FCT191A (GEN) | 5962-8973302FA | CD54HCT193F3A | 5962-9084801MEA |
| 54ABT18245 (GEN) | 5962-9460101QXA | 54FCT191A (GEN) | 5962-89733042A | SN54LS193J | 7600601EA |
| SNJ54ABT18245AWD | 5962-9460102QXA | 54FCT191A (GEN) | 5962-8973304EA | SN54LS193W | 7600601FA |
| 54LS183 (GEN) | 5962-90541012A | 54FCT191A (GEN) | 5962-8973304FA | SNJ54ALS193AFK | 5962-88698012A |
| 54LS183 (GEN) | 5962-9054101DA | 54HC191K01Q | 5962-8689101XC | SNJ54ALS193AJ | 5962-8869801EA |
| AS54LS183C/883C | 5962-9054101CA | 54HC191K01V | 5962-8689101VXC | SNJ54ALS193AW | 5962-8869801FA |
| 54185A (GEN) | 77030012A | 54HC191K02Q | 5962-8689101XA | SNJ54HC193FK | 5962-87724012A |
| 54185A (GEN) | 7703001EA | 54HC191K02V | 5962-8689101VXA | SNJ54HC193J | 5962-8772401EA |
| 54185A (GEN) | 7703001FA | CD54HC191F3A | 5962-8689101EA | SNJ54LS193FK | 76006012A |
| SNJ54ABT18502HV | 5962-9467201QXA | CD54HCT191F3A | 5962-8867101EA | UT54ACS193PQAH | 5962H9656601QEA |
| SNJ54ABTH18502AHV | 5962-9561401QXA | SNJ54ALS191AFK | 5962-86840012A | UT54ACS193PQCH | 5962H9656601QEC |
| SNJ54LVTH18502AHV | 5962-9681101QXA | SNJ54ALS191AJ | 5962-8684001EA | UT54ACS193PVAH | 5962H9656601VEA |
| SNJ54ABT18646HV | 5962-9469801QXA | SNJ54ALS191AW | 5962-8684001FA | UT54ACS193PVCH | 5962H9656601VEC |
| SNJ54ABTH18646AHV | 5962-9669801QXA | SNJ54HC191FK | 5962-86891012A | UT54ACS193-QDIE | 5962H9656601Q9A |
| SL54S189/B2A | 78015022A | SNJ54HC191J | 5962-8689101EA | UT54ACS193UQAH | 5962H9656601QXA |
| SL54S189/B2C | 78015022C | SNJ54LS191EK | 76009012A | UT54ACS193UQCH | 5962H9656601QXC |
| SL54S189/BEA | 7801502EA | SNJ54LS191J | 7600901EA | UT54ACS193UVAH | 5962H9656601VXA |
| SL54S189/BFA | 7801502FA | SNJ54LS191W | 7600901FA | UT54ACS193UVCH | 5962H9656601VXC |
| 54HC190 (GEN) | 5962-89946012A | UT54ACS191PQAH | 5962H9656401QEA | UT54ACS193-VDIE | 5962H9656601V9A |
| 54LS190 (GEN) | 76035012A | UT54ACS191PQCH | 5962H9656401QEC | UT54ACTS193PQAH | 5962H9656701QEA |
| 54LS190 (GEN) | 7603501EA | UT54ACS191PVAH | 5962H9656401VEA | UT54ACTS193PQCH | 5962H9656701QEC |
| 54LS190 (GEN) | 7603501FA | UT54ACS191PVCH | 5962H9656401VEC | UT54ACTS193PVAH | 5962H9656701VEA |
| CD54HC190F3A | 5962-8994601EA | UT54ACS191-Q-DIE | 5962H9656401Q9A | UT54ACTS193PVCH | 5962H9656701VEC |
| UT54ACS190PQAH | 5962H9656201QEA | UT54ACS191UQAH | 5962H9656401QXA | UT54ACTS193UQAH | 5962H9656701QXA |
| UT54ACS190PQCH | 5962H9656201QEC | UT54ACS191UQCH | 5962H9656401QXC | UT54ACTS193UQCH | 5962H9656701QXC |
| UT54ACS190PVAH | 5962H9656201VEA | UT54ACS191UVAH | 5962H9656401VXA | UT54ACTS193UVAH | 5962H9656701VXA |
| UT54ACS190PVCH | 5962H9656201VEC | UT54ACS191UVCH | 5962H9656401VXC | UT54ACTS193UVCH | 5962H9656701VXC |
| UT54ACS190UQAH | 5962H9656201QXA | UT54ACS191-V-DIE | 5962H9656401V9A | 54F194 (GEN) | 5962-86850012A |
| UT54ACS190UQCH | 5962H9656201QXC | UT54ACTS191PQAH | 5962H9656501QEA | 54F194 (GEN) | 5962-8685001EA |
| UT54ACS190UVAH | 5962H9656201VXA | UT54ACTS191PQCH | 5962H9656501QEC | 54F194 (GEN) | 5962-8685001FA |
| UT54ACS190UVCH | 5962H9656201VXC | UT54ACTS191PVAH | 5962H9656501VEA | 54HC194/B2A | 5962-86826012A |
| UT54ACTS190PQAH | 5962H9656301QEA | UT54ACTS191PVCH | 5962H9656501VEC | CD54HC194F3A | 5962-8682601EA |
| UT54ACTS190PQCH | 5962H9656301QEC | UT54ACTS191UQAH | 5962H9656501QXA | SL54S194/BEA | 7604001EA |
| UT54ACTS190PVAH | 5962H9656301VEA | UT54ACTS191UQCH | 5962H9656501QXC | SL54S194/BFA | 7604001FA |
| UT54ACTS190PVCH | 5962H9656301VEC | UT54ACTS191UVAH | 5962H9656501VXA | SNJ54S194J | 7604001EA |
| UT54ACTS190UQAH | 5962H9656301QXA | UT54ACTS191UVCH | 5962H9656501VXC | SNJ54S194W | 7604001FA |
| UT54ACTS190UQCH | 5962H9656301QXC | 54HC192 (GEN) | 5962-87808012A | SNJ54HC195FK | 5962-86827012A |
| UT54ACTS190UVAH | 5962H9656301VXA | CD54HC192F3A | 5962-8780801EA | SNJ54HC195J | 5962-8682701EA |
| UT54ACTS190UVCH | 5962H9656301VXC | SL54192/BEA | 5962-9558401QEA | 54LS196 (GEN) | 77010012A |
| 54AC191DMQB | 5962-8974901EA | SL54192/BFA | 5962-9558401QFA | SL54LS197/BCA | 7601501CA |
| 54AC191FMQB | 5962-8974901FA | SNJ54192J | 5962-9558401QEA | SL54LS197/BDA | 7601501DA |
| 54AC191LMQB | 5962-89749012A | SNJ54192W | 5962-9558401QFA | SNJ54LS197J | 7601501CA |
| 54F191DMQB | 5962-9058201EA | 54FCT193 (GEN) | 5962-9066901M2A | SNJ54LS197W | 7601501DA |
| 54F191FMQB | 5962-9058201FA | 54FCT193 (GEN) | 5962-9066901MEA | 54F198 (GEN) | 5962-90502013A |
| 54F191LMQB | 5962-90582012A | 54FCT193 (GEN) | 5962-9066901MFA | 54F198 (GEN) | 5962-9050201KA |
| 54FCT191 (GEN) | 5962-89733012A | 54FCT193A (GEN) | 5962-9066902M2A | 54F198 (GEN) | 5962-9050201LA |
| 54FCT191 (GEN) | 5962-8973301EA | 54FCT193A (GEN) | 5962-9066902MEA | DG542AP/883 | 5962-9155201MEA |
| 54FCT191 (GEN) | 5962-8973301FA | 54FCT193A (GEN) | 5962-9066902MFA | 54AC20DMQB | 5962-8761301CA |
| 54FCT191 (GEN) | 5962-89733032A | 54HC193K01Q | 5962-8772401XC | 54AC20FMQB | 5962-8761301DA |
| 54FCT191 (GEN) | 5962-8973303EA | 54HC193K01V | 5962-8772401VXC | 54AC20K01Q | 5962-8761303XC |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

| Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN |
|---|---|---|---|---|---|
| 54AC20K01V | 5962-8761303VXC | SNJ54HC21FK | 5962-88576012A | SNJ54BCT2240FK | 5962-9093901M2A |
| 54AC20K02Q | 5962-8761303XA | SNJ54HC21J | 5962-8857601CA | SNJ54BCT2240J | 5962-9093901MRA |
| 54AC20K02V | 5962-8761303VXA | SNJ54HC21W | 5962-8857601DA | SNJ54BCT2240W | 5962-9093901MSA |
| 54AC20LMQB | 5962-87613012A | UT54LVDS217-QDIE | 5962F0153402Q9A | 54F2244 (GEN) | 5962-9325001M2A |
| 54F20DMQB | 5962-9758401QCA | UT54LVDS217-QDIE | 5962H0153402Q9A | 54F2244DMQB | 5962-9325001MRA |
| 54F20FMQB | 5962-9758401QDA | UT54LVDS217-QDIE | 5962R0153401Q9A | 54F2244FMQB | 5962-9325001MSA |
| 54F20LMQB | 5962-9758401Q2A | UT54LVDS217UCA | 5962F0153402QXA | 54FCT2244 (GEN) | 5962-9301901M2A |
| 54HC20 (GEN) | 8403901AA | UT54LVDS217UCA | 5962F0153402VXA | 54FCT2244 (GEN) | 5962-9301901MSA |
| 54HC20 (GEN) | 8403901BA | UT54LVDS217UCA | 5962H0153402QXA | 54FCT2244A (GEN) | 5962-9301902M2A |
| CD54ACT20F3A | 5962-0051301QCA | UT54LVDS217UCA | 5962H0153402VXA | 54FCT2244A (GEN) | 5962-9301902MRA |
| SNJ54ALS20AW | 5962-8858901DA | UT54LVDS217UCA | 5962R0153401QXA | 54FCT2244A (GEN) | 5962-9301902MSA |
| SNJ54F20FK | 5962-9758401Q2A | UT54LVDS217UCA | 5962R0153401VXA | 54FCT2244C (GEN) | 5962-9301903M2A |
| SNJ54F20J | 5962-9758401QCA | UT54LVDS217UCC | 5962F0153402QXC | 54FCT2244C (GEN) | 5962-9301903MRA |
| SNJ54F20W | 5962-9758401QDA | UT54LVDS217UCC | 5962F0153402VXC | 54FCT2244C (GEN) | 5962-9301903MSA |
| SNJ54HC20FK | 84039012A | UT54LVDS217UCC | 5962F0153402VXC | I54FCT2244 (GEN) | 5962-9301901MRA |
| SNJ54HC20J | 8403901CA | UT54LVDS217UCC | 5962H0153402QXC | SNJ54ABT2244FK | 5962-9467301Q2A |
| SNJ54HC20W | 8403901DA | UT54LVDS217UCC | 5962H0153402VXC | SNJ54ABT2244J | 5962-9467301QRA |
| UT54ACS20PQAH | 5962H9652601QCA | UT54LVDS217UCC | 5962R0153401QXC | SNJ54ABT2244W | 5962-9467301QSA |
| UT54ACS20PQCH | 5962H9652601QCC | UT54LVDS217UCC | 5962R0153401VXC | SNJ54BCT2244FK | 5962-9074101M2A |
| UT54ACS20PVAH | 5962H9652601VCA | UT54LVDS217-VDIE | 5962F0153402V9A | SNJ54BCT2244J | 5962-9074101MRA |
| UT54ACS20PVCH | 5962H9652601VCC | UT54LVDS217-VDIE | 5962H0153402V9A | SNJ54BCT2244W | 5962-9074101MSA |
| UT54ACS20-QDIE | 5962H9652601Q9A | UT54LVDS217-VDIE | 5962R0153401V9A | 54FCT2245 (GEN) | 5962-9302001M2A |
| UT54ACS20UQAH | 5962H9652601QXA | UT54LVDS218-QDIE | 5962H0153501Q9A | 54FCT2245 (GEN) | 5962-9302001MRA |
| UT54ACS20UQCH | 5962H9652601QXC | UT54LVDS218-QDIE | 5962H0153502Q9A | 54FCT2245 (GEN) | 5962-9302001MSA |
| UT54ACS20UVAH | 5962H9652601VXA | UT54LVDS218UCA | 5962H0153501QXA | 54FCT2245A (GEN) | 5962-9302002M2A |
| UT54ACS20UVCH | 5962H9652601VXC | UT54LVDS218UCA | 5962H0153501VXA | 54FCT2245A (GEN) | 5962-9302002MRA |
| UT54ACS20-VDIE | 5962H9652601V9A | UT54LVDS218UCA | 5962H0153502QXA | 54FCT2245A (GEN) | 5962-9302002MSA |
| UT54ACTS20PQAH | 5962H9652701QCA | UT54LVDS218UCA | 5962H0153502VXA | 54FCT2245C (GEN) | 5962-9302003M2A |
| UT54ACTS20PQCH | 5962H9652701QCC | UT54LVDS218UCC | 5962H0153501QXC | 54FCT2245C (GEN) | 5962-9302003MRA |
| UT54ACTS20PVAH | 5962H9652701VCA | UT54LVDS218UCC | 5962H0153501VXC | 54FCT2245C (GEN) | 5962-9302003MSA |
| UT54ACTS20PVCH | 5962H9652701VCC | UT54LVDS218UCC | 5962H0153502QXC | SNJ54ABT2245FK | 5962-9560601Q2A |
| UT54ACTS20UQAH | 5962H9652701QXA | UT54LVDS218UCC | 5962H0153502VXC | SNJ54ABT2245J | 5962-9560601QRA |
| UT54ACTS20UQCH | 5962H9652701QXC | UT54LVDS218-VDIE | 5962H0153501V9A | SNJ54ABT2245W | 5962-9560601QSA |
| UT54ACTS20UVAH | 5962H9652701VXA | UT54LVDS218-VDIE | 5962H0153502V9A | UT54LVDM228UPA | 5962H0153701QXA |
| UT54ACTS20UVCH | 5962H9652701VXC | UT54ACTS220PQAH | 5962H9675301QCA | UT54LVDM228UPA | 5962H0153701VXA |
| 54ACT20K01Q | 5962-0051302QXC | UT54ACTS220PQCH | 5962H9675301QCC | UT54LVDM228UPC | 5962H0153701QXC |
| 54ACT20K01V | 5962-0051302VXC | UT54ACTS220PVAH | 5962H9675301VCA | UT54LVDM228UPC | 5962H0153701VXC |
| 54ACT20K02Q | 5962-0051302QXA | UT54ACTS220PVCH | 5962H9675301VCC | SNJ5423J | 5962-9763601QEA |
| 54ACT20K02V | 5962-0051302VXA | UT54ACTS220UQAH | 5962H9675301QXA | 54HC237 (GEN) | 5962-8860601VFA |
| 54FB2031 (GEN) | 5962-9477301QXA | UT54ACTS220UQCH | 5962H9675301QXC | 54HC237/B2A | 5962-88606012A |
| 54FB2033 (GEN) | 5962-9457401QXA | UT54ACTS220UVAH | 5962H9675301VXA | 54HC237/BFA | 5962-8860601FA |
| 54FB2040 (GEN) | 5962-9681501QXA | UT54ACTS220UVCH | 5962H9675301VXC | 54HC237K01Q | 5962-8860601XC |
| 54ALS21 (GEN) | 8414301BA | 54HC221AE/B2A | 5962-87805022A | 54HC237K01V | 5962-8860601VXC |
| 54AS21 (GEN) | 5962-8780401CA | 54HC221AJ/BEA | 5962-8780502EA | 54HC237K02Q | 5962-8860601XA |
| 54F21 (GEN) | 5962-89554012A | CD54HC221F3A | 5962-8780501EA | 54HC237K02V | 5962-8860601VXA |
| 54F21 (GEN) | 5962-8955401CA | SL54221/BEA | 5962-8771101EA | CD54HC237F3A | 5962-8860601EA |
| 54F21 (GEN) | 5962-8955401DA | SNJ54221J | 5962-8771101EA | 54FCT2374 (GEN) | 5962-9302601M2A |
| SNJ54ALS21AFK | 84143012A | SNJ54LS221FK | 76042012A | 54FCT2374 (GEN) | 5962-9302601MRA |
| SNJ54ALS21AJ | 8414301CA | SNJ54LS221J | 7604201EA | 54FCT2374 (GEN) | 5962-9302601MSA |
| SNJ54ALS21AW | 8414301DA | SNJ54LS221W | 7604201FA | 54FCT2374A (GEN) | 5962-9302602M2A |
| SNJ54AS21FK | 5962-87804012A | SNJ54ABT2240AFK | 5962-9469701Q2A | 54FCT2374A (GEN) | 5962-9302602MRA |
| SNJ54AS21W | 5962-8780401DA | SNJ54ABT2240AJ | 5962-9469701QRA | 54FCT2374A (GEN) | 5962-9302602MSA |
| SNJ54AS21WA | 5962-8780401BA | SNJ54ABT2240AW | 5962-9469701QSA | 54FCT2374C (GEN) | 5962-9302603M2A |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

| Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN |
|---|---|---|---|---|---|
| 54FCT2374C (GEN) | 5962-9302603MRA | IDT54FCT240CTDB | 5962-9221305MRA | UT54ACS240PVAH | 5962H9656801VRA |
| 54FCT2374C (GEN) | 5962-9302603MSA | IDT54FCT240CTLB | 5962-9221305M2A | UT54ACS240PVCH | 5962H9656801VRC |
| 54HC238/B2A | 5962-86884012A | IDT54FCT240TDB | 5962-9221301MRA | UT54ACS240UQAH | 5962H9656801QXA |
| CD54HC238F3A | 5962-8688401EA | IDT54FCT240TLB | 5962-9221301M2A | UT54ACS240UQCH | 5962H9656801QXC |
| SNJ54HCT238FK | 5962-89745012A | JM54ACT240B2A | 5962-8775901B2A | UT54ACS240UVAH | 5962H9656801VXA |
| SNJ54HCT238J | 5962-8974501EA | JM54ACT240B2A-R | 5962R8775901B2A | UT54ACS240UVCH | 5962H9656801VXC |
| 54ABT240E-QML | 5962-9318801Q2A | JM54ACT240BRA | 5962-8775901BRA | UT54ACTS240PQAH | 5962H9656901QRA |
| 54ABT240J-QML | 5962-9318801QRA | JM54ACT240BRA-R | 5962R8775901BRA | UT54ACTS240PQCH | 5962H9656901QRC |
| 54ABT240W-QML | 5962-9318801QSA | JM54ACT240BSA | 5962-8775901BSA | UT54ACTS240PVAH | 5962H9656901VRA |
| 54AC240DMQB | 5962-8755001RA | JM54ACT240BSA-R | 5962R8775901BSA | UT54ACTS240PVCH | 5962H9656901VRC |
| 54AC240FMQB | 5962-8755001SA | JM54ACT240S2A-R | 5962R8775901S2A | UT54ACTS240UQAH | 5962H9656901QXA |
| 54AC240K01Q | 5962-8755001XC | JM54ACT240SRA-R | 5962R8775901SRA | UT54ACTS240UQCH | 5962H9656901QXC |
| 54AC240K01V | 5962-8755001VXC | JM54ACT240SSA-R | 5962R8775901SSA | UT54ACTS240UVAH | 5962H9656901VXA |
| 54AC240K02Q | 5962-8755001XA | SL54S240/B2C | 78012012C | UT54ACTS240UVCH | 5962H9656901VXC |
| 54AC240K02V | 5962-8755001VXA | SL54S240/BRA | 7801201RA | 54ACT240K01Q | 5962-8775903QXC |
| 54AC240LMQB | 5962-87550012A | SL54S240/BSA | 7801201SA | 54ACT240K01V | 5962-8775903VXC |
| 54AC240WG-QML | 5962-8755001ZA | SNJ54ABT240FK | 5962-9318801M2A | 54ACT240K02Q | 5962-8775903QXA |
| 54ACT240 (GEN) | 5962-87759012A | SNJ54ABT240J | 5962-9318801MRA | 54ACT240K02V | 5962-8775903VXA |
| 54ACT240 (GEN) | 5962-8775901RA | SNJ54ABT240W | 5962-9318801MSA | CY54FCT240ATDMB | 5962-9221303MRA |
| 54ACT240 (GEN) | 5962-8775901S2A | SNJ54AC240FK | 5962-87550012A | CY54FCT240ATLMB | 5962-9221303M2A |
| 54ACT240 (GEN) | 5962-8775901SA | SNJ54AC240J | 5962-8755001RA | CY54FCT240CTDMB | 5962-9221305MRA |
| 54ACT240 (GEN) | 5962-8775901SRA | SNJ54AC240W | 5962-8755001SA | 54ABT241 (GEN) | 5962-9322701M2A |
| 54ACT240 (GEN) | 5962-8775901SSA | SNJ54ACT240FK | 5962-8775901M2A | 54ABT241 (GEN) | 5962-9322701MRA |
| 54ACT240DMQB | 5962-8775901MRA | SNJ54ACT240J | 5962-8775901MRA | 54ABT241 (GEN) | 5962-9322701MSA |
| 54ACT240FMQB | 5962-8775901MSA | SNJ54ACT240W | 5962-8775901MSA | 54ABT241E-QML | 5962-9322701Q2A |
| 54ACT240LMQB | 5962-8775901M2A | SNJ54AHC240FK | 5962-9680701Q2A | 54ABT241J-QML | 5962-9322701QRA |
| 54ACTQ240DMQB | 5962-9218401MRA | SNJ54AHC240J | 5962-9680701QRA | 54ABT241W-QML | 5962-9322701QSA |
| 54ACTQ240FMQB | 5962-9218401MSA | SNJ54AHC240W | 5962-9680701QSA | 54AC241DMQB | 5962-8755101RA |
| 54ACTQ240LMQB | 5962-9218401M2A | SNJ54AHCT240FK | 5962-9680601Q2A | 54AC241FMQB | 5962-8755101SA |
| 54FCT240A (GEN) | 5962-87655022A | SNJ54AHCT240J | 5962-9680601QRA | 54AC241LMQB | 5962-87551012A |
| 54FCT240A (GEN) | 5962-8765502RA | SNJ54AHCT240W | 5962-9680601QSA | 54AC241WG-QML | 5962-8755101ZA |
| 54FCT240A (GEN) | 5962-8765502SA | SNJ54ALS240AW | 5962-8859101SA | 54ACT241DMQB | 5962-8984701RA |
| 54FCT240AT (GEN) | 5962-9221303MSA | SNJ54BCT240FK | 5962-9074201M2A | 54ACT241E-QMLV | 5962-8984701V2A |
| 54FCT240AT (GEN) | 5962-9221304M2A | SNJ54BCT240J | 5962-9074201MRA | 54ACT241FMQB | 5962-8984701SA |
| 54FCT240AT (GEN) | 5962-9221304MRA | SNJ54BCT240W | 5962-9074201MSA | 54ACT241J-QMLV | 5962-8984701VRA |
| 54FCT240CT (GEN) | 5962-9221305MSA | SNJ54F240FK | 5962-9758501Q2A | 54ACT241LMQB | 5962-89847012A |
| 54FCT240CT (GEN) | 5962-9221306M2A | SNJ54F240J | 5962-9758501QRA | 54ACT241WG-QMLV | 5962-8984701VZA |
| 54FCT240CT (GEN) | 5962-9221306MRA | SNJ54F240W | 5962-9758501QSA | 54ACT241W-QMLV | 5962-8984701VSA |
| 54FCT240DMQB | 5962-8765501RA | SNJ54HC240FK | 84074012A | 54ACTQ241DMQB | 5962-9218501MRA |
| 54FCT240FMQB | 5962-8765501SA | SNJ54HC240J | 8407401RA | 54ACTQ241E-QMLV | 5962-9218501V2A |
| 54FCT240LMQB | 5962-87655012A | SNJ54HC240W | 8407401SA | 54ACTQ241FMQB | 5962-9218501MSA |
| 54FCT240T (GEN) | 5962-9221301MSA | SNJ54HCT240FK | 85505012A | 54ACTQ241J-QMLV | 5962-9218501VRA |
| 54FCT240T (GEN) | 5962-9221302M2A | SNJ54HCT240J | 8550501RA | 54ACTQ241LMQB | 5962-9218501M2A |
| 54FCT240T (GEN) | 5962-9221302MRA | SNJ54LS240FK | 78012012A | 54ACTQ241W-QMLV | 5962-9218501VSA |
| 54HC240 (GEN) | 5962-8407401VSA | SNJ54LS240J | 7801201RA | 54ALS241 (GEN) | 5962-8859601SA |
| 54HC240K01Q | 8407401XC | SNJ54LS240W | 7801201SA | 54FCT241AT (GEN) | 5962-9223203M2A |
| 54HC240K01V | 5962-8407401VXC | SNJ54LVTH240FK | 5962-9950801Q2A | 54FCT241AT (GEN) | 5962-9223203MRA |
| 54HC240K02Q | 8407401XA | SNJ54LVTH240J | 5962-9950801QRA | 54FCT241AT (GEN) | 5962-9223203MSA |
| 54HC240K02V | 5962-8407401VXA | SNJ54LVTH240W | 5962-9950801QSA | 54FCT241AT (GEN) | 5962-9223204M2A |
| CD54HC240F3A | 8407401RA | SNV54LS240J | 5962-7801201VRA | 54FCT241AT (GEN) | 5962-9223204MRA |
| CY54FCT240TDMB | 5962-9221301MRA | SNV54LS240W | 5962-7801201VSA | 54FCT241CT (GEN) | 5962-9223205M2A |
| IDT54FCT240ATDB | 5962-9221303MRA | UT54ACS240PQAH | 5962H9656801QRA | 54FCT241CT (GEN) | 5962-9223205MRA |
| IDT54FCT240ATLB | 5962-9221303M2A | UT54ACS240PQCH | 5962H9656801QRC | 54FCT241CT (GEN) | 5962-9223205MSA |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

| Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN |
|---|---|---|---|---|---|
| 54FCT241CT (GEN) | 5962-9223206M2A | 54AC244K01Q | 5962-8755201XC | IDT54FCT244ATDB | 5962-9220302MRA |
| 54FCT241CT (GEN) | 5962-9223206MRA | 54AC244K01V | 5962-8755201VXC | IDT54FCT244ATLB | 5962-9220302M2A |
| 54FCT241T (GEN) | 5962-9223201M2A | 54AC244K02Q | 5962-8755201XA | IDT54FCT244CTDB | 5962-9220303MRA |
| 54FCT241T (GEN) | 5962-9223201MRA | 54AC244K02V | 5962-8755201VXA | IDT54FCT244CTLB | 5962-9220303M2A |
| 54FCT241T (GEN) | 5962-9223201MSA | 54AC244LMQB | 5962-87552012A | IDT54FCT244DB | 5962-8763001RA |
| 54FCT241T (GEN) | 5962-9223202M2A | 54AC244WG-QML | 5962-8755201ZA | IDT54FCT244LB | 5962-87630012A |
| 54FCT241T (GEN) | 5962-9223202MRA | 54ACQ244DMQB | 5962-9217601MRA | IDT54FCT244TDB | 5962-9220301MRA |
| 54PCT241 (GEN) | 5962-89732012A | 54ACQ244FMQB | 5962-9217601MSA | IDT54FCT244TLB | 5962-9220301M2A |
| 54PCT241 (GEN) | 5962-8973201RA | 54ACQ244LMQB | 5962-9217601M2A | JM54ACT244B2A | 5962-8776001B2A |
| 54PCT241 (GEN) | 5962-8973201SA | 54ACT244 (GEN) | 5962-87760012A | JM54ACT244B2A-RH | 5962R8776001B2A |
| 54PCT241A (GEN) | 5962-89732022A | 54ACT244 (GEN) | 5962-8776001RA | JM54ACT244BRA | 5962-8776001BRA |
| 54PCT241A (GEN) | 5962-8973202RA | 54ACT244 (GEN) | 5962-8776001SA | JM54ACT244BRA-RH | 5962R8776001BRA |
| 54PCT241A (GEN) | 5962-8973202SA | 54ACT244DMQB | 5962-8776001MRA | JM54ACT244BSA | 5962-8776001BSA |
| SNJ54ABT241FK | 5962-9322701Q2A | 54ACT244FMQB | 5962-8776001MSA | JM54ACT244BSA-RH | 5962R8776001BSA |
| SNJ54ABT241J | 5962-9322701QRA | 54ACT244LMQB | 5962-8776001M2A | JM54ACT244S2A-RH | 5962R8776001S2A |
| SNJ54ABT241W | 5962-9322701QSA | 54ACTQ244DMQB | 5962-9218601MRA | JM54ACT244SRA-RH | 5962R8776001SRA |
| SNJ54ACT241FK | 5962-89847012A | 54ACTQ244DMQB-R | 5962R9218601MRA | JM54ACT244SSA-F | 5962F8776001SSA |
| SNJ54ACT241J | 5962-8984701RA | 54ACTQ244E-QMLV | 5962-9218601V2A | JM54ACT244SSA-RH | 5962R8776001SSA |
| SNJ54ACT241W | 5962-8984701SA | 54ACTQ244ERQMLV | 5962R9218601V2A | JM54ACT244SZA-F | 5962F8776001SZA |
| SNJ54ALS241BW | 5962-8859602SA | 54ACTQ244FMQB | 5962-9218601MSA | JM54ACT244SZA-RH | 5962R8776001SZA |
| SNJ54BCT241FK | 5962-9074301M2A | 54ACTQ244FMQB-R | 5962R9218601MSA | SL54LS244/BRA | 7705701RA |
| SNJ54BCT241J | 5962-9074301MRA | 54ACTQ244J-QMLV | 5962-9218601VRA | SL54LS244/BSA | 7705701SA |
| SNJ54BCT241W | 5962-9074301MSA | 54ACTQ244JRQMLV | 5962R9218601VRA | SNJ54ABT244FK | 5962-9214701M2A |
| SNJ54F241FK | 5962-86874012A | 54ACTQ244LMQB | 5962-9218601M2A | SNJ54ABT244J | 5962-9214701MRA |
| SNJ54F241J | 5962-8687401RA | 54ACTQ244LMQB-R | 5962R9218601M2A | SNJ54ABT244W | 5962-9214701MSA |
| SNJ54F241W | 5962-8687401SA | 54ACTQ244W-QMLV | 5962-9218601VSA | SNJ54AC244FK | 5962-87552012A |
| 54ALS242B (GEN) | 84013012A | 54ACTQ244WRQMLV | 5962R9218601VSA | SNJ54AC244J | 5962-8755201RA |
| 54ALS242B (GEN) | 8401301CA | 54FCT244A (GEN) | 5962-8763002SA | SNJ54AC244W | 5962-8755201SA |
| 54ALS242B (GEN) | 8401301DA | 54FCT244AT (GEN) | 5962-9220305M2A | SNJ54ACT244FK | 5962-8776001M2A |
| 54LS242 (GEN) | 80020012A | 54FCT244AT (GEN) | 5962-9220305MRA | SNJ54ACT244J | 5962-8776001MRA |
| 54LS242 (GEN) | 8002001CA | 54FCT244CT (GEN) | 5962-9220306M2A | SNJ54ACT244W | 5962-8776001MSA |
| 54LS242 (GEN) | 8002001DA | 54FCT244CT (GEN) | 5962-9220306MRA | SNJ54AHC244FK | 5962-9678201Q2A |
| 54F243/2A | 5962-86834012A | 54FCT244DMQB | 5962-8763001RA | SNJ54AHC244J | 5962-9678201QRA |
| 54F243/CA | 5962-8683401CA | 54FCT244FMQB | 5962-8763001SA | SNJ54AHC244W | 5962-9678201QSA |
| 54F243/DA | 5962-8683401DA | 54FCT244LMQB | 5962-87630012A | SNJ54AHCT244FK | 5962-9678301Q2A |
| 54HC243 (GEN) | 84090012A | 54FCT244T (GEN) | 5962-9220304M2A | SNJ54AHCT244J | 5962-9678301QRA |
| 54HC243 (GEN) | 8409001BA | 54FCT244T (GEN) | 5962-9220304MRA | SNJ54AHCT244W | 5962-9678301QSA |
| 54HC243 (GEN) | 8409001DA | 54HC244K01Q | 8409601XC | SNJ54ALS244CFK | 5962-86839012A |
| 54LS243 (GEN) | 80020022A | 54HC244K01V | 5962-8409601VXC | SNJ54ALS244CJ | 5962-8683901RA |
| CD54HC243F3A | 8409001CA | 54HC244K02Q | 8409601XA | SNJ54ALS244CW | 5962-8683901SA |
| SNJ54ALS243AFK | 84013022A | 54HC244K02V | 5962-8409601VXA | SNJ54AS244AFK | 5962-9755901Q2A |
| SNJ54ALS243AJ | 8401302CA | CD54HC244F3A | 8409601RA | SNJ54AS244AJ | 5962-9755901QRA |
| SNJ54ALS243AW | 8401302DA | CY54FCT244ATDMB | 5962-9220302MRA | SNJ54AS244AW | 5962-9755901QSA |
| SNJ54LS243J | 8002002CA | CY54FCT244ATLMB | 5962-9220302M2A | SNJ54BCT244FK | 5962-9062501M2A |
| SNJ54LS243W | 8002002DA | CY54FCT244ATW | 5962-9220302MSA | SNJ54BCT244J | 5962-9062501MRA |
| 54ABT244E-QML | 5962-9214701Q2A | CY54FCT244CTDMB | 5962-9220303MRA | SNJ54BCT244W | 5962-9062501MSA |
| 54ABT244E-QMLV | 5962-9214701V2A | CY54FCT244CTLMB | 5962-9220303M2A | SNJ54F244FK | 5962-9758601Q2A |
| 54ABT244J-QML | 5962-9214701QRA | CY54FCT244CTW | 5962-9220303MSA | SNJ54F244J | 5962-9758601QRA |
| 54ABT244J-QMLV | 5962-9214701VRA | CY54FCT244TDMB | 5962-9220301MRA | SNJ54F244W | 5962-9758601QSA |
| 54ABT244W-QML | 5962-9214701QSA | CY54FCT244TLMB | 5962-9220301M2A | SNJ54HC244FK | 84096012A |
| 54ABT244W-QMLV | 5962-9214701VSA | CY54FCT244TW | 5962-9220301MSA | SNJ54HC244J | 8409601RA |
| 54AC244DMQB | 5962-8755201RA | IDT54FCT244ADB | 5962-8763002RA | SNJ54HC244W | 8409601SA |
| 54AC244FMQB | 5962-8755201SA | IDT54FCT244ALB | 5962-87630022A | SNJ54HCT244FK | 85130012A |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

| Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN |
|---|---|---|---|---|---|
| SNJ54HCT244J | 8513001RA | 54AC245K01Q | 5962-8775801XC | IDT54FCT245ALB | 5962-87629022A |
| SNJ54LS244J | 7705701RA | 54AC245K01V | 5962-8775801VXC | IDT54FCT245ATDB | 5962-9221403MRA |
| SNJ54LS244W | 7705701SA | 54AC245K02Q | 5962-8775801XA | IDT54FCT245ATLB | 5962-9221403M2A |
| SNJ54LVCH244AFK | 5962-9754201Q2A | 54AC245K02V | 5962-8775801VXA | IDT54FCT245CTDB | 5962-9221405MRA |
| SNJ54LVCH244AJ | 5962-9754201QRA | 54AC245LMQB | 5962-87758012A | IDT54FCT245CTLB | 5962-9221405M2A |
| SNJ54LVCH244AW | 5962-9754201QSA | 54AC245WG-QML | 5962-8775801ZA | IDT54FCT245DB | 5962-8762901RA |
| SNJ54LVTH244AFK | 5962-9584401Q2A | 54ACQ245DMQB | 5962-9217701MRA | IDT54FCT245LB | 5962-87629012A |
| SNJ54LVTH244AJ | 5962-9584401QRA | 54ACQ245FMQB | 5962-9217701MSA | IDT54FCT245TDB | 5962-9221401MRA |
| SNJ54LVTH244AW | 5962-9584401QSA | 54ACQ245LMQB | 5962-9217701M2A | IDT54FCT245TLB | 5962-9221401M2A |
| SNV54AC244J | 5962-8755201VRA | 54ACT245 (GEN) | 5962-87663012A | JM54ACT245B2A | 5962-8766301B2A |
| SNV54AC244W | 5962-8755201VSA | 54ACT245 (GEN) | 5962-8766301RA | JM54ACT245B2A-R | 5962R8766301B2A |
| SNV54ACT244FK | 5962-8776001S2A | 54ACT245 (GEN) | 5962-8766301SA | JM54ACT245BRA | 5962-8766301BRA |
| SNV54ACT244J | 5962-8776001SRA | 54ACT245DMQB | 5962-8766301MRA | JM54ACT245BRA-R | 5962R8766301BRA |
| SNV54ACT244W | 5962-8776001SSA | 54ACT245FMQB | 5962-8766301MSA | JM54ACT245BSA | 5962-8766301BSA |
| SNV54AHC244J | 5962-9678201VRA | 54ACT245LMQB | 5962-8766301M2A | JM54ACT245BSA-R | 5962R8766301BSA |
| SNV54AHC244W | 5962-9678201VSA | 54ACTQ245DMQB | 5962-9218701MRA | JM54ACT245S2A-R | 5962R8766301S2A |
| SNV54HC244J | 5962-8409601VRA | 54ACTQ245DMQB-R | 5962R9218701MRA | JM54ACT245SRA-R | 5962R8766301SRA |
| SNV54HC244W | 5962-8409601VSA | 54ACTQ245ERQMLV | 5962R9218701V2A | JM54ACT245SSA-R | 5962R8766301SSA |
| SNV54HCT244J | 5962-8513001VRA | 54ACTQ245FMQB | 5962-9218701MSA | SL54S245/B2A | 80021012A |
| SNV54HCT244W | 5962-8513001VSA | 54ACTQ245FMQB-R | 5962R9218701MSA | SL54S245/BSA | 8002101SA |
| SNV54LVCH244AJ | 5962-9754201VRA | 54ACTQ245JRQMLV | 5962R9218701VRA | SNJ54ABT245AFK | 5962-9214802Q2A |
| SNV54LVTH244AJ | 5962-9584401VRA | 54ACTQ245LMQB | 5962-9218701M2A | SNJ54ABT245AJ | 5962-9214802QRA |
| SNV54LVTH244AW | 5962-9584401VSA | 54ACTQ245LMQB-R | 5962R9218701M2A | SNJ54ABT245AW | 5962-9214802QSA |
| UT54ACS244PQAH | 5962H9657001QRA | 54ACTQ245WRQMLV | 5962R9218701VSA | SNJ54ABTH245FK | 5962-9762301Q2A |
| UT54ACS244PQCH | 5962H9657001QRC | 54FCT245A (GEN) | 5962-8762902SA | SNJ54ABTH245J | 5962-9762301QRA |
| UT54ACS244PVAH | 5962H9657001VRA | 54FCT245AT (GEN) | 5962-9221403MSA | SNJ54ABTH245W | 5962-9762301QSA |
| UT54ACS244PVCH | 5962H9657001VRC | 54FCT245AT (GEN) | 5962-9221404M2A | SNJ54AC245FK | 5962-87758012A |
| UT54ACS244UQAH | 5962H9657001QXA | 54FCT245AT (GEN) | 5962-9221404MRA | SNJ54AC245J | 5962-8775801RA |
| UT54ACS244UQCH | 5962H9657001QXC | 54FCT245CT (GEN) | 5962-9221405MSA | SNJ54AC245W | 5962-8775801SA |
| UT54ACS244UVAH | 5962H9657001VXA | 54FCT245CT (GEN) | 5962-9221406M2A | SNJ54ACT245FK | 5962-8766301M2A |
| UT54ACS244UVCH | 5962H9657001VXC | 54FCT245CT (GEN) | 5962-9221406MRA | SNJ54ACT245J | 5962-8766301MRA |
| UT54ACTS244PQAH | 5962H9657101QRA | 54FCT245DMQB | 5962-8762901RA | SNJ54ACT245W | 5962-8766301MSA |
| UT54ACTS244PQCH | 5962H9657101QRC | 54FCT245FMQB | 5962-8762901SA | SNJ54AHC245FK | 5962-9681801Q2A |
| UT54ACTS244PVAH | 5962H9657101VRA | 54FCT245LMQB | 5962-87629012A | SNJ54AHC245J | 5962-9681801QRA |
| UT54ACTS244PVCH | 5962H9657101VRC | 54FCT245T (GEN) | 5962-9221401MSA | SNJ54AHC245W | 5962-9681801QSA |
| UT54ACTS244-QDIE | 5962H9657101Q9A | 54FCT245T (GEN) | 5962-9221402M2A | SNJ54AHCT245FK | 5962-9681901Q2A |
| UT54ACTS244UQAH | 5962H9657101QXA | 54FCT245T (GEN) | 5962-9221402MRA | SNJ54AHCT245J | 5962-9681901QRA |
| UT54ACTS244UQCH | 5962H9657101QXC | 54HC245K01Q | 8408501XC | SNJ54AHCT245W | 5962-9681901QSA |
| UT54ACTS244UVAH | 5962H9657101VXA | 54HC245K01V | 5962-8408501VXC | SNJ54ALS245AFK | 84030012A |
| UT54ACTS244UVCH | 5962H9657101VXC | 54HC245K02Q | 8408501XA | SNJ54ALS245AJ | 8403001RA |
| UT54ACTS244-VDIE | 5962H9657101V9A | 54HC245K02V | 5962-8408501VXA | SNJ54ALS245AW | 8403001SA |
| 54ACT244K01Q | 5962-8776003QXC | 54LCX245 (GEN) | 5962-9754302Q2A | SNJ54BCT245FK | 5962-9051401M2A |
| 54ACT244K01V | 5962-8776003VXC | 54LCX245 (GEN) | 5962-9754302QRA | SNJ54BCT245J | 5962-9051401MRA |
| 54ACT244K02Q | 5962-8776003QXA | 54LCX245 (GEN) | 5962-9754302QSA | SNJ54BCT245W | 5962-9051401MSA |
| 54ACT244K02V | 5962-8776003VXA | CD54HC245F3A | 8408501RA | SNJ54F245FK | 85511012A |
| 54ABT245 (GEN) | 5962-9214801M2A | CD54HCT245F3A | 8550601RA | SNJ54F245J | 8551101RA |
| 54ABT245 (GEN) | 5962-9214801MRA | CY54FCT245ATDMB | 5962-9221403MRA | SNJ54F245W | 8551101SA |
| 54ABT245 (GEN) | 5962-9214801MSA | CY54FCT245ATLMB | 5962-9221403M2A | SNJ54HC245FK | 84085012A |
| 54ABT245E-QML | 5962-9214801Q2A | CY54FCT245CTDMB | 5962-9221405MRA | SNJ54HC245J | 8408501RA |
| 54ABT245J-QML | 5962-9214801QRA | CY54FCT245CTLMB | 5962-9221405M2A | SNJ54HC245W | 8408501SA |
| 54ABT245W-QML | 5962-9214801QSA | CY54FCT245TDMB | 5962-9221401MRA | SNJ54HCT245FK | 85506012A |
| 54AC245DMQB | 5962-8775801RA | CY54FCT245TLMB | 5962-9221401M2A | SNJ54HCT245J | 8550601RA |
| 54AC245FMQB | 5962-8775801SA | IDT54FCT245ADB | 5962-8762902RA | SNJ54LS245FK | 80021012A |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

| Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN |
|---|---|---|---|---|---|
| SNJ54LS245W | 8002101SA | 54ACT245K01V | 5962-8766303VXC | SL54LS253/BFA | 7601701FA |
| SNJ54LVCH245AFK | 5962-9754301Q2A | 54ACT245K02Q | 5962-8766303QXA | SNJ54ALS253FK | 85096012A |
| SNJ54LVCH245AJ | 5962-9754301QRA | 54ACT245K02V | 5962-8766303VXA | SNJ54ALS253J | 8509601EA |
| SNJ54LVCH245AW | 5962-9754301QSA | 54ACT245 (GEN) | 5962-8766301S2A | SNJ54ALS253W | 8509601FA |
| SNJ54LVTH245AFK | 5962-9564201Q2A | 54LS248 (GEN) | 5962-89944012A | SNJ54HC253FK | 5962-88682012A |
| SNJ54LVTH245AJ | 5962-9564201QRA | 54LS248 (GEN) | 5962-8994401EA | SNJ54HC253J | 5962-8868201EA |
| SNJ54LVTH245AW | 5962-9564201QSA | SNJ54AS250AFK | 5962-90562013A | SNJ54LS253FK | 76017012A |
| SNV54AC245J | 5962-8775801VRA | SNJ54AS250AJT | 5962-9056201LA | SNJ54LS253J | 7601701EA |
| SNV54AC245W | 5962-8775801VSA | SNJ54AS250AW | 5962-9056201KA | SNJ54LS253W | 7601701FA |
| SNV54ACT245J | 5962-8766301SRA | 54AC251 (GEN) | 5962-8769201V2A | UT54ACS253PQAH | 5962H9657401QCA |
| SNV54ACT245W | 5962-8766301SSA | 54AC251 (GEN) | 5962-8769201VEA | UT54ACS253PQCH | 5962H9657401QCC |
| SNV54AHC245J | 5962-9681801VRA | 54AC251 (GEN) | 5962-8769201VFA | UT54ACS253PVAH | 5962H9657401VCA |
| SNV54AHC245W | 5962-9681801VSA | 54AC251DMQB | 5962-8769201EA | UT54ACS253PVCH | 5962H9657401VCC |
| SNV54HC245J | 5962-8408501VRA | 54AC251DMQB-RH | 5962R8769201EA | UT54ACS253UQAH | 5962H9657401QXA |
| SNV54HC245W | 5962-8408501VSA | 54AC251ERQMLV | 5962R8769201V2A | UT54ACS253UQCH | 5962H9657401QXC |
| SNV54HCT245J | 5962-8550601VRA | 54AC251FMQB | 5962-8769201FA | UT54ACS253UVAH | 5962H9657401VXA |
| SNV54HCT245W | 5962-8550601VSA | 54AC251FMQB-RH | 5962R8769201FA | UT54ACS253UVCH | 5962H9657401VXC |
| SNV54LS245J | 5962-8002101VRA | 54AC251JRQMLV | 5962R8769201VEA | UT54ACTS253PQAH | 5962H9657501QCA |
| SNV54LS245W | 5962-8002101VSA | 54AC251LMQB | 5962-87692012A | UT54ACTS253PQCH | 5962H9657501QCC |
| SNV54LVCH245AJ | 5962-9754301VRA | 54AC251LMQB-RH | 5962R87692012A | UT54ACTS253PVAH | 5962H9657501VCA |
| SNV54LVCH245AW | 5962-9754301VSA | 54AC251WRQMLV | 5962R8769201VFA | UT54ACTS253PVCH | 5962H9657501VCC |
| SNV54LVCH245AW | 5962-9754301VSA | 54ACT251DMQB | 5962-8959901EA | UT54ACTS253UQAH | 5962H9657501QXA |
| SNV54LVTH245AJ | 5962-9564201VRA | 54ACT251FMQB | 5962-8959901FA | UT54ACTS253UQCH | 5962H9657501QXC |
| SNV54LVTH245AW | 5962-9564201VSA | 54ACT251LMQB | 5962-89599012A | UT54ACTS253UVAH | 5962H9657501VXA |
| UT54ACS245PQAH | 5962H9657201QRA | 54HC251 (GEN) | 8512501FA | UT54ACTS253UVCH | 5962H9657501VXC |
| UT54ACS245PQCH | 5962H9657201QRC | CD54HCT251F3A | 5962-9052401MEA | 54AC257 (GEN) | 5962-8870301VFA |
| UT54ACS245PVAH | 5962H9657201VRA | SL54LS251/BEA | 7601601EA | 54AC257DMQB | 5962-8870301EA |
| UT54ACS245PVCH | 5962H9657201VRC | SL54LS251/BFA | 7601601FA | 54AC257FMQB | 5962-8870301FA |
| UT54ACS245-QDIE | 5962H9657201Q9A | SL54S251/B2A | 80022012A | 54AC257K01Q | 5962-8870301VXC |
| UT54ACS245SPQAH | 5962H9657202QRA | SL54S251/B2C | 80022012C | 54AC257K01Q | 5962-8870301XC |
| UT54ACS245SPQCH | 5962H9657202QRC | SL54S251/BEA | 8002201EA | 54AC257K02Q | 5962-8870301XA |
| UT54ACS245SPVAH | 5962H9657202VRA | SL54S251/BFA | 8002201FA | 54AC257K02V | 5962-8870301VXA |
| UT54ACS245SPVCH | 5962H9657202VRC | SN54LS251J | 7601601EA | 54AC257LMQB | 5962-88703012A |
| UT54ACS245S-QDIE | 5962H9657202Q9A | SN54LS251W | 7601601FA | 54ACT257 (GEN) | 5962-8968901V2A |
| UT54ACS245SUQAH | 5962H9657202QXA | SNJ54ALS251FK | 84135012A | 54ACT257 (GEN) | 5962-8968901VEA |
| UT54ACS245SUQCH | 5962H9657202QXC | SNJ54ALS251J | 8413501EA | 54ACT257 (GEN) | 5962-8968901VFA |
| UT54ACS245SUVAH | 5962H9657202VXA | SNJ54ALS251W | 8413501FA | 54ACT257DMQB | 5962-8968901EA |
| UT54ACS245SUVCH | 5962H9657202VXC | SNJ54HC251FK | 85125012A | 54ACT257DMQB-RH | 5962R8968901EA |
| UT54ACS245S-VDIE | 5962H9657202V9A | SNJ54HC251J | 8512501EA | 54ACT257ERQMLV | 5962R8968901V2A |
| UT54ACS245UQAH | 5962H9657201QXA | 54AC2525DMQB | 5962-9217401MCA | 54ACT257FMQB | 5962-8968901FA |
| UT54ACS245UQCH | 5962H9657201QXC | 54AC2525FMQB | 5962-9217401MDA | 54ACT257FMQB-RH | 5962R8968901FA |
| UT54ACS245UVAH | 5962H9657201VXA | 54AC2525LMQB | 5962-9217401M2A | 54ACT257FRQMLV | 5962R8968901VFA |
| UT54ACS245UVCH | 5962H9657201VXC | 54AC2525WFQMLV | 5962F9217401VDA | 54ACT257JRQMLV | 5962R8968901VEA |
| UT54ACS245-VDIE | 5962H9657201V9A | 54AC2525WRQMLV | 5962R9217401VDA | 54ACT257LMQB | 5962-89689012A |
| UT54ACTS245PQAH | 5962H9657301QRA | 54AC2526 (GEN) | 5962-9325201QFA | 54ACT257LMQB-RH | 5962R89689012A |
| UT54ACTS245PQCH | 5962H9657301QRC | 54AC2526 (GEN) | 5962-9325201VFA | 54FCT257AT (GEN) | 5962-9221103M2A |
| UT54ACTS245PVAH | 5962H9657301VRA | 54AC253DMQB | 5962-8769301EA | 54FCT257AT (GEN) | 5962-9221103MEA |
| UT54ACTS245PVCH | 5962H9657301VRC | 54AC253FMQB | 5962-8769301FA | 54FCT257AT (GEN) | 5962-9221104MFA |
| UT54ACTS245UQAH | 5962H9657301QXA | 54AC253LMQB | 5962-87693012A | 54FCT257CT (GEN) | 5962-9221105M2A |
| UT54ACTS245UQCH | 5962H9657301QXC | 54ACT253DMQB | 5962-8776101EA | 54FCT257CT (GEN) | 5962-9221105MEA |
| UT54ACTS245UVAH | 5962H9657301VXA | 54ACT253FMQB | 5962-8776101FA | 54FCT257CT (GEN) | 5962-9221106MFA |
| UT54ACTS245UVCH | 5962H9657301VXC | 54ACT253LMQB | 5962-87761012A | 54FCT257T (GEN) | 5962-9221101M2A |
| 54ACT245K01Q | 5962-8766303QXC | SL54LS253/BEA | 7601701EA | 54FCT257T (GEN) | 5962-9221101MEA |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

| Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN |
|---|---|---|---|---|---|
| 54FCT257T (GEN) | 5962-9221102MFA | SNJ54ALS259J | 5962-8874101EA | SNJ54HC27W | 8404201DA |
| 54HC257 (GEN) | 5962-8512401VFA | SNJ54ALS259W | 5962-8874101FA | UT54ACS27PQAH | 5962H9652801QCA |
| 54HC257 (GEN) | 8512401FA | SNJ54HC259FK | 85519012A | UT54ACS27PQCH | 5962H9652801QCC |
| 54HC257K01Q | 8512401XC | SNJ54HC259J | 8551901EA | UT54ACS27PVAH | 5962H9652801VCA |
| 54HC257K01V | 5962-8512401VXC | SNJ54HC259W | 8551901FA | UT54ACS27PVCH | 5962H9652801VCC |
| 54HC257K02Q | 8512401XA | SL54LS26/BCA | 7602001CA | UT54ACS27UQAH | 5962H9652801QXA |
| 54HC257K02V | 5962-8512401VXA | SL54LS26/BDA | 7602001DA | UT54ACS27UQCH | 5962H9652801QXC |
| CD54HC257F3A | 8512401EA | SNJ54LS26J | 7602001CA | UT54ACS27UVAH | 5962H9652801VXA |
| CD54HCT257F3A | 5962-8970501EA | SNJ54LS26W | 7602001DA | UT54ACS27UVCH | 5962H9652801VXC |
| IDT54FCT257ATDB | 5962-9221104MEA | SNV54LS26J | 5962-7602001VCA | UT54ACTS27PQAH | 5962H9652901QCA |
| IDT54FCT257ATLB | 5962-9221104M2A | SNV54LS26W | 5962-7602001VDA | UT54ACTS27PQCH | 5962H9652901QCC |
| IDT54FCT257CTDB | 5962-9221106MEA | 54LS261/BEA | 8002601EA | UT54ACTS27PVAH | 5962H9652901VCA |
| IDT54FCT257CTLB | 5962-9221106M2A | 54LS261/BFA | 8002601FA | UT54ACTS27PVCH | 5962H9652901VCC |
| IDT54FCT257TDB | 5962-9221102MEA | UT54ACS264PQAH | 5962H9657601QEA | UT54ACTS27UQAH | 5962H9652901QXA |
| IDT54FCT257TLB | 5962-9221102M2A | UT54ACS264PQCH | 5962H9657601QEC | UT54ACTS27UQCH | 5962H9652901QXC |
| SNJ54ALS257AFK | 85097012A | UT54ACS264PVAH | 5962H9657601VEA | UT54ACTS27UVAH | 5962H9652901VXA |
| SNJ54ALS257AJ | 8509701EA | UT54ACS264PVCH | 5962H9657601VEC | UT54ACTS27UVCH | 5962H9652901VXC |
| SNJ54ALS257AW | 8509701FA | UT54ACS264UQAH | 5962H9657601QXA | 54ABT273 (GEN) | 5962-9321701M2A |
| SNJ54HC257FK | 85124012A | UT54ACS264UQCH | 5962H9657601QXC | 54ABT273 (GEN) | 5962-9321701MRA |
| SNJ54HC257J | 8512401EA | UT54ACS264UVAH | 5962H9657601VXA | 54ABT273 (GEN) | 5962-9321701MSA |
| SNJ54LS257BJ | 7603701EA | UT54ACS264UVCH | 5962H9657601VXC | 54ABT273E-QML | 5962-9321701Q2A |
| SNJ54LS257BW | 7603701FA | UT54ACTS264PQAH | 5962H9657701QEA | 54ABT273J-QML | 5962-9321701QRA |
| SNJ54LVC257AFK | 5962-0050901Q2A | UT54ACTS264PQCH | 5962H9657701QEC | 54ABT273W-QML | 5962-9321701QSA |
| SNJ54LVC257AJ | 5962-0050901QEA | UT54ACTS264PVAH | 5962H9657701VEA | 54AC273 (GEN) | 5962-8775601VSA |
| SNJ54LVC257AW | 5962-0050901QFA | UT54ACTS264PVCH | 5962H9657701VEC | 54AC273DMQB | 5962-8775601RA |
| SNV54LS257BJ | 5962-7603701VEA | UT54ACTS264UQAH | 5962H9657701QXA | 54AC273FMQB | 5962-8775601SA |
| SNV54LS257BW | 5962-7603701VFA | UT54ACTS264UQCH | 5962H9657701QXC | 54AC273K01Q | 5962-8775601XC |
| 54ACT257K01Q | 5962-8968901XC | UT54ACTS264UVAH | 5962H9657701VXA | 54AC273K01V | 5962-8775601VXC |
| 54ACT257K01V | 5962-8968901VXC | UT54ACTS264UVCH | 5962H9657701VXC | 54AC273K02Q | 5962-8775601XA |
| 54ACT257K02Q | 5962-8968901XA | 54HC266 (GEN) | 84043012A | 54AC273K02V | 5962-8775601VXA |
| 54ACT257K02V | 5962-8968901VXA | 54HC266 (GEN) | 8404301AA | 54AC273LMQB | 5962-87756012A |
| 54AC258DMQB | 5962-9160401MEA | 54HC266 (GEN) | 8404301BA | 54AC273WG-QML | 5962-8775601ZA |
| 54AC258FMQB | 5962-9160401MFA | 54HC266 (GEN) | 8404301CA | 54ACTQ273 (GEN) | 5962-8973501V2A |
| 54AC258LMQB | 5962-9160401M2A | 54HC266 (GEN) | 8404301DA | 54ACTQ273 (GEN) | 5962-8973501VRA |
| 54ACT258DMQB | 5962-8870401EA | 54F269 (GEN) | 5962-88627013A | 54ACTQ273 (GEN) | 5962-8973501VSA |
| 54ACT258FMQB | 5962-8870401FA | 54F269 (GEN) | 5962-8862701KA | 54ACTQ273DMQB | 5962-8973501RA |
| 54ACT258LMQB | 5962-88704012A | 54F269 (GEN) | 5962-8862701LA | 54ACTQ273DMQB-R | 5962R8973501RA |
| CD54HCT258F3A | 5962-8970801EA | 54HC27 (GEN) | 5962-8404201VDA | 54ACTQ273ERQMLV | 5962R8973501V2A |
| SL54S258/BEA | 8002301EA | 54HC27 (GEN) | 8404201AA | 54ACTQ273FMQB | 5962-8973501SA |
| SL54S258/BFA | 8002301FA | 54HC27 (GEN) | 8404201BA | 54ACTQ273FMQB-R | 5962R8973501SA |
| SNJ54ALS258AFK | 5962-88626012A | 54HC27K01Q | 8404201XC | 54ACTQ273JRQMLV | 5962R8973501VRA |
| SNJ54ALS258AJ | 5962-8862601EA | 54HC27K01V | 5962-8404201VXC | 54ACTQ273LMQB | 5962-89735012A |
| SNJ54ALS258AW | 5962-8862601FA | 54HC27K02Q | 8404201XA | 54ACTQ273LMQB-R | 5962R89735012A |
| SNJ54LS258BFK | 76038012A | 54HC27K02V | 5962-8404201VXA | 54ACTQ273WRQMLV | 5962R8973501VSA |
| SNJ54LS258BJ | 7603801EA | CD54HC27F3A | 8404201CA | 54F273/DMQB | 5962-8855001RA |
| SNJ54LS258BW | 7603801FA | CD54HCT27F3A | 5962-8970301CA | 54F273/FMQB | 5962-8855001SA |
| SNJ54S258J | 8002301EA | SNJ54ALS27FK | 5962-86838012A | 54F273/LMQB | 5962-88550012A |
| SNJ54S258W | 8002301FA | SNJ54ALS27W | 5962-8683801DA | 54FCT273A (GEN) | 5962-87656022A |
| 54F259 (GEN) | 5962-89723012A | SNJ54F27FK | 5962-89510012A | 54FCT273A (GEN) | 5962-8765602RA |
| 54F259 (GEN) | 5962-8972301EA | SNJ54F27J | 5962-8951001CA | 54FCT273A (GEN) | 5962-8765602SA |
| 54F259 (GEN) | 5962-8972301FA | SNJ54F27W | 5962-8951001DA | 54FCT273AT (GEN) | 5962-9221503MSA |
| CD54HCT259F3A | 5962-8985201EA | SNJ54HC27FK | 84042012A | 54FCT273AT (GEN) | 5962-9221504M2A |
| SNJ54ALS259FK | 5962-88741012A | SNJ54HC27J | 8404201CA | 54FCT273AT (GEN) | 5962-9221504MRA |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART II, Listed By Generic PIN

| Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN |
|---|---|---|---|---|---|
| 54FCT273CT (GEN) | 5962-9221505MSA | UT54ACTS273PVAH | 5962H9657901VRA | SNJ54BCT2827AJT | 5962-9074401MLA |
| 54FCT273CT (GEN) | 5962-9221506M2A | UT54ACTS273PVCH | 5962H9657901VRC | SNJ54BCT2827AW | 5962-9074401MKA |
| 54FCT273CT (GEN) | 5962-9221506MRA | UT54ACTS273UQAH | 5962H9657901QXA | 54BCT2828A (GEN) | 5962-9074501M3A |
| 54FCT273DMQB | 5962-8765601RA | UT54ACTS273UQCH | 5962H9657901QXC | 54BCT2828A (GEN) | 5962-9074501MKA |
| 54FCT273FMQB | 5962-8765601SA | UT54ACTS273UVAH | 5962H9657901VXA | 54BCT2828A (GEN) | 5962-9074501MLA |
| 54FCT273LMQB | 5962-87656012A | UT54ACTS273UVCH | 5962H9657901VXC | 54HC283 (GEN) | 5962-8976501FA |
| 54FCT273T (GEN) | 5962-9221501MSA | CY54FCT273ATDMB | 5962-9221503MRA | 54HC283 (GEN) | 5962-8976501VFA |
| 54FCT273T (GEN) | 5962-9221502M2A | CY54FCT273ATLMB | 5962-9221503M2A | 54HC283K01Q | 5962-8976501XC |
| 54FCT273T (GEN) | 5962-9221502MRA | SNJ54LS279AFK | 76018012A | 54HC283K01V | 5962-8976501VXC |
| 54HC273 (GEN) | 5962-8409901VSA | SNJ54LS279AJ | 7601801EA | 54HC283K02Q | 5962-8976501XA |
| 54HC273K01Q | 8409901XC | SNJ54LS279AW | 7601801FA | 54HC283K02V | 5962-8976501VXA |
| 54HC273K01V | 5962-8409901VXC | UT54ACS279PQAH | 5962H9658001QEA | CD54HC283F3A | 5962-8976501EA |
| 54HC273K02Q | 8409901XA | UT54ACS279PQCH | 5962H9658001QEC | SL54LS283/B2A | 76043012A |
| 54HC273K02V | 5962-8409901VXA | UT54ACS279PVAH | 5962H9658001VEA | SL54LS283/B2C | 76043012C |
| CD54HC273F3A | 8409901RA | UT54ACS279PVCH | 5962H9658001VEC | SL54LS283/BEA | 7604301EA |
| CD54HCT273F3A | 5962-8772501RA | UT54ACS279UQAH | 5962H9658001QXA | SL54LS283/BFA | 7604301FA |
| IDT54FCT273ATDB | 5962-9221503MRA | UT54ACS279UQCH | 5962H9658001QXC | SNJ54F283FK | 5962-9758701Q2A |
| IDT54FCT273ATLB | 5962-9221503M2A | UT54ACS279UVAH | 5962H9658001VXA | SNJ54F283J | 5962-9758701QEA |
| IDT54FCT273CTDB | 5962-9221505MRA | UT54ACS279UVCH | 5962H9658001VXC | SNJ54F283W | 5962-9758701QFA |
| IDT54FCT273CTLB | 5962-9221505M2A | UT54ACTS279PQAH | 5962H9658101QEA | SNJ54LS283FK | 76043012A |
| IDT54FCT273TDB | 5962-9221501MRA | UT54ACTS279PQCH | 5962H9658101QEC | SNJ54LS283J | 7604301EA |
| IDT54FCT273TLB | 5962-9221501M2A | UT54ACTS279PVAH | 5962H9658101VEA | SNJ54LS283W | 7604301FA |
| SL54LS273/B2A | 78010012A | UT54ACTS279PVCH | 5962H9658101VEC | UT54ACS283PQAH | 5962H9658401QEA |
| SL54LS273/B2C | 78010012C | UT54ACTS279UQAH | 5962H9658101QXA | UT54ACS283PQCH | 5962H9658401QEC |
| SL54LS273/BRA | 7801001RA | UT54ACTS279UQCH | 5962H9658101QXC | UT54ACS283PVAH | 5962H9658401VEA |
| SL54LS273/BSA | 7801001SA | UT54ACTS279UVAH | 5962H9658101VXA | UT54ACS283PVCH | 5962H9658401VEC |
| SNJ54ABT273FK | 5962-9321701Q2A | UT54ACTS279UVCH | 5962H9658101VXC | UT54ACS283UQAH | 5962H9658401QXA |
| SNJ54ABT273J | 5962-9321701QRA | 54AC280DMQB | 5962-9220101MCA | UT54ACS283UQCH | 5962H9658401QXC |
| SNJ54ABT273W | 5962-9321701QSA | 54AC280FMQB | 5962-9220101MDA | UT54ACS283UVAH | 5962H9658401VXA |
| SNJ54AHC273FK | 5962-9853001Q2A | 54AC280LMQB | 5962-9220101M2A | UT54ACS283UVCH | 5962H9658401VXC |
| SNJ54AHC273J | 5962-9853001QRA | 54HC280/B2A | 86077012A | UT54ACTS283PQAH | 5962H9658501QEA |
| SNJ54AHC273W | 5962-9853001QSA | CD54HC280F3A | 8607701CA | UT54ACTS283PQCH | 5962H9658501QEC |
| SNJ54ALS273FK | 84136012A | UT54ACS280PQAH | 5962H9658201QCA | UT54ACTS283PVAH | 5962H9658501VEA |
| SNJ54ALS273J | 8413601RA | UT54ACS280PQCH | 5962H9658201QCC | UT54ACTS283PVCH | 5962H9658501VEC |
| SNJ54ALS273W | 8413601SA | UT54ACS280PVAH | 5962H9658201VCA | UT54ACTS283UQAH | 5962H9658501QXA |
| SNJ54HC273FK | 84099012A | UT54ACS280PVCH | 5962H9658201VCC | UT54ACTS283UQCH | 5962H9658501QXC |
| SNJ54HC273J | 8409901RA | UT54ACS280UQAH | 5962H9658201QXA | UT54ACTS283UVAH | 5962H9658501VXA |
| SNJ54HC273W | 8409901SA | UT54ACS280UQCH | 5962H9658201QXC | UT54ACTS283UVCH | 5962H9658501VXC |
| SNJ54LS273FK | 78010012A | UT54ACS280UVAH | 5962H9658201VXA | 54AS286 (GEN) | 5962-89663012A |
| SNJ54LS273J | 7801001RA | UT54ACS280UVCH | 5962H9658201VXC | 54AS286 (GEN) | 5962-8966301CA |
| SNJ54LS273W | 7801001SA | UT54ACTS280PQAH | 5962H9658301QCA | 54AS286 (GEN) | 5962-8966301DA |
| SNV54LS273J | 5962-7801001VRA | UT54ACTS280PQCH | 5962H9658301QCC | 54ABT2952 (GEN) | 5962-9308601M3A |
| SNV54LS273W | 5962-7801001VSA | UT54ACTS280PVAH | 5962H9658301VCA | 54ABT2952 (GEN) | 5962-9308601MKA |
| UT54ACS273PQAH | 5962H9657801QRA | UT54ACTS280PVCH | 5962H9658301VCC | 54ABT2952 (GEN) | 5962-9308601MLA |
| UT54ACS273PQCH | 5962H9657801QRC | UT54ACTS280UQAH | 5962H9658301QXA | SNJ54ABT2952AFK | 5962-9308602Q3A |
| UT54ACS273PVAH | 5962H9657801VRA | UT54ACTS280UQCH | 5962H9658301QXC | SNJ54ABT2952AJT | 5962-9308602QLA |
| UT54ACS273PVCH | 5962H9657801VRC | UT54ACTS280UVAH | 5962H9658301VXA | SNJ54ABT2952AW | 5962-9308602QKA |
| UT54ACS273UQAH | 5962H9657801QXA | UT54ACTS280UVCH | 5962H9658301VXC | CD54HC297F/3A | 5962-8999001EA |
| UT54ACS273UQCH | 5962H9657801QXC | 54AC280K01Q | 5962-9220102QXC | SL54LS298/BEA | 7601901EA |
| UT54ACS273UVAH | 5962H9657801VXA | 54AC280K01V | 5962-9220102VXC | SL54LS298/BFA | 7601901FA |
| UT54ACS273UVCH | 5962H9657801VXC | 54AC280K02Q | 5962-9220102QXA | SNJ54LS298J | 7601901EA |
| UT54ACTS273PQAH | 5962H9657901QRA | 54AC280K02V | 5962-9220102VXA | SNJ54LS298W | 7601901FA |
| UT54ACTS273PQCH | 5962H9657901QRC | SNJ54BCT2827AFK | 5962-9074401M3A | SNJ54ALS29821JT | 5962-9061601LA |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

| Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN |
|---|---|---|---|---|---|
| SNJ54ALS29823FK | 5962-9067501M3A | SNJ54ALS299FK | 83021012A | 54ACTQ32ERQMLV | 5962R8973601V2A |
| SNJ54ALS29823JT | 5962-9067501MLA | SNJ54ALS299J | 8302101RA | 54ACTQ32FMQB | 5962-8973601DA |
| SNJ54ALS29823W | 5962-9067501MKA | SNJ54ALS299W | 8302101SA | 54ACTQ32JRQMLV | 5962R8973601VCA |
| 54ALS29824 (GEN) | 5962-9067502M3A | SNJ54LS299FK | 78024012A | 54ACTQ32LMQB | 5962-89736012A |
| 54ALS29824 (GEN) | 5962-9067502MKA | SNJ54LS299J | 7802401RA | 54ACTQ32WRQMLV | 5962R8973601VDA |
| 54ALS29824 (GEN) | 5962-9067502MLA | SNJ54LS299W | 7802401SA | 54HC32 (GEN) | 8404501AA |
| 54ALS29825 (GEN) | 5962-9069501M3A | MAX543AMJA/883B | 5962-9234501MPA | 54HC32 (GEN) | 8404501BA |
| 54ALS29825 (GEN) | 5962-9069501MKA | MAX543AMLP/883B | 5962-9234501M2C | 54HC32K01Q | 8404501XC |
| 54ALS29825 (GEN) | 5962-9069501MLA | MAX543BMJA/883B | 5962-9234502MPA | 54HC32K01V | 5962-8404501VXC |
| 54ALS29842 (GEN) | 5962-9071001M3A | MAX543BMLP/883B | 5962-9234502M2C | 54HC32K02Q | 8404501XA |
| 54ALS29842 (GEN) | 5962-9071001MKA | 54HC30 (GEN) | 8404001AA | 54HC32K02V | 5962-8404501VXA |
| 54ALS29842 (GEN) | 5962-9071001MLA | 54HC30 (GEN) | 8404001BA | A54SX32 (GEN) | 5962-9958601Q9A |
| 54ALS29843 (GEN) | 5962-9072001M3A | 54HC30/B2A | 84040012A | A54SX32-CQ208B | 5962-9958601QYC |
| 54ALS29843 (GEN) | 5962-9072001MKA | 54HC30/BDA | 8404001DA | A54SX32-CQ256B | 5962-9958601QXC |
| 54ALS29843 (GEN) | 5962-9072001MLA | 54HCT30F3A | 5962-8974601CA | CD54HC32F3A | 8404501CA |
| 54AC299 (GEN) | 5962-8875401VSA | CD54HC30F3A | 8404001CA | CD54HCT32F3A | 5962-8685201CA |
| 54AC299 (GEN) | 5962-8875401VXA | SNJ54ALS30AFK | 5962-86837012A | RHFACT32K01Q | 5962F8973603XC |
| 54AC299 (GEN) | 5962-8875401XA | SNJ54ALS30AW | 5962-8683701DA | RHFACT32K01V | 5962F8973603VXC |
| 54AC299DMQB | 5962-8875401RA | SNJ54AS30FK | 5962-9755801Q2A | RHFACT32K02Q | 5962F8973603XA |
| 54AC299FMQB | 5962-8875401SA | SNJ54AS30J | 5962-9755801QCA | RHFACT32K02V | 5962F8973603VXA |
| 54AC299LMQB | 5962-88754012A | SNJ54F30FK | 5962-88708012A | RT54SX32 (GEN) | 5962-9958603QXC |
| 54ACT299 (GEN) | 5962-8877102VXA | SNJ54F30J | 5962-8870801CA | RT54SX32 (GEN) | 5962-9958603QYC |
| 54ACT299 (GEN) | 5962-8877102XA | SNJ54F30W | 5962-8870801DA | SNJ5432J | 5962-9557401QCA |
| 54ACT299DMQB | 5962-8877101RA | SNJ54S30FK | 5962-9679201Q2A | SNJ5432W | 5962-9557401QDA |
| 54ACT299FMQB | 5962-8877101SA | SNJ54S30J | 5962-9679201QCA | SNJ54AC32FK | 5962-87614012A |
| 54ACT299LMQB | 5962-88771012A | SNJ54S30W | 5962-9679201QDA | SNJ54AC32J | 5962-8761401CA |
| 54F299 (GEN) | 5962-89573012A | 54F30244 (GEN) | 5962-88722013A | SNJ54AC32W | 5962-8761401DA |
| 54F299 (GEN) | 5962-8957301RA | 54F30244 (GEN) | 5962-8872201KA | SNJ54AHC32FK | 5962-9682501Q2A |
| 54F299 (GEN) | 5962-8957301SA | 54F30244 (GEN) | 5962-8872201LA | SNJ54AHC32J | 5962-9682501QCA |
| 54FCT299 (GEN) | 5962-86862012A | 54F30245 (GEN) | 5962-89722013A | SNJ54AHC32W | 5962-9682501QDA |
| 54FCT299 (GEN) | 5962-8686201RA | 54F30245 (GEN) | 5962-8972201KA | SNJ54AHCT32FK | 5962-9682601Q2A |
| 54FCT299 (GEN) | 5962-8686201SA | 54F30245 (GEN) | 5962-8972201LA | SNJ54AHCT32J | 5962-9682601QCA |
| 54FCT299A (GEN) | 5962-86862022A | 54F3037 (GEN) | 5962-90565012A | SNJ54AHCT32W | 5962-9682601QDA |
| 54FCT299A (GEN) | 5962-8686202RA | 54F3037 (GEN) | 5962-9056501EA | SNJ54ALS32FK | 5962-86836012A |
| 54FCT299A (GEN) | 5962-8686202SA | 54F3037 (GEN) | 5962-9056501FA | SNJ54ALS32W | 5962-8683601DA |
| 54FCT299AT (GEN) | 5962-9221603M2A | HCPL-5431 | 5962-8957101PC | SNJ54AS32FK | 5962-9756001Q2A |
| 54FCT299AT (GEN) | 5962-9221603MRA | HCPL-5431#100 | 5962-8957101YA | SNJ54AS32J | 5962-9756001QCA |
| 54FCT299AT (GEN) | 5962-9221604MSA | HCPL-5431#100 | 5962-8957101YC | SNJ54F32FK | 5962-9758801Q2A |
| 54FCT299CT (GEN) | 5962-9221605M2A | HCPL-5431#200 | 5962-8957101PA | SNJ54F32J | 5962-9758801QCA |
| 54FCT299CT (GEN) | 5962-9221605MRA | HCPL-5431#300 | 5962-8957101XA | SNJ54F32W | 5962-9758801QDA |
| 54FCT299CT (GEN) | 5962-9221606MSA | 54AC32 (GEN) | 5962-8761401VDA | SNJ54HC32FK | 84045012A |
| 54FCT299T (GEN) | 5962-9221601M2A | 54AC32DMQB | 5962-8761401CA | SNJ54HC32J | 8404501CA |
| 54FCT299T (GEN) | 5962-9221601MRA | 54AC32FMQB | 5962-8761401DA | SNJ54HC32W | 8404501DA |
| 54FCT299T (GEN) | 5962-9221602MSA | 54AC32K01Q | 5962-8761401XC | SNJ54LVC32AFK | 5962-9761801Q2A |
| 54HC299 (GEN) | 5962-87806012A | 54AC32K01V | 5962-8761401VXC | SNJ54LVC32AJ | 5962-9761801QCA |
| CD54HC299F3A | 5962-8780601RA | 54AC32K02Q | 5962-8761401XA | SNJ54LVC32AW | 5962-9761801QDA |
| CD54HCT299F3A | 5962-8943601MRA | 54AC32K02V | 5962-8761401VXA | SNV54HC32J | 5962-8404501VCA |
| IDT54FCT299ATDB | 5962-9221604MRA | 54AC32LMQB | 5962-87614012A | SNV54HC32W | 5962-8404501VDA |
| IDT54FCT299ATLB | 5962-9221604M2A | 54ACT32K01Q | 5962-8973603XC | A54SX32-1CQ208B | 5962-9958602QYC |
| IDT54FCT299CTDB | 5962-9221606MRA | 54ACT32K01V | 5962-8973603VXC | A54SX32-1CQ256B | 5962-9958602QXC |
| IDT54FCT299CTLB | 5962-9221606M2A | 54ACT32K02Q | 5962-8973603XA | RT54SX32 (GEN) | 5962-9958604QXC |
| IDT54FCT299TDB | 5962-9221602MRA | 54ACT32K02V | 5962-8973603VXA | RT54SX32 (GEN) | 5962-9958604QYC |
| IDT54FCT299TLB | 5962-9221602M2A | 54ACTQ32DMQB | 5962-8973601CA | A54SX32A-1CQ208B | 5962-0151802QYC |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

| Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN |
|---|---|---|---|---|---|
| RT54SX32S-1CQ208B | 5962-0150802QYC | SNJ54CBTD3384W | 5962-9752701QKA | SNJ54HC366FK | 5962-86828012A |
| RT54SX32S-1CQ208E | 5962-0150804QYC | UT54ACS34PQAH | 5962H9653001QCA | SNJ54HC366J | 5962-8682801EA |
| A54SX32A-1CQ256B | 5962-0151802QXC | UT54ACS34PQCH | 5962H9653001QCC | 54367A (GEN) | 5962-9687803QEA |
| RT54SX32S-1CQ256B | 5962-0150802QXC | UT54ACS34PVAH | 5962H9653001VCA | 54367A (GEN) | 5962-9687803QFA |
| RT54SX32S-1CQ256E | 5962-0150804QXC | UT54ACS34PVCH | 5962H9653001VCC | 54F367 (GEN) | 5962-89857012A |
| 54F322 (GEN) | 5962-86074012A | UT54ACS34UQAH | 5962H9653001QXA | 54F367 (GEN) | 5962-8985701EA |
| 54F322 (GEN) | 5962-8607401SA | UT54ACS34UQCH | 5962H9653001QXC | 54F367 (GEN) | 5962-8985701FA |
| 54F322DMQB | 5962-8607401RA | UT54ACS34UVAH | 5962H9653001VXA | 54HC367 (GEN) | 8500201FA |
| A54SX32A-CQ208B | 5962-0151801QYC | UT54ACS34UVCH | 5962H9653001VXC | CD54HCT367F3A | 5962-9070601MEA |
| RT54SX32S-CQ208B | 5962-0150801QYC | UT54ACTS34PQAH | 5962H9653101QCA | SNJ54HC367FK | 85002012A |
| 54ABTH32245PZ | 5962-9557701NXD | UT54ACTS34PQCH | 5962H9653101QCC | SNJ54HC367J | 8500201EA |
| A54SX32A-CQ256B | 5962-0151801QXC | UT54ACTS34PVAH | 5962H9653101VCA | 54368A (GEN) | 5962-9687804QEA |
| RT54SX32S-CQ208E | 5962-0150803QYC | UT54ACTS34PVCH | 5962H9653101VCC | 54368A (GEN) | 5962-9687804QFA |
| RT54SX32S-CQ256B | 5962-0150801QXC | UT54ACTS34UQAH | 5962H9653101QXA | SNJ54HC368FK | 5962-86812012A |
| RT54SX32S-CQ256E | 5962-0150803QXC | UT54ACTS34UQCH | 5962H9653101QXC | SNJ54HC368J | 5962-8681201EA |
| 54ACT323DMQB | 5962-9160701MRA | UT54ACTS34UVAH | 5962H9653101VXA | SN54LS37FK | 5962-9754101Q2A |
| 54ACT323FMQB | 5962-9160701MSA | UT54ACTS34UVCH | 5962H9653101VXC | SN54LS37J | 5962-9754101QCA |
| 54ACT323LMQB | 5962-9160701M2A | SNJ54CDC341FK | 5962-9676101Q2A | SN54LS37W | 5962-9754101QDA |
| SNJ54ALS323FK | 83021022A | SNJ54CDC341J | 5962-9676101QRA | 54ABT373 (GEN) | 5962-9321801M2A |
| SNJ54ALS323J | 8302102RA | SNJ54CDC341W | 5962-9676101QSA | 54ABT373 (GEN) | 5962-9321801MRA |
| SNJ54ALS323W | 8302102SA | 54F350 (GEN) | 5962-86075012A | 54ABT373 (GEN) | 5962-9321801MSA |
| SNJ54ABTH32316HT | 5962-9680801QXA | 54F350 (GEN) | 5962-8607501EA | 54ABT373E-QML | 5962-9321801Q2A |
| 54LVX3245 (GEN) | 5962-9860501QKA | 54F350 (GEN) | 5962-8607501FA | 54ABT373J-QML | 5962-9321801QRA |
| 54LVX3245 (GEN) | 5962-9860501QLA | 54ALS352 (GEN) | 5962-9763201Q2A | 54ABT373W-QML | 5962-9321801QSA |
| 54LVXC3245 (GEN) | 5962-9861901QKA | 54ALS352 (GEN) | 5962-9763201QEA | 54AC373DMQB | 5962-8755501RA |
| 54LVXC3245 (GEN) | 5962-9861901QLA | 54F36 (GEN) | 5962-88709012A | 54AC373FMQB | 5962-8755501SA |
| 54ABTH32501PZ | 5962-9557601NXD | 54F36 (GEN) | 5962-8870901CA | 54AC373K01Q | 5962-8755501XC |
| 54ABTH32543PZ | 5962-9557801NXD | 54F36 (GEN) | 5962-8870901DA | 54AC373K01V | 5962-8755501VXC |
| UT54LVDM328UCA | 5962H0153601QYA | 54ABT3614 (GEN) | 5962-9560901QYA | 54AC373K02Q | 5962-8755501XA |
| UT54LVDM328UCA | 5962H0153601VYA | 54ACT3632 (GEN) | 5962-9562801QYA | 54AC373K02V | 5962-8755501VXA |
| UT54LVDM328UCA | 5962R0153601QYA | 54ACT3641 (GEN) | 5962-9560801QYA | 54AC373LMQB | 5962-87555012A |
| UT54LVDM328UCA | 5962R0153601VYA | 54365 (GEN) | 5962-9687801QEA | 54ACQ373DMQB | 5962-9217801MRA |
| UT54LVDM328UCC | 5962H0153601QYC | 54HC365/BFA | 8500101FA | 54ACQ373FMQB | 5962-9217801MSA |
| UT54LVDM328UCC | 5962H0153601VYC | SNJ54HC365FK | 85001012A | 54ACQ373LMQB | 5962-9217801M2A |
| UT54LVDM328UCC | 5962R0153601QYC | SNJ54HC365J | 8500101EA | 54ACT373DMQB | 5962-8755601RA |
| UT54LVDM328UCC | 5962R0153601VYC | UT54ACS365PQAH | 5962H9658601QEA | 54ACT373FMQB | 5962-8755601SA |
| SL54LS33/B2A | 85126012A | UT54ACS365PQCH | 5962H9658601QEC | 54ACT373K01Q | 5962-8755603XC |
| SL54LS33/B2C | 85126012C | UT54ACS365PVAH | 5962H9658601VEA | 54ACT373K01V | 5962-8755603VXC |
| SL54LS33/BBA | 8512601BA | UT54ACS365PVCH | 5962H9658601VEC | 54ACT373K02Q | 5962-8755603XA |
| SL54LS33/BCA | 8512601CA | UT54ACS365UQAH | 5962H9658601QXA | 54ACT373K02V | 5962-8755603VXA |
| SL54LS33/BDA | 8512601DA | UT54ACS365UQCH | 5962H9658601QXC | 54ACT373LMQB | 5962-87556012A |
| SNJ54LS33FK | 85126012A | UT54ACS365UVAH | 5962H9658601VXA | 54ACTQ373DMQB | 5962-9218801MRA |
| SNJ54LS33J | 8512601CA | UT54ACS365UVCH | 5962H9658601VXC | 54ACTQ373FMQB | 5962-9218801MSA |
| SNJ54LS33W | 8512601DA | UT54ACTS365PQAH | 5962H9658701QEA | 54ACTQ373LMQB | 5962-9218801M2A |
| 54ACT3301 (GEN) | 5962-9862101QFA | UT54ACTS365PQCH | 5962H9658701QEC | 54FCT373A (GEN) | 5962-87644022A |
| 54LVX3383 (GEN) | 5962-9950601QKA | UT54ACTS365PVAH | 5962H9658701VEA | 54FCT373A (GEN) | 5962-8764402RA |
| 54LVX3383 (GEN) | 5962-9950601QLA | UT54ACTS365PVCH | 5962H9658701VEC | 54FCT373A (GEN) | 5962-8764402SA |
| SNJ54CBT3383JT | 5962-9668801QLA | UT54ACTS365UQAH | 5962H9658701QXA | 54FCT373AT (GEN) | 5962-9221702MSA |
| SNJ54CBT3383W | 5962-9668801QKA | UT54ACTS365UQCH | 5962H9658701QXC | 54FCT373AT (GEN) | 5962-9221705M2A |
| 54LVX3384 (GEN) | 5962-9950701QKA | UT54ACTS365UVAH | 5962H9658701VXA | 54FCT373AT (GEN) | 5962-9221705MRA |
| 54LVX3384 (GEN) | 5962-9950701QLA | UT54ACTS365UVCH | 5962H9658701VXC | 54FCT373CT (GEN) | 5962-9221703MSA |
| SNJ54CBTD3384FK | 5962-9752701Q3A | SNJ54366AJ | 5962-9687802QEA | 54FCT373CT (GEN) | 5962-9221706M2A |
| SNJ54CBTD3384JT | 5962-9752701QLA | SNJ54366AW | 5962-9687802QFA | 54FCT373CT (GEN) | 5962-9221706MRA |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART II, Listed By Generic PIN

| Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN |
|---|---|---|---|---|---|
| 54FCT373DMQB | 5962-8764401RA | SNJ54LVTH373W | 5962-9950901QSA | 54ACTQ374LMQB-R | 5962R9218901M2A |
| 54FCT373FMQB | 5962-8764401SA | SNV54AC373J | 5962-8755501VRA | 54ACTQ374WRQMLV | 5962R9218901VSA |
| 54FCT373LMQB | 5962-87644012A | SNV54AC373W | 5962-8755501VSA | 54FCT374A (GEN) | 5962-8762802SA |
| 54FCT373T (GEN) | 5962-9221701MSA | SNV54ACT373J | 5962-8755601VRA | 54FCT374AT (GEN) | 5962-9221803M2A |
| 54FCT373T (GEN) | 5962-9221704M2A | SNV54ACT373W | 5962-8755601VSA | 54FCT374AT (GEN) | 5962-9221803MRA |
| 54FCT373T (GEN) | 5962-9221704MRA | SNV54HC373J | 5962-8407201VRA | 54FCT374AT (GEN) | 5962-9221804MSA |
| 54HC373K01Q | 8407201XC | SNV54HC373W | 5962-8407201VSA | 54FCT374CT (GEN) | 5962-9221805M2A |
| 54HC373K01V | 5962-8407201VXC | SNV54HCT373J | 5962-8686701VRA | 54FCT374CT (GEN) | 5962-9221805MRA |
| 54HC373K02Q | 8407201XA | SNV54HCT373W | 5962-8686701VSA | 54FCT374CT (GEN) | 5962-9221806MSA |
| 54HC373K02V | 5962-8407201VXA | UT54ACS373PQAH | 5962H9658801QRA | 54FCT374DMQB | 5962-8762801RA |
| 54HCT373 (GEN) | 5962-8686701SA | UT54ACS373PQCH | 5962H9658801QRC | 54FCT374FMQB | 5962-8762801SA |
| CD54HC373F3A | 8407201RA | UT54ACS373PVAH | 5962H9658801VRA | 54FCT374LMQB | 5962-87628012A |
| CY54FCT373TDMB | 5962-9221701MRA | UT54ACS373PVCH | 5962H9658801VRC | 54FCT374T (GEN) | 5962-9221801M2A |
| IDT54FCT373ATDB | 5962-9221702MRA | UT54ACS373UQAH | 5962H9658801QXA | 54FCT374T (GEN) | 5962-9221801MRA |
| IDT54FCT373ATLB | 5962-9221702M2A | UT54ACS373UQCH | 5962H9658801QXC | 54FCT374T (GEN) | 5962-9221802MSA |
| IDT54FCT373CTDB | 5962-9221703MRA | UT54ACS373UVAH | 5962H9658801VXA | 54HC374K01Q | 8407101XC |
| IDT54FCT373CTLB | 5962-9221703M2A | UT54ACS373UVCH | 5962H9658801VXC | 54HC374K01V | 5962-8407101VXC |
| IDT54FCT373TDB | 5962-9221701MRA | UT54ACTS373PQAH | 5962H9658901QRA | 54HC374K02Q | 8407101XA |
| IDT54FCT373TLB | 5962-9221701M2A | UT54ACTS373PQCH | 5962H9658901QRC | 54HC374K02V | 5962-8407101VXA |
| SNJ54ABT373FK | 5962-9321801Q2A | UT54ACTS373PVAH | 5962H9658901VRA | CD54HCT374F3A | 8550701RA |
| SNJ54ABT373J | 5962-9321801QRA | UT54ACTS373PVCH | 5962H9658901VRC | CY54FCT374TDMB | 5962-9221802MRA |
| SNJ54ABT373W | 5962-9321801QSA | UT54ACTS373UQAH | 5962H9658901QXA | CY54FCT374TLMB | 5962-9221802M2A |
| SNJ54AC373FK | 5962-87555012A | UT54ACTS373UQCH | 5962H9658901QXC | IDT54FCT374A | 5962-87628022A |
| SNJ54AC373J | 5962-8755501RA | UT54ACTS373UVAH | 5962H9658901VXA | IDT54FCT374ADB | 5962-8762802RA |
| SNJ54AC373W | 5962-8755501SA | UT54ACTS373UVCH | 5962H9658901VXC | IDT54FCT374ATDB | 5962-9221804MRA |
| SNJ54ACT373FK | 5962-87556012A | CY54FCT373ATDMB | 5962-9221702MRA | IDT54FCT374ATLB | 5962-9221804M2A |
| SNJ54ACT373J | 5962-8755601RA | CY54FCT373CTLMB | 5962-9221703M2A | IDT54FCT374CTDB | 5962-9221806MRA |
| SNJ54ACT373W | 5962-8755601SA | 54ABT374 (GEN) | 5962-9314901M2A | IDT54FCT374CTLB | 5962-9221806M2A |
| SNJ54AHC373FK | 5962-9686601Q2A | 54ABT374 (GEN) | 5962-9314901MRA | IDT54FCT374DB | 5962-8762801RA |
| SNJ54AHC373J | 5962-9686601QRA | 54ABT374 (GEN) | 5962-9314901MSA | IDT54FCT374LB | 5962-87628012A |
| SNJ54AHC373W | 5962-9686601QSA | 54ABT374E-QML | 5962-9314901Q2A | IDT54FCT374TDB | 5962-9221802MRA |
| SNJ54AHCT373FK | 5962-9686701Q2A | 54ABT374J-QML | 5962-9314901QRA | IDT54FCT374TLB | 5962-9221802M2A |
| SNJ54AHCT373J | 5962-9686701QRA | 54ABT374W-QML | 5962-9314901QSA | SL54LS374/B2A | 78011012A |
| SNJ54AHCT373W | 5962-9686701QSA | 54AC374DMQB | 5962-8769401RA | SL54LS374/B2C | 78011012C |
| SNJ54ALS373AFK | 83020012A | 54AC374FMQB | 5962-8769401SA | SL54LS374/BRA | 7801101RA |
| SNJ54ALS373AJ | 8302001RA | 54AC374K01Q | 5962-8769401XC | SL54LS374/BSA | 7801101SA |
| SNJ54ALS373AW | 8302001SA | 54AC374K01V | 5962-8769401VXC | SNJ54ABT374FK | 5962-9314901Q2A |
| SNJ54BCT373FK | 5962-9074601M2A | 54AC374K02Q | 5962-8769401XA | SNJ54ABT374J | 5962-9314901QRA |
| SNJ54BCT373J | 5962-9074601MRA | 54AC374K02V | 5962-8769401VXA | SNJ54ABT374W | 5962-9314901QSA |
| SNJ54BCT373W | 5962-9074601MSA | 54AC374LMQB | 5962-87694012A | SNJ54AC374FK | 5962-87694012A |
| SNJ54F373FK | 5962-9758901Q2A | 54ACQ374DMQB | 5962-9217901MRA | SNJ54AC374J | 5962-8769401RA |
| SNJ54F373J | 5962-9758901QRA | 54ACQ374FMQB | 5962-9217901MSA | SNJ54AC374W | 5962-8769401SA |
| SNJ54F373W | 5962-9758901QSA | 54ACQ374LMQB | 5962-9217901M2A | SNJ54ACT374FK | 5962-87631012A |
| SNJ54HC373FK | 84072012A | 54ACT374DMQB | 5962-8763101RA | SNJ54ACT374J | 5962-8763101RA |
| SNJ54HC373J | 8407201RA | 54ACT374FMQB | 5962-8763101SA | SNJ54ACT374W | 5962-8763101SA |
| SNJ54HC373W | 8407201SA | 54ACT374LMQB | 5962-87631012A | SNJ54AHC374FK | 5962-9686401Q2A |
| SNJ54HCT373FK | 5962-86867012A | 54ACTQ374DMQB | 5962-9218901MRA | SNJ54AHC374J | 5962-9686401QRA |
| SNJ54HCT373J | 5962-8686701RA | 54ACTQ374DMQB-R | 5962R9218901MRA | SNJ54AHC374W | 5962-9686401QSA |
| SNJ54LVC373AFK | 5962-9757301Q2A | 54ACTQ374ERQMLV | 5962R9218901V2A | SNJ54AHCT374FK | 5962-9686501Q2A |
| SNJ54LVC373AJ | 5962-9757301QRA | 54ACTQ374FMQB | 5962-9218901MSA | SNJ54AHCT374J | 5962-9686501QRA |
| SNJ54LVC373AW | 5962-9757301QSA | 54ACTQ374FMQB-R | 5962R9218901MSA | SNJ54AHCT374W | 5962-9686501QSA |
| SNJ54LVTH373FK | 5962-9950901Q2A | 54ACTQ374JRQMLV | 5962R9218901VRA | SNJ54ALS374AFK | 83020022A |
| SNJ54LVTH373J | 5962-9950901QRA | 54ACTQ374LMQB | 5962-9218901M2A | SNJ54ALS374AJ | 8302002RA |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART II, Listed By Generic PIN

| Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN |
|---|---|---|---|---|---|
| SNJ54ALS374AW | 8302002SA | UT54ACTS374UVCH | 5962H9659101VXC | IDT54FCT377TLB | 5962-9221901M2A |
| SNJ54AS374FK | 5962-9756201Q2A | 54ACT374K01Q | 5962-8763103XC | JM54ACT377BRA | 5962-8769701BRA |
| SNJ54AS374J | 5962-9756201QRA | 54ACT374K01V | 5962-8763103VXC | JM54ACT377BSA | 5962-8769701BSA |
| SNJ54AS374W | 5962-9756201QSA | 54ACT374K02Q | 5962-8763103XA | JM54ACT377SRA | 5962-8769701SRA |
| SNJ54BCT374FK | 5962-9051601M2A | 54ACT374K02V | 5962-8763103VXA | JM54ACT377SSA | 5962-8769701SSA |
| SNJ54BCT374J | 5962-9051601MRA | CY54FCT374ATDMB | 5962-9221804MRA | SNJ54ABT377FK | 5962-9314801Q2A |
| SNJ54BCT374W | 5962-9051601MSA | CY54FCT374ATLMB | 5962-9221804M2A | SNJ54ABT377J | 5962-9314801QRA |
| SNJ54F374FK | 5962-9759001Q2A | CY54FCT374CTDMB | 5962-9221806MRA | SNJ54ABT377W | 5962-9314801QSA |
| SNJ54F374J | 5962-9759001QRA | CY54FCT374CTLMB | 5962-9221806M2A | SNJ54HC377FK | 5962-87807012A |
| SNJ54F374W | 5962-9759001QSA | 54ABT377 (GEN) | 5962-9314801M2A | SNJ54HC377J | 5962-8780701RA |
| SNJ54HC374FK | 84071012A | 54ABT377 (GEN) | 5962-9314801MRA | 54ACT377 (GEN) | 5962-8769701S2A |
| SNJ54HC374J | 8407101RA | 54ABT377 (GEN) | 5962-9314801MSA | JM54ACT377B2A | 5962-8769701B2A |
| SNJ54HC374W | 8407101SA | 54ABT377E-QML | 5962-9314801Q2A | 54AC378 (GEN) | 5962-9160501M2A |
| SNJ54HCT374FK | 85507012A | 54ABT377J-QML | 5962-9314801QRA | 54AC378 (GEN) | 5962-9160501MEA |
| SNJ54HCT374J | 8550701RA | 54ABT377W-QML | 5962-9314801QSA | 54AC378 (GEN) | 5962-9160501MFA |
| SNJ54LS374FK | 78011022A | 54AC377DMQB | 5962-8870201RA | 54F378 (GEN) | 5962-88555012A |
| SNJ54LS374J | 7801102RA | 54AC377FMQB | 5962-8870201SA | 54F378DMQB | 5962-8855501EA |
| SNJ54LS374W | 7801102SA | 54AC377LMQB | 5962-88702012A | 54F378FMQB | 5962-8855501FA |
| SNJ54LVC374AFK | 5962-9757401Q2A | 54ACT377 (GEN) | 5962-87697012A | SL54LS378/B2A | 5962-89925012A |
| SNJ54LVC374AJ | 5962-9757401QRA | 54ACT377 (GEN) | 5962-8769701RA | SL54LS378/B2C | 5962-89925012C |
| SNJ54LVC374AW | 5962-9757401QSA | 54ACT377 (GEN) | 5962-8769701SA | SL54LS378/BEA | 5962-8992501EA |
| SNJ54LVTH374FK | 5962-9951001Q2A | 54ACT377DMQB | 5962-8769701MRA | SL54LS378/BFA | 5962-8992501FA |
| SNJ54LVTH374J | 5962-9951001QRA | 54ACT377FMQB | 5962-8769701MSA | SNJ54LS378FK | 5962-89925012A |
| SNJ54LVTH374W | 5962-9951001QSA | 54ACT377LMQB | 5962-8769701M2A | SNJ54LS378J | 5962-8992501EA |
| SNV54AC374J | 5962-8769401VRA | 54ACTQ377DMQB | 5962-9219001MRA | SNJ54LS378W | 5962-8992501FA |
| SNV54AC374W | 5962-8769401VSA | 54ACTQ377FMQB | 5962-9219001MSA | 54ALS38B (GEN) | 5962-8687101BA |
| SNV54ACT374J | 5962-8763101VRA | 54ACTQ377LMQB | 5962-9219001M2A | 54F38 (GEN) | 5962-86872012A |
| SNV54ACT374W | 5962-8763101VSA | 54F377DMQB | 5962-9091001MRA | 54F38 (GEN) | 5962-8687201CA |
| SNV54HC374J | 5962-8407101VRA | 54F377FMQB | 5962-9091001MSA | 54F38 (GEN) | 5962-8687201DA |
| SNV54HC374W | 5962-8407101VSA | 54F377LMQB | 5962-9091001M2A | SNJ54ALS38BFK | 5962-86871012A |
| SNV54HCT374J | 5962-8550701VRA | 54FCT377A (GEN) | 5962-87627022A | SNJ54ALS38BJ | 5962-8687101CA |
| SNV54HCT374W | 5962-8550701VSA | 54FCT377A (GEN) | 5962-8762702RA | SNJ54ALS38BW | 5962-8687101DA |
| SNV54LS374J | 5962-7801102VRA | 54FCT377A (GEN) | 5962-8762702SA | 54F381 (GEN) | 5962-86710012A |
| SNV54LS374W | 5962-7801102VSA | 54FCT377AT (GEN) | 5962-9221902MSA | 54F381 (GEN) | 5962-8671001RA |
| SNV54LVC374AJ | 5962-9757401VRA | 54FCT377AT (GEN) | 5962-9221905M2A | 54F381 (GEN) | 5962-8671001SA |
| SNV54LVC374AW | 5962-9757401VSA | 54FCT377AT (GEN) | 5962-9221905MRA | 54HC390/B2A | 86009012A |
| UT54ACS374PQAH | 5962H9659001QRA | 54FCT377CT (GEN) | 5962-9221903MSA | 54HC390/BEA | 8600901EA |
| UT54ACS374PQCH | 5962H9659001QRC | 54FCT377CT (GEN) | 5962-9221906M2A | CD54HCT390F3A | 5962-9098401MEA |
| UT54ACS374PVAH | 5962H9659001VRA | 54FCT377CT (GEN) | 5962-9221906MRA | SNJ54LS390J | 7802601EA |
| UT54ACS374PVCH | 5962H9659001VRC | 54FCT377DMQB | 5962-8762701RA | SNJ54LS390W | 7802601FA |
| UT54ACS374-QDIE | 5962H9659001Q9A | 54FCT377FMQB | 5962-8762701SA | 54HC393 (GEN) | 8410001BA |
| UT54ACS374UQAH | 5962H9659001QXA | 54FCT377LMQB | 5962-87627012A | CD54HC393F3A | 8410001CA |
| UT54ACS374UQCH | 5962H9659001QXC | 54FCT377T (GEN) | 5962-9221901MSA | CD54HCT393F3A | 5962-8989001CA |
| UT54ACS374UVAH | 5962H9659001VXA | 54FCT377T (GEN) | 5962-9221904M2A | SNJ54HC393FK | 84100012A |
| UT54ACS374UVCH | 5962H9659001VXC | 54FCT377T (GEN) | 5962-9221904MRA | SNJ54HC393J | 8410001CA |
| UT54ACS374-VDIE | 5962H9659001V9A | CD54HCT377F3A | 5962-8976901RA | SNJ54HC393W | 8410001DA |
| UT54ACTS374PQAH | 5962H9659101QRA | CY54FCT377ATLMB | 5962-9221902M2A | SNJ54LS396FK | 5962-90503012A |
| UT54ACTS374PQCH | 5962H9659101QRC | CY54FCT377CTLMB | 5962-9221903M2A | SNJ54LS396J | 5962-9050301EA |
| UT54ACTS374PVAH | 5962H9659101VRA | IDT54FCT377ATDB | 5962-9221902MRA | 54ACT399 (GEN) | 5962-9093401M2A |
| UT54ACTS374PVCH | 5962H9659101VRC | IDT54FCT377ATLB | 5962-9221902M2A | 54ACT399 (GEN) | 5962-9093401MEA |
| UT54ACTS374UQAH | 5962H9659101QXA | IDT54FCT377CTDB | 5962-9221903MRA | 54ACT399 (GEN) | 5962-9093401MFA |
| UT54ACTS374UQCH | 5962H9659101QXC | IDT54FCT377CTLB | 5962-9221903M2A | 54ACT399DMQB | 5962-9093401QEA |
| UT54ACTS374UVAH | 5962H9659101VXA | IDT54FCT377TDB | 5962-9221901MRA | 54ACT399DMQB-RH | 5962R9093401QEA |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

| Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN |
|---|---|---|---|---|---|
| 54ACT399ERQMLV | 5962R9093401V2A | UT54ACTS4002PVCH | 5962H9659701VCC | CD54HC4053F3A | 5962-8775401EA |
| 54ACT399FMQB | 5962-9093401QFA | UT54ACTS4002UQAH | 5962H9659701QXA | 54HCT4059 (GEN) | 5962-8862401JA |
| 54ACT399FMQB-RH | 5962R9093401QFA | UT54ACTS4002UQCH | 5962H9659701QXC | CD54HC4059BF3A | 5962-8944501JA |
| 54ACT399JRQMLV | 5962R9093401VEA | UT54ACTS4002UVAH | 5962H9659701VXA | 54HC4060 (GEN) | 5962-87680012A |
| 54ACT399LMQB | 5962-9093401Q2A | UT54ACTS4002UVCH | 5962H9659601VXC | CD54HC4060F3A | 5962-8768001EA |
| 54ACT399LMQB-RH | 5962R9093401Q2A | CD54HCT40102BF3A | 5962-9057401EA | CD54HCT4060F3A | 5962-8977101EA |
| 54ACT399WRQMLV | 5962R9093401VFA | CD54HC40103F3A | 5962-9055301EA | 54HC4066/B2A | 5962-89507012A |
| 54FCT399 (GEN) | 5962-89652012A | CD54HC4015F3A | 5962-8995301EA | CD54HC4066F3A | 5962-8950701CA |
| 54FCT399 (GEN) | 5962-8965201EA | 54HC4016 (GEN) | 5962-88758012A | 54HC4075 (GEN) | 5962-87722012A |
| 54FCT399 (GEN) | 5962-8965201FA | 54HC4016 (GEN) | 5962-8875801CA | 54HC4075 (GEN) | 5962-8772201DA |
| 54FCT399A (GEN) | 5962-89652022A | 54HC4017 (GEN) | 86011012A | CD54HC4075BF3A | 5962-8772201CA |
| 54FCT399A (GEN) | 5962-8965202EA | 54HCT4017 (GEN) | 5962-9059701MEA | 54HC4078 (GEN) | 5962-88574012A |
| 54FCT399A (GEN) | 5962-8965202FA | CD54HC4017F3A | 8601101EA | 54HC4078 (GEN) | 5962-8857401CA |
| 54FCT399AT (GEN) | 5962-9221203M2A | 54F402 (GEN) | 5962-9059301M2A | 54HC42 (GEN) | 5962-8682101FA |
| 54FCT399AT (GEN) | 5962-9221203MEA | 54F402 (GEN) | 5962-9059301MEA | 54LS42 (GEN) | 76031012A |
| 54FCT399AT (GEN) | 5962-9221204M2A | 54F402 (GEN) | 5962-9059301MFA | 54LS42 (GEN) | 7603101EA |
| 54FCT399AT (GEN) | 5962-9221204MEA | CD54HCT4020F3A | 5962-8945801EA | 54LS42 (GEN) | 7603101FA |
| 54FCT399AT (GEN) | 5962-9221204MFA | SNJ54HC4020FK | 85003012A | SNJ54HC42FK | 5962-86821012A |
| 54FCT399CT (GEN) | 5962-9221205M2A | SNJ54HC4020J | 8500301EA | SNJ54HC42J | 5962-8682101EA |
| 54FCT399CT (GEN) | 5962-9221205MEA | SNJ54HC4020W | 8500301FA | 54HC423A (GEN) | 5962-8949201EA |
| 54FCT399CT (GEN) | 5962-9221206M2A | SNJ54HC4024FK | 86012012A | 54LVX4245 (GEN) | 5962-9860601QKA |
| 54FCT399CT (GEN) | 5962-9221206MEA | SNJ54HC4024J | 8601201CA | 54LVX4245 (GEN) | 5962-9860601QLA |
| 54FCT399CT (GEN) | 5962-9221206MFA | 54HC4040 (GEN) | 5962-8500401VFA | 54LVXC4245 (GEN) | 5962-9862001QKA |
| 54FCT399T (GEN) | 5962-9221201M2A | 54HC4040K01Q | 8500401XC | 54LVXC4245 (GEN) | 5962-9862001QLA |
| 54FCT399T (GEN) | 5962-9221201MEA | 54HC4040K01V | 5962-8500401VXC | 54F432 (GEN) | 5962-90585013A |
| 54FCT399T (GEN) | 5962-9221202M2A | 54HC4040K02Q | 8500401XA | 54F432 (GEN) | 5962-9058501KA |
| 54FCT399T (GEN) | 5962-9221202MEA | 54HC4040K02V | 5962-8500401VXA | 54F432 (GEN) | 5962-9058501LA |
| 54FCT399T (GEN) | 5962-9221202MFA | CD54HC4040F3A | 8500401EA | 54LS442 (GEN) | 5962-9166101M2A |
| SNJ54LS399FK | 84154012A | CD54HCT4040F3A | 5962-8994701MEA | 54LS442 (GEN) | 5962-9166101MRA |
| SNJ54LS399J | 8415401EA | SNJ54HC4040FK | 85004012A | 54LS442 (GEN) | 5962-9166101MSA |
| SNJ54LS399W | 8415401FA | SNJ54HC4040J | 8500401EA | 54HC4511 (GEN) | 5962-87733012A |
| HCPL-543K | 5962-8957103KPC | SNJ54HC4040W | 8500401FA | CD54HC4511F3A | 5962-8773301EA |
| HCPL-543K#100 | 5962-8957103KYA | CD54HC4046AF3A | 5962-8960901EA | CD54HC4520F3A | 5962-8995401EA |
| HCPL-543K#100 | 5962-8957103KYC | CD54HCT4046AF3A | 5962-8875701EA | 54HC4538 (GEN) | 5962-86886012A |
| HCPL-543K#200 | 5962-8957103KPA | 54HC4049 (GEN) | 5962-86819012A | CD54HC4538F3A | 5962-8688601EA |
| HCPL-543K#300 | 5962-8957103KXA | 54HC4049 (GEN) | 5962-8681901FA | SNJ5447AJ | 5962-9856401QEA |
| 54HC4002 (GEN) | 8404401AA | 54HC4049 (GEN) | 5962-8681901VFA | SNJ5447AW | 5962-9856401QFA |
| 54HC4002 (GEN) | 8404401BA | 54HC4049K01Q | 5962-8681901XC | SNJ54LS47J | 7604501EA |
| CD54HC4002F3A | 8404401CA | 54HC4049K01V | 5962-8681901VXC | SNJ54LS47W | 7604501FA |
| SNJ54HC4002FK | 84044012A | 54HC4049K02Q | 5962-8681901XA | 54FCT480 (GEN) | 5962-9079801MLA |
| SNJ54HC4002J | 8404401CA | 54HC4049K02V | 5962-8681901VXA | 54FCT480 (GEN) | 5962-9079803MLA |
| SNJ54HC4002W | 8404401DA | CD54HC4049F3A | 5962-8681901EA | 54FCT480A (GEN) | 5962-9079802MLA |
| UT54ACS4002PQAH | 5962H9659601QCA | 54HC4050 (GEN) | 5962-86820012A | DM54LS502 (GEN) | 5962-9080001MFA |
| UT54ACS4002PQCH | 5962H9659601QCC | 54HC4050 (GEN) | 5962-8682001FA | DM54LS502J/883 | 5962-9080001MEA |
| UT54ACS4002PVAH | 5962H9659601VCA | 54HC4050 (GEN) | 5962-8682001VFA | 54F51 (GEN) | 5962-88774012A |
| UT54ACS4002PVCH | 5962H9659601VCC | 54HC4050K01Q | 5962-8682001XC | 54F51 (GEN) | 5962-8877401CA |
| UT54ACS4002UQAH | 5962H9659601QXA | 54HC4050K01V | 5962-8682001VXC | 54F51 (GEN) | 5962-8877401DA |
| UT54ACS4002UQCH | 5962H9659601QXC | 54HC4050K02Q | 5962-8682001XA | 54HC51/B2A | 5962-9151301M2A |
| UT54ACS4002UVAH | 5962H9659601VXA | 54HC4050K02V | 5962-8682001VXA | 54HC51/BCA | 5962-9151301MCA |
| UT54ACS4002UVCH | 5962H9659601VXC | CD54HC4050F3A | 5962-8682001EA | 54F518 (GEN) | 5962-88710012A |
| UT54ACTS4002PQAH | 5962H9659701QCA | CD54HCT4051F3A | 5962-9065401MEA | 54F518 (GEN) | 5962-8871001RA |
| UT54ACTS4002PQCH | 5962H9659701QCC | CD54HCT4052F3A | 5962-9163001MEA | 54F518 (GEN) | 5962-8871001SA |
| UT54ACTS4002PVAH | 5962H9659701VCA | CD54HC4052F3A | 5962-8855601EA | 54F519 (GEN) | 5962-88711012A |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

| Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN |
|---|---|---|---|---|---|
| 54F519 (GEN) | 5962-8871101RA | IDT54FCT521ALB | 5962-88543022A | 54FCT534CT (GEN) | 5962-9223603MRA |
| 54F519 (GEN) | 5962-8871101SA | IDT54FCT521ATDB | 5962-9223404MRA | 54FCT534CT (GEN) | 5962-9223603MSA |
| 54AC520 (GEN) | 5962-9091601B2A | IDT54FCT521ATLB | 5962-9223404M2A | 54FCT534CT (GEN) | 5962-9223606M2A |
| 54AC520 (GEN) | 5962-9091601BRA | IDT54FCT521BDB | 5962-8854303RA | 54FCT534CT (GEN) | 5962-9223606MRA |
| 54AC520 (GEN) | 5962-9091601S2A | IDT54FCT521BLB | 5962-88543032A | 54FCT534T (GEN) | 5962-9223601M2A |
| 54AC520 (GEN) | 5962-9091601SRA | IDT54FCT521BTDB | 5962-9223406MRA | 54FCT534T (GEN) | 5962-9223601MRA |
| 54AC520 (GEN) | 5962-9091601SSA | IDT54FCT521BTLB | 5962-9223406M2A | 54FCT534T (GEN) | 5962-9223601MSA |
| 54AC520DMQB | 5962-9091601MRA | IDT54FCT521CTDB | 5962-9223408MRA | 54FCT534T (GEN) | 5962-9223604M2A |
| 54AC520FMQB | 5962-9091601MSA | IDT54FCT521CTLB | 5962-9223408M2A | 54FCT534T (GEN) | 5962-9223604MRA |
| 54AC520LMQB | 5962-9091601M2A | IDT54FCT521DB | 5962-8854301RA | 54HC534/B2A | 5962-86814012A |
| 54ACT520DMQB | 5962-8979301RA | IDT54FCT521LB | 5962-88543012A | CD54HC534F3A | 5962-8681401RA |
| 54ACT520FMQB | 5962-8979301SA | IDT54FCT521TDB | 5962-9223402MRA | CD54HCT534F3A | 5962-8984901RA |
| 54ACT520LMQB | 5962-89793012A | IDT54FCT521TLB | 5962-9223402M2A | SNJ54ABT534FK | 5962-9314701Q2A |
| 54F520 (GEN) | 5962-88712012A | JM54AC521B2A | 5962-9098501B2A | SNJ54ABT534J | 5962-9314701QRA |
| 54F520 (GEN) | 5962-8871201RA | JM54AC521B2A-RH | 5962R9098501B2A | SNJ54ABT534W | 5962-9314701QSA |
| 54F520 (GEN) | 5962-8871201SA | JM54AC521BRA-RH | 5962R9098501BRA | SNJ54ALS534AFK | 5962-88668012A |
| JM54AC520B2A-RH | 5962R9091601B2A | JM54AC521BSA | 5962-9098501BSA | SNJ54ALS534AJ | 5962-8866801RA |
| JM54AC520BRA-RH | 5962R9091601BRA | JM54AC521BSA-RH | 5962R9098501BSA | SNJ54ALS534AW | 5962-8866801SA |
| JM54AC520BSA | 5962-9091601BSA | JM54AC521S2A-RH | 5962R9098501S2A | UT54ACS54PQAH | 5962H9653201QCA |
| JM54AC520BSA-RH | 5962R9091601BSA | JM54AC521SRA-RH | 5962R9098501SRA | UT54ACS54PQCH | 5962H9653201QCC |
| JM54AC520S2A-RH | 5962R9091601S2A | JM54AC521SSA-RH | 5962R9098501SSA | UT54ACS54PVAH | 5962H9653201VCA |
| JM54AC520SRA-RH | 5962R9091601SRA | SNJ54F521FK | 5962-9759101Q2A | UT54ACS54PVCH | 5962H9653201VCC |
| JM54AC520SSA-RH | 5962R9091601SSA | SNJ54F521J | 5962-9759101QRA | UT54ACS54UQAH | 5962H9653201QXA |
| SNJ54ALS520FK | 5962-88691012A | SNJ54F521W | 5962-9759101QSA | UT54ACS54UQCH | 5962H9653201QXC |
| SNJ54ALS520J | 5962-8869101RA | 54FCT533 (GEN) | 5962-8865101SA | UT54ACS54UVAH | 5962H9653201VXA |
| 54AC521 (GEN) | 5962-9098501BRA | 54FCT533 (GEN) | 5962-88651022A | UT54ACS54UVCH | 5962H9653201VXC |
| 54AC521 (GEN) | 5962-9098501S2A | 54FCT533 (GEN) | 5962-8865102RA | UT54ACTS54PQAH | 5962H9653301QCA |
| 54AC521 (GEN) | 5962-9098501SRA | 54FCT533 (GEN) | 5962-8865102SA | UT54ACTS54PQCH | 5962H9653301QCC |
| 54AC521 (GEN) | 5962-9098501SSA | 54FCT533DMQB | 5962-8865101RA | UT54ACTS54PVAH | 5962H9653301VCA |
| 54AC521DMQB | 5962-9098501MRA | 54FCT533LMQB | 5962-88651012A | UT54ACTS54PVCH | 5962H9653301VCC |
| 54AC521FMQB | 5962-9098501MSA | 54HC533 (GEN) | 5962-86813012A | UT54ACTS54UQAH | 5962H9653301QXA |
| 54AC521LMQB | 5962-9098501M2A | CD54HC533F3A | 5962-8681301RA | UT54ACTS54UQCH | 5962H9653301QXC |
| 54ACT521DMQB | 5962-8979302RA | SNJ54ABT533FK | 5962-9584301Q2A | UT54ACTS54UVAH | 5962H9653301VXA |
| 54ACT521FMQB | 5962-8979302SA | SNJ54ABT533J | 5962-9584301QRA | UT54ACTS54UVCH | 5962H9653301VXC |
| 54ACT521LMQB | 5962-89793022A | SNJ54ABT533W | 5962-9584301QSA | 54AC540DMQB | 5962-8769501RA |
| 54FCT521A (GEN) | 5962-8854302SA | 54ACT534DMQB | 5962-8965801RA | 54AC540FMQB | 5962-8769501SA |
| 54FCT521AT (GEN) | 5962-9223403M2A | 54ACT534FMQB | 5962-8965801SA | 54AC540LMQB | 5962-87695012A |
| 54FCT521AT (GEN) | 5962-9223403MRA | 54ACT534LMQB | 5962-89658012A | 54FCT540 (GEN) | 5962-8976701SA |
| 54FCT521AT (GEN) | 5962-9223404MSA | 54BCT534 (GEN) | 5962-9074701M2A | 54FCT540A (GEN) | 5962-89767022A |
| 54FCT521B (GEN) | 5962-8854303SA | 54BCT534 (GEN) | 5962-9074701MRA | 54FCT540A (GEN) | 5962-8976702RA |
| 54FCT521BT (GEN) | 5962-9223405M2A | 54BCT534 (GEN) | 5962-9074701MSA | 54FCT540A (GEN) | 5962-8976702SA |
| 54FCT521BT (GEN) | 5962-9223405MRA | 54FCT534 (GEN) | 5962-88655012A | 54FCT540AT (GEN) | 5962-9222003M2A |
| 54FCT521BT (GEN) | 5962-9223406MSA | 54FCT534 (GEN) | 5962-8865501RA | 54FCT540AT (GEN) | 5962-9222003MRA |
| 54FCT521CT (GEN) | 5962-9223407M2A | 54FCT534 (GEN) | 5962-8865501SA | 54FCT540AT (GEN) | 5962-9222004M2A |
| 54FCT521CT (GEN) | 5962-9223407MRA | 54FCT534A (GEN) | 5962-88655022A | 54FCT540AT (GEN) | 5962-9222004MRA |
| 54FCT521CT (GEN) | 5962-9223408MSA | 54FCT534A (GEN) | 5962-8865502RA | 54FCT540AT (GEN) | 5962-9222004MSA |
| 54FCT521DMQB | 5962-8854301RA | 54FCT534A (GEN) | 5962-8865502SA | 54FCT540CT (GEN) | 5962-9222005M2A |
| 54FCT521FMQB | 5962-8854301SA | 54FCT534AT (GEN) | 5962-9223602M2A | 54FCT540CT (GEN) | 5962-9222005MRA |
| 54FCT521LMQB | 5962-88543012A | 54FCT534AT (GEN) | 5962-9223602MRA | 54FCT540CT (GEN) | 5962-9222006MSA |
| 54FCT521T (GEN) | 5962-9223401M2A | 54FCT534AT (GEN) | 5962-9223602MSA | 54FCT540DMQB | 5962-8976701RA |
| 54FCT521T (GEN) | 5962-9223401MRA | 54FCT534AT (GEN) | 5962-9223605M2A | 54FCT540LMQB | 5962-89767012A |
| 54FCT521T (GEN) | 5962-9223402MSA | 54FCT534AT (GEN) | 5962-9223605MRA | 54FCT540T (GEN) | 5962-9222001M2A |
| IDT54FCT521ADB | 5962-8854302RA | 54FCT534CT (GEN) | 5962-9223603M2A | 54FCT540T (GEN) | 5962-9222001MRA |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

| Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN |
|---|---|---|---|---|---|
| 54FCT540T (GEN) | 5962-9222002M2A | 54ACTQ541DMQB | 5962-9682901QRA | SNJ54F541FK | 5962-9175301M2A |
| 54FCT540T (GEN) | 5962-9222002MRA | 54ACTQ541E-QMLV | 5962-9682901V2A | SNJ54F541J | 5962-9175301MRA |
| 54FCT540T (GEN) | 5962-9222002MSA | 54ACTQ541FMQB | 5962-9682901QSA | SNJ54F541W | 5962-9175301MSA |
| CY54FCT540CTDMB | 5962-9222006MRA | 54ACTQ541J-QMLV | 5962-9682901VRA | SNJ54LS541FK | 84156012A |
| CY54FCT540CTLMB | 5962-9222006M2A | 54ACTQ541LMQB | 5962-9682901Q2A | SNJ54LS541W | 8415601SA |
| SL54LS540/B2A | 84155012A | 54ACTQ541W-QMLV | 5962-9682901VSA | SNJ54LVC541AFK | 5962-9759501Q2A |
| SL54LS540/B2C | 84155012C | 54ACTS541 (GEN) | 5962H9659501QRA | SNJ54LVC541AJ | 5962-9759501QRA |
| SL54LS540/BRA | 8415501RA | 54ACTS541 (GEN) | 5962H9659501QXA | SNJ54LVC541AW | 5962-9759501QSA |
| SL54LS540/BSA | 8415501SA | 54ACTS541 (GEN) | 5962H9659501VRA | UT54ACS541PQAH | 5962H9659401QRA |
| SNJ54AHC540FK | 5962-9685001Q2A | 54ACTS541 (GEN) | 5962H9659501VXA | UT54ACS541PQCH | 5962H9659401QRC |
| SNJ54AHC540J | 5962-9685001QRA | 54FCT541A (GEN) | 5962-8976602SA | UT54ACS541PVAH | 5962H9659401VRA |
| SNJ54AHC540W | 5962-9685001QSA | 54FCT541AT (GEN) | 5962-9223703MSA | UT54ACS541PVCH | 5962H9659401VRC |
| SNJ54AHCT540FK | 5962-9685101Q2A | 54FCT541AT (GEN) | 5962-9223704M2A | UT54ACS541UQAH | 5962H9659401QXA |
| SNJ54AHCT540J | 5962-9685101QRA | 54FCT541AT (GEN) | 5962-9223704MRA | UT54ACS541UQCH | 5962H9659401QXC |
| SNJ54AHCT540W | 5962-9685101QSA | 54FCT541CT (GEN) | 5962-9223705MSA | UT54ACS541UVAH | 5962H9659401VXA |
| SNJ54BCT540FK | 5962-9074801M2A | 54FCT541CT (GEN) | 5962-9223706M2A | UT54ACS541UVCH | 5962H9659401VXC |
| SNJ54BCT540J | 5962-9074801MRA | 54FCT541CT (GEN) | 5962-9223706MRA | UT54ACTS541EUQAG | 5962G9659503QXA |
| SNJ54BCT540W | 5962-9074801MSA | 54FCT541DMQB | 5962-8976601RA | UT54ACTS541EUQAH | 5962H9659502QXA |
| SNJ54LS540FK | 84155012A | 54FCT541LMQB | 5962-89766012A | UT54ACTS541EUQCG | 5962G9659503QXC |
| SNJ54LS540J | 8415501RA | 54FCT541T (GEN) | 5962-9223701MSA | UT54ACTS541EUQCH | 5962H9659502QXC |
| SNJ54LS540W | 8415501SA | 54FCT541T (GEN) | 5962-9223702M2A | UT54ACTS541EUVAG | 5962G9659503VXA |
| SNJ54LVC540AFK | 5962-9759401Q2A | 54FCT541T (GEN) | 5962-9223702MRA | UT54ACTS541EUVAH | 5962H9659502VXA |
| SNJ54LVC540AJ | 5962-9759401QRA | CY54FCT541TDMB | 5962-9223701MRA | UT54ACTS541EUVCG | 5962G9659503VXC |
| SNJ54LVC540AW | 5962-9759401QSA | CY54FCT541TLMB | 5962-9223701M2A | UT54ACTS541EUVCH | 5962H9659502VXC |
| UT54ACS540PQAH | 5962H9659201QCA | IDT54FCT541ADB | 5962-8976602RA | UT54ACTS541UQAG | 5962G9659501QXA |
| UT54ACS540PQCH | 5962H9659201QCC | IDT54FCT541ALB | 5962-89766022A | UT54ACTS541UQCG | 5962G9659501QXC |
| UT54ACS540PVAH | 5962H9659201VCA | IDT54FCT541ATDB | 5962-9223703MRA | UT54ACTS541UVAG | 5962G9659501VXA |
| UT54ACS540PVCH | 5962H9659201VCC | IDT54FCT541ATLB | 5962-9223703M2A | UT54ACTS541UVCG | 5962G9659501VXC |
| UT54ACS540UQAH | 5962H9659201QXA | IDT54FCT541CTDB | 5962-9223705MRA | CY54FCT541CTDMB | 5962-9223705MRA |
| UT54ACS540UQCH | 5962H9659201QXC | IDT54FCT541CTLB | 5962-9223705M2A | 54ABT543 (GEN) | 5962-9231401MKA |
| UT54ACS540UVAH | 5962H9659201VXA | IDT54FCT541DB | 5962-8976601RA | 54ABT543 (GEN) | 5962-9231401MLA |
| UT54ACS540UVCH | 5962H9659201VXC | IDT54FCT541EB | 5962-8976601SA | 54ABT543E-QML | 5962-9231401Q3A |
| UT54ACTS540PQAH | 5962H9659301QRA | IDT54FCT541LB | 5962-89766012A | 54ABT543J-QML | 5962-9231401QLA |
| UT54ACTS540PQCH | 5962H9659301QRC | IDT54FCT541TDB | 5962-9223701M2A | 54ABT543W-QML | 5962-9231401QKA |
| UT54ACTS540PVAH | 5962H9659301VRA | IDT54FCT541TDB | 5962-9223701MRA | 54F543 (GEN) | 5962-9063901M3A |
| UT54ACTS540PVCH | 5962H9659301VRC | SL54LS541/B2A | 84156012A | 54F543 (GEN) | 5962-9063901MKA |
| UT54ACTS540UQAH | 5962H9659301QXA | SL54LS541/B2C | 84156012C | 54F543 (GEN) | 5962-9063901MLA |
| UT54ACTS540UQCH | 5962H9659301QXC | SL54LS541/BSA | 8415601SA | 54FCT543 (GEN) | 5962-8973001KA |
| UT54ACTS540UVAH | 5962H9659301VXA | SNJ54ABT541FK | 5962-9471801Q2A | 54FCT543A (GEN) | 5962-8973002KA |
| UT54ACTS540UVCH | 5962H9659301VXC | SNJ54ABT541J | 5962-9471801QRA | 54FCT543AT (GEN) | 5962-9222102MKA |
| 54AC541 (GEN) | 5962-8870601VSA | SNJ54ABT541W | 5962-9471801QSA | 54FCT543AT (GEN) | 5962-9222105M3A |
| 54AC541DMQB | 5962-8870601RA | SNJ54AHC541FK | 5962-9685701Q2A | 54FCT543AT (GEN) | 5962-9222105MLA |
| 54AC541FMQB | 5962-8870601SA | SNJ54AHC541J | 5962-9685701QRA | 54FCT543CT (GEN) | 5962-9222103MKA |
| 54AC541K01Q | 5962-8870601VXC | SNJ54AHC541W | 5962-9685701QSA | 54FCT543CT (GEN) | 5962-9222106M3A |
| 54AC541K01Q | 5962-8870601XC | SNJ54AHCT541FK | 5962-9685801Q2A | 54FCT543CT (GEN) | 5962-9222106MLA |
| 54AC541K02Q | 5962-8870601XA | SNJ54AHCT541J | 5962-9685801QRA | 54FCT543T (GEN) | 5962-9222101MKA |
| 54AC541K02V | 5962-8870601VXA | SNJ54AHCT541W | 5962-9685801QSA | 54FCT543T (GEN) | 5962-9222104M3A |
| 54AC541LMQB | 5962-88706012A | SNJ54ALS541FK | 5962-89602012A | 54FCT543T (GEN) | 5962-9222104MLA |
| 54AC541WG-QML | 5962-8870601ZA | SNJ54ALS541J | 5962-8960201RA | CY54FCT543TDMB | 5962-9222101MLA |
| 54ACT541K01Q | 5962-8979501QXC | SNJ54ALS541W | 5962-8960201SA | CY54FCT543TLMB | 5962-9222101M3A |
| 54ACT541K01V | 5962-8979501VXC | SNJ54BCT541FK | 5962-9074901M2A | IDT54FCT543ADB | 5962-8973002LA |
| 54ACT541K02Q | 5962-8979501QXA | SNJ54BCT541J | 5962-9074901MRA | IDT54FCT543ALB | 5962-89730023A |
| 54ACT541K02V | 5962-8979501VXA | SNJ54BCT541W | 5962-9074901MSA | IDT54FCT543ATDB | 5962-9222102MLA |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

| Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN |
|---|---|---|---|---|---|
| IDT54FCT543ATLB | 5962-9222102M3A | 54ACT573DMQB | 5962-8766401RA | SNJ54BCT573W | 5962-9583501QSA |
| IDT54FCT543CTDB | 5962-9222103MLA | 54ACT573DMQB-RH | 5962R8766401RA | SNJ54HC573AFK | 85128012A |
| IDT54FCT543CTLB | 5962-9222103M3A | 54ACT573FMQB | 5962-8766401SA | SNJ54HC573AJ | 8512801RA |
| IDT54FCT543DB | 5962-8973001LA | 54ACT573FMQB-RH | 5962R8766401SA | SNJ54HC573AW | 8512801SA |
| IDT54FCT543LB | 5962-89730013A | 54ACT573LMQB | 5962-87664012A | SNJ54LVC573AFK | 5962-9757501Q2A |
| IDT54FCT543TDB | 5962-9222101MLA | 54ACT573LMQB-RH | 5962R87664012A | SNJ54LVC573AJ | 5962-9757501QRA |
| IDT54FCT543TLB | 5962-9222101M3A | 54ACTQ573DMQB | 5962-9219401MRA | SNJ54LVC573AW | 5962-9757501QSA |
| SNJ54ABT543AFK | 5962-9231402Q3A | 54ACTQ573FMQB | 5962-9219401MSA | SNJ54LVTH573FK | 5962-9583101Q2A |
| SNJ54ABT543AJT | 5962-9231402QLA | 54ACTQ573LMQB | 5962-9219401M2A | SNJ54LVTH573J | 5962-9583101QRA |
| SNJ54ABT543AW | 5962-9231402QKA | 54F573 (GEN) | 5962-9173801MSA | SNJ54LVTH573W | 5962-9583101QSA |
| SNJ54BCT543FK | 5962-9087001M3A | 54F573DMQB | 5962-9173801MRA | SNV54HC573AJ | 5962-8512801VRA |
| SNJ54BCT543JT | 5962-9087001MLA | 54F573LMQB | 5962-9173801M2A | SNV54HC573AW | 5962-8512801VSA |
| SNJ54BCT543W | 5962-9087001MKA | 54FCT573A (GEN) | 5962-88639022A | 54ABT574 (GEN) | 5962-9322001MRA |
| 54ABT543 (GEN) | 5962-9231401M3A | 54FCT573A (GEN) | 5962-8863902RA | 54ABT574 (GEN) | 5962-9322001MSA |
| 54BCT544 (GEN) | 5962-9155401M3A | 54FCT573A (GEN) | 5962-8863902SA | 54ABT574E-QML | 5962-9322001Q2A |
| 54BCT544 (GEN) | 5962-9155401MKA | 54FCT573AT (GEN) | 5962-9223802MSA | 54ABT574J-QML | 5962-9322001QRA |
| 54BCT544 (GEN) | 5962-9155401MLA | 54FCT573AT (GEN) | 5962-9223805M2A | 54ABT574W-QML | 5962-9322001QSA |
| 54F544 (GEN) | 5962-89555013A | 54FCT573AT (GEN) | 5962-9223805MRA | 54AC574 (GEN) | 5962-9677301QZA |
| 54F544 (GEN) | 5962-8955501KA | 54FCT573CT (GEN) | 5962-9223803MSA | 54ACT574 (GEN) | 5962-89601012A |
| 54F544 (GEN) | 5962-8955501LA | 54FCT573CT (GEN) | 5962-9223806M2A | 54ACT574 (GEN) | 5962-8960101BRA |
| 54ALS561A (GEN) | 83022032A | 54FCT573CT (GEN) | 5962-9223806MRA | 54ACT574 (GEN) | 5962-8960101RA |
| 54ALS561A (GEN) | 8302203RA | 54FCT573DMQB | 5962-8863901RA | 54ACT574 (GEN) | 5962-8960101SA |
| 54ALS561A (GEN) | 8302203SA | 54FCT573FMQB | 5962-8863901SA | 54ACT574 (GEN) | 5962-8960101SRA |
| 54ACT563DMQB | 5962-8955601RA | 54FCT573LMQB | 5962-88639012A | 54ACT574 (GEN) | 5962-8960101SSA |
| 54ACT563FMQB | 5962-8955601SA | 54FCT573T (GEN) | 5962-9223801MSA | 54ACT574DMQB | 5962-8960101MRA |
| 54ACT563LMQB | 5962-89556012A | 54FCT573T (GEN) | 5962-9223804M2A | 54ACT574FMQB | 5962-8960101MSA |
| 54HC563/B2A | 5962-86062012A | 54FCT573T (GEN) | 5962-9223804MRA | 54ACT574K01Q | 5962-8960101QXC |
| 54HC563/BSA | 5962-8606201SA | CD54HCT573F3A | 5962-8685601RA | 54ACT574K01V | 5962-8960101VXC |
| CD54HC563F3A | 5962-8606201RA | CY54FCT573ATLMB | 5962-9223802M2A | 54ACT574K02Q | 5962-8960101QXA |
| SNJ54ALS563BFK | 5962-88700012A | CY54FCT573TDMB | 5962-9223801MRA | 54ACT574K02V | 5962-8960101VXA |
| SNJ54ALS563BJ | 5962-8870001RA | IDT54FCT573ATDB | 5962-9223802MRA | 54ACT574LMQB | 5962-8960101M2A |
| SNJ54ALS563BW | 5962-8870001SA | IDT54FCT573ATLB | 5962-9223802M2A | 54F574 (GEN) | 5962-89724012A |
| 54ACT564DMQB | 5962-8955701RA | IDT54FCT573CTDB | 5962-9223803MRA | 54F574 (GEN) | 5962-8972401RA |
| 54ACT564FMQB | 5962-8955701SA | IDT54FCT573CTLB | 5962-9223803M2A | 54F574 (GEN) | 5962-8972401SA |
| 54ACT564LMQB | 5962-89557012A | IDT54FCT573TDB | 5962-9223801MRA | 54FCT574A (GEN) | 5962-8951302SA |
| 54HC564 (GEN) | 5962-86815012A | IDT54FCT573TLB | 5962-9223801M2A | 54FCT574AT (GEN) | 5962-9222203MSA |
| CD54HC564F3A | 5962-8681501RA | SNJ54ABT573FK | 5962-9321901Q2A | 54FCT574AT (GEN) | 5962-9222204M2A |
| SNJ54ALS564BFK | 5962-88728012A | SNJ54ABT573J | 5962-9321901QRA | 54FCT574AT (GEN) | 5962-9222204MRA |
| SNJ54ALS564BJ | 5962-8872801RA | SNJ54ABT573W | 5962-9321901QSA | 54FCT574CT (GEN) | 5962-9222205MSA |
| SNJ54ALS564BW | 5962-8872801SA | SNJ54ACT573FK | 5962-87664012A | 54FCT574CT (GEN) | 5962-9222206M2A |
| SNJ54ALS569AFK | 83025022A | SNJ54ACT573J | 5962-8766401RA | 54FCT574CT (GEN) | 5962-9222206MRA |
| SNJ54ALS569AJ | 8302502RA | SNJ54ACT573W | 5962-8766401SA | 54FCT574DMQB | 5962-8951301RA |
| SNJ54ALS569AW | 8302502SA | SNJ54AHC573FK | 5962-9685601Q2A | 54FCT574FMQB | 5962-8951301SA |
| 54ABT573E-QML | 5962-9321901Q2A | SNJ54AHC573J | 5962-9685601QRA | 54FCT574LMQB | 5962-89513012A |
| 54ABT573J-QML | 5962-9321901QRA | SNJ54AHC573W | 5962-9685601QSA | 54FCT574T (GEN) | 5962-9222201MSA |
| 54ABT573W-QML | 5962-9321901QSA | SNJ54AHCT573FK | 5962-9685501Q2A | 54FCT574T (GEN) | 5962-9222202M2A |
| 54AC573K01Q | 5962-0152401QXC | SNJ54AHCT573J | 5962-9685501QRA | 54FCT574T (GEN) | 5962-9222202MRA |
| 54AC573K01V | 5962-0152401VXC | SNJ54AHCT573W | 5962-9685501QSA | CD54HCT574F3A | 5962-8974201RA |
| 54AC573K02Q | 5962-0152401QXA | SNJ54ALS573CFK | 84012012A | CY54FCT574ATDMB | 5962-9222203MRA |
| 54AC573K02V | 5962-0152401VXA | SNJ54ALS573CJ | 8401201RA | CY54FCT574ATLMB | 5962-9222203M2A |
| 54ACQ573DMQB | 5962-9218001MRA | SNJ54ALS573CW | 8401201SA | CY54FCT574CTDMB | 5962-9222205MRA |
| 54ACQ573FMQB | 5962-9218001MSA | SNJ54BCT573FK | 5962-9583501Q2A | IDT54FCT574ADB | 5962-8951302RA |
| 54ACQ573LMQB | 5962-9218001M2A | SNJ54BCT573J | 5962-9583501QRA | IDT54FCT574ALB | 5962-89513022A |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

| Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN |
|---|---|---|---|---|---|
| IDT54FCT574ATDB | 5962-9222203MRA | SNJ54ALS576BJ | 8400102RA | 54FCT621T (GEN) | 5962-9224001MSA |
| IDT54FCT574ATLB | 5962-9222203M2A | SNJ54ALS576BW | 8400102SA | 54F623 (GEN) | 5962-90506012A |
| IDT54FCT574CTDB | 5962-9222205MRA | 54F579/2A | 5962-89545012A | 54F623 (GEN) | 5962-9050601RA |
| IDT54FCT574CTLB | 5962-9222205M2A | 54F579/RA | 5962-8954501RA | 54FCT623AT (GEN) | 5962-9224202M2A |
| IDT54FCT574DB | 5962-8951301RA | 54F579/SA | 5962-8954501SA | 54FCT623AT (GEN) | 5962-9224202MRA |
| IDT54FCT574LB | 5962-89513012A | SNJ54ALS580BFK | 84012022A | 54FCT623AT (GEN) | 5962-9224202MSA |
| IDT54FCT574TDB | 5962-9222201MRA | SNJ54ALS580BJ | 8401202RA | 54FCT623CT (GEN) | 5962-9224203M2A |
| IDT54FCT574TLB | 5962-9222201M2A | SNJ54ALS580BW | 8401202SA | 54FCT623CT (GEN) | 5962-9224203MRA |
| JM54ACT574B2A | 5962-8960101B2A | 54CDC586 (GEN) | 5962-9754001QXA | 54FCT623CT (GEN) | 5962-9224203MSA |
| JM54ACT574B2A-R | 5962R8960101B2A | SNJ54HC590AFK | 5962-89603012A | 54FCT623T (GEN) | 5962-9224201M2A |
| JM54ACT574BRA-R | 5962R8960101BRA | SNJ54HC590AJ | 5962-8960301EA | 54FCT623T (GEN) | 5962-9224201MRA |
| JM54ACT574BSA | 5962-8960101BSA | SNJ54HC590AW | 5962-8960301FA | 54FCT623T (GEN) | 5962-9224201MSA |
| JM54ACT574BSA-R | 5962R8960101BSA | SNJ54LS590FK | 5962-87517012A | 54HC623 (GEN) | 5962-89989012A |
| JM54ACT574S2A-R | 5962R8960101S2A | SNJ54LS590J | 5962-8751701EA | 54HC623 (GEN) | 5962-8998901RA |
| JM54ACT574SRA-R | 5962R8960101SRA | SNJ54LS590W | 5962-8751701FA | SNJ54ABT623AFK | 5962-9461801Q2A |
| JM54ACT574SSA-R | 5962R8960101SSA | SNJ54LS592FK | 5962-87621012A | SNJ54ABT623AJ | 5962-9461801QRA |
| JM54ACT574SZA-R | 5962R8960101SZA | SNJ54LS592J | 5962-8762101EA | SNJ54ABT623AW | 5962-9461801QSA |
| SNJ54ABT574FK | 5962-9322001Q2A | SNJ54LS592W | 5962-8762101FA | SNJ54BCT623FK | 5962-9094001M2A |
| SNJ54ABT574J | 5962-9322001QRA | SNJ54HC595FK | 5962-86816012A | SNJ54BCT623J | 5962-9094001MRA |
| SNJ54ABT574W | 5962-9322001QSA | SNJ54HC595J | 5962-8681601EA | SNJ54BCT623W | 5962-9094001MSA |
| SNJ54AC574FK | 5962-9677301Q2A | SNJ54LS595FK | 5962-86717012A | SNJ54F623W | 5962-9050601SA |
| SNJ54AC574J | 5962-9677301QRA | SNJ54LS595J | 5962-8671701EA | SNJ54LS628FK | 5962-9204601M2A |
| SNJ54AC574W | 5962-9677301QSA | SNJ54LS595W | 5962-8671701FA | SNJ54LS628J | 5962-9204601MCA |
| SNJ54AHC574FK | 5962-9685401Q2A | SNV54HC595J | 5962-8681601VEA | SNJ54LS629FK | 81021012A |
| SNJ54AHC574J | 5962-9685401QRA | SNV54HC595W | 5962-8681601VFA | SNJ54LS629J | 8102101EA |
| SNJ54AHC574W | 5962-9685401QSA | 54HC597 (GEN) | 5962-86817012A | SNJ54LS629W | 8102101FA |
| SNJ54AHCT574FK | 5962-9685301Q2A | 54HCT597 (GEN) | 5962-8974101EA | 54FCT640 (GEN) | 5962-88654012A |
| SNJ54AHCT574J | 5962-9685301QRA | CD54HC597F3A | 5962-8681701EA | 54FCT640 (GEN) | 5962-8865401RA |
| SNJ54AHCT574W | 5962-9685301QSA | SNJ54LS597FK | 5962-89444012A | 54FCT640 (GEN) | 5962-8865401SA |
| SNJ54ALS574BFK | 84001012A | SNJ54LS597J | 5962-8944401EA | 54FCT640 (GEN) | 5962-88654022A |
| SNJ54ALS574BJ | 8400101RA | SNJ54LS597W | 5962-8944401FA | 54FCT640 (GEN) | 5962-8865402RA |
| SNJ54ALS574BW | 8400101SA | 54LS598 (GEN) | 5962-89756012A | 54FCT640 (GEN) | 5962-8865402SA |
| SNJ54BCT574FK | 5962-9583601Q2A | 54LS598 (GEN) | 5962-8975601RA | 54FCT640AT (GEN) | 5962-9224303M2A |
| SNJ54BCT574J | 5962-9583601QRA | 54LS598 (GEN) | 5962-8975601SA | 54FCT640AT (GEN) | 5962-9224303MRA |
| SNJ54BCT574W | 5962-9583601QSA | HI1-546/883 | 5962-8513101XA | 54FCT640AT (GEN) | 5962-9224304M2A |
| SNJ54LVC574AFK | 5962-9757601Q2A | HI4-546/883 | 5962-85131013A | 54FCT640AT (GEN) | 5962-9224304MRA |
| SNJ54LVC574AJ | 5962-9757601QRA | HS0-0546RH-Q | 5962D9569301V9A | 54FCT640AT (GEN) | 5962-9224304MSA |
| SNJ54LVC574AW | 5962-9757601QSA | HS-0546 (GEN) | 5962D9569301VXA | 54FCT640CT (GEN) | 5962-9224305M2A |
| SNJ54LVTH574AFK | 5962-9583201Q2A | HS1B-0546RH-Q | 5962D9569301VXC | 54FCT640CT (GEN) | 5962-9224305MRA |
| SNJ54LVTH574AJ | 5962-9583201QRA | 54F620 (GEN) | 5962-89466012A | 54FCT640CT (GEN) | 5962-9224306M2A |
| SNJ54LVTH574AW | 5962-9583201QSA | 54F620 (GEN) | 5962-8946601RA | 54FCT640CT (GEN) | 5962-9224306MRA |
| SNV54LVTH574AJ | 5962-9583201VRA | 54F620 (GEN) | 5962-8946601SA | 54FCT640CT (GEN) | 5962-9224306MSA |
| SNV54LVTH574AW | 5962-9583201VSA | SNJ54BCT620AFK | 5962-9075001M2A | 54FCT640T (GEN) | 5962-9224301M2A |
| 54AC574K01Q | 5962-9677302QXC | SNJ54BCT620AJ | 5962-9075001MRA | 54FCT640T (GEN) | 5962-9224301MRA |
| 54AC574K01V | 5962-9677302VXC | SNJ54BCT620AW | 5962-9075001MSA | 54FCT640T (GEN) | 5962-9224302M2A |
| 54AC574K02Q | 5962-9677302QXA | 54F621 (GEN) | 5962-90506022A | 54FCT640T (GEN) | 5962-9224302MRA |
| 54AC574K02V | 5962-9677302VXA | 54F621 (GEN) | 5962-9050602RA | 54FCT640T (GEN) | 5962-9224302MSA |
| 54ABT574 (GEN) | 5962-9322001M2A | 54F621 (GEN) | 5962-9050602SA | 54HCT640F3A | 5962-8974001RA |
| 54ACT574 (GEN) | 5962-8960101S2A | 54FCT621AT (GEN) | 5962-9224002M2A | SL54LS640/B2A | 84161012A |
| 54AS575 (GEN) | 5962-9754901Q3A | 54FCT621AT (GEN) | 5962-9224002MRA | SL54LS640/B2C | 84161012C |
| 54AS575 (GEN) | 5962-9754901QLA | 54FCT621AT (GEN) | 5962-9224002MSA | SL54LS640/BRA | 8416101RA |
| SNJ54AS575W | 5962-9754901QKA | 54FCT621T (GEN) | 5962-9224001M2A | SL54LS640/BSA | 8416101SA |
| SNJ54ALS576BFK | 84001022A | 54FCT621T (GEN) | 5962-9224001MRA | SNJ54ALS640BFK | 5962-88727012A |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART II, Listed By Generic PIN

| Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN |
|---|---|---|---|---|---|
| SNJ54ALS640BJ | 5962-8872701RA | 54AC646SDMQB | 5962-8968201LA | SNJ54LVT646W | 5962-9674801QKA |
| SNJ54ALS640BW | 5962-8872701SA | 54AC646SDMQB-RH | 5962R8968201LA | 54BCT648/B3A | 5962-9172401M3A |
| SNJ54AS640FK | 5962-89553012A | 54ACTQ646FMQB | 5962-9219601MKA | 54BCT648/BKA | 5962-9172401MKA |
| SNJ54AS640J | 5962-8955301RA | 54ACTQ646LMQB | 5962-9219601M3A | 54BCT648/BLA | 5962-9172401MLA |
| SNJ54AS640W | 5962-8955301SA | 54ACTQ646SDMQB | 5962-9219601MLA | 54F648 (GEN) | 5962-8975402KA |
| SNJ54BCT640FK | 5962-9075201M2A | 54F646FMQB | 5962-8975401KA | 54F648LMQB | 5962-89754023A |
| SNJ54BCT640J | 5962-9075201MRA | 54F646LMQB | 5962-89754013A | 54F648SDMQB | 5962-8975402LA |
| SNJ54BCT640W | 5962-9075201MSA | 54F646SDMQB | 5962-8975401LA | SNJ54ALS648FK | 5962-90523013A |
| SNJ54HC640FK | 5962-87809012A | 54FCT646 (GEN) | 5962-88775013A | SNJ54ALS648JT | 5962-9052301LA |
| SNJ54HC640J | 5962-8780901RA | 54FCT646 (GEN) | 5962-8877501KA | SNJ54ALS648W | 5962-9052301KA |
| SNJ54LS640FK | 84161012A | 54FCT646 (GEN) | 5962-8877501LA | 54AS651/B3A | 5962-88753013A |
| SNJ54LS640J | 8416101RA | 54FCT646A (GEN) | 5962-88775023A | 54AS651/BKA | 5962-8875301KA |
| SNJ54LS640W | 8416101SA | 54FCT646A (GEN) | 5962-8877502KA | 54AS651/BLA | 5962-8875301LA |
| SNV54LS640J | 5962-8416101VRA | 54FCT646A (GEN) | 5962-8877502LA | 54ABT652 (GEN) | 5962-9324201M3A |
| SNV54LS640W | 5962-8416101VSA | 54FCT646AT (GEN) | 5962-9222303MKA | 54ABT652 (GEN) | 5962-9324201MKA |
| SL54LS642/B2A | 5962-89748012A | 54FCT646AT (GEN) | 5962-9222304M3A | 54ABT652 (GEN) | 5962-9324201MLA |
| SL54LS642/B2C | 5962-89748012C | 54FCT646AT (GEN) | 5962-9222304MLA | 54ABT652 (GEN) | 5962-9324201Q3A |
| SL54LS642/BRA | 5962-8974801RA | 54FCT646CT (GEN) | 5962-9222305MKA | 54ABT652 (GEN) | 5962-9324201QKA |
| SL54LS642/BSA | 5962-8974801SA | 54FCT646CT (GEN) | 5962-9222306M3A | 54ABT652 (GEN) | 5962-9324201QLA |
| 54FCT645 (GEN) | 5962-88653012A | 54FCT646CT (GEN) | 5962-9222306MLA | 54F652 (GEN) | 5962-8955801KA |
| 54FCT645 (GEN) | 5962-8865301RA | 54FCT646T (GEN) | 5962-9222301MKA | 54F652LMQB | 5962-89558013A |
| 54FCT645 (GEN) | 5962-8865301SA | 54FCT646T (GEN) | 5962-9222302M3A | 54F652SDMQB | 5962-8955801LA |
| 54FCT645A (GEN) | 5962-88653022A | 54FCT646T (GEN) | 5962-9222302MLA | 54FCT652AT (GEN) | 5962-9224602M3A |
| 54FCT645A (GEN) | 5962-8865302RA | 54HC646 (GEN) | 5962-86885013A | 54FCT652AT (GEN) | 5962-9224602MKA |
| 54FCT645A (GEN) | 5962-8865302SA | 54HC646 (GEN) | 5962-8688501LA | 54FCT652AT (GEN) | 5962-9224602MLA |
| 54FCT645AT (GEN) | 5962-9224402M2A | CD54HC646F3A | 5962-8688501JA | 54FCT652AT (GEN) | 5962-9224605M3A |
| 54FCT645AT (GEN) | 5962-9224402MRA | CY54FCT646ATDMB | 5962-9222303MLA | 54FCT652AT (GEN) | 5962-9224605MLA |
| 54FCT645AT (GEN) | 5962-9224402MSA | CY54FCT646ATLMB | 5962-9222303M3A | 54FCT652CT (GEN) | 5962-9224603M3A |
| 54FCT645AT (GEN) | 5962-9224405M2A | CY54FCT646CTLMB | 5962-9222305M3A | 54FCT652CT (GEN) | 5962-9224603MKA |
| 54FCT645AT (GEN) | 5962-9224405MRA | CY54FCT646TLMB | 5962-9222301M3A | 54FCT652CT (GEN) | 5962-9224603MLA |
| 54FCT645CT (GEN) | 5962-9224403M2A | IDT54FCT646ATDB | 5962-9222303MLA | 54FCT652CT (GEN) | 5962-9224606M3A |
| 54FCT645CT (GEN) | 5962-9224403MRA | IDT54FCT646ATLB | 5962-9222303M3A | 54FCT652CT (GEN) | 5962-9224606MLA |
| 54FCT645CT (GEN) | 5962-9224403MSA | IDT54FCT646CTDB | 5962-9222305MLA | 54FCT652T (GEN) | 5962-9224601M3A |
| 54FCT645CT (GEN) | 5962-9224406M2A | IDT54FCT646CTLB | 5962-9222305M3A | 54FCT652T (GEN) | 5962-9224601MKA |
| 54FCT645CT (GEN) | 5962-9224406MRA | IDT54FCT646TDB | 5962-9222301MLA | 54FCT652T (GEN) | 5962-9224601MLA |
| 54FCT645T (GEN) | 5962-9224401M2A | IDT54FCT646TLB | 5962-9222301M3A | 54FCT652T (GEN) | 5962-9224604M3A |
| 54FCT645T (GEN) | 5962-9224401MRA | SNJ54ABT646AFK | 5962-9457702Q3A | 54FCT652T (GEN) | 5962-9224604MLA |
| 54FCT645T (GEN) | 5962-9224401MSA | SNJ54ABT646AJT | 5962-9457702QLA | SNJ54ABT652AFK | 5962-9324202Q3A |
| 54FCT645T (GEN) | 5962-9224404M2A | SNJ54ABT646AW | 5962-9457702QKA | SNJ54ABT652AJ | 5962-9324202QLA |
| 54FCT645T (GEN) | 5962-9224404MRA | SNJ54ALS646FK | 5962-89956013A | SNJ54ABT652AW | 5962-9324202QKA |
| SNJ54ALS645AFK | 84033012A | SNJ54ALS646JT | 5962-8995601LA | SNJ54ALS652FK | 5962-88673013A |
| SNJ54ALS645AJ | 8403301RA | SNJ54ALS646W | 5962-8995601KA | SNJ54ALS652JT | 5962-8867301LA |
| SNJ54ALS645AW | 8403301SA | SNJ54AS646FK | 5962-87595013A | SNJ54ALS652W | 5962-8867301KA |
| 54ABT646 (GEN) | 5962-9457701M3A | SNJ54AS646JT | 5962-8759501LA | SNJ54AS652FK | 5962-88687013A |
| 54ABT646 (GEN) | 5962-9457701MKA | SNJ54AS646W | 5962-8759501KA | SNJ54AS652JT | 5962-8868701LA |
| 54ABT646 (GEN) | 5962-9457701MLA | SNJ54BCT646FK | 5962-9155501M3A | SNJ54AS652W | 5962-8868701KA |
| 54ABT646E-QML | 5962-9457701Q3A | SNJ54BCT646JT | 5962-9155501MLA | SNJ54BCT652FK | 5962-9155301M3A |
| 54ABT646J-QML | 5962-9457701QLA | SNJ54BCT646W | 5962-9155501MKA | SNJ54BCT652JT | 5962-9155301MLA |
| 54ABT646W-QML | 5962-9457701QKA | SNJ54LVC646AFK | 5962-9762601Q3A | SNJ54BCT652W | 5962-9155301MKA |
| 54AC646FMQB | 5962-8968201KA | SNJ54LVC646AJT | 5962-9762601QLA | SNL54LVC652AFK | 5962-9762701Q3A |
| 54AC646FMQB-RH | 5962R8968201KA | SNJ54LVC646AW | 5962-9762601QKA | SNL54LVC652AJT | 5962-9762701QLA |
| 54AC646LMQB | 5962-89682013A | SNJ54LVT646FK | 5962-9674801Q3A | SNL54LVC652AW | 5962-9762701QKA |
| 54AC646LMQB-RH | 5962R89682013A | SNJ54LVT646JT | 5962-9674801QLA | SNJ54ALS653FK | 5962-89687013A |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

| Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN |
|---|---|---|---|---|---|
| SNJ54ALS653JT | 5962-8968701LA | A54SX72A-1CQ208B | 5962-0054302QYC | JM54ACT74SDA | 5962-8752501SDA |
| SNJ54ALS653W | 5962-8968701KA | RT54SX72S-1CQ208B | 5962-0151502QYC | JM54ACT74SDA-RH | 5962R8752501SDA |
| 54ACTQ657FMQB | 5962-9219701MKA | RT54SX72S-1CQ208E | 5962-0151504QYC | JM54ACT74SZA-RH | 5962R8752501SZA |
| 54ACTQ657LMQB | 5962-9219701M3A | A54SX72A-1CQ256B | 5962-0054302QXC | SNJ54AC74FK | 5962-88520012A |
| 54ACTQ657SDMQB | 5962-9219701MLA | RT54SX72S-1CQ256B | 5962-0151502QXC | SNJ54AC74J | 5962-8852001CA |
| 54F657 | 5962-89535013A | RT54SX72S-1CQ256E | 5962-0151504QXC | SNJ54AC74W | 5962-8852001DA |
| 54F657 | 5962-8953501KA | A54SX72A-CQ208B | 5962-0054301QYC | SNJ54ACT74FK | 5962-8752501M2A |
| 54F657 | 5962-8953501LA | RT54SX72S-CQ208B | 5962-0151501QYC | SNJ54ACT74J | 5962-8752501MCA |
| 54LS668 (GEN) | 5962-86876012A | RT54SX72S-CQ208E | 5962-0151503QYC | SNJ54ACT74W | 5962-8752501MDA |
| 54LS668 (GEN) | 5962-8687601EA | A54SX72A-CQ256B | 5962-0054301QXC | SNJ54AHC74FK | 5962-9686001Q2A |
| 54LS668 (GEN) | 5962-8687601FA | RT54SX72S-CQ256B | 5962-0151501QXC | SNJ54AHC74J | 5962-9686001QCA |
| SL54LS670/BEA | 7704201EA | RT54SX72S-CQ256E | 5962-0151503QXC | SNJ54AHC74W | 5962-9686001QDA |
| SL54LS670/BFA | 7704201FA | 54HC7266 (GEN) | 84043022A | SNJ54AHCT74FK | 5962-9686101Q2A |
| SNJ54LS670J | 7704201EA | 54HC7266 (GEN) | 8404302AA | SNJ54AHCT74J | 5962-9686101QCA |
| SNJ54LS670W | 7704201FA | CD54HC7266F3A | 8404302CA | SNJ54AHCT74W | 5962-9686101QDA |
| SNV54LS670J | 5962-7704201VEA | 54HC73 (GEN) | 5962-85153012A | SNJ54ALS74AFK | 84011012A |
| SNV54LS670W | 5962-7704201VFA | CD54HC73F3A | 5962-8515301CA | SNJ54ALS74AJ | 8401101CA |
| SNJ54LS673FK | 5962-88602013A | SNJ54LS73AJ | 5962-9675101QCA | SNJ54ALS74AW | 8401101DA |
| SNJ54LS673J | 5962-8860201JA | SNJ54LS73AW | 5962-9675101QDA | SNJ54AS74AFK | 5962-9862701Q2A |
| SNJ54LS673JT | 5962-8860201LA | SNV54LS73AJ | 5962-9675101VCA | SNJ54AS74AJ | 5962-9862701QCA |
| SNJ54LS673W | 5962-8860201KA | SNV54LS73AW | 5962-9675101VDA | SNJ54F74FK | 5962-9759201Q2A |
| SNJ54LS674FK | 5962-88607013A | 54AC74DMQB | 5962-8852001CA | SNJ54F74J | 5962-9759201QCA |
| SNJ54LS674J | 5962-8860701JA | 54AC74FMQB | 5962-8852001DA | SNJ54F74W | 5962-9759201QDA |
| SNJ54LS674JT | 5962-8860701LA | 54AC74K01Q | 5962-8852001XC | SNJ54HC74FK | 84056012A |
| SNJ54LS674W | 5962-8860701KA | 54AC74K01V | 5962-8852001VXC | SNJ54HC74J | 8405601CA |
| 54F676 (GEN) | 5962-8854601KA | 54AC74K02Q | 5962-8852001XA | SNJ54HC74W | 8405601DA |
| 54F676 (GEN) | 5962-8854601LA | 54AC74K02V | 5962-8852001VXA | SNJ54LVC74AFK | 5962-9761601Q2A |
| 54F676 (GEN) | 5962-88546013A | 54AC74LMQB | 5962-88520012A | SNJ54LVC74AJ | 5962-9761601QCA |
| SNJ54LS682FK | 84151012A | 54ACT74 (GEN) | 5962-87525012A | SNJ54LVC74AW | 5962-9761601QDA |
| SNJ54LS682J | 8415101RA | 54ACT74 (GEN) | 5962-8752501CA | SNV54AC74J | 5962-8852001VCA |
| SNJ54LS682W | 8415101SA | 54ACT74 (GEN) | 5962-8752501DA | SNV54AC74W | 5962-8852001VDA |
| SNJ54LS684FK | 84152012A | 54ACT74 (GEN) | 5962-8752501S2A | SNV54HC74J | 5962-8405601VCA |
| SNJ54LS684J | 8415201RA | 54ACT74 (GEN) | 5962-8752501SCA | SNV54HC74W | 5962-8405601VDA |
| SNJ54LS684W | 8415201SA | 54ACT74DMQB | 5962-8752501MCA | SNV54LVC74AJ | 5962-9761601VCA |
| CD54HCT688F3A | 5962-8685701RA | 54ACT74FMQB | 5962-8752501MDA | SNV54LVC74AW | 5962-9761601VDA |
| SNJ54ALS688FK | 5962-88578012A | 54ACT74LMQB | 5962-8752501M2A | UT54ACS74PQAH | 5962H9653401QCA |
| SNJ54ALS688J | 5962-8857801RA | 54ALS74A (GEN) | 8401101AA | UT54ACS74PQCH | 5962H9653401QCC |
| SNJ54ALS688W | 5962-8857801SA | 54ALS74A (GEN) | 8401101BA | UT54ACS74PVAH | 5962H9653401VCA |
| SNJ54HC688FK | 5962-86818012A | 54HC74 (GEN) | 8405601AA | UT54ACS74PVCH | 5962H9653401VCC |
| SNJ54HC688J | 5962-8681801RA | 54HC74 (GEN) | 8405601BA | UT54ACS74-QDIE | 5962H9653401Q9A |
| SNJ54LS688FK | 84153012A | 54HC74K01Q | 8405601XC | UT54ACS74UQAH | 5962H9653401QXA |
| SNJ54LS688J | 8415301RA | 54HC74K01V | 5962-8405601VXC | UT54ACS74UQCH | 5962H9653401QXC |
| SNJ54LS688W | 8415301SA | 54HC74K02Q | 8405601XA | UT54ACS74UVAH | 5962H9653401VXA |
| SNV54LS688J | 5962-8415301VRA | 54HC74K02V | 5962-8405601VXA | UT54ACS74UVCH | 5962H9653401VXC |
| SNV54LS688W | 5962-8415301VSA | CD54HCT74F3A | 5962-8685301CA | UT54ACS74-VDIE | 5962H9653401V9A |
| HI1-547/883 | 5962-8513102XA | JM54ACT74B2A | 5962-8752501B2A | UT54ACTS74PQAH | 5962H9653501QCA |
| HI4-547/883 | 5962-85131023A | JM54ACT74B2A-RH | 5962R8752501B2A | UT54ACTS74PQCH | 5962H9653501QCC |
| HS0-0547RH-Q | 5962D9569302V9A | JM54ACT74BCA | 5962-8752501BCA | UT54ACTS74PVAH | 5962H9653501VCA |
| HS1B-0547RH-Q | 5962D9569302VXC | JM54ACT74BCA-RH | 5962R8752501BCA | UT54ACTS74PVCH | 5962H9653501VCC |
| 54ACT715DMQB | 5962-9309701MRA | JM54ACT74BDA | 5962-8752501BDA | UT54ACTS74UQAH | 5962H9653501QXA |
| 54ACT715LMQB | 5962-9309701M2A | JM54ACT74BDA-RH | 5962R8752501BDA | UT54ACTS74UQCH | 5962H9653501QXC |
| 54ACT715-RDMQB | 5962-9309702MRA | JM54ACT74S2A-RH | 5962R8752501S2A | UT54ACTS74UVAH | 5962H9653501VXA |
| 54ACT715-RLMQB | 5962-9309702M2A | JM54ACT74SCA-RH | 5962R8752501SCA | UT54ACTS74UVCH | 5962H9653501VXC |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

| Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN |
|---|---|---|---|---|---|
| 54ACT74K01Q | 5962-8752503QXC | 54ALS805A (GEN) | 5962-88694012A | SNJ54AS821AW | 5962-9078001MKA |
| 54ACT74K01V | 5962-8752503VXC | 54ALS805A (GEN) | 5962-8869401RA | 54AS822/B3A | 5962-9078002M3A |
| 54ACT74K02Q | 5962-8752503QXA | SNJ54ALS805AW | 5962-8869401SA | 54AS822/BKA | 5962-9078002MKA |
| 54ACT74K02V | 5962-8752503VXA | SNJ54AS805BFK | 5962-87794012A | 54AS822/BLA | 5962-9078002MLA |
| 54HC75/B2A | 84070012A | SNJ54AS805BJ | 5962-8779401RA | 54ACT823FMQB | 5962-9161001MKA |
| 54HC75/BFA | 8407001FA | SNJ54AS805BW | 5962-8779401SA | 54ACT823LMQB | 5962-9161001M3A |
| CD54HC75F3A | 8407001EA | 54ALS808 (GEN) | 5962-88695012A | 54ACT823SDMQB | 5962-9161001MLA |
| CD54HCT75F3A | 5962-9075801MEA | 54ALS808 (GEN) | 5962-8869501RA | 54FCT823A (GEN) | 5962-8865601KA |
| SL54LS75/BEA | 7601201EA | 54ALS808 (GEN) | 5962-8869501SA | 54FCT823AT (GEN) | 5962-9222901M3A |
| SL54LS75/BFA | 7601201FA | SNJ54AS808BFK | 5962-88522012A | 54FCT823AT (GEN) | 5962-9222901MKA |
| SNJ54LS75J | 7601201EA | SNJ54AS808BJ | 5962-8852201RA | 54FCT823AT (GEN) | 5962-9222901MLA |
| SNJ54LS75W | 7601201FA | SNJ54AS808BW | 5962-8852201SA | 54FCT823AT (GEN) | 5962-9222902M3A |
| SNV54LS75J | 5962-7601201VEA | 54ACT818FMQB | 5962-9160901MKA | 54FCT823AT (GEN) | 5962-9222902MLA |
| SNV54LS75W | 5962-7601201VFA | 54ACT818LMQB | 5962-9160901M3A | 54FCT823B (GEN) | 5962-8865602KA |
| SNJ54AS756FK | 5962-90563012A | 54ACT818SDMQB | 5962-9160901MLA | 54FCT823BT (GEN) | 5962-9222903M3A |
| SNJ54AS756J | 5962-9056301RA | 54ABT821 (GEN) | 5962-9469101M3A | 54FCT823BT (GEN) | 5962-9222903MKA |
| SNJ54AS756W | 5962-9056301SA | 54ABT821 (GEN) | 5962-9469101MKA | 54FCT823BT (GEN) | 5962-9222903MLA |
| 54HC76 (GEN) | 5962-87732012A | 54ABT821 (GEN) | 5962-9469101MLA | 54FCT823BT (GEN) | 5962-9222904M3A |
| 54HC76 (GEN) | 5962-8773201EA | 54AC821FMQB | 5962-9160601MKA | 54FCT823BT (GEN) | 5962-9222904MLA |
| SNJ5476J | 5962-9557501QEA | 54AC821LMQB | 5962-9160601M3A | 54FCT823CT (GEN) | 5962-9222905M3A |
| SNJ5476W | 5962-9557501QFA | 54AC821SDMQB | 5962-9160601MLA | 54FCT823CT (GEN) | 5962-9222905MKA |
| SNJ54ALS76AW | 7601301FA | 54ACT821FMQB | 5962-8870501KA | 54FCT823CT (GEN) | 5962-9222905MLA |
| SNJ54LS76AFK | 76013012A | 54ACT821LMQB | 5962-88705013A | 54FCT823CT (GEN) | 5962-9222906M3A |
| SNJ54LS76AJ | 7601301EA | 54ACT821SDMQB | 5962-8870501LA | 54FCT823CT (GEN) | 5962-9222906MLA |
| SNJ54AS760FK | 5962-87767012A | 54F821 (GEN) | 5962-8943801KA | IDT54FCT823ADB | 5962-8865601LA |
| SNJ54AS760J | 5962-8776701RA | 54F821LMQB | 5962-89438013A | IDT54FCT823ALB | 5962-88656013A |
| SNJ54AS760W | 5962-8776701SA | 54F821SDMQB | 5962-8943801LA | IDT54FCT823BDB | 5962-8865602LA |
| SNJ54BCT760FK | 5962-9093801M2A | 54FCT821A (GEN) | 5962-8860801KA | IDT54FCT823BLB | 5962-88656023A |
| SNJ54BCT760J | 5962-9093801MRA | 54FCT821AT (GEN) | 5962-9222501MKA | SNJ54ABT823FK | 5962-9450801Q3A |
| SNJ54BCT760W | 5962-9093801MSA | 54FCT821AT (GEN) | 5962-9222502M3A | SNJ54ABT823J | 5962-9450801QLA |
| 54F776 (GEN) | 5962-88707013A | 54FCT821AT (GEN) | 5962-9222502MLA | SNJ54ABT823W | 5962-9450801QKA |
| 54F776 (GEN) | 5962-8870701XA | 54FCT821B (GEN) | 5962-8860802KA | SNJ54AS823AFK | 5962-89525013A |
| 54F776 (GEN) | 5962-8870701YA | 54FCT821BT (GEN) | 5962-9222503MKA | SNJ54AS823AJT | 5962-8952501LA |
| 54F777 (GEN) | 5962-9159701M2A | 54FCT821BT (GEN) | 5962-9222504M3A | SNJ54AS823AW | 5962-8952501KA |
| 54F777 (GEN) | 5962-9159701MRA | 54FCT821BT (GEN) | 5962-9222504MLA | 54FCT824A (GEN) | 5962-89665013A |
| 54F777 (GEN) | 5962-9159701MSA | 54FCT821CT (GEN) | 5962-9222505MKA | 54FCT824A (GEN) | 5962-8966501KA |
| SNJ54ABT7819GB | 5962-9470401QXA | 54FCT821CT (GEN) | 5962-9222506M3A | 54FCT824A (GEN) | 5962-8966501LA |
| SNJ54ABT7820GB | 5962-9650901QXA | 54FCT821CT (GEN) | 5962-9222506MLA | 54FCT824B (GEN) | 5962-89665023A |
| 54ACT7881 (GEN) | 5962-9562701QYA | IDT54FCT821ADB | 5962-8860801LA | 54FCT824B (GEN) | 5962-8966502KA |
| HI1-548/883 | 7705202EA | IDT54FCT821ALB | 5962-88608013A | 54FCT824B (GEN) | 5962-8966502LA |
| HI4-548/883 | 77052022A | IDT54FCT821ATDB | 5962-9222501MLA | SNJ54BCT8240AFK | 5962-9174601Q3A |
| HS1B-0548RH-Q | 5962D9569401VEC | IDT54FCT821ATLB | 5962-9222501M3A | SNJ54BCT8240AJT | 5962-9174601QLA |
| TLC548 (GEN) | 5962-9084501M2A | IDT54FCT821BDB | 5962-8860802LA | SNJ54BCT8244AFK | 5962-9172601M3A |
| TLC548 (GEN) | 5962-9084501MPA | IDT54FCT821BLB | 5962-88608023A | SNJ54BCT8244AJT | 5962-9172601MLA |
| 54F803 (GEN) | 5962-9171601M2A | IDT54FCT821BTDB | 5962-9222503MLA | 54BCT8245A (GEN) | 5962-9172801M3A |
| 54F803 (GEN) | 5962-9171601MCA | IDT54FCT821BTLB | 5962-9222503M3A | 54BCT8245A (GEN) | 5962-9172801MLA |
| 54F803 (GEN) | 5962-9171601MDA | IDT54FCT821CTDB | 5962-9222505MLA | SNJ54ABT8245FK | 5962-9318601M3A |
| SNJ54ALS804AFK | 5962-88693012A | IDT54FCT821CTLB | 5962-9222505M3A | SNJ54ABT8245JT | 5962-9318601MLA |
| SNJ54ALS804AJ | 5962-8869301RA | SNJ54ABT821FK | 5962-9469101Q3A | SNJ54BCT8245AFK | 5962-9172801Q3A |
| SNJ54ALS804AW | 5962-8869301SA | SNJ54ABT821JT | 5962-9469101QLA | SNJ54BCT8245AJT | 5962-9172801QLA |
| SNJ54AS804BFK | 5962-87766012A | SNJ54ABT821W | 5962-9469101QKA | 54ACT825DMQB | 5962-9161101MLA |
| SNJ54AS804BJ | 5962-8776601RA | SNJ54AS821AFK | 5962-9078001M3A | 54ACT825FMQB | 5962-9161101MKA |
| SNJ54AS804BW | 5962-8776601SA | SNJ54AS821AJT | 5962-9078001MLA | 54ACT825LMQB | 5962-9161101M3A |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

| Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN |
|---|---|---|---|---|---|
| 54FCT825A (GEN) | 5962-88674013A | IDT54FCT827CTLB | 5962-9224705M3A | 54FCT843C (GEN) | 5962-8975803KA |
| 54FCT825A (GEN) | 5962-8867401KA | SNJ54ABT827FK | 5962-9450901Q3A | 54FCT843C (GEN) | 5962-8975803LA |
| 54FCT825A (GEN) | 5962-8867401LA | SNJ54ABT827JT | 5962-9450901QLA | SNJ54ABT843FK | 5962-9571201Q3A |
| 54FCT825AT (GEN) | 5962-9223001MKA | SNJ54ABT827W | 5962-9450901QKA | SNJ54ABT843JT | 5962-9571201QLA |
| 54FCT825AT (GEN) | 5962-9223002M3A | CY54FCT827ATLMB | 5962-9224701M3A | SNJ54ABT843W | 5962-9571201QKA |
| 54FCT825AT (GEN) | 5962-9223002MLA | SL54LS83A/BEA | 7601401EA | 54FCT845A (GEN) | 5962-88675013A |
| 54FCT825B (GEN) | 5962-88674023A | SL54LS83A/BFA | 7601401FA | 54FCT845A (GEN) | 5962-8867501KA |
| 54FCT825B (GEN) | 5962-8867402KA | SNJ54ALS832AFK | 84145012A | 54FCT845A (GEN) | 5962-8867501LA |
| 54FCT825B (GEN) | 5962-8867402LA | SNJ54ALS832AJ | 8414501RA | 54FCT845B (GEN) | 5962-88675023A |
| 54FCT825BT (GEN) | 5962-9223003MKA | SNJ54ALS832AW | 8414501SA | 54FCT845B (GEN) | 5962-8867502KA |
| 54FCT825BT (GEN) | 5962-9223004M3A | SNJ54AS832BFK | 5962-88523012A | 54FCT845B (GEN) | 5962-8867502LA |
| 54FCT825BT (GEN) | 5962-9223004MLA | SNJ54AS832BJ | 5962-8852301RA | 54F85 (GEN) | 5962-86069012A |
| 54FCT825CT (GEN) | 5962-9223005MKA | SNJ54AS832BW | 5962-8852301SA | 54F85 (GEN) | 5962-8606901EA |
| 54FCT825CT (GEN) | 5962-9223006M3A | 54FCT833A (GEN) | 5962-89731013A | 54F85 (GEN) | 5962-8606901FA |
| 54FCT825CT (GEN) | 5962-9223006MLA | 54FCT833A (GEN) | 5962-8973101KA | 54HC85 (GEN) | 5962-8601301VFA |
| SNJ54AS825AFK | 5962-9078003M3A | 54FCT833A (GEN) | 5962-8973101LA | 54HC85 (GEN) | 86013012A |
| SNJ54AS825AJT | 5962-9078003MLA | 54FCT833B (GEN) | 5962-89731023A | 54HC85 (GEN) | 8601301FA |
| SNJ54AS825AW | 5962-9078003MKA | 54FCT833B (GEN) | 5962-8973102KA | 54HC85K01Q | 8601301XC |
| 54FCT825AT (GEN) | 5962-9223001M3A | 54FCT833B (GEN) | 5962-8973102LA | 54HC85K01V | 5962-8601301VXC |
| 54FCT825AT (GEN) | 5962-9223001MLA | SNJ54BCT8373AFK | 5962-9172501M3A | 54HC85K02Q | 8601301XA |
| 54FCT825BT (GEN) | 5962-9223003M3A | SNJ54BCT8373AJT | 5962-9172501MLA | 54HC85K02V | 5962-8601301VXA |
| 54FCT825BT (GEN) | 5962-9223003MLA | 54BCT8374A (GEN) | 5962-9172701M3A | CD54HC85F3A | 8601301EA |
| 54FCT825CT (GEN) | 5962-9223005M3A | 54BCT8374A (GEN) | 5962-9172701MLA | CD54HCT85F3A | 5962-8867201EA |
| 54FCT825CT (GEN) | 5962-9223005MLA | SNJ54BCT8374AFK | 5962-9172701Q3A | MM54C85 (GEN) | 7703701FA |
| 54AS826/B3A | 5962-9078004M3A | SNJ54BCT8374AJT | 5962-9172701QLA | MM54C85J/883 | 7703701EA |
| 54AS826/BKA | 5962-9078004MKA | 54ACTQ841FMQB | 5962-9220001MKA | SNJ54LS85FK | 5962-9754701Q2A |
| 54AS826/BLA | 5962-9078004MLA | 54ACTQ841LMQB | 5962-9220001M3A | SNJ54LS85J | 5962-9754701QEA |
| 54ACTQ827 (GEN) | 5962-9219901MKA | 54ACTQ841SDMQB | 5962-9220001MLA | SNJ54LS85W | 5962-9754701QFA |
| 54ACTQ827LMQB | 5962-9219901M3A | 54FCT841A (GEN) | 5962-88575013A | UT54ACS85PQAH | 5962H9653601QEA |
| 54ACTQ827SDMQB | 5962-9219901MLA | 54FCT841A (GEN) | 5962-8857501KA | UT54ACS85PQCH | 5962H9653601QEC |
| 54F827 (GEN) | 5962-9209001MKA | 54FCT841A (GEN) | 5962-8857501LA | UT54ACS85PVAH | 5962H9653601VEA |
| 54F827LMQB | 5962-9209001M3A | 54FCT841AT (GEN) | 5962-9222801M3A | UT54ACS85PVCH | 5962H9653601VEC |
| 54F827SDMQB | 5962-9209001MLA | 54FCT841AT (GEN) | 5962-9222801MKA | UT54ACS85UQAH | 5962H9653601QXA |
| 54FCT827A (GEN) | 5962-8950601KA | 54FCT841AT (GEN) | 5962-9222801MLA | UT54ACS85UQCH | 5962H9653601QXC |
| 54FCT827AT (GEN) | 5962-9224701MKA | 54FCT841B (GEN) | 5962-88575023A | UT54ACS85UVAH | 5962H9653601VXA |
| 54FCT827AT (GEN) | 5962-9224702M3A | 54FCT841B (GEN) | 5962-8857502KA | UT54ACS85UVCH | 5962H9653601VXC |
| 54FCT827AT (GEN) | 5962-9224702MLA | 54FCT841B (GEN) | 5962-8857502LA | UT54ACTS85PQAH | 5962H9653701QEA |
| 54FCT827B (GEN) | 5962-8950602KA | 54FCT841BT (GEN) | 5962-9222802M3A | UT54ACTS85PQCH | 5962H9653701QEC |
| 54FCT827BT (GEN) | 5962-9224703MKA | 54FCT841BT (GEN) | 5962-9222802MKA | UT54ACTS85PVAH | 5962H9653701VEA |
| 54FCT827BT (GEN) | 5962-9224704M3A | 54FCT841BT (GEN) | 5962-9222802MLA | UT54ACTS85PVCH | 5962H9653701VEC |
| 54FCT827BT (GEN) | 5962-9224704MLA | 54FCT841CT (GEN) | 5962-9222803M3A | UT54ACTS85UQAH | 5962H9653701QXA |
| 54FCT827CT (GEN) | 5962-9224705MKA | 54FCT841CT (GEN) | 5962-9222803MKA | UT54ACTS85UQCH | 5962H9653701QXC |
| 54FCT827CT (GEN) | 5962-9224706M3A | 54FCT841CT (GEN) | 5962-9222803MLA | UT54ACTS85UVAH | 5962H9653701VXA |
| 54FCT827CT (GEN) | 5962-9224706MLA | SNJ54ABT841FK | 5962-9676901Q3A | UT54ACTS85UVCH | 5962H9653701VXC |
| IDT54FCT827ADB | 5962-8950601LA | SNJ54ABT841JT | 5962-9676901QLA | SNJ54ABT853FK | 5962-9674601Q3A |
| IDT54FCT827ALB | 5962-89506013A | SNJ54ABT841W | 5962-9676901QKA | SNJ54ABT853JT | 5962-9674601QLA |
| IDT54FCT827ATDB | 5962-9224701MLA | 54FCT843A (GEN) | 5962-89758013A | SNJ54ABT853W | 5962-9674601QKA |
| IDT54FCT827ATLB | 5962-9224701M3A | 54FCT843A (GEN) | 5962-8975801KA | SNJ54ABT8543FK | 5962-9461501Q3A |
| IDT54FCT827BDB | 5962-8950602LA | 54FCT843A (GEN) | 5962-8975801LA | SNJ54ABT8543JT | 5962-9461501QXA |
| IDT54FCT827BLB | 5962-89506023A | 54FCT843B (GEN) | 5962-89758023A | 54ALS857 (GEN) | 5962-8753301KA |
| IDT54FCT827BTDB | 5962-9224703MLA | 54FCT843B (GEN) | 5962-8975802KA | SNJ54ALS857FK | 5962-87533013A |
| IDT54FCT827BTLB | 5962-9224703M3A | 54FCT843B (GEN) | 5962-8975802LA | SNJ54ALS857J | 5962-8753301LA |
| IDT54FCT827CTDB | 5962-9224705MLA | 54FCT843C (GEN) | 5962-89758033A | 54AC86 (GEN) | 5962-8955001VDA |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

| Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN |
|---|---|---|---|---|---|
| 54AC86DMQB | 5962-8955001CA | UT54ACTS86UVAH | 5962H9653901VXA | SNJ54ACT8990HV | 5962-9322801MXA |
| 54AC86FMQB | 5962-8955001DA | UT54ACTS86UVCH | 5962H9653901VXC | SNL54ABT8996FK | 5962-9681201Q3A |
| 54AC86K01Q | 5962-8955001XC | 54ACT86K01Q | 5962-9068702QXC | SNL54ABT8996JT | 5962-9681201QLA |
| 54AC86K01V | 5962-8955001VXC | 54ACT86K01V | 5962-9068702VXC | SNL54ABT8996W | 5962-9681201QKA |
| 54AC86K02Q | 5962-8955001XA | 54ACT86K02Q | 5962-9068702QXA | 54ACT8997 (GEN) | 5962-9323901M3A |
| 54AC86K02V | 5962-8955001VXA | 54ACT86K02V | 5962-9068702VXA | 54ACT8997 (GEN) | 5962-9323901MXA |
| 54AC86LMQB | 5962-89550012A | 54FCT861A (GEN) | 5962-89533013A | SNJ54ACT8997FK | 5962-9323901Q3A |
| 54HC86 (GEN) | 5962-8404601VDA | 54FCT861A (GEN) | 5962-8953301KA | SNJ54ACT8997JT | 5962-9323901QXA |
| 54HC86 (GEN) | 8404601AA | 54FCT861A (GEN) | 5962-8953301LA | SNJ54ACT8999FK | 5962-9674701Q3A |
| 54HC86 (GEN) | 8404601BA | 54FCT861B (GEN) | 5962-89533023A | HI1-549/883 | 5962-8513103EA |
| 54HC86K01Q | 8404601XC | 54FCT861B (GEN) | 5962-8953302KA | HI4-549/883 | 5962-85131032A |
| 54HC86K01V | 5962-8404601VXC | 54FCT861B (GEN) | 5962-8953302LA | HS-0549 (GEN) | 5962D9569402VEA |
| 54HC86K02Q | 8404601XA | 54FCT863A (GEN) | 5962-88661013A | HS1B-0549RH-Q | 5962D9569402VEC |
| 54HC86K02V | 5962-8404601VXA | 54FCT863A (GEN) | 5962-8866101KA | TLC549 (GEN) | 5962-9084502M2A |
| CD54HC86F3A | 8404601CA | 54FCT863A (GEN) | 5962-8866101LA | TLC549 (GEN) | 5962-9084502MPA |
| CD54HCT86F3A | 5962-8984401CA | 54FCT863B (GEN) | 5962-88661023A | 54LS90 (GEN) | 76032012A |
| SNJ54AC86FK | 5962-89550012A | 54FCT863B (GEN) | 5962-8866102KA | 54LS90 (GEN) | 7603201AA |
| SNJ54AC86J | 5962-8955001CA | 54FCT863B (GEN) | 5962-8866102LA | 54LS90 (GEN) | 7603201BA |
| SNJ54AC86W | 5962-8955001DA | SNJ54ABT8646FK | 5962-9458601Q3A | SNJ54LS90J | 7603201CA |
| SNJ54ACT86FK | 5962-9068701Q2A | SNJ54ABT8646JT | 5962-9458601QXA | SNJ54LS90W | 7603201DA |
| SNJ54ACT86J | 5962-9068701QCA | SNJ54ABT8652FK | 5962-9461601Q3A | 54C906 (GEN) | 7705601AA |
| SNJ54ACT86W | 5962-9068701QDA | SNJ54ABT8652JT | 5962-9461601QXA | 54C906 (GEN) | 7705601CA |
| SNJ54AHC86FK | 5962-9681601Q2A | SNJ54AS867FK | 5962-89668013A | 54C906 (GEN) | 7705601DA |
| SNJ54AHC86J | 5962-9681601QCA | SNJ54AS867JT | 5962-8966801LA | 54C922 (GEN) | 5962-8752101VA |
| SNJ54AHC86W | 5962-9681601QDA | SNJ54AS867W | 5962-8966801KA | SL54LS93/BAA | 7700101AA |
| SNJ54AHCT86FK | 5962-9681701Q2A | SNJ54AS869FK | 5962-89526013A | SL54LS93/BCA | 7700101CA |
| SNJ54AHCT86J | 5962-9681701QCA | SNJ54AS869JT | 5962-8952601LA | SL54LS93/BDA | 7700101DA |
| SNJ54AHCT86W | 5962-9681701QDA | SNJ54AS869W | 5962-8952601KA | SNJ54ALS996FK | 5962-89945013A |
| SNJ54ALS86FK | 5962-88621012A | 54ALS870 (GEN) | 5962-89889013A | SNJ54ALS996JT | 5962-8994501LA |
| SNJ54ALS86J | 5962-8862101CA | 54ALS870 (GEN) | 5962-8988901KA | SNJ54ALS996W | 5962-8994501KA |
| SNJ54ALS86W | 5962-8862101DA | 54ALS870 (GEN) | 5962-8988901LA | 54FCT2373 (GEN) | 5962-9302501M2A |
| SNJ54AS86AFK | 5962-9757201Q2A | SNJ54ALS873FK | 84032013A | 54FCT2373 (GEN) | 5962-9302501MRA |
| SNJ54AS86AJ | 5962-9757201QCA | SNJ54ALS873JT | 8403201LA | 54FCT2373 (GEN) | 5962-9302501MSA |
| SNJ54HC86FK | 84046012A | SNJ54ALS873W | 8403201KA | 54FCT2373A (GEN) | 5962-9302502M2A |
| SNJ54HC86J | 8404601CA | 54AS874 (GEN) | 5962-9152901M3A | 54FCT2373A (GEN) | 5962-9302502MRA |
| SNJ54HC86W | 8404601DA | 54AS874 (GEN) | 5962-9152901MJA | 54FCT2373A (GEN) | 5962-9302502MSA |
| SNJ54LVC86AFK | 5962-9761901Q2A | 54AS874 (GEN) | 5962-9152901MKA | 54FCT2373C (GEN) | 5962-9302503M2A |
| SNJ54LVC86AJ | 5962-9761901QCA | 54AS874 (GEN) | 5962-9152901MLA | 54FCT2373C (GEN) | 5962-9302503MRA |
| SNJ54LVC86AW | 5962-9761901QDA | SNJ54ALS874BFK | 84010013A | 54FCT2373C (GEN) | 5962-9302503MSA |
| UT54ACS86PQAH | 5962H9653801QCA | SNJ54ALS874BJT | 8401001LA | HCPL-550K | 5962-9085401KPC |
| UT54ACS86PQCH | 5962H9653801QCC | SNJ54ALS874BW | 8401001KA | HCPL-550K#100 | 5962-9085401KYA |
| UT54ACS86PVAH | 5962H9653801VCA | 54ALS876 (GEN) | 84010023A | HCPL-550K#100 | 5962-9085401KYC |
| UT54ACS86PVCH | 5962H9653801VCC | 54ALS876 (GEN) | 8401002KA | HCPL-550K#200 | 5962-9085401KPA |
| UT54ACS86UQAH | 5962H9653801QXA | 54ALS876 (GEN) | 8401002LA | HCPL-550K#300 | 5962-9085401KXA |
| UT54ACS86UQCH | 5962H9653801QXC | 54ALS880 (GEN) | 84032023A | UT550*QCR | 5962R96B0223Q*C |
| UT54ACS86UVAH | 5962H9653801VXA | 54ALS880 (GEN) | 8403202KA | UT550*VCR | 5962R96B0223V*C |
| UT54ACS86UVCH | 5962H9653801VXC | 54ALS880 (GEN) | 8403202LA | HCPL-5501 | 5962-9085401HPC |
| UT54ACTS86PQAH | 5962H9653901QCA | SNJ54AS885FK | 5962-89757013A | HCPL-5501#200 | 5962-9085401HPA |
| UT54ACTS86PQCH | 5962H9653901QCC | SNJ54AS885JT | 5962-8975701LA | HCPL-5501#100 | 5962-9085401HYA |
| UT54ACTS86PVAH | 5962H9653901VCA | SNJ54AS885W | 5962-8975701KA | HCPL-5501#100 | 5962-9085401HYC |
| UT54ACTS86PVCH | 5962H9653901VCC | 54ACT899 (GEN) | 5962-9314101MXA | HCPL-5501#300 | 5962-9085401HXA |
| UT54ACTS86UQAH | 5962H9653901QXA | 54ACT899LMQB | 5962-9314101M3A | 55ALS056 (GEN) | 5962-9062801RA |
| UT54ACTS86UQCH | 5962H9653901QXC | SNJ54ACT8990GB | 5962-9322801MYA | 55ALS056 (GEN) | 5962-9062801SA |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART II, Listed By Generic PIN

| Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN |
|---|---|---|---|---|---|
| 55ALS057 (GEN) | 5962-90629012A | AS5C512K8ECJ-15 | 5962-9560014QMA | AS5C512K8ECJ-25L/H | 5962-9561322HZC |
| 55ALS057 (GEN) | 5962-9062901RA | AS5C512K8ECJ-15L | 5962-9560013QMA | AS5C512K8ECJ-25L/H | 5962-9561327HZA |
| 55ALS057 (GEN) | 5962-9062901SA | AS5C512K8F-15 | 5962-9560014QTA | AS5C512K8ECJ-25L/H | 5962-9561327HZC |
| SNJ55107AFK | 5962-9690301Q2A | AS5C512K8F-15L | 5962-9560013QTA | AS5C512K8F-25 | 5962-9560003MTA |
| SNJ55107AJ | 5962-9690301QCA | AS5C512K8EC-17/H | 5962-9561310HNA | AS5C512K8F-25/H | 5962-9561308HUA |
| SNJ55107AW | 5962-9690301QDA | AS5C512K8EC-17/H | 5962-9561310HNC | AS5C512K8F-25/H | 5962-9561308HUC |
| 55108A (GEN) | 5962-9690302Q2A | AS5C512K8EC-17L/H | 5962-9561324HNA | AS5C512K8F-25/H | 5962-9561313HUA |
| 55108A (GEN) | 5962-9690302QCA | AS5C512K8EC-17L/H | 5962-9561324HNC | AS5C512K8F-25/H | 5962-9561313HUC |
| 55108A (GEN) | 5962-9690302QDA | AS5C512K8ECJ-17/H | 5962-9561310HZA | AS5C512K8F-25L | 5962-9560011QTA |
| 55109 (GEN) | 5962-87547022A | AS5C512K8ECJ-17/H | 5962-9561310HZC | AS5C512K8F-25L/H | 5962-9561322HUA |
| 55109 (GEN) | 5962-8754702CA | AS5C512K8ECJ-17L/H | 5962-9561324HZA | AS5C512K8F-25L/H | 5962-9561322HUC |
| 55109 (GEN) | 5962-8754702DA | AS5C512K8ECJ-17L/H | 5962-9561324HZC | AS5C512K8F-25L/H | 5962-9561327HUA |
| SNJ55110AFK | 5962-87547012A | AS5C512K8F-17/H | 5962-9561310HUA | AS5C512K8F-25L/H | 5962-9561327HUC |
| SNJ55110AJ | 5962-8754701CA | AS5C512K8F-17/H | 5962-9561310HUC | WMS512K8L-25FT | 5962-9561322HUC |
| SNJ55110AW | 5962-8754701DA | AS5C512K8F-17L/H | 5962-9561324HUA | 5C512K8-35L (GEN) | 5962-9560006MNA |
| SNJ55113FK | 5962-88744012A | AS5C512K8F-17L/H | 5962-9561324HUC | AS5C512K8EC-35 | 5962-9560002MNA |
| SNJ55113J | 5962-8874401EA | 5C512K8-20L (GEN) | 5962-9560008MNA | AS5C512K8EC-35/H | 5962-9561307HNA |
| SNJ55113W | 5962-8874401FA | AS5C512K8EC-20 | 5962-9560004MNA | AS5C512K8EC-35/H | 5962-9561307HNC |
| SNJ55114FK | 5962-88744022A | AS5C512K8EC-20/H | 5962-9561309HNA | AS5C512K8EC-35/H | 5962-9561312HNA |
| SNJ55114J | 5962-8874402EA | AS5C512K8EC-20/H | 5962-9561309HNC | AS5C512K8EC-35/H | 5962-9561312HNC |
| SNJ55114W | 5962-8874402FA | AS5C512K8EC-20L | 5962-9560012QNA | AS5C512K8EC-35L | 5962-9560010QNA |
| SNJ55115FK | 5962-88745012A | AS5C512K8EC-20L/H | 5962-9561323HNA | AS5C512K8EC-35L/H | 5962-9561321HNA |
| SNJ55115W | 5962-8874501FA | AS5C512K8EC-20L/H | 5962-9561323HNC | AS5C512K8EC-35L/H | 5962-9561321HNC |
| SNJ55116FK | 5962-88511012A | AS5C512K8ECJ-20 | 5962-9560004MMA | AS5C512K8EC-35L/H | 5962-9561326HNA |
| SNJ55116J | 5962-8851101EA | AS5C512K8ECJ-20/H | 5962-9561309HZA | AS5C512K8EC-35L/H | 5962-9561326HNC |
| 55117 (GEN) | 5962-88511022A | AS5C512K8ECJ-20/H | 5962-9561309HZC | AS5C512K8ECJ-35 | 5962-9560002MMA |
| 55117 (GEN) | 5962-8851102PA | AS5C512K8ECJ-20L | 5962-9560012QMA | AS5C512K8ECJ-35/H | 5962-9561307HZA |
| 55118 (GEN) | 5962-88511032A | AS5C512K8ECJ-20L/H | 5962-9561323HZA | AS5C512K8ECJ-35/H | 5962-9561307HZC |
| 55118 (GEN) | 5962-8851103EA | AS5C512K8ECJ-20L/H | 5962-9561323HZC | AS5C512K8ECJ-35/H | 5962-9561312HZA |
| 55119 (GEN) | 5962-88511042A | AS5C512K8F-20 | 5962-9560004MTA | AS5C512K8ECJ-35/H | 5962-9561312HZC |
| 55119 (GEN) | 5962-8851104PA | AS5C512K8F-20/H | 5962-9561309HUA | AS5C512K8ECJ-35L | 5962-9560010QMA |
| 55121 (GEN) | 5962-87769012A | AS5C512K8F-20/H | 5962-9561309HUC | AS5C512K8ECJ-35L/H | 5962-9561321HZA |
| 55121 (GEN) | 5962-8776901EA | AS5C512K8F-20L | 5962-9560012QTA | AS5C512K8ECJ-35L/H | 5962-9561321HZC |
| AS5C512K8EC-12 | 5962-9560016QNA | AS5C512K8F-20L/H | 5962-9561323HUA | AS5C512K8ECJ-35L/H | 5962-9561326HZA |
| AS5C512K8EC-12/H | 5962-9561329HNA | AS5C512K8F-20L/H | 5962-9561323HUC | AS5C512K8ECJ-35L/H | 5962-9561326HZC |
| AS5C512K8EC-12/H | 5962-9561329HNC | 5C512K8-25L (GEN) | 5962-9560007MNA | AS5C512K8F-35 | 5962-9560002MTA |
| AS5C512K8EC-12L | 5962-9560015QNA | AS5C512K8EC-25 | 5962-9560003MNA | AS5C512K8F-35/H | 5962-9561307HUA |
| AS5C512K8EC-12L/H | 5962-9561328HNA | AS5C512K8EC-25/H | 5962-9561308HNA | AS5C512K8F-35/H | 5962-9561307HUC |
| AS5C512K8EC-12L/H | 5962-9561328HNC | AS5C512K8EC-25/H | 5962-9561308HNC | AS5C512K8F-35/H | 5962-9561312HUA |
| AS5C512K8ECJ-12 | 5962-9560016QMA | AS5C512K8EC-25/H | 5962-9561313HNA | AS5C512K8F-35/H | 5962-9561312HUC |
| AS5C512K8ECJ-12/H | 5962-9561329HZA | AS5C512K8EC-25/H | 5962-9561313HNC | AS5C512K8F-35L | 5962-9560010QTA |
| AS5C512K8ECJ-12/H | 5962-9561329HZC | AS5C512K8EC-25L | 5962-9560011QNA | AS5C512K8F-35L/H | 5962-9561321HUA |
| AS5C512K8ECJ-12L | 5962-9560015QMA | AS5C512K8EC-25L/H | 5962-9561322HNA | AS5C512K8F-35L/H | 5962-9561321HUC |
| AS5C512K8ECJ-12L/H | 5962-9561328HZA | AS5C512K8EC-25L/H | 5962-9561322HNC | AS5C512K8F-35L/H | 5962-9561326HUA |
| AS5C512K8ECJ-12L/H | 5962-9561328HZC | AS5C512K8EC-25L/H | 5962-9561327HNA | AS5C512K8F-35L/H | 5962-9561326HUC |
| AS5C512K8F-12 | 5962-9560016QTA | AS5C512K8EC-25L/H | 5962-9561327HNC | 5C512K8-45L (GEN) | 5962-9560005MNA |
| AS5C512K8F-12/H | 5962-9561329HUA | AS5C512K8ECJ-25 | 5962-9560003MMA | AS5C512K8EC-45 | 5962-9560001MNA |
| AS5C512K8F-12/H | 5962-9561329HUC | AS5C512K8ECJ-25/H | 5962-9561308HZA | AS5C512K8EC-45/H | 5962-9561306HNA |
| AS5C512K8F-12L | 5962-9560015QTA | AS5C512K8ECJ-25/H | 5962-9561308HZC | AS5C512K8EC-45/H | 5962-9561306HNC |
| AS5C512K8F-12L/H | 5962-9561328HUA | AS5C512K8ECJ-25/H | 5962-9561313HZA | AS5C512K8EC-45/H | 5962-9561311HNA |
| AS5C512K8F-12L/H | 5962-9561328HUC | AS5C512K8ECJ-25/H | 5962-9561313HZC | AS5C512K8EC-45/H | 5962-9561311HNC |
| AS5C512K8EC-15 | 5962-9560014QNA | AS5C512K8ECJ-25L | 5962-9560011QMA | AS5C512K8EC-45L | 5962-9560009QNA |
| AS5C512K8EC-15L | 5962-9560013QNA | AS5C512K8ECJ-25L/H | 5962-9561322HZA | AS5C512K8EC-45L/H | 5962-9561320HNA |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

| Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN |
|---|---|---|---|---|---|
| AS5C512K8EC-45L/H | 5962-9561320HNC | SMJ55166-80HKCM | 5962-9564301QYC | HCPL-553K | 5962-8767906KPC |
| AS5C512K8EC-45L/H | 5962-9561325HNA | SNJ55LBC172FK | 5962-9076503Q2A | HCPL-553K#100 | 5962-8767906KYA |
| AS5C512K8EC-45L/H | 5962-9561325HNC | SNJ55LBC172J | 5962-9076503QEA | HCPL-553K#100 | 5962-8767906KYC |
| AS5C512K8ECJ-45 | 5962-9560001MMA | SNJ55LBC172W | 5962-9076503QFA | HCPL-553K#200 | 5962-8767906KPA |
| AS5C512K8ECJ-45/H | 5962-9561306HZA | SNJ55LBC173FK | 5962-9076604Q2A | HCPL-553K#300 | 5962-8767906KXA |
| AS5C512K8ECJ-45/H | 5962-9561306HZC | SNJ55LBC173J | 5962-9076604QEA | SG55451BL/883B | 77049022A |
| AS5C512K8ECJ-45/H | 5962-9561311HZA | SNJ55LBC173W | 5962-9076604QFA | SG55451Y/883B | 7704902PA |
| AS5C512K8ECJ-45/H | 5962-9561311HZC | SNJ55LBC174FK | 5962-9076504Q2A | SNJ55451BFK | 77049022A |
| AS5C512K8ECJ-45L | 5962-9560009QMA | SNJ55LBC174J | 5962-9076504QEA | SNJ55451BJG | 7704902PA |
| AS5C512K8ECJ-45L/H | 5962-9561320HZA | SNJ55LBC174W | 5962-9076504QFA | SG55452BL/883B | 77049012A |
| AS5C512K8ECJ-45L/H | 5962-9561320HZC | SNJ55LBC175FK | 5962-9076603Q2A | SG55452BY/883B | 7704901PA |
| AS5C512K8ECJ-45L/H | 5962-9561325HZA | SNJ55LBC175J | 5962-9076603QEA | SNJ55452BFK | 77049012A |
| AS5C512K8ECJ-45L/H | 5962-9561325HZC | SNJ55LBC175W | 5962-9076603QFA | SNJ55452BJG | 7704901PA |
| AS5C512K8F-45 | 5962-9560001MTA | SNJ55LBC176FK | 5962-9318301Q2A | SNJ55453BFK | 5962-9563301Q2A |
| AS5C512K8F-45/H | 5962-9561306HUA | SNJ55LBC176JG | 5962-9318301QPA | SNJ55453BJG | 5962-9563301QPA |
| AS5C512K8F-45/H | 5962-9561306HUC | 55182 (GEN) | 79008012A | SG55454BL/883B | 5962-88715012A |
| AS5C512K8F-45/H | 5962-9561311HUA | 55182 (GEN) | 7900801CA | SG55464L/883B | 5962-88715022A |
| AS5C512K8F-45/H | 5962-9561311HUC | 55182 (GEN) | 7900801DA | SG55464Y/883B | 5962-8871502PA |
| AS5C512K8F-45L | 5962-9560009QTA | 55183 (GEN) | 7900901AA | SG55474L/883B | 5962-88715032A |
| AS5C512K8F-45L/H | 5962-9561320HUA | SNJ55183FK | 79009012A | SG55474Y/883B | 5962-8871503PA |
| AS5C512K8F-45L/H | 5962-9561320HUC | SNJ55183J | 7900901CA | LMC555 (GEN) | 5962-8950305CA |
| AS5C512K8F-45L/H | 5962-9561325HUA | SNJ55183W | 7900901DA | LMC555 (GEN) | 5962-8950305GA |
| AS5C512K8F-45L/H | 5962-9561325HUC | SNJ55188FK | 5962-86889012A | LMC555J/883C | 5962-8950305PA |
| AS5C512K8EC-55/H | 5962-9561305HNA | SNJ55188J | 5962-8688901CA | TLC555MFKB | 5962-89503012A |
| AS5C512K8EC-55/H | 5962-9561305HNC | SNJ55188W | 5962-8688901DA | TLC555MJGB | 5962-8950301PA |
| AS5C512K8EC-55L/H | 5962-9561319HNA | 55189 (GEN) | 5962-86888012A | 55500EFD/BZA | 8601801ZA |
| AS5C512K8EC-55L/H | 5962-9561319HNC | 55189 (GEN) | 5962-8688801CA | 55500EFJ/BXA | 8601801XA |
| AS5C512K8ECJ-55/H | 5962-9561305HZA | SNJ55189AFK | 5962-86888022A | 55500EJ/BQA | 8601801QA |
| AS5C512K8ECJ-55/H | 5962-9561305HZC | SNJ55189AJ | 5962-8688802CA | 55501EFD/BZA | 8601802ZA |
| AS5C512K8ECJ-55L/H | 5962-9561319HZA | SNJ55189AW | 5962-8688802DA | 55501EFJ/BXA | 8601802XA |
| AS5C512K8ECJ-55L/H | 5962-9561319HZC | 55ALS194 (GEN) | 5962-88648012A | 55501EJ/BQA | 8601802QA |
| AS5C512K8F-55/H | 5962-9561305HUA | 55ALS194 (GEN) | 5962-8864801EA | 55551 (GEN) | 5962-8605401XA |
| AS5C512K8F-55/H | 5962-9561305HUC | 55ALS194 (GEN) | 5962-8864801FA | 55551 (GEN) | 5962-8605401YA |
| AS5C512K8F-55L/H | 5962-9561319HUA | 55ALS195 (GEN) | 5962-88649012A | 55552 (GEN) | 5962-8605402XA |
| AS5C512K8F-55L/H | 5962-9561319HUC | 55ALS195 (GEN) | 5962-8864901EA | 55552 (GEN) | 5962-8605402YA |
| 55138 (GEN) | 5962-8851201QEA | 55ALS195 (GEN) | 5962-8864901FA | 55553 (GEN) | 5962-8605501XA |
| 55ALS160 (GEN) | 5962-89680012A | 5521 (GEN) | 5962-9087901MVA | 55553 (GEN) | 5962-8605501YA |
| 55ALS160 (GEN) | 5962-8968001RA | HCPL-5531 | 5962-8767902PC | 55554 (GEN) | 5962-8605502XA |
| 55ALS160 (GEN) | 5962-8968001SA | HCPL-5531#100 | 5962-8767902YA | 55554 (GEN) | 5962-8605502YA |
| 55ALS161 (GEN) | 5962-89681012A | HCPL-5531#100 | 5962-8767902YC | 55563A (GEN) | 5962-9081301MXA |
| 55ALS161 (GEN) | 5962-8968101RA | HCPL-5531#200 | 5962-8767902PA | 55564A (GEN) | 5962-9081302MXA |
| 55ALS161 (GEN) | 5962-8968101SA | HCPL-5531#300 | 5962-8767902XA | TLC556MFKB | 5962-89503022A |
| 55161-70 (GEN) | 5962-9454902MXA | SNJ55LVDS31FK | 5962-9762101Q2A | TLC556MJB | 5962-8950302CA |
| 55161-70 (GEN) | 5962-9454902MYA | SNJ55LVDS31J | 5962-9762101QEA | IP5560J-DESC | 5962-8672201EA |
| SMJ55161-75GBM | 5962-9454903QXA | SNJ55LVDS31W | 5962-9762101QFA | 5565250 (GEN) | 5962-8751427XA |
| SMJ55161-75HKCM | 5962-9454903QYC | SNV55LVDS31W | 5962-9762101VFA | 5565250 (GEN) | 5962-8751427YA |
| SMJ55161-80GBM | 5962-9454901MXA | SNJ55LVDS32FK | 5962-9762201Q2A | 5565250 (GEN) | 5962-8751427ZA |
| SMJ55161-80HKCM | 5962-9454901MYC | SNJ55LVDS32FK | 5962-9762202Q2A | AD558SD/883B | 5962-8778901EA |
| SMJ55166 (GEN) | 5962-9564302QXA | SNJ55LVDS32J | 5962-9762201QEA | AD558SE/883B | 5962-87789012A |
| SMJ55166 (GEN) | 5962-9564302QYC | SNJ55LVDS32W | 5962-9762201QFA | AD558TD/883B | 5962-8778902EA |
| SMJ55166-75GBM | 5962-9564303QXA | SNV55LVDS32W | 5962-9762201VFA | AD558TE/883B | 5962-87789022A |
| SMJ55166-75HKCM | 5962-9564303QYC | 5537 (GEN) | 5962-8760802PA | 55LBC976 (GEN) | 5962-9672901QXA |
| SMJ55166-80GBM | 5962-9564301QXA | 5539 (GEN) | 5962-8606401CA | 55976A1 (GEN) | 5962-9689301NYD |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

| Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN |
|---|---|---|---|---|---|
| SNJ55976A1WD | 5962-9689301QXA | MT5C6404C-20883C | 5962-8969204XA | MT5C6408EC-20L/883C | 5962-3829457MUA |
| 55976A2 (GEN) | 5962-9689302NYD | MT5C6404EC-20883C | 5962-8969204ZA | MT5C6408F-20/883C | 5962-3829458MMA |
| SNJ55976A2WD | 5962-9689302QXA | MT5C6404C-25883C | 5962-8969202XA | MT5C6408F-20L/883C | 5962-3829457MMA |
| HCPL-560K | 5962-9085501KPC | MT5C6404EC-25883C | 5962-8969202ZA | 5C6408-25 (GEN) | 5962-3829414MUA |
| HCPL-560K#100 | 5962-9085501KYA | MT5C6404C-35 | 5962-8685924TA | 5C6408-25 (GEN) | 5962-3829415MUA |
| HCPL-560K#100 | 5962-9085501KYC | MT5C6404C-35L | 5962-8685923TA | 5C6408-25 (GEN) | 5962-8969102NA |
| HCPL-560K#200 | 5962-9085501KPA | MT5C6404C-45 | 5962-8685922TA | 5C6408-25 (GEN) | 5962-8969102YA |
| HCPL-560K#300 | 5962-9085501KXA | MT5C6404C-45L | 5962-8685921TA | MT5C6408C-25 | 5962-3829456MZA |
| SL560AC (GEN) | 5962-9052001XA | MT5C6404C-55 | 5962-8685920TA | MT5C6408C-25L | 5962-3829455MZA |
| 56001-20 (GEN) | 5962-8951201XA | MT5C6404C-55L | 5962-8685919TA | MT5C6408EC-25 | 5962-3829456MUA |
| 56001-20 (GEN) | 5962-8951201YC | MT5C6405EC-70L | 5962-8685911UA | MT5C6408EC-25L | 5962-3829455MUA |
| 56001A-20 (GEN) | 5962-8951202XA | MT5C6405C-35 | 5962-8685918LA | MT5C6408ECW-20/883 | 5962-3829458MYA |
| 56001A-20 (GEN) | 5962-8951202YC | MT5C6405C-35L | 5962-8685917LA | MT5C6408ECW-20L/88 | 5962-3829457MYA |
| 56002-40 (GEN) | 5962-9456401QXA | MT5C6405EC-35 | 5962-8685918UA | MT5C6408ECW-25 | 5962-3829456MYA |
| HCPL-5601 | 5962-9085501HPC | MT5C6405EC-35L | 5962-8685917UA | MT5C6408ECW-25L | 5962-3829455MYA |
| HCPL-5601#100 | 5962-9085501HYA | MT5C6405C-45 | 5962-8685916LA | MT5C6408F-25 | 5962-3829456MMA |
| HCPL-5601#100 | 5962-9085501HYC | MT5C6405EC-45 | 5962-8685916UA | MT5C6408F-25L | 5962-3829455MMA |
| HCPL-5601#200 | 5962-9085501HPA | MT5C6405EC-45L | 5962-8685915UA | 5C6408-35 (GEN) | 5962-3829412MMA |
| HCPL-5601#300 | 5962-9085501HXA | MT5C6405C-55 | 5962-8685914LA | 5C6408-35 (GEN) | 5962-3829412MUA |
| TLC5602 (GEN) | 5962-9469301Q2A | MT5C6405C-55L | 5962-8685913LA | 5C6408-35 (GEN) | 5962-3829413MMA |
| TLC5602 (GEN) | 5962-9469301QRA | MT5C6405EC-55 | 5962-8685914UA | 5C6408-35 (GEN) | 5962-3829413MUA |
| TLC5618AMFKB | 5962-9955702Q2A | MT5C6405EC-55L | 5962-8685913UA | MT5C6408C-35 | 5962-3829454MZA |
| TLC5618AMJGB | 5962-9955702QPA | MT5C6405C-70 | 5962-8685912LA | MT5C6408C-35L | 5962-3829453MZA |
| TLV5618AMFKB | 5962-9955701Q2A | MT5C6405C-70L | 5962-8685911LA | MT5C6408EC-35 | 5962-3829454MUA |
| TLV5618AMJGB | 5962-9955701QPA | MT5C6405EC-70 | 5962-8685912UA | MT5C6408EC-35L | 5962-3829453MUA |
| 562 (GEN) | 8100801JA | 5C6408-45 (GEN) | 5962-3829410MUA | MT5C6408ECW-35 | 5962-3829454MYA |
| 563 (GEN) | 8100802JA | MT5C6408C-12 | 5962-3829447MZA | MT5C6408ECW-35L | 5962-3829453MYA |
| HCPL-563K | 5962-9800102KPC | MT5C6408C-12L | 5962-3829446MZA | MT5C6408F-35 | 5962-3829454MMA |
| HCPL-5631 | 8102802PC | MT5C6408EC-12 | 5962-3829447MUA | MT5C6408F-35L | 5962-3829453MMA |
| HCPL-5631#100 | 8102802YA | MT5C6408EC-12L | 5962-3829446MUA | 5C6408-45 (GEN) | 5962-3829410MMA |
| HCPL-5631#100 | 8102802YC | MT5C6408ECW-12 | 5962-3829447MYA | 5C6408-45 (GEN) | 5962-3829411MMA |
| HCPL-5631#200 | 8102802PA | MT5C6408ECW-12L | 5962-3829446MYA | 5C6408-45 (GEN) | 5962-3829411MUA |
| HCPL-5631#300 | 8102802ZA | MT5C6408F-12 | 5962-3829447MMA | 5C6408-45 (GEN) | 5962-8552506TA |
| HCPL-563K#100 | 5962-9800102KYA | MT5C6408F-12L | 5962-3829446MMA | 5C6408-45 (GEN) | 5962-8552506YA |
| HCPL-563K#100 | 5962-9800102KYC | 5C6408-15 (GEN) | 5962-8969106NA | MT5C6408C-45 | 5962-3829451MZA |
| HCPL-563K#200 | 5962-9800102KPA | 5C6408-15 (GEN) | 5962-8969106YA | MT5C6408C-45 | 5962-3829452MZA |
| HCPL-563K#300 | 5962-9800102KZA | MT5C6408C-15 | 5962-3829419MZA | MT5C6408EC-45 | 5962-3829451MUA |
| TLV5638MFKB | 5962-9957601Q2A | MT5C6408C-15L | 5962-3829418MZA | MT5C6408EC-45 | 5962-3829452MUA |
| TLV5638MJGB | 5962-9957601QPA | MT5C6408EC-15 | 5962-3829419MUA | MT5C6408ECW-45 | 5962-3829451MYA |
| 5C6401-35 (GEN) | 5962-8601501XA | MT5C6408EC-15L | 5962-3829418MUA | MT5C6408ECW-45 | 5962-3829452MYA |
| 5C6401-35 (GEN) | 5962-8601501ZA | MT5C6408ECW-15 | 5962-3829419MYA | MT5C6408F-45 | 5962-3829451MMA |
| 5C6401-35 (GEN) | 5962-8601502XA | MT5C6408ECW-15L | 5962-3829418MYA | MT5C6408F-45 | 5962-3829452MMA |
| 5C6401-35 (GEN) | 5962-8601502ZA | MT5C6408F-15 | 5962-3829419MMA | 5C6408-55 (GEN) | 5962-3829408MMA |
| 5C6401-45 (GEN) | 5962-8601503XA | MT5C6408F-15L | 5962-3829418MMA | 5C6408-55 (GEN) | 5962-3829408MUA |
| 5C6401-45 (GEN) | 5962-8601503ZA | 5C6408-20 (GEN) | 5962-3829416MMA | 5C6408-55 (GEN) | 5962-3829409MMA |
| 5C6401-45 (GEN) | 5962-8601504XA | 5C6408-20 (GEN) | 5962-3829416MUA | 5C6408-55 (GEN) | 5962-3829409MUA |
| 5C6401-45 (GEN) | 5962-8601504ZA | 5C6408-20 (GEN) | 5962-3829417MMA | MT5C6408C-55 | 5962-3829450MZA |
| 5C6401-55 (GEN) | 5962-8601505XA | 5C6408-20 (GEN) | 5962-3829417MUA | MT5C6408C-55L | 5962-3829449MZA |
| 5C6401-55 (GEN) | 5962-8601505ZA | 5C6408-20 (GEN) | 5962-8969104NA | MT5C6408EC-55 | 5962-3829450MUA |
| 5C6401-55 (GEN) | 5962-8601506XA | 5C6408-20 (GEN) | 5962-8969104YA | MT5C6408ECW-55 | 5962-3829450MYA |
| 5C6401-55 (GEN) | 5962-8601506ZA | MT5C6408C-20/883C | 5962-3829458MZA | MT5C6408ECW-55L | 5962-3829449MUA |
| MT5C6404C-15883C | 5962-8969206XA | MT5C6408C-20L/883C | 5962-3829457MZA | MT5C6408ECW-55L | 5962-3829449MYA |
| MT5C6404EC-15883C | 5962-8969206ZA | MT5C6408EC-20/883C | 5962-3829458MUA | MT5C6408F-55 | 5962-3829450MMA |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART II, Listed By Generic PIN

| Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN |
|---|---|---|---|---|---|
| MT5C6408F-55L | 5962-3829449MMA | WS57C010F-70CMB | 5962-8961413MYC | WS57C291C-35ZMB | 5962-88734033C |
| 5C6408-70 (GEN) | 5962-3829407MMA | WS57C010F-70DMB | 5962-8961408MXA | WS57C291C-45CMB | 5962-87650043A |
| 5C6408-70 (GEN) | 5962-3829407MUA | WS57C010F-70DMB | 5962-8961413MXA | WS57C291C-45CMB | 5962-87650043C |
| MT5C6408C-70 | 5962-3829448MZA | WS57C010F-90CMB | 5962-8961407MYA | WS57C291C-45FMB | 5962-8765004KA |
| MT5C6408EC-70 | 5962-3829448MUA | WS57C010F-90CMB | 5962-8961407MYC | WS57C291C-45KMB | 5962-8873402LA |
| MT5C6408ECW-70 | 5962-3829448MYA | WS57C010F-90DMB | 5962-8961407MXA | WS57C291C-45TMB | 5962-8765004LA |
| MT5C6408F-70 | 5962-3829448MMA | HCPL-5701#100 | 5962-8981001YA | WS57C291C-45ZMB | 5962-88734023A |
| MT5C6405C-45L | 5962-8685915LA | HCPL-5701#100 | 5962-8981001YC | WS57C291C-45ZMB | 5962-88734023C |
| 565AS (GEN) | 5962-9689201VKA | HCPL-5701#300 | 5962-8981001XA | WS57C291C-50CMB | 5962-87650013A |
| 565AS (GEN) | 5962-9689201VLA | HCPL-570K#300 | 5962-8981002KXA | WS57C291C-50CMB | 5962-87650013C |
| 565AT (GEN) | 5962-9689202VLA | AD571SD/883B | 5962-8680202VA | WS57C291C-50FMB | 5962-8765001KA |
| AD565ASD/QMLV | 5962-9689201VJA | AD571SD/QMLV | 5962-8680203VVA | WS57C291C-50TMB | 5962-8765001LA |
| AD565ATD/QMLV | 5962-9689202VJA | WS57C128FB-70CMB | 5962-8766108YC | WS57C291C-55CMB | 5962-87650023A |
| HS0-565BRH-Q | 5962R9675502V9A | WS57C128FB-70DMB | 5962-8766108XA | WS57C291C-55CMB | 5962-87650023C |
| HS1-565BRH-Q | 5962R9675502VJC | WS57C191C-25HMB | 5962-8873404KA | WS57C291C-55FMB | 5962-8765002KA |
| HS-565A (GEN) | 5962R9675501TJC | WS57C191C-35HMB | 5962-8873403KA | WS57C291C-55KMB | 5962-8873401LA |
| HS-565A (GEN) | 5962R9675501TXC | WS57C191C-35YMB | 5962-8873403JA | WS57C291C-55TMB | 5962-8765002LA |
| HS-565A (GEN) | 5962R9675501V9A | WS57C191C-45DMB | 5962-8765004JA | WS57C291C-55ZMB | 5962-88734013A |
| HS-565A (GEN) | 5962R9675501VJC | WS57C191C-45HMB | 5962-8873402KA | WS57C291C-55ZMB | 5962-88734013C |
| HS-565A (GEN) | 5962R9675501VXC | WS57C191C-45YMB | 5962-8873402JA | ACS573 (GEN) | 5962F9672401VRC |
| HS9-565BRH-Q | 5962R9675502VXC | WS57C191C-50DMB | 5962-8765001JA | ACS573KMSR | 5962F9672401VXC |
| HCPL-5651 | 8102805PC | WS57C191C-55DMB | 5962-8765002JA | ACTS573 (GEN) | 5962F9672501VRC |
| HCPL-5651#200 | 8102805PA | WS57C191C-55HMB | 5962-8873401KA | ACTS573 (GEN) | 5962F9672501VXC |
| 567 (GEN) | 5962-8700301CA | WS57C191C-55YMB | 5962-8873401JA | AD573SD/883 | 5962-8850501RA |
| 567 (GEN) | 5962-8700301PA | WS57C191C-25YMB | 5962-8873404JA | HCPL-573K | 5962-8978503KPC |
| AD567SD/883B | 5962-8780101XA | 57C256F-45 | 5962-8606310UA | HCPL-573K#100 | 5962-8978503KYA |
| 568A (GEN) | 5962-9458201MRA | 57C256F-45 | 5962-8606310XA | HCPL-573K#100 | 5962-8978503KYC |
| AD568SE (GEN) | 5962-89808023A | 57C256F-45 | 5962-8606310YA | HCPL-573K#200 | 5962-8978503KPA |
| AD568SQ (GEN) | 5962-8980801JA | 57C256F-45 | 5962-8606310YC | HCPL-573K#300 | 5962-8978503KZA |
| AD568SQ/883B | 5962-8980801LA | AT27C256R-45/UA | 5962-8606310UA | HCS573 (GEN) | 5962R9579401V9A |
| AD570SD/883B | 5962-8680201VA | 57C256F-55 | 5962-8606309UA | HCS573 (GEN) | 5962R9579401VRC |
| HCPL-570K | 5962-8981002KPC | 57C256F-55 | 5962-8606309XA | HCS573KMSR | 5962R9579401VXC |
| HCPL-570K#200 | 5962-8981002KPA | 57C256F-55 | 5962-8606309YA | ACS573 (GEN) | 5962F9672402V9A |
| HI-5700S (GEN) | 5962-9467801MXA | 57C256F-55 | 5962-8606309YC | ACS573 (GEN) | 5962F9672402VRC |
| HCPL-5701 | 5962-8981001PC | AT27C256R-55/XA | 5962-8606309XA | ACS573 (GEN) | 5962F9672402VXC |
| HCPL-5701#200 | 5962-8981001PA | AT27C256R-55/YA | 5962-8606309YA | ACTS573-02 (GEN) | 5962F9672502V9A |
| HCPL-570K#100 | 5962-8981002KYA | AT27C256R-55/YC | 5962-8606309YC | ACTS573-02 (GEN) | 5962F9672502VRC |
| HCPL-570K#100 | 5962-8981002KYC | 57C256F-70 | 5962-8606308XA | ACTS573-02 (GEN) | 5962F9672502VXC |
| WS57C010F-35CMB | 5962-8961416MYA | 57C256F-70 | 5962-8606308YA | ACTS573-02 (GEN) | 5962R9672502TRC |
| WS57C010F-35CMB | 5962-8961416MYC | 57C256F-70 | 5962-8606308YC | ACTS573-02 (GEN) | 5962R9672502TXC |
| WS57C010F-35DMB | 5962-8961416MXA | WS57C291C-25CMB | 5962-87650053A | HCPL-5731 | 5962-8978501PC |
| WS57C010F-45CMB | 5962-8961415MYA | WS57C291C-25CMB | 5962-87650053C | HCPL-5731#100 | 5962-8978501YA |
| WS57C010F-45CMB | 5962-8961415MYC | WS57C291C-25FMB | 5962-8765005KA | HCPL-5731#100 | 5962-8978501YC |
| WS57C010F-45DMB | 5962-8961415MXA | WS57C291C-25KMB | 5962-8873404LA | HCPL-5731#200 | 5962-8978501PA |
| WS57C010F-55CMB | 5962-8961409MYA | WS57C291C-25TMB | 5962-8765005LA | HCPL-5731#300 | 5962-8978501ZA |
| WS57C010F-55CMB | 5962-8961409MYC | WS57C291C-25ZMB | 5962-88734043A | 574AT (GEN) | 5962-8512704YA |
| WS57C010F-55CMB | 5962-8961414MYA | WS57C291C-25ZMB | 5962-88734043C | 574AU (GEN) | 5962-8512703YA |
| WS57C010F-55CMB | 5962-8961414MYC | WS57C291C-35CMB | 5962-87650033A | 574ZA (GEN) | 5962-85127053A |
| WS57C010F-55DMB | 5962-8961409MXA | WS57C291C-35CMB | 5962-87650033C | 574ZA (GEN) | 5962-8512705XC |
| WS57C010F-55DMB | 5962-8961414MXA | WS57C291C-35FMB | 5962-8765003KA | 574ZB (GEN) | 5962-85127063A |
| WS57C010F-70CMB | 5962-8961408MYA | WS57C291C-35KMB | 5962-8873403LA | 574ZB (GEN) | 5962-8512706XC |
| WS57C010F-70CMB | 5962-8961408MYC | WS57C291C-35TMB | 5962-8765003LA | AD574ATD/883B | 5962-8512702XA |
| WS57C010F-70CMB | 5962-8961413MYA | WS57C291C-35ZMB | 5962-88734033A | AD574ATD/QMLR | 5962R8512702VXA |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

| Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN |
|---|---|---|---|---|---|
| AD574ATD/QMLV | 5962-8512702VXA | WS57C43C-45-DMB | 5962-9065803JC | WS57C49C-35CMB | 5962-87515073A |
| AD574ATE/883B | 5962-85127023A | WS57C43C-45-FMB | 5962-9065803KA | WS57C49C-35CMB | 5962-87515073C |
| AD574ATF/QMLR | 5962R8512702VZA | WS57C43C-45-FMB | 5962-9065803KC | WS57C49C-35CMB | 5962-87515083A |
| AD574ATF/QMLV | 5962-8512702VZA | WS57C43C-45-TMB | 5962-9065803LA | WS57C49C-35CMB | 5962-87515083C |
| AD574AUD/883B | 5962-8512701XA | WS57C43C-45-TMB | 5962-9065803LC | WS57C49C-35DMB | 5962-8751507JA |
| AD574AUD/QMLR | 5962R8512701VXA | WS57C43C-55-CMB | 5962-90658023A | WS57C49C-35DMB | 5962-8751508JA |
| AD574AUD/QMLV | 5962-8512701VXA | WS57C43C-55-CMB | 5962-90658023C | WS57C49C-35FMB | 5962-8751507KA |
| AD574AUE/883B | 5962-85127013A | WS57C43C-55-DMB | 5962-9065802JA | WS57C49C-35FMB | 5962-8751508KA |
| AD574AUF/QMLR | 5962R8512701VZA | WS57C43C-55-DMB | 5962-9065802JC | WS57C49C-35HMB | 5962-9080303MKA |
| AD574AUF/QMLV | 5962-8512701VZA | WS57C43C-55-FMB | 5962-9065802KA | WS57C49C-35HMB | 5962-9080307MKA |
| HCTS574 (GEN) | 5962R9575801V9A | WS57C43C-55-FMB | 5962-9065802KC | WS57C49C-35KMB | 5962-9080303MLA |
| HCTS574DMSR | 5962R9575801VRC | WS57C43C-55-TMB | 5962-9065802LA | WS57C49C-35KMB | 5962-9080307MLA |
| HCTS574KMSR | 5962R9575801VXC | WS57C43C-55-TMB | 5962-9065802LC | WS57C49C-35TMB | 5962-8751507LA |
| HI1-574ATD/883 | 5962-8512704XA | WS57C43C-70-CMB | 5962-90658013A | WS57C49C-35TMB | 5962-8751508LA |
| HI1-574AUD/883 | 5962-8512703XA | WS57C43C-70-CMB | 5962-90658013C | WS57C49C-35YMB | 5962-9080307MJA |
| HS574AT (GEN) | 5962-85127083C | WS57C43C-70-DMB | 5962-9065801JA | WS57C49C-35ZMB | 5962-9080303M3A |
| HS574AT (GEN) | 5962-8512708XC | WS57C43C-70-DMB | 5962-9065801JC | WS57C49C-35ZMB | 5962-9080303M3C |
| HS574AU (GEN) | 5962-85127073C | WS57C43C-70-FMB | 5962-9065801KA | WS57C49C-35ZMB | 5962-9080307M3A |
| HS574AU (GEN) | 5962-8512707XC | WS57C43C-70-FMB | 5962-9065801KC | WS57C49C-35ZMB | 5962-9080307M3C |
| MX574ATD/883B | 5962-8512702XC | WS57C43C-70-TMB | 5962-9065801LA | WS57C49C-45CMB | 5962-87515013A |
| MX574ATE/883B | 5962-85127023C | WS57C43C-70-TMB | 5962-9065801LC | WS57C49C-45CMB | 5962-87515013C |
| MX574ATQ/883B | 5962-8512702XA | WS57C45-25HMB | 5962-8873504KA | WS57C49C-45CMB | 5962-87515053A |
| MX574AUD/883B | 5962-8512701XC | WS57C45-25HMB | 5962-8981502KA | WS57C49C-45CMB | 5962-87515053C |
| 57401 (GEN) | 5962-87791012A | WS57C45-25KMB | 5962-8873504LA | WS57C49C-45CMB | 5962-87515093A |
| 57401 (GEN) | 5962-8779101EA | WS57C45-25KMB | 5962-8981502LA | WS57C49C-45CMB | 5962-87515093C |
| 57401A (GEN) | 5962-87791032A | WS57C45-25ZMB | 5962-88735043A | WS57C49C-45DMB | 5962-8751501JA |
| 57401A (GEN) | 5962-8779103EA | WS57C45-25ZMB | 5962-88735043C | WS57C49C-45DMB | 5962-8751505JA |
| 57L401D (GEN) | 5962-8779109EA | WS57C45-25ZMB | 5962-89815023A | WS57C49C-45DMB | 5962-8751509JA |
| C57401 (GEN) | 5962-87791052A | WS57C45-25ZMB | 5962-89815023C | WS57C49C-45FMB | 5962-8751501KA |
| C57401 (GEN) | 5962-8779105EA | WS57C45-35CMB | 5962-87529023A | WS57C49C-45FMB | 5962-8751505KA |
| C57401A (GEN) | 5962-87791072A | WS57C45-35CMB | 5962-87529023C | WS57C49C-45FMB | 5962-8751509KA |
| C57401A (GEN) | 5962-8779107EA | WS57C45-35FMB | 5962-8752902KA | WS57C49C-45HMB | 5962-9080302MKA |
| 57L4013D (GEN) | 5962-8779111EA | WS57C45-35HMB | 5962-8873502KA | WS57C49C-45HMB | 5962-9080306MKA |
| 57402 (GEN) | 5962-87791022A | WS57C45-35HMB | 5962-8873503KA | WS57C49C-45KMB | 5962-9080302MLA |
| 57402 (GEN) | 5962-8779102VA | WS57C45-35HMB | 5962-8981501KA | WS57C49C-45KMB | 5962-9080306MLA |
| 57402A (GEN) | 5962-87791042A | WS57C45-35KMB | 5962-8873502LA | WS57C49C-45TMB | 5962-8751501LA |
| 57402A (GEN) | 5962-8779104VA | WS57C45-35KMB | 5962-8873503LA | WS57C49C-45TMB | 5962-8751505LA |
| 57L402D (GEN) | 5962-8779110VA | WS57C45-35KMB | 5962-8981501LA | WS57C49C-45TMB | 5962-8751509LA |
| C57402 (GEN) | 5962-87791062A | WS57C45-35TMB | 5962-8752902LA | WS57C49C-45YMB | 5962-9080306MJA |
| C57402 (GEN) | 5962-8779106VA | WS57C45-35ZMB | 5962-88735023A | WS57C49C-45ZMB | 5962-9080302M3A |
| C57402A (GEN) | 5962-87791082A | WS57C45-35ZMB | 5962-88735023C | WS57C49C-45ZMB | 5962-9080302M3C |
| C57402A (GEN) | 5962-8779108VA | WS57C45-35ZMB | 5962-88735033A | WS57C49C-45ZMB | 5962-9080306M3A |
| WS57C43C-35-CMB | 5962-90658043A | WS57C45-35ZMB | 5962-88735033C | WS57C49C-45ZMB | 5962-9080306M3C |
| WS57C43C-35-CMB | 5962-90658043C | WS57C45-35ZMB | 5962-89815013A | WS57C49C-55CMB | 5962-87515023A |
| WS57C43C-35-DMB | 5962-9065804JA | WS57C45-35ZMB | 5962-89815013C | WS57C49C-55CMB | 5962-87515023C |
| WS57C43C-35-DMB | 5962-9065804JC | WS57C45-45CMB | 5962-87529013A | WS57C49C-55CMB | 5962-87515063A |
| WS57C43C-35-FMB | 5962-9065804KA | WS57C45-45CMB | 5962-87529013C | WS57C49C-55CMB | 5962-87515063C |
| WS57C43C-35-FMB | 5962-9065804KC | WS57C45-45FMB | 5962-8752901KA | WS57C49C-55CMB | 5962-87515103A |
| WS57C43C-35-TMB | 5962-9065804LA | WS57C45-45HMB | 5962-8873501KA | WS57C49C-55CMB | 5962-87515103C |
| WS57C43C-35-TMB | 5962-9065804LC | WS57C45-45KMB | 5962-8873501LA | WS57C49C-55DMB | 5962-8751502JA |
| WS57C43C-45-CMB | 5962-90658033A | WS57C45-45TMB | 5962-8752901LA | WS57C49C-55DMB | 5962-8751506JA |
| WS57C43C-45-CMB | 5962-90658033C | WS57C45-45ZMB | 5962-88735013A | WS57C49C-55DMB | 5962-8751510JA |
| WS57C43C-45-DMB | 5962-9065803JA | WS57C45-45ZMB | 5962-88735013C | WS57C49C-55FMB | 5962-8751502KA |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

| Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN |
|---|---|---|---|---|---|
| WS57C49C-55FMB | 5962-8751506KA | AD581UH/883B | 5962-8688203XA | MN5906CD/883 | 5962-9326201MVC |
| WS57C49C-55FMB | 5962-8751510KA | AS58C1001ECA-15/883 | 5962-3826718QUA | 592 (GEN) | 84185022A |
| WS57C49C-55HMB | 5962-9080301MKA | AS58C1001ECA-20/883 | 5962-3826717QUA | 592 (GEN) | 8418502CA |
| WS57C49C-55HMB | 5962-9080305MKA | AS58C1001ECA-25/883 | 5962-3826716QUA | 592 (GEN) | 8418502HA |
| WS57C49C-55KMB | 5962-9080301MLA | AS58C1001F-15/883C | 5962-3826718QMA | 592 (GEN) | 8418502IA |
| WS57C49C-55KMB | 5962-9080305MLA | AS58C1001F-20/883C | 5962-3826717QMA | AD598SD/883B | 5962-9067101MRA |
| WS57C49C-55TMB | 5962-8751502LA | AS58C1001F-25/883C | 5962-3826716QMA | TL598 (GEN) | 5962-9166801Q2A |
| WS57C49C-55TMB | 5962-8751506LA | AS58C1001SF-15/883C | 5962-3826718QNA | TL598 (GEN) | 5962-9166801QEA |
| WS57C49C-55TMB | 5962-8751510LA | AS58C1001SF-20/883C | 5962-3826717QNA | 600 (GEN) | 5962-8686401LA |
| WS57C49C-55YMB | 5962-9080305MJA | AS58C1001SF-25/883C | 5962-3826716QNA | 600 (GEN) | 5962-8686401XA |
| WS57C49C-55ZMB | 5962-9080301M3A | MIC5822 (GEN) | 5962-8764101EA | AD600SQ/883B | 5962-9457201MEA |
| WS57C49C-55ZMB | 5962-9080301M3C | AD584S (GEN) | 5962-3812801M2A | UT600*QCR | 5962R96B0224Q*C |
| WS57C49C-55ZMB | 5962-9080305M3A | AD584SH/QMLV | 5962-3812801VGA | UT600*VCR | 5962R96B0224V*C |
| WS57C49C-55ZMB | 5962-9080305M3C | AD584SH/QMLVR | 5962R3812801VGA | XQV600-4CB228 | 5962-9957301QYC |
| WS57C49C-70CMB | 5962-87515033A | AD584T (GEN) | 5962-3812802M2A | XQV600-4CB228 | 5962-9957301QZC |
| WS57C49C-70CMB | 5962-87515033C | AD584TH/QMLV | 5962-3812802VGA | XQVR600-4CB228 | 5962R9957301QYC |
| WS57C49C-70DMB | 5962-8751503JA | AD584TH/QMLVR | 5962R3812802VGA | XQVR600-4CB228 | 5962R9957301QZC |
| WS57C49C-70FMB | 5962-8751503KA | MX584S (GEN) | 5962-3812803M2C | XQV600-4HQ240 | 5962-9957301NTB |
| WS57C49C-70TMB | 5962-8751503LA | MX584SH/883B | 5962-3812803MGC | XQVR600-4HQ240 | 5962R9957301NTB |
| WS57C49C-90CMB | 5962-87515043A | MX584SQ/883B | 5962-3812803MPA | XQV600-4BG432 | 5962-9957301NUA |
| WS57C49C-90CMB | 5962-87515043C | MX584T (GEN) | 5962-3812804M2C | XQVR600-4BG432 | 5962R9957301NUA |
| WS57C49C-90DMB | 5962-8751504JA | MX584TH/883B | 5962-3812804MGC | DG601AK/883 | 5962-9089101MEA |
| WS57C49C-90-MB | 5962-8751504KA | MX584TQ/883B | 5962-3812804MPA | DG601AZ/883 | 5962-9089101M2A |
| WS57C49C-90TMB | 5962-8751504LA | AD585SE/883B | 5962-87540012A | LMF60-100 (GEN) | 5962-9096701MCA |
| MPT57571 | 5962-9958901QXC | AD585SQ/883B | 5962-8754001CA | 602A (GEN) | 5962-9073201MPA |
| MPT57604 | 5962-9959001QXC | AD586SQ/883B | 5962-8982401PA | AD602SQ/883B | 5962-9457202MEA |
| MPT57605 | 5962-0151301QXC | AD586TQ/883B | 5962-8982402PA | AD603SQ/883B | 5962-9457203MPA |
| HCPL-5761 | 5962-8947701PC | AD587S (GEN) | 5962-8982501PA | TSPC603EMAB/C2L | 5962-9760801QXA |
| HCPL-5761#100 | 5962-8947701YA | AD587TQ/883B | 5962-8982502PA | TSPC603EMAB/C3L | 5962-9760802QXA |
| HCPL-5761#100 | 5962-8947701YC | AD587UQ/883B | 5962-8982503PA | TSPC603EMAB/C4L | 5962-9760803QXA |
| HCPL-5761#200 | 5962-8947701PA | AD588S (GEN) | 5962-89728012A | TSPC603EMAB/C5L | 5962-9760804QXA |
| HCPL-5761#300 | 5962-8947701XA | AD588S (GEN) | 5962-8972801EA | TSPC603RMGSB/Q10L | 5962-9760807QYA |
| 57C64-70 (GEN) | 8510207YA | AD588T (GEN) | 5962-8972802EA | TSPC603RMGSB/Q12L | 5962-9760808QYA |
| 57C64-70 (GEN) | 8510207ZA | AD588TE/883B | 5962-89728022A | TSPC603RMGSB/Q14L | 5962-9760809QYA |
| HCPL-576K | 5962-8947702KPC | AD589TH/QMLV | 5962-8992901VXA | TSPC603RMGSB/Q6LC | 5962-9760805QYA |
| HCPL-576K#100 | 5962-8947702KYA | AD590JF/883B | 5962-8757101XA | TSPC603RMGSB/Q8LC | 5962-9760806QYA |
| HCPL-576K#100 | 5962-8947702KYC | AD590JH/883B | 5962-8757101YA | 604A (GEN) | 5962-8956401EA |
| HCPL-576K#200 | 5962-8947702KPA | AD590K (GEN) | 5962-8757102VXA | 604A (GEN) | 5962-9650801NXA |
| HCPL-576K#300 | 5962-8947702KXA | AD590K (GEN) | 5962-8757102VYA | 604A (GEN) | 5962-9650801QEA |
| AD578S (GEN) | 5962-8865801XA | AD590KF/883B | 5962-8757102XA | 604A (GEN) | 5962-9650802NXA |
| AD578T (GEN) | 5962-8865802XA | AD590KH/883B | 5962-8757102YA | LM604 (GEN) | 5962-8963901VA |
| AD578ZS (GEN) | 5962-8865803XA | AD590LF/883B | 5962-8757103XA | 605 (GEN) | 5962-9064401MRA |
| AD578ZT (GEN) | 5962-8865804XA | AD590LF/QMLR | 5962R8757103VXA | 605 (GEN) | 5962-9064401MXA |
| AD580SH/883B | 5962-8686101XA | AD590LF/QMLV | 5962-8757103VXA | LMF60-50 (GEN) | 5962-9096702MCA |
| AD580TH/883B | 5962-8686102XA | AD590LH/883B | 5962-8757103YA | 605 (GEN) | 5962-9064401NYA |
| AD580UH/883B | 5962-8686103XA | AD590LH/QMLR | 5962R8757103VYA | 605 (GEN) | 5962-9064402NYA |
| MX580SH/883B | 5962-8686101XC | AD590LH/QMLV | 5962-8757103VYA | LMC6061AMJ/883 | 5962-9460401MPA |
| MX580TH/883B | 5962-8686102XC | AD590MF/883B | 5962-8757104XA | LMC6062AMJ/883 | 5962-9209403MPA |
| MX580UH/883B | 5962-8686103XC | AD590MF/QMLV | 5962-8757104VXA | LMC6064AMJ/883 | 5962-9209303MCA |
| MIC5800 (GEN) | 5962-8764002CA | AD590MH/883B | 5962-8757104YA | 610 (GEN) | 5962-8947601LA |
| MIC5801AJBQ | 5962-8764001WA | AD590MH/QMLV | 5962-8757104VYA | EP610-15 (GEN) | 5962-8947603LA |
| AD581SH/883B | 5962-8688201XA | HI5905 (GEN) | 5962-9859101NXB | PALCE610H-20 (GEN) | 5962-9169501M3A |
| AD581TH/883B | 5962-8688202XA | MN5906CD/883 | 5962-9326201MVA | PALCE610H-20 (GEN) | 5962-9169501MLA |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

| Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN |
|---|---|---|---|---|---|
| EP610-25 (GEN) | 5962-8947602LA | 6116SA70 (GEN) | 8403613XA | BUS61563 (GEN) | 5962-8869201YA |
| DG611AK/883 | 5962-9325501MEA | IDT6116LA70DB | 8403612JA | BUS61563 (GEN) | 5962-8869201ZA |
| DG611AZ/883 | 5962-9325501M2A | IDT6116LA70TDB | 8403612LA | BUS61564 (GEN) | 5962-8869202TA |
| 6116-82 (GEN) | 8403604JA | IDT6116SA70DB | 8403613JA | BUS61564 (GEN) | 5962-8869202YA |
| 6116-83 (GEN) | 8403605JA | IDT6116SA70TDB | 8403613LA | BUS61564 (GEN) | 5962-8869202ZA |
| 6116-120/3A | 84036153A | 6116L-90 (GEN) | 8403616YA | BUS61565 (GEN) | 5962-8869203YA |
| 6116-120/KA | 8403615KA | 6116LA90 (GEN) | 84036163A | BUS61565 (GEN) | 5962-8869203ZA |
| 6116-120/XA | 8403615XA | 6116LA90 (GEN) | 8403616KA | BUS61569 (GEN) | 5962-9173401HYA |
| 6116-120/YA | 8403615YA | 6116LA90 (GEN) | 8403616XA | BUS61569 (GEN) | 5962-9173401HZA |
| IDT6116LA120DB | 8403615JA | IDT6116LA90DB | 8403616JA | BUS61569 (GEN) | 5962-9173404HYA |
| IDT6116LA120TDB | 8403615LA | IDT6116LA90TDB | 8403616LA | BUS61569 (GEN) | 5962-9173404HZA |
| 6116SA20 (GEN) | 5962-8969002XA | QP6117A-35LMB | 8403614XA | BUS61570 (GEN) | 5962-9173402HYA |
| IDT6116SA20DB | 5962-8969002JA | QP6117A-45LMB | 8403609XA | BUS61570 (GEN) | 5962-9173402HZA |
| IDT6116SA20TDB | 5962-8969002LA | QP6117A-55LMB | 8403611XA | BUS61571 (GEN) | 5962-9173403HYA |
| QP6116A-205DMB | 5962-8969002JA | LM6118 (GEN) | 5962-9156501M2A | BUS61571 (GEN) | 5962-9173403HZA |
| QP6116A-20LMB | 5962-89690023A | LM6118 (GEN) | 5962-9156501MPA | BU-61580BS1-110 | 5962-9306503HXC |
| 6116LA25 (GEN) | 5962-8874002XA | DG612AK/883 | 5962-9325502MEA | BU-61580BS1-110 | 5962-9306503HXC |
| 6116LA25DB | 5962-8874002JA | DG612AZ/883 | 5962-9325502M2A | BU-61580BS1-130 | 5962-9306503HXC |
| 6116LA25TDB | 5962-8874002LA | LM612A (GEN) | 5962-9300201MPA | BU-61580BS1-130 | 5962-9306503HXC |
| 6116SA25 (GEN) | 5962-8969001XA | LM6121 (GEN) | 5962-9081201MGA | BU-61580BS1-140 | 5962-9306503HXA |
| IDT6116SA25DB | 5962-8969001JA | LM6121 (GEN) | 5962-9081201MPA | BU-61580BS1-140 | 5962-9306503HXA |
| IDT6116SA25TDB | 5962-8969001LA | LM6125 (GEN) | 5962-9081501MGA | BU-61580BS1-150 | 5962-9306503HXA |
| QP6116A-25DMB | 5962-8969001JA | DG613AK/883 | 5962-9325503MEA | BU-61580BS1-150 | 5962-9306503HXA |
| QP6116A-25LMB | 5962-89690013A | DG613AZ/883 | 5962-9325503M2A | BU-61580BV1-110 | 5962-9306503HYC |
| 6116LA35 (GEN) | 5962-8874001XA | LM613/M2A | 5962-9300301M2A | BU-61580BV1-110 | 5962-9306503HYC |
| 6116LA35DB | 5962-8874001JA | LM613AMJ/883 | 5962-9300301MEA | BU-61580BV1-130 | 5962-9306503HYC |
| 6116LA35TDB | 5962-8874001LA | 6N134/883B | 8102801EC | BU-61580BV1-130 | 5962-9306503HYC |
| QP6116A-35DMB | 8403614JA | 6N134/883B#100 | 8102801UA | BU-61580BV1-140 | 5962-9306503HYA |
| QP6116A-35LMB | 84036143A | 6N134/883B#100 | 8102801UC | BU-61580BV1-140 | 5962-9306503HYA |
| 6116LA45 (GEN) | 84036083A | 6N134/883B#200 | 8102801EA | BU-61580BV1-150 | 5962-9306503HYA |
| 6116LA45 (GEN) | 8403608KA | 6N134/883B#300 | 8102801TA | BU-61580BV1-150 | 5962-9306503HYA |
| 6116LA45 (GEN) | 8403608XA | LM614A (GEN) | 5962-9300401MEA | BU-61580BV2-110 | 5962-9306504HYC |
| IDT6116LA45DB | 8403608JA | 6N140A | 8302401EA | BU-61580BV2-130 | 5962-9306504HYC |
| IDT6116LA45TDB | 8403608LA | 6N140A | 8302401EC | BU-61580BV2-140 | 5962-9306504HYA |
| IDT6116SA45DB | 8403609JA | 6N140A | 8302401XA | BU-61580BV2-150 | 5962-9306504HYA |
| IDT6116SA45TDB | 8403609LA | 6N140A/883B | 8302401EC | BU-61580J1-110 | 5962-9306503HZC |
| QP6116A-45DMB | 8403609JA | 6N140A/883B#100 | 8302401YA | BU-61580J1-130 | 5962-9306503HZC |
| QP6116A-45LMB | 84036093A | 6N140A/883B#100 | 8302401YC | BU-61580S1-110 | 5962-9306503HXC |
| 6116-55/3A | 84036103A | 6N140A/883B#200 | 8302401EA | BU-61580S1-110 | 5962-9306503HXC |
| 6116-55/KA | 8403610KA | 6N140A/883B#300 | 8302401XA | BU-61580S1-130 | 5962-9306503HXC |
| 6116-55/XA | 8403610XA | 6N140A/883B#600 | 8302401ZA | BU-61580S1-130 | 5962-9306503HXC |
| 6116-55/YA | 8403610YA | 6N140A/883B#600 | 8302401ZC | BU-61580S1-140 | 5962-9306503HXA |
| IDT6116LA55DB | 8403610JA | LM6142AMJ/883 | 5962-9550301QPA | BU-61580S1-140 | 5962-9306503HXA |
| IDT6116LA55TDB | 8403610LA | BUS61553 (GEN) | 5962-8869201XA | BU-61580S1-150 | 5962-9306503HXA |
| IDT6116SA55DB | 8403611JA | BUS61554 (GEN) | 5962-8869202XA | BU-61580S1-150 | 5962-9306503HXA |
| IDT6116SA55TDB | 8403611LA | BUS61554 (GEN) | 5962-8869202XC | BU-61580V1-110 | 5962-9306503HYC |
| QP6116A-55DMB | 8403611JA | BUS61555 (GEN) | 5962-8869203XA | BU-61580V1-110 | 5962-9306503HYC |
| QP6116A-55LMB | 84036113A | BUS61556 (GEN) | 5962-8869204XA | BU-61580V1-130 | 5962-9306503HYC |
| 6116LA70 (GEN) | 84036123A | BUS61559 (GEN) | 5962-9173401HXA | BU-61580V1-130 | 5962-9306503HYC |
| 6116LA70 (GEN) | 8403612KA | BUS61559 (GEN) | 5962-9173404HXA | BU-61580V1-140 | 5962-9306503HYA |
| 6116LA70 (GEN) | 8403612XA | BUS61560 (GEN) | 5962-9173402HXA | BU-61580V1-140 | 5962-9306503HYA |
| 6116SA70 (GEN) | 84036133A | BUS61561 (GEN) | 5962-9173403HXA | BU-61580V1-150 | 5962-9306503HYA |
| 6116SA70 (GEN) | 8403613KA | BUS61563 (GEN) | 5962-8869201TA | BU-61580V1-150 | 5962-9306503HYA |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART II, Listed By Generic PIN

| Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN |
|---|---|---|---|---|---|
| BU-61580V2-110 | 5962-9306504HYC | BU-61580DV3-140 | 5962-9306532HYA | BU-61581BV1-110 | 5962-9306507HYC |
| BU-61580V2-130 | 5962-9306504HYC | BU-61580DV3-150 | 5962-9306532HYA | BU-61581BV1-110 | 5962-9306507HYC |
| BU-61580V2-140 | 5962-9306504HYA | BU-61580DV3-150 | 5962-9306532HYA | BU-61581BV1-130 | 5962-9306507HYC |
| BU-61580V2-150 | 5962-9306504HYA | BU-61581DS3-110 | 5962-9306536HXC | BU-61581BV1-130 | 5962-9306507HYC |
| BU-61580BS2-110 | 5962-9306504HXC | BU-61581DS3-110 | 5962-9306536HXC | BU-61581BV1-140 | 5962-9306507HYA |
| BU-61580BS2-110 | 5962-9306504HXC | BU-61581DS3-130 | 5962-9306536HXC | BU-61581BV1-140 | 5962-9306507HYA |
| BU-61580BS2-130 | 5962-9306504HXC | BU-61581DS3-130 | 5962-9306536HXC | BU-61581BV1-150 | 5962-9306507HYA |
| BU-61580BS2-130 | 5962-9306504HXC | BU-61581DS3-140 | 5962-9306536HXA | BU-61581BV1-150 | 5962-9306507HYA |
| BU-61580BS2-140 | 5962-9306504HXA | BU-61581DS3-140 | 5962-9306536HXA | BU-61581J1-110 | 5962-9306507HZC |
| BU-61580BS2-140 | 5962-9306504HXA | BU-61581DS3-150 | 5962-9306536HXA | BU-61581J1-130 | 5962-9306507HZC |
| BU-61580BS2-150 | 5962-9306504HXA | BU-61581DS3-150 | 5962-9306536HXA | BU-61581S1-110 | 5962-9306507HXC |
| BU-61580BS2-150 | 5962-9306504HXA | BU-61580 (GEN) | 5962-9306512HXA | BU-61581S1-110 | 5962-9306507HXC |
| BU-61580BV2-110 | 5962-9306504HYC | BU-61580 (GEN) | 5962-9306512HYA | BU-61581S1-130 | 5962-9306507HXC |
| BU-61580BV2-130 | 5962-9306504HYC | BU-61580DG6-110 | 5962-9306533HNC | BU-61581S1-130 | 5962-9306507HXC |
| BU-61580BV2-140 | 5962-9306504HYA | BU-61580DG6-110 | 5962-9306533HNC | BU-61581S1-140 | 5962-9306507HXA |
| BU-61580BV2-150 | 5962-9306504HYA | BU-61580DG6-130 | 5962-9306533HNC | BU-61581S1-140 | 5962-9306507HXA |
| BU-61580J2-110 | 5962-9306504HZC | BU-61580DG6-130 | 5962-9306533HNC | BU-61581S1-150 | 5962-9306507HXA |
| BU-61580J2-130 | 5962-9306504HZC | BU-61580DG6-140 | 5962-9306533HNA | BU-61581S1-150 | 5962-9306507HXA |
| BU-61580S2-110 | 5962-9306504HXC | BU-61580DG6-140 | 5962-9306533HNA | BU-61581V1-110 | 5962-9306507HYC |
| BU-61580S2-110 | 5962-9306504HXC | BU-61580DG6-150 | 5962-9306533HNA | BU-61581V1-110 | 5962-9306507HYC |
| BU-61580S2-130 | 5962-9306504HXC | BU-61580DG6-150 | 5962-9306533HNA | BU-61581V1-130 | 5962-9306507HYC |
| BU-61580S2-130 | 5962-9306504HXC | BU-61580DS6-110 | 5962-9306533HXC | BU-61581V1-130 | 5962-9306507HYC |
| BU-61580S2-140 | 5962-9306504HXA | BU-61580DS6-110 | 5962-9306533HXC | BU-61581V1-140 | 5962-9306507HYA |
| BU-61580S2-140 | 5962-9306504HXA | BU-61580DS6-130 | 5962-9306533HXC | BU-61581V1-140 | 5962-9306507HYA |
| BU-61580S2-150 | 5962-9306504HXA | BU-61580DS6-130 | 5962-9306533HXC | BU-61581V1-150 | 5962-9306507HYA |
| BU-61580S2-150 | 5962-9306504HXA | BU-61580DS6-140 | 5962-9306533HXA | BU-61581V1-150 | 5962-9306507HYA |
| BU-61580V2-110 | 5962-9306504HYC | BU-61580DS6-140 | 5962-9306533HXA | BU-61581BS2-110 | 5962-9306508HXC |
| BU-61580V2-130 | 5962-9306504HYC | BU-61580DS6-150 | 5962-9306533HXA | BU-61581BS2-110 | 5962-9306508HXC |
| BU-61580V2-140 | 5962-9306504HYA | BU-61580DS6-150 | 5962-9306533HXA | BU-61581BS2-130 | 5962-9306508HXC |
| BU-61580V2-150 | 5962-9306504HYA | BU-61580DV6-110 | 5962-9306533HYC | BU-61581BS2-130 | 5962-9306508HXC |
| BU-61580 (GEN) | 5962-9306511HXA | BU-61580DV6-110 | 5962-9306533HYC | BU-61581BS2-140 | 5962-9306508HXA |
| BU-61580 (GEN) | 5962-9306511HYA | BU-61580DV6-130 | 5962-9306533HYC | BU-61581BS2-140 | 5962-9306508HXA |
| BU-61580DG3-110 | 5962-9306532HNC | BU-61580DV6-130 | 5962-9306533HYC | BU-61581BS2-150 | 5962-9306508HXA |
| BU-61580DG3-110 | 5962-9306532HNC | BU-61580DV6-140 | 5962-9306533HYA | BU-61581BS2-150 | 5962-9306508HXA |
| BU-61580DG3-130 | 5962-9306532HNC | BU-61580DV6-140 | 5962-9306533HYA | BU-61581BV2-110 | 5962-9306508HYC |
| BU-61580DG3-130 | 5962-9306532HNC | BU-61580DV6-150 | 5962-9306533HYA | BU-61581BV2-110 | 5962-9306508HYC |
| BU-61580DG3-140 | 5962-9306532HNA | BU-61580DV6-150 | 5962-9306533HYA | BU-61581BV2-130 | 5962-9306508HYC |
| BU-61580DG3-140 | 5962-9306532HNA | BU-61581DS6-110 | 5962-9306537HXC | BU-61581BV2-130 | 5962-9306508HYC |
| BU-61580DG3-150 | 5962-9306532HNA | BU-61581DS6-110 | 5962-9306537HXC | BU-61581BV2-140 | 5962-9306508HYA |
| BU-61580DG3-150 | 5962-9306532HNA | BU-61581DS6-130 | 5962-9306537HXC | BU-61581BV2-140 | 5962-9306508HYA |
| BU-61580DS3-110 | 5962-9306532HXC | BU-61581DS6-130 | 5962-9306537HXC | BU-61581BV2-150 | 5962-9306508HYA |
| BU-61580DS3-110 | 5962-9306532HXC | BU-61581DS6-140 | 5962-9306537HXA | BU-61581BV2-150 | 5962-9306508HYA |
| BU-61580DS3-130 | 5962-9306532HXC | BU-61581DS6-140 | 5962-9306537HXA | BU-61581J2-110 | 5962-9306508HZC |
| BU-61580DS3-130 | 5962-9306532HXC | BU-61581DS6-150 | 5962-9306537HXA | BU-61581J2-130 | 5962-9306508HZC |
| BU-61580DS3-140 | 5962-9306532HXA | BU-61581DS6-150 | 5962-9306537HXA | BU-61581S2-110 | 5962-9306508HXC |
| BU-61580DS3-140 | 5962-9306532HXA | BU-61581BS1-110 | 5962-9306507HXC | BU-61581S2-110 | 5962-9306508HXC |
| BU-61580DS3-150 | 5962-9306532HXA | BU-61581BS1-110 | 5962-9306507HXC | BU-61581S2-130 | 5962-9306508HXC |
| BU-61580DS3-150 | 5962-9306532HXA | BU-61581BS1-130 | 5962-9306507HXC | BU-61581S2-130 | 5962-9306508HXC |
| BU-61580DV3-110 | 5962-9306532HYC | BU-61581BS1-130 | 5962-9306507HXC | BU-61581S2-140 | 5962-9306508HXA |
| BU-61580DV3-110 | 5962-9306532HYC | BU-61581BS1-140 | 5962-9306507HXA | BU-61581S2-140 | 5962-9306508HXA |
| BU-61580DV3-130 | 5962-9306532HYC | BU-61581BS1-140 | 5962-9306507HXA | BU-61581S2-150 | 5962-9306508HXA |
| BU-61580DV3-130 | 5962-9306532HYC | BU-61581BS1-150 | 5962-9306507HXA | BU-61581S2-150 | 5962-9306508HXA |
| BU-61580DV3-140 | 5962-9306532HYA | BU-61581BS1-150 | 5962-9306507HXA | BU-61581V2-110 | 5962-9306508HYC |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART II, Listed By Generic PIN

| Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN |
|---|---|---|---|---|---|
| BU-61581V2-110 | 5962-9306508HYC | BU61582F1-140 | 5962-9688701HYA | BU-61585S2-130 | 5962-9306518HXC |
| BU-61581V2-130 | 5962-9306508HYC | BU61582G1-140 | 5962-9688701HZA | BU-61585S2-140 | 5962-9306518HXA |
| BU-61581V2-130 | 5962-9306508HYC | BU61582D2-110 | 5962-9688702HXC | BU-61585S2-140 | 5962-9306518HXA |
| BU-61581V2-140 | 5962-9306508HYA | BU61582F2-110 | 5962-9688702HYC | BU-61585S2-150 | 5962-9306518HXA |
| BU-61581V2-140 | 5962-9306508HYA | BU61582G2-110 | 5962-9688702HZC | BU-61585S2-150 | 5962-9306518HXA |
| BU-61581V2-150 | 5962-9306508HYA | BU61582D2-140 | 5962-9688702HXA | BU-61585V2-110 | 5962-9306518HYC |
| BU-61581V2-150 | 5962-9306508HYA | BU61582F2-140 | 5962-9688702HYA | BU-61585V2-110 | 5962-9306518HYC |
| BU-61581 (GEN) | 5962-9306515HXA | BU61582G2-140 | 5962-9688702HZA | BU-61585V2-130 | 5962-9306518HYC |
| BU-61581 (GEN) | 5962-9306515HYA | BU61582D3-110 | 5962-9688707HXC | BU-61585V2-130 | 5962-9306518HYC |
| BU-61581DG3-110 | 5962-9306536HNC | BU61582F3-110 | 5962-9688707HYC | BU-61585V2-140 | 5962-9306518HYA |
| BU-61581DG3-110 | 5962-9306536HNC | BU61582G3-110 | 5962-9688707HZC | BU-61585V2-140 | 5962-9306518HYA |
| BU-61581DG3-130 | 5962-9306536HNC | BU61582D3-140 | 5962-9688707HXA | BU-61585V2-150 | 5962-9306518HYA |
| BU-61581DG3-130 | 5962-9306536HNC | BU61582F3-140 | 5962-9688707HYA | BU-61585V2-150 | 5962-9306518HYA |
| BU-61581DG3-140 | 5962-9306536HNA | BU61582G3-140 | 5962-9688707HZA | BU-61585 (GEN) | 5962-9306521HXA |
| BU-61581DG3-140 | 5962-9306536HNA | BU61583D0-110 | 5962-9688706HXC | BU-61585 (GEN) | 5962-9306521HYA |
| BU-61581DG3-150 | 5962-9306536HNA | BU61583F0-110 | 5962-9688706HYC | BU-61585DG3-110 | 5962-9306538HNC |
| BU-61581DG3-150 | 5962-9306536HNA | BU61583G0-110 | 5962-9688706HZC | BU-61585DG3-110 | 5962-9306538HNC |
| BU-61581DV3-110 | 5962-9306536HYC | BU61583D0-140 | 5962-9688706HXA | BU-61585DG3-130 | 5962-9306538HNC |
| BU-61581DV3-110 | 5962-9306536HYC | BU61583F0-140 | 5962-9688706HYA | BU-61585DG3-130 | 5962-9306538HNC |
| BU-61581DV3-130 | 5962-9306536HYC | BU61583G0-140 | 5962-9688706HZA | BU-61585DG3-140 | 5962-9306538HNA |
| BU-61581DV3-130 | 5962-9306536HYC | BU61583D1-110 | 5962-9688703HXC | BU-61585DG3-140 | 5962-9306538HNA |
| BU-61581DV3-140 | 5962-9306536HYA | BU61583F1-110 | 5962-9688703HYC | BU-61585DG3-150 | 5962-9306538HNA |
| BU-61581DV3-140 | 5962-9306536HYA | BU61583G1-110 | 5962-9688703HZC | BU-61585DG3-150 | 5962-9306538HNA |
| BU-61581DV3-150 | 5962-9306536HYA | BU61583D1-140 | 5962-9688703HXA | BU-61585DS3-110 | 5962-9306538HXC |
| BU-61581DV3-150 | 5962-9306536HYA | BU61583F1-140 | 5962-9688703HYA | BU-61585DS3-110 | 5962-9306538HXC |
| BU-61581 (GEN) | 5962-9306516HXA | BU61583G1-140 | 5962-9688703HZA | BU-61585DS3-130 | 5962-9306538HXC |
| BU-61581 (GEN) | 5962-9306516HYA | BU61583D2-110 | 5962-9688704HXC | BU-61585DS3-130 | 5962-9306538HXC |
| BU-61581DG6-110 | 5962-9306537HNC | BU61583F2-110 | 5962-9688704HYC | BU-61585DS3-140 | 5962-9306538HXA |
| BU-61581DG6-110 | 5962-9306537HNC | BU61583G2-110 | 5962-9688704HZC | BU-61585DS3-140 | 5962-9306538HXA |
| BU-61581DG6-130 | 5962-9306537HNC | BU61583D2-140 | 5962-9688704HXA | BU-61585DS3-150 | 5962-9306538HXA |
| BU-61581DG6-130 | 5962-9306537HNC | BU61583F2-140 | 5962-9688704HYA | BU-61585DS3-150 | 5962-9306538HXA |
| BU-61581DG6-140 | 5962-9306537HNA | BU61583G2-140 | 5962-9688704HZA | BU-61585DV3-110 | 5962-9306538HYC |
| BU-61581DG6-140 | 5962-9306537HNA | BU-61585 (GEN) | 5962-9306517HZC | BU-61585DV3-110 | 5962-9306538HYC |
| BU-61581DG6-150 | 5962-9306537HNA | BU-61585S1-110 | 5962-9306517HXC | BU-61585DV3-130 | 5962-9306538HYC |
| BU-61581DG6-150 | 5962-9306537HNA | BU-61585S1-110 | 5962-9306517HXC | BU-61585DV3-130 | 5962-9306538HYC |
| BU-61581DV6-110 | 5962-9306537HYC | BU-61585S1-130 | 5962-9306517HXC | BU-61585DV3-140 | 5962-9306538HYA |
| BU-61581DV6-110 | 5962-9306537HYC | BU-61585S1-130 | 5962-9306517HXC | BU-61585DV3-140 | 5962-9306538HYA |
| BU-61581DV6-130 | 5962-9306537HYC | BU-61585S1-140 | 5962-9306517HXA | BU-61585DV3-150 | 5962-9306538HYA |
| BU-61581DV6-130 | 5962-9306537HYC | BU-61585S1-140 | 5962-9306517HXA | BU-61585DV3-150 | 5962-9306538HYA |
| BU-61581DV6-140 | 5962-9306537HYA | BU-61585S1-150 | 5962-9306517HXA | BU-61585DG6-110 | 5962-9306539HNC |
| BU-61581DV6-140 | 5962-9306537HYA | BU-61585S1-150 | 5962-9306517HXA | BU-61585DG6-110 | 5962-9306539HNC |
| BU-61581DV6-150 | 5962-9306537HYA | BU-61585V1-110 | 5962-9306517HYC | BU-61585DG6-130 | 5962-9306539HNC |
| BU-61581DV6-150 | 5962-9306537HYA | BU-61585V1-110 | 5962-9306517HYC | BU-61585DG6-130 | 5962-9306539HNC |
| BU61582D0-110 | 5962-9688705HXC | BU-61585V1-130 | 5962-9306517HYC | BU-61585DG6-140 | 5962-9306539HNA |
| BU61582F0-110 | 5962-9688705HYC | BU-61585V1-130 | 5962-9306517HYC | BU-61585DG6-140 | 5962-9306539HNA |
| BU61582G0-110 | 5962-9688705HZC | BU-61585V1-140 | 5962-9306517HYA | BU-61585DG6-150 | 5962-9306539HNA |
| BU61582D0-140 | 5962-9688705HXA | BU-61585V1-140 | 5962-9306517HYA | BU-61585DG6-150 | 5962-9306539HNA |
| BU61582F0-140 | 5962-9688705HYA | BU-61585V1-150 | 5962-9306517HYA | BU-61585DS6-110 | 5962-9306539HXC |
| BU61582G0-140 | 5962-9688705HZA | BU-61585V1-150 | 5962-9306517HYA | BU-61585DS6-110 | 5962-9306539HXC |
| BU61582D1-110 | 5962-9688701HXC | BU-61585 (GEN) | 5962-9306518HZC | BU-61585DS6-130 | 5962-9306539HXC |
| BU61582F1-110 | 5962-9688701HYC | BU-61585S2-110 | 5962-9306518HXC | BU-61585DS6-130 | 5962-9306539HXC |
| BU61582G1-110 | 5962-9688701HZC | BU-61585S2-110 | 5962-9306518HXC | BU-61585DS6-140 | 5962-9306539HXA |
| BU61582D1-140 | 5962-9688701HXA | BU-61585S2-130 | 5962-9306518HXC | BU-61585DS6-140 | 5962-9306539HXA |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART II, Listed By Generic PIN

| Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN |
|---|---|---|---|---|---|
| BU-61585DS6-150 | 5962-9306539HXA | BU-61586DG3-140 | 5962-9306540HNA | BU-61588CF3-140 | 5962-9306542HTA |
| BU-61585DS6-150 | 5962-9306539HXA | BU-61586DG3-150 | 5962-9306540HNA | BU-61588CF3-150 | 5962-9306542HTA |
| BU-61585DV6-110 | 5962-9306539HYC | BU-61586DG3-150 | 5962-9306540HNA | BU-61588CF3-150 | 5962-9306542HTA |
| BU-61585DV6-110 | 5962-9306539HYC | BU-61586DS3-110 | 5962-9306540HXC | BU-61588CG3-110 | 5962-9306542HMC |
| BU-61585DV6-130 | 5962-9306539HYC | BU-61586DS3-110 | 5962-9306540HXC | BU-61588CG3-110 | 5962-9306542HMC |
| BU-61585DV6-130 | 5962-9306539HYC | BU-61586DS3-130 | 5962-9306540HXC | BU-61588CG3-130 | 5962-9306542HMC |
| BU-61585DV6-140 | 5962-9306539HYA | BU-61586DS3-130 | 5962-9306540HXC | BU-61588CG3-130 | 5962-9306542HMC |
| BU-61585DV6-140 | 5962-9306539HYA | BU-61586DS3-140 | 5962-9306540HXA | BU-61588CG3-140 | 5962-9306542HMA |
| BU-61585DV6-150 | 5962-9306539HYA | BU-61586DS3-140 | 5962-9306540HXA | BU-61588CG3-140 | 5962-9306542HMA |
| BU-61585DV6-150 | 5962-9306539HYA | BU-61586DS3-150 | 5962-9306540HXA | BU-61588CG3-150 | 5962-9306542HMA |
| BU-61586 (GEN) | 5962-9306522HXA | BU-61586DS3-150 | 5962-9306540HXA | BU-61588CG3-150 | 5962-9306542HMA |
| BU-61586 (GEN) | 5962-9306522HYA | BU-61586DV3-110 | 5962-9306540HYC | BU-61588CP3-110 | 5962-9306542HUC |
| BU-61586 (GEN) | 5962-9306519HZC | BU-61586DV3-110 | 5962-9306540HYC | BU-61588CP3-110 | 5962-9306542HUC |
| BU-61586S1-110 | 5962-9306519HXC | BU-61586DV3-130 | 5962-9306540HYC | BU-61588CP3-130 | 5962-9306542HUC |
| BU-61586S1-110 | 5962-9306519HXC | BU-61586DV3-130 | 5962-9306540HYC | BU-61588CP3-130 | 5962-9306542HUC |
| BU-61586S1-130 | 5962-9306519HXC | BU-61586DV3-140 | 5962-9306540HYA | BU-61588CP3-140 | 5962-9306542HUA |
| BU-61586S1-130 | 5962-9306519HXC | BU-61586DV3-140 | 5962-9306540HYA | BU-61588CP3-140 | 5962-9306542HUA |
| BU-61586S1-140 | 5962-9306519HXA | BU-61586DV3-150 | 5962-9306540HYA | BU-61588CP3-150 | 5962-9306542HUA |
| BU-61586S1-140 | 5962-9306519HXA | BU-61586DV3-150 | 5962-9306540HYA | BU-61588CP3-150 | 5962-9306542HUA |
| BU-61586S1-150 | 5962-9306519HXA | BU-61586DG6-110 | 5962-9306541HNC | LM6161 (GEN) | 5962-89621012A |
| BU-61586S1-150 | 5962-9306519HXA | BU-61586DG6-110 | 5962-9306541HNC | LM6161 (GEN) | 5962-8962101HA |
| BU-61586V1-110 | 5962-9306519HYC | BU-61586DG6-130 | 5962-9306541HNC | LM6161J/883 | 5962-8962101PA |
| BU-61586V1-110 | 5962-9306519HYC | BU-61586DG6-130 | 5962-9306541HNC | LM6161J-QMLV | 5962-8962101VPA |
| BU-61586V1-130 | 5962-9306519HYC | BU-61586DG6-140 | 5962-9306541HNA | LM6161WG/883 | 5962-8962101XA |
| BU-61586V1-130 | 5962-9306519HYC | BU-61586DG6-140 | 5962-9306541HNA | LM6161WG-QMLV | 5962-8962101VXA |
| BU-61586V1-140 | 5962-9306519HYA | BU-61586DG6-150 | 5962-9306541HNA | LM6162 (GEN) | 5962-9216501M2A |
| BU-61586V1-140 | 5962-9306519HYA | BU-61586DG6-150 | 5962-9306541HNA | LM6162 (GEN) | 5962-9216501MHA |
| BU-61586V1-150 | 5962-9306519HYA | BU-61586DS6-110 | 5962-9306541HXC | LM6162 (GEN) | 5962-9216501VPA |
| BU-61586V1-150 | 5962-9306519HYA | BU-61586DS6-110 | 5962-9306541HXC | LM6162 (GEN) | 5962-9216501VXA |
| BU-61585 (GEN) | 5962-9306520HZC | BU-61586DS6-130 | 5962-9306541HXC | LM6162J/883 | 5962-9216501MPA |
| BU-61585V2-110 | 5962-9306520HYC | BU-61586DS6-130 | 5962-9306541HXC | LM6162WG/883 | 5962-9216501MXA |
| BU-61585V2-130 | 5962-9306520HYC | BU-61586DS6-140 | 5962-9306541HXA | LM6164 (GEN) | 5962-89624012A |
| BU-61586S2-110 | 5962-9306520HXC | BU-61586DS6-140 | 5962-9306541HXA | LM6164 (GEN) | 5962-8962401HA |
| BU-61586S2-110 | 5962-9306520HXC | BU-61586DS6-150 | 5962-9306541HXA | LM6164J/883 | 5962-8962401PA |
| BU-61586S2-130 | 5962-9306520HXC | BU-61586DS6-150 | 5962-9306541HXA | LM6164J-QMLV | 5962-8962401VPA |
| BU-61586S2-130 | 5962-9306520HXC | BU-61586DV6-110 | 5962-9306541HYC | LM6164WG/883 | 5962-8962401XA |
| BU-61586S2-140 | 5962-9306520HXA | BU-61586DV6-110 | 5962-9306541HYC | LM6164WG-QMLV | 5962-8962401VXA |
| BU-61586S2-140 | 5962-9306520HXA | BU-61586DV6-130 | 5962-9306541HYC | 61CD64L-70 (GEN) | 5962-8601508XA |
| BU-61586S2-150 | 5962-9306520HXA | BU-61586DV6-130 | 5962-9306541HYC | 61CD64S-70 (GEN) | 5962-8601507XA |
| BU-61586S2-150 | 5962-9306520HXA | BU-61586DV6-140 | 5962-9306541HYA | LM6165 (GEN) | 5962-89625012A |
| BU-61586V2-110 | 5962-9306520HYC | BU-61586DV6-140 | 5962-9306541HYA | LM6165 (GEN) | 5962-8962501HA |
| BU-61586V2-130 | 5962-9306520HYC | BU-61586DV6-150 | 5962-9306541HYA | LM6165J/883 | 5962-8962501PA |
| BU-61586V2-140 | 5962-9306520HYA | BU-61586DV6-150 | 5962-9306541HYA | LM6165J-QMLV | 5962-8962501VPA |
| BU-61586V2-140 | 5962-9306520HYA | BU-61588 (GEN) | 5962-9306524HXA | LM6165WG/883 | 5962-8962501XA |
| BU-61586V2-150 | 5962-9306520HYA | BU-61588 (GEN) | 5962-9306524HYA | LM6165WG-QMLV | 5962-8962501VXA |
| BU-61586V2-150 | 5962-9306520HYA | BU-61588 (GEN) | 5962-9306525HTA | 6167SA25 (GEN) | 8413206SA |
| BU-61586 (GEN) | 5962-9306523HXA | BU-61588 (GEN) | 5962-9306525HUA | 6167SA25 (GEN) | 8413206YA |
| BU-61586 (GEN) | 5962-9306523HYA | BU-61588 (GEN) | 5962-9306525HUC | IDT6167SA25DB | 8413206RA |
| BU-61586DG3-110 | 5962-9306540HNC | BU-61588CF3-110 | 5962-9306542HTC | 6167LA35 (GEN) | 8413204SA |
| BU-61586DG3-110 | 5962-9306540HNC | BU-61588CF3-110 | 5962-9306542HTC | 6167LA35 (GEN) | 8413204YA |
| BU-61586DG3-130 | 5962-9306540HNC | BU-61588CF3-130 | 5962-9306542HTC | IDT6167LA35DB | 8413204RA |
| BU-61586DG3-130 | 5962-9306540HNC | BU-61588CF3-130 | 5962-9306542HTC | IDT6167SA35DB | 8413205RA |
| BU-61586DG3-140 | 5962-9306540HNA | BU-61588CF3-140 | 5962-9306542HTA | 6167LA45 (GEN) | 8413209SA |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART II, Listed By Generic PIN

| Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN |
|---|---|---|---|---|---|
| 6167LA45 (GEN) | 8413209YA | BU-61689CG3-130 | 5962-9306546HMC | BU-61705F3-140 | 5962-0151409HTA |
| IDT6167LA45DB | 8413209RA | BU-61689CG3-140 | 5962-9306546HMA | BU-61705F3-140 | 5962-0151409HTA |
| 6168LA25LB | 5962-8670502UA | BU-61689CG3-140 | 5962-9306546HMA | BU-61705G3-140 | 5962-0151409HMA |
| 6168SA25LB | 5962-8670511UA | BU-61689CG3-150 | 5962-9306546HMA | BU-61705G3-140 | 5962-0151409HMA |
| IDT6168LA25DB | 5962-8670502RA | BU-61689CG3-150 | 5962-9306546HMA | BU-61705F3-150 | 5962-0151409HTA |
| IDT6168SA25DB | 5962-8670511RA | BU-61689CP3-110 | 5962-9306546HUC | BU-61705F3-150 | 5962-0151409HTA |
| P4C168-35LMB | 5962-8670512UA | BU-61689CP3-110 | 5962-9306546HUC | BU-61705G3-150 | 5962-0151409HMA |
| 6168LA45LB | 5962-8670506UA | BU-61689CP3-130 | 5962-9306546HUC | BU-61705G3-150 | 5962-0151409HMA |
| 6168SA45LB | 5962-8670513UA | BU-61689CP3-130 | 5962-9306546HUC | BU-61705F4-110 | 5962-0151410HTC |
| IDT6168LA45DB | 5962-8670506RA | BU-61689CP3-140 | 5962-9306546HUA | BU-61705F4-110 | 5962-0151410HTC |
| IDT6168SA45DB | 5962-8670513RA | BU-61689CP3-140 | 5962-9306546HUA | BU-61705G4-110 | 5962-0151410HMC |
| P4C168-70LMB | 5962-8670509UA | BU-61689CP3-150 | 5962-9306546HUA | BU-61705G4-110 | 5962-0151410HMC |
| BU-61688 (GEN) | 5962-9306528HMA | BU-61689CP3-150 | 5962-9306546HUA | BU-61705F4-130 | 5962-0151410HTC |
| BU-61688 (GEN) | 5962-9306528HTA | BU-61703F3-110 | 5962-0151411HTC | BU-61705F4-130 | 5962-0151410HTC |
| BU-61688 (GEN) | 5962-9306528HUA | BU-61703F3-110 | 5962-0151411HTC | BU-61705G4-130 | 5962-0151410HMC |
| BU-61688CF3-110 | 5962-9306545HTC | BU-61703G3-110 | 5962-0151411HMC | BU-61705G4-130 | 5962-0151410HMC |
| BU-61688CF3-110 | 5962-9306545HTC | BU-61703G3-110 | 5962-0151411HMC | BU-61705F4-140 | 5962-0151410HTA |
| BU-61688CF3-130 | 5962-9306545HTC | BU-61703G3-130 | 5962-0151411HMC | BU-61705F4-140 | 5962-0151410HTA |
| BU-61688CF3-130 | 5962-9306545HTC | BU-61703F3-130 | 5962-0151411HTC | BU-61705G4-140 | 5962-0151410HMA |
| BU-61688CF3-140 | 5962-9306545HTA | BU-61703F3-130 | 5962-0151411HTC | BU-61705G4-140 | 5962-0151410HMA |
| BU-61688CF3-140 | 5962-9306545HTA | BU-61703G3-130 | 5962-0151411HMC | BU-61705F4-150 | 5962-0151410HTA |
| BU-61688CF3-150 | 5962-9306545HTA | BU-61703F3-140 | 5962-0151411HTA | BU-61705F4-150 | 5962-0151410HTA |
| BU-61688CF3-150 | 5962-9306545HTA | BU-61703F3-140 | 5962-0151411HTA | BU-61705G4-150 | 5962-0151410HMA |
| BU-61688CG3-110 | 5962-9306545HMC | BU-61703G3-140 | 5962-0151411HMA | BU-61705G4-150 | 5962-0151410HMA |
| BU-61688CG3-110 | 5962-9306545HMC | BU-61703G3-140 | 5962-0151411HMA | LM6172AMJFQML | 5962F9560401QPA |
| BU-61688CG3-130 | 5962-9306545HMC | BU-61703F3-150 | 5962-0151411HTA | LM6172AMJFQMLV | 5962F9560401VPA |
| BU-61688CG3-130 | 5962-9306545HMC | BU-61703F3-150 | 5962-0151411HTA | LM6172AMJ-QML | 5962-9560401QPA |
| BU-61688CG3-140 | 5962-9306545HMA | BU-61703G3-150 | 5962-0151411HMA | LM6172AMJ-QMLV | 5962-9560401VPA |
| BU-61688CG3-140 | 5962-9306545HMA | BU-61703G3-150 | 5962-0151411HMA | LM6172AMWGFQML | 5962F9560401QXA |
| BU-61688CG3-150 | 5962-9306545HMA | BU-61703F4-110 | 5962-0151412HTC | LM6172AMWGFQMLV | 5962F9560401VXA |
| BU-61688CG3-150 | 5962-9306545HMA | BU-61703F4-110 | 5962-0151412HTC | LM6172AMWG-QML | 5962-9560401QXA |
| BU-61688CP3-110 | 5962-9306545HUC | BU-61703G4-110 | 5962-0151412HMC | LM6172AMWG-QMLV | 5962-9560401VXA |
| BU-61688CP3-110 | 5962-9306545HUC | BU-61703G4-110 | 5962-0151412HMC | BU-61743F3-110 | 5962-0151407HTC |
| BU-61688CP3-130 | 5962-9306545HUC | BU-61703F4-130 | 5962-0151412HTC | BU-61743F3-110 | 5962-0151407HTC |
| BU-61688CP3-130 | 5962-9306545HUC | BU-61703F4-130 | 5962-0151412HTC | BU-61743G3-110 | 5962-0151407HMC |
| BU-61688CP3-140 | 5962-9306545HUA | BU-61703G4-130 | 5962-0151412HMC | BU-61743G3-110 | 5962-0151407HMC |
| BU-61688CP3-140 | 5962-9306545HUA | BU-61703G4-130 | 5962-0151412HMC | BU-61743F3-130 | 5962-0151407HTC |
| BU-61688CP3-150 | 5962-9306545HUA | BU-61703F4-140 | 5962-0151412HTA | BU-61743F3-130 | 5962-0151407HTC |
| BU-61688CP3-150 | 5962-9306545HUA | BU-61703F4-140 | 5962-0151412HTA | BU-61743G3-130 | 5962-0151407HMC |
| BU-61689 (GEN) | 5962-9306529HMA | BU-61703G4-140 | 5962-0151412HMA | BU-61743G3-130 | 5962-0151407HMC |
| BU-61689 (GEN) | 5962-9306529HMA | BU-61703G4-140 | 5962-0151412HMA | BU-61743F3-140 | 5962-0151407HTA |
| BU-61689 (GEN) | 5962-9306529HTA | BU-61703F4-150 | 5962-0151412HTA | BU-61743F3-140 | 5962-0151407HTA |
| BU-61689CF3-110 | 5962-9306546HTC | BU-61703F4-150 | 5962-0151412HTA | BU-61743G3-140 | 5962-0151407HMA |
| BU-61689CF3-110 | 5962-9306546HTC | BU-61703G4-150 | 5962-0151412HMA | BU-61743G3-140 | 5962-0151407HMA |
| BU-61689CF3-130 | 5962-9306546HTC | BU-61703G4-150 | 5962-0151412HMA | BU-61743F3-150 | 5962-0151407HTA |
| BU-61689CF3-130 | 5962-9306546HTC | BU-61705F3-110 | 5962-0151409HTC | BU-61743F3-150 | 5962-0151407HTA |
| BU-61689CF3-140 | 5962-9306546HTA | BU-61705F3-110 | 5962-0151409HTC | BU-61743G3-150 | 5962-0151407HMA |
| BU-61689CF3-140 | 5962-9306546HTA | BU-61705G3-110 | 5962-0151409HMC | BU-61743G3-150 | 5962-0151407HMA |
| BU-61689CF3-150 | 5962-9306546HTA | BU-61705G3-110 | 5962-0151409HMC | BU-61743F4-110 | 5962-0151408HTC |
| BU-61689CF3-150 | 5962-9306546HTA | BU-61705F3-130 | 5962-0151409HTC | BU-61743F4-110 | 5962-0151408HTC |
| BU-61689CG3-110 | 5962-9306546HMC | BU-61705F3-130 | 5962-0151409HTC | BU-61743G4-110 | 5962-0151408HMC |
| BU-61689CG3-110 | 5962-9306546HMC | BU-61705G3-130 | 5962-0151409HMC | BU-61743G4-110 | 5962-0151408HMC |
| BU-61689CG3-130 | 5962-9306546HMC | BU-61705G3-130 | 5962-0151409HMC | BU-61743F4-130 | 5962-0151408HTC |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART II, Listed By Generic PIN

| Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN |
|---|---|---|---|---|---|
| BU-61743F4-130 | 5962-0151408HTC | BU-61843F3-140 | 5962-0151415HTA | BU-61845F4-150 | 5962-0151414HTA |
| BU-61743G4-130 | 5962-0151408HMC | BU-61843F3-140 | 5962-0151415HTA | BU-61845G4-150 | 5962-0151414HMA |
| BU-61743G4-130 | 5962-0151408HMC | BU-61843G3-140 | 5962-0151415HMA | BU-61845G4-150 | 5962-0151414HMA |
| BU-61743F4-140 | 5962-0151408HTA | BU-61843G3-140 | 5962-0151415HMA | BU-61864F3-110 | 5962-0151403HTC |
| BU-61743F4-140 | 5962-0151408HTA | BU-61843F3-150 | 5962-0151415HTA | BU-61864F3-110 | 5962-0151403HTC |
| BU-61743G4-140 | 5962-0151408HMA | BU-61843F3-150 | 5962-0151415HTA | BU-61864G3-110 | 5962-0151403HMC |
| BU-61743G4-140 | 5962-0151408HMA | BU-61843G3-150 | 5962-0151415HMA | BU-61864G3-110 | 5962-0151403HMC |
| BU-61743F4-150 | 5962-0151408HTA | BU-61843G3-150 | 5962-0151415HMA | BU-61864F3-130 | 5962-0151403HTC |
| BU-61743F4-150 | 5962-0151408HTA | BU-61843F4-110 | 5962-0151416HTC | BU-61864F3-130 | 5962-0151403HTC |
| BU-61743G4-150 | 5962-0151408HMA | BU-61843F4-110 | 5962-0151416HTC | BU-61864G3-130 | 5962-0151403HMC |
| BU-61743G4-150 | 5962-0151408HMA | BU-61843G4-110 | 5962-0151416HMC | BU-61864G3-130 | 5962-0151403HMC |
| BU-61745F3-110 | 5962-0151405HTC | BU-61843G4-110 | 5962-0151416HMC | BU-61864F3-140 | 5962-0151403HTA |
| BU-61745F3-110 | 5962-0151405HTC | BU-61843F4-130 | 5962-0151416HTC | BU-61864F3-140 | 5962-0151403HTA |
| BU-61745G3-110 | 5962-0151405HMC | BU-61843F4-130 | 5962-0151416HTC | BU-61864G3-140 | 5962-0151403HMA |
| BU-61745G3-110 | 5962-0151405HMC | BU-61843G4-130 | 5962-0151416HMC | BU-61864G3-140 | 5962-0151403HMA |
| BU-61745F3-130 | 5962-0151405HTC | BU-61843G4-130 | 5962-0151416HMC | BU-61864F3-150 | 5962-0151403HTA |
| BU-61745F3-130 | 5962-0151405HTC | BU-61843F4-140 | 5962-0151416HTA | BU-61864F3-150 | 5962-0151403HTA |
| BU-61745G3-130 | 5962-0151405HMC | BU-61843F4-140 | 5962-0151416HTA | BU-61864G3-150 | 5962-0151403HMA |
| BU-61745G3-130 | 5962-0151405HMC | BU-61843G4-140 | 5962-0151416HMA | BU-61864G3-150 | 5962-0151403HMA |
| BU-61745F3-140 | 5962-0151405HTA | BU-61843G4-140 | 5962-0151416HMA | BU-61864F4-110 | 5962-0151404HTC |
| BU-61745F3-140 | 5962-0151405HTA | BU-61843F4-150 | 5962-0151416HTA | BU-61864F4-110 | 5962-0151404HTC |
| BU-61745G3-140 | 5962-0151405HMA | BU-61843F4-150 | 5962-0151416HTA | BU-61864G4-110 | 5962-0151404HMC |
| BU-61745G3-140 | 5962-0151405HMA | BU-61843G4-150 | 5962-0151416HMA | BU-61864G4-110 | 5962-0151404HMC |
| BU-61745F3-150 | 5962-0151405HTA | BU-61843G4-150 | 5962-0151416HMA | BU-61864F4-130 | 5962-0151404HTC |
| BU-61745F3-150 | 5962-0151405HTA | BU-61845F3-110 | 5962-0151413HTC | BU-61864F4-130 | 5962-0151404HTC |
| BU-61745G3-150 | 5962-0151405HMA | BU-61845F3-110 | 5962-0151413HTC | BU-61864G4-130 | 5962-0151404HMC |
| BU-61745G3-150 | 5962-0151405HMA | BU-61845G3-110 | 5962-0151413HMC | BU-61864G4-130 | 5962-0151404HMC |
| BU-61745F4-110 | 5962-0151406HTC | BU-61845G3-110 | 5962-0151413HMC | BU-61864F4-140 | 5962-0151404HTA |
| BU-61745F4-110 | 5962-0151406HTC | BU-61845F3-130 | 5962-0151413HTC | BU-61864F4-140 | 5962-0151404HTA |
| BU-61745G4-110 | 5962-0151406HMC | BU-61845F3-130 | 5962-0151413HTC | BU-61864G4-140 | 5962-0151404HMA |
| BU-61745G4-110 | 5962-0151406HMC | BU-61845G3-130 | 5962-0151413HMC | BU-61864G4-140 | 5962-0151404HMA |
| BU-61745F4-130 | 5962-0151406HTC | BU-61845G3-130 | 5962-0151413HMC | BU-61864F4-150 | 5962-0151404HTA |
| BU-61745F4-130 | 5962-0151406HTC | BU-61845F3-140 | 5962-0151413HTA | BU-61864F4-150 | 5962-0151404HTA |
| BU-61745G4-130 | 5962-0151406HMC | BU-61845F3-140 | 5962-0151413HTA | BU-61864G4-150 | 5962-0151404HMA |
| BU-61745G4-130 | 5962-0151406HMC | BU-61845G3-140 | 5962-0151413HMA | BU-61864G4-150 | 5962-0151404HMA |
| BU-61745F4-140 | 5962-0151406HTA | BU-61845G3-140 | 5962-0151413HMA | BU-61865F3-110 | 5962-0151401HTC |
| BU-61745F4-140 | 5962-0151406HTA | BU-61845F3-150 | 5962-0151413HTA | BU-61865F3-110 | 5962-0151401HTC |
| BU-61745G4-140 | 5962-0151406HMA | BU-61845F3-150 | 5962-0151413HTA | BU-61865G3-110 | 5962-0151401HMC |
| BU-61745G4-140 | 5962-0151406HMA | BU-61845G3-150 | 5962-0151413HMA | BU-61865G3-110 | 5962-0151401HMC |
| BU-61745F4-150 | 5962-0151406HTA | BU-61845G3-150 | 5962-0151413HMA | BU-61865F3-130 | 5962-0151401HTC |
| BU-61745F4-150 | 5962-0151406HTA | BU-61845F4-110 | 5962-0151414HTC | BU-61865F3-130 | 5962-0151401HTC |
| BU-61745G4-150 | 5962-0151406HMA | BU-61845F4-110 | 5962-0151414HTC | BU-61865G3-130 | 5962-0151401HMC |
| BU-61745G4-150 | 5962-0151406HMA | BU-61845G4-110 | 5962-0151414HMC | BU-61865G3-130 | 5962-0151401HMC |
| LM6181 (GEN) | 5962-9081802MPA | BU-61845G4-110 | 5962-0151414HMC | BU-61865F3-140 | 5962-0151401HTA |
| LM6182A (GEN) | 5962-9460301MCA | BU-61845F4-130 | 5962-0151414HTC | BU-61865F3-140 | 5962-0151401HTA |
| BU-61843F3-110 | 5962-0151415HTC | BU-61845F4-130 | 5962-0151414HTC | BU-61865G3-140 | 5962-0151401HMA |
| BU-61843F3-110 | 5962-0151415HTC | BU-61845G4-130 | 5962-0151414HMC | BU-61865G3-140 | 5962-0151401HMA |
| BU-61843G3-110 | 5962-0151415HMC | BU-61845G4-130 | 5962-0151414HMC | BU-61865F3-150 | 5962-0151401HTA |
| BU-61843G3-110 | 5962-0151415HMC | BU-61845F4-140 | 5962-0151414HTA | BU-61865F3-150 | 5962-0151401HTA |
| BU-61843F3-130 | 5962-0151415HTC | BU-61845F4-140 | 5962-0151414HTA | BU-61865G3-150 | 5962-0151401HMA |
| BU-61843F3-130 | 5962-0151415HTC | BU-61845G4-140 | 5962-0151414HMA | BU-61865G3-150 | 5962-0151401HMA |
| BU-61843G3-130 | 5962-0151415HMC | BU-61845G4-140 | 5962-0151414HMA | BU-61865F4-110 | 5962-0151402HTC |
| BU-61843G3-130 | 5962-0151415HMC | BU-61845F4-150 | 5962-0151414HTA | BU-61865F4-110 | 5962-0151402HTC |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART II, Listed By Generic PIN

| Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN |
|---|---|---|---|---|---|
| BU-61865G4-110 | 5962-0151402HMC | 6256 (GEN) | 5962F9584506VZC | HX6256/RQHC | 5962H9584501QXC |
| BU-61865G4-110 | 5962-0151402HMC | 6256 (GEN) | 5962H9584505QXC | HX6256/RQHT | 5962H9584502QXC |
| BU-61865F4-130 | 5962-0151402HTC | 6256 (GEN) | 5962H9584505QYC | HX6256/RQRC | 5962R9584501QXC |
| BU-61865F4-130 | 5962-0151402HTC | 6256 (GEN) | 5962H9584505QZC | HX6256/RQRT | 5962R9584502QXC |
| BU-61865G4-130 | 5962-0151402HMC | 6256 (GEN) | 5962H9584505VXC | HX6256/RVFC | 5962F9584501VXC |
| BU-61865G4-130 | 5962-0151402HMC | 6256 (GEN) | 5962H9584505VYC | HX6256/RVFT | 5962F9584502VXC |
| BU-61865F4-140 | 5962-0151402HTA | 6256 (GEN) | 5962H9584505VZC | HX6256/RVHC | 5962H9584501VXC |
| BU-61865F4-140 | 5962-0151402HTA | 6256 (GEN) | 5962H9584506QXC | HX6256/RVHT | 5962H9584502VXC |
| BU-61865G4-140 | 5962-0151402HMA | 6256 (GEN) | 5962H9584506QYC | HX6256/RVRC | 5962R9584501VXC |
| BU-61865G4-140 | 5962-0151402HMA | 6256 (GEN) | 5962H9584506QZC | HX6256/RVRT | 5962R9584502VXC |
| BU-61865F4-150 | 5962-0151402HTA | 6256 (GEN) | 5962H9584506VXC | HX6256/XQFC | 5962F9584501QZC |
| BU-61865F4-150 | 5962-0151402HTA | 6256 (GEN) | 5962H9584506VYC | HX6256/XQHC | 5962H9584501QZC |
| BU-61865G4-150 | 5962-0151402HMA | 6256 (GEN) | 5962H9584506VZC | HX6256/XQHT | 5962H9584502QZC |
| BU-61865G4-150 | 5962-0151402HMA | 6256 (GEN) | 5962R9584502QZC | HX6256/XQRC | 5962R9584501QZC |
| 6198L35 (GEN) | 5962-8685917KA | 6256 (GEN) | 5962R9584502VZC | HX6256/XVFC | 5962F9584501VZC |
| 6198S35 (GEN) | 5962-8685918KA | 6256 (GEN) | 5962R9584505QXC | HX6256/XVHC | 5962H9584501VZC |
| 6198L45 (GEN) | 5962-8685915KA | 6256 (GEN) | 5962R9584505QYC | HX6256/XVHT | 5962H9584502VZC |
| 6198S45 (GEN) | 5962-8685916KA | 6256 (GEN) | 5962R9584505QZC | HX6256/XVRC | 5962R9584501VZC |
| 6198L55 (GEN) | 5962-8685913KA | 6256 (GEN) | 5962R9584505VXC | HX6356/XQFC | 5962F9584503QZC |
| 6198S55 (GEN) | 5962-8685914KA | 6256 (GEN) | 5962R9584505VYC | HX6356/XQHC | 5962H9584503QZC |
| 6198L70 (GEN) | 5962-8685911KA | 6256 (GEN) | 5962R9584505VZC | HX6356/XQRC | 5962R9584503QZC |
| 6198L70 (GEN) | 5962-8685911XA | 6256 (GEN) | 5962R9584506QXC | HX6356/XVFC | 5962F9584503VZC |
| 6198S70 (GEN) | 5962-8685912KA | 6256 (GEN) | 5962R9584506QYC | HX6356/XVHC | 5962H9584503VZC |
| 6198S70 (GEN) | 5962-8685912XA | 6256 (GEN) | 5962R9584506QZC | HX6356/XVRC | 5962R9584503VZC |
| HX6228/AQHC | 5962H9853701QYC | 6256 (GEN) | 5962R9584506VXC | SMJ626162-12 (GEN) | 5962-9754503NYB |
| HX6228/AQHT | 5962H9853702QYC | 6256 (GEN) | 5962R9584506VYC | SMJ626162-12HKDM | 5962-9754503QXA |
| HX6228/AVHC | 5962H9853701VYC | 6256 (GEN) | 5962R9584506VZC | SMJ626162-15 (GEN) | 5962-9754501NYB |
| HX6228/AVHT | 5962H9853702VYC | 6356 (GEN) | 5962F9584504QZC | SMJ626162-15HKDM | 5962-9754501QXA |
| HX6228/TQHC | 5962H9853701QXC | 6356 (GEN) | 5962F9584504VZC | SMJ626162-20 (GEN) | 5962-9754502NYB |
| HX6228/TQHT | 5962H9853702QXC | 6356 (GEN) | 5962H9584504QZC | SMJ626162-20HKDM | 5962-9754502QXA |
| HX6228/TVHC | 5962H9853701VXC | 6356 (GEN) | 5962H9584504VZC | AR629AU9/883 | 5962-9958101QXC |
| HX6228/TVHT | 5962H9853702VXC | 6356 (GEN) | 5962R9584504QZC | ACS630 (GEN) | 5962F9671101V9A |
| HX6228Die | 5962H9853701Q9A | 6356 (GEN) | 5962R9584504VZC | ACS630DMSR | 5962F9671101VXC |
| HX6228Die | 5962H9853702Q9A | HX6256/NQFC | 5962F9584501QYC | ACS630KMSR | 5962F9671101VYC |
| HCPL-623K | 5962-8876905K2A | HX6256/NQFT | 5962F9584502QYC | ACTS630 (GEN) | 5962F9672101V9A |
| HCPL-6231 | 5962-88769022A | HX6256/NQHC | 5962H9584501QYC | ACTS630 (GEN) | 5962F9672101VXC |
| AD625 (GEN) | 5962-87719012A | HX6256/NQHT | 5962H9584502QYC | ACTS630 (GEN) | 5962F9672101VYC |
| AD625SD/883B | 5962-8771901EA | HX6256/NQRC | 5962R9584501QYC | AD630SD/883 | 5962-8980701RA |
| HCPL-625K | 5962-8876906KFC | HX6256/NQRT | 5962R9584502QYC | AD630SE/883 | 5962-89807012A |
| HCPL-6251 | 5962-8876903FC | HX6256/NVFC | 5962F9584501VYC | MAX630 (GEN) | 5962-9454001MHA |
| 6256 (GEN) | 5962F9584502QZC | HX6256/NVFT | 5962F9584502VYC | MAX630MFB/883B | 5962-9454001MXC |
| 6256 (GEN) | 5962F9584502VZC | HX6256/NVHC | 5962H9584501VYC | MAX630MJA/883B | 5962-9454001MPA |
| 6256 (GEN) | 5962F9584505QXC | HX6256/NVHT | 5962H9584502VYC | ACTS630-02 (GEN) | 5962F9672102V9A |
| 6256 (GEN) | 5962F9584505QYC | HX6256/NVRC | 5962R9584501VYC | ACTS630-02 (GEN) | 5962F9672102VXC |
| 6256 (GEN) | 5962F9584505QZC | HX6256/NVRT | 5962R9584502VYC | ACTS630-02 (GEN) | 5962F9672102VYC |
| 6256 (GEN) | 5962F9584505VXC | HX6256/PQFT | 5962F9584502QUC | ACS630-02 (GEN) | 5962F9671102V9A |
| 6256 (GEN) | 5962F9584505VYC | HX6256/PQHT | 5962H9584502QUC | ACS630-02 (GEN) | 5962F9671102VXC |
| 6256 (GEN) | 5962F9584505VZC | HX6256/PQRT | 5962R9584502QUC | ACS630-02 (GEN) | 5962F9671102VYC |
| 6256 (GEN) | 5962F9584506QXC | HX6256/PVFT | 5962F9584502VUC | MAX631AMJA/883B | 5962-9214101MPA |
| 6256 (GEN) | 5962F9584506QYC | HX6256/PVHT | 5962H9584502VUC | MAX631BMJA/883B | 5962-9214102MPA |
| 6256 (GEN) | 5962F9584506QZC | HX6256/PVRT | 5962R9584502VUC | BUS-63100-617 | 5962-8604905XC |
| 6256 (GEN) | 5962F9584506VXC | HX6256/RQFC | 5962F9584501QXC | BUS-63100-618 | 5962-8604905XA |
| 6256 (GEN) | 5962F9584506VYC | HX6256/RQFT | 5962F9584502QXC | BUS63102II (GEN) | 5962-9174903HYA |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART II, Listed By Generic PIN

| Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN |
|---|---|---|---|---|---|
| BUS-63102II-110 | 5962-9174903HXC | UT63M125DVC | 5962R8864405VYC | MR63147M-2 (GEN) | 5962-9206102HYA |
| BUS-63102II-110 | 5962-9174903HXC | BUS63126II | 5962-8757902YA | MR63147M-2 (GEN) | 5962-9206102HZA |
| BUS-63102II-130 | 5962-9174903HXC | BUS63126II | 5962-8757902YC | UT63M149 (GEN) | 5962-9322602MXA |
| BUS-63102II-130 | 5962-9174903HXC | BUS-63126II | 5962-8757902YA | UT63M149 (GEN) | 5962-9322602MZA |
| BUS-63102II-140 | 5962-9174903HXA | BUS-63126II | 5962-8757902YC | MAX632AMJA/883B | 5962-9214103MPA |
| BUS-63102II-140 | 5962-9174903HXA | BUS63127II | 5962-8982601XA | MAX632BMJA/883B | 5962-9214104MPA |
| BUS-63102II-150 | 5962-9174903HXA | BUS63127II | 5962-8982601XC | MAX633AMJA/883B | 5962-9214105MPA |
| BUS-63102II-150 | 5962-9174903HXA | BUS-63127II | 5962-8982601XA | MAX633BMJA/883B | 5962-9214106MPA |
| BUS63104II (GEN) | 5962-9174904HXA | BUS-63127II | 5962-8982601XC | MAX634MJA/883B | 5962-9212401MPA |
| BUS63104II (GEN) | 5962-9174904HYA | UT63M127BB | 5962-8864406XA | HX6356/PQFT | 5962F9584504QUC |
| BUS-63105 (GEN) | 5962-8604901XA | UT63M127BB | 5962-8864406XC | HX6356/PQHT | 5962H9584504QUC |
| BUS-63105II-110 | 5962-8604902ZC | UT63M127CB | 5962-8864406ZA | HX6356/PQRT | 5962R9584504QUC |
| BUS-63105II-110 | 5962-8604902ZC | UT63M127CB | 5962-8864406ZC | HX6356/PVFT | 5962F9584504VUC |
| BUS-63105II-130 | 5962-8604902ZC | UT63M127DB | 5962-8864406YA | HX6356/PVHT | 5962H9584504VUC |
| BUS-63105II-130 | 5962-8604902ZC | UT63M127DB | 5962-8864406YC | HX6356/PVRT | 5962R9584504VUC |
| BUS-63105II-133 | 5962-8604902ZC | BUS63128II | 5962-8982601YA | HX6356/XQHC | 5962H99A1501QZC |
| BUS-63105II-140 | 5962-8604902ZA | BUS63128II | 5962-8982601YC | HC6364/1 (GEN) | 5962H3829438Q9C |
| BUS-63105II-140 | 5962-8604902ZA | BUS-63128II | 5962-8982601YA | HC6364/1 (GEN) | 5962H3829438V9C |
| BUS-63105II-150 | 5962-8604902ZA | BUS-63128II | 5962-8982601YC | HC6364/1 (GEN) | 5962H3829440Q9C |
| BUS-63105II-150 | 5962-8604902ZA | BUS63135II | 5962-8944704HXC | HC6364/1 (GEN) | 5962H3829440V9C |
| BUS-63105II-633 | 5962-8604902ZC | UT63M135 (GEN) | 5962-8864407XA | HC6364/1 (GEN) | 5962H3829442Q9C |
| BUS-63105II-634 | 5962-8604902ZA | UT63M135 (GEN) | 5962-8864407YA | HC6364/1 (GEN) | 5962H3829442V9C |
| BUS-63105II-634 | 5962-8604902ZA | UT63M135 (GEN) | 5962-8864407ZA | HC6364/1 (GEN) | 5962H3829443Q9C |
| UT63M105PB | 5962-8864401UA | BUS63136II | 5962-8944704HYC | HC6364/1 (GEN) | 5962H3829443V9C |
| UT63M105PB | 5962-8864401UC | UT63M137 (GEN) | 5962-8864408XA | HC6364/2 (GEN) | 5962H3829445Q9C |
| UT63M105PVA | 5962R8864401VUA | UT63M137 (GEN) | 5962-8864408YA | HC6364/2 (GEN) | 5962H3829445V9C |
| UT63M105PVC | 5962R8864401VUC | UT63M137 (GEN) | 5962-8864408ZA | AD637SQ/883B | 5962-8963701CA |
| BUS-63106II-110 | 5962-8604902TC | UT63M145BQA | 5962-9322604QXA | MAX638AMJA/883B | 5962-9212701MPA |
| BUS-63106II-130 | 5962-8604902TC | UT63M145BQC | 5962-9322604QXC | MAX638BMJA/883B | 5962-9212702MPA |
| BUS-63106II-601 | 5962-8604902TC | UT63M145BVA | 5962H9322604VXA | OP64A (GEN) | 5962-90535012A |
| UT63M107PB | 5962-8864402UA | UT63M145BVC | 5962H9322604VXC | OP64A (GEN) | 5962-9053501GA |
| UT63M107PB | 5962-8864402UC | UT63M145CQA | 5962-9322604QZA | OP64A (GEN) | 5962-9053501PA |
| UT63M115 (GEN) | 5962-8864403UA | UT63M145CQC | 5962-9322604QZC | AD640TD/883B | 5962-9095501MRA |
| UT63M117 (GEN) | 5962-8864404UA | UT63M145CVA | 5962H9322604VZA | AD640TE/883B | 5962-9095501M2A |
| BUS-63125 (GEN) | 5962-8757901XA | UT63M145CVC | 5962H9322604VZC | MSK640B (GEN) | 5962-9472701HXA |
| BUS-63125 (GEN) | 5962-8757901YA | MR63147M (GEN) | 5962-9206101HXA | MN6400S (GEN) | 5962-9177002HXA |
| BUS63125II | 5962-8757902XA | MR63147M (GEN) | 5962-9206101HYA | MN6400T (GEN) | 5962-9177001HXA |
| BUS63125II | 5962-8757902XC | MR63147M (GEN) | 5962-9206101HZA | IBM6401C-55 (GEN) | 5962H9215401QXC |
| BUS-63125II | 5962-8757902XA | UT63M147BBX | 5962-9322601MXA | IBM6401C-55 (GEN) | 5962H9215401QYC |
| BUS-63125II | 5962-8757902XC | UT63M147CBX | 5962-9322601MZA | IBM6401C-55 (GEN) | 5962H9215401VXC |
| MR63125M (GEN) | 5962-8757908XA | UT63M147E (GEN) | 5962-9322603Q9A | IBM6401C-55 (GEN) | 5962H9215401VYC |
| MR63125M (GEN) | 5962-8757908YA | UT63M147E(GEN) | 5962-9322603V9A | IBM6401T-55 (GEN) | 5962H9215402QXC |
| UT63M125BB | 5962-8864405XA | UT63M147EBQA | 5962-9322603QXA | IBM6401T-55 (GEN) | 5962H9215402QYC |
| UT63M125BB | 5962-8864405XC | UT63M147EBQC | 5962-9322603QXC | IBM6401T-55 (GEN) | 5962H9215402VXC |
| UT63M125BVA | 5962R8864405VXA | UT63M147EBVA | 5962H9322603VXA | IBM6401T-55 (GEN) | 5962H9215402VYC |
| UT63M125BVC | 5962R8864405VXC | UT63M147EBVC | 5962H9322603VXC | HD1-6402B/883 | 5962-9052502MQA |
| UT63M125CB | 5962-8864405ZA | UT63M147ECQA | 5962-9322603QZA | HD-6402R (GEN) | 5962-9052501MQA |
| UT63M125CB | 5962-8864405ZC | UT63M147ECQC | 5962-9322603QZC | LOR6408C-55 (GEN) | 5962H3829444Q9C |
| UT63M125CVA | 5962R8864405VZA | UT63M147ECVA | 5962H9322603VZA | LOR6408C-55 (GEN) | 5962H3829444V9C |
| UT63M125CVC | 5962R8864405VZC | UT63M147ECVC | 5962H9322603VZC | 6409 (GEN) | 5962-9088801M2A |
| UT63M125DB | 5962-8864405YA | UT63M147E-Q DIE | 5962H9322603Q9A | HD-6409 (GEN) | 5962-9088801MRA |
| UT63M125DB | 5962-8864405YC | UT63M147E-V DIE | 5962H9322603V9A | AD641SQ | 5962-9559801MRA |
| UT63M125DVA | 5962R8864405VYA | MR63147M-2 (GEN) | 5962-9206102HXA | MAX641AMJA/883B | 5962-9325401MPA |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

| Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN |
|---|---|---|---|---|---|
| MSK641B (GEN) | 5962-9472702HXA | HM1-65162C/883 | 8403603JA | BU-65170BV2-140 | 5962-9306502HYA |
| L64230-12 (GEN) | 5962-9050401MXC | HM4-65162/883 | 8403602ZA | BU-65170BV2-150 | 5962-9306502HYA |
| L64230-16 (GEN) | 5962-9050402MXC | BUS-65163II-110 | 5962-9216201HYC | BU-65170BV2-150 | 5962-9306502HYA |
| L64230-60 (GEN) | 5962-9050402MYA | BUS-65163II-140 | 5962-9216201HYA | BU-65170J2-110 | 5962-9306502HZC |
| L64230-75 (GEN) | 5962-9050401MYA | BUS-65164II-110 | 5962-9216202HYC | BU-65170J2-130 | 5962-9306502HZC |
| HCPL-6431 | 5962-89571022A | BUS-65164II-140 | 5962-9216202HYA | BU-65170S2-110 | 5962-9306502HXC |
| HCPL-643K | 5962-8957104K2A | BU-65170BS1-110 | 5962-9306501HXC | BU-65170S2-110 | 5962-9306502HXC |
| MN6450S/B CH | 5962-9225302HXA | BU-65170BS1-110 | 5962-9306501HXC | BU-65170S2-130 | 5962-9306502HXC |
| MN6450S/B CH | 5962-9225302HXC | BU-65170BS1-130 | 5962-9306501HXC | BU-65170S2-130 | 5962-9306502HXC |
| MN6450T (GEN) | 5962-9225301HXA | BU-65170BS1-130 | 5962-9306501HXC | BU-65170S2-140 | 5962-9306502HXA |
| MN6450T (GEN) | 5962-9225301HXC | BU-65170BS1-140 | 5962-9306501HXA | BU-65170S2-140 | 5962-9306502HXA |
| HCTS646 (GEN) | 5962R9575901V9A | BU-65170BS1-140 | 5962-9306501HXA | BU-65170S2-150 | 5962-9306502HXA |
| HCTS646 (GEN) | 5962R9575901VJC | BU-65170BS1-150 | 5962-9306501HXA | BU-65170S2-150 | 5962-9306502HXA |
| HCTS646 (GEN) | 5962R9575901VXC | BU-65170BS1-150 | 5962-9306501HXA | BU-65170V2-110 | 5962-9306502HYC |
| LMC6462AMJ-QML | 5962-9560301QPA | BU-65170BV1-110 | 5962-9306501HYC | BU-65170V2-110 | 5962-9306502HYC |
| LMC6464AMJ-QML | 5962-9560302QCA | BU-65170BV1-110 | 5962-9306501HYC | BU-65170V2-130 | 5962-9306502HYC |
| LMC6464AMWG-QML | 5962-9560302QXA | BU-65170BV1-130 | 5962-9306501HYC | BU-65170V2-130 | 5962-9306502HYC |
| L64710-25 (GEN) | 5962-9217102MXC | BU-65170BV1-130 | 5962-9306501HYC | BU-65170V2-140 | 5962-9306502HYA |
| L64710-33 (GEN) | 5962-9217101MXC | BU-65170BV1-140 | 5962-9306501HYA | BU-65170V2-140 | 5962-9306502HYA |
| AD648SH/QMLV | 5962-9753501VGA | BU-65170BV1-140 | 5962-9306501HYA | BU-65170V2-150 | 5962-9306502HYA |
| AD648SQ/QMLV | 5962-9753501VPA | BU-65170BV1-150 | 5962-9306501HYA | BU-65170V2-150 | 5962-9306502HYA |
| AD648TH/QMLV | 5962-9753502VGA | BU-65170BV1-150 | 5962-9306501HYA | BU-65170 (GEN) | 5962-9306509HXA |
| AD648TQ/QMLV | 5962-9753502VPA | BU-65170J1-110 | 5962-9306501HZC | BU-65170 (GEN) | 5962-9306509HYA |
| LMC6482AMJ/883 | 5962-9453401MPA | BU-65170J1-130 | 5962-9306501HZC | BU-65170DG3-110 | 5962-9306530HNC |
| LMC6484AMJ/883 | 5962-9453402MCA | BU-65170S1-110 | 5962-9306501HXC | BU-65170DG3-110 | 5962-9306530HNC |
| LMC6484AMWG/883 | 5962-9453402QXA | BU-65170S1-110 | 5962-9306501HXC | BU-65170DG3-130 | 5962-9306530HNC |
| LMC6484AMWG-QV | 5962-9453402VXA | BU-65170S1-130 | 5962-9306501HXC | BU-65170DG3-130 | 5962-9306530HNC |
| HM-6504B (GEN) | 8102403VA | BU-65170S1-130 | 5962-9306501HXC | BU-65170DG3-140 | 5962-9306530HNA |
| BUS-65111 (GEN) | 5962-8763201XA | BU-65170S1-140 | 5962-9306501HXA | BU-65170DG3-140 | 5962-9306530HNA |
| BUS-65112 (GEN) | 5962-8753501XA | BU-65170S1-140 | 5962-9306501HXA | BU-65170DG3-150 | 5962-9306530HNA |
| BUS-65117 (GEN) | 5962-8753501YA | BU-65170S1-150 | 5962-9306501HXA | BU-65170DG3-150 | 5962-9306530HNA |
| HM1-6514 (GEN) | 8102406VA | BU-65170S1-150 | 5962-9306501HXA | BU-65170DS3-110 | 5962-9306530HXC |
| HM-6514S (GEN) | 8102402VA | BU-65170V1-110 | 5962-9306501HYC | BU-65170DS3-110 | 5962-9306530HXC |
| BU-65142 (GEN) | 5962-8979805TA | BU-65170V1-110 | 5962-9306501HYC | BU-65170DS3-130 | 5962-9306530HXC |
| BU-65142 (GEN) | 5962-8979805ZA | BU-65170V1-130 | 5962-9306501HYC | BU-65170DS3-130 | 5962-9306530HXC |
| BU-65142 (GEN) | 5962-8979806TA | BU-65170V1-130 | 5962-9306501HYC | BU-65170DS3-140 | 5962-9306530HXA |
| BU-65142 (GEN) | 5962-8979806ZA | BU-65170V1-140 | 5962-9306501HYA | BU-65170DS3-140 | 5962-9306530HXA |
| BU-65142 (GEN) | 5962-8979807TA | BU-65170V1-140 | 5962-9306501HYA | BU-65170DS3-150 | 5962-9306530HXA |
| BU-65142 (GEN) | 5962-8979807ZA | BU-65170V1-150 | 5962-9306501HYA | BU-65170DS3-150 | 5962-9306530HXA |
| BUS-65142 (GEN) | 5962-8979801XC | BU-65170V1-150 | 5962-9306501HYA | BU-65170DS6-140 | 5962-9306531HXA |
| BUS-65143 (GEN) | 5962-8979802XA | BU-65170BS2-110 | 5962-9306502HXC | BU-65170DV3-110 | 5962-9306530HYC |
| BUS-65144 (GEN) | 5962-8979801YA | BU-65170BS2-110 | 5962-9306502HXC | BU-65170DV3-110 | 5962-9306530HYC |
| BUS-65145 (GEN) | 5962-8979802YA | BU-65170BS2-130 | 5962-9306502HXC | BU-65170DV3-130 | 5962-9306530HYC |
| BUS-65153II-110 | 5962-9216201HXC | BU-65170BS2-130 | 5962-9306502HXC | BU-65170DV3-130 | 5962-9306530HYC |
| BUS-65153II-140 | 5962-9216201HXA | BU-65170BS2-140 | 5962-9306502HXA | BU-65170DV3-140 | 5962-9306530HYA |
| BUS-65154II-110 | 5962-9216202HXC | BU-65170BS2-140 | 5962-9306502HXA | BU-65170DV3-140 | 5962-9306530HYA |
| BUS-65154II-140 | 5962-9216202HXA | BU-65170BS2-150 | 5962-9306502HXA | BU-65170DV3-150 | 5962-9306530HYA |
| 6516B (GEN) | 8403607JA | BU-65170BS2-150 | 5962-9306502HXA | BU-65170DV3-150 | 5962-9306530HYA |
| HM-6516 (GEN) | 8403601JA | BU-65170BV2-110 | 5962-9306502HYC | BU-65170 (GEN) | 5962-9306510HXA |
| HM-6516 (GEN) | 8403601ZA | BU-65170BV2-110 | 5962-9306502HYC | BU-65170 (GEN) | 5962-9306510HYA |
| 65162C (GEN) | 8403603ZA | BU-65170BV2-130 | 5962-9306502HYC | BU-65170DG6-110 | 5962-9306531HNC |
| HM1-65162/883 | 8403602JA | BU-65170BV2-130 | 5962-9306502HYC | BU-65170DG6-110 | 5962-9306531HNC |
| HM1-65162B/883 | 8403606JA | BU-65170BV2-140 | 5962-9306502HYA | BU-65170DG6-130 | 5962-9306531HNC |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART II, Listed By Generic PIN

| Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN |
|---|---|---|---|---|---|
| BU-65170DG6-130 | 5962-9306531HNC | BU-65171V1-150 | 5962-9306505HYA | BU-65171DV3-110 | 5962-9306534HYC |
| BU-65170DG6-140 | 5962-9306531HNA | BU-65171BS2-110 | 5962-9306506HXC | BU-65171DV3-110 | 5962-9306534HYC |
| BU-65170DG6-140 | 5962-9306531HNA | BU-65171BS2-110 | 5962-9306506HXC | BU-65171DV3-130 | 5962-9306534HYC |
| BU-65170DG6-150 | 5962-9306531HNA | BU-65171BS2-130 | 5962-9306506HXC | BU-65171DV3-130 | 5962-9306534HYC |
| BU-65170DG6-150 | 5962-9306531HNA | BU-65171BS2-130 | 5962-9306506HXC | BU-65171DV3-140 | 5962-9306534HYA |
| BU-65170DS6-110 | 5962-9306531HXC | BU-65171BS2-140 | 5962-9306506HXA | BU-65171DV3-140 | 5962-9306534HYA |
| BU-65170DS6-110 | 5962-9306531HXC | BU-65171BS2-140 | 5962-9306506HXA | BU-65171DV3-150 | 5962-9306534HYA |
| BU-65170DS6-130 | 5962-9306531HXC | BU-65171BS2-150 | 5962-9306506HXA | BU-65171DV3-150 | 5962-9306534HYA |
| BU-65170DS6-130 | 5962-9306531HXC | BU-65171BS2-150 | 5962-9306506HXA | BU-65171DV6-110 | 5962-9306535HYC |
| BU-65170DS6-140 | 5962-9306531HXA | BU-65171BV2-110 | 5962-9306506HYC | BU-65171DV6-110 | 5962-9306535HYC |
| BU-65170DS6-150 | 5962-9306531HXA | BU-65171BV2-110 | 5962-9306506HYC | BU-65171DV6-130 | 5962-9306535HYC |
| BU-65170DS6-150 | 5962-9306531HXA | BU-65171BV2-130 | 5962-9306506HYC | BU-65171DV6-130 | 5962-9306535HYC |
| BU-65170DV6-110 | 5962-9306531HYC | BU-65171BV2-130 | 5962-9306506HYC | BU-65171DV6-140 | 5962-9306535HYA |
| BU-65170DV6-110 | 5962-9306531HYC | BU-65171BV2-140 | 5962-9306506HYA | BU-65171DV6-140 | 5962-9306535HYA |
| BU-65170DV6-130 | 5962-9306531HYC | BU-65171BV2-140 | 5962-9306506HYA | BU-65171DV6-150 | 5962-9306535HYA |
| BU-65170DV6-130 | 5962-9306531HYC | BU-65171BV2-150 | 5962-9306506HYA | BU-65171DV6-150 | 5962-9306535HYA |
| BU-65170DV6-140 | 5962-9306531HYA | BU-65171BV2-150 | 5962-9306506HYA | BU-61581 (GEN) | 5962-9306514HXA |
| BU-65170DV6-140 | 5962-9306531HYA | BU-65171J2-110 | 5962-9306506HZC | BU-61581 (GEN) | 5962-9306514HYA |
| BU-65170DV6-150 | 5962-9306531HYA | BU-65171J2-130 | 5962-9306506HZC | BU-65171DG6-110 | 5962-9306535HNC |
| BU-65170DV6-150 | 5962-9306531HYA | BU-65171S2-110 | 5962-9306506HXC | BU-65171DG6-110 | 5962-9306535HNC |
| BU-65171BS1-110 | 5962-9306505HXC | BU-65171S2-110 | 5962-9306506HXC | BU-65171DG6-130 | 5962-9306535HNC |
| BU-65171BS1-110 | 5962-9306505HXC | BU-65171S2-130 | 5962-9306506HXC | BU-65171DG6-130 | 5962-9306535HNC |
| BU-65171BS1-130 | 5962-9306505HXC | BU-65171S2-130 | 5962-9306506HXC | BU-65171DG6-140 | 5962-9306535HNA |
| BU-65171BS1-130 | 5962-9306505HXC | BU-65171S2-140 | 5962-9306506HXA | BU-65171DG6-140 | 5962-9306535HNA |
| BU-65171BS1-140 | 5962-9306505HXA | BU-65171S2-140 | 5962-9306506HXA | BU-65171DG6-150 | 5962-9306535HNA |
| BU-65171BS1-140 | 5962-9306505HXA | BU-65171S2-150 | 5962-9306506HXA | BU-65171DG6-150 | 5962-9306535HNA |
| BU-65171BS1-150 | 5962-9306505HXA | BU-65171S2-150 | 5962-9306506HXA | BU-65171DS6-110 | 5962-9306535HXC |
| BU-65171BS1-150 | 5962-9306505HXA | BU-65171V2-110 | 5962-9306506HYC | BU-65171DS6-110 | 5962-9306535HXC |
| BU-65171BV1-110 | 5962-9306505HYC | BU-65171V2-110 | 5962-9306506HYC | BU-65171DS6-130 | 5962-9306535HXC |
| BU-65171BV1-110 | 5962-9306505HYC | BU-65171V2-130 | 5962-9306506HYC | BU-65171DS6-130 | 5962-9306535HXC |
| BU-65171BV1-130 | 5962-9306505HYC | BU-65171V2-130 | 5962-9306506HYC | BU-65171DS6-140 | 5962-9306535HXA |
| BU-65171BV1-130 | 5962-9306505HYC | BU-65171V2-140 | 5962-9306506HYA | BU-65171DS6-140 | 5962-9306535HXA |
| BU-65171BV1-140 | 5962-9306505HYA | BU-65171V2-140 | 5962-9306506HYA | BU-65171DS6-150 | 5962-9306535HXA |
| BU-65171BV1-140 | 5962-9306505HYA | BU-65171V2-150 | 5962-9306506HYA | BU-65171DS6-150 | 5962-9306535HXA |
| BU-65171BV1-150 | 5962-9306505HYA | BU-65171V2-150 | 5962-9306506HYA | BU-65178 (GEN) | 5962-9306526HTA |
| BU-65171BV1-150 | 5962-9306505HYA | BU-61581 (GEN) | 5962-9306513HYA | BU-65178 (GEN) | 5962-9306526HUA |
| BU-65171J1-110 | 5962-9306505HZC | BU-65171 (GEN) | 5962-9306513HXA | BU-65178CF3-110 | 5962-9306543HTC |
| BU-65171J1-130 | 5962-9306505HZC | BU-65171DG3-110 | 5962-9306534HNC | BU-65178CF3-110 | 5962-9306543HTC |
| BU-65171S1-110 | 5962-9306505HXC | BU-65171DG3-110 | 5962-9306534HNC | BU-65178CF3-130 | 5962-9306543HTC |
| BU-65171S1-110 | 5962-9306505HXC | BU-65171DG3-130 | 5962-9306534HNC | BU-65178CF3-130 | 5962-9306543HTC |
| BU-65171S1-130 | 5962-9306505HXC | BU-65171DG3-130 | 5962-9306534HNC | BU-65178CF3-140 | 5962-9306543HTA |
| BU-65171S1-130 | 5962-9306505HXC | BU-65171DG3-140 | 5962-9306534HNA | BU-65178CF3-140 | 5962-9306543HTA |
| BU-65171S1-140 | 5962-9306505HXA | BU-65171DG3-140 | 5962-9306534HNA | BU-65178CF3-150 | 5962-9306543HTA |
| BU-65171S1-140 | 5962-9306505HXA | BU-65171DG3-150 | 5962-9306534HNA | BU-65178CF3-150 | 5962-9306543HTA |
| BU-65171S1-150 | 5962-9306505HXA | BU-65171DG3-150 | 5962-9306534HNA | BU-65178CG3-110 | 5962-9306543HMC |
| BU-65171S1-150 | 5962-9306505HXA | BU-65171DS3-110 | 5962-9306534HXC | BU-65178CG3-110 | 5962-9306543HMC |
| BU-65171V1-110 | 5962-9306505HYC | BU-65171DS3-110 | 5962-9306534HXC | BU-65178CG3-130 | 5962-9306543HMC |
| BU-65171V1-110 | 5962-9306505HYC | BU-65171DS3-130 | 5962-9306534HXC | BU-65178CG3-130 | 5962-9306543HMC |
| BU-65171V1-130 | 5962-9306505HYC | BU-65171DS3-130 | 5962-9306534HXC | BU-65178CG3-140 | 5962-9306543HMA |
| BU-65171V1-130 | 5962-9306505HYC | BU-65171DS3-140 | 5962-9306534HXA | BU-65178CG3-140 | 5962-9306543HMA |
| BU-65171V1-140 | 5962-9306505HYA | BU-65171DS3-140 | 5962-9306534HXA | BU-65178CG3-150 | 5962-9306543HMA |
| BU-65171V1-140 | 5962-9306505HYA | BU-65171DS3-150 | 5962-9306534HXA | BU-65178CG3-150 | 5962-9306543HMA |
| BU-65171V1-150 | 5962-9306505HYA | BU-65171DS3-150 | 5962-9306534HXA | BU-65178CP3-110 | 5962-9306543HUC |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART II, Listed By Generic PIN

| Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN |
|---|---|---|---|---|---|
| BU-65178CP3-110 | 5962-9306543HUC | SMC9-65608EV-30SV | 5962-8959847VZC | 6580-502 | 5962-94B0201QYA |
| BU-65178CP3-130 | 5962-9306543HUC | SMDJ-65608EV-30SV | 5962-8959847VTC | 6580-502 (GEN) | 5962-94B0201MYA |
| BU-65178CP3-130 | 5962-9306543HUC | 65608-35 (GEN) | 5962-8959819VTC | 6580-526 | 5962-98A2001QXC |
| BU-65178CP3-140 | 5962-9306543HUA | 65608-35 (GEN) | 5962-8959819VZC | 6580-527 | 5962-98A3301QXC |
| BU-65178CP3-140 | 5962-9306543HUA | 65608-35 (GEN) | 5962-8959836VTC | 6580-530 | 5962-98A1001QXC |
| BU-65178CP3-150 | 5962-9306543HUA | 65608-35 (GEN) | 5962-8959836VZC | 6580-533 | 5962-99A1801NXB |
| BU-65178CP3-150 | 5962-9306543HUA | 65608-45 (GEN) | 5962-8959835VTC | 6580-535 | 5962-99A2501QXC |
| BU-65179 (GEN) | 5962-9306527HMA | 65608-45 (GEN) | 5962-8959835VZC | 6583-508 | 5962-98A2101QXC |
| BU-65179 (GEN) | 5962-9306527HTA | MMC9-65608EV-45MQ | 5962-8959818MZC | 6583-512 | 5962-98A2102QXC |
| BU-65179 (GEN) | 5962-9306527HUA | MMDJ-65608EV-45MQ | 5962-8959818MTC | 6589-007 | 5962-00A0501QXC |
| BU-65179CF3-110 | 5962-9306544HTC | SMC9-65608EV-45SV | 5962-8959818VZC | AD660SQ/883B | 5962-9463301MLA |
| BU-65179CF3-110 | 5962-9306544HTC | SMDJ-65608EV-45SV | 5962-8959818VTC | LMC660 (GEN) | 5962-9209301MCA |
| BU-65179CF3-130 | 5962-9306544HTC | MMDJ-65609EV-40MQ | 5962-0250101QXC | LPC660 (GEN) | 5962-9209302MCA |
| BU-65179CF3-130 | 5962-9306544HTC | SMDJ-65609EV-40SR | 5962R0250101VXC | MAX660MJA/883B | 5962-9463201MPA |
| BU-65179CF3-140 | 5962-9306544HTA | SMDJ-65609EV-40SV | 5962-0250101VXC | MAX660MLP/883B | 5962-9463201M2C |
| BU-65179CF3-140 | 5962-9306544HTA | HS-65643A (GEN) | 5962F9582201VXC | 66012-300 | 5962-9800201KEA |
| BU-65179CF3-150 | 5962-9306544HTA | HS-65647 (GEN) | 5962F9582301QXC | 66012-300 | 5962-9800201KEC |
| BU-65179CF3-150 | 5962-9306544HTA | HS-65647 (GEN) | 5962F9582301QYC | 66012-300J | 5962-9800201KXA |
| BU-65179CG3-110 | 5962-9306544HMC | HS-65647 (GEN) | 5962F9582301VXC | 66012-300J | 5962-9800201KXC |
| BU-65179CG3-110 | 5962-9306544HMC | HS-65647 (GEN) | 5962F9582301VYC | 66013-001 | 8102801EA |
| BU-65179CG3-130 | 5962-9306544HMC | 6565-041 | 5962-98A0801QXC | 66013-001 | 8102801EC |
| BU-65179CG3-130 | 5962-9306544HMC | 6568-009 | 5962-96A0601QXC | 66013-301 | 5962-9800101KEA |
| BU-65179CG3-140 | 5962-9306544HMA | 6571-026 | 5962-99A2301QXC | 66013-301 | 5962-9800101KEC |
| BU-65179CG3-140 | 5962-9306544HMA | 6571-028 | 5962-00A0801QXC | 66024 (GEN) | 5962-87679012A |
| BU-65179CG3-150 | 5962-9306544HMA | 6571-029 (GEN) | 5962-99A2401QXC | 66024-001 | 5962-8767901EA |
| BU-65179CG3-150 | 5962-9306544HMA | 6571-030 | 5962-00A0701QXC | 66024-001 | 5962-8767901EC |
| BU-65179CP3-110 | 5962-9306544HUC | 6571-031 | 5962-99A2402QXC | 66024-001J | 5962-8767901TA |
| BU-65179CP3-110 | 5962-9306544HUC | 6574-027 | 5962-97A1401QXC | 66024-001J | 5962-8767901TC |
| BU-65179CP3-130 | 5962-9306544HUC | 6577-024 | 5962-99A2001QXC | 66024-300 | 5962-8767905KEA |
| BU-65179CP3-130 | 5962-9306544HUC | 6577-524 | 5962-99A0602QYC | 66024-300 | 5962-8767905KEC |
| BU-65179CP3-140 | 5962-9306544HUA | 6577-525 | 5962-99A0601NXB | 66024-300T | 5962-8767905KTA |
| BU-65179CP3-140 | 5962-9306544HUA | 65787 (GEN) | 5962-8969601XA | 66024-300T | 5962-8767905KTC |
| BU-65179CP3-150 | 5962-9306544HUA | 65787 (GEN) | 5962-8969603XA | 66056-005 | 5962-9085501HPA |
| BU-65179CP3-150 | 5962-9306544HUA | 6580-016 | 5962-96A1701QXA | 66056-005 | 5962-9085501HPC |
| AD652SQ/883B | 5962-9322201MEA | 6580-020 | 5962-97A1201QZC | 66056-005J | 5962-9085501HXA |
| 65262 (GEN) | 8413201RA | 6580-020 (GEN) | 5962-97A1201QXC | 66056-005J | 5962-9085501HXC |
| HM4-65262B/883 | 8413203YA | 6580-024 | 5962-97A1202QYC | 66056-103 | 8102802PA |
| HM-65262 (GEN) | 8413203RA | 6580-025 | 5962-97A1301QXC | 66056-103 | 8102802PC |
| HCPL-6531 | 5962-87679032A | 6580-028 | 5962-98A0601QXC | 66056-301 | 5962-9085501KPA |
| HCPL-653K | 5962-8767907K2A | 6580-029 | 5962-98A0901NXB | 66056-301 | 5962-9085501KPC |
| HCPL-6551 | 5962-8767904FC | 6580-031 | 5962-98A1301QXC | 66056-301J | 5962-9085501KXA |
| 6553-018 | 5962-95A0301Q3A | 6580-032 | 5962-98A1401QXC | 66056-301J | 5962-9085501KXC |
| 6553-018 (GEN) | 5962-95A0301M3A | 6580-033 | 5962-98A1501NXB | 66056-300 | 5962-9800102KPA |
| 6556-033 | 5962-99A0101QXC | 6580-045 | 5962-98A0401QXC | 66056-300 | 5962-9800102KPC |
| 6559-008 | 5962-95A0101QXA | 6580-046 | 5962-98A0201QXC | 66058-105 | 5962-8981001PA |
| 6559-049 | 5962-99A2201QXC | 6580-050 | 5962-98A1901QXC | 66058-105 | 5962-8981001PC |
| 6559-055 | 5962-99A1701QXC | 6580-051 | 5962-98A1901QYC | 66058-300 | 5962-8981002KPA |
| 6559-008 (GEN) | 5962-95A0101MXA | 6580-057 | 5962-98A1201QXC | 66058-300 | 5962-8981002KPC |
| HCPL-655K | 5962-8767908KFC | 6580-062 (GEN) | 5962-99A1102QYC | 66058-003 | 5962-8978501PA |
| MM0-65608EV-30MQ | 5962-8959847Q6A | 6580-063 | 5962-98A0701QXC | 66058-003 | 5962-8978501PC |
| MMC9-65608EV-30MQ | 5962-8959847QZC | 6580-064 | 5962-99A1101NZB | 66058-300 | 5962-8978503KPA |
| MMDJ-65608EV-30MQ | 5962-8959847QTC | 6580-064 (GEN) | 5962-99A1101NXB | 66058-300 | 5962-8978503KPC |
| SM0-65608EV-30SV | 5962-8959847V6A | 6580-065 | 5962-00A0201QXC | 66071-001 | 5962-8978501XA |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART II, Listed By Generic PIN

| Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN |
|---|---|---|---|---|---|
| 66071-001 | 5962-8978501XC | HM1-6617 (GEN) | 5962-8954001JA | 6656 (GEN) | 5962H9751702QXC |
| 66071-300 | 5962-8978505KXA | HM1-6617B (GEN) | 5962-8954002JA | 6656 (GEN) | 5962H9751702QYC |
| 66071-300 | 5962-8978505KXC | HM4-6617 (GEN) | 5962-8954001XA | 6656 (GEN) | 5962H9751702QZC |
| 66072-001/883B | 8102801XA | HM4-6617B (GEN) | 5962-8954002XA | 6656 (GEN) | 5962H9751702VXC |
| 66072-001/883B | 8102801XC | HM6-6617/883 | 5962-8954001LA | 6656 (GEN) | 5962H9751702VYC |
| 66072-300 | 5962-9800101KXA | HM6-6617B (GEN) | 5962-8954002LA | 6656 (GEN) | 5962H9751702VZC |
| 66072-300 | 5962-9800101KXC | HS-6617 (GEN) | 5962R9570801TJC | HX6656/NQHC | 5962H9864401QYC |
| 66079-000 | 5962-9167601HYA | HS-6617 (GEN) | 5962R9570801TXC | HX6656/NQHT | 5962H9864402QYC |
| 66079-000 | 5962-9167601HYC | HS-6617 (GEN) | 5962R9570801VJC | HX6656/NVHC | 5962H9864401VYC |
| 66079-001 | 5962-9167601HXA | HS-6617 (GEN) | 5962R9570801VXC | HX6656/NVHT | 5962H9864402VYC |
| 66079-001 | 5962-9167601HXC | HS-6617 (GEN) | 5962R9570801QJC | HX6656/XQHC | 5962H9864401QZC |
| 66079-300 | 5962-9167601KXA | HS-6617 (GEN) | 5962R9570801QXC | HX6656/XQHT | 5962H9864402QZC |
| 66079-300 | 5962-9167601KXC | LMC662 (GEN) | 5962-9209401MPA | HX6656/XVHC | 5962H9864401VZC |
| 66079-301 | 5962-9167601KYA | LPC662 (GEN) | 5962-9209402MPA | HX6656/XVHT | 5962H9864402VZC |
| 66079-301 | 5962-9167601KYC | 66212 (GEN) | 5962-94A1501MXA | MAX666MJA/883B | 5962-9212603MPA |
| 66111 (GEN) | 5962-94A1401MXA | LMH6624J-QML | 5962-0254401QPA | 6664 (GEN) | 5962H9754401QZC |
| 66115-103 | 5962-8957101PA | LMH6624J-QMLV | 5962-0254401VPA | 6664 (GEN) | 5962H9754401VZC |
| 66115-103 | 5962-8957101PC | LMH6624WG-QML | 5962-0254401QZA | 6664 (GEN) | 5962H9754402QZC |
| 66115-105 | 5962-8957001PA | LMH6624WG-QMLV | 5962-0254401VZA | 6664 (GEN) | 5962H9754402VZC |
| 66115-105 | 5962-8957001PC | LMH6628JFQML | 5962F0254501MPA | HX6664/XQHC-1 | 5962H99A0401QZC |
| 66115-301 | 5962-8957103KPA | LMH6628JFQMLV | 5962F0254501VPA | HX6664/XQHC-2 | 5962H99A0402QZC |
| 66115-301 | 5962-8957103KPC | LMH6628J-QML | 5962-0254501MPA | HX6664/XQHC-3 | 5962H99A0403QZC |
| 66115-302 | 5962-8957002KPA | LMH6628J-QMLV | 5962-0254501VPA | HX6664/XQHC-4 | 5962H99A0404QZC |
| 66115-302 | 5962-8957002KPC | LMH6628WGFQML | 5962F0254501MZA | HS1-6664RH-8 | 5962F9562601QXC |
| 66123-001 | 81028032A | LMH6628WGFQMLV | 5962F0254501VZA | HS1-6664RH-Q | 5962F9562601VXC |
| 66123-001 | 81028032C | LMH6628WG-QML | 5962-0254501MZA | HS1-6664RH-T | 5962R9562601TXC |
| 66123-300 | 5962-9800103K2A | LMH6628WG-QMLV | 5962-0254501VZA | HS9-6664RH-8 | 5962F9562601QYC |
| 66123-300 | 5962-9800103K2C | HCPL-663K | 5962-9800103K2A | HS9-6664RH-Q | 5962F9562601VYC |
| 66124-001 | 5962-89785022A | MAX663MJA/883B | 5962-9212601MPA | HS9-6664RH-T | 5962R9562601TYC |
| 66124-001 | 5962-89785022C | BUS-66300II-140 | 5962-8858601XA | AD667SD/883B | 5962-8865901XA |
| 66124-300 | 5962-8978504K2A | BUS-66300II-883B | 5962-8858601XC | AD667SE/883B | 5962-88659013A |
| 66124-300 | 5962-8978504K2C | BUS-66301II-140 | 5962-8858601YA | MAX667MJA/883B | 5962-9212604MPA |
| 66125-001 | 5962-87679032A | BUS-66301II-883B | 5962-8858601YC | AD668SQ/883B | 5962-9557901MLA |
| 66125-001 | 5962-87679032C | HCPL-6631 | 81028032A | 6685 (GEN) | 8600803EA |
| 66125-300 | 5962-8767907K2A | 66311 (GEN) | 5962-94A1601MXA | 6685 (GEN) | 8600803IA |
| 66126-103 | 5962-8767902PA | AD664TD-BIP/883B | 5962-8871902MXA | AM6687 (GEN) | 7801902EA |
| 66126-103 | 5962-8767902PC | AD664TD-UNI/883B | 5962-8871901MXA | AD670SD/883B | 5962-8763501RA |
| 66126-103J | 5962-8767902XA | AD664TE/883B | 5962-8871903MYA | LMH6702J-QML | 5962-0254601QPA |
| 66126-103J | 5962-8767902XC | MAX664MJA/883B | 5962-9212602MPA | LMH6702WG-QML | 5962-0254601QZA |
| 66126-300 | 5962-8767906KPA | HM1-6642 (GEN) | 5962-8869001JA | LMH6714J-QML | 5962-0420201QPA |
| 66126-300 | 5962-8767906KPC | HM1-6642B (GEN) | 5962-8869002JA | LMH6714WG-QML | 5962-0420201QZA |
| 66126-300J | 5962-8767906KXA | HM4-6642 (GEN) | 5962-88690013A | LMH6715JFQML | 5962F0254701QPA |
| 66126-300J | 5962-8767906KXC | HM4-6642B (GEN) | 5962-88690023A | LMH6715JFQMLV | 5962F0254701VPA |
| 66126-105 | 5962-9085401HPA | HM6-6642 (GEN) | 5962-8869001LA | LMH6715J-QML | 5962-0254701QPA |
| 66126-105J | 5962-9085401HXA | HM6-6642B (GEN) | 5962-8869002LA | LMH6715J-QMLV | 5962-0254701VPA |
| 66126-105J | 5962-9085401HXC | HCPL-665K | 5962-9800104KFA | AD671S-500 (GEN) | 5962-9551901MLA |
| 66126-105 | 5962-9085401HPC | HCPL-6651 | 8102804FC | UT6716455 (GEN) | 5962H3829437BNA |
| 66126-300 | 5962-9085401KPA | 6656 (GEN) | 5962H9751701QXC | UT6716455 (GEN) | 5962H3829437BXA |
| 66126-300 | 5962-9085401KPC | 6656 (GEN) | 5962H9751701QYC | UT6716455 (GEN) | 5962H3829437SNA |
| 66126-300J | 5962-9085401KXA | 6656 (GEN) | 5962H9751701QZC | UT6716455 (GEN) | 5962H3829437SXA |
| 66126-300J | 5962-9085401KXC | 6656 (GEN) | 5962H9751701VXC | UT6716470 | 5962H3829436BNA |
| 66136-001 | 5962-89571022A | 6656 (GEN) | 5962H9751701VYC | UT6716470 | 5962H3829436BNC |
| 66136-301 | 5962-8957104K2A | 6656 (GEN) | 5962H9751701VZC | UT6716470 | 5962H3829436BXA |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

| Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN |
|---|---|---|---|---|---|
| UT6716470 | 5962H3829436BXC | 7204-40 (GEN) | 5962-8956805VTC | 68000-12 (GEN) | 8202104TA |
| UT6716470 | 5962H3829436SNA | 7204-40 (GEN) | 5962-8956805VUC | 68000-12 (GEN) | 8202104XA |
| UT6716470 | 5962H3829436SNC | 7204-40 (GEN) | 5962-8956805VYC | 68000-12 (GEN) | 8202104YA |
| UT6716470 | 5962H3829436SXA | 7204-50 (GEN) | 5962-8956804QNC | 68000-12 (GEN) | 8202104ZA |
| UT6716470 | 5962H3829436SXC | 7204-50 (GEN) | 5962-8956804QTC | TS68C000MC1B/C12A | 5962-8946203MYA |
| UT6716485 | 5962H3829435BNA | 7204-50 (GEN) | 5962-8956804QUC | TS68C000MCB/C12A | 5962-8946203MYC |
| UT6716485 | 5962H3829435BNC | 7204-50 (GEN) | 5962-8956804QYC | TS68C000ME1B/C12A | 5962-8946203MXA |
| UT6716485 | 5962H3829435BXA | 7204-50 (GEN) | 5962-8956804VNC | TS68C000MF1B/C12A | 5962-8946203MZA |
| UT6716485 | 5962H3829435BXC | 7204-50 (GEN) | 5962-8956804VTC | TS68C000MFB/C12A | 5962-8946203MZC |
| UT6716485 | 5962H3829435SNA | 7204-50 (GEN) | 5962-8956804VUC | TS68C000MR1B/C12A | 5962-8946203MUA |
| UT6716485 | 5962H3829435SNC | 7204-50 (GEN) | 5962-8956804VYC | TS68C000MRB/C12A | 5962-8946203MUC |
| UT6716485 | 5962H3829435SXA | 6721-052 | 5962-98A0301QXC | 68000-6 (GEN) | 8202101TA |
| UT6716485 | 5962H3829435SXC | LMH6722J-QML | 5962-0324901QCA | 68000-6 (GEN) | 8202101YA |
| AD671S-750 (GEN) | 5962-9551902MLA | LMH6722WG-QML | 5962-0324901QZA | 68000-6 (GEN) | 8202101ZA |
| LMH6720J-QML | 5962-0420301QPA | AD673SD/883 | 5962-8850502RA | 68000-8 (GEN) | 8202102TA |
| LMH6720WG-QML | 5962-0420301QZA | HCPL-673K | 5962-8978504K2A | 68000-8 (GEN) | 8202102UC |
| 7204-15 (GEN) | 5962-8956808QUC | HCPL-6731 | 5962-89785022A | 68000-8 (GEN) | 8202102XA |
| 7204-15 (GEN) | 5962-8956808QYC | 674 (GEN) | 5962-9468101M2C | 68000-8 (GEN) | 8202102YA |
| 7204-15 (GEN) | 5962-8956808VUC | 674 (GEN) | 5962-9468101MGC | 68000-8 (GEN) | 8202102ZA |
| 7204-15 (GEN) | 5962-8956808VYC | 674 (GEN) | 5962-9468101MPA | TS68C000MC1B/C8A | 5962-8946201MYA |
| MMCP-67204FV-15MQ | 5962-8956808QTC | 674ZA (GEN) | 5962-9169001M3A | TS68C000MCB/C8A | 5962-8946201MYC |
| MMDP-67204FV-15MQ | 5962-8956808QNC | 674ZA (GEN) | 5962-9169001MXC | TS68C000ME1B/C8A | 5962-8946201MXA |
| SMCP-67204FV-15SR | 5962D8956808VTC | 674ZB (GEN) | 5962-9169002M3A | TS68C000MF1B/C8A | 5962-8946201MZA |
| SMCP-67204FV-15SV | 5962-8956808VTC | 674ZB (GEN) | 5962-9169002MXC | TS68C000MFB/C8A | 5962-8946201MZC |
| SMDP-67204FV-15SR | 5962D8956808VNC | AD674AT (GEN) | 5962-88615023A | TS68C000MR1B/C8A | 5962-8946201MUA |
| SMDP-67204FV-15SV | 5962-8956808VNC | AD674AT (GEN) | 5962-8861502XA | TS68C000MRB/C8A | 5962-8946201MUC |
| MMCP-67204HV-25MQ | 5962-8956810QTC | AD674AU (GEN) | 5962-88615013A | 68HC001-10 (GEN) | 5962-8946205MUA |
| MMDP-67204HV-25MQ | 5962-8956810QNC | AD674AU (GEN) | 5962-8861501XA | 68HC001-12 (GEN) | 5962-8946206MUA |
| SMCP-67204HV-25SR | 5962D8956810VTC | AD674BTD/883 | 5962-9169003MXA | 68HC001-8 (GEN) | 5962-8946204MUA |
| SMCP-67204HV-25SV | 5962-8956810VTC | AD674BTE/883B | 5962-9169003M3A | CF68006HFG | 5962-93A2401MYA |
| SMDP-67204HV-25SR | 5962D8956810VNC | AD674BTE/883B | 5962-9169005M3A | CF68010HFG | 5962-93A2501MYA |
| SMDP-67204HV-25SV | 5962-8956810VNC | MAX674MJA/883B | 5962-9468102MPA | CF68014BHFG | 5962-93A2601MYA |
| 7204-30 (GEN) | 5962-8956806QUC | MAX674MLP/883B | 5962-9468102M2C | CF68016GB | 5962-93A2301MXA |
| 7204-30 (GEN) | 5962-8956806QYC | MAX674MTV/883B | 5962-9468102MGC | CF68017GB | 5962-93A2401MXA |
| 7204-30 (GEN) | 5962-8956806VUC | SP674AT (GEN) | 5962-9169004M3C | 68020-12 (GEN) | 5962-8603201XA |
| 7204-30 (GEN) | 5962-8956806VYC | SP674AT (GEN) | 5962-9169004MXC | TS68020MF1B/C16 | 5962-8603202YA |
| MMCP-67204FV-30MQ | 5962-8956806QTC | HCPL-675K | 5962-9800201KFC | TS68020MFB/C16 | 5962-8603202YC |
| MMCP-67204HV-30MQ | 5962-8956809QTC | HCPL-6751 | 8302401FC | TS68020MR1B/C16 | 5962-8603202XA |
| MMDP-67204FV-30MQ | 5962-8956806QNC | AD676TD/883B | 5962-9474301MXA | TS68020MRB/C16 | 5962-8603202XC |
| MMDP-67204HV-30MQ | 5962-8956809QNC | AD677TD/883B | 5962-9559201MEA | TS68020MF1B/C20 | 5962-8603203YA |
| SMCP-67204FV-30SR | 5962D8956806VTC | MAX680MJA/883B | 5962-9312001MPA | TS68020MFB/C20 | 5962-8603203YC |
| SMCP-67204FV-30SV | 5962-8956806VTC | 68000-10 (GEN) | 8202103TA | TS68020MR1B/C20 | 5962-8603203XA |
| SMCP-67204HV-30SR | 5962D8956809VTC | 68000-10 (GEN) | 8202103UC | TS68020MRB/C20 | 5962-8603203XC |
| SMCP-67204HV-30SV | 5962-8956809VTC | 68000-10 (GEN) | 8202103XA | TS68020MF1B/C25 | 5962-8603204YA |
| SMDP-67204FV-30SR | 5962D8956806VNC | 68000-10 (GEN) | 8202103YA | TS68020MFB/C25 | 5962-8603204YC |
| SMDP-67204FV-30SV | 5962-8956806VNC | 68000-10 (GEN) | 8202103ZA | TS68020MR1B/C25 | 5962-8603204XA |
| SMDP-67204HV-30SR | 5962D8956809VNC | TS68C000MC1B/C10A | 5962-8946202MYA | TS68020MRB/C25 | 5962-8603204XC |
| SMDP-67204HV-30SV | 5962-8956809VNC | TS68C000MCB/C10A | 5962-8946202MYC | 6802-503 | 5962-99A2101QXA |
| 7204-40 (GEN) | 5962-8956805QNC | TS68C000ME1B/C10A | 5962-8946202MXA | 68030-16 (GEN) | 5962-8946401XA |
| 7204-40 (GEN) | 5962-8956805QTC | TS68C000MF1B/C10A | 5962-8946202MZA | 68030-16 (GEN) | 5962-8946401YC |
| 7204-40 (GEN) | 5962-8956805QUC | TS68C000MFB/C10A | 5962-8946202MZC | 68030-20 (GEN) | 5962-8946402XA |
| 7204-40 (GEN) | 5962-8956805QYC | TS68C000MR1B/C10A | 5962-8946202MUA | 68030-20 (GEN) | 5962-8946402YC |
| 7204-40 (GEN) | 5962-8956805VNC | TS68C000MRB/C10A | 5962-8946202MUC | 68030-25 (GEN) | 5962-8946403XA |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

| Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN |
|---|---|---|---|---|---|
| 68030-25 (GEN) | 5962-8946403YC | TS68302MRB/C16 | 5962-9315901QXC | 6856 (GEN) | 5962H9215307VUC |
| 68030-33 (GEN) | 5962-8946404XA | 68332-16 (GEN) | 5962-9150101MYA | 6856 (GEN) | 5962H9215307VZC |
| 68030-33 (GEN) | 5962-8946404YC | 68332-16 (GEN) | 5962-9150101QYC | 6856 (GEN) | 5962H9215308Q9C |
| TS68040MF1B/C25 | 5962-9314301MZA | 68332-16 (GEN) | 5962-9150101QZA | 6856 (GEN) | 5962H9215308QMC |
| TS68040MF1B/C33 | 5962-9314302MZA | TS68332MAB/C16 | 5962-9150101MXA | 6856 (GEN) | 5962H9215308QUC |
| TS68040MFB/C25 | 5962-9314301MZC | TS68332MR1B/C16 | 5962-9150101MZA | 6856 (GEN) | 5962H9215308QZC |
| TS68040MFTB/C25 | 5962-9314301MYC | TS68332MRB/C16 | 5962-9150101MZC | 6856 (GEN) | 5962H9215308V9C |
| TS68040MR1B/C25 | 5962-9314301MXA | TS68332MAB/C20 | 5962-9150102MXA | 6856 (GEN) | 5962H9215308VMC |
| TS68040MRB/C25 | 5962-9314301MXC | TS68332MR1B/C20 | 5962-9150102MZA | 6856 (GEN) | 5962H9215308VUC |
| TS68040MFB/C33 | 5962-9314302MZC | TS68332MRB/C20 | 5962-9150102MZC | 6856 (GEN) | 5962H9215308VZC |
| TS68040MFTB/C33 | 5962-9314302MYC | TS68EN360MAB/C25 | 5962-9760701MYA | 6856 (GEN) | 5962R9215305QUC |
| TS68040MR1B/C33 | 5962-9314302MXA | TS68EN360MAB/C33 | 5962-9760702MYA | 6856 (GEN) | 5962R9215305QZC |
| TS68040MRB/C33 | 5962-9314302MXC | TS68EN360MR1B/C25 | 5962-9760701MXA | 6856 (GEN) | 5962R9215305VUC |
| 6805-053 | 5962-00A0901NXB | TS68EN360MR1B/C33 | 5962-9760702MXA | 6856 (GEN) | 5962R9215305VZC |
| 6805-057 | 5962-00A0101QXC | TS68EN360MRB/C25 | 5962-9760701MXC | 6856 (GEN) | 5962R9215306QUC |
| 6805-063 | 5962-01A1101NXB | TS68EN360MRB/C33 | 5962-9760702MXC | 6856 (GEN) | 5962R9215306QZC |
| CF68105HFG | 5962-93A2301MYA | AD684SQ/883B | 5962-9201301MEA | 6856 (GEN) | 5962R9215306VUC |
| CF68107BHFG | 5962-93A2701MYA | 684002-20 (GEN) | 5962-9560004M8A | 6856 (GEN) | 5962R9215306VZC |
| 68HC11A0 (GEN) | 5962-9051001XA | 684002-20 (GEN) | 5962-9560008M8A | 6856 (GEN) | 5962R9215307QUC |
| 68HC11A0 (GEN) | 5962-9051001YC | 684002-25 (GEN) | 5962-9560003M8A | 6856 (GEN) | 5962R9215307QZC |
| TS68HC11A1MC1B/C | 5962-9051002XA | 684002-25 (GEN) | 5962-9560007M8A | 6856 (GEN) | 5962R9215307VUC |
| TS68HC11A1MCB/C | 5962-9051002XC | 684002-35 (GEN) | 5962-9560002M8A | 6856 (GEN) | 5962R9215307VZC |
| TS68HC11A1MF1B/C | 5962-9051002YA | 684002-35 (GEN) | 5962-9560006M8A | 6856 (GEN) | 5962R9215308QUC |
| TS68HC11A1MFB/C | 5962-9051002YC | TS68C429AMFB/C | 5962-9551801MYC | 6856 (GEN) | 5962R9215308QZC |
| CF68115HFG | 5962-93A2801MYA | TS68C429AMRB/C | 5962-9551801MXC | 6856 (GEN) | 5962R9215308VUC |
| 68154 (GEN) | 5962-8857201QA | 68442-8 (GEN) | 5962-8681101XA | 6856 (GEN) | 5962R9215308VZC |
| 68155 (GEN) | 5962-8866601QA | 68442-8 (GEN) | 5962-8681101YA | HC6856/1XQHCC | 5962H9215319QZC |
| 6817-045 | 5962-00A0601NXB | LT685 (GEN) | 8600801EA | HC6856/1XVHCC | 5962H9215319VZC |
| SL68172/BXA | 5962-8770501XA | LT685 (GEN) | 8600801IA | 6856 (GEN) | 5962H9215305Q4C |
| 6817-531 | 5962-00A1501QXC | LT685 (GEN) | 8600802EA | 6856 (GEN) | 5962H9215305V4C |
| 6817-532 | 5962-00A0401QXC | LT685 (GEN) | 8600802IA | 6856 (GEN) | 5962H9215307Q4C |
| 6817-533 | 5962-01A0701QXC | 6856 (GEN) | 5962H9215305Q9C | 6856 (GEN) | 5962H9215307V4C |
| 6817-534 | 5962-01A0601QXC | 6856 (GEN) | 5962H9215305QMC | 6856 (GEN) | 5962R9215305Q4C |
| 6817-536 | 5962-01A1001NXB | 6856 (GEN) | 5962H9215305QUC | 6856 (GEN) | 5962R9215305V4C |
| 6821-016 | 5962-00A1201NXB | 6856 (GEN) | 5962H9215305QZC | 6856 (GEN) | 5962R9215307Q4C |
| 6821-526 | 5962-00A1301QXC | 6856 (GEN) | 5962H9215305V9C | 6856 (GEN) | 5962R9215307V4C |
| 6821-527 | 5962-00A1401QXC | 6856 (GEN) | 5962H9215305VMC | 68562 (GEN) | 5962-8681001XA |
| 68230-10 (GEN) | 5962-9317002MXC | 6856 (GEN) | 5962H9215305VUC | AM686 (GEN) | 7801801EA |
| 68230-10 (GEN) | 5962-9317002MYA | 6856 (GEN) | 5962H9215305VZC | AM686 (GEN) | 7801801IA |
| 68230-8 (GEN) | 5962-9317001MXC | 6856 (GEN) | 5962H9215306Q9C | 68681 (GEN) | 5962-8856603QA |
| 68230-8 (GEN) | 5962-9317001MYA | 6856 (GEN) | 5962H9215306QMC | 68681 (GEN) | 5962-8856603UA |
| 6825-008 | 5962-99A0702QYC | 6856 (GEN) | 5962H9215306QUC | 68C681 (GEN) | 5962-8953203QA |
| 6825-010 | 5962-99A0701NXB | 6856 (GEN) | 5962H9215306QZC | 68C681 (GEN) | 5962-8953203UA |
| 6825-013 | 5962-01A1201NXB | 6856 (GEN) | 5962H9215306V9C | AM687 (GEN) | 7801901EA |
| 6825-512 | 5962-99A0902QYC | 6856 (GEN) | 5962H9215306VMC | AD688SQ/883B | 5962-9321401MEA |
| 6825-514 | 5962-99A0901NXB | 6856 (GEN) | 5962H9215306VUC | AS68HC811E2Q52/883 | 5962-8952701YC |
| 6825-518 | 5962-01A0401QXC | 6856 (GEN) | 5962H9215306VZC | TS68HC811E2MC1B/C | 5962-8952701XA |
| 6829-010 | 5962-00A1601QXC | 6856 (GEN) | 5962H9215307Q9C | TS68HC811E2MCB/C | 5962-8952701XC |
| 6830-005 | 5962-00A1101QXC | 6856 (GEN) | 5962H9215307QMC | TS68HC811E2MF1B/C | 5962-8952701YA |
| 6830-006 (GEN) | 5962-00A0301QXC | 6856 (GEN) | 5962H9215307QUC | TS68HC811E2MFB/C | 5962-8952701YC |
| 6830-007 | 5962-00A0302QXC | 6856 (GEN) | 5962H9215307QZC | 68881-12 (GEN) | 5962-8602101XA |
| TS68302MAB/C16 | 5962-9315901QYA | 6856 (GEN) | 5962H9215307V9C | 68881-16 (GEN) | 5962-8602102XA |
| TS68302MR1B/C16 | 5962-9315901QXA | 6856 (GEN) | 5962H9215307VMC | 68881-16 (GEN) | 5962-8602102YA |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

| Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN |
|---|---|---|---|---|---|
| 68881-20 (GEN) | 5962-8602103XA | UT69R00012WCC | 5962-9855201QYC | UT69151DXE/WVCR | 5962R9466311VYC |
| 68881-20 (GEN) | 5962-8602103YA | UT69R00012WCCH | 5962H9855201QYC | UT69151E (GEN) | 5962H9211802Q9A |
| TS68882MF1B/C16 | 5962-8946301YA | UT69R00012WCCH | 5962H9855201VYC | UT69151E (GEN) | 5962H9211802QXA |
| TS68882MFB/C16 | 5962-8946301YC | UT69R00016FCA | 5962-9855202QZA | UT69151E (GEN) | 5962H9211802QYA |
| TS68882MR1B/C16 | 5962-8946301XA | UT69R00016FCAH | 5962H9855202QZA | UT69151E (GEN) | 5962H9211802QZA |
| TS68882MRB/C16 | 5962-8946301XC | UT69R00016FCAH | 5962H9855202VZA | UT69151E (GEN) | 5962H9211802V9A |
| TS68882MF1B/C20 | 5962-8946302YA | UT69R00016FCC | 5962-9855202QZC | UT69151E (GEN) | 5962H9211802VXA |
| TS68882MFB/C20 | 5962-8946302YC | UT69R00016FCCH | 5962H9855202QZC | UT69151E (GEN) | 5962H9211802VYA |
| TS68882MR1B/C20 | 5962-8946302XA | UT69R00016FCCH | 5962H9855202VZC | UT69151E (GEN) | 5962H9211802VZA |
| TS68882MRB/C20 | 5962-8946302XC | UT69R00016GCA | 5962-9855202QXA | UT69151EFBA | 5962-9211803QZA |
| TS68882MF1B/C25 | 5962-8946303YA | UT69R00016GCAH | 5962H9855202QXA | UT69151EFBC | 5962-9211803QZC |
| TS68882MFB/C25 | 5962-8946303YC | UT69R00016GCAH | 5962H9855202VXA | UT69151EGBA | 5962-9211803QXA |
| TS68882MR1B/C25 | 5962-8946303XA | UT69R00016GCC | 5962-9855202QXC | UT69151EGBC | 5962-9211803QXC |
| TS68882MRB/C25 | 5962-8946303XC | UT69R00016GCCH | 5962H9855202QXC | UT69151EQ-DIEF | 5962F9211804Q9B |
| TS68882MF1B/C33 | 5962-8946304YA | UT69R00016GCCH | 5962H9855202VXC | UT69151EQ-DIER | 5962R9211804Q9B |
| TS68882MFB/C33 | 5962-8946304YC | UT69R00016WCC | 5962-9855202QYC | UT69151EV-DIEF | 5962F9211804V9B |
| TS68882MR1B/C33 | 5962-8946304XA | UT69R00016WCCH | 5962H9855202QYC | UT69151EV-DIER | 5962R9211804V9B |
| TS68882MRB/C33 | 5962-8946304XC | UT69R00016WCCH | 5962H9855202VYC | UT69151EWBA | 5962-9211803QYA |
| 68901-4 (GEN) | 5962-8850601XC | 6901-011 | 5962-99A0301QYC | UT69151EWBC | 5962-9211803QYC |
| 68901-4 (GEN) | 5962-8850601YA | 6901-011 (GEN) | 5962-99A0301QXC | UT69151EWCAF | 5962F9211804QYA |
| 68901-5 (GEN) | 5962-8850602XC | UT69RH051PCA | 5962H9563801QQA | UT69151EWCAF | 5962F9211804VYA |
| 68901-5 (GEN) | 5962-8850602YA | UT69RH051PCA | 5962H9563801VQA | UT69151EWCAR | 5962R9211804QYA |
| 68C901-4 (GEN) | 5962-9086401MUA | UT69RH051PCC | 5962H9563801QQC | UT69151EWCAR | 5962R9211804VYA |
| 68C901-4 (GEN) | 5962-9086401MXA | UT69RH051PCC | 5962H9563801VQC | UT69151EWCCF | 5962F9211804QYC |
| 68C901-4 (GEN) | 5962-9086401MYA | UT69RH051-Q DIE | 5962H9563801Q9A | UT69151EWCCF | 5962F9211804VYC |
| 68C901-4 (GEN) | 5962-9086401MZA | UT69RH051-V DIE | 5962H9563801V9A | UT69151EWCCR | 5962R9211804QYC |
| 68C901-5 (GEN) | 5962-9086402MUA | UT69RH051WCA | 5962H9563801QYA | UT69151EWCCR | 5962R9211804VYC |
| 68C901-5 (GEN) | 5962-9086402MXA | UT69RH051WCA | 5962H9563801VYA | UT69151RTEFCC | 5962-9858701QZC |
| 68C901-5 (GEN) | 5962-9086402MYA | UT69RH051WCC | 5962H9563801QYC | UT69151RTEGCA | 5962-9858701QXA |
| 68C901-5 (GEN) | 5962-9086402MZA | UT69RH051WCC | 5962H9563801VYC | UT69151RTEGCC | 5962-9858701QXC |
| 68C901-8 (GEN) | 5962-9086403MUA | MAX691MJE/883B | 5962-9071101MEA | UT69151RTEWCC | 5962-9858701QYC |
| 68C901-8 (GEN) | 5962-9086403MXA | MAX691MLP/883B | 5962-9071101M2C | 69151LX12 (GEN) | 5962-9466303QXA |
| 68C901-8 (GEN) | 5962-9086403MYA | 69151DX (GEN) | 5962-9466302QXA | 69151LX12 (GEN) | 5962-9466303QYA |
| 68C901-8 (GEN) | 5962-9086403MZA | 69151DX (GEN) | 5962-9466302QYA | 69151LX12 (GEN) | 5962-9466306QXA |
| 68902A (GEN) | 5962-9464201QYC | 69151DXE (GEN) | 5962-9466305QXA | 69151LX12 (GEN) | 5962-9466306QYA |
| 68902A (GEN) | 5962-9464201QZA | 69151DXE (GEN) | 5962-9466305QYA | 69151XT12 (GEN) | 5962-9475803QXC |
| 68902A (GEN) | 5962-9464201QZC | 69151DXE (GEN) | 5962H9466305QXA | 69151XT12 (GEN) | 5962-9475803QYC |
| MAX690 (GEN) | 5962-9071201MHA | 69151DXE (GEN) | 5962H9466305QYA | 69151XTE12 (GEN) | 5962-9475806QXC |
| MAX690MFB/883B | 5962-9071201MXC | 69151DXE (GEN) | 5962H9466305VXA | 69151XTE12 (GEN) | 5962-9475806QYC |
| MAX690MJA/883B | 5962-9071201MPA | 69151DXE (GEN) | 5962H9466305VYA | UT69151LXE12/GQA | 5962-9466309QXA |
| MAX690MLP/883B | 5962-9071201M2C | UT69151 (GEN) | 5962-9211801MXA | UT69151LXE12/GQC | 5962-9466309QXC |
| UT69R00012FCA | 5962-9855201QZA | UT69151 (GEN) | 5962-9211801MYA | UT69151LXE12/WQA | 5962-9466309QYA |
| UT69R00012FCAH | 5962H9855201QZA | UT69151DXE/GQA | 5962-9466308QXA | UT69151LXE12/WQC | 5962-9466309QYC |
| UT69R00012FCAH | 5962H9855201VZA | UT69151DXE/GQC | 5962-9466308QXC | UT69151XTE12/GCA | 5962-9475809QXA |
| UT69R00012FCC | 5962-9855201QZC | UT69151DXE/WQA | 5962-9466308QYA | UT69151XTE12/GCC | 5962-9475809QXC |
| UT69R00012FCCH | 5962H9855201QZC | UT69151DXE/WQAF | 5962F9466311QYA | UT69151XTE12/WCA | 5962-9475809QYA |
| UT69R00012FCCH | 5962H9855201VZC | UT69151DXE/WQAR | 5962R9466311QYA | UT69151XTE12/WCC | 5962-9475809QYC |
| UT69R00012GCA | 5962-9855201QXA | UT69151DXE/WQC | 5962-9466308QYC | 69151LX15 (GEN) | 5962-9466301QXA |
| UT69R00012GCAH | 5962H9855201QXA | UT69151DXE/WQCF | 5962F9466311QYC | 69151LX15 (GEN) | 5962-9466301QYA |
| UT69R00012GCAH | 5962H9855201VXA | UT69151DXE/WQCR | 5962R9466311QYC | 69151LXE15 (GEN) | 5962-9466304QXA |
| UT69R00012GCC | 5962-9855201QXC | UT69151DXE/WVAF | 5962F9466311VYA | 69151LXE15 (GEN) | 5962-9466304QYA |
| UT69R00012GCCH | 5962H9855201QXC | UT69151DXE/WVAR | 5962R9466311VYA | 69151LXE15 (GEN) | 5962R9466304QXA |
| UT69R00012GCCH | 5962H9855201VXC | UT69151DXE/WVCF | 5962F9466311VYC | 69151LXE15 (GEN) | 5962R9466304QYA |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

| Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN |
|---|---|---|---|---|---|
| 69151LXE15 (GEN) | 5962R9466304VXA | IDT7006S20FB | 5962-9150811MYA | IDT7025L35FB | 5962-9161708MYA |
| 69151LXE15 (GEN) | 5962R9466304VYA | IDT7006S20GB | 5962-9150811MXA | IDT7025L35GB | 5962-9161708MXA |
| 69151XT15 (GEN) | 5962-9475801QXC | IDT7006L25FB | 5962-9150810MYA | IDT7025S35FB | 5962-9161707MYA |
| 69151XT15 (GEN) | 5962-9475801QYC | IDT7006L25GB | 5962-9150810MXA | IDT7025S35GB | 5962-9161707MXA |
| 69151XTE15 (GEN) | 5962-9475804QXC | IDT7006S25FB | 5962-9150809MYA | IDT7025L45FB | 5962-9161706MYA |
| 69151XTE15 (GEN) | 5962-9475804QYC | IDT7006S25GB | 5962-9150809MXA | IDT7025L45GB | 5962-9161706MXA |
| UT69151LXE15/GQA | 5962-9466307QXA | IDT7006L35FB | 5962-9150808MYA | IDT7025S45FB | 5962-9161705MYA |
| UT69151LXE15/GQC | 5962-9466307QXC | IDT7006L35GB | 5962-9150808MXA | IDT7025S45GB | 5962-9161705MXA |
| UT69151LXE15/WQA | 5962-9466307QYA | IDT7006S35FB | 5962-9150807MYA | MMK2-67025EV-45MQ | 5962-9161706QZC |
| UT69151LXE15/WQAR | 5962R9466310QYA | IDT7006S35GB | 5962-9150807MXA | SMK2-67025EV-45SV | 5962-9161706VZC |
| UT69151LXE15/WQC | 5962-9466307QYC | IDT7006L45FB | 5962-9150806MYA | IDT7025L55FB | 5962-9161704MYA |
| UT69151LXE15/WQCR | 5962R9466310QYC | IDT7006L45GB | 5962-9150806MXA | IDT7025L55GB | 5962-9161704MXA |
| UT69151LXE15/WVAR | 5962R9466310VYA | IDT7006S45FB | 5962-9150805MYA | IDT7025S55FB | 5962-9161703MYA |
| UT69151LXE15/WVCR | 5962R9466310VYC | IDT7006S45GB | 5962-9150805MXA | IDT7025S55GB | 5962-9161703MXA |
| UT69151XTE15/GCA | 5962-9475807QXA | IDT7006L55FB | 5962-9150804MYA | IDT7025L70FB | 5962-9161702MYA |
| UT69151XTE15/GCC | 5962-9475807QXC | IDT7006L55GB | 5962-9150804MXA | IDT7025L70GB | 5962-9161702MXA |
| UT69151XTE15/WCA | 5962-9475807QYA | IDT7006S55FB | 5962-9150803MYA | IDT7025S70FB | 5962-9161701MYA |
| UT69151XTE15/WCC | 5962-9475807QYC | IDT7006S55GB | 5962-9150803MXA | IDT7025S70GB | 5962-9161701MXA |
| 69151XT5 (GEN) | 5962-9475802QXC | IDT7006L70FB | 5962-9150802MYA | DAC703 (GEN) | 5962-88563013A |
| 69151XT5 (GEN) | 5962-9475802QYC | IDT7006L70GB | 5962-9150802MXA | DAC703 (GEN) | 5962-8856301JA |
| 69151XTE5 (GEN) | 5962-9475805QXC | IDT7006S70FB | 5962-9150801MYA | IS0-705RH-Q | 5962R0053801V9A |
| 69151XTE5 (GEN) | 5962-9475805QYC | IDT7006S70GB | 5962-9150801MXA | IS-705RH (GEN) | 5962F0053801QXC |
| UT69151XTE5/GCA | 5962-9475808QXA | IDT7014S20XLB | 5962-9315303MXA | IS-705RH (GEN) | 5962F0053801V9A |
| UT69151XTE5/GCC | 5962-9475808QXC | IDT7014S25XLB | 5962-9315302MXA | IS-705RH (GEN) | 5962F0053801VXC |
| UT69151XTE5/WCA | 5962-9475808QYA | IDT7014S35XLB | 5962-9315301MXA | IS9-705RH-8 | 5962R0053801QXC |
| UT69151XTE5/WCC | 5962-9475808QYC | IDT7024L20FB | 5962-9166212MYA | IS9-705RH-Q | 5962R0053801VXC |
| MAX692 (GEN) | 5962-9071202MHA | IDT7024L20GB | 5962-9166212MXA | IS9-705RH-T | 5962R0053801TXC |
| MAX692MFB/883B | 5962-9071202MXC | IDT7024S20FB | 5962-9166211MYA | MAX705MJA/883B | 5962-9326701MPA |
| MAX692MJA/883B | 5962-9071202MPA | IDT7024S20GB | 5962-9166211MXA | MAX705MLP/883B | 5962-9326701M2C |
| MAX692MLP/883B | 5962-9071202M2C | IDT7024L25FB | 5962-9166210MYA | MAX706MJA/883B | 5962-9326702MPA |
| MAX693MJE/883B | 5962-9071102MEA | IDT7024L25GB | 5962-9166210MXA | MAX706MLP/883B | 5962-9326702M2C |
| MAX693MLP/883B | 5962-9071102M2C | IDT7024S25FB | 5962-9166209MYA | MAX707MJA/883B | 5962-9326703MPA |
| MAX694 (GEN) | 5962-9071203MHA | IDT7024S25GB | 5962-9166209MXA | MAX707MLP/883B | 5962-9326703M2C |
| MAX694MFB/883B | 5962-9071203MXC | IDT7024L35FB | 5962-9166208MYA | MAX708MJA/883B | 5962-9326704MPA |
| MAX694MJA/883B | 5962-9071203MPA | IDT7024L35GB | 5962-9166208MXA | MAX708MLP/883B | 5962-9326704M2C |
| MAX694MLP/883B | 5962-9071203M2C | IDT7024S35FB | 5962-9166207MYA | CY7C1009-100DMB | 5962-8959831MZA |
| MAX695MJE/883B | 5962-9071103MEA | IDT7024S35GB | 5962-9166207MXA | CY7C1009-100LMB | 5962-8959831MMA |
| TSC695FL-15MAMQ | 5962-0324601QXC | IDT7024L45FB | 5962-9166206MYA | CY7C1009L-100DMB | 5962-8959814MZA |
| TSC695FL-15MBMQ | 5962-0324601Q9A | IDT7024L45GB | 5962-9166206MXA | CY7C1009L-100LMB | 5962-8959814MMA |
| TSC695FL-15SASR | 5962R0324601VXC | IDT7024S45FB | 5962-9166205MYA | CY7C1009-120DMB | 5962-8959830MZA |
| TSC695FL-15SASV | 5962-0324601VXC | IDT7024S45GB | 5962-9166205MXA | CY7C1009-120LMB | 5962-8959830MMA |
| TSC695FL-15SBSV | 5962-0324601V9A | IDT7024L55FB | 5962-9166204MYA | CY7C1009L-120DMB | 5962-8959813MZA |
| TSC695F-25MAMQ | 5962-0054001QXC | IDT7024L55GB | 5962-9166204MXA | CY7C1009L-120LMB | 5962-8959813MMA |
| TSC695F-25MBMQ | 5962-0054001Q9A | IDT7024S55FB | 5962-9166203MYA | QP7C1009B-15DMB | 5962-8959841MZA |
| TSC695F-25SASR | 5962R0054001VXC | IDT7024S55GB | 5962-9166203MXA | QP7C1009B-15FMB | 5962-8959841MTA |
| TSC695F-25SASV | 5962-0054001VXC | IDT7024L70FB | 5962-9166202MYA | QP7C1009B-15LMB | 5962-8959841MMA |
| TSC695F-25SBSV | 5962-0054001V9A | IDT7024L70GB | 5962-9166202MXA | QP7C1009B-20DMB | 5962-8959838MZA |
| MAX696MJE/883B | 5962-9312502MEA | IDT7024S70FB | 5962-9166201MYA | QP7C1009B-20FMB | 5962-8959838MTA |
| MAX696MLP/883B | 5962-9312502M2C | IDT7024S70GB | 5962-9166201MXA | QP7C1009B-20LMB | 5962-8959838MMA |
| MAX697MJE/883B | 5962-9312501MEA | MM0-67025EV-30MQ | 5962-9161709Q9A | QP7C1009BL-20DMB | 5962-8959821MZA |
| MAX697MLP/883B | 5962-9312501M2C | MMK2-67025EV-30MQ | 5962-9161709QZC | QP7C1009BL-20FMB | 5962-8959821MTA |
| IDT7006L20FB | 5962-9150812MYA | SM0-67025EV-30SV | 5962-9161709V9A | QP7C1009BL-20LMB | 5962-8959821MMA |
| IDT7006L20GB | 5962-9150812MXA | SMK2-67025EV-30SV | 5962-9161709VZC | QP7C1009B-25DMB | 5962-8959837MZA |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART II, Listed By Generic PIN

| Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN |
|---|---|---|---|---|---|
| QP7C1009B-25FMB | 5962-8959837MTA | L7C108-45 (GEN) | 5962-8959827MNA | 71256L100 (GEN) | 5962-8855201MA |
| QP7C1009B-25LMB | 5962-8959837MMA | L7C108-55 (GEN) | 5962-8959809MNA | IDT71256L100DB | 5962-8855201XA |
| QP7C1009BL-25DMB | 5962-8959820MZA | L7C108-70 (GEN) | 5962-8959804MNA | IDT71256L100L32B | 5962-8855201YA |
| QP7C1009BL-25FMB | 5962-8959820MTA | L7C108-70 (GEN) | 5962-8959804MTA | IDT71256L100TDB | 5962-8855201UA |
| QP7C1009BL-25LMB | 5962-8959820MMA | L7C108-70 (GEN) | 5962-8959804MYA | IDT71256S100DB | 5962-8866201XA |
| QP7C1009B-35DMB | 5962-8959836MZA | L7C108-70 (GEN) | 5962-8959804MZA | IDT71256S100L32B | 5962-8866201YA |
| QP7C1009B-35FMB | 5962-8959836MTA | L7C108-70 (GEN) | 5962-8959808MNA | IDT71256S100TDB | 5962-8866201NA |
| QP7C1009B-35LMB | 5962-8959836MMA | L7C108-85 (GEN) | 5962-8959803MNA | IDT71256S20DB | 5962-8866207XA |
| QP7C1009BL-35DMB | 5962-8959819MZA | L7C108-85 (GEN) | 5962-8959803MTA | IDT71256S20L32B | 5962-8866207YA |
| QP7C1009BL-35FMB | 5962-8959819MTA | L7C108-85 (GEN) | 5962-8959803MYA | IDT71256L25DB | 5962-8855206XA |
| QP7C1009BL-35LMB | 5962-8959819MMA | L7C108-85 (GEN) | 5962-8959803MZA | IDT71256L25L32B | 5962-8855206YA |
| CY7C1009-45LMB | 5962-8959835MMA | L7C108-85 (GEN) | 5962-8959807MNA | IDT71256L25TDB | 5962-8855206UA |
| QP7C1009B-45DMB | 5962-8959835MZA | L7C109-100 (GEN) | 5962-8959814MNA | IDT71256S25DB | 5962-8866206XA |
| QP7C1009B-45FMB | 5962-8959835MTA | L7C109-120 (GEN) | 5962-8959813MNA | IDT71256S25L32B | 5962-8866206YA |
| QP7C1009B-45LMB | 5962-8959835MMA | L7C109-20 (GEN) | 5962-8959821MNA | IDT71256S25TDB | 5962-8866206NA |
| QP7C1009BL-45DMB | 5962-8959818MZA | L7C109-20 (GEN) | 5962-8959838MNA | IDT71256S35DB | 5962-8866205XA |
| QP7C1009BL-45FMB | 5962-8959818MTA | 7C109-25 (GEN) | 5962-8959837MNA | IDT71256S35L32B | 5962-8866205YA |
| QP7C1009BL-45LMB | 5962-8959818MMA | L7C109-25 (GEN) | 5962-8959820MNA | IDT71256S35TDB | 5962-8866205NA |
| CY7C1009-55DMB | 5962-8959834MZA | L7C109-35 (GEN) | 5962-8959819MNA | 71256L45 (GEN) | 5962-8855204MA |
| CY7C1009-55LMB | 5962-8959834MMA | L7C109-35 (GEN) | 5962-8959836MNA | IDT71256L45DB | 5962-8855204XA |
| CY7C1009L-55DMB | 5962-8959817MZA | L7C109-45 (GEN) | 5962-8959818MNA | IDT71256L45L32B | 5962-8855204YA |
| CY7C1009L-55LMB | 5962-8959817MMA | L7C109-45 (GEN) | 5962-8959835MNA | IDT71256L45TDB | 5962-8855204UA |
| QP7C1009B-55DMB | 5962-8959834MZA | L7C109-55 (GEN) | 5962-8959817MNA | IDT71256S45DB | 5962-8866204XA |
| QP7C1009B-55FMB | 5962-8959834MTA | L7C109-70 (GEN) | 5962-8959816MNA | IDT71256S45L32B | 5962-8866204YA |
| QP7C1009B-55LMB | 5962-8959834MMA | L7C109-85 (GEN) | 5962-8959815MNA | IDT71256S45TDB | 5962-8866204NA |
| QP7C1009BL-55DMB | 5962-8959817MZA | HSSR-711E | 5962-9314001EPC | 71256L55 (GEN) | 5962-8855203MA |
| QP7C1009BL-55FMB | 5962-8959817MTA | HSSR-7111 | 5962-9314001HPC | IDT71256L55DB | 5962-8855203XA |
| QP7C1009BL-55LMB | 5962-8959817MMA | HSSR-7111#100 | 5962-9314001HYA | IDT71256L55L32B | 5962-8855203YA |
| CY7C1009-70DMB | 5962-8959833MZA | HSSR-7111#100 | 5962-9314001HYC | IDT71256L55TDB | 5962-8855203UA |
| CY7C1009-70LMB | 5962-8959833MMA | HSSR-7111#200 | 5962-9314001HPA | IDT71256S55DB | 5962-8866203XA |
| CY7C1009L-70DMB | 5962-8959816MZA | HSSR-7111#300 | 5962-9314001HXA | IDT71256S55L32B | 5962-8866203YA |
| CY7C1009L-70LMB | 5962-8959816MMA | HSSR-7111#600 | 5962-9314001HZA | IDT71256S55TDB | 5962-8866203NA |
| CY7C1009-85DMB | 5962-8959832MZA | HSSR-7111#600 | 5962-9314001HZC | 71256L70 (GEN) | 5962-8855202MA |
| CY7C1009-85LMB | 5962-8959832MMA | HSSR-7112-600 | 5962-9314002HZC | IDT71256L70DB | 5962-8855202XA |
| CY7C1009L-85DMB | 5962-8959815MZA | HSSR-7112 | 5962-9314002HPC | IDT71256L70L32B | 5962-8855202YA |
| CY7C1009L-85LMB | 5962-8959815MMA | HSSR-711E-200 | 5962-9314001EPA | IDT71256L70TDB | 5962-8855202UA |
| L7C108-100 (GEN) | 5962-8959802MNA | HSSR-7112-100 | 5962-9314002HYA | IDT71256S70DB | 5962-8866202XA |
| L7C108-100 (GEN) | 5962-8959802MTA | HSSR-7112-100 | 5962-9314002HYC | IDT71256S70L32B | 5962-8866202YA |
| L7C108-100 (GEN) | 5962-8959802MYA | HSSR-7112-200 | 5962-9314002HPA | IDT71256S70TDB | 5962-8866202NA |
| L7C108-100 (GEN) | 5962-8959802MZA | HSSR-7112-300 | 5962-9314002HXA | QP7C128A-20DMB | 5962-8969002LA |
| L7C108-100 (GEN) | 5962-8959806MNA | HSSR-7112-600 | 5962-9314002HZA | QP7C128A-20KMB | 5962-8969002KA |
| L7C108-120 (GEN) | 5962-8959801MNA | 7C123 (GEN) | 5962-9069603MKA | QP7C128A-20LMB | 5962-8969002YA |
| L7C108-120 (GEN) | 5962-8959801MTA | 7C123 (GEN) | 5962-9069603MXA | QP7C128A-25DMB | 5962-8969001LA |
| L7C108-120 (GEN) | 5962-8959801MYA | 7C123-10 (GEN) | 5962-9069603MLA | QP7C128A-25KMB | 5962-8969001KA |
| L7C108-120 (GEN) | 5962-8959801MZA | 7C123 (GEN) | 5962-9069602MKA | QP7C128A-25LMB | 5962-8969001YA |
| L7C108-120 (GEN) | 5962-8959805MNA | 7C123 (GEN) | 5962-9069602MXA | QP7C128A-35DMB | 8403614LA |
| L7C108-20 (GEN) | 5962-8959839MNA | 7C123-12 (GEN) | 5962-9069602MLA | QP7C128A-35KMB | 8403614KA |
| L7C108-20 (GEN) | 5962-8959840MNA | 7C123 (GEN) | 5962-9069601MKA | QP7C128A-35LMB | 8403614YA |
| L7C108-25 (GEN) | 5962-8959812MNA | 7C123 (GEN) | 5962-9069601MXA | QP7C128A-45DMB | 8403609LA |
| L7C108-25 (GEN) | 5962-8959829MNA | 7C123-15 (GEN) | 5962-9069601MLA | QP7C128A-45KMB | 8403609KA |
| L7C108-35 (GEN) | 5962-8959811MNA | ISL7124SRHQF | 5962F0254201QXC | QP7C128A-45LMB | 8403609YA |
| L7C108-35 (GEN) | 5962-8959828MNA | ISL7124SRHVF | 5962F0254201VXC | QP7C128A-55DMB | 8403611LA |
| L7C108-45 (GEN) | 5962-8959810MNA | ISL7124SRHVX | 5962F0254201V9A | QP7C128A-55KMB | 8403611KA |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART II, Listed By Generic PIN

| Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN |
|---|---|---|---|---|---|
| QP7C128A-55LMB | 8403611YA | IDT7130LA90L48B | 5962-8687505YA | IDT7132LA-70CB | 5962-8700207ZA |
| AD713SQ/883B | 5962-9063301MCA | IDT7130SA90CB | 5962-8687501XA | IDT7132LA70FB | 5962-8700207TA |
| AD713T (GEN) | 5962-9063302MCA | IDT7130SA90FB | 5962-8687501UA | IDT7132LA-70L48B | 5962-8700207UA |
| MN7130H/B | 5962-9057101HXA | IDT7130SA90L48B | 5962-8687501YA | IDT7132SA-70CB | 5962-8700203ZA |
| MN7130H/B | 5962-9057101HXC | 7131-35 (GEN) | 5962-8687517ZA | IDT7132SA70FB | 5962-8700203TA |
| 7130-35 (GEN) | 5962-8687517UA | CY7C131-35LMB | 5962-8687519ZA | IDT7132SA-70L48B | 5962-8700203UA |
| 7130-35 (GEN) | 5962-8687517XA | CY7C131-45LMB | 5962-8687504ZA | 7132LA-90 (GEN) | 5962-8700206XA |
| 7130-35 (GEN) | 5962-8687517YA | CY7C131-55LMB | 5962-8687503ZA | 7132LA-90 (GEN) | 5962-8700206YA |
| 7130-35 (GEN) | 5962-8687521ZA | 7132L25 (GEN) | 5962-8700220ZA | 7132SA-90 (GEN) | 5962-8700202XA |
| CY7C130-35DMB | 5962-8687519XA | 7132S25 (GEN) | 5962-8700219ZA | 7132SA-90 (GEN) | 5962-8700202YA |
| CY7C130-35FMB | 5962-8687519UA | IDT7132LA25FB | 5962-8700220TA | IDT7132LA-90CB | 5962-8700206ZA |
| CY7C130-35LMB | 5962-8687519YA | IDT7132SA25FB | 5962-8700219TA | IDT7132LA90FB | 5962-8700206TA |
| IDT7130LA35CB | 5962-8687521XA | IDT7132LA25L48B | 5962-8700220UA | IDT7132LA-90L48B | 5962-8700206UA |
| IDT7130LA35FB | 5962-8687521UA | IDT7132SA25L48B | 5962-8700219UA | IDT7132SA-90CB | 5962-8700202ZA |
| IDT7130LA35L48B | 5962-8687521YA | CY7C132-35DMB | 5962-9062003MYA | IDT7132SA90FB | 5962-8700202TA |
| 7130-45 (GEN) | 5962-8687508ZA | CY7C132-35FMB | 5962-9062003MUA | IDT7132SA-90L48B | 5962-8700202UA |
| CY7C130-45DMB | 5962-8687504XA | CY7C132-35LMB | 5962-9062003MZA | IDT7133LA35FB | 5962-8866515UA |
| CY7C130-45FMB | 5962-8687504UA | IDT7132LA35CB | 5962-8700218ZA | IDT7133LA35GB | 5962-8866515ZA |
| CY7C130-45LMB | 5962-8687504YA | IDT7132LA35FB | 5962-8700218TA | IDT7133LA45FB | 5962-8866513UA |
| IDT7130LA45CB | 5962-8687508XA | IDT7132SA35CB | 5962-8700217ZA | IDT7133LA45GB | 5962-8866513ZA |
| IDT7130LA45FB | 5962-8687508UA | IDT7132SA35FB | 5962-8700217TA | IDT7133LA55FB | 5962-8866511UA |
| IDT7130LA45L48B | 5962-8687508YA | IDT7132LA35L48B | 5962-8700218UA | IDT7133LA55GB | 5962-8866511ZA |
| IDT7130SA45CB | 5962-8687504XA | IDT7132SA35L48B | 5962-8700217UA | IDT7133SA55FB | 5962-8861011UA |
| IDT7130SA45FB | 5962-8687504UA | 7132LA-45 (GEN) | 5962-8700205XA | IDT7133SA55GB | 5962-8861011ZA |
| IDT7130SA45L48B | 5962-8687504YA | 7132LA-45 (GEN) | 5962-8700205YA | IDT7133LA70FB | 5962-8866509UA |
| 7130-55 (GEN) | 5962-8687507ZA | 7132SA-45 (GEN) | 5962-8700201XA | IDT7133LA70GB | 5962-8866509ZA |
| CY7C130-55DMB | 5962-8687503XA | 7132SA-45 (GEN) | 5962-8700201YA | IDT7133SA70FB | 5962-8861009UA |
| CY7C130-55FMB | 5962-8687503UA | CY7C132-45DMB | 5962-9062002MYA | IDT7133SA70GB | 5962-8861009ZA |
| CY7C130-55LMB | 5962-8687503YA | CY7C132-45FMB | 5962-9062002MUA | IDT7133LA90FB | 5962-8866507UA |
| IDT7130LA55CB | 5962-8687507XA | CY7C132-45LMB | 5962-9062002MZA | IDT7133LA90GB | 5962-8866507ZA |
| IDT7130LA55FB | 5962-8687507UA | IDT7132LA-45CB | 5962-8700205ZA | IDT7133SA90FB | 5962-8861007UA |
| IDT7130LA55L48B | 5962-8687507YA | IDT7132LA45FB | 5962-8700205TA | IDT7133SA90GB | 5962-8861007ZA |
| IDT7130SA55CB | 5962-8687503XA | IDT7132LA-45L48B | 5962-8700205UA | IDT7134LA35CB | 5962-8976408MXA |
| IDT7130SA55FB | 5962-8687503UA | IDT7132SA-45CB | 5962-8700201ZA | IDT7134LA35L48B | 5962-8976408MYA |
| IDT7130SA55L48B | 5962-8687503YA | IDT7132SA45FB | 5962-8700201TA | IDT7134SA35CB | 5962-8976407MXA |
| 7130-70 (GEN) | 5962-8687506ZA | IDT7132SA-45L48B | 5962-8700201UA | IDT7134SA35L48B | 5962-8976407MYA |
| CY7C130-70DMB | 5962-8687502XA | 7132LA-55 (GEN) | 5962-8700208XA | IDT7134LA45CB | 5962-8976406MXA |
| CY7C130-70FMB | 5962-8687502UA | 7132LA-55 (GEN) | 5962-8700208YA | IDT7134LA45L48B | 5962-8976406MYA |
| CY7C130-70LMB | 5962-8687502YA | 7132SA-55 (GEN) | 5962-8700204XA | IDT7134SA45CB | 5962-8976405MXA |
| CY7C131-70LMB | 5962-8687502ZA | 7132SA-55 (GEN) | 5962-8700204YA | IDT7134SA45L48B | 5962-8976405MYA |
| IDT7130LA70CB | 5962-8687506XA | CY7C132-55DMB | 5962-9062001MYA | IDT7134LA55CB | 5962-8976404MXA |
| IDT7130LA70FB | 5962-8687506UA | CY7C132-55FMB | 5962-9062001MUA | IDT7134LA55L48B | 5962-8976404MYA |
| IDT7130LA70L48B | 5962-8687506YA | CY7C132-55LMB | 5962-9062001MZA | IDT7134SA55CB | 5962-8976403MXA |
| IDT7130SA70CB | 5962-8687502XA | IDT7132LA-55CB | 5962-8700208ZA | IDT7134SA55L48B | 5962-8976403MYA |
| IDT7130SA70FB | 5962-8687502UA | IDT7132LA55FB | 5962-8700208TA | IDT7134LA35FB | 5962-8976408MZA |
| IDT7130SA70L48B | 5962-8687502YA | IDT7132LA-55L48B | 5962-8700208UA | IDT7134LA45FB | 5962-8976406MZA |
| 7130-90 (GEN) | 5962-8687505ZA | IDT7132SA-55CB | 5962-8700204ZA | IDT7134LA55FB | 5962-8976404MZA |
| CY7C130-90DMB | 5962-8687501XA | IDT7132SA55FB | 5962-8700204TA | IDT7134LA70CB | 5962-8976402MXA |
| CY7C130-90FMB | 5962-8687501UA | IDT7132SA-55L48B | 5962-8700204UA | IDT7134LA70FB | 5962-8976402MZA |
| CY7C130-90LMB | 5962-8687501YA | 7132LA-70 (GEN) | 5962-8700207XA | IDT7134LA70L48B | 5962-8976402MYA |
| CY7C131-90LMB | 5962-8687501ZA | 7132LA-70 (GEN) | 5962-8700207YA | IDT7134SA35FB | 5962-8976407MZA |
| IDT7130LA90CB | 5962-8687505XA | 7132SA-70 (GEN) | 5962-8700203XA | IDT7134SA45FB | 5962-8976405MZA |
| IDT7130LA90FB | 5962-8687505UA | 7132SA-70 (GEN) | 5962-8700203YA | IDT7134SA55FB | 5962-8976403MZA |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART II, Listed By Generic PIN

| Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN |
|---|---|---|---|---|---|
| IDT7134SA70CB | 5962-8976401MXA | IDT7140LA35L48B | 5962-8687522YA | 7142SA-45 (GEN) | 5962-8700209YA |
| IDT7134SA70FB | 5962-8976401MZA | 7140-45 (GEN) | 5962-8687516ZA | 7C142 (GEN) | 5962-9062005MUA |
| IDT7134SA70L48B | 5962-8976401MYA | IDT7140LA45CB | 5962-8687516XA | 7C142 (GEN) | 5962-9062005MZA |
| CY7C136-35LMB | 5962-9062009MXA | IDT7140LA45FB | 5962-8687516UA | 7C142-45 (GEN) | 5962-9062005MYA |
| CY7C136-45LMB | 5962-9062008MXA | IDT7140LA45L48B | 5962-8687516YA | IDT7142LA-45CB | 5962-8700213ZA |
| CY7C136-55LMB | 5962-9062007MXA | IDT7140SA45CB | 5962-8687512XA | IDT7142LA45FB | 5962-8700213TA |
| UT7C138C45_QDIE | 5962H9684501Q9A | IDT7140SA45FB | 5962-8687512UA | IDT7142LA-45L48B | 5962-8700213UA |
| UT7C138C45_VDIE | 5962H9684501V9A | IDT7140SA45L48B | 5962-8687512YA | IDT7142SA-45CB | 5962-8700209ZA |
| UT7C138C45GCAH | 5962H9684501QXA | 7140-55 (GEN) | 5962-8687515ZA | IDT7142SA45FB | 5962-8700209TA |
| UT7C138C45GCAH | 5962H9684501VXA | IDT7140LA55CB | 5962-8687515XA | IDT7142SA-45L48B | 5962-8700209UA |
| UT7C138C45GCCH | 5962H9684501QXC | IDT7140LA55FB | 5962-8687515UA | 7142LA-55 (GEN) | 5962-8700216XA |
| UT7C138C45GCCH | 5962H9684501VXC | IDT7140LA55L48B | 5962-8687515YA | 7142LA-55 (GEN) | 5962-8700216YA |
| UT7C138C45WCAH | 5962H9684501QYA | IDT7140SA55CB | 5962-8687511XA | 7142SA-55 (GEN) | 5962-8700212XA |
| UT7C138C45WCAH | 5962H9684501VYA | IDT7140SA55FB | 5962-8687511UA | 7142SA-55 (GEN) | 5962-8700212YA |
| UT7C138C45WCCH | 5962H9684501QYC | IDT7140SA55L48B | 5962-8687511YA | 7C142 (GEN) | 5962-9062004MUA |
| UT7C138C45WCCH | 5962H9684501VYC | 7140-70 (GEN) | 5962-8687510ZA | 7C142 (GEN) | 5962-9062004MZA |
| UT7C138C55GCAH | 5962H9684503QXA | 7140-70 (GEN) | 5962-8687514ZA | 7C142-55 (GEN) | 5962-9062004MYA |
| UT7C138C55GCAH | 5962H9684503VXA | IDT7140LA70CB | 5962-8687514XA | IDT7142LA-55CB | 5962-8700216ZA |
| UT7C138C55GCCH | 5962H9684503QXC | IDT7140LA70FB | 5962-8687514UA | IDT7142LA55FB | 5962-8700216TA |
| UT7C138C55GCCH | 5962H9684503VXC | IDT7140LA70L48B | 5962-8687514YA | IDT7142LA-55L48B | 5962-8700216UA |
| UT7C138C55WCAH | 5962H9684503QYA | IDT7140SA70CB | 5962-8687510XA | IDT7142SA-55CB | 5962-8700212ZA |
| UT7C138C55WCAH | 5962H9684503VYA | IDT7140SA70FB | 5962-8687510UA | IDT7142SA55FB | 5962-8700212TA |
| UT7C138C55WCCH | 5962H9684503QYC | IDT7140SA70L48B | 5962-8687510YA | IDT7142SA-55L48B | 5962-8700212UA |
| UT7C138C55WCCH | 5962H9684503VYC | 7140-90 (GEN) | 5962-8687509ZA | 7142LA-70 (GEN) | 5962-8700215XA |
| UT7C139C45_QDIE | 5962H9684502Q9A | 7140-90 (GEN) | 5962-8687513ZA | 7142LA-70 (GEN) | 5962-8700215YA |
| UT7C139C45_VDIE | 5962H9684502V9A | IDT7140LA90CB | 5962-8687513XA | 7142SA-70 (GEN) | 5962-8700211XA |
| UT7C139C45GCAH | 5962H9684502QXA | IDT7140LA90FB | 5962-8687513UA | 7142SA-70 (GEN) | 5962-8700211YA |
| UT7C139C45GCAH | 5962H9684502VXA | IDT7140LA90L48B | 5962-8687513YA | IDT7142LA-70CB | 5962-8700215ZA |
| UT7C139C45GCCH | 5962H9684502QXC | IDT7140SA90CB | 5962-8687509XA | IDT7142LA70FB | 5962-8700215TA |
| UT7C139C45GCCH | 5962H9684502VXC | IDT7140SA90FB | 5962-8687509UA | IDT7142LA-70L48B | 5962-8700215UA |
| UT7C139C45WCAH | 5962H9684502QYA | IDT7140SA90L48B | 5962-8687509YA | IDT7142SA-70CB | 5962-8700211ZA |
| UT7C139C45WCAH | 5962H9684502VYA | 7141-35 (GEN) | 5962-8687518ZA | IDT7142SA70FB | 5962-8700211TA |
| UT7C139C45WCCH | 5962H9684502QYC | 7141-35 (GEN) | 5962-8687520ZA | IDT7142SA-70L48B | 5962-8700211UA |
| UT7C139C45WCCH | 5962H9684502VYC | 7C141-45 (GEN) | 5962-8687512ZA | 7142LA-90 (GEN) | 5962-8700214XA |
| UT7C139C55GCAH | 5962H9684504QXA | 7C141-55 (GEN) | 5962-8687511ZA | 7142LA-90 (GEN) | 5962-8700214YA |
| UT7C139C55GCAH | 5962H9684504VXA | 7142L25 (GEN) | 5962-8700224ZA | 7142SA-90 (GEN) | 5962-8700210XA |
| UT7C139C55GCCH | 5962H9684504QXC | 7142S25 (GEN) | 5962-8700223ZA | 7142SA-90 (GEN) | 5962-8700210YA |
| UT7C139C55GCCH | 5962H9684504VXC | IDT7142LA25FB | 5962-8700224TA | IDT7142LA-90CB | 5962-8700214ZA |
| UT7C139C55WCAH | 5962H9684504QYA | IDT7142SA25FB | 5962-8700223TA | IDT7142LA90FB | 5962-8700214TA |
| UT7C139C55WCAH | 5962H9684504VYA | IDT7142LA25L48B | 5962-8700224UA | IDT7142LA-90L48B | 5962-8700214UA |
| UT7C139C55WCCH | 5962H9684504QYC | IDT7142SA25L48B | 5962-8700223UA | IDT7142SA-90CB | 5962-8700210ZA |
| UT7C139C55WCCH | 5962H9684504VYC | 7C142 (GEN) | 5962-9062006MUA | IDT7142SA90FB | 5962-8700210TA |
| MN7140H/B | 5962-9079701HXA | 7C142 (GEN) | 5962-9062006MZA | IDT7142SA-90L48B | 5962-8700210UA |
| MN7140H/B | 5962-9079701HXC | 7C142-35 (GEN) | 5962-9062006MYA | IDT7143LA35FB | 5962-8866516UA |
| 7140-35 (GEN) | 5962-8687518UA | IDT7142LA35CB | 5962-8700222ZA | IDT7143LA35GB | 5962-8866516ZA |
| 7140-35 (GEN) | 5962-8687518XA | IDT7142LA35FB | 5962-8700222TA | IDT7143LA45FB | 5962-8866514UA |
| 7140-35 (GEN) | 5962-8687518YA | IDT7142SA35CB | 5962-8700221ZA | IDT7143LA45GB | 5962-8866514ZA |
| 7140-35 (GEN) | 5962-8687520UA | IDT7142SA35FB | 5962-8700221TA | IDT7143LA55FB | 5962-8866512UA |
| 7140-35 (GEN) | 5962-8687520YA | IDT7142LA35L48B | 5962-8700222UA | IDT7143LA55GB | 5962-8866512ZA |
| 7140-35 (GEN) | 5962-8687522ZA | IDT7142SA35L48B | 5962-8700221UA | IDT7143SA55FB | 5962-8861012UA |
| 7C140-35 (GEN) | 5962-8687520XA | 7142LA-45 (GEN) | 5962-8700213XA | IDT7143SA55GB | 5962-8861012ZA |
| IDT7140LA35CB | 5962-8687522XA | 7142LA-45 (GEN) | 5962-8700213YA | IDT7143LA70FB | 5962-8866510UA |
| IDT7140LA35FB | 5962-8687522UA | 7142SA-45 (GEN) | 5962-8700209XA | IDT7143LA70GB | 5962-8866510ZA |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

| Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN |
|---|---|---|---|---|---|
| IDT7143SA70FB | 5962-8861010UA | 7B162-12 (GEN) | 5962-9217202MYA | IDT7164L35DB | 5962-3829412MXA |
| IDT7143SA70GB | 5962-8861010ZA | 7B162-15 (GEN) | 5962-9217201MXA | IDT7164L35L32B | 5962-3829412MYA |
| IDT7143LA90FB | 5962-8866508UA | 7B162-15 (GEN) | 5962-9217201MYA | IDT7164L35TDB | 5962-3829412MZA |
| IDT7143LA90GB | 5962-8866508ZA | 7B164 (GEN) | 5962-9159303MKA | IDT7164S35DB | 5962-3829413MXA |
| IDT7143SA90FB | 5962-8861008UA | 7B164 (GEN) | 5962-9159303MYA | IDT7164S35L32B | 5962-3829413MYA |
| IDT7143SA90GB | 5962-8861008ZA | 7B164 (GEN) | 5962-9159303MZA | IDT7164S35TDB | 5962-3829413MZA |
| 7C146-35 (GEN) | 5962-9062012MXA | 7164100 (GEN) | 5962-3829404MTA | 7164L45 (GEN) | 5962-3829410MTA |
| 7C146-45 (GEN) | 5962-9062011MXA | 7164100 (GEN) | 5962-3829404MXA | 7164L45 (GEN) | 5962-8552509YA |
| 7C146-55 (GEN) | 5962-9062010MXA | 7164100 (GEN) | 5962-3829404MYA | 7164L45 (GEN) | 5962-8552509ZA |
| CY7C148-25DMB | 5962-8751307VA | 7164100 (GEN) | 5962-3829404MZA | 7164S45 (GEN) | 5962-3829411MTA |
| CY7C148-35DMB | 5962-8751308VA | 7164100 (GEN) | 5962-3829405MTA | 7C164-45 (GEN) | 5962-8685922KA |
| CY7C148-45DMB | 5962-8751309VA | 7164100 (GEN) | 5962-3829405MXA | 7C164L-45 (GEN) | 5962-8685921KA |
| 7150-15 (GEN) | 5962-8858803LA | 7164100 (GEN) | 5962-3829405MYA | IDT7164L45DB | 5962-3829410MXA |
| 7C150-25 (GEN) | 5962-8858802LA | 7164100 (GEN) | 5962-3829405MZA | IDT7164L45L32B | 5962-3829410MYA |
| 7C150-35 (GEN) | 5962-8858801LA | 7B164 (GEN) | 5962-9159302MKA | IDT7164L45TDB | 5962-3829410MZA |
| UT7156C40PCAH | 5962H9215303QMA | 7B164 (GEN) | 5962-9159302MYA | IDT7164S45DB | 5962-3829411MXA |
| UT7156C40PCAH | 5962H9215303VMA | 7B164 (GEN) | 5962-9159302MZA | IDT7164S45L32B | 5962-3829411MYA |
| UT7156C40PCCH | 5962H9215303QMC | 7164120 (GEN) | 5962-3829402MTA | IDT7164S45TDB | 5962-3829411MZA |
| UT7156C40PCCH | 5962H9215303VMC | 7164120 (GEN) | 5962-3829402MXA | 7164L55 (GEN) | 5962-3829408MTA |
| UT7156C40WCAH | 5962H9215303QTA | 7164120 (GEN) | 5962-3829402MYA | 7164L55 (GEN) | 5962-8552510YA |
| UT7156C40WCAH | 5962H9215303VTA | 7164120 (GEN) | 5962-3829402MZA | 7164L55 (GEN) | 5962-8552510ZA |
| UT7156C40WCCH | 5962H9215303QTC | 7164120 (GEN) | 5962-3829403MTA | 7164S55 (GEN) | 5962-3829409MTA |
| UT7156C40WCCH | 5962H9215303VTC | 7164120 (GEN) | 5962-3829403MXA | IDT7164L55DB | 5962-3829408MXA |
| UT7156C55PBAH | 5962H9215309QMA | 7164120 (GEN) | 5962-3829403MYA | IDT7164L55L32B | 5962-3829408MYA |
| UT7156C55PBAR | 5962R9215309QMA | 7164120 (GEN) | 5962-3829403MZA | IDT7164L55TDB | 5962-3829408MZA |
| UT7156C55PBCH | 5962H9215309QMC | 7B164 (GEN) | 5962-9159301MKA | IDT7164S55DB | 5962-3829409MXA |
| UT7156C55PBCR | 5962R9215309QMC | 7B164 (GEN) | 5962-9159301MYA | IDT7164S55L32B | 5962-3829409MYA |
| UT7156C55WBAH | 5962H9215311QTA | 7B164 (GEN) | 5962-9159301MZA | IDT7164S55TDB | 5962-3829409MZA |
| UT7156C55WBAR | 5962R9215311QTA | 7164150 (GEN) | 5962-3829401MTA | 7164L70 (GEN) | 5962-3829406MTA |
| UT7156C55WBCH | 5962H9215311QTC | 7164150 (GEN) | 5962-3829401MXA | 7164L70 (GEN) | 5962-8552511YA |
| UT7156C55WBCR | 5962R9215311QTC | 7164150 (GEN) | 5962-3829401MYA | 7164S70 (GEN) | 5962-3829407MTA |
| UT7156T55PBAH | 5962H9215310QMA | 7164150 (GEN) | 5962-3829401MZA | IDT7164L70DB | 5962-3829406MXA |
| UT7156T55PBAR | 5962R9215310QMA | 7164L20 (GEN) | 5962-3829416MTA | IDT7164L70L32B | 5962-3829406MYA |
| UT7156T55PBCH | 5962H9215310QMC | 7164S20 (GEN) | 5962-3829417MTA | IDT7164L70TDB | 5962-3829406MZA |
| UT7156T55PBCR | 5962R9215310QMC | IDT7164L20DB | 5962-3829416MXA | IDT7164S70DB | 5962-3829407MXA |
| UT7156T55WBAH | 5962H9215312QTA | IDT7164L20L32B | 5962-3829416MYA | IDT7164S70L32B | 5962-3829407MYA |
| UT7156T55WBAR | 5962R9215312QTA | IDT7164L20TDB | 5962-3829416MZA | IDT7164S70TDB | 5962-3829407MZA |
| UT7156T55WBCH | 5962H9215312QTC | IDT7164S20DB | 5962-3829417MXA | IDT7164L85DB | 5962-8552512XA |
| UT7156T55WBCR | 5962R9215312QTC | IDT7164S20L32B | 5962-3829417MYA | IDT7164L85LB | 5962-8552512YA |
| UT7156C70PBAR | 5962R9215315QMA | IDT7164S20TDB | 5962-3829417MZA | 7B166 (GEN) | 5962-9159306MKA |
| UT7156C70PBCR | 5962R9215315QMC | IDT7164L25DB | 5962-3829414MXA | 7B166 (GEN) | 5962-9159306MLA |
| UT7156C70WBAR | 5962R9215317QTA | IDT7164L25L32B | 5962-3829414MYA | 7B166 (GEN) | 5962-9159306MXA |
| UT7156C70WBCR | 5962R9215317QTC | IDT7164L25TDB | 5962-3829414MZA | 7B166 (GEN) | 5962-9159305MKA |
| UT7156T70PBAR | 5962R9215316QMA | IDT7164S25DB | 5962-3829415MXA | 7B166 (GEN) | 5962-9159305MLA |
| UT7156T70PBCR | 5962R9215316QMC | IDT7164S25L32B | 5962-3829415MYA | 7B166 (GEN) | 5962-9159305MXA |
| UT7156T70WBAR | 5962R9215318QTA | IDT7164S25TDB | 5962-3829415MZA | 7B166 (GEN) | 5962-9159304MKA |
| UT7156T70WBCR | 5962R9215318QTC | 7164L35 (GEN) | 5962-3829412MTA | 7B166 (GEN) | 5962-9159304MLA |
| 7C161A-20 (GEN) | 5962-9059404XA | 7164L35 (GEN) | 5962-8552508YA | 7B166 (GEN) | 5962-9159304MXA |
| 7C161A-25 (GEN) | 5962-9059403XA | 7164L35 (GEN) | 5962-8552508ZA | CY7C167A-35DMB | 8413205RA |
| 7C161A-35 (GEN) | 5962-9059402XA | 7164S35 (GEN) | 5962-3829413MTA | CY7C167A-35KMB | 8413205SA |
| 7B162-10 (GEN) | 5962-9217203MXA | 7164S35 (GEN) | 5962-8552507YA | CY7C167A-35LMB | 8413205YA |
| 7B162-10 (GEN) | 5962-9217203MYA | 7C164-35 (GEN) | 5962-8685924KA | CY7C167A-45DMB | 8413202RA |
| 7B162-12 (GEN) | 5962-9217202MXA | 7C164L-35 (GEN) | 5962-8685923KA | CY7C167A-45KMB | 8413202SA |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

| Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN |
|---|---|---|---|---|---|
| CY7C167A-45LMB | 8413202YA | QP7C185A-20DMB | 5962-8969104ZA | IDT7187L45DB | 5962-8601504YA |
| 71682LA15 (GEN) | 5962-89790033A | QP7C185A-20LMB | 5962-3829430MUA | IDT7187S45DB | 5962-8601503YA |
| 71682LA15 (GEN) | 5962-8979003KA | QP7C185A-25DMB | 5962-3829415MZA | IDT7187L55DB | 5962-8601506YA |
| 71682LA15 (GEN) | 5962-8979003LA | QP7C185A-25DMB | 5962-8969102ZA | IDT7187S55DB | 5962-8601505YA |
| 71682SA15 (GEN) | 5962-89790043A | QP7C185A-25LMB | 5962-3829429MUA | 7187L70 (GEN) | 5962-8601508ZA |
| 71682SA15 (GEN) | 5962-8979004KA | 7C185-35 (GEN) | 5962-8552507TA | 7187S70 (GEN) | 5962-8601507ZA |
| 71682SA15 (GEN) | 5962-8979004LA | 7C185-35 (GEN) | 5962-8552507UA | IDT7187L70DB | 5962-8601508YA |
| 71682LA20 (GEN) | 5962-89790013A | 7C185-35 (GEN) | 5962-8552507ZA | IDT7187S70DB | 5962-8601507YA |
| 71682LA20 (GEN) | 5962-8979001KA | 7C185L-35 (GEN) | 5962-8552508TA | IDT7188L-25DB | 5962-8969201YA |
| 71682LA20 (GEN) | 5962-8979001LA | 7C185L-35 (GEN) | 5962-8552508UA | IDT7188S25DB | 5962-8969202YA |
| 71682LA25 (GEN) | 5962-88611053A | QP7C185A-35DMB | 5962-3829413MZA | IDT7188L35DB | 5962-8685923YA |
| 71682LA25 (GEN) | 5962-8861105KA | QP7C185A-35LMB | 5962-3829427MUA | IDT7188S35DB | 5962-8685924YA |
| 71682LA25 (GEN) | 5962-8861105LA | 7C185-45 (GEN) | 5962-3829434MMA | IDT7188L45DB | 5962-8685921YA |
| 71682LA35 (GEN) | 5962-88611043A | 7C185-45 (GEN) | 5962-3829434MTA | IDT7188S45DB | 5962-8685922YA |
| 71682LA35 (GEN) | 5962-8861104KA | 7C185-45 (GEN) | 5962-3829434MUA | 7188L55 (GEN) | 5962-8685919KA |
| 71682LA35 (GEN) | 5962-8861104LA | 7C185-45 (GEN) | 5962-3829434MYC | 7188S55 (GEN) | 5962-8685920KA |
| 71682LA45 (GEN) | 5962-88611033A | 7C185-45 (GEN) | 5962-3829434MZA | IDT7188L55DB | 5962-8685919YA |
| 71682LA45 (GEN) | 5962-8861103KA | 7C185-45 (GEN) | 5962-8552506UA | IDT7188S55DB | 5962-8685920YA |
| 71682LA45 (GEN) | 5962-8861103LA | 7C185-45 (GEN) | 5962-8552506ZA | 7C190-25 (GEN) | 5962-8969401EA |
| 71682LA55 (GEN) | 5962-88611023A | 7C185L-45 (GEN) | 5962-8552509TA | 7C190-25 (GEN) | 5962-8969401FA |
| 71682LA55 (GEN) | 5962-8861102KA | 7C185L-45 (GEN) | 5962-8552509UA | 7C190-25 (GEN) | 5962-8969401XA |
| 71682LA55 (GEN) | 5962-8861102LA | QP7C185A-45DMB | 5962-3829411MZA | 7C191-25 (GEN) | 5962-9066403MXA |
| 71682LA70 (GEN) | 5962-88611013A | QP7C185A-45LMB | 5962-3829425MUA | 7C191-25 (GEN) | 5962-9066403MYA |
| 71682LA70 (GEN) | 5962-8861101KA | 7C185-55 (GEN) | 5962-3829433MMA | 7C191-25 (GEN) | 5962-9066403MZA |
| 71682LA70 (GEN) | 5962-8861101LA | 7C185-55 (GEN) | 5962-3829433MTA | 7C191-35 (GEN) | 5962-9066402MXA |
| ICM7170 (GEN) | 5962-8765301JA | 7C185-55 (GEN) | 5962-3829433MUA | 7C191-35 (GEN) | 5962-9066402MYA |
| LM7171AMJFQML | 5962F9553601QPA | 7C185-55 (GEN) | 5962-3829433MYA | 7C191-35 (GEN) | 5962-9066402MZA |
| LM7171AMJFQMLV | 5962F9553601VPA | 7C185-55 (GEN) | 5962-3829433MZA | 7C191-45 (GEN) | 5962-9066401MXA |
| LM7171AMJ-QML | 5962-9553601QPA | 7C185-55 (GEN) | 5962-8552505TA | 7C191-45 (GEN) | 5962-9066401MYA |
| LM7171AMJ-QMLV | 5962-9553601VPA | 7C185-55 (GEN) | 5962-8552505UA | 7C191-45 (GEN) | 5962-9066401MZA |
| LM7171AMWFQMLV | 5962F9553601VHA | 7C185-55 (GEN) | 5962-8552505ZA | 7192 (GEN) | 5962-9316801MXC |
| LM7171AMWGFQML | 5962F9553601QXA | 7C185L-55 (GEN) | 5962-8552510TA | 7192 (GEN) | 5962-9316802MXC |
| LM7171AMWGFQMLV | 5962F9553601VXA | 7C185L-55 (GEN) | 5962-8552510UA | 7C192-25 (GEN) | 5962-8993503YA |
| LM7171AMWG-QML | 5962-9553601QXA | QP7C185A-55DMB | 5962-3829409MZA | 7C192-25 (GEN) | 5962-8993503ZA |
| LM7171AMWG-QMLV | 5962-9553601VXA | QP7C185A-55LMB | 5962-3829423MUA | 7C192-35 (GEN) | 5962-8993502YA |
| LM7171AMW-QML | 5962-9553601QHA | 7C185-70 (GEN) | 5962-3829406MUA | 7C192-35 (GEN) | 5962-8993502ZA |
| LM7171AMW-QMLV | 5962-9553601VHA | 7C185-70 (GEN) | 5962-3829420MUA | 7C192-45 (GEN) | 5962-8993501YA |
| 7C172A-20 (GEN) | 5962-89790023A | QP7C185A-70DMB | 5962-3829407MZA | 7C192-45 (GEN) | 5962-8993501ZA |
| 7C172A-20 (GEN) | 5962-8979002KA | QP7C185A-70LMB | 5962-3829421MUA | 7C196-20 (GEN) | 5962-9322504MXA |
| 7C172A-20 (GEN) | 5962-8979002LA | QP7C186A-20DMB | 5962-3829417MXA | 7C196-20 (GEN) | 5962-9322504MYA |
| 71B74S20 (GEN) | 5962-9234401MXA | QP7C186A-20LMB | 5962-3829417MYA | 7C196-20 (GEN) | 5962-9322504MZA |
| 7B185-10 (GEN) | 5962-9159403MTA | QP7C186A-25DMB | 5962-3829415MXA | 7C196-25 (GEN) | 5962-9322503MXA |
| 7B185-10 (GEN) | 5962-9159403MYA | QP7C186A-25LMB | 5962-3829415MYA | 7C196-25 (GEN) | 5962-9322503MYA |
| 7B185-10 (GEN) | 5962-9159403MZA | QP7C186A-35DMB | 5962-3829413MXA | 7C196-25 (GEN) | 5962-9322503MZA |
| 7B185-12 (GEN) | 5962-9159402MTA | QP7C186A-35LMB | 5962-3829413MYA | 7C196-35 (GEN) | 5962-9322502MXA |
| 7B185-12 (GEN) | 5962-9159402MYA | QP7C186A-45DMB | 5962-3829411MXA | 7C196-35 (GEN) | 5962-9322502MYA |
| 7B185-12 (GEN) | 5962-9159402MZA | QP7C186A-45LMB | 5962-3829411MYA | 7C196-35 (GEN) | 5962-9322502MZA |
| 7B185-15 (GEN) | 5962-8969106UA | QP7C186A-55DMB | 5962-3829409MXA | 7C196-45 (GEN) | 5962-9322501MXA |
| 7B185-15 (GEN) | 5962-9159401MTA | QP7C186A-55LMB | 5962-3829409MYA | 7C196-45 (GEN) | 5962-9322501MYA |
| 7B185-15 (GEN) | 5962-9159401MYA | QP7C186A-70DMB | 5962-3829407MXA | 7C196-45 (GEN) | 5962-9322501MZA |
| 7B185-15 (GEN) | 5962-9159401MZA | QP7C186A-70LMB | 5962-3829407MYA | QP7C198-100DMB | 5962-8866201XA |
| 7C185-15 (GEN) | 5962-3829418MTA | 7C187-35 (GEN) | 5962-8601502YA | QP7C198-100LMB | 5962-8866201YA |
| QP7C185A-20DMB | 5962-3829417MZA | IDT7187S35DB | 5962-8601501YA | QP7C198L-100DMB | 5962-8855201XA |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART II, Listed By Generic PIN

| Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN |
|---|---|---|---|---|---|
| QP7C198L-100LMB | 5962-8855201YA | QP7C199L-15KMB | 5962-8855212NA | QP7C199-70DMB | 5962-8866202NA |
| QP7C198-15DMB | 5962-8866208XA | QP7C199L-15LMB | 5962-8855212MA | QP7C199-70FMB | 5962-8866202TA |
| QP7C198-15LMB | 5962-8866208YA | QP7C199L-17DMB | 5962-8855211UA | QP7C199-70KMB | 5962-8866202MA |
| QP7C198L-15DMB | 5962-8855212XA | QP7C199L-17FMB | 5962-8855211TA | QP7C199-70LMB | 5962-8866202UA |
| QP7C198L-15LMB | 5962-8855212YA | QP7C199L-17KMB | 5962-8855211NA | QP7C199L-70DMB | 5962-8855202UA |
| QP7C198L-17DMB | 5962-8855211XA | QP7C199L-17LMB | 5962-8855211MA | QP7C199L-70DMB | 5962-8855207UA |
| QP7C198L-17LMB | 5962-8855211YA | QP7C199-20DMB | 5962-8866207NA | QP7C199L-70FMB | 5962-8855207TA |
| 7198L20 (GEN) | 5962-8989103XA | QP7C199-20FMB | 5962-8866207TA | QP7C199L-70KMB | 5962-8855202NA |
| 7198S20 (GEN) | 5962-8989104XA | QP7C199-20KMB | 5962-8866207MA | QP7C199L-70KMB | 5962-8855207NA |
| QP7C198-20DMB | 5962-8866207XA | QP7C199-20LMB | 5962-8866207UA | QP7C199L-70LMB | 5962-8855207MA |
| QP7C198-20LMB | 5962-8866207YA | QP7C199L-20DMB | 5962-8855210UA | 7200L120 (GEN) | 5962-8966601XA |
| QP7C198L-20DMB | 5962-8855210XA | QP7C199L-20FMB | 5962-8855210TA | IDT7200L30TDB | 5962-8966606XA |
| QP7C198L-20LMB | 5962-8855210YA | QP7C199L-20KMB | 5962-8855210NA | 7200L40 (GEN) | 5962-8966605XA |
| 7198L25 (GEN) | 5962-8989101XA | QP7C199L-20LMB | 5962-8855210MA | 7200L50 (GEN) | 5962-8966604XA |
| 7198S25 (GEN) | 5962-8989102XA | QP7C199-25DMB | 5962-8866206NA | 7200L65 (GEN) | 5962-8966603XA |
| QP7C198-25DMB | 5962-8866206XA | QP7C199-25FMB | 5962-8866206TA | 7200L80 (GEN) | 5962-8966602XA |
| QP7C198-25LMB | 5962-8866206YA | QP7C199-25KMB | 5962-8866206MA | 7201LA30 (GEN) | 5962-8753101UA |
| QP7C198L-25DMB | 5962-8855206XA | QP7C199-25LMB | 5962-8866206UA | IDT7201LA30DB | 5962-8753101XA |
| QP7C198L-25LMB | 5962-8855206YA | QP7C199L-25DMB | 5962-8855206UA | IDT7201LA30LB | 5962-8753101YA |
| QP7C198-35DMB | 5962-8866205XA | QP7C199L-25FMB | 5962-8855206TA | IDT7201LA30TDB | 5962-8753101TA |
| QP7C198-35LMB | 5962-8866205YA | QP7C199L-25KMB | 5962-8855206NA | IDT7201SA30TDB | 5962-8986305YA |
| QP7C198L-35DMB | 5962-8855205XA | QP7C199L-25LMB | 5962-8855206MA | 7201LA50 (GEN) | 5962-8753102UA |
| QP7C198L-35LMB | 5962-8855205YA | 7C199-35 (GEN) | 5962-8855205ZA | 7201LA50 (GEN) | 5962-8753102YA |
| QP7C198-45DMB | 5962-8866204XA | QP7C199-35DMB | 5962-8866205NA | IDT7201LA50DB | 5962-8753102XA |
| QP7C198-45LMB | 5962-8866204YA | QP7C199-35FMB | 5962-8866205TA | IDT7201LA50TDB | 5962-8753102TA |
| QP7C198L-45DMB | 5962-8855204XA | QP7C199-35KMB | 5962-8866205MA | IDT7201SA50TDB | 5962-8986303YA |
| QP7C198L-45DMB | 5962-8855209XA | QP7C199-35LMB | 5962-8866205UA | 7201LA80 (GEN) | 5962-8753103UA |
| QP7C198L-45LMB | 5962-8855204YA | QP7C199L-35DMB | 5962-8855205UA | 7201LA80 (GEN) | 5962-8753103YA |
| QP7C198L-45LMB | 5962-8855209YA | QP7C199L-35FMB | 5962-8855205TA | IDT7201LA80DB | 5962-8753103XA |
| QP7C198-55DMB | 5962-8866203XA | QP7C199L-35KMB | 5962-8855205NA | IDT7201LA80TDB | 5962-8753103TA |
| QP7C198-55LMB | 5962-8866203YA | QP7C199L-35LMB | 5962-8855205MA | 7202LA120 (GEN) | 5962-8953601UA |
| QP7C198L-55DMB | 5962-8855203XA | 7C199-45L (GEN) | 5962-8855209ZA | 7202LA120 (GEN) | 5962-8953601XA |
| QP7C198L-55DMB | 5962-8855208XA | QP7C199-45DMB | 5962-8866204NA | 7202LA120 (GEN) | 5962-8953601YA |
| QP7C198L-55LMB | 5962-8855203YA | QP7C199-45FMB | 5962-8866204TA | 7202LA120 (GEN) | 5962-8953601ZA |
| QP7C198L-55LMB | 5962-8855208YA | QP7C199-45KMB | 5962-8866204MA | 7202LA20 (GEN) | 5962-8953606ZA |
| QP7C198-70DMB | 5962-8866202XA | QP7C199-45LMB | 5962-8866204UA | IDT7202LA20DB | 5962-8953606YA |
| QP7C198-70LMB | 5962-8866202YA | QP7C199L-45DMB | 5962-8855204UA | IDT7202LA20TDB | 5962-8953606XA |
| QP7C198L-70DMB | 5962-8855202XA | QP7C199L-45DMB | 5962-8855209UA | IDTT7202LA20LB | 5962-8953606UA |
| QP7C198L-70DMB | 5962-8855207XA | QP7C199L-45FMB | 5962-8855209TA | 7202LA30 (GEN) | 5962-8953605ZA |
| QP7C198L-70LMB | 5962-8855202YA | QP7C199L-45KMB | 5962-8855204NA | IDT7202LA30DB | 5962-8953605YA |
| QP7C198L-70LMB | 5962-8855207YA | QP7C199L-45KMB | 5962-8855209NA | IDT7202LA30LB | 5962-8953605UA |
| QP7C199-100DMB | 5962-8866201NA | QP7C199L-45LMB | 5962-8855209MA | IDT7202LA30TDB | 5962-8953605XA |
| QP7C199-100FMB | 5962-8866201TA | 7C199-55 (GEN) | 5962-8855208ZA | 7202LA40 (GEN) | 5962-8953604UA |
| QP7C199-100KMB | 5962-8866201MA | QP7C199-55DMB | 5962-8866203NA | 7202LA40 (GEN) | 5962-8953604XA |
| QP7C199-100LMB | 5962-8866201UA | QP7C199-55FMB | 5962-8866203TA | 7202LA40 (GEN) | 5962-8953604YA |
| QP7C199L-100DMB | 5962-8855201UA | QP7C199-55KMB | 5962-8866203MA | 7202LA40 (GEN) | 5962-8953604ZA |
| QP7C199L-100KMB | 5962-8855201NA | QP7C199-55LMB | 5962-8866203UA | 7202LA65 (GEN) | 5962-8953603UA |
| QP7C199-15DMB | 5962-8866208NA | QP7C199L-55DMB | 5962-8855203UA | 7202LA65 (GEN) | 5962-8953603XA |
| QP7C199-15FMB | 5962-8866208TA | QP7C199L-55DMB | 5962-8855208UA | 7202LA65 (GEN) | 5962-8953603YA |
| QP7C199-15KMB | 5962-8866208MA | QP7C199L-55FMB | 5962-8855208TA | 7202LA65 (GEN) | 5962-8953603ZA |
| QP7C199-15LMB | 5962-8866208UA | QP7C199L-55KMB | 5962-8855203NA | 7202LA80 (GEN) | 5962-8953602UA |
| QP7C199L-15DMB | 5962-8855212UA | QP7C199L-55KMB | 5962-8855208NA | 7202LA80 (GEN) | 5962-8953602XA |
| QP7C199L-15FMB | 5962-8855212TA | QP7C199L-55LMB | 5962-8855208MA | 7202LA80 (GEN) | 5962-8953602YA |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

| Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN |
|---|---|---|---|---|---|
| 7202LA80 (GEN) | 5962-8953602ZA | MMCP-672061HV-15M | 5962-9317710QTC | MMDP-67206FV-30MQ | 5962-9317702QNC |
| 7203L120 (GEN) | 5962-8956701XA | MMDP-672061FV-15MQ | 5962-9317706QNC | MMDP-67206HV-30MQ | 5962-9317707QNC |
| 7203L120 (GEN) | 5962-8956701ZA | MMDP-672061HV-15M | 5962-9317710QNC | SMCP-67206FV-30SR | 5962D9317702VTC |
| 72031 (GEN) | 5962-9161802MXA | SMCP-672061FV-15SR | 5962D9317706VTC | SMCP-67206FV-30SV | 5962-9317702VTC |
| 72031 (GEN) | 5962-9161801MXA | SMCP-672061FV-15SV | 5962-9317706VTC | SMCP-67206HV-30SR | 5962D9317707VTC |
| IDT7203S20LB | 5962-8866906ZA | SMCP-672061HV-15SR | 5962D9317710VTC | SMCP-67206HV-30SV | 5962-9317707VTC |
| IDT7203S20TDB | 5962-8866906YA | SMCP-672061HV-15SV | 5962-9317710VTC | SMDP-67206FV-30SR | 5962D9317702VNC |
| IDT7203S30LB | 5962-8866905ZA | SMDP-672061FV-15SR | 5962D9317706VNC | SMDP-67206FV-30SV | 5962-9317702VNC |
| IDT7203S30TDB | 5962-8866905YA | SMDP-672061FV-15SV | 5962-9317706VNC | SMDP-67206HV-30SR | 5962D9317707VNC |
| IDT7203L40DB | 5962-8956705XA | SMDP-672061HV-15SR | 5962D9317710VNC | SMDP-67206HV-30SV | 5962-9317707VNC |
| IDT7203L40LB | 5962-8956705ZA | SMDP-672061HV-15SV | 5962-9317710VNC | 7210L30 (GEN) | 5962-8873304TA |
| 7203L50 (GEN) | 5962-8956704XA | 672061-30 (GEN) | 5962-9317705QUC | 7210L30 (GEN) | 5962-8873304XA |
| 7203L50 (GEN) | 5962-8956704ZA | 672061-30 (GEN) | 5962-9317705QZC | 7210L30 (GEN) | 5962-8873304ZA |
| 7203L65 (GEN) | 5962-8956703XA | 672061-30 (GEN) | 5962-9317705VUC | 72103L120 (GEN) | 5962-8994201QA |
| 7203L65 (GEN) | 5962-8956703ZA | 672061-30 (GEN) | 5962-9317705VZC | 72103L120 (GEN) | 5962-8994201XA |
| 7203L80 (GEN) | 5962-8956702XA | MMCP-672061FV-30MQ | 5962-9317705QTC | 72103L40 (GEN) | 5962-8994205QA |
| 7203L80 (GEN) | 5962-8956702ZA | MMCP-672061HV-30M | 5962-9317709QTC | 72103L40 (GEN) | 5962-8994205XA |
| 7204L120 (GEN) | 5962-8956801XA | MMDP-672061FV-30MQ | 5962-9317705QNC | 72103L50 (GEN) | 5962-8994204QA |
| 7204L120 (GEN) | 5962-8956801YA | MMDP-672061HV-30M | 5962-9317709QNC | 72103L50 (GEN) | 5962-8994204XA |
| 7204L120 (GEN) | 5962-8956801ZA | SMCP-672061FV-30SR | 5962D9317705VTC | 72103L65 (GEN) | 5962-8994203QA |
| 7204L20 (GEN) | 5962-8956807YA | SMCP-672061FV-30SV | 5962-9317705VTC | 72103L65 (GEN) | 5962-8994203XA |
| IDT7204L20DB | 5962-8956807XA | SMCP-672061HV-30SR | 5962D9317709VTC | 72103L80 (GEN) | 5962-8994202QA |
| IDT7204L20LB | 5962-8956807ZA | SMCP-672061HV-30SV | 5962-9317709VTC | 72103L80 (GEN) | 5962-8994202XA |
| IDT7204L20TDB | 5962-8956807UA | SMDP-672061FV-30SR | 5962D9317705VNC | 7210L40 (GEN) | 5962-8873305TA |
| 7204L30 (GEN) | 5962-8956806YA | SMDP-672061FV-30SV | 5962-9317705VNC | 7210L40 (GEN) | 5962-8873305XA |
| IDT7204L30DB | 5962-8956806XA | SMDP-672061HV-30SR | 5962D9317709VNC | 7210L40 (GEN) | 5962-8873305ZA |
| IDT7204L30LB | 5962-8956806ZA | SMDP-672061HV-30SV | 5962-9317709VNC | 72104L120 (GEN) | 5962-8994301QA |
| IDT7204L30TDB | 5962-8956806UA | 67206-15 (GEN) | 5962-9317704QUC | 72104L120 (GEN) | 5962-8994301XA |
| 7204L40 (GEN) | 5962-8956805UA | 67206-15 (GEN) | 5962-9317704QZC | 72104L40 (GEN) | 5962-8994305QA |
| 7204L40 (GEN) | 5962-8956805XA | 67206-15 (GEN) | 5962-9317704VUC | 72104L50 (GEN) | 5962-8994304QA |
| 7204L40 (GEN) | 5962-8956805YA | 67206-15 (GEN) | 5962-9317704VZC | 72104L50 (GEN) | 5962-8994304XA |
| 7204L40 (GEN) | 5962-8956805ZA | MMCP-67206FV-15MQ | 5962-9317704QTC | 72104L65 (GEN) | 5962-8994303QA |
| 7204L50 (GEN) | 5962-8956804UA | MMCP-67206HV-15MQ | 5962-9317708QTC | 72104L65 (GEN) | 5962-8994303XA |
| 7204L50 (GEN) | 5962-8956804XA | MMDP-67206FV-15MQ | 5962-9317704QNC | 72104L80 (GEN) | 5962-8994302QA |
| 7204L50 (GEN) | 5962-8956804YA | MMDP-67206HV-15MQ | 5962-9317708QNC | 72104L80 (GEN) | 5962-8994302XA |
| 7204L50 (GEN) | 5962-8956804ZA | SMCP-67206FV-15SR | 5962D9317704VTC | 7210L-55 (GEN) | 5962-8873301TA |
| 7204L65 (GEN) | 5962-8956803XA | SMCP-67206FV-15SV | 5962-9317704VTC | 7210L-65 (GEN) | 5962-8873302TA |
| 7204L65 (GEN) | 5962-8956803YA | SMCP-67206HV-15SR | 5962D9317708VTC | 7210L75 (GEN) | 5962-8873303TA |
| 7204L65 (GEN) | 5962-8956803ZA | SMCP-67206HV-15SV | 5962-9317708VTC | RTSX72SU-1CQ208B | 5962-0151506QYC |
| 7204L80 (GEN) | 5962-8956802XA | SMDP-67206FV-15SR | 5962D9317704VNC | RTSX72SU-1CQ208E | 5962-0151508QYC |
| 7204L80 (GEN) | 5962-8956802YA | SMDP-67206FV-15SV | 5962-9317704VNC | RTSX72SU-1CQ256B | 5962-0151506QXC |
| 7204L80 (GEN) | 5962-8956802ZA | SMDP-67206HV-15SR | 5962D9317708VNC | RTSX72SU-1CQ256E | 5962-0151508QXC |
| IDT7205L30DB | 5962-9167703MXA | SMDP-67206HV-15SV | 5962-9317708VNC | 7216L20 (GEN) | 5962-8687306UA |
| IDT7205L30LB | 5962-9167703MZA | IDT7206L20DB | 5962-9317703MXA | 7216L20 (GEN) | 5962-8687306ZA |
| IDT7205L30TDB | 5962-9167703MYA | IDT7206L20LB | 5962-9317703MYA | 7216L25 (GEN) | 5962-8687305UA |
| IDT7205L50DB | 5962-9167702MXA | 67206-30 (GEN) | 5962-9317702QUC | 7216L25 (GEN) | 5962-8687305VA |
| IDT7205L50LB | 5962-9167702MZA | 67206-30 (GEN) | 5962-9317702QZC | 7216L25 (GEN) | 5962-8687305VC |
| IDT7205L50TDB | 5962-9167702MYA | 67206-30 (GEN) | 5962-9317702VUC | 7216L25 (GEN) | 5962-8687305XA |
| 672061-15 (GEN) | 5962-9317706QUC | 67206-30 (GEN) | 5962-9317702VZC | 7216L25 (GEN) | 5962-8687305XC |
| 672061-15 (GEN) | 5962-9317706QZC | IDT7206L30DB | 5962-9317702MXA | 7216L25 (GEN) | 5962-8687305YA |
| 672061-15 (GEN) | 5962-9317706VUC | IDT7206L30LB | 5962-9317702MYA | 7216L25 (GEN) | 5962-8687305YC |
| 672061-15 (GEN) | 5962-9317706VZC | MMCP-67206FV-30MQ | 5962-9317702QTC | 7216L25 (GEN) | 5962-8687305ZA |
| MMCP-672061FV-15MQ | 5962-9317706QTC | MMCP-67206HV-30MQ | 5962-9317707QTC | 7216L30 (GEN) | 5962-8687304UA |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART II, Listed By Generic PIN

| Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN |
|---|---|---|---|---|---|
| 7216L30 (GEN) | 5962-8687304VA | 72225LB25 (GEN) | 5962-9205703MXA | 7C235A-30 (GEN) | 5962-8863604LA |
| 7216L30 (GEN) | 5962-8687304VC | 72225LB25 (GEN) | 5962-9205703MYA | 7C235A-40 | 5962-88636013A |
| 7216L30 (GEN) | 5962-8687304XA | 72225LB35 (GEN) | 5962-9205702MXA | 7C235A-40 | 5962-8863601KA |
| 7216L30 (GEN) | 5962-8687304XC | 72225LB35 (GEN) | 5962-9205702MYA | 7C235A-40 | 5962-8863601LA |
| 7216L30 (GEN) | 5962-8687304YA | 72225LB50 (GEN) | 5962-9205701MXA | 7C235A-40 | 5962-88636033A |
| 7216L30 (GEN) | 5962-8687304YC | 72225LB50 (GEN) | 5962-9205701MYA | 7C235A-40 | 5962-8863603KA |
| 7216L30 (GEN) | 5962-8687304ZA | 72231L25 (GEN) | 5962-9470703MXA | CY7C235A-40DMB | 5962-8863603LA |
| 7216L40 (GEN) | 5962-8687301UA | 72231L35 (GEN) | 5962-9470702MXA | AD7237ATQ/QML | 5962-9078502MLA |
| 7216L40 (GEN) | 5962-8687301ZA | 72231L50 (GEN) | 5962-9470701MXA | IDT72401L10DB | 5962-8952305EA |
| 7216L40 (GEN) | 5962-8687301VA | AD7224UE/883B | 5962-9090801M2A | IDT72401L15DMB | 5962-8952306EA |
| 7216L40 (GEN) | 5962-8687301VC | AD7224UQ/883B | 5962-9090801MVA | IDT72401L25DB | 5962-8952307EA |
| 7216L40 (GEN) | 5962-8687301XA | 72240L25 (GEN) | 5962-9550603MXA | IDT72401L35DB | 5962-8952308EA |
| 7216L40 (GEN) | 5962-8687301XC | 72240L35 (GEN) | 5962-9550602MXA | IDT72403L10DB | 5962-8952301EA |
| 7216L40 (GEN) | 5962-8687301YA | 72240L50 (GEN) | 5962-9550601MXA | 72403L15 (GEN) | 5962-8952302EA |
| 7216L40 (GEN) | 5962-8687301YC | 72241L20 (GEN) | 5962-9451104MXA | 72403L25 (GEN) | 5962-8952303EA |
| 7216L55 (GEN) | 5962-8687302UA | 72241L25 (GEN) | 5962-9451103MXA | IDT72403L35DB | 5962-8952304EA |
| 7216L55 (GEN) | 5962-8687302VA | 72241L35 (GEN) | 5962-9451102MXA | 72404L10 (GEN) | 5962-8684601VA |
| 7216L55 (GEN) | 5962-8687302VC | 72241L50 (GEN) | 5962-9451101MXA | 72404L10 (GEN) | 5962-8684601XA |
| 7216L55 (GEN) | 5962-8687302XA | 7224525 (GEN) | 5962-9318903MXA | 72404L25 (GEN) | 5962-8684601SA |
| 7216L55 (GEN) | 5962-8687302XC | 7224525 (GEN) | 5962-9318903MYA | 72404L15 (GEN) | 5962-8684602SA |
| 7216L55 (GEN) | 5962-8687302YA | 7224535 (GEN) | 5962-9318902MXA | 72404L15 (GEN) | 5962-8684602XA |
| 7216L55 (GEN) | 5962-8687302YC | 7224535 (GEN) | 5962-9318902MYA | IDT72404L15DB | 5962-8684602VA |
| 7216L55 (GEN) | 5962-8687302ZA | 7224550 (GEN) | 5962-9318901MXA | 72404L25 (GEN) | 5962-8684603SA |
| 7216L75 (GEN) | 5962-8687303UA | 7224550 (GEN) | 5962-9318901MYA | 72404L25 (GEN) | 5962-8684603VA |
| 7216L75 (GEN) | 5962-8687303VA | CY7C225A-25DMB | 5962-8851807LA | 72404L25 (GEN) | 5962-8684603XA |
| 7216L75 (GEN) | 5962-8687303VC | CY7C225A-25LMB | 5962-88518073A | 72404L35 (GEN) | 5962-86846042A |
| 7216L75 (GEN) | 5962-8687303XA | CY7C225A-30DMB | 5962-8851804LA | 72404L35 (GEN) | 5962-8684604SA |
| 7216L75 (GEN) | 5962-8687303XC | CY7C225A-30LMB | 5962-88518043A | IDT72404L35DB | 5962-8684604VA |
| 7216L75 (GEN) | 5962-8687303YA | CY7C225A-35DMB | 5962-8851805LA | CY7C421-65KMB | 5962-8986302UA |
| 7216L75 (GEN) | 5962-8687303YC | CY7C225A-35DMB | 5962-8851805LA | AD7243SQ/883B | 5962-9320401MEA |
| 7216L75 (GEN) | 5962-8687303ZA | CY7C225A-35LMB | 5962-88518053A | AD7244SQ/883B | 5962-9164701MLA |
| 7217L-40 (GEN) | 5962-8768601UA | CY7C225A-40DMB | 5962-8851806LA | AD7245ATE/883B | 5962-88766013A |
| 7217L-40 (GEN) | 5962-8768601XA | CY7C225A-40LMB | 5962-88518063A | AD7245ATQ/883B | 5962-8876601LA |
| 7217L-40 (GEN) | 5962-8768601YA | RTSX72SU-CQ256B | 5962-0151505QXC | 7C245A/KA | 5962-8981503KA |
| 7217L-40 (GEN) | 5962-8768601ZA | RTSX72SU-CQ256E | 5962-0151507QXC | 7C245A-18 (GEN) | 5962-89815033A |
| 72200L20 (GEN) | 5962-9175701MXA | AD7226TE/883B | 5962-87802012C | 7C245A-18 (GEN) | 5962-8981503LA |
| RTSX72SU-CQ208B | 5962-0151505QYC | AD7226TQ/883B | 5962-8780201RA | CY7C245A-25DMB | 5962-8873504LA |
| RTSX72SU-CQ208E | 5962-0151507QYC | MX7226TE/883B | 5962-87802012C | AD7247ATQ/QML | 5962-9078501MLA |
| IDT72211L25LB | 5962-9324903MXA | MX7226TQ/883B | 5962-8780201RA | AD7248ATQ/883B | 5962-8876602RA |
| IDT72211L35LB | 5962-9324902MXA | TLC7226MFKB | 5962-87802012A | LM725H/883 | 5962-9552901MGA |
| IDT72211L50LB | 5962-9324901MXA | TLC7226MFKB | 5962-87802012C | 7C251-45 (GEN) | 5962-8953703ZA |
| 72215LB25 (GEN) | 5962-9210103MXA | AD7228T (GEN) | 5962-8866301LA | CY7C251-45QMB | 5962-8953703UA |
| 72215LB25 (GEN) | 5962-9210103MYA | AD7228TE/883B | 5962-88663013A | CY7C251-45WMB | 5962-8953703YA |
| 72215LB35 (GEN) | 5962-9210102MXA | AD7228UE/883B | 5962-88663023A | 7C251-55 (GEN) | 5962-8953702ZA |
| 72215LB35 (GEN) | 5962-9210102MYA | AD7228UQ/883B | 5962-8866302LA | CY7C251-55QMB | 5962-8953702UA |
| 72215LB50 (GEN) | 5962-9210101MXA | 7C235A-25 | 5962-88636053A | CY7C251-55WMB | 5962-8953702YA |
| 72215LB50 (GEN) | 5962-9210101MYA | 7C235A-25 | 5962-8863605KA | 7C251-65 (GEN) | 5962-8953701ZA |
| 72220L25 (GEN) | 5962-9313803MXA | 7C235A-25 | 5962-8863605LA | CY7C251-65QMB | 5962-8953701UA |
| 72220L25 (GEN) | 5962-9313803MYA | 7C235A-30 | 5962-88636023A | CY7C251-65WMB | 5962-8953701YA |
| 72220L35 (GEN) | 5962-9313802MXA | 7C235A-30 | 5962-8863602KA | 7C254-45 (GEN) | 5962-8953803UA |
| 72220L35 (GEN) | 5962-9313802MYA | 7C235A-30 | 5962-8863602LA | 7C254-45 (GEN) | 5962-8953803XA |
| 72220L50 (GEN) | 5962-9313801MXA | 7C235A-30 | 5962-88636043A | 7C254-45 (GEN) | 5962-8953803ZA |
| 72220L50 (GEN) | 5962-9313801MYA | 7C235A-30 | 5962-8863604KA | 7C254-55 (GEN) | 5962-8953802XA |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART II, Listed By Generic PIN

| Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN |
|---|---|---|---|---|---|
| 7C254-55 (GEN) | 5962-8953802ZA | 7C265-25 (GEN) | 5962-8948402MYA | 7C271-55 (GEN) | 5962-8981701XA |
| 7C254-65 (GEN) | 5962-8953801XA | CY7C265-25DMB | 5962-8996703MXA | 7C271-55 (GEN) | 5962-8981701YA |
| 7C254-65 (GEN) | 5962-8953801ZA | CY7C265-25KMB | 5962-8996703MYA | 7C271-55 (GEN) | 5962-8981701ZA |
| 7256-15 (GEN) | 5962-9324702MXC | CY7C265-25LMB | 5962-8996703M3A | 7C271-55 (GEN) | 5962-9316601MXA |
| 7256-15 (GEN) | 5962-9324702MYA | CY7C265-25QMB | 5962-8948402M3A | 7C271-55 (GEN) | 5962-9316601MYA |
| 7256-20 (GEN) | 5962-9324701MXC | CY7C265-25WMB | 5962-8948402MXA | 7C274-35 (GEN) | 5962-8981706UA |
| 7256-20 (GEN) | 5962-9324701MYA | 7C265-50 (GEN) | 5962-8948401MYA | 7C274-35 (GEN) | 5962-9316606MUA |
| 7C258-12 (GEN) | 5962-9312202M3A | CY7C265-50DMB | 5962-8996702MXA | 7C274-35 (GEN) | 5962-9316606MZA |
| 7C258-12 (GEN) | 5962-9312202MXA | CY7C265-50KMB | 5962-8996702MYA | CY7C274-35QMB | 5962-8981706ZA |
| 7C258-12 (GEN) | 5962-9312202MYA | CY7C265-50LMB | 5962-8996702M3A | 7C274-45 (GEN) | 5962-8981705UA |
| 7C258-12 (GEN) | 5962-9312302M3A | CY7C265-50QMB | 5962-8948401M3A | 7C274-45 (GEN) | 5962-8981705ZA |
| 7C258-12 (GEN) | 5962-9312302MXA | CY7C265-50WMB | 5962-8948401MXA | 7C274-45 (GEN) | 5962-9316605MUA |
| 7C258-12 (GEN) | 5962-9312302MYA | CY7C265-60DMB | 5962-8996701MXA | 7C274-45 (GEN) | 5962-9316605MZA |
| 7C258-15 (GEN) | 5962-9312201M3A | CY7C265-60KMB | 5962-8996701MYA | 7C274-55 (GEN) | 5962-8981704UA |
| 7C258-15 (GEN) | 5962-9312201MXA | CY7C265-60LMB | 5962-8996701M3A | 7C274-55 (GEN) | 5962-8981704ZA |
| 7C258-15 (GEN) | 5962-9312201MYA | HCTS7266 (GEN) | 5962R9575201V9A | 7C274-55 (GEN) | 5962-9316604MUA |
| 7C258-15 (GEN) | 5962-9312301M3A | HCTS7266 (GEN) | 5962R9575201VCC | 7C274-55 (GEN) | 5962-9316604MZA |
| 7C258-15 (GEN) | 5962-9312301MXA | HCTS7266 (GEN) | 5962R9575201VXC | CY7C277-40DMB | 5962-9215502MXA |
| 7C258-15 (GEN) | 5962-9312301MYA | 7C266-25 (GEN) | 5962-9162402MXA | CY7C277-40KMB | 5962-9215502MZA |
| 7C259-12 (GEN) | 5962-9312204MUA | 7C266-25 (GEN) | 5962-9162402MYA | CY7C277-40LMB | 5962-9215502MYA |
| 7C259-12 (GEN) | 5962-9312204MZA | 7C266-45 (GEN) | 5962-9162401MXA | CY7C277-40QMB | 5962-9174402MYA |
| 7C259-12 (GEN) | 5962-9312304MUA | 7C266-45 (GEN) | 5962-9162401MYA | CY7C277-40TMB | 5962-9174402MZA |
| 7C259-12 (GEN) | 5962-9312304MZA | 7C269-15 (GEN) | 5962-9093003MYA | CY7C277-40WMB | 5962-9174402MXA |
| 7C259-15 (GEN) | 5962-9312203MUA | CY7C269-15QMB | 5962-9093003M3A | CY7C277-50DMB | 5962-9215501MXA |
| 7C259-15 (GEN) | 5962-9312203MZA | CY7C269-15WMB | 5962-9093003MXA | CY7C277-50KMB | 5962-9215501MZA |
| 7C259-15 (GEN) | 5962-9312303MUA | CY7C269-18DMB | 5962-9083104MXA | CY7C277-50LMB | 5962-9215501MYA |
| 7C259-15 (GEN) | 5962-9312303MZA | CY7C269-18KMB | 5962-9083104MYA | CY7C277-50QMB | 5962-9174401MYA |
| CY7C261-25DMB | 5962-9080304MLA | CY7C269-18LMB | 5962-9083104M3A | CY7C277-50TMB | 5962-9174401MZA |
| CY7C261-25KMB | 5962-9080304MKA | 7C269-25 (GEN) | 5962-9093002MYA | CY7C277-50WMB | 5962-9174401MXA |
| CY7C261-25LMB | 5962-9080304M3A | CY7C269-25DMB | 5962-9083103MXA | CY7C281A-30KMB | 5962-8765103KA |
| CY7C261-25QMB | 5962-87515123A | CY7C269-25KMB | 5962-9083103MYA | CY7C281A-30LMB | 5962-87651033A |
| CY7C261-25TMB | 5962-8751512KA | CY7C269-25LMB | 5962-9083103M3A | CY7C281A-30LMB | 5962-8765103LA |
| CY7C261-25WMB | 5962-8751512LA | CY7C269-25QMB | 5962-9093002M3A | CY7C281A-45DMB | 5962-8765102LA |
| CY7C261-35DMB | 5962-9080303MLA | CY7C269-25WMB | 5962-9093002MXA | CY7C281A-45KMB | 5962-8765102KA |
| CY7C261-35DMB | 5962-9080303MLA | 7C269-50 (GEN) | 5962-9093001MYA | CY7C281A-45LMB | 5962-87651023A |
| CY7C261-35QMB | 5962-87515073A | CY7C269-50DMB | 5962-9083102MXA | CY7C282A-30DMB | 5962-8765103JA |
| CY7C261-45WMB | 5962-8751505LA | CY7C269-50KMB | 5962-9083102MYA | CY7C282A-45DMB | 5962-8765102JA |
| CY7C261-55WMB | 5962-8751506LA | CY7C269-50LMB | 5962-9083102M3A | 7C285 (GEN) | 5962-9232202MXA |
| CY7C263-25DMB | 5962-9080308MLA | CY7C269-50QMB | 5962-9093001M3A | 7C285 (GEN) | 5962-9232202MYA |
| CY7C263-25KMB | 5962-9080308MKA | CY7C269-50WMB | 5962-9093001MXA | 7C285 (GEN) | 5962-9232202MZA |
| CY7C263-25LMB | 5962-9080308M3A | CY7C269-60DMB | 5962-9083101MXA | 7C285 (GEN) | 5962-9232201MXA |
| CY7C263-25QMB | 5962-87515113A | CY7C269-60KMB | 5962-9083101MYA | 7C285 (GEN) | 5962-9232201MYA |
| CY7C263-25TMB | 5962-8751511KA | CY7C269-60LMB | 5962-9083101M3A | 7C285 (GEN) | 5962-9232201MZA |
| CY7C263-25WMB | 5962-8751511LA | 7C271-35 (GEN) | 5962-8981703XA | 7C286-60 (GEN) | 5962-9207102MXA |
| CY7C263-35WMB | 5962-8751508LA | 7C271-35 (GEN) | 5962-8981703YA | 7C286-60 (GEN) | 5962-9207102MYA |
| CY7C264-25DMB | 5962-9080308MJA | 7C271-35 (GEN) | 5962-8981703ZA | 7C286-70 (GEN) | 5962-9207101MXA |
| CY7C264-25WMB | 5962-8751511JA | 7C271-35 (GEN) | 5962-9316603MXA | 7C286-70 (GEN) | 5962-9207101MYA |
| 7C265-15 (GEN) | 5962-8948403MYA | 7C271-35 (GEN) | 5962-9316603MYA | CY7C287-55DMB | 5962-9206502MXA |
| CY7C265-15QMB | 5962-8948403M3A | 7C271-45 (GEN) | 5962-8981702YA | CY7C287-55LMB | 5962-9206502MYA |
| CY7C265-15WMB | 5962-8948403MXA | 7C271-45 (GEN) | 5962-9316602MXA | CY7C287-55QMB | 5962-9091302MYA |
| CY7C265-18DMB | 5962-8996704MXA | 7C271-45 (GEN) | 5962-9316602MYA | CY7C287-55WMB | 5962-9091302MXA |
| CY7C265-18KMB | 5962-8996704MYA | CY7C271-45QMB | 5962-8981702ZA | CY7C287-65DMB | 5962-9206501MXA |
| CY7C265-18LMB | 5962-8996704M3A | CY7C271-45WMB | 5962-8981702XA | CY7C287-65LMB | 5962-9206501MYA |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

| Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN |
|---|---|---|---|---|---|
| CY7C287-65QMB | 5962-9091301MYA | 7C331-40 (GEN) | 5962-8985501M3A | CY7C346-30HMB | 5962-9314402MUA |
| CY7C287-65WMB | 5962-9091301MXA | 7C331-40 (GEN) | 5962-8985501MXA | CY7C346-30RMB | 5962-9314402MZC |
| 7C291A-25/3A | 5962-87650053A | 7C331-40 (GEN) | 5962-8985501MYA | CY7C346-30RMB | 5962-9314402MZC |
| 7C291A-25/KA | 5962-8765005KA | 7C331-40 (GEN) | 5962-8985501MZA | CY7C346-35HMB | 5962-9314401MUA |
| CY7C291A-25DMB | 5962-8873404LA | 7C331-40 (GEN) | 5962-9075401MYA | CY7C346-35RMB | 5962-9314401MZC |
| CY7C291A-25LMB | 5962-88734043A | 7C331-40 (GEN) | 5962-9075401MZA | 7C371-66 (GEN) | 5962-9468401QXA |
| 7C291-35/3A | 5962-87650033A | 7C332-20 (GEN) | 5962-9158402MYA | 7C371-83 (GEN) | 5962-9468402QXA |
| 7C291-35/KA | 5962-8765003KA | 7C332-20 (GEN) | 5962-9158402MZA | 7C372-66 (GEN) | 5962-9468801QXA |
| 7C291A-35DMB | 5962-8873403LA | 7C332-25 (GEN) | 5962-9158401M3A | 7C372I-66 (GEN) | 5962-9759701QXA |
| CY7C291-35WMB | 5962-8765003LA | 7C332-25 (GEN) | 5962-9158401MYA | 7C372-83 (GEN) | 5962-9468802QXA |
| CY7C291A-35LMB | 5962-88734033A | 7C332-25 (GEN) | 5962-9158401MZA | 7C372I-83 (GEN) | 5962-9759702QXA |
| 7C291A-45DMB | 5962-8873402LA | CY7C335-50HMB | 5962-9451001MYA | 7C374-66 (GEN) | 5962-9471301QXC |
| CY7C291A-45LMB | 5962-88734023A | CY7C335-50QMB | 5962-9451001MZA | 7C374-66 (GEN) | 5962-9471301QYA |
| 7C291A-55DMB | 5962-8873401LA | CY7C335-50WMB | 5962-9451001MXA | 7C374I-66 (GEN) | 5962-9759801QXC |
| 7C293A-25 (GEN) | 5962-8868004LA | CY7C335-66HMB | 5962-9451002MYA | CY7C374I-66YMB | 5962-9759801QYA |
| 7C293A-30 (GEN) | 5962-8868003LA | CY7C335-66QMB | 5962-9451002MZA | CY7C374I-83YMB | 5962-9759802QYA |
| 7C293A-35 (GEN) | 5962-8868002LA | CY7C335-66QMB | 5962-9451002MZA | 7C374-83 (GEN) | 5962-9471302QXC |
| 7C293A-50 (GEN) | 5962-8868001LA | CY7C335-66WMB | 5962-9451002MXA | 7C374-83 (GEN) | 5962-9471302QYA |
| ISL72991RHQF | 5962F0250301QXC | CY7C335-83HMB | 5962-9451003MYA | CY7C374I-83GMB | 5962-9759802QXC |
| ISL72991RHVF | 5962F0250301VXC | CY7C335-83QMB | 5962-9451003MZA | 7C375-66 (GEN) | 5962-9555701QXC |
| ISL72991RHVX | 5962F0250301V9A | CY7C335-83WMB | 5962-9451003MXA | 7C375-66 (GEN) | 5962-9555701QYC |
| MAX731MJA/883B | 5962-9462101MPA | CY7C341-30HMB | 5962-9206202MXA | 7C375-66 (GEN) | 5962-9555701QZC |
| MAX731MLP/883B | 5962-9462101M2C | CY7C341-30RMB | 5962-9206202MYC | 7C375I-66 (GEN) | 5962-9759901QXC |
| MAX732MJA/883B | 5962-9462102MPA | CY7C341-30RMB | 5962-9206202MYC | 7C375I-66 (GEN) | 5962-9759901QYC |
| MAX732MLP/883B | 5962-9462102M2C | CY7C341-35HMB | 5962-9206203MXA | CY7C375I-66UMB | 5962-9759901QZC |
| 733 (GEN) | 84185012A | CY7C341-35HMB | 5962-9206203MXA | 7C375-83 (GEN) | 5962-9555702QXC |
| 733 (GEN) | 8418501CA | CY7C341-35RMB | 5962-9206203MYC | 7C375-83 (GEN) | 5962-9555702QYC |
| 733 (GEN) | 8418501HA | CY7C341-40HMB | 5962-9206201MXA | 7C375-83 (GEN) | 5962-9555702QZC |
| 733 (GEN) | 8418501IA | CY7C341-40RMB | 5962-9206201MYC | 7C375I-83 (GEN) | 5962-9759902QYC |
| MAX733MJA/883B | 5962-9462103MPA | CY7C342B-15HMB | 5962-8946805YA | CY7C375I-83GMB | 5962-9759902QXC |
| MAX733MLP/883B | 5962-9462103M2C | CY7C342B-15RMB | 5962-8946805XC | CY7C375I-83UMB | 5962-9759902QZC |
| 7C330-28 (GEN) | 5962-8954601XA | 7C342B-20 (GEN) | 5962-8946804ZA | MAX738AMJA/883B | 5962-9312101MPA |
| 7C330-40 (GEN) | 5962-89546023A | CY7C342B-20HMB | 5962-8946804YA | CY7C386A (GEN) | 5962-9559901QXC |
| 7C330-40 (GEN) | 5962-8954602XA | CY7C342B-20RMB | 5962-8946804XC | CY7C386A (GEN) | 5962-9559902QXC |
| 7C330-40 (GEN) | 5962-8954602YA | 7C342B-25 (GEN) | 5962-8946803ZA | CY7C386A (GEN) | 5962-9559903QXC |
| 7C330-50 (GEN) | 5962-89546033A | CY7C342B-25HMB | 5962-8946803YA | ACS74DMSR | 5962F9679901VCC |
| 7C330-50 (GEN) | 5962-8954603XA | CY7C342B-25RMB | 5962-8946803XC | ACS74HMSR | 5962F9679901V9A |
| 7C330-50 (GEN) | 5962-8954603YA | 7C342-30 (GEN) | 5962-8946802ZA | ACS74KMSR | 5962F9679901VXC |
| 7C331-25 (GEN) | 5962-8985503M3A | CY7C342B-30HMB | 5962-8946802YA | ACTS74 (GEN) | 5962F9671301VCC |
| 7C331-25 (GEN) | 5962-8985503MXA | CY7C342B-30RMB | 5962-8946802XC | ACTS74 (GEN) | 5962F9671301VXC |
| 7C331-25 (GEN) | 5962-8985503MYA | 7C342B-35 (GEN) | 5962-8946801ZA | HCS74 (GEN) | 5962R9578201TCC |
| 7C331-25 (GEN) | 5962-8985503MZA | CY7C342B-35HMB | 5962-8946801YA | HCS74 (GEN) | 5962R9578201TXC |
| 7C331-25 (GEN) | 5962-9075403M3A | CY7C342B-35HMB | 5962-8946801YA | HCS74DMSR | 5962R9578201VCC |
| 7C331-25 (GEN) | 5962-9075403MXA | CY7C342B-35RMB | 5962-8946801XC | HCS74HMSR | 5962R9578201V9A |
| 7C331-25 (GEN) | 5962-9075403MYA | CY7C342B-35RMB | 5962-8946801XC | HCS74KMSR | 5962R9578201VXC |
| 7C331-25 (GEN) | 5962-9075403MZA | CY7C343-30HMB | 5962-9215802MXA | HCTS74 (GEN) | 5962R9576301TCC |
| 7C331-30 (GEN) | 5962-8985502M3A | CY7C344-25HMB | 5962-9061102YA | HCTS74 (GEN) | 5962R9576301TXC |
| 7C331-30 (GEN) | 5962-8985502MXA | CY7C344-25HMB | 5962-9061102YA | HCTS74 (GEN) | 5962R9576301V9A |
| 7C331-30 (GEN) | 5962-8985502MYA | CY7C344-25WMB | 5962-9061102XA | HCTS74DMSR | 5962R9576301VCC |
| 7C331-30 (GEN) | 5962-8985502MZA | CY7C344-25WMB | 5962-9061102XA | HCTS74KMSR | 5962R9576301VXC |
| 7C331-30 (GEN) | 5962-9075402M3A | CY7C344-35HMB | 5962-9061101YA | CY7C401-10DMB | 5962-8952305EA |
| 7C331-30 (GEN) | 5962-9075402MYA | CY7C344-35WMB | 5962-9061101XA | CY7C401-10LMB | 5962-89523052A |
| 7C331-30 (GEN) | 5962-9075402MZA | CY7C346-30HMB | 5962-9314402MUA | CY7C401-15DMB | 5962-8952306EA |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART II, Listed By Generic PIN

| Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN |
|---|---|---|---|---|---|
| CY7C401-15LMB | 5962-89523062A | CY7C424-80DMB | 5962-9158502MYA | CY7C432-65DMB | 5962-9071503MXA |
| ACTS74 (GEN) | 5962F9671302VCC | CY7C425-120DMB | 5962-9158501MXA | CY7C432-80DMB | 5962-9071502MXA |
| ACTS74 (GEN) | 5962F9671302VXC | CY7C425-120KMB | 5962-9158501MZA | CY7C433-120DMB | 5962-9071501MUA |
| ACTS74HMSR-02 | 5962F9671302V9C | CY7C425-120LMB | 5962-9158501MUA | CY7C433-120KMB | 5962-9071501MYA |
| ACS74-02 (GEN) | 5962F9679902V9A | CY7C425-30DMB | 5962-9158506MXA | CY7C433-120LMB | 5962-9071501MZA |
| ACS74-02 (GEN) | 5962F9679902VCC | CY7C425-30KMB | 5962-9158506MZA | CY7C433-20DMB | 5962-9071507MUA |
| ACS74-02 (GEN) | 5962F9679902VXC | CY7C425-30LMB | 5962-9158506MUA | CY7C433-20KMB | 5962-9071507MYA |
| 7C403-10 (GEN) | 5962-89523012A | CY7C425-40DMB | 5962-9158505MXA | CY7C433-20LMB | 5962-9071507MZA |
| 7C403-15 (GEN) | 5962-89523022A | CY7C425-40KMB | 5962-9158505MZA | CY7C433-30DMB | 5962-9071506MUA |
| 7C404-10 (GEN) | 5962-86846012A | CY7C425-40LMB | 5962-9158505MUA | CY7C433-30KMB | 5962-9071506MYA |
| 7C404-15 (GEN) | 5962-86846022A | CY7C425-50DMB | 5962-9158504MXA | CY7C433-30LMB | 5962-9071506MZA |
| 7C404-25 (GEN) | 5962-86846032A | CY7C425-50KMB | 5962-9158504MZA | CY7C433-40DMB | 5962-9071505MUA |
| CY7C408A-15DMB | 5962-8966401XA | CY7C425-50LMB | 5962-9158504MUA | CY7C433-40KMB | 5962-9071505MYA |
| CY7C408A-15KMB | 5962-8966401YA | CY7C425-65DMB | 5962-9158503MXA | CY7C433-40LMB | 5962-9071505MZA |
| CY7C408A-15LMB | 5962-89664013A | CY7C425-65KMB | 5962-9158503MZA | CY7C433-50DMB | 5962-9071504MUA |
| CY7C408A-25DMB | 5962-8966402XA | CY7C425-65LMB | 5962-9158503MUA | CY7C433-50KMB | 5962-9071504MYA |
| CY7C408A-25KMB | 5962-8966402YA | CY7C425-80DMB | 5962-9158502MXA | CY7C433-50LMB | 5962-9071504MZA |
| CY7C408A-25LMB | 5962-89664023A | CY7C425-80KMB | 5962-9158502MZA | CY7C433-65DMB | 5962-9071503MUA |
| 7C409A-15 (GEN) | 5962-89661013A | CY7C425-80LMB | 5962-9158502MUA | CY7C433-65KMB | 5962-9071503MYA |
| 7C409A-15 (GEN) | 5962-8966101XA | 7C4271-15 (GEN) | 5962-9763101QXA | CY7C433-65LMB | 5962-9071503MZA |
| 7C409A-15 (GEN) | 5962-8966101YA | CY7C428-20DMB | 5962-8866906XA | CY7C433-80DMB | 5962-9071502MUA |
| 7C409A-25 (GEN) | 5962-89661023A | CY7C428-25DMB | 5962-8866907XA | CY7C433-80KMB | 5962-9071502MYA |
| 7C409A-25 (GEN) | 5962-8966102XA | CY7C428-30DMB | 5962-8866905XA | CY7C433-80LMB | 5962-9071502MZA |
| 7C409A-25 (GEN) | 5962-8966102YA | CY7C428-40DMB | 5962-8866904XA | 7C439/MXA | 5962-9232102MXA |
| CY7C420-25DMB | 5962-8986306XA | CY7C428-50DMB | 5962-8866903XA | 7C439/MYA | 5962-9232102MYA |
| CY7C420-30DMB | 5962-8986305XA | CY7C428-80DMB | 5962-8866901XA | 7C439/MZA | 5962-9232102MZA |
| CY7C420-40DMB | 5962-8986304XA | CY7C429-20DMB | 5962-8866906YA | 7C439-30 (GEN) | 5962-9232103MXA |
| CY7C420-50DMB | 5962-8986303XA | CY7C429-20KMB | 5962-8866906UA | 7C439-30 (GEN) | 5962-9232103MYA |
| CY7C420-65DMB | 5962-8986302XA | CY7C429-20LMB | 5962-8866906ZA | 7C439-30 (GEN) | 5962-9232103MZA |
| CY7C420-80DMB | 5962-8986301XA | CY7C429-25DMB | 5962-8866907YA | 7C439-65 (GEN) | 5962-9232101MXA |
| CY7C421-25DMB | 5962-8986306YA | CY7C429-25KMB | 5962-8866907UA | 7C439-65 (GEN) | 5962-9232101MYA |
| CY7C421-25KMB | 5962-8986306UA | CY7C429-25LMB | 5962-8866907ZA | 7C439-65 (GEN) | 5962-9232101MZA |
| CY7C421-25LMB | 5962-8986306ZA | CY7C429-30DMB | 5962-8866905YA | 7C441-14 (GEN) | 5962-9456706QXA |
| CY7C421-30DMB | 5962-8986305YA | CY7C429-30KMB | 5962-8866905UA | 7C441-14 (GEN) | 5962-9456706QYA |
| CY7C421-30DMB | 5962-8986305YA | CY7C429-30LMB | 5962-8866905ZA | 7C441-20 (GEN) | 5962-9456705QXA |
| CY7C421-30KMB | 5962-8986305UA | CY7C429-40DMB | 5962-8866904YA | 7C441-20 (GEN) | 5962-9456705QYA |
| CY7C421-30LMB | 5962-8986305ZA | CY7C429-40KMB | 5962-8866904UA | 7C441-30 (GEN) | 5962-9456704QXA |
| CY7C421-40DMB | 5962-8986304YA | CY7C429-40LMB | 5962-8866904ZA | 7C441-30 (GEN) | 5962-9456704QYA |
| CY7C421-40KMB | 5962-8986304UA | CY7C429-50DMB | 5962-8866903YA | ISL74422ARHQF | 5962F0152101QXC |
| CY7C421-40LMB | 5962-8986304ZA | CY7C429-50KMB | 5962-8866903UA | ISL74422ARHVF | 5962F0152101VXC |
| CY7C421-50DMB | 5962-8986303YA | CY7C429-50LMB | 5962-8866903ZA | ISL74422ARHVX | 5962F0152101V9A |
| CY7C421-50KMB | 5962-8986303UA | CY7C428-65DMB | 5962-8866902XA | ISL74422BRHQF | 5962F0324801QXC |
| CY7C421-50LMB | 5962-8986303ZA | CY7C429-65DMB | 5962-8866902YA | ISL74422BRHVF | 5962F0324801VXC |
| CY7C421-65DMB | 5962-8986302YA | CY7C429-65KMB | 5962-8866902UA | ISL74422BRHVX | 5962F0324801V9A |
| CY7C421-65LMB | 5962-8986302ZA | CY7C429-65LMB | 5962-8866902ZA | 7C443-14 (GEN) | 5962-9456703QXA |
| CY7C421-80DMB | 5962-8986301YA | CY7C429-80DMB | 5962-8866901YA | 7C443-14 (GEN) | 5962-9456703QYA |
| CY7C421-80KMB | 5962-8986301UA | CY7C429-80KMB | 5962-8866901UA | 7C443-20 (GEN) | 5962-9456702QXA |
| CY7C421-80LMB | 5962-8986301ZA | CY7C429-80LMB | 5962-8866901ZA | 7C443-20 (GEN) | 5962-9456702QYA |
| CY7C424-120DMB | 5962-9158501MYA | CY7C432-120DMB | 5962-9071501MXA | 7C443-30 (GEN) | 5962-9456701QXA |
| CY7C424-30DMB | 5962-9158506MYA | CY7C432-30DMB | 5962-9071507MXA | 7C443-30 (GEN) | 5962-9456701QYA |
| CY7C424-40DMB | 5962-9158505MYA | CY7C432-30DMB | 5962-9071506MXA | 7C451-14 (GEN) | 5962-9317303MXA |
| CY7C424-50DMB | 5962-9158504MYA | CY7C432-40DMB | 5962-9071505MXA | 7C451-14 (GEN) | 5962-9317303MYA |
| CY7C424-65DMB | 5962-9158503MYA | CY7C432-50DMB | 5962-9071504MXA | 7C451-20 (GEN) | 5962-9317302MXA |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART II, Listed By Generic PIN

| Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN |
|---|---|---|---|---|---|
| 7C451-20 (GEN) | 5962-9317302MYA | 7C474-20 (GEN) | 5962-9458803MXA | V750L (GEN) | 5962-88726063A |
| 7C451-30 (GEN) | 5962-9317301MXA | 7C474-20 (GEN) | 5962-9458803MYA | V750L (GEN) | 5962-8872606LA |
| 7C451-30 (GEN) | 5962-9317301MYA | 7C474-25 (GEN) | 5962-9458802MXA | V750L (GEN) | 5962-8872606XA |
| 7C453-14/MXA | 5962-9312403MXA | 7C474-25 (GEN) | 5962-9458802MYA | ATV750-35GM/883 | 5962-9452401MLA |
| 7C453-14/MYA | 5962-9312403MYA | 7C474-40 (GEN) | 5962-9458801MXA | ATV750-35NM/883 | 5962-9452401M3A |
| 7C453-20 (GEN) | 5962-9312402MXA | 7C474-40 (GEN) | 5962-9458801MYA | V750 (GEN) | 5962-8872602XA |
| 7C453-20 (GEN) | 5962-9312402MYA | HCTS75 (GEN) | 5962R9576701V9A | V750-35 (GEN) | 5962-88726023A |
| 7C453-30 (GEN) | 5962-9312401MXA | HCTS75 (GEN) | 5962R9576701VEC | V750-35 (GEN) | 5962-8872602LA |
| 7C453-30 (GEN) | 5962-9312401MYA | HCTS75 (GEN) | 5962R9576701VXC | OM7504SC/883B | 5962-8949005XA |
| CY7C460A-30/MYA | 5962-9167703MYA | UT75*QCR | 5962R96B0214Q*C | V750 (GEN) | 5962-88726013A |
| CY7C460A-30DMB | 5962-9167703MXA | UT75*VCR | 5962R96B0214V*C | V750 (GEN) | 5962-8872601LA |
| CY7C460A-30LMB | 5962-9167703MZA | UT75E/R*QCH | 5962H96B0207Q*A | V750 (GEN) | 5962-8872601XA |
| CY7C460A-50/MYA | 5962-9167702MYA | UT75E/R*VCH | 5962H96B0207V*A | OM7505SC/883B | 5962-8949006XA |
| CY7C460A-50DMB | 5962-9167702MXA | UT75E/R_QCH | 5962H97B0407QXC | OM7506SC/883B | 5962-8949007XA |
| CY7C460A-50LMB | 5962-9167702MZA | UT75E/R_VCH | 5962H97B0407VXC | TL751L05 (GEN) | 5962-9166901Q2A |
| CY7C460A-80/MYA | 5962-9167701MYA | OM7501SC/883B | 5962-8949002XA | TL751L05 (GEN) | 5962-9166901QPA |
| CY7C460A-80DMB | 5962-9167701MXA | ATV750B-10DM/883 | 5962-8872608LA | TL751M05 (GEN) | 5962-9583901Q2A |
| CY7C460A-80LMB | 5962-9167701MZA | ATV750B-10LM/883 | 5962-88726083A | TL751M05 (GEN) | 5962-9583901QPA |
| 7C462-20 (GEN) | 5962-9300803MXA | V750B (GEN) | 5962-8872608YA | TL751L12 (GEN) | 5962-9167001Q2A |
| 7C462-20 (GEN) | 5962-9300803MYA | ATV750B-15DM/883 | 5962-8872609LA | TL751L12 (GEN) | 5962-9167001QPA |
| CY7C462A-20/MUA | 5962-9317703MUA | ATV750B-15LM/883 | 5962-88726093A | TL751M12 (GEN) | 5962-9584001Q2A |
| CY7C462A-20DMB | 5962-9317703MXA | ATV750BL-15DM/883 | 5962-8872611LA | TL751M12 (GEN) | 5962-9584001QPA |
| CY7C462A-20KMB | 5962-9317703MZA | ATV750BL-15LM/883 | 5962-88726113A | 7Q512 (GEN) | 5962D9960601QXA |
| CY7C462A-20LMB | 5962-9317703MYA | V750B (GEN) | 5962-8872609YA | 7Q512 (GEN) | 5962D9960601TXA |
| 7C462-25 (GEN) | 5962-9300802MXA | V750BL3 (GEN) | 5962-8872611YA | 7Q512 (GEN) | 5962D9960602QXA |
| 7C462-25 (GEN) | 5962-9300802MYA | OM7502SC/883B | 5962-8949003XA | 7Q512 (GEN) | 5962D9960602TXA |
| CY7C462A-30/MUA | 5962-9317702MUA | V750 (GEN) | 5962-8872604XA | UT7Q512-UCA | 5962D9960601QUA |
| CY7C462A-30DMB | 5962-9317702MXA | V750 (GEN) | 5962-8872604YA | UT7Q512-UCA | 5962D9960601TUA |
| CY7C462A-30KMB | 5962-9317702MZA | V750-20 (GEN) | 5962-88726043A | UT7Q512-UCA | 5962D9960602QUA |
| CY7C462A-30LMB | 5962-9317702MYA | V750-20 (GEN) | 5962-8872604LA | UT7Q512-UCA | 5962D9960602TUA |
| 7C462-40 (GEN) | 5962-9300801MXA | V750-20 (GEN) | 5962-9452403M3A | UT7Q512-UCC | 5962D9960601QUC |
| 7C462-40 (GEN) | 5962-9300801MYA | V750-20 (GEN) | 5962-9452403MLA | UT7Q512-UCC | 5962D9960601TUC |
| CY7C462A-50/MUA | 5962-9317701MUA | ATV750BL-25DM/883 | 5962-8872612LA | UT7Q512-UCC | 5962D9960602QUC |
| CY7C462A-50DMB | 5962-9317701MXA | ATV750BL-25LM/883 | 5962-88726123A | UT7Q512-UCC | 5962D9960602TUC |
| CY7C462A-50KMB | 5962-9317701MZA | V750 (GEN) | 5962-8872603XA | AD7524MJ | 5962-8770001EA |
| CY7C462A-50LMB | 5962-9317701MYA | V750 (GEN) | 5962-8872603YA | AD7524SE/883B | 5962-87700012A |
| CY7C464A-15DMB | 5962-9315207QXA | V750-25 (GEN) | 5962-88726033A | AD7524TE/883B | 5962-87700022A |
| CY7C464A-15LMB | 5962-9315207QYA | V750-25 (GEN) | 5962-8872603LA | AD7524TQ/883B | 5962-8770002EA |
| 7C464-20 (GEN) | 5962-9315203MXA | V750-25 (GEN) | 5962-9452402M3A | AD7524UE/883B | 5962-87700032A |
| 7C464-20 (GEN) | 5962-9315203MYA | V750-25 (GEN) | 5962-9452402MLA | AD7524UQ/883B | 5962-8770003EA |
| CY7C464A-20DMB | 5962-9315206QXA | V750B (GEN) | 5962-88726103A | MX7524SE/883B | 5962-87700012C |
| CY7C464A-20LMB | 5962-9315206QYA | V750B (GEN) | 5962-8872610LA | MX7524SQ/883B | 5962-8770001EA |
| 7C464-25 (GEN) | 5962-9315202MXA | V750B (GEN) | 5962-8872610YA | MX7524TE/883B | 5962-87700022C |
| 7C464-25 (GEN) | 5962-9315202MYA | V750BL (GEN) | 5962-8872612YA | MX7524TQ/883B | 5962-8770002EA |
| CY7C464A-25DMB | 5962-9315205QXA | V750L (GEN) | 5962-8872607XA | MX7524UE/883B | 5962-87700032C |
| CY7C464A-25LMB | 5962-9315205QYA | V750L (GEN) | 5962-8872607YA | MX7524UQ/883B | 5962-8770003EA |
| 7C464-40 (GEN) | 5962-9315201MXA | V750L-25 (GEN) | 5962-88726073A | AD7528S (GEN) | 5962-87701012A |
| 7C464-40 (GEN) | 5962-9315201MYA | V750L-25 (GEN) | 5962-8872607LA | AD7528SQ/883B | 5962-8770101RA |
| CY7C464A-40DMB | 5962-9315204QXA | V750L-25 (GEN) | 5962-9452405M3A | AD7528TE/883B | 5962-87701022A |
| CY7C464A-40LMB | 5962-9315204QYA | V750L-25 (GEN) | 5962-9452405MLA | AD7528TQ/883B | 5962-8770102RA |
| CY7C466A-15LMB | 5962-9961502QYA | OM7503SC/883B | 5962-8949004XA | AD7528UE/883B | 5962-87701032A |
| CY7C466A-25LMB | 5962-9961501QYA | ATV750L-30GM/883 | 5962-9452404MLA | AD7528UQ/883B | 5962-8770103RA |
| CY7C466A-25LMB | 5962-9961501QYA | ATV750L-30NM/883 | 5962-9452404M3A | MX7528SQ/883B | 5962-8770101RA |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

| Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN |
|---|---|---|---|---|---|
| MX7528TQ/883B | 5962-8770102RA | AD7569TQ/883B | 5962-8962902LA | AD7672TQ05 (GEN) | 5962-8965503LA |
| MX7528UQ/883B | 5962-8770103RA | AD7572SE05/883B | 5962-87591043A | AD7672UQ05 (GEN) | 5962-8965504LA |
| AD7537SQ/883B | 5962-8776301LA | AD7572SQ05/883B | 5962-8759104LA | AD7672TQ10/883B | 5962-8965501LA |
| AD7537UQ/883B | 5962-8776303LA | AD7572TE05/883B | 5962-87591053A | AD7672UQ10/883B | 5962-8965502LA |
| MX7537SE/883B | 5962-87763013C | AD7572TQ05/883B | 5962-8759105LA | 7684AS (GEN) | 5962-89777043A |
| MX7537SQ/883B | 5962-8776301LA | AD7572U (GEN) | 5962-87591063A | 7684AS (GEN) | 5962-8977704XA |
| MX7537TE/883B | 5962-87763023C | AD7572U (GEN) | 5962-8759106LA | 7684AT (GEN) | 5962-89777033A |
| MX7537TQ/883B | 5962-8776302LA | MX7572SE05/883B | 5962-87591043C | 7684AT (GEN) | 5962-8977703XA |
| MX7537UE/883B | 5962-87763033C | MX7572SQ05/883B | 5962-8759104LA | 7684S (GEN) | 5962-89777023A |
| MX7537UQ/883B | 5962-8776303LA | AD7572SQ12/883B | 5962-8759101LA | 7684S (GEN) | 5962-8977702XA |
| AD7541ATE/883B | 5962-89481022A | AD7572T (GEN) | 5962-87591023A | 7684T (GEN) | 5962-89777013A |
| AD7541ATQ/883B | 5962-8948102VA | AD7572T (GEN) | 5962-8759102LA | 7684T (GEN) | 5962-8977701XA |
| MX7541ASE/883B | 5962-89481012C | AD7572U (GEN) | 5962-87591033A | 7690AS (GEN) | 5962-8977706LA |
| MX7541ASQ/883B | 5962-8948101VA | AD7572U (GEN) | 5962-8759103LA | 7690AT (GEN) | 5962-8977705LA |
| MX7541ATE/883B | 5962-89481022C | MX7572SE12/883B | 5962-87591013C | OP-77AJ/883 | 5962-8773802GA |
| MX7541ATQ/883B | 5962-8948102VA | MX7572SQ12/883B | 5962-8759101LA | OP77AJ/QMLV | 5962-8773802VGA |
| PM7541AA (GEN) | 5962-8948104VA | MX7574SE/883B | 5962-89616042C | OP77AL/QMLV | 5962-8773802VHA |
| PM7541AB (GEN) | 5962-89481032A | MX7574SQ/883B | 5962-8961604VA | OP77ARC/QMLV | 5962-8773802V2A |
| PM7541AB (GEN) | 5962-8948103VA | MX7574TE/883B | 5962-89616032C | OP-77AZ/883 | 5962-8773802PA |
| 7545A (GEN) | 5962-87702062A | MX7574TQ/883B | 5962-8961603VA | OP77AZ/QMLV | 5962-8773802VPA |
| 7545A (GEN) | 5962-8770206RA | PM-7574AX | 5962-8961603VA | OP-77BJ/883 | 5962-8773801GA |
| 7545B (GEN) | 5962-87702052A | PM-7574BRC | 5962-89616042A | OP-77BRC/883 | 5962-87738012A |
| 7545B (GEN) | 5962-8770205RA | PM-7574BX | 5962-8961604VA | OP-77BZ/883 | 5962-8773801PA |
| 7545S (GEN) | 5962-8770207RA | AD7575S (GEN) | 5962-87762012A | TL7702AM (GEN) | 5962-88685022A |
| AD7545AUE/883B | 5962-87702042A | AD7575S (GEN) | 5962-8776201VA | TL7702AM (GEN) | 5962-8868502PA |
| AD7545AUQ/883B | 5962-8770204RA | AD7575T (GEN) | 5962-87762022A | TL7702B (GEN) | 5962-88685042A |
| AD7545SQ/883B | 5962-8770201RA | AD7575TQ/883B | 5962-8776202VA | TL7702B (GEN) | 5962-8868504HA |
| AD7545TQ/883B | 5962-8770202RA | AD7579SQ/883B | 5962-8969801LA | TL7702B (GEN) | 5962-8868504PA |
| AD7545UQ/883B | 5962-8770203RA | AD7580 (GEN) | 5962-8969802LA | TL7705AM (GEN) | 5962-88685012A |
| MX7545AUQ/883B | 5962-8770204RA | OM7580ASCM | 5962-0323701MYA | TL7705AM (GEN) | 5962-8868501PA |
| MX7545SE/883B | 5962-87702012C | OM7580ASMM | 5962-0323701MXA | TL7705B (GEN) | 5962-88685032A |
| MX7545SQ/883B | 5962-8770201RA | OM7581SCM | 5962-0323702MZA | TL7705B (GEN) | 5962-8868503HA |
| MX7545TE/883B | 5962-87702022C | OM7581SMM | 5962-0323702MXA | TL7705B (GEN) | 5962-8868503PA |
| MX7545TQ/883B | 5962-8770202RA | OM7585ANMM | 5962-0323703MMA | TL7705B (GEN) | 5962-88685052A |
| MX7545UE/883B | 5962-87702032C | OM7585ASRM | 5962-0323703MUA | TL7705B (GEN) | 5962-8868505HA |
| MX7545UQ/883B | 5962-8770203RA | OM7585ASTM | 5962-0323703MTA | TL7705B (GEN) | 5962-8868505PA |
| AD7547TE/883B | 5962-89657023A | LM759 (GEN) | 5962-9086201MGA | TLC7705MFKB | 5962-9751301Q2A |
| AD7547TQ/883B | 5962-8965702LA | LM760 (GEN) | 5962-8754501CA | TLC7705MJGB | 5962-9751301QPA |
| AD7547UQ/883B | 5962-8965703LA | LM760 (GEN) | 5962-8754501GA | TLC7705MUB | 5962-9751301QHA |
| MX7547SQ/883B | 5962-8965701LA | 7636AS (GEN) | 5962-9174002MRA | LM7709AH/883 | 7800701GA |
| MX7547TQ/883B | 5962-8965702LA | 7636AT (GEN) | 5962-9174001MRA | LM7709AJ/883 | 7800701CA |
| MX7547UQ/883B | 5962-8965703LA | 7645A (GEN) | 5962-88778012A | LM7709AJ8/883 | 7800701PA |
| 75C48S20 (GEN) | 5962-88743013A | 7645A (GEN) | 5962-8877801RA | LM7709AW/883 | 7800701HA |
| 75C48S20 (GEN) | 5962-8874301XA | 7645B (GEN) | 5962-88778022A | AD7710SQ/QML | 5962-9676201QLA |
| 75C48SC30 (GEN) | 5962-88743023A | 7645B (GEN) | 5962-8877802RA | SPT7710AM (GEN) | 5962-9477101MXB |
| 75C48SC30 (GEN) | 5962-8874302XA | AD766SD/883B | 5962-9201601MEA | SPT7710AM (GEN) | 5962-9477101MYC |
| AD7549SQ/883B | 5962-8876501RA | ICL7660AMJA/883B | 5962-3870702MPA | SPT7710BM (GEN) | 5962-9477102MXB |
| AD7549TQ/883B | 5962-8876502RA | ICL7660AMTV/883B | 5962-3870702MGC | SPT7710BM (GEN) | 5962-9477102MYC |
| 7555 (GEN) | 5962-8950303GC | ICL7667MJA/883B | 5962-8766001PA | SPT7725AM (GEN) | 5962-9477103MXB |
| 7555 (GEN) | 5962-8950303PA | ICL7667MJA/883B | 5962-8766001PA | SPT7725AM (GEN) | 5962-9477103MYC |
| 7556 (GEN) | 5962-8950304CA | ICL7667MTV/883B | 5962-8766001GC | SPT7725BM (GEN) | 5962-9477104MXB |
| AD7569S (GEN) | 5962-8962901LA | ICL7667MTV/883B | 5962-8766001GC | SPT7725BM (GEN) | 5962-9477104MYC |
| AD7569SE/883B | 5962-89629013A | AD767SD/883B | 5962-8961701LA | TLC7733MFKB | 5962-9750901Q2A |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

| Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN |
|---|---|---|---|---|---|
| TLC7733MJGB | 5962-9750901QPA | IP7812AG-DESC | 5962-8777601TA | SG7815AT/883B | 5962-8855301XA |
| HI1-774T/883 | 5962-9958201QXC | IP7812AIG-DESC | 5962-8777601UA | SG7818AIG/883B | 5962-8991501UA |
| OM7764ASC | 5962-0323801MYA | IP7812AK-DESC | 5962-8777601YA | SG7818AK/883B | 5962-8991501YA |
| OM7764ASM | 5962-0323801MXA | IP7812AR-DESC | 5962-8777601ZA | SG7818AL/883B | 5962-89915012A |
| TL7770-12 (GEN) | 5962-9093202M2A | IP78M12AH-DESC | 5962-8777601XA | SG7818AR/883B | 5962-8991501ZA |
| TL7770-12 (GEN) | 5962-9093202MEA | IP78M12AJ-DESC | 5962-8777601PA | SG7818AT/883B | 5962-8991501XA |
| TL7770-15 (GEN) | 5962-9093203M2A | IP78M12H-DESC | 5962-8777602XA | AD7820TE/883B | 5962-88650022A |
| TL7770-15 (GEN) | 5962-9093203MEA | IP78M12J-DESC | 5962-8777602PA | AD7820TQ/883B | 5962-8865002RA |
| TL7770-5/M2A | 5962-9093201M2A | OM7812AH/883B | 5962-8777601TA | AD7820UE/883B | 5962-88650012A |
| TL7770-5/MEA | 5962-9093201MEA | OM7812AIH/883B | 5962-8777601UA | AD7820UQ/883B | 5962-8865001RA |
| AD780S (GEN) | 5962-9463601MPA | SDP7812A2MD | 5962-87776012A | DS78C20J/883 | 5962-9321101MCA |
| 7805A (GEN) | 5962-87782034A | SDP7812ANHD | 5962-9961301HNA | MX7820TE/883B | 5962-88650022C |
| 78M05 (GEN) | 5962-87782022A | SDP7812ANHG | 5962-9961301HNC | MX7820TQ/883B | 5962-8865002RA |
| IP7805AG-DESC | 5962-8778201TA | SDP7812ANMD | 5962-8777601NA | MX7820UE/883B | 5962-88650012C |
| IP7805AIG-DESC | 5962-8778201UA | SDP7812ATHD | 5962-9961301HTA | MX7820UQ/883B | 5962-8865001RA |
| IP7805AK-DESC | 5962-8778201YA | SDP7812ATHG | 5962-9961301HTC | SG7820AIG/883B | 5962-9152301MUA |
| IP7805AR-DESC | 5962-8778201ZA | SDP7812ATMD | 5962-8777601TA | SG7820AK/883B | 5962-9152301MYA |
| IP78M05AH-DESC | 5962-8778201XA | SDP7812AUHD | 5962-9961301HUA | SG7820AR/883B | 5962-9152301MZA |
| IP78M05H-DESC | 5962-8778202XA | SDP7812AUHG | 5962-9961301HUC | SG7820AT/883B | 5962-9152301MXA |
| IP78M05J-DESC | 5962-8778202PA | SDP7812AUMD | 5962-8777601UA | AD7821TE/883B | 5962-89518012A |
| OM7805AH/883B | 5962-8778201TA | SDP7812AZHD | 5962-9961301HZA | AD7821TQ/883B | 5962-8951801RA |
| OM7805AIH/883B | 5962-8778201UA | SDP7812AZHG | 5962-9961301HZC | AD7824TQ/883B | 5962-8876401LA |
| OM7805AK/883B | 5962-8778201YA | SDP7812AZMD | 5962-8777601ZA | AD7824UQ/883B | 5962-8876402LA |
| OM7805AL/883B | 5962-87782012A | SG7812AIG/883B | 5962-8777601UA | MX7824TQ/883B | 5962-8876401LA |
| OM7805N5M | 5962-87782016A | SG7812AK/883B | 5962-8777601YA | MX7824UQ/883B | 5962-8876402LA |
| OM7805NMM/883B | 5962-8778201NA | SG7812AL/883B | 5962-87776012A | SG7824AK/883B | 5962-8855401YA |
| OM7805SRM | 5962-87782015A | SG7812AR/883B | 5962-8777601ZA | SG7824AR/883B | 5962-8855401ZA |
| SDP7805A2MD | 5962-87782012A | SG7812AT/883B | 5962-8777601XA | SG7824AT/883B | 5962-8855401XA |
| SDP7805ANHD | 5962-9864301HNA | DS78C120J/883 | 5962-8963001EA | AD7828TQ/883B | 5962-8876403XA |
| SDP7805ANHG | 5962-9864301HNC | 7815A (GEN) | 5962-88553014A | AD7828UE/883B | 5962-88764043A |
| SDP7805ANMD | 5962-8778201NA | 7815A (GEN) | 5962F8855301UA | AD7828UQ/883B | 5962-8876404XA |
| SDP7805ATHD | 5962-9864301HTA | IP7815AG-DESC | 5962-8855301TA | MX7828TQ/883B | 5962-8876403XA |
| SDP7805ATHG | 5962-9864301HTC | IP7815AIG-DESC | 5962-8855301UA | MX7828UQ/883B | 5962-8876404XA |
| SDP7805ATMD | 5962-8778201TA | IP7815AK-DESC | 5962-8855301YA | MM78C29J/883 | 5962-9321001MCA |
| SDP7805AUHD | 5962-9864301HUA | IP7815AR-DESC | 5962-8855301ZA | MM78C29J/883 | 5962-9321001MCA |
| SDP7805AUHG | 5962-9864301HUC | IP78M15AH-DESC | 5962-8855301XA | 78C30 (GEN) | 5962-8988201CA |
| SDP7805AUMD | 5962-8778201UA | SDP7815A2MD | 5962-88553012A | 7831 (GEN) | 80041012A |
| SDP7805AZHD | 5962-9864301HZA | SDP7815ANHD | 5962-9864001HNA | DS7831J/883B | 8004101EA |
| SDP7805AZHG | 5962-9864301HZC | SDP7815ANHG | 5962-9864001HNC | DS7831W/883B | 8004101FA |
| SDP7805AZMD | 5962-8778201ZA | SDP7815ANMD | 5962-8855301NA | DS7832E/883B | 80041022A |
| SG7805AIG/883B | 5962-8778201UA | SDP7815ATHD | 5962-9864001HTA | DS7832J/883B | 8004102EA |
| SG7805AK/883B | 5962-8778201YA | SDP7815ATHG | 5962-9864001HTC | DS7832W/883B | 8004102FA |
| SG7805AL/883B | 5962-87782012A | SDP7815ATMD | 5962-8855301TA | AD7837SQ/883B | 5962-9451801MLA |
| SG7805AR/883B | 5962-8778201ZA | SDP7815AUHD | 5962-9864001HUA | UA78S40DMQB | 5962-8876101EA |
| SG7805AT/883B | 5962-8778201XA | SDP7815AUHG | 5962-9864001HUC | AD7846SE/883B | 5962-89697013A |
| SG7806AK/883B | 5962-8962601YA | SDP7815AUMD | 5962-8855301UA | AD7846SQ/883B | 5962-8969701XA |
| SG7806AR/883B | 5962-8962601ZA | SDP7815AZHD | 5962-9864001HZA | AD7847SQ/883B | 5962-9451802MLA |
| SG7806AT/883B | 5962-8962601XA | SDP7815AZHG | 5962-9864001HZC | HCPL-7851 | 5962-9755701HPC |
| SG7808AIG/883B | 5962-8962801UA | SDP7815AZMD | 5962-8855301ZA | HCPL-7851#100 | 5962-9755701HYA |
| SG7808AK/883B | 5962-8962801YA | SG7815AIG/883B | 5962-8855301UA | HCPL-7851#100 | 5962-9755701HYC |
| SG7808AR/883B | 5962-8962801ZA | SG7815AK/883B | 5962-8855301YA | HCPL-7851#200 | 5962-9755701HPA |
| SG7808AT/883B | 5962-8962801XA | SG7815AL/883B | 5962-88553012A | HCPL-7851#300 | 5962-9755701HXA |
| 78M12 (GEN) | 5962-87776022A | SG7815AR/883B | 5962-8855301ZA | AD7870TE/883B | 5962-9063201M3A |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

| Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN |
|---|---|---|---|---|---|
| AD7870TQ/883B | 5962-9063201MLA | SG7905AR/883B | 5962-8874601ZA | SDP7912AUMD | 5962-8874701UA |
| 7870-01 | 5962-9157901HZA | SG7905AT/883B | 5962-8874601XA | SDP7912AZHD | 5962-9961401HZA |
| 7870-02 | 5962-9157902HZA | T7905EFWMQ | 5962-02A0901QXC | SDP7912AZHG | 5962-9961401HZC |
| 7870-03 | 5962-9157903HZA | T7905EFWMV | 5962-02A0901VXC | SDP7912AZMD | 5962-8874701ZA |
| AD7874SE/883B | 5962-9152101M3A | T7906EKTMQ | 5962-02A0201QXC | SG7912AIG/883B | 5962-8874701UA |
| AD7874SQ/883B | 5962-9152101MXA | T7906EKTSV | 5962-02A0201VXC | SG7912AK/883B | 5962-8874701YA |
| AD7876TQ/883B | 5962-9317901MLA | AT7908EJLMQ | 5962-03A0601QXC | SG7912AL/883B | 5962-88747012A |
| ACT7881PN | 5962-9562701NXD | AT7908EJLSV | 5962-03A0601VXC | SG7912AR/883B | 5962-8874701ZA |
| AD7890SQ-10/QML | 5962-9561501MLA | SG7908AG/883B | 5962-8987001TA | SG7912AT/883B | 5962-8874701XA |
| 7890S-10 (GEN) | 5962-9561501MJA | SG7908AIG/883B | 5962-8987001UA | IP7915AG-DESC | 5962-8874801TA |
| AD7892S (GEN) | 5962-9684601QJA | SG7908AK/883B | 5962-8987001YA | IP7915AIG-DESC | 5962-8874801UA |
| AD7892SQ-1/QML | 5962-9684601QLA | SG7908AR/883B | 5962-8987001ZA | IP7915AK-DESC | 5962-8874801YA |
| 7892-01 | 5962-9159901HZA | SG7908AT/883B | 5962-8987001XA | IP7915AR-DESC | 5962-8874801ZA |
| 7892-02 | 5962-9159902HZA | 7C9101-35 (GEN) | 5962-8951702UA | IP79M15AH-DESC | 5962-8874801XA |
| 7892-03 | 5962-9159903HZA | 7C9101-35 (GEN) | 5962-8951702XA | OM7915AH/883B | 5962-8874801TA |
| AD7893SQ-10/883B | 5962-9475501MPA | 7C9101-35 (GEN) | 5962-8951702YA | OM7915AIH/883B | 5962-8874801UA |
| AD7893SQ-2/883B | 5962-9475502MPA | 7C9101-35 (GEN) | 5962-8951702ZA | SDP7915A2MD | 5962-88748012A |
| AD790S (GEN) | 5962-9150501MPA | 7C9101-45 (GEN) | 5962-8951701TA | SDP7915ANHD | 5962-9864101HNA |
| 7C901-27 (GEN) | 5962-8853502QA | 7C9101-45 (GEN) | 5962-8951701UA | SDP7915ANHG | 5962-9864101HNC |
| 7C901-27 (GEN) | 5962-8853502XA | 7C9101-45 (GEN) | 5962-8951701VA | SDP7915ATHD | 5962-9864101HTA |
| 7C901-27 (GEN) | 5962-8853502YA | 7C9101-45 (GEN) | 5962-8951701XA | SDP7915ATHG | 5962-9864101HTC |
| 7C901-32 (GEN) | 5962-8853501QA | 7C9101-45 (GEN) | 5962-8951701YA | SDP7915ATMD | 5962-8874801TA |
| 7C901-32 (GEN) | 5962-8853501XA | 7C9101-45 (GEN) | 5962-8951701ZA | SDP7915AUHD | 5962-9864101HUA |
| 7C901-32 (GEN) | 5962-8853501YA | 7C910-46 (GEN) | 5962-8770805QA | SDP7915AUHG | 5962-9864101HUC |
| 79M05 (GEN) | 77040012A | 7C910-46 (GEN) | 5962-8770805UA | SDP7915AUMD | 5962-8874801UA |
| 79M05 (GEN) | 7704001HA | 7C910-51 (GEN) | 5962-8770804QA | SDP7915AZHD | 5962-9864101HZA |
| 79M05 (GEN) | 7704001PA | 7C910-51 (GEN) | 5962-8770804UA | SDP7915AZHG | 5962-9864101HZC |
| IP7905AK-DESC | 5962-8874601YA | 7C9116-40 (GEN) | 5962-8861204UA | SDP7915AZMD | 5962-8874801ZA |
| IP7905AR-DESC | 5962-8874601ZA | 7C9116-40 (GEN) | 5962-8861204XA | SG7915AIG/883B | 5962-8874801UA |
| IP7905K-DESC | 7704001YA | 7C9116-40 (GEN) | 5962-8861204YA | SG7915AK/883B | 5962-8874801YA |
| IP79M05H-DESC | 7704001XA | 7C9116-65 (GEN) | 5962-8861203UA | SG7915AL/883B | 5962-88748012A |
| OM7905AH/883B | 5962-8874601TA | 7C9116-65 (GEN) | 5962-8861203XA | SG7915AP/883B | 5962-8874801ZA |
| OM7905AIH/883B | 5962-8874601UA | 7C9116-65 (GEN) | 5962-8861203YA | SG7915AT/883B | 5962-8874801XA |
| OM7905N5M/883B | 5962-88746015A | 7C9116-75 (GEN) | 5962-8861202UA | 7B923 (GEN) | 5962-9689501Q3A |
| OM7905NK/883B | 5962-8874601YA | 7C9116-75 (GEN) | 5962-8861202XA | IP7924 (GEN) | 5962-8874901XA |
| OM7905NM/883B | 5962-8874601NA | 7C9116-75 (GEN) | 5962-8861202YA | IP7924 (GEN) | 5962-8874901YA |
| OM7905SRM/883B | 5962-88746014A | 7C9116-99 (GEN) | 5962-8861201UA | IP7924 (GEN) | 5962-8874901ZA |
| SDP7905A2MD | 5962-88746012A | 7C9116-99 (GEN) | 5962-8861201XA | 79R3081E-25 (GEN) | 5962-9455001MXC |
| SDP7905ANHD | 5962-9864201HNA | 7C9116-99 (GEN) | 5962-8861201YA | 7B933 (GEN) | 5962-9689601Q3A |
| SDP7905ANHG | 5962-9864201HNC | IP7912AG-DESC | 5962-8874701TA | AS7968 | 5962-9052701M3A |
| SDP7905ANMD | 5962-8874601NA | IP7912AIG-DESC | 5962-8874701UA | AS796802BCA | 5962-9052701QXA |
| SDP7905ATHD | 5962-9864201HTA | IP7912AK-DESC | 5962-8874701YA | 7968-125V (GEN) | 5962-9052701MXA |
| SDP7905ATHG | 5962-9864201HTC | IP7912AR-DESC | 5962-8874701ZA | AS796902BCA | 5962-9052801QXA |
| SDP7905ATMD | 5962-8874601TA | IP79M12AH-DESC | 5962-8874701XA | 7969-125V (GEN) | 5962-9052801MXA |
| SDP7905AUHD | 5962-9864201HUA | OM7912AH/883B | 5962-8874701TA | AS7969EC28/883C | 5962-9052801M3A |
| SDP7905AUHG | 5962-9864201HUC | SDP7912A2MD | 5962-88747012A | AS7969ECJ28/883C | 5962-9052801Q7A |
| SDP7905AUMD | 5962-8874601UA | SDP7912ANHD | 5962-9961401HNA | AD797S (GEN) | 5962-9313301MPA |
| SDP7905AZHD | 5962-9864201HZA | SDP7912ANHG | 5962-9961401HNC | CY7B991-7LMB | 5962-9452201MXA |
| SDP7905AZHG | 5962-9864201HZC | SDP7912ATHD | 5962-9961401HTA | CY7B992-7LMB | 5962-9311201MXA |
| SDP7905AZMD | 5962-8874601ZA | SDP7912ATHG | 5962-9961401HTC | HDAS-8/883 | 5962-8851403XA |
| SG7905AIG/883B | 5962-8874601UA | SDP7912ATMD | 5962-8874701TA | HDAS-8/883 | 5962-8851403XC |
| SG7905AK/883B | 5962-8874601YA | SDP7912AUHD | 5962-9961401HUA | NSC800 (GEN) | 8301301QA |
| SG7905AL/883B | 5962-88746012A | SDP7912AUHG | 5962-9961401HUC | NSC800 (GEN) | 8301301ZA |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

| Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN |
|---|---|---|---|---|---|
| AD8001SL/QMLR | 5962R9459301VHA | UT80CRH196KDS-VWD | 5962F0252302V9A | TS80C31BH/BMA | 5962-8506401MMA |
| AD8001SL/QMLV | 5962-9459301VHA | UT80CRH196KDS-WCA | 5962-0252301QXA | TS80C31BH/BQA | 5962-8506401MQA |
| AD8001SQ | 5962-9459301MPA | UT80CRH196KDS-WCA | 5962F0252301QXA | TS80C31BH/BUA | 5962-8506401MXA |
| AD8001SQ/QMLR | 5962R9459301VPA | UT80CRH196KDS-WCA | 5962F0252301VXA | 80C31BH-16 | 5962-8506403MMA |
| AD8001SQ/QMLV | 5962-9459301VPA | UT80CRH196KDS-WC | 5962-0252301QXC | 80C31BH-16 | 5962-8506403MQA |
| Z8001ACPU (GEN) | 8000303ZA | UT80CRH196KDS-WC | 5962F0252301QXC | 80C31BH-16 | 5962-8506403MXA |
| Z8001B (GEN) | 8000304ZA | UT80CRH196KDS-WC | 5962F0252301VXC | 80C31BH16 (GEN) | 8506403QA |
| Z8001CPU (GEN) | 8000301ZA | UT80CRH196KDS-WW | 5962-0252302QXA | 80C31BH16 (GEN) | 8506403XA |
| Z0800206CMB | 8000306QA | UT80CRH196KDS-WW | 5962F0252302QXA | 80C31BH-16 (GEN) | 5962-8506403MYA |
| Z0800206LMB | 8000306YA | UT80CRH196KDS-WW | 5962F0252302VXA | 80C31BH-16 (GEN) | 5962-8506403NUA |
| NSC800 (GEN) | 8301302QA | UT80CRH196KDS-WW | 5962-0252302QXC | 80C31BH-16 (GEN) | 5962-8506403NVA |
| NSC800 (GEN) | 8301302ZA | UT80CRH196KDS-WW | 5962F0252302QXC | 80C31BH-16 (GEN) | 5962-8506407NUA |
| MSK801B | 5962-9157401HXA | UT80CRH196KDS-WW | 5962F0252302VXC | 80C31BH-16 (GEN) | 5962-8506407NVA |
| MSK801B | 5962-9157401HXC | UT80CRH196KD-WCA | 5962R9858301QXA | 80C31BH-16 (GEN) | 8506403YA |
| Z8018008 (GEN) | 5962-9453701MXA | UT80CRH196KD-WCA | 5962R9858301VXA | TS80C31BH-16 | 5962-8506403MMA |
| 80C186XL10 (GEN) | 5962-8850106ZA | UT80CRH196KD-WCC | 5962R9858301QXC | TS80C31BH-16 | 5962-8506403MQA |
| MG80C186-10/BZA | 5962-8850101ZA | UT80CRH196KD-WCC | 5962R9858301VXC | TS80C31BH-16 | 5962-8506403MXA |
| MG80C186-10/BZC | 5962-8850101ZC | UT80CRH196KD-WWA | 5962R9858302QXA | MPD8032 (GEN) | 5962-9553001MEA |
| MQ80C186-10/BYA | 5962-8850101YA | UT80CRH196KD-WWA | 5962R9858302VXA | MPD8032 (GEN) | 5962-9553002MEA |
| MQ80C186-10/BYC | 5962-8850101YC | UT80CRH196KD-WWC | 5962R9858302QXC | MC80C32E-30MQ | 5962-0051801QQC |
| 80C186XL12 (GEN) | 5962-8850105ZA | UT80CRH196KD-WWC | 5962R9858302VXC | MJ80C32E-30MQ | 5962-0051801QXC |
| MG80C186-12/BZA | 5962-8850102ZA | MQ80C196KB-12/BYA | 5962-8998202YA | SC80C32E-30SV | 5962-0051801VQC |
| MG80C186-12/BZC | 5962-8850102ZC | MQ80C196KB-12/BYC | 5962-8998202YC | SJ80C32E-30SV | 5962-0051801VXC |
| MQ80C186-12/BYA | 5962-8850102YA | MQ80C196KB-12/BZA | 5962-8998202ZA | 8035AHL (GEN) | 5962-8856801QA |
| MQ80C186-12/BYC | 5962-8850102YC | MQ80C196KB-12/BZC | 5962-8998202ZC | AD8036SQ | 5962-9559701MPA |
| 80C186 (GEN) | 5962-9310902MXA | 8028610 (GEN) | 5962-8514803XA | Z8036ACMB | 8551701QA |
| 80C186 (GEN) | 5962-9310903MXA | 8028610 (GEN) | 5962-8514803YA | Z8036ALMB | 8551701YA |
| 80C186XL16 (GEN) | 5962-8850104ZA | 80C286-10 (GEN) | 5962-9067801MXC | Z8036CMB | 8551702QA |
| 80C186XL20 (GEN) | 5962-8850103ZA | 80C286-10 (GEN) | 5962-9067801MYA | Z8036LMB | 8551702YA |
| MG80186-6/B | 8501002ZA | 80C286-12 (GEN) | 5962-9067802MXC | 8038 (GEN) | 5962-8877201CA |
| MQ80186-6/B | 8501002YA | 802866 (GEN) | 5962-8514802XA | 80386-12 (GEN) | 5962-8766802MXA |
| 80C186 (GEN) | 5962-9310901MXA | 802866 (GEN) | 5962-8514802YA | 80386-12 (GEN) | 5962-8766802MYA |
| MG80186-8/B | 8501001ZA | 802868 (GEN) | 5962-8514801XA | 80386-12 (GEN) | 5962-8766802XA |
| MQ80186-8/B | 8501001YA | 802868 (GEN) | 5962-8514801YA | 80386-12 (GEN) | 5962-8766802YA |
| 80C18710 (GEN) | 5962-8944901QA | 8028710 (GEN) | 5962-8513301QA | 8038616 (GEN) | 5962-8766801MXA |
| 80C18710 (GEN) | 5962-8944901XA | 80C28710 (GEN) | 5962-9065601MQA | 8038616 (GEN) | 5962-8766801MYA |
| 80C18712 (GEN) | 5962-8944902QA | 802875 (GEN) | 5962-8513303QA | 8038616 (GEN) | 5962-8766801XA |
| 80C18712 (GEN) | 5962-8944902XA | 802878 (GEN) | 5962-8513302QA | 8038616 (GEN) | 5962-8766801YA |
| 80C18716 (GEN) | 5962-8944903QA | Z8030 (GEN) | 5962-8551802QA | 80386SX (GEN) | 5962-9453301MXA |
| 80C18716 (GEN) | 5962-8944903XA | Z8030 (GEN) | 5962-8551802YA | 8038620 (GEN) | 5962-8766803MXA |
| 80C196KB (GEN) | 5962-8998201YA | Z8030A (GEN) | 5962-8551801QA | 8038620 (GEN) | 5962-8766803MYA |
| 80C196KB (GEN) | 5962-8998201ZA | Z8030A (GEN) | 5962-8551801YA | 8038620 (GEN) | 5962-8766803XA |
| UT80C196KD-WCA | 5962-9858301QXA | 80C31BH (GEN) | 5962-8506401MYA | 8038620 (GEN) | 5962-8766803YA |
| UT80C196KD-WCC | 5962-9858301QXC | 80C31BH (GEN) | 5962-8506401NUA | 80386-20 (GEN) | 5962-8766803QXA |
| UT80C196KD-WWA | 5962-9858302QXA | 80C31BH (GEN) | 5962-8506401NVA | 80386-20 (GEN) | 5962-8766803QYA |
| UT80C196KD-WWC | 5962-9858302QXC | 80C31BH (GEN) | 5962-8506405NUA | 80386SX (GEN) | 5962-9453302MXA |
| UT80CRH196KD_QDIE | 5962R9858301Q9A | 80C31BH (GEN) | 5962-8506405NVA | 8038625 (GEN) | 5962-8766804MXA |
| UT80CRH196KD_QWDI | 5962R9858302Q9A | 80C31BH (GEN) | 8506401QA | 8038625 (GEN) | 5962-8766804MYA |
| UT80CRH196KD_VDIE | 5962R9858301V9A | 80C31BH (GEN) | 8506401XA | 8038625 (GEN) | 5962-8766804XA |
| UT80CRH196KD_VWDI | 5962R9858302V9A | 80C31BH (GEN) | 8506401YA | 8038625 (GEN) | 5962-8766804YA |
| UT80CRH196KDS-QCD | 5962F0252301Q9A | 80C31BH/BMA | 5962-8506401MMA | 80386-25 (GEN) | 5962-8766804QXA |
| UT80CRH196KDS-QW | 5962F0252302Q9A | 80C31BH/BQA | 5962-8506401MQA | 80386-25 (GEN) | 5962-8766804QYA |
| UT80CRH196KDS-VCD | 5962F0252301V9A | 80C31BH/BUA | 5962-8506401MXA | 80386EX (GEN) | 5962-9557001QXA |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

| Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN |
|---|---|---|---|---|---|
| 80386EX (GEN) | 5962-9557001QYA | 8050260 (GEN) | 5962-9457806NXC | 80C86/7 (GEN) | 5962-9672801VQC |
| 80386EX (GEN) | 5962-9557002NXA | 8050266 (GEN) | 5962-9457807QXC | 8087 (GEN) | 5962-8854702QA |
| 80386EX (GEN) | 5962-9557002NYA | 8050266 (GEN) | 5962-9457808NXC | 80872 (GEN) | 5962-8854701QA |
| 8038716 (GEN) | 5962-8953401MXA | 8050266 (GEN) | 5962-9457809NXC | 8088 (GEN) | 5962-8768501QA |
| 8038716 (GEN) | 5962-8953401MYA | 80C51 (GEN) | 5962-8506402MQA | 80C88 (GEN) | 5962-8601601XA |
| 8038720 (GEN) | 5962-8953402MXA | 80C51BH (GEN) | 5962-8506402MMA | MD80C88/883 | 5962-8601601QA |
| 8038720 (GEN) | 5962-8953402MYA | 80C51BH (GEN) | 5962-8506402MXA | 80960MX (GEN) | 5962-9556901QYA |
| 80387-20 (GEN) | 5962-8953402QYA | 80C51BH (GEN) | 5962-8506402MYA | 80960MC16 (GEN) | 5962-9094601MXA |
| 8038725 (GEN) | 5962-8953403MXA | 80C51BH (GEN) | 5962-8506402NUA | 80960MC16 (GEN) | 5962-9094601MYA |
| 8038725 (GEN) | 5962-8953403MYA | 80C51BH (GEN) | 5962-8506402NVA | 80960XA16 (GEN) | 5962-9094604MXA |
| 80387-25 (GEN) | 5962-8953403QYA | 80C51BH (GEN) | 5962-8506406NUA | 80960XA16 (GEN) | 5962-9094604MYA |
| AD8041SQ | 5962-9683901MPA | 80C51BH (GEN) | 5962-8506406NVA | 80960MC20 (GEN) | 5962-9094602MXA |
| 80C451 (GEN) | 5962-8972601MUA | 80C51BH (GEN) | 8506402QA | 80960MC20 (GEN) | 5962-9094602MYA |
| 80C451 (GEN) | 5962-8972601MXA | 80C51BH (GEN) | 8506402XA | 80960XA20 (GEN) | 5962-9094605MXA |
| 80C451 (GEN) | 5962-8972601UA | 80C51BH (GEN) | 8506402YA | 80960XA20 (GEN) | 5962-9094605MYA |
| 80C451 (GEN) | 5962-8972601XA | 80C51FB (GEN) | 5962-9097601MTA | 80960MC25 (GEN) | 5962-9094603MXA |
| 80C451/BMA | 5962-8972601MMA | 80C51FB (GEN) | 5962-9097601MUA | 80960MC25 (GEN) | 5962-9094603MYA |
| 8048AH (GEN) | 5962-8856802QA | 80C51FB (GEN) | 5962-9097601MXA | 80960XA25 (GEN) | 5962-9094606MXA |
| 80486DX (GEN) | 5962-9583701QXA | 80C51FB (GEN) | 5962-9097601MZA | 80960XA25 (GEN) | 5962-9094606MYA |
| 80486DX (GEN) | 5962-9583701QYA | 80C51 (GEN) | 5962-8506404MQA | MG8097/B | 8506301ZA |
| 80486DX (GEN) | 5962-9583702QXA | 80C51BH16 (GEN) | 8506404QA | MG8097BH/BZA | 5962-8959601ZA |
| 80486DX (GEN) | 5962-9583702QYA | 80C51BH16 (GEN) | 8506404XA | MG8097BH/BZC | 5962-8959601ZC |
| 80486DX (GEN) | 5962-9583703NXA | 80C51BH-16 (GEN) | 5962-8506404MMA | MQ8097/B | 8506301YA |
| 80486DX (GEN) | 5962-9583703NYA | 80C51BH-16 (GEN) | 5962-8506404MXA | MQ8097BH/BYA | 5962-8959601YA |
| 80486DX (GEN) | 5962-9583704NXA | 80C51BH-16 (GEN) | 5962-8506404MYA | MQ8097BH/BYC | 5962-8959601YC |
| 80486DX (GEN) | 5962-9583704NYA | 80C51BH-16 (GEN) | 5962-8506404NUA | AD810SQ/883B | 5962-9313201MPA |
| 80486DX (GEN) | 5962-9583705NXA | 80C51BH-16 (GEN) | 5962-8506404NVA | UT8Q1024-UWA | 5962L0153201QYA |
| 80486DX (GEN) | 5962-9583705NYA | 80C51BH-16 (GEN) | 5962-8506408NUA | UT8Q1024-UWA | 5962L0153201TYA |
| 80486DX (GEN) | 5962-9583706NXA | 80C51BH-16 (GEN) | 5962-8506408NVA | UT8Q1024-UWC | 5962L0153201QYC |
| 80486DX (GEN) | 5962-9583706NYA | 80C51BH-16 (GEN) | 8506404YA | UT8Q1024-UWC | 5962L0153201TYC |
| 80486 (GEN) | 5962-9310501MXA | 80C51FB (GEN) | 5962-9097602MTA | AD811SE/883B | 5962-9313101M2A |
| 80486 (GEN) | 5962-9310501MYA | 80C51FB (GEN) | 5962-9097602MUA | AD811SQ/883B | 5962-9313101MPA |
| 80486 (GEN) | 5962-9310505QXA | 80C51FB (GEN) | 5962-9097602MXA | 81188 (GEN) | 5962-9473301MXC |
| 80486 (GEN) | 5962-9310503QXA | 80C51FB (GEN) | 5962-9097602MZA | 81256LP35 (GEN) | 5962-8854401YA |
| 80486 (GEN) | 5962-9310503QYA | HS-80C85 (GEN) | 5962R9582401VQC | EDI81256C-35 (GEN) | 5962-8872501YA |
| 80486 (GEN) | 5962-9310507QXA | HS-80C85 (GEN) | 5962R9582401VXC | 81256LP45 (GEN) | 5962-8854402YA |
| 80486 (GEN) | 5962-9310507QYA | MD8085AH/B | 7901001QA | EDI81256C-45 (GEN) | 5962-8872502YA |
| 80486 (GEN) | 5962-9310509NXA | HS-80C85 (GEN) | 5962R9582401QXC | 81256LP55 (GEN) | 5962-8854403YA |
| 80486 (GEN) | 5962-9310509NYA | HS-80C85RH (GEN) | 5962R9582401QQC | EDI81256C-55 (GEN) | 5962-8872503YA |
| 80486 (GEN) | 5962-9310504QXA | 80C86 (GEN) | 8405201QA | 81256P70 (GEN) | 5962-8854404YA |
| 80486 (GEN) | 5962-9310504QYA | 80C86 (GEN) | 8405201XA | EDI81256C-70 (GEN) | 5962-8872504YA |
| 80486 (GEN) | 5962-9310508QXA | HS1-80C86RH-8 | 5962R9572201QQC | UT8R128K32-15WCA | 5962F0323601QXA |
| 80486 (GEN) | 5962-9310508QYA | HS-80C86 (GEN) | 5962R9572201VQC | UT8R128K32-15WCA | 5962F0323601VXA |
| 80486 (GEN) | 5962-9310510NXA | HS9-80C86RH-8 | 5962R9572201QXC | UT8R128K32-15WCC | 5962F0323601QXC |
| 80486 (GEN) | 5962-9310510NYA | HS9-80C86RH-Q | 5962R9572201VXC | UT8R128K32-15WCC | 5962F0323601VXC |
| 80486 (GEN) | 5962-9310502MXA | 80860 (GEN) | 5962-9453201MXA | UT8R128K32-15WWA | 5962F0323602QXA |
| 80486 (GEN) | 5962-9310502MYA | 80860 (GEN) | 5962-9453201MYA | UT8R128K32-15WWA | 5962F0323602VXA |
| 80486 (GEN) | 5962-9310506QXA | 80860 (GEN) | 5962-9453202MXA | UT8R128K32-15WWC | 5962F0323602QXC |
| 8050250 (GEN) | 5962-9457801QXC | 80860 (GEN) | 5962-9453202MYA | UT8R128K32-15WWC | 5962F0323602VXC |
| 8050250 (GEN) | 5962-9457802NXC | 80860 (GEN) | 5962-9453203MXA | AD813SE | 5962-9559601M2A |
| 8050250 (GEN) | 5962-9457803NXC | 80860 (GEN) | 5962-9453203MYA | MAX813LMJA/883B | 5962-9326705MPA |
| 8050260 (GEN) | 5962-9457804QXC | 80C86-2 (GEN) | 8405202QA | MAX813LMLP/883B | 5962-9326705M2C |
| 8050260 (GEN) | 5962-9457805NXC | 80C86-2 (GEN) | 8405202XA | HS-81C55 (GEN) | 5962R9676601VXC |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

| Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN |
|---|---|---|---|---|---|
| HS-81C55 (GEN) | 5962R9676601VYC | SL82S123B/BEA | 5962-8670302EA | 82C2888 (GEN) | 5962-9099702MRA |
| MD8155H/BQA | 5962-8759301QA | SL82S123B/BFA | 5962-8670302FA | (SEE DWG) (GEN) | 82008043A |
| HS-81C55 (GEN) | 5962R9676601QXC | HS-82C12 (GEN) | 5962R9581801QJC | (SEE DWG) (GEN) | 8200804JA |
| HS-81C55 (GEN) | 5962R9676601QYC | HS-82C12 (GEN) | 5962R9581801QXC | 82HS321A/B3A | 82008023A |
| 8156 (GEN) | 5962-8759302QA | 82S129 (GEN) | 5962-8778801EA | 82HS321A/BJA | 8200802JA |
| HS-81C56 (GEN) | 5962R9676602VXC | 82S129/BFA | 5962-8778801FA | 82HS321A/BJA | 8200803JA |
| HS-81C56 (GEN) | 5962R9676602VYC | 82S129A/BEA | 5962-8778802EA | 82HS321A/BKA | 8200802KA |
| HS-81C56 (GEN) | 5962R9676602QXC | 82S129A/BFA | 5962-8778802FA | 82HS321A/BKA | 8200803KA |
| HS-81C56 (GEN) | 5962R9676602QYC | SL82S129/BFA | 5962-8778801FA | SL82HS32131 | 82008023A |
| EDI816256CA20F44B | 5962-9679503MXA | SL82S129A/BEA | 5962-8778802EA | SL82HS321J1 | 8200801JA |
| EDI816256CA20N44B | 5962-9679503MYA | SL82S129A/BFA | 5962-8778802FA | SL82HS321J1 | 8200802JA |
| EDI816256LPA20F44B | 5962-9679506MXA | 82S141/B3A | 78016013A | SL82HS321J1 | 8200803JA |
| EDI816256LPA20N44B | 5962-9679506MYA | 82S141/BJA | 7801601JA | SL82HS321K1 | 8200801KA |
| EDI816256CA25F44B | 5962-9679502MXA | 82S141/BKA | 7801601KA | SL82HS321K1 | 8200802KA |
| EDI816256CA25N44B | 5962-9679502MYA | SL82S141/B3A | 78016013A | SL82HS321K1 | 82008033A |
| EDI816256LPA25F44B | 5962-9679505MXA | SL82S141/BJA | 7801601JA | SL82HS321K1 | 8200803KA |
| EDI816256LPA25N44B | 5962-9679505MYA | SL82S141/BKA | 7801601KA | 82C37A (GEN) | 5962-9054302MXA |
| EDI816256CA35F44B | 5962-9679501MXA | 82S153A (GEN) | 5962-87682012A | HS-82C37A (GEN) | 5962R9582101VQC |
| EDI816256CA35N44B | 5962-9679501MYA | 82S153A (GEN) | 5962-8768201MSA | HS-82C37A (GEN) | 5962R9582101VXC |
| EDI816256LPA35F44B | 5962-9679504MXA | 82S153A (GEN) | 5962-8768201RA | MD82C37A | 5962-9054302MQA |
| EDI816256LPA35N44B | 5962-9679504MYA | 82S153A (GEN) | 5962-8768201SA | 82C37A-12 (GEN) | 5962-9054303MQA |
| HS-82C08 (GEN) | 5962R9571401QRC | 82S153A/B2A | 5962-8768201M2A | 82C37A-12 (GEN) | 5962-9054303MXA |
| HS-82C08 (GEN) | 5962R9571401QXC | 82S153A/BRA | 5962-8768201MRA | 82C37A-5 (GEN) | 5962-9054301MQA |
| HS-82C08 (GEN) | 5962R9571401VRC | SL82S16/BEA | 8602301EA | 82C37A-5 (GEN) | 5962-9054301MXA |
| HS-82C08 (GEN) | 5962R9571401VXC | SL82S16/BFA | 8602301FA | HS-82C37A (GEN) | 5962R9582101QQC |
| 82S105 (GEN) | 5962-86709023A | 82S181A-50/QXA | 5962-0320201QXA | HS-82C37A (GEN) | 5962R9582101QXC |
| 82S105 (GEN) | 5962-8670902XA | 82188 (GEN) | 5962-8767201YA | 8238016 (GEN) | 5962-8959301YA |
| 82S105 (GEN) | 5962-8670902YA | 82S191-50/QJA | 5962-0320302QJA | 8238016 (GEN) | 5962-8959301ZA |
| 82S105/B3A | 5962-86709013A | 82S191-50/QKA | 5962-0320302QKA | 8238020 (GEN) | 5962-8959302YA |
| 82S105/BXA | 5962-8670901XA | 82S191-50/QLA | 5962-0320302QLA | 8238020 (GEN) | 5962-8959302ZA |
| 82S105/BYA | 5962-8670901YA | 82S191-50/QXA | 5962-0320302QXA | 8238025 (GEN) | 5962-8959303YA |
| SL82S105/B3A | 5962-86709013A | 82S191-50/Q3A | 5962-0320302Q3A | 8238025 (GEN) | 5962-8959303ZA |
| SL82S105/BXA | 5962-8670901XA | 82S191-65/QJA | 5962-0320301QJA | 8238412 (GEN) | 5962-8766902VA |
| SL82S105/BYA | 5962-8670901YA | 82S191-65/QKA | 5962-0320301QKA | 8238416 (GEN) | 5962-8766901VA |
| 8211 (GEN) | 5962-9081101MHA | 82S191-65/QLA | 5962-0320301QLA | 8251A (GEN) | 5962-8754801XA |
| ICL8211 (GEN) | 5962-8984201GC | 82S191-65/QXA | 5962-0320301QXA | MD8251A/B | 5962-8754802XA |
| MAX8211MFB/883B | 5962-9081101MXC | 82S191-65/Q3A | 5962-0320301Q3A | MR8251A/B | 5962-87548023A |
| MAX8211MJA/883B | 5962-9081101MPA | AD822S (GEN) | 5962-9320901MPA | 82510 (GEN) | 5962-8972501XA |
| MAX8211MTV/883B | 5962-9081101MGC | DAC8221A (GEN) | 5962-89671013A | 82510 (GEN) | 5962-89725023A |
| 8212 (GEN) | 5962-9081102MHA | DAC-8221AW | 5962-8967101LA | MD82C52/883 | 8501501XA |
| HS-82C12 (GEN) | 5962R9581801V9A | SL82S212/BWA | 5962-8770301WA | MR82C52/883 | 85015013A |
| HS-82C12 (GEN) | 5962R9581801VJC | DAC8222A (GEN) | 5962-8967201LA | 8253 (GEN) | 5962-8752001JA |
| HS-82C12 (GEN) | 5962R9581801VXC | 82C237 (GEN) | 5962-9054304MQA | MD8253/B | 5962-8752002JA |
| ICL8212 (GEN) | 5962-8984202GC | 82C237 (GEN) | 5962-9054304MXA | 8253-5 (GEN) | 5962-8752003JA |
| MAX8212MFB/883B | 5962-9081102MXC | 82C237-12 (GEN) | 5962-9054305MQA | HS1-82C54RH-Q | 5962R9571301VJC |
| MAX8212MJA/883B | 5962-9081102MPA | 82C237-12 (GEN) | 5962-9054305MXA | HS9-82C54RH-Q | 5962R9571301VXC |
| MAX8212MTV/883B | 5962-9081102MGC | 82C28410 (GEN) | 5962-8773401VA | MD82C54/883 | 8406501JA |
| 82S123A/BEA | 5962-8670301EA | 82C2846 (GEN) | 5962-8773403VA | MR82C54/883 | 84065013A |
| 82S123A/BFA | 5962-8670301FA | 82C2848 (GEN) | 5962-8773402VA | 82C54-12 (GEN) | 8406502JA |
| 82S123B/BEA | 5962-8670302EA | 82C28810 (GEN) | 5962-9099703MRA | MR82C54-12/883 | 84065023A |
| 82S123B/BFA | 5962-8670302FA | 82288-6 (GEN) | 5962-8514901RA | HS1-82C54RH-8 | 5962R9571301QJC |
| SL82S123A/BEA | 5962-8670301EA | 82C2886 (GEN) | 5962-9099701MRA | HS9-82C54RH-8 | 5962R9571301QXC |
| SL82S123A/BFA | 5962-8670301FA | 82288-8 (GEN) | 5962-8514902RA | HS1-82C55ARH-Q | 5962R9581901VQC |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

| Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN |
|---|---|---|---|---|---|
| MD8255A/BQA | 5962-8757001QA | IL8286/B3A | 5962-86868013A | DAC8408B (GEN) | 5962-8967802XA |
| MD82C55A/883 | 8406602QA | IL8286/B3C | 5962-86868013C | AD841 (GEN) | 5962-8964101XA |
| MR8255A/BXA | 5962-8757001XA | IL8286/BRA | 5962-8686801RA | AD841SE/883B | 5962-89641012A |
| MR82C55A/883 | 8406602XA | 82C86H-5 (GEN) | 5962-87577012A | AD841SQ/883B | 5962-8964101CA |
| 8255A-5 (GEN) | 5962-8757002QA | MD82C86H-5/883 | 5962-8757701RA | DAC8412AT/883 | 5962-9176401MXA |
| 82C55A-5 (GEN) | 8406601QA | 82C86 (GEN) | 5962-9571701VRC | DAC8412BT/883 | 5962-9176402MXA |
| 82C55A-5 (GEN) | 8406601XA | IL8287/B3A | 5962-86868023A | DAC8412BTC/883 | 5962-9176402M3A |
| HS1-82C55ARH-8 | 5962R9581901QQC | IL8287/BRX | 5962-8686802RA | DAC8413AT/883 | 5962-9176403MXA |
| MD8259A/B | 5962-8751801XA | 82C87H-5 (GEN) | 5962-87577022A | DAC8413BT/883 | 5962-9176404MXA |
| MD82C59A/B | 5962-8501602YA | MD82C87H-5/883 | 5962-8757702RA | DAC8413BTC/883 | 5962-9176404M3A |
| MR8259A/B | 5962-87518013A | 82C88 (GEN) | 84069012A | AD842SE/883B | 5962-89642012A |
| MR82C59A/B | 5962-85016023A | MD82C88/883 | 8406901RA | AD842SH/883B | 5962-8964201XA |
| MD82C59A-5B | 5962-8501601YA | 82C88-10 (GEN) | 8406902RA | AD842SQ/883B | 5962-8964201CA |
| MR82C59A-5B | 5962-85016013A | 82C88 (GEN) | 5962-9672701VRC | Z8420 (GEN) | 8418602QA |
| 82596 (GEN) | 5962-9454201QYA | 82C89 (GEN) | 5962-85528012A | Z8420A (GEN) | 8418601QA |
| MD82C59A/7 | 5962-9571801VXC | 82C89 (GEN) | 5962-8552801RA | Z84C2006CMB | 5962-8951401QA |
| MX-826/883 | 5962-9450601HXC | AD829SE/883B | 5962-9312901M2A | 84256CS20 (GEN) | 5962-9161208MTA |
| SL82S62/BCA | 5962-8754301CA | AD829SQ/883B | 5962-9312901MPA | 84256CS20 (GEN) | 5962-9161208MYA |
| SL82S62/BDA | 5962-8754301DA | PA83M/883 | 5962-9162101HXA | 84256CS20 (GEN) | 5962-9161208MZA |
| 82HS641A (GEN) | 82009023A | AD830SQ/883B | 5962-9313001MPA | 84256LPS20 (GEN) | 5962-9161207MTA |
| 82HS641A (GEN) | 8200902JA | TS83048MCB/C | 5962-9092703MXA | 84256LPS20 (GEN) | 5962-9161207MYA |
| 82HS641B (GEN) | 82009033A | TS83048ME1B/C | 5962-9092703M3A | 84256LPS20 (GEN) | 5962-9161207MZA |
| 82HS641B (GEN) | 8200903JA | 8X305/BUA | 8550201UA | 84256CS25 (GEN) | 5962-9161206MUA |
| R29791 | 82009013A | 8X305/BXA | 8550201XA | 84256CS25 (GEN) | 5962-9161206MXA |
| AD827SE/883B | 5962-9211701M2A | 8X305/BYA | 8550201YA | 84256CS25 (GEN) | 5962-9161206MYA |
| AD827SQ/883B | 5962-9211701MPA | 8X305-10 (GEN) | 8550202UA | 84256CS25 (GEN) | 5962-9161206MZA |
| 82720 (GEN) | 5962-8608801QA | 8X305-10 (GEN) | 8550202XA | 84256LPS25 (GEN) | 5962-9161205MTA |
| 8274 (GEN) | 5962-8771301QA | 8X305-10 (GEN) | 8550202YA | 84256LPS25 (GEN) | 5962-9161205MUA |
| 8282 (GEN) | 84179013A | AD8306A/QML | 5962-9864601QEA | 84256LPS25 (GEN) | 5962-9161205MXA |
| 8282 (GEN) | 8417901RA | 8X320 (GEN) | 5962-8550301QA | 84256LPS25 (GEN) | 5962-9161205MYA |
| 82C82 (GEN) | 84067012A | 8X320 (GEN) | 5962-8550301UA | 84256LPS25 (GEN) | 5962-9161205MZA |
| HI-8282 (GEN) | 5962-8688002XA | 83C451 (GEN) | 5962-8972602MMA | 84256CS25 (GEN) | 5962-9161206MTA |
| IL8282/B3A | 84179033A | 83C451 (GEN) | 5962-8972602MUA | 84256CS35 (GEN) | 5962-9161204MTA |
| IL8282/B3C | 84179033C | 83C451 (GEN) | 5962-8972602MXA | 84256CS35 (GEN) | 5962-9161204MUA |
| IL8282/BRA | 8417903RA | 83C451 (GEN) | 5962-8972602UA | 84256CS35 (GEN) | 5962-9161204MXA |
| MD82C82/883 | 8406701RA | 83C451 (GEN) | 5962-8972602XA | 84256CS35 (GEN) | 5962-9161204MYA |
| HI-8282CM-03 | 5962-8688002QA | IL8X350/B3C | 5962-86052013C | 84256CS35 (GEN) | 5962-9161204MZA |
| 82C82/7 (GEN) | 5962-9571601VRC | SL8X350/B3A | 5962-86052013A | 84256LPS35 (GEN) | 5962-9161203MTA |
| 8283 (GEN) | 84179043A | SL8X350/BWA | 5962-8605201WA | 84256LPS35 (GEN) | 5962-9161203MUA |
| 82C83H (GEN) | 84067022A | 8X371 (GEN) | 5962-8757601XA | 84256LPS35 (GEN) | 5962-9161203MXA |
| 82C83H (GEN) | 8406702RA | 8X376 (GEN) | 5962-8685101XA | 84256LPS35 (GEN) | 5962-9161203MYA |
| IL8283/B2C | 84179023C | HI-8382 (GEN) | 5962-86879013A | 84256LPS35 (GEN) | 5962-9161203MZA |
| IL8283/B3A | 84179023A | HI-8382CM-03 | 5962-8687901EA | 84256CS45 (GEN) | 5962-9161202MTA |
| IL8283/BRA | 8417902RA | TS8388BMFB/Q | 5962-0050401QYC | 84256CS45 (GEN) | 5962-9161202MUA |
| IL8283/BRA | 8417904RA | TS8388BMFSB/Q | 5962-0050401QXC | 84256CS45 (GEN) | 5962-9161202MXA |
| 82C84A (GEN) | 84068012A | 8397 (GEN) | 8552001XA | 84256CS45 (GEN) | 5962-9161202MYA |
| 82C84A (GEN) | 8406802VA | 8397 (GEN) | 8552001YA | 84256CS45 (GEN) | 5962-9161202MZA |
| MD82C84A/883 | 8406801VA | 8397BH (GEN) | 5962-8977201MZA | 84256LPS45 (GEN) | 5962-9161201MTA |
| 82C84A/7 (GEN) | 5962-9571501VVC | PA84M/883 | 5962-9073601HXA | 84256LPS45 (GEN) | 5962-9161201MUA |
| HS1-82C85RH-Q | 5962R9582001VJC | AD840 (GEN) | 5962-89640012A | 84256LPS45 (GEN) | 5962-9161201MXA |
| HS9-82C85RH-Q | 5962R9582001VXC | AD840 (GEN) | 5962-8964001CA | 84256LPS45 (GEN) | 5962-9161201MYA |
| HS1-82C85RH-8 | 5962R9582001QJC | HX84050VHC | 5962H9684001VXC | 84256LPS45 (GEN) | 5962-9161201MZA |
| HS9-82C85RH-8 | 5962R9582001QXC | DAC8408A (GEN) | 5962-8967801XA | AD843SE/883B | 5962-9098001M2A |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

| Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN |
|---|---|---|---|---|---|
| AD843SH/883B | 5962-9098001MXA | UT8Q512-UCA | 5962L9960701QUA | AS8S512K32Q1-45/883 | 5962-9461112HAC |
| AD843SQ/883B | 5962-9098001MPA | UT8Q512-UCA | 5962L9960701TUA | AS8S512K32Q1-45L/88 | 5962-9461106HAA |
| Z8430 (GEN) | 8301602XA | UT8Q512-UCA | 5962L9960703QUA | AS8S512K32Q1-45L/88 | 5962-9461106HAC |
| Z8430A (GEN) | 8301601XA | UT8Q512-UCA | 5962L9960703TUA | AS8S512K32P-15/Q | 5962-9461117HTA |
| Z84C3006CMB | 5962-8951501XA | UT8Q512-UCC | 5962D9960701QUC | AS8S512K32P-15/Q | 5962-9461117HTC |
| AD844SE/QMLR | 5962R8964401V2A | UT8Q512-UCC | 5962D9960701TUC | AS8S512K32P-15L/Q | 5962-9461119HTA |
| AD844SE/QMLV | 5962-8964401V2A | UT8Q512-UCC | 5962L9960701QUC | AS8S512K32P-15L/Q | 5962-9461119HTC |
| AD844SQ/883B | 5962-8964401PA | UT8Q512-UCC | 5962L9960701TUC | AS8S512K32Q-15/Q | 5962-9461117HMA |
| AD844SQ/QMLR | 5962R8964401VPA | UT8Q512-UCC | 5962L9960703QUC | AS8S512K32Q-15/Q | 5962-9461117HMC |
| AD844SQ/QMLV | 5962-8964401VPA | UT8Q512-UCC | 5962L9960703TUC | AS8S512K32Q-15L/Q | 5962-9461119HMA |
| Z8442 (GEN) | 8301502QA | UT8Q512-UWA | 5962L9960702QUA | AS8S512K32Q-15L/Q | 5962-9461119HMC |
| Z8442A (GEN) | 8301501QA | UT8Q512-UWA | 5962L9960702TUA | AS8S512K32Q1-55/883 | 5962-9461111HAA |
| Z84C4206 (GEN) | 5962-8951601QA | UT8Q512-UWA | 5962L9960704QUA | AS8S512K32Q1-55/883 | 5962-9461111HAC |
| AD845SQ/883B | 5962-8964501PA | UT8Q512-UWA | 5962L9960704TUA | AS8S512K32Q1-55L/88 | 5962-9461105HAA |
| AD846S (GEN) | 5962-8964601PA | UT8Q512-UWC | 5962L9960702QUC | AS8S512K32Q1-55L/88 | 5962-9461105HAC |
| AD847SQ/883 | 5962-8964701PA | UT8Q512-UWC | 5962L9960702TUC | AS8S512K32P-17/Q | 5962-9461116HTA |
| HCTS85 (GEN) | 5962R9576801V9A | UT8Q512-UWC | 5962L9960704QUC | AS8S512K32P-17/Q | 5962-9461116HTC |
| HCTS85 (GEN) | 5962R9576801VXC | UT8Q512-UWC | 5962L9960704TUC | AS8S512K32P-17L/Q | 5962-9461110HTA |
| HCTS85DMSR | 5962R9576801VEC | UT8Q512K32-SCA | 5962L0153301QXC | AS8S512K32P-17L/Q | 5962-9461110HTC |
| ACT8500-S | 5962-0050201KXC | UT8Q512K32-SCC | 5962L0153301TXC | AS8S512K32Q-17/Q | 5962-9461116HMA |
| ACT8501-S | 5962-0050202KXC | AS8S512K32Q1-12/883 | 5962-9461118HAA | AS8S512K32Q-17/Q | 5962-9461116HMC |
| ACT8502-S | 5962-0323401KXC | AS8S512K32Q1-12/883 | 5962-9461118HAC | AS8S512K32Q-17L/Q | 5962-9461110HMA |
| UT8Q512_QDIE | 5962L9960701Q9A | AS8S512K32Q1-12L/88 | 5962-9461120HAA | AS8S512K32Q-17L/Q | 5962-9461110HMC |
| UT8Q512_QDIE | 5962L9960702Q9A | AS8S512K32Q1-12L/88 | 5962-9461120HAC | AS8S512K32P-20/Q | 5962-9461115HTA |
| UT8Q512_QDIE | 5962L9960703Q9A | AS8S512K32Q1-15/883 | 5962-9461117HAA | AS8S512K32P-20/Q | 5962-9461115HTC |
| UT8Q512_QDIE | 5962L9960704Q9A | AS8S512K32Q1-15/883 | 5962-9461117HAC | AS8S512K32P-20L/Q | 5962-9461109HTA |
| UT8Q512_TDIE | 5962L9960701T9A | AS8S512K32Q1-15L/88 | 5962-9461119HAA | AS8S512K32P-20L/Q | 5962-9461109HTC |
| UT8Q512_TDIE | 5962L9960702T9A | AS8S512K32Q1-15L/88 | 5962-9461119HAC | AS8S512K32Q-20/Q | 5962-9461115HMA |
| UT8Q512_TDIE | 5962L9960703T9A | AS8S512K32Q1-17/883 | 5962-9461116HAA | AS8S512K32Q-20/Q | 5962-9461115HMC |
| UT8Q512_TDIE | 5962L9960704T9A | AS8S512K32Q1-17/883 | 5962-9461116HAC | AS8S512K32Q-20L/Q | 5962-9461109HMA |
| UT8Q512-ICA | 5962D9960701QXA | AS8S512K32Q1-17L/88 | 5962-9461110HAA | AS8S512K32Q-20L/Q | 5962-9461109HMC |
| UT8Q512-ICA | 5962D9960701TXA | AS8S512K32Q1-17L/88 | 5962-9461110HAC | AS8S512K32P-25/Q | 5962-9461114HTA |
| UT8Q512-ICA | 5962L9960701QXA | AS8S512K32P-12/Q | 5962-9461118HTA | AS8S512K32P-25/Q | 5962-9461114HTC |
| UT8Q512-ICA | 5962L9960701TXA | AS8S512K32P-12/Q | 5962-9461118HTC | AS8S512K32P-25L/Q | 5962-9461108HTA |
| UT8Q512-ICA | 5962L9960703QXA | AS8S512K32P-12L/Q | 5962-9461120HTA | AS8S512K32P-25L/Q | 5962-9461108HTC |
| UT8Q512-ICA | 5962L9960703TXA | AS8S512K32P-12L/Q | 5962-9461120HTC | AS8S512K32Q-25/Q | 5962-9461114HMA |
| UT8Q512-ICC | 5962D9960701QXC | AS8S512K32Q-12/Q | 5962-9461118HMA | AS8S512K32Q-25/Q | 5962-9461114HMC |
| UT8Q512-ICC | 5962D9960701TXC | AS8S512K32Q-12/Q | 5962-9461118HMC | AS8S512K32Q-25L/Q | 5962-9461108HMA |
| UT8Q512-ICC | 5962L9960701QXC | AS8S512K32Q-12L/Q | 5962-9461120HMA | AS8S512K32Q-25L/Q | 5962-9461108HMC |
| UT8Q512-ICC | 5962L9960701TXC | AS8S512K32Q-12L/Q | 5962-9461120HMC | AS8S512K32P-35/Q | 5962-9461113HTA |
| UT8Q512-ICC | 5962L9960703QXC | AS8S512K32Q1-20/883 | 5962-9461115HAA | AS8S512K32P-35/Q | 5962-9461113HTC |
| UT8Q512-ICC | 5962L9960703TXC | AS8S512K32Q1-20/883 | 5962-9461115HAC | AS8S512K32P-35L/Q | 5962-9461107HTA |
| UT8Q512-IWA | 5962L9960702QXA | AS8S512K32Q1-20L/88 | 5962-9461109HAA | AS8S512K32P-35L/Q | 5962-9461107HTC |
| UT8Q512-IWA | 5962L9960702TXA | AS8S512K32Q1-20L/88 | 5962-9461109HAC | AS8S512K32Q-35/Q | 5962-9461113HMA |
| UT8Q512-IWA | 5962L9960704QXA | AS8S512K32Q1-25/883 | 5962-9461114HAA | AS8S512K32Q-35/Q | 5962-9461113HMC |
| UT8Q512-IWA | 5962L9960704TXA | AS8S512K32Q1-25/883 | 5962-9461114HAC | AS8S512K32Q-35L/Q | 5962-9461107HMA |
| UT8Q512-IWC | 5962L9960702QXC | AS8S512K32Q1-25L/88 | 5962-9461108HAA | AS8S512K32Q-35L/Q | 5962-9461107HMC |
| UT8Q512-IWC | 5962L9960702TXC | AS8S512K32Q1-25L/88 | 5962-9461108HAC | AS8S512K32P-45/Q | 5962-9461112HTA |
| UT8Q512-IWC | 5962L9960704QXC | AS8S512K32Q1-35/883 | 5962-9461113HAA | AS8S512K32P-45/Q | 5962-9461112HTC |
| UT8Q512-IWC | 5962L9960704TXC | AS8S512K32Q1-35/883 | 5962-9461113HAC | AS8S512K32P-45L/Q | 5962-9461106HTA |
| UT8Q512TDIE | 5962D9960701T9A | AS8S512K32Q1-35L/88 | 5962-9461107HAA | AS8S512K32P-45L/Q | 5962-9461106HTC |
| UT8Q512-UCA | 5962D9960701QUA | AS8S512K32Q1-35L/88 | 5962-9461107HAC | AS8S512K32Q-45/Q | 5962-9461112HMA |
| UT8Q512-UCA | 5962D9960701TUA | AS8S512K32Q1-45/883 | 5962-9461112HAA | AS8S512K32Q-45/Q | 5962-9461112HMC |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

| Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN |
|---|---|---|---|---|---|
| AS8S512K32Q-45L/Q | 5962-9461106HMA | BUS-8553-110 | 5962-8604905XC | DAC87 (GEN) | 8300201JA |
| AS8S512K32Q-45L/Q | 5962-9461106HMC | BUS-8553-110 | 5962-8604905XC | DAC87 (GEN) | 8300201JC |
| AS8S512K32P-55/Q | 5962-9461111HTA | BUS-8553-110 | 5962-8604905YC | DAC87 (GEN) | 8300201XA |
| AS8S512K32P-55/Q | 5962-9461111HTC | BUS-8553-110 | 5962-8604905YC | AD871SD/883B | 5962-9468601MXA |
| AS8S512K32P-55L/Q | 5962-9461105HTA | BUS-8553-130 | 5962-8604905XC | AD871SE/883B | 5962-9468602MYA |
| AS8S512K32P-55L/Q | 5962-9461105HTC | BUS-8553-130 | 5962-8604905XC | SP8718 (GEN) | 5962-8861701PA |
| AS8S512K32Q-55/Q | 5962-9461111HMA | BUS-8553-130 | 5962-8604905YC | 87C196KC (GEN) | 5962-9069201MXA |
| AS8S512K32Q-55/Q | 5962-9461111HMC | BUS-8553-130 | 5962-8604905YC | 87C196KC (GEN) | 5962-9069201MYA |
| AS8S512K32Q-55L/Q | 5962-9461105HMA | BUS-8553-140 | 5962-8604905XA | 87C196KC (GEN) | 5962-9069204QXA |
| AS8S512K32Q-55L/Q | 5962-9461105HMC | BUS-8553-140 | 5962-8604905XA | 87C196KC (GEN) | 5962-9069204QYA |
| UT8R512K8-15UCA | 5962F0323501QUA | BUS-8553-140 | 5962-8604905YA | 87C196KD (GEN) | 5962-9069202QXA |
| UT8R512K8-15UCA | 5962F0323501VUA | BUS-8553-140 | 5962-8604905YA | 87C196KD (GEN) | 5962-9069202QYA |
| UT8R512K8-15UCC | 5962F0323501QUC | BUS-8553-150 | 5962-8604905XA | 87C196KD (GEN) | 5962-9069203QXA |
| UT8R512K8-15UCC | 5962F0323501VUC | BUS-8553-150 | 5962-8604905XA | 87C196KD (GEN) | 5962-9069203QYA |
| UT8R512K8-15UWA | 5962F0323502QUA | BUS-8553-150 | 5962-8604905YA | AD872ASD/883B | 5962-9306001MXA |
| UT8R512K8-15UWA | 5962F0323502VUA | BUS-8553-150 | 5962-8604905YA | AD872ASD/883B | 5962-9306003MXA |
| UT8R512K8-15UWC | 5962F0323502QUC | AD8561AL/QMLR | 5962R0051501VHA | AD872ASE/883B | 5962-9306002MYA |
| UT8R512K8-15UWC | 5962F0323502VUC | AD8561AL/QMLV | 5962-0051501VHA | AD872ASE/883B | 5962-9306004MYA |
| AS8E512K8CW-150/HQ | 5962-9309101HYA | AD8561AQ/QMLR | 5962R0051501VPA | SP8720 (GEN) | 5962-9057701MEA |
| AS8E512K8CW-150/HQ | 5962-9309101HYC | AD8561AQ/QMLV | 5962-0051501VPA | 8731-001 | 5962-96A1901QXA |
| AS8E512K8CW-200/HQ | 5962-9309104HYA | DP8572AMD/883 | 5962-9164101MJA | SP8741 (GEN) | 5962-9159001MEA |
| AS8E512K8CW-200/HQ | 5962-9309104HYC | ACS86 (GEN) | 5962F9565401VCC | 8744H10 (GEN) | 5962-8997101MQA |
| AS8E512K8CW-250/HQ | 5962-9309103HYA | ACS86 (GEN) | 5962F9565401VXC | 87C451 (GEN) | 5962-9154201MXA |
| AS8E512K8CW-250/HQ | 5962-9309103HYC | ACTS86 (GEN) | 5962F9566001VCC | 87C451/BMA | 5962-9154201MMA |
| AS8E512K8CW-300/HQ | 5962-9309102HYA | ACTS86 (GEN) | 5962F9566001VXC | 8748H (GEN) | 5962-9051201MQA |
| AS8E512K8CW-300/HQ | 5962-9309102HYC | HCS86 (GEN) | 5962R9578301V9A | 8751H/BQA | 8419002QA |
| 8513-001 | 5962-99A2601QXC | HCS86DMSR | 5962R9578301VCC | 8751H/BYA | 8419002YA |
| Z8523008CMB | 5962-8868910QA | HCS86KMSR | 5962R9578301VXC | 87C51 (GEN) | 5962-8768401QA |
| Z8523008LMB | 5962-8868910YA | HCTS86 (GEN) | 5962R9581401V9A | 87C51 (GEN) | 5962-8768401UA |
| Z8523010CMB | 5962-8868908QA | HCTS86 (GEN) | 5962R9581401VCC | 87C51/BMA | 5962-8768401MMA |
| Z8523010LMB | 5962-8868908YA | HCTS86 (GEN) | 5962R9581401VXC | 87C51/BQA | 5962-8768401MQA |
| Z8523016CMB | 5962-8868909QA | RHFAC86K01Q | 5962F8955001XC | 87C51/BUA | 5962-8768401MUA |
| Z8523016LMB | 5962-8868909YA | RHFAC86K01V | 5962F8955001VXC | 87C51FB (GEN) | 5962-9056401TA |
| Z85C3006CMB | 5962-8868901QA | RHFAC86K02Q | 5962F8955001XA | 87C51FB (GEN) | 5962-9056401UA |
| Z85C3006LMB | 5962-8868901YA | RHFAC86K02V | 5962F8955001VXA | 87C51FB (GEN) | 5962-9056401ZA |
| Z85C3008CMB | 5962-8868902QA | RHFACT86K01Q | 5962F9068702QXC | 87C51FC (GEN) | 5962-9169701MTA |
| Z85C3008LMB | 5962-8868902YA | RHFACT86K01V | 5962F9068702VXC | 87C51FC (GEN) | 5962-9169701MUA |
| 85C30-10 (GEN) | 5962-8868903QA | ACS86 (GEN) | 5962F9565402V9A | 87C51FC (GEN) | 5962-9169701MZA |
| 85C30-10 (GEN) | 5962-8868903YA | ACS86 (GEN) | 5962F9565402VCC | 87C51FC (GEN) | 5962-9169701NNA |
| Z85C3010CMB | 5962-8868907QA | ACS86 (GEN) | 5962F9565402VXC | 87C51FC (GEN) | 5962-9169701NYA |
| Z85C3010LMB | 5962-8868907YA | ACTS86 (GEN) | 5962F9566002V9A | 87C51FC (GEN) | 5962-9169703NNA |
| Z85C3010NMB | 5962-8868907XA | ACTS86 (GEN) | 5962F9566002VCC | 87C51FC (GEN) | 5962-9169703NYA |
| 85C30-12 (GEN) | 5962-8868904QA | ACTS86 (GEN) | 5962F9566002VXC | 87C51RB/BMA | 5962-9056401MA |
| 85C30-12 (GEN) | 5962-8868904YA | RHFACT86K02Q | 5962F9068702QXA | 87C51RB/BQA | 5962-9056401XA |
| 85C30-16 (GEN) | 5962-8868905QA | RHFACT86K02V | 5962F9068702VXA | 87C51RC/B4A | 5962-9169701M4A |
| 85C30-16 (GEN) | 5962-8868905YA | SP8602 (GEN) | 5962-9205901MXA | 87C51RC/BMA | 5962-9169701MMA |
| 85C30-8 (GEN) | 5962-8868906QA | SP8620 (GEN) | 5962-9097001MCA | 87C51RC/BQA | 5962-9169701MXA |
| 85C30-8 (GEN) | 5962-8868906YA | SP8630 (GEN) | 5962-9200301MCA | 87C5116 (GEN) | 5962-8768402QA |
| Z0853604CMB | 8300101QA | SP8647 (GEN) | 5962-9061801MEA | 87C5116 (GEN) | 5962-8768402UA |
| Z0853604LMB | 8300101YA | SP8670 (GEN) | 5962-9208801MCA | 87C51-16/BMA | 5962-8768402MMA |
| Z0853606CMB | 8300102QA | 8690A (GEN) | 5962-8767801EA | 87C51-16/BQA | 5962-8768402MQA |
| Z0853606LMB | 8300102YA | 8697-001 | 5962-01A0801NXB | 87C51-16/BUA | 5962-8768402MUA |
| MD85C52/7 | 5962-9581701VXC | ADDAC87D-CBI-V/883 | 8300301JA | 87C51FB (GEN) | 5962-9056402TA |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

| Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN |
|---|---|---|---|---|---|
| 87C51FB (GEN) | 5962-9056402UA | 87C571 (GEN) | 5962-9156605NXA | EDI88128LPS100TB | 5962-8959806MZA |
| 87C51FB (GEN) | 5962-9056402ZA | 87C571 (GEN) | 5962-9156607NXA | EDI88128LPS100ZB | 5962-8959806M8A |
| 87C51FC-16 (GEN) | 5962-9169702MTA | TLC876MDW | 5962-9954001NXD | EDI88130CX100FB | 5962-8959823MTA |
| 87C51FC-16 (GEN) | 5962-9169702MUA | 87C654/BMA | 5962-9056403MA | EDI88128CS12TB | 5962-8959846MZA |
| 87C51FC-16 (GEN) | 5962-9169702MZA | 87C654/BQA | 5962-9056403XA | EDI88130CS12L32B | 5962-8959845MMA |
| 87C51FC-16 (GEN) | 5962-9169702NNA | 87C654OT (GEN) | 5962-9056405MA | EDI88130CS12TB | 5962-8959845MZA |
| 87C51FC-16 (GEN) | 5962-9169702NYA | 87C654OT (GEN) | 5962-9056405XA | EDI88128CS120CB | 5962-8959822MXA |
| 87C51FC-16 (GEN) | 5962-9169704NNA | 87C654-16 (GEN) | 5962-9056406MA | EDI88128CS120FB | 5962-8959822MTA |
| 87C51FC-16 (GEN) | 5962-9169704NYA | 87C654-16 (GEN) | 5962-9056406XA | EDI88128CS120NB | 5962-8959822MYA |
| 87C51RB-16/BMA | 5962-9056402MA | 87C654-16/BMA | 5962-9056404MA | EDI88128CS120TB | 5962-8959822MZA |
| 87C51RB-16/BQA | 5962-9056402XA | 87C654-16/BQA | 5962-9056404XA | EDI88128CS120ZB | 5962-8959822M8A |
| 87C51RC-16/B4A | 5962-9169702M4A | 87C751 (GEN) | 5962-9156601M3A | EDI88128LPS120CB | 5962-8959805MXA |
| 87C51RC-16/BMA | 5962-9169702MMA | 87C751 (GEN) | 5962-9156602M3A | EDI88128LPS120FB | 5962-8959805MTA |
| 87C51RC-16/BQA | 5962-9169702MXA | 87C751/BLA | 5962-9156601MLA | EDI88128LPS120LB | 5962-8959805MUA |
| 87C51-16 (GEN) | 5962-8768404NXA | 87C751/BLA OT | 5962-9156602MLA | EDI88128LPS120NB | 5962-8959805MYA |
| 87C51-16 (GEN) | 5962-8768404NYA | 87C751-16 (GEN) | 5962-9156603M3A | EDI88128LPS120TB | 5962-8959805MZA |
| 87C51-16 (GEN) | 5962-8768406NXA | 87C751-16/BLA | 5962-9156603MLA | EDI88128LPS120ZB | 5962-8959805M8A |
| 87C51-16 (GEN) | 5962-8768406NYA | 87C751-16?BLA OT | 5962-9156604MLA | EDI88128CS120LB | 5962-8959822MUA |
| 87C51 (GEN) | 5962-8768403NXA | 87C752/BXA | 5962-9157701MXA | EDI88128CS15TB | 5962-8959844MZA |
| 87C51 (GEN) | 5962-8768405NXA | 87C752/BXA OT | 5962-9157703MXA | EDI88128LPS15FB | 5962-8959848MTA |
| 87C51 (GEN) | 5962-8768403NYA | 87C752-16/BXA | 5962-9157702MXA | EDI88128CS20CB | 5962-8959839MXA |
| 87C51 (GEN) | 5962-8768405NYA | 87C752-16/BXA OT | 5962-9157704MXA | EDI88128CS20FB | 5962-8959839MTA |
| 8751H-8/BQA | 8419001QA | SP8782 (GEN) | 5962-9208901MPA | EDI88128CS20LB | 5962-8959839MUA |
| 8751H-8/BYA | 8419001YA | 8784-001 | 5962-96A1801QXA | EDI88128CS20NB | 5962-8959839MYA |
| MC8751H-8/BQA | 8419001QA | MG8797BH/BZA | 5962-8680901ZA | EDI88128CS20TB | 5962-8959839MZA |
| MR8751H-8/BYA | 8419001YA | MG8797BH/BZC | 5962-8680901ZC | EDI88128CS20ZB | 5962-8959839M8A |
| 87C52 (GEN) | 5962-9157601MUA | MQ8797BH/BYA | 5962-8680901YA | EDI88128LPS20CB | 5962-8959840MXA |
| 87C52 (GEN) | 5962-9157603MUA | MQ8797BH/BYC | 5962-8680901YC | EDI88128LPS20FB | 5962-8959840MTA |
| 87C52 (GEN) | 5962-9157603NXA | SP8799 (GEN) | 5962-9176101MPA | EDI88128LPS20LB | 5962-8959840MUA |
| 87C52 (GEN) | 5962-9157603NYA | SP8802 (GEN) | 5962-9066101MPA | EDI88128LPS20NB | 5962-8959840MYA |
| 87C52 (GEN) | 5962-9157605NXA | SP8804 (GEN) | 5962-9056701MPA | EDI88128LPS20TB | 5962-8959840MZA |
| 87C52 (GEN) | 5962-9157605NYA | SP8808 (GEN) | 5962-9157001MPA | EDI88128LPS20ZB | 5962-8959840M8A |
| 87C52/BMA | 5962-9157601MMA | 8808AC-10 (GEN) | 5962-8552503YA | EDI88128CS25CB | 5962-8959829MXA |
| 87C52/BMA OT | 5962-9157603MMA | 8808AC-12 (GEN) | 5962-8552502YA | EDI88128CS25FB | 5962-8959829MTA |
| 87C52/BQA | 5962-9157601MQA | 8808ACL-12 (GEN) | 5962-8552513YA | EDI88128CS25LB | 5962-8959829MUA |
| 87C52/BQA OT | 5962-9157603MQA | 8808AC-15 (GEN) | 5962-8552501XA | EDI88128CS25NB | 5962-8959829MYA |
| 87C52-16 (GEN) | 5962-9157602MUA | 8808AC-15 (GEN) | 5962-8552501YA | EDI88128CS25TB | 5962-8959829MZA |
| 87C52-16 (GEN) | 5962-9157604MUA | 8808AC-55 (GEN) | 5962-8552505XA | EDI88128CS25ZB | 5962-8959829M8A |
| 87C52-16 (GEN) | 5962-9157604NXA | 8808AC-55 (GEN) | 5962-8552505YA | EDI88128LPS25CB | 5962-8959812MXA |
| 87C52-16 (GEN) | 5962-9157604NYA | 8808AC-70 (GEN) | 5962-8552504YA | EDI88128LPS25FB | 5962-8959812MTA |
| 87C52-16 (GEN) | 5962-9157606NXA | 8810100 (GEN) | 5962-3829431MXA | EDI88128LPS25LB | 5962-8959812MUA |
| 87C52-16 (GEN) | 5962-9157606NYA | 8810100 (GEN) | 5962-3829431MYA | EDI88128LPS25NB | 5962-8959812MYA |
| 87C52-16/BMA | 5962-9157602MMA | 881070 (GEN) | 5962-3829432MXA | EDI88128LPS25TB | 5962-8959812MZA |
| 87C52-16/BMA OT | 5962-9157604MMA | 881070 (GEN) | 5962-3829432MYA | EDI88128LPS25ZB | 5962-8959812M8A |
| 87C52-16/BQA | 5962-9157602MQA | EDI88128CS100CB | 5962-8959823MXA | EDI88128CS35CB | 5962-8959828MXA |
| 87C52-16/BQA OT | 5962-9157604MQA | EDI88128CS100LB | 5962-8959823MUA | EDI88128CS35FB | 5962-8959828MTA |
| SP8755 (GEN) | 5962-8868401CA | EDI88128CS100NB | 5962-8959823MYA | EDI88128CS35LB | 5962-8959828MUA |
| 87C552 (GEN) | 5962-9233302MMA | EDI88128CS100TB | 5962-8959823MZA | EDI88128CS35NB | 5962-8959828MYA |
| 87C552/BMA | 5962-9233301MMA | EDI88128CS100ZB | 5962-8959823M8A | EDI88128CS35TB | 5962-8959828MZA |
| 87C552 (GEN) | 5962-9233303NYA | EDI88128LPS100CB | 5962-8959806MXA | EDI88128CS35ZB | 5962-8959828M8A |
| 87C552 (GEN) | 5962-9233304NYA | EDI88128LPS100FB | 5962-8959806MTA | EDI88128LPS35CB | 5962-8959811MXA |
| 87C571-16 (GEN) | 5962-9156606NXA | EDI88128LPS100LB | 5962-8959806MUA | EDI88128LPS35FB | 5962-8959811MTA |
| 87C571-16 (GEN) | 5962-9156608NXA | EDI88128LPS100NB | 5962-8959806MYA | EDI88128LPS35LB | 5962-8959811MUA |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART II, Listed By Generic PIN

| Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN |
|---|---|---|---|---|---|
| EDI88128LPS35NB | 5962-8959811MYA | EDI88128LPS85TB | 5962-8959807MZA | EDI88130CS35FB | 5962-8959836MTA |
| EDI88128LPS35TB | 5962-8959811MZA | EDI88128LPS85ZB | 5962-8959807M8A | EDI88130CS35LB | 5962-8959836MUA |
| EDI88128LPS35ZB | 5962-8959811M8A | EDI88128CS100CB | 5962-8959831MXA | EDI88130CS35NB | 5962-8959836MYA |
| EDI88128CS45CB | 5962-8959827MXA | EDI88130CS100FB | 5962-8959831MTA | EDI88130CS35TB | 5962-8959836MZA |
| EDI88128CS45FB | 5962-8959827MTA | EDI88130CS100LB | 5962-8959831MUA | EDI88130LPS35CB | 5962-8959819MXA |
| EDI88128CS45LB | 5962-8959827MUA | EDI88130CS100NB | 5962-8959831MYA | EDI88130LPS35FB | 5962-8959819MTA |
| EDI88128CS45NB | 5962-8959827MYA | EDI88130CS100TB | 5962-8959831MZA | EDI88130LPS35LB | 5962-8959819MUA |
| EDI88128CS45TB | 5962-8959827MZA | EDI88130LPS100CB | 5962-8959814MXA | EDI88130LPS35NB | 5962-8959819MYA |
| EDI88128CS45ZB | 5962-8959827M8A | EDI88130LPS100FB | 5962-8959814MTA | EDI88130LPS35TB | 5962-8959819MZA |
| EDI88128LPS45CB | 5962-8959810MXA | EDI88130LPS100LB | 5962-8959814MUA | EDI88130CS35L32B | 5962-8959836MMA |
| EDI88128LPS45FB | 5962-8959810MTA | EDI88130LPS100NB | 5962-8959814MYA | EDI88130LPS35L32B | 5962-8959819MMA |
| EDI88128LPS45LB | 5962-8959810MUA | EDI88130LPS100TB | 5962-8959814MZA | EDI88130CS45CB | 5962-8959835MXA |
| EDI88128LPS45NB | 5962-8959810MYA | EDI88130CS100L32B | 5962-8959831MMA | EDI88130CS45FB | 5962-8959835MTA |
| EDI88128LPS45TB | 5962-8959810MZA | EDI88130LPS100L32B | 5962-8959814MMA | EDI88130CS45LB | 5962-8959835MUA |
| EDI88128LPS45ZB | 5962-8959810M8A | EDI88130CS120CB | 5962-8959830MXA | EDI88130CS45NB | 5962-8959835MYA |
| EDI88128CS55CB | 5962-8959826MXA | EDI88130CS120FB | 5962-8959830MTA | EDI88130CS45TB | 5962-8959835MZA |
| EDI88128CS55FB | 5962-8959826MTA | EDI88130CS120LB | 5962-8959830MUA | EDI88130LPS45CB | 5962-8959818MXA |
| EDI88128CS55LB | 5962-8959826MUA | EDI88130CS120NB | 5962-8959830MYA | EDI88130LPS45FB | 5962-8959818MTA |
| EDI88128CS55NB | 5962-8959826MYA | EDI88130CS120TB | 5962-8959830MZA | EDI88130LPS45LB | 5962-8959818MUA |
| EDI88128CS55TB | 5962-8959826MZA | EDI88130LPS120CB | 5962-8959813MXA | EDI88130LPS45NB | 5962-8959818MYA |
| EDI88128CS55ZB | 5962-8959826M8A | EDI88130LPS120FB | 5962-8959813MTA | EDI88130LPS45TB | 5962-8959818MZA |
| EDI88128LPS55CB | 5962-8959809MXA | EDI88130LPS120LB | 5962-8959813MUA | EDI88130CS45L32B | 5962-8959835MMA |
| EDI88128LPS55FB | 5962-8959809MTA | EDI88130LPS120NB | 5962-8959813MYA | EDI88130LPS45L32B | 5962-8959818MMA |
| EDI88128LPS55LB | 5962-8959809MUA | EDI88130LPS120TB | 5962-8959813MZA | EDI88130CS55CB | 5962-8959834MXA |
| EDI88128LPS55NB | 5962-8959809MYA | EDI88130CS120L32B | 5962-8959830MMA | EDI88130CS55FB | 5962-8959834MTA |
| EDI88128LPS55TB | 5962-8959809MZA | EDI88130LPS120L32B | 5962-8959813MMA | EDI88130CS55LB | 5962-8959834MUA |
| EDI88128LPS55ZB | 5962-8959809M8A | EDI88130CS15L32 | 5962-8959841MMA | EDI88130CS55NB | 5962-8959834MYA |
| EDI88128C70CB | 5962-8959843MXA | EDI88130CS15TB | 5962-8959841MZA | EDI88130CS55TB | 5962-8959834MZA |
| EDI88128C70NB | 5962-8959843MYA | EDI88130CS20CB | 5962-8959838MXA | EDI88130LPS55CB | 5962-8959817MXA |
| EDI88128CS70CB | 5962-8959825MXA | EDI88130CS20FB | 5962-8959838MTA | EDI88130LPS55FB | 5962-8959817MTA |
| EDI88128CS70FB | 5962-8959825MTA | EDI88130CS20LB | 5962-8959838MUA | EDI88130LPS55LB | 5962-8959817MUA |
| EDI88128CS70LB | 5962-8959825MUA | EDI88130CS20NB | 5962-8959838MYA | EDI88130LPS55NB | 5962-8959817MYA |
| EDI88128CS70NB | 5962-8959825MYA | EDI88130CS20TB | 5962-8959838MZA | EDI88130LPS55TB | 5962-8959817MZA |
| EDI88128CS70TB | 5962-8959825MZA | EDI88130LPS20CB | 5962-8959821MXA | EDI88130CS55L32B | 5962-8959834MMA |
| EDI88128CS70ZB | 5962-8959825M8A | EDI88130LPS20FB | 5962-8959821MTA | EDI88130LPS55L32B | 5962-8959817MMA |
| EDI88128LP70CB | 5962-8959842MXA | EDI88130LPS20LB | 5962-8959821MUA | EDI88130CS70CB | 5962-8959833MXA |
| EDI88128LP70NB | 5962-8959842MYA | EDI88130LPS20NB | 5962-8959821MYA | EDI88130CS70FB | 5962-8959833MTA |
| EDI88128LPS70CB | 5962-8959808MXA | EDI88130LPS20TB | 5962-8959821MZA | EDI88130CS70LB | 5962-8959833MUA |
| EDI88128LPS70FB | 5962-8959808MTA | EDI88130CS20L32B | 5962-8959838MMA | EDI88130CS70NB | 5962-8959833MYA |
| EDI88128LPS70LB | 5962-8959808MUA | EDI88130LPS20L32B | 5962-8959821MMA | EDI88130CS70TB | 5962-8959833MZA |
| EDI88128LPS70NB | 5962-8959808MYA | EDI88130CS25CB | 5962-8959837MXA | EDI88130LPS70CB | 5962-8959816MXA |
| EDI88128LPS70TB | 5962-8959808MZA | EDI88130CS25FB | 5962-8959837MTA | EDI88130LPS70FB | 5962-8959816MTA |
| EDI88128LPS70ZB | 5962-8959808M8A | EDI88130CS25LB | 5962-8959837MUA | EDI88130LPS70LB | 5962-8959816MUA |
| EDI88128CS85CB | 5962-8959824MXA | EDI88130CS25NB | 5962-8959837MYA | EDI88130LPS70NB | 5962-8959816MYA |
| EDI88128CS85FB | 5962-8959824MTA | EDI88130CS25TB | 5962-8959837MZA | EDI88130LPS70TB | 5962-8959816MZA |
| EDI88128CS85LB | 5962-8959824MUA | EDI88130LPS25CB | 5962-8959820MXA | EDI88130CS70L32B | 5962-8959833MMA |
| EDI88128CS85NB | 5962-8959824MYA | EDI88130LPS25FB | 5962-8959820MTA | EDI88130LPS70L32B | 5962-8959816MMA |
| EDI88128CS85TB | 5962-8959824MZA | EDI88130LPS25LB | 5962-8959820MUA | EDI88130CS85CB | 5962-8959832MXA |
| EDI88128CS85ZB | 5962-8959824M8A | EDI88130LPS25NB | 5962-8959820MYA | EDI88130CS85FB | 5962-8959832MTA |
| EDI88128LPS85CB | 5962-8959807MXA | EDI88130LPS25TB | 5962-8959820MZA | EDI88130CS85LB | 5962-8959832MUA |
| EDI88128LPS85FB | 5962-8959807MTA | EDI88130CS25L32B | 5962-8959837MMA | EDI88130CS85NB | 5962-8959832MYA |
| EDI88128LPS85LB | 5962-8959807MUA | EDI88130LPS25L32B | 5962-8959820MMA | EDI88130CS85TB | 5962-8959832MZA |
| EDI88128LPS85NB | 5962-8959807MYA | EDI88130CS35CB | 5962-8959836MXA | EDI88130LPS85CB | 5962-8959815MXA |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

| Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN |
|---|---|---|---|---|---|
| EDI88130LPS85FB | 5962-8959815MTA | EDI88512LPA20N36B | 5962-9560008MMA | EDI88512CA45L32B | 5962-9560001MZA |
| EDI88130LPS85LB | 5962-8959815MUA | EDI88512CA25CB | 5962-9560003MXA | EDI88512LPA45B32B | 5962-9560005MYA |
| EDI88130LPS85NB | 5962-8959815MYA | EDI88512CA25NB | 5962-9560003MUA | EDI88512LPA45F32B | 5962-9560005M9A |
| EDI88130LPS85TB | 5962-8959815MZA | EDI88512LPA25CB | 5962-9560007MXA | EDI88512LPA45L32B | 5962-9560005MZA |
| EDI88130CS85L32B | 5962-8959832MMA | EDI88512LPA25CB | 5962-9560011QXA | EDI88512CA45F36B | 5962-9560001MTA |
| EDI88130LPS85L32B | 5962-8959815MMA | EDI88512LPA25F32B | 5962-9560011Q9A | EDI88512CA45N36B | 5962-9560001MMA |
| EPF8820 (GEN) | 5962-9463401MXC | EDI88512LPA25F36B | 5962-9560011QTA | EDI88512LPA45F36B | 5962-9560005MTA |
| EPF8820 (GEN) | 5962-9463401MYA | EDI88512LPA25L32B | 5962-9560011QZA | EDI88512LPA45N36B | 5962-9560005MMA |
| 8828-001 | 5962-01A0901NXB | EDI88512LPA25N36B | 5962-9560011QMA | 88914 (GEN) | 5962-9317601QCA |
| SP8830AC (GEN) | 5962-9157201MPA | EDI88512LPA25NB | 5962-9560007MUA | 88914 (GEN) | 5962-9317601QDA |
| EDI88512CA12CB | 5962-9560016QXA | EDI88512LPA25NB | 5962-9560011QUA | 88915-55 (GEN) | 5962-9319601QYA |
| EDI88512CA12F32B | 5962-9560016Q9A | EDI88512CA25B32B | 5962-9560003MYA | 88915-55 (GEN) | 5962-9319601QZA |
| EDI88512CA12F36B | 5962-9560016QTA | EDI88512CA25F32B | 5962-9560003M9A | 8908CA35 (GEN) | 5962-8988303XA |
| EDI88512CA12L32B | 5962-9560016QZA | EDI88512CA25L32B | 5962-9560003MZA | 8908CA35 (GEN) | 5962-8988303YA |
| EDI88512CA12N36B | 5962-9560016QMA | EDI88512LPA25B32B | 5962-9560007MYA | 8908CA35 (GEN) | 5962-8988303ZA |
| EDI88512CA12NB | 5962-9560016QUA | EDI88512LPA25F32B | 5962-9560007M9A | 8908CA45 (GEN) | 5962-8988302XA |
| EDI88512LPA12CB | 5962-9560015QXA | EDI88512LPA25L32B | 5962-9560007MZA | 8908CA45 (GEN) | 5962-8988302YA |
| EDI88512LPA12F32B | 5962-9560015Q9A | EDI88512CA25F36B | 5962-9560003MTA | 8908CA45 (GEN) | 5962-8988302ZA |
| EDI88512LPA12F36B | 5962-9560015QTA | EDI88512CA25N36B | 5962-9560003MMA | 8908CA55 (GEN) | 5962-8988301XA |
| EDI88512LPA12L32B | 5962-9560015QZA | EDI88512LPA25F36B | 5962-9560007MTA | 8908CA55 (GEN) | 5962-8988301YA |
| EDI88512LPA12N36B | 5962-9560015QMA | EDI88512LPA25N36B | 5962-9560007MMA | 8908CA55 (GEN) | 5962-8988301ZA |
| EDI88512LPA12NB | 5962-9560015QUA | EDI88512CA35CB | 5962-9560002MXA | HSDC-8915 (GEN) | 5962-9055402XA |
| EDI88512CA15CB | 5962-9560014QXA | EDI88512CA35NB | 5962-9560002MUA | HSDC-8915A (GEN) | 5962-9055401XA |
| EDI88512CA15F32B | 5962-9560014Q9A | EDI88512LPA35CB | 5962-9560006MXA | HSDC-8917II-1 (GEN) | 5962-9070702HYA |
| EDI88512CA15F36B | 5962-9560014QTA | EDI88512LPA35CB | 5962-9560010QXA | HSDC-8917II-1A (GEN) | 5962-9070701HYA |
| EDI88512CA15L32B | 5962-9560014QZA | EDI88512LPA35F32B | 5962-9560010Q9A | HSDC-8919II-1 (GEN) | 5962-9070704HYA |
| EDI88512CA15N36B | 5962-9560014QMA | EDI88512LPA35F36B | 5962-9560010QTA | HSDC-8919II-1A (GEN) | 5962-9070703HYA |
| EDI88512CA15NB | 5962-9560014QUA | EDI88512LPA35L32B | 5962-9560010QZA | HSDC8920 (GEN) | 5962-8768701XA |
| EDI88512LPA15CB | 5962-9560013QXA | EDI88512LPA35N36B | 5962-9560010QMA | LMA9K (GEN) | 5962-95B0102M4C |
| EDI88512LPA15F32B | 5962-9560013Q9A | EDI88512LPA35NB | 5962-9560006MUA | LMA9K (GEN) | 5962-95B0102M5C |
| EDI88512LPA15F36B | 5962-9560013QTA | EDI88512LPA35NB | 5962-9560010QUA | LMA9K (GEN) | 5962-95B0102M6C |
| EDI88512LPA15L32B | 5962-9560013QZA | EDI88512CA35B32B | 5962-9560002MYA | LMA9K (GEN) | 5962-95B0102M7C |
| EDI88512LPA15N36B | 5962-9560013QMA | EDI88512CA35F32B | 5962-9560002M9A | LMA9K (GEN) | 5962-95B0102M8C |
| EDI88512LPA15NB | 5962-9560013QUA | EDI88512CA35L32B | 5962-9560002MZA | LMA9K (GEN) | 5962-95B0102M9C |
| EDI88512CA20CB | 5962-9560004MXA | EDI88512LPA35B32B | 5962-9560006MYA | LMA9K (GEN) | 5962-95B0102MCC |
| EDI88512CA20NB | 5962-9560004MUA | EDI88512LPA35F32B | 5962-9560006M9A | LMA9K (GEN) | 5962-95B0102MMC |
| EDI88512LPA20CB | 5962-9560008MXA | EDI88512LPA35L32B | 5962-9560006MZA | LMA9K (GEN) | 5962-95B0102MNC |
| EDI88512LPA20CB | 5962-9560012QXA | EDI88512CA35F36B | 5962-9560002MTA | LMA9K (GEN) | 5962-95B0102MTC |
| EDI88512LPA20F32B | 5962-9560012Q9A | EDI88512CA35N36B | 5962-9560002MMA | LMA9K (GEN) | 5962-95B0102MUC |
| EDI88512LPA20F36B | 5962-9560012QTA | EDI88512LPA35F36B | 5962-9560006MTA | LMA9K (GEN) | 5962-95B0102MXC |
| EDI88512LPA20L32B | 5962-9560012QZA | EDI88512LPA35N36B | 5962-9560006MMA | LMA9K (GEN) | 5962-95B0102MYC |
| EDI88512LPA20N36B | 5962-9560012QMA | EDI88512CA45CB | 5962-9560001MXA | LMA9K (GEN) | 5962-95B0102MZC |
| EDI88512LPA20NB | 5962-9560008MUA | EDI88512CA45NB | 5962-9560001MUA | LMF90 (GEN) | 5962-9096801MCA |
| EDI88512LPA20NB | 5962-9560012QUA | EDI88512LPA45CB | 5962-9560005MXA | OP90A (GEN) | 5962-8989601PA |
| EDI88512CA20B32B | 5962-9560004MYA | EDI88512LPA45CB | 5962-9560009QXA | OP90ARC/883 | 5962-89896012A |
| EDI88512CA20F32B | 5962-9560004M9A | EDI88512LPA45F32B | 5962-9560009Q9A | AD9000 (GEN) | 5962-89900013A |
| EDI88512CA20L32B | 5962-9560004MZA | EDI88512LPA45F36B | 5962-9560009QTA | AD9000 (GEN) | 5962-8990001EA |
| EDI88512LPA20B32B | 5962-9560008MYA | EDI88512LPA45L32B | 5962-9560009QZA | AD9002SD/883B | 5962-9050801MXA |
| EDI88512LPA20F32B | 5962-9560008M9A | EDI88512LPA45N36B | 5962-9560009QMA | AD9002SE/883B | 5962-9050801M3A |
| EDI88512LPA20L32B | 5962-9560008MZA | EDI88512LPA45NB | 5962-9560005MUA | AD9002TD/883B | 5962-9050802MXA |
| EDI88512CA20F36B | 5962-9560004MTA | EDI88512LPA45NB | 5962-9560009QUA | AD9002TE/883B | 5962-9050802M3A |
| EDI88512CA20N36B | 5962-9560004MMA | EDI88512CA45B32B | 5962-9560001MYA | DS90C031E-QML | 5962-9583301Q2A |
| EDI88512LPA20F36B | 5962-9560008MTA | EDI88512CA45F32B | 5962-9560001M9A | DS90C031WG-QML | 5962-9583301QZA |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

| Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN |
|---|---|---|---|---|---|
| DS90C031WG-QMLV | 5962-9583301VZA | 9064-15 (GEN) | 8201010EA | 93667-45 (GEN) | 8200903LA |
| DS90C031WGRQMLV | 5962R9583301VZA | AD9070T (GEN) | 5962-9756301HXC | 93667-55 (GEN) | 8200902LA |
| DS90C031W-QML | 5962-9583301QFA | ADC-908AX | 5962-8961601VA | HS9378 (GEN) | 5962-8986201XA |
| DS90C031W-QMLV | 5962-9583301VFA | ADC-908BX | 5962-8961602VA | HS9378 (GEN) | 5962-8986202XA |
| DS90C031WRQMLV | 5962R9583301VFA | ADC-908RC | 5962-89616022A | HS9403-16 (GEN) | 5962-8851402XA |
| DS90LV031AWGQML | 5962-9865101QXA | 8080A (GEN) | 7700201QX | HS9403-16 (GEN) | 5962-8851402YA |
| DS90LV031AW-QML | 5962-9865101QFA | AD9100SD (GEN) | 5962-9453501HXA | HS9403-8 (GEN) | 5962-8851401XA |
| DS90C032E-QML | 5962-9583401Q2A | EP910-20 (GEN) | 5962-9079903MQA | OM9422SFM | 5962-8877007HC |
| DS90C032WGLQMLV | 5962L9583401VZA | EP910-25 (GEN) | 5962-9079902MQA | ADS-944/883 | 5962-9319801HXA |
| DS90C032WG-QMLV | 5962-9583401QZA | EP910-30 (GEN) | 5962-9079901MQA | ADS-944/883 | 5962-9319801HXC |
| DS90C032WG-QMLV | 5962-9583401VZA | 9122-35 (GEN) | 5962-8859501KA | F9450-15 (GEN) | 8416901XA |
| DS90C032WLQMLV | 5962L9583401VFA | 9122-35 (GEN) | 5962-8859501WA | F9450-15 (GEN) | 8416901YA |
| DS90C032W-QML | 5962-9583401QFA | MN91253 (GEN) | 5962-9477402HXA | F9450-F15 (GEN) | 8416904XA |
| DS90C032W-QMLV | 5962-9583401VFA | MN91253 (GEN) | 5962-9477402HXC | F9450-F15 (GEN) | 8416904YA |
| DS90LV032AWGQML | 5962-9865201QXA | MN91254 (GEN) | 5962-9477401HXA | F9450-F18 (GEN) | 8416902XA |
| DS90LV032AW-QML | 5962-9865201QFA | MN91254 (GEN) | 5962-9477401HXC | F9450-F18 (GEN) | 8416902YA |
| AD9005B (GEN) | 5962-9066601HXA | 9128-12 (GEN) | 8103907JA | F9450-F20 (GEN) | 8416903XA |
| EP900-60 (GEN) | 5962-8854801QA | 9128-20 (GEN) | 8103908JA | F9450-F20 (GEN) | 8416903YA |
| HS0-9008RH-Q | 5962F9669601V9A | 9128-90 (GEN) | 8103906JA | SP9462 (GEN) | 5962-9579901HXA |
| HS-9008 (GEN) | 5962F9669601VXC | 9150-25 (GEN) | 5962-8759201KA | SP9463 (GEN) | 5962-9579902HXA |
| HS-9008 (GEN) | 5962F9669601VYC | 9150-25 (GEN) | 5962-8759201LA | SP9472 (GEN) | 5962-9579903HXA |
| HS-9008 (GEN) | 5962F9669601QXC | 9150-25 (GEN) | 5962-8759201XA | SP9473 (GEN) | 5962-9579904HXA |
| HS-9008 (GEN) | 5962F9669601QYC | 9150-35 (GEN) | 5962-8759202KA | HAA9-51150R4551 | 5962-97A0101VXC |
| TSS901EAMQ | 5962-01A1701QXC | 9150-35 (GEN) | 5962-8759202LA | HAA9-51154R4552 | 5962-97A1001VXC |
| TSS901EASV | 5962-01A1701VXC | 9150-35 (GEN) | 5962-8759202XA | HAA9-51155R4553 | 5962-97A0701VXC |
| AD9012S (GEN) | 5962-89654013A | 9150-45 (GEN) | 5962-8759203KA | HAA9-51156R4554 | 5962-97A0801VXC |
| AD9012SQ/883B | 5962-8965401XA | 9150-45 (GEN) | 5962-8759203LA | UT9Q512_QDIE | 5962L0053601Q9A |
| AD9012T (GEN) | 5962-89654023A | 9150-45 (GEN) | 5962-8759203XA | UT9Q512_QDIE | 5962L0053602Q9A |
| AD9012TQ/883B | 5962-8965402XA | HC9172 | 5962-9094301H3A | UT9Q512_QDIE | 5962L0053603Q9A |
| TSS902EAMQ | 5962-02A0701QXC | HC9172 | 5962-9094301H3C | UT9Q512_QDIE | 5962L0053604Q9A |
| TSS902EASV | 5962-02A0701VXC | 9241M (GEN) | 5962-9552504MRA | UT9Q512_TDIE | 5962L0053601T9A |
| 9020 (GEN) | 5962-9463701MYA | 9241U (GEN) | 5962-9552503MRA | UT9Q512_TDIE | 5962L0053602T9A |
| 9020 (GEN) | 5962-9463702MYA | 9241W (GEN) | 5962-9552502MRA | UT9Q512_TDIE | 5962L0053603T9A |
| AD9020SZ/883 | 5962-9463701MXC | 9241Y (GEN) | 5962-9552501MRA | UT9Q512_TDIE | 5962L0053604T9A |
| AD9020TZ/883 | 5962-9463702MXC | HS0-2422RH-Q | 5962-97A0501V9A | UT9Q512-ICA | 5962L0053601QXA |
| HAA9-03180R4556 | 5962-97A1101VXC | HS9-2422RH-Q | 5962-97A0501VXC | UT9Q512-ICA | 5962L0053601TXA |
| AD9040A (GEN) | 5962-9475901MYC | CLC925B (GEN) | 5962-9099501HXC | UT9Q512-ICA | 5962L0053603QXA |
| AD9040ATQ/883B | 5962-9475901MXA | HS0-2626RH-Q | 5962-97A0301V9A | UT9Q512-ICA | 5962L0053603TXA |
| AD9042SD/QMLR | 5962R0253801VXA | HS9-2626RH-Q | 5962-97A0301VXC | UT9Q512-ICC | 5962D0053601QXC |
| AD9042SD/QMLV | 5962-0253801VXA | ADS-927/883 | 5962-9475701HXA | UT9Q512-ICC | 5962D0053601TXC |
| AD9042SF/QMLR | 5962R0253801VZA | ADS-927/883 | 5962-9475701HXC | UT9Q512-ICC | 5962L0053601QXC |
| AD9042SF/QMLV | 5962-0253801VZA | HCTS93 (GEN) | 5962R9573701V9A | UT9Q512-ICC | 5962L0053601TXC |
| AD9048SE/883B | 5962-9092702M3A | HCTS93 (GEN) | 5962R9573701VCC | UT9Q512-ICC | 5962L0053603QXC |
| AD9048SQ/883B | 5962-9092702MXA | HCTS93 (GEN) | 5962R9573701VXC | UT9Q512-ICC | 5962L0053603TXC |
| AD9048TE/883B | 5962-9092701M3A | AD9300 (GEN) | 5962-9201401M2A | UT9Q512-ICCA | 5962D0053601QXA |
| AD9048TQ/883B | 5962-9092701MXA | AD9300 (GEN) | 5962-9201401MEA | UT9Q512-ICCA | 5962D0053601TXA |
| AD9058ATD/883B | 5962-9470301MXA | 93S16/BEA | 5962-8672701EA | UT9Q512-IWA | 5962L0053602QXA |
| AD9058ATJ/883B | 5962-9470301MYA | 93S16/BFA | 5962-8672701FA | UT9Q512-IWA | 5962L0053602TXA |
| AD9060S (GEN) | 5962-9158101MXC | SP9320 (GEN) | 5962-9561601MXA | UT9Q512-IWA | 5962L0053604QXA |
| AD9060S (GEN) | 5962-9158101MYA | HS9324 (GEN) | 5962-8862901XA | UT9Q512-IWA | 5962L0053604TXA |
| AD9060T (GEN) | 5962-9158102MXC | DM9328 (GEN) | 5962-9558501QEA | UT9Q512-IWC | 5962L0053602QXC |
| AD9060T (GEN) | 5962-9158102MYA | CLC935B (GEN) | 5962-9203901HXA | UT9Q512-IWC | 5962L0053602TXC |
| 9064-15 (GEN) | 8201009EA | 93CS66 (GEN) | 5962-9154901MPA | UT9Q512-IWC | 5962L0053604QXC |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART II, Listed By Generic PIN

| Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN | Vendor PIN | Drawing PIN |
|---|---|---|---|---|---|
| UT9Q512-IWC | 5962L0053604TXC | DS96F173MJ/883 | 5962-9076602MEA | 9862-075 | 5962-94A1801QXA |
| UT9Q512-QDIE | 5962D0053601Q9A | DS96F173MW/883 | 5962-9076602MFA | 9862-076 | 5962-94A1901QXA |
| UT9Q512-UCA | 5962L0053601QUA | DS96F174ME/883 | 5962-9076502M2A | 9862-079 | 5962-94A1701QXC |
| UT9Q512-UCA | 5962L0053601TUA | DS96F174MJ/883 | 5962-9076502MEA | 9863-027 | 5962-02A0101QXC |
| UT9Q512-UCA | 5962L0053603QUA | DS96F174MJ-QMLV | 5962-9076502VEA | 9864-006 | 5962-00A1001QXA |
| UT9Q512-UCA | 5962L0053603TUA | DS96F174MW/883 | 5962-9076502MFA | 9866-055 | 5962-94A1101QXC |
| UT9Q512-UCC | 5962D0053601QUC | DS96F175ME/883 | 5962-9076601M2A | 9868-056 | 5962-96A0801QXA |
| UT9Q512-UCC | 5962D0053601TUC | DS96F175MJ/883 | 5962-9076601MEA | 9868-062 | 5962-96A0901QXA |
| UT9Q512-UCC | 5962L0053601QUC | DS96F175MW/883 | 5962-9076601MFA | CF98700JD (GEN) | 5962-93A0201MXA |
| UT9Q512-UCC | 5962L0053601TUC | AD9618S (GEN) | 5962-9086803MPA | CF98702JD (GEN) | 5962-93A0301MXA |
| UT9Q512-UCC | 5962L0053603QUC | AD9618S (GEN) | 5962-9086803MXC | 9872-030 | 5962-96A1001QXA |
| UT9Q512-UCC | 5962L0053603TUC | AD9618T (GEN) | 5962-9086804MPA | 9880-025 | 5962-96A0401QXC |
| UT9Q512-UCCA | 5962D0053601QUA | AD9618T (GEN) | 5962-9086804MXC | 9880-026 | 5962-98A2201QXC |
| UT9Q512-UCCA | 5962D0053601TUA | DS9622 (GEN) | 5962-8752201AA | CF99004HFG | 5962-94A1201MYA |
| UT9Q512-UWA | 5962L0053602QUA | DS9622ME/883 | 5962-87522012A | AD9901T (GEN) | 5962-9097901M2A |
| UT9Q512-UWA | 5962L0053602TUA | DS9622MJ/883 | 5962-8752201CA | AD9901T (GEN) | 5962-9097901MCA |
| UT9Q512-UWA | 5962L0053604QUA | DS9627MJ/883 | 5962-8978701MEA | 9914A (GEN) | 5962-8751901QA |
| UT9Q512-UWA | 5962L0053604TUA | DS9636AJ/883 | 5962-8752301PA | 9914A (GEN) | 5962-8751901XA |
| UT9Q512-UWC | 5962L0053602QUC | DS9637AMJ/883 | 5962-8752401PA | AD10265 (GEN) | 5962R0151901TXA |
| UT9Q512-UWC | 5962L0053602TUC | DS9638J/883 | 5962-8754601PA | | |
| UT9Q512-UWC | 5962L0053604QUC | 96685 (GEN) | 86008042A | | |
| UT9Q512-UWC | 5962L0053604TUC | 96685 (GEN) | 8600804EA | | |
| UT9Q512K32-SCA | 5962L0151101QXA | 96685 (GEN) | 8600804IA | | |
| UT9Q512K32-SCA | 5962L0151101TXA | 96687 (GEN) | 78019032A | | |
| UT9Q512K32-SCC | 5962L0151101QXC | 96687 (GEN) | 7801903EA | | |
| UT9Q512K32-SCC | 5962L0151101TXC | AD9696 (GEN) | 5962-9234701MIA | | |
| 9513A/BQA | 5962-8552301QA | AD9696 (GEN) | 5962-9234701MPA | | |
| 9513A/BQA | 5962-8552301QA | AD9696 (GEN) | 5962-9234701MXC | | |
| 9513A/BUA | 5962-8552301XA | AD9696T (GEN) | 5962-9234703VHA | | |
| 9513A/BUA | 5962-8552301XA | AD9696T (GEN) | 5962-9234703VPA | | |
| 9517A (GEN) | 5962-8757501QA | AD9698 (GEN) | 5962-9234702MEA | | |
| 9517A-4 (GEN) | 5962-8757502QA | AD9698 (GEN) | 5962-9234702MYC | | |
| 9519A/BXA | 5962-8759701XA | OP-97A (GEN) | 5962-8954401GA | | |
| 9519A/BYA | 5962-8759701YA | OP-97AZ/883 | 5962-8954401PA | | |
| 9519A/XA | 5962-8759701XA | AD9712BS (GEN) | 5962-9091101M3A | | |
| 9519A/YA | 5962-8759701YA | AD9712BS (GEN) | 5962-9091101MXA | | |
| HS9576S (GEN) | 5962-9079501HXA | AD9712BT (GEN) | 5962-9091102M3A | | |
| HS9576S (GEN) | 5962-9079503HXA | AD9712BT (GEN) | 5962-9091102MXA | | |
| HS9576T (GEN) | 5962-9079502HXA | AD9713BS (GEN) | 5962-9091103M3A | | |
| HS9576T (GEN) | 5962-9079504HXA | AD9713BS (GEN) | 5962-9091103MXA | | |
| SP9588 (GEN) | 5962-9063101HXA | AD9713BTE (GEN) | 5962-9091104M3A | | |
| 96002-33 (GEN) | 5962-9315001MXA | AS9713BC28/883C | 5962-9091104MXA | | |
| AD9617S (GEN) | 5962-9086801MPA | HS9716 (GEN) | 5962-8956601HCA | | |
| AD9617S (GEN) | 5962-9086801MXC | HS9716 (GEN) | 5962-8956601HXA | | |
| AD9617T (GEN) | 5962-9086802MPA | AD9720 (GEN) | 5962-9306201M3A | | |
| AD9617T (GEN) | 5962-9086802MXC | AD9720 (GEN) | 5962-9306201MXA | | |
| 96F172 (GEN) | 5962-9076501MFA | AD9721 (GEN) | 5962-9306202M3A | | |
| DS96F172ME/883 | 5962-9076501M2A | AD9721 (GEN) | 5962-9306202MXA | | |
| DS96F172MJ/883 | 5962-9076501MEA | AD976ASD | 5962-9756401QXA | | |
| DS96F172MJ-QMLV | 5962-9076501VEA | SP9760 (GEN) | 5962-9063001HXA | | |
| DS96F173MJ-QMLV | 5962-9076602VEA | HS0-7687RH-Q | 5962-97A0601V9A | | |
| DS96F175MJ-QMLV | 5962-9076601VEA | HS9-7687RH-Q | 5962-97A0601VXC | | |
| DS96F173ME/883 | 5962-9076602M2A | AD977A (GEN) | 5962-9861401QRA | | |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART III, Listed Approved Sources 1/

| Vendor | Cage | Address | Point of Contact | Comment |
|---|---|---|---|---|
| ACTEL | 0J4Z0 | Actel Corporation<br>2061 Stierlin Court<br>Mountain View, CA 94043-4655 | Nawal Cotran<br>408-522-7522 | |
| ADV. ANALOG | 52467 | Advanced Analog, Inc.<br>2270 Martin Avenue<br>Santa Clara, CA 95050-2781 | Michael Sullivan<br>408-450-5824 | |
| AEROFLEX | 88379 | Aeroflex Plainview, Inc.<br>35 South Service Road<br>Plainview, NY 11803-4101 | | |
| AGILENT | 50434 | Agilent Technologies<br>Semiconductor Products Group<br>350 W. Trimble Rd.<br>San Jose, CA 95131 | | |
| AMI | 31471 | American Microsystems, Inc.<br>2300 Buckskin Road<br>Pocatello, ID 83201 | David Locke<br>208-234-6708 | |
| ANALOG (1) | 24355 | Analog Devices<br>Rt 1 Industrial Park<br>PO Box 9106<br>Norwood, MA 02062 | Paul Kramarz<br>781-461-3801 | |
| ANALOG (2) | 24355 | Analog Devices<br>Rt 1 Industrial Park<br>PO Box 9106<br>Norwood, MA 02062 | Al McEvoy<br>781-937-2673<br>804 Woburn Street<br>Wilmington, MA 01887-3462 | |
| ANALOG (3) | 24355 | Analog Devices<br>Rt 1 Industrial Park<br>PO Box 9106<br>Norwood, MA 02062 | Margie Flood<br>(35361)495999<br>Raheen Business Park<br>Limerick, Ireland | |
| ANALOG (4) | 24355 | Analog Devices<br>Rt 1 Industrial Park<br>PO Box 9106<br>Norwood, MA 02062 | Elaine Trotter<br>336-605-4234<br>7910 Triad Center Drive<br>Greensboro, NC 27409-9605 | |
| ANALOG (5) | 24355 | Analog Devices<br>Rt 1 Industrial Park<br>PO Box 9106<br>Norwood, MA 02062 | Bob Porter<br>408-562-7197<br>For class "V" devices contact:<br>Lawrence Lin<br>408-562-7167<br>1500 Space Park Drive<br>PO Box 58020<br>Santa Clara, CA 95050-8020 | |
| ANALOG (6) | 34031 | Analog Devices<br>7910 Triad Center Drive<br>Greensboro, NC 27409-9605 | Elaine Trotter<br>336-605-4234 | CAGE code 34031 manufactures QML-38534 hybrid products. |
| APEX MICRO. | 60024 | Apex Microtechnology Corporation<br>5980 North Shannon Road<br>Tucson, AZ 85741-5230 | 520-690-8600 | |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART III, Listed Approved Sources 1/

| Vendor | Cage | Address | Point of Contact | Comment |
|---|---|---|---|---|
| ATMEL | 1FN41 | Atmel Corp.<br>2325 Orchard Parkway<br>San Jose, CA 95131-1034 | Kathy White<br>408-436-4354 | |
| ATMEL GREN. | F8385 | Atmel Grenoble<br>Avenue De Rochepleine<br>Saint Egreve F-38120, France | Thales Components Corp.<br>(18778)<br>40G Commerce Way<br>Totowa, NJ 07511-0540 | |
| ATMEL NANTES | F7400 | Atmel Nantes,<br>part of Atmel Wireless and Microcontrollers<br>La Chantrerie BP 70602<br>44306 Nantes Cedex 3<br>France | | |
| AUSTIN SEMI. | 0EU86 | Austin Semiconductor Inc.<br>8701 Cross Park Dr.<br>Austin, TX 78754-4566 | Jeff Kendziorski<br>Marketing Manager<br>512-719-7267<br>Fax: 512-835-8358 | |
| BAE SYSTEMS | 1RU44 | BAE Systems<br>9300 Wellington Road<br>Manassas, VA 20110-4122 | Basil Jeffers<br>703-367-2594 | |
| CMAC MICRO. | K1672 | C-Mac Microelectronics, Ltd.<br>South Denes<br>Great Yarmouth<br>Norfolk NR30 3PX<br>England | Keith Watts, Application Manager<br>phone: +44 (0) 1493 743123<br>fax: +44 (0) 1493 858536 | |
| CYPRESS | 65786 | Cypress Semiconductor<br>3901 N. First Street<br>San Jose, CA 95134-1506 | | |
| DATEL | 50721 | Datel, Inc.<br>11 Cabot Boulevard<br>Mansfield, MA 02048-1151 | Bill Collins<br>508-339-3000 x190 | |
| DDC | 19645 | Data Device Corporation<br>105 Wilbur Place<br>Bohemia, NY 11716-2482 | | |
| DDC IRELAND | S7631 | DDC Ireland, Ltd.<br>Cork Business and Technology Park<br>Model Farm Road<br>Cork, Ireland | | |
| DPA LABS | 6S055 | DPA Laboratories<br>2251 Ward Ave.<br>Simi Valley, CA 93065 | Phil Young<br>805-581-9200 | |
| FAIRCHILD | 1HBD3 | Fairchild Semiconductor Corp<br>1215 South Grant Avenue<br>Loveland, CO 80537-6399 | | |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART III, Listed Approved Sources 1/

| Vendor | Cage | Address | Point of Contact | Comment |
|---|---|---|---|---|
| HOLT | 44270 | Holt Integrated Circuits, Inc.<br>23351 Madero<br>Mission Viejo, CA 92691-2730 | Jerry Donaldson<br>949-859-8800 | |
| HONEYWELL (1) | 34168 | Honeywell SSEC<br>MN14-3C12<br>12001 Hwy 55 West<br>Plymouth, MN 55441 | | |
| IDT | 61772 | Integrated Device Technology, Inc.<br>2975 Stender Way<br>Santa Clara, CA 95054 | | |
| INTER. RECT. | 69210 | International Rectifier<br>205 Crawford Street<br>Leominster, MA 01453-2353 | | |
| INTERPOINT | 50821 | Interpoint Corporation<br>10301 Willows Road<br>PO Box 97005<br>Redmond, WA 98073-9705 | | |
| INTERSIL | 34371 | Intersil Corporation<br>2401 Palm Bay Blvd<br>PO Box 883<br>Melbourne, FL 32902-0883 | Jean Seib<br>321-724-7034 | |
| LANSDALE | 58625 | Lansdale Semiconductor, Inc.<br>2412 W. Huntington Drive<br>Tempe, AZ 85282-3132 | Lee Mathiesen<br>602-438-0123x201 | |
| LATTICE SEMI | 66675 | Lattice Semiconductor Corp.<br>5555 NE Moore Court<br>Hillsboro, OR 97124-6421 | | |
| LINEAR TECH. | 64155 | Linear Technology Corp.<br>1630 McCarthy Blvd.<br>Milpitas, CA 95035-7417 | | |
| MAXIM INTEG. | 1ES66 | Maxim Integrated Products<br>120 San Gabriel Dr<br>Sunnyvale, CA 94086-5125 | Brian Dietsch<br>408-222-3424 | |
| MAXWELL | 68911 | Maxwell Technologies Electronics<br>Components Group, Inc.<br>9244 Balboa Ave.<br>San Diego, CA 92123 | | |
| MICREL | 60496 | Micrel, Inc.<br>1849 Fortune Drive<br>San Jose, CA 95131-1724 | Karen Jakabcin<br>408-944-0800 | |
| MICRO NETWKS | 50507 | Micro Networks Company<br>324 Clarke Street<br>Worcester, MA 01606-1293 | | |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART III, Listed Approved Sources 1/

| Vendor | Cage | Address | Point of Contact | Comment |
|---|---|---|---|---|
| MICRON TECH. | 6Y440 | Micron Technologies, Inc.<br>8000 S. Federal Way<br>Boise, ID 83707 | | |
| MICROPAC | 31757 | Micropac Industries, Inc.<br>Optoelectronics Division<br>905 East Walnut Street<br>Garland, TX 75040-6611 | | |
| MICROSEMI | 34333 | Microsemi Integrated Products<br>11861 Western Avenue<br>Garden Grove, CA 92641-1816 | David Harrison<br>714-372-8386 | |
| MINCO | 60264 | Minco Technology Labs, Inc.<br>1805 Rutherford Lane<br>Austin, TX 78754-5101 | | |
| MS KENNEDY | 51651 | M.S. Kennedy Corporation<br>4707 Dey Road<br>Liverpool, NY 13088 | Dan Miller<br>315-701-6751 | |
| NATEL | 09059 | Natel Engineering Co., Inc.<br>9340 Owensmouth Ave.<br>Chatsworth, CA. 91311 | | |
| NATIONAL | 27014 | National Semiconductor<br>2900 Semiconductor Dr<br>PO Box 58090<br>Santa Clara, CA 95052-8090 | Sandy Martinez<br>408-721-4767 | |
| NATIONAL HYB | 57363 | National Hybrid, Inc.<br>2200 Smithtown Avenue<br>Ronkonkoma, NY 11779-7329 | | |
| PYRAMID | 3DTT2 | Pyramid Semiconductor Corporation<br>1340 Bordeaux Drive<br>Sunnyvale, CA 94089 | Joe Rothstein<br>408-734-8200 | |
| QP SEMI | 0C7V7 | QP Semiconductor<br>2945 Oakmead Village Court<br>Santa Clara, CA 95051 | Bill Bennet<br>408-737-0992 ext.318 | |
| QUICKLOGIC | 0WGG | Quicklogic Corp.<br>1277 Orleans Drive<br>Sunnyvale, CA 94089-1138 | Macrina Gonzalez<br>408-990-4063 | |
| ROCHESTER | 3V146 | Rochester Electronics<br>10 Malcolm Hoyt Drive<br>Newburyport, MA 01950 | Lisa Mollarkey or Mike Gelsomini<br>978-462-9332 | |
| SARNOFF | 0DKS7 | Sarnoff, David Research Center<br>201 Washington Road<br>Princeton, NJ 08540-6449 | John Niemiec<br>609-734-2996<br>FAX-609-514-4044 | |
| SATCON | 27851 | Satcon Electronics<br>165 Cedar Hill Street<br>Marlborough, MA 01752 | Heather Gilchrist<br>508-485-6350x271 | |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART III, Listed Approved Sources 1/

| Vendor | Cage | Address | Point of Contact | Comment |
|---|---|---|---|---|
| SEMELAB | U3158 | Semelab PLC<br>Coventry Road, Lutterworth<br>Leicestershire LE174JB<br>United Kingdom | Steve Ellingworth / Damien Connolly<br>44 1455 556565 | |
| SENSITRON | 13409 | Sensitron Semiconductor<br>221 W. Industry Court<br>Deer Park, N.Y. 11729 | Marilyn Schroh<br>631-586-7600 ext.216 | |
| SILICONIX | 17856 | Siliconix, Inc.<br>2201 Laurelwood Road<br>Santa Clara, CA 95054-1516 | | |
| SIMTEK | 0HMW | Simtek Corporation<br>1465 Kelly Johnson Blvd.<br>Colorado Springs, CO 80920 | David G. Baudendistel<br>719-590-6511 | |
| SOLITRON | 21845 | Solitron Devices, Inc.<br>3301 Electronics Way<br>West Palm Beach, FL 33407-4697 | Joanne Crumbley<br>561-848-4311 x 282 | |
| STMICRO | F8859 | STMicroelectronics<br>3 rue de Suisse<br>BP4199<br>35041 RENNES cedex2-FRANCE | | |
| TELEDYNE | 16170 | Teledyne Electronic Technologies<br>12964 Panama Street<br>Los Angeles, CA 90066-6534 | | |
| TI | 01295 | Texas Instruments, Inc.<br>Semiconductor Group<br>8505 Forest Ln.<br>PO Box 660199<br>Dallas, TX 75243 | U.S. Highway 75 South<br>P.O. Box 84, M/S 853<br>Sherman, TX 75090-9493 | |
| UTMC | 65342 | Aeroflex Colorado Springs, Inc.<br>4350 Centennial Blvd.<br>Colorado Springs, CO 80907-3486 | | |
| VERTICAL | 0CET3 | Vertical Circuits Incorporated<br>19951 Mariner Avenue<br>Torrance, CA 90503 | | |
| VPT | 0ZBZ6 | VPT Incorporated<br>2801 Commerce Street<br>Blackburg, VA 24060-6657 | | |
| WHITE ELEC. | 54230 | White Electronic Designs Corp.<br>3601 E. University Drive<br>Phoenix, AZ 85034 | Marlene Maat<br>Director of Quality Assurance<br>602-437-1520 x121<br>Fax: 602-437-9307 | |
| XICOR | 60395 | Xicor, Inc.<br>1511 Buckeye Drive<br>Milpitas, CA 95035-7431 | | |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.

SECTION 1, MICROCIRCUITS
PART III, Listed Approved Sources 1/

| Vendor | Cage | Address | Point of Contact | Comment |
|---|---|---|---|---|
| XILINX | 68994 | Xilinx, Inc.<br>2100 Logic Drive<br>San Jose, CA 95124 | | |

1/ Since microcircuits supplied to SMDs may be manufactured both onshore and off-shore and often involve manufacturers with multiple facilities and production locations for various processes, the CAGE code shown represents the SMD product ship control location. An additional "point of contact" is shown when a military technical support group is available and when it differs from the SMD product ship control location.

Preparing activity

DLA-CC

(Project 5962-D775)

NOTE: The activities listed above were intrested in this document as of the date of this document. Since organizations and responsibilities can change, you should verify the currency of the information above using the ASSIST Online database at www.dodssp.daps.mil.



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:35Z
Check the source to verify that this is the current version before use.