MIL-A-46655B (MU)
30 APRIL 1965
SUPERSEDING
MIL-A-46655A (MU)
28 FEBRUARY 1964

MILITARY SPECIFICATION

ATTACHMENTS, TOW AND PUSH FOR DEMOLITION KIT, PROJECTED CHARGE, M157 PARTS FOR AND PACKING

1. SCOPE

1.1 This specification covers special requirements not covered by the drawings and quality assurance provisions for fabrication of handling and positioning equipment designated as Tow and Push Attachments for use with Demolition Kit, Projected Charge, M157.

2. APPLICABLE DOCUMENTS

2.1 The following documents of the issue in effect on date of invitation for bids or request for proposals form a part of this specification to the extent specified herein.

SPECIFICATIONS

FEDERAL

UU-T-106	— Masking Tape.
UU-T-111	— Tape, Paper, Gummed (Sealing and Securing).
MIL-P-116	— Preservation, Methods of.
PPP-B-621	— Boxes, Wood, Nailed and Lock-Corner.
PPP-B-636	— Boxes, Fiber.
PPP-C-843	— Cushioning Material, Cellulosic.

MILITARY

MIL-B-117	— Bags, Interior, Packaging.
MIL-B-121	— Barrier Material, Greaseproofed, Waterproofed, Flexible.
MIL-A-2550	— Ammunition and Special Weapons, General Specification for.
MIL-B-3106	— Board, Composition, Water - Resistant, Solid (for Filler and Cushioning Pads).
MIL-T-5021	— Tests, Aircraft Welding Operators Certification.
MIL-G-10924	— Grease, Automotive and Artillery.
MIL-F-26862	— Fiberboard, Solid, Dunnage, Multi-Purpose Cushioning and Blocking Applications.
MIL-I-45607	—Inspection Equipment, Supply and Maintenance of.

FSC 1375

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T06:35Z
Check the source to verify that this is the current version before use.

STANDARDS

FEDERAL

Federal Test Method Standard No. 51 — Metals, General Specification for Inspection of.

MILITARY

MIL-STD-105 — Sampling Procedures and Tables for Inspection by Attributes (ABC-STD-105).

MIL-STD-109 — Quality Assurance Terms and Definitions.

MIL-STD-129 — Marking for Shipment and Storage.

MIL-STD-171 — Finishing of Metal and Wood Surfaces.

MIL-STD-1167 — Ammunition Data Cards.

MIL-STD-1235 — Single and Multilevel Continuous Sampling Procedures and Tables for Inspection by Attributes.

DRAWINGS

ORDNANCE CORPS

8799689 — Wrench, Structural.

8799700 — Tow and Push Attachment Assembly.

8837375 — Picatinny Arsenal Environmental Testing Criteria for Shipping Containers.

PUBLICATIONS

ORDNANCE CORPS

IEL-8799700 — Index of Inspection Equipment Lists.

(Copies of specifications, standards, drawings and publications required by suppliers in connection with specific procurement functions should be obtained from the procuring activity or as directed by the contracting officer).

3. REQUIREMENTS

3.1 **Material.** Materials and parts shall be in accordance with applicable drawings and specifications.

3.2 **Tow and Push Attachments.** The tow and push attachments shall comply with all requirements specified on Drawing (dwg.) 8799700 and with all requirements specified in applicable specifications.

3.3 **Welding.** All welds shall be reasonably smooth and free of craters, cracks and other weld defects. They shall exhibit characteristics of good fusion, penetration and soundness of deposit representative of good welding practices. They shall be free of irregularities which indicate lack of skill or experience on the part of the operator. All scale and weld splatter shall be completely removed prior to application of protective coatings.

3.3.1 *Weld operator certification.* All fusion welding shall be performed by welders currently certified as Class A operators in accordance with Specification MIL-T-5021.

3.4 **Functioning of gear box assembly.** The gear box worm shall rotate the center spool assembly a minimum of 360 degrees in either direction and shall rotate the spool 1 inch, minimum, in the opposite direction, under a load of 2,000 pounds, minimum.

3.5 The button stop end shall comply with all requirements specified on Drawing (dwg.) 8799703 and all requirements specified in applicable specifications.

3.6 **Workmanship.** All parts and assemblies shall be fabricated and finished in a thorough, workmanlike manner. They shall be free of burrs, chips, sharp edges, distortion, dirt, grease, weld splatter, rust corrosion products and other foreign matter. The cleaning method used shall not be injurious to any part nor shall the parts be contaminated by the cleaning agent. Surface coatings shall be continuous except for a few light scratches not ex-

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T06:35Z
Check the source to verify that this is the current version before use.

posing base material. All required markings shall be neat and sharply defined.

4. QUALITY ASSURANCE PROVISIONS

4.1 General quality assurance provisions. Unless otherwise specified in the contract or purchase order, the supplier is responsible for the performance of all inspection requirements as specified herein. Except as otherwise specified, the supplier may utilize his own facilities or any commercial laboratory acceptable to the Government. The Government reserves the right to perform any of the inspections set forth in the specification where such inspections are deemed necessary to assure supplies and services conform to prescribed requirements. Reference shall be made to Standard MIL–STD–109 in order to define terms used herein. The provisions of Specification MIL–A–2550 shall apply.

4.1.1 *Submission of product.* At the time the completed lot of product is submitted to the Government for acceptance the contractor shall supply the following information accompanied by a certificate which attests that the information provided is correct and applicable to the product being submitted:

(a) A statement that the lot complies with all quality assurance provisions specified in this specification.

(b) Number of units of product inspected.

(c) Results obtained, by defect code, for all inspection performed.

(d) Drawing, specification number and date, together with an identification and date of changes.

(e) Statement of findings on all material purchased by the contractor when such material is controlled by Government specifications referenced in any of the contractual documents.

(f) Number of items in the lot.

(g) Date submitted.

The certificate shall be signed by a responsible agent of the certifying organization. The initial certificate submitted shall be substantiated by evidence of the agent's authority to bind his principal. Substantiation of the agent's authority will not be required with subsequent certificates unless, during the course of the contract, this authority is vested in another agent of the certifying organization.

4.1.2 *Government verification.* Using the contractor's written quality assurance procedure, this detail specification, the applicable drawings and other contractual documents as a guide, the Government inspector shall verify at unscheduled intervals all quality assurance operations performed by the contractor. Verification will be performed to the extent necessary to assure compliance with the contractual requirements. Severity of Government inspection of individual characteristics will be directly related to the seriousness of the classification assigned. In no instance will a characteristic classified "critical" be accepted solely on the basis of the contractor's records.

4.2 Initial production inspection.

4.2.1 *Submission.* Prior to the start of production, the contractor shall submit an initial production sample to a Government approved facility as designated by the contracting officer (see 6.4) for evaluation in accordance with the provisions of 4.2.2. The sample shall consist of 2 each of boxes 1 and 2 with contents and 2 complete sets of parts (i.e., 2 each of every individual component) which have been produced by the contractor or furnished by a supplier and which have been manufactured using the same production processes, procedures and equipment which will be used in fulfilling the contract. All parts and materials, including packaging and packing, shall be obtained from the same sources of supply as will be used in regular production. The sample shall be accompanied by

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T06:35Z
Check the source to verify that this is the current version before use.

statements of findings for materials. An initial production sample, or portion thereof, as directed by the contracting officer, shall also be submitted whenever there is a lapse in production for a period in excess of 90 days or whenever a change occurs in manufacturing process, material used, drawing, specification, or source of supply as to significantly affect product uniformity as determined by the Government. Prior to submission, the contractor shall inspect the sample to the degree necessary to assure that it conforms to the requirements of the contract and submit a record of this inspection with the sample. A sample containing known defects will not be submitted unless specifically authorized by the contracting officer.

4.2.2 *Inspections to be performed.* Assemblies and components will be subjected to any or all of the examinations or tests specified in 4.3.2 and 4.3.3.1 of this specification and any or all requirements of the applicable drawings.

4.2.3 *Rejection.* If any assembly or component fails to comply with any of the applicable requirements, the initial production sample shall be rejected. The Government reserves the right to terminate its inspection upon any failure of an assembly or component in the sample to comply with any of the stated requirements. In the event of rejection, the Government reserves the right to require the contractor to take corrective action and submit a new initial production sample, or portion thereof. Until an initial production sample is accepted, the contractor is, in no way, authorized by the Government to initiate regular production unless otherwise directed by the contracting officer.

4.3 **Inspection provisions.**

4.3.1 *Lot formation.* A lot shall consist of attachment assemblies produced by one manufacturer in one unchanged process, in accordance with the same drawing, same drawing revision, same specification, and same specification revision. Drawing, specification, and process changes not affecting safety, performance or fit, as determined by the Government shall not necessitate changing the lot interfix number.

4.3.2 *Examination.* Sampling plans and procedures for the following classifications of defects shall be in accordance with MIL–STD–105 (ABC–STD–105) except that inspection for critical defects, when listed, shall be 100 percent. Continuous sampling plans in accordance with MIL–STD–1235 may be used if approved by the procuring activity. Also, at the option of the procuring activity, AQL's and sampling plans may be applied to the individual characteristics listed using an AQL of 0.40 percent for each major defect and an AQL of 0.65 percent for each minor defect. Equipment necessary for the performance of the inspections listed shall be in accordance with 4.3.4.

4.3.2.1 Wrench, structural (see dwg. 8799689).

Categories	*Defects*	*Method of inspection*	*Code No. (see 6.2)*
Critical:	None defined		
Major:	AQL 0.40 percent		
101.	Distance between jaws	Gage	01001
Minor:	AQL 1.50 percent		
201.	Dimension, offset handle to jaws	Gage	01002
202.	Protective coating missing or damaged	Visual	01003
203.	Evidence of poor workmanship (see 3.6)	Visual	01004

4.3.2.2 Extension bar assembly (see dwg. 8799635 covering a detail of dwg. 8799700).

Categories	*Defects*	*Method of inspection*	*Code No.*
Critical:	None defined		

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T06:35Z
Check the source to verify that this is the current version before use.

Categories	Defects	Method of inspection	Code No.
Major:	AQL 0.65 percent		
101.	Diameter of hole, min.	Gage	02001
102.	Location and alignment of hole	Gage	02002
103.	Welding defect (see 3.3)	Visual	02003
Minor:	AQL 1.00 percent		
201.	Protective coating missing or damaged	Visual	02004
202.	Evidence of poor workmanship (see 3.6)	Visual	02005

4.3.2.3 Plate drag (see dwg. 8799640 covering a detail of dwg. 8799639).

Categories	Defects	Method of inspection	Code No.
Critical:	None defined		
Major:	AQL 0.40 percent		
101.	Diameter of hole, min.	Gage	03001
102.	Distance between holes	Gage	03002
Minor:	AQL 0.40 percent		
201.	Evidence of poor workmanship (see 3.6)	Visual	03003

4.3.2.4 Drag plate assembly (see dwg. 8799639 covering a detail of dwg. 8799700).

Categories	Defects	Method of inspection	Code No.
Critical:	None defined		
Major:	AQL 0.40 percent		
101.	Welding defect (see 3.3)	Visual	04001
Minor:	AQL 1.00 percent		
201.	Protective coating missing or damaged	Visual	04002
202.	Evidence of poor workmanship (see 3.6)	Visual	04003

4.3.2.5 Bracket, No. 1 (see dwg. 8799643 covering a detail of dwg. 8799642).

Categories	Defects	Method of inspection	Code No.
Critical:	None defined		
Major:	AQL 0.40 percent		
101.	Diameter of hole, min.	Gage	05001
102.	Location of hole	Gage	05002
Minor:	AQL 0.40 percent		
201.	Evidence of poor workmanship (see 3.6)	Visual	05003

4.3.2.6 Multiple sheave assembly (see dwg. 8799642 covering a detail of dwg. 8799700).

Categories	Defects	Method of inspection	Code No.
Critical:	None defined		
Major:	AQL 0.65 percent		
101.	Pulley does not move freely in either location or binds	Manual	06001
102.	Welding defect (see 3.3)	Visual	06002
103.	Cotter pin not spread	Visual	06003
Minor:	AQL 1.00 percent		
201.	Protective coating missing or damaged	Visual	06004
202.	Evidence of poor workmanship (see 3.6)	Visual	06005

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T06:35Z
Check the source to verify that this is the current version before use.

4.3.2.7 Bracket, No. 2 (see dwg. 8799652 covering a detail of dwg. 8799651).

Categories	Defects	Method of inspection	Code No.
Critical:	None defined		
Major:	AQL 0.40 percent		
101.	Diameter of hole, min.	Gage	07001
102.	Location of hole	Gage	07002
Minor:	AQL 0.40 percent		
201.	Evidence of poor workmanship (see 3.6)	Visual	07003

4.3.2.8 Single sheave assembly (see dwg. 8799651 covering a detail of dwg. 8799700).

Categories	Defects	Method of inspection	Code No.
Critical:	None defined		
Major:	AQL 0.65 percent		
101.	Pulley does not move freely or binds	Manual	08001
102.	Welding defect (see 3.3)	Visual	08002
103.	Cotter pin not spread	Visual	08003
Minor:	AQL 1.0 percent		
201.	Protective coating missing or damaged	Visual	08004
202.	Evidence of poor workmanship (see 3.6)	Visual	08005

4.3.2.9 Plate, support (see dwg. 8799659 covering a detail of dwg. 8799657).

Categories	Defects	Method of inspection	Code No.
Critical:	None defined		
Major:	AQL 0.40 percent		
101.	Diameter of hole, min.	Gage	09001
102.	Location of hole	Gage	09002
Minor:	AQL 0.40 percent		
201.	Evidence of poor workmanship (see 3.6)	Visual	09003

4.3.2.10 Base (see dwg. 8799658 covering a detail of dwg. 8799657).

Categories	Defects	Method of inspection	Code No.
Critical:	None defined		
Major:	AQL 0.40 percent		
101.	Diameter of hole, min.	Gage	10001
102.	Location of hole	Gage	10002
Minor:	AQL 0.65 percent		
201.	Evidence of poor workmanship (see 3.6)	Visual	10003

4.3.2.11 Frame, pulley (see dwg. 8799662 covering a detail of dwg. 8799657).

Categories	Defects	Method of inspection	Code No.
Critical:	None defined		
Major:	AQL 1.0 percent		
101.	Diameter of holes, min.	Gage	11001
102.	Location of holes	Gage	11002

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T06:35Z
Check the source to verify that this is the current version before use.

Categories	Defects	Method of inspection	Code No.
	103. I.D. dimension between flat surfaces after forming, min.	Gage	11003
	104. Linear formed length	Gage	11004
	105. Width of flat closed end, after forming	Gage	11005
	106. Location and alignment of holes, top and bottom flat after forming	Gage	11006
	107. Number of holes	Visual	11007
Minor:	AQL 1.0 percent		
	201. Protective coating inadequate	Visual	11008
	202. Evidence of poor workmanship (see 3.6)	Visual	11009

4.3.2.12 Pulley support post assembly (see dwg. 8799657 covering a detail of dwg. 8799700).

Categories	Defects	Method of inspection	Code No.
Critical:	None defined		
Major:	AQL 0.65 percent		
	101. Pulley does not move freely or binds	Manual	12001
	102. Component missing	Visual	12002
	103. Welding defect (see 3.3)	Visual	12003
Minor:	AQL 1.00 percent		
	201. Protective finish missing or damaged	Visual	12004
	202. Evidence of poor workmanship (see 3.6)	Visual	12005

4.3.2.13 Chain assembly No. 1 (see dwg. 8799665 covering a detail of dwg. 8799700).

Categories	Defects	Method of inspection	Code No.
Critical:	None defined		
Major:	AQL 0.40 percent		
	101. Component missing	Visual	13001
	102. Cotter pin not spread	Visual	13002
Minor:	AQL 1.50 percent		
	201. Overall length of (%) chain min.	Gage	13003
	202. Groove weld inadequate large links	Visual	13004
	203. Protective finish or coating missing or inadequate	Visual	13005
	204. Evidence of poor workmanship (see 3.6)	Visual	13006

4.3.2.14 Chain assembly, No. 2 (see dwg. 8799667 covering a detail of dwg. 8799700).

Categories	Defects	Method of inspection	Code No.
Critical:	None defined		
Major:	AQL 1.0 percent		
	101. Linear length of chain & links min.	Gage	14001
	102. Component missing	Visual	14002
	103. Variation in chain link quantity	Visual	14003
	104. Variation in quantity (optional)	Visual	14004
	105. Weld inadequate	Visual	14005
Minor:	AQL 1.00 percent		
	201. Protective finish or coating missing or inadequate	Visual	14006
	202. Evidence of poor workmanship (see 3.6)	Visual	14007

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T06:35Z
Check the source to verify that this is the current version before use.

4.3.2.15 Spring assembly (see dwg. 8799673 covering a detail of dwg. 8799700).

Categories	Defects	Method of inspection	Code No.
Critical:	None defined		
Major:	AQL 0.40 percent		
101.	Component missing	Visual	15001
Minor:	None defined		

4.3.2.16 Pin (see dwg. 8799691 covering a detail of dwg. 8799690).

Categories	Defects	Method of inspection	Code No.
Critical:	None defined		
Major:	AQL 0.40 percent		
101.	Large outside diameter, max.	Gage	16001
Minor:	AQL 1.00 percent		
201.	Location of either hole	Gage	16002
202.	Total length	Gage	16003

4.3.2.17 Clevis pin assembly (see dwg. 8799690 covering a detail of dwg. 8799700).

Categories	Defects	Method of inspection	Code No.
Critical:	None defined		
Major:	AQL 0.65 percent		
101.	Component missing or improper	Visual	17001
102.	Cotter pin not spread	Manual	17002
103.	Fastener pin fails to enter hole and be locked in place	Manual	17003
Minor:	None defined		

4.3.2.18 Cable No. 1 and Cable No. 2 (see dwg. 8799706 and 8799703 covering details of dwg. 8799700).

Categories	Defects	Method of inspection	Code No.
Critical:	None defined		
Major:	AQL 2.50 percent		
101.	End of cable improperly tinned	Visual-Gage	18001
102.	Thimble missing or improperly assembled	Visual-Manual	18002
103.	Nut loose	Visual-Manual	18003
104.	Hook safety snap missing or improperly assembled	Visual	18004
105.	Position of U bolt reversed	Visual	18005
106.	Tape missing or improperly applied	Visual	18006
107.	Button stop end missing or improperly swaged (cable No. 2)	Visual-Manual	18007
Minor:	None defined		

4.3.2.19 Housing assembly (see dwg. 8799834 covering a detail of dwg. 8799833).

Categories	Defects	Method of inspection	Code No.
Critical:	None defined		

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T06:35Z
Check the source to verify that this is the current version before use.

Categories	Defects	Method of inspection	Code No.
Major:	AQL 1.0 percent		
101.	Surface of blocks not parallel to each other	Gage	19001
102.	Length	Gage	19002
103.	Width	Gage	19003
104.	Height	Gage	19004
105.	Welding defect (see 3.3)	Visual	19005
106.	Operation omitted	Visual	19006
Minor:	AQL 1.5 percent		
201.	Cable guide missing	Visual	19007
202.	Protective coating missing or damaged	Visual	19008
203.	Paint inside holes	Visual	19009
204.	Evidence of poor workmanship (see 3.6)	Visual	19010

4.3.2.20 Gear box assembly, prior to assembly of top plate (see dwg. 8799833 covering a detail of dwg. 8799700).

Categories	Defects	Method of inspection	Code No.
Critical:	None defined		
Major:	AQL 1.0 percent		
101.	Worm and gear spool, not mating	Visual	20001
102.	Taper pin hole not aligned with assembled shaft and worm	Manual-Visual	20002
103.	Worm gear pin not peened	Visual	20003
104.	Any gear shaft snap ring missing	Visual	20004
105.	Cotter pin missing	Visual	20005
106.	Operation omitted	Visual	20006
Minor:	AQL 1.5 percent		
201.	Sealing compound missing or improper	Visual	20007
202.	Grease missing or improper	Visual	20008
203.	Evidence of poor workmanship (see 3.6)	Visual	20009

4.3.2.21 Gear box assembly (see dwg. 8799833 covering a detail of dwg. 8799700).

Categories	Defects	Method of inspection	Code No.
Critical:	None defined		
Major:	AQL 0.40 percent		
101.	Assembly damaged	Visual	21001
102.	External component missing	Visual	21002
Minor:	AQL 1.00 percent		
201.	Protective coating damaged	Visual	21003
202.	Evidence of poor workmanship (see 3.6)	Visual	21004

4.3.2.22 Socket, short (see dwg. 8799685 covering a detail of dwg. 8799675).

Categories	Defects	Method of inspection	Code No.
Critical:	None defined		
Major:	AQL 0.65 percent		
101.	Distance across flats	Gage	22001
102.	Diameter of bolt cavity	Gage	22002
103.	Depth of bolt cavity	Gage	22003
Minor:	None defined		

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T06:35Z
Check the source to verify that this is the current version before use.

4.3.2.23 Socket, long (see dwg. 8799687 covering a detail of dwg. 8799675).

Categories	Defects	Method of inspection	Code No.
Critical:	None defined		
Major:	AQL 0.65 percent		
101.	Distance across flats	Gage	23001
102.	Diameter of bolt cavity	Gage	23002
103.	Depth of bolt cavity	Gage	23003
Minor:	None defined		

4.3.2.24 Carton, unsealed (see 5.1).

Categories	Defects	Method of inspection	Code No.
Critical:	None defined		
Major:	AQL 0.65 percent		
101.	Component missing (when applicable)	Visual-Manual	24001
102.	Insufficient packing material	Visual-Manual.	24002
103.	Improper wrapping of component	Visual	24003
Minor:	None defined		

4.3.2.25 Carton, sealed (see 5.1).

Categories	Defects	Method of inspection	Code No.
Critical:	None defined		
Major:	AQL 0.65 percent		
101.	Corner not blunted (when applicable)	Visual	25001
102.	Seal not secure	Manual	25002
103.	Contents loose when inverted	Manual	25003
Minor:	AQL 0.40 percent		
201.	Marking missing, misleading or unidentifiable	Visual	25004

4.3.2.26 Carton in sealed barrier bag (see 5.1).

Categories	Defects	Method of inspection	Code No.
Critical:	None defined		
Major:	AQL 0.40 percent		
101.	Bag punctured, cut or improperly sealed	Visual-Manual	26001
102.	Insufficient area for subsequent seals	Visual	26002
Minor:	AQL 0.40 percent		
201.	Marking missing, misleading or unidentifiable	Visual	26003

4.3.2.27 Wood box, sealed (see 5.2).

Categories	Defects	Method of inspection	Code No.
Critical:	None defined		
Major:	AQL 0.65 percent		
101.	Contents exposed	Visual	27001
102.	FSC number missing or misleading	Visual	27002

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T06:35Z
Check the source to verify that this is the current version before use.

Categories	Defects	Method of inspection	Code No.
	103. Board broken	Visual	27003
	104. Strapping missing, broken or loose	Visual-Manual	27004
Minor:	AQL 1.00 percent		
	201. Marking missing, misleading or unidentifiable	Visual	27005
	202. Strapping improperly located	Visual	27006

4.3.3 *Testing.*

4.3.3.1 *Initial production* (see 4.2.1). The samples submitted as the initial production quantity shall be tested as specified below after having been examined for all other drawing requirements. Rejection and resubmission shall be in accordance with 4.2.3.

4.3.3.1.1 Length of spring under load (see dwg. 8799673 and 4.4.2) — Code No. 15002.

4.3.3.1.2 Initial tension and gross load of spring (see dwg. 8799673 and 4.4.2) — Code Nos. 15002 and 15003.

4.3.3.1.3 Functioning of gear box assembly (see 3.4 and 4.4.1) — Code No. 29001.

4.3.3.1.4 *Wood boxes ready for shipment* (see 4.2.1). The boxes shall be submitted to the cornerwise test of dwg. 8837375. Internal blocking and content shall be undamaged after test.

4.3.3.1.5 Pull stop of button, stop end (see 3.5 and 4.4.3) — Code No. 18008.

4.3.3.1.6 Brinell Hardness, worm modified (see 4.2.1 and dwg. 8799851) — Code No. 28001; Gear (see 4.2.1 and dwg. 8885185) — Code No. 28002.

4.3.3.2 *Production testing.*

4.3.3.2.1 Length of spring under load (see dwg. 8799673) — Major defect — Code No. 15002. A sample of 4 springs shall be selected from each heat treatment batch for this test. Testing shall be as specified in 4.4.2. Failure of one or more units of the sample in meeting the requirement shall reject the batch.

4.3.3.2.2 Initial tension and gross load of spring (see dwg. 8799673) — Major defect — Code No. 15002 and 15003. An accepted sample selected for 4.3.3.2.1 may be used for this test which shall be performed as specified in 4.4.2. Failure of one or more units of the sample in meeting either requirement shall reject the batch.

4.3.3.2.3 Functioning of gear box assembly (see 3.4) — Major defect — Code No. 29001. This determination shall be performed 100 percent as specified in 4.4.1. Any unit failing to function as required shall be classed defective and removed from the lot subject to repair and resubmission to test.

4.3.3.2.4 Pull stop of button, stop end (see 3.5) — Major defect — Code No. 18008. A sample of ten (10) cables, No. 2 shall be selected from each lot for this test. Testing shall be as specified in 4.4.3 using test equipment as specified in 4.3.4. Failure of one or more units of the sample in meeting the requirement shall reject the lot, subject to 100% testing.

4.3.3.2.5 Brinell hardness of worm, modified (see dwg. 8799851) — Major defect — Code No. 28001. A sample of ten (10) modified worms shall be selected from each lot for this test. Testing shall be as specified in 4.4.4 using test equipment as specified in 4.3.4. Failure of one or more units of the sample in meeting the requirements shall reject the lot; subject to 100% testing.

4.3.3.2.6 Brinell hardness of gear (see dwg. 8885185) — Major defect — Code No. 28002. A sample of ten (10) gears shall be selected from each lot for this test. Testing shall be as specified in 4.4.4 using test equipment as

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T06:35Z
Check the source to verify that this is the current version before use.

specified in 4.3.4. Failure of one or more units of the sample in meeting the requirements shall reject the lot; subject to 100% testing.

4.3.4 *Inspection Equipment.* Index of Inspection Equipment Number IEL–8799700 identifies the inspection equipment required to perform the examinations and tests prescribed in this section. The contractor shall design inspection equipment in accordance with the instructions in paragraph 6.3.

4.3.4.1 *Government rights to documentation.* Inspection equipment drawings and lists provided and revised in accordance with the requirements of the IEL may be used by DOD activities for design, procurement, manufacture, testing, evaluation, production and receiving inspection, overhaul, shipping, storage, identification of stock, ordering and storage of replacement parts, inspection of items at overhaul, general maintenance of equipment, construction, survey and whenever inspection equipment drawings are needed.

4.3.4.2 *Supply and maintenance.* Supply and maintenance of the equipment listed on the IEL shall be in accordance with Specification MIL–I–45607.

4.3.4.3 *Government use of contractor's inspection and test equipment.* The contractor shall make available to the Government all inspection and test equipment necessary for determining conformance with contract requirements. Personnel for operating the equipment and verification of its accuracy, shall be supplied by the contractor for the performance of examination or test by the Government.

4.4 Test methods and procedures.

4.4.1 *Functioning of gear box assembly under load.* The gear box shall be mounted in the applicable test equipment and specified load shall be applied. A mark shall be placed on the center spool assembly to facilitate determination of 360 degree rotation. The free wrench assembly shall be activated back and forth. If the main shaft does not rotate, the knurled handle of the stationary wrench assembly shall be rotated 180 degrees. Activation of the free wrench assembly shall then rotate the shaft and the center spool assembly. This shall be continued until the mark on the spool assembly rotates to the starting point. The knurled handle of the free wrench shall be rotated 180 degrees and activation of the wrench attempted. If effected, the stationary wrench is defective. If no action occurs, the setting of the stationary wrench shall be reversed, the free wrench activated and the spool assembly shall be moved in the reverse position for the required distance. Any assembly failing to function as required shall be classed defective.

4.4.2 *Spring loads.* This test may be performed either by suspending the spring and attaching the required weight or the load may be applied using a universal type testing machine. Observation shall be made for compliance with the applicable requirement. Any unit failing to meet all requirements shall be classed defective.

4.4.3 *Pull stop.* This test shall be performed by securely affixing the button stop end to the applicable test equipment specified in 4.3.4. The specified force shall be applied. Any unit which separates shall be classed defective.

4.4.4 *Brinell hardness.* This test shall be performed by using the applicable test equipment specified in 4.3.4. Any unit failing to meet the specified requirements shall be classed defective.

5. PREPARATION FOR DELIVERY

5.1 Preservation and packaging.

5.1.1 *Level A.*

5.1.2 *Cleaning.* All metallic parts shall be cleaned by Method C–1, MIL–P–116.

5.1.3 *Preservation.* All open bearings of the gear box shall be charged with preservative

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T06:35Z
Check the source to verify that this is the current version before use.

grease conforming to Specification MIL–G–10924.

5.1.3.1 *Preservation.* Parts shall be painted, plated or preserved in accordance with the requirements specified on the item drawing. Exterior bare metal surfaces shall be preserved with P–1, MIL–P–116 preservative or touched up with a paint or primer the same as contained on the item.

5.1.4 *Packaging.* The gear box shall be wrapped in barrier paper conforming to MIL–B–121, Type II, Class 2, Grade A and placed in a corrugated carton, PPP–B–636, Type I, Style RSC constructed of fiberboard having a minimum bursting strength of 200 p.s.i. Additional cushioning material conforming to PPP–C–843, Type 2, Class B, shall be added as required for a tight pack. The carton shall be closed and sealed by applying 2 inch wide gummed, kraft tape, UU–T–111, Class 2 over the top and bottom center seams with a minimum 2 inch extension on to the end panels. The corners of the carton shall be blunted and the carton inserted into a barrier bag conforming to Specification MIL–B–117, Type I or II, Class e. Excess air shall be exhausted from the bag opening closed by heat sealing. Sealed bags shall meet the heat seal test specified in MIL–P–116.

Component parts listed below, shall be individually wrapped in MIL–B–121, Type II, Class 2, Grade A paper. The wrapper may be secured by application of UU–T–106 masking tape 1 inch width as required. Wrapped parts shall be placed in a corrugated fiberboard box and barrier bag in the same manner as described for the gear box. Sealed bags shall meet the heat sealed requirement of Specification MIL–P–116. Sufficient area shall be left at the sealed end to permit four subsequent seals. The components listed below shall be identified by drawing number and nomenclature on label or tag and shall be wrapped or cushioned to prevent damage and tightly packed in a fiberboard box with a barrier bag overwrap as detailed above. Carton and bag shall be identified by label on each.

Component Parts

Qty.	*Nomenclature*	*Dwg. No.*
1	Structural Wrench	8799689
1	Cable No. 1	8799706
1	Cable No. 2	8799703
1	Pulley Support Post Assembly	8799657
1	Multiple Sheave Assembly	8799642
2	Clevis Pin Assembly	8799690
2	Bolt Stripper	8799701
1	Spring Assembly	8799673
1	Single Sheave Assembly	8799651

5.2 Packing.

5.2.1 *Level A.* Component parts packaged as specified and additional parts not requiring packaging, shall be packed as indicated below in wooden boxes conforming to Specification PPP–B–621, Class 2, Style 2, 2½ or 4 for a Type 3 load. Boxes shall be strapped in accordance with the appendix of the box specification. Blocking or bracing required shall conform to the box requirement of lumber or MIL–F–26862 for fibrous material. Blocking in the boxes shall conform to that meeting the drop test requirements of the initial production lot.

Box No.	*Qty.*	*Dwg. No.*	*Item*
1	2	8799635	Extension Bar
1	1	8799665	Chain Assy. No. 1
1	1	8799667	Chain Assy. No. 2
2	1	8799639	Drag Plate Assy.
2	1	8799833	Gear Box
2	1	Various	Component Parts Package

5.3 Marking. Each unit and exterior container and bulk packed item shall be marked in accordance with the requirements of MIL–STD–129. Bagged items shall have the interior box and bag identified.

5.4 Data cards. Data card information shall be as specified in Specification MIL–STD–1167.

6. NOTES

6.1 Ordering data. Procurement documents shall specify title, number and date of this specification.

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T06:35Z
Check the source to verify that this is the current version before use.

6.2 **Inspection code numbers.** The five digit code numbers assigned to the inspections herein are to facilitate future data collection and analysis by the Government.

6.3 **Inspection equipment.** The contractor shall design inspection equipment as required by the referenced Inspection Equipment Lists (IEL) in accordance with the instructions of paragraphs 6.3.1 through 6.3.7.

6.3.1 *Inspection equipment lists.* Inspection equipment lists indicate the availability of inspection equipment designs by showing in the "number" column of the list of inspection equipment (00 Form 1242-3) the numbers of drawings of existing equipment designs or codes as indicated in paragraph 6.3.2. Design action required of the contractor with respect to the different types of drawings that may be listed is described in paragraphs 6.3.3 and 6.3.4. Action required by the contractor with respect to commercial inspection equipment is described in 6.3.5. The contractor will be required to prepare detailed drawings in accordance with 6.3.6 for all the equipment coded as "Contractor Design" in the number column. These contractor designs must be approved by the Government prior to fabrication of procuring of the equipment. Designs shall be submitted for approval as specified in 6.3.7.

6.3.2 *Inspection equipment list codes.* The inspection equipment as defined in 6.3.3, 6.3.4, 6.3.5 and 6.3.6 will be designed in the IEL by the following codes:

CDAF	—	Contractor's design responsibility on Army format in accordance with MIL-D-45608.
CDCF	—	Contractor's design responsibility on contractor format.
AD	—	Army design.
ADMU	—	Army design, mandatory for use.
CE	—	Commercial equipment.
SCD	—	Specification control drawing.

6.3.3 *Army designs.* Army designs are reflected on detailed drawings which completely depict all the information necessary for the fabrication of the item of inspection equipment. The contractor need provide no design when an Army design is listed for an item of inspection equipment. Army designs fall into two basic classifications, mandatory and non-mandatory. When an inspection equipment list references mandatory Army designs, the contractor shall comply with, and use these designs accordingly. The contractor may, however, in connection with non-mandatory designs and with the approval of the Government, design alternate inspection equipment or use comparable commercial equipment to facilitate his operations. Such contractor prepared designs or commercial equipment selections must be approved by the Government prior to fabrication or procuring of the equipment. Designs shall be submitted for approval as specified in 6.3.7.

6.3.4 *Specification control drawing.* Specification control drawings depict the minimum equipment requirements in outline, descriptive, diagrammatic or pictorial form only and specify the required performance or other characteristics. Contractors must prepare detailed drawings (see 6.3.6) of their designs in support of specification control drawings. These contractor prepared designs must be approved by the Government prior to the fabrication or procuring of the equipment. Commercial equipment meeting the requirements of specification control drawings may be approved if described in sufficient detail to permit identification and evaluation by the Government. Designs shall be submitted for approval as specified in 6.3.7.

6.3.5 *Commercial equipment.* Commercial equipment is inspection equipment that has universal application for a specific function. It is comprised of items commonly used by industry and Government. Contractors are not required to furnish drawings of commercial inspection equipment, but a list of such equipment must be approved by the Government. Lists shall be submitted for approval to the inspection element of the agency administering the contract.

6.3.6 *Contractor designs.* Contractor designs are designs of inspection equipment for which

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T06:35Z
Check the source to verify that this is the current version before use.

the Government has assigned design responsibility to the contractor. Contractor designs shall be supported by detailed drawings which depict all information necessary to completely fabricate, calibrate and operate an item of inspection equipment. This requires that the necessary views, dimensions, materials, finish, notes, operating and calibration instructions be properly depicted in accordance with approved practices to the extent that further calculation or clarification will not be required. Contractor designs identified as CDCF may be developed on the format the contractor normally employs in his equipment design procedure provided such format reflects the detail and information specified above. Contractor designs identified as CDAF shall comply with the format and requirements of MIL–D–45608, and in addition, contain the detail and information specified above.

6.3.7 *Submission of contractor designs.* Designs shall be submitted for approval to the Commanding officer, Picatinny Arsenal, ATTN: SMUPA–ND. Design review will normally be accomplished within one month after receipt by Picatinny Arsenal. Partial submission of inspection equipment designs is permissible and encouraged. However, the Arsenal completion date for design review will be based on the date of the final submission of designs.

6.4 Submission of initial production samples. Instructions, as to the location for the evaluation of the Initial Production Sample shall be obtained from the contracting officer. Upon receipt of such request, the contracting officer shall advise Picatinny Arsenal and instructions will be issued accordingly. All inquiries should be forwarded to: Commanding Officer, Picatinny Arsenal, ATTN: SMUPA–NI.

Custodian:
Army—MU

Preparing activity:
Army—MU
Project No. 1375–A898

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T06:35Z
Check the source to verify that this is the current version before use.