MIL-M-23346 (WEP)
Amendment 2
29 January 1965
Superseding
Amendment 1
December 29, 1964

MILITARY SPECIFICATION

MOTOR FIRE CONNECTOR ASSEMBLY

This amendment forms a part of Military Specification
MIL-M-23346 (WEP) dated 19 August 1964

Page 2, paragraph 2.1, under Drawings, add:

2516341	Head forward (For Mark 38 Mod 0 Rocket Motor)

Page 2, paragraph 2.1, immediately following LD 614000, add:

2.2 Other Publications. The following documents form a part of this specification to the extent specified herein. Unless otherwise specified, the issue in effect on date of invitation for bids shall apply.

CD 2435661	Motor Fire Connector Assembly

Page 4, paragraph 3.2.7, delete and substitute:

3.2.7 Renewal of Preproduction Sample. In the event that there have been major changes or if production has been interrupted such that in the opinion of the procuring activity adverse effects on the motor fire connector may result, an additional preproduction sample may be required.

Page 5, paragraph 4.4, lines 5 and 6, delete "Bureau of Naval Weapons" and substitute "procuring activity".

Page 6, paragraph 4.4.2.5, delete "2435639" and substitute "2516341".

Page 6, paragraph 4.4.3, lines 4 and 5, delete "Chief of the Bureau of Naval Weapons" and substitute "procuring activity".

Page 6, paragraph 4.5.1, delete and substitute:

Source: https://assist.dla.mil -- Downloaded: 20260-19T16:28Z
Check the source to verify that this is the current version before use.

4.5.1 Production Acceptance. Unless otherwise specified, sampling for inspection of major and minor defects listed on CD 2435661 shall be in accordance with MIL-STD-105, Inspection Level II. The AQL's shall be as follows:

(a) Major: 1.0%
(b) Minor: 2.5%

Source: https://assist.dla.mil -- Downloaded: 202610-19T16:28Z
Check the source to verify that this is the current version before use.