INCH-POUND

MIL-A-48607B (AR)
AMENDMENT 1
12 June 1992

MILITARY SPECIFICATION

AMPLIFIER, DOPPLER ASSEMBLY: 11740261

This Amendment forms a part of Military Specification MIL-A-48607B (AR), dated 18 January l991, and is approved 'or use by the U.S. Army Armarnent Munitions and Chemical Command, and is available for use by all Departments and Agencies of the Department of Defense.

PAGE 2

2.1.1, Delete the following military standard:

"MIL-STD-2000 - Standard Requirements for Soldering Electrical and Electronic Assemblies"

2.1.2, Add the following drawing:

"12950877 - Requirements for Soldering Electrical and Electronic Assemblies"

PAGE 3

Delete paragraph 3.3.1 in its entirety and substitute:

"3.3.1 Vibration The doppler amplifier shall not suffer damage and shall meet the requirements of 3.4 and 3.5 after exposure to the equivalent of 6000 miles of track-laying vehicle operational vibration as defined by MIL-STD-810 narrowband random-on-random data for equipment installed on the deck of the M113 armored personnel carrier."

Delete paragraph 3.3.3 in its entirety and substitute:

"3.3.3 Altitude operating The doppler amplifier shall meet the requirements of 3.4 and 3.5 during and after exposure to barometric pressure encountered at 10,000 feet above sea level (20.6 inches of Hg)."

Delete paragraphs 3.3.3.1 and 3.3.3.2 in their entirety.

DISTRIBUTION STATEMENT A. Approved for public release; distribution is unlimited.

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:33Z
Check the source to verify that this is the current version before use.

PAGE 5

Delete paragraph 3.7 in its entirety and substitute:

"3.7 soldering. All soldering shall be in accordance with the requirements of Note 2 of Drawing 12950877."

PAGE 11

4.7.1.1, Change "Procedure 1, of MIL-STD-810 as modified by paragraph 3.3.1 herein" to "Procedure I, of MIL-STD-810 and paragraph 3.3.1 herein".

Delete paragraph 4.7.1.3 in its entirety and substitute:

"4.7.1.3 Altitude operating. This test shall be performed as specified in Procedure II, Method 500, of MIL-STD-810. The operational checkout shall be as specified in 4.7.2 and 4.7.3 for compliance with 3.3.3."

PAGE 14

Delete paragraph 4.8 in its entirety and substitute:

"4.8 soldering. Soldering processes shall be inspected by certified inspectors to the requirements and acceptance criteria of Note 2 of Drawing 12950877 as specified in paragraph 3.7."

Custodian:
Army-AR

Preparing activity:
Army-AR

(Project 1285-A808)

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:33Z
Check the source to verify that this is the current version before use.