**INCH-POUND**

**MIL-DTL-44427A**
**28 February, 2000**
**----------**
**SUPERSEDING**
**MIL-T-44427**
**29 July, 1991**

DETAILED SPECIFICATION

# TENT, SOLDIER CREW

This specification is approved for use by all Departments and Agencies of the Department of Defense.

## 1. SCOPE

1.1 Scope. This specification covers two types of a frame supported soldier crew tent equipped with a frame, tent, pins, liner, fly and a gear net.

1.2 Classification. (see 6.2)

Type I - Tent assembly with reversible (Camouflage Green 483/Tan) fly
Type II - Tent assembly with reversible (Camouflage Green 483/White) fly

## 2. APPLICABLE DOCUMENTS

*2.1 General. The documents listed in this section are specified in sections 3 and 4 of this specification. This section does not include documents cited in other sections of this specification or recommended for additional information or as examples. While every effort has been made to ensure the completeness of this list, document users are cautioned that they must meet all specified requirements documents cited in sections 3 and 4 of this specification, whether or not they are listed.

**Beneficial comments (recommendations, additions, deletions, clarifications) and any pertinent data which may be of use in improving this document should be addressed to: Defense Supply Center Philadelphia, Clothing and Textiles Directorate, Attn: DSCP-CNR, 700 Robbins Ave., Philadelphia, PA 19111-5096 by using the Standardization Document Improvement Proposal (DD Form 1426) appearing at the end of this document or by letter.**

AMSC N/A FSC 8340

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T01:59Z
Check the source to verify that this is the current version before use.

2.2 Government documents.

2.2.1 Specifications, standards, and handbooks. The following specifications, standards, and handbooks form a part of this document to the extent specified herein. Unless otherwise specified, the issues of these documents are those listed in the issue of the Department of Defense Index of Specifications and Standards (DODISS) and supplement thereto, cited in the solicitation (see 6.2).

**SPECIFICATIONS**

MILITARY

MIL-F-44425 - Frame Section, Tent, Soldier Crew

(Unless otherwise indicated. copies of federal and military specifications, standards, and handbooks are available from the Document Automation and Production Service, Bldg. 4D (DPM-DODSSP), 700 Robbins Avenue, Philadelphia, PA 19111-5094.)

*2.2.2 Other Government documents, drawings, and publications. The following other Government documents, drawings, and publications form a part of this document to the extent specified herein. Unless otherwise specified, the issues are those cited in the solicitation.

DRAWINGS

U.S. ARMY SOLDIER BIOLOGICAL CHEMICAL COMMAND, NATICK SOLDIER CENTER

5-4-7581 - Soldier Crew Tent Assembly
5-4-7676 - Instruction Label, Soldier Crew Tent
5-4-7678 - FSCT Pegs, Bag & Contents

(Copies of drawings are available from the U. S. Army Biological Chemical Command, ATTN: AMSSB-REO-S(N), NATICK, MA 01760-5017.)

*2.3 Order of precedence. In the event of a conflict between the text of this specification and the references cited herein, the text of this specification takes precedence. Nothing in this specification, however, supersedes applicable laws and regulations unless a specific exemption has been obtained.

## 3. REQUIREMENTS

*3.1 First article. When specified (see 6.2), a sample shall be subjected to first article inspection (see 4.2 and 6.4).

3.2 Materials and components. Materials and components shall be as specified on the applicable drawings.

3.3 Construction. Construction shall conform to the drawings listed in section 2 and as specified herein.

3.3.1 Type 301 stitching. Ends of all type 301 stitching shall be backstitched or overstitched not less than ½ inch in accordance with the required stitch pattern.



Source: https://assist.dla.mil -- Downloaded: 2026-10-22T01:59Z
Check the source to verify that this is the current version before use.

3.3.1.1 Repairs of type 301 stitching. Repairs of type 301 stitching shall be as follows:

a. When thread breaks or bobbin run-outs occur during the stitching, the stitching shall be repaired by restarting the stitching a minimum of 1 inch from the defective area, (1/2 inch for box-x and W-W stitching), from the end of the stitching.

b. Thread breaks or two or more consecutive skipped or run-of stitches noted during inspection of the item (in-process or end item) shall be repaired by overstitching. The stitching shall start a minimum of 1 inch from the defective area, (1/2 inch for box-x and W-W stitching), continue over the defective area and continue a minimum of 1-inch (1/2 inch for box-x and W-W stitching) beyond the defective area onto the existing stitching. Loose or excessively tight stitching shall be repaired by removing the defective stitching, without damaging the materials, and restitching in the required manner.

3.3.1.2 Type 401 stitching. Thread tension shall be maintained so that there will be no loose stitching. Both ends of all seams or stitching produced with 401 stitch type, when not turned under in a hem or held down by other stitching, shall have a ½ to ¾ inch chain extending beyond each end. The looper (underthread) shall always be on the inside of fabric assemblies. All repairs shall be made in accordance with 3.3.1.1a or 3.3.1.1b. Repairs may be made using stitch type 301.

3.3.1.3 Bartacking. Bartacking shall be free of thread breaks and loose stitching.

3.3.1.4 Automatic stitching. Automatic stitching machines may be used to perform any of the required stitch patterns provided the requirements for the stitch pattern, stitches per inch and size and type of thread are met and at least three or more tying, overlapping or back stitches are used to secure the ends of stitching.

3.3.1.5 Thread ends. All thread ends shall be trimmed to a length of not more than ¼ inch.

3.3.1.6 Thread lubricant. There shall be no lubrication of the thread on the tent and fly prior to or during the sewing operation.

*3.3.2 Setting of grommets. Holes punched to receive grommets shall be smaller than the outside diameter of the grommet barrel so that the barrel must be forced through the hole. Grommets shall be securely clinched without cutting the materials. Roll of the clinched grommet shall not contain more than three scores (splits).

3.3.3 Wicking of sewing thread. There shall be no wicking of water through the tent body or fly stitching when the tent is tested as specified in 4.4.5. The cup test is intended to insure that non-wicking thread has been utilized and that no lubrication has been added to the thread prior to or during the sewing operation.

3.3.3.1 Leaking of taped seams. There shall be no leakage of water through seams requiring seam tapes when the tent is tested as specified in 4.4.5.

*3.4 Repairs to liner assembly fabric. All necessary repairs shall be effected in accordance with the Department of The Army Field Manual FM 10-16 except that hand sewn patches, other than specified herein, will not be acceptable. Patches on holes, cuts or tears not more than 1 inch in diameter or length shall be permitted. A maximum of one patch per liner assembly shall be allowed without prior authorization from the contracting officer. Each patch shall be large enough to overlap the damaged area with a margin of at least ¾ inch on all sides. Patches shall be


Source: https://assist.dla.mil -- Downloaded: 2026-10-22T01:59Z
Check the source to verify that this is the current version before use.

placed on the outside of the liner assemblies and shall not be permitted over the seams or in hardware areas. All other repairs shall require authorization by the contracting officer.

*3.4.1 Repairs to the tent and fly. No more than one repair to holes, cuts, tears or burn throughs resulting from the heat sealing operation shall be allowed. Repairs on holes, cuts, tears or bur throughs not more than one inch in diameter or length shall be performed as follows:

a. Repairs shall be accomplished by the application of cemented patches. Cemented patches shall be large enough to overlap the damaged area with a margin of at least ¾ inch on all sides, using cement per Minnesota Mining and Manufacturing 847 or equal (see 6.5 and 6.7).

b. For repairs of burn-throughs on panel lap seams, the width of the patch shall be such that the overlap on each side of the burn-through shall be equal to the width of the seam.

c. Patches shall be applied to the top side of the assemblies and the patched area shall be smooth, i.e., with the torn or cut edge securely and completely sealed and corners shall have a radius.

3.5 Color. The color of the type I and type II tents shall be as specified in 1.2. The webbings, tapes, slide fastener tapes, fastener tapes, pulls and thread corresponding to the camouflage green portion of the type I and type II tents shall be as specified on the applicable drawings.

3.6 Replacement of defective components. During the spreading, cutting and manufacturing process, components having material defects or damages that are classified as defects in 4.4.3 shall be removed from production and replaced with non-defective and properly matched material.

3.7 Erection/striking of tent. The complete tent assembly shall be capable of being erected/struck when tested as specified in 4.4.5.

3.8 Workmanship. Cloth components shall be clean and free of holes, cuts, tears, or cloth defects such as multiple floats, broken or missing yarns, or areas untreated with compound. Webbing and tapes shall not have frayed or scalloped edges and rope components shall be free of cuts or breaks Where there is sewing, thread tension shall be maintained so that there will be no loose stitching. Care shall be taken in sewing to see that no needle chews occur. All thread ends shall be trimmed to ½ inch or less. Metal components shall be free of burrs, sharp edges and corroded areas and shall not be broken or malformed.

*3.9 Recycled, recovered, or environmentally preferable materials. Recycled, recovered, or environmentally preferable materials should be used to the maximum extent possible provided that the material meets or exceeds the operational and maintenance requirements, and promotes economically advantageous life cycle costs.

## 4. VERIFICATION

4.1 Responsibility for dimensional requirements. Unless otherwise specified in the contract or purchase order, the contractor is responsible for ensuring that all dimensions specified in the component specifications have been met. When dimensions cannot be examined on the end item, inspection shall be made at any point, or at all points in the manufacturing process necessary to ensure compliance with all dimensional requirements.



Source: https://assist.dla.mil -- Downloaded: 2026-10-22T01:59Z
Check the source to verify that this is the current version before use.

4.2 Classification of inspections. The inspection requirements specified herein are classified as follows:

a. First article inspection (see 4.2).
b. Conformance inspection (see 4.3).

4.3 First article inspection. When a first article is required (see 6.2) it shall be examined for the defects listed in 4.4.3 and 4.4.4 and tested as specified in 4.4. The erection/striking test (see 4.5.2) shall be performed for ten complete erect/strike cycles for the first article inspection only. Any nonconformance shall be cause for rejection of the first article.

4.4 Conformance inspection. Sampling for inspection shall be as specified in the contract or purchase order.

4.4.1 Component and material inspection. In accordance with 4.1, components and materials shall be inspected in accordance with all the requirements of referenced documents unless otherwise excluded, amended, modified or qualified in this specification or applicable purchase document.

4.4.2 In-process inspection. Inspection of subassemblies shall be made to ascertain that construction details which cannot be examined in the finished product are in accordance with specified requirements. The government reserves the right to exclude from consideration for acceptance , any material or service for which in-process inspection shall has indicated nonconformance.

a. There shall be no lubrication of polyester thread prior to or during sewing operations for compliance with 3.3.1.5.

b. Holes punched to receive grommets are in compliance with 3.3.6.

Whenever nonconformance is noted, correction shall be made to the items affected and the process.

4.4.3 End item visual examination. The end item shall be examined for the defects listed in Table I. The tents shall be examined in an erected position to make the interior easily accessible for examination. The lot size shall be expressed in units of tents. The sample unit shall be one tent. The inspection level shall be II.

TABLE II. End item visual defects

| Examine | Defect | Classification Major | Minor A | Minor B |
|---|---|---|---|---|
| Grommets | Improperly set, two or more teeth exposed (except where a grommet is set as specified but is in an area of uneven thickness which prevents uniform clinching) | | | 301 |
| | Clinched loosely, allowing grommet to rotate around hole | | | 302 |

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T01:59Z
Check the source to verify that this is the current version before use.

TABLE II. End item visual defects (continued)

| Examine | Defect | Classification Major | Minor A | Minor B |
|---|---|---|---|---|
| | Clinched excessively tight (i.e., cutting cloth) | 101 | | |
| | Insecurely clinched (i.e., grommets or washers become disengaged) | 102 | | |
| | Set with barrel inserted from outside instead of inside at any location | | 201 | |
| | Roll of a grommet contains more than three scores (splits) | | | 303 |
| Reinforcements, general | Any reinforcement not caught in stitching or binding tape as specified | 103 | | |
| | Improperly assembled to body | 104 | | |
| | Causing excessive fullness on reinforcements or reinforced parts, improperly applied | | | 304 |
| Transparent seam tape | Incorrectly applied, peeling off or burnt through | 105 | | |
| Binding | Loosely applied exposing edge of material | 106 | | |
| | Loosely applied but not exposing edge of material | | | 305 |
| | Ends of binding not finished as specified | | | 306 |
| Slide fastener | Slider jams or fails to interlock chain | 107 | | |
| | Any tape improperly assembled, causing failure of chain to effect a smooth and secure closure | 108 | | |
| | Thong omitted | 109 | | |
| | Damaged teeth | 110 | | |
| Fastener tape | Any hole, cut or tear | 111 | | |
| | Hooks flattened, broken or missing, impairing function | 112 | | |
| Cloth | Any hole (except drill holes), cut or tear | 113 | | |
| | Exposed drill holes (i.e., not covered by attached parts | | 202 | |
| | Any abrasion marks, broken or missing yarns or multiple floats clearly visible at normal inspection distance (3 feet) | 114 | | |
| Screening | Any cut, tear or hole noticeably larger than mesh openings | 115 | | |
| | Edges of screen not caught in stitching as required | 116 | | |
| Webbing and tape | Any cut, tear or hole | 117 | | |
| | Edge frayed or scalloped, not firmly or tightly woven | | 203 | |

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T01:59Z
Check the source to verify that this is the current version before use.

TABLE II. End item visual defects (continued)

| Examine | Defect | Classification Major | Minor A | Minor B |
|---|---|---|---|---|
| Rope components tent lines | Any cut or abrasion; any break | | 204 | |
| | Free ends not finished as specified | | | 307 |
| Hardware | Broken | 118 | | |
| | Malformed: | | | |
| | - fails to perform intended function | 119 | | |
| | - but will perform intended function | | 205 | |
| | Corroded area | | | 308 |
| | Burr or sharp edge that may cause injury in handling or damage to fabric | 120 | | |
| | Not specified type or size | | 206 | |
| | Any required component improperly installed causing failure to serve intended purpose | 121 | | |
| Components & assembly | Any operation omitted or not performed in accordance with specification or drawing unless classified herein | 122 | | |
| Raw material | Any wrong material used | 123 | | |
| Stitching margin | Larger or smaller than specified (including tolerance): | | | |
| | - for more than 2 inches but not more than 4 inches in length | | | 309 |
| | - for more than 4 inches in length | | 207 | |
| Seams & stitching | Open seams: | | | |
| | - ½ inch or less | | | 310 |
| | - more than ½ inch | 124 | | |
| | - on cover | | | 311 |
| | Burn through | 125 | | |
| | Note: A seam shall be classified as open when one or more stitches joining a seam are broken, or when one or more skipped or run-off stitches occur. On double stitched seams, a seam shall be classified as open when either one or both sides of a seam are open. | | | |
| Seam & stitch | Not specified seam or stitch type | 126 | | |
| | Seam twisted, pleated or badly puckered (unless otherwise classified herein) | | | 312 |
| | Any line of stitching not beginning or ending where specified (unless otherwise classified herein) | | | 313 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-22T01:59Z
Check the source to verify that this is the current version before use.

TABLE II. End item visual defects (continued)

| Examine | Defect | Classification Major | Minor A | Minor B |
|---|---|---|---|---|
| | Any seam not lapped or finished as specified | | | 314 |
| Raw edge (on edge required to be finished) | More than ½ inch in length when securely caught in stitching | | | 315 |
| | Note: Raw edge not securely caught in stitching shall be classified as an open seam | | | |
| Thread breaks, skipped stitches or runoffs | On stitching other than box-x stitching overstitched less than 1 inch in each direction beyond defective stitching area for 301 and 401 type stitching | | | 316 |
| | On box-x, overstitched less than ½ inch in each direction beyond the defective stitching area | | | 317 |
| | NOTE: Thread breaks or two or more consecutive skipped or runoff stitches not overstitched shall be classified as an open seam | | | |
| Boxstitching | Incomplete: | | | |
| | - one row of stitching omitted | | 208 | |
| | - two or more rows of stitching omitted | | 209 | |
| | Less than specified length by more than 1/8 inch | | | 318 |
| Bartacking | One or more bartacks omitted | 127 | | |
| | Any bartack not as specified or not in specified location | | | 319 |
| | Loose stitching incomplete or broken | | | 320 |
| | Less than specified length by more than 1/8 inch | | | 321 |
| | Width less than 1/8 inch | | 210 | |
| Stitch tension | Tension loose, resulting in loose bobbin or top thread | | | 322 |
| | Tension tight, resulting in puckering of material | | | 323 |
| Stitches per inch | Less than minimum specified (except on panel joining seams) | | | |
| | - one stitch | | | 324 |
| | - two or more stitches | | 211 | |
| Mends, darns or patches | Repairs not in accordance with Department of The Army Field Manual FM 10-16 or not authorized by the contracting officer | 128 | | |



Source: https://assist.dla.mil -- Downloaded: 2026-10-22T01:59Z
Check the source to verify that this is the current version before use.

TABLE II. End item visual defects (continued)

| Examine | Defect | Classification Major | Minor A | Minor B |
|---|---|---|---|---|
| General | Any other construction detail not performed as specified | 129 | | |
| Marking & labels | Omitted, incorrect, illegible, or misplaced: | | | |
| | - erection or maintenance instructions | | 212 | |
| | - identification | | | 325 |
| Cleanness | Grease or oil stains | | | 326 |
| | Thread ends not trimmed to ½ inch or less (except in slide fastener area) | | | 327 |
| | Thread ends not trimmed to ½ inch or less in slide fastener area | | 213 | |

4.4.4 End item dimensional examination. The end item shall be examined for the defects listed in Table II. Only those dimensions that can be evaluated without damaging or disassembling the end items shall be examined. The lot size shall be expressed in units of tents. covers or frame carrying covers, as applicable. The sample unit shall be one end section, intermediate section, tent cover or frame carrying cover, as applicable. The inspection level shall be S-3.

TABLE III. End item dimensional defects

| Examine | Defect | Classification Major | Minor |
|---|---|---|---|
| Overall dimensions of tent, fly and liner | Larger or smaller than specified (including applicable tolerances) | 101 | |
| Dimensions, other than overall on tent fly & liner | Larger or smaller than specified (including applicable tolerances) | | |
| | - affecting serviceability | 102 | |
| | - not affecting serviceability | | 201 |

4.4.5 End item performance testing. Tents shall be tested as specified in 4.5.1 and 4.5.2 for compliance with the requirements of 3.3.3, 3.3.3.1 and 3.7. The lot size shall be expressed in units of tent bodies. The sample unit shall be one completely fabricated tent body. The inspection level shall be S-3. The lot shall be rejected if one or more sample units fail to meet the requirement.

*4.4.6 Packaging examination. The fully packaged end items shall be examined for marking, materials, workmanship and content defects.

4.5 Methods of inspection.



Source: https://assist.dla.mil -- Downloaded: 2026-10-22T01:59Z
Check the source to verify that this is the current version before use.

4.5.1 Wicking of sewing thread (cup test). The tent body assembly and any components utilizing transparent seam tape, shall be tested on any two areas as follows: any two seams on the tent assembly and any two seams on the components utilizing seam tape

4.5.1.1 Procedure. Suspend the seamed section of the test fabric in the center of a 6 ± 1/8 inch diameter hoop and form a depression with the seamed fabric in the hoop to a depth of 1 ± ¼ inch. Slowly pour 500 ml of water at 77° ± 4°F into the cupped area (depression) and observe the under surface of the fabric for water penetration. Any wicking of water along the sewing thread, identified by a discoloration or darkening of the thread within 5 minutes after water is poured shall constitute a test failure. Water leakage through the needle holes or between the plies of the lapped seam fabric shall not be considered a failure.

*4.5.2 Erection/striking of tent test. The complete tent assembly shall be erected/struck tested as follows:

a. The tent shall be unpacked and completely erected in accordance with Drawing No. 5-4-7676. All doors, pockets, zippers and straps shall be operated to ensure performance.

b. After erection set-up is completed, the tent shall be completely struck (taken down) and packed.

The inability to erect/strike tent shall be considered a test failure.

## 5. PACKAGING

*5.1 Packaging. For acquisition purposes, the packaging requirements shall be as specified in the contract or order (see 6.2). When actual packaging of materiel is to be performed by DoD personnel, these personnel need to contact the responsible packaging activity to ascertain requisite packaging requirements. Packaging requirements are maintained by the Inventory Control Point's packaging activity within the Military Department or Defense Agency, or within the Military Department's System Command. Packaging data retrieval is available from the managing Military Department's or Defense Agency's automated packaging files, CD-ROM products, or by contacting the responsible packaging activity.

## 6. NOTES

*(This section contains information of a general or explanatory nature that may be helpful, but is not mandatory.)

6.1 Intended use. The tent is intended for use by up to five soldiers with gear in all climactic conditions.

*6.2 Acquisition requirements. Acquisition documents must specify the following:

a. Title, number, and date of this specification.
b. Issue of DODISS to be cited in the solicitation, and if required, the specific issue of individual documents referenced (see 2.1.1 and 2.2).
c. When first article is required (see 3.1, 4.3 and 6.4).
d. Levels of preservation and packing (see 5.1).

6.3 Sample. For access to standard sample, address the contracting activity issuing the invitation for bids.



Source: https://assist.dla.mil -- Downloaded: 2026-10-22T01:59Z
Check the source to verify that this is the current version before use.

6.4 First article. When a first article is required, it will be inspected and approved under the appropriate provisions of FAR 52.209. The first article should be a preproduction sample. The contracting officer should specify the appropriate type of first article and the number of units to be furnished. The contracting officer should include specific instructions in all acquisition instruments regarding arrangements for selection, inspection, and approval of the first article.

*6.5 Commercial adhesive. A source of supply for the commercial adhesive specified in 3.4.1 is the Minnesota Mining & Mfg. Co., 3M Center, St. Paul, Minnesota 55144.

6.6 Subject term (key word) listing.
Shelter

*6.7 Equal item. Prior to the use of an “or equal” item, the supplier should submit the item, with supporting data to the contracting officer for subsequent approval or disapproval by the responsible military agency.

*6.8 Changes from previous issue. The margins of this document have been marked with an asterisk(*) to indicate where changes (additions, modifications, corrections, deletions) from the previous issue were made. This was done as a convenience only and the Government assumes no liability whatsoever for any inaccuracies in these notations. Bidders and contractors are cautioned to evaluate the requirements of this document based on the entire content, as written, irrespective of the marginal notations and relationship to the last previous issue.

Custodians:
Army - GL

Preparing activity
DLA-CT

Project No: 8340-0580

Review activities:
Army – MD



Source: https://assist.dla.mil -- Downloaded: 2026-10-22T01:59Z
Check the source to verify that this is the current version before use.

**STANDARDIZATION DOCUMENT IMPROVEMENT PROPOSAL**

INSTRUCTIONS

1. The preparing activity must complete blocks 1, 2, 3, and 8. In block 1, both the document number and revision letter should be given.
2. The submitter of this form must complete blocks 4, 5, 6, and 7 and send to preparing activity.
3. The preparing activity must provide a reply within 30 days from receipt of the form.

NOTE: This form may not be used to request copies of documents, nor to request waivers, or clarification of requirements on current contracts. Comments submitted on this form do not constitute or imply authorization to waive any portion of the referenced document(s) or to amend contractual requirements.

| **I RECOMMEND A CHANGE:** | **1. DOCUMENT NUMBER**<br>MIL-DTL-44427A | **2. DOCUMENT DATE** ***(YYYYMMDD)***<br>2000/02/28 |
|---|---|---|

**3. DOCUMENT TITLE**

**4. NATURE OF CHANGE** *(Identify paragraph number and include proposed rewrite, if possible. Attach extra sheets as needed.)*

**5. REASON FOR RECOMMENDATION**

**6. SUBMITTER**

| a. NAME *(Last, First, Middle Initial)* | b. ORGANIZATION | |
|---|---|---|
| c. ADDRESS *(Include Zip Code)* | d. TELEPHONE *(Include Area Code)*<br>(1) Commercial<br>(2) DSN<br>*(If applicable)* | 7. DATE SUBMITT<br>*(YYYYMMDD)* |

**8. PREPARING ACTIVITY**

| a. NAME<br>DEFENSE SUPPLY CENTER PHILADELPHIA<br>DSCP-CNRP | b. TELEPHONE *(Include Area Code)*<br>(1) Commercial (2) DSN<br>(215) 737-3290 444-3290 |
|---|---|
| c. ADDRESS *(Include Zip Code)*<br>700 Robbins Ave. (Bldg 6, C&T)<br>PHILADELPHIA, PA 19111-5092 | **IF YOU DO NOT RECEIVE A REPLY WITHIN 45 DAYS, CONTACT:**<br>Defense Standardization Program Office (DLSC-LM)<br>8725 John J. Kingman Road, Suite 2533<br>Fort Belvoir, Virginia 22060-6221<br>Telephone (703) 767-6888 DSN 427-6888 |

**DD Form 1426, FEB 1999 (EG)** PREVIOUS EDITION IS OBSOLETE
WHS/DIOR, Feb 99



Source: https://assist.dla.mil -- Downloaded: 2026-10-22T01:59Z
Check the source to verify that this is the current version before use.