NOTICE OF INACTIVE

FOR NEW DESIGN

INCH-POUND

MIL-DTL-70953B
NOTICE 1
12 September 2020

DETAIL SPECIFICATION

BUFFER, RECOIL MECHANISM ASSEMBLY, M119A1/A2 HOWITZER, LIGHT, TOWED: 105MM

MIL-DTL-70953B is inactive for new design and is no longer used, except for replacement purposes.

Custodians:

Army – AR

Preparing activity:

Army – AR

(Project 1015-2020-004)

Note: The activities listed above were interested in this document as of the date of this document. Since organizations and responsibilities can change, you should verify the currency of the information above using the ASSIST online database at https://assist.dla.mil.

AMSC N/A

FSC 1015

DISTRIBUTION STATEMENT A. Approved for public release; distribution is unlimited.

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T04:16Z
Check the source to verify that this is the current version before use.