| INCH-POUND |

MIL-A-70753 (AR)
AMENDMENT 2
26 August 1994
SUPERSEDING
AMENDMENT 1
28 January 1991

MILITARY SPECIFICATION

ADAPTERS, PALLET, WOODEN CONTAINER FOR 105MM AND 120MM TANK AMMUNITION

This amendment forms a part of Military Specification MIL-A-70753 (AR), dated 28 June 1988, and is approved for use by the U.S. Army Armament, Munitions and Chemical Command and is available for use by all Departments and Agencies of the Department of Defense.

PAGE 1

2.1.1: Delete:

"FEDERAL
TT-C-490 - Cleaning and .... Protective Coating".

PAGE 2

Delete: "MIL-STD-171 - Finishing of Metal and Wood Surfaces".

2.1.2 DRAWINGS Add:

"AC00000423 - Chemical Agent Resistant Coating (CARC) Finishing Requirements for Metal Pallets and/or Pallet Adapters".

PAGE 3

3.3.1 Delete in its entirety and substitute:

"3.3.1 Tensile strength of weld on ring and ring support assembly. The tensile strength of the weld shall sustain a vertical force of 2500 pounds minimum for a duration of 30 seconds minimum."

DISTRIBUTION STATEMENT A. Approved for public release; distribution is unlimited.

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T03:57Z
Check the source to verify that this is the current version before use.

3.4 Delete in its entirety and substitute:

"3.4 Painted surface. The painted surfaces of the adapters shall comply with the requirements of drawing AC200000423."

3.6.1 Adapters. Add new sentence to the end of the paragraph:

"Weld splatter is permissible on non-load bearing surfaces provided it is firmly attached."

PAGE 4

3.6.2 Delete in its entirety and substitute:

"3.6.2 Paint coating. The finished coat shall cover all required surfaces and be continuous. Paint runs are permissible provided they are no more than three inches in length, solid and free from cracks and blisters. Excess thickness is acceptable in areas where multiple passes of the paint gun are required to obtain total coverage. Paint chips which expose primer or bare metal are acceptable provided they are not more than 0.25 inch in diameter and no more than two such paint chips on a pallet adapter. Scratches which expose primer or bare metal are permissible provided they are no more than 1.5 inches in length and no more than 10 inches total on a pallet adapter. Bare metal is permissible on contact surfaces and in areas inaccessible to paint."

PAGE 7

4.4.2.1:

Major 103: Delete and substitute: "103 Tensile strength of weld on ring and ring support assembly 100% 3.3.1 Test".

Add Major 105:

"105 Weld missing, incomplete or incorrect 1.0% 3.3 Visual".

Minor 202: Delete and substitute: "202 Protective coating thickness (total thickness minus primer thickness) see drawing AC200000423 and Note (b) below 1.0% 3.2 Gage".

Under Notes, add: "(b) The primer thickness shall be determined from a test panel."

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T03:57Z
Check the source to verify that this is the current version before use.

* Add the following APPENDIX as pages 10 and 11, included herein.

"APPENDIX

QUALITY ASSURANCE PROVISIONS FOR REFURBISHMENT

10. SCOPE:

10.1 Scope. This appendix provides the Quality Assurance provisions for the refurbishment of pallet adapters used with the standard wooden base.

20. APPLICABLE DOCUMENTS:

STANDARDS

MILITARY

MIL-STD-105	Sampling Procedures and Tables for Inspection by Attributes.
MIL-STD-171	Finishing of Metal and Wood Surfaces.

30. REFURBISHMENT:

30.1 Cleaning. Loose paint, dirt, grease and rust shall be removed.

30.2 Refinish. The parts shall be finished in accordance with the applicable drawings with the following exception:

a. For refinishing of adapters, "Finish 20.1 or 20.2" from MIL-STD-171 may be utilized.

40. REQUIREMENTS:

40.1 Welds. Welds shall be in accordance with good commercial practices.

40.2 Stackability. The top lift adapter shall not be deformed to the extent that it effects safely stacking of pallets in storage.

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T03:57Z
Check the source to verify that this is the current version before use.

40.3 Lifting rings. The lifting rings shall not be damaged or deformed to the extent of preventing safe handling by a sling during top lifting operations.

40.4 Adapters. The top lift shall not be deformed to the extent that it does not engage the containers.

40.5 Workmanship. See 3.6 unless otherwise specified below:

a. Deformation or damage that does not effect stacking, slinging or assembly of the pallet is allowed.

50. INSPECTION:

50.1 Examination. Unless otherwise specified examinations for major and minor characteristics shall be performed in accordance with MIL-STD-105, inspection Level II.

50.1.1 Adapter - Wooden Pallet (see drawings listed in 2.1.2 as applicable).

CLASS	CHARACTERISTICS	AQL or 100%	INSPECTION METHOD
Critical	None defined		
Major			
101	Welds missing or broken	1.0%	40.1/Visual
102	Stacking surface deformed	1.0%	40.2/Visual
103	Lifting rings damaged or deformed	1.0%	40.3/Visual
104	Adapter damaged or deformed	1.0%	40.4/Visual
Minor			
201	Marking, missing, incorrect or illegible	1.0%	3.2/Visual
202	Protective finish damaged	1.0%	3.2/Visual
203	Poor workmanship	1.0%	40.5/Visual"

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T03:57Z
Check the source to verify that this is the current version before use.

The margins of this amendment are marked with an asterisk or vertical lines to indicate where changes (additions, modifications, corrections, deletions) from the previous amendment were made. This was done as a convenience only and the Government assumes no liability whatsoever for any inaccuracies in these notations. Bidders and contractors are cautioned to evaluate the requirements of this document based on the entire content irrespective of the marginal notations and relationship to the last previous amendment.

Custodian:
Army-AR

Preparing activity:
Army-AR

(Project 8140-0013)

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T03:57Z
Check the source to verify that this is the current version before use.