MILITARY SPECIFICATION

WARHEAD SECTION, GM, TRAINING: XM201

PARTS AND ASSEMBLING

This specification is approved for use by all Departments and Agencies of the Department of Defense.

1. SCOPE

1.1 This specification contains requirements not normally covered by the drawings and provides quality assurance provisions for the fabrication of parts for and assembling of the Warhead Section, GM, Training: XM201.

2. APPLICABLE DOCUMENTS

2.1 The following documents of the issue in effect on date of invitation for bids, or request for proposal form a part of this specification to the extent specified herein.

SPECIFICATIONS

FEDERAL

MILITARY

MIL-A-48078	- Ammunition, Standard Quality Assurance Provisions, General Specification For
MIL-T-5021	- Tests Aircraft and Missile Welding Operator's Qualification
MIL-I-6812	- Bolt, Aircraft
MIL-I-6866	- Inspection, Penetrant, Method of
MIL-I-6868	- Inspection Process, Magnetic Particle
MIL-W-8604	- Welding of Aluminum Alloys, Process for
MIL-S-7742	- Screw Threads, Standard, Optimum Selected Series: General Specifications for

FSC: 1340

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:20Z
Check the source to verify that this is the current version before use.

STANDARDS

MILITARY

MIL-STD-453	- Inspection, Radiographic
MIL-STD-1169	- Packaging, Packing and Marking for Shipment of Inert Ammunition Components

DRAWINGS

PICATINNY ARSENAL

PRODUCT AND PACKAGE DRAWINGS

9215598	- Warhead Section, GM, Training: XM201
9211190	- Pkg and Mkg for Warhead Section, GM, HE: XM251, Proc: XM198, TNG: XM201

2.2 Other publications.-The following documents form a part of this specification to the extent specified herein. Unless otherwise indicated, the issue in effect on the date of invitation for bids or request for proposal shall apply.

AMERICAN SOCIETY FOR TESTING AND MATERIALS

ASTM E 8-69	- Tension Testing of Metallic Materials
ASTM E 18-67	- Tests for Rockwell Hardness and Rockwell Superficial Hardness of Metallic Materials

3. REQUIREMENTS

3.1 Material.-Materials shall be in accordance with the applicable drawings and specifications.

3.2 Parts.-The parts and assemblies shall comply with all requirements specified on Drawing (dwg) 9215598, all associate drawings and with all requirements specified in applicable specifications.

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:20Z
Check the source to verify that this is the current version before use.

3.3 Welding.-The weld of each warhead section shall be such as to produce satisfactory joined parts. All skin welds shall be reasonably smooth and free of craters. They shall exhibit characteristics of good fusion, penetration, and soundness of deposit representative of good welding practice. The process shall be such as to preclude warpage beyond the specified dimensional requirements. All scale and weld splatter shall be completely removed prior to application of protective coatings. A satisfactory weld shall also in addition, be based upon compliance with 3.3.1, 3.3.2, 3.3.3, 3.3.4, 3.3.5, and 3.4.

3.3.1 Electrodes.-Electrodes shall be of a coated type, except as specified in 3.3.2. The coating shall be uniform and without bare spots, except that used to introduce current to the electrode.

3.3.2 Process.-Gas shielded arc-welding or other automatic arc-welding in which bare or lightly coated wire is used with the arc bathed in a reducing gas or other atmosphere - excluding media, may be used.

3.3.3 Qualification.-

3.3.3.1 Welding operators.-Welding operators shall be qualified in accordance with MIL-T-5021.

3.3.3.2 Welding equipment.-Welding equipment shall be qualified in accordance with MIL-W-8604.

3.3.3.3 All welding shall be accomplished in conformance with the process used to qualify the first article sample.

3.3.4 Acceptance weld imperfection permitted in each skin section.

3.3.4.1 Material sag.-Sag of the material in the area adjacent to the weld shall not be more than .010 inch below the surface of the joined part.

3.3.4.2 Porosity.-Porosity or other discontinuity shall not extend as surface cracks in excess of those defined in 3.3.5 as determined in accordance with4.5.1, except that microporosity as evidence by partial penetration into skins by penetrant shall be acceptable.

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:20Z
Check the source to verify that this is the current version before use.

3.3.4.3 Blowouts.-Blowouts may be repaired with hand welding operations, provided they are not greater than one quarter inch in width and one inch in length and no more than three (3) such areas may be repaired in any one skin.

3.3.5 Surface cracks.-Surface cracks shall not be in excess of one surface crack one half inch long in each one inch length. No weld shall have more than a total of two inches of surface crack.

3.4 Mechanical properties.

3.4.1 Component parts.-The aluminum used in fabrication of the components shall comply with the minimum (min) requirements specified in the applicable specification for the heat treat conditions required.

3.4.2 Welds.-The tensile strength of aluminum welds shall not be less than 30,000 pounds per square inch (PSI), the yield strength shall not be less than 25000 (PSI), the elongation shall not be more than eight (8) percent.

3.5 Function of ogive skin.-The ogive skin shall, when disengaged, move forward and rotate, as required, and return to the original position and be securely re-engaged without any motion stoppage due to interferrence between parts.

3.6 Spring embrittlement.-Springs which have been treated for embrittlement relief shall show no visual evidence of cracks and shall not break when pulled to the minimum point of permanent distortion.

3.7 Workmanship.-All parts and assemblies shall be fabricated and finished in a thorough workmanlike manner. They shall be free of burrs, chips, sharp edges, cracks, unblended radii, surface defects, dirt, grease, rust, corrosion products and other foreign matter. The cleaning method used shall not be injurious to any of the parts nor shall the parts be contaminated by the cleaning agents. Required markings shall be neat and sharply defined. Surface coatings shall be continuous except for a few light scratches not exposing base material.

3.8 Mechanical properties.-Cold-working or heat-treating (including quenching-and-tempering, normalizing, normalizing and-tempering, annealing, and stress-relieving) operations, shall be performed in such a manner as to produce the specified properties uniformly throughout the entire lot. The contractor

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:20Z
Check the source to verify that this is the current version before use.

shall determine the detailed procedures to produce parts meeting the required mechanical properties. These procedures shall be documented to the Contracting Officer. Changes in these procedures shall also be documented and submitted to the Contracting Officer.

3.9 First article testing.-This specification contains technical provisions for first article inspection. Requirements for the submission of first article samples by the contractor shall be as specified in the contract.

4. QUALITY ASSURANCE PROVISIONS

4.1 Responsibility for Inspections.-The responsibility for inspection shall comply with MIL-A-48078.

4.2 Classification of Inspections.-The following types of inspection shall be conduced on this item:

a. First Article Inspection
b. Quality Conformance Inspection

4.3 First Article Inspection.-

4.3.1 Submission.-The contractor shall submit a first article sample as designated by the Contracting Officer for evaluation in accordance with the provisions of 4.3.2. The first article sample shall consist of the following items in sample quantities as indicated.

Part Description	Drawing No.	Quantity
Warhead Section, GM, Training: XM201 (unpainted)	9215598	1
Warhead Section, GM, Training: XM201	9215598	1
Ring, fuze	9227332	1
Skin, ogive	9227330	1
Latch Assembly	9227331	2
Disc, station 25.5	9225739	1
Disc, station 39.0	9225740	1
Disc, station 71.5	9225741	1
Ring, station 95.6	9225742	1
Skin, forward	9225743	1
Skin, aft	9225744	1
Ring, aft	9225745	1
Bolt, tee	9237322	4
Weight, forward	9229757	1

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:20Z
Check the source to verify that this is the current version before use.

Weight, aft	9229758	1
Pin, alignment	8877425	2
Pin, shear	8877426	6
Spring, pushbutton	9227335-1	5
Spring, pushbutton	9227335-2	5
Spring, clevis	8836202	5
Spring. latch	8831279	5
Spring, torsion	8831283	5
Nut, external wrenching	9237309	4

4.3.2 Inspections to be Performed.-The First Article parts submitted in accordance with Paragraph 4.3.1 will be subjected by the Government to any or all the requirements of the applicable drawing and to the inspection of Table 1. All inspections listed in Table 1 shall be classified Major unless otherwise specified.

4.3.3 Rejection.-See MIL-A-48078 (PA)

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:20Z
Check the source to verify that this is the current version before use.

TABLE 1 - FIRST ARTICLE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-W-48274 (PA)

PARAGRAPH CATEGORY	TITLE / EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	SHEET 1 OF 4 — DRAWING NUMBER: See Below; NEXT HIGHER ASSEMBLY — PARAGRAPH REFERENCE /INSPECTION METHOD
	Warhead Section, GM, Training: XM201 (Unpainted) (Dwg. 9215598)				
	Examination for Defects	1		3.2	4.4.2.22
	Warhead Section, GM, Training: XM201 (Dwg. 9215598)				
	Examination for Defects	1		3.2	4.4.2.23
	Skin, Ogive (Dwg. 9227330)				
	Examination for Defects	1		3.2	4.4.2.1
	Examintion of Mechanical Properties of Skin	2*		3.4.1	4.5.2
	Examination of Tensile Properties or Welds	4**		3.4.2	4.5.3
	Skin, Forward (Dwg. 9225743)				
	Examination For Defects	1		3.2	4.4.2.2
	Examination of Mechanical Properties of Skin	2*		3.4.1	4.5.2
	Examination of Tensile Properties of Welds	4**		3.4.2	4.5.3
	Skin, Aft (Dwg. 9225744)				
	Examination for Defects	1		3.2	4.4.2.3
	Examination of Mechanical Properties of Skin	2*		3.4.1	4.5.2

NOTES:

* Samples cut from part

** Samples cut from part transverse of welded joint

SARPA-QA FORM 2567 FEB 74

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:20Z
Check the source to verify that this is the current version before use.

TABLE 1 - FIRST ARTICLE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-W-48274 (PA)

PARAGRAPH	TITLE		SHEET 2 OF 4		DRAWING NUMBER See Below
					NEXT HIGHER ASSEMBLY
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
	Examination of Tensile Properties of Welds Ring, Aft (Dwg. 9225745)	4**		3.4.2	4.5.3
	Examination for Defects Ring, Station 95.6 (Dwg. 9225742)	1		3.2	4.4.2.4
	Examination for Defects Ring, Fuze (Dwg. 9227332)	1		3.2	4.4.2.5
	Examination for Defects Disc, Station 25.5 (Dwg. 9225739)	1		3.2	4.4.2.6
	Examination for Defects Disc, Station 39.0 (Dwg. 9225740)	1		3.2	4.4.2.7
	Examination for Defects Disc, Station 71.5 (Dwg. 9225741)	1		3.2	4.4.2.8
	Examination for Defects Weight, Forward (Dwg. 9229757)	1		3.2	4.4.2.9
	Examination for Defects Weight, Aft (Dwg. 9229758)	1		3.2	4.4.2.10
	Examination for Defects	1		3.2	4.4.2.11

NOTES:

** Samples cut from part transverse of welded joint

SARPA-QA FORM 2567 FEB 74

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:20Z
Check the source to verify that this is the current version before use.

TABLE 1 - FIRST ARTICLE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE		SHEET 3 OF 4		DRAWING NUMBER: See Below NEXT HIGHER ASSEMBLY
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
	Bolt, Tee (Dwg. 9237322) Examination for Defects	4		3.2	4.4.2.12
	Nut, External Wrenching (Dwg. 9237309) Examination for Defects	4		3.2	4.4.2.13
	Pin, Alignment (Dwg. 8877425) Examination for Defects	2		3.2	4.4.2.14
	Pin, Shear (Dwg. 8877426) Examination for Defects	6		3.2	4.4.2.15
	Spring, Pushbutton (Dwg. 9228335-1) Examination for Defects	5		3.6	4.4.2.16
	Spring, Pushbutton (Dwg. 9227335-2) Examination for Defects	5		3.6	4.4.2.17
	Spring, Clevis (Dwg. 8836202) Examination for Defects	5		3.6	4.4.2.18
	Spring, Latch (Dwg. 8831279) Examination for Defects	5		3.6	4.4.2.19
	Spring, Torsion (Dwg. 8831283) Examination for Defects	5		3.6	4.4.2.20

NOTES:

SARPA-QA FORM 2567 FEB 74

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:20Z
Check the source to verify that this is the current version before use.

TABLE 1 - FIRST ARTICLE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-W-48274 (PA)

PARAGRAPH	TITLE		SHEET 4 OF 4		DRAWING NUMBER: See Below NEXT HIGHER ASSEMBLY
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
	Latch Assembly (Dwg. 9227331) Examination for Defects	2		3.2	4.4.2.21

NOTES:

SARPA-QA FORM 2567 FEB 74

10

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:20Z
Check the source to verify that this is the current version before use.

4.4 Quality Conformance Inspection-

4.4.1 Inspection Lot Formation-Inspection lots shall comply with the lot formation provisions of MIL-A-48078.

4.4.2 Examination-See MIL-A-48078

a. Sampling Plans-Unless otherwise specified in the Classification of Defects, sampling plans for major and minor defects shall be in accordance with MIL-STD-105, Inspection Level II.

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:20Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE	SHEET	DRAWING NUMBER
4.4.2.1	Skin, Ogive	1 OF 1	9227330 NEXT HIGHER ASSEMBLY 9215598

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101.	Penetrant examination of welds		100%	3.3.4.2	4.5.1
Minor					
201.	Curve of outside surface of skin improper		0.65%	3.2	Gage
202.	Overall length		0.65%	3.2	Gage
203.	Thickness, before forming		0.65%	3.2	Gage
204.	Thickness of nose wall		0.65%	3.2	Gage
205.	Location of holes (outer skin surface)		0.65%	3.2	Gage
206.	Protective finish, omitted or inadequate		0.65%	3.2	Visual
207.	Evidence of poor workmanship		0.65%	3.7	Visual

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:20Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.2	Skin, Forward				9225743
					NEXT HIGHER ASSEMBLY 9215598
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101.	Penetrant examination of welds		100%	3.3.4.2	4.5.1
Minor					
201.	Curve of outside surface of skin improper		0.65%	3.2	Gage
202.	Overall length		0.65%	3.2	Gage
203.	Thickness		0.65%	3.2	Gage
204.	Protective finish omitted or improper		0.65%	3.2	Visual
205.	Evidence of poor workmanship		0.65%	3.6	Visual

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:20Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-W-48274 (PA)

PARAGRAPH	TITLE	SHEET 1 OF 1	DRAWING NUMBER
4.4.2.3	Skin, Aft		9225744
			NEXT HIGHER ASSEMBLY 9215598

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101.	Penetrant examination of welds		100%	3.3.4.2	4.5.1
Minor					
201.	Curve of outside surface of skin improper		0.65%	3.2	Gage
202.	Overall length		0.65%	3.2	Gage
203.	Thickness		0.65%	3.2	Gage
204.	Protective finish omitted or improper		0.65%	3.2	Visual
205.	Evidence of poor workmanship		0.65%	3.7	Visual

NOTES:

SARPA-QA FORM 2567 FEB 74

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:20Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 9225745
4.4.2.4	Ring, Aft				NEXT HIGHER ASSEMBLY 9215598
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101.	Large outside diameter		0.40%	3.2	Gage
102.	Length		0.40%	3.2	Gage
103.	Location of alignment pin holes		0.40%	3.2	Gage
104	Location of shear pin holes		0.40%	3.2	Gage
105.	Location of "T" bolt cutouts		0.40%	3.2	Gage
106.	Any counterbore omitted		0.40%	3.2	Visual
107.	Pitch diameter of alignment pin hole (2 places)		0.40%	3.2	Gage
108.	Minimum effective thread of alignment pin hole (2places)		0.40%	3.2	Gage
109.	Depth of large alignment pin hole (2 places)		0.40%	3.2	Gage
110.	Pitch diameter of shear pin hole (6 places)		0.40%	3.2	Gage
111.	Minimum effective thread of shear pin hole (6 places)		0.40%	3.2	Gage
112.	Depth of large shear pin hole (6 places)		0.40%	3.2	Gage
Minor					
201.	Protective finish omitted or improper		0.65%	3.2	Visual
202.	Evidence of poor workmanship		0.65%	3.7	Visual

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:20Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

MIL-W-48274 (PA)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 9225742
4.4.2.5	Ring, Station 95.6				NEXT HIGHER ASSEMBLY 9215598
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101.	Outside diameter		0.40%	3.2	Gage
102.	Inside diameter		0.40%	3.2	Gage
103.	Thickness		0.40%	3.2	Gage
Minor					
201.	Protective finish omitted or improper		0.65%	3.2	Visual
202.	Evidence of poor workmanship		0.65%	3.7	Visual

NOTES:

SARPA-QA FORM 2567 FEB 74

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:20Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 9227332
4.4.2.6	Ring, Fuze				NEXT HIGHER ASSEMBLY 9215598
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101.	Location of fuze mounting holes		0.40%	3.2	Gage
102.	Pitch diameter of fuze mounting holes		0.40%	3.2	Gage
103.	Minor diameter of fuze mounting holes, max.		0.40%	3.2	Gage
104.	Large outside diameter (datum B)		0.40%	3.2	Gage
105.	Small outside diameter (datum A)		0.40%	3.2	Gage
106.	Concentricity of large outside diameter with small outside diameter		0.40%	3.2	Gage
Minor					
201.	Protective finish omitted or improper		0.65%	3.2	Visual
202.	Evidence of poor workmanship		0.65%	3.7	Visual

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:20Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-W-48274 (PA)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.7	Disc, Station 25.5				9225739
					NEXT HIGHER ASSEMBLY 9215598
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Distance to small basic diameter		0.40%	3.2	Gage
102.	Distance to large basic diameter		0.40%	3.2	Gage
103.	Thickness		0.40%	3.2	Gage
Minor					
201.	Protective finish omitted or improper		0.65%	3.2	Visual
202.	Evidence of poor workmanship		0.65%	3.7	Visual

NOTES:

SARPA-QA FORM 2567 FEB 74

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:20Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.8	Disc, Station 39.0				9225740
					NEXT HIGHER ASSEMBLY 9215598
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101.	Distance to small basic diameter		0.40%	3.2	Gage
102.	Distance to large basic diameter		0.40%	3.2	Gage
103.	Thickness		0.40%	3.2	Gage
Minor					
201.	Protective finish omitted or improper		0.65%	3.2	Visual
202.	Evidence of poor workmanship		0.65%	3.7	Visual

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:20Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 9225741
4.4.2.9	Disc, Station 71.5				NEXT HIGHER ASSEMBLY 9215598
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101.	Distance to small basic diameter		0.40%	3.2	Gage
102.	Distance to large basic diamter		0.40%	3.2	Gage
103.	Thickness		0.40%	3.2	Gage
Minor					
201.	Protective finish omitted or improper		0.65%	3.2	Visual
202.	Evidence of poor workmanship		0.65%	3.7	Visual

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:20Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-W-48274 (PA)

21

PARAGRAPH	TITLE	SHEET 1 OF 1	DRAWING NUMBER
4.4.2.10	Weight, Forward		9229757
			NEXT HIGHER ASSEMBLY 9215598

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101.	Outside diameter		0.40%	3.2	Gage
102.	Diameter between holes (2 places)		0.40%	3.2	Gage
103.	Thickness		0.40%	3.2	Gage
Minor					
201.	Protective finish omitted or improper		0.65%	3.2	Visual
202.	Evidence of poor workmanship		0.65%	3.7	Visual

NOTES:

SARPA-QA FORM 2567 FEB 74

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:20Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

MIL-W-48274 (PA)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.11	Weight, Aft				9229758
					NEXT HIGHER ASSEMBLY 9215598
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101.	Outside diameter		0.40%	3.2	Gage
102.	Diameter between holes		0.40%	3.2	Gage
103.	Counterbore missing		0.40%	3.2	Visual
Minor					
201.	Protective finish omitted or improper		0.65%	3.2	Visual
202.	Evidence of poor workmanship		0.65%	3.7	Visual

NOTES:

SARPA-QA FORM 2567 FEB 74

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:20Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 9237322
4.4.2.12	Bolt, Tee				NEXT HIGHER ASSEMBLY 9215598
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101.	Internal defects inspection		100%	3.2	4.5.4
102.	Magnetic particle inspection		100%	3.2	4.5.5
103.	Pitch diameter		0.40%	3.2	4.5.6
104.	Major diameter		0.40%	3.2	4.5.6
105.	Hardness	25*	Acc. 0 Rej. 1	3.2	4.5.7
Minor					
201.	Symmetry of bolt shank to "A" and "B"		0.65%	3.2	Gage
202.	Overall dimension handle, max.		0.65%	3.2	Gage
203.	Dimension handle, bearing surface, min.		0.65%	3.2	Gage
204.	Evidence of poor workmanship		0.65%	3.7	Visual

NOTES:
*Or five (5) percent, whichever is greater

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:20Z
Check the source to verify that this is the current version before use.

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 9237309
4.4.2.13	Nut, External Wrenching				NEXT HIGHER ASSEMBLY 9215598
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101.	Magnetic particle inspection		100%	3.2	4.5.5
102.	Pitch diameter		0.40%	3.2	4.5.6
103.	Minor diameter		0.40%	3.2	4.5.6
Minor					
201.	Distance across flats of double hex		0.65%	3.2	Gage
202.	Largest distance across double hex, min.		0.65%	3.2	Gage
203.	Length of double, hex, min.		0.65%	3.2	Gage
204.	Diameter of bearing surface, min.		0.65%	3.2	Gage
205.	Largest outside diameter, max.		0.65%	3.2	Gage
206.	Length of largest outside diameter, min.		0.65%	3.2	Gage
207.	Overall length, max.		0.65%	3.2	Gage
208.	Evidence of poor workmanship		0.65%	3.6	Visual

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:20Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-W-48274 (PA)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.14	Pin, Alignment				8877425
					NEXT HIGHER ASSEMBLY 9215598
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101.	Pitch diameter		0.40%	3.2	Gage
102.	Diameter		0.40%	3.2	Gage
103.	Length from shoulder to end		0.40%	3.2	Gage
104.	Overall length		0.40%	3.2	Gage
Minor					
201.	Evidence of poor workmanship		0.65%	3.7	Visual

NOTES:

SARPA-QA FORM 2567 FEB 74

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:20Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

MIL-W-48274 (PA)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.15	Pin, Shear				8877426
					NEXT HIGHER ASSEMBLY
					9215598
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101.	Pitch diameter		0.40%	3.2	Gage
102.	Diameter		0.40%	3.2	Gage
103.	Length from shoulder to end		0.40%	3.2	Gage
104.	Overall length		0.40%	3.2	Gage
Minor					
201.	Evidence of poor workmanship		0.65%	3.7	Visual

NOTES:

SARPA-QA FORM 2567 FEB 74

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:20Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-W-48274 (PA)

PARAGRAPH	TITLE	SHEET 1 OF 1	DRAWING NUMBER
4.4.2.16	Spring, Pushbutton		9227335-1
			NEXT HIGHER ASSEMBLY 9227331

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major 101.	Spring embrittlement	5	Acc.0 Rej.1	3.6	4.5.8
Minor 201	Evidence of poor workmanship		0.65%	3.7	Visual

NOTES:

SARPA-QA FORM 2567 FEB 74

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:20Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-W-48274 (PA)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.17	Spring, Pushbutton				9227335-2
					NEXT HIGHER ASSEMBLY
					9227331
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101.	Spring embrittlement	5	Acc.0 Rej.1	3.6	4.5.8
201.	Evidence of poor workmanship		0.65%	3.7	Visual

NOTES:

28

SARPA-QA FORM 2567 FEB 74

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:20Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 8836202
4.4.2.18	Spring, Clevis				NEXT HIGHER ASSEMBLY 9215598
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major 101.	Spring embrittlement	5	Acc.0 Rej.1	3.6	4.5.8
Minor 201.	Evidence of poor workmanship		0.65%	3.7	Visual

NOTES:

SARPA-QA FORM 2567 FEB 74

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:20Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.19	Spring, Latch				8831279
					NEXT HIGHER ASSEMBLY 9227331
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major 101.	Spring embrittlement	5	Acc.0 Rej.1	3.6	4.5.8
Minor 201.	Evidence of poor workmanship		0.65%	3.7	Visual

NOTES:

SARPA-QA FORM 2567 FEB 74

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:20Z
Check the source to verify that this is the current version before use.

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 8831283
4.4.2.20	Spring, Torsion				NEXT HIGHER ASSEMBLY 9227331
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major 101.	Spring embrittlement	5	Acc.0 Rej. 1	3.6	4.5.8
Minor 201.	Evidence of poor workmanship		0.65%	3.7	Visual

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:20Z
Check the source to verify that this is the current version before use.

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 9227331
4.4.2.21	Latch Assembly				NEXT HIGHER ASSEMBLY 9215598
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major 101.	Any component damaged, missing or improperly assembled		0.40%	3.2	Visual
Minor 201.	Evidence of poor workmanship		0.65%	3.6	Visual

NOTES:

SARPA-QA FORM 2567 FEB 74

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:20Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 9215598
4.4.2.22	Warhead Section, GM, Training, EXM201 (Unpainted)				NEXT HIGHER ASSEMBLY
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101.	Aft ring extending from aft skin max.		0.40%	3.2	Gage
102.	Gaps improper, max.		0.40%	3.2	Gage
103.	Steps, forward facing, improper, max.		0.40%	3.2	Gage
104.	Steps, aft facing, improper, max.		0.40%	3.2	Gage
105.	Steps, longitudinal, improper max.		0.40%	3.2	Gage
106.	Any component missing, damaged or improperly assembled		0.40%	3.2	Visual
107.	Any screw loose (screw moves when turned in CW direction)		0.40%	3.2	Visual/Manual
Minor					
201.	Evidence of poor workmanship		0.65%	3.7	Visual

NOTES:

SARPA-QA FORM 2567 FEB 74

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:20Z
Check the source to verify that this is the current version before use.

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 9215598
4.4.2.23	Warhead Section, GM, Training, XM201				NEXT HIGHER ASSEMBLY
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101.	Weight (including XM816 Fuze)		100%	3.2	Test
102.	Longitudinal center of gravity		100%	3.2	4.5.9
103.	Functioning of ogive skin		100%	3.5	4.5.10
Minor					
201.	Longitudinal location of CG holes (3 places)		0.65%	3.2	Gage
202.	CG band not located on CG holes		0.65%	3.2	Visual
203.	"Dummy" metal stamp omitted or improper		0.65%	3.2	Visual
204.	Markings omitted, improper or unidentifiable		0.65%	3.2	Visual
205.	Protective finish omitted or improper		0.65%	3.2	Visual
206.	Evidence of poor workmanship		0.65%	3.7	Visual

NOTES:

SARPA-QA FORM 2567 FEB 74

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:20Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 9211190
4.4.2.24	Pkg & Mkg for Warhd Sect., GM, HE: XM251; Proc: XM198E1; Tng: XM201 (before assembly of cover assembly)				NEXT HIGHER ASSEMBLY
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Tee bolts not in place in aft support assembly		100%	3.2	Visual
102	External wrenching nuts move when minimum torque is applied		100%	3.2	Gage
103	Safety pin missing or improperly assembled to strap assembly		100%	3.2	Visual
Minor	None defined				

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:20Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

MIL-W-48274 (PA)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.25	Pkg & Mkg for Warhd Sect., GM HE: XM251; Proc: XM198E1; Tng: XM201				9211190
					NEXT HIGHER ASSEMBLY
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Cover assembly improperly assembled		0.40%	3.2	Visual
102	T-bolts missing or improperly assembled		0.40%	3.2	Visual
103	T-bolts move when minimum torque is applied		0.40%	3.2	Gage
104	Lead seals missing or improperly assembled		0.40%	3.2	Visual
105	Marking missing, incomplete or illegible		0.40%	3.2	Visual
Minor	None defined				

NOTES:

SARPA-QA FORM 2567 FEB 74

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:20Z
Check the source to verify that this is the current version before use.

4.4.3 Testing.-Testing is described in the First Article and Quality Conformance Inspection Tables.

4.4.4 Inspection Equipment.-The inspection equipment required to perform the examinations and prescribed herein is described in the Paragraph Reference/Inspection Method column in the tables with Paragraph 4.4.2.1. The contactor shall submit for approval inspection equipment designs in acccordance with the terms of the contract. See Section 6 of MIL-A-48078.

4.5 Test Method and Procedures.-

4.5.1 Penetrant examination of welds.-The welds of the skins shall be subjected to penetrant inspection in accordance with MIL-I-6866. Parts so tested shall be returned to the lot.

4.5.2 Mechanical properties of skin sections.-Samples of material from the ogive skin, forward skin and aft skin shall be subjected to the tension test in accordance with ASTM E 8-69 (Part 31) to determine tensile strength, yield strength and percentage of elongation. This is a destructive test. Parts so tested shall not be returned to the lot.

4.5.3 Tension test of skin welds.-Samples of the welds from the ogive skin, forward skin and aft skin shall be subjected to the tension test in accordance with ASTM E 8-69 (Part 31) to determine tensile strength, yield strength and percentage of elongation. This is a destructive test. Parts so tested shall not be returned to the lot.

4.5.4 Internal defects inspection of tee bolt.-The tee bolt shall be inspected for internal defects in accordance with MIL-STD-453, Q.L. 2-2T. Parts so tested shall be returned to the lot.

4.5.5 Magnetic particle inspection of tee bolt and external wrinding nut.-The tee bolt and external wrenching nut shall be inspected for defects in accordance with MIL-I-6868 and MIL-B-6812. Parts so tested shall be returned to the lot.

4.5.6 Inspection of the bolt and external wrenching nut threads.-The threads of the tee bolt and external wrenching nut shall be inspected in accordance with MIL-S-7742. Parts so tested shall be returned to the lot.

4.5.7 Hardness of tee bolt.-The tee bolt shall be subjected to the hardness test in accordance with ASTM E 18-67. (Part 31) This is a non-destructive test. Parts so tested shall be returned to the lot.

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:20Z
Check the source to verify that this is the current version before use.

4.5.8 Spring embrittlement.-The spring shall be gripped at both ends and extended to the point of minimum permanent distortion. Failure in meeting the requirement shall class the spring defective. Springs so tested shall not be returned to the batch.

4.5.9 Longitudinal center of gravity.-The warhead section shall be placed in a fixture and tested as follows: With the warhead section on the test fixture, lift the tip end enough to insert a pivot at station 39.0. With the front of the head resting on the pivot, lift the rear end of the section with a hoist equipped with a scale. The lift shall be made using a sling center ring around the warhead at station 95.6.

Calculate the longitudinal center of gravity as follows:

$$\text{Center of Gravity} = \frac{(W1)\ (95.6) + (W2)\ (39.0)}{W3}$$

Where:

W1 = Weight lifted by scale and hoist
W2 = Weight of head minus W1
W3 = Weight of head

4.5.10 Functioning of ogive skin.-The push buttons shall be depressed using thumb pressure and the latch levers fully opened. The ogive skin shall be separated from the forward assembly by pulling forward and turning in a clock-wise direction and then returned to its original position and the latch levers closed. At no time in this test shall there be excessive binding nor shall it be necessary to distort any part in order to re-assemble the ogive to the rest of the warhead section.

5. PREPARATION FOR DELIVERY

5.1 Preservation and packaging.-

5.1.1 Level A.-The warhead shall be perserved and packaged in accordance with Dwg. 9211190.

5.2 Packing.

5.2.1 Level A.-The warhead, preserved and packaged as specified in 5.1.1, shall be packed in accordance with Dwg. 9211190.

5.3 Marking.-Marking shall be in accordance with Dwgs 9215598 and 9211190.

5.4 Shipping.-When warheads from more than one lot are shipped as a carload, each lot shall be kept separate, and the division between lots clearly indicated to prevent mixing of the lots in transit.

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:20Z
Check the source to verify that this is the current version before use.

6. NOTES

6.1 Intended Use.-Not applicable

6.2 Ordering data.-See MIL-A-48078 (PA)

6.3 Submission of Designs for Approval.-See 6.2.3 of MIL-A-48078. Submit equipment designs, as required, to Commander, Picatinny Arsenal, Attn: SARPA-QA-T-T, Dover, New Jersey 07801.

Custodian:
Army-PA

Preparing Activity:
Army-PA

Project Number: 1340-A416

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:20Z
Check the source to verify that this is the current version before use.