MIL-P-48760 (PA)
6 June 1975
(see 6.5)

MILITARY SPECIFICATION

PRIMER, STAB, M56
PARTS FOR AND
LOADING, ASSEMBLING, AND PACKING

This specification is approved for use by all Departments and Agencies of the Department of Defense

1. SCOPE

1.1 This specification covers the parts and the loading assembling and packing for one type of initiating device designated as Primer, Stab, M56.

2. APPLICABLE DOCUMENTS

2.1 The following documents of the issue in effect on date of invitation for bids or request for proposal form a part of this specification to the extent specified herein.

SPECIFICATIONS

MILITARY

MIL-P-116 - Preservation, Packaging, Method of
MIL-A-48078 - Ammunition, Standard Quality Assurance Provisions, General Specification For

STANDARDS

MILITARY

MIL-STD-105 - Sampling Procedures and Tables for Inspection by Attributes (ABC-STD-105)
MIL-STD-650 - Explosives: Sampling, Inspection, and Testing
MIL-STD-1169 - Packaging, Packing and Marking for Shipment of Inert Ammunition Components

FSC: 1375

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:39Z
Check the source to verify that this is the current version before use.

DRAWINGS

U.S. ARMY PICATINNY ARSENAL

PRODUCT AND PACKAGING DRAWINGS

9298006 - Primer, Stab, M56
9258182 - Box, Set-up, Packing, Ammunition, Inner for Small Explosive Components
9258183 - Box, Set-up, Packing, Ammunition, Outer, for Small Explosive Components
9258184 - Box, Packing, Ammunition, for Small Explosive Components

INSPECTION EQUIPMENT DRAWINGS

8816367 - Holder, Firing Pin
8827828 - Sleeve
8827829 - Bushing
8827934 - Adapter, ball, steel
9202650 - Disc, Steel
9200012 - Pin, Firing
9201952 - Assembly, firing

(Copies of specifications, standards, drawings and publications required by suppliers in connection with specific procurement functions should be obtained from the procuring activity or as directed by the Contracting Officer).

2.2 Other publications. - The following document forms a part of this specification to the extent specified herein. Unless otherwise indicated, the issue in effect on date of invitation for bids or request for proposal shall apply.

AMERICAN SOCIETY FOR TESTING AND MATERIALS

ASTM Designation E300 - Industrial Chemicals, Recommended Practice for Sampling

(Application for copies should be addressed to the American Society for Testing and Materials, 1916 Race Street, Philadelphia, Penn. 19103).

3. REQUIREMENTS

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:39Z
Check the source to verify that this is the current version before use.

3.1 Material. - Material and parts shall be in accordance with the applicable drawings and specifications.

3.2 Assembly. - The primer assembly shall comply with all requirements specified on Drawing (dwg.) 9298006 and with all requirements specified in applicable specifications.

3.3 Moisture content.

3.3.1 Primer Mixture. - At the time of loading, the moisture content of the primer mixture used in loading the primers shall not exceed 0.30 percent.

3.4 Functioning.

3.4.1 Output. - The primer shall function on the first attempt under an applied energy of 5.92 inch ounces, and shall cause a high order report when fired against the steel disc.

3.4.2 Waterproofness. - The primer shall be waterproof as evidenced by normal functioning, after being immersed in water maintained at 75 degrees Fahrenheit (°F) plus or minus 5 degrees F, at a depth of 2 inches minimum for not less than 48 hours.

3.5 Workmanship. - All parts and assemblies shall be fabricated and loaded in a thorough workmanlike manner, and all manufacturing, processing, and assembly operations shall be correctly performed. They shall be clean and free of burrs, sharp edges, unblended radii, surface defects, chips, dirt, grease and oil (except where specifically required), corrosion products and other foreign matter. The cleaning method used shall not be injurious to any part or assembly nor shall they be contaminated by the cleaning agent. Exterior surface coatings shall be continuous except for a few light scratches not exposing base material. All required markings shall be neat and sharply defined. Required packing shall be dry.

3.6 First Article Inspection. - This specification contains technical provisions for first article inspection. Requirements for the submission of first article samples by the contractor shall be as specified in the contract.

4. QUALITY ASSURANCE PROVISIONS

Source: https://assist.dla.mil -- Downloaded: 202610-22T19:39Z
Check the source to verify that this is the current version before use.

4.1 Responsibility for Inspection and Standard Quality Assurance Provisions. - Unless otherwise specified herein or in the contract, the provisions of MIL-A-48078 shall apply and are hereby made a part of this detail specification.

4.2 Classification of inspections. - The following types of inspection shall be conducted on this item.

a. First Article Inspection

b. Quality Conformance Inspection

4.3 First Article Inspection.

4.3.1 Submission. - The contractor shall submit a first article sample (see 6.1b) as designated by the Contracting Officer for evaluation in accordance with the provisions of 4.3.2 and 4.3.3. The first article sample shall consist of: fifty (50) complete sets of parts (i.e., 50 each of every component); and three hundred forty (340) loaded primers.

4.3.2 Inspections to be performed. - See MIL-A-48078 and paragraphs 4.4.2, 4.4.3 and Table I specified herein.

4.3.3 Rejection. - (See MIL-A-48078)

Source: https://assist.dla.mil -- Downloaded: 202610-22T19:39Z
Check the source to verify that this is the current version before use.

TABLE I

FIRST ARTICLE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-P-48760 (PA)

PARAGRAPH	TITLE	SHEET 1 OF 1			DRAWING NUMBER
*	Primer, Stab, M56, Parts and Complete Assemblies				See Below
					NEXT HIGHER ASSEMBLY
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
	Parts (Dwg. 9298007, 9298008) Examination for defects	50(a)		3.2	4.4.2.1 through 4.4.2.3
	Primers (Complete Assemblies) (Dwg. 9298006) Examination for defects	50(b)		3.2	4.4.2.4
	Tests				
	Functioning	315		3.4.1	
	Waterproofness	25		3.4.2	
	(a) 50 each on every component (b) Randomly selected from the 315 to be functioned				

NOTES:

SARPA-QA FORM 2567 FEB 74

Source: https://assist.dla.mil -- Downloaded: 2026-02-22T19:39Z
Check the source to verify that this is the current version before use.

4.4 Quality conformance inspection.

4.4.1 Inspection lot formation. - Inspection lots shall comply with the lot formation provisions of MIL-A-48078. In addition, inspection lots of primers shall contain:

a. Parts of one lot interfix number from one supplier.

b. Primer mixture from one batch or blending of batches, which result in homogeneity of all primer mixture used in the loading of a lot.

4.4.2 Examination. - (See MIL-A-48078). Unless otherwise specified in the classification of defects and test tables, sampling plans for major and minor defects shall be in accordance with MIL-STD-105, Inspection Level II. Equipment necessary for the performance of the inspections listed shall be in accordance with 4.4.4.

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:39Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-P-48760 (PA)

PARAGRAPH	TITLE	SHEET 1 OF 1	DRAWING NUMBER
4.4.2.1	Disc		9298008
			NEXT HIGHER ASSEMBLY

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major B					
131	Diameter		0.40%	3.2	Gage
132	Thickness		0.40%	3.2	Gage
Minor					
201	Evidence of poor workmanship		0.65%	3.5	Visual

NOTES:

SARPA-QA FORM 2567 FEB 74

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:39Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE	SHEET	DRAWING NUMBER
4.4.2.2	Cup, Prior to Coating	1 OF 1	9298007
			NEXT HIGHER ASSEMBLY

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major B					
131	Outside diameter		0.40%	3.2	Gage
132	Wall thickness		0.40%	3.2	Gage
133	Length		0.40%	3.2	Gage
134	Thickness through bottom		0.40%	3.2	Gage
Minor					
201	Evidence of poor workmanship		0.65%	3.5	Visual

NOTES:

SARPA-QA FORM 2567 FEB 74

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:39Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS MIL-P-48760 (PA)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 9298007
4.4.2.3	Cup, After Coating				NEXT HIGHER ASSEMBLY
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical					
1	Coating missing or contains bare spot		100.0%	3.2	Visual
Major A&B	None defined				
Minor					
201	Evidence of poor workmanship		0.65%	3.5	Visual

NOTES:

SARPA-QA FORM 2567 FEB 74

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:39Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

MIL-P-48760 (PA)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.4	Assembly				9298006
					NEXT HIGHER ASSEMBLY
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical					
1	Cup cracked or split		100.0%	3.2	Visual
Major B					
131	Length		0.40%	3.2	Gage
132	Diameter, max.		0.40%	3.2	Gage
133	Crimp not full 360 degrees		0.40%	3.2	Visual
134	Disc punctured or torn		0.40%	3.2	Visual
135	Cup damaged		0.40%	3.2	Visual
136	End color identification missing or incorrect		0.40%	3.2	Visual
137	Disc seal missing or incomplete		0.40%	3.2	Visual
Minor					
201	Evidence of poor workmanship		0.65%	3.5	Visual

NOTES:

SARPA-QA FORM 2567 FEB 74

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:39Z
Check the source to verify that this is the current version before use.

PARAGRAPH	TITLE	SHEET 1 OF 1	DRAWING NUMBER
4.4.2.5	Box, Set-up, Inner, After Loading and Prior to Closing Slide Cover		9258182
			NEXT HIGHER ASSEMBLY

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical					
1	Filler and cushion assembly missing		100.0%	3.2	Visual
2	Filler and cushion assembly improperly assembled		100.0%	3.2	Visual
3	Stiffner missing		100.0%	3.2	Visual
4	Slide cover assembled reversed		100.0%	3.2	Visual
Major A					
101	Release paper missing		0.40%	3.2	Visual
Minor					
201	Marking missing, incomplete or illegible		0.65%	3.2	Visual
202	Evidence of poor workmanship		0.65%	3.5	Visual

NOTES:

SARPA-QA FORM 2567 FEB 74

Source: https://assist.dla.mil -- Downloaded: 202610-22T19:39Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

MIL-P-48760 (PA)

PARAGRAPH	TITLE	SHEET	DRAWING NUMBER
4.4.2.6	Box, Set-Up, Outer, with Inner Set-Up Boxes Assembled and Prior to Assembling Top	1 OF 1	9258183
			NEXT HIGHER ASSEMBLY

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical					
1	Red surfaces on inner set-up boxes do not alternate on same side of outer set-up boxes		100.0%	3.2	Visual
2	Stiffner not facing one direction		100.0%	3.2	Visual
Major A&B	None defined				
Minor					
201	Marking missing, incomplete or illegible		0.65%	3.2	Visual
202	Box improperly taped		0.65%	3.2	Visual
203	Evidence of poor workmanship		0.65%	3.5	Visual

NOTES:

SARPA-QA FORM 2567 FEB 74

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:39Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

MIL-P-48760 (PA)

PARAGRAPH	TITLE	SHEET	DRAWING NUMBER
4.4.2.7	Sealed Packed Barrier Bag, Prior to Packing in Box	1 OF 1	9258183
			NEXT HIGHER ASSEMBLY

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major A					
101	Waterproofness of barrier bag destroyed by rupture, puncture or separation of heat seal		0.40%	3.2	Visual
102	Evidence of crushed box		0.40%	3.2	Visual
NOTE:	Package should be opened if there is evidence of crushing				
Minor					
201	Heat seal of barrier bag located so that one or more subsequent seals cannot be applied		0.65%	3.2	Visual
202	Marking of bag misleading or unidentifiable		0.65%	3.2	Visual
203	Evidence of poor workmanship		0.65%	3.5	Visual

NOTES:

SARPA-QA FORM 2567 FEB 74

Source: https://assist.dla.mil -- Downloaded: 202640-22T19:39Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

MIL-P-48760 (PA)

PARAGRAPH	TITLE	SHEET	DRAWING NUMBER
4.4.2.8	Box, Packing, Ammunition Prior to Assembling Cover and Strapping	1 OF 1	9258184
			NEXT HIGHER ASSEMBLY

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major B					
131	Bags containing set-up boxes damaged		0.40%	3.2	Visual
132	Cushioning material incomplete or missing from around outer set-up boxes		0.40%	3.2	Visual
133	Marking missing, misleading or unidentifiable		0.40%	3.2	Visual
134	Contents loose within box		0.40%	3.2	Visual/Manual
Minor					
201	Evidence of poor workmanship		0.65%	3.5	Visual

NOTES:

SARPA-QA FORM 2567 FEB 74

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:39Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

MIL-P-48760 (PA)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.9	Box, Packing, Ammunition				9258184
					NEXT HIGHER ASSEMBLY
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major A					
101	Strapping missing, broken, loose or improperly fastened		0.40%	3.2	Visual/Manual
102	Box damaged		0.40%	3.2	Visual
103	Marking missing, incomplete or unidentifiable		0.40%	3.2	Visual
104	Wooden box cover nailed to box		0.40%	3.2	Visual
105	Metallic seal missing		0.40%	3.2	Visual
Minor					
201	Evidence of poor workmanship		0.65%	3.5	Visual

NOTES:

SARPA-QA FORM 2567 FEB 74

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:39Z
Check the source to verify that this is the current version before use.

4.4.3 Testing.

4.4.3.1 Chemical sampling. - A representative sample shall be randomly selected for the tests specified in 4.4.3 The procedure described in ASTM E300 should be used to withdraw the samples. The tests of 4.5 shall be performed using prescribed analytical procedure for replicate determinations given in standard analytical textbooks.

4.4.3.2 Moisture content.

4.4.3.2.1 Primer mixture. - (see 3.3.1) - Major A defect. - The moisture content of the primer mixture shall be determined for each batch or blend of batches at the time of loading. A sample, in sufficient quantity to perform the test detailed in 4.5.1, shall be selected and tested as specified in 4.5.1. If the moisture content is in excess of the percentage specified and loading has not begun, the batch or blend of batches of primer mixture shall be rejected. If loading has begun, action on the unloaded primer mixture shall be as specified above and all detonators loaded with the questionable primer mixture shall be rejected.

4.4.3.3 Functioning.

4.4.3.3.1 Output. - (see 3.4.1) - Major A defect. -A sample of 315 detonators shall be selected at random from each lot. If 3 or more detonators fail to comply with the requirement specified the lot shall be rejected. If one or two defects are found, a second sample of 315 shall be selected at random and tested. If, in the combined first and second sample, a total of 4 or more defects are found the lot shall be rejected. The test shall be performed as specified in 4.5.2.1.

4.4.3.3.2 Waterproofness. - (see 3.4.2) Major A defect. - A sample of 25 primers shall be selected at random from each lot. If one or more primers fail to comply with the requirement specified the lot shall be rejected. The test shall be performed as specified in 4.5.2.2 using test equipment as specified in 4.4 4 and 4.5.2.2.

4.4.3.4 Determination of composition of primer mixture. - (see dwg. 9298009) - Major A defect. - A sample of approximately one gram shall be selected from each batch or blend of batches

Source: https://assist.dla.mil -- Downloaded: 202610-22T19:39Z
Check the source to verify that this is the current version before use.

for test as specified in 4.5.3. All the composition represented by the sample shall be rejected if the sample fails to comply with the requirements.

4.4.3.5 Heat seal test of sealed bag. - (see dwg. 9258183) - Major A defect. - Sampling, acceptance criteria and test procedures for this test shall be as specified in MIL-P-116.

4.4.4 Inspection Equipment. - The inspection equipment required to perform the inspections and tests prescribed in this specification is identified in the 'Paragraph Reference/ Inspection Method' column in the tables starting with paragraph 4.4.2.1, and the test method paragraphs (see 4.5). The contractor shall submit for approval, inspection equipment designs in accordance with the terms of the contract. See Section 6 of MIL-A-48078, and section 6.2 herein.

4.5 Test methods and procedures.

4.5.1 Moisture content of the primer mixture. - The moisture content of the primer mixture shall be determined in accordance with MIL-STD-650, Method 101.5 except that drying temperature shall be 60 plus or minus 5 degrees C. and only 0.40 to 0.70 grams of primer mixture shall be dried.

4.5.2 Functioning.

4.5.2.1 Output. - The primer shall be assembled to the applicable test equipment and a steel ball weighing a maximum of 3.95 ounces shall be dropped from a maximum height of 1 1/2 inches on the firing pin of the test set up. A primer that fails to fire or fails to fire with a high order report shall be classed defective. The method of inspection shall be in accordance with dwgs. 8816367, 8827828, 8827829, 8827934, 9202650, 920012 and 9201952.

4.5.2.2 Waterproofness. - The primers shall be immersed under water to the required depth for the specified time. The primer shall be subjected to the functioning test specified in 4.5.2.1 within one hour after removal from water. Any primer which fails to fire or fails to create a hole in the lead disc of the required size shall be classed defective.

4.5.3 Determination of composition of primer mixture.

Source: https://assist.dla.mil -- Downloaded: 202610-22T19:39Z
Check the source to verify that this is the current version before use.

4.5.3.1 Potassium chlorate.

4.5.3.1.1 Preparation of solutions.

4.5.3.1.1.1 Solution Number 1. - To approximately 800 ml. distilled water, in a one liter amber glass bottle, 40.0 grams (gm.) of potassium thiocyanate shall be added. The bottle shall be sealed with a rubber stopper and the reagent bottle and contents shaken until the solid material is dissolved. To this solution 1.0 gm. of lead thiocyanate, 1.0 gm. of antimony sulfide and 1.0 gm. of lead azide shall be added. The bottle shall again be stoppered and the reagent bottle and contents vigorously shaken for several minutes, and then allowed to stand overnight. Portions of the saturated solution shall be filtered before using.

4.5.3.1.1.2 Solution Number 2. - To approximately 400 ml. of distilled water, in a one-half liter amber glass reagent 1.0 gm. of lead thiocyanate, 1.0 gm. of antimony sulfide and 1.0 gm. of lead azide shall be added. The bottle shall be sealed with a rubber stopper and the reagent bottle and contents vigorously shaken for several minutes and then allowed to stand overnight. Portions of the saturated solution shall be filtered before using.

4.5.3.1.2 Procedure. - A portion of approximately 1.0 gm. of the sample shall be accurately weighed directly into a tared 30 ml. sintered glass crucible of medium porosity. From a burette 3.0 ml. of Solution Number 1 shall be added to the crucible. The solution shall be swirled for exactly one minute, taking care not to spill any liquid; aspirated with suction and the bottom of the crucible wiped dry using tissue paper. The washing shall be continued, using one more 3.0 ml. portion, two 2.0 ml. and two 1.0 ml. portions, making a total of 12.0 ml. The crucible shall be removed and the bottom of the crucible, the funnel, the adapter and the suction flask washed with water. The test tube shall be placed in the flask and the stem of the filtering funnel inserted into the test tube. The crucible and contents shall be washed with one 1.0 ml. portion of Solution Number 1 as above, and aspirated with suction, catching the filtrate in the test tube. The test tube shall be removed, 1.0 ml. of distilled water added and the chlorate ion, determined as follows:

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:39Z
Check the source to verify that this is the current version before use.

The tube shall be inclined at an angle of about 45 degrees and from a dropper about 0.5 ml. of a solution containing 1.0 gm. of diphenylamine in 100 gm. of concentrated sulfuric acid added in two distinct layers. If an appreciable amount of chlorate ion is present, a distinct blue ring will be visible at the border of the two layers. On shaking the tube, the ring disappears, but the contents assume a blue coloration, which lasts several seconds, depending on the amount of chlorate ion present. If only a trace of chlorate ion is present the blue ring may not form, but upon shaking the test tube, a slight bluish coloration will appear momentarily throughout the solution, lasting only a fraction of a second. If a definite blue ring forms, the washing shall be repeated as before using one 1.0 ml. portion of Solution Number 1, and finally a 0.5 ml. portion of the same solution, as needed, depending on the outcome of the tests for the chlorate ion. (Usually a total of 14.0 or 14.5 ml. of Solution Number 1 is sufficient). After complete removal of potassium chlorate the inside of the crucible shall be washed with 1.0 ml of Solution Number 2 and aspirated immediately. The bottom of the crucible shall be wiped dry with tissue paper and dried in an oven at 80 degrees C. plus or minus 1 degree C. for 30 minutes, cooled in a desiccator and weighed. The percentage of potassium chlorate shall be calculated as follows:

Potassium Chlorate, percent = 100B divided by W (1-M)

where:

B = loss in weight of contents of crucible, grams.
W = weight of sample, grams.
M = percent moisture divided by 100

4.5.3.2 Antimony sulfide.

4.5.3.2.1 Preparation of solution of Ferric ammonium sulfate. - To approximately 120 ml. of distilled water, in a one-half liter reagent bottle, 125 gm. of ferric ammonium sulfate shall be added. The bottle shall be stoppered and shaken vigorously for several minutes ahd then allowed to stand overnight. Portions of the saturated solution shall be filtered before using.

4.5.3.2.2 Procedure. - A portion of approximately 1 gm. of the sample shall be accurately weighed directly into a tared 30 ml. sintered glass crucible of medium porosity.

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:39Z
Check the source to verify that this is the current version before use.

Five ml. of one percent nitric acid shall be added and the crucible constantly swirled for one minute in order to dissolve all the ingredients of the powder except antimony sulfide. Care shall be taken not to spill any liquid. The mixture shall be filtered by applying suction employing a vacuum flask. The crucible shall be removed from the adapter and the bottom wiped dry with tissue paper. The operations of washing, using 5.0 ml. of one percent nitric acid each time and swirling for exactly one minute shall be repeated. After a total of 40 ml. of one percent nitric acid has been used, the crucible shall be removed and the bottom of it washed with water. The funnel, the funnel adapter and the vacuum flask shall be washed with water; the filtrate and washings shall be discarded. About 1 ml. of saturated solution of ferric ammonium sulfate shall be placed in the flask. The contents of the crucible shall be treated as before with 5.0 ml. of one percent nitric acid and filtered by means of suction into the flask. If the liquid in the flask turns red, due to the presence of the thiocyanate ion in the filtrate, the washing of the contents in the crucible shall be repeated with additional 5.0 ml. portions of one percent nitric acid until a negative test for the thiocyanate ion is affected. (Usually a total of 50 ml. is sufficient). The crucible and contents shall be dried in an oven at 80 degrees C. plus or minus 1 degree C. for 30 minutes, cooled in a desiccator and weighed. The percentage of antimony sulfide shall be calculated as follows:

Antimony sulfide, percent = 100A divided by B

where:
A = weight of residue in the crucible
B = weight of sample on a moisture-free basis

4.5.3.3 Lead thiocyanate. - The percentage of lead thiocyanate in the sample shall be calculated on a moisture-free basis by subtracting from 100 the sum of the percentages of potassium chlorate and antimony sulfide.

5. PREPARATION FOR DELIVERY

5.1 Preservation and packaging.

*5.1.1 Level C. - The primers shall be packaged in accordance with dwgs. 9258182 and 9258183.

Source: https://assist.dla.mil -- Downloaded: 202610-22T19:39Z
Check the source to verify that this is the current version before use.

5.1.2 Level C. - The primer parts shall be packaged in accordance with MIL-STD-1169 requirements.

5.2 Packing.

5.2.1 Level C. - The primers shall be packed in accordance with dwg. 9258184.

5.2.2 Level C. - The primer parts shall be packed in accordance with MIL-STD-1169 requirements.

5.3 Marking. - Primer containers and bags shall be marked in accordance with instructions contained in dwgs. 9258182, 9258183 and 9258184. Primer parts containers shall be marked in accordance with MIL-STD-1169 requirements.

6. NOTES

6.1 Ordering Data. - Procurement documents shall specify the following:

a. Title, number and date of this specification.

b. Provisions for submission of first article samples.

c. Provisions of MIL-A-48078.

6.2 Submission of Inspection Equipment Designs for Approval. - (See MIL-A-48078). Submit equipment designs as required, to Commander: Picatinny Arsenal, ATTN: SARPA-QA-T Dover, New Jersey 07801.

6.3 Distribution of ammunition data cards. - Distribution of data cards shall include the following: Commander, Picatinny Arsenal, ATTN: SARPA-QA-A-M Dover, New Jersey 07801.

6.4 Check test for possible deterioration. - The following test is designed to prevent primers that have deteriorated from being assembled into major ammunition items. The test shall be performed on primers from each lot which have been stored under normal conditions for more than two years or under adverse conditions for any period of time. If the specification for the ammunition item into which the primers are assembled does not require that the check test be performed, the Contracting Officer should insert in the contract a provision for the performance of the

Source: https://assist.dla.mil -- Downloaded: 202610-22T19:39Z
Check the source to verify that this is the current version before use.

check test. The Contracting Officer will arrange for the contractor to be reimbursed for expense incurred in his performance of the check test for possible deterioration. Primer assemblies shall be selected from each lot for this test.

6.4.1 Functioning. - A sample of 315 primers shall be selected at random from each lot. If 4 or more primers fail to comply with the requirement specified, the lot shall be rejected. If one or two defectives are found, a second sample of 315 shall be selected at random and tested. If in the combined first and second sample a total of 5 or more defectives are found the lot shall be rejected. The test shall be performed as specified in 4.5.3.1.

6.5 This specification contains the requirements, from MIL-P-14100, for the M56 Primer only.

Custodian:
Army-PA

Preparing Activity:
Army-PA

Project No.: 1375-A-132

Source: https://assist.dla.mil -- Downloaded: 202610-22T19:39Z
Check the source to verify that this is the current version before use.

FOLD

POSTAGE AND FEES PAID
DEPARTMENT OF THE ARMY
DOD – 314

OFFICIAL BUSINESS
PENALTY FOR PRIVATE USE $300

COMMANDER
Picatinny Arsenal
ATTN: SARPA-QA-A
Dover, New Jersey 07801

FOLD

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:39Z
Check the source to verify that this is the current version before use.

STANDARDIZATION DOCUMENT IMPROVEMENT PROPOSAL

OMB Approval
No. 22-R255

INSTRUCTIONS: The purpose of this form is to solicit beneficial comments which will help achieve procurement of suitable products at reasonable cost and minimum delay, or will otherwise enhance use of the document. DoD contractors, government activities, or manufacturers/ vendors who are prospective suppliers of the product are invited to submit comments to the government. Fold on lines on reverse side, staple in corner, and send to preparing activity. Comments submitted on this form do not constitute or imply authorization to waive any portion of the referenced document(s) or to amend contractual requirements. Attach any pertinent data which may be of use in improving this document. If there are additional papers, attach to form and place both in an envelope addressed to preparing activity.

DOCUMENT IDENTIFIER AND TITLE

NAME OF ORGANIZATION AND ADDRESS

CONTRACT NUMBER

MATERIAL PROCURED UNDER A

☐ DIRECT GOVERNMENT CONTRACT ☐ SUBCONTRACT

1. HAS ANY PART OF THE DOCUMENT CREATED PROBLEMS OR REQUIRED INTERPRETATION IN PROCUREMENT USE?

A. GIVE PARAGRAPH NUMBER AND WORDING.

B. RECOMMENDATIONS FOR CORRECTING THE DEFICIENCIES

2. COMMENTS ON ANY DOCUMENT REQUIREMENT CONSIDERED TOO RIGID

3. IS THE DOCUMENT RESTRICTIVE?

☐ YES ☐ NO *(If "Yes", in what way?)*

4. REMARKS

SUBMITTED BY *(Printed or typed name and address - Optional)*

TELEPHONE NO.

DATE

DD FORM 1 JAN 72 1426 REPLACES EDITION OF 1 JAN 66 WHICH MAY BE USED

Source: https://assist.dla.mil -- Downloaded: 202610-22T19:39Z
Check the source to verify that this is the current version before use.