# MILITARY SPECIFICATION

# MAX-2 EXPLOSIVE

## 1. SCOPE

1.1 This specification covers one type of explosive designated as MAX-2, for use in ammunition.

## 2. APPLICABLE DOCUMENTS

2.1 The following documents of the issue in effect on date of invitation for bids, form a part of this specification to the extent specified herein:

SPECIFICATIONS

FEDERAL

RR-S-366 - Sieves, Standard, For Testing Purposes.

MILITARY

JAN-G-155 - Graphite (For Use in Ammunition).
JAN-A-289 - Aluminum Powder, Flaked, Grained and Atomized (For Use in Ammunition).
MIL-C-440 - Compositions A3 and A4.
MIL-B-13239 - Barrier Material, Waterproofed, Flexible, All Temperature.

STANDARDS

MILITARY

MIL-STD-105 - Sampling Procedures and Tables for Inspection by Attributes.
MIL-STD-109 - Inspection Terms and Definitions.
MIL-STD-286 - Propellants: Sampling, Inspection and Testing.



Source: https://assist.dla.mil -- Downloaded: 2026-10-22T05:23Z
Check the source to verify that this is the current version before use.

DRAWINGS

ORDNANCE CORPS

F-7548645 - Carton, Packing, Reuseable, Collapsible for High Explosives, Assembly, Details, Packing and Marking.

2.2 Other publications.-The following document forms a part of this specification to the extent specified herein. Unless otherwise indicated, the issue in effect on date of invitation for bids shall apply.

CODE OF FEDERAL REGULATIONS

49 CFR 71-78 - Interstate Commerce Commission Rules and Regulations for the Transportation of Explosives and Other Dangerous Articles.

(The Interstate Commerce Commission Regulations are now a part of the Code of Federal Regulations (1949 Edition and revisions) available from the Superintendent of Documents, Government Printing Office, Washington 25, D.C. Orders for the above publication should cite "49 CFR 71-78 (latest revision)".)

3. REQUIREMENTS

3.1 Materials.-MAX-2 explosive shall consist of the ingredients specified in Table I. The aluminum shall be dichromated prior to use.

3.1.1 Ingredients.-The ingredients used in the manufacture of MAX-2 shall conform to the following specifications:

Table I

| Ingredient | Conforming to specification |
|---|---|
| Aluminum powder | JAN-A-289, Type C, Class A |
| Composition A-4 | MIL-C-440 |
| Graphite | JAN-G-155, Grade IV |



Source: https://assist.dla.mil -- Downloaded: 2026-10-22T05:23Z
Check the source to verify that this is the current version before use.

3.1.2 Aluminum

3.1.2.1 Prior to dichromation.

3.1.2.1.1 Granulation.-The aluminum powder shall have the granulation specified in Table II, when tested as specified in 4.3.3.

Table II

| *U. S. Standard Sieve | Percent passed through |
|---|---|
| *No. 100 | 99.5 min.* |
| No. 325 | 75.0 min. |

*Abbreviations
U.S. = United States
No. = Number
min. = minimum

3.1.2.1.2 Average particle size.-The average particle size shall be 18 ± 6 microns, when determined as specified in 4.3.4.

3.1.2.2 After dichromation.

3.1.2.2.1 Chromium content.-The chromium content of the dichromated aluminum shall be 0.17 ± 0.03 percent, when tested as specified in 4.3.5.

3.2 Moisture.-The moisture content of MAX-2 shall be 0.15 percent maximum (max.), when tested as specified in 4.3.1.

3.3 Composition.-For analytical purposes, the MAX-2 shall be of the following composition, when tested as specified in 4.3.2.

| Ingredient | Parts by weight |
|---|---|
| Dichromated aluminum powder | 61.1 ± 1.0 |
| Composition A-4 | 37.4 ± 0.5 |
| Graphite | 1.5 ± 0.2 |

4. QUALITY ASSURANCE PROVISIONS

4.1 General quality assurance provisions.-The supplier is responsible for the performance of all inspection requirements specified herein. Except as otherwise specified, the supplier may utilize his own or any other inspection facilities and services acceptable to the Government. Inspection records of the examinations and tests shall be



Source: https://assist.dla.mil -- Downloaded: 2026-10-22T05:23Z
Check the source to verify that this is the current version before use.

kept complete and available to the Government as specified in the contract or order. The Government reserves the right to perform any of the inspections set forth in the specification where such inspections are deemed necessary to assure supplies and services conform to prescribed requirements. Reference shall be made to Standard MIL-STD-109 in order to define the terms used herein. Inspection shall be performed in accordance with this specification and other specifications referenced in any of the contractual documents.

4.1.1 Contractor quality assurance system.-If the contractor desires to utilize a quality assurance system which is at variance with the quality assurance provisions of 4.2 and 4.3 and other documents referenced herein, he shall submit a written description of the system to the contracting officer for approval prior to initiation of production. It shall include a description covering controls for lot formation and identification, inspections to be performed, inspection stations, sampling procedures, methods of inspection, (measuring and testing equipment), and provisions for control and disposition of non-conforming material. The written description shall be considered acceptable when, as a minimum, it provides the quality assurance provisions required by the provisions of 4.2 and 4.3 and the other documents referenced herein. The contractor shall not be restricted to the inspection station nor the method of inspection listed in this specification provided that an equivalent control is included in the approved quality assurance procedure. In cases of dispute as to whether certain procedures of the contractor's system provide equal assurance, the comparable procedure of this specification shall apply. The contractor shall notify the Government of, and obtain approval for, any changes to the written description that affects the degree of assurance required by this specification or other documents referenced herein.

4.1.2 Submission of product.-At the time the completed lot of product is submitted to the Government for acceptance, the contractor shall supply the following information accompanied by a certificate which attests that the information provided is correct and applicable to the product being submitted:

a. A statement that the lot complies with all quality assurance provisions of the approved current written description of the system.

b. Quantity of product inspected.

c. Results obtained for inspection performed.

d. Specification number and date, together with an identification and date of changes.



Source: https://assist.dla.mil -- Downloaded: 2026-10-22T05:23Z
Check the source to verify that this is the current version before use.

e. Certificates of analysis on all material procured directly by the contractor.

f. Quantity of product in the lot.

g. Date submitted.

The certificate shall be signed by a responsible agent of the certifying organization. The initial certificate submitted shall be substantiated by evidence of the agent's authority to bind his principal. Substantiation of the agent's authority will not be required with subsequent certificates unless, during the course of the contract, this authority is vested in another agent of the certifying organization.

4.1.3 Government verification.-Using the contractor's written quality assurance procedure (see 4.1.1), this detail specification, and other contractual documents as a guide, the Government inspector shall verify all quality assurance operations performed by the contractor. Verification shall be in accordance with a or b, as applicable, the decision being the responsibility of the procuring activity. In either case, the Government inspector shall also ascertain, prior to acceptance, that the product with all quality assurance provisions of other specifications referenced in any of the contractual documents. Deviations from prescribed or agreed upon procedures discovered by the Government inspector shall be brought to the attention of the supplier. Disposition of the product and remedial action shall be as directed by the Government inspector and, depending on the nature of the deviations, may consist of lot rejection, screening, re-sampling, re-instruction of the supplier's employees, or other appropriate action:

a. Verification at the point of manufacture shall be accomplished at unscheduled intervals in accordance with 4.1.3.1 and 4.1.3.2.

b. Verification at the point of delivery shall be in accordance with 4.1.4.2.

4.1.3.1 Surveillance.-Surveillance shall include, but is not limited to:

a. Observation of procedures concerning lot formation and identification.

b. Observation of sampling procedures and application of acceptance criteria.

c. Determination that all required examinations and tests are performed in accordance with the prescribed procedures of this specification, or approved equivalents thereto.

d. Review of procedures for control and disposition of non-conforming material.



Source: https://assist.dla.mil.-- Downloaded: 2026-10-22T05:23Z
Check the source to verify that this is the current version before use.

4.1.3.2 Product inspection.-Product inspection shall consist of Government inspection of product which has been previously inspected by the contractor and found to meet the quality assurance provisions of this specification. The inspection by the Government shall be performed in order to determine that the product is of the quality required by this specification and that the contractor's records are reliable.

4.2 Inspection provisions.

4.2.1 Lot formation.-A lot shall consist of one or more batches of MAX-2 explosive, produced by one manufacturer, in accordance with the same specification or specification revision, under one continuous set of operating conditions. Each batch shall consist of that quantity of MAX-2 that has been subjected to the same unit chemical or physical mixing process intended to make the final product homogeneous. In addition, each lot shall contain Composition A4 from not more than one lot, from one manufacturer only.

4.2.2 Examination.-Sampling plans and procedures for the following classifications of defects shall be in accordance with Standard MIL-STD-105 except that inspection for critical defects, when tested, shall be 100 percent. Continuous sampling plans in accordance with Handbook ORD-M608-11 may be used if approved by the procuring activity. Also, at the option of the procuring activity, AQL's and sampling plans may be applied to the individual characteristics listed using an AQL of 0.25 percent for each major defect and an AQL of 0.40 percent for each minor defect.

4.2.2.1 Fiberboard carton prior to closing (see dwg. F-7548645).

| Categories | Defects | Method of inspection |
|---|---|---|
| Critical: | None defined | |
| Major: | AQL 0.40 percent | |
| 101. | Foreign matter ..... | Visual |
| 102. | Liner pierced or torn ..... | Visual |
| 103. | Liner improperly closed ..... | Visual |
| Minor: | AQL 0.40 percent | |
| 201. | Type of liner incorrect ..... | Visual |



Source: https://assist.dla.mil -- Downloaded: 2026-10-22T05:23Z
Check the source to verify that this is the current version before use.

4.2.2.2 Sealed fiberboard carton (see dwg. F-7548645).

| Categories | Defects | Method of inspection |
|---|---|---|
| Critical: | None defined | |
| Major: | AQL 0.25 percent | |
| 101. | Assembly torn or pierced | Visual |
| 102. | Banding strips, missing, broken or loose | Visual-Manual |
| Minor: | AQL 1.50 percent | |
| 201. | Stitches missing or loose | Visual |
| 202. | Marking misleading or unidentifiable | Visual |
| 203. | Banding strips improperly assembled | Visual-Manual |

4.2.3 Tests.

4.2.3.1 Sampling.

4.2.3.1.1 Aluminum.-Five 8 ounce samples shall be selected at random from each lot prior to dichromating. If the lot consists of 5 batches or less, one sample shall be taken from each batch. Each sample shall be placed in an airtight container, labeled to show the name of the material, manufacturer, contract or purchase order number, batch and lot number. Each sample shall be subjected to the tests specified in 4.3.3 and 4.3.4.

4.2.3.1.2 Dichromated aluminum.- Five 8 ounce samples shall be selected at random from each lot after dichromation. If the lot consists of 5 batches or less, one sample shall be taken from each batch. Each sample shall be placed in an airtight container, labeled to show the name of the material, manufacturer, contract or purchase order number, batch and lot number. Each sample shall be subjected to the determination of chromium as specified in 4.3.5.

4.2.3.1.3 MAX-2.-Five 8 ounce samples shall be selected at random from each lot. If the lot consists of 5 batches or less, one sample shall be taken from each batch. Each sample shall be placed in an airtight container, labeled to show the name of the material, manufacturer, contract or purchase order number, batch and lot number. Each sample shall be subjected to the tests specified in 4.3.



Source: https://assist.dla.mil -- Downloaded: 2026-10-22T05:23Z
Check the source to verify that this is the current version before use.

4.2.3.2 Rejection and resubmission.-If any sample fails to comply with any requirement, the lot shall be rejected subject to reworking and resubmission. The resubmitted lot shall be considered rejected if any new sample selected in accordance with 4.2.3.1, fails to pass all the tests required by this specification.

4.3 Test methods and procedures.

4.3.1 Determination of moisture content.

4.3.1.1 Procedure.-The following test shall be performed on each sample: Transfer an accurately weighed portion of approximately 1 gram (gm.) of the sample to a tared moisture dish 2 inches in diameter. Place the dish and contents in an oven maintained at 60° ± 5 degrees Centigrade (°C.) for 2 hours, cool in a desiccator and weigh. Calculate the loss in weight of the dish and contents to percent moisture as follows:

$$\text{Percent moisture} = \frac{100A}{W}$$

where:

A = loss in weight of moisture dish and contents.
W = weight of specimen.

4.3.2 Composition.

4.3.2.1 Determination of composition A-4 content.-Place an accurately weighed 1.0 gm. specimen of moisture-free MAX-2 in a tared, sintered porcelain crucible and extracted with 10 successive 20 milliliter (ml.) portions of hot carbon tetrachloride. Allow each portion to remain in contact with the sample for a minimum of two minutes prior to suction filtering. Repeat 10 extractions using 20 ml. each of hot acetone. Dry crucible at 60 ± 5°C. for one hour, cool and weigh. Repeat extraction procedure until the change in weight is less than 0.005 gm. Calculate the loss in weight of the crucible and contents to percent composition A-4 in the specimen as follows:

$$\text{Percent omposition A-4} = \frac{100\ (A-B)}{W}$$

where:

A = weight of curcible and residue after extraction of moisture.
B = weight of crucible and residue after extraction with carbon tetrachloride and acetone.
W = weight of specimen.



Source: https://assist.dla.mil -- Downloaded: 2026-10-22T05:23Z
Check the source to verify that this is the current version before use.

4.3.2.2 Determination of dichromated aluminum.-Transfer the crucible and contents from the composition A-4 extraction to a 400 ml. beaker containing 15 ml. of 1:3 sulfuric acid and 10 ml. of water. Cover the beaker with a cover glass and heat until no further reaction is observed between the aluminum and acid. Wash the outside of the crucible with small portions of water, allowing the washings to fall back into the beaker. (Entire washing procedure is done while holding the crucible above the beaker with forceps). Aspirate the crucible. Pour the contents of the beaker into the crucible. Wash the inside of the beaker with water allowing all washings to fall into the crucible. Aspirate the crucible and wash the inside of the crucible with small portions of water. Dry the crucible and residue at 100°C. to constant weight. Cool in a desiccator and weigh. Reserve the residue in the crucible for determination of graphite. Calculate the loss in weight of the crucible and contents to percent aluminum as follows:

$$\text{Percent dichromated aluminum} = \frac{100\ (B-C)}{W}$$

where:

B = weight of crucible and residue after extraction with carbon tetrachloride and acetone.
C = weight of crucible and residue after extraction with sulfuric acid solution.
W = weight of specimen.

4.3.2.3 Determination of graphite.-Calculate the weight of the dry residue in the crucible, obtained after treatment with sulfuric acid solution, to determine the graphite content as follows:

$$\text{Percent graphite} = \frac{100\ (C-D)}{W}$$

where:

C = weight of crucible and residue after treating with sulfuric acid solution.
D = weight of crucible empty.
W = weight of specimen.

4.3.3 Granulation (prior to dichromation).-The granulation shall be determined in accordance with Standard MIL-STD-286, Method 506.1 except that a 100 gm. specimen shall be used.



Source: https://assist.dla.mil -- Downloaded: 2026-10-22T05:23Z
Check the source to verify that this is the current version before use.

4.3.4 Determination of particle size by Fisher Sub-Sieve Sizer prior to dichromation.

4.3.4.1 Checking of apparatus.-With the sample tube removed from the instrument, the level of the water in the pressure regulator standpipe shall be checked daily. The water level shall correspond exactly with the etched calibration mark on the standpipe. If necessary, water shall be removed or added to the standpipe through the glass intake arm extending through the top of the instrument cabinet. The indicating type drying agent shall be checked once every week or month, depending upon how often the instrument is used. If the agent is blue in color, it is satisfactory. When the color turns to pink, the agent shall be replaced with fresh stock. The sample packing assembly shall be checked about once every month or whenever there is reason to suspect that the brass post beneath the rack and pinion has shifted in position. This adjustment shall be made by inserting both porous plugs and paper disks into the sample tube. The sample tube shall then be placed on the brass post with the lower plug in contact with the upper end of the post. With the rack in the front panel turned down, the two plugs shall be in contact when the crossbar, attached to the upper end of rack, coincides exactly with the baseline on the calculator chart. If the plugs are not in contact or the pointer does not coincide with the baseline, adjustment shall be necessary. Adjustment of the packing assembly shall be made by loosening the setscrew holding the lower brass post in its mounts. The height of the post shall then be such that the crossbar pointer coincides exactly with the baseline of the calculator chart when the porous plugs are held firmly between the brass post and flat lower end of the rack. The level of the water in the manometer shall be checked every time a new series of particle size determinations is begun. The initial level of the water meniscus in the manometer tube shall coincide exactly with the upper edge of the curved portion of the metal crossbar when the tip of the pointer coincides exactly with the baseline of the calculator chart. If necessary, adjustment of the manometer level shall be made by turning the manometer control knob. It is important to note, that the sample tube shall be removed from the instrument when either checking or adjusting the level of the water in the manometer tube.

4.3.4.2 Calibration and standardization.-The instrument shall be calibrated and standardized by the following methods.



Source: https://assist.dla.mil -- Downloaded: 2026-10-22T05:23Z
Check the source to verify that this is the current version before use.

4.3.4.2.1 Calibration.-The calibrator is used in the Fisher Sub-Sieve Sizer in exactly the same manner as a normal sample tube with the sample all ready in place and packed. The calculator chart is set to indicate a porosity of 0.75 and the level of the liquid meniscus in the manometer is checked as described in 4.3.4.3. The calibrator, without porous plugs or filter paper, is mounted as described in 4.3.4.3. The reading marked high will be obtained with the range control set to the 0.2 to 20.0 micron range. The low reading is the actual chart reading obtained with the range control set to the 20 to 50 micron range.

4.3.4.2.2 Standardization.-In the event the readins obtained with the calibrator do not agree within 0.05 microns of the value stamped on the calibrator (see 4.3.4.4), the instrument should be standardized. To do this, proceed as follows: Remove the back panel and turn the instrument to bring the right side forward. There are two glass capillary tubes mounted on the right rear side of the front panel and connected into the system with rubber tubing. The instrument readings are made to coincide with the calibrator readings by moving the fine wires in or out of the capillary tubes. The range control should be set to the 0.2 to 20 micron range, and the setscrew holding the fine wire in position should be loosened. To raise the meniscus in the manometer, the wire in the capillary nearest the right side of the case should be moved further up into the capillary tube. Conversely, to lower the meniscus, the wire should be withdrawn. At least 30 seconds should elapse between moving the wire and taking a reading, to allow the meniscus to stablize. When this wire is adjusted so that the meniscus reads the high value stamped on the calibrator, the setscrew holding the wire is tightened down, the range switch is put into the 20 to 50 micron position, and the same procedure followed with second wire. When this is finished, the back is replaced, and the instrument is again ready for use.

4.3.4.2.3 Cleaning.-Under normal conditions of cleanliness there is not much change of any dirt clogging the ruby orifice. However, the tube can be cleaned by flushing with acetone and drying with vacuum. The orifice should not be cleaned with a wire, since the ruby can be chipped.

4.3.4.2.4 Temperature variation.-The calibrator value was determined at a temperature of 77°F. and a slight variation in readings occur both above and below this temperature. For a temperature change of plus or minus 10°F. the calibration value change is about plus or minus 0.1 micron and should be allowed for whenever the readings obtained disagree with the values given on the tube.



Source: https://assist.dla.mil -- Downloaded: 2026-10-22T05:23Z
Check the source to verify that this is the current version before use.

4.3.4.3 Procedure.-After the instrument settings have been checked, the sample tube shall be placed in a vertical position in a rubber support stand. A paper disk shall be placed over the end of the sample tube. The porous plug shall then be placed on the filter paper with the perforated surface of the plug against the surface of the paper disk. The plug shall be pushed into the tube for about 1/2 inch, forcing the paper to crimp around the edges and preceed the plug into the sample tube. The sample tube shall be inverted in the rubber support stand so that the paper side of the plug is up. A 2.70 gm. portion of aluminum powder shall be weighed to ± 0.01 gm. With the aid of a funnel, the specimen shall be transferred completely into the tube. A second paper disk and porous plug shall be placed into the sample tube as previously described. The specimen, which is now contained between the filter papers and plugs, shall be pressed manually as tightly as possible with the aid of the plug manipulator or a metal or plastic rod. The specimen, pressed as tightly as possible in this way is said to be at "minimum porosity". The sample tube shall be placed on the brass post with the lower plug in contact with the brass post. The pinion knob shall then be turned as far as it will go. The calculator chart shall be shifted laterally until the tip of the pointer coincides with the sample height curve on the chart. If the specimen being tested has a porosity less then 0.40, the supplementary chart shall be used. This chart shall be attached to the back of the Fisher calculator chart. The supplementary chart shall be adjusted by aligning the tip of the pointer with the baseline of the chart. This adjustment shall be made while both plugs and both paper disks are in place in the empty sample tube. When using the supplementary chart, the height of the sample shall be read directly in centimeters on the ordinate scale. The chart shall be moved laterally until the tip of the pointer corresponds to the sample height line on the chart. The chart is constructed so that at this point the abscisse reading shall be equal to the ordinate reading. Once the height of the sample is determined, the calculator chart shall not be moved throughout the reminder of the determination. The sample tube shall then be mounted between the rubber-cushioned supports to the right of the brass post. The upper cap shall be screwed onto the sample tube until an airtight seal is obtained at both ends. Air at constant head, shall then be passed through the specimen compacted to a minimum porosity. The flow of air shall be started by throwing the electrical switch which starts the air pump. The flow of air shall be adjusted by turning the pressure control knob until bubbles rise in the standpipe at the rate of two or three per second. The liquid level in



Source: https://assist.dla.mil -- Downloaded: 2026-10-22T05:23Z
Check the source to verify that this is the current version before use.

the manometer shall be allowed to rise to its maximum height. For fine powders the rise of liquid is slow: for coarse powders the rise is rapid. With the liquid level at a maximum height, the rack shall be turned until the upper edge of the crossbar conincides with the liquid meniscus in the manometer. The particle size shall be indicated directly by the location of the tip of the pointer with relation to the calculator charts. The charts shall be interpolated if the precision of the particular operation warrants it. If the average particle diameter falls in the range of 0.2 to 17.0 microns, the charts shall be read directly with the range control indicator turned to the right ("LO" position). If the particle size is in the range of 17.0 to 30 microns, the range control indicator shall be turned to the left ("HI" position), and the chart reading multiplied by two.

4.3.5 Determination of chromium content of dichromated aluminum.- The test shall be conducted as follows:

4.3.5.1 Apparatus.

a. A Beckman pH meter with an EMF scale has been found satisfactory.

b. A 10 ml. burette, graduated to 0.05 ml., has been found satisfactory.

4.3.5.2 Reagents.

4.3.5.2.1 Sulfuric and nitric acid ($H_2SO_4 \pm HNO_3$) mixture.- Slowly add 100 ml. of sulfuric acid to 250 ml. of water, cool and add 100 ml. of nitric acid. Dilute the solution to 500 ml.

4.3.5.2.2 Silver nitrate solution.-Dissolve 0.8 gms. of silver nitrate in water and dilute to 100 ml.

4.3.5.2.3 Standard ferrous ammonium sulfate solution 0.1 normal (N).-Dissolve 39.2 gm. of ferrous ammonium sulfate in 500 gm. of cold dilute sulfuric acid 5:95, and dilute to one liter with the sulfuric acid 5:95. Standardize against 0.1N potassium dichromate by pipetting 10 ml. of standard potassium dichromate (4.9035 gm. of N, B, S potassium dichromate in 1 liter of water) into a 250 ml. beaker. Add 100 ml. of water and 0.5 ml. of sulfuric acid, cool to room temperature and titrate to a potentrometric end point as described in 4.3.5.3.

4.3.5.3 Procedure.-Transfer an accurately weighed 1.0 gm. specimen to a 250 ml. beaker. Add 30 ml. of the $H_2SO_4 \pm HNO_3$ mixture and 20 ml. silver nitrate solution. Heat the beaker with the ingredients gently until the specimen is completely dissolved. If free silicon is present add a few drops of hydrofluoric acid.



Source: https://assist.dla.mil -- Downloaded: 2026-10-22T05:23Z
Check the source to verify that this is the current version before use.

Boil until brown fumes have been expelled and allow to cool. Dilute the solution to 150 ml. with water and add 2 gm. of ammonium persulfate. Then boil fo 20 minutes. Cool the solution to room temperature and titrate as follows: Assemble a pH meter having an EMF scale with a bright platinum wire as the indicator electrode, and a saturated calomel electrode as the reference electrode. Immerse the electrodes into the solution and measure the potential of the solution. Add 0.05 increments of ferrous ammonium sulfate from the 10 ml. burette, stir the solution and measure the potential. Repeat this technique until the titration has been carried slightly beyond the potentiometric end point. The greatest potential change occurs at the potentiometric end point where a change to 60 to 125 millivolts is noted. It is not necessary to take frequent readings until the vicinity of the end point has been reached. Calculate the percent chromium as follows:

$$\text{Percent chromium} = \frac{(VN)\ (1.734)}{W}$$

where:

V = ml. of standard ferrous ammonium sulfate solution required to reach the potentiometric end point.
N = normality of ferrous ammonium sulfate solution
W = gms of specimen used

5. PREPARATION FOR DELIVERY

5.1 Packing.

5.1.1 Level B.-The MAX-2 explosive shall be packed in fiberboard cartons in accordance with dwg. F-7548645, carton No. 1, except that the bag liner shall be in accordance with Specification MIL-B-13239, Type CW2, dimension 15 by 15 by 21 1/4 inches.

5.1.2 Level C.-Unless otherwise specified the MAX-2 explosive shall be packed as specified in 5.2.2.

5.2 Marking.-The fiberboard carton shall be marked in accordance with dwg. F-7548645. In addition the descriptive nomenclature of the contents shall be: "50 lbs. MAX-2 EXPLOSIVE" and the exterior of the cartons shall be marked in accordance with Code of Federal Regulations, Title 49-Transportation: Chapter 1, Interstate Commerce Commission, Parts 71 to 78, Explosives and Other Dangerous Articles.



Source: https://assist.dla.mil -- Downloaded: 2026-10-22T05:23Z
Check the source to verify that this is the current version before use.

6. NOTES

6.1 Ordering data.-Procurement documents should specify the title, number, and date of this specification.

6.2 For purpose of manufacture.-The MAX-2 may be of the following composition:

| Constituent Material | Parts by weight |
|---|---|
| Dichromated aluminum powder | 62.0 |
| Composition A-4 | 38.0 |
| Graphite, added | 1.5 |

Notice.-When Government drawings, specifications, or other data are used for any purpose other than in connection with a definitely related Government procurement operation, the United States Government thereby incurs no responsibility nor any obligation whatsoever; and the fact that the Government may have formulated, furnished or in any way supplied the said drawings, specifications, or other data is not to be regarded by implication or otherwise as in any manner licensing the holder or any other person or corporation, or conveying any rights or permission to manufacture, use or sell any patented invention that may in any way be related thereto.

Custodian:
Army-Ordnance Corps

Preparing activity:
Army-Ordnance Corps



Source: https://assist.dla.mil -- Downloaded: 2026-10-22T05:23Z
Check the source to verify that this is the current version before use.