MIL-F-45061E (MU)
6 August 1973
SUPERSEDING
MIL-F-45061D (MU)
5 August 1966

MILITARY SPECIFICATION

FUZE, MINE, AT, NM, M606
PARTS FOR

1. SCOPE

1.1 This specification covers the parts for one type of fuze, designated as Fuze, Mine, AT, NM, M606.

2. APPLICABLE DOCUMENTS

2.1 The following documents of the issue in effect on date of invitation for bids, or request for proposals, form a part of this specification to the extent specified herein.

SPECIFICATIONS

MILITARY

MIL-A-2550 - Ammunition and Special Weapons, General Specification for

STANDARDS

MILITARY

MIL-STD-105 - Sampling Procedures and Tables for Inspection by Attributes (ABC-STD-105).
MIL-STD-109 - Quality Assurance Terms and Definitions.
MIL-STD-331 - Fuze and Fuze Components, Environmental and Performance Tests for
MIL-STD-1168 - Lot Numbering of Ammunition
MIL-STD-1169 - Packaging, Packing and Marking for Shipment of Inert Ammunition Components
MIL-STD-1235 - Single and Multilevel Continuous Sampling Procedures and Tables for Inspection by Attributes.

FSC: 1345

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T02:17Z
Check the source to verify that this is the current version before use.

DRAWINGS

U.S. ARMY MUNITIONS COMMAND

8796140 - Fuze, Mine, AT, NM, M606, Parts, Assembly
8801852 - Fixture, Test Air

(Copies of specifications, standards, and drawings required by suppliers in connection with specific procurement functions should be obtained from the procuring activity or as directed by the contracting officer).

3. REQUIREMENTS

3.1 Material.-Materials shall be in accordance with applicable drawings and specifications.

3.2 Parts.-The parts shall comply with all requirements specified on Drawing (dwg.) 8796140 and with all requirements specified in applicable specifications.

3.3 Recovery of firing pin point.-The firing pin point shall return to its original position within .010 inch after applying and removing a load.

3.4 Functioning.-The fuze shall function when the setting knob is moved to the armed position and a functioning load of 400 pounds (lbs.) plus or minus 100 lbs. is applied.

3.5 Penetration of firing pin point.-The firing pin shall penetrate the lead cylinder to a depth of .040 inch minimum (min.) The eccentricity as measured between the center of penetration and the center of the lead cylinder shall not exceed .030 inch.

3.6 Internal air pressure.-The fuze shall withstand without any drop in pressure, an internal air pressure of five pounds per square inch (p.s.i.) for five seconds, min.

3.7 External air pressure.-The fuze shall withstand without any drop in pressure, an external air pressure of five p.s.i. for five seconds, min.

3.8 Jolt.-The fuze shall withstand the jolt test as specified in MIL-STD-331, Test 101.1 except that the peak deceleration can be expected to run from about 100 to 190 g's.

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T02:17Z
Check the source to verify that this is the current version before use.

3.9 Jumble.-The fuze shall withstand the jumble as specified in MIL-STD-331, Test 102.1.

3.10 Susceptibility to cracking.-The fuze parts assembly shall not crack when subjected to temperature conditioning at minus 65 degrees Fahrenheit, plus or minus 5 degrees, for a period of 24 hours, plus or minus 1/2 hour.

3.11 Workmanship.-All parts shall be fabricated and finished in a thorough, workmanlike manner. They shall be free of burrs, sharp edges, cracks, porosity, warpage, checks, chipped edges, flashing, chips, dirt, grease, rust and other foreign matter and defects which would affect their serviceability and appearance. The cleaning method used shall not be injurious to any part nor shall the parts be contaminated by the cleaning agent. All required markings shall be neat and sharply defined.

3.12 First Article Inspection.-The specification makes provisions for first article inspection. Requirements for the submission of first article samples by the contractor shall be as specified in the contract.

4. QUALITY ASSURANCE PROVISIONS

4.1 Responsibility for Inspection.-Unless otherwise specified in the contract or purchase order, the supplier is responsible for the performance of all inspection requirements as specified herein. Except as otherwise specified in the contract or order, the supplier may use his own or any other facilities suitable for the performance of the inspection requirements specified herein, unless disapproved by the Government. The Government reserves the right to perform any of the inspections set forth in the specification where such inspections are deemed necessary to assure supplies and services conform to prescribed requirements. Reference shall be made to MIL-STD-109 to define terms used herein. The provisions of MIL-A-2550 shall apply.

4.1.1 Submission of Product.-At the time each completed lot of items deliverable under the contract is submitted to the Government for acceptance, the contractor shall supply the following information accompanied by a certificate which attests that the information provided is correct and applicable to the product being submitted.

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T02:17Z
Check the source to verify that this is the current version before use.

a. A statement that the lot complies with all of the quality assurance provisions specified in this specification.

b. Drawing and specification number and date, together with identification and date of changes thereto.

c. A statement that all material purchased by the contractor meets requirements, when such material is controlled by Government or commercial specifications referenced in any of the contractual documents, and that certificates of conformance are on file and available for review.

d. Number of items in the lot.

e. Date submitted.

The certificate shall be signed by a responsible agent of the certifying organization. The initial certificate submitted shall be substantiated by evidence of the agent's authority to bind his principal. Substantiation of the agents authority will not be required with subsequent certificates unless, during the course of the contract, this authority is vested in another agent of the certifying organization.

4.2 First Article Inspection

4.2.1 Submission.-Prior to the start of regular production the contractor shall submit a first article sample (see 6.1c) to a Government approved facility as designated by the contracting officer for evaluation in accordance with the provisions of 4.2.2 and 4.2.3. The first article sample shall consist of 15 complete sets of parts and sub-assemblies (i.e. 15 each of every component and sub-assembly, including at least three (3) items from each cavity used to produce plastic parts and be so identified as to permit tracing each item to the cavity in which it was molded) which have been produced by the contractor or furnished by a supplier and which have been manufactured using the same production processes, procedures and equipment which will be used in fulfilling the contract. All parts and materials including packaging and packing shall be obtained from the same source of supply as will be used in regular production. Prior to submission, the contractor shall inspect the sample to the degree necessary to assure that it conforms to the requirements of the contract and submit a record of this inspection with the sample, including a certificate of conformance for materials. A sample containing known defects will not be submitted unless specifically authorized by the Contracting Officer. A first article sample, or portion thereof, as directed by the Contracting Officer, shall also be submitted whenever there is a lapse in

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T02:17Z
Check the source to verify that this is the current version before use.

production for a period in excess of 90 days or whenever a change occurs in manufacturing process, material used, drawing or specification such as to significantly affect product uniformity as determined by the Government.

4.2.2 Inspections to be performed.-Assemblies and components will be subjected by the Government to any or all of the examinations and tests specified in this specification and any or all requirements of the applicable drawings. After classification of defects and other inspections have been performed as specified, the following assemblies shall be subjected to test as indicated below:

a. Susceptability to cracking (see 3.10) - 5 assemblies
b. Jolt test and jumble test (see 3.8 and 3.9) - 5 assemblies
c. Functioning and penetration of firing pin (see 3.4 and 3.5) - 5 assemblies

4.2.3 Rejection.-If any component, sub-assembly or assembly fails to comply with the applicable requirements, the first article sample shall be rejected. In the event of rejection, the Government reserves the right to require the contractor to take corrective action and submit a new first article sample or portion thereof. Until a first article sample is accepted, the contractor is, in no way, authorized by the Government to initiate regular production unless otherwise directed by the contracting officer.

4.3 Inspection provisions

4.3.1 Lot formation.-The term "inspection lot" as used in this specification is defined as an essentially homogeneous collection of units of product from which a representative sample is drawn and inspected to determine conformance with applicable requirements. The sample selected shall represent only that quantity of units from which the sample was drawn and shall not be construed to represent any prior or subsequent quantities presented for inspection. Homogeneity shall be considered to exist provided the inspection lot has been produced by one manufacturer in one unchanged process using the same materials and methods in accordance with the same drawings, same drawing revisions, same specifications and same specification revisions and complies with the provisions for submission of product as specified in MIL-STD-105. Changes to the process, specifications, or drawings not affecting safety, performance, interchangeability, or storage, as determined by the Government, shall not be deemed to alter the homogeneity of an inspection lot. All

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T02:17Z
Check the source to verify that this is the current version before use.

material submitted for inspection in accordance with this specification shall comply with the homogeneity criteria specified herein regardless of the type of sampling procedure which is being applied to determine conformance with requirements. Lot numbering, as required, shall be in accordance with MIL-STD-1168.

4.3.1.1 Process specification.-A process specification specifying the time, temperature and pressure ranges which shall be maintained during production of the molded parts shall be kept on file and available for review.

4.3.2 Examination.-The examinations listed in the following subparagraphs shall be performed on inspection lots (see 4.3.1) of the components or assemblies designated in the applicable paragraph headings. Inspection for critical defects (and major defects, when so specified) shall be 100 percent. Sampling plans for major and minor defects shall be in accordance with MIL-STD-105 except that continuous sampling plans in accordance with MIL-STD-1235 may be used if approved by the Government. Instead of applying the AQL's designated herein to the groups of major and minor defects listed, the contractor may elect to apply AQL's to individual defects using an AQL of 0.40 percent for each major defect and an AQL of 0.65 percent for each minor defect. When this method is elected, it shall be applied to all of the major and minor defects listed in the applicable subparagraphs of this section, except where 100 percent inspection is specified, and be documented as part of the contractor's inspection system. Equipment necessary for the performance of the inspections listed shall be in accordance with 4.3.4.

4.3.2.1 Pin, Firing (see dwg. 8796154 covering a detail of dwg. 8796140).

Categories	Defects	Method of Inspection	Code No. (see 6.2)
Critical: None defined			
Major:	AQL 0.65 percent		
101.	Length of firing pin point.....	Gage	01001
102.	Profile of point and point face....	Gage	01002
103.	Slot missing.....	Visual	01003

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T02:17Z
Check the source to verify that this is the current version before use.

Minor:	AQL 0.65 percent		
201.	Evidence of poor workmanship (see 3.11).....	Visual	01004

4.3.2.2 Spring, Belleville (see dwg. 8796159 covering a detail of dwg. 8796140).

Categories	Defects	Method of Inspection	Code No.
Critical:	None defined.		
Major:	AQL 0.65 percent		
101.	Outside diameter.....	Gage	02001
102.	Inside diameter.....	Gage	02002
103.	Thickness.....	Gage	02003
104.	Angle.....	Gage	02004
Minor:	AQL 1.00 percent		
201.	Identification mark missing or improper.....	Visual	02005
202.	Evidence of poor workmanship (see 3.11).....	Visual	02006

4.3.2.3 Firing Pin assembly (see dwg. 8796153 covering a detail of dwg. 8796140).

Categories	Defects	Method of Inspection	Code No.
Critical:	None defined.		
Major:	AQL 0.65 percent		
101.	Height from pin point to seating surface.....	Gage	03001
102.	Outside diameter of seat foot, maximum (max.).....	Gage	03002
103.	Diameter of body, minimum (min.)...	Gage	03003
104.	True positions of firing pins with body diameter.....	Gage	03004
105.	Firing pin not secure in collar....	Manual	03005

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T02:17Z
Check the source to verify that this is the current version before use.

Minor:	AQL 1.50 percent		
201.	Total height	Gage	03006
202.	Radius of seat foot	Gage	03007
203.	Evidence of poor workmanship (see 3.11)	Visual	03008

4.3.2.4 Spring Belleville (see dwg. 8796165 covering a detail of dwg. 8796140).

Categories	Defects	Method of Inspection	Code No.
Critical:	None defined		
Major:	AQL 0.65 percent		
101.	Thickness	Gage	04001
102.	Inside diameter	Gage	04002
103.	Radius on outside diameter	Gage	04003
104.	Outside diameter	Gage	04004
Minor:	AQL 0.65 percent		
201.	Evidence of poor workmanship (see 3.11)	Visual	04005

4.3.2.5 Firing Pin Spring Assembly (see dwg. 8796156 covering a detail of dwg. 8796140) prior to assembling of collar.

Categories	Defects	Method of Inspection	Code No.
Critical:	None Defined		
Major:	AQL 0.40 percent		
101.	Fit of collar and firing pin assembly not as specified on dwg. 8796152	Gage	05001
102.	Evidence of poor workmanship (see 3.11)	Gage	05002
Minor:	None defined		

4.3.2.6 Clip (see dwg. 8796155 covering a detail of dwg. 8796140).

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T02:17Z
Check the source to verify that this is the current version before use.

Categories	Defects	Method of Inspection	Code No.
Critical:	None defined		
Major:	AQL 0.65 percent		
101.	Distance between points at open end, min	Gage	06001
102.	Outside width, min	Gage	06002
103.	Inside width of opening, max	Gage	06003
Minor:	AQL 0.65 percent		
201.	Evidence of poor workmanship (see 3.11)	Visual	06004

4.3.2.7 Well detonator (see dwg. 8796143 covering a detail of dwg. 8796142).

Categories	Defects	Method of Inspection	Code No.
Critical:	None defined		
Major:	AQL 1.00 percent		
101.	Crack observable without magnifying glass	Visual	07001
102.	Diameter of firing pin hole, max	Gage	07002
103.	Depth of cavity	Gage	07003
104.	Inside diameter, min	Gage	07004
105.	Total length	Gage	07005
Minor:	AQL 1.00 percent		
201.	Outside diameter, min	Gage	07006
202.	Evidence of poor workmanship (see 3.11)	Visual	07007

4.3.2.8 Base, detonator well (see dwg. 8796145 covering a detail of dwg. 8796140).

Categories	Defects	Method of Inspection	Code No.
Critical:	None defined		

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T02:17Z
Check the source to verify that this is the current version before use.

Major:	AQL 0.40 percent		
101.	Pitch diameter of thread.....	Gage	08001
Minor:	AQL 4.00 percent		
201.	Total length, max.....	Gage	08002
202.	Depth to bottom of detonator cavity.....	Gage	08003
203.	Distance to face of flange.....	Gage	08004
204.	Distance across flats.....	Gage	08005
205.	Depth of detonator well counterbore.....	Gage	08006
206.	Diameter of detonator well counterbore.....	Gage	08007
207.	Diameter of detonator cavity, min.....	Gage	08008
208.	Crack or hole evident without magnifying glass.....	Visual	08009
209.	Evidence of poor workmanship (see 3.11).....	Visual	08010

4.3.2.9 Assembly (see dwg. 8796140).

Categories	Defects	Method of Inspection	Code No.
Critical:			
1.	Indicator mark missing or incorrect.....	Visual	09001
2.	Distance to firing pin point.....	Gage	09002
Major:	AQL 0.40 percent		
101.	Failure to accept gage simulating mine (functional).....	Gage	09003
102.	Housing gasket missing.....	Visual	09004
Minor:	1.50 percent		
201.	Marking misleading or unidentifiable.....	Visual	09005
202.	Safety clip cord missing or insecure.....	Visual-Manual	09006
203.	Safety clip missing or insecure....	Visual-Manual	09007

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T02:17Z
Check the source to verify that this is the current version before use.

204.	Evidence of poor workmanship (see 3.11).....	Visual	09008

4.3.2.10 Spring (see dwg. 8796151 covering a detail of dwg. 8796140).

Categories	Defects	Method of Inspection	Code No.
Critical:	None defined		
Major:	AQL 1.00 percent		
101.	Width.....	Gage	10001
102.	Thickness at straight end.....	Gage	10002
103.	Radius at curved end.....	Gage	10003
104.	Profile of face.....	Gage	10004
105.	Length.....	Gage	10005
Minor:	AQL 0.65 percent		
201.	Evidence of poor workmanship (see 3.11).....	Visual	10006

4.3.2.11 Carton, sealed (see Section 5).

Categories	Defects	Method of Inspection	Code No.
Critical:	None defined		
Major:	AQL 0.65 percent		
101.	Contents move when carton is shaken.....	Manual	11001
102.	Carton damaged so that contents are exposed or liable to become exposed.....	Visual	11002
103.	Sealing strip incomplete, badly wrinkled or not in contact with surface for at least 1/2 inch around entire carton (when applicable).....	Visual	11003
Minor:	AQL 0.65 percent		
201.	Marking misleading or unidentifiable.....	Visual	11004

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T02:17Z
Check the source to verify that this is the current version before use.

4.3.3 Testing

4.3.3.1 Recovery of firing pin point (see 3.3) Major defect - Code No. 12001.-The sampling plan for this test shall be in accordance with Standard MIL-STD-105, Code letter J, double sampling plan and an AQL of 0.65 percent. Any assembly which fails to comply with the applicable requirement shall be classed defective. Assemblies that snap through during testing shall be destroyed. The test shall be performed as specified in 4.4.1 using equipment in accordance with 4.3.4.

4.3.3.2 Functioning and penetration of firing pin point (see 3.4 and 3.5) Major defects - Code No. 13001and 13002. Thirty assemblies shall be selected from each lot for testing as specified in 4.4.2. If one or more assemblies fail to meet the functioning requirements specified in 3.4 the lot shall be rejected. If two or more assemblies fail to meet the penetration requirements specified in 3.5, the lot shall be rejected. If one assembly fails to meet the penetration requirements specified in 3.5, a second sample of sixty assemblies shall be selected from the lot and tested. If two or more assemblies from the combined first and second samples fail to comply with the requirements specified in 3.5, the lot shall be rejected. All assemblies used in the function and penetration of firing pin point test shall be destroyed.

4.3.3.3 Internal and external air pressure test (see 3.6 and 3.7) Major defects - Code No. 14001 and 14002.-The sampling plan for this test shall be in accordance with Standard MIL-STD-105, Code letter H, double sampling plan, and an AQL of 1.0 percent. Any assembly which fails to comply with the applicable requirement shall be classed defective. The test shall be performed as specified in 4.4.3 using equipment in accordance with 4.3.4.

4.3.3.4 Sequential Jolt and Jumble test (see 3.8 and 3.9) Major Defects - Code No. 15001and 15002.-Twelve assemblies shall be selected from each lot for test as specified in 4.4.4. The presence of one (1) or more of the following defects shall cause the lot to be rejected:

a. Firing pin assembly in the armed position.
b. Firing pin assembly broken loose or separated, or firing pin loose or separated.
c. Setting knob loose to the extent that verticle movement of the knob of 1/8 inch or more is observed when finger-tip pressure is applied to the clip.

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T02:17Z
Check the source to verify that this is the current version before use.

d. Cracks in base (except in locking ring on outer periphery) visible without the use of a magnifying glass. All assemblies used in the jolt and jumble tests shall be destroyed.

4.3.3.5 Arming torque test (see dwg.8796140) Major defect - Code No. 16001.-Each assembly shall be tested as specified in 4.4.5. The Government inspector shall monitor the contractors performance of the test operations at regular but unscheduled intervals, to determine that the tests are being conducted in accordance with the prescribed test procedures, and that the fuzes failing to meet the requirements are being rejected. If the inspector finds that this is not being done, he will reject all fuzes tested since his last satisfactory surveillance. The contractor shall retest the rejected fuzes 100 percent in the presence of the inspector. Fuzes failing to meet the requirements during retest shall be rejected and removed from the lot.

4.3.3.6 Reversed height, load and travel to snap back, and free overall height of Belleville spring (see dwg. 8796159) Major defect - Code No. 17001.-The sampling plan for these tests shall be in accordance with Standard MIL-STD-105 using code letter H and an AQL of 1.5 percent. Any spring which fails to comply with the specified requirements shall be classed defective. The test shall be performed as specified in 4.4.6.

4.3.3.7 Load, deflection, and overall height under load of large Belleville spring (see dwg. 8796165) Major defect - Code No. 17002.-The sampling plan for this test shall be in accordance with Standard MIL-STD-105 using code letter H and an AQL of 1.0 percent. Any spring which fails to comply with the specified requirements shall be classed defective. The test shall be performed as specified in 4.4.7.

4.3.3.8 Susceptibility to cracking (see 3.10) Major defect - Code No. 18001.-A sample of 18 fuzes shall be selected from each lot for this test. The test shall be performed as specified in 4.4.8. If one or more assemblies fail to comply with the specified requirements, the lot shall be rejected.

4.3.4 Inspection Equipment.-Inspection equipment required to perform the examinations and tests prescribed in this specification is identified in the Examination (4.3.2 and 4.3.5) and Test Method (4.4) paragraphs herein. See 6.3 for details concerning responsibilities for inspection design and approval.

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T02:17Z
Check the source to verify that this is the current version before use.

4.3.5 Dimensional control of molded parts.-In place of normal sampling and inspections associated with the Classification of Defects, and after a curing time for the parts has been approved (see Note 2) a sample of three (3) parts (as molded) from each cavity shall be fully inspected dimensionally to qualify a new or reworked cavity for use in production. The molded parts shall carry the individual cavity identification. As a control of each cavity during production, the above quantity of parts from each cavity shall be inspected for at least the defects listed in paragraphs 4.3.5.1 through 4.3.5.11 after continuous production of each 5,000 parts or at the end of each week, whichever occurs first. Of the three (3) samples, one (1) sample shall be the last part produced. If any defective parts are found during qualification of the cavity, the cavity producing the defective part will not be used in production. If any defective parts are found when inspection is performed for the control of the cavity, the cavity producing the defective part shall be removed from production. Further, that portion of production since the last control check shall be returned to the contractor for inspection for each separate type of defect according to MIL-STD-105, using an AQL of 0.40 percent for each major defect and an AQL of 0.65 percent for each minor defect. All cavities removed from production because of some fault, may after reworking, be returned to production providing they pass the qualification test above. The contractor may request a change of inspection frequency providing he presents objective evidence to the contracting officer to substantiate the request. Contractor design of gages and test equipment required to perform the inspections listed herein shall be forwarded to Commanding Officer, Picatinny Arsenal, Dover, New Jersey 07801, ATTN: SARPA-QA-A-M for approval prior to manufacture of equipment. The noted subparagraphs identify those items and minimum inspections subject to the requirements of this paragraph.

NOTE 2. - In establishing a curing time, dimensionally check ten (10) parts from each cavity at periodic intervals (e.g. every 30, 60, etc. mins.) until dimensional stability is attained. The curing time will be from the time the part comes out of the mold until dimensional stability is attained. The inspection data used in determining the curing time shall be sent to Picatinny Arsenal, Dover, New Jersey 07801 ATTN: SARPA-QA-A-M. If any new change in material, cycle time, a reworked cavity, or a new cavity is used, a new curing time

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T02:17Z
Check the source to verify that this is the current version before use.

shall be established and approved.

4.3.5.1 Plug (see 8796147 covering a detail of dwg. 8796140).

Categories	Defects	Method of Inspection	Code No.
Critical: None defined			
Major: None defined			
Minor:			
	201. Wrench slot missing or defective...	Visual	18001
	202. Evidence of poor workmanship (see 3.11).....	Visual	18002

4.3.5.2 Screw Knob, Setting (see dwg. 8796148 covering a detail of dwg. 8796140).

Categories	Defects	Method of Inspection	Code No.
Critical: None defined			
Major:			
	101. Major diameter of thread, min.....	Gage	19001
	102. Pitch diameter of thread, min.....	Gage	19002
Minor:			
	201. Evidence of poor workmanship (see 3.11).....	Visual	19003

4.3.5.3 Collar (see dwg. 8796152 covering a detail of dwg. 8796140).

Categories	Defects	Method of Inspection	Code No.
Critical: None defined			
Major:			
	101. Diameter of counterbore, max.....	Gage	20001
	102. Depth of counterbore, min.....	Gage	20002
	103. Slots missing or defective.....	Visual	20003

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T02:17Z
Check the source to verify that this is the current version before use.

Minor:
201. Evidence of poor workmanship (see 3.11)..... Visual 20004

4.3.5.4 Plate (see dwg. 8796157 covering a detail of dwg. 8796140).

Categories	Defects	Method of Inspection	Code No.
Critical: None defined			
Major:			
101.	Location of keyway.....	Gage	21001
Minor:			
201.	Location of large hole.....	Gage	21002
202.	Evidence of poor workmanship (see 3.11).....	Visual	21003

4.3.5.5 Knob, Setting (see dwg. 8796158 covering a detail of dwg. 8796140).

Categories	Defects	Method of Inspection	Code No.
Critical: None defined			
Major:			
101.	Diameter of flange, max.....	Gage	02001
102.	Location of wide lug.....	Gage	02002
103.	Wrench slot missing or defective...	Visual	02003
Minor:			
201.	Evidence of poor workmanship (see 3.11).....	Visual	02004

4.3.5.6 Spider (see dwg. 8796160 covering a detail of dwg. 8796140).

Categories	Defects	Method of Inspection	Code No.
Critical: None defined			

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T02:17Z
Check the source to verify that this is the current version before use.

Major:			
101.	Height of keyway, min.....	Gage	23001
102.	Location of support key, min.....	Gage	23002
103.	Width of lugs, min.....	Gage	23003
Minor:			
201.	Evidence of poor workmanship (see 3.11).....	Visual	23004

4.3.5.7 Support (see dwg. 8796161 covering a detail of dwg. 8796140).

Categories	Defects	Method of Inspection	Code No.
Critical: None defined			
Major:			
101.	Height.....	Gage	24001
102.	Height to inner shoulder.....	Gage	24002
Minor:			
201.	Evidence of poor workmanship (see 3.11).....	Visual	24003

4.3.5.8 Plate (see dwg. 8796162 covering a detail of dwg. 8796140).

Categories	Defects	Method of Inspection	Code No.
Critical: None defined			
Major:			
101.	Height of lugs, max.....	Gage	25001
102.	Location of wide setting knob slot.	Gage	25002
103.	Height of spider key, min.....	Gage	25003
104.	Radius to inside of spider key.....	Gage	25004
Minor:			
201.	Evidence of poor workmanship (see 3.11).....	Visual	25005

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T02:17Z
Check the source to verify that this is the current version before use.

4.3.5.9 Plate (see dwg. 8796163 covering a detail of dwg. 8796140).

Categories	Defects	Method of Inspection	Code No.
Critical: None defined			
Major:			
101.	Outside diameter of body, min.....	Gage	26001
102.	Diameter of O-ring slot, min.....	Gage	26002
103.	Location of wide keyway.....	Gage	26003
104.	Location of "S" and "A".....	Visual	26004
Minor:			
201.	Carrying cord holes missing or deformed.....	Visual	26005
202.	Evidence of poor workmanship (see 3.11).....	Visual	26006

4.3.5.10 Base (see dwg. 8796164 covering a detail of dwg. 8796140).

Categories	Defects	Method of Inspection	Code No.
Critical: None defined			
Major:			
101.	Minor diameter of threads, max.....	Gage	27001
102.	Pitch diameter of threads, max.....	Gage	27002
103.	Height to support mating surface...	Gage	27003
104.	Height to spring supporting surface.....	Gage	27004
105.	Location of wide slot.....	Gage	27005
Minor:			
201.	Evidence of poor workmanship (see 3.11).....	Visual	27006

4.3.5.11 Housing (see dwg. 8796166 covering a detail of dwg. 8796140).

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T02:17Z
Check the source to verify that this is the current version before use.

Categories	Defects	Method of Inspection	Code No.
Critical: None defined			
Major:			
101.	Outside diameter under flange, min.	Gage	28001
102.	Location of wide interior lug.....	Gage	28002
103.	Location of exterior lug.....	Gage	28003
Minor:			
201.	Evidence of poor workmanship (see 3.11).....	Gage	28004

4.4 Test methods and procedures

4.4.1 Recovery of firing pin point.-The subassembly consisting of the base, 8796164; nut, 8796144; support, 8796161; firing pin spring assembly, 8796156; plate, 8796157; spider, 8796160; and spring, 8796151 shall be subjected to this test. The depth to the firing pin from the base shall be measured to the nearest .001 inch and recorded. The assembly shall be supported on an inert loaded mine or wooden block approximately six inches square and approximately 3/4 inch thick containing a hole, geometrically centered in the 6 inch by 6 inch surface, approximately 1 inch in diameter. A load shall be applied to the collar of the firing pin assembly at the rate of 1/16 inch to 1/8 inch per minute. The load shall be removed prior to snap through of the Belleville spring. This point is detectable by a decrease in the load reading as the point of the snapping through by the Belleville spring is approached. After releasing the load, the depth of the firing pin shall be measured to the nearest .001 inch.

4.4.2 Functioning and penetration of firing pin.-A lead slug, 0.740 inch - 0.005 inch long by 0.241 inch - 0.004 inch in diameter shall be assembled to the fuze less gasket (dwg. 8796149) in place of the M50 Detonator. The base and the plug of the fuze shall be supported securely and an aluminum plate placed over the top of the fuze. A load shall be applied to the aluminum plate at a rate of of of 1/16 inch to 1/18 inch per minute until functioning (as evidenced by an audible snap) occurs. The load shall be recorded to the nearest pound. The detonator holder assembly shall be removed and the depth of penetration of the firing pin into the lead slug shall be measured from the center of the lead.

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T02:17Z
Check the source to verify that this is the current version before use.

cylinder to the center of the penetration hole made by the firing pin point. Units subjected to this test will be destroyed. Observation shall be made for compliance with the applicable requirements.

4.4.3 Internal and external air pressure test.-The fuze shall be assembled to the test fixture specified on dwg. 8801852 and tested as specified thereon.

4.4.4 Jolt and Jumble

4.4.4.1 Jolt.-The fuzes shall be assembled to a jolt adapter in accordance with 4.3.4 and tested as specified in Standard MIL-STD-331, Method 101.1, except that only the upper and side positions of the jolt machine shall be used. The fuzes shall be reversed in the upper adapter for the third position. The fuzes shall not be examined until the jumble test has been performed.

4.4.4.2 Jumble.-The fuzes tested in 4.4.4.1 shall be tested as specified in Standard MIL-STD-331, Method 102.1.

4.4.5 Arming torque.-Screw, Setting Knob, Part No. 8796148 shall be assembled to Knob, Setting, Part No. 8796158 and adjusted as specified. The arming torque shall be measured with an automatic torque fixture assembly in accordance with 4.3.4.

4.4.6 Reversed height, load and travel to snap back, and free overall height of Belleville spring (dwg. 8796159).-The Belleville springs shall be submitted to an axial load at the rate of 1/2 to 1 inch per minute to cause it to snap through and then to snap back. Observation shall be made that the reversed height is 0.145 plus .015 inch, a load of 20 to 27 pounds is required to snap back, the travel during snap back is 0.085 plus .025 inch, and the height after snap back is 0.155 inch min. to determine compliance with the requirements. Springs so tested shall be scrapped.

4.4.7 Load, deflection and overall height under load of large Belleville spring (dwg. 8796165).-The springs shall be subjected to the applicable axial loads. Observation shall be made to determine compliance with the applicable drawing requirements.

4.4.8 Susceptibility to cracking.-The fuze parts assembly shall be placed in a cold temperature chamber in such a manner that no external mechanical stresses are applied. The assembly

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T02:17Z
Check the source to verify that this is the current version before use.

shall be maintained at a temperature of minus 65 degrees Fahrenheit plus or minus 5 degrees for a period of 24 hours, plus or minus 1/2 hour. Observation shall be made for evidence of cracks, including hairline cracks, as evidence of noncompliance with 3.10.

5. PREPARATION FOR DELIVERY

5.1 Preservation and packaging.

5.1.1 Level C.-The parts for Fuze, Mine, AT, NM, M606 shall be packed in accordance with MIL-STD-1169 in such a manner that no damage will occur during shipment.

5.2 Packing

5.2.1 Level C.-The parts for Fuze, Mine, AT, NM, M606 shall be packed in accordance with MIL-STD-1169. Separately designated items shall not be packed together as a single assembly.

5.3 Shipping.-When component parts from more than one lot are shipped as a carload, each lot must be kept separate and the in transit.

5.4 Marking.-Marking of the cartons shall comply with MIL-STD-1169. Printing shall be in bold type, with black ink on white paper labels. Label size approximately 5 1/2 by 3 3/4 inches.

6. NOTES

6.1 Ordering data.-Procurement documents shall specify the following:

a. Title, number and date of this specification.
b. Data cards. - Data cards shall be prepared for each lot in accordance with the information specified in Standard MIL-STD-1167.
c. Provisions for submission of first article samples.

6.2 Inspection code numbers.-The five digit code numbers assigned to the inspections herein are to facilitate future data collection and analysis by the Government. They should

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T02:17Z
Check the source to verify that this is the current version before use.

be cited as references on drawings of equipment designs submitted by the contractor to the Government for approval (see 6.3.3).

6.3 Inspection Equipment Designs.-Inspection equipment designs are of two types - Government Special Inspection Equipment (SIE) designs and contractor designs. SIE designs are designated by drawing numbers under the "Method of Inspection" headings in Section 4. Design responsibility for all other inspection equipment is assigned to the contractor. The contractor need not furnish any design when a complete Government SIE design is provided. Unless otherwise specified, however, the contractor may submit alternate or modified contractor designs of SIE in accordance with 6.3.2 and 6.3.3 should he elect to do so.

6.3.1 SIE designs.-SIE designs may consist of any of the following:

a. Detailed drawings which completely depict all information necessary for the fabrication and use of the item of inspection equipment.

b. A source control drawing or a specification control drawing as defined in MIL-STD-100.

c. An envelope drawing, as defined in MIL-STD-100, which establishes the criteria which a detailed design shall meet. When envelope drawings are specified, the contractor shall prepare designs which comply with the criteria therein.

6.3.2 Contractor designs.-Contractor designs are required for all inspection equipment for which SIE designs are not specified and may include commercial equipment which the contractor proposes to use. (Commercial equipment is defined as unmodified equipment which is cataloged and available for purchase by the general public.) Contractor designs shall include appropriate operating instructions, calibration procedures and maintenance procedures. Commercial equipment shall be fully described by catalog listings or other means which provide sufficient information to permit identification and evaluation by the Government and may include illustrations and engineering data. Designs shall be prepared for any special fixture(s) required to be used with commercial equipment, or with SIE designs if not otherwise covered thereby (see 6.3.1c). Designs shall be of the category and form (per MIL-D-1000) specified in the Contract Data Requirements Lists (DD Form 1423). The contractor is referred to MIL-HDBK-204,

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T02:17Z
Check the source to verify that this is the current version before use.

"Inspection Equipment Design" for guidance. The specification number and the applicable five digit defect code number (or other specific identifying information) from Section 4 of this specification shall be referenced on each contractor design together with the component or assembly drawing number and revision letter to which the specific design applies.

6.3.3 Submission of Designs for Approval.-Contractor designs shall be approved by the Government prior to fabricating or procuring the equipment. Designs shall be submitted for approval to Picatinny Arsenal, ATTN: SARPA-QA-A-M, Dover, New Jersey 07801 in accordance with the stipulations, time frame and distribution specified in the Contract Data Requirements List (DD Form 1423) or in the contract. Partial submission of inspection equipment designs is permissible and encouraged. However, the completion date for design review will be based on the date of the final submission of designs. Picatinny Arsenal design review will normally be accomplished within one month after receipt.

Custodian:
Army-MU

Preparing Activity:
Army-MU

Project Number: 1345-A-027

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T02:17Z
Check the source to verify that this is the current version before use.