MIL-B-63094B(AR)
Amendment 1
7 December 1978

MILITARY SPECIFICATION

BLASTING MACHINE, 50 CAP, M34

This amendment forms a part of military specification MIL-B-63094B(AR) dated 24 July 1978.

PAGE 6

Table I - First Article Inspection under Sleeve, Rotor delete "(Dwg 9232516)" and substitute, "(Dwg 9235516)."

PAGE 12

Table I - First Article Inspection under Housing, Electrical delete "(Dwg 9235541)" and substitute, "(Dwg 9328279)."

PAGE 16

Paragraph 4.4.2.1 In Next Higher Assembly block delete "9235509" substitute, "9328276."

PAGE 17

Paragraph 4.4.2.2 In Next Higher Assembly block delete "9235509" and substitute, "9328276."

PAGE 24

Paragraph 4.4.2.9 In Next Higher Assembly block delete "9235523" and substitute, "9328275."

PAGE 33

Paragraph 4.4.2.18 delete this paragraph in its entirety.

PAGE 42

Paragraph 4.4.2.27 In Next Higher Assembly block delete "9312773" and substitute, "9328276."

FSC: 1375

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T02:11Z
Check the source to verify that this is the current version before use.

PAGE 45

Paragraph 4.4.2.30 In Drawing Number block delete "9235541" and substitute, "9328279." In Next Higher Assembly block delete "9235509" and substitute "9328276."

PAGE 49

Paragraph 4.4.2.33 In Next Higher Assembly block delete "9235504" and substitute "9312773."

PAGE 55

Paragraph 4.4.5 In the second line from the end of this page, delete the period between the words "selected" and "after" and change the "A" in "after" to "a".

Custodian:
Army-AR

Preparing Activity:
Army-AR

Project No. 1375-A-231

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T02:11Z
Check the source to verify that this is the current version before use.