MILITARY SPECIFICATION

FUZE, POINT INITIATING BASE DETONATING, XM764 (M764)

This Amendment forms a part of Military Specification MIL-F-63499 (AR), dated 12 July 1984, and is approved for use by the U.S. Army Armament, Munitions and Chemical Command, and is available for use by all Departments and Agencies of the Department of Defense.

PAGE 1

Title: Delete "XM764" and substitute "XM764 (M764)". Make this change wherever else it appears in the specification.

1.1, line 3: Delete "XM830" and substitute "XM830 (M830)". Make this change wherever else it appears in the specification.

PAGE 2

2.1.1, MILITARY SPECIFICATIONS: Delete "MIL-A-13812 Steel Plate, Wrought, Homogeneous, for Ammunition Testing (1/4 to 12 Inches, Incl.)" in its entirety.

Add as follows:

"MIL-S-45743 Soldering, Manual Type, High Reliability, Electrical and Electronic Equipment"

MILITARY STANDARDS: Delete "MIL-STD-454 Standard General Requirements for Electrical Equipment" in its entirety.

PAGE 3

2.1.2, line 5: Delete ", MUNITIONS AND CHEMICAL COMMAND" and substitute "RESEARCH AND DEVELOPMENT CENTER".

Add: "12526622 Cartridge, 120mm, HEAT-MP-T, M830".

FSC 1390

DISTRIBUTION STATEMENT A. Approved for public release; distribution is unlimited.

Source: https://assist.dla.mil -- Downloaded: 202640-23T02:58Z
Check the source to verify that this is the current version before use.

Add: "12526846 Test Procedure for M764 and XM763 Fuze Components".

PAGE 4

2.2: Add:

ASTM E34	Chemical Analysis of Aluminum and Aluminum Base Alloys
ASTM E38	Chemical Analysis of Nickel - Chromium and Nickel-Chromium-Iron Alloys

PAGE 6

Add new paragraph 3.6.3 as follows:

"3.6.3 Safety - The fuze shall be in the safe, unarmed, condition when tested as specified in 4.5.17.1".

PAGE 8

3.11.1, lines 2 and 3: Delete "MIL-STD-454, Requirement 5" and substitute "MIL-S-45743".

PAGE 12

4.3.2, line 1: Change "or" to "and".

PAGE 13

Table I: Delete "Capacitor, Ceramic Monolithic (12526748) Examination for Defects, Except Setback Load Test" and substitute "Capacitor, Ceramic Monolithic (12526748) Examination for Defects, Except Voltage Burn-in and Setback Load Test".

Delete "Diode, Rectifier (12526824) Examination for Defects, Except Setback Load Test" and substitute "Diode, Rectifier (12526824) Examination for Defects, Except Stabilization Bake, Power Burn-in and Setback Load Test".

PAGE 14

Table I: Following "EXAMINATION FOR DEFECTS" Add: "2/"

Add 2/ to notes block:

Source: https://assist.dla.mil -- Downloaded: 202640-23T02:58Z
Check the source to verify that this is the current version before use.

"2/ - Categories 102, 103, 104, 105, 106, 107, 201, 202, 203 and 204 only of 4.4.2.46.

PAGE 21

4.4.2.5, Category 201: Delete "Gage" and substitute "Visual".

PAGE 23

4.4.2.7, Category 106: Delete "Temper incorrect" and substitute "Ultimate tensile strength of sheet stock incorrect".

Note 1/: Delete and substitute as follows:

"1/ An average of three sample strips minimum cut from an eight inch minimum by two inch minimum per lot."

PAGE 24

4.4.2.8: Add category 105

"105 Porosity of each end excessive 2/, 25 samples, 3.2, Visual"

Defect 201: Delete in its entirety.

Add to notes block: "2/ No defects allowed"

PAGE 25

4.4.2.9, Add category 204

"204 Magnet cleanliness 0.65% 3.2 Visual"

PAGE 26

4.4.2.10, Category 101: Delete in its entirety.

Category 102: Add "1/" after "burn-in".

Category 103: Delete "2/" and substitute "10".

Category 104: Add "1/" after "burn-in".

Note 2/: Delete in its entirety.

Source: https://assist.dla.mil -- Downloaded: 202610-23T02:58Z
Check the source to verify that this is the currentversion before use.

PAGE 27

4.4.2.11, Category 103: Delete "2/" and substitute "10".

Note 2/: Delete in its entirety.

PAGE 28

4.4.2.12, Category 105: Delete "gross leak" and substitute "leak".

Category 106: Delete "2/" and substitute "10".

Note 2/: Delete in its entirety.

PAGE 33

4.4.2.16, Category 101: Delete "Length of mounting holes" and substitute "Diameter of mounting hole".

Category 102: Delete "locating pins for 90° contact" and substitute "mounting hole and smaller width of elongated mounting slot for 90° contact".

Category 103: Delete "locating pins for 90° contact" and substitute "mounting hole and smaller width of elongated mounting slot for 90° contact".

Add Category 106 as follows:

"106	Smaller width of elongated mounting slot"	0.40%	3.2	Gage

PAGE 34

4.4.2.17, Category 101: Delete "Length of mounting pin" and substitute "Diameter of smaller mounting pin".

Category 102: Delete "locating pins for 90° contact" and substitute "large and small mounting pins for 90° contact".

Category 103: Delete "locating pins for 90° contact" and substitute "large and small mounting pins for 90° contact".

Add Category 106 as follows:

"106	Diameter of larger mounting pin"	0.40%	3.2	Gage

Source: https://assist.dla.mil -- Downloaded: 202610-23T02:58Z
Check the source to verify that this is the current version before use.

PAGE 35

4.4.2.18, Categories 103 and 105: Delete examinations shown and substitute:

"Category 103: True position of the rotor cavity to the shield mounting surfaces and the mechanism mounting surface.

Category 105: True position of the drag sensor cavity to the shield mounting surfaces and the mechanism mounting surface"

Category 107: Delete "interface" and substitute "mounting".

PAGE 36

4.4.2.18, Add Category 109 as follows:

"109	True position of mechanism assembly locating hole to the shield interface diameter, the rotor cavity and the mechanism mounting surface"	0.40%	3.2	Gage

PAGE 38

4.4.2.20, Add new Minor Category as follows:

"203	Cut off nib max"	0.65%	3.2	Gage

PAGE 39

4.4.2.21, Add new Major Category as follows:

"101	Drag weight pin assembled reversed"	100%	3.2	Visual

PAGE 41

4.4.2.23, In notes, delete "2/ Pour two coupons per batch of potting" and substitute "2/ Pour two coupons per each day's potting".

PAGE 42

Add: "204 Shore "D" hardness 4/ 3.2 Gage".

Add: "4/ Test one sample from each mixed batch".

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T02:58Z
Check the source to verify that this is the current version before use.

PAGE 43

4.4.2.24, Category 102: Delete "Contact function" and substitute "Contact function 4/".

Category 103: Delete "2/ 1/" and substitute "2/ 5/". Delete "40" and substitute "1/".

Category 104: Delete "2/" and substitute "2/ 5/".

Category 105: Delete "2/" and substitute "2/ 5/".

Category 106: Delete "2/" and substitute "2/ 5/".

Note 2/: Delete and substitute the following:

"Two or more samples of the eighty tested, which fail to comply with the minimum dent requirement shall reject the lot. Eight or more samples which exceed the function time requirement shall also reject the lot."

Note 3/: Delete "explosive output test" and substitute "steel dent test with the same conditioning".

Add: "4/ Reject on 2 or more samples which fail to meet this requirement. For the purpose of this test only, the contact resistance shall be allowed to be within the range of 1 to 50 kiloohms inclusive."

Add: "5/ In order to assure that the exact number of data points (80) are obtained, additional samples, as necessary, are to be conditioned and available for use as replacements".

PAGE 48

4.4.2.28, Category 107: Delete examination and substitute:

"True position of the detonator output hole to the outside diameter and the front face containing the pin holes."

PAGE 50

4.4.2.30, Category 201: Delete in its entirety.

Add new Minor Category as follows:

"203	Profile of cam to top surface, mounting hub and shaft key location"	0.65%	3.2	Gage

Source: https://assist.dla.mil -- Downloaded: 202640-23T02:58Z
Check the source to verify that this is the current version before use.

PAGE 59

4.4.2.38, Category 101: Delete "Visual" and substitute "Certification".

PAGE 62

4.4.2.41, Category 002: Delete "True position of lead cup hole to inside diameter containing anti-rotation slot" and substitute "True position of lead cup mounting hole to housing and mechanism assembly mounting diameter."

Category 101: Delete in its entirety.

Add Category 104 as follows:

"104	True position of the housing and mechanism assembly mounting diameter to the outside diameter."	0.40%	3.2	Gage

PAGE 66

4.4.2.45, Add Category 203:

"Temper incorrect, 1/, 3.1, 4.5.15"

PAGE 67

4.4.2.46, Add new Critical Category as follows:

"004	Fuze not in initial safe condition"	3.6.3	4.5.17.1

PAGE 68

4.4.2.46, Category 203 Change "gage" to "visual"

PAGE 69

4.4.2.47, Add new Major Category as follows:

"103	One or more protector caps missing from top of fuze prior to assembly of cushion"	100%	3.2	Visual

Source: https://assist.dla.mil -- Downloaded: 202610-23T02:58Z
Check the source to verify that this is the current version before use.

PAGE 74

4.4.3.3.2, line 6: Delete "fifteen" and substitute "five".

PAGE 76

4.4.3.9, line 1: Delete "thirty six" and substitute "thirty two".

line 5: Delete "then an" and substitute "an".

line 6: Delete "forty four" and substitute "forty eight".

line 7: Delete "forty four" and substitute "forty eight".

line 8: Delete "then the lot" and substitute "the lot".

4.4.3.10, line 1: Delete "thirty six" and substitute "thirty two".

line 5: Delete "then an additional sample of forty four" and substitute "an additional sample of forty eight".

line 7: Delete "forty four diodes fail to comply, then" and substitute "forty eight diodes fail to comply,"

PAGE 78

4.5.3.2, Delete paragraph in its entirety.

PAGE 80

4.5.5.2, line 4: Delete "XM256" and substitute "XM256 (M256)". Make this change wherever else it appears in the specification.

line 6: Delete "-37.5^{o} plus $3^{o}C$" and substitute "-32° plus $3^{o}C$".

4.5.5.3, Add to beginning of first sentence: "After the requirements of 4.5.5.1 and 4.5.5.2 have been satisfied,..."

PAGE 81

4.5.5.4, Add to beginning of first sentence: "After the requirements of 4.5.5.1 and 4.5.5.2 have been satisfied,..."

Source: https://assist.dla.mil -- Downloaded: 202610-23T02:58Z
Check the source to verify that this is the current version before use.

PAGE 82

* 4.5.8, line 1: Delete "Procedure 1" and substitute "Procedure II".

* line 2: Delete "(one" in its entirety.

* line 3: Delete "third" and substitute "(three".

* 4.5.11, first sentence: Add to end as follows: ", except: 1) length of conditioning to each procedure shall be 14 days only and 2) high temperature for Procedure III shall be 145°F -5°F."

* second sentence: Delete "Procedure II and the remaining half to Procedure III" and substitute "each Procedure".

line 10: Delete "(minus 37.5° + 3°C and (plus) 52° -3°C" and substitute "-32° plus 3°C and +52° minus 3°C".

PAGE 83

* 4.5.12, line 2: After "113.1" add ", except high temperature shall be 145°F -5°F"

* 4.5.13, line 3: After "Procedure 1", add ", except high temperature shall be 145° -5°F".

4.5.15.1 Change "ASTM A751, E53 or E62" to "ASTM A751, E34, E38, E53 or E62".

PAGE 84

4.5.17.1, line 2: Delete "rotor safety prior to" and substitute "safety after".

PAGE 85

4.5.21, line 2: Delete "prepared" and substitute "prepared and environmentally conditioned to Methods 1 and 2".

PAGE 88

4.5.2.5, Delete second sentence in its entirety and substitute "the voltage level shall be two hundred volts, DC (200 VDC) and shall be applied for four plus one (4+1) seconds".

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T02:58Z
Check the source to verify that this is the current version before use.

6.2.2 Delete line 4 in its entirety.

6.2.2.1, line 7: Delete "DRSMC-QAT-A(D), Dover, New Jersey 07801" and substitute "AMSMC-QAT-A(D), Dover, New Jersey 07801-5001".

*The margins of this amendment are marked with an asterisk or vertical lines to indicate where changes (additions, modifications, corrections, deletions) from the previous amendment were made. This was done as a convenience only and the Government assumes no liability whatsoever for any inaccuracies in these notations. Bidders and contractors are cautioned to evaluate the requirements of this document based on the entire content irrespective of the marginal notations and relationship to the last previous amendment."

Custodian:
Army-AR

Preparing activity:
Army-AR

(Project 1390-A474)

U.S. GOVERNMENT PRINTING OFFICE: 1985 - 605-036/40159

Source: https://assist.dla.mil -- Downloaded: 202610-23T02:58Z
Check the source to verify that this is the current version before use.