MIL-I-394G(AR)
9 June 1982
SUPERSEDING
MIL-I-394F(PA)
15 November 1974

MILITARY SPECIFICATION

IGNITER, TIME, BLASTING FUSE, WEATHERPROOF: M60, PARTS FOR AND LOADING, ASSEMBLING AND PACKING

This specification is approved for use by the U.S. Army Armament Research and Development Command, and is available for use by all Departments and Agencies of the Department of Defense.

1. SCOPE

1.1 Scope. This specification covers quality assurance provisions covering parts, loading, assembling and preparation for delivery for one type of initiating device designated as Igniter, Time, Blasting Fuse, Weatherproof: M60.

2. APPLICABLE DOCUMENTS

2.1 Government documents.

2.1.1 Specifications and standards. Unless otherwise specified (see 6.2), the following specifications and standards of the issue listed in that issue of the Department of Defense Index of Specifications and Standards (DoDISS) specified in the solicitation, form a part of this specification to the extent specified herein.

SPECIFICATIONS

MILITARY

MIL-A-48078 - Ammunition, Standard Quality Assurance Provisions, General Specification For.
MIL-P-60479 - Primer and Base, Igniter, XM110, Parts For and Loading, Assembling and Packing.

STANDARDS

MIL-STD-105 - Sampling Procedures and Tables for Inspection by Attributes.

Beneficial comments (recommendations, additions, deletions) and any pertinent data which may be of use in improving this document should be addressed to: Commander, US Army Armament Research and Development Command, Attn. DRDAR-QA, Dover, New Jersey 07801 by using the self-addressed Standardization Document Improvement Proposal (DD Form 1426) appearing at the end of this document or by letter.

Source: https://assist.dla.mil -- Downloaded: 2026-10-16T07:18Z
Check the source to verify that this is the current version before use.

2.1.2 Other Government documents, drawings, and publications. The following other Government documents, drawings, and publications form a part of this specification to the extent specified herein.

DRAWINGS (see 6.5)

US ARMY ARMAMENT RESEARCH AND DEVELOPMENT COMMAND

2128182 - Pack, Shipping and Storage (For 60 Igniters, Time, Blasting Fuse, Weatherproof: M60).
3139677 - Package, Shipping and Storage (For 30 Igniters, Time, Blasting Fuse, Weatherproof: M60).
8822125 - Box, Packing, Ammunition, for Igniter, Time Blasting Fuse, Weatherproof, M60.
8822126 - Box, Set-up, Packing, Ammunition for Igniter, Time, Blasting Fuse, Weatherproof: M60.
8822497 - Igniter, Time, Blasting Fuse, Weatherproof: M60 Assembly.

(Copies of specifications, standards, handbooks, drawings, and publications required by manufacturers in connection with specific acquisition functions should be obtained from the contracting activity or as directed by the contracting officer.)

2.2 Other publications. The following document(s) form a part of this specification to the extent specified herein. The issues of the documents which are indicated as DoD adopted shall be the issue listed in the current DoDISS and the supplement thereto, if applicable.

AMERICAN SOCIETY FOR TESTING AND MATERIALS (ASTM)

ASTM B 117 - Salt Spray (Fog) Testing.

(Application for copies of ASTM publications should be addressed to the American Society for Testing and Materials, 1916 Race Street, Philadelphia, Pennsylvania 19103.)

2.3 Order of precedence. In the event of a conflict between the text of this specification and the references cited herein, the text of this specification shall take precedence.

3. REQUIREMENTS

3.1 Materials and parts. Materials and parts shall be in accordance with the applicable drawings, specifications and standards.

3.2 Igniter. The igniter shall comply with all requirements specified on Drawing (Dwg.) 8822497, all associated drawings, and with all requirements specified on applicable specifications and standards.

3.3 Embrittlement of firing pin spring. The firing pin spring shall not break or fracture when pulled to the point of minimum permanent distortion when tested as specified in 4.5.1.

Source: https://assist.dla.mil -- Downloaded: 2026-10-16T07:18Z
Check the source to verify that this is the current version before use.

3.4 Pull test of fuse holder. The igniter shall be capable of holding the M700 Fuse in position in the igniter when a pull of 25 pounds, minimum, is applied to the M700 Fuse when tested as specified in 4.5.4.11.

3.5 Waterproofness. The igniter shall be waterproof as evidenced by ignition of the M700 Fuse after being immersed in water at a depth of 31 plus or minus 1 inch, for a period of 6.5 plus or minus 0.5 hours. Testing shall be as specified in 4.5.6.

3.6 Functioning. The igniter shall ignite the M700 Fuse when tested as specified in 4.5.5.

3.7 Quick Reset. The igniter shall be capable of quick resetting of the striker in the firing position when tested as specified in 4.5.7.

3.8 First article inspection. This specification contains technical provisions for first article inspection. Requirements for the submission of first article samples by the contractor shall be as specified in the contract.

3.9 Workmanship.

3.9.1 Metal parts. All parts shall be fabricated and finished in a thorough, workmanlike manner, and all manufacturing, processing, and assembly operations shall be correctly performed. The parts shall be clean and free of burrs, cracks, sharp edges, unblended radii, surface defects, chips, dirt, grease and oil (except where specifically required), corrosion products, and other foreign matter. The cleaning method used shall not be injurious to any part nor shall the parts be contaminated by the cleaning agents. Exterior surface coatings shall be continuous except for a few light scratches not exposing base material. All required markings shall be neat and sharply defined.

3.9.2 Molded parts. All parts and assemblies shall be fabricated and finished in a thorough workmanlike manner, and all manufacturing, processing, and assembly operations shall be correctly performed. They shall be free of burrs, chips, sharp edges, cracks, crazes, unblended radii, porosity, warpage, burn marks, checks, sinks, chipped edges, blisters, excess flash, dirt, grease, rust, salt deposits, visibly raised cement seams, corrosion products, and other defects and foreign matter which would affect their serviceability. The cleaning method used shall not be injurious to any part nor shall the parts be contaminated by the cleaning agents. All required markings shall be neat, legible and sharply defined.

4. QUALITY ASSURANCE PROVISIONS

Source: https://assist.dla.mil -- Downloaded: 2026-10-16T07:18Z
Check the source to verify that this is the current version before use.

4.1 Responsibility for inspection and standard quality assurance provisions. Unless otherwise specified herein or in the contract, the provisions of MIL-A-48078 shall apply and are hereby made a part of this detail specification.

4.2 Classification of inspections. The inspection requirements specified herein are classified as follows:

a. First article inspection (see 4.3).

b. Quality conformance inspection (see 4.4).

4.3 First article inspection.

4.3.1 Submission. The contractor shall submit a first article sample as designated by the Contracting Officer for evaluation in accordance with provisions of 4.3.2. The first article sample shall consist of the following items in sample quantities as indicated below and TABLE 1.

Part Description	Drawings	Quantity
Igniter (Complete assembly)	8822497	100
Pull Ring	8822507	25
Pull Rod	8822508	25
Firing Pin Spring	8822509	25
Firing Pin Housing	8822513	25
Firing Pin	8822514	25
Striker Assembly	8822512	25
Firing Assembly	8822504	25
Friction Seals Washer	8822510	25
Release Washer	8822511	25
Grommet	8822500	5 (Note 1)
Shipping Plug	8822501	5 (Note 1)
Washer, Large	8822502	5 (Note 1)
Washer, Small	8822503	5 (Note 1)
Top Cap	8822505	5 (Note 1)
Fuse Holder Cap	8822498	5 (Note 1)
Collet	8822499	5 (Note 1)
Housing	8822506	5 (Note 1)

Note 1. Five (5) parts from each cavity used to produce the molded parts. Cavity identification shall be maintained so as to permit tracing each part to the cavity in which it was molded.

4.3.2 Inspections to be performed. See MIL-A-48078 and Table I specified herein.

4.3.3 Rejection. See MIL-A-48078.

Source: https://assist.dla.mil -- Downloaded: 2026-10-16T07:18Z
Check the source to verify that this is the current version before use.

TABLE 1. FIRST ARTICLE INSPECTION.

CLASSIFICATION OF DEFECTS & TESTS

MIL-I-394G(AR)

PARAGRAPH	TITLE		SHEET 1 OF 4		DRAWING NUMBER
	Igniter: M60				See Below
					NEXT HIGHER ASSEMBLY
					--
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
	Pull Ring Dwg. 8822507 Examination for Defects	25(a)		3.1	4.4.2.1
	Pull Rod Dwg. 8822508 Examination for Defects	25		3.1	4.4.2.2
	Firing Pin Spring Dwg. 8822509 Examination for Defects	25		3.1	4.4.2.3
	Firing Pin Housing Dwg. 8822513 Examination for Defects	25		3.1	4.4.2.4
	Firing Pin Dwg. 8822514 Examination for Defects	25		3.1	4.4.2.5
	-Cont'd.-				

NOTES: a. Ten (10) pull rings shall be subjected to the salt spray test in accordance with 4.5.8. If any pull ring shows evidence of corrosion or salt deposits, it shall be classed defective.

DRDAR-QA Form 160 Jul 77

Source: https://assist.dla.mil -- Downloaded: 2026-10-16T07:18Z
Check the source to verify that this is the current version before use.

TABLE 1. FIRST ARTICLE INSPECTION.

CLASSIFICATION OF DEFECTS & TESTS

MIL-I-394G(AR)

PARAGRAPH	TITLE		SHEET 2 OF 4		DRAWING NUMBER
cont'd.	Igniter: M60				See Below
					NEXT HIGHER ASSEMBLY
					--
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
	Striker Assembly Dwg. 8822512 Examination for Defects	25		3.2	4.4.2.6
	Firing Assembly Dwg. 8822504 Examination for Defects	25		3.2	4.4.2.7
	Friction Seal Washer Dwg. 8822510 Examination for Drawing Requirements	25.		3.1	Gage
	Release Washer Dwg. 8822511 Examination for Drawing Requirements	25		3.1	Gage
	Shipping Plug Dwg. 8822501 Examination for Defects	5		3.1	4.4.2.8
	-Cont'd.-				

NOTES:

DRDAR-QA Form 160 Jul 77

Source: https://assist.dla.mil -- Downloaded: 2026-10-16T07:18Z
Check the source to verify that this is the current version before use.

TABLE 1. FIRST ARTICLE INSPECTION.

CLASSIFICATION OF DEFECTS & TESTS

MIL-I-394G(AR)

PARAGRAPH	TITLE		SHEET 3 OF 4		DRAWING NUMBER
Cont'd.	Igniter: M60				See Below
					NEXT HIGHER ASSEMBLY
					--
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
	Top Cap Dwg. 8822505 Examination for Defects	5		3.1	4.4.2.9
	Fuse Holder Cap Dwg. 8822498 Examination for Defects	5		3.1	4.4.2.10
	Collett Dwg. 8822499 Examination for Defects	5		3.1	4.4.2.11
	Housing Dwg. 8822506 Examination for Defects	5		3.1	4.4.2.12
	Igniter (complete assembly) Dwg. 8822497 Examination for Defects	Notes a, b 100		3.2	4.4.2.13

Notes: a. The first fifty (50) assemblies shall be subjected to only the cotter pin pull, fuze holder pull, and functioning tests.
b. The second fifty (50) shall be subjected to only the waterproofness and functioning, and quick reset tests.

NOTES:

DRDAR-QA Form 160 Jul 77

Source: https://assist.dla.mil -- Downloaded: 2026-10-16T07:18Z
Check the source to verify that this is the current version before use.

TABLE 1. FIRST ARTICLE INSPECTION.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE		SHEET 4 OF 4		DRAWING NUMBER
Cont'd.	Igniter: M60				See Below
					NEXT HIGHER ASSEMBLY
					--
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
	Grommet Dwg. 8822500 Examination for Drawing Requirements	5		3.1	Gage
	Washer, Large Dwg. 8822502 Examination for Drawing Requirements	5		3.1	Gage
	Washer, Small Dwg. 8822503 Examination for Drawing Requirements	5		3.1	Gage

NOTES:

DRDAR-QA Form 160 Jul 77

Source: https://assist.dla.mil -- Downloaded: 2026-10-16T07:18Z
Check the source to verify that this is the current version before use.

4. Quality conformance inspection.

4.4.1 Inspection lot formation. Inspection lots shall comply with the lot formation provisions of MIL-A-48078. In addition, each lot shall contain:

a. Parts of one lot interfix number from one manufacturer.

b. Primer and base igniters: XM110, of one lot interfix number from one manufacturer. (See 4.4.3.4)

4.4.2 Examination See MIL-A-48078.

a. Sampling plans. Unless otherwise specified in the Classification of Defects and Tests Tables, sampling plans and procedures for major and minor defects shall be in accordance with MIL-STD-105, Inspection Level II.

Source: https://assist.dla.mil -- Downloaded: 2026-10-16T07:18Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

MIL-I-394G(AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 8822507
4.4.2.1	Pull Ring				NEXT HIGHER ASSEMBLY 8822504
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Salt spray test			3.2	Certification (Note a)
Minor					
201	Protective finish damaged		0.65%	3.2	Visual
202	Poor workmanship		1.0%	3.9.1	Visual

NOTES: a. Certification shall be in accordance with 6.6.

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-16T07:18Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

MIL-I-394G(AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.2	Pull Rod				8822508
					NEXT HIGHER ASSEMBLY 8822504
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major A					
101	Diameter at front end		0.40%	3.2	Gage
102	Perpendicularity of shoulder with diameter at rear end		0.40%	3.2	Gage
103	Radius of shoulder, max.		0.40%	3.2	Gage
104	Pressure relief cavity or hole incomplete or blocked		100.0%	3.2	Visual
Major B					
131	Distance from flange to safety pin hole		0.40%	3.2	Gage
132	Distance from flange to pull ring hole		0.40%	3.2	Gage
133	Diameter of relief cavity, min.		0.40%	3.2	Gage
134	Depth of relief cavity, min.		0.40%	3.2	Gage
135	Diameter of relief hole, min.,		0.40%	3.2	Gage
136	Distance from flange to relief hole		0.40%	3.2	Gage
Minor					
201	Total length		0.65%	3.2	Gage
202	Finish improper		0.65%	3.2	Visual
203	Poor workmanship		1.0%	3.9.1	Visual

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-10-16T07:18Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

MIL-I-394G(AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.3	Spring, Firing Pin				8822509
					NEXT HIGHER ASSEMBLY 8822504
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Embrittlement	Note a	--	3.3	4.5.1
102	Solid height, max.		0.40%	3.2	Gage
103	Load at test height (note 7 on Dwg.)		0.40%	3.2	Gage
104	Protective finish damaged or missing		0.40%	3.2	Visual
105	End not squared or ground		0.40%	3.2	Visual
Minor					
201	Poor workmanship		1.0%	3.9.1	Visual

NOTES: a. Thirty-two (32) springs shall be selected from each heat treatment lot and tested as specified in 4.5.1. If one (1) or more springs fail to comply with the requirement specified, the heat treatment lot shall be rejected.

DRDAR-QA Form 160 Jul 77

Source: https://assist.dla.mil -- Downloaded: 2026-10-16T07:18Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

MIL-I-394G(AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 8822513
4.4.2.4	Firing Pin Housing				NEXT HIGHER ASSEMBLY 8822512
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Perpendicularity of cavity base with inside diameter at front end		0.40%	3.2	Gage
102	Outside diameter		0.40%	3.2	Gage
103	Inside diameter at front end		0.40%	3.2	Gage
104	Total length		0.40%	3.2	Gage
Minor					
201	Finish improper		0.65%	3.2	Visual
202	Poor workmanship		1.0%	3.9.1	Visual

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-16T07:18Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

MIL-I-394G(AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 8822514
4.4.2.5	Firing Pin				NEXT HIGHER ASSEMBLY 8822512
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Total length		0.40%	3.2	Gage
102	Length of point		0.40%	3.2	Gage
103	Profile of point		0.40%	3.2	Gage
104	Location of crimp groove		0.40%	3.2	Gage
105	Distance across flange flats		0.40%	3.2	Gage
Minor					
201	Distance from base to flange		0.65%	3.2	Gage
202	Poor workmanship		1.0%	3.9.1	Visual

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-10-16T07:18Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

MIL-I-394G(AR)

PARAGRAPH	TITLE	SHEET 1 OF 1	DRAWING NUMBER
4.4.2.6	Striker Assembly		8822512
			NEXT HIGHER ASSEMBLY 8822504

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Firing pin load test	Note a		3.2	4.5.2
102	Perpendicularity of forward face of flange with outside diameter of firing pin housing		0.40%	3.2	Gage
103	Total length, max.		0.40%	3.2	Gage
104	Slot missing from firing pin housing		0.40%	3.2	Visual
Minor					
201	Crimp improper (shallow or less than 360°)		0.65%	3.2	Visual
202	Poor workmanship		1.0%	3.9.1	Visual

NOTES:

a. See 4.4.3.1.

Source: https://assist.dla.mil -- Downloaded: 2026-10-16T07:18Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

MIL-I-394G(AR)

PARAGRAPH	TITLE	SHEET 1 OF 1	DRAWING NUMBER
4.4.2.7	Firing Assembly		8822504
			NEXT HIGHER ASSEMBLY 8822497

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Cotter pin pull	Note a		3.2	4.5.3
102	Pull rod not engaged		0.40%	3.2	Manual
103	Depth from fuse holder end to firing pin flange		0.40%	3.2	Gage
104	Components missing or loose (firing pin spring, pull rod, release and friction washers, etc.)		0.40%	3.2	Visual/Manual
Minor					
201	Cord improperly tied		0.65%	3.2	Visual
202	Threads damaged		0.65%	3.2	Visual
203	Poor workmanship		1.0%	3.9	Visual

NOTES:
a. See 4.4.3.2

Source: https://assist.dla.mil -- Downloaded: 2026-10-16T07:18Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

MIL-I-394G(AR)

PARAGRAPH	TITLE	SHEET 1 OF 1	DRAWING NUMBER
4.4.2.8	Shipping Plug		8822501
			NEXT HIGHER ASSEMBLY
			8822497

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Outside diameter of shank, min.	Note a	0.40%	3.2	Gage
102	Plug damaged to the extent that sealing properties would be affected	Note a	0.40%	3.2	Visual
Minor					
201	Poor workmanship	Note a	1.0%	3.9.2	Visual

NOTES:

a. See 4.4.5 for alternative method for inspection.

Source: https://assist.dla.mil -- Downloaded: 2026-10-16T07:18Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

MIL-I-394G(AR)

PARAGRAPH	TITLE	SHEET 1 OF 1	DRAWING NUMBER
4.4.2.9	Top Cap		8822505
			NEXT HIGHER ASSEMBLY 8822504

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Distance from front end to bottom of thread	Note a	0.40%	3.2	Gage
102	Total length	Note a	0.40%	3.2	Gage
103	Pitch diameter of thread, max.	Note a	0.40%	3.2	Gage
104	Minor diameter of thread, max.	Note a	0.40%	3.2	Gage
105	Location of cotter pin hole	Note a	0.40%	3.2	Gage
106	Diameter over knurl	Note a	0.40%	3.2	Gage
107	Crack or split	Note a	0.40%	3.2	Gage
108	Surface in bottom not smooth or free of flash	Note a	0.40%	3.2	Visual
Minor					
201	Poor workmanship	Note a	1.0%	3.9.2	Visual

NOTES: a. See 4.4.5 for alternative method for inspection.

Source: https://assist.dla.mil -- Downloaded: 2026-10-16T07:18Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

MIL-I-394G(AR)

PARAGRAPH	TITLE	SHEET 1 OF 1	DRAWING NUMBER
4.4.2.10	Fuse Holder Cap		8822498
			NEXT HIGHER ASSEMBLY 8822497

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Minor diameter of thread, max.	Note a	0.40%	3.2	Gage
102	Pitch diameter of thread, max.	Note a	0.40%	3.2	Gage
103	Total length, min.	Note a	0.40%	3.2	Gage
104	Distance from rear end to cavity below thread	Note a	0.40%	3.2	Gage
105	Distance from rear end to bottom of thread	Note a	0.40%	3.2	Gage
106	Crack or split	Note a	0.40%	3.2	Visual
Minor					
201	Poor workmanship	Note a	1.0%	3.9.2	Visual

NOTES:

a. See 4.4.5 for alternative method for inspection.

Source: https://assist.dla.mil -- Downloaded: 2026-10-16T07:18Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

MIL-I-394G(AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.11	Collet				8822499
					NEXT HIGHER ASSEMBLY
					8822497
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major 101	Inside radius, max.	Note a	0.40%	3.2	Gage
Minor 201	Poor workmanship	Note a	1.0%	3.9.2	Visual

NOTES:

a. See 4.4.5 for alternative method for inspection.

DRDAR-QA Form 160 Jul 77

Source: https://assist.dla.mil -- Downloaded: 2026-10-16T07:18Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

MIL-I-394G(AR)

PARAGRAPH	TITLE	SHEET 1 OF 1	DRAWING NUMBER
4.4.2.12	Housing		8822506
			NEXT HIGHER ASSEMBLY 8822504

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Outside diameter, min.	Note a	0.40%	3.2	Gage
102	Major diameter of thread, min.	Note a	0.40%	3.2	Gage
103	Pitch diameter of thread, min.	Note a	0.40%	3.2	Gage
104	Inside diameter, min.	Note a	0.40%	3.2	Gage
105	Total length	Note a	0.40%	3.2	Gage
106	Threads improper or damaged	Note a	0.40%	3.2	Visual
Minor					
201	Poor workmanship	Note a	1.0%	3.9.2	Visual

NOTES:
a. See 4.4.5 for alternative method for inspection.

Source: https://assist.dla.mil -- Downloaded: 2026-10-16T07:18Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

MIL-I-394G(AR)

PARAGRAPH	TITLE	SHEET 1 OF 2	DRAWING NUMBER
4.4.2.13	Igniter (Complete Assembly)		8822497
			NEXT HIGHER ASSEMBLY --

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Cotter pin pull	(a)		3.2	4.5.3
102	Fuse holder pull	(b)		3.4	4.5.4
103	Functioning	(c)		3.6	4.5.5
104	Waterproofness and functioning	(d)		3.5	4.5.6
105	Quick reset	(e)		3.7	4.5.7
106	Total length, max		0.40%	3.2	Gage
107	Length from top cap to end of fuse holder cap, max.		0.40%	3.2	Gage
108	Components missing or loose (Primer and base igniter, top cap, shipping plug, fuse holder cap, pull ring, collet, etc.)		0.40%	3.2	Visual/Manual
109	Top cap or fuse holder cap cracked or split		0.40%	3.2	Visual
Notes:	a. See 4.4.3.2 b. See 4.4.3.2 c. See 4.4.3.2 d. See 4.4.3.3 e. See 4.4.3.4				

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-10-16T07:18Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

MIL-I-394G(AR)

PARAGRAPH	TITLE		SHEET 2 OF 2		DRAWING NUMBER
4.4.2.13 (Cont'd)	Igniter (Complete Assembly)				8822497
					NEXT HIGHER ASSEMBLY: -
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Minor					
201	Cotter pin not spread		0.65%	3.2	Visual
202	Cotter pin cord missing or improperly tied		0.65%	3.2	Visual
203	Marking misleading, unidentifiable or missing		0.65%	3.2	Visual
204	Protective coating missing		0.65%	3.2	Visual
205	Color improper		0.65%	3.2	Visual
206	Knurl missing(where applicable)		0.65%	3.2	Visual
207	Poor workmanship		1.0%	3.9.1	Visual

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-10-16T07:18Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

MIL-I-394G(AR)

PARAGRAPH	TITLE	SHEET	OF	DRAWING NUMBER
4.4.2.14	Box, Set-up, Packing (Prior to sealing)	1	1	8822126
				NEXT HIGHER ASSEMBLY: 8822125

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Incorrect number of assemblies in box		0.40%	3.2	Visual
102	Assembly damaged		0.40%	3.2	Visual
Minor					
201	Contents loose		0.65%	3.2	Manual
202	Marking misleading, unidentifiable or missing		0.65%	3.2	Visual
203	Poor workmanship		1.0%	3.9	Visual

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-10-16T07:18Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

MIL-I-394G(AR)

PARAGRAPH	TITLE	SHEET	OF	DRAWING NUMBER
4.4.2.15	Box, Set-up (Sealed)	1	1	8822126
				NEXT HIGHER ASSEMBLY 8822125

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Sealing strip improperly applied		0.40%	3.2	Visual
102	Box damaged to extent that contents are exposed or liable to become exposed		0.40%	3.2	Visual
Minor					
201	Contents loose		0.65%	3.2	Manual
202	Marking misleading, unidentifiable or missing		0.65%	3.2	Visual
203	Poor workmanship		1.0%	3.9.1	Visual

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-10-16T07:16Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

MIL-I-394G(AR)

PARAGRAPH	TITLE	SHEET 1 OF 1	DRAWING NUMBER
4.4.2.16	Sealed Packed Barrier Bag (Prior to insertion in Box)		8822126
			NEXT HIGHER ASSEMBLY 8822126

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Waterproofness of barrier bag destroyed by rupture, puncture, or separation of heat seal		0.40%	3.2	Visual
102	Box crushed		0.40%	3.2	Visual
	NOTE: Package shall be opened if there is evidence of crushing				
Minor					
201	Heat seal of barrier bag located so that one or more subsequent seals cannot be applied		0.65%	3.2	Visual
202	Marking of bag misleading, unidentifiable or missing		0.65%	3.2	Visual
203	Poor workmanship		1.0%	3.9.1	Visual

NOTES:

DRDAR-QA Form 160 Jul 77

Source: https://assist.dla.mil/ - Downloaded: 2026-10-16T07:18Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

MIL-I-394G(AR)

PARAGRAPH	TITLE	SHEET 1 OF 1	DRAWING NUMBER
4.4.2.17	Box, Packing (Prior to Sealing)		8822125
			NEXT HIGHER ASSEMBLY 8822125

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Number of set-up boxes incorrect		0.40%	3.2	Visual
102	Set-up box damaged		0.40%	3.2	Visual
Minor					
201	Contents loose		0.65%	3.2	Manual
202	Poor workmanship		1.0%	3.9.1	Visual

NOTES:

DRDAR-QA Form 160 Jul 77

Source: https://assist.dla.mil -- Downloaded: 2026-10-16T07:18Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

MIL-I-394G(AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.18	Sealed Packing Box				8822125
					NEXT HIGHER ASSEMBLY —
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Box damaged to the extent that contents are exposed		0.40%	3.2	Visual
102	DoD symbol misleading, unidentifiable or missing		0.40%	3.2	Visual
103	Hardware broken or loose		0.40%	3.2	Visual/Manual
104	Strapping broken or loose		0.40%	3.2	Visual/Manual
105	Board broken or split		0.40%	3.2	Visual
Minor					
201	Hardware improperly engaged		0.65%	3.2	Visual/Manual
202	Strapping improperly engaged		0.65%	3.2	Visual/Manual
203	Metallic seal unsealed or improperly positioned		0.65%	3.2	Visual
204	Marking misleading, unidentifiable or missing		0.65%	3.2	Visual
205	Poor workmanship		1.0%	3.9.1	Visual

NOTES:

DRDAR-QA Form 160 Jul 77

Source: https://assist.dla.mil -- Downloaded: 2026-10-16T07:18Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

MIL-I-394G(AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.19	Package, Shipping and Storage (Prior to Closing)				3139677
					NEXT HIGHER ASSEMBLY
					--
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical					
Major					
101	Any packing component missing or misassembled		0.40%	3.2	Visual
Minor					
201	Number of desiccant units incorrect		0.65%	3.2	Visual
202	Desiccant bags not properly secured		0.65%	3.2	Visual
203	Indicator card missing		0.65%	3.2	Visual
204	Number of inner packages incorrect		0.65%	3.2	Visual
205	Poor workmanship		1.0%	3.9.1	Visual

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-10-16T07:18Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-I-394G(AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.20	Package, Shipping and Storage				3139677
					NEXT HIGHER ASSEMBLY
					--
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical					
1	CFR markings missing or unidentifiable		100.0%	3.2	Visual
Major					
101	Tray interferes with seal of lid		0.40%	3.2	Visual/Manual
Minor					
201	Marking missing, misleading or unidentifiable		0.65%	3.2	Visual
202	Poor workmanship		1.0%	3.9.1	Visual

NOTES:

DRDAR-QA Form 160 Jul 77

Source: https://assist.dla.mil -- Downloaded: 2026-10-16T07:18Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

MIL-I-394G(AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.21	Pack, Shipping and Storage (Prior to Closing)				2128182
					NEXT HIGHER ASSEMBLY
					--
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major 101	Package missing or improperly positioned		0.40%	3.2	Visual
Minor 201	Poor workmanship		1.0%	3.9.1	Visual

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2022-10-16T07:18Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

MIL-I-394G(AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.22	Pack, Shipping and Storage				2128182
					NEXT HIGHER ASSEMBLY
					--
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical					
1	CFR marking missing or unidentifiable		100.0%	3.2	Visual
Major					
101	Wire binding not properly secured		0.40%	3.2	Visual
102	Car seal missing		0.40%	3.2	Visual
Minor					
201	Marking missing, misleading or unidentifiable		0.65%	3.2	Visual
202	Poor workmanship		1.0%	3.9.1	Visual

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-10-16T07:18Z
Check the source to verify that this is the current version before use.

4.4.3 Testing. Testing is described in the First Article and Quality Conformance Inspection tables and as follows:

4.4.3.1 Firing pin load test. A sample of eighty (80) pull rods and striker assemblies shall be selected from each lot and tested as specified in 4.5.2. If two or more roll crimp failures or pull rod disengagements occur, the lot shall be rejected. (see Table II) (Non-destructive Test)

4.4.3.2 Cotter pin pull, fuse holder pull and functioning. (see Dwg. 8822504, 3.4 and Dwg. 8822497). (Sequentially test in this order) (see Notes 1 and 2 below)

4.4.3.2.1 Beginning with the first lot produced and continuing until three consecutive lots have complied with the acceptance criteria specified, one hundred and fifty (150) igniter assemblies shall be selected from each lot for these tests. The lot shall be rejected, if, during tests, three (3) or more assemblies fail to comply with the combined specified requirements. (see Table II) The 150 igniters shall be sequentially tested as indicated in 4.4.3.2 and in accordance with 4.5.3, 4.5.4 and 4.5.5.

4.4.3.2.2 After three consecutive lots have complied with the acceptance criteria of 4.4.3.2.1, eighty (80) igniter assemblies shall be selected from each lot for these tests. The lot shall be rejected, if during tests, two (2) or more asssemblies fail to comply with the combined specified requirements. (see Table II) The 80 igniters shall be sequentially tested as indicated in 4.4.3.2, and in accordance with 4.5.3, 4.5.4 and 4.5.5.

NOTE 1. Cotter pin (or removable pin) shall be re-inserted into igniter prior to fuse holder and functioning tests.

NOTE 2. Acceptance for the functioning test shall be indicated by observance of the burning of the M700 Time fuse remaining from the fuse holder test, the audible sound of the primer, or disassembly and visual examination for initiation of the primer.

4.4.3.3 Waterproofness and functioning.

4.4.3.3.1 Beginning with the first lot produced and continuing until three consecutive lots have complied with acceptance criteria specified, one hundred and fifty (150) igniters assemblies shall be selected from each lot for these tests. The lot shall be rejected, if during the tests, three or more assemblies fail to comply with the specified requirements (see Table II). The 150 igniters shall be sequentially tested as indicated in 4.4.3.2 (see Table II) and in accordance with 4.5.6.

Source: https://assist.dla.mil -- Downloaded: 2026-10-16T07:18Z
Check the source to verify that this is the current version before use.

4.4.3.3.2 After three consecutive lots have complied with the acceptance criteria of 4.4.3.3.1, eighty (80) igniter assemblies shall be selected from each lot for these tests. The lot shall be rejected, if during tests, two (2) or more assemblies fail to comply with the specified requirements (see Table II). The 80 igniters shall be sequentially tested as indicated in 4.4.3.2 and in accordance with 4.5.6.

TABLE II

Defect	Defect Classification	Requirement
Cotter pin withdraws at lower than min. or fails to withdraw at greater than max.	Major	Dwg. 8822504
M700 time fuse moves in or withdraws from fuse cup holder	Major	3.4
Igniter functions at less than min. or fails to function at greater than max. functioning force	Major	Dwg. 8822497
Igniter leaks and fails to ignite M700 time fuse	Major	3.5 & 3.6
Pull rod fails to re-engage striker during quick reset test	Major	3.7
Roll crimp fails or pull rod disengages during firing pin load test	Major	Dwg. 8822512

4.4.3.4 Check test for deterioration of primer and base (P and B) igniter (See MIL-P-60479). If the total time between original acceptance of any P and B igniter lot and the assembly of that lot into the M60 igniter exceeds two years, or if the P and B igniters have been subjected to adverse conditions, however brief, at any time since previous tests, the P and B igniter lot shall be subjected to and must satisfactorily pass, the check test for deterioration specified in MIL-P-60479 immediately before the P and B igniter lot is assembled into the M60 igniter. This test shall be performed by the contractor on P and B igniters selected by the Government Inspector at the facility assembling the P and B igniters into the M60 igniters. (See 6.8)

Source: https://assist.dla.mil -- Downloaded: 2026-10-16T07:18Z
Check the source to verify that this is the current version before use.

4.4.4 Inspection equipment. The inspection equipment required to perform the inspections and tests prescribed in this specification is identified in the "Paragraph Reference/Inspection Method" column in the tables starting with paragraph 4.4.2.1, and the test method paragraphs (see 4.5). The contractor shall submit for approval inspection equipment designs in accordance with the terms of the contract. See Section 6 of MIL-A-48078 and section 6.3 herein.

4.4.5 Dimensional control of molded parts. (The requirements of this paragraph apply to those dimensions which are considered "as molded", and which do not undergo subsequent operations). In place of normal sampling and inspections associated with the Classification of Defects, and with the approval of the Contracting Officer, and after a curing time for the parts has been approved (see Note 1) a sample of five (5) parts (as molded) from each cavity shall be inspected dimensionally to qualify a new or reworked cavity for use in production. The molded parts shall carry the individual cavity identification when more than one cavity is used in production. As a control of each cavity during production, the above quantity of parts from each cavity shall be inspected for at least the defects listed after continuous production of each 5,000 parts or at the end of each week, whichever occurs first. Of the five (5) samples, one (1) sample shall be the last part produced. If any defective parts are found during qualification of the cavity, the cavity producing the defective part shall not be used in production. If any defective parts are found when inspection is performed for the control of the cavity, the cavity producing the defective part shall be removed from production. Further, that portion of production since the last control check shall be returned to the Contractor for inspection for each separate type of defect according to MIL-STD-105, using an AQL of 0.40 percent for each major defect and an AQL of 0.65 percent for each minor defect. All cavities removed from production because of some fault, may, after reworking, be returned to production providing they pass the qualification test above. The contractor may request a change of inspection frequency providing he presents objective evidence to the contracting officer to substantiate the request. Contractor design of gages and test equipment required to perform the inspections listed herein shall be forwarded to Commander, ARRADCOM, Dover, New Jersey 07801, ATTN: DRDAR-QAT-I, for approval prior to manufacture of equipment.

NOTE 1. For establishing the curing time, dimensionally check ten (10) parts from each cavity at periodic intervals (e.g., every 30, 60, etc. mins.) until dimensional stability is attained. The curing time will be from the time the part comes out of the mold until dimensional stability is attained. The inspection data used in determining the curing time shall be sent to ARRADCOM, Dover, New Jersey 07801, ATTN: DRDAR-QAT-M. If any new change in material, cycle time, a reworked cavity, or a new cavity is used, a new curing time shall be established and approved.

Source: https://assist.dla.mil -- Downloaded: 2026-10-16T07:18Z
Check the source to verify that this is the current version before use.

4.5 Methods of inspection.

4.5.1 Spring embrittlement. The spring shall be stretched until the minimum point of permanent distortion is reached. If the spring breaks when pulled to the point of permanent distortion it shall be classed defective. Springs so tested shall be discarded.

4.5.2 Firing pin load test. This test shall be performed on the sub-assembly consisting of the pull rod assembled to the striker assembly. The pull ring end of the pull rod shall be secured in a suitable holding fixture and the specified axial load shall be applied to the firing pin flange in a direction away from the pull rod. Observation shall be made to determine compliance with the requirements specified on the applicable drawing.

4.5.3 Cotter pin pull. The assembly shall be secured in a horizontal position with the eye of the cotter pin in a downward direction. A weight, equal to but not less than the minimum withdrawal force specified on the applicable drawing, shall be attached to the cotter pin in such a manner that the force applied to the cotter pin does not exceed that specified. This weight shall be removed and replaced by a weight equal to but not greater than the maximum withdrawal force specified on the drawing in the same manner as specified above. If the cotter pin is withdrawn when the minimum withdrawal force is applied or if the cotter pin is not withdrawn when the maximum withdrawal force is applied, the assembly shall be classed defective.

4.5.4 Pull test of fuse holder. A length of M700 fuse shall be prepared and inserted into the igniter as follows: Fuse shall be dry and have clean, square cut ends. The use of standard fuse cutter is satisfactory for preparing the fuse end. (CAUTION: Do not unscrew fuse holder cap completely off because internal parts may become disarranged). Push the plug in towards the primer to break hold of the collets. The plug is then rotated back and forth while it is simultaneously withdrawn. Insert fuse, with freshly cut end into the igniter after removal of the storage plug. The fuse should be inserted into the igniter as far as possible and the cap retightened sufficiently to insure proper holding force. Fingertight closures shall be used. Clamp the pull ring end of the igniter to a suitable holding fixture. Apply the specified axial load to the fuse. If the fuse moves or is withdrawn, the assembly shall be classed defective.

4.5.5 Functioning. The fuse end of the igniter shall be fixed in a suitable test fixture with the pull rod held in the cocked position by means of the cotter pin inserted through the top cap and pull rod. (Dwg. 8822497) A force shall be evenly applied to the pull ring, with the cotter pin removed, such that the igniter functions within the axial force limits specified on the applicable drawing.

Source: https://assist.dla.mil -- Downloaded: 2026-10-16T07:18Z
Check the source to verify that this is the current version before use.

4.5.6 Waterproofness and functioning. An igniter should be assembled to each end of a piece of M700 safety fuse, and then conditioned as specified in paragraph 3.5. Immediately after completion of waterproofness conditioning, the M700 safety fuse shall be cut midway between the igniters, and the igniters shall be functioned as specified in paragraph 4.5.5. If the igniter fails to fire and ignite the fuse, it may be recocked by pushing the pull-rod back into the item to engage the striker and functioned again. The igniter shall be classed defective if it fails to ignite the fuse by the third attempt.

4.5.7 Quick reset. The igniter shall be capable of quick reset for retest which may be required in paragraph 4.5.6. If engagement is not effected, the igniter shall be classed defective.

4.5.8 Salt spray test. The salt spray test shall be performed utilizing the equipment, methods and procedures specified in ASTM B-117. Exposure time shall be not less than twenty-four (24) hours using an atomized sodium chloride solution of five percent (5%).

5. PACKAGING

5.1 Preservation packaging.

5.1.1 Level A. The igniters shall be preserved and packaged in accordance with Dwg. 8822126.

5.1.2 Level A. For Marine Corps use, preservation and packaging shall be in accordance with Dwg. 3139677.

5.2 Packing.

5.2.1 Level A. The igniters shall be packed in accordance with Dwg. 8822125.

5.2.2 Level A. For Marine Corps use, packing shall be in accordance with Dwg. 2128182.

5.3 Marking.

5.3.1 Marking shall be in accordance with Dwgs. 8822125 and 8822126.

5.3.2 For Marine Corps use, marking shall be as specified on Dwgs. 2128182 and 3139677.

5.4 Shipping. When components from more than one lot are shipped at one time, each lot shall be kept separate, and the division between lots clearly indicated to prevent mixing of the lots in transit.

Source: https://assist.dla.mil -- Downloaded: 2026-10-16T07:18Z
Check the source to verify that this is the current version before use.

6. NOTES

6.1 Intended use. The weatherproof time blasting fuse igniter: M60 covered by this specification is intended to be used for initiation of the time blasting fuse M700 generally used for military demolitions.

6.2 Ordering data. See MIL-A-48078. For Marine Corps procurement see 5.1.2, 5.2.2, and 5.3.2 for packing, packaging and marking.

6.3 Submission of inspection equipment designs for approval. (See MIL-A-48078). Equipment designs shall be submitted as required to: Commander, U.S. Army Armament Research and Development Command, ATTN: DRDAR-QAT-I, Dover, New Jersey 07801. Request letter of submittal should state contractor, contract number, specification number, item nomenclature, and classification of defects and test paragraph number.

6.4 Data cards. (See MIL-A-48078). Distribution of data cards shall include the following: Commander, U. S. Army Armament Research and Development Command, ATTN: DRDAR-QAT-M, Dover, New Jersey 07801.

6.5 Drawings. Drawings listed in Section 2 of this specification under the heading US Army Armament Research and Development Command (ARRADCOM) may also include drawings prepared by, and identified as, Edgewood Arsenal, Frankford Arsenal, Rock Island Arsenal or Picatinny Arsenal drawings. Technical data originally prepared by these activities are now under the cognizance of ARRADCOM.

6.6 Data items. Data required by this specification are cited in the paragraphs listed below. The Form DD 1423 should include distribution of data cards as specified in 6.4.

Paragraph	Data Requirement	Applicable DID
4.4.2.1	Quality Inspection Test Demonstration and Evaluation Report	DI-R-1724 (Tailored)
6.4	Ammunition Data Card	DI-L-1410

Source: https://assist.dla.mil -- Downloaded: 2026-10-16T07:18Z
Check the source to verify that this is the current version before use.

6.7 Check test for possible deterioration of M60 igniters. The following test is designed to prevent igniters that have deteriorated from being assembled into major ammunition items. The test shall be performed on igniters from each lot which have been stored under normal conditions for more than two (2) years or under adverse conditions for any period of time. If the specification for the ammunition item into which igniters are assembled does not require that the check test be performed, the Contracting Officer should insert in the contract a provision for the performance of the check test. The Contracting Officer will arrange for the contractor to be reimbursed for expense incurred in his performance of the check tests for possible deterioration. Igniters shall be selected from each lot and tested as per 6.7.1.

6.7.1 Functioning. Eighty (80) M60 igniter assemblies shall be selected from each lot and subjected to the functioning test as specified in 4.5.5, excluding the waterproofness phase. The igniter lot shall be rejected if three (3) or more igniters fail to comply with the functioning requirements specified on Dwg. 8822497. Test equipment shall be as specified in 4.4.4.

6.8 Cost of check test. The contracting officer will arrange for the contractor to be reimbursed for the expense incurred in the performance of the check test for deterioration of the primer and base igniters. The tests shall be conducted at Government expense without cost to the contractor who loaded the primer and base igniters or to the contractor assembling the primer and base igniters into the M60 igniter; and shall not constitute a basis for rejection against either contractor except where deterioration has occurred as a direct result of carelessness in handling, storage, etc., permitted while the primer and base igniter lot was under the jurisdiction of either contractor.

6.9 International standardization agreement. Certain portions of this specification are the subject of international standardization agreement (STANAG No. 2818). When amendment, revision, or cancellation of this specification is proposed which will affect or violate the international agreement concerned, the preparing activity will take appropriate reconciliation action through international standardization channels including departmental standardization offices, if required.

6.10 Changes from previous issue. Asterisks are not used in this revision to identify changes with respect to the previous issue, due to the extensiveness of the changes.

Custodian:
Army-AR

Preparing activity:
Army-AR

(Project 1375-A230)

Source: https://assist.dla.mil -- Downloaded: 2026-10-16T07:18Z
Check the source to verify that this is the current version before use.