INCH-POUND

MIL-P-43649B(GL)
AMENDENT 1
12 January 1994

MILITARY SPECIFICATION

PARACHUTES, CARGO, 12-, 26-, AND 34-FOOT DIAMETER

This amendment forms a part of MIL-P-43649B(GL) dated 28 June 1991, and is approved for use by all Departments and Agencies of the Department of Defense.

PAGE 4

2.1.2, line 2 of note on availability of copies of drawings:

Delete "STRNC-UX" and substitute "SATNC-MII"

2.2, line 8, delete "Commercial Packing" and substitute "Commerical Packaging".

PAGE 5

3.3.1.2, line 2, delete "OD S-1" and substitute "Camouflage Green 483".

PAGES 7, 8, 9, 10 and 11

Replace TABLE I of the specification with TABLE I of this amendment.

TABLE I. Canopy visual defects

Defect	Classification Major	Minor
Cloth, webbing and tape:		
Any hole in cloth (except drill holes):		
1/4 inch diameter or less		201
More than 1/4 inch diameter	101	
Color not as specified		202
Not specified type or class	102	

DISTRIBUTION STATEMENT A. Approved for public release; distribution is unlimited.

Source: https://assist.dla.mil -- Downloaded: 2026-10-21T21:56Z
Check the source to verify that this is the current version before use.

TABLE I. Canopy visual defects (cont'd)

Defect	Classification Major	Classification Minor
Cloth, webbing and tape: (cont'd)		
Cut or tear in cloth:		
1/2 inch or less		203
More than 1/2 inch	103	
Smash	104	
Multiple floats	105	
Grease or oil stain over 3/4 sq. inch	106	
Grease or oil stain(s) less than 3/4 sq. inch area;		204
Not more than 5 per gore: or 15 per canopy		
grease or oil stains - more than 5 per gore or 15 per canopy (3/4 sq. inch area)	107	
Embedded crease or wrinkle in excess of 1/2 inch width	108	
Darns, over 14 per canopy	109	
Patches:		
More than one per canopy	110	
Patch size exceeding 7 inches by 7 inches	111	
Location not as specified	112	
Shape not as specified	113	
Procedure, not as specified in 3.3.3	114	
Cord and thread:		
Not specified type or size as applicable	115	
Color not as specified		205
Vent reinforcement overlap:		
Vent reinforcement overlap does not span two main seams	116	
Vent reinforcement band, improper assembly	117	
Vent line length (across vent) not as specified:		
Less than 1/4 inch	118	
1/4 inch or more		206

Source: https://assist.dla.mil -- Downloaded: 2026-10-21T21:56Z
Check the source to verify that this is the current version before use.

TABLE I. Canopy visual defects (cont'd)

Defect	Classification Major	Minor
Twisted vent line:		
More than 360°		207
More than 360°, causing kinks in line	119	
Gore width at vent, measured C/L to C/L on adjacent radial seams, not as specified:		
Less than 1/4 inch		208
1/4 inch or more	120	
Slot width, not as specified:		
Less than 1/8 inch		209
1/8 inch or more	121	
Skirt reinforcement band improperly assembled	122	
Under fold (raw edge) skirt hem	123	
NOTE: When a raw edge is the result of overfolding the edge extending more than 1/2 inch but less than 1 inch, the raw edge may be trimmed and will not be scored as a defect. If the condition extends more than 1 inch from the inside edge of the skirt hem, the stitching will be removed and the hem refolded and restitched.		
Tucks, wherein section of gore fabric is caught in stitching of hems	124	
Suspension lines crossed	125	
Cut, frayed, or damged suspension or vent lines	126	
suspension line length, not as specified:		
Less than 3/4 inch		210
3/4 inch or more	127	
Suspension line twisted:		
More than 360°		211
More than 360°, causing kinks	128	
Stitches and stitching:		
Wrong type	129	
Two or more stitches per inch less than specified	130	
Two or more stitches per inch more than specified		212

Source: https://assist.dla.mil -- Downloaded: 2026-10-21T21:56Z
Check the source to verify that this is the current version before use.

TABLE I. Canopy visual defects (cont'd)

Defect	Classification Major	Minor
Stitches and stitching: (con't)		
Broken, skipped or missing stitches not overstitched as specified	131	
Open seam	132	
NOTE: A seam shall be classified as open when one or more stitches joining a seam are broken or where two or more skipped stitches occur. Repairs of open seams will not be scored as defects.		
Wrong type seam	133	
Missing or incomplete stitch pattem	134	
Runoff not restitched in accordance with specified pattern		213
Zig-zag stitching not sewn through suspension lines	135	
Tension loose, resulting in loose top or bobbin thread; or tight tension, resulting in tightness or puckering of material		214
Thread ends not trimed		215
Ends of stitching not secured as specified		216
Stitch pattern lengths:		
Less than 1/8 inch minus	136	
1/8 inch or more minus		217
1/2 inch or more plus		218
Stitch pattern not complete	137	
Needle or feed dog damage	138	
Length of components and location dimensions not otherwise covered, not as specified:		
Up to 5 inches:		
Less than 1/8 inch		219
1/8 inch or more	139	
5 inches or over:		
Less than 1/4 inch		220
1/4 inch or more	140	
Riser:		
Length overall, not as specified by:		
Less than 1/2 inch		221
1/2 inch or more	141	
Loop length, not as specified by:		
Less than 1/8 inch		222
1/8 inch or more	142	

Source: https://assist.dla.mil -- Downloaded: 2026-10-21T21:56Z
Check the source to verify that this is the current version before use.

TABLE I Canopy visual defects (cont'd)

Defect	Classification Major	Minor
Insertion of suspension line in core at skirt attachment loop and riser attachment point not as specified by:		
Less than 1/4 inch		223
1/4 inch to 1/2 inch	143	
More than 1/2 inch plus		224
Ends of webbing and tape not seared as specified		225
Suspension line attachment loop length at skirt band not as specified by:		
Less than 1/8 inch		226
1/8 inch or more	144	
Any component missing	145	
Any incomplete assembly	146	
Identification marking illegible, incomplete, or missing		227
Clevis:		
Ccmponent missing	147	
Part fractured, malformed, or damaged	148	
Corrosion or rust	149	

PAGE 11

TABLE II, under "Defect" column for "Darns", delete "over 5 per bag" and substitute "over 4 per bag".

PAGE 13

TABLE III, under "Defect" column for "Darns", delete "over 5 per pack" and substitute "over 4 per pack".

PAGE 22

6. After NOTES: Delete entire note and substitute:

"(This section contains information of a general or explanatory nature that may be helpful, but is not mandatory.)".

Source: https://assist.dla.mil -- Downloaded: 2026-10-21T21:56Z
Check the source to verify that this is the current version before use.

Custodian:

Army GL

Review activity:

Army - AV

Preparing activity:

Army - GL

(Project 1670-A812)

Source: https://assist.dla.mil -- Downloaded: 2026-10-21T21:56Z
Check the source to verify that this is the current version before use.