# MILITARY SPECIFICATION

## FUZE, MINE, AT, XM619
## PARTS AND ASSEMBLY

### 1. SCOPE

1.1 This specification covers the parts and assembly for one type of fuze designated as Fuze, Mine, Anti-Tank, XM619.

### 2. APPLICABLE DOCUMENTS

2.1 The following documents of the issue in effect on date of invitation for bids or request for proposals, form a part of this specification to the extent specified herein.

SPECIFICATIONS

MILITARY

| | | |
|---|---|---|
| MIL-A-2550 | - | Ammunition and Special Weapons; General Specification For. |

STANDARDS

MILITARY

| | | |
|---|---|---|
| MIL-STD-105 | - | Sampling Procedures and Tables For Inspection by Attributes (ABC-STD-105). |
| MIL-STD-109 | - | Quality Assurance Terms and Definitions. |
| MIL-STD-331 | - | Fuze and Fuze Components, Environmental and Performance Tests For. |
| MIL-STD-810 | - | Environmental Test Methods. |
| MIL-STD-1168 | - | Lot Numbering of Ammunition. |
| MIL-STD-1169 | - | Packaging, Packing and Marking for Shipment of Inert Ammunition Components. |
| MIL-STD-1235 | - | Single and Multilevel Continuous Sampling Procedures and Tables For Inspection by Attributes. |

FSC: 1345

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:03Z
Check the source to verify that this is the current version before use.

DRAWINGS

U.S. ARMY MUNITIONS COMMAND

9235367 - Fuze, Mine, Anti-Tank, XM619

PUBLICATIONS

U.S. ARMY MUNITIONS COMMAND

ET-9235367 - Equipment Tabulation

(Copies of specifications, standards, drawings and publications required by contractors in connection with specific procurement functions should be obtained from the procuring activity or as directed by the contracting officer.)

3. REQUIREMENTS

3.1 Material.-The material shall be in accordance with applicable drawings and specifications.

3.2 Fuze.-The fuze shall comply with all requirements specified on drawing (dwg.) 9235367 and with all requirements specified in applicable specifications.

3.3 Environmental

3.3.1 Transportation-vibration.-The fuze (dwg. 9235367) shall withstand the transportation-vibration test as evidenced by satisfactorily meeting all requirements in 3.4 when tested as specified in 4.4.1.

3.3.2 Waterproofness.-The fuze components shall withstand submersion in water as evidenced by satisfactorily meeting all requirements in 3.4 when tested as specified in 4.4.1.

3.3.3 High temperature.-The fuze components shall withstand the high temperature test as evidenced by satisfactorily meeting all requirements in 3.4 when tested as specified in 4.4.1.

3.3.4 Low temperature.-The fuze components shall withstand the low temperature test as evidenced by satisfactorily meeting all requirements in 3.4 when tested as specified in 4.4.1.

3.4 Functioning.-The fuze assembly shall show evidence of proper operation when tested as specified in 4.4.2.



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:03Z
Check the source to verify that this is the current version before use.

3.5 Workmanship.-All parts and assemblies shall be fabricated and assembled in a thorough, workmanlike manner. They shall be free of burrs, sharp edges, cracks, chips, dirt, corrosion products and other foreign material. The cleaning method used shall not be injurious to any of the parts nor shall the parts be contaminated by the cleaning agent. Surface coatings shall be continuous except for a few light scratches not exposing base material. All required markings shall be neat and sharply defined.

3.6 First article inspection.-This specification makes provisions for first article inspection. Requirements for the submission of first article samples by the contractor shall be as specified in the contract.

4. QUALITY ASSURANCE PROVISIONS

4.1 Responsibility for inspection.-Unless otherwise specified in the contract or purchase order, the supplier is responsible for the performance of all inspection requirements as specified herein. Except as otherwise specified in the contract or order, the supplier may use his own or any other facilities suitable for the performance of the inspection requirements specified herein, unless disapproved by the Government. The Government reserves the right to perform any of the inspections set forth in the specification where such inspections are deemed necessary to assure supplies and services conform to prescribed requirements. Reference shall be made to MIL-STD-109 to define terms used herein. The provisions of MIL-A-2550 shall apply.

4.1.1 Submission of product.-At the time each completed lot of items deliverable under the contract is submitted to the Government for acceptance, the contractor shall supply the following information accompanied by a certificate which attests that the information provided is correct and applicable to the product being submitted:

a. A statement that the lot complies with all of the quality assurance provisions specified in this specification

b. Drawing and specification number and date, together with identification and date of changes thereto.

c. A statement that all material purchased by the contractor meets requirements, when such material is controlled by Government or commercial specifications referenced in any of the contractual documents and that certificates of conformance are on file and available for review.

d. Number of items in the lot.

e. Date submitted.



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:03Z
Check the source to verify that this is the current version before use.

The certificate shall be signed by a responsible agent of the certifying organization. The initial certificate submitted shall be substantiated by evidence of the agent's authority to bind his principal. Substantiation of the agent's authority will not be required with subsequent certificates unless, during the course of the contract, this authority is vested in another agent of the certifying organization.

4.2 First article inspection

4.2.1 Submission.-Prior to the start of regular production the contractor shall submit a first article sample to a Government approved facility as designated by the Contracting Officer for evaluation in accordance with the provisions of 4.2.2. The first article sample shall consist of twenty (20) complete assemblies which have been produced by the contractor or furnished by a supplier and which have been manufactured using the same production processes, procedures and equipment which will be used in fulfilling the contract. All parts and materials, including packaging and packing shall be obtained from the same source of supply as will be used in regular production. Prior to submission, the contractor shall inspect the sample to the degree necessary to assure that it conforms to the requirements of the contract and submit a record of this inspection with the sample, including certificates of conformance for materials. A sample containing known defects will not be submitted unless specifically authorized by the contracting officer. A first article sample, or portion thereof, as directed by the contracting officer, shall also be submitted whenever there is a lapse in production for a period in excess of 90 days, or whenever a change occurs in manufacturing process, material used, drawing or specification such as to significantly affect product uniformity as determined by the Government.

4.2.2 Inspections to be performed.-Components, subassemblies and assemblies will be subjected by the Government to any or all of the examinations or tests specified in 4.3.2 of this specification and any or all requirements of the applicable drawings. Test quantities are shown in Table I and applicable requirements and procedures paragraphs are listed in Table II.



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:03Z
Check the source to verify that this is the current version before use.

TABLE I

| 10 Samples<br>Transportation Vibration and Functioning | | 10 Samples<br>Waterproofness and Functioning | |
|---|---|---|---|
| 5 Samples<br>High Temperature and Functioning | 5 Samples<br>Low Temperature and Functioning | 5 Samples<br>High Temperature and Functioning | 5 Samples<br>Low Temperature and Functioning |

Transportation Vibration and Functioning and Waterproofness and Functioning tests shall be performed prior to the respective High or Low Temperature and Functioning tests. The applicable paragraphs are as follows:

TABLE II

| Test | Requirement Paragraph | Test Procedures Paragraph |
|---|---|---|
| Transportation Vibration | 3.3.1 | 4.4.1.1 |
| Waterproofness | 3.3.2 | 4.4.1.2 |
| High Temperature | 3.3.3 | 4.4.1.3 |
| Low Temperature | 3.3.4 | 4.4.1.4 |
| Functioning | 3.4 | 4.4.2 |

4.2.3 Rejection.-If any component or subassembly fails to comply with any of the applicable requirements, the first article sample shall be rejected. The Government reserves the right to terminate its inspection upon any failure of any component or subassembly in the sample to comply with any of the stated requirements.

4.3 Inspection provisions

4.3.1 Lot formation.-The term "inspection" lot as used in this specification is defined as an essentially homogeneous collection of units of product from which a representative sample is drawn and inspected to determine conformance with applicable requirements. The sample selected shall represent only that quantity of units from which the sample was drawn and shall not be construed to represent any prior or subsequent quantities presented for inspection. Homogene-

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:03Z
Check the source to verify that this is the current version before use.

ity shall be considered to exist provided the inspection lot has been produced by one manufacturer in one unchanged process using the same materials and methods in accordance with the same drawings, same drawing revisions, same specifications and same specification revisions and complies with the provisions for submission of product as specified in MIL-STD-105. Changes to the process, specifications, or drawings not affecting safety, performance, interchangeability, or storage, as determined by the Government, shall not be deemed to alter the homogeneity of an inspection lot. All material submitted for inspection in accordance with this specification shall comply with the homogeneity criteria specified herein regardless of the type of sampling procedure which is being applied to determine conformance with requirements. Lot numbering, as required, shall be in accordance with MIL-STD-1168. Each inspection lot of fuzes shall contain:

a. Parts of not more than one lot interfix number from one manufacturer.

b. Geophones of not more than one lot interfix number from one manufacturer.

4.3.2 Examination.-The examinations listed in the following subparagraphs shall be performed on inspection lots (see 4.3.1) of the components or assemblies designated in the applicable paragraph headings. Inspection for critical defects (and major defects, when so specified) shall be 100 percent. Sampling plans for major and minor defects shall be in accordance with MIL-STD-105 except that continuous sampling plans in accordance with MIL-STD-1235 may be used if approved by the Government. Instead of applying the AQL's designated herein to the groups of major and minor defects listed, the contractor may elect to apply AQL's to individual defects using an AQL of 0.40 percent for each major defect and an AQL of 0.65 percent for each minor defect. When this method is elected, it shall be applied to all of the major and minor defects listed in the applicable subparagraph of this section, except where 100 percent inspection is specified, and be documented as part of the contractor's inspection system. Equipment necessary for the performance of the inspections listed shall be in accordance with 4.3.4.

4.3.2.1 Housing (see dwg. 9235388 covering a detail of dwg. 9235386 and 9235415).

| Categories | Defects | Method of Inspection | Code No. |
|---|---|---|---|
| Critical: | None defined. | | |
| Major: | AQL 0.65 percent | | |
| 101. | Large outside diameter | Gage | 01001 |
| 102. | Small inside diameter | Gage | 01002 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:03Z
Check the source to verify that this is the current version before use.

| | | | |
|---|---|---|---|
| 103. | True position of small inside diameter with large outside diameter | Gage | 01003 |
| 104. | True position of lens cavity with small inside diameter | Gage | 01004 |
| Minor: | AQL 1.5 percent | | |
| 201. | Overall length (dwg. 9235388-1) | Gage | 01005 |
| 202. | Overall length (dwg. 9235388-2) | Gage | 01006 |
| 203. | Evidence of poor workmanship (see 3.5) | Visual | 01007 |

4.3.2.2 Window (see dwg. 9235389 covering a detail of dwg. 9235386 and 9235415).

| Categories | Defects | Method of Inspection | Code No. |
|---|---|---|---|
| Critical: | None defined. | | |
| Major: | AQL 0.40 percent | | |
| 101. | Flatness of window | Gage | 02001 |
| Minor: | AQL 1.0 percent | | |
| 201. | Diameter | Gage | 02002 |
| 202. | Evidence of poor workmanship (see 3.5) | Visual | 02003 |

4.3.2.3 Spacer (see dwg. 9235390 covering a detail of dwg. 9235415 and 9235386).

| Categories | Defects | Method of Inspection | Code No. |
|---|---|---|---|
| Critical: | None defined. | | |
| Major: | AQL 0.65 percent | | |
| 101. | Outside diameter | Gage | 03001 |
| 102. | Width | Gage | 03002 |
| 103. | True position of inside diameter with outside diameter | Gage | 03003 |
| 104. | Protective finish inadequate damaged or improper | Visual | 03004 |
| Minor: | AQL 0.65 percent | | |
| 201. | Evidence of poor workmanship (see 3.5) | Visual | 03005 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:03Z
Check the source to verify that this is the current version before use.

4.3.2.4 Plate, End (see dwg. 9235391 covering a detail of dwg. 9235386 and 9235415).

| Categories | Defects | Method of Inspection | Code No. |
|---|---|---|---|
| Critical: | None defined. | | |
| Major: | AQL 0.65 percent | | |
| 101. | Inside diameter | Gage | 04001 |
| 102. | True position of inside diameter with outside diameter | Gage | 04002 |
| 103. | True position of holes with inside diameter | Gage | 04003 |
| Minor: | AQL 0.65 percent | | |
| 201. | Evidence of poor workmanship (see 3.5) | Visual | 04004 |

4.3.2.5 Cap, End (see dwg. 9235392 covering a detail of dwg. 9235386 and 9235415).

| Categories | Defects | Method of Inspection | Code No. |
|---|---|---|---|
| Critical: | None defined. | | |
| Major: | AQL 0.40 percent | | |
| 101. | Small outside diameter | Gage | 05001 |
| 102. | True position of small inside diameter with small outside diameter | Gage | 05002 |
| Minor: | AQL 0.65 percent | | |
| 201. | Evidence of poor workmanship (see 3.5) | Visual | 05003 |

4.3.2.6 Housing Assembly (see dwg. 9235401 covering a detail of dwg. 9235384).

| Categories | Defects | Method of Inspection | Code No. |
|---|---|---|---|
| Critical: | None defined. | | |
| Major: | 1.0 percent | | |
| 101. | Large inside diameter | Gage | 06001 |
| 102. | True position of small inside diameter with large inside diameter | Gage | 06002 |
| 103. | Pitch diameter, battery cap thread, maximum (max) | Gage | 06003 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:03Z
Check the source to verify that this is the current version before use.

| | | | |
|---|---|---|---|
| 104. | Minor diameter, battery cap thread max | Gage | 06004 |
| 105. | True position of sighting groove with large inside diameter | Gage | 06005 |
| 106. | Angular location of sighting groove from boss | Gage | 06006 |
| 107. | Depth of large cavity | Gage | 06007 |
| 108. | Small inside diameter | Gage | 06008 |
| 109. | True position of intermediate inside diameter with large inside diameter | Gage | 06009 |
| 110. | Battery decal missing or incorrectly applied | Visual | 06010 |
| Minor: | AQL 1.0 percent | | |
| 201. | Total length | Gage | 06011 |
| 202. | Evidence of poor workmanship (see 3.5) | Visual | 06012 |

4.3.2.7 Cap, Battery (see dwg. 9235402 covering a detail of dwg. 9235384).

| Categories | Defects | Method of Inspection | Code No. |
|---|---|---|---|
| Critical: | None defined. | | |
| Major: | AQL 0.65 percent | | |
| 101. | Pitch diameter of thread, minimum (min.) | Gage | 07001 |
| 102. | Major diameter of thread, min | Gage | 07002 |
| 103. | Marking missing, incorrect or illegible | Visual | 07003 |
| Minor: | AQL 0.65 percent | | |
| 201. | Evidence of poor workmanship (see 3.5) | Visual | 07004 |

4.3.2.8 Baseplate (see dwg. 9235403 covering a detail of dwg. 9235399).

| Categories | Defects | Method of Inspection | Code No. |
|---|---|---|---|
| Critical: | None defined. | | |
| Major: | None defined. | | |
| Minor: | AQL 1.0 percent | | |
| 201 | Outside diameter, max | Gage | 08001 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:03Z
Check the source to verify that this is the current version before use.

| | | | |
|---|---|---|---|
| 202. | Evidence of poor workmanship (see 3.5) | Visual | 08002 |

4.3.2.9 Baseplate (see dwg. 9235425 covering a detail of dwg. 9235414).

| Categories | Defects | Method of Inspection | Code No. |
|---|---|---|---|
| Critical: | None defined. | | |
| Major: | None defined. | | |
| Minor: | AQL 1.5 percent | | |
| 201. | Outside diameter, max | Gage | 09001 |
| 202. | Inside diameter, min | Gage | 09002 |
| 203. | Evidence of poor workmanship (see 3.5) | Visual | 09003 |

4.3.2.10 Housing Assembly (see dwg. 9235426 covering a detail of dwg. 9235413).

| Categories | Defects | Method of Inspection | Code No. |
|---|---|---|---|
| Critical: | None defined. | | |
| Major: | AQL 1.0 percent | | |
| 101. | Large inside diameter | Gage | 10001 |
| 102. | True position of small inside diameter with large inside diameter | Gage | 10002 |
| 103. | True position of sighting groove with large inside diameter | Gage | 10003 |
| 104. | Inside diameter of end plate, min | Gage | 10004 |
| 105. | Angular location of sighting groove from boss | Gage | 10005 |
| 106. | Depth of large cavity | Gage | 10006 |
| 107. | Small inside diameter | Gage | 10007 |
| Minor: | AQL 1.0 percent | | |
| 201. | Total length | Gage | 10008 |
| 202. | Evidence of poor workmanship (see 3.5) | Visual | 10009 |

4.3.2.11 Gasket (see dwg. 9235455 covering a detail of dwg. 9235437).

| Categories | Defects | Method of Inspection | Code No. |
|---|---|---|---|
| Critical: | None defined. | | |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:03Z
Check the source to verify that this is the current version before use.

| | | | |
|---|---|---|---|
| Major: | AQL 0.40 percent | | |
| 101. | True position of holes | Gage | 11001 |
| 102. | Diameter of holes | Gage | 11002 |
| Minor: | AQL 0.65 percent | | |
| 201. | Evidence of poor workmanship (see 3.5) | Visual | 11003 |

4.3.2.12 Panel assembly (see dwg. 9235438 covering a detail of dwg. 9235437).

| Categories | Defects | Method of Inspection | Code No. |
|---|---|---|---|
| Critical: | None defined. | | |
| Major: | AQL 1.0 percent | | |
| 101. | Distance from end of shorter battery tube to face of panel | Gage | 12001 |
| 102. | Distance from end of longer battery tube to face of panel | Gage | 12002 |
| 103. | Inside diameter of shorter battery tube | Gage | 12003 |
| 104. | Inside diameter of longer battery tube | Gage | 12004 |
| 105. | Pitch diameter of hole 7, maximum | Gage | 12005 |
| 106. | Pitch diameter of hole 8, maximum | Gage | 12006 |
| 107. | Minor diameter of hole 7, maximum | Gage | 12007 |
| 108. | Minor diameter of hole 8, maximum | Gage | 12008 |
| 109. | Location and direction of polarity decals | Visual | 12009 |
| 110. | Adhesive missing or incomplete | Visual | 12010 |
| Minor: | AQL 0.65 percent | | |
| 201. | Evidence of poor workmanship (see 3.5) | Visual | 12011 |

4.3.2.13 Cap, Battery (see dwg. 9235442 covering a detail of dwg. 9235437).

| Categories | Defects | Method of Inspection | Code No. |
|---|---|---|---|
| Critical: | None defined. | | |
| Major: | AQL 1.0 percent | | |
| 101. | Diameter of o'ring groove | Gage | 13001 |
| 102. | Width of o'ring groove | Gage | 13002 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:03Z
Check the source to verify that this is the current version before use.

| | | | |
|---|---|---|---|
| 103. | Depth of o'ring groove | Gage | 13003 |
| 104. | Pitch diameter (min) | Gage | 13004 |
| 105. | Major diameter (min) | Gage | 13005 |
| 106. | Finish inadequate, damaged or improper | Visual | 13006 |
| Minor: | AQL 1.00 percent | | |
| 201. | Width of slot | Gage | 13007 |
| 202. | Evidence of poor workmanship (see 3.5) | Visual | 13008 |

4.3.2.14 Cap, Battery (see dwg. 9235443 covering a detail of dwg. 9235437).

| Categories | Defects | Method of Inspection | Code No. |
|---|---|---|---|
| Critical: | None defined. | | |
| Major: | AQL 1.00 percent | | |
| 101. | Diameter of o'ring groove | Gage | 14001 |
| 102. | Width of o'ring groove | Gage | 14002 |
| 103. | Depth of o'ring groove | Gage | 14003 |
| 104. | Pitch diameter (min) | Gage | 14004 |
| 105. | Major diameter (min) | Gage | 14005 |
| 106. | Finish inadequate, damaged or improper | Visual | 14006 |
| Minor: | AQL 1.00 percent | | |
| 201. | Width of slot | Gage | 14007 |
| 202. | Evidence of poor workmanship (see 3.5) | Visual | 14008 |

4.3.2.15 Baseplate (see dwg. 9235444 covering a detail of dwg. 9235458).

| Categories | Defects | Method of Inspection | Code No. |
|---|---|---|---|
| Critical: | None defined. | | |
| Major: | AQL 0.65 percent | | |
| 101. | Diameter of baseplate | Gage | 15001 |
| 102. | Width of baseplate | Gage | 15002 |
| 103. | True position of holes | Gage | 15003 |
| Minor: | AQL 0.65 percent | | |
| 201. | Evidence of poor workmanship (see 3.5) | Visual | 15004 |

4.3.2.16 Spring, Conical (see dwg. 9235445 covering a detail of dwgs. 9235399, 9235446 and 9235458).



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:03Z
Check the source to verify that this is the current version before use.

| Categories | Defects | Method of Inspection | Code No. |
|---|---|---|---|
| Critical: | None defined. | | |
| Major: | AQL 0.40 percent | | |
| 101. | Load at .62 deflection | Test | 16001 |
| Minor: | AQL 1.00 percent | | |
| 201. | Free length | Gage | 16002 |
| 202. | Evidence of poor workmanship (see 3.5) | Visual | 16003 |

4.3.2.17 Support (see dwg. 9235452 covering a detail of dwg. 9235437).

| Categories | Defects | Method of Inspection | Code No. |
|---|---|---|---|
| Critical: | None defined. | | |
| Major: | AQL 1.50 percent | | |
| 101. | Length | Gage | 17001 |
| 102. | True position of holes | Gage | 17002 |
| 103. | True position of threaded holes | Gage | 17003 |
| 104. | Thickness of thinner portion | Gage | 17004 |
| 105. | Thickness of thicker portion | Gage | 17005 |
| 106. | Height from bottom to threaded hole | Gage | 17006 |
| 107. | Distance from side to threaded hole | Gage | 17007 |
| 108. | Distance from end to hole | Gage | 17008 |
| 109. | Height from bottom to hole | Gage | 17009 |
| 110. | Height of large end | Gage | 17010 |
| 111. | Height of small end | Gage | 17011 |
| 112. | Length of thinner portion | Gage | 17012 |
| 113. | Distance from end to thinner portion | Gage | 17013 |
| 114. | Diameter of holes | Gage | 17014 |
| 115. | Finish inadequate, damaged or improper | Visual | 17015 |
| Minor: | AQL 0.65 percent | | |
| 201. | Evidence of poor workmanship (see 3.5) | Visual | 17016 |

4.3.2.18 Support (see dwg. 9235453 covering a detail of dwg. 9235437).



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:03Z
Check the source to verify that this is the current version before use.

| Categories | Defects | Method of Inspection | Code No. |
|---|---|---|---|
| Critical: | None defined. | | |
| Major: | AQL 1.50 percent | | |
| 101. | Length | Gage | 18001 |
| 102. | True position of holes | Gage | 18002 |
| 103. | True position of threaded holes | Gage | 18003 |
| 104. | Thickness of thinner portion | Gage | 18004 |
| 105. | Thickness of thicker portion | Gage | 18005 |
| 106. | Height from bottom to threaded hole | Gage | 18006 |
| 107. | Distance from side to threaded hole | Gage | 18007 |
| 108. | Distance from end to hole | Gage | 18008 |
| 109. | Height from bottom to hole | Gage | 18009 |
| 110. | Height of large end | Gage | 18010 |
| 111. | Height of small end | Gage | 18011 |
| 112. | Length of thinner portion | Gage | 18012 |
| 113. | Distance from end to thinner portion | Gage | 18013 |
| 114. | Diameter of holes | Gage | 18014 |
| 115. | Finish inadequate, damaged or improper | Visual | 18015 |
| Minor: | AQL 0.65 percent | | |
| 201. | Evidence of poor workmanship (see 3.5) | Visual | 18016 |

4.3.2.19 Baseplate (see dwg. 9235457 covering a detail of dwg. 9235446).

| Categories | Defects | Method of Inspection | Code No. |
|---|---|---|---|
| Critical: | None defined. | | |
| Major: | AQL 0.65 percent | | |
| 101. | Diameter of baseplate | Gage | 19001 |
| 102. | Width of baseplate | Gage | 19002 |
| 103. | True position of holes | Gage | 19003 |
| Minor: | AQL 0.65 percent | | |
| 201. | Evidence of poor workmanship (see 3.5) | Visual | 19004 |



Source: https://assist.dla.mil --- Downloaded: 2026-10-26T04:03Z
Check the source to verify that this is the current version before use.

4.3.2.20 Yoke (see dwg. 9235468 covering a detail of dwg. 9235467).

| Categories | Defects | Method of Inspection | Code No. |
|---|---|---|---|
| Critical: | None defined. | | |
| Major: | AQL 0.65 percent | | |
| 101. | Diameter of center hole | Gage | 20001 |
| 102. | Diameter of spring pin holes | Gage | 20002 |
| 103. | Finish inadequate, damaged or improper | Visual | 20003 |
| Minor: | AQL 0.65 percent | | |
| 201. | Evidence of poor workmanship (see 3.5) | Visual | 20004 |

4.3.2.21 Holder assembly (see dwg. 9235469 covering a detail of dwg. 9235467).

| Categories | Defects | Method of Inspection | Code No. |
|---|---|---|---|
| Critical: | None defined. | | |
| Major: | AQL 0.40 percent | | |
| 101. | Diameter of pin | Gage | 21001 |
| 102. | Protective finish inadequate, damaged or improper | Visual | 21002 |
| Minor: | AQL 0.65 percent | | |
| 201. | Evidence of poor workmanship (see 3.5) | Visual | 21003 |

4.3.2.22 Leg assembly (see dwg. 9235470 covering a detail of dwg. 9235467).

| Categories | Defects | Method of Inspection | Code No. |
|---|---|---|---|
| Critical: | None defined. | | |
| Major: | AQL 0.65 percent | | |
| 101. | Length of leg assembly | Gage | 22001 |
| 102. | Diameter of leg | Gage | 22002 |
| 103. | Diameter of spring pin hole | Gage | 22003 |
| Minor: | AQL 0.65 percent | | |
| 201. | Evidence of poor workmanship (see 3.5) | Visual | 22004 |

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:03Z
Check the source to verify that this is the current version before use.

4.3.2.23 Stake (see dwg. 9243224 covering a detail of dwg. 9235467).

| Categories | Defects | Method of Inspection | Code No. |
|---|---|---|---|
| Critical: | None defined. | | |
| Major: | AQL 0.40 percent | | |
| 101. | Length of stake | Gage | 23001 |
| 102. | Protective finish inadequate, damaged or improper | Visual | 23002 |
| Minor: | AQL 0.65 percent | | |
| 201. | Evidence of poor workmanship (see 3.5) | Visual | 23003 |

4.3.2.24 Source Optics Assembly (see dwg. 9235386 covering a detail of dwg. 9235385).

| Categories | Defects | Method of Inspection | Code No. |
|---|---|---|---|
| Critical: | None defined. | | |
| Major: | AQL 1.0 percent | | |
| 101. | Component missing or improperly assembled | Visual | 24001 |
| 102. | Sealing compound missing from screw | Visual | 24002 |
| 103. | Adhesive omitted | Visual | 24003 |
| 104. | Lamp not cemented in position | Visual | 24004 |
| 105. | Lens not cemented to housing | Visual | 24005 |
| Minor: | AQL 0.65 percent | | |
| 201. | Evidence of poor workmanship (see 3.5) | Visual | 24006 |

4.3.2.25 Printed Circuit Board, Driver (see dwg 9235396 covering a detail of dwg. 9235385).

| Categories | Defects | Method of Inspection | Code No. |
|---|---|---|---|
| Critical: | None defined. | | |
| Major: | AQL 1.0 percent | | |
| 101. | Component missing or incorrectly positioned | Visual | 25001 |
| 102. | Conductor damaged or defective (broken, scatched, pinholes) | Visual | 25002 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:03Z
Check the source to verify that this is the current version before use.

| | | | |
|---|---|---|---|
| 103. | Conductor lifted or separated from board | Visual | 25003 |
| 104. | Circuit board warped | Visual | 25004 |
| 105. | Soldering missing, incomplete or excessive | Visual | 25005 |
| Minor: | AQL 1.0 percent | | |
| 201. | Marking missing, incorrect or unidentifiable | Visual | 25006 |
| 202. | Evidence of poor workmanship (see 3.5) | Visual | 25007 |

4.3.2.26 Printed Circuit Board, Oscillator (see dwg. 9235393 covering a detail of dwg. 9235385).

| Categories | Defects | Method of Inspection | Code No. |
|---|---|---|---|
| Critical: | None defined. | | |
| Major: | AQL 1.0 percent | | |
| 101. | Component missing or incorrectly positioned | Visual | 26001 |
| 102. | Conductor damaged or defective (broken, scratched, pinholes) | Visual | 26002 |
| 103. | Conductor lifted or separated from board | Visual | 26003 |
| 104. | Circuit board warped | Visual | 26004 |
| 105. | Soldering missing, incomplete or excessive | Visual | 26005 |
| Minor: | AQL 1.0 percent | | |
| 201. | Marking missing, incorrect or unidentifiable | Visual | 26006 |
| 202. | Evidence of poor workmanship (see 3.5) | Visual | 26007 |

4.3.2.27 Battery Base Assembly, Source (see dwg. 9235399 covering a detail of dwg. 9235385).

| Categories | Defects | Method of Inspection | Code No. |
|---|---|---|---|
| Critical: | None defined. | | |
| Major: | AQL 0.40 percent | | |
| 101. | Component missing or improperly assembled | Visual | 27001 |
| 102. | Adhesive missing or improperly applied | Visual | 27002 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:03Z
Check the source to verify that this is the current version before use.

| | | | |
|---|---|---|---|
| Minor: | AQL 0.65 percent | | |
| 201. | Evidence of poor workmanship (see 3.5) | Visual | 27003 |

4.3.2.28 Electronics and Optics Assembly, Source (see dwg. 9235385 covering a detail of dwg. 9235384).

| Categories | Defects | Method of Inspection | Code No. |
|---|---|---|---|
| Critical: | None defined. | | |
| Major: | AQL 0.65 percent | | |
| 101. | Component missing | Visual | 28001 |
| 102. | Wiring missing, broken or incorrect | Visual | 28002 |
| 103. | Protective coating inadequate, damaged or improper | Visual | 28003 |
| Minor: | AQL 0.65 percent | | |
| 201. | Evidence of poor workmanship (see 3.5) | Visual | 28004 |

4.3.2.29 Source Assembly (see dwg. 9235384 covering a detail of dwg. 9235367).

| Categories | Defects | Method of Inspection | Code No. |
|---|---|---|---|
| Critical: | None defined. | | |
| Major: | AQL 0.40 percent | | |
| 101. | Component missing or improperly assembled | Visual | 29001 |
| 102. | Finish inadequate, damaged or improper | Visual | 29002 |
| Minor: | AQL 0.65 percent | | |
| 201. | Evidence of poor workmanship (see 3.5) | Visual | 29003 |

4.3.2.30 Printed Circuit Board, Output Amplifier (see dwg. 9235422 covering a detail of dwg. 9235414).

| Categories | Defects | Method of Inspection | Code No. |
|---|---|---|---|
| Critical: | None defined. | | |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:03Z
Check the source to verify that this is the current version before use.

| | | | |
|---|---|---|---|
| Major: | AQL 1.0 percent | | |
| 101. | Component missing or incorrectly positioned | Visual | 30001 |
| 102. | Conductor damaged or defective (broken, scratched, pinholes) | Visual | 30002 |
| 103. | Conductor lifted or separated from board | Visual | 30003 |
| 104. | Circuit board warped | Visual | 30004 |
| 105. | Soldering missing, incomplete or excessive | Visual | 30005 |
| Minor: | AQL 1.0 percent | | |
| 201. | Marking missing, incorrect or unidentifiable | Visual | 30006 |
| 202. | Evidence of poor workmanship (see 3.5) | Visual | 30007 |

4.3.2.31 Printed Circuit Board, Amplifier (see dwg. 9235419 covering a detail of dwg. 9235414).

| Categories | Defects | Method of Inspection | Code No. |
|---|---|---|---|
| Critical: | None defined. | | |
| Major: | AQL 1.0 percent | | |
| 101. | Component missing or incorrectly positioned | Visual | 31001 |
| 102. | Conductor damaged or defective (broken, scratched, pinholes) | Visual | 31002 |
| 103. | Conductor lifted or separated from board | Visual | 31003 |
| 104. | Circuit board warped | Visual | 31004 |
| 105. | Soldering missing, incomplete or excessive | Visual | 31005 |
| Minor: | AQL 1.0 percent | | |
| 201. | Marking missing, incorrect or unidentifiable | Visual | 31006 |
| 202. | Evidence of poor workmanship (see 3.5) | Visual | 31007 |

4.3.2.32 Printed Circuit Board, Preamp (see dwg. 9235416 covering a detail of dwg. 9235414).

| Categories | Defects | Method of Inspection | Code No. |
|---|---|---|---|
| Critical: | None defined. | | |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:03Z
Check the source to verify that this is the current version before use.

| | | | |
|---|---|---|---|
| Major: | AQL 1.0 percent | | |
| 101. | Component missing or incorrectly positioned | Visual | 32001 |
| 102. | Conductor damaged or defective (broken, scratched, pinholes) | Visual | 32002 |
| 103. | Conductor lifted or separated from board | Visual | 32003 |
| 104. | Circuit board warped | Visual | 32004 |
| 105. | Soldering missing, incomplete or excessive | Visual | 32005 |
| Minor: | AQL 1.0 percent | | |
| 201. | Marking missing, incorrect or unidentifiable | Visual | 32006 |
| 202. | Evidence of poor workmanship (see 3.5) | Visual | 32007 |

4.3.2.33 Receiver Optics Assembly (see dwg. 9235415 covering a detail of dwg. 9235414).

| Categories | Defects | Method of Inspection | Code No. |
|---|---|---|---|
| Critical: | None defined. | | |
| Major: | AQL 1.0 percent | | |
| 101. | Component missing or improperly assembled | Visual | 33001 |
| 102. | Sealing compound missing from screw | Visual | 33002 |
| 103. | Adhesive omitted | Visual | 33003 |
| 104. | Detector not cemented in position | Visual | 33004 |
| 105. | Lens not cemented to housing | Visual | 33005 |
| Minor: | AQL 0.65 percent | | |
| 201. | Evidence of poor workmanship (see 3.5) | Visual | 33006 |

4.3.2.34 Electronics and Optics Assembly, Receiver (see dwg. 9235414 covering a detail of dwg. 9235413).

| Categories | Defects | Method of Inspection | Code No. |
|---|---|---|---|
| Critical: | None defined. | | |
| Major: | AQL 0.65 percent | | |
| 101. | Component missing or improperly assembled | Visual | 34001 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:03Z
Check the source to verify that this is the current version before use.

| | | | |
|---|---|---|---|
| 102. | Protective coating inadequate damaged or improper | Visual | 34002 |
| 103. | Wiring missing, broken or incorrect | Visual | 34003 |
| Minor: | AQL 0.65 percent | | |
| 201. | Evidence of poor workmanship (see 3.5) | Visual | 34004 |

4.3.2.35 Receiver assembly (see dwg. 9235413 covering a detail of dwg. 9235367).

| Categories | Defects | Method of Inspection | Code No. |
|---|---|---|---|
| Critical: | None defined. | | |
| Major: | AQL 0.40 percent | | |
| 101. | Component missing or improperly assembled | Visual | 35001 |
| 102. | Finish inadequate, damaged or improper | Visual | 35002 |
| Minor: | AQL 0.65 percent | | |
| 201. | Evidence of poor workmanship (see 3.5) | Visual | 35003 |

4.3.2.36 Printed circuit board (see dwg. 9235450 covering a detail of dwg. 9235437).

| Categories | Defects | Method of Inspection | Code No. |
|---|---|---|---|
| Critical: | None defined. | | |
| Major: | AQL 1.00 percent | | |
| 101. | Component missing or incorrectly positioned | Visual | 36001 |
| 102. | Conductor damaged or defective (broken, scratched, pinholes) | Visual | 36002 |
| 103. | Conductor lifted or separated from board | Visual | 36003 |
| 104. | Circuit board warped | Visual | 36004 |
| 105. | Soldering missing, incomplete or excessive | Visual | 36005 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:03Z
Check the source to verify that this is the current version before use.

| | | | |
|---|---|---|---|
| Minor: | AQL 1.0 percent | | |
| 201. | Marking missing, incorrect or unidentifiable | Visual | 36006 |
| 202. | Evidence of poor workmanship (see 3.5) | Visual | 36007 |

4.3.2.37 Printed Circuit Board (see dwg. 9235447 covering a detail of dwg. 9235437).

| Categories | Defects | Method of Inspection | Code No. |
|---|---|---|---|
| Critical: | None defined. | | |
| Major: | AQL 1.0 percent | | |
| 101. | Component missing or incorrectly positioned | Visual | 37001 |
| 102. | Conductor damaged or defective (broken, scratched, pinholes) | Visual | 37002 |
| 103. | Conductor lifted or separated from board | Visual | 37003 |
| 104. | Circuit board warped | Visual | 37004 |
| 105. | Soldering missing, incomplete or excessive | Visual | 37005 |
| Minor: | AQL 1.0 percent | | |
| 201. | Marking missing, incorrect or unidentifiable | Visual | 37006 |
| 202. | Evidence of poor workmanship (see 3.5) | Visual | 37007 |

4.3.2.38 Battery Base Assembly (see dwg. 9235458 covering a detail of dwg. 9235437).

| Categories | Defects | Method of Inspection | Code No. |
|---|---|---|---|
| Critical: | None defined. | | |
| Major: | AQL 0.40 percent | | |
| 101. | Component missing or incorrectly positioned | Visual | 38001 |
| 102. | Adhesive missing or improperly applied | Visual | 38002 |
| Minor: | AQL 0.65 percent | | |
| 201. | Evidence of poor workmanship (see 3.5) | Visual | 38003 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:03Z
Check the source to verify that this is the current version before use.

4.3.2.39 Battery base assembly (see dwg. 9235446 covering a detail of dwg. 9235437).

| Categories | Defects | Method of Inspection | Code No. |
|---|---|---|---|
| Critical: | None defined. | | |
| Major: | AQL 0.40 percent | | |
| 101. | Component missing or improperly assembled | Visual | 39001 |
| 102. | Adhesive missing or improperly applied | Visual | 39002 |
| Minor: | AQL 0.65 percent | | |
| 201. | Evidence of poor workmanship (see 3.5) | Visual | 39003 |

4.3.2.40 Data processor assembly (see dwg. 9235437 covering a detail of dwg. 9235367).

| Categories | Defects | Method of Inspection | Code No. |
|---|---|---|---|
| Critical: | None defined. | | |
| Major: | AQL 0.65 percent | | |
| 101. | Component missing or improperly assembled | Visual | 40001 |
| 102. | Finish inadequate damaged or improper | Visual | 40002 |
| 103. | Wiring missing, broken or incorrect | Visual | 40003 |
| Minor: | AQL 0.65 percent | | |
| 201. | Evidence of poor workmanship (see 3.5) | Visual | 40004 |

4.3.2.41 Test light assembly (see dwg. 9235373 covering a detail of dwg. 9235371).

| Categories | Defects | Method of Inspection | Code No. |
|---|---|---|---|
| Critical: | None defined. | | |
| Major: | AQL 0.40 percent | | |
| 101. | Component missing or improperly assembled | Visual | 41001 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:03Z
Check the source to verify that this is the current version before use.

| | | | |
|---|---|---|---|
| Minor: | AQL 0.65 percent | | |
| 201. | Evidence of poor workmanship (see 3.5) | Visual | 41002 |

4.3.2.42 Output Cable Assembly (see dwg. 9235371 covering a detail of dwg. 9245834).

| Categories | Defects | Method of Inspection | Code No. |
|---|---|---|---|
| Critical: | None defined. | | |
| Major: | AQL 0.65 percent | | |
| 101. | Component missing or improperly assembled | Visual | 42001 |
| 102. | Potting compound omitted | Visual | 42002 |
| 103. | Wiring broke, missing or incorrect | Visual | 42003 |
| 104. | Marking missing, incorrect or unidentifiable | Visual | 42004 |
| Minor: | AQL 0.65 percent | | |
| 201. | Evidence of poor workmanship (see 3.5) | Visual | 42005 |

4.3.2.43 Spool and Output Cable Assembly (see dwg. 9245834 covering a detail of dwg. 9235367).

| Categories | Defects | Method of Inspection | Code No. |
|---|---|---|---|
| Critical: | None defined. | | |
| Major: | AQL 0.40 percent | | |
| 101. | Component missing or improperly assembled | Visual | 43001 |
| Minor: | AQL 0.65 percent | | |
| 201. | Evidence of poor workmanship (see 3.5) | Visual | 43002 |

4.3.2.44 Tripod Assembly (see dwg. 9235467 covering a detail of dwg. 9235367).

| Categories | Defects | Method of Inspection | Code No. |
|---|---|---|---|
| Critical: | None defined. | | |
| Major: | AQL 0.40 percent | | |
| 101. | Height of assembly | Gage | 44001 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:03Z
Check the source to verify that this is the current version before use.

| | | | |
|---|---|---|---|
| 102. | Component missing or incorrectly assembled | Visual | 44002 |
| Minor: | AQL 0.65 percent | | |
| 201. | Evidence of poor workmanship (see 3.5) | Visual | 44003 |

4.3.2.45 Geophone Assembly (see dwg. 9235369 covering a detail of dwg. 9235367).

| Categories | Defects | Method of Inspection | Code No. |
|---|---|---|---|
| Critical: | None defined. | | |
| Major: | AQL 1.0 percent | | |
| 101. | Component missing or improperly assembled | Visual | 45001 |
| 102. | Potting compound omitted | Visual | 45002 |
| 103. | Sealing, locking and retaining compound omitted | Visual | 45003 |
| 104. | Wiring missing, broken, or incorrect | Visual | 45004 |
| 105. | Marking missing, incorrect or unidentifiable | Visual | 45005 |
| Minor: | AQL 0.65 percent | | |
| 201. | Evidence of poor workmanship (see 3.5) | Visual | 45006 |

4.3.2.46 Receiver cable assembly (see dwg. 9235370 covering a detail of dwg. 9235367).

| Categories | Defects | Method of Inspection | Code No. |
|---|---|---|---|
| Critical: | None defined. | | |
| Major: | AQL 0.65 percent | | |
| 101. | Component missing or improperly assembled | Visual | 46001 |
| 102. | Potting compound omitted | Visual | 46002 |
| 103. | Wiring missing, broken or incorrect | Visual | 46003 |
| 104. | Marking missing, incorrect or unidentifiable | Visual | 46004 |
| Minor: | AQL 0.65 percent | | |
| 201. | Evidence of poor workmanship (see 3.5) | Visual | 46005 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:03Z
Check the source to verify that this is the current version before use.

4.3.3 Testing

4.3.3.1 Sampling.-Lot sample size shall consist of thirty-six (36) randomly selected assemblies. The samples shall be tested as follows:

TABLE III

| 18 Samples<br>Transportation Vibration and Functioning<br>Code No. 47001 | | 18 Samples<br>Waterproofness and Functioning<br>Code No. 47002 | |
|---|---|---|---|
| 9 Samples<br>High Temperature and Functioning<br>Code No. 47003 | 9 Samples<br>Low Temperature and Functioning<br>Code No. 47004 | 9 Samples<br>High Temperature and Functioning<br>Code No. 47005 | 9 Samples<br>Low Temperature and Functioning<br>Code No. 47006 |

Transportation Vibration and Functioning or Waterproofness and Functioning tests shall be performed prior to High Temperature and Functioning or Low Temperature and Functioning tests. The applicable paragraphs are as follows:

TABLE IV

| Test | Requirement Paragraph | Test Procedure Paragraph |
|---|---|---|
| Transportation Vibration | 3.3.1 | 4.4.1.1 |
| Waterproofness | 3.3.2 | 4.4.1.2 |
| High Temperature | 3.3.3 | 4.4.1.3 |
| Low Temperature | 3.3.4 | 4.4.1.4 |
| Functioning | 3.4 | 4.4.2 |

4.3.3.2 Rejection.-the lot shall be rejected if two or more fuze assemblies or components do not function when tested as in accordance with 4.4.2.



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:03Z
Check the source to verify that this is the current version before use.

4.3.4 Inspection equipment.-Equipment Tabulation Number ET-9235367 identifies the inspection equipment required to perform the examinations and tests prescribed in this section. The contractor shall design inspection equipment in accordance with the instructions in 6.3.

4.3.4.1 Government rights to documentation.-Inspection equipment drawings and lists provided and revised in accordance with the requirements of the ET may be used by DOD activities for design, procurement, manufacture, testing, evaluation, production and receiving inspection, overhaul, shipping, storage, identification of stock, ordering and storage of replacement parts, inspection of items at overhaul, general maintenance of equipment, construction, survey and whenever inspection equipment drawings are needed.

4.4 Test methods and procedures

4.4.1 Environmental

4.4.1.1 Transportation-vibration.-The test shall be performed in accordance with MIL-STD-331, Test 104, Procedure II. Test equipment shall be in accordance with 4.3.4.

4.4.1.2 Waterproofness.-The fuze components (dwg. 9235367) shall be submerged under water for 15 to 30 minutes. The submersion conditions shall be such that the fuze assembly senses a one foot, min. head of water or its equivalent for the specified time. Test equipment shall be in accordance with 4.3.4.

4.4.1.3 High temperature.-The test shall be performed in accordance with MIL-STD-810, Method 501, using a maximum temperature of 125 minus 1 degrees Fahrenheit (F). Test equipment shall be in accordance with 4.3.4.

4.4.1.4 Low temperature.-The test shall be performed in accordance with MIL-STD-810, Method 502, using a minimum temperature of minus 25 plus 1 degrees Fahrenheit (F). Test equipment shall be in accordance with 4.3.4.

4.4.2 Functioning.-The source assembly and the receiver assembly shall be aligned 95 + 5 feet apart, the fuze properly wired for functioning and the system activated:

a. The test operator should kneel on one knee holding the geophone by the spike in a steady upright position on the other knee. After 5 to 10 seconds, place an opaque object in front of the receiver (breaking beam) while continuing to hold the geophone steady (lighting of the test light evidences proper functioning).



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:03Z
Check the source to verify that this is the current version before use.

b. Remove geophone cable from data processor. After 5 to 10 seconds, place opaque object in front of receiver (breaking beam). (non-lighting of the test light evidences proper functioning).

5. PREPARATION FOR DELIVERY

5.1 Packaging, packing, preservation and marking.-Packaging, packing, preservation and marking shall be in accordance with MIL-STD-1169 for Level C.

6. NOTES

6.1 Ordering data.-Procurement documents shall specify the following:

a. Title, number and date of this specification.

b. Data cards.-Data cards shall be prepared for each lot in accordance with the information specified in MIL-STD-1167.

c. Provisions for submission of first article samples.

6.2 Inspection code numbers.-The five digit code numbers assigned to the inspections herein are to facilitate future data collection and analysis by the Government. These code numbers are also used to correlate the characteristics cited on Equipment Lists with the inspections listed in this specification. In addition, they should be cited as references on drawings of equipment designs submitted by the contractor to the Government for approval (see 6.3.5).

6.3 Inspection equipment.-The contractor shall design inspection equipment as required by the inspection Equipment Lists (EL) referenced on the applicable ET in accordance with the instructions of paragraph 6.3.1 through 6.3.5.

6.3.1 Inspection equipment lists (EL).-Inspection equipment lists indicate the availability of inspection equipment designs by showing in the "number" column of the list of inspection equipment (Form SMUPA 1010) the numbers of drawings or Federal Stock numbers of existing equipment designs, or codes as indicated in paragraph 6.3.2. Design action required of the contractor is described in paragraphs 6.3.3 and 6.3.4. The contractor will be required to prepare detailed drawings in accordance with 6.3.4 for all the equipment coded as "Contractor Design" in the number column. These contractor designs must be approved by the Government prior to fabrication or procuring of the equipment. Designs shall be submitted for approval as specified in 6.3.5.

6.3.2 Inspection equipment list codes.-The inspection equipment as defined in 6.3.3 and 6.3.4 will be designated in the EL by the following codes:



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:03Z
Check the source to verify that this is the current version before use.

CD - Contractor design on controlled contractor format and/or commercial equipment.

MU - Army design, mandatory for use.

6.3.3 Army designs.-Army designs are reflected on detailed drawings which completely depict all the information necessary for the fabrication of the item of inspection equipment. The contractor need provide no design when an Army design is listed for an item of inspection equipment. Army designs fall into two basic classifications; mandatory (designated "MU") and non-mandatory (indicated by drawing or Federal Stock Number). When an inspection equipment list references mandatory Army designs, the contractor shall comply with, and use these designs accordingly. The contractor may, however, in connection with non-mandatory designs, design alternate inspection equipment or use comparable commercial equipment to facilitate his operations. Such contractor prepared designs or commercial equipment selections must be approved by the Government prior to fabrication or procuring of the equipment. Designs shall be submitted for approval as specified in 6.3.5.

6.3.4 Contractor designs.-Contractor designs are designs of inspection equipment for which the Government has assigned design responsibility to the contractor. Contractor designs shall be supported by detailed drawings which depict all the information necessary to completely fabricate, calibrate and operate an item of inspection equipment. This requires that the necessary views, dimensions, materials, finishes, notes, operating and calibration instructions be properly depicted in accordance with approved practices to the extent that further calculation or clarification will not be required. Unless otherwise specified, contractor designs may be developed on the format the contractor normally employs in his equipment design procedure provided such format reflects the detail and information specified above, subject to the following controls: All submitted contractor designs shall conform to MIL-D-1000, Category A, Form 2. Legibility and reproducibility shall permit conventional making of clearly understandable, high contrast reproductions. Contractors shall submit three copies of final designs as a flat set. Designs shall be submitted for approval as specified in 6.3.5.

6.3.5 Submission of contractor designs.-All submitted designs shall contain a reference to the applicable five digit code number contained in Section 4 of this specification and the appropriate component or assembly drawing number and revision letter to which the specific design applies. Unless otherwise specified on the EL, all designs of equipment for inspection of defects classified as critical and major shall be submitted for



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:03Z
Check the source to verify that this is the current version before use.

approval to the Commanding Officer, Picatinny Arsenal, ATTN: SMUPA-ND15. All other designs of inspection equipment shall be approved by the inspection element of the agency administering the contract; submission shall be as directed by the Contracting Officer. Partial submission of inspection equipment designs is permissible and encouraged. However, the Arsenal completion date for design review will be based on the date of the final submission of designs. Picatinny Arsenal design review will be accomplished normally within one month after receipt.

**Custodian:**
Army-MU

**Preparing Activity:**
Army-MU

**Project Number: 1345-A-308**



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:03Z
Check the source to verify that this is the current version before use.