MIL-F-50983B (AR)
30 JUNE 1980
SUPERSEDING
MIL-F-50983A (PA)
19 January 1977

MILITARY SPECIFICATION

FUZE, MT, SQ, M577

LOADING, ASSEMBLING, PACKING AND METAL PARTS

FUZE, MT, SQ, M582

METAL PARTS

This specification is approved for use by the US Army Armament Research and Development Command, and is available for use by all Departments and Agencies of the Department of Defense.

1. SCOPE

1.1 This specification covers the parts, loading, assembling and packing for the Fuze, Mechanical Time and Superquick, M577, and parts for the Fuze, Mechanical Time and Superquick, M582.

2. APPLICABLE DOCUMENTS

2.1 The following documents of the issue in effect on date of invitation for bids, or request for proposal, form a part of this specification to the extent specified herein.

SPECIFICATIONS

MILITARY

MIL-I-45607 - Inspection Equipment, Acquisition, Maintenance and Disposition of
MIL-A-48078 - Ammunition, Standard Quality Assurance Provisions, General Specification for
MIL-P-60412 - Packaging, Packing and Marking for Shipment of Artillery Type and Rocket Fuzes, General Specification for

FSC:1390

Beneficial comments (recommendations, additions, deletions) and any pertinent data which may be of use in improving this document should be addressed to: Commander, US Army Armament Research and Development Command, Attn. DRDAR-QA, Dover, New Jersey 07801 by using the self-addressed Standardization Document Improvement Proposal (DD Form 1426) appearing at the end of this document or by letter.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:04Z
Check the source to verify that this is the current version before use.

STANDARDS

MILITARY

MIL-STD-105	- Sampling Procedures and Tables for Inspection by Attributes.
MIL-STD-331	- Fuze and Fuze Components, Environmental and Performance Tests for
MIL-STD-414	- Sampling Procedures and Tables for Inspection by Variables for Percent Defective
MIL-STD-1169	- Packaging, Packing and Marking for Shipment of Inert Ammunition Components
MIL-STD-1235	- Single and Multi Level Continious Sampling Procedures and Tables for Inspection by Attributes

DRAWINGS

9236500	- Fuze, Mechanical Time and Superquick, M577
9236700	- Fuze, Mechanical Time and Superquick, M582, Less Booster
8595509	- Cup, Booster
8595510	- Pellet, Booster
9297939	- Spotting Charge, Model APG-2

3. REQUIREMENTS

3.1 Material. Materials shall be in accordance with applicable drawings and specifications.

3.2 Parts and Assemblies. The parts and assemblies shall comply with all requirements specified on the Drawings (dwg. 9236500, 9236700) and will all requirements specified in applicable specifications.

3.3 Workmanship. All parts shall be fabricated and finished in a thorough, workmanlike manner and all manufacturing, processing and assembly operations shall be correctly performed. The parts shall be clean and free of burrs, sharp edges, unblended radii, surface defects, cracks, chips, dirt, grease and oil (except where specifically required), rust and other foreign matter. The cleaning method used shall not be injurious to any part, nor shall the parts be contaminated by the cleaning agent. All required markings shall be neat, legible and sharply defined. The surfaces of Interlock Detent Assembly, SSD (dwg. 9236546), Detent, Interlock, SSD (dwg. 9236547), and Detent, Spin, SSD (dwg. 9236550) shall be no worse than depicted in Figure 4.

3.4 Jolt and Jumble. The fuze shall comply with the requirements of MIL-STD-331, Tests 101.1 and 102.1

3.5 Transportation Vibration. The fuze shall comply with the requirements of MIL-STD-331, Test 104.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:04Z
Check the source to verify that this is the current version before use.

3.6 Forty-Foot Drop. The fuze shall comply with the requirements of MIL-STD-331, Test 103.

3.7 Propagation Test. The explosive components in the loaded fuze (dwg. 9236500, 9236700) shall function when subjected to this test. The test shall be performed with a pre-armed SSD as specified in 4.5.19.

3.8 Waterproofness. The fuze assembly shall comply with the requirements of MIL-STD-331, Test 108, except that the duration of immersion shall be five (5) minutes and the pressure shall be three (3) psi gauge.

3.9 Arming and Non-Arming

3.9.1 Safe Separation Device. The detents in the safe separation device shall release the rotor when rotated at a speed of 1800 - 25 rpm and shall not release the rotor when rotated at a speed of 1000 + 25 rpm. The rotor shall arm and lock in the armed position within the time limit of .89 seconds to 1.62 seconds when rotated at 1800 - 25 rpm.

3.9.2 Trigger. The spin detent in the trigger shall release the firing arm assembly when rotated at a speed of 2000 rpm, minimum and shall not release the firing arm assembly when rotated at a speed of less than or equal to 1000 rpm.

3.10 Functioning and Non-Functioning

3.10.1 Trigger (see dwg. 9236603). The firing arm assembly shall not allow the safety plate assembly to release the firing pin when the following pin is at a radius of 0.630 inches maximum, but shall allow the safety plate assembly to release the firing pin when the following pin is at a radius of 0.680 inches minimum. The firing arm assembly shall not allow the safe separation release lever to release the interlock detent when the following pin is at a radius of 0.566 inches maximum, but shall allow the safe separation release lever to release the interlock detent when the following pin is at a radius of 0.596 inches minimum.

3.10.2 Timer. The spin detent in the timer shall not release the balance wheel when rotated at a speed of 1000 + 25 rpm, but shall release the balance wheel when rotated at a speed of 2000 - 25 rpm.

3.11 Counter Wheel Transfer. The counter wheels shall move and transfer movement freely and smoothly with no evidence of skipping throughout its entire setting range when rotated through the #3 wheel.

3.12 Proving Grounds

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:04Z
Check the source to verify that this is the current version before use.

3.12.1 Premature Bursts (see 6.3). There shall be no premature bursts in the gun bore or in flight.

3.12.2 Setting. The fuze shall be capable of being positioned to any setting from the shipping position to a setting of 200 seconds and maintain that setting or be reset.

3.12.3 Ballistic Functioning (see 6.4)

3.12.3.1 Target Impact Non-Function Distance. The fuze, when set PD (see 6.5), shall not cause the projectile to function upon impact of the PD element when fired in the 105MM, M103 Tube, Charge 7 at a two (2) inch plywood target located 150 - 5 feet from the muzzle of the weapon.

3.12.3.2 Target Impact Function Distance. The fuze, when set PD, shall cause the projectile to function upon impact of the PD element when fired in the 155MM, M1 Tube, Charge 1 at a two (2) inch plywood target located 820 - 5 feet from the muzzle of the weapon.

3.12.3.3 Mechanical Time Functioning. The fuze, when set in the time mode, shall cause the projectile to function airburst within the following upper (UL) and lower (LL) time limits:

Set Time (Sec)	Function Time Limits (Sec)	
15	LL = 14.61	UL = 15.39
50	LL = 49.55	UL = 50.45
75	LL = 74.41	UL = 75.59

3.12.3.4 Extreme Temperature Functioning. The fuze, when set in the time mode, shall cause the projectile to function airburst within the following upper (UL) and lower (LL) time limits:

Set Time (Sec)	Function Time Limits (Sec)	
25	LL = 24.61	UL = 25.39
50	LL = 49.50	UL = 50.50

3.13 Setback Detents. Setback detents shall be capable of operating freely while being depressed and returning to their initial positions. When fully depressed, they shall not interfere with the operation of spin detents in the fuze.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:04Z
Check the source to verify that this is the current version before use.

3.14 Timer Beat Rate. The timer assembly (dwg. 9236634) shall have a beat rate that falls within the limits of 80.74 ± .10 beats per second at an amplitude of 115° min.

3.15 Ogive Air Leakage. The ogive assembly, with the setting key, setting key ring and applicable grease, shall exhibit no pressure change when the body opening is sealed and the assembly is held in an evacuated state for one minute.

3.16 Marking. The S.S.D. Assembly (see dwg. 9236524), and the Three Module Assembly (see dwg. 9236569), after undergoing critical classifed tests, shall be marked as specified in 5.2 using mechanized equipment (preferably automated) in accordance with 4.4.4.

3.17 Die Castings. The die castings shall be of uniform quality, free of voids, cracks, blow holes and porosity and shrinkage defects. All flash must be completely removed from parting lines, internal and external profiles, cored holes and ejector pin marks. All waste material remaining from gates must be removed. The castings must be dry, clean and free from chips. All unfilled castings shall be rejected.

3.17.1 Porosity, General. Porosity shall not be allowed on any unmachined functional surface. Maximum single pore size on a machined surface shall not exceed 1/8 inch in any direction on a functional surface and 3/16 inch on a non-functioned surface except as noted in 3.17.2. Porosity shall not reduce a machined functional surface to less than 67% min. of its ideal surface or as noted in 3.17.2. Porosity that alters the configuration of any drawing feature shall not be allowed.

3.17.2 Porosity, Specific. Porosity shall be no worse than that depicted in Figures 5 and 6.

3.17.3 Reusable Scrap. No scrap shall be used other than sprues, gates and rejected die castings of the particular material required by the item print and produced in the manufacturer's plant, when the material is a zinc alloy. The material used shall be free from finishes, lubricants, cleaning agents and any other substance which may contaminate the material of the product. No aluminum scrap of any kind shall be reused.

3.18 First Article Inspection. This specificaaion contains technical provisions for first article inspection. Requirements for the submission of first article samples by the contractor shall be as specified in the contract.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:04Z
Check the source to verify that this is the current version before use.

QUALITY ASSURANCE PROVISIONS

4.1 Responsibility for Inspection and Standard Quality Assurance Provisions. Unless otherwise specified herein or in the contract, the provisions of MIL-A-48078 shall apply and are hereby made a part of this detail specification.

4.1.1 Submission of Product. At the time each completed lot of items deliverable under the contract is submitted to the Government for acceptance, the contractor shall supply the following information, accompanied by a certificate which attests that the information provided is correct and applicable to the product being submitted:

a. A statement that the lot complies with all of the quality assurance provisions specified in this specification.
b. Drawing and specification number and date, together with identification and date of changes thereto.
c. A statement that all material purchased by the contractor meets the requirement, when such material is controlled by Government or commercial specifications referenced in any of the contractual documents, and that certificates of conformance are on file and available for review.
d. Number of items in the lot.
e. Date submitted.

The certificate shall be signed by a responsible agent of the certifying organization. The initial certificate submitted shall be substantiated by evidence of the agent's authority to bind his principal. Subs- tantiation of the agent's authority will not be required with subsequent certificates unless, during the course of the contract, this authority is vested in another agent of the certifying organization.

4.2 Classification of Inspections. See MIL-A-48078

4.3 First Article Inspection

4.3.1 Submission. The contractor shall submit a first article sample as designated by the Contracting Officer for evaluation in accordance with the provisions of 4.3.2 The first article sample shall consist of 137 complete assemblies, 30 complete sets of parts (i.e. 30 each of every component and every subassembly), and the following additional number of parts and assemblies - 15 each: 9236502,

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:04Z
Check the source to verify that this is the current version before use.

9236518, 9236540, 9236547, 9236550.

50 each: 9236473, 9236484, 9236525, 9236526, 9236528, 9236534, 9236537, 9236546, 9236552, 9236569, 9236573, 9236599, 9236604, 9236609, 9236610, 9236614, 9236617, 9236620, 9236624, 9236630, 9236635, 9236640, 9236648, 9236661, 9236663, 9236665, 9236668, 9236672, 9236678, 9236685, 9236690, 9236691, 9236692, 9236697, 9236705

55 each: 9236511, 9236647,

65 each: 9236517

which have been produced by the contractor or furnished by a supplier and which have been manufactured using the same production processes, procedures and equipment which will be used in fulfilling the contract. The Three Module Assembly (dwg. 9236558) and the P.D. Housing Assembly (dwg. 9236560) used only for first article inspections and tests, shall be loaded with inert detonators. These items shall be clearly and indelibly marked by the word "INERT" on two visible surfaces located approximately 180° apart. They will not be used for any testing that requires the functioning of the detonators. All parts and materials, including packaging and packing, shall be obtained from the same source of supply as will be issued in regular production. Prior to submission, the contractor shall inspect the sample to the degree necessary to assure that it conforms to the requirements of the contract and submit a record of this inspection with the sample, including statement of findings for materials, processes and tests. When a multiple cavity mold is used in the fabrication of die cast components, a minimum of ten (10) components from each mold cavity shall be included in the first article sample; 30 if only one cavity is used. The components shall bear a mark which identifies the component with its individual cavity. The mark shall be located on a non-functional surface, where subsequent machining operations shall not obliterate the mark. A sample containing known defects will not be submitted unless specifically authorized by the Contracting Officer. A first article sample, or portion thereof as directed by the Contracting Officer, shall also be submitted whenever there is a lapse in production for a period in excess of 90 days, or whenever a change occurs in manufacturing process, material used, drawing or specification such as to significantly affect product uniformity, as determined by the Government.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:04Z
Check the source to verify that this is the current version before use.

4.3.2 Inspections to be Performed. The first article parts and assemblies submitted in accordance with paragraph 4.3.1, will be subjected by the Government to any or all of the applicable examinations and tests specified in 4.4.2 and 4.4.3 of this specification and to any or all of the requirements of the applicable drawings and specifications.

4.3.3 Rejection. See MIL-A-48078

4.4 Quality Conformance Inspection

4.4.1 Inspection Lot Formation. Inspection lots shall comply with the lot formation provisions of MIL-A-48078. In addition, each lot shall contain:

a. Leads of one lot interfix from one manufacturer.

b. M94 detonators of one lot interfix from one manufacturer.

c. M55 detonators of one lot interfix from one manufacturer.

d. Mild detonating fuzes of one lot interfix from one manufacturer.

e. Safe separation devices of one lot interfix from one manufacturer.

f. Timers of one lot interfix from one manufacturer.

4.4.2 Examination. See MIL-A-48078

a. Sampling Plans. Unless otherwise specified in the Classification of Defects and Test Tables, sampling plans for Major and Minor defects shall be in accordance with MIL-STD-105, Inspection Level II or MIL-STD-1235, Inspection Level II, where applicable.

b. Special Plan. Where Level I of MIL-STD-105 is noted in the following tables, and selected, the sampling plan specified herein shall apply. Whenever Level I is used, the required number of units of product, in the sample to be selected and inspected per lot, shall be grouped into five (5) unit of product sub-samples. When a multiple cavity mold or die is used in the fabrication of molded, cast or stamped components, the selected sub-sample shall represent all mold cavitites or dies being used (this may mean increasing the sub-sample size; for computations the sub-sample shall remain at (5). Identification of the cavity or die shall be by cavity or die mark. The number of sub-samples required shall be divided into the estimated lot size to obtain the interval between selection of sub-samples. The sub-samples shall then be selected and inspected systematically starting with the first five (5)

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:04Z
Check the source to verify that this is the current version before use.

items produced. The lot size shall not exceed its estimate by more than ten percent . The last five (5) units of product manufactured for the lot shall also be inspected (see lot formation requirements in 4.4.1). The inspection records for the lot shall be annotated, as a minimum, with the lot number, start and completion dates, the estimated and actual lot sizes, the computed interval, the number of cavities, the results of each sub-sample inspection and the total cumulative results. When multiple cavities or dies are used, the sub-sample and total results shall be so listed as to identify each cavity or die. This plan may be used only when machining operations, subsequent to part removal from the cavity, are not necessary to produce a completed part. If subsequent machining operations are to be performed, then 4.4.2.a applies.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:04Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-F-50983B (AR)

PARAGRAPH	TITLE	SHEET 1 OF 1	DRAWING NUMBER
4.4.2.1	Scroll, Timing, Timer		9271993
			NEXT HIGHER ASSEMBLY
			9236690

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical					
1	Discontinuity or crack in spiral wall		100%	3.2	Visual w/aid A
Major					
101	Die casting defect	10	a	3.17	Visual w/aid C
102	Depth of grooves, min		0.40%	3.2	Gage
103	Height of lower contact surface, min.		0.40%	3.2	Gage
104	Width of groove at location 1		0.40%	3.2	Gage
105	True Position of groove at location 1		0.40%	3.2	Gage
106	Width of groove at location 3		0.40%	3.2	Gage
107	Major diameter, max.		0.40%	3.2	Gage
108	Width of groove at location 6		0.40%	3.2	Gage
109	True position of groove at location 3		0.40%	3.2	Gage
110	True position of groove at location 6		0.40%	3.2	Gage
111	True position of major diameter		0.65%	3.2	Gage
Minor					
201	Evidence of poor workmanship		1.0%	3.3	Visual

NOTES: a. Reject the lot if one (1) or more defective units are found

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:04Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-F-50983B (AR)

PARAGRAPH	TITLE	SHEET	DRAWING NUMBER
4.4.2.2	Ring Gear, Support and Shaft Assembly, Timer	1 OF 1	9236708
			NEXT HIGHER ASSEMBLY 9236690

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	True position of gear minor diameter		0.40%	3.2	Gage
102	5 lbs. Pull-off load on gear	80a	b	3.2	4.5.1.aq
103	Distance from top of ring gear to bottom of upper shaft pivot, max.		0.65%	3.2	Gage
Minor					
201	Evidence of ppor workmanship		1.0%	3.3	Visual

NOTES: a. Non-destructive
b. Reject the lot if two (2) or more defective units are found.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:04Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-F-50983B (AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 9236705
4.4.2.3	Spring, Setback, Timer				NEXT HIGHER ASSEMBLY 9236634
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Load Test	80b	a	3.2	4.5.3.f
Minor					
201	Evidence of poor workmanship		1.0%	3.3	Visual

NOTES:
a. Reject the lot if two (2) or more defective units are found.
b. Non-destructive

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:04Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-F-50983B (AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 9236703
4.4.2.4	Pin, Setback, Timer				NEXT HIGHER ASSEMBLY 9236702
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Inside diameter, min.		0.40%	3.2	Gage
Minor					
201	Evidence of poor workmanship		1.0%	3.3	Visual

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:04Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-F-50983B (AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 9236702
4.4.2.5	Setback Pin Assembly, Timer				NEXT HIGHER ASSEMBLY 9236634
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101.	Depth of inside diameter		0.40%	3.2	Gage
102.	Staking missing		0.40%	3.2	Visual
Minor					
201.	Evidence of poor workmanship		1.0	3.3	Visual

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:04Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-F-50983B (AR)

PARAGRAPH	TITLE		SHEET OF		DRAWING NUMBER
4.4.2.6	Mainspring and Barrel Assembly, Timer		1 1		9236697
					NEXT HIGHER ASSEMBLY 9236690
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Maximum & minimum Torque	80a	b	3.2	4.5.3.e
Minor					
201	Evidence of poor workmanship		1.0%	3.3	Visual

NOTES: a. Non-Destructive
b. Reject the lot if two (2) or more defective units are found.

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-26104:04Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-F-50983B (AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 9236695
4.4.2.7	Shaft, Ring Gear, Timer				NEXT HIGHER ASSEMBLY 9236691
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Height of upper pivot, max.		0.40%	3.2	Gage
102	True position of scroll diameter		0.40%	3.2	Gage
103	Height from support seat to lower pivot end		0.40%	3.2	Gage
104	Diameter of pivots, min.		0.40%	3.2	Gage
Minor					
201	Evidence of poor workmanship		1.0%	3.3	Visual

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2020-10-26T04:04Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-F-50983B (AR)

PARAGRAPH	TITLE		SHEET OF	DRAWING NUMBER
4.4.2.8	Gear, Ring, Timer		1 1	9236694
				NEXT HIGHER ASSEMBLY 9236692

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Tooth to tooth composite error		0.40%	3.2	Gage
Minor					
201	Evidence of poor workmanship		1.0%	3.3	Visual

NOTES: a. Level I of MIL-STD-105 may be used in accordance with special plan in 4.4.2.

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:04Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-F-50983B (AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 9236692
4.4.2.9	Ring Gear and Support Assembly, Timer				NEXT HIGHER ASSEMBLY 9236691
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	5 lb. Pull-Off Load on Gear	80a	b	3.2	4.5.1.aq
Minor					
201	Evidence of poor workmanship		1.0%	3.3	Visual

NOTES:
a. Non-Destructive
b. Reject the lot if two (2) or more defective units are found.

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:04Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-F-50983B (AR)

PARAGRAPH	TITLE		SHEET OF		DRAWING NUMBER
4.4.2.10	Ring Gear, Support and Shaft Assembly, Timer		1 1		9236691
					NEXT HIGHER ASSEMBLY 9236690
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	True position of gear minor diameter		0.40%	3.2	Gage
102	Distance from top of ring gear to bottom of upper shaft pivot, max.		0.65%	3.2	Gage
Minor					
201	Evidence of poor workmanship		1.0%	3.3	Visual

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:04Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-F-50983B (AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.11	Timing Scroll Assembly, Timer				9236690
					NEXT HIGHER ASSEMBLY
					9236634
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	15 lb. Push-Off Load on Ring Gear support and shaft assembly	80a	b	3.2	4.5.1.ap
102	Perpendicularity of ring gear to shaft		0.40%	3.2	Gage
103	Height from bottom of scroll to top of boss seat on shaft		0.40%	3.2	Gage
104	2 in. lb. Torque on Ring Gear and Scroll	80a	b	3.2	4.5.2.e
Minor					
201	Evidence of poor workmanship		1.0%	3.3	Visual

NOTES:
a. Non-destructive
b. Reject the lot if two (2) or more defective units are found.

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:04Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-F-50983B (AR)

PARAGRAPH	TITLE		SHEET OF	DRAWING NUMBER
4.4.2.12	Screw, Machine, Fillister Head, Timer		1 1	9236689
				NEXT HIGHER ASSEMBLY
				9236634
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH / PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined			
Major				
101	Thread pitch diameter, min.		0.65%	3.2 Gage
102	Thread major diameter, min.		0.65%	3.2 Gage
Minor				
201	Distance to head, min.		1.0%	3.2 Gage
202	Evidence of poor workmanship		1.0%	3.3 Visual

NOTES:

21

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:04Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-F-50983B (AR)

PARAGRAPH	TITLE	SHEET	DRAWING NUMBER
4.4.2.13	Housing, Barrel, Timer	1 OF 1	9236688
			NEXT HIGHER ASSEMBLY 9236634

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Depth of barrel diameter, min.		0.40%	3.2	Gage
102	Outside diameter, min.		0.40%	3.2	Gage
Minor					
201	Evidence of poor workmanship		1.0%	3.3	Visual

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:04Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-F-50983B (AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 9236685/9236707
4.4.2.14	Washer, Spring, Timer				NEXT HIGHER ASSEMBLY 9236634
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Load Test	80a	b	3.2	4.5.3.d
Minor					
201	Evidence of poor workmanship		1.0%	3.3	Visual

NOTES:
a. Non-destructive
b. Reject the lot if two (2) or more defective units are found.

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:04Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-F-50983B (AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 9236681
4.4.2.15	Plate, No. 6, Timer				NEXT HIGHER ASSEMBLY 9236634
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Diameter of location pin hole, max.		0.40%	3.2	Gage
102	Width of location pin slot, max.		0.40%	3.2	Gage
103	Diameter of Gear & Pinion No. 2 hole, max.		0.40%	3.2	Gage
104	Diameter of Gear & pinion No. 1 hole, max.		0.40%	3.2	Gage
105	Diameter of Escapement hole, max.		0.40%	3.2	Gage
106	Diameter of ring gear pivot hole, max.		0.40%	3.2	Gage
107	True position of tumbler slots		0.40%	3.2	Gage
108	True position of location pin hole		0.40%	3.2	Gage
109	True position of location pin slot		0.40%	3.2	Gage
110	True position of Gear & Pinion No. 2 pivot hole		0.40%	3.2	Gage
111	True position of Gear & Pinion No. 1 pivot hole		0.40%	3.2	Gage
112	Length of minor outside diameter, max.		0.40%	3.2	Gage
Minor					
201	Evidence of poor workmanship		1.0%	3.3	Visual

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:04Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-F-50983B (AR)

PARAGRAPH	TITLE		SHEET OF	DRAWING NUMBER
4.4.2.16	Pinion, No. 2, Timer		1 1	9236680
				NEXT HIGHER ASSEMBLY 9236678

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Diameter of upper pivot, min.		0.40%	3.2	Gage
102	Diameter of lower pivot, min.		0.40%	3.2	Gage
103	Tolerance zone around pinion teeth		0.40%	3.2	Gage
Minor					
201	Evidence of poor workmanship		1.0%	3.3	Visual w/aid B

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:04Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-F-50983B (AR)

PARAGRAPH	TITLE		SHEET	OF	DRAWING NUMBER
4.4.2.17	Gear No. 2 and Pinion Assembly, Timer		1	1	9236678
					NEXT HIGHER ASSEMBLY 9236634
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Runout of gear to shaft		0.40%	3.2	Gage
102	Runout of gear major diameter to shaft		0.40%	3.2	Gage
103	10 lb. Push-Off Load on Staking	80a	b	3.2	4.5.1.ao
Minor					
201	Evidence of poor workmanship		1.0%	3.3	Visual w/aid A

NOTES:
a. Non-destructive
b. Reject the lot if two (2) or more defective units are found.

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:04Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-F-50983B (AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 9236677
4.4.2.18	Pinion, No. 1, Timer				NEXT HIGHER ASSEMBLY 9236675
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Diameter of pivots, min.		0.40%	3.2	Gage
102	Tolerance zone around pinion teeth		0.40%	3.2	Gage
Minor					
201	Evidence of poor workmanship		1.0%	3.3	Visual w/aid B

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:04Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-F-50983B (AR)

PARAGRAPH	TITLE	SHEET	OF	DRAWING NUMBER
4.4.2.19	Gear No. 1 and Pinion Assembly, Timer	1	1	9236675
				NEXT HIGHER ASSEMBLY 9236634

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Runout of gear to shaft		0.40%	3.2	Gage
102	Runout of gear major diameter to shaft		0.40%	3.2	Gage
103	12 lb. Push-Off Load Staking	80a	b	3.2	4.5.1.an
Minor					
201	Evidence of poor workmanship		1.0%	3.3	Visual w/aid A

NOTES:
a. Non-destructive
b. Reject the lot if two (2) or more defective units are found.

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:04Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-F-50983B (AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 9236674
4.4.2.20	Wheel, Escape, Timer				NEXT HIGHER ASSEMBLY 9236672
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Damaged or missing tooth		0.40%	3.2	Visual w/aid A
Minor					
201	Evidence of poor workmanship		1.0%	3.3	Visual w/aid B

NOTES: a. Level I of MIL-STD-105 may be used with the special plan in 4.4.2.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:04Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-F-50983B (AR)

PARAGRAPH	TITLE	SHEET	DRAWING NUMBER
4.4.2.21	Pinion, Escape, Timer	1 OF 1	9236673
			NEXT HIGHER ASSEMBLY 923 6672

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Diameter of pivots, min.		0.40%	3.2	Gage
102	Tolerance zone around teeth		0.40%	3.2	Gage
Minor					
201	Evidence or poor workmanship		1.0%	3.3	Visual w/aid B

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:04Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-F-50983B (AR)

PARAGRAPH	TITLE	SHEET	DRAWING NUMBER
4.4.2.22	Escape Wheel and Pinion Assembly, Timer	1 OF 1	9236672
			NEXT HIGHER ASSEMBLY 9236634

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Runout of wheel major diameter to shaft		0.40%	3.2	Gage
102	Runout of wheel to shaft		0.40%	3.2	Gage
103	10 lb. Push-Off Load	80a	b	3.2	4.5.1.am
Minor					
201	Evidence of poor workmanship		1.0%	3.3	Visual w/aid A

NOTES:
a. Non-destructive
b. Reject the lot if two (2) or more defective units are found.

Source: https://assist.dla.mil - Downloaded: 2026-10-26T04:04Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-F-50983B (AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 9236670
4.4.2.23	Bearing, Timer				NEXT HIGHER ASSEMBLY 9236668
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Minor inside diameter, max.		0.40%	3.2	Gage
Minor					
201	Evidence of poor workmanship		1.0%	3.3	Visual w/aid C

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:04Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-F-50983B (AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 9236669
4.4.2.24	Plate, No. 4, Timer				NEXT HIGHER ASSEMBLY 9236668
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	True position of Gear and Pinion No. 2 pivot hole		0.40%	3.2	Gage
102	True position of Gear and Pinion No. 1 pivot hole		0.40%	3.2	Gage
103	True position of lever pivot hole		0.40%	3.2	Gage
104	True position of location pin slot		0.40%	3.2	Gage
105	True position of location pin hole		0.40%	3.2	Gage
106	Diameter of lever hole		0.40%	3.2	Gage
107	Diameter of Gear and Pinion No. 2 pivot hole, max.		0.40%	3.2	Gage
108	Diameter of Gear and Pinion No. 1 pivot hole, max.		0.40%	3.2	Gage
109	Diameter of location pin hole, max.		0.40%	3.2	Gage
110	Width of location pin slot, max.		0.40%	3.2	Gage
Minor					
201	Evidence of poor workmanship		1.0%	3.3	Visual

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:04Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-F-50983B (AR)

PARAGRAPH	TITLE		SHEET OF		DRAWING NUMBER
4.4.2.25	Plate No. 4, and Bearing Assembly, Timer		1 1		9236668
					NEXT HIGHER ASSEMBLY 9236634
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101.	2 lb. Push-Off Load on Bearing	80a	b.	3.2	4.5.1.21
102	Gap between bearing and plate		0.40%	3.2	Visual w/aid C
Minor					
201	Evidence of poor workmanship		1.0%	3.3	Visual w/aid C

NOTES:
a. Non-destructive
b. Reject the lot if two (2) or more defective units are found.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26104:04Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-F-50983B (AR)

PARAGRAPH	TITLE	SHEET	OF	DRAWING NUMBER
4.4.2.26	Pallet Support and Pin Assembly, Timer	1	1	9236665
				NEXT HIGHER ASSEMBLY 9236661

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Distance from lever seat to end of pin, min.		0.40%	3.2	Gage
102	3 lb. Push-Off Load on Pin	80a	b	3.2	4.5.1.ak
Minor					
201	Evidence of poor workmanship		1.0%	3.3	Visual w/aid C

NOTES:
a. Non-destructive
b. Reject the lot if two (2) or more defective units are found.

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:04Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-F-50983B (AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 9236663
4.4.2.27	Lever Staff Assembly, Timer				NEXT HIGHER ASSEMBLY 9236661
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	1 lb. Axial Unseating Load	80a	b	3.2	4.5.1.aj
Minor					
201	Evidence of poor workmanship		1.0%	3.3	Visual w/aid C

NOTES:
a. Non-destructive
b. Reject the lot if two (2) or more defective units are found.

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:04Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-F-50983B (AR)

PARAGRAPH	TITLE		SHEET OF		DRAWING NUMBER
4.4.2.28	Lever Assembly, Timer		1 1		9236661
					NEXT HIGHER ASSEMBLY 9236634
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	2 lb. Push-Off Load on Staking	80a	b	3.2	4.5.1.ai
Minor					
201	Evidence of poor workmanship		1.0%	3.3	Visual w/aid B

NOTES:
a. Non-Destructive
b. Reject the lot if two (2) or more defective units are found.

Source: https://nasiat.dla.mil/ - Downloaded: 2020-10-26T04:04:04Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-F-50983B (AR)

PARAGRAPH	TITLE	SHEET 1 OF 1	DRAWING NUMBER
4.4.2.29	Plate, No. 2, Timer		9236659
			NEXT HIGHER ASSEMBLY 9236634

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	True position of location pin slot		0.40%	3.2	Gage
102	True position of lever pivot hole		0.40%	3.2	Gage
103	Diameter of lever pivot hole, max.		0.40%	3.2	Gage
104	Diameter of location pin hole, max.		0.40%	3.2	Gage
105	Width of location pin slot, max.		0.40%	3.2	Gage
Minor					
201	Evidence of poor workmanship		1.0%	3.3	Visual

NOTES: a. Level I of MIL-STD-105 may be used with the special plan in 4.4.2.

Source: https://assist.dla.mil - Downloaded: 2026-01-26T04:04Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-F-50983B (AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 9236657
4.4.2.30	Detent, Spin, Timer				NEXT HIGHER ASSEMBLY 9236656
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Die casting defect	10	b	3.17	Visual w/aid C
Minor					
201	Evidence of poor workmanship		1.0%	3.3	Visual

NOTES:
a. Level I of MIL-STD-105 may be used with special plan in 4.4.2
b. Reject the lot if one (1) or more defective units are found.

Source: https://assist.dla.mil - Downloaded: 2020-10-26T04:04Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-F-50983B (AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.31	Balance Staff and Pin Assembly, Timer				9236648
					NEXT HIGHER ASSEMBLY
					0236473
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Height of pins from staff surface, min.		0.40%	3.2	Gage
102	1.5 lb. Axial Unseating load on pins	80a	b	3.2	4.5.1.ah
Minor					
201	Evidence of poor workmanship		1.0%	3.3	Visual w/aid A

NOTES:
a. Non-destructive
b. Reject the lot if two (2) or more defective units are found.

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:04Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-F-50983B (AR)

PARAGRAPH	TITLE	SHEET	DRAWING NUMBER
4.4.2.32	Balance Wheel, Staff and Hairspring Assembly Timer	1 OF 1	9236647
			NEXT HIGHER ASSEMBLY 9236635

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Balance wheel outside tolerance zone		0.40%	3.2	Gage
102	9 lbs axial load on hairspring pivots	40a	b	3.2	4.5.1.ag
Minor					
201	Evidence of poor workmanship		1.0%	3.3	Visual w/aid A

NOTES:
a. Destructive
b. Reject the lot if one (1) or more defective units are found.

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:04Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-F-50983B (AR)

PARAGRAPH	TITLE	SHEET	DRAWING NUMBER
4.4.2.33	Tube, Hairspring, Timer	1 OF 1	9236644
			NEXT HIGHER ASSEMBLY: 9236635

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Diameter of knurl, min.		0.40%	3.2	Gage
Minor					
201	Evidence of poor workmanship		1.0%	3.3	Visual

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:04Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-F-50983B (AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.34	Setting Ring Gear Assembly, Timer				9236640
					NEXT HIGHER ASSEMBLY
					9236635
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	5 lb. Axial unseating load on pin	80a	b	3.2	4.5.1.af
Minor					
201	Evidence of poor workmanship		1.0%	3.3	Visual

NOTES:
a. Non-destructive
b. Reject the lot if two (2) or more defective units are formed.

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:04Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-F-50983B (AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.35	Plate, No. 1, Timer				9236636
					NEXT HIGHER ASSEMBLY
					9236635
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR /100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Height from bottom to wheel surface, min.		0.40%	3.2	Gage
102	Pitch diameter of thread, max.		0.40%	3.2	Gage
103	Diameter of tube hole, max.		0.40%	3.2	Gage
104	Height from bottom to ring gear seat, min.		0.40%	3.2	Gage
Minor					
201	Evidence of poor workmanship		1.0%	3.3	Visual

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:04Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-F-50983B (AR)

PARAGRAPH	TITLE		SHEET OF	DRAWING NUMBER
4.4.2.36	Plate No. 1 Assembly, Timer		1 1	9236635
				NEXT HIGHER ASSEMBLY 9236634

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	True position of balance wheel, staff and hairspring assembly		0.40%	3.2	Gage
102	6 lb. Pull-Out load on balance wheel, staff and hairspring assembly	40b	c	3.2	4.5.1.ae
103	50 in. lb. torque load on ring gear assembly	80a	d	3.2	4.5.2.d
104	5 lb. axial unseating load on spin detent pivot pin	80a	d	3.2	4.5.1.ab
105	5 lb. axial unseating load on bushing	80a	d	3.2	4.5.1.ac
106	40 lb. axial unseating load on dowel pins	80a	d	3.2	4.5.1.ad
Minor					
201	Evidence of poor workmanship		1.0%	3.3	Visual

NOTES: a. Non-destructive
b. Destructive
c. Reject the lot if one (1) or more defective units are found.
d. Reject the lot if two (2) or more defective units are found.

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:04Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-F-50983B (AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.37	Timer Assembly				9236634 and 9236711
					NEXT HIGHER ASSEMBLY
					9236569
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Limits of angle between tumbler and scroll exit port		0.40%	3.2	Gage
102	Balance wheel not detented in proper position and setback detent not restraining spin detent		0.40%	3.2	Visual
103	Mainspring not wound as indicated		0.40%	3.2	Manual
104	Mainspring barrel stakes missing or insufficient		0.40%	3.2	Visual
105	Epoxy missing on indicated surfaces	b	0.40%	3.2	Visual
106	Timer function test	a	100%	3.10.2	4.5.9
107	Timer non-function test	a	100%	3.10.2	4.5.10
108	Setback pin arming test	a	100%	3.13	4.5.11
109	Timer Beat Rate and amplitude	a	100%	3.14	4.5.13
110	Expansion plug above flush		0.40%	3.2	Visual
111	Protective cap missing	c	0.65%	3.2	Visual
Minor					
201	Evidence of poor workmanship		1.0%	3.3	Visual

NOTES:
a. Non-destructive
b. Does not apply to 9236711
c. Does not apply to 9236634

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:04Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-F-50983B (AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 9236631
4.4.2.3g	Sleeve				NEXT HIGHER ASSEMBLY 9236630
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Barrel diameter, max.		0.40%	3.2	Gage
102	Scroll diameter, min.		0.40%	3.2	Gage
103	True position of scroll diameter		0.40%	3.2	Gage
104	Diameter of trigger location pin holes, max.		0.40%	3.2	Gage
105	True position of trigger location pin holes		0.40%	3.2	Gage
106	Depth of release slot, min.		0.40%	3.2	Gage
107	Diameter of snap ring slot, min.		0.65%	3.2	Gage
108	Height of scroll diameter, max.		0.65%	3.2	Gage
Minor					
201	Evidence of poor workmanship		1.0%	3.3	Visual

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:04Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-F-50983B (AR)

PARAGRAPH	TITLE	SHEET 1 OF 1	DRAWING NUMBER
4.4.2.39	Sleeve Assembly		9236630
			NEXT HIGHER ASSEMBLY 9236569

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	5 lb. axial unseating load on key	80a	b	3.2	4.5.1.aa
102	Length between key and sleeve inside dia., max.		0.40%	3.2	Gage
Minor					
201	Evidence of poor workmanship		1.0%	3.3	Visual

NOTES:
a. Non-destructive
b. Reject the lot if two (2) or more defective units are found.

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:04Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.40	Plate, Bottom Trigger				9236627
					NEXT HIGHER ASSEMBLY
					9236603
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR /100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Diameter of location pin hole, max.		0.40%	3.2	Gage
102	Diameter of firing arm pivot hole, max.		0.40%	3.2	Gage
103	True position of location pin slot		0.40%	3.2	Gage
104	True position of release lever pivot hole		0.40%	3.2	Gage
105	True position of safety plate pivot hole		0.40%	3.2	Gage
106	True position of firing arm shaft pivot hole		0.40%	3.2	Gage
107	Diameter of safety plate pivot hole, max		0.40%	3.2	Gage
108	Diameter of release level pivot hole, max.		0.40%	3.2	Gage
109	Absence of firing pin bevel		0.40%	3.2	Visual
Minor					
201	Evidence of poor workmanship		1.0%	3.3	Visual

NOTES:

a. Alternative "compressive load test" may be performed in lieu of above inspections; see paragraph 4.4.2.56, Trigger Assembly.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:04Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-F-50983B (AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 9236624
4.4.2.41	Spring, Firing Pin, Trigger				NEXT HIGHER ASSEMBLY 9236603
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Load test	80a	b	3.2	4.5.3.c
Minor					
201	Evidence of poor workmanship		1.0%	3.3	Visual

NOTES:
a. Non-destructive
b. Reject the lot if two (2) or more defective units are found.

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:04Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-F-50983B (AR)

PARAGRAPH	TITLE		SHEET OF	DRAWING NUMBER
4.4.2.42	Pin, Firing, Trigger		1 1	9236623
				NEXT HIGHER ASSEMBLY 9236603

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Profile of point		0.40%	3.2	Gage
102	Finish above specified		0.40%	3.2	Gage w/aid C
103	Length of firing pin point, min.		0.40%	3.2	Gage
Minor					
201	Evidence of poor workmanship		1.0%	3.3	Visual w/aid A

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:04Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-F-50983B (AR)

PARAGRAPH	TITLE	SHEET	OF	DRAWING NUMBER
4.4.2.43	Shaft, Release, Trigger	1	1	9236622
				NEXT HIGHER ASSEMBLY 9236620

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Diameter of pivots, min.		0.40%	3.2	Gage
102	Finish above specified		0.40%	3.2	Gage
103	Height of lower pivot		0.40%	3.2	Gage
Minor					
201	Evidence of poor workmanship		1.0%	3.3	Visual

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:04Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-F-50983B (AR)

PARAGRAPH	TITLE		SHEET OF		DRAWING NUMBER
4.4.2.44	Safe Separation Release Assembly, Trigger		1 1		9236620
					NEXT HIGHER ASSEMBLY 9236603
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	10 lb. Push-Off load on staking	80a	b	3.2	4.5.1.z
Minor					
201	Evidence of poor workmanship		1.0%	3.3	Visual

NOTES:
a. Non-destructive
b. Reject the lot if two (2) or more defective units are found.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:04Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-F-50983B (AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 9236619
4.4.2.45	Shaft, Safety Plate, Trigger				NEXT HIGHER ASSEMBLY 9236617
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Height of lower pivot, max.		0.40%	3.2	Gage
102	Height of plate seat diameter, min.		0.65%	3.2	Gage
Minor					
201	Evidence of poor workmanship		1.0%	3.3	Visual

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:04Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-F-50983B (AR)

PARAGRAPH	TITLE		SHEET OF	DRAWING NUMBER
4.4.2.46	Plate, Safety, Trigger		1 1	9236618
				NEXT HIGHER ASSEMBLY
				9236617
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH / PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined			
Major				
101	Length of step along restraining edge min.		0.40%	3.2 Gage
Minor				
201	Evidence of poor workmanship		1.0%	3.3 Visual w/aid A

NOTES: a. Level I of MIL-STD-105 may be used with special plan in 4.4.2.

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:04Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-F-50983B (AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 9236617
4.4.2.47	Firing Safety Plate Assembly, Trigger				NEXT HIGHER ASSEMBLY 9236603
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Perpendicularity of plate to shaft		0.40%	3.2	Gage
102	25 lb. Push-Off load on staking	80a	b	3.2	4.5.1.y
Minor					
201	Evidence of poor workmanship		1.0%	3.3	Visual

NOTES: a. Non-destructive
b. Reject the lot if two (2) or more defective units are found.

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:04Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-F-50983B (AR)

PARAGRAPH	TITLE		SHEET OF	DRAWING NUMBER
4.4.2.48	Rotor, Detent, Trigger		1 1	9236615
				NEXT HIGHER ASSEMBLY
				9236614
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Height of upper pivot, max.		0.40%	3.2	Gage
Minor					
201	Evidence of poor workmanship		1.0%	3.3	Visual w/aid A

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:04Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-F-50983B (AR)

PARAGRAPH	TITLE		SHEET OF		DRAWING NUMBER
4.4.2.49	Detent Assembly, Trigger		1 1		9236614
					NEXT HIGHER ASSEMBLY 9236603
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	15 lb. Push-Off load on staking	80a	b	3.2	4.5.1.x
Minor					
201	Evidence of poor workmanship		1.0%	3.3	Visual

NOTES:
a. Non-destructive
b. Reject the lot if two (2) or more defective units are found.

Source: https://assist.dla.mil - Downloaded: 2026-10-26T04:04Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-F-50983B (AR)

PARAGRAPH	TITLE		SHEET OF		DRAWING NUMBER
4.4.2.50	Shaft, Firing Arm, Trigger		1 1		9236611
					NEXT HIGHER ASSEMBLY
					9236609
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Diameter of pivots, min.		0.40%	3.2	Gage
102	Total length without pivots, min.		0.40%	3.2	Gage
103	Height of pivots, max.		0.40%	3.2	Gage
104	Height of shaft body below slot		0.65%	3.2	Gage
Minor					
201	Evidence of poor workmanship		1.0%	3.3	Visual

NOTES:

Source: https://assist.dla.mil - Downloaded: 2025-01-28T04:04Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-F-50983B (AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 9236610
4.4.2.51	Spring, Torsion, Trigger				NEXT HIGHER ASSEMBLY 9236609
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Torque test	80a	b	3.2	4.5.3.b
Minor					
201	Evidence of poor workmanship		1.0%	3.3	Visual

NOTES:
a. Non-destructive
b. Reject the lot if two (2) or more defective units are found.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:04Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-F-50983B (AR)

PARAGRAPH	TITLE	SHEET	OF	DRAWING NUMBER
4.4.2.52	Firing Arm Assembly, Trigger	1	1	9236609
				NEXT HIGHER ASSEMBLY 9236603

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	15 lb. Push-Off load on staking	80a	b	3.2	4.5.1.w
Minor					
201	Evidence of poor workmanship		1.0%	3.3	Visual

NOTES:
a. Non-destructive
b. Reject the lot if two (2) or more defective units are found.

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:04Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-F-50983B (AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 9236608
4.4.2.53	Plate, Top, Trigger				NEXT HIGHER ASSEMBLY 9236603
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Diameter of firing arm pivot hole, max.		0.40%	3.2	Gage
102	Diameter of scroll pivot hole, max.		0.40%	3.2	Gage
103	True position of location pin slot		0.40%	3.2	Gage
104	True position of hole "Y"		0.40%	3.2	Gage
105	True position of scroll pivot hole		0.40%	3.2	Gage
106	Diameter of location pin hole, max.		0.40%	3.2	Gage
Minor					
201	Evidence of poor workmanship		1.0%	3.3	Visual

NOTES:
a. Alternative "compressive load test" may be performed in lieu of above inspections, see paragraph 4.4.2.56, Trigger Assembly.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:04Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-F-50983B (AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.54	Spacer, Trigger				9236605
					NEXT HIGHER ASSEMBLY
					9236604
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	True position of safety plate pivot hole		0.40%	3.2	Gage
102	True position of release lever pivot hole		0.40%	3.2	Gage
103	Diameter of safety plate pivot hole, max.		0.40%	3.2	Gage
104	Diameter of release lever pivot hole, max.		0.40%	3.2	Gage
105	Die casting defects	10	a	3.17	Visual w/aid C
Minor					
201	Evidence of poor workmanship		1.0%	3.3	Visual

NOTES:
a. Reject the lot if one (1) or more defective units are found.
b. Alternative "compressive load test" may be performed in lieu of inspections 101 to 104; see paragraph 4.4.2.56, Trigger Assembly.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:04Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-F-50983B (AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 9236604
4.4.2.55	Spacer Assembly, Trigger				NEXT HIGHER ASSEMBLY 9236603
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	True position of top pins		0.40%	3.2	Gage
102	True position of bottom pins		0.40%	3.2	Gage
103	35 lb. axial unseating load on bottom pins	80a	b	3.2	4.5.1.u
104	5 lb. axial unseating load on top pins	80a	b	3.2	4.5.1.v
105	Height of bottom pins above spacer surface		0.65%	3.2	Gage
106	Height of top pins above spacer surface, min.		0.65%	3.2	Gage
Minor					
201	Evidence of poor workmanship		1.0%	3.3	Visual

NOTES: a. Non-destructive
b. Reject the lot if two (2) or more defective units are found.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:04Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-F-50983B (AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.56	Trigger Assembly				9236603
					NEXT HIGHER ASSEMBLY 9236569
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical					
1	Height of following pin from top plate		100%	3.2	Gage
Major					
101	Rivets above flush		0.40%	3.2	Visual
102	Torsion spring not prewound		0.40%	3.2	Manual
103	2000 RPM Detent Release	a	100%	3.9.2	4.5.6
104	1000 RPM Detent Non-Release	a	100%	3.9.2	4.5.7
105	Sequential Trigger Function	a	100%	3.10.1	4.5.8
Minor					
201	Evidence of poor workmanship		1.0%	3.3	Visual

NOTES: a. Non-destructive. b. "Compressive load test". If the tests of 103, 104 and 105 are performed while the unit is under the compressive load stipulated on the drawing, then the inspections required on the noted paragraphs may be omitted.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:04Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-F-50983B (AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 9236600
4.4.2.57	Pin, Setback				NEXT HIGHER ASSEMBLY 0236569
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Inside diameter, min.		0.40%	3.2	Gage
102	Height of inside diameter, min.		0.40%	3.2	Gage
Minor					
201	Evidence of poor workmanship		1.0%	3.3	Visual

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-26104:04Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-F-50983B (AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 9236599
4.4.2.58	Spring, Setback				NEXT HIGHER ASSEMBLY 9236569
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Load test	80a	b	3.2	4.5.3.a
Minor					
201	Evidence of poor workmanship		1.0%	3.3	Visual

NOTES:
a. Non-destructive
b. Reject the lot if two (2) or more defective units are found.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:04Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-F-50983B (AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 9236591
4.4.2.59	Gear, Setting				NEXT HIGHER ASSEMBLY 9236484
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Total composite error		0.40%	3.2	Gage
102	Tooth to tooth composite error		0.40%	3.2	Gage
Minor					
201	Evidence of poor workmanship		1.0%	3.3	Visual w/aid A

NOTES: a. Level I of MIL-STD-105 may be used with special plan in 4.4.2.

Source: https://assist.dla.mil - Downloaded: 2026-10-26T04:04Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-F-50983B (AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 9236590
4.4.2.60	Pinion, Setting				NEXT HIGHER ASSEMBLY 9236484
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Diameter of pivots, min.		0.40%	3.2	Gage
102	Tooth to tooth composite error		0.40%	3.2	Gage
103	Total composite error		0.40%	3.2	Gage
Minor					
201	Evidence of poor workmanship		1.0%	3.3	Visual w/aid A

NOTES:

Source: https://assist.dla.mil - Downloaded: 2020-10-20T04:04Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-F-50983B (AR)

PARAGRAPH	TITLE		SHEET OF		DRAWING NUMBER
4.4.2.61	Timer Housing Assembly		1 1		9236588
					NEXT HIGHER ASSEMBLY 9236569
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical					
1	Setting gears and pinions missing or deformed		100%	3.2	Visual
Major					
101	Bearing plate fastened insecurely		0.40%	3.2	Manual
102	Rivets above flush		0.65%	3.2	Visual
Minor					
201	Evidence of poor workmanship		1.0%	3.3	Visual

NOTES:

Source: https://assist.dla.mil - Downloaded: 2026-02-20T04:04:04Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-F-50983B (AR)

PARAGRAPH	TITLE		SHEET	OF	DRAWING NUMBER
4.4.2. 62	Counter, Pinion		1	1	9236580
					NEXT HIGHER ASSEMBLY 9236573
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Die casting defect	10	b	3.17	Visual w/aid C
Minor					
201	Evidence of poor workmanship		1.0%	3.3	Visual

NOTES: a. Level I of MIL-STD-105 may be used with special plan in 4.4.2
b. Reject the lot if one (1) or more defective units are found.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:04Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-F-50983B (AR)

PARAGRAPH	TITLE		SHEET OF		DRAWING NUMBER
4.4.2.63	Wheel, No. 3, Counter		1 1		9236579
					NEXT HIGHER ASSEMBLY 9236573
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	True position of numbers		0.40%	3.2	Gage
102	True position of saw teeth minor diameter		0.40%	3.2	Gage
Minor					
201	Evidence of poor workmanship		1.0%	3.3	Visual

NOTES: a. Level I of MIL-STD-105 may be used with special plan in 4.4.2.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26104:04Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-F-50983B (AR)

PARAGRAPH	TITLE		SHEET OF		DRAWING NUMBER
4.4.2.64	Body, Counter		1 1		9236575
					NEXT HIGHER ASSEMBLY 9236574
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Die casting defect	10	b	3.17	Visual w/aid C
Minor					
201	Evidence of poor workmanship		0.65%	3.3	Visual

NOTES: a. Level I of MIL-STD-105 may be used with special plan in 4.4.2.
b. Reject the lot if one (1) or more defective units are found.

Source: https://assist.dla.mil - Downloaded: 2026-10-26T04:04Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-F-50983B (AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.65	Counter Assembly				9236573
					NEXT HIGHER ASSEMBLY
					9236569
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical					
1	Counter Wheel Transfer	a	100%	3.11	4.5.12
Major					
101	5 lb. Push-Off on retaining ring	80a	b	3.2	4.5.1.t
102	Hairline not stationary with respect to body and in excess of allowable tolerances		0.40%	3.2	Manual
103	Index lines missing or unreadable		0.40%	3.2	Visual
Minor					
201	Evidence of poor workmanship		1.0%	3.3	Visual

NOTES: a. Non-destructive
b. Reject the lot if two (2) or more defective units are found.

Source: https://assist.dla.mil -- Downloaded: 2026-03-02T16:04Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-F-50983B (AR)

PARAGRAPH	TITLE		SHEET 1 OF 2		DRAWING NUMBER 9236569
4.4.2.66	Three Module Assembly				NEXT HIGHER ASSEMBLY 9236558
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical					
1	Setback detent does not hold spin detent in position to lock the trigger in the unfired position		100%	3.2	Visual/Manual
2	S.S.D. release lever missing or not restrained by firing arm shaft in unfire position		100%	3.2	Visual
Major					
101	Timer housing stakes missing or insecure		0.40%	3.2	Visual/Manual
102	Setback retainer stakes missing or insecure		0.40%	3.2	Visual/Manual
103	Zero setting improper		0.40%	3.2	Visual
104	Trigger assembly not in unfired position		0.40%	3.2	Visual
105	Grease missing in setback pin cavity		0.40%	3.2	Visual
106	Position of tumblers incorrect		0.40%	3.2	Visual
107	Skirt crimps missing or insecure		0.40%	3.2	Visual/Manual
108	9.0 + 4.0 in.-lb. grip ring torque	80a	b	3.2	4.5.2.c
109	4.5 min. in.-lb. grip ring torque	80a	b	3.2	4.5.2.b
110	Tumbler Stop	125a	0.40%	3.2	4.5.2.f
111	Trigger setback pin arming		0.40%	3.13	4.5.14
112	True position of hairline		0.65%	3.2	Gage
113	Gap between trigger and sleeve		0.65%	3.2	Visual

NOTES: a. Non-destructive
b. Reject the lot if two (2) or more defective units are found.

75

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:04Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-F-50983B (AR)

PARAGRAPH	TITLE		SHEET 2 OF 2		DRAWING NUMBER 9236569
4.4.2.66	Three Module Assembly				NEXT HIGHER ASSEMBLY 9236558
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Minor					
201	Evidence of poor workmanship		1.0%	3.3	Visual

NOTES:

a. Non-destructive
b. Reject the lot if two (2) or more defective units are found.

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:04Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-F-50983B (AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 9236563
4.4.2.67	Plate, Firing				NEXT HIGHER ASSEMBLY 9236561
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Radius on firing pin points		0.40%	3.2	Gage
102	Width of tab., min.		0.40%	3.2	Gage
103	Material thickness, max.		0.40%	3.2	Gage
104	True position of firing pin width		0.40%	3.2	Gage
105	True position of tab		0.40%	3.2	Gage
106	Height between base and firing pin point, min.		0.40%	3.2	Gage
Minor					
201	Evidence of poor workmanship		1.0%	3.3	Visual

NOTES:

a. Level I of MIL-STD-105 may be used with special plan in 4.4.2.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:04Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-F-50983B (AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.68	Holder, Detonator				9236562
					NEXT HIGHER ASSEMBLY 9236561
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	True position of firing plate seat outside diameter		0.40%	3.2	Gage
102	Width of tab slot, max.		0.40%	3.2	Gage
103	True position of tab slot		0.40%	3.2	Gage
104	True position of detonator holes minor diameter		0.40%	3.2	Gage
Minor					
201	Evidence of poor workmanship		1.0%	3.3	Visual

NOTES:

a. Level of MIL-STD-105 may be used with special plan in 4.4.2.

Archive: https://assist.dla.mil - Downloaded: 2024-10-26T04:04Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-F-50983B (AR)

PARAGRAPH	TITLE		SHEET	OF	DRAWING NUMBER
4.4.2.69	P.D. Housing Assembly		1	1	9236560
					NEXT HIGHER ASSEMBLY 9236558
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Detonator(s) missing or inverted		0.40%	3.2	Visual
102	Crimp missing over detonator holder		0.40%	3.2	Visual
103	Tape missing from indicated surfaces		0.40%	3.2	Visual
104	20 lb. Pull-Off and 3 in-lb radial torque on detonator holder	40a	b	3.2	4.5.1.s
105	Detonator(s) not positioned over MDF		0.65%	3.2	Visual
Minor					
201	Evidence of poor workmanship		1.0%	3.3	Visual

NOTES: a. Destructive (inert units per paragraph 4.3.1 may be used.)
b. Reject the lot if one (1) or more defective units are found.

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:04Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-F-50983B (AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 9236558
4.4.2.70	Three Module Assembly, Loaded				NEXT HIGHER ASSEMBLY 9236500/9236700
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Gap between MDF and centerline of firing pin, max.		0.40%	3.2	Gage
102	Tape missing or not holding MDF on trigger		0.40%	3.2	Visual/Manual
Minor					
201	Evidence of poor workmanship		1.0%	3.3	Visual

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:04Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-F-40983B (AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 9236555
4.4.2.71	Spacer, SSD				NEXT HIGHER ASSEMBLY 9236552
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Die casting defect	10	b	3.17	Visual w/aid C
Minor					
201	Evidence of poor workmanship		1.0%	3.3	Visual

NOTES:
a. Level I of MIL-STD-105 may be used in accordance with special plan in 4.4.2.
b. Reject the lot if one (1) or more defective units are found.

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:04Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-F-50983B (AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.72	Plate, Top, SSD				9236553
					NEXT HIGHER ASSEMBLY
					9236552
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Width of trigger location pin slot, max.		0.40%	3.2	Gage
102	Diameter of trigger location pin hole, max.		0.40%	3.2	Gage
103	True position of trigger location pin hole		0.40%	3.2	Gage
104	True position of trigger location pin slot		0.40%	3.2	Gage
Minor					
201	Evidence of poor workmanship		1.0%	3.3	Visual

NOTES: a. Level 1 of MIL-STD-105 may be used in accordance with special plan in 4.4.2.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:04Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-F-50983B (AR)

PARAGRAPH	TITLE	SHEET	DRAWING NUMBER
4.4.2.73	Detent, Spin, SSD	1 OF 1	9236550
			NEXT HIGHER ASSEMBLY 9236549

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	40 lb. load on detent nib	40a	b	3.2	4.5.1.r
Minor					
201	Evidence of poor workmanship		1.0%	3.3	Visual

NOTES:
a. Destructive
b. Reject the lot if one (1) or more defective units are found.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:04Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-F-50983B (AR)

PARAGRAPH	TITLE		SHEET OF		DRAWING NUMBER
4.4.2.74	Pin, Interlock, SSD		1 1		9236548
					NEXT HIGHER ASSEMBLY 9236546
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Large diameter (min.)		0.40%	3.2	Gage
Minor					
201	Evidence of poor workmanship		1.0%	3.3	Visual

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:04Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-F-50983B (AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 9236547
4.4.2.75	Detent, Interlock, SSD				NEXT HIGHER ASSEMBLY 9236546
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	40 lb. load on detent nib	40a	b	3.2	4.5.1.p
Minor					
201	Evidence of poor workmanship		1.0%	3.3	Visual

NOTES:
a. Destructive
b. Reject the lot if one (1) or more defective units are found.

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:04Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-F-50983B (AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 9236546
4.4.2.76	Interlock Detent Assembly, SSD				NEXT HIGHER ASSEMBLY 9236544
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	True position of interlock pin		0.40%	3.2	Gage
102	36 lb. cantilever load on pin	40a	c	3.2	4.5.1.n
103	5 lb. axial load on interlock pin	80b	d	3.2	4.5.1.o
Minor					
201	Evidence of poor workmanship		1.0%	3.3	Visual

NOTES:
a. Destructive
b. Non-destructive
c. Reject the lot if one (1) or more defective units are found.
d. Reject the lot if two (2) or more defective units are found.

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2020-10-26T04:04Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-F-50983B (AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 9236541
4.4.2.77	Shaft, Lever, SSD				NEXT HIGHER ASSEMBLY 9236540
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Pivot diameters, min.		0.40%	3.2	Gage
102	Thickness of flat section, min.		0.40%	3.2	Gage
103	Pivot lengths, max.		0.40%	3.2	Gage
Minor					
201	Evidence of poor workmanship		1.0%	3.3	Visual w/aid A

NOTES:

Source: https://nassist.dla.mil - Downloaded: 2020-10-26T04:04Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-F-50983B (AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 9236540
4.4.2.7a	Lever Assembly, SSD				NEXT HIGHER ASSEMBLY 9236526
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical					
1	5 lb. axial load on pins		100%	3.2	4.5.1.q
Major					
101	20 lb. axial unseating load on shaft	40a	b.	3.2	4.5.1.m
102	Stakes missing or insufficient		0.40%	3.2	Visual w/aid A
Minor					
201	Evidence of poor workmanship		1.0%	3.3	Visual

NOTES: a. Destructive

b. Reject the lot if one (1) or more defective units are found.

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:04Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-F-50983B (AR)

PARAGRAPH	TITLE		SHEET	OF	DRAWING NUMBER
4.4.2.79	Pinion, Escapement, SSD		1	1	9236538
					NEXT HIGHER ASSEMBLY 9236537
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Diameter of pivots, min.		0.40%	3.2	Gage
102	Pivot length, max.		0.40%	3.2	Gage
Minor					
201	Evidence of poor workmanship		1.0%	3.3	Visual w/aid B

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:04Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-F-50983B (AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 9236537
4.4.2.80	Escapement Wheel Assembly, SSD				NEXT HIGHER ASSEMBLY 9236526
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical					
1	Stakes missing or insufficient		100%	3.2	Visual w/aid A
Major					
101	10 lb. push-off load on staking	80a	b	3.2	4.5.1.1
Minor					
201	Evidence of poor workmanship		1.0%	3.3	Visual

NOTES:
a. Non-destructive
b. Reject the lot if two (2) or more defective units are found.

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:04Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-F-50983B (AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 9236535
4.4.2.81	Pinion, SSD				NEXT HIGHER ASSEMBLY 9236534
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Diameter of pivots, min.		0.40%	3.2	Gage
102	Pivot lengths, max.		0.40%	3.2	Gage
Minor					
201	Evidence of poor workmanship		1.0%	3.3	Visual w/aid A

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:04Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-F-50983B (AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 9236534
4.4.2.82	Gear and Pinion Assembly, SSD				NEXT HIGHER ASSEMBLY 9236526
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical					
1	Stakes missing or insufficient		100%	3.2	Visual w/aid A
Major					
101	12 lb. push-off on staking	80a	b	3.2	4.5.1.k
Minor					
201	Evidence of poor workmanship		1.0%	3.3	Visual

NOTES:
a. Non-destructive
b. Reject the lot if two (2) or more defective units are found.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:04Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-F-50983B (AR)

PARAGRAPH	TITLE	SHEET	DRAWING NUMBER
4.4.2.83	Shaft, Rotor, SSD	1 OF 1	9236529
			NEXT HIGHER ASSEMBLY 9236528

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Length of upper pivot, max.		0.40%	3.2	Gage
102	Length of rotor diameter and lower pivot max.		0.40%	3.2	Gage
Minor					
201	Evidence of poor workmanship		1.0%	3.3	Visual

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:04Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-F-50983B (AR)

PARAGRAPH	TITLE	SHEET	OF	DRAWING NUMBER
4.4.2.84	Rotor Assembly, SSD	1	1	9236528
				NEXT HIGHER ASSEMBLY 9236526

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Rotor lock does not return to dimension indicated after being depressed below surface "x"		0.40%	3.2	Gage
102	5 lb. push-off load on rotor weight	80a	b	3.2	4.5.1.h
103	5 lb. axial load on shaft	80a	b	3.2	4.5.1.i
104	5 lb. axial unseating load on detonator sleeve	80a	c	3.2	4.5.1.j
Minor					
201	Evidence of poor workmanship		1.0%	3.3	Visual

NOTES: a. Non-destructive
b. Reject the lot if two (2) or more defective units are found.
c. Reject the lot if one (1) or more defective units are found.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:04Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-F-50983B (AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 9236525
4.4.2.85	SSD Loaded Assembly				NEXT HIGHER ASSEMBLY 9236524
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Detonator inverted		0.40%	3.2	Visual
102	3 lb. axial unseating load on detonator	80a	b	3.2	4.5.1.g
Minor					
201	Evidence of poor workmanship		1.0%	3.3	Visual

NOTES: a. Non-destructive
b. Reject the lot if one (1) or more defective units are found.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:04Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-F-50983B (AR)

PARAGRAPH	TITLE	SHEET	OF	DRAWING NUMBER
4.4.2.86	Safe Separation Device Assembly	1	1	9236524
				NEXT HIGHER ASSEMBLY: 9236500/9236700

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical					
1	Rotor not fully detented by both detents in safe position		100%	3.2	Visual
2	Non-arming spin test	a	100%	3.9.1	4.5.5
3	Time-to-arm, min.	a	100%	3.9.1	4.5.4
Major					
101	Time-to-arm, max.	a	100%	3.9.1	4.5.4
Minor					
201	Evidence of poor workmanship		1.0%	3.3	Visual

NOTES: a. Non-destructive

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-26104:04Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-F-50983B (AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 9236518
4.4.2.87	Element, Crush				NEXT HIGHER ASSEMBLY 9236516
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Static Load Test	40a	b	3.2	4.5.1.f
Minor					
201	Evidence of poor workmanship		1.0%	3.3	Visual

NOTES:
a. Destructive
b. Reject the lot if one (1) or more defective units are found.

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:04Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-F-50983B (AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 9236516
4.4.2.88	Setting Key Assembly				NEXT HIGHER ASSEMBLY 9236500/9236700
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Crush retainer missing		0.40%	3.2	Visual
102	Crush element missing		0.40%	3.2	Manual
Minor					
201	Evidence of poor workmanship		1.0%	3.3	Visual

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:04Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-F-50983B (AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.89	Ogive				9236512
					NEXT HIGHER ASSEMBLY
					9236511
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Length between wrench slots, max.		0.40%	3.2	Gage
102	Width of wrench slots, min.		0.40%	3.2	Gage
Minor					
201	Ogive profile		1.0%	3.2	Gage
202	Evidence of poor workmanship		1.0%	3.3	Visual

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:04Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-F-50983B (AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.90	Ogive Assembly				9236511
					NEXT HIGHER ASSEMBLY
					9236500/9236700
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	65 lb. Push-Out load on window	40a	c, e	3.2	4.5.1.e
102	Air leakage	80b	d	3.15	4.5.15
Minor					
201	Evidence of poor workmanship		1.0%	3.3	Visual

NOTES:
a. Destructive
b. Non-destructive
c. Reject the lot if one (1) or more defective units are found.
d. Reject the lot if two (2) or more defective units are found.
e. Samples may be subjected to the air leak test per CD 102. Those samples passing the test may be returned to the lot.

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:04Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-F-50983B (AR)

PARAGRAPH	TITLE	SHEET	OF	DRAWING NUMBER
4.4.2.91	Body	1	1	9236509
				NEXT HIGHER ASSEMBLY: 9236500/9236700

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Major diameter of small outside thread		0.40%	3.2	Gage
102	Pitch diameter of small outside thread		0.40%	3.2	Gage
103	Major diameter of large outside thread		0.40%	3.2	Gage
104	Pitch diameter of large outside thread		0.40%	3.2	Gage
Minor					
201	Evidence of poor workmanship		1.0%	3.3	Visual

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:04Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-F-50983B (AR)

PARAGRAPH	TITLE	SHEET	DRAWING NUMBER
4.4.2.92	Plug, Body	1 OF 1	9236503
			NEXT HIGHER ASSEMBLY 9236502

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Height of minor outside diameter, max.		0.40%	3.2	Gage
Minor					
201	Evidence of poor workmanship		1.0%	3.3	Visual

NOTES:

102

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:04Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-F-50983B (AR)

PARAGRAPH	TITLE		SHEET OF	DRAWING NUMBER
4.4.2.93	Plug Assembly		1 1	9236502
				NEXT HIGHER ASSEMBLY
				9236500/9236700

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	5 lb. Push-out load on lead	80a	b	3.2	4.5.1.d
Minor					
201	Evidence of poor workmanship		1.0%	3.2	Visual

NOTES:
a. Non-destructive
b. Reject the lot if two (2) or more defective units are found.

103

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:04Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-F-50983B (AR)

PARAGRAPH	TITLE	SHEET	DRAWING NUMBER
4.4.2.94	Fuze, Mechanical Time and Superquick (Prior to Assembly into the Body)	1 OF 1	9236500/9236700
			NEXT HIGHER ASSEMBLY: Final

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical					
1	Marking missing from major flat on SSD diameter		100%	3.16	Visual
2	Marking missing from outside diameter of trigger spacer in area of setback pin cavity		100%	3.16	Visual
3	SSD interlock pin engaged in trigger release lever		100%	3.16	Visual
Major					
101	Trigger not in unfired position		100%	3.2	Visual
102	Three module assembly not keyed and locked in ogive		100%	3.2	Visual/Manual
Minor					
201	Evidence of poor workmanship		1.0%	3.3	Visual

NOTES:

104

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:04Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.95	Fuze, Mechanical Time and Superquick M577/M582				9236500/9236700
					NEXT HIGHER ASSEMBLY
					Final
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical					
1	Plug not flush to below flush with lower body		100%	3.2	Visual
Major					
101	Hairline and numbers not visible through window		0.40%	3.2	Visual
102	Setting test	80a	b	3.2	4.5.2.a
103	Fuze not on shipping position		0.40%	3.2	Visual
104	Height from bottom of fuze to bottom of ogive		0.40%	3.2	Gage
105	Adhesive missing on indicated surfaces		0.65%	3.2	Visual
Minor					
201	Evidence of poor workmanship		1.0%	3.3	Visual
202	Marking incorrect or unreadable		1.0%	3.2	Visual

NOTES:
a. Non-destructive
b. Reject the lot if two (2) or more defective units are found.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:04Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.96	Fuze, Mechanical Time and Superquick, M577/582 Destructive Lot Acceptance Tests				9236500/9236700
					NEXT HIGHER ASSEMBLY
					Final
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical					
1	Jolt and Jumble Test, MIL-STD-331, Test Nos. 101.1 and 102.1	6		3.4	4.5.16
2	Transportation Vibration Test, MIL-STD-331, Test No. 104	10		3.5	4.5.17
	Forty Foot Drop Test, MIL-STD-331, Test No. 103	5		3.6	4.5.18
4	Ballistic Impact Non-Functioning	10a		3.12.3.1	4.5.21.1
5	Premature	70b		3.12.1	4.5.1
Major					
101	Propagation Test	5		3.7	4.5.19
102	Waterproofness Test, MIL-STD-331, Test modified	4		3.8	4.5.20
103	Ballistic Impact Functioning	10		3.12.3.2	4.5.21
104	Group Reliability	50c		3.12.3.3	4.5.21
105	Estimated Percent Defective	50d		3.12.3.3	4.5.21
106	Off Times	50d		3.12.3.3	4.5.21
107	Fuze Setting	70b		3.12.2	4.5.21
108	Total Duds	60e		3.12.3	4.5.21

NOTES:
a. Transportation Vibrated fuzes from 4.4.3.2
b. Samples from 4, 103, and 104
c. Includes 10 Transportation Vibrated fuzes from 4.4.3.2
d. Samples from 104
e. Samples from 103 and 104

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:04Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-F-50983B (AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 9236484
4.4.2.97	Setting Gear and Pinion Assembly				NEXT HIGHER ASSEMBLY 9236588
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	15 lb. Push-Off load on staking	80a	b	3.2	4.5.1.c
Minor					
201	Evidence of poor workmanship		1.0%	3.3	Visual w/aid A

NOTES:
a. Non-destructive
b. Reject the lot if two (2) or more defective units are found.

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-26104:04Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-F-50983B (AR)

PARAGRAPH	TITLE	SHEET	OF	DRAWING NUMBER
4.4.2.98	Balance Wheel Assembly, Timer	1	1	9236473
				NEXT HIGHER ASSEMBLY 9236647

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	4 oz. axial push-off load on balance wheel	80a	b	3.2	4.5.1.a
102	6 lb. axial unseating load on lower hairspring pivot	40d	c	3.2	4.5.1.b
Minor					
201	Evidence of poor workmanship		1.0%	3.3	Visual

NOTES:
a. Non-Destructive
b. Reject the lot if two (2) or more defective units are found.
c. Reject the lot if one (1) or more defective units are found.
d. Destructive

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:04Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-F-50983B (AR)

PARAGRAPH	TITLE		SHEET OF	DRAWING NUMBER
4.4.2.99	Cup, Booster		1 1	8895509
				NEXT HIGHER ASSEMBLY
				9236700

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Pitch diameter of thread		0.40%	3.2	Gage
102	Minor diameter of thread		0.40%	3.2	Gage
103	Cup cracked or otherwise damaged		0.40%	3.2	Visual
104	Inside depth, max.		0.40%	3.2	Gage
105	Thickness of cup at bottom		0.40%	3.2	Gage
106	Outside diameter, max.		0.65%	3.2	Gage
Minor					
201	Evidence of poor workmanship		1.0%	3.3	Visual

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:04Z
Check the source to verify that this is the current version before use.

4.4.3 Testing

4.4.3.1 Jolt and Jumble

4.4.3.1.1 Beginning with the first lot produced and continuing until six consecutive lots have complied with the acceptance criteria specified herein, a sample of twelve (12) loaded fuze assemblies set in the shipping position shall be randomly selected from each lot and subjected to the Jolt and Jumble test specified in 4.5.16. If one or more assemblies are classed defective, the lot shall be rejected.

4.4.3.1.2 After six consecutive lots have complied with the criteria specified in 4.4.3.1.1, a sample as specified in 4.4.2.96 shall be randomly selected from each of the subsequent lots and tested as specified above. If one or more fuzes are classed defective, the lot shall be rejected and sampling and testing procedures shall revert to those specified in 4.4.3.1.1 until six additional consecutive lots have again been accepted.

4.4.3.2 Transportation Vibration. A sample of thirty-five (35) loaded fuze assemblies set in the shipping position shall be randomly selected from each lot and subjected to the Transportation Vibration test specified in 4.5.17. If any fuze is found to be defective, the lot shall be rejected. If the fuzes are not found to be defective, the remaining twenty-five (25) units shall be forwarded to the proving grounds for ballistic testing in accordance with 4.4.3.6. When the ballistic test is accomplished in accordance with 4.4.3.6.2, thirty (30) samples shall be used in lieu of thiry-five (35) with twenty (20) going to the proving grounds in lieu of twenty-five (25).

4.4.3.3 Forty (40) Foot Drop

4.4.3.3.1 Beginning with the first lot produced and continuing until three consecutive lots have complied with the acceptance criteria specified herein, a sample of ten (10) loaded fuze assemblies set in the shipping position shall be randomly selected from each lot and subjected to the Drop test specified in 4.5.18. If one or more assemblies are found to be defective, the lot shall be rejected.

4.4.3.3.2 After three consecutive lots have complied with criteria specified in 4.4.3.3.1, a sample as specified in 4.4.2.96 shall be randomly selected from each of the subsequent lots and tested as specified above. If one or more fuzes are classed defective, the lot shall be rejected and the sampling and testing procedures shall revert to those specified in 4.4.3.3.1 until three consecutive lots have again been accepted.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:04Z
Check the source to verify that this is the current version before use.

4.4.3.4 Propagation Test

4.4.3.4.1 Beginning with the first lot produced and continuing until three (3) consecutive lots have complied with the acceptance criteria specified herein, a sample of ten (10) loaded fuze assemblies shall be randomly selected and subjected to the Propagation test specified in 4.5.19. If one or more assemblies are classed defective, the lot shall be rejected.

4.4.3.4.2 After three consecutive lots have complied with the criteria specified in 4.4.3.4.1, a sample as specified in 4.4.2.96 shall be randomly selected from each of the subsequent lots and testd as specified above. If one or more fuzes are classed defective, the lot shall be rejected and sampling and testing procedures shall revert to those specified in 4.4.3.4.1 until three consecutive lots have again been accepted.

4.4.3.5 Waterproofness. From each lot produced, a sample as specified in 4.4.2.96 shall be randomly selected and subjected to the Waterproofness test specified in 4.5.20. If one or more assemblies are classed defective, the lot shall be rejected.

4.4.3.6 Proving Grounds

4.4.3.6.1 Beginning with the first article sample, following with the first lot produced and continuing until three consecutive lots have complied with the acceptance criteria specified herein, ninety (90) loaded fuze assemblies (25 of which are TV samples from 4.4.3.2) shall be randomly selected from each lot and tested as specified in 4.5.21. If one or more of the following defect criteria are found, the lot shall be rejected.

a. Premature Burst - Any premature burst (see 6.3).

b. Point Detonating Dud - More than one point detonating dud (see 6.5) in the functioning test.

c. Time Dud - More than two time duds (see 6.6) in any one phase of the temperature tests or the mechanical time test.

d. Function - Any function (see 6.4) in the non-function test.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:04Z
Check the source to verify that this is the current version before use.

e. Off Time - Any early burst off time (EOF) or more than one late burst off time (see 6.8) in the entire ballistic test.

f. Total Duds - More than four (4) duds in the entire ballistic test.

g. Setting - More than one fuze which cannot be set to the time required by the ballistic test.

h. Failure to meet the time limits in 3.12.3 by an estimated lot percent defective greater than the appropriate value given below:

SAMPLE SIZE (see 6.7)	MAXIMUM ALLOWABLE PERCENT DEFECT
10	1.300
9	1.250
8	1.189
7	1.063
20	1.335
19	1.341
18	1.279
17	1.295
16	1.319
15	1.344

4.4.3.6.2 After three consecutive lots have complied with the criteria in 4.4.3.6.1, a sample as specified in 4.4.2.96 shall be randomly selected from each subsequent lot and tested as specified in 4.5.21. If one or more of the defect criteria ini 4.4.3.6.1 are found, the lot shall be rejected and the testing and sampling procedures shall revert to those specifed in 4.4.3.6.1.

4.4.4 Inspection Equipment. The equipment required to perform the examinations and tests prescribed herein is described in the "Paragraph Reference/Inspection Method" column in the table starting with paragraph 4.4.2.1. The contractor shall submit for approval equipment designs in accordance with the terms of the contract. See Section 6 of MIL-A-48078 and Section 6 herein.

4.5 Test Methods and Procedures

a. On all tests, spins shall be applied for five (5) seconds minimum, and peak loads shall be applied for one tenth (0.10) of a second minimum, unless otherwise specified in the test. No known defective parts or assemblies shall be placed in any lot after the following tests are performed.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:04Z
Check the source to verify that this is the current version before use.

b. When more than one type of test is indicated for one part or assembly, it is not necessary to use a separate part or assembly for each type of test. The tests indicated for one drawing number may be performed on one each of every part or assembly submitted for testing in accordance with the sample size listed for the test. Thus, if Test A is performed once on each of eighty (80) samples, Test B, which requires twenty-five (25) samples, extracted from the eighty (80) may be used for Test A. In order to minimize the number of samples required and scrapped, all destructive tests indicated for one drawing number shall be performed on the same samples. Thus, if Test B above is a destructive test and another destructive test (Test C requiring twenty-five (25) samples) is to be performed, then Test C shall be performed once on each of the twenty-five (25) samples selected for Test B. Care should be exercised in the performance of tests and development of test equipment to prevent damage to other components or interfaces. Such damage may invalidate subsequent tests to be performed on the part or assembly, or may cause a non-destructive test to be, in actuality, destructive. Should any conflicts arise concerning the above, the Government technical agency shall be contacted for solution. Additional samples may be required.

4.5.1 Linear Load Test. Any assembly in which the part or assembly on which the load is applied or is intended to be tested moves, deforms, becomes loose or detaches from its mated part or assembly, shall be classed defective. Any additional defect criteria or qualifications to the above shall be stated in the Remarks column in the following table and denoted by an asterisk (*). The first item stated in the Test column is the part or assembly which is to have the load applied. The second item indicated is the assembly on which the first item is tested. The drawing for the second item (number indicated) contains the note requirement for the test. Unless otherwise noted in the table, on each test the only part or assembly that is allowed freedom of movement is the first item in the Test column and those indicated in the Load & Application column.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:04Z
Check the source to verify that this is the current version before use.

TABLE I

Test	Orientation	Load & Application	Remarks
a. Balance Wheel; Balance Wheel Assembly (dwg. 9326473 and 9236720)		4 Oz. Min., Axial Unseating as per dwg.	*Movement with respect to Balance Staff Assembly
b. Lower Hairspring Pivot Balance Wheel Assembly (dwg. 9236473 and 9236720)		6 Lb. Min., Axial Unseating as per dwg.	*End of Hairspring Pivot to Balance Staff Dimension not met
c. Setting Pinion; Setting Gear and Pinion Assembly (dwg. 9236484)		15 Lb. Min., Push-Off as per dwg.	
d. Lead; Plug Assembly (dwg. 9236502)		5 Lb. Min., Axial Push-Out as per dwg.	*Stake and Lead not flush to below flush with applicable surface.
e. Window; Ogive Assembly (dwg. 9236511)		65 Lb. Push-Out as per dwg.	
f. Crush Element (dwg. 9236518)	Element Axis aligned with direction of applied load	Load as per dwg.	*Displacement does not fall within the shaded area of the requirement chart for the applied load
g. Detonator; S.S.D. Loaded Assembly (dwg. 9236525)		3.00 + .25 Lb., Axial Unseating as per dwg.	
h. Rotor Weight; Rotor Assembly (dwg. 9236528)		5 Lb. Min., Push-Off as per dwg.	*Relative motion beteen rotor and weight
i. Rotor Shaft; Rotor Assembly (dwg. 9236528)		5 Lb. Min., Axial Load as per dwg.	*Relative motion between rotor and shaft
j. Detonator Sleeve; Rotor Assembly (dwg. 9236528)	Detonator Sleeve down under Rotor	5 Lb. Min., Axial Unseating down on Sleeve	*Relative motion between rotor and sleeve

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:04Z
Check the source to verify that this is the current version before use.

TABLE I (Cont'd)

	Test	Orientation	Load & Application	Remarks
k.	Gear; Gear and Pinion Assembly (dwg. 9236534)		12 Lb. Min., Push-Off as per dwg.	
l.	Escape Wheel; Escapement Wheel Assembly (dwg. 9236537)		10.0 Lb. Min., Push-Off as per dwg.	
m.	Shaft; Lever Assembly (dwg. 9236540)		20 Lb. Min., Axial Unseating as per dwg.	Parts may deform provided relative movement between shaft and lever does not occur
n.	Interlock Pin; Interlock Detent Assembly (dwg. 9236546)		36.0 Lb., Cantilever as per dwg.	Movement of pin with respect to detent allowed. *Detent and pin do not maintain secure engagement. Note 6 of dwg. 9236546 not met after test load is removed
o.	Interlock Pin; Interlock Detent Assembly (dwg. 9236546)	Interlock Pin down below Detent	5.0 Lb. Min., Axial Unseating down on Interlock Pin	
p.	Interlock Detent Nib; Interlock Detent (dwg. 9236547)		40 Lb. Min., as per dwg.	*Evidence of Cracking or Fracturing
q.	Pins; Lever Assembly (dwg. 9236540)		5 Lb. Min., as per dwg.	The measuring System used shall be sufficiently sensitive to discern a relative movement as small as 0.001 inch.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:04Z
Check the source to verify that this is the current version before use.

TABLE I (Cont'd)

	Test	Orientation	Load & Appliction	Remarks
r.	Detent Nib; Spin Detent (dwg. 9236550)		40 Lb. Min., as per dwg.	*Evidence of Cracking or Fracturing
s.	Detonator Holder Assembly; PD Housing Assembly (dwg. 9236560)	Detonator Holder Assembly Accessible	20.0 Lb. Min., Pull-Off and 3.0 In. - Lb. Min., Radial Torque applied to Detonator Holder Assembly	Movement of Detonator Holder Assembly in excess of drawing allowance
t.	Retaining Ring; Counter Assembly (dwg. 9236573)	Counter Base up and Washer on bottom	5 Lb. Min., Push-Off up through Wheels and Tab on Retaining Ring	
u.	Pin; Spacer Assembly (dwg. 9236604	Bottom Plate Side down	35 Lb. Min., Axial Unseating down on Pin	Both Pins
v.	Pin; Spacer Assembly (dwg. 9236604)	Bottom Plate Side up	5.0 Lb. Min., Axial Unseating down on Pin	Both Pins
w.	Firing Arm; Firing Arm Assembly (dwg. 9236609)		15 Lb. Min., Push-Off as per dwg.	
x.	Detent Lever; Detent Assembly (dwg. 9236614)		15 Lb. Min., Push-Off as per dwg.	
y.	Plate; Firing Safety Plate Assembly (dwg. 9236617)		25 Lb. Min., Push-Off as per dwg.	
z.	Lever; S.S.D. Release Assembly (dwg. 9236620)		10 Lb. Min., Push-Off as per dwg.	
aa.	Key; Sleeve Assembly (dwg. 9236630)	Either open end down	5 Lb. Min., from inside Sleeve on inserted part of the key	

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:04Z
Check the source to verify that this is the current version before use.

TABLE I (Cont'd)

Test	Orientation	Load & Application	Remarks
ab. Spin Detent Pivot Pin; Plate No. 1 Assembly (dwg. 9236635 and 9236712)		5 Lb. Min., Axial Unseating as per dwg.	Plate No. 1 Assembly less Ring Gear Assembly. *Pin end to Plate No. 1 Bottom Surface Dimension not met
ac. Bushing; Plate No. 1 Assembly (dwg. 9236635 and 9236712)		5 Lb. Min., Axial Unseating as per dwg.	Plate No. 1 Assembly less Hairspring Tube, Balance Wheel Assembly and Intermediate Support. *Bushing to Plate No. 1 Dimension not met
ad. Dowel Pins; Plate No. 1 Assembly (dwg. 9236635 and 9236712)		40 Lb. Min., Axial Unseating as per dwg.	Plate No. 1 Assembly less Ring Gear Assembly. Both Pins. *Plate No. 1 to end of Pin Dimension not met
ae. Balance Wheel, Staff and Hairspring Assembly; Plate no. 1 Assembly (dwg. 9236635 and 9236712)		6 Lb. Min., Pull-Out as per dwg. or 9 lb. min. axial load per drawing	After clamping with Outboard Support Sleeve. *Top of Balance Staff to Plate No. 1 Dimension not met
af. Pin; Setting Ring Gear Assembly (dwg. 9236640)		5.0 Lb. Min., Axial Unseating as per dwg.	*Gear to end of Pin Dimension not met

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:04Z
Check the source to verify that this is the current version before use.

TABLE I (Cont'd)

	Test	Orientation	Load & Application	Remarks
ag.	Hairspring Pivots; Balance Wheel, Staff and Hairspring Assembly (dwg. 9236647 and 9236718)	Hairspring and Pivots vertical and clamped twice around the Hairspring Diameter. One Clamp above or below the other.	9 Lb. Min., Pull-Out attached to lower Clamp	The Hairspring and Pivots shall be allowed to move axially in the Clamps. The top clamp is fixed; the lower Clamp is free to move. The Clamps shall not allow the Pivots to pass through them. *Relative movement between the pivots and the hairspring
ah.	Pins; Balance Staff and Pin Assembly (dwg. 9236648)		1.5 Lb. Min., Axial Unseating as per dwg.	*End of Pin to Balance Staff Dimension not met. Both pins
ai.	Supports and Staff Lever Assembly (dwg. 9236661)		2 Lb. Min., Push-Off as per dwg.	*Dimensions of Lever Assembly altered
aj.	Pin; Lever Staff Assembly (dwg. 9236663)		1.0 Lb. Min., Axial Unseating as per dwg.	*End of Pin to Staff Dimension not met
ak.	Pin; Pallet Support and Pin Assembly (dwg. 9236665)		3.0 Lb. Min., Push-Off as per dwg.	*End of Pin to Support Dimension not met
al.	Bearing; Plate No. 4 and Bearing Assembly (dwg. 9236668)		2 Lb. Min., Push-Off as per dwg.	*Gap between Bearing and Plate
am.	Escape Wheel; Escape Wheel and Pinion Assembly (dwg. 9236672)		10 Lb. Min., Push-Off as per dwg.	
an.	Gear; Gear No. 1 and Pinion Assembly (dwg. 9236675)		12 Lb. Min., Push-Off as per dwg.	

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:04Z
Check the source to verify that this is the current version before use.

TABLE I (Cont'd)

	Test	Orientation	Load & Application	Defect Criteria
ao.	Gear; Gear No. 2 and Pinion Assembly (dwg. 9236678)		10 Lb. Min., Push-Off as per dwg.	
ap.	Ring Gear, Support and Shaft Assembly; Timing Scroll Assembly (dwg. 9236690)		16 Lb. Min., Push-Off as per dwg.	*Scroll to Shaft Major Diameter Dimension not met
aq.	Gear; Ring Gear and Support Assembly (dwg. 9236692) Or ring gear, support and shaft assembly, timer (dwg. 9236708)	Ring Gear up above support	5 Lb. Min., Axial Pull-Off up on Ring Gear	*Top of Ring Gear to Bottom of Support Max. Dimension not met
ar.	Pivot, support and pivot assembly, timer (dwg. 9236714)		15 Lb. Min., Axial Unseating as per dwg.	

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:04Z
Check the source to verify that this is the current version before use.

4.5.2 Torque Load Tests. Any part or assembly that does not meet the requirements as stated in the following table and the indicated drawing shall be classed defective. The first item stated in the Test column is the part or assembly to which the load is applied. The second item indicated is the assembly on which the first item is tested. The drawing for the second item (number indicated) contains the note requirement for the test. Unless otherwise noted in the table, on each test the only part or assembly that is allowed freedom of movement is the first item in the Test column and those indicated in the Load & Application column.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:04Z
Check the source to verify that this is the current version before use.

TABLE II

	Test	Orientation	Load & Application	Defect Criteria
a.	Setting Test through Setting Key Assy Fuze, MT, SQ, M577/ M582 (dwg. 9236500/ 9236700	Nose up & accessible	Any applied torque as per dwg.	Fuze does not read 60.0 seconds when read to the near 0.1 seconds after torque is removed
b.	Grip Rings; Three Module Assembly (dwg. 9236569)	Grip Rings & Setting Shaft accessible	4.5 In.-Lb. Min direction of increasing time	Counter turns
c.	Grip Rings; Three Module Assembly (dwg. 9236569)	Grip Rings & Setting Shaft accessible.	9.0 + 4.0 In.-Lb. as per dwg.	Grip Rings do not slip.
d.	Ring Gear Assembly; Plate No. 1 Assembly (dwg. 9236635 and 9236712)	Hairspring Tube up above Plate No. 1	50 In.-Lb. Min., Direction arbitrary	Ring Gear Assembly moves, deforms, becomes loose or detaches from Plate No. 1 Assembly
e.	Ring Gear; Timing Scroll Assembly (dwg. 9236690)	Ring Gear side up. Scroll locked	2.0 In.-Lb. Min., on Ring Gear. Direction arbitrary	Any part of the Timing Scroll Assembly moves, deforms, becomes loose or detaches. The Main Spring and Barrel Housing is excluded from the above as per dwg.
f.	Grip rings: three module assembly (dwg. 9236569)	Grip rings accessible, Firing Arm and timing scroll area visible		Stop not encountered as per dwg. Firing arm contacts end of slot in timing scroll. Setting changes when torque is applied as per dwg
g.	Pivot, Support pivot assy. Timer (dwg. 9236714)	Support locked and pivot accessible	1.0 In.-Lb. Min. on pivot, direction arbitrary	Pivot moves, deforms, breaks or detaches.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:04Z
Check the source to verify that this is the current version before use.

4.5.3 Spring Test. Any spring which does not yield the required results as indicated in the following table and indicated drawings, shall be classed defective.

TABLE III

Part	Orientation	Initial Position	1st Position	1st Yield	2nd Position	2nd Yield
a. Setback Spring (Dwg. 9236599)	Either end up	Compressed to solid height	Compressed height of .270 In.	.127 lb. Max.	Compressed height of .390 In.	.090 Lb. Min.
b. Torsion Spring (Dwg. 9236610)	Bend End fixed and straight end Mobile	Loaded beyond Final Position	As per dwg. Final position	.15 In. - Lb. Max.	As per dwg. Initial Position	.07 In. - Lb. Min.
c. Firing Pin Spring (Dwg. 9236624)	Either end up	Compressed to solid height	Compressed height of .36 In.	9.0 Lb. Max.	Compressed height of .52 In.	3.0 Lb. Min.
d. Spring Washer (Dwg. 9236685) (Dwg. 9236707)	Either side up	Compressed height of .037 In. (0.026 In.)	Compressed height of .039 In. (0.030 In.)	70.0 Lb. Max. (110 to 140 lbs.)	Compressed height of .079 In. (0.039 In.)	23.0 Lb. Min. (80 to 110 Lb.)
e. Mainspring; Mainspring and Barrel Assembly (Dwg. 9236697)	Barrel stationary	8 1/4 turns min. toward full wind	7 3/4 ± 1/4 turns toward full wind	34 Oz. - In. Max.	3 3/4 ± 1/4 turns toward full wind	22 Oz. - In. Min.
f. Setback Spring (Dwg. 9236705)	Either End up	Compressed to solid height	Compressed to height of .270 In.	.063 - .010 Lbs.	Compressed to height of .390 In.	.044 - .010 Lbs.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:04Z
Check the source to verify that this is the current version before use.

4.5.4 Time-To-Arm, S.S.D. Assembly. The completed S.S.D. assembly in its non-armed position (see Figure 1.a) shall be placed in a suitable test fixture with the spin detents locked in place. The fixture shall rotate the S.S.D. to a speed of 1800-25 rpm and cause the release of the spin detents. The equipment shall determine that the S.S.D. has armed within the time limits specified in 3.9.1. The armed position is indicated by the presence of the detonator in the center hole (see Figure 1.c). Any assembly that does not comply with the requirements of 3.9.1 shall be classed defective as follows:

a. Critical Defect - Those units arming faster than the specified lower time limit.

b. Major Defect - Those units unarmed, partially armed (see Figure 1.b), armed after the upper time limit has been exceeded or not locked in the armed position.

All assemblies shall be returned to the non-armed position and the accepted ones shall then be subjected to the non-arming test specified in 4.5.5.

4.5.5 Non-Arming Test; S.S.D. Assembly. The S.S.D. Assemblies from the Time-To-Arm test specified in 4.5.4, in the non-armed position (see Figure 1.a), shall be placed in a suitable test fixture. The fixture shall rotate the S.S.D. to a speed of 1000 + 25 rpm. The fixture shall determine that the S.S.D. has remained in the non-armed position. The non-armed position is indicated by both detent nibs being engaged in their respective rotor slots and no evidence of the detonator in the center hole (see Figure 1.b and c). Any assembly that does not comply with the requirements of 3.9.1 shall be classed defective, Assemblies that pass this test shall have an indelible mark placed upon the major flat of the S.S.D. diameter as the S.S.D exits the equipment.

4.5.6 Two-Thousand RPM Detent Release Test; Trigger Assembly. The trigger assembly shall be placed in a suitable test fixture. The firing pin shall be in its cocked position and the firing arm assembly lever shall be restrained by the detent shaft prior to the test. The test fixture shall rotate the trigger assembly to 2000 - 25 rpm. Any trigger assembly that does not comply with the requirements of 3.9.2 shall be classed defective. Assemblies which pass this test shall then be re-cocked and subjected to the Non-Release test specified in 4.5.7.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:04Z
Check the source to verify that this is the current version before use.

4.5.7 One-Thousand RPM Detent Non-Release Test; Trigger Assembly. The trigger assemblies from the 2000 RPM Release Test specified in 4.5.6 shall be placed in a suitable test fixture. The firing pin shall be in the cocked position and the firing arm assembly lever shall be restrained by the detent shaft prior to the test. The test fixture shall rotate the trigger assembly to 1000 + 25 rpm. Any trigger assembly that does not comply with the requirements of 3.9.2 shall be classed defective.

4.5.8 Sequential Trigger Function Test; Trigger Assembly. The trigger assemblies shall be placed in a suitable test fixture with the firing pin in the cocked position and the detent assembly in the armed position. The safe separation release assembly and the safety plate assembly shall be restrained from functioning by the firing arm assembly shaft. The fixture shall hold the following pin at a radius of less than .566 inches. The fixture shall then move the following pin to the positions below and observations for compliance with 3.10.1 shall be made at each position:

a. 0.566 inch radius, max.
b. 0.596 inch radius, min.
c. 0.630 inch radius, max.
d. 0.680 inch radius, min.

Any assembly that does not comply with all of the requirements in 3.10.1 shall be classed defective. All assemblies that pass this test shall be placed in the safe and unfired position.

4.5.9 Timer Function. The timer assembly shall be placed in a suitable test fixture with the setback detent depressed in such a manner as not to interfere with the operation of the spin detent and balance wheel. The assembly shall then be rotated at a speed of 2000 - 25 rpm. The spin detent shall move, allowing the balance wheel freedom of movement. Any assembly that does not comply with the requirements specified in 3.10.2 shall be classed defective. Assemblies which pass this test shall be reset and used to conduct the Timer Non-Function test specified in 4.5.10.

4.5.10 Timer Non-Function. The timer assemblies from the Timer Function test specified in 4.5.9, with the spin detent locking the balance wheel, shall be placed in a suitable test fixture with the setback detent depressed in such a manner as not to interfere with the operation of the spin detent and balance wheel. The assembly shall

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:04Z
Check the source to verify that this is the current version before use.

then be rotated at a speed of 1000 + 25 rpm. The spin detent shall remain in position detenting the balance wheel. Any assembly that does not comply with the requirements specified in 3.10.2 shall be classed defective.

4.5.11 Setback Pin Arming Test; Timer Assembly. The timer assembly shall be placed in a suitable test fixture. A load shall be placed on the pin in a downward direction until the pin has reached its maximum depth and then unloaded to allow it to rise. Any assembly with a pin that does not comply with the requirements specified in 3.13 shall be classed defective.

4.5.12 Counter Wheel Transfer Test; Counter Assembly. The counter assembly shall be placed in a suitable test fixture. The No. 3 wheel shall be rotated in the direction of increasing time, through 200 digits and returned to the start point. Any assembly that does not comply with the requirements specified in 3.11 shall be classed defective.

4.5.13 Timer Beat Rate; Timer Assembly. The timer assembly shall be placed in a suitable test fixture. The spin detent and setback detent shall be manually subverted and the timer allowed to operate. The fixture shall record the beat rate and amplitude of the balance wheel in the timer over a time duration of 50+10 sec. Any assembly that does not comply with the requirements specified in 3.14 shall be classed defective. Assemblies which pass the test shall be returned to the non-function position.

4.5.14 Trigger Setback Pin Arming Test; Three Module Assembly. The inert three module assembly, less the grease in the setback detent cavity, shall be placed in a suitable test fixture with the setback detent in the trigger assembly in an accessible position. A load shall be placed on the setback pin in the direction shown by the arrow on the drawing. The detent pin shall be depressed flush to below flush with the applicable surface indicated on the drawing and allowed to return to its original position when the load is removed. Any assembly in which the pin does not comply with the requirements of 3.13 shall be classed defective. All assemblies which pass this test shall have an indelible mark signifying acceptance placed on the outside diameter of the trigger spacer in the area of the setback pin cavity as the part exits the equipment.

4.5.15 Air Leakage; Ogive Assembly with Setting Key, Setting Key Ring and Applicable Grease. The ogive assembly shall be placed in a

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:04Z
Check the source to verify that this is the current version before use.

suitable test fixture that will keep the setting key in a position that simulates its normal position in a fuze during the test operation. The assembly, with the body opening sealed, shall be evacuated to a vacuum pressure of 20 inches Hg min., and recorded. The assembly shall be held in an evacuated state for one minute. Those assemblies which do not meet the requirements of 3.15 shall be classed defective.

4.5.16 Jolt and Jumble Test. The loaded fuze assemblies shall be subjected to the Jolt test in accordance with MIL-STD-331, Test 101.1. Immediately following the completion of the Jolt test, the fuzes shall be subjected to the Jumble test in accordance with MIL-STD-331, Test 102.1. After the Jumble test, the fuzes shall be disassembled to determine compliance with MIL-STD-331. As a minimum inspection requirement, the following criteria shall be used:

a. No part of the explosive train has functioned.

b. The rotor in the safe separation device shall be located and locked in the safe position by both spin detents (see Figure 1.a).

c. The setback and spin detents in the trigger shall be secure and in the safe position (see Figure 2).

d. The safe separation device spin detent shall not be broken and the interlock pin shall be secure and restrained by the release lever in the trigger.

e. The trigger firing arm assembly shall be secure and in the safe position and shall restrain the release lever (see Figure 2).

Any fuze that does not comply with the requirements of 3.4 and the defect criteria stated herein, shall be classed defective.

4.5.17 Transportation Vibration Test. The loaded fuze assemblies shall be subjected to the Transportation Vibration test in accordance with MIL-STD-331, Test 104, Procedure 2. After this test, ten (10) fuzes from the sample shall be randomly selected and disassembled to determine that the fuze is safe. As a minimum inspection requirement, the criteria in 4.5.16 shall be used. Any fuze that does not comply with the requirements of 3.5 or the criteria referenced herein, shall be classed defective.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:04Z
Check the source to verify that this is the current version before use.

4.5.18 Forty Foot Drop Test. The loaded fuze assemblies shall be assembled to inert loaded 105MM, M1 projectiles and subjected to the Forty (40) Foot Drop test in accordance with MIL-STD-331, Test 103. After this test, the fuzes shall be disassembled to determine compliance with 3.6. As a minimum inspection requirement, the criteria of 4.5.16 shall be used except requirement "a". Requirement "a" for this test is that the output lead shall not function. A record shall be kept of whether the rotor detonator functions. Any assembly that does not comply with the requirements of 3.6 or the criteria referenced herein, shall be classed defective.

4.5.19 Propagation Test. The selected loaded fuze assemblies shall be set for PD functioning and the safe separation device shall be manually pre-armed. The fuze shall then be placed on a block large enough to cover completely the base of the fuze. The fuze shall then be impact detonated by crushing the PD element in the nose of the fuze by dropping a 5.0 pound weight on the setting key from 3.0 feet above the fuze. Any fuze that does not comply with the requirements of 3.7 shall be classed defective. A function is determined by visual observation for complete detonation of the Lead. Defective assemblies shall be examined and the cause of failure noted on the inspection records of the lot.

4.5.20 Waterproofness. The loaded fuze assemblies shall be subjected to the waterproofness test in accordance with MIL-STD-331, Test 108, except as provided in paragraph 3.8. After this test, the fuzes shall be disassembled and examined under the ultra-violet light to determine compliance with 3.8. Any assembly that does not comply with the requirements specified in 3.8 shall be classified defective.

4.5.21 Proving Grounds. The fuze assemblies used in the following tests shall be fired with booster pellets (dwg. 8595510) and booster cups (dwg. 8595509) as indicated in Table IV and the applicable following paragraph after being assembled to the projectile indicated.

4.5.21.1 Impact Non-Function Distance. The T.V. preconditioned fuzes shall be fired at a 2 inch thick plywood screen adequately supported and placed 150 - 5 feet away from the muzzle of the weapon. Any fuze that does not comply with the requirements of 3.12.3.1 shall be classed premature (see 6.3). Observation of impact non-functioning is required and shall be noted on the ballistic records.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:04Z
Check the source to verify that this is the current version before use.

TABLE IV

TEST	WEAPON	TUBE	PROJECTILE	CHARGE ZONE	SETTING	TEMPERATURE	SAMPLE[a] SIZE	SAMPLE[b] SIZE
Non-Function[e]	105MM	M103	M1	7	PD	70°±10F	15[c]	10[c]
Function[e]	155MM	M1	M107	1	PD	70°±10°F	15	10
Mechanical Time[d]	155MM	M185	M107	8	50.0 Sec.	70°±10°F	10[c]	10[c]
	155MM	M185	M107	8	75.0 Sec.	70°±10°F	10	10
	105MM	M103	M1	7	50.0 Sec.	70°±10°F	10	20
	8 Inch	M2	M106	1	15.0 Sec.	70°±10°F	10	
Extreme Temperature[d]	105MM	M103	M1	7	50.0 Sec.	+145°F	10	-
	8 Inch	M2	M106	1	25.0 Sec.	-35°F	10	10

NOTES

a. For First Article and three consecutive acceptable lots (See 4.4.3.6.1).

b. For subsequent lots after "a" above (See 4.4.3.6.2).

c. Transportation Vibration samples.

d. The Quadrant Elevation (QE0 and Height of Burst (HOB) shall be as specified in 6.10. All rounds fired shall use Spotting Charge, Model APG-2 (9297939).

e. The Spotting Charge above shall not be used.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:04Z
Check the source to verify that this is the current version before use.

4.5.21.2 Impact Function Distance. The fuzes shall be fired at a 2 inch thick plywood screen adequately supported and placed 820 - 5 feet away from the muzzle of the gun. Any fuze which does not comply with the requirements of 3.12.3.2 shall be classed a point detonating dud (see 6.5). Appropriate coverage shall be required on this test. Any fuze functioning beyond the screen shall be referred to DRSAR-QAM. Observation of impact functioning and non-functioning is required and shall be noted on the ballistic records.

4.5.21.3 Mechanical Time function. The fuze assembly shall be set and fired for airburst functioning. Three independent infrared sensing chronograph systems will be used to measure time to burst. The times shall be recorded from the chronograph counters to four decimal places. The three recorded time values for each round are averaged and the average is rounded to the nearest 0.001 second using the method prescribed by the American Society for Testing Materials and recorded. If one time value is lost or is determined to be invalid (see 4.5.21.3.1), the remaining two values are used. If a round fails to function in flight, observations shall be made to determine if the round functions on impact. All defects shall be recorded. A back-up system of electric clocks or stopwatches shall also be employed and their measurements recorded to the nearest 0.01 second; these times will not be used in computations. Any fuze which does not airburst function shall be classed a time dud (see 6.6).

4.5.21.3.1 Lost Time. When a fuze is fired for an airburst function and is observed to have functioned, but a chronograph system used to determine the elapsed time to function fails for any reason to record the appropriate value, then an entry of lost time shall be used instead of any recorded value. The round shall be considered lost when the above occurs for 2 or more chronograph systems. When any chronograph reading differs by more than ten (10) milliseconds from another chronograph reading, which is the closest of the remaining two to the first reading, the first reading shall be considered lost. The other two readings shall be averaged. When no two readings agree, then all readings shall be considered lost.

4.5.21.3.2 Lot Percent Defective. The time values obtained by the chronograph systems shall be used to calculate the estimate of lot percent defective. Where at least two chronograph systems provide a time value, the average shall be taken as the individual fuze value. The estimate of the lot percent defective shall be calculated using the method prescribed in MIL-STD-414, Example B3. For sample sizes 8 through 9 and 16 through 19 the estimated lot percent defective value shall be determined by interpolation between the values given in Table B5, MIL-STD-414 for sample sizes 7 and 10 and 15 and 20, respectively.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:04Z
Check the source to verify that this is the current version before use.

All appropriate time values obtained for each airburst functioning phases shall be used in the initial calculation of the sample mean ($\bar{x}$) and standard deviation (s).

4.5.21.3.3 Off Time (see 6.8). When the fuzes in a test group are fired for air-burst functioning and the elapsed times to function are greater than the time expressed by t - (4 + .06t), where t is set time, then the following table shall be used to determine off times:

Setting (Sec.)	Early Off Time (Sec.)	Late Off Time (Sec.)
15	14.00 or less	16.00 or more
25	23.50 or less	26.50 or more
50	47.50 or less	52.50 or more
75	72.00 or less	78.00 or more

When an off time is recorded on the ballistic records, it shall be annotated as EOF for an early burst off time or LOF for a late burst off time.

4.5.21.3.4 Outliers (See 6.9). When the estimated percent defective is not within the specified limits, a search for outliers should be made. The averaged chronograph readings less off times should be arranged in ascending or descending order and the suspect value (either the highest) (X_n) or lowest (X_1) chosen. The values should then be operated by the following appropriate formula to determine the outlier statistic:

Sample Size	Suspect Value: Highest	Suspect Value: Lowest
7	$(X_n - X_{n-1})/(X_n - X_1)$	$(X_2 - X_1)/(X_n - X_1)$
8 - 10	$(X_n - X_{n-1})/(X_n - X_2)$	$(X_2 - X_1)/(X_{n-1} - X_1)$
15 - 20	$(X_n - X_{n-2})/(X_n - X_3)$	$(X_3 - X_1)/(X_{n-2} - X_1)$

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:04Z
Check the source to verify that this is the current version before use.

If the value obtained from the appropriate formula above is greater than the appropriate value in Table V and the suspect value falls outside the function time limits, then the suspect value can be considered an outlier and eliminated.

TABLE V

N	MAXIMUM ALLOWABLE OUTLIER STATISTIC
7	.507
8	.554
9	.512
10	.477
15	.525
16	.507
17	.490
18	.475
19	.462
20	.450

If the value obtained from the appropriate formula is less than or equal to, the appropriate value in Table V, then the value shall be retained. If either the highest or lowest value is chosen as the suspect value and found not to be an outlier, then the other value may be tested. If the other value is found to be an outlier, then it may be rejected. There shall be only one outlier rejected per test group, with an allowable total of three (3) in the entire ballistic test. After the outlier is rejected, a new mean time and standard deviation shall be calculated. The new values shall comply with the requirements stated in 3.12.3.

4.5.21.4 Extreme Temperature. The temperature conditioned fuze assembly shall be set and fired for airburst functioning. Data shall be accumulated as specified in 4.5.21.3 The requirements of 3.12.3.4 apply.

4.5.21.4.1 Temperature Condition. The round with the fuze assembled to it shall be placed in a temperature conditioning chamber. With the round in the chamber, start the test at ambient temperature. The chamber shall then be maintained at no less than 97% of either of the specified temperature extremes (as applicable) until a steady-state condition exists. After a steady-state temperature condition is reached, the fuze shall be saturated for twenty-four (24) hours minimum at that temperature.

4.5.21.5 Dud Recovery. For informational purposes only, efforts shall be made to recover all duds encountered during the ballistic test excluding those fuzes fired in the non-function test. These recovered fuzes are to be held for analysis by ARRADCOM.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:04Z
Check the source to verify that this is the current version before use.

5. PREPARATION FOR DELIVERY

5.1 Packaging, Packing and Marking. Packaging, packing and marking shall be in accordance with the requirements and inspection procedures specified in MIL-P-60412, except that the air leakage test (Para. 4.3.1) will not be performed.

5.2 Automated (Mechanized) Marking of S.S.D's and Three Module Assemblies. The S.S.D. and Three Module Assembly, upon exiting the test equipment, shall be indelibly marked as specified in 4.5.5 and 4.5.14.

6. NOTES

6.1 Ordering Data. See MIL-A-48078

6.2 Inspection Equipment Designs. See MIL-A-48078 (PA). Required equipment designs shall be submitted for approval to US Army Armament Research and Development Command; ATTN: DRDAR-QAR-I, Dover, New Jersey 07801.

6.3 Premature Burst. A malfunction in which a fuze functions before safe separation. In the Point Detonating (PD) mode, safe separation is defined by the minimum arming distance per 3.12.3.1. In the Mechanical Time (MT) mode, safe separation is defined by the equation t - (4 + 0.06t.) where t is the set time.

6.4 Ballistic Function. A function is evidenced by the detonation of the projectile specified in 4.5.21.

6.5 Point Detonating Dud. A fuze which does not function on impact when intended. A point detonating setting is indicated by a counter position of◀98.

6.6 Time Dud. When a fuze is set to function in air and fails to function as intended, it shall be considered a time dud. This is independent of whether or not the fuze functions upon subsequent impact.

6.7 Required Number of Data Points. The number of readings (N) to be used as a basis for the estimated percent defective shall be no less than fifteen (15) for a sample group of twenty (20) or seven (7) for a sample group of ten (10). The number of readings used as a basis shall exclude time duds, off times, outliers and lost times. If there are insufficient rounds in any group, it is the Government's option to require additional rounds to be fired under the conditions of the group, until sufficient in accordance with the above.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:04Z
Check the source to verify that this is the current version before use.

6.8 Off Time. A fuze function time which has a high probability of falling outside the sample population limits, thereby reducing the effectiveness of group functioning.

6.9 Outlier. An outlier is a fuze whose averaged chronograph reading does not fall within the fuze function time limits and is statistically different from the other values of the sample.

6.10 QE and HOB. The QE and HOB to be used in the Ballistic test shall fall within the following ranges for the applicable weapon system:

Weapon	Zone	Setting	QE (mils)	HOB (meters)
105MM, M103	7	50.0	800-1000	600-2600
155MM, M185	8	50.0	600- 800	950-4100
155MM, M185	8	75.0	1000-1200	1200-3900
8 Inch, M2	1	15.0	600- 800	900-1500
8 Inch, M2	1	25.0	700- 800	750-1200

6.11 The figures presented in this specification are for use as pictorial aids; they are not to be construed as representing contractual, rigid configurations.

6.12 Inspections w/aid. Aid is defined as specified below. Where surface finishes are to be inspected, the gage used for surface comparisons shall be viewed under the same magnification as the sample being inspected.

a. Aid A - 3X

b. Aid B - 5X

c. Aid C - 7X

6.13 Submission of First Article Samples. Instructions as to the location for the evaluation of first article samples shall be obtained from the Contracting Officer. Upon receipt of such request, the Contracting Officer shall advise US Army Armament Research and Development and instructions will be issued accordingly. All enquiries shall be forwarded to: Commander, US Army Armament Research and Development Command, ATTN: DRDAR-QAM-Q Dover, NJ 07801

Custodian:
Army-AR

Preparing Activity:
Army-AR

Project Number: 1390-A243

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:04Z
Check the source to verify that this is the current version before use.

STANDARDIZATION DOCUMENT IMPROVEMENT PROPOSAL

INSTRUCTIONS: This form is provided to solicit beneficial comments which may improve this document and enhance its use. DoD contractors, government activities, manufacturers, vendors, or other prospective users of the document are invited to submit comments to the government. Fold on lines on reverse side, staple in corner, and send to preparing activity. Attach any pertinent data which may be of use in improving this document. If there are additional papers, attach to form and place both in an envelope addressed to preparing activity. A response will be provided to the submitter, when name and address is provided, within 30 days indicating that the 1426 was received and when any appropriate action on it will be completed.
NOTE: This form shall not be used to submit requests for waivers, deviations or clarification of specification requirements on current contracts. Comments submitted on this form do not constitute or imply authorization to waive any portion of the referenced document(s) or to amend contractual requirements.

DOCUMENT IDENTIFIER *(Number)* AND TITLE
MIL-F-50983B Fuze, MT, SQ, M577 LAP & Metal Parts Fuze, MT, SQ, M582 Metal Parts

NAME OF ORGANIZATION AND ADDRESS OF SUBMITTER

☐ VENDOR ☐ USER ☐ MANUFACTURER

1. ☐ HAS ANY PART OF THE DOCUMENT CREATED PROBLEMS OR REQUIRED INTERPRETATION IN PROCUREMENT USE? ☐ IS ANY PART OF IT TOO RIGID, RESTRICTIVE, LOOSE OR AMBIGUOUS? PLEASE EXPLAIN BELOW.

A. GIVE PARAGRAPH NUMBER AND WORDING

B. RECOMMENDED WORDING CHANGE

C. REASON FOR RECOMMENDED CHANGE(S)

2. REMARKS

SUBMITTED BY *(Printed or typed name and address — Optional)*	TELEPHONE NO.
	DATE

DD FORM 1 OCT 76 1426 EDITION OF 1 JAN 72 WILL BE USED UNTIL EXHAUSTED.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:04Z
Check the source to verify that this is the current version before use.