MIL-T-43309C
15 February 1979
SUPERSEDING
MIL-T-43309B
4 June 1973

MILITARY SPECIFICATION

TARPAULIN: COTTON DUCK, FOR WIND MEASURING SET

This specification is approved for use by all Departments and Agencies of the Department of Defense.

1. SCOPE

1.1 Scope. This specification covers a tarpaulin fabricated from cotton duck. The tarpaulin is provided with tie-down cords for securing to the trailer (see 6.1).

2. APPLICABLE DOCUMENTS

* 2.1 Issues of documents. The following documents of the issue in effect on date of invitation for bids or request for proposal, form a part of this specification to the extent specified herein:

SPECIFICATIONS

FEDERAL

T-C-571	-	Cords, Cotton; General and Special Purpose, Sash and Venetian Blind
V-T-285	-	Thread, Polyester
KK-L-154	-	Leather, Cattlehide, (Bag and Case)
TT-P-595	-	Preservation Coating, Canvas

Beneficial comments (recommendations, additions, deletions) and any pertinent data which may be of use in improving this document should be addressed to: US Army Natick Research and Development Command, Natick, MA 01760 by using the self-addressed Standardization Document Improvement Proposal (DD Form 1426) appearing at the end of this document or by letter.

FSC 8340

Source: https://assist.dla.mil -- Downloaded: 2026-10-21T21:08Z
Check the source to verify that this is the current version before use.

UU-P-268	-	Paper, Kraft, Wrapping
CCC-C-419	-	Cloth, Duck, Cotton, Unbleached, Plied-Yarns, Army and Numbered
CCC-D-950	-	Dyeing and Aftertreating Processes for Cotton Cloths
DDD-L-20	-	Label, For Clothing, Equipage, and Tentage, (General Use)
PPP-B-636	-	Boxes, Shipping, Fiberboard

MILITARY

MIL-C-496	-	Clips, End, Strap
MIL-W-530	-	Webbing, Textile, Cotton, General Purpose, Natural or in Colors
MIL-L-1709	-	Lines, Tent
MIL-H-9890	-	Hardware, Individual Load Carrying Equipment; and Hardware, Miscellaneous
MIL-G-16491	-	Grommet, Metallic
MIL-T-43566	-	Tape, Textile, Cotton, General Purpose, Natural or in Colors

STANDARDS

FEDERAL

FED-STD-751	-	Stitches, Seams, and Stitchings

MILITARY

MIL-STD-105	-	Sampling Procedures and Tables for Inspection by Attributes
MIL-STD-129	-	Marking for Shipment and Storage

DRAWINGS

US ARMY NATICK RESEARCH AND DEVELOPMENT COMMAND

5-10-38	-	Tarpaulin, Cotton Duck, For Wind Measuring Set; Assembly and Views
5-10-39	-	Sections and Details

Source: https://assist.dla.mil -- Downloaded: 2026-10-21T21:08Z
Check the source to verify that this is the current version before use.

LAWS AND REGULATIONS

Department of the Army Field Manual FM 10-16 - General Repair for Tents, Canvas, and Webbing

(Copies of specifications, standards, drawings and publications required by contractors in connection with specific procurement functions should be obtained from the procuring activity or as directed by the contracting officer.)

2.2 Other publications. The following documents form a part of this specification to the extent specified herein. Unless otherwise indicated, the issue in effect on date of invitation for bids or request for proposal shall apply:

NATIONAL MOTOR FREIGHT TRAFFIC ASSOCIATION, INC., AGENT

National Motor Freight Classification

(Application for copies should be addressed to the American Trucking Associations, Inc., Traffic Department, 1616 P Street, N.W., Washington, DC 20036.)

UNIFORM CLASSIFICATION COMMITTEE, AGENT

Uniform Freight Classification

(Application for copies should be addressed to the Uniform Classification Committee, Room 1106, 222 South Riverside Plaza, Chicago, IL 60606.)

(Technical society and technical association specifications and standards are generally available for reference from libraries. They are also distributed among technical groups and using Federal agencies.)

3. REQUIREMENTS

3.1 First article. When specified (see 6.2), the contractor shall furnish a sample for first article inspection and approval (see 4.3 and 6.4).

3.2 Materials and components (see 6.6).

3.2.1 Cloth, duck, cotton. The cloth for the tarpaulin shall be No. 8 hard texture, conforming to type I of CCC-C-419.

Source: https://assist.dla.mil -- Downloaded: 2026-10-21T21:08Z
Check the source to verify that this is the current version before use.

3.2.1.1 Color and treatment. The cotton duck shall be olive drab shade No. 7 and conform to type I, class B of CCC-D-950.

3.2.2 Webbing, textile, cotton. The webbing for the web strap shall be olive drab shade No. 7 and conform to type IIb, class 4, 5/8-inch (16 mm) width of MIL-W-530.

3.2.3 Tape, textile, cotton. The binding tape shall be olive drab shade No. 7 and conform to type I, class 4, 3/4-inch (19 mm) width of MIL-T-43566.

3.2.4 Thread, polyester. The thread shall conform to type I, class 1, subclass B, shade S-1 (CA 66022) of V-T-285. The dyed thread shall show fastness to weathering equal to or better than the standard shade sample (see 6.3). If no standard shade sample is available, the dyed thread shall show good fastness to weathering. Thread sizes shall be as follows:

For all stitching, except stitching indicated by "Z" on drawings	..	Size FF for needle and bobbin
For stitching indicated by "Z" on drawings	-	Size FF for needle, size F for looper

3.2.5 Cord, cotton, braided. The tie-down cord shall conform to type I, class 3, size No. 7 of T-C-571. The color shall be olive drab shade No. 7 prior to mildew-resistant treatment and the shade imparted by the mildew-resistant treatment will be acceptable.

3.2.6 Leather, cattlehide. The leather for the cap and reinforcements shall conform to type II, class 1, style A, B or C, smooth finish, color natural (as produced by the tanning agents), 8 ounce of KK-L-154.

3.2.7 Buckle, tongueless. The buckle shall conform to type XII, class A of MIL-H-9890.

3.2.8 Clip, end, strap. The web strap end clip shall conform to type I, class 1 or 2, size 5/8-inch (16 mm) of MIL-C-496.

3.2.9 Grommet, metallic. The grommets shall conform to type III, class 3, size No. 3 of MIL-G-16491.

3.3 Construction. The construction of the tarpaulin shall conform to the drawings listed in section 2 and as specified herein.

Source: https://assist.dla.mil -- Downloaded: 2026-10-21T21:08Z
Check the source to verify that this is the current version before use.

3.3.1 Stitches, seams, and stitchings.

3.3.1.1 Types of stitching. Stitching shall conform to FED-STD-751 as follows:

For all stitching, except stitching indicated by "Z" on drawings	- Type 301, 5 to 7 stitches per inch (2 to 3 stitches/cm)
For stitching indicated by "Z" on drawings	- Type 401, 5 to 7 stitches per inch (2 to 3 stitches/cm) - Chain portion of stitching shall not appear on outside of tarpaulin

3.3.1.2 Thread breaks. Thread breaks in stitching shall be overstitched not less than 1 inch (25 mm) at each break on type 301 stitching and not less than 1-1/2 inches (38 mm) at each break on type 401 stitching. Thread breaks in type 401 stitching may be overstitched with type 301 stitching. Thread breaks noted during inspection shall be repaired by overstitching the existing stitching for a distance of 1 inch (25 mm) on both sides of the break. The ends of repair stitching are not required to be backstitched.

3.3.1.3 Stitching ends, type 301. The ends of type 301 stitching shall be overstitched not less than 1 inch (25 mm) except where ends are turned under in a hem or held down by other stitching. Where stitching is performed automatically, stitch patterns such as box, box with cross-stitch, "W" stitching or straight line tacking, 3 or more tying, overlapping or backstitches shall be used to secure the ends of stitching.

3.3.1.4 Skipped stitches. Skipped stitches in type 401 stitching shall be overstitched not less than 1-1/2 inches (38 mm) and not less than 1 inch (25 mm) where 3 or more consecutively skipped stitches occur on type 301 stitching. Skipped stitches in 401 stitching may be overstitched with 301 stitching.

* 3.3.1.5 Lubrication of thread. The addition of any lubricant to the polyester thread prior to or during the sewing operations is prohibited.

* 3.3.1.6 Stitching margin. All stitching margins shall be 1/8 $\pm$ 1/16 inch (3 $\pm$ 2 mm).

* 3.3.2 Tie-down cord ends. The ends of the tie-down cords shall be machine-served in conformance with MIL-L-1709.

Source: https://assist.dla.mil -- Downloaded: 2026-10-21T21:08Z
Check the source to verify that this is the current version before use.

3.3.3 Setting of grommets. Holes punched to receive the grommets shall be smaller than the outside diameter of the grommet barrel so that the barrel must be forced through the hole. The grommets shall be securely clinched without cutting the materials.

3.3.4 Setting of end clips. The webbing shall be inserted the full depth of the clips. The clips shall be securely attached without cutting the webbing and the webbing shall be flat at the point of entrance.

* 3.3.5 Wicking of sewing thread (cup test). There shall be no seepage of water through the tarpaulin stitching when tested as specified in 4.4.3.3. The cup test is intended to insure that nonwicking thread has been utilized and that no lubrication has been added to the thread during the sewing operation.

* 3.3.6 Repairs. Repairs, whenever necessary, and when authorized by the contracting officer, shall be effected in accordance with Department of the Army Field Manual 10-16 except that handsewn patches or cemented patches will not be acceptable. Repairs required as a result of failure of the cup test, and when authorized by the contracting officer, shall be performed by treating with a compound conforming to type I, class 1 of TT-P-595 prior to retesting (see 6.5).

* 3.4 Marking. All markings and labels shall conform to DDD-L-20. The letters "US" on the tarpaulin shall conform to type IV, class 9 in the size characters and in the location shown on the drawing. Class 9 markings shall be clearly legible after subjection to accelerated weathering.

3.4.1 Identification label. The identification marking shall conform to type III or IV, class 8 and shall be located as indicated on the drawing.

* 3.5 Workmanship. Cloth components shall be clean and free of holes, cuts, tears or cloth defects such as multiple floats, or broken or missing yarns. Webbing and tapes shall contain no frayed or scalloped edges and cord components shall be free of cuts or abrasions. Thread tension shall be maintained with seam properly sewed so that no runoffs, twists, pleats, or open seams shall result. Care shall be taken in sewing to see that no needle chews occur. All thread ends shall be trimmed to 1/2 inch (13 mm) or less. Metal components shall be free of burrs, sharp edges or corroded areas and shall not be broken or malformed.

4. QUALITY ASSURANCE PROVISIONS

* 4.1 Responsibility for inspection. Unless otherwise specified in the contract, the contractor is responsible for the performance of all inspection requirements as specified herein. Except as otherwise specified in the

Source: https://assist.dla.mil -- Downloaded: 2026-10-21T21:08Z
Check the source to verify that this is the current version before use.

contract, the contractor may use his own or any other facilities suitable for the performance of the inspection requirements specified herein, unless disapproved by the Government. The Government reserves the right to perform any of the inspections set forth in the specification where such inspections are deemed necessary to assure supplies and services conform to prescribed requirements.

4.2 Classification of inspection. The inspection requirements specified herein are classified as follows:

1. First article inspection (see 4.3).
2. Quality conformance inspection (see 4.4).

4.3 First article inspection. When a first article is required, it shall be examined for the defects listed in tables I and II and tested as specified in 4.5. Any visual defect, any dimension not within the specified requirements, or failure to conform to the test requirements, shall be cause for rejection of the first article.

4.4 Quality conformance inspection. Except as otherwise specified herein, sampling for inspection shall be made in accordance with MIL-STD-105.

4.4.1 Component and material inspection. In accordance with 4.1, components and materials shall be inspected in accordance with all the requirements of referenced specifications, drawings and standards unless otherwise excluded, amended, modified or qualified in this specification or applicable purchase document.

* 4.4.2 In-process inspection. Inspection shall be made of the following fabrication processes to establish conformance with specified requirements.

a. There shall be no lubrication of polyester thread prior to or during the sewing operation for compliance with 3.3.1.5.

b. Holes punched to receive grommets are in compliance with 3.3.3.

Whenever nonconformance is noted, correction shall be made to the items affected and the process.

4.4.3 End item inspection. The lot shall consist of all completely fabricated tarpaulins offered for inspection at one time. The sample unit shall be one completely fabricated tarpaulin.

Source: https://assist.dla.mil -- Downloaded: 202610-21T21:08Z
Check the source to verify that this is the current version before use.

* 4.4.3.1 Visual examination. The tarpaulins shall be examined for defects in table I. The inspection level shall be II and the acceptable quality levels (AQLs) expressed in terms of defects per hundred units shall be 6.5 for major defects, 15.0 for major and minor A defects combined and 25.0 for major, minor A and B defects combined.

TABLE I. Classification of defects for visual characteristics

Examine	Defect	Classification Major	Minor A	Minor B
Cloth	Cut, tear or hole:			
	- greater than 1/8 inch (3 mm) in length or diameter	X		
	- greater than 3/32 inch (2 mm) but not greater than 1/8 inch (3 mm) in length or diameter		X	
	- more than 5 holes 3/32 inch (2 mm) or less in length or diameter			X
	- broken or missing yarns, multiple floats clearly visible at normal inspection distance, approximately 3 feet (1 m)		X	
Webbing and tape	Edge frayed or scalloped			X
Tie-down cord	Cut or abraded		X	
	Free end of cord not finished as specified			X
Leather components	Cut, tear or hole; brand, grub hole, open scratch, or deep wrinkle:			
	- on reinforcements		X	
	- on throat cap	X		
Hardware	Broken	X		
	Malformed:			
	- fails to perform intended function	X		
	- but will perform intended function		X	
	Corroded area		X	
	Burr or sharp edge which may cause injury or damage to cloth	X		

Source: https://assist.dla.mil -- Downloaded: 2026-10-21T21:08Z
Check the source to verify that this is the current version before use.

TABLE I. Classification of defects for visual characteristics (cont'd)

Examine	Defect	Classification Major	Minor A	Minor B
Grommets	Improperly set; two or more teeth exposed			X
	Clinched loosely allowing grommet to rotate in hole			X
	Clinched excessively tight, cutting fabric or insecurely clinched, i.e., grommet or washer become disengaged	X		
End clips	Improperly clinched, i.e., webbing not flat at point of entrance into clip			X
	Clip will not pass through opening in buckle		X	
	Clinched excessively tight, cutting webbing or loosely clinched, i.e., clip becomes disengaged from webbing	X		
Seams and stitching	Open seams on stitch type 301:			
	- more than 1/4 inch (6 mm), but not more than 1 inch (25 mm)			X
	- more than 1 inch (25 mm)		X	
	Open seams on stitch type 401:			
	- one row open for 1 inch (25 mm) or less			X
	- one row open for more than 1 inch (25 mm)		X	
	- both rows open (not necessarily at same location)	X		
	NOTE: A seam shall be classified as open when one or more stitches joining a seam are broken or when one or more skipped or run-off stitches occur. On double stitched seams, a seam shall be considered as open when either one or both sides of a seam are open.			

Source: https://assist.dla.mil -- Downloaded: 2026-10-21T21:08Z
Check the source to verify that this is the current version before use.

TABLE I. Classification of defects for visual characteristics (cont'd)

Examine	Defect	Classification Major	Minor A	Minor B
Seams and stitching (cont'd)	Thread breaks:			
	- overstitched less than 1 inch (25 mm) on stitch type 301			X
	- overstitched less than 1-1/2 inches (38 mm) on stitch type 401			X
	NOTE: Thread breaks not overstitched shall be classified as open seams.			
	Skipped stitches overstitched:			
	- less than 1 inch (25 mm) on stitch type 301 (where 3 or more stitches are skipped consecutively)			X
	- less than 1-1/2 inches (38 mm) on stitch type 401			X
	NOTE: Skipped stitches not overstitched shall be classified as open seams. Needle chews resulting in cut, tear or hole (see cut, tear or hole).			
Seam and stitch type	One or more required rows of stitching omitted (except on boxstitching)	X		
	Wrong seam or stitch type	X		
Stitch tension	Loose, resulting in an exposed bobbin or top thread for more than 6 inches (152 mm)		X	
	Tight, as evidenced by puckering on seams for more than 6 inches (152 mm)		X	

Source: https://assist.dla.mil -- Downloaded: 2026-10-21T21:08Z
Check the source to verify that this is the current version before use.

TABLE I. Classification of defects for visual characteristics (cont'd)

Examine	Defect	Classification Major	Minor A	Minor B
Stitches per inch	Less than minimum specified:			
	- one stitch			X
	- two or more stitches		X	
	One or more stitches in excess of maximum specified			X
	NOTE: Variation in the number of stitches per inch (stitches/cm), caused by the operator's speeding up the machine and pulling the fabric in order to sew over heavy places or heavy seams or in turning corners, shall be classified as follows:			
	a. Within the minor "B" defect classification - no defect			
	b. Within the minor "A" defect classification - minor "B" defect			
Stitching gage	Not as specified		X	
	NOTE: Applicable when double needle machine is used. When two rows of stitching are applied with a single needle machine, tolerance for stitching margin shall apply.			
Stitching margin	Larger than specified by more than 3/16 inch (5 mm):			
	- for 2 inches (51 mm) but not more than 4 inches (102 mm) in length			X

Source: https://assist.dla.mil -- Downloaded: 2026-10-21T21:08Z
Check the source to verify that this is the current version before use.

TABLE I. Classification of defects for visual characteristics (cont'd)

Examine	Defect	Classification Major	Minor A	Minor B
Stitching margin (cont'd)	Less than specified:			
	- for more than 2 inches (51 mm) but not more than 4 inches (102 mm) in length			X
	- for more than 4 inches (102 mm) in length		X	
Stitching ends	Overstitched less than 1 inch (25 mm) stitch type 301 (except where ends are held down by other stitching or turned under in a hem or where stitching is performed automatically)		X	
	Secured with less than three tying, overlapping, or backstitches when automatic stitching is performed		X	
Stitching indicated by "Z" on drawing	Chain portion of stitching shown on outside of tarpaulin		X	
Boxstitching	Incomplete:			
	- one row of stitching omitted		X	
	- two or more rows of stitching omitted	X		
	Any boxstitching less than specified length by more than 1/8 inch (3 mm)			X
Construction and workmanship				
Components and assembly	Any required component or operation omitted or not as specified (unless otherwise specified herein)	X		
Repairs	Not in accordance with Department of the Army Field Manual FM-10-16 when authorized by the contracting officer or not authorized by the contracting officer (see 3.3.6)	X		

Source: https://assist.dla.mil -- Downloaded: 2026-10-21T21:08Z
Check the source to verify that this is the current version before use.

TABLE I. Classification of defects for visual characteristics (cont'd)

Examine	Defect	Classification Major	Minor A	Minor B
Construction and workmanship (cont'd)				
Seams	Pleated			X
Hems	Constructed with partial turnunder when double turnunder is required		X	
	Twisted or pleated			X
Reinforcements	Improperly applied, causing excessive fullness on reinforcements or reinforced parts			X
	Not stitched to reinforced parts on all sides or not securely caught in seams or stitching of reinforced parts		X	
Throat bindings	Improperly or loosely applied			X
Markings	Omitted, incorrect, illegible, misplaced or size characters not as specified		X	
Cleanness	Grease or oil stains, thread ends not trimmed to 1/2 inch (13 mm) or less			X

4.4.3.2 Dimensional examination. The tarpaulins shall be examined for defects in table II. The inspection level shall be S-3 and the AQLs, expressed in terms of defects per hundred units, shall be 2.5 for major defects and 15.0 for major and minor defects combined.

Source: https://assist.dla.mil -- Downloaded: 2026-10-21T21:08Z
Check the source to verify that this is the current version before use.

TABLE II. Classification of defects for dimensional characteristics

Examine	Defect	Classification Major	Classification Minor
Overall dimensions	Smaller than specified dimensions	X	
	Larger than specified dimensions and applicable plus tolerance indicated on drawings		X
Components and location dimensions	Not within the specified tolerances		X

* 4.4.3.3 Testing of the end item. Tarpaulin samples shall be tested as specified in 4.5 for compliance with 3.3.5. The sample unit shall be one completely fabricated tarpaulin. The lot shall consist of all completely fabricated tarpaulins offered for inspection. The inspection level shall be S-3. Failure in any area shall be cause for rejection of the lot.

4.4.4 Packaging inspection. An examination shall be made to determine that preservation, packing, and marking are in compliance with section 5. Defects shall be scored in accordance with table III. The sample unit shall be one shipping container fully packaged except that it need not be closed. Examination for the closure defects listed below shall be made on shipping containers fully packaged. The lot shall be the number of shipping containers offered for inspection at one time. The inspection level shall be S-2 and the AQL shall be 2.5 expressed in terms of defects per hundred units.

TABLE III. Examination of preparation for delivery

Examine	Defect
Marking	Omitted; incorrect; illegible; of improper size, location, sequence or method of application
Materials	Any component missing or damaged
Workmanship	Inadequate application of components, such as incomplete closure of container flap, loose strapping or taping, inadequate stapling
	Bulging or distortion of containers
Contents	Not as specified

Source: https://assist.dla.mil -- Downloaded: 2026-10-21T21:08Z
Check the source to verify that this is the current version before use.

4.5 Tests.

4.5.1 Wicking of sewing thread (cup test). The tarpaulin shall be tested in two areas as follows: at a seam joining the body to the front or rear flap and at a panel lap seam.

* 4.5.1.1 Procedure. Suspend the seamed section of the test fabric in the center of a 6 ± 1/8 inch (152 ± 3 mm) diameter hoop and form a depression with the seamed fabric in the hoop to a depth of 1 ± 1/4 inch (25 ± 6 mm). Slowly pour 500 ml of water at 77 ± 4°F (25 ± 2°C) into the cupped area (depression) and observe the under surface of the fabric for water penetration. Any wicking of water along the sewing thread, identified by a discoloration or darkening of the thread within 5 minutes after water is poured, shall constitute a failure. Water leakage through the needle holes or between the plies of the lapped seamed fabric shall not be considered a failure.

5. PACKAGING

5.1 Preservation. Preservation shall be level A or Commercial as specified (see 6.2).

5.1.1 Level A. Each tarpaulin shall be laid out flat, inside up, with the throat folded onto the tarpaulin body. Each tarpaulin shall then be compactly folded with the "US" visible and crosstied with cotton tape or twine.

5.1.2 Commercial. Tarpaulins shall be unit packed to afford adequate protection against physical damage during shipment from the contractor to the first receiving activity. The unit pack and the quantity per unit pack shall be the same as that normally used by the contractor for retail distribution.

5.2 Packing. Packing shall be level A, B or Commercial as specified (see 6.2).

5.2.1 Level A packing. Three tarpaulins, unit packed as specified in 5.1, shall be packed in a close-fitting fiberboard shipping container conforming to style RSC-L, grade V2s of PPP-B-636. The inside of each container shall be fitted with a liner conforming to type CF, class weather-resistant, variety DW, grade V15c of PPP-B-636. The unit packs shall be placed flat, alternately reversing the built-up throat extremity, end for end, to achieve an evenly balanced pack within a shipping container. Each container shall have the contents completely covered on top and bottom with a sheet of 30-pound minimum basis weight (49 g/m^2) kraft paper conforming to type I, grade B of UU-P-268. Each container shall be closed in accordance with method III, waterproofed in accordance with method V, and reinforced as specified in the appendix of PPP-B-636, except that the inspection shall be in accordance with 4.4.4.

Source: https://assist.dla.mil -- Downloaded: 2026-10-21T21:08Z
Check the source to verify that this is the current version before use.

5.2.2 Level B packing. Three tarpaulins, unit packed as specified in 5.1, shall be packed in a close-fitting fiberboard shipping container conforming to style RSC-L, type CF, (variety SW) or type SF, class domestic, grade 275 of PPP-B-636. The inside of each container shall be fitted with a liner conforming to type CF, class domestic, variety SW, grade 275 of PPP-B-636. The unit packs shall be placed flat, alternately reversing the built-up throat extremity, end for end, to achieve an evenly balanced pack within a shipping container, Each container shall have the contents completely covered on top and bottom with a sheet of 30-pound minimum basis weight (49 g/m^2) kraft paper conforming to type I, grade B of UU-P-268. Each container shall be closed in accordance with method II as specified in the appendix of PPP-B-636, except that the inspection shall be in accordance with 4.4.4.

5.2.2.1 Weather-resistant containers. When specified (see 6.2), shipping containers shall be a V3c, V3s, or V4s fiberboard box fabricated in accordance with PPP-B-636 and closed in accordance with method III as specified in the appendix of PPP-B-636, except that the inspection shall be in accordance with 4.4.4.

5.2.3 Commercial packing. Tarpaulins, unit packed as specified in 5.1, shall be packed in a manner to insure carrier acceptance and safe delivery at destination at the lowest transportation rate for such supplies. The quantity per shipping container shall be the same as that normally used by the contractor for retail distribution. Containers shall comply with Uniform Freight Classification or National Motor Freight Classification, as applicable.

5.3 Marking. In addition to any special marking required by the contract or order, shipping containers shall be marked in accordance with MIL-STD-129.

6. NOTES

6.1 Intended use. The tarpaulin is used to protect the components of trailer-mounted wind measuring set, AN/MMQ-I.

6.2 Ordering data. Procurement documents should specify the following:

(a) Title, number, and date of this specification.
(b) When a first article is required (see 3.1, 4.3 and 6.4).
(c) Selection of applicable levels of packaging and packing (see 5.1 and 5.2).
(d) Whether V-board containers are required for level B shipments (see 5.2.2.1).

Source: https://assist.dla.mil -- Downloaded: 202610-21T21:08Z
Check the source to verify that this is the currentversion before use.

6.3 For access to standard shade sample of thread, address the procuring office issuing the invitation for bids.

6.4 First article. When a first article is required, it shall be inspected and approved under appropriate provisions of Armed Services Procurement Regulations ASPR 7-104.55. The contracting officer should specify the appropriate type of first article and the number of units to be furnished. The contracting officer should include specific instructions in all procurement instruments regarding arrangements for inspection and approval of the first article.

* 6.5 Method of repair of leaking seams. A satisfactory method of applying the compound for the repair of leaking seams is as follows:

a. A suitable volume of textile compound conforming to type I, class 1 of TT-P-595 (NSN 8030-00-290-4383) shall be thoroughly stirred and diluted with an equal volume of petroleum solvent (Stoddard solvent or equivalent). Thoroughly stir the mixture again before use.

b. Prior to application of the compound, the tarpaulin must be dry. Special attention must be taken to insure adequate ventilation and that proper fire preventive measures are taken since the compound is flammable.

c. Two coats of the compound shall be then applied to the seams (on the outside of the tarpaulin only). A 4-inch (102 mm) wide stiff brush is recommended for use. The first coat shall be air dried for a minimum of 4 hours prior to application of the second coat. Elapsed time between coats may be reduced by providing a supply of hot air to evaporate the solvent more quickly. In this manner, a second coat may be applied as soon as the first coat is dry to the touch. After application of the second coat, the treated tarpaulin shall be allowed to air dry for a period of at least 24 hours.

6.5.1 Seams to be treated. Seams which have failed the test specified in 4.5.1 shall be treated as follows:

a. Failure at seam joining body to front or rear flaps - treat all seams joining body to flaps.

b. Failure at panel lap seam - treat all panel lap seams.

* 6.6 Recycled material. It is encouraged that recycled material be used when practical as long as it meets the requirements of the specification (see 3.2).

Source: https://assist.dla.mil -- Downloaded: 202610-21T21:08Z
Check the source to verify that this is the currentversion before use.

* 6.7 Metric equivalents. Metric equivalents, indicated in parentheses throughout this document, are based on practices, conversion factors, and symbols specified in ASTM E 380 Standard for Metric Practice, and are for information only. In each instance, the value stated in US customary units shall be controlling.

6.8 Changes from previous issue. The margins of this specification are marked with an asterisk (*) to indicate where changes (additions, modifications, corrections, deletions) from the previous issue were made. This was done as a convenience only and the Government assumes no liability whatsoever for any inaccuracies in these notations. Bidders and contractors are cautioned to evaluate the requirements of this specification based on the entire content irrespective of the marginal notations and relationship to the last previous issue.

Custodians:

Army - GL
Navy - NU

Review activities:

Army - ER
DPSC - CT

Preparing activity:

Army - GL

Project No. 8340-0357

Source: https://assist.dla.mil -- Downloaded: 2026-10-21T21:08Z
Check the source to verify that this is the current version before use.

STANDARDIZATION DOCUMENT IMPROVEMENT PROPOSAL

INSTRUCTIONS: This form is provided to solicit beneficial comments which may improve this document and enhance its use. DoD contractors, government activities, manufacturers, vendors, or other prospective users of the document are invited to submit comments to the government. Fold on lines on reverse side, staple in corner, and send to preparing activity. Attach any pertinent data which may be of use in improving this document. If there are additional papers, attach to form and place both in an envelope addressed to preparing activity. A response will be provided to the submitter, when name and address is provided, within 30 days indicating that the 1426 was received and when any appropriate action on it will be completed.
NOTE: This form shall not be used to submit requests for waivers, deviations or clarification of specification requirements on current contracts. Comments submitted on this form do not constitute or imply authorization to waive any portion of the referenced document(s) or to amend contractual requirements.

DOCUMENT IDENTIFIER *(Number)* AND TITLE

MIL-T-43309C Tarpaulin: Cotton Duck, For Wind Measuring Set

NAME OF ORGANIZATION AND ADDRESS OF SUBMITTER

☐ VENDOR ☐ USER ☐ MANUFACTURER

1. ☐ HAS ANY PART OF THE DOCUMENT CREATED PROBLEMS OR REQUIRED INTERPRETATION IN PROCUREMENT USE? ☐ IS ANY PART OF IT TOO RIGID, RESTRICTIVE, LOOSE OR AMBIGUOUS? PLEASE EXPLAIN BELOW.

A. GIVE PARAGRAPH NUMBER AND WORDING

B. RECOMMENDED WORDING CHANGE

C. REASON FOR RECOMMENDED CHANGE(S)

2. REMARKS

SUBMITTED BY *(Printed or typed name and address — Optional)*

TELEPHONE NO.

DATE

DD FORM 1426 1 OCT 76

EDITION OF 1 JAN 72 WILL BE USED UNTIL EXHAUSTED.

Source: https://assist.dla.mil -- Downloaded: 2026-10-21T21:08Z
Check the source to verify that this is the current version before use.

FOLD

DEPARTMENT OF THE ARMY
US ARMY NATICK RESEARCH and DEVELOPMENT COMMAND
NATICK, MASSACHUSETTS 01760

OFFICIAL BUSINESS
PENALTY FOR PRIVATE USE $300

DRDNA-ES

POSTAGE AND FEES PAID
DEPARTMENT OF THE ARMY
DOD-314

U.S.MAIL

Commander
US Army Natick Research and Development Command
ATTN: DRDNA-ES
Natick, MA 01760

NATICK OP 1 AUG 78
FOLD

Source: https://assist.dla.mil -- Downloaded: 2026-10-21T21:08Z
Check the source to verify that this is the current version before use.