NOTICE OF GROUP CANCELLATION

INCH-POUND

MIL-C-39029D
NOTICE 2
29 April 2005
SUPERSEDING
NOTICE 1
16 October 1991

MILITARY SPECIFICATION

CONTACTS, ELECTRICAL CONNECTOR, GENERAL SPECIFICATION FOR

MIL-C-39029D, the following specification sheets associated with MIL-C-39029, MIL-C-39029, Supplement 1, and current amendments and notices are hereby canceled:

| Document | Date | Cancellation Notice No. | DoD Project No. | Replacement |
|---|---|---|---|---|
| MIL-C-39029D | 2-May-88 | 2 | 5935-4256 | SAE-AS39029 |
| MIL-C-39029/1F | 12-Mar-82 | 1 | 5935-4256-001 | SAE-AS39029/1 |
| MIL-C-39029/2B | 2-Aug-76 | 1 | 5935-4256-002 | SAE-AS39029/2 |
| MIL-C-39029/3B | 2-Aug-76 | 1 | 5935-4256-003 | SAE-AS39029/3 |
| MIL-C-39029/4F | 10-Apr-87 | 2 | 5935-4256-004 | SAE-AS39029/4 |
| MIL-C-39029/5G | 10-Apr-87 | 2 | 5935-4256-005 | SAE-AS39029/5 |
| MIL-C-39029/6A | 2-Aug-76 | 1 | 5935-4256-006 | SAE-AS39029/6 |
| MIL-C-39029/7B | 2-Aug-76 | 1 | 5935-4256-007 | SAE-AS39029/7 |
| MIL-C-39029/8B | 2-Aug-76 | 1 | 5935-4256-008 | SAE-AS39029/8 |
| MIL-C-39029/9E | 19-Oct-82 | 1 | 5935-4256-009 | SAE-AS39029/9 |
| MIL-C-39029/10E | 19-Oct-82 | 1 | 5935-4256-010 | SAE-AS39029/10 |
| MIL-C-39029/11J | 25-Apr-80 | 1 | 5935-4256-011 | SAE-AS39029/11 |
| MIL-C-39029/12J | 25-Apr-80 | 1 | 5935-4256-012 | SAE-AS39029/12 |
| MIL-C-39029/13A | 2-Aug-76 | 1 | 5935-4256-013 | SAE-AS39029/13 |
| MIL-C-39029/14A | 2-Aug-76 | 1 | 5935-4256-014 | SAE-AS39029/14 |
| MIL-C-39029/16C | 25-Apr-80 | 3 | 5935-4256-015 | SAE-AS39029/16 |
| MIL-C-39029/17C | 25-Apr-80 | 2 | 5935-4256-016 | SAE-AS39029/17 |
| MIL-C-39029/18C | 25-Apr-80 | 3 | 5935-4256-017 | SAE-AS39029/18 |
| MIL-C-39029/19A | 2-Aug-76 | 1 | 5935-4256-018 | SAE-AS39029/19 |
| MIL-C-39029/20A | 2-Aug-76 | 1 | 5935-4256-019 | SAE-AS39029/20 |
| MIL-C-39029/21A | 2-Aug-76 | 1 | 5935-4256-020 | SAE-AS39029/21 |
| MIL-C-39029/22B | 3-Nov-89 | 1 | 5935-4256-021 | SAE-AS39029/22 |
| MIL-C-39029/23B | 25-Apr-80 | 2 | 5935-4256-022 | SAE-AS39029/23 |
| MIL-C-39029/24B | 25-Apr-80 | 2 | 5935-4256-023 | SAE-AS39029/24 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-21T18:31Z
Check the source to verify that this is the current version before use.

| Document | Date | Cancellation Notice No. | DoD Project No. | Replacement |
|---|---|---|---|---|
| MIL-C-39029/25C | 25-Apr-80 | 3 | 5935-4256-024 | SAE-AS39029/25 |
| MIL-C-39029/26C | 25-Apr-80 | 3 | 5935-4256-025 | SAE-AS39029/26 |
| MIL-C-39029/27D | 10-May-85 | 1 | 5935-4256-026 | SAE-AS39029/27 |
| MIL-C-39029/28C | 2-Mar-79 | 1 | 5935-4256-027 | SAE-AS39029/28 |
| MIL-C-39029/29B | 25-Sep-81 | 2 | 5935-4256-028 | SAE-AS39029/29 |
| MIL-C-39029/30A | 25-Apr-80 | 3 | 5935-4256-029 | SAE-AS39029/30 |
| MIL-C-39029/31B | 25-Apr-80 | 3 | 5935-4256-091 | SAE-AS39029/31 |
| MIL-C-39029/32B | 9-May-79 | 2 | 5935-4256-031 | SAE-AS39029/32 |
| MIL-C-39029/33C | 18-Nov-85 | 1 | 5935-4256-032 | SAE-AS39029/33 |
| MIL-C-39029/34B | 10-Mar-80 | 2 | 5935-4256-033 | SAE-AS39029/34 |
| MIL-C-39029/35C | 2-Mar-92 | 1 | 5935-4256-034 | SAE-AS39029/35 |
| MIL-C-39029/36A | 10-Mar-80 | 2 | 5935-4256-035 | SAE-AS39029/36 |
| MIL-C-39029/37A | 10-Mar-80 | 2 | 5935-4256-036 | SAE-AS39029/37 |
| MIL-C-39029/44D | 15-Nov-88 | 1 | 5935-4256-037 | SAE-AS39029/44 |
| MIL-C-39029/45D | 15-Nov-88 | 1 | 5935-4256-038 | SAE-AS39029/45 |
| MIL-C-39029/46C | 18-Nov-85 | 2 | 5935-4256-039 | SAE-AS39029/46 |
| MIL-C-39029/47C | 18-Nov-85 | 2 | 5935-4256-040 | SAE-AS39029/47 |
| MIL-C-39029/48D | 16-Sep-85 | 1 | 5935-4256-041 | SAE-AS39029/48 |
| MIL-C-39029/49D | 16-Sep-85 | 1 | 5935-4256-042 | SAE-AS39029/49 |
| MIL-C-39029/50A | 25-Apr-80 | 3 | 5935-4256-043 | SAE-AS39029/50 |
| MIL-C-39029/51A | 25-Apr-80 | 3 | 5935-4256-044 | SAE-AS39029/51 |
| MIL-C-39029/54B | 20-Feb-81 | 2 | 5935-4256-045 | SAE-AS39029/54 |
| MIL-C-39029/55B | 20-Feb-81 | 2 | 5935-4256-046 | SAE-AS39029/55 |
| MIL-C-39029/56E | 14-Feb-95 | 1 | 5935-4256-047 | SAE-AS39029/56 |
| MIL-C-39029/57C | 14-Feb-95 | 1 | 5935-4256-048 | SAE-AS39029/57 |
| MIL-C-39029/58E | 14-Feb-95 | 1 | 5935-4256-049 | SAE-AS39029/58 |
| MIL-C-39029/59D | 26-Dec-88 | 1 | 5935-4256-050 | SAE-AS39029/59 |
| MIL-C-39029/60D | 26-Dec-88 | 1 | 5935-4256-051 | SAE-AS39029/60 |
| MIL-C-39029/63C | 28-Oct-93 | 1 | 5935-4256-052 | SAE-AS39029/63 |
| MIL-C-39029/64C | 10-Feb-92 | 1 | 5935-4256-053 | SAE-AS39029/64 |
| MIL-C-39029/69B | 21-Aug-81 | 2 | 5935-4256-054 | SAE-AS39029/69 |
| MIL-C-39029/70B | 21-Aug-81 | 2 | 5935-4256-055 | SAE-AS39029/70 |
| MIL-C-39029/71C | 19-Aug-88 | 1 | 5935-4256-056 | SAE-AS39029/71 |
| MIL-C-39029/72D | 19-Aug-88 | 1 | 5935-4256-057 | SAE-AS39029/72 |
| MIL-C-39029/73C | 29-Aug-86 | 2 | 5935-4256-058 | SAE-AS39029/73 |
| MIL-C-39029/74C | 29-Aug-86 | 2 | 5935-4256-059 | SAE-AS39029/74 |
| MIL-C-39029/75B | 10-May-85 | 1 | 5935-4256-060 | SAE-AS39029/75 |
| MIL-C-39029/76A | 2-Mar-79 | 3 | 5935-4256-061 | SAE-AS39029/76 |
| MIL-C-39029/77B | 22-Nov-85 | 2 | 5935-4256-062 | SAE-AS39029/77 |
| MIL-C-39029/78B | 22-Nov-85 | 2 | 5935-4256-063 | SAE-AS39029/78 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-21T18:31Z
Check the source to verify that this is the current version before use.

| Document | Date | Cancellation Notice No. | DoD Project No. | Replacement |
|---|---|---|---|---|
| MIL-C-39029/79A | 28-Jul-86 | 1 | 5935-4256-064 | SAE-AS39029/79 |
| MIL-C-39029/80A | 28-Jul-86 | 1 | 5935-4256-065 | SAE-AS39029/80 |
| MIL-C-39029/83C | 16-Sep-85 | 1 | 5935-4256-066 | SAE-AS39029/83 |
| MIL-C-39029/84D | 16-Sep-85 | 1 | 5935-4256-067 | SAE-AS39029/84 |
| MIL-C-39029/85C | 19-Apr-88 | 1 | 5935-4256-068 | SAE-AS39029/85 |
| MIL-C-39029/86C | 19-Apr-88 | 1 | 5935-4256-069 | SAE-AS39029/86 |
| MIL-C-39029/87C | 19-Apr-88 | 1 | 5935-4256-070 | SAE-AS39029/87 |
| MIL-C-39029/88A | 11-Feb-83 | 2 | 5935-4256-071 | SAE-AS39029/88 |
| MIL-C-39029/89C | 19-Apr-88 | 1 | 5935-4256-072 | SAE-AS39029/89 |
| MIL-C-39029/90A | 18-Jan-85 | 1 | 5935-4256-073 | SAE-AS39029/90 |
| MIL-C-39029/91A | 18-Jan-85 | 1 | 5935-4256-074 | SAE-AS39029/91 |
| MIL-C-39029/92B | 2-Mar-89 | 1 | 5935-4256-075 | SAE-AS39029/92 |
| MIL-C-39029/93A | 9-Dec-88 | 1 | 5935-4256-076 | SAE-AS39029/93 |
| MIL-C-39029/94A | 9-Dec-88 | 1 | 5935-4256-077 | SAE-AS39029/94 |
| MIL-C-39029/97A | 9-Dec-88 | 1 | 5935-4256-078 | SAE-AS39029/97 |
| MIL-C-39029/98A | 9-Dec-88 | 1 | 5935-4256-079 | SAE-AS39029/98 |
| MIL-C-39029/99A | 9-Dec-88 | 1 | 5935-4256-080 | SAE-AS39029/99 |
| MIL-C-39029/100A | 9-Dec-88 | 1 | 5935-4256-081 | SAE-AS39029/100 |
| MIL-C-39029/101A | 10-Mar-89 | 1 | 5935-4256-082 | SAE-AS39029/101 |
| MIL-C-39029/102A | 31-Mar-88 | 1 | 5935-4256-083 | SAE-AS39029/102 |
| MIL-C-39029/103A | 31-Mar-88 | 1 | 5935-4256-084 | SAE-AS39029/103 |
| MIL-C-39029/104 | 9-Nov-87 | 1 | 5935-4256-085 | SAE-AS39029/104 |
| MIL-C-39029/105 | 9-Nov-87 | 1 | 5935-4256-086 | SAE-AS39029/105 |
| MIL-C-39029/106A | 21-Sep-90 | 1 | 5935-4256-087 | SAE-AS39029/106 |
| MIL-C-39029/107A | 21-Sep-90 | 1 | 5935-4256-088 | SAE-AS39029/107 |
| MIL-C-39029/108 | 30-Apr-90 | 1 | 5935-4256-089 | SAE-AS39029/108 |
| MIL-C-39029/109 | 30-Apr-90 | 1 | 5935-4256-090 | SAE-AS39029/109 |

CAUTION: The supersession information is valid as of the date of this notice and may be superseded by subsequent revisions of superseding document.

(Application for copies of SAE-Aerospace standards should be addressed to SAE, 400 Commonwealth Drive, Warrendale, PA 15096-0001.)



Source: https://assist.dla.mil -- Downloaded: 2026-10-21T18:31Z
Check the source to verify that this is the current version before use.

Preparing activity:
Navy - AS

(Project 5935-4256)

Custodians:
Army - CR
Navy - AS
Air Force - 11
DLA - CC

Review activities:
Army - AR, MI
Navy - EC, MC, OS, SH

NOTE: The activities listed above were interested in this document as of the date of this document. Since organizations can change, you should verify the currency of the information using the ASSIST Online database at http://assist.daps.dla.mil.



Source: https://assist.dla.mil -- Downloaded: 2026-10-21T18:31Z
Check the source to verify that this is the current version before use.