NOTICE OF CANCELLATION

INCH-POUND

AN783 REV 10
NOTICE 1
22 April 1999

AIR FORCE/NAVY AERONAUTICAL STANDARD

TEE, FLARED TUBE, INTERNAL THREAD ON SIDE

AN783 REV 10, dated 10 February 1988, is hereby cancelled. Future acquisitions for this item should refer to Society of Automotive Engineers (SAE) Aerospace Standard (AS) AS1031, "Tee, Standard and Reducer, Bulkhead on Run, Internal Port on Side, Flared Tube."

Table 1 provides a detailed cross-reference of cancelled AN783 Part or Identifying Numbers (PINs) and replacement AS1031 PINs. The use of "AS" parts is preferable, but "AN" parts may be used for a period of three years from the date of this notice to deplete existing stock. Users are cautioned to evaluate replacements for their particular application.

(DoD activities may obtain copies of SAE AS1031 from the DoDSSP, Standardization Document Order Desk, 700 Robbins Avenue, Building 4D, Philadelphia, PA 19111-5094. The private sector and other Government agencies may purchase copies from the Society of Automotive Engineers International, 400 Commonwealth Drive, Warrendale, PA 15096-0001.)

Custodians:
Army - AV
Navy - AS
Air Force – 99
DLA - CC

Preparing activity:
DLA - CC

(Project 4730-0411)

Review activity:
Air Force - 82

AMSC N/A FSC 4730

DISTRIBUTION STATEMENT A. Approved for public release; distribution is unlimited.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T14:16Z
Check the source to verify that this is the current version before use.

TABLE 1 - Cross-Reference Data

Cancelled AN PIN	Tube Size	Replacement AS PIN
AN783-2	.125	AS1031-020202
AN783D2	.125	AS1031D020202
AN783J2	.125	AS1031J020202
AN783K2	.125	AS1031K020202
AN783S2	.125	AS1031S020202
AN783T2	.125	AS1031T020202
AN783W2	.125	AS1031W020202
AN783-3	.188	AS1031-030303
AN783D3	.188	AS1031D030303
AN783J3	.188	AS1031J030303
AN783K3	.188	AS1031K030303
AN783S3	.188	AS1031S030303
AN783T3	.188	AS1031T030303
AN783W3	.188	AS1031W030303
AN783-4	.250	AS1031-040404
AN783D4	.250	AS1031D040404
AN783J4	.250	AS1031J040404
AN783K4	.250	AS1031K040404
AN783S4	.250	AS1031S040404
AN783T4	.250	AS1031T040404
AN783W4	.250	AS1031W040404
AN783-5	.312	AS1031-050505
AN783D5	.312	AS1031D050505
AN783J5	.312	AS1031J050505
AN783K5	.312	AS1031K050505
AN783S5	.312	AS1031S050505
AN783T5	.312	AS1031T050505
AN783W5	.312	AS1031W050505
AN783-6	.375	AS1031-060606
AN783D6	.375	AS1031D060606
AN783J6	.375	AS1031J060606
AN783K6	.375	AS1031K060606
AN783S6	.375	AS1031S060606
AN783T6	.375	AS1031T060606
AN783W6	.375	AS1031W060606

Cancelled AN PIN	Tube Size	Replacement AS PIN
AN783-8	.500	AS1031-080808
AN783D8	.500	AS1031D080808
AN783J8	.500	AS1031J080808
AN783K8	.500	AS1031K080808
AN783S8	.500	AS1031S080808
AN783T8	.500	AS1031T080808
AN783W8	.500	AS1031W080808
AN783-10	.625	AS1031-101010
AN783D10	.625	AS1031D101010
AN783J10	.625	AS1031J101010
AN783K10	.625	AS1031K101010
AN783S10	.625	AS1031S101010
AN783T10	.625	AS1031T101010
AN783W10	.625	AS1031W101010
AN783-12	.750	AS1031-121212
AN783D12	.750	AS1031D121212
AN783J12	.750	AS1031J121212
AN783K12	.750	AS1031K121212
AN783S12	.750	AS1031S121212
AN783T12	.750	AS1031T121212
AN783W12	.750	AS1031W121212
AN783-16	1.000	AS1031-161616
AN783D16	1.000	AS1031D161616
AN783J16	1.000	AS1031J161616
AN783K16	1.000	AS1031K161616
AN783S16	1.000	AS1031S161616
AN783T16	1.000	AS1031T161616
AN783W16	1.000	AS1031W161616
AN783-20	1.250	AS1031-202020
AN783D20	1.250	AS1031D202020
AN783J20	1.250	AS1031J202020
AN783K20	1.250	AS1031K202020
AN783S20	1.250	AS1031S202020
AN783T20	1.250	AS1031T202020
AN783W20	1.250	AS1031W202020

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T14:16Z
Check the source to verify that this is the current version before use.