NOTICE OF CANCELLATION

INCH-POUND

AN783 Rev 10
NOTICE 2
15 November 2010
SUPERSEDING
NOTICE 1
22 April 1999

AIR FORCE/NAVY AERONAUTICAL STANDARD

TEE, FLARED TUBE, INTERNAL THREAD ON SIDE

AN783 Rev 10, dated 10 February 1988, is hereby cancelled. Future acquisitions for this item should refer to SAE-AS1031, " Fitting, Tee, Standard and Reducer, Bulkhead on Run, Internal Port on Side, Flared".

(Copies of these documents are available from SAE International, 400 Commonwealth Drive, Warrendale, PA 15096-0001, Tel: 877-606-7323 (inside USA and Canada) or 724-776-4970 (outside USA), www.sae.org.)

Reason for NOTICE 2: SAE inactivated Part or Identifying Number (PIN) with material code letter D for replacement parts and for new design to use code letter W. This is because code letter W is stronger in tensile strength than code letter D. This is based on the previous PA's revision, as a result of lessons learned. Plus to add back material code letter S for replacement parts and for new design to use code letter R. The code letter R is better for applications requiring higher temperature.

Table l provides a detailed cross-reference of cancelled AN783 Rev 10 PINs and replacement SAE-AS1031 PINs.

CAUTION: The supersession information is valid as of the date of this notice and may be superseded by subsequent revisions of the superseding document.

CONCLUDING MATERIAL

Custodians:
Army - AV
Navy - AS
Air Force – 99
DLA - CC

Preparing activity:
DLA - CC

(Project 4730-2010-024)

Review activities:
Army – AR, CR4
Navy – MC, SA
Air Force –11, 71

NOTE: The activities listed above were interested in this document as of the date of this document. Since organizations and responsibilities can change, you should verify the currency of the information above using the ASSIST Online database at https://assist.daps.dla.mil.

AMSC N/A

FSC 4730

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T14:16Z
Check the source to verify that this is the current version before use.

TABLE I. AN783 Rev 10 to SAE-AS1031, cross-reference data.

Cancelled AN PIN	Tube Size	Replacement AS PIN	New Design	Cancelled AN PIN	Tube Size	Replacement AS PIN	New Design
AN783-2	.125	AS1031-020202		AN783-8	.500	AS1031-080808	
AN783D2	.125	AS1031D020202	AS1031W020202	AN783D8	.500	AS1031D080808	AS1031W080808
AN783J2	.125	AS1031J020202		AN783J8	.500	AS1031J080808	
AN783K2	.125	AS1031K020202		AN783K8	.500	AS1031K080808	
AN783S2	.125	AS1031S020202	AS1031R020202	AN783S8	.500	AS1031S080808	AS1031R080808
AN783T2	.125	AS1031T020202		AN783T8	.500	AS1031T080808	
AN783W2	.125	AS1031W020202		AN783W8	.500	AS1031W080808	
AN783-3	.188	AS1031-030303		AN783-10	.625	AS1031-101010	
AN783D3	.188	AS1031D030303	AS1031W030303	AN783D10	.625	AS1031D101010	AS1031W101010
AN783J3	.188	AS1031J030303		AN783J10	.625	AS1031J101010	
AN783K3	.188	AS1031K030303		AN783K10	.625	AS1031K101010	
AN783S3	.188	AS1031S030303	AS1031R030303	AN783S10	.625	AS1031S101010	AS1031R101010
AN783T3	.188	AS1031T030303		AN783T10	.625	AS1031T101010	
AN783W3	.188	AS1031W030303		AN783W10	.625	AS1031W101010	
AN783-4	.250	AS1031-040404		AN783-12	.750	AS1031-121212	
AN783D4	.250	AS1031D040404	AS1031W040404	AN783D12	.750	AS1031D121212	AS1031W121212
AN783J4	.250	AS1031J040404		AN783J12	.750	AS1031J121212	
AN783K4	.250	AS1031K040404		AN783K12	.750	AS1031K121212	
AN783S4	.250	AS1031S040404	AS1031R040404	AN783S12	.750	AS1031S121212	AS1031R121212
AN783T4	.250	AS1031T040404		AN783T12	.750	AS1031T121212	
AN783W4	.250	AS1031W040404		AN783W12	.750	AS1031W121212	

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T14:16Z
Check the source to verify that this is the current version before use.

TABLE I. AN783 Rev 10 to SAE-AS1031, cross-reference data – Continued.

Cancelled AN PIN	Tube Size	Replacement AS PIN	New Design	Cancelled AN PIN	Tube Size	Replacement AS PIN	New Design
AN783-5	.312	AS1031-050505		AN783-16	1.000	AS1031-161616	
AN783D5	.312	AS1031 D050505	AS1031 W050505	AN783D16	1.000	AS1031 D161616	AS1031 W161616
AN783J5	.312	AS1031 J050505		AN783J16	1.000	AS1031 J161616	
AN783K5	.312	AS1031 K050505		AN783K16	1.000	AS1031 K161616	
AN783S5	.312	AS1031 S050505	AS1031 R050505	AN783S16	1.000	AS1031 S161616	AS1031 R161616
AN783T5	.312	AS1031 T050505		AN783T16	1.000	AS1031 T161616	
AN783W5	.312	AS1031 W050505		AN783W16	1.000	AS1031 W161616	
AN783-6	.375	AS1031-060606		AN783-20	1.250	AS1031-202020	
AN783D6	375	AS1031 D060606	AS1031 W060606	AN783D20	1.250	AS1031 D202020	AS1031 W202020
AN783J6	375	AS1031 J060606		AN783J20	1.250	AS1031 J202020	
AN783K6	375	AS1031 K060606		AN783K20	1.250	AS1031 K202020	
AN783S6	375	AS1031 S060606	AS1031 R060606	AN783S20	1.250	AS1031 S202020	AS1031 R202020
AN783T6	375	AS1031 T060606		AN783T20	1.250	AS1031 T202020	
AN783W6	375	AS1031 W060606		AN783W20	1.250	AS1031 W202020	

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T14:16Z
Check the source to verify that this is the current version before use.