MIL-F-50988B (AR)
10 October 1978
SUPERSEDING
MIL-F-50988A
17 January 1977

MILITARY SPECIFICATION

FUZE, PD, M567
LOADING, ASSEMBLING, AND PACKING

This specification is approved for use by the US Army Armament Research and Development Command, and is available for use by all Departments and Agencies of the Department of Defense.

1. SCOPE

1.1 This specification contains requirements and provides quality assurance provisions for loading, assembling, and packing of the M567 Point Detonating Fuze. See paragraph 6.1.

2. APPLICABLE DOCUMENTS

2.1 The following documents of the issue in effect on date of invitation for bids or request for proposals form a part of this specification to the extent specified herein.

SPECIFICATIONS

MILITARY

MIL-P-45486	-	Pellets, RDX (For Use in Ammunition)
MIL-A-48078	-	Ammunition Standard Quality Assurance Provisions, General Specification For
MIL-P-60412	-	Packaging, Packing and Marking for Shipment of Artillery Type and Rocket Fuzes, General Specification For

STANDARDS

MILITARY

MIL-STD-331	-	Fuze and Fuze Components, Environmental and Performance Test For

FSC: 1390

Beneficial comments (recommendations, additions, deletions) and any pertinent data which may be of use in improving this document should be addressed to: Commander, US Army Armament Research and Development Command, Attn. DRDAR-QA, Dover, New Jersey 07801 by using the self-addressed Standardization Document Improvement Proposal (DD Form 1426) appearing at the end of this document or by letter.

Source: https://assist.dla.mil -- Downloaded: 202610-22T20:46Z
Check the source to verify that this is the current version before use.

DRAWINGS (See 6.5)

US ARMY ARMAMENT RESEARCH AND DEVELOPMENT COMMAND (ARRADCOM)

PRODUCT AND PACKAGING DRAWINGS

9246242 - Fuze, Point Detonating M567
9247277 - Carton, Packing, Ammunition, for Fuze, PD, M567
9247276 - Box, Wirebound, Packing, Ammunition for Fuze, PD, M567

INSPECTION EQUIPMENT DRAWINGS

8816014 - Ball
8816368 - Lead Disc
9200012 - Firing Pin
9243921 - M98 Stab Detonator

(Copies of specifications, standards, drawings and publications required by suppliers in connection with specific procurement functions should be obtained from the procuring activity or as directed by the contracting officer.)

3. REQUIREMENTS

3.1 Material. Materials and parts shall be in accordance with applicable drawings and specifications.

3.2 Fuze assembly. The PD, M567 fuze assemblies shall comply with all requirements specified on drawing (dwg.) 9246242 and with all requirements specified in applicable specifications.

3.3 Jolt and jumble. The fuze assembly shall comply with the requirements of MIL-STD-331A, Tests 101.2 and 102.1.

3.4 Transportation vibration. The fuze assembly shall comply with the requirements of MIL-STD-331A, Test 104 and of paragraphs 3.5.1 and 3.5.2.

3.5 Proving ground

3.5.1 Premature bursts. There shall be no premature bursts or metal parts failure in the mortar or in flight.

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:46Z
Check the source to verify that this is the current version before use.

3.5.2 Functioning. The fuze shall function on impact with the ground (as evidence by cartridge functioning).

3.5.3 Arming safety. The fuze shall not function on impact against a 1/2" plywood screen positioned at a distance of 100 meters ± 1 meter.

3.6 Lead assembly output test. The lead assembly shall pierce a hole .220 inch minimum in diameter in a lead disc (dwg. 8816368).

3.7 Complete fuze leak test. The fuze shall have an air leakage rate no greater than 0.5 psi per 15 seconds.

3.8 First article inspection. This specification contains technical provisions for first article inspection. Requirements for the submission of first article samples by the contractor shall be as specified in the contract.

3.9 Workmanship. All parts and assemblies shall be fabricated in a thorough, workmanlike manner. They shall be free of burrs, sharp edges, cracks, dirt, rust and other foreign matter. The cleaning methods used shall not be injurious to any part, nor shall the parts be contaminated by the cleaning agent. Exterior surface coatings shall be uniform and continuous except for a few light scratches not exposing base material.

4. QUALITY ASSURANCE PROVISIONS

4.1 Responsibility for inspection and standard quality assurance provisions. Unless otherwise specified herein or in the contract, the provisions of MIL-A-48078 shall apply and are hereby made a part of this detail specification.

4.2 Classification of inspections. The following types of inspection shall be conducted on this item:

a. First Article Inspection

b. Quality Conformance Inspection

4.3 First article inspection

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:46Z
Check the source to verify that this is the current version before use.

4.3.1 Submission. The contractor shall submit a first article sample as designated by the Contracting Officer for evaluation in accordance with provisions of 4.3.2. The first article sample shall consist of the following items in sample quantities as indicated.

Part Description	Drawings	Quantity
Cup, Lead	9234684	10
Lead Assembly	9234683	60
Pellet, Booster	9255163	10
Fuze, PD, M567	9246242	404*

* Total complete fuze sample size is 404. Of this quantity, 176 samples shall be submitted for ballistic testing and 176 samples be withheld by the contractor (see Acceptance Note (e), Table I). The remaining samples are for non-ballistic tests as per Table I.

4.3.2 Inspections to be performed. See MIL-A-48078 and Table I specified herein.

4.3.3 Rejection. Unless stated otherwise, any defect found in first article testing (Table I) shall be cause for rejection of the first article sample as specified in MIL-48078.

Source: https://assist.dla.mil -- Downloaded: 202610-22T20:46Z
Check the source to verify that this is the current version before use.

TABLE I - FIRST ARTICLE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-F-50988B (AR)

PARAGRAPH	TITLE		SHEET 1 OF 2		DRAWING NUMBER
	M567 PD Fuze and Components				See Below
					NEXT HIGHER ASSEMBLY
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
	Cup, Lead (Dwg. 9234684)				
	Examination for defects	10	(b)	3.2	4.4.2.1
	Lead Assembly (Dwg. 9234683)				
	Examination for defects	10	(b)	3.2	4.4.2.2
	Lead assembly output test	50	(b)	3.6	4.5.3
	Pellet, Booster (Dwg. 9255163)				
	Examination for defects	10	(b)	3.2	4.4.2.3
	Fuze, PD, M567 (Dwg. 9246242)				
	Examination for defects	15	(a)(b)	3.2	4.4.2.6
	Examination for defects - after disassembling front and rear bodies	15	(a)(b)	3.2	4.4.2.5
	Complete fuze leak test	25	(b)	3.7	4.5.4
	Jolt and jumble	12	(b)	3.3	4.5.1

NOTES:
(a) The same quantity of 15 shall be used for both tests.
(b) One (1) or more defects shall be cause for rejection.

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:46Z
Check the source to verify that this is the current version before use.

TABLE I - FIRST ARTICLE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE		SHEET 2 OF 2	DRAWING NUMBER
	CONTINUATION SHEET			See Below
				NEXT HIGHER ASSEMBLY
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
	Fuze, PD, M567, Destructive Acceptance Testing (Dwg. 9246242)		(e)		
	Ballistic test SQ	124	(c)	3.5.2	4.5.5
	Ballistic test delay	30	(d)	3.5.2	4.5.5
	Arming safety test	12	(b)	3.5.3	4.5.6
	Transportation vibration	10	(f)	3.4	4.5.2

NOTES:

(c) More than 2 duds or any premature functioning shall be cause for rejection.
(d) Five (5) fuzes of the charge zero quantity shall be TV conditioned prior to ballistic test. Any premature functioning shall be cause for rejection. Other results for information only.
(e) In addition to the above samples, an additional proving ground sample of 176 fuzes shall be withheld by the manufacturer pending successful completion of all tests and disposition instructions from the contracting officer.
(f) One (1) or more defects shall be cause for rejection.

Source: https://assist.dla.mil -- Downloaded: 2026-02-22T20:46Z
Check the source to verify that this is the current version before use.

4.4 Quality conformance inspection

4.4.1 Inspection lot formation. Inspection lots shall comply with the lot formation provisions of MIL-A-48078. In addition, inspection lots of fuzes shall contain:

a. Fuze components, less auxiliary boosters and boosters, of one interfix number from one manufacturer.

b. Booster pellets of one lot interfix number from one manufacturer.

c. Auxiliary boosters of one lot interfix number from one manufacturer.

4.4.2 Examination. See MIL-A-48078.

a. Sampling plans. Unless otherwise specified in the Classification of Defects and Test Tables, sampling plans for major and minor defects shall be in accordance with MIL-STD-105, Inspection Level II.

Source: https://assist.dla.mil -- Downloaded: 202610-22T20:46Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION
CLASSIFICATION OF DEFECTS & TESTS

MIL-F-50988B (AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 9234684
4.4.2.1	Cup, Lead				NEXT HIGHER ASSEMBLY 9234683
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Thickness of base		0.40%	3.2	Gage
102	Inside diameter		0.40%	3.2	Gage
103	Outside diameter		0.40%	3.2	Gage
104	Outside flange diameter		0.40%	3.2	Gage
105	Thickness of flange		0.40%	3.2	Gage
106	Length from bottom to base of flange		0.40%	3.2	Gage
107	Corner radii (two places)		0.40%	3.2	Gage
Minor					
201	Protective finish damaged		1.00%	3.2	Visual
202	Surface finish improper		1.00%	3.2	Visual
203	Evidence of poor workmanship		1.00%	3.9	Visual

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:46Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-F-50988B (AR)

PARAGRAPH	TITLE	SHEET	OF	DRAWING NUMBER
4.4.2.2	Lead Assembly	1	1	9234683
				NEXT HIGHER ASSEMBLY 9246241

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Overall length		0.40%	3.2	Gage
102	Outside diameter		0.40%	3.2	Gage
103	Charge depth improper		0.40%	3.2	Gage
104	Identification mark missing or improper		0.40%	3.2	Visual
105	Lead assembly output test	200	(a)	3.6	4.5.3
Minor					
201	Evidence of poor workmanship		1.00%	3.9	Visual

NOTES: (a) More than two (2) defects shall cause the lot to be rejected.

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:46Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-F-50988B (AR)

PARAGRAPH	TITLE		SHEET OF		DRAWING NUMBER
4.4.2.3	Pellet, Booster		1 1		9255163
					NEXT HIGHER ASSEMBLY 9246242
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Diameter		0.40%	3.2	Gage
102	Height		0.40%	3.2	Gage
103	Cracked, chipped or broken		0.40%	3.2	Visual
104	Weight		0.40%	3.2	Gage (see note a)
105	Density		0.40%	3.2	(see note b)
Minor					
201	Evidence of poor workmanship		1.00%	3.9	Visual

NOTES:
(a) Pellet which fails this requirement may be accepted if density is proper.
(b) Check density per MIL-P-45486 if weight requirement is not met.

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-02-22T20:46Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-F-50988B (AR)

PARAGRAPH	TITLE	SHEET	OF	DRAWING NUMBER
4.4.2.4	Body Assembly, Front	1	1	9246241
				NEXT HIGHER ASSEMBLY 9246242

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical					
1	Pullwire assembly missing or not fully seated		100%	3.2	Visual
Major					
101	Lead missing		0.40%	3.2	Visual
102	Tape missing from lead		0.40%	3.2	Visual
103	Retainer plug missing or loose		0.40%	3.2	Visual-Manual
104	Contaminents in retainer plug cavity		0.40%	3.2	Visual
Minor					
201	Evidence of shipping damage		1.00%	3.2	Visual

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:46Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-F-50988B (AR)

PARAGRAPH	TITLE	SHEET	OF	DRAWING NUMBER
4.4.2.5	Fuze, PD, M567 (Before assembling front and rear bodies)	1	1	9246242
				NEXT HIGHER ASSEMBLY

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Felt pad missing or folded		0.40%	3.2	Visual
102	Booster pellet missing		0.40%	3.2	Visual
103	Disc missing or improperly assembled		0.40%	3.2	Visual
104	O-ring missing or improperly assembled		0.40%	3.2	Visual
105	Aft support improperly assembled		0.40%	3.2	Visual
106	Auxiliary booster missing or improperly assembled		0.40%	3.2	Visual
107	Tape missing from auxiliary booster		0.40%	3.2	Visual
108	Sealant missing from threads		0.40%	3.2	Visual
Minor	None defined				

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

12

Source: https://assist.dla.mil -- Downloaded: 2026-02-22T20:46Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-F-50988B (AR)

PARAGRAPH	TITLE	SHEET OF	DRAWING NUMBER
4.4.2.6	Fuze, PD, M567	1 1	9246242
			NEXT HIGHER ASSEMBLY -------

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical					
1	Pull wire assembly missing or not seated		100%	3.2	Gage
Major					
101	Insufficient torque retaining front and rear bodies		0.40%	3.2	Gage
102	Windshield depression excessive		0.40%	3.2	Gage
103	Fuze improperly marked		0.40%	3.2	Visual
104	Label missing, damaged or illegible		0.40%	3.2	Visual
105	Complete fuze leak test	20	(a)	3.7	4.5.4
Minor					
201	Evidence of poor workmanship		1.00%	3.9	Visual

NOTES: (a) Two (2) or more defects shall cause the lot to be rejected.

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:46Z
Check the source to verify that this is the current version before use.

PARAGRAPH	TITLE	SHEET	OF	DRAWING NUMBER
4.4.2.7	Fuze, PD, M567, Destructive Lot Acceptance Testing	1	1	9246242
				NEXT HIGHER ASSEMBLY: -------

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical					
1	Jolt and jumble test, MIL-STD-331 Test no. 101.2 and 102.1	12	(d)	3.3	4.5.1
2	Transportation vibration test MIL-STD-331 test no. 104 and premature burst during firing	10	(d)	3.4	4.5.2
3	Premature burst in ballistic test	128	(d)	3.5.1	4.5.5
4	Function in arming safety test	12	(d)	3.5.3	4.5.6
Major					
101	Ballistic test SQ	88	(a)	3.5.2	4.5.5
102	Ballistic test delay	30	(b)	3.5.2	4.5.5
103	Transportation vibration firing phase non-function	10	(c)	3.5.2	4.5.2
Minor	None defined				

NOTES:
(a) Three (3) or more duds shall cause the lot to be rejected. After three (3) consecutive lots have been accepted according to this criteria, a special double sampling plan shall be used - see paragraph 4.5.5.1.3.
(b) Five (5) fuzes from the charge zero quantity shall be TV conditioned prior to ballistic test. Results for information only except for premature functioning.
(c) Two (2) or more dudsshall cause the lot to be rejected.
(d) One (1) or more defects shall be cause for lot rejection.

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:46Z
Check the source to verify that this is the current version before use.

4.4.3 Inspection equipment. The inspection equipment required to perform the examination and tests prescribed herein is described in the Paragraph Reference/Inspection Method column in the tables starting with paragraph 4.4.2.1. The contractor shall submit for approval inspection equipment designs in accordance with the terms of the contract. See Section 6 of MIL-A-48078 and para. 6.3 of this specification.

4.5 Methods of inspection

4.5.1 Jolt and jumble. The tests shall be conducted upon complete fuze assemblies (dwg. 9246242). The test shall be conducted in accordance with procedures outlined in MIL-STD-331 Test 101.2 and after completion of that test, the fuze shall not be disassembled but shall be subjected to Test 102.1, utilizing the appropriate fixture. Assemblies subjected to this test shall not be returned to the lot. After completion of the test, the fuzes shall be disassembled and inspected for compliance with requirements of para. 3.3 and MIL-STD-331. As a minimum, observation shall be made for compliance with the following requirements (these defects are classified as "critical"):

a. The assembly shall not be broken or come apart in any way.

b. The slider shall not be in the armed position.

c. The setback pins shall not have moved so as to release the balls retaining the firing pin assembly or the striker.

d. The arming pin shall not have moved to the armed position.

e. The pull wire assembly shall not have come loose in such a way as to not block the slider.

f. No explosive components shall have detonated.

g. The firing pin or striker shall not move past the balls to the armed position.

h. There shall be no explosive dust present.

If any fuze fails to meet the requirements of MIL-STD-331 or the requirements of this specification, the lot shall be rejected.

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:46Z
Check the source to verify that this is the current version before use.

4.5.2 Transportation vibration. The test shall be performed on complete fuze assemblies (dwg. 9246242) in the unarmed position set SQ. The test shall be conducted in accordance with the procedures outlined in MIL-STD-331A, Test 104 using equipment as specified in 4.4.3 of this specification. Upon completion of the test, the fuzes shall not be disassembled but shall be x-rayed to determine if the fuze has armed, become unsafe in any way, or has been damaged so as to not function. If so, that condition shall be classed as a test failure, and the ballistic sample shall not be fired. If the x-rays indicate the fuzes are safe and operable, they shall be assembled to 81MM, M374 rounds and fired at Charge 0 set SQ, as detailed in para. 4.5.5. If any sample fails to function high order that sample shall be classified defective.

4.5.3 Lead assembly output test. The test shall be performed on the lead assembly (dwg. 9234683). A fixture shall be used to hold the lead assembly in central contact with the lead disc (dwg. 8816368). A ball (dwg. 8816014) shall be dropped a distance of five (5) inches onto a firing pin (dwg. 9200012)-distance is measured from the bottom of the ball to the top of the firing pin. The firing pin shall strike and initiate an M98 detonator (dwg. 9243921) which in turn will function the lead assembly. Observation shall be made for compliance with requirements as defined in para. 3.6. Other suggested, but not mandatory, equipment which could be utilized in conjunction with this set-up are: Holder (dwg. 8816367), bushing (dwg. 8827829) and base (dwg. 8802085). Government approval of the test fixture to be used, is required.

4.5.4 Complete fuze leak test. This test shall be performed on complete fuzes (dwg. 9246242). A fixture shall be used which covers the entire outer surface of the fuze with as little clearance as possible. The test shall be conducted at ambient temperature using 3 $\pm$ 0.5 psi. Any sample which exhibits a pressure drop of more than 0.5 psi in 15 seconds minimum after stabilization shall be classed defective. A fixed volume of air shall be used so as to detect gross leaks. Equipment shall be as specified in 4.4.3.

4.5.5 Ballistic test (proving ground)

4.5.5.1 Functioning test. The sample fuzes shall be assembled to the 81MM, HE, M374 cartridges and fired from an appropriate mortar between 45° and 75° elevation. If any fuze fails to cause

Source: https://assist.dla.mil -- Downloaded: 202610-22T20:46Z
Check the source to verify that this is the current version before use.

the shell to function high order, that fuze shall be classified as defective. If any fuze in either SQ or Delay setting mode causes the round to function prematurely, that fuze shall be classified as having a critical defect. The proving ground shall utilize a geophonic sensing device to differentiate super-quick and delay functionings at maximum charge.

4.5.5.1.1 SQ phase. The sample fuzes shall be divided into two (2) equal groups. The groups shall be fired at Charge 0 set SQ and maximum charge set SQ.

4.5.5.1.2 Delay phase. The sample fuzes shall be divided into two (2) equal groups. The groups shall be fired at Charge 0 set Delay and maximum charge set Delay, respectively. Sample fuzes required to be TV tested shall be conditioned in accordance with para. 4.5.2 except that the fuzes shall be set Delay after conditioning. This test is for informational purposes only and shall not be considered for lot acceptance purposes except for premature functions.

4.5.5.1.3 Double sample SQ. After three (3) consecutive lots have met the ballistic requirements of para. 4.4.2.7, a special double sample for the ballistic, SQ phase shall be employed. Forty-four (44) sample fuzes shall be fired in accordance with para. 4.5.5.1.1. If no (0) duds result, the lot shall be accepted. If two (2) or more duds are found the lot shall be rejected. If one (1) dud results, another sample of forty-four (44) fuzes shall be fired. If more than one (1) additional dud results, the lot shall be rejected. If only the first sample is required, the Premature Burst sample size shall be reduced to eighty-four (84).

4.5.6 Arming safety (proving ground). The fuzes shall be assembled to the inert filled M374 round set SQ and fired at Charge 0 from a 81MM mortar. They shall be fired against a 1/2 inch plywood screen set at a distance of 100 meters $\pm$ 1 meter. A minimum muzzle velocity of 180 fps is required for every round. If any fuze functions when the muzzle velocity is equal to or greater than the requirement, the lot shall be rejected. If any fuze functions and the muzzle velocity is less than the requirement, the lot shall be referred. If a fuze does not function, but the muzzle velocity for that round is below the requirement, that sample shall be classed a "no-test" and a new sample shall be tested.

Source: https://assist.dla.mil -- Downloaded: 20260-22T20:46Z
Check the source to verify that this is the current version before use.

5. PACKAGING

5.1 Packaging requirements. Packaging shall be in accordance with the requirements of MIL-P-60412 and drawing 9247277.

5.2 Packing and marking. Packing and marking shall be in accordance with the requirements of MIL-P-60412 and dwg. 9247276.

6. NOTES

6.1 Intended use. The components covered by this specification are intended for use on 81MM Mortar Ammunition. This specification is intended exclusively for use with the M567 Point Detonating Fuze, Less Boosters, manufactured in accordance with MIL-F-50945.

6.2 Ordering data. See MIL-A-48078.

6.3 Submission of inspection equipment for design approvals. See MIL-A-48078. Submit designs as required to Commander, US Army Armament Research and Development Command, ATTN: DRDAR-QAR-I, Dover, New Jersey 07801.

6.4 Proving ground summary

6.4.1 Quality conformance test

FUNCTIONING

Weapon	Cartridge	Charge	Fuze Setting	Quantity
81MM Mortar	81MM, HE, M374	0	SQ	44 (a)
		0	Delay	15 (b)
		Maximum	SQ	44 (a)
		Maximum	Delay	15 (b)

(a) Quantity reduced to twenty-two (22) per test phase as required when employing special double sample.

(b) Results for informational purposes only except for premature functionings. Five (5) fuzes of the charge zero quantity shall be TV conditioned prior to functioning test.

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:46Z
Check the source to verify that this is the current version before use.

ARMING DELAY

Weapon	Cartridge	Charge	Fuze Setting	Quantity
81MM Mortar	M374 Inert	0	SQ	12

TRANSPORTATION VIBRATION

Weapon	Cartridge	Charge	Fuze Setting	Quantity
81MM Mortar	M374 HE	0	SQ	10

6.4.2 First article inspection test

FUNCTIONING

Weapon	Cartridge	Charge	Fuze Setting	Quantity
81MM Mortar	81MM, HE, M374	0	SQ	62
		0	Delay	15 (a)
		Maximum	SQ	62
		Maximum	Delay	15 (a)

(a) Results for information only except for premature functioning. Five (5) fuzes of the charge zero quantity shall be TV conditioned prior to functioning test.

ARMING DELAY

Weapon	Cartridge	Charge	Fuze Setting	Quantity
81MM Mortar	81MM, Inert, M374	0	SQ	12

TRANSPORTATION VIBRATION

Weapon	Cartridge	Charge	Fuze Setting	Quantity
81MM Mortar	M374 HE	0	SQ	10

Source: https://assist.dla.mil -- Downloaded: 202610-22T20:46Z
Check the source to verify that this is the current version before use.

6.5 Drawings. Drawings listed in Section 2 of this specification under the heading US Army Armament Research and Development Command (ARRADCOM) may also include drawings prepared by, and identified as, Edgewood Arsenal, Frankford Arsenal, Rock Island Arsenal or Picatinny Arsenal drawings. Technical data originally prepared by these activities is now under the cognizance of ARRADCOM.

6.6 Changes from previous issue. Asterisks are not used in this revision to identify changes with respect to the previous issue, due to the extensiveness of the changes.

Custodian:
ARMY-AR

Preparing Activity:
ARMY-AR

Project Number: 1390-A198

Source: https://assist.dla.mil -- Downloaded: 202610-22T20:46Z
Check the source to verify that this is the current version before use.

STANDARDIZATION DOCUMENT IMPROVEMENT PROPOSAL

INSTRUCTIONS: This form is provided to solicit beneficial comments which may improve this document and enhance its use. DoD contractors, government activities, manufacturers, vendors, or other prospective users of the document are invited to submit comments to the government. Fold on lines on reverse side, staple in corner, and send to preparing activity. *Attach any pertinent data which may be of use in improving this document.* If there are additional papers, attach to form and place both in an envelope addressed to preparing activity. A response will be provided to the submitter, when name and address is provided, within 30 days indicating that the 1426 was received and when any appropriate action on it will be completed.
NOTE: This form shall not be used to submit requests for waivers, deviations or clarification of specification requirements on current contracts. Comments submitted on this form do not constitute or imply authorization to waive any portion of the referenced document(s) or to amend contractual requirements.

DOCUMENT IDENTIFIER *(Number)* AND TITLE

Fuze, Pd, M567 Loading, Assembling and Packing MIL-F-50988B

NAME OF ORGANIZATION AND ADDRESS OF SUBMITTER

☐ VENDOR ☐ USER ☐ MANUFACTURER

1. ☐ HAS ANY PART OF THE DOCUMENT CREATED PROBLEMS OR REQUIRED INTERPRETATION IN PROCUREMENT USE? ☐ IS ANY PART OF IT TOO RIGID, RESTRICTIVE, LOOSE OR AMBIGUOUS? PLEASE EXPLAIN BELOW.

A. GIVE PARAGRAPH NUMBER AND WORDING

B. RECOMMENDED WORDING CHANGE

C. REASON FOR RECOMMENDED CHANGE(S)

2. REMARKS

SUBMITTED BY *(Printed or typed name and address — Optional)*

TELEPHONE NO.

DATE

DD FORM 1 OCT 76 1426 EDITION OF 1 JAN 72 WILL BE USED UNTIL EXHAUSTED.

Source: https://assist.dla.mil -- Downloaded: 202640-22T20:46Z
Check the source to verify that this is the current version before use.