INCH POUND

MIL-G-48062C (AR)
AMENDMENT 5
12 April 1993
SUPERSEDING
AMENDMENT 4
21 November 1985

MILITARY SPECIFICATION

GRENADE, HE, G.P., M46
LOADING AND ASSEMBLING

This amendment forms a part of Military Specification MIL-G-48062C (AR), dated 4 January 1982, and is approved for use by the U.S. Army Armament, Munitions, and Chemical Command, and is available for use by all Departments and Agencies of the Department of Defense.

PAGE 2

2.1: Under US ARMY ARMAMENT RESEARCH AND DEVELOPMENT CENTER, add the following:

"PRODUCT AND PACKAGING DRAWINGS

9349337 - Packing and Marking for Box Outer for Grenade: M42, M46 and M77"

PAGE 3

3.2: Add "(see 6.12)" at the end of paragraph.

3.2.1: Add the following new paragraph:

"3.2.1 Lead cup assembly. The lead cup assembly shall be free of all splits or cracks."

DISTRIBUTION STATEMENT A. Approved for public release; distribution is unlimited.

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:11Z
Check the source to verify that this is the current version before use.

* 3.3: Line 3, After Rockwell hardness of B74 minimum, Add: "or Brinell hardness of 135 minimum,"

Delete paragraph 3.3.1 and substitute:

"3.3.1 Normal standoff.

3.3.1.1 Cone configuration (Dwg. 9215347). When tested at normal standoff, the body loading assembly, Dwg. 9215372) shall penetrate a minimum of 3.00 inches of mild steel or a minimum of 2.50 inches of ammunition testing plate.

3.3.1.2 Liner configuration (Dwg. 9349371). When tested at normal standoff, the body loading assembly, (Dwg. 9215371) shall penetrate a minimum of 4.00 inches of mild steel or a minimum of 3.25 inches of ammunition testing plate."

Delete paragraph 3.3.2 and substitute:

"3.3.2 Modified standoff.

3.3.2.1 Cone configuration. When tested at a standoff distance, which is 4 1/4 + 1/16 inches greater than the normal standoff distance, the body loading assembly shall penetrate a minimum of 5.50 inches of mild steel or a minimum of 4.50 inches of ammunition testing plate.

3.3.2.2 Liner configuration. When tested at a standoff distance, which is 3 1/2 + 1/16 inches greater than the normal standoff distance, the body loading assembly shall penetrate a minimum of 7.00 inches of mild steel (2 blocks - 5.50 and 1.50 inches) or a minimum of 5.5 inches of ammunition testing plate (2 blocks - 4.50 and 1.00 inches)."

4.3.1: Add the following first article sample items:

"Packable slider lock 9329680 30"

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:11Z
Check the source to verify that this is the current version before use.

PAGE 5

4.3.2, Table I: Under the heading of Body Loading Assy, delete "3.2.1" and substitute "3.2" and delete "4.5.5.1" and substitute "4.5.5" for unseating force of cone swage. Delete "4.5.5.2 or 4.5.5.3" and substitute "4.5.5" for test for presence of caked explosive entrapped in groove.

Add the following inspection:

"Packable slider lock (Dwg. 9329680), Examination for defects per 4.4.2.9 30 3.2"

PAGE 6

Delete paragraph 4.3.3 and substitute:

"4.3.3 Rejection. See MIL-A-48078 (AR).

4.3.3.1 Cone configuration. In addition, if any body fuze assembly fails the normal standoff static penetration test, or if two (2) or more body fuze assemblies fail the modified standoff static penetration test, or if two (2) or more samples fail the functioning test, the first article sample shall be rejected.

4.3.3.2 Line configuration. In addition, if any body fuze assembly fails the normal standoff static penetration test, or if the sample (30) tested at a modified standoff fails to meet the accept/reject criteria as specified in paragraph 4.4.3.5, or if two (2) samples fail the functioning test, the first article sample shall be rejected."

PAGE 10

* 4.4.2.4 Delete in its entirety and substitute included paragraph 4.4.2.4.

PAGES 13 and 14

* 4.4.2.6 Delete in its entirety and substitute included pages 13 and 14, paragraph 4.4.2.6.

Add the following new paragraphs 4.4.2.7; 4.4.2.8 and 4.4.2.9 as included, pages (14a), (14b) and (14c).

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:11Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE	SHEET 1 OF 2	DRAWING NUMBER
4.4.2.4	Body Loading Assembly		9215372
			NEXT HIGHER ASSEMBLY: 9215371

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical					
1	Evidence of any crack in body		100%	3.2	Visual or Gage (See 4.5.8)
2	Lead cup assembly split or cracked		100%	3.2.1	Visual
Major					
101	Unseating force of cone swage	Note a		3.2	4.5.5
102	Test for presence of caked explosive entrapped in groove	Note a		3.2	4.5.5
103	Distance from open end to largest cone basic diameter		0.40%	3.2	Gage
104	Distance from largest cone basic diameter to smallest cone basic diameter		0.40%	3.2	Gage
105	Runout of cone at basic length		0.40%	3.2	Gage
106	Largest outside diameter, max.		0.40%	3.2	Gage
107	Lead cup assembly above or excessively below flush		0.40%	3.2	Gage
108	Cone swage missing, incomplete or improper		0.40%	3.2	Visual
109	Any part cracked, dented, distorted or missing		0.40%	3.2	Visual
110	Static penetration test, modified standoff	30/per lot	4.4.3.5	3.3.2	4.5.6.2
111	Static penetration test, normal standoff	30/per lot	4.4.3.6	3.3.1	4.5.6.1

NOTES: a: For each test randomly select 50 samples per lot or select 2 samples per machine at the start of production each day and 2 samples per machine after every 4 hours of production or portion thereof. Accept no failures and reject on 1 failure.

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:11Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE		SHEET 1 OF 2		DRAWING NUMBER
4.4.2.6	Grenade				9215370
					NEXT HIGHER ASSEMBLY
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical					
1	Safety pin of fuze missing or damaged to the extent that the slider would not be restrained or subsequent production operations will be hindered		100%	3.2	Visual or Gage
2	Slide protruding from fuze indicating armed or partially armed condition		100%	3.2	Visual
3	Slider lock broken, cracked, incomplete or missing		100%	3.2	Visual
4	Safety clip of fuze missing, damaged, or double end not protruding beyond end of fuze tunnel	Note c	100%	3.2	Visual
5	Slider lock improperly positioned such that slider is not restrained		100%	3.2	Visual
Major					
101	Arming screw not free to rotate		0.40%	3.2	Visual/Manual
102	Evidence of loose or incorrectly positioned tape		0.40%	3.2	Visual
104	Arming screw clinch missing, incomplete or not properly centered	Note e	0.40%	3.2	Visual
105	Fuze housing cracked or deformed		0.40%	3.2	Visual
106	Stud clinch cracked, split, missing, incomplete or not properly centered		0.40%	3.2	Visual
107	Washer missing	Note e	0.40%	3.2	Visual or Gage

NOTES: a: 2 samples (See 4.5.4.1) per 1800 grenade assemblies produced on each machine, accept on 0 reject on 1 failure.
e: Requires slider lock removal if slider lock is automatically assembled during the fuze assembly operation.

Source: https://assist.dla.mil -- Downloaded: 2026-02-22T19:11Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE		SHEET 2 OF 2		DRAWING NUMBER
4.4.2.6	Grenade				9215370
					NEXT HIGHER ASSEMBLY
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
108	Unthreading torque test of clinched arming screw	Note a		3.2	4.5.4.2
109	Arming test of fuze slide	Note a		3.4	4.5.4.3
110	Drop load and torque test of arming screw clinch	Note a		3.2	4.5.4.4
111	Pull test of clinched studs	Note a		3.2	4.5.4.5
112	Functioning	Note b		3.2	4.5.7/92244981,9225396, 9202784, 9202788
113	Evidence of gap between fuze housing and cover or fuze cover and grenade cap or loose fuze stake		0.40%	3.2	Visual/Manual
114	Height from the shoulder of grenade body to bottom of wound ribbon (two places)		0.40%	3.2	Gage
115	Entire washer not within tape overlap area		0.40%	3.2	Visual
Minor 201	Evidence of poor workmanship		0.65%	3.9	Visual

NOTES: b: 50 samples per lot or 30 samples per 4 hours production, accept on 1 reject on 2 failures.
c: Applies only if slide lock is not assembled immediately after tape winding operation.

Source: https://assist.dla.mil - (24) Downloaded: 2026-10-22T19:11Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-G-48062C (AR)
AMENDMENT 5

PARAGRAPH	TITLE	SHEET	DRAWING NUMBER
4.4.2.7	Packing and Marking for Box, Fiberboard for Grenade, GP: M42, M46 and M77	1 OF 1	9349336
			NEXT HIGHER ASSEMBLY: 9349337

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Partitions missing		0.40%	3.2	Visual
102	Tubes missing		0.40%	3.2	Visual
103	Barrier bag torn, punctured or heat seal incomplete		0.40%	3.2	Visual
104	Box damaged, exposing contents		0.40%	3.2	Visual
105	Corners not blunted		0.40%	3.2	Visual
Minor					
201	Contents loose		0.65%	3.2	Manual
202	Box marking missing, incomplete or illegible		0.65%	3.2	Visual
203	Barrier bag marking missing, incomplete or illegible		0.65%	3.2	Visual

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-02-22T19:11Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE	SHEET	DRAWING NUMBER
4.4.2.8	Packing and Marking for Box, Outer for Grenade: M42, M46 and M77	1 OF 1	9349337
			NEXT HIGHER ASSEMBLY

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Contents loose		0.40%	3.2	Manual
102	Box damaged, exposing contents		0.40%	3.2	Visual
103	Strapping missing (wood box only)		0.40%	3.2	Visual
104	Seal missing (wire bound box only)		0.40%	3.2	Visual
Minor					
201	Marking missing, incomplete or illegible		0.65%	3.2	Visual

NOTES:

Source: https://assist.dla.mil - 8 Downloaded: 2026-10-22T19:11Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE	SHEET 1 OF 1	DRAWING NUMBER
4.4.2.9	Packable Slider Lock		9329680
			NEXT HIGHER ASSEMBLY 9215370

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical					
1	Locking tab cracked, incomplete or missing		100%	3.2	Visual
Major					
101	Profile of minimum interior dimensions undersize		0.40%	3.2	Gage
102	Location of locking tab		0.40%	3.2	Gage
103	Length of locking tab		0.40%	3.2	Gage
104	Location of safety pin hole		0.40%	3.2	Gage
105	Width of safety pin hole		0.40%	3.2	Gage
106	Length of safety pin hole		0.40%	3.2	Gage
107	Pull test, max.		0.40%	3.2	4.5.9
108	Pull test, min.	(a)		3.2	4.5.9
109	Hardness test	(b or c)		3.2	4.5.10
Minor					
201	Width		0.65%	3.2	Gage
202	Thickness		0.65%	3.2	Gage
203	Protective coating incomplete or missing		0.65%	3.2	Visual
204	Evidence of poor workmanship		0.65%	3.9	Visual

NOTES: (a) The same sample from Major 107, accept on 0 - reject on 1.
(b) 25 samples per 4 hours production, accept on 0 - reject on 1, by the producer.
(c) When alternate material (Martensite steel) is used apply special insp level S-4, AQL 0.15%. Mfg's certification of hardness for preheat treated material is required.

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:11Z
Check the source to verify that this is the current version before use.

* Delete paragraph 4.4.3.5 in its entirety (which was added in a previous amendment) and substitute the following new paragraphs 4.4.3.5, 4.4.3.5.1, 4.4.3.5.2 and 4.4.3.6.

"4.4.3.5 Static penetration test of body loading assembly (modified standoff) major defect. The accept/reject criteria for this test are given in paragraph 4.4.3.5.1 for body loading assemblies with the trumpet liner shaped charge (dwg. 9349370) and paragraph 4.4.3.5.2 for body loading assemblies with the straight wall cone shaped charge (dwg. 9215342). If the test sample fails, another 30 samples from the same lot shall be selected for static penetration testing at normal standoff (paragraph 4.4.2.4, Major Defect 111). If this additional sample fails the normal standoff requirements, the lot shall be rejected. If the sample passes the normal standoff requirements, the lot shall be accepted, and the test results (both modified and normal standoff) shall be forwarded to the technical agency for informational purposes see 6.13).

4.4.3.5.1 Penetration test (liner) If mild steel test blocks are used, an observation shall be made first of the total number of penetrations of the 7.00 inch block assembly and then of the total number of penetrations of the 5.50 inch test block. Accept on 19 failures, reject on 20 failures for the 7.00 inch block assembly and accept on 2 failures, reject on 3 failures for the 5.50 inch block.

If ammunition test plate blocks are used, an observation shall be made first of the total number of penetrations of the 5.50 inch block assembly and then of the total number of penetrations of the 4.50 inch block. Accept on 19 failures, reject on 20 failures for the 5.50 inch block assembly and accept on 2 failures, reject on 3 failures for the 4.50 inch block.

4.4.3.5.2 Penetration test (cone). Accept on 2 failures, reject on 3 failures.

Source: https://assist.dla.mil -- Downloaded: 202610-22T19:11Z
Check the source to verify that this is the currentversion before use.

4.4.3.6 Static penetration test of body loading assembly (normal standoff) major defect. An adequate thickness of test block shall be used such that the entire depth of penetration is captured. The depth of penetration shall be determined by x-ray or other technique approved by the technical agency. From the test samples fired, the average and standard deviation of the penetration depths shall be computed. Each body load assembly shall meet the requirements of 3.3.1, and the average penetration minus 3 times the standard deviation shall be greater than the minimum requirement specified in 3.3.1."

PAGE 18

4.5.4.1: Add at the end of paragraph:

"After fuze assembly it is mandatory to re-insert a safety clip in the fuze prior to the transferring of the sample to the test site. If the slider lock is automatically assembled during the fuze assembly operation, then a removal of the slider lock is necessary to re-insert the safety clip."

PAGE 19

4.5.4.5: Delete the last sentence "If the fuze loosens as evidence by gap..." and replace with the following:

"The sample shall be removed from the fixture and inspected for a gap around the studs between the fuze housing and the cover, and between the fuze cover and the grenade gap. A separating force shall be applied manually to the fuze grenade assembly while gaging. If the sample exceeds the gap permitted on the applicable drawing, the sample shall be classed defective."

4.5.5 and 4.5.5.1: Delete in their entirety and substitute the following:

"4.5.5 Unseating force test of cone swage and test for presence of entrapped powder of body loading assembly.

Source: https://assist.dla.mil -- Downloaded: 202640-22T19:11Z
Check the source to verify that this is the currentversion before use.

4.5.5.1 Preparation of sample items and test procedure for unseating force.

The quantity of body loading assemblies shall be cut in two, in a plane perpendicular to the longitudinal axis of the body. The cut shall be located at a minimum distance of .7000 inches from the open end. The cut shall be made cleanly through the body wall and explosive material.

The portion of the cut sample containing the swage of the cone shall have any remaining explosive material cleaned away and then shall be mounted in an approved fixture. The load as specified on the applicable drawings shall be applied to the cone. If the cone is dislodged from its swaged position in the body loading assembly by the specified load, that body loading assembly shall be classed defective."

PAGE 20

4.5.5.2 thru 4.5.5.4: Delete in their entirety and substitute the following:

"4.5.5.2 Test for presence of entrapped powder in body loading assembly. The test may be accomplished by one of the following procedures.

a. Alternate 1. The quantity of body loading assemblies shall be cut in a plane perpendicular to the axis of the body at a minimum distance of .700 inches from the open end. The cut shall be made cleanly through the body wall, cone and filler material.

The ring containing the base end of the cone shall then be cut into two semi-circular halves so that the cone can be lifted out. An alternative to the above method is to cut the cone into two semi-circular halves leaving the base end of the body in ring form. The cone halves shall then be removed but without loss of any entrapped powder.

The two halves of the cone shall be lifted out and the body shall be visually examined for evidence of caked powder entrapped in the crimping groove (see 4.5.5.4).

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:11Z
Check the source to verify that this is the current version before use.

b. Alternate 2. The quantity of body loading assemblies shall be cut on the longitudinal axis in two halves. The cut shall be made cleanly through the body wall, the explosive material, and cone. The sectioned cone in each half shall be lifted out and the body shall be visually examined for evidence of caked powder entrapped in the crimping groove (see 4.5.5.4).

4.5.5.3 Combined testing of force test and test for entrapped powder (alternative method). The force test and test for entrapped powder may be combined, provided the contractor uses powder nests or equivalent loading aids to reduce the occurrence of entrapped powder during grenade body loading. To use this alternative the contractor must, prior to use, request approval from the procuring agency and furnish documentation of the method planned to reduce the possibility of entrapped powder. For this combined test the same samples are used for both the force test and entrapped powder test. After having passed the 2000 lb. force requirement, the load shall be increased until the cone is dislodged from the grenade body. The grenade body shall be examined for evidence of powder that had been entrapped in the crimping groove (see 4.5.5.4).

4.5.5.4 Reject criteria of the test for presence of entrapped powder in body loading assembly. The body loading assembly shall be cause for the rejection, if the test reveals any of the following:

a. The explosive material fills the crimping groove between upper and lower swaging ridge in excess of 30 degrees of the circumference and it is either continuous or additive.

b. The presence of explosive material in the crimping groove is in excess of 90 degrees of the circumference and it is either continuous or additive.

4.5.5.5 Disposition. If any body loading assembly fails to comply with any of these tests the production quantity represented by the test sample shall be rejected."

Source: https://assist.dla.mil -- Downloaded: 202610-22T19:11Z
Check the source to verify that this is the current version before use.

* 4.5.6.1 Delete second sentence and add the following to the end of first sentence:

"and when a lot fails the modified penetration test."

Delete paragraph 4.5.6.2 and substitute:

"4.5.6.2 Modified standoff.

4.5.6.2.1 Cone configuration. Each body loading assembly to be subjected to this test shall be set into a tube or other approved holding device such that the normal standoff distance is increased by the modified standoff distance (see 3.3). The block, of material and height in accordance with 3.3, shall measure 2 1/2 + 1/16 inches wide and a minimum of 18 inches long. The block shall be placed on a firm horizontal surface with 2 1/2 inch width uppermost and the body loading assembly (with increased standoff) placed on it so the centerline of the cone is 2 inches from the end (End A). Each subsequent shot is to be located a distance of 2 inches from the centerline of the previous hole and the centerline of the last (eighth) shot for that surface shall be located a minimum of 2 inches from the opposite end. The block shall then be turned over (180°) and the centerline of the cone shall be located 3.00 inches from the end (End A). Each subsequent shot is to be located a distance of 2 inches from the centerline of the previous hole, and the centerline of the last (fifteenth) shot shall be located a minimum of 3 inches from the opposite end. The depth of shots failing to penetrate the entire block height shall be measured with a depth gage or other probe. Should any measurement fail to comply with the specified minimum depth requirement, and lot acceptance is dependent upon the result of that shot, the depth shall again be measured, using radiographic means.

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:11Z
Check the source to verify that this is the current version before use.

4.5.6.2.2 Liner configuration. Each body loading assembly to be subjected to this test shall be set into a tube or other approved holding device such that the normal standoff distance is increased by the modified standoff distance (see 3.3). The test blocks, of material and height in accordance with 3.3, shall measure 2 1/2 + 1/16 inches wide and a minimum of 18 inches long. The assembly interface surface of the blocks shall be free of burrs and high spots which would prevent a good flush contact between the surfaces. The block assembly shall be placed on a firm horizontal surface (thinner block on bottom) with 2 1/2 inch width uppermost and the body loading assembly with increased standoff placed on it so the centerline of the liner is 2 inches from the end (End A). Each subsequent shot is to be located a distance of 2 inches from the centerline of the previous hole and the centerline of the last (eighth) shot shall be located a minimum of 2 inches from the opposite end of the block. The top block shall then be turned over 180°) and the centerline of the liner be located 3.00 inches from the end (End A). Each subsequent shot is to be located a distance of 2 inches from the centerline of the previous hole, and the centerline of the last (fifteenth) shot shall be located a minimum of 3 inches from the opposite end. The depth of shots failing to penetrate the applicable block height shall be measured with a depth gage or other probe. Should any measurement fail to comply with the specified minimum depth requirement, and lot acceptance is dependent upon the result of that shot, the depth shall again be measured, using radiographic means.

NOTE: The above is a recommended test procedure. Requests for the use of alternate procedures shall be submitted to Commander, US ARDEC, ATTN: SMCAR-QAR-Q, Picatinny Arsenal, NJ 07806-5000, for approval prior to use."

PAGE 23

4.5.9 and 4.5.10: Add the following new paragraphs:

"4.5.9 Pull test of the slider lock (non-destructive). Each sample slider lock shall be assembled to a fixture simulating a maximum dimension fuze housing and pull tested until the slider lock releases. The load shall be applied to the top of the lock in a direction away from the simulated housing. Any slider lock failing to meet the force requirement on the applicable drawing shall be classed defective.

Source: https://assist.dla.mil -- Downloaded: 202610-22T19:11Z
Check the source to verify that this is the current version before use.

4.5.10 Hardness test of the slider lock (non-destructive). This test shall be performed in accordance with ASTM-E-18 using the standard penetrator for the specified hardness scale. Readings shall be taken on the top surface of the slider lock. Any slider lock failing to meet the applicable hardness requirement shall be classed defective."

5: Delete in its entirety and substitute the following:

"5. PACKAGING (This section is not applicable to intraplant usage).

5.1 Packaging. Level A (not intended for long term storage) and Level B: Packaging shall be in accordance with Drawing 9349336.

5.2 Packing. Level A (not intended for long term storage) and Level B: Packing shall be in accordance with Drawing 9349337.

5.3 Marking. Marking of fiberboard box and bag shall be in accordance with Drawing 9349336. Outer box shall be marked in accordance with Drawing 9349337."

PAGE 24

6.4: Add to paragraph column, "4.5.9 and 4.5.10" for "Quality Inspection Test Demonstration and Evaluation Report."

PAGE 25

* Add new paragraphs 6.12 and 6.13.

"6.12 This specification has provisions for two (2) shape-charge configuration-original and improved-for LAP. The original has a plain straight wall cone and the improved has a trumpet-shape liner. If the liner is used in LAP, Dwg. 9349371 shall be referenced in place of Dwg. 9215372 and wherever the cone is noted, change to "liner", except use applicable subparagraph in paragraph 3.3.1, 3.3.2, 4.3.3, 4.5.6.2 and CD 110 in paragraph 4.4.2.4.

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:11Z
Check the source to verify that this is the current version before use.

* 6.13 Failure of the modified standoff penetration test. If a lot fails the modified standoff penetration test and subsequently passes the normal standoff penetration test, the test results shall be provided to Commander, USA AMCCOM, ARDEC, ATTN: SMCAR-QAR-Q, Picatinny Arsenal, NJ 07806-5000. Information on the lot should include as a minimum: number of failures at modified standoff, penetration depth of each failure at modified standoff, individual penetration depths at normal standoff, average and standard deviation of the penetration depths at normal standoff, and cone/liner lot number. Additional information may be requested.

Shaped charge penetration at modified standoff is highly sensitive to changes in the loading process as well as changes in the cone/liner dimensions."

The margins of this amendment are marked with an asterisk or vertical lines to indicate where changes (additions, modifications, corrections, deletions) from the previous issue were made. This was done as a convenience only and the Government assumes no liability whatsoever for any inaccuracies in these notations. Bidders and contractors are cautioned to evaluate the requirements of this document based on the entire content irrespective of the marginal notations and relationship to the last previous issue.

Custodian:
Army - AR

Preparing activity:
Army - AR

(Project 1300-A375)

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:11Z
Check the source to verify that this is the current version before use.