MIL-C-10859H
Amendment-1
21 November 1985

MILITARY SPECIFICATION

CLOTH, OXFORD, COTTON, (PERMEABLE)

This amendment forms a part of Military Specification MIL-C-10859H dated 20 March 1984, and is approved for use by all Departments and Agencies of the Department of Defense.

PAGE 1

1.2, Type I, Class 2: Delete "Natural flame resistant treated" and substitute: "Natural, flame resistant and mildew resistant treated."

PAGE 4

3.4.3: Delete and substitute:

"3.4.3 Matching. The color of the dyed cloth shall match the standard sample when viewed under filtered tungsten lamps which approximate artificial daylight having a correlated color temperature of 7000 ± 500 K, with illumination of 100 ± 20 foot candles, and shall be a good match to the standard sample under incandescent lamplight at 2300 ± 100 K."

3.5.1: Delete and substitute:

"3.5.1 Width. The width of the cloth shall be as specified (see 6.2) and shall be the minimum acceptable width inclusive of the selvage when fly shuttle looms or shuttleless with tuck-in selvage looms are used. For all other shuttleless looms the width measurement shall be made between the last warp yarn on each side excluding the protruding fringe(s)."

FSC 8305

DISTRIBUTION STATEMENT A. Approved for public release; distribution is unlimited.

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T14:30Z
Check the source to verify that this is the current version before use.

PAGE 5

3.6.2, line 3: Delete "treatment" and substitute: "and mildew resistant treatments."

3.7, line 2, after "(see 6.5)": Add, "and mildew resistant treatment."

Add the following paragraph:

"3.7.4 Mildew Resistance. The cloth shall be treated with solubilized copper-8-quinolinolate applied from an aqueous or solvent base. The finished cloth shall have a copper content of not less than 0.18 percent and not greater than 0.27 percent when tested as specified in 4.2.3."

PAGE 7

4.2.2.1, line 3: Delete "G" and substitute: "G or 1 as applicable".

4.2.2.1.1, after line 9, add the following:

"Hole, tear, or cut
Slack or tight selvages 1/

1/ To determine the presence of unnacceptable selvage conditions, the following procedure shall be observed: During the visual examination, the perch shall be stopped a minimum of three times for each roll in the sample, the tension removed and the finished cloth examined for the selvage conditions. Suspect rolls should be removed from the perch and unrolled on the floor or a table and further examined for the condition. A waviness in the selvage or significant ripples diagonally across the width of the fabric is an indication of slack or tight selvages."

PAGE 8

4.2.3, line 9: Delete, "treatment" and substitute: "and mildew resistant treatments."

PAGE 9

Table II: Add the following:

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T14:30Z
Check the source to verify that this is the current version before use.

Characteristic	Requirement paragraph	Test Method
"Mildew resistance:		
Total copper analysis	3.7.4	2050 or 2051
Fungicide	3.7.4	2060"

Custodians:

Army - GL
Navy - NU
Air Force - 99

Review activities:

Army - MD
Air Force - 82
DLA - CT

User activity:

Navy - MC

Preparing activity:

Army - GL

Project No. 8305-0040

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T14:30Z
Check the source to verify that this is the current version before use.