MIL-I-60283(MU)
AMENDMENT 1
20 July 1973

MILITARY SPECIFICATION

INITIATOR, CARTRIDGE ACTUATED, M27 ASSEMBLY

This amendment forms a part of Military Specification MIL-I-60283(MU) dated 15 April 1966.

Change "Cartridge, Initiator, M91" to "Cartridge, Impulse M91" wherever referenced.

Page 1, Para. 2.1 under "Standards" Delete "MIL-STD-414" and "MIL-STD-1167" in their entirety. Add under Drawings: "C9241115 - Box, Fiberboard, Alternative".

Page 3, Para. 4.1 Delete and substitute:

"4.1 Responsibility for inspection.-Unless otherwise specified in the contract or purchase order, the supplier is responsible for the performance of all inspection requirements as specified herein. Except as otherwise specified in the contract or order, the supplier may use his own or any other facilities suitable for the performance of the inspection requirements specified herein, unless disapproved by the Government. The Government reserves the right to perform any of the inspections set forth in the specification where such inspections are deemed necessary to assure supplies and services conform to prescribed requirements."

Page 3, Para. 4.2.1.1 Delete "or MIL-STD-414 as applicable" at end of paragraph.

Page 3, Para. 4.2.1.2 Delete and substitute:

"4.2.1.2 Size of lot.-A lot shall consist of an identifiable group of assembled initiators containing metal parts assemblies produced by a homogeneous process and loaded with accepted cartridges."

Page 6 Add Para. 4.2.2.8:

"4.2.2.8 Box, Fiberboard Alternative, Drawing C9241115.

Defect	Method of Inspection
CRITICAL	
None defined	

FSC 1377

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T00:26Z
Check the source to verify that this is the current version before use.

MAJOR

None defined

MINOR

201.	Contents loose	Manual
202.	Box broken or damaged	Visual
203.	Number of units contained incorrect	Visual
204.	Marking missing, incorrect or illegible	Visual
205.	Tape incomplete	Visual"

Page 7, Para. 4.2.3.5.1 Delete and substitute:

"4.2.3.5.1 Ballistics.-Twenty-one units shall be tested to determine compliance with 3.6.1, 3.6.2 and 3.6.3. The units shall be temperature conditioned as provided in Table III and 4.3.5.1.1. Failure of any unit to comply with the requirements of 3.6.1, 3.6.2 and 3.6.3 shall be cause for rejection of the lot.

Table III

Temperature	Sample Size
-65° to -70°F	7
65° to 75°F	7
160°to 165°F	7"

Page 8, Para. 4.3.5.1 Add to end of first sentence "and initiated by a force delivering an output equal to a M3A2 Initiator".

Page 8, Para. 5.1 Delete and substitute:

"5.1 Packing and marking.-Packing and marking shall be as specified by the procuring activity: Level A - Dwgs. C8830984 and C8830985, Level B - Dwgs. C8830984 and C9241155."

Page 8, Para. 5.2 Delete in its entirety.

Page 8, Para. 6 Delete and substitute:

"6.1 Ordering data.-Procurement documents should specify the title, number and date of this specification.

Source: https://assist.dla.mil - Downloaded: 2026-10-23T00:26Z
Check the source to verify that this is the current version before use.

6.2 A mechanical failure is defined as any deformation or breakage of a part, the occurrence of which is other than a design function.

6.3 Ignition delay is defined as the time that elapses between the firing of the pressure element and the beginning of the continuous pressure rise on the pressure time record.

6.4 Explosive Hazard Classification Information
Explosive Hazard Classification (Quantity - Distance) - Class 1
Storage Compatibility - Group B, E or N
Department of Transportation (DOT) Hazard - Class C
DOT Marking "Explosive Power Device - Class C - Handle Carefully Keep Fire Away".

Custodian:

Army - MU

Preparing Activity:

Army - MU

Project No.: 1377-A541

Source: https://assist.dla.mil -- Downloaded: 202610-23T00:26Z
Check the source to verify that this is the current version before use.