MIL-V-51496(EA)
AMENDMENT 1
6 April 1987

MILITARY SPECIFICATION

VOICEMITTER-OUTLET VALVE ASSEMBLY

This amendment forms a part of MIL-V-51496(EA), dated 15 August 1983, and is approved for use within the Chemical Research, Development and Engineering Center, Department of the Army and is available for use by all Departments and Agencies of the Department of Defense.

PAGE 1

2.1.1, Under "STANDARDS" add: "Fed. STD. No. 123 - Marking for Shipment (Civil Agencies)."

PAGE 2

2.1.2, After "DRAWINGS" delete "PUBLICATIONS".

PAGE 5

3.6.2, Delete in its entirety and substitute the following:

"3.6.2 Voicemitter assembly. DOP smoke penetration of the voicemitter-outlet valve assembly, with the opening in the valve seat and the drink tube mouthpiece sealed, shall not exceed 0.001 percent when tested as specified in 4.4.4.9."

PAGE 6

3.11, Delete last sentence and replace with "Epoxy sealer, holding the outlet valve to the frame, shall not be excessively applied so as to be evident within 1/8 inch of the outlet valve well face (frame face)."

PAGE 7

4.4.1, Add in paragraph after second sentence "A lot of diaphragm material is the quantity represented by actual physical test data, and presented at one time to the Government for agent testing."

AMSC N/A FSC 4240

DISTRIBUTION STATEMENT A. Approved for public release; distribution is unlimited.

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T21:02Z
Check the source to verify that this is the current version before use.

PAGE 9

4.4.3.3:

Delete under "(d) Frame (Drawing D5-81-111)" the following:

"102 Well taper (1°) incorrect"

Renumber "Major Defects".

PAGE 11

4.4.4.9, Change to ". . . to its neutral or rest position. Seal the drink tube mouthpiece with a plug which is dimensionally the same as 5-81-101, plunger. Mount the voicemitter in the Q127 Penetrometer (D136-42-102-7) and test for smoke penetration. The plug shall be removed after the test."

PAGE 12

Section 5, Delete in its entirety and add the following:

"5. PACKAGING

5.1 Interplant shipment (see 6.3). The Voicemitter Outlet Valve Assembly shall be unit packed and packed to provide adequate protection from physical damage from the supply source to the first receiving activity for immediate use or further processing. Shipping containers shall be in compliance with the rules and regulations applicable to the mode of transportation. Marking shall be in accordance with FED-STD-123, and shipping containers shall include the contractor's name, address, contract number, and date of manufacture.

5.2 Repair parts. When this item is being procured for storage and issue as a repair part, unit packing, packing and marking shall be as specified on SPI P5-81-292-10."

PAGE 13

6.3, Delete in its entirety and substitute the following:

"6.3 Interplant shipment. Packaging and packing for interplant shipment is for supplies and materials that do not enter the military supply system. Typical interplant shipments are shipments from a vendor to a subcontractor or a prime contractor, or from a subcontractor to a prime contractor, or from a vendor or contractor to a military arsenal or plant."

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T21:02Z
Check the source to verify that this is the current version before use.

Custodian:

Army - EA

Preparing activity:

Army - EA

(Project No. 4240-A884)

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T21:02Z
Check the source to verify that this is the current version before use.