NOTICE OF CANCELLATION

INCH-POUND

AND10141
NOTICE 3
26 February 2004
Superseding
NOTICE 2
20 February 1996

MILITARY SPECIFICATION

TEE-BULB SECTION EXTRUDED

AND10141, dated 3 March 1982, is hereby canceled. Future acquisitions for this item should refer to Society of Automotive Engineers (SAE) AMS10141, dated 01 January 1998, "TEE-BULB SECTION EXTRUDED".

(Copies of this document are available from Society of Automotive Engineers (SAE) International, 400 Commonwealth Drive, Warrendale, PA 15096-0001 or www.sae.org.)

Table I provides an example of cross-reference of cancelled AND10141 Part or Identifying Numbers (PINs) and replacement SAE-AMS10141 PINs:

TABLE I. Cross-reference data.

Cancelled document and PIN	Replacement AMS and PIN
AND10141-*[1]	AMS10141-*[1]

Footnote: *[1] represents the same dash number for AND and AMS PINs.

Custodians:
Air Force - 99

Preparing Activity:
Air Force - 84

Agent Activity:
Air Force - 99

(Project 9540-0181)

NOTE: The activities listed above were interested in this document as of the date of this document. Since organization and responsibilities can change, you should verify the currency of the information above using the ASSIST Online database at www.dodssp.daps.mil.

AMSC N/A

FSC 9540

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T14:29Z
Check the source to verify that this is the current version before use.