INCH-POUND

MIL-W-70467 (AR)
AMENDMENT 3
14 October 1992
SUPERSEDING
AMENDMENT 2
18 March 1991

MILITARY SPECIFICATION

WARHEAD, 2.75 INCH ROCKET, PRACTICE: XM274

This amendment forms a part of Military Specification MIL-W-70467 (AR), dated 15 May 1986, and is approved for use by the U.S. Army Armament, Munitions, and Chemical Command, and is available for use by all Departments and Agencies of the Department of Defense.

PAGE 1

Title: Delete "XM274" and substitute "M274".

1.1: Delete "XM274" and substitute "M274".

PAGE 2

2.1.2: Delete "XM274" and substitute "M274".

Delete "MIS-50263 Rocket, 2.75 Inch, Complete Round with MK40 and MK 4 Motor: Assembling, Packing, and Testing".

Delete "INSPECTION EQUIPMENT DRAWINGS 9201212 Envelope Drawing, Safety, and Arming Inspection Equipment".

PAGE 6

4.3.1: Delete "XM274" and substitute "M274".

Delete "Plug 9370245 15"

Add the following:

| | | |
|---|---|---|
| "Washer, Felt | 12599973 | 15 |
| Cap, Smoke Tube | 12599974 | 15 |
| Tube, Smoke | 12599976 | 15 |
| Smoke, Tube Assembly | 12699977 | 25" |


DISTRIBUTION STATEMENT A. Approved for public release; distribution is unlimited.

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T03:30Z
Check the source to verify that this is the current version before use.

PAGE 7

TABLE I: Delete "XM274" and substitute "M274".

PAGE 8

TABLE I: Delete "XM274" and substitute "M274".

Delete

| | | | |
|---|---|---|---|
| "Plug | | | |
| (Dwg. 9370245) | | | |
| Examination for defects | 15 | 3.2 | 4.4.2.8". |

PAGE 9

TABLE I: Delete "XM274" and substitute "M274".

PAGE 10

TABLE I: Delete "XM274" and substitute "M274".

PAGE 11

TABLE I: Delete "XM274" and substitute "M274".

PAGE 12

TABLE I: Delete "XM274" and substitute "M274".

Add the following:

| | | | |
|---|---|---|---|
| "Tube, Smoke | | | |
| (Dwg. 12599976) | | | |
| Examination for defects | 16 | 3.2 | 4.4.2.25 |
| Cap, Smoke Tube | | | |
| (Dwg. 12699974) | | | |
| Examination for defects | 15 | 3.2 | 4.4.2.26 |
| Washer, Felt | | | |
| (Dwg. 12599973) | | | |
| Examination for defects | 15 | 3.2 | 4.4.2.27 |
| Smoke Tube Assembly | | | |
| (Dwg. 12599977) | | | |
| Examination for defects | 25 | 3.2 | 4.4.2.28" |

PAGE 13

4.4.1: Delete "XM274" and substitute "M274".



Source: https://assist.dla.mil -- Downloaded: 202610-23T03:30Z
Check the source to verify that this is the current version before use.

PAGE 18

4.4.2.5: Under Major 101: Delete "Diameter" and substitute "Outside Diameter".

Add Major 103 as follows:

| | | | | |
|---|---|---|---|---|
| "103 | Location of Hole | 0.40% | 3.2 | Gage". |

Add Minor 201 as follows:

| | | | | |
|---|---|---|---|---|
| "201 | Inside Diameter | 0.65% | 3.2 | Gage". |

PAGE 21

4.4.2.8: Delete in its entirety.

PAGE 22

4.4.2.9: Delete Major 104 in its entirety.

Add Minor 204 as follows:

| | | | | |
|---|---|---|---|---|
| "204 | Diameter of partition hole | 0.65% | 3.2 | Gage". |

PAGE 23

4.4.2.10: Delete Major 107 in its entirety.

Add Majors 111 and 112 as follows:.

| | | | | |
|---|---|---|---|---|
| "111 | Retainer groove diameter | 0.40% | 3.2 | Gage |
| 112 | Retainer groove location | 0.40% | 3.2 | Gage". |

PAGE 27

4.4.2.13: Delete "8883686" and substitute "9215619-1".

PAGE 29

4.4.2.15: Add "-1" next to 9215619.

PAGE 34

4.4.2.20: Add "-1" next to 9215619.

PAGE 36

4.4.2.22: Add "-1" next to 9215619.



Source: https://assist.dla.mil -- Downloaded: 2026-10-23T03:30Z
Check the source to verify that this is the current version before use.

PAGE 37

4.4.2.23: Delete Minor 201 in its entirety.

PAGE 38

4.4.2.24: Delete "XM274" and substitute "M274".

PAGE 39

Add 4.4.2.25 enclosed as Page 5 (38a).
Add 4.4.2.26 enclosed as Page 6 (38b).
Add 4.4.2.27 enclosed as Page 7 (38c).
Add 4.4.2.28 enclosed as Page 8 (38d).

PAGE 41

4.5.5: Delete "4.5.5" and substitute "4.5.4".

PAGE 44

4.5.5.17: Delete "4.4.4.3 and 4.4.4.4" and substitute "4.4.5.1 and 4.4.5.2".

PAGE 46

4.5.7: Delete "or MIS-50263, or whichever is applicable".

PAGE 47

4.5.7: Delete "or MIS-50263, or whichever is applicable".

PAGE 51

4.5.12: Delete in its entirety and substitute the following:

"4.5.12 Ballistic test. The requirement for the warhead is to provide a visible signature at impact with a functional reliability of greater than 93.7% when fired with Mk 66 motors. Performance shall be evaluated by ground launching a sample of 36 M274 warheads. 12 rocket shall be conditioned at -50 F±5 F, 12 rockets at 70 F±15 F, and 12 rockets at 160 F±5 F for a minimum of 6 hours. All 36 rockets shall be fired from an M260 or M261 launcher to impact at 6000 meters. If three or more warheads fail to function the lot shall be rejected."

* 5.1: Add "when shipping the loaded S&A's to the warhead assembly site, CFR49, Parts 100-199 apply."



Source: https://assist.dla.mil -- Downloaded: 202610-23T03:30Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

# CLASSIFICATION OF DEFECTS & TESTS

MIL-W-70467 (AR)
AMENDMENT 3

| PARAGRAPH | TITLE | SHEET | DRAWING NUMBER |
|---|---|---|---|
| 4.4.2.25 | Tube, Smoke | 1 OF 1 | 12599976 |
| | | | NEXT HIGHER ASSEMBLY: 12599977 |

| CATEGORY | EXAMINATION OR TEST | NO. OF SAMPLE UNITS | AQL OR 100% | REQUIREMENT PARAGRAPH | PARAGRAPH REFERENCE /INSPECTION METHOD |
|---|---|---|---|---|---|
| Critical | None defined. | | | | |
| Major | | | | | |
| 101 | Wall thickness of radius end | | 0.40% | 3.2 | Gage |
| Minor | | | | | |
| 201 | Total length | | 0.65% | 3.2 | Gage |
| 202 | Outside diameter | | 0.65% | 3.2 | Gage |
| 203 | Wall thickness | | 0.65% | 3.2 | Gage |
| 204 | Thread pitch | | 0.65% | 3.2 | Gage |
| 205 | Evidence of poor workmanship | | 0.65% | 3.18 | Visual |

NOTES:

AMSMC Form 1570, 1 Feb 85

Replaces DRSMC-QA (D) Form 160, 1 Aug 83, which may not be used.

Source: https://assist.dla.mil - Downloaded: 2026-02-23T03:30Z
Check the source to verify that this is the current version before use.

## CLASSIFICATION OF DEFECTS & TESTS



| PARAGRAPH | TITLE | | SHEET 1 OF 1 | | DRAWING NUMBER 12599974 |
|---|---|---|---|---|---|
| 4.4.2.26 | Cap, Smoke Tube | | | | NEXT HIGHER ASSEMBLY 12599977 |
| CATEGORY | EXAMINATION OR TEST | NO. OF SAMPLE UNITS | AQL OR 100% | REQUIREMENT PARAGRAPH | PARAGRAPH REFERENCE /INSPECTION METHOD |
| Critical | None defined. | | | | |
| Major | None defined. | | | | |
| Minor | | | | | |
| 201 | Height | | 0.65% | 3.2 | Gage |
| 202 | Inside diameter | | 0.65% | 3.2 | Gage |
| 203 | Thread pitch | | 0.65% | 3.2 | Gage |
| 204 | Evidence of poor workmanship | | 0.65% | 3.18 | Visual |

NOTES:



Source: https://assist.dla.mil -- Downloaded: 2026-10-23T03:30Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

## CLASSIFICATION OF DEFECTS & TESTS

MIL-W-70467 (AR)
AMENDMENT 3

| PARAGRAPH | TITLE | SHEET | DRAWING NUMBER |
|---|---|---|---|
| 4.4.2.27 | Washer, Felt | 1 OF 1 | 12599973 |
| | | | NEXT HIGHER ASSEMBLY: 9370252 |

| CATEGORY | EXAMINATION OR TEST | NO. OF SAMPLE UNITS | AQL OR 100% | REQUIREMENT PARAGRAPH | PARAGRAPH REFERENCE /INSPECTION METHOD |
|---|---|---|---|---|---|
| Critical | None defined. | | | | |
| Major | None defined. | | | | |
| Minor | | | | | |
| 201 | Thickness | | 0.65% | 3.2 | Gage |
| 202 | Hole diameter | | 0.65% | 3.2 | Gage |
| 203 | Evidence of poor workmanship | | 0.65% | 3.18 | Visual |

NOTES:

AMSMC Form 1570, 1 Feb 85

Replaces DRSMC-QA (D) Form 160, 1 Aug 83, which may not be used.

(38c) 7

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T03:30Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

## CLASSIFICATION OF DEFECTS & TESTS

MIL-W-70467 (AR)
AMENDMENT 3

| PARAGRAPH | TITLE | | SHEET 1 OF 1 | | DRAWING NUMBER 12599977 |
|---|---|---|---|---|---|
| 4.4.2.28 | Smoke Tube Assembly | | | | NEXT HIGHER ASSEMBLY 9370252 |
| CATEGORY | EXAMINATION OR TEST | NO. OF SAMPLE UNITS | AQL OR 100% | REQUIREMENT PARAGRAPH | PARAGRAPH REFERENCE /INSPECTION METHOD |
| Critical | None defined. | | | | |
| Major | | | | | |
| 101 | Joint of smoke tube cap and smoke tube taped incorrectly (note 4) | | 0.40% | 3.2 | Visual |
| 102 | Smoke tube cap installed incorrectly | | 0.40% | 3.2 | Visual |
| Minor | | | | | |
| 201 | Weight of smoke composition | | 0.65% | 3.2 | Gage |
| 202 | Evidence of poor workmanship | | 0.65% | 3.18 | Visual |

NOTES:

AMSMC Form 1570, 1 Feb 85 Replaces DRSMC-QA (D) Form 160, 1 Aug 83, which may not be used.

Source: https://assist.dla.mil - Downloaded: 2026-10-23T03:30Z
Check the source to verify that this is the current version before use.

The margin of this amendment are marked with an asterisk or vertical lines to indicate where changes (additions, modifications, corrections, deletions) from the previous amendment were made. This was done as a convenience only and the Government assumes no liability whatsoever for any inaccuracies in these notations. Bidders and contractors are cautioned to evaluate the requirements of this document based on the entire content irrespective of the marginal notations and relationship to the last previous amendment.

Custodian:
Army-AR

Preparing activity:
Army-AR

(Project 1340-A873)



Source: https://assist.dla.mil -- Downloaded: 2026-10-23T03:30Z
Check the source to verify that this is the current version before use.