[INCH-POUND]
A-A-59547B
13 March 2024
SUPERSEDING
A-A-59547A
8 August 2005

COMMERCIAL ITEM DESCRIPTION

RELAYS, ELECTROMAGNETIC, SOCKET MODULE EXTRACTION TOOL

The General Services Administration has authorized the use of this commercial item description (CID) as a replacement for "Relays, Electromagnetic, Socket Module Extraction Tool" of MIL-PRF-6106/32 for all federal agencies.

1. SCOPE. This CID covers the general requirements for a socket module extraction tool for electromagnetic relays. Socket module extraction tool for electromagnetic relays covered by this CID are intended for commercial/industrial applications.

2. CLASSIFICATION OR IDENTIFICATION NUMBER (PIN). This CID uses a classification system which is included in the Part Identification Number (PIN) as shown in the following example (see 7.1).

AA59547	-	001
CID number		Dash number

Beneficial comments, recommendations, additions, deletions, clarifications, etc., and any data that may improve this document should be sent to: DLA Land and Maritime, ATTN: VAT, P.O. Box 3990, Columbus OH 43218–3990, or email relay@dla.mil. Since contact information can change you may want to verify the currency of the address information using the ASSIST Online database at https://assist.dla.mil/.


AMSC N/A
FSC 5945

DISTRIBUTION STATEMENT A. Approved for public release; distribution is unlimited.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T10:17Z
Check the source to verify that this is the current version before use.

3. SALIENT CHARACTERISTICS.

3.1 Interface and physical dimensions. . A socket module extraction tool for electromagnetic relays supplied to this CID shall be as specified herein (see figure 1).



Inches	mm	Inches	mm
.010	0.25	.600	15.24
.015	0.38	.885	22.48
.025	0.64	1.000	25.40
.080	2.03	1.750	44.45
.125	3.18	3.900	99.06
.250	6.35		

NOTES:
1. Dimensions are in inches.
2. Metric equivalents are given for general information.

FIGURE 1. Outline drawing, socket module extraction tool.

3.2 Material: Corrosion resistant, .037 ±.005 thick. Passivated stainless steel has been considered acceptable in the past.

3.3 Capability: The relay socket module extraction tool for electromagnetic relays shall be capable of removing modules from relay bracket mount, MIL-DTL-12883/53.

3.3 Marking. A socket module extraction tool for electromagnetic relays supplied to this CID shall be marked with the manufacturer's (MFR's) standard commercial PIN. The part number on the unit pack shall be the CID PIN.

3.4 Recycled, recovered, or environmentally preferable, or biobased materials. Recycled, recovered, or environmentally preferable, or biobased materials should be used to the maximum extent possible provided that the material meets or exceeds the operational and maintenance requirements, and promotes economically advantageous life cycle costs.

3.5 Workmanship. The relay socket module extraction tool for electromagnetic relays shall be processed in such a manner as to be uniform in quality and shall be free from other defects that will affect life, serviceability, or appearance.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T10:17Z
Check the source to verify that this is the current version before use.

4. Regulatory Requirements. The offeror/contractor is encouraged to use recovered materials to the maximum extent practicable, in accordance with 23.403 of the Federal Acquisition Regulation (FAR).

5.0 PRODUCT CONFORMANCE PROVISION

5.1 Product conformance. The products provided shall meet the salient characteristics of this CID, conform to the producer's own drawings, specifications, standards, and quality assurance practices, and be the same product offered for sale in the commercial market. The Government reserves the right to require proof of such conformance.

6.0 PACKAGING.

6.1 Preservation, packing, and marking. Preservation, packing, and marking shall be as specified in the contract or order.

7.0 NOTES.

7.1 PIN. The PIN should be used for Government purposes to buy commercial products to this CID. See section 2 for PIN format example.

7.2 Commercial and Government Entity (CAGE) code. For ordering purposes, inventory control, and submission of this socket module extraction tool for electromagnetic relays to DLA Land and Maritime under the Parts Management Advisor Team (PMAT) evaluation program, CAGE code 58536 should be used.

7.3 Source of documents.

Federal Specifications

MIL-DTL-12883/53 - Sockets and Accessories for Plug-In Electronic Components, Mounting Track, for Sockets and Electromagnetic Relays

(Copies of this document is available online at https://quicksearch.dla.mil.)

FEDERAL REGULATIONS

FAR – Federal Acquisition Regulations (FAR)

(Copies of this document is available online at https://www.acquisition.gov/far/.)

7.4 Ordering data. The contract or order should specify the following:

a. CID document number, revision, and CID PIN.

b. Product conformance provisions.

c. Packaging requirements.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T10:17Z
Check the source to verify that this is the current version before use.

7.5 Commercial products. As part of the market analysis and research effort, this CID was coordinated with the following manufacturers of commercial products. At the time of CID preparation and coordination, this manufacturer was known to have commercial products that would meet the requirements of this CID. (NOTE: This information should not be considered as a list of approved manufacturers or be used to restrict procurement to only the manufacturers shown.)

MFR's CAGE	MFR's name and address
58657	Leach International Corp 6900 Orangethorpe Ave. Buena Park, CA 90620 (714) 736-7328

7.6 Part number (P/N) supersession data. This CID supersedes the following manufacturer's P/N's as shown. This information is being provided to assist in reducing proliferation in the Government inventory system.

TABLE I. P/N supersession data.

Dash number (see table I) AA59547-	MFR's CAGE	MFR's P/N 1/
001	58657	002-3669-000

1/ The manufacturer's P/N shall not be used for procurement to the requirements of this CID. At the time of preparation of this CID, the aforementioned commercial products were reviewed and could be replaced by the CID PIN shown.

7.7 Government users. To acquire information on obtaining this socket module extraction tool for electromagnetic relays from the Government inventory system, contact DLA Land and Maritime, ATTN: (VAT), P.O. Box 3990, Columbus, OH 43218–3990, or telephone (614) 692–4481.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T10:17Z
Check the source to verify that this is the current version before use.

MILITARY INTERESTS:

Custodians:
AF - 85
DLA - CC

CIVIL AGENCY COORDINATING ACTIVITY:

GSA - FAS

Preparing Activity:
DLA-CC

Project 5945-2024-029

NOTE: The activities listed above were interested in this document as of the date of this document. Since organizations and responsibilities can change, you should verify the currency of the information above using the ASSIST Online database at https://assist.dla.mil/.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T10:17Z
Check the source to verify that this is the current version before use.