NOTICE OF CANCELLATION

INCH-POUND

MS24389F
NOTICE 2
1 December 2010
SUPERSEDING
NOTICE 1
22 April 1999

MILITARY STANDARD

# TEE, TUBE, INTERNAL THREAD ON RUN, PRECISION TYPE

MS24389F, dated 16 April 1982, is hereby cancelled. Future acquisitions for this item should refer to SAE-AS1032, " Fitting, Tee, Standard and Reducer, Bulkhead on Run, Internal Port on Run, Flared".

(Copies of these documents are available from SAE International, 400 Commonwealth Drive, Warrendale, PA 15096-0001, Tel: 877-606-7323 (inside USA and Canada) or 724-776-4970 (outside USA), www.sae.org.)

Reason for NOTICE 2: SAE inactivated Part or Identifying Number (PIN) with material code letter D for replacement parts and for new design to use code letter W. This is because code letter W is stronger in tensile strength than code letter D. This is based on the previous PA's revision, as a result of lessons learned. Plus to add back material code letter S for replacement parts and for new design to use code letter R. The code letter R is better for applications requiring higher temperature.

Table l provides a detailed cross-reference of cancelled MS24389F PINs and replacement SAE-AS1032 PINs.

CAUTION: The supersession information is valid as of the date of this notice and may be superseded by subsequent revisions of the superseding document.

## CONCLUDING MATERIAL

Custodians:
Army - AV
Navy - AS
Air Force - 99
DLA - CC

Preparing activity:
DLA - CC

(Project 4730-2010-051)

Review activities:
Army - AR, CR4
Navy - MC, SA
Air Force - 11, 71

NOTE: The activities listed above were interested in this document as of the date of this document. Since organizations and responsibilities can change, you should verify the currency of the information above using the ASSIST Online database at https://assist.daps.dla.mil.

AMSC N/A

FSC 4730

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T14:53Z
Check the source to verify that this is the current version before use.

TABLE I. MS24389F to SAE-AS1032, cross-reference data.

| Cancelled AN PIN | Tube Size | Replacement AS PIN | New Design | Cancelled AN PIN | Tube Size | Replacement AS PIN | New Design |
|---|---|---|---|---|---|---|---|
| MS24389-2 | .125 | AS1032-020202 | | MS24389-8 | .500 | AS1032-080808 | |
| MS24389D2 | .125 | AS1032D020202 | AS1032W020202 | MS24389D8 | .500 | AS1032080808 | AS1032W080808 |
| MS24389J2 | .125 | AS1032J020202 | | MS24389J8 | .500 | AS1032J080808 | |
| MS24389K2 | .125 | AS1032K020202 | | MS24389K8 | .500 | AS1032K080808 | |
| MS24389S2 | .125 | AS1032S020202 | AS1032R020202 | MS24389S8 | .500 | AS1032S080808 | AS1032R080808 |
| MS24389T2 | .125 | AS1032T020202 | | MS24389T8 | .500 | AS1032T080808 | |
| MS24389W2 | .125 | AS1032W020202 | | MS24389W8 | .500 | AS1032W080808 | |
| MS24389-3 | .188 | AS1032-030303 | | MS24389-10 | .625 | AS1032-101010 | |
| MS24389D3 | .188 | AS1032D030303 | AS1032W030303 | MS24389D10 | .625 | AS1032D101010 | AS1032W101010 |
| MS24389J3 | .188 | AS1032J030303 | | MS24389J10 | .625 | AS1032J101010 | |
| MS24389K3 | .188 | AS1032K030303 | | MS24389K10 | .625 | AS1032K101010 | |
| MS24389S3 | .188 | AS1032S030303 | AS1032R030303 | MS24389S10 | .625 | AS1032S101010 | AS1032R101010 |
| MS24389T3 | .188 | AS1032T030303 | | MS24389T10 | .625 | AS1032T101010 | |
| MS24389W3 | .188 | AS1032W030303 | | MS24389W10 | .625 | AS1032W101010 | |
| MS24389-4 | .250 | AS1032-040404 | | MS24389-12 | .750 | AS1032-121212 | |
| MS24389D4 | .250 | AS1032D040404 | AS1032W040404 | MS24389D12 | .750 | AS1032D121212 | AS1032W121212 |
| MS24389J4 | .250 | AS1032J040404 | | MS24389J12 | .750 | AS1032J121212 | |
| MS24389K4 | .250 | AS1032K040404 | | MS24389K12 | .750 | AS1032K121212 | |
| MS24389S4 | .250 | AS1032S040404 | AS1032R040404 | MS24389S12 | .750 | AS1032S121212 | AS1032R121212 |
| MS24389T4 | .250 | AS1032T040404 | | MS24389T12 | .750 | AS1032T121212 | |
| MS24389W4 | .250 | AS1032W040404 | | MS24389W12 | .750 | AS1032W121212 | |



Source: https://assist.dla.mil -- Downloaded: 2026-10-23T14:53Z
Check the source to verify that this is the current version before use.

TABLE I. MS24389F to SAE-AS1032, cross-reference data - Continued.

| Cancelled AN PIN | Tube Size | Replacement AS PIN | New Design | Cancelled AN PIN | Tube Size | Replacement AS PIN | New Design |
|---|---|---|---|---|---|---|---|
| MS24389-5 | .312 | AS1032-050505 | | MS24389-16 | 1.000 | AS1032-161616 | |
| MS24389D5 | .312 | AS1032 D050505 | AS1032 W050505 | MS24389D16 | 1.000 | AS1032 D161616 | AS1032 W161616 |
| MS24389J5 | .312 | AS1032 J050505 | | MS24389J16 | 1.000 | AS1032 J161616 | |
| MS24389K5 | .312 | AS1032 K050505 | | MS24389K16 | 1.000 | AS1032 K161616 | |
| MS24389S5 | .312 | AS1032 S050505 | AS1032 R050505 | MS24389S16 | 1.000 | AS1032 S161616 | AS1032 R161616 |
| MS24389T5 | .312 | AS1032 T050505 | | MS24389T16 | 1.000 | AS1032 T161616 | |
| MS24389W5 | .312 | AS1032 W050505 | | MS24389W16 | 1.000 | AS1032 W161616 | |
| MS24389-6 | .375 | AS1032-060606 | | MS24389-20 | 1.250 | AS1032-202020 | |
| MS24389D6 | .375 | AS1032 D060606 | AS1032 W060606 | MS24389D20 | 1.250 | AS1032 D202020 | AS1032 W202020 |
| MS24389J6 | .375 | AS1032 J060606 | | MS24389J20 | 1.250 | AS1032 J202020 | |
| MS24389K6 | .375 | AS1032 K060606 | | MS24389K20 | 1.250 | AS1032 K202020 | |
| MS24389S6 | .375 | AS1032 S060606 | AS1032 R060606 | MS24389S20 | 1.250 | AS1032 S202020 | AS1032 R202020 |
| MS24389T6 | .375 | AS1032 T060606 | | MS24389T20 | 1.250 | AS1032 T202020 | |
| MS24389W6 | .375 | AS1032 W060606 | | MS24389W20 | 1.250 | AS1032 W202020 | |



Source: https://assist.dla.mil -- Downloaded: 2026-10-23T14:53Z
Check the source to verify that this is the current version before use.