MIL-T-12354F
29 July 1988
SUPERSEDING
MIL-T-12354E
15 June 1984

MILITARY SPECIFICATION

TENT, ARCTIC, 10 MAN

This specification is approved for use by all Departments and Agencies of the Department of Defense.

1. SCOPE

1.1 Scope. This document covers a pole-supported six-sided pyramidal tent fabricated of wind-resistant, cotton sateen cloth. A fire-resistant insulating liner and a protective cover for the tent and components are provided with the tent.

2. APPLICABLE DOCUMENTS

* 2.1 Government documents.

2.1.1 Specifications, standards, and handbooks. The following specifications, standards, and handbooks form a part of this specification to the extent specified herein. Unless otherwise specified, the issues of these documents shall be those listed in the issue of the Department of Defense Index of Specifications and Standards (DODISS) and supplement thereto, cited in the solicitation.

SPECIFICATIONS

FEDERAL

* A-A-203 - Paper, Kraft, Untreated
T-C-571 - Cord, Cotton; General and Special Purpose, Sash and Venetian Blind
* T-T-871 - Twine, Cotton, Wrapping

* Beneficial comments (recommendations, additions, deletions) and any pertinent data which may be of use in improving this document should be addressed to: U.S. Army Natick Research, Development and Engineering Center, Natick, MA 01760-5014 by using the self-addressed Standardization Document Improvement Proposal (DD Form 1426) appearing at the end of this document or by letter.

AMSC/N/A FSC 8340

* DISTRIBUTION STATEMENT A. Approved for public release; distribution is unlimited.

Source: https://assist.dla.mil -- Downloaded: 202610-17T22:44Z
Check the source to verify that this is the current version before use.

T-T-911	-	Twine, Fibrous, Jute
V-F-106	-	Fasteners, Slide, Interlocking
V-T-285	-	Thread, Polyester
QQ-W-321	-	Wire, Copper Alloy
TT-P-595	-	Preservation Coating, Canvas
CCC-C-429	-	Cloth, Osnaburg, Cotton
CCC-C-467	-	Cloth, Burlap, Jute (or Kenaf)
DDD-L-20	-	Label; for Clothing, Equipage, and Tentage, (General Use)
GGG-N-202	-	Needle, Sailmaker's
PPP-B-601	-	Boxes, Wood, Cleated-Plywood
PPP-T-42	-	Tape, Pressure-Sensitive Adhesive, Packaging/Paper

MILITARY

MIL-F-495	-	Finish, Chemical, Black, for Copper Alloys
MIL-C-496	-	Clips, End, Strap
MIL-P-500	-	Plates, Tent, Peak and Ridge
MIL-P-501	-	Pins, Tent, Metal
MIL-W-530	-	Webbing, Textile, Cotton, General Purpose, Natural or in Colors
MIL-H-1608	-	Hooks, Tent
MIL-L-1709	-	Lines, Tent
MIL-P-1716	-	Poles, Tent, Telescopic, Adjustable 5-Feet to 9-Feet, Magnesium
MIL-S-1734	-	Slips, Tent Line
MIL-R-2327	-	Rings, Connecting, Round
MIL-C-2399	-	Cement, Liquid, Tent Patching
MIL-R-3390	-	Rings, Dee
MIL-C-3395	-	Cloth, Netting; Nylon or Polyester
MIL-F-10884	-	Fasteners, Snap
MIL-L-11075	-	Loops, Strap Fastener
MIL-C-12095	-	Cloth, Wind-Resistant Sateen, Cotton; Fire and Water Resistant
MIL-G-16491	-	Grommet, Metallic
MIL-T-40625	-	Tubing, Bias Sewn (Burlap or Osnaburg) Cloth
MIL-S-43002	-	Shield, Stovepipe, Tent, Nonmetallic
MIL-C-43006	-	Cloth Strip, Laminated or Coated
MIL-C-43256	-	Cord, Polyester, Solid Braid
MIL-T-43333	-	Tent Liner, General Purpose, Small and Arctic, 10-Man
MIL-T-43566	-	Tape, Textile, Cotton or Polyester, General Purpose, Natural or in Colors
MIL-C-43627	-	Cloth, Duck, Cotton, Plied Yarns, Fire, Water, Weather and Mildew Resistant Treated, Lightdry Finish
MIL-W-43638	-	Webbing, Textile, Woven, for Tent Framing

Source: https://assist.dla.mil -- Downloaded: 202610-17T22:44Z
Check the source to verify that this is the current version before use.

MIL-S-43770/10 - Snap Hooks, Cast Body, Fixed Loop Eye w/o Roller, Flat Spring Closure, Wide Mouth
MIL-W-44049 - Webbing, Textile and Tape, Textile, Polypropylene, General Purpose, Natural or in Colors

STANDARDS

FEDERAL

FED-STD-751 - Stitches, Seams, and Stitchings

MILITARY

MIL-STD-105 - Sampling Procedures and Tables for Inspection by Attributes
MIL-STD-129 - Marking for Shipment and Storage

* (Copies of specifications, standards, and handbooks required by contractors in connection with specific acquisition functions should be obtained from the contracting activity or as directed by the contracting activity.)

* 2.1.2 Other Government documents, drawings, and publications. The following other Government documents, drawings, and publications form a part of this specification to the extent specified herein. Unless otherwise specified, the issues shall be those in effect on the date of the solicitation.

Department of the Army Field Manual FM 10-16 -
General Repair of Tents, Canvas and Webbing

(Copies may be obtained from the Superintendent of Documents, U.S. Government Printing Office, Washington, DC 20402.)

DRAWINGS

* U.S. ARMY NATICK RESEARCH, DEVELOPMENT, AND ENGINEERING CENTER

5-4-231 - Cover, Tent; Hexagonal, Lightweight and Arctic, 10-Man
5-4-284 - Tent Arctic, 10-Man; Illustrations
5-4-285 - Assembly and Details
5-4-286 - Views and Details
5-4-287 - Front and Rear Details
5-4-288 - Assembled Front, Rear and Details
5-4-289 - Side Details and Sections
5-4-290 - Ventilator and Details
5-4-291 - Screen Door and Details
5-4-544 - Erection Instructions
5-4-545 - Maintenance, Striking and Folding Instructions

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T22:44Z
Check the source to verify that this is the current version before use.

5-4-580 - Repair Kit
* 5-4-1075 - Pole, Telescopic, Adjustable, 5'-0" to 9'-0", Magnesium; Details

(Copies of drawings, publications, and other Government documents required by contractors in connection with specific acquisition functions should be obtained from the contracting activity or as directed by the contracting activity.)

* 2.2 Other publications. The following documents form a part of this specification to the extent specified herein. Unless otherwise specified, the issues of the documents which are DOD adopted shall be those listed in the issue of the DODISS specified in the solicitation. Unless otherwise specified, the issues of documents not listed in the DODISS shall be the issues of the nongovernment documents which are current on the date of the solicitation.

AMERICAN SOCIETY FOR TESTING AND MATERIALS (ASTM)

D 2016 Standard Test Methods for Moisture Content of Wood

D 3951 - Standard Practice for Commercial Packaging

(Copies should be obtained from the American Society for Testing and Materials, 1916 Race Street, Philadelphia, PA 19103.)

(Nongovernment standards and other publications are normally available from the organizations which prepare or which distribute the documents. These documents also may be available in or through libraries or other informational services.)

* 2.3 Order of precedence. In the event of a conflict between the text of this specification and the references cited herein, the text of this specification shall take precedence. Nothing in this specification, however, shall supersede applicable laws and regulations unless a specific exemption has been obtained.

3. REQUIREMENTS

* 3.1 First article. When specified in the contract or purchase order, a sample shall be subjected to first article inspection (see 4.3, 6.2, and 6.4).

3.2 Materials and components. (see 6.5)

3.2.1 Cloth, wind-resistant sateen, cotton. The cloth for the tent shall be Olive Green 107 and shall conform to MIL-C-12095.

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T22:44Z
Check the source to verify that this is the current version before use.

3.2.2 Cloth, cotton duck. The cotton duck for the peak reinforcement shall be dyed Olive Drab 7 and shall conform to MIL-C-43627. Requirements for colorfastness to weathering shall not apply.

3.2.2.1 Cloth, laminated. The cloth for the tent cover shall conform to type 1, class 2 of MIL-C-43006, and the color shall be camouflage green, shade #483.

3.2.3 Cloth, netting, nylon. The nylon netting for the ventilator opening and screen door shall conform to type I or II of MIL-C-3395.

3.2.4 Shield, stovepipe, tent. The flexible, silicone rubber coated stovepipe shield shall conform to MIL-S-43002.

* 3.2.5 Tape, textile, cotton. The tape shall be dyed Olive Drab 7 and shall conform to type I, class 4, 1/2 inch, 3/4 inch, 1-1/2 inch and 2 inch widths (as specified on applicable drawings) of MIL-T-43566. For covers only, polypropylene tape conforming to type 1, class 4, 3/4 inch width of MIL-W-44049 may be used as an alternate.

* 3.2.6 Webbing, textile, cotton. The webbing shall be dyed Olive Drab 7 and shall conform to type IIb, class 4, 1 inch width and type III, class 4, 5/8 inch and 1-1/2 inch widths (as specified on applicable drawings) of MIL-W-530. For covers only, polypropylene webbing conforming to type 11b, class 4, 1 inch width of MIL-W-44049 may be used as an alternate.

3.2.7 Webbing, textile, woven, low elongation. The webbing shall be natural, conforming to type I, 1 inch width of MIL-W-43638.

3.2.8 Thread, polyester.

* 3.2.8.1 Tent screens and cover. The thread shall conform to type I, class 1, sub-class B, shade S-1 (C.A. 66022) of V-T-285. The dyed thread shall show fastness to weathering equal to or better than the standard shade sample. When no standard shade sample is available, the dyed thread shall show good fastness to weathering.

* 3.2.8.2 Sizes. Thread sizes shall be as follows:

* For all stitching except zig-zag stitching, bartacking and stitching indicated by "Z" on drawings	- Size F for needle and size E for bobbin
For zig-zag stitching and bartacking	- Size E for needle and bobbin
For stitching indicated by "Z" on drawings	- Size F needle, size E for looper.

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T22:44Z
Check the source to verify that this is the current version before use.

3.2.9 Lines, tent. The tent lines shall conform to class D of MIL-L-1709 in the following types:

Type	
LII	(Intermediate eave line, corner eave line)
LIII	(Corner line) except that the length shall be 20 feet
LIV	(Door eave line)

3.2.10 Cord, polyester. The cord used for the sock lines, toggle loops and beckets shall be natural, 1/8 inch diameter cord conforming to MIL-C-43256.

3.2.11 Cord, cotton. The cord for the footstops and drip cap stiffener shall conform to type I, class 3, size No. 7 of T-C-571. The footstops shall be as shown on Drawing 5-4-285.

3.2.12 Toggles.

3.2.12.1 Toggles, wood. The wood toggles, of the design and dimensions shown on Drawing 5-4-288, shall be fabricated from uniformly dried, straight-grained lumber and shall not contain more than 15 percent moisture when tested as specified in 4.4.1.1. The toggles shall be free from knots, shakes, checks, splits, or splintery surface. Any of the following woods may be used:

Hickory	Beech	Pecan	Maple, hard
Red or White Oak	Birch	Rock Elm	Ash

3.2.12.2 Toggles, metal. The metal toggles shall be of the design and dimensions shown on Drawing 5-4-286 and shall be fabricated from brass wire conforming to alloy No. 270, half hard temper of QQ-W-321. The toggles shall be given a black chemical finish conforming to MIL-F-495.

3.2.13 Slips, tent line. The tent line slips shall conform to type II of MIL-S-1734.

* 3.2.14 Fasteners, slide interlocking. The slide fasteners shall conform to type III, style 1, size H, wire stirrup pulls of V-F-106. Slide fastener chain shall be fabricated of brass or polyester coil. The slider for the brass chain shall be brass and the slider for the polyester coil shall be die cast zinc alloy. The slide fastener tape shall be dyed to match olive drab shades S (CA 66519) and be water repellent and mildew-resistant. (Tapes made of 100 percent polyester need not be tested for mildew resistance.) The color of the tape after treatment will be considered acceptable. The tape shall show good fastness to weathering. Alternatively, the slide fastener chain shall be polyester continuous monofilament in a ladder or coil type configuration. Color of the chain shall be Olive Drab or natural finish brass and the sliders shall be brass.

3.2.15 Rings, dee. The dee rings shall conform to class 1 or 2, configuration K, 1 inch by 3/4 inch of MIL-R-3390.

Source: https://assist.dla.mil -- Downloaded: 202610-17T22:44Z
Check the source to verify that this is the current version before use.

3.2.16 Rings, connecting. The connecting rings shall conform to class 2 or 5, size 2 of MIL-R-2327.

3.2.17 Plate, peak. The peak plate shall conform to type XVIII of MIL-P-500.

3.2.18 Snaphooks. The snaphooks shall conform to MIL-S-43770/10.

3.2.19 Grommets, metallic. The grommets shall conform to type III, class 3 of MIL-G-16491 in the following sizes:

No. 1 (for connecting lug becket cord)
No. 2 (for footstops, type "B")
No. 4 (for footstops, type "A")

3.2.20 Fasteners, snap. The snap fasteners shall conform to style 2, finish 2, button 24 line size, size 1 and eyelet size 1 of MIL-F-10884.

3.2.21 Clips, end strap. The end clips shall conform to type I, class 1 or 2, size 1 inch of MIL-C-496.

3.2.22 Loops, strap fastener. The strap fastener loops shall conform to type III, style B of MIL-L-11075.

3.2.23 Hooks, tent. The tent hooks used at the peak plate shall conform to type I, size 1 inch of MIL-H-1608.

3.2.24 Tent liner. The liner for the tent shall conform to MIL-T-43333.

3.2.25 Pins, tent, metal. When required (see 6.2) the tent pins shall be type I, conforming to MIL-P-501.

3.2.26 Poles, tent, telescopic. When required (see 6.2), the magnesium, adjustable, telescopic tent pole shall conform to MIL-P-1716.

* 3.3 Construction. The construction shall conform in all respects to the drawings listed in section 2 and as specified herein.

3.3.1 Stitching, machine.

* 3.3.1.1 Stitch types. Stitch types, except bartacks, shall conform to FED-STD-751 as follows:

For all stitching, except bar-tacking, "zig-zag" stitching. Stitching indicated by "Z" on drawings, and alternatively for the attachment of slide fasteners.	- Type 301, 5 to 7 stitches per inch
For "zig-zag" stitching	- Type 304, 10 to 16 stitches per inch, 1/4 inch wide (bight)

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T22:44Z
Check the source to verify that this is the current version before use.

For stitching indicated by "Z" on drawings and alternatively for attachment of slide fasteners	- Type 401, 5 to 7 stitches per inch. Chain portion of stitching shall not appear on outside of shelter or cover.
For bartacking	- Bartack, 1/2 ± 1/16 inch long, 1/8 ± 1/16 inch wide (bight) and shall contain 28 stitches

3.3.1.2 Type 301 stitching. Ends of all stitching shall be backstitched or overstitched 1/2 inch minimum except when caught in other stitching or turned under in a hem. Thread tension shall be maintained so that there will be no loose stitching resulting in puckering of material sewn. The lock shall be embedded in the material sewn.

3.3.1.2.1 Repairs of type 301 stitching. Repairs of type 301 stitching shall be as follows:

a. When thread breaks or bobbin run-outs occur during sewing, the stitching shall be repaired by restarting the stitching a minimum of 1 inch behind the end of the stitching. 1/

b. Thread breaks or two or more consecutive skipped stitches or run-off stitches noted during inspection of the item (in-process or end item) shall be repaired by overstitching. The stitching shall start a minimum of 1 inch before the defective area (1/2 inch on box, box and cross, and W-W stitching) and continue a minimum of 1 inch beyond the defective area onto the existing stitching. Loose or excessively tight stitching shall be repaired by removing the defective stitching, without damaging the materials, and restitching in the required manner. 1/

1/ When making the above repairs, the ends of the stitching are not required to be backstitched.

3.3.1.3 Type 401 stitching. Thread tension shall be maintained so that there will be no loose stitching. Both ends of seams or stitching produced with a 401 stitch type, when not turned under a hem or held down by other stitching, shall have a 3/4 to 1 inch chain extending beyond each end. The looper (under thread) shall always be on the inside of the tent or cover. All repairs shall be made using a 301 stitch in accordance with 3.3.1.2.1 a or 3.3.1.2.1 b.

3.3.1.4 Type 304 stitching. For type 304 stitching, thread tension shall be maintained so that there will be no loose or excessively tight stitching. Repairs shall be in accordance with 3.3.1.2.1 a or 3.3.1.2.1 b except that the stitching shall over stitch the defective stitching area a minimum of three stitches onto the existing stitches.

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T22:44Z
Check the source to verify that this is the current version before use.

* 3.3.1.5 Automatic stitching. Automatic stitching machines may be used to perform any of the required stitch patterns provided the requirements of the stitch pattern, stitches per inch, size and type of thread are met, and at least three or more tying, overlapping, or backstitches are used to secure the ends of the stitching.

* 3.3.1.6 Thead ends. All thread ends that are visible on the finished item shall be trimmed to a length of not more than 1/4 inch.

* 3.3.1.7 Lubrication of thread. The addition of any lubricant to the polyester sewing thread prior to or during the sewing operation is prohibited.

* 3.3.1.8 Stitching margins. Unless otherwise specified, all stitch margins shall be 1/8, +1/16 -0 inch.

* 3.3.1.9 Bartacking. Bartacking shall be free of thread breaks or loose stitching.

* 3.3.2 Attachment of wood toggles. Wood toggles shall be attached as shown on Drawing 5-4-288.

* 3.3.3 Setting of grommets. Holes punched to receive the grommets shall be smaller than the outside diameter of the grommet barrel so that the barrel must be forced through the hole. The grommets shall be securely clinched without cutting the materials. Roll of the clinched grommet shall not contain any splits.

3.3.4 Setting of snap fasteners. If a hole is punched before inserting the male or female part of the fasteners, it shall be smaller than the outside diameter of the fastener tube so that the tube must be forced through the hole. The fasteners shall be securely clinched. Roll of the clinched eyelet of the assembled fastener component shall not contain more than three scores (splits).

3.3.5 Setting of end clips. The webbing shall be inserted the full depth of the clips. The clips shall be securely attached without cutting the webbing and the webbing shall lie flat at the point of entrance.

3.3.6 Splicing of webbing. If required, the webbing shall be spliced as shown on Drawing 5-4-289. A maximum of one splice per gore will be permitted. The minimum distance between splices in the remainder of the tent shall be 5 feet.

* 3.3.7 Splicing of cloth. There shall be no splicing of roof, wall, or tent cover panels. Splicing of reinforcements and snow cloth sections will be permitted and, if performed, shall conform to the following requirements:

Source: https://assist.dla.mil -- Downloaded: 202610-17T22:44Z
Check the source to verify that this is the current version before use.

a. Eight feet or less in length - One splice permitted;
More than 8 feet but not more than 12 feet in length - Two splices permitted;
More than 12 feet in length - Three splices permitted.

b. The shortest length of any spliced piece shal be not less than 2 feet.

c. Pieces shall be joined as shown on Drawing 5-4-289.

* 3.3.8 Splicing of Beckets. Splicing will be permitted in the tent doorways and if performed shall conform to Drawing 5-4-285 with a minimum distance of 5 feet between splices. No splice shall be in any portion of the loop.

3.3.9 Attachment of slide fasteners. Care shall be exercised to maintain specified distances between edges of fabric attached to slide fastener tape so that there will be no interference with the operation of the slider. The length of the slide fastener shall be such that after the slide fastener is sewed on, the tape shall not be puckered and the slider shall operate freely.

3.3.10 Kit, repair. The repair kit bag shall be fabricated from the material specified in 3.2.1 and of the design and dimensions shown on Drawing 5-4-580. The snap fastener on the pocket shall be as specified in 3.2.20 and the tie cord on the bag shall be as specified in 3.2.10. The bag, containing the repair kit components, shall be securely tied and placed in the repair kit pocket of each completed tent.

3.3.10.1 Components, repair. Components for each kit shall consist of the items listed in table I.

TABLE I. Repair kit components

Item	Quantity	Specification or reference
Cloth, wind-resistant sateen, cotton	1/2 yard full width	3.2.1
Thread, polyester, type I, class 1, sub-class B, size F, shade S-1, 2 ounce spool	1 spool	3.2.8
Needle, sailmaker's size 16	3	GGG-N-202
Pusher, needle	1	Drawing 5-4-580 and wood specified in 3.2.12.1

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T22:44Z
Check the source to verify that this is the current version before use.

TABLE I. Repair kit components (cont'd)

Item	Quantity	Specification or reference
Sleeve, lock, retaining	2	Drawing 5-4-1075, item 10 of MIL-P-1716
Lock, upper	1	Drawing 5-4-1075, item 7 of MIL-P-1716
Lock, lower	1	Drawing 5-4-1075, item 8 of MIL-P-1716

* 3.3.11 Wicking of sewing thread (cup test). There shall be no dripping of water through the tent stitching when the tent is tested as specified in 4.5.1. The cup test is intended to insure that non-wicking thread has been utilized and that no lubrication has been added to the polyester thread prior to or during the sewing operation.

3.3.12 Repairs. Any necessary repairs shall be effected in accordance with Department of the Army Field Manual FM 10-16, except that hand-sewn patches, or cemented patches other than as specified herein, will not be acceptable. Cemented patches on holes, cuts or tears not more than 1 inch in diameter or length, using cement specified in MIL-C-2399, shall be permitted. A maximum of three cemented patches per tent shall be allowed without prior authorization. A patch shall be large enough to overlap the damaged area with a margin of at least 3/4 inch on all sides. Cemented patches shall not be applied over seams or hardware areas. All other repairs shall require contracting officer authorization. Repairs required as a result of failure of the cup test and when authorized by the contracting officer shall be performed by treating with a compound conforming to type I, class 1 of TT-P-595 prior to retesting (see 6.7.1).

* 3.3.13 Fusing of ends of synthetic cord, webbing and tape. All ends of synthetic cord, webbing, and tape shall be fused. The apparatus used to fuse the ends shall be capable of providing sufficient heat to provide a smooth edge and with the cut ends of the yarns all fused together. Fusing of the ends shall be accomplished prior to being assembled for stitching.

* 3.3.14 Replacement of defective components. During the spreading, cutting and manufacturing process, components of the tent having material defects or damages that are classified as defects in 4.4.3 or 4.4.4 shall be removed from production and replaced with non-defective and properly matched components.

3.4 Marking. All marking and labels shall conform to DDD-L-20.

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T22:44Z
Check the source to verify that this is the current version before use.

3.4.1 Special marking. The application of the letters "US", on the tent and cover, the instructions on the door, the marking on repair kit and the nomenclature on the cover shall conform to type IV, class 9 in the size characters and in the locations shown on the drawings. Class 9 markings shall be clearly legible after subjection to accelerated weathering.

3.4.2 Identification labels. Identification labels shall be stitched to the tent and cover in the locations shown on the drawings and shall conform to type VI, class 6 and shall be 3-1/2 inches by 5-1/2 inches minimum and a blank space of at least 1-1/4 inches shall be provided on the bottom of the label for the Department of Defense inspector's stamp.

* 3.4.3 Erection instruction label. Labels of erection instructions shall conform to type VI, class 7 and shall be stitched to the tent and cover in the locations shown on the drawings. The label shall be a proportionate copy of Drawing 5-4-544 as reproduced from a glossy print of this drawing furnished by the contracting officer. The size of the label shall be, borderline to borderline, 15 ± 1/4 inches in the longer dimension, with a minimum 1/2-inch margin outside of the borderline on all sides.

* 3.4.4 Care and maintenance instruction label. Labels of care and maintenance instructions shall conform to type VI, class 7 and shall be stitched to the tent and cover in the locations shown on the drawings. The label shall be a proportionate copy of Drawing 5-4-545, as reproduced from a glossy print of this drawing furnished by the contracting officer. The size of the label shall be, borderline to borderline, 15 ± 1/4 inches in the longer dimension, with a minimum 1/2 inch margin outside of the borderline on all sides.

* 3.5 Workmanship. Cloth components shall be clean and free of holes, cuts, tears or cloth defects such as multiple floats or broken or missing yarns. Webbing and tapes shall contain no frayed or scalloped edges and rope components shall be free of cuts or breaks. Thread tension shall be maintained so that there will be no loose stitching and seam allowances shall be maintained with seams properly sewed so that no runoffs, pleats, or open seams shall result. Care shall be taken in sewing so that there shall be no needle chews. Metal components shall be free of burrs, sharp edges, corroded areas and shall not be broken or malformed. The tent shall conform to the quality of product established by this document and the occurrence of defects shall not exceed the applicable acceptable quality levels.

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T22:44Z
Check the source to verify that this is the current version before use.

4. QUALITY ASSURANCE PROVISIONS

4.1 Responsibility for inspection. Unless otherwise specified in the contract or purchase order, the contractor is responsible for the performance of all inspection requirements as specified herein. Except as otherwise specified in the contract or purchase order, the contractor may use his own or any other facilities suitable for the performance of the inspection requirements specified herein, unless disapproved by the Government. The Government reserves the right to perform any of the inspections set forth in this document where such inspections are deemed necessary to assure supplies and services conform to prescribed requirements.

* 4.1.1 Responsibility for compliance. All items must meet all requirements of sections 3 and 5. The inspection set forth in this document shall become a part of the contractor's overall inspection system or quality program. The absence of any inspection requirements in the document shall not relieve the contractor of the responsibility of assuring that all products or supplies submitted to the Government for acceptance comply with all requirements of the contract. Sampling in quality conformance does not authorize submission of known defective material, either indicated or actual, nor does it commit the Government to acceptance of defective material.

* 4.1.2 Responsibility for dimensional requirements. Unless otherwise specified in the contract or purchase order, the contractor is responsible for assuring that all specified dimensions have been met. When dimensions cannot be examined on the end item, inspection shall be made at any point, or at all points in the manufacturing process necessary to assure compliance with all dimensional requirements.

4.2 Classification of inspection. The inspection requirements specified herein are classified as follows:

a. First article inspection (see 4.3).
b. Quality conformance inspection (see 4.4).

* 4.3 First article inspection. When a first article is required (see 6.2), it shall be examined for the defects specified in 4.4.3 and 4.4.4, and tested for the characteristics specified in 4.4.5. The presence of any defect or failure to pass any test shall be cause for rejection of the first article.

4.4 Quality conformance inspection. Unless otherwise specified herein, sampling for inspection shall be performed in accordance with MIL-STD-105.

4.4.1 Component and material inspection. In accordance with 4.1, components and materials shall be inspected in accordance with all the requirements of referenced documents, unless otherwise excluded, amended, modified, or qualified in this document or applicable purchase document.

Source: https://assist.dla.mil -- Downloaded: 202610-17T22:44Z
Check the source to verify that this is the current version before use.

* 4.4.1.1 Wood toggle moisture content testing. In addition to the quality assurance provisions of the subsidiary documents, the wood toggles shall be tested for conformance to the moisture content requirements in 3.2.12.1 The moisture content shall be determined in accordance with the oven-drying or the electrical meter method referenced in ASTM D 2016. The results shall be reported to the nearest 0.1 percent for each toggle tested. The lot size shall be expressed in toggles. The sample unit shall be one toggle. The inspection level shall be S-1 and the acceptable quality level (AQL), expressed in terms of defects per hundred units, shall be 4.0.

* 4.4.2 In-process inspection. Inspection shall be made of the following operations and assemblies to establish conformance to specified requirements. Whenever nonconformance is noted, correction shall be made to the items affected and to the operation. Items which cannot be corrected shall be removed from production.

a. Holes punched to receive grommets conform to requirements in 3.3.3.

b. There shall be no lubrication of polyester thread prior to or during sewing operations in compliance with 3.3.1.7.

c. Holes punched to receive male or female parts of snap fasteners are in compliance with 3.3.4.

* 4.4.3 End item visual examination.

* 4.4.3.1 Tent with cover. The end items shall be in an erected position so that both the inside and outside of the tent can be examined, along with its cover, for defects listed in table II. The lot size shall be expressed in units of tents with covers. The sample unit shall be one tent with its cover. The inspection level shall be I and the AQL, expressed in terms of defects per hundred units, shall be 40 for major defects, 150 for major and minor A combined defects, and 250 for total (major and minor combined) defects.

* 4.4.3.2 Cover, only. The end items shall be in a position so that both the inside and outside of the cover can be examined for the applicable defects listed in table II. The lot size shall be expressed in units of covers. The sample units shall be one cover. The inspection level shall be I and the AQL, expressed in terms of defects per hundred units, shall be 6.5 for major defects, 15 for major and minor A combined defects, and 40 for total (major and minor combined) defects.

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T22:44Z
Check the source to verify that this is the current version before use.

TABLE II. End item visual defects

Examine	Defect	Classification Major	Minor A	Minor B
Fabric	Cut, tear, or hole (including exposed drill hole) greater than 1/8 inch in length or diameter:			
	- on tent	X		
	- on cover or snow cloth		X	
	Cut, tear, or hole (including exposed drill hole) 1/8 inch or less in length or diameter:			
	- more than 20 holes:			
	- on tent	X		
	- on cover or snow cloth		X	
	- more than 10 but not more than 20:			
	- on tent		X	
	- on cover or snow cloth			X
	- more than 5 but not more than 10 on tent			X
	Broken or missing yarns; multiple floats clearly visible at normal inspection distance (approximately 3 feet)		X	
* Netting	Hole, cut or tear:			
	- more than 2 inches in length	X		
	- more than 1/4 inch but not more than 2 inches in length		X	
	- 1/4 inch in diameter			X
Webbing and tape	Edge frayed or scalloped			X
Hardware	Broken	X		
	Malformed:			
	- fails to perform intended function	X		
	- but will perform intended function		X	
	Corroded area			X
	Burr or sharp edge which may cause injury in handling or damage to fabric	X		

Source: https://assist.dla.mil -- Downloaded: 202610-17T22:44Z
Check the source to verify that this is the current version before use.

TABLE II. End item visual defects (cont'd)

Examine	Defect	Classification Major	Minor A	Minor B
* Grommets	Improperly set; two or more teeth exposed (except where grommet is set as specified but is in an area of unequal thickness which prevents uniform clinching)			X
	Clinched loosely, allowing grommet to rotate in hole			X
	Clinched excessively tight, cutting fabric	X		
	Insecurely clinched; i.e. grommet or washer may become disengaged	X		
	Roll of grommet contains any (splits)			X
Tent Hooks	Hook not securely closed allowing connecting hardware to become disengaged		X	
	Set with hook portion facing roof			X
Snap hooks	Reversed; i.e. set with spring tongue facing roof in lieu of interior of tent in a downward position		X	
End clips	Not securely clinched, webbing not flat at point of insertion			X
	Clinched excessively tight cutting webbing		X	
Snap fasteners	Female components used where male components are required; fasteners fail to snap in closed position or to remain firmly closed		X	
	Roll of clinched eyelet fastener assembly contains more than three scores (splits)			X

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T22:44Z
Check the source to verify that this is the current version before use.

TABLE II. End item visual defects (cont'd)

Examine	Defect	Classification Major	Minor A	Minor B
Wood toggles	Contains knot, shake, splits, or splintery surface		X	
Cord components	Any cut; any abrasion		X	
	Eave lines, corner lines and foot-stops improperly knotted; free ends of lines not finished as specified			X
Tent pins	Not type specified	X		
Tent poles	Not as specified	X		
Seams and stitching	Open seam on stitch type 301:			
	- for more than 1/4 inch but not more than 1 inch			X
	- for more than 1 inch		X	
	Open seam on stitch type 401:			
	- one row of stitching open for 1 inch or less:			
	- on tent or cover			X
	- one row of stitching open for more than 1 inch:			
	- on roof		X	
	- on wall or cover			X
	- both rows of stitching open (not necessarily at same location):			
	- on roof	X		
	- on wall or cover		X	

NOTE: A seam shall be classified as open when one or more stitches joining a seam are broken, or when two or more skipped or run-off stitches occur. On double-stitched seams, a seam shall be classified as open when either one or both sides of seam are open.

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T22:44Z
Check the source to verify that this is the current version before use.

TABLE II. End item visual defects (cont'd)

Examine	Defect	Classification Major	Minor A	Minor B
Seams and stitching (cont'd)				
	Raw edges caught in stitching:			
	- more than 1 inch but not more than 3 inches			X
	- more than 3 inches		X	
	Thread breaks:			
	- overstitched less than 1 inch on stitch type 401			X
	- overstitched less than 1 inch on stitch type 301			X
	- overstitched less than 3 stitches on stitch type 304			X
	NOTE: Thread breaks not overstitched shall be classified as open seams.			
	Skipped stitches:			
	- overstitched less than 1-1/2 inches on stitch type 401			X
	- overstitched less than 1 inch on stitch type 301 or 304 (where two or more consecutive skipped stitches occur)			X
	NOTE: Skipped stitches not overstitched shall be classified as open seams.			
	Needle chew resulting in cut, tear, or hole (see cut, tear, or hole.)			
	One or more required rows of stitching omitted (except on boxstitching and "W" stitching)	X		
Boxstitching	Incomplete:			
	- one row of stitching omitted			X
	- two or more rows of stitching omitted		X	
	Any boxstitching less than specified length by more than 1/8 inch			X

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T22:44Z
Check the source to verify that this is the current version before use.

TABLE II. End item visual defects (cont'd)

Examine	Defect	Classification Major	Minor A	Minor B
Seams and stitching (cont'd)				
"W" stitching	Incomplete:			
	- one row of stitching omitted		X	
	- two or more rows of stitching omitted	X		
	Any "W" stitching less than specified length by more than 1 inch			X
Bartacking	Any bartacking less than specified length by more than 1/8 inch			X
Stitching ends	Overstitched less than 1/2 inch on stitch type 301 (except where ends are held down by other stitching, turned under in a hem, or where stitching is performed automatically)			X
	Secured with less than three tying, overlapping or backstitches with automatic stitching is performed			X
	Secured with less than 1/4 inch of backstitching, overstitching or an increased number of stitches per inch at the end of stitch type 304			X
Seams	Seam pleated:			
	- on roof		X	
	- on eave, on wall, or cover			X
Seam type	Wrong seam type	X		
Stitch type	Wrong stitch type	X		
Stitch tension	Loose, resulting in an exposed bobbin or top thread, for more than 6 inches		X	
	Tight, as evidenced by puckering on fabric, for more than 6 inches		X	

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T22:44Z
Check the source to verify that this is the current version before use.

TABLE II. End item visual defects (cont'd)

Examine	Defect	Classification Major	Minor A	Minor B
Seams and stitching (cont'd)				
Stitches per inch	Less than minimum specified (except panel joining seams):			
	- one stitch			X
	- two or more stitches		X	
	Less than minimum specified on panel joining seams		X	
	More than maximum specified:			
	- one stitch			X
	- two or more stitches		X	
	NOTE: Variation in the number of stitches per inch, caused by the operator speeding up the machine and pulling the fabric in order to sew over heavy places or heavy seams or in turning corners, shall be classified as follows:			
	a. Within the minor "B" defect classification - no defect			
	b. Within the minor "A" defect classification - minor "B" defect			
Stitching gage	Not as specified		X	
Stitching margin	Larger than specified:			
	- for more than 2 inches but not more than 4 inches in length			X
	- for more than 4 inches in length		X	
	Less than specified:			
	- for more than 2 inches but not more than four inches in length			X
	- for more than four inches in length		X	
Stitching indicated by "Z" on drawings	Chain portion of stitching shows on outside of tent, or cover		X	

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T22:44Z
Check the source to verify that this is the current version before use.

TABLE II. End item visual defects (cont'd)

Examine	Defect	Classification Major	Minor A	Minor B
Seams and stitching (cont'd)				
Mends, darns or patches	Repairs not in accordance with Department of the Army Field Manual FM 10-16 or not authorized by the contracting officer (see 3.3.12)	X		
Repair kit	Missing; not as specified		X	
Components and assembly	Any component omitted	X		
	Any component part not fabricated of applicable referenced material	X		
Hems	Constructed with partial turn-under when double turnunder is required		X	
	Twisted or pleated			X
Reinforcements	Improperly applied causing excessive fullness on reinforcement or reinforced part			X
	Number of splices per reinforcement more than permitted (see 3.3.7)		X	
	Spliced pieces not joined as shown on Drawing 5-4-289			X
Binding	Improperly, or loosely applied, ends not finished as specified			X
* Slider fasteners	Slider jams or fails to interlock chain	X		
	Any tape improperly assembled, causing failure of chain to effect a smooth and secure closure	X		
	Wrong length	X		
	Width not as specified	X		
	Puckering of tape	X		
	Broken or missing scoops	X		
	Thong omitted		X	

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T22:44Z
Check the source to verify that this is the current version before use.

TABLE II. End item visual defects (cont'd)

Examine	Defect	Classification Major	Minor A	Minor B
* Slide fasteners (cont'd)				
	NOTE: The inspection shall pull slide fasteners three or four times to an open and closed position to determine proper function and effectiveness of each fastener.			
Construction detail defects:				
Tent line lugs	Any lug stitched through roof only instead of through reinforcement webbing and roof reinforcement	X		
	Any part of lug single ply construction		X	
	Piece "B" improperly set, causing fullness on tent or distortion of corners		X	
Doorway flaps	Left edge of flap not stitched through door opening tape reinforcement		X	
	Top end of flap no stitched through wall, eave band and tape reinforcement		X	
	Facing improperly applied, causing fullness on flap			X
* Toggles	Toggle held in place with single turn of rope around groove or double turn not overhand knotted		X	
Toggle loops	Loops not securely stitched to flap		X	
	End of loops exposed, i.e., not turned under or not caught in stitching attaching flap to wall			X

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T22:44Z
Check the source to verify that this is the current version before use.

TABLE II. End item visual defects (cont'd)

Examine	Defect	Classification Major	Minor A	Minor B
Construction detail defects: (cont'd)				
* Beckets	Cord not continuous			X
	Any becket loose, i.e. not caught in stitching on either side		X	
	Not continuous or spliced within 6 inches of grommet			X
	Not spliced as specified			X
	More than two splices per connecting lug		X	
	Spliced cord less than 5 feet in length		X	
	Splice not centered between beckets			X
	Splice not made as indicated on Drawing 5-4-285		X	
Stovepipe shield	Set to roof with oval opening in a horizontal position instead of vertical	X		
	Exposed stitching or needle holes			X
Peak assembly	Webbing engaging snaps out of alignment with peak plate holes resulting in distortion or stress on the fabric	X		
Peak cap	Improperly applied, i.e., irregular in circumference			X
* Splicing of webbing	Splicing (when necessary) not made as indicated on Drawing 5-4-289		X	
	More than one splice per gore on seams joining tent panels		X	

Source: https://assist.dla.mil -- Downloaded: 202610-17T22:44Z
Check the source to verify that this is the current version before use.

TABLE II. End item visual defects (cont'd)

Examine	Defect	Classification Major	Minor A	Minor B
* Cloth splicing	Splice in roof, wall, or tent cover panels	X		
	Number of splices per reinforcement or sod cloth section more than specified			X
	Spliced pieces not joined as shown on Drawing 5-4-289		X	
General	Any other construction detail not performed as specified		X	
Labels	Omitted, incorrect, illegible, or misplaced:			
*	- care and maintenance; erection instruction		X	
	- identification			X
Markings; "US" and identification	Omitted, incorrect, illegible, or misplaced			X
Cleanness	Grease or oil stains			X
	Thread ends not trimmed to 1/4 inch or less (except in slide fastener area)			X
	Thread ends not trimmed to 1/4 inch or less in slider fastener area		X	

* 4.4.4 End item dimensional examination.

* 4.4.4.1 Tent with cover. The end items shall be in erected position so that both the inside and outside of the tent can be examined, along with its cover, for defects listed in table III. The lot size shall be expressed in units of tents with covers. The sample unit shall be one tent with its cover. The inspection level shall be S-3 and the AQL, expressed in terms of defects per hundred units, shall be 2.5 for major defects, 15 for major and minor A combined defects, and 40 for total (major and minor combined) defects.

Source: https://assist.dla.mil -- Downloaded: 20261O-17T22:44Z
Check the source to verify that this is the currentversion before use.

* 4.4.4.2 Cover, only. The end items shall be in a position so that both the inside and outside of the cover can be examined for the applicable defects listed in table III. The lot size shall be expressed in units of covers. The sample unit shall be one cover. The inspection level shall be S-3 and the AQL, expressed in terms of defects per hundred units, shall be 4.0 for major defects, 10 for major and minor A combined defects and 25 for total (major and minor combined) defects.

TABLE III. End item dimensional defects

Examine	Defect	Classification Major	Minor A	Minor B
Overall dimensions of tent	Smaller than specified dimensions less applicable minus tolerance indicated on drawings	X		
	Larger than specified dimensions and applicable plus tolerance indicated on drawings			X
Dimensions: tent cover; ventilator opening	Smaller than specified dimensions less applicable minus tolerance indicated on drawings, but not smaller than the specified dimensions less twice the applicable minus tolerance			X
	Smaller than specified dimensions less twice the applicable minus tolerance indicated on drawings		X	
	Larger than specified dimensions and applicable plus tolerance indicated on drawings			X
Location dimensions (unless otherwise specified)	Not within specified tolerance		X	
Webbing, tie tapes	Finished length less than specified by more than 1 inch			X
	Distance between splices on webbing less than 5 feet			X
Grommets	Set beyond specified location by more than 1/2 inch			X

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T22:44Z
Check the source to verify that this is the current version before use.

TABLE III. End item dimensional defects (cont'd)

Examine	Defect	Classification Major	Minor A	Minor B
Cord components; tent lines	Eye on footstop or line less than specified by more than 1/2 inch			X
	Finished length of guy line less than specified:			
	- by more than 4 inches			X
	- by more than 4 inches but not more than 12 inches		X	
	- by more than 12 inches	X		
Beckets	Misplaced:			
	- by more than 1/4 inch but not more than 1/2 inch			X
	- by more than 1/2 inch		X	
	Length of loop more or less than specified by 1/2 inch or more		X	
Toggle loops	Free end of loop extending less than 3/4 inch beyond edge of flap			X
Metal toggle chapes	Misplaced:			
	- by more than 1/4 inch but not more than 1/2 inch			X
	- by more than 1/2 inch		X	
Hems	Hems required to finish less than 3/4 inch in width, less than specified; hems required to finish more than 3/4 inch in width, less than specified by more than 1/4 inch			X
Reinforcements	Finished dimension less than specified by more than 1/2 inch			X
	Any spliced piece less than 2 feet in length			X
Tent line lugs	Loop portion of piece "A" less than 3/4 inch		X	
Snow cloths	Less than specified width by more than 1 inch			X

Source: https://assist.dla.mil -- Downloaded: 202640-17T22:44Z
Check the source to verify that this is the currenversion before use.

TABLE III. End item dimensional defects (cont'd)

Examine	Defect	Classification Major	Minor A	Minor B
Doorway flaps	Bottom end of flap uneven with breakline of wall by more than 1/4 inch; outer edge or end of facing uneven with edge or end of flap by more than 1/4 inch			X
Peak of wall	Peak of wall halves joined to roof with edges of door opening less than 7/8 inch apart, failing to provide clearance for top of slide fastener		X	
Ventilator opening	Misplaced: - by more than 1/2 inch			X
Stovepipe opening	Misplaced: - by more than 1/2 inch			X
* Ring, ring chapes, straps and strap reinforcement	Misplaced: - by more than 1/4 inch but not more than 1/2 inch			X
	- by more than 1/2 inch		X	
Cover flaps	Center line of flaps set off center of body by more than 3/4 inch			X

4.4.5 End item testing. The completely fabricated tents with covers shall be tested as specified in 4.5.1 for conformance to the wicking requirements specified in 3.3.11. The lot size shall be expressed in units of tents. The sample size shall be the number of tents indicated by inspection level S-3. Any test failure shall be cause for rejection of the lot.

* 4.4.6 Packaging examination. The fully packaged end items shall be examined for the defects listed below. The lot size shall be expressed in units of shipping containers. The sample unit shall be one shipping container fully packaged. The inspection level shall be S-2 and the AQL, expressed in terms of defects per hundred units, shall be 2.5.

Source: https://assist.dla.mil -- Downloaded: 202610-17T22:44Z
Check the source to verify that this is the current version before use.

Examine	Defect
Marking (exterior and interior)	Omitted; incorrect; illegible; of improper size, location; sequence, or method of application.
Materials	Any component missing, damaged, or not as specified.
Workmanship	Inadequate applications of components such as; incomplete closure of cloth covered bundles or bundles insecurely sewn.

4.5 Methods of inspection.

* 4.5.1 Wicking of sewing thread (cup test). The tent shall be tested in each of the three areas as follows: at the peak, ridge or joining seam abutting the peaks or ridge; at an intersection of a horizontal and vertical seam such as at an intersection of a side wall and roof; and on a roof panel seam. Suspend the seamed section of the test fabric in the center of a 6 ± 1/8 inch diameter hoop and form a depression with the seamed fabric in the hoop to a depth of 1 ± 1/4 inch. Slowly pour 500 mL of water at 77°F ± 4°F into the cupped area (depression) and observe the under surface of the fabric for water penetration. Any wicking of water along the sewing thread, identified by a discoloration or darkening of the thread within five minutes after water is poured, shall constitutute a failure. Water leakage through the needle holes or between the plies of the lapped seamed fabric shall not be considered a failure.

5. PACKAGING

5.1 Preservation. Preservation shall be level A or Commercial as specified (see 6.2).

5.1.1 Level A.

5.1.1.1 Tent with liner. Each tent shall have its liner attached by use of the toggles provided for that purpose. The sock lines shall be threaded through the toggles in their proper places. The slide fasteners on the tent and screen doors shall be close. The tent shall be folded in accordion pleats extending from the peak to the bottom of the sidewall. The tent shall then be laid flat, the pleats smoothed, and the lines placed on top of the tent. The peak of the tent shall be folded over and extend down the tent deck approximately four feet. The tent shall then be folded approximately in half along its length and then each end equally folded over toward the middle so that no portion of the liner is exposed. The completely folded tent shall be placed within its cover and the cover securely closed with the cover straps.

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T22:44Z
Check the source to verify that this is the current version before use.

* 5.1.1.1.1 Tent with liner, tent pole, tent pins and cover. Each tent shall be folded as specified in 5.1.1.1. Twenty-eight tent pins (see 3.2.25) and one tent pole (see 3.2.26) shall be inserted into the pocket of the tent cover. Prior to insertion, the tent pole shall be reduced to the shortest length, and the tent pins shall be grouped into units of four. Each unit of four pins shall be nested and completely wrapped in 50 pound basis weight kraft paper conforming to A-A-203 and secured with minimum 1-inch wide tape conforming to PPP-T-42. The completely folded tent shall be placed within its cover and the cover securely closed with the cover straps.

5.1.1.2 Tent (only). Each tent shall have the sock lines threaded through at least one toggle in their proper places. The slide fasteners on the tent and screen doors shall be closed. The tent shall be folded in accordion pleats extending from the peak to the bottom of the sidewall. The tent shall then be laid flat, the pleats smoothed, and the lines placed on top of the tent. The peak of the tent shall be folded over and extend down the tent deck approximately four feet. The tent shall then be folded approximately in half along its length and then each end equally folded over toward the middle. The completely folded tent shall be placed within its cover and the cover securely closed with the cover straps.

5.1.1.3 Tent covers. Each tent cover shall be compactly folded so that the identification markings are visible. The folded cover shall measure approximately 20 by 14 inches. All straps shall be placed within the folds. Five folded covers shall be stacked and cross-tied with cotton tape or twine.

5.1.2 Commercial. Each tent with liner; tent with liner, tent pole, tent pins, and cover; tent only; or tent covers only shall be preserved in accordance with ASTM D 3951.

5.2 Packing. Packing shall be level A, B or Commercial as specified (see 6.2).

5.2.1 Level A packing. One tent with liner; one tent with liner, tent pole, tent pins and cover; one tent only; or ten tent covers only, preserved as specified in 5.1, shall be packed in a close-fitting plywood box conforming to overseas type, style A of PPP-B-601. Each box shall be closed and reinforced with flat steel strapping in accordance with the box specification.

5.2.2 Level B packing. One tent with liner; one tent with liner, tent pole, tent pins and cover; one tent only; or ten tent covers, preserved as specified in 5.1, shall be wrapped in cotton osnaburg cloth conforming to class 2 of CCC-C-429, or burlap cloth conforming to class 3 of CCC-C-467. The wrapping shall be securely hand sewn with type I or II, 16-ply cotton twine conforming to T-T-871, or type I, size No. 2 jute twine conforming to T-T-911, with approximately one stitch to the inch and every third stitch overhand knotted. Alternatively, the seams of the wrap may be machine-sewn. In lieu of the sewn wrap, bias sewn tubing conforming to MIL-T-40625 may be used. A minimum of five inches of wrapping or tubing shall be gathered together on each of the four corners and securely sewn into ears for handles. Wherever

Source: https://assist.dla.mil -- Downloaded: 202610-17T22:44Z
Check the source to verify that this is the current version before use.

machine sewing is used, the thread type, stitch type and number of stitches per inch shall conform to the requirements specified in MIL-T-40625. The polyester thread used to manufacture the tent may be used for affecting the machine sewn closure of the wrapping or tubing.

5.2.3 Commercial packing. Each tent with liner; tent with liner, tent pole, tent pins and cover; tent only; or tent covers only, preserved as specified in 5.1.2 shall be packed in accordance with ASTM D-3951.

5.3 Marking. In addition to any special marking required by the contract or purchase order, shipments shall be marked in accordance with MIL-STD-129, or ASTM D-3951, as applicable.

5.3.1 Additional marking. The following shall be stenciled or imprinted on each cloth covered bundle and shipping container in characters not less than 3/4 inch high:

"SEE ERECTION INSTRUCTION
SEWED TO INSIDE OF TENT COVER"

6. NOTES

6.1 Intended use. The tent, with the liner, is intended for use as a temporary shelter for troops operating in extremely cold and cold-wet areas.

6.2 Ordering data. Acquisition documents should specify the following:

a. Title, number, and date of this document.
b. When a first article is required (see 3.1, 4.3, and 6.4).
c. Selection of applicable levels of preservation and packing (see 5.1 and 5.2).
d. When pins and poles are required (see 3.2.25 and 3.2.26).

* 6.3 Standards samples. For access to a standard shade of thread, address the contracting officer issuing the invitation for bids.

* 6.4 First article. When a first article is required, it shall be inspected and approved under the appropriate provisions of FAR 52.209. The first article should be a preproduction sample. The contracting officer should specify the appropriate type of first article and the number of units to be furnished. The contracting officer should include specific instructions in all acquisition instruments regarding arrangements for selection, inspection, and approval of the first article.

6.5 Recycled material. It is encouraged that recycled material be used when practical as long as it meets the requirements of the document (see 3.2).

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T22:44Z
Check the source to verify that this is the current version before use.

* 6.6 Other components. The following components are required for the erection of the tent:

1 each - Pole, Tent, Telescopic, adjustable 5 feet to 9 feet, Magnesium

For erection on hard ground, unfrozen

28 each - Pin, Tent, Aluminum, 9 inches

6.7 Seams to be treated. Seams which have failed the test specified in 4.5.1 shall be treated as follows:

a. Failure at roof panel lap seams - treat all roof panel lap seams.
b. Failure at peak reinforcement - treat all peak reinforcement stitching.
c. Failure at eave - treat all stitching at eave and webbing reinforced roof joining seams.

6.7.1 Repair of leaking seams. A satisfactory method of applying the textile compound for the repair of leaking seams is as follows:

a. A suitable volume of textile compound conforming to type I, class 1 of TT-P-595 (NSN 8030-00-290-4383), 55 gallon drum shall be throughly stirred and diluted with an equal volume of petroleum solvent (Stoddard solvent or equivalent). Thoroughly stir the mixture again before use.

b. Prior to application of the compound, the tent must be dry. Special attention must be taken to insure adequate ventilation and that proper fire preventive measures are taken since the compound is flammable.

c. Two coats of the textile compound shall then be applied to the seams (on the outside of the tent only). A 4-inch wide stiff brush is recommended for use. The first coat shall be air dried for a minimum of 4 hours prior to application of the second coat. Elapsed time between coats may be reduced by providing a supply of hot air to evaporate the solvent more quickly. In this manner, a second coat may be applied as soon as the first coat is dry to the touch. After the application of the second coat, the treated tent shall be allowed to air dry for a period of at least 24 hours.

6.8 International standardization agreements. Certain provisions of this document are the subject of international standardization agreement as cited in NATO, STANAG NO. 2882, relative to camouflage requirements for tents, shelters and subsidiary components. When amendment, revisions, or cancellation of this document is proposed which will affect or violate the international agreement concerned, the preparing activity will take appropriate reconciliation action through international standardization channels including departmental standardization offices, if required.

Source: https://assist.dla.mil -- Downloaded: 202610-17T22:44Z
Check the source to verify that this is the current version before use.

* 6.9 Subject term (key word) listing.

Arctic
Shelter
Tent

6.10 Changes from previous issue. The margins of this document are marked with an asterisk to indicate where changes (additions, modifications, corrections, deletions) from the previous issue were made. This was done as a convenience only and the Government assumes no liability whatsoever for any inaccuracies in these notations. Bidders and contractors are cautioned to evaluate the requirements of this document based on the entire content irrespective of the marginal notations and relationship to the last previous issue.

Custodians:

Army - GL
Navy - NU
Air Force - 99

Review activities:

Army - MD
Air Force - 82
DLA - CT

User activities:

Air Force 45
* Navy - MC, YD

Preparing activity:

Army - GL

Project No. 8340-0504

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T22:44Z
Check the source to verify that this is the current version before use.

INSTRUCTIONS: In a continuing effort to make our standardization documents better, the DoD provides this form for use in submitting comments and suggestions for improvements. All users of military standardization documents are invited to provide suggestions. This form may be detached, folded along the lines indicated, taped along the loose edge *(DO NOT STAPLE)*, and mailed. In block 5, be as specific as possible about particular problem areas such as wording which required interpretation, was too rigid, restrictive, loose, ambiguous, or was incompatible, and give proposed wording changes which would alleviate the problems. Enter in block 6 any remarks not related to a specific paragraph of the document. If block 7 is filled out, an acknowledgement will be mailed to you within 30 days to let you know that your comments were received and are being considered.

NOTE: This form may not be used to request copies of documents, nor to request waivers, deviations, or clarification of specification requirements on current contracts. Comments submitted on this form do not constitute or imply authorization to waive any portion of the referenced document*(s)* or to amend contractual requirements.

(Fold along this line)

(Fold along this line)

DEPARTMENT OF THE ARMY

U.S. ARMY NATICK RESEARCH, DEVELOPMENT
and ENGINEERING CENTER
ATTN: STRNC-ES
Natick, MA 01760-5014

OFFICIAL BUSINESS
PENALTY FOR PRIVATE USE $300

NO POSTAGE
NECESSARY
IF MAILED
IN THE
UNITED STATES

BUSINESS REPLY MAIL
FIRST CLASS PERMIT NO. 12062 WASHINGTON D. C.

POSTAGE WILL BE PAID BY THE DEPARTMENT OF THE ARMY

Commander
U.S. Army Natick Research, Development
and Engineering Center
ATTN: STRNC-ES
Natick, MA 01760-5014

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T22:44Z
Check the source to verify that this is the current version before use.

STANDARDIZATION DOCUMENT IMPROVEMENT PROPOSAL

(See Instructions – Reverse Side)

1. DOCUMENT NUMBER	2. DOCUMENT TITLE
MIL-T-12354F	TENT, ARCTIC, 10 MAN

3a. NAME OF SUBMITTING ORGANIZATION	4. TYPE OF ORGANIZATION *(Mark one)*
	☐ VENDOR
	☐ USER
b. ADDRESS *(Street, City, State, ZIP Code)*	☐ MANUFACTURER
	☐ OTHER *(Specify)*: _____

5. PROBLEM AREAS

a. Paragraph Number and Wording:

b. Recommended Wording:

c. Reason/Rationale for Recommendation:

6. REMARKS

7a. NAME OF SUBMITTER *(Last, First, MI)* – Optional	b. WORK TELEPHONE NUMBER *(Include Area Code)* – Optional
c. MAILING ADDRESS *(Street, City, State, ZIP Code)* – Optional	8. DATE OF SUBMISSION *(YYMMDD)*

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T22:44Z
Check this source to verify that this is the current version before use.