INCH POUND

MIL-DTL-12354G
21 December 2000

SUPERSEDING
MIL-T-12354F
29 July 1988

DETAILED SPECIFICATION

TENT, ARCTIC, 10 MAN

This specification is approved for use by all Departments and Agencies of the Department of Defense.

1. **SCOPE**

1.1 Scope. This document covers a pole-supported six-sided pyramidal tent fabricated of wind-resistant, cotton sateen cloth. A fire-resistant insulting liner and a protective cover for the tent and components are provided with the tent.

2. **APPLICABLE DOCUMENTS**

*2.1 General. The documents listed in this section are specified in sections 3 and 4 of this specification. This section does not include documents cited in other sections of this specification or recommended for additional information or as examples. While every effort has been made to ensure the completeness of this list, document users are cautioned that they must meet all specified requirements documents cited in sections 3 and 4 of this specification, whether or not they are listed.

*2.2 Government documents.

Beneficial comments (recommendations, additions, deletions) and any pertinent data which may be of use in improving this document should be addressed to: Defense Supply Center Philadelphia, Clothing and Textiles Directorate, Attn: DSCP-CNR, 700 Robbins Avenue, Building 6D, Philadelphia, PA 19111-5094, by using the Standardization Document Improvement Proposal (DD Form 1426) appearing at the end of this document or by letter.

AMSC N/A FSC 8340

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T22:44Z
Check the source to verify that this is the current version before use.

*2.2.1 Specifications, standards, and handbooks. The following specifications, standards, and handbooks form a part of this document to the extent specified herein. Unless otherwise specified, the issue of these documents are those listed in the issue of the Department of Defense Index of Specifications and Standards (DODISS) and supplement thereto, cited in the solicitation (see 6.2).

SPECIFICATIONS

FEDERAL

A-A-55126	- Fastener Tapes, Hook and Pile, Synthetic
V-F-106	- Fasteners, Slide, Interlocking
V-T-285	- Thread, Polyester
TT-P-595	- Preservation Coating, Canvas
DDD-L-20	- Label, for Clothing, Equipage and Tentage, (General Use)
GGG-N-202	- Needle, Sailmaker's

MILITARY

MIL-C-496	- Clip, End Strap
MIL-P-500	- Plates, Tent, Peak and Ridge
MIL-P-501	- Pins, Tent, Metal
MIL-W-530	- Webbing, Textile, Cotton, General Purpose, Natural or in Colors
MIL-H-1608	- Hooks, Tent
MIL-L-1709	- Lines, Tent
MIL-DTL-1716	- Poles, Tent, telescopic, Adjustable 5-Feet to 9-Feet, Magnesium
MIL-S-1734	- Slips, Tent Line
MIL-R-3390	- Rings, Dee
MIL-C-3395	- Cloth, Netting; Nylon or Polyester
MIL-F-10884	- Fasteners, Snap
MIL-L-11075	- Loops, Strap Fastener
MIL-C-12095	- Cloth, Wind-Resistant Sateen, Cotton; Fire and Water Resistant
MIL-PRF-20696	- Cloth, Coated, Polyester and Nylon, Waterproof
MIL-S-43002	- Shield, Stovepipe, Tent, Nonmetallic
MIL-C-43256	- Cord, Polyester, Solid Braid
MIL-T-43333	- Tent Liner, General Purpose, Small and Artic, 10-Man
MIL-T-43566	- Tape, Textile, Cotton or Polyester, General Purpose, Natural or in Colors
MIL-C-43627	- Cloth, Duck, Cotton, Plied Yarns, Fire, Water, Weather and Mildew Resistant Treated, Lightdry Finish
MIL-W-43638	- Webbing, Textile, Woven, for Tent Framing
MIL-W-44049	- Webbing, Textile and Tape, Textile, Polypropylene General Purpose, Natural or in Colors

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T22:44Z
Check the source to verify that this is the current version before use.

*(Unless otherwise indicated, copies of federal and military specifications, standards and handbooks are available from the Defense Automated Printed Service, Bldg. 4D, 700 Robbins Avenue, Philadelphia, PA 19111-5094.)

*2.2.2 Other government documents, drawings, and publications. The following other Government documents, drawings, and publications form a part of this document to the extent specified herein. Unless otherwise specified, the issues are those cited in the solicitation.

DEPARTMENT OF THE ARMY FIELD MANUAL

FM 10-16 - General Repair of Tents, Canvas and Webbing

*(Copies of the manual are available from the U. S. Army Biological and Chemical Command, ATTN: SSCNC-EMSS, Natick, MA 01760-5017.)

DRAWINGS

U.S. ARMY BIOLOGICAL AND CHEMICAL COMMAND

4-1-206	-	Rings, Connecting, Round
5-4-231	-	Cover, Tent; Hexagonal, Lightweight and Arctic, 10-Man
5-4-284	-	Tent, Arctic, 10-Man; Illustrations
5-4-285	-	Assembly and Details
5-4-286	-	Views and Details
5-4-287	-	Front and Rear Details
5-4-288	-	Assembled Front, Rear and Details
5-4-289	-	Side Details and Sections
5-4-290	-	Ventilator and Details
5-4-291	-	Screen Door and Details
5-4-544	-	Erection Instructions
5-4-545	-	Maintenance, Striking and Folding Instructions
5-4-580	-	Repair Kit
5-4-1075	-	Pole, Telescopic, Adjustable, 5’-0” to 9’-0”, Magnesium; Details

*(Copies of drawings are available from the U.S. Army Biological and Chemical Command, ATTN: SSCNC-EMSS, NATICK, MA 01760-5017.)

*2.3 Non-Government publications. The following document(s) form a part of this document to the extent specified herein. Unless otherwise specified, the issues of the documents which are DoD adopted are those listed in the issue of the DODISS cited in this solicitation. Unless otherwise specified, the issues of documents not listed in the DODISS are the issues of the documents cited in the solicitation (see 6.2).

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T22:44Z
Check the source to verify that this is the current version before use.

AMERICAN SOCIETY FOR TESTING AND MATERIALS (ASTM)

A47	-	Standard Specification for Ferritic Malleable Iron Castings
A513	-	Standard Specification for Electric-Resistance-Welded Carbon and Alloy Steel Mechanical Tube
A519	-	Standard Specification for Seamless Carbon and Alloy Steel Mechanical Tubing
A641	-	Standard Specification for Zinc-Coated (Galvanized) Carbon Steel Wire
A809	-	Standard Specification for Aluminum-Coated (Aluminized) Carbon Steel Wire
A818	-	Standard Specification for Coppered Carbon Steel Wire
A853	-	Standard Specification for Steel Wire, Carbon, for General Use
B134	-	Standard Specification for Brass Wire
B 159	-	Standard Specification for Phosphor Bronze Wire
B 159M	-	Standard Specification for Phosphor Bronze Wire (Metric)
B 206	-	Standard Specification for Copper-Nickel-Zinc Alloy (Nickel Silver) Wire and Copper
B206M	-	Standard Specification for Copper-Nickel-Zinc Alloy (Nickel Silver) Wire and Copper (Metric)
D6193	-	Seams, Stitching and Sewing

*(Copies may be obtained from the American Society for testing and Materials, 100 Barr Harbor Drive, West Conshohocken, PA 19428.)

NAVAL LOGISTICS LIBRARY (NLL) NASM
NATIONAL AEROSPACE STANDARDS COMMITTEE (NA/NAS)

NASM 16491	-	Grommet, Metallic
NASM 43770/10	-	Snap, Hooks, Cast Body, Fixed Loop Eye w/o Roller, Flat Spring Closure, Wide Mouth

* (Copies may be obtained from the Naval Logistics Library, 5450 Carlisle Pike, Mechanicsburg, PA. (703) 813-8387.

AMERICAN NATIONAL STANDARDS INSTITUTE(ANSI) ANSI / ASQC Z1.4-SAMPLING PROCEDURES AND TABLES FOR INSPECTION BY ATTRIBUTES

* (Applications for copies should be obtained from: American Society for Quality Control, 611 East Wisconsin Avenue, Milwaukee, WI 53202).

*2.4 Order of precedence. In the event of a conflict between the text of this specification and the references cited herein, the text of this specification takes precedence. Nothing in this specification, however, supersedes applicable laws and regulations unless a specific exemption has been obtained.

3. **REQUIREMENTS**

*3.1 First article. When specified, (see 6.2), a sample shall be subjected to first article inspection (see 4.2 and 6.2).

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T22:44Z
Check the source to verify that this is the current version before use.

*3.2 Materials and components. Materials and components shall be as specified herein and in referenced documents and drawings. Materials not definitely specified shall be of the quality normally used by the manufacturer provided the complete item complies with all provisions of this document. It is encouraged that recycled material be used when practical as long as it meets the requirements of this document.

*3.2.1 Cloth, wind-resistant sateen, cotton. The cloth for the tent shall be Camouflage Green 483 and shall conform to MIL-C-12095.

*3.2.2 Cloth, cotton duck. The cotton duck for the peak reinforcement shall be Camouflage Green 483 and shall conform to type I of MIL-C-43627. Requirements for colorfastness to weathering shall not apply.

*3.2.2.1 Cloth, coated. The cloth for the tent cover shall conform to type II, class 2 of MIL-PRF-20696 and the color shall be Camouflage Green 483.

*3.2.2.2 Fastener tape. The fastener tapes, hook and pile shall conform to type II, class 3, Color 3422 of A-A-55126.

3.2.3 Cloth, netting, nylon. The nylon netting for the ventilator opening and screen door shall conform to type I or II of MIL-C-3395.

3.2.4 Shield, stovepipe, tent. The flexible, silicone rubber coated stovepipe shield shall conform to MIL-S-43002.

*3.2.5 Tape, textile, cotton. The tape shall be Camouflage Green 483 and shall conform to type I, class 4, ½ inch, ¾ inch, 1-1/2 inch and 2 inch widths (as specified on applicable drawings) of MIL-T-43566. For covers only, polypropylene tape conforming to type I, class 4, ¾ inch width of MIL-W-44049 may be used as an alternate.

*3.2.6 Webbing, textile, cotton. The webbing shall be Camouflage Green 483 and shall conform to type IIb, class 4, 1 inch width and type III, class 4, 5/8 inch and 1-1/2 inch widths (as specified on applicable drawings) of MIL-W-530. For covers only, polypropylene webbing conforming to type IIb, class 4, 1 inch width of MIL-W-44049 may be used as an alternate.

*3.2.7 Webbing, textile, woven, low elongation. The webbing shall be natural, conforming to type I, 1 inch width of MIL-W-43638.

3.2.8 Thread, polyester. The thread for the tent screens and cover shall conform to type I, class 1, sub-class B, shade S-1 (C.A. 66022) of V-T-285. The dyed thread shall show fastness to weathering equal to or better than the standard shade sample. When no standard shade sample is available, the thread shall show good fastness to weathering.

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T22:44Z
Check the source to verify that this is the current version before use.

3.2.8.1 Sizes. Thread sizes shall be as follows:

For all stitching except zig-zag stitching, bartacking and stitching indicated by "Z" on drawings	- Size F for needle and size E for bobbin
For zig-zag stitching and bartacking	- Size E for needle and bobbin
For stitching indicated by "Z" on drawings	- Size F needle, size E for looper.

3.2.9 Lines, tent. The tent lines shall conform to class D of MIL-L-1709 in the following types:

Type	
LII	(Intermediate eave line, corner eave line)
LIII	(Corner line) except that the length shall be 20 feet
LIV	(Door eave line)

3.2.10 Cord, polyester. The cord used for the sock lines, toggle loops and beckets shall be Camouflage Green 483, 1/8 inch diameter cord conforming to MIL-C-43256.

3.2.11 Cord, cotton. The cord for the footstops and drip cap stiffener shall conform to type I, class 3, size No. 7 of A-A-55622. The footstops shall be as shown on Drawing 5-4-285.

3.2.12 Toggles.

3.2.12.1 Toggles, wood. The wood toggles of the design and dimensions shown on Drawing 5-4-288, shall be fabricated from uniformly dried, straight-grained lumber and shall not contain more than 15 percent moisture when tested as specified in 4.4.1.1. The toggles shall be free from knots, shakes, checks, splits, or splintery surface. Any of the following woods may be used:

Hickory	Beech	Pecan	Maple, hard
Red or White Oak	Birch	Rock Elm	Ash

*3.2.12.2. Toggles, metal. The metal toggles shall be of the design and dimensions shown on Drawing 5-4-286 and shall be fabricated from brass wire conforming to alloy No. 270, half hard temper of ASTM B134, ASTM B159, ASTM B206. The toggles shall have a black chemical finish.

3.2.13 Slips, tent line. The tent line slips shall conform to type II of MIL-S-1734.

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T22:44Z
Check the source to verify that this is the current version before use.

3.2.14 Fasteners, slide interlocking. The slide fasteners shall conform to type III, style 1, size H, wire stirrup pulls of V-F-106. Slide fastener chain shall be fabricated of brass or polyester coil. The slider for the brass chain shall be brass and the slider for the polyester coil shall be die cast zinc alloy. The slide fastener tape shall be dyed to match CG 483 and be water repellent and mildew resistant. (Tapes made of 100 percent polyester need not be tested for mildew resistance.) The color of the tape after treatment will be considered acceptable. The tape shall show good fastness to weathering. Alternatively, the slide fastener chain shall be polyester continuous monofilament in a ladder or coil type configuration. Color of the chain shall be CG 483 or natural finish brass and the sliders shall be brass.

3.2.15 Rings, dee. The dee rings shall conform to class 1 or 2, configuration K, 1 inch by ¾ inch of MIL-R-3390.

*3.2.16 Ring, connecting. The connecting rings shall be of steel wire or cast malleable iron, black enamel, phosphate treated, zinc plate finished, size 2 or 5 in accordance with
Drawing 4-1-206.

*3.2.16.1 Steel wire. The steel wire shall conform to steel numbers 1006 to 1020 in accordance with ASTM A853, ASTM A818, ASTM A641 or ASTM A809.

*3.2.16.2 Steel tube. The steel tube shall be seamless, round in accordance with ASTM A513 and ASTM 519.

*3.2.16.3 Malleable iron. The malleable iron shall be grade I (35018)-Black, ungalvanized or grade II (32510)-Black, ungalvanized in accordance with ASTM A47. The first three digits of the grade designations indicate the minimum yield strength (x 100 p.s.i.). The last two digits indicate the minimum elongation (percent in 2 inches).

3.2.17 Plate, peak. The peak plate shall conform to type XVIII of MIL-P-500.

*3.2.18 Snaphooks. The snaphooks shall conform to NASM 43770/10.

*3.2.19 Grommets, metallic. The grommets shall conform to type III, class 3 of NASM 16491 in the following sizes:

No. 1 (for connecting lug becket cord)
No. 2 (for footstops, type “B”)
No. 4 (for footstops, type “A”)

3.2.20 Fasteners, snap. The snap fasteners shall conform to style 2, finish 2, button 24 line size, size 1 and eyelet size 1 of MIL-F-10884.

3.2.21 Clip, end strap. The end clips shall conform to type I, class 1 or 2, size 1 inch of MIL-C-496.

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T22:44Z
Check the source to verify that this is the current version before use.

3.2.22 Loops, strap fastener. The strap fastener loops shall conform to type III, style B of MIL-L-11075.

3.2.23 Hooks, tent. The tent hooks used at the peak plate shall conform to type I, size 1 inch of MIL-H-1608.

3.2.24 Tent liner. The liner for the tent shall conform to MIL-L-43333.

3.2.25 Pins, tent, metal. When required (see 6.2), the tent pins shall be type I, conforming to MIL-P-501.

3.2.26 Pole, tent, telescope. When required (see 6.2), the magnesium, adjustable telescopic tent poles shall conform to MIL-P-1716.

3.3 Construction. The construction shall conform in all respects to the drawings listed in section 2 and as specified herein.

3.3.1 Stitching, machine.

3.3.1.1 Stitch types. Stitch types, except bartacks, shall conform to ASTM D6193 as follows:

For all stitching, except bartacking, "zig-zag" stitching. Stitching indicated by "Z" on drawings, and alternatively for the attachment of slide fasteners.	-	Type 301, 5 to 7 stitches per inch
For "zig-zag" stitching	-	Type 304, 10 to 16 stitches per inch, ¼ inch wide (bight)
For stitching indicated by "Z" on drawings and alternatively for attachment of slide fasteners	-	Type 401, 5 to 7 stitches per inch. Chain portion of stitching shall not appear on outside of shelter or cover.
For bartacking	-	Bartack, ½ ± 1/16 inch long, 1/8 ± 1/16 inch wide (bight) and shall contain 28 stitches

3.3.1.2 Type 301 stitching. Ends of all stitching shall be backstitched or overstitched 1/2 inch minimum except when caught in other stitching or turned under in the hem. Thread tension shall be maintained so that there will be no loose stitching resulting in puckering of material sewn. The lock shall be imbedded in the material sewn.

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T22:44Z
Check the source to verify that this is the current version before use.

3.3.1.2.1 Repairs of type 301 stitching. Repairs of type 301 stitching shall be as follows:

a. When thread breaks or bobbin run-outs occur during sewing, the stitching shall be repaired by restarting the stitching a minimum of one inch behind the end of the stitching. 1/

b. Thread breaks, two or more consecutively skipped stitches or run-off stitches noted during inspection of the item (in-process or end item) shall be repaired by overstitching. The stitching shall start a minimum of 1 inch before the defective area (1/2 inch on box, box and cross and W-W stitching) and continue a minimum of 1 inch beyond the defective area onto the existing stitching. Loose or excessively tight stitching shall be repaired by removing the defective stitching, without damaging the materials, and restitching in the required manner. 1/

1/ When making the above repairs, the ends of the stitching are not required to be backstitched.

3.3.1.3 Type 401 stitching. Thread tension shall be maintained so that there will be no loose stitching. Both ends of seams or stitching produced with a 401 stitch type, when not turned under in a hem or held down by other stitching, shall have a ¾ to 1 inch chain extending beyond each end. The looper (under thread) shall always be on the inside of the tent or cover. All repairs shall be made using a 301 stitch in accordance with 3.3.1.2.1 a or 3.3.1.2.1 b.

3.3.1.4 Type 304 stitching. For type 304 stitching, thread tension shall be maintained so that there will be no loose or excessively tight stitching. Repairs shall be in accordance with 3.3.1.2.1 a or 3.3.1.2. lb except that the stitching shall over stitch the defective stitching area a minimum of three stitches onto the existing stitching.

3.3.1.5 Automatic stitching. Automatic stitching machines may be used to perform any of the required stitch patterns provided the requirements of the stitch pattern, stitches per inch, size and type of thread are met, and at least three or more tying, overlapping or backstitches are used to secure the ends of the stitching.

3.3.1.6 Thread ends. All thread ends that are visible on the finished item shall be trimmed to a length of not more than ¼ inch.

3.3.1.7 Lubrication of thread. The addition of any lubricant to the polyester sewing thread prior to or during the sewing operation is prohibited.

3.3.1.8 Stitching margins. Unless otherwise specified, all stitch margins shall be 1/8, +1/16 -0 inch.

3.3.1.9 Bartacking. Bartacking shall be free of thread breaks or loose stitching.

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T22:44Z
Check the source to verify that this is the current version before use.

3.3.2 Attachment of wood toggles. Wood toggles shall be attached as shown on Drawing 5-4-288.

3.3.3 Setting of grommets. Holes punched to receive the grommets shall be smaller than the outside diameter of the grommet barrel so that the barrel must be forced through the hole. The grommets shall be securely clinched without cutting the materials. Roll of the clinched grommet shall not contain splits.

3.3.4 Setting of snap fasteners. If a hole is punched before inserting the male or female part of the fasteners, it shall be smaller than the outside diameter of the fastener tube so that the tube must be forced through the hole. The fasteners shall be securely clinched. Roll of the clinched eyelet of the assembled fastener component shall not contain more that three scores (splits).

3.3.5 Setting of end clips. The webbing shall be inserted in the full depth of the clips. The clips shall be securely attached without cutting the webbing and the webbing shall lie flat at the point of entrance.

3.3.6 Splicing of webbing. If required, the webbing shall be spliced as shown on Drawing 5-4-289. A maximum of one splice per gore will be permitted. The minimum distance between splices in the remainder of the tent shall be 5 feet.

3.3.7 Splicing of cloth. There shall be no splicing of roof, wall or tent cover panels. Splicing of reinforcements and snow cloth sections will be permitted and, if performed, shall conform to the following requirements:

a. Eight feet or less in length — One splice permitted;
More than 8 feet but not more than 12 feet in length — Two splices permitted. More than 12 feet in length — Three splices permitted.

b. The shortest length of any spliced piece shall be not less than 2 feet.

c. Pieces shall be joined as shown on Drawing 5-4-289.

3.3.8 Splicing of Beckets. Splicing will be permitted in the tent doorways and if performed shall conform to Drawing 5-4-285 with a minimum distance of 5 feet between splices. No splice shall be in any portion of the loop.

3.3.9 Attachment of slide fasteners. Care shall be exercised to maintain specified distances between edges of fabric attached to slide fastener tape so that there will be no interference with the operation of the slider. The length of the slide fastener shall be such that after the slide fastener is sewed on, the tape shall not be puckered and the slider shall operate freely.

3.3.10 Kit, repair. The repair kit bag shall be fabricated from the material specified in 3.2.1 and of the design

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T22:44Z
Check the source to verify that this is the current version before use.

and dimensions shown on Drawing 5-4-580. The snap fastener on the pocket shall be as specified in 3.2.20 and the tie cord on the bag shall be as specified in 3.2.10. The bag, containing the repair kit components, shall be securely tied and placed in the repair kit pocket of each completed tent.

3.3.10.1 Components, repair. Components for each kit shall consist of the items listed in table I.

TABLE I. Repair kit components

Item	Quantity	Specification or reference
Cloth, wind-resistant sateen, cotton	½ yard full width	3.2.1
Thread, polyester, type I, class 1, sub-class B, size F, shade S-l, 2 ounce spool	1 spool	3.2.8
Needle, sailmaker' s Size 16	3	GGG-N-202
Pusher, needle	1	Drawing 5-4-580 and wood specified in 3.2.12.1
Sleeve, lock, retaining	2	Drawing 5-4-1075 Item 10 of MIL-P-1716
Lock, upper	1	Drawing 5-4-1075 Item 7 of MIL-P-l716
Lock, lower	1	Drawing 5-4-1075 Item 8 of MIL-P-1716

3.3.11 Wicking. There shall be no dripping of water through the tent stitching when the tent is tested as specified in 4.5.1. The cup test is intended to ensure that non-wicking thread has been utilized and that no lubrication has been added to the polyester thread prior to or during the sewing operation.

*3.3.12 Repairs. Any necessary repairs shall be effected in accordance with Department of the Army Field Manual FM 10-16 except that hand-sewn patches, or cemented patches other than as specified herein, will not be acceptable. Cemented patches on holes, cuts or tears not more than 1 inch in diameter or length, using cement in accordance with Part No.LA495 of Clifton Adhesive Company, or equal shall be permitted. A maximum of three cemented patches per tent will be allowed without prior authorization. A patch shall be large enough to overlap the damaged area with a margin of at least ¾ inch on all sides. Cemented patches shall

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T22:44Z
Check the source to verify that this is the current version before use.

not be applied over seams or hardware areas. All other repairs required as a result of failure to meet the requirements of the cup test and when authorized by the contracting officer shall be performed by treating with a compound conforming to type I, class 1 of TT-P-595 prior to retesting (see 6.5.1).

3.3.13 Fusing of ends of synthetic webbing and tape. All ends of synthetic webbing, and tape shall be fused. The apparatus used to fuse the ends shall be capable of providing sufficient heat to provide a smooth edge and with the cut ends of the yarns all fused together. Fusing of the ends shall be accomplished prior to being assembled for stitching.

3.3.14 Replacement of defective components. During the spreading, cutting and manufacturing process, components of the tent having material defects or damages that are classified as defects in 4.3.2 or 4.3.3 shall be removed from production and replaced with non-defective and properly matched components.

3.4 Marking. All marking and labels shall conform to DDD-L-20.

3.4.1 Special marking. The application of the letters "US" on the tent and cover, the instructions on the door, the marking on the repair kit and the nomenclature on the cover shall conform to type IV, class 9 in the size characters and in the locations shown on the drawings. Class 9 markings shall be clearly legible after subjection to accelerated weathering.

3.4.2 Identification label. The identification labels shall be stitched to the tent and cover in the locations shown on the drawings and shall conform to type VI, class 6 and shall be 3-1/2 inches by 5-1/2 inches minimum and a blank space of at least 1-1/4 inches shall be provided on the bottom of the label for the Department of Defense inspector's stamp.

3.4.3 Erection instruction label. Labels of erection instructions shall conform to type VI, class 7 and shall be stitched to the tent and cover in the locations shown on the drawings. The label shall be a proportionate copy of Drawing 5-4-544 as reproduced from a glossy print of this drawing furnished by the contracting officer. The size of the label shall be, borderline to borderline, 15±1/4 inches in the longer dimension, with a minimum V_2 inch margin outside of the borderline on all sides.

3.4.4 Care and maintenance instruction label. Labels of care and maintenance instructions shall conform to type VI, class 7 and shall be stitched to the tent and cover in the locations shown on the drawings. The label shall be a proportionate copy of Drawing *5-4-545*, as reproduced from a glossy print of this drawing furnished by the contracting officer. The size of the label shall be, borderline to borderline,
15±1/4 inches in the longer dimension, with a maximum 1/2 inch margin outside of the borderline on all sides.

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T22:44Z
Check the source to verify that this is the current version before use.

*3.5 Workmanship. Cloth components shall be clean and free of holes, cuts, tears or cloth defects such as multiple floats or broken or missing yarns. Webbing and tapes shall contain no frayed or scalloped edges and rope components shall be free of cuts or breaks. Thread tension shall be maintained so that there will be no loose stitching and seam allowances shall be maintained with seams properly sewed so that no runoffs, pleats, or open seams shall result. Care shall be taken in sewing so that there will shall be no needle chews. Metal components shall be free of burrs, sharp edges, corroded areas and shall not be broken or malformed. The tent shall conform to the quality of product established by this document.

*4 VERIFICATION

*4.1 Classification of inspection. The inspection requirements specified herein are classified as follows:

a. First article inspection (see 4.3).
b. Conformance inspection (see 4.4).

* 4.2 First article inspection. When a first article is required (see 3.1 and 6.2) it shall be examined for the defects specified in 4.4.3. Any nonconformance shall be cause for rejection of the first article.

* 4.3 Responsibility for dimensional requirements. Unless otherwise specified in the contract or purchase order, the contractor is responsible for assuring that all specified dimensions have been met. When dimensions cannot be examined on the end item, inspection shall be made at any point, or at all points in the manufacturing process necessary to assure compliance with all dimensional requirements.

* 4.4 Conformance inspection. Sampling for inspection shall be as specified in the contract or purchase order.

* 4.4.1 Component and material inspection. Components and materials shall be inspected in accordance with all the requirements of referenced documents unless otherwise excluded, amended, modified or qualified in this specification or applicable purchase document.

4.4.1.1 Wood toggle moisture content testing. In addition to the quality assurance provisions of the subsidiary documents, the wood toggles shall be tested for conformance to the moisture content requirements in 3.2.12.1. The moisture content shall be determined in accordance with the oven-drying or the electrical meter method reference ASTM D 2016. The results shall be reported to the nearest 0.1 percent for each toggle tested. The lot size shall be expressed in toggles. The sample unit shall be one toggle. The inspection level shall be S-1.

4.4.2 In-process inspection. Inspection shall be made of the following operations or assemblies to establish conformance to specified requirements. Whenever nonconformance is noted, correction shall be made to the items affected and to the operation. Items which cannot be corrected shall be removed from production.

a. Holes punched to receive grommets conform to the requirements in 3.3.3.

b. There shall be no lubrication of polyester thread prior to or during sewing operations in compliance with 3.3.1.7.

c. Holes punched to receive male or female parts of snap fasteners are in compliance with 3.3.4.

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T22:44Z
Check the source to verify that this is the current version before use.

4.4.3 End item visual examination.

*4.4.3.1 Tent with liner and cover. The end item shall be in an erected position so that both the inside and outside of the tent can be examined, along with its cover, for defects listed in table II. The lot size shall be expressed in units of tents with covers. The sample unit shall be one tent with its cover. The inspection level shall be I.

*4.4.3.2 Cover, only. The end item shall be in an erected position so that both the inside and outside of the cover for the applicable defects listed in table II. The lot size shall be expressed in units of covers. The sample unit shall be one cover. The inspection level shall be I.

TABLE II. End item visual defects

Examine	Defect	Classification		
		Major	Minor	
			A	B
Fabric	Cut, tear, or hole (including exposed drill hole) greater than 1/8 inch in length or diameter:			
	- on tent	101		
	- on cover or snow cloth		201	
	Cut , tear, or hole (including exposed drill hole) 1/8 inch or less in length or diameter:			
	- more than 20 holes:			
	-on tent	102		
	- on cover or snow cloth		202	
	- more than 10 but not more than 20:			
	- on tent		203	
	- on cover or snow cloth			301
	- more than 5 but not more than 10:			
	- on tent			302
	Broken or missing yarns; multiple floats clearly visible at normal inspection distance (approximately 3 feet)		204	
Netting	Hole, cut or tear:			
	- more than 2 inches in length	103		
	- more than ¼ inch but not			
	- more than 2 inches in length		205	
	- ¼ inch in diameter			303
Webbing and tape	Edge frayed or scalloped			304

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T22:44Z
Check the source to verify that this is the current version before use.

Table II. End item visual defects cont'd

Examine	Defect	Classification Major	A	Minor B
Hardware	Broken	104		
	Malformed:			
	- fails to perform intended function	105		
	- but will perform intended function		206	
	Corroded area			305
	Burr or sharp edge which may cause injury in handling or damage to fabric	106		
Grommets	Improperly set; two or more teeth exposed (except where grommet is set as specified but is in an area of unequal thickness which prevents uniform clinching)			306
	Clinched loosely allowing grommet to rotate in a hole			307
	Clinched excessively tight, cutting fabric	107		
	Insecurely clinched, i.e. grommet or washer may become disengaged	108		
	Roll of a grommet contains any (splits)			308
Tent hooks	Hook not securely closed allowing connecting hardware to become disengaged		207	
	Set with hook portion facing roof			309
Snap hooks	Reversed; i.e. set with spring tongue facing roof in lieu of interior of tent in a downward position		208	
End clips	Improperly clinched, webbing not flat at point of insertion			
	Clinched excessively tight cutting webbing		209	

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T22:44Z
Check the source to verify that this is the current version before use.

TABLE II. End item visual defects cont'd

Examine	Defect	Classification Major	Minor A	Minor B
Snap fasteners	Female components used where male components are required; fasteners fail to snap in a closed position or to remain firmly closed		210	
	Roll of clinched eyelet fastener assembly contains more than three scores (splits)			310
Wood toggles	Contain knots, shakes, splits, or splintery surface		211	
Cord components	Eave lines, corner lines, or foot-Any cut; any abrasion		212	
	stops improperly knotted; free ends of lines not finished as specified			311
Tent pins	Not type specified	109		
Tent poles	Not as specified	110		
Seams and stitching	Open seam on stitch type 301: - for more than ¼ inch but not more than 1 inch			312
	- for more than 1 inch		213	
	Open seam on stitch type 401: - one row of stitching open for 1 inch or less:			
	- on tent cover			313
	- one row of stitching open for more than 1 inch:			
	- on tent roof		214	
	- on wall or cover			314
	- both rows of stitching open (not necessarily at same location):			
	- on roof	111		
	- on wall or cover		215	

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T22:44Z
Check the source to verify that this is the current version before use.

TABLE II. End item visual defects (cont'd)

Examine	Defect	Classification Major	Minor A	Minor B
Seams and Stitching (cont'd)	NOTE: A seam shall be classified as open when one or more stitches joining a seam are broken or when two or more skipped or run-off stitches occur. On double-stitched seams, a seam shall be classified as open when either one or both sides of seam are open.			
	Raw edges caught in stitching:			
	- more than 1 inch, but not more than 3 inches			315
	- more than 3 inches		216	
	Thread breaks:			
	- overstitched less than 1 inch on stitch type 401			316
	- overstitched less than 1 inch on stitch type 301			317
	- overstitched less than 3 stitches on stitch type 304			318
	NOTE: Thread breaks not overstitched shall be classified as open seams.			
	Skipped stitches:			
	- overstitched less than 1-1/2 inches on stitch type 401			319
	- overstitched less than 1 inch on stitch type 301 or 304 (where two or more consecutive skipped stitches occur)			320
	NOTE: Skipped stitches not overstitched shall be classified as open seams.			
	Needle chew resulting in cut, tear or hole (see cut, tear, or hole)			
	One or more required rows of stitching omitted (except on boxstitching and "W" stitching)	112		
Boxstitching	Incomplete:			
	- one row of stitching omitted			321

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T22:44Z
Check the source to verify that this is the current version before use.

TABLE II. End item visual defects (cont'd)

Examine	Defect	Classification Major	Minor A	Minor B
Boxstitching (cont'd)	- two or more rows of stitching omitted		217	
	Any boxstitching less than specified length by more than 1/8 inch			322
"W" stitching	Incomplete:			
	-one row of stitching omitted		218	
	-two or more rows of stitching omitted	113		
	Any "W" stitching less than specified length by more than 1 inch			323
Bartacking	Any bartacking less than specified length by more than 1/8 inch			324
Stitching ends	Overstitched less than 1/2 inch on stitch type 301 (except where ends are held down by other stitching, turned under in a hem, or where stitching is performed automatically)			325
	Secured with less than three tying, overlapping or backstitches when automatic stitching is performed			326
	Secured with less than ¼ inch of backstitching, overstitching or an increased number of stitches per inch at the end of stitch type 304			327
Seams	Seam pleated:			
	- on roof		219	
	- on eave, on wall, on cover			328
Seam type	Wrong seam type	114		
Stitch type	Wrong stitch type	115		
Stitch tension	Loose, resulting in an exposed bobbin or top thread, for more than 6 inches		220	
	Tight, as evidenced by puckering on fabric, for more than 6 stitches		221	

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T22:44Z
Check the source to verify that this is the current version before use.

TABLE II. End item visual defects (cont'd)

Examine	Defect	Classification Major	Minor A	Minor B
Stitches per inch	Less than minimum specified (except Panel joining seams):			
	- one stitch			329
	- two or more stitches		222	
	Less than minimum specified on panel joining seam		223	
	More than minimum specified:			
	- one stitch			330
	- two or more stitches		224	
	NOTE: Variation in the number of stitches Per inch, caused by the operator Speeding up the machine and pulling The fabric in order to sew over heavy Places or heavy seams or in turning Corners, shall be classified as follows:			
	a. Within the minor "B" defect classification - no defect			
	b. Within the minor "A" defect classification - minor "B" defect			
Stitching gage	Not as specified		225	
Stitching margin	Larger than specified:			
	- for more than 2 inches but not more than 4 inches in length			331
	- for more than 4 inches in length		226	
	Less than specified:			
	- for more than 2 inches but not more			
	- than 4 inches in length			332
	- for more than 4 inches in length		227	
Stitching indicated by "Z" on drawing	Chain portion of stitching shows on outside of tent, or cover		228	
Mends, darns, or patches	Repairs not in accordance with Department of the Army field Manual FM 10-16 or not authorized by the contracting officer (see 3.3.12)	116		
Repair kit	Not as specified		229	

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T22:44Z
Check the source to verify that this is the current version before use.

TABLE II. End item visual defects (cont'd)

Examine	Defect	Classification Major	Minor A	Minor B
Component and Assembly	Any component part omitted	117		
	Any component part not fabricated of applicable referenced material	118		
Hems	Constructed with partial turnunder when double turnunder is required		230	
	Twisted or pleated			333
Reinforcements	Improperly applied causing excessive fullness on reinforcement or reinforced part			334
	Number of splices per reinforcement more than permitted (see 3.3.7)		231	
	Spliced pieces not joined as shown on Drawing 5-4-289			335
Binding	Improperly or loosely applied, ends not finished as specified			336
Slide fasteners	Slider jams or fails to interlock chain	119		
	Any tape improperly assembled causing failure of chain to effect a smooth and secure closure	120		
	Wrong lengths	121		
	Width not as specified	122		
	Puckering of tape	123		
	Broken or missing scoops	124		
	Thong omitted		232	
	NOTE: The inspector shall pull slide fasteners three or four times to an open and closed position to determine proper function and effectiveness of each fastener			
Construction detail defects:				
Tent line lugs	Any lug stitched through roof only instead of through reinforcement webbing and roof reinforcement	125		

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T22:44Z
Check the source to verify that this is the current version before use.

TABLE II. End item visual defects (cont'd)

Examine	Defect	Classification		
		Major	Minor	
			A	B
Construction detail defects: (cont'd)				
Tent line lugs cont'd	Any part of lug single ply construction		233	
	Piece "B" improperly set causing fullness on tent or distortion of corners		234	
Doorway flaps	Turned-under edge of flap not stitched through door opening tape reinforcement		235	
	Top end of flap not stitched through wall, eave band and tape reinforcement		236	
	Facing improperly applied, causing fullness on flap			337
Toggles	Toggle held in place with single turn of rope around groove or double turn not overhand knotted		237	
Toggle loops	Loops not securely stitched to flap		238	
	Ends of loops exposed, i.e. not turned under or not caught in stitching attaching flap to wall			338
Beckets	Cord not continuous			339
	Any becket loose, i.e. not caught in stitching on either side		239	
	Not continuous or spliced within *6* inches of grommet			340
	Not spliced as specified			341
	More than two splices per connecting lug		240	
	Spliced cord less than *5* feet in length		241	
	Splice not centered between beckets			342
	Splices not made as indicated on Drawing 5-4-285		242	
Stovepipe shield	Set to roof with oval opening in a horizontal position instead of vertical	126		
	Exposed stitching or needle holes			343

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T22:44Z
Check the source to verify that this is the current version before use.

TABLE II. End item visual defects (cont'd)

Examine	Defect	Classification Major	Minor A	Minor B
Construction detail defects: (cont'd)				
Peak assembly	Webbing engaging snaps out of alignment with peak plate holes resulting in distortion or stress on the fabric	127		
Peak cap	Improperly applied, i.e., irregular in circumference			344
Splicing of Webbing	Splicing (when necessary) not made as indicated on Drawing 5-4-289		243	
	More than one splice per gore on seams joining tent panels		244	
Cloth splicing	Splice in roof, wall, or tent cover panels	128		
	Number on splices per reinforcement or cloth section more than specified			345
	Spliced pieces not joined as shown on Drawing 5-4-289		245	
General	Any other construction detail not performed as specified		246	
Labels	Omitted, incorrect, illegible, or misplaced:			
	- care and maintenance; erection instructions		247	
	- identification			346
Marking "US" and Identification	Omitted, incorrect, illegible, or misplaced			347
Cleanliness	Grease oil stains			348
	Thread ends not trimmed to 1/4 inch Or less (except in slide fastener area)			349
	Thread ends not trimmed to 1/4 inch Or less in slide fastener area		248	

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T22:44Z
Check the source to verify that this is the current version before use.

4.4.4 End item dimension examination.

*4.4.4.1 Tent with cover. The end item shall be in erected position so that both the inside and outside of the tent can be examined, along with its cover, for defects listed in table III. The lot size shall be expressed in units of tents with covers. The sample unit shall be one tent with its cover. The inspection level shall be S-3. arctic

*4.4.4.2 Cover only. The end item shall be in a position so that both the inside and outside of the cover can be examined for the applicable defects listed in table III. The lot size shall be expressed in units of covers. The sample unit shall be one cover. The inspection level shall be S-3.

TABLE III. End item dimensional defects

Examine	Defect	Classification		
		Major	Minor	
			A	B
Overall dimensions of tent	Smaller than specified dimensions less applicable minus tolerance indicated on drawing	101		
	Larger than specified dimensions and applicable plus tolerance indicated on drawings			301
Dimensions: tent cover; ventilator opening	Smaller than specified dimensions less applicable minus tolerance indicated on drawings, but not smaller than the specified dimensions less twice the applicable minus tolerance			302
	Smaller than specified dimensions less twice the applicable minus tolerance indicated on drawing		201	
	Larger than specified dimensions and applicable plus tolerance indicated on drawings			303
Location dimensions	Not within specified tolerance (unless otherwise specified)		202	
Webbing, tie tapes	Finished length less than specified by more than 1 inch			304
	Distance between splices on webbing less than 5 feet			305
Grommets	Set beyond specified specified location by more than 1/2 inch			306

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T22:44Z
Check the source to verify that this is the current version before use.

TABLE III. End item dimensional defects cont'd

Examine	Defect	Classification		
		Major	Minor	
			A	B
Cord components:	Eye on footstop or line less than specified by more than 2 inch			307
	Finished length of guy line less than specified:			
	- by more than 4 inches			308
	- by more than 4 inches but not more than 12 inches		203	
	- by more than 12 inches	102		
Beckets	Misplaced:			
	- by more than ¼ inch but not more than 1/2 inch			309
	- by more than 1/2 inch		204	
	Length of loop more or less than specified by 1/2 inch or more		205	
Toggle loops	Free ends of loop extending less than 3/4 inch beyond edge of flap			310
Metal toggle Chapes	Misplaced:			
	- by more than 1/4 inch but not more than 1/2 inch			311
	- by more than 1/2 inch		206	
Hems	Hems required to finish less than ¾ inch in width, less than specified; hems required to finish more than ¾ inch in width, less than specified by more than 1/4 inch			312
Reinforcements	Finished dimensions less than specified by more than 1/2 inch			313
	Any spliced piece less than 2 feet in length			314
Tent line lugs	Loop portion of piece "A" less than 3/4 inch		207	

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T22:44Z
Check the source to verify that this is the current version before use.

TABLE III. End item dimensional defects cont'd

Examine	Defect	Classification Major	Minor A	Minor B
Snow cloths	Less than specified width by more than 1 inch			315
Doorway flaps	Bottom end of flap uneven with breakline of wall by more than 1/4 inch; outer edge or end of facing uneven with edge or end of flap by more than 1/4 inch			316
Peak of wall	Peak of wall halves joined to roof with edges of door opening less than 7/8 inch apart, failing to provide clearance for top of slide fastener		208	
Ventilator opening	Misplaced: - by more than 1/2 inch			317
Stovepipe opening	Misplaced: - by more than 1/2 inch			318
Ring, ring chapes, straps and strap reinforcement	Misplaced: - by more than ¼ inch but not more than 1/2 inch - by more than 1/2 inch		209	319
Cover flaps	Center line of flaps set off center of body more than 3/4 inch			320

4.4.5 End item testing. The completely fabricated tents with covers shall be tested as specified in 4.5.1 for conformance to the wicking requirements specified in 3.3.11. The lot size shall be expressed in units of tents. The sample size shall be the number of tents indicated by inspection level S-3. Any test failure shall be cause for rejection of the lot.

4.4.6 Packaging examination. The fully packaged end items shall be examined for the defects listed below. The lot size shall be expressed in units of shipping containers. The sample unit shall be one shipping container fully packaged. The inspection level shall be S-2.

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T22:44Z
Check the source to verify that this is the current version before use.

Examine	Defect
Marking (exterior and interior	Omitted; incorrect; illegible; of improper size, location; sequence, or method of application.
Materials	Any component missing, damaged, or not as specified.
Workmanship	Inadequate applications of components such as; incomplete closure of cloth covered bundles or bundles insecurely sewn.

4.5 Methods of inspection.

4.5.1 Wicking of sewing thread (cup test). The tent shall be tested in each of the three areas as follows: at the peak, ridge or joining seam abutting the peaks or ridge; at an intersection of a horizontal and vertical seam such as at an intersection of a side wall and roof; and on a roof panel seam. Suspend the seamed section of the test fabric in the center of a 6 ± 1/8 inch diameter hoop and form a depression with the seamed fabric in the hoop to a depth of 1 + ¼ inch. Slowly pour 500 mL of water at 77°F ± 4°F into the cupped area (depression) and observe the under surface of the fabric for water penetration. Any wicking of water along the sewing thread, identified by a discoloration or darkening of the thread within five minutes after water is poured, shall constitute a test failure. Water leakage through the needle holes or between the plies of the lapped seamed fabric shall not be considered a failure.

5. **PACKAGING**

*5.1 Packaging. For acquisition purposes, the packaging requirements shall be as specified in the contract or order (see 6.2). When actual packaging of materiel is to be performed by DoD personnel, these personnel need to contact the responsible packaging activity to ascertain requisite packaging requirements. Packaging requirements are maintained by the Inventory Control Point's packaging activity within the Military Department or Defense Agency, or within the Military Department's System Command. Packaging data retrieval is available from the managing Military Department's or Defense Agency's automated packaging files, CD-ROM products, or by contacting the responsible packaging activity.

6. **NOTES**

*(This section contains information of a general or explanatory nature that may be helpful, but is not mandatory.)

6.1 Intended use. The tent, with the liner, is intended for use as a temporary shelter for troops operating in extremely cold and cold-wet areas.

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T22:44Z
Check the source to verify that this is the current version before use.

* 6.2 Acquisition requirements. Acquisition documents should specify the following:

a. Title, number and date of this specification.
b. When first article inspection is required, (see 3.1 and 4.3).
c. When pins and poles are required (see 3.2.25 and 3.2.26).
d. Which of the following items to be purchased:

1. Tent with liner and cover, or
2. Tent with liner,tent pole, tent pins and cover, or
3. Tent only, or
4. Tent covers

* 6.3 Standard samples. For access to a standard shade of thread, address the contracting activity issuing the invitation for bids.

* 6.4 Other components. The following components are required for the erection of the tent:

1 each — Pole, Tent, Telescopic, adjustable 5 feet to 9 feet, Magnesium

For erection on hard ground, unfrozen

28 each — Pin, Tent, Aluminum, 9 inches

* 6.5 Seams to be treated. It is recommended that seams which have failed the test specified in 4.5.1 be treated as follows:

a. Failure at roof panel lap seams — treat all roof panel lap seams.

b. Failure at peak reinforcement — paint all peak reinforcement stitching.

c. Failure at eave — paint all stitching at eave and webbing reinforced roof joining seams.

* 6.5.1 Repairs of leaking seams. Applying the textile compound for the repair of leaking seams is as follows:

a. Stir and dilute a suitable volume of textile compound conforming to type I, class 1 of TT-P-595 with an equal volume of petroleum solvent (Stoddard solvent or equivalent). Thoroughly stir the mixture again before use.

b. Prior to application of the compound, the tent must be dry. Special attention must be taken to ensure adequate ventilation and that proper fire prevention measures are taken since the compound is flammable.

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T22:44Z
Check the source to verify that this is the current version before use.

c. Apply two coats of the textile compound to the seams (on the outside of the tent only). A 4-inch wide stiff brush is recommended for use. Allow the first coat to air dry for a minimum of 4 hours prior to application of the second coat. Elapsed time between coats may be reduced by providing a supply of hot air to evaporate the solvent more quickly. In this manner, apply second coat as soon as the first coat is dry. After the application of the second coat, allow the treated tent to air dry for a period of at least 24 hours.

6.4 Subject term (key word) listing.

Shelter
Pole Support
Liner
Extreme Cold /Cold Wet

6.5 International standardization agreements. Certain provisions of this document are the subject of international standardization agreement as cited in NATO, STANAG No. 2882, relative to camouflage requirements for tents, shelters and subsidiary components. When amendment, revision, or cancellation of this document is proposed which will affect or violate the international agreement concerned, the preparing activity will take appropriate reconciliation action through international standardization channels including departmental standardization offices, if required.

*6.6 Changes from previous issue. The margins of this specification are marked with asterisks (*) to indicate where changes from the previous issue were made. This was done as a convenience only and the Government assumes no liability whatsoever for any inaccuracies in these notations. Bidders and contractors are cautioned to evaluate the requirements of this document based on the entire content irrespective of the marginal notations and relationship to the last previous issue.

MILITARY 1NTERESTS:

Custodians:
Army-GL
Navy-MC
Air Force-11

Preparing activity:
DLA-CT

Review activities:
Army-MD
Air Force-11.6

(Project 8340-0578)

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T22:44Z
Check the source to verify that this is the current version before use.

STANDARDIZATION DOCUMENT IMPROVEMENT PROPOSAL

INSTRUCTIONS

1. The preparing activity must complete blocks 1, 2, 3, and 8. In block 1, both the document number and revision letter should be given.
2. The submitter of this form must complete blocks 4, 5, 6, and 7 and send to preparing activity.
3. The preparing activity must provide a reply within 30 days from receipt of the form.

NOTE: This form may not be used to request copies of documents, nor to request waivers, or clarification of requirements on current contracts. Comments submitted on this form do not constitute or imply authorization to waive any portion of the referenced document(s) or to amend contractual requirements.

I RECOMMEND A CHANGE:	**1. DOCUMENT NUMBER** MIL-DTL-12354G	**2. DOCUMENT DATE *(YYYYMMDD)*** 2000DEC21

3. DOCUMENT TITLE

TENT, ARCTIC, 10 MAN

4. NATURE OF CHANGE *(Identify paragraph number and include proposed rewrite, if possible. Attach extra sheets as needed.)*

5. REASON FOR RECOMMENDATION

6. SUBMITTER

a. NAME *(Last, First, Middle Initial)*	b. ORGANIZATION	
c. ADDRESS *(Include Zip Code)*	d. TELEPHONE *(Include Area Code)* (1) Commercial (2) DSN *(If applicable)*	7. DATE SUBMITTED *(YYYYMMDD)*

8. PREPARING ACTIVITY

a. NAME DEFENSE SUPPLY CENTER PHILADELPHIA DSCP-CNRP	b. TELEPHONE *(Include Area Code)* (1) Commercial (215) 737-5653 (2) DSN 444-5653
c. ADDRESS *(Include Zip Code)* 700 Robbins Ave (Bldg 6, C&T) PHILADELPHIA, PA 19111-5092	**IF YOU DO NOT RECEIVE A REPLY WITHIN 45 DAYS, CONTACT:** Defense Standardization Program Office (DLSC-LM) 8725 John J. Kingman Road, Suite 2533 Fort Belvoir, Virginia 22060-6221 Telephone (703) 767-6888 DSN 427-6888

DD Form 1426, FEB 1999 (EG) PREVIOUS EDITION IS OBSOLETE WHS/DIOR, Feb 99

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T22:44Z
Check the source to verify that this is the current version before use.