MIL-F-50823A (AR)
AMENDMENT 5
15 DECEMBER 1980
SUPERSEDING
AMENDMENT 4
15 May 1978

MILITARY SPECIFICATION

FUZE, GM, ET, LANCE, M811
PARTS, LOADING, ASSEMBLING AND PACKING

This Amendment forms a part of Military Specification MIL-F-50823A (AR) dated 8 November 1974.

PAGE 3

3.3.5: Delete first two tests and replace with the following:

"K	shorted to L	to M
L	shorted to M	to K
K	shorted to M	to L

Delete the "R" in the last test and add the following test:

"R to chassis".

* 3.3.6 - Add the following:

"The resistance between connector pins A to B and B to D shall be 1.0 ohm minimum @ -40 degrees F".

PAGE 4

3.3.7.2: Delete in its entirety.

PAGE 5

3.4.2: Add the following: "The criteria for passing the reduced pressure test of para. 4.4.2.14 shall be a visual that the piston has extended".

FSC: 1336

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:39Z
Check the source to verify that this is the current version before use.

PAGE 8

* 3.5.8 - Add the following:

"The resistance, when tested at -40 degrees F, shall be 3.0 ± 1.5 ohms".

PAGE 9

3.6.1.1: Insert the complete paragraph:

3.6.1.1: Detonator Shorting Wire. The detonator shorting wire shall be removed such that no remaining section of the wire can contact any other section. All removed sections shall be accounted for.

PAGE 11

* 3.6.5.4: Add the following:

"SCO Interlock P2-9 to J3-R 0.1 Ohm Max".

* 3.6.5.4: Change the Resistance against Set Interconnect, P2-1 to P2-7 from "1K ± 10%" to "1K ± 15%".

PAGE 12

* 3.6.6.1: Delete "J1-5 to Chassis".

* 3.6.6.2: Delete "SCO Interlock J1-5 to J1-6, 50 Megohms Min."

PAGE 13

3.7.3: Delete "1 x 10" and substitute "1 x 10^{-6}".

PAGE 14

3.7.12 Delete "shown" and substitute "shock".

PAGE 19

3.13: Insert the complete paragraph:

3.13: Escapement and Gear Assembly (9243620). The escapement and gear assembly shall meet all requirements of its applicable drawings and of the tests contained herein.

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:39Z
Check the source to verify that this is the current version before use.

3.13.1: Spring Embrittlement. No spring used in the fabrication of the escapement shall break when extended or distorted to the point of minimum permanent distortion.

PAGE 26

4.3.2.11: Insert the complete paragraph:

4.3.2.11: Detonator (See dwg. 9243603 covering a detail dwg. 9242183).

Categories	Defects	Method of Inspection
Critical:		
1.	Improper detonator	Visual

Categories	Defects	Method of Inspection
	AQL 0.40 Percent	
Major:		
101	Diameter of case	Gage
102	Length of case	Gage
103	Length of insulation on wires	Scale
104	Minimum solderable area	Scale
105	Diameter of lead wires	Gage
	AQL 0.65 Percent	
Minor:		
201	Evidence of poor workmanship	Visual

PAGE 28

4.3.2.13: Delete "MIL-S-60902" and substitute "MIL-S-45743".

PAGE 29

4.3.2.17: Delete "MIL-S-60902" and substitute "MIL-S-45743".

PAGE 30

4.3.2.18: Delete "MIL-S-60902" and substitute "MIL-S-45743".

4.3.2.19: Delete "MIL-S-60902" and substitute "MIL-S-45743".

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:39Z
Check the source to verify that this is the current version before use.

4.3.2.20: Delete "MIL-S-60902" and substitute "MIL-S-45743".

PAGE 31

4.3.2.21: Add Critical 4 as follows:

"4. Integrity of rotor contact.....Visual"
assembly, detonator shorting
wire/solder joint.

4.3.2.21: Add Major 112 as follows:

"112. Integrity of detonator.....Visual"
lead wire/solder joint.
(After shorting wire removed).

4.3.2.21: Major 103 - Delete in its entirety.

4.3.2.21: Major 108 - Delete and substitute:

"Minimum torque on terminal board standoff screws".

4.3.2.21: Add Major 111 as follows:

"111. Height Overall (1.72 inch max).....Gage".
improper

PAGE 37

TABLE 1: Group IX - Reduced Pressure - Change requirement paragraph from 3.5.16 to 3.5.15. Remove the "20" in the "All Fire (MN-AFV)" row and replace the "20" in the -40 degrees F. Column.

PAGE 42

TABLE 3: Group III - Resistance Bridgewire - Change para. 3.8.6 to 3.8.5 and change para. 4.4.6.6 to 4.4.6.5.

PAGE 48

TABLE 4: Groups VI, VII and VIII - Insulation Resistance (Post Fire) - transpose 3.9.4.2 to 3.4.9.2.

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:39Z
Check the source to verify that this is the current version before use.

PAGE 54

4.3.3.5: Change to read: 4.3.3.2.5

4.3.3.5.1: Change to read: 4.3.3.2.5.1

PAGE 56

4.3.3.2.8: Insert the following:

"A 100% inspection shall be made of the sealed Tuning Fork Resonator (Dwg. 9251908) to determine that the coil polarity is correct.

4.3.3.2.10: Insert the complete paragraph:

4.3.3.2.10: Escapement Gear Assembly. Each lot of escapements submitted for acceptance, shall be subjected to the acceptance inspections specified in Table 7. Assemblies failing to comply with the critical, non-destructive requirements, shall be classed defective and removed from the lot.

4.3.3.2.10.1: Lever Pallet Load Test, Pre-Production. Prior to lot production, a sample of 50 lever assemblies (Dwg. 8883706 - with or without shaft assembled) shall be assembled and tested to the destructive requirement. Testing shall be in accordance with 4.4.9.5.

4.3.3.2.10.2: Spring Embrittlement (See 3.13.1). A sample of 10 springs shall be selected from each heat treatment batch. The batch shall be rejected if one or more springs fail to comply with the specified requirement. Springs tested as specified shall be discarded as scrap. Testing shall be in accordance with 4.4.9.9.

TABLE 7: Insert the complete Table:

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:39Z
Check the source to verify that this is the current version before use.

TABLE 7

ESCAPEMENT AND GEAR ASSEMBLY, ACCEPTANCE INSPECTION FOR

CATEGORY	EXAMINATION OR TEST	REQUIREMENT PARAGRAPH	METHOD PARAGRAPH NOTE 3/	SAMPLE, NON-DEST.	AQL OR 100% DEST. 4/
Critical	Load Test of No. 1 Gear and Pinion Assy	3.2	4.4.9.1	100%	40 1/
Critical	Load Test of No. 2 Gear and Pinion Assy	3.2	4.4.9.2	100%	40 1/
Critical	Load Test of Escapement Gear and Pinion Assy	3.2	4.4.9.3	100%	40 1/
Critical	Load Test of Lever Shaft	3.2	4.4.9.4	100%	40 1/
Critical	Load Test of Lever Pallet	3.2	4.4.9.5	100%	40 1/
Critical	Torque Test of Lever Shaft	3.2	4.4.9.6	--	0.10% 2/
Critical	Load Test of Bridge Rivet	3.2	4.4.9.7	--	0.10% 2/
Major	Load Test of Pillars	3.2	4.4.9.8	--	0.10% 2/
Major	Spring Embrittlement	3.13.1	4.4.9.9	--	10

1/ Forty (40) items or the summation of 5 items per each hour of production shall be destructively tested, whichever is greater. Destructive sample shall be drawin after 100% testing.
2/ Sampling Plan per MIL-STD-105, - Inspection Level II.
3/ Appropriate forces for the destructive and non-destructive tests are found on the respective assembly dwgs. (see 4.4.9).
4/ All items tested destructively shall be discarded as scrap.

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:39Z
Check the source to verify that this is the current version before use.

PAGE 60

4.4.1.8.1.1: Delete "4.4.1.8.1.1: and substitute "4.4.1.8.1.2".

PAGE 63

* 4.4.2.8: Change, in part, from: "... 100 + 5 milliamperes..." to "... 30 + 5 milliamperes...".

PAGE 64

4.4.2.15: Add the following: "Silastic compound is permitted on the front of the piston actuator and this may be removed for this test."

PAGE 67

4.4.4: Delete (see 3.6) and substitute (4.3.3.2.4.2). Also delete entire last sentence (Testing shall be in the order indicated below).

4.4.4.3: Delete "SCO" and substitute "SECO".

PAGE 68

* 4.4.4.7: Insert the complete paragraph:

"4.4.4.7 SCO Interlock Check. After the test in 4.4.4.4 has been completed, but prior to installation of the S&A, an electrical check shall be made between J1-6 and J3-R and shall read 50 Megohms minimum. Current limit shall be one (1) ma maximum."

PAGE 70

4.4.5.11: Delete "8.3VDC MAX" and substitute "10VDC MAX".

PAGE 72

4.4.6.6: Insert the complete paragraph:

"4.4.6.6 Output (Switch) Resistance (see 3.8.5) - The output leadwire to leadwire resistance shall be measured as specified in MIL-STD-202, Test Method 303, using a test current of 1.0 ± 0.1 milliamperes."

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:39Z
Check the source to verify that this is the current version before use.

PAGE 77

* 4.4.7, Step 7: Change in part, to read as follows:

".. in accordance with Paragraphs 4.4.4.4 and 4.4.4.7."

PAGE 78

4.4.8: Insert the complete paragraph:

"4.4.8 The switches shall be mounted in an approved fixture in order that contact resistance can be measured in each position. The switches shall be rotated (360 degrees) 25 times in each direction with measurements made in each position."

4.4.9: Insert the complete paragraph:

"4.4.9 Escapement and Gear Assembly

4.4.9.1 Load Test of No. 1 Gear and Pinion Assembly. - Apply an axial load perpendicular to the No. 1 gear and in such a direction as to test the assembly of th No. 1 gear and pinion. The resistive force shall act against the No. 1 gear. Upon removal of the non-destructive force, the maximum permissible gap shall be inspected for compliance with the drawing requirement. Any pinion that breaks away from the gear during destructive testing shall be classed defective (see dwg. 8883703).

4.4.9.2 Load Test of No. 2 Gear and Pinion Assembly. - Apply an axial load perpendicular to the No. 2 gear and in such a direction as to test the assembly of the No. 2 gear and pinion. The resistive force shall act against the No. 2 gear. Upon removal of the non-destructive force, the maximum permissible gap shall be inspected for compliance with the drawing requirement. Any pinion that breaks away from the gear during destructive testing shall be classed defective (see dwg. 8883700).

4.4.9.3 Load Test of Escapement Gear and Pinion Assembly. - Apply an axial load perpendicular to the escapement gear and in such a direction as to test the assembly of the escapement gear and pinion. The resistive force shall act against the escapement gear. Upon removal of the non-destructive force, the maximum permissible gap shall be inspected for compliance

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:39Z
Check the source to verify that this is the current version before use.

with the drawing requirement. Any pinion that breaks away from the gear during destructive testing shall be classed defective (see dwg. 8883710).

4.4.9.4 Load Test of Lever Shaft. - Apply an axial load perpendicular to the lever and in such a direction as to test the assembly of the lever and lever shaft. The resistive force shall act against the lever. Upon the removal of the non-destructive force, the maximum permissible gap shall be inspected for compliance with the drawing requirement. Any lever shaft that breaks away from the lever during destructive testing shall be classed defective (see dwg. 8883706).

4.4.9.5 Load Test of Lever Pallet. - Apply an axial load perpendicular to the lever and in such a direction as to test the assembly of the lever and lever pallet. The resistive force shall act against the lever. Upon the removal of the required force, destructive or non-destructive, the height of the lever pallet above the lever shall be inspected for compliance with the drawing requirement (see dwg. 8883706).

4.4.9.6 Torque Test of Lever Shaft. - The required torque shall be applied between the lever and lever shaft. Any rotational motion observed during the test shall be sufficient to class the assembly defective (see dwg. 8883706).

4.4.9.7 Load Test of Bridge Rivet. - Apply the required axial load perpendicular to the inner plate and into the bridge rivet from the side opposite the bridge. The resistive force shall act against the inner plate. Any rivet that loosens shall be classed defective (see dwg. 8883693).

4.4.9.8 Load Test of Pillars. - Apply the required axial load perpendicular to the inner plate and in such a direction as to test the assembly of the pillars to the inner plate and outer plate. The resistive force shall act against the inner plate. Upon removal of the required force, the maximum thickness from the outer to inner plate shall be inspected for compliance with the drawing requirement (see dwg. 9243620).

4.4.9.8 Spring Embrittlement (see 3.13.1). - The spring shall be stretched along its longitudinal axis until the spring no longer returns to its original position. When the spring no longer returns to its original or profile, it shall be considered distorted permanently. Any spring that breaks prior to this point shall be classed defective.

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:39Z
Check the source to verify that this is the current version before use.

NOTE: "The margins of this amendment are marked with an asterisk to indicate where changes (additions, modifications, corrections, deletions) from the previous amendment were made. This was done as a convenience only and the Government assumes no liability whatsoever for any inaccuracies in these notations. Bidders and contractors are cautioned to evaluate the requirements of this document based on the entire content irrespective of the marginal notations and relationship to the last previous amendment."

Custodian:
Army-AR

Preparing activity:
Army-AR

Project No.: 1336-A336

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:39Z
Check the source to verify that this is the current version before use.