MILITARY SPECIFICATION

FUZE, MINE, AT, M607
LOADING, ASSEMBLING AND PACKING

This Amendment forms a part of Military Specification MIL-F-45429C(AR), dated 6 June 1986, and is approved for use within the U.S. Army Armament, Munitions and Chemical Command, and is available for use by all Departments and Agencies of the Department of Defense.

PAGE 3

3.3: Delete in its entirety and substitute with the following:

"3.3 Jolt. The loaded fuzes shall withstand the jolt test specified in MIL-STD-331 when tested as specified in 4.5.2."

3.4:

Add the following new paragraph:

"3.4 Jumble. The loaded fuzes shall withstand the jumble test specified in MIL-STD-331 when tested as specified in 4.5.3".

Renumber "3.4" to "3.5" and "4.5.3" to "4.5.4".

3.5: Renumber "3.5" to "3.6".

3.6: Renumber "3.6" to "3.7" and "4.5.4" to "4.5.5".

3.7: Renumber "3.7" to "3.8".

3.8: Renumber "3.8" to "3.9".

AMSC N/A FCS 1345

DISTRIBUTION STATEMENT A. Approved for public release; distribution is unlimited.

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T02:58Z
Check the source to verify that this is the current version before use.

PAGE 4

4.3.1, Under "Quantities": Delete in its entirety and substitute with the following:

"Quantities

10
10

10
62".

PAGE 5

TABLE I: Delete in its entirety and substitute with the new TABLE I included.

PAGE 7

4.4.2.1, Minor 201: Change AQL to "1.0%" and Requirement Paragraph to "3.9".

PAGE 8

4.4.2.2, Minor 201: Change AQL to "1.0%" and Requirement Paragraph to "3.9".

PAGE 9

4.4.2.3:

Change "Minor 201" to "Major 101" with an AQL of "0.40%".

Change "Minor 202" to read:

"201 Workmanship 1.0% 3.9 Visual".

PAGE 10

4.4.2.4: Delete in its entirety and substitute with the new Paragraph 4.4.2.4 included.

Source: https://assist.dla.mil -- Downloaded: 202610-22T02:58Z
Check the source to verify that this is the current version before use.

TABLE I. First article inspection

CLASSIFICATION OF DEFECTS & TESTS

MIL-F-45429C(AR)
AMENDMENT 1

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
	Fuze, Mine, AT, M607				See below
					NEXT HIGHER ASSEMBLY

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
	Assembly prior to staking detonator (Dwg. 8833784)				
	Examination for defects	10		3.2	4.4.2.1
	Assembly prior to staking retainer (Dwg. 8833783)				
	Examination for defects	10		3.2	4.4.2.2
	Assembly prior to assembly of closure assembly (Dwg. 8833783)				
	Examination for defects	10		3.2	4.4.2.3
	Loading assembly (Dwg. 8833783)				
	Examination for defects	50		3.2	4.4.2.4
	X-ray	50-0-1 (1)		3.7	4.5.5
	Static functioning	50-1-2 (1)		3.5	4.5.4
	Jolt	6-0-1		3.3	4.5.2
	Jumble	6-0-1		3.4	4.5.3

NOTES:
(1) X-ray prior to static functioning.

AMSMC Form 1570, 1 Feb 85 — Replaces DRSMC-QA (D) Form 160, 1 Aug 83, which may not be used.

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T02:58Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE	SHEET	DRAWING NUMBER
4.4.2.4	Fuze, Mine, AT, M607, Loading Assembly	1 OF 1	8833783
			NEXT HIGHER ASSEMBLY: ---

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical					
1	Boxed and pin missing		100%	3.2	Visual
2	X-ray		100%	3.7	4.5.5
3	Jolt	6-0-1 (1)		3.3	4.5.2
4	Jumble	6-0-1 (1)		3.4	4.5.3
Major					
101	Closure assembly turns when min. torque is applied in tightening direction		0.40%	3.6	4.5.1
102	Assembly damaged (dented, deformed, cracked, or punctured)		0.40%	3.2	Visual
103	Static functioning		0.40%	3.5	4.5.4
104	Jolt	6-0-1 (1)		3.3	4.5.2
105	Jumble	6-0-1 (1)		3.4	4.5.3
Minor					
201	Protective coating damaged (other than light scratches)		0.65%	3.2	Visual
202	Marking misleading or unidentifiable		0.65%	3.2	Visual
203	Poor workmanship		1.0%	3.9	Visual

NOTES:
(1) Samples which have detonator firing during tests shall be classed as critical defects. Samples which fail for causes other than detonator firing shall be classed as major defects.

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T02:58Z
Check the source to verify that this is the current version before use.

PAGE 13

4.5.2: Delete in its entirety and substitute with the following:

"4.5.2 Jolt. The fuze shall be assembled to a specified fixture and subjected to the jolt test as specified in MIL-STD-331. Upon completion of the test, the fuze shall be examined for detonator firing, unseating of the detonator or other listed defects by removing the boxed end pin, band and stop".

4.5.3: Delete in its entirety and substitute with the following:

"4.5.3 Jumble. The fuze shall be subjected to the jumble test as specified in MIL-STD-331. Upon completion of the test, the fuze shall be examined for detonator firing, unseating of the detonator or other listed defects be removing the boxed and pin, band and stop".

PAGE 14

4.5.4: Delete in its entirety and substitute with the following:

"4.5.4 Static functioning. The closure assembly, boxed end pin and the band and stop shall be removed from the fuzes. A vertical load of 400 ± 10 lbs. shall be applied to the pressure ring of the fuze until functioning occurs. Observation shall be made for satisfactory functioning as specified in 3.5".

4.5.5: Add the following new paragraph:

"4.5.5 X-ray of loaded fuze assembly. The entire production of loaded fuze assemblies, less tilt rod extension, shall be x-rayed to confirm proper seating of the tilt rod on the firing pin spring assembly, presence of tilt rod groove pin and firing pin spring assembly groove pin, and to assure firing pin spring assembly is in the correct position for firing".

PAGE 15

6.5:

Renumber "6.5" to "6.6".

Source: https://assist.dla.mil -- Downloaded: 202610-22T02:58Z
Check the source to verify that this is the current version before use.

Add the following new paragraph "6.5":

"6.5 Intended use. When the M607 is manufactured specifically to be used in the M624 Adapter and Fuze Assembly, the closure assembly will not be manufactured and therefore all references to said assembly are not applicable."

Custodian:
Army-AR

Preparing activity:
Army-AR

(Project 1345-A384)

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T02:58Z
Check the source to verify that this is the current version before use.