INCH-POUND
MIL-F-45429C(AR)
AMENDMENT 2
27 March 1998
SUPERSEDING
AMENDMENT 1
12 September 1986

MILITARY SPECIFICATION

FUZE, MINE, AT, M607
LOADING, ASSEMBLING AND PACKING

MIL-F-45429C was inactivated after 5 February 1997 for New Design.

This amendment forms a part of MIL-F-45429C(AR), dated 6 June 1986, and is approved for use by the U.S. Army Armament Research, Development and Engineering Center, and is available for use by all Departments and Agencies of the Department of Defense.

PAGE 3

3.3: Delete in its entirety and substitute with the following:

"3.3 Jolt. The loaded fuzes shall withstand the jolt test specified in MIL-STD-331 when tested as specified in 4.5.2."

3.4:

Add the following new paragraph:

"3.4 Jumble. The loaded fuzes shall withstand the jumble test specified in MIL-STD-331 when tested as specified in 4.5.3."

Renumber "3.4" to "3.5" and "4.5.3" to 4.5.4"

3.5: Renumber "3.5" to "3.6".

3.6: Renumber "3.6" to "3.7" and "4.5.4" to "4.5.5".

3.7: Renumber "3.7" to "3.8".

AMSC N/A FSC 1345

DISTRIBUTION STATEMENT A. Approved for public release; distribution is unlimited.

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T02:58Z
Check the source to verify that this is the current version before use.

3.8: Renumber “3.8” to “3.9”.

PAGE 4

4.3.1, Under “Quantities”: Delete in its entirety and substitute with the following:

“Quantities

10
10

10
62”.

PAGE 5

TABLE I: Delete in its entirety and substitute with the new TABLE I included.

PAGE 7

4.4.2.1, Minor 201: Change AQL to “1.0%” and Requirement Paragraph to “3.9”.

PAGE 8

4.4.2.2, Minor 201: Change AQL to “1.0%” and Requirement Paragraph to “3.9”.

PAGE 9

4.4.2.3:

Change “Minor 201” to Major “101” with an AQL of “0.40%”.

Change “Minor 202” to read:

“201 Workmanship 1.0% 3.9 Visual”.

PAGE 10

4.4.2.4:
Delete in its entirety and substitute with the new Paragraph 4.4.2.4 included.

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T02:58Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS AND TESTS

PARAGRAPH	TITLE: Fuze, Mine, AT, M607			SHEET 1 OF 1	DRAWING NUMBER: see below
CLASSIFICATION	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAPGRAPH	NEXT HIGHER ASSEMBLY / INSPECTION METHOD REFERENCE
	Assembly prior to staking detonator				
	(Dwg. 8833784)				
	Examination for defects	10		3.2	4.4.2.1
	Assembly prior to staking retainer				
	(Dwg, 8833783)				
	Examination for defects	10		3.2	4.4.2.2
	Assembly prior to assembly of closure assembly				
	(Dwg. 8833783)				
	Examination for defects	10		3.2	4.4.2.3
	Loading assembly				
	(Dwg. 8833783)				
	Examination for defects	50		3.2	4.4.2.4
	X-ray	50-0-1 (1)		3.7	4.5.5
	Static functioning	50-1-2 (1)		3.5	4.5.4
	Jolt	6-0-1		3.3	4.5.2
	Jumble	6-0-1		3.4	4.5.3

NOTES (1) X-ray prior to static functioning

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T02:58Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS AND TESTS

PARAGRAPH	TITLE			SHEET	DRAWING NUMBER
4.4.2.4	Fuze, Mine, AT, M607, Loading Assembly			1 OF 1	8833783

CLASSIFICATION	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAPGRAPH	NEXT HIGHER ASSEMBLY / INSPECTION METHOD REFERENCE
Critical					
1	Box and pin missing		100%	3.2	Visual
2	X-ray		100%	3.7	4.5.5
3	Jolt	6-0-1 (1)		3.3	4.5.2
4	Jumble	6-0-1 (1)		3.4	4.5.3
Major					
101	Closure assembly turns when min. torque is applied in tighten direction		0.40%	3.6	4.5.1
102	Assembly damaged (dented, deformed, cracked, or punctured)		0.40%	3.2	Visual
103	Static functioning		0.40%	3.5	4.5.4
104	Jolt	6-0-1 (1)		3.3	4.5.2
105	Jumble	6-0-1 (1)		3.4	4.5.3
Minor					
201	Protective coating damaged (other than light scratches)		0.65%	3.2	Visual
202	Marking misleading or unidentifiable		0.65%	3.2	Visual
203	Poor workmanship		1.0%	3.9	Visual

NOTES (1) Samples which have detonator firing during tests shall be classed as critical defects. Samples which fail for causes other than detonator firing shall be classed as major defects.

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T02:58Z
Check the source to verify that this is the current version before use.

* Critical 1: Delete “Boxed end pin missing” and substitute “Boxed end pin missing or improperly assembled”.

* Add new major 106 as follows: “106 Boxed end pin installed incorrectly 3.3 Visual”.

* Critical 4: Add “(2)” under “6-0-1”.

* Major 105: Add “(2)” under “6-0-1”.

* NOTES: Delete in its entirety and substitute the folowing:

“(1) Samples which have the detonator firing during tests or have a cracked collars at the completion of the test shall be classed as critical defects. Samples which fail for other causes shall be classed as major defects.

(2) Jumble tests are not required for M607 lot acceptance testing when the M607 Fuze is manufactured as a subasssembly for the M624 Adapter and Fuze.”

PAGE 13

4.5.2: Delete in its entirety and substitute with the following:

“4.5.2 Jolt. The fuze shall be assembled to a specified fixture and subjected to the jolt test as specified in MIL-STD-331. Upon completion of the test, the fuze shall be examined for detonator firing, unseating of the detonator or other listed defects by removing the boxed end pin, band and stop.”

4.5.3: Delete in its entirety and substitute with the following:

“4.5.3 Jumble. The fuze shall be subjected to the jumble test as specified in MIL-STD-331. Upon completion of the test, the fuze shall be examined for detonator firing, unseating of the detonator or other listed defects by removing the boxed pin, band and stop.”

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T02:58Z
Check the source to verify that this is the current version before use.

PAGE 14

4.5.4: Delete in its entirety and substitute with the following:

"4.5.4 Static functioning. The closure assembly, boxed end pin and the band and stop shall be removed from the fuzes. A vertical load of 400 ± 10 lbs. shall be applied to the pressure ring of the fuze until functioning occurs. Observation shall be made for satisfactory functioning as specified in 3.5."

* Line 3: Delete "400 ± 10" and substitute "510 ± 10".

4.5.5: Delete in its entirety and substitute with the following:

"4.5.5 X-ray of loaded fuze assembly. The entire production of loaded fuze assemblies, less tilt rod extension, shall be x-rayed to confirm proper seating of the tilt rod on the firing pin spring assembly, presence of tilt rod groove pin and firing pin spring assembly groove pin, and to assure firing pin spring assembly is in the correct position for firing."

PAGE 15

6.5:

Renumber "6.5" to 6.6.".

Add the following new paragraph "6.5":

"6.5 Intended use. When the M607 is manufactured specifically to be used in the M624 Adapter and Fuze Assembly, the closure assembly will not be manufactured and therefore all references to said assembly are not applicable."

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T02:58Z
Check the source to verify that this is the current version before use.

The margins of this amendment are marked with an asterisk or vertical line to indicate where changes (additions, modifications, corrections, deletions) from the previous amendment were made. This was done as a convenience only and the Government assumes no liability whatsoever for any inaccuracies in these notations. Bidders and contractors are cautioned to evaluate the requirements of this document based on the entire content irrespective of the marginal notations and relationship to the last previous amendment.

Custodian:
Army-AR

Preparing activity:
Army-AR

(Project 1345-0029)

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T02:58Z
Check the source to verify that this is the current version before use.