INCH-POUND

MIL-S-50666A (AR)
AMENDMENT 1
24 September 1993

MILITARY SPECIFICATION

SERVO DRIVE, TRAVERSE: 10548052

This amendment forms a part of MIL-S-50666A (AR) , dated 30 April 1990, and is approved for use by the US Army Armament, Munitions, and Chemical Command, and is available for use by all Departments and Agencies of the Department of Defense.

PAGE 2

2.1.1: Delete the following Military Specifications:

'MIL-S-45743 - Soldering, Manual Type, High Reliability Electrical and Electronic Equipment
MIL-S-46844 - Soldering, Bath Soldering of Printed Wiring Assemblies"

2.1.2: Add the following Drawings:

'12563321 - Antenna Assembly, AS-2049A/VPS-2A
12950877 - Requirements for Soldering Electrical and Electronic Assemblies"

PAGE *3*

3.2: Delete the following *line:*

"e. Soldering electrical connections."

3.3.1: Delete in its entirety and substitute the following:

'3.3.1 Vibration. The traverse servo drive shall not suffer damage and shall meet the requirements of 3.4 and 3.5 after exposure to the equivalent of 6000 miles of track-laying vehicle operational vibration as defined by MIL-STD-810 narrowband random-on-random data for equipment installed on the deck of the M113 armored personnel carrier."

Distribution STATEMENT A. Approved for public release; distribution is unlimited .

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:33Z
Check the source to verify that this is the current version before use.

PAGE 4

3.3.3: Delete paragraphs 3.3.3, 3.3.3.1 and 3.3.3.2 in their entirety and substitute the following:

"**3.3.3** Altitude operating. The traverse servo drive shall meet the requirements **of** 3.4 and 3.5 during and after exposure to barometric pressure encountered at 10,000 feet above sea level (20.6 inches of Hg)."

PAGE 5

3.5.1: Delete in its entirety.

3.7: Delete **in its entirety and substitute the following:**

"3.7 Soldering. All soldering shall be in accordance with the requirements of Note 2 of Drawing 12950877."

PAGE 16

4.7.1.1, line 2: Delete "Method 514.3" and substitute "Method 514".

4.7.1.2, line 2: Delete "Method 516.3" and substitute "Method 516".

4.7.1.3, lines 2-3: Delete "Procedures 11 and **III, Method 500.2" and substitute "Procedure II, Method 500".**

PAGE 17

4.7.1.4.1, line 2: Delete "Method 501.2" and substitute "Method 501".

4.7.1.4.2, line 2: Delete "Method 502.2" and substitute "Method **502**".

4.7.1.5, line 2: Delete "Method 507.2" and substitute "Method 507".

4.7.3.2: Delete in its entirety.

PAGE 18

4.7.3.3: Delete in its entirety.

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:33Z
Check the source to verify that this is the current version before use.

PAGE 21

Add new paragraph 4.8 as **follows:**

"**4.8** Soldering. Soldering processes shall be inspected by certified inspectors to the requirements and acceptance criteria of Note 2 of Drawing 12950877 as specified in paragraph **3.7**."

Custodian:
Army-AR

Preparing activity:
Army-AR

(Project 1285-A891)

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:33Z
Check the source to verify that this is the current version before use.