INCH-POUND

MIL-C-48397A (AR)
AMENDMENT 3
23 August 1994

SUPERSEDING
AMENDMENT 2
06 May 1993

MILITARY SPECIFICATION

CARTRIDGE, IGNITION, M752A1
LOADING, ASSEMBLING AND PACKING

This Amendment forms a part of MIL-C-48397A (AR), dated 22 October 1986, and is approved for use by the U.S. Army Armament, Munitions and Chemical Command, and is available for use by all Departments and Agencies of the Department of Defense.

PAGE 1

1.1, Delete: "M853", and substitute: "M853A1".

PAGE 4

3.6.2, Delete: "220", and substitute: "200".

Delete: "200", and substitute: "180".

3.7, Delete: "210", and substitute: "190".

PAGE 9

4.4.2.2, Major 102: Delete in its entirety.

Major 103: Delete: "Gage", and substitute: "Visual".

AMSC N/A
DISTRIBUTION STATEMENT A.

FSC 1315
Approved for public release; distribution is unlimited.

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:24Z
Check the source to verify that this is the current version before use.

PAGE 10

4.4.2.3, Major 101, 102, 105 and 106: Delete in their entirety and substitute:

"101 Primer missing or inverted ...100% ...3.2 ...Visual

102 Primer above flush or more than .015 in. below flush ...0.4% ...3.2 ...Gage

105 Primer loose after staking (prior to applying lacquer) ...100% ...3.2 ...Manual/4.5.1

106 Primer bulged after staking ...100% ...3.2 ...Visual".

* Major 104, Delete: "lacquer",

and substitute: "any adhesive or sealant".

Add Major 107 as follows:

"107 One or more stakes missing or not full ...1/ ...3.2 ...Visual"

Add Note as follows:

"1/ Inspect the tool or one body at the start of each day's production and each hour thereafter. A missing or broken tooth shall be cause for rejection of all parts staked since the last successful inspection."

PAGE 11

4.4.2.4, Delete: drawing number "9549177",

and substitute: "7549177".

PAGE 12

4.4.2.5, Add Critical 5 as follows:

"5 Firing plug above flush with head surface ...100% ...3.2 ...Gage".

Majors 101, 102, 103 and 104, Delete in their entirety.

Major 106, Delete: "gage", and substitute: "Visual".

Source: https://assist.dla.mil -- Downloaded: 20260-22T19:24Z
Check the source to verify that this is the current version before use.

PAGE 13

4.4.2.6, Add Major 103 as follows:

"103 Environmental conditions inadequate .../a ...3.2 ...Gage".

Add Note as follows:

"(a): Temperature and humidity shall be checked at the beginning and end of each shift. If conditions are not proper at either time, the quantity of product represented by the conditioning shall be rejected."

PAGE 14

4.4.2.7, Major 101, Delete examination callout in its entirety, and substitute:

"Channel not completely filled with RTV sealant".

Major 104, Delete in its entirety.

Major 105, Delete in its entirety and substitute:

"105 True position of outside diameter with major diameter of head thread ...0.40% ...3.2 ...Gage".

Add Majors 110, 111 as follows:

"110 Environmental conditions inadequate ...b/ ...3.2 ...Gage

111 Presence of excessive sealant ...0.40% ...3.2 ...Visual".

Add Note (b) as follows:

"(b) Temperature and humidity shall be checked at the beginning and end of each shift. If conditions are not proper at either time, the quantity of product represented by the conditioning shall be rejected."

PAGE 20

4.4.3.1, Delete in its entirety.

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:24Z
Check the source to verify that this is the current version before use.

PAGE 21

4.4.3.4.1, Delete: "0.025", and substitute: 0.25".

4.4.3.4.1.1, Delete: "0.040", and substitute: "0.40".

PAGE 22

4.5.1, Delete in its entirety and substitute:

"4.5.1 Primer security test. Prior to applying lacquer the primed body shall be shaken. Rattling or other evidence of the loose primer shall cause rejection of that assembly."

PAGE 24

4.5.6, Delete: "8.9 ± 0.02 lbs for M853",

and substitute: "10.35 ± 0.02 lbs for M819".

4.5.7, Delete: "8.9 +", and substitute: "10.35 ±".

Delete: "M853", and substitute: "M819".

Delete: "Develoment", and substitute: "Development".

PAGE 25

6.1, Delete: "M853", and substitute: "M853A1"

The margins of this amendment are marked with an asterisk or vertical lines to indicate where changes (additions, deletions, modifications, corrections) from the previous amendment were made. This was done as a convenience only and the Government assumes no liability whatsoever for any inaccuracies in these notations. Bidders and contractors are cautioned to evaluate the requirements of this document based on the entire content irrespective of the marginal notations and relationship to the last previous amendment.

Custodian:
Army-AR

Preparing activity:
Army-AR

(Project 1315-0014)

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:24Z
Check the source to verify that this is the current version before use.