NOTICE OF GROUP CANCELLATION

INCH-POUND

MIL-DTL-5015H
NOTICE 1
23 December 2009

DETAIL SPECIFICATION

CONNECTORS, ELECTRICAL, CIRCULAR THREADED,
AN TYPE, GENERAL SPECIFICATION FOR

MIL-DTL-5015 and the following specification sheets associated with MIL-DTL-5015 are hereby canceled.

| Document | Date | Cancellation Notice No. | Replacement | DOD Project No. |
|---|---|---|---|---|
| MIL-DTL-5015H | 18-May-2000 | 1 | SAE-AS50151 | 5935-2009-007 |
| Connectors, Solder Contact | | | | |
| MS3100F | 20-Aug-1992 | 3 | SAE-AS31001 | 5935-2009-010 |
| MS3101D | 20-Aug-1992 | 2 | SAE-AS31011 | 5935-2009-011 |
| MS3102E | 20-Aug-1992 | 3 | SAE-AS31021 | 5935-2009-012 |
| MS3103D | 31-Aug-1990 | 3 | SAE-AS31031 | 5935-2009-014 |
| MS3106D | 20-Aug-1992 | 2 | SAE-AS31061 | 5935-2009-016 |
| MS3107C | 20-Aug-1992 | 3 | SAE-AS31071 | 5935-2009-017 |
| MS3108D | 20-Aug-1992 | 2 | SAE-AS31081 | 5935-2009-018 |
| MS3142D | 23-Jan-1978 | 3 | SAE-AS31421 | 5935-2009-145 |
| MS3436A | 07-Oct-1974 | 2 | SAE-AS34361 | 5935-2009-029 |
| MS3441 | 07-Oct-1974 | 2 | SAE-AS34411 | 5935-2009-031 |
| MS3507A | 07-Oct-1974 | 1 | SAE-AS35071 | 5935-2009-038 |
| MS25183C | 28-Sep-1971 | 3 | SAE-AS25183 | 5935-2009-041 |
| Connectors, Crimp Contact, Front Release | | | | |
| MS3400G | 23-Mar-1976 | 3 | SAE-AS34001 | 5935-2009-020 |
| MS3401G | 09-Apr-1979 | 3 | SAE-AS34011 | 5935-2009-021 |
| MS3402G | 15-Feb-1993 | 3 | SAE-AS34021 | 5935-2009-022 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-23T12:57Z
Check the source to verify that this is the current version before use.

| Document | Date | Cancellation Notice No. | Replacement | DOD Project No. |
|---|---|---|---|---|
| MS3404G | 23-Mar-1976 | 3 | SAE-AS34041 | 5935-2009-023 |
| MS3406H | 09-Apr-1979 | 3 | SAE-AS34061 | 5935-2009-024 |
| MS3408D | 09-Apr-1979 | 1 | SAE-AS34081 | 5935-2009-025 |
| MS3409B | 09-Apr-1979 | 2 | SAE-AS34091 | 5935-2009-026 |
| MS3412D | 23-Mar-1976 | 2 | SAE-AS34121 | 5935-2009-027 |
| MS3450E | 23-Mar-1976 | 1 | SAE-AS34501 | 5935-2009-030 |
| MS3451C | 23-Mar-1976 | 2 | SAE-AS34511 | 5935-2009-032 |
| MS3452D | 15-Feb-1993 | 1 | SAE-AS34521 | 5935-2009-033 |
| MS3454C | 23-Mar-1976 | 2 | SAE-AS34541 | 5935-2009-034 |
| MS3456D | 23-Mar-1976 | 1 | SAE-AS34561 | 5935-2009-035 |
| Connector Accessories | | | | |
| MS3105A | 18-Jun-1969 | 2 | SAE-AS31051 | 5935-2009-015 |
| MS25042K | 28-Dec-1987 | 2 | SAE-AS25042 | 5935-2009-039 |
| MS25043K | 28-Dec-1987 | 2 | SAE-AS25043 | 5935-2009-040 |
| MS3155C | 11-Dec-1978 | 3 | SAE-AS31551 | 5935-2009-019 |
| MS3420C | 19-Apr-1978 | 4 | SAE-AS85049/139 | 5935-2009-028 |

Caution: The supersession information is valid as of the date of this notice and may be superseded by subsequent revisions of the superseding documents.

(Copies of the superseding documents are available from SAE International, 400 Commonwealth Drive, Warrendale, PA 15096-0001 or www.sae.org.)

Custodians:
Army - CR
Navy - AS
Air Force - 85
DLA - CC

Preparing activity:
Navy - AS

(Project 5935-2009-007)

Review activities:
Army- AR, MI
Navy - EC
Air Force - 99
Other - NA

NOTE: The activities listed above were interested in this document as of the date of this document. Since organizations and responsibilities can change, you should verify the currency of the information above using the ASSIST Online database at https://assist.daps.dla.mil.



Source: https://assist.dla.mil -- Downloaded: 2026-10-23T12:57Z
Check the source to verify that this is the current version before use.