MILITARY SPECIFICATION

FUZE, PD, XM935
LOADING, ASSEMBLING AND PACKING

This specification is approved for use by all Departments and Agencies of the Department of Defense.

1. SCOPE

1.1 This specification covers the loading, assembling and packing of the XM935 Point Detonating Fuze.

2. APPLICABLE DOCUMENTS

2.1 The following documents of the issue in effect on date of invitation for bids or request for proposal form a part of this specification to the extent specified herein.

SPECIFICATIONS

MILITARY

MIL-P-45486B - Pellets, RDX (For Use in Ammunition)
MIL-A-48078 - Ammunition, Standard Quality Assurance Provisions, General Specification for
MIL-P-60412 - Packaging, Packing and Marking for Shipment of Artillery Type and Rocket Fuzes, General Specification for

STANDARDS

MILITARY

MIL-STD-331A - Fuze and Fuze Components, Environmental and Performance Tests for

Beneficial comments (recommendations, additions, deletions) and any pertinent data which may be of use in improving this document should be addressed to: Commander, US Army Armament Research and Development Command, Attn. DRDAR-QA, Dover, New Jersey 07801 by using the self-addressed Standardization Document Improvement Proposal (DD Form 1426) appearing at the end of this document or by letter.

FSC: 1390

Source: https://assist.dla.mil -- Downloaded: 202640-22T19:16Z
Check the source to verify that this is the current version before use.

DRAWINGS (see 6.5)

US ARMY ARMAMENT RESEARCH AND DEVELOPMENT COMMAND

PRODUCT AND PACKAGING DRAWINGS

9255258 - Fuze, PD, XM935

INSPECTION EQUIPMENT DRAWINGS

8816014 - Ball
8816368 - Lead Disc
9200012 - Firing Pin
9243921 - M98 Stab Detonator

3. REQUIREMENTS

3.1 Material.-Materials and parts shall be in accordance with applicable drawings and specifications.

3.2 Fuze Assembly.-The PD, M935 fuze assemblies shall comply with all requirements specified on drawing (dwg.) 9255258 and with all requirements specified in applicable specifications.

3.3 Jolt and Jumble.-The fuze assembly shall comply with the requirements of MIL-STD-331A, Tests 101.2 and 102.1.

3.4 Transportation Vibration.-The fuze assembly shall comply with the requirements of MIL-STD-331A, Test 104, and of paras. 3.5.1 and 3.5.2.

3.5 Proving Ground

3.5.1 Premature Bursts.-There shall be no premature bursts or metal parts failure in the mortar or in flight.

3.5.2 Functioning.-The fuze shall function on impact with the ground (as evidenced by cartridge functioning).

3.5.3 Arming Safety.-The fuze shall not function on impact against a 1/2" plywood screen positioned at a distance of 100 meters ± 1 meter.

3.6 Lead Assembly Output Test.-The lead assembly shall pierce a hole .220" minimum in diameter in a lead disc (dwg. 8816368).

3.7 Complete Fuze Leak Test.-The fuze shall have an air leakage rate no greater than 0.5 psi per 15 seconds.

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:16Z
Check the source to verify that this is the current version before use.

3.8 First Article Inspection.-This specification contains technical provisions for first article inspection. Requirements for the submission of first article samples by the contractor shall be as specified in the contract.

3.9 Workmanship.-All parts and assemblies shall be fabricated in a thorough, workmanlike manner. They shall be free of burrs, sharp edges, cracks, dirt, rust and other foreign matter. The cleaning methods shall not be injurious to any part, nor shall the parts be contaminated by the cleaning agent. Exterior surface coatings shall be uniform and continuous except for a few light scratches not exposing base material.

4. QUALITY ASSURANCE PROVISIONS

4.1 Responsibility for Inspection and Standard Quality Assurance Provisions.-Unless otherwise specified herein or in the contract, the provisions of MIL-A-48078 shall apply and are hereby made a part of this detail specification.

4.2 Classification of Inspections.-The following types of inspection shall be conducted on this item:

a. First Article Inspection

b. Quality Conformance Inspection

4.3 First Article Inspection

4.3.1 Submission.-The contractor shall submit a first article sample as designated by the Contracting Officer for evaluation in accordance with provisions of 4.3.2. The first article sample shall consist of the following items in sample quantities as indicated.

Part Description	Drawings	Quantity
Cup, Lead	9234684	10
Lead Assembly	9234683	60
Pellet, Booster	9255257	10
PAD	9255259	10
Disc, Cover	9255260	10
Fuze, PD, XM935	9255258	188

4.3.2 Inspections to be performed.-See MIL-A-48078 and Table I specified herein.

4.3.3 Rejection.-See MIL-A-48078(PA).

Source: https://assist.dla.mil -- Downloaded: 202610-22T19:16Z
Check the source to verify that this is the current version before use.

TABLE I - FIRST ARTICLE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS MIL-F-48172 (AR)

PARAGRAPH	TITLE		SHEET 1 OF 2		DRAWING NUMBER
	XM935 PD Fuze and Components				See Below
					NEXT HIGHER ASSEMBLY
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
	Cup, Lead (Dwg. 9234684)				
	Examination for Defects	10	100%	3.2	4.4.2.1
	Lead Assembly (Dwg. 9234683)				
	Examination for Defects	10	100%	3.2	4.4.2.2
	Lead Assembly Output Test	50	100%	3.6	
	Pellet, Booster (Dwg. 9255257)				
	Examination for Defects	10	100%	3.2	4.4.2.3
	PAD (Dwg. 9255259)	10	100%	3.2	4.4.2.4
	Disc, Cover (Dwg. 9255260)	10	100%	3.2	4.4.2.5
	Fuze, PD, M567 (Dwg. 9246242)				
	Examination for Defects	15	100%	3.2	4.4.2.7
	Examination for Defects - After disassembling front and rear bodies	15	100%	3.2	4.4.2.6
	Complete Fuze Leak Test	15	100%	3.7	4.5.5
	Jolt and Jumble	12	100%	3.3	4.5.1
	Transportation Vibration	10	100%	3.4	4.5.2

NOTES:

SARPA-QA FORM 2567 FEB 74 4810

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:16Z
Check the source to verify that this is the current version before use.

TABLE I - FIRST ARTICLE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-F-48172 (AR)

PARAGRAPH	TITLE		SHEET 2 OF 2		DRAWING NUMBER
	CONTINUATION SHEET				See Below
					NEXT HIGHER ASSEMBLY
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
	Fuze, PD, M567 (Dwg. 9246242)				
	Proving Ground Premature Bursts (May be observed during proving ground functioning phase)	124	100%	3.5.1	4.5.5
	Proving Ground Functioning	124	(a)	3.5.2	4.5.5
	Proving Ground Arming Safety	12	100%	3.5.3	4.5.6

NOTES: (a) More than 2 duds shall be cause for rejection.

SARPA-QA FORM 2567 FEB 74 4810

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:16Z
Check the source to verify that this is the current version before use.

4.4 Quality Conformance Inspection.

4.4.1 Inspection Lot Formation.-Inspection lots shall comply with the lot formation provisions of MIL-A-48078. In addition, inspection lots of fuzes shall contain:

a. Fuze components less booster pellets or one lot interfix number from one manufacturer.

b. Booster pellets of one lot interfix number.

4.4.2 Examination.-See MIL-A-48078.

a. Sampling Plans.-Unless otherwise specified in the Classification of Defects and Test Tables, sampling plans for major and minor defects shall be in accordance with MIL-STD-105, Inspection Level II.

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:16Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-F-48172 (AR)

PARAGRAPH	TITLE	SHEET 1 OF 1	DRAWING NUMBER
4.4.2.1	Cup, Lead		9234684
			NEXT HIGHER ASSEMBLY 9234683

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Thickness of base		0.40	3.2	Gage
102	Inside diameter		0.40	3.2	Gage
103	Outside diameter		0.40	3.2	Gage
104	Outside flange diameter		0.65	3.2	Gage
105	Thickness of flange		0.65	3.2	Gage
106	Length from bottom to base of flange		0.40	3.2	Gage
107	Corner radii (two places)		0.65	3.2	Gage
Minor					
201	Protective finish damaged		1.00	3.2	Visual
202	Surface finish improper		1.00	3.2	Visual
203	Evidence of poor workmanship		1.00	3.2	Visual

NOTES:

SARPA-QA FORM 2567 FEB 74 4810

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:16Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-F-48172 (AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.2	Lead Assembly				9234683
					NEXT HIGHER ASSEMBLY 9255261
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Overall length		0.40	3.2	Gage
102	Outside diameter		0.40	3.2	Gage
103	Charge depth improper		0.40	3.2	Gage
104	Identification mark missing or improper		0.40	3.2	Visual
105	Lead Assembly Output Test	200	0.40	3.6	4.5.3
Minor					
201	Evidence of poor workmanship		1.00	3.8	Visual

NOTES.

SARPA-QA FORM 2567 FEB 74 4810

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:16Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-F-48172 (AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 9255257
4.4.2.3	Pellet, Booster				NEXT HIGHER ASSEMBLY 9255258
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Diameter		0.40	3.2	Gage
102	Height		0.40	3.2	Gage
103	Cracked, chipped or broken		0.40	3.2	Visual
104	Weight		0.40	3.2	Gage (See Note a)
105	Density		0.40	3.2	(See Note b)
Minor					
201	Evidence of poor workmanship		1.00	3.8	Visual

NOTES: a. Pellet which fails this requirement may be accepted if density is proper.
b. Check density per MIL-P-45486B if weight requirement is not met.

SARPA-QA FORM 2567 FEB 74 4810

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:16Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-F-48172 (AR)

PARAGRAPH	TITLE	SHEET 1 OF 1	DRAWING NUMBER
4.4.2.4	Pad		9255259
			NEXT HIGHER ASSEMBLY
			9255258

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Diameter		0.40	3.2	Gage
102	Thickness		0.40	3.2	Gage
Minor					
201	Evidence of poor workmanship		1.00	3.8	Visual

NOTES:

10

SARPA-QA FORM 2567 FEB 74 4810

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:16Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-F-48172 (AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.5	Disk, Cover				9255260
					NEXT HIGHER ASSEMBLY
					9255258
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Outside diameter		0.40	3.2	Gage
102	Inside diameter		0.40	3.2	Gage
103	Thickness		0.40	3.2	Gage
Minor					
201	Evidence of poor workmanship		1.00	3.8	Visual

NOTES:

SARPA-QA FORM 2567 FEB 74 4810

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:16Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS MIL-F-48172 (AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.6	Body Assembly, Front				9255261
					NEXT HIGHER ASSEMBLY 9255258
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	Pull pin assembly missing or not fully seated		100%	3.2	Visual
Major					
101	Lead missing		0.40	3.2	Visual
102	Tape over lead missing		0.40	3.2	Visual
103	Excessive depression in windshield		0.40	3.2	Visual
Minor					
201	Evidence of shipping damage		1.00	3.2	Visual

NOTES:

SARPA-QA FORM 2567 FEB 74 4810

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:16Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-F-48172 (AR)

PARAGRAPH	TITLE			SHEET 1 OF 1	DRAWING NUMBER 9255258
4.4.2.7	Fuze, PD, M935 (During and after assembly)				NEXT HIGHER ASSEMBLY
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Booster pellet missing, damaged or cracked		0.40	3.2	Visual
102	Sealant missing from threads of booster cup		0.40	3.2	Visual
103	Disc missing or improperly assembled		0.40	3.2	Visual
104	Fuze improperly marked		0.40	3.2	Visual
105	Label missing damaged or illegible		0.40	3.2	Visual
106	Insufficient torque on booster cup		0.40	3.2	Gage
107	Complete Fuze Leak Test	20	100%	3.7	4.5.4
Minor					
201	Evidence of poor workmanship		1.00	3.9	Visual

NOTES:

SARPA-QA FORM 2567 FEB 74 4810

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:16Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.8	Fuze, PD, M935, Destructive Lot Acceptance Testing				9255258
					NEXT HIGHER ASSEMBLY
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical					
1.	Jolt and Jumble Test, MIL-STD-331A Test No. 101.2 and Test No. 102.1	12	100%	3.3	4.5.1
2.	Transportation Vibration Test MIL-STD-331A, Test No. 104 and Premature burst during firing.	10	100%	3.4	4.5.2
3.	Premature Burst in Ballistic Test	124	100%	3.5.1	4.5.5
4.	Function in Arming Safety Test	12	100%	3.5.3	4.5.6
Major					
101	Ballistic Test Non-Function	124	(a)	3.5.2	4.5.5
102	Transportation Vibration Firing Phase Non-Function	10	(b)	3.5.2	4.5.2

NOTES:

a. In the ballistic test alone if no more than two duds are observed, the lot shall be accepted.

b. The results of the TV firing and ballistic test shall be combined. If no more than three duds are observed, the lot shall be accepted. There is no separate requirement for the TV firing phase.

SARPA-QA FORM 2567 FEB 74 4810

Source: https://assist.dla.mil -- Downloaded: 2026-02-22T19:16Z
Check the source to verify that this is the current version before use.

4.4.3 Inspection Equipment.-The inspection equipment required to perform the examination and tests prescribed herein is described in the Paragraph Reference/Inspection Method column in the tables starting with paragraph 4.4.2.1. The contractor shall submit for approval inspection equipment designs in accordance with the terms of the contract. See Section 6 of MIL-A-48078 and para. 6.3 of this specification.

4.5 Test Methods and Procedures.

4.5.1 Jolt and Jumble.-The test shall be conducted upon complete fuze assemblies (dwg. 9244258). The test shall be conducted in accordance with procedures outlined in MIL-STD-331A, Test 101.2 and after completion of that test, the fuze shall not be disassembled but shall be subjected to Test 102.1, utilizing the appropriate fixture. Assemblies subjected to this test shall not be returned to the lot. After completion of the test, the fuzes shall be disassembled and inspected for compliance with requirements of para. 3.3 and MIL-STD-331A. As a minimum, observation shall be made for compliance with the following requirements (these defects are classified as "critical"):

a. The assembly shall not be broken or come apart in any way.
b. The slider shall not be in the armed position.
c. The setback pins shall not have moved so as to release the balls retaining the firing pin assembly or the striker.
d. The arming pin shall not have moved to the armed position.
e. The pull wire assembly shall not have come loose in such a way as to not block the slider.
f. No explosive components shall have detonated.
g. The firing pin or striker shall not move past the balls to the armed position.
h. There shall be no explosive dust present.

If any fuze fails to meet the requirements of MIL-STD-331 or the requirements of this specification, the lot shall be rejected.

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:16Z
Check the source to verify that this is the current version before use.

4.5.2 Transportation Vibration.-The test shall be performed on complete fuze assemblies (dwg. 9255258) in the unarmed position set SQ. The test shall be conducted in accordance with the procedures outlined in MIL-STD-331, Test 104 using equipment as specified in 4.2.3 of this specification. Upon completion of the test, the fuzes shall not be disassembled but shall be x-rayed to determine of the fuze has armed, become unsafe in any way, or has been damaged so as to not function. If so, that condition shall be classed as a test failure, and the ballistic sample shall not be fired. If the x-rays indicate the fuzes safe and operable, then they shall be assembled to 60MM, HE, M720 rounds and fired at Charge 0; on half SQ, the other Delay as detailed in para. 4.3.6. If any sample fails to function high order that sample shall be classed defective.

4.5.3 Lead Assembly Output Test.-The test shall be performed on the lead assembly (dwg. 9234683). A fixture shall be used to hold the lead assembly in central contact with the lead disc (dwg. 8816368). A ball (dwg. 8816014) shall be dropped a distance of five (5) inches onto a firing pin (dwg. 9200012) - distance is measured from the bottom of the ball to the top of the firing pin. The firing pin shall strike and initiate an M98 detonator (dwg. 9243921) which in turn will function the lead assembly. Observation shall be made for compliance with requirements as defined in para. 3.6. Other suggested, but not mandatory, equipment which could be utilized in conjunction with this set-up are: holder (dwg. 8816367), bushing (dwg. 8827829) and base (dwg. 8802085). Government approval, of the test fixture to be used, is required.

4.5.4 Complete Fuze Leak Test.-This test shall be performed on complete fuzes (dwg. 9255258). A fixture shall be used which covers the entire outer surface of the fuze with as little clearance as possible. The test shall be conducted at ambient temperature using 3 $\pm$ 0.5 psi. Any sample which exhibits a pressure drop of more than 0.5 psi in 15 seconds minimum after stabilization shall be classed defective. A fixed volume of air shall be used so as to detect gross leaks. Equipment shall be as specified in 4.4.3.

4.5.5 Functioning (Proving Ground).-The sample fuzes shall be assembled to 60MM, HE, M720 cartridges and fired from a mortar standard for that round at an elevation between 45° and 75°. The samples shall be divided into four (4) equal groups. The groups shall be fired at Charge 0-set SQ, Charge 0-set Delay, Charge 4-set SQ and Charge 4-set Delay. Any fuze which fails to function the cartridge high order shall be classed defective. The Proving Ground shall utilize a geophonic sensing device to differentiate superquick and delay functioning at charge four.

Source: https://assist.dla.mil -- Downloaded: 2026l0-22T19:16Z
Check the source to verify that this is the currentversion before use.

4.5.6 Arming Safety (Proving Ground).-The fuzes shall be assembled to the inert filled M720 round set SQ and fired at Charge 0 from a 60MM mortar. They shall be fired against a 1/2 inch plywood screen set at a distance of 100 meters ± 1 meter. A minimum muzzle velocity of 180 fps is required for every round. If any fuze functions when the muzzle velocity is equal to or greater than the requirement, the lot shall be rejected. If any fuze functions and the muzzle velocity is less than the requirement, the lot shall be referred. If a fuze does not function, but the muzzle velocity for that round is below the requirement, that sample shall be classed a "no-test" and a new sample shall be selected and tested.

5. PREPARATION FOR DELIVERY

5.1 Packaging, Packing and Marking.-Packaging, packing and marking shall be in accordance with the requirements and inspection procedures specified in MIL-P-60412.

6. NOTES

6.1 Intended Use.-The XM935 Fuze is intended for use on 60MM mortar ammunition.

6.2 Ordering Data.-See MIL-A-48078 (PA).

6.3 Submission of Designs for Approval.-See 6.2.3 of MIL-A-48078 (PA). Submit equipment designs, as required, to Commander, ARRADCOM, ATTN: DRDAR-QAR-I, Dover, N.J., 07801.

6.4 Proving Ground Summary.

6.4.1 Quality Conformance Test

FUNCTIONING

Weapon	Cartridge	Zone	Fuze Setting	Quantity
60MM Mortar	60MM,HE,M720	0	SQ	31
		0	Delay	31
		4	SQ	31
		4	Delay	31

Source: https://assist.dla.mil -- Downloaded: 202610-22T19:16Z
Check the source to verify that this is the current version before use.

ARMING DELAY

Weapon	Cartridge	Zone	Fuze Setting	Quantity
60MM Mortar	M720 Inert	0	SQ	12

TRANSPORTATION VIBRATION

Weapon	Cartridge	Zone	Fuze Setting	Quantity
60MM Mortar	M720, HE	0	SQ	5
		0	Delay	5

ACCEPTANCE CRITERIA

Defect	Accept	Reject
Premature Burst	0	1
Fuze Function on Screen	0	1
Duds		
a. TV + Functioning	3	4
b. Functioning Only	2	3
c. TV Only (No requirement - See a.)		

6.4.2 First Article Inspection Test

FUNCTIONING

Weapon	Cartridge	Zone	Fuze Setting	Quantity
60MM Mortar	60MM,HE,M720	0	SQ	31
		0	Delay	31
		4	SQ	31
		4	Delay	31

ARMING DELAY

Weapon	Cartridge	Zone	Fuze Setting	Quantity
60MM Mortar	60MM,Inert,M720	0	SQ	12

Source: https://assist.dla.mil -- Downloaded: 20261O-22T19:16Z
Check the source to verify that this is the current version before use.

6.5 Drawings.-Drawings listed in Section 2 of this specification under the heading US Army Armament Research and Development Command (ARRADCOM) may also include drawings prepared by, and identified as, Edgewood Arsenal, Frankford Arsenal, Rock Island Arsenal or Picatinny Arsenal drawings. Technical data originally prepared by these activities is now under the cognizance of ARRADCOM.

Custodian:
Army - AR

Preparing activity:
Army - AR

Project Number: 1390-A013

Source: https://assist.dla.mil -- Downloaded: 202640-22T19:16Z
Check the source to verify that this is the currenversion before use.

STANDARDIZATION DOCUMENT IMPROVEMENT PROPOSAL

INSTRUCTIONS: This form is provided to solicit beneficial comments which may improve this document and enhance its use. DoD contractors, government activities, manufacturers, vendors, or other prospective users of the document are invited to submit comments to the government. Fold on lines on reverse side, staple in corner, and send to preparing activity. Attach any pertinent data which may be of use in improving this document. If there are additional papers, attach to form and place both in an envelope addressed to preparing activity. A response will be provided to the submitter, when name and address is provided, within 30 days indicating that the 1426 was received and when any appropriate action on it will be completed.

NOTE: This form shall not be used to submit requests for waivers, deviations or clarification of specification requirements on current contracts. Comments submitted on this form do not constitute or imply authorization to waive any portion of the referenced document(s) or to amend contractual requirements.

DOCUMENT IDENTIFIER *(Number)* AND TITLE

MIL-F-48172 Fuze, PD, XM935 LAP

NAME OF ORGANIZATION AND ADDRESS OF SUBMITTER

☐ VENDOR ☐ USER ☐ MANUFACTURER

1. ☐ HAS ANY PART OF THE DOCUMENT CREATED PROBLEMS OR REQUIRED INTERPRETATION IN PROCUREMENT USE? ☐ IS ANY PART OF IT TOO RIGID, RESTRICTIVE, LOOSE OR AMBIGUOUS? PLEASE EXPLAIN BELOW.

A. GIVE PARAGRAPH NUMBER AND WORDING

B. RECOMMENDED WORDING CHANGE

C. REASON FOR RECOMMENDED CHANGE(S)

2. REMARKS

SUBMITTED BY *(Printed or typed name and address — Optional)*	TELEPHONE NO.
	DATE

DD FORM 1426 1 OCT 76

EDITION OF 1 JAN 72 WILL BE USED UNTIL EXHAUSTED.

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:16Z
Check the source to verify that this is the current version before use.

FOLD

POSTAGE AND FEES PAID

U.S. MAIL

OFFICIAL BUSINESS
PENALTY FOR PRIVATE USE $300

COMMANDER
US ARMY ARMAMENT RESEARCH & DEVELOPMENT COMMAND
ATTN: DRDAR-QAR
DOVER, NJ 07801

FOLD

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:16Z
Check the source to verify that this is the current version before use.