MILITARY SPECIFICATION

RADIAC REPAIR FACILITY (MOBILE), AN/MDM-1( )

This amendment forms a part of Military Specification MIL-R-23260(SHIPS), 29 November 1962.

Page 1, paragraph 1.1, line 6: Delete "It is" and substitute "When outfitting is completed, it is".

Page 1, paragraph 2.1: Delete reference to "STANDARDS".

Page 1, paragraph 2.1: Add the following drawings:

"DRAWINGS

BUREAU OF SHIPS
RHA6F6000A - Mobile Radiac Repair Facility AN/MDM-1.
RHA6F6001A - Mobile Radiac Repair Facility Calibration Trailer."

Page 1, paragraph 3.1.1, lines 3 through 6: Delete "and a front mounted "Vehicle mounting drum winch (Basic) mechanically driven, 20,000 pounds capacity" shall be provided." and substitute "and a vehicle mounting drum winch (Basic) mechanically driven, 12,000 pounds capacity mounted in back of front bumper shall be provided."

Page 1, paragraph 3.1.1.1, line 2: After "output", add "to run winch".

Page 3, paragraph 3.2.2, line 7: After "4", add "herein and in RHA6F6000A".

Page 3, paragraph 3.2.2.1, line 3: Delete "figure 3" and substitute "sheet 2 of RHA6F6000A."

Page 3, paragraph 3.2.2.2: Add "and Sheet 2 of RHA6F6000A".

Page 4, paragraph 3.2.2.2.13: Add "The blower and air filter system shall be an Engineering Laboratories Model 62-107 Single Direction Exhaust Fan with Filter or equal."

Page 4: Add as paragraph 3.2.3.4.1:

"3.2.3.4.1 The water tank and plumbing shall be heated. The 1/2-inch copper plumbing shall contain CHROMALOX Therm wire band type TAB, or equivalent. Also, the water tank shall contain a CHROMALOX screw plug immersion element type TM copper sheath (one inch standard pipe thread), or equivalent. Both of the above heaters shall be connected to a CHROMALOX thermostat No. TWR-90A, 120 volts, 1500 watts, or equivalent, installed in the interior of the van.

1/ CHANGES FROM PREVIOUS ISSUE. THE OUTSIDE MARGINS OF THIS DOCUMENT HAVE BEEN MARKED "#" TO INDICATE WHERE CHANGES (DELETIONS, ADDITIONS, ETC.) FROM THE PREVIOUS ISSUE HAVE BEEN MADE. THIS HAS BEEN DONE AS A CONVENIENCE ONLY AND THE GOVERNMENT ASSUMES NO LIABILITY WHATSOEVER FOR ANY INACCURACIES IN THESE NOTATIONS. BIDDERS AND CONTRACTORS ARE CAUTIONED TO EVALUATE THE REQUIREMENTS OF THIS DOCUMENT BASED ON THE ENTIRE CONTENT AS WRITTEN IRRESPECTIVE OF THE MARGINAL NOTATIONS AND RELATIONSHIP TO THE LAST PREVIOUS ISSUE.

Source: https://assist.dla.mil -- Downloaded: 202610-19T16:04Z
Check the source to verify that this is the current version before use.

Page 4, paragraph 3.2.3.6: Delete and substitute:

"3.2.3.6 The gasoline motor-generator storage compartment shall be constructed and installed in the left side of the van as shown on sheets 1 and 3 of RHA6F6000. - The following items on sheet 1 of Drawing RHA6F6000A are not required:

Item	Nomenclature
1	VOM Meter
2	Battery Tester TS-183B/U
4	Tube tester TV-3( )/U "

Page 5, paragraph 3.2.5, item (c), lines 2 and 3: Delete "20,000 pounds capacity in accordance with MS51353" and substitute "12,000 pounds capacity including 100 feet of 1/2-inch cable, GAR WOOL MODEL 125, or equivalent."

Page 5, paragraph 3.2.5: Add item (x):

"(X) Power steering."

Page 5, paragraph 3.3, last sentence: Delete and substitute "Detail requirements are contained in RHA6F6001A, except as follows:".

Page 5, paragraph 3.3.1: Delete.

Pages 5 and 6, paragraphs 3.3.3 through 3.3.12.6: Delete.

Page 7, paragraph 3.5: Add as second sentence: "Two small covers shall be provided to close the space between the van and the ground."

Page 7, paragraph 3.5.1: Delete and substitute:

"3.5.1 Dimensions. - The length of the covers shall be made the maximum length of the van body to maximize the work areas. Other dimensions shall be as shown on figure 8."

Page 7, paragraph 3.5.3: Delete and substitute:

"3.5.3 Doors. - Four 3 by 6 feet zippered doors with tie down straps to hold doors open shall be provided as shown on figure 8."

Page 7, paragraph 3.5.5: Delete and substitute:

"3.5.5 Fasteners. - Fasteners, designed to fasten easily and to securely hold the shelter covers in place shall be attached to the roofline of the van by easily sliding them into a water tight molding. The covers shall be attached to the sides and bottom of the van with quarter turn fasteners."

Page 7: Add as paragraph 3.5.6:

"3.5.6 Storage bags. - Two storage bags made of the same material as the covers shall be provided to protect the covers when they are not in use."

Page 7, paragraph 4.2.2.2, last line: Delete and substitute "it is functioning correctly".

Preparing activity:
Navy - SH
(Project 6665-N231Sh)

Source: https://assist.dla.mil -- Downloaded: 2026-10-19T16:04Z
Check the source to verify that this is the current version before use.