INCH-POUND

MIL-C-46228B
AMENDMENT 1
31 May 1995

MILITARY SPECIFICATION

CARTRIDGE, DELAY, M93 ASSEMBLY

This amendment forms a part of MIL-C-46228B, dated 23 April 1991, and is approved for use by all departments and agencies of the Department of Defense.

PAGE 1

Military Specifications: Delete "MIL-C-60539" and its title, and substitute the following:

" MIL-A-8625 Anodic Coating for Aluminum and Aluminum Alloys"

Beneficial comment box: Delete address and substitute "Commander, Indian Head Division, Naval Surface Warfare Center, Standardization Branch (Code 8420), 101 Strauss Avenue, Indian Head, MD 20640-5035".

PAGE 2

2.1.1 Add new section:

" OTHER GOVERNMENT DOCUMENTS

WS21535 Ignition Devices, (Percussion), PVU-1/A"

Drawings: Delete "NAVAL ORDNANCE STATION" and substitute "NAVAL SURFACE WARFARE CENTER".

Drawings: Add:

" 851AS110 Ignition Device PVU-1/A"

Application for copies: Delete address and substitute "Commander, Indian Head Division, Naval Surface Warfare Center, Data Control Branch (Code 8410), 101 Strauss Avenue, Indian Head, MD 20640-5035".

PAGE 3

Paragraph 3.4.1, first line: Delete "M42 Primer", and substitute "PVU-1/A Ignition Device".

DISTRIBUTION STATEMENT A: Approved for public release; distribution is unlimited.

Source: https://assist.dla.mil -- Downloaded: 202610-22T05:17Z
Check the source to verify that this is the current version before use.

Paragraph 3.4.1.1: Delete in its entirety and substitute the following:

" **3.4.1.1 Ignition device.** The ignition device shall be furnished from lots manufactured within the preceding 24 months or recertified within the preceding 12 months. The ignition device shall be manufactured per Drawing 851AS110 and accepted per WS 21535. Prior to assembly into a cartridge, the ignition device shall be radiographically examined for defects as specified in 4.7.1."

Paragraph 3.4.3 , second line: Delete "MIL-C-60539" and substitute "MIL-A-8625".

Paragraph 3.5.3, third line: Delete "primer" and substitute "ignition device"

PAGE 4

Paragraph 3.6.1, title and first line: Delete "primer" and substitute "ignition device".

PAGE 5

Paragraph 4.4, sixth and ninth lines: Delete "primer" and substitute "ignition device".

PAGE 6

Paragraph 4.4.2, title and second line: Delete "primer" and substitute "ignition device".

Table II, title: Delete "Primer" and substitute "Ignition device".

PAGE 8

Paragraph 4.6.2, Critical 3: Delete "Primer" and substitute "Ignition Device".

PAGE 10

Paragraph 4.7.1, title, first, second and fourth lines: Delete "primer" and substitute "ignition device".

Seventh line and list: Delete as follows: "the following:

Presence of Primer Charge
No Material Defects"

and substitute as follows: "the following: missing or abnormally thin charge; charge broken, cracked or porous; cracked or off-center anvil or other misplaced or deformed inert parts; anvil abnormally close to the ignition device cup dome; and all other observable defects in assembly."

Paragraph 4.7.3, Third line: Delete "MIL-C-60539" and substitute "MIL-A-8625".

Source: https://assist.dla.mil -- Downloaded: 202610-22T05:17Z
Check the source to verify that this is the current version before use.

PAGE 11

Paragraph 4.7.7, fifth line: Delete "primer" and substitute "ignition device".

Paragraph 4.7.8.1, title and sixth line: Delete "primer" and substitute "ignition device".

PAGE 12

Paragraph 6.2h: Delete "primers" and substitute "ignition devices".

PAGE 13

Paragraph 6.6.1: Delete "primer" and substitute "ignition device".

Custodian:
Navy - OS
Air Force - 99

Review Activity:
Air Force - 70

Preparing activity:
Navy - OS
(Project 1377-0E93)

Source: https://assist.dla.mil -- Downloaded: 202610-22T05:17Z
Check the source to verify that this is the current version before use.