MIL-B-3461G
AMENDMENT 2
23 April 1985
SUPERSEDING
INT AMENDMENT 1 (IH)
25 September 1984

MILITARY SPECIFICATION

BUTTON, INSIGNIA, METAL, UNIFORM AND CAP

This amendment forms a part of Military Specification MIL-B-3461G, dated 30 September 1979, and is approved for use by all Departments and Agencies of the Department of Defense.

Page 2

Paragraph 1.2 - Under "Type I Style 3, "Class A Subclass 1" - Delete "(Officers)" and delete "Subclass 2" in its entirety.

Under Type II Style 5, Class "A" add

Subclass 1 - Male
Subclass 2 - Female

Page 8

Paragraph 3.6.2 - Delete (see 6.2) and substitute (see 3.6.2.4 and 6.2)

Add paragraph 3.6.2.4 in the proper sequence.

3.6.2.4 Cap button for USCG Female Officers. - All subclass 2 button (22-1/2 ligne cap button) for USCG female officers shall have a staple type prong, attaching device. The prongs shall be 7/8 ± 1/8 each long and shall be formed from 0.040 ± 0.002 diameter gold colored wire. The prong shall be centered on and fused, soldered or swedged on the back of the button so when spread open the prongs shall be horizontal to the button design.

/PSC 8455/

Source: https://assist.dla.mil -- Downloaded: 2026-10-16T17:46Z
Check the source to verify that this is the current version before use.

Table III - Delete in its entirety and substitute.

"Ligne size	Air Force	Marine Corps	Navy		Coast Guard Auxiliary		Solid Design	Pierced Design	Corps of Engineers	JROTC
	Silver	Gold	Gold	Silver	Silver	Gold	Gold	Gold	Gold	Gold
20 2/	--	--	--	--	--	--	--	--	1.5	--
20 3/	--	--	--	--	--	--	--	--	0.5	--
20	6.0	--	--	--	--	--	1.0	--	--	--
20 1/	20.0	--	--	--	--	--	--	--	--	--
22	--	.545	--	--	--	--	--	--	--	--
22-1/2 4/	--	1.0	1.0	7.5	1.0	--	--	--	--	--
25 2/	--	--	--	--	--	--	--	1.5	1.5	--
25	12.0	--	--	--	--	--	1.0	--	--	0.5
25 3/	--	--	--	--	--	--	--	0.5	0.5	--
27	--	.545	--	--	--	--	--	--	--	--
28	--	--	1.25	--	6.0	1.25	--	--	--	--
30 2/	--	--	--	--	--	--	--	2.25	2.25	--
30	18.0	--	--	--	--	--	1.5	--	--	0.75
30 3/	--	--	--	--	--	--	--	0.75	0.75	--
35	--	--	2.0	18.5	9.0	2.0	--	--	--	--
36 2/	--	--	--	--	--	--	--	3.0	3.0	--
36	24.0	--	--	--	--	--	2.0	--	--	1.0
36 3/	--	--	--	--	--	--	--	1.0	1.0	--
40	--	1.51	2.5	22.5	--	2.5	--	--	--	--
45	36.0	--	--	--	--	--	--	--	--	--

1/ Cuff link button
2/ Pierced design shell
3/ Pierced design liner
4/ When the button is to be procured for use on the service cap frame or shoulder mark, the gold content specified shall not apply, however, the button front and rim shall be 24 karat gold electroplated."

Source: https://assist.dla.mil -- Downloaded: 2026-10-16T17:46Z
Check the source to verify that this is the current version before use.

Page 16

Table VI - Add the following to the table.

"Examine	Defects	Classification Major (*)	Minor
Staple type	Not material specified		x
Prong	Not properly swedged or soldered		x
	Not annealed		x"

Page 22

Paragraph 5.1.1.1.1.1 - Delete paragraph title in its entirety, substitute "Type I, style 3, Type II, styles 4 and 5 and Type III, buttons."

Also delete 6th line in its entirety and substitute "Putting the button shank or staple type prong through the precut holes in the bristol board."

Page 26

Table IX - Last line, delete "Screw post, cap" and substitute Cap (see 3.6.2.4).

Page 27

Paragraph 6.2 - Delete second line of "(i)" in its entirety and substitute "(see 3.6.2 and 3.6.2.4)."

CUSTODIANS:	REVIEW ACTIVITIES:	USER ACTIVITIES:	PREPARING ACTIVITY:
ARMY IH			THE INSTITUTE OF HERALDRY,
AIR FORCE 99	11,82	45	UNITED STATES ARMY
NAVY NU	MC	CG	
OTHER	CT		

Project No. 8455-0081

/FSC 8455/

Source: https://assist.dla.mil -- Downloaded: 202640-16T17:46Z
Check the source to verify that this is the currentversion before use.