INCH-POUND

MIL-F-15733/61B
AMENDMENT 6
15 April 1994
SUPERSEDING
AMENDMENT 5
5 May 1993

MILITARY SPECIFICATION SHEET

FILTERS, RADIO FREQUENCY INTERFERENCE,
STYLES FL30, FL32, FL34 AND FL43

This amendment forms a part of MIL-F-15733/61B, dated 26 November 1982, and is approved for use by all Departments and Agencies of the Department of Defense.

PAGE 3

FIGURE 1, notes, add the following:

"10. Potting shall not extend beyond .030 inches (0.76 mm) from the filter body.

11. An undercut or imperfect threads out to a maximum of .060 inches (1.52 mm) from the hexhead or mounting surface is permissible."

PAGE 7

After rated current, add:

"Insertion loss: At 25°C and at temperature extremes (see table III)."

Temperature rise, delete and substitute:

"Temperature rise. For dash numbers 0001 thru 0013, the temperature rise shall be 25°C maximum. For dash number 0014, temperature rise shall be 40°C maximum.

PAGE 8

TABLE III, dash number 0009, minimum insertion loss (dB), +25°C, 5 MHz column: Delete "25" and substitute "20".

TABLE III, dash number 0014, rated current (amperes) column: Delete "25" and substitute "20".

TABLE III, footnote 1/: Delete "20 MHz" and substitute "10 MHz" (two places).

PAGE 9

Thermal shock and immersion paragraphs, delete and substitute:

"Thermal shock and immersion: Not applicable."

PAGE 10

Moisture resistance paragraphs, delete and substitute:

"Moisture resistance: Not applicable."

DISTRIBUTION STATEMENT A. Approved for public release; distribution is unlimited.

Source: https://assist.dla.mil -- Downloaded: 2026-10-18T07:27Z
Check the source to verify that this is the current version before use.

PAGE 11

After "Part number" paragraph, add the following:

"Application note: These nonhermetically sealed filters may be susceptible to moisture intrusion when subjected to repeated thermal cycling. If these items are to be utilized in applications enduring harsh environments, the user should consider placing them within hermetic enclosures."

Supersession data, dash numbers 0013 and 0014, change to:

"Part number M15733/61-	Inactive part numbers
0013	M15733/28-0004
0014	M15733/28-0003 "

PAGE 12

* TABLE IV, delete and substitute:

TABLE IV. Group A inspection.

Test or inspection	Sampling procedure
Voltage conditioning	100%
Dielectric withstanding voltage	100%
Insulation resistance	100%
Voltage drop 1/	100%
Insertion loss (check test)	100%
Radiographic inspection 2/	100%
Visual and mechanical inspection	See MIL-F-15733, group A inspection

1/ DC voltage drop/dc resistance test for dc rated filters shall be performed on a sample basis in accordance with MIL-F-15733, group A inspection.
2/ Applicable to dash numbers 0010 through 0012 only. "

The margins of this amendment are marked with asterisks to indicate where changes (additions, modifications, corrections, deletions) from the previous amendment were made. This was done as a convenience only and the Government assumes no liability whatsoever for any inaccuracies in these notations. Bidders and contractors are cautioned to evaluate the requirements of this document based on the entire content irrespective of the marginal notations and relationship to the last previous amendment.

CONCLUDING MATERIAL

Custodians:
Army - ER
Navy - EC
Air Force - 85

Review activities:
Army - AR, AT, AV, ME, MI
Navy - AS, MC, OS, SH
Air Force - 19, 99

Preparing activity:
DLA - ES

(Project 5915-0377-03)

Source: https://assist.dla.mil -- Downloaded: 2026-10-18T07:27Z
Check the source to verify that this is the current version before use.