MIL-L-22624A(WEP)
AMENDMENT 2
4 April 1966

Superseding
Amendment - 1
13 January 1966

MILITARY SPECIFICATION

LINK, AMMUNITION, 20MM, MARK 6 MODS 4, 5 AND 6

This amendment forms a part of Military specification MIL-L-22624A(WEP) dated 13 June 1964 and has been approved by the Bureau of Naval Weapons, Department of the Navy.

Page 2, revise paragraph 3.1 to read as follows:

3.1 Preproduction sample. Unless otherwise specified in the contract or order, a preproduction sample of links shall be delivered for testing at a facility designated in the contract or order (see 6.2). The links shall be delivered as follows:

(a) 7,486 links shall be Mod 4 links.

(b) 56 links shall be Mod 5 links.

(c) 56 links shall be Mod 6 links.

Fifty-two of the Mod 4 links shall be delivered unbelted. The Mod 4 links shall also be belted into one length of 60 links, seven lengths of 50 links, one length of 13 links, and one length of 11 links. The remainder of the Mod 4 links (7,000) shall be supplied in belts of 50 links. The preproduction sample shall be manufactured using the methods proposed for production. Any production by the supplier prior to approval of the preproduction sample shall be at the supplier's risk.

Page 5 add the following:

3.5.4 Endurance. When tested as specified in 4.6.3.6, the ammunition links shall be capable of functioning in the Mk 4 pod without a stoppage for 7,000 rounds and shall meet the requirements of 3.5.1, 3.5.2, and 3.5.3.

FSC 1305

Source: https://assist.dla.mil -- Downloaded: 2026-10-19T13:08Z
Check the source to verify that this is the current version before use.

Page 5, revise paragraph 3 .6.1 to read as follows:

3.6.1 Resistance to salt spray. Each link tested in accordance with 4.6.1.2 shall be examined visually for evidence of rust. Rust staining and rust drainage shall not be considered when measuring the area of rust spots. Each carrier assembly shall show not more than six rust spots, each measuring not more than 1/8 inch in diameter or equivalent area. Each loop shall show not more than three rust spots of the specified diameter. Each lug, rivet and spring shall show not more than one rust spot of the specified diameter. Any edge rust on the link components shall not be considered in the determination of failure to pass the salt spray test.

Page 7 revise paragraph 4.6.1.2 to read as follows:

4.6.1.2 Salt spray resistance test. After components of the Mk 6 link have received the phosphate coating of specification MIL-P-16232, Type M, Class 1, ten samples of the assembled unbelted Mod 4 link with supplemental coating (VV-L-800 oil) will be subjected to the test of Federal Test Method Standard No. 151, Method 811.1 for twenty-four hours. The link shall meet the requirements of 3.6.1. Test links shall not be reused for other tests nor shall they be delivered to the Government as units of production. Part preparation by mechanical tumbling is permitted prior to phosphate coating and immersion times in phosphate solutions will be adequate to provide proper coating weight and thickness (MIL-P-16232), provided the aforementioned meets the requirements of 3.6.1.

Page 8 revise paragraph 4.6.1.8 to read as follows:

4.6.1.8 Pitch distance test. Eleven Mod 4 links shall be linked and loaded with dummy rounds (see 3.7) and suspended vertically by the rivet of the first link from an appropriate holding device. The distance between the rivet of the first link and the rivet of the last link shall be measured and divided by ten. The link shall meet the requirements of 3.4.6.

Page 9. add the following:

4.6.1.14 Gunfire performance tests. A successful gunfire performance test is required for each increment of 250,000 Mk 6 Mod 4 links (approximately 10 lots). The tests shall be conducted in accordance with 4.6.3.3 wherein a sample of 256 Mod 4 links shall

Source: https://assist.dla.mil -- Downloaded: 2026-10-19T13:08Z
Check the source to verify that this is the current version before use.

be tested. The preproduction tests shall suffice for the first 250,000 links produced. Thereafter, production lots accepted by each performance test shall extend to the lot from which the next performance test link sample is selected. These tests may be conducted prior to the completion of fabrication of the 250,000 link increment. Failure of any link to meet the requirements of 3.5.1, 3.5.2 or 3.5.3 shall be cause for rejection of the 250,000 link increment. The rejected 250,000 link increment may be re-submitted for test under this paragraph, 4.6.1.14, after corrective action has been taken. The link shall not be judged defective if it is verified to the satisfaction of the Government representative that a stoppage or other malfunction was caused by a component other than the links under test, or that the stoppage occurred in the last five rounds of the belt.

Page 11, add the following:

4.6.3.6 Endurance test. The ammunition magazine of the Mk 4 Gun Pod shall be completely filled with Mk 6 Mod 4 ammunition links containing Mk 105 target practice rounds. The rounds shall be fired in bursts of approximately 125 rounds. After the first, second, fourth and fifth bursts the gun shall be allowed to cool for 3 minutes ± 15 seconds. After the third and sixth bursts, the gun pod shall be cooled until the entire mass of the gun pod has been stabilized at the ambient temperature of the test facility. The ammunition magazine shall be refilled and the test repeated. Gun pod maintenance shall be performed as specified in Publication OP 2719. The automatic charge feature may be disconnected during endurance firing to simplify stoppage analysis. The links shall meet the requirements of 3.5.4. The link shall not be judged defective if it is verified to the satisfaction of the Government representative that a stoppage or other malfunction was caused by a component other than the links under test, or that the stoppage occurred in the last five rounds of a belt.

Source: https://assist.dla.mil -- Downloaded: 2026-10-19T13:08Z
Check the source to verify that this is the current version before use.