MIL-S-51482A(EA)
AMENDMENT 3
21 October 1987
SUPERSEDING
AMENDMENT 2
13 February 1987

MILITARY SPECIFICATION

SIMULATOR, DETECTOR TICKETS, CHEMICAL AGENT: TRAINING, M256

This amendment forms a part of MIL-S-51482A(EA), dated 29 May 1986, and is approved for use within the Chemical Research, Development and Engineering Center, Department of the Army and is available for use by all Departments and Agencies of the Department of Defense.

PAGE 1

2.1.1: Delete the following:

"SPECIFICATIONS

MILITARY

MIL-B-22191 - Barrier Materials, Transparent, Flexible, Heat-Sealable.
MIL-D-51083 - Detector Ticket, Anticholinesterase Agent."

PAGE 2

2.1.1: Delete the following:

"STANDARD

FEDERAL

Fed. Test Method Std. No. 101 - Test Procedures for Packaging Materials."

2.1.2:

Line 5: Delete "AND TECHNICAL DATA PACKAGE LIST (TDPL)".

Line 8: Delete "TDPL".

AMSC N/A FSC 6910

DISTRIBUTION STATEMENT A. Approved for public release; distribution is unlimited.

Source: https://assist.dla.mil -- Downloaded: 202610-22T21:02Z
Check the source to verify that this is the currentversion before use.

2.2: Delete the following:

"UNIFORM FREIGHT CLASSIFICATION RULES

(Application for copies should be addressed to Uniform Classification Committee, Room 1106, 222 South Riverside Plaza, Chicago, IL 60606.)"

PAGE 3

2.2: Delete the following:

"NATIONAL MOTOR FREIGHT CLASSIFICATION RULES

(Application for copies should be addressed to the American Trucking Associations, Inc., Traffic Department, 1616 P Street, NW, Washington, DC 20036.)"

3.1.1, line 1: Delete "TDPL" and substitute "Drawing".

3.1.2, line 2: Delete "TDPL" and substitute "Drawing".

PAGE 4

3.6: Delete in its entirety.

3.7: Delete in its entirety.

PAGE 6

Table II: Delete the following row:

"Cholinesterase activity (3.6)	4 each T-400, T-402 T-403, T404 and T404A packaged samplers (20 total)"	Acc 1 Rej 2	4.4.4.4

Source: https://assist.dla.mil -- Downloaded: 202640-22T21:02Z
Check the source to verify that this is the currentversion before use.

PAGE 7

4.4.3.2: Delete the following:

"(a) Nerve spot color (see 3.7).

Categories	Defects
Critical:	None defined
Major:	AQL 2.5 percent defective
101	Color not uniform
102	Color incorrect"

PAGE 8

Table III: Delete the following row:

"Cholinesterase activity (3.6)	MIL-STD-105, inspection level S-1, for stored samplers and MIL-STD-105, inspection S-1 for unstored samplers. Exclude T-401 samplers"	AQL 2.5 percent defective for each sample size	4.4.4.4

4.4.3.2(b), after line 8: Add the following:

"105 Flatness requirement not met"

PAGE 10

4.4.3.2(h), line 11: Delete "code".

4.4.4.3: Delete in its entirety and substitute the following:

"4.4.4.3 Packaged sampler leakage. Place the packaged samplers in a transparent vacuum chamber under no less than 1 inch of water at ambient temperature. Evacuate the chamber to an absolute pressure of 220 ± 25 millimeters of mercury. Continuously examine the samplers for no less than 60 seconds. The samplers that show air bubbles or any other signs of leakage shall be removed from the vacuum chamber, wiped dry, and then opened. Any evidence of moisture or water absorption on the sampler shall be considered evidence of leakage."

4.4.4.4: Delete in its entirety.

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T21:02Z
Check the source to verify that this is the current version before use.

6.1(e): Delete "markings".

Custodian:

Army - EA

Preparing activity:

Army - EA

Project No. 6910-A004

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T21:02Z
Check the source to verify that this is the current version before use.